Appendix H2
Phase I ESA Parcel B

PARTNER
Engineering and Science, Inc.®



PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT

Parcel B – Rohr Inc, a Collins Aerospace Company
850 Lagoon Drive
Chula Vista, California 91910

Report Date: February 12, 2021
Partner Project No. 20-302755.1



Prepared for:

PW Wohl G Street LLC
2251 San Diego Avenue, Suite A-247
San Diego, California 92110

PARTNER
Engineering and Science, Inc.

February 12, 2021

Mr. Emil Wohl
PW Wohl G Street LLC
2251 San Diego Avenue, Suite A-247
San Diego, California 92110

Subject: Phase I Environmental Site Assessment
Parcel B – Rohr Inc., a Collins Aerospace Company
850 Lagoon Drive
Chula Vista, California 91910
Partner Project No. 20-302755.1

Dear Mr. Wohl:

Partner Engineering and Science, Inc. (Partner) is pleased to provide the results of the *Phase I Environmental Site Assessment* (Phase I ESA) report of the abovementioned address (the "subject property"). This assessment was performed in conformance with the scope and limitations as detailed in the ASTM Practice E1527-13 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.

This assessment included a site reconnaissance as well as research and interviews with representatives of the public, property ownership, site manager, and regulatory agencies. An assessment was made, conclusions stated, and recommendations outlined.

We appreciate the opportunity to provide environmental services to you. If you have any questions concerning this report, or if we can assist you in any other matter, please contact either of the undersigned.

Sincerely,

DRAFT

Mike Arias
National Technical Director, Principal
(626) 604-5203

DRAFT

Misty Ponce, PE
Principal
(818) 337-1203

EXECUTIVE SUMMARY

Partner Engineering and Science, Inc. (Partner) has performed a Phase I Environmental Site Assessment (ESA) in accordance with the scope of work and limitations of ASTM Standard Practice E1527-13, the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (AAI) (40 CFR Part 312) and set forth by PW Wohl G Street LLC for the property located at 850 Lagoon Drive (Parcel B) in Chula Vista, San Diego County, California (the "subject property"). The Phase I Environmental Site Assessment is designed to provide PW Wohl G Street LLC with an assessment concerning environmental conditions (limited to those issues identified in the report) as they exist at the subject property.

Property Description

The subject property is bound by G Street to the north, H Street to the south, a rail line to the east, and Marina Parkway to the west within an industrial area of San Diego County. Please refer to the table below for further description of the subject property:

Subject Property Data	
Address(es):	850 Lagoon Drive, Chula Vista, California 91910
Additional Address(es):	Parcel B – North Campus; Foot of G Street; Foot of H Street
Historical Address(es):	802 and 848 G Street
Property Use:	Industrial
Land Acreage (Ac):	30 +/- Ac
Number of Buildings:	21 +/-
Number of Floors:	One with mezzanine areas
Gross Building Area (SF):	720,032 +/- SF estimate
Net Rentable Area (SF):	720,032 +/- SF estimate
Date of Construction:	1941 with subsequent additions
Assessor's Parcel Numbers (APNs):	571-330-24-00, 571-330-27-00, 571-330-29-00
Type of Construction:	Metal Frame/Concrete Block/Concrete Slab
Current Tenants:	Rohr Inc., a Collins Aerospace Company
Site Assessment Performed By:	Margaret Thomas of Partner
Site Assessment Conducted On:	January 13, 2021

The subject property is currently occupied by Rohr Inc., a Collins Aerospace Company (Rohr) who is actively decommissioning the onsite manufacturing facility for future sale and redevelopment. Rohr was a manufacturer of aircraft components and aerospace systems that started manufacturing at the subject property in 1941, primarily within Building 1, which is centrally located on Parcel B and is the largest building. Manufacturing operations ceased approximately one year ago. These operations included metal casting and fabrication, metal cutting, punching, bending, forming, anodizing, alodining and painting of metal parts, milling through the use of machining and chemical processes, tool and die casting and shaping, assembly, and storage. Secondary activities that supported the manufacturing processes included maintenance and storage of vehicles, recycling of materials, hazardous materials storage in aboveground and underground storage tanks (ASTs/USTs), and operation of an industrial wastewater treatment plant (WWTP).

In addition to the current structures, the subject property is also improved with paved driveways and parking areas, open-sided awning structures, perimeter fencing, and limited landscaping within the fenced facility.

According to available historical sources, the subject property was formerly undeveloped land within and along the San Diego Bay shoreline as early as 1904 to 1918. In the 1920s, a facility was present at the northeast corner of the subject property that manufactured a cementitious material called Tycrete under the business names of R&H Tyce then Pioneer Pyrophyllite Manufacturing Company, apparently operating at this location until at least 1962. Sanborn maps depicted a mill building for milling and grinding operations that included a laboratory and paint shop. A small dwelling and storage buildings were also depicted. From 1929 to 1930, an unpaved air depot and airfield was reportedly located between G and H Streets that traversed the subject property. The airfield and a flying school operated at this location through circa 1940. The airfield and runway properties were leased to Rohr Aircraft Corporation in 1940 for constructing its aircraft component manufacturing plant. In the late 1950s through early 1960s, sediment was dredged from San Diego Bay and placed on the west side of the subject property (Parcel B) and adjacent areas to create more land on which additional manufacturing buildings were eventually built. The subject property is situated within a historical aerospace manufacturing campus operated by Rohr Inc. that included associated manufacturing and support structures present at different times in all directions.

The immediately surrounding properties consist of a San Diego Gas & Electric (SDG&E) substation and G Street to the north followed by several Rohr Inc. facility buildings (Parcel C) used for warehouse, office, testing, and former co-generation plant (Buildings 61, 78, 79, 118) with Parcel A Buildings 99 and 100 to the northeast reportedly used for offices, a fitness center and engine test laboratory as of 2013 and open wetlands to the northwest; H Street to the south followed by vacant land (former South Campus parcel used by Rohr Industries Inc. with all buildings demolished in circa 2007); a rail line (San Diego and Arizona Eastern right-of-way) to the east followed by a long rectangular industrial building occupied by Rohr Inc. (Parcel A - Building 29) used for product development, aftermarket, tooling and engineering uses; and a narrow strip of partially vacant land and parking area to the west followed by Marina Parkway beyond which is vacant land identified as Rohr Inc. Parcel H-3.

As part of the on-going subject property investigation, Partner reviewed a Report of *Interim Remedy Baseline and Consolidated Third Quarter Groundwater Monitoring and Sampling* report dated October 15, 2020, which reports depth to groundwater at the subject property between 2 to 10 feet below ground surface (bgs), and groundwater flow is reported to be westward toward San Diego Bay. Groundwater flow conditions in the identified water-bearing zones (Zone A, Upper Zone B and Lower Zone B) in the subject property vicinity are tidally influenced. The salinity and density of groundwater varies among the monitoring wells. The North Campus monitoring well network consists of 55 monitoring wells, several of which are collocated clusters of between two to four wells that monitor several specific areas of concern at the subject property and adjacent North Campus areas.

Findings

A *recognized environmental condition (REC)* refers to the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: due to release to the environment; under conditions indicative of a release to the environment; or under conditions that pose a material threat of a future release to the environment. The following was identified during the course of this assessment:

- Aerospace manufacturing operations were conducted at the subject property from circa 1941 until approximately one year ago, which involved the operation of heavy machinery within below grade vaults, multiple solvent degreasers, paint spray booths, multiple ASTs/USTs, and other equipment and the use of various hazardous substances including halogenated volatile organic compounds (VOCs) such as trichloroethene (TCE), metals (aluminum, titanium, chromium, lead and steel), petroleum hydrocarbons, polynuclear aromatic hydrocarbons (PAHS), polychlorinated biphenyls (PCBs), and other substances identified as chemicals of concern (COC) that have been reported in soil, soil vapor and groundwater underlying the subject property. TCE and 1,1,1-trichloroethane (1,1,1-TCA) were historically used as degreasing solvents and have been the subject of soil, soil vapor, and groundwater investigations at the subject property facility dating back to the 1980s. The subject property is currently being investigated under the regulatory oversight of the San Diego Regional Water Quality Control Board (SDRWQCB) under a corrective action order (CAO) 98-08 dated April 1998 addressed to Rohr Inc., for site wide environmental impacts (North Campus) resulting from historical releases including into the storm drain conveyance system and San Diego Bay. The CAO requires the cleanup and abatement of wastes discharged from Rohr's manufacturing operations.

  Interim remedial actions are currently underway on the adjacent parcel located downgradient of the subject property source areas, known as Rohr Parcel H-3, pursuant to the 1998 CAO No. 98-08. Redevelopment activities are planned for Parcel H-3 as part of a large Bayfront redevelopment project in the coming months. Implementation of the interim remedy on Parcel H-3 occurred from April to September 2020 and includes four permeable reactive barriers (PRBs), injection of in situ chemical reduction (ISCR) and enhanced in situ bioremediation (EISB) amendments. The PRBs were placed as such to capture impacts originating from the subject property in efforts to prevent contamination from reaching the San Diego Bay. SDRWQCB is currently preparing a new site wide CAO No. R9-2020-0099, which will address the cleanup remedies and timeline of all wastes discharged to soil, soil vapor, and groundwater from the manufacturing operations at the North Campus Property (subject property). CAO No. R9-2020-0099 will supersede CAO No. 98-08 except for the interim remedial actions at Parcel H-3, which will continue to be conducted under CAO No. 98-08. The new CAO No. R9-2020-0099 is not yet final, although remediation work plans, feasibility studies, and a human health risk assessment (HHRA) are underway and/or in the planning stages for the subject property to address soil, soil vapor and groundwater impacts. Based on Partner's current understanding of the status of proposed remediation, a soil vapor extraction system may be employed as well as targeted efforts

for groundwater; however, remedial action plans have not been determined or finalized for the subject property.

A considerable number of investigations have been conducted on the subject property since the late 1980s. Currently there are several hot spots and comingled groundwater plumes at the subject property that include but are not limited to a 1,1,1–TCA/TCE AST that was formerly located west of former Building 57 near the northwest corner of the subject property; the *Oiler Shed* located at the middle south side of the subject property; and a vapor degreaser line aligned east/west through Building 1. COCs in these specific areas included TCE, 1,1,1-TCA and their degradation products and hexavalent chromium (salt bath area inside Building 1). According to an Annual Groundwater Monitoring and Sampling Report dated November 21, 2019, TCE was detected more frequently and at higher concentrations than other VOCs. The maximum TCE concentration was detected in monitoring well NCW-14A at 31,000 micrograms per liter (µg/L). Well NCW-14A is completed in Zone A and is located immediately downgradient of the suspected Oiler Shed release area. TCE concentrations in Zone A decrease downgradient of NCW-14A. VOC concentrations in Lower Zone B remain substantially less than in the shallower groundwater zones. In addition, based on reviewed information, COCs have migrated off site to the west and southwest in all water bearing zones, primarily in Zones A and Upper Zone B. TCE impacts are widespread across the subject property (Parcel B) in the shallow groundwater Zone A then taper off in the lower B Zones.

According to Rohr Inc., personnel, Rohr Inc. is reportedly responsible for site cleanup at this time. No specific remedial action plans for soil, soil vapor and groundwater cleanup have been finalized. No active remediation systems are present at the subject property; only groundwater monitoring wells at this time. The identified soil, soil vapor and groundwater impacts at the subject property and current regulatory status is considered a REC.

A *controlled recognized environmental condition (CREC)* refers to a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority, with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls. The following was identified during the course of this assessment:

- Partner did not identify CRECs during the course of this assessment.

A *historical recognized environmental condition (HREC)* refers to a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls. The following was identified during the course of this assessment:

- The subject property is identified as having several prior documented release cases that were investigated, remediated and received regulatory case closure letters from either SDRWQCB or the local San Diego County Department of Environmental Health (DEH) that are HRECs. Partner notes that a majority of the cases continue to be investigated as part of the site wide groundwater investigation and cleanup efforts due to groundwater impacts identified in those areas such as the salt bath area in Building 1 and the oiler shed. The release events with documented regulatory case closures include the following:
    - BF Goodrich Aerospace Facility, 850 Lagoon Drive, UST closure of one 10,000-gallon diesel tank adjacent to former Building 57 in August 1987. Impacted soils around the UST were removed and disposed along with 500 gallons of impacted water. This UST received regulatory closure from the County DEH on August 2, 2002.
    - UTC Aerospace Systems, Former North Oiler Shed, Building 1. An undocumented 550-gallon UST was discovered and removed in 2000 during renovations in the oiler shed area that contained petroleum hydrocarbons and VOCs. The tank had holes and corrosion, and a groundwater sample identified elevated concentrations of TCE and other VOCs. This UST was granted closure on January 3, 2013, for total recoverable petroleum hydrocarbons (TRPH) only, while the remaining VOC impacts are being addressed by the site wide CAO.
    - Goodrich Aerostructures, Tank 6, Oiler Shed Sump, Building 1. This sump was described as 2'x2'x3' that discharged to a long drainage trench where machine coolant was collected, recycled and dispensed. Initially equipment and metal chip tubs were drained of oil or coolant and accumulated in the trough and sump where it was then pumped into an AST until 1992. This sump was granted closure on June 1, 2012, for petroleum hydrocarbons only, while the remaining VOC impacts are being addressed by the site wide CAO.
    - Goodrich Aerostructures – North Campus – Salt Bath C70, 850 Lagoon Drive, the former salt bath consisted of four below-grade structures that were considered to be USTs. The salt baths were used in the aluminum forming process and formerly contained a hexavalent chrome additive to control corrosion. The operation is the subject of an ongoing evaluation, due to hexavalent chromium found in groundwater in this area. Soil beneath the salt baths was reportedly excavated and disposed. The Salt Bath C70 was administratively closed on May 8, 2019, however potential contaminant releases from it are part of the larger cleanup and remediation efforts at the subject property as a whole.
    - Goodrich Aerostructures Machine Shop Sump, Tank No. 34. The sump was located in the southern portion of Building 1, was constructed in 1943, and consisted of a 4'x4' concrete structure that was approximately 6 feet deep (total capacity reportedly 720 gallons). This feature was categorized as an UST by the DEH. Hydraulic oil was collected from larger, floor-mounted milling machines (N/C machines) that were plumbed to the sump. The

N/C machines were supplied with hydraulic oil from a central hydraulic unit. Hydraulic oil was transferred to each N/C machine through utility trenches via hydraulic lines. Tank No. 34 was administratively closed on May 8, 2019, however potential contaminant releases from it are part of the larger cleanup and remediation efforts at the subject property as a whole.

An *environmental issue* refers to environmental concerns identified by Partner, which do not qualify as RECs; however, warrant further discussion. The following was identified during the course of this assessment:

- Up to 100 ASTs, USTs, vessels, and vaults were operated at the subject property associated with aerospace manufacturing activities, several of which are identified as contributors to the known environmental impacts at the subject property. No active USTs are currently operated at the subject property, and the ASTs, vaults and vessels have either been removed or are in the process of being removed, sold or scrapped. No active industrial processes are occurring at the subject property. The various sized above ground tanks and vessels contained hazardous substances including acids, caustics, wastewater, deionized water, cleaners, solvents, petroleum hydrocarbons including gasoline and diesel, hydraulic oil, coolant, and other substances. The USTs were reportedly closed or abandoned in place under regulatory oversight. One 10,000-gallon waste oil UST was closed in place in 1987 in the oiler shed, which will likely be encountered during redevelopment activities is surface disturbance occurs in the area it is located. At least one UST was undocumented and was discovered during renovations, indicating other undocumented USTs may be found during redevelopment of the property. It is expected that residual contaminant impacts will be encountered during site redevelopment in and around historic subsurface vessels, vaults, USTs, and piping, including along the historic shoreline where impacts were reported during prior subsurface investigations. Based on historical uses of ASTs and USTs for hazardous material storage that may have residually impacted underlying soils, this represents an environmental concern that must be managed during site redevelopment.
- Based on a review of regulatory documents posted to the State Water Resources Control Board GeoTracker database and other provided information, there is an extensive storm water conveyance system (SWCS) on the subject property that currently drains through two outfalls (Outfall Nos. 1 and 2) to San Diego Bay. During the 1970s, there were reportedly 7 to 10 stormwater outfalls discharging to San Diego Bay, in and around the subject property, including a historic drainage ditch. Due to the low elevation of the property, the SWCS is tidally influenced. Historical allegations of process rinse water discharges to the SWCS were reported in the 1950s to 1970s prior to the installation of a WWTP. These historical discharges have possibly resulted in contaminant impacts to the sediment at the discharge points and vicinity in the San Diego Bay. This issue was the subject of the 1998 CAO and will be addressed in the future via a separate CAO that will likely include the subject property. Based on the reported historical industrial waste discharges to the SWCS and known sediment impacts from the historic outfalls, this represents a potential environmental concern.

- Due to the age of the subject property buildings, there is a potential that asbestos-containing materials (ACMs) and/or lead-based paint (LBP) are present. The buildings are proposed for demolition in the coming months at which time suspect materials will be required to be abated and properly disposed. A 1989 ACM survey identified ACM at the subject property in multiple locations, and LBP was identified in Building 54 during a 2016 sampling survey. The property has an Asbestos Operations and Maintenance (O&M) Program in place dated July 2013, which reports ACM and *Assumed Positive Materials* in Buildings 1, 22, 50, 54, 55, 63, 68, 79, 88, 91, 310, and 503. Additional sampling prior to demolition may be required for waste characterization and disposal purposes.

Conclusions, Opinions and Recommendations

Partner has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E1527-13 of Parcel B at 850 Lagoon Drive in Chula Vista, San Diego County, California (the "subject property"). Any exceptions to, or deletions from, this practice are described in Section 1.5 of this report.

This assessment has revealed evidence of recognized environmental conditions and environmental issues in connection with the subject property. Based on the conclusions of this assessment, Partner recommends the following:

- Continue to adhere to existing, and future CAOs, issued by SDRWQCB as they pertain to soil, soil vapor, groundwater, and bay sediments contamination resulting from historical uses on the subject property.
- A detailed Soil Management Plan is recommended for site redevelopment to address unexpected items such as below grade features, piping and residual soil impacts.
- A Vapor Barrier is recommended to be incorporated into the new site development plan to act as a mitigating factor for known VOC impacts in the groundwater.
- A demolition level Hazardous Materials Survey is recommended to identify items that require abatement prior to demolition such as mercury switches and lamp tubes, PCB-containing light ballasts and switches, fluorescent lights, refrigerant-containing HVAC systems, and other items.
- Groundwater wells may need to be temporarily abandoned and re-installed during site redevelopment.

TABLE OF CONTENTS

1.0 INTRODUCTION 1
1.1 Purpose 1
1.2 Scope of Work 1
1.3 Limitations 2
1.4 User Reliance 2
1.5 Limiting Conditions 3
2.0 SITE DESCRIPTION 4
2.1 Site Location and Legal Description 4
2.2 Current Property Use 4
2.3 Current Use of Adjacent Properties 4
2.4 Physical Setting Sources 5
2.4.1 Topography 5
2.4.2 Hydrology 5
2.4.3 Geology/Soils 6
2.4.4 Flood Zone Information 7
3.0 HISTORICAL INFORMATION 8
3.1 Aerial Photograph Review 8
3.2 Fire Insurance Maps 10
3.3 City Directories 12
3.4 Historical Topographic Maps 12
4.0 REGULATORY RECORDS REVIEW 15
4.1 Regulatory Agencies 15
4.2 Mapped Database Records Search 22
4.2.1 Regulatory Database Summary 22
4.2.2 Subject Property Listings 23
4.2.3 Adjacent Property Listings 24
4.2.4 Sites of Concern Listings 25
4.2.5 Orphan Listings 26
5.0 USER PROVIDED INFORMATION AND INTERVIEWS 27
5.1 Interviews 28
5.1.1 Interview with Owner 28
5.1.2 Interview with Report User 28
5.1.3 Interview with Key Site Manager 28
5.1.4 Interviews with Past Owners, Operators and Occupants 28
5.1.5 Interview with Others 28
5.2 User Provided Information 29
5.2.1 Title Records, Environmental Liens, and Activity and Use Limitations (AULs) 29
5.2.2 Specialized Knowledge 29
5.2.3 Actual Knowledge of the User 29
5.2.4 Valuation Reduction for Environmental Issues 29
5.2.5 Commonly Known or Reasonably Ascertainable Information 29
5.2.6 Previous Reports and Other Provided Documentation 29

6.0 SITE RECONNAISSANCE 35
6.1 General Site Characteristics 35
6.2 Potential Environmental Hazards 37
6.3 Non-ASTM Services 40
6.3.1 Asbestos-Containing Materials (ACMs) 40
6.3.2 Lead-Based Paint (LBP) 40
6.3.3 Radon 41
6.3.4 Lead in Drinking Water 41
6.3.5 Mold 41
6.4 Adjacent Property Reconnaissance 42
7.0 FINDINGS AND CONCLUSIONS 43
8.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS 48
9.0 REFERENCES 49

Figures

Figure 1 Site Location Map
Figure 2 Site Plan
Figure 3 Topographic Map

Appendices

Appendix A Site Photographs
Appendix B Historical/Regulatory Documentation
Appendix C Regulatory Database Report
Appendix D Qualifications

1.0 INTRODUCTION

Partner Engineering and Science, Inc. (Partner) has performed a Phase I Environmental Site Assessment (ESA) in conformance with the scope and limitations of ASTM Standard Practice E1527-13 and the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (AAI) (40 CFR Part 312) for the property located at 850 Lagoon Drive in Chula Vista, San Diego County, California (the "subject property"). Any exceptions to, or deletions from, this scope of work are described in the report.

1.1 Purpose

The purpose of this ESA is to identify existing or potential Recognized Environmental Conditions (as defined by ASTM Standard E1527-13) affecting the subject property that: 1) constitute or result in a material violation or a potential material violation of any applicable environmental law; 2) impose any material constraints on the operation of the subject property or require a material change in the use thereof; 3) require clean-up, remedial action or other response with respect to Hazardous Substances or Petroleum Products on or affecting the subject property under any applicable environmental law; 4) may affect the value of the subject property; and 5) may require specific actions to be performed with regard to such conditions and circumstances. The information contained in the ESA Report will be used by Client to: 1) evaluate its legal and financial liabilities for transactions related to foreclosure, purchase, sale, loan origination, loan workout or seller financing; 2) evaluate the subject property's overall development potential, the associated market value and the impact of applicable laws that restrict financial and other types of assistance for the future development of the subject property; and/or 3) determine whether specific actions are required to be performed prior to the foreclosure, purchase, sale, loan origination, loan workout or seller financing of the subject property.

This ESA was performed to permit the *User* to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on scope of Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. §9601) liability (hereinafter, the "*landowner liability protections*," or "*LLPs*"). ASTM Standard E1527-13 constitutes "*all appropriate inquiry* into the previous ownership and uses of the *property* consistent with good commercial or customary practice" as defined at 42 U.S.C. §9601(35)(B).

1.2 Scope of Work

The scope of work for this ESA is in accordance with the requirements of ASTM Standard E1527-13. This assessment included: 1) a property and adjacent site reconnaissance; 2) interviews with key personnel; 3) a review of historical sources; 4) a review of regulatory agency records; and 5) a review of a regulatory database report provided by a third-party vendor. Partner contacted local agencies, such as environmental health departments, fire departments and building departments in order to determine any current and/or former hazardous substances usage, storage and/or releases of hazardous substances on the subject property. Additionally, Partner researched information on the presence of activity and use limitations (AULs) at these agencies. As defined by ASTM E1527-13, AULs are the legal or physical restrictions or limitations on the use of, or access to, a site or facility: 1) to reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil or groundwater on the subject

property; or 2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. These legal or physical restrictions, which may include institutional and/or engineering controls (IC/ECs), are intended to prevent adverse impacts to individuals or populations that may be exposed to hazardous substances and petroleum products in the soil or groundwater on the property.

If requested by Client, this report may also include the identification, discussion of, and/or limited sampling of asbestos-containing materials (ACMs), lead-based paint (LBP), mold, and/or radon.

1.3 Limitations

Partner warrants that the findings and conclusions contained herein were accomplished in accordance with the methodologies set forth in the Scope of Work. These methodologies are described as representing good commercial and customary practice for conducting an ESA of a property for the purpose of identifying recognized environmental conditions. There is a possibility that even with the proper application of these methodologies there may exist on the subject property conditions that could not be identified within the scope of the assessment or which were not reasonably identifiable from the available information. Partner believes that the information obtained from the record review and the interviews concerning the subject property is reliable. However, Partner cannot and does not warrant or guarantee that the information provided by these other sources is accurate or complete. The conclusions and findings set forth in this report are strictly limited in time and scope to the date of the evaluations. The conclusions presented in the report are based solely on the services described therein, and not on scientific tasks or procedures beyond the scope of agreed-upon services or the time and budgeting restraints imposed by the Client. No other warranties are implied or expressed.

Some of the information provided in this report is based upon personal interviews, and research of available documents, records, and maps held by the appropriate government and private agencies. This report is subject to the limitations of historical documentation, availability, and accuracy of pertinent records, and the personal recollections of those persons contacted.

This practice does not address requirements of any state or local laws or of any federal laws other than the all appropriate inquiry provisions of the LLPs. Further, this report does not intend to address all of the safety concerns, if any, associated with the subject property.

Environmental concerns, which are beyond the scope of a Phase I ESA as defined by ASTM include the following: ACMs, LBP, radon, and lead in drinking water. These issues may affect environmental risk at the subject property and may warrant discussion and/or assessment; however, are considered non-scope issues. If specifically requested by the Client, these non-scope issues are discussed in Section 6.3.

1.4 User Reliance

PW Wohl G Street LLC engaged Partner to perform this assessment in accordance with an agreement governing the nature, scope and purpose of the work as well as other matters critical to the engagement. All reports, both verbal and written, are for the sole use and benefit of PW Wohl G Street LLC. Either verbally or in writing, third parties may come into possession of this report or all or part of the

information generated as a result of this work. In the absence of a written agreement with Partner granting such rights, no third parties shall have rights of recourse or recovery whatsoever under any course of action against Partner, its officers, employees, vendors, successors or assigns. Any such unauthorized user shall be responsible to protect, indemnify and hold Partner, Client and their respective officers, employees, vendors, successors and assigns harmless from any and all claims, damages, losses, liabilities, expenses (including reasonable attorneys' fees) and costs attributable to such Use. Unauthorized use of this report shall constitute acceptance of and commitment to these responsibilities, which shall be irrevocable and shall apply regardless of the cause of action or legal theory pled or asserted. Additional legal penalties may apply.

This report has been completed under specific Terms and Conditions relating to scope, relying parties, limitations of liability, indemnification, dispute resolution, and other factors relevant to any reliance on this report. Any parties relying on this report do so having accepted Partner's standard Terms and Conditions, a copy of which can be found at http://www.partneresi.com/terms-and-conditions.php.

1.5 Limiting Conditions

The findings and conclusions contain all of the limitations inherent in these methodologies that are referred to in ASTM E1527-13.

Specific limitations and exceptions to this ESA are more specifically set forth below:

- Interviews with past owners, operators and occupants were not reasonably ascertainable and thus constitute a data gap. Based on information obtained from other historical sources (as discussed in Section 3.0), this data gap is not expected to alter the findings of this assessment.
- Partner requested information relative to deed restrictions and environmental liens, a title search, and completion of the AAI User Questionnaire from the Report User. This information was not provided at the time of the assessment.

Due to time constraints associated with this report, the Client has requested the report despite the above-listed limitations.

2.0 SITE DESCRIPTION

2.1 Site Location and Legal Description

The subject property at 850 Lagoon Drive in Chula Vista, California is bound by G Street to the north, H Street to the south, a rail line to the east, and Marina Parkway to the west within an industrial area of San Diego County. According to the San Diego County Assessor, the subject property is associated with Assessor's Parcel Numbers (APNs) 571-330-24, 571-330-27, and 571-330-29. The current owner is reported as Rohr Inc., who has owned the subject property since circa 1950s under various entity names.

Please refer to Figure 1: Site Location Map, Figure 2: Site Plan, Figure 3: Topographic Map, and Appendix A: Site Photographs for the location and site characteristics of the subject property.

2.2 Current Property Use

The subject property is currently occupied by Rohr Inc., a Collins Aerospace Company (Rohr) who is actively decommissioning the onsite manufacturing facility for future sale and redevelopment. The subject property is developed with approximately 21 +/- structures, many of which are small auxiliary storage structures. Other uses of the buildings included a café, welding shop, paint storage, automotive maintenance, warehouse, foundry, and others. Rohr was a manufacturer of aircraft components and aerospace systems that started manufacturing at the subject property in 1941, which centered primarily within Building 1 which is centrally located on Parcel B and is the largest building. Manufacturing operations ceased approximately one year ago. These operations included metal casting and fabrication, metal cutting, punching, bending, forming, anodizing, alodining and painting of metal parts, milling through the use of machining and chemical processes, tool and die casting and shaping, assembly, and storage. Several deep mechanical pits (12 +/- feet) are present inside Building 1. Secondary activities that supported the manufacturing processes included maintenance and storage of vehicles, recycling of materials, hazardous materials storage in ASTs/USTs, and operation of an industrial WWTP.

In addition to the current structures, the subject property is also improved with paved driveways and parking areas, open-sided awning structures, perimeter fencing, and limited landscaping within the fenced facility.

The subject property is zoned Local Coastal Program Specific Plan Area by the City of Chula Vista in the Chula Vista Bayfront Area.

The subject property is identified on multiple Federal, State and local regulatory databases due to years of hazardous materials handling, hazardous waste activity, air emission permitting, operation of ASTs/USTs, storm water regulated site, and environmental cleanup, as further discussed in Section 4.2.

2.3 Current Use of Adjacent Properties

The subject property is located within an industrial area of San Diego County. During the vicinity reconnaissance, Partner observed the following land use on properties in the immediate vicinity of the subject property:

Immediately Surrounding Properties

North: SDG&E substation and G Street followed by several Rohr Inc. facility buildings (Parcel C) used for warehouse, office, testing, and former co-generation plant (Buildings 61, 78, 79, 118) with Parcel A Buildings 99 and 100 to the northeast reportedly used for offices, a fitness center and engine test laboratory as of 2013 and open wetlands to the northwest

South: H Street followed by vacant land (former South Campus parcel used by Rohr Industries Inc. with all buildings demolished in 2007)

East: A rail line (San Diego and Arizona Eastern right-of-way) followed by a long rectangular industrial building occupied by Rohr Inc. (Parcel A - Building 29) used for product development, aftermarket, tooling and engineering uses

West: A narrow strip of partially vacant land and parking area followed by Marina Parkway beyond which is vacant land identified as Rohr Inc. Parcel H-3

The adjacent parcels currently and formerly occupied by Rohr Inc., are identified as part of an on-going site wide cleanup and abatement investigation, as further discussed in Section 4.2.

2.4 Physical Setting Sources

2.4.1 Topography

The United States Geological Survey (USGS) *National City, California* Quadrangle 7.5-minute series topographic map was reviewed for this ESA. According to the contour lines on the topographic map, the subject property is located at approximately 10 feet above mean sea level (MSL). The contour lines in the area of the subject property indicate the area is sloping gently toward the west. The subject property is depicted as developed with several structures dating back to 1953 at which time the west portion of the subject property (Parcel B) is within the San Diego Bay. By 1967, the subject property land was expanded from dredged material from the Bay including the addition of several new structures.

A copy of the most recent topographic map is included as Figure 3 of this report.

2.4.2 Hydrology

According to topographic map interpretation, the direction of groundwater flow in the vicinity of the subject property is inferred to be toward the west. The nearest surface water in the vicinity of the subject property is the San Diego Bay located approximately 1,100 feet northwest of the subject property at its nearest point with wetlands located adjacent to the northwest across G Street. No settling ponds, lagoons, surface impoundments, wetlands or natural catch basins were observed at the subject property during this assessment.

According to available information, a public water system operated by the City of Chula Vista serves the subject property vicinity. The City obtains municipal drinking water through the Sweetwater Authority who obtains municipal drinking water from four sources: the Sweetwater River (drawn at Sweetwater Reservoir in Spring Valley), deep freshwater wells in National City, brackish water wells in Chula Vista, and the region's imported supply, which is drawn from the Colorado River and/or the State Water Project in northern California. The location of public drinking water well(s) were not readily available in public records. During the site visit, Partner did not identify evidence of public, private, or irrigation wells on or

adjacent to the subject property. Therefore, it can be assumed that shallow groundwater beneath the subject property is not directly used for domestic purposes.

According to a Report of Interim Remedy Baseline and Consolidated Third Quarter Groundwater Monitoring and Sampling report dated October 15, 2020, depth to groundwater at the subject property ranges from 2 to 10 feet bgs, and groundwater flow is reported to be westward toward the San Diego Bay. Groundwater flow conditions in the identified water-bearing zones (Zone A, Upper Zone B and Lower Zone B) in the site vicinity are tidally influenced. The salinity and density of groundwater varies among the monitoring wells. The North Campus monitoring well network consists of 55 monitoring wells, several of which are collocated clusters of two or three wells that monitor several specific areas of concern at the subject property and adjacent areas.

The three primary water bearing zones beneath the subject property are described as follows:

- Zone A: extends to a depth of approximately 25 feet bgs onsite, which generally corresponds to the artificial fill and Bay Deposits.
- Upper Zone B: extends to a depth of 55 to 70 feet bgs, which corresponds to the upper portion of the Bay Point Formation.
- Lower Zone B: extends to a depth of approximately 125 feet bgs, which corresponds to the lower portion of the Bay Point Formation.

In general, groundwater flow in Zone A and Upper Zone B is westward towards San Diego Bay. Density-dependent flow conditions influence groundwater flow near San Diego Bay as seawater intrudes landward beneath less saline groundwater in this area causing eastward (landward) equivalent freshwater head gradients in portions of Lower Zone B.

2.4.3 Geology/Soils

The subject property and adjacent areas are underlain by fill material, both undocumented and dredged material from San Diego Bay, and with increasing depth Holocene Bay Deposits (Bay Deposits), the Pleistocene Bay Point Formation, and the Pliocene San Diego Formation. The fill generally consists of silt, clayey sand, and fine sand, but locally contains some gravel. West of the historic shoreline, the fill consists of dredged materials from San Diego Bay. The fill locally extends to depths of 10 feet bgs onsite. Bay Deposits underlie much of the fill material. The Bay Deposits consist of clay and silt interbedded with fine sand and locally extends to a depth of approximately 25 feet bgs at North Campus. The Bay Point Formation underlies the Bay Deposits and consists of alternating sequences of clay, silt, and sand deposited in a nearshore environment. The Bay Point Formation extends to a depth of approximately 150 feet. A clay zone at its base forms a regional aquitard and separates the Bay Point Formation from the underlying San Diego Formation.

The San Diego Bay tidelands were developed during the 1940s through the 1960s at the North Campus with undocumented fill and dredged materials. Because of dominant fine-grained materials, the underlying fill material is considered to have a low hydraulic conductivity. The dredged fill and Bay Deposits are also considered to have low hydraulic conductivities.

Based on information obtained from the USDA Natural Resources Conservation Service Web Soil Survey online database, the subject property is mapped as Huerhuero-Urban land complex, 2 to 9 percent slopes (HuC) and Made Land (Md). The landform for HuC soils is described as marine terraces with the parent material described as calcareous alluvium derived from sedimentary rock. The Made Land is discussed above as dredged material from the San Diego Bay to increase land area at the subject property and surrounding areas.

2.4.4 Flood Zone Information

Partner performed a review of the Flood Insurance Rate Map, published by the Federal Emergency Management Agency (FEMA). According to Community Panel Number 06073C1913H dated December 20, 2019, the subject property is mapped in Zone X, an area of minimal flood hazard along the north side of the property and mapped as Zone X with an overlay indicating a 0.2 percent chance flood hazard for the remainder and majority of the subject property.

A copy of the reviewed flood map is not included in Appendix B of this report.

3.0 HISTORICAL INFORMATION

Partner obtained historical use information about the subject property from a variety of sources. A chronological listing of the historical data found is summarized in the table below:

Historical Use Information		
Period/Date	**Source**	**Description/Use**
1904-1918	Topographic Maps, Sanborn Maps	Undeveloped/Native land and San Diego Bay
1926-1962	Topographic Maps, Sanborn Maps	Tycrete manufacturing facility
1930	Aerial Photograph	Airfield
1941-Present	Aerial Photographs, Topographic Maps, Previous Reports, Sanborn Maps, Regulatory Records	Rohr Inc., aerospace manufacturing

According to available historical sources, the subject property was formerly undeveloped land within and along the San Diego Bay shoreline as early as 1904 to 1918. In the 1920s, a facility was present at the northeast corner of the subject property that manufactured a cementitious material called Tycrete under the business names of R&H Tyce then Pioneer Pyrophyllite Manufacturing Company, apparently operating at this location until at least 1962. Sanborn maps depicted a mill building for milling and grinding operations that included a laboratory and paint shop. A small dwelling and storage buildings were also depicted. Ludwig Tyce formed the Tycrete company to manufacture a waterproof, colored cement that he patented.

From 1929 to 1930, an unpaved air depot and airfield was reportedly located between G and H Streets that traversed the subject property. The airfield and a flying school operated at this location through circa 1940. The airfield and runway properties were leased to the Rohr Aircraft Corporation in 1940 for constructing its aircraft component manufacturing plant at the foot of H Street. In the late 1950s through early 1960s, sediment was dredged from San Diego Bay and placed on the west side of the subject property (Parcel B) and adjacent areas to create more land in which additional manufacturing buildings were eventually built on the subject property. The subject property is situated within the center of a historical aerospace manufacturing campus operated by Rohr Inc. that included associated manufacturing and support structures in all directions constructed at various times.

3.1 Aerial Photograph Review

Partner obtained available aerial photographs of the subject property and surrounding area from Environmental Data Resources (EDR) on January 11, 2021, and from a prior Phase I ESA prepared by URS dated April 2, 2013, that included aerial photographs dating back to circa 1929 and 1930. The following was observed on the subject property and adjacent properties during the aerial photograph review:

Date: Circa 1929	***Scale: 1"=500'***
Subject Property:	An unpaved airfield with two or more runways is present through the subject property surrounded by undeveloped land with several small structures present at the northeast corner of the property, identified as a small mill that manufactures tycrete. The west side of the property is within the San Diego Bay with shoreline and natural wetlands present
North:	G Street is present beyond which is a manufacturing facility comprised of several buildings occupied by International Magnesite Products Company
South:	Unpaved airfield and open space
East:	Rail spur followed by agricultural land and what appears to be residences
West:	San Diego Bay

Date: 1930s	***Scale: 1"=500'***
Subject Property:	The property is primarily undeveloped land with an unpaved airstrip that appears different from the prior aerial. Several small airplanes are present on the north side of the property. The tycrete mill is present at the northeast corner of the property.
North:	No significant changes noted
South:	No significant changes noted
East:	A single rail line is depicted although the area beyond is not included on the aerial photograph
West:	No significant changes noted

Date: 1944	***Scale: 1"=500'***
Subject Property:	The property is developed with multiple buildings where Building 1 is two buildings that will later be connected. Three rectangular shaped buildings are present at the northwest corner of the property that are no longer present at this time. The west side of the property is a storage yard along the shore, which is in its original alignment (prior to dredging). Two ASTs are present. The tycrete mill is present at the northeast corner of the property
North:	G Street beyond which is a small sewage treatment plant near the shoreline that includes two settling ponds and the same manufacturing buildings. Orchard is present to the northeast
South:	Manufacturing buildings are present (South Parcel) with multiple aircraft present along the south side of the parcel. H Street is not present
East:	Multiple rail lines are present beyond which is agricultural and residential uses
West:	San Diego Bay

Date: 1948, 1953	***Scale: 1"=500'***
Subject Property:	The property includes multiple buildings with some new structures; the original shoreline is still present. Building 1 has been joined into one large building. The east side of the property is used for parking of employee vehicles. A large quantity of exterior storage of materials is visible across the property. The tycrete plant is still present
North:	No significant changes noted
South:	Rohr manufacturing facility known as South Parcel
East:	Rail line followed by industrial uses

Date: 1948, 1953	*Scale: 1"=500'*
West:	San Diego Bay

Date: 1964, 1966	*Scale: 1"=500'*
Subject Property:	The property land has been expanded westward with several new structures present along the west side
North:	No significant changes noted with the exception of new buildings that appear to be used by Rohr Inc.
South:	No significant changes noted with the exception of increased land and structures used by Rohr for manufacturing
East:	Building 29 is present on Parcel A including another smaller building on the south side of Building 29 that is no longer present
West:	New vacant land created by dredging San Diego Bay with Marina Parkway with new structures present in 1966 (Parcel H-3)

Date: 1970, 1979, 1985, 1989, 1994, 1996, 2002, 2005, 2009	*Scale: 1"=500'*
Subject Property:	Building 1 appears to be similar to its current configuration with multiple surrounding auxiliary structures. By 2002, the three side-by-side rectangular buildings are no longer present along the northwest side of the property, and the area is used as an exterior storage yard. Also, in 2002, the existing WWTP is visible
North:	A new large warehouse building (Building 61 on Parcel C) is present which displaced the former sewage treatment plant including additional buildings used by Rohr Inc. In 1979, new buildings were present to the northeast (Parcel A - Buildings 99 and 100)
South:	Multiple manufacturing buildings are present on the South Parcel used by Rohr Inc.
East:	Two industrial buildings are present. By 1996, the smaller structure on the south side of Building 29 was no longer present
West:	Marina Parkway is present beyond which is a large surface parking lot and exterior storage lot with industrial structures beyond. In 1985, the Chula Vista Marina is depicted further southwest

Date: 2012, 2016	*Scale: 1"=500'*
Subject Property:	No significant changes noted
North:	No significant changes noted
South:	The South Parcel buildings appear to have been demolished with the concrete slab and/or building outlines still visible
East:	No significant changes noted
West:	The area appears to have been demolished with the outline of former buildings still visible. By 2016, this area is used as a large surface parking lot

Copies of reviewed aerial photographs are included in Appendix B of this report.

3.2 Fire Insurance Maps

Partner reviewed the collection of Sanborn Fire insurance maps from EDR on January 12, 2021. The following was observed on the subject property and adjacent properties during the fire insurance map review:

Date: 1918	
Subject Property:	The northern side of the property is depicted as vacant land. The south side is not included on the map
North:	The area is developed with the International Magnesite Company manufacturers of magnesite mineral. This facility included a mill, drying bins, storage buildings, a laboratory, offices, a small transformer house, a fuel tank, sheds, and a rail spur with platform. The area to the northeast is depicted as vacant
South:	Area not included on map
East:	Area not included on map
West:	Area not included on map

Date: 1926	
Subject Property:	A small mill is depicted at the northeast corner of the subject property named R&H Tyce manufacturers of tycrete building material. The mill included one building sectioned into a paint shop, office and laboratory, storage bins and grinding area. the remainder of the north side of the property was depicted as vacant
North:	No significant changes noted
South:	Area not included on map
East:	Area not included on map
West:	Area not included on map

Date: 1949, 1950	
Subject Property:	The property is developed with the same mill building, which is slightly larger, occupied by Pioneer Pyrophyllite Manufacturing Company (insect powder mfrs), which includes a dwelling and storage garage on the west side of the mill. Other lettering on the map cannot be determined; however, it is known the property was developed and occupied for aerospace manufacturing
North:	G Street is depicted beyond which is the same mill building with additional new structures present labeled as Aircraft Engineering Service. The new buildings are labeled as office, machine shops and a plating shop
South:	Area not included on map
East:	Area not included on map
West:	Area not included on map

Date: 1962	
Subject Property:	The property continues to be occupied by Pioneer Pyrophyllite Manufacturing Company along with a notation of U.S. Government Rohr Aircraft Company on a building to the west of the mill. No other buildings are uses are included on the map
North:	Several new buildings are depicted labeled as machine shops occupied by Tyce Engineering Corporation
South:	Area not included on map
East:	Area not included on map
West:	Area not included on map

Copies of reviewed Sanborn Maps are included in Appendix B of this report.

3.3 City Directories

Partner reviewed historical city directories obtained from EDR on January 29, 2021, for past names and businesses that were listed for the subject property and adjacent properties. The findings are presented in the following table:

City Directory Search for 850 Lagoon Drive (Subject Property)	
Year(s)	**Occupant Listed**
1955	Pioneer Pyrophyllite Producers insect powder mfrs and Redlite Aggregate Company building materials (848 G Street)
1956	Pioneer Pyrophillite Producers Inc. (802 G Street)
1992	No listings on Lagoon Drive or G Street
1995	No listings on Lagoon Drive or G Street
2000	Charles Johnston (850 Lagoon Drive)
2005	Goodrich Corporation and Goodrich Corporation Aerostructure Group (850 Lagoon Drive)
2010	Goodrich Aerostructures Group (850 Lagoon Drive)
2014	Goodrich Aerostructures (850 Lagoon Drive)
2017	Goodrich Aerostructures (850 Lagoon Drive)

According to the city directory review, the subject property has been used for manufacturing operations dating back to the 1950s. It appears that the subject property used a different address on G or H Streets or Bay Boulevard prior to circa 1990s while operating under Rohr Inc.

City Directory Search for Adjacent Properties	
Year(s)	**Occupant Listed**
1955	Tyce Engineering Corporation aircraft parts (809 G Street)
1956	Rohr warehouse (444 Bay Boulevard); Tyce Engineering Corporation aircraft parts (809 G Street at Bay Boulevard); Rohr Aircraft Corporation (H Street at Bay Boulevard intersection)
1960	Rohr Aircraft Corporation warehouse (444 Bay Boulevard); Tyce Engineering Corporation aircraft parts (809 G Street at Bay Boulevard)
1964	Rohr Corporation Architectural Division, Rohr Aircraft Corporation warehouse (444 Bay Boulevard); Rohr Corporation parts mfrs (H Street at Bay Boulevard intersection)
1965	Tyce Engineering Corporation aircraft parts (809 G Street)
1969	Rohr Corporation, aircraft parts mfgs and Manning's Rohr Cafeteria (800 H Street); Rohr Corporation Antenna Division (444 Bay Boulevard)
1973	Rohr Industries Inc., aircraft parts mfgs (800 H Street)
1985	Rohr Ind Inc. (H Street)

According to the city directory review, the adjacent properties have been occupied by aerospace manufacturing operations by Rohr Inc. and Tyce Engineering Corporation dating back to the 1950s.

Copies of reviewed city directories are included in Appendix B of this report.

3.4 Historical Topographic Maps

Partner reviewed historical topographic maps obtained from EDR on January 11, 2021. The following was observed on the subject property and adjacent properties during the topographic map review:

Date: 1904	
Subject Property:	The property is depicted as undeveloped land that is partially located within the natural boundary of the San Diego Bay, a natural harbor
North:	Undeveloped land and harbor/wetlands
South:	Undeveloped land and harbor/wetlands
East:	Coronado Railroad tracks beyond which is undeveloped land
West:	San Diego Bay

Date: 1930	
Subject Property:	Four small structures are depicted on the subject property along the north and south sides. The north structures are most likely associated with the historical tycrete mill
North:	G Street is present beyond which are several small structures associated with historical manufacturing operations in this area along with San Diego Bay and likely wetlands
South:	The foot of H Street is present beyond which is undeveloped land and San Diego Bay
East:	San Diego and Arizona Eastern railroad right-of-way beyond which are several small structures that are likely residences and farm related structures
West:	San Diego Bay

Date: 1942, 1943, 1944	
Subject Property:	Three small structures are depicted along the north side of the property along G Street including a rail spur that crosses the corner of the subject property and enters the north adjacent property's manufacturing site
North:	G Street is present beyond which are several small structures associated with historical manufacturing operations in this area along with San Diego Bay and likely wetlands
South:	Undeveloped land and San Diego Bay (no structures or uses are depicted)
East:	San Diego and Arizona Eastern railroad right-of-way beyond which are several small structures that are likely residences and farm related structures
West:	San Diego Bay

Date: 1953	
Subject Property:	Six distinct structures are depicted. The west side of the property is within the San Diego Bay
North:	G Street is present beyond which is undeveloped land and wetlands. No buildings are depicted
South:	Four distinct buildings are depicted. H Street does not extend along the subject property
East:	Railroad right-of-way followed by several small industrial structures. A new freeway 101 is present just beyond
West:	San Diego Bay

Date: 1967	
Subject Property:	The subject property land has expanded westward due to dredging of the Bay. Additional buildings and sheds are present including ASTs. A rail spur enters the subject property from the South Parcel next to the ASTs.
North:	G Street is present beyond which is a sewage disposal site and several small (former) industrial buildings
South:	Rohr manufacturing buildings are present which was expanded due to dredging of the Bay
East:	Parcel A Building 29 and a second smaller industrial building are depicted along with smaller auxiliary buildings along the east side of the parcel
West:	Marina Parkway is present beyond which are three industrial buildings and open space that was used for parking

Date: 1975, 1991	
Subject Property:	Building 1 is present in the center of the property that is shaded purple indicating new construction from prior maps. Building 1 became one large structure. Multiple additional buildings are present around Building 1
North:	A new warehouse building is present identified a Building 61 on Parcel C along with smaller older structures
South:	Several structures are present on the South Parcel, some of which are shaded purple indicating new development or expansion of older buildings
East:	No significant changes noted
West:	No significant changes noted

Date: 1996	
Subject Property:	Only Building 1 is depicted
North:	Only Building 61 on Parcel C is depicted beyond G Street. The remaining area is shaded for general urban development
South:	No significant changes noted
East:	Railroad right-of-way followed by Building 29. No other buildings are depicted
West:	No structures or uses are depicted. The area is shaded for general urban development

Date: 2012	
Subject Property:	No structures or uses are depicted, only the surrounding streets
North:	No structures or uses are depicted, only the surrounding streets
South:	No structures or uses are depicted, only the surrounding streets
East:	No structures or uses are depicted, only the surrounding streets
West:	No structures or uses are depicted, only the surrounding streets

Copies of reviewed topographic maps are included in Appendix B of this report.

4.0 REGULATORY RECORDS REVIEW

4.1 Regulatory Agencies

4.1.1 State Department

Regulatory Agency Data	
Name of Agency:	California Environmental Protection Agency (Cal EPA) California Department of Toxic Substances Control (DTSC)
Point of Contact:	http://www.envirostor.dtsc.ca.gov/public/ http://hwts.dtsc.ca.gov/report_search.cfm?id=5 https://siteportal.calepa.ca.gov
Agency Phone Number:	(800) 728-6942
Date of Contact:	February 2021
Method of Communication:	Online
Summary of Communication:	The EnviroStor database is the DTSC's data management system for tracking cleanup, permitting, enforcement, and investigation efforts at hazardous waste facilities and sites with known contamination or sites where there may be reasons to investigate further. No records were identified for the subject property on the EnviroStor database. The on-going investigation and cleanup occurring at the subject property is under the jurisdiction of the SDRWQCB and not the State DTSC at this time. The DTSC Hazardous Waste Tracking System (HWTS) was researched for hazardous waste manifest data submitted to the California DTSC. Rohr Inc., a Collins Aerospace Company at 850 Lagoon Drive is identified on the HWTS database dating back to 1993 for large quantities of hazardous waste generated at the subject property that are classified under multiple different waste codes. Waste codes include but are not limited to aqueous solutions with organic residues and metals, metal sludge, asbestos-containing waste, metal dust and machining waste, organic and inorganic solid waste, halogenated and oxygenated solvents, hydrocarbon solvents, solvent mixture, waste oil and mixed oil, tank bottom waste, pesticide production waste, adhesives, PCBs, latex waste, pharmaceutical waste, paint sludge, unspecified sludge waste, laboratory waste, baghouse waste, photochemicals, contaminated soils from site cleanups, empty containers, and others. RCRA waste codes are also reported dating back to 1993 for corrosives, metals, solvents, and wastewater treatment sludge from chemical conversion coating of aluminum. Some of the waste materials were generated only periodically or once or twice. These wastes were manifested for off-site disposal. Hazardous waste is no longer generated at the subject property. Partner reviewed the CalEPA California Environmental Reporting System (CERS) database for regulatory and chemical inventory

information. CERS is the statewide web-based system that supports the electronic exchange of required Unified Program (CUPA) information among businesses, local governments and the U.S. EPA. The subject property is identified on the CERS database under the name of Rohr Inc., a Collins Aerospace Company at 850 Lagoon Drive as a RCRA Large Quantity Generator, a hazardous waste generator, chemical storage facility, and aboveground petroleum storage tank site. The start date for inclusion in the CERS database is listed as July 2013. The CERS database lists 113 individual chemicals that were used and stored at the subject property during the time the facility was active. The chemicals range from various compressed gases, petroleum-based oils, acids, solvents, alcohols, and multiple waste substances. No violations are reported. The last inspection date is listed as April 27, 2018, by the local CUPA agency.

Copies of pertinent documents are included in Appendix B of this report.

4.1.2 County Department of Environmental Health

Regulatory Agency Data	
Name of Agency:	San Diego County Department of Environmental Health (DEH) – CUPA Agency
Point of Contact:	https://www.sandiegocounty.gov/content/sdc/deh/doclibrary/ https://www.civicdata.com
Agency Phone Number:	(858) 505-6700
Date of Contact:	February 2021
Method of Communication:	Telephone
Summary of Communication:	This agency maintains records pertaining to hazardous materials and hazardous waste inspections and permitting, site investigation and remediation and USTs dating back to circa 1975. This agency has the authority to open case files for initial site investigations where soil impacts are discovered or suspected. Cases are referred to the SDRWQCB when groundwater impacts are discovered. According to reviewed information, this agency maintains at least seven historic case files for the subject property dating back to the 1980s pertaining to former USTs, salt bath, and degreasers, which were either closed (no further action) or were referred to the SDRWQCB due to groundwater impacts identified in those areas, which are currently being investigated under the current 1998 CAO No. 98-08. According to a records search, no violations or active USTs are reported at this time in connection with the subject property address, and no active cases are reported at this time. Information from the DEH indicates a pending inspection dated July 2020. It appears that a final inspection of the facility may be required once it is fully decommissioned.

Copies of pertinent documents are not included in Appendix B of this report.

4.1.3 Air Pollution Control Agency

Regulatory Agency Data	
Name of Agency:	San Diego Air Pollution Control District (SDAPCD)
Point of Contact:	www.sdapcd.org
Agency Phone Number:	(858) 586-2600
Date of Contact:	February 2021
Method of Communication:	Online and Telephone
Summary of Communication:	According to information from the SDAPCD, 125 permits have been retired in association with the subject property address. Based on reviewed information, the subject property formerly maintained air emission permits for various machinery including spray booths, degreasers, foundry sand aerator, coating operations, abrasive blasting, caustic chemical milling tank, diesel engine generators, a melting pot, and others. The machinery is no longer present or will

Regulatory Agency Data	
	be removed from the subject property in the near future and is not currently maintained or operational.

Copies of pertinent documents are included in Appendix B of this report.

4.1.4 State Water Resources Control Board

Regulatory Agency Data	
Name of Agency:	State Water Resources Control Board – GeoTracker Database
Point of Contact:	http://geotracker.waterboards.ca.gov/default.asp Mr. Tom Alo, Case Worker (619) 521-3375
Agency Phone Number:	(619) 516-1990 (San Diego RWQCB)
Date of Contact:	February 2021
Method of Communication:	Online and Telephone
Summary of Communication:	GeoTracker is the State Water Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater. GeoTracker contains records for sites that require cleanup, such as Leaking Underground Storage Tank (LUST) Sites, Department of Defense Sites, and Cleanup Program Sites. GeoTracker also contains records for various unregulated projects as well as permitted facilities including: Irrigated Lands, Oil and Gas production, operating Permitted USTs, and Land Disposal Sites. GeoTracker portals retrieve records and view integrated data sets from multiple State Water Board programs and other agencies. The subject property is identified on the GeoTracker database in connection with an ongoing investigation and cleanup for site wide environmental impacts resulting from historical releases of hazardous substances to the subsurface including into the storm drain conveyance system and the San Diego Bay. The subject property is currently being investigated under the regulatory oversight of the SDRWQCB under a CAO No. 98-08 dated April 1998 to Rohr Inc. The CAO requires the cleanup and abatement of wastes discharged from Rohr's historical manufacturing operations at Parcel B. Aerospace manufacturing operations were conducted at the subject property from circa 1941 until approximately one year ago, which involved the operation of heavy machinery within below grade vaults, multiple solvent degreasers, paint spray booths, multiple USTs, and other equipment and the use of various hazardous substances including halogenated VOCs such as TCE, metals (aluminum, titanium, lead and steel), petroleum hydrocarbons, PAHS, PCBs, and other substances identified as COC that have been reported in soil, soil vapor and groundwater underlying the subject property. TCE and 1,1,1-TCA were historically used as degreasing solvents and have been the subject of soil, soil vapor and groundwater investigations at

the subject property facility dating back to the 1980s.

Interim remedial actions are currently underway on the adjacent parcel located downgradient of the subject property source areas, known as Parcel H-3, pursuant to the 1998 CAO No. 98-08. Redevelopment activities are planned for Parcel H-3 in the coming months. Implementation of the interim remedy on Parcel H-3 occurred from April to September 2020 and includes four permeable reactive barriers (PRBs), injection of in situ chemical reduction (ISCR) and enhanced in situ bioremediation (EISB) amendments. The PRBs were placed as such to capture impacts originating from the subject property in hopes to prevent contamination from reaching the San Diego Bay. The SDRWQCB is currently preparing a new site wide CAO No. R9-2020-0099, which will address the cleanup remedies and timeline of all wastes discharged to soil, soil vapor, and groundwater from the manufacturing operations at the North Campus Property (subject property). CAO No. R9-2020-0099 will supersede CAO No. 98-08 except for the interim remedial actions at Parcel H-3, which will continue to be conducted under CAO No. 98-08.

The new CAO No. R9-2020-0099 is not yet final, although remediation work plans and feasibility studies are underway at the subject property to address soil and groundwater impacts. It is being surmised that a soil vapor extraction system may be employed as well as targeted efforts for groundwater; however, remedial action plans have not been determined or finalized.

A considerable number of investigations have been conducted on the subject property since the late 1980s. Currently there are several hot spots and comingled groundwater plumes at the subject property that include but are not limited to a 1,1,1–TCA/TCE AST that was formerly located west of former Building 57; the oiler shed located at the middle south side of the subject property; and a vapor degreaser line aligned east/west through Building 1. COC in these specific areas included TCE, 1,1,1-TCA and their degradation products and hexavalent chromium (salt bath area inside Building 1).

According to an Annual Groundwater Monitoring and Sampling Report dated November 21, 2019, TCE was detected more frequently and at higher concentrations than other VOCs. The maximum TCE concentration was detected in monitoring well NCW-14A (31,000 micrograms per liter (µg/L)). Well NCW-14A is completed in Zone A and is located immediately downgradient of the suspected Oiler Shed release area. TCE concentrations in Zone A decrease downgradient of well NCW-14A. At well NCW-020, which is located approximately 500 feet downgradient of NCW-14A, the reported TCE concentration

Regulatory Agency Data	
	was 79 µg/L. The highest VOC concentrations in Upper Zone B were detected in well NCW-004B and NCW-006A (both 8,400 µg/L TCE). These wells are located offsite and downgradient of the former TCE/1,1,1-TCA AST area adjacent to former Building 57. The VOC concentrations in Lower Zone B remain substantially less than in the shallower groundwater zones. No active remediation systems are present on Parcel B; only groundwater monitoring wells at this time. The identified soil and groundwater impacts at the subject property and current regulatory status is considered to be a REC.

Copies of pertinent documents are included in Appendix B of this report.

4.1.5 Building Department

Regulatory Agency Data	
Name of Agency:	City of Chula Vista Building Department (CVBD), Development Services
Point of Contact:	https://www.chulavistaca.gov/departments/development-services/apply-for-a-permit/online-permit-services
Agency Phone Number:	(619) 691-5272
Date of Contact:	February 2021
Method of Communication:	Online public records request
Summary of Communication:	Multiple permits are on file for 850 Lagoon Drive with the CVBD through their online portal dating back to 1992 for various tenant improvements, seismic retrofit to Building 1, new construction, utility installations, interior demolition of walls, a new storm water collection basin (2001), demolition of the South Parcel buildings in 2005, and many others. The address of 850 Lagoon Drive pertains to the entire Rohr Inc. facility; therefore, a large number of permits have been issued for this address, many of which do not pertain to the subject property. Based on other reliable sources of historical information reviewed and based on the pending demolition and redevelopment of the subject property, historical permits (prior to 1992) were not researched.

Copies of pertinent documents are not included in Appendix B of this report.

4.1.6 Planning Department

Regulatory Agency Data	
Name of Agency:	City of Chula Vista Planning Department
Point of Contact:	https://gisweb.chulavistaca.gov/zonefinder/
Agency Phone Number:	(619) 691-5101
Date of Contact:	February 2021
Method of Communication:	Online
Summary of Communication:	According to records reviewed, the subject property is currently

Regulatory Agency Data	
	zoned Local Coastal Program Specific Plan Area by the City of Chula Vista in the Chula Vista Bayfront Area.

Copies of pertinent documents are included in Appendix B of this report.

4.1.7 Oil & Gas Exploration

Regulatory Agency Data	
Name of Agency:	California Department of Conservation (DOC), Geologic Energy Management Division (CalGEM)
Point of Contact:	https://maps.conservation.ca.gov/doggr/wellfinder/#close
Agency Phone Number:	(916) 322-1080
Date of Contact:	February 2021
Method of Communication:	Online
Summary of Communication:	According to the DOC CalGEM database, no historical oil or gas wells are located on the subject property, nor is the subject property mapped with the boundary of a designated oil field.

Copies of pertinent documents are included in Appendix B of this report.

4.1.8 Assessor's Office

Regulatory Agency Data	
Name of Agency:	San Diego County Assessor (SDCA)
Point of Contact:	https://arcc.sdcounty.ca.gov/Pages/assessor.aspx
Agency Phone Number:	(619) 236-3771
Date of Contact:	February 2021
Method of Communication:	Online
Summary of Communication:	According to records reviewed, the subject property is identified by APNs 571-330-24, 571-330-27, and 571-330-29. The current owner is reported as Rohr Inc., who has owned the subject property since circa 1950s and which has undergone several name changes.

Copies of pertinent documents are included in Appendix B of this report.

4.1.9 California Solid Waste Information System (SWIS)

Regulatory Agency Data	
Name of Agency:	CalRecycle
Point of Contact:	https://www2.calrecycle.ca.gov/SolidWaste/Site/Search
Agency Phone Number:	(916) 322-4027
Date of Contact:	February 2021
Method of Communication:	Online
Summary of Communication:	No records were identified pertaining to past or present landfill activities at the subject property or adjacent areas.

A copy of pertinent documents is not included in Appendix B of this report.

4.2 Mapped Database Records Search

Information from standard federal, state, county, and city environmental record sources was provided by Environmental Data Resources, Inc. (EDR). Data from governmental agency lists are updated and integrated into one database, which is updated as these data are released. The information contained in this report was compiled from publicly available sources and the locations of the sites are plotted utilizing a geographic information system, which geocodes the site addresses. The accuracy of the geocoded locations is approximately +/-300 feet.

Using the ASTM definition of migration, Partner considers the migration of hazardous substances or petroleum products in any form onto the subject property during the evaluation of each site listed on the radius report, which includes solid, liquid, and vapor.

4.2.1 Regulatory Database Summary

Radius Report Data

Database	Search Radius (mile)	Subject Property	Adjacent Properties	Sites of Concern
Federal NPL or Delisted NPL Site	1.00	N	N	N
Federal CERCLIS Site	0.50	N	N	N
Federal CERCLIS-NFRAP Site	0.50	N	N	N
Federal RCRA CORRACTS Facility	1.00	N	N	N
Federal RCRA TSDF Facility	0.50	N	N	N
Federal RCRA Generators Site (LQG, SQG, CESQG)	0.25	**Y**	**Y**	N
Federal IC/EC Registries	0.50	N	N	N
Federal ERNS Site	Subject Property	N	N	N
State/Tribal Equivalent NPL	1.00	N	N	N
State/Tribal Equivalent CERCLIS	1.00	N	N	N
State/Tribal Landfill/Solid Waste Disposal Site	0.50	N	N	N
State/Tribal Leaking Storage Tank Site	0.50	N	N	N
State/Tribal Registered Storage Tank Sites (UST/AST)	0.25	**Y**	**Y**	N
State/Tribal Voluntary Cleanup Sites (VCP)	0.50	N	N	N
State/Tribal Spills	0.50	N	N	N
Federal Brownfield Sites	0.50	N	N	N
State Brownfield Sites	0.50	N	N	N
State HWTS Manifest	Varies	**Y**	**Y**	N
State Waste Discharge Requirements	Varies	**Y**	N	N
State Cleanup Site	Varies	**Y**	**Y**	N
County Regulated Site	Varies	**Y**	**Y**	N
EDR MGP	Varies	N	N	N
EDR US Hist Auto Station	Varies	N	N	N
EDR US Hist Cleaners	Varies	N	N	N

4.2.2 Subject Property Listings

The subject property is identified on multiple Federal, State and local regulatory databases in connection with historical aerospace manufacturing operations, hazardous waste activity, air emissions, storm water tracking, and several release cases under the address of 850 Lagoon Drive. The release cases were investigated, remediated and received regulatory case closure letters from the SDRWQCB or the local San Diego County DEH; however, a majority of the historical cases continue to be investigated as part of the site wide groundwater investigation and cleanup efforts due to groundwater impacts identified in those areas such as the salt bath area in Building 1 and the oiler shed. The release events as identified in the EDR report and GeoTracker database include the following:

- BF Goodrich Aerospace Facility, 850 Lagoon Drive, UST closure of one 10,000-gallon diesel tank adjacent to former Building 57 in August 1987. Impacted soils around the UST were removed and disposed along with 500 gallons of impacted water. This UST received regulatory closure from the County DEH on August 2, 2002.
- UTC Aerospace Systems, Former North Oiler Shed, Building 1. The Oiler Shed consists of a covered storage area outside the south end of Building 1 where historically new oil product was stored and used cutting oil was recovered from scrap metal shavings. An undocumented 550-gallon UST was discovered and removed in 2000 during renovations in the oiler shed area that contained petroleum hydrocarbons and VOCs. The tank had holes and corrosion, and a groundwater sample identified elevated concentrations of TCE and other VOCs. This UST was granted closure on January 3, 2013, for total recoverable petroleum hydrocarbons (TRPH) only, while the remaining VOC impacts are being addressed by the site wide CAO. This area of the subject property is considered to be a hot spot.
- Goodrich Aerostructures, Tank 6, Oiler Shed Sump, Building 1. This sump was 2'x2' and three feet deep including a long drainage trench where machine coolant was collected, recycled and dispensed. Initially equipment and metal chip tubs were drained of oil or coolant and accumulated in the trough and sump where it was then pumped into an AST up until 1992. This sump was granted closure on June 1, 2012, for petroleum hydrocarbons only, while the remaining VOC impacts are being addressed by the site wide CAO.
- Goodrich Aerostructures – North Campus – Salt Bath C70, 850 Lagoon Drive, the former salt bath consisted of four below-grade structures that were considered to be USTs. The salt baths were used in the aluminum forming process and formerly contained a hexavalent chrome additive to control corrosion. The operation is the subject of an ongoing evaluation, due to hexavalent chromium found in groundwater in this area. Soil beneath the salt baths was reportedly excavated and disposed. The Salt Bath C70 was administratively closed on May 8, 2019, however potential contaminant releases from it are part of the larger cleanup and remediation efforts at the subject property as a whole.

- Goodrich Aerostructures Machine Shop Sump, Tank No. 34. The sump was located in the southern portion of Building 1 and was constructed in 1943 and consisted of a 4-foot by 4-foot concrete structure that was approximately 6 feet deep (total capacity: approximately 720 gallons) and considered to be an UST by the DEH. Hydraulic oil was collected from larger, floor-mounted milling machines (N/C machines) that were plumbed to the sump. The N/C machines were supplied with hydraulic oil from a central hydraulic unit. Hydraulic oil was transferred to each N/C machine through utility trenches via hydraulic lines. The Tank 34 was administratively closed on May 8, 2019, however potential contaminant releases from it are part of the larger cleanup and remediation efforts at the subject property as a whole.
- Goodrich Aerostructures/Rohr – Goodrich Aerostructures North Campus, 850 Lagoon Drive. The regulatory status is reported as *Open-Assessment & Interim Remedial Action as of March 13, 2020*. This case pertains to the on-going investigation and cleanup of the subject property discussed in Section 4.1.4 above. In summary, Parcel B as part of the Rohr Inc. North Campus property that includes Parcels A, B and C, was issued a CAO in 1998 for the investigation and remediation of environmental impacts at the subject property from historical manufacturing operations. Site remedial action plans for soil, soil vapor and groundwater and a Human Health Risk Assessment (HHRA) for Parcel B is in progress. Health-based remediation goals (HBRGs) are being developed for Parcel B, which will drive the remediation at Parcel B.

4.2.3 Adjacent Property Listings

Adjacent properties under investigation for soil and/or groundwater impacts include the following:

- Chula Vista Bayfront Master Plan Development (CVBMP) is a cooperative public/private planning effort of the Port of San Diego, the City of Chula Vista, and Pacifica Companies that totals approximately 556 acres of land. The CVBMP includes the former South Bay Power Plant demolition, assessment, and cleanup area, the Chula Vista Marina area and a former portion of the Rohr Inc./BF Goodrich facility property (adjacent South Campus and Parcel H-3). The purpose of the project is to develop a master plan that transformers underutilized industrial properties into a thriving waterfront resort destination. This project has a regulatory status of *Open-Assessment & Interim Remedial Action as of May 10, 2017*, under the jurisdiction of the SDRWQCB for environmental impacts to soil, soil vapor and groundwater from VOCs, metals, PCBs, and petroleum hydrocarbons. The investigation is ongoing.
- Rohr Inc., South Campus (south of H Street) was formerly developed with multiple buildings operated by Rohr Inc. dating back to 1941, where manufacturing of engine components for use in the aviation and aerospace industry was performed (similar to the subject property). Chemicals stored at the South Campus Property and used during manufacturing operations have been found in the soil, soil gas, and groundwater as reported in site environmental investigation reports and groundwater monitoring reports. The group of chemicals discharged include, but are not limited to, VOCs, metals, petroleum hydrocarbons, PAHs, and PCBs.

In 1998, the SDRWQCB issued CAO No. 98-08 to Rohr, Inc. that requires the cleanup and abatement of wastes discharged from Rohr's manufacturing operations located at 850 Lagoon Drive (North Campus Property and South Campus Property). On July 13, 1999, the City of Chula Vista, the Redevelopment Agency of the City of Chula Vista, the Port of San Diego, and Rohr entered into a Relocation Agreement. Thirty-eight acres of Rohr-owned property were transferred to the Port of San Diego and a 28-acre lease of Port tidelands was terminated as part of this Relocation Agreement for the entire South Campus site. In 2002, Rohr vacated the South Campus Property and consolidated manufacturing operations to the North Campus Property (subject property). In 2007, the Port of San Diego demolished all buildings at the South Campus. In 2014, the SDRWQCB issued CAO No. R9-2014-0019, which requires the cleanup or abatement of all wastes discharged to soil, soil gas, and groundwater from the manufacturing operations at the South Campus Property. CAO No. R9-2014-0019 supersedes CAO No. 98-08. Implementation of the soil Remedial Action Plan (RAP) is currently underway and has not yet received final regulatory closure. Groundwater monitoring and remedial efforts are ongoing.

- Rohr, Inc., North Campus – Parcel A, 850 Lagoon Drive (adjacent parcel to the east). The regulatory status is listed as *Open-Site Assessment as of November 17, 2017*. The site comprises two parcels that are part of the Rohr manufacturing facility that include Buildings 29, 99 and 100. Industrial activities and historical chemical use on Parcel A were more limited compared to the main manufacturing portions of the facility located on Parcel B and the former South Campus. Building 29 was primarily used for tooling, machining, and office space. At one time, the northernmost portion served as the maintenance department. Rohr purchased Buildings 99 and 100 in 1986 and primarily used them for administrative purposes. Prior to Rohr's ownership, Parcel A had other uses. It is reported that Parcel A buildings were previously equipped with USTs containing gasoline, diesel and waste oil, two wastewater clarifiers, ASTs, a paint spray booth, solvent degreasers, and other equipment. Soil, soil vapor and groundwater investigations are ongoing at Parcel A. According to a November 2020 Conceptual Site Model (CSM) report for Parcel A, a Human Health Risk Assessment (HHRA) for Parcel A is in progress. Health-based remediation goals (HBRGs) are being developed for Parcel A. There were no environmental concerns related to soil or soil vapor at Buildings 99 and 100. It is reported in the CSM for Parcel A that VOC releases have migrated through the soil to groundwater, resulting in a groundwater plume that extends westward below Parcel B (subject property).

Based on the findings, vapor migration is a potential environmental concern at this time.

4.2.4 Sites of Concern Listings

No additional sites of concern are identified in the regulatory database report.

4.2.5 Orphan Listings

Thirteen orphan listings are identified in the EDR regulatory database report that include the subject property and nearby or adjacent parcels of land. Goodrich Corporation DBA Rohr Inc. at Foot of H Street is listed on the County HMMD (Hazardous Materials Management Division) database for historical hazardous materials inventory dated 2012 as well as UST records maintained by the County. Up to 50 USTs and exempt vaults are reported at the subject property. The USTs are listed as removed or closed, while the vaults (sumps) are listed as exempt.

Three solid waste landfills are listed, which are not located in the immediate vicinity of the subject property. The Chula Vista Bayfront Master Plan – South Bay Power Plant (Bay Sediment Assessment) site is listed that was discussed in Section 4.2.3. The remaining orphan listings are not located in the vicinity of the subject property and are not expected to represent a significant environmental concern.

A copy of the regulatory database report is included in Appendix C of this report.

5.0 USER PROVIDED INFORMATION AND INTERVIEWS

In order to qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the *Brownfields Amendments*), the *User* must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. The *User* should provide the following information to the *environmental professional*. Failure to provide this information could result in a determination that *all appropriate inquiries* is not complete. The *User* is asked to provide information or knowledge of the following:

- Review Title and Judicial Records for Environmental Liens and AULs
- Specialized Knowledge or Experience of the User
- Actual Knowledge of the User
- Reason for Significantly Lower Purchase Price
- Commonly Known or *Reasonably Ascertainable* information
- Degree of Obviousness
- Reason for Preparation of this Phase I ESA

Fulfillment of these user responsibilities is key to qualification for the identified defenses to CERCLA liability. Partner requested our Client to provide information to satisfy User Responsibilities as identified in Section 6 of the ASTM guidance.

Pursuant to ASTM E1527-13, Partner requested the following site information from PW Wohl G Street LLC (User of this report).

User Responsibilities

Item	Provided by User	Not Provided by User	Discussed Below	Does Not Apply
AAI User Questionnaire		**X**	**X**	
Title Records, Environmental Liens, and AULs		**X**	**X**	
Specialized Knowledge	**X**		**X**	
Actual Knowledge	**X**		**X**	
Valuation Reduction for Environmental Issues	**X**		**X**	
Identification of Key Site Manager	**Section 5.1.3**		**X**	
Reason for Performing Phase I ESA	**Section 1.1**		**X**	
Prior Environmental Reports	**X**		**X**	
Other	**X**		**X**	

5.1 Interviews

5.1.1 Interview with Owner

Mr. Rick Siordia and Mr. David Danchise with Rohr Inc., subject property owner representatives, were not aware of any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the subject property; any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the subject property; or any notices from a governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.

Mr. Siordia and Mr. Danchise further stated that the property is currently being decommissioned where equipment is being removed from the property in anticipation of redevelopment. Mr. Siordia and Mr. Danchise stated that no active USTs or industrial processes are being conducted and that manufacturing activities ceased approximately one year ago. Small quantities of hazardous substances including petroleum products are still present in support of decommissioning and dismantling activities of large pieces of equipment such as ovens, spray booths and other large units still present in the building. The WWTP is still present but not operational with several associated ASTs having been removed. Mr. Siordia and Mr. Danchise are aware of the ongoing investigation and cleanup of the subject property and provided general status information.

5.1.2 Interview with Report User

Mr. Emil Wohl, report user, is not aware of any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the subject property; any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the subject property; or any notices from a governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.

According to Mr. Wohl, the facility is actively decommissioning in anticipation of redevelopment. Mr. Wohl is aware of the ongoing investigation and cleanup of the subject property and provided general status information for the property.

5.1.3 Interview with Key Site Manager

Mr. Rick Siordia and Mr. Danchise acted as key site managers (see Section 5.1.1 above).

5.1.4 Interviews with Past Owners, Operators and Occupants

Interviews with past owners, operators and occupants were not conducted since information regarding the potential for contamination at the subject property was obtained from other sources.

5.1.5 Interview with Others

As the subject property is not an abandoned property as defined in ASTM 1527-13, interview with others were not performed.

5.2 User Provided Information

5.2.1 Title Records, Environmental Liens, and Activity and Use Limitations (AULs)

Partner was not provided with title records or environmental lien and AUL information for review as part of this assessment. As a note, an EDR Environmental Lien and AUL Search report was prepared in April 2013 as part of a prior Phase I ESA prepared by URS; however, it does not appear to include the subject property APNs.

5.2.2 Specialized Knowledge

The User did have specialized knowledge of environmental conditions associated with the subject property at the time of the assessment in connection with the ongoing investigation and cleanup of the subject property due to historical manufacturing operations, which resulted in soil, soil vapor and groundwater impacts (see Section 4.0 for discussions).

5.2.3 Actual Knowledge of the User

The User was not aware of environmental liens and/or AULs encumbering the subject property or in connection with the subject property at the time of the assessment.

5.2.4 Valuation Reduction for Environmental Issues

The User was not aware of any reductions in property value due to environmental issues; however, a sale agreement for Parcel B reportedly has not been finalized according to Rohr Inc. personnel.

5.2.5 Commonly Known or Reasonably Ascertainable Information

The User did provide information that is commonly known or *reasonably ascertainable* within the local community about the subject property at the time of the assessment.

5.2.6 Previous Reports and Other Provided Documentation

Multiple prior reports were provided to Partner for review during the course of this assessment, some of which are discussed below. In addition, hundreds of investigations have been conducted for the Rohr Inc. facility that are posted to the State Water Resources Control Board GeoTracker website at: https://geotracker.waterboards.ca.gov. Partner reviewed the most current information on GeoTracker and spoke with the case manager (Mr. Tom Alo), the information from which is incorporated into this Phase I ESA report.

Phase I Environmental Site Assessment, UTAS Chula Vista, 850 Lagoon Drive, prepared by URS Corporation Americas (URS) dated April 2, 2013

URS prepared this report on behalf of United Technologies Aerospace Systems (UTAS) when UTAS acquired Goodrich Aerostructures Group. The format and content of this report were prepared in general accordance with ASTM International Standard Practice for Environmental Site Assessments: Phase I Site Assessment Practice E 1527-05 and the United States EPA's standards for All Appropriate Inquiry (AAI) at 40 CFR Part 312, with particular emphasis on historical operations. The report was prepared for the North Campus only and included a site reconnaissance visit, extensive regulatory and historical research, review

of prior environmental site assessment reports, and review of local physiographic and hydrogeologic conditions in the site vicinity.

The facility was described by URS as used primarily for manufacturing structural and engine components for aircraft. Industrial activities included metals casting and fabrication, and materials manufacturing, handling, assembly, and storage. The manufacturing process includes tool and die casting and shaping and milling of metal parts by machining and chemical processes. Support activities included maintenance and storage of vehicles, recycling of materials, and industrial wastewater treatment. Goodrich also operated a Cogeneration Plant that was constructed in 2001 on adjacent Parcel C. The Cogeneration Plant was operated by NORESCO and consisted of three Fairbanks Morse natural gas-fired internal combustion engines with 4,410 brake horsepower producing about 3,165 kilowatts of power. The Cogeneration plant is no longer present on Parcel C.

As of 2013, a considerable number of investigations of COCs in soil, groundwater and sediment at and downgradient of the subject property were conducted. Investigations were specific to certain source areas. Since issuance of the CAO by the RWQCB in 1998, much of the investigation conducted has focused on the site-wide occurrence of TCE and other VOCs in soil and groundwater associated with historic operations at the subject property and the investigation and corrective actions in storm water Outfall No 1 and other historical outfalls.

URS concluded that there were several locations of historical operations, former vessels, and vaults that are areas of potential concern that warrant further investigation. Some of the areas are coincident with current operations. Since the SWCS historically served as a conveyance for discharges of waste to the Bay, it was recommended at that time that the former outfall locations be investigated. Past investigations have also indicated the presence of COCs and debris along the former high tide line (shoreline).

Report Data Gap Assessment, Rohr Inc. North Campus, prepared by AECOM dated February 2016

AECOM (formerly URS Corporation Americas) prepared this report for Rohr Inc., a UTC Aerospace Systems Company. The purpose of the investigation was to assess the potential for migration of VOCs in groundwater from the North to the South Campus as directed by the RWQCB. This report addressed this request specific to the southern portion of the North Campus and includes an assessment of combined data that extends from the southern portion of North Campus to the northern portion of South Campus.

Multiple investigations have been conducted on the site since the late 1980s. Investigations prior to issuance of the CAO by the RWQCB in March 1998 were conducted under the regulatory oversight of the San Diego County DEH, and there were several subsurface structures that were designated as having had releases of hazard materials. The ensuing investigations and soil remediation activities initially focused on targeted locations that included a diesel-fuel UST (case closed), a 1,1,1–TCA/TCE AST that was formerly located west of the former location of Building 57, and the Salt Bath (C-70) in Building 1. Each of these features is no longer present on the subject property but are still considered hot spot areas. Constituents of concern (COCs) in these specific areas included TCE, 1,1,1-TCA and their daughter products, petroleum hydrocarbons (former) and hexavalent chromium.

The purpose of this focused investigation was to collect additional data for evaluating the presence of VOCs in groundwater both on and off-site. The investigation borings were generally placed along the boundary between the North and South Campuses to fill data gaps. The scope of work included the advancement of 15 CPT-MIP (Cone Penetrometer Technology/Membrane Interface Probe) borings (CPT-026 through CPT-040) and collected groundwater grab samples at each location to evaluate subsurface geology and groundwater quality and the analysis of the groundwater samples for VOCs and general water quality parameters.

In Zone A, there is contribution of VOCs from North Campus in the vicinity of former Building 45 located on the South Campus. There is a source of PCE, TCE, and 1,1-DCE (from 1,1,1-TCA) in Zone A near the Oiler Shed. Most of the plume derived from the Oiler Shed is migrating down-dip along a sand layer that starts above 25 ft bgs (Zone A) and dips down into Upper Zone B by the time the plume reaches CPT-028 located at the southwest corner of Parcel B. Isoconcentration maps included with this report show that chemicals of concern have migrated off site to the west and southwest in all water bearing zones, primarily in Zones A and Upper Zone B. TCE impacts are widespread across Parcel B in the shallowest groundwater Zone A then taper off in the lower B Zones.

Phase II Environmental Site Assessment, Project Springsteen Parcel B, 850 Lagoon Drive, prepared by Haley & Aldrich, Inc., dated January 2018

The report was prepared on behalf of UTC Aerospace Systems, Inc. (UTAS). The purpose of the Phase II was to investigate soil for the presence of COCs and characterize soil conditions at the subject property. The assessment included the advancement of 121 soil borings with the analysis of 246 soil samples and 43 groundwater samples from those borings for the presence of COC. Soil analytical results were compared to potentially relevant human health risk screening criteria for residential and commercial/industrial property uses, and groundwater protection levels developed for the adjacent South Campus. Groundwater analytical results were compared to California Maximum Contaminant Levels (MCLs) and San Francisco Bay Regional Water Quality Control Board vapor-intrusion screening levels. Haley & Aldrich concluded the following:

No additional major VOC sources were identified in soil with the exception of boring PB-026 located near the former foundry inside Building 1. No major VOC sources were identified along the former historical shoreline, except for one boring PB-109 placed between Building 1 and the WWTP.

The TCE concentrations in shallow groundwater at boring PB-050 inside Building 1 suggests that there could be additional sources in soil that have not been previously identified.

PCBs were not identified in soil within the historical manufacturing areas inside Building 1 with the exception of one boring location. No significant concentrations of PCBs were present in soil in the machine shop or oiler shed locations. PCBs were identified along the former historical shoreline and near former storm drain outfalls, including an area north of H Street that was previously identified and remediated. In addition, PCB analytical results for soil do not support the wide-spread use of PCB-containing cutting oils or fluids.

Petroleum hydrocarbons at concentrations above 1,000 mg/kg are present along the former historical shoreline near Building 50 and in the stretch forming area at boring PB-033 inside Building 1. Petroleum product was observed and remediated in the area of the existing WWTP in circa 2000 at the time the plant was constructed. Also, URS reported oily soil in the stretch forming area in 2013 (boring UT-46).

There were no significant concentrations of metals identified in soil within the historical manufacturing areas of the facility. The metals of concern appear to include antimony, lead and hexavalent chromium along the former historical shoreline and the former western drainage ditch. Further characterization and profiling will be needed prior to remediating soil.

Groundwater analytical results for the borings were generally consistent with the current understanding of the distribution of TCE in shallow groundwater across the property, found in various and comingled plumes. Certain VOCs are present in groundwater above their respective MCLs and commercial/industrial ESLs for vapor intrusion across the subject property.

PCBs were present in groundwater on the south side of the subject property at boring PB-122 along H Street at the H Street excavation area above the MCL.

Metals do not appear to be a significant concern in groundwater. There were four locations where one or more of the following metals was present above its MCL: antimony and lead at boring PB-24 at the east side of Building 1; cadmium at boring PB-031 in the former foundry area; chromium at boring PB-011 at the north side of the subject property; and nickel at boring PB-018 at the northwest corner of the subject property.

Indoor Air Screening Technical Memorandum, Rohr Inc., Building 1, prepared by Haley & Aldrich Inc., dated October 2018

This report was prepared on behalf of Rohr Inc., a UTC Aerospace Systems Company. Rohr requested indoor air screening in Building 1 as TCE has been found in soil and shallow groundwater (5 to 8 feet bgs) beneath the subject property. Building 1 was constructed in 1941 as the facility's main manufacturing building and the location where solvents were used. The assessment was conducted to assess the potential presence of TCE in indoor air, to identify potential preferential pathways for subsurface vapor intrusion and to evaluate whether response actions are necessary. Building 1 includes adjoining buildings that share a common wall or doorway including Buildings 22, 54 and 55. At the time of this assessment, portions of the building were being vacated in connection with downsizing of operations.

Investigations conducted since the 1980s have shown that soil and groundwater contain VOCs, primarily TCE, found to be present beneath the building slab at high concentrations. The highest TCE concentrations were generally located near historical degreasers, mechanical vaults and where solvents were used. Indoor air and preferential pathway screening were conducted in the building using direct-reading instruments. First a hand-held photoionization detector (PID) was used to measure total VOCs (TVOCs). As PID screening results fluctuate, the measurements were recorded in concentration ranges. PID screening was conducted at 88 locations in Building 1 and seven ambient outdoor locations. Following the breathing zone and preferential pathway screening with the PID, TCE measurements were collected and analyzed using a portable gas chromatograph/mass spectrometer (GC/MS) device.

TCE screening results were less than 8 µg/m3 EPA Region 9 Indoor Air Response Action Level for TCE, also identified by DTSC as the commercial/industrial worker accelerated response action level assuming an 8-hour workday. In certain areas of the building, TVOC measurements and TCE screening results were likely influenced by building ventilation and indoor chemical usage. There were some slab penetrations that appeared to be serving as a preferential pathway for subsurface vapor intrusion. Recommendations included sealing cracks, utility trench plate perforations and conduits then retesting those areas; conduct indoor air screening during winter months to evaluate the effect of closed doors on indoor air quality; and maintain good ventilation.

Conceptual Site Model (CSM), Rohr Inc. – North Campus, 850 Lagoon Drive, prepared by Haley & Aldrich, Inc., dated May 2020

Haley & Aldrich, Inc., submitted this report to the SDRWQCB on behalf of Rohr, Inc. for the North Campus, Parcels A, B, and C. The CSM was prepared to meet the requirements of a new Cleanup and Abatement Order (CAO) that will supersede CAO No. 98-08. The new CAO has not yet been issued. Rohr is in the process of decommissioning and selling portions of the North Campus.

The North Campus groundwater monitoring network consists of 55 monitoring wells, 30 of which are collocated clusters of three wells, and four of which are collocated clusters of two wells. The monitoring well network at the subject property comprises the following:

- Salt Bath Area Wells: MW1-1 through MW1-7 were installed near the former C-70 Salt Bath inside Building 1 to monitor total and hexavalent chromium concentrations in groundwater. The wells are screened in first encountered groundwater and are shallower than Zone A wells at the subject property.
- Former Building 57 Area Wells: MW57-1, -2, -3, -5, -6, and -7 were installed to monitor total petroleum hydrocarbons (TPH) and VOC concentrations in groundwater in the vicinity of a diesel-fuel UST and a 1,1,1–TCA/TCE AST that had been located west of former Building 57. Like the Salt Bath Area wells, the Building 57 Area wells are screened in first encountered groundwater and are shallower than Zone A wells at the subject property.
- Site-Wide Cluster Wells: Cluster wells NCW-001 though NCW-009 and NCW-013 each consist of three wells with screens completed in Zone A, Upper Zone B, or Lower Zone B. The wells were installed to monitor VOC concentrations and groundwater flow conditions Site-wide. Cluster wells NCW-006 thought -009 are on Parcel H-3 to the adjacent west of the subject property.
- Oiler Shed/North of Chula Vista Marina Monitoring Wells: NCW-014 and NCW-015 cluster wells consist of two wells with screens completed in Zone A and Upper Zone B; monitoring wells NCW-016 through NCW-020 are single monitoring wells completed in Zone A or Upper Zone B. The wells were installed in 2018 as part of the Oiler Shed and North of Marina investigation to monitor VOC concentrations and groundwater flow conditions in the area between the Oiler Shed and the Chula Vista Marina, due to off-site migration of contamination.

Soil and groundwater conditions have been extensively characterized on the North Campus. The following observations and information collected from the past Site investigation and remediation activities on the North and South Campuses have revealed the following:

- VOCs in soil are typically localized around former tanks and vaults.
- The occurrence of metals above DTSC-SLs for commercial/industrial property use or GPLs developed for the adjacent South Campus are typically found at former surface water features (former outfalls, shoreline, and along the former drainage features).
- PCBs are found mostly along the historical shoreline and outfalls. None were detected in the Machine Shop and Oiler Shed where petroleum hydrocarbons have been identified.
- Shallow groundwater is the primary vapor intrusion source. VOCs in soil in source areas also contribute to vapor intrusion.

Haley & Aldrich concluded that, in their opinion, the vadose zone soil at the subject property has been adequately characterized. Further evaluation of soil can be accomplished when implementing soil remedial action plans (RAPs) on Parcels A and B and a Demolition and Environmental Monitoring Plan on Parcel B once the building foundations and pavement have been removed. Groundwater has also been adequately characterized. While shallow groundwater has been sampled extensively using in-situ sampling devices, the results may overestimate metals concentrations in Zone A groundwater on the North Campus. Groundwater metals analyses are recommended for the existing Zone A wells on the North Campus to evaluate whether the in-situ groundwater results are representative of actual groundwater quality.

Copies of pertinent pages reviewed are included in Appendix B of this report.

6.0 SITE RECONNAISSANCE

The weather at the time of the site visit was sunny and clear. Refer to Section 1.5 for limitations encountered during the field reconnaissance and Sections 2.1 and 2.2 for subject property operations. The table below provides the site assessment details:

Site Assessment Data	
Site Assessment Performed By:	Margaret Thomas
Site Assessment Conducted On:	January 13, 2021

The table below provides the subject property personnel interviewed during the field reconnaissance:

Site Visit Personnel for 850 Lagoon Drive (Subject Property)			
Name	**Title/Role**	**Contact Number**	**Site Walk* Yes/No**
Emil Wohl	Client Representative	(619) 296-4113	Yes
Rick Siordia	EHS Manager, Rohr Inc.	(619) 691-4279	Yes
David Danchise	Facilities Manager, Rohr Inc.	(619) 691-4279	Yes

* Accompanied Partner during the field reconnaissance activities and provided information pertaining to the current operations and maintenance of the subject property

Environmental concerns were identified during the onsite reconnaissance related to former USTs, vaults, the former storage, use, and generation of hazardous substances, indications of former subsurface investigations, etc., as further discussed in Sections 6.1 and 6.2.

6.1 General Site Characteristics

6.1.1 Solid Waste Disposal

Municipal waste dumpsters and large bins are located throughout the subject property used for appropriate waste disposal of items including scrap metal recycling and other recycled materials. An independent solid waste disposal contractor removes solid waste from the subject property. No evidence of illegal dumping of solid waste was observed during the Partner site reconnaissance.

6.1.2 Sewage Discharge and Disposal

Sanitary discharges on the subject property are directed into the municipal sanitary sewer system. The City of Chula Vista services the subject property vicinity. No septic systems were observed or reported on the subject property. An inactive WWTP is present (see Section 6.1.6).

6.1.3 Surface Water Drainage

Storm water is removed from the subject property primarily by sheet flow action across the paved surfaces towards storm water drains located throughout the subject property and in the public right of way. Temporary berms were observed around the storm drain inlets at the subject property. An extensive storm water conveyance system (SWCS) is present at the subject property that currently drains through two outfalls (Outfall Nos. 1 and 2) to San Diego Bay. During the 1970s, there were 7 to 10 reported stormwater outfalls discharging to San Diego Bay in and around the subject property. Due to the low elevation of the

property, the SWCS is tidally influenced. Historical allegations of process rinse water discharges to the SWCS were reported in the 1950s to 1970s prior to the installation of a WWTP where there is a possibility of sediment impacts in and around the San Diego Bay and/or along the historical shoreline, which was the subject of the 1998 CAO and will be addressed in the future via a separate CAO, which may involve the subject property. Based on the reported historical industrial waste discharges to the SWCS, sediment impacts in and around the San Diego Bay represent a potential environmental concern.

The subject property does not appear to be a designated wetland area, based on information obtained from the United States Fish & Wildlife Service, National Wetlands Inventory database; however, a comprehensive wetlands survey would be required in order to formally determine actual wetlands on the subject property. No surface impoundments, wetlands, natural catch basins, settling ponds, or lagoons are located on the subject property. No drywells were identified on the subject property.

6.1.4 Source of Heating and Cooling

Heating and cooling systems as well as domestic hot water equipment are fueled by electricity and natural gas provided by San Diego Gas & Electric (SDG&E). Heating and cooling systems are limited at the subject property to office areas, the cafeteria building and other spaces. Large warehouse spaces are heated by ceiling mounted space heaters. A majority of the buildings at the subject property are small storage structures with no heating and cooling.

6.1.5 Wells and Cisterns

Multiple groundwater monitoring wells are present across the subject property in connection with an ongoing investigation and remediation of the property (see Section 5.2.6 for discussion on groundwater monitoring wells).

6.1.6 Wastewater

Domestic wastewater generated at the subject property is disposed by means of the sanitary sewer system. No industrial processes are currently performed at the subject property; however, an inactive WWTP is present at the subject property that was constructed in 2000 to replace a former WWTP located on the South Campus. When the South Campus closed, many of the processes and equipment were transferred to the subject property Parcel B. The WWTP is situated west of Building 1 and south of Building 117 along the historic shoreline of the San Diego Bay. The entire WWTP is constructed within a secondary containment that includes concrete slurry walls and a liner. Approximately 15 2,500- to 6,000-gallon capacity treatment and bulk storage ASTs and three 50,000-gallon capacity process tanks are located within additional containment vaults in this area. The WWTP system operated under Industrial Discharge User Permit #13-0161-04.

According to reviewed information, the WWTP systems included chrome reduction, pH adjustment for heavy metal precipitation, pH neutralization, microfiltration, and final neutralization. The treated effluent was further treated by carbon filtration and reverse osmosis (RO). The RO reject is discharged to the sewer and the balance, if further treated, went through an ion exchange system. The resulting deionized (DI) water was stored in a 50,000-gallon AST. The DI water was recycled back to the chemical process

lines. Waste streams from this process were characterized as hazardous and transported offsite for disposal by a variety of licensed waste transporters under hazardous waste manifest. Bulk storage of acidic and caustic product was also stored in the WWTP. As a note, debris and hydrocarbon product were uncovered during construction of the WWTP that may be associated with historical releases or dumping that occurred along the pre-1960 shoreline.

In addition, an inground grease interceptor is present adjacent to the cafeteria building (Building 33). Based on its intended use, it is not expected to represent a significant environmental concern.

Four active clarifiers were reported in 2013 at the subject property at Buildings 1 and 341, which are currently inactive and will be removed during site redevelopment (see also Section 6.2.7).

6.1.7 Septic Systems

No septic systems were observed or reported on the subject property.

6.1.8 Additional Site Observations

No additional general site characteristics were observed during the site reconnaissance.

6.2 Potential Environmental Hazards

6.2.1 Hazardous Substances and Petroleum Products Used or Stored at the Site

No significant quantities of hazardous substances or petroleum products were observed on the subject property during the site reconnaissance, as the facility is currently in the process of decommissioning and removing equipment and materials to offsite locations. Partner observed several new 55-gallon drums of petroleum-based oils in the Oiler Shed on secondary containment and several flammable materials cabinets located throughout the facility. The CERS database reports a chemical inventory that most likely reflects inventory from a few years ago (see Section 4.1.1).

According to prior site investigations, hazardous materials were used both in bulk and in small quantities throughout the facility. Generally, hydraulic and lubricating oils were used to operate numerous hydraulic machinery; caustic solutions were used in product process lines for cleaning and etching of aluminum, steel and titanium; and caustic chemicals were stored and processed in the WWTP. Additionally, cutting oils and kerosene were used in the machine shop, and paint solvents were used for thinning and cleaning at several paint process locations where spray booths and other associated machinery were located. Bulk storage of hazardous materials was also stored in Building 310 (Chemical Services) and the Oiler Shed.

Historically the facility used TCE and 1,1,1-TCA as its primary degreasing solvents. TCE use was phased out in circa 1973 and replaced by 1,1,1-TCA. 1,1,1-TCA was used at the facility until the late 1990s, at which time it was replaced by water-based degreasers, such as Spray Clean 12, a non-hazardous aqueous alkaline cleaner to clean parts of oil and grease prior to painting. MEK, MIBK and acetone were also used for degreasing purposes in the past.

6.2.2 Aboveground & Underground Hazardous Substance or Petroleum Product Storage Tanks (ASTs/USTs)

ASTs are present at the subject property in the WWTP, which are no longer in use. No active USTs are present at the subject property, although, several prior USTs were removed with one known UST abandoned in place at or near the oiler shed. The largest USTs included four 10,000-gallon tanks, which contained diesel, gasoline and waste oil/coolant removed and closed-in place in 1987 under the oversight of the County DEH. Three 6,000-gallon USTs containing gasoline and diesel (reported at Building 25) were removed in 2002 also under the oversight of the County DEH.

Multiple additional smaller USTs, vaults and a sump were reported all of which are closed or removed.

6.2.3 Evidence of Releases

Multiple groundwater monitoring wells are located across the subject property that is evidence of a release. See Section 4.1.4 and 5.2.6 for a discussion of response actions being taken at the subject property.

6.2.4 Polychlorinated Biphenyls (PCBs)

Older transformers and other electrical equipment could contain PCBs at a level that subjects them to regulation by the U.S. EPA. PCBs in electrical equipment are controlled by United States Environmental Protection Agency regulations 40 CFR, Part 761. Under the regulations, there are three categories into which electrical equipment can be classified: 1) Less than 50 parts per million (ppm) of PCBs – "*Non-PCB;*" 2) 50 ppm-500 ppm – "*PCB-Contaminated;*" and, 3) Greater than 500 ppm – "*PCB-Containing.*" The manufacture, process, or distribution in commerce or use of any PCB in any manner other than in a totally enclosed manner was prohibited after July 2, 1979.

The on-site reconnaissance addressed indoor and outdoor transformers that may contain PCBs. Multiple electrical transformers are present at the subject property that are owned and maintained by SDG&E. Of the transformers observed, no leaks or stains were observed on the concrete pad at the base of the units. Based on our experience, SDG&E is responsible for reporting that potential PCBs associated with their transformers are within regulatory limits. According to reviewed information, it does not appear that the transformers at Parcel B contain PCBs, as the units were retrofitted many years ago.

In addition, it is reported that PCBs were not known to be present in hydraulic manufacturing machinery operated at the subject property.

SDG&E operates the Montgomery Substation on an adjacent parcel situated along the north side of the subject property, south of G Street. According to provided information, it appears that several of the transformer units within the substation have been retrofitted between 1987 and 1992 and do not contain regulated quantities of PCBs. The status of the remaining transformers is not currently known; however, it is likely that all remaining transformers were also retrofitted by SDG&E.

According to the 2013 URS Phase I ESA report, PCBs have been documented in sediment removed from the Outfall No. 1 Tidal Inlet. PCBs are present within sediment throughout San Diego Bay, and the sources are not all specifically known. It is unclear where the source of the PCBs in Outfall No. 1 may have been

located, and it may have included the adjacent Chula Vista Sewage Treatment Plant (CVSTP). It is possible that PCBs may be associated with the former SWCS outfalls and drainage ditches that pre-dated the placement of dredged fill on the tidelands west of the North Campus, and also Outfall No. 2 that post-dates the dredged fill placement. The historic outfalls were considered RECs by URS. The investigation of the Outfalls is ongoing under the oversight of the SDRWQCB.

6.2.5 Strong, Pungent or Noxious Odors

No strong, pungent or noxious odors were evident during the site reconnaissance.

6.2.6 Pools of Liquid

No pools of liquid were observed on the subject property during the site reconnaissance.

6.2.7 Drains, Sumps and Clarifiers

Interior floor drains, sumps and clarifiers are reported at the subject property associated with historical mechanical equipment, various process lines and conveyance piping, and an industrial WWTP. Many of these features have been closed and/or will be closed/abandoned in the near future as part of the facility decommission and redevelopment. Drains, sumps and clarifiers are considered potential source areas for environmental impacts and have been the focus of prior subsurface investigations.

Four clarifiers are reported at the subject property. One is located at the Vehicle Maintenance Area at Building 119, and three are located in Building 1. One unit supported tooling for a plaster sink at interior support column C35, and two units are located at interior support columns B16 and C16 for two prior water jets. Aqueous effluents from clarifiers typically discharge to the municipal sewer system. It is also possible that one or more of the clarifiers drained through the WWTP.

There is a network of subgrade trenches in the Machine Shop area of Building 1 that historically drained coolant from the machines into a holding sump identified as Tank No. 34 on prior documents. The machines were retrofitted in the 1990s so that the used coolant was recycled within the unit where the trenches were no longer used for conveyance of coolant. The said trenches were subsequently used for compressed air and electrical lines.

6.2.8 Pits, Ponds and Lagoons

No natural pits, ponds or lagoons were observed on the subject property.

6.2.9 Stressed Vegetation

No stressed vegetation was observed on the subject property.

6.2.10 Additional Potential Environmental Hazards

No additional environmental hazards, including landfill activities or radiological hazards, were observed.

6.3 Non-ASTM Services

6.3.1 Asbestos-Containing Materials (ACMs)

Asbestos is the name given to a number of naturally occurring, fibrous silicate minerals mined for their useful properties such as thermal insulation, chemical and thermal stability, and high tensile strength. The Occupational Safety and Health Administration (OSHA) regulation 29 CFR 1926.1101 requires certain construction materials to be presumed to contain asbestos, for purposes of this regulation. All thermal system insulation (TSI), surfacing material, and asphalt/vinyl flooring that are present in a building that have not been appropriately tested are "presumed asbestos-containing material" (PACM).

The subject property buildings were constructed as early as 1941. The buildings are proposed for demolition in the coming months at which time ACM will be required to be abated and properly disposed. A 1989 ACM survey prepared by McLaren Environmental Engineering identified ACM at the subject property in multiple locations. The property has an Asbestos Operations and Maintenance (O&M) Program in place dated July 2013, which reports ACM and *Assumed Positive Materials* in Buildings 1, 22, 50, 54, 55, 63, 68, 79, 88, 91, 310, and 503.

Prior to disturbance, additional sampling may be required to confirm whether a specific material contains asbestos for waste characterization and disposal purposes. A variety of friable and non-friable ACMs is expected to be present (surfacing materials, thermal system insulation and miscellaneous materials such as flooring and mastics). All suspect materials must be handled as ACM according to applicable regulations until the results of sampling and analysis indicate the material is a non-ACM.

6.3.2 Lead-Based Paint (LBP)

Lead is a highly toxic metal that affects virtually every system of the body. LBP is defined as any paint, varnish, stain, or other applied coating that has 1 mg/cm^2 (or 5,000 ug/g or 0.5% by weight) or more of lead. Congress passed the Residential Lead-Based Paint Hazard Reduction Act of 1992, also known as "Title X," to protect families from exposure to lead from paint, dust, and soil. Under Section 1017 of Title X, intact LBP on most walls and ceilings is not considered a "hazard," although the condition of the paint should be monitored and maintained to ensure that it does not become deteriorated. Further, Section 1018 of this law directed the Housing and Urban Development (HUD) and the US EPA to require the disclosure of known information on LBP and LBP hazards before the sale or lease of most housing built before 1978.

Based on the age of the subject property buildings (pre-1978), there is a potential that LBP is present. Actual material samples would need to be collected in order to determine if LBP is present. Partner reviewed a LBP sampling report for Building 54 dated February 9, 2017, prepared by Altec Testing & Engineering Inc., which identified LBP on several building components in Building 54, which was the only building included in the survey. Additional sampling may be required of other buildings prior to demolition of building materials for proper waste characterization and disposal purposes.

6.3.3 Radon

Radon is a colorless, odorless, naturally occurring, radioactive, inert, gaseous element formed by radioactive decay of radium (Ra) atoms. The US EPA has prepared a map to assist National, State, and local organizations to target their resources and to implement radon-resistant building codes. The map divides the country into three Radon Zones, according to the table below:

EPA Radon Zones		
EPA Zones	**Average Predicted Radon Levels**	**Potential**
Zone 1	Exceed 4.0 pCi/L	Highest
Zone 2	Between 2.0 and 4.0 pCi/L	Moderate
Zone 3	Less than 2.0 pCi/L	Low

It is important to note that the EPA has found homes with elevated levels of radon in all three zones, and the US EPA recommends site-specific testing in order to determine radon levels at a specific location. However, the map does give a valuable indication of the propensity of radon gas accumulation in structures.

Radon sampling was not conducted as part of this assessment. Review of the US EPA Map of Radon Zones places the subject property in Zone 3. Based upon the radon zone classification, radon is not considered to be a significant environmental concern.

6.3.4 Lead in Drinking Water

According to available information, a public water system operated by the City of Chula Vista serves the subject property vicinity. The City obtains municipal drinking water through the Sweetwater Authority who obtains municipal drinking water from four sources: the Sweetwater River (drawn at Sweetwater Reservoir in Spring Valley), deep freshwater wells in National City, brackish water wells in Chula Vista, and the region's imported supply, which is drawn from the Colorado River and/or the State Water Project in northern California. According to the Sweetwater Authority 2020 Annual Water Quality Report, water supplied to the subject property is in compliance with all State and Federal regulations pertaining to drinking water standards, including lead and copper. Water sampling was not conducted to verify water quality.

6.3.5 Mold

Molds are microscopic organisms found virtually everywhere, indoors and outdoors. Mold will grow and multiply under the right conditions, needing only sufficient moisture (e.g., in the form of very high humidity, condensation, or water from a leaking pipe, etc.) and organic material (e.g., ceiling tile, drywall, paper, or natural fiber carpet padding).

Partner observed accessible, interior areas for the subject property buildings for significant evidence of mold growth with the exceptions detailed in Section 1.5 of this report; however, this ESA should not be used as a mold survey or inspection. Additionally, this limited assessment was not designed to assess all areas of potential mold growth that may be affected by mold growth on the subject property. Rather, it is intended to give the client an indication as to whether or not conspicuous (based on observed areas)

mold growth is present at the subject property. This evaluation did not include a review of pipe chases, mechanical systems, or areas behind enclosed walls and ceilings.

No obvious indications of water damage or mold growth were observed during Partner's visual assessment.

6.4 Adjacent Property Reconnaissance

The adjacent property reconnaissance consisted of observing the adjacent properties from the subject property premises (see Section 2.3 for adjacent uses). The adjacent properties are all part of the historical Rohr Inc. manufacturing campus, which are under investigation for soil and/or groundwater impacts under the oversight of the SDRWQCB. See Section 4.2.3 for a discussion of the adjacent parcels.

7.0 FINDINGS AND CONCLUSIONS

Findings

A *REC* refers to the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: due to release to the environment; under conditions indicative of a release to the environment; or under conditions that pose a material threat of a future release to the environment. The following was identified during the course of this assessment:

- Aerospace manufacturing operations were conducted at the subject property from circa 1941 until approximately one year ago, which involved the operation of heavy machinery within below grade vaults, multiple solvent degreasers, paint spray booths, multiple ASTs/USTs, and other equipment and the use of various hazardous substances including halogenated volatile organic compounds (VOCs) such as trichloroethene (TCE), metals (aluminum, titanium, chromium, lead and steel), petroleum hydrocarbons, polynuclear aromatic hydrocarbons (PAHS), polychlorinated biphenyls (PCBs), and other substances identified as chemicals of concern (COC) that have been reported in soil, soil vapor and groundwater underlying the subject property. TCE and 1,1,1-trichloroethane (1,1,1-TCA) were historically used as degreasing solvents and have been the subject of soil, soil vapor, and groundwater investigations at the subject property facility dating back to the 1980s. The subject property is currently being investigated under the regulatory oversight of the San Diego Regional Water Quality Control Board (SDRWQCB) under a corrective action order (CAO) 98-08 dated April 1998 addressed to Rohr Inc., for site wide environmental impacts (North Campus) resulting from historical releases including into the storm drain conveyance system and San Diego Bay. The CAO requires the cleanup and abatement of wastes discharged from Rohr's manufacturing operations.

  Interim remedial actions are currently underway on the adjacent parcel located downgradient of the subject property source areas, known as Rohr Parcel H-3, pursuant to the 1998 CAO No. 98-08. Redevelopment activities are planned for Parcel H-3 as part of a large Bayfront redevelopment project in the coming months. Implementation of the interim remedy on Parcel H-3 occurred from April to September 2020 and includes four permeable reactive barriers (PRBs), injection of in situ chemical reduction (ISCR) and enhanced in situ bioremediation (EISB) amendments. The PRBs were placed as such to capture impacts originating from the subject property in efforts to prevent contamination from reaching the San Diego Bay. SDRWQCB is currently preparing a new site wide CAO No. R9-2020-0099, which will address the cleanup remedies and timeline of all wastes discharged to soil, soil vapor, and groundwater from the manufacturing operations at the North Campus Property (subject property). CAO No. R9-2020-0099 will supersede CAO No. 98-08 except for the interim remedial actions at Parcel H-3, which will continue to be conducted under CAO No. 98-08. The new CAO No. R9-2020-0099 is not yet final, although remediation work plans, feasibility studies, and a human health risk assessment (HHRA) are underway and/or in the planning stages for the subject property to address soil, soil vapor and groundwater impacts. Based on Partner's current understanding of the status of

proposed remediation, a soil vapor extraction system may be employed as well as targeted efforts for groundwater; however, remedial action plans have not been determined or finalized for the subject property.

A considerable number of investigations have been conducted on the subject property since the late 1980s. Currently there are several hot spots and comingled groundwater plumes at the subject property that include but are not limited to a 1,1,1–TCA/TCE AST that was formerly located west of former Building 57 near the northwest corner of the subject property; the *Oiler Shed* located at the middle south side of the subject property; and a vapor degreaser line aligned east/west through Building 1. COCs in these specific areas included TCE, 1,1,1-TCA and their degradation products and hexavalent chromium (salt bath area inside Building 1). According to an Annual Groundwater Monitoring and Sampling Report dated November 21, 2019, TCE was detected more frequently and at higher concentrations than other VOCs. The maximum TCE concentration was detected in monitoring well NCW-14A at 31,000 micrograms per liter (µg/L). Well NCW-14A is completed in Zone A and is located immediately downgradient of the suspected Oiler Shed release area. TCE concentrations in Zone A decrease downgradient of NCW-14A. VOC concentrations in Lower Zone B remain substantially less than in the shallower groundwater zones. In addition, based on reviewed information, COCs have migrated off site to the west and southwest in all water bearing zones, primarily in Zones A and Upper Zone B. TCE impacts are widespread across the subject property (Parcel B) in the shallow groundwater Zone A then taper off in the lower B Zones.

According to Rohr Inc., personnel, Rohr Inc. is reportedly responsible for site cleanup at this time. No specific remedial action plans for soil, soil vapor and groundwater cleanup have been finalized. No active remediation systems are present at the subject property; only groundwater monitoring wells at this time. The identified soil, soil vapor and groundwater impacts at the subject property and current regulatory status is considered a REC.

A *CREC* refers to a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority, with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls. The following was identified during the course of this assessment:

- Partner did not identify CRECs during the course of this assessment.

A *HREC* refers to a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls. The following was identified during the course of this assessment:

- The subject property is identified as having several prior documented release cases that were investigated, remediated and received regulatory case closure letters from either SDRWQCB or the local San Diego County Department of Environmental Health (DEH) that are HRECs. Partner notes that a majority of the cases continue to be investigated as part of the site wide

groundwater investigation and cleanup efforts due to groundwater impacts identified in those areas such as the salt bath area in Building 1 and the oiler shed. The release events with documented regulatory case closures include the following:

- BF Goodrich Aerospace Facility, 850 Lagoon Drive, UST closure of one 10,000-gallon diesel tank adjacent to former Building 57 in August 1987. Impacted soils around the UST were removed and disposed along with 500 gallons of impacted water. This UST received regulatory closure from the County DEH on August 2, 2002.
- UTC Aerospace Systems, Former North Oiler Shed, Building 1. An undocumented 550-gallon UST was discovered and removed in 2000 during renovations in the oiler shed area that contained petroleum hydrocarbons and VOCs. The tank had holes and corrosion, and a groundwater sample identified elevated concentrations of TCE and other VOCs. This UST was granted closure on January 3, 2013, for total recoverable petroleum hydrocarbons (TRPH) only, while the remaining VOC impacts are being addressed by the site wide CAO.
- Goodrich Aerostructures, Tank 6, Oiler Shed Sump, Building 1. This sump was described as 2'x2'x3' that discharged to a long drainage trench where machine coolant was collected, recycled and dispensed. Initially equipment and metal chip tubs were drained of oil or coolant and accumulated in the trough and sump where it was then pumped into an AST until 1992. This sump was granted closure on June 1, 2012, for petroleum hydrocarbons only, while the remaining VOC impacts are being addressed by the site wide CAO.
- Goodrich Aerostructures – North Campus – Salt Bath C70, 850 Lagoon Drive, the former salt bath consisted of four below-grade structures that were considered to be USTs. The salt baths were used in the aluminum forming process and formerly contained a hexavalent chrome additive to control corrosion. The operation is the subject of an ongoing evaluation, due to hexavalent chromium found in groundwater in this area. Soil beneath the salt baths was reportedly excavated and disposed. The Salt Bath C70 was administratively closed on May 8, 2019, however potential contaminant releases from it are part of the larger cleanup and remediation efforts at the subject property as a whole.
- Goodrich Aerostructures Machine Shop Sump, Tank No. 34. The sump was located in the southern portion of Building 1, was constructed in 1943, and consisted of a 4'x4' concrete structure that was approximately 6 feet deep (total capacity reportedly 720 gallons). This feature was categorized as an UST by the DEH. Hydraulic oil was collected from larger, floor-mounted milling machines (N/C machines) that were plumbed to the sump. The N/C machines were supplied with hydraulic oil from a central hydraulic unit. Hydraulic oil was transferred to each N/C machine through utility trenches via hydraulic lines. Tank No. 34 was administratively closed on May 8, 2019, however potential contaminant

releases from it are part of the larger cleanup and remediation efforts at the subject property as a whole.

An *environmental issue* refers to environmental concerns identified by Partner, which do not qualify as RECs; however, warrant further discussion. The following was identified during the course of this assessment:

- Up to 100 ASTs, USTs, vessels, and vaults were operated at the subject property associated with aerospace manufacturing activities, several of which are identified as contributors to the known environmental impacts at the subject property. No active USTs are currently operated at the subject property, and the ASTs, vaults and vessels have either been removed or are in the process of being removed, sold or scrapped. No active industrial processes are occurring at the subject property. The various sized above ground tanks and vessels contained hazardous substances including acids, caustics, wastewater, deionized water, cleaners, solvents, petroleum hydrocarbons including gasoline and diesel, hydraulic oil, coolant, and other substances. The USTs were reportedly closed or abandoned in place under regulatory oversight. One 10,000-gallon waste oil UST was closed in place in 1987 in the oiler shed, which will likely be encountered during redevelopment activities is surface disturbance occurs in the area it is located. At least one UST was undocumented and was discovered during renovations, indicating other undocumented USTs may be found during redevelopment of the property. It is expected that residual contaminant impacts will be encountered during site redevelopment in and around historic subsurface vessels, vaults, USTs, and piping, including along the historic shoreline where impacts were reported during prior subsurface investigations. Based on historical uses of ASTs and USTs for hazardous material storage that may have residually impacted underlying soils, this represents an environmental concern that must be managed during site redevelopment.
- Based on a review of regulatory documents posted to the State Water Resources Control Board GeoTracker database and other provided information, there is an extensive storm water conveyance system (SWCS) on the subject property that currently drains through two outfalls (Outfall Nos. 1 and 2) to San Diego Bay. During the 1970s, there were reportedly 7 to 10 stormwater outfalls discharging to San Diego Bay, in and around the subject property, including a historic drainage ditch. Due to the low elevation of the property, the SWCS is tidally influenced. Historical allegations of process rinse water discharges to the SWCS were reported in the 1950s to 1970s prior to the installation of a WWTP. These historical discharges have possibly resulted in contaminant impacts to the sediment at the discharge points and vicinity in the San Diego Bay. This issue was the subject of the 1998 CAO and will be addressed in the future via a separate CAO that will likely include the subject property. Based on the reported historical industrial waste discharges to the SWCS and known sediment impacts from the historic outfalls, this represents a potential environmental concern.
- Due to the age of the subject property buildings, there is a potential that ACMs and/or LBP are present. The buildings are proposed for demolition in the coming months at which time suspect materials will be required to be abated and properly disposed. A 1989 ACM survey identified ACM at the subject property in multiple locations, and LBP was identified in Building 54 during a

2016 sampling survey. The property has an Asbestos O&M Program in place dated July 2013, which reports ACM and *Assumed Positive Materials* in Buildings 1, 22, 50, 54, 55, 63, 68, 79, 88, 91, 310, and 503. Additional sampling prior to demolition may be required for waste characterization and disposal purposes.

Conclusions, Opinions and Recommendations

Partner has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E1527-13 of 850 Lagoon Drive in Chula Vista, San Diego County, California (the "subject property"). Any exceptions to, or deletions from, this practice are described in Section 1.5 of this report.

This assessment has revealed evidence of recognized environmental conditions and environmental issues in connection with the subject property. Based on the conclusions of this assessment, Partner recommends the following:

- Continue to adhere to existing and future CAOs issued by SDRWQCB as they pertain to soil, soil vapor, groundwater, and bay sediments contamination resulting from historical uses on the subject property.
- A detailed Soil Management Plan is recommended for site redevelopment to address unexpected items such as below grade features, piping and residual soil impacts.
- A Vapor Barrier is recommended to be incorporated into the new site development plan to act as a mitigating factor for known VOC impacts in the groundwater.
- A demolition level Hazardous Materials Survey is recommended to identify items that require abatement prior to demolition such as mercury switches and lamp tubes, PCB-containing light ballasts and switches, fluorescent lights, refrigerant-containing HVAC systems, and other items.
- Groundwater wells may need to be temporarily abandoned and re-installed during site redevelopment.

8.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

Partner has performed a Phase I Environmental Site Assessment of the property located at 850 Lagoon Drive in Chula Vista, San Diego County, California in conformance with the scope and limitations of the protocol and the limitations stated earlier in this report. Exceptions to or deletions from this protocol are discussed earlier in this report.

By signing below, Partner declares that, to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in §312.10 of 40 CFR §312. Partner has the specific qualifications based on education, training, and experience to assess a *property* of the nature, history, and setting of the subject *property*. Partner has developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Prepared By:

DRAFT

Margaret Thomas
Senior Assessor

Reviewed By:

DRAFT

Caroline Ziegler
Project Manager

9.0 REFERENCES

Reference Documents

American Society for Testing and Materials, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM Designation: E1527-13.

Environmental Data Resources (EDR), Radius Report, February 2021

Federal Emergency Management Agency, Federal Insurance Administration, National Flood Insurance Program, Flood Insurance Map, accessed via internet, February 2021

United States Department of Agriculture, Natural Resources Conservation Service, accessed via internet, February 2021

United States Department of Agriculture, Natural Resources Conservation Service, Web Soil Survey, accessed via the internet, February 2021

United States Environmental Protection Agency, EPA Map of Radon Zones (Document EPA-402-R-93-071), accessed via the internet, February 2021

United States Geological Survey, accessed via the Internet, February 2021


United States Geological Survey Topographic Maps, 7.5-minute series, EDR Historical Topo Map Report, February 2021

FIGURES

1 SITE LOCATION MAP

2 SITE PLAN

3 TOPOGRAPHIC MAP



N

Drawing Not To Scale

KEY:
Subject Property


FIGURE 1: SITE LOCATION MAP
Project No. 20-302755.1

PARTNER



FIGURE 2: SITE PLAN
Project No. 20-302755.1

PARTNER



N


USGS 7.5 Minute *National City, California* Quadrangle
Created: 2012

KEY:
Subject Property

FIGURE 3: TOPOGRAPHIC MAP
Project No. 20-302755.1

PARTNER

APPENDIX A: SITE PHOTOGRAPHS



1. View of main signage to entrance of facility along F Street looking east-southeast



2. View of the east side of Building 1 looking westerly



3. View of the west side of the subject property looking north, noting auxiliary structures



4. View of Building 54 looking north



5. View of central access driveway at Building 1 looking NW, with cafeteria on left (red awning)



6. View of same central access driveway as shown in Photo #5 looking north (oiler shed on right)



7. View of vehicle maintenance structure (Building 119) looking north



8. View of Building 453 storage shed looking north



9. View of Building 50 looking south



10. View of awning structure on the north side of Building 1 looking northeast



11. View of the south side of Building 50 looking northwest



12. View of the wastewater treatment plant (WWTP) looking west



13. View of the WWTP



14. View of the WWTP



15. View of the WWTP



16. View of the east side of Building 1 looking north



17. View of the east side of Building 1 looking northwest



18. View of Building 1 looking southwest from the north side of the building



19. View of a mechanical pit on the north side of Building 1




20. View of deep mechanical pit inside Building 1



21. View of idle ovens inside Building 1



22. View of idle oven inside Building 1



23. View of mechanical pit inside Building 1 looking west



24. View of additional mechanical pits inside Building 1



25. View of the interior of Building 1



26. View of mechanical vault inside Building 1



27. View of process line inside Building 1 looking east



28. View of process line inside Building 1 looking west



29. View of overhead conveyance piping above the line shown in Photos #27 and #28




30. View of floor trench on the west side of Building 1 in a sandblast room looking west



31. View of sandblast area, same area as shown in Photo #30, looking southwest across the room



32. View of the interior of Building 117



33. View of the interior of Building 54 formerly used for warehouse purposes, looking north



34. View of the interior of Building 54 formerly used for warehouse purposes, looking northeast



35. View of the interior of the vehicle repair shop (Building 119) looking east



36. View of small storage sheds at Building 98 located near the southwest side of the property looking west



37. View of grease interceptor adjacent to the cafeteria building (Building 33) looking north



38. View of the oiler shed looking south



39. View of drums of petroleum-based motor oil and/or hydraulic oil inside the oiler shed



40. View of portable waste oil service tank inside the oiler shed



41. View inside secondary containment machinery oil crib located at the oiler shed



42. View of sign above Photo #41



43. View of former machining area inside Building 1 near middle east side of the building looking NNE



44. View of floor trenching in the former machining area shown in Photo #43



45. View of plaster sink and aboveground filter unit under the sink inside Building 1, near SEC of building



46. View of former machining area, same area as shown in Photos #43 and #44



47. View of spray booth on the east side of Building 1 looking northwest



48. View inside the spray booth shown in Photo #47 looking north



49. View of row of spray booths inside Building 1 looking southeast



50. View inside one of the spray booths shown in Photo #49



51. View of the east side of Building 1 looking north



52. General view of the central area of Building 1 looking northwest



53. View of monitoring well inside Building 1



54. View of storm drain inlet on the east side of the property noting the berm around the inlet



55. View of the adjacent SDG&E substation looking north



56. View of the north side of the subject property looking north in the area of the former degreaser (hot spot)



57. View of the north side of the subject property looking east in the area of the former degreaser (hot spot)



58. View of the north side of Building 1 looking southeast from the north side of the property



59. View of the South Campus property looking southeast from H Street



60. View of adjacent parking area to the west with Building 61 in the background looking northeast



61. View of adjacent property to the west looking north from H Street



62. View of adjacent property to the west looking northeast with subject property beyond fence



63. View of adjacent property to the west Parcel H-3, looking west from foot of H street



64. View of adjacent property to the west Parcel H-3 looking northwest from foot of H Street



65. View of adjacent Building 29 on Parcel A looking north from H Street



66. View of subject property along H Street looking northwest

APPENDIX B: HISTORICAL/REGULATORY DOCUMENTATION


PARTNER



500 1000 2000

N

Key: Subject Property



500 1000 2000

N

Key: Subject Property



500 1000 2000

N


Key: Subject Property



500 1000 2000

N


Key: Subject Property



500 1000 2000

N

Key: Subject Property



500 1000 2000

N


Key: Subject Property



500 1000 2000

N


Key: Subject Property



500 1000 2000

N


Key: Subject Property



500 1000 2000

N

Key: Subject Property



500 1000 2000

N

Key: Subject Property



500 1000 2000

N

Key: Subject Property



500 1000 2000

N

Key: Subject Property



500 1000 2000

N

Key: Subject Property



500 1000 2000

N


Key: Subject Property



500 1000 2000

N

Key: Subject Property



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 26C7-4CB2-9761


Site Name:	Parcel B Buildings - Former Collins Aerospace
Address:	South of G Street
City, ST, ZIP:	Chula Vista, CA 91910
Client:	Partner Engineering and Science, Inc.
EDR Inquiry:	6326895.3
Order Date:	01/12/2021
Certification #	
Copyright	1918

Volume 1, Sheet 2

0 Feet 150 300 600

N

Key: Subject Property



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 26C7-4CB2-9761

Site Name: Parcel B Buildings - Former Collins Aerospace
Address: South of G Street
City, ST, ZIP: Chula Vista, CA 91910
Client: Partner Engineering and Science, Inc.
EDR Inquiry: 6326895.3
Order Date: 01/12/2021
Certification #
Copyright 1926


Volume 1, Sheet 15

0 Feet 150 300 600

N

Key: Subject Property

APPENDIX B: Certified Sanborn Maps
Project No. 20-302755.1



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 26C7-4CB2-9761

Site Name:	Parcel B Buildings - Former Collins Aerospace
Address:	South of G Street
City, ST, ZIP:	Chula Vista, CA 91910
Client:	Partner Engineering and Science, Inc.
EDR Inquiry:	6326895.3
Order Date:	01/12/2021
Certification #	
Copyright	1949

Volume 1, Sheet 15

0 Feet 150 300 600

N

Key: Subject Property



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 26C7-4CB2-9761


Site Name: Parcel B Buildings - Former Collins Aerospace
Address: South of G Street
City, ST, ZIP: Chula Vista, CA 91910
Client: Partner Engineering and Science, Inc.
EDR Inquiry: 6326895.3
Order Date: 01/12/2021
Certification #
Copyright 1950

Volume 1, Sheet 15

0 Feet 150 300 600

N

Key: Subject Property



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification # 26C7-4CB2-9761

Site Name: Parcel B Buildings - Former Collins Aerospace
Address: South of G Street
City, ST, ZIP: Chula Vista, CA 91910
Client: Partner Engineering and Science, Inc.
EDR Inquiry: 6326895.3
Order Date: 01/12/2021
Certification #
Copyright 1962

Volume 1, Sheet 15

0 Feet 150 300 600

N

Key: Subject Property

Parcel B Buildings - Former Collins Aerospace
South of G Street
Chula Vista, CA 91910

Inquiry Number: 6326895.5
January 15, 2021

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY


DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.



RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2017	☑	☐	EDR Digital Archive
2014	☑	☐	EDR Digital Archive
2010	☑	☐	EDR Digital Archive
2005	☑	☐	EDR Digital Archive
2000	☑	☐	EDR Digital Archive
1995	☑	☐	EDR Digital Archive
1992	☑	☐	EDR Digital Archive
1986	☑	☐	Haines Criss-Cross Directory
1982	☑	☐	Haines Criss-Cross Directory
1979	☑	☐	Haines Criss-Cross Directory
1975	☑	☐	Haines Criss-Cross Directory
1971	☑	☐	Haines Criss-Cross Directory
1965	☑	☐	POLK DIRECTORY CO
1960	☑	☐	POLK DIRECTORY CO
1955	☑	☐	POLK DIRECTORY CO

EXECUTIVE SUMMARY

Year	***Target Street***	***Cross Street***	***Source***

FINDINGS

TARGET PROPERTY STREET

South of G Street
Chula Vista, CA 91910

Year	*CD Image*	*Source*
G ST		
2017	pg A2	EDR Digital Archive
2014	pg A16	EDR Digital Archive
2010	pg A32	EDR Digital Archive
2005	pg A48	EDR Digital Archive
2000	pg A64	EDR Digital Archive
1995	pg A74	EDR Digital Archive
1992	pg A85	EDR Digital Archive
1986	pg A90	Haines Criss-Cross Directory
1986	pg A91	Haines Criss-Cross Directory
1986	pg A92	Haines Criss-Cross Directory
1982	pg A93	Haines Criss-Cross Directory
1982	pg A94	Haines Criss-Cross Directory
1982	pg A95	Haines Criss-Cross Directory
1979	pg A96	Haines Criss-Cross Directory
1979	pg A97	Haines Criss-Cross Directory
1979	pg A98	Haines Criss-Cross Directory
1975	pg A100	Haines Criss-Cross Directory
1975	pg A101	Haines Criss-Cross Directory
1975	pg A99	Haines Criss-Cross Directory
1971	pg A102	Haines Criss-Cross Directory
1971	pg A103	Haines Criss-Cross Directory
1971	pg A104	Haines Criss-Cross Directory
1971	pg A105	Haines Criss-Cross Directory
1965	pg A106	POLK DIRECTORY CO
1965	pg A107	POLK DIRECTORY CO
1965	pg A108	POLK DIRECTORY CO
1965	pg A109	POLK DIRECTORY CO
1965	pg A110	POLK DIRECTORY CO
1960	pg A111	POLK DIRECTORY CO
1960	pg A112	POLK DIRECTORY CO

FINDINGS

Year	***CD Image***	***Source***
1960	pg A113	POLK DIRECTORY CO
1955	pg A114	POLK DIRECTORY CO
1955	pg A115	POLK DIRECTORY CO

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017

14	ACKERMAN, RICHARD J
15	FLYNN, MARY E
30	FLACKE, HELFRIED G
39	ROYAL GARDEN GUEST HOME
	TABLADILLO, RODOLFO M
42	HILDEBRAND, ERNEST H
45	TAYLOR, JONATHAN W
48	WHITECOTTON, BETTY J
52	SHADDUCK, GARY N
55	RICHARDSON, MICHAEL A
60	DEESE, BOBBY L
66	YU, JIA L
70	STANCZAK, FRANK J
71	NELSON, ROSALYN J
77	SEARLES, ROBERT C
78	DUARTE, SAUL D
83	TAYLOR, ALICIA R
84	GRANADOS, ERNEST C
86	DUNKLE, RAYMOND E
87	CHASE, PALMER S
90	MURRAY, LUPE M
93	FORTUNA, EDMUND F
108	CARRERA, CECILIA M
115	COVARRUBIAS, ROMAN J
121	MAGANA, HILDA R
130	HULST, WARREN J
134	HARGIS, PATRICIA J
140	TELLO, DOROTHY M
147	FORTE, DELANO K
152	MORENO, JOSE M
155	EVAN, LARRY D
156	HUVAR, CAROL L
159	WALLACE, JEFFREY S
160	MICHEL, JOEL E
161	BIOMMELL, DARRELL L
163	RASCON, MARISA R
164	KELLY, THOMAS M
167	CASTILLO, ANTONIO
170	COSTELLO, PAUL M
174	TORRES, VERONICA
177	GARCIA, JESSICA M
186	VERDUGO, WENDY
194	VAZQUEZ, ALFREDO
195	TROTTER, RONALD G
197	ESPIRITU, JEFFREY E
202	MARTINEZ, ESPERANZA D
203	JOHANSEN, JACK
207	AMOS, ANSON S
210	DURAN, DIANA
211	ROMERO, JORGE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

215	PARKS, JOHNNIE L
217	BLACKWELL, WARRIENE
222	AMALIA, INIGUEZ
	ARRIAGA, GLORIA I
	BORBON, REBECCA
	CAPP, KYLE
	CATE, CHARLES A
	CHAVEZ, GERARDO V
	COVARRUBIAS, M
	CUEVA, HERNANDEZ
	DIAZSANTANA, LUIS
	ENGLISH, WAYNE S
	GILROY, RAQUEL
	GONZALES, LETICIA
	GUIMONT, LANCE
	HARRIS, JANE N
	HOVERMALE, CONNIE
	IRIZARRY, AIDA
	KING, AUDREY
	KISLEY, KATHY
	LEONHARDT, MARY A
	MARTINEZ, ELIAS M
	MARTINEZ, YESENIA
	MORA, JOSE O
	OCHOA, ALMA
	PARRA, RAYMOND A
	PARTIDA, MARIA C
	PENWELL, EDITH A
	PORTERFIELD, DAVID M
	REYES, GUADALUPE B
	SANCHEZ, SILVIO
	TELLERIA, JOSE L
	VELASQUEZ, JULIAN R
	WILLIAMS, RHONDA L
	WRIGHT, CHRISTINE M
223	DIAZ, RICARDO G
	GANDARA, SERGIO M
	SOTO, ENRIQUETA
	ZULAICA, BENITO H
226	BARRAZA, JESUS R
	GIMENEZ, DAMIAN P
	MARTINEZ, PABLO
227	CARBAJAL, LUIS E
228	GONZALES, ROBERT A
229	MOSHER, KEITH E
233	DOEGE, AMANDA M
239	CONVIRSE, SILVIA D
	RAMOS, ARMANDO O
	RANGEL, ROSIE
240	NIDO, FERNANDO

G ST 2017 (Cont'd)

241	GRIER, SYDNEY
	PEREZ, GEORGINA
244	HALL, KAREN S
	WHITE, MICHELLE C
248	CRANE, RON
	FLOOD, DON O
250	MARTINEZ, MELISSA A
252	LOPEZ, JOSH
	MORALES, MARIA T
255	AGUIRRE, MAXIMO R
	CAPANGAN, GENE
	ELBELLE, ELIZABETH E
	JORGENSON, LANCE K
	PENROD, CECILIA E
	RASMUSSEN, JENNIFER L
264	OVIEDO, LORENZO
	RODRIGUEZ, JAVIER
	SARRIZ, MARIA L
265	BEMAL, MARIA
	ESCANO, JINKY
	GARCIA, ADRIAN
	HUGHES, JESSE J
	MCINTYRE, BRET M
	SANDOVAL, RAUL S
	URIAS, EMILIO
	VERA, ARAMIS D
268	LAM, BENITO A
	LOPEZ, JUAN J
	RODRIGUEZ, HENRY
282	GARCIA, NADINE
283	JON MILLER REALTY
286	BUTLERS AUTO REPAIR
309	BEESON, RENEE
	GARDUNO, CARLOS
	SALAAM, ESKHARIA
	VILLEGAS, RAMIRO
310	CASTRO, JOSE
	COBB, MICHAEL R
	CONLIN, NAYELI
	CORONA, GIOVANNA
	ESPINAL, JOHN V
	FLORES, GUILLERMINA O
	GANS, SUMMER
	PEREZ, EDWARD
	SKELTON, GREG
	STIVERS, SUSANA S
	TORRES, SALVADOR
	YOUNG, LINDA L
	YOUNG, PATRICIA L
311	THOMPSON, WAYNE K

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

313	DIAZ, NACOR
	FIOL, RENE A
315	MORALES, JESSE
317	BRUDER, ROBERT M
	QUINTERO, EDGAR A
	QUINTERO, VICTOR
318	CALDERON, JOSE D
	DELTRAN-CALDERON, JOSE
	HARTENSTEIN, PEDRO
	HERNANDEZ, KIMBERLY
	NIGHTINGALE, CRAIG
	VERDUZCO, JESUS R
319	TORRES, LYNN
320	CAMBRANIS, JORGE
	HERRERIAS, FRANCISCO
	RICO, RICHARD A
	ROMERO, JUAN
	SKELTON, GREGORY A
	WALKER, ROBERT L
329	GARCIA, VANIA
	HERRERA, JUAN
	REYES, MARY
330	CASTILLO, JOSE N
	PARKERSON, GEORGETTE L
	PELLATIRO, LOUIS J
	RIVERA, ESTEBAN
	SHEA, KELLY
	VAZQUEZ, HECTOR R
333	OGILVIE, EVA I
334	AGUIRRE, LARRY J
	AMADOR, ALICIA B
	CARRANZA, WALTER S
	CONTRERAS, GILBERTO C
	CUEVAS, ANNEL
	HERNANDEZ, ROSAURA
	KASEM, TAMARA
	MONTOYA, RUBEN A
	PACHECO, MICHELLE
	PERCHEMLIAN, TANIA
335	WILLIAMS, CHRISTINA L
336	ARCE, ARACELY
	OWEN, ILA J
	RAMIREZ, ABIGAIL B
340	BONE, MARY
	MAGANA, ANTONIO
	RUVALCABA, FERNANDO
	WHEELER, TEREZA G
341	MILLER, MELISSA D
	SHAW, STEVE E
345	PEREZ, ROBERTO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

350	BERNACHI, BRENDA
	CANEDO, NELLY C
	CISNEROS, SHANNON L
	COOK, EUGENE E
	DENHERDER, WALLACE D
	FERRIS, DENISE M
	FORTIN, BRIDGETTE
	GASTELUM, LARRY J
	GIGEAR, PAULETTE P
	GOMEZ, AMY
	KIDWELL, CAROL S
	KRUSAS, CHARLENE F
	MAFUD, ALANA
	MORALES, ARTURO
	NGUYEN, BRIAN
	ROARK, ERIC A
	RODRIGUEZ, JENNIFER
	VENEGAS, VALERIE
	WESSELS, WH H
	ZATARAIN, HECTOR R
363	KERN, STUART
	TORAIN, MAURICE A
367	CHAVEZ, JAMIL
368	MONTANEZ, LYDIA L
	ORTIZ, MARTHA
370	ESTRADA, FRANCISCO
371	CARRERA, WINDY
372	ARCE, MARIA V
	GARCIA, JOSE G
	KOPACZEWSKI, KRISTEN
	LOPEZ, JUAN
	LOPEZ, JUANA A
	REINOSO, KATHERINE
375	IGLESIAS, MARCO A
385	MARTINEZ, JUAN M
386	VELAZQUE, PABLO I
390	MADDOX, WILLIAM B
	STEMMERMANN, KIMBERLY
391	ALVARADO, ARTURO
	CANTOR, EDWARD
	CASTANEDA, ROSA B
	HITCHCOCK, VIRGINIA L
	URIBE, ADAM
	VALDEZHERNANDEZ, LUIS
	VASQUEZ, MICHAEL A
394	FLORES, FRANCISCO
	PALAFOX, ROSA A
399	ADAMS, BRANDI
	MACHADO, FABIAN
	VILLAVICENCIO, PAUL J

G ST 2017 (Cont'd)

402	MANRIQUE, CHRISTIAN
404	OREA, DORA
408	CORONADO, AARON A
410	TREJO, CECILIA
411	CORONA, BLAS G
	CORTES, YADIRA
412	FIGUEROA, ROSA
415	BOSCOSKY, LYNN I
418	VERA, DAVID
420	PUPUHI, GLORIA A
423	FLORES, JOHN
	MERCHANT, ANDRES
	SWISENBERG, FAITH
424	AYALA, BLANCA
	CASTANEDA, JUAN
	REYES, FRANCISCO
	RODRIGUEZ, BERENICE C
	ROSAS, ELLEN G
427	WOOD, ARLEN O
431	WILLIAMS, DAVID S
433	MORALES, MARIA L
439	CHAVEZ, MARIA J
443	ESQUIVEL, ELENA H
447	HEITMAN, COLLEEN
	YANEZ, ANDREA
453	GARCIA, MANUEL M
459	NUNEZ, MARIA J
463	CALVIN, ANGELA M
469	ALOYO, ANGEL L
473	ANDRADE, MONICA I
479	MENDOZA, AIDA Y
481	TREJO, ROGELIO A
485	CRUZ, ROSEA M
	OXILIFE
489	MARQUEZ, SANDRA
503	LOPEZ, IVAN
507	MURRAY, WILLIAM W
515	HERNANDEZ, EDWARD
517	SOTO, LINDA M
521	AVILA, BELEN
	MANZANARES, IRENE J
	TEMBLADOR, MARIO A
	TORRES, JOSE
525	AVILA, BELEN
531	CONTRERAS, EDUARDO
535	BOJORQUEZ, BERTHA
	CASTRO, ANTHONY M
	DE, ZENAIDA
537	COSIO, ELVA
	HORT, SHERRY R

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

537	QUILES, MARTHA
	SILVA, SAMUEL
540	VISTA SQUARE ELEMENTARY SCHOOL
541	BANKS, ASHLEY K
	DIETZ, JARED P
543	ALDRETE, ALICE
	MARTINEZ, MIKE R
551	BACHE, GERARDO
	DUARTE, LUIS A
	GARCIA, FABIAN L
	IBARRA, OLGA
	MARIN, EDUARDO
	MEZA, LILIA
	SALGADO, EDUARDO M
	SAUL, AXIA I
553	GASTON, CAMOU
	MORENO, SAUL
	REAL, PAUL A
	VARGAS, JANY
556	HOCUTT, SHERIKA N
560	FARFAN, VICTOR A
561	GARCIA, LETICIA
	LIZARRAGA, JULIA
	VASQUEZ, MARIA Y
564	BOUGHAN, ESTELA B
	FEELEY, J
565	COLLINS, VERONICA
	ESCOBAR, ELIAS
	SANCHEZ, VICTOR
	SANTILLAN, ELIZABETH
	VALENZUELA, ARMANDO
568	MAYEN, MELISSA L
580	BADEAU, CHARLIENE
	BARBOSA, VICTOR M
	BERNAL, JOSE M
	BURNSIDE, ELLEN M
	DIAZ, JUAN
	FAGAN, THOMAS
	FIGUEROA, ELVIA
	GARCIA, BERNAL A
	GREFALDEO, LORETO G
	MELENDEZ, MARIO I
	MENDOZA, MIKE S
	MONRREAL, JUAN C
	NAVARRO, MARCO A
	SAYLOR, STEPHEN J
	THE GLORIA APARTMENTS
	VALDEZ, CESAR
585	JL SOUND
590	BECERRA, JUAN

G ST 2017 (Cont'd)

590 CLARK, RICHARD
GALINDO RUIZ GUADALUPE
610 ALVAREZ, VANESSA
AVILA, SILVIA
BACA, RIKI E
BLUNT, ALBERTHA
CHAVEZ, FRANK A
CISNEROS, GUILLERMO E
CISNEROS, MARIA
COBIAN, ALICE
CUSTODIO, HENRY
DESAHAGUN, ROSENDO S
ENCISO, NOEMI B
FLETES, DOMINIQUE
HABEEBULLAH, LINDA A
LUNA, XOCHITL C
PEREZ, IVAN D
PIPES, AMBER D
REED, ALICIA
RODRIGUEZ, IRENE
ROGOFF, ARIES
TOLEDO, SANTIAGO
TORRES, MARIA S
ZAMORA, MONICA
616 ACUNA, KAREN Y
ARANETA, MARYJANE J
ARCE, SHERWIN
ARCOS, ROBERTO
ARMAS, MELISSA C
AVELAR, SAMUEL
AVILEZ, GLORIA
BURNS, BRANDON
CANSECO, FELIPE
CARRAWAY, MARIA
CASTELLANOS, GABRIEL C
CASTILLO, MARCUS S
CHAPMAN, GALE R
DAVILA, LEANDRA
DEGUZMAN, CORNELIA C
DELACRUZ, GUADALUPE D
DUARTE, JUDY
DUVALL, PATRICK D
EWEST, RONALD V
FLADE, MATT
GARAN, BARON F
GARCIA, JOSE A
GENERAL PARKS LLC
GIL, FRANCISCO
GOMEZ, EVA M
GONZALES, JAIME

G ST 2017 (Cont'd)

616	GUTIERREZ, SCARLETT
	HERNANDEZ, HECTOR A
	HERRERA, RICARDO
	HOLLINS, DORIS A
	HORTA, RUBEN
	HOWELL, JASON S
	HURTADO, JAVIER
	INZUNZA, MARISA
	JARAMILLO, JUANA C
	JOHN, Y
	KUEBLER & KUEBLER LIMITED
	LESNESKI, G
	LUNA, JUANITA
	MARISCAL, LIDIA A
	MARTINEZ, ALEJANDRO D
	MARTINEZ, MARIA
	MARTINEZ, VICTOR
	MCCLELLAND, RONALD
	MCMILLAN, STEWART B
	MEDINA, FORTUNATO A
	MEJIA, TINA
	MOHR, MITCHELL J
	MONTOYA, MIGUEL A
	MURAD, CECILIA
	PINEDA, MARK R
	RAMIREZ, MARLA
	RENDON, HORTENCIA G
	RODRIGUEZ, RICARDO E
	RODRIQUEZ, RICARDO
	ROUJANSKY, CAROL L
	SANCHEZ, JOSE L
	SANCHEZ, TOMAS I
	SCHIAFFINO, JOSE
	SNYDER, DANIEL R
	THOMPSON, KIMBERLY
	TIRADO, HECTOR
	URIBE, SONIA
	VALLE, FAUSTINO F
	YASMINEH, JOHN J
628	VALLE, RUBEN
633	JACKSON, PETRA
635	LARRO, SILVIA
651	AGUILAR, JOSE L
677	AHRENS, CLAUD
	ALFARO, JEFF
	AMAYA, LUZDEL C
	ARANDA, MARIA G
	ARGUELLO, MIGUEL M
	ARROYO, ROSA C
	ARSENAULT, JOHN E

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

677 AUDLEY, EDWARD F
AUSTRIA, PRESCILA
AVILES, MARCELA V
BAILEY, ROBERT
BERGERON, RAYMOND J
BESHEARS, IMELDA M
BIGGERS, DOROTHY R
BLANCK, SKIP
BLINN, GLEN E
BOLDRIDGE, LEON I
BREARLEY, WALTER D
BROWNING, DALIA O
BUCHANAN, PAUL
BUTTERWORTH, MARCELLE S
BYRD, VELVA J
CAMPOS, HERMELINDA
CARRANZA, JENNIFER
CASKINETTE, RICHARD J
CASTRO, FRED H
CEJA, RODOLFO M
CHRISTENSEN, BRENDA
CLARK, PATRICIA A
COMMER, RAFAEL
CONNOLLY, ANGELINA G
CORTEZ, JOHNNY M
CRABBE, MICHAEL P
CRIE, WILLIAM D
CROCKETT, BONNIE W
CRUMP, DANIELLE A
DELCAMPO, ENRIQUE M
DUGAN, DON N
EDWARDS, CLAUDE G
EPSTEIN, RANDY P
ESCOTO, REYES G
FAIRLEE, LARRY L
FERNANDEZ, JOSE L
FRANCOUR, SANDRA L
GENTZ, LINDA I
GINDROZ, ROBERT J
GOMEZ, MICAELA L
GOMEZ, PABLO
GONZALEZ, JOSE A
GONZALEZ, LORETO
GRAVES, DAVID
GRAVES, REBECCA
GUERRA, JOE R
HAHN, RAY A
HALL, DONALD W
HEDGE, WILLIAM A
HERMOSILLO, MARIA L

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

677
HERNANDEZ, GUADALUPE
HERNANDEZ, MARCO
HERRERA, FRANCISCO J
HIGA, DOROTHY T
HOFF, RONNIE J
HOGAN, ALMA J
HUBERT, RICHARD L
IBANEZ, RUBEN N
JOHNSON, RONALD G
JONES, LAMAR R
KAMINS, SYBIL R
KANITZ, LEVY L
KELLOGG, HEIDI C
KIRKPATRICK, SARA
KRAMER, JAMES M
KRUPINSKI, DOUGLAS J
LEACH, JEFF F
LEGASPI, OSCAR L
LIMIN, ESTER M
LISTER, ROBERT R
LOZANO, ARMIDA
MACIAS, ADELINA
MAEVA, TUTAI
MANLEY, SARA J
MANNON, THEODORE T
MARK, DOROTHY
MARKEL, JOSEPH L
MARTINEZ, CARLOS L
MELENDEZ, ERNEST
MELVILLE, MARGARITA B
MEZA, MARCELA A
MORALES, ANDRES M
MORRIS, AARON B
MORRIS, REGINALD J
MOTL, STEVEN
MOYA, ELIZABETH
MUCH, JULIETTE E
MUSGRAVE, ROSE M
NEAL, JULIETTE M
NEWNHAM, EDITH L
ORAMAS, JOSEFINA O
OSUNA, ANA M
OURS, JUDITH E
PAGE, SYLVIA J
PALOMARES, MARIANA
PARMLEY, RONALD A
PASSENEAU, CAROLYN S
PEARSON, GLADYS M
PETRA, CRUZ
PRECIADO, PETRA G

G ST 2017 (Cont'd)

677	PROVENCHER, JANICE L
	RADINOVSKY, KATHRYN M
	READER, MALINDA S
	RIVERAASTACIO, JOSE E
	ROBBINS, BRUCE E
	ROCHA, JOSE
	ROSSETTI, RITA J
	SANDOVAL, DONNA J
	SCHLEGEL, JERRY J
	SHAFFER, ORLA
	SHAWBELL, LEWIS R
	SILVA, DAMIANA
	SMITH, CINDY L
	SPITZER, JOYCE L
	STINEBUCK, NANCY J
	SUNSET CAB
	TAAVASA, FRANKIE L
	TERRYS MOBILE PARK
	THAYER-STOKES, LAVERNE M
	TIMBOL, NENITA
	TORRES, MARK
	TURO, MARJORIE L
	VASQUEZ, ADELINA C
	VAZQUEZ, JOSE C
	VELASCO, ISAURA
	VIGIL, GREG F
	VILLAFUERTE, JOSE D
	VISTA, GLORIA
	VOGT, HERMELINDA M
	VOLLER, NORMA J
	WADELL, LORRAINE C
	WALKER, YONG C
	WATKINS, WILLIAM R
	WATSON, KENNETH D
	WESTON, NANCY O
	WITMER, MICHAEL P
	WOOD, CAROLYN F
	YOUNG, PAUL G
	ZAMUDIO, ORALIA G
	ZARAGOZ, ALBERTO N
	ZEPEDA, ROSA L
704	BARAJAS, MARTHA
	GARCIA, JUAN A
	GARCIA, MARIA
716	CORONADO, HENRY H
	RAMIREZ, GABRIEL
	YOUSSOFI, TERESA
724	JOHNSON, STEVEN
	PHILLIP, MERVYN
	STIMPSON, MARY E

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

731 ACKER, JOHN S
AGLIPAY, RONALD M
ALEXANDER, MARIA S
ANDERSON, BILLIE J
ARCE, MARIA E
BACALLAO, IRMA A
BARRAGAN, PETRA P
BEELES, RONALD G
BENFER, ESPERANZA Z
BONATUS, JACKIE D
BOWLES, PEGGY D
CABRILLO MOBILE HOME PARK
CASTANEDA, ODILA
CASTRO, PABLO
CISNEROS, BULMARO
CLAY, MARSHALL L
CONTRERAS, MARIA
CRUZ, REYNALDA N
CUEVA, FILIBERTO C
CUNARD, MARIA E
DEMOORE, IRMA
DORSCHER, SHEILA
DUENAS-JR, RAMON J
EASTWOOD, MARIA B
ELIAS, MARTHA G
ENCISO, MARIA M
ESTRELLA, ELVIA
FALLING, BILLY
FIERRO, SILVINA
GALEANA, FERNANDO
GALEANA, MARIA
GARCIA, RITA
GLEASON, EDWARD J
GOMEZ, ROSALINDA
HAUSWIRTH, DENNIS J
HEADLAND, JAMES N
HERNANDEZ, ANGELICA L
HERNANDEZ, EVA
HERNANDEZ, JUAN S
JUAREZ, JESUS A
KARAKEY, APOLONI A
LITTLE, MICHAEL D
LUGO, ANGELINA L
LUPPENS, JOHN A
MANJARREZ, MARIA C
MARCUSSEN, BJORN B
MAYBURY, KATHLEEN R
MCGONIGLE, GARY R
MEDINA, DAVID E
MELVIN, JOHN H

G ST 2017 (Cont'd)

731	MENDOZA, PEDRO
	MILES, BOB P
	MILLER, JOSEPH R
	MOORE, IRMA C
	OLSON, ARACELI
	ORTEGA, FLAVIO
	ORTEGA, SARAH
	ORTEGA, ZENORINA
	OVERSTREET, JEAN L
	PALOMINO, PASCUAL
	PATRON, MARIA G
	PENA, MANUELA
	PENNERMAN, WILLIAM A
	PERRY, HARLEY L
	PRADO, GUADALUPE R
	REYES, IRMA
	REYNOSO, JESOS J
	RHOADES, TERRY M
	RICHARDS, ROBERT S
	ROMERO, NORMA B
	SAMANIEGO, GUILLERMO A
	SANCHEZ, EFRAIN
	SEGHERS, DOREEN H
	SIZE, KIM
	SPATIG, BETTY L
	TALAMANTES, PATRICIA
	TOBIE, SOTO G
	TOSCANO, VICTORIO A
	TROY, JOHN W
	TUMBOKON, ELVIRA L
	TURNIR, MAGDALENA
	URIBE, LUIS
	YOUNG, FLORENCE A
	ZARATE, MARIA A
	ZENORINA, ORTEGA
	ZIDLER, MILAGROS
	ZIGLER, MILAGROS D
	ZINN, ALEXANDRA C
736	DEJESUS, TOMAS M
	LOZANO, ASHLEY
	VELA, EDUARDO
	VELAZQUEZ, PRISCILLA
997	MARINE GROUP BOAT WORKS
	TRUITT MACHINE & FABRICATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014

14	ACKERMAN, RICHARD J
15	HALE, DOUG
30	FLACKE, HELFRIED G
36	OCCUPANT UNKNOWN,
39	ROYAL GARDEN GUEST HOME
	TABLADILLO, RODOLFO C
42	HILDEBRAND, ERNEST H
45	TAYLOR, JONATHAN W
48	THOMAS, ROBERT A
52	SHADDUCK, GARY N
55	RICHARDSON, MICHAEL A
60	DEESE, BOBBY L
66	YU, EDWARD H
67	FOURROUX, GUVERN
70	STANCZAK, EDWARD
71	MICHAEL, BRAUN
	NELSON, ROSALYN J
77	ARAIZA, ALEXIS
78	DUARTE, SAUL L
83	ARIZAGA, RAUL
84	GRANADOS, ERNEST C
86	DUNKLE, RAYMOND E
87	CHASE, PALMER S
90	MURRAY, LUPE M
93	FORTUNA, EDMUND F
102	MEJIA, MANUEL
108	CARRERA, CECILIA M
111	DALE, JANE E
115	COVARRUBIAS, ROMAN J
121	ZAPPONE, PATRICIA A
130	HULST, WARREN J
134	HARGIS, PATRICIA J
135	TOMIC, BETTY
140	TELLO, DOROTHY M
141	ARREOLA, IRMA J
147	COLON, IVAN K
155	EVAN, LARRY D
	MOUNTAIN CHESS LAKE CAMP
156	HUVAR, CAROL L
159	WALLACE, JEFF S
160	MICHEL, JOEL E
161	BIOMMELL, DARRELL L
163	RASCON, MARISA R
164	KELLY, THOMAS M
167	HINOJOSA, ROBERT
170	COSTELLO, PAUL M
173	FEMANDEZ, ANDREW
174	MOLSBERRY, MARK A
177	OCCUPANT UNKNOWN,
181	MOORE, DENNIS P

G ST 2014 (Cont'd)

182	BARNES, ALBERT A
186	MONTAGUE, ALISSA M
194	VAZQUEZ, ALFREDO
195	TROTTER, RONALD G
197	ESPIRITU, JEFFREY M
198	DENT, TRACY A
202	POWELL, TOMMY
203	JOHANSEN, JACK
207	AMOS, ANSON S
210	ZUNIGA, ANA B
211	QUINONEZ, JAIME
215	PARKS, JUANA L
217	BLACKWELL, WARRIENE
222	ACEVES, NORMA
	BUDIONGAN, ROBINSON M
	CAREY, ANN M
	CASS, ERA A
	CATE, CHARLES A
	CELIA, ROMERO
	COREY, JOAN L
	CORONA, JOSE E
	COVARRUBIAS, M
	CUEVA, HERNANDEZ
	DEKLE, JEROME
	DELGADO, CHARLES G
	DELOPEZ, ESPERANZA
	ENGLISH, WAYNE S
	GARCIA, LORI
	GARZA, GLORIA
	GISH, MILDRED E
	GUIMONT, LANCE
	HARRIS, JANE N
	HORNADAY, SANDRA
	HOVERMALE, CONNIE
	MARTINEZ, ELIAS M
	MCCASKILL, BARBARA J
	MORA, JOSE O
	NUNNELEE, BARBARA G
	PARRA, RAYMOND A
	PENWELL, EDITH A
	PORTERFIELD, DAVID M
	REYES, GUADALUPE B
	RUIZ, MONICA L
	SCRIPOCH, ELIZABETH N
	STEWART, WARREN C
	VENEGAS, M
	WRIGHT, CHRISTINE M
223	GANDARA, SERGIO M
	LOPEZ, MELISA
	SILVA, CARLOS

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

223	ZULAICA, BENITO H
226	BARRAZA, JESUS R
	CASTANEDA, TERESA
	MARTINEZ, PABLO
	TANTON, HEATHER J
227	GONZALEZ, MANUEL G
	OCCUPANT UNKNOWN,
228	OCCUPANT UNKNOWN,
229	MOSHER, KEITH E
233	DOEGE, PATRICIA M
236	OCCUPANT UNKNOWN,
239	RAMOS, ARMANDO O
240	NIDO, FERNANDO
241	CRESPO, LETICIA
	MUNGUIA, VANESSA
	POWELL, RICHARD K
	SALAZAR, CHARLES R
	VIEYRA, ALBERTO
244	MCINTYRE, ANTHONY
	OCCUPANT UNKNOWN,
	WALTERS, SANDRA F
246	OCCUPANT UNKNOWN,
248	BROWN, GREGORY J
	CRANE, RON
	OCCUPANT UNKNOWN,
250	BLASINGAME, HOWARD L
	HERNANDEZ, GONZALO M
252	HERRERA, ELENA L
	LOPEZ, ROSALVA
	MEJIA, GIZSY
	MEJIAS, NATHALIE
	MORALES, MARIA A
255	AGUIRRE, MAXIMO R
	CAPANGAN, GENE
	ELBELLE, ELIZABETH
	FINNEY, MICHAEL
	JORGENSON, LANCE K
	LOPEZ, GUILLERMO A
	RASMUSSEN, ELEANOR
264	SALAZAR, GRISALDA M
	TAKASHIMA, RACHEL H
265	CHAVARIN, MARYLOU L
	COWHERD, JUDITH M
	HUGHES, JESSE J
	MCINTYRE, BRET M
	REYES, ALLISON
	RIVERA, MARILOU
	SANDOVAL, RAUL S
	VERA, ARAMIS D
268	AGUILAR, EDGAR

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

268	BRADLEY, DAMA O
	RODRIGUEZ, HENRY
274	PAEZ, KARLOS A
281	SERVICE RITE ELECTRIC
282	OCCUPANT UNKNOWN,
283	JON MILLER REALTY INC
286	BUTLERS AUTO REPAIR
309	GARDUNO, CARLOS
	GUZMAN, DAVID
	RUIZ, KARLA
	VILLEGAS, RAMIRO
310	ALLISON, CHRISTINA L
	CONLIN, JEROME D
	FLORES, GUILLERMINA O
	GANS, SUMMER
	HALL, EMILY
	PEREZ, EDWARD
	PINNEY, DENA D
	SAMUELS, ELIZABETH
	SKELTON, GREG
	STIVERS, SUSANA S
	WEBB, RAYMOND R
	YOUNG, MARCELLA L
311	THOMPSON, WAYNE K
313	FIOL, RENE A
	VELASQUEZ, VALERIA
315	MORALES, VIRGINIA
316	ROBLES, BETTY
317	BRUDER, ROBERT M
	OCCUPANT UNKNOWN,
	QUINTERO, EDGAR A
318	GONZALEZ, SAUL
	NIGHTINGALE, CRAIG
	PEREZ, MARY
	VAZQUEZ, JESSICA
	VEGA, VICTORIA
319	RIOS, BRENDA
320	CAMBRANIS, JORGE
	MEYERS, JENNIFER E
	ROMERO, MARIA E
323	HIRSCHY, WAYNE T
325	MENDEZ, BIBIANA
329	MENDOZA, BRIANNA
	PINA, MICHAEL R
330	ARRIAGA, AL
	GONZALEZ, RUBEN
	GUTIERREZ, ROSARIO
	PARKERSON, GEORGETTE L
	PELLATIRO, LOUIS J
	RIVERA, ESTEBAN

G ST 2014 (Cont'd)

330	SHEA, KELLY
	VAZQUEZ, HECTOR R
333	OGILVIE, EVA I
334	AGUIRRE, LARRY J
	CONTRERAS, GILBERTO C
	GILLETTE, LISA R
	JORDAN, CHRISTIAN D
	MARTINEZ, STEPHANIE
	MONTOYA, RUBEN A
	PACHECO, MICHELLE
	PERCHEMLIAN, TANIA
335	WILLIAMS, CHRISTINA L
336	ALVAREZ, EDWARD
	RAMIREZ, ABIGAIL B
	RIVERA, JUAN J
340	BONE, MARY
	MAGANA, ANTONIO
	RUVALCABA, FERNANDO
	SANTANA, MARTHA
341	MILLER, MELISSA D
	SHAW, STEVE E
345	LOPEZ, FORTUNATO G
350	ARRINGTON, DEME
	BERNACHI, MARIO A
	CANEDO, NELLY C
	CARRANZA, JOSHUA
	CERVANTES, BERNADINA
	COOK, EUGENE E
	DAMON, SHAUNDELLE
	ESTRELLA, JOE
	FISHAUF, NATHAN
	GIGEAR, PAULETTE P
	GIOAKARIS, CARMEN D
	GUZMAN, JOSE M
	KIDWELL, RALPH W
	KRUSAS, CHARLENE F
	KUGLER, MANNIE L
	ROARK, ERIC A
	ROJAS, ENEDINA A
	SABELLA, EL G
	VENEGAS, VALERIE
	ZATARAIN, HECTOR R
363	TORAIN, MAURICE A
364	ESCOBEDO, DANIELA
367	OCCUPANT UNKNOWN,
368	ORTIZ, MARTHA
370	ESTRADA, FRANCISCO
371	CARRERA, WINDY
	FLORES, FRANCISCO A
	RODRIGUEZ, JUVENAL

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

372	ARCE, MARIA V
	DEVAZQUEZ, MARIA A
	JUANA, ARMIDA
	LOPEZ, JUANA A
	SMITH, ASHLEY
	TOVAR, EDGAR
374	ANGULO, VICTORIA G
375	BARAJAS, GABRIEL
	IGLESIAS, MARCO A
379	OCCUPANT UNKNOWN,
385	MARTINEZ, JUAN M
386	MORENO, MARTHA
390	JENKINS, RUDOLPH J
	MADDOX, WILLIAM B
	VALENZUELA, VERONICA
391	ALVARADO, ARTURO
	CASTANEDA, ROSA B
	DELGADO, ROBERT M
	GALA, AMELIA
	HINOJOSA, MARIA
	HITCHCOCK, VIRGINIA L
	LAPOINTE, LORI K
	URIBE, ADAM
394	ATIENZA, PATRICK
	FLORES, APRIL
	HERNANDEZ, IRMA
	PALAFOX, ROSA A
	PRADO, PETER
399	ADAMS, BRANDI
	JOSE, LARIOS
	MACHADO, FABIAN
	VILLAVICENCIO, PAUL J
402	MANRIQUE, CHRISTIAN
404	BALVANEDA, MARIA
408	CORTEZ, ROBERTO C
410	TREJO, ALFREDO C
411	CORONA, BLAS G
412	FIGUEROA, ROSA
414	LUTES, MICHAEL J
415	KEARNS, PATRICK B
416	PRECIADO, JOSE A
418	VERA, ALEJANDRINA
419	BOSCOSKY, ROBERT Z
420	PUPUHI, GLORIA A
422	OCCUPANT UNKNOWN,
423	ANTHONY, S
	BARAJAS, JOSE
	FLORES, JOHN
	MERCHANT, ANDRES
	PENA, EDUARDO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

424	AYALA, BLANCA
	CASTANEDA, JUAN
	HUDSON, STEPHEN J
	MCLAUGHLIN, HERMELINDA
427	WOOD, ARLEN O
431	LOPEZ, HENRY
433	MORALES, JIMI
439	OCCUPANT UNKNOWN,
443	ROBLES, GASPAR J
447	BUZAN, TFFANY R
453	GARCIA, MANUEL
459	HERRERA, MARIA A
463	AKERS, JUSTIN W
469	ALOYO, ANGEL L
473	DAVALOS, DEMESIO D
479	MENDOZA, AIDA Y
481	ANDRADE, DIANA
	BAILEY, JEANELLY
	LITTLETON, CONNIE
	SILVA, GILBERTO
	TREJO, ROGELIO A
	TREJO, VICTOR
	WYLIE, GARRY M
485	OXILIFE
	VILLAGOMEZ, ANTONIO R
489	BOYCAN, MELISSA M
502	VAZQUEZ, AGUSTIN
503	LOPEZ, OBDULLA
507	MURRAY, WILLIAM W
513	CORONA, AIXA
	MURPHY, PATRICIA I
515	HERNANDEZ, NANCY
517	LEE, MARY
519	REYES, CESAR R
521	AVILA, BELEN
	MEJIA, DANA
	RAMIREZ, MARCELA
	ROBLES, RAFAELA
525	OCCUPANT UNKNOWN,
529	VASQUEZ, FELIPE A
531	VASQUEZ, MARCIA Y
535	AVILA, SUGEY
	FRUTOS, MANUEL A
	LIRA, MARLYN
	MORLES, JULIE J
	OLALDE, AZENTH
	QUILES, MARTHA
537	COSIO, ELVA
	MONTES, DEOCA Z
	MONTESDEOCA, FERNANDO

G ST 2014 (Cont'd)

537 SILVA, SAMUEL
VELASQUEZ, MARTIN
540 VISTA SQUARE ELEMENTARY SCHOOL
541 BANKS, DONNA D
DIETZ, JARED P
543 MARTINEZ, LUIS
OCCUPANT UNKNOWN,
551 ACEVEDO, NANCY
DUARTE, LUIS A
GARCIA, FABIAN L
MADRIGAL, BRENDA
MEZA, LILIA
SALGADO, EDUARDO M
553 MERCADO, ANA
RUIZ, MOISES
VARGAS, JANY
556 ANGUIANO, JOEL
560 FARFAN, VICTOR A
561 CHAVEZ, ANA
LIZARRAGA, JULIA
ROBLES, MARCO A
ROSA, PANIAGUA
VASQUEZ, MARIA
VILLANUEVA, RUBEN F
564 BOUGHAN, ESTELA B
FEELEY, J
FRANKENBERGER, THOMAS K
GONZALEZ, SAMANTHA
565 CERVANTES, TERESA
MARTINEZ, MAGDALENA
QUINONES, FANY
SANCHEZ, VICTOR
567 OCCUPANT UNKNOWN,
568 MAYEN, MELISSA L
571 FORD, JOEL P
580 ASTORGA, ALICIA
BADEAU, CHARLIENE
BARBOSA, VICTOR M
BERNAL, JOSE M
ELIZALDE, IRMA
GARCIA, BERNAL A
GLORIA APARTMENTS THE
GREFALDEO, LORETO G
HERRERA, JAVIER
KEYS, CARL
KHAZAL, VERONICA
LAMERS, STEPHEN J
LEWIS, DALE
MENDOZA, MIKE S
MONRREAL, JUAN C

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

580	OCHOA, MARIA S
	ORTEGA, GLORIA
	RAMOS, CARMEN
	SAMANO, LARRY
	TORRES, CESAR
581	OCCUPANT UNKNOWN,
583	OCCUPANT UNKNOWN,
585	J L SOUND
590	CLARK, RICHARD
	GALINDO RUIZ GUADALUPE
	MEMOS CUSTOM CANVAS
610	ALVAREZ, VANESSA
	BACA, RIKI E
	BRIER, VERONICA G
	CARTER, BARBARA N
	CHAVEZ, FRANK A
	CISNEROS, GUILLERMO E
	CORTES, MAELENA
	CRUZ, MICHAEL
	CUSTODIO, NOEL T
	GARCIA, RENAN
	GARCIA, SERGIO
	GONZALES, JAIME
	GUTIERREZ, HERNANDO
	HERNANDEZ, JESUS G
	LUNA, XOCHITL C
	MATTOX, JOYCE M
	PATRICIA, ANASTACIO
	POQUI, CARMEN
	RANGEL, FRANCISCO
	REYES, ARTURO L
	SOTELO, LUZ
	TIDWELL, DONTE
	TORRES, MARIA S
616	ACUNA, KAREN
	ALCAZAR, GINA
	ALMALKI, MAJEEDAH M
	ARANETA, MARY J
	ARCOS, ROBERTO
	AVILEZ, GLORIA
	BANFIELD, JOHN
	CABANA, SARAH
	CAMACHO, JOHNNY P
	CAMPOS, CONNIE
	CANO, MARIA E
	CANSECO, FELIPE
	CARBAJAL, HIGINIO
	CARRAWAY, MARIA
	CARRILLO, ROSA
	CASTILLO, MARCUS S

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

616	CHAPMAN, GALE R
	COKLEY, JOHNTAY
	CRUTCHER, AVALON
	CURTIS, SHERRY D
	DAWOOD, VALENTINA
	DEGUZMAN, CORNELIA C
	DELA, DOLORA
	DELACRUZ, GUADALUPE D
	DONAHUE, CHARLES C
	DUBOIS, MARIA G
	ESTRADA, RAFAEL
	FABILA, BENEDICT
	FIELDING, AARON L
	FLORES, RICARDO C
	GARAN, BARON F
	GENERAL PARKS LLC
	GLOUDON, THOE
	GRANT, JAYDEEN L
	GUTIERREZ, SCARLETT
	HANKS, JAMES P
	HERNANDEZ, LUIS P
	HOLLINS, DORIS A
	HOLMES, HAROLD J
	HOWELL, JASON S
	KNOWLTON, AL
	KORYAL, GANAN
	KUEBLER & KUEBLER LIMITED
	LE, BINH
	LESNESKI, JOHN H
	LINGUISTIC SYSTEMS INC
	LOPEZ, YVONNE
	MARTINEZ, ALEJANDRO D
	MAYA, CHRISTIAN
	MCMILLAN, STEWART B
	MEJIA, TINA
	MENDOZA, JULIEANNE
	MOHR, MITCHELL J
	MONTOYA, MIGUEL A
	MORALES, DESIREE
	MORGAN, PAUL E
	MORTERA, VICTORIA
	MURAD, CECILIA
	NEVAREZ, LUIS
	ONEILL, KEVIN
	PARRA, VERONICA P
	PINA, TERESA
	RAMOS, EDY
	RODRIGUEZ, NOEM D
	RODRIGUEZ, OSCAR
	ROMO, ALICIA

G ST 2014 (Cont'd)

616	ROMO, CARLOS C
	ROSALES, JOEL L
	ROSALES, JUAN
	ROUJANSKY, CAROL L
	SANCHEZ, ANTONIO
	SHROPSHIRE, VINCENT N
	SITHEN, SITHORA
	SLADE, MATTHEW J
	SNYDER, DANIEL R
	SUAREZ, NORMA
	TORRES, ANEL
	VAZQUEZ, ENRIQUE G
	VIRGINIA, ANTOIN
	WARDA, DINA
	WILSON, FATIMAH
	WOOLDRIDGE, AIMEE L
	ZENDEJAS, JAIME
626	DOTSON, NASHELL
628	OCCUPANT UNKNOWN,
629	OCCUPANT UNKNOWN,
633	JACKSON, PETRA
635	OCCUPANT UNKNOWN,
644	FREE WILL BAPTIST CHURCH
650	KRUSAS, CHARLENE
651	OCCUPANT UNKNOWN,
677	ACUNA, ROBERTO T
	AHRENS, CLAUD
	AMAYA, LUZDEL C
	ANDREWS, ELLIOTT
	ANES, ANA A
	ANGEL, MARIA E
	ARROYO, ROSA C
	ARSENAULT, JOHN E
	AUDLEY, EDWARD F
	BAILEY, ROBERT R
	BARRIOS, JOSE G
	BAUMGARDNER, LORAINE J
	BEERS, WESLEY J
	BERGERON, RAYMOND J
	BESHEARS, IMELDA M
	BIBO, ROBERT G
	BIGGERS, DOROTHY R
	BLANCK, SKIP
	BLINN, GLEN M
	BOLDRIDGE, LEON I
	BREARLEY, WALTER D
	BRIZUELA, ISMAEL H
	BROWNING, DALIA O
	BURKETT, SALLY R
	BUTTERWORTH, MARCELLE S

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

677

BYRD, VELVA J
CARRERA, CARLOS M
CASTRO, FRED H
CEJA, RODOLFO M
CHRISTENSEN, BRENDA
CHRISTIAN, MADELYN R
CONNELLY, ROBERT W
CRABBE, MICHAEL P
CRIE, DON
CURTIS, ROGER J
DAKEL, AMBER
DELCAMPO, ENRIQUE M
DOERING, KENNETH M
DOUGLAS, JEFFREY A
DUGAN, DON N
ESCOTO, REYES G
FAIRLEE, LARRY L
FERNANDEZ, JOSE L
FRANCOUR, SANDRA L
GENTZ, LINDA I
GOMEZ, PABLO
GONZALEZ, JOSE A
GUERRA, JOE R
HALL, DONALD W
HARVEY, JERRY D
HEDGE, WILLIAM A
HERNANDEZ, RAFAEL
HERNANDEZ, RAMIRO
HERRERA, FRANCISCO J
HIGA, DOROTHY T
HOFF, BRIAN E
HOGAN, ALMA J
HUBERT, RICHARD L
JACKSON, DAISSE
JARVIS, LEONARD G
JOHNSON, RONALD G
JONES, LAMAR R
KAMINS, SYBIL R
KANITZ, LEVY D
KINCAID, FLORENCE I
LAMB, GLORIA J
LEGASPI, OSCAR L
LIMON, EDUARDO G
LISTER, ROBERT R
LOZANO, ARMIDA
MACIAS, ADELINA
MAMANGUN, ZENAIDA Z
MANLEY, SARA J
MANNON, THEODORE T
MARK, DOROTHY

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

677
MARKEL, JOSEPH L
MARSH, ANNE M
MARTINEZ, MANUEL D
MATHEWS, DORA M
MAXWELL, TOM M
MEILE, RALPH E
MELENDEZ, ERNEST
MELICIA, EUGENIO
MELVILLE, THOMAS
MORRIS, REGINALD J
MOTL, STEVEN
MUCH, JULIETTE E
MURGUIA, ISSAC
MUSGRAVE, ROSE M
NEAL, JULIETTE M
NEELY, BILLY J
NEWNHAM, EDITH L
NIETO, JAMES
OH, WON Y
OSUNA, ANA M
OURS, JUDITH E
OWN A PROPERTY REALTY
PACELY, SILVIA
PARKER, JOE M
PARMLEY, RONALD A
PASSENEAU, CAROLYN S
PEARSON, GLADYS M
PIERCE, MARY M
PIKE, MARTIN E
POE, LINDA L
PROVENCHER, JANICE L
RADINOVSKY, KATHRYN M
RAMIREZ, JOSIE
READER, MALINDA S
REED, EUGENE W
RIVERAASTACIO, JOSE E
ROACH, FRANK D
ROBBINS, BRUCE E
ROSSETTI, RITA J
SHAFFER, ORLA
SILVA, DAMIANA
SPITZER, JOYCE L
SUNSET CAB
TAAVASA, FRANKIE L
TAYLOR, CAROL
TERRYS MOBILE HOME PARK
THAYER-STOKES, LAVERNE M
TIMBOL, NENITA
TURO, MARJORIE L
ULRICH, JIM

G ST 2014 (Cont'd)

677	VALLEJO, JOSE J
	VALLIN, ESTEBAN
	VASQUEZ, ADELINA C
	VAZQUEZ, JOSE C
	VIGIL, GREG F
	VILLAFUERTE, JOSE D
	VISTA, GLORIA
	VOGT, HERMELINDA
	VOLLER, NORMA J
	WADELL, LORRAINE C
	WALKER, JOHNNY E
	WATSON, KENNETH D
	WESTON, NANCY O
	WISCHSTADT, CHRIS
	WOOD, CAROLYN F
	WRIGHT, BONNIE K
	YOUNG, PAUL G
	ZEPEDA, ROSA L
691	GARCIA, REBECA
704	CASTANEDA, FERNANDO F
	GARCIA, JUAN A
	NAVARRO, MARIA E
	RUELAS, MARIA M
	SMITH, HARVEY C
716	BENAVENTE, RICARDO
	CORONADO, HENRY U
	RAMIREZ, GABRIEL
724	JOHN LAFFERTY
	JOHNSON, STEVEN
	STIMPSON, MARY E
731	ACKER, JOHN S
	AGLIPAY, RONALD M
	AHUMADA, ARTURO P
	ALEXANDER, MARIA S
	ANDERSON, BILLIE J
	AYOTTE, JIM
	BARRAGAN, PETRA P
	BEELES, RONALD G
	BENFER, ESPERANZA Z
	BERMUDEZ, RAQUEL L
	BERNAL, AL
	BOWLES, PEGGY D
	BROWN, PAUL R
	CABRILLO MOBILE HOME PARK
	CASTANEDA, ODILA
	CHAVEZ, P
	CISNEROS, BULMARO
	CLAY, MARSHALL L
	CONKLIN, STEVEN R
	CONNER, RONALD D

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

731 CRUZ, REYNALDA N
CUNARD, MARIA E
DORSCHER, SHEILA
DUENAS-JR, RAMON J
EASTWOOD, MARIA B
ELIAS, MARTHA
EROS, JOEL
ESTRELLA, ELVIA
FALLING, BILLY
FARRIS, THOMAS
GALEANA, MARIA
GLEASON, EDWARD J
GOMEZ, ROSALINA
GONZALEZ, DAWNA R
GUERRA, TONY
GUTIERREZ, JUANA
HAUSWIRTH, DENNIS L
HEADLAND, JAMES N
HERNANDEZ, EVA
HERNANDEZ, JUAN S
HUNT, BRENT R
JUAREZ, JESUS A
KARAKEY, APOLONI A
KRASTINE, NANCY
LITTLE, MICHAEL D
MANJARREZ, MARIA C
MAPLE, GRAYDEON R
MARCUSSEN, BJORN B
MARISCAL, MARIA R
MARTINEZ, MARIO A
MAYBURY, KATHLEEN R
MCGONIGLE, GARY R
MELVIN, JOHN H
MENDOZA, ROSA
MILES, BOB P
MILLER, JOSEPH R
OCHOA, GERMAN
PALOMINO, PASCUAL
PARDEE, BARBARA J
PATRON, MARIA G
PENNERMAN, WILLIAM A
PERRY, HARLEY L
PERRY, RONALD K
PRADO, GUADALUPE R
RHOADES, TERRY M
RICHARDS, ROBERT S
RITCHIE, ELIDIA G
ROMERO, NORMA B
RUIZ, IRMA
SAMANIEGO, GUILLERMO A

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

731	SEGHERS, DOREEN H
	SIMPSON, TAMARA
	SPATIG, BETTY L
	TALAMANTES, PATRICIA
	TOBIE, SOTO G
	TROY, JOHN W
	TUMBOKON, ELVIRA L
	URIBE, FRANCISCO
	VELASQUEZ, JOSE A
	WALTHALL, LAWRENCE B
	YOUNG, FLORENCE A
	ZIGLER, MILAGROS D
	ZINN, ALEXANDRA C
736	VELA, EDUARDO
	WISSER, JOHN H
931	BETCHER, FRED
997	PACIFIC YACHT REFITTERS INC
	SOUTH BAY BOAT YARD
	SOUTH BAY BOAT YARD NAUTICAL HARDWAR
	TRUITT MACHINE & FABRICATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010

14	ACKERMAN, RICHARD J
15	MORGAN, O
30	FLACKE, HELFRIED G
36	HIPPERSON, DUANE M
39	ROYAL GARDEN GUEST HOME
	TABLADILLO, RODOLFO C
42	HILDEBRAND, ERNEST H
45	TAYLOR, JONATHAN W
48	THOMAS, ROBERT D
52	VEGA, MICHAEL E
55	SLATER, ELLIE M
60	DEESE, BOBBY L
66	YU, LIU
70	STANCZAK, FRANK J
71	MICHAEL, BRAUN
	NELSON, ROSALYN J
77	SANDERLIN, PAUL F
78	DUARTE, SAUL L
83	ARIZAGA, RAUL J
84	GRANADOS, ERNEST
86	DUNKLE, RAYMOND E
87	CHASE, PALMER S
90	MURRAY, LUPE M
93	STONE, BILLIE C
102	TOVAR, GERARDO
108	GASTON, KERRI
111	DALE, JANE E
115	GALLEGOS, PHILLIP
121	HUFFMAN, JAMES J
130	HULST, WARREN J
134	HARGIS, PATRICIA J
135	TOMIC, BETTY J
140	TELLO, DOROTHY M
141	ARREOLA, IRMA J
146	OCCUPANT UNKNOWN,
147	COLON, IVAN K
152	WOMACK, JULIA F
155	EVANS, LARRY
	MOUNTAIN LAKE CHESS CAMP
156	HUVAR C F 3 GENERAL CONTRACTOR
	HUVAR, CAROL L
159	WALLACE, FRANK T
160	OCCUPANT UNKNOWN,
161	BIOMMELL, DARRELL L
163	RASCON, MARISA R
164	KELLY, THOMAS M
167	JIMENEZ, RICARDO D
170	COSTELLO, PAUL M
173	OCCUPANT UNKNOWN,
174	MOLSBERRY, MARK A

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

177	ESCOBEDO, PEDRO A
181	MOORE, JOSEPHINE H
182	BARNES, ALBERT A
186	OCCUPANT UNKNOWN,
194	ALFREDO, VAZQUEZ
195	TROTTER, RONALD G
197	ESPIRITU, JEFFREY M
198	SMITH, JERRY R
202	TERRADO, FRANCIS
203	JOHANSEN, JACK
207	AMOS, ANSON S
210	FLORES, ZOILA
211	MARTINEZ, MICHELLE
215	PARKS, JUANA L
	SANCHEZ, LUIS R
217	BLACKWELL, WARRIENE
222	BREEDEN, LOIS
	BRUBAKER, SHIRLEY L
	BUDIONGAN, ROBINSON M
	CAREY, ANN
	CASS, ERA A
	CATE, JEAN M
	CHELLO, RENEE
	COREY, JOAN L
	CORONA, JOSE E
	ELLIOTT, SHIRLEY M
	GISH, MILDRED E
	HALL, CAROL V
	HANLEY, RUTH E
	HARRIS, JANE N
	JONES, BETTY L
	LE CHATEAU APARTMENTS
	LOPEZ, ESPERANZA T
	MOFTON, ANN
	MORTON, JAMES E
	NORTH, STANLEY P
	PARRA, RAYMOND A
	PENWELL, EDITH A
	PORTERFIELD, DAVID
	RIVERA, GLORIA
	RODGERS, MARY A
	SANCHEZ, SILVIO
	SANIGA, MICHAEL
	SCOTT, DAVID M
	SCRIPOCH, ELIZABETH N
	STEWART, WARREN
	SWAN, NORMA M
	VILLEGAS, JESS C
	WILLIAMS, ROBERT E
	WILLIAMS, SHERRY L

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

223	BOOTHE, MIRANDA L
	HOUSTON, MICHELE
	PRINCE, MARRISSA A
226	BARRIOS, CARMEN A
	MARTINEZ, PABLO
227	CARBAJAL, MAYRA
	OCCUPANT UNKNOWN,
228	QUINTERO, LAURA
229	MOSHER, KEITH E
233	DOEGE, DOUGLAS W
236	VASQUEZ, PEDRO
239	AGUILAR, EDGAR
	JIMENEZ, ROSA
	MIKELL, SHA L
240	NIDO, MARIA G
241	ESTRADA, MICHAEL D
	MONTOYA, ALFREDO C
	VIEYRA, ALBERTO
244	RICO, MICHELLE C
	WHITE, MICHELLE C
246	TESSLER, DANELL
248	CRANE, RON
	OCCUPANT UNKNOWN,
250	HERRARA, CERTIO A
	HOYOS, CARLOS
	OCCUPANT UNKNOWN,
252	ALCALA, JUAN M
	AVILES, LISBETH I
	CHHITH, SAROEUN
	MEJIA, GIZSY
	TRUJILLO, ANTHONY R
255	CAPANGAN, GENE
	FINNEY, OTIS L
	JORGENSON, LANCE K
	JORGERSON, R
	LOPEZ, GUILLERMO
	MARTINEZ, MONICA
	RASMUSSEN, ANDRE K
264	LANNIN, GARY B
	PURON, FRANK
265	BECKER, KAREN M
	COWHERD, JUDITH M
	CURIEL, LAURA L
	KOGOK, DAVID P
	MARRERO, RONY H
	MIRANDA, EVA C
	PEELER, KERRY D
	WAGNER, DIANE M
268	LAVAUD, GEORGE
	PRECIADO, DAVID

G ST 2010 (Cont'd)

268	RODRIGUEZ, HENRY
274	PAEZ, KARLOS A
281	REAL ESTATE CTR
282	RAMIREZ, FRANCISCO
283	JON MILLER REALTY
287	LOS NINOS HELPING CHILDREN
289	LA BELLA CAFE & GAMES
309	ARENAS, VERONICA
	VIDRIO, ESTHER
	VILLEGAS, RAMIRO
310	ARDREY, MARYANN A
	CONLIN, JEROME D
	FLORES, GUILLERMINA O
	GANS, SUMMER
	HYDER, BRIAN
	MONTANEZ, LIZBETH L
	PEREZ, EDWARD
	STIVER, SUSANA
	STIVERS, G
	TIMMER, SANDRA J
	YOUNG, MARCELLA L
311	GONZALES, EVA
313	BEYDOUN, RAMZE
315	MORALES, VIRGINIA
316	ROBLES, BETTY
	RODRIGUEZ, BRENDA J
	SALGADO, IRMA
317	OCCUPANT UNKNOWN,
	QUINTERO, EDGAR A
318	HART, LINDA E
	HUEZO, ALDO
	JAMES, KAMIRAE
	JENKINS, AMY N
	MUNIZ, CHRISTINA
	NIGHTINGALE, GEORGENE A
	SALCEDO, MELISSA
	VAZQUEZ, JESSICA
319	RIOS, BRENDA
320	CAMBRANIS, JORGE
	DEWEZ, J
	DOLFO, LAURA
	DUKES, VICTOR M
	GUERRERO, MARTIN
	HERNANDEZ, LAURA
	MENDIOLA, HECTOR
	MORALES, NANCY
	ROMERO, MARIA
	SCHNEEMANN, ROLAND
	SKELTON, SHIRLEY
323	DEB & I

G ST 2010 (Cont'd)

325	SANTACRUZ, CARMEN S
329	ALCALA, JUAN
	ARENAS, P J
330	AQUINO, DENNIS K
	BAUTISTA, NORA
	GIL, ANGELICA
	HUIZAR, CYNTHIA
	JUAREZ, GINA
	PELLATIRO, LOUIS J
	PENA, CARLOS
	RIVERA, ESTEBAN
333	OGILVIE, EVA I
334	AGUIRRE, LARRY
	AMADOR, ALICIA B
	BAKER, CHARLOTTE K
	CARRANZA, WALTER S
	CORNEJO, ARTHUR J
	PADILLA, GERARDO
	REYES, JORGE F
	VASQUEZ, AMADA
335	WILLIAMS, CHRISTINA L
336	ARCE, ARACELY
	OWEN, ILA J
	RAMIREZ, ABIGAIL B
340	RUVALCABA, FERNANDO
	SANTANA, MARTHA
345	KENNEDY, JESSICA J
350	ADAME, ALBERT F
	ARAIZA, OSCAR
	BLACKWELL, JOSEFINA J
	BLAKELY, JOHN M
	CAMACHO, JULIE M
	CANEDO, NELLY C
	ESPINOZA, CONSUELO
	ESTRELLA, JOE
	FERRIS, DENISE M
	GASTELUM, LARRY J
	GIGEAR, PAULETTE P
	GIOAKARIS, CARMEN D
	KIDWELL, CAROL S
	KRUSAS, CHARLENE F
	KUGLER, MANNIE L
	MACASADIA, NEIL G
	MARTINEZ, LAWRENCE M
	PACHECO, MARVELA
	PENA, FIDEL
	RAMOS, JOSE R
	ROARK, ERNIE A
	RODE, MARILU A
	SKUZINSKI, PHYLLIS L

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

350 VILLARREAL, D
ZATARAIN, GLORIA
363 TORAIN, MAURICE A
364 GARDUNO, FEDERICO E
VIDABAC INC
367 FIGUEROA, JAMIL R
368 DRAKE, FRANCIS F
MONTANEZ, LIZBETH L
ORTIZ, MARIA J
371 CARRERA, WINDY
FLORES, FRANCISCO F
372 GARCIA, VANESSA
LOPEZ, JUANA A
PIMENTEL, SERAFINA
SMITH, ASHLEY
374 CARRILLO, GABRIEL J
375 BARAJAS, JOSE
KINNALLY, WILLIAM J
379 KAMERY, MARLENE A
385 MARTINEZ, JUAN M
386 ANGULO, JULIO C
INZUNZA, MAURO C
390 JENKINS, RUDOLPH J
MADDOX, WILLIAM B
391 CASTANEDA, ROSA B
CHEN, WEI B
FLORES, PATRICIA
GALA, CARMEN
GOMEZ, KARLA M
TORRES, NATALIA
WOODS, ARMIN
394 ATIENZA, PATRICK
CUNNINGHAM, ANDRE P
GRACIAN, ROSA
HARMON, MICHEAL L
HOLMES, NAEEM A
MELENDEZ, DAVID C
PRADO, PETER
399 JACOBO, MARIA D
REYES, PIEDAD G
VILLAVICENCIO, PAUL J
402 MANRIQUE, CHRISTIAN
406 LUNA, PEDRO
408 SORIANO, RUBEN
410 TREJO, CECILIA
411 CHAVEZ, ANA E
CORONA, BLAS
CORTES, YADIRA
412 MOSBY, MITCHELLE A
414 OCCUPANT UNKNOWN,

G ST 2010 (Cont'd)

415	KEARNS, PATRICK B
416	PRECIADO, MONICA
418	OCCUPANT UNKNOWN,
419	BOSCOSKY, ROBERT Z
420	PUPUHI, GLORIA A
422	ROUSSEAU, LAURA
423	ACEVES, MARA
	BARAJAS, MAYTE
	CARRILLO, MARA A
	FLORES, JOHN
	HERNANDEZ, VICTOR
	LOMELI, DANNY
	LUCERO, ESTELA
	SANCHEZ, JESUS C
424	AYALA, BLANCA
	DOW, CHERE
	HUDSON, STEPHEN J
	SAOMARCOS, CECELIA
427	WOOD, JUAN A
431	HERRERA, IRENE
433	OCCUPANT UNKNOWN,
435	MAYO, ROY J
439	CHAVEZ, MARIA J
	OCCUPANT UNKNOWN,
443	GASPAR, GUADALUPE
453	HARMON, TERRY L
459	FAMILY LOAN REAL ESTATE
	OCCUPANT UNKNOWN,
469	ALOYO, ANGEL L
473	QUINTERO, ALFREDO D
479	JIMENEZ, FABIOLA
481	RENNOLDS, KAREN O
485	GARCIA, CAROLINE P
489	ALVAREZ, NORMA V
502	VAZQUEZ, AGUSTIN
503	LOPEZ, NATARET J
507	MURRAY, WILLIAM W
513	MURPHY, PATRICIA I
515	HERNANDEZ, JAMES
517	GUTIERREZ, ANGELICA
519	OCCUPANT UNKNOWN,
521	IRRIBE, RAFAEL
	PICHARDO, YOLANDA G
	RAMIREZ, MARCELA
	VEGA, DUNIA
525	OCCUPANT UNKNOWN,
529	DELAROSA, BENITO D
531	RAMIREZ, MARIA O
535	CAMPOS, RUBEN
	CASTRO, ELODIA L

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

535	FRUTOS, L M
	IRIBE, MAGDALENA
	LEON, RAFAEL
	LIRA, MARLYN
	MARTINEZ, MARIA R
	MORLES, JULIE J
	OLALDE, AZENTH
	QUILES, MARTHA
537	COSIO, ELVA
	DEOCA, PAULA M
	MONTES, DEOCA O
	RAMOS, ALFONSO
	VELASQUEZ, MARTIN
540	VISTA SQUARE ELEMENTARY SCHOOL
541	BANKS, DONNA
	OCCUPANT UNKNOWN,
543	GUIAO, LARRY
	MARTINEZ, JOSE L
551	EPPERLY, MARCUS
	FLORES, JUAN J
	GARCIA, FABIAN L
	GARCIA, JOSE A
	IBARRA, OLGA
	MARLINE, JOSEPH A
	QUINTERO, LORENZO G
	SALGADO, EDUARDO M
553	GALLARDO, RAUL
	HEMERICK, RICIK A
	PIEDRA, CLAUDIA
	RUIZ, MOISES
	VARGAS, JANY
556	ANGUIANO, JOEL
560	FARFAN, VICTOR M
561	CASAS, SANDRA
	CHARLES, GINA M
	HERNANDEZ, LOUISA V
	LIZARRAGA, JULIA
	ROSA, PANIAGUA
	SANTILLAN, MARIA
	VASQUEZ, MARIA
564	GUARISCO, SANDRA L
565	GASTELUM, JONA
	SANCHEZ, VICTOR
	SANTILLAN, ELIZABETH
	VIVAS, JANET
567	OCCUPANT UNKNOWN,
568	MORALES-MAYEN, LIVIER M
571	FORD, JOEL P
580	ARIZALA, FANCISCA L
	BARBOSA, VICTOR M

G ST 2010 (Cont'd)

580	BURNSIDE, ELLEN
	DAMIAN, MARIA
	DAVIA, MARIO
	DEANDA, RUDY
	DEL, CASTILLO
	DUNNIVANT, TE J
	ESPARZA, MARIA E
	FIGUEROA, EDLEYN M
	FISCH, FRANCES
	GAMBER, NEIL R
	GARCIA, BERNAL A
	GLORIA APARTMENTS
	GUTIERREZ, MARISELA
	HERNANDEZ, RAMON F
	KHAZALI, VERONICA
	LEDESMA, RUBEN
	LEWIS, DALE
	LOEZA, SALVADOR P
	LOZANO, DANIEL
	MARTINEZ, JOSE G
	MONRREAL, JUAN C
	SANCHEZ, LAURA
	SANTELIZ, NICOLE A
	VASQUEZ, ANGELICA
581	OCCUPANT UNKNOWN,
583	OCCUPANT UNKNOWN,
585	DAVIS DRY CLEANING SUPPLIES
	PLUMBING STORE SVC
590	ALVARADO, GEORGE
	CRISWELL, CORRIE
	GALINDO RUIZ GUADALUPE
	MEMOS CUSTOM CANVAS
	ORTIZ, EVA
	WOLFE, MARY J
610	CARRILLO, A
	CARTER, BARBARA N
	CISNEROS, GUILLERMO E
	COBIAN, GUADALUPE
	CRUZ, NIKHOLAS
	CUSTODIO, NOEL T
	DESAHAGUN, S
	FERNANDEZ, JOSE
	GARCIA, RENAN
	GUTIERREZ, OSCAR
	HERNANDEZ, JESUS G
	K SIGNS
	MALDONADO, EMYLIS
	MARTINEZ, XOCHITL C
	ONEILL, PEGGY A
	PATRICIA, ANASTACIO

G ST 2010 (Cont'd)

610	PIPES, AMBER D
	RANGEL, FRANCISCO
	REYES, ARTURO L
	REYES, RODRIGUEZ
	SANCHEZ, KARLA
	THOMAS, ANGELA
	TOM, WALTER
	TORRES, MARIA S
616	ANGUIANO, JOSE A
	ARCOS, MARINA
	ARELLANO, PATRICIA
	AVENDANO, JOSEPHINE
	BECK, THOM
	BENSON, GWENDOLYN S
	CASTILLO, MARCUS S
	COOMBS, PATRICK R
	CURTIS, SHERRY D
	DAVES SUPER STORE
	DAVIS, VERONICA
	DAWOOD, M
	DELA, DOLORA
	DONAHUE, CHARLES C
	DOUGLAS, NAKIA
	DUARTE, JUDY
	FABILA, BENEDICT
	FERGUSON, SUE A
	FLORES, SUSAN M
	GOGERTY, MICHELLE
	GONZALES, CEDRIC G
	GONZALEZ, AURORA C
	HANKS, JP P
	HOLMES, HAROLD J
	HOWELL, MARLENE A
	HOYOS, CARLOS A
	KNOWLTON, JOYCE I
	KOALA KIDS FUN N GLOW
	LE, BINH
	LUNA, DELAIAH R
	MARTINEZ, ALEJANDRO
	MAXX AUTO GLASS
	MEJIA, TINA
	MENDOZA, ELIZABETH A
	METCALF, KRISTOFFER M
	MHAMAD, KUISTAN
	MILLER, OPAL M
	NATIVIDAD, SEGUNDINA
	OCAMPO, ANNA M
	OCHOA, TINA M
	OJEDA, EDUARDO
	OSORNO, SHARON

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

616	PADILLA, RAYMOND
	PALAFOX, CITLALLI
	PALVATANA, GINA
	PRONTO, ANTONIO D
	RASHAAD, DEMETRIUS M
	REDD, EMERALD
	SANDOVAL, MELISSA
	SIPPEL, DULAURA
	SNYDER, DANIEL R
	SOLORIO, MIGUEL S
	SOUTH BAY TOWERS APARTMENTS
	SUAREZ, NORMA
	TUCKER, MICHAEL
	URIBE, SONIA
	VICTORIA, SANDRA
	VIRGINIA, ANTOIN
	WOOLDRIDGE, AIMEE L
	ZENDEJAS, JAIME
626	DOTSON, NASHELL
628	VALLE, JUANA
629	SANCHEZ, KARISSA
633	OCCUPANT UNKNOWN,
635	WRAY, CATO W
644	FREEWILL BAPTIST CHURCH
651	TISDALE, LONNIE L
677	ACKERMAN, ABRAHAM N
	AHRENS, YOKO I
	AMAYA, LUZDEL C
	AMICK, IRENE G
	ANGEL, LILIA E
	ARSENAULT, JOHN E
	AVILA, ELLY G
	BAILEY, ROBERT L
	BEERS, WESLEY J
	BERGERON, RAYMOND J
	BIGGERS, DOROTHY R
	BRANDT, STEVE N
	BREARLEY, WALTER D
	BREESE, REUBEN V
	BROWN, OLIVIA M
	BUTTERWORTH, MARCELLE S
	BYRD, VELVA J
	CANEZ, JESUS A
	CARDONA, PRISCILLA M
	CARRERA, ALEJANDRA
	CASKINETTE, ANN
	CASTRO, RUBEN
	CEJA, RODOLFO
	CHRISTIAN, MADELYN R
	COMER, C

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

677 CONNELLY, ROBERT W
CORBIN, ROBERT L
CRABBE, MICHAEL P
CURRY, ROBERT L
CURTIS, ROGER J
DAKEL, AMBER
DANIELS, EDWARD A
DOUGLAS, JEFFREY A
DUGAN, DONNA M
DUNHAM, MARILYN E
DUNKER, DOUGLAS A
ELKINS, M J
ESCOTO, REYES G
FAIRLEE, LARRY L
FRANCOUR, SANDRA L
FRANKLIN, HARRY
FUSCO, BRYAN E
GAONA, ALAN
GENTZ, LINDA I
GOMEZ, MICAELA L
GONZALEZ, JOSE A
GUADALUPE, BARRIOS J
GUERRA, ALBERTO C
GUERRA, JOE R
HAHN, RAY A
HALL, CHERYL P
HALL, VIVIAN L
HAMBY, JUANA C
HARVEY, JERRY D
HEDGE, WILLIAM
HEDRICK, WILLIE L
HENDRICK, WILLIE
HERNANDEZ, RAFAEL
HERNANDEZ, RAMIRO
HOFF, BRIAN E
HORD, RAYMOND K
JACKSON, ANDREW W
JACKSON, DAISSE
JARVIS, LEONARD G
JOHNSON, RONALD G
JONES, LEROY R
KALIN, SYDNEY
KAMINS, SYBIL R
KINCAID, FLORENCE I
KING, BARBARA A
KNOWLES, CAROL S
KRUPINSKI, DOUGLAS J
LAMARK, DOROTHY L
LANGLOIS, BLANCHE N
LARSON, KATHLEEN

G ST 2010 (Cont'd)

677
LEGASPI, OSCAR L
LIMON, EDUARDO G
LOTZGESELLE, FRANK W
LUCY, MARGARET
MACIAS, ADELINA
MACIAS, MARIA G
MAGALLANES, ALICIA R
MAMANGUN, CONSUELO
MANLEY, JOYCE L
MANN, HILDRA B
MANNON, THEODORE T
MARSH, ANNE
MATHEWS, R P
MAXWELL, TOM M
MCCAULEY, BETTY J
MCGRATH, BILL B
MEILE, RALPH E
MEZA, ANDREA C
MORRIS, AARON B
MOSLEY, MARGARET M
MUCH, JULIETTE E
MUSGRAVE, ROSE M
NEELY, BILLY J
NEWNHAM, EDITH L
NIETO, JAMES
NORMAN, DORIS F
ORAMAS, JOSEFINA O
OURS, JUDITH E
OWN A PROPERTY REALTY
PACELY, SILVIA
PARKHURST, LINDA K
PEARSON, GLADYS M
PERENA, DELFIN
PIERCE, MARY
PIKE, MARTIN E
POTTS, CLAUDIA T
PRECIADO, CRUZ
PURDUE, CLARA L
RADINOVSKY, KATHRYN M
RAINS, YUKO
RAMIREZ, JOSIE
REED, EUGENE W
RIVERAASTACIO, JOSE E
ROBB, MARJORY C
ROBBINS, BRUCE E
ROSSETTI, RITA J
SANCHEZ-ALDANA, GABRIEL
SHAFFER, ORLA
SHELTON, MARK C
SMITH, ARTHUR

G ST 2010 (Cont'd)

677	SMITH, EARL J
	SOTO, IRMA V
	STINEBUCK, NANCY J
	SUNSET CAB
	SUNSHINE CAB CO
	TERRYS MOBILE PARK
	THAYER-STOKES, LAVERNE M
	TIMBOL, EPENITO
	TOBIE, SOTO G
	TURO, MARJORIE L
	VALVERDE, MIGUEL
	VEGA, GLORIA
	VIGILIA, SANDIE
	VILLAFURTE, LETICIA D
	VOLLER, NORMA J
	WACHTLER, REGENIA G
	WATERS, RONALD B
	WATSON, KENNETH D
	WEATHERLY, V
	WILLIAMS, BERNARD
	WOOD, CAROLYN F
	WRIGHT, BONNIE K
	ZAMUDIO, ORALIA G
691	GARCIA, REBECA
704	CASTANEDA, FERNANDO F
	GARCIA, JUAN A
	NAVARRO, MARIA E
	SMITH, HARVEY C
716	CORONADO, HENRY U
	MAINWARING, ELIZABETH M
	RAMIREZ, GABRIEL
	ROMO, YESSICA
724	CARTER, EMIKO S
	JOHNSON, STEVEN
	PHILLIP, RABBIA
	STIMPSON, MARY E
731	ALEXANDER, MARIA
	ANDERSON, BILLIE
	AYOTTE, JIM
	BARRAGAN, PETRA
	BEELES, RONALD G
	BENFER, ESPERANZA
	BERMUDEZ, RAQUEL L
	BETCHER, GOTTFRIED E
	BIRKINSHAW, JACK R
	BONATUS, JACKIE D
	BOWLES, PEGGY D
	BRIDGES, MARSHA
	CABRILLO MOBILE LODGE LLC
	CASTANEDA, MANUEL

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

731 CLARK, DONALD F
CLAY, MARSHALL L
CONKLIN, EDWARD C
CONNER, RONALD D
CUEVA, FILIBERTO C
CUEVA, FRANCISCO J
CUNARD, MARIA E
DORSCHER, SHIRLEY J
EASTWOOD, MARIA B
FALLING, BILLY
FERREIRA, MARIA
GARCIA, RITA
GERBASIO, MARGARET A
GLEASON, EDWARD J
GRASSO, SALVATORE I
HAUSWIRTH, DENNIS L
HERNANDEZ, EVA
HODGES, MACK C
JACKSON, WARREN H
JACQUEZ, ORTENCIA S
JUAREZ, JESUS
KARAKEY, APOLONI A
KNIGHT, SHAWN M
LITTLE, MICHAEL D
LUGO, ANGELINA L
MANJARREZ, MARIA C
MAPLE, GRAYDEON R
MARISCAL, MARIA
MARTINEZ, MARGARITA
MCGONIGLE, GARY R
MEASEL, GLENN J
MEDINA, RAMON
MELVIN, JOHN H
OSEJO, MARIA
PARDEE, BARBARA J
PATRON, MARIA G
PENNERMAN, WILLIAM A
PERRY, HARLEY L
PRADO, GUADALUPE R
RHOADES, TERRY M
RICHIE, ELIDA
RITCHIE, ELIDIA G
ROBERTS, SANFORD
RODRIGUEZ, GUILLERMO
RODRIGUEZ, JUANA
RODRIGUEZ, WILLIAM
SANCHEZ, ESTELA C
SEGHERS, DOREEN H
SWANSON, DOROTHY J
THOMAS, L

G ST 2010 (Cont'd)

731	THOMPSON, ROBERT N
	TUMBOKON, ELVIRA L
	TURNER, THERESA
	UNDERHILL, BRENDAN J
	URIBE, JOSE G
	VAZQUEZ, JAVIER A
	VELASQUEZ, JOSE A
	WALTHALL, GLEN A
	WOODY, NEREIDA
	YOUNG, FLORENCE
	ZABALA, BULMARO C
	ZIGLER, MILAGROS D
	ZINN, ALEXANDRA C
736	BAXTER, STUART A
	PEYRO, JUAN S
	VELA, EDUARDO
997	FIVE STAR YACHT SVC INC
	PACIFIC YACHT REFITTERS INC
	SOUTH BAY BOAT YARD
	TRUITT MACHINE & FABRICATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005

14	ACKERMAN, RICHARD J
30	FLACKE, JUDITH L
36	HIPPERSON, DUANE M
39	TABLADILLO, RODOLFO C
42	HILDEBRAND, ERNEST H
45	TAYLOR, JONATHAN W
48	THOMAS, ROBERT D
50	MATZEK, DEBORAH
52	VEGA, MICHAEL E
55	SLATER, ROBERT M
60	DEESE, BOBBY L
66	OCCUPANT UNKNOWN,
70	STANCZAK, FRANK J
71	NELSON, ROSALYN J
77	SEARLES, ROBERT C
78	DUARTE, SAUL
83	ARIZAGA, RAUL J
84	COSTELLO, TIMOTHY P
86	DUNKLE, RAYMOND E
87	CHASE, PALMER S
90	MURRAY, LUPE M
93	STONE, BILLIE C
102	ROJAS, MANUEL C
108	CARRERA, CECILIA M
111	DALE, JANE E
115	OCCUPANT UNKNOWN,
121	ZAPPONE, CARL M
123	TAULBEE, NORMAN L
130	HULST, WARREN J
134	HARGIS, PATRICIA J
135	TOMIC, BETTY J
140	TELLO, DOROTHY M
141	EGGERS, DARREN J
146	JENNINGS, MARY G
147	OCCUPANT UNKNOWN,
152	WOMACK, JULIA M
155	LOPEZ, FLORENCIO D
156	HUVAR C F 3 GENERAL CONTRACTOR
	RADER, CAROL L
159	WALLACE, FRANK T
160	OCCUPANT UNKNOWN,
161	BIOMMELL, DARRELL L
163	RASCON, MARISA R
164	KELLY, THOMAS M
167	GURROLA, ENRIQUE
	NURSE STATIONS COM
	NURSELINK
170	OCCUPANT UNKNOWN,
173	OCCUPANT UNKNOWN,
174	MOLSBERRY, MARK A

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

177	MARINELLO, JOSEPH S
181	TROTTER, RON
182	BARNES, ALBERT A
186	OCCUPANT UNKNOWN,
194	DIXON, TIMOTHY B
195	TROTTER, RONALD G
197	ESPIRITU JANITORIAL SERVICE
	ESPIRITU, JEFFREY M
198	SMITH, JERRY R
202	MAESTRE, ESPER I
203	JOHANSEN, JACK
207	AMOS, ANSON S
210	LADD, JAMES L
211	OCCUPANT UNKNOWN,
215	PARKS, JUANA L
222	ACEVES, OCTAVIO
	BARCUS, JOHN W
	BUDIONGAN, ROBINSON M
	BUMSTED, VIOLA E
	CATE, JEAN M
	CUBILLOS, JUAN
	ELLIOTT, SHIRLEY M
	FALLE, VIONA E
	GALVAS, JOHN J
	GISH, MILDRED E
	HALL, CAROL V
	HELM, JOHN E
	HINKEY, RUSSELL
	KNOX, JULIETTE E
	LE CHATEAU A PARTMENTS
	LYONS, DICK M
	MORTON, JAMES E
	OBRIEN, WILLIAM J
	PEARSON, GLADYS M
	PENWELL, EDITH A
	PHELPS, GREG M
	RICHARDSON, MADELINE
	RODGERS, MARY A
	SCOTT, DAVID M
	SHEPHERD, ERON
	SIMON, ESTELLE L
	STONE, FREDERICK L
	SWAN, NORMA M
	TAPIA, SALLY
	VILLEGAS, JESS C
223	MEYERS, RICHARD J
	ZULAICA, BENITO
226	GIMENEZ, DAMIAN P
	URIAS, PRISCILLA
227	RINCON, ANTONIO

G ST 2005 (Cont'd)

228	OCCUPANT UNKNOWN,
229	OCCUPANT UNKNOWN,
233	RYAN, MARION A
236	OCCUPANT UNKNOWN,
239	ANDERSON, TREVA
	CARDENAS, JUANA
	CORTEZ, MARIA
	ESPINOZA, LUPE M
	FLORES, FRANCISCA
	GARCIA, DIANA V
	RADCLIFF, JACKIE
241	BECKY, GONZALES
	ESSEX, GEORGE E
	GUZMAN, STEVE
	LEON, RUBEN
	MCGEE, PATRICIA A
	MONTOYA, EMILIANA C
	RODRIGUEZ, DEVINA
	SOTO, ARTEMIO
244	HIX, THOMAS
	SNYDER, VERNON R
246	OCCUPANT UNKNOWN,
248	GRAPES, HANNAH
	KOTSALA, MICHAEL V
250	OCCUPANT UNKNOWN,
252	ALCALA, YERALDINE
	GILBERT, LAWRENCE F
	SORIANO, ROCIO
255	FINNEY, OTIS L
	JACKSON, JOHN E
	JORGENSON, LANCE K
	KANE, TIFFANY
	RODRIGUEZ, GLORIA
	SPREKELMEYER, LINDA R
264	ACOSTA, ANABEL Y
	ARCE, REBECCA
	CLEANING ANGEL SERVICES
	CLEANING ANGELS SERVICE
	GLEGHORN, REBECCA H
	GRUBE, MATHEW
	QUIROGA, HECTOR M
	WHIZAR, LUCIANA
265	BRYANT, TERRY L
	CARR, MIKE E
	CLEANING ANGEL SERVICES
	COWHERD, JUDITH M
	HOLIDAY COMFORTS CUSTOM PILLOWS AND
	HOLIDAY COMFORTS CUSTOM PLW
	MARRERO, RONY
	MIRANDA, EVA J

G ST 2005 (Cont'd)

265	MOORE, JONATHAN H
	PERKINS, MARVIN K
	SANDOVAL, EVA
	THE PILLOW PEOPLE BY MNC & VRN
	THE PILLOW PEOPLE BY MONICA & VERONI
	WAGNER, DIANE M
268	BRADLEY, DAMA O
	WERTZ, MARY
	WIELENGA, PHYLLIS
274	BROWDER, ERIN C
281	JORDAN AND ASSOCIATES
	PEPPERTREE ESTATES
283	MILLER JON REALTY
286	AIR CONDITIONING BY BUTLER
287	ESPERANZA INTERNATIONAL
	LOS NINOS
	VOLUNTOURS
309	ARENAS, VERONICA
	GUENTHER, JUSTIN
	HENDERSON, MARIA
	LUNA, JENNIFER
	STEVENSON, JANET
	VILLEGAS, RAMIRO
	VINAS, SERGIO
310	CONLIN, JAMES P
	FLORES, GUILLERMINA O
	HERNANDEZ, MARITZA B
	KOHMETSCHER, KENNETH
	OCAMPO, MARIBEL
	TIMMER, SANDRA J
	TRAYLOR, STEVEN H
	VANSLYKE, CLAUDINE
	YOUNG, LINDA
	YOUNG, MARCELLA L
311	HOWE, THOMAS G
313	KEPHART, CHRISTY L
315	CAMERON, PATRICIA A
316	HERNANDEZ, DANIEL A
317	BRUDER, ROBERT
	CARLETON, COLLEEN G
318	FRANKLIN, WILLIAM E
	HARMON, KELLY
	HICKEY, MEGAN
	HOLLAND, STEPHANIE
	ISIP, CHARLIE V
	LAPINSKY, MICHELLE
	LOBELLO, NICOLE
	MUNIZ, FRANCISCA
	PADGETT, JOSEPH
	ROYBAL, GERTRUDE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

318 VENEGAS, ARMANDO L
320 CHAMBERS, RICHARD
DUKES, VICTOR M
KNUDSEN, JOHN F
LOPEZ, LUZ
MEYERS, JENNIFER C
RUSTIN, CHERYL L
SUAREZ, ERNESTO
321 OCCUPANT UNKNOWN,
323 DEB & I
HOWE, THOMAS G
325 POLLOCK, HOLLY
329 DIRECTLY CREATIVE
330 GIBSON, NORA
NINE-TRIANON, L
THOMPSON, LESLIE C
333 OGILVIE, EVA I
334 BELTRAN, JESUS
CARRANZA, WALTER S
CORNEJO, ARTHUR J
DNA COMPUTER REPAIR
GOMEZ, JESSICA
JAGGARS, RUSSELL
MACIAS, SELENA R
MARTINEZ, MIGUEL A
TIPPETT, RICHARD L
WARD, SHARON L
335 WILLIAMS, CHRISTINA L
336 MADEROS, KORINA
MEDEROS, OMAR M
340 GUARDADO, EFRAIN R
LEBINH, BLANC
RUVALCABA, FERNANDO
ZATARAIN, OSCAR E
341 OCCUPANT UNKNOWN,
345 CASTILLO, TERESA
350 BLACKWELL, JOSEFINA J
CAMACHO, JULIE M
CANEDO, NELLY C
EAGER, ELIZABETH
FOREST, B
GIGEAR, PAULETTE
GIOAKARIS, CARMEN D
KIDWELL, CAROL S
KLEINICK, MICHAEL D
KREMER, LAURA E
KRUSAS, CHARLENE F
KUGLER, MANNIE L
MACASADIA, NEIL G
MARTINEZ, LAWRENCE M

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

350	MEDICAL SCNTFIC INTERPRETATION
	PORTILLO, MATTHEW
	RAMEY, DEBORAH
	RIVERA, L
	ROARK, ERNIE A
	SKUZINSKI, PHYLLIS L
	ZATARAIN, GLORIA
357	CHULA VISTA WOMANS CLUB
363	PRICE, LISA
364	OCCUPANT UNKNOWN,
367	ALACAL, YASSARETTE
368	JERVAY, B
	MONTANEZ, LIZBETH L
	WAGNER, MONICA J
370	MCKINLEY, SARAH R
371	FLORES, FRANCISCO
372	PIMENTEL, SERAFINA
	TOTTRESS, TYRONE A
	ZEPEDA, KARLA
374	ANGULO, VICTORIA G
375	BARAJAS, GUADALUPE
	CASTILLO, JENNIFER
	KNOWLTON, JOSIE T
379	ALL FAITHS
	KEMERY, WILLIAM E
	NEW THOUGHT EPISCOPAL CHURCH
	WM E KEMERY PHD DD
385	MARTINEZ, JUAN M
386	ANGULO, JULIO C
390	MADDOX, WILLIAM B
	MAYEN, M L
	MERCADO, VICTOR B
	MOLINA, D
391	CAMARILLO, JANET G
	FORD, LEKEBIA
	HINOJOSA, MARIA
	KEVIN, MARSHALL
	OLIVOS, JORGE
	PONCE, HENRY J
	WOODS, ARMIN
394	BATTON, LAURA L
	COGGINS, MELISSA
	COLE, C
	CUNNINGHAM, ANDRE P
	HELLER, CHRIS L
	HOLMES, NA E
	MARTINO, ROSALINA
	MEZA, MERCEDES M
	PRADO, RODRIGO S
399	REYES, ISMAEL

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

402	CHAVEZ, MARIA
404	DURAZO, LIZETTH
406	LUNA, PEDRO
408	D & R CLEANING SERVICES
	FLORES, ZERBEL
410	TREJO, CECILIA
411	AVITIA, BLANCA I
	CHAVEZ, ANA E
414	OCCUPANT UNKNOWN,
415	OCCUPANT UNKNOWN,
418	SANCHEZ, MARCELO H
419	BOSCOSKY, ROBERT Z
420	OCCUPANT UNKNOWN,
422	OCCUPANT UNKNOWN,
423	BARAJAS, MAYTE
	DOMINGUEZ, GUADALUPE
	MOLINA, DEL R
	PARICA, ROY
	RODRIGUEZ, GUILLERMO
	SANCHEZ, JOEL G
	SUAREZ, JOSE M
	SUNSET CAB
	TESTER, GLENN A
	WIGHTMAN, L
424	AVILA, A
	DEGRADO, JOAN
	HUDSON, STEPHEN J
	MINNICK, RICK
	ROUSSEAU, LAURA
	VISTA, SQUARE
427	WOOD, JUAN A
431	GONZALEZ, OSCAR L
433	LAW OFC OF TMTHY A SCOTT A PRO
	WEHBE, ELIAS M
435	ORTEGA, HECTOR A
439	OCCUPANT UNKNOWN,
	PEREZ, JORGE A
443	GASPAR, GUADALUPE
447	CAYETANO, LAURA
453	SANMARTIN, CAROL I
459	CAZARES, RAFAEL A
	FAMILYS LOANS & REAL ESTATE
	INDEPENDENT REAL ESTATE BRKR
	THE FAMILY LOAN REAL ESTATE
	THE FAMILYS LOANS AND REAL ESTATE
463	LAWRENCE, CHRIS J
469	ALOYO, ANGEL L
473	ANDRADE, RAMIRO
479	NUNEZ, LETICIA
481	WIMBERLY, O

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

485 ARCE, KARLA
489 CARLSON, EARL L
502 VAZQUEZ, AGUSTIN
503 ZAZUETA, EVANGELINA
507 MURRAY, WILLIAM W
513 HILDAS HOUSE CLEANING
OCCUPANT UNKNOWN,
ROCHA, LEONILA
S & S MAID SERVICE
515 HERNANDEZ, NANCY
516 GARCIARUIZ, MANUEL J
519 GREGORY, ARITHA K
521 CORTEZ, OMAR A
MACIEL, KYLEEN
MANZANARES, IRENE J
MANZARES, STEVEN
PADILLA, ALMA
RAMIREZ, MARCELA
SALINAS, SALUD
525 OCCUPANT UNKNOWN,
527 TALARO, OSCAR N
529 VAZQUEZ, JAVIER A
531 VAZQUEZ, JAVIER A
535 CASTRO, ELODIA L
LEON, RAFAEL
LEONS LANDSCAPE
MARTINEZ, MARIA R
MORLES, JULIE
PICHARDO-JR, HECTOR M
537 SILVA, BENJAMIN
540 VISTA SQUARE ELEMENTARY SCHOOL
541 GARCIA, MARIA
OCCUPANT UNKNOWN,
543 OCCUPANT UNKNOWN,
551 DUARTE, SYLVIA A
GARCIA, FABIAN
MANRIQUEZ, ANGEL
QUINTERO, LORENZO
RODRIGUEZ, MARIA E
SALGADO, EDUARDO
SAUL, CONRAD
553 FABIAN, JOSE
FIGUEROA, JAVIER
MORALES, GRACIELA
RAMIREZ, SONIA
RANDLE, P
SUAREZ, JOAQUIN
VILLANUEVA DAY CARE
556 PEREZ, PERLITA
560 FARFAN, VICTOR M

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

561 HERNANDEZ, LOUISA
564 GUARISCO, SANDRA L
OCCUPANT UNKNOWN,
WMM DRYWALL & TEXTURE
WMM DRYWALL TEXTURE
565 CAMPOS, ANA
CONTERAS, JUAN J
DELGADO, PEDRO
GARCIA, DIANA M
GLASS, KAREN
MANRIQUEZ, J
MINJAREZ, ARTURO A
ROBINSON, LETICIA
SALGADO, RUBENDO A
567 DOMINGUEZ, FLORENCIO
568 OCHOA, MARIA A
571 FORD, JOEL P
580 BERNAL, ALFONSO G
DAVIA, MARIO
FISCH, FRANCES
GARCIA, MIGUEL
GLORIA APARTMENTS THE
GUTIERREZ, JESUS
GUZMAN, RAINNIER M
HUESO, CECILIA
IRRIBE, RAFAEL
JIMENEZ, MONICA
LARIOS, CARMEN
MACIAS, ADRIAN
MEDRANO, REBECA D
MEJIA, JOSE
MONRREAL, JUAN C
REYES, CESAR
REYES, JESUS R
SALAZAR, CECILIA G
SANCHEZ, CRISTIE
SANTELIZ, GAIL
TORRES, BEATRIZ
581 OCCUPANT UNKNOWN,
583 OCCUPANT UNKNOWN,
585 PLUMBING STORE SERVICE
590 ABILITEES CO
CORTEZ, VICTOR
LIVERMAN, MONICA
MEMOS CUSTOM CANVAS
ORTIZ, EVA
PANCHITAS TAROT
PERFECT PHOTO
ROMAN ZERMENO
610 AGUAYO, JOSE

G ST 2005 (Cont'd)

610	CARRILLO, A
	CASTILLO, JACOB
	CHANCE, JANE L
	DEMBY, CONSTANCE M
	DESAHAGUN, NERO S
	ESTRADA, CHRISTOPHER
	GILLESPIE, JENNIFER
	GUIZAR, CARLOS A
	HERNANDEZ, SARA N
	JOHNSON, WALTER T
	LAVA MAX CARPET & UPHOLSTERY
	LOTA, JOSE
	MALLOY, ROBERT W
	MARTINEZ, XOCHITL C
	MAXON, PETER L
	MOORE, MARIAH
	OCLEARY, SHANNON
	ONEILL, PEGGY A
	PASAY, AIDA A
	REYES, ARTURO L
	ROBERTS, ANNABELLE
	TORRES, MARIA S
	VILLA, LINDA
616	AKOU, SARID Z
	AMADOR, HUGO J
	AMESQUITA, SAMUEL R
	ARIAS, FRANK A
	BLOOMFIELD, PHILIP
	BULLUCK, MARK L
	CAMPS, JUAN
	CHAPPELL, PAUL
	COLE, RACENE
	COOMBS, PATRICK
	CURTIS, SHERRY D
	DAWOOD, M
	DELA, CRUZ
	DELAVEGA, EMMA
	DOUGLAS, NAKIA
	DUARTE, JUDY
	FARID Z AKOU CARPET CLEANING
	FREY, LESLIE
	FUENTES, DANIEL
	GLORIA, JEFFREY
	GOMEZ, ALONZO
	GORGES, ADEL
	GUTIERREZ, MARTINA
	HANNA, APRIL
	IRELAND, ANN
	JIMENEZ, JORGE A
	LE, BINH

G ST 2005 (Cont'd)

616	LEBOEUF, RON
	LUNA, RICHARD B
	MELENDEZ, SANDINO A
	MILLER, OPAL
	NATIVIDAD, SEGUNDINA
	NELSON, JENNIFER
	ORALIA CLEANING SERVICE
	OROZCO, AGUSTIN
	PALAFOX, CITLALLI
	QUEZADA, NADIA C
	RAPPLEY, ALAN D
	SASS, HAROLD
	SCOTT, SHANON S
	SHAEBAN, WAHID
	SLEWA, WILLIAM D
	SNYDER, DANIEL R
	TOMA, RAMZI
	TUCKER, MICHAEL
	VIRGINIA, ANTOIN
	ZANGANA, ALAN
626	DOTSON, NASHELL
628	OCCUPANT UNKNOWN,
629	GOMEZ, MELISA D
633	BENITES, PAULA
635	OCCUPANT UNKNOWN,
644	FREEWILL BAPTIST CHURCH
651	TISDALE, CHARLES E
667	AGUILAR, ALBA M
677	ACKERMAN, ABRAHAM N
	AMERICAN SOUTHWEST SERVICES
	ANGEL, MARIA E
	BEERS, WESLEY J
	BERGERON, RAYMOND J
	BERRY, VIVIAN A
	BOWEN, ANGIE M
	BRANDT, STEVE N
	BREARLEY, WALTER
	BREESE, REUBEN V
	BURT, STUART C
	BUTTERWORTH, MARCELLE S
	BYRD, VELVA J
	CAMPBELL, CHARLES L
	CASTRO, FRED H
	CEJA, MARIA A
	CHANG, GERMAINE F
	CHILDERS, WILLIAM
	CONNELLY, ROBERT W
	COOK, MARGARET W
	CORBETT, RICHARD J
	CORBIN, ROBERT L

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

677	DECK, JERRY E
	DELAHUERTA, GUSTAVO
	DELAHUERTA, J G
	DOERING, KENNETH M
	DOUGLAS, JEFFREY A
	DUGAN, DONNA M
	DUNKER, NORMA M
	DUPERRON, DONALD J
	EDINGTON, ARVEL H
	ELKINS, M J
	FAVERTY, CAROLYN F
	FRANKLIN, HARRY
	FUSCO, BRYAN E
	GAGLIANO, ANGELINA
	GALARZA, ARMANDO R
	GENTZ, LINDA I
	GOMEZ, MICAELA L
	GONZALEZ, J A
	GRAHAM, GEORGE H
	GREEN, LUCILE Y
	GUERRA, ALBERTO C
	HAHN, JEAN A
	HALL, CHERYL P
	HALL, DONALD W
	HALL, VIVIAN L
	HAMILTON, JUANITA M
	HARVEY, HAL K
	HEDRICK, WILLIE L
	HENDRICK, WILLIE
	HUBERT, RICHARD
	JACKSON, DAISSE
	JDK WEBS
	JOHNSON, DANIEL J
	JONES, CAROL V
	JONES, LAMAR R
	JONES, LEROY M
	KALIN, SYDNEY
	KAMINS, MARVIN S
	KELLOGG, WILLIAM B
	KINCAID, FLORENCE I
	KING, JUDITH E
	KISBERT, MARY A
	KNOWLES, CAROL S
	KOHLMAN, LAVADA J
	KRUPINSKI, DOUGLAS J
	LAMARK, DOROTHY L
	LANGLOIS, BLANCHE K
	LEDINGHAM, COLLEEN
	LONGHOFER, WAYNE
	LOTZGESELLE, FRANK W

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

677 MACIAS, MARIA G
MAGALLANES, ALICIA
MAMANGUN, CONSUELO
MANLEY, JOYCE L
MANN, HILDRA B
MARSH, ROBERT
MARTINEZ, LUPE C
MATHEWS, R P
MAXWELL, TOM M
MCGRATH, BILL B
MEILE, RALPH E
MENDOZA, LUPE C
MILLER, RAV
MORRIS, AARON B
MUSGRAVE, ROSE M
NEAL, ROBERT I
NEELY, BILLY J
NEWMAN, LUETTA L
NIETO, JAMES
NORMAN, DORIS F
OLVERA, SONIA R
ONLINESALES
ORTNER, CONSTANCE L
PARKER, JOE
PARKHURST, LINDA K
PIKE, MARTIN E
POTTS, CLAUDIA T
PURDUE, CLARA L
RADINOVSKY, KATHRYN M
RAINS, YUKO
REED, EUGENE W
REEVES, LAURA
ROBB, MARJORY C
SANDOVAL, HERMELINDA A
SAUNDERS, LESLIE
SCHLEGEL, WILLIAM J
SERVICIO RADIANTE
SHAFFER, ORLA
SMILEY, WANDA F
SMITH, TIMOTHY A
SOTO, IRMA V
STINEBUCK, NANCY J
STONE, ANNA J
STONE-WEYGAND, ANNA
STRAHAN, LOUIS
SYMO CONSULTING OF CALIFORNIA
TAGLE, JOSE
TERRYS MOBILE HOME PARK CORP
THOMPSON, LAWRENCE E
TREVINO, ROBERT L

G ST 2005 (Cont'd)

677	VALENZUELA, PEDR
	VALUATOIN CONCEPTS INC
	VALVERDE, MIGUEL
	VAZQUEZ, ANTONIA
	VIGIL, ELFIDES M
	VILLAFUERTE, TONY P
	VISTA, GLORIA
	VOLLER, DONALD R
	WACHTLER, REGENIA G
	WATERS, RONALD B
	WATSON, KENNETH D
	WATTS, JOAN M
	WESTON, NANCY O
	WHITING, EDNA R
	WHITTAKER, BARBARA A
	WILLIAMS, BERNARD
	WOLFE, DOLORES
	WOLFORD, JOANN E
	WRIGHT, BONNIE K
691	GARCIA, REBECA
704	AVILA, RUBEN
	CASTANEDA, FERNANDO
	MARTINEZ, ROBERT
	MONTOYA, DANIEL J
	SMITH, STEPHEN E
716	CORONADO, HENRY U
	MAINWARING, ELIZABETH
	RAMIREZ, FRANCISCA
	ROARK, ERNIE A
724	CARTER, EMIKO S
	JOHNSON, STEVEN
730	HOLLMAN, MARIE J
731	ACKER, JOHN S
	BARRAGAN, PETRA
	BERMUDEZ, RAQUEL L
	BIRKINSHAW, JACK R
	BOWLES, PEGGY D
	BYRNE, HELEN A
	CABRILLO MOBILE LODGE LLC
	CALDEAN, ALLEN
	CHAPMAN, WILLIAM
	CISNEROS, BULMARO
	CLARK, DONALD F
	CLAY, MARSHALL L
	CONNER, RONALD D
	CUEVA, FRANCISCO J
	CUEVA, GRACIELA C
	DAWSON, JOE W
	DORSCHER, SHIRLEY J
	ESTRADA, JULIAN

G ST 2005 (Cont'd)

731 GERBASIO, MARGARET A
GLEASON, EDWARD J
GRALEY, JAMES E
GRASSO, SALVATORE
GROSSMAN, BARBARA
GUTHRIE, IRMA
HATCHETT, IRA H
HAUSWIRTH, DENNIS L
HOLLINGER, ROSELA M
JACKSON, WARREN H
JOLLY, BARBARA E
KALLENBERGER, MARVIN B
KARAKEY, APOLONIA
KIENLEN, TOM
LARA, JOSE L
LITTLE, MICHAEL D
LUGO, ANGELINA
LUPPENS, JOHN
MAPLE, GRAYDEON R
MARTINEZ, TRINIDAD
MCGONIGLE, GARY R
MEDINA, RAMON
MELFORD, MICHEAL B
MELVIN, JOHN H
MONCRIEF, CAROLYN A
NEVEU, KERRY L
PASCHEN, JOE M
PATRON, MARIA G
PAWLAK, EDWARD F
PENNERMAN, WILLIAM A
PERRY, H L
PROTHEROE, IVOR
RITCHIE, ELIDIA S
RODRIGUEZ, GUILLERMO
ROMANDIA, YVONNE E
SAENZ, ARMANDO
SANCHEZ, ESEQUIEL
SANCHEZ, ESTELA C
SEGHERS, DOREEN H
SERRANO, LUPE
SINGER, THOMAS
SPENCER, W A
THOMAS, JOHN S
TINITIGAN, ZENAIDA P
TURNER, ALFRED S
UNDERHILL, BRENDAN J
WALTHALL, GLEN A
WENTWORTH, FRED E
WILLIAMS, SHERRY L
YAOTANI, BENIGNA

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

731 YOUNG, FLORENCE
736 PEYRO, JUAN J
VELA, EDUARDO
WISSER, JOHN H
979 PACIFIC DEFENSE SYSTEMS
997 MARINE GROUP LLC
PACIFIC MARITIME FREIGHT INC
SD FUEL DELIVERY
SOUTH BAY BOAT YARD
TRUITT MACHINE & FABRICATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000

10	RINGGOLD, ERNEST W
12	HAWLEY, DONALD E
14	ACKERMAN, DICK
15	OCCUPANT UNKNOWN,
22	GUTHRIE, CAROLYN
30	OCCUPANT UNKNOWN,
33	CORNEJO, DORIS A
34	CORNEJO, DORIS A
36	OCCUPANT UNKNOWN,
39	OCCUPANT UNKNOWN,
42	HILDEBRAND, ERNEST H
45	OCCUPANT UNKNOWN,
52	JONES, MARK
55	OGDEN, JACK
60	DEESE, BOB L
66	JETER, T
70	STANCZAK, FRANK J
71	NELSON, ANTON J
77	CROPLEY, CARROLL D
78	PERRY, DALE W
83	ARIZAGA, RAUL
84	JENKINS, SIDNEY R
86	DUNKLE, RAYMOND E
87	GOLDSTEIN, EDWARD
90	MURRAY, LUPE M
93	STONE, BILLIE C
102	ROJAS, MARTHA F
108	CARRERA, CECILIA
111	JOHNSTONE, WILLIAM B
115	OCCUPANT UNKNOWN,
121	OCCUPANT UNKNOWN,
130	HULST, WARREN J
134	RAZO, RICHARD
135	PHILLIPS, CORA I
140	CASTILLO, ANA A
141	ALLEN, V E
146	OCCUPANT UNKNOWN,
152	DAVEY, WADE D
155	OCCUPANT UNKNOWN,
156	HUVAR, CYRIL F
159	WALLACE, FRANK T
160	OCCUPANT UNKNOWN,
161	BOMMEL, DARRELL L
163	CLINE, P H
164	KELLY, THOMAS M
167	HICKMON, GOLDIE R
170	SCROGGINS, ARTHUR W
173	OCCUPANT UNKNOWN,
174	MOLSBERRY, MARK
177	OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000 (Cont'd)

181	TROTTER, GUY H
182	BARNES, ALBERT A
186	BARNES, ANITA L
189	OCCUPANT UNKNOWN,
194	DIXON, R L
195	TROTTER, JANET C
202	OCCUPANT UNKNOWN,
203	JOHANSEN, JACK
205	AMOS, E H
207	AMOS, E H
210	LADD, L E
211	NEVAREZ, MARTIN
215	PARKS, JUANA L
	VALDEZ, JOSEPH P
216	ABDUL, SEEPAL
217	KEELEY, TERENCE F
222	ALLEY, F G
	ASHCRAFT, MILTON T
	BARNHART, RICHARD E
	FALLE, VIONA E
	FELDMAN, E
	GALVAS, JOHN J
	GISH, MILDRED
	GOOD, PETER H
	GUTHRIE, CAROLYN S
	JORDAN, HILDA E
	KODISH, SAMUEL J
	LECHATEAU APARTMENTS
	MATTISON, M
	OBRIEN, WILLIAM J
	PHELPS, GREGORY M
	REYES, G
	ROBERTS, R F
	SHEPHERD, DONALD R
	STEPHENS, J
	ZAVALA, ALEX
226	BARRIOS, CARMEN A
	JEANS, DAWN R
227	OJEDA, M
228	OCCUPANT UNKNOWN,
229	MOSHER, KEITH E
233	DOEGE, DOUGLAS W
241	ESSEX, GEORGE
	MCGEE, P
244	SNYDER, MARY A
246	AMAN, MARY A
248	CARSON, TESSA M
250	SINGLETON, V J
252	ALCALA, JUAN M
255	FINNEY, OTIS L

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000 (Cont'd)

255	MILLER, M G
	MORGAN, M G
	RASMUSSEN, ELEANOR
	SPREKELMEYER, J
264	LATONI, GERARDO
265	BENSON, JULIE A
	CARR, MIKE
	COSFORD, DAVID T
	COWHERD, JUDITH M
	CURIEL, LAURA
	GARCIA, ALBERT U
	MIRANDA, EVA J
	URIAS, LIZETH
	WAGNER, DIANE M
268	JOHNSON, RICHARD A
274	OCCUPANT UNKNOWN,
277	FRITCHER, JAMES F
281	JORDAN & ASSOCIATES REAL ESTATE APPRAISAL
	JORDAN, DAN
	YELLOW BIRD COMPANY
282	WHITTINGTON F L & ASSOCIATES REAL ESTATE
283	SOUTH BAY YOUTH & FAMILY SERVICE
286	AIR CONDITIONING BY BUTLER
	BUTLERS AUTO REPAIR
287	LOS NINOS HELPING CHILDREN
309	MACCOMISH, TIMOTEA G
	RODRIGUEZ, ANTONIO
310	BELTRAN, RICHARD C
	FLORES, G O
	GANS, RICK O
	KOHMETSCHER, KENNETH
	TIMMER, SANDRA
	TRAYLOR, STEVEN H
	WILLIAMS, CHARLES W
313	OCCUPANT UNKNOWN,
315	STOCKTON, PEGGY L
318	BRANNEN, MELISSA R
	COURTEMANCHE, J
	GOMEZ, DANIEL
	MEINUNG, ARTHUR
	RATLIFF, B
319	HERNANDEZ, RUBIN J
320	HASTY, DANNY R
	RUSTIN, CHERYL L
	STARRETT, V E
323	OCCUPANT UNKNOWN,
329	LAMB, G E
330	CARRILLO, ALFONSO
	CHAVEZ, LORENA
	CRUZ, P

G ST 2000 (Cont'd)

330	FUJII, F
	HANA, LINDA
	MAUTINO, KATHRIN
	STEWART, P J
	VALENCIA, NANCY I
	WOOD, TODD W
333	OGILVIE, FLOYD E
334	BURCIAGA, RAQUEL
	CONNELLY, SONYA
	CORNEJO, DORIS
	GUILLEN, A J
	JAGGARS, L
	LEON, ANDRE
	LEVERENCE, DANIEL E
	MARTINEZ, M
	MCCUAIG, JOHN B
	MILLER, MARILYN J
	PALOMO, CONNIE
	ROMAN, FARAH
	TAITINGFONG, ANTHONY
	VEJAR, ARTHUR
	WARD, S L
335	WILLIAMS, C L
336	GALVAN, EUNICE
	TORRES, ROBERT D
340	SCOTT, ARLITA
342	KOPEPASSAH, M D
345	OCCUPANT UNKNOWN,
350	BEWICK, SOPHIE
	BLACKWELL, JOSIE
	BLEYLE, J
	CANEDO, NELLY
	COMBS, JERRY L
	FERNANDEZ, RICARDO
	FORD, RICHARD J
	FREESE, SHARON K
	GIOAKARIS, CARMEN D
	GIOUKARIS, CARMEN D
	GOBEL, DENNIS E
	GUASTAFIERRO, IRMA S
	HIGH, LEONORA G
	KRUSAS, C F
	LI, BAOHE H
	LIBAO, H
	MATZEK, DEBORAH L
	SIMS, CAROLYN
	SKUZINSKI, PHYLLIS L
	STENGLE, P
	THOMAS, STEVE C
	ZATARAIN, HECTOR

G ST 2000 (Cont'd)

357 CHULA VISTA WOMANS CLUB
363 MACDOUGALL, K
364 BOBBY D ENTERPRISES INCORPORATED
GONZALES, J
375 BARAJAS, JOSE
KNOWLTON, JOSIE
379 ALL FAITHS
KEMERY WILLIAM E DD
KEMERY WILLIAM E PHD DD
NEW THOUGHT EPISCOPAL CHURCH
385 MARTINEZ, JUAN
386 OCCUPANT UNKNOWN,
390 ALVAREZ, P
GETZEL, JASON M
SCHOENFELD, BRIAN E
391 BAYLON, P
LOPEZ, M M
MILLER, W
OTAR, GONUL
394 OSBORNE, HEATHER
PRADO, RODRIGO S
TIRADO, HECTOR
UDAVE, JUAN
399 JET BUILDING MAINTENANCE
404 OCCUPANT UNKNOWN,
406 OCCUPANT UNKNOWN,
408 OCCUPANT UNKNOWN,
410 OCCUPANT UNKNOWN,
412 CERVANTES, JOSE L
414 SPARBY, JEAN
416 TRUSTY, WENDY L
419 OCCUPANT UNKNOWN,
420 GONZALEZ, GERARDO
422 RODRIGUEZ, EDWIN
423 LACOSTE, JACK
424 AVILA, A
CHAVARRIA, A
CROSTHWAITE, HERB R
427 OCCUPANT UNKNOWN,
431 OCCUPANT UNKNOWN,
433 STARR, ROBERT E
435 ORTEGA, MARTHA
439 PEREZ, JORGE A
443 OCCUPANT UNKNOWN,
447 SILVA, CARLOS
453 SANMARTIN, CAROL I
459 DEARDORFF, ROBERT T
469 OCCUPANT UNKNOWN,
473 OCCUPANT UNKNOWN,
479 OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000 (Cont'd)

481	OCCUPANT UNKNOWN,
485	PEREZ, ALFREDO
489	CARLSON, EARL
503	OCCUPANT UNKNOWN,
507	MURRAY, WILLIAM W
513	MCDERMOTT, MALISSA
515	HERNANDEZ, NANCY
519	ROMERO, ALI E
521	PENA, MARIA
525	OCCUPANT UNKNOWN,
527	TALARO, JACKIE J
529	VAZQUEZ, JAVIER A
531	VAZQUEZ, LILIA A
533	OCCUPANT UNKNOWN,
535	CASTRO, ELODIA L
	ESQUER, YOLANDA
	MORLES, JULIE
537	GERARDO, REBECCA
540	VISTA SQUARE ELEMENTARY SCHOOL
541	QUINTERO, BLANCA B
543	SORIANO, JUDITH M
551	BORBOA, RICARDO
	FLORES, A
	GARCIA, FABIAN
	MARTINEZ, ANGEL M
	OROZCO, S F
	ORTEGA, RICARDO
	OSEGUEDA, D
	QUINTERO, LORENZO
	WALKER, J
553	GONZALES, BRENDA
	ORTEGA, DENIS J
560	FARFAN, VICTOR
	VILLALVAZO, MARIA R
561	MEZA, BRIGIDO
564	MATTHEUS, MARIA G
565	CATAGUA, FLOR
	PANTOJA, MARIA
	PEREZ, PAULINA
	RODRIGUEZ, NANCY
	SILVA, YOLANDA
567	OCHOA, VICTOR
568	OCCUPANT UNKNOWN,
571	FORD, JOEL P
580	CAMACHO, F
	COHEN, EDUARDO G
	DAVIA, MARIO
	GLORIA APARTMENTS THE
	GOMES, TAKA
	MERCADO, RAUL

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000 (Cont'd)

580	MEZA, C
	MIRANDA, ISMAEL
	ONEDERRA, MANUEL
	PEREDA, JULIO
585	DAVIS LES
590	ABILITEES COMPANY
	ALL VALLEY DRIVING SCHOOL
	GARCIA, G
	ROMAN ZERMENO
610	BARROWS, KAREN S
	CASTILLO, JACOB
	CLARK, JEFFREY
	COBB, RACHEL L
	CRUZ, MICHAEL
	DEAN, KEITH
	DESAHAGUN, NERO S
	HOOD, WILLIAM J
	KING, STEVEN D
	LUBIANO, A A
	MADDEN, LAURA L
	MURPHY, DENNIS M
	ONEILL, PEGGY
	RATLIFF, BONNIE A
	TUCKER, E
616	FIRST IMAGE PHOTOGRAPHY
	SOUTH BAY TOWERS APARTMENTS
628	THE WOODCHUCKS
633	ESTRADA, M
635	WRAY, CATO W
637	BELTRAN, BEVERLY M
644	FREEWILL BAPTIST CHURCH
651	OCCUPANT UNKNOWN,
677	ACKERMAN, A
	ADAMSON, RALPH T
	ANDREWS, BEULAH
	BEERS, WESLEY J
	BERGERON, RAYMOND J
	BIGGERS, EARL D
	BRANDT, STEVE N
	BURGER, A
	BUSCHUR, LAURA
	CASTEEL, RUBY L
	COOK, ROLINE
	COOPER, JOHN E
	CORBETT, RICHARD J
	CORBIN, ROBERT L
	DECARO, MICHAEL
	DUNKER, N M
	ECKHARDT, S A
	ELKINS, M J

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000 (Cont'd)

677	ELMORE, JAMES
	FRANKLIN, HARRY
	GAGLIANO, A
	GARCIA, OFELIA
	GIUSTI, JULIUS J
	HAHN, JEAN A
	HALL, STANLEY B
	HAMILTON, J M
	HAMNER, JULIA
	HARVEY, JERRY D
	HIME, M H
	HINKLE, DARYL B
	HUBERT, RICHARD
	HUTCHISON, H S
	JACKMAN, D
	JOHNSON, L A
	JOHNSON, RAY B
	JONES, HUGH L
	JONES, LAMAR R
	KANNITZER, TONY
	KELLOGG, EVELYN B
	KINCAID, F I
	KOLBOWSKI, JENS D
	KURINKO, HAZEL
	LAMARK, DOROTHY L
	LEDINGHAM, COLLEEN
	LLOYD, H D
	MAGALLANES, ALICIA
	MANGLESS, DONALD R
	MANLEY, DONALD A
	MANN, HILDRA
	MATHEWS, R P
	MCCAMON, FRANK
	MCGRATH, W B
	MEILE, R E
	MENDOZA, LUPE C
	MEZA, ANDREA
	MEZA, MARCELA
	MORSE, MICHAEL W
	MOSS, WILLIAM W
	NELSON, JOYCE
	NEWMAN, L L
	NICHOLS, BARBARA
	ORTIZ, J
	PEREA, CHARLIE H
	PERRY, BARBARA G
	POTTS, CLAUDIA T
	RADINOVSKY, SID
	RAINS, YUKO
	RICE, WILLIAM A

G ST 2000 (Cont'd)

677	RICHE, JAMES
	ROBB, MARJORY C
	ROTHELL, CHERYL E
	RUIZ, ALFREDO
	RUSSELL, FRANK
	SANDOVAL, H A
	SAUNDERS, LESLIE
	SCHOLL, L M
	SMITH, EARL J
	STINEBUCK, NANCY J
	TAGLE, BEATRIZ N
	TERRYS MOBILE PARK
	THOMAS, WENDELL C
	TREVINO, ROBERT
	UHER, C
	VILLAFURTE, TONY
	VINING, GORDON
	VOLLER, DONALD R
	WATSON, KENNETH D
	WEIR, NORMAN J
	WHITE, L D
	WHITTAKER, ROBERT
	WILLIAMS, BERNARD
	WILLIAMS, JARRETT R
	WOLFE, GERALD
	YELLAND, E M
691	GARCIA, REBECCA
704	CASTANEDA, GUADALU
	ZATARAIN, JOSE
716	CORONADO, HENRY U
	HAMPTON, MARIA
	LOPEZ, EDUARDO R
	MACIAS, INES
	MOORE, V A
724	CARTER, EMIKO S
	HADDAD, LUMA
	KHALIFEH, ISSA O
	SOCAL ROOFING COMPANY
731	ABBOTT, BEN
	ALLEN, GEORGE J
	ARCHULETA, MARTHA
	BOWEN, A
	BYRNE, HELEN A
	CABRILLO MOBILE LODGE
	CLAY, M L
	CORONA, M
	CORONA, S
	CUEVA, G C
	DENESSEN, DONALD A
	DONOGHUE, LEO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000 (Cont'd)

731	DONOHUE, M E
	DREDGE, HENRY
	DROZE, S L
	DUFFY, WILLIAM A
	GERBASIO, M
	GLEASON, EDWARD J
	GROSSMAN, B
	HARTMAN, BETTY J
	HATCHETT, IRA H
	HOLLINGER, OSBORN E
	IULI, PHILLIP
	JENKINS, ROGER F
	JOLLY, BARBARA
	LEWIS, FOX C
	LITTLE, M D
	LOTZGESELLE, LINDA A
	LUGO, A
	MILLER, ALICE
	MILLER, BABY
	MOULTON, EDWARD H
	MURPHY, LINDA
	OROZCO, MANUEL C
	PAWLAK, EDWARD F
	PULLIN, C T
	RAMIREZ, VICTOR J
	SEGHERS, DOREEN H
	SHEPHERD, NICK
	SPENCER, W A
	THOMAS, JOHN S
	TINITIGAN, ZENAIDA P
	TURNER, ALFRED
	WALTHALL, GLENN A
	WENTWORTH, FRED E
	WHITTINGTON, R L
	WYMORE, R W
736	BORGE, JAMES
	VELA, EDUARDO
	VELASQUEZ, CESAR L
	VELAZQUEZ, GABRIEL H
	WISSER, JOHN H
997	PARAMOUNT SCAFFOLD COMPANY
	SOUTH BAY BOAT YARD NAUTICAL HARDWARE STORE
	SWATH OCEAN SYSTEMS INCORPORATED

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995

30	OCCUPANT UNKNOWNN
36	MEYER, RENE
39	DIEZDEBONILLA, E
42	HILDEBRAND, ERNEST H
45	INTERIORS UNLIMITED
	OCCUPANT UNKNOWNN
48	SHARP, LEAH
52	LONG, FRANK
55	OCCUPANT UNKNOWNN
67	JONES, LAMAR
70	STANCZAK, FRANK J JR
78	PERRY, DALE W
83	ARIZAGA, RAUL
84	OCCUPANT UNKNOWNN
86	DUNKLE, RAYMOND E
87	CHASE, P A
90	MURRAY, F E
93	STONE, BILLIE C
102	RICO, J
108	CARRERA, CECILIA
111	DALE, ROBERT G
115	OCCUPANT UNKNOWNN
121	ZAPPONE, CARMEN
124	OCCUPANT UNKNOWNN
130	OCCUPANT UNKNOWNN
134	PERRY, ROBERT R
135	PHILLIPS, IRENE
140	EVANS, BRIAN
141	OCCUPANT UNKNOWNN
146	DEERING, R W
152	MURPHY, DAVID J
155	LEYBA, RAMON
156	RADER, TIFFANY N
159	STEIN, K F
	WALLACE, FRANK T
160	DELAGARZA, CRYSTAL
161	OCCUPANT UNKNOWNN
163	SUTTON, THOMAS W
164	KELLY, THOMAS M
167	HICKMON, GOLDIE R
170	OCCUPANT UNKNOWNN
173	VINSON, CHARLES L
174	MOLSBERRY, MARK
177	KINNAMON, KEVIN C
181	HALTMEYER, FRED H
182	OCCUPANT UNKNOWNN
186	BARNES, ANITA L
194	DIXON, TIM B
195	TROTTER, JANET C
198	MCLINTOCK, WILLIAM N

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

202	BECKWORTH, NORMAN
203	JOHANSEN, JACK
204	OCCUPANT UNKNOWNN
205	AMOS, E H
207	AMOS, E H
210	EICHER, DARRYL
	LADD, L E
211	DOBSON, FORREST
214	OCCUPANT UNKNOWNN
215	AVILA, PEARL
	PARKS, JUANA L
217	OCCUPANT UNKNOWNN
222	ALLEN, W H
	ALLEY, F G
	ANDINO, CECILIA T
	BARRY, F E
	BORG, P N
	BOWMAN, MARY
	CALVERT, G L
	DIXON, D V
	EVANS, M
	FELDMAN, EDYTHE
	GALVAS, JOHN J
	HANSMAN, FRANCES L
	HAUSS, H C
	KNOX, J
	KODISH, SAMUEL J
	LE CHATEAU APARTMENTS
	LOCKWOOD, C M
	NORTH, STANLEY P
	PRESTON, RALPH G JR
	RAMIREZ, L
	ROBERTS, R F
	SALONIA, M
	SHALL, A
	STEPHENS, JEAN
	TOBITS, ARTHUR W
	ZAVALA, ALEX
223	FASTH, M
	ZULAICA, BENITO
224	PRESTON, RALPH
226	BARRIOS, CARMEN A
227	OCCUPANT UNKNOWNN
229	OCCUPANT UNKNOWNN
233	DOEGE, DOUGLAS W
236	OCCUPANT UNKNOWNN
239	ZANDS, SAMUEL
241	DALY, C
	GONZALEZ, BECKY
	ORTIZ, MARIO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

241	SANCHEZ, MARIA E
246	OCCUPANT UNKNOWNN
248	STOUT, PAGE
252	BERNABEI, LAURA
	BLACKTON, BOBBIE
255	BOGART, JAMES M
	MILLER, M G
264	ROSAS, E
265	ADAME, GRACE
	CARR, MIKE
	COWHERD, JUDITH M
	ESTRADA, JOSEPH
	GALLEGOS, WILL
268	JOHNSON, RICHARD A
	QUIGLEY, AMY
274	OCCUPANT UNKNOWNN
	PHOTOGRAPHY BY GREGORY
277	FRITCHER, JAMES F
	JIMS GUN SHOP
281	FAMILY TAX & BOOKKEEPING SVC
	JAY DEE REALTY
	JORDAN & ASSOC REAL ESTATE
	JORDAN, DAN
	YELLOW BIRD CO
282	F L WHITTINGTON & ASSOC
283	DWIGHT GOVE AGENCY INC
286	BUTLERS AUTO & ELECTRIC
287	DENNIS S MC DOUGALL
	FRANK A ROCKWELL
289	OCCUPANT UNKNOWNN
309	CASAS, A
310	FRACAROLLI, R
	FRANTZ, JESSIE
	GARDNER, RALPH
	KENNERLY, AL
	KOHMETSCHER, KENNETH
311	HABEL, N S
313	STOCKTON, PEGGY L
315	OCCUPANT UNKNOWNN
317	BRUDER, DORIS M
	ONOFRIO, E R
	REDMAN, C A
318	BOUTWELL, THOMAS F
	CHICCA, ANN M
	FARIS, BRANDE
	GATES, R
319	POLIDORI, M
320	BAKER, ROGER E
	COLE, NELLIE S
	DUKES, VICTOR M

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

320	FIFE, PAMELA
	HASTY, DANNY R
	KNUDSEN, JOHN
	PURVIS, GUILA H
321	TORRES, RAUL H
323	OCCUPANT UNKNOWNN
325	OCCUPANT UNKNOWNN
330	CAMACHO, DELMA
	CARRENO, ELENA
	LOPEZ, ROMELIA G
	MAUTINO, KATHRIN
	TRUJILLO, ESTHELA
333	OGILVIE, FLOYD E JR
334	ABBOTT, REBECCA M
	ACUNA, P
	BARENO, DAVID
	BUCHER, LISA L
	HERNANDEZ, JAVIER
	JONES, CHARLES R
	MONTANO, MARIA D
	WOOD, SCOTT
335	WILLIAMS, C L
336	PONCE, KIM
340	ALARID, JESSICA G
	DEJOURNETT, JASON
	WEAVER, ROY E
341	TORRES, MIGUEL
345	HUGHES, M
350	GUTIERREZ, JORGE
	HATCHER, JANA
	HIGH, LEONORA G
	INIGUEZ, E
	LONGENECKER, KIRK
	MCCULLOUGH, LOUISE M
	PRICE, RODNEY
	SKUZINSKI, PHYLLIS L
	ZATARAIN, SHELLEY
357	CHULA VISTA WOMANS CLUB
	UNITY BY THE BAY
363	OCCUPANT UNKNOWNN
364	OCCUPANT UNKNOWNN
367	OCCUPANT UNKNOWNN
368	BETTS, MARSHA
370	PADILLA, FRANCES
371	DIAZ, DANIEL
372	PINDO, LOURDES
	PINEDO, LOURDES
374	SLINKARD, WILLIAM C
375	HUFFMASTER, PAUL
	MURPHEY, LILLIAN H

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

379	ALL FAITHS
	KEMERY, WILLIAM E
	NEW THOUGHT EPISCOPAL CHURCH
383	MARTINEZ, JUAN M
385	MARTINEZ, JUAN
386	BAILEY, CLAY
390	BLASKO, M
	FERNANDEZ, S
391	PALACIOS, DAVID R
394	DOMINGUEZ, GABRIEL
	RENINGER, ERICK M
399	HAMMOND, JAMES M
402	ROSARIO, NANCY
404	GARZA, V
406	OCCUPANT UNKNOWNN
408	OCCUPANT UNKNOWNN
411	KONDRASHOFF, BRANDY
	SANTOS, URSULA
	SUMACOT, FACUNDO
412	OCCUPANT UNKNOWNN
414	SPARBY, REBECCA I
415	OCCUPANT UNKNOWNN
416	OCCUPANT UNKNOWNN
418	WILSON, PENNI L
419	BOSCOSKY, ROBERT
422	CASTLE, V
423	POWELL, F L
	TESTER, GLENN
	WORTHAM, MYRIAME
427	OCCUPANT UNKNOWNN
431	KELLY, SHEA
439	OCCUPANT UNKNOWNN
447	ELLIS, JOYCE E
459	MORRELL, JOHN E
463	LAWRENCE, CHRIS
469	GENTILE, HENRY
473	MACK, BEN L
479	ZACHARIAS, BOB
485	MILLER, PETER G
489	ORSINGHER, CASSIE
503	NATARET, JOSE L
507	MEJIA, F J
515	OCCUPANT UNKNOWNN
517	FOWLER, ROLLY
519	ROMERO, ALI
521	GUTIERREZ, DORIS
	MORENO, MARIA
525	VICTA, RICK
529	ASTORGA, STEVE H
531	OCCUPANT UNKNOWNN

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

535	ALARCON, G
537	OCCUPANT UNKNOWNN
540	VISTA SQUARE ELEMENTARY SCHL
543	OCCUPANT UNKNOWNN
551	BORBOA, RICARDO
	DOBBINS, RAYMOND T
553	ORTEGA, DENIS J
556	OCCUPANT UNKNOWNN
560	FARFAN, VICTOR
561	RODRIGUEZ, ENRIQUE
565	FIGUEROA, MARIA R
567	OCHOA, VICTOR SR
568	ANDREWS, ROBERT F
571	FORD, JOEL P
580	ACUNA, MAYOLA
	GLORIA APARTMENTS
	LABSAN, LOU
	MORFIN, M
	PORTILLA, ELSA
	PROTILLA, ELASA
	SANTAMARIA, TONY
	VASQUEZ, JOHN
581	LARA, AGUSTIN
590	ALL VALLEY DRIVING SCHOOL
	ARCHITECTURAL & CONSTRUCTION
	CENTURION TRADING INC
	INDEPENDENT BANKRUPTCY DIVORCE
	PTS
	STAR SATELLITE CO
610	CASTILLO, JACOB
	CONNAIR, K
	GLORIA, JEFF
	GOODMAN, RICHARD
	HESS, L
	HORTON, J
	KAMRAN, SAHMAN
	LOPEZ, ELLA
	NEELY, WINSTON
	NUNEZ, JUAN
	ODONNELL, JOHN M
	ONEILL, PEGGY
	REYES, ARTURO L
	SCHNIZ, DEBORAH
	SCHUTZ, DEBORAH
	VALARIANO, ANA
	VLAERIANO, RUTHANN
615	OCCUPANT UNKNOWNN
616	ABBOTT, TYNA
	AQRAWI, SABAH
	BAUKOL, DONALD R

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

616	BECKLEY, C
	BLOOMFIELD, PHILIP
	BUTLER, L
	CASSADY, EDWARD L
	CONTANT, L E
	COOPER, RUSSELL W
	DARGALAYE, NOEMI
	DENESSEN, HELEN F
	FELDT, JOHN H
	GARCIA, ROBERT
	GARDINER, THOMAS
	HAAS, WENDY
	HANSON, R C
	HASTINGS, GLENN
	JIRICEK, MYRON
	JOHNSTON, JOHN F
	KERNS, BONNIE
	KONIARSKI, JEANE M
	LEBOEUF, RON
	MILLER, VICTOR L
	NAVE, J R
	RICHARDS, FRANK
	RITCHIE, LORAINE
	ROTHBART, JASON
	SAINZ, H L
	SCHAUFELBERGER, JAMES B
	SCHOLLIAN, CLARA
	SIOR, DOUGLAS L
	SLATTERY, DONALD D
	SMITH, K
	SOUTH BAY TOWERS APARTMENTS
	THOMPSON, J J
	THOMPSON, TODD
	TORRES, YSAIAS S
	TYNER, COREY
	UPDEGRAFF, E H
	WHITMAN, MARY L
	YOUSEF, HASAN
	ZANGANA, ALAN
	ZOURA, FAEEZ
628	OCCUPANT UNKNOWNN
629	OCCUPANT UNKNOWNN
633	ESTRADA, M
635	OCCUPANT UNKNOWNN
644	FIRST FREE WILL BAPTIST CHURCH
646	OCCUPANT UNKNOWNN
649	OCCUPANT UNKNOWNN
651	SUMNER, CLINT G SR
667	SITZ, PATSY F
677	ACKERMAN, A

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

677 ADAMSON, RALPH T
ALLEN, E
BARBER, MICHAEL
BARKER, T L
BEERS, WESLEY J
BEHRENS, E
BENNETT, M L
BERGERON, RAMOND J
BIGGERS, EARL D
BOTTS, ROBERT J
BRANDT, STEVE N
BRODERICK, ARTHUR
BURGER, MICHAEL T
BUSCHUR, LAURA
BUXTON, FRED
COOK, ROLINE
COOPER, JOHN E
CORBIN, AVIS
CSILLAG, MURIEL
CUESTA, K
DAVIS, MAUDE L
DOUGHERTY, F E
DOYLE, R
DUNGAN, K W
DUNKER, N M
ECKHARDT, S A
ELKINS, M J
FRANKLIN, HARRY
FREELAND, BILL
GAGLIANO, A
GIUSTI, JULIUS J
GLENN, LOIS
GOERSS, FRITZ
GREENE, FRANK S SR
HALL, STANLEY B
HAMILTON, J M
HAMNER, LYLE E
HARVEY, JERRY D
HAYDEN, ANNA
HIME, M H
HINKLE, DARYL B
HORST, PAUL
HUTCHISON, H S
JACKMAN, D
JOHNSON, GENE
JONES, LAMAR R
KANNITZER, TONY
KELLOGG, EVELYN B
KELLOGG, ROY F
KELLY, JAMES P

G ST 1995 (Cont'd)

677 KETCHUM, GEORGE
KINCAID, F I
KISBERT, CHARLES A
KOLBOWSKI, JENS D
KURINKO, HAZEL
LABEAU, A
LEBLANC, RONALD
LLOYD, H D
MAGALLANES, ALICIA
MANGLESS, DONALD R
MANLEY, DONALD A
MANN, HILDRA
MARSH, ROBERT L
MARSTERS, GORDON
MATHEWS, R P
MCCAMON, FRANK
MCKEE, D
MCMILLAN, CARL A
MEILE, R E
MENDOZA, LUPE C
MEZA, ANDREA
MUNTER, WILFRED
NEWMAN, L L
NICHOLS, BARBARA B
NORMAN, CLINT SR
PERRY, G H
PORTER, ALFRED L
POTTS, CLAUDIA T
RICE, WILLIAM A
RICHE, LYNNE
RIIFF, DORIS M
ROBB, MARJORY C
SALLAM, MYNNA
SAUNDERS, LESLIE
SCHOLL, L M
SHAFFER, ORLA
SMITH, EARL J
SMITH, LEWIS V
STROUP, CHARLES W
SWOPE, D R
TAGLE, BEATRIZ
TERRYS MOBILE PARK
THOMAS, WENDELL C
TREVINO, ROBERT
UHER, J P
VALITON, H D
VERSLUIS, ISABEL L
VINING, GORDON
VOLLER, DONALD R
WALKER, ERVIN G

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

677	WATERS, RONALD B
	WATSON, KENNETH D
	WEBSTER, LUCILLE
	WHITE, L D
	WILLIAMS, BERNARD
	WILLIAMS, H
	WILLIAMS, JARRETT R
	WOLFE, GERALD
	YELLAND, E M
704	ORTIZ, E
	QUIROZ, BARBARA
716	CORONADO, HENRY U
	WRIGHT, DONOVAN
724	CARTER, LOIS
730	OCCUPANT UNKNOWNN
731	BOARD, WILLIAM D
	BROOKS, W
	BYRNE, HELEN A
	CABRILLO MOBILE LODGE
	CLAY, M L
	CYRANKOWSKI, LUCY
	DECOLIBUS, GLEN
	DONOHUE, M E
	DREDGE, HENRY
	DROZE, S L
	DUFFY, WILLIAM A
	DWYER, JOHN
	FARNSWORTH, GLADYS
	GERBASIO, M
	GLAHOLM, THOMAS
	GLEASON, EDWARD J
	HARRIS, EARL G
	HARTMAN, BETTY J
	HOLMES, MARETTA F
	HOWARD, H J
	JACKSON, WILLIAM R
	JORGENSON, VERNON
	KIRKPATRICK, ROBERT M
	LESHINSKI, JOSEPH A
	LITTLE, M D
	LUNDGREN, ALAN C
	MEYER, SARA
	MILLER, ALICE
	MILLER, BABY
	MILLER, J L
	MOULTON, EDWARD H
	OROZCO, MANUEL C
	ORTUSO, NATHAN
	PHELPS, RALPH C
	PULLIN, C T

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

731	ROMANDIA, YVONNE
	RYAN, G
	SEGHERS, D H
	SHENNERS, CHUCK
	SINCLAIR, CLAUDIA
	SPENCER, W A
	TURNER, ALFRED
	WENTWORTH, FRED E
736	BORGE, JAMES
	SANTANA, ROSA M
	WISSER, JOHN H
979	SWATH OCEAN SYSTEMS INC
997	BAYSIDE BOAT STORAGE
	SOUTH BAY BOAT YARD

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1992

15	MORGAN, LEE J
42	HILDEBRAND, ERNEST H
45	INTERIORS UNLIMITED
	MICHAEL, HENRY L
52	LONG, FRANK
55	OGDEN, JACK L
70	STANCZAK, FRANK J JR
71	NELSON, ANTON J
86	DUNKLE, RAYMOND E
93	STONE, BILLIE C
111	DALE, ROBERT G
121	ZAPPONE, CARMEN
130	HULST, WARREN J
134	PERRY, ROBERT R
135	PHILLIPS, IRENE
141	ALLEN, VIVIAN E
146	DEERING, R W
159	STEIN, K F
	WALLACE, FRANK T
163	SUTTON, THOMAS W
164	KELLY, THOMAS M
173	TAULBEE, L
181	HALTMEYER, FRED H
194	DIXON, TIM B
195	TROTTER, JANET C
202	BECKWORTH, NORMAN
203	JOHANSEN, JACK
207	AMOS, E H
210	LADD, L E
215	PARKS, JUANA L
222	ALLEN, W H
	BARNHART, RICHARD E
	BARRY, F E
	BUTLER, EDITH C
	LECHATEAU APARTMNTS
	PRAY, M L
	SALONIA, M
	ZAVALA, ALEX
223	FASTH, M
	LOPEZRIVERA, CARLOS
	ZULAICA, BENITO
226	BARRIOS, CARMEN A
229	PRICE, KEVIN
233	DOEGE, DOUGLAS W
241	RUTHERFORD, VIOLEE F
244	LILLEYMAN, A I
252	FLINT, SUZANNE L
	ISLEK, ALP
255	VISCARRA, ADRIANA
264	CASILLAS, XAVIER

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1992 (Cont'd)

264 SORENSON, ROBERT
268 JOHNSON, RICHARD A
SPRING CLEANING
274 PHOTOGRAPHY GREGORY
277 FRITCHER JAS F
FRITCHER, JAMES F
281 DEE JAY REALTY
FAMILY TAX SERVICE
JORDAN DAN
JORDAN, DAN
YELLOW BIRD COMPANY
282 AILE INTERIOR DSGN
WHITTINGTON F&ASCTS
283 GOVE DWIGHT AGCY
286 BUTLERS AUTO&ELEC
287 MCDOUGALL D S ATTY
ROCKWELL F APC ATTY
309 GOMEZ, MANUEL
310 KENNERLY, AL
KOHMETSCHER, KENNETH
311 HABEL, N S
313 STOCKTON, PEGGY L
317 GALLAGHER, JOE
ONOFRIO, ESTHER R
318 DELAROSA, RICHARD
DUENAS, JOHN
POPE, S
319 POLIDORI, M
320 COLE, NELLIE S
SOTO, OLIVIA
325 KAYE, JOHNNY
330 KEATING, TROY
WEATHERRED, C G
333 OGILVIE, FLOYD E JR
334 SANTAMARIA, JOSEPH
335 LUCKINBILL, CHARLES O
340 WEAVER, ROY E
350 HIGH, LEONORA G
MCCULLOUGH, L M
SIEVI, VERA
357 CHULA VST WOMAN CLB
371 KONDRASHOFF, EUGENE R
374 SLINKARD, WILLIAM C
375 MURPHEY, LILLIAN H
379 ALL FAITHS
KEMERY, WILLIAM E
NEW THGHT EPSCPL CH
383 MORTON, LARRY
394 DOMINGUEZ, GABRIEL
399 HAMMOND, JAMES M

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1992 (Cont'd)

411 SUMACOT, EMMA
414 SPARBY, REBECCA I
419 BOSCOSKY, ROBERT
424 ENGLISH, P
JIMENEZ, JOSE
LONG, DAVID D
427 WOOD, JUAN A
473 MACK, BEN L
479 MACK, L
489 HARTZHEIM, GARY
507 MEJIA, F J
515 DELEON, CONNIE
517 FOWLER, ROLLY
521 AGUILAR, S
DAVIS, AUBREY
535 CASTRO, ANTHONY
540 VISTA SQ ELEM SCHL
553 ORTEGA, DENIS J
560 FARFAN, VICTOR
564 DORAME, C
NAVARRO, ROSIO
565 RAMIREZ, ABIGAIL B
567 OCHOA, VICTOR SR
568 GONZALEZ, VICTOR
580 CADENA, N
CAMACHO, SANDRA
GLORIA APTS THE
GONZALEZ, RAQUEL
TANSLEY, M
URIBE, IGNACIO S
WHITE, G
581 LARAS&AARONS APLNCS
585 DAVIS, LES
590 ARCHITCTRL&CONSTR
CASAS DE MARQUEZ
INDEP BNKRPTY DVRCE
MOARALES, AGUSTIN A
MORALES AGUSTIN A
NIMAC PROPERTIES
P T S
610 CAPWELL, JOHN
HANSON, ROMAINE C
HARDIMAN, PAP J
HESS, L
WALLACE, THOMAS J
616 ARAUJO, ARMANDO
GRIMSBY, TRESA
JOHNSON, DENNIS A
JOHNSTON, BRUCE F SR
MANKUS, EDWARD

G ST 1992 (Cont'd)

616	PETZEL, NEIL
	RODRIGUEZ, YOLANDA
	SAINZ, H L
	SLEWA, WILLIAM D
	SOUTH BAY TOWER APT
	TORRES, YSAIAS S
	VARGAS, PEDRO
633	ESTRADA, M
635	WRAY, CATO W
644	FREEWILL BAPTIST CH
651	SUMNER, CLINT G SR
667	MARSTERS, GORDON
677	BENNETT, M L
	BOTTS, ROBERT J
	BROADWAY TRAILER PK
	DENTON, WALLACE W
	DUNGAN, K W
	ELKINS, M J
	GAGLIANO, A
	GEORGE, L B
	GREENE, FRANK S SR
	HAYDEN, ANNA
	HOWELL, JOHN P
	JOHNSON, GENE
	KELLY, THOMAS
	KETCHUM, GEORGE
	MARNETTE, OTTO H
	POTTS, CLAUDIA T
	SMITH, LEWIS V
	SWOPE, D R
	WEIR, I
	WILHELMI, W D
716	CORONADO, HENRY U
731	APPLETON, PERRY H
	CABRILLO MOBILE LDG
	CYRANKOWSKI, LUCY
	DWYER, JOHN
	GLEASON, EDWARD J
	GRASSO, S
	LITTLE, M D
	MILLER, ALICE
	MILLER, BABY
	MILLER, J L
	PULLICIN, C T
	QUINN, E L
	SEGHERS, D H
	SPENCER, W A
	VANCUYK, B
	WILSON, G A
736	BORGE, JAMES

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1992 (Cont'd)

736 WISSER, JOHN H
997 BAYSIDE BOAT STRG
SOUTH BAY BOAT YARD
SWATH OCEAN SYSTEMS

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1986

G 92010 CHULA VISTA

NO #	CA CRANE&RIGGING SV	425-6590	3
NO #	CA CRANE&RIGGING SV	238-1456	1
NO #	POOLE BOAT CO	420-1383	2
14	ACKERMAN DICK	427-3829	
15	MORGAN LEE J	422-5951	
30	XXXX	00	
36	XXXX	00	
39	XXXX	00	
42	HILDEBRAND ERNEST	420-3626	
45	FOWLER ROLLY W	427-2847	3
48	XXXX	00	
52	LONG FRANK	422-7840	4
55	OGDEN JACK L	422-2664	1
60	XXXX	00	
68	XXXX	00	
70	STANCZAK FRANK JR	420-6731	8
71	NELSON ANTON J	422-5463	0
78	WILLIAMS ARTIE	420-6597	8
83	JOHNSON ROBT G MR5	420-8995	0
84	JENKIN5 SIDNEY R	422-5557	
86	XXXX	00	
87	XXXX	00	
90	MURRAY L	422-6837	4
93	5TONE B C	422-8838	
102	FIRKINS WM G DC	585-0300	5
108	REMLEY J R JR	425-9253	1
111	DALE ROBT G	422-6217	
115	LAIRD HAROLD L	422-6039	
121	ZAPPONE CARMEN	427-3194	
130	HULST WARREN J	585-7194	+8
134	XXXX	00	
135	PHILLIPS IRENE	422-7494	
141	ALLEN ERVIN	422-3797	
148	DEERING R W	420-6445	
147	RHODES ROBT R	420-3035	5
155	XXXX	00	
159	STEIN K F	420-1470	1
	WALLACE FRANK T	420-1470	1
160	CORNELL DANA A	585-3706	+6
161	XXXX	00	
163	SUTTON THOS W	422-6296	
164	MATTSON MATT W	422-2376	
173	LONG L K	422-5580	2
174	XXXX	00	
177	MCCLAIN RONALD	585-3267	5
181	HALTMEYER F H	422-1885	
182	XXXX	00	
186	SOTO RAFAEL Y	422-8701	9
194	DIXON CARMEN C	427-0173	
195	TROTTER RONALD G	420-1687	1
	TROTTER RONALD G	420-9688	4
197	FETTER E	425-3409	+6
	SEKULA V	425-3409	+6
198	DEWEY ROCKFERD R	425-0936	3
	SMITH JASON	425-0936	1
202	FLORES JOSE M	422-4603	
203	JOHANSEN A	425-5747	9
207	AMOS E H	422-6038	
210	LADD L E	422-6456	
215	PARKS JUANA L	426-1333	1
	SIMAS OSCAR	691-9438	5
217	DAMM L W	426-2755	
222	LECHATEAU APTS		
16	ADAMS HESTON D	427-3026	
	ADAMS LUCILLE	427-3026	
302	ALLEN W H	420-3079	
	BEATTY BEA G	425-4567	+6
309	BENGE E R	426-0273	9
317	BUTLER EDITH C	426-1907	
213	CALVERT G L	425-0988	0
	DIBLASI CHRISTINA M	425-6019	4
209	DIXON D V	427-0931	
	ELLIS DELMAR D	427-4954	5
102	GALVAS JOHN J	427-0813	
303	GAUSDEN MATTABELLE	422-6909	9
	HICKMAN ROBERT G	426-3097	3
206	JONES M	426-6513	
	KODISH SAML J	420-1171	+6
16	KOOB O E	427-2229	
115	LECHATEAU APARTMNTS	422-4656	
307	LOCKWOOD C M	427-1204	
	MAGNUSON EILEEN I	691-7813	+6
	NEGAS M L	426-2206	3
110	PANKHURST RICHARD	425-1989	9
112	PAUL LEON	426-8397	0
	PAZANEN C	420-4413	+6
301	PIRIE M C	425-4801	7
315	PRAY M L	420-6515	
109	QUEEN MILORED	427-2397	
	SALONIA M	420-3624	2
214	SCHILLING FRANK MRS	427-0911	
	STEWART H C	425-9211	4
	TOOVEY A M	420-9645	+6
	TURNER RICHARD T	425-1105	5
313	WILCOX LAWRENCE	420-2663	
222			
223	FASTH M	427-3209	
226	HERRERA BERNARD	425-4319	
	HERRERA MAY	426-4319	4
	LOVSTROM STEWART	426-4384	+6
227½	FORREST E L	422-3424	
228	XXXX	00	
229	PRICE BARBARA	691-8130	
	PRICE KEVIN	691-8130	5
233	DOEGE DOUGLAS W	425-3996	
239	BRIGGS EDW L	425-3330	

Target Street	Cross Street	Source
✔	-	Haines Criss-Cross Directory

G ST 1986



Target Street	Cross Street	Source
✔	-	Haines Criss-Cross Directory

G ST 1986



Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1982

G 92010 CHULA VISTA

NO #	CALIF CRANE&RGGNG	238-1458	1
NO #	POOLE BOAT CO	420-1383	+2
14	ACKERMAN DICK	427-3829	
15	MORGAN LEE J	422-5951	
	MORGAN NELLIE E	422-5168	0
30	XXXX	DD	
36	XXXX	DD	
39	XXXX	DD	
42	HILDEBRAND ERNEST	420-3626	3
45	XXXX	DD	
48	XXXX	DD	
52	LONG FRANK M	422-5406	6
55	OGDEN JACK L	422-2664	1
60	XXXX	DD	
66	HONDIUS PETER	422-2277	
70	STANCZAK FRANK JR	420-6731	8
71	NELSON ANTON J	422-5463	D
78	WILLIAMS ARTIE	420-6597	8
83	JOHNSON ROBT G MRS	420-8995	0
84	JENKINS SIDNEY R	422-5557	
86	HARRINGTON ROBT	420-0483	1
87	CHASE PALMER	425-9553	1
90	RODR JE2 NORALMA	427-4816	1
93	STONE B C	422-8838	4
102	FIRKINS WM G DC	427-6966	3
108	REMLEY J RJR	425-9253	1
111	DALE ROBT G	422-6217	
115	LAIRD HAROLD L	422-6039	
121	ZAPPONE CARMEN	427-3194	
130	HULST WARREN J	427-7478	9
134	XXXX	DD	
135	PHILLIPS IRENE	422-7494	
141	ALLEN ERVIN	422-3797	
146	DEERING R W	420-6445	
147	XXXX	DD	
155	XXXX	DD	
159	STEIN K F	420-1470	1
	WALLACE FRANK T	420-1470	1
160	PEDROZA R	426-4935	D
161	EGGERT JOS M	422-5095	1
	MALAGO D L	422-5095	1
163	SUTTON THOS W	422-6296	
164	MATTSON MATT W	422-2376	
173	LONG L K	422-5580	+2
174	XXXX	DD	
177	CURETON S W	422-5625	
181	HALTMEYER F H	422-1685	
182	XXXX	DD	
186	BARNES LEO	422-6768	
	SOTO RAFAEL Y	422-8701	9
194	DIXON CARMEN C	427-0173	
195	TROTTER RONALD G	420-9089	+2
	TROTTER RONALD G	420-1637	1
197	WENK WILLIAM	420-3969	1
198	SMITH JASON	425-0936	1
202	FLORES JOSE M	422-4503	
203	JOHANSEN A	425-5747	9
207	AMOS E H	422-6038	
210	LADD L E	422-6456	
215	PARKS JUANA L	426-1333	1
217	DAMM L W	426-2755	
222	LECHATEAU APTS		
16	ADAMS HESTON D	427-3026	4
302	ALLEN W H	420-3079	
309	BENGE E R	426-0273	9
317	BUTLER EDITH C	426-1907	
213	CALVERT G L	425-0988	D
306	CUNARD I C	426-1167	4
	DEBEAULIEU LOUIS V	422-5028	D
209	DIXON D V	427-0931	3
205	FLOYD R A MAJ	422-4807	9
102	GALVAS JOHN J	427-0613	
303	GAUSDEN HATTABELLE	422-6909	9
	GOODBODY VIRGINIA	426-7514	1
206	JONES M	426-6513	6
16	KOOD O E	427-2229	6
115	LECHATEAU APARTMNTS	422-4655	
	LEDBETTER LEONARD E	427-8093	1
307	LOCKWOOD C M	427-1204	4
	MAGEE ALBERT L	422-4298	+2
18	MCCORMICK CLAY	422-9187	5
110	PANKHURST RICHARD	425-1969	9
112	PAUL LEON	426-6387	D
316	PEITON J C	427-2868	
301	PIRIE M C	425-4801	7
315	PRAY M L	420-6515	
109	QUEEN MILDRED	427-2387	6
204	RULIK W	420-4512	4
	SALONIA M	420-3624	+2
214	SCHILLING FRANK MRS	427-0911	3
314	SEAMAN H K	420-0309	3
201	SKINNER HARRY	425-3847	D
202	SNYDER WILBUR A	427-8061	5

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1982




G		9201D CONT
310	WEAVER BILLY B	427-2785 0
313	WILCOX LAWRENCE	420-2663
311	WOERNER ORMAND	425-2544 5
222		
223	FASTH M	427-3209 5
	JOHNSON W B	427-8677 +2
226	HANOMO HELFON DR	426-4727 +2
	SPARKS RAYMOND L	420-7360 1
227	FORREST WALTER W	422-1023
227½	FORREST E L	422-3424
228	XXXX	00
229	WOODEN0 MYRTLE M	422-2640
233	DORGE DOUGLAS W	425-3996 5
239	APARTMENTS	
	BRIGGS EDW L	425-3330 8
	ESTRADA SEBASTIAN	426-5799 +2
	FREAKLEY R H	422-2568 1
	MURRAY NILA	422-8228 1
	SMITH D V	427-8389 1
239		
240	THOMAS J M	422-4254
241	MANJARREZ ROGELIO	427-4314 1
	RUTHERFORD V F	420-2313 D
244	LILLEYMAN A I	420-3572 5
244½	NICKELSON J J	422-3247 D
246	ARNEAL M	420-5927 6
248	CUNNINGHAM S F	422-2212 5
250	HENDEL E C	427-8796 D
252	ARCE FRED	425-5450 +2
	HARVEY ZITA M	425-3529 1
	WALKE S E	426-3916 4
255	BOGART MARK	427-0257 +2
	BROWDER J M	425-5915 +2
	MILLER M G	426-6348 +2
	RASMUSSEN DALE L	425-5595 +2
264	GAITAN GENARO	426-6393 +2
	HOWARD PHILLIP H	426-8064 +2
	PRADO ANA	426-9052 +2
265	APARTMENTS	
	AGUIRRE M	425-0697 +2
	CONNER M	420-2870 +2
	DENTON R A	426-5010 +2
	FRENCH DENNIS M	422-2245 +2
	HOLMAN J G	422-7607 +2
	MARTINEZ LUIS R	426-0506 +2
	MCKINNEY D C	427-1843 +2
265		
268	BARTLETT M L	422-5719 +2
	DUNN A D	425-9984 9
274	SIMARD PAUL O	422-1945
277	FRITCHER JAS F	422-7902
	JIMS GUN SHOP	422-7902
281	LANE F B	420-3338
282	HILDAHL GEORGE E	420-1950 +2
	WARREN MICHAEL A	420-1950 7
283	DWIGHT GOVE AGCY	426-3200
	GOVE DWIGHT AGCY	426-3200
284	XXXX	00
286	DEWEYS GARAGE	427-8922 1
	NAUGEN DUANE S	427-8922 +2
287	ROCKWELL FRANK A	425-4731 +2
289	XXXX	00
310	HENNEY APTS	
16	CLARK ROBT A	427-3416 8
1	CORKRUM O L	420-0327 1
3	LLANOS LEONA	420-2282 9
10	MURRAY J F	426-7635 8
6	PETERS DORIS E	426-7569 D
11	SCOTT PAUL K	422-1550 6
	THORELL JOHN R	420-2426 +2
9	VINEYARD CLYDE V	420-7675 D
	WIDMAN G	422-3589 1
310		
311	HUDSON E F	425-2839 +2
313	XXXX	00
315	JOHNSTON J A	422-5431 4
316	CARMAN E S	420-1251 3
	WYMORE R W	426-6486 7
317	MILLARD J B	422-5946
	ONOFRIO E R	427-2246 1
318	APARTMENTS	
	BEAUCHAMP J D	422-3005 +2
5	GUILLEMETTE LOUIS	426-8067 8
	PINNEY J R	425-4095 +2
	SONES ESTHER	422-2128 +2
	STPIERRE W H	422-1418 +2
7	WEHKING EARL	427-D796
318		
319	ASHOOK PHIL W	427-8676 3
	ASHOOK ROSE L	427-8676 3
320	APARTMENTS	
5	BAKER VIOLA F	420-1569
1	BROOKS M H	426-4055 6
	COLE N S	426-2236 D
	KOMINSKI ADOLPH	425-7056 +2
4	MYERS J L	420-7622 4
3	PURVIS GUILA H	425-D413 8
320		
321	ADAMS S M	426-2207 7
323	BRORBY ALVIN O	422-3320
325	XXXX	00
329	GOMEZ BERTA L	426-3398 +2
330	ARGENBRIGHT FELICA	426-9039 +2
332	XXXX	00
333	OGILVIE FLOYD E JR	426-6731 4
334	APARTMENTS	
	ALSIP V P	427-5567 9
6	BAKER WM W	425-5649 8
4	CHESSMORE DAVID T	427-9998 8
	JANTZ G	427-5467 +2
71	JONES CHAS R	426-6543 4
16	KWIATKOWSKI FRANK	420-2304 9
	ROBNETT RAYMOND A	420-5143 1
11	SIMPSON FREDERICK	427-8155 0
334		
335	LUCKINBILL C O	422-1478
336	CUMMINGS L A	426-2278 1
	KENEFICK M	426-5199 4
	PHILLIPS RAYMOND	426-7685 +2
	POTTS L	422-0996 1
340	KUSHENBACH ALFRED	426-7893
	LOVETERE J A	420-3972 8
341	FOX JESSE B	422-1460
344	MAGNAN PHILIP A	427-8789 1
345	BRYAN W M	422-5821
350	TALNADOE JAS R	420-9484 7
354	TALNADOE STEPHEN	422-4159
357	CHULA VSTA WMNS CLB	422-9706
363	XXXX	00
364	BLACK ALLENE	422-4452
367	XXXX	00
368	XXXX	00
370	FLORES RICARDO JR	420-3284 +2
371	KONDRASHOFF EUGENE	422-7806
372	MARTINEZ ROBERTO S	427-6823 1
	PEECHNER SCOTT A	425-4015 +2
374	SLINKARD WM C	422-2124
375	BROWSON MARY	426-9062 1
	EVITTS MARK C	420-3550 0
	MATTHEWS LOUISE	426-9062 1
379	KEMERY WM E PHD DO	422-0402 4
385	XXXX	00
386	BENGUAT RAQUEL M	427-8698
390	AVERY JOHN R	420-7249 1
	LUGINBUEHL GEO A	420-4705 8
394	ALVAREZ ROLFF R	425-8804 1
	BORGER FRANK	425-5962 +2
	MARTIN DELCAMPO R	420-8782 +2
	SALIDO ARTURO W	426-7291 1
399	VANDERVEEN T J	422-1785
402	RAGADOS PRISCILLA	425-7007 +2
404	PALACIOS ARTURO F	426-2792 D
406	XXXX	00
408	HELM JOHN	420-1837 +2
410	XXXX	00
411	LAESKE FRED P	422-2533 9
	MARISCAL HECTOR L	420-D183 +2

G		9201D CONT
412	XXXX	00
414	SEARBY R I	426-5418
418	CA FINANCIAL SERVS	425-8322 +2
	MCPHILLIPS RANDALL	425-9187 +2
418	WILSON P L	427-3442 9
419	BOSCOSKY ROBT	427-8741
420	XXXX	00
422	YANKULOV ANTHONY	426-1686 +2
423	RUBALCAVA CONSUELO	425-9892 1
424	APARTMENTS	
	ENGLISH P	422-5437 9
	HOLT ANDREW E	426-2235 1
	MELSER R G	427-9976 9
	REED DAVID O	420-9369 +2
F	MARQUEZ RUBEN R	426-6727 3
424		
427	WOOD ARLEN O	420-9286
431	FOLEY D M	420-2001
435	HEIZER BERNITINE	420-1302 +2
	VENNEL FRANK	420-1302 +2
439½	HILLIDGE S S	426-3360 D
447	RULLINS D D	422-2517
453	SANMARTIN ANGELA	422-2232 4
459	XXXX	00
463	XXXX	00
473	MACK BEN L	422-0946
479	ALSIP DAVID M	420-2896
481	ESTEVES JOSE	426-6566 1
485	XXXX	00
489	PAPICH JACK	422-4972
503	PIERSON B M	420-D742 4
507	KUBIE WALTER	420-3316
511	XXXX	00
515	XXXX	00
519	MALDONADO R	427-4404 0
521	GARCIA MARY	426-6812 9
	PAINE JOSEPH	426-3969 +2
525	XXXX	00
529	ARCE GILBERT	420-1267 +2
535	FUNK JOHN A	427-3061
540	VISTA SQ ELEM SCHL	422-8374
541	GOMEZ VICTOR	425-9297 1
541½	FIELDS PATRICIA A	420-3826 +2
543	DELECN HECTOR S	420-0689 1
547	XXXX	00
551	ABLES RANDY	427-0611 1
	ESCOBEDO V R	425-4883 D
	LOPEZ ALFREDO P	425-2321 D
	SULLIVAN S	426-4621 9
553	CHAVEZ JOHN	425-5255 +2
	MORGAN JERRY W	425-8162 +2
556	ODELL RONALD H	426-4216 +2
560	MARTINEZ HECTOR R	426-9864 1
561	JOHNSON JULIA K	425-6733 +2
564	EARLEY GRACE	427-5063 +2
	THOMAS JOHN W	426-3425 +2
565	FRYER R D	420-8569 +2
	JAMES PAUL G	426-2093 +2
568	GONZALEZ VICTOR	422-2581
571	FORD J P	420-9972 8
	FORD J P	420-2528
580	GLOFIAS APTS	
	CARMICHAEL ERNIE	427-8664 +2
	CROCKETT MARY M	420-6510 +2
	HAUN F L	422-5903 1
	JAMES JOHN H	425-6278 +2
3	LEWIS JESSIE L	425-4608 1
11	OJEDA CARLOS	427-9765 9
	REED STEVEN W	426-4297 +2
15	WHEAT GROVER C	427-4692 0
588		
581	GARCIA JOSE L	426-8905 1
590	AMERICH TUDOR PROJCT	425-1821 1
	BRYAN PUBLICATIONS	425-1887 1
	CUSTUMER FLW UP SVC	427-1787 9
	LATIN INTERNATNL	425-1887 1
	SANCHEZ RUBEN D	422-4077 +2
	SANCHEZ RUBEN D	422-6006 +2
	SIERRA DATA INTL	425-5149 +2
	SOUTH SHORE ENGINRG	420-5555 +2
	TIEMPO MARKETING	425-5067 +2
595	XXXX	00
605	HEMENWAY LEO	427-8835 7
610	APARTMENTS	
	FINGOWSKI LYDIA	422-4562 +2
	KLEINMAN N B	422-7381 +2
	MARTINEZ REDRC D	425-7197 +2
23	MITCHELL MABEL E	425-0919 8
	OFPOFF WALTER	422-4519 +2
	SHAW GUY	422-0542 +2
25	STORM A	427-1654 4
	STRASSER FRED F	422-0480 +2
	THORNBERG ROBERT	427-9268 +2
610		
616	SOUTH BAY TOWERS	
	AGUILAR ESTHER R	425-7250 1
	ARMSTRONG DENNIS W	426-3874 1
4	BAKER E I	422-1296 1
	BARTON PHILLIPS E	422-6950 1
83	BAUKOL DONALD R	426-2668 6
	BELCHER AARON	422-4713
119	BLOOMFIELD PHILIP	425-3827 1
	BROWNLEE L M	420-0692 +2
	CERONE D W	425-7864 1
111	CLARY B J	427-0353 9
	COFE KEVIN D	426-6902 +2
	CRAIN J C	422-8559 D
64	CURTIS LAWRENCE E	420-5515 1
25	DAMSEL SOPHIA	422-0307 9
106	DART LYSTON C	426-5554 1
	DICKERHOFF C B	420-3817 1
	DUNLOR A J	425-8749 +2
	EDWARDS JOHN S	426-0670 +2
	EGGLESTON E A	427-2793 0
27	EGGLESTON WILSON	427-2724 D
6E	ELHARD JOHN H	426-9457 1
34	FAULKNER JOHN	427-1871 0
	FELDT JOHN H	425-6302 +2
16	FIELDER BOBBY , JR	426-5612 D
	FOUNTAIN JOSEPH J	426-8844 +2
	FREEMAN CRYSTAL	422-7800 +2
	FRISCH B J	425-9838 +2
61	GARDNER MELISSA	426-4507
	GUARINO LEO	427-7839
	HAMILTON DARREL D	425-7837 +2
96	HARDIMAN M MRS	427-2352 1
36	HICKS ORIN W	427-4288 6
71	HILL MARK R	427-3682 1
102	HOLDER I V	427-D192 8
62	HOLDER RUSSELL S	425-2127 6
87	HOLLIS K L	420-3694 0
52	HOLMES BOOBY D	427-8627 3
40	HOOK JAMES A JR	426-9013 1
05	HUNTER GEO L	426-7958 6
5	JACKSON E L	426-1276 8
	JOHNSON ALEX	427-4789 1
22	JOHNSTON JOHN F	426-9279 6
	KIENLEN ARTHUR	426-3572 +2
2	KIRSCHT JOHN A	426-7433 6
118	LIND PAUL S	426-2528 D
	LOOMIS HARRISON R	427-2075 +2
65	LOVINS RICHARD	422-1661 D
	LUALLEN D F	422-0054 1
17	MENGES DON W	420-0853 9
	NELSON JOHN K	427-5376 +2
130	PATTERSON CAROLYN	426-72 3 9
	PETERSON S	420-5476 1
69	POGAS VIRGINIA M	422-4545 D
49	PROUTY MICHAEL L	422-3545 1
	RESNICK A G	422-2354 0
84	RODRIGUEZ LUISA	425-1725 6
	RUSHEED EMANUEL	422-3723 +2
24	SCHNELL CHAS L	420-5265
101	SELGO O A	426-0757 1
	SIMPSON L	425-8 51 +2
77	SKALLET W S	427-9473 1
50	SOUTH BAY TOWERS	427-5533

© EXCEPT AS AUTHORIZED IN WRITING BY HAINES & CO., INC.

Target Street	Cross Street	Source
✔	-	Haines Criss-Cross Directory

G ST 1982



G		92010 CONT	
94	STAUBER SHELDON	422-1509	1
35	STEINBACH WM	422-2432	6
	TATTLER ANTHONY	427-4153	+2
50	TEEL DONALD M	425-6274	1
40	THOMPSON JACQUELIN	426-0507	9
73	THOMPSON R	425-4233	1
	ULLE KRIS	425-5191	+2
33	VRBANCIC JOS B	426-7759	3
	WALTON JULES	427-8686	1
	WEEKS KIM D	426-2439	+2
	WOLD LIONEL K	422-2129	+2
	WOODBURN DELMER E	422-4640	+2
110	YASMINEH JOHN	427-8452	1
	YEAKEL CARL E	425-9701	+2
616			
628	XXXX	00	
629	XXXX	00	
633	XXXX	00	
635	ALLEN R D	422-2954	4
644	XXXX	00	
649	ELY EDW H	426-7868	6
651	SUMNER CLINT G SR	422-5633	6
667	XXXX	00	
677	BROADWAY TRLR PK		
	ACKERMAN C	425-8497	+2
34	ALLEN E	422-7679	5
33	ANDERSON GEO K	422-7224	
98	ANDERSON W A	422-7689	
129	ASHCRAFT M T	426-4109	1
3	BAKER M J	420-1460	0
94	BARCLAY THEO M	420-9032	
32	BARKER T L	420-3998	8
12	BEEBE S E	426-5356	7
152	BEHRENS RAYMOND L	427-5919	7
158	BELL T ROTH	422-1805	
188	BENDER EDMUND F	422-6052	6
59	BESTINY JOS	427-3449	
67	BOTTS JOHN B	420-3573	
	BOTTS ROBT J	420-5565	8
40	BROADWAY TRLR PARK	422-0242	
96	BRODERICK MARY	426-6479	7
149	BRUNER RUTH L	422-3214	7
27	BUSCHUR LAURA	426-6589	3
58	CADDICK H	422-8187	9
E5	CHENOWETH R W	422-6662	3
	CHERRIS A R	425-0744	+2
	CHRISTENSEN MARTIN	422-8819	1
130	COOK ROLINE	422-1289	
79	CRAIG CHARLOTTE S	422-3840	9
72	CREWS JOHN W	420-3494	
49	CSILLAG MURIEL	420-9284	
156	DARLON DAVID	422-6869	
44	DAVID MAUDE L	420-0415	1
14	DIDOMIZIO DANIEL	422-3070	9
136	DOKE RICHARD	420-7997	9
187	DOUGHERTY FERN MRS	422-6467	
47	DOYLE R	422-4554	0
146	DUNGAN K W	425-5567	1
107	DUNKER N M	427-8604	9
60	DUNTON WALLACE W	422-2175	
53	DURHAM HENRY C SR	427-9893	
	ESTES M	425-3797	+2
7	FUHRMAN ALICE L	422-6262	
190	GIUSTI THOS P	426-7097	1
73	GLENN CHAS D	425-9864	9
135	GLENN L	427-5541	0
171	GOEPPER E H	427-0766	
90	GOERSS FRITZ	422-5822	
	GRAY CARL G	426-3895	+2
115	GREEN FLOYD I	422-9353	4
181	GREEN JERRY L	422-0467	
81	GREER MARVIN C	425-8538	8
74	GUNTLE M E	420-8151	
13	HALL STANLEY USN	420-5106	8
176	HALL SYDNEY	422-2569	
	HARBECK A A	426-8452	8
172	HASELMIRE JOS M	420-5813	
35	HATCHER CHARLIE L	422-0203	
10	HENDERSON ROBT L	420-4601	
183	HIME PAUL E	425-7412	0
22	HINKLE DARYL B	427-1475	
64	HOBBS GEO E	427-4008	5
84	HORST PAUL	426-4237	4
31	HUFFMAN GUY V	420-0549	
1	HUNT E B	426-5476	
108	HUTCHISON JOHN G	420-8896	1
48	INCOME TAX&BNSS SR	425-7936	0
	INMAN LILLIAN P	425-0242	+2
151	JOHNSON G G	422-2344	
148	JOHNSON ROBERT L	427-3195	0
119	JONES LAMAR R	427-1159	8
122	KELLOGG ROY F	422-5575	
97	KELLOGG STEARNS W	420-5693	
62	KELLY JAS P	426-9923	
28	KELLY THOMAS	427-6896	9
180	KINCAID F I	422-2827	6
154	KIRCHMAIER WM E	420-0888	
52	KIRKPATRICK WALTER	427-1018	
165	KISBERT CHAS A	420-6769	
75	LEYDEN WALTER T	420-3269	
129	LLOYD H D T	425-7936	0
95	LUND ELLIS M	420-1920	
89	MAGERS BEN R	420-0494	
5	MANGLESS DONALD R	422-9035	5
123	MARNETTE OTTO H	425-1149	8
100	MARSH ROBT L	422-1584	7
84	MARTLEY EARL H	420-3368	
64	MATHEWS R P	420-0531	
110	MCCAMON FRANK	422-2328	5
12	MCKINLEY THOS T MRS	420-8349	
102	MEIER R E	422-7419	
14	MENDENHALL L F	427-3884	
17	MERGEN S M	420-4691	4
71	MESTER CHAS H	422-3047	
145	MILTON FRANCIS J	422-2921	3
45	MITCHELL ROBT H	422-2217	
6	MOE C O	420-1041	
161	MORRIS WM N	422-7927	
41	MUNTER WILFRED CDR	422-0293	8
19	NADEAU A	420-3886	
186	NEWMAN L L	427-3734	6
30	NICKLES CLARENCE	422-6213	1
2	OGDEN HOWARD	420-0442	
68	PATTERSON EDMUND L	426-1322	
140	PELLERITO M L	427-4456	0
178	PERRY G H	420-2646	
162	PILLA PAUL J	422-2598	6
4	POHL AUSTIN F	427-9254	3
127	POLLARD D H	427-0334	
189	PORTER ALFRED L	420-3793	
23	PRICE WALKER W	420-5844	
	RARICK MARGARET L	425-7936	0
143	RICHARDS REX M	425-1624	1
128	RORABECK R S	422-0667	
25	SAUNDERS LESLIE	425-6971	1
170	SCHREIBER M L	420-6354	
143	SEDILLO BETTA L	422-8072	8
	SIMON RALPH E	426-7149	+2
50	SISEMORE NAOMI R	420-4320	
166	SMULLIN F L	427-5243	9
15	STAJMARO BARTOL MRS	420-9214	
92	STOAKES FREDERICK	425-6657	9
168	STOUDT M U	420-3543	4
192	SUMNER V	420-0660	4
40	TERRYS MOBILE PARK	422-0242	
83	THOE IRVIN L	426-8906	6
138	THOMAS AVIS	420-2719	1
131	THOMAS WENDELL C	427-4296	
99	THORNTON C O	427-1371	
132	TRAGO RICHARD C	422-7989	
	UMER J P	427-3721	1
117	VALENCIA WALTER S	427-2931	4
169	VALITON H D	427-6339	1
39	VANZANTE M M	428-5614	
20	VESTAL LYMETTE B	422-1071	
	VINCENT MARGIE L	427-6550	+2
113	WALKER ERVIN G	422-0872	5

G		92010 CONT	
104	WEBBER S M	422-6580	
157	WEBSTER LUCILLE	420-4840	
174	WIDEN ALBERTA E	420-0316	8
173	WILHELMI W D	427-3867	
	WILLIAMS BERNARD	425-4722	1
91	WILLIAMS FORREST C	422-8539	6
	WILLIAMS JARRET R	427-9349	
116	WILLIAMS M N	422-1709	5
	WILSON L M	425-7639	1
85	WOLL D J	427-1453	
	YAGEL GEO C JR	422-3411	+2
24	YELLAND WM J	426-6019	3
677			
691	XXXX	00	
704	TUITE MARY R	420-4370	+2
	WILHARMS THOMAS L	420-3277	1
716	LARAGIONE DOMINIC E	426-5491	+2
724	BERNSTEIN G A	420-7902	1
A	KASTLUNGER JOHN A	420-7902	+2
731	CABRILLO MBL LDG		
28D	ALDER EMMA	420-3117	3
	BLACKWOOD B J	427-6513	+2
10A	BOARD WM D	425-6899	9
5B	BUXTON FRED H	420-2621	
7A	CABRILLO MOBILE LDG	422-0245	
	CAMPBELL R H 2D	420-0617	1
13E	CAREY B H	427-1724	0
16B	CARR JAS	426-7980	0
20D	CLAY MARSHALL L	425-6455	1
4C	CONROE GERALD F	427-4108	5
17C	CORBRAN C A	420-2302	5
20B	CUNARD EDWARD	420-2653	1
1B	DAVIS JOS A	422-5157	
76C	DAWSON JOE	420-1587	
8E	DEHAVEN BARBARA R	425-1820	1
	DEMPSEY RAYMOND	426-2796	+2
6A	DIETZ WINN	420-7758	0
6B	DONOHUE M E	420-0069	
18B	DOUGLASS MAURICE	427-1545	6
22A	DROZE S L	426-1995	9
	DUGO LEWIS G	420-6193	+2
3C	ENDLICH JOS	426-9715	7
	ESPINOSA JOSE J	420-4274	+2
16D	FARNSWORTH GLADYS	422-4948	8
3D	FITZGERALD E L	426-6242	8
22B	FUGATE HARRY R	427-8768	5
27A	GATES F M	426-0408	0
3E	GEALER F A	426-4773	1
	GERBASIO MARGARET	425-9572	+2
10B	GRANTHAM FLORENCE	427-2545	5
10B	GRANTHAM PAUL	427-2545	5
12D	HANKS JOE	427-9524	6
10D	HARRIS ALBERT G	427-9494	6
5C	HARTMAN MARION MRS	427-5338	7
7D	HAY HAROLD B	427-8972	9
15E	HILL ALBERT W	426-4627	3
24A	HOLMES MARETTA F	422-3268	9
	HOUGH C M	425-6987	+2
24B	HUME WM C	422-6071	
2B	INMAN G B	427-9722	5
23A	JACKSON WM R	426-0784	3
12A	JONES DOROTHY LEE	420-6042	9
9D	JONES H A	420-6168	1
1E	JORGENSON VERNON	427-4975	6
5E	KELLER MARGARET	420-2670	
4E	KIKER EVELYN L	425-9457	1
14D	KINNE C	422-4191	1
4B	LAUGHLIN W F	422-0443	0
1C	LAVIGNE VICTOR J	427-1854	6
14C	LESMINSKI JOS A	425-9909	1
	LEWIS MICHAEL	427-7152	+2
13D	LONG CLINTON	422-2760	9
2C	MEYER SARA	420-9180	
14E	MILLER HERMAN H	427-7555	8
14A	MONEYPENNY ERIC	426-1666	1
9D	MOULTON EDW H	422-8681	
12C	MYERS H B	420-6782	7
8C	NOACK ALICE	422-3131	3
12E	NOBLE ROBERTA S	426-4597	7
7A	ORTUSE NATHAN	427-8145	1
	ORTUSO PATSY	420-0479	+2
4A	PARK ADA M	422-9058	8
20A	PARKINSON MILTON E	422-2449	
	POST B	427-7857	+2
2D	PRICE NAIDA	425-0369	1
19C	QUINN WM R	420-9127	
16A	RATH EDWARD	422-8781	9
	ROWANIUK NICK	426-8957	1
9A	RYAN G	427-0708	6
15B	SHANTEK STEPHEN P	425-7610	0
25D	STEELE HOWARD A	420-5843	
8A	STEIGER HENRY G	422-2555	7
5D	SUTTER V	422-8940	9
	TURNER LINDA	426-8076	+2
23B	VANCUYK B	426-2035	1
26C	WATSON R L	427-5315	6
3C	WENTWORTH D H	422-7617	1
18C	WENTWORTH FRED E	427-5270	1
12B	WENTWORTH KAREN A	426-2648	9
7A	WHITE STEWART M	420-7434	
6B	WHITNEY ESTHER G	425-0125	8
731			
736	BORGE JAS A	426-8442	1
	COREANO ROSENDO	422-3322	+2
	SANTANA RAMON	425-5246	+2
A	WISSER J H	425-2528	5
	• 27 BUS 617 RES 121 NEW		

G WEST 92101 SAN DIEGO

110	CAMPBELL HARVEY R	231-1027	0
211	J A A D INC	236-0811	8
241	TILTON ROGER FILMS	233-6513	8
301	DOUBLE R MEATS	234-8010	1
	POLAR GOLF SHOP	233-3186	3
	PRESTO FOOD PRDCTS	233-3186	+2
335	DANN A EAGO	239-5488	
401	XXXX	00	
415	XXXX	00	
505	SD MARINE HARDWARE	231-8334	7
	SD MARINE HARDWARE	234-5877	7
550	XXXX	00	
803	XXXX	00	
1255	CROWLEY CONSTRUCTRS	239-8752	9
1277	XXXX	00	
1355	LAIS T RSTRNTBLNGE	234-1584	5
	TOM LAIS RESTAURANT	234-1584	
	• 11 BUS 6 RES 1 NEW		

G AV 92118 CORONADO

121	PARKER RUDOLPH M	435-6974	
122	RAMAY JACK L	435-3086	
124	OLIVER VINCENT	435-3042	1
125	XXXX	00	
132	HOPEWELL R S CDR	437-8736	1
133	XXXX	00	
135	GRIMM W F APPLC	435-0703	9
	GRIMM W F CAPT	435-5477	4
140	PURPON TECHI	437-8791	1
145	DESIGNER LTD	435-9256	+2
	ENGLISH GENE R	435-8271	0
	ENGLISH GENE R	435-3385	0
145½	BOLDING ROBT D	435-3027	0
146	XXXX	00	
150	XXXX	00	
155	OWEN BILL	435-8920	
	OWEN WM D CAPT	435-8920	
160	SWEET RALPH L	435-4652	
161	XXXX	00	
164	ROGERS W H CAPT	435-3439	6
165	KLEEHAMMER THOMAS	437-8074	1
165½	WRIGHT R J	437-9660	1
175	WARDERS GLENN L	435-6498	
209	TAYLOR A	435-1924	0
218	MARKLEY RALPH B	435-3658	

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory


G ST 1979

G 92010 CHULA VISTA

NO	#		
		FRASERS BOILER SERV	426-7780+9
14		ACKERMAN DICK	427-3829 1
15		MORGAN LEE J	422-5951
30		GODENIUS WALTER E	422-1930 0
36		XXXX	00
39		XXXX	00
42		HILDEBRAND ERNEST	420-3626 3
45		XXXX	00
48		SHARP MENDEL	420-2414 4
		SHARP S C	420-2414
52		LONG FRANK M	422-5408 6
		LONG FRANK M-TEEN	422-7831 6
55		XXXX	00
60		FLORES MIGUEL A	426-5376 5
66		HONDIUS PETER	422-2277
70		STANCZAK FRANK JR	420-6731 8
71		REDDIN HAROLD L	420-8152 6
78		WILLIAMS ARTIE	420-6597 8
83		JOHNSON ROBT G MRS	420-8995 0
84		JENKINS SIDNEY R	422-5557
87		CHASE PALMER S	427-9986 8
90		MURRAY FRANK E	420-1792
93		STONE B C	422-8838 4
102		FIRKINS WM G-DC	427-6966 3
108		GARCIA TEODULO G	427-0028 7
111		DALE ROBT G	422-6217
115		LAIRD HAROLD L	422-6039
121		ZAPPONE CARMEN	427-3194
130		HULST WARREN J	427-7478+9
134		XXXX	00
135		PHILLIPS IRENE	422-7494
141		ALLEN ERVIN	422-3797
146		DEERING R W	420-6445 1
147		COBEN CHAS-SR LCDR	422-7648 1
155		DUBERG JAS S	427-6160+9
159		XXXX	00
161		LIMBACH CASPER A	422-6309
163		SUTTON THOS W	422-6296
164		MATTSON MATT W	422-2376
173		XXXX	00
174		HILL JAS E	420-6122 7
177		CURETON S W	422-5625 0
181		HALTMEYER F H	422-1885
182		XXXX	00
186		BARNES LEO	422-6768
		SOTO RAFAEL Y	422-8701+9
194		DIXON CARMEN C	427-0173
195		TROTTER RONALD G	420-9688 8
197		LADD J	425-0689 8
198		MILTON SAML W	427-6519 6
202		FLORES JOSE M	422-4603
203		JOHANSEN A	425-5747+9
207		AMOS E H	422-6038
210		LADD L E	422-6456
215		PARKS JUANA L	420-7281+9
217		DAMM L W	426-2755 0

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1979



G		92010 CONT
222	LECHATEAU APTS	
216	ADAMS HESTON D	427–3026 4
302	ALLEN W H	420–3079 0
	BENGE E R	426–0273+9
112G	BODEN G	426–9840+9
317	BUTLER EDITH C	426–1907 1
203	CAREY SAML A	420–3566 2
106	CLOSE EDWIN C	422–2435 5
306	CUNARD I C	426–1167 4
209	DIXON D V	427–0931 3
	DORFMAN JACK	426–0570+9
	FLOYD R A MAJ	422–4807+9
102	GALVAS JOHN J	427–0813
	GAUSDEN HATTABELLE	422–6909+9
113	HINTON W E	420–3296 4
103	JANTZ G	427–5467 5
206	JONES M	426–6513 6
116	KOOB O E	427–2229 6
115•	LECHATEAU APARTMNTS	422–4655
307	LOCKWOOD C M	427–1204 4
	MACE CHERYL A	426–8296+9
318	MCCORMICK CLAY	422–9187 5
212	MILAN MICHAEL A	427–8247 7
	MINNICK J H–MRS	420–4425 8
305	MYERS ARTHUR	426–2858 6
51	PANKHURST RICHARD	425–1989+9
316	PEITON J C	427–2868
301	PIRIE M C	425–4801 7
315	PRAY M L	420–6515
109	QUEEN MILDRED–MRS	427–2397 6
204	RULIK W	420–4512 4
214	SCHILLING FRANK–MRS	427–0911 3
314	SEAMAN H K	420–0309 3
108	SHAW MABEL A	426–0224
	SHOEMAKE TRUMAN	427–6629 8
208	SNYDER WILBUR A	427–8061 5
	SWANSON M F	427–0600+9
313	WILCOX LAWRENCE	420–2663
311	WOERNER ORMAND	425–2544 5
101	WOOD G A	427–7904 4
222		
223	FASTH M	427–3209 5
	RICHARDSON GEORGE	422–0889+9
B	MERCER STANLEY N	420–9641+9
227	FORREST WALTER W	422–1023
227½	FORREST E L	422–3424 0
229	WOODEND MYRTLE M	422–2640
233	DOEGE DOUGLAS W	425–3996 5
239	BRIGGS EDW L	425–3330 6
	MCDONALD DOUGLAS D	425–0959+9
240	THOMAS J M	422–4254
241	BAKER ROBT M	426–7643+9
B	PRADO ANA	426–9052 5
244	LILLEYMAN A I	420–3572 5
244½	NICKESON J	422–3247+9
246	ARNEAL M	420–5927 6
248	CUNNINGHAM S F	422–2212 5
250	HENDEL H S	427–8795+9
250½	DAVIS JOSEPHINE	420–8639 2
252	HAIGHT M A	425–4766+9
	KAGARICE STEPHEN J	425–0491 8
	WALKE S E	426–3916 4
264	GANFIELD WILLIAM J	420–4374+9
	MAYNE KENT	426–5874+9
	NEUBERT L D	420–4208 8
268	BARTLETT M L	422–5719 5
	BROWN BETTY A	426–6360+9
	DARLING L W	422–1984+9
	DUNN A D	425–9984+9
274	SIMARD PAUL O	422–1945
277	FRITCHER JAS F	422–7902
•	JIMS GUN SHOP	422–7902 0
281	LANE F B	420–3338 0
282	WARREN MICHAEL A	420–1950 7
283•	DWIGHT GOVE AGCY	428–3200 1
•	GOVE DWIGHT AGCY	426–3200 1
284	XXXX	00
285•	KANTRUDS GARAGE	427–8922 7
287•	BROOKS TRUMAN RLTRS	426–9331 8
289•	BROWSE AROUND THE	420–8091 7
310	HENNEY APTS	
	CLARK ROBT A	427–3416 8
17	DANIELS ANDREA MISS	422–3589
14	KNOX A L	426–7524 7
	LLANOS LEONA	420–2282+9
15	LONG V B	420–1553 5
	MURRAY J F	426–7635 8
11	SCOTT PAUL K	422–1550 6
9	SORENSON MINA	422–2336
16	WALLACE W D MRS	427–6418
310		
311	GEHRER CATHERINE M	422–3636+9
313	XXXX	00
315	JOHNSTON J A	422–5431 4
316	CARMAN E S	420–1251 3
	WYMORE R W	426–8488 7
317	MILLARD J B	422–5946
318	APARTMENTS	
	GUILLEMETTE LOUIS	426–8087 8
	MACKLEY JAS W	422–3747 8
	MCKENDRY STEWART J	427–4403 8
6	MOLINA O–SISTER	426–5907 7
8	MOORE SARA E	425–4971 5
3	SWAIN JUDY H	422–8080 6
7	WEHKING EARL	427–0796 1
15	WHITTAKER MYRTLE O	427–2767 4
318		
319	ASHOOK PHIL W	427–8676 3
	ASHOOK ROSE L–MRS	427–8676 3
320	APARTMENTS	
5	BAKER VIOLA F MRS	420–1569
1	BROOKS M H	426–4055 6
	BRYAN ORVAL L	427–9564+9
	GRIFFIN MICHAEL D	420–2901+9
4	MYERS J L	420–7822 4
	POPELKA M W	425–3887 8
	PURVIS GUILA H	425–0113 8
6	SHELTON BYRDA MRS	420–2287
320		
321	ADAMS JOS H	426–2207 7
323	BRORBY ALVIN O	422–3320
325	XXXX	00
329	BEGO MICHAEL W	425–6177+9
	BUCK M W	422–0275
	KALEY EDW E	426–7796 7
330	LANDAU O B	422–4741
332	XXXX	00
333	OGILVIE FLOYD E JR	426–6731 4
334	APARTMENTS	
	ALSIP V P	427–5567+9
	BAKER WM W	425–5649 8
	CHESSMORE DAVID T	427–9998 8
	FLOWERS E P	426–4367 8
	HIGGINS ROBT L	420–5244 8
71	JONES CHAS R	426–6543 4
	KWIATKOWSKI FRANK	420–2804+9
	PARR CHAS V	422–6539+9
334		
335	LUCKINBILL C O	422–1478 0
336	BLACK JAS N	420–4280
	KENEFICK M	426–5199 4
	TERRASI MARGARITA	420–3187 3
340	KUSHENBACH ALFRED	426–7893 1
	LONG THELMA	427–0884 4
	LOVETERE J A	420–3972 8

G		92010 CONT
341	FOX JESSE B	422–1460
344	GIRE GORDON O	420–0972 3
345	BRYAN W M	422–5821
350	TALNADGE JAS R	420–9484 7
354	TALNADGE STEPHEN	422–4159
357•	CHULA VSTA WMNS CLB	422–9706
363	HENRY J O MRS	420–6163
364	BLACK L E	422–4452
367	HUBBERT GEO N	422–2235
368	VANCLEAVE DALE A	427–4547 7
370	XXXX	00
371	KONDRASHOFF EUGENE	422–7806
372	LOPEZ WETTANAKASAE	427–8412+9
374	SLINKARD WM C	422–2124
375	SCHLOTTHAUER ETHEL	425–8544+9
	TULLIS B W	425–6286 8
379	KEMERY WM E–PHD DD	422–0402 4
385	BROCKWAY CHARLES E	422–0355+9
386	BENGUIAT RAQUEL M	427–8698 1
390	LUGINBUEHL GEO A	420–4705 8
	ROFFE JEANIE	427–1048+9
394	APARTMENTS	
	CARLSON ROY	426–4186+9
	REYNOLDS JACQUELYN	426–6631+9
	SIMMONS WYNDELL D	422–6305+9
	WATSON DAVID L	426–9152+9
	WHITT TIM	427–3812+9
394		
399	VANDERVEEN T J	422–1785
402	SCHAMBERGER THOS	426–6284 2
404	CLARK MELVIN M	420–1561 8
406	NEAL C M	427–3588 4
408	ALBREKTSEN EDWARD	422–6962+9
411	LAESKE FRED P	422–2933+9
412	SMITH RICHARD ST	426–9830+9
414	SPARBY R I	426–5418 1
416	SMITH JAS E	427–8203 8
418	WILSON P L	427–3442+9
419	BOSCOSKY ROBT	427–8741 2
420	XXXX	00
422	LUTU JOHN A	420–5652+9
423	APARTMENTS	
	HUNT D	426–8418+9
	MEANS LOURDES L	426–5717+9
	MORENO FRANCISCO G	426–2976+9
	RIDDLE VICKI	422–5683+9
	ROSS K	426–8418+9
	VITCO ALBERT D JR	422–1606 6
423		
424	ENGLISH P	422–5437+9
	MELSER R G	427–9926+9
•	VISTA SO ARARTMENTS	420–0188 4
F	MARQUEZ RUBEN R	426–6727 3
427	WOOD ARLEN O	420–9286
431	FOLEY D M	420–2001
435	XXXX	00
439•	CORRAL ISAURA T	420–3306+9
447	PULLINS D O	422–2917
453	BLOCKER MARY	425–9433+9
	SANMARTIN ANGELA	422–2232 4
459	XXXX	00
463	XXXX	00
473	MACK BEN L	422–0946
479	ALSIP DAVID M	420–2896
485	XXXX	00
489	PAPICH JACK	422–4972
503	PIERSON B M	420–0742 4
507	KUBIE WALTER	420–3316
511	XXXX	00
515	XXXX	00
519	XXXX	00
521	GARCIA MARY	426–6812+9
	INGRAM PAUL B	426–7616 7
	NERIA ROSA	426–8613+9
	PEREZ GUILLERMO C	426–0438 8
525	XXXX	00
529	XXXX	00
535	FUNK JOHN A	427–3061
540•	VISTA SO ELEM SCHL	422–8374 0
541½	FIELDS PATRICIA A	420–3826 5
547	XXXX	00
551	SULLIVAN C	426–4621+9
553	ACOSTA NORMA	422–6246 8
	CURDIE DWAYNE D	420–5677+9
	FARFAN DOLORES	422–5149 8
556	XXXX	00
560	XXXX	00
561	CURDIE ELLA S	427–1294 7
	DEAN JUDY J	426–6116+9
	KINZER DANL D	422–5921 8
564	WEBER MICHAEL	426–8513+9
565	ESPINOZA FRANCISCA	426–8731+9
	LEDBETTER FRANK E	427–6473+9
568	GONZALEZ VICTOR	422–2581
571	FORD J P	420–2528
	FORD J P	420–9972 8
580	GLORIAS APTS	
	ASAR ELENA	425–8510+9
	CRUZ ROSE	427–7164+9
	DEMPSEY JOHN J	425–9978+9
	DORST ARTHUR	420–8206+9
	HERNANDEZ J S	422–3844+9
	OJEDA CARLOS	427–9765+9
	SENZAMICI JAS	427–8830+9
	SPENCER GERTRUDE E	427–8302+9
	TREVINO JOHN	427–8535+9
	VIRUEGAS DIANE L	427–7744+9
580		
581	GARONIER MELISSA	426–4507+9
583½	•DEPENDABLE GLASS	420–8433+9
585•	DAVIS CLEANERS	428–8920+9
	KVEDRIS JOSEPH M	427–0079+9
590•	BALLARD PAUL RLTY	420–5871 8
•	CUSTOMER FLW UP SVC	427–1767+9
•	DEVELOPMENTAL READG	420–6202+9
•	INVESTMENT CNSLT	427–9100+9
•	LEARNING CENTER	420–6202 8
•	MEXICAR EXPO	427–2031 8
•	OWENS TOM LRNG CNTR	420–6202+9
•	READING CENTER	420–6202 8
•	READING CLINIC	420–8202+9
•	TOM O LRNG CNTR	420–6202+9
	WELCH P A	425–5438+9
•	WESTCOTT MOBILE HMS	425–0383+9
595	XXXX	00
605	HEMENWAY LEO	427–8835 7
610	APARTMENTS	
	BATEMAN A MICHAEL	427–0591+9
	BOETTCHER RALPH E	426–6599+9
	BOMEKE JACK M	427–4405+9
	CASHMAN DONALD E	426–9698+9
	FISHER S E	422–7637+9
	HAUGH JOHN E	426–8034+9
	KMECIK BENJAMIN J	426–6114 8
23	MITCHELL MABEL E	425–0919 8
10	MORSHEAD DAVID	422–1521 6
	NELSON J	426–8352+9
	OLSER RICHARD B	425–9339+9
	ONEILL PEGGY	425–3877 8
	RUIZ ROGELIO R	425–3355+9
	SANCHEZ ESMERELDA	425–3877 8
25	STORM A	427–1654 4
	STRIBLING JOE W	422–4519+9
	STUBBS THOMAS J	425–8826+9
	WILBERG E P	425–8025+9

G		92010 CONT
24	WOODBURN DELMER E	422–4640 5
	ZABLER R G	427–1655+9
610		
616	SOUTH BAY TOWERS	
	QUINN S R	422–8965 8
	ABRAMS FREDERICK C	427–1897+9
	AHRENS R	422–6317+9
	AUTON JOEL L	426–8093+9
12	AYUB MARGARITA	422–5079 1
83	BAUKOL DONALD R	426–2668 6
	BEAULAC A J	420–5615+9
	BEELER M D	422–6679 8
	BELLOWS THEODORE W	427–7314+9
	BROOKS ANTIONETTE	427–6049 8
	BROWN KENNETH C	422–8829+9
	BUNNEY WM S	420–2529 8
78	CHRISTIANSON M M	426–1378+9
	CLARY B J	427–0353+9
129	CLEMONS GARY E	422–3952 7
29	CRAWFORD ROSS H	422–2139 7
	DAMSEL SOPHIA–MRS	422–0307+9
	DEGUZMAN ANN	425–9685+9
	DENHAM C R	426–9807+9
51	DUPONT SUSAN	427–3660 5
51	DUPONT THOS	427–3660 5
	DURHAM J E	422–4237+9
	ERICKSON SUSAN J	426–0742+9
6	EVANS HARRY B	420–1334 7
	FRIX P S	425–9635+9
	FULLER SANDRA	426–8516 8
	GARWOOD C S	425–4619+9
126	GEORGE PAUL E	426–8415 7
	GREGOR DONALD	426–4018+9
	GURNSEY S K	425–7036+9
	HAYWOOD R R	427–7235+9
36	HICKS ORIN W	427–4288 6
	HOLDER I V	427–0192 8
62	HOLDER RUSSELL S	425–2127 6
52	HOLMES BOBBY D	427–8627 3
	HOWARD STANLEY	427–1486 8
	HUDSON EDDIE F	422–5659 8
105	HUNTER GEO L	426–7958 6
	JACKSON E L	426–1276 8
	JARRELL DORIS K	420–8565+9
	JESS P A	425–9495+9
	JOHNSON LEVA C	422–0722+9
33	JOHNSTON JOHN F	426–9279 6
	KEP RON	420–2330+9
2	KIRSCHT JOHN A	426–7433 5
	LEDBETTER J L	426–8455+9
	LYNN STEVEN J	427–7062+9
	MACKEY MICHAEL F	422–45 3+9
89	MARTIN WILBERT L	420–6626 7
	MARTINEZ R M	425–4387 8
	MCCABE ROBERT J	425–5913+9
	MCMAHAN MICHAEL D	422–1936+9
	MEANS B K	422–6794+9
	MENGES DON W	420–0853+9
	MONTEZ MARVIN	427–0478+9
	MOORE E L	422–4149 8
	MOREY B	427–6637+9
	OCHS EARL W	422–5083 8
	PATTERSON CAROLYN	426–7273+9
	QUINN S R	422–8965+9
	REED RICHARD V	427–4533+9
	REGAN C	420–6730+9
97	RILEY RICHARD A	425–0436 6
84	RODRIGUEZ LUISA	425–1725 6
	SANDERSON K J	427–6537+9
16	SARAFIN JOS	427–6997 7
24	SCHNELL CHAS L	420–5265 1
	SCHREFFLER H	422–6679 8
	SEARCY TONY	426–1084+9
	SEARS O	425–3849 8
	SELANDER MICHAEL R	426–2832+9
	SHORT GAY J	425–7239 8
	SKINNER CHAS F	427–2830+9
	SLINKARD WM C	426–5942+9
	SMILEY KAREN D	426–1456+9
	SMITH JOAN K	420–0594+9
50•	SOUTH BAY TOWERS	427–5533 0
	STANARD MERLE E	425–3717 8
35	STEINBACH WM	422–2432 6
72	STENTON BRIAN	427–3999 7
	STEPHENS ROBERT D	427–9782+9
48	STOFER GARY K	425–0398 6
	SWORD JEFFREY D	426–8591+9
	THIBODEAU M C	426–9717+9
140	THOMPSON JACQUELIN	426–0507+9
	TOUCHBERRY FORREST	422–8889+9
	TREGLE GLENN T	426–8006+9
	ULLE KARL F JR	426–1367 8
125	VALAZQUEZ MAURO A	422–0339 5
435	VRBANCIC JOS B	426–7759 3
	WAITE DWIGHT C	426–2437+9
	WILLIAMS JACK L	425–6289 8
	WOLD LIONEL K	425–9639 8
616		
628	XXXX	00
629	MACIAS MARIA M	427–9505+9
633	XXXX	00
635	ALLEN R D	422–2954 4
644	XXXX	00
649	ELY EDW H	426–7868 6
651	SUMNER CLINT G SR	422–5633 6
667	XXXX	00
677	BROADWAY TRLR PK	
34	ALLEN E	422–7679 5
133	ANDERSON GEO K	422–7224
46	ANDERSON VICTOR R	425–1755 6
98	ANDERSON W A	422–7688
94	BARCLAY THEO M	420–9032
	BARKER T L	420–3998 8
112	BEEBE S E	426–5356 7
152	BEHRENS RAYMOND L	427–5919 7
158	BELL T ROTH	422–1805
188	BENDER EDMUND F	422–6052 6
59	BESTINY JOS	427–3449 0
191	BIELAN KARL	420–7454 6
21	BISAILLON LUDGER J	426–0200 6
67	BOTTS JOHN B	420–3573
	BOTTS ROBT J	420–5565 8
	BOYD Z C	427–8801+9
132	BRINE WM J	427–1801 3
40•	BROADWAY TRLR PARK	422–0242
96	BRODERICK MARY	426–6479 7
149	BRUNER RUTH L	422–3214 7
27	BUSCHUR LAURA	426–6589 3
	CADDICK H	422–8187+9
11	CARTHY FRED	422–0242 5
65	CHENOWETH R W	422–6662 3
130	COOK ROLINE	422–1289
42	CORNELIUS HUGO J	422–8411 7
	CRAIG CHARLOTTE S	426–3840+9
72	CREWS JOHN W	420–3494
63	CROPLEY CLYDE P	420–8074 2
49	CSILLAG MURIEL	420–9284 0
156	DARLON DAVID	422–6869 1
	DIDOMIZIO DANIEL	422–3070+9
	DODSON WILBUR T	425–9998+9
	DOKE RICHARD	420–7997+9
187	DOUGHERTY FERN MRS	422–6467 0
	DUNKER N M	427–8604+9
60	DUNTON WALLACE W	422–2175
153	DURHAM HENRY C SR	427–9893 2

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1979



G		92010 CONT
174	EDMONDS A E	420-0316
138	ELLIOTT M	420-6669 2
101	ELLZEY ELIZABETH	420-2007 3
150	FARMER EMMA W	427-8837
169	FAULKNER DOYAL	420-2552 7
77	FLACK A B	420-8373 3
7	FUHRMAN ALICE L	422-6262
	GLENN CHAS O	425-9864+9
171	GOEPPER E H	427-0766
90	GOERSS FRITZ	422-5822
115	GREEN FLOYD I	422-9353 4
181	GREEN JERRY L	422-0467
	GREER MARVIN C	425-8538 8
74	GUNTLE M E	420-8151
	HALL STANLEY-USN	420-5108 8
176	HALL SYDNEY	422-2569
56	HANSEN CARL C	420-4883
	HARBECK A A	426-8152 8
172	HASELMIRE JOS M	420-5813
35	HATCHER CHARLIE L	422-0203
134	HAYDEN DEWEY M	427-4372
106	HENDERSON ROBT L	420-4601
22	HINKLE DARYL B	427-1475
64	HOBBS GEO E	427-4008 5
184	HORST PAUL	426-4237 4
105	HUFF MABEL C	420-5634 1
31	HUFFMAN GUY V	420-0549 1
1	HUNT E B	426-5476 2
	ISAACS MARGIE L	427-6550 8
151	JOHNSON G G	422-2344
148	JOHNSON ROBT LYNN	427-3195 5
	JONES LAMAR R	427-1159 8
122	KELLOGG ROY F	422-5575
97	KELLOGG STEARNS W	420-5693
62	KELLY JAS P	426-9923 2
	KELLY THOMAS	427-6896+9
180	KINCAID F I	422-2827 6
154	KIRCHMAIER WM E	420-0888
52	KIRKPATRICK WALTER	427-1018
165	KISBERT CHAS A	420-6769
131	KOHL KENNETH	420-8164 7
75	LEYDEN WALTER T	420-3269
95	LUND ELLIS M	420-1920
135	LYNCHEHAN L	427-5541 0
89	MAGERS BEN R	420-0494 0
5	MANGLESS DONALD R	422-9035 5
	MARNETTE OTTO H	425-1149 8
100	MARSH ROBT L	422-1584 7
84	MARTLEY EARL H	420-3368
164	MATHEWS R P	420-0531
108	MCCAMON FRANK	422-2328 5
190	MCKAY W A	420-0578
12	MCKINLEY THOS T-MRS	420-8349 2
102	MEILE R E	422-7419 1
114	MENDENHALL L F	427-3884
17	MERGEN S M	420-4691 4
71	MESTER CHAS H	422-3047 1
145	MILTON FRANCIS J	422-2921 3
45	MITCHELL ROBT H	422-2217
6	MOE C O	420-1041 0
78	MOORE ALICE O	426-0423 1
161	MORRIS WM N	422-7927
44	MULCAHEY WM F	420-5823 3
	MUNTER WILFRED-CDR	422-0293 8
19	NADEAU A	420-3886
186	NEWMAN L L	427-3734 6
	ODELL RONALD H	427-3477+9
2	OGDEN HOWARD	420-0442 1
68	PATTERSON EDMUND L	426-1322
155	PAULEY A E	422-6276
121	PAXTON RALPH JR	420-1147
178	PERRY G H	420-2646
	PETERS M B	425-6974+9
162	PILLA PAUL J	422-2598 6
4	POHL AUSTIN F	427-9254 3
127	POLLARD D H	427-0334
189	PORTER ALFRED L	420-3793
23	PRICE WALKER W	420-5844
88	RANCOURT M L	420-1668 5
	RARICK GUY	425-7936 8
16	REISS ALMA L	422-9057 4
128	RORABECK R S	422-0667
182	RULE EDGAR J	422-6718
170	SCHREIBER M L	420-6354
	SEOILLO BETTA L	422-8072 8
25	SELGO TED W-REV	427-2344 6
	SHELTON H B	426-4157 8
50	SISEMORE NAOMI R	420-4320
141	SKILLEN G LEW	422-8288
	SMULLIN F L	427-5243+9
15	STAGNARO BARTOL MRS	420-9214 0
167	STEVENS E M	422-0696
	STOAKES FREDERICK	425-6657+9
168	STOUDT M U	420-3513 4
192	SUMNER V	420-0660 4
40*	TERRYS MOBILE PARK	422-0242
83	THOE IRVIN L	426-8908 6
33	THOMAS M F	422-5232
129	THOMAS WENDELL C	427-4296
99	THORNTON C O	427-1371
110	TRAGO RICHARD C	422-7989
117	VALENCIA WALTER S	427-2931 4
57	VANTUYL A M	426-1405 4
39	VANZANTE N M	426-5614 1
147	VAZQUEZ FRANK	427-3963 1
20	VESTAL LYNETTE B	422-1071
113	WALKER ERVIN G	422-0872 5
142	WATKINS ARTHUR E	422-6210
104	WEBBER S M	422-6580
157	WEBSTER LUCILLE	420-4840
	WIDEN ALBERTA E	420-0316 8
173	WILHELMI W D	427-3867 0
91	WILLIAMS FORREST C	422-8539 6
184	WILLIAMS JARRETT R	427-9349 0
116	WILLIAMS M N	422-1709 5
93	WINGFIELD EDWIN J	427-3196
185	WOLL D J	427-1453 0
24	YELLAND WM J	426-6019 3
677		
691	XXXX	00
704	WHITTINGHAM V G	427-8784 8
B	VAUGHN BRUCE	420-1973 8
716	GRAFTON RICHARD JR	425-2478 8
	SPAIN KENNETH C	422-3834+9
724	STEWART LYLIE C	420-7083 8
731	CABRILLO MBL LDG	
	AAROE MURREL R	426-5095 8
28D	ALDER EMMA	420-3117 2
	ATWELL LARRY	422-7436+9
	BALLARD WM	427-3073+9
11A	BIRTHISEL L B	426-5097 5
	BOARD WM D	425-6899+9
14D	BRENNAN E Y	427-5863 3
58	BUXTON FRED H	420-2621
17A*	CABRILLO MOBILE LOG	422-0245
24C	CONROE GERALD F	427-4108 5
17C	CORBRAN C A	420-2302 5
21B	DAVIS JOS A	422-5157 2
	DAVIS ROGER D	425-6617+9
16C	DAWSON JOE	420-1587
	DOHERTY EDWARD J	426-2588+9
8B	DONOHUE M E	420-0069
18B	DOUGLASS MAURICE	427-1545 6
	DROZE S L	426-1995+9
18A	DUNGAN K W	425-5567 7
23C	ENDLICH JOS	426-9715 7
	FARNSWORTH GLADYS	422-4948 8
	FITZGERALD ENID	426-6242 8
22B	FUGATE HARRY R	427-8768 5
6A	GARSKY HARRY	420-7358 5
10B	GRANTHAM FLORENCE	427-2545 5
10B	GRANTHAM PAUL	427-2545 5
	GUTIERREZ ROBERTO	422-0590+9
18C	HAGEDORN LOUIS E	420-8429 2
3A	HAMBRICK JOE	420-7882 7
12D	HANKS JOE	427-9524 6
10D	HARRIS ALBERT G	427-9494 6
5C	HARTMAN MARION-MRS	427-5338 7
	HAY HAROLD B	427-8972+9
15D	HEPLER M L	426-8750 3
15E	HILL ALBERT W	426-4627 3
	HOLMES MARETTA F	422-3268+9
24B	HUME WM C	422-6071
2B	INMAN G B	427-9722 5
	INMAN LILLIAN	422-4713+9
23A	JACKSON WM R	426-0784 3
	JAMES THOS F	427-5641 8
	JONES DOROTHY LEE	420-6042+9
13A	JONES ORPHA M	420-0120 6
4D	JORGENSON VERNON	427-4975 6
15E	KELLER MARGARET MRS	420-2670
1C	LAVIGNE VICTOR J	427-1854 6
	LONG CLINTON	422-2760+9
9D	MARSHALL E L	426-2524 6
20B	MARTIN N	427-1584+9
13B	MAZZARELLI DANL	426-2274 2
	MCWHORTER ROY	420-4953 8
12C	MEYER SARA	420-9180 0
14E	MILLER HERMAN H	427-7555 8
23B	MITCHELL C M	427-7875 7
19D	MOULTON EDW H	422-8681
25C	MYERS H B	420-6782 7
8C	NOACK ALICE	422-3131 3
12E	NOBLE ROBERTA S	426-4597 7
	OBERG D L	425-9517+9
12B	OVERSTREET PRICE JR	420-4637
	PARK ADA M	422-9058 8
20A	PARKINSON MILTON E	422-2449
8E	PELLERIN JOS A	426-5779 1
4B	PRICE B L	420-3452 1
11B	PUCKETT LILLIAN R	420-8655 3
19C	QUINN WM R	420-9127
	RATH EDWARD	422-8781+9
1B	RHODES MARY S	426-3478 3
3B	ROBINSON WM A	426-5695 1
	ROTH J K	427-5623+9
9A	RYAN G	427-0708 6
	SAUNDERS LESLIE	425-6971+9
21A	SCHULTZ M A MRS	427-4966
26A	SEGHERS DOREEN H	422-2903
	SNOW THOS	426-3239+9
25D	STEELE HOWARD A	420-5843
8A	STEIGER HENRY G	422-2555 7
	STINNETT CARTER	427-5858+9
	SUTTER V	422-8940+9
7A	VEST JEWEL	420-2328
26C	WATSON R L	427-5315 6
	WENTWORTH KAREN A	426-2648+9
17A	WHITE STEWART M	420-7434
	WHITNEY ESTHER G	425-0125 8
731		
736	BERNAL Z	426-7656+9
	STARRS JEANNIE	420-7646+9
A	WISSER J H	425-2528 5
*	29 BUS 652 RES	187 NEW

G 92024 ENCINITAS

55	RESECK ALEX D	753-3201
56	DALEY FRANK P	753-2528
215*	CLATON TIRE CO	753-6316
*	CLAYTON TIRE CO	753-6316 0
221	POWERS CHARLES	436-9837+9
223	CLARK JOHN	436-5987 8
225	BARTLETT DEANNA	436-7371+9
227	ISON DOUGLAS	753-0600 8
230	XXXX	00
333	ECKENRODE W	753-2986 3
*	2 BUS 8 RES	2 NEW

G 92065 RAMONA


305	MANGIONE VINCENT	789-3763+9
311	ALVA ROBERT	789-4691+9
317	MAXA GARY J	789-3279+9
329	ALTHAGE DAVID E	789-4240+9
333	XXXX	00
335	PROFANCIK JAMES	789-1949+9
347	EVANS DOUGLAS D	789-3263+9
353	LUDWIG STEVEN G	789-3447+9
407	ESTES DAN	789-4294+9
411	MACON JOS TAYLOR	789-3564 6
412	HARVEY WARREN P	789-4296 7
419	XXXX	00
423	XXXX	00
427	DAIGLE ELIZABETH	789-3491+9
	RODGERS GREGG H	789-3491+9
431	BESNAH GLENN	789-1389 6
507	XXXX	00
516	GRIFFIN ELTON	789-1186 7
535	NERVIG CONRAD A	789-0673
618	THOMAS ANN	789-4927 8
	THOMAS JERRY	789-4927 8
622	CASTLE DAVID M	789-1398+9
628	BIRUSELL JAMES A	789-5149+9
650	LAWS BILL	789-2817+9
702	BALDWIN VICTOR L	789-3064 7
712	GRIFFIN TOM H	789-1213
715	YOUNG B M	789-0927 5
719	CASS EDW F SR	789-4486 7
720	MURGUIA STANLEY N	789-2106 7
722*	R&T REFRIGERATED SV	789-1144
*	RICHARDSON WM A	789-1144
725	XXXX	00
733	CASTEEL WM TAFT	789-1804 8
739	MUELLER LAVERNE	789-0190+9
745	MILLER VEDA	789-1953+9
750	DONNELLY MICHAEL J	789-3443 8
*	2 BUS 34 RES	15 NEW

G WEST 92101 SAN DIEGO

211*	J A A D INC	239-0611 8
241*	TILTON ROGER FILMS	233-8513 8
301*	COLORADO PRIME FOOD	231-0515+9
*	COLORADO PRIME MEAT	231-1698+9
*	POLAR GOLF SHOP	233-3186 3
335*	DANN A E&CO	239-5488
401	XXXX	00
415*	ABEL E H	234-0467 8
	ABEL E H	234-2025 8
*	MOTO RADIO	234-6457
419*	CITY SIGN COMPANY	232-3575
505*	SD MARINE HARDWARE	234-6677 7
*	SD MARINE HARDWARE	231-8334 7

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1975



..G 92102 CONT..

4448 XXXX 00
4455 JACKSON MARTY 263-4625+5
4470 *JEHOVAHS WITNESSES 262-5816
4487 XXXX 00
4488 SCOTT DWIGHT 263-5995 3
SCOTT M B 263-5995 3
4511 ARMSTRONG BARBARA 264-4027+5
4521 AVALOS PAUL V 264-5032
4522 PREWITT ELIZABETH 264-5207+5
4532 URESTI MARIA 264-1261 2
4542 XXXX 00
4551 CONTRERAS MANUEL H 262-6106
4561 BANUELOAS C 263-4004 4
4571 SHARP MARY ANN 263-1565+5
SHARP WINSTON JR 263-1565+5
4582 PURVIS WILBERT 264-3605+5
4583 CROCE PRIMO 264-6067
4591 CASTILLO GLORIA 262-5460+5
4593 LOVETT RUTH A 263-3362 4
* 43 BUS 186 RES 75 NEW

G 92010 CHULA VISTA


14 ACKERMAN DICK 427-3829 1
15 MORGAN LEE J 422-5951
30 GOOENIUS WALTER E 422-1930 0
36 XXXX 00
39 XXXX 00
42 HILDEBRAND ERNEST 420-3626 3
45 GRAVES GERALD H REV 427-0727 1
48 SHARP MENDEL 420-2414 4
SHARP S C 420-2414
52 LONG FRANK M 422-7831
55 XXXX 00
60 FLORES MIGUEL A 426-5376+5
66 HONOIUS PETER 422-2277
70 ASHBURN O A 427-8094
71 GOODWIN JAS W 420-3787 3
78 SORENSON VERDEL 427-7698
83 JOHNSON ROBT G MRS 420-8995 0
84 JENKINS SIDNEY R 422-5557
87 JENSEN WM P 422-4557
90 MURRAY FRANK E 420-1792
93 STONE B C 422-8838 4
102 FIRKINS WM G OC 427-6966 3
108 XXXX 00
111 OALE ROBT G 422-6217
115 LAIRO HAROLO L 422-6039
121 ZAPPONE CARMEN 427-3194
130 XXXX 00
134 XXXX 00
135 PHILLIPS IRENE 422-7494
141 ALLEN ERVIN 422-3797
146 OEERING R W 420-6445 1
147 COBEN CHAS SR LCOR 422-7648 1
155 XXXX 00
159 OEZORT IRVIN L 420-3280 2
161 LIMBACH CASPER A 422-6309
163 SUTTON THOS W 422-6296
164 MATTSON MATT W 422-2376
173 BREEN G B 422-8591+5
174 HAYES F S 422-6614
177 CURETON PAUL W 422-5625 1
CURETON S W 422-5625 0
181 HALTMEYER F H 422-1885
182 SOTO HENRY Y 422-8701
186 BARNES LEO 422-6768
194 OIXON CARMEN C 427-0173
195 STOUT W R 422-0418
197 XXXX 00
198 BARTON FRANK W 427-9824 0
202 FLORES JOSE M 422-4603
203 JOHANSEN WM E 420-9699
207 AMOS E H 422-6038
210 LAOO JAS L 427-9201+5
LAOO L E 422-6456
215 PARKS JUANA L 426-1536 3
217 OAMM L W 426-2755 0
222....LECHATEAU APTS
216 ADAMS HESTON O 427-3026 4
312 ALLEN W H 420-3079 0
BALOWIN MARTIN 425-1384+5
BARRY MARY MRS 420-2981+5
104 BRAOY EMMETT T 427-9231
317 BUTLER EOITH C 426-1907 1
203 CAREY SAML A 420-3566 2
CLOSE EOWIN C 422-2435+5
306 CUNARD I C 426-1167 4
202 DELO OAVID L 427-7478 1
112 DIXON JAS C 427-0931 3
211 FLOYD R A MAJ 422-4807 4
102 GALVAS JOHN J 427-0813
303 GAUSOEN HATTABELLE 422-6909 3
302 GREEN JOS L 422-8083
113 HINTON W E 420-3296 4
JACKSON H P 425-1878+5
JANTZ G 427-5467+5
208 JOHNSON ELSPETH A 426-5359 4
212 JONES CHAS R 426-6543 4
LAMBERTON M C 426-7088+5
115 *LECHATEAU APARTMNTS 422-4655
307 LOCKWOOD C M 427-1204 4
MCCORMICK CLAY 422-9187+5
MCKINNEY JOHN J 422-5663+5
NEUMANN WM K 475-0334+5
316 PEITON J C 427-2868
315 PRAY M L 420-6515
204 RULIK W 420-4512 4
214 SCHILLING FRANK MRS 427-0911 3
SCUPIN JOS 425-5646+5
314 SEAMAN H K 420-0309 3
108 SHAW MABEL A 426-0224
SNYOER WILBUR A 427-8061+5
TENNEY HAROLO O 425-2205+5
309 TICHENOR FLORENCE E 427-4690
206 WHELAN WM L 426-0083 4
207 WILCOX LAWRENCE 420-2663
WOERNER ORMAND 425-2544+5
1 WOOD G A 427-7904 4
222.....
223 FASTH M 427-3209+5

..G 92010 CONT..

JOHNSON BELEW M 420-5899 0
WALLEN OEBBIE 425-3685+5
227 FORREST WALTER W 422-1023
227½ FORREST E L 422-3424 0
228 XXXX 00
229 WOODEND MYRTLE M 422-2640
233 DOEGE DOUGLAS W 425-3996+5
239 NERBOVIG J G 420-7015+5
WALLICK CHAS M 427-5919 4
240 THOMAS J M 422-4254
241....APARTMENTS
CLICHE ROSE 425-5429+5
MILTON A N 420-7664 4
DRIOLA DOMENICO 426-2834+5
PRADO ANA 426-9052+5
TOWLE HAZEL J 427-1844 2
241.....
244 LILLEYMAN A I 420-3572+5
246 ARNEAL MILDRED MRS 420-5927
248 CUNNINGHAM S F 422-2212+5
250 HOPKINS MILDRED E 422-3531
250½ DAVIS JOSEPHINE 420-8639 2
252 HAMM G 427-6618 4
ROBERTS MICHAEL L 427-0294+5
WALKE S E 426-3916 4
264 WILLIAMS ALICE E 420-8130 4
8 GANFIELD WM J 420-4374
F DIXON E M 422-6779 2
268 BARTLETT M L 422-5719+5
HUDDLESTON N R 427-3205+5
JOHNSON FRED M 426-7825 1
274 SIMARD PAUL O 422-1945
277 FRITCHER JAS F 422-7902
*JIMS GUN SHOP 422-7902 0
281 LANE F B 420-3338 0
PARKS JOHN A 427-5967+5
282 *LITTLETON VIRGINIA 426-4633 4
*O K REALTY 426-4633 4
283 *OWIGHT GOVE AGCY 426-3200 1
*GOVE OWIGHT AGCY 426-3200 1
284 *AMER OPINION LIBRY 422-5196
286 *KANTRUDS TONY GARGE 427-6922 2
287 *SAN OGO URBN NWSPR 425-1180+5
310....HENNEY APARTMENTS
5 BELOHRADSKA NINA 427-8386
17 OANIELS ANDREA MISS 422-3589
HOD P 422-6703+5
13 HOWE HENRY J 426-9831 4
LONG V B 420-1553+5
10 LUSTER ELIZABETH G 426-5886 1
MEZE N 426-6425+5
MULKINS C O 420-6466+5
PEEK CHAS 425-2486+5
9 SORENSON MINA 422-2336
STEPHENS KEN JR 425-5585+5
16 WALLACE W D MRS 427-6418
310.....
311 KING E B 426-4686 4
313 XXXX 00
315 JOHNSTON J A 422-5431 4
316 CARMAN E S 420-1251 3
WINSTON EMILY C MRS 427-5121 2
317 MILLARD J B 422-5946
318....APARTMENTS
2 BRUOIE M L 426-2521
OIXON ALAN 426-1347+5
EARL S J 427-0926+5
MOORE SARA E 425-4971+5
4 SANSOM FLOYO 420-9157 4
14 TAROJFF F C 426-0515 4
7 WEHKING EARL 427-0796 1
15 WHITTAKER MYRTLE O 427-2767 4
WYMORE R W 426-6488+5
ZOWARKA R 427-7498+5
318.....
319 ASHOOK PHIL W 427-8676 3
ASHOOK ROSE L MRS 427-8676 3
320....APARTMENTS
5 BAKER VIOLA F MRS 420-1569
BIRCHFIELO C B 426-9130+5
BROOKS M H 426-4055+5
2 MCCONNEL MAE L 422-5715
4 MYERS J L 420-7622 4
6 SHELTON BYRDA MRS 420-2287
TORQUATO LARRY B 422-6746+5
320.....
321 PIERCE ESTELLA MRS 422-9157 0
323 BRORBY ALVIN O 422-3320
325 XXXX 00
329 ARTIAGA OIANE 425-0595+5
BUCK M W 422-0275
JENSEN OAVIO A 427-7959+5
TAYLOR S W 422-9058+5
330 LANOAU O B 422-4741
332 KALEY EOW E 426-7796 4
333 OGILVIE FLOYO E JR 426-6731 4
335 LUCKINBILL C O 422-1478 0
336 BLACK JAS N 420-4280
HAMELS ADRAIN 420-3825 1
KENEFICK M 426-5199 4
TERRASI MARGARITA 420-3187 3
340 BROOKS ALAN M MRS 422-5274
KUSHENBACH ALFRED 426-7893 1
LONG THELMA 427-3884 4
REBELES RAMON 427-1852 3
341 FOX JESSE B 422-1460
344 GIRE GORDON O 420-0972 3
345 BRYAN W M 422-5821
350 FAHRING J K MRS 422-2311+5
354 TALNADGE STEPHEN 422-4159
357 *CHLA VSTA WMNS CLUB 422-9706
363 HENRY J O MRS 420-6163
364 BLACK L E 422-4452
367 HUBBERT GEO N 422-2235
368 BRAINARO JACK L 426-6473+5
370 BEWICK CAROLE J 425-1292+5
SALVESTRINI CAROLE 425-1292 4
371 KONDRASHOFF EUGENE 422-7606
372....APARTMENTS
ALCARAZ WALTER A 422-4296+5
HIGGS HUEY J 426-0986+5
MCGLELLAN JOHN A 425-2038+5
VAUGHN CLIFFORO L 420-4492 3

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1975




..G 9201C CONT..
VAUGHN NORMAN L 420-3462
372.....
374 SLINKARD WM C 422-2124
375 ANDERSON MICHAEL 420-8804+5
ODWNEY CATHY L 427-9657+5
LILLEYMAN H K 426-2259+5
TURK N 426-4169+5
379 KEMERY WM E OO 422-0402 4
385 CLARK P K 420-9012+5
386 BENGUIAT RAQUEL M 427-8698 1
390 XXXX OO
394....APARTMENTS
CAMPBELL RICHARD 20426-8128+5
CUNARD R A 425-5584+5
FETRAS NICK 426-3725+5
HIPWELL REGINALD H 422-8605 4
HOLLOWAY GERALD L 425-5938+5
LUZAK F 426-3659 4
NADASDY EMERY R 425-4274+5
394.....
399 VANDERVEEN T J 422-1785
402 SCHAMBERGER THOS 426-6284 2
404 XXXX OO
406 NEAL C M 427-3588 4
408 TOBIN L R 427-3260+5
411 MADRIGAL AUGUSTINA 420-9293 1
MARTINEZ ESPERANZA 426-8273 3
412 HURLBURT GARY 426-6472+5
414 SPARBY R I 426-5416 1
418 RULAND BEVERLY J 427-0705 2
419 BOSCOSKY ROBT 427-8741 2
420 XXXX OO
422 GURLEY ALVIN J 426-9532+5
423 XXXX OO
424*VISTA SQUARE APTS 420-0188 4
E PIANO NICHOLAS W 426-7768 4
F MARQUEZ RUBEN R 426-6727 3
427 WOOD ARLEN D 420-9286
431 FOLEY O M 420-2001
435 HEIZER EMORY W 427-0470
439 VASQUEZ RAFAEL 426-8044+5
447 PULLINS D O 422-2917
453 SANMARTIN ANGELA 422-2232 4
459 WYNKOOP PATRICK M 425-3610+5
463 SLOTTEN HENRY WM 420-6184
473 MACK BEN L 422-0946
479 ALSIP DAVID M 420-2896
485 WHILDEN DAVID 426-7252 2
489 PAPICH JACK 422-4972
503 PIERSON B M 420-0742 4
507 KUBIE WALTER 420-3316
511*SD CO AGRICULTURE 422-2622 3
515 XXXX OO
519 MALDONADO RAMONA 427-9202 2
521 CLIPSON JOHN O 427-6877+5
HUEZO RAFAEL 427-8083+5
MCLENACHEN RONALD 422-8718 4
525 XXXX OO
529 WILKINSON MARSHALL 426-7559 3
531 NASH M T 425-3808+5
535 FUNK JOHN A 427-3061
540*VISTA SQ ELEM SCHL 422-8374 0
541½ FIELDS PATRICIA A 420-3826+5
543 SUSTAITA ROBT 426-9526+5
553 BEAUORY RON 422-8112+5
HERNANDEZ JULIA 422-3298+5
HERNANDEZ MIGUEL J 422-3298+5
RODRIGUEZ GLORIA 427-3326+5
TERRIQUEZ MANUEL C 420-2148 4
556 PEERY HOWARD P 427-0989+5
560 CHRISTIANSON D G 426-4497 2
561 GAUTREAU ALEXANDRA 427-6681 4
HELTON M 422-6950+5
RIVAS ELENA 420-4071 3
565*BROWN A S 426-0884+5
GARCIA JORGE 425-3944+5
GARDNER ERNEST M 427-9877 3
HEWARD BRUCE 425-0289+5
568 GONZALEZ VICTOR 422-2581
571 FORD J P 420-2528
580....GLORIAS APTS
28 BANKS MICHAEL 420-2361 4
19 *GLORIAS APARTMENTS 422-8252
10 GOVAN GLADYS MRS 427-3498 1
KURTZ STEVEN R 426-5468+5
LAMADRID NORMA 425-5238+5
27 LAWSON VIOLETTE M 427-9946
20 LONG ROBT G 427-3762 4
MAGALLANES ANTONIO 425-3821+5
MURPHY DENNIS 425-1097+5
6 RILEY CAROLYN M 427-3439 3
24 RODGERS CHAS L 422-7622 3
SANDERSON GERALD L 427-7945+5
SHARP LARRY O 425-3682+5
9 SHERFIELD DAVID 427-4101 4
SUAREZ MARIE 427-5652+5
YOUNG CHRISTOPHER 426-0870+5
580.....
581 XXXX OO
585*HAAS BEAUTY RANCH 422-9254
*HUCON BUILDERS INC 420-1753+5
590*HOOT GRAPHICS 420-5763 4
*ROGERS PAUL CECO 427-1544 0
*TANG SOO DO KARATE 420-2261 4
605 XXXX OO
610....APARTMENTS
ALLEN MICHAEL 426-0740+5
BEWICK SOPHIE 420-1012+5
23 CARAMELLO JOS J 422-6707 4
17 COOK J A 420-7876 4
OENT DANNIE S 425-2115+5
FARMER PAT 420-0218+5
31 FLOYD MICHAEL R 420-6196 4
18 GASKIN S A 427-9083 3
22 GELFO JAS J 426-8642 3
GERTEN EDW J 420-3457+5
KOMARA MARCELLE 420-7876+5
20 MCFADYEN A F 426-8866 4
MEYERS ROBT E 427-2901+5
29 MIKULEC ROGER 427-7624 4
9 ORTIZ RAUL 426-9426 4
25 STORM A 427-1654 4
21 SYVERSON ROBT J 426-8495 4

..G 9201C CONT..
TEELA RICHARD W 427-7371+5
TRAUPEL M K 427-9447+5
TUNGATE DENNIS 425-5678+5
WOODBURN DELMER E 422-4640+5
YEAGER GREG 422-5473+5
610.....
616....SOUTH BAY TOWERS
AGUILAR CARLOS B 427-8713+5
116Y ANDERSON DELBERT J 426-6169 4
12 AYUB MARGARITA 422-5079 1
BAKER GREG 426-6347+5
BALL DANL GLENN 426-9939+5
BOKAMPER CHRIS 420-7108+5
BOKAMPER FERN 420-7108+5
BRIGHT C M 427-7130+5
BROWN P R 420-6908+5
CAWTHON CHAS R 426-6283+5
CHAPMAN CRAIG C 420-0916+5
CLARK JAS L 427-2483+5
CONNELLY ALLAN W 427-9512+5
DALEY WM D ' 425-3196+5
57 DAVIS C A 427-9714 4
DEANDA MARIO JR 420-3718+5
DEMARZIO ROBT J 420-3635+5
DESCH J 427-5893+5
DONWEN NICKOLAS 427-1716+5
DUPONT SUSAN 427-3660+5
DUPONT THOS 427-3660+5
DURBIN DAVID 427-8925+5
DYCHTER SAML 427-9368+5
84 EDWARDS C O 426-4761 4
ENGLEHART DAVID R 427-1260+5
FALLS GERALD 422-6315+5
FRANCIS HOZEL 425-1416+5
GALLAGHER DANL N 426-6347+5
GASSETT ALLAN O 425-1103+5
GEORGACOPOULOS GEO 426-4524+5
GILLIS LAWRENCE C 426-3928+5
GRAY JASPER W 427-8625+5
56 HOLMES BOBBY O 427-8627 3
JOHNSON DORIS F 425-0909+5
JOHNSON WM B 426-9898+5
KENNEDY KEVIN G 427-9218+5
485 KESNER DAVID L 427-2329 3
106 KIRK JOHN E 426-0883 4
KIRSCHT JOHN A 426-7433+5
LAMADRID OLAFF 420-7739+5
LOUMAKIS TAKIS 425-0756+5
MARTIN E RANDALL 425-3878+5
MARTIN GLENN P 427-0202+5
METCALFE RANDY 425-1452+5
MILLER JAS R 425-1265+5
MOORE JEFF E 426-3047+5
MOORE T H 425-4537+5
MORELLI JOS A 425-3919+5
MURPHY MICHAEL G 420-2613+5
NACHTIGAL E G 426-0677+5
OGINO SHIGERU 420-9215+5
ORDONEZ ISMAEL M 420-9309+5
ORONA CHRISTINE 425-0847+5
PACHECO MANUEL 422-8975+5
PEACE STEPHEN 425-1419+5
PERSHING R L 422-0733+5
POORMAN O 427-0388+5
RAMSEY CHAS F 426-9630+5
ROBERTSON DONALD J 426-1490+5
ROMINE R H 425-2165+5
129 ROUTE CLARENCE N 304422-3593 4
ROZOLSKY LAWRENCE 422-2368+5
SAVINO MICHAEL T 426-6135+5
24 SCHNELL CHAS L 420-5265 1
33R SMETANA JIRI 426-7555 2
SOSA GUSTAVO 420-4229+5
*SOUTH BAY TOWERS 427-5533 0
SUGAR ROBT J 420-8398+5
SWOPE TIMOTHY J 426-7257+5
TABER V S 426-4574+5
THOMPSON J J 426-0507+5
74 VAGNETTI JOHN W 426-6620 3
VALAZQUEZ MAURO A 422-0339+5
VINSON TED A 420-6755+5
435 VRBANCIC JOS B 426-7759 3
WHITENACK C ARTHUR 422-5053+5
WOOD BRUCE M 425-0551+5
23R ZINTGURE JOS 427-6052 3
616.....
628 TRAUPEL MAURICE D 422-1974
629 GUZMAN A P 420-6674+5
635 ALLEN R D 422-2954 4
644*FREE WILL BAPTIST 420-9465
649 SNYDER WALTER C 422-8698 0
667 JONES LAMAR R 427-1159+5
677....BROADWAY TRAILER PK
14 ADLER EUGENE H 420-1379
ALLEN E 422-7679+5
133 ANDERSON GEO K 422-7224
98 ANDERSON W A 422-7689
94 BARCLAY THEO M 420-9032
158 BELL T ROTH 422-1805
59 BESTINY JOS 427-3449 0
13 BEVINGTON EARL P 420-7595
178 BEYSTROM LLOYD 420-3113 1
146 BORTON EDWIN C 420-1959
67 BOTTS JOHN B 420-3573
132 BRINE WM J 427-1801 3
40 *BROADWAY TRLR PARK 422-0242
27 BUSCHUR LAURA 426-6589 3
BYRNE P C 425-4976+5
CARTHY FRED 422-0242+5
65 CHENOWETH R W 422-6662 3
130 COOK ROLINE 422-1289
72 CREWS JOHN W 420-3494
63 CROPLEY CLYDE P 420-8074 2
49 CSILLAG MURIEL 420-9284 0
156 DARLON DAVID 422-6869 1
144 DAUBER JAS W 420-7068
28 DINI C 420-5398
136 DOKE RICHARD J 420-7997
187 DOUGHERTY FERN MRS 422-6467 0
60 DUNTON WALLACE W 422-2175
153 DURHAM HENRY C SR 427-9893 2
174 EDMONDS A E 420-0316
138 ELLIOTT M 420-6669 2
169 ELLIOTT T M 420-2552

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1975



..G 92010 CONT..

101 ELLZEY ELIZABETH 420-2007 3
150 FARMER EMMA W 427-8837
30 FARR MALCOLM E 420-1926
81 FISHER OSCAR A MRS 420-8205
77 FLACK A B 420-8373 3
7 FUHRMAN ALICE L 422-6262
103 GAPP LORETTA 427-4781
GARCIA JORGE F 426-9390+5
107 GAYESKE WM 420-4577
171 GOEPPER E H 427-0766
90 GOERSS FRITZ 422-5822
115 GREEN FLOYD I 422-9353 4
181 GREEN JERRY L 422-0467
74 GUNTLE M E 420-8151
176 HALL SYDNEY 422-2569
HAMBRICK JOE 420-7882+5
56 HANSEN CARL C 420-4883
66 HANSOM M 427-1315
172 HASELMIRE JOS M 420-5813
35 HATCHER CHARLIE L 422-0203
134 HAYDEN DEWEY M 427-4372
86 HAYS FERN V 420-4146
106 HENDERSON ROBT L 420-4601
79 HENSCHEL JEAN 427-4945 0
22 HINKLE DARYL B 427-1475
HOBBS GEO E 427-4008+5
184 HORST PAUL 426-4237 4
105 HUFF MABEL C 420-5634 1
31 HUFFMAN GUY V 420-0549 1
1 HUNT E B 426-5476 2
64 JEWETT M L 420-1835 3
151 JOHNSON GRACE G 422-2344
JOHNSON ROBT LYNN 427-3195+5
48 JORDAN R V 427-1315
188 KALER EARL B 422-8504
97 KELLOGG EVELYN 420-5693
122 KELLOGG ROY F 422-5575
97 KELLOGG STEARNS W 420-5693
62 KELLY JAS P 426-9923 2
160 KELSO L F CWO USN 422-6235
180 KINCAID GALE J 422-2827
154 KIRCHMAIER WM E 420-0888
52 KIRKPATRICK WALTER 427-1016
165 KISBERT CHAS A 420-6769
80 KRAFT CARL S 427-3608
75 LEYDEN WALTER T 420-3269
95 LUND ELLIS M 420-1920
135 LYNCHEHAN JOHN E 427-5541 0
89 MAGERS BEN R 420-0494 0
MANGLESS DONALD R 422-9035+5
84 MARTLEY EARL H 420-3368
57 MASON J W 426-7266 3
109 MASSAD MIRIAM M MRS 420-8490
164 MATHEWS R P 420-0531
MCCAMON FRANK 422-2328+5
46 MCCURRY JOHN W 427-4849 4
190 MCKAY W A 420-0578
12 MCKINLEY THOS T MRS 420-8349 2
102 MEILE R E 422-7419 1
114 MENDENHALL L F 427-3884
17 MERGEN S M 420-4691 4
71 MESTER CHAS H 422-3047 1
145 MILTON FRANCIS J 422-2921 3
45 MITCHELL ROBT H 422-2217
6 MOE C D 420-1041 0
78 MOORE ALICE D 426-0423 1
163 MOORE E L 427-0781
161 MORRIS WM N 422-7927
44 MULCAHEY WM F 420-5623 3
19 NADEAU A 420-3886
NEUMAN L L 427-3734+5
NOE GERALDINE 422-7261+5
2 OGDEN HOWARD 420-0442 1
37 PARSONS WILBUR T 427-6286 3
68 PATTERSON EDMUND L 426-1322
140 PAUL VERNE G 420-7226
155 PAULEY R F 422-6276
121 PAXTON RALPH JR 420-1147
179 PERRY BARBARA 420-2646
179 PERRY G H 420-2646
123 PLESS CLAUDE D 420-0536
4 POHL AUSTIN F 427-9254 3
127 POLLARD DOLLY H 427-0334
189 PORTER ALFRED L 420-3793
23 PRICE WALKER W 420-5844
RANCOURT M L 420-1668+5
92 REHKEMPER E C 427-3761 0
16 REISS ALMA L 422-9057 4
RESTLE E F 420-7338+5
11 RICHARDSON K D 426-0015 3
128 ROBBECK R S 422-0667
36 ROSE P MRS 427-2134 0
162 RULE EDGAR J 422-6718
170 SCHREIBER M L 420-6354
32 SEITZ DALE A 422-4031
50 SISEMORE NAOMI R 420-4320
141 SKILLEN G LEW 422-8288
29 SNELGROVE C H 427-0738 2
175 SPAINHOWER CHAS E 420-7512 3
15 STAGNARO BARTOL MRS 420-9214 0
167 STEVENS E M 422-0696
96 STEWART YETTA ILEEN 422-3518
55 STONESTREET JOHN W 420-5446 4
168 STOUDT M U 420-3513 4
192 SUMNER HOLLY 420-0660
192 SUMNER V 420-0660 4
40 *TERRYS MOBILE PARK 422-0242
THOE IRVIN L 425-4746+5
33 THOMAS M F 422-5232
129 THOMAS WENDELL C 427-4296
99 THORNTON C D 427-1371
110 TRAGO RICHARD C 422-7989
117 VALENCIA WALTER S 427-2931 4
57 VANTUYL A M 426-1405 4
39 VANZANTE N M 426-5614 1
147 VAZQUEZ FRANK 427-3963 1
20 VESTAL LYNETTE B 422-1071
WALKER ERVIN G 422-0872+5
183 WARD E C 420-8348 2
142 WATKINS ARTHUR E 422-6210
104 WEBBER S M 422-6580
157 WEBSTER LUCILLE 420-4840
40 *WESTERGAARD F C 422-0242 0
WESTERGAARD FAY C 420-4610+5

..G 92010 CONT..

58 WIDEN ALBERTA E 420-4107
173 WILHELMI W O 427-3867 0
184 WILLIAMS JARRETT R 427-9349 0
WILLIAMS M N 422-1709+5
93 WINGFIELD EDWIN J 427-3196
185 WOLL O J 427-1453 0
24 YELLAND WM J 426-6019 3
26 YOCKEL FRED R 426-2634 1
677.....
691 XXXX OO
704 WILCOX RALPH 420-7769+5
A NICKOLS JOHN M 426-3069+5
B VAUGHN BRUCE 422-3629+5
716 CONNER J L 427-8422+5
D MAKI K 426-1358+5
724 FREEMAN CHUCK 427-5289+5
731....CABRILLO MOBIL LODGE
24C ACCETTA F E 426-7854 1
11C ADCOCK MYRTLE B 427-8693 0
280 ALDER EMMA 420-3117 3
BIRTHISEL L B 426-5097+5
14D BRENNAN E Y 427-5863 3
BUENO VIRGINIA 420-5286+5
BUTORAC CRAIG 420-1098+5
BUXTON FRED H 420-2621
*CABRILLO MOBILE LODGE 422-0245
CAMERON DONALD 425-3720+5
7E CAMPBELL VIRGIL F 422-6876 4
CARRASCO RUDY 425-3083+5
CONROE GERALD F 427-4108+5
CORBRAN C A 420-2302+5
CRUMP EDITH O 420-8908
218 DAVIS JOS A 422-5157 2
DAWSON JOE 420-1587
DONOHUE M E 420-0069
160 ECKER GLADYS 422-4948 2
FUGATE HARRY R 427-8768+5
FULLEN ROLLIE C 420-7092
GARSKY HARRY 420-7758+5
GIBSON WILMA 420-3528+5
188 GORDON EVERETT 420-6881
GRANTHAM FLORENCE 427-2545+5
GRANTHAM PAUL 427-2545+5
18C HAGEDORN LOUIS E 420-8429 2
HARRIS ALICE C 420-4028
HARRIS CLARENCE I 420-4028
HART MABEL B MRS 427-6771
3A HAUSE DICK 420-3224 1
150 HEPLER M L 426-8750 3
HESTER MICHAEL 425-5677+5
HIGBY E L 422-4872
15E HILL ALBERT W 426-4627 3
27A HINSON CHAS 426-5937 4
24A HOLMES MARETTA F 422-3268
HOOKER CHAS L 422-8624+5
HOOKER COLLEEN S 422-8624+5
HUME WM C 422-6071
INMAN G B 427-9722+5
JACKSON WM R 426-0784 3
JONES ORPHA M MRS 420-0120
15E KELLER MARGARET MRS 420-2670
230 LANCASTER BERTHA 426-8964 4
1C LAVIGNE MYRTLE M 427-1854 4
18A LEWIS MICHAEL E 426-6118 3
2C MALKOWSKI FELIX J 427-5064 0
9D MARSHALL WM N 426-2524 2
7D MASSEY LELAH 426-3084 1
MATSON W L 420-7185
138 MAZZARELLI DANL 426-2274 2
MCELENY A W 427-0307+5
MEYER SARA 420-9180 0
MILLER HERMANN H 427-7555
MORRISON MARIE A 426-5741+5
MOULTON EDW H 422-8681
8C NOACK ALICE 422-3131 3
OLSON CARL I 420-2130
OVERSTREET PRICE JR 420-4637
PARKINSON MILTON E 422-2449
PASSMORE P L 427-6848
4E PAYNE L W 420-9113 1
PELLERIN JOS A 426-5779 1
PRICE B L 420-3452 1
PUCKETT LILLIAN R 420-8655 3
16A QUINN WM R 420-9127
26B REED L H 426-8739 3
26D REILLY HUGH E 426-0621 1
18 RHODES MARY S 426-3478 3
RICHARDSON BRUCE J 426-8140+5
ROBINSON WM A 426-5685 1
21A SCHULTZ M A MRS 427-4966
188 SEELEY M 426-8151 3
26A SEGHERS DOREEN H 422-2903
SEILER FRANK R 422-5080+5
2E SIRKEGIAN R R 427-9499 4
SPENCER ELIZABETH 427-4942+5
27A STEELE HOWARD A 420-5843
6E STINNETT CARTER O 427-5722
6E STINNETT VOSIE A 427-5722
SWIFT ORVILLE 427-7854
22A TESAR R S 427-0195
78 VEAL E 427-5338 3
7A VEST JEWEL 420-2328
14C WALKER P L 422-2001 3
22C WARNER GENE 426-1300
19A WESTROPE W T 427-0448
WHELCHEL PAULINE 420-9782
WHITE STEWART M 420-7434
158 WILCOX W B MRS 420-9729
731.....
736 BLY ROBT D 426-5197+5
ESTRADA GUILLERMO 422-8865+5
WILLIAMS WALTER G 420-2297+5
A WISSER J H 425-2528+5
809 XXXX OO
* 25 BUS 657 RES 217 NEW

(92024 ENCINITAS

55 RESECK ALEX D 753-3201
56 DALEY FRANK P 753-2528
215 *CLATON TIRE CO 753-6316
*CLAYTON TIRE CO 753-6316 0

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory


G ST 1971

G 92010 CHULA VISTA

NO #*CHLA VSTA ANML SHLT427-3300
14 ACKERMAN OICK 427-3829+1
15 MORGAN LEE J 422-5951
30 GUDENIUS WALTER E 422-1930 0
36 VIRZI R J 422-7393
39 SILVEYRA SYLVIA 420-7627
42 RYDER JOHN F 426-0683 0
45 GRAVES GERALD H REV427-0727+1
48 SHARR S C 420-2414
52 LONG FRANK M 422-7831
55 XXXX 00
60 LOPEZ LUIS G 426-5376+1
66 HONDIUS PETER 422-2277
70 ASHBURN D A 427-8094
78 SORENSON VERDEL 427-7698
83 JOHNSON ROBT G MRS 420-8995 0
84 JENKINS SIDNEY R 422-5557
87 JENSEN WM P 422-4557
90 MURRAY FRANK E 420-1792
102 SWART JOS 420-5749
108 XXXX 00
111 DALE ROBT G 422-6217
115 LAIRD HAROLD L 422-6039
121 ZAPPONE CARMEN 427-3194
130 LANE COY 420-4942+1
134 BAXLEY CURTIS 420-9073
135 PHILLIPS IRENE 422-7494
141 ALLEN ERVIN 422-3797
146 DEERING R W 420-6445+1
147 COBEN CHAS SR LCDR 422-7648+1
159 GOYETTE PETER D 420-0064
161 LIMBACH CASPER A 422-6309
163 SUTTON THOS W 422-6296
164 MATTSON MATT W 422-2376
173 BREEN DANL F 422-8591
174 HAYES F S 422-6614
177 CURETON PAUL W 422-5625+1
CURETON S W 422-5625 0
181 HALTMEYER F H 422-1885
182 SOTO HENRY Y 422-8701
186 BARNES LEO 422-6768
BAUMAN FRED 427-6878
194 DIXON CARMEN C 427-0173
195 STOUT W R 422-0418
197 MYNDERS J H 422-6656
198 BARTON FRANK W 427-9824 0
202 FLORES JOSE M 422-4603
203 JOHANSEN WM E 420-9699
207 AMOS E H 422-6038
210 LADD L E 422-6456
215 PARKS RAY E 420-3345
217 DAMM L W 426-2755 0
222 LECHATEAU APTS
AKINS RONALD L 420-6034+1
ALLEN W H 420-3079 0
BERNARD THOS J 427-6793
BRADY EMMETT T 427-9231
BUTLER EDITH C 426-1907+1
CARRUTHERS J L 420-9173
CARY SAML A 420-3566+1
CATE J DWIGHT 420-0159+1
CLEMENS DAVID M 426-6868+1
CRAIG WM G 426-7044+1
CURTIS GARY R 426-1313+1
DELO DAVID L 427-7478+1
DYSON R E 426-5218+1
ELDRIDGE RAYMOND 420-3161 0
FINLEY THOS F JR 420-5444 0
FITHIAN GLEN R 422-4283 0
FURRY JOS H 426-6365+1
GALVAS JOHN J 427-0813
GAUSDEN HATTABELLE 420-0396
GRASHAM A C 426-1646 0
GRAY JAS R 420-2035 0
GREEN JOS L 422-8083
HUSTON LESTER T 420-5020 0
*LECHATEAU APARTMNTS422-4655
LEVINE PHILLIP A 427-6462+1
MAHR ROBT 426-7349+1
PEITON J C 427-2868
RRAY M L 420-6515
RAPP RONALD L 422-4729+1
SHAW MABEL A 426-0224
SMITH SIG V 427-0258+1
SPURGEON JAS R 426-4097+1
TICHENOR FLORENCE E427-4690
TIMMERMAN WALTER E 422-7612

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1971



..G 92010 CONT..


WEINKLE BRIAN E 426-6658+1
WIKLE KENNETH G 427-1617 O
WILCOX LAWRENCE 420-2663
WILKIN M L 422-2709+1
223 JUHNSON BELEM M 420-5899 D
MCKAY KENNETH 427-7672 D
YOUNG LONNIE R 420-6459+1
227 FORREST WALTER W 422-1023
FORREST E L 422-3424 D
228 BATES IRMA 422-5241
229 WCCOEND MYRTLE M 422-2640
239 BAGLEY WM T 420-4405 O
CARDARELLI J C 427-4230+1
ESCANDON D A 427-7376
MARGITA JAS E 420-9891 O
OVERGARO DAVID 427-9461+1
240 THOMAS J M 422-4254
241 ALLEN THOS E 427-1834+1
LUNA S S 420-7588 D
244 LILLEYMAN LUKE MRS 420-3572
246 AKNEAL MILDRED MRS 420-5927
248 CUNNINGHAM RICHARD 422-2212
CUNNINGHAM SHIRLEY 422-2212
ROMIGUIERE RON R 420-9826 D
250 HOPKINS MILDRED E 422-3531
250½ GRAHAM IVA A MISS 422-3562+1
252 PRICE JEANNE 427-7176+1
RECKERD CHAS 422-1613
264 GANFIELD WM J 420-4374
HUSKEY AUBREY 422-3086+1
MILTON ANDREW A MRS 420-7664+1
WRIGHT MICHAEL P 426-4591+1
268 AVERY PAUL 427-6393+1
BROWN NORMAN F 426-3242+1
JOHNSON FRED M 426-7825+1
SIMMONS GEO W 422-2512+1
274 SIMARD PAUL O 422-1945
277 FRITCHER JAS F 422-7902
*JIMS GUN SHOP 422-7902 D
281 LANE F B 420-3338 D
282 STARK J D 427-5220 O
283*CHLA VSTA JAY CEES 422-7940+1
*DWIGHT GOVE AGCY 426-3200+1
*GOVE DWIGHT AGCY 426-3200+1
284*AMER OPINION LIBRY 422-5196
*KANTRUDS TONY GARGE 427-6922 D
287 CRITES CHAS J 422-2666
310 HENNEY APARTMENTS
BELOHRADSKA NINA 427-8386
BIRMINGHAM WM MRS 426-2722+1
BROWN NORBERTA MRS 422-4232
DANIELS ANDREA MISS 422-3589
HEANEY CHAS 422-1676
HOWE HENRY J 420-3826
KIOO R M MRS 422-6341
LONG VIOLA B MRS 420-1553 D
LUSTER ELIZABETH G 426-5886+1
SORENSON MINA 422-2336
WALLACE W D MRS 427-6418
311 DUNCAN N L 427-0576
313 KANTRUD HENRY T 420-6149+1
STEEN FRED A 420-9482
315 JOHNSTON FRED W MRS 422-5431
316 CONRAD DORCY E 427-9245
B KELLER OPAL A 422-3298
317 MILLARD J B 422-5946
318 BIRSNER M A 422-8915
BRUDIE M L 426-2521
CHASE BEN SR 420-5146+1
CRAWFORD VERNA 426-3682+1
MCAFEE M A 422-3282+1
SHAW ISOBEL M 422-3508 D
TAPIA EOW 427-2178 D
TARDIFF F C 426-0515+1
WEHKING EARL 427-0796+1
320 APARTMENTS
AUER PAUL R 427-1875
BAKER VIOLA F MRS 420-1569
BERGSTROM MABLE 422-9051
CRICKSMAN HARRY 426-0919
GATTERER MARY 427-5547
HANSON GEO A 426-5681+1
HARVEY HENRY M 426-2876 D
HUDSON M F 422-0277
MCCONNEL MAE L 422-5715
SHELTON BYRDA MRS 420-2287
321 PIERCE ESTELLA MRS 422-9157 D
323 BRORBY ALVIN O 422-3320
325 EHRHORN FRED R 420-6697
329 BERGQUIST FRED J 420-8323+1
BUCK M W 422-0275
POULL VINCENT M 422-5724+1
330 LANDAU O B 422-4741
332 LUSSAN ETHEL 427-0888
LUSSAN WALTER A 427-0888
333 BULLOCK EARL C 422-4481
335 LUCKINBILL C O 422-1478 D
336 BLACK JAS N 420-4280
HAMELS ADRAIN 420-3825+1
TERRASI MARGARITA 420-3187
340 BIRCHFIELD C B 426-1512 D
BROOKS ALAN M MRS 422-5274
KUSHENBACH ALFRED 426-7893+1
MARCK LEONARD G 422-0015
341 FOX JESSE B 422-1460
344 LIVOLSI MICHAEL J 427-4382 O
345 BRYAN W M 422-5821
350 FAHRING J K MRS 422-2311 D
354 TALNADGE STEPHEN 422-4159
357*CHLA VSTA WMNS CLUB 422-9706
363 HENRY J O MRS 420-6163
364 BLACK L E 422-4452
367 HUBBERT GEO N 422-2235
368 ANDREWS A A 422-2085
371 KONDRASHOFF EUGENE 422-7606
372 CARDINO DOYLE 426-3749+1
PRATT ERIC W 426-7760+1
VAUGHN NORMAN L 420-3462
374 SLINKARD WM C 422-2124
379 KEMERY WM E 420-9462 O
385 RARICK GUY 420-9012
386 BENGUIAT RAQUEL M 427-8698+1
394 DURANO ANTHONY J 427-6504 O
FERNANDEZ CHAS M 426-7088+1

..G 92010 CONT..

GAUTEREAUX KENNETH 420-9081
KELLEY JOHN J 426-7692+1
RITTER G P 426-0909
WOODBURN HAROLD J 427-0795
399 VANOERVEEN T J 422-1785
402 HULL ROSE MARIE 427-8249+1
404 XXXX OO
406 COX RICHARD H 422-9172+1
408 MAGUIRE CHAS F 427-8384+1
*VISTA SQUARE APTS 420-0188+1
411 MADRIGAL AUGUSTINA 420-9293+1
SPROUSE J O 427-3163+1
412 XXXX OO
414 SPARBY R J 426-5418+1
419 XXXX OO
420 COFFEY MICHAEL C 426-0753
422 AMAN LLOYD 422-3877+1
423 BITSKO DOUGLAS 420-3854+1
ESTRELLA GILBERT G 420-2033+1
HASSELBRING ROBT E 420-6179+1
KLIEVER KERRY R 426-6757+1
WADDELL WAYNE R 426-5707+1
424 HALL JUDSON 426-1784+1
RANDALL J W 426-1455+1
VEGGE TOBIAS 422-7703+1
427 WOOD ARLEN O 420-9286
431 FOLEY D M 420-2001
435 HEIZER EMORY W 427-0470
439 PARADISE JAS 426-3998+1
WEST ANN 420-2787 D
447 PULLINS D O 422-2917
453 SAN MARTIN F 422-2232
459 WORD LEE ANNA 427-5898 O
463 SLOTTEN HENRY WM 420-6184
473 MACK BEN L 422-0946
479 ALSIP BECKY 420-2896
ALSIP DAVID M 420-2896
489 PAPICH JACK 422-4972
503 PIERSON BETTY M 420-0742
507 KUBIE WALTER 420-3316
511*SD CO AGRCLTR DEPT 422-2622
515 CRUGGS TERRY D 426-3955+1
519 RICE JOHN E GENE JR 422-8755
521 ABRAHAM CHAS WM 426-2109+1
BIBO ILSE MRS 422-4306
BIBO OSCAR L 422-4306
LOPEZ JOE V 420-2149+1
MARTIN R A 426-1344+1
525 XXXX OO
529 BURKE RONALD E 420-8928+1
531*CHULA VISTA FURS 420-1219
535 FUNK JOHN A 427-3061
540*VISTA SQ ELEM SCHL 422-8374 D
541 VAZQUEZ CHAS C 427-9950+1
543 BRIGHT CATHERINE M 427-9943 D
BRIGHT KENNETH J 427-9943 O
547 FLIPPEN JOHN T 420-1735+1
553 PAYNE RONALD 420-0826+1
556 COCHRANE LOYAL O 427-0989+1
560 MCINTYRE JAS C 427-8240
561 PASCHINI MARC 422-3184 D
WEAVER JOHN M 420-2098+1
565 BRUNS K G 426-2417
STOREY WM R 427-3821 D
568 GONZALEZ VICTOR 422-2581
571 FORD J P 420-2528
580 GLORIAS APTS
BROWN GORDON L 426-1974
COCHRANE LOYAL D 422-8252
DELAMARTER VICTOR 426-0653+1
EBERHARD JACK R 420-6044+1
FITZGERALD DONALD 426-6066+1
FITZGERALD SHERRY 426-6066+1
*GLORIAS APARTMENTS 422-8252
GOVAN GLADYS MRS 427-3498+1
HILLMAN RUSSELL G 427-6411 O
HOLEMAN ROBT 422-3831+1
KAMAKIAN JOHN M 426-7654+1
KEMP FRANK D 422-9165 D
LANDIS IRWIN J 420-1659
LAWSON VIOLETTE M 427-9946
MILLER JAS K 426-3531+1
NELSON RODNEY J 427-4802+1
OVERSON LARRY 422-0559+1
RILEY JERRY C 427-0787+1
ROSS CYNOY 426-5506+1
ROSS GEO E 426-5506+1
TROPE ROBT W 427-7039+1
ZEBOR J F 427-8220
583 XXXX OO
585*CALIF BUR SHIPPING 422-5639
*HAAS BEAUTY RANCH 422-9254
590 BUILDING
*BAILEY PATRICK D 420-0400 O
*CHLA VSTA ELEM EDUC 420-2929
*CHULA VSTA EMPLYMNT 422-1128
*CREDITORS BSNS EXCH 426-7430+1
*MARCO PRODUCTS COR 427-5556
*MCNORTON ROBT B 427-0160+1
*ROGERS PAUL C&CO 427-1544 O
*UNTD 3 WAY ATO LSNG 426-7811+1
605 MILLS GLADYS M MRS 427-4531
616 SOUTH BAY TOWERS
ALLEN M L 426-5645+1
ALLOWAY JOHN M 427-1264+1
ANDERSEN M P LTJG 426-7085+1
ANDREWS FRANK D 422-5726+1
ANSLEY YVONNE 426-1577+1
ARMENDARIZ JUDITH 420-9179+1
AYUB MARGARITA 422-5079+1
BELAUSTEGUI JESUS 426-4995+1
BERG HENRY L 426-4577+1
BIDDLES HENRY NEAL 420-4690+1
BOYD JOHN S 420-0814+1
BRANAN PHILLIP H 427-8474+1
BROWN DWIGHT 420-9332+1
BROWN FRANK M 420-8999+1
BRUNICON CLARENCE 426-4219+1
BURNETT JOHN C 427-4535+1
CAMPBELL ORTON T 426-4267+1
*CIRULI BROKERAGE CO 427-9220+1
CLAPPER JOS L 422-5578+1
CONNOR WALTER R 426-4484+1

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1971



..G 92D10 CONT..

CRANE STEPHEN N 426-D151+1
DAIGLE RON 426-3710+1
DALBERG RICHARD L 420-7945+1
DOANE CAROLYN 426-4996+1
DOANE HERBERT S 426-4996+1
DONAN ROBT M 426-3156+1
DRYSDALE A G 426-4165+1
EWEN BONNIE 422-5430+1
FOREMAN W B 422-7787+1
FOUST JAS E 420-3080+1
FRIEP CONNIE S 427-8729+1
GULBRANDSON CHAS R 422-4267+1
HAGER HAMPTON C 426-4499+1
HARBISON DONALD L 422-4687+1
HATCH PAUL B 426-D219+1
HILL WM J LCDR 426-4665+1
HUGHES O C 426-5250+1
JOHNSON JOE B 420-2011+1
KANE ROBT M 420-7377+1
KING JOS E 427-4618+1
KROHN ALEX 420-5851+1
LESLIE CLARENCE W 426-5D10+1
LORD STEPHEN T 420-2991+1
LOTITO GOE L 426-D287+1
LYON A 420-75D5+1
MANTONYA ROBT R 427-7231+1
MARTIN CRAIG E 426-3673+1
MARTINDALE WM J 420-4181+1
MCADAMS CHAS 420-D792+1
MCCLELLAN R R 420-1149+1
MILLER CALEEN A 427-27D3+1
MILLER DOUGLAS H 427-2703+1
MILLER HELEN C 422-1851+1
MOORE DAVID G 426-3D85+1
MURRELL PEGI J MRS 426-2621+1
DONNELL BENJAMIN 427-9878+1
OSTERWALD WALTER 427-4193+1
OWENS BOBBY L 426-34D6+1
PALMER WAYNE L 420-251R+1
PANIAGUA FRUTOS 427-7D85+1
PARKER THEODORE B 426-42D1+1
PATTERSON W J 426-6153+1
PEPITONE J 420-9547+1
PERALTA ALEX R 426-2629+1
PIERCE GEO E LCDR 42D-7660+1
PURKINS JEAN M 420-4615+1
QUINN RAY E 426-7877+1
RAINBOLT MICHAEL 420-9332+1
RANKIN ROBT L 426-3760+1
ROTHAMEL STEVE 420-2011+1
RYAN FRANKLIN T 426-5755+1
SCHEBLE JOHN P 420-3382+1
SCHNELL CHAS L 420-5265+1
SEXTON THEODORE C 426-6D73+1
SHANAHAN ARTHUR J 427-1266+1
SHEA L 427-6D68+1
SHEEHAN GREGORY 420-9785+1
SMITH HELEN V 426-5024+1
*SOUTH BAY TOWERS 427-5533 D
SPECTOR MILTON COL 426-1215+1
STAUBER ORVILLE LT 420-1189+1
STEPHENS CHAS E 426-7142+1
STEPHENS HERMON W 426-D969+1
STREET FRED E 427-3648+1
TAYLOR STEPHEN 420-9332+1
TROUTMAN P M 427-5821+1
VAUGHN RICHARD L 426-7346+1
VEVLE TOM 426-3850+1
WALTON DENNIS E JR 427-3D39+1
WEBB FRED R 420-2011+1
WENDE RAYMOND A 420-3759+1
WEYKER LYNNAE J 422-3817+1
WILLIAMS BRIAN C 422-73D6+1
WILLIAMS I 420-3721+1
WILSON HARRY L 426-5D25+1
YOUNG L 427-6D68+1
YOUNG RONALD A 427-6549+1
ZANOS SAML 426-2672+1
628 TRAUPEL MARY KAY 427-4328
TRAUPEL MAURICE D 422-1974
TRAUPEL MICHAEL L 427-943D
629 LOVELL R M 426-2454
636 CUMBIE JAS 426-2D96+1
644*FREE WILL BAPTIST 420-9465
649 SNYDER WALTER C 422-8698 D

677 BROADWAY TRAILER PK


ADLER EUGENE H 420-1379
AORIAN KEITH E 42D-3724
ALLEY BLANCHE 420-7826 D
ANDERSON GEO K 422-7224
ANDERSON W A 422-7689
ARTHUR HOLLAND S 420-9163 D
AZEVEDO JOE J 427-1720
BARCLAY THEO M 420-9032
BARFIELD M C 422-6682
BELL T ROTH 422-1805
BESTINY JOS 427-3449 D
BETTS DALE K 427-6039
BEVINGTON EARL P 420-7595
BEYNON C ED 420-1555
BEYSTROM LLOYD 420-3113+1
BLISS BERNIECE MRS 420-4D8D
BLOOM M E 420-D569
BORCHERS LAURA E 420-5194
BORTON EDWIN C 420-1959
BOTTS JOHN B 420-3573
BOZYK B A 420-4857
BRENNAN P MRS 420-D128
BRINE WM J MRS 427-1801
*BROADWAY TRLR PARK 422-D242
CLAYPOOL ERNEST A 420-5D48
COOK ROLINE 422-1289
CODKE FRED 426-5D35+1
CREWS JOHN W 420-3494
CSILLAG MURIEL 420-9284 D
CURTIS NANCY E 420-8348
DANA WALTER L 427-0871
DARLON DAVID 422-6869+1
DAUBER JAS W 420-7D68

..G 92D10 CONT..

DINI C 420-5398
DOKE RICHARD J 420-7997
DOUGHERTY FERN MRS 422-6467 D
DUNTON WALLACE W 422-2175
DURHAM HENRY C SR 427-9893+1
EDMONDS A E 420-D316
EICHEL HERMAN JR 422-0872 D
ELLIOTT CARL S MRS 420-6669+1
ELLIOTT LOREN J 422-5139+1
ELLIOTT T M 420-2552
FARMER EMMA W 427-8837
FARR MALCOLM E 420-1926
FISHER OSCAR A MRS 420-82D5
FOHRMAN ALICE L 422-6262
GAPP LORETTA 427-4781
GAYESKE WM 420-4577
GOEPPER E H 427-D766
GOERSS FRITZ 422-5822
GREEN JERRY L 422-D467
GROSS HUGH JR 420-2574
GROTHE J A 420-D766
GUNTLE M E 420-8151
HALE GERALDYN B MRS 427-D547
HALL SYDNEY 422-2569
HANSEN CARL C 420-4883
HANSOM M 427-1315
HASELMIRE JOS M 420-5813
HATCHER CHARLIE L 422-D2D3
HAYDEN DEWEY M 427-4372
HAYS FERN V 420-4146
HENDERSON ROBT L 420-46D1
HENSCHEL JEAN 427-4945 D
HINKELMAN FRANCIS 427-2DD3 D
HINKLE DARYL B 427-1475
HOPKINS FRANK W 422-1857
HOUCK KENNETH E 42D-7882
HUFF MABEL C 420-5634+1
HUFFMAN GUY V 420-D549+1
JACKSON PATRICIA A 422-4316+1
JACKSON RUTH MRS 422-3678
JEWETT LYLE C 422-2704
JEWETT M R 420-1835
JOHNSON GRACE G 422-2344
JONES ANNA B 427-6382 D
JORDAN R V 427-1315
KALER EARL B 422-8504
KELLEY FLORENCE 427-2204
KELLOGG EVELYN 420-5693
KELLOGG ROY F 422-5575
KELLOGG STEARNS W 420-5693
KELSO L F CWO USN 422-6235
KINCAID GALE J 422-2827
KING MARION B 422-6381
KIRCHMAIER WM E 420-D888
KIRKPATRICK WALTER 427-1D18
KISBERT CHAS A 420-6769
KRAFT CARL S 427-36D8
LEYDEN WALTER T 420-3269
LUND ELLIS M 420-1920
LYNCHEHAN JOHN E 427-5541 D
MAGERS BEN R 420-D494 D
MARTLEY EARL H 420-3368
MASSAD MIRIAM M MRS 420-8490
MATHEWS R P 420-D531
MCKAY W A 420-0578
MCKINLEY THOS T 420-8349
MCQUISTON R G 420-7649
MEILE R E 422-7419+1
MENDENHALL L F 427-3884
MERGEN CARL B 420-4691
MESTER CHAS H 422-3D47+1
MILLER FRED J 420-7D59
MITCHELL ROBT H 422-2217
MOE C D 420-1041 D
MOORE ALBERTA 427-0781
MOORE ALICE O 426-D423+1
MOORE E L 427-D781
MORRIS WM N 422-7927
MOSS WALT A 427-1885
NAOEAU A 42D-3886
NESTER A LCDR 420-D821
OGDEN HOWARD 420-D442+1
PALMER WM J 420-2877
PARSONS WILBUR T 427-6286 D
PATTERSON EDMUND L 426-1322
PAUL VERNE G 420-7226
PAULEY R F 422-6276
PAXTON RALPH JR 420-1147
PECK BEATRICE H 420-9714
PERRY BARBARA 420-2646
PERRY G H 420-2646
PETERSON WALTER R 420-29D1+1
PLESS CLAUDE D 420-0536
POLLARD DOLLY H 427-0334
PORTER ALFRED L 420-3793
PRICE WALKER W 420-5844
REHKEMPER E C 427-3761 D
RESTLE EVA MRS 420-7338
RINEHARD B J 420-D781
RORABECK R S 422-D667
ROSE P MRS 427-2134 D
RULE EDGAR J 422-6718
SCHREIBER M L 420-6354
SEITZ DALE A 422-4D31
SISEMORE NAOMI R 420-4320
SKILLEN G LEW 422-8288
SPAINHOWER ELLIS 420-7512
SPEAS ANNA MRS 420-5212 D
STAGNARO BARTOL MRS 420-9214 D
STEPKA E N 420-8151
STEVENS E M 422-D696
STEWART YETTA ILEEN 422-3518
SUMNER HOLLY 420-066D
SUMNER VIRGINIA 420-D660
*TERRYS MOBILE PARK 422-D242
THOMAS M F 422-5232
THOMAS WENDELL C 427-4296
THORNTON C D 427-1371
TRAGO RICHARD C 422-7989
VANZANTE N M 426-5614+1
VAZQUEZ FRANK 427-3963+1
VESTAL LYNETTE B 422-1071
WADLEY LLOYD G 422-6531
WARD EVE 420-8348

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1971



..G $2010 CONT..
WATKINS ARTHUR E 422-6210
WEBBER S M 422-6580
WEBSTER LUCILLE 420-484D
*WESTERGAARD F C 422-D242 O
WIDEN ALBERTA E 420-41D7
WILHELMI W D 427-3867 O
WILLIAMS JARRETT R 427-9349 O
WINGFIELD EDWIN J 427-3196
WOLL D J 427-1453 O
YOCKEL FREG R 426-2634+1

691 GARCIA ESTHER DEL R422-2768
704 POWELL THOS 426-6387+1
716 GRANADOS EDW R 426-6181+1
SPERL RAYMOND 426-4273+1
TOLIVER IRA L 427-18D6 O
A FRITCHOFF MARY I 420-1181
724 AHLIN DALE A 426-43D6+1
GEVOY RICHARD J 427-4D48+1
KOENIG DAVID M 426-7882+1
731 CABRILLO MOBIL LDGE
ACCETTA F S 426-7854+1
AGCOCK MYRTLE B 427-8693 D
BAIR ANNA R 426-2532 D
BELL F M 427-6417
BINKLEY IRA A 420-82D9 O
BRADY R F MRS 422-816D
BRENSEL EDNA 420-D7D8
BUENO KELLY A 420-5286 D
BUXTON FRED H 420-2621
*CABRILLO MOBILE LDG422-0245
CASTOR RUTH MRS 427-534D+1
CHADWICK FRED 420-4614
CORBRAN JOS L 420-2302 D
CROMER E L 420-63D4
CRUMP EDITH O 420-6908
CYR EMILE A 420-2946
DAWSON JOE 420-1587
DAY WILLA 426-D462+1
GONGHUE M E 420-D069
ECKER AMBROSE J 422-4948
FULLEN ROLLIE C 420-7D92
GORDON EVERETT 420-6881
GUEL ANTONIA H MRS 420-0573
HAGEDORN LOUIS E 427-2822
HARRIS ALICE O 420-4028
HARRIS CLARENCE I 420-4D28
HART MABEL B MRS 427-6771
HAUSE GICK 420-3224+1
HENTERSEMER GEO 427-2809
HEPLER MARJORIE L 427-0341 C
HIGBY E L 422-4872
HIRTZLER LOUISE MRS422-8092 O
HOLCER W C 427-3379
HOLMES MARETTA F 422-3268
HUME WM C 422-6071
JACKSON WM R 426-0784
JACOVITCH C MRS 427-4808+1
JONES MELVIN 422-1622
JONES ORPHA M MRS 420-0120
KELLER MARGARET MRS420-267D
KITCHENS TEDDY B 426-2696+1
LAWRENCE WM J 420-8429
LEFEVOUR E H 420-5492
LEON MARTHA FOSSA 422-5907
LEWIS HAZEL M MRS 427-1250 C
LEWIS MICHAEL E 427-1250 C
LINOBERG MARGARET 420-0661+1
MALKOWSKI FELIX J 427-5064 C
MASSEY LELAH 426-3084+1
MATSON W L 420-7185
MCNAMARA F B 427-1901+1
MEYER SARA 420-9180 O
MICK GABRIEL 420-2651
MILLER HERMANN H 427-7555
MORGAN WM 427-4359
MOULTON EDW H 422-8681
OLSON CARL I 420-2130
OLSON LILLY MRS 420-2130
OVERSTREET PRICE JR420-4637
PARKINSON MILTON E 422-2449
PASSMORE P L 427-6848
PAYNE L W 420-9113+1
PELLERIN JOS A 426-5779+1
PRICE B L 420-3452+1
QUINN WM R 420-9127
REILLY HUGH E 426-D621+1
REISS ALMA L 422-9057
RHODES SAML W 422-0245
ROBINSON WM A 426-5685+1
RUSTAD AGNES P 426-0532
SCHULTZ M A MRS 427-4966
SEGHERS OUREEN H 422-2903
SHORT LEO 426-6199+1
SPENCER EARL C LCDR427-4942
STAFFORD HENRY J 427-1586
STEELE HOWARD A 420-5843
STINNETT CARTER O 427-5722
STINNETT VOSIE A 427-5722
SWIFT ORVILLE 427-7854
TASSIN GERALD 427-9626 O
TASSIN PEGGY 427-9626 D
TESAR R S 427-D195
TOWER CHAS W 427-6050+1
VEST JEWEL 420-2328
WARNER GENE 426-13D0
WESTROPE W T 427-0448
WHELCHEL PAULINE 420-9782
WHITE LEONARD L 427-4749
WHITE STEWART M 420-7434
WILCOX W B MRS 420-9729
WILLIAMS GUY R 426-7482+1
736 GOSCH SANDRA 426-0982+1
WEHLAGE M L 426-4903+1
809 XXXX GO
• 31 BUS 652 RES 242 NEW

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1965

G-From 400 Hilltop dr east

14 Ackerman Richd J ◎ 420-4910
15 Morgan Lee J ◎ 422-5954
30 Vacant
36 Vacant
39 Silveyra Augustine ◎ 422-0205
42 Smith Lorraine Mrs ◎ 422-4126
48 Sharp Salem C 420-2414
52 Nickelson Nicholas W ◎ 422-2479
55 Ogden Jack L jr ◎ 422-2795
60 Rayfield Wm S ◎ 420-0210
66 Hondius Peter ◎ 422-2277
70 Joost Rodney E 427-0532
71 Merrell Howard E ◎ 420-5600
77 Kendall Bart F ◎
78 Taylor Wm R ◎ 420-8580
83 Chenoweth Eug T ◎ 422-2016
84 Jenkins Sidney R ◎ 422-5557
86 McLenachen John G 422-6666
87 Jensen Wm P ◎ 422-4557

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1965



90 Scotford Wm L © 420-4148
93 Vacant
1st av intersects
102 Williams Walter L 427-1020
108 Foster David D © 420-1483
111 Dale Robt G © 422-6217
115 Laird Harold L © 422-6039
121 Avery Vernon © 422-1735
Alpine av intersects
130 Kagey Clarence C © 422-6565
134 Duensing Paul L 427-0819
135 Phillips Roscoe © 422-7494
140 Rathbun Arth © 420-6034
141 Allen Ervin © 422-3797
146 Dittenhaver Donald B © 422-4153
147 Coben Chas E © 422-7648
DelMar av intersects
152 Reed DeWayne 420-7727
155 Pitchford Luther G © 422-7646
rear Shaw Edw K 420-5540
159 Larson Geo H 420-2642
160 Chlarson Harvey G ©
161 Limbach Margt Mrs © 422-6309
163 Sutton Thos W © 422-6296
164 Mattson Matt W © 422-2376
167 Higgins Minor Rev © 422-1397
170 Novak Chas © 422-3671
173 Morton Wm R © 422-1665
JEN-Lou Secretarial Serv
422-1665
174 Skipwitz Jean Mrs 420-3464
177 Cureton Celesta W Mrs © 422-5625
181 Haltmeyer Fred H © 422-1885
182 Soto Henry Y © 422-8701
186 Barnes Leo A © 422-6768
rear Vacant
195 Vacant
197 Mynders Jos H © 422-6656
198 Vaught Kay Mrs © 420-7645

106

2d av intersects
202 Burtis Laura J Mrs © 422-4141
203 Johansen Wm 420-9699
207 Amos E Harrison © 422-6038
210 Ladd Leonard E © 422-6456
211 Cesena Ildrolfo © 422-1632
215 Savala Robt E 420-2783
217 Damm LeRoy W © jwlry mfr
422-4285
222 **LeChateau Apartments** 422-4655
101 Greaser Clifford E 422-2489
102 Galvas John J 427-0813
103 Vacant
104 Gaffey Roger R jr 420-7317
105 Isaacson Eric E 427-0295
106 Fullerton Walter
107-08 Vacant
109 Husain Margt 422-8291
110 Passerino John O 427-2599
111 Dayton Benton A 422-3806
112 Donahue Mary H Mrs 420-6037
113 Stiles Keith E 422-6574
114 McNeight T E
115 Vacant
116 Wagner Theo F 422-4655
201 Vowinkel Ray C 422-7954
202 Harmon Larry
203 No Return
204 Tyler E A 420-4605
205 Florida Thos
206 Vacant
207 Carmichael Donald
208 Vacant
209 Landgren Carl 420-6925
210 Vacant
211 Beason Timothy
212 No Return
213 Schilling Frank X 427-0911

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1965

G–Contd
222 LeChateau Apts–Contd
214 Brown Chas A 422-1509
215 Long Mamie T 427-2600
216 Voekle Donald W 422-0456
217 Mack Bruce R 422-7831
218 Varner Vonnie 420-4575
301 Linehan Donald R 427-2459
302 Dickter Jaime M 422-4984
303 Faehner Richd J 420-5625
304 Williams Jerry
305-06 Vacant
307 Smith Vernon L 420-8767
308 Cox Herbert J 420-8728
309 Tichenor Frank E 426-4690
310 Vacant
311 Stibigh Dorothy B Mrs 420-6420
312 Benshop Edw
313 Confal John 420-0039
314 Timmerman Wm E 422-7612
315-16 Vacant
317 Primeax Richd A 420-0339
318 Eklund Gerald G 420-1619
223a Owens E M 427-2685
223b Vacant
223c Rhodes Verna M 422-1871
227 Forrest Walter W ◎ 422-1023
227½ Forrest Eva Mrs 422-1023
228 Vacant
229 Kahler Lillian Mrs ◎ 422-2640
233 Gustafson E A 422-6437
236 Shadley Rex E ◎ 420-9642
239a Phillips Randolph F 422-2156
239b Huntington Joan P Mrs 420-8843
239c Deeds Raymond
239d Williams Ruby A Mrs
239e Vacant
239f Josserand John L 420-2827
240 Thomas Jesse M ◎ 422-4254
241a Childress Richd L 427-0806
241b Jones Leroy
241c Cherinian Robt 426-4301
241d Benson Mark J
241e Atkins Julie
241f Bogan John F 422-1433
244 Lilleyman Adah I Mrs 420-3572
244½ Miller David
246 Arnal Frank C 420-5927
248 Matchett Fred D 420-2623
248½ Bills Vera I 427-0147
250 Hopkins Mildred E Mrs 422-3531
250½ Vacant
252 Gonzales Jorge 420-4669
252a Reckerd Chas ◎ 422-1613
252b Vacant
252c Filbey Lloyd J 420-8663
252d Weidmayer Jan E 426-4403
252e No Return

Del Mar ct intersects

264a Otten Eliz A Mrs 422-7801
264b Ganfield Gretchen
264c-d Vacant
264e-f Vacant
268a Leonhardt A R Mrs 422-2877
268b No Return
268c Vacant
268d Ganfield Wm J 420-0934
268e Thayer Helen
268f Richter Rehan 420-4695
274 Simard Paul O ◎ 422-1945
277 Vacant

Church av intersects

281 Lane Claude L ◎ 422-0827
282 Vacant
283 Gove Dwight Agcy Inc ins 422-0149
rear Sin Chas A 422-7797
284 Am Opinion Library 422-5196
287 Crites Chas J ◎ 422-2666
289 Vacant

108

2d av intersects

310 **Heaney Apartments** 422-1676
1 Dinwoddie Wm
2 Kidd Richd M 422-6341
3 Condrey Susan
4 Touraille Emil
5 Wallace Hertha Mrs
6 Pauluck Lillian
7 Birmingham Bernice 422-8479
8 Kalke Wallace
9 Sorenson Mina
10 Simon Sara Mrs
11 Brown Norberto S
12 Rowell Edw
13 Howe Henry J
14 Heaney Chas T ◎ 422-1676
15 Fahring Jane K Mrs 422-0876
16 Gibson Robt
17 Daniels Andrea M 422-3589
311 Coutts Lillian M Mrs 422-0226
313 Steen Fred A 420-9482
315 Johnston Jane A Mrs 422-5431
316 No Return
Keller Opal A 422-3298
Packard Alpheus
317 Millard Jesse B 422-5946
318 **Palo Verde Apartments**
1 Crowe A Lee jr 420-0058
2 Brudie Marie Mrs 420-5717
3 Cullen Myrtle L
4 Hoey W S
5 Birsner Marjorie A 422-3041
6 Diandrea Dominick
7-9 Vacant
10 Schlechte Roger E 420-0462
11-12 Vacant
14 Frasier Joyce A
15 Tutteur Mary G
319 Brown Chloe Mrs
320 **Apartments**
1 Shaman Harold L 422-1541
2 Negley Paul L 422-2037
3 Bowser Ross V 420-1758
4 Vacant
5 Clark Mary I
6 Shelton Byrda Mrs 420-2287
7 Petty G R
8 Fisher John W 420-6746
9 Hayes Thos W 420-6459
10 Madden John
11 Boblet Dorothy
12 Bergstrom Mable 422-9051

Street continued

321 Vacant
323 Brorby Alvin O 422-3320
325 Chambers Jas 420-1732
329a Harrell A Blanche ◎ 422-1203
329b Buck Carolyn Mrs ◎ 422-0275
329c Vacant
329d Crawford Mildred A
330 Landau Mary L Mrs ◎ 422-4741
332 Lusson Walter A ◎ 427-0888
333 Tague Glen M ◎ 422-2378
335 Luckinbill Chas ◎ 422-1478
336a McConnel Mae L
336b Murchie Vivienne Mrs
336c Long Harry A
336d Black Jas N 420-4280
340a Brooks Idella M Mrs 422-5274
340b Marck Leonard G 422-0015
340c Vacant
340d Straka John 422-7976
341 Fox Jesse B ◎ 422-1460

Garrett av intersects

344 Vacant
345 Bryon Wm 422-5821

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1965


G–Contd
350 Baskin Mary Mrs ◎ 422-2311
354 Talnadge Steph ◎ 422-4159
357 Chula Vista Women's Club 422-4515
Chula Vista Junior Women's Club 422-4515
363 Henry Evelyn M Mrs ◎ 420-6163
364 Black Clara Mrs ◎ 422-4452
367 Hubbert Geo N ◎ 422-2235
368 Andrews Fronia M Mrs mus tchr 422-2085
Andrews Archie A ◎ 422-2085
370 Vacant
371 Kondrashoff Eug 422-7606
372 Porter Chas F
Apartments
(A-B) Vacant
(C) Hunter Chas D
(D) Vacant
374 Slinkard Wm C ◎ 422-2124
379 Hubler Vernon R 420-7497
385 Mullen Robt F 422-4215
rear Vacant
386 Whilden Adolphus ◎ 420-4720
390 Vacant
394 No Return
399 Vanderveen Martha Mrs ◎ 422-1785

110

4th av intersects
402 Miles Helen J Mrs 422-4728
404 Jarvis Norman R 422-2231
406 Winkler David E 420-5327
408 Hamels Adrian F 420-3825
410 Clowers Wylma R Mrs
411 Barnell Dorothy Mrs
412 Woolstenhulme J R
414-15 No Return
416 Peters Linda L Mrs
418 Jaeger John C
419 Widdel Ann 420-3204
420 Morris Chas W 422-9351
422 Franklin James A
423 **Lancer Apartments**
(A) McMahan Paul
(B) Vacant
(C) Swanson Bert T 427-0725
(D) Anderson Leila
(E) Thomas R B
(F) Boggs Chas L 427-1330
(G) Palmer Evelyn
424 Simpson Douglas C
424a Faust Ronald E 420-4064
424b Vacant
424c Campa Sondra Mrs
424d Vacant
424e Collette Bill
424f Goad Robt C
424g Johnson Lillian Mrs
427 Mosbarger Jas M ◎ 420-2832
431 Foley Don M ◎ 420-2001
435 Button Roger ◎ 420-1837
439 Fluharty Ivan V ◎ 422-4739
439½ Vacant
443 Davidson Donald F ◎
447 Pullins Delmas D ◎ 422-2917
453 SanMartin Filemon ◎ 422-2232
459 Franklin Betty A ◎ 420-4292
463 Slotten Henry W ◎ 420-6184
469 Luckie Leo L ◎ 422-1429
473 Mack Ben L ◎ 422-0946
479 Alsip D Michl ◎ 420-2896
481 Price Bryan F ◎ 422-2673
485 No Return
489 Papich Jack ◎ 422-1972
E 5th intersects
503 Knauff J M
507 Swallow Norman W 420-8741
511 County Agrl Comnr 422-2622
515 Ainsworth A E
517 Vacant
519 Rice John E jr 422-8755
521a Vacant
521b Johnson Benj F
521c Babtiste Annette Mrs
521d Bibo Oscar 422-4306
521e Gore Milton
525 Perin Maria Mrs ◎
529 Green Harold L
531 No Return
535 Funk John A ◎ 422-4563
540 Vista Square Sch 422-8374
541 Johnston Jas K 426-4665
541½ Vacant
543 Terrill Dan M 422-3250
543½ Denney Leighton E 427-1300
547-49 Vacant
Smith av intersects
553a Hartzog Wm 422-0237
553b Lemons Jas F
553c Fishel Terry
553d Elder Roger
556 Nelson Geo H 422-2291
560 Skibbe Errol L ◎ 422-7779
561a Carter Milton C
561b Anschutz Leland
561c Cutchin Oland
561d Dame Glen E 422-0791
564 Vacant
567 Hendrex Ralph J ◎ 420-6542
568 Gonzalez Victor 422-2581
571 Ford Joel P ◎ 420-2528
580 **Gloria's Apartments**
1 Johnson Judith B
2 Nelson Everett R 420-3141
3 Vacant
4 Machado Theresa C Mrs 422-8252
5 Kidd G S
6 Berger Sol 424-2394
7-9 Vacant
8-10 Vacant
11 Mason Marie Mrs 427-2520
12 Vacant
13 Hargus Jas W 426-4463
14 Tripp Wayman D 427-2476
15 Geiger Alf E
16 Vacant
17 delaCruz Ricardo
18 Vacant
19 Ennis Colette D
20 Smith Robt L
21 Fisher Maria Mrs
22 Stowe Carl W
23 Vacant
24 Turner Garth E 422-5556
25 Gargano Diane
26 Neighbors Walter E 420-9784
27 Astiazaran Joe
28 Ruston Chas
Street continued
581 Roberts Russell D
581½ Gilbert Thos
583 Aranda Carlos G ◎ 422-1742
585 Haas Beauty Ranch 422-9254
Komendera Ronald F ins agt 420-6871
589 Kelsey Warren M ◎
590 **Building**
Rooms:
1-2 Vacant
3-4 Ovation Cosmetic Sls 427-2644
5 Joan's Hse of Samples women's clo 422-2060
6 Sweetwater Educ Assn 427-1627
7-8 Vacant

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1965



G-Contd
590 Bldg-Contd
9 Vacant
10 Chula Vista Employment Agcy 422-1128

136

Broadway intersects
605 Vacant
610 Linthicum Anna L Mrs © 422-1540
610a Moffett Newton
610b Vacant
628 Traupel Maurice D © 422-1974
629 Ware Gerald C 420-8290
644 Culnan Edgar B © 422-6321
rear Brinnen Faye Mrs 422-1865
649 Vacant
677 **Terry's Mobile Park** 422-0242
Pauley Ralph F pntr 422-6276
Roos Cornelis 422-0242
691 Garcia Esther Mrs © 422-2768
695 DelRio Josefa A Mrs
Jefferson intersects
704a-c Vacant
704d Stein Wm V 422-4409
716a Carter Jewell Mrs
716b Smith Geo C 420-5734
716c Osborn Paul G 420-6810
716d Vacant
724a Vacant
724b Flower Robt D 427-2487
724c Vacant
724d Mackenzie Edw H 427-2929
736a Zeller Richd W
736b Walters Clarence C
731 **Cabrillo Mobile Lodge** 422-0245
Rhodes Saml
736a Cole Arth L 426-4707
736c No Return
736d Vacant
772 Vacant
774 No Return
776 Wrought Iron Specialties 422-3055
809 Tyce Engineering Corp aircraft parts 422-0191
856 Hobart Consolidated bldg contr 422-8361
Hobart Inv Co 422-8361
Johnson H H Constn Co bldg contr 422-8361
Johnson H H Inc bldg contr 422-8361
Johnson H H Development Co bldg contrs 422-8361
Johnson-Tyson & Lynds bldg contr 422-8361
Seabrook Reginald S loans 422-1173
Williams Harry L bldg contr 422-1133
ft Chula Vista Animal Shelter 422-2669

SAN DIEGO
131 W. ASH STREET

FORTUNA --Contd
121 Violette Fred M ◎ ΔHA0-0812
126 Marrin Wardell C ◎ ΔHA0-6153
127 Payseno Arnold R ◎ ΔHA0-1969
Fogey Gary W ΔHA0-1969
130 Gilligan Richd E ◎ ΔGA2-9152
134 Gunn Curtis ◎ ΔGA2-1881
135 Mangles Donald R ◎ ΔGA2-9035
140 Borup J Deane ◎ ΔHA0-2714
146 Toth Raymond J ◎ ΔHA0-1747

114

FREDERICK PARKWAY—From 100 blk E 3d av south, 1 east of C
271 Green Chas B ΔHA0-3344
277 Sauter CarlA ΔHA0-4729
281 Davis Maude Mrs ΔHA0-3080
Carter Newton E ΔHA0-3080

118

G—From 400 Hilltop dr east
14 Hymas Leonard C ◎ ΔGA2-7025
15 Morgan Lee J ΔGA2-0126
30 Coleman Jack A ◎ ΔGA2-0721
36 Conklin Roland H ◎ ΔGA2-1601
39 Silveyra Augustine ◎ ΔGA2-0205
42 Smith Cecil W ◎ ΔGA2-4126
48 Smith Howard R ◎ ΔGA2-0582
52 Nickelson Nicholas W ◎ ΔGA2-2479
55 Moss Frank ◎ ΔGA2-8127
60 Young Guy K ◎ ΔHA0-5168
66 Hondius Peter ◎ ΔGA2-2277
70 Markey Clifford F ΔHA0-6341
71 Merrell Howard E ◎ ΔHA0-5600
77 Merrick Norma E ◎ ΔGA2-6863
78 Thompson Margt L Mrs ◎ ΔGA2-1938
83 Chenoweth Eug T ◎ ΔGA2-2016
84 Vacant
86 Downs Kenneth R ◎ ΔGA2-5767
87 Jensen Wm P ◎ ΔGA2-4557
90 Scotford Wm L ◎ ΔHA0-4148
93 Jaenisch Otto ◎ ΔGA2-6595

1st av intersects
102 Axsom Marvin L ◎ ΔGA2-5752
108 Gosney Lawrence O ◎ ΔGA2-0595
111 Dale Robt G ◎ ΔGA2-6217
115 Laird Harold L ◎ ΔGA2-6039
121 Avery Vernon ◎ ΔHA9-5689

Alpine av intersects
130 Kagey Clarence C ◎ ΔGA2-6565
134 Stebbings Chas L ◎ ΔGA2-9049
135 Phillips Roscoe ◎ ΔGA2-7494
140 Gordon Chas S
141 Allen Virgil ◎ ΔGA2-3797
146 Dittenhaver Neil B ◎ ΔGA2-4153
147 Coben Chas E ◎ ΔGA2-7648

Del Mar av discontinues
152 Vacant
155 Pitchford Luther G ◎ ΔGA2-7646
156 Pennington Martin L ◎ ΔHA0-2600
rear Smith Ollie V Mrs ◎ ΔHA0-4423
159 Larson Geo H ◎ ΔHA0-2642
160 Chlarson Harvey G ◎ ΔGA2-3240
161 Limbach Casper A ◎ ΔGA2-6309
163 Sutton Thos W ◎ ΔGA2-6296
164 Mattson Matt W ◎ ΔGA2-2376
167 Beveridge Warren R ◎ ΔGA2-5424
170 Novak Chas ◎ ΔGA2-3671
173 Breen Danl F ◎ ΔGA2-8591
174 Hill Geo V ◎ ΔGA2-1717
177 Cureton Celesta W Mrs ◎ ΔGA2-5625
181 Turner Pauline C Mrs ◎ ΔGA2-6313
182 Willard Chas J ◎ ΔGA2-1755
186 Barnes Leo A ◎ ΔGA2-6768
rear Olsen Kristine A Mrs ΔGA2-7052
194 Copeland Wm D ◎ ΔGA2-1784
195 Alvarez Frank F
197 Mynders Jos H ◎ ΔGA2-6656
198 Vaught Kay K Mrs ◎ ΔGA2-2192

106

2d av intersects
202 Burtis Laura J Mrs ◎ ΔGA2-4141
203 Sharpe Steph F ΔHA0-4470
207 Amos E Harrison ◎ ΔGA2-0638
210 Ladd Leonard E ΔGA2-6456
211 Cesena Ildralfo ◎ ΔGA2-1632
215 Ryan Alva jr ◎
217 Damm LeRoy W ◎ jwlry mfrs ΔGA2-4285
222 Warren Carlyle ◎
223a Vacant
223b Sparby Aune V Mrs
223c Rasmussen Keith L
227 Forrest Walter W ◎ ΔFA2-1023
227½ Wyatt Clark E ΔHA0-6714
228 Williams Roger K ◎ ΔGA2-4624
229 Woodend Myrtle M ◎ ΔGA2-2640
233 Gustafson E A ΔGA2-6437
236 Shadley Rex E ◎ ΔHA0-9642
240 Thomas Jesse M ◎ ΔGA2-4252
241 Johnson Willard S ΔHA0-4204
244 Lilleyman Luke J
244½ Arnell Fred C
246 Parker Delbert ΔHA0-3354
248 Floor John
248½ West Robt H ΔGA2-3239
250 Hopkins Mildred E Mrs ΔGA2-3531
250½ Coombs Troy ΔHA0-7262
252 Weaver Robt C
252a Reckerd Chas ◎ ΔGA2-1613
252b Bolden Ann
252c Castiglione Andrew ΔHA0-7845
252d Vacant
252e Vacant

DelMar av intersects
264a Logan Gerald L
264b McTaggart Roy
264c Goodwin Dan
264d O'Brien Jas ΔHA0-5789
264e Dunlap Christopher
264f Vacant
268a Clark Mary Mrs
268c Ascolese Anthony
268d Elias Richd
268e Hultz Ann
274 Simard Paul O ◎ ΔGA2-1945
277 Vacant

Church av intersects
281 Norris Wendell W ΔGA2-4132
282 Guaranteed Homes bldg contrs ΔHA0-8881
283 Gove Dwight Agcy Inc ins ΔGA2-1049
rear Vacant
284 South Bay Realty ΔHA0-9880
287 Crites Chas J ◎ ΔGA2-2666
289 Maguire Henry F phys ΔHA0-5050
Mankin Jas W phys ΔHA0-5050

108

3d av intersects
310 **VanDyke Apartments**
1 Vacant
2 Kidd Richd M ΔGA2-6341
3 Garrison Wilma A ΔHA0-5817

G ST 1960

G--Contd
310 VanDyke Apts—Contd
4 Brown Norberta Mrs ΔGA2-4232
5 Vacant
6 Vacant
7 Vacant
8 Mayfield Barbara E ΔGA2-6617
9 Larson Betty Mrs ΔHA0-4171
10 Vacant
11 Noffsinger John H ΔGA2-6063
12 DeSpain Wm S ΔHA0-6848
13 Howell Henry
14 Heaney Chas T ◎ ΔGA2-1676
15 Wagner Sarah L Mrs ΔGA2-0236
16 Hasfurther Vincent J ΔGA2-8573
17 Daniels Andrea M ΔGA2-3589
Street continued
311 Allen Flo Mrs ΔHA0-5747
315 Johnston Jane A Mrs ΔGA2-5431
316 Bahns Leonard ΔHA0-1628
Cash Glenna A ΔHA0-6627
Trittle Paul ΔGA2-8435
317 Howe Gertrude G Mrs ◎ ΔGA2-1637
318 Moranda Maria Mrs◎ ΔHA0-3151
319 Cleveland Wm
320 **Apartments**
1 Scott Paul K ΔGA2-1550
2 Hensler Clem L ΔGA2-2018
3 Cloud E Jessie Mrs ΔHA0-5855
4 Skelton Wm W
5 Widdel Ann
6 Henpel Viola H
7 Vacant
8 Rogers Frieda Mrs
9 Williams Ronald R
10 Wittrock Eliz C Mrs
11 Abamia Maxio
12 Barnett J T
Street continued
321 No Return
323 Smith Frances Mrs ◎ ΔGA2-0277
325 Chambers Jas ΔHAΔ-1732
329a Harrell A Blanche ◎ ΔGA2-2103
329b Buck M W ΔGA2-0275
329c Fahring Jane K Mrs ΔGA2-0876
Blanchard Florence A Mrs ΔGA2-3989
330 Landau Mary L Mrs ◎ ΔGA2-4741
332 Redman Guy R ◎ ΔGA2-4544
333 Tague Glen M ◎ ΔGA2-2378
335 Magata Geo ΔHA0-8702
Flenry Louis
336a Wolfe Helvetia Mrs ΔHA0-2796
336b Higgs Vina Mrs ΔGA2-5025
336c Stone Joanne M Mrs
336d Thorpe Francis
340a Batty Mary A Mrs ΔGA2-3560
340b Marck Leonard G ΔGA2-0015
340c Kovasics Louis ΔGA2-1542
340d Randolph Donald B ΔGA2-1995
341 Fox Jesse B ◎ ΔGA2-1460
Garrett av intersects
344 Brooks Idella M Mrs ◎ ΔGA2-5274
350 Baskin Mary Mrs ◎ ΔGA2-2311
354 Talnadge Stephen ◎ ΔGA2-4159
357 Chula Vista Fuschia Society ΔGA2-4515
Chula Vista Women's Club ΔGA2-4515
Chula Vista Junior Women's Club ΔGA2-4515
Chula Vista Toastmistress Club ΔGA2-4515
363 Richardson Robt W ◎
364 Black Clara A Mrs ◎ ΔGA2-4452
367 Hubbert Geo N ◎ ΔGA2-2235
368 Andrews Archie A ◎ ΔGA2-2085
370 Seeley Robt
371 Lamb Louise Mrs ΔGA2-0423
372 Been Hansell E ◎ ΔGA2-3513
374 Slinkard Wm C ◎ ΔGA2-2124
379 Wolfe Ernest B ◎ ΔGA2-2824
381 Pittman Edw E ◎
385 Muller Robt F ΔGA2-4215
rear Vacant
386 Greenfield Leonard C ◎ ΔGA2-3949
390 Boyd Richd M ΔGA2-0328
394 Edwards E C ΔHA0-8352
399 Vanderveen Theo J ◎ ΔGA2-1785

110

4th av intersects
402 Cushman Francis R ΔGA2-8137
404 Vacant
406 Huth Wilbur W ΔGA2-2159
408 McPhearson Fred ΔGA2-8942
410 Hayde Robt T
411a Vacant
411b Henneberger Robt P
411c Vacant
412 Vacant
414 Buchborn Herbert L ΔGA2-9515
415 Kearns Alice H Mrs ◎ ΔGA2-2207
416 Genaw Jas R ΔHA0-5434
418 Hamels Adrian F ΔHA0-3825
419 Vacant
420 LeRiche Rita C Mrs
422 Robb Douglas A ΔHA0-4609
423 Curry Carl J ΔHA0-2813
424 Wallace Alf D
424a Holden Fredk A
424b Savoy Donald ΔHA0-3315
424c Spears John J ΔHA07469
424d Ring Stanley C ΔHA0-4162
424e Zurek Steph
424f Vacant
424g Wooten C B ΔHA0-8346
427 Mosbarger Jas M ◎ ΔHA0-2832
431 Foley Don M ◎ ΔHA0-2001
435 Button Roger ◎ ΔHA0-1837
439 Owens Robertson H ◎ ΔGA2-2156
439½ Tappan Ralph
443 Davidson Donald F ◎ ΔGA2-2349
447 Pullins Delmas D ◎ ΔGA2-2917
rear Pullins Leland J ◎
453 SanMartin Filemon ◎ ΔGA2-2232
459 Crow Donald ◎ ΔGA2-5000
rear Strayer Ora E Mrs ΔHA0-5640
463 Slotten Henry ΔHA0-6184
469 Luckie Leo L ◎ ΔGA2-1429

G--Contd
473 Burke LaVerne F Mrs ◎ ΔGA2-3440
479 Washlewski Carl R
481 Price Bryan F ◎ ΔGA2-2673
485 Gilman Tora A Mrs ◎ ΔGA2-0276
489 Papich Jack ◎ ΔGA2-4972

E 5th intersects

503 Skitch John A
507 BonnerGuy E ◎ ΔGA2-0448
511 County Agrl Comnr ΔGA2-2622
515 Wiltshire Wallace W ΔGA2-6298
rear Hennings R E
519 Rice John E jr ΔGA2-8755
521 Yantis Fern ΔHA0-3760
521a Vacant
521b Gilbert Phillip A ΔHA0-1490
521c Vacant
521d Miller Thelma L Mrs ΔHA0-8206
525 Perin Maria Mrs ◎ ΔGA2-4375
529 Morse Steph K ΔHA0-9727
531 Berg Robt L ◎ ΔHA0-3571
535 Funk John A ◎ ΔGA2-4563
539 Austin C Betty Mrs ΔGA2-5485
540 Vista Square Sch ΔGA2-8374
541 Vacant
541½ Vacant
543 Vacant
543½ Nelson Stanley W ΔGA2-7753
547 Vacant
549 Massengale Magness

Smith av intersects

553 **Apartments**
(A) Boucher Richd A ΔHA0-6616
(B) Coddington Archie T ΔHA0-4708
(C) Hilban John R ΔGA2-4766
(D) Peery Lillian R Mrs ΔGA2-7445
556 Syme Edw H ΔHA0-7421
560 Skibbe Errol L ◎ ΔGA2-7779
561 Hyatt Ray L jr ΔHA0-5119
Allen Wm D
564 Cole Jerry E ◎
567 Hendrex Ralph ◎ ΔHA0-6542
568 Gonzalez Victor ◎ ΔGA2-5851
571 Ford Joel P ◎ ΔHA0-2528
574 Vacant
580 Algert Henry W civil eng ΔGA2-1226
581 Woods Ray
583 Aranda Carlos G ◎ ΔGA2-1742
585 Churning Robt R ◎ ΔGA2-5248
586 Binks Jean School of Dancing ΔGA2-8155
589 Kelsey Warren M ◎ ΔGA2-8166
590 Haas Beauty Ranch beauty shop ΔGA2-9332
594 Chula Vista Blue Print Co ΔHA0-5500

136

Broadway intersects

605 Mills Benj L
850 Harms Edw W ΔGA2-1216
856 Hobart Homes Inc bldg contrs ΔGA2-8361
Johnson H H Constn Co bldg contrs ΔGA2-8361
Johnson H H Development Co bldg contrs ΔGA2-8361
Johnson H H Inc bldg contrs ΔGA2-8361
Morgan John B Constn Co ΔGA2-8333
Wilco Development Co real est ΔGA2-1173
610 Linthicum Anna L Mrs ◎ ΔGA2-1540
610a Moffett Newton
610b Benton Jas T ΔHA0-6347
628 Traukel Maurice D ◎ ΔGA2-1974
629 Howell Agnes P Mrs ◎ ΔGA2-3651
644 Culnan Edgar B ◎ ΔGA2-6321
rear Williams Donald
649 Mullenix Robt D
677 Terry's Trailer Park ΔGA2-0242
Roos Cornelis ΔGA2-0242
691 Garcia Esther Mrs ◎ ΔGA2-2768

Bay blvd intersects

731 Cabrillo Mobile Lodge ΔGA2-0245
Rictor Alf
Pierson Wm E
772 Bollin John T ΔGA2-2725
744 Romaine Van
776 Vacant
809 Tyce Engineering Corp air craft parts ΔGA2-0191
Williams Harry L bldg contrs ΔGA2-1133
Seabrook Reginald S loans ΔGA2-1173
ft Animal Shelter ΔGA2-2669

114

GARRETT AV—From 350 D south

106 Fisher Royden K ΔHA0-0115
109 Lancaster Newman C ◎ ΔHA0-0029
110 Hutson Egbert R ◎ ΔHA0-1746
114 Box Gordon T ◎ ΔHA0-3418
115 Buch Roger L ΔHA0-8943
116 Box Nona Mrs ◎ ΔHA0-3593
116½ Anderson Lena S ΔHA0-2809
118 Hollenback Earton J ΔHA0-0979
119 Marshall Bert O ◎ ΔHA0-2045
120 Fluss Martha L Mrs
120a Vacant
120b Weinhold Laurence W ΔHA0-2555
120c Nelander Bertha Mrs ◎ ΔHA0-0564
121 Ross Gene C contr ΔHA0-8815
Reorganized Church of Jesus Christ of Latted Day Saints ΔCY5-9391
124-34 **Somerset East Apts** ΔGA2-3172
124a Johnson Mildred J Mrs ΔHA0-4525
124b Vacant
124c Vacant
124d Smith Robt S ΔHA0-5889
124e Strickler Ernest H ΔHA0-5615
124f Skeoch Phyllis Mrs
124g Noonan Albert W jr ΔHA0-7840
124i Shreaves Edw W ΔGA2-0584
124½a Martinez Leonard
124½b Vacant
124½c Vacant
124½d McDade Sharon J ΔGA2-6357
125 Wise Airel B Mrs ◎ ΔHA0-4596
126a O'Malley Edith Mrs ΔHA0-3329
126b Sennett Harley
126c Johnson Dorothea I ΔHA0-6711
126d Gerlach Jas
126e McMickell O L ΔHA0-4548
126f Hatfield Josephine ΔGA2-1482
128a Brown Rex D ΔGA2-7071
128b Gray John R
128c Fullerton Jas R ΔHA0-8216
128d Vacant
128e Machnicki Mitchell R ΔGA2-8454
130a Vacant
130b Vacant
130c Vacant

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1955

FRONTAGE RD—Contd
Dorothy intersects

18

G—West from 400 Hilltop dr to city limits
ft Animal Shelter ΔGA2-2669
39 Silverya Augustine ®
41 Vacant
52 Nicholson Nicholas W ® ΔGA2-2479
55 Moss Frank ® ΔGA2-8127
60 Dwarniczak Jos ® ΔGA2-4406
66 Hondius Peter ® ΔGA2-2277
70 Schock Chas O jr ΔGA2-4639
71 Smole Cath Mrs ® ΔGA2-3418
77 Menick Norma E ® ΔGA2-6863
78 Thompson Raymond L ® ΔGA2-1938
83 Cheneweth Eug T ® ΔGA2-2016
84 Jenkins Sidney R ® ΔGA2-4780
86 Downs Kenneth R ® ΔGA2-5767
87 Jensen Wm P ® ΔGA2-4557
90 Menzel Louisa C E Mrs ® ΔGA2-6139
93 Wigington John ® ΔGA2-6460
1st av intersects
102 Axsom Marvin L ® ΔGA2-5752
108 Dew Jas C jr ® ΔGA2-6096
111 Lami Weikko S ® ΔGA2-3514
115 Laird Harold L ® ΔGA2-6039
127 Logan Theo J ® ΔGA2-7636
Alpine av resumes
130 Kagey Clarence C ® ΔGA2-6565
134 Walker Anna C Mrs ® ΔGA2-6544
135 Phillips Roscoe ® ΔGA2-7494
140 Sacks Eug ® ΔGA2-6035
146 Dittenhaver Neil B ® ΔGA2-4153
147 Coben Chas E ® ΔGA2-8082
DelMar av discontinues
152 Erickson Kenneth
155 Layne Edsal E
156 Walters Dorothy Mrs ΔGA2-7769
159 Jordon Fred A ® ΔGA2-1907
160 Chlarson Harvey G ® ΔGA2-3204
161 Limbach Casper A ® ΔGA2-6309
163 Burg Raymond L ® ΔGA2-6219
164 Rendigs Walter ®
167 Bevridge Warren R ® ΔGA2-5425
170 Novak Chas H ® ΔGA2-3671
173 Breen Danl F ® ΔGA2-2447
174 Gates Erwin L ® ΔGA2-8002
177 Cureton Sam W ® ΔGA2-5625
181 Turner Britton D ® ΔGA2-6313
182 Willard Chas J ® ΔGA2-1755
186 Befort Geo L ® genl contr ΔGA2-4772
194 Copeland Wm D ® ΔGA2-1784
195 Strause Rufulo Mrs
197 Ivie Curtis B
198 Vaught Robt G ® ΔGA2-2192

6

2d av intersects
202 Burtis Earl K ΔGA2-4141
203 Beck Robt V ® ΔGA2-7276
207 Amos E Harrison ® ΔGA2-4954
210 Dennison Ralph A ® ΔGA2-5232
211 Cesena Illerolfo ® ΔGA2-1632
215 Parks Ray E
217 Damm LeRoy W ® ΔGA2-4285
222 Rosvall Otto W ® ΔGA2-2611
223a Thompson Roy H
223b Craig Wm
223c Vacant
227 Forrest Walter W ® ΔGA2-1023
Hall Frances L ΔGA2-4624
227½ Vargas Delia
228 Williams Roger K ® ΔGA2-4624
229 Kahler Lillian Mrs ®
233 McGrath Jas B ΔGA2-5694
236 Shadley Rex E ®
240 Thomas Jesse M ® ΔGA2-4254
241 Bennington Mabel E Mrs ® ΔGA2-1513
244 Racik Stanley ΔGA2-0629
244½ Corkill Guy G ΔGA2-2944
246 Hammerle Frank A ΔGA2-7002
248 Willem Rene E
Winthrop Andrew A ΔGA2-0306
250 Cecil Donald L ΔGA2-3466
250½ Bullen Russell H jr ΔGA2-0223
252 Beasley Harriett Mrs ® ΔGA2-1554
DelMar av ends
274 Benger Minnie Mrs ® ΔGA2-1945
277 Hall Frances L Mrs Δ2-1798
Church av intersects
281 Downs Rolin O ® ΔGA2-1275
283 Gove Dwight Ins Agcy ΔGA2-0149
Junior Chamber of Commerce ΔGA2-7940
287 Crites Chas J ® ΔGA2-2666
289 McClary Robt W osteo ΔGA2-8311
Sheetz Martin A osteo ΔGA2-8311

8

3d av intersects
310 VanDyke Apartments
Apartments:
1 Wilson Madge Mrs
2 Kidd Richd M ΔGA2-6341
3 Bright Lois
4 Vacant
5 Mack Nellie M ΔGA2-0608
6 Cooper Daisy Mrs ΔGA2-4709
7 Vacant
8 Mayfield Barbara
9 Boyden Donald L ΔGA2-3055
10 Winegarden Sam
11 Noffsinger John
12 Crabb Saml L ΔGA2-2319
13 Hasfurther V G
14 Heaney Chas T ®
15 Wagner Sarah
16 Brown Bess
17 Daniels Andrea
Street continued
311 Hudson Mabel F Mrs ΔGA2-0277
315 Thompson Nettie ΔGA2-1505
316 Dale Robt G ® ΔGA2-6217
317 Howe Gertrude G Mrs ® ΔGA2-1637
318 Morando Marie Mrs ®
319 Scott Jas C ΔGA2-5150
320 Apartments
1 Boyd Atherton S
2 Fernandez Chas
3 Etchnique Regina Mrs
4 Millard Jess B
5 Kircher Glen
6 Wasserman Abe ® ΔGA2-4497
Street continued
321 Bussey Clarence V ΔGA2-3861
323 Maner Wm F ΔGA2-3908
325 Barber Winnie ΔGA2-3761
329a Harrell A Blanche ® ΔGA2-1203
329b Page Charlotte M ΔGA2-1575
329c Buck M W ΔGA2-0275
329d Blanchard Florence A ΔGA2-3989
330 Landau Orphus B ® ΔGA2-4741
332 Redman Guy R ® ΔGA2-4544
333 Tague Glen M ® ΔGA2-2378
335 North Jas G ΔGA2-1707
336a Ritz John H ΔGA2-5525
336b Higgs Vina Mrs
336c Pike Phillip A ΔGA2-2593
336d Sheppard Roy E
340a Batty Tom ΔGA2-3560
340b Lange Arth H ΔGA2-5398
340c Bergquist Fred
340d Fasig Wayne R
341 Fox Jesse B ® ΔGA2-1460
Garrett av intersects

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1955

G—Contd
344 Brooks Idella M Mrs ® ΔGA2-5274
350 Baskin Andrew C ® ΔGA2-2311
354 Talnadge Stephan ΔGA2-4159
357 Chula Vista Women's Club ΔGA2-4515
Chula Vista Junior Womens Club ΔGA2-4515
Junior Chamber of Commerce
Chula Vista Theatre Guild
Chula Vista Lions Club
South Bay Christian Ch
363 Tyce Roland ΔGA2-1933
364 Black Loris E ® ΔGA2-4452
367 Fuller Edwin C ΔGA2-2235
368 Andrews Archie A ® ΔGA2-2085
371 Lamb Louise ΔGA2-0423
372 Little Betty T Mrs ® ΔGA2-1975
374 Slinkard Wm C ® ΔGA2-2124
379 Wolfe Ernest B ® ΔGA2-2824
385 Mullen Robt F ® ΔGA2-4215
386 Greenfield Leonard C ® ΔGA2-3949
390 Wilks Kenneth D
394 Morton Jack E ® ΔGA2-3257
399 Hartman Wm ® ΔGA2-7982

10

4th av intersects

402 Gain Robt F ΔGA2-3217
404 Anderson Geo R
406 Huth Wilbur W ΔGA2-2159
408 Pearce Merlin C
410 Bellarts Lawrence P ΔGA2-3890
411 Harper Edna O ® ΔGA2-2088
Somers Gordon E ΔGA2-5640
412 Sell Caroline J ΔGA2-1482
414 Eberspacher Robt
415 Franks Jas M ® ΔGA2-4118
416 Tucker Donald C ΔGA2-7979
418 Crabbe Wallis J
419 Rader Jessie H Mrs ΔGA2-2962
420 Vacant
422 Thomas Geo W ΔGA2-6576
423 Montiel Geo E ® ΔGA2-2788
424 Reid Walter C ΔGA2-8108
427 Vacant
431 Price Edw ® ΔGA2-4437
435 Leonard Bert H ® ΔGA2-5147
439 Owens Robertson H ® ΔGA2-2156
443 McGregor Vernon R ® ΔGA2-2845
447 Pullins Delmas D ® ΔGA2-2917
453 SanMartin Filemon ® ΔGA2-2232
459 Donica John W ®
463 Miller Frank H ® ΔGA2-6009
469 Luckie Leo L ® ΔGA2-1429
473 Eller Kenneth F ® ΔGA2-2986
479 Culp Glen ® ΔGA2-4433
481 Price Bryan F ® ΔGA2-2673
485 Gilman Tora A Mrs ® ΔGA2-0276
489 Papich Jack ® ΔGA2-4972

E 5th intersects

cor 5th Vista Square Elem Sch
503 Forseth Martin F ® ΔGA2-5754
507 Bonner Guy E ® ΔGA2-0448
511 County Office Insectory
515 Swayne Mary Mrs ®
519 Rauzon Geo D ΔGA2-2414
525 Leake Anna B Mrs ® ΔGA2-1733
535 Funk John H ®
539 Thompson Donald R ΔGA2-0593
540 Vista Square Sch
541 Padilla Carmen Mrs
547 Overstreet Price E jr ΔGA2-6668
549 Pfaff Burdette L

Smith av resumes

555 Holmes Fred ®
556 Humble Asa H ® ΔGA2-4785
557 Bennett Margt Mrs ® ΔGA2-4219
560 Nabort Chas E ΔGA2-7387
564 Parkinson Milton E ® ΔGA2-2449
568 Gonzalez Victor ® ΔGA2-2581
583 Aranda Carlos G ® ΔGA2-1742
585 Churning Robt R ® ΔGA2-5248
589 Kelsey Warren M ®

36

National av intersects

610 Linthicum Everett C ® ΔGA2-1540
610a Polk Jerry
610b Swaboda Robt
628 Woodward Chas W ΔGA2-7423
629 Howell Agnes P Mrs ® ΔGA2-3651
644 Culnan Edgar B ® ΔGA2-6321
691 Garcia Manuel ® ΔGA2-2768
698 Azuma Takeo ® ΔGA2-3220

Bay blvd intersects

772 Bolin Jeff J ΔGA2-3776
774 Bolin John T ΔGA2-2725
809 Tyce Engineering Corp air craft parts ΔGA2-0191
848 Pioneer Pyrophyllite Producers insect powder mfrs ΔGA2-2992
Redlite Aggregate Co bldg matls ΔGA2-2992
850 Harms Edw W ΔGA2-1216
856 **Construction Service Bldg**
Cotton Constn ΔGA2-5371-72
Edwards Leslie H Co ΔGA2-5319
Electrical Constructors ΔGA2-1173
Hobart Homes Inc real est ΔGA2-1175
Johnson H H Constn Co genl contrs ΔGA2-1171
Johnson H H Inc genl contrs ΔGA2-1171
Williams Harry L genl contrs ΔGA2-1133

14

GARRETT AV—South from D to F, thence south from Park way to G, thence south from Mankato 1 block

106 Bristoll Arth F Δ1008J
109 Lancaster Newman C ® Δ60M
110 Hutson Egbert R ® Δ746W
114 Box Gordon T ®
115 Kirby John E ® Δ1280W
116 Box Nona Mrs Δ1168R
rear Anderson Lena Mrs
118 Hart Carten M ® Δ1545W
119 Bernhard John W Δ418J
120 Nelander Bertha Mrs ® Δ364J
121 Joseph Gernie A ® Δ52M
125 Wise John J ® Δ1168J
131 Edwards John J ®
135 Alexander Merrill S Δ1592
136 Jack Robt K ® Δ1545R
139 Stockton Lee B ® Δ1176W
143 Bush Jos V ® Δ741W
147 Tschogl Florian C ® Δ417W
152-64 **Cromwell Apartments**
Apartments:
20 Davis Florence Mrs Δ802M
21 Tankersley Paul M Δ857J
22 Mathes Reba V Mrs
23 Munoz Geo G
24 Coppin Jack H
25 Jackson Mildred A Δ802R
Street continued
155 Butler Rayford ® Δ1581J
156 **Apartments**
14 Lewis Russell T Δ401
15 Felheim Louis L Δ802J
16 Fink Wm S Δ364W
17 Miller Ray E
18 Fieselman W B
19 Anderson Ruth M Mrs Δ417J
Street continued
159 Lange John E ® Δ899W
160 **Apartments**
7 Norton Wm G Δ60R
8 Vacant

Parcel B Buildings - Former Collins Aerospace
850 Lagoon Drive
Chula Vista, CA 91910

Inquiry Number: 6344626.1
January 29, 2021

The EDR-City Directory Image Report

Environmental Data Resources Inc
6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY


DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.



RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2017	☑	☐	EDR Digital Archive
2014	☑	☐	EDR Digital Archive
2010	☑	☐	EDR Digital Archive
2005	☑	☐	EDR Digital Archive
2000	☑	☐	EDR Digital Archive
1995	☑	☐	EDR Digital Archive
1992	☑	☐	EDR Digital Archive
1986	☑	☐	Haines Criss-Cross Directory
1982	☑	☐	Haines Criss-Cross Directory
1979	☑	☐	Haines Criss-Cross Directory
1975	☑	☐	Haines Criss-Cross Directory
1971	☑	☐	Haines Criss-Cross Directory
1965	☑	☐	POLK DIRECTORY CO
1960	☑	☐	POLK DIRECTORY CO
1955	☑	☐	POLK DIRECTORY CO

EXECUTIVE SUMMARY

Year	***Target Street***	***Cross Street***	***Source***

FINDINGS

TARGET PROPERTY STREET

850 Lagoon Drive
Chula Vista, CA 91910

Year	*CD Image*	*Source*
G ST		
2017	pg A2	EDR Digital Archive
2014	pg A10	EDR Digital Archive
2010	pg A17	EDR Digital Archive
2005	pg A24	EDR Digital Archive
2000	pg A31	EDR Digital Archive
1995	pg A37	EDR Digital Archive
1992	pg A44	EDR Digital Archive
1986	pg A47	Haines Criss-Cross Directory
1986	pg A48	Haines Criss-Cross Directory
1982	pg A49	Haines Criss-Cross Directory
1982	pg A50	Haines Criss-Cross Directory
1979	pg A51	Haines Criss-Cross Directory
1979	pg A52	Haines Criss-Cross Directory
1979	pg A53	Haines Criss-Cross Directory
1975	pg A54	Haines Criss-Cross Directory
1975	pg A55	Haines Criss-Cross Directory
1971	pg A56	Haines Criss-Cross Directory
1971	pg A57	Haines Criss-Cross Directory
1971	pg A58	Haines Criss-Cross Directory
1965	pg A59	POLK DIRECTORY CO
1960	pg A60	POLK DIRECTORY CO
1960	pg A61	POLK DIRECTORY CO
1955	pg A62	POLK DIRECTORY CO
LAGOON DR		
2017	pg A8	EDR Digital Archive
2014	pg A15	EDR Digital Archive
2010	pg A22	EDR Digital Archive
2005	pg A29	EDR Digital Archive

FINDINGS

Year	CD Image	Source	
2000	pg A35	EDR Digital Archive	
1995	-	EDR Digital Archive	Target and Adjoining not listed in Source
1992	-	EDR Digital Archive	Target and Adjoining not listed in Source
1986	-	Haines Criss-Cross Directory	Street not listed in Source
1982	-	Haines Criss-Cross Directory	Street not listed in Source
1979	-	Haines Criss-Cross Directory	Street not listed in Source
1975	-	Haines Criss-Cross Directory	Street not listed in Source
1971	-	Haines Criss-Cross Directory	Street not listed in Source
1965	-	POLK DIRECTORY CO	Street not listed in Source
1960	-	POLK DIRECTORY CO	Street not listed in Source
1955	-	POLK DIRECTORY CO	Street not listed in Source

MARINA PKWY

2017	pg A9	EDR Digital Archive	
2014	pg A16	EDR Digital Archive	
2010	pg A23	EDR Digital Archive	
2005	pg A30	EDR Digital Archive	
2000	pg A36	EDR Digital Archive	
1986	-	Haines Criss-Cross Directory	Street not listed in Source
1982	-	Haines Criss-Cross Directory	Street not listed in Source
1979	-	Haines Criss-Cross Directory	Street not listed in Source
1975	-	Haines Criss-Cross Directory	Street not listed in Source
1971	-	Haines Criss-Cross Directory	Street not listed in Source
1965	-	POLK DIRECTORY CO	Street not listed in Source
1960	-	POLK DIRECTORY CO	Street not listed in Source
1955	-	POLK DIRECTORY CO	Street not listed in Source

MARINA PKY

1995	pg A41	EDR Digital Archive
1992	pg A45	EDR Digital Archive

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017

677

AHRENS, CLAUD
ALFARO, JEFF
AMAYA, LUZDEL C
ARANDA, MARIA G
ARGUELLO, MIGUEL M
ARROYO, ROSA C
ARSENAULT, JOHN E
AUDLEY, EDWARD F
AUSTRIA, PRESCILA
AVILES, MARCELA V
BAILEY, ROBERT
BERGERON, RAYMOND J
BESHEARS, IMELDA M
BIGGERS, DOROTHY R
BLANCK, SKIP
BLINN, GLEN E
BOLDRIDGE, LEON I
BREARLEY, WALTER D
BROWNING, DALIA O
BUCHANAN, PAUL
BUTTERWORTH, MARCELLE S
BYRD, VELVA J
CAMPOS, HERMELINDA
CARRANZA, JENNIFER
CASKINETTE, RICHARD J
CASTRO, FRED H
CEJA, RODOLFO M
CHRISTENSEN, BRENDA
CLARK, PATRICIA A
COMMER, RAFAEL
CONNOLLY, ANGELINA G
CORTEZ, JOHNNY M
CRABBE, MICHAEL P
CRIE, WILLIAM D
CROCKETT, BONNIE W
CRUMP, DANIELLE A
DELCAMPO, ENRIQUE M
DUGAN, DON N
EDWARDS, CLAUDE G
EPSTEIN, RANDY P
ESCOTO, REYES G
FAIRLEE, LARRY L
FERNANDEZ, JOSE L
FRANCOUR, SANDRA L
GENTZ, LINDA I
GINDROZ, ROBERT J
GOMEZ, MICAELA L
GOMEZ, PABLO
GONZALEZ, JOSE A
GONZALEZ, LORETO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

677
GRAVES, DAVID
GRAVES, REBECCA
GUERRA, JOE R
HAHN, RAY A
HALL, DONALD W
HEDGE, WILLIAM A
HERMOSILLO, MARIA L
HERNANDEZ, GUADALUPE
HERNANDEZ, MARCO
HERRERA, FRANCISCO J
HIGA, DOROTHY T
HOFF, RONNIE J
HOGAN, ALMA J
HUBERT, RICHARD L
IBANEZ, RUBEN N
JOHNSON, RONALD G
JONES, LAMAR R
KAMINS, SYBIL R
KANITZ, LEVY L
KELLOGG, HEIDI C
KIRKPATRICK, SARA
KRAMER, JAMES M
KRUPINSKI, DOUGLAS J
LEACH, JEFF F
LEGASPI, OSCAR L
LIMIN, ESTER M
LISTER, ROBERT R
LOZANO, ARMIDA
MACIAS, ADELINA
MAEVA, TUTAI
MANLEY, SARA J
MANNON, THEODORE T
MARK, DOROTHY
MARKEL, JOSEPH L
MARTINEZ, CARLOS L
MELENDEZ, ERNEST
MELVILLE, MARGARITA B
MEZA, MARCELA A
MORALES, ANDRES M
MORRIS, AARON B
MORRIS, REGINALD J
MOTL, STEVEN
MOYA, ELIZABETH
MUCH, JULIETTE E
MUSGRAVE, ROSE M
NEAL, JULIETTE M
NEWNHAM, EDITH L
ORAMAS, JOSEFINA O
OSUNA, ANA M
OURS, JUDITH E

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

677	PAGE, SYLVIA J
	PALOMARES, MARIANA
	PARMLEY, RONALD A
	PASSENEAU, CAROLYN S
	PEARSON, GLADYS M
	PETRA, CRUZ
	PRECIADO, PETRA G
	PROVENCHER, JANICE L
	RADINOVSKY, KATHRYN M
	READER, MALINDA S
	RIVERAASTACIO, JOSE E
	ROBBINS, BRUCE E
	ROCHA, JOSE
	ROSSETTI, RITA J
	SANDOVAL, DONNA J
	SCHLEGEL, JERRY J
	SHAFFER, ORLA
	SHAWBELL, LEWIS R
	SILVA, DAMIANA
	SMITH, CINDY L
	SPITZER, JOYCE L
	STINEBUCK, NANCY J
	SUNSET CAB
	TAAVASA, FRANKIE L
	TERRYS MOBILE PARK
	THAYER-STOKES, LAVERNE M
	TIMBOL, NENITA
	TORRES, MARK
	TURO, MARJORIE L
	VASQUEZ, ADELINA C
	VAZQUEZ, JOSE C
	VELASCO, ISAURA
	VIGIL, GREG F
	VILLAFUERTE, JOSE D
	VISTA, GLORIA
	VOGT, HERMELINDA M
	VOLLER, NORMA J
	WADELL, LORRAINE C
	WALKER, YONG C
	WATKINS, WILLIAM R
	WATSON, KENNETH D
	WESTON, NANCY O
	WITMER, MICHAEL P
	WOOD, CAROLYN F
	YOUNG, PAUL G
	ZAMUDIO, ORALIA G
	ZARAGOZ, ALBERTO N
	ZEPEDA, ROSA L
704	BARAJAS, MARTHA
	GARCIA, JUAN A

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

704	GARCIA, MARIA
716	CORONADO, HENRY H
	RAMIREZ, GABRIEL
	YOUSSOFI, TERESA
724	JOHNSON, STEVEN
	PHILLIP, MERVYN
	STIMPSON, MARY E
731	ACKER, JOHN S
	AGLIPAY, RONALD M
	ALEXANDER, MARIA S
	ANDERSON, BILLIE J
	ARCE, MARIA E
	BACALLAO, IRMA A
	BARRAGAN, PETRA P
	BEELES, RONALD G
	BENFER, ESPERANZA Z
	BONATUS, JACKIE D
	BOWLES, PEGGY D
	CABRILLO MOBILE HOME PARK
	CASTANEDA, ODILA
	CASTRO, PABLO
	CISNEROS, BULMARO
	CLAY, MARSHALL L
	CONTRERAS, MARIA
	CRUZ, REYNALDA N
	CUEVA, FILIBERTO C
	CUNARD, MARIA E
	DEMOORE, IRMA
	DORSCHER, SHEILA
	DUENAS-JR, RAMON J
	EASTWOOD, MARIA B
	ELIAS, MARTHA G
	ENCISO, MARIA M
	ESTRELLA, ELVIA
	FALLING, BILLY
	FIERRO, SILVINA
	GALEANA, FERNANDO
	GALEANA, MARIA
	GARCIA, RITA
	GLEASON, EDWARD J
	GOMEZ, ROSALINDA
	HAUSWIRTH, DENNIS J
	HEADLAND, JAMES N
	HERNANDEZ, ANGELICA L
	HERNANDEZ, EVA
	HERNANDEZ, JUAN S
	JUAREZ, JESUS A
	KARAKEY, APOLONI A
	LITTLE, MICHAEL D
	LUGO, ANGELINA L

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

731	LUPPENS, JOHN A
	MANJARREZ, MARIA C
	MARCUSSEN, BJORN B
	MAYBURY, KATHLEEN R
	MCGONIGLE, GARY R
	MEDINA, DAVID E
	MELVIN, JOHN H
	MENDOZA, PEDRO
	MILES, BOB P
	MILLER, JOSEPH R
	MOORE, IRMA C
	OLSON, ARACELI
	ORTEGA, FLAVIO
	ORTEGA, SARAH
	ORTEGA, ZENORINA
	OVERSTREET, JEAN L
	PALOMINO, PASCUAL
	PATRON, MARIA G
	PENA, MANUELA
	PENNERMAN, WILLIAM A
	PERRY, HARLEY L
	PRADO, GUADALUPE R
	REYES, IRMA
	REYNOSO, JESOS J
	RHOADES, TERRY M
	RICHARDS, ROBERT S
	ROMERO, NORMA B
	SAMANIEGO, GUILLERMO A
	SANCHEZ, EFRAIN
	SEGHERS, DOREEN H
	SIZE, KIM
	SPATIG, BETTY L
	TALAMANTES, PATRICIA
	TOBIE, SOTO G
	TOSCANO, VICTORIO A
	TROY, JOHN W
	TUMBOKON, ELVIRA L
	TURNIR, MAGDALENA
	URIBE, LUIS
	YOUNG, FLORENCE A
	ZARATE, MARIA A
	ZENORINA, ORTEGA
	ZIDLER, MILAGROS
	ZIGLER, MILAGROS D
	ZINN, ALEXANDRA C
736	DEJESUS, TOMAS M
	LOZANO, ASHLEY
	VELA, EDUARDO
	VELAZQUEZ, PRISCILLA
997	MARINE GROUP BOAT WORKS

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2017 (Cont'd)

997 TRUITT MACHINE & FABRICATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

LAGOON DR 2017

833 BANNER BANK ATM
850 GOODRICH AEROSTRUCTURES

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MARINA PKWY 2017

477	UNLIMITED PLACEMATS & MENUS
550	CHULA VISTA MARINA
	GALLEY AT THE MARINA
640	CALIFORNIA YACHT MARINA
642	ABRAZADO, ABRAHAM A
	ADMASSACHEW, NOEL A
	ALTMAN, BRAD J
	ARNESON, ELLA L
	BASMADJAN, ARAM
	BERRY, DEAN
	CIUDIN, CATALIN
	CONNER, AMY
	DUNING, JOHN L
	DUNING, PENNY S
	FITZGERALD, RICHARD D
	GRIMM, MICHAEL
	HUYNH, TAM H
	JOHNSON, RICHARD
	MALLEN, JOHN G
	MANISCALCO, CARL A
	MURRAY, DONALD
	REYNOLDS, STEVEN L
	RUDMAN, NORMAN C
	SCHEETZ, LINDA J
	SCHULTZ, MARK D
	SHELBY, CHARLES
	SHOEMAKER, OWENS M
	SUMMERVILLE, LARRY
	TOWNSEND, AL
	VINCE, WHALEN

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014

677	ACUNA, ROBERTO T
	AHRENS, CLAUD
	AMAYA, LUZDEL C
	ANDREWS, ELLIOTT
	ANES, ANA A
	ANGEL, MARIA E
	ARROYO, ROSA C
	ARSENAULT, JOHN E
	AUDLEY, EDWARD F
	BAILEY, ROBERT R
	BARRIOS, JOSE G
	BAUMGARDNER, LORAINE J
	BEERS, WESLEY J
	BERGERON, RAYMOND J
	BESHEARS, IMELDA M
	BIBO, ROBERT G
	BIGGERS, DOROTHY R
	BLANCK, SKIP
	BLINN, GLEN M
	BOLDRIDGE, LEON I
	BREARLEY, WALTER D
	BRIZUELA, ISMAEL H
	BROWNING, DALIA O
	BURKETT, SALLY R
	BUTTERWORTH, MARCELLE S
	BYRD, VELVA J
	CARRERA, CARLOS M
	CASTRO, FRED H
	CEJA, RODOLFO M
	CHRISTENSEN, BRENDA
	CHRISTIAN, MADELYN R
	CONNELLY, ROBERT W
	CRABBE, MICHAEL P
	CRIE, DON
	CURTIS, ROGER J
	DAKEL, AMBER
	DELCAMPO, ENRIQUE M
	DOERING, KENNETH M
	DOUGLAS, JEFFREY A
	DUGAN, DON N
	ESCOTO, REYES G
	FAIRLEE, LARRY L
	FERNANDEZ, JOSE L
	FRANCOUR, SANDRA L
	GENTZ, LINDA I
	GOMEZ, PABLO
	GONZALEZ, JOSE A
	GUERRA, JOE R
	HALL, DONALD W
	HARVEY, JERRY D

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2014 (Cont'd)

677	HEDGE, WILLIAM A
	HERNANDEZ, RAFAEL
	HERNANDEZ, RAMIRO
	HERRERA, FRANCISCO J
	HIGA, DOROTHY T
	HOFF, BRIAN E
	HOGAN, ALMA J
	HUBERT, RICHARD L
	JACKSON, DAISSE
	JARVIS, LEONARD G
	JOHNSON, RONALD G
	JONES, LAMAR R
	KAMINS, SYBIL R
	KANITZ, LEVY D
	KINCAID, FLORENCE I
	LAMB, GLORIA J
	LEGASPI, OSCAR L
	LIMON, EDUARDO G
	LISTER, ROBERT R
	LOZANO, ARMIDA
	MACIAS, ADELINA
	MAMANGUN, ZENAIDA Z
	MANLEY, SARA J
	MANNON, THEODORE T
	MARK, DOROTHY
	MARKEL, JOSEPH L
	MARSH, ANNE M
	MARTINEZ, MANUEL D
	MATHEWS, DORA M
	MAXWELL, TOM M
	MEILE, RALPH E
	MELENDEZ, ERNEST
	MELICIA, EUGENIO
	MELVILLE, THOMAS
	MORRIS, REGINALD J
	MOTL, STEVEN
	MUCH, JULIETTE E
	MURGUIA, ISSAC
	MUSGRAVE, ROSE M
	NEAL, JULIETTE M
	NEELY, BILLY J
	NEWNHAM, EDITH L
	NIETO, JAMES
	OH, WON Y
	OSUNA, ANA M
	OURS, JUDITH E
	OWN A PROPERTY REALTY
	PACELY, SILVIA
	PARKER, JOE M
	PARMLEY, RONALD A

G ST 2014 (Cont'd)

677 PASSENEAU, CAROLYN S
PEARSON, GLADYS M
PIERCE, MARY M
PIKE, MARTIN E
POE, LINDA L
PROVENCHER, JANICE L
RADINOVSKY, KATHRYN M
RAMIREZ, JOSIE
READER, MALINDA S
REED, EUGENE W
RIVERAASTACIO, JOSE E
ROACH, FRANK D
ROBBINS, BRUCE E
ROSSETTI, RITA J
SHAFFER, ORLA
SILVA, DAMIANA
SPITZER, JOYCE L
SUNSET CAB
TAAVASA, FRANKIE L
TAYLOR, CAROL
TERRYS MOBILE HOME PARK
THAYER-STOKES, LAVERNE M
TIMBOL, NENITA
TURO, MARJORIE L
ULRICH, JIM
VALLEJO, JOSE J
VALLIN, ESTEBAN
VASQUEZ, ADELINA C
VAZQUEZ, JOSE C
VIGIL, GREG F
VILLAFUERTE, JOSE D
VISTA, GLORIA
VOGT, HERMELINDA
VOLLER, NORMA J
WADELL, LORRAINE C
WALKER, JOHNNY E
WATSON, KENNETH D
WESTON, NANCY O
WISCHSTADT, CHRIS
WOOD, CAROLYN F
WRIGHT, BONNIE K
YOUNG, PAUL G
ZEPEDA, ROSA L

691 GARCIA, REBECA

704 CASTANEDA, FERNANDO F
GARCIA, JUAN A
NAVARRO, MARIA E
RUELAS, MARIA M
SMITH, HARVEY C

716 BENAVENTE, RICARDO

G ST 2014 (Cont'd)

716 CORONADO, HENRY U
RAMIREZ, GABRIEL
724 JOHN LAFFERTY
JOHNSON, STEVEN
STIMPSON, MARY E
731 ACKER, JOHN S
AGLIPAY, RONALD M
AHUMADA, ARTURO P
ALEXANDER, MARIA S
ANDERSON, BILLIE J
AYOTTE, JIM
BARRAGAN, PETRA P
BEELES, RONALD G
BENFER, ESPERANZA Z
BERMUDEZ, RAQUEL L
BERNAL, AL
BOWLES, PEGGY D
BROWN, PAUL R
CABRILLO MOBILE HOME PARK
CASTANEDA, ODILA
CHAVEZ, P
CISNEROS, BULMARO
CLAY, MARSHALL L
CONKLIN, STEVEN R
CONNER, RONALD D
CRUZ, REYNALDA N
CUNARD, MARIA E
DORSCHER, SHEILA
DUENAS-JR, RAMON J
EASTWOOD, MARIA B
ELIAS, MARTHA
EROS, JOEL
ESTRELLA, ELVIA
FALLING, BILLY
FARRIS, THOMAS
GALEANA, MARIA
GLEASON, EDWARD J
GOMEZ, ROSALINA
GONZALEZ, DAWNA R
GUERRA, TONY
GUTIERREZ, JUANA
HAUSWIRTH, DENNIS L
HEADLAND, JAMES N
HERNANDEZ, EVA
HERNANDEZ, JUAN S
HUNT, BRENT R
JUAREZ, JESUS A
KARAKEY, APOLONI A
KRASTINE, NANCY
LITTLE, MICHAEL D

G ST 2014 (Cont'd)

731	MANJARREZ, MARIA C
	MAPLE, GRAYDEON R
	MARCUSSEN, BJORN B
	MARISCAL, MARIA R
	MARTINEZ, MARIO A
	MAYBURY, KATHLEEN R
	MCGONIGLE, GARY R
	MELVIN, JOHN H
	MENDOZA, ROSA
	MILES, BOB P
	MILLER, JOSEPH R
	OCHOA, GERMAN
	PALOMINO, PASCUAL
	PARDEE, BARBARA J
	PATRON, MARIA G
	PENNERMAN, WILLIAM A
	PERRY, HARLEY L
	PERRY, RONALD K
	PRADO, GUADALUPE R
	RHOADES, TERRY M
	RICHARDS, ROBERT S
	RITCHIE, ELIDIA G
	ROMERO, NORMA B
	RUIZ, IRMA
	SAMANIEGO, GUILLERMO A
	SEGHERS, DOREEN H
	SIMPSON, TAMARA
	SPATIG, BETTY L
	TALAMANTES, PATRICIA
	TOBIE, SOTO G
	TROY, JOHN W
	TUMBOKON, ELVIRA L
	URIBE, FRANCISCO
	VELASQUEZ, JOSE A
	WALTHALL, LAWRENCE B
	YOUNG, FLORENCE A
	ZIGLER, MILAGROS D
	ZINN, ALEXANDRA C
736	VELA, EDUARDO
	WISSER, JOHN H
931	BETCHER, FRED
997	PACIFIC YACHT REFITTERS INC
	SOUTH BAY BOAT YARD
	SOUTH BAY BOAT YARD NAUTICAL HARDWAR
	TRUITT MACHINE & FABRICATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

LAGOON DR 2014

850 GOODRICH AEROSTRUCTURES

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MARINA PKWY 2014

477	UNLIMITED PLACEMATS & MENUS
550	BARTLETT, CAROL
	CHULA VISTA MARINA
	CRANDELL, WILSON J
	GALLEY AT THE MARINA
	GRIMM, MICHAEL
	OHIER, DOMINIQUE G
	PLENERT, KATHERINE A
	RAINS, PENNY R
	REES, THOMAS J
	ROSSER, CHARLOTTE R
	RUBLE, VICTORIA
	TAPSCOTT, PENNY S
570	SAN DIEGO CATERING CONCEPTS
604	CAYS YACHT SALES INC
	CHILDS MARINE SERVICES
624	SUMMERVILLE, LARRY
640	CALIFORNIA YACHT MARINA
642	ALLS, BENNY B
	ALTMAN, BRAD J
	ARMER, WALLEY D
	BODEN, RICHARD
	BOECKMANN, TOD
	CONKLIN, MARY C
	COOPER, JILL
	DAVIES, HOWARD E
	DUNING, JOHN L
	FITZGERALD, RICHARD D
	FREEMAN, RICHARD A
	GILL, BETTY L
	HICKAM, MICHAEL C
	HUYNH, TAM H
	JESSE, ANTHONY M
	KALPUS, JOHN A
	MCNUTT, REBECCA K
	MERCER, JACQUELINE
	MORTENSEN, RICK W
	MURRAY, DONALD
	OBRIEN, JAMES S
	OSBORNE, KEVIN
	REYNOLDS, STEVEN L
	RUDD, JANET
	RUDMAN, NORMAN C
	SCHEETZ, LINDA J
	SHELBY, CHARLES
	SHOEMAKER, OWENS M
	TOWNSEND, AL
	VINCE, WHALEN
650	CHULA VISTA YACHT CLUB

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010

677 ACKERMAN, ABRAHAM N
AHRENS, YOKO I
AMAYA, LUZDEL C
AMICK, IRENE G
ANGEL, LILIA E
ARSENAULT, JOHN E
AVILA, ELLY G
BAILEY, ROBERT L
BEERS, WESLEY J
BERGERON, RAYMOND J
BIGGERS, DOROTHY R
BRANDT, STEVE N
BREARLEY, WALTER D
BREESE, REUBEN V
BROWN, OLIVIA M
BUTTERWORTH, MARCELLE S
BYRD, VELVA J
CANEZ, JESUS A
CARDONA, PRISCILLA M
CARRERA, ALEJANDRA
CASKINETTE, ANN
CASTRO, RUBEN
CEJA, RODOLFO
CHRISTIAN, MADELYN R
COMER, C
CONNELLY, ROBERT W
CORBIN, ROBERT L
CRABBE, MICHAEL P
CURRY, ROBERT L
CURTIS, ROGER J
DAKEL, AMBER
DANIELS, EDWARD A
DOUGLAS, JEFFREY A
DUGAN, DONNA M
DUNHAM, MARILYN E
DUNKER, DOUGLAS A
ELKINS, M J
ESCOTO, REYES G
FAIRLEE, LARRY L
FRANCOUR, SANDRA L
FRANKLIN, HARRY
FUSCO, BRYAN E
GAONA, ALAN
GENTZ, LINDA I
GOMEZ, MICAELA L
GONZALEZ, JOSE A
GUADALUPE, BARRIOS J
GUERRA, ALBERTO C
GUERRA, JOE R
HAHN, RAY A

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

677

HALL, CHERYL P
HALL, VIVIAN L
HAMBY, JUANA C
HARVEY, JERRY D
HEDGE, WILLIAM
HEDRICK, WILLIE L
HENDRICK, WILLIE
HERNANDEZ, RAFAEL
HERNANDEZ, RAMIRO
HOFF, BRIAN E
HORD, RAYMOND K
JACKSON, ANDREW W
JACKSON, DAISSE
JARVIS, LEONARD G
JOHNSON, RONALD G
JONES, LEROY R
KALIN, SYDNEY
KAMINS, SYBIL R
KINCAID, FLORENCE I
KING, BARBARA A
KNOWLES, CAROL S
KRUPINSKI, DOUGLAS J
LAMARK, DOROTHY L
LANGLOIS, BLANCHE N
LARSON, KATHLEEN
LEGASPI, OSCAR L
LIMON, EDUARDO G
LOTZGESELLE, FRANK W
LUCY, MARGARET
MACIAS, ADELINA
MACIAS, MARIA G
MAGALLANES, ALICIA R
MAMANGUN, CONSUELO
MANLEY, JOYCE L
MANN, HILDRA B
MANNON, THEODORE T
MARSH, ANNE
MATHEWS, R P
MAXWELL, TOM M
MCCAULEY, BETTY J
MCGRATH, BILL B
MEILE, RALPH E
MEZA, ANDREA C
MORRIS, AARON B
MOSLEY, MARGARET M
MUCH, JULIETTE E
MUSGRAVE, ROSE M
NEELY, BILLY J
NEWNHAM, EDITH L
NIETO, JAMES

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

677	NORMAN, DORIS F
	ORAMAS, JOSEFINA O
	OURS, JUDITH E
	OWN A PROPERTY REALTY
	PACELY, SILVIA
	PARKHURST, LINDA K
	PEARSON, GLADYS M
	PERENA, DELFIN
	PIERCE, MARY
	PIKE, MARTIN E
	POTTS, CLAUDIA T
	PRECIADO, CRUZ
	PURDUE, CLARA L
	RADINOVSKY, KATHRYN M
	RAINS, YUKO
	RAMIREZ, JOSIE
	REED, EUGENE W
	RIVERAASTACIO, JOSE E
	ROBB, MARJORY C
	ROBBINS, BRUCE E
	ROSSETTI, RITA J
	SANCHEZ-ALDANA, GABRIEL
	SHAFFER, ORLA
	SHELTON, MARK C
	SMITH, ARTHUR
	SMITH, EARL J
	SOTO, IRMA V
	STINEBUCK, NANCY J
	SUNSET CAB
	SUNSHINE CAB CO
	TERRYS MOBILE PARK
	THAYER-STOKES, LAVERNE M
	TIMBOL, EPENITO
	TOBIE, SOTO G
	TURO, MARJORIE L
	VALVERDE, MIGUEL
	VEGA, GLORIA
	VIGILIA, SANDIE
	VILLAFURTE, LETICIA D
	VOLLER, NORMA J
	WACHTLER, REGENIA G
	WATERS, RONALD B
	WATSON, KENNETH D
	WEATHERLY, V
	WILLIAMS, BERNARD
	WOOD, CAROLYN F
	WRIGHT, BONNIE K
	ZAMUDIO, ORALIA G
691	GARCIA, REBECA
704	CASTANEDA, FERNANDO F

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2010 (Cont'd)

704	GARCIA, JUAN A
	NAVARRO, MARIA E
	SMITH, HARVEY C
716	CORONADO, HENRY U
	MAINWARING, ELIZABETH M
	RAMIREZ, GABRIEL
	ROMO, YESSICA
724	CARTER, EMIKO S
	JOHNSON, STEVEN
	PHILLIP, RABBIA
	STIMPSON, MARY E
731	ALEXANDER, MARIA
	ANDERSON, BILLIE
	AYOTTE, JIM
	BARRAGAN, PETRA
	BEELES, RONALD G
	BENFER, ESPERANZA
	BERMUDEZ, RAQUEL L
	BETCHER, GOTTFRIED E
	BIRKINSHAW, JACK R
	BONATUS, JACKIE D
	BOWLES, PEGGY D
	BRIDGES, MARSHA
	CABRILLO MOBILE LODGE LLC
	CASTANEDA, MANUEL
	CLARK, DONALD F
	CLAY, MARSHALL L
	CONKLIN, EDWARD C
	CONNER, RONALD D
	CUEVA, FILIBERTO C
	CUEVA, FRANCISCO J
	CUNARD, MARIA E
	DORSCHER, SHIRLEY J
	EASTWOOD, MARIA B
	FALLING, BILLY
	FERREIRA, MARIA
	GARCIA, RITA
	GERBASIO, MARGARET A
	GLEASON, EDWARD J
	GRASSO, SALVATORE I
	HAUSWIRTH, DENNIS L
	HERNANDEZ, EVA
	HODGES, MACK C
	JACKSON, WARREN H
	JACQUEZ, ORTENCIA S
	JUAREZ, JESUS
	KARAKEY, APOLONI A
	KNIGHT, SHAWN M
	LITTLE, MICHAEL D
	LUGO, ANGELINA L

G ST 2010 (Cont'd)

731 MANJARREZ, MARIA C
MAPLE, GRAYDEON R
MARISCAL, MARIA
MARTINEZ, MARGARITA
MCGONIGLE, GARY R
MEASEL, GLENN J
MEDINA, RAMON
MELVIN, JOHN H
OSEJO, MARIA
PARDEE, BARBARA J
PATRON, MARIA G
PENNERMAN, WILLIAM A
PERRY, HARLEY L
PRADO, GUADALUPE R
RHOADES, TERRY M
RICHIE, ELIDA
RITCHIE, ELIDIA G
ROBERTS, SANFORD
RODRIGUEZ, GUILLERMO
RODRIGUEZ, JUANA
RODRIGUEZ, WILLIAM
SANCHEZ, ESTELA C
SEGHERS, DOREEN H
SWANSON, DOROTHY J
THOMAS, L
THOMPSON, ROBERT N
TUMBOKON, ELVIRA L
TURNER, THERESA
UNDERHILL, BRENDAN J
URIBE, JOSE G
VAZQUEZ, JAVIER A
VELASQUEZ, JOSE A
WALTHALL, GLEN A
WOODY, NEREIDA
YOUNG, FLORENCE
ZABALA, BULMARO C
ZIGLER, MILAGROS D
ZINN, ALEXANDRA C

736 BAXTER, STUART A
PEYRO, JUAN S
VELA, EDUARDO

997 FIVE STAR YACHT SVC INC
PACIFIC YACHT REFITTERS INC
SOUTH BAY BOAT YARD
TRUITT MACHINE & FABRICATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

LAGOON DR 2010

850 EUREST DINING SVC GOODS
GOODRICH AEROSTRUCTURES GROUP
PACIFIC TRUST BANK

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MARINA PKWY 2010

477	UNLIMITED PLACEMATS & MENUS
510	GORZEGNO, ARTHUR
550	BAY VIEW NAUTICAL
	BENNETT MOTOR EXPRESS
	CHULA VISTA MARINA
	CONNOR, ROBERT L
	GALLEY AT THE MARINA
	JESSE BRETT MARINE SVC
	JESSE RUBLE ROOFING
	MCMANUS, KAJANE S
	MONAGHAN, TOM T
	RAINS, PENNY R
	SCHMID, JOAN T
	SERENITY SEAS
	SOUTH SHORE YACHT SALES
	VONGLASCOE, CHRISTINE A
560	SMITH, KARENNE
570	SOUTH BAY FISH & GRILL
640	CALIFORNIA YACHT MARINA
	EURO HOME & GDN CONCEPTS LTD
642	ARMER, WALLEY D
	BECKNER, ROBERT L
	CALFIRST FINANCIAL
	CAMERON, CARRIE
	CHULA VISTA YACHT CLUB
	DAVIES, HOWARD E
	DEBRISK, JOSEPH R
	DUFF, MARY A
	DUNING, JOHN L
	FREEMAN, RICHARD A
	GADOLA, MICHELE A
	GARCIA, GEORGE R
	MCARDLE, DELISA L
	MCNUTT, REBECCA S
	MERCER, TERENCE C
	PALOMBIT, A
	REECE, RAYMOND J
	RIGNEY, THOMAS C
	RUDMAN, NORMAN C
	SCHEETZ, LINDA J
	SHOEMAKER-OWENS, MARCUS T
	SMITH, MANFRED C
	TOWNSEND, ELAINE S
	TROTTIER, BRADLEY M
	WILLIAMS, GUY S
	WISE, PHIL
	WOOD, MELISSA J

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005

667	AGUILAR, ALBA M
677	ACKERMAN, ABRAHAM N
	AMERICAN SOUTHWEST SERVICES
	ANGEL, MARIA E
	BEERS, WESLEY J
	BERGERON, RAYMOND J
	BERRY, VIVIAN A
	BOWEN, ANGIE M
	BRANDT, STEVE N
	BREARLEY, WALTER
	BREESE, REUBEN V
	BURT, STUART C
	BUTTERWORTH, MARCELLE S
	BYRD, VELVA J
	CAMPBELL, CHARLES L
	CASTRO, FRED H
	CEJA, MARIA A
	CHANG, GERMAINE F
	CHILDERS, WILLIAM
	CONNELLY, ROBERT W
	COOK, MARGARET W
	CORBETT, RICHARD J
	CORBIN, ROBERT L
	DECK, JERRY E
	DELAHUERTA, GUSTAVO
	DELAHUERTA, J G
	DOERING, KENNETH M
	DOUGLAS, JEFFREY A
	DUGAN, DONNA M
	DUNKER, NORMA M
	DUPERRON, DONALD J
	EDINGTON, ARVEL H
	ELKINS, M J
	FAVERTY, CAROLYN F
	FRANKLIN, HARRY
	FUSCO, BRYAN E
	GAGLIANO, ANGELINA
	GALARZA, ARMANDO R
	GENTZ, LINDA I
	GOMEZ, MICAELA L
	GONZALEZ, J A
	GRAHAM, GEORGE H
	GREEN, LUCILE Y
	GUERRA, ALBERTO C
	HAHN, JEAN A
	HALL, CHERYL P
	HALL, DONALD W
	HALL, VIVIAN L
	HAMILTON, JUANITA M
	HARVEY, HAL K

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

677
HEDRICK, WILLIE L
HENDRICK, WILLIE
HUBERT, RICHARD
JACKSON, DAISSE
JDK WEBS
JOHNSON, DANIEL J
JONES, CAROL V
JONES, LAMAR R
JONES, LEROY M
KALIN, SYDNEY
KAMINS, MARVIN S
KELLOGG, WILLIAM B
KINCAID, FLORENCE I
KING, JUDITH E
KISBERT, MARY A
KNOWLES, CAROL S
KOHLMAN, LAVADA J
KRUPINSKI, DOUGLAS J
LAMARK, DOROTHY L
LANGLOIS, BLANCHE K
LEDINGHAM, COLLEEN
LONGHOFER, WAYNE
LOTZGESELLE, FRANK W
MACIAS, MARIA G
MAGALLANES, ALICIA
MAMANGUN, CONSUELO
MANLEY, JOYCE L
MANN, HILDRA B
MARSH, ROBERT
MARTINEZ, LUPE C
MATHEWS, R P
MAXWELL, TOM M
MCGRATH, BILL B
MEILE, RALPH E
MENDOZA, LUPE C
MILLER, RAV
MORRIS, AARON B
MUSGRAVE, ROSE M
NEAL, ROBERT I
NEELY, BILLY J
NEWMAN, LUETTA L
NIETO, JAMES
NORMAN, DORIS F
OLVERA, SONIA R
ONLINESALES
ORTNER, CONSTANCE L
PARKER, JOE
PARKHURST, LINDA K
PIKE, MARTIN E
POTTS, CLAUDIA T

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2005 (Cont'd)

677	PURDUE, CLARA L
	RADINOVSKY, KATHRYN M
	RAINS, YUKO
	REED, EUGENE W
	REEVES, LAURA
	ROBB, MARJORY C
	SANDOVAL, HERMELINDA A
	SAUNDERS, LESLIE
	SCHLEGEL, WILLIAM J
	SERVICIO RADIANTE
	SHAFFER, ORLA
	SMILEY, WANDA F
	SMITH, TIMOTHY A
	SOTO, IRMA V
	STINEBUCK, NANCY J
	STONE, ANNA J
	STONE-WEYGAND, ANNA
	STRAHAN, LOUIS
	SYMO CONSULTING OF CALIFORNIA
	TAGLE, JOSE
	TERRYS MOBILE HOME PARK CORP
	THOMPSON, LAWRENCE E
	TREVINO, ROBERT L
	VALENZUELA, PEDR
	VALUATOIN CONCEPTS INC
	VALVERDE, MIGUEL
	VAZQUEZ, ANTONIA
	VIGIL, ELFIDES M
	VILLAFUERTE, TONY P
	VISTA, GLORIA
	VOLLER, DONALD R
	WACHTLER, REGENIA G
	WATERS, RONALD B
	WATSON, KENNETH D
	WATTS, JOAN M
	WESTON, NANCY O
	WHITING, EDNA R
	WHITTAKER, BARBARA A
	WILLIAMS, BERNARD
	WOLFE, DOLORES
	WOLFORD, JOANN E
	WRIGHT, BONNIE K
691	GARCIA, REBECA
704	AVILA, RUBEN
	CASTANEDA, FERNANDO
	MARTINEZ, ROBERT
	MONTOYA, DANIEL J
	SMITH, STEPHEN E
716	CORONADO, HENRY U
	MAINWARING, ELIZABETH

G ST 2005 (Cont'd)

716 RAMIREZ, FRANCISCA
ROARK, ERNIE A
724 CARTER, EMIKO S
JOHNSON, STEVEN
730 HOLLMAN, MARIE J
731 ACKER, JOHN S
BARRAGAN, PETRA
BERMUDEZ, RAQUEL L
BIRKINSHAW, JACK R
BOWLES, PEGGY D
BYRNE, HELEN A
CABRILLO MOBILE LODGE LLC
CALDEAN, ALLEN
CHAPMAN, WILLIAM
CISNEROS, BULMARO
CLARK, DONALD F
CLAY, MARSHALL L
CONNER, RONALD D
CUEVA, FRANCISCO J
CUEVA, GRACIELA C
DAWSON, JOE W
DORSCHER, SHIRLEY J
ESTRADA, JULIAN
GERBASIO, MARGARET A
GLEASON, EDWARD J
GRALEY, JAMES E
GRASSO, SALVATORE
GROSSMAN, BARBARA
GUTHRIE, IRMA
HATCHETT, IRA H
HAUSWIRTH, DENNIS L
HOLLINGER, ROSELA M
JACKSON, WARREN H
JOLLY, BARBARA E
KALLENBERGER, MARVIN B
KARAKEY, APOLONIA
KIENLEN, TOM
LARA, JOSE L
LITTLE, MICHAEL D
LUGO, ANGELINA
LUPPENS, JOHN
MAPLE, GRAYDEON R
MARTINEZ, TRINIDAD
MCGONIGLE, GARY R
MEDINA, RAMON
MELFORD, MICHEAL B
MELVIN, JOHN H
MONCRIEF, CAROLYN A
NEVEU, KERRY L
PASCHEN, JOE M

G ST 2005 (Cont'd)

731	PATRON, MARIA G
	PAWLAK, EDWARD F
	PENNERMAN, WILLIAM A
	PERRY, H L
	PROTHEROE, IVOR
	RITCHIE, ELIDIA S
	RODRIGUEZ, GUILLERMO
	ROMANDIA, YVONNE E
	SAENZ, ARMANDO
	SANCHEZ, ESEQUIEL
	SANCHEZ, ESTELA C
	SEGHERS, DOREEN H
	SERRANO, LUPE
	SINGER, THOMAS
	SPENCER, W A
	THOMAS, JOHN S
	TINITIGAN, ZENAIDA P
	TURNER, ALFRED S
	UNDERHILL, BRENDAN J
	WALTHALL, GLEN A
	WENTWORTH, FRED E
	WILLIAMS, SHERRY L
	YAOTANI, BENIGNA
	YOUNG, FLORENCE
736	PEYRO, JUAN J
	VELA, EDUARDO
	WISSER, JOHN H
979	PACIFIC DEFENSE SYSTEMS
997	MARINE GROUP LLC
	PACIFIC MARITIME FREIGHT INC
	SD FUEL DELIVERY
	SOUTH BAY BOAT YARD
	TRUITT MACHINE & FABRICATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

LAGOON DR 2005

850 ADECCO EMPLOYMENT SERVICES
ADO STAFFING INC
EUREST DINING SERVICE GOO
GOODRICH CORP
GOODRICH CORP AEROSTRUCTURE GROUP
TOLO INC
TORREY PINES PROPERTIES

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MARINA PKWY 2005

500	GEARY, JOHN F
510	GORZEGNO, ARTHUR
520	A F S INDUSTRIAL LLC
	LOVIE, MARK D
550	AWARENESS COMM TECHNOLOGY
	BAY VIEW NAUTICAL
	CHILDS MARINE SERVICES INC
	INTERRANTE, GINNY
	JESSE RUBLE ROOFING
	LIFE SKILLS U
	RELX
	SCHOONER INC
	SOUTH SHORE YACHT SALES
	STARFISH MARINE
560	SMITH, KARENNE
570	SANDIEGOWEDDINGS
640	A DADS DIVORCE CENTER
	CALIFORNIA YACHT MARINA
642	ARMER, WALLEY D
	BAKER, SCOTT I
	BURNES, GLEN W
	BURNS, KEN D
	CHULA VISTA YACHT CLUB
	DUNING, JOHN L
	EVANS, A E
	GARCIA, GEORGE R
	HICKAM, MICHAEL C
	ICATCHING GRAPHICS
	LAVIOLETTE, GILBERT J
	LUDOVISSY, CHUCK F
	LUNDY, STANLEY D
	MALLEN JOHN GRARD OTREACH SERVICES
	MERCER, TERENCE
	MORAN, MARILYN J
	OSBORN, ROBERT T
	PALOMBIT, A
	RING, ALAN C
	RUDMAN, NORMAN C
	SMITH, MANFRED C
	STEENBAKKER, EMANUEL
	TOMS TAX SERVICE
	VEITCH, JAMES
	YU, KRISTI M
652	HULSE, KATHLEEN M

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000

677
ACKERMAN, A
ADAMSON, RALPH T
ANDREWS, BEULAH
BEERS, WESLEY J
BERGERON, RAYMOND J
BIGGERS, EARL D
BRANDT, STEVE N
BURGER, A
BUSCHUR, LAURA
CASTEEL, RUBY L
COOK, ROLINE
COOPER, JOHN E
CORBETT, RICHARD J
CORBIN, ROBERT L
DECARO, MICHAEL
DUNKER, N M
ECKHARDT, S A
ELKINS, M J
ELMORE, JAMES
FRANKLIN, HARRY
GAGLIANO, A
GARCIA, OFELIA
GIUSTI, JULIUS J
HAHN, JEAN A
HALL, STANLEY B
HAMILTON, J M
HAMNER, JULIA
HARVEY, JERRY D
HIME, M H
HINKLE, DARYL B
HUBERT, RICHARD
HUTCHISON, H S
JACKMAN, D
JOHNSON, L A
JOHNSON, RAY B
JONES, HUGH L
JONES, LAMAR R
KANNITZER, TONY
KELLOGG, EVELYN B
KINCAID, F I
KOLBOWSKI, JENS D
KURINKO, HAZEL
LAMARK, DOROTHY L
LEDINGHAM, COLLEEN
LLOYD, H D
MAGALLANES, ALICIA
MANGLESS, DONALD R
MANLEY, DONALD A
MANN, HILDRA
MATHEWS, R P

G ST 2000 (Cont'd)

677	MCCAMON, FRANK
	MCGRATH, W B
	MEILE, R E
	MENDOZA, LUPE C
	MEZA, ANDREA
	MEZA, MARCELA
	MORSE, MICHAEL W
	MOSS, WILLIAM W
	NELSON, JOYCE
	NEWMAN, L L
	NICHOLS, BARBARA
	ORTIZ, J
	PEREA, CHARLIE H
	PERRY, BARBARA G
	POTTS, CLAUDIA T
	RADINOVSKY, SID
	RAINS, YUKO
	RICE, WILLIAM A
	RICHE, JAMES
	ROBB, MARJORY C
	ROTHELL, CHERYL E
	RUIZ, ALFREDO
	RUSSELL, FRANK
	SANDOVAL, H A
	SAUNDERS, LESLIE
	SCHOLL, L M
	SMITH, EARL J
	STINEBUCK, NANCY J
	TAGLE, BEATRIZ N
	TERRYS MOBILE PARK
	THOMAS, WENDELL C
	TREVINO, ROBERT
	UHER, C
	VILLAFURTE, TONY
	VINING, GORDON
	VOLLER, DONALD R
	WATSON, KENNETH D
	WEIR, NORMAN J
	WHITE, L D
	WHITTAKER, ROBERT
	WILLIAMS, BERNARD
	WILLIAMS, JARRETT R
	WOLFE, GERALD
	YELLAND, E M
691	GARCIA, REBECCA
704	CASTANEDA, GUADALU
	ZATARAIN, JOSE
716	CORONADO, HENRY U
	HAMPTON, MARIA
	LOPEZ, EDUARDO R

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000 (Cont'd)

716 MACIAS, INES
MOORE, V A
724 CARTER, EMIKO S
HADDAD, LUMA
KHALIFEH, ISSA O
SOCAL ROOFING COMPANY
731 ABBOTT, BEN
ALLEN, GEORGE J
ARCHULETA, MARTHA
BOWEN, A
BYRNE, HELEN A
CABRILLO MOBILE LODGE
CLAY, M L
CORONA, M
CORONA, S
CUEVA, G C
DENESSEN, DONALD A
DONOGHUE, LEO
DONOHUE, M E
DREDGE, HENRY
DROZE, S L
DUFFY, WILLIAM A
GERBASIO, M
GLEASON, EDWARD J
GROSSMAN, B
HARTMAN, BETTY J
HATCHETT, IRA H
HOLLINGER, OSBORN E
IULI, PHILLIP
JENKINS, ROGER F
JOLLY, BARBARA
LEWIS, FOX C
LITTLE, M D
LOTZGESELLE, LINDA A
LUGO, A
MILLER, ALICE
MILLER, BABY
MOULTON, EDWARD H
MURPHY, LINDA
OROZCO, MANUEL C
PAWLAK, EDWARD F
PULLIN, C T
RAMIREZ, VICTOR J
SEGHERS, DOREEN H
SHEPHERD, NICK
SPENCER, W A
THOMAS, JOHN S
TINITIGAN, ZENAIDA P
TURNER, ALFRED
WALTHALL, GLENN A

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 2000 (Cont'd)

731	WENTWORTH, FRED E
	WHITTINGTON, R L
	WYMORE, R W
736	BORGE, JAMES
	VELA, EDUARDO
	VELASQUEZ, CESAR L
	VELAZQUEZ, GABRIEL H
	WISSER, JOHN H
997	PARAMOUNT SCAFFOLD COMPANY
	SOUTH BAY BOAT YARD NAUTICAL HARDWARE STORE
	SWATH OCEAN SYSTEMS INCORPORATED

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

LAGOON DR 2000

850 JOHNSTON, CHARLES F

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MARINA PKWY 2000

477	ABCHEM MANUFACTURING CO
	ARTWOW COM
	BORDER ENVIRONMENTAL COMMERCE ALLIANCE BECA
	BROWN BAG DESIGN GROUP
	CORAZON ECONOMIC DEVELOPMENT CONSULTING
	EZRA INTERNATL INCORPORATED
	GLOBAL GREENCARS INCORPORATED
	HIETT GARY S
	IDET
	KENSINGTON GROUP LLC
	MARTHA VALDES & ASSOCIATES
	METALLIC POWER
	MILLENNIUM ENTREPRENEURS
	REWATER SYSTEMS
	RIGHT ANGLE COMMUNICATIONS
	ROMO OSCAR
	SCHOCK POWER CONVERSION
	SCHOCK, JOSEF P
	TERRA SEGURA INTERNATIONAL
	ULTRA FORCE BATTERY
500	GEARY, JOHN F
550	BAY VIEW NAUTICAL
	BRIANS CARPET CLEANING
	CHULA VISTA MARINA BANQUET FACILITIES
	GALLEY AT THE MARINA
	MONAGHAN, TOM T
560	BROWN, LEE A
570	BOBS ON THE BAY JAKES SAN DIEGO BAY
	JAKES SAN DIEGO BAY
604	PUTTIN ON THE RITZ ACRYLIC
	RITZ AT THE MARINA
610	MITCHELL, RANDAL L
640	CALIFORNIA YACHT MARINA
	SEA DANCE CHARTERS INCORPORATED
642	ADAMS, BARBARA L
	FOULDS, DAVID J
	GALLANT, WILFRED J
	JONES, LEVI W
	ODEHNAL, MARY
	ROWDEN, THAYERN D
	STUTZMAN, ROBERT
650	CHULA VISTA YACHT CLUB

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995

677
ACKERMAN, A
ADAMSON, RALPH T
ALLEN, E
BARBER, MICHAEL
BARKER, T L
BEERS, WESLEY J
BEHRENS, E
BENNETT, M L
BERGERON, RAMOND J
BIGGERS, EARL D
BOTTS, ROBERT J
BRANDT, STEVE N
BRODERICK, ARTHUR
BURGER, MICHAEL T
BUSCHUR, LAURA
BUXTON, FRED
COOK, ROLINE
COOPER, JOHN E
CORBIN, AVIS
CSILLAG, MURIEL
CUESTA, K
DAVIS, MAUDE L
DOUGHERTY, F E
DOYLE, R
DUNGAN, K W
DUNKER, N M
ECKHARDT, S A
ELKINS, M J
FRANKLIN, HARRY
FREELAND, BILL
GAGLIANO, A
GIUSTI, JULIUS J
GLENN, LOIS
GOERSS, FRITZ
GREENE, FRANK S SR
HALL, STANLEY B
HAMILTON, J M
HAMNER, LYLE E
HARVEY, JERRY D
HAYDEN, ANNA
HIME, M H
HINKLE, DARYL B
HORST, PAUL
HUTCHISON, H S
JACKMAN, D
JOHNSON, GENE
JONES, LAMAR R
KANNITZER, TONY
KELLOGG, EVELYN B
KELLOGG, ROY F

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

677 KELLY, JAMES P
KETCHUM, GEORGE
KINCAID, F I
KISBERT, CHARLES A
KOLBOWSKI, JENS D
KURINKO, HAZEL
LABEAU, A
LEBLANC, RONALD
LLOYD, H D
MAGALLANES, ALICIA
MANGLESS, DONALD R
MANLEY, DONALD A
MANN, HILDRA
MARSH, ROBERT L
MARSTERS, GORDON
MATHEWS, R P
MCCAMON, FRANK
MCKEE, D
MCMILLAN, CARL A
MEILE, R E
MENDOZA, LUPE C
MEZA, ANDREA
MUNTER, WILFRED
NEWMAN, L L
NICHOLS, BARBARA B
NORMAN, CLINT SR
PERRY, G H
PORTER, ALFRED L
POTTS, CLAUDIA T
RICE, WILLIAM A
RICHE, LYNNE
RIIFF, DORIS M
ROBB, MARJORY C
SALLAM, MYNNA
SAUNDERS, LESLIE
SCHOLL, L M
SHAFFER, ORLA
SMITH, EARL J
SMITH, LEWIS V
STROUP, CHARLES W
SWOPE, D R
TAGLE, BEATRIZ
TERRYS MOBILE PARK
THOMAS, WENDELL C
TREVINO, ROBERT
UHER, J P
VALITON, H D
VERSLUIS, ISABEL L
VINING, GORDON
VOLLER, DONALD R

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

677	WALKER, ERVIN G
	WATERS, RONALD B
	WATSON, KENNETH D
	WEBSTER, LUCILLE
	WHITE, L D
	WILLIAMS, BERNARD
	WILLIAMS, H
	WILLIAMS, JARRETT R
	WOLFE, GERALD
	YELLAND, E M
704	ORTIZ, E
	QUIROZ, BARBARA
716	CORONADO, HENRY U
	WRIGHT, DONOVAN
724	CARTER, LOIS
730	OCCUPANT UNKNOWNN
731	BOARD, WILLIAM D
	BROOKS, W
	BYRNE, HELEN A
	CABRILLO MOBILE LODGE
	CLAY, M L
	CYRANKOWSKI, LUCY
	DECOLIBUS, GLEN
	DONOHUE, M E
	DREDGE, HENRY
	DROZE, S L
	DUFFY, WILLIAM A
	DWYER, JOHN
	FARNSWORTH, GLADYS
	GERBASIO, M
	GLAHOLM, THOMAS
	GLEASON, EDWARD J
	HARRIS, EARL G
	HARTMAN, BETTY J
	HOLMES, MARETTA F
	HOWARD, H J
	JACKSON, WILLIAM R
	JORGENSON, VERNON
	KIRKPATRICK, ROBERT M
	LESHINSKI, JOSEPH A
	LITTLE, M D
	LUNDGREN, ALAN C
	MEYER, SARA
	MILLER, ALICE
	MILLER, BABY
	MILLER, J L
	MOULTON, EDWARD H
	OROZCO, MANUEL C
	ORTUSO, NATHAN
	PHELPS, RALPH C

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1995 (Cont'd)

731	PULLIN, C T
	ROMANDIA, YVONNE
	RYAN, G
	SEGHERS, D H
	SHENNERS, CHUCK
	SINCLAIR, CLAUDIA
	SPENCER, W A
	TURNER, ALFRED
	WENTWORTH, FRED E
736	BORGE, JAMES
	SANTANA, ROSA M
	WISSER, JOHN H
979	SWATH OCEAN SYSTEMS INC
997	BAYSIDE BOAT STORAGE
	SOUTH BAY BOAT YARD

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MARINA PKY 1995

550	BROUSSARD, F L
	CAPLIN, MYRON
	CATES, ROBERT
	CHULA VISTA MARINA
	COOPER, LARRY
	CYR, VERNON
	DEHAAN, JAMES
	DEROSIA, LEEANNE
	DOCKSIDE MARINE
	DOYLE, VINCENT
	DUDA, JEFF
	ENGLISH, FLOYD E
	FAIR, ROBERT J
	FISHER YACHT SALES
	FLORES, SERGIO
	FORMICO, MIKE
	GALAN, CARLOS
	GARTLAND, MICHAEL
	GILLIS, DARLA
	GRAF, L S
	GRASCIA, SUSAN
	HANSEN, ROBERT L
	HEBERT, FRANCES
	HELPS, S
	INCOME PROPERTY MANAGEMENT
	KENT, L
	KLAMPE, NYLES O
	KUESPERT, ANDREA
	KUHN, RAYMOND G
	LAMPLEY, PAUL H
	LASALLE, ROGER JR
	LASNIK, ERIK
	LIBBY, DONALD W
	LINSLEY, EDWARD
	LOPEZ, ROBERT
	MACPHERSON, JOHN
	MAGLEY, DONALD
	MCMULLEN, ARTHUR
	MEYERS, B J
	MORRIS, DARREN
	NEWPHER, ART
	OLSON, DERALD
	OZENBAUGH, WILLIAM
	PARSON, M E
	PEARSON, KEVIN
	QUINN, KRISTY
	RAINS, J
	RAMOUSSE, J F
	REAL, THOMAS A
	REDFIELD, FRANK

MARINA PKY 1995 (Cont'd)

550	RICHARDSON, GARY D
	RUSSELL, HAROLD
	SAMPSON, RAYMOND M
	SCHMID, J
	SCHOEN, JOHN W
	SCHUMM, DONALD L
	SEGUINE, KEN
	SHORE, CARY
	SIEGEL, DAN
	SLAVIN, FRANCIS
	SMITH, DAVID J
	STANNARD, GEORGE
	VERGARA, EDUARDO
	WACHTER, EMIL
	WARD, DAVID E
	WESTON, NANCY L
	WHITE, WALTER
	WOLF, ROBERT L
570	JAKES SOUTH BAY
640	BAKER, FRANK L
	BARNUM, GENE
	BELKNAP, WILLIAM R
	BLAISDELL, PHIL
	BUTTERFIELD, C
	CALIFORNIA YACHT MARINA
	CORUM, JOSEPH P
	CUNNINGHAM, JOHN V
	DEHAAN, JAMES
	DENNISON, EARL
	EBERHARD, E
	ERVING, WILLIAM
	ESTUDILLO, ROBERTO
	FISHER, ROBERT K
	GARRISON, CHARLES R
	HINKLEY, VERN
	HORTON, AVERY T
	IRWIN, JOHN
	JENNERS, JOE
	KAMRATH, GEORGE SR
	LOWDER, WALT
	MACNEILL, JOHN C
	MCCLELLAND, JOHN R
	MCDOWELL, BRUCE
	MCLAIN, JERRY
	NASON, JAMES
	NELSON, MARTIN E
	PHILLIPS, W R
	RUNYON, DONALD
	SLACK, JOHN M
	SMITH, JIM A

MARINA PKY 1995 (Cont'd)

640	SWEARS, BILL
	VARNER, ROBIN
642	COLEMAN, F
	MACROSTIE, ERNEST P
	MCCLELLAND, JOHN R
	SCHWARTZER, JERI
664	STANFILL, DONALD

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

G ST 1992

667	MARSTERS, GORDON
677	BENNETT, M L
	BOTTS, ROBERT J
	BROADWAY TRAILER PK
	DENTON, WALLACE W
	DUNGAN, K W
	ELKINS, M J
	GAGLIANO, A
	GEORGE, L B
	GREENE, FRANK S SR
	HAYDEN, ANNA
	HOWELL, JOHN P
	JOHNSON, GENE
	KELLY, THOMAS
	KETCHUM, GEORGE
	MARNETTE, OTTO H
	POTTS, CLAUDIA T
	SMITH, LEWIS V
	SWOPE, D R
	WEIR, I
	WILHELMI, W D
716	CORONADO, HENRY U
731	APPLETON, PERRY H
	CABRILLO MOBILE LDG
	CYRANKOWSKI, LUCY
	DWYER, JOHN
	GLEASON, EDWARD J
	GRASSO, S
	LITTLE, M D
	MILLER, ALICE
	MILLER, BABY
	MILLER, J L
	PULLICIN, C T
	QUINN, E L
	SEGHERS, D H
	SPENCER, W A
	VANCUYK, B
	WILSON, G A
736	BORGE, JAMES
	WISSER, JOHN H
997	BAYSIDE BOAT STRG
	SOUTH BAY BOAT YARD
	SWATH OCEAN SYSTEMS

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MARINA PKY 1992

550	ALMADA, MANUEL
	ANDREWS, JOHN C JR
	ASHER, DOUGLAS
	AVEY, ROBERT J
	BARTON, JASON
	DEHAAN, JAMES
	DEILY, PETER
	DORF, STEVE
	DOYLE, VINCENT
	DRAKE, LEE
	DUKE, DREW
	EVELEIGH, LONIE F
	EVEN, DAN
	GISSI, MICHAEL R
	GRAF, L S
	GROOME, MAURICE
	GROSS, FLOYD J
	HALLAM, GREGG
	HANSEN, ROBERT L
	HOLDEN, THOMAS
	INCOME PROPERTY MNG
	JACKSON, ERIK R
	KECK, LANE D
	KENT, L
	KVARDA, JOSEPH
	LADEKUNS, M E
	LUSH, DON
	MCGAVROCK, CAROLYN
	MEYERS, B J
	MILLER, BRENT A
	MOOMEY, DON
	MORRIS, DAVID
	MURPHY, ANDREW F
	NESS, J R
	OZENBAUGH, WILLIAM
	PIERZCHAJLO, STAN
	PIETERS, EDWARD
	RYAN, CAROL
	SCHALLER, PAUL
	SEA VENTURE CHARTRS
	SEGUINE, KEN
	SLAVIN, FRANCIS
	TOWNSEND, AL
	VERGARA, E
	WILLMANN, BOB
	WOLDRIDGE, DARYL
	WOLF, ROBERT L
	WRIGHT, PRESTON
570	JAKES SOUTH BAY
640	BELKNAP, WILLIAM R

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MARINA PKY 1992 (Cont'd)

640	BODINE, ROBERT E
	BUTTERFIELD, C
	CA YACHT MARINA
	CASON, ROGER
	CHAFFEE, WILLIAM K
	CLARK, R W
	CORUM, JOSEPH P
	DAVIS JOS M JR CAPT
	ERVING, WILLIAM
	ESTUDILLO, ROBERTO
	GARRISON, CHARLES R
	GIBSON, DANA E
	GILL, JAMES B
	HORTON, AVERY T
	IRWIN, JOHN
	JOHNSON, DENNIS D
	KAMRATH, GEORGE SR
	LENSTON, E E
	LIENERT, JOHN
	MACNEILL, JOHN C
	MCDOWELL, BRUCE
	MEAKER, J
	MILLER, JACK C
	MINNICK, DONALD L
	MINTZ, MARK L
	MOREY, ROBERT
	RIDDLE, TOM
	RUNYON, DONALD
	SLACK, JOHN M
	SORENSEN, AL R
	WHITNEY, ALAN
642	TIERNEY RICHD A DDS
646	SLIPWAY MARINE YCHT
650	CHULA VST YACHT CLB
902	HALE JOE CONSTR CO


Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1986

677	BROADWAY TRLR PK		
34	ALLEN E	422-7679	
33	ANDERSON GEO K	422-7224	
3	BAKER M J	420-1460	0
32	BARKER T L	420-3998	8
	BEATTY OTIS M	422-6478	3
12	BEEBE S E	426-5356	7
	BEHRENS ELIZABETH C	427-5919	7
152	BEHRENS RAYMOND L	427-5919	
158	BELL T ROTH	422-1805	
188	BENDER EDMUND F	422-6062	
	BENNETT KEMP W	427-4456	4
59	BESTINY JOS	427-3449	
	BICSKEI HELEN	427-7143	5
	BIGGERS EARL D	425-9370	3
	BOTTS ROBT J	420-5565	8
40	BROADWAY TRLR PARK	422-0242	
96	BRODERICK MARY	426-6479	7
	BRUMMER MARIE	425-5415	+8
149	BRUNER RUTH L	422-3214	7
	BURGER ALICE I	427-3943	
	BURGER MICHARL	427-3943	3
27	BUSCHUR LAURA	426-6589	
	CARNEY RAYMOND A	425-7507	3
	GOLLEY PAUL B	427-8761	3
	COMISKY LOIS	426-8036	+8
	COMISKY RAYMOND	426-8336	+8
130	COOK ROLINE	422-1269	
	COOPER JOHN E	426-6157	3
79	CRAIG CHARLOTTE S	422-3640	9
72	CREWS JOHN W	420-3494	
49	CSILLAG MURIEL	420-9284	
156	DARLON DAVID	422-6869	
44	DAVID MAUDE L	420-0415	1
14	DIDOMIZIO DANIEL	422-3070	9
136	DOKE RICHARD	420-7997	9
187	DOUGHERTY F E	422-6467	
47	DOYLE R	422-4554	0
146	DUNGAN K W	425-5567	1
107	DUNKER N M	427-3684	9
50	DUNTON WALLACE W	422-2175	
53	DURHAM HENRY	427-9893	
	ELKINS WILLIE	425-2733	
	ELKINS POWELL	425-2733	4
	ESTES M	425-3797	2
	GAGLIANO ANGELINA	420-8168	4
	GEORGE L B	422-0242	3
	GIUSTI JULIUS J	427-1626	4
73	GLENN CHAS D	425-9864	9
135	GLENN L	427-5541	0
171	GOEPPER E H	427-0766	
90	GOERSS FRITZ	422-5622	
	GRANGER E T	691-7646	4
81	GREER MARVIN C	425-8588	8
	GROTE B	427-1019	3
13	HALL STANLEY USN	420-5106	8
176	HALL SYDNEY	422-2589	
	HAMILTON J M	691-7682	4
	HARBECK A A	426-8152	8
	HARTICH JACK	422-3225	3
172	HASELMIRE JOS M	420-5813	
35	HATCHER CHARLIE L	422-0203	
10	HENDERSON ROBT L	420-4601	
	HOWE M H	425-7412	0
22	HUNKLE DARYL B	427-1475	
	HOGAN ROBT B	691-9549	4
84	HOFST PAUL	426-4237	
	HOUGH VERGIL SR	425-8565	4
31	HUFFMAN GUY	420-0549	
1	HUNT E B	426-5476	
108	HUTCHISON JOHN G	420-8896	1
48	INCOME TAX & BUS SVC	425-7936	0
148	JOHNSON E J	427-3195	0
	JOHNSON GENE	425-4618	+8
	JOHNSON RAY B	425-6115	3
119	JONES LAMAR R	427-1159	8
122	KELLOGG ROY F	422-5575	
97	KELLOGG STEARNS W	420-5693	
62	KELLY JAS P	426-3923	
28	KELLY THOMAS	427-6896	9
100	KINCAID F I	422-2827	
154	KIRCHMAIER WM E	420-0888	
52	KIRKPATRICK WALTER	427-1018	
165	KISBERT CHAS A	420-6769	
	KURINKO HAZEL	422-3064	+8
	LAPLANTE V J	425-6693	3
	LEBLANC HERVE	425-9760	5
129	LLOYD H D TEO	425-7936	0
95	LUND ELLIS M	420-1920	
89	MAGERS BEN R	420-0494	
5	MANGLESS DONALD R	422-9035	
123	MARNETTE OTTO H	425-1149	8
100	MARSH ROBT L	422-1584	7
	MARSTERS CORDON	585-0604	+8

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory


G ST 1986



G 92010 CONT.
84 MARTLEY EARL H 420-3368
64 MATHEWS R P 420-0531
110 MCCAMON FRANK 422-2328
12 MCKINLEY THOS T MRS 420-8349
102 MEYLE R E 422-7419
17 MERGEN S M 420-4691
145 MILTON FRANCIS J 422-2921
45 MITCHELL ROBT H 422-2217
6 MOE C O 420-1041
41 MUNTER WILFRED COR 422-0293 8
19 NADEAU A 420-3386
186 NEWMAN L L 427-3734
30 NICKLES CLARENCE 422-6213
NICKLES MARGARET 422-6213 1
2 OGDEN HOWARD 420-0442
63 PATTERSON EDMUND L 426-1322
178 PERRY G H 420-2646
162 PILLA HELEN C 422-2598
169 PORTER ALFRED L 420-3793
POST B 427-7657 4
RARICK MARGARET L 425-7836 0
RICE WILLIAM A 426-2896 3
ROBB MARJORY C 420-8927 +8
ROBERTS JOHN L 425-6567 4
SANFORD W B 425-6386 3
25 SAUNDERS LESLIE 425-6971 1
170 SCHREIBER M L 420-6354
143 SEDILLO BETTA L 422-8072 8
50 SISEMORE NAOMI R 420-4320
SMITH LEWIS V 427-4347 4
168 STOUDT M U 420-3513
192 SUMNER V 420-0660
40 TERRYS MOBILE PARK 422-0242
83 THOE IRVIN L 426-8908
138 THOMAS AVIS 420-2719 1
131 THOMAS WENDELL C 427-4296
132 TRACO RICHARD C 422-7989
UHER J P 427-3721 1
117 VALENCIA WALTER S 427-2931
169 VALITON H O 427-6339 1
VANKOUWENBERG DORIS 691-1219
VANKOUWENBERG J 691-1219 4
39 VANZANTE N M 426-5614
20 VESTAL LYNETTE B 422-1071
VINCENT MARGIE L 427-6550 2
113 WALKER ERVIN G 422-0672
WATSON KENNETH D 427-7091 3
WATSON MILLIE 427-7091
104 WEBBER S M 422-6580
157 WEBSTER LUCILLE 420-4840
174 WIDEN ALBERTA E 420-0316 8
173 WILHELMI W D 427-3867
WILLIAMS BERNARD 425-4722 1
91 WILLIAMS FORREST C 422-8539
WILLIAMS JARRET R 427-9349
116 WILLIAMS M N 422-1709
WOLFE GERALD 425-0273 5
85 WOLL F J 427-1453
24 YELLAND WM J 426-6019
ZOLEZZI B C 426-3330 5
677
691 XXXX 00
704 SANDEERG L 420-4370 4
VEGA JOSE I 425-9196 +8
716 DOORILL G M 426-4413 4
724 ASCOLESE A 422-2193 5
731 CABRILLO MBL LDG
ANGNER H O 425-4271 5
AYOTTA JIM 425-8006 4
BELLEVANCE ROMEO 425-2838 4
SILLHEIMER WILBERT 427-8139 +8
BOARD KATHLEEN 425-6839
10A BOARD WM D 425-6899 9
58 BUXTON FRED H 420-2621
7A CABRILLO MOBILE LDG 422-0245
CAMPBELL RICHARD 20 420-0617 1
13E CAREY B H 427-1724 0
168 CARR JAS 426-7960 0
CHARTRAND M P 585-9903 +8
200 CLAY MARSHALL L 425-6455 1
CUMMINGS PATRICK C 422-6111 5
200 CUNARD EDWARD 420-2653 1
CYRANKOWSKI LUCY 426-E374 +8
1B DAVIS JOS A 422-5157
EA DIETZ WINN 420-7758 0
80 DONOHUE M E 420-0069
22A DROZE S L 426-1995 9
SC HARTMAN BETTY J 427-5338 7
HEILCHUCK BARBARA 585-8749 +8
HEILCHUCK JIM 585-8749 +8
LIPPERT LOUIS T 426-7234 +8
12C MYERS M Y 420-6782 7
PUGGLES ELAINE 427-8365 +8
SHEPHERD ZONA 425-6236
VANCUYK B 691-9411 +8
VANGUNDY DONALD 425-8449 +8
VANGUNDY ETHEL 425-8449 +8
YOUNGER GEORGE J 420-5299 +8
G DUFFY WM A 420-6247 5
3C ENDLICH JOS 426-9715 7
16D FARNSWORTH GLADYS 422-4948 8
22B FUGATE HARRY R 427-8768
GERBASIO MARGARET 425-9572 2
GLEASON EDW J 426-0704 3
120 HANKS JOE 427-9524
HANSON LESLIE R 426-6964 4
100 HARRIS ALBERT G 427-3494
7O HAY HAROLD B 427-8972 9
HOLMBERG DOROTHY J 585-9228 5
24A HOLMES MARETTA F 422-3268 9
HOMICK MARIE S 420-4545 4
HOWARD JOHN M 425-0466 3
23A JACKSON WM R 426-0784
JOLLY S 425-1820 4
12A JONES DOROTHY LEE 420-6042 9
9D JONES H A 420-6163 1
1E JORGENSON VERNON 427-4975
4E KIKER EVELYN L 425-9457 1
G KIRKPATRICK ROBT M 422-7820 5
LAVIGNE VICTOR J 426-5266 5
14C LESHINSKI JOS A 425-9909 1
2C MEYER SARA 420-9180
MILLER HERMAN H 427-7203 5
14A MONEYPENNY ERIC 426-1666 1
9O MOULTON EDW H 422-8631
7A ORTUSO NATHAN 427-8145 1
4A PARK ADA M 422-9058 8
20A PARKINSON MILTON E 422-2449
PEARCE M A 422-7660 4
20 PRICE ROBT 425-0369 1
18C QUINN E L 420-9127
16A RATH EDWARD 422-8781 9
REISS ALMA L 420-5280 3
9A RYAN G 427-0706
SEGHERS O H 427-0160 3
SHEPHERD NICK 425-6236 5
SPENCER W A 426-0498 4
25D STEELE HOWARD A 420-5843
8A STEIGER HENRY G 422-2555 7
5D SUTTER V 422-8940 9
25C WATSON R L 427-5315
18C WENTWORTH FRED E 427-5270 1
12O WENTWORTH KAREN A 426-2648 9
731
736 GONZALEZ FILEMON 585-7057 +8
SCHMIDT SCOTT K 422-0845 +8
A WISSER J H 425-2528
* 36 BUS 656 RES 142 NEW

Target Street	Cross Street	Source
✔	-	Haines Criss-Cross Directory

G ST 1982



677	BROADWAY TRLR PK	
	ACKERMAN C	425-8497 +2
34	ALLEN E	422-7679 5
33	ANDERSON GEO K	422-7224
98	ANDERSON W A	422-7689
129	ASHCRAFT M T	426-4109 1
3	BAKER M J	420-1460 0
94	BARCLAY THEO M	420-9032
32	BARKER T L	420-3998 8
12	BEEBE S E	426-5356 7
152	BEHRENS RAYMOND L	427-5919 7
158	BELL T ROTH	422-1805
188	BENDER EDMUND F	422-6052 6
59	BESTINY JOS	427-3449
67	BOTTS JOHN B	420-3573
	BOTTS ROBT J	420-5565 8
40	BROADWAY TRLR PARK	422-0242
96	BRODERICK MARY	426-6479 7
149	BRUNER RUTH L	422-3214 7
27	BUSCHUR LAURA	426-6589 3
58	CADDICK H	422-8187 9
E5	CHENOWETH R W	422-6662 3
	CHERRIS A R	425-0744 +2
	CHRISTENSEN MARTIN	422-8819 1
130	COOK ROLINE	422-1289
79	CRAIG CHARLOTTE S	422-3840 9
72	CREWS JOHN W	420-3494
49	CSILLAG MURIEL	420-9284
156	DARLON DAVID	422-6869
44	DAVID MAUDE L	420-0415 1
14	DIDOMIZIO DANIEL	422-3070 9
136	DOKE RICHARD	420-7997 9
187	DOUGHERTY FERN MRS	422-6467
47	DOYLE R	422-4554 0
146	DUNGAN K W	425-5567 1
107	DUNKER N M	427-8604 9
60	DUNTON WALLACE W	422-2175
53	DURHAM HENRY C SR	427-9893
	ESTES M	425-3797 +2
7	FUHRMAN ALICE L	422-6262
190	GIUSTI THOS P	426-7097 1
73	GLENN CHAS D	425-9864 9
135	GLENN L	427-5541 0
171	GOEPPER E H	427-0766
90	GOERSS FRITZ	422-5822
	GRAY CARL G	426-3895 +2
115	GREEN FLOYD I	422-9353 4
181	GREEN JERRY L	422-0467
81	GREER MARVIN C	425-8538 8
74	GUNTLE M E	420-8151
13	HALL STANLEY USN	420-5106 8
176	HALL SYDNEY	422-2569
	HARBECK A A	426-8152 8
172	HASELMIRE JOS M	420-5813
35	HATCHER CHARLIE L	422-0203
10	HENDERSON ROBT L	420-4601
183	HIME PAUL E	425-7412 0
22	HINKLE DARYL B	427-1475
64	HOBBS GEO E	427-4008 5
84	HORST PAUL	426-4237 4
31	HUFFMAN GUY V	420-0549
1	HUNT E B	426-5476
108	HUTCHISON JOHN G	420-8896 1
48	INCOME TAX&BSNSS SR	425-7936 0
	INMAN LILLIAN P	425-0242 +2
151	JOHNSON G G	422-2344
148	JOHNSON ROBERT L	427-3195 0
119	JONES LAMAR R	427-1159 8
122	KELLOGG ROY F	422-5575
97	KELLOGG STEARNS W	420-5693
62	KELLY JAS P	426-9923
28	KELLY THOMAS	427-6896 9
180	KINCAID F I	422-2827 6
154	KIRCHMAIER WM E	420-0888
52	KIRKPATRICK WALTER	427-1018
165	KISBERT CHAS A	420-6769
75	LEYDEN WALTER T	420-3269
129	LLOYD H D T	425-7936 0
95	LUND ELLIS M	420-1920
89	MAGERS BEN R	420-0494
5	MANGLESS DONALD R	422-9035 5
123	MARNETTE OTTO H	425-1149 8
100	MARSH ROBT L	422-1584 7
84	MARTLEY EARL H	420-3368
64	MATHEWS R P	420-0531
110	MCCAMON FRANK	422-2328 5
12	MCKINLEY THOS T MRS	420-8349
102	MEILE R E	422-7419
14	MENDENHALL L F	427-3884
17	MERGEN S M	420-4691 4
71	MESTER CHAS H	422-3047
145	MILTON FRANCIS J	422-2921 3
45	MITCHELL ROBT H	422-2217
6	MOE C O	420-1041
161	MORRIS WM N	422-7927
41	MUNTER WILFRED CDR	422-0293 8
19	NADEAU A	420-3886
186	NEWMAN L L	427-3734 6
30	NICKLES CLARENCE	422-6213 1
2	OGDEN HOWARD	420-0442
68	PATTERSON EDMUND L	426-1322
140	PELLERITO M L	427-4456 0
178	PERRY G H	420-2646
162	PILLA PAUL J	422-2598 6
4	POHL AUSTIN F	427-9254 3
127	POLLARD D H	427-0334
189	PORTER ALFRED L	420-3793
23	PRICE WALKER W	420-5844
	RARICK MARGARET L	425-7936 0
143	RICHARDS REX M	425-1624 1
128	RORABECK R S	422-0667
25	SAUNDERS LESLIE	425-6971 1
170	SCHREIBER M L	420-6354
143	SEDILLO BETTA L	422-8072 8
	SIMON RALPH E	426-7149 +2
50	SISEMORE NAOMI R	420-4320
166	SMULLIN F L	427-5243 9
15	STAGMARO BARTOL MRS	420-9214
92	STOAKES FREDERICK	425-6657 9
168	STOUDT M U	420-3513 4
192	SUMNER V	420-0660 4
40	TERRYS MOBILE PARK	422-0242
83	THOE IRVIN L	426-8906 6
138	THOMAS AVIS	420-2719 1
131	THOMAS WENDELL C	427-4296
99	THORNTON C O	427-1374
132	TRAGO RICHARD C	422-7989
	UHER J P	427-3721 1
117	VALENCIA WALTER S	427-2931 4
169	VALITOH H D	427-6339 1
39	VANZANTE M M	428-5614
20	VESTAL LYMETTE B	422-1071
	VINCENT MARGIE L	427-6550 +2
113	WALKER ERVIN G	422-0872 5

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1982

G		92010 CONT	
104	WEBBER S M	422-6580	
157	WEBSTER LUCILLE	420-4840	
174	WIDEN ALBERTA E	420-0316	8
173	WILHELMI W D	427-3867	
	WILLIAMS BERNARD	425-4722	1
91	WILLIAMS FORREST C	422-8539	6
	WILLIAMS JARRET R	427-9349	
116	WILLIAMS M N	422-1709	5
	WILSON L M	425-7639	1
85	WOLL D J	427-1453	
	YAGEL GEO C JR	422-3411	+2
24	YELLAND WM J	426-6019	3
677			
691	XXXX	0D	
704	TUITE MARY R	420-4370	+2
	WILHARMS THOMAS L	420-3277	1
716	LARAGIONE DOMINIC E	426-5491	+2
724	BERNSTEIN G A	420-7902	1
A	KASTLUNGER JOHN A	420-7902	+2
731	CABRILLO MBL LDG		
28D	ALDER EMMA	420-3117	3
	BLACKWOOD B J	427-6513	+2
10A	BOARD WM D	425-6899	9
5B	BUXTON FRED H	420-2621	
7A	CABRILLO MOBILE LDG	422-0245	
	CAMPBELL R H 2D	420-0617	1
13E	CAREY B H	427-1724	0
16B	CARR JAS	426-7980	0
20D	CLAY MARSHALL L	425-6455	1
4C	CONROE GERALD F	427-4108	5
17C	CORBRAN C A	420-2302	5
20B	CUNARD EDWARD	420-2653	1
1B	DAVIS JOS A	422-5157	
76C	DAWSON JOE	420-1587	
8E	DEHAVEN BARBARA R	425-1820	1
	DEMPSEY RAYMOND	426-2796	+2
6A	DIETZ WINNI	420-7758	0
8B	DONOHUE M E	420-0069	
1BB	DOUGLASS MAURICE	427-1545	6
22A	DROZE S L	426-1995	9
	DUGO LEWIS G	420-6193	+2
3C	ENDLICH JOS	426-9715	7
	ESPINOSA JOSE J	420-4274	+2
16D	FARNSWORTH GLADYS	422-4948	8
3D	FITZGERALD E L	426-6242	8
22B	FUGATE HARRY R	427-8768	5
27A	GATES F M	426-0408	0
3E	GEALER F A	426-4773	1
	GERBASIO MARGARET	425-9572	+2
10B	GRANTHAM FLORENCE	427-2545	5
10B	GRANTHAM PAUL	427-2545	5
12D	HANKS JOE	427-9524	6
10D	HARRIS ALBERT G	427-9494	6
5C	HARTMAN MARION MRS	427-5338	7
7D	HAY HAROLD B	427-8972	9
15E	HILL ALBERT W	426-4627	3
24A	HOLMES MARETTA F	422-3268	9
	HOUGH C M	425-6987	+2
24B	HUME WM C	422-6071	
2B	INMAN G B	427-9722	5
23A	JACKSON WM R	426-0784	3
12A	JONES DOROTHY LEE	420-6042	9
9D	JONES H A	420-6168	1
1E	JORGENSON VERNON	427-4975	6
5E	KELLER MARGARET	420-2670	
4E	KIKER EVELYN L	425-9457	1
14D	KINNE C	422-4191	1
4B	LAUGHLIN W F	422-0443	0
1C	LAVIGNE VICTOR J	427-1854	6
14C	LESHINSKI JOS A	425-9909	1
	LEWIS MICHAEL	427-7152	+2
13D	LONG CLINTON	422-2760	9
2C	MEYER SARA	420-9180	
14E	MILLER HERMAN H	427-7555	8
14A	MONEYPENNY ERIC	426-1666	1
9D	MOULTON EDW H	422-8681	
12C	MYERS H B	420-6782	7
8C	NOACK ALICE	422-3131	3
12E	NOBLE ROBERTA S	426-4597	7
7A	ORTUSE NATHAN	427-8145	1
	ORTUSO PATSY	420-0479	+2
4A	PARK ADA M	422-9058	8
20A	PARKINSON MILTON E	422-2449	
	POST B	427-7857	+2
2D	PRICE NAIDA	425-0369	1
19C	QUINN WM R	420-9127	
16A	RATH EDWARD	422-8781	9
	ROMANIUK NICK	426-8957	1
9A	RYAN G	427-0708	6
15B	SHANTEK STEPHEN P	425-7610	0
25D	STEELE HOWARD A	420-5843	
8A	STEIGER HENRY G	422-2555	7
5D	SUTTER V	422-8940	9
	TURNER LINDA	426-8076	+2
23B	VANCUYK B	426-2035	1
26C	WATSON R L	427-5315	6
3C	WENTWORTH D H	422-7617	1
18C	WENTWORTH FRED E	427-5270	1
12B	WENTWORTH KAREN A	426-2648	9
7A	WHITE STEWART M	420-7434	
6B	WHITNEY ESTHER G	425-0125	8
731			
736	BORGE JAS A	426-8442	1
	COREANO ROSENDO	422-3322	+2
	SANTANA RAMON	425-5246	+2
A	WISSER J H	425-2528	5
*	27 BUS 617 RES	121 NEW	


Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1979

667	XXXX	00	
677	BROADWAY TRLR PK		
34	ALLEN E	422-7679	5
133	ANDERSON GEO K	422-7224	
46	ANDERSON VICTOR R	425-1755	6
98	ANDERSON W A	422-7689	
94	BARCLAY THEO M	420-9032	
	BARKER T L	420-3998	8
112	BEEBE S E	426-5356	7
152	BEHRENS RAYMOND L	427-5919	7
158	BELL T ROTH	422-1805	
188	BENDER EDMUND F	422-6052	6
59	BESTINY JOS	427-3449	0
191	BIELAN KARL	420-7454	6
21	BISAILLON LUDGER J	426-0200	6
67	BOTTS JOHN B	420-3573	
	BOTTS ROBT J	420-5565	8
	BOYD Z C	427-6801+	9
132	BRINE WM J	427-1801	3
40★	BROADWAY TRLR PARK	422-0242	
96	BRODERICK MARY	426-6479	7
149	BRUNER RUTH L	422-3214	7
27	BUSCHUR LAURA	426-6589	3
	CADDICK H	422-8187+	9
11	CARTHY FRED	422-0242	5
65	CHENOWETH R W	422-6662	3
13D	COOK ROLINE	422-1289	
42	CORNELIUS HUGO J	422-8411	7
	CRAIG CHARLOTTE S	422-3840+	9
72	CREWS JOHN W	420-3494	
63	CROPLEY CLYDE P	420-8074	2
49	CSILLAG MURIEL	420-9284	0
156	DARLON DAVID	422-6869	1
	DIDOMIZIO DANIEL	422-3070+	9
	DODSON WILBUR T	425-9998+	9
	DOKE RICHARD	420-7997+	9
187	DOUGHERTY FERN MRS	422-6467	0
	DUNKER N M	427-8604+	9
60	DUNTON WALLACE W	422-2175	
153	DURHAM HENRY C SR	427-9893	2

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1979



G		92010 CONT
174	EDMONDS A E	420-0316
138	ELLIOTT M	420-6669 2
101	ELLZEY ELIZABETH	420-2007 3
150	FARMER EMMA W	427-8837
169	FAULKNER DOYAL	420-2552 7
77	FLACK A B	420-8373 3
7	FUHRMAN ALICE L	422-6262
	GLENN CHAS O	425-9864+9
171	GOEPPER E H	427-0766
90	GOERSS FRITZ	422-5822
115	GREEN FLOYD I	422-9353 4
181	GREEN JERRY L	422-0467
	GREER MARVIN C	425-8538 8
74	GUNTLE M E	420-8151
	HALL STANLEY-USN	420-5108 8
176	HALL SYDNEY	422-2569
56	HANSEN CARL C	420-4883
	HARBECK A A	426-8152 8
172	HASELMIRE JOS M	420-5813
35	HATCHER CHARLIE L	422-0203
134	HAYDEN DEWEY M	427-4372
106	HENDERSON ROBT L	420-4601
22	HINKLE DARYL B	427-1475
64	HOBBS GEO E	427-4008 5
184	HORST PAUL	426-4237 4
105	HUFF MABEL C	420-5634 1
31	HUFFMAN GUY V	420-0549 1
1	HUNT E B	426-5476 2
	ISAACS MARGIE L	427-6550 8
151	JOHNSON G G	422-2344
148	JOHNSON ROBT LYNN	427-3195 5
	JONES LAMAR R	427-1159 8
122	KELLOGG ROY F	422-5575
97	KELLOGG STEARNS W	420-5693
62	KELLY JAS P	426-9923 2
	KELLY THOMAS	427-6896+9
180	KINCAID F I	422-2827 6
154	KIRCHMAIER WM E	420-0888
52	KIRKPATRICK WALTER	427-1018
165	KISBERT CHAS A	420-6769
131	KOHL KENNETH	420-8164 7
75	LEYDEN WALTER T	420-3269
95	LUND ELLIS M	420-1920
135	LYNCHEHAN L	427-5541 0
89	MAGERS BEN R	420-0494 0
5	MANGLESS DONALD R	422-9035 5
	MARNETTE OTTO H	425-1149 8
100	MARSH ROBT L	422-1584 7
84	MARTLEY EARL H	420-3368
164	MATHEWS R P	420-0531
108	MCCAMON FRANK	422-2328 5
190	MCKAY W A	420-0578
12	MCKINLEY THOS T--MRS	420-8349 2
102	MEILE R E	422-7419 1
114	MENDENHALL L F	427-3884
17	MERGEN S M	420-4691 4
71	MESTER CHAS H	422-3047 1
145	MILTON FRANCIS J	422-2921 3
45	MITCHELL ROBT H	422-2217
6	MOE C O	420-1041 0
78	MOORE ALICE O	426-0423 1
161	MORRIS WM N	422-7927
44	MULCAHEY WM F	420-5623 3
	MUNTER WILFRED--CDR	422-0293 8
19	NADEAU A	420-3886
186	NEWMAN L L	427-3734 6
	ODELL RONALD H	427-3477+9
2	OGDEN HOWARD	420-0442 1
68	PATTERSON EDMUND L	426-1322
155	PAULEY A E	422-6276
121	PAXTON RALPH JR	420-1147
178	PERRY G H	420-2646
	PETERS M B	425-6974+9
162	PILLA PAUL J	422-2598 6
4	POHL AUSTIN F	427-9254 3
127	POLLARD D H	427-0334
189	PORTER ALFRED L	420-3793
23	PRICE WALKER W	420-5844
88	RANCOURT M L	420-1658 5
	RARICK GUY	425-7936 8
16	REISS ALMA L	422-9057 4
128	RORABECK R S	422-0667
182	RULE EDGAR J	422-6718
170	SCHREIBER M L	420-6354
	SEDILLO BETTA L	422-8072 8
25	SELGO TED W--REV	427-2344 6
	SHELTON H B	426-4157 8
50	SISEMORE NAOMI R	420-4320
141	SKILLEN G LEW	422-8288
	SMULLIN F L	427-5243+9
15	STAGNARO BARTOL MRS	420-9214 0
167	STEVENS E M	422-0696
	STOAKES FREDERICK	425-6657+9
188	STOUDT M U	420-3513 4
192	SUMNER V	420-0660 4
40♦	TERRYS MOBILE PARK	422-0242
83	THOE IRVIN L	426-8908 6
33	THOMAS M F	422-5232
129	THOMAS WENDELL C	427-4296
99	THORNTON C O	427-1371
110	TRAGO RICHARD C	422-7989
117	VALENCIA WALTER S	427-2931 4
57	VANTUYL A M	426-1405 4
39	VANZANTE N M	426-5614 1
147	VAZQUEZ FRANK	427-3963 1
20	VESTAL LYNETTE B	422-1071
113	WALKER ERVIN G	422-0872 5
142	WATKINS ARTHUR E	422-6210
104	WEBBER S M	422-6580
157	WEBSTER LUCILLE	420-4840
	WIDEN ALBERTA E	420-0316 8
173	WILHELMI W D	427-3867 0
91	WILLIAMS FORREST C	422-8539 6
184	WILLIAMS JARRETT R	427-9349 0
116	WILLIAMS M N	422-1709 5
93	WINGFIELD EDWIN J	427-3196
185	WOLL D J	427-1453 0
24	YELLAND WM J	426-6019 3
677		
691	XXXX	00
704	WHITTINGHAM V G	427-8784 8
B	VAUGHN BRUCE	420-1973 8
716	GRAFTON RICHARD JR	425-2478 8
	SPAIN KENNETH C	422-3834+9
724	STEWART LYLIE C	420-7083 8
731	CABRILLO MBL LDG	
	AAROE MURREL R	426-5095 8
28D	ALDER EMMA	420-3117 3
	ATWELL LARRY	422-7436+9
	BALLARD WM	427-3073+9
11A	BIRTHISEL L B	426-5097 5
	BOARD WM D	425-6899+9
14D	BRENNAN E Y	427-5863 3
5B	BUXTON FRED H	420-2621
17A♦	CABRILLO MOBILE LOG	422-0245
24C	CONROE GERALD F	427-4108 5
17C	CORBRAN C A	420-2302 5
21B	DAVIS JOS A	422-5157 2
	DAVIS ROGER D	425-6617+9
16C	DAWSON JOE	420-1587
	DOHERTY EDWARD J	426-2588+9
8B	DONOHUE M E	420-0069
18B	DOUGLASS MAURICE	427-1545 6
	DROZE S L	426-1995+9
18A	DUNGAN K W	425-5567 7

COPYRIGHT HAINES & CO. INC. INFO

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1979


G		92010 CONT	
23C	ENDLICH JOS	426-9715	7
	FARNSWORTH GLADYS	422-4948	8
	FITZGERALD ENID	426-6242	8
22B	FUGATE HARRY R	427-8768	5
6A	GARSKY HARRY	420-7758	5
10B	GRANTHAM FLORENCE	427-2545	5
10B	GRANTHAM PAUL	427-2545	5
	GUTIERREZ ROBERTO	422-0590+	9
18C	HAGEDORN LOUIS E	420-8429	2
3A	HAMBRICK JOE	420-7882	7
12D	HANKS JOE	427-9524	6
10D	HARRIS ALBERT G	427-9494	6
5C	HARTMAN MARION-MRS	427-5338	7
	HAY HAROLD B	427-8972+	9
15D	HEPLER M L	426-8750	3
15E	HILL ALBERT W	426-4627	3
	HOLMES MARETTA F	422-3268+	9
24B	HUME WM C	422-6071	
2B	INMAN G B	427-9722	5
	INMAN LILLIAN	422-4713+	9
23A	JACKSON WM R	426-0784	3
	JAMES THOS F	427-5641	8
	JONES DOROTHY LEE	420-6042+	9
13A	JONES ORPHA M	420-0120	6
4D	JORGENSON VERNON	427-4975	6
15E	KELLER MARGARET MRS	420-2670	
1C	LAVIGNE VICTOR J	427-1854	6
	LONG CLINTON	422-2760+	9
9D	MARSHALL E L	426-2524	6
20B	MARTIN N	427-1584+	9
13B	MAZZARELLI DANL	426-2274	2
	MCWHORTER ROY	420-4953	8
12C	MEYER SARA	420-9180	0
14E	MILLER HERMAN H	427-7555	8
23B	MITCHELL C M	427-7875	7
19D	MOULTON EDW H	422-8681	
25C	MYERS H B	420-6782	7
8C	NOACK ALICE	422-3131	3
12E	NOBLE ROBERTA S	426-4597	7
	OBERG D L	425-9517+	9
12B	OVERSTREET PRICE JR	420-4637	
	PARK ADA M	422-9058	8
20A	PARKINSON MILTON E	422-2449	
8E	PELLERIN JOS A	426-5779	1
4B	PRICE B L	420-3452	1
11B	PUCKETT LILLIAN R	420-8655	3
19C	QUINN WM R	420-9127	
	RATH EDWARD	422-8781+	9
1B	RHODES MARY S	426-3478	3
3B	ROBINSON WM A	426-5685	1
	ROTH J K	427-5623+	9
9A	RYAN G	427-0708	6
	SAUNDERS LESLIE	425-6971+	9
21A	SCHULTZ M A MRS	427-4966	
26A	SEGHERS DOREEN H	422-2903	
	SNOW THOS	426-3239+	9
25D	STEELE HOWARD A	420-5843	
8A	STEIGER HENRY G	422-2555	7
	STINNETT CARTER	427-5858+	9
	SUTTER V	422-8940+	9
7A	VEST JEWEL	420-2328	
26C	WATSON R L	427-5315	6
	WENTWORTH KAREN A	426-2648+	9
17A	WHITE STEWART M	420-7434	
	WHITNEY ESTHER G	425-0125	8
731			
736	BERNAL Z	426-7656+	9
	STARRS JEANNIE	420-7646+	9
A	WISSER J H	425-2528	5
*	29 BUS 652 RES	187 NEW	

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1975

677	....8RJAOWAY TRAILER PK		
14	AJLER EUGENE H	42C-1379	
	ALLEN E	422-7679+5	
133	ANJERSON GEJ K	422-7224	
98	ANOERSJN W A	422-7689	
94	8ARCLAY THEO M	420-9032	
158	8ELL T ROTH	422-18C5	
59	8ESTINY JJS	427-3449	O
13	8EVINGTON EARL P	42C-7595	
178	8EYSTRJM LLOYJ	42C-3113	1
146	8JRTJN EOWIN C	420-1959	
67	8JTTS JJHN 8	420-3573	
132	8RINE WM J	427-18C1	3
4C	*8ROAOWAY TRLR PARK	422-0242	
27	8USCHUR LAURA	426-6589	3
	8YRNE P C	425-4976+5	
	CARTHY FREO	422-0242+5	
65	CHENOWETH R W	422-6662	3
13C	COJK RJLINE	422-1289	
72	CREWS JOHN W	42C-3494	
63	CROPLEY CLYJE P	420-8074	2
49	CSILLAG MURIEL	42C-9284	C
156	OARLON OAVIO	422-6869	1
144	JAU8ER JAS W	42C-7C68	
28	OINI C	420-5398	
136	JJKE RICHARO J	42C-7997	
187	OOUGHERTY FERN MRS	422-6467	C
60	OUNTJN WALLACE W	422-2175	
153	OURHAM HENRY C SR	427-9893	2
174	EOMONJS A E	42C-C316	
138	ELLIOTT M	42C-6669	2
169	ELLIJTT T M	420-2552	

G ST 1975



..G 92010 CONT..

101 ELLZEY ELIZABETH 420-2007 3
150 FARMER EMMA W 427-8837
30 FARR MALCOLM E 420-1926
81 FISHER OSCAR A MRS 420-8205
77 FLACK A B 420-8373 3
7 FUHRMAN ALICE L 422-6262
103 GAPP LORETTA 427-4781
GARCIA JORGE F 426-9390+5
107 GAYESKE WM 420-4577
171 GOEPPER E H 427-0766
90 GOERSS FRITZ 422-5822
115 GREEN FLOYD I 422-9353 4
181 GREEN JERRY L 422-0467
74 GUNTLE M E 420-8151
176 HALL SYDNEY 422-2569
HAMBRICK JOE 420-7882+5
56 HANSEN CARL C 420-4883
66 HANSOM M 427-1315
172 HASELMIRE JOS M 420-5813
35 HATCHER CHARLIE L 422-0203
134 HAYDEN DEWEY M 427-4372
86 HAYS FERN V 420-4146
106 HENDERSON ROBT L 420-4601
79 HENSCHEL JEAN 427-4945 0
22 HINKLE DARYL B 427-1475
HOBBS GEO E 427-4008+5
184 HORST PAUL 426-4237 4
105 HUFF MABEL C 420-5634 1
31 HUFFMAN GUY V 420-0549 1
1 HUNT E B 426-5476 2
64 JEWETT M L 420-1835 3
151 JOHNSON GRACE G 422-2344
JOHNSON ROBT LYNN 427-3195+5
48 JORDAN R V 427-1315
188 KALER EARL B 422-8504
97 KELLOGG EVELYN 420-5693
122 KELLOGG ROY F 422-5575
97 KELLOGG STEARNS W 420-5693
62 KELLY JAS P 426-9923 2
160 KELSO L F CWO USN 422-6235
180 KINCAID GALE J 422-2827
154 KIRCHMAIER WM E 420-0888
52 KIRKPATRICK WALTER 427-1018
165 KISBERT CHAS A 420-6769
80 KRAFT CARL S 427-3608
75 LEYDEN WALTER T 420-3269
95 LUND ELLIS M 420-1920
135 LYNCHEHAN JOHN E 427-5541 0
89 MAGERS BEN R 420-0494 0
MANGLESS DONALD R 422-9035+5
84 MARTLEY EARL H 420-3368
57 MASON J W 426-7266 3
109 MASSAD MIRIAM M MRS 420-8490
164 MATHEWS R P 420-0531
MCCAMON FRANK 422-2328+5
46 MCCURRY JOHN W 427-4849 4
190 MCKAY W A 420-0578
12 MCKINLEY THOS T MRS 420-8349 2
102 MEILE R E 422-7419 1
114 MENDENHALL L F 427-3884
17 MERGEN S M 420-4691 4
71 MESTER CHAS H 422-3047 1
145 MILTON FRANCIS J 422-2921 3
45 MITCHELL ROBT H 422-2217
6 MOE C D 420-1041 0
78 MOORE ALICE D 426-0423 1
163 MOORE E L 427-0781
161 MORRIS WM N 422-7927
44 MULCAHEY WM F 420-5623 3
19 NADEAU A 420-3886
NEUMAN L L 427-3734+5
NOE GERALDINE 422-7261+5
2 OGDEN HOWARD 420-0442 1
37 PARSONS WILBUR T 427-6286 3
68 PATTERSON EDMUND L 426-1322
140 PAUL VERNE G 420-7226
155 PAULEY R F 422-6276
121 PAXTON RALPH JR 420-1147
179 PERRY BARBARA 420-2646
179 PERRY G H 420-2646
123 PLESS CLAUDE D 420-0536
4 POHL AUSTIN F 427-9254 3
127 POLLARD DOLLY H 427-0334
189 PORTER ALFRED L 420-3793
23 PRICE WALKER W 420-5844
RANCOURT M L 420-1668+5
92 REHKEMPER E C 427-3761 0
16 REISS ALMA L 422-9057 4
RESTLE E F 420-7338+5
11 RICHARDSON K D 426-0015 3
128 RORABECK R S 422-0667
36 ROSE P MRS 427-2134 0
182 RULE EDGAR J 422-6718
170 SCHREIBER M L 420-6354
32 SEITZ DALE A 422-4031
50 SISEMORE NAOMI R 420-4320
141 SKILLEN G LEW 422-8288
29 SNELGROVE C H 427-0738 2
175 SPAINHOWER CHAS E 420-7512 3
15 STAGNARO BARTOL MRS 420-9214 0
167 STEVENS E M 422-0696
96 STEWART YETTA ILEEN 422-3518
55 STONESTREET JOHN W 420-5446 4
168 STOUDT M U 420-3513 4
192 SUMNER HOLLY 420-0660
192 SUMNER V 420-0660 4
40 *TERRYS MOBILE PARK 422-0242
THOE IRVIN L 425-4746+5
33 THOMAS M F 422-5232
129 THOMAS WENDELL C 427-4296
99 THORNTON C D 427-1371
110 TRAGO RICHARD C 422-7989
117 VALENCIA WALTER S 427-2931 4
57 VANTUYL A M 426-1405 4
39 VANZANTE N M 426-5614 1
147 VAZQUEZ FRANK 427-3963 1
20 VESTAL LYNETTE B 422-1071
WALKER ERVIN G 422-0872+5
183 WARD E C 420-8348 2
142 WATKINS ARTHUR E 422-6210
104 WEBBER S M 422-6580
157 WEBSTER LUCILLE 420-4840
40 *WESTERGAARD F C 422-0242 0
WESTERGAARD FAY C 420-4610+5

..G 92010 CONT..

58 WIDEN ALBERTA E 420-4107
173 WILHELMI W O 427-3867 0
184 WILLIAMS JARRETT R 427-9349 0
WILLIAMS M N 422-1709+5
93 WINGFIELD EDWIN J 427-3196
185 WOLL O J 427-1453 0
24 YELLAND WM J 426-6019 3
26 YOCKEL FRED R 426-2634 1
677.....
691 XXXX OO
704 WILCOX RALPH 420-7769+5
A NICKOLS JOHN M 426-3069+5
B VAUGHN BRUCE 422-3629+5
716 CONNER J L 427-8422+5
D MAKI K 426-1358+5
724 FREEMAN CHUCK 427-5289+5
731....CABRILLO MOBIL LODGE
24C ACCETTA F E 426-7854 1
11C ADCOCK MYRTLE B 427-8693 0
280 ALDER EMMA 420-3117 3
BIRTHISEL L B 426-5097+5
14D BRENNAN E Y 427-5863 3
BUENO VIRGINIA 420-5286+5
BUTORAC CRAIG 420-1098+5
BUXTON FRED H 420-2621
*CABRILLO MOBILE LOG 422-0245
CAMERON DONALD 425-3720+5
7E CAMPBELL VIRGIL F 422-6876 4
CARRASCO RUDY 425-3083+5
CONROE GERALD F 427-4108+5
CORBRAN C A 420-2302+5
CRUMP EDITH O 420-8908
218 DAVIS JOS A 422-5157 2
DAWSON JOE 420-1587
DONOHUE M E 420-0069
16D ECKER GLADYS 422-4948 2
FUGATE HARRY R 427-8768+5
FULLEN ROLLIE C 420-7092
GARSKY HARRY 420-7758+5
GIBSON WILMA 420-3528+5
188 GORDON EVERETT 420-6881
GRANTHAM FLORENCE 427-2545+5
GRANTHAM PAUL 427-2545+5
18C HAGEDORN LOUIS E 420-8429 2
HARRIS ALICE C 420-4028
HARRIS CLARENCE I 420-4028
HART MABEL B MRS 427-6771
3A HAUSE DICK 420-3224 1
15D HEPLER M L 426-8750 3
HESTER MICHAEL 425-5677+5
HIGBY E L 422-4872
15E HILL ALBERT W 426-4627 3
27A HINSON CHAS 426-5937 4
24A HOLMES MARETTA F 422-3268
HOOKER CHAS L 422-8624+5
HOOKER COLLEEN S 422-8624+5
HUME WM C 422-6071
INMAN G B 427-9722+5
JACKSON WM R 426-0784 3
JONES ORPHA M MRS 420-0120
15E KELLER MARGARET MRS 420-2670
23D LANCASTER BERTHA 426-8964 4
1C LAVIGNE MYRTLE M 427-1854 4
18A LEWIS MICHAEL E 426-6118 3
2C MALKOWSKI FELIX J 427-5064 0
9D MARSHALL WM N 426-2524 2
7D MASSEY LELAH 426-3084 1
MATSON W L 420-7185
138 MAZZARELLI DANL 426-2274 2
MCELENY A W 427-0307+5
MEYER SARA 420-9180 0
MILLER HERMANN H 427-7555
MORRISON MARIE A 426-5741+5
MOULTON EDW H 422-8681
8C NOACK ALICE 422-3131 3
OLSON CARL I 420-2130
OVERSTREET PRICE JR 420-4637
PARKINSON MILTON E 422-2449
PASSMORE P L 427-6848
4E PAYNE L W 420-9113 1
PELLERIN JOS A 426-5779 1
PRICE B L 420-3452 1
PUCKETT LILLIAN R 420-8655 3
16A QUINN WM R 420-9127
268 REED L H 426-8739 3
26D REILLY HUGH E 426-0621 1
18 RHODES MARY S 426-3478 3
RICHARDSON BRUCE J 426-8140+5
ROBINSON WM A 426-5685 1
21A SCHULTZ M A MRS 427-4966
188 SEELEY M 426-8151 3
26A SEGHERS DOREEN H 422-2903
SEILER FRANK R 422-5080+5
2E SIRKEGIAN R R 427-9499 4
SPENCER ELIZABETH 427-4942+5
27A STEELE HOWARD A 420-5843
6E STINNETT CARTER O 427-5722
6E STINNETT VOSIE A 427-5722
SWIFT ORVILLE 427-7854
22A TESAR R S 427-0195
78 VEAL E 427-5338 3
7A VEST JEWEL 420-2328
14C WALKER P L 422-2001 3
22C WARNER GENE 426-1300
19A WESTROPE W T 427-0448
WHELCHEL PAULINE 420-9782
WHITE STEWART M 420-7434
158 WILCOX W B MRS 420-9729
731.....
736 BLY ROBT D 426-5197+5
ESTRADA GUILLERMO 422-8865+5
WILLIAMS WALTER G 420-2297+5
A WISSER J H 425-2528+5
809 XXXX OO
* 25 BUS 657 RES 217 NEW

(92024 ENCINITAS

55 RESECK ALEX D 753-3201
56 DALEY FRANK P 753-2528
215*CLATON TIRE CO 753-6316
*CLAYTON TIRE CO 753-6316 0

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory


G ST 1971

677 BROADWAY TRAILER PK

	ADLER EUGENE H	420-1379
	AORIAN KEITH E	420-3724
	ALLEY BLANCHE	420-7826 D
	ANDERSON GEO K	422-7224
	ANOERSON W A	422-7689
	ARTHUR HOLLAND S	420-9163 O
	AZEVEDO JOE J	427-1720
	BARCLAY THEO M	420-9032
	BARFIELD M C	422-6682
	BELL T ROTH	422-1805
	BESTINY JOS	427-3449 O
	BETTS OALE K	427-6039
	BEVINGTON EARL P	420-7595
	BEYNDN C ED	420-1555
	BEYSTROM LLOYD	420-3113+1
	BLISS BERNIECE MRS	420-4D8D
	BLOOM M E	420-D569
	BORCHERS LAURA E	420-5194
	BORTDN EDWIN C	420-1959
	BOTTS JOHN B	420-3573
	BOZYK B A	420-4857
	BRENNAN P MRS	420-D128
	BRINE WM J MRS	427-1801
*	BROADWAY TRLR PARK	422-D242
	CLAYPOOL ERNEST A	420-5D48
	COOK ROLINE	422-1289
	CODKE FRED	426-5D35+1
	CREWS JOHN W	420-3494
	CSILLAG MURIEL	420-9284 D
	CURTIS NANCY E	420-8348
	DANA WALTER L	427-0871
	OARLON DAVID	422-6869+1
	OAUBER JAS W	420-7D68

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1971




..G 92D1D CONT..

OINI C 420-5398
DDKE RICHARD J 420-7997
DDUGHERTY FERN MRS 422-6467 O
DUNTON WALLACE W 422-2175
OURHAM HENRY C SR 427-9893+1
EDMONDS A E 420-D316
EICHEL HERMAN JR 422-0872 O
ELLIOTT CARL S MRS 420-6669+1
ELLIOTT LOREN J 422-5139+1
ELLIOTT T M 420-2552
FARMER EMMA W 427-8837
FARR MALCOLM E 420-1926
FISHER OSCAR A MRS 420-82D5
FOHRMAN ALICE L 422-6262
GAPP LORETTA 427-4781
GAYESKE WM 420-4577
GOEPPER E H 427-D766
GOERSS FRITZ 422-5822
GREEN JERRY L 422-D467
GROSS HUGH JR 420-2574
GROTHE J A 420-D766
GUNTLE M E 420-8151
HALE GERALDYN B MRS 427-D547
HALL SYDNEY 422-2569
HANSEN CARL C 420-4883
HANSOM M 427-1315
HASELMIRE JOS M 420-5813
HATCHER CHARLIE L 422-D2D3
HAYDEN DEWEY M 427-4372
HAYS FERN V 420-4146
HENDERSON ROBT L 420-46DI
HENSCHEL JEAN 427-4945 D
HINKELMAN FRANCIS 427-2DD3 D
HINKLE DARYL B 427-1475
HOPKINS FRANK W 422-1857
HOUCK KENNETH E 42D-7882
HUFF MABEL C 420-5634+1
HUFFMAN GUY V 420-D549+1
JACKSON PATRICIA A 422-4316+1
JACKSON RUTH MRS 422-3678
JEWETT LYLE C 422-2704
JEWETT M R 420-1835
JOHNSON GRACE G 422-2344
JONES ANNA B 427-6382 O
JORDAN R V 427-1315
KALER EARL B 422-8504
KELLEY FLORENCE 427-2204
KELLOGG EVELYN 420-5693
KELLOGG RDY F 422-5575
KELLOGG STEARNS W 420-5693
KELSO L F CWO USN 422-6235
KINCAID GALE J 422-2827
KING MARION B 422-6381
KIRCHMAIER WM E 420-D888
KIRKPATRICK WALTER 427-1D18
KISBERT CHAS A 420-6769
KRAFT CARL S 427-36D8
LEYOEN WALTER T 420-3269
LUND ELLIS M 420-1920
LYNCHEHAN JOHN E 427-5541 D
MAGERS BEN R 420-D494 D
MARTLEY EARL H 420-3368
MASSAD MIRIAM M MRS 420-84?0
MATHEWS R P 420-D531
MCKAY W A 420-0578
MCKINLEY THOS T 420-8349
MCQUISTON R G 420-7649
MEILE R E 422-7419+1
MENDENHALL L F 427-3884
MERGEN CARL B 420-4691
MESTER CHAS H 422-3D47+1
MILLER FRED J 420-7D59
MITCHELL ROBT H 422-2217
MOE C D 420-1041 O
MOORE ALBERTA 427-0781
MOORE ALICE O 426-D423+1
MOORE E L 427-D781
MORRIS WM N 422-7927
MOSS WALT A 427-1885
NADEAU A 42D-3886
NESTER A LCDR 420-D82I
OGDEN HOWARD 420-D442+1
PALMER WM J 420-2877
PARSONS WILBUR T 427-6286 D
PATTERSON EDMUND L 426-1322
PAUL VERNE G 420-7226
PAULEY R F 422-6276
PAXTON RALPH JR 420-1147
PECK BEATRICE H 420-9714
PERRY BARBARA 420-2646
PERRY G H 420-2646
PETERSON WALTER R 420-29D1+1
PLESS CLAUDE D 420-0536
POLLARD DOLLY H 427-0334
PORTER ALFRED L 420-3793
PRICE WALKER W 420-5844
REHKEMPER E C 427-3761 D
RESTLE EVA MRS 420-7338
RINEHARD B J 420-D781
RORABECK R S 422-D667
ROSE P MRS 427-2134 O
RULE EDGAR J 422-6718
SCHREIBER M L 420-6354
SEITZ DALE A 422-4D31
SISEMORE NAOMI R 420-4320
SKILLEN G LEW 422-8288
SPAINHOWER ELLIS 420-7512
SPEAS ANNA MRS 420-5212 D
STAGNARO BARTOL MRS 420-9214 O
STEPKA E N 420-8151
STEVENS E M 422-D696
STEWART YETTA ILEEN 422-3518
SUMNER HOLLY 420-066D
SUMNER VIRGINIA 420-D660
*TERRYS MOBILE PARK 422-D242
THOMAS M F 422-5232
THOMAS WENDELL C 427-4296
THORNTON C D 427-1371
TRAGO RICHARD C 422-7989
VANZANTE N M 426-5614+1
VAZQUEZ FRANK 427-3963+1
VESTAL LYNETTE B 422-1D71
WADLEY LLOYD G 422-6531
WARD EVE 420-8348

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

G ST 1971



..G $2010 CONT..
WATKINS ARTHUR E 422-6210
WEBBER S M 422-6580
*WEBSTER LUCILLE 420-4840
**WESTERGAARD F C 422-0242 O
WIDEN ALBERTA E 420-4107
WILHELMI W D 427-3867 O
WILLIAMS JARRETT R 427-9349 O
WINGFIELD EDWIN J 427-3196
WOLL D J 427-1453 O
YOCKEL FRED R 426-2634+1

691 GARCIA ESTHER DEL R422-2768
704 POWELL THOS 426-6387+1
716 GRANADOS EDW R 426-6181+1
SPERL RAYMOND 426-4273+1
TOLIVER IRA L 427-1806 O
A FRITCHOFF MARY I 420-1181
724 AHLIN DALE A 426-4306+1
GEVOY RICHARD J 427-4048+1
KOENIG DAVID M 426-7882+1
731 CABRILLO MOBIL LDGE
ACCETTA F E 426-7854+1
AGCOCK MYRTLE B 427-8693 D
BAIR ANNA R 426-2532 D
BELL F M 427-6417
BINKLEY IRA A 420-8209 O
BRADY R F MRS 422-8160
BRENSEL EDNA 420-0708
BUENO KELLY A 420-5286 D
BUXTON FRED H 420-2621
*CABRILLO MOBILE LOG422-0245
CASTOR RUTH MRS 427-5340+1
CHADWICK FRED 420-4614
CORBRAN JOS L 420-2302 D
CROMER E L 420-6304
CRUMP EDITH O 420-8908
CYR EMILE A 420-2946
DAWSON JOE 420-1587
DAY WILLA 426-0462+1
DONOHUE M E 420-0069
ECKER AMBROSE J 422-4948
FULLEN ROLLIE C 420-7092
GORDON EVERETT 420-6881
GUEL ANTONIA H MRS 420-0573
HAGEDORN LOUIS E 427-2822
HARRIS ALICE O 420-4028
HARRIS CLARENCE I 420-4028
HART MABEL B MRS 427-6771
HAUSE DICK 420-3224+1
HENTERSEHER GEO 427-2809
HEPLER MARJORIE L 427-0341 O
HIGBY E L 422-4872
HIRTZLER LOUISE MRS422-8092 O
HOLCER W C 427-3379
HOLMES MARETTA F 422-3268
HUME WM C 422-6071
JACKSON WM R 426-0784
JACOVITCH C MRS 427-4808+1
JONES MELVIN 422-1622
JONES ORPHA M MRS 420-0120
KELLER MARGARET MRS420-2670
KITCHENS TEDDY B 426-2696+1
LAWRENCE WM J 420-8429
LEFEVOUR E H 420-5492
LEON MARTHA FOSSA 422-5907
LEWIS HAZEL M MRS 427-1250 C
LEWIS MICHAEL E 427-1250 C
LINDBERG MARGARET 420-0661+1
MALKOWSKI FELIX J 427-5064 C
MASSEY LELAH 426-3084+1
MATSON W L 420-7185
MCNAMARA F B 427-1901+1
MEYER SARA 420-9180 O
MICK GABRIEL 420-2651
MILLER HERMANN H 427-7555
MORGAN WM 427-4359
MOULTON EDW H 422-8681
OLSON CARL I 420-2130
OLSON LILLY MRS 420-2130
OVERSTREET PRICE JR420-4637
PARKINSON MILTON E 422-2440
PASSMORE P L 427-6848
PAYNE L W 420-9113+1
PELLERIN JOS A 426-5779+1
PRICE B L 420-3452+1
QUINN WM R 420-9127
REILLY HUGH E 426-0621+1
REISS ALMA L 422-9057
RHODES SAML W 422-0245
ROBINSON WM A 426-5685+1
RUSTAD AGNES P 426-0532
SCHULTZ M A MRS 427-4966
SEGHERS DOREEN H 422-2903
SHORT LEO 426-6199+1
SPENCER EARL C LCDR427-4942
STAFFORD HENRY J 427-1586
STEELE HOWARD A 420-5843
STINNETT CARTER O 427-5722
STINNETT VOSIE A 427-5722
SWIFT ORVILLE 427-7854
TASSIN GERALD 427-9626 O
TASSIN PEGGY 427-9626 D
TESAR R S 427-0195
TOWER CHAS W 427-6050+1
VEST JEWEL 420-2328
WARNER GENE 426-1300
WESTROPE W T 427-0448
WHELCHEL PAULINE 420-9782
WHITE LEONARD L 427-4749
WHITE STEWART M 420-7434
WILCOX W B MRS 420-9729
WILLIAMS GUY R 426-7482+1
736 GOSCH SANDRA 426-0982+1
WEHLAGE M L 426-4903+1
809 XXXX 00
* 31 BUS 652 RES 242 NEW

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1965

677 Terry's Mobile Park 422-0242
Pauley Ralph F pntr 422-6276
Roos Cornelis 422-0242
691 Garcia Esther Mrs ◎ 422-2768
695 DelRio Josefa A Mrs
Jefferson intersects
704a-c Vacant
704d Stein Wm V 422-4409
716a Carter Jewell Mrs
716b Smith Geo C 420-5734
716c Osborn Paul G 420-6810
716d Vacant
724a Vacant
724b Flower Robt D 427-2487
724c Vacant
724d Mackenzie Edw H 427-2929
736a Zeller Richd W
736b Walters Clarence C
731 Cabrillo Mobile Lodge 422-0245
Rhodes Saml
736a Cole Arth L 426-4707
736c No Return
736d Vacant
772 Vacant
774 No Return
776 Wrought Iron Specialties 422-3055
809 Tyce Engineering Corp aircraft parts 422-0191
856 Hobart Consolidated bldg contr 422-8361
Hobart Inv Co 422-8361
Johnson H H Constn Co bldg contr 422-8361
Johnson H H Inc bldg contr 422-8361
Johnson H H Development Co bldg contrs 422-8361
Johnson-Tyson & Lynds bldg contr 422-8361
Seabrook Reginald S loans 422-1173
Williams Harry L bldg contr 422-1133
ft Chula Vista Animal Shelter 422-2669

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1960

Broadway intersects

605 Mills Benj L
850 Harms Edw W ΔGA2-1216
856 Hobart Homes Inc bldg contrs
ΔGA2-8361
Johnson H H Constn Co bldg contrs
ΔGA2-8361
Johnson H H Development Co bldg
contrs ΔGA2-8361
Johnson H H Inc bldg contrs
ΔGA2-8361
Morgan John B Constn Co
ΔGA2-8333
Wilco Development Co real est
ΔGA2-1173
610 Linthicum Anna L Mrs @
ΔGA2-1540
610a Moffett Newton
610b Benton Jas T ΔHA0-6347

Target Street	Cross Street	Source
✓	-	POLK DIRECTORY CO

G ST 1960

628 Traukel Maurice D ®
ΔGA2-1974
629 Howell Agnes P Mrs ®
ΔGA2-3651
644 Culnan Edgar B ® ΔGA2-6321
rear Williams Donald
649 Mullenix Robt D
677 Terry's Trailer Park ΔGA2-0242
Roos Cornelis ΔGA2-0242
691 Garcia Esther Mrs ®
ΔGA2-2768
Bay blvd intersects
731 Cabrillo Mobile Lodge ΔGA2-0245
Rictor Alf
Pierson Wm E
772 Bollin John T ΔGA2-2725
744 Romaine Van
776 Vacant
809 Tyce Engineering Corp air craft
parts ΔGA2-0191
Williams Harry L bldg contrs
ΔGA2-1133
Seabrook Reginald S loans
ΔGA2-1173
ft Animal Shelter ΔGA2-2669


39

National av intersects

610 Linthicum Everett C @ ΔGA2-1540
610a Polk Jerry
610b Swaboda Robt
628 Woodward Chas W ΔGA2-7423
629 Howell Agnes P Mrs @ ΔGA2-3651
644 Culnan Edgar B @ ΔGA2-6321
691 Garcia Manuel @ ΔGA2-2768
698 Azuma Takeo @ ΔGA2-3220

Bay blvd intersects

772 Bolin Jeff J ΔGA2-3776
774 Bolin John T ΔGA2-2725
809 Tyce Engineering Corp air craft parts ΔGA2-0191
848 Pioneer Pyrophyllite Producers insect powder mfrs ΔGA2-2992
Redlite Aggregate Co bldg matls ΔGA2-2992
850 Harms Edw W ΔGA2-1216
856 Construction Service Bldg
Cotton Constn ΔGA2-5371-72
Edwards Leslie H Co ΔGA2-5319
Electrical Constructors ΔGA2-1173
Hobart Homes Inc real est ΔGA2-1175
Johnson H H Constn Co genl contrs ΔGA2-1171
Johnson H H Inc genl contrs ΔGA2-1171
Williams Harry L genl contrs ΔGA2-1133




TP, San Diego, 1904, 15-minute

0 Miles 0.25 0.5 1 1.5

N

Key: Subject Property



TP, San Diego, 1930, 15-minute

0 Miles 0.25 0.5 1 1.5

N

Key: Subject Property



TP, National City, 1944, 7.5-minute
SE, San Ysidro, 1943, 7.5-minute
NW, Point Loma, 1942, 7.5-minute

0 Miles 0.25 0.5 1 1.5


N

Key: Subject Property

APPENDIX B: Topographic Maps

Project No. 20-302755.1

PARTNER



TP, National City, 1953, 7.5-minute
SE, San Ysidro, 1953, 7.5-minute
NW, Point Loma, 1953, 7.5-minute

0 Miles 0.25 0.5 1 1.5


N

Key: Subject Property

APPENDIX B: Topographic Maps

Project No. 20-302755.1

PARTNER




UNMAPPED

TP, National City, 1967, 7.5-minute
NW, Point Loma, 1967, 7.5-minute

0 Miles 0.25 0.5 1 1.5

N

Key: Subject Property



TP, National City, 1975, 7.5-minute
S, Imperial Beach, 1975, 7.5-minute
NW, Point Loma, 1975, 7.5-minute

0 Miles 0.25 0.5 1 1.5

N

Key: Subject Property

APPENDIX B: Topographic Maps

Project No. 20-302755.1

PARTNER



TP, SAN DIEGO, 1991, 15-minute

0 Miles 0.25 0.5 1 1.5


N

Key: Subject Property

APPENDIX B: Topographic Maps

Project No. 20-302755.1

PARTNER



TP, National City, 1996, 7.5-minute
S, Imperial Beach, 1996, 7.5-minute
NW, Point Loma, 1996, 7.5-minute

0 Miles 0.25 0.5 1 1.5

N

Key: Subject Property

APPENDIX B: Topographic Maps

Project No. 20-302755.1

PARTNER



TP, National City, 2012, 7.5-minute
SE, Imperial Beach, 2012, 7.5-minute
SW, Imperial Beach OE W, 2012, 7.5-minute
NW, Point Loma, 2012, 7.5-minute

0 Miles 0.25 0.5 1 1.5

N

Key: Subject Property

APPENDIX B: Topographic Maps

Project No. 20-302755.1

Jared Blumenfeld
Secretary for
Environmental Protection

Department of Toxic Substances Control
Meredith Williams, Ph.D., Director
1001 "I" Street
P.O. Box 806
Sacramento, California 95812-0806

Gavin Newsom
Governor

Facility Search Results

Selection Criteria:

Facility:
Search on: Physical Address
Street: 850 Lagoon
City: Chula Vista
Status: Active and Inactive
Sort Direction: asc
Sorted By: EPA ID
Records Found: 4

EPA ID Number	Name	Address	City	Zip
CAC002577707	THE PORT OF SAN DIEGO	850 LAGOON DR	CHULA VISTA	91910
CAC003056223	GOODRICH AEROSTRUCTURES, CHULA VISTA	850 LAGOON DRIVE	CHULA VISTA	91910
CAD008382053	ROHR INC., A COLLINS AEROSPACE COMPANY	850 LAGOON DR	CHULA VISTA	919102001
CAL000297149	PORT OF SAN DIEGO	850 LAGOON DR	CHULA VISTA	919102001

The Department of Toxics Substances Control (DTSC) takes every precaution to ensure the accuracy of data in the Hazardous Waste Tracking System (HWTS). However, because of the large number of manifests handled, inaccuracies in the submitted data, limitations of the manifest system and the technical limitations of the database, DTSC cannot guarantee that the data accurately reflect what was actually transported or produced.


Report Generation Date: 02/02/2021

Site Report

ROHR INC., A COLLINS AEROSPACE COMPANY

850 LAGOON DR
CHULA VISTA, CA 91910

County	San Diego County
CalEnviroscreen 3.0 Percentile Range	76-80%



SIC Codes

3728	Aircraft equipment, n.e.c.

NAICS Codes

336413	Other Aircraft Parts and Auxiliary Equipment Manufacturing

Alternate IDs

Dun & Bradstreet Number	004467452	**Facilities Explorer ID**	400868
FRS	110000478518	**EPA Identifier**	CAD008382053
Facility Identifier	37-000-102457		

Regulatory Programs

Description	Source System	Program Id	Start Date	End Date
Aboveground Petroleum Storage	California Environmental Reporting System	10123903	07/10/2013	
Chemical Storage Facilities	California Environmental Reporting System	10123903	07/10/2013	
Hazardous Waste Generator	California Environmental Reporting System	10123903	07/10/2013	

Description	Source System	Program Id	Start Date	End Date
RCRA LQ HW Generator	California Environmental Reporting System	10123903	07/10/2013	

Site Contacts

Name	Title	Phone	Address
JENNY LUMN	ENVIRONMENT, HEALTH & SAFETY SPECIALIST		850 LAGOON DR., MAIL ZONE M02 CHULA VISTA, CA 91910
Mailing Address			850 LAGOON DRIVE, MAIL ZONE 1-C CHULA VISTA, CA 91910-2098
ROHR INC., A COLLINS AEROSPACE		(619) 691-4111	850 LAGOON DR, MAIL ZONE 1-C Chula Vista, CA 91910
ROHR INC., A COLLINS AEROSPACE COMPANY		(619) 691-4111	
ROHR, INC., A COLLINS AEROSPACE COMPANY		(619) 691-4111	850 LAGOON DR Chula Vista, CA 91910
San Diego County Env Health		(858) 505-6880	PO Box 129261 San Diego, CA 92112-9261

ROHR INC., A COLLINS AEROSPACE COMPANY

850 LAGOON DR
CHULA VISTA CA 91910

Chemical Storage

REPORTING PERIOD	SUBMITTED ON
2020	04/09/2020

Chemicals

Name	Max Daily Amount / Unit	Avg Daily Amount / Unit	Days Onsite	Physical
2% OXYGEN IN ARGON 4460-0142-007813	0-2599 Cubic Feet	0-2599 Cubic Feet	365	Gas, Mix
2-BUTANOL (862-01394-006194)	60-119 Gallons	12-59 Gallons	365	Liquid, M
2-BUTOXYETHANOL (4490-0431-005081)	60-119 Gallons	12-59 Gallons	365	Liquid, M
2-Ethylhexyl 7-oxabicyclo[4 1 0] heptane-3-carboxylate (824-98580-008597)	60-119 Gallons	12-59 Gallons	365	Liquid, M
2-PROPANOL (4490-0498-007895)	120-599 Gallons	12-59 Gallons	365	Liquid, M
4-(2-NITROBUTYL) MORPHOLINE (5655-0633-002304)	60-119 Gallons	12-59 Gallons	365	Liquid, M
ACETIC ACID, 56% DILUTION (4015-0123-016292)	60-119 Gallons	12-59 Gallons	365	Liquid, M
ACETONE (6445-0261-011937/6445-0029-011937)	120-599 Gallons	60-119 Gallons	365	Liquid, F
ACETYLENE (4460-0133-012223)	0-2599 Cubic Feet	0-2599 Cubic Feet	365	Gas, Pur
Air	260000-649999 Cubic Feet	130000-259999 Cubic Feet	365	Gas, Mix
ALIPHATIC HYDROCARBONS (5655-0157-001724)	60-119 Gallons	12-59 Gallons	365	Liquid, M
ALIPHATIC HYDROCARBONS (STODDARD TYPE) (5655-0850-009823)	60-119 Gallons	12-59 Gallons	365	Liquid, M
ALKYL DIMETHYL BENZYL AMMONIUM CHLORIDE (4490-0450-003048)	120-599 Gallons	12-59 Gallons	365	Liquid, M

+	ALODINE 1200S (4060-0009-006327)	600-1199 Gallons	60-119 Gallons	365	Liquid, M
+	ALUMINUM OXIDE 80-240 GRIT	1000-4999 Pounds	100-499 Pounds	365	Solid, Mi
+	AMINE MIXTURE (9310-0032-014069)	120-599 Gallons	12-59 Gallons	365	Liquid, M
+	AMMONIUM BIFLUORIDE (4015-0013-006809)	1000-4999 Pounds	0-99 Pounds	365	Solid, Mi
+	ARGON (4460-0113-001765)	2600-12999 Cubic Feet	0-2599 Cubic Feet	365	Gas, Pur
+	ARGON (4460-0300-001765)	2600-12999 Cubic Feet	0-2599 Cubic Feet	365	Gas, Pur
+	BACTERIAL CONCENTRATE (4490-0480-006962)	120-599 Gallons	0-11 Gallons	365	Liquid, M
+	BORIC-SULFURIC ACID	3000-5999 Gallons	3000-5999 Gallons	365	Liquid, M
+	CALCIUM CHLORIDE (4460-1346-008340)	1200-2999 Gallons	120-599 Gallons	365	Liquid, M
+	CASTOR OIL (5655-0161-002569)	600-1199 Gallons	12-59 Gallons	365	Liquid, P
+	CAUSTIC SODA 50% LIQUID (4015-0106-011232)	3000-5999 Gallons	3000-5999 Gallons	365	Liquid, M
+	CHEVRON DELO 400 (5655-0814-008934)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	diethyl toluene diamine	600-1199 Gallons	120-599 Gallons	365	Liquid, M
+	DIETHYLENE GLYCOL MONOBUTYL ETHER (4490-0504-008104)	120-599 Gallons	12-59 Gallons	365	Liquid, M
+	DIGLYCOLAMINE (6445-0102-000276)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	Dioctyl Azelate	60-119 Gallons	12-59 Gallons	365	Liquid, P
+	diphenylmethadiisocyanate, isomeres	600-1199 Gallons	120-599 Gallons	365	Liquid, M
+	DRY ICE SOLID BLOCKS (4460-0092-001294)	500-999 Pounds	100-499 Pounds	365	Solid, Pu
+	ethoxylated alcohol (4490-0617-002673)	12-59 Gallons	12-59 Gallons	365	Liquid, M
+	ETHOXYLATED ALCOHOLS (4490-0380-003218)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	Ethylene Glycol (4460-0290-000104)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	EXCLUDED RECYCLABLE MATERIAL, RINSE WATER FROM CHEM PROCESS	60000-119999 Gallons	12000-59999 Gallons	365	Liquid, M
+	GARNET	1000-4999 Pounds	100-499 Pounds	365	Solid, Pu
+	GAS OIL (5655-0084-000245)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	GLYCERINE (5655-0797-008094)	60-119 Gallons	12-59 Gallons	366	Liquid, M
+	HELIUM (4460-0105-012301 / 4460-0251-001766 / 4592-0109-014835)	13000-25999 Cubic Feet	2600-12999 Cubic Feet	365	Gas, Pur
+	HYDRAULIC FLUID (5655-0860-010141)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	ISOPROPYL ALCOHOL (6445-0052-010892)	60-119 Gallons	12-59 Gallons	365	Liquid, F

+	KEROSENE ODORLESS (5655-0950-011892)	60-119 Gallons	12-59 Gallons	365	Liquid, P
+	MIBK/MEK SOLVENT (6445-0092-004341)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	MICROBIOCIDE (504 LB DRUM) (4460-0544-008608)	600-1199 Gallons	120-599 Gallons	365	Liquid, M
+	MINERAL OIL (4460-1258-007392)	60-119 Gallons	12-59 Gallons	365	Liquid, P
+	MOBIL DTE OIL EXTRA HEAVY (5655-0026-000250)	120-599 Gallons	60-119 Gallons	365	Liquid, M
+	NAPHTHLENE (5655-0488-00198)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	NITRIC ACID (4015-0028-011253)	3000-5999 Gallons	3000-5999 Gallons	365	Liquid, M
+	NITROGEN (4592-0070-012009 / 4460-0107-002034)	120-599 Gallons	120-599 Gallons	365	Liquid, P
+	NITROGEN (4460-0094-002034 / 4460-0454-002034 / 4460-0454-002034 / 4460-0250-002034 / 4460-1302-002058)	2600-12999 Cubic Feet	0-2599 Cubic Feet	365	Gas, Pur
+	OXYGEN (4460-0093-002914)	0-2599 Cubic Feet	0-2599 Cubic Feet	365	Gas, Pur
+	OXYGEN 6 PACK (4460-1301-002057)	2600-12999 Cubic Feet	0-2599 Cubic Feet	365	Gas, Pur
+	PETROLATUM (5655-0059-000154)	60-119 Gallons	12-59 Gallons	365	Liquid, P
+	PETROLEUM	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PETROLEUM (5655-0082-000170)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PETROLEUM (5655-0207-000995)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PETROLEUM (5655-0211-000186)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PETROLEUM (5655-0245-000169)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PETROLEUM (5655-0985-015027)	60-119 Gallons	12-59 Gallons	365	Liquid, P
+	PETROLEUM DISTILLATES (5655-0242-000171)	3000-5999 Gallons	3000-5999 Gallons	365	Liquid, M
+	PETROLEUM DISTILLATES (5655-0640-000254)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PETROLEUM DISTILLATES (5655-0696-005002)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PETROLEUM DISTILLATES 5655-0177-000533	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PETROLEUM HYDROCARBON (6445-0017-010615)	60-119 Gallons	12-59 Gallons	365	Liquid, P
+	PETROLEUM OIL (5655-0911-011665)	60-119 Gallons	12-59 Gallons	365	Liquid, P
+	plaster of paris (9310-9993-001205)	1000-4999 Pounds	0-99 Pounds	365	Solid, Mi
+	POLYALPHAOLEFIN (5655-0946-012883)	60-119 Gallons	12-59 Gallons	365	Liquid, M
+	PROPANE LIQUID (5655-0655-003121 / 4460-1189-003121)	1200-2999 Gallons	600-1199 Gallons	365	Liquid, P
+					

	PROPYLENE GLYCOL (5115-0019-009474)	60-119 Gallons	12-59 Gallons	365	Liquid, N
+	PROPYLENE GLYCOL PHENYL ETHER (4490-0433-001472)	60-119 Gallons	12-59 Gallons	365	Liquid, N
+	REFINED MINERAL OIL (5655-0081-000247)	60-119 Gallons	12-59 Gallons	365	Liquid, N
+	REFINED MINERAL OIL (5655-0238-000234)	60-119 Gallons	12-59 Gallons	365	Liquid, N
+	secondary alcohol ethoxylate (5850-0013-001184)	60-119 Gallons	12-59 Gallons	365	Liquid, N
+	SODIUM BISULFITE (4460-0472-003186)	1200-2999 Gallons	600-1199 Gallons	365	Liquid, N
+	SODIUM HYPOCHLORITE 12.5% (4460-0209-002968)	120-599 Gallons	120-599 Gallons	365	Liquid, N
+	SODIUM NITRITE SOLUTION (5655-0736-006517 / 5655-0980-006517)	120-599 Gallons	60-119 Gallons	365	Liquid, N
+	SODIUM SILICATE SOLUTION (4490-0531-005752)	120-599 Gallons	120-599 Gallons	365	Liquid, N
+	SULFURIC ACID (4015-0108-011593)	3000-5999 Gallons	3000-5999 Gallons	365	Liquid, N
+	SULFURIZED ANIMAL FATTY ACID ALKYL ESTERS (5655-0020-001514)	60-119 Gallons	12-59 Gallons	365	Liquid, N
+	TALLOW (5655-0865-005822)	60-119 Gallons	12-59 Gallons	365	Liquid, N
+	TOLUENE (6445-0009-001354)	60-119 Gallons	12-59 Gallons	365	Liquid, N
+	WASTE 121 CAUSTIC SOL'N WITH METALS*	3000-5999 Gallons	3000-5999 Gallons	365	Liquid
+	WASTE 121 WASTE CAUSTIC SOL'N WITH METALS	3000-5999 Gallons	3000-5999 Gallons	365	Liquid
+	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG	3000-5999 Gallons	3000-5999 Gallons	365	Liquid
+	WASTE 134 WASTE OIL & MIXED OIL*	3000-5999 Gallons	1200-2999 Gallons	365	Liquid
+	WASTE 135 UNSPECIFIED AQUEOUS SOL'N	3000-5999 Gallons	3000-5999 Gallons	365	Liquid
+	WASTE 135 UNSPECIFIED AQUEOUS SOL'N	3000-5999 Gallons	3000-5999 Gallons	365	Liquid
+	WASTE 151 ASBESTOS CONTAINING WASTE	500-999 Pounds	100-499 Pounds	365	Solid
+	WASTE 172 METAL DUST & MACHINING WASTE	5000-9999 Pounds	1000-4999 Pounds	365	Solid
+	WASTE 181 INORGANIC SOLID WASTE (OTHER) -	0-99 Pounds	0-99 Pounds	365	Solid
+	WASTE 181 INORGANIC SOLID WASTE (OTHER) --	100-499 Pounds	0-99 Pounds	365	Solid
+	WASTE 181 INORGANIC SOLID WASTE (OTHER)*	1000-4999 Pounds	1000-4999 Pounds	365	Solid
+	WASTE 181 INORGANIC SOLID WASTE (OTHER)*	5000-9999 Pounds	1000-4999 Pounds	365	Solid
+	WASTE 181 INORGANIC SOLID WASTE (OTHER)*	100-499 Pounds	0-99 Pounds	365	Solid
+	WASTE 181 INORGANIC SOLID WASTE PAINT FILTERS	1000-4999 Pounds	1000-4999 Pounds	365	Solid
+	WASTE 214 UNSPEC SOLVENT MIXTURE	120-599 Gallons	120-599 Gallons	365	Liquid

+	WASTE 222 OIL/WATER SEPARATION SLUDGE	120-599 Gallons	12-59 Gallons	365	Liquid
+	WASTE 241 TANK BOTTOM WASTE	1000-4999 Pounds	100-499 Pounds	365	Solid
+	WASTE 241 TANK BOTTOM WASTE	1000-4999 Pounds	500-999 Pounds	365	Solid
+	WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE	3000-5999 Gallons	3000-5999 Gallons	365	Liquid

100 rows

Page: 1 of 2

ROHR INC., A COLLINS AEROSPACE COMPANY

850 LAGOON DR
CHULA VISTA CA 91910

PROFILE MAP REGULATORY PROGRAMS COMPLIANCE CHEMICALS

Chemical Storage

REPORTING PERIOD	SUBMITTED ON
2020	04/09/2020

Chemicals


Name	Max Daily Amount / Unit	Avg Daily Amount / Unit	Days Onsite	Physical
WASTE 352 ORGANIC SOLIDS (OTHER)	5000-9999 Pounds	1000-4999 Pounds	365	Solid
WASTE 352 ORGANIC SOLIDS (OTHER) -	10000-24999 Pounds	5000-9999 Pounds	365	Solid
WASTE 461 PAINT SLUDGE	1000-4999 Pounds	1000-4999 Pounds	365	Solid
WASTE 611 CONTAMINATED SOIL	50000-74999 Pounds	1000-4999 Pounds	365	Solid
WASTE 723 LIQUIDS W CHROMIUM - R	3000-5999 Gallons	600-1199 Gallons	365	Liquid
WASTE 791 LIQUIDS WITH PH <OR= 2	3000-5999 Gallons	600-1199 Gallons	365	Liquid
WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*	3000-5999 Gallons	1200-2999 Gallons	365	Liquid
WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*	3000-5999 Gallons	3000-5999 Gallons	365	Liquid
WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*	3000-5999 Gallons	3000-5999 Gallons	365	Liquid
WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*	3000-5999 Gallons	600-1199 Gallons	365	Liquid
WASTE 901 INFECTIOUS WASTE, GENERAL	0-99 Pounds	0-99 Pounds	365	Solid
WASTE 902 INFECTIOUS WASTE, SHARPS	0-99 Pounds	0-99 Pounds	365	Solid
WASTE MACHINING COOLANT	600-1199 Gallons	120-599 Gallons	365	Liquid
WASTE WATER 171 FILTER CAKE METAL SLUDGE	10000-24999 Pounds	10000-24999 Pounds	365	Solid
WASTE WATER WITH METALS	12000-59999 Gallons	12000-59999 Gallons	365	Liquid

+	WASTE WATER WITH METALS	12000-59999 Gallons	12000-59999 Gallons	365	Liquid

100 rows

Page: 2 of 2

1



Sites Shown on Map: 204 Total Sites | 185 Open Sites | 19 Closed Sites | 13 Sites w/Water Quality Data

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
SAN DIEGO REGION

CLEANUP AND ABATEMENT ORDER NO. 98-08
(Revised April 2, 1998)

AEROSTRUCTURES GROUP OF BF GOODRICH AEROSPACE (formerly ROHR, INC.) AND THE BF GOODRICH COMPANY
850 Lagoon Drive, Chula Vista
San Diego County, California

1. The Aerostructures Group of the Aerospace Division of the BF Goodrich Co. (formerly Rohr, Inc., and hereinafter referred to as Rohr) discharged various wastes from its manufacturing operations at 850 Lagoon Drive in Chula Vista, San Diego County. Rohr has discharged chlorinated solvents, metals, and fuel hydrocarbons to soil and ground water in multiple locations and metals into the storm water conveyance system serving the site. Other wastes associated with metal melting, metal casting, metal parts fabrication, degreasing, cleaning, anodizing, plating, chemical milling, conversion coating, painting, and sludge treatment/recycling activities may have been discharged. Discharges of waste from the storm water conveyance system, whether from within the system or infiltrative, are carried to San Diego Bay by daily tidal flux and storm water. Discharges of waste from Rohr have caused an exceedance of water quality objectives in ground water and surface water.

2. In December 1997, BF Goodrich acquired Rohr and the facility is now known as the Aerostructures Group of the Aerospace Division of BF Goodrich.

3. This enforcement action is exempt from the provisions of the California Environmental Quality Act (Public Resources Code, §21000 et seq.) in accordance with §15321, Chapter 3, Title 14, California Code of Regulations.

IT IS HEREBY ORDERED that BF Goodrich Aerospace (formerly Rohr, Inc.) and The BF Goodrich Company of Richfield, Ohio, hereinafter "the Dischargers," shall cleanup the waste and the effects of the discharges in a manner that conforms with State Water Resources Control Board Resolution No. 92-49[1] and shall:

A. PROVIDE A SITEWIDE ENVIRONMENTAL SITE ASSESSMENT

The Dischargers shall conduct an **Environmental Site Assessment**, commonly known as a Phase One Site Assessment, and submit a report to the San Diego Regional Water Quality Control Board (SDRWQCB) by **June 4, 1998.**

1) The **Environmental Site Assessment Report** (hereinafter **Phase One Report**) shall provide comprehensive documentation of historical through present-day facility uses, subsurface infrastructure, and disposal practices. Activities conducted to develop the Phase One Report should be equivalent to the ASTM Standard Practices for Environmental Site Assessments.

The approximate date(s) and specific location(s) of operation(s) relative to permanent references or current surface features should be included. Drawings should be provided in an appropriate and consistent scale and a comprehensive set of aerial and other photographs should be included.

2) Site plot plans should clearly illustrate the current and historical alignments and locations of the following features:

i. Stormdrains, drainage conveyances (including former earthen/clay lined pipes or flumes), and subsurface utilities and/or backfilled utility trenches.
ii. Each building and surface improvement (e.g. roads, fences, tracks).
iii. All sumps, oil/water separators, clarifiers, impoundment area(s), and other liquid waste disposal features including the associated discharge points.
iv. All waste dumps, burn dumps, treatment/recycling features, and other significant waste storage and solid waste disposal areas.
v. All fuel docks, chemical transfer stations, chemical dispensing, chemical baths, degreasers, metal washing, and other waste generating industrial activities.
vi. All storage vessels of fuels, oils, and hazardous products or wastes that are or were aboveground, belowgrade, and underground.
vii. All areas where rocket fuel, rocket propellant, munitions, or explosives were fired, tested, or otherwise used.
viii. Current and former discharge outfalls to San Diego Bay that are/were within 1000 ft bayward of the 1940s shoreline from Gunpowder Point to 1000 feet south of J Street.
ix. The inland reach of tidal marine waters within the stormdrains or other subsurface conveyance systems.

All current and former extensions to San Diego Bay or its tributary waters of any of the above features should also be included. Access openings and current and former connections to subsurface drainage systems of all of the above features should also be detailed.

3) Lists and explanations of primary materials used, wastes generated, and waste disposal practices should be included and should be integrated with or keyed to the plot plans. Hazardous material storage and dispensing areas should also be described and depicted graphically.

4) Areas of known or suspected hydrological connection(s) between surface water and ground water should be described and depicted graphically.

B. CONDUCT COMPREHENSIVE STORM WATER RUNOFF SAMPLING

The Dischargers shall conduct a **Storm Water Runoff Sampling Program** and submit a report to the SDRWQCB by **May 11, 1998.** The comprehensive **Storm Water Sampling Report** shall contain the results of implementing the following required elements:

1) For each storm water conveyance collect concurrent samples from the following four locations **during the next storm:**
   - i. the most downgradient, nontidally-influenced, accessible portion of the storm water conveyance system (hereinafter SWCS) for each facility catchment.
   - ii. every drainage outfall along the property line,
   - iii. every drainage outfall located beyond the property line to which Rohr is the sole or primary contributor of runoff (e.g. outfall to F&G Street Marsh), and
   - iv. every sampling location from which previous samples have been collected pursuant to the General Industrial Storm Water Permit not described under i, ii, or iii above.

2) At the terminus of all SWCS outfalls to which Rohr is the sole or primary storm water contributor, collect at least one sample of the flow during dry weather. This sampling shall only be performed after one week of dry weather (no rainfall) and only during a low tide when the flow within the storm drain is in the outgoing (seaward) direction.

3) Analytical sampling required in 1) and 2) above shall be performed using USEPA-approved methods which have detection levels appropriate for comparison with both fresh and marine water quality objectives. At a minimum, the following constituents should be tested in all samples:
   - i. Priority Pollutant Metals;
   - ii. Volatile Organic Compounds (including PCE, TCE, MTBE and Methylene Chloride)
   - iii. Total Petroleum Hydrocarbons;
   - iv. Polynuclear Aromatic Hydrocarbons;
   - v. Semi-Volatile Organic Compounds;
   - vi. pH;
   - vii. TDS;
   - viii. Specific Conductance

4) Adequate quality assurance and quality control (QA/QC) procedures for sampling must be used and photodocumentation of field conditions and sampling locations is required

5) Copies of the **analytical laboratory sampling reports** for the sampling described in B.1) and 2) above shall be submitted, along with the laboratory QA/QC materials and the chain-

of-custody documents, to the SDRWQCB **within three working days of the date originally received** by the Dischargers.

C. CONDUCT A COMPREHENSIVE STORM WATER CONVEYANCE SYSTEM INVESTIGATION

The Dischargers shall conduct a comprehensive investigation of the storm water conveyance system (SWCS) that drains all property formerly or currently controlled by the Dischargers. The property to be investigated shall include San Diego Unified Port District tideland areas where the Dischargers have operated. A **Comprehensive Storm Water Conveyance System Investigation Report (SWCS Investigation Report)** shall be submitted to the SDRWQCB by **July 13, 1998.** The following elements are required:

1) The alignments, openings, connections, and flow gradients of the SWCS must be identified on map(s), whether or not the conveyances are currently in use. Each outdoor storm drain inlet and indoor floor drain opening shall be detailed, the approximate catchment area for each delineated, and the status of use (e.g. open, covered, permanently sealed, etc.) of the opening described. The competency of the SWCS must be thoroughly evaluated. To locate ends, openings, and interconnection(s), activities such as dye and smoke tests, geophysical techniques or video must be performed. Documentation of all field activity shall be included.

2) A description of flows which are or have been transported in each conveyance. At minimum, the description should distinguish flow which originates from precipitation (e.g. rain, snow), commonly called "storm water," from flow which originates from all sources other than precipitation, commonly called "non-storm water." The description shall also include the approximate timeframe each conveyance, or portion of each, was used for a distinct flow type (e.g. pipeline 'AB' held non-storm water-specifically degreasing process wastewater from the north east portion of Building 18 from 1955 to 1962). Elevation drawing showing San Diego Bay tidal influence at both low and high tides within all conveyances originating from the Dischargers' property shall also be included.

3) Either concurrently or subsequently to activities 1) and 2) above, a flow quality investigation shall be conducted after a 1 week period of dry weather. For any sediment, sludge, or liquids found within the SWCS at or during low tide, a sample shall be taken, characterized, and analyzed. Field observations of the condition of that portion of the SWCS where the sediment, sludge or liquid was found shall be documented and submitted.

4) The Dischargers **may** elect to proceed with sealing, removing, cleaning out, otherwise repairing, or replacing (as appropriate) any portion of the SWCS conveyance to abate or prevent future discharges. Consideration of protecting the quality of both surface water(s)

and of ground water should be incorporated into these decision(s). All such activities undertaken from the date of this order shall be documented **until otherwise notified.**

5) **In the future,** a study of the integrity of the SWCS and an evaluation of its utilization and capacity for conveying storm water runoff may be required. Any requirement for such a study may be requested **at a date to be determined.**

D. PERFORM SITEWIDE DATA COMPILATION AND EVALUATION

The Dischargers shall compile and evaluate all geologic, hydrogeologic, geochemical, and soil and ground water quality monitoring data generated within the last 10 years. The Dischargers shall submit a **Data Compilation and Evaluation Report (Data Evaluation Report)** to the SDRWQCB on or before **May 27, 1998.**

1) The land area to be addressed shall include all current and former property used, leased, or otherwise controlled by the Dischargers since its inception on the Chula Vista waterfront as Rohr Aircraft Company. The Data Evaluation Report shall also incorporate all available data on properties that are in the upgradient (by ground water direction) of this land area and west of Interstate 5.

2) Data taken from original data source documents should be thoroughly referenced (e.g. document names, page numbers, dates, etc.) in the Data Evaluation Report.

E. INTERIM REMEDIAL ACTION(S)

The Dischargers shall conduct an **Interim Remedial Action** as necessary to abate or correct the effects of the discharge and/or to mitigate emergency situations.

1) Interim remedial actions may occur concurrently with any other phase of soil and water investigation and/or cleanup and abatement.

2) The Dischargers may submit proposals for appropriate interim remedial action(s) for consideration by the SDRWQCB **at any time** during the cleanup and abatement process.

PROVISIONS

No Nuisance:

Neither the treatment nor the discharge of wastes shall create a condition of pollution or nuisance.

Investigative Derived Wastes:

The Dischargers shall properly manage, treat and/or dispose of contaminated soils and ground water in accordance with applicable federal, state, and local regulations. Additional regulatory action may be required to obtain proper permits for remedial actions, waste discharges, and related activities.

Good Operation and Maintenance:

The discharger shall maintain and operate, as efficiently as possible, any facility or control system installed to achieve compliance with the requirements of this Order.

Access to Site and Records:

The Dischargers shall permit the SDRWQCB or its authorized representative:

i. Entry upon premises in which any pollution source exists, or may potentially exist, or in which any required records are kept, which are relevant to this Order.
ii. Access to copy any records required to be kept under the requirements of this Order.
iii. Inspection of any monitoring or remediation facilities installed in response to this Order.
iv. Sampling of any ground water or soil which is accessible, or may become accessible, as part of any investigation or remedial action program undertaken by the Discharger.

Contractor/Consultant Qualifications:

All hydrogeologic documents (plans, specifications, and reports) shall be signed by and stamped with the seal of a California Registered Geologist, a Specialist Geologist, California Certified Engineering Geologist, or a California Registered Civil Engineer with appropriate hydrologic experience.

Lab Qualifications:

All samples shall be analyzed by State-certified laboratories or laboratories accepted by the SDRWQCB using approved US Environmental Protection Agency methods for the type of analysis to be performed.

Periodic Review:


The SDRWQCB will review this Order periodically and may revise it when necessary. The discharger may request revisions and upon review the Executive Officer may recommend that the SDRWQCB revise these requirements.

Notifications/Reporting requirements:

Failure to comply with the requirements of this Order may subject you to enforcement action, including but not limited to: administratively imposed civil liability up to $5,000 for each day in which the violation occurs, or referral to the Attorney General for injunctive relief or judicially imposed civil liability up to $15,000 per day, or referral to the District Attorney for criminal prosecution.

Reimbursement of Regulatory Oversight Costs:

The Dischargers are hereby notified that the SDRWQCB is entitled to and plans to seek reimbursement for all reasonable costs actually incurred by the SDRWQCB to investigate unauthorized discharges of waste and to oversee cleanup of such waste, the abatement or effects thereof, or other remedial action required by this cleanup and abatement order. Reimbursable costs may include costs incurred by the SDRWQCB since July 1, 1997. Upon receipt of a billing statement for such costs, the Dischargers shall reimburse the SDRWQCB.



JOHN H. ROBERTUS
Executive Officer

Date issued: April 2, 1998

D:\CASES\ROHR_CV\NEWCAO6.DOC

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
SAN DIEGO REGION

CLEANUP AND ABATEMENT ORDER NO. 98-08
(Revised April 2, 1998)

AEROSTRUCTURES GROUP OF BFGOODRICH AEROSPACE
(formerly ROHR, INC.) AND BFGOODRICH COMPANY
850 Lagoon Drive, Chula Vista
San Diego County, California

REQUIREMENTS AND SCHEDULE:

SUBMITTAL:	DEADLINE:
Phase One Report	June 4, 1998
Lab Report(s) from Storm Water Program	within 3 working days of the date that the Dischargers receive it
Storm Water Sampling Report	May 11, 1998
Data Evaluation Report	May 27, 1998
SWCS Investigation Report	July 13, 1998

Additional submittals will be required. Additional requirements may be established through the adoption of future amendment(s) to this Order or by other administrative means.

ENDNOTES:

[1] State Water Resources Control Board Resolution No. 92-49 as amended is entitled *"Policies and Procedures for Investigation and Cleanup and Abatement of Discharges under Waste Code Section 13304."* The amendment dates are April 1994 and October 1996. This document is attached for your reference.

All State Water Resources Policy and Procedures Documents are available 24 hours per day via the following Internet website: **www.swrcb.ca.gov**

HALEY ALDRICH


www.haleyaldrich.com

CONCEPTUAL SITE MODEL
ROHR, INC. – NORTH CAMPUS
850 LAGOON DRIVE
CHULA VISTA, CALIFORNIA
GEOTRACKER ID T10000001489

by
Haley & Aldrich, Inc.
San Diego, California

for
Rohr, Inc., a part of Collins Aerospace
Chula Vista, California

File No. 127827-016
May 2020



HALEY & ALDRICH, INC.
5333 Mission Center Road
Suite 300
San Diego, CA 92108
619.280.9210

May 19, 2020
File No. 127827-016

San Diego Regional Water Quality Control Board
2375 Northside Drive, Suite 100
San Diego, California 92108-2700

Attention: Mr. Tom Alo

Subject: Conceptual Site Model
Rohr, Inc. – North Campus
850 Lagoon Drive
Chula Vista, California
GeoTracker ID No. T10000001489

Dear Mr. Alo:

Haley & Aldrich, Inc., is submitting this Conceptual Site Conceptual Model (CSM) to the San Diego Regional Water Quality Control Board on behalf of Rohr, Inc., a part of Collins Aerospace, for the North Campus, Parcels A, B, and C, at 850 Lagoon Drive in Chula Vista, California. The CSM was prepared to meet the requirements of a new Cleanup and Abatement Order (CAO) that will supersede CAO No. 98-08. It is our understanding that the new CAO will soon be issued. This CSM was prepared in a format like the Updated CSM for the South Campus. Please contact the undersigned if you have any comments or questions regarding this CSM.

Sincerely yours,
HALEY & ALDRICH, INC.



Robert K. Scott, PG, CHg, QISP
Senior Associate Hydrogeologist

c: Rohr, Inc., a part of Collins Aerospace; Attn: Mr. Bruce Amig
Rohr, Inc., a part of Collins Aerospace; Attn: Mr. Rick Siordia
GSI Environmental Inc.; Attn: Mr. Gino Bianchi-Mosquera

HALEY & ALDRICH, INC.
5333 MISSION CENTER ROAD
SUITE 300
SAN DIEGO, CA 92108
619.280.9210

SIGNATURE PAGE FOR

CONCEPTUAL SITE MODEL
ROHR, INC. – NORTH CAMPUS
850 LAGOON DRIVE
CHULA VISTA, CALIFORNIA

PREPARED FOR
ROHR, INC., A PART OF COLLINS AEROSPACE
CHULA VISTA, CALIFORNIA

PREPARED BY:

Heidi Heggeness, GIT
Senior Staff Geologist

PREPARED BY:

Robert K. Scott, PG, CHg, QISP
Senior Associate Hydrogeologist
Haley & Aldrich, Inc.



REVIEWED AND APPROVED BY:

Mehdi Miremadi
Principal
Haley & Aldrich, Inc.

Table of Contents

		Page
List of Tables		**iii**
List of Figures		**iii**
1. Site Background		**1**
1.1	SITE SETTING	1
1.2	SITE HISTORY	1
1.2.1	Parcel A	2
1.2.2	Parcel B	2
1.2.3	Parcel C	3
1.3	SITE ASSESSMENT	4
1.3.1	Pre-1998 Assessment	4
1.3.2	Post-1998 Assessment	5
2. Site Description		**7**
2.1	SITE GEOLOGY	7
2.1.1	Fill and Bay Deposits	7
2.1.2	Bay Point Formation	7
2.1.3	Clay Aquitard	7
2.1.4	San Diego Formation	8
2.2	SITE HYDROGEOLOGY	8
2.2.1	Groundwater Monitoring Well Network	9
2.2.2	Groundwater Flow Direction and Gradients	9
2.2.3	Tidal Effects	10
2.2.4	Hydraulic Conductivity	11
3. Environmental Features		**12**
3.1	HISTORICAL OPERATIONAL FEATURES	12
3.2	HISTORICAL SURFACE WATER AND CONVEYANCE SYSTEM FEATURES	12
4. Distribution of Chemicals at the Site		**15**
4.1	EXTENT OF CHEMICALS IN VADOSE ZONE SOIL	15
4.2	EXTENT OF CHEMICALS IN SOIL GAS	16
4.3	EXTENT OF CHEMICALS IN GROUNDWATER	16
4.3.1	VOCs	16
4.3.2	1,4-Dioxane	16
4.3.3	Metals	17
4.4	VOC MIGRATION PATHWAYS	17
4.5	ABIOTIC AND BIOLOGICAL DEGRADATION	18
4.6	MASS STORAGE AND BACK DIFFUSION IN FINE GRAINED UNITS	19

Table of Contents
(continued) Page

5. Conceptual Site Model 20

6. Data Gap Assessment 21

References 22

Tables
Figures
Appendix A – AECOM Figures
Appendix B – Groundwater Protection Levels

HALEY ALDRICH

List of Tables

Table No.	Title
1	Historical Environmental Features, Parcel A
2	Historical Environmental Features, Parcel B
3	Historical Environmental Features, Parcel C

List of Figures

Figure No.	Title
1	Site Locus
2	Historical Environmental Features
3	Soil Containing COPCs above Screening Criteria
4	Conceptual Site Model
5	Exposure Pathways, Parcel A
6	Exposure Pathways, Parcel B
7	Exposure Pathways, Parcel C

1. Site Background

1.1 SITE SETTING

Haley & Aldrich, Inc., (Haley & Aldrich) prepared this Conceptual Site Model (CSM) on behalf of Rohr, Inc. a part of Collins Aerospace (Rohr) for its North Campus facility located at 850 Lagoon Drive in the City of Chula Vista, California (Site). The Site's location is shown on Figure 1; the Site's boundaries, including the property to the west of the Site known as the H-3 Parcel, are shown on Figure 2. The Site is bounded on the north by Marina Parkway (formerly F Street), on the east by Bay Boulevard, on the south by H Street and on the west by the F and G Street Marsh (part of the South San Diego National Wildlife Refuge), Marina Parkway, the H-3 Parcel, and another San Diego Unified Port District (District) Property. The Site occupies approximately 82 acres. Assessor's Parcel Numbers for the Site are shown on Figure 2. AECOM Technical Services, Inc. (AECOM) prepared a separate CSM in 2019 for the H-3 Parcel as required by the San Diego Regional Water Quality Control Board (SDRWQCB). Elements of the H-3 Parcel and South Campus CSMs are relevant to the North Campus and included herein. Figures prepared by AECOM [and URS Corporation (URS)] that support this CSM are included in Appendix A.

Rohr is in the process of decommissioning and selling portions of the facility. The Site has been divided into three parts: Parcels A, B and C. Each parcel is described as follows:

Parcel A: Parcel A includes the properties occupied by Buildings 29, 99, and 100, which are located between Bay Boulevard and the railroad right-of-way (ROW). The properties designated as Parcel A had included the vacant properties owned by Rohr south of Lagoon Drive (formerly F Street) between Bay Boulevard and the railroad ROW (vacant Bay Boulevard properties). Rohr intends to retain these parcels and they are now included in Parcel C.

Parcel B: Parcel B includes the properties occupied by the Building 1 complex, which includes Buildings 54, 55, and 22 and Building 50. Parcel B is used for manufacturing. Rohr plans to cease manufacturing on Parcel B by January 31, 2021.

Parcel C: Parcel C includes the Building 107 office complex and will be retained by Rohr. Other buildings on Parcel C from west to east include Buildings 61, 78, 79, and 118. While industrial activities will continue, there will be no manufacturing on Parcel C. An inactive railroad ROW runs approximately north-south through the Site, crosses Parcel C, and serves as the boundary between Parcels A and B.

Surface water features include a tidal inlet west of Building 61 that connects to San Diego Bay, which is west of the H-3 Parcel and Bayfront Park. Chula Vista Marina is located west of the southwest corner of the Site and H Street. An extensive storm water conveyance system (SWCS) controls storm water runoff that discharges from three locations at the Site. The SWCS and the outfalls are shown on Figure 2.

1.2 SITE HISTORY

The histories of Parcels A, B, and C are described below. The information provided is primarily derived from the following documents:

- Phase I Environmental Site Assessment (Phase I) prepared by Adrian Brown Consultants ([Adrian Brown], 1998);

- Data Compilation and Evaluation Report prepared by Woodward-Clyde Consultants (WCC, 1998b);
- Phase I prepared by URS Corporation when United Technologies Corporation acquired Goodrich Aerostructures Group (URS, 2013);
- Phase Is prepared by Haley & Aldrich for Buildings 29, 99 and 100 on Parcel A and the Vacant Properties in the 300 Block of Bay Boulevard on Parcel C (Haley & Aldrich, 2016a, 2016b).

Rohr's industrial activities on the North Campus included the manufacture and assembly of aerospace parts, primarily engine parts and covers (nacelles). These manufacturing operations included metal cutting, punching, bending, stretching, forming, anodizing, alodining, milling, etching, and painting as well as chemical handling and storage, wastewater treatment, and material recycling. Chlorinated solvents, acids, caustics, cutting oils, petroleum fuel products, and metals were historically used at the Site. As Rohr's business grew and diversified, the facility expanded onto areas reclaimed from San Diego Bay through the placement of fill. Other activities that were conducted at the facility included manufacturing and assembling light rail cars, buses, large array antennas, and missiles, among others (Bodhi, 2013). Prior to Rohr's construction of Building 1 on the North Campus in 1941, portions of the Site had other uses (Adrian Brown, 1998; WCC, 1998; URS, 2013; Haley & Aldrich, 2016a, 2016b).

1.2.1 Parcel A

Parcel A consists of two areas that have been part of the Rohr manufacturing facility. Buildings 99 and 100 are located north of G Street and Building 29 is located south of G Street. Rohr purchased Buildings 99 and 100 in 1986 and primarily used them for administrative purposes. Test laboratories were housed in Building 100.

Building 29 was constructed in phases beginning in about 1957 through 1962. The building was primarily used for tooling and machining, and office space for most of its history. At one time, the northernmost portion served as the Maintenance Department for the facility. Most recently the building housed laboratories, kitting, an After-Market Spares Warehouse, Service Center and FAI repairs, storage, tool calibration, product development, and office space. Prior to Rohr's ownership, Parcel A had a variety of other historical uses, including agriculture, trailer park, employee parking, truck engine repair, and a possible lumber yard.

Another former building (Building 28) was built on the southern portion of Parcel A in the mid-1940s and served as a cafeteria. The building was located south of Building 29 and it was demolished around 2000. The area is now occupied by a parking lot.

1.2.2 Parcel B

Parcel B has served as the core of the manufacturing facility that was first developed by Rohr when Building 1 was constructed in 1941 (Adrian Brown, 1998; WCC, 1998b; URS, 2013; Bodhi Group, 2013). Prior to Rohr's presence on the Chula Vista bayfront, Parcel B also had other uses. In the 1920s, there was a facility just south of G Street and west of the railroad ROW (R&H Tyce/Pioneer Pyrophyllite) that manufactured a cementitious material called Tycrete. The facility included a rotary kiln, laboratory, and a paint shop (URS, 2013).

In 1929, the City of Chula Vista (City) passed a bond measure for improving the tidelands, including portions of the Site, and granted the United States certain tidelands to be used as an air depot (Bodhi Group, 2013). By 1930, there was an unpaved airfield located between G and H Streets with a runway extending to J Street (Adrian Brown, 1998; URS, 2013). The Tyce brothers operated the airfield and the

Chula Vista Airport and Flying School at this location through 1940. The airport consisted of several buildings, including those of the former International Magnesite Company (IMC) north of G Street. The airfield and runway properties were leased to the Rohr Aircraft Corporation in 1940 for constructing its aircraft component manufacturing plant at the foot of H Street (Bodhi, 2013).

According to a U.S. Army Corps of Engineers "Categorical Exclusion and Ineligible Findings Form" completed in 1998, the facility operated under the sponsorship of the U.S. Navy's Bureau of Aeronautics as a Defense plant corporation facility. The plant manufactured aircraft components, including bomb bay doors, bomb racks, and engine components. The property included approximately 32 acres in fee and 4.62 acres in leases from the City of Chula Vista (City) during World War II (WWII). After WWII, two parcels (3.7 acres) were sold to other businesses. In 1951, the City parcels were surrendered by the Public Buildings Service. Of the remaining acreage owned in fee, 28.3 acres were leased by Rohr in 1947 through 1949 through the Reconstruction Finance Corporation (RFC). RFC quitclaimed the property to the U.S. Government in 1955, leased it to Rohr, and the land was then quitclaimed to Rohr in 1957. None of the land was owned or directly occupied by the U.S. Department of Defense. During WWII and in the years that followed, Rohr leased some of the current acreage from the U.S. Government, and title to the land was transferred to Rohr in 1957.

In 1960, the newly formed District dredged channels to allow for ships to access the southern portion of San Diego Bay. The dredged material was hydraulically placed to reclaim the tidelands and allow for further future development on the bayfront. Rohr's operations expanded onto these reclaimed filled areas that it leased from the District until 2002. As part of a property transfer agreement with the District and the City in 1999, Rohr obtained ownership of lands west of the high tide line and the vacant Bay Boulevard properties on the North Campus and sold its property east of the high tide line on the South Campus to the District.

When the District placed dredged fill (75-acre fill) west of the high tide line on the North Campus and part of the South Campus, a drainage channel (Western Drainage Channel) remained along the former shoreline. This channel extended from the tidal inlet west of Building 61 to 300 feet south of H Street (Rohr, 1966; Bryant, et al., 1969). This channel allowed the water to drain from the dredged fill placed hydraulically to the west. It also allowed storm water and other discharges from the SWCS to enter San Diego Bay. Rohr experienced periodic flooding at the facility given its low elevation and undersized SWCS. In 1967, the District retained a consulting engineering firm to evaluate storm water flows and design a conveyance system that would extend the bay (Bryant, et al., 1969). Pipes were installed in the Western Drainage Channel in 1969. The existing Rohr SWCS was connected to the new drainpipes so that storm water could be discharged to the bay. A 1966 report prepared by Rohr for the SDRWQCB summarized its handling of the discharge of process rinse waters to the bay via the SWCS and drainage ditches (Rohr, 1966).

1.2.3 Parcel C

Parcel C comprises multiple parcels that have had other uses dating back to before the 1920s and prior to Rohr's ownership (Figure 2). There are seven parcels that comprise the vacant Bay Boulevard properties. These properties were historically used for agricultural purposes at least as early as 1929, first for citrus and then for row crops (Haley & Aldrich, 2016b). The parcels transitioned from agricultural to commercial/industrial use sometime in the late 1940s, and crop cultivation ceased by 1953. Businesses that occupied these parcels included aircraft parts manufacturing, refrigeration unit repair, storage, junkyards, and a veterinary hospital (Haley & Aldrich, 2016b). By the mid-1980s, many of the properties were acquired by the City and business operations ceased. Rohr considered purchasing the vacant Bay Boulevard properties in the late 1980s to construct its corporate

headquarters but purchased the property west of the railroad ROW instead. Rohr has never used or conducted any operations on the vacant Bay Boulevard properties. Site investigations occurred as part of environmental due diligence starting in the late 1980s. In the 2000s, the San Diego County Department of Environmental Health (DEH) Voluntary Assistance Program provided three no further action (NFA) letters for the open cases contingent on continued commercial/industrial property use.

The parcels currently occupied by the Building 107 office complex were vacant and unused until the 1940s. In 1957, the land was being used for row crops, and by 1986 the parcels laid fallow. Rohr constructed the office complex in 1990.

The property immediately north of G Street occupied by Buildings 118, 78, and 79 was used for industrial purposes at least as early as 1918. It operated as IMC (Ducalite Corporation in 1925) and calcined the mineral magnesite that was primarily used as refractory materials in steel production. Prior to World War I (WWI), the U.S. imported magnesite from Europe. During WWI, the U.S. depended on ore deposits and processing in California to meet industrial demands. The processing of the ore at the facility is described in Walter W. Bradley, 1925. The magnesite was crushed through a gyratory crusher and then passed by conveyor belt to two sets of rolls where it was further reduced. It was then fed into an oil-burning rotary calciner and then elevated to a 40-foot-high cooling tower. The resultant product was ¾-inch diameter and 90 percent magnesium oxide. Sanborn maps from 1926 note a fuel oil tank and transformer on the property. The Sanborn map from 1926 also indicates that an aviation company was located east of IMC called Aircraft Engineering Service (a possible precursor to Tyce Engineering). It included five buildings: an office, three machine shops, and a plating shop. Aerial photographs indicate these buildings and IMC's ore shed were razed by 1944. In about 1959, Rohr acquired the Tyce Engineering's operations north of G Street.

Other businesses also operated in the 800 Block on the north side of G Street in the 1960s, including the Chula Vista Animal Shelter, construction contractors, and marine sales. To the west, where Building 61 is currently located, the City operated a sewage treatment plant north of G Street from the late 1930s until the mid-1960s. The wastewater treatment plant primarily treated Rohr's wastewater (Pomeroy & Associates, 1952). There were two settling ponds at the current location of Building 61 from about 1944 to 1959. Two settling ponds were located west of Building 61 around 1965. The treated effluent was discharged to San Diego Bay via an outfall approximately 940 feet from the shoreline at that time (Pomeroy & Associates, 1952).

1.3 SITE ASSESSMENT

A considerable number of investigations have been conducted on the Site since the late 1980s, including more than 300 borings and 55 wells both on and off Site. A Site plan showing boring location is shown on Figure 2 and a map showing well locations is provided in Appendix A. A list of references for these activities is provided in the References. The investigations are described pre- and post-CAO in the sections below.

1.3.1 Pre-1998 Assessment

Investigations prior to the SDRWQCB's issuance of the CAO in March 1998 were conducted under the DEH's oversight specific to underground storage tanks (USTs). The ensuing investigations and soil remediation activities initially focused on targeted locations that included a diesel-fuel UST, a 1,1,1–trichloroethane/trichloroethene (1,1,1–TCA/TCE) aboveground storage tank (AST) that was formerly located west of the former location of Building 57, and the Salt Bath (C-70) in Building 1 that used molten salt containing sodium dichromate to treat parts. Each of these features have been removed,

and the DEH provided a No Further Action letter for the diesel-fuel UST. Following issuance of the CAO in 1998, the DEH retained its oversight of USTs on the Site. Other investigated USTs included the N/C Machine Shop Sump, the Oiler Shed Sump, and the North Oiler Shed UST. There were also other USTs removed post-1998 that were granted NFAs by the DEH as described in Tables 1 through 3.

In addition to the pre-1998 assessment on the manufacturing portions of the North Campus described above, several investigations and soil remediation were conducted for the vacant properties in the 300 Block of Bay Boulevard and the Building 107 portion of Parcel C since the late 1980s. These are extensively described in the URS Phase I ESA (URS, 2013). The vacant properties are also described in the Haley & Aldrich Phase I ESA (Haley & Aldrich, 2016b). Rohr received the vacant properties as part of the South Campus relocation agreement in 1999. It never used the properties for any purpose. There were four cases that were active with the DEH: 798 F Street (Rados Property, two cases), 340 Bay Boulevard (Thermo King), and 350-360 Bay Boulevard. Each case received an NFA letter from the DEH stipulating that the NFA was valid if the property use remained commercial/industrial.

1.3.2 Post-1998 Assessment

The following sections describe investigations that were completed following issuance of the CAO by the SDRWQCB in March 1998. The CAO requested the following elements be completed:

- Sitewide Phase I ESA (completed by Adrian Brown);
- Compiling and evaluating data collected on the Site and adjoining properties to date (completed by Woodward-Clyde);
- Wet weather storm water sampling of the SWCS for the next storm event (completed by Woodward-Clyde);
- Dry weather sampling from the SWCS (completed by Woodward-Clyde); and
- Investigating the condition of the SWCS (completed by Woodward-Clyde).

Rohr met the CAO-specified submittal dates for documents containing the information requested above. Four submittals were prepared to comply with the CAO (Adrian Brown, 1998, Woodward-Clyde 1998a, 1998b, 1998c). Rohr also identified illicit connections, breaches, and leaks in the SWCS and either sealed or removed them over a period of a few years.

A chronology of the assessment and remediation activities conducted under the CAO includes the following:

2001: SWCS soil and groundwater investigation;

2002 and 2004: On- and off-Site cone penetrometer test (CPT) groundwater investigations;

2003 – 2005: Sediment sampling and remediation in the tidal inlet at Outfall 1;

2006: Installing on-Site well clusters targeting the three water-bearing zones identified at the Site (Zone A, Upper Zone B, and Lower Zone B) and a soil investigation of Building 61;

2007: Additional investigation on Parcel C, including the area around Building 61;

2000-2012: Oiler Shed UST investigations;

2000-2013: Investigation activities at the N/C Machine Shop Sump;

2000-2012: Investigation activities at the North Oiler Shed UST;

2013: Supplemental remedial investigation conducted during due diligence for the United Technologies Corporation purchase of Rohr (then part of Goodrich Aerospace;

2015: Data Gap Assessments, and a focused groundwater assessment of the Oiler Shed and the area along the boundary with the adjacent South Campus;

2016: Phase II ESAs for potential property sale, Eastern Parcels (vacant Bay Boulevard properties and Buildings 29, 99 and 100);

2018: Phase II ESA for potential property sale, Parcel B;

2018: Soil gas survey, Eastern Parcels (Buildings 29, 99 and 100);

2018: Indoor Air Screening, Late Summer/Early Autumn, Eastern Parcels, Building 29 (Parcel A) and Building 1, Parcel B;

2018: Additional Groundwater Investigations; Western Boundary and Oiler Shed /North of Marina areas consisting of membrane interface probe and hydraulic profiling tool (MiHpt)investigations, discrete-depth groundwater sampling, and the installation of nine new monitoring wells;

2019: Western Boundary and Oiler Shed/North of Marina reports submittals summarizing the 2018 findings;

2019: Indoor Air Screening, Late Winter/Early Spring, Eastern Parcels, Building 29 (Parcel A) and Building 1, (Parcel B);

2019 CPT/MiHpt Investigation: Additional groundwater investigations primarily consisting of off-Site MiHpt investigations and discrete-depth groundwater sampling;

2019: Data Gap Assessment, Parcel B; additional soil, soil vapor, and groundwater sampling; and

2020: Data Gap Assessment, Eastern Parcels (Parcel A, Building 29); additional soil and groundwater sampling.

Reports associated with these investigation activities are listed in the References, and many can be found on GeoTracker.

2. Site Description

2.1 SITE GEOLOGY

Detailed Site geology has been presented in several reports submitted to the SDRWQCB and is summarized below for this CSM. Referenced documents provide additional discussion, figures, and tables. The most recent geologic cross sections prepared by AECOM can be found in Appendix A. The North Campus is underlain by fill material, both undocumented and dredged material from San Diego Bay, bay mud, the Pleistocene Bay Point Formation, a clay aquitard, and the Pliocene San Diego Formation ([San Diego Formation]; Haley & Aldrich, 2015; AECOM, 2019).

2.1.1 Fill and Bay Deposits

The San Diego Bay tidelands were developed during the 1940s through the 1960s at the North Campus with undocumented fill and dredged materials. The fill generally consists of silt, clayey sand, and fine sand, but locally contains some gravel and may extend to a depth of approximately 10 feet on Site. Because of dominant fine-grained materials, the fill is considered to have a low hydraulic conductivity. The Bay Deposits consist of clay and silt interbedded with fine sand and locally extends to a depth of approximately 25 feet below ground surface (bgs) on the North Campus. The dredged fill and Bay Deposits are also considered to have low hydraulic conductivities.

2.1.2 Bay Point Formation

The Bay Point Formation underlies the Bay Deposits and extends to a depth of approximately 150 feet bgs. Marine sand and silt deposits predominate the Site subsurface from approximately 25 to 150 feet bgs west of the former shoreline. East of the former shoreline there are areas where the Bay Point Formation is present at the ground surface, particularly on the parcels along Bay Boulevard in Parcels A and C. The Bay Point Formation consists of a highly heterogeneous, interbedded mixture of silts and clays with sand and gravel layers and lenses. The clays are red to brown marine deposits. Brown clay deposits ranging in thickness from approximately 15 to 35 feet have been encountered below the fill/bay mud. Below the clay deposits, the Bay Point Formation generally consists of interbedded fine to medium sands and silty sands with thin clayey silts and clays.

Wes Danskin with the United States Geological Survey (USGS) prefers to refer to the Bay Point Formation as Quaternary alluvium. The thickness of the Quaternary sediment in the San Diego embayment can be highly variable, ranging from approximately 200 to possibly as much as 700 feet. The Bay Point Formation is Pleistocene in age and was deposited in nearshore marine and onshore fluvial depositional environments.

2.1.3 Clay Aquitard

A blue-gray estuarine clay, designated as a “clay aquitard” occurs below the sandy interval at about 125 to 150 feet bgs (Huntley, 2000). The clay aquitard varies in thickness from 20 to almost 40 feet. A blue-gray clay layer has also been encountered beneath the North Campus at a depth of approximately 125 to 150 feet bgs with a thickness of 20 to 65 feet. Although the aquitard materials encountered may differ in color at various locations throughout the North Campus and the Site, the materials are characterized as clay with a low hydraulic conductivity. Note that borings advanced during the 2015 soil and groundwater conditions assessment did not attempt to observe or sample the clay aquitard or underlying San Diego Formation.

A geothermal test boring from the 1980s located south of former Building 5 on the South Campus also recorded encountering the clay aquitard. Borings advanced on the South Campus to install wells PMW-101(LB), PMW-109(LB) and PMW-116(LB) encountered dark gray sandy clay and fine sand at similar depths. The clay aquitard has a low hydraulic conductivity and plays a significant role in isolating the Bay Point Formation from the San Diego Formation.

2.1.4 San Diego Formation

There is a 20-foot-plus thick interval of coarse sands, gravels, and cobbles beneath the clay aquitard that is attributed to the San Diego Formation (Huntley, 2000). These strata were investigated during a drilling and aquifer testing program that Rohr conducted in 1998 and 1999 on behalf of the Sweetwater Authority to characterize the hydrogeology beneath the North Campus (URS Greiner Woodward-Clyde [URSGWC], 1999). These coarser-grained sediments were referred to as the Upper Gravel Unit in the URSGWC study and, based on geophysical logs and borehole flowmeter logging, Huntley suggested that the Upper Gravel Unit is the most productive zone investigated during this study (Huntley, 2000). The Upper Gravel Unit is underlain by a series of discontinuous lenses of fine to medium sands, silty sands, clayey sands, and silts and clays to a depth of at least 400 feet bgs (Huntley, 2000).

The San Diego Formation consists of two portions: the upper and lower members. The upper member of the San Diego Formation is present on the land surface in the vicinity of downtown San Diego and Chollas Creek but does not seem to be present or exposed in the South Bay, where the Site is located. The upper member was deposited in a higher energy environment, closer to the continent; the lower member was deposited in a lower energy environment, typical of a deeper marine environment. The thickest section of the San Diego Formation is located adjacent to the southeastern edge of San Diego Bay, south of the Site.

The age of the San Diego Formation is less well defined but considered to be of the Plio-Pleistocene age. Like the Quaternary sediment, the San Diego Formation was deposited in nearshore marine and onshore fluvial depositional environments. The contact with the overlying Quaternary alluvium is erosional and very difficult to distinguish in the subsurface and in geophysical logs. The term “San Diego Formation” has historically been used quite liberally, and in some instances, probably inaccurately. For example, marine mollusks present in the clay aquitard during URSGWC’s study were found to be Pleistocene age, and part of the Quaternary sediments (Bay Point Formation).

Recent work by the USGS indicates that San Diego Formation groundwater near the Sweetwater and Otay Rivers is isotopically enriched, reflecting the process of seawater intrusion (Anders et al, 2013). Furthermore, chloride concentrations decline within the saline section of the San Diego Formation at depths of about 500 to 820 feet bgs, indicating that the greatest quantity of regional groundwater recharge (originating in higher elevations to the east), may flow through the coastal aquifer at these depths.

2.2 SITE HYDROGEOLOGY

Two distinct water-bearing zones above the clay aquitard have been characterized at the Site and are shown on the geologic cross sections prepared by AECOM for the North Campus in Appendix A (AECOM, 2019a).

- Zone A groundwater: This zone corresponds to the “artificial fill/bay mud/dredged material water-bearing zone” and extends to approximately 25 feet bgs over most of the Site. Zone A consists of silt and clay with discontinuous sand lenses.

- Zone B groundwater: This zone corresponds to the "Bay Point Formation" and extends from below Zone A (25 feet) to approximately 125 feet bgs. Zone B is a highly heterogeneous, interbedded mixture of silts and clays with sand and gravel layers and lenses. Zone B groundwater is further divided into:
  - Upper Zone B groundwater (between Zone A and 55 to 70 feet bgs); and
  - Lower Zone B groundwater (below 55 and 70 feet to the top of the clay aquitard).

2.2.1 Groundwater Monitoring Well Network

The North Campus monitoring network consists of 55 monitoring wells, 30 of which are collocated clusters of three wells, and four of which are collocated clusters of two wells. Well construction details and historical groundwater level measurements can be found in, "Report of Annual Groundwater Monitoring and Sampling - 2019" prepared by AECOM (AECOM, 2019b). A table summarizing the well construction details and a well location map from that report are provided in Appendix A. The monitoring well network comprises the following:

Salt Bath Area Wells: MW1-1 through MW1-7 were installed near the former C-70 Salt Bath to monitor total and hexavalent chromium concentrations in groundwater. The wells are screened in first encountered groundwater and are shallower than Zone A wells at the Site.

Building 57 Area Wells: MW57-1, -2, -3, -5, -6, and -7 were installed to monitor total petroleum hydrocarbons (TPH) and volatile organic compound (VOC) concentrations in groundwater in the vicinity of a diesel-fuel UST and a 1,1,1–TCA/TCE AST that had been located west of former Building 57 (Figure 2). Like the Salt Bath Area wells, the Building 57 Area wells are screened in first encountered groundwater and are shallower than Zone A wells at the Site.

Site-Wide Cluster Wells: Cluster wells NCW-001 though NCW-009 and NCW-013 each consist of three wells with screens completed in Zone A, Upper Zone B, or Lower Zone B. The wells were installed to monitor VOC concentrations and groundwater flow conditions Site-wide. Cluster wells NCW-006 thought -009 are on the H-3 Parcel to the west of the Site.

Building 61 Area Wells: Zone A wells NCW-010, NCW-011, and NCW-012 were installed near Building 61 to monitor VOCs observed during previous investigations in this area.

Oiler Shed/North of Marina Monitoring Wells: NCW-014 and NCW-015 cluster wells consist of two wells with screens completed in Zone A and Upper Zone B; monitoring wells NCW-016 through NCW-020 are single monitoring wells completed in Zone A or Upper Zone B. The wells were installed in 2018 as part of the Oiler Shed and North of Marina investigation to monitor VOC concentrations and groundwater flow conditions in the area between the Oiler Shed and the Chula Vista Marina. Some of the wells are located to the west of the Site.

2.2.2 Groundwater Flow Direction and Gradients

Flow directions and gradients on the North Campus and the H-3 Parcel in the three water-bearing zones have been evaluated by AECOM (2019) and by Haley & Aldrich for the South Campus (Haley & Aldrich 2019b) during annual monitoring and sampling events and have a general vector direction to the west. Groundwater gradients are estimated using equivalent fresh water heads corrected for salinity based on sodium and chloride data collected for each of the groundwater zones. Groundwater flow conditions in each of the three zones are tidally influenced.

The groundwater beneath the Site has variable density as a function of salinity both laterally away from the shore of the San Diego Bay and with depth that result in density-dependent flow conditions. This is represented by the "salt water wedge," where fresh groundwater discharge to the ocean leads to upwelling of the denser underlying salt water, and circulating patterns set up by mixing freshwater and salt water in a transition zone cause the salt water to extend landward in a wedge shape. Mixing in the transition zone occurs through dispersion and diffusion.

Groundwater elevation contour maps that consider fresh water head calculations for Zone A, Upper Zone B and Lower Zone B are provided in Appendix A (Figures 3, 4 and 5 of AECOM's "Report of Annual Groundwater Monitoring and Sampling – 2019." AECOM concluded that horizontal groundwater flow directions are generally toward the west in Zone A and Upper Zone B and then to the northeast (landward) in Lower Zone B along the western perimeter of the H-3 Parcel (AECOM, 2019a). The hydraulic gradient was approximately 0.001 foot per foot (ft/ft) in Zone A, 0.003 ft/ft in Upper Zone B, and essentially flat in Lower Zone B. The groundwater flow direction in Upper Zone B in the area north of the Marinas was south toward the Marinas. AECOM also concluded that the vertical hydraulic gradients vary but are generally upward in wells closest to the Bay and downward in wells furthest from the Bay on the North Campus.

Haley & Aldrich has estimated similar gradients using "Using Hydraulic Head Measurements in Variable-Density Ground Water Flow Analyses" (Post et al., 2007) for each of the water-bearing zones on the South Campus:

- 0.002 to 0.005 ft/ft in Zone A;
- 0.0005 to 0.0007 ft/ft in Upper Zone B; and
- 0.002 ft/ft to 0.0007 ft/ft in Lower Zone B.

Haley & Aldrich has also estimated vertical gradients for the South Campus using equivalent fresh water heads. They found that vertical gradients between Zone A and Upper Zone B are variable with areas of downward gradient landward and neutral or upward gradient evident near the Marinas. The vertical gradient between Upper Zone B and Lower Zone B is typically upward which is consistent with this hydrogeologic setting, where groundwater is discharging to the ocean/bay.

2.2.3 Tidal Effects

Studies to assess the tidal influence on the Zone A and Upper Zone B groundwater gradients have been conducted by both AECOM and Haley & Aldrich for the North Campus, H-3 Parcel, and the South Campus. AECOM found that the average tidally induced groundwater level fluctuation was approximately 4.6 feet in well NCW-019 near the Marinas to 1.4 feet in well NCW-015B, which was 1,000 feet landward during its study during a neap tide in December 2018. The findings showed that although gradient reversals do occur during tidal cycles, the average groundwater flow directions shift from westerly at the North Campus to southerly (seaward) near the Marinas. In the area of the wells closest to the Marinas, groundwater flow directions at the lowest tidal stage were to the south (seaward) with gradients of approximately 0.002 to 0.005; at the highest tidal stage, the groundwater flow direction in this area was to the east (landward), with gradients of approximately 0.001 to 0.002. On average over five tidal cycles, flow directions were seaward, with gradients of approximately 0.001 to 0.003. AECOM conducted a second tidal study in August 2019, and the results have not yet been reported.

The results of the study conducted by Haley & Aldrich on the South Campus showed that groundwater elevations are tidally influenced in Zone A (up to 0.8 foot of elevation change between low and high tides) and Upper Zone B (up to 2 feet of elevation change between low and high tides) within 150 feet of the Marinas' shoreline. Similar conditions were observed during a tidal influence study in October 2000, where it was found that tidal effects diminished with distance to the east and were minimal near the former shoreline. Gradient reversal (to the east) was not observed along the Zone A well transect; however, gradient reversal (to the east) was observed in Upper Zone B during high tide between wells PMW-122(UB) and PMW-112(UB), located within 250 feet of the Marinas.

2.2.4 Hydraulic Conductivity

AECOM has estimated hydraulic conductivity in Zone A and Upper Zone B by conducting pneumatic slug tests in 13 wells on Parcel H-3, the North Campus, and the area north of the Marinas (AECOM, 2019a). The monitoring wells tested were screened in 10-foot intervals, typically in coarser grained or interbedded zones. The estimated hydraulic conductivities for the two wells screened in Zone A were 15 feet per day (ft/day) and 50 ft/day. The estimated hydraulic conductivities for the wells screened in Upper Zone B ranged from approximately 7 to 57 ft/day, with an average of approximately 22 ft/day.

Haley & Aldrich estimated horizontal hydraulic conductivity in both the coarser- and finer-grained strata in each of the water-bearing units beneath the South Campus. The estimates were calculated empirically based on grain size distribution analysis (Vukovic and Soro 1992) and by assessing tidal efficiency by comparing groundwater-level hydrographs with tidal fluctuations in San Diego Bay for Upper Zone B only. This zone demonstrates enough tidal influence to give a reasonable estimate (Erskine, 1999). Haley & Aldrich's hydraulic conductivity estimates appear in Table 1 in the South Campus Updated CSM (Haley & Aldrich, 2019a). The estimates reported by AECOM for Zone A and Upper Zone B fall within the ranges reported by Haley & Aldrich for the coarser-grained zones on the South Campus.

Haley & Aldrich also concluded that the maximum and minimum hydraulic conductivity (K) values in the granular zones are roughly three to six orders of magnitude higher than the respective values in the fine-grained zones (Haley & Aldrich, 2019a). The tidal efficiency-based estimate was comparable to the high range of gradation-based estimates in the granular zone for Upper Zone B. This is intuitive because soils that are granular, with moderate- to high-K_h, are more likely to respond to tidal fluctuations than fine-grained, low-K_h soils. The maximum and minimum vertical hydraulic conductivity (K_v) estimates (derived from laboratory permeability testing) are roughly 1 to 4 orders of magnitude lower than the corresponding ranges of K_h.

These observations support the fate and transport element of the CSM, which concludes that the complex interbedded stratigraphy of the Site is conducive to horizontal advective transport preferentially through granular strata that are bounded vertically and, in some places, horizontally, by fine-grained, low-K_h strata.

3. Environmental Features

Historical environmental features at the Site are described in Tables 1, 2, and 3 for Parcels A, B and C, respectively. Each table first describes Rohr operational features, followed by pre-Rohr operational features for each parcel. These are followed by historical surface water features such as drainage channels, historical outfalls, and the former shoreline. The information has been compiled from numerous historical sources and the results of Site assessment activities at the Site. References are also noted and listed on the last page of each table.

Soil remediation activities have been conducted on the Site under the CAO and are shown on Figure 2. Remedial excavations have been conducted in the following areas:

- C-70 Salt Bath in Building 1;
- Former diesel-fuel UST west of Building 57;
- Chemical Process Lines (D-, E/F- and R-Lines) in Building 1;
- Northeast corner of the Wastewater Treatment Plant;
- Vat excavation in the parking lot east of Building 1; and
- H Street PCB excavation (adjacent to North Campus in area of H Street Extension).

Sediment in the Outfall 1 tidal inlet west of Building 61 was also remediated. This remedial action received an NFA letter from the SDRWQCB.

3.1 HISTORICAL OPERATIONAL FEATURES

Figure 2 shows former operational features, including buildings, ASTs, USTs, chemical process lines, underground vessels, vaults, paint booths, degreasers, hydraulic equipment, and maintenance and storage areas. Many of the features have been removed, decommissioned, or abandoned in place. Those that remain on Parcels A and B are in the process of being decommissioned. Rohr Tank IDs are noted in Tables 1, 2, 3 and on Figure 2, where appropriate. The numbering of these features on Figure 2 correspond to the tables. The numbering of the features in the tables and on the figure is consistent with the Adrian Brown Phase I ESA (Adrian Brown, 1998) and the URS Phase I ESA (URS, 2013).

3.2 HISTORICAL SURFACE WATER AND CONVEYANCE SYSTEM FEATURES

Both the Adrian Brown Phase I and the SECOR Phase II identified the locations of the former shorelines based on available historical aerial photographs and drawings. As time passed, the shoreline was filled with undocumented and dredged material from San Diego Bay at least as early as 1944 through 1962 west of the North Campus. The Rohr facility expanded onto these reclaimed lands on the North and South Campuses in phases. These activities are evident on historical aerial photographs and other available historical drawings (State Lands Commission, 1953; SECOR, 1999; Adrian Brown, 1998; Rohr, 1966; and Bryant, et al., 1969, URS, 2013, Bohdi Group, 2013).

To comply with the CAO, Rick Engineering conducted an engineering survey of the SWCS in 1998, which is the basis of the SWCS locations shown on Figure 2 (Rick Engineering, 1998). As filling occurred on the tidelands, the SWCS was extended to convey flows to San Diego Bay. Often, the new pipes that extended to the bay were placed in the existing channels. The points where the former SWCS crossed

the historical shorelines represent the locations of the historical outfalls. Based on Adrian Brown 1998, there were seven outfalls along the former North Campus shoreline (labeled A through G on Figure 3).

Information regarding historical practices for the disposal of wastes at the facility are described in a URS Phase I ESA (URS, 2013). It states that in 1993, Bechtel Environmental, Inc., (Bechtel) was contracted by U.S. Environmental Protection Agency (EPA) Region 9 to conduct a Site inspection under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act and the Superfund Amendments and Reauthorization Act of 1986 (Bechtel, 1993). From 1941 through the 1960s, Rohr discharged industrial wastes to storm drains and earthen-lined ditches that flowed to the bay that included metal-treating rinse solutions, oils, paints, and solvents. A 1952 SDRWQCB report titled, "Extent, Effects and Limitations of Waste Disposal into San Diego Bay" described Rohr as discharging wastes directly into San Diego Bay. Sewage and other wastes from the facility were treated by the City's waste treatment plant until 1963 (SDRWQCB, 1998a).

Other documents also describe Rohr's waste disposal practices at that time (Pomeroy & Associates, 1952, Rohr 1966, SDRWQCB 1966). The Pomeroy reports describe that Rohr was considering designing and constructing a seepage pit at a location close to the northwest portion of Building 1 to be used to infiltrate process rinse waters and eliminate discharges via the SWCS. Site investigations have not identified the location of a seepage pit, and it is unclear based on available information and drawings whether it was constructed and operated (URS, 2013).

The Rohr report from 1966 indicates that spent rinse waters were discharged to the SWCS that conveyed them to San Diego Bay. It also states that a wastewater recovery system was being installed by Rohr at this time and spent solvents acids, plating and cleaning solutions were being hauled off Site for disposal. Rohr indicated the it wished to cooperate with the requirements of the SDRWQCB in whatever manner was necessary. Discharges to the SWCS in the 1980s and early 1990s resulted in several violations and issuance of the CAO by the SDRWQCB in 1998 (SDRWQCB, 1998b).

There were seven historical outfalls where SWCS lines that discharged to the former high tide line on the North Campus (Historical Outfalls A through G). In approximately 1960, dredged fill was placed along the shoreline to the bay, west of the Rohr facility from G Street to approximately 300 feet south of H Street (known as the "75-acre fill"). It was filled using sediment that had been dredged from San Diego Bay to deepen channels to improve accessibility to south San Diego Bay. A drainage channel (Western Drainage Ditch) extended along the historical shoreline for approximately 1,350 feet. The SWCS lines that discharged to the former high tide line were extended to the Western Drainage Ditch. The portion of the Western Drainage Ditch north of Building 50 flowed north to the Outfall 1 tidal inlet, and the portion to the south of Building 50 flowed south and entered San Diego Bay (Rohr 1966; Bryant, et. al, 1969, Rohr, 1970). The drainage ditch allowed water to drain from the dredged fill following its placement. This drainage channel had approximate 2:1 slopes and was approximately 50 feet wide. It extended to a depth of approximately 5 to 6 feet bgs.

In July 1967, Jefferies and Phillips conducted an engineering study for the District that discusses installing new storm water conveyance pipes to abate the issues of flooding on the western side of the facility (Jefferies and Phillips, 1967). The report states that the existing channel was detrimental to Site development and the land's fullest and best use. Design drawings from 1969 show that the new SWCS pipes would be placed in the drainage ditch and the existing Rohr outfalls to the Western Drainage Ditch would be connected to the new pipes to convey flow to the bay via Outfall 1 and the tidal inlet and Outfall 2 in the Marinas.

The drawings indicate that the bottom of the channel was excavated to install the storm drain lines. The pipe was placed on 12 to 36 inches of rock bedding depending on the diameter of the pipe. The storm drainpipes were installed in the drainage channel on the North Campus only. At H Street, the pipes turned west and then south along Marina Parkway, where they joined the main drain line that discharges to Outfall 2 at the northeast corner of the Marinas (Figure 3). The portion of the Western Drainage Ditch south of H Street was filled in 1968.

Following the sale of the South Campus to the District, Rohr moved certain operations on the South Campus to the North Campus and other Rohr facilities. This included relocating the chemical process lines in Building 45 to the northwest portion of Building 1 and constructing a new wastewater treatment plant west of Building 1 and south of Building 50. In addition, Rohr realigned its SWCS on the North Campus. These activities were conducted prior to Rohr vacating the South Campus (December 31, 2002).

Rohr's SWCS improvements included replacing and installing approximately 2,100 feet of new pipe above the existing lines so that as much of it as possible could be above groundwater level. The existing lines were abandoned by filling them with concrete slurry. Pipe that could not be replaced and remained below the water table was rehabilitated installing a thermoplastic, seamless liner. The current SWCS is also depicted on Figure 2.

In 2004, 530 tons of sediment was removed from the tidal inlet down stream of Outfall No. 1 (URS, 2005a). The remedial action was conducted to remove sediment containing certain metals, polycyclic aromatic hydrocarbons, and polychlorinated biphenyls (PCBs) to concentrations below the Effects Range Low values. The SDRWQCB provided an NFA letter for this remedial action.

4. Distribution of Chemicals at the Site

4.1 EXTENT OF CHEMICALS IN VADOSE ZONE SOIL

The Site soil data have been compared to Groundwater Protection Levels (GPLs) developed for the South Campus (Haley & Aldrich, 2014a, 2014b). These criteria are relevant for the North Campus since the operations were the same as the South Campus (they were the same facility) and the hydrogeology is very similar. This justification will be described in the Soil Feasibility Studies and the Remedial Action Plans (Soil RAPs) being prepared for the North Campus and provided under separate cover. GPLs for vadose zone soil are summarized in Table 10 of the Soil RAP for the northern portion of the South Campus. A copy of this table is provided in Appendix B (Haley & Aldrich, 2018d).

Investigation has identified certain VOCs (primarily TCE), metals, and TPH in soil in specific areas that are above the GPLs as shown on Figure 3 and in the table below. The GPL for total PCBs is 130 milligrams per kilogram. The PCB concentrations in soil have been compared to the commercial/industrial California Department Toxic Substances Control-Screening Levels (DTSC-SLs). Those PCB mixtures that have been detected in soil above their respective DTSC-SLs are also noted on Figure 3 and in the table below. Those chemicals of potential concern (COPCs) that have been found in soil above GPLs include the following:

VOCs	PCBs*	Metals
1,1,1-trichloroethane	Aroclor 1248	Antimony
1,1-dichloroethane (1,1-DCA)	Aroclor 1254	Chromium
1,2- dichloroethane	Aroclor 1260	Hexavalent chromium
1,1-dichloroethene (1,1-DCE)		Lead
cis-1,2-dichloroethene (cis-1,2-DCE)		
trans-1,2-dichloroethene		
TCE		
vinyl chloride		
benzene		
toluene		

* Above commercial/industrial DTSC-SLs; see explanation in text.

Human Health Risk Assessments (HHRAs) for Parcels A and B are in progress. Health-based remediation goals will be developed for the Site and this section of the CSM will be updated based on the results of the HHRAs.

4.2 EXTENT OF CHEMICALS IN SOIL GAS

Two soil vapor surveys were conducted on Parcels A and B in 2018 and 2019, respectively (Haley & Aldrich 2018e; Haley & Aldrich 2020). The soil vapor survey on Parcel B was limited to those areas of known VOC sources. VOC concentrations in soil gas are the result of volatilization from soil and groundwater. The VOCs that are named as risk drivers in the CAO for soil vapor on the South Campus include 1,1-DCA, 1,1-DCE, bromodichloromethane, cis-1,2-DCE, PCE, TCE and vinyl chloride. The general distribution of higher chemical concentrations in soil vapor on Parcels A and B is coincident with observed concentrations in soil and groundwater. TCE, PCE, 1,1,1-TCA and their daughter products are the most prevalent chemicals detected in soil vapor on Parcels A and B. Higher chemical concentrations of VOCs in soil vapor on Parcel A were observed in the northern third of the building that was formerly occupied by the Maintenance Department (Haley & Aldrich, 2018e). Each of the source areas investigated on Parcel B appeared to show elevated concentrations of VOCs in soil vapor (Haley & Aldrich, 2020).

4.3 EXTENT OF CHEMICALS IN GROUNDWATER

4.3.1 VOCs

The general distribution of observed chemical concentrations in groundwater beneath the Site have been presented in URS' "Supplemental Remedial Investigation Report" (URS, 2015) and AECOM's "Conceptual Site Model Report for Parcel H-3 and Off-Site Areas" (AECOM, 2019a). Of the VOCs, TCE has been detected most frequently and at the highest concentrations in groundwater at the North Campus, at Parcel H-3, and downgradient areas. The other VOCs occur with TCE and have similar distributions; therefore, the distribution of TCE in groundwater is representative of groundwater impacts beneath the North Campus and the H-3 Parcel. Composite TCE contours prepared by URS (currently AECOM) in 2015 and AECOM in 2019 are provided in Appendix A. The contours are coincident with former historical environmental features associated with long-term chemical usage and storage, waste collection, and discharges; former degreasers, equipment vaults, the 1,1,1-TCA/TCE AST, USTs, other vessels, storm drain outfalls and the former historical shoreline. The VOCs that are named as risk drivers in the CAO for South Campus groundwater are 1,1-DCE, carbon tetrachloride, chloroform, cis-1,2-DCE, hexavalent chromium, PCE, TCE, and vinyl chloride. Because similar operations occurred historically on the North Campus, the risk drivers for the North Campus are assumed to be the same.

The chemical distribution in groundwater was evaluated across the Site and in adjacent areas off Site. The ongoing monitoring of 55 Site monitoring wells screened in Zone A and Upper and Lower Zone B groundwater have demonstrated a relatively consistent plume configuration beneath the Site for the past 15 years. Similar conditions have existed on the South Campus. Monitoring data through 2019 was used by AECOM to prepare the composite isoconcentration contour map for TCE that appears in the H-3 Parcel CSM (provided in Appendix A).

4.3.2 1,4-Dioxane

Figures 14 through 16 from AECOM's CSM for the H-3 Parcel that show isoconcentration contours for 1,4-dioxane in Zone A, Upper Zone B and Lower Zone B are also included in Appendix A. These data were collected during an additional groundwater investigation conducted by AECOM in 2019. The cross sections from the AECOM CSM (Figures 6 through 10) also show select groundwater analytical results for TCE and 1,4-dioxane and are included in Appendix A. 1,4-dioxane concentrations in groundwater in Zone A on Site have been detected up to 3,500 micrograms per liter (µg/L) and found to exceed the California Division of Drinking Water drinking water notification level (NL) of 1 µg/L and the associated Response

Level of 35 µg/L. The contours suggest that the sources of 1,4-dioxane in Zone A groundwater may include the vicinity of the former 1,1,1-TCA/TCE AST near former Building 57 (boring HP-57, 3.500 µg/L), the Stretch Forming Area (HP-58; 2,900 µg/L), the V2 Degreaser (HP-23; 660 µg/L), and west of the Oiler Shed (NCW-014A, 1,700 µg/L). These locations are coincident with TCE sources. Detectable 1,4-dioxane concentrations on the H-3 Parcel in Zone A are not detected or present at low concentrations (e.g., less than the NL) at most locations. The 1,4-dioxane isoconcentration contours show that this compound has migrated downward into Upper Zone B and migrated beneath the H-3 Parcel from the on-Site sources that have been identified in Zone A. Lower Zone B shows minimal detections in groundwater above the NL, both on Site and on the H-3 Parcel.

4.3.3 Metals

Site assessment activities have included groundwater samples collected from Zone A using in-situ sampling techniques. While the samples have been analyzed for dissolved metals following filtering and preserving the samples prior to analysis, it is possible that some metals concentrations that are above their respective Maximum Contaminant Levels (MCLs) in drinking water or South Campus background may be overestimated.

Haley & Aldrich conducted a background metals study for groundwater, and the groundwater cleanup levels appear in the CAO for the South Campus (SDRWQCB, 2015). The SDRWQCB has concurred that the background metals concentrations are relevant for the H-3 Parcel. These background values should also be relevant to the North Campus based on the similarities in hydrogeologic conditions—both the North and South Campus are within the same watershed.

The metals that have exceeded an MCL in one or more Zone A groundwater sample have included hexavalent chromium, chromium, arsenic, lead, thallium, cadmium, antimony, cobalt, molybdenum, barium, copper, and nickel. However, metals are typically insoluble at the pH values observed in Site groundwater and some MCL exceedances may be due to the presence of fines in water samples. Groundwater sample analyses from monitoring wells have been performed for VOCs, TPH, 1,4-dioxane and natural attenuation parameters. While it is possible that some of these exceedances may be associated with historical operations, it is recommended that groundwater samples be collected from the existing Zone A monitoring wells and analyzed for Title 22 metals to confirm the presence of metals above background.

4.4 VOC MIGRATION PATHWAYS

VOCs in vadose zone soil are generally localized because of the low hydraulic conductivity of the predominantly fine-grained materials. However, utility conduits and the surrounding engineered backfill with higher hydraulic conductivity may serve as localized preferential migration pathways for shallow groundwater influencing the flow pattern. These utility conduits that may be below the level of groundwater include former and current storm drains, sanitary sewer lines, and utility corridors.

The chlorinated VOCs releases from historical environmental features at the North Campus, including the 1,1,1-TCA/TCE AST, the V-1, V-2 and V-3 Degreasers, Oiler Shed and other historical environmental features, have migrated with groundwater flow to the west onto Parcel H-3 and other off-Site areas. In general, the artificial fill, bay mud, and shallow Bay Point Formation are fine-grained with relatively low hydraulic conductivity and consequently, limited lateral dissolved-phase migration has occurred in these shallow materials at the North Campus (AECOM, 2016). However, where releases have migrated vertically into underlying more conductive, laterally continuous (sand) zones, lateral VOC migration in

groundwater has occurred to the extent that VOCs have migrated westward from the North Campus to the H-3 Parcel.

Laterally-continuous, coarse-grained sequences are present at elevations of approximately -15 feet mean sea level datum (msl) in Zone A, -40 feet msl in Upper Zone B, and -70 feet msl in Lower Zone B at the North Campus and extend off-Site beneath Parcel H-3. Off-Site VOC migration occurs in each of these units with the highest concentrations present in Zone A at the former location of environmental features. However, the extent to which VOCs are present in Zone A on the H-3 Parcel is limited. It may suggest that the releases predated the placement of the 75-acre dredged fill. The highest VOC concentrations off-Site occur in groundwater in Upper Zone B.

Vertical groundwater gradients may drive VOC migration between these coarser zones, especially where intervening finer-grained units are thin or absent. Vertical gradients are variable in the CSM area but generally shift from downward at well clusters located on the North Campus to upward at clusters located near the bay. Sea water intrudes below less saline water near the bay, driving upward vertical gradients into the overlying freshwater zones. This process may also force the upward migration of the VOC plumes as they approach San Diego Bay. The influence of tidal fluctuations, which causes lateral reversals in flow direction near the shoreline, enhances mixing and dispersion of the VOC plume in these areas. This enhanced mixing/dispersion will cause attenuation of the plume concentrations, particularly in the nearshore areas.

Interactions between vadose zone soil and Zone A groundwater, subject to tidal influence, may allow chemicals present within the capillary fringe to be introduced to shallow groundwater. On the South Campus, the estimated K_h values for the underlying Zone A groundwater, range from 1.8×10^{-5} to 0.84 foot per day for fine-grained zones and from 8.5 to 200 ft/day for granular zones, resulting in the observed distribution of chemicals in groundwater, where preferential flow occurs in coarser zones, where present. COPCs have also diffused into silt and clay soils in Zone A groundwater, and very slow back-diffusion of this mass is occurring and will continue to occur over decades to a century. However, the general distribution of chemicals in groundwater on both the North and South Campus has remained similar and stable over the past 15 years of assessment and monitoring. These stable historical concentrations, combined with hydrogeological data, are due to the significant natural attenuation already occurring in groundwater. For additional discussion of chemical migration in groundwater and the ongoing process of natural attenuation at the Site refer to the South Campus Groundwater RAP (Haley & Aldrich, 2015).

4.5 ABIOTIC AND BIOLOGICAL DEGRADATION

Biological degradation and other natural attenuation processes such as mixing and dispersion can result in mass removal and stability of VOC plumes. Biological degradation byproducts of TCE via reductive dichlorination processes include cis-1,2-DCE and vinyl chloride. Several wells have trends of increasing cis-1,2-DCE and vinyl chloride and decreasing TCE concentrations (AECOM, 2019a). These trends and the widespread presence of vinyl chloride commingled with cis-1,2-DCE provide supporting evidence of ongoing TCE mass removal through reductive dichlorination. 1,1-DCE detections, a byproduct of abiotic degradation of 1,1,1-TCA, are also widespread. Based on the presence of these degradation products, reductive dichlorination and/or abiotic degradation are important mass removal mechanisms for chlorinated ethenes and ethane in groundwater beneath the North Campus, Parcel H-3, and the off-Site areas. 1,4-dioxane does not readily degrade by biological or abiotic mechanisms, so natural attenuation will be primarily limited to mixing and dispersion.

4.6 MASS STORAGE AND BACK DIFFUSION IN FINE GRAINED UNITS

The processes of forward- and back-diffusion of VOCs into and then out of fine-grained soils have been shown to sustain VOC concentrations in aquifers at levels well above cleanup criteria for long periods of time at Sites where fine-grained clay or silt is present (Chapman and Parker, 2005; Parker et al., 2008; Kavanaugh et al., 2013; Carey et al., 2014; Carey et al., 2015). Site-specific evaluations of back-diffusion and mass storage have been prepared for release areas at the North and South Campuses (AECOM, 2019a; Haley and Aldrich, 2015). While these investigations have focused on source areas, the same process occur within plumes. On the North Campus, specifically Parcel B, dissolved-phase TCE concentrations exceed 100,000 µg/L in the fine-grained strata and greater than 10,000 µg/L in coarse-grained sequences where plumes are migrating. The coarser-grained sequences include interbedded fine-grained intervals that are underlain and overlain by relatively thick fine-grained zones. During plume migration at these concentrations, VOC concentration gradients between the impacted sand units drive forward VOC diffusion into the fine-grained layers, effectively storing VOC mass in these layers. As concentrations in the sand units decline because of natural attenuation processes or active remediation efforts, slow back diffusion from the VOC mass stored in these fine-grained layers can generate sustained VOC concentrations that can prolong remediation time frames on the order of decades to centuries.

5. Conceptual Site Model

As previously noted, historical chemical sources are coincident with former Site areas associated with long-term chemical usage, storage, and waste collection and discharge. A summary of historical environmental features and status of their investigation and remediation are provided in Tables 1, 2, and 3 for Parcels A, B and C, respectively. The CSM for the North Campus (Parcels, A, B and C) is provided on Figure 4. Figures 5, 6 and 7 show the Site human health exposure pathways and depicts historical chemical sources, primary release mechanisms, primary impacted media, transport mechanisms, secondary impacted media, exposure routes, and potentially exposed receptors for Parcels A, B and C, respectively. Exposure pathways considered to be likely significant will be quantified in the HHRAs. Those pathways considered to be insignificant will not be quantified.

6. Data Gap Assessment

Soil and groundwater conditions have been extensively characterized on the North Campus. The following observations and information collected from the past Site investigation and remediation activities on the North and South Campuses have revealed the following:

- VOCs in soil are typically localized around former tanks and vaults. This is what Haley & Aldrich had observed for these features on the South Campus.
- The occurrence of metals above DTSC-SLs for commercial/industrial property use or GPLs developed for the adjacent South Campus are typically found at former surface water features (former outfalls, shoreline, and along the former drainage features).
- PCBs are found mostly along the historical shoreline and outfalls. None were detected in the Machine Shop and Oiler Shed where petroleum hydrocarbons have been identified.
- Shallow groundwater is the primary vapor intrusion source. VOCs in soil in source areas also contribute to vapor intrusion.

In our opinion, the vadose zone soil at the Site has been adequately characterized. Further evaluation of soil can be accomplished when implementing the Soil RAPs on Parcels A and B and a Demolition and Environmental Monitoring Plan on Parcel B once the building foundations and pavement have been removed.

Groundwater has also been adequately characterized with multiple sampling events of 55 monitoring wells. While shallow groundwater has been sampled extensively using in-situ sampling devices, the results may overestimate metals concentrations in Zone A groundwater on the North Campus. Groundwater metals analyses are recommended for the existing Zone A wells on the North Campus to evaluate whether the in-situ groundwater results are representative of groundwater quality.

References

1. Adrian Brown Consultants, 1998. ASTM Phase I Site Assessment, B.F. Goodrich Aerospace, 850 Lagoon Drive, Chula Vista, California. June 4.

2. AECOM. 2016. Report Data Gap Assessment Rohr, Inc. – North Campus, 850 Lagoon Drive, Chula Vista, California. February 10.

3. AECOM, 2019a. Conceptual Site Model Report Parcel H-3 and Offsite Areas, North Campus, Rohr Inc. September 30.

4. AECOM, 2019b. Report of Annual Groundwater Monitoring and Sampling, Rohr, Inc. - A Collins Aerospace Company – North Campus, 850 Lagoon Drive, Chula Vista, California. November 21.

5. Anders, R., Mendez, G.O., Futa, K. and Danskin, W.R., 2013. A Geochemical Approach to Determine Sources and Movement of Saline Groundwater in a Coastal Aquifer. Ground Water. doi: 10.1111/gwat.12108, 13 p. Available at http://ca.water.usgs.gov/projects/sandiego/pdfs/AndersEtAl2013.pdf

6. Bechtel Environmental, Inc. 1993. Site Inspection, Rohr Industries, Inc. (aka Rohr, Inc.), Foot of H Street, Chula Vista, CA 92012, for EPA Region IX. November 15.

7. Bodhi Group, Inc. 2013. Draft Report, Source Evaluation of Waste at Outfall 4, L-Ditch and Goodrich Aerostructures Facilities, Chula Vista, California. December.

8. Bradley, Walter W. 1925. Magnesite in California. California Mining Bureau. Bulletin No. 79. May.

9. Bryant, Jehle, Jeffries & Phillips, 1969. Storm Drains in and Adjacent to Tidelands Avenue and "G" Street. July 21.

10. Carey, G. R., McBean, E. A., & Feenstra, S., 2014. DNAPL Source Depletion: 2. Attainable goals and cost-benefit analyses. Remediation Journal, Autumn 2014, 79-106.

11. Carey, G. R., Parker, B.L., Chapman, S.W., & McGregor, R., 2015. Application of an adapted version of MT3DMS for modeling back-diffusion remediation timeframes. Remediation Journal, Autumn 2015, 55-79.

12. Chapman, S. W. & Parker, B. L., 2005. Plume persistence due to aquitard back diffusion following dense nonaqueous phase liquid source removal or isolation. Water Resources Research. Vol. 41, W12411, p. 1-16.

13. Erskine, A.D., 1991. The Effect of Tidal Fluctuation on a Coastal Aquifer in the UK. Ground Water. Vol. 29, No. 4, p. 556-562.

14. Haley & Aldrich, Inc., 2014a. Derivation of Site-specific Groundwater Quality Protection Levels for Vadose Zone Soil, South Campus Property, Chula Vista, California. January 30.

15. Haley & Aldrich, Inc., 2014b. Revised Derivation of Site-specific Groundwater Quality Protection Levels for Vadose Zone Soil, South Campus Property, Chula Vista, California. November 11.

16. Haley & Aldrich, Inc., 2015 Haley & Aldrich, Inc., 2015. Groundwater Remedial Action Plan – Former South Campus, Chula Vista, California. Prepared for Rohr, Inc., a UTC Aerospace Systems Company, San Diego, California, December 14.

17. Haley & Aldrich, Inc. 2016a. ASTM Phase I Environmental Site Assessment, Rohr Property IDs 7 and 15 (Eastern Portion), Chula Vista. June 21.

18. Haley & Aldrich, Inc. 2017. Groundwater Remedial Action Plan Addendum, Former South Campus, Chula Vista, California. SDRWQCB Reference: SL209294204:talo. August 25.

19. Haley & Aldrich, Inc. 2018a. Phase II Environmental Site Assessment, Buildings 99 and 29, 850 Lagoon Drive, Chula Vista, California, GeoTracker Global ID# T10000011095. January 11.

20. Haley & Aldrich, Inc. 2018b. Phase II Environmental Site Assessment, Vacant Bay Boulevard Properties, 300 Block, Bay Boulevard, Chula Vista, California, GeoTracker Global ID# T10000011095. January 11.

21. Haley & Aldrich, Inc. 2018c. Phase II Environmental Site Assessment, Project Springsteen, Parcel B, 850 Lagoon Drive, Chula Vista, California. January 11.

22. Haley & Aldrich, Inc, 2018d. Revised Soil Remedial Action Plan, Former South Campus, North of Exchange Parcel, Chula Vista, California. April 20.

23. Haley & Aldrich, Inc. 2018e. Sub-slab and Focused Soil Vapor Survey Report, Rohr, Inc. – Eastern Parcels, Buildings 29, 99 and 100, Chula Vista, California. September 6.

24. Haley and Aldrich, 2019a. Updated Site Conceptual Model, Former South Campus, Chula Vista, California. August 21.

25. Haley & Aldrich, Inc., 2019b. Data Gap Assessment Report, Rohr, Inc. - Parcel B, 850 Lagoon Drive, Chula Vista, California. November 11.

26. Haley & Aldrich, Inc., 2020. Data Gap Assessment Report, Rohr, Inc. - Parcel A, Building 29, 850 Lagoon Drive, Chula Vista, California. February 18.

27. Huntley, David, 2000. Analysis of the Potential for Downward Leakage of Dissolved-Phase Chlorinated Hydrocarbons, BF Goodrich Aerospace Facility, Chula Vista, CA. January 9.

28. Kavanaugh et al., 2013. Alternatives for managing the nation's complex contaminated groundwater sites. The National Academies Press, Washington, D.C.

29. Pomeroy & Associates, 1952. Proposed Waste Disposal Program for Rohr Aircraft Corporation – Chula Vista. December 15.

30. Post, Vincent, Kooi, Henk, and Simmons, Craig, 2007. Using Hydraulic Head Measurements in Variable-Density Ground Water Flow Analyses, Ground Water, Vol 45, No. 6, p. 664-671.

31. Rick Engineering, 1998. BF Goodrich Aerospace Campus Existing Storm Drain Exhibit. July 10.

32. Rohr Corporation, 1966. A Report on the Process Rinse Waters and Other Wastes for the Water Quality Control Board. March 1.

33. Rohr Corporation, 1970. Facilities Planning, Long Range Planning Section, updated: January.

34. San Diego Regional Water Quality Control Board, 1966. A Staff Report to the San Diego Regional Water Quality Control Board, San Diego Bay – 1966. April 13.

35. San Diego Regional Water Quality Control Board, 1998a. Staff Report for Cleanup and Abatement Order No. 98-08 issued to The Aerostructures Group of BF Goodrich Aerospace (formerly Rohr, Inc.) and BF Goodrich Company" by K. Zachary. March 26.

36. San Diego Regional Water Quality Control Board, 1998b. Cleanup and Abatement Order No. 98-08, Aerostructures Group of BF Goodrich Aerospace (formerly Rohr, Inc.) and the BF Goodrich Company, 850 Lagoon Drive, Chula Vista, San Diego County, California. April 2.

37. San Diego Regional Water Quality Control Board, 2015. Addendum No. 2 to Cleanup and Abatement Order No. R9-2014-0019, Former South Campus Site, Chula Vista, CA (Site ID #2092900). December 17.

38. SECOR International Incorporated, 1999. Phase I and Phase II Site Investigation, BF Goodrich Aerospace Aerostructures Group (Formerly Rohr, Inc.), Chula Vista, California. October 25.

39. Superfund Amendment and Reauthorization Act. 1986.

40. URS Corporation. 2001. Results of Subsurface Investigation Vicinity of New Wastewater Treatment Plant, West of Building 1, BF Goodrich Aerospace Aerostructures Group, Chula Vista, California. March 9.

41. URS Corporation. 2005a. "Report of Corrective Action, Goodrich Aerostructures, Inc. – Outfall No. 1, Chula Vista, California. April 25.

42. URS Corporation. 2005b. Report of Site Investigation and Groundwater Modeling Evaluation of Environmental Impacts Related to Proposed Undergrounding of SDG&E Power Lines Across Goodrich Aerostructures Facility, Chula Vista, California. November 17.

43. URS Corporation. 2007. Report of Vat Removal and Site Assessment, Goodrich Aerostructures, North Campus, Chula Vista, California. June 21.

44. URS Corporation. 2009. Report of Subsurface Investigation, Emergency containment Sump, Rohr - Tank No. 6, Goodrich Aerostructures, 850 Lagoon Drive, Chula Vista, California. June 11.

45. URS Corporation. 2010. Report of Subsurface Investigation, N/C Machine Shop Sump – HMMD Tank No. 34, Goodrich Aerostructures, 850 Lagoon Drive, Chula Vista, California. December 20.

46. URS Corporation. 2010. Goodrich Aerostructures, Tank No. 6 – Oiler Shed Sump, Building 1, 850 Lagoon Drive, Chula Vista, California. Voluntary Assistance Program No. H02457-001. December 15.

47. URS Corporation. 2012. Site Assessment Report, Goodrich Aerostructures, Former North Oiler Shed UST, Chula Vista, California, DEH VAP Case No. H02457-013. April 26.

48. URS Corporation. 2013. Phase I Environmental Site Assessment, UTAS – Chula Vista, 850 Lagoon Drive Chula Vista, California 91910. April 2.

49. URS Corporation. 2015. Supplemental Remedial Investigation Report, Rohr, Inc. – North Campus, 850 Lagoon Drive, Chula Vista, California. May 1.

50. URS Greiner Woodward-Clyde, 1999. Report of Subsurface Investigation, BFGoodrich Aerospace Facility, Chula Vista, California. January 12.

51. URS Greiner Woodward-Clyde. 2000. "Report of MTBE Groundwater Sampling, Soil Excavation and Product Recovery, BFGoodrich Aerospace Aerostructures Facility, Building 57-Former Diesel-fuel UST Release, Chula Vista California. April 12.

52. U.S. Environmental Protection Agency, 1989. RAGS, Part A EPA, 1989. Risk Assessment Guidance for Superfund (RAGS), Vol. I, Human Health Evaluation Manual (Part A). Office of Emergency and Remedial Response. December.

53. U.S. Army Corps of Engineers. 1998. "Categorical Exclusion and Ineligible Findings Form, Defense Environmental Restoration Program, Formerly Used Defense Sites." March 10.

54. Vukovic, M., and Soro, A., 1992. Determination of Hydraulic Conductivity of Porous Media from Grain-Size Composition. Water Resources Publications, Littleton, CO.

55. Woodward-Clyde Consultants. 1998a. Report of Comprehensive Storm Water Runoff Sampling, March-April 1998, Rohr, Inc., Chula Vista, California. May 11.

56. Woodward-Clyde Consultants. 1998b. Data Compilation and Evaluation Report, Rohr, Inc., Chula Vista, California." May 27.

57. Woodward-Clyde Consultants. 1998c. "Storm Water Conveyance System Investigation Report, Rohr, Inc., Chula Vista, California. July 13.

TABLES

TABLE 1
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL A
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless otherwise specified)	Status	Potential Chemicals Associated with Feature/Area	Previous Soil Assessment Summary	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Underground Storage Tanks/Underground Vessels									
Machining Coolant UST (Blanchard Grinder)	29	3-09598	1,345	closed	TPH, Metals	Closure sampling, UT-22, B29-V19, B29-33A, -33B and -33C	N	ABC - Active in 1998 URS - Closed on 6/15/99 based on TPH results DEH Permit No. AT4199 TCE present in soil vapor.	ABC Plate 9, URS Phase I, H&A Phase I, URS Phase II, H&A Vapor Survey
Wastewater Clarifier	29	204	U	inactive	TPH, VOCs, Metals	B29-17	N	No issues in B29-17.	H&A Phase I, H&A Phase II
Clarifier	100	200	U	inactive	TPH, Metals	UT-03, B99-02, B100-V03	N	H&A reported in Phase I "uncertain if it remains present."	URS Phase II, H&A Phase II, H&A Vapor Survey
Sump	100	NA	U	U	TPH, VOCs, Metals	UT-03, B99-02, B100-V03	N	Soil samples collected at 1 and 5 feet. No VOCs or PCBs detected. TPH detected at 1 foot at 170 mg/kg. Arsenic, cadmium, and lead below industrial CHHSLs but above residential criteria in 2013. Identified as a REC in H&A Phase I because groundwater was not sampled.	URS Phase II, H&A Phase II, H&A Vapor Survey
Aboveground Storage Tanks/ Paint Booths									
Photo Lab Collection AST	29	T-29-1 (201)	1,100	removed	TPH, Metals	B29-06, B29-V10	N	Polyethylene wastewater collection tank from Photo Lab	H&A Phase I, H&A Phase II, H&A Vapor Survey
500 gallon R&D Lab Collection AST	29	T-29-2 (202)	500	removed	TPH, Metals	B29-04	N	Polyethylene wastewater collection tank from R&D Labs	H&A Phase I, H&A Phase II
HTSD Line (4 ASTs)	29	T-29-(HTS 1) (203)	163 each	removed	TPH, Metals	UT-19	N	Consisted of 4 ASTs: alkaline cleaning, hot water seal, rinse and wastewater. No issues downgradient at UT-19.	H&A Phase I, URS Phase II
LPG Tanks (2)	29	226	436 each	removed/ inactive	None	NA	N	LPG tanks do not require investigation.	URS Phase I, H&A Phase I
Former Paint Booth	29	161	U	removed	VOCs, Metals	UT-25, B29-10, B29-15, B29-V13, B29-V16	N	ABC - Active in 1998 URS - Removed in 2013 URS - Relocated to southern part of Bldg. 29, then relocated to Building 1 south of Machine Shop	ABC Plate 9, URS Phase I, H&A Phase I, URS Phase II, H&A Phase II, H&A Vapor Survey
Degreasers									
Small Degreaser	29	300	U	removed	VOCs	B29-V03, B29-24	N	Recent discussion with Rohr personnel indicates there was a small degreasing unit located in the northern portion of Building 29 in the Former Maintenance Department.	
Cold Solvent Degreaser	29	301	U	closed	VOCs	B29-17	N	Graymills Model T4330F Parts Washer H&A noted in Phase I "Obtained from retired APCD permit, 1998." Recent discussion with Rohr personnel indicates that this degreaser was in the southern portion of Building 29 in small tool repair.	URS Phase II, H&A Phase I and IIs, H&A Vapor Survey

TABLE 1
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL A
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless otherwise specified)	Status	Potential Chemicals Associated with Feature/Area	Previous Soil Assessment Summary	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Other Operations/Equipment									
Mills and Lathes (4)	29	NA	NA	removed	TPH, VOCs	B29-V17, B29-21, B29-32 through -35 (A, B & C)	N	H&A reported in the Phase I that photographs of the mills and lathes in the tooling area showed fluid on the floor surface. Some investigated. VOCs in soil vapor in some instances.	H&A Phase I, H&A Phase II, H&A Vapor Survey
Former Maintenance Department	29	NA	NA	NA	TPH, VOCs	Downgradient (UT-23, UT-24, UT-25), B29-V01 through -V09, B29-22 through -31	TCE	H&A reported in the Phase I that the historical use of oils and potentially solvents in a portion of Building 29. Soil vapor indicated VOCs present. Further data gap assessment proposed.	H&A Phase I, URS Phase II, H&A Vapor Survey
Pre-Rohr Features									
Unleaded Gasoline UST	99/100	145	10,000	closed	TPHg, BTEX	B99-01, B100-V01	N	URS reported this feature as closed prior to Rohr ownership.	ABC Plate 9, URS Phase I, H&A Phase I, H&A Phase II, H&A Vapor Survey
Diesel Fuel UST	99/100	146	10,000	closed	TPHd	B99-01, B100-V01	N	URS reported this feature as closed prior to Rohr ownership.	ABC Plate 9, URS Phase I, H&A Phase I, H&A Phase II, H&A Vapor Survey
Waste Oil UST	99/100	147	1,000	closed	TPH, Metals	B99-01, B100-V01	N	URS reported this feature as closed prior to Rohr ownership.	ABC Plate 9, URS Phase I, H&A Phase I, H&A Phase II, H&A Vapor Survey
Waste Solvent UST	99/100	148	100	closed	VOCs, TPH	B99-02, B100-V02	N	URS reported this feature as closed prior to Rohr ownership.	ABC Plate 9, URS Phase I, H&A Phase I, H&A Phase II, H&A Vapor Survey
Possible Former Lumber Yard	29	NA	NA	NA	Phenols	UT-25, B29-08 through -11, B29-V11, B29-V13	N	H&A reported in the Phase I that historical documents and photos suggested a lumber yard occupied a portion of Parcel 15 in the late 1940s and may have engaged in wood treating prior to Rohr's ownership. No phenols detected. No VOCs in soil vapor.	H&A Phase I, URS Phase II

TABLE 1
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL A
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless otherwise specified)	Status	Potential Chemicals Associated with Feature/Area	Previous Soil Assessment Summary	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Other Operations/Equipment									
Former Shallow Swale	29	NA	NA	NA	VOCs	UT-23, UT-24, B29-06, B29-08, B29-V06, -08 and -09, B29-22 through -31	N	H&A reported in the Phase I that 1948 aerial photograph showed a shallow depression filled with debris on the southern and western perimeter of the northern quarter of the parcel (Rohr ID 15). May be current location of storm drain. Investigated through data gap assessment in Maintenance Department.	H&A Phase I, URS Phase II
Former Truck Engine Repair with potential hydraulic lifts	100	NA	NA	NA	TPH, VOCs	UT-03, B99-02, B100-V02	N	H&A reported in the Phase I that Bldg. 100 contained three bays. The bays were used for truck repair. URS indicated that there was a 30-inch deep work pit in the bays.	URS Phase I and IIs, H&A Phase I and IIs, H&A Vapor Survey
Western Drainage Swale	29, 99, and 100	NA	NA	NA	Metals, VOCs, PCBs, PAHs	UT-02, UT-03, UT-18, UT-19, UT-20, UT-21, UT-66	N	URS detected PCBs in boring UT-02 (770 µg/kg).	URS Phase I and IIs
Former Agricultural Property Use	29, 99, and 100	NA	NA	NA	Metals, OCPs	B99-01 through -04, B29-01 through -20	As	H&A reported vacant land was previously used for agricultural purposes for citrus and row crops prior to 1950s. Evaluate Metals in surface soil.	URS Phase I and IIs, H&A Phase I and IIs, H&A Data Gap

NOTES AND ABBREVIATIONS:

UST - Underground storage tank
AST - Aboveground storage tank
UV - Underground vessel
Y - Yes
N - No
NA - Not applicable
U - Unknown
µg/kg - microgram per kilogram
µg/L - microgram per liter
bgs - below ground surface
DEH - San Diego Department of Environmental Health
SDRWQCB - San Diego Regional Water Quality Control Board
VOCs - volatile organic compounds
Metals -Title 22 metals
TCE - trichloroethene
OCPs - organochlorine pesticides
TPH - total petroleum hydrocarbons
PAH - Polynuclear Aromatic Hydrocarbons
TPHd - TPH diesel range organics
TPHg - TPH gasoline range organics
PCBs - Polychlorinated biphenyls
BTEX - Benzene, toluene, ethylbenzene and xylenes
As - Arsenic

Map ID is the Rohr tank number or number assigned by Adrian Brown Consultants (1998) or URS Corporation (2013). The Map IDs are noted on Figure 4.

1. Adrian Brown Consultants, Inc. 1998. ASTM Phase I Site Assessment, B.F. Goodrich Aerospace, Foot of H Street, Chula Vista, California. June 4.
2. Woodward-Clyde International-Americas. 1998. Data Compilation and Evaluation Report, Volume I, Rohr, Inc. Chula Vista, California. May 27.
3. URS Corporation. 2013. Phase I Environmental Site Assessment, UTAS - Chula Vista, Chula Vista, California. April 2.
4. URS Corporation. 2015. Supplemental Remedial Investigation Report, Rohr, Inc. – North Campus, 850 Lagoon Drive, Chula Vista, California. May 1.
5. Haley & Aldrich Inc. 2016. ASTM Phase I Environmental Site Assessment, Rohr, Inc., Property IDs 7 and 15, Chula Vista, California. July 21.
6. Haley & Aldrich, Inc. 2018. Phase II Environmental Site Assessment, Buildings 99 and 29, 850 Lagoon Drive, Chula Vista, California, GeoTracker Global ID# T10000011095. January 11.
7. Haley & Aldrich, Inc. 2018. Sub-slab and Focused Soil Vapor Survey Report, Rohr, Inc. – Eastern Parcels, Buildings 29, 99 and 100, Chula Vista, California. September 6.
8. Haley & Aldrich Inc. 2020. Data Gap Assessment Report, Rohr, Inc. - Parcel A, Building 29, Chula Vista, California. February 18.

TABLE 2
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL B
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless specified)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Underground Storage Tanks/Underground Vessels									
Waste Oil and Coolant UST	1	5	10,000	closed	TPH, VOCs, Metals	T6-01 through -04, PB-V06	N	ABC - reported in 1998 as closed URS - reported in 2013 as closed in place February 1987. Adjacent to building footing. Permit No. AT0792 DHS record shows closure on 8/11/86 UST located in Oiler Shed and not the Machine Shop as indicated in ABC 1998	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap,
North Oiler Shed UST	1	6a	550	closed	TPH, VOCs	Soil sampling during tank closure, B1-UST08C	1,2-DCA	ABC - reported in 1998 as closed. UST removed by URS in 2000. DHS Compliance Report dated 1/30/02. Claim of Exemption 1/27/87. Was not in use.	ABC Plate 9, URS Phase I, GeoTracker ID No. T0607301189
Oiler Shed Sump	1	6b	90	closed	TPH, VOCs	T6-01 through -04	N	ABC - reported in 1998 as active URS - reported as closed in place 6/15/99, Permit No. AT4410 Included 15-foot-long trench investigated in 2000. Closure by DEH for TRPH only.	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap, GeoTracker ID No. T0607399259
N/C Machine Shop Sump and associated trenches	1	34	720	closed	TPH, VOCs	T34-01 through -09, UT-48, UT-49, PB-74 through -79, PB-V05	N	URS - reported in 2013 tank filled with concrete DEH Compliance Report 1/30/03 Permit No. AT4410 closed on 6/15/99 DEH transferred case to RWQCB, 2012 Administratively closed in 2019	URS Phase I and IIs, H&A Phase II, H&A Data Gap, GeoTracker ID No. T0608187932
Water UST (Rinse Tank), C70 Salt Bath	1	1(1-C70R)	3,600	removed	Water	B1B-series borings, MW1-series wells	N	Adjacent to C70 Salt Bath ABC - reported as active in 1998 URS - removed in 2011, closed by DEH, transfer to RWQCB	ABC Plate 9, URS Phase I WCC Salt Bath Investigation, 1992
Water UST (Quench Tank), C70 Salt Bath	1	15(15-C70Q)	3,600	removed	Water	B1B-series borings, MW1-series wells	N	Adjacent to C70 Salt Bath ABC - reported as active in 1998 URS - removed in 2013, closed by DEH, transfer to RWQCB	ABC Plate 9, URS Phase I WCC Salt Bath Investigation, 1992
C70 Salt Bath	1	3(3-C70SB)	3,600	removed	Cr(VI)	B1B-series borings, MW1-series wells	N	Aluminum Salt Bath Conditioner ABC - reported as active in 1998 Soil containing CrVI removed in 1992 URS - removed in 2013, closed by DEH, transfer to RWQCB	WCC Data Compilation, ABC Plate 9, URS Phase I, URS Phase II, H&A Data Gap
Cooling Water Sump/UST, C70 Salt Bath	1	4-(4-C70S)	1,681	closed	U	MW1-3	N	ABC - reported as inactive in 1998 URS - reported as closed in 2013, closed by DEH, transferred to RWQCB, filled with concrete	WCC Data Compilation, ABC Plate 9, URS Phase I

TABLE 2
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL B
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless specified)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Underground Storage Tanks/Underground Vessels									
V-2 Degreaser (1,1,1-TCA UST)	1	3-07824	U	closed	VOCs (1,1,1-TCA)	UT-58, PB-041, PB-042, PB-058, PB-109, PB-V13	cis-1,2-DCE, trans-1,2-DCE	Degreaser was in below-grade vault. ABC - reported as exempt in 1998, mislabeled on ABC Plate 9 URS - Vault filled with concrete.	ABC Plate 9, URS Phase I, URS Phase II, H&A Phase II, H&A Data Gap
V-3 Degreaser (1,1,1-TCA UST)	1	3-13888	U	closed	VOCs (1,1,1-TCA)	V3-3, V3-4, HPNC-14, PB-43, PB-V08	N	Degreaser was in below-grade vault. Metal tank, 10 feet by 25 feet in 30- by 40-foot rectangular vault. Installed in 1984. ABC - reported as exempt in 1998, mislabeled on ABC Plate 9 URS - Vault filled with concrete. Investigated for closure in 1993. Degreaser used 1,1,1-TCA, but TCE was present in groundwater.	ABC Plate 9, URS Phase I, URS Phase II, H&A Phase II, H&A Data Gap
Unleaded Gasoline UST	25	116	10,000	removed	TPHg	UST Closure Sampling, NCW-013	N	ABC - reported as closed in 1998 URS - reported as closed by removal 4/29/87 Permit No. NT0622 DHS record shows closure on 8/11/86 Precursor to 3-15615, 3-15616, 3-15617	ABC Plate 9, URS Phase I, H&A Closure
Unleaded Gasoline UST	25	3-15615	6,000	closed	TPHg	UST Closure Sampling, NCW-013	N	ABC - reported as active in 1998 URS - Transportation Area USTs Closed by removal 8/3/02 Permit No. AT4828 DEH records show closure on 11/19/02	ABC Plate 9, URS Phase I, H&A Closure
Unleaded Gasoline UST	25	3-15616	6,000	closed	TPHg	UST Closure Sampling, NCW-013	N	ABC - reported as active in 1998 URS - Transportation Area USTs Closed by removal 8/3/02 Permit No. AT4828 DEH records show closure on 11/19/02	ABC Plate 9, URS Phase I, H&A Closure
Diesel Fuel UST	25	3-15617	6,000	closed	TPHd	UST Closure Sampling, NCW-013	N	ABC - reported as active in 1998 URS - Transportation Area USTs Closed by removal 8/3/02 Permit No. AT4828 DEH records show closure on 11/19/02	ABC Plate 9, URS Phase I, H&A Closure
Diesel Fuel UST	57	1 (102)	10,000	closed	TPHd	MW57-series wells, HP57-series borings, B57-series borings, PB-V11, PB-V12	N	ABC - reported closed in 1998 URS- reported closed by removal 8/5/87 Rohr Tank No. 1 Permit No. NT0622 DHS record shows closure on 8/11/86	ABC Plate 9, URS Phase I, H&A Data Gap

TABLE 2
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL B
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless specified)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Underground Storage Tanks/Underground Vessels									
Diesel Fuel UST	343	2	50	closed	TPHd	UST Closure Sampling	N	ABC - reported feature in 1998 as drum, closed URS - reported in 2013 feature closed by removal 3/2/93 Permit No. AT2841 Backup fuel for fire system	ABC Plate 9, URS Phase I
Storage Tank (1970)	9	NA	UN	UN	VOCs, Metals, CrVI	PB-017	N	Storage tank shown on Rohr 1970, north of Building 9. It could be incorrectly located and represent the diesel fuel UST at Building 57.	H&A Phase II
Historical C60 Salt Bath, Quench and Rinse Tanks	1	166, 167, and 168	3,600 each	filled	CrVI, VOCs	MW1-3, -4, -5, UT-67, PB-V02	N	Mirror image of C70 salt bath with salt bath quench and rinse tanks. Filled pre-1974.	WCC Salt Bath Investigation, 1992, URS Phase I, URS Phase II
V-1 Degreaser (1,1,1-TCA) UV	1	3-09978	U	closed	VOCs (1,1,1-TCA)	UT-37, PB-V03	1,1-DCE	Degreaser was in below-grade vault. ABC - reported as exempt in 1998 URS - Vault filled with concrete.	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap
50-Ton Vault (Column B-15)	1	208, 209	NA	filled	TPH, VOCs	UT-38, PB-063	N	Column B-15 Feature was existing as of URS Phase II. Hydraulic equipment in vault.	URS Phase I and IIs, H&A Phase II
Historical WD Line (Column D-4/5)	1	230	NA	removed	VOCs, Metals	UT-40	N	Column D-4/5	URS Phase I and IIs
Hufford Vault and Sheridan 1 and 2 Vaults	1	216, 217, 218	NA	Inactive	TPH, VOCs	UT-45, UT-46, PB-032, PB-033, PB-046, PB-V09	TPH, 1,1-DCA, 1,1-DCE, cis-1,2-DCE	Oils present on floor surface during operations. Free product in UT-46 VOCs in soil vapor	URS Phase I and IIs, H&A Phase II, H&A Data Gap
R Line	1	223	4,765 each	inactive	VOCs, Metals	R-series borings, UT-42, UT-43, PB-034, PB-035, PB-049, PB-049A	N	Soil removed and disposed prior to construction, 2000.	URS Phase I and IIs, H&A Phase II
E/F Line	1	222	multiple	inactive	CrVI, VOCs, Metals	EF-series borings, UT-41, PB-36, PB-37	N	Soil removed and disposed prior to construction, 2000. Boring was downgradient of Alodine Tank, Column G-14	URS Phase I and IIs, H&A Phase II
D Line	1	221	multiple	inactive	CrVI, VOCs, Metals	CD-series borings, PB-039	N	Soil removed and disposed prior to construction, 2000.	H&A Phase II
Hydrotest/HD Line	1	212	NA	inactive	TPH, VOCs, Metals	UT-47	N	Product cleaning and etching process line. Hydraulic equipment. Column D-12. Below-grade vault.	URS Phase I and IIs
Machine Shop: 5-Axis Mill, VTL Lathe	1	213, 214	NA	filled	TPH, VOCs, Metals	UT-48, UT-49, UT-50, PB-078	N	5-Axis Mill (Column C-23) Former VTL lathe (Column C-35/36) Hydraulic equipment, below-grade vaults.	URS Phase I and IIs, H&A Phase II

TABLE 2
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL B
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless specified)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Underground Storage Tanks/Underground Vessels									
Diesel Fuel UV	343	13	100	closed	TPHd	Information not readily available.	N	ABC - reported in 1998 as closed URS - closed by removal 4/2/85 Permit No. AT0004 DHS record shows closure on 2/11/88	ABC Plate 9, URS Phase I
Hot Size	1	220	NA	former	TPH, VOCs, Metals	UT-51, UT-52, PB-052	N	Hydraulic vault	ABC Plate 8, URS Phase I and IIs, H&A Phase II
VTL Lathe	1	225	NA	former	TPH, VOCs, Metals	PB-056	N	Hydraulic vault t	ABC Plate 8, URS Phase I and IIs, H&A Phase II
Aboveground Tanks/Paint Booths									
Oiler Shed - Light Hydraulic Oil AST	1	107	3,000	former	TPH	T6-01 through -04, PB-082, PB-V06	N	URS Table 5 indicates feature was removed	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap
Oiler Shed - Heavy to Medium Hydraulic Oil AST	1	108	3,000	former	TPH	T6-01 through -04, PB-082, PB-V06	N	URS Table 5 indicates feature was removed	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap
Hydraulic Oil AST	1	119	U	former	TPH	T6-01 through -04, PB-082, PB-V06	N	URS - reported as removed as of 2013	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap
Hydraulic Oil AST (Mobile 25 DTE)	1	124	4,000	active	TPH	T6-01 through -04, PB-082, PB-V06	N	URS - reported as active in 2013	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap
Hydraulic Oil AST (Mobile 25 DTE)	1	125	4,000	active	TPH	T6-01 through -04, PB-082, PB-V06	N	URS - reported as active in 2013	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap
Lubricant Coolant AST	1	126	1,000	active	TPH, coolant	T6-01 through -04, PB-082, PB-V06	N	URS - reported as active in 2013	ABC Plate 9, URS Phase I, H&A Phase II, H&A Data Gap
Historical Chemical Baths <1974 (Former D and H Lines)	1	169	U	removed	CrVI, Metals, VOCs	UT-32, UT-33, UT-35, PB-030, PB-031	cis-1,2-DCE, trans-1,2-DCE	Rohr 1966 - Area 1 metal cleaning process tanks, D-Line (6 tanks) and H-line (2 tanks). Wastewater discharged north of Bldg. 9 (now in Bldg. 50) contained Cr (10 mg/L), Ni (10 mg/L), TPH (50,000 mg/L) and VOCs (20,000 mm/L as volatile suspended solids).	Rohr 1966, URS Phase I and IIs, H&A Phase II
Historical Degreasers (Nos. 170 & 171)	1	170, 171	U	removed	VOCs	UT-34, UT-35	N	Column B-4	URS Phase I and IIs
Propane (Mapp gas) AST	48	109	1,100	former	propane	None	NA	Propane AST URS reported feature as removed	ABC Plate 9, URS Phase I
TCE/TCA AST	57	103	10,000	former	TCE, 1,1,1-TCA	MW57-series wells, HP57-series borings, B57-series borings, PB-V11, PB-V12	TCE, 1,1,1-TCA, cis-1,2-DCE, 1,1-DCE, 1,1-DCA	Removed to construct tool yard. Many investigations conducted. Soil remediated through excavation. Free product removed.	ABC Plate 9, URS Phase I, H&A Data Gap

TABLE 2
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL B
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless specified)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Aboveground Tanks/Paint Booths									
Diesel Fuel AST	57	105	5,275	former	TPHd	NA	NA	URS reported there was no evidence of this feature.	ABC Plate 9, URS Phase I
LPG AST Farm (4 tanks)	57	106	102,000	removed	TPHg	NA	NA	ABC reported these features as active in 1998 URS reported these features as removed in 2013	ABC Plate 9, URS Phase I
Argon AST	443	117	580,000 ft3	former	NA	NA	NA	Argon gas tank.	ABC Plate 9, URS Phase I
Historical Process Lines	311 443	NA	NA	former	VOCs, Metals, CrVI	UT-35, PB-007, PB-008	N	ABC Plate 9 shows Building numbers as 311 and 443 H&A investigated these areas, as there were former process lines located here.	URS Phase I and IIs, H&A Phase II
Particulate Collection Tank	500	302	NA	former	Metals	PB-020	N	Grinding of kirksite (lead-zinc alloy) was conducted in Shed 500. Particulates from the exhaust system collected in a water-filled tank into the early 1990s. A dry vacuum system replaced the wet unit.	URS Phase I, H&A Phase II
Transportation Oil - Water Separator	25/341	144	U	inactive	VOCs, TPH, Metals, SVOCs, PCBs	UT-64, PB-113	N	ABC reported this feature as active in 1998 URS reported this feature as active in 2013	ABC Plate 9, URS Phase II, H&A Phase II
1,1,1-TCA Aboveground Degreaser	50	172	NA	removed	VOCs	UT-53	N	1,1,1-TCA aboveground unit	URS Phase II
Paint Booth	1	164	U	removed	VOCs, Metals	PB-052, PB-V10	N	ABC - reported as active in 1998 URS - reported as removed in 2013	ABC Plate 9, URS Phase I, H&A Phase II
Paint Booth	1	165	U	removed	VOCs, Metals	PB-056	N	ABC - reported as active in 1998 URS - reported as removed in 2013	ABC Plate 9, URS Phase I, H&A Phase II
East Inlet Paint Shop (2 Paint booths)	116	205	U	removed	VOCs, Metals	PB-070, PB-065	N	Two paint booths were installed post-2000.	URS Phase I, H&A Phase II
Detail Paint Shop (5 Paint Booths)	1	219	U	removed	VOCs , Metals	PB-035, PB-044	N	The paint booths were installed post-2000.	URS Phase I, H&A Phase II
West Paint Shop	55	303	U	removed	VOCs , Metals	PB-093	N	There were two paint booths in the West Paint Shop that were installed post-2000.	H&A Phase II
Paint Booth	1	215	U	removed	VOCs, Metals	PB-078	N	There was a single paint booth south of the machine shop. The other booths noted in URS Phase I were grinding booths. This paint booth was relocated from Building 29.	URS Phase I and Iis, H&A Phase II
Paint Booth	47 (WWTP)	150	2,212	removed	VOCs, Metals	UT-62	N	URS reported the feature as removed URS drilled UT-62 to assess west side of WWTP and former paint booth.	Rohr 1966, ABC Plate 9, URS Phase I, URS Phase II
Paint Booth	Just south of G Street	224	NA	former	VOCs, Metals	PB-018	N	Shown on Rohr 1970.	H&A Phase II

TABLE 2
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL B
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless specified)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Other Operations									
Foundry	**1**	NA	NA	former	Metals	PB--019 through PB-22	N	Northeast corner of building where tools were melted and forged.	H&A Phase II
Drop Hammer Presses	1	NA	NA	removed	TPH, VOCs	PB-022	N	Drop hammers were located on wooden foundations to absorb vibration. Oils present on floor surface during operations.	URS Phase I, H&A Phase II
William and White Press	1	NA	NA	inactive	TPH, VOCs	UT-36, PB-028	N	Feature was existing as of URS Phase II. Hydraulic equipment in vault. Oils present on floor surface during operations.	URS Phase I and IIs, H&A Phase II
Other Operations									
Historical Process Line (Door 1-20)	1	231	NA	removed	VOCs	UT-39, PB-064	N	Door 1-20	URS Phase I and IIs, H&A Phase II
Building 55 (Former Maintenance Building 2)	55	NA	NA	NA	U	UT-44, PB-086 through -089, -092 and -093	N	Rohr facility drawing identifies former Building 2 as being used for maintenance. Tank noted at approx. NW corner of Bldg. 55.	Rohr 1970, URS Phase II, H&A Phase II
Former Building 11	11	NA	NA	former	VOCs, Metals	PB-009, PB-010	N	VOCs present in groundwater in this general area.	H&A Phase II
Former Building 56	56	NA	NA	former	VOCs, Metals	HP57-11, PB-011, PB-012	N	VOCs present in groundwater in this general area.	H&A Phase II
Former Building 57	57	NA	NA	former	VOCs, Metals	HP57-series borings, PB-013, PB-014	N	VOCs present in groundwater in this general area related to TCA/TCE AST.	H&A Phase II
Chemical Services	Southwestern portion of Site	NA	NA	existing	VOCs, Metals, TPH	UT-65	N	Facility constructed in 2000 when Chem Stores moved here from South Campus.	URS Phase II
Equipment Maintenance Area	Southwestern portion of Site	NA	NA	active	TPH, BTEX	UT-63	N	Maintained equipment on this paved area.	URS Phase I and IIs
Wastewater Treatment Plant	Western portion of Site	NA	NA	active	Acids, caustics, CrVI	UT-60, UT-62	N	WWTP constructed in 2000 to replace WWTP on South Campus. Tanks described in Table 6 - URS Phase I.	URS Phase I and IIs
Surface Water Features									
Historical Outfall A (1940s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	HPNC-06, UT-54, PB-104, PB-131, PB-132, PB-133	PCBs	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 8, URS Phase I and IIs, H&A Phase II, H&A Data Gap
Historical Outfall B (1940s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	PB-134, PB-135, PB-136	N	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 8, URS Phase I and IIs, H&A Data Gap
Historical Outfall C (1940s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	UT-55, PB-106, PB-107, PB-137, PB-138, PB-139	N	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 8, URS Phase I and IIs H&A Phase II, H&A Data Gap

TABLE 2
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL B
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless specified)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Surface Water Features									
Historical Outfall D (1940s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	UT-56, PB-109, PB-140, PB-141, PB-142	Sb, Cr, Pb, PCBs	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 8, URS Phase I and IIs H&A Phase II, H&A Data Gap
Historical Outfall E (1940s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	PB-143, PB-144, PB-145	PCBs	Approximate location of outfall based on storm water conveyance system overlay. URS Phase II encountered refusal.	ABC Plate 8, URS Phase I, H&A Data Gap
Historical Outfall F (1940s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	UT-57, PB-146, PB-147, PB-148	Sb	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 8, URS Phase I and IIs, H&A Phase II, H&A Data Gap
Historical Outfall G (1940s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	UT-58, PB-113, PB-114, PB-149, PB-150	Sb,Pb,TCE, cis-1,2-DCE, T, PCBs	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 8, URS Phase I and IIs, H&A Data Gap
Historical Outfall H (1960s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs, PAHs	PB-115, PB-130	N	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 7, URS Phase I and IIs, H&A Phase II, H&A Data Gap
Historical Outfall I (1960s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	CPT-006, UT-59, PB-129	N	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 7, URS Phase I and IIs, H&A Data Gap
Historical Outfall J (1960s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	UT-60, PB-128	N	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 7, URS Phase I and IIs, H&A Data Gap
Historical Outfall K (1960s)	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	UT-61, PB-127	N	Approximate location of outfall based on storm water conveyance system overlay.	ABC Plate 7, URS Phase I and IIs, H&A Data Gap
Former Shoreline, 1940s	Western portion of Site	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs	See map	Sb, Cr, Pb, 1,1-DCE, cis-1,2-DCE, trans-1,2-DCE, T, PCBs	Investigations have identified undocumented fill, hydrocarbon product, and other materials present in borings and excavations along the former shoreline.	Pomeroy & Associates 1952, RWQCB 1966, ABC Plate 7, URS Phase I and II, H&A Phase II, H&A Data Gap
Storm Water Conveyance System	Sitewide	NA	NA	active	VOCs, Metals, CrVI, TPH, PCBs, PAHs	HPNC-01 through -14	Sb, Pb	SWCS conveyed process rinse water to bay prior to installation of a WWTP in early 1970s. SWCS subject of CAO.	Rohr 1966, URS 2001
Drainage Swale	South of G Street	NA	NA	former	VOCs, Metals	HPNC-01, HPNC-02, PB-015, PB-016	Sb	Drainage channel visible on historical aerial photographs.	URS Phase II
Former 1960s Western Drainage Ditch	West of Building 50 and WWTP	NA	NA	former	VOCs, TPH, CrVI, PCBs	UT-59 through -61, PB-115 through PB-120, PB-127 through PB-130	Pb	Remnant drainage ditch following placement of "75-acre" dredged fill west of site that conveyed discharges to San Diego Bay. Storm drain installed in ditch in 1970.	Rohr 1966, Bryant, et. al 1969, Rohr 1970, ABC Plate 7, URS Phase I and IIs, H&A Phase II, H&A Data Gap
PCBs Adjacent to H Street Soil Remediation	West of former 1940s shoreline	NA	NA	NA	PCBs, Metals	PB-121, PB-122, PB-123, CPT-029, CPT-030	N	Northern H Street excavation sidewall contained PCBs when H&A conducted soil remediation. PCBs detected below DTSC comm/ind SLs	H&A 2013, URS Phase II, H&A Phase II, AECOM Data Gap
Western Property Boundary	Western Property Boundary	NA	NA	NA	VOCs, PCBs, Metals	PB-100, Pb-124 through -126	N	Borings advances along property boundary to investigate potential dumping.	H&A Phase II

TABLE 2
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL B
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons unless specified)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs Above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Pre-Rohr Features									
Pioneer Pyrophyllite - VAT (1920s)	East of 1, Parking Lot	NA	NA	NA	TPH	VAT borings PB-001, PB-002	N	Concrete-filled metal feature was encountered when SDG&E was undergrounding its overhead power lines. It was inaccurately reported to DEH as a UST. Soil borings were drilled to delineate TPH and VOCs in shallow groundwater. DEH referred case to RWQCB.	URS Vat Investigations, URS Phase I, H&A Phase II
R&H Tyce Paint Shop (1926)/Pioneer Pyrophyllite	Parking area east of SDGE Substation	NA	NA	former	VOCs, Metals, TPH	PB-001, PB-002	N	Noted on 1926 Sanborn map.	URS Phase I, H&A Phase II
San Diego & Arizona Eastern Railroad Line	Between Pacels A and B	NA	NA	former	TPH, PAHs, Metals	UT-18 though UT-21 and UT-66	N	Easement is owned by Metropolitan Transit System.	URS Phase II
SDG&E Fuel Oil Pipeline	Eastern Parking Lots	NA	NA	former	TPH	VAT-series borings	N	SDG&E operated a fuel oil pipeline that ran from the National City Marine Terminal to the former South Bay Power Plant. The line was drained and cleaned upon its decommissioning by SDG&E. The condition of the line was unknown.	URS Vat Removal
SDG&E Montgomery Substation	South of G Street	NA	NA	active	PCBs	UT-27, UT-28, UT-29, UT-30	PCBs	Sampling conducted at perimeter of substation. Substation not part of the site. PCBs (Aroclor 1248) = 44 mg/kg.	URS Phase II
Chula Vista Sewage Pump Station	South of G Street	NA	NA	active	TPH, VOCs, Metals	NA	NA	City pump station constructed in the 1960s.	

NOTES AND ABBREVIATIONS:

UST - underground storage tank
AST - aboveground storage tank
UV - underground vessel
Y - Yes
N - No
NA - Not Applicable
U - Unknown
µg/L - micrograms per liter
mg/kg - milligrams per kilogram
mg/L - milligrams per liter
bgs - below ground surface
DEH - San Diego Department of Environmental Health
SDRWQCB - San Diego Regional Water Quality Control Board
WWTP - Wastewater Treatment Plant
VOCs - volatile organic compounds
Metals - Title 22 metals
OCPs - organochlorine pesticides

PAH - Polynuclear Aromatic Hydrocarbons
TPHd - TPH diesel range organics
TPHg - TPH gasoline range organics
PCBs - Polychlorinated biphenyls
SVOCs - Semi-volatile organic compounds
Sb - Antimony
Cr - Chromium
BTEX - benzene, toluene, ethylbenzene, and xylene
SWCS - stormwater conveyance system
Pb - Lead
DCE - Dichloroethene
DCA - Dichloroethane
TCE - Trichloroethene
TCA - Trichloroethane
T - Toluene
TPH - total petroleum hydrocarbons
TRPH - total recoverable petroleum hydrocarbons

1. Pomeroy & Associates. 1952.Proposed Waste Disposal Program for Rohr Aircraft Corporation - Chula Vista. December 15.
2. Rohr Corporation. 1966. A Report on the Process Rinse Waters and Other Wastes for the Water Quality Control Board. March 1.
3. San Diego Regional Water Quality Control Borad. 1966. A staff Report to the SDRWQCB, San Diego Bay -1966. April 13.
4. Bryant, Jehle, Jeffries & Phillips, 1969. Storm Drains in and Adjacent to Tidelands Avenue and "G" Street. July 21.
5. Rohr Corporation. 1970. Facilities Plan. January.
6. Adrian Brown Consultants, Inc. 1998. ASTM Phase I Site Assessment, B.F. Goodrich Aerospace, Foot of H Street, Chula Vista, California. June 4.
7. Woodward-Clyde International-Americas. 1998. Data Compilation and Evaluation Report, Volume I, Rohr, Inc. Chula Vista, California. May 27.
8. URS Corporation. 2007. Report of Vat Removal and Site Assessment, Goodrich Aerostructures - North Campus, Chula Vista, California. June 21.
9. URS Corporation. 2013. Phase I Environmental Site Assessment, UTAS - Chula Vista, Chula Vista, California. April 2.
10. Haley & Aldrich Inc. Phase II Environmental Site Assessment, Project Springsteen, Parcel B, Chula Vista, California. January 11.
11. Haley & Aldrich Inc., Data Gap Assessment Report, Rohr, Inc. Parcel B, Chula Vista, California. November 11.
12. AECOM. 2019. Oiler Shed and North of Marina Areas Investigation Report, Rohr, Inc., North Campus, Chula Vista , California. June 7.

TABLE 3
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL C
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Wastewater UV	61	14	129	closed	VOCs, Metals, TPH	None	N	ABC - reported in 1998 as active URS - reported in 2013 as closed DEH e-mail response dated 6/2/03 documents closure of sump	ABC Plate 9, URS Phase I
Paint Booth	61	162	U	inactive	VOCs, Metals	NCW-012	N	ABC - active in 1998 URS - inactive in 2013	ABC Plate 9, URS Phase I
Paint Booth	61	163	U	inactive	VOCs, Metals	UT-10	N	ABC - active in 1998 URS - inactive in 2013, used for storage	ABC Plate 9, URS Phase I
Tyce Buildings (Buildings 78 and 79)	78/79	NA	NA	NA	VOCs	UT-14, UT-15, UT-17, HPNC-series borings	N	Site interview indicated that degreasers may have been in these buildings historically.	URS Phase I and IIs
Outfall 1 Tidal Inlet	West of 61	NA	NA	closed	Metals, PCBs, and PAHs	C-series samples and post-excavation confirmation samples.	N	Sediment was investigated in 2004 under work plan approved by SDRWQCB. Sediment was excavated to concentrations below the Effects Range-Low (ERL) or background and disposed. Clean material was returned to the tidal inlet. SWRWQCB granted no further action following remediation.	URS Outfall I Tidal Inlet
Pre-Rohr Features									
AES Machine Shops (1926)	East of 118	NA	NA	former	TPH, VOCs	UT-04, UT-05, UT-06, UT-07	N	Noted on Sanborn Maps	URS Phase I and IIs
Transformer (1918-1926)	80' W of Railroad ROW, North of G Street	NA	NA	former	PCBs	UT-07	N	Noted on Sanborn Maps	URS Phase I and IIs
Rail Spur	71/78/79	NA	NA	NA	VOCs, PAHs	UT-14, UT-15	N	ABC Plate 9 shows a rail spur running east from Building 79 and bisects west of Building 71, one section continuing east past 71, and the other section running south to connect with the rail line west of Building 29.	ABC Plate 9
IMC Fuel Oil AST (1918-1954)	78	NA	NA	NA	TPH	UT-13	N	Site interviews revealed that oil was encountered near west side of Buildings 78 and 79 when some palms were planted for customer service center.	URS Phase I and IIs
Chula Vista Sewage Treatment Plant	61	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs, PAHs	UT-09, UT-10	N	Facility operated from 1944 through 1966. It included a series of treatment tanks and settling ponds. A pipe discharged the treated effluent into San Diego Bay approximately 930 feet from the historical shoreline.	URS Phase I and IIs
	61	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs, PAHs	UT-11	N		URS Phase I and IIs

TABLE 3
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL C
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Pre-Rohr Features									
Undocumented Fill/Debris Piles	North and West of Building 61	NA	NA	former	VOCs, Metals, CrVI, TPH, PCBs, PAHs	HPNC-19 through -25, HPNC-27, HPNC-28, NCW-011, NCW-012, UT-08, UT-12, UT-17	N	Observed on historical aerial photographs from 1945 through 1959.	URS Phase I and lls
OCP-impacted Soil - Building 107	107	NA	NA	capped/ closed	OCPs	Information not readily available	N	Low concentrations of VOCs in groundwater. Groundwater sampling from monitoring wells (destroyed). Site closed by DEH. OCP-containing soil capped on property with DEH approval.	WCC Data Compilation Report, URS Phase I
Possible USTs - 798 F St.	798 F St.	U	U	U	BTEX, VOCs, TPH	Information not readily available	N	Previous Phase I completed by Ogden for the City of Chula Vista reported a UST located on the property. It was investigated but the Phase I and Phase II reports were not available for review. The DEH VAP provided a NFA letter for these parcels but stipulated that changes in its proposed use as office buildings and parking may require reevaluation for public health purposes.	WCC Data Compilation Report, URS Phase I, H&A Phase I and lls
Lead-containing Surface Soil 350-360 Bay Blvd.	350-360 Bay Boulevard	NA	NA	NA	Lead	Information not readily available	N	Surface soil containing lead was excavated and used as foundation material for cap to close the Otay Class I Landfill under the oversight of the DEH VAP. A NFA letter was issued but not on GeoTracker or EDR.	WCC Data Compilation Report, URS Phase I, H&A Phase I and lls
Monitoring Well MW-1B 350-360 Bay Blvd.	350-360 Bay Boulevard	NA	NA	NA	NA	MW-1B	N	One of three wells (MW-1B, -2B, and MW-3B) installed in 1988 as part of a real estate transaction. H&A reported in 2016, the well was not destroyed because it could not be located. If encountered during construction, a well destruction permit would need to be obtained from the DEH and abandonment would need to be conducted in accordance with regulatory guidelines.	WCC Data Compilation Report, URS Phase I, H&A Phase I and lls
Former Concrete Sump - 340 Bay Boulevard	340 Bay Boulevard	NA	NA	NA	TCE	Information not readily available	N	Based on the results of a vapor risk evaluation related to TCE in groundwater, the DEH VAP provided a NFA letter that stipulated changes to present use (industrial) may require reevaluation for public health purposes.	WCC Data Compilation Report, URS Phase I, H&A Phase I and lls
Western Drainage Swale - Vacant Properties	West of Vacant Properties	NA	NA	NA	PCBs	UT-01, UT-02	N	PCBs were detected by URS in the drainage swale along the western boundary of the vacant land parcels. PCBs were also present in soil at concentrations up to 7.4 mg/kg. It is unknown whether the impacted soil was characterized and removed.	WCC Data Compilation Report, URS Phase I and IIs, H&A Phase I and lls

TABLE 3
HISTORICAL ENVIRONMENTAL FEATURES - PARCEL C
ROHR, INC.
CHULA VISTA, CALIFORNIA

Areas or Features of Potential Environmental Concern	Location/ Building No.	Map ID (see Figure 4)	Size (gallons)	Status of Feature	Potential Chemicals Associated with Feature/Area	Previous Borings	COCs above GPLs and/or DTSC Comm/Ind SLs in Soil	Comments	References
Pre-Rohr Features									
Former Agricultural Property Use - Vacant Properties	Vacant Properties	NA	NA	NA	OCPs, Metals	BB-01 through -23	N	H&A reported vacant land was previously used for agricultural purposes for citrus and row crops prior to 1950s.	URS Phase I, H&A Phase I

NOTES AND ABBREVIATIONS:

UST - Underground storage tank
AST - Aboveground storage tank
UV - Underground vessel
Y - Yes
N - No
NA - Not applicable
U - Unknown
mg/kg - milligrams per kilogram
bgs - below ground surface
DEH - San Diego Department of Environmental Health
SDRWQCB - San Diego Regional Water Quality Control Board
BTEX - benzene, toluene, ethylbenzene, and xylene
VOCs - volatile organic compounds
Metals -Title 22 metals
TCE - trichloroethene
OCPs - organochlorine pesticides
TPH - total petroleum hydrocarbons
PAH - Polynuclear Aromatic Hydrocarbons
TPHd - TPH diesel range organics
TPHg - TPH gasoline range organics
PCBs - Polychlorinated biphenyls
SVOCs - Semi-volatile organic compounds
As - Arsenic

Map ID is the Rohr tank number or number assigned by Adrian Brown Consultants (1998) or URS Corporation (2013). The Map IDs are noted on Figure 4.

1. Adrian Brown Consultants, Inc. 1998. ASTM Phase I Site Assessment, B.F. Goodrich Aerospace, Foot of H Street, Chula Vista, California. June 4.
2. Woodward-Clyde International-Americas. 1998. Data Compilation and Evaluation Report, Volume I, Rohr, Inc. Chula Vista, California. May 27.
3. URS Corporation. 2004. Report of Additional Site Investigation, Goodrich Aerostructures – Outfall No.1, Chula Vista, California. February 27.
4. URS Corporation. 2005. Report of Corrective Action, Goodrich Aerostructures, Inc. – Outfall No. 1, Chula Vista, California. April 25.
5. URS Corporation. 2013. Phase I Environmental Site Assessment, UTAS - Chula Vista, Chula Vista, California. April 2.
6. URS Corporation. 2015. Supplemental Remedial Investigation Report, Rohr, Inc. – North Campus, 850 Lagoon Drive, Chula Vista, California. May 1.
7. Haley & Aldrich Inc. ASTM Phase I Environmental Site Assessment, Vacant Bay Boulevard Properties, Rohr, Inc., Property IDs 4, 5, 6, 8, 9, 10, and 11, Chula Vista, California. July 21.

FIGURES







MAP SOURCE: ESRI
USGS QUAD: NATIONAL CITY, IMPERIAL BEACH
SITE COORDINATES: 32°38'03.8"N, 117°05'56.9"W

HALEY ALDRICH


ROHR, INC, A PART OF COLLINS AEROSPACE
NORTH CAMPUS CONCEPTUAL MODEL
CHULA VISTA, CALIFORNIA

SITE LOCUS

APPROXIMATE SCALE: 1 IN = 2,000 FT
MAY 2020

FIGURE 1

G:\127827_North Campus\Global\GIS\Maps\2020_05\127827_001_0001_SITE_LOCUS.mxd



LEGEND

- FORMER MILLS/LATHES

CURRENT AND FORMER VESSELS AND VAULTS

- UST (UNDERGROUND STORAGE TANK)
- UV (UNDERGROUND VESSEL)
- AST (ABOVEGROUND STORAGE TANK)
- PAINT BOOTH
- DEGREASER
- VAULT LOCATION

APPROXIMATE LOCATIONS OF FORMER OUTFALLS BY YEAR (SOURCE: ADRIAN BROWN, 1998)

- 1940s
- 1960s
- HISTORICAL SHORELINE, 1944
- HISTORICAL SHORELINE, 1960
- SDG&E 10" FUEL LINE (ABANDONED IN-PLACE)

STORM WATER CONVEYANCE SYSTEM

- CURRENT
- FORMER (PRE-1998)
- 57133016 ASSESSOR'S PARCEL BOUNDARY AND NUMBER
- DEBRIS PILES
- SLUDGE PONDS
- FORMER EXCAVATION AREA
- SITE BOUNDARY

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. ***204*** = STORAGE FEATURE NUMBER. CORRESPONDS TO ADRIAN BROWN, 1998 AND URS, 2013

   (R) REMOVED
   (C) CLOSED
3. AERIAL IMAGERY SOURCE: PICTOMETRY, DECEMBER 2014

0 120 240 360 480

SCALE IN FEET

HALEY ALDRICH


ROHR, INC, A PART OF COLLINS AEROSPACE
NORTH CAMPUS CONCEPTUAL MODEL
CHULA VISTA, CALIFORNIA

HISTORICAL SITE FEATURES

MAY 2020

FIGURE 2

GIS FILE PATH: G:\127827_North Campus\Global\GIS\Maps\2020_05\127827_001_0002_HISTORICAL_FEATURES.mxd — USER: dfm — LAST SAVED: 5/11/2020 10:11:59 AM



LEGEND

BORING LOCATION
- BELOW GPL OR DTSC CRITERIA
- EXCEED GPL CRITERIA
- EXCEED DTSC CRITERIA
- FORMER MILLS/LATHES

CURRENT AND FORMER VESSELS AND VAULTS
- UST (UNDERGROUND STORAGE TANK)
- UV (UNDERGROUND VESSEL)
- AST (ABOVEGROUND STORAGE TANK)
- PAINT BOOTH
- DEGREASER
- VAULT LOCATION

APPROXIMATE LOCATIONS OF FORMER OUTFALLS BY YEAR (SOURCE: ADRIAN BROWN, 1998)
- △ 1940s
- ▽ 1960s
- HISTORICAL SHORELINE, 1944
- HISTORICAL SHORELINE, 1960
- SDG&E 10" FUEL LINE (ABANDONED IN-PLACE)

STORM WATER CONVEYANCE SYSTEM
- CURRENT
- FORMER (PRE-1998)
- ASSESSOR'S PARCEL BOUNDARY AND NUMBER
- DEBRIS PILES
- SLUDGE PONDS
- FORMER EXCAVATION AREA
- SITE BOUNDARY

LOCATION ID	PB-109	
	2017-11	2017-11
	0.5	2.5
Metals		
Cr	-	**1110**
Pb	-	**21100**
Sb	-	**643**
VOCs		
1,1,1-TCA	**9.2**	-
c-1,2-DCE	-	**16**
t-1,2-DCE	-	**1.1**
Toluene	-	**0.48**
VC	-	4.6
PCBs		
PCB-1248	-	21
PCB-1254	-	41

LOCATION ID — SAMPLING DATE — SAMPLE DEPTH (FEET BELOW GROUND SURFACE)

ANALYTE — CONCENTRATION IN MILLIGRAMS PER KILOGRAM (mg/kg) EXCEED COMMERCIAL/INDUSTRIAL DTSC-SL. BOLD INDICATES CONCENTRATION EXCEEDS GPL

NOTES

1. ALL LOCATIONS AND DIMENSIONS ARE APPROXIMATE.
2. ***204*** = STORAGE FEATURE NUMBER. CORRESPONDS TO ADRIAN BROWN, 1998 AND URS, 2013

   (R) REMOVED
   (C) CLOSED

3. CONCENTRATIONS ARE IN MILLIGRAMS PER KILOGRAM (mg/kg)
4. SOIL AT THE SAMPLE LOCATIONS WITH TEXT BOXES CONTAINED THE ANALYTE(S) NOTED AT A CONCENTRATION ABOVE ITS DTSC SL FOR COMMERCIAL/INDUSTRIAL USE AND/OR GROUNDWATER PROTECTION LEVEL (GPL). USEPA REGION 9 RSL USED WHERE NO DTSC SL IS ESTABLISHED.
5. ABBREVIATIONS/ACRONYMS:

   COPCs = CHEMICALS OF POTENTIAL CONCERN
   TCE = TRICHLOROETHENE
   1,1,1-TCA =1,1,1-TRICHLOROETHANE
   1,1-DCA = 1,1-DICHLOROETHANE
   1,1-DCE = 1,1-DICHLOROETHENE
   1,2-DCA = 1,2-DICHLOROETHANE
   c-1,2-DCE = CIS-1,2-DICHLOROETHENE
   t-1,2-DCE = TRANS-1,2-DICHLOROETHENE
   VC = VINYL CHLORIDE
   PCB = POLYCHLORINATED BIPHENYL
   DTSC SLs = DEPARTMENT OF TOXIC SUBTANCE CONTROL SCREENING LEVELS
   USEPA RSLs = U.S. ENVIRONMENTAL PROTECTION AGENCY REGIONAL SCREENING LEVELS

HALEY ALDRICH


ROHR, INC, A PART OF COLLINS AEROSPACE
NORTH CAMPUS CONCEPTUAL MODEL
CHULA VISTA, CALIFORNIA

COPCS IN SOIL ABOVE SCREENING CRITERIA

MAY 2020

FIGURE 3

GIS FILE PATH: G:\127827_North Campus\Global\GIS\Maps\2020_05\127827_001_0003_COPCs_IN_SOIL_SCREEN.mxd — USER: dfm — LAST SAVED: 5/11/2020 1:09:04 PM




ROHR, INC., A COLLINS AEROSPACE COMPANY
NORTH CAMPUS
CHULA VISTA, CALIFORNIA

CONCEPTUAL SITE MODEL

MAY 2020

FIGURE 4

MCELENEY, TERRI Printed: 2/20/2020 11:27 AM Layout: CSM-NORTHCAMPUS
J:\GRAPHICS\12782\12782\12782\12782-016 CSM NORTH CAMPUS 2020-0219.DWG



LEGEND

- ● Complete: Exposure pathway currently exists for that receptor.
- ◑ Potentially Complete: Exposure pathway may exist for future receptor.
- ⊗ Insignificant: All criteria exist for a complete pathway, but data suggest low concentrations, low exposure frequency, potential insignificant risk, or significant pathway in comparison to other pathways.
- ○ Incomplete: One or more criteria for a complete pathway do not exist.


HALEY ALDRICH

ROHR, INC., A PART OF COLLINS AEROSPACE
NORTH CAMPUS
CHULA VISTA, CALIFORNIA

EXPOSURE PATHWAYS
NORTH CAMPUS - PARCEL A

MAY 2020

FIGURE 5



LEGEND

- ● Complete: Exposure pathway currently exists for that receptor.
- ◑ Potentially Complete: Exposure pathway may exist for future receptor.
- ⊗ Insignificant: All criteria exist for a complete pathway, but data suggest low concentrations, low exposure frequency, potential insignificant risk, or significant pathway in comparison to other pathways.
- ○ Incomplete: One or more criteria for a complete pathway do not exist.


HALEY ALDRICH

ROHR, INC., A PART OF COLLINS AEROSPACE
NORTH CAMPUS
CHULA VISTA, CALIFORNIA

EXPOSURE PATHWAYS
NORTH CAMPUS - PARCEL B

MAY 2020

FIGURE 6



LEGEND

- ● Complete: Exposure pathway currently exists for that receptor.
- ◐ Potentially Complete: Exposure pathway may exist for future receptor.
- ⊗ Insignificant: All criteria exist for a complete pathway, but data suggest low concentrations, low exposure frequency, potential insignificant risk, or significant pathway in comparison to other pathways.
- ○ Incomplete: One or more criteria for a complete pathway do not exist.

HALEY ALDRICH

ROHR, INC., A PART OF COLLINS AEROSPACE
NORTH CAMPUS
CHULA VISTA, CALIFORNIA

EXPOSURE PATHWAYS
NORTH CAMPUS - PARCEL C


MAY 2020

FIGURE 7


APPENDIX A

AECOM Figures

A (EAST) — A' (WEST)



A" (WEST)



LEGEND

- SILT CLAY
- SANDY SILT
- FINE SAND SILTY-CLAYEY SAND
- MEDIUM TO COARSE SAND
- SAND AND GRAVEL
- WELL SCREEN INTERVAL


1,400 TCE CONCENTRATIONS IN µg/L

10
0
100
APPROXIMATE GRAPHIC SCALE (FEET)
VERTICAL EXAGGERATION 10:1

LINE OF CROSS-SECTION A-A'/A"
ROHR - CHULA VISTA

AECOM | 50 0 50 100 Ft SCALE: 1"=100' | CHECKED BY: LW | DATE: 01-14-16 | PM: LW | PROJ. NO: 60439239 | FIG. NO: 7

C:\Users\ardian_kuqi\AppData\Local\Microsoft\Windows\Temporary Internet Files\Content.Outlook\PQL1ZEVA\UTC Cross Sections A.dwg Feb 10, 2016 - 5:08pm



LEGEND

- NORTH – SOUTH CAMPUS BOUNDARY
- SILT CLAY
- SANDY SILT
- FINE SAND SILTY–CLAYEY SAND
- MEDIUM TO COARSE SAND
- SAND AND GRAVEL
- SILT (ML) AND CLAY (CL)
- SILTY (SM) AND OR CLAYEY SAND (SC)
- FINE TO COARSE SAND WITH LITTLE FINES (SP), (GM)
- WELL SCREEN INTERVAL
- 1,400 TCE CONCENTRATIONS IN µg/L

10
0
100
APPROXIMATE GRAPHIC SCALE (FEET)
VERTICAL EXAGGERATION 10:1

LINE OF CROSS-SECTION B-B'
ROHR - CHULA VISTA

AECOM | 50 0 50 100 Ft SCALE: 1"=100' | CHECKED BY: LW | DATE: 01-14-16 | PM: LW | PROJ. NO: 60439239 | FIG. NO: 8

M:\Projects\United Technologies Corp\60439239_DataGapAss\400-Technical\413 HazMat\019 CAD\UTC Cross Sections B.dwg Feb 10, 2016 - 8:40am

C-C'

HISTORIC SHORE LINE

NCW-001 | CPT-008 | CPT-007 | NCW-002A,B,C | CPT-006 | CPT-005 | CPT-004 | NCW-003 | CPT-003 | CPT-028 | PMW-102 | PZ-04 | PMW-101 | PZ-03 | SN-005 | PZ-02 | SN-006 | PZ-01 | PMW-110 | CPT-008SC

10 0 −10 −20 −30 −40 −50 −60 −70 −80 −90 −100 −110 −120

NCW-001: <1, ?, ?, 5.4, ?, ?, 41, ?

CPT-008: 3,760, 3,120, 21.4, 2.66

CPT-007: 2,600, 3,060, 3.24, 7.99

NCW-002A,B,C: <1, 100, <1

CPT-006: 6,440, 2,310, 2.09

CPT-005: 5,700, 7,740, 1,060

CPT-004: 15,300, 4,710, 752

NCW-003: 1,000, 4,500, <1

CPT-003: 181, 20.6, 51.7

CPT-028: ?, 2,100, 2,300, ?

PMW-102: ?, NO LOG, ND, ND

PZ-04: NO LOG, 849

PMW-101: 1300, NO LOG, ND

PZ-03: 197, NO LOG

SN-005: NO LOG

PZ-02: 120, NO LOG

SN-006: NO LOG

PZ-01: NO LOG, 13.3

PMW-110: ND, NO LOG, ND, <2, <2, ND

CPT-008SC: ?, ND, 53.9, ?, ?

LEGEND

- SILT CLAY
- SANDY SILT
- FINE SAND SILTY–CLAYEY SAND
- MEDIUM TO COARSE SAND
- SAND AND GRAVEL
- WELL SCREEN INTERVAL

1,400 TCE CONCENTRATIONS IN µg/L

10
0 100
APPROXIMATE GRAPHIC SCALE (FEET)
VERTICAL EXAGGERATION 10:1

LINE OF CROSS-SECTION C-C'
ROHR - CHULA VISTA


AECOM | 50 0 50 100 Ft SCALE: 1"=100' | CHECKED BY: LW | DATE: 01–14–16 | PM: LW | PROJ. NO: 60439239 | FIG. NO: 9

M:\Projects\United Technologies Corp\60439239_DataGapAss\400-Technical\413 HazMat\019 CAD\UTC Cross Sections C.dwg Feb 10, 2016 - 8:25am


Table 2
Monitoring Well Completion Information
Rohr - North Campus

Well No.	Stratigraphic Zone	Date Installed	Well Diameter / Construction	TOC Elevation (feet MSL)	Total Well Depth (feet btoc)	Approx. Screen Interval Depth (feet btoc)	Screen Interval Elevation (feet MSL)
Well Clusters:							
NCW-001A	A	05/23/06	4" PVC	9.73	15.40	5 - 15	4.73 to -5.27
NCW-001B	UB	05/19/06	4" PVC	9.76	50.41	40 - 50	-30.24 to -40.24
NCW-001C	LB	05/18/06	4" PVC	9.37	100.62	90 -100	-80.63 to -90.63
NCW-002A	A	05/31/06	4" PVC	7.93	16.85	7 - 17	0.93 to -9.07
NCW-002B	UB	05/31/06	4" PVC	7.82	40.50	30.5 - 40.5	-22.68 to -32.68
NCW-002C	LB	06/23/06	4" PVC	7.99	74.65	65 - 75	-57.01 to -67.01
NCW-003A	A	05/25/06	4" PVC	8.75	21.07	11 - 21	-2.25 to -12.25
NCW-003B	UB	05/25/06	4" PVC	8.79	43.00	33 - 43	-24.21 to -34.21
NCW-003C	LB	05/24/06	4" PVC	8.55	110.25	100 - 110	-91.45 to -101.45
NCW-004A	A	05/09/06	4" PVC	11.26	15.40	5 - 15	6.26 to -3.74
NCW-004B	UB	05/12/06	4" PVC	11.44	35.20	25 - 35	-13.56 to -23.56
NCW-004C	LB	05/09/06	4" PVC	11.41	111.15	101 - 111	-89.59 to -99.59
NCW-005A	A	05/16/06	4" PVC	12.32	15.40	5 - 15	7.32 to -2.68
NCW-005B	UB	05/17/06	4" PVC	12.28	52.30	42 - 52	-29.72 to -39.72
NCW-005C	LB	05/16/06	4" PVC	12.27	94.60	85 - 95	-72.73 to -82.73
NCW-006A	UB	09/20/12	4" PVC	13.75	40.20	30 - 40	-16.25 to -26.25
NCW-006B	UB	09/20/12	4" PVC	13.61	69.20	59 - 69	-45.39 to -55.39
NCW-006C	LB	09/19/12	4" PVC	13.33	90.66	80 - 90	-66.67 to -76.67
NCW-007A	UB	10/09/12	4" PVC	9.83	40.43	30 - 40	-20.17 to -30.17
NCW-007B	UB	10/09/12	4" PVC	9.87	61.25	51 - 61	-41.13 to -51.13
NCW-007C	LB	10/08/12	4" PVC	9.56	91.01	81 - 91	-71.44 to -81.44
NCW-008A	UB	10/03/12	4" PVC	11.25	26.27	16 - 26	-4.75 to -14.75
NCW-008B	UB	10/03/12	4" PVC	11.04	53.66	43 - 53	-31.96 to -41.96
NCW-008C	LB	10/02/12	4" PVC	11.37	97.87	87.5 - 97.5	-76.13 to -86.13
NCW-009A	UB	09/28/12	4" PVC	11.04	40.98	31 - 41	-19.96 to -29.96
NCW-009B	UB	09/27/12	4" PVC	10.72	68.37	58 - 68	-47.28 to -57.28
NCW-009C	LB	09/26/12	4" PVC	10.82	93.07	83 - 93	-72.18 to -82.18
NCW-013A	A	11/01/12	4" PVC	9.24	20.05	10 - 20	-0.76 to -10.76
NCW-013B	UB	10/31/12	4" PVC	9.32	41.02	31 - 41	-21.68 to -31.68
NCW-013C	LB	10/30/12	4" PVC	9.32	96.98	87 - 97	-77.68 to -87.68
Oiler Shed/North of Marina Area:							
NCW-014A	A	10/04/18	2" PVC	9.87	22.40	12 - 22	-2.13 to -12.13
NCW-014B	UB	10/04/18	2" PVC	10.04	47.71	37.5 - 47.5	-27.46 to -37.46
NCW-015A	A	10/02/18	2" PVC	9.05	29.32	19 - 29	-9.95 to -19.95
NCW-015B	UB	10/02/18	2" PVC	8.61	45.40	35.5 - 45.5	-26.89 to -36.89
NCW-016	UB	09/27/18	2" PVC	13.86	31.14	21 - 31	-7.14 to -17.14
NCW-017	UB	09/26/18	2" PVC	20.70	38.72	28.5 - 38.5	-7.80 to -17.80
NCW-018	UB	09/25/18	2" PVC	15.06	35.33	25 - 35	-9.94 to -19.94
NCW-019	UB	10/01/18	2" PVC	11.13	52.28	42 - 52	-30.87 to -40.87
NCW-020	A	10/05/18	2" PVC	8.78	21.53	11.5 - 21.5	-2.72 to -12.72
Building 61 Area:							
NCW-010	A	09/21/12	4" PVC	11.03	17.55	7.5 - 17.5	3.53 to -6.47
NCW-011	A	09/27/12	4" PVC	10.65	18.45	8 - 18	2.65 to -7.35
NCW-012	A	09/27/12	4" PVC	10.38	18.25	8 - 18	2.38 to -7.62
Building 57 Area:							
MW57-1	A*	05/02/89	2" PVC	8.14	12.64	3 -13	5.14 to -4.86
MW57-2	A*	06/09/92	4" PVC	7.70	7.80	2.5 - 7.5	5.20 to 0.20
MW57-3	A*	06/09/92	4" PVC	7.55	8.50	3.5 - 8.5	4.05 to -0.95
MW57-5	A*	06/09/92	4" PVC	7.60	8.00	3 - 8	4.60 to -0.40
MW57-6	A*	06/09/92	4" PVC	7.89	7.80	2.5 - 7.5	5.39 to 0.39
MW57-7	A*	06/09/92	4" PVC	7.83	7.95	2.5 - 7.5	5.33 to 0.33
Salt Bath (C-70):							
MW1-1	A*	09/21/92	4" PVC	11.53	15.40	5 - 15	6.53 to -3.47
MW1-2	A*	09/21/92	4" PVC	11.51	15.40	5 - 15	6.51 to -3.49
MW1-3	A*	09/17/92	4" PVC	11.56	15.10	5 - 15	6.56 to -3.44
MW1-4	A*	03/12/93	4" PVC	11.77	13.00	8 - 13	3.77 to -1.23
MW1-5	A*	03/15/93	4" PVC	11.44	14.60	10 - 15	1.44 to -3.56
MW1-6	A*	07/10/01	4" PVC	11.73	15.00	5 - 15	6.73 to -3.27
MW1-7	A*	07/10/01	4" PVC	11.62	14.10	4 - 14	7.62 to -2.38

Notes:
*: Wells are screened in a shallower interval than the other Zone A wells on-site.
bgs: below ground surface
btoc: Below top of casing
MSL: Mean sea level datum, NAD83, NAVD88
UB : Upper Zone B
LB : Lower Zone B



Path: G:\GIS\Projects\DCS AMERICAS\Western Region US\UTC Chula Vista\2_2019 Annual Groundwater Monitoring Report (GWMR)\2. Workspace\4. Maps\Figure2_Site plan\v1\06\Zone_A_VOC.mxd, Irina.Nastase, 11/1/2019, 5:50:18 PM



LEGEND

✦	Cluster Well Location
◑	Single Monitoring Well Location
⌖	Shallow Monitoring Well Location
(3.55)	Equivalent fresh water head elevation (in feet mean sea level) Measured on July 24, 2019
i = 0.004 - 0.002	Estimated Hydraulic Gradient in feet per foot (ft/ft)
4.0?	Estimated fresh water head contour in feet above mean sea level; queried where uncertain
	Rohr North Campus Boundary
*	Not used in contour interpretation

EQUIVALENT FRESH WATER HEAD GROUNDWATER CONTOURS ZONE A ROHR - CHULA VISTA

SOURCES:
World Imagery ESRI (aerial);
AECOM (Sample Locations).

AECOM

150 0 150 300 Feet

SCALE: 1" = 300' (1:3,600)
SCALE CORRECT WHEN PRINTED AT 11X17

CREATED BY: IIN	DATE: 11/1/2019	FIG. NO: 3
PM: RS	PROJ. NO: 60586844	

Path: G:\GIS\Projects\DCS AMERICAS\Western Region US\UTC Chula Vista\2_2019 Annual Groundwater Monitoring Report (GWMR)\2. Workspace\4. Maps\Figure3_Zone A\v106\20191101_Zone_A_Groundwater.mxd, Irina.Nastase, 11/1/2019, 3:12:44 PM

Path: G:\GIS\Projects\DCS AMERICAS\Western Region USUTC Chula Vista\2_2019 Annual Groundwater Monitoring Report (GWMR)\2. Workspace\4. Maps\Figure4_Zone UBlv.106\20191017_Upper_Zone_B_Groundwater.mxd, Irina.Nastase, 11/1/2019, 3:22:07 PM

LAGOON DRIVE

MARINA PARKWAY

G STREET

QUAY AVENUE

BAYSIDE WAY

SANDPIPER WAY

MARINA PARKWAY

NCW-014B (3.22)

NCW-013B (3.20)

NCW-015B (3.30)

NCW-002B (3.19)

NCW-003B (3.02)

NCW-001B (3.28)

PMW-102(UB)R

NCW-004B (3.29)

NCW-005B (3.30)

NCW-016 (3.18)

NCW-017 (3.18)

NCW-006A (3.38)

NCW-006B (3.09)

NCW-018 (3.28)

NCW-019 (3.55)

NCW-009B (5.19)

NCW-009A (3.29)

NCW-008A (2.99)

NCW-008B (3.89)

NCW-007A (4.25)

NCW-007B (3.43)

3.5

4.0

?

i = 0.003

LEGEND

- Cluster Well Location
- Single Monitoring Well Location
- South Campus Well
- (3.55) Equivalent fresh water head elevation (in feet mean sea level) Measured on July 24, 2019
- i = 0.003 Estimated hydraulic gradient in feet per foot (ft/ft)
- 4.0? Estimated fresh water head contour in feet above mean sea level; queried where uncertain
- Rohr North Campus Boundary

EQUIVALENT FRESH WATER HEAD CONTOURS
ZONE UB
ROHR - CHULA VISTA

SOURCES:
World Imagery ESRI (aerial);
AECOM (Sample Locations).

AECOM

150 0 150 300 Feet

SCALE: 1" = 300' (1:3,600)
SCALE CORRECT WHEN PRINTED AT 11X17

CREATED BY: IIN	DATE: 11/1/2019	FIG. NO:
PM: RS	PROJ. NO: 60586844	4

NCW-013C
(3.31)

NCW-002C
(3.39)

NCW-003C
(4.30)

NCW-001C
(3.50)

NCW-005C
(3.77)

LAGOON DRIVE

MARINA PARKWAY

G STREET

MARINA PARKWAY

? 4.0

NCW-004C
(3.99)

i = 0.001 - 0.004

NCW-006C
(4.62)

SANDPIPER WAY

? 5.0

QUAY AVENUE

NCW-007C
(5.23)

BAYSIDE WAY

NCW-008C
(5.54)

? 6.0

? 7.0

NCW-009C
(7.45)

LEGEND

	Cluster Well Location
i = 0.001 - 0.004	Estimated Hydraulic Gradient in feet per foot (ft/ft)
(3.77)	Equivalent fresh water head elevation (in feet mean sea level) Measured on July 24, 2019
4.0?	Estimated fresh water head contour in feet above mean sea level; queried where uncertain
	Rohr North Campus Boundary

SOURCES:
World Imagery ESRI (aerial);
AECOM (Sample Locations).

EQUIVALENT FRESH WATER HEAD CONTOURS
ZONE LB
ROHR - CHULA VISTA

AECOM

150 0 150 300 Feet

SCALE: 1" = 300' (1:3,600)
SCALE CORRECT WHEN PRINTED AT 11X17

CREATED BY: IIN	DATE: 11/1/2019	FIG. NO:
PM: RS	PROJ. NO: 60586844	5

Path: G:\GIS\Projects\DCS AMERICAS\Western Region US\UTC Chula Vista\2_2019 Annual Groundwater Monitoring Report (GWMR)\2. Workspace\4. Maps\Figure5_Zone LB\v106\20191017_Lower_Zone_B_Groundwatermxd, Irina.Nastase, 11/1/2019, 3:27:28 PM

LEGEND

- Parcel H-3 Boundary
- Rohr Property Boundary
- South Campus Property Boundary
- TCE Concentration Contour (µg/L)*

2019 Additional Groundwater Investigation

- Hydropunch Boring — *Year: TCE Concentration @ Depth*

2018 Western Property Boundary/Oiler Shed/North of Marina Investigations

- Groundwater Monitoring Well — *(Screen Depth): Year: TCE Concentration*
- Hydropunch Boring Locations — *Year: TCE Concentration @ Depth*

2015 AECOM Investigation

- CPT-MIP Boring Locations — *(Depth) Year: TCE Concentration*

2015 Tetra Tech Investigation

- Tetra Tech Boring — *Year: TCE Concentration @ Depth*

2015 Haley & Aldrich Hydropunch Boring Locations

- Hydropunch Boring — *Year: TCE Concentration @ Depth*

Former Investigation Data Points

- UT — *(Depth) Year: TCE Concentration*
- CPT — *(Depth) Year: TCE Concentration*
- Boring; Well — *(Screen Depth): Year: TCE Concentration*
- Hydropunch — *(Depth) Year: TCE Concentration*

*NOTES:

Trichloroethene in micrograms per liter (µg/L); Depth in feet below ground surface.
Concentrations shown as ND or < are not detect for TCE
Newer data and data from wells were weighted more for contouring
Not all data shown were used for contouring
*For boring H3-DP14 - Data appears anomalous and will be confirmed through additional sampling.

SOURCES:
Monitoring Wells, CPT, Hydropunch, CPT/MIP Boring Locations (URS/AECOM 1999-2019); South Campus Borings, Hydropunch Borings (Haley & Aldrich 2015); Boring Locations (Tetra Tech 2015); Aerial Imagery (SANDAG 2017).

COMPOSITE TCE ISOCONCENTRATION CONTOURS IN GROUNDWATER - ZONE A ROHR - CHULA VISTA

AECOM

150 0 150 300 Feet

SCALE: 1" = 150' (1:1,800)
SCALE CORRECT WHEN PRINTED AT 22X34

CREATED BY: DA	DATE: 9/30/2019	FIG. NO: 10
PM: RS	PROJ. NO: 60611775.01	

Path: P:_GMM\60606790_UTC_Buhr\06-CAD-GIS\mxd\2019\H3 Report\Fig_11_ZoneA_TCE_med_dated.aerial.mxd, 9/30/2019, 11:57:40 AM

LEGEND

- Parcel H-3 Boundary
- North Campus Property Boundary
- South Campus Property Boundary
- TCE Concentration Contour (µg/L)*

2019 Additional Groundwater Investigation

- Hydropunch Boring — *Year: TCE Concentration @ Depth*

2018 Western Property Boundary/Oiler Shed/North of Marina Investigations

- Groundwater Monitoring Well — *(Screen Depth): Year: TCE Concentration*
- Hydropunch Boring Locations — *Year: TCE Concentration @ Depth*

2015 AECOM Investigation

- CPT-MIP Boring Locations — *(Depth) Year: TCE Concentration*

2015 Haley & Aldrich Hydropunch Boring Locations

- Hydropunch Boring — *Year: TCE Concentration @ Depth*

Former Investigation Data Points

- CPT — *(Depth) Year: TCE Concentration*
- Boring; Well — *(Screen Depth): Year: TCE Concentration*
- Hydropunch — *(Depth) Year: TCE Concentration*

*NOTES:

Trichloroethene in micrograms per liter (µg/L); Depth in feet below ground surface.

Concentrations shown as ND or < are not detect for TCE

Newer data and data from wells were weighted more for contouring

Not all data shown were used for contouring

SOURCES:
Monitoring Wells, CPT, Hydropunch, CPT/MIP Boring Locations (URS/AECOM 1999-2019); South Campus Borings, Hydropunch Borings (Haley & Aldrich 2015); Aerial Imagery (SANDAG 2017).

COMPOSITE TCE ISOCONCENTRATION CONTOURS IN GROUNDWATER - ZONE UB
ROHR - CHULA VISTA

AECOM

150 0 150 300 Feet

SCALE: 1" = 150' (1:1,800)
SCALE CORRECT WHEN PRINTED AT 22X34

CREATED BY: DA	DATE: 9/10/2019	FIG. NO: 11
PM: RS	PROJ. NO: 60611775.01	

Path: P:\...\60606060790_UTC_Bulk\GW-CEQ\GIS\ZUB\GIS\mxd\2019\ER Report\Fig_11_ZoneUB_TCE_med_dateEarlierBias_9102019_2:31:32 PM

CPT-016(70)
2002:ND

CPT-015
2002:52.5 @ 78'
ND @ 90.5'

CPT-014(88)
2002:ND

CPT-013C (88-98)
2017: 17

CPT-013sc (67)
1999: ND

CPT-039 (70)
2015: 10

CPT-040 (66)
2015: 10

CPT-038 (62)
2015: 21

CPT-020(105)
2004:ND

NCW-013C(88-89)
2019: 5.4

CPT-009 (92)
2002:ND

CPT-010 (96)
2002: 94.8

CPT-011(100)
2002: 2.94

PMW-104 (LB)
2013: 11

CPT-009sc (95)
1999: ND

CPT-012 (88)
2002: 5.7

CPT-007sc (73)
1999:10.6

HP22 (58.5)
2018: 2100

HP-56
2019: 15,000@59'
1900@73'

HP23 (58.5)
2018: 1800

NCW-002 (65-67)
2016: <1.0

CPT-012sc (79)
1999: 117

CPT-007
2002: 3.24 @ 85'
7.99 @ 100'

CPT-008
2002: 21.4 @ 85'
2.66 @ 100'

CPT-006 (83)
2002: 2.09

CPT-004 (82)
2002: 752

HP9 (57.5)
2018: 25

NCW-003C (100-110)
2016: <10

CPT-003 (90)
2002: 51.7

CPT-005 (75)
2002: 1060

HP20 (59.5)
2018: 160

PMW-101(LB)
2018: 3.3

PMW-110(LB)
2018: 0.554J

CPT-008sc (76)
1999: ND

DP-416
2015: 110 @ 65'

CPT-019 (82)
2004: 2.4

HP-65
2019: 170 @65'

HP-55
2019: 4800@81'

NCW-001C (101-111)
2019: 0.37 J

HP-62
2019: 718 @64'

CPT-027 (56)
2015: 2,300

CPT-011sc (64)
1999: 249

CPT-002 (99)
2002: 7.56

NCW-005C (85-95)
2019: <0.24

HP-66
2019: 260@84'

HP-64
2019: 1.3@66'

HP-50
2019: 170@81'

CPT-001 (100)
2002: 4.24

NCW-004C (100-111)
2016: <0.24

DP-465
2015: 290 @ 65'
230 @ 75'

HP-54
2019: 9.91@74'
6.4@85.2'

HP-67
2019: 0.669 J @81'

NCW-006C (80-90)
2018: 0.64

HP-41
2019: 4.5@72.5'

HP-68
2019: 1.46@84'

HP-69
2019: <1@79'

CPT-025 (93)
2004: ND

NCW-009C (83-93)
2017: 2.6

NCW-008C (87.5-97.5)
2017: <1.0

NCW-007C (81-91)
2017: <1.0

LEGEND

- Parcel H-3 Boundary
- North Campus Property Boundary
- South Campus Property Boundary
- TCE Concentration Contour (µg/L)*

ProposedCPTMIP - UB

2019 Additional Groundwater Investigation

- Hydropunch Boring *Year: TCE Concentration @ Depth*

2018 Western Property Boundary/Oiler Shed/North of Marina Investigations

- Hydropunch Boring Locations *Year: TCE Concentration @ Depth*

2015 AECOM Investigation

- CPT-MIP Boring Locations *(Depth) Year: TCE Concentration*

Former Investigation Data Points

- CPT *(Depth) Year: TCE Concentration*
- Boring; Well *(Screen Depth): Year: TCE Concentration*

*NOTES:

Trichloroethene in micrograms per liter (µg/L); Depth in feet below ground surface.

Concentrations shown as ND or < are not detect for TCE

Newer data and data from wells were weighted more for contouring

Not all data shown were used for contouring

SOURCES:
Monitoring Wells, CPT, Hydropunch, CPT/MIP Boring Locations (URS/AECOM 1999-2019); South Campus Borings, Hydropunch Borings (Haley & Aldrich 2015); Aerial Imagery (SANDAG 2017).

COMPOSITE TCE ISOCONCENTRATION CONTOURS IN GROUNDWATER - ZONE LB ROHR - CHULA VISTA

AECOM

150 0 150 300 Feet

SCALE: 1" = 150' (1:1,800)
SCALE CORRECT WHEN PRINTED AT 22X34

CREATED BY: DA | DATE: 9/10/2019

PM: RS | PROJ. NO: 60611775.01

FIG. NO: 12

Path: P:\...\60606060706_UTC_Rohr\06-CAD-GIS\mxd\2019\Q3 Report\Fig_13_Zone1b_TCE.mxd, dated/Last Mod: 9/10/2019, 2:40:20 PM

NCW-011
2019: <0.5

NCW-012
2018: <0.5

NCW-001A
2019: <0.5

NCW-004A
2019: <0.5

NCW-002A
2019: 29

NCW-003A
2019: 7.9

NCW-005A
2019: <0.5

NCW-013A
2019: 1.4

NCW-014A
2019: 1.700

NCW-015A
2019: 840

NCW-020A
2019: 9.8

MW57-2
2019: 210

MW57-6
2019: 12

HP-56
2019: 7.3@23'

HP23 (17')
2018: 660

HP-57
2019:3,500@24'

HP-61
2019: 50@16'

HP24 (24.5')
2018: 45

HP25 (24.5')
2018: 39

HP-62
2019:1.10@8'

HP-65
2019:0.461@8'

HP-55
2019:<1@8'

HP-63
2019:2.54@10'

HP-51*
2019: < 0.50@19'

HP-48*
2019: 0.218@15.5'

HP-67
2019:0.539@14.5'

HP-68*
2019: 1.39@15.5'

HP-46*
2019: 0.275@29'

HP-69*
2019: <0.4@16'

HP-45
2019:<4@18'

HP-41
2019:4.14@8.5'

HP-43
2019:0.230@8'

PMW-101(A)
2018: 0.485

PMW-117(A)
2018: 0.182

PMW-125(A)
2018: 0.509

1,000

100

10

1

LEGEND

- Parcel H-3 Boundary
- North Campus Property Boundary
- South Campus Property Boundary
- 1,4 Dioxane Concentration Contour (µg/L)*

2019 Additional Groundwater Investigation

- Hydropunch Boring — *Year: 1,4 Dioxane Concentration @ Depth*

2018 Western Property Boundary/Oiler Shed/North of Marina Investigations

- Groundwater Monitoring Well — *Year: 1,4 Dioxane Concentration*
- Hydropunch Boring Locations — *Year: 1,4 Dioxane Concentration*

Former Investigation Data Points

- Boring; Well — *Year: 1,4 Dioxane Concentration*

NOTES:

1,4 Dioxane in micrograms per liter (µg/L); Depth in feet below ground surface.

Concentrations shown as ND or < are not detect for 1,4 Dioxane

Newer data and data from wells were weighted more for contouring

Not all data shown were used for contouring

*Samples collected in area re-graded in 2018 . Elevation is 4 - 15 ft above original ground surface .

SOURCES:
Monitoring Wells, CPT, Hydropunch, CPT/MIP Boring Locations (URS/AECOM 1999-2019); South Campus Borings, Hydropunch Borings (Haley & Aldrich 2015); Aerial Imagery (SANDAG 2017).

1,4-DIOXANE ISOCONCENTRATION CONTOURS
ZONE A
ROHR - CHULA VISTA

AECOM

150 0 150 300 Feet

SCALE: 1" = 150' (1:1,800)
SCALE CORRECT WHEN PRINTED AT 22X34

CREATED BY: DA	DATE: 3/5/2020	FIG. NO:
PM: RS	PROJ. NO: 60611775.01	13

Path: P:\...\60606090\06_GTC_Rohr\06-CAD-GIS\06-GIS\mxd\2019\H3 Report\Fig_1A_Zone1_1_4_Dioxane_detailLowRes_5/5/2020, 6:54:39 PM

NCW-014B
2019: 7.3

NCW-013B
2019: ND

NCW-015B
2019: 100

HP22 (43.5')
2018: 12

HP23 (40.5')
2018: 16

HP-56
2019: 4.9@37'

HP-57
2019:8.4@39'

HP-61
2019: <0.5@39'

NCW-002B
2019: ND

HP21 (27.5')
2018: 1,000

HP25 (44.5')
2018: 8

HP24 (36')
2018: 36

HP17 (35.5')
2018: 33

NCW-001B
2019: ND

NCW-003B
2019: 1.7

PMW-103(UB)
2018: 1.84

PMW-102(UB)R
2018: 49.9

PMW-101(UB)
2018: 0.728

HP-62
2019: 590@24'
1,100@34'
580@49'

HP-65
2019: 3.08@24'
10@43'

HP-55
2019: 8.52@26'
0.958@49'

NCW-016
2019: 33

PMW-122(UB)
2018: 1.7

PMW-126(UB)
2018: 2.1

NCW-005B
2019: 2.3

NCW-004B
2019: 160

HP-63
2019: 10@28'
1.4@44'
<0.5@53'

HP-51
2019: 12@32.5'

NCW-017
2019: 25

PMW-121(UB)
2018: 43.2

HP-49
2019: 3.8@54'

HP-53
2019: 2.9@32'

HP-54
2019: 55.5@30'
22.7@53'
21.5@63'

HP-48
2019: 0.623@37'
0.421@54'

NCW-018
2019: ND

HP-67
2019: 0.476@30'
<0.47@59'

HP-47
2019: 8.1@51.5'

HP-41
2019: 2.81@26'
0.624@46'
4.13@54'

NCW-006A
2019: 3.0

NCW-006B
2019: 2.4

NCW-019
2019: 4.5

HP-68
2019: 1.40@48'
<0.4@69'

HP-46
2019: 0.320@43'
0.328@51'

HP-69
2019: <0.4@46'
<0.4@69'

HP-45
2019: <4@25'
<4@50'
<4@65'

NCW-008A
2019: ND

NCW-008B
2019: ND

NCW-009A
2019: ND

NCW-007A
2019: ND

LEGEND

- Parcel H-3 Boundary
- North Campus Property Boundary
- South Campus Property Boundary
- 1,4 Dioxane Concentration Contour (µg/L)*

2019 Additional Groundwater Investigation

- Hydropunch Boring *Year: 1,4 Dioxane Concentration @ Depth*

2018 Western Property Boundary/Oiler Shed/North of Marina Investigations

- Groundwater Monitoring Well *Year: 1,4 Dioxane Concentration*
- Hydropunch Boring Locations *Year: 1,4 Dioxane Concentration*

Former Investigation Data Points

- Boring; Well *Year: 1,4 Dioxane Concentration*

*NOTES:

1,4 Dioxane in micrograms per liter (µg/L); Depth in feet below ground surface.

Concentrations shown as ND or < are not detect for 1,4 Dioxane

Newer data and data from wells were weighted more for contouring

Not all data shown were used for contouring

SOURCES:
Monitoring Wells, CPT, Hydropunch, CPT/MIP Boring Locations (URS/AECOM 1999-2019); South Campus Borings, Hydropunch Borings (Haley & Aldrich 2015); Aerial Imagery (SANDAG 2017).

1,4-DIOXANE ISOCONCENTRATION CONTOURS
ZONE UB
ROHR - CHULA VISTA

AECOM

150 0 150 300 Feet

SCALE: 1" = 150' (1:1,800)
SCALE CORRECT WHEN PRINTED AT 22X34

CREATED BY: DA	DATE: 3/5/2020	FIG. NO: 14
PM: RS	PROJ. NO: 60611775.01	

Path: P:_GWM\WWW\Chula_Vista\CAD+GIS\GIS\ArcGIS\Chula_Vista_Mapping_Project.gdb\Figure_15_Zone_UB_1_4_Dioxane_Isocontours_2019

Plotted: Thursday, March 05, 2020 6:38:36 PM

HP-56
2019: 1.1@59'

HP22 (58.5)
2018: 4.7

HP-57
2019:1.4@56'

PMW-110(LB)
2018: 0.365

NCW-001C
2019: <0.5

HP-62
2019:13.7@64'

HP-65
2019: 0.298@65'

HP-55
2019: 3.59@81'

NCW-005C
2019: <0.5

NCW-004C
2019: <0.5

HP-54
2019: 0.558@82.5'

HP-48
2019: 0.544@72'

HP-67
2019: ND <0.472@81'

NCW-006C
2019: <0.5

HP-46
2019: 1.42@70'

HP-68
2019: <0.4@84'

HP-69
2019: <0.4@79'

LEGEND

- Parcel H-3 Boundary
- North Campus Property Boundary
- South Campus Property Boundary
- 1,4 Dioxane Concentration Contour (µg/L)*

2019 Additional Groundwater Investigation

- Hydropunch Boring *Year: 1,4 Dioxane Concentration @ Depth*

2018 Western Property Boundary/Oiler Shed/North of Marina Investigations

- Hydropunch Boring Locations *Year: 1,4 Dioxane Concentration*

Former Investigation Data Points

- Boring; Well *Year: 1,4 Dioxane Concentration*

*NOTES:

1,4 Dioxane in micrograms per liter (µg/L); Depth in feet below ground surface.

Concentrations shown as ND or < are not detect for 1,4 Dioxane

Newer data and data from wells were weighted more for contouring

Not all data shown were used for contouring

SOURCES:
Monitoring Wells, CPT, Hydropunch, CPT/MIP Boring Locations (URS/AECOM 1999-2019); South Campus Borings, Hydropunch Borings (Haley & Aldrich 2015); Aerial Imagery (SANDAG 2017).

1,4-DIOXANE ISOCONCENTRATION CONTOURS
ZONE LB
ROHR - CHULA VISTA

AECOM

150 0 150 300 Feet

SCALE: 1" = 150' (1:1,800)
SCALE CORRECT WHEN PRINTED AT 22X34

CREATED BY: DA | DATE: 3/2/2020

PM: RS | PROJ. NO: 60611775.01

FIG. NO: **15**

Path: P:_GMA\60606790_UTC_Buhr\900-CAD-GIS\920 GIS\mxd\2019\H3 Report\Fig_06_ZoneLB_1_4_Dioxane_dandEvanWare_3/2/2020, 11:23:20 AM

APPENDIX B

Groundwater Protection Levels


TABLE 10

GROUNDWATER PROTECTION LEVELS
FORMER SOUTH CAMPUS, NORTH OF EXCHANGE PARCEL
CHULA VISTA, CA

Groundwater Protection Level (GPL)	
Chemical	**All Areas**
VOCs	**(µg/kg)**
1,1,1-Trichloroethane	1,700
1,1,2-Trichloroethane	40
1,1-Dichloroethane	560
1,1-Dichloroethene	71
1,2-Dichlorobenzene	28,000
1,2-Dichloroethane	2.8
1,4-Dichlorobenzene	230
Benzene	19
Chlorobenzene	2,000
cis-1,2-Dichloroethene	4,900
Ethylbenzene	7,700
Methylene chloride	19
Tetrachloroethene	2,100
Toluene	440
trans-1,2-Dichloroethene	170
Trichloroethene	27,000
Trifluorotrichloroethane (Freon 113)	6,400
Vinyl chloride	13,000
Xylenes	6,000
SVOCs	**(mg/kg)**
Benzo(a)pyrene	14
bis(2-Ethylhexyl)phthalate	57
PCBs (Total Aroclors) [e]	130
PETROLEUM MIXTURES	**(mg/kg)**
Gasoline (C6-C8)	2,900
Diesel (C9-C16)	5,400
Oil (C17-C32)	7,300
INORGANICS	**(mg/kg)**
Antimony	7.84
Arsenic	24.3
Barium	43,000
Cadmium	970
Chromium	660
Chromium VI (Hexavalent)	30
Copper	5,600
Lead	232
Mercury	2.1
Nickel	3,400

NOTES:

ug/kg = micrograms per kilogram
mg/kg = milligrams per kilogram
VOC = volatile organic compound
SVOC = semi-volatile organic compound
PCB = polychlorinated biphenyls



NOTE:
100 SERIES TANK NUMBERS REFER TO TANKS WITHOUT ROHR I.D.

STATUS
Active tanks refer to tanks that are currently in use by BF Goodrich and are registered with the State of California.
Inactive tanks are vessels that are no longer used by BF Goodrich but are still on site and may or may not be registered with the state depending on the date the vessel became inactive.
Closed tanks are vessels that are either closed in place or removed with the states knowledge.
Former tanks are vessels that have been abandoned in place, removed before notification was required, or tanks whose status is unknown.
Removed tanks refer to AST's removed from the site that do not required closure from the state.

SITE MAP LEGEND

LINE FONTS
- RETAINING WALLS, CONCRETE BLOCK WALLS BUILDING & SHED MAIN EXTERIOR WALLS
- DRAIN LINES, ROADS, CURBS, PATIO COVERS, DITCHES
- FENCES, GATES
- RAILROAD TRACKS
- 1940'S SHORELINE

SYMBOLS
- SDG&E POWER TOWER

TANK SYMBOLS & ABBREVIATIONS
- UV (UNDERGROUND VESSEL)
- AST
- PAINT BOOTH

(F) FORMER
(A) ACTIVE
(C) CLOSED
(I) INACTIVE
(R) REMOVED

Rohr Tank No.	Assigned ID No.	Bldg No.	Size	Contents	Type	Status
2	N/A	343	50	diesel fuel	drum	closed
5	N/A	1	10000	oil and coolant	uv	closed
6a	N/A	1	550	coolant	uv	closed
6b	N/A	1	90	oil	uv	active
7a	N/A	5	550	jet A fuel	uv	closed
7b	N/A	salvage	105	machining coolant	uv	closed
8	N/A	3	3000	maskant	uv	closed
9	N/A	pretreatment area	1500	processing water	uv	active
10	N/A	pretreatment area	40000	wastewater	uv	active
11	N/A	3	600	sulfuric acid	uv	inactive
12	N/A	30	22	wastewater	uv	active
13	N/A	343	100	diesel fuel	uv	closed
14	N/A	61	129	wastewater	uv	active
16	N/A	3	750	wastewater	uv	active
17	N/A	3	345	wastewater	uv	inactive
18	N/A	19	4000	fixer/developer	uv	closed
19	N/A	30	121	wastewater	uv	closed
20	N/A	30	62	wastewater	paint booth	active
22	N/A	airflow	4000	wastewater	uv	closed
N/A	101	5	5000	diesel fuel	uv	former
N/A	102	57	10000	diesel fuel	uv	closed
N/A	103	57	10000	tce	ast	former
N/A	104	57	6500	MEK	ast	former
N/A	105	57	5275	diesel fuel	ast	former
N/A	106	57	102000	LPG	ast farm (4 tanks)	active
N/A	107	1	3000	lt hydraulic oil	ast	former
N/A	108	1	3000	hv to med hydraulic oil	ast	former
N/A	109	48	1100	mapp gas	ast	former
N/A	110	3	5000	diesel fuel	uv	former
N/A	111	3	5000	diesel fuel	uv	former
N/A	112	449	12750	LPG	ast	former
N/A	113	salvage	1000	diesel fuel	ast	former
N/A	114	salvage	550	diesel fuel	ast	former
N/A	115	25	10000	gasoline	uv	closed
N/A	116	25	10000	gasoline	uv	closed
N/A	117	443	580000ft3	argon	ast	former
N/A	118	45	88000ft3	argon	ast	former
N/A	119	1	unk	hydraulic oil	ast	former
N/A	120	pretreatment area	2800	waste oil/coolant	ast	active
N/A	121	pretreatment area	5000	waste oil/coolant	ast	active
N/A	122	pretreatment area	5000	waste oil/coolant	ast	active
N/A	123	pretreatment area	5000	waste coolant	ast	active
N/A	124	Bldg 1, Oilers shed	4000	Mobil 25 DTE	ast	active
N/A	125	Bldg 1, Oilers shed	4000	Mobil 25 DTE	ast	active
N/A	126	Bldg 1, Oilers shed	1000	Lubricant coolant AC	ast	active
N/A	127	45	12000	diesel fuel	uv	former
N/A	128	45	12000	diesel fuel	uv	former
N/A	129	45	12000	diesel fuel	uv	former
N/A	130	45	550	waste oil	uv	former
N/A	131	6	500	wastewater	uv	active
N/A	132	3	8000	water	ast	active
N/A	133	3	6000	water	ast	active
N/A	134	3	5000	liquid argon	ast	active
N/A	135	49	unk	wastewater	uv	active
N/A	136	356	6000	MEK	ast	inactive
N/A	137	60	5000	diesel fuel	ast	inactive
N/A	138	60	4000	diesel fuel	ast	inactive
N/A	139	5	unk	wastewater	paint booth	inactive
N/A	140	327	750	wastewater	ast	active
N/A	141	45	unk	wastewater	uv	active
N/A	140	327	750	wastewater	ast	active
N/A	141	45	unk	wastewater	uv	active
N/A	142	45	unk	wastewater	uv	active
N/A	143	45	unk	wastewater	uv	active
N/A	144	341	unk	wastewater	uv	active
N/A	145	100	unk	diesel fuel	uv	closed
N/A	146	100	unk	diesel fuel	uv	closed
N/A	147	100	unk	waste oil	uv	closed
N/A	148	100	unk	waste solvent	uv	closed
N/A	149	3	unk	1,1,1-TCA	uv	inactive
N/A	150	47	212	washwater	paint booth	inactive
N/A	151	3	50	1,1,1-TCA	ast	removed
N/A	152	45	50	1,1,1-TCA	ast	removed
N/A	153	911	50	1,1,1-TCA	ast	removed
N/A	154	30	50	1,1,1-TCA	ast	removed
N/A	155	45	50	1,1,1-TCA	ast	removed
N/A	156	45	unk	wastewater	paint booth	active
N/A	157	45	unk	wastewater	paint booth	active
N/A	158	45	unk	wastewater	paint booth	active
N/A	159	45	unk	wastewater	paint booth	active
N/A	160	45	unk	wastewater	paint booth	active
N/A	161	29	unk	wastewater	paint booth	active
N/A	162	61	unk	wastewater	paint booth	active
N/A	163	61	unk	wastewater	paint booth	active
N/A	164	1	unk	wastewater	paint booth	active
N/A	165	1	unk	wastewater	paint booth	inactive
1(1-C70R)	N/A	1	3600	city water	uv	active
15(15-C70Q)	N/A	1	3600	city water	uv	active
3(3-C70SB)	N/A	1	3600	aluminum salt bath conditioner	uv	active
3-06383	N/A	45	4314	wash water	paint booth	active
3-07824	N/A	1	unk	1,1,1-TCA	uv	exempt
3-09598	N/A	29	1345	machining coolant	uv	active
3-09978	N/A	1	unk	1,1,1-TCA	uv	exempt
3-11893	N/A	30	3810	water	paint booth	active
3-13888	N/A	1	unk	1,1,1-TCA	uv	inactive
3-14873	N/A	45	unk	water	paint booth	active
3-14874	N/A	45	unk	water	paint booth	inactive
3-15615	N/A	25	6000	unleaded gas	uv	active
3-15616	N/A	25	6000	unleaded gas	uv	active
3-15617	N/A	25	6000	diesel fuel	uv	active
3-17707	N/A	30	1400	aluminum salt bath conditioner	uv	active
3-17919	N/A	45	6720	dgs kolene	uv	active
4(4-C70S)	N/A	1	1681	cooling water	uv	inactive

REVISIONS			
REV	DESCRIPTION	DATE	APPROVED
1			

200 0 100 200 400
SCALE IN FEET

VESSEL LOCATIONS

AdrianBrown
Groundwater Hydrology • Geochemistry • Remediation
333 W. Hampden Avenue
Denver, Colorado 80223-1801
303.698.9060
Innovative Environmental Solutions

B.F.GOODRICH AEROSPACE

DESIGNED	KTW	DATE: 05/25/98	FILE:\SERVER1\KWRIGHT\PROJECTS\1506A\05-98\BF-UST.DWG; 05/25/98
DRAWN	KTW/VS	DATE: 05/25/98	
CHECKED		DATE:	


PLATE NUMBER
9

Well Finder
CalGEM GIS

More Info | Help | ©

- Well Status and Well Type Filter
- Search
- Zoom to Field
- Measurement
- Layers

- [ ] Notice and Permit
- [x] Well
  - [x] Well
  - [x] Geothermal Well
- [ ] Facility
  - [x] Tank
  - [x] Pit/Sump
  - [x] Setting
  - [x] Facility Boundary (non-wellstar)
- [ ] Underground Gas Storage
- [ ] Well Stimulation
- [ ] TR26 Onshore Seep Count
- [x] Oil/Gas Field
- [x] CalGEM District
- [ ] Public Land Survey System
- [ ] City
- [ ] Legislative Districts
- [ ] County
- [ ] California Geologic Map



Ernie Dronenburg , County Assessor

Property Address: **FOOT OF G ST CHULA VISTA CA 00000**

General Information

Parcel # (APN):	**571-330-24-00** Open Map
Owner:	See Full Detail
Mailing Address:	**8 FARM SPRINGS RD MS #8FS2 FARMINGTON CT 06032**
Legal Description:	**TR 166 QSEC 171*DOC99-845735&845741 IN**
Use Type:	**PARKING LOT**
Tax Rate Area:	**001-082**
Value Notice:	Open



Full Detail $14.95 Add to Cart The Full Property Detail includes everything displayed here plus completed information for those fields where "See Full Detail" is shown. If a field is empty on this page, no data is available, and the field will also be empty on the Full Property Detail.

Assessment

Total Value:	**$3,237,202**	Year Assd:	**2020**
Land:	**$3,203,425**	Zoning:	See Full Detail
Structures:	**$33,777**	Use Code:	See Full Detail
Other:		Census Tract:	
% Improved:	See Full Detail	Price/SqFt:	
Exempt Amt:			
HO Exempt:	**N**		

Sale History

	Sale 1	Sale 2	Sale 3	Transfer
Document Date:				See Full Detail
Document Number:				See Full Detail
Document Type:				
Transfer Amount:				
Seller (Grantor):				

Property Characteristics

Bedrooms:		Fireplace:		Units:	See Full Detail
Baths (Full):		A/C:		Stories:	
Baths (Half):		Heating:		Quality:	
Total Rooms:		Pool:		Building Class:	
Bldg/Liv Area:	**770**	Park Type:		Condition:	
Lot Acres:	**3.960**	Spaces:		Site Influence:	
Lot SqFt:	**172,497**	Garage SqFt:		Timber Preserve:	
Year Built:				Ag Preserve:	
Effective Year:					

**The information provided here is deemed reliable, but is not guaranteed.

Additional reports on this property

© 2021 **ParcelQuest** | Toll Free 1-844-893-7216 | Privacy Policy | Refund Policy | Disclaimer | Usage Limits

Ernie Dronenburg , County Assessor

Property Address: **TIDELANDS AVE CHULA VISTA CA 00000**

General Information

Parcel # (APN):	**571-330-27-00** Open Map
Owner:	See Full Detail
Mailing Address:	**8 FARM SPRINGS RD MS #8FS2 FARMINGTON CT 06032**
Legal Description:	**TIDELANDS SAN DIEGO BAY*DOC99-845733&845739 IN**
Use Type:	**INDUSTRIAL**
Tax Rate Area:	**001-266**
Value Notice:	Open



Full Detail $14.95 Add to Cart The Full Property Detail includes everything displayed here plus completed information for those fields where "See Full Detail" is shown. If a field is empty on this page, no data is available, and the field will also be empty on the Full Property Detail.

Assessment

Total Value:	**$7,656,690**	Year Assd:	**2020**
Land:	**$6,192,913**	Zoning:	See Full Detail
Structures:	**$1,463,777**	Use Code:	See Full Detail
Other:		Census Tract:	
% Improved:	See Full Detail	Price/SqFt:	
Exempt Amt:			
HO Exempt:	**N**		

Sale History

	Sale 1	Sale 2	Sale 3	Transfer
Document Date:				See Full Detail
Document Number:				See Full Detail
Document Type:				
Transfer Amount:				
Seller (Grantor):				

Property Characteristics

Bedrooms:		Fireplace:		Units:	See Full Detail
Baths (Full):		A/C:		Stories:	
Baths (Half):		Heating:		Quality:	
Total Rooms:		Pool:		Building Class:	
Bldg/Liv Area:	**39,953**	Park Type:		Condition:	
Lot Acres:	**9.910**	Spaces:		Site Influence:	
Lot SqFt:	**431,679**	Garage SqFt:		Timber Preserve:	
Year Built:				Ag Preserve:	
Effective Year:					

**The information provided here is deemed reliable, but is not guaranteed.

Additional reports on this property

© 2021 **ParcelQuest** | Toll Free 1-844-893-7216 | Privacy Policy | Refund Policy | Disclaimer | Usage Limits

Ernie Dronenburg , County Assessor

Property Address: **G ST CHULA VISTA CA 00000**

General Information

Parcel # (APN):	**571-330-29-00** Open Map
Owner:	See Full Detail
Mailing Address:	**2828 E FOOTHILL BLVD #201 PASADENA CA 91107**
Legal Description:	**TR 166 QSEC172*(EX PAR6 SBE141-37-139)39**
Use Type:	**INDUSTRIAL**
Tax Rate Area:	**001-082**
Value Notice:	Open



Full Detail **$14.95** Add to Cart The Full Property Detail includes everything displayed here plus completed information for those fields where "See Full Detail" is shown. If a field is empty on this page, no data is available, and the field will also be empty on the Full Property Detail.

Assessment

Total Value:	**$58,551,210**	Year Assd:	**2020**
Land:	**$19,141,741**	Zoning:	See Full Detail
Structures:	**$39,409,469**	Use Code:	See Full Detail
Other:		Census Tract:	
% Improved:	See Full Detail	Price/SqFt:	
Exempt Amt:			
HO Exempt:	**N**		

Sale History

	Sale 1	Sale 2	Sale 3	Transfer
Document Date:	**09/25/2020**			See Full Detail
Document Number:	**0570885**			See Full Detail
Document Type:	See Full Detail			
Transfer Amount:	**$19,163,000**			
Seller (Grantor):				

Property Characteristics

Bedrooms:		Fireplace:		Units:	See Full Detail
Baths (Full):		A/C:		Stories:	
Baths (Half):		Heating:		Quality:	
Total Rooms:		Pool:		Building Class:	
Bldg/Liv Area:		Park Type:		Condition:	
Lot Acres:	**39.140**	Spaces:		Site Influence:	
Lot SqFt:	**1,704,938**	Garage SqFt:		Timber Preserve:	
Year Built:				Ag Preserve:	
Effective Year:					

**The information provided here is deemed reliable, but is not guaranteed.

Additional reports on this property

© 2021 **ParcelQuest** | Toll Free 1-844-893-7216 | Privacy Policy | Refund Policy | Disclaimer | Usage Limits

COLLINS AEROSPACE REDEVELOPMENT SITE

390 Bay Boulevard

CHULA VISTA, CA

INVESTMENT OFFERING MEMORANDUM



A ±50 Acre Redevelopment and/or Repurpose Opportunity Inclusive of a 41,360 SF Office Building And 920,087 SF of Industrial Buildings Situated on ±50 Acres

JLL®

CONFIDENTIALITY AGREEMENT

The information contained in this investment offering material ("Offering Memorandum") is confidential, furnished solely for the purpose of a review by a prospective purchaser of the Property and is not to be used for any other purpose or made available to any other person without the express written consent of JLL. The material is based in part upon information supplied by the owner of the Property ("Owner") and in part upon information obtained by JLL from sources it deems reasonably reliable. Summaries of any documents are not intended to be comprehensive or all inclusive but rather only outlines of some of the provisions contained herein. No warranty or representation, expressed or implied, is made by Owner, JLL, or any of their respective affiliates, as to the accuracy or completeness of the information contained herein or as to engineering or environmental matters. Prospective purchasers should make their own projections and conclusions without reliance upon the material contained herein and conduct their own independent due diligence, including engineering and environmental inspections to determine the condition of the Property and the existence of any potentially hazardous material used in the construction or maintenance of the building or located at the site. Delivery of this Offering Memorandum is also subject to the "Confidentiality and Conditions" section hereof.

This Offering Memorandum was prepared by JLL and has been reviewed by Owner. It contains selected information pertaining to the Property and does not purport to be all-inclusive or to contain all of the information, which a prospective purchaser may desire. All financial projections are provided for general reference purposes only and are based on assumptions relating to the general economy, competition, and other factors beyond control and, therefore, are subject to material change or variation. An opportunity to inspect the Property will be made available to qualified prospective purchasers.

In this Offering Memorandum, certain documents, including leases and other materials, are described in summary form. The summaries do not purport to be complete nor, necessarily, accurate descriptions of the full agreements involved, nor do they constitute a legal analysis of such documents. Interested parties are expected to independently review all documents. This Offering Memorandum is subject to prior placement, errors, omissions, changes or withdrawal without notice and does not constitute a recommendation, endorsement or advice as to the value of the Property by JLL or the Owner. Each prospective purchaser is to rely upon its own investigation, evaluation and judgment as the advisability of purchasing the Property described herein.

Owner and JLL expressly reserve the right, at their sole discretion, to reject any or all expressions of interest or offers to purchase the Property and/or to terminate discussions with any party at any time with or without notice. Owner shall have no legal commitment or obligation to any purchaser reviewing this Offering Memorandum or making an offer to purchase the Property unless a written agreement for the purchase of the Property has been fully executed, delivered, and approved by the Owner and any conditions to Owner's obligations hereunder have been satisfied or waived. JLL is not authorized to make any representations or agreements on behalf of Owner.

This Offering Memorandum is the Property of JLL and may be used by parties approved by JLL. The Property is privately offered and, by accepting this Offering Memorandum, the party in possession hereof agrees (i) to return it to JLL immediately upon request of JLL or Owner and (ii) that this Offering Memorandum and its contents are of a confidential nature and will be held and treated in the strictest confidence. No portion of this Offering Memorandum may be copied or otherwise reproduced or disclosed to anyone without the prior written authorization of JLL and Owner.

The Offering Memorandum may be disclosed to the Prospective Purchaser's partners, employees, legal counsel and institutional lenders ("Related Parties") only on a "need-to know" basis for the purpose of evaluating the potential purchase of the Property; provided, however, that Prospective Purchaser shall inform such Related Parties of the confidential nature of the Offering Memorandum, and shall be responsible for a breach of this agreement caused by such Related Parties. The terms and conditions set forth above apply to this Offering Memorandum in its entirety.

EXCLUSIVE MARKETING ADVISORS

JLL Capital Markets | Industrial - West Region

Ryan Sitov
Senior Vice President
310 595 3806
ryan.sitov@am.jll.com

Bo Mills, SIOR, CCIM
Managing Director
213 239 6303
bo.mills@am.jll.com

Mark Detmer, SIOR, CCIM
Managing Director
213 239 6377
mark.detmer@am.jll.com

JLL Local Market Experts

Jay Alexander
Managing Director
858 410 1188
jay.alexander@am.jll.com

Joe Anderson
Vice President
858 410 6360
j.anderson@am.jll.com

JLL Capital Markets | Finance

Brian Halpern
Managing Director
310 595 3626
brian.halpern@am.jll.com

Alex Kane
Vice President
310 595 3628
alex.kane@am.jll.com

Design and Production by Spire Creative
spirecreative.com

Collins Aerospace Redevelopment Site

CHULA VISTA, CALIFORNIA

Table of Contents

Executive and Investment Summary 7

Property Overview 21

Market and Area Overview 33

Financial Analysis 55

JLL®


H STREET
PARCEL B
INDUSTRIAL BUILDING
A
G STREET
B
PARCEL A
INDUSTRIAL BUILDING 29
BAY BLVD
INTERSTATE
5
Collins Aerospace Potential Future Parking
A: SDGE Substation
B: SDGE Easement & Utilities



DEAL CLIFF NOTES

- Please read the proposed CC&Rs starting on page 56
- The current zoning summary is on page 10. Please refer to the city of Chula Vista's website for a detailed overview
- Collins Aerospace will require ±3 acres for future parking. The proposed area is outlined on page 8. Alternative options may be proposed
- Building 29 and 100 Leaseback Requirements
  - Collins Aerospace will leaseback ±62,500 of ground floor area and 16,000sf of the mezzanine in Building 29 through December 31, 2019, Please see Exhibit A in Property Overview Section. Collins Aerospace will have two, six-month extension options
  - Collins Aeropsace will leaseback all of Building 100, +- 2,800sf through December 31, 2019. Collins Aerospace will have two, six-month extension options
  - All offers to purchase the property should include proposed leaseback options for Building 29 and 100
- Parcel B Leaseback Requirements
  - Collins Aerospace will leaseback the entire site with complete access and control through December 31, 2020. Collins Aerospace will have two, six-month extension options
  - All offers to purchase the property should include proposed leaseback options for Parcel B
- Environmental reports will be provided to groups that make the Best and Final
- Deal Timeline – Collins Aerospace would like to close this transaction in July 2019
  - Initial Marketing – Week of January 14th
  - Group Tours – February 11th – February 22nd
    - All tours to be coordinated through JLL, Courtney Webb courtney.webb@am.jll.com
    - Tour space is limited and will be booked on a first come first serve basis
    - Tour Participant Requirements
      - Full Name (first, middle, and last)
      - Citizenship
      - If you are a US Citizen and have a green card, please provide an identification number
      - Company Name
  - Call For Offers – February 27th
  - Best and Final – March 13th
  - Buyer Interviews – Week of March 18th
  - Select Buyer – Week of March 25th



Collins Aerospace Redevelopment Site

390 Bay Boulevard

Chula Vista, CA

A ±50 ACRE REDEVELOPMENT AND/OR REPURPOSE OPPORTUNITY INCLUSIVE OF A 41,360 SF OFFICE BUILDING AND 920,087 SF OF INDUSTRIAL BUILDINGS SITUATED ON ±50 ACRES



EXECUTIVE SUMMARY


INTERSTATE
5
BAY BLVD
PARCEL A
LAND
BUILDING
99
BUILDING
100
PARCEL A
INDUSTRIAL BUILDING 29
F STREET
G STREET
H STREET
B
A
PARCEL B
INDUSTRIAL BUILDING
Collins Aerospace Potential Future Parking
A: SDGE Substation
B: SDGE Easement & Utilities
N

THE OFFERING

JLL Industrial Capital Markets, as exclusive advisor, is pleased to present the opportunity to acquire the 100% fee-simple interest in the Collins Aerospace Redevelopment Site (the "Site") in Chula Vista, CA. The Site is situated on ±50 acres and encompasses a 41,360 square foot office building located at 390 Bay Boulevard and 920,087 square feet of industrial buildings.

The Site is located in the desirable, infill Chula Vista industrial submarket and is immediately adjacent to the Chula Vista Bayfront plan, one of the largest public/private planned developments in San Diego County.

With its location in the Chula Vista bay, the Collins Aerospace Site is an excellent and rare value-add repurposing and development opportunity that offers investors the chance to acquire an area of substantial scale in an infill market where demand is at its highest in over five years.

OFFERING SIUMMARY

	Parcel A			Parcel B	
	Land	Office Building 99/100	Industrial Building 29	Industrial Building	Totals
Land Size (Acres)	±7	±3	±9	±30	±49
RSF	0	41,360	225,000	695,087	961,447
General Plan Zoning	Light Industrial	Light Industrial	Light Industrial	General Industrial	

*Totals do not include 63,000sf of mezzanine space in Building 29

•Building 29 (0 G Street – south property) consisting of a 216,960 SF footprint and 63,900 SF of L-shaped, elevator-served mezzanine space for a total footage of 280,860. It is a 22' clear manufacturing building. It is concrete tilt-up with a metal skin.
•Building 99 (390 Bay Boulevard – north property) consisting of a 30,650 SF footprint and 8,083 SF of mezzanine space for a total footage of 38,733. It is a 24' clear flex building with raised flooring in the warehouse and 100% HVAC throughout the building. Originally used as a warehouse, it was most recently used as a training center. It is concrete tilt-up.
•Building 100 (390 Bay Boulevard – north property) consisting of 2,768 SF. It is a maintenance building in connection with Building 99. It appears to be concrete tilt-up.

INVESTMENT SUMMARY

PROPERTY HIGHLIGHTS

Rare Value Add Opportunity

Building Repurpose

Freeway Frontage – Both buildings on Parcel A provide freeway frontage along Interstate 5, the main interstate on the West Coast that runs through California, Oregon and Washington.

Abundant Parking – 390 Bay Boulevard has abundant parking to support a variety of potential building uses.

Contiguous Industrial Space – 850 Lagoon Drive is the second largest contiguous block of industrial space in San Diego County, making the site a rare and highly functional area.

Land and/or Building Redevelopment

Rare Large Lot – The Site is ±50 acres, a substantial size in an area where there is no industrial land for sale.

Light Industrial Zoning –

- The vacant lot, along with the land on which the office building at 390 Bay Boulevard currently sits, are designated I-RL (2-b), research and limited industrial, specifically food service commercial.
- Maximum FAR is 0.5, giving developers a chance to build up to ±218,000 square feet.
- Sub-zoning provides an in-demand option to develop commercial and mixed-use properties to maximize value.
- The sub-zoning can also be changed and encompasses other uses such as convenience sales and service commercial, business & communication service commercial, retail business supply commercial, research development commercial, auto fee parking commercial, custom industrial, essential service civic, parking service civic and community assembly civic.

General Industrial zoning –

- The ±39 acres on which the industrial building at 850 Lagoon Drive currently sits is designated I-G (2-b), convenience sales and service commercial.
- Maximum FAR is 0.5, giving developers a chance to build up to ±849,420 square feet.
- Zoning provides an excellent opportunity for last mile delivery requirements with a location in the heart of San Diego and access to the entire West Coast.

INVESTMENT SUMMARY

LOCATION HIGHLIGHTS

Immediate Adjacency to Chula Vista Bayfront Master Plan

- The Site is located adjacent to the 535 acre Chula Vista Bayfront Master Plan, an area of high demand, increasing both building and land values.
- Chula Vista Bayfront Master Plan is one of the most successful publicly/privately planned developments in San Diego County with a $1.3 billion economic impact, $11.5 billion in annual tax revenue, and creation of 2,200 permanent jobs.
- A mix of industrial, residential and office properties along with 2,850 hotel rooms, a 1,100-3,000 space parking garage, 600,000 square feet of restaurant retail and marina support uses, and 220,000 square feet of mixed-use commercial recreation/marine-related office uses.
- The recent unanimous vote to approve the financing of the hotel and convention center was called a “historic” moment by Chula Vista’s Mayor, Casillas Salas.
- The Bayfront will offer a unique opportunity to develop a place that will draw from local and regional populations, as well as from the broader U.S. and international visitor groups that have historically travelled through San Diego or Mexico.

Expedited Permitting Area

- Chula Vista permitting allows business to complete the permitting process in a quicker timeframe.

Port of San Diego Marine Hub

- The Port of San Diego is the Nations’ specialty cargo gateway with on-dock Class I rail service, processing primarily specialty cargo that does not fit standardized containers, including breakbulk (heavy, high and wide cargo shipped without containers), refrigerated cargo and bulk commodities.
- The National City Marine terminal serves as the primary port of entry for one out of every 10 new foreign cars shipped to the United States.




MIXED-USE
COMMERCIAL
INTERSTATE
5
BAY BOULEVARD
F STREET


INDUSTRIAL
HOTEL & OFFICE
RESIDENTIAL
RETAIL
HOTEL & RETAIL
PARCEL B
RESORT HOTEL &
CONVENTION CENTER
N

COLLINS AEROSPACE REDEVELOPMENT SITE
CHULA VISTA, CALIFORNIA

Ideal Demographic Location

- Chula Vista is the second largest city in San Diego County with one of the heaviest populated and densest job centers.
- Advanced Manufacturing, both in Precision Manufacturing and Aerospace, as well as Navigation and Maritime Technologies, is Chula Vista's strongest niche in the Region.
- Located in a submarket with established corporate neighbors including Best Buy, Walmart, Mazda, Nissan, Toyota, Starbucks, In-N-Out, Costco, Target, Old Navy, The Home Depot, etc.

Close proximity to Rail, Mail, Air and Ports

- Less than half a mile to Interstate-5 Freeway
- 10 miles to the Port of San Diego
- 7 miles BNSF Yard
- ~2 hour drive to Union Pacific Yard




CHULA VISTA BAYFRONT MASTER PLAN











Naval Base San Diego

- Largest West coast naval base
- Composed of 13 piers stretched over 977 acres of land and 326 acres of water
- Total on-base population 24,000 military personnel and over 10,000 civilians
- The base has plant value of $2.1 billion
- 2.1 billion in direct spending in 2017

Unified Port of San Diego

- 135-acre complex
- 4 functional berths
- Serves as the primary port of entry for one out every 10 new foreign cars shipped to the United States including Audi, Bentley, Honda, Mitsubishi Fuso, Isuzu, Porsche, Volkswagen, Hyundai and Kia

POPULATION SUMMARY	15 MILES	35 MILES	55 MILES
2018 Total Population	1,679,966	2,722,171	3,328,685
2023 Total Population	1,754,881	2,848,604	3,483,727
2018-2023 Annual Population Growth Rate	0.89%	0.92%	0.93%
Total Businesses	58,781	100,555	119,818
Total Employees	735,996	1,251,725	1,467,619
Labor Force By Occupation - White Collar	61.5%	66.0%	54.6%
Labor Force By Occupation - Blue Collar	16.3%	14.8%	15.9%
Labor Force By Occupation - Services	22.2%	19.2%	29.5%



INVESTMENT SUMMARY

MARKET HIGHLIGHTS - Q3 2018

	Inventory	Total Vacancy (%)	Average Asking Rent (PSF/MO)	YTD Net Absorption (SF)	Under Construction
San Diego	121,004,918	4.20%	$0.93	988,328	2,248,519
South Bay San Diego	26,600,875	4.60%	$0.72	427,122	424,960
Chula Vista	7,550,012	1.40%	$0.53	-58,723	163,000



- **Sustained High Asking Rents –**
  - Asking rents for San Diego are growing 1.1% quarter-over-quarter and 6.9% year-over-year.
  - Average asking rents and occupancy rates are well above their pre-recession peak levels. Average asking rents are now 26% higher than the peak back in 2007, when vacancy was notably higher at 6.3% versus the current vacancy of 4.0%.



- **Increased Demand –** Vacancies will remain tight and asking rates high in Chula Vista as a result of the increased demand from defense contractors and importers for properties in the submarket.



- **Dearth of Availability –** In the South Bay industrial market, there is only 7.5% of the available space, increasing the demand for the potential ±200,000 square feet repurpose and/or redevelopment opportunity.



- **Low Vacancies -**
  - Vacancy rate in San Diego has decreased 20% since 2016 from 4.8% to 4.0%.
  - Of the whole San Diego market, Chula Vista has one of the lowest total vacancy rates, hovering at 1.4%.

- **Limited Construction Activity –** Chula Vista recorded 163,000 square feet of construction in Q3 2018 in comparison to the rest of South Bay and San Diego as a whole, further tightening vacancies in the submarket and making the Site a rare development opportunity. The last new industrial delivery was Chula Vista Commerce Center by Voit Real Estate in 2007 while the last new office delivery was Fresenius Dialysis Center in 2012.





Collins Aerospace Redevelopment Site

390 Bay Boulevard

Chula Vista, CA

A ±50 ACRE REDEVELOPMENT AND/OR REPURPOSE OPPORTUNITY INCLUSIVE OF A 41,360 SF OFFICE BUILDING AND 920,087 SF OF INDUSTRIAL BUILDINGS SITUATED ON ±50 ACRES



PROPERTY OVERVIEW

PROPERTY OVERVIEW

LOCATION

The Collins Aerospace ±50 acre site is conveniently located in San Diego's tightest submarket, is immediately adjacent to the Chula Vista Bayfront Plan, a 535 acre master plan development, and is less than half a mile to the I-5 Freeway.




INTERSTATE
5
F STREET
G STREET
N



- Collins Aerospace Potential Future Parking
- **A:** SDGE Substation
- **B:** SDGE Easement & Utilities

SITE SUMMARY TABLE

BUILDINGS		
Address:	390 Bay Boulevard, Chula Vista, CA	Industrial Building, Chula Vista, CA
Submarket:	South Bay	South Bay
Asset Type:	Office	Industrial
Land Area:	±3 acres	± 9 acres
Total Rentable Area:	41,360	225,000
Dock High / Grade Level:	NA	0/2
Sprinkler:	Sweetwater Authority South face near SW corner	Private - UTAS from Bldg 1 10” Two locations on the east side
Electrical:	Private - UTAS from BLDG 112 sub 99, 2000 kva	Private - UTAS from BLDGS 1 & 112 sub 29A, 3 @ 1000 kva; sub 29B, 100 kva; sub 29C, 2000 kva
Water:	Sweetwater Authority 1 1/2” diameter Between Bay Blvd and Bldg 99 near NE corner	Sweetwater Authority Two at 2” diameter Between Bay Blvd and Bldg 29 near southern 1/3 point Chilled Water – private (UTAS from Bldg 1)
Gas:	San Diego Gas & Electric 2” diameter South face near SW corner	Private - UTAS from Bldg 1 2” diameter, 10 psi Near column M6
Compressed Air:	None	Private - UTAS from Bldg 1 3” diameter, 100 psi 3” diameter, 100 psi
Sewer:	City of Chula Vista West to Walnut Avenue	City of Chula Vista South to G Street
Zoning:	I-RL (2-b)	I-G (2-b)
APN:	5670223000	5713302900
Max. FAR:	0.5	0.5
Max Development SF:	±218,000	±200,000



LAND	
Address:	310-368 Bay Boulevard, 798 F Street
Land Size:	±7 acres
Zoning:	I-RL (2-b)
APN:	5670223600; 5670223500; 5670221700; 5670223100; 5670223300; 5670222800; 5670220100
Max. FAR:	0.5
Max Development SF:	±152,000



INTERSTATE
5
F STREET
G STREET
H STREET
N


INTERSTATE
5
BAY BLVD
G STREET
H STREET
A
B
91
116
503
500
1 Mezz Office
Canopy
1
98
33
55
54
22
119
50
117
453
70
310
80-82
380
327
Collins Aerospace Potential Future Parking
A: SDGE Substation
B: SDGE Easement & Utilities
N

SQ. FT. APPROXIMATE – NOT TO BE USED AS AN ACTUAL REPRESENTATION


Bldg#	Floor	Footprint	Utilization	Comments
1	1	466,400	Mfg	OE / Spares Manufacturing
1	2	56,626	Offices	Offices
22	1	5,825	mfg suppt	IT storage
33	1	3,500	mfg suppt	Café
50	1	38,545	Mfg.	Previously used for MFG.; currently used for warehousing
54	1	92,817	mfg suppt	Storage; 75K s.f. has floor to ceiling racks supporting roof
55	1	31,374	Mfg.	A350 Fan Cowl Assembly
70	1	2,323	mfg suppt	Weld Shop
80	1	267	mfg suppt	Storage shed
81	1	267	mfg suppt	Storage shed
82	1	267	mfg suppt	Storage shed
91	1	871	mfg suppt	Gate 25 Security
98	1	260	mfg suppt	Maintenance Shed
116	1	7,046	mfg suppt	East Paint Shop
117	1	1,510	mfg suppt	Waste Water Treatment Control Room
119	1	3,406	mfg suppt	Autoshop
310	1	3,486	mfg suppt	Chemical Stores Canopy
310	1	288	na	Chem Stores shed
327	1	1,793	mfg suppt	Salvage Office
380	1	575	mfg suppt	Storage shed
453	1	576	mfg suppt	Chem Stores shed
500	1	1,511	mfg suppt	Foundry
503	1	500	mfg suppt	Fire Station Building lean-to
na	-	-	na	Six storage containers
Total		**720,032**		

390 BAY BOULEVARD



BUILDING 29 - INDUSTRIAL BUILDING

BUILDING 29 & BUILDING 100
LEASEBACK SPACE REQUIREMENT
(THROUGH 2019)



Leaseback of 2.8K s.f. of building 100 required



Collins Aerospace Redevelopment Site

390 Bay Boulevard

Chula Vista, CA

A ±50 ACRE REDEVELOPMENT AND/OR REPURPOSE OPPORTUNITY INCLUSIVE OF A 41,360 SF OFFICE BUILDING AND 920,087 SF OF INDUSTRIAL BUILDINGS SITUATED ON ±50 ACRES

National Flood Hazard Layer FIRMette

FEMA

117°6'18"W 32°37'57"N



117°5'41"W 32°37'27"N

0 250 500 1,000 1,500 2,000 Feet

1:6,000

Basemap: USGS National Map: Orthoimagery: Data refreshed October, 2020

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 / 17.5 Cross Sections with 1% Annual Chance Water Surface Elevation
- Coastal Transect
- Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 1/28/2021 at 3:28 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

U.S. Fish and Wildlife Service
National Wetlands Inventory

Parcel B



February 5, 2021

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.



Map Scale: 1:4,250 if printed on A landscape (11" x 8.5") sheet.

N

Meters: 0 50 100 200 300

Feet: 0 200 400 800 1200

Map projection: Web Mercator Corner coordinates: WGS84 Edge tics: UTM Zone 11N WGS84

MAP LEGEND

Area of Interest (AOI)

- Area of Interest (AOI)

Soils

- Soil Map Unit Polygons
- Soil Map Unit Lines
- Soil Map Unit Points

Special Point Features

- Blowout
- Borrow Pit
- Clay Spot
- Closed Depression
- Gravel Pit
- Gravelly Spot
- Landfill
- Lava Flow
- Marsh or swamp
- Mine or Quarry
- Miscellaneous Water
- Perennial Water
- Rock Outcrop
- Saline Spot
- Sandy Spot
- Severely Eroded Spot
- Sinkhole
- Slide or Slip
- Sodic Spot
- Spoil Area
- Stony Spot
- Very Stony Spot
- Wet Spot
- Other
- Special Line Features

Water Features

- Streams and Canals

Transportation

- Rails
- Interstate Highways
- US Routes
- Major Roads
- Local Roads

Background

- Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:24,000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL:
Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: San Diego County Area, California
Survey Area Data: Version 15, May 27, 2020

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Aug 22, 2018—Aug 31, 2018

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
HuC	Huerhuero-Urban land complex, 2 to 9 percent slopes	27.9	68.6%
Md	Made land	12.7	31.4%
Totals for Area of Interest		**40.6**	**100.0%**

San Diego County Area, California

HuC—Huerhuero-Urban land complex, 2 to 9 percent slopes

Map Unit Setting

National map unit symbol: hbcs
Elevation: 1,100 feet
Mean annual precipitation: 12 to 20 inches
Mean annual air temperature: 57 degrees F
Frost-free period: 260 days
Farmland classification: Not prime farmland

Map Unit Composition

Huerhuero and similar soils: 50 percent
Urban land: 30 percent
Minor components: 15 percent
Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Huerhuero

Setting

Landform: Marine terraces
Down-slope shape: Linear
Across-slope shape: Linear
Parent material: Calcareous alluvium derived from sedimentary rock

Typical profile

H1 - 0 to 12 inches: loam
H2 - 12 to 55 inches: clay loam, clay
H2 - 12 to 55 inches: stratified sand to sandy loam
H3 - 55 to 72 inches:

Properties and qualities

Slope: 2 to 9 percent
Depth to restrictive feature: More than 80 inches
Drainage class: Moderately well drained
Runoff class: Very high
Capacity of the most limiting layer to transmit water (Ksat): Very low to moderately low (0.00 to 0.06 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)
Sodium adsorption ratio, maximum: 25.0
Available water capacity: Moderate (about 6.6 inches)

Interpretive groups

Land capability classification (irrigated): 4e
Land capability classification (nonirrigated): 4e

Hydrologic Soil Group: D
Hydric soil rating: No

Description of Urban Land

Typical profile
H1 - 0 to 6 inches: variable

Interpretive groups
Land capability classification (irrigated): None specified
Land capability classification (nonirrigated): 8
Hydric soil rating: No

Minor Components

Las flores
Percent of map unit: 10 percent
Hydric soil rating: No

Oliventain
Percent of map unit: 5 percent
Hydric soil rating: No

Data Source Information

Soil Survey Area: San Diego County Area, California
Survey Area Data: Version 15, May 27, 2020

San Diego County Area, California

Md—Made land

Map Unit Composition

Made land: 100 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Made Land

Typical profile

H1 - 0 to 6 inches: variable

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 8

Hydric soil rating: No

Data Source Information


Soil Survey Area: San Diego County Area, California
Survey Area Data: Version 15, May 27, 2020

Available online at
www.sweetwater.org/wqreport

SWEETWATER AUTHORITY'S
Annual Drinking Water Quality Report for 2019

Last year, the water delivered to you by Sweetwater Authority met all state and federal drinking water health standards

EL REPORTE CONTIENE VALIOSA INFORMACIÓN SOBRE LA CALIDAD DE SU AGUA POTABLE Esta disponible en nuestro sitio de web www.sweetwater.org/wqreportsp



twitter @sweetwaterauth
facebook.com/swawater
linkedin.com/company/sweetwater-authority
youtube.com/user/SweetwaterAuthority

1 ABOUT YOUR DRINKING WATER AND THIS REPORT

WHAT IS SAFE DRINKING WATER?

The U. S. Environmental Protection Agency (USEPA) and the California State Water Resources Control Board (State Water Board) regulate California's tap water. These agencies establish standards that define our current understanding of safe drinking water. Last year, the water delivered by Sweetwater Authority (Authority) met all USEPA and State Water Board drinking water health standards.


This report provides information about the ways that the Authority vigilantly safeguards and treats your drinking water supplies. In accordance with state and federal laws, it also provides a detailed listing of constituents found in your drinking water, and compares those levels to the maximum levels considered safe for the general public by the USEPA and the State Water Board. If you have questions about Authority operations or the contents of this report, please visit www.sweetwater.org or call the Water Treatment Superintendent at 619-409-6812.

This report also includes information about the Authority's water sources and how those sources are protected, as well as people to contact for more details, and ways you can become more involved in protecting your water.

ABOUT SWEETWATER AUTHORITY

The Authority is a publicly-owned, joint powers water agency, with policies and procedures established by a seven-member Governing Board. Five directors are elected by the citizens of the South Bay Irrigation District. Two directors are appointed by the Mayor of National City, subject to City Council confirmation.

The Authority provides safe, reliable water service to approximately 190,000 people in National City, Bonita, and western and central portions of Chula Vista. Its customers include residential, business, government, and industrial water users in an area covering more than 36 square miles in the South Bay region of San Diego County.



ABOUT YOUR DRINKING WATER

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that the water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the USEPA Safe Drinking Water Hotline at 1-800-426-4791, or visiting the USEPA website at www.epa.gov/ground-water-and-drinking-water.

Note to special populations: Some people may be more vulnerable to contaminants in drinking water than the general population. Immuno-compromised persons, such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. To obtain USEPA/Centers for Disease Control and Prevention (CDC) guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants, please call the USEPA Safe Drinking Water Hotline at 1-800-426-4791.

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive materials, and can pick up substances resulting from the presence of animals or from human activity.

Before water is treated, raw water may contain contaminants including:

Microbial contaminants, such as viruses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.

Inorganic contaminants, such as salts and metals, that can be naturally occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.

Pesticides and herbicides, that may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.

Organic chemical contaminants, including synthetic and volatile organic chemicals that are by-products of industrial processes and petroleum production, and can also come from gas stations, urban stormwater runoff, agricultural applications, and septic systems.

Radioactive contaminants, that can be naturally occurring or the result of oil and gas production, and mining activities.

To learn more about contaminants and health effects, call the USEPA Safe Drinking Water Hotline at 1-800-426-4791. Further information is available at www.sweetwater.org or www.mwdh2o.com.

In order to ensure that tap water is safe to drink, the USEPA and the State Water Board prescribe regulations that limit the amount of certain contaminants in water provided by public water systems. The U.S. Food and Drug Administration regulations and California law also establish limits for contaminants in bottled water that provide the same protection for public health.

Water Sources: Authority customers receive water from four sources: the Sweetwater River (drawn at Sweetwater Reservoir in Spring Valley), deep freshwater wells in National City, brackish water wells in Chula Vista, and the region's imported supply, which is drawn from the Colorado River and/or the State Water Project in northern California. Source water assessments are available for each of these sources.

Public Participation

Public participation is welcome at all Sweetwater Authority Board meetings. Meetings are held at 505 Garrett Avenue, Chula Vista, the second and fourth Wednesday of each month at 6:00 p.m. Agendas are posted at 505 Garrett Avenue, Chula Vista. Meeting agendas and minutes are published on the Authority's website at www.sweetwater.org.

How is your water protected from contamination?
The local water used by the Authority can be affected by activities within its watershed, a 230-square-mile area leading into the streams that feed the Sweetwater River. The Authority uses a multiple-barrier approach to ensure water quality. Education, stakeholder involvement, and comments to local planners are part of Authority efforts, in addition to the "hardware" solutions described here:

1) An innovative diversion system captures urban runoff before it enters Sweetwater Reservoir and transports the runoff below Sweetwater Dam, reducing the buildup of mineral salts in the reservoir. The diversion system can also capture and hold runoff from a chemical spill or sewage system failure, allowing the contaminants to be removed and trucked away for proper disposal.

2) Well sites are closely monitored to assure that contaminants have not entered the well fields.


3) Surface water is treated and disinfected at the Robert A. Perdue Water Treatment Plant.

4) Potable groundwater is disinfected.

5) Brackish groundwater is treated with reverse osmosis and disinfected. (To learn more, visit www.sweetwater.org/water.)

Consumer questions and answers about water quality, taste, color and odor, can be found at www.sweetwater.org/wq.

The Source Water Assessment identifies activities to which water sources are considered "most vulnerable." In 2002, source water assessments were completed for the Authority's water supplies. There were NO contaminants from the "possible contaminating activities" found in the Authority's water supplies. To request a summary of the assessments, contact the Water Quality Services Technician at 619-409-6805, or cpino@sweetwater.org.



How to Reach Us

Customer Service	619-420-1413
After Hours Emergency	619-420-1413
Water Quality Info	619-409-6780
Water Efficiency Helpline	619-409-6779
Fluoride Info Line	619-409-6780
Construction Information	619-409-6850
School Programs	619-409-6781
Community Presentations	619-409-6723
Board Secretary	619-409-6703

PRIMARY STANDARDS **For the 2019 calendar year**				National City Wells (Disinfected with chloramine)		Treated at Reynolds Groundwater Desal Facility	Treated at Robert A. Perdue Water Treatment Plant		Treated[1] Sweetwater Authority Drinking Water	**If you do not see a contaminant listed here, it was not detected in 2019.** **Typical Source of Contaminant:**
Inorganic Contaminants	MCL [MRDL]	PHG (MCLG) [MRDLG]	Range and Average	— BEFORE TREATMENT —						
				National City Well 3	National City Well 4	SD Formation Wells 1 - 11	Lake Skinner Outlet (Aqueduct)	Sweetwater Reservoir		
Fluoride (ppm)	2.0	1	Range	0.4 - 0.4	0.4 - 0.4	0.1 - 0.5	0.1 - 0.2	0.2 - 0.3	0.5 - 0.9[10]	Erosion of natural deposits; discharge from fertilizer and aluminum factories; water additive that promotes oral health
			Average	0.4	0.4	0.2	0.2	0.2	0.7	
Aluminum (ppb)	1000	600	Range	ND	ND	ND	ND	ND - 420[2]	ND	Erosion of natural deposits; residue from surface water treatment processes
			Average	ND	ND	ND	ND	217	ND	
Arsenic (ppb)	10	0.004	Range	ND	ND	ND - 3.9[2]	ND	ND - 2.0[2]	ND	Erosion of natural deposits; glass and electronics production wastes
			Average	ND	ND	1.8	ND	1.7	ND	
Barium (ppm)	1	2	Range	ND	0.1 - 0.1	ND - 0.2[2]	ND	ND	ND - 0.1	Erosion of natural deposits; discharges of oil drilling wastes and from metal refineries
			Average	ND	0.1	0.1	ND	ND	ND	
Selenium (ppb)	50	30	Range	ND	ND	ND - 18[2]	ND	ND	ND	Refineries, mines, and chemical waste discharges; erosion of natural deposits; runoff
			Average	ND	ND	5	ND	ND	ND	
Radionuclides (a)										
Gross Alpha (pCi/L)	15	(0)	Range	ND	ND	ND - 11[2,3]	ND - 3.7[2,3]	ND	NA	Erosion of natural deposits
			Average	ND	ND	3.9	ND	ND	NA	
Gross Beta (pCi/L)	50	(0)	Range	NA	NA	ND - 17[3]	ND	ND - 13[3]	NA	Decay of natural and man-made deposits
			Average	NA	NA	8.1	ND	5.5	NA	
Radium - 226 (pCi/L)	5	0.05	Range	ND	ND	ND - 1.2[2,3]	ND	ND	NA	Erosion of natural deposits
			Average	ND	ND	ND	ND	ND	NA	
Uranium (pCi/L)	20	0.43	Range	ND	ND	ND - 8.3[2,3]	ND - 1.3[2,3]	2.1[2,3,4]	NA	Erosion of natural deposits
			Average	ND	ND	2.4	ND	2.1	NA	
Turbidity (b)										
Combined Filter Effluent Turbidity (NTU)	TT = 1 NTU	NA	Highest Single Measurement						0.28	Soil runoff
	TT = 95% of samples ≤0.3 NTU		Lowest Monthly Percent of Samples Meeting MCL						100.0%	
Unregulated Contaminants[5]										
Boron (ppm)	NA	NL = 1.0	Range	0.23 - 0.24	0.17 - 0.18	0.23 - 0.46	0.13[4]	0.11 - 0.13	0.13 - 0.23	Runoff/leaching from natural deposits; industrial wastes
			Average	0.24	0.18	0.33	0.13	0.12	0.18	
Vanadium (ppb)	NA	NL = 50	Range	ND	13 - 14	ND	ND	5.3 - 5.5[2]	ND	Naturally occurring; industrial waste discharge
			Average	ND	14	ND	ND	5.4	ND	
Perfluorooctanesulfonic acid (PFOS) (ppt)	NA	NL = 6.5	Range	NA	NA	ND - 7.1[2]	ND	NA	ND	Products manufactured with perfluoroalkyl substances (PFAS) include non-stick cookware, fast-food packaging, stain- and water-repellent fabrics, including clothing and carpets. PFAS chemicals are also found in fire-fighting foam, wastewater effluent, and in landfills.
			Average	NA	NA	2.1	ND	NA	ND	
Perfluorooctanoic acid (PFOA) (ppt)	NA	NL = 5.1	Range	NA	NA	ND - 6.8[2]	ND	NA	ND	
			Average	NA	NA	1.6	ND	NA	ND	
Perfluorobutanesulfonic acid (PFBS) (ppt)	NA	NA	Range	NA	NA	ND - 2.2[2]	ND	NA	ND	
			Average	NA	NA	ND	ND	NA	ND	
Perfluorohexanesulfonic acid (PFHxS) (ppt)	NA	NA	Range	NA	NA	ND - 8.3[2]	ND	NA	ND	
			Average	NA	NA	2.4	ND	NA	ND	
Perfluorohexanoic acid (PFHxA) (ppt)	NA	NA	Range	NA	NA	ND	2.2 - 2.6	NA	ND[2a]	
			Average	NA	NA	ND	2.4	NA	ND	

PRIMARY STANDARDS CONTINUED				National City Wells (Disinfected with chloramine)		Treated at Reynolds Groundwater Desal Facility	Treated at Robert A. Perdue Water Treatment Plant		Treated[1] Sweetwater Authority Drinking Water	If you do not see a contaminant listed here, it was not detected in 2019. Typical Source of Contaminant:
Inorganic Contaminants	MCL [MRDL]	PHG (MCLG) [MRDLG]	Range and Average	— BEFORE TREATMENT —						
				National City Well 3	National City Well 4	SD Formation Wells 1 - 11	Lake Skinner Outlet (Aqueduct)	Sweetwater Reservoir		
Unregulated Contaminant Monitoring Rule 3 (UCMR3) (c)										
Chlorate (ppb)	NA	NL = 800	Combined Distribution System Range						43 - 700	By-product of drinking water disinfection when using chlorine dioxide; hypochlorite degradation
			Combined Distribution System Average						275	
Molybdenum (ppb)	NA	NA	Combined Distribution System Range						1.0 - 8.2	Naturally occuring; manufacturing process waste
			Combined Distribution System Average						4.4	
Strontium (ppb)	NA	NA	Combined Distribution System Range						320 - 1100	Erosion of natural deposits; atmospheric deposition; wastewater discharges
			Combined Distribution System Average						684	
Vanadium (ppb)	NA	NL = 50	Combined Distribution System Range						ND - 7.2	Naturally occuring; industrial waste discharge
			Combined Distribution System Average						2.2	
Unregulated Contaminant Monitoring Rule 4 (UCMR4) (c)										
Total Organic Carbon (ppm)	TT	NA	Range	Perdue Water Treatment Plant - Raw Water Influent (Before Treatment)			2.9 - 12		NA	Various natural and man-made sources
			Average				8.6		NA	
Bromide (ppb)	NA	NA	Range	Perdue Water Treatment Plant - Raw Water Influent (Before Treatment)			81 - 420		NA	Runoff/leaching from natural deposits; seawater influence
			Average				315		NA	
Manganese (ppb)	50	NL = 500	Combined Distribution System Range						ND - 10	Leaching from natural deposits
			Combined Distribution System Average						3.3	
HAA5 (ppb)	60	NA	Combined Distribution System Range						ND - 38.2	Byproduct of drinking water chlorination
			Combined Distribution System Average						17.3	
HAA6Br (ppb)	NA	NA	Combined Distribution System Range						ND - 39.6	Byproduct of drinking water chlorination
			Combined Distribution System Average						17.0	
HAA9 (ppb)	NA	NA	Combined Distribution System Range						ND - 66.4	Byproduct of drinking water chlorination
			Combined Distribution System Average						30.0	
Disinfection and By-product Contaminants										
Total Trihalomethanes (TTHMs) (ppb)	80	NA	Highest Locational Running Annual Average (LRAA)						48.5	By-product of drinking water chlorination
			Range of All Distribution Sample Points						2.5 - 63.5[6]	
Haloacetic Acids (HAAs) (ppb)	60	NA	Highest Locational Running Annual Average (LRAA)						27.2	By-product of drinking water chlorination
			Range of All Distribution Sample Points						ND - 40.3[6]	
Chloramines (ppm)	[4.0]	[4]	Highest Running Annual Average (RAA)						2.8	Drinking water disinfectant added for treatment
			Combined Distribution System Range						0.5 - 4.6[6]	
Chlorine Dioxide (ppb)	[800]	[800]	Perdue Plant Clearwell Effluent Range						ND - 240[6]	Drinking water disinfectant added for treatment
			Perdue Plant Clearwell Effluent Average						ND	
Chlorite (ppm)	1.0	0.05	Combined Distribution System Range						ND - 0.43[6]	By-product of drinking water disinfection when using chlorine dioxide
			Combined Distribution System Average						0.21	
Chlorate (ppb)	NA	NL = 800	Combined Distribution System Range						70 - 490[6]	By-product of drinking water disinfection when using chlorine dioxide; hypochlorite degradation
			Combined Distribution System Average						310	
Lead and Copper Rule			Number of sites found above AL						90 percent of samples below	
Lead (ppb)	AL = 15	0.2	1 site above AL out of 62 sites sampled						ND[3]	Corrosion of onsite plumbing systems
Copper (ppm)	AL = 1.3	0.3	0 sites above AL out of 62 sites sampled						0.13[3]	

PRIMARY STANDARDS CONTINUED				National City Wells (Disinfected with chloramine)		Treated at Reynolds Groundwater Desal Facility	Treated at Robert A. Perdue Water Treatment Plant		Treated[1] Sweetwater Authority Drinking Water	If you do not see a contaminant listed here, it was not detected in 2019. Typical Source of Contaminant:
Inorganic Contaminants	MCL [MRDL]	PHG (MCLG) [MRDLG]	Range and Average	— BEFORE TREATMENT —						
				National City Well 3	National City Well 4	SD Formation Wells 1 - 11	Lake Skinner Outlet (Aqueduct)	Sweetwater Reservoir		
School Lead Testing[11]										
In 2019, the Authority completed lead sampling at 2 schools within its service area in compliance with State Water Board regulations.										
Microbiological (d)									Highest monthly percentage	
Total Coliform Bacteria	5.0% (TT)	(0)	Number of positive samples taken this year = 1						1.1%	Naturally present in the environment
E.coli Coliform Bacteria	(d)	(0)	Number of positive samples taken this year = 0						0%	Human and animal fecal waste
Cryptosporidium (Oocysts/10L)	TT	(0)	Range				NA	ND[7]	NA	Naturally present in the environment
			Average				NA	ND	NA	
SECONDARY STANDARDS										
Aluminum[8] (ppb)	200	NA	Range	ND	ND	ND	ND	ND - 420[2]	ND	Erosion of natural deposits; residue from some surface water treatment processes
			Average	ND	ND	ND	ND	217	ND	
Copper (ppb)	1000	NA	Range	ND	ND	ND	ND	ND - 86[2]	ND	Erosion of natural deposits; leaching from wood preservatives; Internal corrosion of household plumbing systems
			Average	ND	ND	ND	ND	61	ND	
Iron (ppb)	300	NA	Range	ND	ND	ND - 420[2]	ND	ND - 440[2]	ND	Leaching from natural deposits; industrial wastes
			Average	ND	ND	ND	ND	235	ND	
Manganese (ppb)	50	NL = 500	Range	ND	ND	27 - 3000[2]	ND	35 - 69[2]	ND - 21	Leaching from natural deposits
			Average	ND	ND	602	ND	52	ND	
Specific Conductance (microseimens/centi-meter)	1600	NA	Range	1100 - 1100	870 - 900	1800 - 9400[2]	543 - 686	860 - 1000	620 - 1100	Substances that form ions when in water; seawater influence
			Average	1100	885	3459	614	930	840	
Total Dissolved Solids (ppm)	1000	NA	Range	590 - 620	490 - 500	1000 - 6100[2]	312 - 394	510 - 650	340 - 670	Runoff/leaching from natural deposits; seawater influence
			Average	605	495	2232	353	580	503	
Chloride (ppm)	500	NA	Range	200 - 210	150 - 160	370 - 3100[2]	64 - 82	140 - 170	160 - 180	Runoff/leaching from natural deposits; seawater influence
			Average	205	155	980	73	155	168	
Sulfate (ppm)	500	NA	Range	58 - 59	38 - 39	116 - 488[2]	76 - 113	84 - 107	24 - 127	Runoff/leaching from natural deposits; industrial wastes
			Average	58	38	192	94	96	71	
Color (units)	15	NA	Range	1 - 3	1 - 3	1 - 3	5 - 10	20 - 70	1 - 3	Naturally occurring organic materials; iron and manganese
			Average	2	2	2	8	45	2	
Odor-Threshold (units)	3	NA	Range	ND	ND - 1	ND - 1	7[2,4]	3 - 8[2]	ND - 1	Naturally occurring organic materials
			Average	ND	1	ND	7	6	1	
Turbidity[8] (NTU)	5	NA	Range	0.12- 0.13	0.07 - 0.07	0.04 - 0.41	0.8 - 1.2	1.3 - 11.3	0.04 - 0.42	Soil runoff
			Average	0.13	0.07	0.14	1.0	6.3	0.16	
Foaming Agents (MBAS) (ppb)	500	NA	Range	ND	ND	ND	ND	ND	ND	Municipal and industrial waste discharges
			Average	ND	ND	ND	ND	ND	ND	

Inorganic Contaminants	MCL [MRDL]	PHG (MCLG) [MRDLG]	Range and Average	National City Wells (Disinfected with chloramine)		Treated at Reynolds Groundwater Desal Facility	Treated at Robert A. Perdue Water Treatment Plant		Treated[1] Sweetwater Authority Drinking Water	**If you do not see a contaminant listed here, it was not detected in 2019.** **Typical Source of Contaminant:**
				— BEFORE TREATMENT —						
				National City Well 3	National City Well 4	SD Formation Wells 1 - 11	Lake Skinner Outlet (Aqueduct)	Sweetwater Reservoir		
OTHER PARAMETERS										
Sodium (ppm)	NA	NA	Range	150 - 160	130 - 130	260 - 1300[2]	55 - 69	90 - 110	80 - 120	Runoff/leaching from natural deposits; seawater influence
			Average	155	130	484	62	100	100	
Hardness (Total Hardness as $CaCO_3$) (ppm)	NA	NA	Range	190 - 190	160 - 170	320 - 1800[2]	137 - 170	260 - 310	91 - 300	Leaching from natural deposits
			Average	190	165	658	154	285	194	
Radon (pCi/L)[9]	NA	NA	Range	270[4]	374[4]	190 - 300[2]	ND	NA	NA	Decay of natural deposits
			Average	270	374	240	ND	NA	NA	
pH (Standard Units)	NA	NA	Range	7.8 - 8.1	7.9 - 8.2	7.2 - 8.2	8.0 - 8.4	8.1 - 8.7	8.1 - 9.1	Soil geology, water hardness, and alkalinity
			Average	8.0	8.1	7.9	8.2	8.4	8.6	
Total Organic Carbon (ppm)	TT	NA	Range	NA	NA	NA	3.2 - 3.7	9.7 - 12.7	2.2 - 9.2	Various natural and man-made sources
			Average	NA	NA	NA	3.4	11.1	7.4	

Informational Statements
The Authority vigilantly safeguards its water supplies and has met all state and federal health standards. The following information describes potential health effects of drinking water that contain contaminants above federal maximum levels.

Radon: Radon is a radioactive gas that you cannot see, taste, or smell. It is found throughout the U.S. Radon can move up through the ground and into a home through cracks and holes in the foundation. Radon can build up to high levels in all types of homes. Radon can also get into indoor air when released from tap water through showering, washing dishes, and other household activities. In most cases, the amount of radon entering a home from tap water will be much less than the amount of radon entering the home through soil. Radon is a known human carcinogen. Breathing air containing radon can lead to lung cancer. Drinking water containing radon may also cause increased risk of stomach cancer. If you are concerned about radon in your home, test the air in your home. Testing is inexpensive and easy. You should pursue radon removal for your home if the level of radon in your air is 4 picocuries per liter of air (pCi/L) or higher. For additional information, call the State Radon Program (1-800-745-7236), the USEPA Safe Drinking Water Hotline (1-800-426-4791), or the National Radon Hotline (1-800-767-7236).

Lead: If present, elevated levels of lead can cause serious health problems, especially for pregnant women, infants, and young children. Lead in drinking water is primarily from materials and components associated with service lines and household plumbing. The Authority is responsible for providing high quality drinking water, but cannot control the variety of materials used in household plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to two minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested.

Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the USEPA Safe Drinking Water Hotline (1-800-426-4791) or at www.epa.gov/lead.

Fluoride is a naturally occurring mineral found in both surface water and groundwater. Fluoridation is the addition of fluoride to a drinking water supply so that it contains the level recommended for optimal protection against tooth decay. California law mandates fluoridation. Public water systems with at least 10,000 service connections are required, once funded, to fluoridate their drinking water. The Authority began fluoridation of the water supply delivered to customers in January 2017. This action is in compliance with the State Water Board Regulations Related to Drinking Water (Section 64433). State regulations require the fluoride levels in the treated water be maintained within a concentration range of 0.6 mg/L to 1.2 mg/L with the optimal target dose set at 0.7 mg/L, which is considered to provide optimal oral health benefits. Additional information about fluoridation is available from the State Water Board Division of Drinking Water at www.swrcb.ca.gov/drinking_water/certlic/drinkingwater/Fluoridation.shtml.

2 TABLE DEFINITIONS

AL = Regulatory Action Level: The concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow (AL now applies only to lead and copper).

MCL = Maximum Contaminant Level: The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible. Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.

MCLG = Maximum Contaminant Level Goal: The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by the USEPA.

MRDL = Maximum Residual Disinfectant Level: The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

MRDLG = Maximum Residual Disinfectant Level Goal: The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

NA = Not Applicable (No standard specified or no monitoring required)

ND = Not Detected

NL = Regulatory Notification Level: (previously known as Action Level). The concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow.

pCi/l = picoCuries per liter (a measure of radiation).

PDWS = Primary Drinking Water Standard: MCLs and MRDLs for contaminants that affect health along with their monitoring and reporting requirements, and water treatment requirements.

PHG = Public Health Goal: The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California Environmental Protection Agency (CalEPA).

ppb = Parts per billion or micrograms per liter.

ppm = Parts per million or milligrams per liter.

ppt = Parts per trillion or nanograms per liter.

TT = Treatment Technique: A required process intended to reduce the level of a contaminant in drinking water.

3 FOOTNOTES

1. Sweetwater Authority drinking water data is representative of water which has been processed through the Robert A. Perdue Water Treatment Plant (conventional treatment) or the Richard A. Reynolds Groundwater Desalination Facility (reverse osmosis treatment).

2. The contaminants listed are in the untreated waters. The water is processed through either a reverse osmosis filtration plant (Reynolds Groundwater Desalination Facility) or through a conventional water treatment plant (Perdue Water Treatment Plant). These water treatment applications typically remove these contaminants to concentrations below detectable levels.

2a. This contaminant was not detected in the Reynolds Desalination Facility finished water; contaminant not determined in the Robert A. Perdue Water Treatment Plant finished water.

3. The State Water Board allows the Authority to monitor for some contaminants less than once per year because the concentrations of the contaminants do not change frequently. Radiological data on untreated source waters was collected in 2006-2007, 2017-2019. Lead and Copper data was collected in July 2017. Compliance with the lead and copper action levels is determined at the 90th percentile.

4. Reported value represents a single measurement; therefore, the range and average are the same.

5. Unregulated contaminant monitoring helps USEPA and the State Water Board to determine where certain contaminants occur and whether the contaminants need to be regulated.

On March 15, 2019 the State Water Board, Division of Drinking Water issued an Order requiring the Authority to conduct quarterly monitoring for one year for per- and poly-flourinated alkyl substances (PFAS) at three San Diego Formation Wells (SDF 1, 2, and 6), which are used as a source of supply to the Reynolds Desalination Facility. These wells were selected because they are located in proximity to an abandoned landfill in National City. Of the PFAS chemicals, perfluorooctanoic acid (PFOA) and perfluorooctane sulfonic acid (PFOS) have been the most extensively studied and DDW has assigned health-based notification levels of 5.1 and 6.5 parts per trillion (ppt) respectively to these chemicals. In addition, the State Water Board is currently in the process of developing public health goals (PHGs) and maximum contaminant levels (MCLs) for PFOS and PFOA. In 2019, both PFOA and PFOS were detected in SDF2 above their respective notification levels, however the reverse osmosis technology used at the Reynolds Desalination Facility effectively removes these chemicals to below detectable levels, therefore there was no impact to our customers and no notification was required. This was confirmed with the State Water Board by sampling the Reynolds Desalination Facility finished water, which showed that none of the 18 PFAS chemicals tested by EPA Method 537.1 were detected. For more information on PFAS, visit www.sweetwater.org/wq.

6. MRDL compliance for chloramines is determined on a system-wide basis by calculating a running annual average of all distribution sampling point averages. MCL compliance for trihalomethanes (TTHMs) and haloacetic acids (HAAs)

is determined by calculating a quarterly locational running annual average at each Stage 2 DBP Rule monitoring location. MCL compliance for chlorine dioxide is based on daily samples at the entrance to the distribution system and follow-up distribution system monitoring following an MRDL exceedance. MCL compliance for chlorite is based on daily samples at the entrance to the distribution system, monthly distribution system monitoring, and follow-up/confirmation sampling following an MCL exceedance.

7. Cryptosporidium (Crypto) monitoring. In 2019, Crypto was not detected in Sweetwater Reservoir. The last detection for Crypto in Sweetwater Reservoir occurred in August of 2005 (1.0 oocyst in 10 liters).

8. Aluminum and Turbidity have both a primary and a secondary MCL.

9. Radon was sampled in 2000 for San Diego Formation Wells 1-5, in 2001 for the National City Wells 2 and 3, and in 2008 for San Diego Formation Well 6 and National City Well 4.

10. Fluoride - The Authority treats your water by adding fluoride to the naturally occurring level to help prevent tooth decay in consumers. State regulations require the fluoride levels in the treated water be maintained within a concentration range of 0.6 mg/L to 1.2 mg/L with an optimal target dose set at 0.7 mg/L, which is considered to provide optimal oral health benefits. In 2019, the Authority's monitoring showed fluoride levels in the (fluoridated) treated water ranged from 0.5 mg/L to 0.9 mg/L, with an average of 0.7 mg/L. Information about fluoridation, oral health and current issues is available at www.swrcb.ca.gov/drinking_water/certlic/drinkingwater/Fluoridation.shtml.

11. School Lead Testing - In January 2017, the State Water Board issued an amended permit to all public water systems in California, requiring them to sample for lead at all K-12 schools within their service area. Under this mandate, school officials can request in writing that their local water agency sample their school for lead. The written request must be submitted by November 1, 2019. In 2017, the Authority received requests from 46 schools (out of a total of 67 eligible schools) for lead sampling. The Authority worked with those schools to develop sampling plans and conduct testing. In 2018, no schools submitted written requests for lead testing. In 2019 two schools were tested as required by California Assembly Bill 746 (AB746). The Authority has now completed the school lead sampling requirements as specified by the Authority's Water Supply Permit Amendment and AB746. Please contact the Water Treatment Superintendent at 619-409-6812 to obtain a summary of the lead testing results.

(a) Compliance with the radiological MCLs is typically based upon samples collected every three to nine years (depending on previous monitoring results), unless waived by the State Water Board. Compliance with the gross alpha MCL is determined by excluding the values for radon and uranium. The State Water Board considers 50 pCi/L to be the level of concern for beta particles. The MCL for radium is for the combination of the "226" and "228" isotopes.

(b) The turbidity level of the filtered water shall be less than or equal to 0.3 NTU (Nephelometric Turbidity Units) in 95 percent of the measurements taken each month and shall not exceed 1.0 NTU for more than eight consecutive hours or 1 NTU for more than one continuous hour and none of the 4-hour interval readings shall exceed 1 NTU.

Turbidity is a measure of the cloudiness of the water. The Authority monitors turbidity because it is a good indicator of the effectiveness of our filtration system.

(c) Quarterly UCMR3 monitoring was conducted in 2014-2015. UCMR3 monitoring consisted of 28 List 1 and List 2 chemicals. Of these, only chlorate, vanadium, molybdenum, and strontium were detected. In addition to UCMR3, the Authority routinely monitors for vanadium as an unregulated contaminant and for chlorate as part of the Disinfection By-products Rule.

Quarterly UCMR4 monitoring was conducted in 2018 - 2019 for the 17 List 1 chemicals and the 11 List 2 chemicals. Of these, only TOC, bromide, manganese, and haloacetic acids were detected. For UCMR4, the haloacetic acids are reported in three groups (HAA5, HAA6Br, and HAA9), as follows:

HAA5 equals the sum of monochloroacetic acid, dichloroacetic acid, trichloroacetic acid, monobromoacetic acid, and dibromoacetic acid.

HAA6Br equals the sum of monobromoacetic acid, dibromoacetic acid, bromochloroacetic acid, bromodichloroacetic acid, chlorodibromoacetic acid, and tribromoacetic acid.

HAA9 equals the sum of monochloroacetic acid, dichloroacetic acid, trichloroacetic acid, monobromoacetic acid, dibromoacetic acid, bromochloroacetic acid, bromodichloroacetic acid, chlorodibromoacetic acid, and tribromoacetic acid.

In addition to UCMR4, the Authority routinely monitors for HAA5 and TOC as part of the Disinfection By-products Rule.

(d) Please note, starting in 2016, the State Water Board required California public water systems to be in simultaneous compliance with both the CA TCR and the Federal RTCR criteria listed below.

State of California Total Coliform Rule (CA TCR) - Total coliform MCL: No more than 5.0% of the monthly samples may be total coliform positive. Acute coliform (*E.coli*) MCL: A routine sample and a repeat sample are total coliform positive, and one of these is also *E.coli* positive. The Authority did not violate either MCL in 2019. Results are based on the distribution system's highest monthly percent positives. Compliance is based on the combined distribution system sampling from all treatment plants. In 2019, 1,914 samples were analyzed.

Federal Revised Total Coliform Rule (RTCR) - Total Coliform TT trigger, Level 1 assessments, and total coliform TT violations: More than 5.0% total coliform positive samples in a month trigger a Level 1 assessment. Failure to conduct

FOOTNOTES CONT.

an assessment and take corrective action within 30 days is a total coliform violation. In 2019, no triggers, Level 1 assessments, or violations occurred.

E.coli MCL and Level 2 TT triggers for assessments: Routine and repeat samples are total coliform positive and either sample is *E.coli* positive or the system fails to collect all repeat samples following an *E.coli* positive sample, or fails to test for *E.coli* when the repeat sample is total coliform positive. In 2019, no samples were *E.coli* positive and no MCL violations or assessments occurred.

4 WATER AGENCIES DELIVER MAJOR PUBLIC HEALTH BENEFIT

A clean water supply is the norm thanks to modern water treatment

Modern treatment techniques have improved water supplies to the point where people often take the safety of tap water for granted.

However, ensuring water quality is a big commitment. Local and regional water agencies work around-the-clock to make sure customers have safe, reliable drinking water.

A century ago, however, many people did not have access to safe, reliable water. That was why filtration and chlorination systems were first installed in municipal water systems.

That seemingly basic service made a profound difference; U.S. life expectancy increased and child mortality decreased. Once-common diseases such as cholera and typhoid have been essentially wiped out.

Continuous advances in technology have allowed water agencies to adopt increasingly sophisticated ways of preventing harmful levels of bacteria and chemicals from fouling water supplies.

Federal and state agencies oversee the testing process, periodically setting more stringent safeguards. Over the past 30 years, the number of regulated contaminants in potable water has nearly quadrupled; and contaminant levels that once were measured in parts per million are now traced to parts per billion – giving consumers an even greater margin of safety.

The entire process has delivered a major public health benefit, a real value that customers help pay for a little at a time.

Public water providers just charge what it costs to deliver safe supplies

Every few months when corporations publicly announce their revenues, shareholders expect a big return. Some multi-national energy companies routinely post annual profits in the billions.

Not so for the public agencies which deliver another crucial resource – water – right to your home or business every day. They make $0 profit annually. In fact, agencies such as the Authority are legally required to charge only what it costs to treat and deliver drinking water.

All the money collected is invested into the pumps, pipes, and other elements of the water system. The system is complex, and includes securing supplies; pumping, moving, treating, and testing water; maintaining and financing infrastructure; and establishing financial reserves for emergencies and paying for environmental enhancements or mitigation.

Related costs have grown over time due to a variety of factors, such as increases in the price of energy and treatment chemicals. Local water suppliers are also strategically increasing the use of local sources, such as recycled water and groundwater, to buffer our region from shortages.


In all those efforts, customers of public water agencies can be confident that they are paying the actual costs of providing safe and reliable water service – a real value day in and day out.

The Authority is committed to maintaining a safe and reliable supply of drinking water for current and future customers.

5 UNDERSTANDING WATER

Water quality standards are measured in “parts per million” or “parts per billion.” But those terms can be difficult to relate to, and it’s hard to know what they mean. This chart can help you visualize the proportions in terms of some ordinary items.

Source: USEPA; Alaska Department of Environmental Conservation; Sweetwater Authority

ITEM		PARTS PER MILLION	PARTS PER BILLION
Linear Measure		1 inch in 15.78 miles	1 inch in 15,780 miles
Time		1 minute in 1.9 years	1 minute in 1,902 years
Money		1 cent in $10,000	1 cent in $10 million
1 drop of water		1 drop in a half-full bathtub	1 drop in an Olympic-size swimming pool

MISSION

The mission of Sweetwater Authority is to provide our current and future customers with a safe and reliable water supply through the use of the best available technology, sound management practices, public participation and a balanced approach to human and environmental needs.

VISION

Sweetwater Authority is a premier water agency. We partner with public and private sectors to maximize value for our rate payers. Our water system infrastructure is innovative, yet functional, practical and cost-effective. We provide a reliable and sustainable source of water. We consistently deliver industry-leading service to our customers.



Sweetwater Authority
505 Garrett Avenue
Chula Vista, CA 91910
619-420-1413

twitter @sweetwaterauth
facebook.com/swawater
linkedin.com/company/sweetwater-authority
youtube.com/user/SweetwaterAuthority

APPENDIX C: REGULATORY DATABASE REPORT

PARTNER

Parcel B Buildings - Former Collins Aerospace
South of G Street
Chula Vista, CA 91910

Inquiry Number: 6326895.2s
January 11, 2021

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	712
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-6
Physical Setting Source Map	A-15
Physical Setting Source Map Findings	A-17
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

SOUTH OF G STREET
CHULA VISTA, CA 91910

COORDINATES

Latitude (North):	32.6300140 - 32° 37' 48.05''
Longitude (West):	117.1002050 - 117° 6' 0.73''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	490600.2
UTM Y (Meters):	3610086.0
Elevation:	12 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5629176 NATIONAL CITY, CA
Version Date:	2012
Southeast Map:	5622818 IMPERIAL BEACH, CA
Version Date:	2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140530
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
SOUTH OF G STREET
CHULA VISTA, CA 91910

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
1	CHULA VISTA BAYFRONT	SAN DIEGO BAYFRONT	CPS-SLIC, CERS	Lower	1 ft.
A2	COMMANDER NAVY REGIO	868 G ST	RCRA-LQG, FINDS, ECHO	Lower	1 ft.
B3	ROHR AIRCRAFT	FOOT OF H STREET	ENVIROSTOR	Higher	1 ft.
B4	ROHR TIES ROHR INDUS	FOOT OF H STREET ADJ	HIST UST	Higher	1 ft.
A5	DERILICT VESSEL STOR	891 G ST	RCRA-LQG, FINDS, ECHO	Lower	40, 0.008, NW
C6	PARTY CITY CORP DBA	865 H STREET	RCRA NonGen / NLR	Higher	131, 0.025, ESE
C7	BAY BLVD PROJECTS	NONE BAY BL	CPS-SLIC, CERS	Higher	300, 0.057, East
C8	UNIVERSITY COGENERAT	H ST	LUST, San Diego Co. HMMD	Higher	381, 0.072, ESE
9	MHE REPAIR FACILITY	596A SANDPIPER WAY	RCRA-SQG	Lower	434, 0.082, SSW
10	LAWLESS	390 BAY BLVD	HIST UST	Higher	447, 0.085, NNE
11	ROHR INDUSTRIES INC	H ST	SAN DIEGO CO. SAM, SAN DIEGO CO LOP	Higher	711, 0.135, SE
D12	CITY OF CHULA VISTA	350-360 BAY BOULEVAR	ENVIROSTOR	Higher	805, 0.152, NNE
E13	THOMAS DINANNO	550 MARINA PKWY	RCRA-SQG	Lower	817, 0.155, South
E14	CHULA VISTA MARINA	550 MARINA PKWY	RCRA NonGen / NLR	Lower	817, 0.155, South
E15	CHULA VISTA MARINA	550 MARINA PY	San Diego Co. HMMD, CERS HAZ WASTE, HAZNET, CERS,...	Lower	817, 0.155, South
F16	AGUNDEZ CLAUDIA	410 COLORADO AVE #C	RCRA NonGen / NLR	Higher	888, 0.168, NE
G17	GBAHE TRAZIE	456 COLORADO AVENUE	RCRA NonGen / NLR	Higher	889, 0.168, ENE
D18	FORMERLY THERMO KING	340 BAY BL	SAN DIEGO CO. SAM, CPS-SLIC, CERS	Higher	898, 0.170, NNE
D19	FORMER THERMO-KING F	340 BAY BLVD	CPS-SLIC	Higher	898, 0.170, NNE
D20	THERMO KING OF SAN D	340 BAY BOULEVARD	SEMS-ARCHIVE	Higher	898, 0.170, NNE
H21	MANNS TEXACO & U-HAU	730 H ST	San Diego Co. HMMD, SWEEPS UST	Higher	912, 0.173, East
H22	FORMER EXXONMOBIL /	745 H ST	CPS-SLIC, CERS	Higher	979, 0.185, East
H23	EXXONMOBIL OIL CORP	745 H STREET	RCRA-SQG	Higher	979, 0.185, East
H24	MTDB	745 H ST	SAN DIEGO CO. SAM, CPS-SLIC, SAN DIEGO CO LOP,...	Higher	979, 0.185, East
H25	H STREET TRANSIT STA	745 H ST	RCRA-SQG	Higher	979, 0.185, East
F26	MC INVESTMENT PARTNE	423 COLORADO AVE	RCRA NonGen / NLR	Higher	1019, 0.193, ENE
G27	THE NAJAR FAMILY TRU	455 COLORADO AVE, UN	RCRA NonGen / NLR	Higher	1020, 0.193, ENE
G28	ARCELIA GONZALEZ	455 COLORADO AVE UNI	RCRA NonGen / NLR	Higher	1020, 0.193, ENE
G29	RYAN ABIDES	443 COLORADO AVE	RCRA NonGen / NLR	Higher	1020, 0.193, ENE
F30	DASHAWN PALMER	724 G ST	RCRA NonGen / NLR	Higher	1035, 0.196, NE
G31	MC INVESTMENT PARTNE	467 COLORADO AVE	RCRA NonGen / NLR	Higher	1035, 0.196, East
H32	ARCO MINI MARKET	720 H ST	LUST, San Diego Co. HMMD, CERS HAZ WASTE, CERS...	Higher	1074, 0.203, East
H33	DONN SWARTZ	720 H ST 1914	SWEEPS UST	Higher	1074, 0.203, East
H34	TESORO 97610-1914	720 H ST	RCRA NonGen / NLR	Higher	1074, 0.203, East
H35	RALPH E EMARINE DBA	720 H STREET	HIST UST	Higher	1074, 0.203, East
H36	RALPH E EMARINE	720 H ST	HIST UST	Higher	1074, 0.203, East
H37	"H" STREET ARCO	720 H ST	UST	Higher	1074, 0.203, East
H38	GS & SS PETROLIUM IN	720 H ST	RCRA NonGen / NLR	Higher	1074, 0.203, East
H39	ARCO AM/PM MINI MARK	720 H ST	SAN DIEGO CO. SAM, UST, Cortese, SAN DIEGO CO LOP,...	Higher	1074, 0.203, East

MAPPED SITES SUMMARY

Target Property Address:
SOUTH OF G STREET
CHULA VISTA, CA 91910

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
I40	THE MARINE GROUP, LL	997 G STREET	CPS-SLIC, CERS	Lower	1080, 0.205, West
I41	MARINE GROUP BOAT WO	997 G ST	AST, San Diego Co. HMMD, CERS HAZ WASTE, CERS...	Lower	1080, 0.205, West
I42	SOUTH BAY BOAT YARD	997 G	SEMS-ARCHIVE	Lower	1080, 0.205, West
I43	PACIFIC YACHT REFITT	997 G ST	RCRA-SQG, HAZNET, HWTS	Lower	1080, 0.205, West
I44	PACIFIC YACHT REFITT	997 G ST	AST, San Diego Co. HMMD	Lower	1080, 0.205, West
I45	MARINE GROUP BOAT WO	997 G ST	RCRA-LQG	Lower	1080, 0.205, West
I46	SOUTH BAY BOILER REP	997 G ST	RCRA NonGen / NLR	Lower	1080, 0.205, West
I47	MARINE GROUP BOAT WO	997 G ST	RCRA-SQG	Lower	1080, 0.205, West
G48	RON MARTIN	456 WOODAWN AVE	RCRA NonGen / NLR	Higher	1145, 0.217, ENE
I49	WILLIAM D. EVANS STE	996 G. STREET	RCRA NonGen / NLR	Higher	1271, 0.241, West
I50	SC COMMERCIAL	996 G. ST	RCRA NonGen / NLR	Higher	1271, 0.241, West
51	WILLIAM KEMERY	415 WOODLAWN AVE	RCRA NonGen / NLR	Higher	1280, 0.242, ENE
J52	RADOS, CHULA VISTA C	798 F ST	SAN DIEGO CO. SAM, CPS-SLIC, CERS	Higher	1285, 0.243, North
K53	ROHR INC A COLLINS A	850 LAGOON DR MAIL Z	RCRA-LQG, CHMIRS, TRIS, PADS, ICIS, US AIRS,...	Higher	1312, 0.248, NNW
K54	GOODRICH AEROSTRUCTU	850 LAGOON DRIVE	CPS-SLIC	Higher	1312, 0.248, NNW
K55	BF GOODRICH, AEROSTR	850 LAGOON DRIVE	CPS-SLIC	Higher	1312, 0.248, NNW
K56	ROHR INC., A COLLINS	850 LAGOON DR	CERS HAZ WASTE, CERS TANKS, CERS, HWTS	Higher	1312, 0.248, NNW
K57	ROHR IND INC	FOOT OF H ST	SEMS-ARCHIVE	Higher	1312, 0.248, NNW
K58	GOODRICH AEROSTRUCTU	850 LAGOON DRIVE	RCRA NonGen / NLR	Higher	1312, 0.248, NNW
K59	GOODRICH AEROSTRUCTU	850 LAGOON DRIVE	CPS-SLIC, CERS	Higher	1312, 0.248, NNW
K60	ROHR INC., A UTC AER	850 LAGOON DR	AST	Higher	1312, 0.248, NNW
K61	BF GOODRICH AEROSPAC	850 LAGOON DR	LUST, CPS-SLIC, AST, CHMIRS, Cortese, EMI, CERS	Higher	1312, 0.248, NNW
K62	BF GOODRICH, AEROSTR	850 LAGOON DRIVE	CPS-SLIC, CHMIRS	Higher	1312, 0.248, NNW
K63	SAN DIEGO UNIFIED PO	850 LAGOON DRIVE	RCRA-SQG	Higher	1312, 0.248, NNW
K64	GOODRICH AEROSTRUCTU	850 LAGOON DRIVE	CPS-SLIC	Higher	1312, 0.248, NNW
K65	ROHR INC., A UTC AER	850 LAGOON DR	UST	Higher	1312, 0.248, NNW
L66	CHEVRON #9-6056	695 H ST	SAN DIEGO CO. SAM, UST, San Diego Co. HMMD, SAN...	Higher	1325, 0.251, East
L67	CHEVRON #9-6056	695 H ST	LUST, CPS-SLIC, SWEEPS UST, Cortese, EMI, HIST...	Higher	1325, 0.251, East
68	F & G STREET MARSH	LAGOON DR. & MARINA	SWF/LF, CERS	Higher	1332, 0.252, NW
K69	ROHR F ST PROPERTY	F ST	SAN DIEGO CO. SAM, San Diego Co. HMMD, SAN DIEGO...	Higher	1347, 0.255, NNW
J70	RADOS	798 LAGOON DR. (FORM	ENVIROSTOR	Higher	1356, 0.257, North
M71	SEDIMENT OFF FORMER	980 LAGOON DRIVE	CPS-SLIC, CERS	Higher	1373, 0.260, NW
M72	FORMER SHANGRILA SIT	980 LAGOON DR	SAN DIEGO CO. SAM, CPS-SLIC, San Diego Co. HMMD,...	Higher	1373, 0.260, NW
J73	LAGOON DRIVE CHEMICA	BAY BLVD. & LAGOON D	SEMS-ARCHIVE, PRP	Higher	1396, 0.264, North
M74	SAN DIEGO SHIP BUILD	980 F STREET	SEMS-ARCHIVE	Higher	1415, 0.268, NW
N75	ROHR AIRCRAFT CORP.		FUDS	Higher	1485, 0.281, SE
N76	ROHR AIRCRAFT CORP		ENVIROSTOR	Higher	1489, 0.282, SE
O77	SWEETWATER AUTHORITY	744 F ST	LUST, SAN DIEGO CO. SAM, CPS-SLIC, AST, San Diego...	Higher	1536, 0.291, NNE
M78	FLUID SYSTEMS	965 F ST	ENVIROSTOR, LUST, SAN DIEGO CO. SAM, San Diego Co....	Higher	1550, 0.294, NW

MAPPED SITES SUMMARY

Target Property Address:
SOUTH OF G STREET
CHULA VISTA, CA 91910

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
L79	WORLD OIL MARKETING	685 H ST	SAN DIEGO CO. SAM, UST, San Diego Co. HMMD, CERS...	Higher	1567, 0.297, East
L80	WORLD OIL STATION #4	685 H ST	LUST	Higher	1567, 0.297, East
L81	WORLD OIL #46	685 H ST	LUST, Cortese, HIST CORTESE, CERS	Higher	1567, 0.297, East
O82	PRUDENTIAL OVERALL S	740 F ST	Cortese, HAZNET, HWTS	Higher	1612, 0.305, NNE
O83	PRUDENTIAL OVERALL S	740 F STREET	RCRA-SQG, LUST, SAN DIEGO CO. SAM, San Diego Co....	Higher	1612, 0.305, NNE
P84	THRIFTY OIL COMPANY	666 H ST	LUST, SAN DIEGO CO. SAM, San Diego Co. HMMD,...	Higher	1723, 0.326, East
P85	THRIFTY SERIVCE STAT	666 H ST	LUST	Higher	1723, 0.326, East
Q86	CHULA VISTA CITY PUB	707 F STREET	CPS-SLIC, CERS	Higher	1832, 0.347, NNE
Q87	CITY OF CHULA VISTA	707 F STREET	LUST	Higher	1832, 0.347, NNE
Q88	CHULA VISTA,CITY OF,	707 F ST	WMUDS/SWAT	Higher	1832, 0.347, NNE
Q89	CHULA VISTA, PUBLIC	707 F STREET	Toxic Pits	Higher	1832, 0.347, NNE
Q90	CITY OF CHULA VISTA	707 F STREET	LUST, SAN DIEGO CO. SAM, CPS-SLIC, San Diego Co....	Higher	1832, 0.347, NNE
R91	VACANT PROPERTY OWNE	MARINA PARKWAY	CPS-SLIC, CERS	Lower	1918, 0.363, South
R92	CHULA VISTA BAYFRONT	MARINA PARKWAY	CPS-SLIC, DEED	Higher	2177, 0.412, SSE
S93	CHULA VISTA BAYFRONT	215 BAY BOULEVARD	CPS-SLIC, CERS	Higher	2515, 0.476, North
94	WOODLAWN COLONIAL AP	245-255 WOODLAWN AVE	ENVIROSTOR, VCP	Higher	2520, 0.477, NNE
S95	U S FISH AND WILDLIF	NONE E ST(FOOT OF)	CPS-SLIC, CERS	Higher	2573, 0.487, North
T96	H STREET AUTO WASH	498 BROADWAY	LUST, CPS-SLIC, HIST UST, Cortese, SAN DIEGO CO...	Higher	2608, 0.494, East
T97	OPTIMA CAR WASH	498 BROADWAY	SAN DIEGO CO. SAM, UST, San Diego Co. HMMD, CERS...	Higher	2608, 0.494, East
T98	H STREET CAR WASH	498 BROADWAY	LUST, SWEEPS UST, HIST CORTESE	Higher	2608, 0.494, East
99	E STREET PLAZA SHOPP	640-692 E STREET	ENVIROSTOR	Higher	3203, 0.607, NNE
100	CHERNISS TIRE WORLD	101 BROADWAY	LUST, SAN DIEGO CO. SAM, San Diego Co. HMMD, CERS...	Higher	4813, 0.912, NNE
101	CHULA VISTA LEARNING	821/824 BROADWAY/562	ENVIROSTOR, SCH	Higher	4870, 0.922, SE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-VSQG ---------- RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State- and tribal - equivalent NPL

RESPONSE ---------- State Response Sites

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS ---------- Considered Brownfieds Sites Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY ---------- Recycler Database
HAULERS ---------- Registered Waste Tire Haulers Listing
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
ODI ---------- Open Dump Inventory
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
HIST Cal-Sites ---------- Historical Calsites Database
SCH ---------- School Property Evaluation Program
CDL ---------- Clandestine Drug Labs
San Diego Co. HMMD ---------- Hazardous Materials Management Division Database
US CDL ---------- National Clandestine Laboratory Register
PFAS ---------- PFAS Contamination Site Location Listing

Local Lists of Registered Storage Tanks

CA FID UST ---------- Facility Inventory Database

Local Land Records

LIENS ---------- Environmental Liens Listing

LIENS 2	CERCLA Lien Information

Records of Emergency Release Reports

HMIRS	Hazardous Materials Information Reporting System
CHMIRS	California Hazardous Material Incident Report System
LDS	Land Disposal Sites Listing
MCS	Military Cleanup Sites Listing
SPILLS 90	SPILLS 90 data from FirstSearch

Other Ascertainable Records

DOD	Department of Defense Sites
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR	Financial Assurance Information
EPA WATCH LIST	EPA WATCH LIST
2020 COR ACTION	2020 Corrective Action Program List
TSCA	Toxic Substances Control Act
TRIS	Toxic Chemical Release Inventory System
SSTS	Section 7 Tracking Systems
ROD	Records Of Decision
RMP	Risk Management Plans
RAATS	RCRA Administrative Action Tracking System
PRP	Potentially Responsible Parties
PADS	PCB Activity Database System
ICIS	Integrated Compliance Information System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
FUSRAP	Formerly Utilized Sites Remedial Action Program
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US AIRS	Aerometric Information Retrieval System Facility Subsystem
US MINES	Mines Master Index File
ABANDONED MINES	Abandoned Mines
FINDS	Facility Index System/Facility Registry System
UXO	Unexploded Ordnance Sites
ECHO	Enforcement & Compliance History Information
DOCKET HWC	Hazardous Waste Compliance Docket Listing
FUELS PROGRAM	EPA Fuels Program Registered Listing
CA BOND EXP. PLAN	Bond Expenditure Plan
CUPA Listings	CUPA Resources List
DRYCLEANERS	Cleaner Facilities
EMI	Emissions Inventory Data
ENF	Enforcement Action Listing
Financial Assurance	Financial Assurance Information Listing
HAZNET	Facility and Manifest Data

ICE ICE
HWP EnviroStor Permitted Facilities Listing
HWT Registered Hazardous Waste Transporter Database
MINES Mines Site Location Listing
MWMP Medical Waste Management Program Listing
NPDES NPDES Permits Listing
PEST LIC Pesticide Regulation Licenses Listing
PROC Certified Processors Database
UIC UIC Listing
UIC GEO UIC GEO (GEOTRACKER)
WASTEWATER PITS Oil Wastewater Pits Listing
WDS Waste Discharge System
WIP Well Investigation Program Case List
MILITARY PRIV SITES MILITARY PRIV SITES (GEOTRACKER)
PROJECT PROJECT (GEOTRACKER)
WDR Waste Discharge Requirements Listing
SAN DIEGO CO LOP Local Oversight Program Listing
CIWQS California Integrated Water Quality System
CERS CERS
NON-CASE INFO NON-CASE INFO (GEOTRACKER)
OTHER OIL GAS OTHER OIL & GAS (GEOTRACKER)
PROD WATER PONDS PROD WATER PONDS (GEOTRACKER)
SAMPLING POINT SAMPLING POINT (GEOTRACKER)
WELL STIM PROJ Well Stimulation Project (GEOTRACKER)
MINES MRDS Mineral Resources Data System
HWTS Hazardous Waste Tracking System

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants
EDR Hist Auto EDR Exclusive Historical Auto Stations
EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF Recovered Government Archive Solid Waste Facilities List
RGA LUST Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 10/28/2020 has revealed that there are 5 SEMS-ARCHIVE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
THERMO KING OF SAN D Site ID: 0904766 EPA Id: CAD983658428	340 BAY BOULEVARD	NNE 1/8 - 1/4 (0.170 mi.)	D20	58
ROHR IND INC Site ID: 0901097 EPA Id: CAD008382053	FOOT OF H ST	NNW 1/8 - 1/4 (0.248 mi.)	K57	334
LAGOON DRIVE CHEMICA SAN DIEGO SHIP BUILD Site ID: 0905282 EPA Id: CAD107568321	***BAY BLVD. & LAGOON D*** 980 F STREET	***N 1/4 - 1/2 (0.264 mi.)*** NW 1/4 - 1/2 (0.268 mi.)	***J73*** M74	***389*** 391

Lower Elevation	Address	Direction / Distance	Map ID	Page
SOUTH BAY BOAT YARD Site ID: 0904774 EPA Id: CAD983658451	997 G	W 1/8 - 1/4 (0.205 mi.)	I42	200

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/14/2020 has revealed that there are 4 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROHR INC A COLLINS A	***850 LAGOON DR MAIL Z***	***NNW 1/8 - 1/4 (0.248 mi.)***	***K53***	***244***

EPA ID:: CAD008382053

Lower Elevation	Address	Direction / Distance	Map ID	Page
COMMANDER NAVY REGIO EPA ID:: CAR000243360	***868 G ST***	***0 - 1/8 (0.000 mi.)***	***A2***	***10***
DERILICT VESSEL STOR EPA ID:: CAL000347973	***891 G ST***	***NW 0 - 1/8 (0.008 mi.)***	***A5***	***16***
MARINE GROUP BOAT WO EPA ID:: CAR000298620	997 G ST	W 1/8 - 1/4 (0.205 mi.)	I45	221

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/14/2020 has revealed that there are 7 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EXXONMOBIL OIL CORP EPA ID:: CAR000208108	745 H STREET	E 1/8 - 1/4 (0.185 mi.)	H23	64
H STREET TRANSIT STA EPA ID:: CAR000187492	745 H ST	E 1/8 - 1/4 (0.185 mi.)	H25	70
SAN DIEGO UNIFIED PO EPA ID:: CAC002577707	850 LAGOON DRIVE	NNW 1/8 - 1/4 (0.248 mi.)	K63	362

Lower Elevation	Address	Direction / Distance	Map ID	Page
MHE REPAIR FACILITY EPA ID:: CAR000014530	596A SANDPIPER WAY	SSW 0 - 1/8 (0.082 mi.)	9	23
THOMAS DINANNO EPA ID:: CAP000076059	550 MARINA PKWY	S 1/8 - 1/4 (0.155 mi.)	E13	32
PACIFIC YACHT REFITT EPA ID:: CAR000186155	***997 G ST***	***W 1/8 - 1/4 (0.205 mi.)***	***I43***	***201***
MARINE GROUP BOAT WO EPA ID:: CAL000017529	997 G ST	W 1/8 - 1/4 (0.205 mi.)	I47	228

State- and tribal - equivalent CERCLIS

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to,

identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 07/27/2020 has revealed that there are 8 ENVIROSTOR sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROHR AIRCRAFT Facility Id: 37370020 Status: Refer: Other Agency	FOOT OF H STREET	0 - 1/8 (0.000 mi.)	B3	14
CITY OF CHULA VISTA Facility Id: 37000027 Status: Refer: 1248 Local Agency	350-360 BAY BOULEVAR	NNE 1/8 - 1/4 (0.152 mi.)	D12	31
RADOS Facility Id: 37000014 Status: Refer: 1248 Local Agency	798 LAGOON DR. (FORM	N 1/4 - 1/2 (0.257 mi.)	J70	386
ROHR AIRCRAFT CORP Facility Id: 80000939 Status: Inactive - Needs Evaluation		SE 1/4 - 1/2 (0.282 mi.)	N76	392
FLUID SYSTEMS Facility Id: 37760082 Status: Refer: Local Agency	***965 F ST***	***NW 1/4 - 1/2 (0.294 mi.)***	***M78***	***426***
WOODLAWN COLONIAL AP Facility Id: 60001253 Status: No Further Action	***245-255 WOODLAWN AVE***	***NNE 1/4 - 1/2 (0.477 mi.)***	***94***	***634***
E STREET PLAZA SHOPP Facility Id: 60001334 Status: Active	640-692 E STREET	NNE 1/2 - 1 (0.607 mi.)	99	669
CHULA VISTA LEARNING Facility Id: 37880001 Status: No Further Action	***821/824 BROADWAY/562***	***SE 1/2 - 1 (0.922 mi.)***	***101***	***708***

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Integrated Waste Management Board's Solid Waste Information System (SWIS) database.

A review of the SWF/LF list, as provided by EDR, has revealed that there is 1 SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
F & G STREET MARSH Database: SAN DIEGO CO. LF, Date of Government Version: 04/18/2018 Database: SWF/LF (SWIS), Date of Government Version: 05/11/2020 Facility ID: 37-CR-0129 Operational Status: Closed Operational Status: CLOSED	***LAGOON DR. & MARINA***	***NW 1/4 - 1/2 (0.252 mi.)***	***68***	***383***

Regulation Status: Unpermitted
Facility Status: CLOSED SITES

State and tribal leaking storage tank lists

SAN DIEGO CO. SAM: The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

A review of the SAN DIEGO CO. SAM list, as provided by EDR, and dated 03/23/2010 has revealed that there are 15 SAN DIEGO CO. SAM sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROHR INDUSTRIES INC	***H ST***	***SE 1/8 - 1/4 (0.135 mi.)***	***11***	***27***
Case Number: H02457-001				
Case Number: H02457-002				
Case Number: H02457-003				
Case Number: H02457-004				
Case Number: H02457-005				
**Additional key fields are available in the Map Findings section*				
Facility Status: Preliminary Assessment				
Facility Status: Remedial Investigation				
Facility Status: Closed Case				
FORMERLY THERMO KING	***340 BAY BL***	***NNE 1/8 - 1/4 (0.170 mi.)***	***D18***	***56***
Case Number: H31018-001				
Facility Status: Closed Case				
MTDB	***745 H ST***	***E 1/8 - 1/4 (0.185 mi.)***	***H24***	***68***
Case Number: H39642-001				
Case Number: H39642-002				
Facility Status: Remedial Investigation				
ARCO AM/PM MINI MARK	***720 H ST***	***E 1/8 - 1/4 (0.203 mi.)***	***H39***	***135***
Case Number: H20106-001				
Facility Status: Remedial Action (Clean-Up)				
RADOS, CHULA VISTA C	***798 F ST***	***N 1/8 - 1/4 (0.243 mi.)***	***J52***	***242***
Case Number: H39651-001				
Case Number: H39651-002				
Facility Status: Closed Case				
CHEVRON #9-6056	***695 H ST***	***E 1/4 - 1/2 (0.251 mi.)***	***L66***	***366***
Case Number: H13127-001				
Facility Status: Closed Case				
ROHR F ST PROPERTY	***F ST***	***NNW 1/4 - 1/2 (0.255 mi.)***	***K69***	***384***
Case Number: H31398-001				
Facility Status: Preliminary Assessment				
FORMER SHANGRILA SIT	***980 LAGOON DR***	***NW 1/4 - 1/2 (0.260 mi.)***	***M72***	***388***
Case Number: H37165-001				
Facility Status: Closed Case				
SWEETWATER AUTHORITY	***744 F ST***	***NNE 1/4 - 1/2 (0.291 mi.)***	***O77***	***393***
Case Number: H20099-001				
Facility Status: Closed Case				
FLUID SYSTEMS	***965 F ST***	***NW 1/4 - 1/2 (0.294 mi.)***	***M78***	***426***

Case Number: H32432-001
Case Number: H32432-002
Case Number: H32432-003
Facility Status: Closed Case

WORLD OIL MARKETING ***685 H ST*** ***E 1/4 - 1/2 (0.297 mi.)*** ***L79*** ***434***
Case Number: H03739-001
Case Number: H03739-002
Facility Status: Remedial Investigation
Facility Status: Closed Case

PRUDENTIAL OVERALL S ***740 F STREET*** ***NNE 1/4 - 1/2 (0.305 mi.)*** ***O83*** ***484***
Case Number: H11432-001
Case Number: H11432-002
Facility Status: Remedial Action (Clean-Up)
Facility Status: Closed Case

THRIFTY OIL COMPANY ***666 H ST*** ***E 1/4 - 1/2 (0.326 mi.)*** ***P84*** ***531***
Case Number: H20174-001
Facility Status: Remedial Investigation

CITY OF CHULA VISTA ***707 F STREET*** ***NNE 1/4 - 1/2 (0.347 mi.)*** ***Q90*** ***545***
Case Number: H04568-001
Case Number: H04568-002
Case Number: H04568-003
Case Number: H04568-004
Case Number: H04568-005
Facility Status: Preliminary Assessment
Facility Status: Closed Case

OPTIMA CAR WASH ***498 BROADWAY*** ***E 1/4 - 1/2 (0.494 mi.)*** ***T97*** ***647***
Case Number: H05368-001
Case Number: H05368-002
Case Number: H05368-003
Facility Status: Remedial Investigation
Facility Status: Closed Case

LUST: Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the LUST list, as provided by EDR, has revealed that there are 15 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UNIVERSITY COGENERAT	***H ST***	***ESE 0 - 1/8 (0.072 mi.)***	***C8***	***22***
Database: LUST REG 9, Date of Government Version: 03/01/2001 Status: Preliminary site assessment underway Case Number: 9UT3961				
ARCO MINI MARKET	***720 H ST***	***E 1/8 - 1/4 (0.203 mi.)***	***H32***	***87***
Database: LUST REG 9, Date of Government Version: 03/01/2001 Database: LUST, Date of Government Version: 09/08/2020 Status: Completed - Case Closed Status: Preliminary site assessment underway Global Id: T0607301869 Case Number: 9UT3103				
BF GOODRICH AEROSPAC	***850 LAGOON DR***	***NNW 1/8 - 1/4 (0.248 mi.)***	***K61***	***340***
Database: LUST REG 9, Date of Government Version: 03/01/2001 Database: LUST, Date of Government Version: 09/08/2020				

Status: Completed - Case Closed
Global Id: T0607302732
Global Id: T0607300932
Global Id: T0607301766
Global Id: T0607301464

CHEVRON #9-6056 ***695 H ST*** ***E 1/4 - 1/2 (0.251 mi.)*** ***L67*** ***374***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Status: Preliminary site assessment underway
Global Id: T0607301886
Case Number: 9UT3119

SWEETWATER AUTHORITY ***744 F ST*** ***NNE 1/4 - 1/2 (0.291 mi.)*** ***O77*** ***393***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Closed Date: 8/8/86
Status: Case Closed
Case Number: 9UT527

FLUID SYSTEMS ***965 F ST*** ***NW 1/4 - 1/2 (0.294 mi.)*** ***M78*** ***426***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Closed Date: 2/19/93
Status: Case Closed
Global Id: T0607300888
Case Number: 9UT2120

WORLD OIL STATION #4 685 H ST E 1/4 - 1/2 (0.297 mi.) L80 472
Database: LUST REG 9, Date of Government Version: 03/01/2001
Closed Date: 4/25/00
Status: Case Closed
Case Number: 9UT3926

WORLD OIL #46 ***685 H ST*** ***E 1/4 - 1/2 (0.297 mi.)*** ***L81*** ***472***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Status: Preliminary site assessment underway
Global Id: T0607301884
Global Id: T0607302686
Case Number: 9UT3117

PRUDENTIAL OVERALL S ***740 F STREET*** ***NNE 1/4 - 1/2 (0.305 mi.)*** ***O83*** ***484***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Closed Date: 2/18/88
Status: Remedial action (cleanup) Underway
Status: Case Closed
Global Id: T0607301090
Global Id: T0607302719
Case Number: 9UT2320
Case Number: 9UT403

THRIFTY OIL COMPANY ***666 H ST*** ***E 1/4 - 1/2 (0.326 mi.)*** ***P84*** ***531***
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Global Id: T0607302991

THRIFTY SERIVCE STAT 666 H ST E 1/4 - 1/2 (0.326 mi.) P85 541
Database: LUST REG 9, Date of Government Version: 03/01/2001

Status: Remedial action (cleanup) Underway
Case Number: 9UT728

CITY OF CHULA VISTA | 707 F STREET | NNE 1/4 - 1/2 (0.347 mi.) | Q87 | 543
Database: LUST REG 9, Date of Government Version: 03/01/2001
Status: Preliminary site assessment workplan submitted
Case Number: 9UT4025

CITY OF CHULA VISTA | ***707 F STREET*** | ***NNE 1/4 - 1/2 (0.347 mi.)*** | ***Q90*** | ***545***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Closed Date: 3/29/99
Status: Case Closed
Global Id: T06019774117
Global Id: T0607302137
Global Id: T0607399063
Case Number: 9UT3376

H STREET AUTO WASH | ***498 BROADWAY*** | ***E 1/4 - 1/2 (0.494 mi.)*** | ***T96*** | ***638***
Database: LUST, Date of Government Version: 09/08/2020
Status: Open - Remediation
Global Id: T0607302590

H STREET CAR WASH | ***498 BROADWAY*** | ***E 1/4 - 1/2 (0.494 mi.)*** | ***T98*** | ***667***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Status: Preliminary site assessment underway
Case Number: 9UT3827

CPS-SLIC: Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the CPS-SLIC list, as provided by EDR, has revealed that there are 25 CPS-SLIC sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BAY BLVD PROJECTS	***NONE BAY BL***	***E 0 - 1/8 (0.057 mi.)***	***C7***	***21***
Database: CPS-SLIC, Date of Government Version: 09/08/2020 Facility Status: Completed - Case Closed Global Id: T0608135646				
FORMERLY THERMO KING	***340 BAY BL***	***NNE 1/8 - 1/4 (0.170 mi.)***	***D18***	***56***
Database: CPS-SLIC, Date of Government Version: 09/08/2020 Facility Status: Completed - Case Closed Global Id: T0608199629				
FORMER THERMO-KING F	340 BAY BLVD	NNE 1/8 - 1/4 (0.170 mi.)	D19	57
Database: SLIC REG 9, Date of Government Version: 09/10/2007 Status: Dead Status: Open				
FORMER EXXONMOBIL /	***745 H ST***	***E 1/8 - 1/4 (0.185 mi.)***	***H22***	***63***
Database: CPS-SLIC, Date of Government Version: 09/08/2020 Facility Status: Open - Remediation Global Id: T0607310406				
MTDB	***745 H ST***	***E 1/8 - 1/4 (0.185 mi.)***	***H24***	***68***
Database: CPS-SLIC, Date of Government Version: 09/08/2020				

Facility Status: Completed - Case Closed
Global Id: T10000000291

RADOS, CHULA VISTA C ***798 F ST*** ***N 1/8 - 1/4 (0.243 mi.)*** ***J52*** ***242***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T06019719942
Global Id: T06019723044

GOODRICH AEROSTRUCTU 850 LAGOON DRIVE NNW 1/8 - 1/4 (0.248 mi.) K54 327
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Open - Assessment & Interim Remedial Action
Global Id: T10000001489

BF GOODRICH, AEROSTR 850 LAGOON DRIVE NNW 1/8 - 1/4 (0.248 mi.) K55 328
Database: SLIC REG 9, Date of Government Version: 09/10/2007

GOODRICH AEROSTRUCTU ***850 LAGOON DRIVE*** ***NNW 1/8 - 1/4 (0.248 mi.)*** ***K59*** ***338***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Open - Remediation
Global Id: SL209294204

BF GOODRICH AEROSPAC ***850 LAGOON DR*** ***NNW 1/8 - 1/4 (0.248 mi.)*** ***K61*** ***340***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Facility Status: Open - Site Assessment
Global Id: T0608184113
Global Id: T0607399048
Global Id: T0607301189
Global Id: T0608190387
Global Id: T10000011095
**Additional key fields are available in the Map Findings section*

BF GOODRICH, AEROSTR ***850 LAGOON DRIVE*** ***NNW 1/8 - 1/4 (0.248 mi.)*** ***K62*** ***360***
Database: SLIC REG 9, Date of Government Version: 09/10/2007

GOODRICH AEROSTRUCTU 850 LAGOON DRIVE NNW 1/8 - 1/4 (0.248 mi.) K64 365
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T0608187932

CHEVRON #9-6056 ***695 H ST*** ***E 1/4 - 1/2 (0.251 mi.)*** ***L67*** ***374***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T10000002801

SEDIMENT OFF FORMER ***980 LAGOON DRIVE*** ***NW 1/4 - 1/2 (0.260 mi.)*** ***M71*** ***387***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Open - Inactive
Global Id: T10000008878

FORMER SHANGRILA SIT ***980 LAGOON DR*** ***NW 1/4 - 1/2 (0.260 mi.)*** ***M72*** ***388***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T0608177370

SWEETWATER AUTHORITY ***744 F ST*** ***NNE 1/4 - 1/2 (0.291 mi.)*** ***O77*** ***393***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T0607302820

CHULA VISTA CITY PUB ***707 F STREET*** ***NNE 1/4 - 1/2 (0.347 mi.)*** ***Q86*** ***542***
Database: CPS-SLIC, Date of Government Version: 09/08/2020

Facility Status: Completed - Case Closed
Global Id: T10000008489

CITY OF CHULA VISTA ***707 F STREET*** ***NNE 1/4 - 1/2 (0.347 mi.)*** ***Q90*** ***545***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: SLT19762335

CHULA VISTA BAYFRONT ***MARINA PARKWAY*** ***SSE 1/4 - 1/2 (0.412 mi.)*** ***R92*** ***632***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Open - Remediation
Global Id: T10000004581

CHULA VISTA BAYFRONT ***215 BAY BOULEVARD*** ***N 1/4 - 1/2 (0.476 mi.)*** ***S93*** ***633***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T10000006477

U S FISH AND WILDLIF ***NONE E ST(FOOT OF)*** ***N 1/4 - 1/2 (0.487 mi.)*** ***S95*** ***638***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T0608124509

H STREET AUTO WASH ***498 BROADWAY*** ***E 1/4 - 1/2 (0.494 mi.)*** ***T96*** ***638***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T0608164049
Global Id: T0608118503

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHULA VISTA BAYFRONT	***SAN DIEGO BAYFRONT***	***0 - 1/8 (0.000 mi.)***	***1***	***9***

Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Open - Assessment & Interim Remedial Action
Global Id: T10000010383

THE MARINE GROUP, LL ***997 G STREET*** ***W 1/8 - 1/4 (0.205 mi.)*** ***I40*** ***137***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Open - Inactive
Global Id: T10000008876

VACANT PROPERTY OWNE ***MARINA PARKWAY*** ***S 1/4 - 1/2 (0.363 mi.)*** ***R91*** ***631***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed
Global Id: T10000005120

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, has revealed that there are 3 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
"H" STREET ARCO	720 H ST	E 1/8 - 1/4 (0.203 mi.)	H37	132

Database: UST, Date of Government Version: 09/08/2020

Facility Id: 37-000-215933

ARCO AM/PM MINI MARK	***720 H ST***	***E 1/8 - 1/4 (0.203 mi.)***	***H39***	***135***
Database: UST, Date of Government Version: 09/08/2020 Facility Id: H20106				
ROHR INC., A UTC AER	850 LAGOON DR	NNW 1/8 - 1/4 (0.248 mi.)	K65	366
Database: UST, Date of Government Version: 09/08/2020 Facility Id: 37-000-102457				

AST: A listing of aboveground storage tank petroleum storage tank locations.

A review of the AST list, as provided by EDR, has revealed that there are 4 AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROHR INC., A UTC AER	850 LAGOON DR	NNW 1/8 - 1/4 (0.248 mi.)	K60	340
Database: AST, Date of Government Version: 07/06/2016				
BF GOODRICH AEROSPAC	***850 LAGOON DR***	***NNW 1/8 - 1/4 (0.248 mi.)***	***K61***	***340***
Database: AST, Date of Government Version: 07/06/2016				

Lower Elevation	Address	Direction / Distance	Map ID	Page
MARINE GROUP BOAT WO	***997 G ST***	***W 1/8 - 1/4 (0.205 mi.)***	***I41***	***138***
Database: AST, Date of Government Version: 07/06/2016				
PACIFIC YACHT REFITT	***997 G ST***	***W 1/8 - 1/4 (0.205 mi.)***	***I44***	***208***
Database: AST, Date of Government Version: 07/06/2016				

State and tribal voluntary cleanup sites

VCP: Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

A review of the VCP list, as provided by EDR, and dated 07/27/2020 has revealed that there is 1 VCP site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WOODLAWN COLONIAL AP	***245-255 WOODLAWN AVE***	***NNE 1/4 - 1/2 (0.477 mi.)***	***94***	***634***
Status: No Further Action Facility Id: 60001253				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: The Waste Management Unit Database System is used for program tracking and inventory of waste management units. The source is the State Water Resources Control Board.

A review of the WMUDS/SWAT list, as provided by EDR, and dated 04/01/2000 has revealed that there is 1 WMUDS/SWAT site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHULA VISTA,CITY OF,	707 F ST	NNE 1/4 - 1/2 (0.347 mi.)	Q88	543

Local Lists of Hazardous waste / Contaminated Sites

Toxic Pits: The Toxic Pits Cleanup Act Sites database identifies sites suspected of containing hazardous substances where cleanup has not yet been completed. The data come from the State Water Resources Control Board.

A review of the Toxic Pits list, as provided by EDR, and dated 07/01/1995 has revealed that there is 1 Toxic Pits site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHULA VISTA, PUBLIC Closure Date: 03/20/90 Task #: 89009 Status: CLOSED	707 F STREET	NNE 1/4 - 1/2 (0.347 mi.)	Q89	545

CERS HAZ WASTE: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

A review of the CERS HAZ WASTE list, as provided by EDR, and dated 10/19/2020 has revealed that there are 4 CERS HAZ WASTE sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ARCO MINI MARKET	***720 H ST***	***E 1/8 - 1/4 (0.203 mi.)***	***H32***	***87***
ROHR INC., A COLLINS	***850 LAGOON DR***	***NNW 1/8 - 1/4 (0.248 mi.)***	***K56***	***328***
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CHULA VISTA MARINA	***550 MARINA PY***	***S 1/8 - 1/4 (0.155 mi.)***	***E15***	***37***
MARINE GROUP BOAT WO	***997 G ST***	***W 1/8 - 1/4 (0.205 mi.)***	***I41***	***138***

Local Lists of Registered Storage Tanks

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are

2 SWEEPS UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MANNS TEXACO & U-HAU Comp Number: 12972	***730 H ST***	***E 1/8 - 1/4 (0.173 mi.)***	***H21***	***59***
DONN SWARTZ Status: A Tank Status: A Comp Number: 20106	720 H ST 1914	E 1/8 - 1/4 (0.203 mi.)	H33	127

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 4 HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROHR TIES ROHR INDUS Facility Id: 00000065045	FOOT OF H STREET ADJ	0 - 1/8 (0.000 mi.)	B4	15
LAWLESS Facility Id: 00000001218	390 BAY BLVD	NNE 0 - 1/8 (0.085 mi.)	10	26
RALPH E EMARINE DBA	720 H STREET	E 1/8 - 1/4 (0.203 mi.)	H35	131
RALPH E EMARINE Facility Id: 00000026658	720 H ST	E 1/8 - 1/4 (0.203 mi.)	H36	131

CERS TANKS: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

A review of the CERS TANKS list, as provided by EDR, and dated 10/19/2020 has revealed that there are 3 CERS TANKS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ARCO MINI MARKET	***720 H ST***	***E 1/8 - 1/4 (0.203 mi.)***	***H32***	***87***
ROHR INC., A COLLINS	***850 LAGOON DR***	***NNW 1/8 - 1/4 (0.248 mi.)***	***K56***	***328***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MARINE GROUP BOAT WO	***997 G ST***	***W 1/8 - 1/4 (0.205 mi.)***	***I41***	***138***

Local Land Records

DEED: The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes .

A review of the DEED list, as provided by EDR, and dated 08/31/2020 has revealed that there is 1 DEED site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHULA VISTA BAYFRONT	***MARINA PARKWAY***	***SSE 1/4 - 1/2 (0.412 mi.)***	***R92***	***632***

Status: OPEN - REMEDIATION
Envirostor ID: T10000004581

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/14/2020 has revealed that there are 18 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PARTY CITY CORP DBA EPA ID:: CAC002979701	865 H STREET	ESE 0 - 1/8 (0.025 mi.)	C6	19
AGUNDEZ CLAUDIA	410 COLORADO AVE #C	NE 1/8 - 1/4 (0.168 mi.)	F16	51
GBAHE TRAZIE EPA ID:: CAC002971563	456 COLORADO AVENUE	ENE 1/8 - 1/4 (0.168 mi.)	G17	53
MC INVESTMENT PARTNE	423 COLORADO AVE	ENE 1/8 - 1/4 (0.193 mi.)	F26	72
THE NAJAR FAMILY TRU	455 COLORADO AVE, UN	ENE 1/8 - 1/4 (0.193 mi.)	G27	75
ARCELIA GONZALEZ	455 COLORADO AVE UNI	ENE 1/8 - 1/4 (0.193 mi.)	G28	77
RYAN ABIDES EPA ID:: CAC003033005	443 COLORADO AVE	ENE 1/8 - 1/4 (0.193 mi.)	G29	80
DASHAWN PALMER	724 G ST	NE 1/8 - 1/4 (0.196 mi.)	F30	82
MC INVESTMENT PARTNE	467 COLORADO AVE	E 1/8 - 1/4 (0.196 mi.)	G31	85
TESORO 97610-1914 EPA ID:: CAL000410683	720 H ST	E 1/8 - 1/4 (0.203 mi.)	H34	128
GS & SS PETROLIUM IN EPA ID:: CAL000267011	720 H ST	E 1/8 - 1/4 (0.203 mi.)	H38	132
RON MARTIN EPA ID:: CAC003019955	456 WOODAWN AVE	ENE 1/8 - 1/4 (0.217 mi.)	G48	232
WILLIAM D. EVANS STE EPA ID:: CAC003056384	996 G. STREET	W 1/8 - 1/4 (0.241 mi.)	I49	234
SC COMMERCIAL EPA ID:: CAC003056061	996 G. ST	W 1/8 - 1/4 (0.241 mi.)	I50	237
WILLIAM KEMERY EPA ID:: CAC003049111	415 WOODLAWN AVE	ENE 1/8 - 1/4 (0.242 mi.)	51	239
GOODRICH AEROSTRUCTU EPA ID:: CAC003056223	850 LAGOON DRIVE	NNW 1/8 - 1/4 (0.248 mi.)	K58	336

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHULA VISTA MARINA EPA ID:: CAL000120646	550 MARINA PKWY	S 1/8 - 1/4 (0.155 mi.)	E14	34
SOUTH BAY BOILER REP EPA ID:: CAL000287787	997 G ST	W 1/8 - 1/4 (0.205 mi.)	I46	225

EXECUTIVE SUMMARY

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 08/05/2020 has revealed that there is 1 FUDS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ROHR AIRCRAFT CORP.		SE 1/4 - 1/2 (0.281 mi.)	N75	392

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 06/22/2020 has revealed that there are 10 Cortese sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ARCO AM/PM MINI MARK	***720 H ST***	***E 1/8 - 1/4 (0.203 mi.)***	***H39***	***135***
Cleanup Status: COMPLETED - CASE CLOSED				
BF GOODRICH AEROSPAC	***850 LAGOON DR***	***NNW 1/8 - 1/4 (0.248 mi.)***	***K61***	***340***
Cleanup Status: COMPLETED - CASE CLOSED				
CHEVRON #9-6056	***695 H ST***	***E 1/4 - 1/2 (0.251 mi.)***	***L67***	***374***
Cleanup Status: COMPLETED - CASE CLOSED				
FLUID SYSTEMS	***965 F ST***	***NW 1/4 - 1/2 (0.294 mi.)***	***M78***	***426***
Cleanup Status: COMPLETED - CASE CLOSED				
WORLD OIL MARKETING	***685 H ST***	***E 1/4 - 1/2 (0.297 mi.)***	***L79***	***434***
Cleanup Status: COMPLETED - CASE CLOSED				
WORLD OIL #46	***685 H ST***	***E 1/4 - 1/2 (0.297 mi.)***	***L81***	***472***
Cleanup Status: COMPLETED - CASE CLOSED				
PRUDENTIAL OVERALL S	***740 F ST***	***NNE 1/4 - 1/2 (0.305 mi.)***	***O82***	***481***
Cleanup Status: COMPLETED - CASE CLOSED				
THRIFTY OIL COMPANY	***666 H ST***	***E 1/4 - 1/2 (0.326 mi.)***	***P84***	***531***
Cleanup Status: COMPLETED - CASE CLOSED				
CITY OF CHULA VISTA	***707 F STREET***	***NNE 1/4 - 1/2 (0.347 mi.)***	***Q90***	***545***
Cleanup Status: COMPLETED - CASE CLOSED				
H STREET AUTO WASH	***498 BROADWAY***	***E 1/4 - 1/2 (0.494 mi.)***	***T96***	***638***
Cleanup Status: OPEN - REMEDIATION				

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 9 HIST CORTESE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ARCO MINI MARKET	***720 H ST***	***E 1/8 - 1/4 (0.203 mi.)***	***H32***	***87***
Reg Id: 9UT3103				
CHEVRON #9-6056	***695 H ST***	***E 1/4 - 1/2 (0.251 mi.)***	***L67***	***374***

Reg Id: 9UT3119				
SWEETWATER AUTHORITY Reg Id: 9UT527	***744 F ST***	***NNE 1/4 - 1/2 (0.291 mi.)***	***O77***	***393***
FLUID SYSTEMS Reg Id: 9UT2120	***965 F ST***	***NW 1/4 - 1/2 (0.294 mi.)***	***M78***	***426***
WORLD OIL #46 Reg Id: 9UT3926 Reg Id: 9UT3117	***685 H ST***	***E 1/4 - 1/2 (0.297 mi.)***	***L81***	***472***
PRUDENTIAL OVERALL S Reg Id: 9UT2320 Reg Id: 9UT403	***740 F STREET***	***NNE 1/4 - 1/2 (0.305 mi.)***	***O83***	***484***
THRIFTY OIL COMPANY Reg Id: 9UT728	***666 H ST***	***E 1/4 - 1/2 (0.326 mi.)***	***P84***	***531***
CITY OF CHULA VISTA Reg Id: 9 000002N89 Reg Id: 9UT3376	***707 F STREET***	***NNE 1/4 - 1/2 (0.347 mi.)***	***Q90***	***545***
H STREET CAR WASH Reg Id: 9UT3827	***498 BROADWAY***	***E 1/4 - 1/2 (0.494 mi.)***	***T98***	***667***

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

A review of the Notify 65 list, as provided by EDR, and dated 12/07/2020 has revealed that there are 2 Notify 65 sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CITY OF CHULA VISTA	***707 F STREET***	***NNE 1/4 - 1/2 (0.347 mi.)***	***Q90***	***545***
CHERNISS TIRE WORLD	***101 BROADWAY***	***NNE 1/2 - 1 (0.912 mi.)***	***100***	***676***

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 13 records.

Site Name	Database(s)
SHINOHARA I	SWF/LF, RGA LF
GUNPOWDER POINT (PARADISE MARSH)	SWF/LF
N STREET LF	SWF/LF
GOODRICH CORP. DBA ROHR INC	San Diego Co. HMMD
U S FISH AND WILDLIFE SERVICE	San Diego Co. HMMD
SAN DIEGO UNIFIED PORT DIST	San Diego Co. HMMD
IN-N-OUT BURGER #70	San Diego Co. HMMD
LEX-TEK	San Diego Co. HMMD
CHULA VISTA BAYFRONT MASTER PLAN D	CPS-SLIC
BNSF CAR TRANSFER LOT	ENVIROSTOR
BAY BLVD PROJECTS	SAN DIEGO CO. SAM
CAPE COD BLUES PROPERTY	SAN DIEGO CO. SAM
U S FISH AND WILDLIFE SERVICE	SAN DIEGO CO. SAM

OVERVIEW MAP - 6326895.2S



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Parcel B Buildings - Former Collins Aerospace	CLIENT:	Partner Engineering and Science, Inc.
ADDRESS:	South of G Street Chula Vista CA 91910	CONTACT:	Karli Mcmurray
LAT/LONG:	32.630014 / 117.100205	INQUIRY #:	6326895.2s
		DATE:	January 11, 2021 1:37 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 6326895.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Parcel B Buildings - Former Collins Aerospace	CLIENT:	Partner Engineering and Science, Inc.
ADDRESS:	South of G Street Chula Vista CA 91910	CONTACT:	Karli Mcmurray
LAT/LONG:	32.630014 / 117.100205	INQUIRY #:	6326895.2s
		DATE:	January 11, 2021 1:44 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	3	2	NR	NR	5
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		2	2	NR	NR	NR	4
RCRA-SQG	0.250		1	6	NR	NR	NR	7
RCRA-VSQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent NPL								
RESPONSE	1.000		0	0	0	0	NR	0
State- and tribal - equivalent CERCLIS								
ENVIROSTOR	1.000		1	1	4	2	NR	8
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	0.500		0	0	1	NR	NR	1
State and tribal leaking storage tank lists								
SAN DIEGO CO. SAM	0.500		0	5	10	NR	NR	15

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LUST	0.500		1	2	12	NR	NR	15
INDIAN LUST	0.500		0	0	0	NR	NR	0
CPS-SLIC	0.500		2	12	11	NR	NR	25
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250		0	3	NR	NR	NR	3
AST	0.250		0	4	NR	NR	NR	4
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal voluntary cleanup sites								
VCP	0.500		0	0	1	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
WMUDS/SWAT	0.500		0	0	1	NR	NR	1
SWRCY	0.500		0	0	0	NR	NR	0
HAULERS	TP		NR	NR	NR	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
HIST Cal-Sites	1.000		0	0	0	0	NR	0
SCH	0.250		0	0	NR	NR	NR	0
CDL	TP		NR	NR	NR	NR	NR	0
San Diego Co. HMMD	TP		NR	NR	NR	NR	NR	0
Toxic Pits	1.000		0	0	1	0	NR	1
CERS HAZ WASTE	0.250		0	4	NR	NR	NR	4
US CDL	TP		NR	NR	NR	NR	NR	0
PFAS	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
SWEEPS UST	0.250		0	2	NR	NR	NR	2
HIST UST	0.250		2	2	NR	NR	NR	4
CERS TANKS	0.250		0	3	NR	NR	NR	3
CA FID UST	0.250		0	0	NR	NR	NR	0
Local Land Records								
LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	TP		NR	NR	NR	NR	NR	0
DEED	0.500		0	0	1	NR	NR	1
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
CHMIRS	TP		NR	NR	NR	NR	NR	0
LDS	TP		NR	NR	NR	NR	NR	0
MCS	TP		NR	NR	NR	NR	NR	0
SPILLS 90	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		1	17	NR	NR	NR	18
FUDS	1.000		0	0	1	0	NR	1
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
CA BOND EXP. PLAN	1.000		0	0	0	0	NR	0
Cortese	0.500		0	2	8	NR	NR	10
CUPA Listings	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
EMI	TP		NR	NR	NR	NR	NR	0
ENF	TP		NR	NR	NR	NR	NR	0
Financial Assurance	TP		NR	NR	NR	NR	NR	0
HAZNET	TP		NR	NR	NR	NR	NR	0
ICE	TP		NR	NR	NR	NR	NR	0
HIST CORTESE	0.500		0	1	8	NR	NR	9
HWP	1.000		0	0	0	0	NR	0
HWT	0.250		0	0	NR	NR	NR	0
MINES	0.250		0	0	NR	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
NPDES	TP		NR	NR	NR	NR	NR	0
PEST LIC	TP		NR	NR	NR	NR	NR	0
PROC	0.500		0	0	0	NR	NR	0
Notify 65	1.000		0	0	1	1	NR	2
UIC	TP		NR	NR	NR	NR	NR	0
UIC GEO	TP		NR	NR	NR	NR	NR	0
WASTEWATER PITS	0.500		0	0	0	NR	NR	0
WDS	TP		NR	NR	NR	NR	NR	0
WIP	0.250		0	0	NR	NR	NR	0
MILITARY PRIV SITES	TP		NR	NR	NR	NR	NR	0
PROJECT	TP		NR	NR	NR	NR	NR	0
WDR	TP		NR	NR	NR	NR	NR	0
SAN DIEGO CO LOP	TP		NR	NR	NR	NR	NR	0
CIWQS	TP		NR	NR	NR	NR	NR	0
CERS	TP		NR	NR	NR	NR	NR	0
NON-CASE INFO	TP		NR	NR	NR	NR	NR	0
OTHER OIL GAS	TP		NR	NR	NR	NR	NR	0
PROD WATER PONDS	TP		NR	NR	NR	NR	NR	0
SAMPLING POINT	TP		NR	NR	NR	NR	NR	0
WELL STIM PROJ	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0
HWTS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA LF	TP		NR	NR	NR	NR	NR	0
RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		0	10	69	62	3	0	144

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

1 **CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CHU** **CPS-SLIC** **S120762619**
SAN DIEGO BAYFRONT **CERS** **N/A**
< 1/8 **CHULA VISTA, CA 91910**
1 ft.

Relative: Lower

Actual: 6 ft.

CPS-SLIC:

Name:	CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CHULA VISTA BAYFRONT DEVELOPMENT
Address:	SAN DIEGO BAYFRONT
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Open - Assessment & Interim Remedial Action**
Status Date:	05/10/2017
Global Id:	T10000010383
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.62978
Longitude:	-117.10229
Case Type:	Cleanup Program Site
Case Worker:	TCA
Local Agency:	Not reported
RB Case Number:	4090005
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Contaminated Surface / Structure, Other Groundwater (uses other than drinking water), Sediments, Soil, Soil Vapor, Under Investigation
Potential Contaminants of Concern:	Dichloroethene (DCE), Other Chlorinated Hydrocarbons, Trichloroethylene (TCE), Polychlorinated biphenyls (PCBs), Other Metal, Other Petroleum
Site History:	General File for information relating to activities associated with the Chula Vista Bayfront Master Plan. Coastal area along eastern San Diego Bay from Sweetwater Parcels south to the former South Bay Power Plant site in Chula Vista.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CHULA VISTA BAYFRONT DEVELOPMENT
Address:	SAN DIEGO BAYFRONT
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	421673
CERS ID:	T10000010383
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213375

A2 **COMMANDER NAVY REGION SW** **RCRA-LQG** **1016452963**
868 G ST **FINDS** **CAR000243360**
< 1/8 **CHULA VISTA, CA 91990** **ECHO**
1 ft.

Site 1 of 2 in cluster A

Relative: **Lower**
Actual: **10 ft.**

RCRA-LQG:

Date Form Received by Agency:	2018-08-08 00:00:00.0
Handler Name:	COMMANDER NAVY REGION SW
Handler Address:	868 G ST
Handler City,State,Zip:	CHULA VISTA, CA 91990
EPA ID:	CAR000243360
Contact Name:	VIRGINIA MAKALE
Contact Address:	937 NORTH HARBOR DR
Contact City,State,Zip:	SAN DIEGO, CA 92132
Contact Telephone:	619-532-3840
Contact Fax:	Not reported
Contact Email:	VIRGINIA.MAKALE@NAVY.MIL
Contact Title:	CNRSW HW PROGRAM MGR
EPA Region:	09
Land Type:	District
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 18170
Mailing City,State,Zip:	CORONADO, CA 92135
Owner Name:	UNIFIED PORT OF SAN DIEGO
Owner Type:	District
Operator Name:	MARINE GROUP BOAT WORKS
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

COMMANDER NAVY REGION SW (Continued) **1016452963**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-08-10 15:00:20.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D011
Waste Description:	SILVER

COMMANDER NAVY REGION SW (Continued) **1016452963**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MARINE GROUP BOAT WORKS
Legal Status:	Private
Date Became Current:	2012-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	868 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MARINE GROUP BOAT WORKS
Legal Status:	Private
Date Became Current:	2012-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNIFIED PORT OF SAN DIEGO
Legal Status:	District
Date Became Current:	1962-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	3165 PACIFIC HWY
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92101
Owner/Operator Telephone:	619-686-6200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNIFIED PORT OF SAN DIEGO
Legal Status:	District
Date Became Current:	1962-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	3165 PACIFIC HWY
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92101
Owner/Operator Telephone:	619-686-6200
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2014-01-06 00:00:00.0
Handler Name:	COMMANDER NAVY REGION SW
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

COMMANDER NAVY REGION SW (Continued) **1016452963**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2018-08-08 00:00:00.0
Handler Name:	COMMANDER NAVY REGION SW
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	336611
NAICS Description:	SHIP BUILDING AND REPAIRING

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

FINDS:

Registry ID: 110056511298

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016452963
Registry ID:	110056511298
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110056511298
Name:	COMMANDER NAVY REGION SW
Address:	868 G ST
City,State,Zip:	CHULA VISTA, CA 91990

B3 **ROHR AIRCRAFT** **ENVIROSTOR** **S101481972**
FOOT OF H STREET **N/A**
< 1/8 **CHULA VISTA, CA 92010**
1 ft.

Site 1 of 2 in cluster B

Relative: **Higher**

Actual: **16 ft.**

ENVIROSTOR:

Name:	ROHR AIRCRAFT
Address:	FOOT OF H STREET
City,State,Zip:	CHULA VISTA, CA 92010
Facility ID:	37370020
Status:	Refer: Other Agency
Status Date:	08/21/1995
Site Code:	600023
Site Type:	Historical
Site Type Detailed:	* Historical
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	* Mmonroy
Division Branch:	Cleanup Cypress
Assembly:	Not reported
Senate:	Not reported
Special Program:	* RCRA 3012 - Past Haz Waste Disp Inven Site
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not reported
Latitude:	0
Longitude:	0
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	* ACID SOLUTION 2>PH WITH METALS * Sludge - Degreasing * Sludge - Paint * UNSPECIFIED SOLVENT MIXTURES * ALKALINE SOLUTION 2<PH<12.5, WITH METALS Polychlorinated biphenyls (PCBs
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	ROHR INDUSTRIES, INC.
Alias Type:	Alternate Name
Alias Name:	ROHR TURBINE SITE
Alias Type:	Alternate Name
Alias Name:	CAD008382053
Alias Type:	EPA Identification Number
Alias Name:	SL209294204
Alias Type:	GeoTracker Global ID
Alias Name:	T0607301766
Alias Type:	GeoTracker Global ID
Alias Name:	T0608187932
Alias Type:	GeoTracker Global ID
Alias Name:	CAD981168164
Alias Type:	HWTS Identification Code
Alias Name:	600023
Alias Type:	Project Code (Site Code)
Alias Name:	37370020
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

ROHR AIRCRAFT (Continued) **S101481972**

Completed Document Type:	Site Screening
Completed Date:	11/07/1994
Comments:	CALSITES VALIDATION PROGRAM CONFIRMS NFA FOR DTSC.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Assessment Report
Completed Date:	09/14/1984
Comments:	PERMIT(OTHER) PERMIT: INDUST MATL PERMITS FROM CITY WATER UTILITIES DEPT, CO HMMS ASP SURVEY 11/9/81 - 1)SOURCE ACT: MFG OF AEROSPACE COMPONENTS,DEGREASING,PLATG PAINTING,ANODIZE 2)YR OF OPER: 1940-PRSN SUBMIT TO EPA PRELIM ASSESS DONE RCRA 3012
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	* Discovery
Completed Date:	10/14/1982
Comments:	FACILITY IDENTIFIED ID VIA 50 PHONE BOOK
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

B4 **ROHR TIES ROHR INDUSTRIES** **HIST UST** **U001571108**
FOOT OF H STREET ADJACENT TO **N/A**
< 1/8 **CHULA VISTA, CA 92011**
1 ft.

Site 2 of 2 in cluster B

Relative: HIST UST:
Higher

Name:	ROHR TIES ROHR INDUSTRIES
Address:	FOOT OF H STREET ADJACENT TO
City,State,Zip:	CHULA VISTA, CA 92011
File Number:	0002F279
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002F279.pdf
Region:	STATE
Facility ID:	00000065045
Facility Type:	Other
Other Type:	UTILITY
Contact Name:	Not reported
Telephone:	6196962993
Owner Name:	SAN DIEGO GAS & ELECTRIC COMPA
Owner Address:	101 ASH ST.
Owner City,St,Zip:	SAN DIEGEO, CA 91112
Total Tanks:	0001
Tank Num:	001
Container Num:	1404
Year Installed:	1978
Tank Capacity:	00000550
Tank Used for:	WASTE
Type of Fuel:	Not reported

Actual:
16 ft.

ROHR TIES ROHR INDUSTRIES (Continued) **U001571108**

Container Construction Thickness: .220
Leak Detection: Groundwater Monitoring Well

Click here for Geo Tracker PDF:

A5 **DERILICT VESSEL STORAGE YARD** **RCRA-LQG** **1017785671**
NW **891 G ST** **FINDS** **CAL000347973**
< 1/8 **CHULA VISTA, CA 91910** **ECHO**
0.008 mi.
40 ft. **Site 2 of 2 in cluster A**

Relative: RCRA-LQG:
Lower
Actual:
6 ft.

Date Form Received by Agency:	2015-02-02 00:00:00.0
Handler Name:	DERILICT VESSEL STORAGE YARD
Handler Address:	891 G ST
Handler City,State,Zip:	CHULA VISTA, CA 91910
EPA ID:	CAL000347973
Contact Name:	PAUL H BROWN
Contact Address:	PO BOX 120488
Contact City,State,Zip:	SAN DIEGO, CA 92112
Contact Telephone:	619-686-7283
Contact Fax:	Not reported
Contact Email:	PBROWN@PORTOFSANDIEGO.ORG
Contact Title:	PROGRAM MANAGER
EPA Region:	09
Land Type:	District
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 120488
Mailing City,State,Zip:	SAN DIEGO, CA 92112
Owner Name:	SAN DIEGO UNIFIED PORT DISTRICT
Owner Type:	District
Operator Name:	SAN DIEGO UNIFIED PORT DISTRICT
Operator Type:	District
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

DERILICT VESSEL STORAGE YARD (Continued) **1017785671**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-01 13:01:16.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SAN DIEGO UNIFIED PORT DISTRICT
Legal Status:	District
Date Became Current:	1962-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported

DERILICT VESSEL STORAGE YARD (Continued) **1017785671**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SAN DIEGO UNIFIED PORT DISTRICT
Legal Status: District
Date Became Current: 1962-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 120488
Owner/Operator City,State,Zip: SAN DIEGO, CA 92112
Owner/Operator Telephone: 619-686-7283
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2015-02-02 00:00:00.0
Handler Name: DERILICT VESSEL STORAGE YARD
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 48831
NAICS Description: PORT AND HARBOR OPERATIONS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063994682

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

DERILICT VESSEL STORAGE YARD (Continued) **1017785671**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1017785671
Registry ID:	110063994682
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110063994682
Name:	DERILICT VESSEL STORAGE YARD
Address:	891 G ST
City,State,Zip:	CHULA VISTA, CA 91910

C6 **PARTY CITY CORP DBA HALLOWEEN CITY #8339** **RCRA NonGen / NLR** **1024759849**
ESE **865 H STREET** **CAC002979701**
< 1/8 **CHULA VISTA, CA 91910**
0.025 mi.
131 ft. **Site 1 of 3 in cluster C**

Relative:
Higher

Actual:
21 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2018-09-11 00:00:00.0
Handler Name:	PARTY CITY CORP DBA HALLOWEEN CITY #8339
Handler Address:	865 H STREET
Handler City,State,Zip:	CHULA VISTA, CA 91910
EPA ID:	CAC002979701
Contact Name:	LARRY WUDYKA
Contact Address:	41100 PLYMOUTH RD, STE 101
Contact City,State,Zip:	PLYMOUTH, MI 48170
Contact Telephone:	734-591-5468
Contact Fax:	Not reported
Contact Email:	LWUDYKA@PARTYCITY.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PO BOX 2513
Mailing City,State,Zip:	TRUCKEE, CA 96160
Owner Name:	PARTY CITY CORP.
Owner Type:	Other
Operator Name:	LARRY WUDYKA
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes

PARTY CITY CORP DBA HALLOWEEN CITY #8339 (Continued) **1024759849**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-10-01 18:38:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PARTY CITY CORP.
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	25 GREEN POND RD, STE #1
Owner/Operator City,State,Zip:	ROCKAWAY, NJ 07866
Owner/Operator Telephone:	973-453-8600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

PARTY CITY CORP DBA HALLOWEEN CITY #8339 (Continued) **1024759849**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	LARRY WUDYKA
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	41100 PLYMOUTH RD, STE 101
Owner/Operator City,State,Zip:	PLYMOUTH, MI 48170
Owner/Operator Telephone:	734-591-5468
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2018-09-11 00:00:00.0
Handler Name:	PARTY CITY CORP DBA HALLOWEEN CITY #8339
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

C7 **BAY BLVD PROJECTS** **CPS-SLIC** **S106916042**
East **NONE BAY BL** **CERS** **N/A**
< 1/8 **CHULA VISTA, CA 91911**
0.057 mi.
300 ft. **Site 2 of 3 in cluster C**

Relative:
Higher

Actual:
21 ft.

CPS-SLIC:

Name:	BAY BLVD PROJECTS
Address:	NONE BAY BL
City,State,Zip:	CHULA VISTA, CA 91911
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	09/17/2001
Global Id:	T0608135646
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H26520-001
Latitude:	32.6295162393125
Longitude:	-117.096948814438
Case Type:	Cleanup Program Site

BAY BLVD PROJECTS (Continued) **S106916042**

Case Worker:	NS
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	BAY BLVD PROJECTS
Address:	NONE BAY BL
City,State,Zip:	CHULA VISTA, CA 91911
Site ID:	240915
CERS ID:	T0608135646
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	NASSER SIONIT - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

C8 **UNIVERSITY COGENERATION INC** **LUST** **S100725914**
ESE **H ST** **San Diego Co. HMMD** **N/A**
< 1/8 **CHULA VISTA, CA 91910**
0.072 mi.
381 ft. **Site 3 of 3 in cluster C**

Relative:
Higher

Actual:
22 ft.

LUST REG 9:

Region:	9
Status:	Preliminary site assessment underway
Case Number:	9UT3961
Local Case:	H02457-011
Substance:	Waste Oil
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Unknown
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Soil only
Date Found:	06/15/1999
Date Stopped:	06/15/1999
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	07/12/1999
Desc Pollution:	Not reported
Remed Plan:	/ /

UNIVERSITY COGENERATION INC (Continued) **S100725914**

Remed Action: Not reported
Began Monitor: Not reported
Release Date: 06/15/1999
Enforce Date: Not reported
Closed Date: Not reported
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 909.12
GW Depth: Not reported
Beneficial Use: MUNBU
NPDES Number: Not reported
Priority: Low priority. Priority ranking can change over time.
File Dispn: Not reported
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

HMMD SAN DIEGO:
Name: UNIVERSITY COGENERATION INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 119265
Business Type: 6HK52
EPA Id Number: CAD981967284
APN: 592-192-23-00
Last HMMD Inspection: 04/14/1999
Facility Telephone: Not reported
Permit Status: INAC
Permit Expiration: 04/14/1999
Date Last Updated: 11/02/2012
Facility Owner: Not reported
Facility Mailing Address: Not reported
Facility Mailing City: Not reported
Facility Mailing State: Not reported
Facility Mailing Zip: Not reported
UST Owner: Not reported
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

---

9 SSW < 1/8 0.082 mi. 434 ft.

MHE REPAIR FACILITY NAVY
596A SANDPIPER WAY
CHULA VISTA, CA 91910

RCRA-SQG **1001115517**
CAR000014530

Relative: Lower

Actual: 9 ft.

RCRA-SQG:
Date Form Received by Agency: 1996-11-05 00:00:00.0
Handler Name: MHE REPAIR FACILITY NAVY
Handler Address: 596A SANDPIPER WAY
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAR000014530
Contact Name: LEE HEMING
Contact Address: 830 PROFESSIONAL PL

MHE REPAIR FACILITY NAVY (Continued) **1001115517**

Contact City,State,Zip:	CHESAPEAKE, VA 23320
Contact Telephone:	619-427-9221
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Federal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	596A SANDPIPER WAY
Mailing City,State,Zip:	CHULA VISTA, CA 91910
Owner Name:	MORLEY GOLDEN
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	The land is federally-owned
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

MHE REPAIR FACILITY NAVY (Continued) **1001115517**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:39:23.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MORLEY GOLDEN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	517 WILDFLOWER
Owner/Operator City,State,Zip:	SUN VALLEY, ID 83353
Owner/Operator Telephone:	619-427-9221
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1996-11-05 00:00:00.0
Handler Name:	MHE REPAIR FACILITY NAVY
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

10
NNE
< 1/8
0.085 mi.
447 ft.

LAWLESS
390 BAY BLVD
CHULA VISTA, CA 92010

HIST UST **U001571036**
N/A

Relative:
Higher

Actual:
25 ft.

HIST UST:

Name:	LAWLESS
Address:	390 BAY BLVD
City,State,Zip:	CHULA VISTA, CA 92010
File Number:	0002B650
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002B650.pdf
Region:	STATE
Facility ID:	00000001218
Facility Type:	Other
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	6194253480
Owner Name:	LAWLESS DETROLT DIESEL, INC.
Owner Address:	13644 E. NELSON
Owner City,St,Zip:	CITY OF INDUSTRY, CA 91746
Total Tanks:	0003
Tank Num:	001
Container Num:	1
Year Installed:	1977
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	002
Container Num:	2
Year Installed:	1977
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	WASTE
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	None

Click here for Geo Tracker PDF:

11
SE
1/8-1/4
0.135 mi.
711 ft.

ROHR INDUSTRIES INC
H ST
CHULA VISTA, CA 91910

SAN DIEGO CO. SAM
SAN DIEGO CO LOP

S108407211
N/A

Relative:
Higher

Actual:
19 ft.

SAN DIEGO CO. SAM:

Name:	ROHR INDUSTRIES INC
Address:	H ST
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H02457-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	GW With No Beneficial Use Designation
Facility Status:	Closed Case
Date:	12/16/1986
Date Began:	8/21/1986

Name:	ROHR INDUSTRIES INC
Address:	H ST
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H02457-002
Agency:	DEH Site Assessment & Mitigation
Funding:	**LOP - Federal Fund**
Facility Type:	GW With No Beneficial Use Designation
Facility Status:	Closed Case
Date:	8/2/2002
Date Began:	8/5/1987

Name:	ROHR INDUSTRIES INC
Address:	H ST
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H02457-003
Agency:	DEH Site Assessment & Mitigation
Funding:	**LOP - Federal Fund**
Facility Type:	Soils Only
Facility Status:	Closed Case
Date:	1/23/1992
Date Began:	10/20/1987

Name:	ROHR INDUSTRIES INC
Address:	H ST
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H02457-004
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	Drinking Water Aquifer Impacted
Facility Status:	Closed Case
Date:	2/18/1993
Date Began:	4/7/1992

Name:	ROHR INDUSTRIES INC
Address:	H ST
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H02457-005
Agency:	CA Regional Water Quality Control Board
Funding:	**Non Billable**
Facility Type:	Drinking Water Aquifer Impacted
Facility Status:	Preliminary Assessment

ROHR INDUSTRIES INC (Continued) **S108407211**

Date: 2/9/1995
Date Began: 6/18/1992

Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-006
Agency: DEH Site Assessment & Mitigation
Funding: **Private - For Non-LOP Tank**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Preliminary Assessment
Date: 7/23/1992
Date Began: 7/13/1992

Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-007
Agency: CA Regional Water Quality Control Board
Funding: **Non Billable**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Preliminary Assessment
Date: 10/28/1992
Date Began: 10/28/1992

Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-008
Agency: CA Regional Water Quality Control Board
Funding: **Non Billable**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 3/10/1993
Date Began: 1/11/1993

Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-009
Agency: DEH Site Assessment & Mitigation
Funding: **Private - For Non-LOP Tank**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 6/12/1998
Date Began: 6/24/1993

Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-010
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 3/21/1991
Date Began: 8/30/1990

ROHR INDUSTRIES INC (Continued) **S108407211**

Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-011
Agency: DEH Site Assessment & Mitigation
Funding: **Private - Site Designation**
Facility Type: Soils Only
Facility Status: Remedial Investigation
Date: 5/23/2000
Date Began: 6/15/1999

Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-012
Agency: DEH Site Assessment & Mitigation
Funding: **Private - Site Designation**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 7/12/1999
Date Began: 6/15/1999

Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-013
Agency: DEH Site Assessment & Mitigation
Funding: **Private - For Non-LOP Tank**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 4/24/2000
Date Began: 4/24/2000

Name: ROHR INDUSTRIES INC
Address: 0 H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H02457-014
Agency: CA Regional Water Quality Control Board
Funding: **Non Billable**
Facility Type: Soils Only
Facility Status: Preliminary Assessment
Date: 1/19/2007
Date Began: 10/26/2006

SAN DIEGO CO LOP:
Name: ROHR INDUSTRIES INC
Address: H ST
City,State,Zip: CHULA VISTA, CA 91910
Record ID: DEH1992-LSAM-H02457-007
Record Status: Completed
Opened Date: 10/28/1992
Parcel Number: 571-330-16-00
Case Type: Not reported
Historical Name: ROHR INDUSTRIES
SWRCB Global ID: T10000001489
Funding: N - Non-Billable
Lead Agency: RWQCB

ROHR INDUSTRIES INC (Continued) **S108407211**

Lead Agency Date:	10/28/1992
Census Tract:	126.00
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6269306
Longitude:	-117.0969047
X MapCoord:	6300833.278
Y MapCoord:	1809185.631

Name:	ROHR INDUSTRIES INC
Address:	H ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1993-LSAM-H02457-008
Record Status:	Completed
Opened Date:	02/09/1993
Parcel Number:	571-330-16-00
Case Type:	Not reported
Historical Name:	ROHR INDUSTRIES
SWRCB Global ID:	T10000001489
Funding:	N - Non-Billable
Lead Agency:	RWQCB
Lead Agency Date:	12/05/1996
Census Tract:	126.00
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6269306
Longitude:	-117.0969047
X MapCoord:	6300833.278
Y MapCoord:	1809185.631

Name:	ROHR INDUSTRIES INC
Address:	H ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH2007-LSAM-H02457-014
Record Status:	Completed
Opened Date:	01/08/2007
Parcel Number:	571-330-16-00
Case Type:	Not reported
Historical Name:	GOODRICH AEROSTRUCTURES
SWRCB Global ID:	Not reported
Funding:	N - Non-Billable
Lead Agency:	RWQCB
Lead Agency Date:	01/19/2007
Census Tract:	126.00
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6269306
Longitude:	-117.0969047

ROHR INDUSTRIES INC (Continued) **S108407211**

X MapCoord:	6300833.278
Y MapCoord:	1809185.631
Name:	ROHR INDUSTRIES INC
Address:	H ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1987-LSAM-H02457-002
Record Status:	Completed
Opened Date:	08/13/1987
Parcel Number:	571-330-16-00
Case Type:	LOP - Local Oversight Program
Historical Name:	ROHR INDUSTRIES INC
SWRCB Global ID:	T0607302732
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	08/13/1987
Census Tract:	126.00
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6269306
Longitude:	-117.0969047
X MapCoord:	6300833.278
Y MapCoord:	1809185.631

D12 **CITY OF CHULA VISTA** **ENVIROSTOR** **S106797681**
NNE **350-360 BAY BOULEVARD** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.152 mi.
805 ft. **Site 1 of 4 in cluster D**

Relative: ENVIROSTOR:
Higher

Actual:
25 ft.

Name:	CITY OF CHULA VISTA
Address:	350-360 BAY BOULEVARD
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	37000027
Status:	Refer: 1248 Local Agency
Status Date:	01/31/2001
Site Code:	Not reported
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Cypress
Assembly:	80
Senate:	40
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not Applicable
Latitude:	32.63410
Longitude:	-117.0989

CITY OF CHULA VISTA (Continued) **S106797681**

APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 37000027
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: SB 1248 Notification
Completed Date: 01/31/2001
Comments: SB 1248 San Diego County

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

E13 **THOMAS DINANNO** **RCRA-SQG** **1025879251**
South **550 MARINA PKWY** **CAP000076059**
1/8-1/4 **CHULA VISTA, CA 91910**
0.155 mi.
817 ft. **Site 1 of 3 in cluster E**

Relative: **Lower**
Actual: **8 ft.**

RCRA-SQG:
Date Form Received by Agency: 2000-06-21 00:00:00.0
Handler Name: THOMAS DINANNO
Handler Address: 550 MARINA PKWY
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAP000076059
Contact Name: THOMAS DINANNO
Contact Address: 4284 ACACIA AVE
Contact City,State,Zip: BONITA, CA 91902
Contact Telephone: 619-421-9847
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 09
Land Type: Private
Federal Waste Generator Description: Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: 4284 ACACIA AVE
Mailing City,State,Zip: BONITA, CA 91902
Owner Name: THOMAS DINANNO
Owner Type: Private
Operator Name: Not reported

THOMAS DINANNO (Continued) **1025879251**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-10-22 12:10:40.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

THOMAS DINANNO (Continued) **1025879251**

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D018
Waste Description: BENZENE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: THOMAS DINANNO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4284 ACACIA AVE
Owner/Operator City,State,Zip: BONITA, CA 91902
Owner/Operator Telephone: 619-421-9847
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2000-06-21 00:00:00.0
Handler Name: THOMAS DINANNO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E14 **CHULA VISTA MARINA** **RCRA NonGen / NLR** **1024792322**
South **550 MARINA PKWY** **CAL000120646**
1/8-1/4 **CHULA VISTA, CA 91910**
0.155 mi.
817 ft. **Site 2 of 3 in cluster E**

Relative: **Lower**
Actual: **8 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 1994-08-26 00:00:00.0
Handler Name: CHULA VISTA MARINA
Handler Address: 550 MARINA PKWY
Handler City,State,Zip: CHULA VISTA, CA 91910-4069

CHULA VISTA MARINA (Continued) **1024792322**

EPA ID:	CAL000120646
Contact Name:	ANDREA LAVALLEY MGR
Contact Address:	550 MARINA PKWY
Contact City,State,Zip:	CHULA VISTA, CA 91910
Contact Telephone:	619-691-1860
Contact Fax:	619-420-9667
Contact Email:	ANDREA@CVMARINA.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	550 MARINA PKWY
Mailing City,State,Zip:	CHULA VISTA, CA 91910-0000
Owner Name:	ACTIVE CARE LIVING
Owner Type:	Other
Operator Name:	ANDREA LAVALLEY MGR
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CHULA VISTA MARINA (Continued) **1024792322**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 15:42:44.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ACTIVE CARE LIVING
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	550 MARINA PKWY
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910-0000
Owner/Operator Telephone:	619-691-1860
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ANDREA LAVALLEY MGR
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	550 MARINA PKWY
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-691-1860
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1994-08-26 00:00:00.0
Handler Name: CHULA VISTA MARINA	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CHULA VISTA MARINA (Continued) **1024792322**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 71393
NAICS Description: MARINAS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E15 **CHULA VISTA MARINA** **San Diego Co. HMMD** **S110497331**
South **550 MARINA PY** **CERS HAZ WASTE** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **HAZNET**
0.155 mi. **CERS**
817 ft. **Site 3 of 3 in cluster E** **HWTS**

Relative: **Lower**
Actual: **8 ft.**

HMMD SAN DIEGO:
Name: CHULA VISTA MARINA
Address: 550 MARINA PY
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 212365
Business Type: 6HK18
EPA Id Number: CAL000120646
APN: 760-048-01-01
Last HMMD Inspection: 07/02/2012
Facility Telephone: 619-691-1860
Permit Status: OPEN
Permit Expiration: 11/30/2012
Date Last Updated: 11/02/2012
Facility Owner: CHULA VISTA MARINA LLC
Facility Mailing Address: 550 MARINA PY
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910
UST Owner: Not reported
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 212365
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported

CHULA VISTA MARINA (Continued) **S110497331**

Hazardous Categories 2: Not reported

Permit Number: 212365
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: DRAINED
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 212365
Update Date: 11/02/2012
Inspection Date: 07/02/2012
Violation Code: 6HV1002
Violation: HMBP NOT ESTABISHED/IMPLEMENTED.
Violation Citation: Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity: ACTIVE

Permit Number: 212365
Update Date: 11/02/2012
Inspection Date: 07/02/2012
Violation Code: 6HV0226
Violation: HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation: Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity: ACTIVE

Permit Number: 212365
Update Date: 11/02/2012
Inspection Date: 07/26/2010
Violation Code: 6HV0131
Violation: UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation: A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity: ACTIVE

Name: CHULA VISTA MARINA
Address: 550 MARINA PY
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 212365
Business Type: 6HK18
EPA Id Number: CAL000120646
APN: 760-048-01-01
Last HMMD Inspection: 07/02/2012
Facility Telephone: 619-691-1860
Permit Status: OPEN
Permit Expiration: 11/30/2012
Date Last Updated: 11/02/2012
Facility Owner: CHULA VISTA MARINA LLC
Facility Mailing Address: 550 MARINA PY
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910
UST Owner: Not reported

CHULA VISTA MARINA (Continued) **S110497331**

Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 212365
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 212365
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: DRAINED
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 212365
Update Date: 11/02/2012
Inspection Date: 07/02/2012
Violation Code: 6HV1002
Violation: HMBP NOT ESTABISHED/IMPLEMENTED.
Violation Citation: Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity: ACTIVE

Permit Number: 212365
Update Date: 11/02/2012
Inspection Date: 07/02/2012
Violation Code: 6HV0226
Violation: HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation: Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity: ACTIVE

Permit Number: 212365
Update Date: 11/02/2012
Inspection Date: 07/26/2010
Violation Code: 6HV0131
Violation: UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation: A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity: ACTIVE

Name: CHULA VISTA MARINA
Address: 550 MARINA PKWY
City,State,Zip: CHULA VISTA, CA 91910

CHULA VISTA MARINA (Continued) **S110497331**

Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAL000120646
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-691-1860
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	03/26/2020
Facility Owner:	Not reported
Facility Mailing Address:	550 Marina Pkwy, Chula Vista, CA 91910
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	N
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-212365
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5532642
Return To Compliance Date:	2016-10-20T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-03-26T11:33:45.000
Inspection Date:	2016-10-19T14:05:00.000
Violation Code:	3030007 Failed to properly label/date hazardous waste container and/or tank. 22 CCR 66262.34(f)

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-212365
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5532642
Return To Compliance Date:	2016-10-20T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-03-26T11:33:45.000
Inspection Date:	2016-10-19T14:05:00.000
Violation Code:	3030004 Failed to properly manage, store, label, and/or recycle used oil filters and/or used fuel filters. HSC 25250.22; 22 CCR 66266.130

Record ID:	DEH2010-HUPFP-212365

CHULA VISTA MARINA (Continued) **S110497331**

Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-212365
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	4097327
Return To Compliance Date:	2014-10-20T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-03-26T11:33:45.000
Inspection Date:	2014-10-20T12:41:00.000
Violation Code:	1010002 Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet; HSC 6.95 25508(a)1A

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-212365
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	4097327
Return To Compliance Date:	2014-10-20T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-03-26T11:33:45.000
Inspection Date:	2014-10-20T12:41:00.000
Violation Code:	1010008 Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date. For facilities with invenntory that exceed EPCRA thresholds; failure to submit inventory reports (Activities, Owner/Operator, Hazardous Materials Descriptions and Map pages HSC 6.95 25508.2 / 19 CCR 4 2729.5(c)

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-212365
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5532642
Return To Compliance Date:	2016-10-20T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-03-26T11:33:45.000
Inspection Date:	2016-10-19T14:05:00.000
Violation Code:	3030015 Failed to accumulate or store hazardous waste in a lined/compatible container. (40 CFR 262.34(d)(2); 265.172) 22 CCR 66262.34(d)(2)

CHULA VISTA MARINA (Continued) **S110497331**

Waste and Materials:

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HWAST-0098328
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-11-28T02:32:56.000
Chemical Name:	WASTE 221 WASTE OIL & MIXED OIL
Common Name:	USED OIL
Case Number:	Not reported

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HWAST-0228667
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2020-03-26T11:33:51.000
Chemical Name:	WASTE 221 WASTE OIL & MIXED OIL
Common Name:	WASTE OIL & MIXED OIL
Case Number:	Not reported

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HWAST-0228668
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2020-03-26T11:33:51.000
Chemical Name:	Waste 222. Oil / water separation sludge
Common Name:	Waste Oily Water
Case Number:	Not reported

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0173235
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-10-23T02:37:26.000
Chemical Name:	WASTE 221 WASTE OIL & MIXED OIL
Common Name:	WASTE OIL & MIXED OIL
Case Number:	Not reported

Record ID:	DEH2010-HUPFP-212365
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0173236
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-10-23T02:37:26.000
Chemical Name:	Waste 222. Oil / water separation sludge
Common Name:	Waste Oily Water
Case Number:	Not reported

Record ID:	DEH2010-HUPFP-212365

CHULA VISTA MARINA (Continued) **S110497331**

Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HWAST-0098329
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-11-28T02:32:56.000
Chemical Name:	oily water
Common Name:	oily water
Case Number:	Not reported

CERS HAZ WASTE:

Name:	CHULA VISTA MARINA
Address:	550 MARINA PKWY
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	18974
CERS ID:	10358425
CERS Description:	Hazardous Waste Generator

HAZNET:

Name:	CHULA VISTA MARINA
Address:	550 MARINA PKWY
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 919104069
Contact:	ANDREA LAVALLEY MGR
Telephone:	6196911860
Mailing Name:	Not reported
Mailing Address:	550 MARINA PKWY
Year:	2011
Gepaid:	CAL000120646
TSD EPA ID:	CAT080013352
CA Waste Code:	223 - Unspecified oil-containing waste
Disposal Method:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.4587
Year:	2003
Gepaid:	CAL000120646
TSD EPA ID:	CAT080033681
CA Waste Code:	352 - Other organic solids
Disposal Method:	R01 - Recycler
Tons:	0.075
Year:	2001
Gepaid:	CAL000120646
TSD EPA ID:	CAT080033681
CA Waste Code:	352 - Other organic solids
Disposal Method:	R01 - Recycler
Tons:	0.4
Year:	1999
Gepaid:	CAL000120646
TSD EPA ID:	CAT080033681
CA Waste Code:	352 - Other organic solids
Disposal Method:	R01 - Recycler

CHULA VISTA MARINA (Continued) **S110497331**

Tons: 0.15

Year: 1998
Gepaid: CAL000120646
TSD EPA ID: CAT080033681
CA Waste Code: 352 - Other organic solids
Disposal Method: R01 - Recycler
Tons: 0.2293

Additional Info:
Year: 1999
Gen EPA ID: CAL000120646

Shipment Date: 19991012
Creation Date: 1/11/2000 0:00:00
Receipt Date: 19991027
Manifest ID: 99124777
Trans EPA ID: CAD028277036
Trans Name: Not reported
Trans 2 EPA ID: CAD028277036
Trans 2 Name: Not reported
TSDF EPA ID: CAT080033681
Trans Name: Not reported
TSDF Alt EPA ID: CAT080033681
TSDF Alt Name: Not reported
Waste Code Description: 352 - Other organic solids
RCRA Code: Not reported
Meth Code: R01 - Recycler
Quantity Tons: 0.15
Waste Quantity: 300
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 2001
Gen EPA ID: CAL000120646

Shipment Date: 20010927
Creation Date: 1/16/2002 0:00:00
Receipt Date: 20011008
Manifest ID: 20793065
Trans EPA ID: CAD028277036
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAT080033681
Trans Name: Not reported
TSDF Alt EPA ID: CAT080033681
TSDF Alt Name: Not reported
Waste Code Description: 352 - Other organic solids
RCRA Code: Not reported

CHULA VISTA MARINA (Continued) **S110497331**

Meth Code:	R01 - Recycler
Quantity Tons:	0.4
Waste Quantity:	800
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2011
Gen EPA ID:	CAL000120646
Shipment Date:	20110323
Creation Date:	6/4/2011 18:30:41
Receipt Date:	20110406
Manifest ID:	008147732JJK
Trans EPA ID:	CAD028277036
Trans Name:	ASBURY ENVIRONMENTAL SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	DEMENNO / KERDOON
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	223 - Unspecified oil-containing waste
RCRA Code:	Not reported
Meth Code:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons:	0.4587
Waste Quantity:	110
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1998
Gen EPA ID:	CAL000120646
Shipment Date:	19981216
Creation Date:	2/26/1999 0:00:00
Receipt Date:	19981229
Manifest ID:	98513310
Trans EPA ID:	CAD028277036
Trans Name:	Not reported
Trans 2 EPA ID:	CAD028277036
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080033681
Trans Name:	Not reported
TSDF Alt EPA ID:	CAT080033681
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids

CHULA VISTA MARINA (Continued) **S110497331**

RCRA Code: Not reported
Meth Code: R01 - Recycler
Quantity Tons: 0.2293
Waste Quantity: 55
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 2003
Gen EPA ID: CAL000120646

Shipment Date: 20030708
Creation Date: 7/28/2004 10:45:53
Receipt Date: 20030718
Manifest ID: 22459230
Trans EPA ID: CAD028277036
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAT080033681
Trans Name: Not reported
TSDF Alt EPA ID: CAT080033681
TSDF Alt Name: Not reported
Waste Code Description: 352 - Other organic solids
RCRA Code: Not reported
Meth Code: R01 - Recycler
Quantity Tons: 0.075
Waste Quantity: 150
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

CERS:
Name: CHULA VISTA MARINA
Address: 550 MARINA PKWY
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 18974
CERS ID: 10358425
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 18974
Site Name: CHULA VISTA MARINA
Violation Date: 10-19-2016
Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22
Violation Description: Failure to properly manage used oil and/or fuel filters in accordance with the requirements.
Violation Notes: Returned to compliance on 10/20/2016.
Violation Division: San Diego County Department of Env Health

CHULA VISTA MARINA (Continued) **S110497331**

Violation Program: HW
Violation Source: CERS

Site ID: 18974
Site Name: CHULA VISTA MARINA
Violation Date: 10-20-2014
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Notes: Returned to compliance on 10/20/2014.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 18974
Site Name: CHULA VISTA MARINA
Violation Date: 10-19-2016
Citation: 40 CFR 1 265.172 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.172
Violation Description: Failure to accumulate or store hazardous waste in container made of or lined with materials which will not react with, and are otherwise compatible with, the hazardous waste to be stored.
Violation Notes: Returned to compliance on 10/20/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS

Site ID: 18974
Site Name: CHULA VISTA MARINA
Violation Date: 10-19-2016
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description: Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes: Returned to compliance on 10/20/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS

Site ID: 18974
Site Name: CHULA VISTA MARINA
Violation Date: 10-20-2014
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Description: Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes: Returned to compliance on 10/20/2014.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

CHULA VISTA MARINA (Continued) **S110497331**

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-20-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Joaquino Billie Marcos Inspection ID:4097327
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-20-2014
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Joaquino Billie Marcos Inspection ID:4097327
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	11-13-2018
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Joaquino Billie Inspection ID:6023759
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	11-13-2018
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Joaquino Billie Inspection ID:6023759
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-19-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Herrera Zoraida Inspection ID:5532642
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-19-2016
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Herrera Zoraida Inspection ID:5532642
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Coordinates:

CHULA VISTA MARINA (Continued) **S110497331**

Site ID:	18974
Facility Name:	CHULA VISTA MARINA
Env Int Type Code:	HWG
Program ID:	10358425
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	32.624700
Longitude:	-117.102760

Affiliation:

Affiliation Type Desc:	Operator
Entity Name:	CHULA VISTA MARINA LLC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 691-1860

Affiliation Type Desc:	Parent Corporation
Entity Name:	CHULA VISTA MARINA
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	550 Marina Pkwy
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported

Affiliation Type Desc:	Environmental Contact
Entity Name:	Robert Zimmerman
Entity Title:	Not reported
Affiliation Address:	550 Marina Pkwy
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported

Affiliation Type Desc:	Legal Owner
Entity Name:	CHULA VISTA MARINA LLC
Entity Title:	Not reported
Affiliation Address:	550 Marina Pkwy
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States

CHULA VISTA MARINA (Continued) **S110497331**

Affiliation Zip: 91910
Affiliation Phone: (619) 691-1860

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880

HWTS:
Name: CHULA VISTA MARINA
Address: 550 MARINA PKWY
Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 919104069
EPA ID: CAL000120646
Inactive Date: Not reported
Create Date: 08/26/1994
Last Act Date: 08/25/2020
Mailing Name: SARAH EVEN MULCAHY
Mailing Address: 550 MARINA PKWY
Mailing Address 2: Not reported
Mailing City,State,Zip: CHULA VISTA, CA 919100000
Owner Name: ACTIVE CARE LIVING
Owner Address: 550 MARINA PKWY
Owner Address 2: Not reported
Owner City,State,Zip: CHULA VISTA, CA 919100000
Contact Name: SARAH MULCAHY
Contact Address: 550 MARINA PKWY
Contact Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 91910

NAICS:
EPA ID: CAL000120646
Create Date: 2002-12-03 15:25:10.000
NAICS Code: 71393
NAICS Description: Marinas
Issued EPA ID Date: 1994-08-26 00:00:00
Inactive Date: Not reported
Facility Name: CHULA VISTA MARINA
Facility Address: 550 MARINA PKWY
Facility Address 2: Not reported
Facility City: CHULA VISTA
Facility County: Not reported
Facility State: CA
Facility Zip: 919104069

F16 **AGUNDEZ CLAUDIA** **RCRA NonGen / NLR** **1026486316**
NE **410 COLORADO AVE #C** **CAC003092468**
1/8-1/4 **CHULA VISTA, CA 91910**
0.168 mi.
888 ft. **Site 1 of 3 in cluster F**

Relative: **Higher**

Actual: **28 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-11-11 00:00:00.0
Handler Name:	AGUNDEZ CLAUDIA	
Handler Address:		410 COLORADO AVE #C
Handler City,State,Zip:		CHULA VISTA, CA 91910
EPA ID:		CAC003092468
Contact Name:		CLAUDIA AGUNDEZ
Contact Address:		1580 MENDOCINO DR
Contact City,State,Zip:		CHULA VISTA, CA 91911
Contact Telephone:		664-387-8544
Contact Fax:		Not reported
Contact Email:		LIANNEMENDIAS@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1580 MENDOCINO DR
Mailing City,State,Zip:		CHULA VISTA, CA 91911
Owner Name:		CLAUDIA AGUNDEZ
Owner Type:		Other
Operator Name:		CLAUDIA AGUNDEZ
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

AGUNDEZ CLAUDIA (Continued) **1026486316**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-11-17 18:47:17.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CLAUDIA AGUNDEZ
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1580 MENDOCINO DR
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91911
Owner/Operator Telephone:	664-387-8544
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CLAUDIA AGUNDEZ
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1580 MENDOCINO DR
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91911
Owner/Operator Telephone:	664-387-8544
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

AGUNDEZ CLAUDIA (Continued) **1026486316**

Historic Generators:
Receive Date: 2020-11-11 00:00:00.0
Handler Name: AGUNDEZ CLAUDIA
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G17 **GBAHE TRAZIE** **RCRA NonGen / NLR** **1024751768**
ENE **456 COLORADO AVENUE #C** **CAC002971563**
1/8-1/4 **CHULA VISTA, CA 91910**
0.168 mi.
889 ft. **Site 1 of 6 in cluster G**

Relative: **Higher**
Actual: **25 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 2018-07-18 00:00:00.0
Handler Name: GBAHE TRAZIE
Handler Address: 456 COLORADO AVENUE #C
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAC002971563
Contact Name: GBAHE TRAZIE
Contact Address: 456 COLORADO AVENUE #C
Contact City,State,Zip: CHULA VISTA, CA 91910
Contact Telephone: 619-850-9190
Contact Fax: Not reported
Contact Email: SOCALREMEDIATION@GMAIL.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: 456 COLORADO AVENUE #C
Mailing City,State,Zip: CHULA VISTA, CA 91910
Owner Name: GBAHE TRAZIE

GBAHE TRAZIE (Continued) **1024751768**

Owner Type:	Other
Operator Name:	GBAHE TRAZIE
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-08-31 17:12:20.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

GBAHE TRAZIE (Continued) **1024751768**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: GBAHE TRAZIE
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 456 COLORADO AVENUE #C
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910
Owner/Operator Telephone: 619-850-9190
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GBAHE TRAZIE
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 456 COLORADO AVENUE #C
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910
Owner/Operator Telephone: 619-850-9190
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2018-07-18 00:00:00.0
Handler Name: GBAHE TRAZIE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D18 **FORMERLY THERMO KING** **SAN DIEGO CO. SAM** **S105694706**
NNE **340 BAY BL** **CPS-SLIC** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **CERS**
0.170 mi.
898 ft. **Site 2 of 4 in cluster D**

Relative:
Higher

Actual:
26 ft.

SAN DIEGO CO. SAM:

Name:	FORMERLY THERMO KING
Address:	340 BAY BL
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H31018-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	GW With No Beneficial Use Designation
Facility Status:	Closed Case
Date:	6/5/2007
Date Began:	6/4/1991

CPS-SLIC:

Name:	FORMERLY THERMO KING
Address:	340 BAY BL
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	06/05/2007
Global Id:	T0608199629
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H31018-001
Latitude:	32.634409
Longitude:	-117.099078
Case Type:	Cleanup Program Site
Case Worker:	JS
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	1639000
File Location:	Local Agency
Potential Media Affected:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	* Chlorinated Hydrocarbons
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	FORMERLY THERMO KING
Address:	340 BAY BL
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	207638
CERS ID:	T0608199629
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

D19 **FORMER THERMO-KING FAC.** **CPS-SLIC** **S104570309**
NNE **340 BAY BLVD** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.170 mi.
898 ft. **Site 3 of 4 in cluster D**

Relative: SLIC REG 9:
Higher

Actual:
26 ft.

Name:	FORMER THERMO-KING FAC.
Address:	340 BAY BLVD
City:	CHULA VISTA
Region:	9
Facilty Type:	Not reported
Status:	Dead
Sort Code:	20-0052.05
Waste Discharger Id:	Not reported
Local Case Num:	Not reported
Responsible Party:	CHULA VISTA, CITY OF
Category:	ENFORCEMENT
Class:	SLIC
Order Number:	Not reported
File Number:	1
Date Entered:	06/1991
End Date:	04/1996
Archive Box #:	915
Archive Box Storage:	3-1-13R
Archive Box Storage Location:	REDEVELOPMENT DEPARTMENT
Remarks:	Not reported

Name:	FORMER THERMO-KING FAC.
Address:	340 BAY BLVD
City:	CHULA VISTA
Region:	9
Facilty Type:	Not reported
Status:	Open
Sort Code:	20-0052.05
Waste Discharger Id:	Not reported
Local Case Num:	Not reported
Responsible Party:	CHULA VISTA, CITY OF
Category:	ENFORCEMENT
Class:	SLIC
Order Number:	Not reported
File Number:	2
Date Entered:	04/1996
End Date:	Not reported
Archive Box #:	0
Archive Box Storage:	Not reported
Archive Box Storage Location:	REDEVELOPMENT DEPARTMENT
Remarks:	Not reported

Name:	FORMER THERMO-KING FAC.
Address:	340 BAY BLVD
City:	CHULA VISTA
Region:	9
Facilty Type:	Not reported
Status:	Open
Sort Code:	20-0052.051
Waste Discharger Id:	X
Local Case Num:	Not reported
Responsible Party:	CHULA VISTA, CITY OF

FORMER THERMO-KING FAC. (Continued) **S104570309**

Category:	ENF. REPORT
Class:	SLIC
Order Number:	Not reported
File Number:	1
Date Entered:	07/1991
End Date:	Not reported
Archive Box #:	0
Archive Box Storage:	Not reported
Archive Box Storage Location:	REDEVELOPMENT DEPARTMENT
Remarks:	Not reported

D20 **THERMO KING OF SAN DIEGO, INC.** **SEMS-ARCHIVE** **1003879831**
NNE **340 BAY BOULEVARD** **CAD983658428**
1/8-1/4 **CHULA VISTA, CA 92010**
0.170 mi.
898 ft. **Site 4 of 4 in cluster D**

Relative:
Higher

Actual:
26 ft.

SEMS Archive:

Site ID:	0904766
EPA ID:	CAD983658428
Name:	THERMO KING OF SAN DIEGO, INC.
Address:	340 BAY BOULEVARD
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 92010
Cong District:	44
FIPS Code:	06073
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	09
Site ID:	0904766
EPA ID:	CAD983658428
Site Name:	THERMO KING OF SAN DIEGO, INC.
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1994-01-04 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	09
Site ID:	0904766
EPA ID:	CAD983658428
Site Name:	THERMO KING OF SAN DIEGO, INC.
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1993-02-08 05:00:00
Finish Date:	1993-02-08 05:00:00

THERMO KING OF SAN DIEGO, INC. (Continued) **1003879831**

Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0904766
EPA ID:	CAD983658428
Site Name:	THERMO KING OF SAN DIEGO, INC.
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1994-01-04 05:00:00
Qual:	N
Current Action Lead:	EPA Perf

H21 **MANNS TEXACO & U-HAUL** **San Diego Co. HMMD** **S104747597**
East **730 H ST** **SWEEPS UST** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.173 mi.
912 ft. **Site 1 of 13 in cluster H**

Relative:
Higher

Actual:
27 ft.

HMMD SAN DIEGO:

Name:	MANNS TEXACO & U-HAUL
Address:	730 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	112972
Business Type:	Not reported
EPA Id Number:	Not reported
APN:	571-030-12-00
Last HMMD Inspection:	06/10/1988
Facility Telephone:	619-426-1212
Permit Status:	INAC
Permit Expiration:	06/10/1988
Date Last Updated:	11/02/2012
Facility Owner:	WALLACE A MANN
Facility Mailing Address:	730 H ST
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910-4004
UST Owner:	WALLACE A MANN
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 112972 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	112972
Tank Type:	SINGLE WALL
Additional Id:	5
Capacity Gallons:	500

MANNS TEXACO & U-HAUL (Continued) **S104747597**

UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1988-09-19 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR
UST Name:	UNDERGROUND TANK 112972 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	112972
Tank Type:	SINGLE WALL
Additional Id:	4
Capacity Gallons:	6000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	REMOVED
Remove Close Date:	1988-09-19 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR
UST Name:	UNDERGROUND TANK 112972 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	112972
Tank Type:	SINGLE WALL
Additional Id:	1
Capacity Gallons:	6000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1988-09-19 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR
UST Name:	UNDERGROUND TANK 112972 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	112972
Tank Type:	SINGLE WALL
Additional Id:	2
Capacity Gallons:	6000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1988-09-19 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported

MANNS TEXACO & U-HAUL (Continued) **S104747597**

Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR
UST Name:	UNDERGROUND TANK 112972 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	112972
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	6000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1988-09-19 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

SWEEPS UST:

Name:	MANNS TEXACO & U-HAUL
Address:	730 H ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	12972
Number:	Not reported
Board Of Equalization:	44-022681
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012972-000001
Tank Status:	Not reported
Capacity:	500
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	WASTE
Content:	Not reported
Number Of Tanks:	5

Name:	MANNS TEXACO & U-HAUL
Address:	730 H ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	12972
Number:	Not reported
Board Of Equalization:	44-022681
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012972-000002
Tank Status:	Not reported

MANNS TEXACO & U-HAUL (Continued) **S104747597**

Capacity: 6000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: OTHER
Number Of Tanks: Not reported

Name: MANNS TEXACO & U-HAUL
Address: 730 H ST
City: CHULA VISTA
Status: Not reported
Comp Number: 12972
Number: Not reported
Board Of Equalization: 44-022681
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012972-000003
Tank Status: Not reported
Capacity: 6000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: MANNS TEXACO & U-HAUL
Address: 730 H ST
City: CHULA VISTA
Status: Not reported
Comp Number: 12972
Number: Not reported
Board Of Equalization: 44-022681
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012972-000004
Tank Status: Not reported
Capacity: 6000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Name: MANNS TEXACO & U-HAUL
Address: 730 H ST
City: CHULA VISTA
Status: Not reported
Comp Number: 12972
Number: Not reported
Board Of Equalization: 44-022681
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported

MANNS TEXACO & U-HAUL (Continued) **S104747597**

Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012972-000005
Tank Status:	Not reported
Capacity:	6000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported

H22 **FORMER EXXONMOBIL / MTS STATION** **CPS-SLIC S122853913**
East **745 H ST** **CERS N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.185 mi.
979 ft. **Site 2 of 13 in cluster H**

Relative:
Higher

Actual:
28 ft.

CPS-SLIC:

Name:	FORMER EXXONMOBIL / MTS STATION
Address:	745 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Open - Remediation**
Status Date:	05/08/2017
Global Id:	T0607310406
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.6298429059738
Longitude:	-117.094388008118
Case Type:	Cleanup Program Site
Case Worker:	LT
Local Agency:	Not reported
RB Case Number:	2090042
File Location:	Regional Board
Potential Media Affected:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	and the southern portion of former Colorado Avenue (Figure 2). The southeastern portion of the site (lots 7, 8, 17, and 18) was developed as a Humble-branded gasoline station from 1966 to 1972 and operated as an Exxon-branded gasoline service station from 1972 to 1978. The remaining portion of the site was vacant until developed as residential homes in approximately 1953. In 1980, the San Diego Metropolitan Transit Development Board acquired the site and developed it as an MTS train and bus station and associated parking lot. The former site configuration for the Humble/Exxon service station consisted of a service station building with two service bays, one hydraulic hoist, one clarifier, two dispenser islands south of the service station building, and three 8,000-gallon underground storage tanks (USTs), west of the service station building. The installation and removal dates of these improvements were not documented in the City of Chula Vista building records; however, station construction permits were obtained by Humble Oil in 1965. As part of an investigation for an adjacent gasoline station, PSH was encountered on the site. Due to the presence of petroleum hydrocarbons and the historic site use the DEH opened a case on this site.

Click here to access the California GeoTracker records for this facility:

FORMER EXXONMOBIL / MTS STATION (Continued) **S122853913**

CERS:
- Name: FORMER EXXONMOBIL / MTS STATION
- Address: 745 H ST
- City,State,Zip: CHULA VISTA, CA 91910
- Site ID: 198635
- CERS ID: T0607310406
- CERS Description: Cleanup Program Site

Affiliation:
- Affiliation Type Desc: Regional Board Caseworker
- Entity Name: LALITHA THOTAKURA - SAN DIEGO RWQCB (REGION 9)
- Entity Title: Not reported
- Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
- Affiliation City: SAN DIEGO
- Affiliation State: CA
- Affiliation Country: Not reported
- Affiliation Zip: Not reported
- Affiliation Phone: 6195213002

H23 **EXXONMOBIL OIL CORP 99MTS** **RCRA-SQG** **1014387324**
East **745 H STREET** **CAR000208108**
1/8-1/4 **CHULA VISTA, CA 91910**
0.185 mi.
979 ft. **Site 3 of 13 in cluster H**

Relative: **Higher**

Actual: **28 ft.**

RCRA-SQG:
- Date Form Received by Agency: 2017-09-27 00:00:00.0
- Handler Name: EXXONMOBIL OIL CORP 99MTS
- Handler Address: 745 H STREET
- Handler City,State,Zip: CHULA VISTA, CA 91910
- EPA ID: CAR000208108
- Contact Name: DONNA HYMES
- Contact Address: 800 E WASHINGTON ST
- Contact City,State,Zip: WEST CHESTER, PA 19380
- Contact Telephone: 610-430-8151
- Contact Fax: 610-430-8016
- Contact Email: DHYMES@JD2ENV.COM
- Contact Title: EXXONMOBIL HAZARDOUS WASTE COORD
- EPA Region: 09
- Land Type: Private
- Federal Waste Generator Description: Small Quantity Generator
- Non-Notifier: Not reported
- Biennial Report Cycle: Not reported
- Accessibility: Not reported
- Active Site Indicator: Handler Activities
- State District Owner: Not reported
- State District: Not reported
- Mailing Address: 800 E WASHINGTON ST
- Mailing City,State,Zip: WEST CHESTER, PA 19380
- Owner Name: METROPOLITAN TRANSIT SYSTEM MTS
- Owner Type: Private
- Operator Name: EXXONMOBIL ENVIRONMENTAL SVCS
- Operator Type: Private
- Short-Term Generator Activity: No
- Importer Activity: No
- Mixed Waste Generator: No
- Transporter Activity: No

EXXONMOBIL OIL CORP 99MTS (Continued) **1014387324**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2017-10-06 12:37:29.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

EXXONMOBIL OIL CORP 99MTS (Continued) **1014387324**

Waste Code: D008
Waste Description: LEAD

Waste Code: D018
Waste Description: BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	METROPOLITAN TRANSIT SYSTEM MTS
Legal Status:	Private
Date Became Current:	1980-09-24 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	1255 IMPERIAL AVE
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92101
Owner/Operator Telephone:	619-231-1466
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	METROPOLITAN TRANSIT DEVELOPMENT BOARD
Legal Status:	Municipal
Date Became Current:	1980-09-24 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	1255 IMPERIAL AVE
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92101
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	METROPOLITAN TRANSIT SYSTEM MTS
Legal Status:	Private
Date Became Current:	1980-09-24 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	1255 IMPERIAL AVE
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92101
Owner/Operator Telephone:	619-231-1466
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	EXXONMOBIL ENVIRONMENTAL SVCS
Legal Status:	Private
Date Became Current:	2009-09-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	EXXONMOBIL ENVIRONMENTAL SVCS

EXXONMOBIL OIL CORP 99MTS (Continued) **1014387324**

Legal Status:	Private
Date Became Current:	2009-09-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	EXXONMOBIL ENVIRONMENTAL SVCS
Legal Status:	Private
Date Became Current:	2009-09-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	22777 SPRINGWOODS VILLAGE PKWY
Owner/Operator City,State,Zip:	SPRING, TX 77389
Owner/Operator Telephone:	832-624-6081
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JIMMY.J.STREET@EXXONMOBIL.COM

Historic Generators:

Receive Date:	2017-09-27 00:00:00.0
Handler Name:	EXXONMOBIL OIL CORP 99MTS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No
Receive Date:	2010-03-25 00:00:00.0
Handler Name:	EXXONMOBIL OIL CORP 99MTS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	Yes
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2014-09-17 00:00:00.0
Handler Name:	EXXONMOBIL OIL CORP 99MTS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

EXXONMOBIL OIL CORP 99MTS (Continued) **1014387324**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 48511
NAICS Description: URBAN TRANSIT SYSTEMS

NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

H24 **MTDB** **SAN DIEGO CO. SAM** **S106875131**
East **745 H ST** **CPS-SLIC** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **SAN DIEGO CO LOP**
0.185 mi. **CERS**
979 ft. **Site 4 of 13 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

SAN DIEGO CO. SAM:
Name: MTDB
Address: 745 H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H39642-001
Agency: CA Regional Water Quality Control Board
Funding: **Non Billable**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 11/24/2003
Date Began: 4/1/2003

Name: MTDB
Address: 745 H ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H39642-002
Agency: DEH Site Assessment & Mitigation
Funding: **XV**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 7/3/2008
Date Began: Not reported

CPS-SLIC:
Name: MTDB
Address: 745 H ST
City,State,Zip: CHULA VISTA, CA 91910

MTDB (Continued) **S106875131**

Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	07/24/2009
Global Id:	T10000000291
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H39642-002
Latitude:	32.6298203171667
Longitude:	-117.094484567642
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Not reported
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

SAN DIEGO CO LOP:

Name:	MTDB
Address:	745 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH2003-LSAM-H39642-001
Record Status:	Completed
Opened Date:	10/10/2003
Parcel Number:	567-190-29-00
Case Type:	Not reported
Historical Name:	MTDB
SWRCB Global ID:	T0607310406
Funding:	N - Non-Billable
Lead Agency:	RWQCB
Lead Agency Date:	06/25/2009
Census Tract:	125.01
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6301266
Longitude:	-117.0947830
X MapCoord:	6301562.885
Y MapCoord:	1810132.012

CERS:

Name:	MTDB
Address:	745 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	250092
CERS ID:	T10000000291
CERS Description:	Cleanup Program Site

H25 **H STREET TRANSIT STATION** **RCRA-SQG** **1010562143**
East **745 H ST** **CAR000187492**
1/8-1/4 **CHULA VISTA, CA 91910**
0.185 mi.
979 ft. **Site 5 of 13 in cluster H**

Relative: **Higher**

Actual: **28 ft.**

RCRA-SQG:

Date Form Received by Agency:	2007-09-24 00:00:00.0
Handler Name:	H STREET TRANSIT STATION
Handler Address:	745 H ST
Handler City,State,Zip:	CHULA VISTA, CA 91910
EPA ID:	CAR000187492
Contact Name:	TIM ALLISON
Contact Address:	1225 IMPERIAL AVE
Contact City,State,Zip:	SAN DIEGO, CA 92101
Contact Telephone:	619-595-4903
Contact Fax:	Not reported
Contact Email:	TIM.ALLISON@SDMTS.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1225 IMPERIAL AVE
Mailing City,State,Zip:	SAN DIEGO, CA 92101
Owner Name:	METROPOLITAN TRANSIT DEVELOPMENT BOARD
Owner Type:	Municipal
Operator Name:	METROPOLITAN TRANSIT DEVELOPMENT BOARD
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

H STREET TRANSIT STATION (Continued) **1010562143**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2007-10-12 18:47:46.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	METROPOLITAN TRANSIT DEVELOPMENT BOARD
Legal Status:	Municipal
Date Became Current:	1979-04-24 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	1225 IMPERIAL AVE
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92101
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	METROPOLITAN TRANSIT DEVELOPMENT BOARD
Legal Status:	Municipal
Date Became Current:	1981-07-26 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

H STREET TRANSIT STATION (Continued) **1010562143**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2007-09-24 00:00:00.0
Handler Name: H STREET TRANSIT STATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 485112
NAICS Description: COMMUTER RAIL SYSTEMS

NAICS Code: 485113
NAICS Description: BUS AND OTHER MOTOR VEHICLE TRANSIT SYSTEMS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F26 **MC INVESTMENT PARTNERS, LLC** **RCRA NonGen / NLR** **1026169251**
ENE **423 COLORADO AVE** **CAC003069299**
1/8-1/4 **CHULA VISTA, CA 91910**
0.193 mi.
1019 ft. **Site 2 of 3 in cluster F**

Relative: RCRA NonGen / NLR:
Higher Date Form Received by Agency: 2020-06-03 00:00:00.0
Actual: Handler Name: MC INVESTMENT PARTNERS, LLC
28 ft. Handler Address: 423 COLORADO AVE
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAC003069299
Contact Name: MANOJ RAJEGOWDA
Contact Address: 1200 PROSPECT STREET
Contact City,State,Zip: LA JOLLA, CA 92037
Contact Telephone: 646-239-2669
Contact Fax: Not reported
Contact Email: VANESSAPIZARRO@ALLIANCE-ENVIRO.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported

MC INVESTMENT PARTNERS, LLC (Continued) **1026169251**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1200 PROSPECT STREET
Mailing City,State,Zip:	LA JOLLA, CA 92037
Owner Name:	MC INVESTMENT PARTNERS, LLC
Owner Type:	Other
Operator Name:	MANOJ RAJEGOWDA
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

MC INVESTMENT PARTNERS, LLC (Continued) **1026169251**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-06-08 20:36:47.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MC INVESTMENT PARTNERS, LLC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1200 PROSPECT STREET
Owner/Operator City,State,Zip:	LA JOLLA, CA 92037
Owner/Operator Telephone:	646-239-2669
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MANOJ RAJEGOWDA
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1200 PROSPECT STREET
Owner/Operator City,State,Zip:	LA JOLLA, CA 92037
Owner/Operator Telephone:	646-239-2669
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-06-03 00:00:00.0
Handler Name:	MC INVESTMENT PARTNERS, LLC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

MC INVESTMENT PARTNERS, LLC (Continued) **1026169251**

Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G27 **THE NAJAR FAMILY TRUST** **RCRA NonGen / NLR** **1026470857**
ENE **455 COLORADO AVE, UNIT D** **CAC003076413**
1/8-1/4 **CHULA VISTA, CA 91910**
0.193 mi.
1020 ft. **Site 2 of 6 in cluster G**

Relative:
Higher

Actual:
28 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-07-27 00:00:00.0
Handler Name:	THE NAJAR FAMILY TRUST	
Handler Address:		455 COLORADO AVE, UNIT D
Handler City,State,Zip:		CHULA VISTA, CA 91910
EPA ID:		CAC003076413
Contact Name:		THE NAJAR FAMILY TRUST
Contact Address:		10121 BURROCK DR
Contact City,State,Zip:		SANTEE, CA 92071
Contact Telephone:		619-807-7662
Contact Fax:		Not reported
Contact Email:		ERIKAM@CVECORP.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		10121 BURROCK DR
Mailing City,State,Zip:		SANTEE, CA 92071
Owner Name:		THE NAJAR FAMILY TRUST
Owner Type:		Other
Operator Name:		THE NAJAR FAMILY TRUST
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

THE NAJAR FAMILY TRUST (Continued) **1026470857**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-08-14 15:09:36.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	THE NAJAR FAMILY TRUST
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	10121 BURROCK DR
Owner/Operator City,State,Zip:	SANTEE, CA 92071
Owner/Operator Telephone:	619-807-7662
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	THE NAJAR FAMILY TRUST
Legal Status:	Other
Date Became Current:	Not reported

THE NAJAR FAMILY TRUST (Continued) **1026470857**

Date Ended Current: Not reported
Owner/Operator Address: 10121 BURROCK DR
Owner/Operator City,State,Zip: SANTEE, CA 92071
Owner/Operator Telephone: 619-807-7662
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2020-07-27 00:00:00.0
Handler Name: THE NAJAR FAMILY TRUST
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G28 **ARCELIA GONZALEZ** **RCRA NonGen / NLR** **1026470231**
ENE **455 COLORADO AVE UNIT D** **CAC003075750**
1/8-1/4 **CHULA VISTA, CA 91910**
0.193 mi.
1020 ft. **Site 3 of 6 in cluster G**

Relative: RCRA NonGen / NLR:
Higher Date Form Received by Agency: 2020-07-21 00:00:00.0
Actual: Handler Name: ARCELIA GONZALEZ
28 ft. Handler Address: 455 COLORADO AVE UNIT D
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAC003075750
Contact Name: ARCELIA GONZALEZ
Contact Address: 11622 EL CAMINO REAL, STE 100
Contact City,State,Zip: SAN DIEGO, CA 92130
Contact Telephone: 619-229-2440
Contact Fax: Not reported
Contact Email: ERIKAM@CVECORP.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported

ARCELIA GONZALEZ (Continued) **1026470231**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	11622 EL CAMINO REAL, STE 100
Mailing City,State,Zip:	SAN DIEGO, CA 92130
Owner Name:	ARCELIA GONZALEZ
Owner Type:	Other
Operator Name:	ARCELIA GONZALEZ
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

ARCELIA GONZALEZ (Continued) **1026470231**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-08-14 15:09:23.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ARCELIA GONZALEZ
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	11622 EL CAMINO REAL, STE 100
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92130
Owner/Operator Telephone:	619-229-2440
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ARCELIA GONZALEZ
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	11622 EL CAMINO REAL, STE 100
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92130
Owner/Operator Telephone:	619-229-2440
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-07-21 00:00:00.0
Handler Name: ARCELIA GONZALEZ	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

ARCELIA GONZALEZ (Continued) **1026470231**

Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G29 **RYAN ABIDES** **RCRA NonGen / NLR** **1025852824**
ENE **443 COLORADO AVE** **CAC003033005**
1/8-1/4 **CHULA VISTA, CA 91910**
0.193 mi.
1020 ft. **Site 4 of 6 in cluster G**

Relative: **Higher**
Actual: **28 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2019-09-09 00:00:00.0
Handler Name:	RYAN ABIDES	
Handler Address:		443 COLORADO AVE
Handler City,State,Zip:		CHULA VISTA, CA 91910
EPA ID:		CAC003033005
Contact Name:		RYAN ABIDES
Contact Address:		443 COLORADO AVE
Contact City,State,Zip:		CHULA VISTA, CA 91910
Contact Telephone:		619-240-4282
Contact Fax:		Not reported
Contact Email:		KERRIEP@CVECORP.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		443 COLORADO AVE
Mailing City,State,Zip:		CHULA VISTA, CA 91910
Owner Name:		RYAN ABIDES
Owner Type:		Other
Operator Name:		RYAN ABIDES
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---

RYAN ABIDES (Continued) **1025852824**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-09-13 17:13:41.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RYAN ABIDES
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	443 COLORADO AVE
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-240-4282
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RYAN ABIDES
Legal Status:	Other
Date Became Current:	Not reported

RYAN ABIDES (Continued) **1025852824**

Date Ended Current:	Not reported
Owner/Operator Address:	443 COLORADO AVE
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-240-4282
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2019-09-09 00:00:00.0
Handler Name: RYAN ABIDES	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

F30 **DASHAWN PALMER** **RCRA NonGen / NLR** **1026160967**
NE **724 G ST** **CAC003060947**
1/8-1/4 **CHULA VISTA, CA 91910**
0.196 mi.
1035 ft. **Site 3 of 3 in cluster F**

Relative: **Higher**

Actual: **30 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-03-20 00:00:00.0
Handler Name:	DASHAWN PALMER	
Handler Address:		724 G ST
Handler City,State,Zip:		CHULA VISTA, CA 91910
EPA ID:		CAC003060947
Contact Name:		DASHAWN PALMER
Contact Address:		724 G ST
Contact City,State,Zip:		CHULA VISTA, CA 91910
Contact Telephone:		716-541-5814
Contact Fax:		Not reported
Contact Email:		DPALMER477@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported

DASHAWN PALMER (Continued) **1026160967**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	724 G ST
Mailing City,State,Zip:	CHULA VISTA, CA 91910
Owner Name:	DASHAWN PALMER
Owner Type:	Other
Operator Name:	DASHAWN PALMER
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

DASHAWN PALMER (Continued) **1026160967**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-08 18:59:04.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	DASHAWN PALMER
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	724 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	716-541-5814
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DASHAWN PALMER
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	724 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	716-541-5814
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-03-20 00:00:00.0
Handler Name: DASHAWN PALMER	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

DASHAWN PALMER (Continued) **1026160967**

Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G31 **MC INVESTMENT PARTNERS, LLC** **RCRA NonGen / NLR** **1026162545**
East **467 COLORADO AVE** **CAC003062531**
1/8-1/4 **CHULA VISTA, CA 91910**
0.196 mi.
1035 ft. **Site 5 of 6 in cluster G**

Relative: **Higher**
Actual: **28 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2020-04-06 00:00:00.0
Handler Name:	MC INVESTMENT PARTNERS, LLC
Handler Address:	467 COLORADO AVE
Handler City,State,Zip:	CHULA VISTA, CA 91910
EPA ID:	CAC003062531
Contact Name:	MINOJ RAJEGOWDA
Contact Address:	1200 PROSPECT STREET
Contact City,State,Zip:	LA JOLLA, CA 92037
Contact Telephone:	646-239-2669
Contact Fax:	Not reported
Contact Email:	VANESSAPIZARRO@ALLIANCE-ENVIRO.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1200 PROSPECT STREET
Mailing City,State,Zip:	LA JOLLA, CA 92037
Owner Name:	MC INVESTMENT PARTNERS, LLC
Owner Type:	Other
Operator Name:	MINOJ RAJEGOWDA
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---

MC INVESTMENT PARTNERS, LLC (Continued) **1026162545**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-08 18:59:37.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MC INVESTMENT PARTNERS, LLC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1200 PROSPECT STREET
Owner/Operator City,State,Zip:	LA JOLLA, CA 92037
Owner/Operator Telephone:	646-239-2669
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MINOJ RAJEGOWDA
Legal Status:	Other
Date Became Current:	Not reported

MC INVESTMENT PARTNERS, LLC (Continued) **1026162545**

Date Ended Current:	Not reported
Owner/Operator Address:	1200 PROSPECT STREET
Owner/Operator City,State,Zip:	LA JOLLA, CA 92037
Owner/Operator Telephone:	646-239-2669
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-04-06 00:00:00.0
Handler Name:	MC INVESTMENT PARTNERS, LLC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

H32 **ARCO MINI MARKET** **LUST** **S100731291**
East **720 H ST** **San Diego Co. HMMD** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **CERS HAZ WASTE**
0.203 mi. **CERS TANKS**
1074 ft. **Site 6 of 13 in cluster H** **HIST CORTESE**
CERS

Relative:
Higher

Actual:
28 ft.

LUST REG 9:

Region:	9
Status:	Preliminary site assessment underway
Case Number:	9UT3103
Local Case:	H20106-001
Substance:	Unleaded Gasoline
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Subsurface Monitoring
How Stopped:	Not reported
Source:	Not reported
Cause:	Not reported
Lead Agency:	Local Agency
Case Type:	Aquifer affected
Date Found:	07/25/1995

ARCO MINI MARKET (Continued) **S100731291**

Date Stopped: / /
Confirm Date: 07/25/1995
Submit Workplan: Not reported
Prelim Assess: 08/30/1995
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 07/25/1995
Enforce Date: 8/29/95
Closed Date: Not reported
Enforce Type: SEL
Pilot Program: LOP
Basin Number: 909.11
GW Depth: Not reported
Beneficial Use: MUNBU
NPDES Number: Not reported
Priority: High priority
File Dispn: Not reported
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

LUST:
Name: ARCO AM/PM MINI MARKET #1914
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 919104004
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301869
Global Id: T0607301869
Latitude: 32.6294498599177
Longitude: -117.094243168831
Status: Completed - Case Closed
Status Date: 04/07/2020
Case Worker: LT
RB Case Number: 9UT3103
Local Agency: Not reported
File Location: Local Agency
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: In April 1995, Liquid Phase Hydrocarbons were identified on site. Site assessment activities have been ongoing to determine the extent of the contamination plume for this site. Joint monitoring is occuring between this site and the MTDB site (DEH case # H39642-001). Joint monitoring is utilized to compare both sites and ensure that the data will represent a larger area for data analysis. Please see the Environmental Data tab for additional site specific informaiton.

LUST:
Global Id: T0607301869
Contact Type: Regional Board Caseworker
Contact Name: LALITHA THOTAKURA
Organization Name: SAN DIEGO RWQCB (REGION 9)
Address: 2375 NORTHSIDE DRIVE, SUITE 100
City: SAN DIEGO

ARCO MINI MARKET (Continued) **S100731291**

Email: lalitha.thotakura@waterboards.ca.gov
Phone Number: 6195213002

LUST:

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 08/06/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 07/19/2018
Action: Email Correspondence

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 06/29/2018
Action: Referral to Regional Board

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 09/11/2018
Action: Email Correspondence

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 01/25/2019
Action: Staff Letter

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 11/06/2018
Action: Notification - Public Notice of Case Closure

Global Id: T0607301869
Action Type: Other
Date: 07/25/1995
Action: Leak Reported

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 07/15/2009
Action: Letter - Notice

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 03/05/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301869
Action Type: RESPONSE
Date: 01/30/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/30/2012

ARCO MINI MARKET (Continued) **S100731291**

Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 04/07/2020
Action: Closure/No Further Action Letter

Global Id: T0607301869
Action Type: RESPONSE
Date: 11/10/2008
Action: Monitoring Report - Quarterly

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/30/2009
Action: Monitoring Report - Quarterly

Global Id: T0607301869
Action Type: RESPONSE
Date: 05/04/2009
Action: Monitoring Report - Quarterly

Global Id: T0607301869
Action Type: RESPONSE
Date: 10/30/2009
Action: Monitoring Report - Quarterly

Global Id: T0607301869
Action Type: RESPONSE
Date: 01/30/2014
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 01/16/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301869
Action Type: RESPONSE
Date: 01/30/2009
Action: Monitoring Report - Quarterly

Global Id: T0607301869
Action Type: RESPONSE
Date: 01/30/2010
Action: Monitoring Report - Quarterly

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/30/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 04/04/2017
Action: Technical Correspondence / Assistance / Other

ARCO MINI MARKET (Continued) **S100731291**

Global Id: T0607301869
Action Type: Other
Date: 07/25/1995
Action: Leak Began

Global Id: T0607301869
Action Type: RESPONSE
Date: 08/05/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/30/2017
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 06/07/2019
Action: Well Destruction Report

Global Id: T0607301869
Action Type: RESPONSE
Date: 08/29/2019
Action: Well Destruction Report

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/30/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 01/30/2017
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 09/28/2016
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 10/05/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301869
Action Type: Other
Date: 07/25/1995
Action: Leak Discovery

Global Id: T0607301869
Action Type: RESPONSE

ARCO MINI MARKET (Continued) **S100731291**

Date: 01/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/31/2018
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 01/30/2018
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/30/2014
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301869
Action Type: RESPONSE
Date: 09/15/2015
Action: Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Global Id: T0607301869
Action Type: ENFORCEMENT
Date: 08/29/1995
Action: Notice of Responsibility

Global Id: T0607301869
Action Type: RESPONSE
Date: 02/26/2016
Action: Soil Vapor Intrusion Investigation Report - Regulator Responded

Global Id: T0607301869
Action Type: RESPONSE
Date: 02/03/2017
Action: Well Installation Workplan - Regulator Responded

Global Id: T0607301869
Action Type: REMEDIATION
Date: 06/24/2002
Action: Soil Vapor Extraction (SVE)

Global Id: T0607301869
Action Type: Other
Date: 07/25/1995
Action: Leak Stopped

Global Id: T0607301869
Action Type: RESPONSE
Date: 07/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607301869
Action Type: RESPONSE
Date: 01/30/2012
Action: Monitoring Report - Semi-Annually

ARCO MINI MARKET (Continued) **S100731291**

LUST:

Global Id:	T0607301869
Status:	Open - Case Begin Date
Status Date:	07/25/1995
Global Id:	T0607301869
Status:	Open - Remediation
Status Date:	02/23/2004
Global Id:	T0607301869
Status:	Completed - Case Closed
Status Date:	04/07/2020

HMMD SAN DIEGO:

Name:	ARCO FACILITY NO. 1914
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	120106
Business Type:	6HK28
EPA Id Number:	CAL000225443
APN:	571-030-09-00
Last HMMD Inspection:	01/12/2011
Facility Telephone:	619-425-5356
Permit Status:	SUSP
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	BP WEST COAST PRODUCTS LLC
Facility Mailing Address:	PO BOX 6038
Facility Mailing City:	ARTESIA
Facility Mailing State:	CA
Facility Mailing Zip:	90702-6038
UST Owner:	BP WEST COAST PRODUCTS LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	120106
Update Date:	11/02/2012
Case Number:	74-98-6
Name:	PROPANE
Other Information:	LPG
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	CRYOGENIC
Permit Number:	120106
Update Date:	11/02/2012
Case Number:	Not reported
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 120106 T005
Material Waste:	Material
Hazardous Categories 1:	FIRE

ARCO MINI MARKET (Continued) **S100731291**

Hazardous Categories 2: Not reported

Permit Number: 120106
Update Date: 11/02/2012
Case Number: Not reported
Name: SUPER UNLEADED
Other Information: UNDERGROUND TANK 120106 T004
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 120106
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: FUEL/H20
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120106
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED GASOLINE FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 120106
Update Date: 11/02/2012
Inspection Date: 01/31/2003
Violation Code: 6HV3113
Violation: 2NDRY CONT TEST NOT SENT TO CUPA
Violation Citation: Secondary Containment testing not submitted to CUPA within 30 days. 2637(a)(4)
Activity: SUSP

UST:
UST Name: UNDERGROUND TANK 120106 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 120106
Tank Type: SINGLE WALL
Additional Id: NT2259 SUPER UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 20
UST Monitor Method: DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

ARCO MINI MARKET (Continued) **S100731291**

UST Name:	UNDERGROUND TANK 120106 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	SINGLE WALL
Additional Id:	NT2259 PLUS UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 120106 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	SINGLE WALL
Additional Id:	NT2259 REGULAR UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name:	UNDERGROUND TANK 120106 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4294/RT4116
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 120106 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4116
Capacity Gallons:	20000

ARCO MINI MARKET (Continued) **S100731291**

UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2001-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name: ARCO FACILITY NO. 1914
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 120106
Business Type: 6HK28
EPA Id Number: CAL000225443
APN: 571-030-09-00
Last HMMD Inspection: 01/12/2011
Facility Telephone: 619-425-5356
Permit Status: SUSP
Permit Expiration: 01/31/2013
Date Last Updated: 11/02/2012
Facility Owner: BP WEST COAST PRODUCTS LLC
Facility Mailing Address: PO BOX 6038
Facility Mailing City: ARTESIA
Facility Mailing State: CA
Facility Mailing Zip: 90702-6038
UST Owner: BP WEST COAST PRODUCTS LLC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 120106
Update Date: 11/02/2012
Case Number: 74-98-6
Name: PROPANE
Other Information: LPG
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CRYOGENIC

Permit Number: 120106
Update Date: 11/02/2012
Case Number: Not reported
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 120106 T005
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 120106
Update Date: 11/02/2012

ARCO MINI MARKET (Continued) **S100731291**

Case Number: Not reported
Name: SUPER UNLEADED
Other Information: UNDERGROUND TANK 120106 T004
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 120106
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: FUEL/H20
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120106
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED GASOLINE FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 120106
Update Date: 11/02/2012
Inspection Date: 01/31/2003
Violation Code: 6HV3113
Violation: 2NDRY CONT TEST NOT SENT TO CUPA
Violation Citation: Secondary Containment testing not submitted to CUPA within 30 days. 2637(a)(4)
Activity: SUSP

UST:
UST Name: UNDERGROUND TANK 120106 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 120106
Tank Type: SINGLE WALL
Additional Id: NT2259 SUPER UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 20
UST Monitor Method: DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name: UNDERGROUND TANK 120106 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 120106

ARCO MINI MARKET (Continued) **S100731291**

Tank Type:	SINGLE WALL
Additional Id:	NT2259 PLUS UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 120106 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	SINGLE WALL
Additional Id:	NT2259 REGULAR UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name:	UNDERGROUND TANK 120106 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4294/RT4116
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 120106 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4116
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE

ARCO MINI MARKET (Continued) **S100731291**

Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	"H" STREET ARCO
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAL000267011
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-425-5356
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	08/11/2020
Facility Owner:	Not reported
Facility Mailing Address:	720 H ST, Chula Vista , CA 91910
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	Y
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-215933
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	4963339
Return To Compliance Date:	2014-01-02T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	91
Container/Tank Id:	Not reported
Last Update:	2020-08-11T01:13:19.000
Inspection Date:	2014-01-02T21:30:00.000
Violation Code:	2030016 Failure to continuously monitor the interstitial space of the tank, piping and/or sumps sump such that the leak detection activates an audible/visual alarm when a leak is detected. 23 CCR 16 2631(g), 2632(c)(2)(A)&(B), 2633(c), 2636(f).

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-215933

ARCO MINI MARKET (Continued) **S100731291**

Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5831646
Return To Compliance Date:	2018-01-04T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	24788
Container/Tank Id:	Not reported
Last Update:	2020-08-11T01:13:19.000
Inspection Date:	2018-01-04T05:14:22.000
Violation Code:	2060020 (RP) Failure to comply with one or more of the following: Failure to install or maintain a liquid-tight spill bucket, have a minimum capacity of 5 gallons, have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container, and/or be resistant to galvanic corrosion. 23 CCR 2635(b), 2665

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-215933
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6056664
Return To Compliance Date:	2019-01-30T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	24787
Container/Tank Id:	Not reported
Last Update:	2020-08-11T01:13:19.000
Inspection Date:	2019-01-16T00:00:00.000
Violation Code:	2030036 (TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. 6. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. 7. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. 8. Inspected within 30 days after a repair to the overfill prevention equipment. 9. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 10. Inspected by a certified UST service technician. 11. Maintain records of overfill prevention equipment inspection for 36 months. 23 CCR 2635(c)(1), 2635(d), 2637.2(a-c), 2665, 2712(b)(1)(G)

ARCO MINI MARKET (Continued) **S100731291**

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-215933
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	4452056
Return To Compliance Date:	2013-07-01T00:00:00.000
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-08-11T01:13:19.000
Inspection Date:	2013-01-03T12:32:00.000
Violation Code:	1010005 25509(a)(7) Failure to complete and/or submit an annotated site map if required by CUPA; 19 CCR 4 2729.2(a)(3).

UST DTL:

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-215933
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	GS & SS PETROLEUM, INC
Tankid:	24788
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	Motor Vehicle Fueling
Piping System Type:	Pressure
Last Updated:	2020-08-11T01:13:29.000
Tank Capacityin Gallons:	20000
Tank Contents:	Regular Unleaded
Type Of Tank:	Double Wall

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-215933
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	GS & SS PETROLEUM, INC
Tankid:	24787
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	Motor Vehicle Fueling
Piping System Type:	Pressure
Last Updated:	2020-08-11T01:13:29.000
Tank Capacityin Gallons:	12000
Tank Contents:	Premium Unleaded
Type Of Tank:	Double Wall

Waste and Materials:

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0131202
Trade Secret:	N

ARCO MINI MARKET (Continued) **S100731291**

Hazardous Material Type: Pure
Last Updated: 2017-04-18T12:22:08.000
Chemical Name: Gasoline
Common Name: UNDERGROUND TANK 120106 T005
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0131203
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-04-18T12:22:08.000
Chemical Name: Gasoline
Common Name: UNDERGROUND TANK 120106 T004
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0109646
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-04-18T12:22:08.000
Chemical Name: Gasoline Contaminated Liquids
Common Name: Sump Water, Spill Bucket Water, SB989 Testing Water (HAZWASTE)
Case Number: Not reported

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0109647
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-04-18T12:22:08.000
Chemical Name: Used Spill Kit and Used Fuel Filters
Common Name: Fuel Contaminated Waste Absorbent & Used Fuel Filters (HAZWASTE)
Case Number: Not reported

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0177578
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-04-09T12:54:49.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0177579
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-04-09T12:54:49.000

ARCO MINI MARKET (Continued) **S100731291**

Chemical Name: Gasoline
Common Name: Underground Tank 120106 T005
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0177580
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-04-09T12:54:49.000
Chemical Name: Gasoline
Common Name: Underground Tank 120106 T004
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0152122
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-04-09T12:54:49.000
Chemical Name: Gasoline Contaminated Liquids
Common Name: Sump Water, Spill Bucket Water, SB989 Testing Water (HAZWASTE)
Case Number: Not reported

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0152123
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-04-09T12:54:49.000
Chemical Name: Used Spill Kit and Used Fuel Filters
Common Name: Fuel Contaminated Waste Absorbent & Used Fuel Filters (HAZWASTE)
Case Number: Not reported

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0165273
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-03-07T00:34:44.000
Chemical Name: Gasoline
Common Name: Underground Tank 120106 T005
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0206840
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-06-01T00:54:12.000
Chemical Name: Gasoline
Common Name: Underground Tank 120106 T004

ARCO MINI MARKET (Continued) **S100731291**

Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0206841
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-06-01T00:54:12.000
Chemical Name: Gasoline
Common Name: Underground Tank 120106 T005
Case Number: 86290-81-5

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0206842
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-06-01T00:54:12.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0178635
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-06-01T00:54:13.000
Chemical Name: Used Spill Kit and Used Fuel Filters
Common Name: Fuel Contaminated Waste Absorbent & Used Fuel Filters (HAZWASTE)
Case Number: Not reported

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0178636
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-06-01T00:54:13.000
Chemical Name: Gasoline Contaminated Liquids
Common Name: Sump Water, Spill Bucket Water, SB989 Testing Water (HAZWASTE)
Case Number: Not reported

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0213961
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-08-11T01:13:28.000
Chemical Name: Used Spill Kit and Used Fuel Filters
Common Name: Fuel Contaminated Waste Absorbent & Used Fuel Filters (HAZWASTE)
Case Number: Not reported

ARCO MINI MARKET (Continued) **S100731291**

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HWAST-0213962
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2020-08-11T01:13:28.000
Chemical Name:	Gasoline Contaminated Liquids
Common Name:	Sump Water, Spill Bucket Water, SB989 Testing Water (HAZWASTE)
Case Number:	Not reported

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HCHEM-0243047
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2020-08-11T01:13:28.000
Chemical Name:	Gasoline
Common Name:	Underground Tank 120106 T004
Case Number:	86290-81-5

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HCHEM-0243048
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2020-08-11T01:13:28.000
Chemical Name:	Gasoline
Common Name:	Underground Tank 120106 T005
Case Number:	86290-81-5

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HCHEM-0165274
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-03-07T00:34:44.000
Chemical Name:	Gasoline
Common Name:	Underground Tank 120106 T004
Case Number:	86290-81-5

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0140521
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-03-07T00:34:45.000
Chemical Name:	Gasoline Contaminated Liquids
Common Name:	Sump Water, Spill Bucket Water, SB989 Testing Water (HAZWASTE)
Case Number:	Not reported

Record ID:	DEH2012-HUPFP-215933
Permit Status:	Permit Renewed

ARCO MINI MARKET (Continued) **S100731291**

Active Permit: Y
Child Record Id: DEH2018-HWAST-0140522
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-03-07T00:34:45.000
Chemical Name: Used Spill Kit and Used Fuel Filters
Common Name: Fuel Contaminated Waste Absorbent & Used Fuel Filters (HAZWASTE)
Case Number: Not reported

Record ID: DEH2012-HUPFP-215933
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0243049
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-08-11T01:13:28.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Name: ARCO FACILITY NO. 1914
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 215933
Business Type: 6HK28
EPA Id Number: Not reported
APN: 571-030-09-00
Last HMMD Inspection: 01/09/2012
Facility Telephone: 619-425-5356
Permit Status: TEMP
Permit Expiration: 01/31/2013
Date Last Updated: 11/02/2012
Facility Owner: GS & SS PETROLEUM, INC
Facility Mailing Address: 720 H ST
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910
UST Owner: GS & SS PETROLEUM, INC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 215933
Update Date: 11/02/2012
Case Number: 74-98-6
Name: PROPANE
Other Information: LPG
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CRYOGENIC

Permit Number: 215933
Update Date: 11/02/2012

ARCO MINI MARKET (Continued) **S100731291**

Case Number: Not reported
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 120106 T005
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 215933
Update Date: 11/02/2012
Case Number: Not reported
Name: SUPER UNLEADED
Other Information: UNDERGROUND TANK 120106 T004
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 215933
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: FUEL/H20
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 215933
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED GASOLINE FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

UST:
UST Name: UNDERGROUND TANK 120106 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: SINGLE WALL
Additional Id: NT2259 SUPER UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 20
UST Monitor Method: DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name: UNDERGROUND TANK 120106 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: SINGLE WALL
Additional Id: NT2259 PLUS UNLEADED

ARCO MINI MARKET (Continued) **S100731291**

Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 120106 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	SINGLE WALL
Additional Id:	NT2259 REGULAR UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name:	UNDERGROUND TANK 120106 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4294/RT4116/RT5718
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 120106 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4116/RT5718
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00

ARCO MINI MARKET (Continued) **S100731291**

Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	ARCO FACILITY NO. 1914
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	120106
Business Type:	6HK28
EPA Id Number:	CAL000225443
APN:	571-030-09-00
Last HMMD Inspection:	01/12/2011
Facility Telephone:	619-425-5356
Permit Status:	SUSP
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	BP WEST COAST PRODUCTS LLC
Facility Mailing Address:	PO BOX 6038
Facility Mailing City:	ARTESIA
Facility Mailing State:	CA
Facility Mailing Zip:	90702-6038
UST Owner:	BP WEST COAST PRODUCTS LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	120106
Update Date:	11/02/2012
Case Number:	74-98-6
Name:	PROPANE
Other Information:	LPG
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	CRYOGENIC

Permit Number:	120106
Update Date:	11/02/2012
Case Number:	Not reported
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 120106 T005
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	120106
Update Date:	11/02/2012
Case Number:	Not reported
Name:	SUPER UNLEADED
Other Information:	UNDERGROUND TANK 120106 T004
Material Waste:	Material
Hazardous Categories 1:	FIRE

ARCO MINI MARKET (Continued) **S100731291**

Hazardous Categories 2: Not reported

Permit Number: 120106
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: FUEL/H20
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120106
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED GASOLINE FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 120106
Update Date: 11/02/2012
Inspection Date: 01/31/2003
Violation Code: 6HV3113
Violation: 2NDRY CONT TEST NOT SENT TO CUPA
Violation Citation: Secondary Containment testing not submitted to CUPA within 30 days. 2637(a)(4)
Activity: SUSP

UST:
UST Name: UNDERGROUND TANK 120106 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 120106
Tank Type: SINGLE WALL
Additional Id: NT2259 SUPER UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 20
UST Monitor Method: DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name: UNDERGROUND TANK 120106 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 120106
Tank Type: SINGLE WALL
Additional Id: NT2259 PLUS UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED

ARCO MINI MARKET (Continued) **S100731291**

Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 120106 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	SINGLE WALL
Additional Id:	NT2259 REGULAR UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL
UST Name:	UNDERGROUND TANK 120106 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4294/RT4116
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 120106 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	120106
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4116
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A

ARCO MINI MARKET (Continued) **S100731291**

UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name: ARCO FACILITY NO. 1914
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 215933
Business Type: 6HK28
EPA Id Number: Not reported
APN: 571-030-09-00
Last HMMD Inspection: 01/09/2012
Facility Telephone: 619-425-5356
Permit Status: TEMP
Permit Expiration: 01/31/2013
Date Last Updated: 11/02/2012
Facility Owner: GS & SS PETROLEUM, INC
Facility Mailing Address: 720 H ST
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910
UST Owner: GS & SS PETROLEUM, INC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 215933
Update Date: 11/02/2012
Case Number: 74-98-6
Name: PROPANE
Other Information: LPG
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CRYOGENIC

Permit Number: 215933
Update Date: 11/02/2012
Case Number: Not reported
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 120106 T005
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 215933
Update Date: 11/02/2012
Case Number: Not reported
Name: SUPER UNLEADED
Other Information: UNDERGROUND TANK 120106 T004
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 215933

ARCO MINI MARKET (Continued) **S100731291**

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: FUEL/H20
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 215933
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED GASOLINE FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

UST:
UST Name: UNDERGROUND TANK 120106 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: SINGLE WALL
Additional Id: NT2259 SUPER UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 20
UST Monitor Method: DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name: UNDERGROUND TANK 120106 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: SINGLE WALL
Additional Id: NT2259 PLUS UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 120106 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: SINGLE WALL
Additional Id: NT2259 REGULAR UNLEADED

ARCO MINI MARKET (Continued) **S100731291**

Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name:	UNDERGROUND TANK 120106 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4294/RT4116/RT5718
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 120106 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4116/RT5718
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	ARCO FACILITY NO. 1914
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	215933
Business Type:	6HK28
EPA Id Number:	Not reported
APN:	571-030-09-00
Last HMMD Inspection:	01/09/2012
Facility Telephone:	619-425-5356
Permit Status:	TEMP

ARCO MINI MARKET (Continued) **S100731291**

Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	GS & SS PETROLEUM, INC
Facility Mailing Address:	720 H ST
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910
UST Owner:	GS & SS PETROLEUM, INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	74-98-6
Name:	PROPANE
Other Information:	LPG
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	CRYOGENIC

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	Not reported
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 120106 T005
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	Not reported
Name:	SUPER UNLEADED
Other Information:	UNDERGROUND TANK 120106 T004
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	FUEL/H20
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information:	USED GASOLINE FILTERS
Material Waste:	Waste

ARCO MINI MARKET (Continued) **S100731291**

Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

UST:

UST Name: UNDERGROUND TANK 120106 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: SINGLE WALL
Additional Id: NT2259 SUPER UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 20
UST Monitor Method: DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name: UNDERGROUND TANK 120106 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: SINGLE WALL
Additional Id: NT2259 PLUS UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 120106 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: SINGLE WALL
Additional Id: NT2259 REGULAR UNLEADED
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1982-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 20
UST Monitor Method: DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL

UST Name: UNDERGROUND TANK 120106 T004
Last Update: 2012-11-02 14:17:38

ARCO MINI MARKET (Continued) **S100731291**

Permit Number:	215933
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4294/RT4116/RT5718
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 120106 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4116/RT5718
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	ARCO FACILITY NO. 1914
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	215933
Business Type:	6HK28
EPA Id Number:	Not reported
APN:	571-030-09-00
Last HMMD Inspection:	01/09/2012
Facility Telephone:	619-425-5356
Permit Status:	TEMP
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	GS & SS PETROLEUM, INC
Facility Mailing Address:	720 H ST
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910
UST Owner:	GS & SS PETROLEUM, INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

ARCO MINI MARKET (Continued) **S100731291**

Inventory Active Permits (not SQG Medical):

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	74-98-6
Name:	PROPANE
Other Information:	LPG
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	CRYOGENIC

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	Not reported
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 120106 T005
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	Not reported
Name:	SUPER UNLEADED
Other Information:	UNDERGROUND TANK 120106 T004
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	FUEL/H20
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	215933
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information:	USED GASOLINE FILTERS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

UST:

UST Name:	UNDERGROUND TANK 120106 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	SINGLE WALL
Additional Id:	NT2259 SUPER UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED

ARCO MINI MARKET (Continued) **S100731291**

Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL
UST Name:	UNDERGROUND TANK 120106 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	SINGLE WALL
Additional Id:	NT2259 PLUS UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 120106 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	SINGLE WALL
Additional Id:	NT2259 REGULAR UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL
UST Name:	UNDERGROUND TANK 120106 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	215933
Tank Type:	DOUBLE WALL
Additional Id:	NT2259/RT3228/RT4294/RT4116/RT5718
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2001-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF &

ARCO MINI MARKET (Continued) **S100731291**

FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 120106 T005
Last Update: 2012-11-02 14:17:38
Permit Number: 215933
Tank Type: DOUBLE WALL
Additional Id: NT2259/RT3228/RT4116/RT5718
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2001-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

CERS HAZ WASTE:
Name: "H" STREET ARCO
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 61
CERS ID: 10358482
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: "H" STREET ARCO
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 61
CERS ID: 10358482
CERS Description: Underground Storage Tank

HIST CORTESE:
edr_fname: ARCO MINI MARKET
edr_fadd1: 720 H
City,State,Zip: CHULA VISTA, CA
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT3103

CERS:
Name: "H" STREET ARCO
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 61
CERS ID: 10358482
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 61
Site Name: "H" STREET ARCO

ARCO MINI MARKET (Continued) **S100731291**

Violation Date:	01-16-2019
Citation:	23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description:	Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1,- 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October- 1,- 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.
Violation Notes:	Returned to compliance on 01/30/2019. Inspection Sequence ID:6056664;Tank ID:24787,24788;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	61
Site Name:	"H" STREET ARCO
Violation Date:	01-04-2018
Citation:	23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description:	Failure to comply with one or more of the following: Failure to install or maintain a liquid-tight spill bucket. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container. Be resistant to galvanic corrosion.

ARCO MINI MARKET (Continued) **S100731291**

Violation Notes: Returned to compliance on 01/04/2018.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 61
Site Name: "H" STREET ARCO
Violation Date: 01-02-2014
Citation: 23 CCR 16 2636(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)
Violation Description: Failure to continuously monitor the interstitial space of the tank, piping and/or sumps sump such that the leak detection activates an audible/visual alarm when a leak is detected.
Violation Notes: Returned to compliance on 01/02/2014.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-02-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:4963339
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-02-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:4963339
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-04-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5831646
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-04-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5831646
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-04-2018

ARCO MINI MARKET (Continued) **S100731291**

Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5831646
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-05-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5563725
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-05-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5563725
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-05-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5563725
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-11-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5200129
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-15-2020
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6388983
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-16-2015
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5195416

ARCO MINI MARKET (Continued) **S100731291**

Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-16-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5195416
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-16-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5195416
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-16-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6056664
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-16-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6056664
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-16-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6056664
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Coordinates:
Site ID: 61
Facility Name: "H" STREET ARCO
Env Int Type Code: HWG
Program ID: 10358482
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.629310

ARCO MINI MARKET (Continued) **S100731291**

Longitude: -117.094260

Affiliation:

Affiliation Type Desc:	Document Preparer
Entity Name:	Gloria Jimenez
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	UST Permit Applicant
Entity Name:	Rebecca Watkins
Entity Title:	CERSAdminister
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 302-6779

Affiliation Type Desc:	UST Property Owner Name
Entity Name:	GS & SS Petroleum, Inc.
Entity Title:	Not reported
Affiliation Address:	720 H St.
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 425-5336

Affiliation Type Desc:	Parent Corporation
Entity Name:	"H" STREET ARCO
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	UST Tank Operator
Entity Name:	GS & SS Petroleum, Inc.
Entity Title:	Not reported
Affiliation Address:	720 H St.
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 425-5336

Affiliation Type Desc:	UST Tank Owner
Entity Name:	GS & SS PETROLEUM, INC
Entity Title:	Not reported
Affiliation Address:	720 H ST

ARCO MINI MARKET (Continued) **S100731291**

Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 425-5356
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880
Affiliation Type Desc:	Legal Owner
Entity Name:	GS & SS PETROLEUM, INC
Entity Title:	Not reported
Affiliation Address:	720 H St
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 425-5356
Affiliation Type Desc:	Operator
Entity Name:	GS & SS PETROLEUM, INC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 425-5356
Affiliation Type Desc:	Property Owner
Entity Name:	GS & SS Petroleum, Inc
Entity Title:	Not reported
Affiliation Address:	720 H St
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 425-5356
Affiliation Type Desc:	Environmental Contact
Entity Name:	Rely Environmental
Entity Title:	Not reported
Affiliation Address:	3941 Mason St. Suite 4
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92110
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address

ARCO MINI MARKET (Continued) **S100731291**

Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	720 H ST
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	Gloria Jimenez
Entity Title:	CERS Account Admin
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

H33 **DONN SWARTZ** **SWEEPS UST** **S106925476**
East **720 H ST 1914** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.203 mi.
1074 ft. **Site 7 of 13 in cluster H**

Relative: **Higher**

Actual: **28 ft.**

SWEEPS UST:

Name:	DONN SWARTZ
Address:	720 H ST 1914
City:	CHULA VISTA
Status:	Active
Comp Number:	20106
Number:	9
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-020106-000001
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	3
Name:	DONN SWARTZ
Address:	720 H ST 1914
City:	CHULA VISTA
Status:	Active
Comp Number:	20106
Number:	9
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported

DONN SWARTZ (Continued) **S106925476**

SWRCB Tank Id:	37-000-020106-000002
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported
Name:	DONN SWARTZ
Address:	720 H ST 1914
City:	CHULA VISTA
Status:	Active
Comp Number:	20106
Number:	9
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-020106-000003
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	LEADED
Number Of Tanks:	Not reported

H34 **TESORO 97610-1914** **RCRA NonGen / NLR** **1024851896**
East **720 H ST** **CAL000410683**
1/8-1/4 **CHULA VISTA, CA 91910**
0.203 mi.
1074 ft. **Site 8 of 13 in cluster H**

Relative: **Higher**

Actual: **28 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2015-09-25 00:00:00.0
Handler Name:	TESORO 97610-1914	
Handler Address:		720 H ST
Handler City,State,Zip:		CHULA VISTA, CA 91910
EPA ID:		CAL000410683
Contact Name:		JO-ANNE ALVAREZ
Contact Address:		400 OCEANGATE BLVD, SUITE 600
Contact City,State,Zip:		LONG BEACH, CA 90802
Contact Telephone:		562-495-6837
Contact Fax:		Not reported
Contact Email:		JO-ANNE.J.ALVAREZ@ANDEAVOR.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		19100 RIDGEWOOD PKWY

TESORO 97610-1914 (Continued) **1024851896**

Mailing City,State,Zip:	SAN ANTONIO, TX 78259
Owner Name:	TESORO ENVIRONMENTAL RESOURCES CO
Owner Type:	Other
Operator Name:	JO-ANNE ALVAREZ
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-06 17:06:48.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

TESORO 97610-1914 (Continued) **1024851896**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: JO-ANNE ALVAREZ
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 400 OCEANGATE BLVD, SUITE 600
Owner/Operator City,State,Zip: LONG BEACH, CA 90802
Owner/Operator Telephone: 562-495-6837
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: TESORO ENVIRONMENTAL RESOURCES CO
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 400 OCEANGATE BLVD, SUITE 600
Owner/Operator City,State,Zip: LONG BEACH, CA 90802-0000
Owner/Operator Telephone: 562-495-6837
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2015-09-25 00:00:00.0
Handler Name: TESORO 97610-1914
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44719
NAICS Description: OTHER GASOLINE STATIONS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

H35 **RALPH E EMARINE DBA AM/PM MIN** **HIST UST** **S118414375**
East **720 H STREET** **N/A**
1/8-1/4 **CHULA VISTA, CA 92010**
0.203 mi.
1074 ft. **Site 9 of 13 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

HIST UST:

Name:	RALPH E EMARINE DBA AM/PM MIN
Address:	720 H STREET
City,State,Zip:	CHULA VISTA, CA 92010
File Number:	0002F1C6
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002F1C6.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

H36 **RALPH E EMARINE** **HIST UST** **U001571044**
East **720 H ST** **N/A**
1/8-1/4 **CHULA VISTA, CA 92010**
0.203 mi.
1074 ft. **Site 10 of 13 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

HIST UST:

Name:	RALPH E EMARINE
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 92010
File Number:	0002ABC0
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002ABC0.pdf
Region:	STATE
Facility ID:	00000026658
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	0000000000
Owner Name:	ARCO PETROLEUM PRODUCTS CO.
Owner Address:	515 SOUTH FLOWER STREET
Owner City,St,Zip:	LOS ANGELES, CA 90071
Total Tanks:	0003
Tank Num:	001
Container Num:	0000000001
Year Installed:	1982

RALPH E EMARINE (Continued) **U001571044**

Tank Capacity:	00012000
Tank Used for:	PRODUCT
Type of Fuel:	06
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10
Tank Num:	002
Container Num:	0000000002
Year Installed:	1982
Tank Capacity:	00012000
Tank Used for:	PRODUCT
Type of Fuel:	06
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10
Tank Num:	003
Container Num:	0000000003
Year Installed:	1982
Tank Capacity:	00012000
Tank Used for:	PRODUCT
Type of Fuel:	06
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10

Click here for Geo Tracker PDF:

H37 **"H" STREET ARCO** **UST** **U004315825**
East **720 H ST** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.203 mi.
1074 ft. **Site 11 of 13 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

UST:

Name:	"H" STREET ARCO
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	37-000-215933
Permitting Agency:	San Diego County Department of Environmental Health
Latitude:	32.62931
Longitude:	-117.09426

H38 **GS & SS PETROLIUM INC** **RCRA NonGen / NLR** **1024806068**
East **720 H ST** **CAL000267011**
1/8-1/4 **CHULA VISTA, CA 91910**
0.203 mi.
1074 ft. **Site 12 of 13 in cluster H**

Relative: **Higher**
Actual: **28 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2003-02-27 00:00:00.0
Handler Name:	GS & SS PETROLIUM INC	
Handler Address:		720 H ST
Handler City,State,Zip:		CHULA VISTA, CA 91910
EPA ID:		CAL000267011
Contact Name:		SAM SALEM
Contact Address:		720 H ST
Contact City,State,Zip:		CHULA VISTA, CA 91910

GS & SS PETROLIUM INC (Continued) **1024806068**

Contact Telephone:	619-454-4488
Contact Fax:	000-000-0000
Contact Email:	INFO@RELYENVIRONMENTAL.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	720 H ST
Mailing City,State,Zip:	CHULA VISTA, CA 91910-0000
Owner Name:	GS & SS PETROLIUM INC
Owner Type:	Other
Operator Name:	SAM SALEM
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

GS & SS PETROLIUM INC (Continued) **1024806068**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 20:24:47.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SAM SALEM
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	720 H ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-454-4488
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GS & SS PETROLIUM INC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	720 H ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910-0000
Owner/Operator Telephone:	691-425-5356
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2003-02-27 00:00:00.0
Handler Name: GS & SS PETROLIUM INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

GS & SS PETROLIUM INC (Continued) **1024806068**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44719
NAICS Description: OTHER GASOLINE STATIONS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

H39 **ARCO AM/PM MINI MARKET #1914** **SAN DIEGO CO. SAM** **U003937905**
East **720 H ST** **UST** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **Cortese**
0.203 mi. **SAN DIEGO CO LOP**
1074 ft. **Site 13 of 13 in cluster H** **CERS**

Relative: Higher
Actual: 28 ft.

SAN DIEGO CO. SAM:
Name: ARCO AM/PM MINI MARKET #1914
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 919104004
Case Number: H20106-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Action (Clean-Up)
Date: 2/26/2004
Date Began: 7/25/1995

UST:
Name: ARCO AM/PM MINI MARKET #1914
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 91910
Facility ID: H20106
Permitting Agency: SAN DIEGO COUNTY
Latitude: 32.6305819
Longitude: -117.0928471

CORTESE:
Name: ARCO AM/PM MINI MARKET #1914
Address: 720 H ST
City,State,Zip: CHULA VISTA, CA 919104004
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607301869
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported

ARCO AM/PM MINI MARKET #1914 (Continued) **U003937905**

Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

SAN DIEGO CO LOP:

Name:	ARCO AM/PM MINI MARKET #1914
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1995-LSAM-H20106-001
Record Status:	Completed
Opened Date:	07/25/1995
Parcel Number:	571-030-09-00
Case Type:	LOP - Local Oversight Program
Historical Name:	ARCO 1914
SWRCB Global ID:	T0607301869
Funding:	S - LOP State Fund
Lead Agency:	RWQCB
Lead Agency Date:	07/01/2018
Census Tract:	126.00
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6293162
Longitude:	-117.0942588
X MapCoord:	6301727.884
Y MapCoord:	1809818.256

CERS:

Name:	ARCO AM/PM MINI MARKET #1914
Address:	720 H ST
City,State,Zip:	CHULA VISTA, CA 919104004
Site ID:	260825
CERS ID:	T0607301869
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	LALITHA THOTAKURA - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213002

I40 **THE MARINE GROUP, LLC** **CPS-SLIC** **S118504899**
West **997 G STREET** **CERS** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.205 mi.
1080 ft. **Site 1 of 10 in cluster I**

Relative:
Lower

Actual:
9 ft.

CPS-SLIC:

Name:	THE MARINE GROUP, LLC
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Open - Inactive**
Status Date:	05/05/2016
Global Id:	T10000008876
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.63091
Longitude:	-117.10629
Case Type:	Cleanup Program Site
Case Worker:	UNA
Local Agency:	Not reported
RB Case Number:	3100109
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Contaminated Surface / Structure, Sediments, Soil, Surface water, Under Investigation
Potential Contaminants of Concern:	Polychlorinated biphenyls (PCBs), Other Metal, Diesel, Polynuclear aromatic hydrocarbons (PAHs)
Site History:	Facility and offshore sediments need to be assessed.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	THE MARINE GROUP, LLC
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	369324
CERS ID:	T10000008876
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Unassigned - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195161990

I41 **MARINE GROUP BOAT WORKS, LLC** **AST** **S103993648**
West **997 G ST** **San Diego Co. HMMD** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **CERS HAZ WASTE**
0.205 mi. **CERS TANKS**
1080 ft. **Site 2 of 10 in cluster I** **ENF**
NPDES
Relative: **CIWQS**
Lower **CERS**

Actual:
9 ft.

AST:

Name:	MARINE GROUP BOAT WORKS, LLC
Address:	997 G ST
City/Zip:	CHULA VISTA,91910
Certified Unified Program Agencies:	Not reported
Owner:	Marine Group Boat Works LLC
Total Gallons:	Not reported
CERSID:	10357831
Facility ID:	37-000-109768
Business Name:	MARINE GROUP BOAT WORKS, LLC
Phone:	619-427-6767
Fax:	Not reported
Mailing Address:	997 G street
Mailing Address City:	Chule Vista
Mailing Address State:	CA
Mailing Address Zip Code:	91910
Operator Name:	Marine Group Boat Works LLC
Operator Phone:	619-427-6767
Owner Phone:	619-427-6767
Owner Mail Address:	997 G Street
Owner State:	CA
Owner Zip Code:	91910
Owner Country:	United States
Property Owner Name:	Marine Group Boat Works LLC
Property Owner Phone:	Not reported
Property Owner Mailing Address:	997 G ST
Property Owner City:	CHULA VISTA
Property Owner Stat :	CA
Property Owner Zip Code:	91910
Property Owner Country:	United States
EPAID:	CAL000017529

HMMD SAN DIEGO:

Name:	MARINE GROUP BOAT WORKS, LLC
Address:	997 G ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	109768
Business Type:	6HK33
EPA Id Number:	CAL000017529
APN:	760-048-17-00
Last HMMD Inspection:	07/25/2011
Facility Telephone:	619-427-6767
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	MARINE GROUP BOAT WORKS LLC
Facility Mailing Address:	997 G ST
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910-

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 109768
Update Date: 11/02/2012
Case Number: 74-86-2
Name: ACETYLENE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: 7440-34-1
Name: ARGON
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: CO2/HELIUM/ARGON
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 109768
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: OXYGEN
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: PAINTS

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: 74-98-6
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: OIL/H20/DIESEL-BILGE H20
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: SPRAY BOOTH FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: USED SANDBLAST WASTE/COPPER SLAG
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 213 HYDROCARBON SOLVENTS
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 213 HYDROCARBON SOLVENTS
Other Information: USED GASOLINE/DIESEL
Material Waste: Waste
Hazardous Categories 1: Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: WASTE OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information: SUMP SLUDGE + RUN OFF FROM TANK YARD
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 223 UNSPEC OIL CONTAINING WASTE
Other Information: MXD OIL WST ABSORBNT/RAGS/DEBRIS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 223 UNSPEC OIL CONTAINING WASTE
Other Information: OILY WATER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: TOLUENE AND XYLENE/PAINT WASTE OR BRAKE FLUID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: CORES EXCHANGED F/CREDIT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 461 PAINT SLUDGE
Other Information:	PAINT SLUDGE/SOLIDS(FILTERS)
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	109768
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 888 USED OIL FILTERS
Other Information:	DRAINED USED OIL FILTERS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Violations Active Permits:

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	09/07/2005
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	09/07/2005
Violation Code:	6HV0205
Violation:	WASTE CONTAINER: POOR CONDITION
Violation Citation:	Failed to transfer hazardous waste from a container that leaked or was in poor condition to another container in good condition. CCR 66265.171
Activity:	ACTIVE

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	09/07/2005
Violation Code:	6HV0207
Violation:	FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Violation Citation:	Facility not maintained &/operated to minimize possibility of fire, explosion or release. CCR 66265.31
Activity:	ACTIVE

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector’s review. 25505(e)
Activity:	ACTIVE

Permit Number:	109768
Update Date:	11/02/2012

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Inspection Date:	07/25/2011
Violation Code:	6HV0215
Violation:	OIL FILTERS IMPROPERLY MANAGED
Violation Citation:	Used oil filters not properly drained, stored, or labeled prior to transport for the purpose of metal reclamation. CCR 66266.130
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0216
Violation:	HAZMATS WITHOUT PROPER LABELS
Violation Citation:	Hazardous materials have not been adequately labeled within 10 days & are now declared hazardous waste. HSC 25124(b)(3)(A) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0225
Violation:	ACCUMULATED HW>180 OR >270 DAYS
Violation Citation:	Accumulated waste too long (>180 or 270 days). 66262.34(d), CFR 262.34(e)&(f), &/or 25201(a) [>90 days for AHW waste]
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0228
Violation:	CONTAINER NOT KEPT CLOSED
Violation Citation:	Failed to keep container closed. CFR 265.173
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0229
Violation:	HW CONTAINERS NOT INSPECTED WEEKLY
Violation Citation:	Failed to conduct weekly inspections. CFR 265.174
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0407
Violation:	EMPLOYEE TRAINING NOT ADEQUATE
Violation Citation:	Employee training program for small quantity generator of hazardous waste is inadequate. CFR 262.34(d)(5)(iii)

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0304
Violation:	WASTE DETERMINATION NOT MADE
Violation Citation:	Generator of a waste has not determined if that waste is a hazardous waste as defined by law. CCR 66262.11 & 66260.200(c)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV5104
Violation:	SPCC PLAN NOT AVAILABLE ONSITE
Violation Citation:	Spill Prevention Control and Countermeasures Plan was not available onsite. 25270.4.5(a), 25270.5 & 25270.12(a) [ref. CFR 112.3(e)]
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV1018
Violation:	INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation:	Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0217
Violation:	HAZMAT CON. NOT REPACKAGED WI 96 HRS.
Violation Citation:	Failed to repackage damaged/deteriorated hazardous material container within 96 hours. 25124(b)(3)(B) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0218
Violation:	FILTERS:FUEL/OIL NOT LABELED OR CLOSED
Violation Citation:	Failed to label &/or close drained used oil filters &/or used fuel filters. 25250.22 and 66266.130(c)(3)
Activity:	ACTIVE

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0226
Violation:	HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation:	Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity:	ACTIVE

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0228
Violation:	CONTAINER NOT KEPT CLOSED
Violation Citation:	Failed to keep container closed. CFR 265.173
Activity:	ACTIVE

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0229
Violation:	HW CONTAINERS NOT INSPECTED WEEKLY
Violation Citation:	Failed to conduct weekly inspections. CFR 265.174
Activity:	ACTIVE

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0407
Violation:	EMPLOYEE TRAINING NOT ADEQUATE
Violation Citation:	Employee training program for small quantity generator of hazardous waste is inadequate. CFR 262.34(d)(5)(iii)
Activity:	ACTIVE

Name:	MARINE GROUP BOAT WORKS, LLC
Address:	997 G ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	109768
Business Type:	6HK33
EPA Id Number:	CAL000017529
APN:	760-048-17-00
Last HMMD Inspection:	07/25/2011
Facility Telephone:	619-427-6767
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	MARINE GROUP BOAT WORKS LLC
Facility Mailing Address:	997 G ST

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910-
UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Y
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 109768
Update Date: 11/02/2012
Case Number: 74-86-2
Name: ACETYLENE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: 7440-34-1
Name: ARGON
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: CO2/HELIUM/ARGON
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 109768
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: OXYGEN
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 109768

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Update Date:	11/02/2012
Case Number:	Not reported
Name:	PAINTS
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	CHRONIC
Hazardous Categories 2:	Not reported

Permit Number:	109768
Update Date:	11/02/2012
Case Number:	74-98-6
Name:	PROPANE
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	109768
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	OIL/H20/DIESEL-BILGE H20
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	109768
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information:	SPRAY BOOTH FILTERS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	109768
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information:	USED SANDBLAST WASTE/COPPER SLAG
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	109768
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 213 HYDROCARBON SOLVENTS
Other Information:	PARTS WASHER
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	109768
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 213 HYDROCARBON SOLVENTS

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Other Information: USED GASOLINE/DIESEL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: WASTE OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information: SUMP SLUDGE + RUN OFF FROM TANK YARD
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 223 UNSPEC OIL CONTAINING WASTE
Other Information: MXD OIL WST ABSORBNT/RAGS/DEBRIS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 223 UNSPEC OIL CONTAINING WASTE
Other Information: OILY WATER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: TOLUENE AND XYLENE/PAINT WASTE OR BRAKE FLUID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: CORES EXCHANGED F/CREDIT
Material Waste: Waste
Hazardous Categories 1: Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 461 PAINT SLUDGE
Other Information: PAINT SLUDGE/SOLIDS(FILTERS)
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 109768
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: DRAINED USED OIL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 109768
Update Date: 11/02/2012
Inspection Date: 09/07/2005
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

Permit Number: 109768
Update Date: 11/02/2012
Inspection Date: 09/07/2005
Violation Code: 6HV0205
Violation: WASTE CONTAINER: POOR CONDITION
Violation Citation: Failed to transfer hazardous waste from a container that leaked or was in poor condition to another container in good condition. CCR 66265.171
Activity: ACTIVE

Permit Number: 109768
Update Date: 11/02/2012
Inspection Date: 09/07/2005
Violation Code: 6HV0207
Violation: FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Violation Citation: Facility not maintained &/operated to minimize possibility of fire, explosion or release. CCR 66265.31
Activity: ACTIVE

Permit Number: 109768
Update Date: 11/02/2012
Inspection Date: 07/25/2011
Violation Code: 6HV1013
Violation: HMBP NOT AVAILABLE FOR REVIEW
Violation Citation: Copy of HMBP not onsite for inspector’s review. 25505(e)
Activity: ACTIVE

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0215
Violation:	OIL FILTERS IMPROPERLY MANAGED
Violation Citation:	Used oil filters not properly drained, stored, or labeled prior to transport for the purpose of metal reclamation. CCR 66266.130
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0216
Violation:	HAZMATS WITHOUT PROPER LABELS
Violation Citation:	Hazardous materials have not been adequately labeled within 10 days & are now declared hazardous waste. HSC 25124(b)(3)(A) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0225
Violation:	ACCUMULATED HW>180 OR >270 DAYS
Violation Citation:	Accumulated waste too long (>180 or 270 days). 66262.34(d), CFR 262.34(e)&(f), &/or 25201(a) [>90 days for AHW waste]
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0228
Violation:	CONTAINER NOT KEPT CLOSED
Violation Citation:	Failed to keep container closed. CFR 265.173
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0229
Violation:	HW CONTAINERS NOT INSPECTED WEEKLY
Violation Citation:	Failed to conduct weekly inspections. CFR 265.174
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0407
Violation:	EMPLOYEE TRAINING NOT ADEQUATE

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Violation Citation:	Employee training program for small quantity generator of hazardous waste is inadequate. CFR 262.34(d)(5)(iii)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV0304
Violation:	WASTE DETERMINATION NOT MADE
Violation Citation:	Generator of a waste has not determined if that waste is a hazardous waste as defined by law. CCR 66262.11 & 66260.200(c)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/25/2011
Violation Code:	6HV5104
Violation:	SPCC PLAN NOT AVAILABLE ONSITE
Violation Citation:	Spill Prevention Control and Countermeasures Plan was not available onsite. 25270.4.5(a), 25270.5 & 25270.12(a) [ref. CFR 112.3(e)]
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV1018
Violation:	INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation:	Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0217
Violation:	HAZMAT CON. NOT REPACKAGED WI 96 HRS.
Violation Citation:	Failed to repackage damaged/deteriorated hazardous material container within 96 hours. 25124(b)(3)(B) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0218
Violation:	FILTERS:FUEL/OIL NOT LABELED OR CLOSED
Violation Citation:	Failed to label &/or close drained used oil filters &/or used fuel filters. 25250.22 and 66266.130(c)(3)

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0226
Violation:	HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation:	Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0228
Violation:	CONTAINER NOT KEPT CLOSED
Violation Citation:	Failed to keep container closed. CFR 265.173
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0229
Violation:	HW CONTAINERS NOT INSPECTED WEEKLY
Violation Citation:	Failed to conduct weekly inspections. CFR 265.174
Activity:	ACTIVE
Permit Number:	109768
Update Date:	11/02/2012
Inspection Date:	07/27/2007
Violation Code:	6HV0407
Violation:	EMPLOYEE TRAINING NOT ADEQUATE
Violation Citation:	Employee training program for small quantity generator of hazardous waste is inadequate. CFR 262.34(d)(5)(iii)
Activity:	ACTIVE

Name:	MARINE GROUP BOAT WORKS, LLC
Address:	997 G ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAR000298620
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-427-6767
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	02/12/2020

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Facility Owner:	Not reported
Facility Mailing Address:	997 G Street, Chula Vista, CA 91910
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	N
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-109768
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4687493
Return To Compliance Date:	2015-04-06T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-02-12T00:00:00.000
Inspection Date:	2015-03-25T00:00:00.000
Violation Code:	3030014 Failure to accumulate hazardous waste in a container that is in good condition.; 22 CCR 15 66265.171.

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-109768
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4687493
Return To Compliance Date:	2015-03-25T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-02-12T00:00:00.000
Inspection Date:	2015-03-25T00:00:00.000
Violation Code:	3050002 Failure to properly dispose of hazardous waste at an authorized location.; HSC 6.5 25189.5(a).

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-109768
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4687493
Return To Compliance Date:	2015-04-06T00:00:00.000
Nov:	No
Violation Classification:	Minor

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2020-02-12T00:00:00.000
Inspection Date: 2015-03-25T00:00:00.000
Violation Code: 3130003 RCRA: Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.; 22 CCR 12 66262.34(f).

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-109768
Program Element: Hazardous Waste Generator
Inspection Type: Routine
Inspection Number: 4687493
Return To Compliance Date: 2015-04-06T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2020-02-12T00:00:00.000
Inspection Date: 2015-03-25T00:00:00.000
Violation Code: 3130013 RCRA: Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to the air, soil, or surface water which could threaten human health or the environment. 22 CCR 15 66265.31.

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-109768
Program Element: Aboveground Petroleum Storage Act
Inspection Type: Routine
Inspection Number: 6191626
Return To Compliance Date: 2019-07-27T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2020-02-12T00:00:00.000
Inspection Date: 2019-07-11T00:00:00.000
Violation Code: 4010001 Failed to prepare a Spill Prevention, Control, and Countermeasures (SPCC) Plan. HSC 25270.4.5(a), 40 CFR 112.3, 112.6

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-109768
Program Element: Hazardous Materials Release Response Plans
Inspection Type: Routine
Inspection Number: 4687493
Return To Compliance Date: 2015-06-01T00:00:00.000
Nov: No
Violation Classification: Minor

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2020-02-12T00:00:00.000
Inspection Date: 2015-03-25T00:00:00.000
Violation Code: 1010003 Owner/Operator failed to complete and/or submit the Business Activities Page and/or Business Owner Operator Identification Page; 19 CCR 4 2729.2(a)(1).

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-109768
Program Element: Hazardous Materials Release Response Plans
Inspection Type: Routine
Inspection Number: 4687493
Return To Compliance Date: 2015-06-01T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2020-02-12T00:00:00.000
Inspection Date: 2015-03-25T00:00:00.000
Violation Code: 1010001 Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet; HSC 6.95 25507(a).

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-109768
Program Element: Hazardous Waste Generator
Inspection Type: Routine
Inspection Number: 4687493
Return To Compliance Date: 2015-04-06T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2020-02-12T00:00:00.000
Inspection Date: 2015-03-25T00:00:00.000
Violation Code: 3130007 RCRA: Failure to properly close hazardous waste containers when not in active use. 22 CCR 15 66265.173.

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-109768
Program Element: Hazardous Waste Generator
Inspection Type: Routine
Inspection Number: 6191626
Return To Compliance Date: 2019-08-15T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2020-02-12T00:00:00.000

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Inspection Date:	2019-07-11T00:00:00.000
Violation Code:	3010004 Failed to obtain a California ID Number from DTSC or federal ID Number from USEPA prior to accumulating 5,000 kgs or more of Universal Waste. 22 CCR 66273.32(a-b)
Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-109768
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4687493
Return To Compliance Date:	2015-03-25T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-02-12T00:00:00.000
Inspection Date:	2015-03-25T00:00:00.000
Violation Code:	3130001 RCRA: Failure to determine if the waste generated is a hazardous waste. 22 CCR 12 66262.11.
Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-109768
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	4687493
Return To Compliance Date:	2015-04-06T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-02-12T00:00:00.000
Inspection Date:	2015-03-25T00:00:00.000
Violation Code:	3130008 RCRA: Failure to inspect hazardous waste storage areas at least weekly. 22 CCR 15 66265.174.

Waste and Materials:

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0138415
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-12-02T00:34:40.000
Chemical Name:	Waste Coolant/Antifreeze
Common Name:	Waste Coolant/Antifreeze
Case Number:	Not reported
Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0138416
Trade Secret:	N
Hazardous Material Type:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Last Updated: 2017-12-02T00:34:40.000
Chemical Name: Waste Aerosols
Common Name: Waste Aerosols
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227843
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Carbon Dioxide
Common Name: Carbon Dioxide
Case Number: 124-38-9

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227844
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197660
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Oily Rags/Oily Sludge/Oily Debris
Common Name: Oily Rags/Oily Sludge/Oily Debris
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197661
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Waste Coolant/Antifreeze
Common Name: Waste Coolant/Antifreeze
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227842
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Diesel Fuel

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Common Name: Diesel Fuel
Case Number: 68334-30-5

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227845
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Argon
Common Name: Argon
Case Number: 7440-37-1

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227846
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227847
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Helium
Common Name: Helium
Case Number: 7440-59-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227848
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227849
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Lubricating Oils
Common Name: Lubricating Oils
Case Number: 72623-83-7

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227850
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Flammable Paints
Common Name: Flammable Paints
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197656
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Paint/Solvent Waste
Common Name: Paint/Solvent Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197657
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Waste 221. Waste oil
Common Name: Waste oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197658
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Paint Waste
Common Name: Paint Waste/Paint Cans
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197659
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Diesel Waste
Common Name: Diesel Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Active Permit: Y
Child Record Id: DEH2019-HWAST-0197662
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-02-12T02:32:14.000
Chemical Name: Waste Aerosols
Common Name: Waste Aerosols
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162758
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Diesel Fuel
Common Name: Diesel Fuel
Case Number: 68334-30-5

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162759
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Carbon Dioxide
Common Name: Carbon Dioxide
Case Number: 124-38-9

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162760
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162761
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Argon
Common Name: Argon
Case Number: 7440-37-1

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162762

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162763
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Helium
Common Name: Helium
Case Number: 7440-59-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162764
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162765
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Lubricating Oils
Common Name: Lubricating Oils
Case Number: 72623-83-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0162766
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-12-02T00:34:39.000
Chemical Name: Flammable Paints
Common Name: Flammable Paints
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138409
Trade Secret: N
Hazardous Material Type: Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Last Updated: 2017-12-02T00:34:40.000
Chemical Name: Paint/Solvent Waste
Common Name: Paint/Solvent Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138410
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-12-02T00:34:40.000
Chemical Name: Waste 221. Waste oil
Common Name: Waste oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138411
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-12-02T00:34:40.000
Chemical Name: Paint Waste
Common Name: Paint Waste/Paint Cans
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138412
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-12-02T00:34:40.000
Chemical Name: Bilge Water/Oily Water with Diesel
Common Name: Bilge Water/Oily Water with Diesel
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138413
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-12-02T00:34:40.000
Chemical Name: Diesel Waste
Common Name: Diesel Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138414
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-12-02T00:34:40.000
Chemical Name: Oily Rags/Oily Sludge/Oily Debris

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Common Name: Oily Rags/Oily Sludge/Oily Debris
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189959
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Diesel Fuel
Common Name: Diesel Fuel
Case Number: 68334-30-5

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189960
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Carbon Dioxide
Common Name: Carbon Dioxide
Case Number: 124-38-9

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189961
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189962
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Argon
Common Name: Argon
Case Number: 7440-37-1

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189963
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189964
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Helium
Common Name: Helium
Case Number: 7440-59-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189965
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189966
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Lubricating Oils
Common Name: Lubricating Oils
Case Number: 72623-83-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189967
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Flammable Paints
Common Name: Flammable Paints
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0164454
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Paint/Solvent Waste
Common Name: Paint/Solvent Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0164455
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-02-13T02:32:16.000
Chemical Name:	Waste 221. Waste oil
Common Name:	Waste oil
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0164456
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-02-13T02:32:16.000
Chemical Name:	Paint Waste
Common Name:	Paint Waste/Paint Cans
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0164457
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-02-13T02:32:16.000
Chemical Name:	Diesel Waste
Common Name:	Diesel Waste
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0164458
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-02-13T02:32:16.000
Chemical Name:	Oily Rags/Oily Sludge/Oily Debris
Common Name:	Oily Rags/Oily Sludge/Oily Debris
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0164459
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-02-13T02:32:16.000
Chemical Name:	Waste Coolant/Antifreeze
Common Name:	Waste Coolant/Antifreeze
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0164460

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-02-13T02:32:16.000
Chemical Name: Waste Aerosols
Common Name: Waste Aerosols
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146358
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Diesel Fuel
Common Name: Diesel Fuel
Case Number: 68334-30-5

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146359
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Carbon Dioxide
Common Name: Carbon Dioxide
Case Number: 124-38-9

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146360
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Oxygen
Common Name: Oxygen
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146361
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Argon
Common Name: Argon
Case Number: 7440-37-1

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146362
Trade Secret: N
Hazardous Material Type: Pure

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146363
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Helium
Common Name: Helium
Case Number: 7440-59-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146364
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146365
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Lubricating Oils
Common Name: Lubricating Oils
Case Number: 72623-83-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0146366
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Flammable Paints
Common Name: Flammable Paints
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0125108
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Paint/Solvent Waste

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Common Name: Paint/Solvent Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0125109
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Waste 221. Waste oil and mixed oil
Common Name: Waste oil and mixed oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0125110
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Paint Waste
Common Name: Paint Waste/Paint Cans
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0125111
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Bilge Water/Oily Water with Diesel
Common Name: Bilge Water/Oily Water with Diesel
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0125112
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Diesel Waste
Common Name: Diesel Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0125113
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-07-27T13:36:07.000
Chemical Name: Oily Rags/Oily Sludge/Oily Debris
Common Name: Oily Rags/Oily Sludge/Oily Debris
Case Number: Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0125114
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-07-27T13:36:07.000
Chemical Name:	Waste Coolant/Antifreeze
Common Name:	Waste Coolant/Antifreeze
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0125115
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-07-27T13:36:07.000
Chemical Name:	Waste Oil/Diesel
Common Name:	Waste Oil/Diesel
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0125116
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-07-27T13:36:07.000
Chemical Name:	Waste Aerosols
Common Name:	Waste Aerosols
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0125117
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-07-27T13:36:07.000
Chemical Name:	Unknown
Common Name:	Oily and unknown liquids
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0124428
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2017-02-03T02:32:24.000
Chemical Name:	Stoddard Solvent/Thinner
Common Name:	Stoddard Solvent/Thinner
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0124429
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2017-02-03T02:32:24.000
Chemical Name:	Diesel Fuel
Common Name:	Diesel Fuel
Case Number:	68334-30-5
Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0124430
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2017-02-03T02:32:24.000
Chemical Name:	Carbon Dioxide
Common Name:	Carbon Dioxide
Case Number:	124-38-9
Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0124431
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2017-02-03T02:32:24.000
Chemical Name:	Oxygen
Common Name:	Oxygen
Case Number:	7782-44-7
Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0124432
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2017-02-03T02:32:24.000
Chemical Name:	Argon
Common Name:	Argon
Case Number:	7440-37-1
Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0124433
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2017-02-03T02:32:24.000
Chemical Name:	Propane
Common Name:	Liquefied Petroleum Gas (lpg)
Case Number:	74-98-6
Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0124434

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Helium
Common Name: Helium
Case Number: 7440-59-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0124435
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0124436
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Lubricating Oils
Common Name: Lubricating Oils
Case Number: 72623-83-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0124437
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Flammable Paints
Common Name: Flammable Paints
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103807
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Paint/Solvent Waste
Common Name: Paint/Solvent Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103808
Trade Secret: N
Hazardous Material Type: Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Waste 221. Waste oil and mixed oil
Common Name: Waste oil and mixed oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103809
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Paint Waste
Common Name: Paint Waste/Paint Cans
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103810
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Bilge Water/Oily Water with Diesel
Common Name: Bilge Water/Oily Water with Diesel
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103811
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Diesel Waste
Common Name: Diesel Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103812
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Oily Rags/Oily Sludge/Oily Debris
Common Name: Oily Rags/Oily Sludge/Oily Debris
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103813
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Waste Coolant/Antifreeze

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Common Name: Waste Coolant/Antifreeze
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103814
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Waste Oil/Diesel
Common Name: Waste Oil/Diesel
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103815
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Waste Aerosols
Common Name: Waste Aerosols
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103816
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Unknown
Common Name: Oily and unknown liquids
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0103817
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-03T02:32:24.000
Chemical Name: Unknown
Common Name: Thinner/Liquid Paint Sludge
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0163127
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Diesel Fuel
Common Name: Diesel Fuel
Case Number: 68334-30-5

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0163128
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-02-21T02:31:58.000
Chemical Name:	Carbon Dioxide
Common Name:	Carbon Dioxide
Case Number:	124-38-9

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0163129
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-02-21T02:31:58.000
Chemical Name:	Oxygen
Common Name:	Oxygen
Case Number:	7782-44-7

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0163130
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-02-21T02:31:58.000
Chemical Name:	Argon
Common Name:	Argon
Case Number:	7440-37-1

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0163131
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-02-21T02:31:58.000
Chemical Name:	Propane
Common Name:	Liquefied Petroleum Gas (lpg)
Case Number:	74-98-6

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0163132
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-02-21T02:31:58.000
Chemical Name:	Helium
Common Name:	Helium
Case Number:	7440-59-7

Record ID:	DEH2002-HUPFP-109768
Permit Status:	Permit Renewed

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Active Permit: Y
Child Record Id: DEH2017-HCHEM-0163133
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Acetylene
Common Name: Acetylene
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0163134
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Lubricating Oils
Common Name: Lubricating Oils
Case Number: 72623-83-7

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0163135
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Flammable Paints
Common Name: Flammable Paints
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138834
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Paint/Solvent Waste
Common Name: Paint/Solvent Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138835
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Waste 221. Waste oil
Common Name: Waste oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138836

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Paint Waste
Common Name: Paint Waste/Paint Cans
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138837
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Bilge Water/Oily Water with Diesel
Common Name: Bilge Water/Oily Water with Diesel
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138838
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Diesel Waste
Common Name: Diesel Waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138839
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Oily Rags/Oily Sludge/Oily Debris
Common Name: Oily Rags/Oily Sludge/Oily Debris
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138840
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Waste Coolant/Antifreeze
Common Name: Waste Coolant/Antifreeze
Case Number: Not reported

Record ID: DEH2002-HUPFP-109768
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0138841
Trade Secret: N
Hazardous Material Type: Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Last Updated: 2018-02-21T02:31:58.000
Chemical Name: Waste Aerosols
Common Name: Waste Aerosols
Case Number: Not reported

CERS HAZ WASTE:
Name: MARINE GROUP BOAT WORKS, LLC
Address: 997 G ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 132912
CERS ID: 10357831
CERS Description: RCRA LQ HW Generator

Name: MARINE GROUP BOAT WORKS, LLC
Address: 997 G ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 132912
CERS ID: 10357831
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: MARINE GROUP BOAT WORKS, LLC
Address: 997 G ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 132912
CERS ID: 10357831
CERS Description: Aboveground Petroleum Storage

ENF:
Name: MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address: 997 G STREET
City,State,Zip: CHULA VISTA, CA 91910
Region: 9
Facility Id: 257811
Agency Name: The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Place Type: Manufacturing
Place Subtype: Boatyard/Shipyard
Facility Type: Industrial
Agency Type: Privately-Owned Business
Of Agencies: 1
Place Latitude: 32.629876
Place Longitude: -117.107004
SIC Code 1: 3732
SIC Desc 1: Boat Building and Repairing
SIC Code 2: Not reported
SIC Desc 2: Not reported
SIC Code 3: Not reported
SIC Desc 3: Not reported
NAICS Code 1: Not reported
NAICS Desc 1: Not reported
NAICS Code 2: Not reported
NAICS Desc 2: Not reported
NAICS Code 3: Not reported
NAICS Desc 3: Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	0
Threat To Water Quality:	2
Complexity:	C
Pretreatment:	X - Facility is not a POTW
Facility Waste Type:	Process waste, NEC
Facility Waste Type 2:	Stormwater runoff
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDNONMUNIPRCS
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	9 000000481
Reg Measure Id:	388926
Reg Measure Type:	Enrollee - NPDES
Region:	9
Order #:	R9-2013-0026
Npdes# CA#:	CAG719001
Major-Minor:	Minor
Npdes Type:	OTH
Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Active
Status Date:	11/07/2018
Effective Date:	10/01/2013
Expiration/Review Date:	09/01/2018
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	57 - RB SW industrial Permits (INDSTW)
Direction/Voice:	Passive
Enforcement Id(EID):	426666
Region:	9
Order / Resolution Number:	Not reported
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	11/21/2018
Adoption/Issuance Date:	11/21/2018
Achieve Date:	Not reported
Termination Date:	11/21/2018
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	SEL for The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Description:	Not reported
Program:	NPDNONMUNIPRCS
Latest Milestone Completion Date:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	257811
Agency Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Place Type:	Manufacturing
Place Subtype:	Boatyard/Shipyard
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	32.629876
Place Longitude:	-117.107004
SIC Code 1:	3732
SIC Desc 1:	Boat Building and Repairing
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	0
Threat To Water Quality:	2
Complexity:	C
Pretreatment:	X - Facility is not a POTW
Facility Waste Type:	Process waste, NEC
Facility Waste Type 2:	Stormwater runoff
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDNONMUNIPRCS
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	9 000000481
Reg Measure Id:	388926
Reg Measure Type:	Enrollee - NPDES
Region:	9
Order #:	R9-2013-0026
Npdes# CA#:	CAG719001
Major-Minor:	Minor
Npdes Type:	OTH

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Active
Status Date:	11/07/2018
Effective Date:	10/01/2013
Expiration/Review Date:	09/01/2018
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	57 - RB SW industrial Permits (INDSTW)
Direction/Voice:	Passive
Enforcement Id(EID):	403543
Region:	9
Order / Resolution Number:	Not reported
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	12/16/2015
Adoption/Issuance Date:	12/16/2015
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Active
Title:	SEL for The Marine Group, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Description:	Not reported
Program:	NPDNONMUNIPRCS
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0
Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	257811
Agency Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Place Type:	Manufacturing
Place Subtype:	Boatyard/Shipyard
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	32.629876

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Place Longitude:	-117.107004
SIC Code 1:	3732
SIC Desc 1:	Boat Building and Repairing
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	0
Threat To Water Quality:	2
Complexity:	C
Pretreatment:	X - Facility is not a POTW
Facility Waste Type:	Process waste, NEC
Facility Waste Type 2:	Stormwater runoff
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDNONMUNIPRCS
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	9 000000481
Reg Measure Id:	388926
Reg Measure Type:	Enrollee - NPDES
Region:	9
Order #:	R9-2013-0026
Npdes# CA#:	CAG719001
Major-Minor:	Minor
Npdes Type:	OTH
Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Active
Status Date:	11/07/2018
Effective Date:	10/01/2013
Expiration/Review Date:	09/01/2018
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	57 - RB SW industrial Permits (INDSTW)
Direction/Voice:	Passive
Enforcement Id(EID):	398715
Region:	9
Order / Resolution Number:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	11/17/2014
Adoption/Issuance Date:	11/17/2014
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Active
Title:	SEL for The Marine Group, LLC (fmrly Southbay Boat Yard and Knight and Carver) for Category 2 Proposal
Description:	MG submitted a Category 2 proposal, but hasn't implemented it yet.
Program:	NPDNONMUNIPRCS
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	257811
Agency Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Place Type:	Manufacturing
Place Subtype:	Boatyard/Shipyard
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	32.629876
Place Longitude:	-117.107004
SIC Code 1:	3732
SIC Desc 1:	Boat Building and Repairing
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	0
Threat To Water Quality:	2
Complexity:	C
Pretreatment:	X - Facility is not a POTW
Facility Waste Type:	Process waste, NEC
Facility Waste Type 2:	Stormwater runoff

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDNONMUNIPRCS
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	9 000000481
Reg Measure Id:	388926
Reg Measure Type:	Enrollee - NPDES
Region:	9
Order #:	R9-2013-0026
Npdes# CA#:	CAG719001
Major-Minor:	Minor
Npdes Type:	OTH
Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Active
Status Date:	11/07/2018
Effective Date:	10/01/2013
Expiration/Review Date:	09/01/2018
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	57 - RB SW industrial Permits (INDSTW)
Direction/Voice:	Passive
Enforcement Id(EID):	396858
Region:	9
Order / Resolution Number:	Not reported
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	07/03/2014
Adoption/Issuance Date:	07/03/2014
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Active
Title:	SEL for The Marine Group Chula Vista
Description:	Monitoring plan not submitted. Upgrading to meet 5-year. Remodel should be complete July 2014.
Program:	NPDNONMUNIPRCS
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	257811
Agency Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Place Type:	Manufacturing
Place Subtype:	Boatyard/Shipyard
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	32.629876
Place Longitude:	-117.107004
SIC Code 1:	3732
SIC Desc 1:	Boat Building and Repairing
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	0
Threat To Water Quality:	2
Complexity:	C
Pretreatment:	X - Facility is not a POTW
Facility Waste Type:	Process waste, NEC
Facility Waste Type 2:	Stormwater runoff
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDINDSML
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	9 000000481
Reg Measure Id:	306929
Reg Measure Type:	NPDES Permits
Region:	9
Order #:	R9-2005-0153
Npdes# CA#:	CA0109126
Major-Minor:	Minor
Npdes Type:	OTH
Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	N
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	08/13/2013
Effective Date:	01/01/2006
Expiration/Review Date:	12/14/2010
Termination Date:	09/30/2013

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	66 - NPDES Based on Flow
Direction/Voice:	Active
Enforcement Id(EID):	379269
Region:	9
Order / Resolution Number:	Not reported
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	Not reported
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	08/21/2012
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	08/21/12 SEL for Order No. R9-2005-0153; The Marine Group, LLC
Description:	Review of quarterly and annual SMR from the reporting periods of January 2006 - March 2012. Order No. R9-2005-0153, NPDES CA0109126.
Program:	NPDESWW
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	257811
Agency Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Place Type:	Manufacturing
Place Subtype:	Boatyard/Shipyard
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	32.629876
Place Longitude:	-117.107004
SIC Code 1:	3732
SIC Desc 1:	Boat Building and Repairing
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	0
Threat To Water Quality:	2
Complexity:	C
Pretreatment:	X - Facility is not a POTW
Facility Waste Type:	Process waste, NEC
Facility Waste Type 2:	Washwater waste
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDNONMUNIPRCS
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	9 000000481
Reg Measure Id:	213850
Reg Measure Type:	Enrollee
Region:	9
Order #:	R9-2000-0213
Npdes# CA#:	CAG719001
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	07/15/2013
Effective Date:	09/13/1991
Expiration/Review Date:	12/31/2005
Termination Date:	12/31/2005
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	Y
Individual/General:	I
Fee Code:	66 - NPDES Based on Flow
Direction/Voice:	Passive
Enforcement Id(EID):	242492
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	08/28/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	08/28/2003
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Title:	Enforcement - 9 000000481
Description:	Incomplete report: no non-storm water visual observations included.
Program:	NPDNONMUNIPRCS
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	257811
Agency Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Place Type:	Manufacturing
Place Subtype:	Boatyard/Shipyard
Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	32.629876
Place Longitude:	-117.107004
SIC Code 1:	3732
SIC Desc 1:	Boat Building and Repairing
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	0
Threat To Water Quality:	2
Complexity:	C
Pretreatment:	X - Facility is not a POTW
Facility Waste Type:	Process waste, NEC
Facility Waste Type 2:	Washwater waste
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDINDSML
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	9 000000481
Reg Measure Id:	148277
Reg Measure Type:	NPDES Permits

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Region:	9
Order #:	R9-2000-0213
Npdes# CA#:	CA0109126
Major-Minor:	Minor
Npdes Type:	OTH
Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	N
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/31/2005
Effective Date:	10/11/2000
Expiration/Review Date:	12/31/2005
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	66 - NPDES Based on Flow
Direction/Voice:	Passive
Enforcement Id(EID):	234541
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	05/31/2000
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	05/31/2000
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	Enforcement - 9 000000481
Description:	Letter requesting penalty of perjury statement.
Program:	NPDINDSML
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	257811
Agency Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Place Type:	Manufacturing
Place Subtype:	Boatyard/Shipyard

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Facility Type:	Industrial
Agency Type:	Privately-Owned Business
# Of Agencies:	1
Place Latitude:	32.629876
Place Longitude:	-117.107004
SIC Code 1:	3732
SIC Desc 1:	Boat Building and Repairing
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	0
Threat To Water Quality:	2
Complexity:	C
Pretreatment:	X - Facility is not a POTW
Facility Waste Type:	Process waste, NEC
Facility Waste Type 2:	Washwater waste
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDINDSML
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	9 000000481
Reg Measure Id:	148277
Reg Measure Type:	NPDES Permits
Region:	9
Order #:	R9-2000-0213
Npdes# CA#:	CA0109126
Major-Minor:	Minor
Npdes Type:	OTH
Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	N
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/31/2005
Effective Date:	10/11/2000
Expiration/Review Date:	12/31/2005
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	66 - NPDES Based on Flow

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Direction/Voice:	Passive
Enforcement Id(EID):	234135
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Oral Communication
Effective Date:	03/01/2000
Adoption/Issuance Date:	Not reported
Achieve Date:	3/2/2000
Termination Date:	03/01/2000
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	Enforcement - 9 000000481
Description:	called discharger to inform him of missing report; he faxed report on 3/2/2000
Program:	NPDINDSML
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

NPDES:

Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Facility Status:	Active
NPDES Number:	CAG719001
Region:	9
Agency Number:	27797
Regulatory Measure ID:	388926
Place ID:	257811
Order Number:	R9-2013-0026
WDID:	9 000000481
Regulatory Measure Type:	Enrollee - NPDES
Program Type:	NPDNONMUNIPRCS
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	10/01/2013
Termination Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	10/01/2018
Discharge Address:	997 G Street
Discharge Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Discharge City:	Chula Vista
Discharge State:	CA
Discharge Zip:	91910
Status:	Not reported
Status Date:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City:	Not reported
Operator State:	Not reported
Operator Zip:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

NPDES as of 03/2018:

NPDES Number:	CAG719001
Status:	Active
Agency Number:	27797
Region:	9
Regulatory Measure ID:	388926
Order Number:	R9-2013-0026
Regulatory Measure Type:	Enrollee
Place ID:	257811
WDID:	9 000000481
Program Type:	NPDNONMUNIPRCS
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	10/01/2013
Expiration Date Of Regulatory Measure:	09/01/2018
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Discharge Address:	997 G Street
Discharge City:	Chula Vista
Discharge State:	CA
Discharge Zip:	91910
Received Date:	Not reported
Processed Date:	Not reported
Status:	Not reported
Status Date:	Not reported
Place Size:	Not reported
Place Size Unit:	Not reported
Contact:	Not reported
Contact Title:	Not reported
Contact Phone:	Not reported
Contact Phone Ext:	Not reported
Contact Email:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City:	Not reported
Operator State:	Not reported
Operator Zip:	Not reported
Operator Contact:	Not reported
Operator Contact Title:	Not reported
Operator Contact Phone:	Not reported
Operator Contact Phone Ext:	Not reported
Operator Contact Email:	Not reported
Operator Type:	Not reported
Developer:	Not reported
Developer Address:	Not reported
Developer City:	Not reported
Developer State:	Not reported
Developer Zip:	Not reported
Developer Contact:	Not reported
Developer Contact Title:	Not reported
Constype Linear Utility Ind:	Not reported
Emergency Phone:	Not reported
Emergency Phone Ext:	Not reported
Constype Above Ground Ind:	Not reported
Constype Below Ground Ind:	Not reported
Constype Cable Line Ind:	Not reported
Constype Comm Line Ind:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Constype Commertial Ind:	Not reported
Constype Electrical Line Ind:	Not reported
Constype Gas Line Ind:	Not reported
Constype Industrial Ind:	Not reported
Constype Other Description:	Not reported
Constype Other Ind:	Not reported
Constype Recons Ind:	Not reported
Constype Residential Ind:	Not reported
Constype Transport Ind:	Not reported
Constype Utility Description:	Not reported
Constype Utility Ind:	Not reported
Constype Water Sewer Ind:	Not reported
Dir Discharge Uswater Ind:	Not reported
Receiving Water Name:	Not reported
Certifier:	Not reported
Certifier Title:	Not reported
Certification Date:	Not reported
Primary Sic:	Not reported
Secondary Sic:	Not reported
Tertiary Sic:	Not reported
NPDES Number:	CAG719001
Status:	Active
Agency Number:	27797
Region:	9
Regulatory Measure ID:	388926
Order Number:	R9-2013-0026
Regulatory Measure Type:	Enrollee
Place ID:	785854
WDID:	9 000000481
Program Type:	NPDNONMUNIPRCS
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	10/01/2013
Expiration Date Of Regulatory Measure:	09/01/2018
Termination Date Of Regulatory Measure:	Not reported
Discharge Name:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Discharge Address:	997 G Street
Discharge City:	Chula Vista
Discharge State:	CA
Discharge Zip:	91910
Received Date:	Not reported
Processed Date:	Not reported
Status:	Not reported
Status Date:	Not reported
Place Size:	Not reported
Place Size Unit:	Not reported
Contact:	Not reported
Contact Title:	Not reported
Contact Phone:	Not reported
Contact Phone Ext:	Not reported
Contact Email:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City:	Not reported
Operator State:	Not reported
Operator Zip:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Operator Contact:	Not reported
Operator Contact Title:	Not reported
Operator Contact Phone:	Not reported
Operator Contact Phone Ext:	Not reported
Operator Contact Email:	Not reported
Operator Type:	Not reported
Developer:	Not reported
Developer Address:	Not reported
Developer City:	Not reported
Developer State:	Not reported
Developer Zip:	Not reported
Developer Contact:	Not reported
Developer Contact Title:	Not reported
Constype Linear Utility Ind:	Not reported
Emergency Phone:	Not reported
Emergency Phone Ext:	Not reported
Constype Above Ground Ind:	Not reported
Constype Below Ground Ind:	Not reported
Constype Cable Line Ind:	Not reported
Constype Comm Line Ind:	Not reported
Constype Commertial Ind:	Not reported
Constype Electrical Line Ind:	Not reported
Constype Gas Line Ind:	Not reported
Constype Industrial Ind:	Not reported
Constype Other Description:	Not reported
Constype Other Ind:	Not reported
Constype Recons Ind:	Not reported
Constype Residential Ind:	Not reported
Constype Transport Ind:	Not reported
Constype Utility Description:	Not reported
Constype Utility Ind:	Not reported
Constype Water Sewer Ind:	Not reported
Dir Discharge Uswater Ind:	Not reported
Receiving Water Name:	Not reported
Certifier:	Not reported
Certifier Title:	Not reported
Certification Date:	Not reported
Primary Sic:	Not reported
Secondary Sic:	Not reported
Tertiary Sic:	Not reported

CIWQS:

Name:	MARINE GROUP BOAT WORKS - CHULA VISTA (FMRLY SOUTH BAY BOATYARD)
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	The Marine Group Boat Works, LLC (fmrly Southbay Boat Yard and Knight and Carver)
Agency Address:	997 G Street, Chula Vista, CA 91910
Place/Project Type:	Boatyard/Shipyard
SIC/NAICS:	3732
Region:	9
Program:	CERFILLEXC, NPDINDSML, NPDNONMUNIPRCS
Regulatory Measure Status:	Active
Regulatory Measure Type:	Enrollee - NPDES
Order Number:	R9-2013-0026
WDID:	9 000000481
NPDES Number:	CAG719001

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Adoption Date:	Not reported
Effective Date:	10/01/2013
Termination Date:	Not reported
Expiration/Review Date:	10/01/2018
Design Flow:	0
Major/Minor:	Minor
Complexity:	C
TTWQ:	2
Enforcement Actions within 5 years:	2
Violations within 5 years:	2
Latitude:	32.629876
Longitude:	-117.107004

Name:	MARINE GROUP BOAT WORKS
Address:	997 G STREET
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Marine Group Boat Works
Agency Address:	997 G Street, Chula Vista, CA 91910
Place/Project Type:	Construction
SIC/NAICS:	Not reported
Region:	9
Program:	CONSTW
Regulatory Measure Status:	Terminated
Regulatory Measure Type:	Storm water construction
Order Number:	2009-0009-DWQ
WDID:	9 37C369484
NPDES Number:	CAS000002
Adoption Date:	Not reported
Effective Date:	04/18/2014
Termination Date:	01/12/2015
Expiration/Review Date:	Not reported
Design Flow:	Not reported
Major/Minor:	Not reported
Complexity:	Not reported
TTWQ:	Not reported
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.630918
Longitude:	-117.106298

CERS:

Name:	MARINE GROUP BOAT WORKS, LLC
Address:	997 G ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	132912
CERS ID:	10357831
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	03-25-2015
Citation:	22 CCR 15 66265.31 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.31
Violation Description:	Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

	to the air, soil, or surface water which could threaten human health or the environment.
Violation Notes:	Returned to compliance on 04/06/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HWLQG
Violation Source:	CERS
Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	07-11-2019
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to prepare a Spill Prevention, Control, and Countermeasures (SPCC) Plan.
Violation Notes:	Returned to compliance on 07/27/2019. Inspection Sequence ID:6191626
Violation Division:	San Diego County Department of Env Health
Violation Program:	APSA
Violation Source:	CERS
Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	03-25-2015
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 04/06/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HWLQG
Violation Source:	CERS
Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	03-25-2015
Citation:	22 CCR 15 66265.173 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.173
Violation Description:	Failure to properly close hazardous waste containers when not in active use.
Violation Notes:	Returned to compliance on 04/06/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HWLQG
Violation Source:	CERS
Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	03-25-2015
Citation:	22 CCR 12 66262.11 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.11
Violation Description:	Failure to determine if the waste generated is a hazardous waste.
Violation Notes:	Returned to compliance on 03/25/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HWLQG
Violation Source:	CERS
Site ID:	132912

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	03-25-2015
Citation:	19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.
Violation Notes:	Returned to compliance on 06/01/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	03-25-2015
Citation:	HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507
Violation Description:	Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes:	Returned to compliance on 06/01/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	03-25-2015
Citation:	22 CCR 15 66265.171 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.171
Violation Description:	Failure to accumulate hazardous waste in a container that is in good condition.
Violation Notes:	Returned to compliance on 04/06/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	03-25-2015
Citation:	HSC 6.5 25189.5(a) - California Health and Safety Code, Chapter 6.5, Section(s) 25189.5(a)
Violation Description:	Failure to properly dispose of hazardous waste at an authorized location.
Violation Notes:	Returned to compliance on 03/25/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	132912
Site Name:	MARINE GROUP BOAT WORKS, LLC
Violation Date:	07-11-2019
Citation:	22 CCR 23 66273.32(b) - California Code of Regulations, Title 22, Chapter 23, Section(s) 66273.32(b)
Violation Description:	Failure of a universal waste handler to obtain an ID Number from DTSC prior to storing 5,000 kilograms or more of non-RCRA universal waste.
Violation Notes:	Returned to compliance on 08/15/2019. Inspection Sequence ID:6191626
Violation Division:	San Diego County Department of Env Health

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Violation Program: HW
Violation Source: CERS

Site ID: 132912
Site Name: MARINE GROUP BOAT WORKS, LLC
Violation Date: 03-25-2015
Citation: 22 CCR 15 66265.174 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.174
Violation Description: Failure to inspect hazardous waste storage areas at least weekly.
Violation Notes: Returned to compliance on 04/06/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HWLQG
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-25-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Javid Hasti Inspection ID:4687493
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-25-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Javid Hasti Inspection ID:4687493
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-25-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Javid Hasti Inspection ID:4687493
Eval Division: San Diego County Department of Env Health
Eval Program: HWLQG
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-21-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Anderson Sean Inspection ID:5646058
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-21-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Anderson Sean Inspection ID:5646058
Eval Division: San Diego County Department of Env Health

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	06-21-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Anderson Sean Inspection ID:5646058
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-11-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Griffith Gary Inspection ID:6191626
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-11-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Griffith Gary Inspection ID:6191626
Eval Division:	San Diego County Department of Env Health
Eval Program:	HWLQG
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-11-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Griffith Gary Inspection ID:6191626
Eval Division:	San Diego County Department of Env Health
Eval Program:	APSA
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-11-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Griffith Gary Inspection ID:6191626
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Coordinates:

Site ID:	132912
Facility Name:	MARINE GROUP BOAT WORKS, LLC
Env Int Type Code:	HWG
Program ID:	10357831
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	32.630920
Longitude:	-117.106300

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Affiliation:

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	997 G street
Affiliation City:	Chule Vista
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported

Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880

Affiliation Type Desc:	Document Preparer
Entity Name:	Joe Beltran
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Environmental Contact
Entity Name:	Joe Beltran
Entity Title:	Not reported
Affiliation Address:	997 G street
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported

Affiliation Type Desc:	Identification Signer
Entity Name:	Joe Beltran
Entity Title:	Compliance Manager
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Parent Corporation
Entity Name:	MARINE GROUP BOAT WORKS, LLC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **S103993648**

Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	MARINE GROUP BOAT WORKS LLC
Entity Title:	Not reported
Affiliation Address:	997 G Street
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 427-6767
Affiliation Type Desc:	Operator
Entity Name:	MARINE GROUP BOAT WORKS LLC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 373-2822

I42 **SOUTH BAY BOAT YARD** **SEMS-ARCHIVE** **1003879834**
West **997 G** **CAD983658451**
1/8-1/4 **CHULA VISTA, CA 92010**
0.205 mi.
1080 ft. **Site 3 of 10 in cluster I**

Relative:
Lower

Actual:
9 ft.

SEMS Archive:

Site ID:	0904774
EPA ID:	CAD983658451
Name:	SOUTH BAY BOAT YARD
Address:	997 G
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 92010
Cong District:	44
FIPS Code:	06073
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	09
Site ID:	0904774
EPA ID:	CAD983658451
Site Name:	SOUTH BAY BOAT YARD
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1993-10-05 04:00:00
Qual:	Not reported

SOUTH BAY BOAT YARD (Continued) **1003879834**

Current Action Lead: EPA Perf In-Hse

Region: 09
Site ID: 0904774
EPA ID: CAD983658451
Site Name: SOUTH BAY BOAT YARD
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1993-02-08 05:00:00
Finish Date: 1993-02-08 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0904774
EPA ID: CAD983658451
Site Name: SOUTH BAY BOAT YARD
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: Not reported
Finish Date: 1993-10-05 04:00:00
Qual: N
Current Action Lead: EPA Perf

I43 **PACIFIC YACHT REFITTERS INC** **RCRA-SQG** **1010562049**
West **997 G ST** **HAZNET** **CAR000186155**
1/8-1/4 **CHULA VISTA, CA 91910** **HWTS**
0.205 mi.
1080 ft. **Site 4 of 10 in cluster I**

Relative: RCRA-SQG:
Lower
Date Form Received by Agency: 2007-07-26 00:00:00.0
Actual: Handler Name: PACIFIC YACHT REFITTERS INC
9 ft. Handler Address: 997 G ST
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAR000186155
Contact Name: STACI J HOYLE
Contact Address: 997 G ST
Contact City,State,Zip: CHULA VISTA, CA 91910
Contact Telephone: 619-426-1998
Contact Fax: Not reported
Contact Email: STACI@PYRSD.COM
Contact Title: Not reported
EPA Region: 09
Land Type: District
Federal Waste Generator Description: Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported

PACIFIC YACHT REFITTERS INC (Continued) **1010562049**

Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	997 G ST
Mailing City,State,Zip:	CHULA VISTA, CA 91910
Owner Name:	DANIEL CUMMINS
Owner Type:	Private
Operator Name:	PACIFIC YACHT REFITTERS INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	Yes
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2007-08-13 14:20:01.0

PACIFIC YACHT REFITTERS INC (Continued) **1010562049**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D005
Waste Description:	BARIUM

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PACIFIC YACHT REFITTERS INC
Legal Status:	Private
Date Became Current:	2007-06-12 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	DANIEL CUMMINS
Legal Status:	Private
Date Became Current:	1997-08-13 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	997 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2007-07-26 00:00:00.0
Handler Name:	PACIFIC YACHT REFITTERS INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

PACIFIC YACHT REFITTERS INC (Continued) **1010562049**

List of NAICS Codes and Descriptions:
NAICS Code: 336611
NAICS Description: SHIP BUILDING AND REPAIRING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

HAZNET:
Name: PACIFIC YACHT REFITTERS INC
Address: 997 G ST
Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 919100000
Contact: DANIEL CUMMINS
Telephone: 6194261998
Mailing Name: Not reported
Mailing Address: 997 G ST

Year: 2010
Gepaid: CAR000186155
TSD EPA ID: CAD008252405
CA Waste Code: 331 - Off-specification, aged or surplus organics
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 2.1621

Year: 2009
Gepaid: CAR000186155
TSD EPA ID: CAD008252405
CA Waste Code: 331 - Off-specification, aged or surplus organics
Disposal Method: -
Tons: 0.2315

Year: 2009
Gepaid: CAR000186155
TSD EPA ID: CAD008252405
CA Waste Code: 331 - Off-specification, aged or surplus organics
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.716

Additional Info:
Year: 2010
Gen EPA ID: CAR000186155

Shipment Date: 20100304
Creation Date: 12/3/2010 18:30:22
Receipt Date: 20100311
Manifest ID: 005697092JJK
Trans EPA ID: CAR000159459
Trans Name: NORTH STATE ENVIRONMENTAL
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported

PACIFIC YACHT REFITTERS INC (Continued) **1010562049**

TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	0.3405
Waste Quantity:	681
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20100111
Creation Date:	10/26/2010 18:30:22
Receipt Date:	20100114
Manifest ID:	005697006JJK
Trans EPA ID:	CAR000159459
Trans Name:	NORTH STATE ENVIRONMENTAL
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	1.8216
Waste Quantity:	552
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2009
Gen EPA ID:	CAR000186155

Shipment Date:	20091009
Creation Date:	12/11/2012 22:16:18
Receipt Date:	Not reported
Manifest ID:	005696751JJK
Trans EPA ID:	CAR000159459
Trans Name:	NORTH STATE ENVIRONMENTAL
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics

PACIFIC YACHT REFITTERS INC (Continued) **1010562049**

RCRA Code:	D001
Meth Code:	- Not reported
Quantity Tons:	0.2315
Waste Quantity:	463
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20090219
Creation Date:	7/20/2009 18:30:18
Receipt Date:	20090226
Manifest ID:	005662844JJK
Trans EPA ID:	CAR000159459
Trans Name:	NORTH STATE ENVIRONMENTAL
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	0.179
Waste Quantity:	358
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20090205
Creation Date:	7/14/2009 18:30:20
Receipt Date:	20090210
Manifest ID:	005662834JJK
Trans EPA ID:	CAR000159459
Trans Name:	NORTH STATE ENVIRONMENTAL
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	0.2425
Waste Quantity:	485
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported

PACIFIC YACHT REFITTERS INC (Continued) **1010562049**

Additional Code 5:	Not reported
Shipment Date:	20090129
Creation Date:	7/2/2009 18:30:42
Receipt Date:	20090204
Manifest ID:	005662753JJK
Trans EPA ID:	CAR000159459
Trans Name:	NORTH STATE ENVIRONMENTAL
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	0.2945
Waste Quantity:	589
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HWTS:

Name:	PACIFIC YACHT REFITTERS INC
Address:	997 G ST
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 919100000
EPA ID:	CAR000186155
Inactive Date:	06/30/2017
Create Date:	08/21/2007
Last Act Date:	02/15/2017
Mailing Name:	DANIEL CUMMINS
Mailing Address:	2626 SOUTHPORT WAY STE B
Mailing Address 2:	Not reported
Mailing City,State,Zip:	NATIONAL CITY, CA 919500000
Owner Name:	PACIFIC YACHT REFITTERS INC
Owner Address:	997 G ST
Owner Address 2:	Not reported
Owner City,State,Zip:	CHULA VISTA, CA 919100000
Contact Name:	DANIEL CUMMINS
Contact Address:	997 G ST
Contact Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 91910

I44 **PACIFIC YACHT REFITTER, INC** **AST** **S106060174**
West **997 G ST** **San Diego Co. HMMD** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.205 mi.
1080 ft. **Site 5 of 10 in cluster I**

Relative:
Lower

Actual:
9 ft.

AST:

Name:	THE MARINE GROUP LLC
Address:	997 G ST
City/Zip:	CHULA VISTA,
Certified Unified Program Agencies:	San Diego
Owner:	THE MARINE GROUP LLC
Total Gallons:	2815
CERSID:	Not reported
Facility ID:	Not reported
Business Name:	Not reported
Phone:	Not reported
Fax:	Not reported
Mailing Address:	Not reported
Mailing Address City:	Not reported
Mailing Address State:	Not reported
Mailing Address Zip Code:	Not reported
Operator Name:	Not reported
Operator Phone:	Not reported
Owner Phone:	Not reported
Owner Mail Address:	Not reported
Owner State:	Not reported
Owner Zip Code:	Not reported
Owner Country:	Not reported
Property Owner Name:	Not reported
Property Owner Phone:	Not reported
Property Owner Mailing Address:	Not reported
Property Owner City:	Not reported
Property Owner Stat :	Not reported
Property Owner Zip Code:	Not reported
Property Owner Country:	Not reported
EPAID:	Not reported

HMMD SAN DIEGO:

Name:	PACIFIC YACHT REFITTER, INC
Address:	997 G ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	102647
Business Type:	6HK70
EPA Id Number:	CAR000186155
APN:	DEH-102647
Last HMMD Inspection:	06/29/2011
Facility Telephone:	619-426-1998
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	DANIEL CUMMINS
Facility Mailing Address:	997 G ST#B
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910-
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 102647
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102647
Update Date: 11/02/2012
Case Number: Not reported
Name: PAINTS (VARIOUS TYPES)
Other Information: THINNERS, ACETONE, SOLVENT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102647
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 461 PAINT SLUDGE
Other Information: PAINT WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 102647
Update Date: 11/02/2012
Inspection Date: 11/01/2005
Violation Code: 6HV0207
Violation: FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Violation Citation: Facility not maintained &/operated to minimize possibility of fire, explosion or release. CCR 66265.31
Activity: ACTIVE

Permit Number: 102647
Update Date: 11/02/2012
Inspection Date: 06/29/2011
Violation Code: 6HV1001
Violation: NO UPF PERMIT FOR HAZMATS
Violation Citation: A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity: ACTIVE

Permit Number: 102647
Update Date: 11/02/2012
Inspection Date: 06/29/2011
Violation Code: 6HV0131
Violation: UPF Permit NOT OBTAINED for HAZWASTE

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Violation Citation:	A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector's review. 25505(e)
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	10/08/2003
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	09/12/2007
Violation Code:	6HV1018
Violation:	INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation:	Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	09/12/2007
Violation Code:	6HV0138
Violation:	NO TSDF SIGNED MANIFEST ONSITE
Violation Citation:	Generator has not maintained the required signed copy of the hazardous waste manifest from the TSD facility on site for review. CCR 66262.40(a)
Activity:	ACTIVE
Name:	PACIFIC YACHT REFITTER, INC
Address:	997 G ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	102647
Business Type:	6HK70
EPA Id Number:	CAR000186155
APN:	DEH-102647
Last HMMD Inspection:	06/29/2011
Facility Telephone:	619-426-1998
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	DANIEL CUMMINS
Facility Mailing Address:	997 G ST#B
Facility Mailing City:	CHULA VISTA

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Facility Mailing State: CA
Facility Mailing Zip: 91910-
UST Owner: Not reported
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 102647
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102647
Update Date: 11/02/2012
Case Number: Not reported
Name: PAINTS (VARIOUS TYPES)
Other Information: THINNERS, ACETONE, SOLVENT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102647
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 461 PAINT SLUDGE
Other Information: PAINT WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 102647
Update Date: 11/02/2012
Inspection Date: 11/01/2005
Violation Code: 6HV0207
Violation: FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Violation Citation: Facility not maintained &/operated to minimize possibility of fire, explosion or release. CCR 66265.31
Activity: ACTIVE

Permit Number: 102647
Update Date: 11/02/2012
Inspection Date: 06/29/2011
Violation Code: 6HV1001
Violation: NO UPF PERMIT FOR HAZMATS
Violation Citation: A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity: ACTIVE

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV0131
Violation:	UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation:	A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity:	ACTIVE

Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector's review. 25505(e)
Activity:	ACTIVE

Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	10/08/2003
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE

Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	09/12/2007
Violation Code:	6HV1018
Violation:	INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation:	Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity:	ACTIVE

Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	09/12/2007
Violation Code:	6HV0138
Violation:	NO TSDF SIGNED MANIFEST ONSITE
Violation Citation:	Generator has not maintained the required signed copy of the hazardous waste manifest from the TSD facility on site for review. CCR 66262.40(a)
Activity:	ACTIVE

Name:	PACIFIC YACHT REFITTER, INC
Address:	997 G ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	102647
Business Type:	6HK70
EPA Id Number:	CAR000186155
APN:	DEH-102647
Last HMMD Inspection:	06/29/2011
Facility Telephone:	619-426-1998
Permit Status:	OPEN

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	DANIEL CUMMINS
Facility Mailing Address:	997 G ST#B
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910-
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	102647
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	CHRONIC
Hazardous Categories 2:	Not reported

Permit Number:	102647
Update Date:	11/02/2012
Case Number:	Not reported
Name:	PAINTS (VARIOUS TYPES)
Other Information:	THINNERS, ACETONE, SOLVENT
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported

Permit Number:	102647
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 461 PAINT SLUDGE
Other Information:	PAINT WASTE
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Violations Active Permits:

Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	11/01/2005
Violation Code:	6HV0207
Violation:	FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Violation Citation:	Facility not maintained &/operated to minimize possibility of fire, explosion or release. CCR 66265.31
Activity:	ACTIVE

Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV1001

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Violation:	NO UPF PERMIT FOR HAZMATS
Violation Citation:	A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV0131
Violation:	UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation:	A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector’s review. 25505(e)
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	10/08/2003
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	09/12/2007
Violation Code:	6HV1018
Violation:	INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation:	Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	09/12/2007
Violation Code:	6HV0138
Violation:	NO TSDF SIGNED MANIFEST ONSITE
Violation Citation:	Generator has not maintained the required signed copy of the hazardous waste manifest from the TSD facility on site for review. CCR 66262.40(a)
Activity:	ACTIVE
Name:	PARAMOUNT SCAFFOLD INC
Address:	997 G ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	205776
Business Type:	6HK70

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

EPA Id Number: CAL000334038
APN: 760-048-17-00
Last HMMD Inspection: 05/09/2011
Facility Telephone: 619-498-8552
Permit Status: OPEN
Permit Expiration: 01/31/2013
Date Last Updated: 11/02/2012
Facility Owner: DAN JOHNSON
Facility Mailing Address: 997 G ST
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910
UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: N
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 205776
Update Date: 11/02/2012
Case Number: 74-98-6
Name: DIESEL FUEL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 205776
Update Date: 11/02/2012
Case Number: 68476-85-7
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 205776
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: USED AEROSOLS CANS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 205776
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 205776

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 05/09/2011
Violation Code: 6HV1013
Violation: HMBP NOT AVAILABLE FOR REVIEW
Violation Citation: Copy of HMBP not onsite for inspector's review. 25505(e)
Activity: ACTIVE

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 05/09/2011
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity: ACTIVE

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 05/09/2011
Violation Code: 6HV0227
Violation: HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation: Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity: ACTIVE

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 07/13/2007
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity: ACTIVE

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 07/13/2007
Violation Code: 6HV1013
Violation: HMBP NOT AVAILABLE FOR REVIEW
Violation Citation: Copy of HMBP not onsite for inspector's review. 25505(e)
Activity: ACTIVE

Name: PACIFIC YACHT REFITTER, INC
Address: 997 G ST

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 102647
Business Type: 6HK70
EPA Id Number: CAR000186155
APN: DEH-102647
Last HMMD Inspection: 06/29/2011
Facility Telephone: 619-426-1998
Permit Status: OPEN
Permit Expiration: 02/28/2013
Date Last Updated: 11/02/2012
Facility Owner: DANIEL CUMMINS
Facility Mailing Address: 997 G ST#B
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910-
UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 102647
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102647
Update Date: 11/02/2012
Case Number: Not reported
Name: PAINTS (VARIOUS TYPES)
Other Information: THINNERS, ACETONE, SOLVENT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102647
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 461 PAINT SLUDGE
Other Information: PAINT WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 102647
Update Date: 11/02/2012
Inspection Date: 11/01/2005
Violation Code: 6HV0207
Violation: FIRE/EXPLOSION/RELEASE NOT MINIMIZED

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Violation Citation:	Facility not maintained &/operated to minimize possibility of fire, explosion or release. CCR 66265.31
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV1001
Violation:	NO UPF PERMIT FOR HAZMATS
Violation Citation:	A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV0131
Violation:	UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation:	A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	06/29/2011
Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector's review. 25505(e)
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	10/08/2003
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	09/12/2007
Violation Code:	6HV1018
Violation:	INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation:	Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity:	ACTIVE
Permit Number:	102647
Update Date:	11/02/2012
Inspection Date:	09/12/2007
Violation Code:	6HV0138
Violation:	NO TSDF SIGNED MANIFEST ONSITE
Violation Citation:	Generator has not maintained the required signed copy of the hazardous waste manifest from the TSD facility on site for review. CCR 66262.40(a)

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Activity: ACTIVE

Name: PARAMOUNT SCAFFOLD INC
Address: 997 G ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 205776
Business Type: 6HK70
EPA Id Number: CAL000334038
APN: 760-048-17-00
Last HMMD Inspection: 05/09/2011
Facility Telephone: 619-498-8552
Permit Status: OPEN
Permit Expiration: 01/31/2013
Date Last Updated: 11/02/2012
Facility Owner: DAN JOHNSON
Facility Mailing Address: 997 G ST
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910
UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Y
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 205776
Update Date: 11/02/2012
Case Number: 74-98-6
Name: DIESEL FUEL
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 205776
Update Date: 11/02/2012
Case Number: 68476-85-7
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 205776
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: USED AEROSOLS CANS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 205776
Update Date: 11/02/2012

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 205776
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 05/09/2011
Violation Code: 6HV1013
Violation: HMBP NOT AVAILABLE FOR REVIEW
Violation Citation: Copy of HMBP not onsite for inspector's review. 25505(e)
Activity: ACTIVE

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 05/09/2011
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity: ACTIVE

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 05/09/2011
Violation Code: 6HV0227
Violation: HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation: Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity: ACTIVE

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 07/13/2007
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity: ACTIVE

Permit Number: 205776
Update Date: 11/02/2012
Inspection Date: 07/13/2007

PACIFIC YACHT REFITTER, INC (Continued) **S106060174**

Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector's review. 25505(e)
Activity:	ACTIVE

I45 **MARINE GROUP BOAT WORKS, LLC** **RCRA-LQG** **1025882837**
West **997 G ST** **CAR000298620**
1/8-1/4 **CHULA VISTA, CA 91910**
0.205 mi.
1080 ft. **Site 6 of 10 in cluster I**

Relative: RCRA-LQG:
Lower

Actual: Date Form Received by Agency:	2020-02-28 00:00:00.0
9 ft. Handler Name:	MARINE GROUP BOAT WORKS, LLC
Handler Address:	997 G ST
Handler City,State,Zip:	CHULA VISTA, CA 91910
EPA ID:	CAR000298620
Contact Name:	JOSE A BELTRAN
Contact Address:	G ST
Contact City,State,Zip:	CHULA VISTA, CA 91910
Contact Telephone:	619-427-6767 x143
Contact Fax:	619-427-0324
Contact Email:	JBELTRAN@MARINEGROUPBW.COM
Contact Title:	EHS COMPLIANCE MANAGER
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2019
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	G ST
Mailing City,State,Zip:	CHULA VISTA, CA 91910
Owner Name:	MARINE GROUP BOAT WORKS, LLC
Owner Type:	Private
Operator Name:	MARINE GROUP BOAT WORKS, LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **1025882837**

Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-10-21 18:30:59.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D035
Waste Description:	METHYL ETHYL KETONE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR

MARINE GROUP BOAT WORKS, LLC (Continued) **1025882837**

MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MARINE GROUP BOAT WORKS, LLC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	997 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-427-6767
Owner/Operator Telephone Ext:	143
Owner/Operator Fax:	619-427-0324
Owner/Operator Email:	JBELTRAN@MARINEGROUPBW.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MARINE GROUP BOAT WORKS, LLC
Legal Status:	Private
Date Became Current:	2010-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	997 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-427-6767
Owner/Operator Telephone Ext:	143
Owner/Operator Fax:	619-427-0324
Owner/Operator Email:	JBELTRAN@MARINEGROUPBW.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MARINE GROUP BOAT WORKS, LLC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	997 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-427-6767
Owner/Operator Telephone Ext:	143
Owner/Operator Fax:	619-427-0324
Owner/Operator Email:	JBELTRAN@MARINEGROUPBW.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MARINE GROUP BOAT WORKS, LLC
Legal Status:	Private
Date Became Current:	2010-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	997 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910

MARINE GROUP BOAT WORKS, LLC (Continued) **1025882837**

Owner/Operator Telephone: 619-427-6767
Owner/Operator Telephone Ext: 143
Owner/Operator Fax: 619-427-0324
Owner/Operator Email: JBELTRAN@MARINEGROUPBW.COM

Historic Generators:
Receive Date: 2020-02-28 00:00:00.0
Handler Name: MARINE GROUP BOAT WORKS, LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 2019-08-12 00:00:00.0
Handler Name: MARINE GROUP BOAT WORKS, LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 336611
NAICS Description: SHIP BUILDING AND REPAIRING

NAICS Code: 336612
NAICS Description: BOAT BUILDING

Facility Has Received Notices of Violation:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

MARINE GROUP BOAT WORKS, LLC (Continued) **1025882837**

Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	2019-07-11 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

I46 **SOUTH BAY BOILER REPAIR, INC.** **RCRA NonGen / NLR** **1024810033**
West **997 G ST** **CAL000287787**
1/8-1/4 **CHULA VISTA, CA 91910**
0.205 mi.
1080 ft. **Site 7 of 10 in cluster I**

Relative: **Lower**

Actual: **9 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2004-11-01 00:00:00.0
Handler Name:	SOUTH BAY BOILER REPAIR, INC.
Handler Address:	997 G ST
Handler City,State,Zip:	CHULA VISTA, CA 91910
EPA ID:	CAL000287787
Contact Name:	JAMES WILKERSON
Contact Address:	1224 ROOSEVELT AVE
Contact City,State,Zip:	NATIONAL CITY, CA 91950
Contact Telephone:	619-474-8563
Contact Fax:	619-474-1873
Contact Email:	JIMW@SBBR.BIZ
Contact Title:	Not reported
EPA Region:	09

SOUTH BAY BOILER REPAIR, INC. (Continued) **1024810033**

Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1224 ROOSEVELT AVE
Mailing City,State,Zip:	NATIONAL CITY, CA 91950-0000
Owner Name:	JAMES WILKERSON
Owner Type:	Other
Operator Name:	JAMES WILKERSON
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

SOUTH BAY BOILER REPAIR, INC. (Continued) **1024810033**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 20:26:07.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JAMES WILKERSON
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1224 ROOSEVELT AVE
Owner/Operator City,State,Zip:	NATIONAL CITY, CA 91950-0000
Owner/Operator Telephone:	619-474-8563
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	JAMES WILKERSON
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1224 ROOSEVELT AVE
Owner/Operator City,State,Zip:	NATIONAL CITY, CA 91950
Owner/Operator Telephone:	619-474-8563
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2004-11-01 00:00:00.0
Handler Name:	SOUTH BAY BOILER REPAIR, INC.
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	48839
NAICS Description:	OTHER SUPPORT ACTIVITIES FOR WATER TRANSPORTATION

SOUTH BAY BOILER REPAIR, INC. (Continued) **1024810033**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I47 **MARINE GROUP BOAT WORKS LLC** **RCRA-SQG** **1019899308**
West **997 G ST** **CAL000017529**
1/8-1/4 **CHULA VISTA, CA 91910**
0.205 mi.
1080 ft. **Site 8 of 10 in cluster I**

Relative: RCRA-SQG:
Lower

Date Form Received by Agency:	2018-02-19 00:00:00.0
Handler Name:	MARINE GROUP BOAT WORKS LLC
Handler Address:	997 G ST
Handler City,State,Zip:	CHULA VISTA, CA 91910-3414
EPA ID:	CAL000017529
Contact Name:	JOE A BELTRAN
Contact Address:	G ST
Contact City,State,Zip:	CHULA VISTA, CA 91910-3414
Contact Telephone:	619-427-6767 143
Contact Fax:	619-427-0324
Contact Email:	JBELTRAN@MARINEGROUPBW.COM
Contact Title:	COMPLIANCE MANAGER
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	G ST
Mailing City,State,Zip:	CHULA VISTA, CA 91910-3414
Owner Name:	MARINE GROUP BOAT WORKS, LLC
Owner Type:	Private
Operator Name:	MARINE GROUP BOAT WORKS, LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported

Actual:
9 ft.

MARINE GROUP BOAT WORKS LLC (Continued) **1019899308**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-11-26 18:57:03.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	Not reported

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: F003

MARINE GROUP BOAT WORKS LLC (Continued) **1019899308**

Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	TODD ROBERTS
Legal Status:	Private
Date Became Current:	2009-12-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MARINE GROUP BOAT WORKS, LLC
Legal Status:	Private
Date Became Current:	2010-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	997 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910-3414
Owner/Operator Telephone:	619-427-6767
Owner/Operator Telephone Ext:	143
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JBELTRAN@MARINEGROUPBW.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MARINE GROUP BOAT WORKS, LLC
Legal Status:	Private
Date Became Current:	2010-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	997 G ST
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910-3414
Owner/Operator Telephone:	619-427-6767
Owner/Operator Telephone Ext:	143
Owner/Operator Fax:	Not reported
Owner/Operator Email:	JBELTRAN@MARINEGROUPBW.COM

MARINE GROUP BOAT WORKS LLC (Continued) **1019899308**

Owner/Operator Indicator: Owner
Owner/Operator Name: ART ENGEL
Legal Status: Private
Date Became Current: 2009-12-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 997 G STREET
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910
Owner/Operator Telephone: 619-427-6767
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2016-07-05 00:00:00.0
Handler Name: MARINE GROUP BOAT WORKS LLC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2018-02-19 00:00:00.0
Handler Name: MARINE GROUP BOAT WORKS LLC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 336611
NAICS Description: SHIP BUILDING AND REPAIRING

NAICS Code: 336612
NAICS Description: BOAT BUILDING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G48 **RON MARTIN** **RCRA NonGen / NLR** **1025840351**
ENE **456 WOODAWN AVE** **CAC003019955**
1/8-1/4 **CHULA VISTA, CA 91910**
0.217 mi.
1145 ft. **Site 6 of 6 in cluster G**

Relative: **Higher**

Actual: **28 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2019-06-17 00:00:00.0
Handler Name:	RON MARTIN	
Handler Address:		456 WOODAWN AVE
Handler City,State,Zip:		CHULA VISTA, CA 91910
EPA ID:		CAC003019955
Contact Name:		RON MARTIN
Contact Address:		456 WOODAWN AVE
Contact City,State,Zip:		CHULA VISTA, CA 91910
Contact Telephone:		916-385-4342
Contact Fax:		Not reported
Contact Email:		INFO@JJANDSCONSTRUCTION.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		456 WOODAWN AVE
Mailing City,State,Zip:		CHULA VISTA, CA 91910
Owner Name:		RON MARTIN
Owner Type:		Other
Operator Name:		RON MARTIN
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

RON MARTIN (Continued) **1025840351**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-06-27 14:20:04.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RON MARTIN
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	456 WOODAWN AVE
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	916-385-4342
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RON MARTIN
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	456 WOODAWN AVE
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	916-385-4342
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

RON MARTIN (Continued) **1025840351**

Historic Generators:
- Receive Date: 2019-06-17 00:00:00.0
- Handler Name: RON MARTIN
- Federal Waste Generator Description: Not a generator, verified
- State District Owner: Not reported
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Code: 56299
- NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

I49 **WILLIAM D. EVANS STERNWHEELER** **RCRA NonGen / NLR** **1026049612**
West **996 G. STREET** **CAC003056384**
1/8-1/4 **CHULA VISTA, CA 91911**
0.241 mi.
1271 ft. **Site 9 of 10 in cluster I**

Relative: **Higher**
Actual: **12 ft.**

RCRA NonGen / NLR:
- Date Form Received by Agency: 2020-02-18 00:00:00.0
- Handler Name: WILLIAM D. EVANS STERNWHEELER
- Handler Address: 996 G. STREET
- Handler City,State,Zip: CHULA VISTA, CA 91911
- EPA ID: CAC003056384
- Contact Name: BAHIA RESORT HOTEL
- Contact Address: 998 W. MISSIN BAY DR.
- Contact City,State,Zip: SAN DIEGO, CA 92109
- Contact Telephone: 858-488-0551
- Contact Fax: Not reported
- Contact Email: JLE@NRCC.COM
- Contact Title: Not reported
- EPA Region: 09
- Land Type: Not reported
- Federal Waste Generator Description: Not a generator, verified
- Non-Notifier: Not reported
- Biennial Report Cycle: Not reported
- Accessibility: Not reported
- Active Site Indicator: Not reported
- State District Owner: Not reported
- State District: Not reported
- Mailing Address: 998 W. MISSIN BAY DR.
- Mailing City,State,Zip: SAN DIEGO, CA 92109
- Owner Name: BAHIA RESORT HOTEL

WILLIAM D. EVANS STERNWHEELER (Continued) **1026049612**

Owner Type:	Other
Operator Name:	BAHIA RESORT HOTEL
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-03-06 18:10:54.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

WILLIAM D. EVANS STERNWHEELER (Continued) **1026049612**

Sub-Part P Indicator: No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BAHIA RESORT HOTEL
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	998 W. MISSIN BAY DR.
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92109
Owner/Operator Telephone:	858-488-0551
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	BAHIA RESORT HOTEL
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	998 W. MISSIN BAY DR.
Owner/Operator City,State,Zip:	SAN DIEGO, CA 92109
Owner/Operator Telephone:	858-488-0551
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-02-18 00:00:00.0
Handler Name:	WILLIAM D. EVANS STERNWHEELER
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	48423
NAICS Description:	SPECIALIZED FREIGHT (EXCEPT USED GOODS) TRUCKING, LONG-DISTANCE

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

I50 **SC COMMERCIAL** **RCRA NonGen / NLR** **1026049326**
West **996 G. ST** **CAC003056061**
1/8-1/4 **CHULA VISTA, CA 91910**
0.241 mi.
1271 ft. **Site 10 of 10 in cluster I**

Relative: **Higher**

Actual: **12 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-02-14 00:00:00.0
Handler Name:	SC COMMERCIAL	
Handler Address:		996 G. ST
Handler City,State,Zip:		CHULA VISTA, CA 91910
EPA ID:		CAC003056061
Contact Name:		CHAD MYERS
Contact Address:		145 VERNON WAY
Contact City,State,Zip:		EL CAJON, CA 92020
Contact Telephone:		619-520-8752
Contact Fax:		Not reported
Contact Email:		JLE@NRCC.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		145 VERNON WAY
Mailing City,State,Zip:		EL CAJON, CA 92020
Owner Name:		SC COMMERCIAL
Owner Type:		Other
Operator Name:		CHAD MYERS
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

SC COMMERCIAL (Continued) **1026049326**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-03-06 18:10:49.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SC COMMERCIAL
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	145 VERNON WAY
Owner/Operator City,State,Zip:	EL CAJON, CA 92020
Owner/Operator Telephone:	619-520-8752
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CHAD MYERS
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	145 VERNON WAY
Owner/Operator City,State,Zip:	EL CAJON, CA 92020
Owner/Operator Telephone:	619-520-8752
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SC COMMERCIAL (Continued) **1026049326**

Historic Generators:
Receive Date: 2020-02-14 00:00:00.0
Handler Name: SC COMMERCIAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 48423
NAICS Description: SPECIALIZED FREIGHT (EXCEPT USED GOODS) TRUCKING, LONG-DISTANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

51 **WILLIAM KEMERY** **RCRA NonGen / NLR** **1026042915**
ENE **415 WOODLAWN AVE** **CAC003049111**
1/8-1/4 **CHULA VISTA, CA 91910**
0.242 mi.
1280 ft.

Relative:
Higher

Actual:
32 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 2020-01-02 00:00:00.0
Handler Name: WILLIAM KEMERY
Handler Address: 415 WOODLAWN AVE
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAC003049111
Contact Name: WILLIAM KEMERY
Contact Address: 9503 AMSTER DR
Contact City,State,Zip: SANTEE, CA 92071-2765
Contact Telephone: 619-258-2556
Contact Fax: Not reported
Contact Email: DANIELLEECKES@ALLIANCE-ENVIRO.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Not reported
State District: Not reported
Mailing Address: 9503 AMSTER DR
Mailing City,State,Zip: SANTEE, CA 92071-2765
Owner Name: WILLIAM KEMERY

WILLIAM KEMERY (Continued) **1026042915**

Owner Type:	Other
Operator Name:	WILLIAM KEMERY
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-02-10 17:51:59.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

WILLIAM KEMERY (Continued) **1026042915**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: WILLIAM KEMERY
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9503 AMSTER DR
Owner/Operator City,State,Zip: SANTEE, CA 92071-2765
Owner/Operator Telephone: 619-258-2556
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WILLIAM KEMERY
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 9503 AMSTER DR
Owner/Operator City,State,Zip: SANTEE, CA 92071-2765
Owner/Operator Telephone: 619-258-2556
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2020-01-02 00:00:00.0
Handler Name: WILLIAM KEMERY
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

J52 **RADOS, CHULA VISTA CITY, REDEVELOP.** **SAN DIEGO CO. SAM** **S108407197**
North **798 F ST** **CPS-SLIC** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **CERS**
0.243 mi.
1285 ft. **Site 1 of 3 in cluster J**

Relative:
Higher

Actual:
25 ft.

SAN DIEGO CO. SAM:

Name:	RADOS, CHULA VISTA CITY, REDEVELOP.
Address:	798 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H39651-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	Soils Only
Facility Status:	Closed Case
Date:	12/14/2004
Date Began:	Not reported

Name:	RADOS, CHULA VISTA CITY, REDEVELOP.
Address:	798 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H39651-002
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	Soils Only
Facility Status:	Closed Case
Date:	2/16/2006
Date Began:	Not reported

CPS-SLIC:

Name:	RADOS, CHULA VISTA CITY, REDEVELOP.
Address:	798 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	02/16/2006
Global Id:	T06019719942
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H39651-002
Latitude:	32.635106
Longitude:	-117.099665
Case Type:	Cleanup Program Site
Case Worker:	NS
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Name:	RADOS, CHULA VISTA CITY, REDEVELOP.
Address:	798 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	12/14/2004
Global Id:	T06019723044

RADOS, CHULA VISTA CITY, REDEVELOP. (Continued) **S108407197**

Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H39651-001
Latitude:	32.63514879222
Longitude:	-117.099360791002
Case Type:	Cleanup Program Site
Case Worker:	NS
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Polychlorinated biphenyls (PCBs)
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	RADOS, CHULA VISTA CITY, REDEVELOP.
Address:	798 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	202408
CERS ID:	T06019723044
CERS Description:	Cleanup Program Site

Coordinates:

Site ID:	202408
Facility Name:	RADOS, CHULA VISTA CITY, REDEVELOP.
Env Int Type Code:	CPS
Program ID:	T06019719942
Coord Name:	Not reported
Ref Point Type Desc:	Unknown
Latitude:	32.635106
Longitude:	-117.099665

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	NASSER SIONIT - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Name:	RADOS, CHULA VISTA CITY, REDEVELOP.
Address:	798 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	202408
CERS ID:	T06019719942
CERS Description:	Cleanup Program Site

Coordinates:

Site ID:	202408
Facility Name:	RADOS, CHULA VISTA CITY, REDEVELOP.
Env Int Type Code:	CPS
Program ID:	T06019719942

RADOS, CHULA VISTA CITY, REDEVELOP. (Continued) **S108407197**

Coord Name: Not reported
Ref Point Type Desc: Unknown
Latitude: 32.635106
Longitude: -117.099665

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: NASSER SIONIT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

K53 **ROHR INC A COLLINS AEROSPACE CO** **RCRA-LQG** **1000351369**
NNW **850 LAGOON DR MAIL ZONE 1-C** **CHMIRS** **92010RHRNDFOOTO**
1/8-1/4 **CHULA VISTA, CA 91910** **TRIS**
0.248 mi. **PADS**
1312 ft. **Site 1 of 14 in cluster K** **ICIS**
US AIRS
Relative: Higher **FINDS**
ECHO
Actual: 12 ft.

RCRA-LQG:
Date Form Received by Agency: 2020-02-27 00:00:00.0
Handler Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Handler Address: 850 LAGOON DR
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAD008382053
Contact Name: RICK SIORDIA
Contact Address: LAGOON DR, MAILSTOP M24
Contact City,State,Zip: CHULA VISTA, CA 91910
Contact Telephone: 619-691-4279 x4279
Contact Fax: Not reported
Contact Email: RICK.SIORDIA@COLLINS.COM
Contact Title: SENIOR EH&S MANAGER
EPA Region: 09
Land Type: Private
Federal Waste Generator Description: Large Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: 2019
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: LAGOON DR, MAILSTOP M24
Mailing City,State,Zip: CHULA VISTA, CA 91910
Owner Name: UNITED TECHNOLOGIES CORPORATION
Owner Type: Private
Operator Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-09-30 18:51:47.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years

Year:	2017

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:
Year: 2011

Click Here for Biennial Reporting System Data:
Year: 2009

Click Here for Biennial Reporting System Data:
Year: 2007

Click Here for Biennial Reporting System Data:
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D003
Waste Description: REACTIVE WASTE

Waste Code: D004
Waste Description: ARSENIC

Waste Code: D005
Waste Description: BARIUM

Waste Code: D006
Waste Description: CADMIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D011
Waste Description: SILVER

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F006
Waste Description: WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS, EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC, AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Waste Code: F019
Waste Description: WASTEWATER TREATMENT SLUDGES FROM THE CHEMICAL CONVERSION COATING OF ALUMINUM, EXCEPT FROM ZIRCONIUM PHOSPHATING IN ALUMINUM CAN WASHING WHEN SUCH PHOSPHATING IS AN EXCLUSIVE CONVERSION COATING PROCESS.

Waste Code: LABP
Waste Description: LAB PACK

Waste Code: P012
Waste Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Waste Code: U080
Waste Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Waste Code: U134
Waste Description: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

Waste Code: U210
Waste Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Waste Code: U220
Waste Description: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U226
Waste Description: ETHANE, 1,1,1-TRICHLORO- (OR) METHYL CHLOROFORM

Waste Code: U228
Waste Description: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: ROHR INC., A UTC AEROSPACE SYSTEMS COMPANY
Legal Status: Private
Date Became Current: 1941-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 850 LAGOON DR
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910-2001
Owner/Operator Telephone: 619-691-4279
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: RICK.SIORDIA@UTAS.UTC.COM

Owner/Operator Indicator: Operator
Owner/Operator Name: GOODRICH
Legal Status: Private
Date Became Current: 1959-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROHR, INC
Legal Status: Private

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Date Became Current: 1945-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 850 LAGOON DRIVE
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ROHR, INC. DBA GOODRICH
Legal Status: Private
Date Became Current: 1945-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: UNITED TECHNOLOGIES CORPORATION
Legal Status: Private
Date Became Current: 2012-06-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 2730 WEST TYVOLA ROAD
Owner/Operator City,State,Zip: CHARLOTTE, NC 28217
Owner/Operator Telephone: 704-423-7000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: RICK.SIORDIA@UTAS.UTC.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: ROHR INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 850 LAGOON DR
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910-2098
Owner/Operator Telephone: 619-691-4111
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROHR INC.
Legal Status: Private
Date Became Current: 1941-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 850 LAGOON DRIVE MAIL ZONE 1-C EH&
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910
Owner/Operator Telephone: 619-691-4111
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROHR, INC A UNITED TECHNOLOGIES AEROSPAC
Legal Status:	Private
Date Became Current:	1941-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNITED TECHNOLOGIES CORPORATION
Legal Status:	Private
Date Became Current:	2012-06-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	2730 WEST TYVOLA ROAD
Owner/Operator City,State,Zip:	CHARLOTTE, NC 28217
Owner/Operator Telephone:	704-423-7000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	RICK.SIORDIA@UTAS.UTC.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROHR INC.
Legal Status:	Private
Date Became Current:	1941-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	850 LAGOON DRIVE
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-691-4111
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROHR INC. BDA GOODRICH
Legal Status:	Private
Date Became Current:	1941-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	850 LAGOON DRIVE MAIL ZONE 1-C EH&
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-691-4111
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROHR INC, A TECHNOLOGIES AEROSPACE SYSTM
Legal Status:	Private
Date Became Current:	1991-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	850 LAGOON AVE
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-691-4111
Owner/Operator Telephone Ext:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NOT REQUIRED
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, ME 99999
Owner/Operator Telephone: 415-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROHR INC.
Legal Status: Private
Date Became Current: 1941-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 850 LAGOON DR
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ROHR INC. DBA GOODRICH AEROSTRUCTURES
Legal Status: Private
Date Became Current: 1941-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROHR INC.
Legal Status: Private
Date Became Current: 1941-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 850 LAGOON DRIVE
Owner/Operator City,State,Zip: CHULA VISTA, CA 91910
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Legal Status: Private
Date Became Current: 1941-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 850 LAGOON DR

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-691-4279
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	RICK.SIORDIA@COLLINS.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROHR INC. DBA GOODRICH
Legal Status:	Private
Date Became Current:	1941-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROHR INC. DBA GOODRICH
Legal Status:	Private
Date Became Current:	1941-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROHR INC A UTC AEROSPACE SYSTEMS COMPANY
Legal Status:	Private
Date Became Current:	1941-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROHR INC A UTC AEROSPACE SYSTEMS COMPANY
Legal Status:	Private
Date Became Current:	1941-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	850 LAGOON DR
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-691-2588
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROHR INC. DBA GOODRICH
Legal Status:	Private

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Date Became Current: 1959-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2010-06-15 00:00:00.0
Handler Name: ROHR INC. DBA GOODRICH AEROSTRUCTURES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2012-03-02 00:00:00.0
Handler Name: ROHR INC. DBA GOODRICH AEROSTRUCTURES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2014-03-01 00:00:00.0
Handler Name: ROHR INC, A UNITED TECHNOLOGIES AEROSPACE SYSTEMS CO
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2016-05-18 00:00:00.0
Handler Name: ROHR INC A SUBSIDIARY OF UTC AEROSPACE SYSTEMS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2018-02-26 00:00:00.0
Handler Name: ROHR INC DBA GOODRICH AEROSTRUCTURES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 2020-02-27 00:00:00.0
Handler Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 1996-09-01 00:00:00.0
Handler Name: ROHR INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1980-08-12 00:00:00.0
Handler Name: ROHR INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Receive Date:	1998-01-26 00:00:00.0
Handler Name: ROHR INC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1990-04-11 00:00:00.0
Handler Name: ROHR INDUSTRIES INC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1992-03-02 00:00:00.0
Handler Name: ROHR, INC.	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1994-03-30 00:00:00.0
Handler Name: ROHR, INC	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1996-02-27 00:00:00.0
Handler Name: ROHR, INC.	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1999-03-04 00:00:00.0
Handler Name: ROHR, INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2000-10-12 00:00:00.0
Handler Name: BFGOODRICH AEROSTRUCTURES DBA ROHR INC.
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2002-02-28 00:00:00.0
Handler Name: ROHR INC. DBA GOODRICH AEROSTRUCTURES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2004-02-25 00:00:00.0
Handler Name: ROHR, INC. DBA GOODRICH
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2006-01-18 00:00:00.0
Handler Name: ROHR INC. DBA GOODRICH AEROSTRUCTURES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2008-02-07 00:00:00.0
Handler Name: ROHR INC. DBA GOODRICH AEROSTRUCTURES
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 336412
NAICS Description: AIRCRAFT ENGINE AND ENGINE PARTS MANUFACTURING

NAICS Code: 336413
NAICS Description: OTHER AIRCRAFT PARTS AND AUXILIARY EQUIPMENT MANUFACTURING

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 1984-06-25 00:00:00.0
Actual Return to Compliance Date: 1985-06-10 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 1985-05-31 00:00:00.0
Enforcement Identifier: 001
Date of Enforcement Action: 1985-05-01 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R9STA
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	2006-06-26 00:00:00.0
Actual Return to Compliance Date:	2006-07-14 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	501
Date of Enforcement Action:	2006-06-26 00:00:00.0
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 2004-04-14 00:00:00.0
Actual Return to Compliance Date: 2004-04-14 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Evaluation Action Summary:

Evaluation Date:	1984-06-25 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	1985-06-10 00:00:00.0
Scheduled Compliance Date:	1985-05-31 00:00:00.0
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	2010-06-10 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	2015-11-05 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	2006-06-26 00:00:00.0
Evaluation Responsible Agency:	Local
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	2006-07-14 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	2013-08-12 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	1985-06-10 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE SCHEDULE EVALUATION
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	2018-04-27 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	2004-04-14 00:00:00.0
Evaluation Responsible Agency:	State Contractor/Grantee
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	2004-04-14 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

CHMIRS:

Name:	Not reported
Address:	FOOT OF H STREET
City,State,Zip:	CHULA VISTA, CA 91912
OES Incident Number:	6508
OES notification:	Not reported
OES Date:	1/13/1993
OES Time:	02:16:00 PM

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	rohr inc.
Containment:	Not reported
What Happened:	Not reported
Type:	PETROLEUM
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1993
Agency:	rohr inc
Incident Date:	1200
Admin Agency:	Not reported
Amount:	1/2-1 gal 1/4-1/2 gal
Contained:	Not reported
Site Type:	IND PLT
E Date:	Not reported
Substance:	breacoat oil deliminate/water
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	UNKNOWN
Number of Injuries:	UNKNOWN
Number of Fatalities:	UNKNOWN
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	transfer pump plugged, stream cleaning pump kicked in causing above substance to the soil

Facility, Chemical, Releases and Other Waste Management Summary Information:

TRI ID:	92010RHRNDFOOTO
Form Type:	Form R
Reporting year:	2018
Trade secret indicator:	NO
Sanitized indicator:	NO
Title of certifying official:	OPERATIONS MANAGER THOMAS MARQUIS
Certifying officials signature indicator:	ELECTRONIC
Date signed:	2019-06-20
Name:	ROHR INC A COLLINS AEROSPACE CO
Address:	850 LAGOON DR MAIL ZONE 1-C
City,State,Zip:	CHULA VISTA, CA 91910
BIA code:	Not reported
Tribe name:	Not reported
Mailing name:	ROHR INC A COLLINS AEROSPACE CO
Mailing street:	850 LAGOON DR MAIL ZONE 1-C
Mailing province:	Not reported
Mailing City,State,Zip:	CHULA VISTA, CA 91910
Entire facility ind:	YES
Partial facility ind:	NO
Federal facility ind:	NO
Goco facility ind:	NO
Assigned fed facility flag:	NO
Public contact name:	RICK SIORDIA
Public contact phone and Ext:	6196914279
Public contact email:	RICK.SIORDIA@UTAS.UTC.COM
Primary sic code:	Not reported
Sic code 2:	Not reported
Sic code 3:	Not reported
Sic code 4:	Not reported
Sic code 5:	Not reported
Sic code 6:	Not reported
Naics origin:	Not reported
Primary naics code:	336413
Naics code 2:	Not reported
Naics code 3:	Not reported
Naics code 4:	Not reported
Naics code 5:	Not reported
Naics code 6:	Not reported
Latitude:	32.635103
Longitude:	-117.101893
D and B number A:	008382053
D and B number B:	Not reported
RCRA number A:	CAD008382053
RCRA number B:	Not reported
RCRA number C:	Not reported
RCRA number D:	Not reported
RCRA number E:	Not reported
RCRA number F:	Not reported
RCRA number G:	Not reported
RCRA number H:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

NPDES number A:	Not reported
NPDES number B:	Not reported
NPDES number C:	Not reported
NPDES number D:	Not reported
NPDES number E:	Not reported
NPDES number F:	Not reported
NPDES number G:	Not reported
Parent company name:	UNITED TECHNOLOGIES CORP
Parent company D and B number:	001344142
Standardized parent company name:	UNITED TECHNOLOGIES CORP
Document control number:	1318216991784
TRI ID:	92010RHRNDFOOTO
Cas number:	N090
Chemical name:	CHROMIUM COMPOUNDS(EXCEPT CHROMITE ORE MINED IN THE TRANSVAAL REGION)
Classification:	TRI
Unit of measure:	Pounds
Metal ind:	YES
Revision code 1:	Not reported
Revision code 2:	Not reported
Maximum amount on site:	03
Fugitive air emissions - total release pounds:	0
Fugitive air emissions - total release range code:	Not reported
Total fugitive air emissions:	0
Fugitive air emissions - basis of estimate:	Other
Stack air emissions - release pounds:	.14
Stack air emissions - release range code:	Not reported
Total stack air emissions:	.14
Stack air emissions - basis of estimate:	Other
Total air emissions:	.14
Discharges to stream a - stream name:	SAN DIEGO BAY
Total discharges to stream a:	.1
Discharges to stream a - basis of estimate:	Periodic/Random Monotoning Data
Discharges to stream a - % from stormwater:	100
Discharges to stream b - stream name:	Not reported
Total discharges to stream b:	Not reported
Discharges to stream b - basis of estimate:	Not reported
Discharges to stream b - % from stormwater:	Not reported
Discharges to stream c - stream name:	Not reported
Total discharges to stream c:	Not reported
Discharges to stream c - basis of estimate:	Not reported
Discharges to stream c - % from stormwater:	Not reported
Discharges to stream d - stream name:	Not reported
Total discharges to stream d:	Not reported
Discharges to stream d - basis of estimate:	Not reported
Discharges to stream d - % from stormwater:	Not reported
Discharges to stream e - stream name:	Not reported
Total discharges to stream e:	Not reported
Discharges to stream e - basis of estimate:	Not reported
Discharges to stream e - % from stormwater:	Not reported
Discharges to stream f - stream name:	Not reported
Total discharges to stream f:	Not reported
Discharges to stream f - basis of estimate:	Not reported
Discharges to stream f - % from stormwater:	Not reported
Discharges to stream g - stream name:	Not reported
Total discharges to stream g:	Not reported
Discharges to stream g - basis of estimate:	Not reported
Discharges to stream g - % from stormwater:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Total number of receiving streams:	1
Total surface water discharge:	.1
Total on-site underground inj - pounds:	Not reported
On-site underground inj - basis of estimate:	Not reported
Total on-site ugrnd inj to cl i wells - pounds:	0
On-site underground inj to c1 i wells - basis of estimate:	Not reported
Total on-site ugrnd inj to cl ii-v wells - pounds:	0
On-site ungrnd inj to cl ii-v wells - basis of estimate:	Not reported
Total on-site underground injection:	0
Total on-site landfills:	Not reported
On-site landfills - basis of estimate:	Not reported
Total on-site RCRA subtitle c landfills:	0
On-site RCRA subtitle c landfills - basis of estimate:	Not reported
Total other on-site landfills:	0
Other landfills - basis of estimate:	Not reported
Total on-site land treatment:	0
Land trtmt/appl farming - basis of estimate:	Not reported
Total surface impoundments:	Not reported
Surface impoundment - basis of estimate:	Not reported
Total RCRA c surface impoundments:	0
RCRA c Surface impoundment - basis of estimate:	Not reported
Total other surface impoundments:	0
Other surface impoundment - basis of estimate:	Not reported
Total other disposal:	0
Other disposal - basis of estimate:	Not reported
Total on-site land releases:	0
Total on-site releases:	.24
Off-site - POTW releases:	2
Off-site - storage only:	0
Off-site - solid/stab - metals:	0
Off-site - wastewater treatment release - metals:	0
Off-site - solid/stab - release - metals:	0
Off-site - wastewater treatment - metals:	0
Off-site - underground injection:	0
Off-site - underground injection - class 1 wells:	0
Off-site - underground injection - class ii-v wells:	0
Off-site - landfills/disposal surface impoundments:	0
Off-site - surface impoundment:	0
Off-site - RCRA subtitle c surface impoundments:	0
Off-site - other surface impoundments:	0
Off-site - other landfills:	0
Off-site - RCRA subtitle c landfills:	21648
Off-site - disposal - land treatment:	0
Off-site - disposal - other land disposal:	0
Off-site - disposal - other off-site management:	0
Off-site - disposal - transfer to waste broker:	74
Off-site - disposal - unknown:	221.1
Total transferred off site for disposal:	21945.1
Off-site - recycling - solvents/organics recovery:	0
Off-site - recycling -metals recovery:	4902.7
Off-site - recycling - other reuse or recovery:	0
Off-site - recycling - acid regeneration:	0
Off-site - recycling - transfer to waste broker:	2300
Total transferred off site for recycling:	7202.7
Off-site - energy recovery:	0
Off-site - transfer to waste broker for energy recovery:	0
Total transferred off site for energy recovery:	0

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Off-site - POTW treatment:	0
Off-site - solid/stab treatment - non metals:	0
Off-site -incineration/thermal treatment:	0
Off-site - incineration/insignificant heat value:	0
Off-site - wastewater treatment - non-metals:	0
Off-site - other waste treatment:	0
Off-site - transfer to waste broker - waste treatment:	0
Total transferred off site for treatment:	0
Off-site - transfer to waste broker:	0
Total transferred off site for further waste management:	29145.8
Total POTW transfer:	2
Energy recovery on site current year:	0
Recycled on site current year:	0
Treated on site current year:	0
Total on-site waste management:	0
On-site energy recovery method 1:	Not Applicable
On-site energy recovery method 2:	Not reported
On-site energy recovery method 3:	Not Applicable
On-site energy recovery method 4:	Not reported
On-site recycling processes method 1:	Not Applicable
On-site recycling processes method 2:	Not reported
On-site recycling processes method 3:	Not reported
On-site recycling processes method 4:	Not reported
On-site recycling processes method 5:	Not reported
On-site recycling processes method 6:	Not reported
On-site recycling processes method 7:	Not reported
FRS Facility ID:	110000478518
Elemental Metal Included:	NO
Waste Rock Pile managed Indicator:	0
Waste Rock Quantity:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	2

Chemical Activities and Uses:

Cas number:	N090
Document control number:	1318216991784
Chemical name:	CHROMIUM COMPOUNDS(EXCEPT CHROMITE ORE MINED IN THE TRANSVAAL REGION)
Classification:	TRI
Unit of measure:	Pounds
Produce the chemical:	No
Import the chemical:	No
On-site use of the chemical:	No
Sale or distribution of the chemical:	No
As a byproduct:	No
As a manufactured impurity:	No
Used as a reactant:	No
P101 feedstocks:	No
P102 raw materials:	No
P103 intermediates:	No
P104 initiators:	No
P199 other:	No
Added as a formulation component:	No
P201 additives:	No
P202 dyes:	No
P203 reaction diluents:	No
P204 initiators:	No
P205 solvents:	No
P206 inhibitors:	No

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

P207 emulsifiers:	No
P208 surfactants:	No
P209 lubricants:	No
P210 flame retardants:	No
P211 rheological modifiers:	No
P299 other:	No
Used as an article component:	No
Repackaging:	No
As a process impurity:	No
Processed / recycling:	No
Used as a chemical processing aid:	No
Z101 process solvents:	No
Z102 catalysts:	No
Z103 inhibitors:	No
Z104 initiators:	No
Z105 reaction terminators:	No
Z106 solution buffers:	No
Z199 other:	No
Used as a manufacturing aid:	Yes
Z201 process lubricants:	No
Z202 metalworking fluids:	No
Z203 coolants:	No
Z204 refrigerants:	No
Z205 hydraulic fluids:	No
Z299 other:	No
Ancillary or other use:	Yes
Z301 cleaner:	No
Z302 degreaser:	No
Z303 lubricant:	No
Z304 fuel:	No
Z305 flame retardant:	No
Z306 waste treatment:	No
Z307 water treatment:	No
Z308 construction materials:	No
Z399 other:	No

Submitted Facility Name:	ROHR INC A UTC AEROSPACE SYSTEMS CO
Submitted Street:	850 LAGOON DR MAIL ZONE 1-C
Submitted City:	CHULA VISTA
Submitted County:	SAN DIEGO
Submitted State:	CA
Submitted Zip Code:	91910
Submitted BIA Code:	Not reported
Submitted Tribe Name:	Not reported
Submitted Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Parent Company DB Number:	001344142
Submitted Standardized Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Primary NAICS Code:	336413
Submitted Industry Code:	336
Submitted Industry Name:	Transportation Equipment
Industry Code:	336
Industry Name:	Transportation Equipment
Last year the facility reported:	2019
First year the facility reported:	1987
Number of forms submitted:	5
Total number of forms submitted:	272 20200808

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Detailed Source Reduction Activities and Methods:

Cas number:	N090
Document control number:	1318216991784
Chemical name:	CHROMIUM COMPOUNDS(EXCEPT CHROMITE ORE MINED IN THE TRANSVAAL REGION)
Classification:	TRI
Unit of measure:	Pounds
On-site limited releases - prior year:	0
On-site limited releases - current year:	0
On-site limited releases - following year:	0
On-site limited releases - 2nd-following year:	0
Other on-site releases - prior year:	.7
Other on-site releases - current year:	.24
Other on-site releases - following year:	.2
Other on-site releases - 2nd-following year:	.2
Off-site limited releases - prior year:	830
Off-site limited releases - current year:	270
Off-site limited releases - following year:	260
Off-site limited releases - 2nd-following year:	250
Other off-site releases - previous year:	3300
Other off-site releases - current year:	300
Other off-site releases - following year:	290
Other off-site releases - 2nd-following year:	280
Energy recovery on site prior year:	0
Energy recovery on site current year:	0
Energy recovery on site following year:	0
Energy recovery on site 2nd-following year:	0
Energy recovery off site prior year:	0
Energy recovery off site current year:	0
Energy recovery off site following year:	0
Energy recovery off site 2nd-following year:	0
Quantity recycled on site prior year:	0
Quantity recycled on site current year:	0
Quantity recycled on site following year:	0
Quantity recycled on site 2nd-following year:	0
Quantity recycled off site prior year:	5100
Quantity recycled off site current year:	7200
Quantity recycled off site following year:	6900
Quantity recycled off site 2nd-following year:	6600
Quantity treated on site prior year:	0
Quantity treated on site current year:	0
Quantity treated on site following year:	0
Quantity treated on site 2nd-following year:	0
Quantity treated off site prior year:	0
Quantity treated off site current year:	0
Quantity treated off site following year:	0
Quantity treated off site 2nd-following year:	0
Catastrophic releases or other one-time events:	21000
Prod ratio/activity index:	.96
Prod ratio or activity:	ACTIVITY
1st SR reduction activity:	NA-NA
1st SR activity ID meth code and desc 1:	Not reported
1st SR activity ID meth code and desc 2:	Not reported
1st SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 1st source REDN act code and desc:	Not reported
2nd SR activity code and desc:	Not reported
2nd SR activity ID meth code and desc 1:	Not reported
2nd SR activity ID meth code and desc 2:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

2nd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 2nd source REDN act code and desc:	Not reported
3rd SR activity code and desc:	Not reported
3rd SR activity ID meth code and desc 1:	Not reported
3rd SR activity ID meth code and desc 2:	Not reported
3rd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 3rd source REDN act code and desc:	Not reported
4th SR activity code and desc:	Not reported
4th SR activity ID meth code and desc 1:	Not reported
4th SR activity ID meth code and desc 2:	Not reported
4th SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 4th source REDN act code and desc:	Not reported

Detailed On-site Waste Treatment Methods and Efficiency:

Cas number:	N090
Document control number:	1318216991784
Chemical name:	CHROMIUM COMPOUNDS(EXCEPT CHROMITE ORE MINED IN THE TRANSVAAL REGION)
Classification:	TRI
Unit of measure:	Pounds
Stream 1 - waste stream code:	Wastewater (aqueous waste)
Stream 1 - trtmt method - sequence 1:	Chemical reduction with or without precipitation
Stream 1 - trtmt method - sequence 2:	Sludge treatment and/or dewatering
Stream 1 - trtmt method - sequence 3:	Settling or clarification
Stream 1 - trtmt method - sequence 4:	Other treatment
Stream 1 - trtmt method - sequence 5:	Not reported
Stream 1 - trtmt method - sequence 6:	Not reported
Stream 1 - trtmt method - sequence 7:	Not reported
Stream 1 - trtmt method - sequence 8:	Not reported
Stream 1 - based on operating data:	NO
Stream 2 - waste stream code:	Not reported
Stream 2 - trtmt method - sequence 1:	Not reported
Stream 2 - trtmt method - sequence 2:	Not reported
Stream 2 - trtmt method - sequence 3:	Not reported
Stream 2 - trtmt method - sequence 4:	Not reported
Stream 2 - trtmt method - sequence 5:	Not reported
Stream 2 - trtmt method - sequence 6:	Not reported
Stream 2 - trtmt method - sequence 7:	Not reported
Stream 2 - trtmt method - sequence 8:	Not reported
Stream 2 - based on operating data:	Not reported
Stream 3 - waste stream code:	Not reported
Stream 3 - trtmt method - sequence 1:	Not reported
Stream 3 - trtmt method - sequence 2:	Not reported
Stream 3 - trtmt method - sequence 3:	Not reported
Stream 3 - trtmt method - sequence 4:	Not reported
Stream 3 - trtmt method - sequence 5:	Not reported
Stream 3 - trtmt method - sequence 6:	Not reported
Stream 3 - trtmt method - sequence 7:	Not reported
Stream 3 - trtmt method - sequence 8:	Not reported
Stream 3 - based on operating data:	Not reported
Stream 4 - waste stream code:	Not reported
Stream 4 - trtmt method - sequence 1:	Not reported
Stream 4 - trtmt method - sequence 2:	Not reported
Stream 4 - trtmt method - sequence 3:	Not reported
Stream 4 - trtmt method - sequence 4:	Not reported
Stream 4 - trtmt method - sequence 5:	Not reported
Stream 4 - trtmt method - sequence 6:	Not reported
Stream 4 - trtmt method - sequence 7:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Stream 4 - trtmt method - sequence 8:	Not reported
Stream 4 - based on operating data:	Not reported
Stream 5 - waste stream code:	Not reported
Stream 5 - trtmt method - sequence 1:	Not reported
Stream 5 - trtmt method - sequence 2:	Not reported
Stream 5 - trtmt method - sequence 3:	Not reported
Stream 5 - trtmt method - sequence 4:	Not reported
Stream 5 - trtmt method - sequence 5:	Not reported
Stream 5 - trtmt method - sequence 6:	Not reported
Stream 5 - trtmt method - sequence 7:	Not reported
Stream 5 - trtmt method - sequence 8:	Not reported
Stream 5 - based on operating data:	Not reported

Details of Off-site Transfers:

Cas number:	N090
Document control number:	1318216991784
Chemical name:	CHROMIUM COMPOUNDS(EXCEPT CHROMITE ORE MINED IN THE TRANSVAAL REGION)
Classification:	TRI
Offsite RCRA id nr:	ARD981057870
Offsite transfer sequence number:	2
Offsite name:	RINECO CHEMICAL INDUSTRIES, INC
Offsite street address:	1007 VULCAN ROAD
Offsite City,State,Zip:	BENTON, AR 72015
Offsite county:	SALINE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	220
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	220
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	ARD981057870
Offsite transfer sequence number:	2
Offsite name:	RINECO CHEMICAL INDUSTRIES, INC
Offsite street address:	1007 VULCAN ROAD
Offsite City,State,Zip:	BENTON, AR 72015
Offsite county:	SALINE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite TRF to WST broker for DSP m94 LBS:	74
Offsite TRF to WST broker for DSP m94 BOE:	Other
Total amount transferred offsite for disposal:	74
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	UTD981552177
Offsite transfer sequence number:	3
Offsite name:	CLEAN HARBORS ARAGONITE, LLC

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Offsite street address:	11600 N APTUS ROAD
Offsite City,State,Zip:	ARAGONITE, UT 84029
Offsite county:	TOOELE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	660
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	660
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	110000906985

Offsite RCRA id nr:	CAD980675276
Offsite transfer sequence number:	4
Offsite name:	CLEAN HARBORS BUTTONWILLOW LLC
Offsite street address:	2500 WEST LOKERN
Offsite City,State,Zip:	BUTTONWILLOW, CA 932060000
Offsite county:	KERN
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	20000
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	20000
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	110000500912

Offsite RCRA id nr:	UTD991301748
Offsite transfer sequence number:	5
Offsite name:	CLEAN HARBORS GRASSY MOUNTAIN
Offsite street address:	3 MILES EAST, 7 MILES NROTH KNOL
Offsite City,State,Zip:	KNOLLS, UT 84029
Offsite county:	TOOELE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	690
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	690
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	110013709754

Offsite RCRA id nr:	CAT080013352
Offsite transfer sequence number:	6
Offsite name:	DEMENNO KERDOON
Offsite street address:	2000 N ALAMEDA STREET
Offsite City,State,Zip:	COMPTON, CA 90222
Offsite county:	LOS ANGELES

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Total amount transferred offsite for disposal:	0
Offsite metals recovery m24 LBS:	2.7
Offsite metals recovery m24 BOE:	Other
Total amount transferred offsite for recycling:	2.7
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	CAT080013352
Offsite transfer sequence number:	6
Offsite name:	DEMENNO KERDOON
Offsite street address:	2000 N ALAMEDA STREET
Offsite City,State,Zip:	COMPTON, CA 90222
Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	.3
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	.3
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	OHD980613541
Offsite transfer sequence number:	7
Offsite name:	HERITAGE THERMAL SERVICES INC
Offsite street address:	1250 SAINT GEORGE ST
Offsite City,State,Zip:	EAST LIVERPOOL, OH 43920
Offsite county:	COLUMBIANA
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	.8
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	.8
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	110027242320

Offsite RCRA id nr:	CAD981450349
Offsite transfer sequence number:	8
Offsite name:	JACK ENGLE & CO
Offsite street address:	8440 S. ALAMEDA STREET
Offsite City,State,Zip:	LOS ANGELES, CA 90001
Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Unit of measure:	Pounds
Total amount transferred offsite for disposal:	0
Offsite TRF to WST broker for recycl m93 LBS:	2300
Offsite TRF to WST broker for recycl m93 BOE:	Other
Total amount transferred offsite for recycling:	2300
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported
Offsite RCRA id nr:	NVT330010000
Offsite transfer sequence number:	9
Offsite name:	US ECOLOGY NEVADA INC
Offsite street address:	HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:	BEATTY, NV 89003
Offsite county:	NYE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	298
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	298
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported
Offsite RCRA id nr:	NVT330010000
Offsite transfer sequence number:	9
Offsite name:	US ECOLOGY NEVADA INC
Offsite street address:	HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:	BEATTY, NV 89003
Offsite county:	NYE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Total amount transferred offsite for disposal:	0
Offsite metals recovery m24 LBS:	4900
Offsite metals recovery m24 BOE:	Other
Total amount transferred offsite for recycling:	4900
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Details of Transfers to Publicly Owned Treatment Works:

Cas number:	N090
Document control number:	1318216991784
Chemical name:	CHROMIUM COMPOUNDS(EXCEPT CHROMITE ORE MINED IN THE TRANSVAAL REGION)
Classification:	TRI
Unit of measure:	Pounds
POTW name:	POINT LOMA WASTEWATER TREATMENT PLANT
POTW address:	1902 GATCHELL ROAD
POTW City,State,Zip:	SAN DIEGO, CA 92106
POTW county:	SAN DIEGO
Quantity transferred:	2
Basis of estimate:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Discharges to water streams:	0
Discharges to water streams - basis of estimate:	Not reported
Discharges to other activities:	0
Discharges to other activities - basis of estimate:	Not reported
Released to air:	0
Released to air - basis of estimate:	Not reported
Sludge to disposal:	0
Sludge to disposal - basis of estimate:	Not reported
Sludge to incineration - metals:	0
Sludge to incineration - metals - basis of estimate:	Not reported
Sludge to agricultural applications:	0
Sludge to agricultural applications - basis of estimate:	Not reported
Other or unknown disposal:	2
Other or unknown disposal - basis of estimate:	Periodic/Random Monotoning Data
Other or unknown treatment:	0
Other or unknown treatment - basis of estimate:	Not reported
Sludge to incineration - nonmetals:	0
Sludge to incineration - nonmetals - basis of estimate:	Not reported
Total treated:	0
POTW Registry ID:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	2
Off Site - POTW Releases:	2
Experimental and Est. Treatment:	0
Experimental and Est. Treatment - Basis of Est.:	Not reported

TRI ID:		92010RHRNDFOOTO
Cas number:		007440508
Chemical name:	COPPER	
Classification:		TRI
Unit of measure:		Pounds
Metal ind:		YES
Revision code 1:		Not reported
Revision code 2:		Not reported
Maximum amount on site:		04
Fugitive air emissions - total release pounds:		0
Fugitive air emissions - total release range code:		Not reported
Total fugitive air emissions:		0
Fugitive air emissions - basis of estimate:		Other
Stack air emissions - release pounds:		.6
Stack air emissions - release range code:		Not reported
Total stack air emissions:		.6
Stack air emissions - basis of estimate:		Other
Total air emissions:		.6
Discharges to stream a - stream name:		SAN DIEGO BAY
Total discharges to stream a:		8.6
Discharges to stream a - basis of estimate:		Periodic/Random Monotoning Data
Discharges to stream a - % from stormwater:		100
Discharges to stream b - stream name:		Not reported
Total discharges to stream b:		Not reported
Discharges to stream b - basis of estimate:		Not reported
Discharges to stream b - % from stormwater:		Not reported
Discharges to stream c - stream name:		Not reported
Total discharges to stream c:		Not reported
Discharges to stream c - basis of estimate:		Not reported
Discharges to stream c - % from stormwater:		Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Discharges to stream d - stream name:	Not reported
Total discharges to stream d:	Not reported
Discharges to stream d - basis of estimate:	Not reported
Discharges to stream d - % from stormwater:	Not reported
Discharges to stream e - stream name:	Not reported
Total discharges to stream e:	Not reported
Discharges to stream e - basis of estimate:	Not reported
Discharges to stream e - % from stormwater:	Not reported
Discharges to stream f - stream name:	Not reported
Total discharges to stream f:	Not reported
Discharges to stream f - basis of estimate:	Not reported
Discharges to stream f - % from stormwater:	Not reported
Discharges to stream g - stream name:	Not reported
Total discharges to stream g:	Not reported
Discharges to stream g - basis of estimate:	Not reported
Discharges to stream g - % from stormwater:	Not reported
Total number of receiving streams:	1
Total surface water discharge:	8.6
Total on-site underground inj - pounds:	Not reported
On-site underground inj - basis of estimate:	Not reported
Total on-site ugrnd inj to cl i wells - pounds:	0
On-site underground inj to c1 i wells - basis of estimate:	Not reported
Total on-site ugrnd inj to cl ii-v wells - pounds:	0
On-site ungrnd inj to cl ii-v wells - basis of estimate:	Not reported
Total on-site underground injection:	0
Total on-site landfills:	Not reported
On-site landfills - basis of estimate:	Not reported
Total on-site RCRA subtitle c landfills:	0
On-site RCRA subtitle c landfills - basis of estimate:	Not reported
Total other on-site landfills:	0
Other landfills - basis of estimate:	Not reported
Total on-site land treatment:	0
Land trtmt/appl farming - basis of estimate:	Not reported
Total surface impoundments:	Not reported
Surface impoundment - basis of estimate:	Not reported
Total RCRA c surface impoundments:	0
RCRA c Surface impoundment - basis of estimate:	Not reported
Total other surface impoundments:	0
Other surface impoundment - basis of estimate:	Not reported
Total other disposal:	0
Other disposal - basis of estimate:	Not reported
Total on-site land releases:	0
Total on-site releases:	9.2
Off-site - POTW releases:	2.4
Off-site - storage only:	0
Off-site - solid/stab - metals:	0
Off-site - wastewater treatment release - metals:	0
Off-site - solid/stab - release - metals:	0
Off-site - wastewater treatment - metals:	0
Off-site - underground injection:	0
Off-site - underground injection - class 1 wells:	0
Off-site - underground injection - class ii-v wells:	0
Off-site - landfills/disposal surface impoundments:	0
Off-site - surface impoundment:	0
Off-site - RCRA subtitle c surface impoundments:	0
Off-site - other surface impoundments:	0
Off-site - other landfills:	0

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Off-site - RCRA subtitle c landfills:	940
Off-site - disposal - land treatment:	0
Off-site - disposal - other land disposal:	0
Off-site - disposal - other off-site management:	0
Off-site - disposal - transfer to waste broker:	.4
Off-site - disposal - unknown:	37.4
Total transferred off site for disposal:	980.2
Off-site - recycling - solvents/organics recovery:	0
Off-site - recycling -metals recovery:	95
Off-site - recycling - other reuse or recovery:	0
Off-site - recycling - acid regeneration:	0
Off-site - recycling - transfer to waste broker:	20000
Total transferred off site for recycling:	20095
Off-site - energy recovery:	0
Off-site - transfer to waste broker for energy recovery:	0
Total transferred off site for energy recovery:	0
Off-site - POTW treatment:	0
Off-site - solid/stab treatment - non metals:	0
Off-site -incineration/thermal treatment:	0
Off-site - incineration/insignificant heat value:	0
Off-site - wastewater treatment - non-metals:	0
Off-site - other waste treatment:	0
Off-site - transfer to waste broker - waste treatment:	0
Total transferred off site for treatment:	0
Off-site - transfer to waste broker:	0
Total transferred off site for further waste management:	21072.8
Total POTW transfer:	2.4
Energy recovery on site current year:	0
Recycled on site current year:	0
Treated on site current year:	0
Total on-site waste management:	0
On-site energy recovery method 1:	Not Applicable
On-site energy recovery method 2:	Not reported
On-site energy recovery method 3:	Not Applicable
On-site energy recovery method 4:	Not reported
On-site recycling processes method 1:	Not Applicable
On-site recycling processes method 2:	Not reported
On-site recycling processes method 3:	Not reported
On-site recycling processes method 4:	Not reported
On-site recycling processes method 5:	Not reported
On-site recycling processes method 6:	Not reported
On-site recycling processes method 7:	Not reported
FRS Facility ID:	110000478518
Elemental Metal Included:	NO
Waste Rock Pile managed Indicator:	0
Waste Rock Quantity:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	2.4

Chemical Activities and Uses:

Cas number:		007440508
Document control number:		1318216991796
Chemical name:	COPPER	
Classification:		TRI
Unit of measure:		Pounds
Produce the chemical:		No
Import the chemical:		No
On-site use of the chemical:		No

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Sale or distribution of the chemical:	No
As a byproduct:	No
As a manufactured impurity:	No
Used as a reactant:	No
P101 feedstocks:	No
P102 raw materials:	No
P103 intermediates:	No
P104 initiators:	No
P199 other:	No
Added as a formulation component:	No
P201 additives:	No
P202 dyes:	No
P203 reaction diluents:	No
P204 initiators:	No
P205 solvents:	No
P206 inhibitors:	No
P207 emulsifiers:	No
P208 surfactants:	No
P209 lubricants:	No
P210 flame retardants:	No
P211 rheological modifiers:	No
P299 other:	No
Used as an article component:	Yes
Repackaging:	No
As a process impurity:	No
Processed / recycling:	No
Used as a chemical processing aid:	No
Z101 process solvents:	No
Z102 catalysts:	No
Z103 inhibitors:	No
Z104 initiators:	No
Z105 reaction terminators:	No
Z106 solution buffers:	No
Z199 other:	No
Used as a manufacturing aid:	No
Z201 process lubricants:	No
Z202 metalworking fluids:	No
Z203 coolants:	No
Z204 refrigerants:	No
Z205 hydraulic fluids:	No
Z299 other:	No
Ancillary or other use:	No
Z301 cleaner:	No
Z302 degreaser:	No
Z303 lubricant:	No
Z304 fuel:	No
Z305 flame retardant:	No
Z306 waste treatment:	No
Z307 water treatment:	No
Z308 construction materials:	No
Z399 other:	No

Submitted Facility Name:	ROHR INC A UTC AEROSPACE SYSTEMS CO
Submitted Street:	850 LAGOON DR MAIL ZONE 1-C
Submitted City:	CHULA VISTA
Submitted County:	SAN DIEGO
Submitted State:	CA

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Submitted Zip Code:	91910
Submitted BIA Code:	Not reported
Submitted Tribe Name:	Not reported
Submitted Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Parent Company DB Number:	001344142
Submitted Standardized Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Primary NAICS Code:	336413
Submitted Industry Code:	336
Submitted Industry Name:	Transportation Equipment
Industry Code:	336
Industry Name:	Transportation Equipment
Last year the facility reported:	2019
First year the facility reported:	1987
Number of forms submitted:	5
Total number of forms submitted:	272 20200808

Detailed Source Reduction Activities and Methods:

Cas number:	007440508
Document control number:	1318216991796
Chemical name: COPPER	
Classification:	TRI
Unit of measure:	Pounds
On-site limited releases - prior year:	0
On-site limited releases - current year:	0
On-site limited releases - following year:	0
On-site limited releases - 2nd-following year:	0
Other on-site releases - prior year:	3.6
Other on-site releases - current year:	9.2
Other on-site releases - following year:	8.9
Other on-site releases - 2nd-following year:	8.5
Off-site limited releases - prior year:	54
Off-site limited releases - current year:	710
Off-site limited releases - following year:	680
Off-site limited releases - 2nd-following year:	650
Other off-site releases - previous year:	120
Other off-site releases - current year:	40
Other off-site releases - following year:	38
Other off-site releases - 2nd-following year:	36
Energy recovery on site prior year:	0
Energy recovery on site current year:	0
Energy recovery on site following year:	0
Energy recovery on site 2nd-following year:	0
Energy recovery off site prior year:	0
Energy recovery off site current year:	0
Energy recovery off site following year:	0
Energy recovery off site 2nd-following year:	0
Quantity recycled on site prior year:	0
Quantity recycled on site current year:	0
Quantity recycled on site following year:	0
Quantity recycled on site 2nd-following year:	0
Quantity recycled off site prior year:	21000
Quantity recycled off site current year:	20000
Quantity recycled off site following year:	19000
Quantity recycled off site 2nd-following year:	18000
Quantity treated on site prior year:	0
Quantity treated on site current year:	0
Quantity treated on site following year:	0

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Quantity treated on site 2nd-following year:	0
Quantity treated off site prior year:	0
Quantity treated off site current year:	0
Quantity treated off site following year:	0
Quantity treated off site 2nd-following year:	0
Catastrophic releases or other one-time events:	230
Prod ratio/activity index:	.96
Prod ratio or activity:	ACTIVITY
1st SR reduction activity:	NA-NA
1st SR activity ID meth code and desc 1:	Not reported
1st SR activity ID meth code and desc 2:	Not reported
1st SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 1st source REDN act code and desc:	Not reported
2nd SR activity code and desc:	Not reported
2nd SR activity ID meth code and desc 1:	Not reported
2nd SR activity ID meth code and desc 2:	Not reported
2nd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 2nd source REDN act code and desc:	Not reported
3rd SR activity code and desc:	Not reported
3rd SR activity ID meth code and desc 1:	Not reported
3rd SR activity ID meth code and desc 2:	Not reported
3rd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 3rd source REDN act code and desc:	Not reported
4th SR activity code and desc:	Not reported
4th SR activity ID meth code and desc 1:	Not reported
4th SR activity ID meth code and desc 2:	Not reported
4th SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 4th source REDN act code and desc:	Not reported

Detailed On-site Waste Treatment Methods and Efficiency:

Cas number:	007440508
Document control number:	1318216991796
Chemical name: COPPER	
Classification:	TRI
Unit of measure:	Pounds
Stream 1 - waste stream code:	Wastewater (aqueous waste)
Stream 1 - trtmt method - sequence 1:	Other chemical precipitation with or without pre-treatment
Stream 1 - trtmt method - sequence 2:	Neutralization
Stream 1 - trtmt method - sequence 3:	Chemical reduction with or without precipitation
Stream 1 - trtmt method - sequence 4:	Settling or clarification
Stream 1 - trtmt method - sequence 5:	Sludge treatment and/or dewatering
Stream 1 - trtmt method - sequence 6:	Not reported
Stream 1 - trtmt method - sequence 7:	Not reported
Stream 1 - trtmt method - sequence 8:	Not reported
Stream 1 - based on operating data:	NO
Stream 2 - waste stream code:	Not reported
Stream 2 - trtmt method - sequence 1:	Not reported
Stream 2 - trtmt method - sequence 2:	Not reported
Stream 2 - trtmt method - sequence 3:	Not reported
Stream 2 - trtmt method - sequence 4:	Not reported
Stream 2 - trtmt method - sequence 5:	Not reported
Stream 2 - trtmt method - sequence 6:	Not reported
Stream 2 - trtmt method - sequence 7:	Not reported
Stream 2 - trtmt method - sequence 8:	Not reported
Stream 2 - based on operating data:	Not reported
Stream 3 - waste stream code:	Not reported
Stream 3 - trtmt method - sequence 1:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Stream 3 - trtmt method - sequence 2:	Not reported
Stream 3 - trtmt method - sequence 3:	Not reported
Stream 3 - trtmt method - sequence 4:	Not reported
Stream 3 - trtmt method - sequence 5:	Not reported
Stream 3 - trtmt method - sequence 6:	Not reported
Stream 3 - trtmt method - sequence 7:	Not reported
Stream 3 - trtmt method - sequence 8:	Not reported
Stream 3 - based on operating data:	Not reported
Stream 4 - waste stream code:	Not reported
Stream 4 - trtmt method - sequence 1:	Not reported
Stream 4 - trtmt method - sequence 2:	Not reported
Stream 4 - trtmt method - sequence 3:	Not reported
Stream 4 - trtmt method - sequence 4:	Not reported
Stream 4 - trtmt method - sequence 5:	Not reported
Stream 4 - trtmt method - sequence 6:	Not reported
Stream 4 - trtmt method - sequence 7:	Not reported
Stream 4 - trtmt method - sequence 8:	Not reported
Stream 4 - based on operating data:	Not reported
Stream 5 - waste stream code:	Not reported
Stream 5 - trtmt method - sequence 1:	Not reported
Stream 5 - trtmt method - sequence 2:	Not reported
Stream 5 - trtmt method - sequence 3:	Not reported
Stream 5 - trtmt method - sequence 4:	Not reported
Stream 5 - trtmt method - sequence 5:	Not reported
Stream 5 - trtmt method - sequence 6:	Not reported
Stream 5 - trtmt method - sequence 7:	Not reported
Stream 5 - trtmt method - sequence 8:	Not reported
Stream 5 - based on operating data:	Not reported

Details of Off-site Transfers:

Cas number:	007440508
Document control number:	1318216991796
Chemical name: COPPER	
Classification:	TRI
Offsite RCRA id nr:	CAT080013352
Offsite transfer sequence number:	2
Offsite name:	DEMENNO KERDOON
Offsite street address:	2000 N ALAMEDA STREET
Offsite City,State,Zip:	COMPTON, CA 90222
Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Total amount transferred offsite for disposal:	0
Offsite metals recovery m24 LBS:	95
Offsite metals recovery m24 BOE:	Other
Total amount transferred offsite for recycling:	95
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	CAT080013352
Offsite transfer sequence number:	2
Offsite name:	DEMENNO KERDOON
Offsite street address:	2000 N ALAMEDA STREET
Offsite City,State,Zip:	COMPTON, CA 90222

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	.3
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	.3
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	CAD981450349
Offsite transfer sequence number:	3
Offsite name:	JACK ENGLE & CO
Offsite street address:	8440 S. ALAMEDA STREET
Offsite City,State,Zip:	LOS ANGELES, CA 90001
Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Total amount transferred offsite for disposal:	0
Offsite TRF to WST broker for recycl m93 LBS:	20000
Offsite TRF to WST broker for recycl m93 BOE:	Other
Total amount transferred offsite for recycling:	20000
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	ARD981057870
Offsite transfer sequence number:	4
Offsite name:	RINECO CHEMICAL INDUSTRIES, INC
Offsite street address:	1007 VULCAN ROAD
Offsite City,State,Zip:	BENTON, AR 72015
Offsite county:	SALINE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite TRF to WST broker for DSP m94 LBS:	.4
Offsite TRF to WST broker for DSP m94 BOE:	Other
Total amount transferred offsite for disposal:	.4
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	ARD981057870
Offsite transfer sequence number:	4
Offsite name:	RINECO CHEMICAL INDUSTRIES, INC
Offsite street address:	1007 VULCAN ROAD
Offsite City,State,Zip:	BENTON, AR 72015
Offsite county:	SALINE
Offsite province:	Not reported
Offsite country id:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	36
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	36
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	NVT330010000
Offsite transfer sequence number:	5
Offsite name:	US ECOLOGY NEVADA INC
Offsite street address:	HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:	BEATTY, NV 89003
Offsite county:	NYE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	940
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	940
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	CAD097030993
Offsite transfer sequence number:	6
Offsite name:	US ECOLOGY VERNON, INC.
Offsite street address:	5375 SOUTH BOYLES AVENUE
Offsite City,State,Zip:	VERNON, CA 90058
Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	1.1
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	1.1
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Details of Transfers to Publicly Owned Treatment Works:

Cas number:	007440508
Document control number:	1318216991796
Chemical name: COPPER	
Classification:	TRI
Unit of measure:	Pounds
POTW name:	POINT LOMA WASTEWATER TREATMENT PLANT
POTW address:	1902 GATCHELL ROAD
POTW City,State,Zip:	SAN DIEGO, CA 92106
POTW county:	SAN DIEGO
Quantity transferred:	2.4

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Basis of estimate:	Not reported
Discharges to water streams:	0
Discharges to water streams - basis of estimate:	Not reported
Discharges to other activities:	0
Discharges to other activities - basis of estimate:	Not reported
Released to air:	0
Released to air - basis of estimate:	Not reported
Sludge to disposal:	0
Sludge to disposal - basis of estimate:	Not reported
Sludge to incineration - metals:	0
Sludge to incineration - metals - basis of estimate:	Not reported
Sludge to agricultural applications:	0
Sludge to agricultural applications - basis of estimate:	Not reported
Other or unknown disposal:	2.4
Other or unknown disposal - basis of estimate:	Periodic/Random Monotoning Data
Other or unknown treatment:	0
Other or unknown treatment - basis of estimate:	Not reported
Sludge to incineration - nonmetals:	0
Sludge to incineration - nonmetals - basis of estimate:	Not reported
Total treated:	0
POTW Registry ID:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	2.4
Off Site - POTW Releases:	2.4
Experimental and Est. Treatment:	0
Experimental and Est. Treatment - Basis of Est.:	Not reported

TRI ID:	92010RHRNDFOOTO
Cas number:	007439921
Chemical name: LEAD	
Classification:	PBT
Unit of measure:	Pounds
Metal ind:	YES
Revision code 1:	Not reported
Revision code 2:	Not reported
Maximum amount on site:	05
Fugitive air emissions - total release pounds:	0
Fugitive air emissions - total release range code:	Not reported
Total fugitive air emissions:	0
Fugitive air emissions - basis of estimate:	Other
Stack air emissions - release pounds:	.1
Stack air emissions - release range code:	Not reported
Total stack air emissions:	.1
Stack air emissions - basis of estimate:	Other
Total air emissions:	.1
Discharges to stream a - stream name:	SAN DIEGO BAY
Total discharges to stream a:	1.3
Discharges to stream a - basis of estimate:	Periodic/Random Monotoning Data
Discharges to stream a - % from stormwater:	100
Discharges to stream b - stream name:	Not reported
Total discharges to stream b:	Not reported
Discharges to stream b - basis of estimate:	Not reported
Discharges to stream b - % from stormwater:	Not reported
Discharges to stream c - stream name:	Not reported
Total discharges to stream c:	Not reported
Discharges to stream c - basis of estimate:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Discharges to stream c - % from stormwater:	Not reported
Discharges to stream d - stream name:	Not reported
Total discharges to stream d:	Not reported
Discharges to stream d - basis of estimate:	Not reported
Discharges to stream d - % from stormwater:	Not reported
Discharges to stream e - stream name:	Not reported
Total discharges to stream e:	Not reported
Discharges to stream e - basis of estimate:	Not reported
Discharges to stream e - % from stormwater:	Not reported
Discharges to stream f - stream name:	Not reported
Total discharges to stream f:	Not reported
Discharges to stream f - basis of estimate:	Not reported
Discharges to stream f - % from stormwater:	Not reported
Discharges to stream g - stream name:	Not reported
Total discharges to stream g:	Not reported
Discharges to stream g - basis of estimate:	Not reported
Discharges to stream g - % from stormwater:	Not reported
Total number of receiving streams:	1
Total surface water discharge:	1.3
Total on-site underground inj - pounds:	Not reported
On-site underground inj - basis of estimate:	Not reported
Total on-site ugrnd inj to cl i wells - pounds:	0
On-site underground inj to c1 i wells - basis of estimate:	Not reported
Total on-site ugrnd inj to cl ii-v wells - pounds:	0
On-site ungrnd inj to cl ii-v wells - basis of estimate:	Not reported
Total on-site underground injection:	0
Total on-site landfills:	Not reported
On-site landfills - basis of estimate:	Not reported
Total on-site RCRA subtitle c landfills:	0
On-site RCRA subtitle c landfills - basis of estimate:	Not reported
Total other on-site landfills:	0
Other landfills - basis of estimate:	Not reported
Total on-site land treatment:	0
Land trtmt/appl farming - basis of estimate:	Not reported
Total surface impoundments:	Not reported
Surface impoundment - basis of estimate:	Not reported
Total RCRA c surface impoundments:	0
RCRA c Surface impoundment - basis of estimate:	Not reported
Total other surface impoundments:	0
Other surface impoundment - basis of estimate:	Not reported
Total other disposal:	0
Other disposal - basis of estimate:	Not reported
Total on-site land releases:	0
Total on-site releases:	1.4
Off-site - POTW releases:	.3
Off-site - storage only:	0
Off-site - solid/stab - metals:	0
Off-site - wastewater treatment release - metals:	0
Off-site - solid/stab - release - metals:	0
Off-site - wastewater treatment - metals:	0
Off-site - underground injection:	0
Off-site - underground injection - class 1 wells:	0
Off-site - underground injection - class ii-v wells:	0
Off-site - landfills/disposal surface impoundments:	0
Off-site - surface impoundment:	0
Off-site - RCRA subtitle c surface impoundments:	0
Off-site - other surface impoundments:	0

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Off-site - other landfills:	0
Off-site - RCRA subtitle c landfills:	40519
Off-site - disposal - land treatment:	0
Off-site - disposal - other land disposal:	0
Off-site - disposal - other off-site management:	0
Off-site - disposal - transfer to waste broker:	490
Off-site - disposal - unknown:	270.5
Total transferred off site for disposal:	41279.8
Off-site - recycling - solvents/organics recovery:	0
Off-site - recycling -metals recovery:	197
Off-site - recycling - other reuse or recovery:	0
Off-site - recycling - acid regeneration:	0
Off-site - recycling - transfer to waste broker:	0
Total transferred off site for recycling:	197
Off-site - energy recovery:	0
Off-site - transfer to waste broker for energy recovery:	0
Total transferred off site for energy recovery:	0
Off-site - POTW treatment:	0
Off-site - solid/stab treatment - non metals:	0
Off-site -incineration/thermal treatment:	0
Off-site - incineration/insignificant heat value:	0
Off-site - wastewater treatment - non-metals:	0
Off-site - other waste treatment:	0
Off-site - transfer to waste broker - waste treatment:	0
Total transferred off site for treatment:	0
Off-site - transfer to waste broker:	0
Total transferred off site for further waste management:	41476.5
Total POTW transfer:	.3
Energy recovery on site current year:	0
Recycled on site current year:	0
Treated on site current year:	0
Total on-site waste management:	0
On-site energy recovery method 1:	Not Applicable
On-site energy recovery method 2:	Not reported
On-site energy recovery method 3:	Not Applicable
On-site energy recovery method 4:	Not reported
On-site recycling processes method 1:	Not Applicable
On-site recycling processes method 2:	Not reported
On-site recycling processes method 3:	Not reported
On-site recycling processes method 4:	Not reported
On-site recycling processes method 5:	Not reported
On-site recycling processes method 6:	Not reported
On-site recycling processes method 7:	Not reported
FRS Facility ID:	110000478518
Elemental Metal Included:	NO
Waste Rock Pile managed Indicator:	0
Waste Rock Quantity:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	.3

Chemical Activities and Uses:

Cas number:		007439921
Document control number:		1318216991822
Chemical name:	LEAD	
Classification:		PBT
Unit of measure:		Pounds
Produce the chemical:		No
Import the chemical:		No

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

On-site use of the chemical:	No
Sale or distribution of the chemical:	No
As a byproduct:	No
As a manufactured impurity:	No
Used as a reactant:	No
P101 feedstocks:	No
P102 raw materials:	No
P103 intermediates:	No
P104 initiators:	No
P199 other:	No
Added as a formulation component:	No
P201 additives:	No
P202 dyes:	No
P203 reaction diluents:	No
P204 initiators:	No
P205 solvents:	No
P206 inhibitors:	No
P207 emulsifiers:	No
P208 surfactants:	No
P209 lubricants:	No
P210 flame retardants:	No
P211 rheological modifiers:	No
P299 other:	No
Used as an article component:	Yes
Repackaging:	No
As a process impurity:	No
Processed / recycling:	No
Used as a chemical processing aid:	No
Z101 process solvents:	No
Z102 catalysts:	No
Z103 inhibitors:	No
Z104 initiators:	No
Z105 reaction terminators:	No
Z106 solution buffers:	No
Z199 other:	No
Used as a manufacturing aid:	No
Z201 process lubricants:	No
Z202 metalworking fluids:	No
Z203 coolants:	No
Z204 refrigerants:	No
Z205 hydraulic fluids:	No
Z299 other:	No
Ancillary or other use:	Yes
Z301 cleaner:	No
Z302 degreaser:	No
Z303 lubricant:	No
Z304 fuel:	No
Z305 flame retardant:	No
Z306 waste treatment:	No
Z307 water treatment:	No
Z308 construction materials:	No
Z399 other:	No

Submitted Facility Name:	ROHR INC A UTC AEROSPACE SYSTEMS CO
Submitted Street:	850 LAGOON DR MAIL ZONE 1-C
Submitted City:	CHULA VISTA
Submitted County:	SAN DIEGO

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Submitted State:	CA
Submitted Zip Code:	91910
Submitted BIA Code:	Not reported
Submitted Tribe Name:	Not reported
Submitted Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Parent Company DB Number:	001344142
Submitted Standardized Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Primary NAICS Code:	336413
Submitted Industry Code:	336
Submitted Industry Name:	Transportation Equipment
Industry Code:	336
Industry Name:	Transportation Equipment
Last year the facility reported:	2019
First year the facility reported:	1987
Number of forms submitted:	5
Total number of forms submitted:	272 20200808

Detailed Source Reduction Activities and Methods:

Cas number:	007439921
Document control number:	1318216991822
Chemical name: LEAD	
Classification:	PBT
Unit of measure:	Pounds
On-site limited releases - prior year:	0
On-site limited releases - current year:	0
On-site limited releases - following year:	0
On-site limited releases - 2nd-following year:	0
Other on-site releases - prior year:	.9
Other on-site releases - current year:	1.4
Other on-site releases - following year:	1.3
Other on-site releases - 2nd-following year:	1.2
Off-site limited releases - prior year:	370
Off-site limited releases - current year:	240
Off-site limited releases - following year:	230
Off-site limited releases - 2nd-following year:	220
Other off-site releases - previous year:	1100
Other off-site releases - current year:	600
Other off-site releases - following year:	580
Other off-site releases - 2nd-following year:	560
Energy recovery on site prior year:	0
Energy recovery on site current year:	0
Energy recovery on site following year:	0
Energy recovery on site 2nd-following year:	0
Energy recovery off site prior year:	0
Energy recovery off site current year:	0
Energy recovery off site following year:	0
Energy recovery off site 2nd-following year:	0
Quantity recycled on site prior year:	0
Quantity recycled on site current year:	0
Quantity recycled on site following year:	0
Quantity recycled on site 2nd-following year:	0
Quantity recycled off site prior year:	54
Quantity recycled off site current year:	200
Quantity recycled off site following year:	190
Quantity recycled off site 2nd-following year:	180
Quantity treated on site prior year:	0
Quantity treated on site current year:	0

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Quantity treated on site following year:	0
Quantity treated on site 2nd-following year:	0
Quantity treated off site prior year:	0
Quantity treated off site current year:	0
Quantity treated off site following year:	0
Quantity treated off site 2nd-following year:	0
Catastrophic releases or other one-time events:	40000
Prod ratio/activity index:	.96
Prod ratio or activity:	ACTIVITY
1st SR reduction activity:	NA-NA
1st SR activity ID meth code and desc 1:	Not reported
1st SR activity ID meth code and desc 2:	Not reported
1st SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 1st source REDN act code and desc:	Not reported
2nd SR activity code and desc:	Not reported
2nd SR activity ID meth code and desc 1:	Not reported
2nd SR activity ID meth code and desc 2:	Not reported
2nd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 2nd source REDN act code and desc:	Not reported
3rd SR activity code and desc:	Not reported
3rd SR activity ID meth code and desc 1:	Not reported
3rd SR activity ID meth code and desc 2:	Not reported
3rd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 3rd source REDN act code and desc:	Not reported
4th SR activity code and desc:	Not reported
4th SR activity ID meth code and desc 1:	Not reported
4th SR activity ID meth code and desc 2:	Not reported
4th SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 4th source REDN act code and desc:	Not reported

Detailed On-site Waste Treatment Methods and Efficiency:

Cas number:	007439921
Document control number:	1318216991822
Chemical name: LEAD	
Classification:	PBT
Unit of measure:	Pounds
Stream 1 - waste stream code:	Wastewater (aqueous waste)
Stream 1 - trtmt method - sequence 1:	Other chemical precipitation with or without pre-treatment
Stream 1 - trtmt method - sequence 2:	Sludge treatment and/or dewatering
Stream 1 - trtmt method - sequence 3:	Settling or clarification
Stream 1 - trtmt method - sequence 4:	Other treatment
Stream 1 - trtmt method - sequence 5:	Not reported
Stream 1 - trtmt method - sequence 6:	Not reported
Stream 1 - trtmt method - sequence 7:	Not reported
Stream 1 - trtmt method - sequence 8:	Not reported
Stream 1 - based on operating data:	NO
Stream 2 - waste stream code:	Not reported
Stream 2 - trtmt method - sequence 1:	Not reported
Stream 2 - trtmt method - sequence 2:	Not reported
Stream 2 - trtmt method - sequence 3:	Not reported
Stream 2 - trtmt method - sequence 4:	Not reported
Stream 2 - trtmt method - sequence 5:	Not reported
Stream 2 - trtmt method - sequence 6:	Not reported
Stream 2 - trtmt method - sequence 7:	Not reported
Stream 2 - trtmt method - sequence 8:	Not reported
Stream 2 - based on operating data:	Not reported
Stream 3 - waste stream code:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Stream 3 - trtmt method - sequence 1:	Not reported
Stream 3 - trtmt method - sequence 2:	Not reported
Stream 3 - trtmt method - sequence 3:	Not reported
Stream 3 - trtmt method - sequence 4:	Not reported
Stream 3 - trtmt method - sequence 5:	Not reported
Stream 3 - trtmt method - sequence 6:	Not reported
Stream 3 - trtmt method - sequence 7:	Not reported
Stream 3 - trtmt method - sequence 8:	Not reported
Stream 3 - based on operating data:	Not reported
Stream 4 - waste stream code:	Not reported
Stream 4 - trtmt method - sequence 1:	Not reported
Stream 4 - trtmt method - sequence 2:	Not reported
Stream 4 - trtmt method - sequence 3:	Not reported
Stream 4 - trtmt method - sequence 4:	Not reported
Stream 4 - trtmt method - sequence 5:	Not reported
Stream 4 - trtmt method - sequence 6:	Not reported
Stream 4 - trtmt method - sequence 7:	Not reported
Stream 4 - trtmt method - sequence 8:	Not reported
Stream 4 - based on operating data:	Not reported
Stream 5 - waste stream code:	Not reported
Stream 5 - trtmt method - sequence 1:	Not reported
Stream 5 - trtmt method - sequence 2:	Not reported
Stream 5 - trtmt method - sequence 3:	Not reported
Stream 5 - trtmt method - sequence 4:	Not reported
Stream 5 - trtmt method - sequence 5:	Not reported
Stream 5 - trtmt method - sequence 6:	Not reported
Stream 5 - trtmt method - sequence 7:	Not reported
Stream 5 - trtmt method - sequence 8:	Not reported
Stream 5 - based on operating data:	Not reported

Details of Off-site Transfers:

Cas number:		007439921
Document control number:		1318216991822
Chemical name:	LEAD	
Classification:		PBT
Offsite RCRA id nr:		ARD981057870
Offsite transfer sequence number:		2
Offsite name:		RINECO CHEMICAL INDUSTRIES, INC
Offsite street address:		1007 VULCAN ROAD
Offsite City,State,Zip:		BENTON, AR 72015
Offsite county:		SALINE
Offsite province:		Not reported
Offsite country id:		Not reported
Offsite control:		NO
Unit of measure:		Pounds
Offsite TRF to WST broker for DSP m94 LBS:		490
Offsite TRF to WST broker for DSP m94 BOE:		Other
Total amount transferred offsite for disposal:		490
Total amount transferred offsite for recycling:		0
Total amount transferred offsite for energy recovery:		0
Total amount transferred offsite for treatment:		0
FRS ID - Transfer Location:		Not reported

Offsite RCRA id nr:	ARD981057870
Offsite transfer sequence number:	2
Offsite name:	RINECO CHEMICAL INDUSTRIES, INC
Offsite street address:	1007 VULCAN ROAD

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Offsite City,State,Zip:	BENTON, AR 72015
Offsite county:	SALINE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	270
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	270
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	UTD981552177
Offsite transfer sequence number:	3
Offsite name:	CLEAN HARBORS ARAGONITE, LLC
Offsite street address:	11600 N APTUS ROAD
Offsite City,State,Zip:	ARAGONITE, UT 84029
Offsite county:	TOOELE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	1400
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	1400
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	110000906985

Offsite RCRA id nr:	CAD980675276
Offsite transfer sequence number:	4
Offsite name:	CLEAN HARBORS BUTTONWILLOW LLC
Offsite street address:	2500 WEST LOKERN
Offsite City,State,Zip:	BUTTONWILLOW, CA 932060000
Offsite county:	KERN
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	36000
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	36000
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	110000500912

Offsite RCRA id nr:	UTD991301748
Offsite transfer sequence number:	5
Offsite name:	CLEAN HARBORS GRASSY MOUNTAIN
Offsite street address:	3 MILES EAST, 7 MILES NROTH KNOL
Offsite City,State,Zip:	KNOLLS, UT 84029
Offsite county:	TOOELE
Offsite province:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	2800
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	2800
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	110013709754

Offsite RCRA id nr:	CAT080013352
Offsite transfer sequence number:	6
Offsite name:	DEMENNO KERDOON
Offsite street address:	2000 N ALAMEDA STREET
Offsite City,State,Zip:	COMPTON, CA 90222
Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	.3
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	.3
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	CAT080013352
Offsite transfer sequence number:	6
Offsite name:	DEMENNO KERDOON
Offsite street address:	2000 N ALAMEDA STREET
Offsite City,State,Zip:	COMPTON, CA 90222
Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Total amount transferred offsite for disposal:	0
Offsite metals recovery m24 LBS:	160
Offsite metals recovery m24 BOE:	Other
Total amount transferred offsite for recycling:	160
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	NVT330010000
Offsite transfer sequence number:	7
Offsite name:	US ECOLOGY NEVADA INC
Offsite street address:	HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:	BEATTY, NV 89003
Offsite county:	NYE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Total amount transferred offsite for disposal:	0
Offsite metals recovery m24 LBS:	37
Offsite metals recovery m24 BOE:	Other
Total amount transferred offsite for recycling:	37
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported
Offsite RCRA id nr:	NVT330010000
Offsite transfer sequence number:	7
Offsite name:	US ECOLOGY NEVADA INC
Offsite street address:	HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:	BEATTY, NV 89003
Offsite county:	NYE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	319
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	319
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported
Offsite RCRA id nr:	CAD097030993
Offsite transfer sequence number:	8
Offsite name:	US ECOLOGY VERNON, INC.
Offsite street address:	5375 SOUTH BOYLES AVENUE
Offsite City,State,Zip:	VERNON, CA 90058
Offsite county:	LOS ANGELES
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	.2
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	.2
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Details of Transfers to Publicly Owned Treatment Works:

Cas number:	007439921
Document control number:	1318216991822
Chemical name: LEAD	
Classification:	PBT
Unit of measure:	Pounds
POTW name:	POINT LOMA WASTEWATER TREATMENT PLANT
POTW address:	1902 GATCHELL ROAD
POTW City,State,Zip:	SAN DIEGO, CA 92106
POTW county:	SAN DIEGO
Quantity transferred:	.3
Basis of estimate:	Not reported
Discharges to water streams:	0

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Discharges to water streams - basis of estimate:	Not reported
Discharges to other activities:	0
Discharges to other activities - basis of estimate:	Not reported
Released to air:	0
Released to air - basis of estimate:	Not reported
Sludge to disposal:	0
Sludge to disposal - basis of estimate:	Not reported
Sludge to incineration - metals:	0
Sludge to incineration - metals - basis of estimate:	Not reported
Sludge to agricultural applications:	0
Sludge to agricultural applications - basis of estimate:	Not reported
Other or unknown disposal:	.3
Other or unknown disposal - basis of estimate:	Periodic/Random Monotoning Data
Other or unknown treatment:	0
Other or unknown treatment - basis of estimate:	Not reported
Sludge to incineration - nonmetals:	0
Sludge to incineration - nonmetals - basis of estimate:	Not reported
Total treated:	0
POTW Registry ID:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	.3
Off Site - POTW Releases:	.3
Experimental and Est. Treatment:	0
Experimental and Est. Treatment - Basis of Est.:	Not reported

TRI ID:	92010RHRNDFOOTO
Cas number:	N511
Chemical name:	NITRATE COMPOUNDS
Classification:	TRI
Unit of measure:	Pounds
Metal ind:	NO
Revision code 1:	Not reported
Revision code 2:	Not reported
Maximum amount on site:	04
Fugitive air emissions - total release pounds:	0
Fugitive air emissions - total release range code:	Not reported
Total fugitive air emissions:	0
Fugitive air emissions - basis of estimate:	Other
Stack air emissions - release pounds:	0
Stack air emissions - release range code:	Not reported
Total stack air emissions:	0
Stack air emissions - basis of estimate:	Other
Total air emissions:	0
Discharges to stream a - stream name:	NA
Total discharges to stream a:	0
Discharges to stream a - basis of estimate:	Not reported
Discharges to stream a - % from stormwater:	Not reported
Discharges to stream b - stream name:	Not reported
Total discharges to stream b:	Not reported
Discharges to stream b - basis of estimate:	Not reported
Discharges to stream b - % from stormwater:	Not reported
Discharges to stream c - stream name:	Not reported
Total discharges to stream c:	Not reported
Discharges to stream c - basis of estimate:	Not reported
Discharges to stream c - % from stormwater:	Not reported
Discharges to stream d - stream name:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Total discharges to stream d:	Not reported
Discharges to stream d - basis of estimate:	Not reported
Discharges to stream d - % from stormwater:	Not reported
Discharges to stream e - stream name:	Not reported
Total discharges to stream e:	Not reported
Discharges to stream e - basis of estimate:	Not reported
Discharges to stream e - % from stormwater:	Not reported
Discharges to stream f - stream name:	Not reported
Total discharges to stream f:	Not reported
Discharges to stream f - basis of estimate:	Not reported
Discharges to stream f - % from stormwater:	Not reported
Discharges to stream g - stream name:	Not reported
Total discharges to stream g:	Not reported
Discharges to stream g - basis of estimate:	Not reported
Discharges to stream g - % from stormwater:	Not reported
Total number of receiving streams:	0
Total surface water discharge:	0
Total on-site underground inj - pounds:	Not reported
On-site underground inj - basis of estimate:	Not reported
Total on-site ugrnd inj to cl i wells - pounds:	0
On-site underground inj to c1 i wells - basis of estimate:	Not reported
Total on-site ugrnd inj to cl ii-v wells - pounds:	0
On-site ungrnd inj to cl ii-v wells - basis of estimate:	Not reported
Total on-site underground injection:	0
Total on-site landfills:	Not reported
On-site landfills - basis of estimate:	Not reported
Total on-site RCRA subtitle c landfills:	0
On-site RCRA subtitle c landfills - basis of estimate:	Not reported
Total other on-site landfills:	0
Other landfills - basis of estimate:	Not reported
Total on-site land treatment:	0
Land trtmt/appl farming - basis of estimate:	Not reported
Total surface impoundments:	Not reported
Surface impoundment - basis of estimate:	Not reported
Total RCRA c surface impoundments:	0
RCRA c Surface impoundment - basis of estimate:	Not reported
Total other surface impoundments:	0
Other surface impoundment - basis of estimate:	Not reported
Total other disposal:	0
Other disposal - basis of estimate:	Not reported
Total on-site land releases:	0
Total on-site releases:	0
Off-site - POTW releases:	23400
Off-site - storage only:	0
Off-site - solid/stab - metals:	0
Off-site - wastewater treatment release - metals:	0
Off-site - solid/stab - release - metals:	0
Off-site - wastewater treatment - metals:	0
Off-site - underground injection:	0
Off-site - underground injection - class 1 wells:	0
Off-site - underground injection - class ii-v wells:	0
Off-site - landfills/disposal surface impoundments:	0
Off-site - surface impoundment:	0
Off-site - RCRA subtitle c surface impoundments:	0
Off-site - other surface impoundments:	0
Off-site - other landfills:	0
Off-site - RCRA subtitle c landfills:	260

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Off-site - disposal - land treatment:	0
Off-site - disposal - other land disposal:	0
Off-site - disposal - other off-site management:	0
Off-site - disposal - transfer to waste broker:	0
Off-site - disposal - unknown:	48
Total transferred off site for disposal:	23708
Off-site - recycling - solvents/organics recovery:	0
Off-site - recycling -metals recovery:	0
Off-site - recycling - other reuse or recovery:	1
Off-site - recycling - acid regeneration:	0
Off-site - recycling - transfer to waste broker:	0
Total transferred off site for recycling:	1
Off-site - energy recovery:	0
Off-site - transfer to waste broker for energy recovery:	0
Total transferred off site for energy recovery:	0
Off-site - POTW treatment:	0
Off-site - solid/stab treatment - non metals:	0
Off-site -incineration/thermal treatment:	1.1
Off-site - incineration/insignificant heat value:	0
Off-site - wastewater treatment - non-metals:	0
Off-site - other waste treatment:	0
Off-site - transfer to waste broker - waste treatment:	0
Total transferred off site for treatment:	1.1
Off-site - transfer to waste broker:	0
Total transferred off site for further waste management:	21370.1
Total POTW transfer:	23400
Energy recovery on site current year:	0
Recycled on site current year:	0
Treated on site current year:	0
Total on-site waste management:	0
On-site energy recovery method 1:	Not Applicable
On-site energy recovery method 2:	Not reported
On-site energy recovery method 3:	Not Applicable
On-site energy recovery method 4:	Not reported
On-site recycling processes method 1:	Not Applicable
On-site recycling processes method 2:	Not reported
On-site recycling processes method 3:	Not reported
On-site recycling processes method 4:	Not reported
On-site recycling processes method 5:	Not reported
On-site recycling processes method 6:	Not reported
On-site recycling processes method 7:	Not reported
FRS Facility ID:	110000478518
Elemental Metal Included:	NO
Waste Rock Pile managed Indicator:	0
Waste Rock Quantity:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	23400

Chemical Activities and Uses:

Cas number:	N511
Document control number:	1318216991808
Chemical name:	NITRATE COMPOUNDS
Classification:	TRI
Unit of measure:	Pounds
Produce the chemical:	Yes
Import the chemical:	No
On-site use of the chemical:	No
Sale or distribution of the chemical:	No

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

As a byproduct:	Yes
As a manufactured impurity:	No
Used as a reactant:	No
P101 feedstocks:	No
P102 raw materials:	No
P103 intermediates:	No
P104 initiators:	No
P199 other:	No
Added as a formulation component:	No
P201 additives:	No
P202 dyes:	No
P203 reaction diluents:	No
P204 initiators:	No
P205 solvents:	No
P206 inhibitors:	No
P207 emulsifiers:	No
P208 surfactants:	No
P209 lubricants:	No
P210 flame retardants:	No
P211 rheological modifiers:	No
P299 other:	No
Used as an article component:	No
Repackaging:	No
As a process impurity:	No
Processed / recycling:	No
Used as a chemical processing aid:	No
Z101 process solvents:	No
Z102 catalysts:	No
Z103 inhibitors:	No
Z104 initiators:	No
Z105 reaction terminators:	No
Z106 solution buffers:	No
Z199 other:	No
Used as a manufacturing aid:	No
Z201 process lubricants:	No
Z202 metalworking fluids:	No
Z203 coolants:	No
Z204 refrigerants:	No
Z205 hydraulic fluids:	No
Z299 other:	No
Ancillary or other use:	No
Z301 cleaner:	No
Z302 degreaser:	No
Z303 lubricant:	No
Z304 fuel:	No
Z305 flame retardant:	No
Z306 waste treatment:	No
Z307 water treatment:	No
Z308 construction materials:	No
Z399 other:	No

Submitted Facility Name:	ROHR INC A UTC AEROSPACE SYSTEMS CO
Submitted Street:	850 LAGOON DR MAIL ZONE 1-C
Submitted City:	CHULA VISTA
Submitted County:	SAN DIEGO
Submitted State:	CA
Submitted Zip Code:	91910

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Submitted BIA Code:	Not reported
Submitted Tribe Name:	Not reported
Submitted Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Parent Company DB Number:	001344142
Submitted Standardized Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Primary NAICS Code:	336413
Submitted Industry Code:	336
Submitted Industry Name:	Transportation Equipment
Industry Code:	336
Industry Name:	Transportation Equipment
Last year the facility reported:	2019
First year the facility reported:	1987
Number of forms submitted:	5
Total number of forms submitted:	272 20200808

Detailed Source Reduction Activities and Methods:

Cas number:	N511
Document control number:	1318216991808
Chemical name:	NITRATE COMPOUNDS
Classification:	TRI
Unit of measure:	Pounds
On-site limited releases - prior year:	0
On-site limited releases - current year:	0
On-site limited releases - following year:	0
On-site limited releases - 2nd-following year:	0
Other on-site releases - prior year:	0
Other on-site releases - current year:	0
Other on-site releases - following year:	0
Other on-site releases - 2nd-following year:	0
Off-site limited releases - prior year:	5000
Off-site limited releases - current year:	260
Off-site limited releases - following year:	250
Off-site limited releases - 2nd-following year:	240
Other off-site releases - previous year:	1700
Other off-site releases - current year:	23000
Other off-site releases - following year:	22000
Other off-site releases - 2nd-following year:	21000
Energy recovery on site prior year:	0
Energy recovery on site current year:	0
Energy recovery on site following year:	0
Energy recovery on site 2nd-following year:	0
Energy recovery off site prior year:	0
Energy recovery off site current year:	0
Energy recovery off site following year:	0
Energy recovery off site 2nd-following year:	0
Quantity recycled on site prior year:	0
Quantity recycled on site current year:	0
Quantity recycled on site following year:	0
Quantity recycled on site 2nd-following year:	0
Quantity recycled off site prior year:	0
Quantity recycled off site current year:	1
Quantity recycled off site following year:	1
Quantity recycled off site 2nd-following year:	1
Quantity treated on site prior year:	0
Quantity treated on site current year:	0
Quantity treated on site following year:	0
Quantity treated on site 2nd-following year:	0

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Quantity treated off site prior year:	15000
Quantity treated off site current year:	1.1
Quantity treated off site following year:	1.1
Quantity treated off site 2nd-following year:	1.1
Catastrophic releases or other one-time events:	Not reported
Prod ratio/activity index:	.96
Prod ratio or activity:	ACTIVITY
1st SR reduction activity:	NA-NA
1st SR activity ID meth code and desc 1:	Not reported
1st SR activity ID meth code and desc 2:	Not reported
1st SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 1st source REDN act code and desc:	Not reported
2nd SR activity code and desc:	Not reported
2nd SR activity ID meth code and desc 1:	Not reported
2nd SR activity ID meth code and desc 2:	Not reported
2nd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 2nd source REDN act code and desc:	Not reported
3rd SR activity code and desc:	Not reported
3rd SR activity ID meth code and desc 1:	Not reported
3rd SR activity ID meth code and desc 2:	Not reported
3rd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 3rd source REDN act code and desc:	Not reported
4th SR activity code and desc:	Not reported
4th SR activity ID meth code and desc 1:	Not reported
4th SR activity ID meth code and desc 2:	Not reported
4th SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 4th source REDN act code and desc:	Not reported

Detailed On-site Waste Treatment Methods and Efficiency:

Cas number:	N511
Document control number:	1318216991808
Chemical name:	NITRATE COMPOUNDS
Classification:	TRI
Unit of measure:	Pounds
Stream 1 - waste stream code:	Wastewater (aqueous waste)
Stream 1 - trtmt method - sequence 1:	Chemical reduction with or without precipitation
Stream 1 - trtmt method - sequence 2:	Other chemical precipitation with or without pre-treatment
Stream 1 - trtmt method - sequence 3:	Neutralization
Stream 1 - trtmt method - sequence 4:	Settling or clarification
Stream 1 - trtmt method - sequence 5:	Sludge treatment and/or dewatering
Stream 1 - trtmt method - sequence 6:	Not reported
Stream 1 - trtmt method - sequence 7:	Not reported
Stream 1 - trtmt method - sequence 8:	Not reported
Stream 1 - based on operating data:	NO
Stream 2 - waste stream code:	Not reported
Stream 2 - trtmt method - sequence 1:	Not reported
Stream 2 - trtmt method - sequence 2:	Not reported
Stream 2 - trtmt method - sequence 3:	Not reported
Stream 2 - trtmt method - sequence 4:	Not reported
Stream 2 - trtmt method - sequence 5:	Not reported
Stream 2 - trtmt method - sequence 6:	Not reported
Stream 2 - trtmt method - sequence 7:	Not reported
Stream 2 - trtmt method - sequence 8:	Not reported
Stream 2 - based on operating data:	Not reported
Stream 3 - waste stream code:	Not reported
Stream 3 - trtmt method - sequence 1:	Not reported
Stream 3 - trtmt method - sequence 2:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Stream 3 - trtmt method - sequence 3:	Not reported
Stream 3 - trtmt method - sequence 4:	Not reported
Stream 3 - trtmt method - sequence 5:	Not reported
Stream 3 - trtmt method - sequence 6:	Not reported
Stream 3 - trtmt method - sequence 7:	Not reported
Stream 3 - trtmt method - sequence 8:	Not reported
Stream 3 - based on operating data:	Not reported
Stream 4 - waste stream code:	Not reported
Stream 4 - trtmt method - sequence 1:	Not reported
Stream 4 - trtmt method - sequence 2:	Not reported
Stream 4 - trtmt method - sequence 3:	Not reported
Stream 4 - trtmt method - sequence 4:	Not reported
Stream 4 - trtmt method - sequence 5:	Not reported
Stream 4 - trtmt method - sequence 6:	Not reported
Stream 4 - trtmt method - sequence 7:	Not reported
Stream 4 - trtmt method - sequence 8:	Not reported
Stream 4 - based on operating data:	Not reported
Stream 5 - waste stream code:	Not reported
Stream 5 - trtmt method - sequence 1:	Not reported
Stream 5 - trtmt method - sequence 2:	Not reported
Stream 5 - trtmt method - sequence 3:	Not reported
Stream 5 - trtmt method - sequence 4:	Not reported
Stream 5 - trtmt method - sequence 5:	Not reported
Stream 5 - trtmt method - sequence 6:	Not reported
Stream 5 - trtmt method - sequence 7:	Not reported
Stream 5 - trtmt method - sequence 8:	Not reported
Stream 5 - based on operating data:	Not reported

Details of Off-site Transfers:

Cas number:	N511
Document control number:	1318216991808
Chemical name:	NITRATE COMPOUNDS
Classification:	TRI
Offsite RCRA id nr:	NVT330010000
Offsite transfer sequence number:	2
Offsite name:	US ECOLOGY NEVADA INC
Offsite street address:	HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:	BEATTY, NV 89003
Offsite county:	NYE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Total amount transferred offsite for disposal:	0
Offsite other reuse or recovery m26 LBS:	1
Offsite other reuse or recovery m26 BOE:	Other
Total amount transferred offsite for recycling:	1
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	NVT330010000
Offsite transfer sequence number:	2
Offsite name:	US ECOLOGY NEVADA INC
Offsite street address:	HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:	BEATTY, NV 89003
Offsite county:	NYE

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite RCRA subtitle c landfillsm65 LBS:	260
Offsite RCRA subtitle c landfillsm65 BOE:	Other
Total amount transferred offsite for disposal:	260
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Offsite RCRA id nr:	IND093219012
Offsite transfer sequence number:	3
Offsite name:	HERITAGE ENVIRONMENTAL SERVICES LLC
Offsite street address:	7901 W MORRIS ST
Offsite City,State,Zip:	INDIANAPOLIS, IN 46231
Offsite county:	MARION
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	48
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	48
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	110000397393

Offsite RCRA id nr:	OHD980613541
Offsite transfer sequence number:	4
Offsite name:	HERITAGE THERMAL SERVICES INC
Offsite street address:	1250 SAINT GEORGE ST
Offsite City,State,Zip:	EAST LIVERPOOL, OH 43920
Offsite county:	COLUMBIANA
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Total amount transferred offsite for disposal:	0
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Offsite incineration/thermal treatment m50 LBS:	1.1
Offsite incineration/thermal treatment m50 BOE:	Other
Total amount transferred offsite for treatment:	1.1
FRS ID - Transfer Location:	110027242320

Details of Transfers to Publicly Owned Treatment Works:

Cas number:	N511
Document control number:	1318216991808
Chemical name:	NITRATE COMPOUNDS
Classification:	TRI
Unit of measure:	Pounds
POTW name:	POINT LOMA WASTEWATER TREATMENT PLANT
POTW address:	1902 GATCHELL ROAD
POTW City,State,Zip:	SAN DIEGO, CA 92106

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

POTW county:	SAN DIEGO
Quantity transferred:	23400
Basis of estimate:	Not reported
Discharges to water streams:	0
Discharges to water streams - basis of estimate:	Not reported
Discharges to other activities:	0
Discharges to other activities - basis of estimate:	Not reported
Released to air:	0
Released to air - basis of estimate:	Not reported
Sludge to disposal:	0
Sludge to disposal - basis of estimate:	Not reported
Sludge to incineration - metals:	0
Sludge to incineration - metals - basis of estimate:	Not reported
Sludge to agricultural applications:	0
Sludge to agricultural applications - basis of estimate:	Not reported
Other or unknown disposal:	23400
Other or unknown disposal - basis of estimate:	Mass Balance Calculations
Other or unknown treatment:	0
Other or unknown treatment - basis of estimate:	Not reported
Sludge to incineration - nonmetals:	0
Sludge to incineration - nonmetals - basis of estimate:	Not reported
Total treated:	0
POTW Registry ID:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	23400
Off Site - POTW Releases:	23400
Experimental and Est. Treatment:	0
Experimental and Est. Treatment - Basis of Est.:	Not reported

TRI ID:		92010RHRNDFOOTO
Cas number:		007697372
Chemical name:	NITRIC ACID	
Classification:		TRI
Unit of measure:		Pounds
Metal ind:		NO
Revision code 1:		Not reported
Revision code 2:		Not reported
Maximum amount on site:		04
Fugitive air emissions - total release pounds:		NA
Fugitive air emissions - total release range code:		Not reported
Total fugitive air emissions:		0
Fugitive air emissions - basis of estimate:		Not reported
Stack air emissions - release pounds:		61
Stack air emissions - release range code:		Not reported
Total stack air emissions:		61
Stack air emissions - basis of estimate:		Other
Total air emissions:		61
Discharges to stream a - stream name:		NA
Total discharges to stream a:		0
Discharges to stream a - basis of estimate:		Not reported
Discharges to stream a - % from stormwater:		Not reported
Discharges to stream b - stream name:		Not reported
Total discharges to stream b:		Not reported
Discharges to stream b - basis of estimate:		Not reported
Discharges to stream b - % from stormwater:		Not reported
Discharges to stream c - stream name:		Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Total discharges to stream c:	Not reported
Discharges to stream c - basis of estimate:	Not reported
Discharges to stream c - % from stormwater:	Not reported
Discharges to stream d - stream name:	Not reported
Total discharges to stream d:	Not reported
Discharges to stream d - basis of estimate:	Not reported
Discharges to stream d - % from stormwater:	Not reported
Discharges to stream e - stream name:	Not reported
Total discharges to stream e:	Not reported
Discharges to stream e - basis of estimate:	Not reported
Discharges to stream e - % from stormwater:	Not reported
Discharges to stream f - stream name:	Not reported
Total discharges to stream f:	Not reported
Discharges to stream f - basis of estimate:	Not reported
Discharges to stream f - % from stormwater:	Not reported
Discharges to stream g - stream name:	Not reported
Total discharges to stream g:	Not reported
Discharges to stream g - basis of estimate:	Not reported
Discharges to stream g - % from stormwater:	Not reported
Total number of receiving streams:	0
Total surface water discharge:	0
Total on-site underground inj - pounds:	Not reported
On-site underground inj - basis of estimate:	Not reported
Total on-site ugrnd inj to cl i wells - pounds:	0
On-site underground inj to c1 i wells - basis of estimate:	Not reported
Total on-site ugrnd inj to cl ii-v wells - pounds:	0
On-site ungrnd inj to cl ii-v wells - basis of estimate:	Not reported
Total on-site underground injection:	0
Total on-site landfills:	Not reported
On-site landfills - basis of estimate:	Not reported
Total on-site RCRA subtitle c landfills:	0
On-site RCRA subtitle c landfills - basis of estimate:	Not reported
Total other on-site landfills:	0
Other landfills - basis of estimate:	Not reported
Total on-site land treatment:	0
Land trtmt/appl farming - basis of estimate:	Not reported
Total surface impoundments:	Not reported
Surface impoundment - basis of estimate:	Not reported
Total RCRA c surface impoundments:	0
RCRA c Surface impoundment - basis of estimate:	Not reported
Total other surface impoundments:	0
Other surface impoundment - basis of estimate:	Not reported
Total other disposal:	0
Other disposal - basis of estimate:	Not reported
Total on-site land releases:	0
Total on-site releases:	61
Off-site - POTW releases:	0
Off-site - storage only:	0
Off-site - solid/stab - metals:	0
Off-site - wastewater treatment release - metals:	0
Off-site - solid/stab - release - metals:	0
Off-site - wastewater treatment - metals:	0
Off-site - underground injection:	0
Off-site - underground injection - class 1 wells:	0
Off-site - underground injection - class ii-v wells:	0
Off-site - landfills/disposal surface impoundments:	0
Off-site - surface impoundment:	0

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Off-site - RCRA subtitle c surface impoundments:	0
Off-site - other surface impoundments:	0
Off-site - other landfills:	0
Off-site - RCRA subtitle c landfills:	0
Off-site - disposal - land treatment:	0
Off-site - disposal - other land disposal:	0
Off-site - disposal - other off-site management:	0
Off-site - disposal - transfer to waste broker:	0
Off-site - disposal - unknown:	1100
Total transferred off site for disposal:	1100
Off-site - recycling - solvents/organics recovery:	0
Off-site - recycling -metals recovery:	0
Off-site - recycling - other reuse or recovery:	0
Off-site - recycling - acid regeneration:	33000
Off-site - recycling - transfer to waste broker:	0
Total transferred off site for recycling:	33000
Off-site - energy recovery:	0
Off-site - transfer to waste broker for energy recovery:	0
Total transferred off site for energy recovery:	0
Off-site - POTW treatment:	0
Off-site - solid/stab treatment - non metals:	0
Off-site -incineration/thermal treatment:	0
Off-site - incineration/insignificant heat value:	0
Off-site - wastewater treatment - non-metals:	0
Off-site - other waste treatment:	0
Off-site - transfer to waste broker - waste treatment:	0
Total transferred off site for treatment:	0
Off-site - transfer to waste broker:	0
Total transferred off site for further waste management:	34100
Total POTW transfer:	0
Energy recovery on site current year:	0
Recycled on site current year:	0
Treated on site current year:	24000
Total on-site waste management:	24000
On-site energy recovery method 1:	Not Applicable
On-site energy recovery method 2:	Not reported
On-site energy recovery method 3:	Not Applicable
On-site energy recovery method 4:	Not reported
On-site recycling processes method 1:	Not Applicable
On-site recycling processes method 2:	Not reported
On-site recycling processes method 3:	Not reported
On-site recycling processes method 4:	Not reported
On-site recycling processes method 5:	Not reported
On-site recycling processes method 6:	Not reported
On-site recycling processes method 7:	Not reported
FRS Facility ID:	110000478518
Elemental Metal Included:	NO
Waste Rock Pile managed Indicator:	0
Waste Rock Quantity:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	0

Chemical Activities and Uses:

Cas number:		007697372
Document control number:		1318216991810
Chemical name:	NITRIC ACID	
Classification:		TRI
Unit of measure:		Pounds

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Produce the chemical:	No
Import the chemical:	No
On-site use of the chemical:	No
Sale or distribution of the chemical:	No
As a byproduct:	No
As a manufactured impurity:	No
Used as a reactant:	Yes
P101 feedstocks:	No
P102 raw materials:	No
P103 intermediates:	No
P104 initiators:	No
P199 other:	No
Added as a formulation component:	No
P201 additives:	No
P202 dyes:	No
P203 reaction diluents:	No
P204 initiators:	No
P205 solvents:	No
P206 inhibitors:	No
P207 emulsifiers:	No
P208 surfactants:	No
P209 lubricants:	No
P210 flame retardants:	No
P211 rheological modifiers:	No
P299 other:	No
Used as an article component:	No
Repackaging:	No
As a process impurity:	No
Processed / recycling:	No
Used as a chemical processing aid:	Yes
Z101 process solvents:	No
Z102 catalysts:	No
Z103 inhibitors:	No
Z104 initiators:	No
Z105 reaction terminators:	No
Z106 solution buffers:	No
Z199 other:	No
Used as a manufacturing aid:	Yes
Z201 process lubricants:	No
Z202 metalworking fluids:	No
Z203 coolants:	No
Z204 refrigerants:	No
Z205 hydraulic fluids:	No
Z299 other:	No
Ancillary or other use:	Yes
Z301 cleaner:	No
Z302 degreaser:	No
Z303 lubricant:	No
Z304 fuel:	No
Z305 flame retardant:	No
Z306 waste treatment:	No
Z307 water treatment:	No
Z308 construction materials:	No
Z399 other:	No

Submitted Facility Name:	ROHR INC A UTC AEROSPACE SYSTEMS CO
Submitted Street:	850 LAGOON DR MAIL ZONE 1-C

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Submitted City:	CHULA VISTA
Submitted County:	SAN DIEGO
Submitted State:	CA
Submitted Zip Code:	91910
Submitted BIA Code:	Not reported
Submitted Tribe Name:	Not reported
Submitted Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Parent Company DB Number:	001344142
Submitted Standardized Parent Company Name:	UNITED TECHNOLOGIES CORP
Submitted Primary NAICS Code:	336413
Submitted Industry Code:	336
Submitted Industry Name:	Transportation Equipment
Industry Code:	336
Industry Name:	Transportation Equipment
Last year the facility reported:	2019
First year the facility reported:	1987
Number of forms submitted:	5
Total number of forms submitted:	272 20200808

Detailed Source Reduction Activities and Methods:

Cas number:	007697372
Document control number:	1318216991810
Chemical name: NITRIC ACID	
Classification:	TRI
Unit of measure:	Pounds
On-site limited releases - prior year:	0
On-site limited releases - current year:	0
On-site limited releases - following year:	0
On-site limited releases - 2nd-following year:	0
Other on-site releases - prior year:	62
Other on-site releases - current year:	61
Other on-site releases - following year:	59
Other on-site releases - 2nd-following year:	57
Off-site limited releases - prior year:	0
Off-site limited releases - current year:	0
Off-site limited releases - following year:	0
Off-site limited releases - 2nd-following year:	0
Other off-site releases - previous year:	0
Other off-site releases - current year:	1100
Other off-site releases - following year:	1100
Other off-site releases - 2nd-following year:	1100
Energy recovery on site prior year:	0
Energy recovery on site current year:	0
Energy recovery on site following year:	0
Energy recovery on site 2nd-following year:	0
Energy recovery off site prior year:	0
Energy recovery off site current year:	0
Energy recovery off site following year:	0
Energy recovery off site 2nd-following year:	0
Quantity recycled on site prior year:	0
Quantity recycled on site current year:	0
Quantity recycled on site following year:	0
Quantity recycled on site 2nd-following year:	0
Quantity recycled off site prior year:	0
Quantity recycled off site current year:	33000
Quantity recycled off site following year:	32000
Quantity recycled off site 2nd-following year:	31000

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Quantity treated on site prior year:	19000
Quantity treated on site current year:	24000
Quantity treated on site following year:	23000
Quantity treated on site 2nd-following year:	22000
Quantity treated off site prior year:	43000
Quantity treated off site current year:	0
Quantity treated off site following year:	0
Quantity treated off site 2nd-following year:	0
Catastrophic releases or other one-time events:	Not reported
Prod ratio/activity index:	.96
Prod ratio or activity:	ACTIVITY
1st SR reduction activity:	NA-NA
1st SR activity ID meth code and desc 1:	Not reported
1st SR activity ID meth code and desc 2:	Not reported
1st SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 1st source REDN act code and desc:	Not reported
2nd SR activity code and desc:	Not reported
2nd SR activity ID meth code and desc 1:	Not reported
2nd SR activity ID meth code and desc 2:	Not reported
2nd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 2nd source REDN act code and desc:	Not reported
3rd SR activity code and desc:	Not reported
3rd SR activity ID meth code and desc 1:	Not reported
3rd SR activity ID meth code and desc 2:	Not reported
3rd SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 3rd source REDN act code and desc:	Not reported
4th SR activity code and desc:	Not reported
4th SR activity ID meth code and desc 1:	Not reported
4th SR activity ID meth code and desc 2:	Not reported
4th SR activity ID meth code and desc 3:	Not reported
EST Ann REDN 4th source REDN act code and desc:	Not reported

Detailed On-site Waste Treatment Methods and Efficiency:

Cas number:	007697372
Document control number:	1318216991810
Chemical name: NITRIC ACID	
Classification:	TRI
Unit of measure:	Pounds
Stream 1 - waste stream code:	Wastewater (aqueous waste)
Stream 1 - trtmt method - sequence 1:	Other chemical precipitation with or without pre-treatment
Stream 1 - trtmt method - sequence 2:	Neutralization
Stream 1 - trtmt method - sequence 3:	Chemical reduction with or without precipitation
Stream 1 - trtmt method - sequence 4:	Settling or clarification
Stream 1 - trtmt method - sequence 5:	Sludge treatment and/or dewatering
Stream 1 - trtmt method - sequence 6:	Not reported
Stream 1 - trtmt method - sequence 7:	Not reported
Stream 1 - trtmt method - sequence 8:	Not reported
Stream 1 - based on operating data:	NO
Stream 2 - waste stream code:	Not reported
Stream 2 - trtmt method - sequence 1:	Not reported
Stream 2 - trtmt method - sequence 2:	Not reported
Stream 2 - trtmt method - sequence 3:	Not reported
Stream 2 - trtmt method - sequence 4:	Not reported
Stream 2 - trtmt method - sequence 5:	Not reported
Stream 2 - trtmt method - sequence 6:	Not reported
Stream 2 - trtmt method - sequence 7:	Not reported
Stream 2 - trtmt method - sequence 8:	Not reported

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Stream 2 - based on operating data:	Not reported
Stream 3 - waste stream code:	Not reported
Stream 3 - trtmt method - sequence 1:	Not reported
Stream 3 - trtmt method - sequence 2:	Not reported
Stream 3 - trtmt method - sequence 3:	Not reported
Stream 3 - trtmt method - sequence 4:	Not reported
Stream 3 - trtmt method - sequence 5:	Not reported
Stream 3 - trtmt method - sequence 6:	Not reported
Stream 3 - trtmt method - sequence 7:	Not reported
Stream 3 - trtmt method - sequence 8:	Not reported
Stream 3 - based on operating data:	Not reported
Stream 4 - waste stream code:	Not reported
Stream 4 - trtmt method - sequence 1:	Not reported
Stream 4 - trtmt method - sequence 2:	Not reported
Stream 4 - trtmt method - sequence 3:	Not reported
Stream 4 - trtmt method - sequence 4:	Not reported
Stream 4 - trtmt method - sequence 5:	Not reported
Stream 4 - trtmt method - sequence 6:	Not reported
Stream 4 - trtmt method - sequence 7:	Not reported
Stream 4 - trtmt method - sequence 8:	Not reported
Stream 4 - based on operating data:	Not reported
Stream 5 - waste stream code:	Not reported
Stream 5 - trtmt method - sequence 1:	Not reported
Stream 5 - trtmt method - sequence 2:	Not reported
Stream 5 - trtmt method - sequence 3:	Not reported
Stream 5 - trtmt method - sequence 4:	Not reported
Stream 5 - trtmt method - sequence 5:	Not reported
Stream 5 - trtmt method - sequence 6:	Not reported
Stream 5 - trtmt method - sequence 7:	Not reported
Stream 5 - trtmt method - sequence 8:	Not reported
Stream 5 - based on operating data:	Not reported

Details of Off-site Transfers:

Cas number:		007697372
Document control number:		1318216991810
Chemical name:	NITRIC ACID	
Classification:		TRI
Offsite RCRA id nr:		NVT330010000
Offsite transfer sequence number:		2
Offsite name:		US ECOLOGY NEVADA INC
Offsite street address:		HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:		BEATTY, NV 89003
Offsite county:		NYE
Offsite province:		Not reported
Offsite country id:		Not reported
Offsite control:		NO
Unit of measure:		Pounds
Total amount transferred offsite for disposal:		0
Offsite acid regeneration m28 LBS:		33000
Offsite acid regeneration m28 BOE:		Other
Total amount transferred offsite for recycling:		33000
Total amount transferred offsite for energy recovery:		0
Total amount transferred offsite for treatment:		0
FRS ID - Transfer Location:		Not reported

Offsite RCRA id nr:	NVT330010000
Offsite transfer sequence number:	2

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Offsite name:	US ECOLOGY NEVADA INC
Offsite street address:	HWY 95 11 MI S OF BEATTY
Offsite City,State,Zip:	BEATTY, NV 89003
Offsite county:	NYE
Offsite province:	Not reported
Offsite country id:	Not reported
Offsite control:	NO
Unit of measure:	Pounds
Offsite disposal unknown m99 LBS:	1100
Offsite disposal unknown m99 BOE:	Other
Total amount transferred offsite for disposal:	1100
Total amount transferred offsite for recycling:	0
Total amount transferred offsite for energy recovery:	0
Total amount transferred offsite for treatment:	0
FRS ID - Transfer Location:	Not reported

Details of Transfers to Publicly Owned Treatment Works:

Cas number:	007697372
Document control number:	1318216991810
Chemical name: NITRIC ACID	
Classification:	TRI
Unit of measure:	Pounds
POTW name:	POINT LOMA WASTEWATER TREATMENT PLANT
POTW address:	1902 GATCHELL ROAD
POTW City,State,Zip:	SAN DIEGO, CA 92106
POTW county:	SAN DIEGO
Quantity transferred:	0
Basis of estimate:	Not reported
Discharges to water streams:	0
Discharges to water streams - basis of estimate:	Not reported
Discharges to other activities:	0
Discharges to other activities - basis of estimate:	Not reported
Released to air:	0
Released to air - basis of estimate:	Not reported
Sludge to disposal:	0
Sludge to disposal - basis of estimate:	Not reported
Sludge to incineration - metals:	0
Sludge to incineration - metals - basis of estimate:	Not reported
Sludge to agricultural applications:	0
Sludge to agricultural applications - basis of estimate:	Not reported
Other or unknown disposal:	0
Other or unknown disposal - basis of estimate:	Other
Other or unknown treatment:	0
Other or unknown treatment - basis of estimate:	Not reported
Sludge to incineration - nonmetals:	0
Sludge to incineration - nonmetals - basis of estimate:	Not reported
Total treated:	0
POTW Registry ID:	Not reported
Off Site - POTW Releases 81C:	0
Off Site - POTW Releases 81D:	0
Off Site - POTW Releases:	0
Experimental and Est. Treatment:	0
Experimental and Est. Treatment - Basis of Est.:	Not reported

PADS:

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Name:	ROHR, INC. DBA GOODRICH
Address:	850 LAGOON DR.
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 91910-2098
EDR ID:	1000351369
EPAID:	CAD008382053
Region:	9
Generator:	Y
Storer:	N
Disposer:	N
Transporter:	N
Smelter:	N
Research Facility:	N
Mailing Address:	850 LAGOON DR., MZ 1-T
Mailing Address 2:	Not reported
Mailing City:	CHULA VISTA
Mailing State:	CA
Mailing Zip:	91910-2098
Mailing Country:	US
Owner Name:	ROHR, INC.
Certification Date:	06/09/2005
Contact Name:	RICHARD SIORDIA
Contact Title:	Not reported
Contact Telephone:	619-691-4279
Contact Text:	Not reported
Contact Email:	Not reported

ICIS:

Enforcement Action ID:	HQ-2003-5115
FRS ID:	110000478518
Action Name:	Rohr, Inc., dba Goodrich Aerospace Group
Facility Name:	ROHR, INC., DBA GOODRICH AEROSPACE GROUP
Facility Address:	850 LAGOON DRIVE CHULA VISTA, CA 91910
Enforcement Action Type:	EPCRA 325 Action For Penalty
Facility County:	SAN DIEGO
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	325
Facility SIC Code:	Not reported
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	32.635097
Longitude in Decimal Degrees:	-117.101916
Permit Type Desc:	Not reported
Program System Acronym:	5869619
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	HQ-1997-0208
FRS ID:	110000478518
Action Name:	ROHR INC.
Facility Name:	BFGOODRICH AEROSTRUCTURES GROUP
Facility Address:	850 LAGOON DRIVE CHULA VISTA, CA 919102098
Enforcement Action Type:	TSCA 16 Action For Penalty
Facility County:	SAN DIEGO
Program System Acronym:	ICIS

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 16
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 32.635097
Longitude in Decimal Degrees: -117.101916
Permit Type Desc: Not reported
Program System Acronym: 29127
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: CASDSA0000060730057700059
FRS ID: 110000478518
Action Name: BF GOODRICH 060730057700059
Facility Name: BF GOODRICH
Facility Address: 850 LAGOON DR
CHULA VISTA, CA 91910
Enforcement Action Type: Administrative Order
Facility County: SAN DIEGO
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3728
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 32.635868
Longitude in Decimal Degrees: -117.099546
Permit Type Desc: Not reported
Program System Acronym: CASDS0000607300577
Facility NAICS Code: 336413
Tribal Land Code: Not reported

Enforcement Action ID: CASDSA0000060730057700054
FRS ID: 110000478518
Action Name: BF GOODRICH 060730057700054
Facility Name: BF GOODRICH
Facility Address: 850 LAGOON DR
CHULA VISTA, CA 91910
Enforcement Action Type: Administrative Order
Facility County: SAN DIEGO
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3728
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 32.635868
Longitude in Decimal Degrees: -117.099546
Permit Type Desc: Not reported
Program System Acronym: CASDS0000607300577
Facility NAICS Code: 336413
Tribal Land Code: Not reported

Enforcement Action ID: CASDSA0000060730057700053
FRS ID: 110000478518
Action Name: BF GOODRICH 060730057700053
Facility Name: BF GOODRICH
Facility Address: 850 LAGOON DR
CHULA VISTA, CA 91910

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Enforcement Action Type: Notice of Violation
Facility County: SAN DIEGO
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3728
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 32.635868
Longitude in Decimal Degrees: -117.099546
Permit Type Desc: Not reported
Program System Acronym: CASDS0000607300577
Facility NAICS Code: 336413
Tribal Land Code: Not reported

Enforcement Action ID: CASDSA0000060730057700046
FRS ID: 110000478518
Action Name: BF GOODRICH 060730057700046
Facility Name: BF GOODRICH
Facility Address: 850 LAGOON DR
CHULA VISTA, CA 91910
Enforcement Action Type: Administrative Order
Facility County: SAN DIEGO
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3728
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 32.635868
Longitude in Decimal Degrees: -117.099546
Permit Type Desc: Not reported
Program System Acronym: CASDS0000607300577
Facility NAICS Code: 336413
Tribal Land Code: Not reported

Enforcement Action ID: CASDSA0000060730057700040
FRS ID: 110000478518
Action Name: BF GOODRICH 060730057700040
Facility Name: BF GOODRICH
Facility Address: 850 LAGOON DR
CHULA VISTA, CA 91910
Enforcement Action Type: Notice of Violation
Facility County: SAN DIEGO
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 3728
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 32.635868
Longitude in Decimal Degrees: -117.099546
Permit Type Desc: Not reported
Program System Acronym: CASDS0000607300577
Facility NAICS Code: 336413
Tribal Land Code: Not reported

Enforcement Action ID: CASDSA0000060730057700037
FRS ID: 110000478518
Action Name: BF GOODRICH 060730057700037

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Facility Name:	BF GOODRICH
Facility Address:	850 LAGOON DR CHULA VISTA, CA 91910
Enforcement Action Type:	Notice of Violation
Facility County:	SAN DIEGO
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	3728
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	32.635868
Longitude in Decimal Degrees:	-117.099546
Permit Type Desc:	Not reported
Program System Acronym:	CASDS0000607300577
Facility NAICS Code:	336413
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1000351369
Region Code:	09
Programmatic ID:	AIR CASDS0000607300577
Facility Registry ID:	110000478518
D and B Number:	Not reported
Primary SIC Code:	3728
NAICS Code:	336413
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	09
Programmatic ID:	AIR CASDS0000607300577
Facility Registry ID:	110000478518
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	Not reported
Activity Status Date:	1994-05-13 00:00:00
Activity Group:	Case File
Activity Type:	Case File
Activity Status:	Resolved

Region Code:	09
Programmatic ID:	AIR CASDS0000607300577
Facility Registry ID:	110000478518
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	Not reported
Activity Status Date:	1994-08-05 00:00:00
Activity Group:	Case File
Activity Type:	Case File
Activity Status:	Resolved

Region Code:	09

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: Not reported
Activity Status Date: 1995-11-09 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Resolved

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1976-03-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1978-02-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1979-02-05 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1980-01-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1981-01-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1982-01-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1983-01-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-01-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1984-06-05 00:00:00

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1985-02-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-02-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-09-02 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-05-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1987-08-25 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-02-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-08-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1989-02-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-07-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1991-03-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1992-02-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1993-01-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1994-03-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1995-03-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1996-03-08 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1997-04-24 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-03-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-03-23 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-04-25 00:00:00

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-09-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-02-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-02-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-02-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-02-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2006-04-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-03-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-04-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2010-05-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2011-04-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2012-04-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2013-04-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2014-03-27 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1994-05-13 00:00:00
Activity Status Date: 1994-05-13 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Activity Status: Final Order Issued

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1994-08-05 00:00:00
Activity Status Date: 1994-08-05 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1995-04-26 00:00:00
Activity Status Date: 1995-04-26 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1994-04-01 00:00:00
Activity Status Date: 1994-04-01 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1994-05-13 00:00:00
Activity Status Date: 1994-05-13 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

Region Code: 09
Programmatic ID: AIR CASDS0000607300577
Facility Registry ID: 110000478518
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1995-04-26 00:00:00

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

Activity Status Date: 1995-04-26 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

FINDS:
Registry ID: 110000478518

Click Here:

Environmental Interest/Information System:
NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
TSCA SUBMITTER
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
OSHA ESTABLISHMENT
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER
STATE MASTER
AIR MINOR
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate

ROHR INC A COLLINS AEROSPACE CO (Continued) **1000351369**

that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000351369
Registry ID:	110000478518
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000478518
Name:	ROHR INC DBA GOODRICH AEROSTRUCTURES GROUP
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91910

K54 **GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRU** **CPS-SLIC** **S118504627**
NNW **850 LAGOON DRIVE** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 2 of 14 in cluster K**

Relative: **Higher**
Actual: **12 ft.**

CPS-SLIC:

Name:	GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - NORTH CAMPUS
Address:	850 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910-2098
Region:	STATE
Facility Status:	**Open - Assessment & Interim Remedial Action**
Status Date:	03/13/2020
Global Id:	T10000001489
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.6308097015706
Longitude:	-117.100696563721
Case Type:	Cleanup Program Site
Case Worker:	TCA
Local Agency:	Not reported
RB Case Number:	2092900
File Location:	Regional Board
Potential Media Affected:	Contaminated Surface / Structure, Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern:	1,1,1-Trichloroethane (TCA), Other Chlorinated Hydrocarbons, Trichloroethylene (TCE), Vinyl chloride, Polychlorinated biphenyls (PCBs), Other Petroleum, Polynuclear aromatic hydrocarbons (PAHs)
Site History:	Since 1941, structural and engine components for use in the aviation and aerospace industry have been manufactured at the North Campus Property. Chemicals stored at the North Campus Property and used during manufacturing operations have been found in the soil, soil gas, and groundwater as reported in site environmental investigation reports and groundwater monitoring reports. The group of chemicals discharged include, but are not limited to, volatile organic compounds (VOCs), metals, petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and polychlorinated biphenyls (PCBs). In 1998, the San Diego Water Board issued CAO No. 98-08 to Rohr, Inc. CAO No. 98-08 requires the cleanup and abatement of wastes discharged from Rohrs manufacturing operations located at 850 Lagoon Drive in Chula Vista, California (North Campus Property and South Campus Property).

GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - N (Continued) **S118504627**

CAO No. 98-08 includes directives to (1) conduct a site-wide environmental site assessment, (2) conduct a comprehensive storm water runoff sampling program, (3) conduct a comprehensive storm water conveyance system investigation, (4) perform a site-wide data compilation and evaluation, and (5) conduct interim remedial actions. The first four directives have been completed. All subsequent activities have been conducted as interim remedial measures pursuant to the fifth directive. Interim remedial actions are currently underway at an off-property area located downgradient, known as Parcel H-3, pursuant to CAO No. 98-08. Redevelopment activities will be initiated on Parcel H-3 beginning in Summer 2020. The San Diego Water Board is currently preparing CAO No. R9-2020-0099, which addresses the cleanup or abatement of all wastes discharged to soil, soil gas, and groundwater from the manufacturing operations at the North Campus Property. CAO No. R9-2020-0099 will supersede CAO No. 98-08 except for the interim remedial actions at Parcel H-3, which will continue to be conducted under CAO No. 98-08. This CAO will be issued by Summer 2020. The North Campus Property is planned for redevelopment and is separated into three parcels: Parcels A, B, and C. Parcel A is approximately 12 acres and is currently for sale. The potential buyer plans to repurpose the three existing buildings on Parcel A. Parcel B is approximately 30 acres and is currently for sale. The potential buyer plans to demolish all the existing buildings on Parcel B. Parcel C is approximately 43 acres and includes 11 buildings, and is currently not for sale.

Click here to access the California GeoTracker records for this facility:

K55 **BF GOODRICH, AEROSTRUCTURES GROUP** **CPS-SLIC** **S106072880**
NNW **850 LAGOON DRIVE** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 3 of 14 in cluster K**

Relative: CPS-SLIC:
Higher No Details: No Details
Actual:
12 ft.

K56 **ROHR INC., A COLLINS AEROSPACE COMPANY** **CERS HAZ WASTE** **S123406600**
NNW **850 LAGOON DR** **CERS TANKS** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **CERS**
0.248 mi. **HWTS**
1312 ft. **Site 4 of 14 in cluster K**

Relative: CERS HAZ WASTE:
Higher
Actual: Name: ROHR INC., A COLLINS AEROSPACE COMPANY
12 ft. Address: 850 LAGOON DR
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 400868
CERS ID: 10123903
CERS Description: Hazardous Waste Generator

Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Address: 850 LAGOON DR
City,State,Zip: CHULA VISTA, CA 91910

ROHR INC., A COLLINS AEROSPACE COMPANY (Continued) **S123406600**

Site ID: 400868
CERS ID: 10123903
CERS Description: RCRA LQ HW Generator

CERS TANKS:
Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Address: 850 LAGOON DR
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 400868
CERS ID: 10123903
CERS Description: Aboveground Petroleum Storage

CERS:
Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Address: 850 LAGOON DR
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 400868
CERS ID: 10123903
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 400868
Site Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Violation Date: 08-12-2013
Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Description: Haz Waste Generator Program - Operations/Maintenance - General
Violation Notes: Returned to compliance on 08/13/2013. Inspection Sequence ID:4087639;Violation:HMD0235 Did not accumulate waste in container or tank. 66262.34(a)(1).
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS

Site ID: 400868
Site Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Violation Date: 11-05-2015
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Description: Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes: Returned to compliance on 02/29/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Marquez Marie Inspection ID:5774304
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

ROHR INC., A COLLINS AEROSPACE COMPANY (Continued) **S123406600**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Marquez Marie Inspection ID:5774304
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Marquez Marie Inspection ID:5774304
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Marquez Marie Inspection ID:5774304
Eval Division: San Diego County Department of Env Health
Eval Program: HWLQG
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-10-2010
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector Name: San Diego County; Determination of RCRA LQG status was based on a download of sites registered as RCRA LQGs on the USEPA website. Military bases in San Diego County registered under a primary EPA number but each command or unit permitted and inspected as a seperate enity b
Eval Division: California Environmental Protection Agency
Eval Program: HWLQG
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-12-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Javid Hasti Inspection ID:4087639
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-12-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Javid Hasti Inspection ID:4087639
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

ROHR INC., A COLLINS AEROSPACE COMPANY (Continued) **S123406600**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-12-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Javid Hasti Inspection ID:4087639
Eval Division: San Diego County Department of Env Health
Eval Program: HWLQG
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-12-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Javid Hasti Inspection ID:4087639
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 11-05-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Marquez Marie Inspection ID:5200783
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 11-05-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Marquez Marie Inspection ID:5200783
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 11-05-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Marquez Marie Inspection ID:5200783
Eval Division: San Diego County Department of Env Health
Eval Program: HWLQG
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 11-05-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Marquez Marie Inspection ID:5200783
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Coordinates:
Site ID: 400868
Facility Name: ROHR INC., A COLLINS AEROSPACE COMPANY

ROHR INC., A COLLINS AEROSPACE COMPANY (Continued) **S123406600**

Env Int Type Code: APSA
Program ID: 10123903
Coord Name: Not reported
Ref Point Type Desc: Unknown
Latitude: 32.635037
Longitude: -117.101951

Affiliation:
Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880

Affiliation Type Desc: Document Preparer
Entity Name: RICK SIORDIA
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Legal Owner
Entity Name: ROHR INC., A COLLINS AEROSPACE
Entity Title: Not reported
Affiliation Address: 850 LAGOON DR, MAIL ZONE 1-C
Affiliation City: Chula Vista
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 691-4111

Affiliation Type Desc: Operator
Entity Name: ROHR INC., A COLLINS AEROSPACE COMPANY
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 691-4111

Affiliation Type Desc: Property Owner
Entity Name: ROHR, INC., A COLLINS AEROSPACE COMPANY
Entity Title: Not reported
Affiliation Address: 850 LAGOON DR
Affiliation City: Chula Vista
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 691-4111

ROHR INC., A COLLINS AEROSPACE COMPANY (Continued) **S123406600**

Affiliation Type Desc: Environmental Contact
Entity Name: JENNY LUMN
Entity Title: Not reported
Affiliation Address: 850 LAGOON DR., MAIL ZONE M02
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91910
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 850 LAGOON DRIVE, MAIL ZONE 1-C
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91910-2098
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer
Entity Name: RICK SIORDIA
Entity Title: MANAGER, ENVIRONMENTAL
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: ROHR INC., a UTC AEROSPACE SYSTEMS COMPANY
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

HWTS:
Name: GOODRICH AEROSTRUCTURES, CHULA VISTA
Address: 850 LAGOON DRIVE
Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAC003056223
Inactive Date: 05/18/2020
Create Date: 02/17/2020
Last Act Date: 05/19/2020
Mailing Name: Not reported
Mailing Address: 850 LAGOON DRIVE
Mailing Address 2: Not reported
Mailing City,State,Zip: CHULA VISTA, CA 91910
Owner Name: SHALOM RAYMOND
Owner Address: 850 LAGOON DRIVE
Owner Address 2: Not reported

ROHR INC., A COLLINS AEROSPACE COMPANY (Continued) **S123406600**

Owner City,State,Zip: CHULA VISTA, CA 91910
Contact Name: SHALOM RAYMOND
Contact Address: 850 LAGOON DRIVE
Contact Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 91910

NAICS:
EPA ID: CAC003056223
Create Date: 2020-02-17 14:52:01.200
NAICS Code: 333319
NAICS Description: Other Commercial and Service Industry Machinery Manufacturing
Issued EPA ID Date: 2020-02-17 14:52:01.20000
Inactive Date: 2020-05-18 14:52:01.16700
Facility Name: GOODRICH AEROSTRUCTURES, CHULA VISTA
Facility Address: 850 LAGOON DRIVE
Facility Address 2: Not reported
Facility City: CHULA VISTA
Facility County: Not reported
Facility State: CA
Facility Zip: 91910

K57 **ROHR IND INC** **SEMS-ARCHIVE** **1015732654**
NNW **FOOT OF H ST** **CAD008382053**
1/8-1/4 **CHULA VISTA, CA 92012**
0.248 mi.
1312 ft. **Site 5 of 14 in cluster K**

Relative:
Higher

Actual:
12 ft.

SEMS Archive:
Site ID: 0901097
EPA ID: CAD008382053
Name: ROHR IND INC
Address: FOOT OF H ST
Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 92012
Cong District: 44
FIPS Code: 06073
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:
Region: 09
Site ID: 0901097
EPA ID: CAD008382053
Site Name: ROHR IND INC
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 1993-12-21 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 09
Site ID: 0901097

ROHR IND INC (Continued) **1015732654**

EPA ID:	CAD008382053
Site Name:	ROHR IND INC
NPL:	N
FF:	N
OU:	00
Action Code:	SI
Action Name:	SI
SEQ:	1
Start Date:	1993-05-21 04:00:00
Finish Date:	1993-12-21 05:00:00
Qual:	N
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901097
EPA ID:	CAD008382053
Site Name:	ROHR IND INC
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1993-02-18 05:00:00
Qual:	H
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901097
EPA ID:	CAD008382053
Site Name:	ROHR IND INC
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1985-01-01 06:00:00
Finish Date:	1985-01-01 06:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901097
EPA ID:	CAD008382053
Site Name:	ROHR IND INC
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	2
Start Date:	1985-01-01 06:00:00
Finish Date:	1985-08-01 05:00:00
Qual:	N
Current Action Lead:	St Perf

K58 **GOODRICH AEROSTRUCTURES, CHULA VISTA** **RCRA NonGen / NLR** **1026049475**
NNW **850 LAGOON DRIVE** **CAC003056223**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 6 of 14 in cluster K**

Relative:
Higher

Actual:
12 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2020-02-17 00:00:00.0
Handler Name:	GOODRICH AEROSTRUCTURES, CHULA VISTA
Handler Address:	850 LAGOON DRIVE
Handler City,State,Zip:	CHULA VISTA, CA 91910
EPA ID:	CAC003056223
Contact Name:	SHALOM RAYMOND
Contact Address:	850 LAGOON DRIVE
Contact City,State,Zip:	CHULA VISTA, CA 91910
Contact Telephone:	619-691-4142
Contact Fax:	Not reported
Contact Email:	NARDA@NORTHSOUTHMACHINERY.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	850 LAGOON DRIVE
Mailing City,State,Zip:	CHULA VISTA, CA 91910
Owner Name:	SHALOM RAYMOND
Owner Type:	Other
Operator Name:	SHALOM RAYMOND
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

GOODRICH AEROSTRUCTURES, CHULA VISTA (Continued) **1026049475**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-03-06 18:10:52.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SHALOM RAYMOND
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	850 LAGOON DRIVE
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-691-4142
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SHALOM RAYMOND
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	850 LAGOON DRIVE
Owner/Operator City,State,Zip:	CHULA VISTA, CA 91910
Owner/Operator Telephone:	619-691-4142
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

GOODRICH AEROSTRUCTURES, CHULA VISTA (Continued) **1026049475**

Historic Generators:
- Receive Date: 2020-02-17 00:00:00.0
- Handler Name: GOODRICH AEROSTRUCTURES, CHULA VISTA
- Federal Waste Generator Description: Not a generator, verified
- State District Owner: Not reported
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Code: 56299
- NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

K59 **GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRU** **CPS-SLIC S118504559**
NNW **850 LAGOON DRIVE** **CERS N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 7 of 14 in cluster K**

Relative: **Higher**
Actual: **12 ft.**

CPS-SLIC:
- Name: GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - SOUTH CAMPUS
- Address: 850 LAGOON DRIVE
- City,State,Zip: CHULA VISTA, CA 91910-2098
- Region: STATE
- **Facility Status: Open - Remediation**
- Status Date: 03/13/2020
- Global Id: SL209294204
- Lead Agency: SAN DIEGO RWQCB (REGION 9)
- Lead Agency Case Number: Not reported
- Latitude: 32.6257497210496
- Longitude: -117.09775686264
- Case Type: Cleanup Program Site
- Case Worker: TCA
- Local Agency: Not reported
- RB Case Number: 2090086
- File Location: Regional Board
- Potential Media Affected: Surface water, Aquifer used for drinking water supply
- Potential Contaminants of Concern: Asbestos Containing Materials (ACM), 1,4-Dioxane, Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Polychlorinated biphenyls (PCBs), Chromium VI, Other Metal, Other Petroleum, Polynuclear aromatic hydrocarbons (PAHs), Total Petroleum Hydrocarbons (TPH)
- Site History: Since 1941, structural and engine components for use in the aviation

GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - S (Continued) **S118504559**

and aerospace industry have been manufactured at the South Campus Property. Chemicals stored at the South Campus Property and used during manufacturing operations have been found in the soil, soil gas, and groundwater as reported in site environmental investigation reports and groundwater monitoring reports. The group of chemicals discharged include, but are not limited to, volatile organic compounds (VOCs), metals, petroleum hydrocarbons, polycyclic aromatic hydrocarbons (PAHs), and polychlorinated biphenyls (PCBs). In 1998, the San Diego Water Board issued CAO No. 98-08 to Rohr, Inc. CAO No. 98-08 requires the cleanup or abatement of wastes discharged from Rohrs manufacturing operations located at 850 Lagoon Drive in Chula Vista, California (North Campus Property and South Campus Property). CAO No. 98-08 includes directives to (1) conduct a site-wide environmental site assessment, (2) conduct a comprehensive storm water runoff sampling program, (3) conduct a comprehensive storm water conveyance system investigation, (4) perform a site-wide data compilation and evaluation, and (5) conduct interim remedial actions. The first four directives have been completed. On July 13, 1999, the City of Chula Vista, the Redevelopment Agency of the City of Chula Vista, the Port of San Diego, and Rohr entered into a Relocation Agreement. Thirty-eight acres of Rohr-owned property were transferred to the Port of San Diego and a 28-acre lease of Port tidelands was terminated as part of this Relocation Agreement for the entire South Campus Site. In 2002, Rohr vacated the South Campus Property and consolidated manufacturing operations to the North Campus Property. In 2007, the Port of San Diego demolished all buildings at the South Campus. In 2014, the San Diego Water Board issued CAO No. R9-2014-0019, which requires the cleanup or abatement of all wastes discharged to soil, soil gas, and groundwater from the manufacturing operations at the South Campus Property. CAO No. R9-2014-0019 supersedes CAO No. 98-08. Implementation of the soil Remedial Action Plan (RAP) is currently underway. The groundwater RAP will be finalized by Summer 2020.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - SOUTH CAMPUS
Address:	850 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910-2098
Site ID:	234448
CERS ID:	SL209294204
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213375

K60 **ROHR INC., A UTC AEROSPACE SYSTEMS COMPANY** **AST** **A100423963**
NNW **850 LAGOON DR** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 8 of 14 in cluster K**

Relative:
Higher

Actual:
12 ft.

AST:

Name:	ROHR INC., A UTC AEROSPACE SYSTEMS COMPANY
Address:	850 LAGOON DR
City/Zip:	CHULA VISTA,91910
Certified Unified Program Agencies:	Not reported
Owner:	UNITED TECHNOLOGIES AEROSPACE SYSTEMS, DBA ROHR INC.
Total Gallons:	Not reported
CERSID:	10123903
Facility ID:	37-000-102457
Business Name:	Rohr Inc., a UTC Aerospace Systems Company
Phone:	619-691-4111
Fax:	Not reported
Mailing Address:	850 LAGOON DRIVE, MAIL ZONE 1-C
Mailing Address City:	CHULA VISTA
Mailing Address State:	CA
Mailing Address Zip Code:	Not reported
Operator Name:	ROHR INC., a UTC AEROSPACE SYSTEMS COMPANY
Operator Phone:	619-691-4111
Owner Phone:	619-691-4111
Owner Mail Address:	850 LAGOON DR, MAIL ZONE 1-C
Owner State:	CA
Owner Zip Code:	91910
Owner Country:	United States
Property Owner Name:	Rohr, Inc., a UTC Aerospace Systems Company
Property Owner Phone:	619-691-4111
Property Owner Mailing Address:	850 LAGOON DR
Property Owner City:	Chula Vista
Property Owner Stat :	CA
Property Owner Zip Code:	91910
Property Owner Country:	United States
EPAID:	CAD008382053

K61 **BF GOODRICH AEROSPACE AEROSTRUCTURES** **LUST** **S104735649**
NNW **850 LAGOON DR** **CPS-SLIC** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910** **AST**
0.248 mi. **CHMIRS**
1312 ft. **Site 9 of 14 in cluster K** **Cortese**
EMI

Relative:
Higher

CERS

Actual:
12 ft.

LUST:

Name:	ROHR INDUSTRIES INC
Address:	850 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302732
Global Id:	T0607302732
Latitude:	32.6309853051255
Longitude:	-117.102119475603
Status:	Completed - Case Closed
Status Date:	08/02/2002
Case Worker:	Not reported
RB Case Number:	9UT420 2092900

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Local Agency: Not reported
File Location: Local Agency
Local Case Number: H02457-002
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607302732
Action Type: ENFORCEMENT
Date: 08/13/1987
Action: Notice of Responsibility

Global Id: T0607302732
Action Type: Other
Date: 08/13/1987
Action: Leak Reported

Global Id: T0607302732
Action Type: Other
Date: 08/05/1987
Action: Leak Began

Global Id: T0607302732
Action Type: Other
Date: 08/05/1987
Action: Leak Discovery

Global Id: T0607302732
Action Type: ENFORCEMENT
Date: 08/02/2002
Action: Closure/No Further Action Letter

Global Id: T0607302732
Action Type: Other
Date: 08/13/1987
Action: Leak Stopped

LUST:
Global Id: T0607302732
Status: Open - Case Begin Date
Status Date: 08/05/1987

Global Id: T0607302732
Status: Completed - Case Closed
Status Date: 08/02/2002

Name: ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607300932
Global Id: T0607300932
Latitude: 32.6268702313552
Longitude: -117.099232173663

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Status: Completed - Case Closed
Status Date: 01/23/1992
Case Worker: Not reported
RB Case Number: 9UT2162 2092900
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H02457-003
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

LUST:
Global Id: T0607300932
Action Type: Other
Date: 10/20/1987
Action: Leak Reported

Global Id: T0607300932
Action Type: Other
Date: 10/20/1987
Action: Leak Began

Global Id: T0607300932
Action Type: ENFORCEMENT
Date: 10/27/1987
Action: Notice of Responsibility

Global Id: T0607300932
Action Type: Other
Date: 10/20/1987
Action: Leak Discovery

Global Id: T0607300932
Action Type: Other
Date: 10/20/1987
Action: Leak Stopped

LUST:
Global Id: T0607300932
Status: Open - Case Begin Date
Status Date: 10/20/1987

Global Id: T0607300932
Status: Completed - Case Closed
Status Date: 01/23/1992

Name: GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - NORTH CAMPUS
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910-2098
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301766
Global Id: T0607301766
Latitude: 32.6305567093394
Longitude: -117.099537849426
Status: Completed - Case Closed

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Status Date:	05/08/2019
Case Worker:	TCA
RB Case Number:	9UT2999 2092900
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	1,1,1-Trichloroethane (TCA), Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Vinyl chloride, Polychlorinated biphenyls (PCBs), Chromium VI, Lead, Zinc, Gasoline, Total Petroleum Hydrocarbons (TPH)
Site History:	BF Goodrich Aerospace engages in the design and manufacture of technical equipment and technology used to build aircraft. The company provides various aerospace components, systems and services, such as fuel measurement, management, health monitoring, and diagnostic systems to the aerospace industry through a network of manufacturing, engineering and assembly plants, as well as service centers, including the airframe maintenance. It also supplies components, systems, and services to the aerospace industry. Administratively closed May 8, 2019. Salt Bath C70 is part of the larger cleanup and remediation efforts and will be addressed as part of Geotracker Site ID T10000001489 - GOODRICH AEROSTRUCTURES - NORTH CAMPUS.

LUST:

Global Id:	T0607301766
Contact Type:	Regional Board Caseworker
Contact Name:	TOM ALO
Organization Name:	SAN DIEGO RWQCB (REGION 9)
Address:	2375 NORTHSIDE DRIVE, SUITE 100
City:	SAN DIEGO
Email:	tom.alo@waterboards.ca.gov
Phone Number:	6195213375

LUST:

Global Id:	T0607301766
Action Type:	ENFORCEMENT
Date:	01/22/2013
Action:	Referral to Regional Board
Global Id:	T0607301766
Action Type:	Other
Date:	07/13/1992
Action:	Leak Reported
Global Id:	T0607301766
Action Type:	RESPONSE
Date:	03/14/2013
Action:	Other Report / Document
Global Id:	T0607301766
Action Type:	RESPONSE
Date:	03/14/2013
Action:	Other Report / Document
Global Id:	T0607301766
Action Type:	ENFORCEMENT

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Date: 02/11/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301766
Action Type: ENFORCEMENT
Date: 11/30/2009
Action: Letter - Notice

Global Id: T0607301766
Action Type: RESPONSE
Date: 06/04/1998
Action: Site Assessment Report

Global Id: T0607301766
Action Type: ENFORCEMENT
Date: 04/07/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301766
Action Type: RESPONSE
Date: 10/25/1999
Action: Site Investigation

Global Id: T0607301766
Action Type: Other
Date: 07/13/1992
Action: Leak Began

Global Id: T0607301766
Action Type: RESPONSE
Date: 03/20/1952
Action: Other Report / Document

Global Id: T0607301766
Action Type: RESPONSE
Date: 03/01/1966
Action: Operation and Maintenance Plan/Monitoring Report

Global Id: T0607301766
Action Type: ENFORCEMENT
Date: 07/23/1992
Action: Notice of Responsibility

Global Id: T0607301766
Action Type: Other
Date: 07/13/1992
Action: Leak Discovery

Global Id: T0607301766
Action Type: RESPONSE
Date: 11/13/1984
Action: Other Report / Document

Global Id: T0607301766
Action Type: RESPONSE
Date: 02/08/1968
Action: Monitoring Report - Other

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Global Id: T0607301766
Action Type: ENFORCEMENT
Date: 12/15/1952
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301766
Action Type: RESPONSE
Date: 01/01/1952
Action: Sensitive Receptor Survey Report - Regulator Responded

Global Id: T0607301766
Action Type: RESPONSE
Date: 08/06/1993
Action: Respond to Petition - Regulator Responded

Global Id: T0607301766
Action Type: Other
Date: 07/13/1992
Action: Leak Stopped

LUST:
Global Id: T0607301766
Status: Open - Case Begin Date
Status Date: 07/13/1992

Global Id: T0607301766
Status: Open - Site Assessment
Status Date: 07/23/1992

Global Id: T0607301766
Status: Completed - Case Closed
Status Date: 05/08/2019

Name: ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301464
Global Id: T0607301464
Latitude: 32.6271683515917
Longitude: -117.101222276688
Status: Completed - Case Closed
Status Date: 06/12/1998
Case Worker: Not reported
RB Case Number: 9UT2711 2092900
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H02457-009
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

LUST:
Global Id: T0607301464
Action Type: ENFORCEMENT

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Date: 06/08/1998
Action: Closure/No Further Action Letter

Global Id: T0607301464
Action Type: Other
Date: 07/13/1993
Action: Leak Reported

Global Id: T0607301464
Action Type: ENFORCEMENT
Date: 04/27/1998
Action: Clean Up Fund - Case Closure Review Summary Report (RSR) - #H02457-009

Global Id: T0607301464
Action Type: Other
Date: 06/24/1993
Action: Leak Began

Global Id: T0607301464
Action Type: Other
Date: 06/24/1993
Action: Leak Discovery

Global Id: T0607301464
Action Type: Other
Date: 06/24/1993
Action: Leak Stopped

LUST:
Global Id: T0607301464
Status: Open - Case Begin Date
Status Date: 06/24/1993

Global Id: T0607301464
Status: Completed - Case Closed
Status Date: 06/12/1998

CPS-SLIC:
Name: GOODRICH AEROSTRUCTURES / ROHR - ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 02/18/1993
Global Id: T0608184113
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H02457-004
Latitude: 32.623225325238
Longitude: -117.097504734993
Case Type: Cleanup Program Site
Case Worker: Not reported
Local Agency: Not reported
RB Case Number: 2092900
File Location: Local Agency
Potential Media Affected: Not reported

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Potential Contaminants of Concern: Not reported
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Name: GOODRICH AEROSTRUCTURES
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 06/01/2012
Global Id: T0607399048
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H02457-011
Latitude: 32.6285143463431
Longitude: -117.099345002655
Case Type: Cleanup Program Site
Case Worker: LA
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: 9UT3961
File Location: Local Agency
Potential Media Affected: Soil
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Go to "Site Maps/Documents" tab for Closure Documents

Click here to access the California GeoTracker records for this facility:

Name: ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 12/16/1986
Global Id: T0607301189
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H02457-001
Latitude: 32.6288038763338
Longitude: -117.099199987155
Case Type: Cleanup Program Site
Case Worker: Not reported
Local Agency: Not reported
RB Case Number: 9UT2424 2092900
File Location: Local Agency
Potential Media Affected: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Diesel
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Name: GOODRICH AEROSTRUCTURES / ROHR - ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 03/21/1991
Global Id: T0608190387
Lead Agency: SAN DIEGO COUNTY LOP

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Lead Agency Case Number:	H02457-010
Latitude:	32.6273852103302
Longitude:	-117.09835767746
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	2092900
File Location:	Local Agency
Potential Media Affected:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Name:	GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - NORTH CAMPUS - EASTERN PARCEL A
Address:	850 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910-2098
Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	11/17/2017
Global Id:	T10000011095
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.6308
Longitude:	-117.09765
Case Type:	Cleanup Program Site
Case Worker:	TCA
Local Agency:	Not reported
RB Case Number:	2092900
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Soil
Potential Contaminants of Concern:	1,1,1-Trichloroethane (TCA), Dichloroethene (DCE), Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Toluene, Xylene
Site History:	The subject site comprises two parcels that are part of the Rohr manufacturing facility. Two buildings (Buildings 99 and 100) are located on APN 567-022-30-00; one building (Building 29) is located on the eastern portion of 571-330-29-00. Rohr purchased APN 567-022-30-00 in 1986. The parcel has been used primarily for administrative purposes. Test laboratories are located in Building 100. Building 29 on the eastern portion of 571-330-29-00 was constructed in the late 1950s and has primarily been used for tooling and machining, and office space for most of its history. The northernmost portion served as the Maintenance Department for the facility. The building currently houses a number of laboratories, kitting, an After Market Spares Warehouse, Service Center and FAI repairs, storage, tool calibration, product development and office space. Prior to Rohrfs ownership, the subject site had a variety of other historical uses, including agriculture, truck engine repair, and a possible lumber yard.

Click here to access the California GeoTracker records for this facility:

Name:	GOODRICH AEROSTRUCTURES / ROHR - ROHR INDUSTRIES INC
Address:	850 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	02/01/2013
Global Id:	T0607399259
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H02457-013
Latitude:	32.6286807927867
Longitude:	-117.099441289902
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	9UT4069 2092900
File Location:	Local Agency
Potential Media Affected:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Not reported
Site History:	An authorized release was observed during soil sampling for the removal of a 550 gallon underground storage tank (UST) discovered some remodeling being conducted in the Oiler Shed area beneath the existing canopy. The former use of the UST was not known. The UST contained approximately 24 inches of liquid when discovered with approximately six inches of sludge on the bottom. Of the 24 inches of liquid, several inches was reported to be free hydrocarbon product. A sample was obtained of the liquid in the UST and was analyzed. The liquid was reported to be within the carbon range of kerosene and in the range of waste oil. Volatile Organic Vapors (VOCs) found in the liquid were reported to be 1,1-dichloroethane at a concentration of 37,500 a%g/l and Freon 113 at a concentration of 48,500 a%g/l. The single wall steel UST and associated piping was removed on April 24, 2000, after the contents of the tank were removed by Triad Marine & Industrial Cleaning Corp. Corrosion and several holes were noted on the UST by the Department of Environmental Health (DEH) inspector. Total Recoverable Petroleum Hydrocarbons (TRPH) up to 137 mg/kg were observed at a side-wall sample directed by the inspector. Five additional soil samples were collected at the request of BF Goodrich personnel. The additional soil sampling analytical results included low levels of Acetone, 2-butanone (MEK), 1,1-dichloroethane, 1,2-dichloroethane, cis-1,2-dichloroethene, and 1, 1, 1-tricholoethane. The Underground Storage Tank Removal and Soil Sampling Report requested no further action as a low risk groundwater case. DEH directed that the groundwater impacts be evaluated and that a complete site assessment report be submitted in order to evaluate the case for closure. The area of investigation is located along the former high tide line of San Diego Bay and is underlain by artificially compacted fill. Fill materials are located at the surface grade to depths of 7 to 8 feet below ground surface (bgs). The fill consists of a mixture of clay and silty sand with gravel. Bay deposits and the Bay Point Formation encountered beneath the fill consist mostly of clay and sandy clay to the maximum depth investigated at approximately 12 feet bgs. The site is located within a designated beneficial use water basin, and the nearest surface water body is the San Diego Bay which is located approximately 2,500 feet west of the site. One soil boring was advanced on February 15, 2012 in the center of the former tank pit to a depth of approximately 12 feet bgs. A temporary slotted PVC casing was placed in the boring to collect a groundwater sample. The groundwater analytical results were Non-detect for TRPH, however the Trichloroethene concentration was observed at 74,000 a%g/l. Additional VOCs included in the

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

groundwater sample results were 1,1-Dichloroethane, 1,2-Dichloroethane, 1,1-Dichloethene, cis-1,2-Dichloroethene, and Vinyl Chloride. *The Trichloroethene (TCE) observed in groundwater in the investigation is above the Maximum Contaminant Levels for a beneficial groundwater use basin. Goodrich is investigating TCE in groundwater site-wide under the oversight of the Regional Water Quality Control Board (RWQCB) in accordance with Cleanup and Abatement Order No. 98-08. The RWQCB was notified of the proposed closure of this Voluntary Assistance Program (VAP) case on August 11, 2011 and they stated they had no issues concerning this closure. The Closure is for the TRPH contamination only. The remaining TRPH contamination does not pose a threat to human health or the environment.

Click here to access the California GeoTracker records for this facility:

AST:

Name:	ROHR INC DBA BF GOODRICH
Address:	850 LAGOON DR
City/Zip:	CHULA VISTA,
Certified Unified Program Agencies:	San Diego
Owner:	ROHR INC DBA BF GOODRICH
Total Gallons:	26363
CERSID:	Not reported
Facility ID:	Not reported
Business Name:	Not reported
Phone:	Not reported
Fax:	Not reported
Mailing Address:	Not reported
Mailing Address City:	Not reported
Mailing Address State:	Not reported
Mailing Address Zip Code:	Not reported
Operator Name:	Not reported
Operator Phone:	Not reported
Owner Phone:	Not reported
Owner Mail Address:	Not reported
Owner State:	Not reported
Owner Zip Code:	Not reported
Owner Country:	Not reported
Property Owner Name:	Not reported
Property Owner Phone:	Not reported
Property Owner Mailing Address:	Not reported
Property Owner City:	Not reported
Property Owner Stat :	Not reported
Property Owner Zip Code:	Not reported
Property Owner Country:	Not reported
EPAID:	Not reported

CHMIRS:

Name:	Not reported
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91910
OES Incident Number:	10-3514
OES notification:	06/08/2010
OES Date:	Not reported
OES Time:	Not reported

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Date Completed:	**Not reported**
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
More Than Two Substances Involved?:	Not reported
Resp Agncy Personel # Of Decontaminated:	Not reported
Responding Agency Personel # Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:	Not reported
Others Number Of Decontaminated:	Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Industrial Plant
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Lbs.
Other:	Not reported
Date/Time:	1351
Year:	2010
Agency:	Goodrich Aero Structures
Incident Date:	6/8/2010
Admin Agency:	San Diego County Health Services Department
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Nitric Acid
Quantity Released:	3998
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	Not reported
Number of Injuries:	Not reported
Number of Fatalities:	Not reported
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	RP states that a tank was over filled causing the release of product into secondary containment. No waterways were affected.

CORTESE:

Name:	ROHR INDUSTRIES INC
Address:	850 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607301464
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

Name:	ROHR INDUSTRIES INC
Address:	850 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607300932
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

File Name:	Active Open
Name:	ROHR INDUSTRIES INC
Address:	850 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607302732
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

EMI:

Name:	ROHR INDUSTRIES.
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91912
Year:	1998
County Code:	37
Air Basin:	SD
Facility ID:	99
Air District Name:	SD
SIC Code:	3728
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	23
Reactive Organic Gases Tons/Yr:	15
Carbon Monoxide Emissions Tons/Yr:	3
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ROHR INDUSTRIES.
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91912
Year:	1999
County Code:	37
Air Basin:	SD
Facility ID:	99
Air District Name:	SD
SIC Code:	3728

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	23
Reactive Organic Gases Tons/Yr:	15
Carbon Monoxide Emissions Tons/Yr:	3
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ROHR INDUSTRIES.
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91912
Year:	2000
County Code:	37
Air Basin:	SD
Facility ID:	99
Air District Name:	SD
SIC Code:	3728
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	39
Reactive Organic Gases Tons/Yr:	21
Carbon Monoxide Emissions Tons/Yr:	4
NOX - Oxides of Nitrogen Tons/Yr:	5
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers and Smllr Tons/Yr:	2

Name:	ROHR INDUSTRIES
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91912
Year:	2001
County Code:	37
Air Basin:	SD
Facility ID:	99
Air District Name:	SD
SIC Code:	3728
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	34
Reactive Organic Gases Tons/Yr:	19
Carbon Monoxide Emissions Tons/Yr:	4
NOX - Oxides of Nitrogen Tons/Yr:	9
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers and Smllr Tons/Yr:	2

Name:	ROHR INDUSTRIES.
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91912
Year:	2002
County Code:	37
Air Basin:	SD

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Facility ID:	99
Air District Name:	SD
SIC Code:	3728
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	42
Reactive Organic Gases Tons/Yr:	22
Carbon Monoxide Emissions Tons/Yr:	8
NOX - Oxides of Nitrogen Tons/Yr:	9
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers and Smllr Tons/Yr:	2

Name:	ROHR INDUSTRIES.
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91912
Year:	2003
County Code:	37
Air Basin:	SD
Facility ID:	99
Air District Name:	SD
SIC Code:	3728
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	42
Reactive Organic Gases Tons/Yr:	22
Carbon Monoxide Emissions Tons/Yr:	8
NOX - Oxides of Nitrogen Tons/Yr:	9
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers and Smllr Tons/Yr:	2

Name:	ROHR INDUSTRIES.
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91912
Year:	2004
County Code:	37
Air Basin:	SD
Facility ID:	99
Air District Name:	SD
SIC Code:	3728
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	41.72271396
Reactive Organic Gases Tons/Yr:	21.61623796
Carbon Monoxide Emissions Tons/Yr:	7.564876751
NOX - Oxides of Nitrogen Tons/Yr:	9.027076256
SOX - Oxides of Sulphur Tons/Yr:	0.05412081
Particulate Matter Tons/Yr:	2.275386393
Part. Matter 10 Micrometers and Smllr Tons/Yr:	2.275386393

CERS:

Name:	ROHR INDUSTRIES INC
Address:	850 LAGOON DRIVE

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

City,State,Zip: CHULA VISTA, CA 91910
Site ID: 200498
CERS ID: T0607301464
CERS Description: Leaking Underground Storage Tank Cleanup Site

Name: ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 200498
CERS ID: T0607302732
CERS Description: Leaking Underground Storage Tank Cleanup Site

Name: GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - NORTH CAMPUS - SALT B
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910-2098
Site ID: 205622
CERS ID: T0607301766
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

Name: GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - NORTH CAMPUS - SALT B
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910-2098
Site ID: 205622
CERS ID: T0608187932
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

Name: GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - NORTH CAMPUS - SALT B
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910-2098
Site ID: 205622
CERS ID: T10000001489

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

Name: ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 200498
CERS ID: T0607300932
CERS Description: Leaking Underground Storage Tank Cleanup Site

Name: ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 200498
CERS ID: T0607301189
CERS Description: Cleanup Program Site

Name: GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - NORTH CAMPUS - SALT B
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910-2098
Site ID: 205622
CERS ID: T10000011095
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

Name: ROHR INC DBA GOODRICH AEROSTRUCTURES GROUP
Address: 850 LAGOON DR
City,State,Zip: CHULA VISTA, CA 91910-2001
Site ID: 490805
CERS ID: 110000478518
CERS Description: US EPA Air Emission Inventory System (EIS)

Affiliation:
Affiliation Type Desc: Environmental Contact
Entity Name: MELIZA J TOTANES LINCOLN
Entity Title: SENIOR ENVIRONMENTAL ANALYST

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Affiliation Address:	850 LAGOON DR 1C
Affiliation City:	CHULAVISTA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner
Entity Name:	ROHRNA ; NA A UTC ARSPC SYS
Entity Title:	Not reported
Affiliation Address:	850 LAGOON DR
Affiliation City:	CHULAVISTA
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Environmental Contact
Entity Name:	KATHLEEN REINERT
Entity Title:	Not reported
Affiliation Address:	850 LAGOON DR NA MAIL ZONE 1-C
Affiliation City:	CHULAVISTA
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Environmental Contact
Entity Name:	MELIZA J TOTANES-LINCOLN
Entity Title:	SR ENV ANALYST, GENERALIS
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Public Contact
Entity Name:	Paul Johnson
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Public Contact
Entity Name:	Shawn Ivey
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

Name: GOODRICH AEROSTRUCTURES / ROHR - ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 238661
CERS ID: T0607399259
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

Name: GOODRICH AEROSTRUCTURES / ROHR - ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 238661
CERS ID: T0608184113
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

Name: GOODRICH AEROSTRUCTURES / ROHR - ROHR INDUSTRIES INC
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 238661
CERS ID: T0608190387
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

Name: GOODRICH AEROSTRUCTURES
Address: 850 LAGOON DRIVE

BF GOODRICH AEROSPACE AEROSTRUCTURES (Continued) **S104735649**

City,State,Zip: CHULA VISTA, CA 91910
Site ID: 257670
CERS ID: T0607399048
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: LAURIE APECECHEA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

K62 **BF GOODRICH, AEROSTRUCTURES GROUP** **CPS-SLIC S108054502**
NNW **850 LAGOON DRIVE** **CHMIRS N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 10 of 14 in cluster K**

Relative: Higher

Actual: 12 ft.

CPS-SLIC:
No Details: No Details

CHMIRS:
Name: Not reported
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910
OES Incident Number: 08-8352
OES notification: 11/20/2008
OES Date: Not reported
OES Time: Not reported
Date Completed: Not reported
Property Use: Not reported
Agency Id Number: Not reported
Agency Incident Number: Not reported
Time Notified: Not reported
Time Completed: Not reported
Surrounding Area: Not reported
Estimated Temperature: Not reported
Property Management: Not reported
More Than Two Substances Involved?: Not reported
Resp Agncy Personel # Of Decontaminated: Not reported
Responding Agency Personel # Of Injuries: Not reported
Responding Agency Personel # Of Fatalities: Not reported
Others Number Of Decontaminated: Not reported
Others Number Of Injuries: Not reported

BF GOODRICH, AEROSTRUCTURES GROUP (Continued) **S108054502**

Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA DOT PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Industrial Plant
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Gal(s)
Other:	Not reported
Date/Time:	1400
Year:	2008
Agency:	Goodrich Aerospace
Incident Date:	11/20/2008
Admin Agency:	San Diego County Health Services Dept.
Amount:	Not reported
Contained:	Yes
Site Type:	Not reported
E Date:	Not reported
Substance:	Nitric/ Ammonia Biflouride
Quantity Released:	.5
Unknown:	Not reported
Substance #2:	Not reported
Substance #3:	Not reported
Evacuations:	5
Number of Injuries:	0
Number of Fatalities:	0
#1 Pipeline:	Not reported
#2 Pipeline:	Not reported
#3 Pipeline:	Not reported
#1 Vessel >= 300 Tons:	Not reported
#2 Vessel >= 300 Tons:	Not reported
#3 Vessel >= 300 Tons:	Not reported
Evacs:	Not reported
Injuries:	Not reported
Fatals:	Not reported
Comments:	Not reported
Description:	Caller states that a drag out screen from a process tank was leaking and emitted vapors. 5 people were evacuated to the Scripps and Sharps Chula Vista hospitals.

K63 **SAN DIEGO UNIFIED PORT DISTRICT** **RCRA-SQG** **1010312847**
NNW **850 LAGOON DRIVE** **CAC002577707**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 11 of 14 in cluster K**

Relative: RCRA-SQG:
Higher

Actual: Date Form Received by Agency: 2006-02-28 00:00:00.0
12 ft. Handler Name: SAN DIEGO UNIFIED PORT DISTRICT
Handler Address: 850 LAGOON DRIVE
Handler City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAC002577707
Contact Name: LARRY MCCAULEY
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 619-866-6470
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 09
Land Type: District
Federal Waste Generator Description: Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: RECREATIONAL & ENV.SRVS. DEPT
Mailing City,State,Zip: SAN DIEGO, CA 92112
Owner Name: PORT OF SAN DIEGO
Owner Type: District
Operator Name: LARRY MCCAULEY
Operator Type: District
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No
Underground Injection Control: No
Off-Site Waste Receipt: No
Universal Waste Indicator: No
Universal Waste Destination Facility: No
Federal Universal Waste: No
Active Site Fed-Reg Treatment Storage and Disposal Facility: Not reported
Active Site Converter Treatment storage and Disposal Facility: Not reported
Active Site State-Reg Treatment Storage and Disposal Facility: Not reported
Active Site State-Reg Handler: ---
Federal Facility Indicator: Not reported
Hazardous Secondary Material Indicator: NN
Sub-Part K Indicator: Not reported
Commercial TSD Indicator: No
Treatment Storage and Disposal Type: Not reported
2018 GPRA Permit Baseline: Not on the Baseline
2018 GPRA Renewals Baseline: Not on the Baseline
Permit Renewals Workload Universe: Not reported

SAN DIEGO UNIFIED PORT DISTRICT (Continued) **1010312847**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2007-03-05 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	LARRY MCCAULEY
Legal Status:	District
Date Became Current:	2004-05-17 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PORT OF SAN DIEGO
Legal Status:	District

SAN DIEGO UNIFIED PORT DISTRICT (Continued) **1010312847**

Date Became Current: 1963-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: P.O. BOX 120448
Owner/Operator City,State,Zip: SAN DIEGO, CA 92112
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: LARRY MCCAULEY
Legal Status: District
Date Became Current: 2004-05-17 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PORT OF SAN DIEGO
Legal Status: District
Date Became Current: 1963-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: P.O. BOX 120448
Owner/Operator City,State,Zip: SAN DIEGO, CA 92112
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2006-02-28 00:00:00.0
Handler Name: SAN DIEGO UNIFIED PORT DISTRICT
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2006-02-28 00:00:00.0
Handler Name: SAN DIEGO UNIFIED PORT DISTRICT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes

SAN DIEGO UNIFIED PORT DISTRICT (Continued) **1010312847**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 92119
NAICS Description: OTHER GENERAL GOVERNMENT SUPPORT

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

K64 **GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRU** **CPS-SLIC** **S118504617**
NNW **850 LAGOON DRIVE** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 12 of 14 in cluster K**

Relative: **Higher**
Actual: **12 ft.**

CPS-SLIC:
Name: GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - NORTH CAMPUS - TANK 34, BLDG 1
Address: 850 LAGOON DRIVE
City,State,Zip: CHULA VISTA, CA 91910-2098
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 05/08/2019
Global Id: T0608187932
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number: Not reported
Latitude: 32.6292284883906
Longitude: -117.099366188049
Case Type: Cleanup Program Site
Case Worker: TCA
Local Agency: Not reported
RB Case Number: 2092900
File Location: Local Agency
Potential Media Affected: Aquifer used for drinking water supply
Potential Contaminants of Concern: 1,1,1-Trichloroethane (TCA), Other Chlorinated Hydrocarbons, Other Solvent or Non-Petroleum Hydrocarbon, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Vinyl chloride
Site History: BF Goodrich Aerospace engages in the design and manufacture of technical equipment and technology used to build aircraft. The company provides various aerospace components, systems and services, such as fuel measurement, management, health monitoring, and diagnostic systems to the aerospace industry through a network of manufacturing, engineering and assembly plants, as well as service centers, including the airframe maintenance. It also supplies components, systems, and services to the aerospace industry. Administratively closed May 8, 2019. T34 in Building No. 1 is a sump release and is part of the larger cleanup and remediation efforts and will be addressed as part of Geotracker Site ID T10000001489 - GOODRICH AEROSTRUCTURES - NORTH CAMPUS.

GOODRICH AEROSTRUCTURES / ROHR - GOODRICH AEROSTRUCTURES - N (Continued) **S118504617**

Click here to access the California GeoTracker records for this facility:

K65 **ROHR INC., A UTC AEROSPACE SYSTEMS COMPANY** **UST** **U004261883**
NNW **850 LAGOON DR** **N/A**
1/8-1/4 **CHULA VISTA, CA 91910**
0.248 mi.
1312 ft. **Site 13 of 14 in cluster K**

Relative:
Higher

Actual:
12 ft.

UST:

Name:	ROHR INC., A UTC AEROSPACE SYSTEMS COMPANY
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	37-000-102457
Permitting Agency:	San Diego County Department of Environme
Latitude:	32.6304121
Longitude:	-117.0997095

Name:	ROHR INC., A COLLINS AEROSPACE COMPANY
Address:	850 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	37-000-102457
Permitting Agency:	San Diego County Department of Environmental Health
Latitude:	32.6304121
Longitude:	-117.0997095

L66 **CHEVRON #9-6056** **SAN DIEGO CO. SAM** **U003938721**
East **695 H ST** **UST** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910** **San Diego Co. HMMD**
0.251 mi. **SAN DIEGO CO LOP**
1325 ft. **Site 1 of 5 in cluster L** **CERS**

Relative:
Higher

Actual:
31 ft.

SAN DIEGO CO. SAM:

Name:	CHEVRON #9-6056
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Case Number:	H13127-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**LOP - State Fund**
Facility Type:	Drinking Water Aquifer Impacted
Facility Status:	Closed Case
Date:	9/18/2007
Date Began:	10/17/1995

UST:

Name:	CHEVRON #9-6056
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	H13127
Permitting Agency:	SAN DIEGO COUNTY
Latitude:	32.631451
Longitude:	-117.092321

HMMD SAN DIEGO:

Name:	CHEVRON #9-6056

CHEVRON #9-6056 (Continued) **U003938721**

Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	113127
Business Type:	6HK29
EPA Id Number:	CAD982487035
APN:	567-190-27-00
Last HMMD Inspection:	06/07/2006
Facility Telephone:	619-422-1316
Permit Status:	INAC
Permit Expiration:	07/31/2006
Date Last Updated:	11/02/2012
Facility Owner:	CHEVRON USA INC.
Facility Mailing Address:	PO BOX 6004
Facility Mailing City:	SAN RAMON
Facility Mailing State:	CA
Facility Mailing Zip:	94583-
UST Owner:	CHEVRON USA INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Violations Inactive Permits:

Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	05/12/2003
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	Inactive Permit

Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	05/12/2003
Violation Code:	6HV3152
Violation:	ALL MAINT/MONITOR RECORDS NOT AVAILABLE
Violation Citation:	All maintenance/monitoring/calibration/ repair records not available. 25293; 2712 (b)
Activity:	Inactive Permit

Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	05/12/2003
Violation Code:	6HV3113
Violation:	2NDRY CONT TEST NOT SENT TO CUPA
Violation Citation:	Secondary Containment testing not submitted to CUPA within 30 days. 2637(a)(4)
Activity:	Inactive Permit

Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	05/12/2003
Violation Code:	6HV3255
Violation:	SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation:	Spill container is not in good condition and/or liquid free.

CHEVRON #9-6056 (Continued) **U003938721**

	2635(b)(1), 2636(a)(1)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	05/12/2003
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	05/12/2003
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	05/12/2003
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	05/12/2003
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3102
Violation:	OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3105
Violation:	NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation:	Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012

CHEVRON #9-6056 (Continued) **U003938721**

Inspection Date:	04/30/2004
Violation Code:	6HV3255
Violation:	SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation:	Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3256
Violation:	NO FUNCTIONAL DRAIN BOX/BACKUP
Violation Citation:	Fill box drain not functional and backup system is not available. 2635(b)(1)(C)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3258
Violation:	SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation:	Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3258
Violation:	SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation:	Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3258
Violation:	SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation:	Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3258
Violation:	SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation:	Sensors not placed adequately and/or at low point in sumps. 2641(a),

CHEVRON #9-6056 (Continued) **U003938721**

	25291(a)(7)(C)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV0209
Violation:	WASTE ONSITE >90/180/270 DAYS
Violation Citation:	Hazardous waste is stored in excess of allowable time period (90 days) without a State permit or written variance. CCR 25201(a) & 66262.34(a)&(c)
Activity:	Inactive Permit
Permit Number:	113127
Update Date:	11/02/2012
Inspection Date:	04/30/2004
Violation Code:	6HV0215
Violation:	OIL FILTERS IMPROPERLY MANAGED
Violation Citation:	Used oil filters not properly drained, stored, or labeled prior to transport for the purpose of metal reclamation. CCR 66266.130

CHEVRON #9-6056 (Continued) **U003938721**

Activity: Inactive Permit

UST:

UST Name:	UNDERGROUND TANK 113127 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	113127
Tank Type:	SINGLE WALL
Additional Id:	1
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1995-10-17 00:00:00
Year Installed:	1970-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 113127 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	113127
Tank Type:	SINGLE WALL
Additional Id:	2
Capacity Gallons:	10000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1995-10-17 00:00:00
Year Installed:	1970-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 113127 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	113127
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	5000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1995-10-17 00:00:00
Year Installed:	1970-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 113127 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	113127

CHEVRON #9-6056 (Continued) **U003938721**

Tank Type:	SINGLE WALL
Additional Id:	4
Capacity Gallons:	1000
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1995-10-17 00:00:00
Year Installed:	1970-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	Not reported
Monitor Code:	07
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY
UST Name:	UNDERGROUND TANK 113127 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	113127
Tank Type:	DOUBLE WALL
Additional Id:	NT1857 UNLEADED/AT5135
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2005-09-08 00:00:00
Year Installed:	1995-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.
UST Name:	UNDERGROUND TANK 113127 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	113127
Tank Type:	DOUBLE WALL
Additional Id:	NT1857 UNLEADED/AT5135
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2005-09-08 00:00:00
Year Installed:	1995-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.
UST Name:	UNDERGROUND TANK 113127 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	113127
Tank Type:	DOUBLE WALL
Additional Id:	NT1857 UNLEADED/AT5135
Capacity Gallons:	12000
UST Contents:	MIDGRADE UNLEADED
Other Content Info:	MIDGRADE UNLEADED
Reg Status:	REMOVED

CHEVRON #9-6056 (Continued) **U003938721**

Remove Close Date:	2005-09-08 00:00:00
Year Installed:	1995-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.
UST Name:	UNDERGROUND TANK 113127 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	113127
Tank Type:	DOUBLE WALL
Additional Id:	NT1857/AT5135
Capacity Gallons:	1000
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2005-09-08 00:00:00
Year Installed:	1995-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	GRAVITY
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

SAN DIEGO CO LOP:

Name:	CHEVRON #9-6056
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1995-LSAM-H13127-001
Record Status:	Completed
Opened Date:	10/17/1995
Parcel Number:	567-190-27-00
Case Type:	LOP - Local Oversight Program
Historical Name:	CHEVRON #9-6056
SWRCB Global ID:	T0607301886
Funding:	S - LOP State Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	10/17/1995
Census Tract:	125.01
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6301024
Longitude:	-117.0936705
X MapCoord:	6301906.772
Y MapCoord:	1810109.247

CERS:

Name:	CHEVRON #9-6056
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Site ID:	235121

CHEVRON #9-6056 (Continued) **U003938721**

CERS ID: T0607301886
CERS Description: Leaking Underground Storage Tank Cleanup Site

---

L67 **CHEVRON #9-6056** **LUST** **S101669511**
East **695 H ST** **CPS-SLIC** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910** **SWEEPS UST**
0.251 mi. **Cortese**
1325 ft. **Site 2 of 5 in cluster L** **EMI**
HIST CORTESE
Relative: **CERS**
Higher

Actual: **31 ft.**

LUST REG 9:
Region: 9
Status: Preliminary site assessment underway
Case Number: 9UT3119
Local Case: H13127-001
Substance: Gasoline
Qty Leaked: 0
Abate Method: Not reported
Local Agency: San Diego
How Found: Not reported
How Stopped: Not reported
Source: Tank
Cause: Corrosion
Lead Agency: Local Agency
Case Type: Soil only
Date Found: 10/17/1995
Date Stopped: 10/17/1995
Confirm Date: 10/17/1995
Submit Workplan: Not reported
Prelim Assess: 10/26/1995
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 10/17/1995
Enforce Date: Not reported
Closed Date: Not reported
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 908.32
GW Depth: Not reported
Beneficial Use: Municipal groundwater use
NPDES Number: Not reported
Priority: Low priority. Priority ranking can change over time.
File Dispn: Administratively opened on database, however no file physically exists
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

LUST:
Name: CHEVRON #9-6056
Address: 695 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301886

CHEVRON #9-6056 (Continued) **S101669511**

Global Id: T0607301886
Latitude: 32.6299965097104
Longitude: -117.093642354012
Status: Completed - Case Closed
Status Date: 09/18/2007
Case Worker: Not reported
RB Case Number: 9UT3119
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H13127-001
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607301886
Action Type: Other
Date: 10/17/1995
Action: Leak Reported

Global Id: T0607301886
Action Type: ENFORCEMENT
Date: 09/19/2007
Action: Closure/No Further Action Letter

Global Id: T0607301886
Action Type: Other
Date: 10/17/1995
Action: Leak Began

Global Id: T0607301886
Action Type: Other
Date: 10/17/1995
Action: Leak Discovery

Global Id: T0607301886
Action Type: ENFORCEMENT
Date: 10/26/1995
Action: Notice of Responsibility

Global Id: T0607301886
Action Type: Other
Date: 10/17/1995
Action: Leak Stopped

LUST:
Global Id: T0607301886
Status: Open - Case Begin Date
Status Date: 10/17/1995

Global Id: T0607301886
Status: Completed - Case Closed
Status Date: 09/18/2007

CPS-SLIC:
Name: FORMER CHEVRON

CHEVRON #9-6056 (Continued) **S101669511**

Address:	695 H STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	02/10/2011
Global Id:	T10000002801
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H13127-002
Latitude:	32.630102
Longitude:	-117.09367
Case Type:	Cleanup Program Site
Case Worker:	KH
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Soil Vapor
Potential Contaminants of Concern:	Gasoline
Site History:	VAP Case. - This case was opened to allow the County to review a proposed development on the subject property. The review is to determine if the proposed development will be impacted by the presence of residual soil and groundwater impacts.

Click here to access the California GeoTracker records for this facility:

SWEEPS UST:

Name:	PAULS CHEVRON SERVICE
Address:	695 H ST
City:	CHULA VISTA
Status:	Active
Comp Number:	13127
Number:	9
Board Of Equalization:	44-022710
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013127-000001
Tank Status:	A
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	4

Name:	PAULS CHEVRON SERVICE
Address:	695 H ST
City:	CHULA VISTA
Status:	Active
Comp Number:	13127
Number:	9
Board Of Equalization:	44-022710
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013127-000002

CHEVRON #9-6056 (Continued) **S101669511**

Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: PAULS CHEVRON SERVICE
Address: 695 H ST
City: CHULA VISTA
Status: Active
Comp Number: 13127
Number: 9
Board Of Equalization: 44-022710
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-013127-000003
Tank Status: A
Capacity: 5000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: PAULS CHEVRON SERVICE
Address: 695 H ST
City: CHULA VISTA
Status: Active
Comp Number: 13127
Number: 9
Board Of Equalization: 44-022710
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-013127-000004
Tank Status: A
Capacity: 1000
Active Date: Not reported
Tank Use: PETROLEUM
STG: W
Content: Not reported
Number Of Tanks: Not reported

CORTESE:
Name: CHEVRON #9-6056
Address: 695 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607301886
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED

CHEVRON #9-6056 (Continued) **S101669511**

Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

EMI:

Name:	CHEVRON / H STREET CHULA VISTA
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Year:	1999
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON / H STREET CHULA VISTA
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Year:	2000
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

CHEVRON #9-6056 (Continued) **S101669511**

Name:	CHEVRON / H STREET CHULA VISTA
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Year:	2001
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON / H STREET CHULA VISTA
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Year:	2002
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON H STREET CHULA VISTA
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Year:	2003
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

CHEVRON #9-6056 (Continued) **S101669511**

Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: CHEVRON H STREET CHULA VISTA
Address: 695 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Year: 2004
County Code: 37
Air Basin: SD
Facility ID: 4493
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2.9149918
Reactive Organic Gases Tons/Yr: 2.9149918
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: CHEVRON H STREET CHULA VISTA
Address: 695 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Year: 2005
County Code: 37
Air Basin: SD
Facility ID: 4493
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2.9149918
Reactive Organic Gases Tons/Yr: 2.9149918
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: CHEVRON
Address: 695 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Year: 2006
County Code: 37
Air Basin: SD
Facility ID: 4493
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2.63
Reactive Organic Gases Tons/Yr: 2.63

CHEVRON #9-6056 (Continued) **S101669511**

Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Year:	2007
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.63
Reactive Organic Gases Tons/Yr:	2.63
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Year:	2008
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.63
Reactive Organic Gases Tons/Yr:	2.63
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Year:	2009
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported

CHEVRON #9-6056 (Continued) **S101669511**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.6299999999999999
Reactive Organic Gases Tons/Yr:	2.6299999999999999
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	695 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Year:	2010
County Code:	37
Air Basin:	SD
Facility ID:	4493
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.6299999999999999
Reactive Organic Gases Tons/Yr:	2.6299999999999999
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

HIST CORTESE:

edr_fname:	CHEVRON #9-6056
edr_fadd1:	695 H
City,State,Zip:	CHULA VISTA, CA 92010
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT3119

CERS:

Name:	FORMER CHEVRON
Address:	695 H STREET
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	257587
CERS ID:	T10000002801
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	KEVIN HEATON - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

CHEVRON #9-6056 (Continued) **S101669511**

Name: CHEVRON
Address: 695 H ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 459192
CERS ID: 110002828012
CERS Description: US EPA Air Emission Inventory System (EIS)

Affiliation:
Affiliation Type Desc: Environmental Contact
Entity Name: KATHY NORRIS SLUSHER
Entity Title: WASTE TECH
Affiliation Address: POBOX 6004
Affiliation City: SANRAMON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

68
NW
1/4-1/2
0.252 mi.
1332 ft.

F & G STREET MARSH **SWF/LF** **S120834622**
LAGOON DR. & MARINA PARKWAY **CERS** **N/A**
CHULA VISTA, CA

Relative:
Higher

Actual:
12 ft.

SAN DIEGO CO. LF:
Name: F&G STREET MARSH
Address: Not reported
City,State,Zip: CA
Facility Status: CLOSED SITES
Operational Status: CLOSED
Region: SAN DIEGO
SWIS Number: 37-CR-0129
Owner Name: LAGOON DR. & MARINA PARKWAY CHULA VISTA, CA 91911
Operator: US FISH & WILDLIFE 1080 GUNPOWDER POINT DR CHULA VISTA, CA 91910
Facility Type: CLOSED LANDFILLS INSPECTED QUARTERLY
Facility Type2: LANDFILL
PERMTIER: CLOSED SITE
Inspection Frequency: QUARTERLY

SWF/LF (SWIS):
Name: F & G STREET MARSH
Address: LAGOON DR. & MARINA PARKWAY
City,State,Zip: CHULA VISTA, CA
Facility ID: 37-CR-0129
Lat/Long: 32.63294 / -117.10182
Owner Name: USA Fish and Wildlife Service
Owner Telephone: 6194769150
Owner Address: Not reported
Owner Address2: 1080 Gunpowder Point Dr.
Owner City,St,Zip: Chula Vista, CA 91910
Operational Status: Closed
Operator: Not reported
Operator Phone: Not reported
Operator Address: Not reported
Operator Address2: Not reported
Operator City,St,Zip: Not reported
Permit Date: Not reported

F & G STREET MARSH (Continued) **S120834622**

Permit Status:	Not reported
Permitted Acreage:	Not reported
Activity:	Solid Waste Disposal Site
Regulation Status:	Unpermitted
Landuse Name:	Not reported
GIS Source:	Map
Category:	Disposal
Unit Number:	01
Inspection Frequency:	Quarterly
Accepted Waste:	Not reported
Closure Date:	01/01/1975
Closure Type:	Estimated
Disposal Acreage:	Not reported
SWIS Num:	37-CR-0129
Waste Discharge Requirement Num:	Not reported
Program Type:	Not reported
Permitted Throughput with Units:	Not reported
Actual Throughput with Units:	Not reported
Permitted Capacity with Units:	Not reported
Remaining Capacity:	Not reported
Remaining Capacity with Units:	Not reported
Lat/Long:	32.63294 / -117.10182

CERS:

Name:	F & G STREET MARSH
Address:	LAGOON DR. & MARINA PARKWAY
City,State,Zip:	CHULA VISTA, CA
Site ID:	508613
CERS ID:	37-CR-0129
CERS Description:	Solid Waste and Recycle Sites

Affiliation:

Affiliation Type Desc:	Legal Owner
Entity Name:	USA Fish and Wildlife Service
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	6194769150

K69 **ROHR F ST PROPERTY** **SAN DIEGO CO. SAM** **S100735731**
NNW **F ST** **San Diego Co. HMMD** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910** **SAN DIEGO CO LOP**
0.255 mi.
1347 ft. **Site 14 of 14 in cluster K**

Relative:
Higher

Actual:
12 ft.

SAN DIEGO CO. SAM:

Name:	ROHR F ST PROPERTY
Address:	F ST
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H31398-001
Agency:	CA Regional Water Quality Control Board
Funding:	**Non Billable**
Facility Type:	Soils Only
Facility Status:	Preliminary Assessment

ROHR F ST PROPERTY (Continued) **S100735731**

Date: 5/23/1988
Date Began: 5/23/1988

HMMD SAN DIEGO:
Name: ROHR F ST PROPERTY
Address: F ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 131398
Business Type: Not reported
EPA Id Number: Not reported
APN: 567-010-29-00
Last HMMD Inspection: Not reported
Facility Telephone: Not reported
Permit Status: INAC
Permit Expiration: Not reported
Date Last Updated: 11/02/2012
Facility Owner: ROHR F ST PROPERTY
Facility Mailing Address: F ST
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91911-
UST Owner: Not reported
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Not reported
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

SAN DIEGO CO LOP:
Name: ROHR F ST PROPERTY
Address: F ST
City,State,Zip: CHULA VISTA, CA 91910
Record ID: DEH1988-LSAM-H31398-001
Record Status: Completed
Opened Date: 05/23/1988
Parcel Number: 567-010-29-00
Case Type: Not reported
Historical Name: ROHR F STREET PROPERTY
SWRCB Global ID: SL163904227
Funding: N - Non-Billable
Lead Agency: RWQCB
Lead Agency Date: 03/03/1992
Census Tract: 126.00
Community: Chula Vista
Jurisdiction: CHULA VISTA
Watershed Basin Number: 909.12
Water Purveyor: CHULA VISTA
Fire Agency: CHULA VISTA
Latitude: 32.6338503
Longitude: -117.1010925
X MapCoord: 6299640.919
Y MapCoord: 1811473.918

J70 **RADOS** **ENVIROSTOR** **S106797669**
North **798 LAGOON DR. (FORMER "F" STREET)** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910**
0.257 mi.
1356 ft. **Site 2 of 3 in cluster J**

Relative:
Higher

Actual:
26 ft.

ENVIROSTOR:

Name:	RADOS
Address:	798 LAGOON DR. (FORMER "F" STREET)
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	37000014
Status:	Refer: 1248 Local Agency
Status Date:	05/10/2004
Site Code:	Not reported
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Cypress
Assembly:	77
Senate:	Not reported
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not Applicable
Latitude:	0
Longitude:	0
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	37000014
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	Not reported
Completed Sub Area Name:	Not reported
Completed Document Type:	Not reported
Completed Date:	Not reported
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

M71
NW
1/4-1/2
0.260 mi.
1373 ft.

SEDIMENT OFF FORMER SHANGRILA SITE
980 LAGOON DRIVE
CHULA VISTA, CA 91910

Site 1 of 4 in cluster M

CPS-SLIC **S118504901**
CERS **N/A**

Relative:
Higher

Actual:
14 ft.

CPS-SLIC:

Name:	SEDIMENT OFF FORMER SHANGRILA SITE
Address:	980 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Open - Inactive**
Status Date:	05/05/2016
Global Id:	T10000008878
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.63311
Longitude:	-117.10669
Case Type:	Cleanup Program Site
Case Worker:	UNA
Local Agency:	Not reported
RB Case Number:	3100109
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Sediments, Surface water, Under Investigation
Potential Contaminants of Concern:	Polychlorinated biphenyls (PCBs), Copper, Lead, Other Metal, Zinc, Other Petroleum
Site History:	Possible sediment impacts from sandblasting operations.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	SEDIMENT OFF FORMER SHANGRILA SITE
Address:	980 LAGOON DRIVE
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	369323
CERS ID:	T10000008878
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Unassigned - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195161990

M72
NW
1/4-1/2
0.260 mi.
1373 ft.

FORMER SHANGRILA SITE
980 LAGOON DR
CHULA VISTA, CA 91910

Site 2 of 4 in cluster M

SAN DIEGO CO. SAM
CPS-SLIC
San Diego Co. HMMD
CERS

S104756001
N/A

Relative:
Higher

Actual:
14 ft.

SAN DIEGO CO. SAM:

Name:	FORMER SHANGRILA SITE
Address:	980 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91910
Case Number:	H37165-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	Soils Only
Facility Status:	Closed Case
Date:	9/1/2000
Date Began:	10/8/1998

CPS-SLIC:

Name:	FORMER SHANGRILA SITE
Address:	980 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	09/01/2000
Global Id:	T0608177370
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H37165-001
Latitude:	32.6336831159184
Longitude:	-117.106004495338
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

HMMD SAN DIEGO:

Name:	FORMER SHANGRILA SITE
Address:	980 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	137165
Business Type:	Not reported
EPA Id Number:	Not reported
APN:	567-010-19-00
Last HMMD Inspection:	Not reported
Facility Telephone:	Not reported
Permit Status:	INAC
Permit Expiration:	Not reported
Date Last Updated:	11/02/2012
Facility Owner:	Not reported
Facility Mailing Address:	Not reported
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported

FORMER SHANGRILA SITE (Continued) **S104756001**

Facility Mailing Zip:	Not reported
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

CERS:

Name:	FORMER SHANGRILA SITE
Address:	980 LAGOON DR
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	232295
CERS ID:	T0608177370
CERS Description:	Cleanup Program Site

J73 **LAGOON DRIVE CHEMICALS** **SEMS-ARCHIVE** **1001230659**
North **BAY BLVD. & LAGOON DRIVE** **PRP** **CA0002323871**
1/4-1/2 **CHULA VISTA, CA 91910**
0.264 mi.
1396 ft. **Site 3 of 3 in cluster J**

Relative:
Higher

Actual:
28 ft.

SEMS Archive:

Site ID:	0905388
EPA ID:	CA0002323871
Name:	LAGOON DRIVE CHEMICALS
Address:	BAY BLVD. & LAGOON DRIVE
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 91910
Cong District:	Not reported
FIPS Code:	06073
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	09
Site ID:	0905388
EPA ID:	CA0002323871
Site Name:	LAGOON DRIVE CHEMICALS
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	2003-09-15 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	09
Site ID:	0905388
EPA ID:	CA0002323871
Site Name:	LAGOON DRIVE CHEMICALS
NPL:	N
FF:	N

LAGOON DRIVE CHEMICALS (Continued) **1001230659**

OU: 00
Action Code: VU
Action Name: UNARCHIVE
SEQ: 1
Start Date: Not reported
Finish Date: 2003-12-15 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 09
Site ID: 0905388
EPA ID: CA0002323871
Site Name: LAGOON DRIVE CHEMICALS
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 2
Start Date: Not reported
Finish Date: 2013-11-08 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 09
Site ID: 0905388
EPA ID: CA0002323871
Site Name: LAGOON DRIVE CHEMICALS
NPL: N
FF: N
OU: 00
Action Code: RV
Action Name: RMVL
SEQ: 1
Start Date: 1998-03-05 05:00:00
Finish Date: 1998-03-25 05:00:00
Qual: C
Current Action Lead: EPA Perf

Region: 09
Site ID: 0905388
EPA ID: CA0002323871
Site Name: LAGOON DRIVE CHEMICALS
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 2001-10-01 04:00:00
Finish Date: 2002-05-07 04:00:00
Qual: N
Current Action Lead: St Perf

PRP:
PRP Name: GARY A. RASMUSSEN

M74 **SAN DIEGO SHIP BUILDING** **SEMS-ARCHIVE** **1003880059**
NW **980 F STREET** **CAD107568321**
1/4-1/2 **CHULA VISTA, CA 92010**
0.268 mi.
1415 ft. **Site 3 of 4 in cluster M**

Relative:
Higher

Actual:
12 ft.

SEMS Archive:

Site ID:	0905282
EPA ID:	CAD107568321
Name:	SAN DIEGO SHIP BUILDING
Address:	980 F STREET
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 92010
Cong District:	44
FIPS Code:	06073
FF:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region:	09
Site ID:	0905282
EPA ID:	CAD107568321
Site Name:	SAN DIEGO SHIP BUILDING
NPL:	N
FF:	N
OU:	00
Action Code:	VS
Action Name:	ARCH SITE
SEQ:	1
Start Date:	Not reported
Finish Date:	1996-09-18 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf In-Hse

Region:	09
Site ID:	0905282
EPA ID:	CAD107568321
Site Name:	SAN DIEGO SHIP BUILDING
NPL:	N
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA
SEQ:	1
Start Date:	Not reported
Finish Date:	1996-09-18 04:00:00
Qual:	N
Current Action Lead:	St Perf

Region:	09
Site ID:	0905282
EPA ID:	CAD107568321
Site Name:	SAN DIEGO SHIP BUILDING
NPL:	N
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1

SAN DIEGO SHIP BUILDING (Continued) **1003880059**

Start Date:	1995-08-23 04:00:00
Finish Date:	1995-08-23 04:00:00
Qual:	Not reported
Current Action Lead:	St Perf

N75 **ROHR AIRCRAFT CORP.** **FUDS** **1024903970**
SE **N/A**
1/4-1/2 **CHULA VISTA, CA**
0.281 mi.
1485 ft. **Site 1 of 2 in cluster N**

Relative: FUDS:
Higher

Actual:
17 ft.

EPA Region:	09
Installation ID:	CA99799FA08600
Congressional District Number:	51
Facility Name:	ROHR AIRCRAFT CORP.
FUDS Number:	J09CA7263
City:	CHULA VISTA
State:	CA
County:	SAN DIEGO
Object ID:	6867
USACE District:	Los Angeles District (SPL)
Status:	Properties without projects
Current Owner:	Not reported
EMS Map Link:	https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=54012
Eligibility:	Ineligible
Has Projects:	No
NPL Status:	Not Listed
Latitude:	32.625
Longitude:	-117.09583333

N76 **ROHR AIRCRAFT CORP** **ENVIROSTOR** **S107737165**
SE **N/A**
1/4-1/2 **CHULA VISTA, CA**
0.282 mi.
1489 ft. **Site 2 of 2 in cluster N**

Relative: ENVIROSTOR:
Higher

Actual:
17 ft.

Name:	ROHR AIRCRAFT CORP
Address:	Not reported
City,State,Zip:	CHULA VISTA, CA
Facility ID:	80000939
Status:	Inactive - Needs Evaluation
Status Date:	07/01/2005
Site Code:	Not reported
Site Type:	Military Evaluation
Site Type Detailed:	FUDS
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Not reported
Supervisor:	Douglas Bautista
Division Branch:	Cleanup Cypress
Assembly:	80

ROHR AIRCRAFT CORP (Continued) **S107737165**

Senate:	40
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	DERA
Latitude:	32.625
Longitude:	-117.0958
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	CA99799FA08600
Alias Type:	Federal Facility ID
Alias Name:	J09CA7263
Alias Type:	INPR
Alias Name:	80000939
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Inventory Project Report (INPR)
Completed Date:	03/10/1998
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

O77 **SWEETWATER AUTHORITY** **LUST** **S100946074**
NNE **744 F ST** **SAN DIEGO CO. SAM** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910** **CPS-SLIC**
0.291 mi. **AST**
1536 ft. **Site 1 of 3 in cluster O** **San Diego Co. HMMD**
CERS HAZ WASTE
Relative: **SWEEPS UST**
Higher
CERS TANKS
Actual: **HIST CORTESE**
32 ft.
CERS

LUST REG 9:

Region:	9
Status:	Case Closed
Case Number:	9UT527
Local Case:	H20099-001
Substance:	0
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Other Means
How Stopped:	Repair Piping

SWEETWATER AUTHORITY (Continued) **S100946074**

Source: Other Source
Cause: Other Cause
Lead Agency: Local Agency
Case Type: Soil only
Date Found: 05/29/1986
Date Stopped: / /
Confirm Date: / /
Submit Workplan: Not reported
Prelim Assess: / /
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 05/29/1986
Enforce Date: Not reported
Closed Date: 8/8/86
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 909.12
GW Depth: Not reported
Beneficial Use: Not reported
NPDES Number: Not reported
Priority: Low priority. Priority ranking can change over time.
File Dispn: File discarded, case closed
Interim Remedial Actions: Yes
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

SAN DIEGO CO. SAM:
Name: SWEETWATER AUTHORITY
Address: 744 F ST
City,State,Zip: CHULA VISTA, CA 919102006
Case Number: H20099-001
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 8/8/1986
Date Began: 5/29/1986

CPS-SLIC:
Name: SWEETWATER AUTHORITY
Address: 744 F ST
City,State,Zip: CHULA VISTA, CA 919102006
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 08/08/1986
Global Id: T0607302820
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H20099-001
Latitude: 32.634918
Longitude: -117.096872
Case Type: Cleanup Program Site
Case Worker: KH
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: 9UT527

SWEETWATER AUTHORITY (Continued) **S100946074**

File Location: Local Agency
Potential Media Affected: Not reported
Potential Contaminants of Concern: Not reported
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

AST:
Name: SWEETWATER AUTHORITY
Address: 744 F ST
City/Zip: CHULA VISTA,91910
Certified Unified Program Agencies: Not reported
Owner: SWEETWATER AUTHORITY
Total Gallons: Not reported
CERSID: 10357768
Facility ID: 37-000-120099
Business Name: SWEETWATER AUTHORITY
Phone: 619-420-1413
Fax: Not reported
Mailing Address: 744 F Street
Mailing Address City: CHULA VISTA
Mailing Address State: CA
Mailing Address Zip Code: 91910
Operator Name: SWEETWATER AUTHORITY
Operator Phone: 619-420-1413
Owner Phone: 619-420-1413
Owner Mail Address: 744 F Street
Owner State: CA
Owner Zip Code: 91910
Owner Country: United States
Property Owner Name: SWEETWATER AUTHORITY
Property Owner Phone: 619-420-1413
Property Owner Mailing Address: 744 F ST
Property Owner City: CHULA VISTA
Property Owner Stat : CA
Property Owner Zip Code: 91910
Property Owner Country: United States
EPAID: CAL000004840

Name: SWEETWATER AUTHORITY
Address: 744 F ST
City/Zip: CHULA VISTA,
Certified Unified Program Agencies: San Diego
Owner: SWEETWATER AUTHORITY
Total Gallons: 1625
CERSID: Not reported
Facility ID: Not reported
Business Name: Not reported
Phone: Not reported
Fax: Not reported
Mailing Address: Not reported
Mailing Address City: Not reported
Mailing Address State: Not reported
Mailing Address Zip Code: Not reported
Operator Name: Not reported
Operator Phone: Not reported
Owner Phone: Not reported

SWEETWATER AUTHORITY (Continued) **S100946074**

Owner Mail Address:	Not reported
Owner State:	Not reported
Owner Zip Code:	Not reported
Owner Country:	Not reported
Property Owner Name:	Not reported
Property Owner Phone:	Not reported
Property Owner Mailing Address:	Not reported
Property Owner City:	Not reported
Property Owner Stat :	Not reported
Property Owner Zip Code:	Not reported
Property Owner Country:	Not reported
EPAID:	Not reported

HMMD SAN DIEGO:

Name:	SWEETWATER AUTHORITY
Address:	744 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	120099
Business Type:	6HK52
EPA Id Number:	CAL000004840
APN:	567-090-02-00
Last HMMD Inspection:	12/07/2011
Facility Telephone:	619-420-1413
Permit Status:	OPEN
Permit Expiration:	06/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	SWEETWATER AUTHORITY
Facility Mailing Address:	505 GARRETT AVE
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910
UST Owner:	SWEETWATER AUTHORITY
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Y
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	124-38-9
Name:	CARBON DIOXIDE GAS
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	PRESSURE RELEASE
Hazardous Categories 2:	Not reported

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL #2
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	CHRONIC
Hazardous Categories 2:	Not reported

SWEETWATER AUTHORITY (Continued) **S100946074**

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	74-85-1
Name:	ETHYLENE
Other Information:	ACETYLENE
Material Waste:	Material
Hazardous Categories 1:	PRESSURE RELEASE
Hazardous Categories 2:	Not reported

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	8002-05-9
Name:	OILS, LUBRICATING
Other Information:	VARIOUS GRADES, ATF, GREASE, HYDRAULIC
Material Waste:	Material
Hazardous Categories 1:	CHRONIC
Hazardous Categories 2:	Not reported

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	7782-44-7
Name:	OXYGEN
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 120099 T003
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information:	PARTS WASHER
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 151 ASBESTOS CONTAINING WASTE
Other Information:	Not reported
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	Not reported

SWEETWATER AUTHORITY (Continued) **S100946074**

Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: AST EXEMPTION DTD 7-10-03
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: ANTIFREEZE, COOLANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: OILY ABSORBENT (30 GALLON DRUM)
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: POWERSIDE BATTERY CO
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 860 UNIVERSAL WASTE CRTS/LAMPS/BATTERIES/ETC
Other Information: UNIVERSAL WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL FILTERS/USED FUEL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/19/2007
Violation Code: 6HV1009
Violation: HMBP: INADEQUATE SITE MAP

SWEETWATER AUTHORITY (Continued) **S100946074**

Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/19/2007
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/19/2007
Violation Code:	6HV0136
Violation:	NO DISPOSAL RECORDS: BATTERIES
Violation Citation:	Generator has not maintained onsite documentation for lead-acid battery disposal. CCR 66266.81(a)(4)(B)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/19/2007
Violation Code:	6HV0147
Violation:	UW RECORDS NOT KEPT ONSITE FOR 3 YEARS
Violation Citation:	Failed to keep universal waste record for 3 years for offsite shipment. SQH:66273.19(b)&(c)(2); LQH:66273.39(b)&(c)(2)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/09/2005
Violation Code:	6HV3105
Violation:	NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation:	Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/09/2005
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/07/2010
Violation Code:	6HV1012
Violation:	SPCC PLAN NOT PREPARED
Violation Citation:	Spill Prevention Countermeasures & Control Plan not prepared as

SWEETWATER AUTHORITY (Continued) **S100946074**

required. 25270.5 (c)
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/28/2010
Violation Code: 6HV3602
Violation: SWCSP: NO DAILY MONITORING/RECORD
Violation Citation: SINGLE WALLED CONVENTIONAL SUCTION PIPING: Daily monitoring not performed and/or logged. 2643(d), App. II
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/28/2010
Violation Code: 6HV3163
Violation: CONTRACTOR W/O REQUIRED LICENSE
Violation Citation: Contractor did not have required license, i.e., Class A, C-10, C34, C36 and/or C61. 25284.1(a)(5)(D); 2715
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/02/2004
Violation Code: 6HV0209
Violation: WASTE ONSITE >90/180/270 DAYS
Violation Citation: Hazardous waste is stored in excess of allowable time period (90 days) without a State permit or written variance. CCR 25201(a) & 66262.34(a)&(c)
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/02/2004
Violation Code: 6HV1605
Violation: NO DAILY TANK INSPECTION/LOG
Violation Citation: Failed to inspect and/or document daily HW tank system inspections. 66265.195 (c)
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/07/2011
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/07/2011
Violation Code: 6HV3193
Violation: NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation: Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity: ACTIVE

SWEETWATER AUTHORITY (Continued) **S100946074**

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/07/2011
Violation Code: 6HV3191
Violation: NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation: Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 11/24/2003
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 120099 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 120099
Tank Type: SINGLE WALL
Additional Id: 1
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1998-01-12 00:00:00
Year Installed: Not reported
Pipe Type: SINGLE WALL
Delivery System: GRAVITY
Monitor Code: Not reported
UST Monitor Method: Not reported

UST Name: UNDERGROUND TANK 120099 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 120099
Tank Type: SINGLE WALL
Additional Id: 2 DIESEL
Capacity Gallons: 2000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: 1998-01-12 00:00:00
Year Installed: Not reported
Pipe Type: UNKNOWN
Delivery System: SUCTION
Monitor Code: 01
UST Monitor Method: SW TANK SW SUCTION PIPE W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST TRIENNIALLY

UST Name: UNDERGROUND TANK 120099 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 120099
Tank Type: SINGLE WALL
Additional Id: RT0871/RT2585 REGULAR UNLEADED, RT3076, RT4584

SWEETWATER AUTHORITY (Continued) **S100946074**

Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1979-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	SUCTION
Monitor Code:	11
UST Monitor Method:	SW TANK SW SUCTION PIPE W/ CERTIFIED ATG: IN-TANK TEST MONTHLY, PIPE TEST TRIENNIALLY

UST Name:	UNDERGROUND TANK 120099 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	120099
Tank Type:	SINGLE WALL
Additional Id:	4 REGULAR UNLEADED
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1989-01-09 00:00:00
Year Installed:	Not reported
Pipe Type:	UNKNOWN
Delivery System:	SUCTION
Monitor Code:	01
UST Monitor Method:	SW TANK SW SUCTION PIPE W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST TRIENNIALLY

Name:	SWEETWATER AUTHORITY
Address:	744 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	120099
Business Type:	6HK52
EPA Id Number:	CAL000004840
APN:	567-090-02-00
Last HMMD Inspection:	12/07/2011
Facility Telephone:	619-420-1413
Permit Status:	OPEN
Permit Expiration:	06/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	SWEETWATER AUTHORITY
Facility Mailing Address:	505 GARRETT AVE
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910
UST Owner:	SWEETWATER AUTHORITY
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	120099
Update Date:	11/02/2012

SWEETWATER AUTHORITY (Continued) **S100946074**

Case Number: 124-38-9
Name: CARBON DIOXIDE GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL #2
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: 74-85-1
Name: ETHYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: 8002-05-9
Name: OILS, LUBRICATING
Other Information: VARIOUS GRADES, ATF, GREASE, HYDRAULIC
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: OXYGEN
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 120099 T003
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: PARTS WASHER

SWEETWATER AUTHORITY (Continued) **S100946074**

Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 151 ASBESTOS CONTAINING WASTE
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: AST EXEMPTION DTD 7-10-03
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: ANTIFREEZE, COOLANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: OILY ABSORBENT (30 GALLON DRUM)
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: POWERSIDE BATTERY CO
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 120099
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 860 UNIVERSAL WASTE CRTS/LAMPS/BATTERIES/ETC
Other Information: UNIVERSAL WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

SWEETWATER AUTHORITY (Continued) **S100946074**

Permit Number:	120099
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 888 USED OIL FILTERS
Other Information:	USED OIL FILTERS/USED FUEL FILTERS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Violations Active Permits:

Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/19/2007
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE

Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/19/2007
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	ACTIVE

Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/19/2007
Violation Code:	6HV0136
Violation:	NO DISPOSAL RECORDS: BATTERIES
Violation Citation:	Generator has not maintained onsite documentation for lead-acid battery disposal. CCR 66266.81(a)(4)(B)
Activity:	ACTIVE

Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/19/2007
Violation Code:	6HV0147
Violation:	UW RECORDS NOT KEPT ONSITE FOR 3 YEARS
Violation Citation:	Failed to keep universal waste record for 3 years for offsite shipment. SQH:66273.19(b)&(c)(2); LQH:66273.39(b)&(c)(2)
Activity:	ACTIVE

Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/09/2005
Violation Code:	6HV3105
Violation:	NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation:	Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity:	ACTIVE

SWEETWATER AUTHORITY (Continued) **S100946074**

Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/09/2005
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/07/2010
Violation Code:	6HV1012
Violation:	SPCC PLAN NOT PREPARED
Violation Citation:	Spill Prevention Countermeasures & Control Plan not prepared as required. 25270.5 (c)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/28/2010
Violation Code:	6HV3602
Violation:	SWCSP: NO DAILY MONITORING/RECORD
Violation Citation:	SINGLE WALLED CONVENTIONAL SUCTION PIPING: Daily monitoring not performed and/or logged. 2643(d), App. II
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/28/2010
Violation Code:	6HV3163
Violation:	CONTRACTOR W/O REQUIRED LICENSE
Violation Citation:	Contractor did not have required license, i.e., Class A, C-10, C34, C36 and/or C61. 25284.1(a)(5)(D); 2715
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/02/2004
Violation Code:	6HV0209
Violation:	WASTE ONSITE >90/180/270 DAYS
Violation Citation:	Hazardous waste is stored in excess of allowable time period (90 days) without a State permit or written variance. CCR 25201(a) & 66262.34(a)&(c)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012
Inspection Date:	12/02/2004
Violation Code:	6HV1605
Violation:	NO DAILY TANK INSPECTION/LOG
Violation Citation:	Failed to inspect and/or document daily HW tank system inspections. 66265.195 (c)
Activity:	ACTIVE
Permit Number:	120099
Update Date:	11/02/2012

SWEETWATER AUTHORITY (Continued) **S100946074**

Inspection Date: 12/07/2011
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/07/2011
Violation Code: 6HV3193
Violation: NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation: Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 12/07/2011
Violation Code: 6HV3191
Violation: NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation: Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity: ACTIVE

Permit Number: 120099
Update Date: 11/02/2012
Inspection Date: 11/24/2003
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 120099 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 120099
Tank Type: SINGLE WALL
Additional Id: 1
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1998-01-12 00:00:00
Year Installed: Not reported
Pipe Type: SINGLE WALL
Delivery System: GRAVITY
Monitor Code: Not reported
UST Monitor Method: Not reported

UST Name: UNDERGROUND TANK 120099 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 120099
Tank Type: SINGLE WALL
Additional Id: 2 DIESEL
Capacity Gallons: 2000

SWEETWATER AUTHORITY (Continued) **S100946074**

UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	REMOVED
Remove Close Date:	1998-01-12 00:00:00
Year Installed:	Not reported
Pipe Type:	UNKNOWN
Delivery System:	SUCTION
Monitor Code:	01
UST Monitor Method:	SW TANK SW SUCTION PIPE W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST TRIENNIALLY
UST Name:	UNDERGROUND TANK 120099 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	120099
Tank Type:	SINGLE WALL
Additional Id:	RT0871/RT2585 REGULAR UNLEADED, RT3076, RT4584
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1979-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	SUCTION
Monitor Code:	11
UST Monitor Method:	SW TANK SW SUCTION PIPE W/ CERTIFIED ATG: IN-TANK TEST MONTHLY, PIPE TEST TRIENNIALLY
UST Name:	UNDERGROUND TANK 120099 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	120099
Tank Type:	SINGLE WALL
Additional Id:	4 REGULAR UNLEADED
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1989-01-09 00:00:00
Year Installed:	Not reported
Pipe Type:	UNKNOWN
Delivery System:	SUCTION
Monitor Code:	01
UST Monitor Method:	SW TANK SW SUCTION PIPE W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST TRIENNIALLY

CERS HAZ WASTE:

Name:	SWEETWATER AUTHORITY
Address:	744 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	158667
CERS ID:	10357768
CERS Description:	Hazardous Waste Generator

SWEEPS UST:

Name:	SWEETWATER AUTHORITY

SWEETWATER AUTHORITY (Continued) **S100946074**

Address:	744 F ST
City:	CHULA VISTA
Status:	Active
Comp Number:	20099
Number:	9
Board Of Equalization:	44-023093
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-020099-000001
Tank Status:	A
Capacity:	550
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	W
Content:	Not reported
Number Of Tanks:	2

Name:	SWEETWATER AUTHORITY
Address:	744 F ST
City:	CHULA VISTA
Status:	Active
Comp Number:	20099
Number:	9
Board Of Equalization:	44-023093
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-020099-000002
Tank Status:	A
Capacity:	2000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	OTHER
Number Of Tanks:	Not reported

Name:	SWEETWATER AUTHORITY
Address:	744 F ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	20099
Number:	Not reported
Board Of Equalization:	44-023093
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-020099-000003
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED

SWEETWATER AUTHORITY (Continued) **S100946074**

Number Of Tanks: 2

Name: SWEETWATER AUTHORITY
Address: 744 F ST
City: CHULA VISTA
Status: Not reported
Comp Number: 20099
Number: Not reported
Board Of Equalization: 44-023093
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020099-000004
Tank Status: Not reported
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

CERS TANKS:
Name: SWEETWATER AUTHORITY
Address: 744 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 158667
CERS ID: 10357768
CERS Description: Aboveground Petroleum Storage

Name: SWEETWATER AUTHORITY
Address: 744 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 158667
CERS ID: 10357768
CERS Description: Underground Storage Tank

HIST CORTESE:
edr_fname: SWEETWATER AUTHORITY
edr_fadd1: 744 F
City,State,Zip: CHULA VISTA, CA 92010
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT527

CERS:
Name: SWEETWATER AUTHORITY
Address: 744 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 158667
CERS ID: T0607302820
CERS Description: Cleanup Program Site

Violations:
Site ID: 158667

SWEETWATER AUTHORITY (Continued) **S100946074**

Site Name: SWEETWATER AUTHORITY
Violation Date: 12-18-2013
Citation: 23 CCR 16 2638 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2638
Violation Description: Failure to test leak detection equipment as required every 12 months (VPH, sensor, LLD, ATG, etc.) and/or submit monitoring system certification to the CUPA within 30 days of completion of the test
Violation Notes: Returned to compliance on 12/18/2013.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 158667
Site Name: SWEETWATER AUTHORITY
Violation Date: 12-19-2019
Citation: 23 CCR 16 2661(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2661(f)
Violation Description: "For single-walled conventional suction systems, failure to conduct 0.1 gallon per hour piping integrity test at one of the following times: Every 36 months. Within 30 days of the date of the completion of a repair to the piping."
Violation Notes: Returned to compliance on 12/19/2019. Inspection Sequence ID:6303754;Tank ID:24773;Violation Description:(TCR 9d) Failure to conduct 0.1 gallon per hour piping integrity test at any of the following times: Every 36 months. Within 30 days of the date of the completion of a repair to the piping. 23 CCR 2643(d), 2661(f)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 158667
Site Name: SWEETWATER AUTHORITY
Violation Date: 12-14-2016
Citation: 23 CCR 16 2643(d) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2643(d)
Violation Description: Failure to conduct 0.1 gallon per hour piping integrity test every three years for single-walled conventional suction systems.
Violation Notes: Returned to compliance on 12/28/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 158667
Site Name: SWEETWATER AUTHORITY
Violation Date: 12-19-2019
Citation: 23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description: Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that

SWEETWATER AUTHORITY (Continued) **S100946074**

none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1,- 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October- 1,- 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.

Violation Notes: Returned to compliance on 05/26/2020. Inspection Sequence ID:6303754;Tank ID:24773;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equip
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 158667
Site Name: SWEETWATER AUTHORITY
Violation Date: 12-18-2013
Citation: 23 CCR 16 2636(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)
Violation Description: Failure to continuously monitor the interstitial space of the tank, piping and/or sumps sump such that the leak detection activates an audible/visual alarm when a leak is detected.
Violation Notes: Returned to compliance on 12/19/2013.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-01-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5781199
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

SWEETWATER AUTHORITY (Continued) **S100946074**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-01-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5781199
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-01-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5781199
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-01-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5781199
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6032980
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6032980
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6032980
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-05-2018
Violations Found: No

SWEETWATER AUTHORITY (Continued) **S100946074**

Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6032980
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:5180972
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:5180972
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:5180972
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5397957
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5397957
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4936479
Eval Division: San Diego County Department of Env Health

SWEETWATER AUTHORITY (Continued) **S100946074**

Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4936479
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4936479
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4999272
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4999272
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4999272
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4999272
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

SWEETWATER AUTHORITY (Continued) **S100946074**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-19-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Ayala Anthony Inspection ID:6303754
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Coordinates:
Site ID: 158667
Facility Name: SWEETWATER AUTHORITY
Env Int Type Code: HWG
Program ID: 10357768
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.635040
Longitude: -117.096790

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 744 F Street
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91910
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer
Entity Name: Dan Bresniker
Entity Title: Safety Coordinator
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: UST Permit Applicant
Entity Name: Dan Bresniker
Entity Title: Safety Coordinator
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported

SWEETWATER AUTHORITY (Continued) **S100946074**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 409-6867

Affiliation Type Desc: UST Tank Owner
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: 744 F Street
Affiliation City: Chula Vista
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 420-1413

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880

Affiliation Type Desc: Document Preparer
Entity Name: Dan Bresniker
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker
Entity Name: KEVIN HEATON - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Operator
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 420-1413

Affiliation Type Desc: Property Owner
Entity Name: Sweetwater Authority
Entity Title: Not reported

SWEETWATER AUTHORITY (Continued) **S100946074**

Affiliation Address: 744 F ST
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 420-1413

Affiliation Type Desc: UST Tank Operator
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: 744 F Street
Affiliation City: Chula Vista
Affiliation State: Ca
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 420-1413

Affiliation Type Desc: Environmental Contact
Entity Name: Dan Bresniker
Entity Title: Not reported
Affiliation Address: 744 F ST
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91910
Affiliation Phone: Not reported

Affiliation Type Desc: UST Property Owner Name
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: 744 F Street
Affiliation City: Chula Vista
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 420-1413

Affiliation Type Desc: Legal Owner
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: 744 F Street
Affiliation City: Chula Vista
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 420-1413

Name: SWEETWATER AUTHORITY
Address: 744 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 158667
CERS ID: 10357768
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 158667
Site Name: SWEETWATER AUTHORITY

SWEETWATER AUTHORITY (Continued) **S100946074**

Violation Date:	12-18-2013
Citation:	23 CCR 16 2638 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2638
Violation Description:	Failure to test leak detection equipment as required every 12 months (VPH, sensor, LLD, ATG, etc.) and/or submit monitoring system certification to the CUPA within 30 days of completion of the test
Violation Notes:	Returned to compliance on 12/18/2013.
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	158667
Site Name:	SWEETWATER AUTHORITY
Violation Date:	12-19-2019
Citation:	23 CCR 16 2661(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2661(f)
Violation Description:	"For single-walled conventional suction systems, failure to conduct 0.1 gallon per hour piping integrity test at one of the following times: Every 36 months. Within 30 days of the date of the completion of a repair to the piping."
Violation Notes:	Returned to compliance on 12/19/2019. Inspection Sequence ID:6303754;Tank ID:24773;Violation Description:(TCR 9d) Failure to conduct 0.1 gallon per hour piping integrity test at any of the following times: Every 36 months. Within 30 days of the date of the completion of a repair to the piping. 23 CCR 2643(d), 2661(f)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	158667
Site Name:	SWEETWATER AUTHORITY
Violation Date:	12-14-2016
Citation:	23 CCR 16 2643(d) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2643(d)
Violation Description:	Failure to conduct 0.1 gallon per hour piping integrity test every three years for single-walled conventional suction systems.
Violation Notes:	Returned to compliance on 12/28/2016.
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	158667
Site Name:	SWEETWATER AUTHORITY
Violation Date:	12-19-2019
Citation:	23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description:	Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to

SWEETWATER AUTHORITY (Continued) **S100946074**

product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1,- 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October- 1,- 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.

Violation Notes: Returned to compliance on 05/26/2020. Inspection Sequence ID:6303754;Tank ID:24773;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equip
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 158667
Site Name: SWEETWATER AUTHORITY
Violation Date: 12-18-2013
Citation: 23 CCR 16 2636(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)
Violation Description: Failure to continuously monitor the interstitial space of the tank, piping and/or sumps sump such that the leak detection activates an audible/visual alarm when a leak is detected.
Violation Notes: Returned to compliance on 12/19/2013.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-01-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5781199
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

SWEETWATER AUTHORITY (Continued) **S100946074**

Eval Date: 12-01-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5781199
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-01-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5781199
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-01-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5781199
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6032980
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6032980
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-05-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Inspection ID:6032980
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-05-2018
Violations Found: No
Eval Type: Routine done by local agency

SWEETWATER AUTHORITY (Continued) **S100946074**

Eval Notes: Inspector: Joaquino Billie Inspection ID:6032980
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:5180972
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:5180972
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:5180972
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5397957
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-14-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5397957
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4936479
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP

SWEETWATER AUTHORITY (Continued) **S100946074**

Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4936479
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4936479
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4999272
Eval Division: San Diego County Department of Env Health
Eval Program: APSA
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4999272
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4999272
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-18-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Joaquino Billie Marcos Inspection ID:4999272
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

SWEETWATER AUTHORITY (Continued) **S100946074**

Eval Date: 12-19-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Ayala Anthony Inspection ID:6303754
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Coordinates:
Site ID: 158667
Facility Name: SWEETWATER AUTHORITY
Env Int Type Code: HWG
Program ID: 10357768
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.635040
Longitude: -117.096790

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 744 F Street
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91910
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer
Entity Name: Dan Bresniker
Entity Title: Safety Coordinator
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: UST Permit Applicant
Entity Name: Dan Bresniker
Entity Title: Safety Coordinator
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported

SWEETWATER AUTHORITY (Continued) **S100946074**

Affiliation Zip: Not reported
Affiliation Phone: (619) 409-6867

Affiliation Type Desc: UST Tank Owner
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: 744 F Street
Affiliation City: Chula Vista
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 420-1413

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880

Affiliation Type Desc: Document Preparer
Entity Name: Dan Bresniker
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Local Agency Caseworker
Entity Name: KEVIN HEATON - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Operator
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 420-1413

Affiliation Type Desc: Property Owner
Entity Name: Sweetwater Authority
Entity Title: Not reported
Affiliation Address: 744 F ST

SWEETWATER AUTHORITY (Continued) **S100946074**

Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 420-1413
Affiliation Type Desc:	UST Tank Operator
Entity Name:	Sweetwater Authority
Entity Title:	Not reported
Affiliation Address:	744 F Street
Affiliation City:	Chula Vista
Affiliation State:	Ca
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 420-1413
Affiliation Type Desc:	Environmental Contact
Entity Name:	Dan Bresniker
Entity Title:	Not reported
Affiliation Address:	744 F ST
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	Sweetwater Authority
Entity Title:	Not reported
Affiliation Address:	744 F Street
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 420-1413
Affiliation Type Desc:	Legal Owner
Entity Name:	Sweetwater Authority
Entity Title:	Not reported
Affiliation Address:	744 F Street
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 420-1413

M78 **FLUID SYSTEMS** **ENVIROSTOR** **S102430054**
NW **965 F ST** **LUST** **N/A**
1/4-1/2 **CHULA VISTA, CA 92010** **SAN DIEGO CO. SAM**
0.294 mi. **San Diego Co. HMMD**
1550 ft. **Site 4 of 4 in cluster M** **SWEEPS UST**
Cortese
Relative: **HIST CORTESE**
Higher
SAN DIEGO CO LOP
Actual: **CERS**
12 ft.

FLUID SYSTEMS (Continued) **S102430054**

ENVIROSTOR:
Name: UOP FLUID SYSTEMS
Address: 965 F STREET
City,State,Zip: CHULA VISTA, CA 92010
Facility ID: 37760082
Status: Refer: Local Agency
Status Date: 01/11/2011
Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: 0
NPL: NO
Regulatory Agencies: US EPA
Lead Agency: US EPA
Program Manager: Not reported
Supervisor: Eileen Mananian
Division Branch: Cleanup Cypress
Assembly: 80
Senate: 40
Special Program: EPA - PASI
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 32.63417
Longitude: -117.1063
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: CHULA VISTA REDEVELOPMENT AGENCY
Alias Type: Alternate Name
Alias Name: T0607300888
Alias Type: GeoTracker Global ID
Alias Name: 37760082
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: Not reported
Completed Sub Area Name: Not reported
Completed Document Type: Not reported
Completed Date: Not reported
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: PA/SI Site Screening
Future Due Date: 2021
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

LUST REG 9:
Region: 9
Status: Case Closed

FLUID SYSTEMS (Continued) **S102430054**

Case Number: 9UT2120
Local Case: H32432-001
Substance: Gasoline
Qty Leaked: Not reported
Abate Method: Not reported
Local Agency: San Diego
How Found: Tank Closure
How Stopped: Close Tank
Source: Piping
Cause: Corrosion
Lead Agency: Regional Board
Case Type: Aquifer affected
Date Found: 12/27/1991
Date Stopped: 12/27/1991
Confirm Date: 12/27/1991
Submit Workplan: 1/14/92
Prelim Assess: / /
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 12/27/1991
Enforce Date: Not reported
Closed Date: 2/19/93
Enforce Type: Not reported
Pilot Program: UST
Basin Number: 909.12
GW Depth: 6’
Beneficial Use: MUNB/E
NPDES Number: Not reported
Priority: Medium priority
File Dispn: Not reported
Interim Remedial Actions: Yes
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

LUST:
Name: FLUID SYSTEMS
Address: 965 F ST
City,State,Zip: CHULA VISTA, CA 92010
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607300888
Global Id: T0607300888
Latitude: 32.634174
Longitude: -117.106321
Status: Completed - Case Closed
Status Date: 10/06/1995
Case Worker: Not reported
RB Case Number: 9UT2120
Local Agency: Not reported
File Location: Not reported
Local Case Number: H32432-002
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: UOP Fluid Systems site is located at 965 F Street, Chula Vista, CA 91910. Presently site is vacant, unused and covered with vegetation

FLUID SYSTEMS (Continued) **S102430054**

with some illegal dumping of debris of household materials and auto body parts. This site is located in an industrial zone and there are some industrial units but no residential units within a radius of about one mile. In April, 1992, TorStan, Inc. 160 Chesterfield, Suite 3, Cardiff, CA 92007 conducted a Phase II Site Assessment for the site for San Diego County and City of Chula Vista, California and discovered that: 1) Four of the six 5-gallon buckets observed on the site appeared to contain roofing tar. Of the two remaining buckets, one appeared to contain motor oil and other gear lubricant. 2) Two underground tanks were removed under permit; one tank had an unauthorized release while the second tank was removed in good condition with no evidence of a release. A 2000 & 6000 Gal. gas tanks were removed 12/27/91 with no holes observed. 100 gallons of petroleum product and water were pumped out from the 2000 gal. tank pit. 3) History of the on-site well indicated that the well was used to pump sea water to an on-site basin for desalination and water treatment research and there were no Title 22 Metals above the instrument detection limit. 4) Analyses of materials in the various outdoor basins indicated the presence of arsenic above regulatory limits. 5) On-site presence of a septic system indicated that the site accessed water from the Sweetwater Authority and that the site was not on City sewer. Based upon analytical results from the subsurface assessment it did not appear that the septic system was used to dispose of petroleum products. On February 19, 1993, San Diego County Hazardous Materials Management Division (HMMD) transferred oversight of the site to San Diego RWQCB for further site investigation and mitigation activities. On October 6, 1995, as a result of the bioremediation at this site and on the basis of soil and groundwater results provided by Ninyo & Moore, San Diego RWQCB closed the site for further action because the site was not posing any threat to water quality and the environment.

LUST:
Global Id: T0607300888
Action Type: Other
Date: 12/27/1991
Action: Leak Reported

Global Id: T0607300888
Action Type: Other
Date: 12/27/1991
Action: Leak Discovery

Global Id: T0607300888
Action Type: Other
Date: 12/27/1991
Action: Leak Stopped

LUST:
Global Id: T0607300888
Status: Open - Case Begin Date
Status Date: 12/27/1991

Global Id: T0607300888
Status: Open - Site Assessment
Status Date: 12/27/1991

FLUID SYSTEMS (Continued) **S102430054**

Global Id: T0607300888
Status: Open - Site Assessment
Status Date: 01/14/1992

Global Id: T0607300888
Status: Completed - Case Closed
Status Date: 10/06/1995

SAN DIEGO CO. SAM:
Name: FLUID SYSTEMS
Address: 965 F ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H32432-001
Agency: CA Regional Water Quality Control Board
Funding: **LOP - Federal Fund**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Closed Case
Date: 2/19/1993
Date Began: 12/27/1991

Name: FLUID SYSTEMS
Address: 965 F ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H32432-002
Agency: CA Regional Water Quality Control Board
Funding: **Private - VAP**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 2/19/1993
Date Began: 12/27/1991

Name: FLUID SYSTEMS
Address: 965 F ST
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H32432-003
Agency: CA Regional Water Quality Control Board
Funding: **Non Billable**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 10/6/1995
Date Began: 12/27/1991

HMMD SAN DIEGO:
Name: FLUID SYSTEMS
Address: 965 F ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 132432
Business Type: Not reported
EPA Id Number: Not reported
APN: 567-010-19-00
Last HMMD Inspection: 09/17/1991
Facility Telephone: Not reported
Permit Status: INAC
Permit Expiration: Not reported
Date Last Updated: 11/02/2012

FLUID SYSTEMS (Continued) **S102430054**

Facility Owner:	Not reported
Facility Mailing Address:	Not reported
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 132432 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	132432
Tank Type:	UNKNOWN
Additional Id:	AT2483
Capacity Gallons:	2000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1991-12-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 132432 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	132432
Tank Type:	UNKNOWN
Additional Id:	AT2483
Capacity Gallons:	6000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1991-12-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

SWEEPS UST:

Name:	FLUID SYSTEMS
Address:	965 F ST
City:	CHULA VISTA
Status:	Active
Comp Number:	32432
Number:	9
Board Of Equalization:	Not reported

FLUID SYSTEMS (Continued) **S102430054**

Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: Not reported
Tank Status: Not reported
Capacity: Not reported
Active Date: Not reported
Tank Use: Not reported
STG: Not reported
Content: Not reported
Number Of Tanks: Not reported

Name: FLUID SYSTEMS
Address: 965 F ST
City: CHULA VISTA
Status: Not reported
Comp Number: 32432
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-032432-000001
Tank Status: Not reported
Capacity: 2000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 2

Name: FLUID SYSTEMS
Address: 965 F ST
City: CHULA VISTA
Status: Not reported
Comp Number: 32432
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-032432-000002
Tank Status: Not reported
Capacity: 6000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

CORTESE:
Name: FLUID SYSTEMS
Address: 965 F ST
City,State,Zip: CHULA VISTA, CA 92010

FLUID SYSTEMS (Continued) **S102430054**

Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607300888
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	FLUID SYSTEMS
edr_fadd1:	965 F
City,State,Zip:	CHULA VISTA, CA 92010
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT2120

SAN DIEGO CO LOP:

Name:	FLUID SYSTEMS
Address:	965 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1991-LSAM-H32432-003
Record Status:	Completed
Opened Date:	12/27/1991
Parcel Number:	567-010-19-00
Case Type:	Not reported
Historical Name:	FLUID SYSTEMS
SWRCB Global ID:	T0607300888
Funding:	N - Non-Billable
Lead Agency:	RWQCB
Lead Agency Date:	02/19/1993
Census Tract:	126.00
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6334497
Longitude:	-117.1058826
X MapCoord:	6298155.007
Y MapCoord:	1811365.781

FLUID SYSTEMS (Continued) **S102430054**

Name:	FLUID SYSTEMS
Address:	965 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1991-LSAM-H32432-001
Record Status:	Completed
Opened Date:	12/27/1991
Parcel Number:	567-010-19-00
Case Type:	LOP - Local Oversight Program
Historical Name:	FLUID SYSTEMS
SWRCB Global ID:	Not reported
Funding:	F - LOP Federal Fund
Lead Agency:	RWQCB
Lead Agency Date:	02/19/1993
Census Tract:	126.00
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6334497
Longitude:	-117.1058826
X MapCoord:	6298155.007
Y MapCoord:	1811365.781

CERS:

Name:	FLUID SYSTEMS
Address:	965 F ST
City,State,Zip:	CHULA VISTA, CA 92010
Site ID:	244332
CERS ID:	T0607300888
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	JOHN R. ODERMATT - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195215906

L79 **WORLD OIL MARKETING CO. #46** **SAN DIEGO CO. SAM** **U003943055**
East **685 H ST** **UST** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910** **San Diego Co. HMMD**
0.297 mi. **CERS HAZ WASTE**
1567 ft. **Site 3 of 5 in cluster L** **SWEEPS UST**
CERS TANKS
Relative: **Cortese**
Higher **SAN DIEGO CO LOP**
CERS
Actual:
36 ft.

SAN DIEGO CO. SAM:

Name:	WORLD OIL MARKETING CO. #46
Address:	685 H ST
City,State,Zip:	CHULA VISTA, CA 919104222

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Case Number: H03739-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 2/2/2010
Date Began: 9/18/1995

Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Case Number: H03739-002
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 4/25/2000
Date Began: 4/29/1999

UST:
Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 91910
Facility ID: 37-000-103739
Permitting Agency: San Diego County Department of Environmental Health
Latitude: 32.63032
Longitude: -117.09293

HMMD SAN DIEGO:
Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 103739
Business Type: 6HK28
EPA Id Number: CAD981160674
APN: 567-201-03-00
Last HMMD Inspection: 10/03/2012
Facility Telephone: 619-420-9710
Permit Status: OPEN
Permit Expiration: 06/30/2013
Date Last Updated: 11/02/2012
Facility Owner: WORLD OIL MARKETING CO
Facility Mailing Address: P.O. BOX 1966
Facility Mailing City: SOUTH GATE
Facility Mailing State: CA
Facility Mailing Zip: 90280
UST Owner: WORLD OIL MARKETING CO
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 103739
Update Date: 11/02/2012

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Case Number:	8006-61-9
Name:	MIDGRADE UNLEADED
Other Information:	UNDERGROUND TANK 103739 T008
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	103739
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUND TANK 103739 T009
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	103739
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 103739 T006
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	103739
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 103739 T007
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	103739
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	SUMP&MONITORING WELL GASOLINE
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	103739
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information:	USED GASOLINE FILTERS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Violations Active Permits:

Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV3255

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Violation:	SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation:	Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV3267
Violation:	DISP. CONTAINMENT NOT ADEQ. MONITORED
Violation Citation:	Dispenser containment not adequately monitored. 2636(f)(1) or (f)(5)(A)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV3410
Violation:	ALARM NOT FUNCTIONAL/NO DISP FLOW STOP
Violation Citation:	DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Continuous audible and visual alarm not functioning or does not stop flow at dispenser. 2636(f)(1)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV3411
Violation:	LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation:	DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	11/08/2005
Violation Code:	6HV0138
Violation:	NO TSDF SIGNED MANIFEST ONSITE
Violation Citation:	Generator has not maintained the required signed copy of the hazardous waste manifest from the TSD facility on site for review. CCR 66262.40(a)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/29/2010
Violation Code:	6HV1014

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Violation:	HMBP INCOMPLETE/NOT AMENDED
Violation Citation:	HMBP is incomplete/inadequate/not amended to reflect changes. 25504, 25505(a)(2) &/or 25509(a); 25505(b); 19 CCR 2729
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/29/2010
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/29/2010
Violation Code:	6HV3255
Violation:	SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation:	Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/29/2010
Violation Code:	6HV3258
Violation:	SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation:	Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/29/2010
Violation Code:	6HV3262
Violation:	SEC CONT PIPING DRAINAGE OBSTRUCTED
Violation Citation:	Secondary containment piping obstructed preventing drainage to sump. 2632
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/17/2006
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/17/2006
Violation Code:	6HV3193
Violation:	NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation:	Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/17/2006
Violation Code:	6HV3267
Violation:	DISP. CONTAINMENT NOT ADEQ. MONITORED
Violation Citation:	Dispenser containment not adequately monitored. 2636(f)(1) or (f)(5)(A)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/17/2006
Violation Code:	6HV3267
Violation:	DISP. CONTAINMENT NOT ADEQ. MONITORED
Violation Citation:	Dispenser containment not adequately monitored. 2636(f)(1) or (f)(5)(A)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/17/2006
Violation Code:	6HV3267
Violation:	DISP. CONTAINMENT NOT ADEQ. MONITORED
Violation Citation:	Dispenser containment not adequately monitored. 2636(f)(1) or (f)(5)(A)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	10/17/2006
Violation Code:	6HV3267
Violation:	DISP. CONTAINMENT NOT ADEQ. MONITORED
Violation Citation:	Dispenser containment not adequately monitored. 2636(f)(1) or (f)(5)(A)
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	09/28/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	09/28/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	103739

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Update Date:	11/02/2012
Inspection Date:	09/28/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	103739
Update Date:	11/02/2012
Inspection Date:	09/28/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE

UST:

UST Name:	UNDERGROUND TANK 103739 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	SINGLE WALL
Additional Id:	4601
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1999-03-19 00:00:00
Year Installed:	Not reported
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	12
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ CERTIFIED ATG: IN-TANK TEST MONTHLY, PIPE TEST ANNUALLY
UST Name:	UNDERGROUND TANK 103739 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	SINGLE WALL
Additional Id:	4602
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1999-03-19 00:00:00
Year Installed:	Not reported
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	12
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ CERTIFIED ATG: IN-TANK TEST MONTHLY, PIPE TEST ANNUALLY
UST Name:	UNDERGROUND TANK 103739 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	SINGLE WALL
Additional Id:	4603

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1999-03-19 00:00:00
Year Installed:	Not reported
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	12
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ CERTIFIED ATG: IN-TANK TEST MONTHLY, PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 103739 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	SINGLE WALL
Additional Id:	4604
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1999-03-19 00:00:00
Year Installed:	Not reported
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	12
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ CERTIFIED ATG: IN-TANK TEST MONTHLY, PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 103739 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	SINGLE WALL
Additional Id:	0000000001 UNLEADED
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1999-03-19 00:00:00
Year Installed:	Not reported
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	12
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ CERTIFIED ATG: IN-TANK TEST MONTHLY, PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 103739 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	DOUBLE WALL
Additional Id:	NT2182/RT3498, RT4350
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1999-04-21 00:00:00

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30B
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ MECHANICAL FLOAT
UST Name:	UNDERGROUND TANK 103739 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	DOUBLE WALL
Additional Id:	NT2182/RT3498, RT4350
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1999-04-21 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30B
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ MECHANICAL FLOAT
UST Name:	UNDERGROUND TANK 103739 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	DOUBLE WALL
Additional Id:	NT2182/RT3498, RT4350
Capacity Gallons:	20000
UST Contents:	MIDGRADE UNLEADED
Other Content Info:	MIDGRADE UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1999-04-21 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30B
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ MECHANICAL FLOAT
UST Name:	UNDERGROUND TANK 103739 T009
Last Update:	2012-11-02 14:17:38
Permit Number:	103739
Tank Type:	DOUBLE WALL
Additional Id:	NT2182 /RT3498, RT4350
Capacity Gallons:	20000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1999-04-21 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30B
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ MECHANICAL FLOAT

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

CERS HAZ WASTE:

Name:	WORLD OIL MARKETING CO. #46
Address:	685 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	172366
CERS ID:	10357825
CERS Description:	Hazardous Waste Generator

SWEEPS UST:

Name:	WORLD OIL MARKETING CO. #46
Address:	685 H ST
City:	CHULA VISTA
Status:	Active
Comp Number:	3739
Number:	9
Board Of Equalization:	44-011115
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-003739-000001
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	5

Name:	WORLD OIL MARKETING CO. #46
Address:	685 H ST
City:	CHULA VISTA
Status:	Active
Comp Number:	3739
Number:	9
Board Of Equalization:	44-011115
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-003739-000002
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	WORLD OIL MARKETING CO. #46
Address:	685 H ST
City:	CHULA VISTA
Status:	Active
Comp Number:	3739
Number:	9
Board Of Equalization:	44-011115

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-003739-000003
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City: CHULA VISTA
Status: Active
Comp Number: 3739
Number: 9
Board Of Equalization: 44-011115
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-003739-000004
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City: CHULA VISTA
Status: Active
Comp Number: 3739
Number: 9
Board Of Equalization: 44-011115
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-003739-000005
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

CERS TANKS:
Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 91910

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Site ID: 172366
CERS ID: 10357825
CERS Description: Underground Storage Tank

CORTESE:
Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607301884
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

SAN DIEGO CO LOP:
Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 91910
Record ID: DEH1995-LSAM-H03739-001
Record Status: Completed
Opened Date: 09/18/1995
Parcel Number: 567-201-03-00
Case Type: LOP - Local Oversight Program
Historical Name: WORLD OIL #46
SWRCB Global ID: T0607301884
Funding: S - LOP State Fund
Lead Agency: RWQCB
Lead Agency Date: 07/01/2013
Census Tract: 125.01
Community: Chula Vista
Jurisdiction: CHULA VISTA
Watershed Basin Number: 909.12
Water Purveyor: SOUTH BAY IRRIGATION LAND
Fire Agency: CHULA VISTA
Latitude: 32.6303221
Longitude: -117.0929299
X MapCoord: 6302026.9572584
Y MapCoord: 1810142.49592449

Name: WORLD OIL MARKETING CO. #46

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Address:	685 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1999-LSAM-H03739-002
Record Status:	Completed
Opened Date:	04/29/1999
Parcel Number:	567-201-03-00
Case Type:	LOP - Local Oversight Program
Historical Name:	WORLD OIL MARKETING #46
SWRCB Global ID:	T0607302686
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	04/30/1999
Census Tract:	125.01
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6303221
Longitude:	-117.0929299
X MapCoord:	6302140.886
Y MapCoord:	1810180.249

CERS:

Name:	WORLD OIL MARKETING CO. #46
Address:	685 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	172366
CERS ID:	10357825
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	172366
Site Name:	WORLD OIL MARKETING CO. #46
Violation Date:	02-12-2020
Citation:	HSC 6.7 25293 - California Health and Safety Code, Chapter 6.7, Section(s) 25293
Violation Description:	Failure to maintain UST records in sufficient detail to enable the UPA to determine whether the UST systems are in compliance.
Violation Notes:	Returned to compliance on 02/12/2020. Inspection Sequence ID:6389041;Tank ID:17791,17792,17793,17794;Violation Description:Failure to maintain UST records in sufficient detail to enable the CUPA to determine whether the UST systems are in compliance. HSC 25293
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS

Site ID:	172366
Site Name:	WORLD OIL MARKETING CO. #46
Violation Date:	09-26-2017
Citation:	23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description:	Failure to comply with one or more of the following: Failure to install or maintain a liquid-tight spill bucket. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

container. Be resistant to galvanic corrosion.
Violation Notes: Returned to compliance on 09/26/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 172366
Site Name: WORLD OIL MARKETING CO. #46
Violation Date: 09-30-2015
Citation: HSC 6.7 25291 - California Health and Safety Code, Chapter 6.7, Section(s) 25291
Violation Description: Failure to maintain under-dispenser containment, sumps, and/or other secondary containment in good condition and/or free of debris/liquid.
Violation Notes: Returned to compliance on 09/30/2015. Inspection Sequence ID:5254941;Tank ID:17791,17792,17793,17794;Violation Description:Failure to maintain under dispenser containment, sumps, and/or other secondary containment in good condition and/or free of debris/liquid. HSC 25290.1, 25290.2, 25291
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 172366
Site Name: WORLD OIL MARKETING CO. #46
Violation Date: 02-12-2020
Citation: 23 CCR 16 2636(f)(4) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(4)
Violation Description: Failure to meet one or more of the following monitoring requirements in lieu of the requirement to be tightness tested every 12 months: The monitoring system maintains all product piping outside the dispenser to be fail-safe and shut down the pump when a leak is detected. The monitoring system shuts down the pump or stops flow when a leak is detected in the under dispenser containment (UDC).
Violation Notes: Returned to compliance on 02/12/2020. Inspection Sequence ID:6389041;Tank ID:17791,17792,17793;Violation Description:(TCR 9d) Failure to meet one or more of the following monitoring requirements in lieu of the requirement to be tightness tested every 12 months: The monitoring system maintains all product piping outside the dispenser to be fail-safe and shut down the pump when a leak is detected. The monitoring system shuts down the pump or stops flow when a leak is detected in the under dispenser containment (UDC). 23 CCR 2636(f)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 172366
Site Name: WORLD OIL MARKETING CO. #46
Violation Date: 02-12-2020
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description: "Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes,

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "

Violation Notes: Returned to compliance on 02/12/2020. Inspection Sequence ID:6389041;Tank ID:17791,17792;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5898801
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5898801
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5898801
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-12-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6389041
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-14-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-14-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-14-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-28-2016
Violations Found:	No

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5500361
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-28-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5500361
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-30-2015
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254941
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-30-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254941
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-01-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Tank HT205 Inspection ID:5110174
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-01-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Tank HT205 Inspection ID:5110174
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-01-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Tank HT205 Inspection ID:5110174
Eval Division:	San Diego County Department of Env Health

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-02-2013
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:4086938
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-02-2013
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:4086938
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS

Coordinates:

Site ID:	172366
Facility Name:	WORLD OIL MARKETING CO. #46
Env Int Type Code:	HWG
Program ID:	10357825
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	32.630320
Longitude:	-117.092930

Affiliation:

Affiliation Type Desc:	Document Preparer
Entity Name:	Evelyn Kywe
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Environmental Contact
Entity Name:	John Hundley
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90280
Affiliation Phone:	Not reported
Affiliation Type Desc:	UST PO Name
Entity Name:	WLD OIL CORPRT
Entity Title:	Not reported
Affiliation Address:	9302 GARFIELD AVE

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Affiliation City:	SOUTHGATE
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	Jim Tostado
Entity Title:	Director
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Operator
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213374
Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN SAN DIEGO RWQCB REGN 9
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVENA SUITE 100
Affiliation City:	SANDIEGO
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	UST Tank Operator
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	Environmental Contact

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Entity Name:	JOHN HUNDLEY
Entity Title:	Not reported
Affiliation Address:	9302 GARFIELD AVE
Affiliation City:	SOUTHGATE
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90280
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	Property Owner
Entity Name:	WLD OIL CORPRT
Entity Title:	Not reported
Affiliation Address:	9302 GARFIELD AVE
Affiliation City:	SOUTHGATE
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880
Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	EWAN MOFFAT SAN DIEGO CNTY LOP
Entity Title:	Not reported
Affiliation Address:	POBOX 129261
Affiliation City:	SANDIEGO
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Affiliation Phone:	Not reported
Affiliation Type Desc:	Parent Corporation
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner
Entity Name:	World Oil Corp.
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	UST Permit Applicant
Entity Name:	Jim Tostado
Entity Title:	Director
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	World Oil Corp.
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	UST Tank Owner
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Name:	WORLD OIL MARKETING CO. #46
Address:	685 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	172366

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

CERS ID: T0607301884
CERS Description: Leaking Underground Storage Tank Cleanup Site

Violations:

Site ID: 172366
Site Name: WORLD OIL MARKETING CO. #46
Violation Date: 02-12-2020
Citation: HSC 6.7 25293 - California Health and Safety Code, Chapter 6.7, Section(s) 25293
Violation Description: Failure to maintain UST records in sufficient detail to enable the UPA to determine whether the UST systems are in compliance.
Violation Notes: Returned to compliance on 02/12/2020. Inspection Sequence ID:6389041;Tank ID:17791,17792,17793,17794;Violation Description:Failure to maintain UST records in sufficient detail to enable the CUPA to determine whether the UST systems are in compliance. HSC 25293
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 172366
Site Name: WORLD OIL MARKETING CO. #46
Violation Date: 09-26-2017
Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description: Failure to comply with one or more of the following: Failure to install or maintain a liquid-tight spill bucket. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container. Be resistant to galvanic corrosion.
Violation Notes: Returned to compliance on 09/26/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 172366
Site Name: WORLD OIL MARKETING CO. #46
Violation Date: 09-30-2015
Citation: HSC 6.7 25291 - California Health and Safety Code, Chapter 6.7, Section(s) 25291
Violation Description: Failure to maintain under-dispenser containment, sumps, and/or other secondary containment in good condition and/or free of debris/liquid.
Violation Notes: Returned to compliance on 09/30/2015. Inspection Sequence ID:5254941;Tank ID:17791,17792,17793,17794;Violation Description:Failure to maintain under dispenser containment, sumps, and/or other secondary containment in good condition and/or free of debris/liquid. HSC 25290.1, 25290.2, 25291
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 172366
Site Name: WORLD OIL MARKETING CO. #46
Violation Date: 02-12-2020
Citation: 23 CCR 16 2636(f)(4) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(4)
Violation Description: Failure to meet one or more of the following monitoring requirements in lieu of the requirement to be tightness tested every 12 months: The

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

monitoring system maintains all product piping outside the dispenser to be fail-safe and shut down the pump when a leak is detected. The monitoring system shuts down the pump or stops flow when a leak is detected in the under dispenser containment (UDC).

Violation Notes: Returned to compliance on 02/12/2020. Inspection Sequence ID:6389041;Tank ID:17791,17792,17793;Violation Description:(TCR 9d) Failure to meet one or more of the following monitoring requirements in lieu of the requirement to be tightness tested every 12 months: The monitoring system maintains all product piping outside the dispenser to be fail-safe and shut down the pump when a leak is detected. The monitoring system shuts down the pump or stops flow when a leak is detected in the under dispenser containment (UDC). 23 CCR 2636(f)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 172366
Site Name: WORLD OIL MARKETING CO. #46
Violation Date: 02-12-2020
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description: "Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "
Violation Notes: Returned to compliance on 02/12/2020. Inspection Sequence ID:6389041;Tank ID:17791,17792;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5898801
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-02-2018
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5898801
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-02-2018
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5898801
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-12-2020
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6389041
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-14-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-14-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-14-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	No

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-28-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5500361
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-28-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5500361
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-30-2015
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254941
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-30-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254941
Eval Division:	San Diego County Department of Env Health

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-01-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Tank HT205 Inspection ID:5110174
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-01-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Tank HT205 Inspection ID:5110174
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-01-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Tank HT205 Inspection ID:5110174
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-02-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:4086938
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-02-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:4086938
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Coordinates:
Site ID: 172366
Facility Name: WORLD OIL MARKETING CO. #46
Env Int Type Code: HWG
Program ID: 10357825
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.630320
Longitude: -117.092930

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Affiliation:

Affiliation Type Desc:	Document Preparer
Entity Name:	Evelyn Kywe
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Environmental Contact
Entity Name:	John Hundley
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90280
Affiliation Phone:	Not reported

Affiliation Type Desc:	UST PO Name
Entity Name:	WLD OIL CORPRT
Entity Title:	Not reported
Affiliation Address:	9302 GARFIELD AVE
Affiliation City:	SOUTHGATE
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Identification Signer
Entity Name:	Jim Tostado
Entity Title:	Director
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Operator
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(562) 928-0100

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213374
Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN SAN DIEGO RWQCB REGN 9
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVENA SUITE 100
Affiliation City:	SANDIEGO
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	UST Tank Operator
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	Environmental Contact
Entity Name:	JOHN HUNDLEY
Entity Title:	Not reported
Affiliation Address:	9302 GARFIELD AVE
Affiliation City:	SOUTHGATE
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90280
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	Property Owner
Entity Name:	WLD OIL CORPRT
Entity Title:	Not reported

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Affiliation Address:	9302 GARFIELD AVE
Affiliation City:	SOUTHGATE
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880
Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	EWAN MOFFAT SAN DIEGO CNTY LOP
Entity Title:	Not reported
Affiliation Address:	POBOX 129261
Affiliation City:	SANDIEGO
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Parent Corporation
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner
Entity Name:	World Oil Corp.
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	UST Permit Applicant
Entity Name:	Jim Tostado
Entity Title:	Director
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(562) 928-0100

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Affiliation Type Desc:	UST Property Owner Name
Entity Name:	World Oil Corp.
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100

Affiliation Type Desc:	UST Tank Owner
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100

Name:	WORLD OIL MARKETING CO. #46
Address:	685 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	172366
CERS ID:	110018988871
CERS Description:	US EPA Air Emission Inventory System (EIS)

Violations:

Site ID:	172366
Site Name:	WORLD OIL MARKETING CO. #46
Violation Date:	02-12-2020
Citation:	HSC 6.7 25293 - California Health and Safety Code, Chapter 6.7, Section(s) 25293
Violation Description:	Failure to maintain UST records in sufficient detail to enable the UPA to determine whether the UST systems are in compliance.
Violation Notes:	Returned to compliance on 02/12/2020. Inspection Sequence ID:6389041;Tank ID:17791,17792,17793,17794;Violation Description:Failure to maintain UST records in sufficient detail to enable the CUPA to determine whether the UST systems are in compliance. HSC 25293
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS

Site ID:	172366
Site Name:	WORLD OIL MARKETING CO. #46
Violation Date:	09-26-2017
Citation:	23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description:	Failure to comply with one or more of the following: Failure to install or maintain a liquid-tight spill bucket. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container. Be resistant to galvanic corrosion.
Violation Notes:	Returned to compliance on 09/26/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Violation Source:	CERS
Site ID:	172366
Site Name:	WORLD OIL MARKETING CO. #46
Violation Date:	09-30-2015
Citation:	HSC 6.7 25291 - California Health and Safety Code, Chapter 6.7, Section(s) 25291
Violation Description:	Failure to maintain under-dispenser containment, sumps, and/or other secondary containment in good condition and/or free of debris/liquid.
Violation Notes:	Returned to compliance on 09/30/2015. Inspection Sequence ID:5254941;Tank ID:17791,17792,17793,17794;Violation Description:Failure to maintain under dispenser containment, sumps, and/or other secondary containment in good condition and/or free of debris/liquid. HSC 25290.1, 25290.2, 25291
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	172366
Site Name:	WORLD OIL MARKETING CO. #46
Violation Date:	02-12-2020
Citation:	23 CCR 16 2636(f)(4) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(4)
Violation Description:	Failure to meet one or more of the following monitoring requirements in lieu of the requirement to be tightness tested every 12 months: The monitoring system maintains all product piping outside the dispenser to be fail-safe and shut down the pump when a leak is detected. The monitoring system shuts down the pump or stops flow when a leak is detected in the under dispenser containment (UDC).
Violation Notes:	Returned to compliance on 02/12/2020. Inspection Sequence ID:6389041;Tank ID:17791,17792,17793;Violation Description:(TCR 9d) Failure to meet one or more of the following monitoring requirements in lieu of the requirement to be tightness tested every 12 months: The monitoring system maintains all product piping outside the dispenser to be fail-safe and shut down the pump when a leak is detected. The monitoring system shuts down the pump or stops flow when a leak is detected in the under dispenser containment (UDC). 23 CCR 2636(f)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	172366
Site Name:	WORLD OIL MARKETING CO. #46
Violation Date:	02-12-2020
Citation:	HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description:	"Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "
Violation Notes:	Returned to compliance on 02/12/2020. Inspection Sequence

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

ID:6389041;Tank ID:17791,17792;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5898801
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5898801
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5898801
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-12-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6389041
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-14-2019
Violations Found: No
Eval Type: Routine done by local agency

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-14-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-14-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:6079706
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-26-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5727707
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-28-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5500361
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-28-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5500361
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-30-2015
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254941
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-30-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254941
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-01-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Tank HT205 Inspection ID:5110174
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-01-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Tank HT205 Inspection ID:5110174
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-01-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Tank HT205 Inspection ID:5110174
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Eval Date: 10-02-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:4086938
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-02-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:4086938
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Coordinates:
Site ID: 172366
Facility Name: WORLD OIL MARKETING CO. #46
Env Int Type Code: HWG
Program ID: 10357825
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.630320
Longitude: -117.092930

Affiliation:
Affiliation Type Desc: Document Preparer
Entity Name: Evelyn Kywe
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: John Hundley
Entity Title: Not reported
Affiliation Address: 9302 Garfield Ave.
Affiliation City: South Gate
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 90280
Affiliation Phone: Not reported

Affiliation Type Desc: UST PO Name
Entity Name: WLD OIL CORPRT
Entity Title: Not reported
Affiliation Address: 9302 GARFIELD AVE
Affiliation City: SOUTHGATE
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	Jim Tostado
Entity Title:	Director
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Operator
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213374
Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN SAN DIEGO RWQCB REGN 9
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVENA SUITE 100
Affiliation City:	SANDIEGO
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	UST Tank Operator
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	Environmental Contact
Entity Name:	JOHN HUNDLEY
Entity Title:	Not reported
Affiliation Address:	9302 GARFIELD AVE
Affiliation City:	SOUTHGATE

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90280
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	Property Owner
Entity Name:	WLD OIL CORPRT
Entity Title:	Not reported
Affiliation Address:	9302 GARFIELD AVE
Affiliation City:	SOUTHGATE
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880
Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	EWAN MOFFAT SAN DIEGO CNTY LOP
Entity Title:	Not reported
Affiliation Address:	POBOX 129261
Affiliation City:	SANDIEGO
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Parent Corporation
Entity Name:	World Oil Marketing Company

WORLD OIL MARKETING CO. #46 (Continued) **U003943055**

Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner
Entity Name:	World Oil Corp.
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	UST Permit Applicant
Entity Name:	Jim Tostado
Entity Title:	Director
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	World Oil Corp.
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100
Affiliation Type Desc:	UST Tank Owner
Entity Name:	World Oil Marketing Company
Entity Title:	Not reported
Affiliation Address:	9302 Garfield Ave.
Affiliation City:	South Gate
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90280
Affiliation Phone:	(562) 928-0100

L80 **WORLD OIL STATION #46** **LUST** **S104539615**
East **685 H ST** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910**
0.297 mi.
1567 ft. **Site 4 of 5 in cluster L**

Relative: **Higher**
Actual: **36 ft.**

LUST REG 9:

Region:	9
Status:	Case Closed
Case Number:	9UT3926
Local Case:	H03739-002
Substance:	Waste Oil
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Tank
Cause:	Corrosion
Lead Agency:	Local Agency
Case Type:	Soil only
Date Found:	04/29/1999
Date Stopped:	04/29/1999
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	04/30/1999
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	04/29/1999
Enforce Date:	Not reported
Closed Date:	4/25/00
Enforce Type:	Not reported
Pilot Program:	LOP
Basin Number:	909.12
GW Depth:	17.09
Beneficial Use:	MUNBU
NPDES Number:	Not reported
Priority:	Low priority. Priority ranking can change over time.
File Dispn:	Administratively opened on database, however no file physically exists
Interim Remedial Actions:	Not reported
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

L81 **WORLD OIL #46** **LUST** **S100726393**
East **685 H ST** **Cortese** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910** **HIST CORTESE**
0.297 mi. **CERS**
1567 ft. **Site 5 of 5 in cluster L**

Relative: **Higher**
Actual: **36 ft.**

LUST REG 9:

Region:	9
Status:	Preliminary site assessment underway
Case Number:	9UT3117
Local Case:	H03739-001
Substance:	Gasoline
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego

WORLD OIL #46 (Continued) **S100726393**

How Found: Not reported
How Stopped: Not reported
Source: Tank
Cause: Unknown
Lead Agency: Local Agency
Case Type: Soil only
Date Found: 09/18/1995
Date Stopped: / /
Confirm Date: / /
Submit Workplan: 9/18/95
Prelim Assess: 10/24/1995
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 09/18/1995
Enforce Date: 10/17/95
Closed Date: Not reported
Enforce Type: SEL
Pilot Program: LOP
Basin Number: 909.12
GW Depth: Not reported
Beneficial Use: Municipal groundwater use
NPDES Number: Not reported
Priority: Low priority. Priority ranking can change over time.
File Dispn: Administratively opened on database, however no file physically exists
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

LUST:
Name: WORLD OIL MARKETING CO. #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301884
Global Id: T0607301884
Latitude: 32.6302506340439
Longitude: -117.092884163229
Status: Completed - Case Closed
Status Date: 06/21/2017
Case Worker: SM
RB Case Number: 9UT3117
Local Agency: Not reported
File Location: Local Agency
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: In August 1995 two hand-auger borings were advanced near the UST pit which detected petroleum hydrocarbon impacted soil. DEH case H03739-001 was opened and multiple wells and borings were advanced on and offsite to assess hydrocarbon impacted soil and groundwater. On April 23, 2003, an IRAP was implemented with the startup of a high vacuum dual-phase extraction system in an effort to mitigate several feet of liquid-phase hydrocarbons observed across the site. The system operated until 2007 when DEH directed the RP to shut down the

WORLD OIL #46 (Continued) **S100726393**

system until disagreements with the adjacent Thrifty Station (H20174) about responsibility for offsite impacts could be alleviated.

LUST:
Global Id: T0607301884
Contact Type: Regional Board Caseworker
Contact Name: SEAN MCCLAIN
Organization Name: SAN DIEGO RWQCB (REGION 9)
Address: 2375 NORTHSIDE DRIVE, SUITE 100
City: SAN DIEGO
Email: sean.mcclain@waterboards.ca.gov
Phone Number: 6195213374

LUST:
Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 01/14/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 10/18/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 07/01/2013
Action: Referral to Regional Board

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 06/21/2017
Action: Closure/No Further Action Letter

Global Id: T0607301884
Action Type: RESPONSE
Date: 08/02/2012
Action: Remedial Progress Report

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 06/19/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 11/19/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 06/14/2017
Action: Email Correspondence

Global Id: T0607301884
Action Type: Other
Date: 09/18/1995

WORLD OIL #46 (Continued) **S100726393**

Action:	Leak Reported
Global Id:	T0607301884
Action Type:	RESPONSE
Date:	01/15/2013
Action:	Correspondence
Global Id:	T0607301884
Action Type:	RESPONSE
Date:	01/14/2013
Action:	Correspondence
Global Id:	T0607301884
Action Type:	RESPONSE
Date:	01/16/2013
Action:	Monitoring Report - Semi-Annually
Global Id:	T0607301884
Action Type:	ENFORCEMENT
Date:	07/09/2009
Action:	Letter - Notice
Global Id:	T0607301884
Action Type:	RESPONSE
Date:	05/07/2013
Action:	Monitoring Report - Semi-Annually
Global Id:	T0607301884
Action Type:	RESPONSE
Date:	04/08/2013
Action:	Well Installation Report
Global Id:	T0607301884
Action Type:	ENFORCEMENT
Date:	08/12/2009
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607301884
Action Type:	ENFORCEMENT
Date:	01/05/2010
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607301884
Action Type:	RESPONSE
Date:	07/31/2009
Action:	Monitoring Report - Semi-Annually
Global Id:	T0607301884
Action Type:	RESPONSE
Date:	01/30/2009
Action:	Monitoring Report - Quarterly
Global Id:	T0607301884
Action Type:	RESPONSE
Date:	11/06/2009
Action:	Monitoring Report - Semi-Annually

WORLD OIL #46 (Continued) **S100726393**

Global Id: T0607301884
Action Type: RESPONSE
Date: 01/31/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607301884
Action Type: RESPONSE
Date: 03/06/2015
Action: Monitoring Report - Other

Global Id: T0607301884
Action Type: RESPONSE
Date: 10/21/2014
Action: Other Report / Document

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 04/06/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 03/18/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607301884
Action Type: RESPONSE
Date: 05/04/2009
Action: Other Report / Document

Global Id: T0607301884
Action Type: RESPONSE
Date: 03/30/2009
Action: Soil and Water Investigation Workplan

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 09/29/2016
Action: Notification - Fee Title Owners Notice

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 09/29/2016
Action: Notification - Public Notice of Case Closure

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 11/05/2015
Action: Staff Letter

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 04/11/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607301884
Action Type: Other

WORLD OIL #46 (Continued) **S100726393**

Date: 09/18/1995
Action: Leak Began

Global Id: T0607301884
Action Type: RESPONSE
Date: 02/23/2016
Action: Monitoring Report - Other

Global Id: T0607301884
Action Type: RESPONSE
Date: 06/21/2017
Action: Well Destruction Report

Global Id: T0607301884
Action Type: Other
Date: 09/18/1995
Action: Leak Discovery

Global Id: T0607301884
Action Type: RESPONSE
Date: 11/30/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607301884
Action Type: RESPONSE
Date: 03/02/2012
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607301884
Action Type: RESPONSE
Date: 05/18/2012
Action: Other Report / Document - Regulator Responded

Global Id: T0607301884
Action Type: RESPONSE
Date: 11/05/2012
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301884
Action Type: RESPONSE
Date: 05/13/2013
Action: Corrective Action Plan / Remedial Action Plan - Regulator Responded

Global Id: T0607301884
Action Type: RESPONSE
Date: 01/20/2014
Action: Other Workplan - Regulator Responded

Global Id: T0607301884
Action Type: RESPONSE
Date: 12/20/2013
Action: Other Workplan - Regulator Responded

Global Id: T0607301884
Action Type: RESPONSE
Date: 05/07/2013
Action: CAP/RAP - Other Report - Regulator Responded

WORLD OIL #46 (Continued) **S100726393**

Global Id: T0607301884
Action Type: RESPONSE
Date: 01/20/2014
Action: Soil Vapor Intrusion Investigation Report - Regulator Responded

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 10/17/1995
Action: Notice of Responsibility

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 05/03/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301884
Action Type: RESPONSE
Date: 05/05/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607301884
Action Type: RESPONSE
Date: 05/09/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607301884
Action Type: RESPONSE
Date: 01/31/2011
Action: Monitoring Report - Other

Global Id: T0607301884
Action Type: RESPONSE
Date: 03/28/2011
Action: Other Report / Document

Global Id: T0607301884
Action Type: RESPONSE
Date: 07/21/2011
Action: Other Report / Document

Global Id: T0607301884
Action Type: RESPONSE
Date: 11/03/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607301884
Action Type: RESPONSE
Date: 02/02/2016
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301884
Action Type: ENFORCEMENT
Date: 05/03/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301884
Action Type: ENFORCEMENT

WORLD OIL #46 (Continued) **S100726393**

Date: 10/23/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301884
Action Type: RESPONSE
Date: 02/03/2012
Action: Monitoring Report - Quarterly

Global Id: T0607301884
Action Type: RESPONSE
Date: 05/02/2012
Action: Monitoring Report - Semi-Annually

LUST:
Global Id: T0607301884
Status: Open - Case Begin Date
Status Date: 09/18/1995

Global Id: T0607301884
Status: Open - Remediation
Status Date: 09/18/1998

Global Id: T0607301884
Status: Open - Verification Monitoring
Status Date: 02/29/2016

Global Id: T0607301884
Status: Open - Eligible for Closure
Status Date: 12/15/2016

Global Id: T0607301884
Status: Completed - Case Closed
Status Date: 06/21/2017

Name: WORLD OIL #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302686
Global Id: T0607302686
Latitude: 32.630238209174
Longitude: -117.092786729336
Status: Completed - Case Closed
Status Date: 04/25/2000
Case Worker: EM
RB Case Number: 9UT3926
Local Agency: SAN DIEGO COUNTY LOP
File Location: Local Agency
Local Case Number: H03739-002
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

LUST:
Global Id: T0607302686

WORLD OIL #46 (Continued) **S100726393**

Contact Type: Local Agency Caseworker
Contact Name: EWAN MOFFAT
Organization Name: SAN DIEGO COUNTY LOP
Address: P.O. Box 129261
City: San Diego
Email: ewan.moffat@sdcounty.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607302686
Action Type: ENFORCEMENT
Date: 04/25/2000
Action: Closure/No Further Action Letter

Global Id: T0607302686
Action Type: Other
Date: 04/29/1999
Action: Leak Reported

Global Id: T0607302686
Action Type: Other
Date: 04/29/1999
Action: Leak Began

Global Id: T0607302686
Action Type: Other
Date: 04/29/1999
Action: Leak Discovery

LUST:
Global Id: T0607302686
Status: Open - Case Begin Date
Status Date: 04/29/1999

Global Id: T0607302686
Status: Completed - Case Closed
Status Date: 04/25/2000

CORTESE:
Name: WORLD OIL #46
Address: 685 H ST
City,State,Zip: CHULA VISTA, CA 919104222
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607302686
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active

WORLD OIL #46 (Continued) **S100726393**

Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	WORLD OIL MARKETING #46
edr_fadd1:	685 H
City,State,Zip:	CHULA VISTA, CA 92010
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT3926

edr_fname:	WORLD OIL #46
edr_fadd1:	685 H
City,State,Zip:	CHULA VISTA, CA 92010
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT3117

CERS:

Name:	WORLD OIL #46
Address:	685 H ST
City,State,Zip:	CHULA VISTA, CA 919104222
Site ID:	258186
CERS ID:	T0607302686
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	EWAN MOFFAT - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

O82 **PRUDENTIAL OVERALL SUPPLY** **Cortese** **S123771662**
NNE **740 F ST** **HAZNET** **N/A**
1/4-1/2 **CHULA VISTA, CA 92010** **HWTS**
0.305 mi.
1612 ft. **Site 2 of 3 in cluster O**

Relative:
Higher

Actual:
32 ft.

CORTESE:

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
City,State,Zip:	CHULA VISTA, CA 919102006
Region:	CORTESE

PRUDENTIAL OVERALL SUPPLY (Continued) **S123771662**

Envirostor Id:	Not reported
Global ID:	T0607301090
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
City,State,Zip:	CHULA VISTA, CA 92010
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607302719
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HAZNET:

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 920100000
Contact:	ALBERT BECKER
Telephone:	6194271240
Mailing Name:	Not reported
Mailing Address:	--

Year: 1986

PRUDENTIAL OVERALL SUPPLY (Continued) **S123771662**

Gepaid: CAX000031211
TSD EPA ID: CAD981161128
CA Waste Code: 221 - Waste oil and mixed oil
Disposal Method: 01 -
Tons: 1.251

Year: 1986
Gepaid: CAX000031211
TSD EPA ID: Not reported
CA Waste Code: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method: 01 -
Tons: 12.927

Year: 1986
Gepaid: CAX000031211
TSD EPA ID: Not reported
CA Waste Code: 221 - Waste oil and mixed oil
Disposal Method: 01 -
Tons: 14.2822

Year: 1986
Gepaid: CAX000031211
TSD EPA ID: CAT080013552
CA Waste Code: 221 - Waste oil and mixed oil
Disposal Method: -
Tons: 0.834

Year: 1986
Gepaid: CAX000031211
TSD EPA ID: CAT000646117
CA Waste Code: 241 - Tank bottom waste
Disposal Method: D99 - Disposal, Other
Tons: 8.34

Year: 1986
Gepaid: CAX000031211
TSD EPA ID: CAD095894556
CA Waste Code: 241 - Tank bottom waste
Disposal Method: T01 - Treatment, Tank
Tons: 0.1251

Year: 1986
Gepaid: CAX000031211
TSD EPA ID: CAD095894556
CA Waste Code: 241 - Tank bottom waste
Disposal Method: D99 - Disposal, Other
Tons: 1.668

Year: 1985
Gepaid: CAX000031211
TSD EPA ID: CAT080011059
CA Waste Code: 221 - Waste oil and mixed oil
Disposal Method: R01 - Recycler
Tons: 2.085

Year: 1985
Gepaid: CAX000031211

PRUDENTIAL OVERALL SUPPLY (Continued) **S123771662**

TSD EPA ID:	CAT080011059
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	01 -
Tons:	0.834
Year:	1985
Gepaid:	CAX000031211
TSD EPA ID:	CAT080011059
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	-
Tons:	4.3368

Click this hyperlink while viewing on your computer to access
3 additional CA HAZNET: record(s) in the EDR Site Report.

HWTS:

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 920100000
EPA ID:	CAX000031211
Inactive Date:	06/30/1998
Create Date:	08/24/1983
Last Act Date:	04/27/1999
Mailing Name:	Not reported
Mailing Address:	--
Mailing Address 2:	Not reported
Mailing City,State,Zip:	CHULA VISTA, CA 920100000
Owner Name:	--
Owner Address:	--
Owner Address 2:	Not reported
Owner City,State,Zip:	--, 99 --
Contact Name:	ALBERT BECKER
Contact Address:	INACT PER 98VQ FINAL NOTICE
Contact Address 2:	- BATCH 4/27
City,State,Zip:	--, 99 --

O83 **PRUDENTIAL OVERALL SUPPLY** **RCRA-SQG** **1000187281**
NNE **740 F STREET** **LUST** **CAD028015410**
1/4-1/2 **CHULA VISTA, CA 91910** **SAN DIEGO CO. SAM**
0.305 mi. **San Diego Co. HMMD**
1612 ft. **Site 3 of 3 in cluster O** **CERS HAZ WASTE**
SWEEPS UST
Relative: Higher **HIST UST**
FINDS
Actual: 32 ft. **ECHO**
HIST CORTESE
SAN DIEGO CO LOP
CERS

RCRA-SQG:

Date Form Received by Agency:	1988-12-31 00:00:00.0
Handler Name:	PRUDENTIAL OVERALL SUPPLY
Handler Address:	740 F STREET
Handler City,State,Zip:	CHULA VISTA, CA 91910
EPA ID:	CAD028015410

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	740 F STREET
Contact City,State,Zip:	CHULA VISTA, CA 92010
Contact Telephone:	619-427-1240
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Other
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	4
Mailing Address:	740 F STREET
Mailing City,State,Zip:	CHULA VISTA, CA 91910
Owner Name:	JOHN D CLARK
Owner Type:	Private
Operator Name:	NOT REQUIRED
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:23:07.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JOHN D CLARK
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1988-12-31 00:00:00.0
Handler Name:	PRUDENTIAL OVERALL SUPPLY
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 812332
NAICS Description: INDUSTRIAL LAUNDERERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LUST REG 9:
Region: 9
Status: Remedial action (cleanup) Underway
Case Number: 9UT2320
Local Case: H11432-002
Substance: Stoddard Solvent
Qty Leaked: Not reported
Abate Method: Remove Free Product - remove floating product from water table
Local Agency: San Diego
How Found: Other Means
How Stopped: Other Means
Source: Tank
Cause: Unknown
Lead Agency: Local Agency
Case Type: Aquifer affected
Date Found: 11/16/1992
Date Stopped: 11/16/1992
Confirm Date: 09/03/1986
Submit Workplan: 11/16/92
Prelim Assess: / /
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: 11/16/92
Began Monitor: Not reported
Release Date: 11/16/1992
Enforce Date: Not reported
Closed Date: Not reported
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 909.12
GW Depth: 20’
Beneficial Use: MUNBU
NPDES Number: Not reported
Priority: 2B
File Dispn: Not reported
Interim Remedial Actions: Yes
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Region: 9
Status: Case Closed
Case Number: 9UT403
Local Case: H11432-001
Substance: Diesel
Qty Leaked: Not reported
Abate Method: EDFP
Local Agency: San Diego
How Found: Tank Closure
How Stopped: Close Tank
Source: Tank
Cause: Overfill
Lead Agency: Regional Board
Case Type: Aquifer affected
Date Found: 09/03/1986
Date Stopped: 09/03/1986
Confirm Date: / /
Submit Workplan: Not reported
Prelim Assess: 09/21/1987
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 09/05/1986
Enforce Date: Not reported
Closed Date: 2/18/88
Enforce Type: Not reported
Pilot Program: UST
Basin Number: 909.12
GW Depth: ~20
Beneficial Use: Municipal groundwater use
NPDES Number: Not reported
Priority: Not reported
File Dispn: Not reported
Interim Remedial Actions: Yes
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

LUST:
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 919102006
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301090
Global Id: T0607301090
Latitude: 32.6356164180624
Longitude: -117.096812725067
Status: Completed - Case Closed
Status Date: 05/05/2017
Case Worker: SM
RB Case Number: 9UT0403
Local Agency: Not reported
File Location: Local Agency
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Tetrachloroethylene (PCE), Trichloroethylene (TCE), Diesel, Stoddard

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

solvent / Mineral Spriits / Distillates

Site History: A release from Underground Storage Tanks was identified in September 1986. The UST's were removed and soil excavation activities took place at that time. Site assessment activities have been ongoing, and additional remediation activities are currently being evaluated. Please see the submitted ESI documents for additional site specific information.

LUST:
Global Id: T0607301090
Contact Type: Regional Board Caseworker
Contact Name: SEAN MCCLAIN
Organization Name: SAN DIEGO RWQCB (REGION 9)
Address: 2375 NORTHSIDE DRIVE, SUITE 100
City: SAN DIEGO
Email: sean.mcclain@waterboards.ca.gov
Phone Number: 6195213374

LUST:
Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 07/22/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 07/01/2013
Action: Referral to Regional Board

Global Id: T0607301090
Action Type: Other
Date: 09/03/1986
Action: Leak Reported

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 05/06/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 07/08/2009
Action: Letter - Notice

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 07/24/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301090
Action Type: RESPONSE
Date: 10/24/2014
Action: Other Report / Document

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 01/25/2011

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Action: Technical Correspondence / Assistance / Other

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 05/31/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 08/31/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 10/12/2016
Action: Email Correspondence

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 08/04/2016
Action: Notification - Fee Title Owners Notice

Global Id: T0607301090
Action Type: Other
Date: 09/03/1986
Action: Leak Began

Global Id: T0607301090
Action Type: RESPONSE
Date: 05/15/2016
Action: Request for Closure

Global Id: T0607301090
Action Type: RESPONSE
Date: 04/17/2017
Action: Well Destruction Report

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 11/16/1992
Action: Notice of Responsibility

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 11/18/2011
Action: Staff Letter

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 01/12/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 08/04/2016
Action: Notification - Preclosure

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Global Id: T0607301090
Action Type: Other
Date: 09/03/1986
Action: Leak Discovery

Global Id: T0607301090
Action Type: RESPONSE
Date: 01/30/2010
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 09/03/2009
Action: Interim Remedial Action Plan - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 11/30/2009
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 04/30/2010
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 04/30/2011
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 10/31/2011
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 01/02/2012
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 04/30/2012
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 04/30/2013
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 11/28/2012
Action: Site Assessment Report - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Date: 10/31/2012
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: RESPONSE
Date: 06/08/2015
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 05/05/2017
Action: Closure/No Further Action Letter

Global Id: T0607301090
Action Type: RESPONSE
Date: 06/07/2016
Action: Request for Closure - Regulator Responded

Global Id: T0607301090
Action Type: ENFORCEMENT
Date: 05/14/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301090
Action Type: Other
Date: 09/03/1986
Action: Leak Stopped

LUST:
Global Id: T0607301090
Status: Open - Case Begin Date
Status Date: 09/03/1986

Global Id: T0607301090
Status: Open - Remediation
Status Date: 06/08/2000

Global Id: T0607301090
Status: Open - Verification Monitoring
Status Date: 03/17/2016

Global Id: T0607301090
Status: Open - Eligible for Closure
Status Date: 08/15/2016

Global Id: T0607301090
Status: Completed - Case Closed
Status Date: 05/05/2017

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 92010
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302719
Global Id: T0607302719

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Latitude: 32.635905
Longitude: -117.096999
Status: Completed - Case Closed
Status Date: 02/18/1988
Case Worker: DTB
RB Case Number: 9UT403
Local Agency: Not reported
File Location: Not reported
Local Case Number: H11432-001
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Diesel
Site History: Not reported

LUST:
Global Id: T0607302719
Contact Type: Regional Board Caseworker
Contact Name: DAVID T. BARKER
Organization Name: SAN DIEGO RWQCB (REGION 9)
Address: 2375 NORTHSIDE DRIVE, SUITE 100
City: SAN DIEGO
Email: david.barker@waterboards.ca.gov
Phone Number: 6195213007

LUST:
Global Id: T0607302719
Action Type: Other
Date: 09/05/1986
Action: Leak Reported

Global Id: T0607302719
Action Type: Other
Date: 09/03/1986
Action: Leak Discovery

Global Id: T0607302719
Action Type: Other
Date: 09/03/1986
Action: Leak Stopped

LUST:
Global Id: T0607302719
Status: Open - Case Begin Date
Status Date: 09/03/1986

Global Id: T0607302719
Status: Open - Site Assessment
Status Date: 09/21/1987

Global Id: T0607302719
Status: Completed - Case Closed
Status Date: 02/18/1988

SAN DIEGO CO. SAM:
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

City,State,Zip: CHULA VISTA, CA 919102006
Case Number: H11432-001
Agency: CA Regional Water Quality Control Board
Funding: **Non Billable**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 2/18/1988
Date Began: 9/5/1986

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 919102006
Case Number: H11432-002
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Action (Clean-Up)
Date: 1/26/2001
Date Began: 9/3/1986

HMMD SAN DIEGO:
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: Not reported
Business Type: Not reported
EPA Id Number: CAD981983265
APN: Not reported
Last HMMD Inspection: Not reported
Facility Telephone: (619) 427-1240
Permit Status: Permit Renewed
Permit Expiration: Not reported
Date Last Updated: 05/06/2020
Facility Owner: Not reported
Facility Mailing Address: P.O. Box 11210, Santa Ana, CA 92711
Facility Mailing City: Not reported
Facility Mailing State: Not reported
Facility Mailing Zip: Not reported
UST Owner: N
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: N
Generate Medical Waste: Not reported

Inspection Violation:
Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-111432
Program Element: Hazardous Materials Release Response Plans
Inspection Type: Routine
Inspection Number: 4385152
Return To Compliance Date: 2015-04-09T00:00:00.000
Nov: No
Violation Classification: Class II

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-05-06T15:42:49.000
Inspection Date:	2015-01-21T00:00:00.000
Violation Code:	1010005 Failure to complete and/or submit an annotated site map if required by CUPA; HSC 6.95 25505(a)2.
Record ID:	DEH2002-HUPFP-111432
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-111432
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	4385152
Return To Compliance Date:	2015-04-09T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-05-06T15:42:49.000
Inspection Date:	2015-01-21T00:00:00.000
Violation Code:	1010008 Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date. For facilities with invenntory that exceed EPCRA thresholds; failure to submit inventory reports (Activities, Owner/Operator, Hazardous Materials Descriptions and Map pages HSC 6.95 25508.2 / 19 CCR 4 2729.5(c)
Record ID:	DEH2002-HUPFP-111432
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-111432
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	4385152
Return To Compliance Date:	2015-04-09T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-05-06T15:42:49.000
Inspection Date:	2015-01-21T00:00:00.000
Violation Code:	1010006 Failure to update hazardous material inventory within 30 days when one of the following occurs: A 100 percent or more increase in the quantity of a previously disclosed material; Any handling of a previously undisclosed hazardous materials; A change of business address, business ownership, or business name; HSC 6.95 25508.1(a)/(b)/(c)/(d)/(e).
Record ID:	DEH2002-HUPFP-111432
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-111432
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5591577
Return To Compliance Date:	2017-02-20T00:00:00.000
Nov:	No

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-05-06T15:42:49.000
Inspection Date:	2017-01-03T14:46:00.000
Violation Code:	1020002 Initial and/or annual employee training not conducted for hazardous materials management and/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4)
Record ID:	DEH2002-HUPFP-111432
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-111432
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6080736
Return To Compliance Date:	2019-05-13T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-05-06T15:42:49.000
Inspection Date:	2019-05-13T16:10:53.000
Violation Code:	1010004 Chemical inventory incomplete or not submitted in CERS. HSC 25505(a)(1); 25507(a); 25508.1(a-b); 19 CCR 2654 (a) or (d)
Record ID:	DEH2002-HUPFP-111432
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-111432
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	4385152
Return To Compliance Date:	2015-04-09T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2020-05-06T15:42:49.000
Inspection Date:	2015-01-21T00:00:00.000
Violation Code:	1020001 Failure to include an adequate training program in the business plan, which is reasonable and appropriate for the size of the business and the nature of the hazardous material handled; HSC 6.95 25505(a)4
Record ID:	DEH2002-HUPFP-111432
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-111432
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6080736
Return To Compliance Date:	2019-05-13T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Last Update: 2020-05-06T15:42:49.000
Inspection Date: 2019-05-13T16:10:53.000
Violation Code: 3010002 Failed to obtain &/or maintain an active EPA ID Number. 22 CCR 66262.12(a)

UST DTL:

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-111432
Facility Type (Ust Facility): Not reported
Tank Owner Name: PRUDENTIAL OVERALL SUPPLY
Tankid: 20969
Tank Status: Removed
Date Ust Permanently Closed: 11/08/1986
Tank Use: Not reported
Piping System Type: Not reported
Last Updated: 2020-05-06T15:42:53.000
Tank Capacityin Gallons: 10000
Tank Contents: Not reported
Type Of Tank: 01

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-111432
Facility Type (Ust Facility): Not reported
Tank Owner Name: PRUDENTIAL OVERALL SUPPLY
Tankid: 20970
Tank Status: Removed
Date Ust Permanently Closed: 11/08/1986
Tank Use: 01
Piping System Type: Not reported
Last Updated: 2020-05-06T15:42:53.000
Tank Capacityin Gallons: 7500
Tank Contents: 02
Type Of Tank: 01

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-111432
Facility Type (Ust Facility): Not reported
Tank Owner Name: PRUDENTIAL OVERALL SUPPLY
Tankid: 20966
Tank Status: Removed
Date Ust Permanently Closed: 11/08/1986
Tank Use: Not reported
Piping System Type: Not reported
Last Updated: 2020-05-06T15:42:53.000
Tank Capacityin Gallons: 2000
Tank Contents: Not reported
Type Of Tank: 01

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Facility Id Number: 37-000-111432
Facility Type (Ust Facility): Not reported
Tank Owner Name: PRUDENTIAL OVERALL SUPPLY
Tankid: 20967
Tank Status: Removed
Date Ust Permanently Closed: 11/08/1986
Tank Use: Not reported
Piping System Type: Not reported
Last Updated: 2020-05-06T15:42:53.000
Tank Capacityin Gallons: 10000
Tank Contents: Not reported
Type Of Tank: 01

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-111432
Facility Type (Ust Facility): Not reported
Tank Owner Name: PRUDENTIAL OVERALL SUPPLY
Tankid: 20968
Tank Status: Removed
Date Ust Permanently Closed: 11/08/1986
Tank Use: Not reported
Piping System Type: Not reported
Last Updated: 2020-05-06T15:42:53.000
Tank Capacityin Gallons: 2000
Tank Contents: Not reported
Type Of Tank: 01

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-111432
Facility Type (Ust Facility): Not reported
Tank Owner Name: PRUDENTIAL OVERALL SUPPLY
Tankid: 20963
Tank Status: Removed
Date Ust Permanently Closed: 11/08/1986
Tank Use: Not reported
Piping System Type: Not reported
Last Updated: 2020-05-06T15:42:53.000
Tank Capacityin Gallons: 2000
Tank Contents: Not reported
Type Of Tank: 01

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-111432
Facility Type (Ust Facility): Not reported
Tank Owner Name: PRUDENTIAL OVERALL SUPPLY
Tankid: 20964
Tank Status: Removed
Date Ust Permanently Closed: 11/08/1986
Tank Use: Not reported
Piping System Type: Not reported
Last Updated: 2020-05-06T15:42:53.000

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Tank Capacityin Gallons: 2000
Tank Contents: Not reported
Type Of Tank: 01

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-111432
Facility Type (Ust Facility): Not reported
Tank Owner Name: PRUDENTIAL OVERALL SUPPLY
Tankid: 20965
Tank Status: Removed
Date Ust Permanently Closed: 11/08/1986
Tank Use: Not reported
Piping System Type: Not reported
Last Updated: 2020-05-06T15:42:53.000
Tank Capacityin Gallons: 2000
Tank Contents: Not reported
Type Of Tank: 01

Waste and Materials:
Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0224017
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-03-26T12:52:32.000
Chemical Name: Water based paint
Common Name: Water based paint
Case Number: Not reported

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0224016
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-03-26T12:52:32.000
Chemical Name: Propane
Common Name: Propane
Case Number: 74-98-6

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0089415
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-04-11T02:31:25.000
Chemical Name: OXYGEN
Common Name: OXYGEN
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Child Record Id: DEH2016-HCHEM-0089416
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-04-11T02:31:25.000
Chemical Name: ACETYLENE
Common Name: ACETYLENE
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0089417
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-04-11T02:31:25.000
Chemical Name: Propane
Common Name: Propane
Case Number: 74-98-6

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0208067
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-03-26T02:34:45.000
Chemical Name: OXYGEN
Common Name: OXYGEN
Case Number: 7782-44-7

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0208068
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-03-26T02:34:45.000
Chemical Name: ACETYLENE
Common Name: ACETYLENE
Case Number: 74-86-2

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0208069
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-03-26T02:34:45.000
Chemical Name: Propane
Common Name: Propane
Case Number: 74-98-6

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0262302
Trade Secret: N

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Hazardous Material Type: Pure
Last Updated: 2020-05-06T15:42:53.000
Chemical Name: Propane
Common Name: Propane
Case Number: 74-98-6

Record ID: DEH2002-HUPFP-111432
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0262303
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-05-06T15:42:53.000
Chemical Name: Water based paint
Common Name: Water based paint
Case Number: Not reported

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 111432
Business Type: 6HK54
EPA Id Number: CAD981983265
APN: 567-090-03-00
Last HMMD Inspection: 10/13/2010
Facility Telephone: 427-1240
Permit Status: OPEN
Permit Expiration: 04/30/2013
Date Last Updated: 11/02/2012
Facility Owner: PRUDENTIAL OVERALL SUPPLY
Facility Mailing Address: 740 F ST
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910-2006
UST Owner: PRUDENTIAL OVERALL SUPPLY
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Y
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 111432
Update Date: 11/02/2012
Case Number: Not reported
Name: ACCENTUATE 11 (DOBER)
Other Information: STARCH
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 111432
Update Date: 11/02/2012
Case Number: 74-86-2
Name: ACETYLENE
Other Information: Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 111432
Update Date: 11/02/2012
Case Number: Not reported
Name: BOBER BASE OIL
Other Information: DIPROPYLENE GLYCOL METHYL ETHER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 111432
Update Date: 11/02/2012
Case Number: 10124-56-8
Name: BOILER CARE 2036 (ECOLAB)
Other Information: SODIUM HEXAMETH PHOSPHATE
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 111432
Update Date: 11/02/2012
Case Number: Not reported
Name: CATIONIC POLYMER
Other Information: DWT 5256
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 111432
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: E-MAX ALKALI (DOBER)
Other Information: SODIUM HYDROXIDE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 111432
Update Date: 11/02/2012
Case Number: Not reported
Name: E-MAX-DETERGENT (DOBER)
Other Information: ALCOHOL ETHOXYLATE
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: Not reported

Permit Number: 111432
Update Date: 11/02/2012
Case Number: Not reported
Name: FABRISTAT
Other Information: DIALKYL DIMETHYL AMMONIUM CHLORIDE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Permit Number:	111432
Update Date:	11/02/2012
Case Number:	7705-08-0
Name:	FERRIC CHLORIDE
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	CHRONIC

Permit Number:	111432
Update Date:	11/02/2012
Case Number:	16961-83-4
Name:	HYDROFLUOSILICIC ACID: SUPER REDUCE (2 TANKS)
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	CHRONIC

Permit Number:	111432
Update Date:	11/02/2012
Case Number:	7782-44-7
Name:	OXYGEN
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	PRESSURE RELEASE
Hazardous Categories 2:	Not reported

Permit Number:	111432
Update Date:	11/02/2012
Case Number:	74-98-6
Name:	PROPANE
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	PRESSURE RELEASE
Hazardous Categories 2:	Not reported

Permit Number:	111432
Update Date:	11/02/2012
Case Number:	7681-52-9
Name:	SODIUM HYPOCHLORITE: BLEACH
Other Information:	12.5%
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported

Permit Number:	111432
Update Date:	11/02/2012
Case Number:	7772-98-7
Name:	SODIUM THIOSULFATE SOLUTION (10-15%); BANNISH ANTI-CHLOR
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported

Permit Number:	111432
Update Date:	11/02/2012
Case Number:	7320-34-5

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Name:	TETRAPOTASSIUM PYROPHOSPHATE: PRISM
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported
Permit Number:	111432
Update Date:	11/02/2012
Case Number:	Not reported
Name:	URSA SUPER PLUS MOTOR OILS
Other Information:	SOLVENT-DEWAXED HEAVY PARAFFINIC DISTILLATE
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported
Permit Number:	111432
Update Date:	11/02/2012
Case Number:	Not reported
Name:	VORTEX EMULSION (DOBER)
Other Information:	DETERGENT
Material Waste:	Material
Hazardous Categories 1:	REACTIVE
Hazardous Categories 2:	ACUTE
Permit Number:	111432
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 132 AQUEOUS SOL'N WITH METALS
Other Information:	PARTS WASHER AQUEOUS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	111432
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 221 WASTE OIL & MIXED OIL
Other Information:	ALSO AES,EVERGREEN
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	111432
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 444 USED BATTERIES
Other Information:	ALLSTATE BATTERY, KRAGEN
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	111432
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 888 USED OIL FILTERS
Other Information:	CONBINED AT VISTA PLANT
Material Waste:	Waste

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 111432
Update Date: 11/02/2012
Inspection Date: 10/13/2010
Violation Code: 6HV1014
Violation: HMBP INCOMPLETE/NOT AMENDED
Violation Citation: HMBP is incomplete/inadequate/not amended to reflect changes. 25504, 25505(a)(2) &/or 25509(a); 25505(b); 19 CCR 2729
Activity: ACTIVE

Permit Number: 111432
Update Date: 11/02/2012
Inspection Date: 06/27/2006
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

Permit Number: 111432
Update Date: 11/02/2012
Inspection Date: 06/27/2006
Violation Code: 6HV0209
Violation: WASTE ONSITE >90/180/270 DAYS
Violation Citation: Hazardous waste is stored in excess of allowable time period (90 days) without a State permit or written variance. CCR 25201(a) & 66262.34(a)&(c)
Activity: ACTIVE

Permit Number: 111432
Update Date: 11/02/2012
Inspection Date: 05/12/2010
Violation Code: 6HV1014
Violation: HMBP INCOMPLETE/NOT AMENDED
Violation Citation: HMBP is incomplete/inadequate/not amended to reflect changes. 25504, 25505(a)(2) &/or 25509(a); 25505(b); 19 CCR 2729
Activity: ACTIVE

Permit Number: 111432
Update Date: 11/02/2012
Inspection Date: 05/12/2010
Violation Code: 6HV1017
Violation: HMBP NOT CERTIFIED ANNUALLY
Violation Citation: Business Plan not certified annually. 25505(d) & (e)(2)
Activity: ACTIVE

Permit Number: 111432
Update Date: 11/02/2012
Inspection Date: 05/12/2010
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a)

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

	& 25160.2(b)(3)
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	05/12/2010
Violation Code:	6HV0146
Violation:	NO ERM EXEMPTION CLAIM DOCUMENTS
Violation Citation:	Failed to have adequate records demonstrating claim of exemption for Excluded Recyclable Material (ERM). 25143.2(f) & 66261.2(g)
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	05/12/2010
Violation Code:	6HV0234
Violation:	FACILITY NOT OPERATED TO MINIM. RELEASE
Violation Citation:	Did not maintain &/or operate facility to prevent release or fire. CFR 265.31
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	05/12/2010
Violation Code:	6HV0407
Violation:	EMPLOYEE TRAINING NOT ADEQUATE
Violation Citation:	Employee training program for small quantity generator of hazardous waste is inadequate. CFR 262.34(d)(5)(iii)
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	06/11/2008
Violation Code:	6HV1014
Violation:	HMBP INCOMPLETE/NOT AMENDED
Violation Citation:	HMBP is incomplete/inadequate/not amended to reflect changes. 25504, 25505(a)(2) &/or 25509(a); 25505(b); 19 CCR 2729
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	06/11/2008
Violation Code:	6HV1017
Violation:	HMBP NOT CERTIFIED ANNUALLY
Violation Citation:	Business Plan not certified annually. 25505(d) & (e)(2)
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	06/11/2008
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	ACTIVE

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	06/11/2008
Violation Code:	6HV0304
Violation:	WASTE DETERMINATION NOT MADE
Violation Citation:	Generator of a waste has not determined if that waste is a hazardous waste as defined by law. CCR 66262.11 & 66260.200(c)
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	06/11/2008
Violation Code:	6HV0224
Violation:	MISMANAGED EMPTY CONTAINERS >5GALS.
Violation Citation:	Failed to mark date on empty container larger than 5 gallons and/or manage it within one year. 66261.7(e) & (f).
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	06/11/2008
Violation Code:	6HV1714
Violation:	IMPROPER/INADEQUATE UNIT CLOSURE
Violation Citation:	Improper/inadequate closure of treatment unit (closure includes removal or decontamination of equipment, waste residues, containment systems, soils and/or structures). {CE: 25201.5(d)(8)(A); CEL: 25201.14(c)(1); CA: 25200.3(g)(1); PBR: 67450.3(c)(11)}
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	04/25/2003
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	04/25/2003
Violation Code:	6HV0304
Violation:	WASTE DETERMINATION NOT MADE
Violation Citation:	Generator of a waste has not determined if that waste is a hazardous waste as defined by law. CCR 66262.11 & 66260.200(c)
Activity:	ACTIVE
Permit Number:	111432
Update Date:	11/02/2012
Inspection Date:	01/07/2005
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

UST:

UST Name:	UNDERGROUND TANK 111432 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	111432
Tank Type:	SINGLE WALL
Additional Id:	1
Capacity Gallons:	2000
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1966-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 111432 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	111432
Tank Type:	SINGLE WALL
Additional Id:	2
Capacity Gallons:	2000
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1966-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 111432 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	111432
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	2000
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1966-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 111432 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	111432
Tank Type:	SINGLE WALL
Additional Id:	4

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Capacity Gallons:	2000
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1966-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.
UST Name:	UNDERGROUND TANK 111432 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	111432
Tank Type:	SINGLE WALL
Additional Id:	5
Capacity Gallons:	10000
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1966-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.
UST Name:	UNDERGROUND TANK 111432 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	111432
Tank Type:	SINGLE WALL
Additional Id:	6
Capacity Gallons:	2000
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.
UST Name:	UNDERGROUND TANK 111432 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	111432
Tank Type:	SINGLE WALL
Additional Id:	7
Capacity Gallons:	10000
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 111432 T008
Last Update: 2012-11-02 14:17:38
Permit Number: 111432
Tank Type: SINGLE WALL
Additional Id: 8
Capacity Gallons: 7500
UST Contents: LEADED
Other Content Info: LEADED
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

CERS HAZ WASTE:
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 145266
CERS ID: 10357903
CERS Description: Hazardous Waste Generator

SWEEPS UST:
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City: CHULA VISTA
Status: Active
Comp Number: 11432
Number: 9
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: Not reported
Tank Status: Not reported
Capacity: Not reported
Active Date: Not reported
Tank Use: Not reported
STG: Not reported
Content: Not reported
Number Of Tanks: Not reported

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City: CHULA VISTA

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Status:	Not reported
Comp Number:	11432
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-011432-000001
Tank Status:	Not reported
Capacity:	2000
Active Date:	Not reported
Tank Use:	CHEMICAL
STG:	PRODUCT
Content:	Not reported
Number Of Tanks:	8

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	11432
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-011432-000002
Tank Status:	Not reported
Capacity:	2000
Active Date:	Not reported
Tank Use:	CHEMICAL
STG:	PRODUCT
Content:	Not reported
Number Of Tanks:	Not reported

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	11432
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-011432-000003
Tank Status:	Not reported
Capacity:	2000
Active Date:	Not reported
Tank Use:	CHEMICAL
STG:	WASTE
Content:	Not reported
Number Of Tanks:	Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	11432
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-011432-000004
Tank Status:	Not reported
Capacity:	2000
Active Date:	Not reported
Tank Use:	CHEMICAL
STG:	PRODUCT
Content:	Not reported
Number Of Tanks:	Not reported

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	11432
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-011432-000005
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	CHEMICAL
STG:	PRODUCT
Content:	Not reported
Number Of Tanks:	Not reported

Name:	PRUDENTIAL OVERALL SUPPLY
Address:	740 F ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	11432
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-011432-000006
Tank Status:	Not reported
Capacity:	2000
Active Date:	Not reported
Tank Use:	UNKNOWN
STG:	PRODUCT

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Content: Not reported
Number Of Tanks: Not reported

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City: CHULA VISTA
Status: Not reported
Comp Number: 11432
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-011432-000007
Tank Status: Not reported
Capacity: 10000
Active Date: Not reported
Tank Use: CHEMICAL
STG: PRODUCT
Content: Not reported
Number Of Tanks: Not reported

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City: CHULA VISTA
Status: Not reported
Comp Number: 11432
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-011432-000008
Tank Status: Not reported
Capacity: 7500
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

HIST UST:
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 "F" STREET
City,State,Zip: CHULA VISTA, CA 92010
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000003306
Facility Type: Other
Other Type: INDUSTRIAL LAUNDRY
Contact Name: AL BECKER
Telephone: 6194271240
Owner Name: PRUDENTIAL OVERALL SUPPLY
Owner Address: 1661 ALTON AVENUE

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Owner City,St,Zip:	IRVINE, CA 92714
Total Tanks:	0008
Tank Num:	001
Container Num:	1
Year Installed:	1966
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	1/4
Leak Detection:	None
Tank Num:	002
Container Num:	2
Year Installed:	1966
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	1/4
Leak Detection:	None
Tank Num:	003
Container Num:	3
Year Installed:	1966
Tank Capacity:	00002000
Tank Used for:	WASTE
Type of Fuel:	Not reported
Container Construction Thickness:	1/4
Leak Detection:	None
Tank Num:	004
Container Num:	4
Year Installed:	1966
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	1/4
Leak Detection:	None
Tank Num:	005
Container Num:	5
Year Installed:	1966
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	1/4
Leak Detection:	None
Tank Num:	006
Container Num:	6
Year Installed:	Not reported
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	None

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Tank Num: 007
Container Num: 7
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: None

Tank Num: 008
Container Num: 8
Year Installed: Not reported
Tank Capacity: 00007500
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: Not reported
Leak Detection: None

FINDS:
Registry ID: 110006466902

Click Here:

Environmental Interest/Information System:
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
STATE MASTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000187281
Registry ID: 110006466902
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110006466902
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F STREET
City,State,Zip: CHULA VISTA, CA 91910

HIST CORTESE:
edr_fname: PRUDENTIAL OVERALL SUPPLY
edr_fadd1: 740 F
City,State,Zip: CHULA VISTA, CA 92010
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT2320

edr_fname: PRUDENTIAL OVERALL SUPPLY

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

edr_fadd1: 740 F
City,State,Zip: CHULA VISTA, CA 92010
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT403

SAN DIEGO CO LOP:
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 91910
Record ID: DEH1986-LSAM-H11432-001
Record Status: Completed
Opened Date: 09/05/1986
Parcel Number: 567-090-03-00
Case Type: Not reported
Historical Name: PRUDENTIAL OVERALL SUPPLY
SWRCB Global ID: Not reported
Funding: N - Non-Billable
Lead Agency: RWQCB
Lead Agency Date: 09/05/1986
Census Tract: 125.01
Community: Chula Vista
Jurisdiction: CHULA VISTA
Watershed Basin Number: 909.12
Water Purveyor: CHULA VISTA
Fire Agency: CHULA VISTA
Latitude: 32.6358594
Longitude: -117.0970365
X MapCoord: 6300902.980
Y MapCoord: 1812221.671

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 91910
Record ID: DEH1986-LSAM-H11432-002
Record Status: Completed
Opened Date: 09/03/1986
Parcel Number: 567-090-03-00
Case Type: LOP - Local Oversight Program
Historical Name: PRUDENTIAL OVERALL SUPPLY
SWRCB Global ID: T0607301090
Funding: S - LOP State Fund
Lead Agency: RWQCB
Lead Agency Date: 07/01/2013
Census Tract: 125.01
Community: Chula Vista
Jurisdiction: CHULA VISTA
Watershed Basin Number: 909.12
Water Purveyor: CHULA VISTA
Fire Agency: CHULA VISTA
Latitude: 32.6358594
Longitude: -117.0970365
X MapCoord: 6300902.980
Y MapCoord: 1812221.671

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

CERS:
Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 145266
CERS ID: T0607301090
CERS Description: Leaking Underground Storage Tank Cleanup Site

Violations:
Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-21-2015
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Notes: Returned to compliance on 04/09/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-03-2017
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 02/20/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-21-2015
Citation: HSC 6.95 25508.1(a)-(e) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(e)
Violation Description: Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name.
Violation Notes: Returned to compliance on 04/09/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-21-2015
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description: Failure to complete and electronically submit a site map with all

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

required content.
Violation Notes: Returned to compliance on 04/09/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-21-2015
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.
Violation Notes: Returned to compliance on 04/09/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 05-13-2019
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes: Returned to compliance on 05/13/2019. Inspection Sequence ID:6080736
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 05-13-2019
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description: Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes: Returned to compliance on 05/13/2019. Inspection Sequence ID:6080736
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chairs Michelle Inspection ID:4385152
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2015

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Chairs Michelle Inspection ID:4385152
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-13-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Farhang Farnaz Inspection ID:6080736
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-13-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Farhang Farnaz Inspection ID:6080736
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-03-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Villena Elaine Inspection ID:5591577
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Coordinates:

Site ID:	145266
Facility Name:	PRUDENTIAL OVERALL SUPPLY
Env Int Type Code:	HMBP
Program ID:	10357903
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	32.635860
Longitude:	-117.097040
Site ID:	145266
Facility Name:	PRUDENTIAL OVERALL SUPPLY
Env Int Type Code:	LUSTCS
Program ID:	T0607301090
Coord Name:	Not reported
Ref Point Type Desc:	Unknown
Latitude:	32.635616
Longitude:	-117.096812

Affiliation:

Affiliation Type Desc:	Environmental Contact
Entity Name:	Joel Bickel

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Entity Title:	Not reported
Affiliation Address:	P.O. Box 11210
Affiliation City:	Santa Ana
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92711
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	PRUDENTIAL OVERALL SUPPLY
Entity Title:	Not reported
Affiliation Address:	P.O. Box 11210
Affiliation City:	SANTA ANA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92711
Affiliation Phone:	(619) 427-1240
Affiliation Type Desc:	Operator
Entity Name:	PRUDENTIAL OVERALL SUPPLY
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 427-1240
Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	DAVID T. BARKER - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213007
Affiliation Type Desc:	Document Preparer
Entity Name:	MLM & Associates Engineering
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	740 F STREET
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Affiliation Type Desc: Regional Board Caseworker
Entity Name: SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213374

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880

Affiliation Type Desc: Identification Signer
Entity Name: Joel Bickel
Entity Title: Associate Staff Engineer
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: PRUDENTIAL OVERALL SUPPLY
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: PRUDENTIAL OVERALL SUPPLY
Entity Title: Not reported
Affiliation Address: P.O. Box 11210
Affiliation City: SANTA ANA
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 92711
Affiliation Phone: (949) 250-4855

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 145266
CERS ID: T0607302719
CERS Description: Leaking Underground Storage Tank Cleanup Site

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Violations:

Site ID:	145266
Site Name:	PRUDENTIAL OVERALL SUPPLY
Violation Date:	01-21-2015
Citation:	HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description:	Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Notes:	Returned to compliance on 04/09/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	145266
Site Name:	PRUDENTIAL OVERALL SUPPLY
Violation Date:	01-03-2017
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Returned to compliance on 02/20/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	145266
Site Name:	PRUDENTIAL OVERALL SUPPLY
Violation Date:	01-21-2015
Citation:	HSC 6.95 25508.1(a)-(e) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(e)
Violation Description:	Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name.
Violation Notes:	Returned to compliance on 04/09/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	145266
Site Name:	PRUDENTIAL OVERALL SUPPLY
Violation Date:	01-21-2015
Citation:	HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Returned to compliance on 04/09/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	145266
Site Name:	PRUDENTIAL OVERALL SUPPLY

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Violation Date: 01-21-2015
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.
Violation Notes: Returned to compliance on 04/09/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 05-13-2019
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes: Returned to compliance on 05/13/2019. Inspection Sequence ID:6080736
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 05-13-2019
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description: Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes: Returned to compliance on 05/13/2019. Inspection Sequence ID:6080736
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chairs Michelle Inspection ID:4385152
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chairs Michelle Inspection ID:4385152
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Eval Date: 05-13-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6080736
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-13-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6080736
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-03-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5591577
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Coordinates:
Site ID: 145266
Facility Name: PRUDENTIAL OVERALL SUPPLY
Env Int Type Code: HMBP
Program ID: 10357903
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.635860
Longitude: -117.097040

Site ID: 145266
Facility Name: PRUDENTIAL OVERALL SUPPLY
Env Int Type Code: LUSTCS
Program ID: T0607301090
Coord Name: Not reported
Ref Point Type Desc: Unknown
Latitude: 32.635616
Longitude: -117.096812

Affiliation:
Affiliation Type Desc: Environmental Contact
Entity Name: Joel Bickel
Entity Title: Not reported
Affiliation Address: P.O. Box 11210
Affiliation City: Santa Ana
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92711
Affiliation Phone: Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Affiliation Type Desc:	Legal Owner
Entity Name:	PRUDENTIAL OVERALL SUPPLY
Entity Title:	Not reported
Affiliation Address:	P.O. Box 11210
Affiliation City:	SANTA ANA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92711
Affiliation Phone:	(619) 427-1240

Affiliation Type Desc:	Operator
Entity Name:	PRUDENTIAL OVERALL SUPPLY
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 427-1240

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	DAVID T. BARKER - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213007

Affiliation Type Desc:	Document Preparer
Entity Name:	MLM & Associates Engineering
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	740 F STREET
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Affiliation Zip: Not reported
Affiliation Phone: 6195213374

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880

Affiliation Type Desc: Identification Signer
Entity Name: Joel Bickel
Entity Title: Associate Staff Engineer
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: PRUDENTIAL OVERALL SUPPLY
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: PRUDENTIAL OVERALL SUPPLY
Entity Title: Not reported
Affiliation Address: P.O. Box 11210
Affiliation City: SANTA ANA
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 92711
Affiliation Phone: (949) 250-4855

Name: PRUDENTIAL OVERALL SUPPLY
Address: 740 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 145266
CERS ID: 10357903
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-21-2015
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

business plan is complete, accurate, and up-to-date.
Violation Notes: Returned to compliance on 04/09/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-03-2017
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 02/20/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-21-2015
Citation: HSC 6.95 25508.1(a)-(e) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(e)
Violation Description: Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name.
Violation Notes: Returned to compliance on 04/09/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-21-2015
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description: Failure to complete and electronically submit a site map with all required content.
Violation Notes: Returned to compliance on 04/09/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 01-21-2015
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.
Violation Notes: Returned to compliance on 04/09/2015.

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 05-13-2019
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes: Returned to compliance on 05/13/2019. Inspection Sequence ID:6080736
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 145266
Site Name: PRUDENTIAL OVERALL SUPPLY
Violation Date: 05-13-2019
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description: Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.
Violation Notes: Returned to compliance on 05/13/2019. Inspection Sequence ID:6080736
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chairs Michelle Inspection ID:4385152
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-21-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chairs Michelle Inspection ID:4385152
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-13-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6080736
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-13-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Farhang Farnaz Inspection ID:6080736
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-03-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Villena Elaine Inspection ID:5591577
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Coordinates:

Site ID:	145266
Facility Name:	PRUDENTIAL OVERALL SUPPLY
Env Int Type Code:	HMBP
Program ID:	10357903
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	32.635860
Longitude:	-117.097040

Site ID:	145266
Facility Name:	PRUDENTIAL OVERALL SUPPLY
Env Int Type Code:	LUSTCS
Program ID:	T0607301090
Coord Name:	Not reported
Ref Point Type Desc:	Unknown
Latitude:	32.635616
Longitude:	-117.096812

Affiliation:

Affiliation Type Desc:	Environmental Contact
Entity Name:	Joel Bickel
Entity Title:	Not reported
Affiliation Address:	P.O. Box 11210
Affiliation City:	Santa Ana
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92711
Affiliation Phone:	Not reported

Affiliation Type Desc:	Legal Owner
Entity Name:	PRUDENTIAL OVERALL SUPPLY
Entity Title:	Not reported
Affiliation Address:	P.O. Box 11210
Affiliation City:	SANTA ANA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92711

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Affiliation Phone:	(619) 427-1240
Affiliation Type Desc:	Operator
Entity Name:	PRUDENTIAL OVERALL SUPPLY
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 427-1240
Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	DAVID T. BARKER - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213007
Affiliation Type Desc:	Document Preparer
Entity Name:	MLM & Associates Engineering
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	740 F STREET
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported
Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213374
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego

PRUDENTIAL OVERALL SUPPLY (Continued) **1000187281**

Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880
Affiliation Type Desc:	Identification Signer
Entity Name:	Joel Bickel
Entity Title:	Associate Staff Engineer
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Parent Corporation
Entity Name:	PRUDENTIAL OVERALL SUPPLY
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner
Entity Name:	PRUDENTIAL OVERALL SUPPLY
Entity Title:	Not reported
Affiliation Address:	P.O. Box 11210
Affiliation City:	SANTA ANA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92711
Affiliation Phone:	(949) 250-4855

P84 **THRIFTY OIL COMPANY #080** **LUST** **S103065396**
East **666 H ST** **SAN DIEGO CO. SAM** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910** **San Diego Co. HMMD**
0.326 mi. **SWEEPS UST**
1723 ft. **Site 1 of 2 in cluster P** **Cortese**
HIST CORTESE
Relative: Higher **SAN DIEGO CO LOP**
CERS

Actual: 37 ft.

LUST:

Name:	THRIFTY OIL COMPANY #080
Address:	666 H ST
City,State,Zip:	CHULA VISTA, CA 919104220
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302991
Global Id:	T0607302991
Latitude:	32.6300010274634
Longitude:	-117.092156410217
Status:	Completed - Case Closed
Status Date:	01/27/2017
Case Worker:	SM

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

RB Case Number: 9UT728
Local Agency: Not reported
File Location: Local Agency
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: Commingled Plume Account: Please search on H03739-001 for additional 2010 and later reports. Uploaded under World Oil #80. Following the removal of USTs and demolition of site improvements in 1987, hydrocarbon impacts were observed with a series of investigation trenches and borings. Liquid-phase hydrocarbons (LPH) were observed at the site during these and subsequent investigations prompting LPH removal activities via tanker truck extraction and LPH bailing operations. Soil vapor extraction and limited dual-phase extraction have been implemented at the site with some success. World Oil Station #46 (H03739), located across the intersection, reported a significant unauthorized release in 1997. Based on available data, LPH appears inseparably commingled from the Thrifty and World Oil sites and extends offsite. Cleanup activities for these sites must be coordinated.

LUST:
Global Id: T0607302991
Contact Type: Regional Board Caseworker
Contact Name: SEAN MCCLAIN
Organization Name: SAN DIEGO RWQCB (REGION 9)
Address: 2375 NORTHSIDE DRIVE, SUITE 100
City: SAN DIEGO
Email: sean.mcclain@waterboards.ca.gov
Phone Number: 6195213374

LUST:
Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 07/01/2013
Action: Referral to Regional Board

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 06/19/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 05/03/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 04/18/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 05/04/2012
Action: File review

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 10/18/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: Other
Date: 03/17/1987
Action: Leak Reported

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 04/09/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 07/09/2009
Action: Letter - Notice

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 08/11/2009
Action: File review

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 05/02/2014
Action: Notification - Public Notice of Case Closure

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 10/01/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 01/06/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: RESPONSE
Date: 07/30/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 05/02/2014
Action: Notification - Fee Title Owners Notice

Global Id: T0607302991
Action Type: RESPONSE
Date: 07/30/2008
Action: Monitoring Report - Semi-Annually

Global Id: T0607302991
Action Type: RESPONSE

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

Date: 01/30/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 09/28/2009
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 04/11/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607302991
Action Type: RESPONSE
Date: 09/30/2009
Action: Soil and Water Investigation Workplan

Global Id: T0607302991
Action Type: RESPONSE
Date: 11/25/2014
Action: Other Report / Document

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 06/24/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: Other
Date: 03/17/1987
Action: Leak Began

Global Id: T0607302991
Action Type: RESPONSE
Date: 01/22/2016
Action: Correspondence

Global Id: T0607302991
Action Type: Other
Date: 03/17/1987
Action: Leak Discovery

Global Id: T0607302991
Action Type: RESPONSE
Date: 10/05/2016
Action: Well Destruction Report

Global Id: T0607302991
Action Type: RESPONSE
Date: 02/14/2014
Action: Request for Closure - Regulator Responded

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 03/19/1987
Action: Notice of Responsibility

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 05/03/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 11/05/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302991
Action Type: ENFORCEMENT
Date: 01/27/2017
Action: Closure/No Further Action Letter

Global Id: T0607302991
Action Type: RESPONSE
Date: 01/31/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607302991
Action Type: Other
Date: 03/17/1987
Action: Leak Stopped

LUST:
Global Id: T0607302991
Status: Open - Case Begin Date
Status Date: 03/17/1987

Global Id: T0607302991
Status: Open - Remediation
Status Date: 04/30/1989

Global Id: T0607302991
Status: Open - Eligible for Closure
Status Date: 03/03/2014

Global Id: T0607302991
Status: Completed - Case Closed
Status Date: 01/27/2017

SAN DIEGO CO. SAM:
Name: THRIFTY OIL STN #080
Address: 666 H ST
City,State,Zip: CHULA VISTA, CA 919104220
Case Number: H20174-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 2/2/2010
Date Began: 3/17/1987

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

HMMD SAN DIEGO:

Name:	THRIFTY OIL STN #080
Address:	666 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	120174
Business Type:	Not reported
EPA Id Number:	Not reported
APN:	571-062-21-00
Last HMMD Inspection:	Not reported
Facility Telephone:	213-923-9876
Permit Status:	INAC
Permit Expiration:	Not reported
Date Last Updated:	11/02/2012
Facility Owner:	THRIFTY OIL CO
Facility Mailing Address:	P O BOX 2128
Facility Mailing City:	SANTA FE SPRING
Facility Mailing State:	CA
Facility Mailing Zip:	90670-
UST Owner:	THRIFTY OIL CO
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 120174 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	120174
Tank Type:	SINGLE WALL
Additional Id:	080-1
Capacity Gallons:	12000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 120174 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	120174
Tank Type:	SINGLE WALL
Additional Id:	080-2
Capacity Gallons:	6000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.
UST Name:	UNDERGROUND TANK 120174 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	120174
Tank Type:	SINGLE WALL
Additional Id:	080-3
Capacity Gallons:	8000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.
UST Name:	UNDERGROUND TANK 120174 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	120174
Tank Type:	SINGLE WALL
Additional Id:	080-7
Capacity Gallons:	6000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.
UST Name:	UNDERGROUND TANK 120174 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	120174
Tank Type:	SINGLE WALL
Additional Id:	080-10
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

SWEEPS UST:

Name:	THRIFTY OIL STN #080
Address:	666 H ST
City:	CHULA VISTA
Status:	Active
Comp Number:	20174
Number:	9
Board Of Equalization:	44-007386
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported
STG:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

Name:	THRIFTY OIL STN #080
Address:	666 H ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	20174
Number:	Not reported
Board Of Equalization:	44-007386
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-020174-000001
Tank Status:	Not reported
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	5

Name:	THRIFTY OIL STN #080
Address:	666 H ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	20174
Number:	Not reported
Board Of Equalization:	44-007386
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-020174-000002
Tank Status:	Not reported
Capacity:	6000
Active Date:	Not reported
Tank Use:	M.V. FUEL

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: THRIFTY OIL STN #080
Address: 666 H ST
City: CHULA VISTA
Status: Not reported
Comp Number: 20174
Number: Not reported
Board Of Equalization: 44-007386
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020174-000003
Tank Status: Not reported
Capacity: 8000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Name: THRIFTY OIL STN #080
Address: 666 H ST
City: CHULA VISTA
Status: Not reported
Comp Number: 20174
Number: Not reported
Board Of Equalization: 44-007386
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020174-000004
Tank Status: Not reported
Capacity: 6000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: THRIFTY OIL STN #080
Address: 666 H ST
City: CHULA VISTA
Status: Not reported
Comp Number: 20174
Number: Not reported
Board Of Equalization: 44-007386
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020174-000005
Tank Status: Not reported

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

Capacity:	550
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	WASTE
Content:	Not reported
Number Of Tanks:	Not reported

CORTESE:

Name:	THRIFTY OIL COMPANY #080
Address:	666 H ST
City,State,Zip:	CHULA VISTA, CA 919104220
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607302991
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	THRIFTY SERVICE STATION #
edr_fadd1:	666 H
City,State,Zip:	CHULA VISTA, CA 92020
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT728

SAN DIEGO CO LOP:

Name:	THRIFTY OIL STN #080
Address:	666 H ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1987-LSAM-H20174-001
Record Status:	Completed
Opened Date:	03/17/1987
Parcel Number:	571-062-21-00
Case Type:	LOP - Local Oversight Program
Historical Name:	THRIFTY #080 (EL POLLO LOCO)
SWRCB Global ID:	T0607302991
Funding:	S - LOP State Fund
Lead Agency:	RWQCB
Lead Agency Date:	07/01/2013

THRIFTY OIL COMPANY #080 (Continued) **S103065396**

Census Tract:	126.00
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	SOUTH BAY IRRIGATION LAND
Fire Agency:	CHULA VISTA
Latitude:	32.6298758
Longitude:	-117.0922415
X MapCoord:	6302363.81624117
Y MapCoord:	1809920.30864198

CERS:

Name:	THRIFTY OIL COMPANY #080
Address:	666 H ST
City,State,Zip:	CHULA VISTA, CA 919104220
Site ID:	196843
CERS ID:	T0607302991
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213374

P85 **THRIFTY SERIVCE STATION #88** **LUST** **S101301469**
East **666 H ST** **N/A**
1/4-1/2 **CHULA VISTA, CA 92020**
0.326 mi.
1723 ft. **Site 2 of 2 in cluster P**

Relative:
Higher

Actual:
37 ft.

LUST REG 9:

Region:	9
Status:	Remedial action (cleanup) Underway
Case Number:	9UT728
Local Case:	H20174-001
Substance:	Gasoline
Qty Leaked:	0
Abate Method:	FPVS
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Piping
Cause:	Corrosion
Lead Agency:	Local Agency
Case Type:	Aquifer affected
Date Found:	03/17/1987
Date Stopped:	03/17/1987
Confirm Date:	03/17/1987
Submit Workplan:	Not reported
Prelim Assess:	/ /
Desc Pollution:	Not reported

THRIFTY SERIVCE STATION #88 (Continued) **S101301469**

Remed Plan:	08/04/1987
Remed Action:	9/1/89
Began Monitor:	Not reported
Release Date:	03/17/1987
Enforce Date:	3/19/87
Closed Date:	Not reported
Enforce Type:	SEL
Pilot Program:	LOP
Basin Number:	909.12
GW Depth:	Not reported
Beneficial Use:	Municipal groundwater use
NPDES Number:	Not reported
Priority:	2A
File Dispn:	Not reported
Interim Remedial Actions:	Yes
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

Q86 **CHULA VISTA CITY PUBLIC WORKS** **CPS-SLIC** **S118504795**
NNE **707 F STREET** **CERS** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910**
0.347 mi.
1832 ft. **Site 1 of 5 in cluster Q**

Relative:
Higher

Actual:
35 ft.

CPS-SLIC:

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F STREET
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	10/10/1997
Global Id:	T10000008489
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.63677
Longitude:	-117.09719
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	15-02N89.02
File Location:	Regional Board
Potential Media Affected:	Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern:	Other Chlorinated Hydrocarbons, Other Solvent or Non-Petroleum Hydrocarbon, Trichloroethylene (TCE), Chromium, Chromium VI, Lead, Other Metal
Site History:	Former Toxic Pits Cleanup Act (TPCA) case.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F STREET
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	364526
CERS ID:	T10000008489
CERS Description:	Cleanup Program Site

Q87 **CITY OF CHULA VISTA PUBLIC WORKS** **LUST** **S104494717**
NNE **707 F STREET** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910**
0.347 mi.
1832 ft. **Site 2 of 5 in cluster Q**

Relative: **Higher**
Actual: **35 ft.**

LUST REG 9:

Region:	9
Status:	Preliminary site assessment workplan submitted
Case Number:	9UT4025
Local Case:	H04568-003
Substance:	Diesel
Qty Leaked:	Not reported
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Tank
Cause:	Overfill
Lead Agency:	Local Agency
Case Type:	Soil only
Date Found:	12/02/1999
Date Stopped:	12/02/1999
Confirm Date:	/ /
Submit Workplan:	1/18/00
Prelim Assess:	/ /
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	12/02/1999
Enforce Date:	Not reported
Closed Date:	Not reported
Enforce Type:	Not reported
Pilot Program:	LOP
Basin Number:	909.12
GW Depth:	70-80
Beneficial Use:	MUNBU
NPDES Number:	Not reported
Priority:	Low priority. Priority ranking can change over time.
File Dispn:	Administratively opened on database, however no file physically exists
Interim Remedial Actions:	Not reported
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

Q88 **CHULA VISTA,CITY OF, PUB WORKS** **WMUDS/SWAT** **S103442800**
NNE **707 F ST** **N/A**
1/4-1/2 **CHULA VISTA CA, CA 91910**
0.347 mi.
1832 ft. **Site 3 of 5 in cluster Q**

Relative: **Higher**
Actual: **35 ft.**

WMUDS/SWAT:

Edit Date:	Not reported
Complexity:	Not reported
Primary Waste:	CNSOIL
Primary Waste Type:	Hazardous/Influent or Solid Wastes that contain toxic, corrosive, ignitable or reactive substances and must be managed according to applicable DOHS standards.
Secondary Waste:	Contaminated Ground Water

CHULA VISTA,CITY OF, PUB WORKS (Continued) **S103442800**

Secondary Waste Type:	H
Base Meridian:	Not reported
NPID:	Not reported
Tonnage:	0
Regional Board ID:	Not reported
Municipal Solid Waste:	False
Superorder:	False
Open To Public:	False
Waste List:	False
Agency Type:	City
Agency Name:	CHULA VISTA, CITY OF
Agency Department:	Not reported
Agency Address:	276 4TH AVE
Agency City,St,Zip:	CHULA VISTA CA 91910
Agency Contact:	CLIFFORD SWANSON
Agency Telephone:	6196915021
Land Owner Name:	Not reported
Land Owner Address:	Not reported
Land Owner City,St,Zip:	Not reported
Land Owner Contact:	Not reported
Land Owner Phone:	Not reported
Region:	9
Facility Type:	Municipal/Domestic - Facility that treats sewage or a mixture of predominantly sewage and other waste from districts, municipalities, communities, hospitals, schools, and publicly or privately owned systems (excluding individual subsurface leaching systems disposing of less than 1,000 gallons per day).
Facility Description:	Not reported
Facility Telephone:	Not reported
SWAT Facility Name:	Not reported
Primary SIC:	7535
Secondary SIC:	Not reported
Comments:	Not reported
Last Facility Editors:	Not reported
Waste Discharge System:	True
Solid Waste Assessment Test Program:	False
Toxic Pits Cleanup Act Program:	False
Resource Conservation Recovery Act:	True
Department of Defence:	False
Solid Waste Assessment Test Program:	Not reported
Threat to Water Quality:	Not reported
Sub Chapter 15:	True
Regional Board Project Officer:	JPA
Number of WMUDS at Facility:	1
Section Range:	Not reported
RCRA Facility:	No
Waste Discharge Requirements:	H
Self-Monitoring Rept. Frequency:	Quarterly Submittal
Waste Discharge System ID:	9 000002N89
Solid Waste Information ID:	Not reported

Q89
NNE
1/4-1/2
0.347 mi.
1832 ft.

CHULA VISTA, PUBLIC WORKS/OPER
707 F STREET
CHULA VISTA, CA 91910

Site 4 of 5 in cluster Q

Toxic Pits **S100925153**
N/A

Relative:
Higher

Actual:
35 ft.

TOXIC PITS:

Region:	09
Task #:	89009
Owner:	CITY OF CHULA VISTA
1/2 Mi Limit:	Y
Num. of Pits:	2
Cease Discharge Due:	05/08/90
Cease Discharge Complete:	03/20/90
Closure Due:	08/15/91
Closure Completed:	**03/20/90**
Status:	CLOSED
Hydro Geological Assessment Report Due:	/ /
Final Hydro Geological Assessment Review Completed:	11/16/89

Q90
NNE
1/4-1/2
0.347 mi.
1832 ft.

CITY OF CHULA VISTA
707 F STREET
CHULA VISTA, CA 91910

Site 5 of 5 in cluster Q

LUST **S100178527**
SAN DIEGO CO. SAM **N/A**
CPS-SLIC
San Diego Co. HMMD
SWEEPS UST
Cortese
ENF
HIST CORTESE
Notify 65
SAN DIEGO CO LOP
CIWQS
CERS
HWTS

Relative:
Higher

Actual:
35 ft.

LUST REG 9:

Region:	9
Status:	Case Closed
Case Number:	9UT3376
Local Case:	H04568-002
Substance:	Unleaded Gasoline
Qty Leaked:	0
Abate Method:	No Action Required - incident is minor, requiring no remedial action
Local Agency:	San Diego
How Found:	Other Means
How Stopped:	Repair Piping
Source:	Piping
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Aquifer affected
Date Found:	11/08/1994
Date Stopped:	11/08/1994
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	01/03/1994
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	11/08/1994
Enforce Date:	1/17/95

CITY OF CHULA VISTA (Continued) **S100178527**

Closed Date: 3/29/99
Enforce Type: SEL
Pilot Program: LOP
Basin Number: 909.12
GW Depth: 32.5
Beneficial Use: MUNBU
NPDES Number: Not reported
Priority: 2B
File Dispn: Administratively opened on database, however no file physically exists
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

LUST:
Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T06019774117
Global Id: T06019774117
Latitude: 32.6372065531399
Longitude: -117.097113132477
Status: Completed - Case Closed
Status Date: 07/07/2008
Case Worker: NS
RB Case Number: Not reported
Local Agency: SAN DIEGO COUNTY LOP
File Location: Local Agency
Local Case Number: H04568-005
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

LUST:
Global Id: T06019774117
Contact Type: Local Agency Caseworker
Contact Name: NASSER SIONIT
Organization Name: SAN DIEGO COUNTY LOP
Address: P.O. Box 129261
City: San Diego
Email: nasser.sionit@sdcounty.ca.gov
Phone Number: Not reported

LUST:
Global Id: T06019774117
Action Type: ENFORCEMENT
Date: 07/07/2008
Action: Closure/No Further Action Letter

Global Id: T06019774117
Action Type: Other
Date: 11/24/2004
Action: Leak Reported

Global Id: T06019774117
Action Type: Other

CITY OF CHULA VISTA (Continued) **S100178527**

Date: 11/08/2004
Action: Leak Began

Global Id: T06019774117
Action Type: Other
Date: 11/08/2004
Action: Leak Discovery

Global Id: T06019774117
Action Type: ENFORCEMENT
Date: 12/07/2004
Action: Notice of Responsibility

Global Id: T06019774117
Action Type: Other
Date: 11/30/2004
Action: Leak Stopped

LUST:
Global Id: T06019774117
Status: Open - Case Begin Date
Status Date: 11/08/2004

Global Id: T06019774117
Status: Open - Site Assessment
Status Date: 12/07/2004

Global Id: T06019774117
Status: Completed - Case Closed
Status Date: 07/07/2008

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302137
Global Id: T0607302137
Latitude: 32.637411
Longitude: -117.097395
Status: Completed - Case Closed
Status Date: 03/29/1999
Case Worker: Not reported
RB Case Number: 9UT3376
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H04568-002
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607302137
Action Type: ENFORCEMENT
Date: 01/17/1995
Action: Notice of Responsibility

CITY OF CHULA VISTA (Continued) **S100178527**

Global Id: T0607302137
Action Type: Other
Date: 11/08/1994
Action: Leak Reported

Global Id: T0607302137
Action Type: Other
Date: 11/08/1994
Action: Leak Began

Global Id: T0607302137
Action Type: ENFORCEMENT
Date: 03/15/1999
Action: Closure/No Further Action Letter - #H04568-002

Global Id: T0607302137
Action Type: Other
Date: 11/08/1994
Action: Leak Discovery

Global Id: T0607302137
Action Type: Other
Date: 11/08/1994
Action: Leak Stopped

LUST:
Global Id: T0607302137
Status: Open - Case Begin Date
Status Date: 01/03/1994

Global Id: T0607302137
Status: Completed - Case Closed
Status Date: 03/29/1999

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607399063
Global Id: T0607399063
Latitude: 32.6370077878008
Longitude: -117.097177505493
Status: Completed - Case Closed
Status Date: 07/12/2017
Case Worker: CQC
RB Case Number: 9UT4025
Local Agency: Not reported
File Location: Local Agency
Local Case Number: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Diesel, Gasoline
Site History: This case was opened following the discovery of contaminated soil during the removal of a 10,000 gallon diesel tank on December 2, 1999. Additionally, case H04568-005 opened in 1/2004 was administratively consolidated with this case in July 2008. Two USTs

CITY OF CHULA VISTA (Continued) **S100178527**

were removed in 2004 and diesel fuel contamination was discovered beneath a dispenser island. The diesel fuel contamination was over-excavated during the tank removal activities.

LUST:
Global Id: T0607399063
Contact Type: Regional Board Caseworker
Contact Name: CHARLES Q. CHENG
Organization Name: SAN DIEGO RWQCB (REGION 9)
Address: 2375 NORTHSIDE DRIVE, SUITE 100
City: SAN DIEGO
Email: charles.cheng@waterboards.ca.gov
Phone Number: 6195213359

LUST:
Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 10/29/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 07/28/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 12/02/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 04/14/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: Other
Date: 12/02/1999
Action: Leak Reported

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 03/24/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 07/09/2009
Action: Letter - Notice

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 06/12/2017
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT

CITY OF CHULA VISTA (Continued) **S100178527**

Date: 07/28/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 10/21/2009
Action: Verbal Enforcement

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 08/31/2009
Action: Letter - Notice

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 11/30/2010
Action: Staff Letter

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 10/01/2014
Action: Referral to Regional Board

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 06/11/2014
Action: Letter - Notice

Global Id: T0607399063
Action Type: RESPONSE
Date: 08/10/2009
Action: Verbal Communication

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 06/03/2014
Action: Site Visit / Inspection / Sampling

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 06/03/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 07/21/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 06/02/2016
Action: File review

Global Id: T0607399063
Action Type: RESPONSE
Date: 10/23/2009
Action: Monitoring Report - Other

CITY OF CHULA VISTA (Continued) **S100178527**

Global Id: T0607399063
Action Type: RESPONSE
Date: 11/14/2014
Action: Other Report / Document

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 05/19/2011
Action: Staff Letter

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 06/15/2011
Action: Staff Letter

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 04/10/2017
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: Other
Date: 12/02/1999
Action: Leak Began

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 01/18/2000
Action: Notice of Responsibility

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 09/21/2011
Action: Staff Letter

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 04/11/2017
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 06/25/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: RESPONSE
Date: 08/13/2010
Action: Monitoring Report - Quarterly

Global Id: T0607399063
Action Type: RESPONSE
Date: 08/13/2010
Action: Soil and Water Investigation Report

Global Id: T0607399063
Action Type: RESPONSE

CITY OF CHULA VISTA (Continued) **S100178527**

Date: 06/29/2012
Action: Conceptual Site Model - Regulator Responded

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 06/27/2016
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 05/02/2017
Action: Notification - Public Notice of Case Closure

Global Id: T0607399063
Action Type: Other
Date: 12/02/1999
Action: Leak Discovery

Global Id: T0607399063
Action Type: RESPONSE
Date: 06/14/2016
Action: Well Installation Workplan - Regulator Responded

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 05/14/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 05/04/2017
Action: Notification - Fee Title Owners Notice

Global Id: T0607399063
Action Type: ENFORCEMENT
Date: 07/12/2017
Action: Closure/No Further Action Letter

Global Id: T0607399063
Action Type: Other
Date: 12/02/1999
Action: Leak Stopped

LUST:
Global Id: T0607399063
Status: Open - Case Begin Date
Status Date: 12/02/1999

Global Id: T0607399063
Status: Open - Site Assessment
Status Date: 12/02/1999

Global Id: T0607399063
Status: Open - Eligible for Closure
Status Date: 05/04/2017

Global Id: T0607399063

CITY OF CHULA VISTA (Continued) **S100178527**

Status: Completed - Case Closed
Status Date: 07/12/2017

SAN DIEGO CO. SAM:

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Case Number: H04568-001
Agency: CA Regional Water Quality Control Board
Funding: **Private - VAP**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 5/2/1997
Date Began: 10/22/1987

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Case Number: H04568-002
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 3/29/1999
Date Began: 11/8/1994

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Case Number: H04568-003
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: OX
Facility Status: Preliminary Assessment
Date: 12/29/1999
Date Began: 12/2/1999

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Case Number: H04568-004
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 4/14/2005
Date Began: Not reported

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Case Number: H04568-005
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Soils Only
Facility Status: Closed Case

CITY OF CHULA VISTA (Continued) **S100178527**

Date: 7/7/2008
Date Began: 11/8/2004

CPS-SLIC:
Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Region: STATE
Facility Status: Completed - Case Closed
Status Date: 04/14/2005
Global Id: SLT19762335
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H04568-004
Latitude: 32.6372336574701
Longitude: -117.097134590149
Case Type: Cleanup Program Site
Case Worker: NS
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

HMMD SAN DIEGO:
Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 104568
Business Type: 6HK70
EPA Id Number: CAD981435852
APN: 567-031-27-00
Last HMMD Inspection: 01/21/2005
Facility Telephone: 619-691-5027
Permit Status: INAC
Permit Expiration: 06/30/2005
Date Last Updated: 11/02/2012
Facility Owner: JACK DICKENS, FLT MGR
Facility Mailing Address: 1800 MAXWELL RD
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91911-6158
UST Owner: CITY OF CHULA VISTA
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Violations Inactive Permits:
Permit Number: 104568
Update Date: 11/02/2012
Inspection Date: 01/06/2003
Violation Code: 6HV3501

CITY OF CHULA VISTA (Continued) **S100178527**

Violation: NO MONTHLY 0.2 GPH TANK GAUGING TEST
Violation Citation: SINGLE WALLED TANKS:OPTION 1: Monthly 0.2 gallon per hour tank gauging test not performed. 2643(b)(1)
Activity: Inactive Permit

Permit Number: 104568
Update Date: 11/02/2012
Inspection Date: 01/06/2003
Violation Code: 6HV3501
Violation: NO MONTHLY 0.2 GPH TANK GAUGING TEST
Violation Citation: SINGLE WALLED TANKS:OPTION 1: Monthly 0.2 gallon per hour tank gauging test not performed. 2643(b)(1)
Activity: Inactive Permit

Permit Number: 104568
Update Date: 11/02/2012
Inspection Date: 01/06/2003
Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: Inactive Permit

Permit Number: 104568
Update Date: 11/02/2012
Inspection Date: 01/06/2003
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: Inactive Permit

Permit Number: 104568
Update Date: 11/02/2012
Inspection Date: 01/06/2003
Violation Code: 6HV1009
Violation: HMBP: INADEQUATE SITE MAP
Violation Citation: Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity: Inactive Permit

Permit Number: 104568
Update Date: 11/02/2012
Inspection Date: 01/29/2004
Violation Code: 6HV3112
Violation: 2NDRY CONT TEST NOT DONE (6/36 MOS.)
Violation Citation: Secondary containment testing not conducted at 6months/36 months. 25284.1; 2637(a)
Activity: Inactive Permit

Permit Number: 104568
Update Date: 11/02/2012
Inspection Date: 01/29/2004
Violation Code: 6HV1009
Violation: HMBP: INADEQUATE SITE MAP
Violation Citation: Business Plan does not have a site map which provides sufficient or

CITY OF CHULA VISTA (Continued) **S100178527**

complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity: Inactive Permit

UST:
UST Name: UNDERGROUND TANK 104568 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 104568
Tank Type: SINGLE WALL
Additional Id: RT1376/AT5114
Capacity Gallons: 12000
UST Contents: DIESEL
Other Content Info: EMPTY
Reg Status: REMOVED
Remove Close Date: 2004-11-08 00:00:00
Year Installed: 1980-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 05
UST Monitor Method: SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name: UNDERGROUND TANK 104568 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 104568
Tank Type: SINGLE WALL
Additional Id: Not reported
Capacity Gallons: 550
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: 1987-01-12 00:00:00
Year Installed: 1965-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 104568 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 104568
Tank Type: SINGLE WALL
Additional Id: Not reported
Capacity Gallons: 1000
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1987-01-12 00:00:00
Year Installed: 1965-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 104568 T004

CITY OF CHULA VISTA (Continued) **S100178527**

Last Update:	2012-11-02 14:17:38
Permit Number:	104568
Tank Type:	SINGLE WALL
Additional Id:	Not reported
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1987-01-12 00:00:00
Year Installed:	1965-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 104568 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	104568
Tank Type:	SINGLE WALL
Additional Id:	RT1376 REGULAR UNLEADED/AT5114
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	EMPTY 1-28-04
Reg Status:	REMOVED
Remove Close Date:	2004-11-08 00:00:00
Year Installed:	1980-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 104568 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	104568
Tank Type:	SINGLE WALL
Additional Id:	8 DIESEL
Capacity Gallons:	10000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	REMOVED
Remove Close Date:	1999-12-02 00:00:00
Year Installed:	1982-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	SUCTION
Monitor Code:	01
UST Monitor Method:	SW TANK SW SUCTION PIPE W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST TRIENNIALLY

SWEEPS UST:

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City:	CHULA VISTA
Status:	Active
Comp Number:	4568

CITY OF CHULA VISTA (Continued) **S100178527**

Number: 9
Board Of Equalization: 44-022065
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-004568-000001
Tank Status: A
Capacity: 12000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 3

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City: CHULA VISTA
Status: Active
Comp Number: 4568
Number: 9
Board Of Equalization: 44-022065
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-004568-000005
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City: CHULA VISTA
Status: Active
Comp Number: 4568
Number: 9
Board Of Equalization: 44-022065
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-004568-000006
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: OTHER
Number Of Tanks: Not reported

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST

CITY OF CHULA VISTA (Continued) **S100178527**

City:	CHULA VISTA
Status:	Not reported
Comp Number:	4568
Number:	Not reported
Board Of Equalization:	44-022065
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-004568-000002
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	OTHER
Number Of Tanks:	3

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	4568
Number:	Not reported
Board Of Equalization:	44-022065
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-004568-000003
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	WASTE
Content:	Not reported
Number Of Tanks:	Not reported

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City:	CHULA VISTA
Status:	Not reported
Comp Number:	4568
Number:	Not reported
Board Of Equalization:	44-022065
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-004568-000004
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	UNKNOWN
STG:	PRODUCT
Content:	Not reported
Number Of Tanks:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

CORTESE:

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 919102005
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T06019774117
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 919102005
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607302137
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 919102005
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607399063

CITY OF CHULA VISTA (Continued) **S100178527**

Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

ENF:

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW

CITY OF CHULA VISTA (Continued) **S100178527**

Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403303
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2007-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	10/26/2015
Effective Date:	01/24/2007
Expiration/Review Date:	Not reported
Termination Date:	06/26/2013
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	395681
Region:	9
Order / Resolution Number:	Not reported
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	04/11/2014
Adoption/Issuance Date:	04/11/2014
Achieve Date:	Not reported
Termination Date:	04/11/2014
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	SEL 04/11/2014 for Chula Vista City re R9-2007-0001
Description:	Staff enforcement letter (via email) requiring the City to provide recommendations for bringing its construction storm water management program into compliance with the requirements of Order No. R9-2007-0001.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0
Name:	CHULA VISTA MS4

CITY OF CHULA VISTA (Continued) **S100178527**

Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	254951
Region:	9
Order / Resolution Number:	R9-2005-0035
Enforcement Action Type:	13267 Letter
Effective Date:	01/20/2005
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	02/14/2005
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	13267 Letter regarding NOV R9-2005-0035 at Otay Ranch Village 11 Copermittee Chula Vista City of R9-2001-0001
Description:	13267 letter issued due to municipal storm water permit violations.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	254950
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Notice of Violation
Effective Date:	01/20/2005
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	01/20/2005
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	NOV R9-2001-0001 Copermitee Chula Vista City (MS4 Violations)
Description:	NOV for municipal storm water permit violations.
Program:	MNSTW1

CITY OF CHULA VISTA (Continued) **S100178527**

Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	253147
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Notice of Violation
Effective Date:	09/10/2004
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	09/10/2004
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	NOV R9-2001-0001 Copermitee Chula Vista City (Powerwashing City Bus Stop)
Description:	A City of Chula Vista crew was powerwashing a bus stop. The polluted urban runoff discharged to a storm drain. The crew did not use any reclamation BMPs. Powerwashing discharges are prohibited by the Municipal urban runoff permit.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency

CITY OF CHULA VISTA (Continued) **S100178527**

# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	249649

CITY OF CHULA VISTA (Continued) **S100178527**

Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	11/05/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/05/2003
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	SEL R9-2001-0001 Copermittee Chula Vista City (Facility Inspection Report Documentg Violations)
Description:	Staff Enforcement Letter in the form of the Facility Inspection Report documenting violations of the SD MS4 permit. Violations include failure to enforce stormwater ordinance, failure to implement JURMP's enforcement protocol at private construction site.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	247192
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	13267 Letter
Effective Date:	11/21/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/21/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	13267 Letter re violations of NOV R9-2002-0386 Copermitee Chula Vista City of R9-2001-0001
Description:	13267 letter requesting technical report due to violations in NOV No. R9-2002-0386. Report includes: 1)Inspections and Enforcements section, 2) Site status report, 3) Construction component update 3) Educations section
Program:	MNSTW1
Latest Milestone Completion Date:	12/19/2002
# Of Programs1:	1

CITY OF CHULA VISTA (Continued) **S100178527**

Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	247191
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Notice of Violation
Effective Date:	11/21/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/21/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	NOV R9-2001-0001 Copermitee Chula Vista City (Failure to Enforce & Implement BMPs)
Description:	Violations of Municipal Permit at Oakwood development construction site. Failure to enforce ordinances. Failure to implement/maintain BMPs to MEP standard. Failure to implement BMPs
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619

CITY OF CHULA VISTA (Continued) **S100178527**

Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	247129
Region:	9
Order / Resolution Number:	UNKNOWN

CITY OF CHULA VISTA (Continued) **S100178527**

Enforcement Action Type:	13267 Letter
Effective Date:	11/18/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/18/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	13267 Letter R9-2001-0001 Copermitee Chula Vista City (Report on Inspections & Enforcement)
Description:	13267 letter requesting information on Chula Vista's inspection and enforcement activities at a private construction site.
Program:	MNSTW1
Latest Milestone Completion Date:	12/5/2002
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	246445
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	13267 Letter
Effective Date:	10/31/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	10/31/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	13267 Letter R9-2001-0001 Copermittee Chula Vista City (Technical Report for Status and Corrective Actions)
Description:	Request for Technical Report including:1)Immediate Actions Section,2)Site Status Report Section,3)Education Actions Section.
Program:	MNSTW1
Latest Milestone Completion Date:	11/25/2002
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0

CITY OF CHULA VISTA (Continued) **S100178527**

Project $ Completed:	0
Total $ Paid/Completed Amount:	0
Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001

CITY OF CHULA VISTA (Continued) **S100178527**

Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	246444
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Notice of Violation
Effective Date:	10/31/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	10/31/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	NOV R9-2001-0001 Copermitee Chula Vista City (Failure to Implement BMPs and Reduce Discharges MEP)
Description:	Notice of Violation of Municipal Permit. Failure to Implement BMPs, Failure to prevent illicit discharges, Failure to Implement BMPs to reduce pollutant discharges to the maximum extent practicable.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	245970
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	13267 Letter
Effective Date:	01/27/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	01/27/2003

CITY OF CHULA VISTA (Continued) **S100178527**

ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	13267 Letter R9-2001-0001 Copermiteee Chula Vista City (Report on SUSMP Implementation)
Description:	13267 letter requesting a report including: 1) Description of city efforts to implement the local SUSMP to protect water bodies 2) City efforts to implement SUSMP including departmental roles and responsibilities 3) Updated SUSMP.
Program:	MNSTW1
Latest Milestone Completion Date:	2/6/2003
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW

CITY OF CHULA VISTA (Continued) **S100178527**

Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	245969
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Notice of Violation
Effective Date:	01/27/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	01/27/2003
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	NOV R9-2001-0001 Copermittee Chula Vista City (SUSMP Deficiency)
Description:	NOtice of Violation for the City of Chula Vista's local SUSMP did not contain a definitions section or a Implementation Process Section.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0
Name:	CHULA VISTA MS4
Address:	707 F ST

CITY OF CHULA VISTA (Continued) **S100178527**

City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	245967
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	01/27/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	01/27/2003
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	SEL R9-2001-0001 Copermitee Chula Vista City (Violations of SUSMP Language)
Description:	A Staff enforcement letter for violations where the local SUSMP language deviated from the Model SUSMP.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	245547
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	11/26/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/26/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	SEL R9-2001-0001 Copermitee Chula Vista City (Violations Construction Pacific Eastlake Vistas III)
Description:	Staff enforcement letter for violations of Municipal Permit construction component at Western Pacific Eastlake Vistas

CITY OF CHULA VISTA (Continued) **S100178527**

	III Summer Hill private construction site. enforce ordinance, BMPs, MEP standard.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0
Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001

CITY OF CHULA VISTA (Continued) **S100178527**

Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	245546
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	11/26/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/26/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	SEL R9-2001-0001 CoPermitee Chula Vista City (Violations Construction Rolling Hills Ranch 7A & 7B)
Description:	Staff enforcement letter for violations of Municipal Permit construction component at a Rolling Hills Ranch Neighborhood Neighborhood 7A & 7B private construction site. enforce ordinance, BMPs, MEP standard.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility

CITY OF CHULA VISTA (Continued) **S100178527**

Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I

CITY OF CHULA VISTA (Continued) **S100178527**

Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	245515
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	13267 Letter
Effective Date:	11/26/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/26/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	13267 Letter R9-2001-0001 Copermitee Chula Vista City (Technical Report on Construction Violations Otay Village 1)
Description:	13267 letter requesting technical report due to violations of the SDRWQCB Municipal Permit's construction component at the Otay Ranch Village 1 Neighborhood R-47 private construction site.
Program:	MNSTW1
Latest Milestone Completion Date:	12/20/2002
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas

CITY OF CHULA VISTA (Continued) **S100178527**

Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	245514
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Notice of Violation
Effective Date:	11/26/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/26/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	NOV R9-2001-0001 Copermitee Chula Vista City (Construction violations Otay Ranch Village 1)
Description:	NOV for violations of SDRWQCB Municipal Permit construction component at the Otay Ranch Village 1 West Neighborhood R-47 private construction site.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	245513
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	11/25/2002
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	11/25/2002
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	SEL R9-2001-0001 Copermitee Chula Vista City (Construction CV Police Station not under CGP)
Description:	Staff enforcement letter for violations of the Municipal Permit's construction component at the city of Chula Vista's construction of a new police station. SIte is under 5 acres, therefore not covered by the General Construction permit at this time.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency

CITY OF CHULA VISTA (Continued) **S100178527**

# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	242984

CITY OF CHULA VISTA (Continued) **S100178527**

Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Staff Enforcement Letter
Effective Date:	07/22/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	07/22/2003
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	SEL R9-2001-0001 Copermitee Chula Vista City (Inadequate BMPs East Lake Golf Course)
Description:	Inadequate BMPs at East Lake Green golf course.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015
Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	242079
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	13267 Letter
Effective Date:	07/30/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	08/29/2003
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	13267 letter R9-2001-0001 Co Permittee Chula Vista City (Information on Corrective Actions)
Description:	13267 letter requesting information on correction of observed violations. letter requests: 1)Immediate Actions, 2) Site Status Report, 3) Education Actions, and 4) Inspection Activities. report due on August 29, 2003.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0

CITY OF CHULA VISTA (Continued) **S100178527**

Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0
Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Chula Vista City
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	MNSTW1
Program Category1:	NPDESSW
Program Category2:	NPDESSW
# Of Programs:	1
WDID:	Not reported
Reg Measure Id:	403376
Reg Measure Type:	Co-Permitee
Region:	9
Order #:	R9-2001-0001
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	12/24/2015

CITY OF CHULA VISTA (Continued) **S100178527**

Effective Date:	02/21/2001
Expiration/Review Date:	Not reported
Termination Date:	01/23/2007
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	I
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	242077
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	Notice of Violation
Effective Date:	07/30/2003
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	07/30/2003
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	NOV R9-2001-0001 CoPermitee Chula Vista City (Inadequate BMP's and illicit discharges)
Description:	NOV for violations of the San Diego Municipal Storm Water Permit observed at the Chula Vista Municipal Golf Course.Violations included illicit discharge of vehicle wash water, inadequate BMPs, and BMPs not to the MEP standard.
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA,CITY OF, PUB WORKS
Address:	707 F
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214495
Agency Name:	Chula Vista City
Place Type:	Facility
Place Subtype:	Not reported
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	Not reported
SIC Desc 1:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	Not reported
Program Category1:	Not reported
Program Category2:	UNREGS
# Of Programs:	Not reported
WDID:	9 000002N89
Reg Measure Id:	162171
Reg Measure Type:	Unregulated
Region:	9
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	06/17/2005
Effective Date:	Not reported
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	Not reported
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	221405
Region:	9
Order / Resolution Number:	89-038
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date:	04/21/1989
Adoption/Issuance Date:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Achieve Date:	9/16/1996
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	Enforcement - 9 000002N89
Description:	CLEANUP AND ABATEMENT ORDER ISSUED FOR TPCA SITE.
Program:	ENFCAO
Latest Milestone Completion Date:	9/16/1996
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA,CITY OF, PUB WORKS
Address:	707 F
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214495
Agency Name:	Chula Vista City
Place Type:	Facility
Place Subtype:	Not reported
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	Not reported
SIC Desc 1:	Not reported
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	Not reported
Program Category1:	Not reported
Program Category2:	UNREGS
# Of Programs:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

WDID:	9 000002N89
Reg Measure Id:	162171
Reg Measure Type:	Unregulated
Region:	9
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	06/17/2005
Effective Date:	Not reported
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	Not reported
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	221404
Region:	9
Order / Resolution Number:	89-038A4
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date:	02/09/1995
Adoption/Issuance Date:	Not reported
Achieve Date:	9/16/1996
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	Enforcement - 9 000002N89
Description:	UNKNOWN
Program:	ENFCAO
Latest Milestone Completion Date:	9/16/1996
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA,CITY OF, PUB WORKS
Address:	707 F
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214495
Agency Name:	Chula Vista City

CITY OF CHULA VISTA (Continued) **S100178527**

Place Type:	Facility
Place Subtype:	Not reported
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	Not reported
SIC Desc 1:	Not reported
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	Not reported
Program Category1:	Not reported
Program Category2:	UNREGS
# Of Programs:	Not reported
WDID:	9 000002N89
Reg Measure Id:	162171
Reg Measure Type:	Unregulated
Region:	9
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	06/17/2005
Effective Date:	Not reported
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N

CITY OF CHULA VISTA (Continued) **S100178527**

Individual/General:	Not reported
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	221403
Region:	9
Order / Resolution Number:	89-038A5
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date:	02/06/1996
Adoption/Issuance Date:	Not reported
Achieve Date:	9/26/1996
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	Enforcement - 9 000002N89
Description:	UNKNOWN
Program:	ENFCAO
Latest Milestone Completion Date:	9/26/1996
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

Name:	CHULA VISTA,CITY OF, PUB WORKS
Address:	707 F
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214495
Agency Name:	Chula Vista City
Place Type:	Facility
Place Subtype:	Not reported
Facility Type:	Municipal/Domestic
Agency Type:	City Agency
# Of Agencies:	1
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	Not reported
SIC Desc 1:	Not reported
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Reg Meas
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	Not reported
Program Category1:	Not reported
Program Category2:	UNREGS
# Of Programs:	Not reported
WDID:	9 000002N89
Reg Measure Id:	162171
Reg Measure Type:	Unregulated
Region:	9
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Historical
Status Date:	06/17/2005
Effective Date:	Not reported
Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	N
Individual/General:	Not reported
Fee Code:	Not reported
Direction/Voice:	Passive
Enforcement Id(EID):	220737
Region:	9
Order / Resolution Number:	96-062
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date:	09/26/1996
Adoption/Issuance Date:	Not reported
Achieve Date:	9/26/1999
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	Enforcement - 9 000002N89
Description:	UNKNOWN
Program:	ENFCAO
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0

CITY OF CHULA VISTA (Continued) **S100178527**

Project $ Completed:	0
Total $ Paid/Completed Amount:	0
Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Region:	9
Facility Id:	214491
Agency Name:	Not reported
Place Type:	Utility
Place Subtype:	MS4
Facility Type:	Municipal/Domestic
Agency Type:	Not reported
# Of Agencies:	Not reported
Place Latitude:	32.636619
Place Longitude:	-117.096437
SIC Code 1:	9511
SIC Desc 1:	Air and Water Resource and Solid Waste Management
SIC Code 2:	Not reported
SIC Desc 2:	Not reported
SIC Code 3:	Not reported
SIC Desc 3:	Not reported
NAICS Code 1:	Not reported
NAICS Desc 1:	Not reported
NAICS Code 2:	Not reported
NAICS Desc 2:	Not reported
NAICS Code 3:	Not reported
NAICS Desc 3:	Not reported
# Of Places:	1
Source Of Facility:	Enf Action
Design Flow:	Not reported
Threat To Water Quality:	Not reported
Complexity:	Not reported
Pretreatment:	Not reported
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	Not reported
Program Category1:	Not reported
Program Category2:	NPDESSW
# Of Programs:	Not reported
WDID:	Not reported
Reg Measure Id:	Not reported
Reg Measure Type:	Not reported
Region:	Not reported
Order #:	Not reported
Npdes# CA#:	Not reported
Major-Minor:	Not reported
Npdes Type:	Not reported
Reclamation:	Not reported
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	Not reported
Status:	Not reported
Status Date:	Not reported
Effective Date:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Expiration/Review Date:	Not reported
Termination Date:	Not reported
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	Not reported
Individual/General:	Not reported
Fee Code:	Not reported
Direction/Voice:	Not reported
Enforcement Id(EID):	253148
Region:	9
Order / Resolution Number:	UNKNOWN
Enforcement Action Type:	13267 Letter
Effective Date:	09/10/2004
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	09/10/2004
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	13267 Letter R9-2001-0001 Copermitee Chula Vista City (Report on City's Powerwashing Activities)
Description:	13267 letter requesting a technical report due to a powerwashing discharge by a City of Chula Vista Crew. The report is to include 8 sections providing a comprehensive review of the City's powerwashing policies and procedures including recovery procedure
Program:	MNSTW1
Latest Milestone Completion Date:	Not reported
# Of Programs1:	1
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability $ Amount:	0
Project $ Amount:	0
Liability $ Paid:	0
Project $ Completed:	0
Total $ Paid/Completed Amount:	0

HIST CORTESE:

edr_fname:	CHULA VISTA, CITY OF, PUB
edr_fadd1:	707 F
City,State,Zip:	CHULA VISTA, CA 92010
Region:	CORTESE
Facility County Code:	37
Reg By:	WBC&D
Reg Id:	9 000002N89

edr_fname:	CITY OF CHULA VISTA
edr_fadd1:	707 F
City,State,Zip:	CHULA VISTA, CA 92010
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT3376

CITY OF CHULA VISTA (Continued) **S100178527**

NOTIFY 65:

Name:	CITY OF CHULA VISTA
Address:	707 F STREET
City,State,Zip:	CHULA VISTA, CA 91910-2005
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

SAN DIEGO CO LOP:

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1994-LSAM-H04568-002
Record Status:	Completed
Opened Date:	11/08/1994
Parcel Number:	567-031-27-00
Case Type:	LOP - Local Oversight Program
Historical Name:	CITY OF CHULA VISTA
SWRCB Global ID:	T0607302137
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	01/03/1994
Census Tract:	125.02
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6374065
Longitude:	-117.0973574
X MapCoord:	6300767.057
Y MapCoord:	1812815.188

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1999-LSAM-H04568-003
Record Status:	Completed
Opened Date:	12/02/1999
Parcel Number:	567-031-27-00
Case Type:	LOP - Local Oversight Program
Historical Name:	CITY OF CHULA VISTA
SWRCB Global ID:	T0607399063
Funding:	S - LOP State Fund
Lead Agency:	RWQCB
Lead Agency Date:	09/26/2014
Census Tract:	125.02
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12

CITY OF CHULA VISTA (Continued) **S100178527**

Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6374065
Longitude:	-117.0973574
X MapCoord:	6300767.057
Y MapCoord:	1812815.188

Name:	CHULA VISTA CITY PUBLIC WORKS
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH2004-LSAM-H04568-005
Record Status:	Completed
Opened Date:	11/24/2004
Parcel Number:	567-031-27-00
Case Type:	LOP - Local Oversight Program
Historical Name:	CHULA VISTA CITY YARD
SWRCB Global ID:	T06019774117
Funding:	S - LOP State Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	11/30/2004
Census Tract:	125.02
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6374065
Longitude:	-117.0973574
X MapCoord:	6300767.057
Y MapCoord:	1812815.188

CIWQS:

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Oceanside City
Agency Address:	300 North Coast Highway, Oceanside, CA 92054
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619

CITY OF CHULA VISTA (Continued) **S100178527**

Longitude:	-117.096437
Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	San Marcos City
Agency Address:	1 Civic Center Drive, San Marcos, CA 92069
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437
Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Del Mar City
Agency Address:	1050 Camino Del Mar, Del Mar, CA 92014
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437
Name:	CHULA VISTA MS4

CITY OF CHULA VISTA (Continued) **S100178527**

Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	National City
Agency Address:	1243 National City Avenue, National City, CA 91950
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Vista City
Agency Address:	200 Civic Center Drive, Vista, CA 92084
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	El Cajon City

CITY OF CHULA VISTA (Continued) **S100178527**

Agency Address:	200 Civic Center Way, El Cajon, CA 92020
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Encinitas City
Agency Address:	505 South Vulcan Avenue, Encinitas, CA 92024
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Escondido City
Agency Address:	201 North Broadway, Escondido, CA 92025
Place/Project Type:	MS4
SIC/NAICS:	9511

CITY OF CHULA VISTA (Continued) **S100178527**

Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	La Mesa City
Agency Address:	Po Box 937, La Mesa, CA 91944-0937
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Poway City
Agency Address:	13325 Civic Center Drive, Poway, CA 92064-0789
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical

CITY OF CHULA VISTA (Continued) **S100178527**

Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Carlsbad City
Agency Address:	1635 Faraday Avenue, Carlsbad, CA 92008-7314
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Lemon Grove City
Agency Address:	3232 Main Street, Lemon Grove, CA 91945
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Chula Vista City
Agency Address:	276 4th Avenue, Chula Vista, CA 91910-2699
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	Co-Permitee
Order Number:	R9-2007-0001
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	01/24/2007
Effective Date:	01/24/2007
Termination Date:	06/26/2013
Expiration/Review Date:	Not reported
Design Flow:	Not reported
Major/Minor:	Major
Complexity:	Not reported
TTWQ:	Not reported
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	Coronado City
Agency Address:	1300 First Street, Coronado, CA 92118-1598
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990

CITY OF CHULA VISTA (Continued) **S100178527**

Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	San Diego City Transp & Stormwater Dept (Storm Water Division) Public Works
Agency Address:	9370 Chesapeake Drive 100, San Diego, CA 92025
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437

Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	San Diego Cnty Dept of Environmental Health
Agency Address:	5500 Overland Avenue 170, San Diego, CA 92123
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0

CITY OF CHULA VISTA (Continued) **S100178527**

Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437
Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	San Diego County Dept of Public Works
Agency Address:	5510 Overland Avenue 210/O350, San Diego, CA 92123
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	32.636619
Longitude:	-117.096437
Name:	CHULA VISTA MS4
Address:	707 F ST
City,State,Zip:	CHULA VISTA, CA 91910
Agency:	San Diego Unified Port District
Agency Address:	3165 Pacific Highway, San Diego, CA 92101-1128
Place/Project Type:	MS4
SIC/NAICS:	9511
Region:	9
Program:	MNSTW1
Regulatory Measure Status:	Historical
Regulatory Measure Type:	NPDES Permit
Order Number:	R9-1990-0042
WDID:	Not reported
NPDES Number:	Not reported
Adoption Date:	07/16/1990
Effective Date:	07/16/1990
Termination Date:	02/20/2001
Expiration/Review Date:	07/16/1995
Design Flow:	0
Major/Minor:	Major
Complexity:	A
TTWQ:	1

CITY OF CHULA VISTA (Continued) **S100178527**

Enforcement Actions within 5 years: 0
Violations within 5 years: 0
Latitude: 32.636619
Longitude: -117.096437

Name: CHULA VISTA MS4
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 91910
Agency: Imperial Beach City
Agency Address: 825 Imperial Beach Boulevard, Imperial Beach, CA 91932
Place/Project Type: MS4
SIC/NAICS: 9511
Region: 9
Program: MNSTW1
Regulatory Measure Status: Historical
Regulatory Measure Type: NPDES Permit
Order Number: R9-1990-0042
WDID: Not reported
NPDES Number: Not reported
Adoption Date: 07/16/1990
Effective Date: 07/16/1990
Termination Date: 02/20/2001
Expiration/Review Date: 07/16/1995
Design Flow: 0
Major/Minor: Major
Complexity: A
TTWQ: 1
Enforcement Actions within 5 years: 0
Violations within 5 years: 0
Latitude: 32.636619
Longitude: -117.096437

CERS:
Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Site ID: 221144
CERS ID: SLT19762335
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: NASSER SIONIT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Regional Board Caseworker
Entity Name: CHARLES Q. CHENG - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA

CITY OF CHULA VISTA (Continued) **S100178527**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213359

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Site ID: 221144
CERS ID: T06019774117
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: NASSER SIONIT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Regional Board Caseworker
Entity Name: CHARLES Q. CHENG - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213359

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Site ID: 221144
CERS ID: T0607399063
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: NASSER SIONIT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Regional Board Caseworker
Entity Name: CHARLES Q. CHENG - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA

CITY OF CHULA VISTA (Continued) **S100178527**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213359

Name: CHULA VISTA CITY PUBLIC WORKS
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 919102005
Site ID: 221144
CERS ID: T0607302137
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: NASSER SIONIT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Regional Board Caseworker
Entity Name: CHARLES Q. CHENG - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213359

Name: CHULA VISTA MS4
Address: 707 F ST
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 18977
CERS ID: 214491
CERS Description: NPDES Wastewater and Stormwater

Violations:
Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 11-26-2002
Citation: California Water Code
Violation Description: Not reported
Violation Notes: City of Chula Vista failed to implement BMPs at the Rolling Hills Ranch Neighborhoods 7A and 7B private construction site. BMPs lacking sediment tracking, BMP maintenance at storm drain inlets and materials for weather triggered action plan.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 11-19-2002

CITY OF CHULA VISTA (Continued) **S100178527**

Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	City of Chula Vista failed to implement BMPS to the MEP standard at the Otay Ranch Village 1 West Neighborhhod R-47 construction site.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	07-16-2003
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	At the Chula Vista Municipal Golf Course, BMPs were not implemented to the MEP standard.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	10-09-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	At the old public works yard, An inside hand washing sink was not connected to the sewer, rather the sink discharged through pipes directly outside to the pavement.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	10-09-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	A drum of asphalt emulsion with diesel was outside without secondary containment or cover. This violation was also cited on the EPA/Tetratech audit dated July 25, 2002 as follows: "Hazardous materials improperly stored outside... etc."
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	10-09-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	Excessive trash was littered throughout the city''s old public works yard.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4

CITY OF CHULA VISTA (Continued) **S100178527**

Violation Date:	10-09-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	Used Oil stored outside in an open plastic bowl. Obvious signs of staining from spills and leaks surrounding. This violation was also cited on the EPA/Tetratech audit dated July 25, 2002 as follows: "Hazardous materials improperly stored outside... etc."
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	07-16-2003
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	At the Chula Vista Municipal Golf Course, golf carts were being washed off directly over a storm drain.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	01-27-2003
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	The City of Chula Vista''s local SUSMP did not include an Implementation Section.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	11-19-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	City of Chula Vista failed to implement BMPs at the Otay Ranch Village 1Neighborhood R-47 private construction site. BMPs lacking included erosion control, sediment control, sediment tracking, pollutant prevention.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	11-19-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	City of Chula Vista failed to enforce their stormwater ordinances at the Otay Ranch, Village 1, Neighborhood R-47 construction site.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS

CITY OF CHULA VISTA (Continued) **S100178527**

Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	11-13-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	The City of Chula Vista failed to enforce the City of Chula Vista Municipal Code Section 14.20.120.A. Best Management Practices Implementation at Otay Ranch Village 1 West Neighborhoods R-55 (North), R-56, R-57, & R-58.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS

Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	10-09-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	Numerous violations of BMP practices indicate that BMPs are not being implemented to meet MEP standards as required by Section E of the permit.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS

Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	11-19-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	The City of Chula Vista did not ensure implementation of the designated minimum BMPs at the construction of the city''s new police station. BMPs were lacking for storage of pollutant materials and for waste handling and storage.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS

Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	01-27-2003
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	The local SUSMP stats that design options are determined applicable and feasible by the developer. Correctly, design options should be determined applicable and feasible by the City of CHula Vista with input form the developer.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS

Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	11-26-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	City of Chula Vista failed to implement BMPs at the Western Pacific

CITY OF CHULA VISTA (Continued) **S100178527**

Housing Eastlake Vistas III - Summer Hill private construction site. BMPs lacking included erosion control on flat pads or desilting basin.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 11-05-2003
Citation: California Water Code
Violation Description: Not reported
Violation Notes: Failure to enforce City stormwater ordinance at private construction site. Failure to implement the JURMPs enforcement program.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 12-29-2004
Citation: California Water Code
Violation Description: Not reported
Violation Notes: BMPs not implemented to the MEP standard at a private construction site within the City of Chula Vista''s jurisdiction.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 11-13-2002
Citation: California Water Code
Violation Description: Not reported
Violation Notes: Otay Ranch Village 1 West Neighborhoods R-55(North), R-56, R-57, & R-58. BMPs lacking included sediment and erosion control, sediment tracking, pollution prevention. BMPs were not to the Maximum Extent Practicable Standard.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 09-03-2004
Citation: California Water Code
Violation Description: Not reported
Violation Notes: A City of Chula Vista work crew was power washing a bus stop. The polluted wash water discharged into the storm drain in violation of the Municipal Stormwater Permit.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 10-09-2002
Citation: California Water Code

CITY OF CHULA VISTA (Continued) **S100178527**

Violation Description:	Not reported
Violation Notes:	Numerous oils spills outside indicating lack of spill prevention and clean up.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	11-13-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	The City of Chula Vista did not ensure implementation of the designated minimum BMPs at Otay Ranch Village 1 West Neighborhoods R-55(North), R-56, R-57, & R-58. BMPs lacking included sediment and erosion control, sediment tracking, pollution prevention.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	07-16-2003
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	Better management of drums is needed at East Lake Greens.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	01-27-2003
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	When the SUSMP conflicts with local practice, the City will make the final determination of applicability . Correctly, where the SUSMP conflicts with local practice the more stringent rule applies, as determined by the City.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	08-05-2015
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	San Diego Bay WMA Water Quality Improvement Plan submitted June 26, 2015 failed to include the information necessary to be in compliance with the requirements of Provisions B in Order No. R9-2013-0001.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4

CITY OF CHULA VISTA (Continued) **S100178527**

Violation Date:	11-26-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	City of Chula Vista failed to implement BMPS to the MEP standard at the Rolling Hills Ranch Neighborhood R-47 private construction site.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	11-19-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	The City of Chula Vista did not ensure implementation of BMPs to the Maximum Extent Practicable Standard. Pollution prevention and waste storage and handling BMPs were needed at the city''s construction of a new police station.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	01-27-2003
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	"to the extent feasible" added in the section on locating BMPs near pollutant sources. Correctly, feasibility is granted by a waiver by the city.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	10-09-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	Fuel spills were not cleaned up properly around the fuel island at the City''s old Public works yard.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Violation Date:	10-09-2002
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	City''s old public works yard did not practice minimum good housekeeping practices. An outside tools bench had trash strewn around it and also had spill stains. Old sandbags had deteriorated and needed to be cleaned up.
Violation Division:	Water Boards
Violation Program:	MNSTW1
Violation Source:	CIWQS

CITY OF CHULA VISTA (Continued) **S100178527**

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 03-13-2014
Citation: California Water Code
Violation Description: Not reported
Violation Notes: For the three construction sites under the City?s jurisdiction inspected by the San Diego Water Board, the City?s implementation of its construction management program is not in compliance with the requirements of sections D.2.a.(2)(a)-(b), D.2.c.(3), D.2.d, D.2.e, and D.5.b.(1)(a)-(b) of Order No. R9-2007-0001.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 07-16-2003
Citation: California Water Code
Violation Description: Not reported
Violation Notes: Housekeeping issues noted at East Lake Greens.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 01-27-2003
Citation: California Water Code
Violation Description: Not reported
Violation Notes: The City of Chula Vista''s local SUSMP did not include a definitions section
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 07-16-2003
Citation: California Water Code
Violation Description: Not reported
Violation Notes: Failure to implement BMPs at the Chula Vista Municipal Golf Course. Fueling area was not covered nor did it have a berm to contain leaks or spills, vehicles were leaking and mowers were being repaired outside, stains from improper material disposal
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 07-16-2003
Citation: California Water Code
Violation Description: Not reported
Violation Notes: Maintenance of mower was conducted outside at East Lake Greens.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

CITY OF CHULA VISTA (Continued) **S100178527**

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 07-16-2003
Citation: California Water Code
Violation Description: Not reported
Violation Notes: Port-a-pottys need containment pans at East Lake Greens.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 11-26-2002
Citation: California Water Code
Violation Description: Not reported
Violation Notes: City of Chula Vista failed to enforce their stormwater ordinances at the Western Pacific Housing Eastlake Vistas III - Summer Hill construction site.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 11-26-2002
Citation: California Water Code
Violation Description: Not reported
Violation Notes: City of Chula Vista failed to enforce their stormwater ordinances at the Rolling Hills Ranch Neighborhoods 7A & 7B.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 12-29-2004
Citation: California Water Code
Violation Description: Not reported
Violation Notes: Failure to implement the construction component of the JURMP at Otay Ranch Village 11.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Violation Date: 11-26-2002
Citation: California Water Code
Violation Description: Not reported
Violation Notes: City of Chula Vista failed to implement BMPS to the MEP standard at the Western Pacific Housing Eastlake Vistas III Summer Hill private construction site.
Violation Division: Water Boards
Violation Program: MNSTW1
Violation Source: CIWQS

CITY OF CHULA VISTA (Continued) **S100178527**

Enforcement Action:

Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	01-20-2005
Enf Action Type:	Enforcement Letter (Formal)
Enf Action Description:	Enforcement Letter Citing Violations and with Required Actions (Formal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS

Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	01-20-2005
Enf Action Type:	Notice of Violation (Water)
Enf Action Description:	Notice of Violation Letter (Informal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS

Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	01-27-2003
Enf Action Type:	Enforcement Letter (Formal)
Enf Action Description:	Enforcement Letter Citing Violations and with Required Actions (Formal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS

Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	01-27-2003
Enf Action Type:	Notice of Violation (Water)
Enf Action Description:	Notice of Violation Letter (Informal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS

Site ID:	18977
Site Name:	Chula Vista MS4

CITY OF CHULA VISTA (Continued) **S100178527**

Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 01-27-2003
Enf Action Type: Staff Enforcement Letter (Informal)
Enf Action Description: Staff Enforcement Letter (Informal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 04-11-2014
Enf Action Type: Staff Enforcement Letter (Informal)
Enf Action Description: Staff Enforcement Letter (Informal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 07-22-2003
Enf Action Type: Staff Enforcement Letter (Informal)
Enf Action Description: Staff Enforcement Letter (Informal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 07-30-2003
Enf Action Type: Enforcement Letter (Formal)
Enf Action Description: Enforcement Letter Citing Violations and with Required Actions (Formal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 07-30-2003

CITY OF CHULA VISTA (Continued) **S100178527**

Enf Action Type:	Notice of Violation (Water)
Enf Action Description:	Notice of Violation Letter (Informal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	08-05-2015
Enf Action Type:	Staff Enforcement Letter (Informal)
Enf Action Description:	Staff Enforcement Letter (Informal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	09-10-2004
Enf Action Type:	Enforcement Letter (Formal)
Enf Action Description:	Enforcement Letter Citing Violations and with Required Actions (Formal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	09-10-2004
Enf Action Type:	Notice of Violation (Water)
Enf Action Description:	Notice of Violation Letter (Informal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	10-31-2002
Enf Action Type:	Enforcement Letter (Formal)
Enf Action Description:	Enforcement Letter Citing Violations and with Required Actions (Formal)
Enf Action Notes:	Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	10-31-2002
Enf Action Type:	Notice of Violation (Water)
Enf Action Description:	Notice of Violation Letter (Informal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	11-05-2003
Enf Action Type:	Staff Enforcement Letter (Informal)
Enf Action Description:	Staff Enforcement Letter (Informal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	11-18-2002
Enf Action Type:	Enforcement Letter (Formal)
Enf Action Description:	Enforcement Letter Citing Violations and with Required Actions (Formal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS
Site ID:	18977
Site Name:	Chula Vista MS4
Site Address:	707 F ST
Site City:	CHULA VISTA
Site Zip:	91910
Enf Action Date:	11-21-2002
Enf Action Type:	Enforcement Letter (Formal)
Enf Action Description:	Enforcement Letter Citing Violations and with Required Actions (Formal)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS

CITY OF CHULA VISTA (Continued) **S100178527**

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 11-21-2002
Enf Action Type: Notice of Violation (Water)
Enf Action Description: Notice of Violation Letter (Informal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 11-25-2002
Enf Action Type: Staff Enforcement Letter (Informal)
Enf Action Description: Staff Enforcement Letter (Informal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 11-26-2002
Enf Action Type: Enforcement Letter (Formal)
Enf Action Description: Enforcement Letter Citing Violations and with Required Actions (Formal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA
Site Zip: 91910
Enf Action Date: 11-26-2002
Enf Action Type: Notice of Violation (Water)
Enf Action Description: Notice of Violation Letter (Informal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

Site ID: 18977
Site Name: Chula Vista MS4
Site Address: 707 F ST
Site City: CHULA VISTA

CITY OF CHULA VISTA (Continued) **S100178527**

Site Zip: 91910
Enf Action Date: 11-26-2002
Enf Action Type: Staff Enforcement Letter (Informal)
Enf Action Description: Staff Enforcement Letter (Informal)
Enf Action Notes: Not reported
Enf Action Division: Water Boards
Enf Action Program: UNSPEC
Enf Action Source: CIWQS

HWTS:
Name: CITY OF CHULA VISTA
Address: 707 F STREET
Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAC003070628
Inactive Date: Not reported
Create Date: 06/12/2020
Last Act Date: 06/12/2020
Mailing Name: Not reported
Mailing Address: 1800 MAXWELL ROAD
Mailing Address 2: Not reported
Mailing City,State,Zip: CHULA VISTA, CA 91911
Owner Name: CITY OF CHULA VISTA
Owner Address: 276 FOURTH AVENUE
Owner Address 2: Not reported
Owner City,State,Zip: CHULA VISTA, CA 91911
Contact Name: JONATHAN SALSMAN
Contact Address: 1800 MAXWELL ROAD
Contact Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 91911

NAICS:
EPA ID: CAC003070628
Create Date: 2020-06-12 11:58:28.230
NAICS Code: 99999
NAICS Description: Not Otherwise Specified
Issued EPA ID Date: 2020-06-12 11:58:28.23000
Inactive Date: Not reported
Facility Name: CITY OF CHULA VISTA
Facility Address: 707 F STREET
Facility Address 2: Not reported
Facility City: CHULA VISTA
Facility County: Not reported
Facility State: CA
Facility Zip: 91910

Name: CITY OF CHULA VISTA
Address: 707 F ST
Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 919102005
EPA ID: CAL000005539
Inactive Date: 01/01/1900
Create Date: 11/14/1989
Last Act Date: 11/23/2004
Mailing Name: Not reported

CITY OF CHULA VISTA (Continued) **S100178527**

Mailing Address:	707 F ST
Mailing Address 2:	Not reported
Mailing City,State,Zip:	CHULA VISTA, CA 919102005
Owner Name:	CITY OF CHULA VISTA
Owner Address:	--
Owner Address 2:	Not reported
Owner City,State,Zip:	--, 99 --
Contact Name:	VALID #CAD981435852
Contact Address:	--
Contact Address 2:	Not reported
City,State,Zip:	--, 99 --

R91 **VACANT PROPERTY OWNED BY THE SD UNIFIED PORT DISTR** **CPS-SLIC S113888528**
South **MARINA PARKWAY** **CERS N/A**
1/4-1/2 **CHULA VISTA, CA 91910**
0.363 mi.
1918 ft. **Site 1 of 2 in cluster R**

Relative: **Lower**
Actual: **5 ft.**

CPS-SLIC:

Name:	VACANT PROPERTY OWNED BY THE SD UNIFIED PORT DISTRICT (PLAT NO. 032-008)
Address:	MARINA PARKWAY
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	05/08/2019
Global Id:	T10000005120
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.6229450989516
Longitude:	-117.09878549469
Case Type:	Cleanup Program Site
Case Worker:	TCA
Local Agency:	Not reported
RB Case Number:	T10000004581
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Polychlorinated biphenyls (PCBs), Arsenic, Lead, Other Metal
Site History:	This was Port owned property adjacent to the former BF Goodrich/Rohr South Campus property. It is part of the "Exchange Parcels" for redevelopment in the Chula Vista Marina District. No known industrial, commercial, or residental activities has taken place on this property. This case was opened to accommodate a Phase II assessment. If contamination is discovered during development of the Exchange Parcels the Port will be required to remediate. Administratively closed May 8, 2019. Any further activity associated with this property will be addressed through Geotracker site ID T10000004581 - CVBD - PACIFICA EXCHANGE PARCELS (H-13, H-14, H-15, HP-5).

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	VACANT PROPERTY OWNED BY THE SD UNIFIED PORT DISTRICT (PLAT NO. 032-008)
Address:	MARINA PARKWAY
City,State,Zip:	CHULA VISTA, CA 91910

VACANT PROPERTY OWNED BY THE SD UNIFIED PORT DISTRICT (PLAT (Continued) **S113888528**

Site ID: 221169
CERS ID: T10000005120
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: TOM ALO - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213375

R92 **CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CVB** **CPS-SLIC** **S118504658**
SSE **MARINA PARKWAY** **DEED** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910**
0.412 mi.
2177 ft. **Site 2 of 2 in cluster R**

Relative:
Higher

Actual:
12 ft.

CPS-SLIC:
Name: CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CVBD - PACIFICA EXCHANGE PARCELS (H-13, H-14, H-15, HP-5)
Address: MARINA PARKWAY
City,State,Zip: CHULA VISTA, CA 91910
Region: STATE
Facility Status: **Open - Remediation**
Status Date: 03/12/2015
Global Id: T10000004581
Lead Agency: SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number: Not reported
Latitude: 32.6223306340135
Longitude: -117.098291968231
Case Type: Cleanup Program Site
Case Worker: TCA
Local Agency: Not reported
RB Case Number: 4090008
File Location: Regional Board
Potential Media Affected: Other Groundwater (uses other than drinking water), Sediments, Soil, Soil Vapor, Surface water
Potential Contaminants of Concern: Dichloroethene (DCE), Other Chlorinated Hydrocarbons, Trichloroethylene (TCE), Lead, Diesel, Other Petroleum, Total Petroleum Hydrocarbons (TPH)
Site History: The Chula Vista Bayfront Master Plan (CVBMP) is a joint master planning process of the Port of San Diego, the City of Chula Vista, and Pacifica Companies. The purpose of the project is to develop a master plan that transforms the Chula Vista waterfront into a world-class destination for local residents and visitors.

Click here to access the California GeoTracker records for this facility:

DEED:
Name: CVBD - PACIFICA EXCHANGE PARCELS (H-13, H-14, H-15, HP-5)
Address: MARINA PARKWAY
City,State,Zip: CHULA VISTA, CA 91910
Envirostor ID: T10000004581

CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CVBD - PACIFI (Continued) **S118504658**

Area: Not reported
Sub Area: Not reported
Site Type: SLIC
Status: OPEN - REMEDIATION
Agency: SWRCB
Covenant Uploaded: Y
Deed Date(s): 05/19/2016
File Name: Geotracker Land Use/Deed Restrictions

S93 **CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CHU** **CPS-SLIC** **S117624735**
North **215 BAY BOULEVARD** **CERS** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910**
0.476 mi.
2515 ft. **Site 1 of 2 in cluster S**

Relative:
Higher

Actual:
24 ft.

CPS-SLIC:

Name:	CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - SWEETWATER PARCELS
Address:	215 BAY BOULEVARD
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	05/02/2016
Global Id:	T10000006477
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.636401755839
Longitude:	-117.101328643655
Case Type:	Cleanup Program Site
Case Worker:	SAM
Local Agency:	Not reported
RB Case Number:	4090005
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Aquifer used for drinking water supply, Soil, Soil Vapor
Potential Contaminants of Concern:	Dichloroethane (DCA), Dichloroethene (DCE), Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Chlordane, DDD / DDE / DDT, Other Insecticides / Pesticide / Fumigants / Herbicides, Toxaphene, Arsenic, Lead, Diesel
Site History:	The approximately 97-acre site is located adjacent to the Sweetwater Marsh/San Diego Bay National Wildlife Refuge and is targeted for development as part of the Chula Vista Bayfront Master Plan. Redevelopment will include an RV park, recreational parks, streets, and utilities. The site has been impacted by historical agricultural use (pesticides in surface and near-surface soil), illegal dumping, petroleum from historical USTs, lead in shallow soil (potential secondary deposits of burn ash from other sources and aerially deposited lead), migration of VOC-contaminated groundwater from off-site industrial sources, metals in shallow soil from former industrial operations (e.g., sandblasting), and possibly waste disposal. Several environmental investigations have been performed at the site since 1999. Additional site assessment was performed in 2015 that involved shallow soil sampling and performance of a human health risk assessment. No further work is required to be performed at this site and the site was issued a No Further Action letter on January 4, 2016. A Soil Management Plan will be prepared for the site for use during future site redevelopment.

CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CHULA VISTA B (Continued) **S117624735**

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	CHULA VISTA BAYFRONT MASTER PLAN DEVELOPMENT - CHULA VISTA BAYFRONT MASTER PLAN
Address:	215 BAY BOULEVARD
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	275248
CERS ID:	T10000006477
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SARAH A. MEARON - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213363

94
NNE
1/4-1/2
0.477 mi.
2520 ft.

WOODLAWN COLONIAL APARTMENTS
245-255 WOODLAWN AVENUE
CHULA VISTA, CA 91910

ENVIROSTOR **S110275496**
VCP **N/A**

Relative:
Higher

Actual:
43 ft.

ENVIROSTOR:

Name:	WOODLAWN COLONIAL APARTMENTS
Address:	245-255 WOODLAWN AVENUE
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	60001253
Status:	No Further Action
Status Date:	06/30/2014
Site Code:	401514
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	4.87
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Irena Edwards
Supervisor:	Manny Alonzo
Division Branch:	Cleanup Cypress
Assembly:	80
Senate:	40
Special Program:	Voluntary Cleanup Program
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	32.63855
Longitude:	-117.0969
APN:	567-032-09-00
Past Use:	DRY CLEANING
Potential COC:	Tetrachloroethylene (PCE

WOODLAWN COLONIAL APARTMENTS (Continued) **S110275496**

Confirmed COC: Tetrachloroethylene (PCE
Potential Description: IA, OTH
Alias Name: 567-032-09-00
Alias Type: APN
Alias Name: 401514
Alias Type: Project Code (Site Code)
Alias Name: 60001253
Alias Type: Envirostor ID Number
Alias Name: 60001334
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Letter - Demand
Completed Date: 03/25/2011
Comments: Reminder letter sent for unpaid past due invoice.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 04/28/2011
Comments: Closeout memo sent to accounting.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 06/03/2010
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 04/28/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Correspondence - Received
Completed Date: 02/07/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement Termination Notification
Completed Date: 07/08/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 12/17/2009
Comments: Fully Executed VCA.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 12/10/2010

WOODLAWN COLONIAL APARTMENTS (Continued) **S110275496**

Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

VCP:

Name:	WOODLAWN COLONIAL APARTMENTS
Address:	245-255 WOODLAWN AVENUE
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	60001253
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	4.87
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Irena Edwards
Supervisor:	Manny Alonzo
Division Branch:	Cleanup Cypress
Site Code:	401514
Assembly:	80
Senate:	40
Special Programs Code:	Voluntary Cleanup Program
Status:	No Further Action
Status Date:	06/30/2014
Restricted Use:	NO
Funding:	Responsible Party
Lat/Long:	32.63855 / -117.0969
APN:	567-032-09-00
Past Use:	DRY CLEANING
Potential COC:	30022
Confirmed COC:	30022
Potential Description:	IA, OTH
Alias Name:	567-032-09-00
Alias Type:	APN
Alias Name:	401514
Alias Type:	Project Code (Site Code)
Alias Name:	60001253
Alias Type:	Envirostor ID Number
Alias Name:	60001334
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Letter - Demand
Completed Date:	03/25/2011
Comments:	Reminder letter sent for unpaid past due invoice.

WOODLAWN COLONIAL APARTMENTS (Continued) **S110275496**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	04/28/2011
Comments:	Closeout memo sent to accounting.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Characterization Workplan
Completed Date:	06/03/2010
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Characterization Report
Completed Date:	04/28/2011
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	*Correspondence - Received
Completed Date:	02/07/2011
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement Termination Notification
Completed Date:	07/08/2011
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Standard Voluntary Agreement
Completed Date:	12/17/2009
Comments:	Fully Executed VCA.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	12/10/2010
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

S95 **U S FISH AND WILDLIFE SERVICE** **CPS-SLIC** **S106916013**
North **NONE E ST(FOOT OF)** **CERS** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910**
0.487 mi.
2573 ft. **Site 2 of 2 in cluster S**

Relative:
Higher

Actual:
22 ft.

CPS-SLIC:

Name:	U S FISH AND WILDLIFE SERVICE
Address:	NONE E ST(FOOT OF)
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	10/02/1991
Global Id:	T0608124509
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H26542-001
Latitude:	32.6387129382742
Longitude:	-117.101752167917
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	U S FISH AND WILDLIFE SERVICE
Address:	NONE E ST(FOOT OF)
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	208429
CERS ID:	T0608124509
CERS Description:	Cleanup Program Site

T96 **H STREET AUTO WASH** **LUST** **U001571003**
East **498 BROADWAY** **CPS-SLIC** **N/A**
1/4-1/2 **CHULA VISTA, CA 92010** **HIST UST**
0.494 mi. **Cortese**
2608 ft. **Site 1 of 3 in cluster T** **SAN DIEGO CO LOP**
CERS

Relative:
Higher

Actual:
45 ft.

LUST:

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302590
Global Id:	T0607302590
Latitude:	32.6310651899366
Longitude:	-117.09001038102
Status:	Open - Remediation
Status Date:	04/15/2002
Case Worker:	JW
RB Case Number:	9UT3827
Local Agency:	Not reported

H STREET AUTO WASH (Continued) **U001571003**

File Location: Local Agency
Local Case Number: Not reported
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: Three underground storage tanks were removed on 12/4/98 and soil sampling results indicated a release in both the gas and diesel carbon ranges. Several investigations showed that both soil and groundwater were impacted by gasoline. Soil contamination has been assessed. The leading edge of the groundwater plume has not been defined. A workplan approval letter was issued on 6/23/09 to install three more groundwater monitoring wells down gradient. Since December 2009, we have been trying to locate a Responsible Party to continue with the assessment.

LUST:
Global Id: T0607302590
Contact Type: Regional Board Caseworker
Contact Name: JOE WHEARTY
Organization Name: SAN DIEGO RWQCB (REGION 9)
Address: 2375 Northside Drive Suite 100
City: SAN DIEGO
Email: joe.whearty@waterboards.ca.gov
Phone Number: 6195213357

LUST:
Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 07/12/2012
Action: Notice of Responsibility

Global Id: T0607302590
Action Type: RESPONSE
Date: 08/07/2012
Action: Other Report / Document

Global Id: T0607302590
Action Type: Other
Date: 12/04/1998
Action: Leak Reported

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 07/09/2009
Action: Letter - Notice

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 06/13/2017
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 08/17/2018
Action: Other Report

Global Id: T0607302590
Action Type: ENFORCEMENT

H STREET AUTO WASH (Continued) **U001571003**

Date: 07/05/2018
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 06/24/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 01/28/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 06/20/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 05/18/2010
Action: Letter - Notice

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 06/09/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: RESPONSE
Date: 04/06/2009
Action: Soil and Water Investigation Workplan - Addendum

Global Id: T0607302590
Action Type: RESPONSE
Date: 06/30/2015
Action: Correspondence

Global Id: T0607302590
Action Type: RESPONSE
Date: 10/16/2014
Action: Other Report / Document

Global Id: T0607302590
Action Type: RESPONSE
Date: 07/03/2015
Action: Correspondence

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 05/09/2011
Action: Letter - Notice

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 01/26/2011
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

H STREET AUTO WASH (Continued) **U001571003**

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 04/12/2012
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607302590
Action Type: RESPONSE
Date: 05/15/2015
Action: Other Workplan

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 01/13/2017
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: Other
Date: 12/04/1998
Action: Leak Began

Global Id: T0607302590
Action Type: RESPONSE
Date: 01/12/2016
Action: Correspondence

Global Id: T0607302590
Action Type: RESPONSE
Date: 03/31/2016
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0607302590
Action Type: RESPONSE
Date: 11/16/2016
Action: Correspondence

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 01/10/2011
Action: File review

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 01/27/2017
Action: Verbal Communication

Global Id: T0607302590
Action Type: Other
Date: 12/04/1998
Action: Leak Discovery

Global Id: T0607302590
Action Type: RESPONSE
Date: 12/04/1998
Action: Tank Removal Report / UST Sampling Report

Global Id: T0607302590
Action Type: RESPONSE

H STREET AUTO WASH (Continued) **U001571003**

Date: 03/12/2015
Action: Monitoring Report - Other - Regulator Responded

Global Id: T0607302590
Action Type: RESPONSE
Date: 05/05/2015
Action: Well Installation Workplan - Regulator Responded

Global Id: T0607302590
Action Type: RESPONSE
Date: 03/12/2015
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607302590
Action Type: RESPONSE
Date: 12/15/2015
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 01/29/1999
Action: Notice of Responsibility

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 12/29/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 02/01/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 01/25/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 04/13/2017
Action: Technical Correspondence / Assistance / Other

Global Id: T0607302590
Action Type: RESPONSE
Date: 04/15/2016
Action: Correspondence - Regulator Responded

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 01/02/2013
Action: Referral to Regional Board

Global Id: T0607302590
Action Type: ENFORCEMENT
Date: 07/26/2018
Action: Technical Correspondence / Assistance / Other

H STREET AUTO WASH (Continued) **U001571003**

LUST:

Global Id:	T0607302590
Status:	Open - Case Begin Date
Status Date:	12/04/1998
Global Id:	T0607302590
Status:	Open - Remediation
Status Date:	04/15/2002

CPS-SLIC:

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	06/16/1992
Global Id:	T0608164049
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H05368-002
Latitude:	32.6311346211571
Longitude:	-117.089962319318
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Under Investigation
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	01/21/1988
Global Id:	T0608118503
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H05368-001
Latitude:	32.6311090030704
Longitude:	-117.089844302449
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

H STREET AUTO WASH (Continued) **U001571003**

HIST UST:

Name:	H STREET AUTO WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 92010
File Number:	0002ACFD
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002ACFD.pdf
Region:	STATE
Facility ID:	00000008568
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	DON BEDFORD
Telephone:	6197471398
Owner Name:	C. D. ENTERPRISES
Owner Address:	498 BROADWAY
Owner City,St,Zip:	CHULA VISTA, CA 92010
Total Tanks:	0003
Tank Num:	001
Container Num:	1
Year Installed:	1971
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	1971
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	3
Year Installed:	1971
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

Click here for Geo Tracker PDF:

CORTESE:

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607302590
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	OPEN - REMEDIATION
Status Date:	Not reported

H STREET AUTO WASH (Continued) **U001571003**

Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

SAN DIEGO CO LOP:

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1998-LSAM-H05368-003
Record Status:	Completed
Opened Date:	12/04/1998
Parcel Number:	567-200-39-00
Case Type:	LOP - Local Oversight Program
Historical Name:	H STREET CAR WASH
SWRCB Global ID:	T0607302590
Funding:	S - LOP State Fund
Lead Agency:	RWQCB
Lead Agency Date:	01/23/2013
Census Tract:	125.01
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	SOUTH BAY IRRIGATION LAND
Fire Agency:	CHULA VISTA
Latitude:	32.6311871
Longitude:	-117.0900811
X MapCoord:	6303018.16275341
Y MapCoord:	1810492.85155231

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1986-LSAM-H05368-001
Record Status:	Completed
Opened Date:	08/28/1986
Parcel Number:	567-200-39-00
Case Type:	FIT - Failed Integrity Test
Historical Name:	H ST AUTO WASH
SWRCB Global ID:	T0608118503
Funding:	N - Non-Billable
Lead Agency:	DEH/SAM
Lead Agency Date:	08/28/1986
Census Tract:	125.01
Community:	Chula Vista
Jurisdiction:	CHULA VISTA

H STREET AUTO WASH (Continued) **U001571003**

Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6311871
Longitude:	-117.0900811
X MapCoord:	6303018.163
Y MapCoord:	1810492.852

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1991-LSAM-H05368-002
Record Status:	Completed
Opened Date:	11/12/1991
Parcel Number:	567-200-39-00
Case Type:	FIT - Failed Integrity Test
Historical Name:	H STREET CAR WASH
SWRCB Global ID:	T0608164049
Funding:	N - Non-Billable
Lead Agency:	DEH/SAM
Lead Agency Date:	11/14/1991
Census Tract:	125.01
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6311871
Longitude:	-117.0900811
X MapCoord:	6303018.163
Y MapCoord:	1810492.852

CERS:

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	213954
CERS ID:	T0607302590
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195213374

Name:	OPTIMA CAR WASH
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	213954
CERS ID:	T0608164049

H STREET AUTO WASH (Continued) **U001571003**

CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213374

Name: OPTIMA CAR WASH
Address: 498 BROADWAY
City,State,Zip: CHULA VISTA, CA 91910
Site ID: 213954
CERS ID: T0608118503
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: SEAN MCCLAIN - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213374

T97 **OPTIMA CAR WASH** **SAN DIEGO CO. SAM** **U003789227**
East **498 BROADWAY** **UST** **N/A**
1/4-1/2 **CHULA VISTA, CA 91910** **San Diego Co. HMMD**
0.494 mi. **CERS HAZ WASTE**
2608 ft. **Site 2 of 3 in cluster T** **CERS TANKS**
CERS

Relative:
Higher

Actual:
45 ft.

SAN DIEGO CO. SAM:
Name: OPTIMA CAR WASH
Address: 498 BROADWAY
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H05368-001
Agency: DEH Site Assessment & Mitigation
Funding: **Non Billable**
Facility Type: Failed Integrity Test
Facility Status: Closed Case
Date: 1/21/1988
Date Began: 8/28/1986

Name: OPTIMA CAR WASH
Address: 498 BROADWAY
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H05368-002
Agency: DEH Site Assessment & Mitigation
Funding: **Non Billable**
Facility Type: Failed Integrity Test

OPTIMA CAR WASH (Continued) **U003789227**

Facility Status: Closed Case
Date: 6/16/1992
Date Began: 10/23/1991

Name: OPTIMA CAR WASH
Address: 498 BROADWAY
City,State,Zip: CHULA VISTA, CA 91910
Case Number: H05368-003
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 5/16/2005
Date Began: 12/4/1998

UST:
Name: OPTIMA CAR WASH
Address: 498 BROADWAY
City,State,Zip: CHULA VISTA, CA 91910
Facility ID: H05368
Permitting Agency: SAN DIEGO COUNTY
Latitude: 32.63094
Longitude: -117.08954

HMMD SAN DIEGO:
Name: OPTIMA CAR WASH
Address: 498 BROADWAY
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 105368
Business Type: 6HK28
EPA Id Number: CAL000191911
APN: 567-200-39-00
Last HMMD Inspection: 10/18/2011
Facility Telephone: 619-691-0942
Permit Status: OPEN
Permit Expiration: 01/31/2013
Date Last Updated: 11/02/2012
Facility Owner: HA TA
Facility Mailing Address: 498 BROADWAY
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910-4304
UST Owner: HA TA
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 105368
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: MIDGRADE UNLEADED
Other Information: UNDERGROUND TANK 105368 T005
Material Waste: Material

OPTIMA CAR WASH (Continued) **U003789227**

Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 105368
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 105368 T006
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 105368
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 105368 T004
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 105368
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: GASOLINE CONTAMINATED WATER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 105368
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: GASOLINE DISPENSING FLTRS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 10/19/2007
Violation Code: 6HV3152
Violation: ALL MAINT/MONITOR RECORDS NOT AVAILABLE
Violation Citation: All maintenance/monitoring/calibration/ repair records not available. 25293; 2712 (b)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 10/19/2007
Violation Code: 6HV3193
Violation: NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation: Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity: ACTIVE

OPTIMA CAR WASH (Continued) **U003789227**

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	10/05/2005
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	10/19/2010
Violation Code:	6HV3193
Violation:	NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation:	Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	10/19/2010
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	10/19/2010
Violation Code:	6HV0138
Violation:	NO TSDF SIGNED MANIFEST ONSITE
Violation Citation:	Generator has not maintained the required signed copy of the hazardous waste manifest from the TSD facility on site for review. CCR 66262.40(a)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	10/06/2006
Violation Code:	6HV3105
Violation:	NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation:	Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	10/06/2006
Violation Code:	6HV3267
Violation:	DISP. CONTAINMENT NOT ADEQ. MONITORED
Violation Citation:	Dispenser containment not adequately monitored. 2636(f)(1) or (f)(5)(A)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012

OPTIMA CAR WASH (Continued) **U003789227**

Inspection Date: 10/06/2006
Violation Code: 6HV3267
Violation: DISP. CONTAINMENT NOT ADEQ. MONITORED
Violation Citation: Dispenser containment not adequately monitored. 2636(f)(1) or (f)(5)(A)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 10/06/2006
Violation Code: 6HV3267
Violation: DISP. CONTAINMENT NOT ADEQ. MONITORED
Violation Citation: Dispenser containment not adequately monitored. 2636(f)(1) or (f)(5)(A)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 10/18/2011
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 10/18/2011
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 10/18/2011
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 10/18/2011
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 10/27/2008
Violation Code: 6HV3114

OPTIMA CAR WASH (Continued) **U003789227**

Violation:	2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation:	Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	10/27/2008
Violation Code:	6HV3164
Violation:	MONITOR EQUIP NOT PER MANUF. SPECS
Violation Citation:	All monitoring equipment not installed, calibrated, operated, and/or maintained per manufacturer instructions. 2638(a), 2641(j)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	10/27/2008
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/11/2003
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/11/2003
Violation Code:	6HV0401
Violation:	TRAINING RECORDS UNAVAILABLE
Violation Citation:	Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/11/2003
Violation Code:	6HV3102
Violation:	OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/11/2003
Violation Code:	6HV3106
Violation:	NO OWNER/OPERATOR AGREEMENT

OPTIMA CAR WASH (Continued) **U003789227**

Violation Citation:	Owner/operator agreement not available/complete/submitted to HMD. 25284(a)(3); 2620(b)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/11/2003
Violation Code:	6HV3111
Violation:	CONTIN MONITOR SYSTEM NOT CERT. YRLY
Violation Citation:	Continuous monitoring system not certified annually. 25284.1(a)(4)(C; 2630(d), 2637(b).
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/11/2003
Violation Code:	6HV3113
Violation:	2NDRY CONT TEST NOT SENT TO CUPA
Violation Citation:	Secondary Containment testing not submitted to CUPA within 30 days. 2637(a)(4)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/11/2003
Violation Code:	6HV3151
Violation:	ALL RELEASES NOT REPORTED/RECORDED
Violation Citation:	All releases not recorded and/or reported. 25294, 25295, 2650, 2651, 2652
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/11/2003
Violation Code:	6HV3152
Violation:	ALL MAINT/MONITOR RECORDS NOT AVAILABLE
Violation Citation:	All maintenance/monitoring/calibration/ repair records not available. 25293; 2712 (b)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3102
Violation:	OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3103
Violation:	NO UST PLAN CHECK PERMIT OBTAINED
Violation Citation:	UST repair/modify/closure permit not obtained .68.1004, 68.1005, 68.1009.5
Activity:	ACTIVE

OPTIMA CAR WASH (Continued) **U003789227**

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3105
Violation:	NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation:	Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity:	ACTIVE

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3152
Violation:	ALL MAINT/MONITOR RECORDS NOT AVAILABLE
Violation Citation:	All maintenance/monitoring/calibration/ repair records not available. 25293; 2712 (b)
Activity:	ACTIVE

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3264
Violation:	SPILL CONT. NOT TESTED ANNUALLY
Violation Citation:	Spill containment at fill point not tested annually. 25284.2
Activity:	ACTIVE

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3264

OPTIMA CAR WASH (Continued) **U003789227**

Violation:	SPILL CONT. NOT TESTED ANNUALLY
Violation Citation:	Spill containment at fill point not tested annually. 25284.2
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3264
Violation:	SPILL CONT. NOT TESTED ANNUALLY
Violation Citation:	Spill containment at fill point not tested annually. 25284.2
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3407
Violation:	PIPE INT. TEST DOESN'T DETECT.1 GPH @150
Violation Citation:	DOUBLE WALLED PRESSURIZED PIPING: OPTION 2-Piping integrity test does not detect 0.1-gph leak with ELLD or at 150% pressure 2636(f)(4)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3407
Violation:	PIPE INT. TEST DOESN'T DETECT.1 GPH @150
Violation Citation:	DOUBLE WALLED PRESSURIZED PIPING: OPTION 2-Piping integrity test does not detect 0.1-gph leak with ELLD or at 150% pressure 2636(f)(4)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV3407
Violation:	PIPE INT. TEST DOESN'T DETECT.1 GPH @150
Violation Citation:	DOUBLE WALLED PRESSURIZED PIPING: OPTION 2-Piping integrity test does not detect 0.1-gph leak with ELLD or at 150% pressure 2636(f)(4)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV1006
Violation:	HMBP: INVENTORY INADEQUATE
Violation Citation:	Business Plan inventory does not list all hazardous materials on site in disclosable quantities. HSC 25504(a),25503.5
Activity:	ACTIVE

OPTIMA CAR WASH (Continued) **U003789227**

Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/14/2004
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/22/2009
Violation Code:	6HV3102
Violation:	OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/22/2009
Violation Code:	6HV3105
Violation:	NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation:	Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/22/2009
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/22/2009
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012
Inspection Date:	09/22/2009
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	105368
Update Date:	11/02/2012

OPTIMA CAR WASH (Continued) **U003789227**

Inspection Date: 09/22/2009
Violation Code: 6HV3193
Violation: NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation: Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 09/22/2009
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 09/22/2009
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 105368
Update Date: 11/02/2012
Inspection Date: 09/22/2009
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 105368 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 105368
Tank Type: SINGLE WALL
Additional Id: 1
Capacity Gallons: 10000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: REMOVED
Remove Close Date: 1998-04-12 00:00:00
Year Installed: 1971-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 02
UST Monitor Method: SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANNUALLY

UST Name: UNDERGROUND TANK 105368 T002
Last Update: 2012-11-02 14:17:38

OPTIMA CAR WASH (Continued) **U003789227**

Permit Number:	105368
Tank Type:	SINGLE WALL
Additional Id:	2
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1998-04-12 00:00:00
Year Installed:	1971-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	02
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 105368 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	105368
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1998-04-12 00:00:00
Year Installed:	1971-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	02
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 105368 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	105368
Tank Type:	DOUBLE WALL
Additional Id:	NT2123 REGULAR UNLEADED/RT2911/RT4634
Capacity Gallons:	15000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31B
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ MECHANICAL FLOAT

UST Name:	UNDERGROUND TANK 105368 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	105368
Tank Type:	DOUBLE WALL
Additional Id:	NT2123/RT2911/RT4634
Capacity Gallons:	7500
UST Contents:	MIDGRADE UNLEADED
Other Content Info:	MIDGRADE

OPTIMA CAR WASH (Continued) **U003789227**

Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31B
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ MECHANICAL FLOAT

UST Name:	UNDERGROUND TANK 105368 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	105368
Tank Type:	DOUBLE WALL
Additional Id:	NT2123 SUPER UNLEADED/RT2911/RT4634
Capacity Gallons:	7500
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31B
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ MECHANICAL FLOAT

CERS HAZ WASTE:

Name:	BROADWAY GAS & MARKET
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	100147
CERS ID:	10357954
CERS Description:	Hazardous Waste Generator

CERS TANKS:

Name:	BROADWAY GAS & MARKET
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	100147
CERS ID:	10357954
CERS Description:	Underground Storage Tank

CERS:

Name:	BROADWAY GAS & MARKET
Address:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Site ID:	100147
CERS ID:	10357954
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	100147
Site Name:	BROADWAY GAS & MARKET
Violation Date:	10-14-2015
Citation:	23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter

OPTIMA CAR WASH (Continued) **U003789227**

16, Section(s) 2641(a)
Violation Description: Failure of sensor to be located in the proper position/location.
Violation Notes: Returned to compliance on 10/14/2015. Inspection Sequence ID:5254450;Tank ID:19391;Violation Description:(RD) Failure of sensor to be located in the proper position/location. 23 CCR 2630(d), 2641(a)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 100147
Site Name: BROADWAY GAS & MARKET
Violation Date: 10-09-2014
Citation: 23 CCR 16 2632, 2634, 2636, 2666 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632, 2634, 2636, 2666
Violation Description: Failure of the leak detection equipment to be properly programmed or properly operated.
Violation Notes: Returned to compliance on 10/09/2014.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 100147
Site Name: BROADWAY GAS & MARKET
Violation Date: 10-11-2017
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description: Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements:Monitor at least hourly.Be capable of detecting a release of 3.0 gallons per hour at 10 p.s.i.g. Restrict or shut off the flow of product through the piping when a leak is detected.
Violation Notes: Returned to compliance on 10/11/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 100147
Site Name: BROADWAY GAS & MARKET
Violation Date: 10-09-2018
Citation: 23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)
Violation Description: Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.
Violation Notes: Returned to compliance on 10/09/2018. Inspection Sequence ID:5995807;Tank ID:19391,19392;Violation Description:(TCR 9d) Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly. 23 CCR 2638(a), 2641(j)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS

Site ID: 100147
Site Name: BROADWAY GAS & MARKET
Violation Date: 10-14-2015
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description: Failure to complete and electronically submit a site map with all

OPTIMA CAR WASH (Continued) **U003789227**

	required content.
Violation Notes:	Returned to compliance on 12/07/2015. Inspection Sequence ID:5254450
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	100147
Site Name:	BROADWAY GAS & MARKET
Violation Date:	10-09-2018
Citation:	23 CCR 16 2641(a) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(a)
Violation Description:	Failure of leak detection equipment to be located such that equipment is capable of detecting a leak at the earliest possible opportunity.
Violation Notes:	Returned to compliance on 10/09/2018. Inspection Sequence ID:5995807;Tank ID:19390,19391,19392;Violation Description:(TCR 9d) Failure of leak detection equipment to be located such that equipment is capable of detecting a leak at the earliest possible opportunity. 23 CCR 2630(d), 2641(a)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	100147
Site Name:	BROADWAY GAS & MARKET
Violation Date:	10-21-2013
Citation:	23 CCR 16 2666 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2666
Violation Description:	Failure of the leak detection equipment to be properly programmed or properly operated.
Violation Notes:	Returned to compliance on 10/25/2013.
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS
Site ID:	100147
Site Name:	BROADWAY GAS & MARKET
Violation Date:	10-14-2015
Citation:	23 CCR 16 2715(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(f)
Violation Description:	Failure to comply with one or more of the following: provide training to facility employee(s) responsible for proper operation and maintenance every 12 months and/or train new employee(s) who are responsible for proper operation and maintenance within 30-days of hire and/or to have at least one employee present during operating hours that has been trained in the proper operation and maintenance of the UST system.
Violation Notes:	Returned to compliance on 10/14/2015. Inspection Sequence ID:5254450;Tank ID:19390,19391,19392;Violation Description:Failure to comply with one or more of the following: provide training to facility employee(s) responsible for proper operation and maintenance every 12 months and/or train new employee(s) who are responsible for proper operation and maintenance within 30-days of hire and/or to have at least one employee present during operating hours that has been trained in the proper operation and maintenance of the UST system. 23 CCR 16 2715(c)(6), 2715(f)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST

OPTIMA CAR WASH (Continued) **U003789227**

Violation Source: CERS

Evaluation:

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6256984
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6256984
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:6256984
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-09-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Tank HT205 Inspection ID:5109866
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-09-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Tank HT205 Inspection ID:5109866
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-09-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Tank HT205 Inspection ID:5109866
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

OPTIMA CAR WASH (Continued) **U003789227**

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-09-2018
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5995807
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-09-2018
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5995807
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-09-2018
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5995807
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-11-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5739479
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-11-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5739479
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-11-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5739479
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-13-2016
Violations Found:	No

OPTIMA CAR WASH (Continued) **U003789227**

Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5510141
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-13-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5510141
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-13-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5510141
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-14-2015
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254450
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-14-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254450
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-14-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:5254450
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-21-2013
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Archer Veronica Inspection ID:4086926
Eval Division:	San Diego County Department of Env Health

OPTIMA CAR WASH (Continued) **U003789227**

Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-21-2013
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:4086926
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS

Coordinates:
Site ID: 100147
Facility Name: BROADWAY GAS & MARKET
Env Int Type Code: HWG
Program ID: 10357954
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.631080
Longitude: -117.089560

Affiliation:
Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880

Affiliation Type Desc: Document Preparer
Entity Name: ED GRIFFIN
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer
Entity Name: ROBERT MARCOS
Entity Title: OWNER
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: UST Property Owner Name
Entity Name: RHMV OIL INC
Entity Title: Not reported

OPTIMA CAR WASH (Continued) **U003789227**

Affiliation Address:	498 BROADWAY
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92910
Affiliation Phone:	(619) 729-1290
Affiliation Type Desc:	Operator
Entity Name:	ROBERT MARCOS
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 729-1290
Affiliation Type Desc:	UST Tank Operator
Entity Name:	ROBERT MARCOS
Entity Title:	Not reported
Affiliation Address:	498 Broadway
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 729-1290
Affiliation Type Desc:	UST Tank Owner
Entity Name:	RHMV OIL INC.
Entity Title:	Not reported
Affiliation Address:	498 BROADWAY
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91911-
Affiliation Phone:	(619) 729-1290
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	498 BROADWAY
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910-4304
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	RHMV OIL INC.
Entity Title:	Not reported
Affiliation Address:	498 BROADWAY
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91910
Affiliation Phone:	(619) 729-1290

OPTIMA CAR WASH (Continued) **U003789227**

Affiliation Type Desc:	Property Owner
Entity Name:	RHMV OIL INC.
Entity Title:	Not reported
Affiliation Address:	498 BROADWAY
Affiliation City:	CHULA VISTA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92910
Affiliation Phone:	(619) 691-0942

Affiliation Type Desc:	UST Permit Applicant
Entity Name:	ROBERT MARCOS
Entity Title:	OWNER
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 729-1290

Affiliation Type Desc:	Environmental Contact
Entity Name:	ED GRIFFIN
Entity Title:	Not reported
Affiliation Address:	11365 MARJAY DR.
Affiliation City:	LAKESIDE
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92040
Affiliation Phone:	Not reported

Affiliation Type Desc:	Parent Corporation
Entity Name:	BROADWAY GAS & WASH
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

T98 **H STREET CAR WASH** **LUST** **S103723435**
East **498 BROADWAY** **SWEEPS UST** **N/A**
1/4-1/2 **CHULA VISTA, CA 91911** **HIST CORTESE**
0.494 mi.
2608 ft. **Site 3 of 3 in cluster T**

Relative:
Higher

Actual:
45 ft.

LUST REG 9:

Region:	9
Status:	Preliminary site assessment underway
Case Number:	9UT3827
Local Case:	H05368-003
Substance:	Unleaded Gasoline
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank

H STREET CAR WASH (Continued) **S103723435**

Source: Tank
Cause: Corrosion
Lead Agency: Local Agency
Case Type: Soil only
Date Found: 12/04/1998
Date Stopped: 12/04/1998
Confirm Date: / /
Submit Workplan: Not reported
Prelim Assess: 01/15/1999
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 12/04/1998
Enforce Date: Not reported
Closed Date: Not reported
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 909.12
GW Depth: >16'
Beneficial Use: MUNBU
NPDES Number: Not reported
Priority: 3B
File Dispn: Administratively opened on database, however no file physically exists
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

SWEEPS UST:
Name: H ST AUTO WASH
Address: 498 BROADWAY
City: CHULA VISTA
Status: Active
Comp Number: 5368
Number: 9
Board Of Equalization: 44-022208
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-005368-000001
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: 3

Name: H ST AUTO WASH
Address: 498 BROADWAY
City: CHULA VISTA
Status: Active
Comp Number: 5368
Number: 9
Board Of Equalization: 44-022208
Referral Date: Not reported

H STREET CAR WASH (Continued) **S103723435**

Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-005368-000002
Tank Status:	A
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	OTHER
Number Of Tanks:	Not reported

Name:	H ST AUTO WASH
Address:	498 BROADWAY
City:	CHULA VISTA
Status:	Active
Comp Number:	5368
Number:	9
Board Of Equalization:	44-022208
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-005368-000003
Tank Status:	A
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

HIST CORTESE:

edr_fname:	H STREET CAR WASH
edr_fadd1:	498 BROADWAY
City,State,Zip:	CHULA VISTA, CA 92010
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT3827

99
NNE
1/2-1
0.607 mi.
3203 ft.

E STREET PLAZA SHOPPING CENTER **ENVIROSTOR** **S110653092**
640-692 E STREET **N/A**
CHULA VISTA, CA 91910

Relative: Higher

Actual: 48 ft.

ENVIROSTOR:

Name:	E STREET PLAZA SHOPPING CENTER
Address:	640-692 E STREET
City,State,Zip:	CHULA VISTA, CA 91910
Facility ID:	60001334
Status:	Active
Status Date:	04/21/2015
Site Code:	401482
Site Type:	Tiered Permit
Site Type Detailed:	Tiered Permit

E STREET PLAZA SHOPPING CENTER (Continued) **S110653092**

Acres:	4
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Gregory Shaffer
Supervisor:	Maryam Tasnif-Abbasi
Division Branch:	Cleanup Cypress
Assembly:	80
Senate:	40
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	32.64007
Longitude:	-117.0955
APN:	5670320600, 5670320800
Past Use:	DRY CLEANING
Potential COC:	Tetrachloroethylene (PCE
Confirmed COC:	Tetrachloroethylene (PCE
Potential Description:	IA, OTH, SOIL, SV
Alias Name:	5670320600
Alias Type:	APN
Alias Name:	5670320800
Alias Type:	APN
Alias Name:	T0608166036
Alias Type:	GeoTracker Global ID
Alias Name:	401482
Alias Type:	Project Code (Site Code)
Alias Name:	60001253
Alias Type:	Envirostor ID Number
Alias Name:	60001334
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Monitoring Report
Completed Date:	05/27/2014
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Fieldwork
Completed Date:	04/04/2014
Comments:	Completed
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Work Notice
Completed Date:	02/25/2014
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Monitoring Report
Completed Date:	01/27/2015
Comments:	Not reported

E STREET PLAZA SHOPPING CENTER (Continued) **S110653092**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 02/25/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/28/2015
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 09/23/2014
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 10/28/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 04/06/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 05/10/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/12/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 07/30/2013
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 11/13/2014
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence

E STREET PLAZA SHOPPING CENTER (Continued) **S110653092**

Completed Date: 04/14/2015
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/10/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/19/2016
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 11/29/2018
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/28/2017
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 01/12/2017
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pre-HARP Form
Completed Date: 04/28/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Oversight
Completed Date: 05/05/2020
Comments: GSB staff completed field oversight on 5/5/2020 during sewer line excavations

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 04/18/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 07/16/2015
Comments: Completed

E STREET PLAZA SHOPPING CENTER (Continued) **S110653092**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 01/05/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pilot/Treatability Study Report
Completed Date: 01/05/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 02/25/2016
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 12/16/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 10/07/2007
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 01/26/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 03/16/2017
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 07/28/2016
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 11/06/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pilot Study/Treatability Workplan

E STREET PLAZA SHOPPING CENTER (Continued) **S110653092**

Completed Date: 11/15/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Report
Completed Date: 06/18/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Interim Measures Workplan
Completed Date: 02/10/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: *Correspondence - Received
Completed Date: 02/08/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 02/24/2012
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Workplan
Completed Date: 11/10/2011
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Report
Completed Date: 04/02/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soil Vapor Extraction Monitoring Report
Completed Date: 07/09/2012
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soil Vapor Extraction Monitoring Report
Completed Date: 10/05/2012
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soil Vapor Extraction Monitoring Report
Completed Date: 03/20/2013
Comments: Not reported

E STREET PLAZA SHOPPING CENTER (Continued) **S110653092**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soil Vapor Extraction Monitoring Report
Completed Date: 09/26/2013
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pilot Study/Treatability Workplan
Completed Date: 08/08/2013
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pilot Study/Treatability Workplan
Completed Date: 01/07/2014
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 10/15/2013
Comments: Field work completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 02/04/2019
Comments: Going forward, GSU recommends gauging all groundwater monitoring wells for each monitoring event so that a groundwater contour map can be generated from the data.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 11/19/2018
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Monitoring Report
Completed Date: 06/10/2020
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consent Agreement
Completed Date: 09/21/2009
Comments: Agreement Fully Executed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/29/2010
Comments: Completed

Completed Area Name: PROJECT WIDE

E STREET PLAZA SHOPPING CENTER (Continued) **S110653092**

Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/27/2011
Comments: Completed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 02/09/2011
Comments: Completed

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Interim Measures Implementation Report
Future Due Date: 2021
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

100
NNE
1/2-1
0.912 mi.
4813 ft.

Relative:
Higher

Actual:
55 ft.

CHERNISS TIRE WORLD INC
101 BROADWAY
CHULA VISTA, CA 91910

LUST **S100178768**
SAN DIEGO CO. SAM **N/A**
San Diego Co. HMMD
CERS HAZ WASTE
Cortese
HAZNET
Notify 65
SAN DIEGO CO LOP
CERS
HWTS

LUST:
Name: CHERNISS TIRE WORLD INC
Address: 101 BROADWAY
City,State,Zip: CHULA VISTA, CA 919102207
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607300063
Global Id: T0607300063
Latitude: 32.6446825196167
Longitude: -117.094597220421
Status: Completed - Case Closed
Status Date: 11/23/1988
Case Worker: Not reported
RB Case Number: 9UT1048
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H08975-001
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607300063
Action Type: Other
Date: 09/13/1988
Action: Leak Reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Global Id: T0607300063
Action Type: Other
Date: 09/13/1988
Action: Leak Began

Global Id: T0607300063
Action Type: Other
Date: 09/13/1988
Action: Leak Discovery

Global Id: T0607300063
Action Type: Other
Date: 09/13/1988
Action: Leak Stopped

LUST:
Global Id: T0607300063
Status: Open - Case Begin Date
Status Date: 09/13/1988

Global Id: T0607300063
Status: Completed - Case Closed
Status Date: 11/23/1988

SAN DIEGO CO. SAM:
Name: CHERNISS TIRE WORLD INC
Address: 101 BROADWAY
City,State,Zip: CHULA VISTA, CA 919102207
Case Number: H08975-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 11/23/1988
Date Began: 9/13/1988

HMMD SAN DIEGO:
Name: CHERNISS TIRE WORLD INC
Address: 101 BROADWAY
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: Not reported
Business Type: Not reported
EPA Id Number: CAL000285676
APN: Not reported
Last HMMD Inspection: Not reported
Facility Telephone: 619-427-9121
Permit Status: Permit Renewed
Permit Expiration: Not reported
Date Last Updated: 12/31/2019
Facility Owner: Not reported
Facility Mailing Address: 101 BROADWAY, CHULA VISTA, CA 91910-2207
Facility Mailing City: Not reported
Facility Mailing State: Not reported
Facility Mailing Zip: Not reported
UST Owner: N

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: N
Generate Medical Waste: Not reported

Inspection Violation:
Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-108975
Program Element: Hazardous Materials Release Response Plans
Inspection Type: Routine
Inspection Number: 6286141
Return To Compliance Date: 2019-09-10T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2019-12-31T00:00:00.000
Inspection Date: 2019-09-10T16:40:27.000
Violation Code: 1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508(a)(1)(A), 25508.2, 19 CCR 2654(b)

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-108975
Program Element: Hazardous Materials Release Response Plans
Inspection Type: Routine
Inspection Number: 4091468
Return To Compliance Date: 2015-11-19T00:00:00.000
Nov: No
Violation Classification: CLASS II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2019-12-31T00:00:00.000
Inspection Date: 2015-10-13T14:22:00.000
Violation Code: 1010002 HMBP not submitted to the CUPA in CERS. HSC 25508(a)(1)(A); HSC 25404(e)(4); 27 CCR 15188(a), (d)

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-108975
Program Element: Hazardous Materials Release Response Plans
Inspection Type: Routine
Inspection Number: 5759163
Return To Compliance Date: 2017-10-13T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2019-12-31T00:00:00.000
Inspection Date: 2017-10-13T12:29:00.000
Violation Code: 1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508(a)(1)(A), 25508.2, 19 CCR 2654(b)

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Record ID:	DEH2002-HUPFP-108975
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-108975
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5759163
Return To Compliance Date:	2017-12-05T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2019-12-31T00:00:00.000
Inspection Date:	2017-10-13T12:29:00.000
Violation Code:	1020002 Initial &/or annual employee training not conducted for hazardous materials management &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

UST DTL:

Record ID:	DEH2002-HUPFP-108975
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-108975
Facility Type (Ust Facility):	Not reported
Tank Owner Name:	CHERNISS TIRE WORLD INC
Tankid:	20591
Tank Status:	Removed
Date Ust Permanently Closed:	09/13/1988
Tank Use:	02
Piping System Type:	01
Last Updated:	2019-12-31T02:36:48.000
Tank Capacityin Gallons:	550
Tank Contents:	Not reported
Type Of Tank:	01

Record ID:	DEH2002-HUPFP-108975
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-108975
Facility Type (Ust Facility):	Not reported
Tank Owner Name:	CHERNISS TIRE WORLD INC
Tankid:	20592
Tank Status:	Removed
Date Ust Permanently Closed:	09/13/1988
Tank Use:	04
Piping System Type:	Not reported
Last Updated:	2019-12-31T02:36:48.000
Tank Capacityin Gallons:	550
Tank Contents:	Not reported
Type Of Tank:	01

Record ID:	DEH2002-HUPFP-108975
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-108975
Facility Type (Ust Facility):	Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Tank Owner Name: CHERNISS TIRE WORLD INC
Tankid: 20590
Tank Status: Removed
Date Ust Permanently Closed: 09/13/1988
Tank Use: 01
Piping System Type: 01
Last Updated: 2019-12-31T02:36:48.000
Tank Capacityin Gallons: 1000
Tank Contents: 1A
Type Of Tank: 01

Waste and Materials:
Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0231153
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-12-31T02:36:48.000
Chemical Name: OILS: LUBRICATING, MOTOR
Common Name: OILS: LUBRICATING, MOTOR
Case Number: 8002-05-9

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0231154
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-12-31T02:36:48.000
Chemical Name: Ethylene Glycol
Common Name: Ethylene Glycol
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0201076
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-12-31T02:36:48.000
Chemical Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Common Name: WASTE ANTIFREEZE
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0201078
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-12-31T02:36:48.000
Chemical Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name: AQUEOUS PARTS CLEANER
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0201079
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-12-31T02:36:48.000
Chemical Name: Paper Oil Filters
Common Name: Paper oil filters
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0201077
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-12-31T02:36:48.000
Chemical Name: WASTE 221 WASTE OIL & MIXED OIL
Common Name: Used Oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0159288
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-12-28T02:32:49.000
Chemical Name: OILS: LUBRICATING, MOTOR
Common Name: OILS: LUBRICATING, MOTOR
Case Number: 8002-05-9

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0135170
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-12-28T02:32:49.000
Chemical Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Common Name: WASTE ANTIFREEZE
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0135171
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-12-28T02:32:49.000
Chemical Name: WASTE 221 WASTE OIL & MIXED OIL
Common Name: Used Oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Child Record Id: DEH2017-HWAST-0135172
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-12-28T02:32:49.000
Chemical Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name: AQUEOUS PARTS CLEANER
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0135173
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-12-28T02:32:49.000
Chemical Name: Paper Oil Filters
Common Name: Paper oil filters
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2002-HCHEM-684866
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-03-28T23:06:53.000
Chemical Name: OILS: LUBRICATING, MOTOR
Common Name: Not reported
Case Number: 8002-05-9

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2002-HCHEM-684867
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-03-28T23:06:53.000
Chemical Name: ETHYLENE GLYCOL
Common Name: Not reported
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2002-HWAST-684862
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-03-28T23:06:53.000
Chemical Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name: AQUEOUS PARTS CLEANER
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2002-HWAST-684863
Trade Secret: N

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Hazardous Material Type: Not reported
Last Updated: 2017-03-28T23:06:53.000
Chemical Name: WASTE 888 USED OIL FILTERS
Common Name: USED OIL FILTERS
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2002-HWAST-684864
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-03-28T23:06:53.000
Chemical Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Common Name: WASTE ANTIFREEZE
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2002-HWAST-684865
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-03-28T23:06:53.000
Chemical Name: WASTE 221 WASTE OIL & MIXED OIL
Common Name: ALSO ADVANCED & EFR HLR
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2002-HWAST-684868
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-03-28T23:06:53.000
Chemical Name: WASTE 444 USED BATTERIES
Common Name: USED LEAD ACID BATTERIES/INTERSTATE BATTERY
Case Number: Not reported

Record ID: DEH2002-HUPFP-108975
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0159289
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-12-28T02:32:49.000
Chemical Name: Ethylene Glycol
Common Name: Ethylene Glycol
Case Number: 107-21-1

Name: CHERNISS TIRE WORLD INC
Address: 101 BROADWAY
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 108975
Business Type: 6HK26
EPA Id Number: CAL000285676

CHERNISS TIRE WORLD INC (Continued) **S100178768**

APN:	565-170-32-00
Last HMMD Inspection:	08/22/2012
Facility Telephone:	619-427-9121
Permit Status:	OPEN
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	CHERNISS TIRE WORLD INC
Facility Mailing Address:	101 BROADWAY
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910-2207
UST Owner:	MCMILLIN DEVELOPMENT INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	107-21-1
Name:	ETHYLENE GLYCOL
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	CHRONIC

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	8002-05-9
Name:	OILS: LUBRICATING, MOTOR
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	AQUEOUS PARTS CLEANER
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 221 WASTE OIL & MIXED OIL
Other Information:	ALSO ADVANCED & EFR HLR
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	108975
Update Date:	11/02/2012

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Case Number:	Not reported
Name:	WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information:	WASTE ANTIFREEZE
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 444 USED BATTERIES
Other Information:	USED LEAD ACID BATTERIES/INTERSTATE BATTERY
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 888 USED OIL FILTERS
Other Information:	USED OIL FILTERS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Violations Active Permits:

Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector’s review. 25505(e)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV1018
Violation:	INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation:	Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV0136

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Violation:	NO DISPOSAL RECORDS: BATTERIES
Violation Citation:	Generator has not maintained onsite documentation for lead-acid battery disposal. CCR 66266.81(a)(4)(B)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	02/21/2006
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	02/21/2006
Violation Code:	6HV0401
Violation:	TRAINING RECORDS UNAVAILABLE
Violation Citation:	Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	11/22/2010
Violation Code:	6HV0132
Violation:	EPA ID NUMBER NOT OBTAINED/MAINTAINED
Violation Citation:	Generator of hazardous waste has not obtained/maintained an EPA identification number. CCR 66262.12(a)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	11/22/2010
Violation Code:	6HV0226
Violation:	HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation:	Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	11/22/2010
Violation Code:	6HV0228
Violation:	CONTAINER NOT KEPT CLOSED
Violation Citation:	Failed to keep container closed. CFR 265.173

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Activity: ACTIVE

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 03/08/2004
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 03/08/2004
Violation Code: 6HV0204
Violation: WASTE CONTAINER:IMPROPER MGMT
Violation Citation: Hazardous waste storage container is not handled or stored in a manner which will prevent leaks or rupture. CCR 66265.173
Activity: ACTIVE

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 03/08/2004
Violation Code: 6HV0401
Violation: TRAINING RECORDS UNAVAILABLE
Violation Citation: Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 108975 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 108975
Tank Type: SINGLE WALL
Additional Id: 1
Capacity Gallons: 1000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: 1988-09-13 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: PRESSURE
Monitor Code: 10
UST Monitor Method: SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name: UNDERGROUND TANK 108975 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 108975
Tank Type: SINGLE WALL
Additional Id: 550
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: MOTOR OIL

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Reg Status:	REMOVED
Remove Close Date:	1988-09-13 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	PRESSURE
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name:	UNDERGROUND TANK 108975 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	108975
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1988-09-13 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

Name:	CHERNISS TIRE WORLD INC
Address:	101 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	108975
Business Type:	6HK26
EPA Id Number:	CAL000285676
APN:	565-170-32-00
Last HMMD Inspection:	08/22/2012
Facility Telephone:	619-427-9121
Permit Status:	OPEN
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	CHERNISS TIRE WORLD INC
Facility Mailing Address:	101 BROADWAY
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910-2207
UST Owner:	MCMILLIN DEVELOPMENT INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	107-21-1
Name:	ETHYLENE GLYCOL
Other Information:	Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	CHRONIC
Permit Number:	108975
Update Date:	11/02/2012
Case Number:	8002-05-9
Name:	OILS: LUBRICATING, MOTOR
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	AQUEOUS PARTS CLEANER
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 221 WASTE OIL & MIXED OIL
Other Information:	ALSO ADVANCED & EFR HLR
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information:	WASTE ANTIFREEZE
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 444 USED BATTERIES
Other Information:	USED LEAD ACID BATTERIES/INTERSTATE BATTERY
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 888 USED OIL FILTERS
Other Information:	USED OIL FILTERS
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Violations Active Permits:

Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV1013
Violation:	HMBP NOT AVAILABLE FOR REVIEW
Violation Citation:	Copy of HMBP not onsite for inspector's review. 25505(e)
Activity:	ACTIVE

Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV1018
Violation:	INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation:	Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity:	ACTIVE

Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity:	ACTIVE

Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV0136
Violation:	NO DISPOSAL RECORDS: BATTERIES
Violation Citation:	Generator has not maintained onsite documentation for lead-acid battery disposal. CCR 66266.81(a)(4)(B)
Activity:	ACTIVE

Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE

Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	02/21/2006
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE

Permit Number:	108975

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Update Date:	11/02/2012
Inspection Date:	02/21/2006
Violation Code:	6HV0401
Violation:	TRAINING RECORDS UNAVAILABLE
Violation Citation:	Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	11/22/2010
Violation Code:	6HV0132
Violation:	EPA ID NUMBER NOT OBTAINED/MAINTAINED
Violation Citation:	Generator of hazardous waste has not obtained/maintained an EPA identification number. CCR 66262.12(a)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	11/22/2010
Violation Code:	6HV0226
Violation:	HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation:	Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	11/22/2010
Violation Code:	6HV0228
Violation:	CONTAINER NOT KEPT CLOSED
Violation Citation:	Failed to keep container closed. CFR 265.173
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	03/08/2004
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	03/08/2004
Violation Code:	6HV0204
Violation:	WASTE CONTAINER:IMPROPER MGMT
Violation Citation:	Hazardous waste storage container is not handled or stored in a manner which will prevent leaks or rupture. CCR 66265.173
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	03/08/2004
Violation Code:	6HV0401

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Violation: TRAINING RECORDS UNAVAILABLE
Violation Citation: Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 108975 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 108975
Tank Type: SINGLE WALL
Additional Id: 1
Capacity Gallons: 1000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: 1988-09-13 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: PRESSURE
Monitor Code: 10
UST Monitor Method: SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name: UNDERGROUND TANK 108975 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 108975
Tank Type: SINGLE WALL
Additional Id: 550
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: MOTOR OIL
Reg Status: REMOVED
Remove Close Date: 1988-09-13 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: PRESSURE
Monitor Code: 10
UST Monitor Method: SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name: UNDERGROUND TANK 108975 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 108975
Tank Type: SINGLE WALL
Additional Id: 3
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1988-09-13 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 10
UST Monitor Method: SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Name:	CHERNISS TIRE WORLD INC
Address:	101 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	108975
Business Type:	6HK26
EPA Id Number:	CAL000285676
APN:	565-170-32-00
Last HMMD Inspection:	08/22/2012
Facility Telephone:	619-427-9121
Permit Status:	OPEN
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	CHERNISS TIRE WORLD INC
Facility Mailing Address:	101 BROADWAY
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910-2207
UST Owner:	MCMILLIN DEVELOPMENT INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	107-21-1
Name:	ETHYLENE GLYCOL
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	CHRONIC

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	8002-05-9
Name:	OILS: LUBRICATING, MOTOR
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	AQUEOUS PARTS CLEANER
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	108975
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 221 WASTE OIL & MIXED OIL
Other Information:	ALSO ADVANCED & EFR HLR

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 108975
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: WASTE ANTIFREEZE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 108975
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: USED LEAD ACID BATTERIES/INTERSTATE BATTERY
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 108975
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 10/18/2007
Violation Code: 6HV1013
Violation: HMBP NOT AVAILABLE FOR REVIEW
Violation Citation: Copy of HMBP not onsite for inspector’s review. 25505(e)
Activity: ACTIVE

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 10/18/2007
Violation Code: 6HV1018
Violation: INVENTORY INCOMPLETE/NOT AMENDED
Violation Citation: Inventory not amended for 100% increase of hazardous material onsite or inventory is incomplete. 25509, 25510
Activity: ACTIVE

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 10/18/2007
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV0136
Violation:	NO DISPOSAL RECORDS: BATTERIES
Violation Citation:	Generator has not maintained onsite documentation for lead-acid battery disposal. CCR 66266.81(a)(4)(B)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	10/18/2007
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	02/21/2006
Violation Code:	6HV0202
Violation:	WASTE CONTAINER W/O LABELS
Violation Citation:	Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	02/21/2006
Violation Code:	6HV0401
Violation:	TRAINING RECORDS UNAVAILABLE
Violation Citation:	Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	11/22/2010
Violation Code:	6HV0132
Violation:	EPA ID NUMBER NOT OBTAINED/MAINTAINED
Violation Citation:	Generator of hazardous waste has not obtained/maintained an EPA identification number. CCR 66262.12(a)
Activity:	ACTIVE
Permit Number:	108975
Update Date:	11/02/2012
Inspection Date:	11/22/2010
Violation Code:	6HV0226
Violation:	HW NOT ACCUMULATED IN TANK/CONTAINER
Violation Citation:	Did not accumulate waste in container or tank. 66262.34 (d)(2)
Activity:	ACTIVE

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 11/22/2010
Violation Code: 6HV0228
Violation: CONTAINER NOT KEPT CLOSED
Violation Citation: Failed to keep container closed. CFR 265.173
Activity: ACTIVE

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 03/08/2004
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 03/08/2004
Violation Code: 6HV0204
Violation: WASTE CONTAINER:IMPROPER MGMT
Violation Citation: Hazardous waste storage container is not handled or stored in a manner which will prevent leaks or rupture. CCR 66265.173
Activity: ACTIVE

Permit Number: 108975
Update Date: 11/02/2012
Inspection Date: 03/08/2004
Violation Code: 6HV0401
Violation: TRAINING RECORDS UNAVAILABLE
Violation Citation: Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 108975 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 108975
Tank Type: SINGLE WALL
Additional Id: 1
Capacity Gallons: 1000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: 1988-09-13 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: PRESSURE
Monitor Code: 10
UST Monitor Method: SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name: UNDERGROUND TANK 108975 T002
Last Update: 2012-11-02 14:17:38

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Permit Number:	108975
Tank Type:	SINGLE WALL
Additional Id:	550
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	MOTOR OIL
Reg Status:	REMOVED
Remove Close Date:	1988-09-13 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	PRESSURE
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name:	UNDERGROUND TANK 108975 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	108975
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1988-09-13 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

CERS HAZ WASTE:

Name:	CHERNISS TIRE WORLD INC
Address:	101 BROADWAY
City,State,Zip:	CHULA VISTA, CA 919102207
Site ID:	18165
CERS ID:	10357918
CERS Description:	Hazardous Waste Generator

CORTESE:

Name:	CHERNISS TIRE WORLD INC
Address:	101 BROADWAY
City,State,Zip:	CHULA VISTA, CA 919102207
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607300063
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HAZNET:

Name:	CHERNISS TIRE WORLD INC
Address:	101 BROADWAY
Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 919100000
Contact:	RANDY CHERNISS
Telephone:	6194279121
Mailing Name:	Not reported
Mailing Address:	101 BROADWAY
Year:	2019
Gepaid:	CAL000285676
TSD EPA ID:	AZR000515924
CA Waste Code:	352 - Other organic solids
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.17500
Year:	2019
Gepaid:	CAL000285676
TSD EPA ID:	AZR000521146
CA Waste Code:	352 - Other organic solids
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.17500
Year:	2017
Gepaid:	CAL000285676
TSD EPA ID:	AZR000515924
CA Waste Code:	352 - Other organic solids
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.175

Additional Info:

Year:	2017
Gen EPA ID:	CAL000285676
Shipment Date:	20171227
Creation Date:	10/16/2018 18:31:07
Receipt Date:	20180103
Manifest ID:	017985563JJK
Trans EPA ID:	CAR000244277
Trans Name:	MAMMOTH ENVIRONMENTAL LLC

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZR000515924
Trans Name:	YUMA YES LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.175
Waste Quantity:	350
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20170116
Creation Date:	5/9/2018 18:31:32
Receipt Date:	20170124
Manifest ID:	016216045JJK
Trans EPA ID:	CAR000244277
Trans Name:	MAMMOTH ENVIRONMENTAL LLC
Trans 2 EPA ID:	CAD028277036
Trans 2 Name:	ASBURY ENVIRONMENTAL SERVICES
TSDF EPA ID:	AZR000515924
Trans Name:	YUMA YES LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.175
Waste Quantity:	350
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

NOTIFY 65:

Name:	C. M. AUTO PARTS
Address:	101 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910-2207
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

SAN DIEGO CO LOP:

Name:	CHERNISS TIRE WORLD INC
Address:	101 BROADWAY
City,State,Zip:	CHULA VISTA, CA 91910
Record ID:	DEH1988-LSAM-H08975-001
Record Status:	Completed
Opened Date:	09/13/1988
Parcel Number:	565-170-32-00
Case Type:	LOP - Local Oversight Program
Historical Name:	CM AUTO PARTS
SWRCB Global ID:	T0607300063
Funding:	S - LOP State Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	09/13/1988
Census Tract:	124.02
Community:	Chula Vista
Jurisdiction:	CHULA VISTA
Watershed Basin Number:	909.12
Water Purveyor:	CHULA VISTA
Fire Agency:	CHULA VISTA
Latitude:	32.6445728
Longitude:	-117.0942181
X MapCoord:	6301783.525
Y MapCoord:	1815373.712

CERS:

Name:	CHERNISS TIRE WORLD INC
Address:	101 BROADWAY
City,State,Zip:	CHULA VISTA, CA 919102207
Site ID:	18165
CERS ID:	10357918
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	18165
Site Name:	CHERNISS TIRE WORLD INC
Violation Date:	10-13-2015
Citation:	HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Description:	Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes:	Returned to compliance on 11/19/2015.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	18165
Site Name:	CHERNISS TIRE WORLD INC
Violation Date:	10-13-2017
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Returned to compliance on 12/05/2017. Received fax on 12/5/17 of

CHERNISS TIRE WORLD INC (Continued) **S100178768**

training sign-in sheet
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 18165
Site Name: CHERNISS TIRE WORLD INC
Violation Date: 09-10-2019
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes: Returned to compliance on 09/10/2019. Inspection Sequence ID:6286141
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 18165
Site Name: CHERNISS TIRE WORLD INC
Violation Date: 10-13-2017
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes: Returned to compliance on 10/13/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-10-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6286141
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-10-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6286141
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Thai Darren Inspection ID:4091468
Eval Division: San Diego County Department of Env Health
Eval Program: HW

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Thai Darren Inspection ID:4091468
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5759163
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5759163
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Coordinates:
Site ID: 18165
Facility Name: CHERNISS TIRE WORLD INC
Env Int Type Code: HWG
Program ID: 10357918
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.644640
Longitude: -117.094740

Affiliation:
Affiliation Type Desc: Legal Owner
Entity Name: Cherniss Tire World Inc.
Entity Title: Not reported
Affiliation Address: 101 BROADWAY
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 427-9121

Affiliation Type Desc: Parent Corporation
Entity Name: CHERNISS TIRE WORLD INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Environmental Contact
Entity Name:	Randy Cherniss
Entity Title:	Not reported
Affiliation Address:	101 Broadway
Affiliation City:	Chula Vista
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91910
Affiliation Phone:	Not reported
Affiliation Type Desc:	Operator
Entity Name:	CHERNISS TIRE WORLD INC
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 427-9121
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880
Affiliation Type Desc:	Document Preparer
Entity Name:	Randy Cherniss
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	Randy Cherniss
Entity Title:	Manager
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Affiliation Address: 101 BROADWAY
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91910-2207
Affiliation Phone: Not reported

Name: CHERNISS TIRE WORLD INC
Address: 101 BROADWAY
City,State,Zip: CHULA VISTA, CA 919102207
Site ID: 18165
CERS ID: T0607300063
CERS Description: Leaking Underground Storage Tank Cleanup Site

Violations:

Site ID: 18165
Site Name: CHERNISS TIRE WORLD INC
Violation Date: 10-13-2015
Citation: HSC 6.95 25508(d) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(d)
Violation Description: Failure to complete and/or electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes: Returned to compliance on 11/19/2015.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 18165
Site Name: CHERNISS TIRE WORLD INC
Violation Date: 10-13-2017
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 12/05/2017. Received fax on 12/5/17 of training sign-in sheet
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 18165
Site Name: CHERNISS TIRE WORLD INC
Violation Date: 09-10-2019
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes: Returned to compliance on 09/10/2019. Inspection Sequence ID:6286141
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Site ID: 18165

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Site Name: CHERNISS TIRE WORLD INC
Violation Date: 10-13-2017
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes: Returned to compliance on 10/13/2017.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-10-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6286141
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-10-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Farhang Farnaz Inspection ID:6286141
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Thai Darren Inspection ID:4091468
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Thai Darren Inspection ID:4091468
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5759163
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:5759163
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS

Coordinates:
Site ID: 18165
Facility Name: CHERNISS TIRE WORLD INC
Env Int Type Code: HWG
Program ID: 10357918
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 32.644640
Longitude: -117.094740

Affiliation:
Affiliation Type Desc: Legal Owner
Entity Name: Cherniss Tire World Inc.
Entity Title: Not reported
Affiliation Address: 101 BROADWAY
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91910
Affiliation Phone: (619) 427-9121

Affiliation Type Desc: Parent Corporation
Entity Name: CHERNISS TIRE WORLD INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Environmental Contact
Entity Name: Randy Cherniss
Entity Title: Not reported
Affiliation Address: 101 Broadway
Affiliation City: Chula Vista
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91910
Affiliation Phone: Not reported

Affiliation Type Desc: Operator
Entity Name: CHERNISS TIRE WORLD INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 427-9121

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880

Affiliation Type Desc: Document Preparer
Entity Name: Randy Cherniss
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Identification Signer
Entity Name: Randy Cherniss
Entity Title: Manager
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 101 BROADWAY
Affiliation City: CHULA VISTA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91910-2207
Affiliation Phone: Not reported

HWTS:
Name: CHERNISS TIRE WORLD INC
Address: 101 BROADWAY
Address 2: Not reported
City,State,Zip: CHULA VISTA, CA 91910
EPA ID: CAL000285676
Inactive Date: Not reported
Create Date: 08/17/2004
Last Act Date: 07/03/2020
Mailing Name: Not reported
Mailing Address: 101 BROADWAY
Mailing Address 2: Not reported

CHERNISS TIRE WORLD INC (Continued) **S100178768**

Mailing City,State,Zip:	CHULA VISTA, CA 919100000
Owner Name:	CHERNISS TIRE WORLD INC.
Owner Address:	101 BROADWAY
Owner Address 2:	Not reported
Owner City,State,Zip:	CHULA VISTA, CA 919100000
Contact Name:	RANDY CHERNISS
Contact Address:	101 BROADWAY
Contact Address 2:	Not reported
City,State,Zip:	CHULA VISTA, CA 91910

NAICS:

EPA ID:	CAL000285676
Create Date:	2004-08-17 10:42:44.633
NAICS Code:	45299
NAICS Description:	All Other General Merchandise Stores
Issued EPA ID Date:	2004-08-17 10:42:44.60000
Inactive Date:	Not reported
Facility Name:	CHERNISS TIRE WORLD INC
Facility Address:	101 BROADWAY
Facility Address 2:	Not reported
Facility City:	CHULA VISTA
Facility County:	Not reported
Facility State:	CA
Facility Zip:	91910

---

101 SE 1/2-1 0.922 mi. 4870 ft.

CHULA VISTA LEARNING COMMUNITY CHARTER **ENVIROSTOR SCH** **S107736129 N/A**
821/824 BROADWAY/562 NORTH K STREET
CHULA VISTA, CA 91911

Relative: Higher

Actual: 52 ft.

ENVIROSTOR:

Name:	CHULA VISTA LEARNING COMMUNITY CHARTER
Address:	821/824 BROADWAY/562 NORTH K STREET
City,State,Zip:	CHULA VISTA, CA 91911
Facility ID:	37880001
Status:	No Further Action
Status Date:	03/29/2001
Site Code:	404047
Site Type:	School Investigation
Site Type Detailed:	School
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Not reported
Supervisor:	Mark Malinowski
Division Branch:	Southern California Schools & Brownfields Outreach
Assembly:	80
Senate:	40
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	School District
Latitude:	32.62055
Longitude:	-117.0852
APN:	NONE SPECIFIED

CHULA VISTA LEARNING COMMUNITY CHARTER (Continued) **S107736129**

Past Use: RESIDENTIAL AREA
Potential COC: Arsenic DDD DDE DDT Lead
Confirmed COC: NONE SPECIFIED
Potential Description: SOIL
Alias Name: CHULA VISTA ELEM. SD-BROADWAY & K ELEM.
Alias Type: Alternate Name
Alias Name: CHULA VISTA ELEMENTARY SCHOOL DISTRICT
Alias Type: Alternate Name
Alias Name: CHULA VISTA LEARNING COMM. CHTR/VCA
Alias Type: Alternate Name
Alias Name: CHULA VISTA LEARNING SCHOOL
Alias Type: Alternate Name
Alias Name: 400804
Alias Type: Project Code (Site Code)
Alias Name: 404047
Alias Type: Project Code (Site Code)
Alias Name: 37880001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 03/29/2001
Comments: DTSC approved the PEA with a no further action determination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 11/23/1999
Comments: DTSC approved the Phase I with a PEA requied determination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 03/16/2000
Comments: DTSC entered into an EOA (Docket Number HSA-A 99/00-085)

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/22/2000
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/19/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 12/06/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

CHULA VISTA LEARNING COMMUNITY CHARTER (Continued) **S107736129**

Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	11/01/2001
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

SCH:

Name:	CHULA VISTA LEARNING COMMUNITY CHARTER
Address:	821/824 BROADWAY/562 NORTH K STREET
City,State,Zip:	CHULA VISTA, CA 91911
Facility ID:	37880001
Site Type:	School Investigation
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	Not reported
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Not reported
Supervisor:	Mark Malinowski
Division Branch:	Southern California Schools & Brownfields Outreach
Site Code:	404047
Assembly:	80
Senate:	40
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	03/29/2001
Restricted Use:	NO
Funding:	School District
Latitude:	32.62055
Longitude:	-117.0852
APN:	NONE SPECIFIED
Past Use:	RESIDENTIAL AREA
Potential COC:	Arsenic, DDD, DDE, DDT, Lead
Confirmed COC:	NONE SPECIFIED
Potential Description:	SOIL
Alias Name:	CHULA VISTA ELEM. SD-BROADWAY & K ELEM.
Alias Type:	Alternate Name
Alias Name:	CHULA VISTA ELEMENTARY SCHOOL DISTRICT
Alias Type:	Alternate Name
Alias Name:	CHULA VISTA LEARNING COMM. CHTR/VCA
Alias Type:	Alternate Name
Alias Name:	CHULA VISTA LEARNING SCHOOL
Alias Type:	Alternate Name
Alias Name:	400804
Alias Type:	Project Code (Site Code)
Alias Name:	404047

CHULA VISTA LEARNING COMMUNITY CHARTER (Continued) **S107736129**

Alias Type: Project Code (Site Code)
Alias Name: 37880001
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 03/29/2001
Comments: DTSC approved the PEA with a no further action determination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 11/23/1999
Comments: DTSC approved the Phase I with a PEA requied determination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 03/16/2000
Comments: DTSC entered into an EOA (Docket Number HSA-A 99/00-085)

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 03/22/2000
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/19/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 12/06/1999
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 11/01/2001
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

Count: 13 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
CHULA VISTA	S123406599	GOODRICH CORP. DBA ROHR INC	H (FOOT OF) ST	91910	San Diego Co. HMMD
CHULA VISTA	S109118195	BAY BLVD PROJECTS	BAY BL	91911	SAN DIEGO CO. SAM
CHULA VISTA	S108406977	CAPE COD BLUES PROPERTY	BROADWAY	91911	SAN DIEGO CO. SAM
CHULA VISTA	S114732655	SHINOHARA I	4705 OTAY VALLEY RD, EAST OF 8		SWF/LF, RGA LF
CHULA VISTA	S106062456	U S FISH AND WILDLIFE SERVICE	SAINT FOOT OF	91910	San Diego Co. HMMD
CHULA VISTA	S122356454	CHULA VISTA BAYFRONT MASTER PLAN D	SAN DIEGO BAY	91911	CPS-SLIC
CHULA VISTA	S108407279	U S FISH AND WILDLIFE SERVICE	E ST(FOOT OF)	91910	SAN DIEGO CO. SAM
CHULA VISTA	S105155601	GUNPOWDER POINT (PARADISE MARSH)	SWEETWATER RIVER CHANNEL, W OF		SWF/LF
NATIONAL CITY	S105155614	N STREET LF	SW CORNER OF 26TH ST & N STREE		SWF/LF
NATIONAL CITY	S106063499	SAN DIEGO UNIFIED PORT DIST	FOOT OF 24TH ST	91950	San Diego Co. HMMD
NATIONAL CITY	S125951368	IN-N-OUT BURGER #70	500 MILES OF CARS WAY	91950	San Diego Co. HMMD
NATIONAL CITY	S106893851	BNSF CAR TRANSFER LOT	SEC OF 24TH AND TIDELANDS AVE.	91950	ENVIROSTOR
NATIONAL CITY	S123406941	LEX-TEK	2704 TRANSPORTATION AVE #G & H	91950	San Diego Co. HMMD

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 04/03/2019
Date Data Arrived at EDR: 04/05/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/23/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/06/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/11/2020
Number of Days to Update: 82

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/18/2020
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/18/2020
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/15/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 7

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

State- and tribal - equivalent NPL

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 07/27/2020
Date Data Arrived at EDR: 07/27/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 73

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 10/26/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 07/27/2020
Date Data Arrived at EDR: 07/27/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 73

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 10/26/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 05/11/2020
Date Data Arrived at EDR: 05/12/2020
Date Made Active in Reports: 07/27/2020
Number of Days to Update: 76

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 11/10/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

LUST REG 6L: Leaking Underground Storage Tank Case Listing
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks
California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

LUST REG 4: Underground Storage Tank Leak List
Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 7: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 1: Active Toxic Site Investigation
Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List
Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

LUST REG 9: Leaking Underground Storage Tank Report
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

LUST: Leaking Underground Fuel Tank Report (GEOTRACKER)

Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

LUST REG 3: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST REG 5: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/29/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/26/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 78
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/15/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

CPS-SLIC: Statewide SLIC Cases (GEOTRACKER)
Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36

Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11

Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 07/21/2020
Date Data Arrived at EDR: 09/03/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 83

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

UST CLOSURE: Proposed Closure of Underground Storage Tank (UST) Cases
UST cases that are being considered for closure by either the State Water Resources Control Board or the Executive Director have been posted for a 60-day public comment period. UST Case Closures being proposed for consideration by the State Water Resources Control Board. These are primarily UST cases that meet closure criteria under the decisional framework in State Water Board Resolution No. 92-49 and other Board orders. UST Case Closures proposed for consideration by the Executive Director pursuant to State Water Board Resolution No. 2012-0061. These are cases that meet the criteria of the Low-Threat UST Case Closure Policy. UST Case Closure Review Denials and Approved Orders.

Date of Government Version: 09/03/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/03/2020
Number of Days to Update: 86
Source: State Water Resources Control Board
Telephone: 916-327-7844
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

UST: Active UST Facilities
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Semi-Annually

MILITARY UST SITES: Military UST Sites (GEOTRACKER)
Military ust sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

AST: Aboveground Petroleum Storage Tank Facilities
A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 07/06/2016
Date Data Arrived at EDR: 07/12/2016
Date Made Active in Reports: 09/19/2016
Number of Days to Update: 69
Source: California Environmental Protection Agency
Telephone: 916-327-5092
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/03/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/29/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/26/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 78

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 07/27/2020
Date Data Arrived at EDR: 07/27/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 73

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 10/26/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Considered Brownfieds Sites Listing
A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 09/21/2020
Date Data Arrived at EDR: 09/22/2020
Date Made Active in Reports: 12/11/2020
Number of Days to Update: 80

Source: State Water Resources Control Board
Telephone: 916-323-7905
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/14/2020
Date Data Arrived at EDR: 09/15/2020
Date Made Active in Reports: 12/10/2020
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 12/11/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: Waste Management Unit Database
Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 10/20/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: No Update Planned

SWRCY: Recycler Database
A listing of recycling facilities in California.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing
A listing of registered waste tire haulers.

Date of Government Version: 05/28/2020
Date Data Arrived at EDR: 05/29/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 75

Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 10/20/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land
A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 10/30/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 03/18/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 07/27/2020
Date Data Arrived at EDR: 07/27/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 73

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 10/26/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 06/30/2019
Date Data Arrived at EDR: 05/28/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

CERS HAZ WASTE: CERS HAZ WASTE

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80

Source: CalEPA
Telephone: 916-323-2514
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 03/18/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

A listing of PFAS contaminated sites included in the GeoTracker database.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

UST MENDOCINO: Mendocino County UST Database

A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 05/20/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/06/2020
Number of Days to Update: 78

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Annually

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SAN FRANCISCO AST: Aboveground Storage Tank Site Listing
Aboveground storage tank sites

Date of Government Version: 08/03/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/22/2020
Number of Days to Update: 78

Source: San Francisco County Department of Public Health
Telephone: 415-252-3896
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

CERS TANKS: California Environmental Reporting System (CERS) Tanks
List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Quarterly

CA FID UST: Facility Inventory Database
The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Environmental Liens Listing
A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 08/26/2020
Date Data Arrived at EDR: 08/28/2020
Date Made Active in Reports: 11/17/2020
Number of Days to Update: 81

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Semi-Annually

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 81

Source: DTSC and SWRCB
Telephone: 916-323-3400
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/20/2020
Date Data Arrived at EDR: 09/22/2020
Date Made Active in Reports: 12/14/2020
Number of Days to Update: 83

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 09/30/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80

Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Semi-Annually

LDS: Land Disposal Sites Listing (GEOTRACKER)

Land Disposal sites (Landfills) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing (GEOTRACKER)

Military sites (consisting of: Military UST sites; Military Privatized sites; and Military Cleanup sites [formerly known as DoD non UST]) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 08/05/2020
Date Data Arrived at EDR: 08/13/2020
Date Made Active in Reports: 10/21/2020
Number of Days to Update: 69

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/07/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63
Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/21/2020
Date Data Arrived at EDR: 09/22/2020
Date Made Active in Reports: 12/14/2020
Number of Days to Update: 83
Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88
Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 11/02/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73
Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 11/06/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85
Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 07/24/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 10/21/2020
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 10/14/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 04/27/2020
Date Data Arrived at EDR: 05/06/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 34
Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

PADS: PCB Activity Database System
PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/09/2019
Date Data Arrived at EDR: 10/11/2019
Date Made Active in Reports: 12/20/2019
Number of Days to Update: 70
Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System
The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/05/2020
Date Data Arrived at EDR: 08/10/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 59
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 10/12/2020
Next Scheduled EDR Contact: 01/31/2021
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 01/15/2020
Number of Days to Update: 42
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 11/30/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/06/2021
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 10/27/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2020
Date Data Arrived at EDR: 10/08/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 88

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 151

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 12/23/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 11/06/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/20/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 12/02/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 09/10/2020
Date Data Arrived at EDR: 09/15/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 66

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 11/24/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/04/2020
Date Data Arrived at EDR: 08/25/2020
Date Made Active in Reports: 11/18/2020
Number of Days to Update: 85

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/16/2020
Date Data Arrived at EDR: 09/17/2020
Date Made Active in Reports: 12/10/2020
Number of Days to Update: 84

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 12/10/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 09/04/2020
Date Data Arrived at EDR: 09/15/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 66

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 10/03/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 90

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites
A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 77
Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 10/08/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing
A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71
Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/17/2020
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 10/21/2020
Number of Days to Update: 65
Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Quarterly

CA BOND EXP. PLAN: Bond Expenditure Plan
Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6
Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/04/2020
Number of Days to Update: 74
Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

CUPA LIVERMORE-PLEASANTON: CUPA Facility Listing
list of facilities associated with the various CUPA programs in Livermore-Pleasanton

Date of Government Version: 05/01/2019
Date Data Arrived at EDR: 05/14/2019
Date Made Active in Reports: 07/17/2019
Number of Days to Update: 64
Source: Livermore-Pleasanton Fire Department
Telephone: 925-454-2361
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

DRYCLEAN AVAQMD: Antelope Valley Air Quality Management District Drycleaner Listing
A listing of dry cleaners in the Antelope Valley Air Quality Management District.

Date of Government Version: 08/25/2020
Date Data Arrived at EDR: 08/26/2020
Date Made Active in Reports: 11/13/2020
Number of Days to Update: 79

Source: Antelope Valley Air Quality Management District
Telephone: 661-723-8070
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

DRYCLEAN SOUTH COAST: South Coast Air Quality Management District Drycleaner Listing
A listing of dry cleaners in the South Coast Air Quality Management District

Date of Government Version: 08/19/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 09/04/2020
Number of Days to Update: 14

Source: South Coast Air Quality Management District
Telephone: 909-396-3211
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

DRYCLEANERS: Cleaner Facilities
A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 08/06/2020
Date Data Arrived at EDR: 08/28/2020
Date Made Active in Reports: 11/17/2020
Number of Days to Update: 81

Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Annually

EMI: Emissions Inventory Data
Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 08/28/2020
Number of Days to Update: 73

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Varies

ENF: Enforcement Action Listing
A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 10/16/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80

Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing
Financial Assurance information

Date of Government Version: 10/13/2020
Date Data Arrived at EDR: 10/14/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 08/05/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 79

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 11/04/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 04/15/2020
Date Made Active in Reports: 07/02/2020
Number of Days to Update: 78

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 01/05/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Annually

ICE: ICE

Contains data pertaining to the Permitted Facilities with Inspections / Enforcements sites tracked in Envirostor.

Date of Government Version: 08/17/2020
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 80

Source: Department of Toxic Subsances Control
Telephone: 877-786-9427
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List

The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HWP: EnviroStor Permitted Facilities Listing

Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 08/17/2020
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Quarterly

HWT: Registered Hazardous Waste Transporter Database

A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 10/05/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 12/23/2020
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 01/05/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Quarterly

MINES: Mines Site Location Listing
A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: Department of Conservation
Telephone: 916-322-1080
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing
The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 81
Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

NPDES: NPDES Permits Listing
A listing of NPDES permits, including stormwater.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/10/2020
Date Made Active in Reports: 10/29/2020
Number of Days to Update: 80
Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Quarterly

PEST LIC: Pesticide Regulation Licenses Listing
A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 81
Source: Department of Pesticide Regulation
Telephone: 916-445-4038
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

PROC: Certified Processors Database
A listing of certified processors.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

NOTIFY 65: Proposition 65 Records
Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 12/07/2020
Date Data Arrived at EDR: 12/09/2020
Date Made Active in Reports: 12/10/2020
Number of Days to Update: 1
Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 12/07/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UIC: UIC Listing
A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84
Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

UIC GEO: Underground Injection Control Sites (GEOTRACKER)
Underground control injection sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resource Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

WASTEWATER PITS: Oil Wastewater Pits Listing
Water officials discovered that oil producers have been dumping chemical-laden wastewater into hundreds of unlined pits that are operating without proper permits. Inspections completed by the Central Valley Regional Water Quality Control Board revealed the existence of previously unidentified waste sites. The water boards review found that more than one-third of the region's active disposal pits are operating without permission.

Date of Government Version: 11/19/2019
Date Data Arrived at EDR: 01/07/2020
Date Made Active in Reports: 03/09/2020
Number of Days to Update: 62
Source: RWQCB, Central Valley Region
Telephone: 559-445-5577
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9
Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: No Update Planned

WIP: Well Investigation Program Case List
Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13
Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: No Update Planned

MILITARY PRIV SITES: Military Privatized Sites (GEOTRACKER)
Military privatized sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

PROJECT: Project Sites (GEOTRACKER)
Projects sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

WDR: Waste Discharge Requirements Listing

In general, the Waste Discharge Requirements (WDRs) Program (sometimes also referred to as the "Non Chapter 15 (Non 15) Program") regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. Exemptions from Title 27 may be granted for nine categories of discharges (e.g., sewage, wastewater, etc.) that meet, and continue to meet, the preconditions listed for each specific exemption. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84
Source: State Water Resources Control Board
Telephone: 916-341-5810
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

CIWQS: California Integrated Water Quality System

The California Integrated Water Quality System (CIWQS) is a computer system used by the State and Regional Water Quality Control Boards to track information about places of environmental interest, manage permits and other orders, track inspections, and manage violations and enforcement activities.

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 81
Source: State Water Resources Control Board
Telephone: 866-794-4977
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

CERS: CalEPA Regulated Site Portal Data

The CalEPA Regulated Site Portal database combines data about environmentally regulated sites and facilities in California into a single database. It combines data from a variety of state and federal databases, and provides an overview of regulated activities across the spectrum of environmental programs for any given location in California. These activities include hazardous materials and waste, state and federal cleanups, impacted ground and surface waters, and toxic materials

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80
Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

NON-CASE INFO: Non-Case Information Sites (GEOTRACKER)

Non-Case Information sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

OTHER OIL GAS: Other Oil & Gas Projects Sites (GEOTRACKER)

Other Oil & Gas Projects sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

PROD WATER PONDS: Produced Water Ponds Sites (GEOTRACKER)
Produced water ponds sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

SAMPLING POINT: Sampling Point ? Public Sites (GEOTRACKER)
Sampling point - public sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

WELL STIM PROJ: Well Stimulation Project (GEOTRACKER)
Includes areas of groundwater monitoring plans, a depiction of the monitoring network, and the facilities, boundaries, and subsurface characteristics of the oilfield and the features (oil and gas wells, produced water ponds, UIC wells, water supply wells, etc?) being monitored

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

PCS: Permit Compliance System
PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55
Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

PCS INACTIVE: Listing of Inactive PCS Permits
An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120
Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29
Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

HWTS: Hazardous Waste Tracking System

DTSC maintains the Hazardous Waste Tracking System that stores ID number information since the early 1980s and manifest data since 1993. The system collects both manifest copies from the generator and destination facility.

Date of Government Version: 10/13/2020
Date Data Arrived at EDR: 10/14/2020
Date Made Active in Reports: 11/03/2020
Number of Days to Update: 20

Source: Department of Toxic Substances Control
Telephone: 916-324-2444
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Department of Resources Recycling and Recovery
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

ALAMEDA COUNTY:

CS ALAMEDA: Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 01/09/2019
Date Data Arrived at EDR: 01/11/2019
Date Made Active in Reports: 03/05/2019
Number of Days to Update: 53

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

UST ALAMEDA: Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 12/23/2020
Number of Days to Update: 78

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA AMADOR: CUPA Facility List
Cupa Facility List

Date of Government Version: 05/18/2020
Date Data Arrived at EDR: 05/19/2020
Date Made Active in Reports: 06/01/2020
Number of Days to Update: 13

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA BUTTE: CUPA Facility Listing
Cupa facility list.

Date of Government Version: 04/21/2017
Date Data Arrived at EDR: 04/25/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 106

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA CALVERAS: CUPA Facility Listing
Cupa Facility Listing

Date of Government Version: 12/15/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 12/24/2020
Number of Days to Update: 8

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA COLUSA: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/06/2020
Date Data Arrived at EDR: 04/23/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 78

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Semi-Annually

CONTRA COSTA COUNTY:

SL CONTRA COSTA: Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 07/16/2020
Date Data Arrived at EDR: 07/22/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 78

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 10/20/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA DEL NORTE: CUPA Facility List
Cupa Facility list

Date of Government Version: 06/08/2020
Date Data Arrived at EDR: 08/13/2020
Date Made Active in Reports: 10/22/2020
Number of Days to Update: 70

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 10/20/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA EL DORADO: CUPA Facility List
CUPA facility list.

Date of Government Version: 08/13/2020
Date Data Arrived at EDR: 08/13/2020
Date Made Active in Reports: 10/22/2020
Number of Days to Update: 70

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 10/20/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA FRESNO: CUPA Resources List
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 10/02/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 77

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 12/22/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Semi-Annually

GLENN COUNTY:

CUPA GLENN: CUPA Facility List
Cupa facility list

Date of Government Version: 01/22/2018
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 03/14/2018
Number of Days to Update: 49

Source: Glenn County Air Pollution Control District
Telephone: 830-934-6500
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: No Update Planned

HUMBOLDT COUNTY:

CUPA HUMBOLDT: CUPA Facility List
CUPA facility list.

Date of Government Version: 08/13/2020
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 80

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Semi-Annually

IMPERIAL COUNTY:

CUPA IMPERIAL: CUPA Facility List
Cupa facility list.

Date of Government Version: 10/14/2020
Date Data Arrived at EDR: 10/15/2020
Date Made Active in Reports: 01/05/2021
Number of Days to Update: 82

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INYO COUNTY:

CUPA INYO: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/03/2018
Date Made Active in Reports: 06/14/2018
Number of Days to Update: 72

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

KERN COUNTY:

CUPA KERN: CUPA Facility List
A listing of sites included in the Kern County Hazardous Material Business Plan.

Date of Government Version: 07/28/2020
Date Data Arrived at EDR: 07/30/2020
Date Made Active in Reports: 10/13/2020
Number of Days to Update: 75

Source: Kern County Public Health
Telephone: 661-321-3000
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

UST KERN: Underground Storage Tank Sites & Tank Listing
Kern County Sites and Tanks Listing.

Date of Government Version: 07/28/2020
Date Data Arrived at EDR: 07/30/2020
Date Made Active in Reports: 10/14/2020
Number of Days to Update: 76

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA KINGS: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 05/11/2020
Date Data Arrived at EDR: 05/12/2020
Date Made Active in Reports: 07/27/2020
Number of Days to Update: 76

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

LAKE COUNTY:

CUPA LAKE: CUPA Facility List
Cupa facility list

Date of Government Version: 08/13/2020
Date Data Arrived at EDR: 08/13/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 71

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 10/07/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Varies

LASSEN COUNTY:

CUPA LASSEN: CUPA Facility List
Cupa facility list

Date of Government Version: 07/31/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 80

Source: Lassen County Environmental Health
Telephone: 530-251-8528
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

LOS ANGELES COUNTY:

AOCONCERN: Key Areas of Concerns in Los Angeles County
San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office. Date of Government Version: 3/30/2009 Exide Site area is a cleanup plan of lead-impacted soil surrounding the former Exide Facility as designated by the DTSC. Date of Government Version: 7/17/2017

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206

Source: N/A
Telephone: N/A
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: No Update Planned

HMS LOS ANGELES: HMS: Street Number List
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 07/06/2020
Date Data Arrived at EDR: 07/10/2020
Date Made Active in Reports: 09/28/2020
Number of Days to Update: 80

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

LF LOS ANGELES: List of Solid Waste Facilities
Solid Waste Facilities in Los Angeles County.

Date of Government Version: 10/09/2020
Date Data Arrived at EDR: 10/09/2020
Date Made Active in Reports: 12/29/2020
Number of Days to Update: 81

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 10/09/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Varies

LF LOS ANGELES CITY: City of Los Angeles Landfills
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 80

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 10/07/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Varies

LOS ANGELES AST: Active & Inactive AST Inventory
A listing of active & inactive above ground petroleum storage tank site locations, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

LOS ANGELES CO LF METHANE: Methane Producing Landfills
This data was created on April 30, 2012 to represent known disposal sites in Los Angeles County that may produce and emanate methane gas. The shapefile contains disposal sites within Los Angeles County that once accepted degradable refuse material. Information used to create this data was extracted from a landfill survey performed by County Engineers (Major Waste System Map, 1973) as well as historical records from CalRecycle, Regional Water Quality Control Board, and Los Angeles County Department of Public Health

Date of Government Version: 04/30/2012
Date Data Arrived at EDR: 04/17/2019
Date Made Active in Reports: 05/29/2019
Number of Days to Update: 42
Source: Los Angeles County Department of Public Works
Telephone: 626-458-6973
Last EDR Contact: 10/12/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: No Update Planned

LOS ANGELES HM: Active & Inactive Hazardous Materials Inventory
A listing of active & inactive hazardous materials facility locations, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

LOS ANGELES UST: Active & Inactive UST Inventory
A listing of active & inactive underground storage tank site locations and underground storage tank historical sites, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

SITE MIT LOS ANGELES: Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 07/20/2020
Date Data Arrived at EDR: 10/09/2020
Date Made Active in Reports: 12/29/2020
Number of Days to Update: 81
Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 10/09/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Annually

UST EL SEGUNDO: City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/10/2017
Number of Days to Update: 21
Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 10/07/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: No Update Planned

UST LONG BEACH: City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 04/22/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/27/2019
Number of Days to Update: 65

Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

UST TORRANCE: City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 09/11/2020
Date Data Arrived at EDR: 10/07/2020
Date Made Active in Reports: 12/23/2020
Number of Days to Update: 77

Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 10/05/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA MADERA: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 72

Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

MARIN COUNTY:

UST MARIN: Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 09/26/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/02/2018
Number of Days to Update: 29

Source: Public Works Department Waste Management
Telephone: 415-473-6647
Last EDR Contact: 12/21/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Semi-Annually

MERCED COUNTY:

CUPA MERCED: CUPA Facility List
CUPA facility list.

Date of Government Version: 07/28/2020
Date Data Arrived at EDR: 07/30/2020
Date Made Active in Reports: 07/31/2020
Number of Days to Update: 1

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

MONO COUNTY:

CUPA MONO: CUPA Facility List
CUPA Facility List

Date of Government Version: 08/20/2020
Date Data Arrived at EDR: 08/24/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 77

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 11/15/2020
Next Scheduled EDR Contact: 03/08/3021
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA MONTEREY: CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 07/13/2020
Date Data Arrived at EDR: 07/15/2020
Date Made Active in Reports: 07/31/2020
Number of Days to Update: 16

Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 12/21/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Varies

NAPA COUNTY:

LUST NAPA: Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 03/02/2017
Number of Days to Update: 50

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

UST NAPA: Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 09/05/2019
Date Data Arrived at EDR: 09/09/2019
Date Made Active in Reports: 10/31/2019
Number of Days to Update: 52

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA NEVADA: CUPA Facility List
CUPA facility list.

Date of Government Version: 07/29/2020
Date Data Arrived at EDR: 07/30/2020
Date Made Active in Reports: 10/13/2020
Number of Days to Update: 75

Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 10/20/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

ORANGE COUNTY:

IND_SITE ORANGE: List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 06/10/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 10/19/2020
Number of Days to Update: 77

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/02/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Annually

LUST ORANGE: List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 07/02/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 79

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/02/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

UST ORANGE: List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 07/01/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 10/19/2020
Number of Days to Update: 77

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/03/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

PLACER COUNTY:

MS PLACER: Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 11/24/2020
Date Data Arrived at EDR: 11/24/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 1

Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Semi-Annually

PLUMAS COUNTY:

CUPA PLUMAS: CUPA Facility List
Plumas County CUPA Program facilities.

Date of Government Version: 03/31/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/26/2019
Number of Days to Update: 64

Source: Plumas County Environmental Health
Telephone: 530-283-6355
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

RIVERSIDE COUNTY:

LUST RIVERSIDE: Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 10/06/2020
Date Data Arrived at EDR: 10/07/2020
Date Made Active in Reports: 11/03/2020
Number of Days to Update: 27

Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Quarterly

UST RIVERSIDE: Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 10/06/2020
Date Data Arrived at EDR: 10/07/2020
Date Made Active in Reports: 11/03/2020
Number of Days to Update: 27
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

CS SACRAMENTO: Toxic Site Clean-Up List
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 02/18/2020
Date Data Arrived at EDR: 03/31/2020
Date Made Active in Reports: 06/15/2020
Number of Days to Update: 76
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

ML SACRAMENTO: Master Hazardous Materials Facility List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 02/24/2020
Date Data Arrived at EDR: 03/31/2020
Date Made Active in Reports: 06/17/2020
Number of Days to Update: 78
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

SAN BENITO COUNTY:

CUPA SAN BENITO: CUPA Facility List
Cupa facility list

Date of Government Version: 08/04/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/22/2020
Number of Days to Update: 78
Source: San Benito County Environmental Health
Telephone: N/A
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

SAN BERNARDINO COUNTY:

PERMITS SAN BERNARDINO: Hazardous Material Permits
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 08/04/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 82
Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

HMMD SAN DIEGO: Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/23/2020
Number of Days to Update: 84

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

LF SAN DIEGO: Solid Waste Facilities

San Diego County Solid Waste Facilities.

Date of Government Version: 04/18/2018
Date Data Arrived at EDR: 04/24/2018
Date Made Active in Reports: 06/19/2018
Number of Days to Update: 56

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

SAN DIEGO CO LOP: Local Oversight Program Listing

A listing of all LOP release sites that are or were under the County of San Diego's jurisdiction. Included are closed or transferred cases, open cases, and cases that did not have a case type indicated. The cases without a case type are mostly complaints; however, some of them could be LOP cases.

Date of Government Version: 07/14/2020
Date Data Arrived at EDR: 07/16/2020
Date Made Active in Reports: 09/29/2020
Number of Days to Update: 75

Source: Department of Environmental Health
Telephone: 858-505-6874
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

SAN DIEGO CO SAM: Environmental Case Listing

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24

Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

CUPA SAN FRANCISCO CO: CUPA Facility Listing

Cupa facilities

Date of Government Version: 08/03/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/22/2020
Number of Days to Update: 78

Source: San Francisco County Department of Environmental Health
Telephone: 415-252-3896
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

LUST SAN FRANCISCO: Local Oversite Facilities

A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10

Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: No Update Planned

UST SAN FRANCISCO: Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 08/03/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 82

Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

UST SAN JOAQUIN: San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 06/22/2018
Date Data Arrived at EDR: 06/26/2018
Date Made Active in Reports: 07/11/2018
Number of Days to Update: 15

Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA SAN LUIS OBISPO: CUPA Facility List
Cupa Facility List.

Date of Government Version: 07/27/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 75

Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

SAN MATEO COUNTY:

BI SAN MATEO: Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 02/20/2020
Date Data Arrived at EDR: 02/20/2020
Date Made Active in Reports: 04/24/2020
Number of Days to Update: 64

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 12/11/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Annually

LUST SAN MATEO: Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/29/2019
Date Data Arrived at EDR: 03/29/2019
Date Made Active in Reports: 05/29/2019
Number of Days to Update: 61

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA SANTA BARBARA: CUPA Facility Listing
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28

Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: No Update Planned

SANTA CLARA COUNTY:

CUPA SANTA CLARA: Cupa Facility List
Cupa facility list

Date of Government Version: 08/20/2020
Date Data Arrived at EDR: 08/20/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 81

Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

HIST LUST SANTA CLARA: HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22

Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LUST SANTA CLARA: LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014
Date Data Arrived at EDR: 03/05/2014
Date Made Active in Reports: 03/18/2014
Number of Days to Update: 13

Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

SAN JOSE HAZMAT: Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 07/30/2020
Date Data Arrived at EDR: 07/31/2020
Date Made Active in Reports: 10/16/2020
Number of Days to Update: 77

Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA SANTA CRUZ: CUPA Facility List
CUPA facility listing.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 05/23/2017
Number of Days to Update: 90

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA SHASTA: CUPA Facility List
Cupa Facility List.

Date of Government Version: 06/15/2017
Date Data Arrived at EDR: 06/19/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 51

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

SOLANO COUNTY:

LUST SOLANO: Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 06/04/2019
Date Data Arrived at EDR: 06/06/2019
Date Made Active in Reports: 08/13/2019
Number of Days to Update: 68

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 06/03/2019
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

UST SOLANO: Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 08/25/2020
Date Data Arrived at EDR: 08/26/2020
Date Made Active in Reports: 09/16/2020
Number of Days to Update: 21

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 12/03/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

SONOMA COUNTY:

CUPA SONOMA: Cupa Facility List
Cupa Facility list

Date of Government Version: 12/15/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 12/23/2020
Number of Days to Update: 7

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

LUST SONOMA: Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 09/18/2020
Date Data Arrived at EDR: 09/22/2020
Date Made Active in Reports: 12/14/2020
Number of Days to Update: 83

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

STANISLAUS COUNTY:

CUPA STANISLAUS: CUPA Facility List
Cupa facility list

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 77

Source: Stanislaus County Department of Ennvironmental Protection
Telephone: 209-525-6751
Last EDR Contact: 10/02/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Varies

SUTTER COUNTY:

UST SUTTER: Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 08/25/2020
Date Data Arrived at EDR: 08/26/2020
Date Made Active in Reports: 11/17/2020
Number of Days to Update: 83

Source: Sutter County Environmental Health Services
Telephone: 530-822-7500
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Semi-Annually

TEHAMA COUNTY:

CUPA TEHAMA: CUPA Facility List
Cupa facilities

Date of Government Version: 08/11/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 75

Source: Tehama County Department of Environmental Health
Telephone: 530-527-8020
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

TRINITY COUNTY:

CUPA TRINITY: CUPA Facility List
Cupa facility list

Date of Government Version: 10/14/2020
Date Data Arrived at EDR: 10/15/2020
Date Made Active in Reports: 01/05/2021
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 760-352-0381
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

TULARE COUNTY:

CUPA TULARE: CUPA Facility List
Cupa program facilities

Date of Government Version: 08/06/2020
Date Data Arrived at EDR: 08/06/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 81

Source: Tulare County Environmental Health Services Division
Telephone: 559-624-7400
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

TUOLUMNE COUNTY:

CUPA TUOLUMNE: CUPA Facility List
Cupa facility list

Date of Government Version: 04/23/2018
Date Data Arrived at EDR: 04/25/2018
Date Made Active in Reports: 06/25/2018
Number of Days to Update: 61

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

VENTURA COUNTY:

BWT VENTURA: Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 07/10/2020
Date Data Arrived at EDR: 07/22/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 78
Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Quarterly

LF VENTURA: Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 12/21/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: No Update Planned

LUST VENTURA: Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: No Update Planned

MED WASTE VENTURA: Medical Waste Program List
To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 07/10/2020
Date Data Arrived at EDR: 07/22/2020
Date Made Active in Reports: 10/07/2020
Number of Days to Update: 77
Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Quarterly

UST VENTURA: Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 08/26/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

YOLO COUNTY:

UST YOLO: Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 12/21/2020
Date Data Arrived at EDR: 12/23/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 12
Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 12/20/2020
Next Scheduled EDR Contact: 04/11/2021
Data Release Frequency: Annually

YUBA COUNTY:

CUPA YUBA: CUPA Facility List
CUPA facility listing for Yuba County.

Date of Government Version: 08/06/2020
Date Data Arrived at EDR: 08/07/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 80

Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 11/03/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 10/20/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 13

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 04/29/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/30/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/07/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 10/02/2019
Date Made Active in Reports: 12/10/2019
Number of Days to Update: 69

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 12/03/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

PARCEL B BUILDINGS - FORMER COLLINS AEROSPACE
SOUTH OF G STREET
CHULA VISTA, CA 91910

TARGET PROPERTY COORDINATES

Latitude (North):	32.630014 - 32° 37' 48.05''
Longitude (West):	117.100205 - 117° 6' 0.74''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	490600.2
UTM Y (Meters):	3610086.0
Elevation:	12 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5629176 NATIONAL CITY, CA
Version Date:	2012
Southeast Map:	5622818 IMPERIAL BEACH, CA
Version Date:	2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WSW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 12 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
06073C1913G	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
06073C1914G	FEMA FIRM Flood data
06073C2151F	FEMA FIRM Flood data
06073C2152F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
NATIONAL CITY	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1/8 - 1/4 Mile ESE
Site Name:	ROHR IND INC
Site EPA ID Number:	CAD008382053
Groundwater Flow Direction:	Southwest
Measured Depth to Water:	5 feet.
Hydraulic Connection:	Information is not available regarding the hydraulic connection between aquifer(s) underlying the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information based on site-specific subsurface investigations is documented in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Q137	1/4 - 1/2 Mile East	SW
Q172	1/4 - 1/2 Mile East	W
182	1/2 - 1 Mile NNE	Not Reported
185	1/2 - 1 Mile ENE	W
1G	1/2 - 1 Mile NNE	Not Reported
2G	1/2 - 1 Mile ENE	W
3G	1/4 - 1/2 Mile East	W
4G	1/4 - 1/2 Mile East	SW

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Cenozoic
System:	Tertiary
Series:	Pliocene
Code:	Tp *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 6326895.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Parcel B Buildings - Former Collins Aerospace	CLIENT:	Partner Engineering and Science, Inc.
ADDRESS:	South of G Street Chula Vista CA 91910	CONTACT:	Karli Mcmurray
LAT/LONG:	32.630014 / 117.100205	INQUIRY #:	6326895.2s
		DATE:	January 11, 2021 1:47 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: HUERHUERO

Soil Surface Texture: loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	11 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 7.4
2	11 inches	55 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 7.4
3	55 inches	72 inches	stratified sand to sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 7.4

Soil Map ID: 2

Soil Component Name: MADE LAND

Soil Surface Texture: variable

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class:
Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	variable	Not reported	Not reported	Max: Min:	Max: Min:

Soil Map ID: 3

Soil Component Name: TIDAL FLATS

Soil Surface Texture: variable

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Very poorly drained

Hydric Status: All hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	59 inches	variable	Not reported	Not reported	Max: Min:	Max: Min:

Soil Map ID: 4

Soil Component Name: HUERHUERO

Soil Surface Texture: loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Moderately well drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	11 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 7.4
2	11 inches	55 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 7.4

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	55 inches	72 inches	stratified sand to sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 7.4

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
M92	USGS40000129277	1/4 - 1/2 Mile NE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	CAEDF0000049398	0 - 1/8 Mile SSE
A2	CAEDF0000109844	0 - 1/8 Mile SSE
A3	CAEDF0000065484	0 - 1/8 Mile SSE
A4	CAEDF0000086268	0 - 1/8 Mile SSE
A5	CAEDF0000087165	0 - 1/8 Mile SSE
A6	CAEDF0000105219	1/8 - 1/4 Mile South
A7	CAEDF0000110759	1/8 - 1/4 Mile South
A8	CAEDF0000037512	1/8 - 1/4 Mile SSE
B9	CAEDF0000136505	1/8 - 1/4 Mile NNW
A10	CAEDF0000019489	1/8 - 1/4 Mile SSE
A11	CAEDF0000087663	1/8 - 1/4 Mile SSE
C12	CAEDF0000099873	1/8 - 1/4 Mile SSW
D13	CAEDF0000021937	1/8 - 1/4 Mile South
D14	CAEDF0000107481	1/8 - 1/4 Mile South
B15	CAEDF0000094986	1/8 - 1/4 Mile NNW
C16	CAEDF0000085494	1/8 - 1/4 Mile SSW
17	CAEDF0000091531	1/8 - 1/4 Mile NW
D18	CAEDF0000127165	1/8 - 1/4 Mile South
C19	CAEDF0000134024	1/8 - 1/4 Mile SSW
C20	CAEDF0000061015	1/8 - 1/4 Mile SSW
C21	CAEDF0000005647	1/8 - 1/4 Mile SSW
C22	CAEDF0000132562	1/8 - 1/4 Mile SSW
E23	CAEDF0000109518	1/8 - 1/4 Mile SE
F24	CAEDF0000047375	1/8 - 1/4 Mile South
F25	CAEDF0000070611	1/8 - 1/4 Mile South
G26	CAEDF0000071898	1/8 - 1/4 Mile SSW
H27	CAEDF0000068762	1/4 - 1/2 Mile East
I28	CAEDF0000031652	1/4 - 1/2 Mile WSW
I29	CAEDF0000067669	1/4 - 1/2 Mile WSW
G30	CAEDF0000092478	1/4 - 1/2 Mile SSW
G31	CAEDF0000000612	1/4 - 1/2 Mile SSW
H32	CAEDF0000095519	1/4 - 1/2 Mile East
H33	CAEDF0000000712	1/4 - 1/2 Mile East
I34	CAEDF0000121466	1/4 - 1/2 Mile WSW
F35	CAEDF0000099614	1/4 - 1/2 Mile South
F36	CAEDF0000122008	1/4 - 1/2 Mile South
J37	CAEDF0000084872	1/4 - 1/2 Mile SSE
J38	CAEDF0000034082	1/4 - 1/2 Mile SSE
E39	CAEDF0000137836	1/4 - 1/2 Mile SSE
G40	CAEDF0000143625	1/4 - 1/2 Mile SW
J41	CAEDF0000113906	1/4 - 1/2 Mile SSE
J42	CAEDF0000076753	1/4 - 1/2 Mile South
J43	CAEDF0000136870	1/4 - 1/2 Mile South
H44	CAEDF0000090478	1/4 - 1/2 Mile East
F45	CAEDF0000080135	1/4 - 1/2 Mile South
F46	CAEDF0000143525	1/4 - 1/2 Mile South
F47	CAEDF0000098790	1/4 - 1/2 Mile South
H48	CAEDF0000130209	1/4 - 1/2 Mile East
H49	CAEDF0000126951	1/4 - 1/2 Mile East
H50	CAEDF0000095069	1/4 - 1/2 Mile East
H51	CAEDF0000016043	1/4 - 1/2 Mile East
H52	CAEDF0000003741	1/4 - 1/2 Mile East

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
H53	CAEDF0000052014	1/4 - 1/2 Mile East
H54	CAEDF0000011758	1/4 - 1/2 Mile East
H55	CAEDF0000100606	1/4 - 1/2 Mile East
H56	CAEDF0000080807	1/4 - 1/2 Mile East
H57	CAEDF0000002848	1/4 - 1/2 Mile East
H58	CAEDF0000118986	1/4 - 1/2 Mile East
H59	CAEDF0000040455	1/4 - 1/2 Mile East
H60	CAEDF0000088277	1/4 - 1/2 Mile East
K61	CAEDF0000136269	1/4 - 1/2 Mile East
H62	CAEDF0000003960	1/4 - 1/2 Mile East
H63	CAEDF0000138525	1/4 - 1/2 Mile East
K64	CAEDF0000088879	1/4 - 1/2 Mile East
K65	CAEDF0000040339	1/4 - 1/2 Mile East
H66	CAEDF0000022397	1/4 - 1/2 Mile East
H67	CAEDF0000079194	1/4 - 1/2 Mile East
H68	CAEDF0000051193	1/4 - 1/2 Mile East
H69	CAEDF0000093984	1/4 - 1/2 Mile East
K70	CAEDF0000008594	1/4 - 1/2 Mile East
K71	CAEDF0000056819	1/4 - 1/2 Mile East
K72	CAEDF0000051991	1/4 - 1/2 Mile East
K73	CAEDF0000135216	1/4 - 1/2 Mile East
K74	CAEDF0000081579	1/4 - 1/2 Mile East
J75	CAEDF0000054423	1/4 - 1/2 Mile SSE
K76	CAEDF0000140002	1/4 - 1/2 Mile East
K77	CAEDF0000042283	1/4 - 1/2 Mile East
L78	CAEDF0000018227	1/4 - 1/2 Mile SSE
L79	CAEDF0000022305	1/4 - 1/2 Mile SSE
J80	CAEDF0000041503	1/4 - 1/2 Mile South
J81	CAEDF0000053146	1/4 - 1/2 Mile South
K82	CAEDF0000037587	1/4 - 1/2 Mile East
K83	CAEDF0000067169	1/4 - 1/2 Mile East
K84	CAEDF0000010921	1/4 - 1/2 Mile East
K85	CAEDF0000079471	1/4 - 1/2 Mile East
K86	CAEDF0000082455	1/4 - 1/2 Mile East
K87	CAEDF0000083188	1/4 - 1/2 Mile East
K88	CAEDF0000141359	1/4 - 1/2 Mile East
K89	CAEDF0000137703	1/4 - 1/2 Mile East
K90	CAEDF0000129706	1/4 - 1/2 Mile ESE
M91	CAUSGSN00016092	1/4 - 1/2 Mile NE
K93	CAEDF0000078647	1/4 - 1/2 Mile East
K94	CAEDF0000059786	1/4 - 1/2 Mile East
N95	CAUSGSN00007088	1/4 - 1/2 Mile North
N96	CAUSGSN00004801	1/4 - 1/2 Mile North
N97	CAUSGSN00008715	1/4 - 1/2 Mile North
N98	CAUSGSN00000848	1/4 - 1/2 Mile North
N99	CAUSGSN00016734	1/4 - 1/2 Mile North
N100	CAUSGSN00017247	1/4 - 1/2 Mile North
K101	CAEDF0000116581	1/4 - 1/2 Mile East
K102	CAEDF0000037896	1/4 - 1/2 Mile East
O103	CAEDF0000117285	1/4 - 1/2 Mile SW
P104	CAEDF0000055812	1/4 - 1/2 Mile South
P105	CAEDF0000085899	1/4 - 1/2 Mile South

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
Q106	CAEDF0000110021	1/4 - 1/2 Mile East
Q107	CAEDF0000140286	1/4 - 1/2 Mile East
K108	CAEDF0000119999	1/4 - 1/2 Mile East
Q109	CAEDF0000119823	1/4 - 1/2 Mile East
P110	CAEDF0000102810	1/4 - 1/2 Mile South
R111	CAEDF0000091290	1/4 - 1/2 Mile NNE
Q112	CAEDF0000049959	1/4 - 1/2 Mile East
Q113	CAEDF0000118044	1/4 - 1/2 Mile East
P114	CAEDF0000117064	1/4 - 1/2 Mile South
M115	CAEDF0000005147	1/4 - 1/2 Mile NNE
S116	CAEDF0000039333	1/4 - 1/2 Mile WSW
S117	CAEDF0000035649	1/4 - 1/2 Mile WSW
Q118	CAEDF0000070921	1/4 - 1/2 Mile East
Q119	CAEDF0000055540	1/4 - 1/2 Mile East
L120	CAEDF0000099164	1/4 - 1/2 Mile SSE
S121	CAEDF0000098940	1/4 - 1/2 Mile WSW
Q122	CAEDF0000046744	1/4 - 1/2 Mile East
Q123	CAEDF0000002622	1/4 - 1/2 Mile East
T124	CAEDF0000129510	1/4 - 1/2 Mile West
T125	CAEDF0000092535	1/4 - 1/2 Mile West
L126	CAEDF0000096390	1/4 - 1/2 Mile SSE
127	CAEDF0000072442	1/4 - 1/2 Mile SSE
M128	CAEDF0000045651	1/4 - 1/2 Mile NNE
M129	CAEDF0000024007	1/4 - 1/2 Mile NNE
Q130	CAEDF0000002539	1/4 - 1/2 Mile East
Q131	CAEDF0000078566	1/4 - 1/2 Mile East
Q132	CAEDF0000121823	1/4 - 1/2 Mile East
T133	CAEDF0000126681	1/4 - 1/2 Mile West
M134	CAEDF0000018545	1/4 - 1/2 Mile NNE
L135	CAEDF0000058030	1/4 - 1/2 Mile SSE
L136	CAEDF0000074736	1/4 - 1/2 Mile SSE
M138	CAEDF0000059346	1/4 - 1/2 Mile NNE
M139	CAEDF0000012099	1/4 - 1/2 Mile NNE
Q140	CAEDF0000009061	1/4 - 1/2 Mile East
O141	CAEDF0000078512	1/4 - 1/2 Mile SW
O142	CAEDF0000085952	1/4 - 1/2 Mile SW
O143	CAEDF0000111346	1/4 - 1/2 Mile SW
M144	CAEDF0000121572	1/4 - 1/2 Mile NNE
P145	CAEDF0000034678	1/4 - 1/2 Mile South
P146	CAEDF0000122712	1/4 - 1/2 Mile South
Q147	CAEDF0000047852	1/4 - 1/2 Mile East
Q148	CAEDF0000060906	1/4 - 1/2 Mile East
Q149	CAEDF0000101027	1/4 - 1/2 Mile East
Q150	CAEDF0000048218	1/4 - 1/2 Mile East
P151	CAEDF0000041123	1/4 - 1/2 Mile South
Q152	CAEDF0000095184	1/4 - 1/2 Mile East
Q153	CAEDF0000125791	1/4 - 1/2 Mile East
R154	CAEDF0000057163	1/4 - 1/2 Mile NNE
Q155	CAEDF0000122756	1/4 - 1/2 Mile East
Q156	CAEDF0000047451	1/4 - 1/2 Mile East
Q157	CAEDF0000143005	1/4 - 1/2 Mile East
Q158	CAEDF0000059455	1/4 - 1/2 Mile East

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
U159	CAEDF0000061482	1/4 - 1/2 Mile South
Q160	CAEDF0000117337	1/4 - 1/2 Mile East
Q161	CAEDF0000105553	1/4 - 1/2 Mile East
Q162	CAEDF0000064238	1/4 - 1/2 Mile East
Q163	CAEDF0000103685	1/4 - 1/2 Mile East
U164	CAEDF0000064335	1/4 - 1/2 Mile South
R165	CAEDF0000115183	1/4 - 1/2 Mile NNE
Q166	CAEDF0000109106	1/4 - 1/2 Mile East
Q167	CAEDF0000064001	1/4 - 1/2 Mile East
Q168	CAEDF0000103584	1/4 - 1/2 Mile East
Q169	CAEDF0000066014	1/4 - 1/2 Mile East
V170	CAEDF0000056127	1/4 - 1/2 Mile East
V171	CAEDF0000043968	1/4 - 1/2 Mile East
V173	CAEDF0000076042	1/4 - 1/2 Mile East
174	CAEDF0000127347	1/2 - 1 Mile SSE
175	CAEDF0000133674	1/2 - 1 Mile SSE
W176	CAEDF0000035168	1/2 - 1 Mile East
W177	CAEDF0000106376	1/2 - 1 Mile East
W178	CAEDF0000093236	1/2 - 1 Mile East
W179	CAEDF0000003553	1/2 - 1 Mile East
W180	CAEDF0000002918	1/2 - 1 Mile East
W181	CAEDF0000059100	1/2 - 1 Mile East
W183	CAEDF0000089777	1/2 - 1 Mile East
W184	CAEDF0000053463	1/2 - 1 Mile East
X186	CAEDF0000071152	1/2 - 1 Mile NE
X187	CAEDF0000032052	1/2 - 1 Mile NE
X188	CAEDF0000070255	1/2 - 1 Mile NE
X189	CAEDF0000059160	1/2 - 1 Mile NE
Y190	CAEDF0000142196	1/2 - 1 Mile ESE
Y191	CAEDF0000127100	1/2 - 1 Mile ESE
Z192	CAEDF0000121954	1/2 - 1 Mile NNE
Z193	CAEDF0000020134	1/2 - 1 Mile NNE
Z194	CAEDF0000040344	1/2 - 1 Mile NNE
Z195	CAEDF0000061047	1/2 - 1 Mile NNE
Y196	CAEDF0000011697	1/2 - 1 Mile ESE
Y197	CAEDF0000081394	1/2 - 1 Mile ESE
Y198	CAEDF0000140426	1/2 - 1 Mile ESE
Z199	CAEDF0000083841	1/2 - 1 Mile NNE
Z200	CAEDF0000012685	1/2 - 1 Mile NNE
Y201	CAEDF0000128578	1/2 - 1 Mile ESE
Y202	CAEDF0000044000	1/2 - 1 Mile ESE
Y203	CAEDF0000008793	1/2 - 1 Mile ESE
Y204	CAEDF0000015272	1/2 - 1 Mile ESE
Z205	CAEDF0000090210	1/2 - 1 Mile NNE
Z206	CAEDF0000139315	1/2 - 1 Mile NNE
Z207	CAEDF0000109072	1/2 - 1 Mile NNE
Z208	CAEDF0000000723	1/2 - 1 Mile NNE
Z209	CAEDF0000133917	1/2 - 1 Mile NNE
Y210	CAEDF0000019980	1/2 - 1 Mile ESE
Y211	CAEDF0000089990	1/2 - 1 Mile ESE
Z212	CAEDF0000102819	1/2 - 1 Mile NNE
Z213	CAEDF0000122428	1/2 - 1 Mile NNE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
Z214	CAEDF0000073004	1/2 - 1 Mile NNE
Y215	CAEDF0000051456	1/2 - 1 Mile ESE
Z216	CAEDF0000088089	1/2 - 1 Mile NNE
Z217	CAEDF0000066409	1/2 - 1 Mile NNE
Z218	CAEDF0000131984	1/2 - 1 Mile NNE
Z219	CAEDF0000060321	1/2 - 1 Mile NNE
Y220	CAEDF0000086893	1/2 - 1 Mile ESE
Z221	CAEDF0000044683	1/2 - 1 Mile NNE
Y222	CAEDF0000130710	1/2 - 1 Mile ESE
Z223	CAEDF0000007359	1/2 - 1 Mile NNE
Z224	CAEDF0000062632	1/2 - 1 Mile NNE
AA225	CAEDF0000120070	1/2 - 1 Mile ESE
Z226	CAEDF0000110879	1/2 - 1 Mile NNE
Z227	CAEDF0000004968	1/2 - 1 Mile NNE
AA228	CAEDF0000054714	1/2 - 1 Mile ESE
AA229	CAEDF0000084476	1/2 - 1 Mile ESE
AA230	CAEDF0000062606	1/2 - 1 Mile ESE
AB231	CAEDF0000096792	1/2 - 1 Mile East
AB232	CAEDF0000007253	1/2 - 1 Mile ENE
AC233	CAEDF0000046930	1/2 - 1 Mile ENE
AB234	CAEDF0000103782	1/2 - 1 Mile ENE
AB235	CAEDF0000002186	1/2 - 1 Mile ENE
AB236	CAEDF0000039033	1/2 - 1 Mile ENE
AB237	CAEDF0000050726	1/2 - 1 Mile East
AB238	CAEDF0000020355	1/2 - 1 Mile ENE
AC239	CAEDF0000011109	1/2 - 1 Mile ENE
AC240	CAEDF0000078660	1/2 - 1 Mile ENE
AD241	CAEDF0000091010	1/2 - 1 Mile ENE
AD242	CAEDF0000064384	1/2 - 1 Mile East
AD243	CAEDF0000014666	1/2 - 1 Mile ENE

PHYSICAL SETTING SOURCE MAP - 6326895.2s



County Boundary
Major Roads
Contour Lines
Earthquake Fault Lines
Earthquake epicenter, Richter 5 or greater
Water Wells
Public Water Supply Wells
Cluster of Multiple Icons

0 1/4 1/2 1 Miles

Groundwater Flow Direction
Indeterminate Groundwater Flow at Location
Groundwater Flow Varies at Location
Closest Hydrogeological Data
Oil, gas or related wells

SITE NAME:	Parcel B Buildings - Former Collins Aerospace	CLIENT:	Partner Engineering and Science, Inc.
ADDRESS:	South of G Street Chula Vista CA 91910	CONTACT:	Karli Mcmurray
LAT/LONG:	32.630014 / 117.100205	INQUIRY #:	6326895.2s
		DATE:	January 11, 2021 1:46 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
SSE
0 - 1/8 Mile
Higher

CA WELLS **CAEDF0000049398**

Well ID:	T10000001489-NCW-014B	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-014B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-014B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-014B		

A2
SSE
0 - 1/8 Mile
Higher

CA WELLS **CAEDF0000109844**

Well ID:	T10000001489-NCW-014A	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-014A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-014A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-014A		

A3
SSE
0 - 1/8 Mile
Higher

CA WELLS **CAEDF0000065484**

Well ID:	T10000001489-NCW-013C	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-013C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-013C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-013C		

A4
SSE
0 - 1/8 Mile
Higher

CA WELLS **CAEDF0000086268**

Well ID:	T10000001489-NCW-013A	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-013A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-013A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-013A		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A5
SSE
0 - 1/8 Mile
Higher

CA WELLS **CAEDF0000087165**

Well ID:	T10000001489-NCW-013B	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-013B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-013B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-013B		

A6
South
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000105219**

Well ID:	T10000001489-NCW-015A	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-015A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-015A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-015A		

A7
South
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000110759**

Well ID:	T10000001489-NCW-015B	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-015B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-015B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-015B		

A8
SSE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000037512**

Well ID:	SL209294204-PMW105(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW105(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW105(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW105(UB)		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B9
NNW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000136505**

Well ID:	T10000001489-NCW-010	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-010
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-010&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-010		

A10
SSE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000019489**

Well ID:	SL209294204-PMW106(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW106(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW106(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW106(UB)		

A11
SSE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000087663**

Well ID:	SL209294204-PMW106(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW106(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW106(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW106(A)		

C12
SSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000099873**

Well ID:	T10000001489-NCW-020	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-020
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-020&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-020		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D13
South
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000021937**

Well ID:	SL209294204-PMW104(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW104(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW104(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW104(UB)		

D14
South
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000107481**

Well ID:	SL209294204-PMW104(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW104(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW104(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW104(LB)		

B15
NNW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000094986**

Well ID:	T10000001489-NCW-011	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-011
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-011&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-011		

C16
SSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000085494**

Well ID:	SL209294204-PMW102(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW102(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW102(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW102(UB)		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

17
NW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000091531**

Well ID:	T10000001489-NCW-012	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-012
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-012&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-012		

D18
South
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000127165**

Well ID:	SL209294204-PMW120(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW120(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW120(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW120(A)		

C19
SSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000134024**

Well ID:	SL209294204-PMW101(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW101(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW101(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW101(A)		

C20
SSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000061015**

Well ID:	SL209294204-PMW101(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW101(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW101(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW101(UB)		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C21
SSW
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000005647**

Well ID:	SL209294204-PMW101(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW101(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW101(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW101(LB)		

C22
SSW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000132562**

Well ID:	T10000001489-NCW-016	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-016
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-016&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-016		

E23
SE
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000109518**

Well ID:	SL209294204-PMW107(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW107(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW107(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW107(UB)		

F24
South
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000047375**

Well ID:	SL209294204-PMW103(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW103(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW103(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW103(A)		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F25
South
1/8 - 1/4 Mile
Higher

CA WELLS **CAEDF0000070611**

Well ID:	SL209294204-PMW103(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW103(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW103(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW103(UB)		

G26
SSW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000071898**

Well ID:	T10000001489-NCW-017	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-017
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-017&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-017		

H27
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000068762**

Well ID:	T0607310406-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-12		

I28
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000031652**

Well ID:	T10000001489-NCW-006B	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-006B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-006B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-006B		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

I29
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000067669**

Well ID:	T10000001489-NCW-006C	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-006C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-006C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-006C		

G30
SSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000092478**

Well ID:	SL209294204-PMW121(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW121(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW121(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW121(UB)		

G31
SSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000000612**

Well ID:	SL209294204-PMW121(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW121(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW121(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW121(A)		

H32
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000095519**

Well ID:	T0607310406-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H33
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000000712**

Well ID:	T0607310406-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-8		

I34
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000121466**

Well ID:	T10000001489-NCW-006A	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-006A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-006A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-006A		

F35
South
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000099614**

Well ID:	SL209294204-PMW123(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW123(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW123(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW123(UB)		

F36
South
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000122008**

Well ID:	SL209294204-PMW123(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW123(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW123(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW123(A)		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J37
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000084872**

Well ID:	SL209294204-MW-98-2B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-98-2B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=MW-98-2B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=MW-98-2B		

J38
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000034082**

Well ID:	SL209294204-MW-98-3B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-98-3B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=MW-98-3B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=MW-98-3B		

E39
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000137836**

Well ID:	SL209294204-PMW108(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW108(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW108(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW108(UB)		

G40
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000143625**

Well ID:	T10000001489-NCW-018	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-018
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-018&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-018		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J41
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000113906**

Well ID:	SL209294204-MW-98-1B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-98-1B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=MW-98-1B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=MW-98-1B		

J42
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000076753**

Well ID:	SL209294204-PMW109(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW109(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW109(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW109(UB)		

J43
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000136870**

Well ID:	SL209294204-PMW109(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW109(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW109(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW109(LB)		

H44
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000090478**

Well ID:	T0607310406-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F45
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000080135**

Well ID:	SL209294204-PMW110(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW110(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW110(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW110(A)		

F46
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000143525**

Well ID:	SL209294204-PMW110(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW110(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW110(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW110(UB)		

F47
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000098790**

Well ID:	SL209294204-PMW110(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW110(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW110(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW110(LB)		

H48
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000130209**

Well ID:	T0607310406-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H49
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000126951**

Well ID:	T0607310406-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-13		

H50
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000095069**

Well ID:	T0607310406-MW-24	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-24		

H51
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000016043**

Well ID:	T0607310406-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-9		

H52
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000003741**

Well ID:	T0607310406-MW-23	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-23
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-23&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-23		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H53
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000052014**

Well ID:	T0607310406-RW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	RW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=RW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=RW-2		

H54
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000011758**

Well ID:	T0607310406-RW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	RW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=RW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=RW-1		

H55
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000100606**

Well ID:	T0607310406-MW-21	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-21		

H56
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000080807**

Well ID:	T0607310406-RW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	RW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=RW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=RW-8		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H57
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000002848**

Well ID:	T0607310406-RW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	RW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=RW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=RW-3		

H58
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000118986**

Well ID:	T0607310406-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-10		

H59
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000040455**

Well ID:	T0607301869-MW-20	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-20
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-20&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-20		

H60
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000088277**

Well ID:	T0607301869-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-14		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K61
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000136269**

Well ID:	T0607301869-MW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-15		

H62
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000003960**

Well ID:	T0607310406-RW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	RW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=RW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=RW-5		

H63
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000138525**

Well ID:	T0607310406-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-6		

K64
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000088879**

Well ID:	T0607301869-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-11		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K65
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000040339**

Well ID:	T0607301869-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-12		

H66
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000022397**

Well ID:	T0607310406-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=MW-2		

H67
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000079194**

Well ID:	T0607310406-RW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	RW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607310406&assigned_name=RW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607310406&assigned_name=RW-7		

H68
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000051193**

Well ID:	T0607301884-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H69
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000093984**

Well ID:	T0607301886-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301886&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301886&assigned_name=MW-6		

K70
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000008594**

Well ID:	T0607301869-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-9		

K71
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000056819**

Well ID:	T0607301869-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-13		

K72
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000051991**

Well ID:	T0607301869-MW-19	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-19&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-19		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K73
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000135216**

Well ID:	T0607301869-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-10		

K74
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000081579**

Well ID:	T0607301869-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-8		

J75
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000054423**

Well ID:	SL209294204-PMW113(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW113(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW113(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW113(LB)		

K76
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000140002**

Well ID:	T0607301884-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=MW-5		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K77
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000042283**

Well ID:	T0607301886-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301886&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301886&assigned_name=MW-5		

L78
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000018227**

Well ID:	SL209294204-PMW113(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW113(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW113(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW113(A)		

L79
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000022305**

Well ID:	SL209294204-PMW113(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW113(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW113(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW113(UB)		

J80
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000041503**

Well ID:	SL209294204-PMW112(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW112(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW112(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW112(UB)		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J81
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000053146**

Well ID:	SL209294204-PMW112(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW112(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW112(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW112(LB)		

K82
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000037587**

Well ID:	T0607301869-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-7		

K83
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000067169**

Well ID:	T0607301869-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-6		

K84
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000010921**

Well ID:	T0607301869-MW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-16		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K85
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000079471**

Well ID:	T0607301886-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301886&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301886&assigned_name=MW-3		

K86
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000082455**

Well ID:	T0607301869-MW-18	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-18		

K87
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000083188**

Well ID:	T0607301886-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301886&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301886&assigned_name=MW-4		

K88
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000141359**

Well ID:	T0607301869-MW-21	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-21		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K89
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000137703**

Well ID:	T0607301869-MW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-17		

K90
ESE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000129706**

Well ID:	T0607301869-MW-24	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-24		

M91
NE
1/4 - 1/2 Mile
Higher

CA WELLS **CAUSGSN00016092**

Well ID:	USGS-323804117054701	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-323804117054701	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-323804117054701&store_num=		
GeoTracker Data:	Not Reported		

M92
NE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000129277**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	018S002W03P001S	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	California Coastal Basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19930920	Well Depth:	750
Well Depth Units:	ft	Well Hole Depth:	800
Well Hole Depth Units:	ft		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K93
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000078647**

Well ID:	T0607301886-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301886&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301886&assigned_name=MW-2		

K94
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000059786**

Well ID:	T0607301869-MW-22	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301869&assigned_name=MW-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301869&assigned_name=MW-22		

N95
North
1/4 - 1/2 Mile
Higher

CA WELLS **CAUSGSN00007088**

Well ID:	USGS-323808117060402	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-323808117060402	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-323808117060402&store_num=		
GeoTracker Data:	Not Reported		

N96
North
1/4 - 1/2 Mile
Higher

CA WELLS **CAUSGSN00004801**

Well ID:	USGS-323808117060401	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-323808117060401	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-323808117060401&store_num=		
GeoTracker Data:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

N97
North
1/4 - 1/2 Mile
Higher

CA WELLS **CAUSGSN00008715**

Well ID:	USGS-323808117060404	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-323808117060404	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-323808117060404&store_num=		
GeoTracker Data:	Not Reported		

N98
North
1/4 - 1/2 Mile
Higher

CA WELLS **CAUSGSN00000848**

Well ID:	USGS-323808117060406	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-323808117060406	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-323808117060406&store_num=		
GeoTracker Data:	Not Reported		

N99
North
1/4 - 1/2 Mile
Higher

CA WELLS **CAUSGSN00016734**

Well ID:	USGS-323808117060403	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-323808117060403	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-323808117060403&store_num=		
GeoTracker Data:	Not Reported		

N100
North
1/4 - 1/2 Mile
Higher

CA WELLS **CAUSGSN00017247**

Well ID:	USGS-323808117060405	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-323808117060405	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-323808117060405&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

K101
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000116581**

Well ID:	T0607301886-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301886&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301886&assigned_name=MW-1		

K102
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000037896**

Well ID:	T0607301884-TSG-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	TSG-MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=TSG-MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=TSG-MW-12		

O103
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000117285**

Well ID:	T10000001489-NCW-019	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-019
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-019&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-019		

P104
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000055812**

Well ID:	SL209294204-PMW111(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW111(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW111(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW111(UB)		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

P105
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000085899**

Well ID:	SL209294204-PMW111(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW111(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW111(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW111(LB)		

Q106
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000110021**

Well ID:	T0607301884-TSG-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	TSG-MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=TSG-MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=TSG-MW-8		

Q107
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000140286**

Well ID:	T0607301884-TSG-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	TSG-MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=TSG-MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=TSG-MW-11		

K108
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000119999**

Well ID:	T0607301884-TSG-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	TSG-MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=TSG-MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=TSG-MW-13		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q109
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000119823**

Well ID:	T0607301884-TSG-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	TSG-MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=TSG-MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=TSG-MW-9		

P110
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000102810**

Well ID:	SL209294204-PMW122(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW122(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW122(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW122(A)		

R111
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000091290**

Well ID:	T0607301090-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW7		

Q112
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000049959**

Well ID:	T0607301884-SE-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	SE-MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=SE-MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=SE-MW-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q113
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000118044**

Well ID:	T0607301884-SE-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	SE-MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=SE-MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=SE-MW-4		

P114
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000117064**

Well ID:	SL209294204-PMW122(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW122(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW122(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW122(UB)		

M115
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000005147**

Well ID:	T0607301090-MW9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW9		

S116
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000039333**

Well ID:	T10000001489-NCW-008B	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-008B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-008B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-008B		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

S117
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000035649**

Well ID:	T10000001489-NCW-008A	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-008A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-008A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-008A		

Q118
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000070921**

Well ID:	T0607301884-EW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	EW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=EW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=EW-4		

Q119
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000055540**

Well ID:	T0607301884-EW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	EW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=EW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=EW-2		

L120
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000099164**

Well ID:	SL209294204-PMW114(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW114(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW114(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW114(A)		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

S121
WSW
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000098940**

Well ID:	T10000001489-NCW-008C	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-008C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-008C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-008C		

Q122
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000046744**

Well ID:	T0607301884-EW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	EW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=EW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=EW-3		

Q123
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000002622**

Well ID:	T0607301884-EW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	EW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=EW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=EW-1		

T124
West
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000129510**

Well ID:	T10000001489-NCW-007A	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-007A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-007A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-007A		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

T125
West
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000092535**

Well ID:	T10000001489-NCW-007B	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-007B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-007B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-007B		

L126
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000096390**

Well ID:	SL209294204-PMW115(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW115(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW115(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW115(UB)		

127
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000072442**

Well ID:	SL209294204-PMW114(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW114(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW114(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW114(UB)		

M128
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000045651**

Well ID:	T0607301090-MW10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

M129
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000024007**

Well ID:	T0607301090-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW5		

Q130
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000002539**

Well ID:	T0607301884-EW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	EW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=EW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=EW-6		

Q131
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000078566**

Well ID:	T0607301884-TSG-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	TSG-MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=TSG-MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=TSG-MW-10		

Q132
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000121823**

Well ID:	T0607301884-EW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	EW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=EW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=EW-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

T133
West
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000126681**

Well ID:	T10000001489-NCW-007C	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-007C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-007C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-007C		

M134
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000018545**

Well ID:	T0607301090-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW2		

L135
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000058030**

Well ID:	SL209294204-PMW115(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW115(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW115(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW115(A)		

L136
SSE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000074736**

Well ID:	SL209294204-PMW115(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW115(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW115(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW115(LB)		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database | EDR ID Number

Q137
East
1/4 - 1/2 Mile
Higher

AQUIFLOW **37957**

Site ID:	Not Reported
Groundwater Flow:	SW
Shallow Water Depth:	Not Reported
Deep Water Depth:	Not Reported
Average Water Depth:	15
Date:	09/18/1995

M138
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000059346**

Well ID:	T0607301090-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW3		

M139
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000012099**

Well ID:	T0607301090-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW1		

Q140
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000009061**

Well ID:	T0607301884-SE-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	SE-MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=SE-MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=SE-MW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O141
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000078512**

Well ID:	T10000001489-NCW-009C	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-009C
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-009C&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-009C		

O142
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000085952**

Well ID:	T10000001489-NCW-009A	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-009A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-009A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-009A		

O143
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000111346**

Well ID:	T10000001489-NCW-009B	Well Type:	MONITORING
Source:	EDF	Other Name:	NCW-009B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000001489&assigned_name=NCW-009B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000001489&assigned_name=NCW-009B		

M144
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000121572**

Well ID:	T0607301090-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

P145
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000034678**

Well ID:	SL209294204-PMW117(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW117(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW117(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW117(UB)		

P146
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000122712**

Well ID:	SL209294204-PMW117(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW117(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW117(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW117(LB)		

Q147
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000047852**

Well ID:	T0607301884-SE-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	SE-MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=SE-MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=SE-MW-3		

Q148
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000060906**

Well ID:	T0607301884-SE-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	SE-MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=SE-MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=SE-MW-5		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q149
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000101027**

Well ID:	T0607302991-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=MW-12		

Q150
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000048218**

Well ID:	T0607301884-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=MW-12		

P151
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000041123**

Well ID:	SL209294204-PMW117(A)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW117(A)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW117(A)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW117(A)		

Q152
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000095184**

Well ID:	T0607302991-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=MW-10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q153
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000125791**

Well ID:	T0607301884-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=MW-10		

R154
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000057163**

Well ID:	T0607301090-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW8		

Q155
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000122756**

Well ID:	T0607302991-RS-7	Well Type:	MONITORING
Source:	EDF	Other Name:	RS-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=RS-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=RS-7		

Q156
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000047451**

Well ID:	T0607301884-RS-7	Well Type:	MONITORING
Source:	EDF	Other Name:	RS-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=RS-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=RS-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q157
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000143005**

Well ID:	T0607302991-RS-8	Well Type:	MONITORING
Source:	EDF	Other Name:	RS-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=RS-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=RS-8		

Q158
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000059455**

Well ID:	T0607301884-RS-8	Well Type:	MONITORING
Source:	EDF	Other Name:	RS-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=RS-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=RS-8		

U159
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000061482**

Well ID:	SL209294204-PMW116(UB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW116(UB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW116(UB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW116(UB)		

Q160
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000117337**

Well ID:	T0607302991-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=MW-11		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q161
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000105553**

Well ID:	T0607301884-SE-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	SE-MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=SE-MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=SE-MW-6		

Q162
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000064238**

Well ID:	T0607301884-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=MW-11		

Q163
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000103685**

Well ID:	T0607302991-RS-9	Well Type:	MONITORING
Source:	EDF	Other Name:	RS-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=RS-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=RS-9		

U164
South
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000064335**

Well ID:	SL209294204-PMW116(LB)	Well Type:	MONITORING
Source:	EDF	Other Name:	PMW116(LB)
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW116(LB)&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW116(LB)		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

R165
NNE
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000115183**

Well ID:	T0607301090-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301090&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301090&assigned_name=MW6		

Q166
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000109106**

Well ID:	T0607302991-RE-4	Well Type:	MONITORING
Source:	EDF	Other Name:	RE-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=RE-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=RE-4		

Q167
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000064001**

Well ID:	T0607301884-RE-4	Well Type:	MONITORING
Source:	EDF	Other Name:	RE-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=RE-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=RE-4		

Q168
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000103584**

Well ID:	T0607302991-RE-6	Well Type:	MONITORING
Source:	EDF	Other Name:	RE-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=RE-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=RE-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q169
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000066014**

Well ID:	T0607301884-RE-6	Well Type:	MONITORING
Source:	EDF	Other Name:	RE-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=RE-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=RE-6		

V170
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000056127**

Well ID:	T0607301884-RE-3	Well Type:	MONITORING
Source:	EDF	Other Name:	RE-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=RE-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=RE-3		

V171
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000043968**

Well ID:	T0607302991-RE-3	Well Type:	MONITORING
Source:	EDF	Other Name:	RE-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302991&assigned_name=RE-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302991&assigned_name=RE-3		

Q172
East
1/4 - 1/2 Mile
Higher

AQUIFLOW **33954**

Site ID:	9UT728
Groundwater Flow:	W
Shallow Water Depth:	20
Deep Water Depth:	22
Average Water Depth:	Not Reported
Date:	05/17/1993

V173
East
1/4 - 1/2 Mile
Higher

CA WELLS **CAEDF0000076042**

Well ID:	T0607301884-TSG-MW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	TSG-MW-15

GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301884&assigned_name=TSG-MW-15&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301884&assigned_name=TSG-MW-15

174
SSE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000127347**

Well ID: SL209294204-PMW118(UB) Well Type: MONITORING
Source: EDF Other Name: PMW118(UB)
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW118(UB)&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW118(UB)

175
SSE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000133674**

Well ID: SL209294204-PMW119(UB) Well Type: MONITORING
Source: EDF Other Name: PMW119(UB)
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SL209294204&assigned_name=PMW119(UB)&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SL209294204&assigned_name=PMW119(UB)

W176
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000035168**

Well ID: T0607302590-MW9 Well Type: MONITORING
Source: EDF Other Name: MW9
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302590&assigned_name=MW9&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302590&assigned_name=MW9

W177
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000106376**

Well ID: T0607302590-MW4 Well Type: MONITORING
Source: EDF Other Name: MW4
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302590&assigned_name=MW4&store_num=

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302590&assigned_name=MW4

W178
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000093236**

Well ID:	T0607302590-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302590&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302590&assigned_name=MW2		

W179
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000003553**

Well ID:	T0607302590-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302590&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302590&assigned_name=MW6		

W180
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000002918**

Well ID:	T0607302590-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302590&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302590&assigned_name=MW7		

W181
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000059100**

Well ID:	T0607302590-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302590&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302590&assigned_name=MW5		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

			Database	EDR ID Number
182 **NNE** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	9UT403 Not Reported 3.7 20.7 Not Reported 02/18/1993	**AQUIFLOW**	**33972**

W183
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000089777**

Well ID:	T0607302590-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302590&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302590&assigned_name=MW8		

W184
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000053463**

Well ID:	T0607302590-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302590&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302590&assigned_name=MW3		

			Database	EDR ID Number
185 **ENE** **1/2 - 1 Mile** **Higher**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	9UT973 W 15 20 Not Reported 08/10/1988	**AQUIFLOW**	**33961**

X186
NE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000071152**

Well ID:	T0607391332-DW4	Well Type:	MONITORING
Source:	EDF	Other Name:	DW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391332&assigned_name=DW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391332&assigned_name=DW4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

X187
NE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000032052**

Well ID:	T0607391332-DW1	Well Type:	MONITORING
Source:	EDF	Other Name:	DW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391332&assigned_name=DW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391332&assigned_name=DW1		

X188
NE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000070255**

Well ID:	T0607391332-DW3	Well Type:	MONITORING
Source:	EDF	Other Name:	DW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391332&assigned_name=DW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391332&assigned_name=DW3		

X189
NE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000059160**

Well ID:	T0607391332-DW2	Well Type:	MONITORING
Source:	EDF	Other Name:	DW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391332&assigned_name=DW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391332&assigned_name=DW2		

Y190
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000142196**

Well ID:	T0607301832-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-13		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Y191
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000127100**

Well ID:	T0607301832-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-12		

Z192
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000121954**

Well ID:	T0607300695-MW-18	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-18		

Z193
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000020134**

Well ID:	T0607300695-MW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-17		

Z194
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000040344**

Well ID:	T0607300695-MW-21	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-21		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Z195
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000061047**

Well ID:	T0607300695-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-12		

Y196
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000011697**

Well ID:	T0607301832-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-11		

Y197
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000081394**

Well ID:	T0607301832-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-7		

Y198
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000140426**

Well ID:	T0607301832-MW-18	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-18		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Z199
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000083841**

Well ID:	T0607300695-MW-25	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-25
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-25&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-25		

Z200
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000012685**

Well ID:	T0607300695-MW-24	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-24		

Y201
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000128578**

Well ID:	T0607301832-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-3		

Y202
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000044000**

Well ID:	T0607301832-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Y203
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000008793**

Well ID:	T0607301832-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-2		

Y204
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000015272**

Well ID:	T0607301832-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-8		

Z205
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000090210**

Well ID:	T0607300695-MW-19	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-19&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-19		

Z206
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000139315**

Well ID:	T0607300695-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Z207
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000109072**

Well ID:	T0607300695-MW-22	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-22		

Z208
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000000723**

Well ID:	T0607300695-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-13		

Z209
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000133917**

Well ID:	T0607300695-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-4		

Y210
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000019980**

Well ID:	T0607301832-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Y211
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000089990**

Well ID:	T0607301832-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-14		

Z212
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000102819**

Well ID:	T0607300695-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-3		

Z213
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000122428**

Well ID:	T0607300695-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-9		

Z214
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000073004**

Well ID:	T0607300695-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-14		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Y215
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000051456**

Well ID:	T0607301832-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-1		

Z216
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000088089**

Well ID:	T0607300695-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-2		

Z217
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000066409**

Well ID:	T0607300695-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-8		

Z218
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000131984**

Well ID:	T0607300695-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Z219
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000060321**

Well ID:	T0607300695-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-1		

Y220
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000086893**

Well ID:	T0607301832-DW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	DW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=DW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=DW-15		

Z221
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000044683**

Well ID:	T0607300695-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-5		

Y222
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000130710**

Well ID:	T0607301832-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=MW-10		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Z223
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000007359**

Well ID:	T0607300695-MW-23	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-23
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-23&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-23		

Z224
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000062632**

Well ID:	T0607300695-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-7		

AA225
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000120070**

Well ID:	T0607301832-DW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	DW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=DW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=DW-16		

Z226
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000110879**

Well ID:	T0607300695-MW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-15		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Z227
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000004968**

Well ID:	T0607300695-MW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300695&assigned_name=MW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300695&assigned_name=MW-16		

AA228
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000054714**

Well ID:	T0607301832-DW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	DW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301832&assigned_name=DW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301832&assigned_name=DW-17		

AA229
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000084476**

Well ID:	T0607302451-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302451&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302451&assigned_name=MW2		

AA230
ESE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000062606**

Well ID:	T0607302451-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302451&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302451&assigned_name=MW3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AB231
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000096792**

Well ID:	T0607301341-MW-21	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-21		

AB232
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000007253**

Well ID:	T0607301341-MW-18	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-18		

AC233
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000046930**

Well ID:	T0607301341-MW-19	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-19&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-19		

AB234
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000103782**

Well ID:	T0607301341-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-14		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AB235
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000002186**

Well ID:	T0607301341-MW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-15		

AB236
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000039033**

Well ID:	T0607301341-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-7		

AB237
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000050726**

Well ID:	T0607301341-MW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-16		

AB238
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000020355**

Well ID:	T0607301341-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-8		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

AC239
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000011109**

Well ID:	T0607301341-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-13		

AC240
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000078660**

Well ID:	T0607301341-MW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-17		

AD241
ENE
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000091010**

Well ID:	T0607301341-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-3		

AD242
East
1/2 - 1 Mile
Higher

CA WELLS **CAEDF0000064384**

Well ID:	T0607301341-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-6		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

		Database	EDR ID Number
AD243 **ENE** **1/2 - 1 Mile** **Higher**		**CA WELLS**	**CAEDF0000014666**

Well ID:	T0607301341-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301341&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301341&assigned_name=MW-4		

1G **NNE** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	9UT403 Not Reported 3.7 20.7 Not Reported 02/18/1993	**AQUIFLOW**	**33972**

2G **ENE** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	9UT973 W 15 20 Not Reported 08/10/1988	**AQUIFLOW**	**33961**

3G **East** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	9UT728 W 20 22 Not Reported 05/17/1993	**AQUIFLOW**	**33954**

4G **East** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	Not Reported SW Not Reported Not Reported 15 09/18/1995	**AQUIFLOW**	**37957**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
91910	20	2

Federal EPA Radon Zone for SAN DIEGO County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for SAN DIEGO COUNTY, CA

Number of sites tested: 30

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.677 pCi/L	100%	0%	0%
Living Area - 2nd Floor	0.400 pCi/L	100%	0%	0%
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

OTHER STATE DATABASE INFORMATION

Groundwater Ambient Monitoring & Assessment Program
State Water Resources Control Board
Telephone: 916-341-5577
The GAMA Program is Californias comprehensive groundwater quality monitoring program. GAMA collects data by testing the untreated, raw water in different types of wells for naturally-occurring and man-made chemicals. The GAMA data includes Domestic, Monitoring and Municipal well types from the following sources, Department of Water Resources, Department of Heath Services, EDF, Agricultural Lands, Lawrence Livermore National Laboratory, Department of Pesticide Regulation, United States Geological Survey, Groundwater Ambient Monitoring and Assessment Program and Local Groundwater Projects.

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Public Health
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

California Oil and Gas Well Locations
Source: Dept of Conservation, Geologic Energy Management Division
Telephone: 916-323-1779
Oil and Gas well locations in the state.

California Earthquake Fault Lines
Source: California Division of Mines and Geology
The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

RADON

State Database: CA Radon
Source: Department of Public Health
Telephone: 916-210-8558
Radon Database for California

PHYSICAL SETTING SOURCE RECORDS SEARCHED

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GOODRICH CORP. DBA ROHR INC
H (FOOT OF) ST
CHULA VISTA, CA 91910

Inquiry Number:
February 3, 2021

EDR Site Report™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

The EDR-Site Report™ is a comprehensive presentation of government filings on a facility identified in a search of federal, state and local environmental databases.

Section 1: Facility Detail Reports . . . . . Page 3

All available detailed information from databases where sites are identified.

Section 2: Databases and Update Information. . . . . Page 186

Name, source, update dates, contact phone number and description of each of the databases for this report.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources , Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assesment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SECTION 1: FACILITY DETAIL REPORTS

GOODRICH CORP. DBA ROHR INC
H (FOOT OF) ST
CHULA VISTA, CA 91910
EDR ID #S123406599

Databases:
HMMD SAN DIEGO: Hazardous Materials Management Division Database

HMMD SAN DIEGO:

Name:	GOODRICH CORP. DBA ROHR INC
Address:	H (FOOT OF) ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	102457
Business Type:	6HK49
EPA Id Number:	CAD008382053
APN:	567-022-01-00
Last HMMD Inspection:	06/10/2010
Facility Telephone:	619-691-4111
Permit Status:	OPEN
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	GOODRICH CORP. DBA ROHR INC
Facility Mailing Address:	850 LAGOON DRIVE
Facility Mailing City:	CHULA VISTA
Facility Mailing State:	CA
Facility Mailing Zip:	91910-2098
UST Owner:	ROHR INDUSTRIES INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Y
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	102457
Update Date:	11/02/2012
Case Number:	10102-44-0
Name:	0.45% NITROGEN DIOXIDE IN NITROGEN CALIBRATION GAS
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102457
Update Date:	11/02/2012
Case Number:	67-64-1
Name:	ACETONE
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	102457
Update Date:	11/02/2012
Case Number:	68815-10-1
Name:	ALIPHATIC PETROLEUM OIL
Other Information:	BRAYCO MICRONIC 882
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	102457
Update Date:	11/02/2012
Case Number:	7727-37-9
Name:	ANTENSLB NITROGEN LIQUID AIR
Other Information:	NITROGEN LIQUID AIR
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported

Permit Number:	102457
Update Date:	11/02/2012
Case Number:	7632-00-0
Name:	AQUA QUCNCH 251-B
Other Information:	SODIUM MITRATE SOLUTION
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	102457
Update Date:	11/02/2012

Case Number: 7632-00-0
Name: AQUAQUENCH INHIBITOR 211
Other Information: SODIUM NITRITE SOLUTION
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 312 NEXTEL CERAMIC FIBER
Other Information: 312 NEXTEL CERAMIC FIBER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 321-N
Other Information: 321-N
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: BLDG-001 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-001 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-001 ALODINE 1500 LIQUID
Other Information: ALODINE 1500 LIQUID
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ALUMINUX
Other Information: ALUMINUX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: BLDG-001 AMMONIUM BIFLUORIDE-F
Other Information: AMMONIUM BIFLUORIDE-F
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: BLDG-001 AQUA QUENCH 251 LUBE/COOLANT
Other Information: AQUA QUENCH 251 LUBE/COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ATM-2000-X1 FUSED SILICA
Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-88-0
Name: BLDG-001 AZ 644-10 LOT WR ACRYLIC EMULSION/CARBOXYLATED
Other Information: AZ 644-10 LOT WR ACRYLIC EMULSION/CARBOXYLATED
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 124-38-9
Name: BLDG-001 CARBON DIOXIDE, REFRIGERATED LIQUID
Other Information: CARBON DIOXIDE, REFRIGERATED LIQUID
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-001 CAUSTIC SODA 50% LIQUID
Other Information: CAUSTIC SODA 50% LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: BLDG-001 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-47-8
Name: BLDG-001 CROWN DEODERIZED KEROSENE/OIL BASE DSB/AKA CHEV
Other Information: CROWN DEODERIZED KEROSENE/OIL BASE DSB/AKA CHEV
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 DRAW TEMP 430
Other Information: DRAW TEMP 430

Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 FYRQUEL 220
Other Information: FYRQUEL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 GMC 528-B
Other Information: GMC 528-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 111-76-2
Name: BLDG-001 GMC 528-B METAL CLEANER
Other Information: GMC 528-B METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: BLDG-001 HOUGHTO-DRAW 650 LUBRICANT
Other Information: HOUGHTO-DRAW 650 LUBRICANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7647-01-0
Name: BLDG-001 HYDROCHLORIC ACID
Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 JETTACIN
Other Information: JETTACIN
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-001 KEROSENE DEODORIZED
Other Information: KEROSENE DEODORIZED
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-001 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 LIQUID ARGON
Other Information: LIQUID ARGON
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52
Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: BLDG-001 MAGNAFLUX/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUX/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: BLDG-001 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: BLDG-001 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-56-1
Name: BLDG-001 METHYL ALCOHOL

Other Information: METHYL ALCOHOL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE 24 OIL
Other Information: MOBIL DTE 24 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE OIL EXTRA HEAVY
Other Information: MOBIL DTE OIL EXTRA HEAVY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL MIST LUBE #27
Other Information: MOBIL MIST LUBE #27
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VACTRA OIL NO. 2
Other Information: MOBIL VACTRA OIL NO. 2
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-85-4
Name: BLDG-001 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VACUOLINE 1405 OIL
Other Information: MOBIL VACUOLINE 1405 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL VACUOLINE 1409 OIL
Other Information: MOBIL VACUOLINE 1409 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VELOCITE OIL NO 6
Other Information: MOBIL VELOCITE OIL NO 6
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID BULK
Other Information: NITRIC ACID BULK
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-001 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 497-19-8
Name: BLDG-001 OAKITE LOW HEAT CLEANER 1 CLEANER
Other Information: OAKITE LOW HEAT CLEANER 1 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-9

Name: BLDG-001 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: BLDG-001 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SCA 636
Other Information: SCA 636
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SHELL SOL 340 HT
Other Information: SHELL SOL 340 HT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-001 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SODIUM HYDROSULFIDE SOLID
Other Information: SODIUM HYDROSULFIDE SOLID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-001 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: BLDG-001 TECTYL 802A/MIL-L-3150 A9944 LUBE
Other Information: TECTYL 802A/MIL-L-3150 A9944 LUBE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 75-09-2
Name: BLDG-001 TURCO 5351 CLEANER/STRIPPER
Other Information: TURCO 5351 CLEANER/STRIPPER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 6834-92-0
Name: BLDG-001 TURCO HTC METAL CLEANER
Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO PRETREAT
Other Information: TURCO PRETREAT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 V LUBE B
Other Information: V LUBE B
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-92-2
Name: BLDG-001 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: BLDG-001 WITHROW X49 DRAWING COMPOUND
Other Information: WITHROW X49 DRAWING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-001 ZL-66A ZYGLO WATER WASHABLE PENETRANT
Other Information: ZL-66A ZYGLO WATER WASHABLE PENETRANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012

Case Number: 7440-37-1
Name: BLDG-003 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-003 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-003 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-003 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-85-4
Name: BLDG-005 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-98-6
Name: BLDG-009 LPG GAS
Other Information: LPG GAS - PROPANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-011 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-011 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-011 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-019 ARGON
Other Information: ARAGON
Material Waste: Material

Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-019 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-019 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-21-1
Name: BLDG-025 ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Other Information: ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-025 UNLEADED FUEL BULK
Other Information: UNLEADED FUEL BULK
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 1-8% OXYGEN IN ARGON
Other Information: 1-8% OXYGEN IN ARGON
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 7544/139
Other Information: 7544/139
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-029 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-029 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-029 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-029 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ARGON AIR PRODUCT
Other Information: ARGON AIR PRODUCT
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 AS-150 ANTI-SLIP COATING 440
Other Information: AS-150 ANTI-SLIP COATING 440
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 DOK DEODORIZED KERONSENE
Other Information: DOK DEODORIZED KERONSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 FR-5317-W EPOXY RESIN
Other Information: FR-5317-W EPOXY RESIN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 25068-38-6
Name: BLDG-029 FR-5317-W EPOXY RESIN SYSTEM
Other Information: FR-5317-W EPOXY RESIN SYSTEM
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-029 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-029 NITROGEN
Other Information: NITROGEN

Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-029 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-029 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-029 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ULTRACAL 30
Other Information: ULTRACAL 30
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-88-4
Name: BLDG-029 UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Other Information: UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-030 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-030 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 ACETONE UNION CARBIDE
Other Information: ACETONE UNION CARBIDE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 DOK DEODORIZED KEROSENE
Other Information: DOK DEODORIZED KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 HELIUM MG
Other Information: HELIUM MG
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 ISOPROPYL ALCOHOL UNION
Other Information: ISOPROPYL ALCOHOL UNION
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 ROHR BLEND #1
Other Information: ROHR BLEND #1
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 SHELL SOL 340 HT
Other Information: SHELL SOL 340 HT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-032 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-032 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-032 ARGON LIQUID AIR

Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG--032 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: BLDG-036 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-036 DOK DEORDORIZED KEROSENE
Other Information: DOK DEORDORIZED KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-036 LIQUID NITROGEN
Other Information: LIQUID NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-036 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1
Name: BLDG-036 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-53-6
Name: BLDG-036 SOLVOL 6582 COOLANT
Other Information: SOLVOL 6582 COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-211-1
Name: BLDG-038 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-038 MOBIL DELVAC 1230
Other Information: MOBIL DELVAC 1230
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-040 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 321-N
Other Information: 321-N
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: BLDG-045 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-045 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-045 ALODINE 1500 LIQUID
Other Information: ALODINE 1500 LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 ALUMINUX
Other Information: ALUMINUX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Other Information: ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7

Name: BLDG-045 AMMONIUM BIFLUORIDE-F
Other Information: AMMONIUM BIFLUORIDE-F
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-045 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-045 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 CAUSTIC SODA 50% LIQUID
Other Information: CAUSTIC SODA 50% LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7778-50-9
Name: BLDG-045 DEOXIDIZER 17 REPLENISHER
Other Information: DEOXIDIZER 17 REPLINISHER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 DEOXIDIZER 7 MAKE-UP
Other Information: DEOXIDIZER 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 EPOXY PRIMER 10P4-16
Other Information: EPOXY PRIMER 10P4-16
Material Waste: Material
Hazardous Categories 1: FIRE

Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 GMC 528-B
Other Information: GMC 528-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 111-76-2
Name: BLDG-045 GMC 528-B METAL CLEANER
Other Information: GMC 528-B METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7647-01-0
Name: BLDG-045 HYDROCHLORIC ACID
Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-39-3
Name: BLDG-045 HYDROFLUORIC ACID 49%
Other Information: HYDROFLUORIC ACID 49%
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 KLEENSWEEP WAX BASE 1320
Other Information: KLEENSWEEP WAX BASE 1320
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012

Case Number: 78-93-3
Name: BLDG-045 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NA9194 DEOXID 7 MAKE-UP
Other Information: NA9194 DEOXID 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NABC NON-ACID BATH CLNR
Other Information: NABC NON-ACID BATH CLNR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NITRIC ACID BULK
Other Information: NITRIC ACID BULK
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 497-19-8
Name: BLDG-045 OAKITE LOW HEAT CLEANER 1 CLEANER
Other Information: OAKITE LOW HEAT CLEANER 1 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-045 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: BLDG-045 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material

Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 SCA 636
Other Information: SCA 636
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-045 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 SODIUM HYDROSULFIDE SOLID
Other Information: SODIUM HYDROSULFIDE SOLID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-045 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: BLDG-045 TT-L-32A AM1 TYPE 2 17875 INS WHT/5432320078750
Other Information: TT-L-32A AM1 TYPE 2 17875 INS WHT/5432320078750
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 75-09-2
Name: BLDG-045 TURCO 5351 CLEANER/STRIPPER
Other Information: TURCO 5351 CLEANER/STRIPPER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 6834-92-0
Name: BLDG-045 TURCO HTC METAL CLEANER
Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO PRETREAT
Other Information: TURCO PRETREAT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-045 ZL-66A ZYGLO WATER WASHABLE PENETRANT
Other Information: ZL-66A ZYGLO WATER WASHABLE PENETRANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-048 KEROSENE
Other Information: KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-050 ATM-2000-X1 FUSED SILICA
Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-92-2
Name: BLDG-050 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-054 OXYGEN BULK LIQUID
Other Information: OXYGEN BULK LIQUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-054 PROPANE
Other Information: PROPANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-055 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B

Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-055 ARGON GENERIC
Other Information: ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-058 ELECTRO-OX
Other Information: ELECTRO-OX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-058 GARNET SAND
Other Information: GARNET SAND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: BLDG-058 GARNET SAND 60 GRIT
Other Information: GARNET SAND 60 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 LIQUID ARGON GENERIC
Other Information: LIQUID ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 2528-36-1
Name: BLDG-061 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500 B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-067 ARGON AIR PROD
Other Information: ARGON AIR PROD
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-067 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 2528-36-1
Name: BLDG-067 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-068 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-070 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-070 OXYGEN LIQUID
Other Information: LIQUID OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-081 SAFESTEP SORBENT
Other Information: SAFESTEP SORBENT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-085 ALODINE 1200R LIQUID
Other Information: ALODINE 1200R LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 77-92-9
Name: BLDG-085 ANHYDROUS CITRIC ACID, U.S.P.F.C.C.
Other Information: ANHYDROUS CITRIC ACID, U.S.P. F.C.C.
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10043-35-3
Name: BLDG-085 BORIC ACID

Other Information: BORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-085 DEOXIDIZER 7 MAKE-UP
Other Information: DEOXIDIZER 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-085 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-085 WCD 315L INHIBITOR/DISPERSANT-SODIUM BICHROM
Other Information: WCD 315L INHIBITOR/DISPERSANT-SODIUM BICHROM
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 ALODINE 1500 HENKEL
Other Information: ALODINE 1500 HENKEL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 AQUA QUENCH 260-B
Other Information: AQUA QUENCH 260-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-092 CAUSTIC SODA
Other Information: CAUSTIC SODA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 HOUGHTO-DRAW 650
Other Information: HOUGHTO-DRAW 650
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-90-5
Name: BLDG-092 SODIUM BISULFITE
Other Information: SODIUM BISULFITE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-092 SULFURIC ACID
Other Information: SULFURIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-092 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-098 FLOOR DRY
Other Information: FLOOR DRY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-41-7
Name: BLDG-099 ANHYDROUS AMMONIA
Other Information: ANHYDROUS AMMONIA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: BLDG-114 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-114 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-114 CARBON DIOXIDE
Other Information: CARBON DIOXIDE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-114 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-114 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1

Name: BLDG-310 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1
Name: BLDG-311 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: BLDG-341 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDSG-001 LUBRICOOLANT 2050AC
Other Information: LUBRICOOLANT 2050AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLSG-029 D-STROY
Other Information: D-STROY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-21-1
Name: CMST- 002 HOUGHTO-SAFE 620 HYDRAULIC SYSTEMS FLUID
Other Information: HOUGHTO-SAFE 620 HYDRAULIC SYSTEMS FLUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: CMST-001 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: CMST-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: CMST-001 CHEVRON SOLUBLE OIL B
Other Information: CHEVRON SOLUBLE OIL B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-001 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: CMST-001 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: CMST-001 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-001 LIQUID NITROGEN
Other Information: LIQUID NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: CMST-002 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7732-18-5
Name: CMST-002 ACTIVOL 1357 WETTING AGENT
Other Information: ACTIVOL 1357 WETTING AGENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 141-43-5
Name: CMST-002 CEE BEE A276 COATING REMOVER (55 GAL DRUMS) ST
Other Information: CEE BEE A276 COATING REMOVER (55 GAL DRUMS)ST
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: CMST-002 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012

Case Number: 107-21-1
Name: CMST-002 ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Other Information: ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-63-0
Name: CMST-002 ISOPROPANOL, ANHYDROUS
Other Information: ISOPROPANOL, ANHYDROUS
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: CMST-002 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL DELVAC SAE 30 OIL
Other Information: MOBIL DELVAC SAE 30 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL DTE 24 OIL
Other Information: MOBIL DTE 24 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL HYDRAULIC OIL 220
Other Information: MOBIL HYDRAULIC OIL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL MULTI-PURPOSE ATF OIL
Other Information: MOBIL MULTI-PURPOSE ATF OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL VACUOLINE 1405 OIL
Other Information: MOBIL VACUOLINE 1405 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL VELOCITE OIL NO 6
Other Information: MOBIL VELOCITE OIL NO 6
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBILUBE HD 80W-90 GEAR LUBE
Other Information: MOBILUBE HD 80W-90 GEAR LUBE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8052-41-3
Name: CMST-002 SOLVENT M-4 (CLEANING, COMPOUND LIQUID)
Other Information: SOLVENT M-4 (CLEANING, COMPOUND LIQUID)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68477-31-6
Name: CMST-002 TURCO 4460 SOLVENT
Other Information: TURCO 4460 SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: CMST-002 VINYL MODIFIED CASTOR OIL CODE H2006
Other Information: VINYL MODIFIED CASTOR OIL CODE H2006
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: CMST-003 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: CMST-003 AQUA QUENCH 251 LUBE/COOLANT
Other Information: AQUA QUENCH 251 LUBE/COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: CMST-003 HOUGHTO-DRAW 650 LUBRICANT
Other Information: HOUGHTO-DRAW 650 LUBRICANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: CMST-003 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: CMST-003 PENRECO AMBER (PETROLATUM)
Other Information: PENRECO AMBER (PETROLATUM) CODE 4510
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 7664-93-9
Name: CMST-003 SULFURIC ACID 66 DEG BE
Other Information: SULFURIC ACID 66 DEG BE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-92-2
Name: CMST-003 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 6834-92-0
Name: CMST-004 TURCO HTC METAL CLEANER
Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-53-6
Name: CMST-005 SOLVOL 6582 COOLANT
Other Information: SOLVOL 6582 COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 1-8% OXYGEN IN ARGON
Other Information: 1-8% OXYGEN IN ARGON
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 7544/139
Other Information: 7544/139
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-815-0 THINNER
Other Information: AC-815-0 THINNER
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-850
Other Information: AC-850

Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ACTIVOL 1357
Other Information: ACTIVOL 1357
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ALODINE 1500 HENKEL
Other Information: ALODINE 1500 HENKEL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARDROX 180-B
Other Information: ARDROX 180-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARDROX 7050-W
Other Information: ARDROX 7050-W
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON AIR PROD
Other Information: ARGON AIR PROD
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON GENERIC
Other Information: ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AS-150 ANTI-SLIP COATING
Other Information: AS-150 ANTI-SLIP COATING
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ATM-2000-X1 FUSED SILICA
Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BLASOCUT 4000 STRONG
Other Information: BLASOCUT 4000 STRONG
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BORIC ACID US BORAX
Other Information: BORIC ACID US BORAX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BUCKEYE SHOPMASTER
Other Information: BUCKEYE SHOPMASTER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BUCKEYE SHOPMASTER RTU
Other Information: BUCKEYE SHOPMASTER RTU
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CASTING PLASTER REG
Other Information: CASTING PLASTER REG
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CEE BEE A-276

Other Information: CEE BEE A-276
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DIESEL FUEL BULK
Other Information: DIESEL FUEL BULK
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DRAW TEMP 430
Other Information: DRAW TEMP 430
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 D-STROY
Other Information: D-STROY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ELECTRO-OX
Other Information: ELECTRO-OX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FERROUS SULFATE HEPTAHYDR
Other Information: FERROUS SULFATE HEPTAHYDR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FORMULA 28
Other Information: FORMULA 28
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FYRQUEL 220
Other Information: FYRQUEL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HELIUM LIQUID AIR
Other Information: HELIUM LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HELIUM MG
Other Information: HELIUM MG
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HOUGHTO-SAFE 620
Other Information: HOUGHTO-SAFE 620
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HYDROCHLORIC ACID
Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 JETTACIN
Other Information: JETTACIN
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LIQUID ARGON GENERIC
Other Information: LIQUID ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported

Name: CMST-006 LIQUID CAUSTIC SODA 50%
Other Information: LIQUID CAUSTIC SODA 50%
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LIQUID HELIUM PRAXAIR
Other Information: LIQUID HELIUM PRAXAIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-006 LIQUID OXYGEN
Other Information: LIQUID OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1309-42-8
Name: CMST-006 MAGNESIUM HYDROXIDE SUS
Other Information: MAGNESIUM HYDROXIDE SUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MF ACID
Other Information: MF ACID
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DELVAC 1230
Other Information: MOBIL DELVAC 1230
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE OIL EXTRA HEAVY
Other Information: MOBIL DTE OIL EXTRA HEAVY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL STE 24
Other Information: MOBIL DTE 24
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACTRA OIL NO. 2
Other Information: MOBIL VACTRA OIL NO. 2
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACUOLINE 1409 OIL
Other Information: MOBIL VACUOLINE 1409 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBILMET OMEGA
Other Information: MOBILMET OMEGA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 NABC NON-ACID BATH CLNR
Other Information: NABC NON-ACID BATH CLNR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 NITRIC ACID BULK
Other Information: NITRIC ACID BULK
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-006 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012

Case Number: Not reported
Name: CMST-006 OXYGEN MG
Other Information: OXYGEN MG
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 PROPANE
Other Information: PROPANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ROHR BLEND #1
Other Information: ROHR BLEND #1
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SODIUM BISULFITE
Other Information: SODIUM BISULFITE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SODIUM HYPOCHLORITE 12.5%
Other Information: SODIUM HYPOCHLORITE 12.5%
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO 5351
Other Information: TURCO 5351
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ULTRACAL 30
Other Information: ULTRACAL 30
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 V LUBE B
Other Information: V LUBE B
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: BLDG 118 COGENERATION PLANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 103-24-2
Name: DIOCTYL AZELATE
Other Information: QUINSYN COMPRESSOR OIL
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL - COOLANT
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, METAL CHIPS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, METAL CHIPS IN COOLANT
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, RINSE WATER FROM CHEM PROCESS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, X-RAY FIXER SOLUTION
Other Information: RECYCLABLE SILVER SALTS IN SOLUTION
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 7783-06-4
Name: HYDROGEN SULFIDE, 25 PPM IN NONFLAMMABLE CALIBRATION GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68037-01-4
Name: LUBRIPLATE SYNLUBE HD 220
Other Information: 1-DECENE, HOMOPOLYMER, HYDROGENATED
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: MF ACID
Other Information: AMMONIUM BIFLUORIDE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-54-7
Name: MOBIL DTE 25
Other Information: PETROLEUM LUBRICANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: MOBILGEAR 600 XP 150
Other Information: BASE OIL & ADDITIVES
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: MOBILGREASE XHP 005
Other Information: BASE OIL & ADDITIVES
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10024-97-2
Name: NITROUS OXIDE
Other Information: LAUGHING GAS
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: PEGASUS 1005 NATURAL GAS ENGINE OIL
Other Information: PETROLEUM OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: MIXTURE
Name: PT2114
Other Information: WHITE EPOXY LAMINATING RESIN
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 541-02-6
Name: QSOL 300 LOW VOC SOLVENT
Other Information: DECAMETHYLCYCLOPENTASILOSANE

Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: SHED 415 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: SHED 415 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: SHED-327 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7732-18-5
Name: SHED-327 ACTIVOL 1357 WETTING AGENT
Other Information: ACTIVOL 1357 WETTING AGENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: SHED-327 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-63-0
Name: SHED-327 ISOPROPANOL, ANHYDROUS
Other Information: ISOPROPANOL, ANHYDROUS
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: SHED-327 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68477-31-6
Name: SHED-327 TURCO 4460 SOLVENT
Other Information: TURCO 4460 SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-88-4
Name: SHED-327 UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Other Information: UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

SECTION 1: FACILITY DETAIL REPORTS

...Continued...

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 111-76-2
Name: SHED-356 321-N COATING
Other Information: 321-N COATING
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: SHED-356 ABRASIVE GARNET SAND 60-80 GRIT
Other Information: ABRASIVE GARNET SAND 60-80 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: SHED-356 ABRASIVE GRIT GARNET SAND BAC 5748 150 GRIT
Other Information: ABRASIVE GRIT GARNET SAND BAC 5748 150 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: SHED-356 ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Other Information: ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: SHED-356 AMMONIUM BIFLUORIDE
Other Information: AMMONIUM BIFLUORIDE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 471-34-1
Name: SHED-356 CALCIUM CARBONATE
Other Information: CALCIUM CARBONATE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: SHED-356 DEOXIDIZER 17 REPLENISHER
Other Information: DEOXIDIZER 17 REPLENISHER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1344-28-1
Name: SHED-356 FUSED ALUMINUM OXIDE 240 GRIT
Other Information: FUSED ALUMINUM OXIDE 240 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1344-28-1
Name: SHED-356 FUSED ALUMINUM OXIDE 46 GRIT
Other Information: FUSED ALUMINUM OXIDE 46 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 56550-16-0
Name: SHED-356 FYRQUEL 220 (FIRE RESISTANT HYDRAULIC FLUID)

Other Information: FYRQUEL 220 (FIRE RESISTANT HYDRAULIC FLUID)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: SHED-356 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: SHED-356 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 2528-36-1
Name: SHED-356 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: SHED-356 TECTYL 802A/MIL-L-3150 A9944 LUBE
Other Information: TECTYL 802A/MIL-L-3150 A9944 LUBE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-88-3
Name: SHED-356 TURCO PRETREAT SCALE INHIBITOR
Other Information: TURCO PRETREAT SCALE INHIBITOR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: SHED-356 WITHROW X49 DRAWING COMPOUND
Other Information: WITHROW X49 DRAWING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7446-09-5
Name: SULFUR DIOXIDE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS
Other Information: CAUSTUC LIQUIDS/SOLIDS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS
Other Information: TANK E2 ETCH CLEAN DIVERSEY 202
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS -
Other Information: ALKALINE CLEAN
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS*
Other Information: TANKS R8 & R13 SODIUM HYDROXIDE CHEMICAL MILLING SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 132 AQUEOUS SOL'N WITH METALS
Other Information: PHOSPHATE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: AQUA QUENCH COOLANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: WASTE COOLANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: SOAP/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 151 ASBESTOS CONTAINING WASTE
Other Information: ASBESTOS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE
Other Information: FILTER CAKE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE
Other Information: WATER JET SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported

Name: WASTE 171 METAL SLUDGE (OTHER)
Other Information: LAZER JET FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE*
Other Information: FERROUS ALUMINUM SILICATE-GARNET, ALUMINA & SILICA SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE*
Other Information: WASTE WATER TREATMENT FILTER CAKE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 172 METAL DUST & MACHINING WASTE
Other Information: SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 172 METAL DUST & MACHINING WASTE
Other Information: WASTE LASER JET FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: CHEMICAL BAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: PAINT FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) -
Other Information: LAB PACK - MERCURY
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) --
Other Information: BAG HOUSE FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) ---
Other Information: LP - KOLENE
Material Waste: Waste
Hazardous Categories 1: Not reported

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) PAINTF
Other Information: PAINT FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: DRAW-TEMP 430 SALT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: KOLENE DGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE CHEMICAL BAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE GRINDING DEBRIS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE LEAD DROSS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE PAINT BOOTH FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)LEAD
Other Information: LEAD DROSS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 214 UNSPEC SOLVENT MIXTURE
Other Information: PAINT/SOLVENTS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012

Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: MACHINE OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: MOBIL PEGASUS 801 OIL, ROHR G/S #5655-0879-010588
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: BASE OIL AND ADDITIVES
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: MOBIL GEAR 600 XP 320 GEAR OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: MOBILMET 766 CUTTING OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: WASTE MACHINE OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL.
Other Information: TECTYL 502C CLASS I PRESERVATIVE OIL G/S #5855-0850-009823
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information: WASTE OIL SUMP SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 241 TANK BOTTOM WASTE
Other Information: HAULER CODE: 2431 SUMP SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 241 TANK BOTTOM WASTE
Other Information: WASTE SUMP SLUDGE
Material Waste: Waste

Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: WASTE PAINT & SOLVENT W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: PAINT RELATED
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: ABSORBANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: OILY ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER) -
Other Information: CONTAMINATED RAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)*
Other Information: WASTE PAINT & SOLVENT RAGS W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: U.S. BATTERY
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 461 PAINT SLUDGE
Other Information: WASTE PAINT DEBRIS W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 611 CONTAMINATED SOIL
Other Information: SITE ASSESSMENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 723 LIQUIDS W CHROMIUM - R
Other Information: HENKEL DEOXIDIZER 6/16 MAKE-UP & REPLENISHER FOR TANK E4
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 791 LIQUIDS WITH PH <OR= 2
Other Information: TANK D6 NITRIC ACID PASSIVATION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS
Other Information: ALODINE 1500
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS
Other Information: CHROMIC, NITRIC
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS -
Other Information: BORRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS -
Other Information: NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS --
Other Information: R-20 HF ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS ---
Other Information: F-8 SULFURIC ACID, CHROMIUM
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS ----
Other Information: HYDROFLUORIC/NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: ALODINE 1200 & 1500 LIQUID

Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: DILUTE SULFURIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: MIXUTRE OF CHROMIC ACID & NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: R20 TITANIUM CHEMICAL MILLING SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: TANK R11 TURCO SMUT-GO NCB NONCHROMATED DESMUT SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: TANKS D3 & D4 STEEL & TITANIUM CLEANER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 901 INFECTIOUS WASTE, GENERAL
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 902 INFECTIOUS WASTE, SHARPS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0207
Violation: FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Violation Citation: Facility not maintained &/operated to minimize possibility of fire, explosion or

release. CCR 66265.31
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0142
Violation: DID NOT NOTIFY OF TIERED PERMITTING
Violation Citation: TIERED PERMITTING: Facility has failed to notify local CUPA and DTSC of eligible onsite treatment of hazardous waste. 25201(a)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0218
Violation: FILTERS:FUEL/OIL NOT LABELED OR CLOSED
Violation Citation: Failed to label &/or close drained used oil filters &/or used fuel filters. 25250.22 and 66266.130(c)(3)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 04/14/2004
Violation Code: 6HV4209
Violation: NO GENERATOR'S INFO ON RED BAGS/SHARPS
Violation Citation: Red bags, sharps containers not labeled with generator's name, address, and phone number. 68.1205
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 04/14/2004
Violation Code: 6HV1605
Violation: NO DAILY TANK INSPECTION/LOG
Violation Citation: Failed to inspect and/or document daily HW tank system inspections. 66265.195 (c)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 03/03/2009
Violation Code: 6HV1007
Violation: HIGHLY TOXIC GAS NOT ON CHEM INVENTORY
Violation Citation: Highly toxic gas (TLV less than or equal to 10 ppm) not disclosed in chemical inventory. 68.1113(b)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 03/03/2009
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 102457 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5284
Capacity Gallons: 1200
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-06 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T045
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 500
UST Contents: Not reported
Other Content Info: Not reported

Reg Status:	REMOVED
Remove Close Date:	2006-10-26 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name:	UNDERGROUND TANK 102457 T046
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	AT5287
Capacity Gallons:	5000
UST Contents:	DIESEL
Other Content Info:	Not reported
Reg Status:	REMOVED
Remove Close Date:	2006-10-26 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name:	UNDERGROUND TANK 102457 T047
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	AT5287
Capacity Gallons:	5000
UST Contents:	DIESEL
Other Content Info:	Not reported
Reg Status:	REMOVED
Remove Close Date:	2006-10-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name:	UNDERGROUND TANK 102457 T048
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	AT5287
Capacity Gallons:	1500
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	REMOVED
Remove Close Date:	2006-10-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name:	UNDERGROUND TANK 102457 T049
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	AT5287
Capacity Gallons:	5000
UST Contents:	DIESEL
Other Content Info:	Not reported
Reg Status:	REMOVED
Remove Close Date:	2006-10-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name:	UNDERGROUND TANK 102457 T050
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	AT5287
Capacity Gallons:	350
UST Contents:	DIESEL
Other Content Info:	Not reported

Reg Status:	REMOVED
Remove Close Date:	2006-10-26 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name:	UNDERGROUND TANK 102457 T022
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	R-ID#7
Capacity Gallons:	100
UST Contents:	Not reported
Other Content Info:	GASOLINE & WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1993-07-28 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T023
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 1 - C-70 SALT ACTIVE PROCESS TANK, IN VAULT, V
Capacity Gallons:	3600
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T024
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	OTHER
Additional Id:	BLD 1 - C-70 RINSE ACTIVE PROCESS TANK, IN VAULT,
Capacity Gallons:	3600
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T025
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	OTHER
Additional Id:	15-C70Q C-70 QUENCH TANK
Capacity Gallons:	3600
UST Contents:	Not reported
Other Content Info:	NON-HAZARDOUS RINSE WATER
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	UNKNOWN
Delivery System:	Not reported
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name:	UNDERGROUND TANK 102457 T026
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 1 - V1 DEGREASER 1,1,1, TRI CLOSED PER 3/27/98
Capacity Gallons:	10
UST Contents:	Not reported
Other Content Info:	Not reported

Reg Status: CLOSED
Remove Close Date: 2003-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T027
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 1 - V2 DEGREASER 1,1,1, TRI CLOSED PER 3/27/98
Capacity Gallons: 10
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2003-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T028
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 45 - PAINT BOOTH 45-3, CLOSED PER 3/27/98 DEH
Capacity Gallons: 4314
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T029
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: 3-09598 BLANCHARD GRINDER : MACHINING COOLANT
Capacity Gallons: 1345
UST Contents: Not reported
Other Content Info: BLANCHARD GRINDER : MACHINING
Reg Status: CLOSED
Remove Close Date: 1999-06-15 00:00:00
Year Installed: Not reported
Pipe Type: UNKNOWN
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T030
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 30 - PAINT BOOTH 30-1, PE NOT UST CLOSED IN PL
Capacity Gallons: 3810
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T031
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 45 - KOLENE TANK IN VAULT PROCESS TANK CLOSED
Capacity Gallons: 6720
UST Contents: Not reported
Other Content Info: Not reported

Reg Status:	CLOSED
Remove Close Date:	1998-03-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T032
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	BLD 30 - C72 SALT BATH PROCESS TANK IN VAULT CLOSE
Capacity Gallons:	1400
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	CLOSED
Remove Close Date:	1998-03-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T033
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	BLD 1 - C-70 TOWER SUMP CLOSED IN PLACE PER 3/27/9
Capacity Gallons:	1681
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	CLOSED
Remove Close Date:	1998-03-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T034
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	BLD 1 - NC MACHINE SHOP DRUM CLOSED AT4410
Capacity Gallons:	55
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	CLOSED
Remove Close Date:	1999-06-01 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T035
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 30 - ALODINE SUMP CLOSED ET0039
Capacity Gallons:	22
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	CLOSED
Remove Close Date:	2000-06-01 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T036
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 61 - PAINT BOOTH SUMP 61-3 (EXEMPT TANK CLOSE
Capacity Gallons:	129
UST Contents:	Not reported
Other Content Info:	Not reported

Reg Status:	CLOSED
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T037
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 3 - TRANSFER SUMP WASTEWATER
Capacity Gallons:	750
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T038
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 3 - S LINE SUMP WASTEWATER
Capacity Gallons:	345
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T039
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 30 - PAINT BOOTH SUMP WASTEWATER
Capacity Gallons:	62
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T040
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	AT4591
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	OTHER - SPECIFY
Reg Status:	REMOVED
Remove Close Date:	2000-04-24 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	99
UST Monitor Method:	OTHER - BLIND REMARK REQUIRED

UST Name:	UNDERGROUND TANK 102457 T041
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	ET0039
Capacity Gallons:	4000
UST Contents:	Not reported
Other Content Info:	OTHER - SPECIFY
Reg Status:	REMOVED

Remove Close Date: 2000-07-06 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 99
UST Monitor Method: OTHER - BLIND REMARK REQUIRED

UST Name: UNDERGROUND TANK 102457 T042
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: ET0039
Capacity Gallons: 20
UST Contents: Not reported
Other Content Info: OTHER - SPECIFY
Reg Status: REMOVED
Remove Close Date: 2000-07-06 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 99
UST Monitor Method: OTHER - BLIND REMARK REQUIRED

UST Name: UNDERGROUND TANK 102457 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT0004
Capacity Gallons: 100
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: 1988-11-02 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: 0000
Capacity Gallons: 10000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1973-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 2
Capacity Gallons: 50
UST Contents: LEADED
Other Content Info: LEADED
Reg Status: REMOVED
Remove Close Date: 1993-02-03 00:00:00
Year Installed: 1979-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 07
UST Monitor Method: SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name: UNDERGROUND TANK 102457 T004
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 000
Capacity Gallons: 10000
UST Contents: LEADED
Other Content Info: LEADED
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1973-01-01 00:00:00

Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	000
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1973-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	000
Capacity Gallons:	10000
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1965-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	DOUBLE WALL
Additional Id:	AT4828
Capacity Gallons:	6000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1987-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	SUCTION
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name:	UNDERGROUND TANK 102457 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	DOUBLE WALL
Additional Id:	AT4828
Capacity Gallons:	6000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1987-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	SUCTION
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name:	UNDERGROUND TANK 102457 T009
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	DOUBLE WALL
Additional Id:	AT4828
Capacity Gallons:	6000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1987-01-01 00:00:00

Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T010
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 1 - COOLANT, EXEMPT CLOSED IN PLACE PER 3/27/9
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2002-06-07 00:00:00
Year Installed: 1983-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T011
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT0374
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: INVALID CODE
Reg Status: REMOVED
Remove Close Date: 1988-11-02 00:00:00
Year Installed: 1974-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T012
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 3 - MASKANT EMERGENCY DUMP TANK CLOSED BY REMO
Capacity Gallons: 3000
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1968-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T013
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: NOTTINGHAM SUMP WASTE WATER WITH 0.00008% HEAVY ME
Capacity Gallons: 1500
UST Contents: Not reported
Other Content Info: WASTE WATER WITH 0.00008% HEAV
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T014
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: EQUALIZATION SUMP WASTE WATER WITH 0.00028% HEAVY
Capacity Gallons: 40000
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported

Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 25
UST Monitor Method: EXTERNAL MONITOR : CONTINUOUS VADOSE ZONE VAPOR MONITORS AND / OR WEEKLY (MINIMUM) VADOSE ZONE LIQUID MONITORING

UST Name: UNDERGROUND TANK 102457 T015
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: R-ID#11 WATER-EXEMPT AS NONHAZARDOUS
Capacity Gallons: 600
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: 1968-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T016
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 45 - PAINT BOOTH 45-7
Capacity Gallons: 18000
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: 1985-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T017
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 45 - PAINT BOOTH 45-8
Capacity Gallons: 10000
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: 1985-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T018
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#22
Capacity Gallons: 4000
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1993-02-03 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T019
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: 3-13888
Capacity Gallons: 255
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: Not reported

Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T020
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	R-ID#18
Capacity Gallons:	4000
UST Contents:	Not reported
Other Content Info:	GASOLINE & WASTE OIL
Reg Status:	CLOSED
Remove Close Date:	1993-06-22 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T021
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	R-ID#19
Capacity Gallons:	120
UST Contents:	Not reported
Other Content Info:	GASOLINE & WASTE OIL
Reg Status:	CLOSED
Remove Close Date:	1993-06-22 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T043
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	Not reported
Additional Id:	AT4757
Capacity Gallons:	Not reported
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	Not reported
UST Monitor Method:	Not reported

UST Name:	UNDERGROUND TANK 102457 T044
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	Not reported
Additional Id:	AT4757
Capacity Gallons:	Not reported
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	Not reported
UST Monitor Method:	Not reported

Name:	GOODRICH CORP. DBA ROHR INC
Address:	H (FOOT OF) ST
City,State,Zip:	CHULA VISTA, CA 91910
Permit Number:	102457
Business Type:	6HK49
EPA Id Number:	CAD008382053
APN:	567-022-01-00
Last HMMD Inspection:	06/10/2010
Facility Telephone:	619-691-4111
Permit Status:	OPEN
Permit Expiration:	01/31/2013
Date Last Updated:	11/02/2012

Facility Owner: GOODRICH CORP. DBA ROHR INC
Facility Mailing Address: 850 LAGOON DRIVE
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910-2098
UST Owner: ROHR INDUSTRIES INC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Y
Generate Haz Waste: Y
Treat Haz Waste: Y
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10102-44-0
Name: 0.45% NITROGEN DIOXIDE IN NITROGEN CALIBRATION GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: ACETONE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68815-10-1
Name: ALIPHATIC PETROLEUM OIL
Other Information: BRAYCO MICRONIC 882
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: ANTENSLB NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: AQUA QUCNCH 251-B
Other Information: SODIUM MITRATE SOLUTION
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: AQUAQUENCH INHIBITOR 211
Other Information: SODIUM NITRITE SOLUTION
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 312 NEXTEL CERAMIC FIBER
Other Information: 312 NEXTEL CERAMIC FIBER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 321-N
Other Information: 321-N
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: BLDG-001 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-001 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-001 ALODINE 1500 LIQUID
Other Information: ALODINE 1500 LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ALUMINUX
Other Information: ALUMINUX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: BLDG-001 AMMONIUM BIFLUORIDE-F
Other Information: AMMONIUM BIFLUORIDE-F
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0

Name: BLDG-001 AQUA QUENCH 251 LUBE/COOLANT
Other Information: AQUA QUENCH 251 LUBE/COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ATM-2000-X1 FUSED SILICA
Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-88-0
Name: BLDG-001 AZ 644-10 LOT WR ACRYLIC EMULSION/CARBOXYLATED
Other Information: AZ 644-10 LOT WR ACRYLIC EMULSION/CARBOXYLATED
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE

Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 124-38-9
Name: BLDG-001 CARBON DIOXIDE, REFRIGERATED LIQUID
Other Information: CARBON DIOXIDE, REFRIGERATED LIQUID
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-001 CAUSTIC SODA 50% LIQUID
Other Information: CAUSTIC SODA 50% LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: BLDG-001 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-47-8
Name: BLDG-001 CROWN DEODERIZED KEROSENE/OIL BASE DSB/AKA CHEV
Other Information: CROWN DEODERIZED KEROSENE/OIL BASE DSB/AKA CHEV
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 DRAW TEMP 430
Other Information: DRAW TEMP 430
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 FYRQUEL 220
Other Information: FYRQUEL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 GMC 528-B
Other Information: GMC 528-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012

Case Number: 111-76-2
Name: BLDG-001 GMC 528-B METAL CLEANER
Other Information: GMC 528-B METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: BLDG-001 HOUGHTO-DRAW 650 LUBRICANT
Other Information: HOUGHTO-DRAW 650 LUBRICANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7647-01-0
Name: BLDG-001 HYDROCHLORIC ACID
Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 JETTACIN
Other Information: JETTACIN
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-001 KEROSENE DEODORIZED
Other Information: KEROSENE DEODORIZED
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-001 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 LIQUID ARGON
Other Information: LIQUID ARGON
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52
Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: BLDG-001 MAGNAFLUX/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUX/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: BLDG-001 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: BLDG-001 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-56-1
Name: BLDG-001 METHYL ALCOHOL
Other Information: METHYL ALCOHOL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE 24 OIL
Other Information: MOBIL DTE 24 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE OIL EXTRA HEAVY
Other Information: MOBIL DTE OIL EXTRA HEAVY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL MIST LUBE #27
Other Information: MOBIL MIST LUBE #27
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VACTRA OIL NO. 2
Other Information: MOBIL VACTRA OIL NO. 2
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-85-4
Name: BLDG-001 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VACUOLINE 1405 OIL
Other Information: MOBIL VACUOLINE 1405 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL VACUOLINE 1409 OIL
Other Information: MOBIL VACUOLINE 1409 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VELOCITE OIL NO 6
Other Information: MOBIL VELOCITE OIL NO 6
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID BULK
Other Information: NITRIC ACID BULK

Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-001 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 497-19-8
Name: BLDG-001 OAKITE LOW HEAT CLEANER 1 CLEANER
Other Information: OAKITE LOW HEAT CLEANER 1 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-9
Name: BLDG-001 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: BLDG-001 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SCA 636
Other Information: SCA 636
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SHELL SOL 340 HT
Other Information: SHELL SOL 340 HT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-001 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SODIUM HYDROSULFIDE SOLID
Other Information: SODIUM HYDROSULFIDE SOLID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-001 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: BLDG-001 TECTYL 802A/MIL-L-3150 A9944 LUBE
Other Information: TECTYL 802A/MIL-L-3150 A9944 LUBE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 75-09-2
Name: BLDG-001 TURCO 5351 CLEANER/STRIPPER
Other Information: TURCO 5351 CLEANER/STRIPPER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 6834-92-0
Name: BLDG-001 TURCO HTC METAL CLEANER

Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO PRETREAT
Other Information: TURCO PRETREAT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 V LUBE B
Other Information: V LUBE B
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-92-2
Name: BLDG-001 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: BLDG-001 WITHROW X49 DRAWING COMPOUND
Other Information: WITHROW X49 DRAWING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-001 ZL-66A ZYGLO WATER WASHABLE PENETRANT
Other Information: ZL-66A ZYGLO WATER WASHABLE PENETRANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-003 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-003 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-003 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-003 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-85-4
Name: BLDG-005 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-98-6
Name: BLDG-009 LPG GAS
Other Information: LPG GAS - PROPANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-011 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-011 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-011 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-019 ARGON
Other Information: ARAGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-019 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-019 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-21-1

Name: BLDG-025 ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Other Information: ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-025 UNLEADED FUEL BULK
Other Information: UNLEADED FUEL BULK
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 1-8% OXYGEN IN ARGON
Other Information: 1-8% OXYGEN IN ARGON
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 7544/139
Other Information: 7544/139
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-029 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-029 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-029 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-029 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ARGON AIR PRODUCT
Other Information: ARGON AIR PRODUCT
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE

Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 AS-150 ANTI-SLIP COATING 440
Other Information: AS-150 ANTI-SLIP COATING 440
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 DOK DEODORIZED KERONSENE
Other Information: DOK DEODORIZED KERONSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 FR-5317-W EPOXY RESIN
Other Information: FR-5317-W EPOXY RESIN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 25068-38-6
Name: BLDG-029 FR-5317-W EPOXY RESIN SYSTEM
Other Information: FR-5317-W EPOXY RESIN SYSTEM
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-029 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-029 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-029 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-029 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012

Case Number: 7782-44-7
Name: BLDG-029 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ULTRACAL 30
Other Information: ULTRACAL 30
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-88-4
Name: BLDG-029 UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Other Information: UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-030 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-030 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 ACETONE UNION CARBIDE
Other Information: ACETONE UNION CARBIDE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 DOK DEODORIZED KEROSENE
Other Information: DOK DEODORIZED KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 HELIUM MG
Other Information: HELIUM MG
Material Waste: Material

Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 ISOPROPYL ALCOHOL UNION
Other Information: ISOPROPYL ALCOHOL UNION
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 ROHR BLEND #1
Other Information: ROHR BLEND #1
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 SHELL SOL 340 HT
Other Information: SHELL SOL 340 HT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-032 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-032 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-032 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG--032 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: BLDG-036 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457

Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-036 DOK DEORDORIZED KEROSENE
Other Information: DOK DEORDORIZED KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-036 LIQUID NITROGEN
Other Information: LIQUID NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-036 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1
Name: BLDG-036 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-53-6
Name: BLDG-036 SOLVOL 6582 COOLANT
Other Information: SOLVOL 6582 COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-211-1
Name: BLDG-038 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-038 MOBIL DELVAC 1230
Other Information: MOBIL DELVAC 1230
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-040 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 321-N
Other Information: 321-N
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)

Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: BLDG-045 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-045 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-045 ALODINE 1500 LIQUID
Other Information: ALODINE 1500 LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 ALUMINUX
Other Information: ALUMINUX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Other Information: ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: BLDG-045 AMMONIUM BIFLUORIDE-F
Other Information: AMMONIUM BIFLUORIDE-F
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-045 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

SECTION 1: FACILITY DETAIL REPORTS

...Continued...

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-045 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 CAUSTIC SODA 50% LIQUID
Other Information: CAUSTIC SODA 50% LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7778-50-9
Name: BLDG-045 DEOXIDIZER 17 REPLENISHER
Other Information: DEOXIDIZER 17 REPLINISHER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 DEOXIDIZER 7 MAKE-UP
Other Information: DEOXIDIZER 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 EPOXY PRIMER 10P4-16
Other Information: EPOXY PRIMER 10P4-16
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 GMC 528-B
Other Information: GMC 528-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 111-76-2
Name: BLDG-045 GMC 528-B METAL CLEANER
Other Information: GMC 528-B METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7647-01-0
Name: BLDG-045 HYDROCHLORIC ACID

Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-39-3
Name: BLDG-045 HYDROFLUORIC ACID 49%
Other Information: HYDROFLUORIC ACID 49%
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 KLEENSWEEP WAX BASE 1320
Other Information: KLEENSWEEP WAX BASE 1320
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: BLDG-045 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NA9194 DEOXID 7 MAKE-UP
Other Information: NA9194 DEOXID 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NABC NON-ACID BATH CLNR
Other Information: NABC NON-ACID BATH CLNR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NITRIC ACID BULK
Other Information: NITRIC ACID BULK
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 497-19-8
Name: BLDG-045 OAKITE LOW HEAT CLEANER 1 CLEANER
Other Information: OAKITE LOW HEAT CLEANER 1 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-045 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: BLDG-045 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 SCA 636
Other Information: SCA 636
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-045 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported

Name: BLDG-045 SODIUM HYDROSULFIDE SOLID
Other Information: SODIUM HYDROSULFIDE SOLID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-045 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: BLDG-045 TT-L-32A AM1 TYPE 2 17875 INS WHT/5432320078750
Other Information: TT-L-32A AM1 TYPE 2 17875 INS WHT/5432320078750
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 75-09-2
Name: BLDG-045 TURCO 5351 CLEANER/STRIPPER
Other Information: TURCO 5351 CLEANER/STRIPPER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 6834-92-0
Name: BLDG-045 TURCO HTC METAL CLEANER
Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO PRETREAT
Other Information: TURCO PRETREAT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-045 ZL-66A ZYGLO WATER WASHABLE PENETRANT
Other Information: ZL-66A ZYGLO WATER WASHABLE PENETRANT
Material Waste: Material
Hazardous Categories 1: FIRE

Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-048 KEROSENE
Other Information: KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-050 ATM-2000-X1 FUSED SILICA
Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-92-2
Name: BLDG-050 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-054 OXYGEN BULK LIQUID
Other Information: OXYGEN BULK LIQUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-054 PROPANE
Other Information: PROPANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-055 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-055 ARGON GENERIC
Other Information: ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-058 ELECTRO-OX
Other Information: ELECTRO-OX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012

Case Number: Not reported
Name: BLDG-058 GARNET SAND
Other Information: GARNET SAND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: BLDG-058 GARNET SAND 60 GRIT
Other Information: GARNET SAND 60 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 LIQUID ARGON GENERIC
Other Information: LIQUID ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 2528-36-1
Name: BLDG-061 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500 B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-067 ARGON AIR PROD
Other Information: ARGON AIR PROD
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-067 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 2528-36-1
Name: BLDG-067 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material

Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-068 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-070 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-070 OXYGEN LIQUID
Other Information: LIQUID OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-081 SAFESTEP SORBENT
Other Information: SAFESTEP SORBENT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-085 ALODINE 1200R LIQUID
Other Information: ALODINE 1200R LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 77-92-9
Name: BLDG-085 ANHYDROUS CITRIC ACID, U.S.P.F.C.C.
Other Information: ANHYDROUS CITRIC ACID, U.S.P. F.C.C.
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10043-35-3
Name: BLDG-085 BORIC ACID
Other Information: BORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-085 DEOXIDIZER 7 MAKE-UP
Other Information: DEOXIDIZER 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-085 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-085 WCD 315L INHIBITOR/DISPERSANT-SODIUM BICHROM
Other Information: WCD 315L INHIBITOR/DISPERSANT-SODIUM BICHROM
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 ALODINE 1500 HENKEL
Other Information: ALODINE 1500 HENKEL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 AQUA QUENCH 260-B
Other Information: AQUA QUENCH 260-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-092 CAUSTIC SODA
Other Information: CAUSTIC SODA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 HOUGHTO-DRAW 650
Other Information: HOUGHTO-DRAW 650
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-90-5
Name: BLDG-092 SODIUM BISULFITE
Other Information: SODIUM BISULFITE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-092 SULFURIC ACID
Other Information: SULFURIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-092 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-098 FLOOR DRY
Other Information: FLOOR DRY

Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-41-7
Name: BLDG-099 ANHYDROUS AMMONIA
Other Information: ANHYDROUS AMMONIA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: BLDG-114 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-114 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-114 CARBON DIOXIDE
Other Information: CARBON DIOXIDE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-114 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-114 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1
Name: BLDG-310 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1
Name: BLDG-311 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: BLDG-341 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDSG-001 LUBRICOOLANT 2050AC
Other Information: LUBRICOOLANT 2050AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLSG-029 D-STROY
Other Information: D-STROY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-21-1
Name: CMST- 002 HOUGHTO-SAFE 620 HYDRAULIC SYSTEMS FLUID
Other Information: HOUGHTO-SAFE 620 HYDRAULIC SYSTEMS FLUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: CMST-001 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: CMST-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: CMST-001 CHEVRON SOLUBLE OIL B
Other Information: CHEVRON SOLUBLE OIL B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-001 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: CMST-001 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: CMST-001 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-001 LIQUID NITROGEN

Other Information: LIQUID NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: CMST-002 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7732-18-5
Name: CMST-002 ACTIVOL 1357 WETTING AGENT
Other Information: ACTIVOL 1357 WETTING AGENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 141-43-5
Name: CMST-002 CEE BEE A276 COATING REMOVER (55 GAL DRUMS) ST
Other Information: CEE BEE A276 COATING REMOVER (55 GAL DRUMS)ST
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: CMST-002 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-21-1
Name: CMST-002 ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Other Information: ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-63-0
Name: CMST-002 ISOPROPANOL, ANHYDROUS
Other Information: ISOPROPANOL, ANHYDROUS
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: CMST-002 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL DELVAC SAE 30 OIL
Other Information: MOBIL DELVAC SAE 30 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL DTE 24 OIL
Other Information: MOBIL DTE 24 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL HYDRAULIC OIL 220
Other Information: MOBIL HYDRAULIC OIL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL MULTI-PURPOSE ATF OIL
Other Information: MOBIL MULTI-PURPOSE ATF OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL VACUOLINE 1405 OIL
Other Information: MOBIL VACUOLINE 1405 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL VELOCITE OIL NO 6
Other Information: MOBIL VELOCITE OIL NO 6
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBILUBE HD 80W-90 GEAR LUBE
Other Information: MOBILUBE HD 80W-90 GEAR LUBE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8052-41-3
Name: CMST-002 SOLVENT M-4 (CLEANING, COMPOUND LIQUID)
Other Information: SOLVENT M-4 (CLEANING, COMPOUND LIQUID)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68477-31-6

Name: CMST-002 TURCO 4460 SOLVENT
Other Information: TURCO 4460 SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: CMST-002 VINYL MODIFIED CASTOR OIL CODE H2006
Other Information: VINYL MODIFIED CASTOR OIL CODE H2006
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: CMST-003 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: CMST-003 AQUA QUENCH 251 LUBE/COOLANT
Other Information: AQUA QUENCH 251 LUBE/COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: CMST-003 HOUGHTO-DRAW 650 LUBRICANT
Other Information: HOUGHTO-DRAW 650 LUBRICANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: CMST-003 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: CMST-003 PENRECO AMBER (PETROLATUM)
Other Information: PENRECO AMBER (PETROLATUM) CODE 4510
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: CMST-003 SULFURIC ACID 66 DEG BE
Other Information: SULFURIC ACID 66 DEG BE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-92-2
Name: CMST-003 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 6834-92-0
Name: CMST-004 TURCO HTC METAL CLEANER
Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-53-6
Name: CMST-005 SOLVOL 6582 COOLANT
Other Information: SOLVOL 6582 COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 1-8% OXYGEN IN ARGON
Other Information: 1-8% OXYGEN IN ARGON
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 7544/139
Other Information: 7544/139
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-815-0 THINNER
Other Information: AC-815-0 THINNER
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ACTIVOL 1357
Other Information: ACTIVOL 1357
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ALODINE 1500 HENKEL
Other Information: ALODINE 1500 HENKEL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012

Case Number: Not reported
Name: CMST-006 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARDROX 180-B
Other Information: ARDROX 180-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARDROX 7050-W
Other Information: ARDROX 7050-W
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON AIR PROD
Other Information: ARGON AIR PROD
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON GENERIC
Other Information: ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AS-150 ANTI-SLIP COATING
Other Information: AS-150 ANTI-SLIP COATING
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ATM-2000-X1 FUSED SILICA
Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BLASOCUT 4000 STRONG
Other Information: BLASOCUT 4000 STRONG
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BORIC ACID US BORAX
Other Information: BORIC ACID US BORAX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BUCKEYE SHOPMASTER
Other Information: BUCKEYE SHOPMASTER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BUCKEYE SHOPMASTER RTU
Other Information: BUCKEYE SHOPMASTER RTU
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CASTING PLASTER REG
Other Information: CASTING PLASTER REG
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CEE BEE A-276
Other Information: CEE BEE A-276
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DIESEL FUEL BULK
Other Information: DIESEL FUEL BULK
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DRAW TEMP 430
Other Information: DRAW TEMP 430
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 D-STROY
Other Information: D-STROY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ELECTRO-OX
Other Information: ELECTRO-OX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FERROUS SULFATE HEPTAHYDR
Other Information: FERROUS SULFATE HEPTAHYDR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FORMULA 28
Other Information: FORMULA 28
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FYRQUEL 220
Other Information: FYRQUEL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HELIUM LIQUID AIR
Other Information: HELIUM LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HELIUM MG
Other Information: HELIUM MG

Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HOUGHTO-SAFE 620
Other Information: HOUGHTO-SAFE 620
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HYDROCHLORIC ACID
Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 JETTACIN
Other Information: JETTACIN
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LIQUID ARGON GENERIC
Other Information: LIQUID ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LIQUID CAUSTIC SODA 50%
Other Information: LIQUID CAUSTIC SODA 50%
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LIQUID HELIUM PRAXAIR
Other Information: LIQUID HELIUM PRAXAIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-006 LIQUID OXYGEN
Other Information: LIQUID OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1309-42-8
Name: CMST-006 MAGNESIUM HYDROXIDE SUS
Other Information: MAGNESIUM HYDROXIDE SUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MF ACID
Other Information: MF ACID
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DELVAC 1230
Other Information: MOBIL DELVAC 1230
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE OIL EXTRA HEAVY
Other Information: MOBIL DTE OIL EXTRA HEAVY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL STE 24
Other Information: MOBIL DTE 24
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACTRA OIL NO. 2

Other Information: MOBIL VACTRA OIL NO. 2
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACUOLINE 1409 OIL
Other Information: MOBIL VACUOLINE 1409 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBILMET OMEGA
Other Information: MOBILMET OMEGA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 NABC NON-ACID BATH CLNR
Other Information: NABC NON-ACID BATH CLNR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 NITRIC ACID BULK
Other Information: NITRIC ACID BULK
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-006 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 OXYGEN MG
Other Information: OXYGEN MG
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 PROPANE
Other Information: PROPANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ROHR BLEND #1
Other Information: ROHR BLEND #1
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SODIUM BISULFITE
Other Information: SODIUM BISULFITE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SODIUM HYPOCHLORITE 12.5%
Other Information: SODIUM HYPOCHLORITE 12.5%
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO 5351
Other Information: TURCO 5351
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ULTRACAL 30
Other Information: ULTRACAL 30
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 V LUBE B
Other Information: V LUBE B
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68476-34-6

Name: DIESEL FUEL
Other Information: BLDG 118 COGENERATION PLANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 103-24-2
Name: DIOCTYL AZELATE
Other Information: QUINSYN COMPRESSOR OIL
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL - COOLANT
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, METAL CHIPS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, METAL CHIPS IN COOLANT
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, RINSE WATER FROM CHEM PROCESS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, X-RAY FIXER SOLUTION
Other Information: RECYCLABLE SILVER SALTS IN SOLUTION
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7783-06-4
Name: HYDROGEN SULFIDE, 25 PPM IN NONFLAMMABLE CALIBRATION GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68037-01-4
Name: LUBRIPLATE SYNLUBE HD 220
Other Information: 1-DECENE, HOMOPOLYMER, HYDROGENATED
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: MF ACID
Other Information: AMMONIUM BIFLUORIDE
Material Waste: Material
Hazardous Categories 1: ACUTE

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-54-7
Name: MOBIL DTE 25
Other Information: PETROLEUM LUBRICANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: MOBILGEAR 600 XP 150
Other Information: BASE OIL & ADDITIVES
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: MOBILGREASE XHP 005
Other Information: BASE OIL & ADDITIVES
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10024-97-2
Name: NITROUS OXIDE
Other Information: LAUGHING GAS
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: PEGASUS 1005 NATURAL GAS ENGINE OIL
Other Information: PETROLEUM OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: MIXTURE
Name: PT2114
Other Information: WHITE EPOXY LAMINATING RESIN
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 541-02-6
Name: QSOL 300 LOW VOC SOLVENT
Other Information: DECAMETHYLCYCLOPENTASILOSANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: SHED 415 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: SHED 415 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012

Case Number: 67-64-1
Name: SHED-327 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7732-18-5
Name: SHED-327 ACTIVOL 1357 WETTING AGENT
Other Information: ACTIVOL 1357 WETTING AGENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: SHED-327 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-63-0
Name: SHED-327 ISOPROPANOL, ANHYDROUS
Other Information: ISOPROPANOL, ANHYDROUS
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: SHED-327 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68477-31-6
Name: SHED-327 TURCO 4460 SOLVENT
Other Information: TURCO 4460 SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-88-4
Name: SHED-327 UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Other Information: UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 111-76-2
Name: SHED-356 321-N COATING
Other Information: 321-N COATING
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: SHED-356 ABRASIVE GARNET SAND 60-80 GRIT
Other Information: ABRASIVE GARNET SAND 60-80 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: SHED-356 ABRASIVE GRIT GARNET SAND BAC 5748 150 GRIT
Other Information: ABRASIVE GRIT GARNET SAND BAC 5748 150 GRIT
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: SHED-356 ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Other Information: ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: SHED-356 AMMONIUM BIFLUORIDE
Other Information: AMMONIUM BIFLUORIDE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 471-34-1
Name: SHED-356 CALCIUM CARBONATE
Other Information: CALCIUM CARBONATE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: SHED-356 DEOXIDIZER 17 REPLENISHER
Other Information: DEOXIDIZER 17 REPLENISHER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1344-28-1
Name: SHED-356 FUSED ALUMINUM OXIDE 240 GRIT
Other Information: FUSED ALUMINUM OXIDE 240 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1344-28-1
Name: SHED-356 FUSED ALUMINUM OXIDE 46 GRIT
Other Information: FUSED ALUMINUM OXIDE 46 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 56550-16-0
Name: SHED-356 FYRQUEL 220 (FIRE RESISTANT HYDRAULIC FLUID)
Other Information: FYRQUEL 220 (FIRE RESISTANT HYDRAULIC FLUID)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: SHED-356 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: SHED-356 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 2528-36-1
Name: SHED-356 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: SHED-356 TECTYL 802A/MIL-L-3150 A9944 LUBE
Other Information: TECTYL 802A/MIL-L-3150 A9944 LUBE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-88-3
Name: SHED-356 TURCO PRETREAT SCALE INHIBITOR
Other Information: TURCO PRETREAT SCALE INHIBITOR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: SHED-356 WITHROW X49 DRAWING COMPOUND
Other Information: WITHROW X49 DRAWING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7446-09-5
Name: SULFUR DIOXIDE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS
Other Information: CAUSTUC LIQUIDS/SOLIDS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS
Other Information: TANK E2 ETCH CLEAN DIVERSEY 202
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS -
Other Information: ALKALINE CLEAN
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS*
Other Information: TANKS R8 & R13 SODIUM HYDROXIDE CHEMICAL MILLING SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 132 AQUEOUS SOL'N WITH METALS
Other Information: PHOSPHATE

Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: AQUA QUENCH COOLANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: WASTE COOLANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: SOAP/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 151 ASBESTOS CONTAINING WASTE
Other Information: ASBESTOS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE
Other Information: FILTER CAKE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE
Other Information: WATER JET SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE (OTHER)
Other Information: LAZER JET FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE*
Other Information: FERROUS ALUMINUM SILICATE-GARNET, ALUMINA & SILICA SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE*
Other Information: WASTE WATER TREATMENT FILTER CAKE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 172 METAL DUST & MACHINING WASTE
Other Information: SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 172 METAL DUST & MACHINING WASTE
Other Information: WASTE LASER JET FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: CHEMICAL BAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: PAINT FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) -
Other Information: LAB PACK - MERCURY
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) --
Other Information: BAG HOUSE FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) ---
Other Information: LP - KOLENE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) PAINTF
Other Information: PAINT FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: DRAW-TEMP 430 SALT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*

Other Information: KOLENE DGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE CHEMICAL BAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE GRINDING DEBRIS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE LEAD DROSS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE PAINT BOOTH FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)LEAD
Other Information: LEAD DROSS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 214 UNSPEC SOLVENT MIXTURE
Other Information: PAINT/SOLVENTS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: MACHINE OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: MOBIL PEGASUS 801 OIL, ROHR G/S #5655-0879-010588
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: BASE OIL AND ADDITIVES
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: MOBIL GEAR 600 XP 320 GEAR OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: MOBILMET 766 CUTTING OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: WASTE MACHINE OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL.
Other Information: TECTYL 502C CLASS I PRESERVATIVE OIL G/S #5855-0850-009823
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information: WASTE OIL SUMP SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 241 TANK BOTTOM WASTE
Other Information: HAULER CODE: 2431 SUMP SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 241 TANK BOTTOM WASTE
Other Information: WASTE SUMP SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: WASTE PAINT & SOLVENT W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: PAINT RELATED
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported

Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: ABSORBANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: OILY ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER) -
Other Information: CONTAMINATED RAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)*
Other Information: WASTE PAINT & SOLVENT RAGS W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: U.S. BATTERY
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 461 PAINT SLUDGE
Other Information: WASTE PAINT DEBRIS W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 611 CONTAMINATED SOIL
Other Information: SITE ASSESSMENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 723 LIQUIDS W CHROMIUM - R
Other Information: HENKEL DEOXIDIZER 6/16 MAKE-UP & REPLENISHER FOR TANK E4
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 791 LIQUIDS WITH PH <OR= 2
Other Information: TANK D6 NITRIC ACID PASSIVATION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS
Other Information: ALODINE 1500
Material Waste: Waste
Hazardous Categories 1: Not reported

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS
Other Information: CHROMIC, NITRIC
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS -
Other Information: BORRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS -
Other Information: NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS --
Other Information: R-20 HF ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS ---
Other Information: F-8 SULFURIC ACID, CHROMIUM
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS ----
Other Information: HYDROFLUORIC/NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: ALODINE 1200 & 1500 LIQUID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: DILUTE SULFURIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: MIXUTRE OF CHROMIC ACID & NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012

Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: R20 TITANIUM CHEMICAL MILLING SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: TANK R11 TURCO SMUT-GO NCB NONCHROMATED DESMUT SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: TANKS D3 & D4 STEEL & TITANIUM CLEANER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 901 INFECTIOUS WASTE, GENERAL
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 902 INFECTIOUS WASTE, SHARPS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0207
Violation: FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Violation Citation: Facility not maintained &/operated to minimize possibility of fire, explosion or release. CCR 66265.31
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0142
Violation: DID NOT NOTIFY OF TIERED PERMITTING
Violation Citation: TIERED PERMITTING: Facility has failed to notify local CUPA and DTSC of eligible onsite treatment of hazardous waste. 25201(a)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0218
Violation: FILTERS:FUEL/OIL NOT LABELED OR CLOSED
Violation Citation: Failed to label &/or close drained used oil filters &/or used fuel filters. 25250.22 and 66266.130(c)(3)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 04/14/2004

Violation Code: 6HV4209
Violation: NO GENERATOR'S INFO ON RED BAGS/SHARPS
Violation Citation: Red bags, sharps containers not labeled with generator's name, address, and phone number. 68.1205
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 04/14/2004
Violation Code: 6HV1605
Violation: NO DAILY TANK INSPECTION/LOG
Violation Citation: Failed to inspect and/or document daily HW tank system inspections. 66265.195 (c)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 03/03/2009
Violation Code: 6HV1007
Violation: HIGHLY TOXIC GAS NOT ON CHEM INVENTORY
Violation Citation: Highly toxic gas (TLV less than or equal to 10 ppm) not disclosed in chemical inventory. 68.1113(b)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 03/03/2009
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

UST:

UST Name: UNDERGROUND TANK 102457 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5284
Capacity Gallons: 1200
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-06 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T045
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 500
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-26 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T046
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-26 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE

DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T047
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T048
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 1500
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T049
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T050
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 350
UST Contents: DIESEL
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-26 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T022
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#7
Capacity Gallons: 100
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1993-07-28 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE

DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T023
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 1 - C-70 SALT ACTIVE PROCESS TANK, IN VAULT, V
Capacity Gallons: 3600
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T024
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: OTHER
Additional Id: BLD 1 - C-70 RINSE ACTIVE PROCESS TANK, IN VAULT,
Capacity Gallons: 3600
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T025
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: OTHER
Additional Id: 15-C70Q C-70 QUENCH TANK
Capacity Gallons: 3600
UST Contents: Not reported
Other Content Info: NON-HAZARDOUS RINSE WATER
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: UNKNOWN
Delivery System: Not reported
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T026
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 1 - V1 DEGREASER 1,1,1, TRI CLOSED PER 3/27/98
Capacity Gallons: 10
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2003-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T027
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 1 - V2 DEGREASER 1,1,1, TRI CLOSED PER 3/27/98
Capacity Gallons: 10
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2003-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE

DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T028
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 45 - PAINT BOOTH 45-3, CLOSED PER 3/27/98 DEH
Capacity Gallons: 4314
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T029
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: 3-09598 BLANCHARD GRINDER : MACHINING COOLANT
Capacity Gallons: 1345
UST Contents: Not reported
Other Content Info: BLANCHARD GRINDER : MACHINING
Reg Status: CLOSED
Remove Close Date: 1999-06-15 00:00:00
Year Installed: Not reported
Pipe Type: UNKNOWN
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T030
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 30 - PAINT BOOTH 30-1, PE NOT UST CLOSED IN PL
Capacity Gallons: 3810
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T031
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 45 - KOLENE TANK IN VAULT PROCESS TANK CLOSED
Capacity Gallons: 6720
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T032
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 30 - C72 SALT BATH PROCESS TANK IN VAULT CLOSE
Capacity Gallons: 1400
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE

DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T033
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	BLD 1 - C-70 TOWER SUMP CLOSED IN PLACE PER 3/27/9
Capacity Gallons:	1681
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	CLOSED
Remove Close Date:	1998-03-27 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T034
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	BLD 1 - NC MACHINE SHOP DRUM CLOSED AT4410
Capacity Gallons:	55
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	CLOSED
Remove Close Date:	1999-06-01 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T035
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 30 - ALODINE SUMP CLOSED ET0039
Capacity Gallons:	22
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	CLOSED
Remove Close Date:	2000-06-01 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T036
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 61 - PAINT BOOTH SUMP 61-3 (EXEMPT TANK CLOSE
Capacity Gallons:	129
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	CLOSED
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T037
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 3 - TRANSFER SUMP WASTEWATER
Capacity Gallons:	750
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE

DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T038
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 3 - S LINE SUMP WASTEWATER
Capacity Gallons:	345
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T039
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	BLD 30 - PAINT BOOTH SUMP WASTEWATER
Capacity Gallons:	62
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	EXEMPT
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 102457 T040
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	AT4591
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	OTHER - SPECIFY
Reg Status:	REMOVED
Remove Close Date:	2000-04-24 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	99
UST Monitor Method:	OTHER - BLIND REMARK REQUIRED

UST Name:	UNDERGROUND TANK 102457 T041
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	SINGLE WALL
Additional Id:	ET0039
Capacity Gallons:	4000
UST Contents:	Not reported
Other Content Info:	OTHER - SPECIFY
Reg Status:	REMOVED
Remove Close Date:	2000-07-06 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	99
UST Monitor Method:	OTHER - BLIND REMARK REQUIRED

UST Name:	UNDERGROUND TANK 102457 T042
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	UNKNOWN
Additional Id:	ET0039
Capacity Gallons:	20
UST Contents:	Not reported
Other Content Info:	OTHER - SPECIFY
Reg Status:	REMOVED
Remove Close Date:	2000-07-06 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	99
UST Monitor Method:	OTHER - BLIND REMARK REQUIRED

UST Name:	UNDERGROUND TANK 102457 T001

Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT0004
Capacity Gallons: 100
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: 1988-11-02 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: 0000
Capacity Gallons: 10000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1973-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 2
Capacity Gallons: 50
UST Contents: LEADED
Other Content Info: LEADED
Reg Status: REMOVED
Remove Close Date: 1993-02-03 00:00:00
Year Installed: 1979-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 07
UST Monitor Method: SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name: UNDERGROUND TANK 102457 T004
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 000
Capacity Gallons: 10000
UST Contents: LEADED
Other Content Info: LEADED
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1973-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T005
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 000
Capacity Gallons: 10000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1973-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T006

Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 000
Capacity Gallons: 10000
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1965-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: AT4828
Capacity Gallons: 6000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1987-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T008
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: AT4828
Capacity Gallons: 6000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1987-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T009
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: AT4828
Capacity Gallons: 6000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1987-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T010
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 1 - COOLANT, EXEMPT CLOSED IN PLACE PER 3/27/9
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2002-06-07 00:00:00
Year Installed: 1983-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T011

Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT0374
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: INVALID CODE
Reg Status: REMOVED
Remove Close Date: 1988-11-02 00:00:00
Year Installed: 1974-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T012
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 3 - MASKANT EMERGENCY DUMP TANK CLOSED BY REMO
Capacity Gallons: 3000
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1968-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T013
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: NOTTINGHAM SUMP WASTE WATER WITH 0.00008% HEAVY ME
Capacity Gallons: 1500
UST Contents: Not reported
Other Content Info: WASTE WATER WITH 0.00008% HEAV
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T014
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: EQUALIZATION SUMP WASTE WATER WITH 0.00028% HEAVY
Capacity Gallons: 40000
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 25
UST Monitor Method: EXTERNAL MONITOR : CONTINUOUS VADOSE ZONE VAPOR MONITORS AND / OR WEEKLY (MINIMUM) VADOSE ZONE LIQUID MONITORING

UST Name: UNDERGROUND TANK 102457 T015
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: R-ID#11 WATER-EXEMPT AS NONHAZARDOUS
Capacity Gallons: 600
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: 1968-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T016

Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 45 - PAINT BOOTH 45-7
Capacity Gallons: 18000
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: 1985-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T017
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 45 - PAINT BOOTH 45-8
Capacity Gallons: 10000
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: 1985-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T018
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#22
Capacity Gallons: 4000
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1993-02-03 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T019
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: 3-13888
Capacity Gallons: 255
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T020
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#18
Capacity Gallons: 4000
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T021

Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#19
Capacity Gallons: 120
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T043
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: Not reported
Additional Id: AT4757
Capacity Gallons: Not reported
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: Not reported
UST Monitor Method: Not reported

UST Name: UNDERGROUND TANK 102457 T044
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: Not reported
Additional Id: AT4757
Capacity Gallons: Not reported
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: Not reported
UST Monitor Method: Not reported

Name: GOODRICH CORP. DBA ROHR INC
Address: H (FOOT OF) ST
City,State,Zip: CHULA VISTA, CA 91910
Permit Number: 102457
Business Type: 6HK49
EPA Id Number: CAD008382053
APN: 567-022-01-00
Last HMMD Inspection: 06/10/2010
Facility Telephone: 619-691-4111
Permit Status: OPEN
Permit Expiration: 01/31/2013
Date Last Updated: 11/02/2012
Facility Owner: GOODRICH CORP. DBA ROHR INC
Facility Mailing Address: 850 LAGOON DRIVE
Facility Mailing City: CHULA VISTA
Facility Mailing State: CA
Facility Mailing Zip: 91910-2098
UST Owner: ROHR INDUSTRIES INC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Y
Generate Haz Waste: Y
Treat Haz Waste: Y
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10102-44-0
Name: 0.45% NITROGEN DIOXIDE IN NITROGEN CALIBRATION GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 67-64-1
Name: ACETONE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68815-10-1
Name: ALIPHATIC PETROLEUM OIL
Other Information: BRAYCO MICRONIC 882
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: ANTENSLB NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: AQUA QUCNCH 251-B
Other Information: SODIUM MITRATE SOLUTION
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: AQUAQUENCH INHIBITOR 211
Other Information: SODIUM NITRITE SOLUTION
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 312 NEXTEL CERAMIC FIBER
Other Information: 312 NEXTEL CERAMIC FIBER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 321-N
Other Information: 321-N
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AC-850
Other Information: AC-850

Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: BLDG-001 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-001 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-001 ALODINE 1500 LIQUID
Other Information: ALODINE 1500 LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ALUMINUX
Other Information: ALUMINUX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: BLDG-001 AMMONIUM BIFLUORIDE-F
Other Information: AMMONIUM BIFLUORIDE-F
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: BLDG-001 AQUA QUENCH 251 LUBE/COOLANT
Other Information: AQUA QUENCH 251 LUBE/COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ATM-2000-X1 FUSED SILICA
Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-88-0
Name: BLDG-001 AZ 644-10 LOT WR ACRYLIC EMULSION/CARBOXYLATED
Other Information: AZ 644-10 LOT WR ACRYLIC EMULSION/CARBOXYLATED
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 124-38-9
Name: BLDG-001 CARBON DIOXIDE, REFRIGERATED LIQUID
Other Information: CARBON DIOXIDE, REFRIGERATED LIQUID
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-001 CAUSTIC SODA 50% LIQUID
Other Information: CAUSTIC SODA 50% LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: BLDG-001 CHEVRON THINNER 325

Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-47-8
Name: BLDG-001 CROWN DEODERIZED KEROSENE/OIL BASE DSB/AKA CHEV
Other Information: CROWN DEODERIZED KEROSENE/OIL BASE DSB/AKA CHEV
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 DRAW TEMP 430
Other Information: DRAW TEMP 430
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 FYRQUEL 220
Other Information: FYRQUEL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 GMC 528-B
Other Information: GMC 528-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 111-76-2
Name: BLDG-001 GMC 528-B METAL CLEANER
Other Information: GMC 528-B METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-001 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: BLDG-001 HOUGHTO-DRAW 650 LUBRICANT
Other Information: HOUGHTO-DRAW 650 LUBRICANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7647-01-0
Name: BLDG-001 HYDROCHLORIC ACID
Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 JETTACIN
Other Information: JETTACIN
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-001 KEROSENE DEODORIZED
Other Information: KEROSENE DEODORIZED
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-001 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 LIQUID ARGON
Other Information: LIQUID ARGON
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52

Name: BLDG-001 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: BLDG-001 MAGNAFLUX/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUX/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: BLDG-001 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: BLDG-001 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-56-1
Name: BLDG-001 METHYL ALCOHOL
Other Information: METHYL ALCOHOL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE 24 OIL
Other Information: MOBIL DTE 24 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL DTE OIL EXTRA HEAVY
Other Information: MOBIL DTE OIL EXTRA HEAVY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL MIST LUBE #27
Other Information: MOBIL MIST LUBE #27
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VACTRA OIL NO. 2
Other Information: MOBIL VACTRA OIL NO. 2
Material Waste: Material
Hazardous Categories 1: ACUTE

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-85-4
Name: BLDG-001 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VACUOLINE 1405 OIL
Other Information: MOBIL VACUOLINE 1405 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 MOBIL VACUOLINE 1409 OIL
Other Information: MOBIL VACUOLINE 1409 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: BLDG-001 MOBIL VELOCITE OIL NO 6
Other Information: MOBIL VELOCITE OIL NO 6
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 NITRIC ACID BULK
Other Information: NITRIC ACID BULK
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012

SECTION 1: FACILITY DETAIL REPORTS

...Continued...

Case Number: 1310-73-2
Name: BLDG-001 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 497-19-8
Name: BLDG-001 OAKITE LOW HEAT CLEANER 1 CLEANER
Other Information: OAKITE LOW HEAT CLEANER 1 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-9
Name: BLDG-001 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: BLDG-001 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SCA 636
Other Information: SCA 636
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SHELL SOL 340 HT
Other Information: SHELL SOL 340 HT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-001 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SODIUM HYDROSULFIDE SOLID
Other Information: SODIUM HYDROSULFIDE SOLID
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-001 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: BLDG-001 TECTYL 802A/MIL-L-3150 A9944 LUBE
Other Information: TECTYL 802A/MIL-L-3150 A9944 LUBE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 75-09-2
Name: BLDG-001 TURCO 5351 CLEANER/STRIPPER
Other Information: TURCO 5351 CLEANER/STRIPPER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 6834-92-0
Name: BLDG-001 TURCO HTC METAL CLEANER
Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 TURCO PRETREAT
Other Information: TURCO PRETREAT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 V LUBE B
Other Information: V LUBE B
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 78-92-2
Name: BLDG-001 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: BLDG-001 WITHROW X49 DRAWING COMPOUND
Other Information: WITHROW X49 DRAWING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-001 ZL-66A ZYGLO WATER WASHABLE PENETRANT
Other Information: ZL-66A ZYGLO WATER WASHABLE PENETRANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-001 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-003 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-003 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-003 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-003 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-85-4
Name: BLDG-005 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-98-6
Name: BLDG-009 LPG GAS
Other Information: LPG GAS - PROPANE

Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-011 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-011 BULK ARGON
Other Information: BULK ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-011 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-019 ARGON
Other Information: ARAGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-019 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-019 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-21-1
Name: BLDG-025 ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Other Information: ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-025 UNLEADED FUEL BULK
Other Information: UNLEADED FUEL BULK
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 1-8% OXYGEN IN ARGON
Other Information: 1-8% OXYGEN IN ARGON
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

SECTION 1: FACILITY DETAIL REPORTS

...Continued...

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 7544/139
Other Information: 7544/139
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-029 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: BLDG-029 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-029 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-029 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ARGON AIR PRODUCT
Other Information: ARGON AIR PRODUCT
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 AS-150 ANTI-SLIP COATING 440
Other Information: AS-150 ANTI-SLIP COATING 440
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 DOK DEODORIZED KERONSENE

Other Information: DOK DEODORIZED KERONSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 FR-5317-W EPOXY RESIN
Other Information: FR-5317-W EPOXY RESIN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 25068-38-6
Name: BLDG-029 FR-5317-W EPOXY RESIN SYSTEM
Other Information: FR-5317-W EPOXY RESIN SYSTEM
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-029 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-029 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-029 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-029 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-029 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-029 ULTRACAL 30
Other Information: ULTRACAL 30
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-88-4
Name: BLDG-029 UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Other Information: UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-030 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-030 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 ACETONE UNION CARBIDE
Other Information: ACETONE UNION CARBIDE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 DOK DEODORIZED KEROSENE
Other Information: DOK DEODORIZED KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 HELIUM MG
Other Information: HELIUM MG
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 ISOPROPYL ALCOHOL UNION
Other Information: ISOPROPYL ALCOHOL UNION
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported

Name: BLDG-031 ROHR BLEND #1
Other Information: ROHR BLEND #1
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-031 SHELL SOL 340 HT
Other Information: SHELL SOL 340 HT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-032 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-032 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-032 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG--032 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: BLDG-036 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-036 DOK DEORDORIZED KEROSENE
Other Information: DOK DEORDORIZED KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-036 LIQUID NITROGEN
Other Information: LIQUID NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-036 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE

Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1
Name: BLDG-036 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-53-6
Name: BLDG-036 SOLVOL 6582 COOLANT
Other Information: SOLVOL 6582 COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-211-1
Name: BLDG-038 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-038 MOBIL DELVAC 1230
Other Information: MOBIL DELVAC 1230
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-040 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 321-N
Other Information: 321-N
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: BLDG-045 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012

Case Number: 74-86-2
Name: BLDG-045 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-045 ALODINE 1500 LIQUID
Other Information: ALODINE 1500 LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 ALUMINUX
Other Information: ALUMINUX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Other Information: ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: BLDG-045 AMMONIUM BIFLUORIDE-F
Other Information: AMMONIUM BIFLUORIDE-F
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: BLDG-045 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: BLDG-045 BULK HELIUM LINDE #13LR11
Other Information: BULK HELIUM LINDE #13LR11
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 CAUSTIC SODA 50% LIQUID
Other Information: CAUSTIC SODA 50% LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7778-50-9
Name: BLDG-045 DEOXIDIZER 17 REPLENISHER
Other Information: DEOXIDIZER 17 REPLINISHER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 DEOXIDIZER 7 MAKE-UP
Other Information: DEOXIDIZER 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 EPOXY PRIMER 10P4-16
Other Information: EPOXY PRIMER 10P4-16
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 GMC 528-B
Other Information: GMC 528-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 111-76-2
Name: BLDG-045 GMC 528-B METAL CLEANER
Other Information: GMC 528-B METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7647-01-0
Name: BLDG-045 HYDROCHLORIC ACID
Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-39-3
Name: BLDG-045 HYDROFLUORIC ACID 49%
Other Information: HYDROFLUORIC ACID 49%
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457

Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 KLEENSWEEP WAX BASE 1320
Other Information: KLEENSWEEP WAX BASE 1320
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-045 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: BLDG-045 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NA9194 DEOXID 7 MAKE-UP
Other Information: NA9194 DEOXID 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NABC NON-ACID BATH CLNR
Other Information: NABC NON-ACID BATH CLNR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 NITRIC ACID BULK
Other Information: NITRIC ACID BULK

Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 497-19-8
Name: BLDG-045 OAKITE LOW HEAT CLEANER 1 CLEANER
Other Information: OAKITE LOW HEAT CLEANER 1 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-045 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: BLDG-045 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 SCA 636
Other Information: SCA 636
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-045 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 SODIUM HYDROSULFIDE SOLID
Other Information: SODIUM HYDROSULFIDE SOLID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-045 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

SECTION 1: FACILITY DETAIL REPORTS

...Continued...

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: BLDG-045 TT-L-32A AM1 TYPE 2 17875 INS WHT/5432320078750
Other Information: TT-L-32A AM1 TYPE 2 17875 INS WHT/5432320078750
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 75-09-2
Name: BLDG-045 TURCO 5351 CLEANER/STRIPPER
Other Information: TURCO 5351 CLEANER/STRIPPER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 6834-92-0
Name: BLDG-045 TURCO HTC METAL CLEANER
Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 TURCO PRETREAT
Other Information: TURCO PRETREAT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-045 ZL-66A ZYGLO WATER WASHABLE PENETRANT
Other Information: ZL-66A ZYGLO WATER WASHABLE PENETRANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-045 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: BLDG-048 KEROSENE
Other Information: KEROSENE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-050 ATM-2000-X1 FUSED SILICA

Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-92-2
Name: BLDG-050 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: BLDG-054 OXYGEN BULK LIQUID
Other Information: OXYGEN BULK LIQUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-054 PROPANE
Other Information: PROPANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-055 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-055 ARGON GENERIC
Other Information: ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-058 ELECTRO-OX
Other Information: ELECTRO-OX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-058 GARNET SAND
Other Information: GARNET SAND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: BLDG-058 GARNET SAND 60 GRIT
Other Information: GARNET SAND 60 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 ACETYLENE LIQUID AIR
Other Information: ACETYLENE LIQUID AIR
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: REACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 LIQUID ARGON GENERIC
Other Information: LIQUID ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-061 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 2528-36-1
Name: BLDG-061 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500 B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-067 ARGON AIR PROD
Other Information: ARGON AIR PROD
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-067 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 2528-36-1
Name: BLDG-067 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-068 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-070 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7

Name: BLDG-070 OXYGEN LIQUID
Other Information: LIQUID OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-081 SAFESTEP SORBENT
Other Information: SAFESTEP SORBENT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1333-82-0
Name: BLDG-085 ALODINE 1200R LIQUID
Other Information: ALODINE 1200R LIQUID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 77-92-9
Name: BLDG-085 ANHYDROUS CITRIC ACID, U.S.P.F.C.C.
Other Information: ANHYDROUS CITRIC ACID, U.S.P. F.C.C.
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10043-35-3
Name: BLDG-085 BORIC ACID
Other Information: BORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-085 DEOXIDIZER 7 MAKE-UP
Other Information: DEOXIDIZER 7 MAKE-UP
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-085 SODIUM BICHROMATE ANHYDROUS
Other Information: SODIUM BICHROMATE ANHYDROUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10588-01-9
Name: BLDG-085 WCD 315L INHIBITOR/DISPERSANT-SODIUM BICHROM
Other Information: WCD 315L INHIBITOR/DISPERSANT-SODIUM BICHROM
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 ALODINE 1500 HENKEL
Other Information: ALODINE 1500 HENKEL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 AQUA QUENCH 260-B
Other Information: AQUA QUENCH 260-B
Material Waste: Material
Hazardous Categories 1: ACUTE

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: BLDG-092 CAUSTIC SODA
Other Information: CAUSTIC SODA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 HOUGHTO-DRAW 650
Other Information: HOUGHTO-DRAW 650
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-092 NITRIC ACID
Other Information: NITRIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-90-5
Name: BLDG-092 SODIUM BISULFITE
Other Information: SODIUM BISULFITE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-092 SULFURIC ACID
Other Information: SULFURIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: BLDG-092 SULFURIC ACID SOLUTION
Other Information: SULFURIC ACID SOLUTION
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-098 FLOOR DRY
Other Information: FLOOR DRY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-41-7
Name: BLDG-099 ANHYDROUS AMMONIA
Other Information: ANHYDROUS AMMONIA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: BLDG-114 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012

Case Number: Not reported
Name: BLDG-114 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDG-114 CARBON DIOXIDE
Other Information: CARBON DIOXIDE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-114 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: BLDG-114 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1
Name: BLDG-310 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-10-1
Name: BLDG-311 ROHR SOLVENT BLEND T3163001
Other Information: ROHR SOLVENT BLEND T3163001
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: BLDG-341 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLDSG-001 LUBRICOOLANT 2050AC
Other Information: LUBRICOOLANT 2050AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: BLSG-029 D-STROY
Other Information: D-STROY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-21-1
Name: CMST- 002 HOUGHTO-SAFE 620 HYDRAULIC SYSTEMS FLUID
Other Information: HOUGHTO-SAFE 620 HYDRAULIC SYSTEMS FLUID
Material Waste: Material

Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 74-86-2
Name: CMST-001 ACETYLENE
Other Information: ACETYLENE
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-37-1
Name: CMST-001 ARGON
Other Information: ARGON
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: CMST-001 CHEVRON SOLUBLE OIL B
Other Information: CHEVRON SOLUBLE OIL B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-001 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7440-59-7
Name: CMST-001 HELIUM
Other Information: HELIUM
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: CMST-001 KOLENE DGS (DESCALING CHEMICAL) BEADS
Other Information: KOLENE DGS (DESCALING CHEMICAL) BEADS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-001 LIQUID NITROGEN
Other Information: LIQUID NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-001 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-001 OXYGEN
Other Information: OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457

Update Date: 11/02/2012
Case Number: 67-64-1
Name: CMST-002 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7732-18-5
Name: CMST-002 ACTIVOL 1357 WETTING AGENT
Other Information: ACTIVOL 1357 WETTING AGENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 141-43-5
Name: CMST-002 CEE BEE A276 COATING REMOVER (55 GAL DRUMS) ST
Other Information: CEE BEE A276 COATING REMOVER (55 GAL DRUMS)ST
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: CMST-002 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 107-21-1
Name: CMST-002 ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Other Information: ETHYLENE GLYCOL ANTIFREEZE GRADE/CODE 32371/940
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-63-0
Name: CMST-002 ISOPROPANOL, ANHYDROUS
Other Information: ISOPROPANOL, ANHYDROUS
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: CMST-002 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL DELVAC SAE 30 OIL
Other Information: MOBIL DELVAC SAE 30 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL DTE 24 OIL
Other Information: MOBIL DTE 24 OIL

Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL HYDRAULIC OIL 220
Other Information: MOBIL HYDRAULIC OIL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL MULTI-PURPOSE ATF OIL
Other Information: MOBIL MULTI-PURPOSE ATF OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBIL VACUOLINE 1405 OIL
Other Information: MOBIL VACUOLINE 1405 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-002 MOBIL VELOCITE OIL NO 6
Other Information: MOBIL VELOCITE OIL NO 6
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8012-95-1
Name: CMST-002 MOBILUBE HD 80W-90 GEAR LUBE
Other Information: MOBILUBE HD 80W-90 GEAR LUBE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8052-41-3
Name: CMST-002 SOLVENT M-4 (CLEANING, COMPOUND LIQUID)
Other Information: SOLVENT M-4 (CLEANING, COMPOUND LIQUID)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68477-31-6
Name: CMST-002 TURCO 4460 SOLVENT
Other Information: TURCO 4460 SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8008-20-6
Name: CMST-002 VINYL MODIFIED CASTOR OIL CODE H2006
Other Information: VINYL MODIFIED CASTOR OIL CODE H2006
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 127-18-4
Name: CMST-003 AC-850 MASKANT
Other Information: AC-850 MASKANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

SECTION 1: FACILITY DETAIL REPORTS

...Continued...

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7632-00-0
Name: CMST-003 AQUA QUENCH 251 LUBE/COOLANT
Other Information: AQUA QUENCH 251 LUBE/COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: CMST-003 HOUGHTO-DRAW 650 LUBRICANT
Other Information: HOUGHTO-DRAW 650 LUBRICANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8042-47-5
Name: CMST-003 MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Other Information: MAGNAFLUZ/MAGNAGLO CARRIER II KEROSENE MIX
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: CMST-003 PENRECO AMBER (PETROLATUM)
Other Information: PENRECO AMBER (PETROLATUM) CODE 4510
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7664-93-9
Name: CMST-003 SULFURIC ACID 66 DEG BE
Other Information: SULFURIC ACID 66 DEG BE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-92-2
Name: CMST-003 VF-77 DEBURRING COMPOUND
Other Information: VF-77 DEBURRING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 6834-92-0
Name: CMST-004 TURCO HTC METAL CLEANER
Other Information: TURCO HTC METAL CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-53-6
Name: CMST-005 SOLVOL 6582 COOLANT
Other Information: SOLVOL 6582 COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 02353 ANTI-FREEZE COOLANT
Other Information: 02353 ANTI-FREEZE COOLANT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 1-8% OXYGEN IN ARGON

Other Information: 1-8% OXYGEN IN ARGON
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 7544/139
Other Information: 7544/139
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-815-0 THINNER
Other Information: AC-815-0 THINNER
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-818-0-30 MASK (W7-65C)
Other Information: AC-818-0-30 MASK (W7-65C)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AC-850
Other Information: AC-850
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ACTIVOL 1357
Other Information: ACTIVOL 1357
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ALODINE 1500 HENKEL
Other Information: ALODINE 1500 HENKEL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AQUA-QUENCH 251B
Other Information: AQUA-QUENCH 251B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARDROX 180-B
Other Information: ARDROX 180-B
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARDROX 7050-W
Other Information: ARDROX 7050-W
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON AIR PROD
Other Information: ARGON AIR PROD
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON GENERIC
Other Information: ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ARGON LIQUID AIR
Other Information: ARGON LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 AS-150 ANTI-SLIP COATING
Other Information: AS-150 ANTI-SLIP COATING
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ATM-2000-X1 FUSED SILICA
Other Information: ATM-2000-X1 FUSED SILICA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BLASOCUT 2000 CF
Other Information: BLASOCUT 2000 CF
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BLASOCUT 4000 STRONG
Other Information: BLASOCUT 4000 STRONG
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BORIC ACID US BORAX
Other Information: BORIC ACID US BORAX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BRUSH WASH SOL RX-3500
Other Information: BRUSH WASH SOL RX-3500
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported

Name: CMST-006 BUCKEYE SHOPMASTER
Other Information: BUCKEYE SHOPMASTER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BUCKEYE SHOPMASTER RTU
Other Information: BUCKEYE SHOPMASTER RTU
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 BUCKEYE WORKOUT
Other Information: BUCKEYE WORKOUT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CASTING PLASTER REG
Other Information: CASTING PLASTER REG
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CEE BEE A-276
Other Information: CEE BEE A-276
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 CLOROX BLEACH
Other Information: CLOROX BLEACH
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DIESEL FUEL BULK
Other Information: DIESEL FUEL BULK
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DIVERSEY WYANDOTTE 202
Other Information: DIVERSEY WYANDOTTE 202
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 DRAW TEMP 430
Other Information: DRAW TEMP 430
Material Waste: Material
Hazardous Categories 1: CHRONIC

Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 D-STROY
Other Information: D-STROY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ELECTRO-OX
Other Information: ELECTRO-OX
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FERROUS SULFATE HEPTAHYDR
Other Information: FERROUS SULFATE HEPTAHYDR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FORMULA 28
Other Information: FORMULA 28
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 FYRQUEL 220
Other Information: FYRQUEL 220
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HELIUM LIQUID AIR
Other Information: HELIUM LIQUID AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HELIUM MG
Other Information: HELIUM MG
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HOUGHTO-SAFE 620
Other Information: HOUGHTO-SAFE 620
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 HYDROCHLORIC ACID
Other Information: HYDROCHLORIC ACID
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012

Case Number: Not reported
Name: CMST-006 HYDROFLUORIC ACID 49% LCI
Other Information: HYDROFLUORIC ACID 49% LCI
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 JETTACIN
Other Information: JETTACIN
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 KOLENE DGS
Other Information: KOLENE DGS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LIQUID ARGON GENERIC
Other Information: LIQUID ARGON GENERIC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LIQUID CAUSTIC SODA 50%
Other Information: LIQUID CAUSTIC SODA 50%
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LIQUID HELIUM PRAXAIR
Other Information: LIQUID HELIUM PRAXAIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: CMST-006 LIQUID OXYGEN
Other Information: LIQUID OXYGEN
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 LUBRICOOLANT AC
Other Information: LUBRICOOLANT AC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1309-42-8
Name: CMST-006 MAGNESIUM HYDROXIDE SUS
Other Information: MAGNESIUM HYDROXIDE SUS
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MF ACID
Other Information: MF ACID
Material Waste: Material

Hazardous Categories 1: REACTIVE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MISSION SPRAY 93
Other Information: MISSION SPRAY 93
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DELVAC 1230
Other Information: MOBIL DELVAC 1230
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE 25
Other Information: MOBIL DTE 25
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL DTE OIL EXTRA HEAVY
Other Information: MOBIL DTE OIL EXTRA HEAVY
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL STE 24
Other Information: MOBIL DTE 24
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACTRA OIL NO. 2
Other Information: MOBIL VACTRA OIL NO. 2
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACTRA OIL NO. 4
Other Information: MOBIL VACTRA OIL NO. 4
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBIL VACUOLINE 1409 OIL
Other Information: MOBIL VACUOLINE 1409 OIL
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 MOBILMET OMEGA
Other Information: MOBILMET OMEGA
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 NABC NON-ACID BATH CLNR
Other Information: NABC NON-ACID BATH CLNR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 NITRIC ACID BULK
Other Information: NITRIC ACID BULK
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: CMST-006 NITROGEN LIQUID AIR
Other Information: NITROGEN LIQUID AIR
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 OXYGEN MG
Other Information: OXYGEN MG
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 PROPANE
Other Information: PROPANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ROHR BLEND #1
Other Information: ROHR BLEND #1
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SODIUM BISULFITE
Other Information: SODIUM BISULFITE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SODIUM HYPOCHLORITE 12.5%
Other Information: SODIUM HYPOCHLORITE 12.5%
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 SULFURIC ACID GENERAL
Other Information: SULFURIC ACID GENERAL

Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO 4215 NC-LT
Other Information: TURCO 4215 NC-LT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO 5351
Other Information: TURCO 5351
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: EXTREMELY HAZARDOUS

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 TURCO HTC
Other Information: TURCO HTC
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ULTRACAL 30
Other Information: ULTRACAL 30
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 V LUBE B
Other Information: V LUBE B
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: CMST-006 ZYGLO PENE ZL-67
Other Information: ZYGLO PENE ZL-67
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL FUEL
Other Information: BLDG 118 COGENERATION PLANT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 103-24-2
Name: DIOCTYL AZELATE
Other Information: QUINSYN COMPRESSOR OIL
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL - COOLANT
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, METAL CHIPS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, METAL CHIPS IN COOLANT
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, RINSE WATER FROM CHEM PROCESS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: EXCLUDED RECYCLABLE MATERIAL, X-RAY FIXER SOLUTION
Other Information: RECYCLABLE SILVER SALTS IN SOLUTION
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7783-06-4
Name: HYDROGEN SULFIDE, 25 PPM IN NONFLAMMABLE CALIBRATION GAS
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68037-01-4
Name: LUBRIPLATE SYNLUBE HD 220
Other Information: 1-DECENE, HOMOPOLYMER, HYDROGENATED
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: MF ACID
Other Information: AMMONIUM BIFLUORIDE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-54-7
Name: MOBIL DTE 25
Other Information: PETROLEUM LUBRICANT
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: MOBILGEAR 600 XP 150
Other Information: BASE OIL & ADDITIVES
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: MOBILGREASE XHP 005

Other Information: BASE OIL & ADDITIVES
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 10024-97-2
Name: NITROUS OXIDE
Other Information: LAUGHING GAS
Material Waste: Material
Hazardous Categories 1: REACTIVE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: PEGASUS 1005 NATURAL GAS ENGINE OIL
Other Information: PETROLEUM OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: MIXTURE
Name: PT2114
Other Information: WHITE EPOXY LAMINATING RESIN
Material Waste: Material
Hazardous Categories 1: CHRONIC
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 541-02-6
Name: QSOL 300 LOW VOC SOLVENT
Other Information: DECAMETHYLCYCLOPENTASILOSANE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7782-44-7
Name: SHED 415 COMPRESSED AIR
Other Information: COMPRESSED AIR
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7727-37-9
Name: SHED 415 NITROGEN
Other Information: NITROGEN
Material Waste: Material
Hazardous Categories 1: PRESSURE RELEASE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-64-1
Name: SHED-327 ACETONE
Other Information: ACETONE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7732-18-5
Name: SHED-327 ACTIVOL 1357 WETTING AGENT
Other Information: ACTIVOL 1357 WETTING AGENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8030-30-6
Name: SHED-327 CHEVRON THINNER 325
Other Information: CHEVRON THINNER 325
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 67-63-0
Name: SHED-327 ISOPROPANOL, ANHYDROUS
Other Information: ISOPROPANOL, ANHYDROUS
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 78-93-3
Name: SHED-327 MEK SOLVENT
Other Information: MEK SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 68477-31-6
Name: SHED-327 TURCO 4460 SOLVENT
Other Information: TURCO 4460 SOLVENT
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-88-4
Name: SHED-327 UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Other Information: UNOCAL KOOLKUT II HD (CODE 04780) CUTTING OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 111-76-2
Name: SHED-356 321-N COATING
Other Information: 321-N COATING
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: SHED-356 ABRASIVE GARNET SAND 60-80 GRIT
Other Information: ABRASIVE GARNET SAND 60-80 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7631-86-9
Name: SHED-356 ABRASIVE GRIT GARNET SAND BAC 5748 150 GRIT
Other Information: ABRASIVE GRIT GARNET SAND BAC 5748 150 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: SHED-356 ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Other Information: ALUMINUX (ALKALINE ETCHANT FOR ALUMINUM)
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1341-49-7
Name: SHED-356 AMMONIUM BIFLUORIDE
Other Information: AMMONIUM BIFLUORIDE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 471-34-1

Name: SHED-356 CALCIUM CARBONATE
Other Information: CALCIUM CARBONATE
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: SHED-356 DEOXIDIZER 17 REPLENISHER
Other Information: DEOXIDIZER 17 REPLENISHER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1344-28-1
Name: SHED-356 FUSED ALUMINUM OXIDE 240 GRIT
Other Information: FUSED ALUMINUM OXIDE 240 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1344-28-1
Name: SHED-356 FUSED ALUMINUM OXIDE 46 GRIT
Other Information: FUSED ALUMINUM OXIDE 46 GRIT
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 56550-16-0
Name: SHED-356 FYRQUEL 220 (FIRE RESISTANT HYDRAULIC FLUID)
Other Information: FYRQUEL 220 (FIRE RESISTANT HYDRAULIC FLUID)
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 1310-73-2
Name: SHED-356 OAKITE 90 CLEANER
Other Information: OAKITE 90 CLEANER
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 8009-03-8
Name: SHED-356 PETROLATUM T1585
Other Information: PETROLATUM T1585
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 2528-36-1
Name: SHED-356 SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Other Information: SKYDROL 500B-4 FIRE RESISTANT HYDRAULIC FLUID
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64742-52-5
Name: SHED-356 TECTYL 802A/MIL-L-3150 A9944 LUBE
Other Information: TECTYL 802A/MIL-L-3150 A9944 LUBE
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 108-88-3
Name: SHED-356 TURCO PRETREAT SCALE INHIBITOR
Other Information: TURCO PRETREAT SCALE INHIBITOR
Material Waste: Material
Hazardous Categories 1: FIRE

Hazardous Categories 2: ACUTE

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 64741-97-5
Name: SHED-356 WITHROW X49 DRAWING COMPOUND
Other Information: WITHROW X49 DRAWING COMPOUND
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: 7446-09-5
Name: SULFUR DIOXIDE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: ACUTE
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS
Other Information: CAUSTUC LIQUIDS/SOLIDS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS
Other Information: TANK E2 ETCH CLEAN DIVERSEY 202
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS -
Other Information: ALKALINE CLEAN
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 121 ALKALINE SOL'N WITH METALS*
Other Information: TANKS R8 & R13 SODIUM HYDROXIDE CHEMICAL MILLING SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 132 AQUEOUS SOL'N WITH METALS
Other Information: PHOSPHATE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: AQUA QUENCH COOLANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: WASTE COOLANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012

Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: SOAP/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 151 ASBESTOS CONTAINING WASTE
Other Information: ASBESTOS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE
Other Information: FILTER CAKE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE
Other Information: WATER JET SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE (OTHER)
Other Information: LAZER JET FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE*
Other Information: FERROUS ALUMINUM SILICATE-GARNET, ALUMINA & SILICA SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 171 METAL SLUDGE*
Other Information: WASTE WATER TREATMENT FILTER CAKE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 172 METAL DUST & MACHINING WASTE
Other Information: SAND
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 172 METAL DUST & MACHINING WASTE
Other Information: WASTE LASER JET FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: CHEMICAL BAGS
Material Waste: Waste

Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)
Other Information: PAINT FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) -
Other Information: LAB PACK - MERCURY
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) --
Other Information: BAG HOUSE FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) ---
Other Information: LP - KOLENE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER) PAINTF
Other Information: PAINT FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: DRAW-TEMP 430 SALT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: KOLENE DGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE CHEMICAL BAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE GRINDING DEBRIS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE LEAD DROSS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)*
Other Information: WASTE PAINT BOOTH FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 181 INORGANIC SOLID WASTE (OTHER)LEAD
Other Information: LEAD DROSS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 214 UNSPEC SOLVENT MIXTURE
Other Information: PAINT/SOLVENTS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: MACHINE OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: MOBIL PEGASUS 801 OIL, ROHR G/S #5655-0879-010588
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: BASE OIL AND ADDITIVES
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: CHRONIC

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: MOBIL GEAR 600 XP 320 GEAR OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: MOBILMET 766 CUTTING OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL*
Other Information: WASTE MACHINE OIL

Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL.
Other Information: TECTYL 502C CLASS I PRESERVATIVE OIL G/S #5855-0850-009823
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information: WASTE OIL SUMP SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 241 TANK BOTTOM WASTE
Other Information: HAULER CODE: 2431 SUMP SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 241 TANK BOTTOM WASTE
Other Information: WASTE SUMP SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: WASTE PAINT & SOLVENT W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: PAINT RELATED
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: ABSORBANT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: OILY ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER) -
Other Information: CONTAMINATED RAGS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)*
Other Information: WASTE PAINT & SOLVENT RAGS W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: U.S. BATTERY
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 461 PAINT SLUDGE
Other Information: WASTE PAINT DEBRIS W/CHROME
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 611 CONTAMINATED SOIL
Other Information: SITE ASSESSMENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 723 LIQUIDS W CHROMIUM - R
Other Information: HENKEL DEOXIDIZER 6/16 MAKE-UP & REPLENISHER FOR TANK E4
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 791 LIQUIDS WITH PH <OR= 2
Other Information: TANK D6 NITRIC ACID PASSIVATION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS
Other Information: ALODINE 1500
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS
Other Information: CHROMIC, NITRIC
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS -
Other Information: BORRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS -

Other Information: NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS --
Other Information: R-20 HF ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS ---
Other Information: F-8 SULFURIC ACID, CHROMIUM
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS ----
Other Information: HYDROFLUORIC/NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: ALODINE 1200 & 1500 LIQUID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: DILUTE SULFURIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: MIXUTRE OF CHROMIC ACID & NITRIC ACID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: R20 TITANIUM CHEMICAL MILLING SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: TANK R11 TURCO SMUT-GO NCB NONCHROMATED DESMUT SOLUTION
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 792 LIQUIDS W/PH <OR= 2 W/METALS*
Other Information: TANKS D3 & D4 STEEL & TITANIUM CLEANER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 901 INFECTIOUS WASTE, GENERAL
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 102457
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 902 INFECTIOUS WASTE, SHARPS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0207
Violation: FIRE/EXPLOSION/RELEASE NOT MINIMIZED
Violation Citation: Facility not maintained &/operated to minimize possibility of fire, explosion or release. CCR 66265.31
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0142
Violation: DID NOT NOTIFY OF TIERED PERMITTING
Violation Citation: TIERED PERMITTING: Facility has failed to notify local CUPA and DTSC of eligible onsite treatment of hazardous waste. 25201(a)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 06/26/2006
Violation Code: 6HV0218
Violation: FILTERS:FUEL/OIL NOT LABELED OR CLOSED
Violation Citation: Failed to label &/or close drained used oil filters &/or used fuel filters. 25250.22 and 66266.130(c)(3)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 04/14/2004
Violation Code: 6HV4209
Violation: NO GENERATOR'S INFO ON RED BAGS/SHARPS
Violation Citation: Red bags, sharps containers not labeled with generator's name, address, and phone number. 68.1205
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 04/14/2004
Violation Code: 6HV1605
Violation: NO DAILY TANK INSPECTION/LOG
Violation Citation: Failed to inspect and/or document daily HW tank system inspections. 66265.195 (c)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 03/03/2009
Violation Code: 6HV1007
Violation: HIGHLY TOXIC GAS NOT ON CHEM INVENTORY
Violation Citation: Highly toxic gas (TLV less than or equal to 10 ppm) not disclosed in chemical inventory. 68.1113(b)
Activity: ACTIVE

Permit Number: 102457
Update Date: 11/02/2012
Inspection Date: 03/03/2009
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: ACTIVE

UST:

UST Name: UNDERGROUND TANK 102457 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5284
Capacity Gallons: 1200
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-06 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T045
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 500
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-26 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T046
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-26 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T047
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T048
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287

Capacity Gallons: 1500
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T049
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 5000
UST Contents: DIESEL
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T050
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT5287
Capacity Gallons: 350
UST Contents: DIESEL
Other Content Info: Not reported
Reg Status: REMOVED
Remove Close Date: 2006-10-26 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 102457 T022
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#7
Capacity Gallons: 100
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1993-07-28 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T023
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 1 - C-70 SALT ACTIVE PROCESS TANK, IN VAULT, V
Capacity Gallons: 3600
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T024
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: OTHER
Additional Id: BLD 1 - C-70 RINSE ACTIVE PROCESS TANK, IN VAULT,

Capacity Gallons: 3600
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T025
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: OTHER
Additional Id: 15-C70Q C-70 QUENCH TANK
Capacity Gallons: 3600
UST Contents: Not reported
Other Content Info: NON-HAZARDOUS RINSE WATER
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: UNKNOWN
Delivery System: Not reported
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T026
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 1 - V1 DEGREASER 1,1,1, TRI CLOSED PER 3/27/98
Capacity Gallons: 10
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2003-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T027
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 1 - V2 DEGREASER 1,1,1, TRI CLOSED PER 3/27/98
Capacity Gallons: 10
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2003-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T028
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 45 - PAINT BOOTH 45-3, CLOSED PER 3/27/98 DEH
Capacity Gallons: 4314
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T029
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: 3-09598 BLANCHARD GRINDER : MACHINING COOLANT

Capacity Gallons: 1345
UST Contents: Not reported
Other Content Info: BLANCHARD GRINDER : MACHINING
Reg Status: CLOSED
Remove Close Date: 1999-06-15 00:00:00
Year Installed: Not reported
Pipe Type: UNKNOWN
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T030
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 30 - PAINT BOOTH 30-1, PE NOT UST CLOSED IN PL
Capacity Gallons: 3810
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T031
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 45 - KOLENE TANK IN VAULT PROCESS TANK CLOSED
Capacity Gallons: 6720
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T032
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 30 - C72 SALT BATH PROCESS TANK IN VAULT CLOSE
Capacity Gallons: 1400
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T033
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 1 - C-70 TOWER SUMP CLOSED IN PLACE PER 3/27/9
Capacity Gallons: 1681
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T034
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 1 - NC MACHINE SHOP DRUM CLOSED AT4410

Capacity Gallons: 55
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1999-06-01 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T035
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 30 - ALODINE SUMP CLOSED ET0039
Capacity Gallons: 22
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2000-06-01 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T036
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 61 - PAINT BOOTH SUMP 61-3 (EXEMPT TANK CLOSE
Capacity Gallons: 129
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T037
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 3 - TRANSFER SUMP WASTEWATER
Capacity Gallons: 750
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T038
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 3 - S LINE SUMP WASTEWATER
Capacity Gallons: 345
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T039
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 30 - PAINT BOOTH SUMP WASTEWATER

Capacity Gallons: 62
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T040
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT4591
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: OTHER - SPECIFY
Reg Status: REMOVED
Remove Close Date: 2000-04-24 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 99
UST Monitor Method: OTHER - BLIND REMARK REQUIRED

UST Name: UNDERGROUND TANK 102457 T041
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: ET0039
Capacity Gallons: 4000
UST Contents: Not reported
Other Content Info: OTHER - SPECIFY
Reg Status: REMOVED
Remove Close Date: 2000-07-06 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 99
UST Monitor Method: OTHER - BLIND REMARK REQUIRED

UST Name: UNDERGROUND TANK 102457 T042
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: ET0039
Capacity Gallons: 20
UST Contents: Not reported
Other Content Info: OTHER - SPECIFY
Reg Status: REMOVED
Remove Close Date: 2000-07-06 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 99
UST Monitor Method: OTHER - BLIND REMARK REQUIRED

UST Name: UNDERGROUND TANK 102457 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT0004
Capacity Gallons: 100
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: 1988-11-02 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: 0000
Capacity Gallons: 10000
UST Contents: DIESEL
Other Content Info: DIESEL

Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1973-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 2
Capacity Gallons: 50
UST Contents: LEADED
Other Content Info: LEADED
Reg Status: REMOVED
Remove Close Date: 1993-02-03 00:00:00
Year Installed: 1979-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 07
UST Monitor Method: SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name: UNDERGROUND TANK 102457 T004
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 000
Capacity Gallons: 10000
UST Contents: LEADED
Other Content Info: LEADED
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1973-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T005
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 000
Capacity Gallons: 10000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1973-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T006
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: 000
Capacity Gallons: 10000
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1965-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: AT4828
Capacity Gallons: 6000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED

Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1987-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T008
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: AT4828
Capacity Gallons: 6000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1987-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T009
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: DOUBLE WALL
Additional Id: AT4828
Capacity Gallons: 6000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1987-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: SUCTION
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name: UNDERGROUND TANK 102457 T010
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 1 - COOLANT, EXEMPT CLOSED IN PLACE PER 3/27/9
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 2002-06-07 00:00:00
Year Installed: 1983-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T011
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: AT0374
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: INVALID CODE
Reg Status: REMOVED
Remove Close Date: 1988-11-02 00:00:00
Year Installed: 1974-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T012
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: BLD 3 - MASKANT EMERGENCY DUMP TANK CLOSED BY REMO
Capacity Gallons: 3000
UST Contents: Not reported
Other Content Info: Not reported

Reg Status: REMOVED
Remove Close Date: Not reported
Year Installed: 1968-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T013
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: NOTTINGHAM SUMP WASTE WATER WITH 0.00008% HEAVY ME
Capacity Gallons: 1500
UST Contents: Not reported
Other Content Info: WASTE WATER WITH 0.00008% HEAV
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T014
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: EQUALIZATION SUMP WASTE WATER WITH 0.00028% HEAVY
Capacity Gallons: 40000
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: EXEMPT
Remove Close Date: Not reported
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 25
UST Monitor Method: EXTERNAL MONITOR : CONTINUOUS VADOSE ZONE VAPOR MONITORS AND / OR WEEKLY (MINIMUM) VADOSE ZONE LIQUID MONITORING

UST Name: UNDERGROUND TANK 102457 T015
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: SINGLE WALL
Additional Id: R-ID#11 WATER-EXEMPT AS NONHAZARDOUS
Capacity Gallons: 600
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: 1968-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T016
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 45 - PAINT BOOTH 45-7
Capacity Gallons: 18000
UST Contents: Not reported
Other Content Info: Not reported
Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: 1985-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T017
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: BLD 45 - PAINT BOOTH 45-8
Capacity Gallons: 10000
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL

Reg Status: CLOSED
Remove Close Date: 1998-03-27 00:00:00
Year Installed: 1985-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T018
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#22
Capacity Gallons: 4000
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1993-02-03 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T019
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: 3-13888
Capacity Gallons: 255
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T020
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#18
Capacity Gallons: 4000
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T021
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: UNKNOWN
Additional Id: R-ID#19
Capacity Gallons: 120
UST Contents: Not reported
Other Content Info: GASOLINE & WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1993-06-22 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 102457 T043
Last Update: 2012-11-02 14:17:38
Permit Number: 102457
Tank Type: Not reported
Additional Id: AT4757
Capacity Gallons: Not reported
UST Contents: Not reported
Other Content Info: Not reported

Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	Not reported
UST Monitor Method:	Not reported

UST Name:	UNDERGROUND TANK 102457 T044
Last Update:	2012-11-02 14:17:38
Permit Number:	102457
Tank Type:	Not reported
Additional Id:	AT4757
Capacity Gallons:	Not reported
UST Contents:	Not reported
Other Content Info:	Not reported
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	Not reported
UST Monitor Method:	Not reported

SECTION 2: DATABASES AND UPDATE DATES

To maintain currency of the following federal, state and local databases, EDR contacts the appropriate government agency on a monthly or quarterly basis as required.

Elapsed ASTM days: Provides confirmation that this report meets or exceeds the 90-day updating requirement of the ASTM standard.

DATABASES FOUND IN THIS REPORT

CA HMMD SAN DIEGO: Hazardous Materials Management Division Database
Source: Hazardous Materials Management Division
Telephone: 619-338-2268
The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 08/31/2020
Database Release Frequency: Quarterly

Date of Last EDR Contact: 12/01/2020
Date of Next Scheduled Update: 03/15/2021

APPENDIX D: QUALIFICATIONS

PARTNER

Education

Bachelor of Arts, Political Science, University of California, Irvine, CA
Diploma, Executive Assistant Business Program, Heald Business College, Hayward, CA

Registrations

California EPA Registered Environmental Assessor I – 07364
California OSHA Certified Site Surveillance Technician No. 97-2116

Training

40-Hour OSHA HAZWOPER Training
EPA-Certified AHERA Asbestos Building Inspector
EPA-Certified AHERA Contractor/Supervisor/Competent Person

Highlights

15 + years of experience in the environmental due diligence industry:

- Phase I Environmental Site Assessments
- Phase II Environmental Site Assessments
- Property Condition Assessments
- Asbestos Surveys
- Transaction Screen Assessments
- Environmental Desktop Reviews and Reports
- UST Removal
- Regulatory Work Plan Preparation for remediation of hazardous materials
- Business Development / Client Relations

Experience Summary

Ms. Thomas is a Project Assessor at Partner Engineering and Science, Inc. (Partner) and is located out of the Torrance, California office. She is responsible for conducting Phase I Environmental Site Assessments (ESA) including site reconnaissance, regulatory file review, historical research, interpretation of data and maps, and technical writing. Ms. Thomas has broad project experience from small privately owned properties to large portfolios of industrial sites in both the private and public sectors. This experience includes properties with impact to soil and groundwater from petroleum and solvent releases and required extensive regulatory file review. Ms. Thomas has received training in risk management and liability as it pertains to environmentally impacted properties.

Project Experience

Initial Site Assessment for Freeway Expansion, Los Angeles County, California. Performed an *Initial Site Assessment* for California Department of Transportation (Caltrans) for the Interstate 5 Freeway expansion project in Burbank, Glendale and Los Angeles, which included 10 miles of assessment area and many properties with hazardous materials, USTs and groundwater contamination issues.

Initial Study and Biological Survey, Madera, California. City of Madera, California: Performed an *Initial Study* for the City of Madera Wastewater Treatment Plant expansion project, which included a Biological Survey and assessment for hazardous materials.

Phase I Environmental Site Assessment and Underground Storage Tank Removal, Beverly Hills, California. Project Manager for the removal of an old waste oil underground storage tank that was identified through due diligence research, which was subsequently removed and received case closure from the Los Angeles County Environmental Programs Division.

Phase II Environmental Site Assessment and Work Plan for Remedial Action, Garden Grove, California. Project Manager for site characterization of a former dry cleaner that included a soil gas survey, soil sampling and the installation of five groundwater monitoring wells. Ms. Thomas conducted the initial Phase II ESA, which identified soil and groundwater impact. Preparation of a Work Plan for site characterization was approved by the Santa Ana Regional Water Quality Control Board and implemented.

Phase II Environmental Site Assessment, Inglewood, California. Project Manager of a *Phase II ESA* on a former gas station property that was redeveloped in the early 1980s into a coin operated laundry mat. The client was a prospective buyer of the property. Limited information pertaining to the former gas station was identified at the local regulatory agencies; therefore, a Phase II scope of work was designed and implemented to best identify the former UST and piping locations. Significantly contaminated soil was identified.

Phase I Environmental Site Assessment, Downtown Los Angeles, California. Performed a *Phase I ESA* for the Los Angeles County Metropolitan Transportation Authority (MTA) for its Division One Bus Depot Expansion project on a site in downtown Los Angeles that was a former Texaco Super Truck Service Depot with former fueling, carwash and automotive services. Ms. Thomas has performed several Phase I ESA projects for the Los Angeles County MTA.

Contact

mathomas@partneresi.com

Caroline Ziegler, PG
Project Manager

Education

MS, Geology, Texas A&M University, College Station, TX
BA, Geology, Trinity University, San Antonio, TX

Registrations

Professional Geologist: California, 2005, No. 7825

Training

29 CFR 1910.120 40-hour HAZWOPER, Hazard Communication, Safety Awareness, Project Delivery, Asbestos Awareness, and other project management related courses.

Highlights

30+ years of experience in environmental consulting and regulatory compliance
30+ years performing site inspections for determination of environmental regulatory compliance, site investigations in advance of environmental cleanups, sampling and analysis of contaminated soil and groundwater to determine impacts to human health and the environment, development of remedial action plans for site cleanups, negotiating cleanup requirements with federal, state and local environmental regulatory agencies, preparing reports that meet project specific documentation requirements, conducting Phase I and II Environmental Site Assessments
30 + years with commercial, industrial, residential and military sites

Experience Summary

Ms. Ziegler is a Project Manager at the Partner Engineering and Science, Inc. (Partner) Dallas, Texas office supporting Phase I and Phase II Environmental Site Assessments. She has recently contributed to preparation of documentation on multiple Site Mitigation projects, including subsurface investigations and remediation, that involve regulatory agency requirements for approval.

Ms. Ziegler is an environmental professional experienced with managing projects for commercial, industrial, municipal and federal clients, including U.S. Environmental Protection Agency (USEPA) and U.S. Department of Defense. Ms. Ziegler recently relocated back to Dallas, Texas after seventeen years as an environmental compliance consultant, both for a large environmental consulting firm and as an independent. She has demonstrated her ability to define and map environmental project scopes, specifications, timelines, resources, and budgets. She has a keen ability to gain stakeholders acceptance from proposal stage through project closeout. Ms. Ziegler maintains her Professional Geologist license from the State of California and is working toward obtaining the same licensure in Texas.

Over the span of her career, Ms. Ziegler has managed the oversight of large, complex environmental remedial action projects for industrial clients and federal entities. Her areas of expertise include project management, soil and groundwater site investigations, remedial action oversight and environmental regulatory compliance under CERCLA, RCRA, and California state agencies, including the State Water Resources Control Board (SWRCB) and Department of Toxic Substances Control (DTSC). She was considered the leading senior project manager of the Western Region for conducting five-year reviews at sites undergoing remedial activities that included operations and maintenance of groundwater treatment systems, soil vapor extraction, landfill gas and leachate collection, and soil removal and disposal.

Project Experience

Alicia Towne Center, Mission Viejo, California. Ms. Ziegler prepared a site characterization workplan in response to a pending Voluntary Cleanup Agreement (VCA) with DTSC's Brownfields Restoration and School Evaluation Branch. Previous investigations have shown that the property has elevated concentrations of tetrachloroethene (PCE) and related compounds in soil and soil gas resulting from operations of former dry cleaners. The workplan proposes further investigation of chlorinated volatile organic constituents in the soil and soil gas to delineate the lateral and vertical extent and be prepared to propose remedial alternatives if necessary.

Southern Nevada Operating Engineers Training Center, Las Vegas, Nevada. Ms. Ziegler oversaw preparation of a Limited Subsurface Investigation report based upon the findings of a Phase I ESA report identifying Recognized Environmental Conditions. The constituents of concern were identified in the soil samples, and included volatile organic compounds, total petroleum hydrocarbons, metals, asbestos and lead.

Allmark Plaza, Rancho Cucamonga, California. Ms. Ziegler prepared a revised Removal Action Workplan based on comments received from the DTSC's Brownfields Restoration and School Evaluation Branch. The workplan presents a scope of work to remove concentrations of tetrachloroethene (PCE) and related compounds identified in soil and soil gas on the property that resulted from operations of a former dry cleaner. The removal action workplan proposes installation of a soil vapor extraction (SVE) system.

Former Industrial Facilities, Los Angeles, California. Ms. Ziegler prepared both a soil management plan (SMP) and a soil excavation work plan. The purpose of the SMP is to outline protocol for ensuring the proper handling and/or disposal of impacted soil that may be encountered during future grading and/or other redevelopment activities. Specifically, the SMP includes a brief summary of the site history and potential chemicals of concern (COCs) and provides guidance for the following: identifying suspected impacted soil; managing and stockpiling graded soil (e.g., dust control, stockpile maintenance); collecting and analyzing samples from stockpiled soil as necessary to establish waste classification; establishing specific threshold levels to evaluate whether excavated soil is suitable for reuse on-site; and handling and/or disposing of soil with confirmed impacts. The focused Arsenic Remedial Excavation Work Plan (Work Plan) was prepared as required by the Los Angeles County Fire Department's Site Mitigation Unit to remediate soils containing elevated concentrations of arsenic on the property.

Iconex, Joplin, Missouri and Local Portfolio, Toledo, Ohio area. Ms. Ziegler conducted site visits and was responsible for the completion of Phase I Environmental Site Assessments (ESAs) for five total sites.

Project Compass (Confidential Client), various Canadian Provinces. Ms. Ziegler helped oversee the completion of Phase I activities at six power generation facilities in the Alberta and Saskatchewan Provinces. Two out of the six sites were coal-fired power plants. The activities included conducting the site inspections, review of regulatory database and other historical information, and preparation of detailed environmental assessment reports.

Lennar Mare Island, Vallejo, CA. Ms. Ziegler served as project manager/task lead for hazardous waste sites on a multi-million dollar project to redevelop a local naval base. She managed a team to define and implement manageable scopes of work, cost estimates, and schedules that satisfied both regulatory agency and divergent stakeholder needs. Incorporated various task components into the development of these

items, such as initial scope development to selecting a task team to obtaining final regulatory approval. Was responsible for preparing multiple project deliverables with strict deadlines and frequent project scope changes. Developed field investigation work plans, remedial technology evaluations, and summary reports while incorporating both client and state agency inputs. Organized and prioritized multiple tasks for field and office staff with the goal of maintaining budgets and achieving schedule milestones.

Publications

"*Assessment of Human Exposure to Naturally Occurring (Unprocessed) Asbestos at the Clear Creek Management Area, California*." Suer, Lynn; Den, Arnold; Lane, Jackie; Stralka, Daniel; Brass, Brian; Moore, Timothy; Ross, Steve; Ziegler, Caroline; and Braun, Richard. Presented by USEPA at the GSA Cordilleran Section 101st Annual Meeting, April 2005.

Contact

cziegler@partneresi.com

Michael P. Arias
Technical Director
Investment Advisory Group

Education

B.S. Urban and Regional Planning, California State Polytechnic University, Pomona, CA

Training

Safety Assessment Volunteer, State of California

Highlights

35 years in the architectural and construction fields
Extensive knowledge of real estate due diligence
25 years of experience with institutional and private clients
Acquisitions/dispositions and mortgage lending property condition assessments
Construction monitoring services

Experience Summary

Mr. Arias serves as the Technical Director for the Investment Advisory Group (IAG) of the Building Science Division of Partner Engineering and Science, Inc. (Partner). IAG provides technical support to the Equity Asset Management industry by providing capital improvement cost-benefit analysis on real estate transactions. IAG produces a more thorough Property Condition Assessment for the institutional and equity client beyond the "ASTM E2018-08 Standard Guide for Property Condition Assessments: Baseline Property Condition Assessment Process". In order to provide a detailed level of assessment, IAG engages both in-house engineers and trade specialists including, but not limited to, structural/seismic engineers, Mechanical/Electrical/Plumbing engineers, Fire/Life Safety and Code specialists and elevator, roof and accessibility specialists. IAG supports equity acquisitions and dispositions assessments on office buildings, multi-family residential, retail, hotel and industrial properties.

Mr. Arias has completed hundreds of Property Condition Assessments (PCAs) including planning, field work, report preparation/quality control, and client contact on a myriad of acquisition/disposition projects including: high-rise offices; suburban office; regional and local retail centers; industrial; and multi-family housing projects. He has provided owner's representation services on various projects for institutional investors. Mr. Arias managed the review of numerous document reviews for institutional-level development projects in all disciplines on a variety of projects including office, retail, industrial, multi-family, etc. These reviews consisted of projects noted in the Owner's Representation Services. He has also performed job captain and project manager responsibilities for a design/build general construction firm specializing in industrial concrete tilt-up construction, retail centers and auto dealerships. He has significant knowledge of the accessibility requirements of ADA and FHA, and is currently a candidate for California's CASp (Certified Access Specialist) program.

Additionally, over the past 15 years, Mr. Arias' responsibilities also included evaluation of staff; developing new skills and improving existing skills within the staff; scheduling of personnel; maintaining quality control practices consistent with company goals; and participated in development of protocols and practices to serve national clients of the firm.

Project Experience

Multi-Family Project, Oakland, CA. Organized and led a team of engineers and specialists to conduct an equity-level property condition assessment of a five-story, 300+ unit apartment project in downtown Oakland, CA. The project had been dormant prior to the client purchasing the property, therefore, the client required a detailed assessment of the building systems but also an assessment of investigation and construction documentation. The team consisted of structural engineers performing a seismic risk assessment; elevator, roof and façade specialists; mechanical, electrical, plumbing and fire/life safety engineers and an acoustical engineer. Mr. Arias assessed all other systems including the ADA and FFHA accessibility elements of the project. Mr. Arias led team in meetings with client and their counsel.

Hospitality Project, San Jose, CA. Organized and led a team of engineers and specialists to conduct an equity-level property condition assessment of a 28-story, 500+ guestroom, 400,000-square foot hospitality project in downtown San Jose, CA. The institutional client required a detailed assessment of the building systems including an assessment of the façade from the building's swing stage due to observed water intrusion issues. The team consisted of structural engineers performing a seismic risk assessment; elevator, roof and façade specialists; mechanical, electrical, plumbing and fire/life safety engineers, as well as a specialist to sample the fire sprinkler water to identify microbial influence corrosion (MIC) in the fire sprinkler piping system. Mr. Arias assessed all other systems including the ADA accessibility elements of the project.

Retail Project, Emeryville, CA. Organized and led a team of engineers and specialists to conduct an equity-level property condition assessment of a popular and active 800,000-square foot mixed-use project in Emeryville, CA. The institutional client required a detailed assessment of the building systems including destructive testing of several locations of the façade to confirm construction of the exterior walls. The team consisted of structural engineers performing a seismic risk assessment, roof and façade specialists, mechanical, electrical, plumbing and fire/life safety engineers. Mr. Arias assessed all other systems including the ADA accessibility elements of the project.

Senior Housing Portfolio, Numerous Sites in US. Assisted with organizing teams to conduct disposition property condition assessments of 30 senior housing projects throughout the West and Midwest. The client required a summary of issues identified by the field assessors. Mr. Arias reviewed all property condition assessments for accuracy and quality control.

Owners' Representation Services. Mr. Arias has provided owner's representation services on various projects for institutional investors, including recent developments of numerous 50 to 250-unit multi-family projects in Santa Monica, Los Angeles, and Glendale, CA., several concrete tilt-up industrial developments in the Inland Empire area of Southern California and San Diego totaling over 1 million square feet; major hospitality projects consisting of the W-Hotel and Manchester Grand Hyatt Hotel in San Diego and several large "big box" retail centers in the San Fernando Valley in Southern California.

Project Management Services, Southern California. Mr. Arias managed staff and performed Project Management services on numerous projects including reconstruction of balcony decks of an existing multi-family project in Pasadena, California; forensic analysis and resealing of a plaza deck, also in Pasadena and an exterior wall repair, plaza deck waterproofing, and structural repair project for a homeowner association of a large condominium project in Marina del Rey.

Affiliations

American Institute of Architects, Associate
Certified Access Specialist Institute, Associate
International Code Council

Contact

marias@partneresi.com

Misty Vazquez Ponce, PE
Principal

Education

M.S. Civil-Environmental Engineering, California State University, Fullerton
B.S. Environmental Engineering, University of California, Riverside
Coursework in Legal and Regulatory Framework for Environmental Management, University of California Irvine
Coursework in Mold Inspection

Registrations

Professional Engineer, Colorado
Engineer-In Training (EIT), California
State of California Registered Environmental Assessor (program canceled in July 2012)
LEED Green Associate (GA) Accredited Professional, United States Green Building Council
AHERA Certified Building Inspector for Asbestos

Training

OSHA 40-hour HAZWOPER, Operations Level Health and Safety Training
OSHA 10-hour Construction Safety Training
Trained/Certified – Hazardous Waste in California, US Department of Transportation Hazardous Materials Transportation, and USEPA Hazardous/Toxic Waste management (LION)

Highlights

Over 16 years in the environmental and engineering consulting industry with institutional and private clients
Environmental Engineer
Extensive knowledge of real estate due diligence
Phase I and Phase II Environmental Site Assessments
Site Mitigation and Remediation

Experience Summary

Ms. Ponce is an environmental engineer with more than 16 years of experience in the environmental and engineering services industries. As a Principal and National Client Manager working within Partner's Investment Advisory Group, Ms. Ponce strives to provide the expected high level of client service for the Equity Asset Management industry.

Ms. Ponce has significant experience in the field of environmental due diligence, site assessment, remediation, and regulatory compliance. Ms. Ponce provides environmental support to clients nationwide during the acquisition, disposition, development, and on-going management and operation of commercial, industrial, and multifamily residential properties.

Ms. Ponce has considerable experience in Phase I and Phase II Environmental Site Assessments (ESAs) of commercial, agricultural, and industrial properties and projects involving water quality, soil quality, and regulatory compliance including hazardous and solid waste site characterization and remediation; remediation system design installation, and operation; tank removals; asbestos surveys; lead-based paint surveys; radon studies; mold assessments; lead-in water sampling and analysis; and technical reporting.

Ms. Ponce has been involved with feasibility and treatability studies associated with several remediation projects including soil and groundwater treatment systems, UST/LUST closures, and management of construction soils generated during redevelopment of agricultural and industrial properties. Other equity and finance level services managed and directed by Ms. Ponce include management of Property Condition Assessments, ALTA Land Surveys, zoning reports, Seismic Risk Assessments (PML), Construction Risk Management, construction monitoring services, and construction document cost review analysis.

Real estate investors, financial institutions, insurance lenders, property managers, developers, and brokers have come to rely on her advice and judgment to help them with their real estate business decisions. Ms. Ponce is a dedicated professional who takes pride and pleasure in meeting her client's needs and spearheading and assembling the team with the expertise to handle any issue that may come up during the real estate transaction.

Project Experience

Ms. Ponce has conducted, managed, and directed thousands of ESAs, industrial hygiene, and engineering assessments throughout her career, nationally and globally. The following select projects and client base provide a glimpse of her consulting experience and due diligence background:

Ford Leasing Development Company / Sunset Ford, Westminster, California. Conducted a Phase I and II ESA and remedial activities at a closing automobile dealership with 41 service bays containing active, decommissioned, or removed in-ground hydraulic vehicle lifts. The Phase II ESA identified petroleum hydrocarbon and VOC impacts in soil and groundwater in the immediate vicinity of the lifts. Based on the identified impacts, managed the removal of all lifts and contaminated soil under regulatory oversight and conducted a comprehensive site investigation, including well installation and soil, groundwater, and soil vapor sampling. Prepared and submitted final reports to the client and regulatory agencies and obtained regulatory site closure.

UBS Realty Investors, LLC, Riverside, California. Conducted a Phase I ESA of an approximately 36-acre commercial shopping center containing retail stores; restaurants; banks; grocery stores; a movie theater; hair, nail, and beauty salons; and a dry cleaner in a total of 16 buildings. Work included site reconnaissance, tenant inspections, site history review, database search, and final report preparation with recommendations for additional assessment.

USDA Forest Service, Mountain Center, California. Prepared a Soil Excavation and Groundwater Well Installation Workplan to assess a release that was discovered during the removal of two 1,000-gallon USTs. Elevated contaminant concentrations were detected in confirmation soil samples collected at that time. Installed one groundwater monitoring well into fractured bedrock and later abandoned the well due to planned excavation activities in the area. A groundwater sample collected prior to well abandonment contained elevated contaminant concentrations. Prepared a Site Investigation Summary Report summarizing site activities and investigations to date. Prepared a Groundwater Assessment Workplan to assess the extent of contaminant concentrations in groundwater. Site assessment work is pending.

American Golf Corporation, Eighteen Sites in Southern California. Managed underground storage tank removal and closure activities. Work included performing initial confirmation soil sampling and analysis and subsequent monitoring and soil and/or groundwater testing in association with the removal of the

underground storage tanks, associated dispensers, and piping at sixteen sites located throughout Southern California. Prepared soil and/or groundwater investigation workplans as needed to address contamination issues at several of the sites and closure reports for the various State and local authorities. To date, regulatory closure has been obtained at most of the facilities. Currently managing ongoing monitoring and/or remediation is occurring at several of the facilities.

G.E. Capital, Tijuana, Mexico. Managed and conducted more than 30 Phase I and Phase II ESAs for active and proposed industrial developments within various areas of Tijuana, Mexico. Work included site reconnaissance, site history review, and final report preparation.

Affiliations

Member, Commercial Real Estate Development Association (NAIOP)
Member, Urban Land Institute (ULI)
Member, National Ground Water Association (NGWA)
Associate Member, American Society of Civil Engineers (ASCE)
Member, Commercial Real Estate Women (CREW)
Member, Groundwater Resources Association (GRA) of California
Intern Environmental Engineer, American Academy of Environmental Engineers (AAEE)
Member, International Council of Shopping Centers (ICSC)

Contact

mponce@partneresi.com