PHASE I AND LIMITED PHASE II ENVIRONMENTAL SITE ASSESSMENT
VERNOLA RANCH NORTH PROJECT
12080 BELLEGRAVE AVENUE
CITY OF JURUPA VALLEY, RIVERSIDE COUNTY, CALIFORNIA 91752

October 25, 2021

Project No. 2903-CR

Prepared For:

Vernola Trust
P.O. Box 217
Upland, California 91785-0217

GEOTEK

GeoTek, Inc.
1548 North Maple Street, Corona, California 92878
(951) 710-1160 Office (951) 710-1167 Fax www.geotekusa.com

October 25, 2021
Project No. 2903-CR

Vernola Trust
P.O. Box 217
Upland, California 91785-0217

Attention: Mr. Rick Bondar

Subject: Phase I and Limited Phase II Environmental Site Assessment
Vernola Ranch North Project
12080 Bellegrave Avenue
City of Jurupa Valley, Riverside County, California 91752

Dear Mr. Bondar:

GEOTEK, INC. (GEOTEK) is pleased to present this Phase I and Limited Phase II Environmental Site Assessment for the above-referenced subject Site. Services were conducted in substantial conformance with the scope and limitations of the American Society of Testing and Materials E 1527-13, "*Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process,*" which is approved to meet the requirements of the federal All Appropriate Inquiries (AAI) standards as set forth in the Code of Federal Regulations, Title 40, Section 312 (40 CFR 312), and GEOTEK'S Proposal No. P-0706821-CR, dated July 23, 2021.

This Phase I and Limited Phase II Environmental Site Assessment has not revealed evidence of a recognized environmental condition or concern in connection with the subject Site. Stained soils associated with two (2) 55-gallon drums located in the northeast portion of the Site should be cleaned up to visual limits as a housekeeping measure. No further investigation is required at this time.

We appreciate this opportunity to be of service. If you have any questions, or if we can be of further service, please contact us at (951) 710-1160.

Sincerely,
GEOTEK, INC.



Edward H. LaMont
Principal Geologist, CEG 1892
Expires 07/31/2022

J. Michael Batten, CEM, REPA
Environmental Services Manager
Registered Environmental Property
Assessor No. 113162
Expires 06/15/2022

Anna M. Scott
Project Geologist

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY 1
2.0 INTRODUCTION 4
2.1 Purpose 4
2.2 Scope of Work 4
2.3 Significant Assumptions 5
2.4 Limitations and Exceptions 6
2.5 Special Terms and Conditions 6
2.6 Reliance 6
3.0 DESCRIPTION OF SITE AND SURROUNDING AREA 8
3.1 Site Location and Legal Description 8
3.2 Site and Vicinity General Characteristics 8
3.3 Current Property Use 8
3.4 Site Improvements 8
3.4.1 Hazardous Substances 9
3.4.2 Storage Tanks 9
3.4.3 Poly-Chlorinated Biphenyls (PCBs) 9
3.4.4 Controlled Substances 9
3.4.5 Indications of Solid Waste Disposal 9
3.4.6 Utility Supply 10
3.4.7 Drainage 10
3.4.8 Other Conditions of Concern 10
3.4.9 Interviews 10
3.5 Current Adjoining Property Use 10
4.0 CLIENT PROVIDED INFORMATION 12
4.1 Environmental Clean Up Liens 12
4.2 Activity and Use Limitations 12
4.3 Specialized Knowledge 12
4.4 Purchase Price 12
4.5 Commonly Known Information 12
4.6 Obvious Indicators of Contamination 13
4.7 Owner, Property Manager and Occupant Information 13
4.8 Reason for Performing Phase I ESA 13
4.9 Other User Provided Information 13
5.0 PROPERTY PHYSICAL SETTING 14
5.1 Regional Geology 14
5.2 Local Geologic Setting and Topography 14
5.3 Vicinity Surface Drainage 14

TABLE OF CONTENTS

5.4 HYDROGEOLOGY 15
6.0 ENVIRONMENTAL REGULATORY RECORDS REVIEW 16
6.1 ENVIRONMENTAL DATABASE RECORDS SEARCH 16
6.2 DISCUSSION OF REGULATORY RECORDS 17
6.2.1 NATIONAL PRIORITY LIST 17
6.2.2 SUPERFUND ENTERPRISE MANAGEMENT SYSTEM 18
6.2.3 RESOURCE CONSERVATION AND RECOVERY ACT 18
6.2.4 EMERGENCY RESPONSE NOTIFICATION SYSTEM 19
6.2.5 FEDERAL INSTITUTIONAL CONTROL/ENGINEERING CONTROL REGISTRIES 19
6.2.6 STATE RESPONSE SITES 19
6.2.7 ENVIROSTOR DATABASE 19
6.2.8 CALIFORNIA HAZARDOUS MATERIAL INCIDENT REPORT SYSTEM 20
6.2.9 SOLID WASTE FACILITIES LIST 20
6.2.10 LEAKING UNDERGROUND STORAGE TANKS LIST 20
6.2.11 UNDERGROUND STORAGE TANKS LIST 21
6.2.12 SPILLS, LEAKS, INVESTIGATION AND CLEANUP COST RECOVERY LISTING (SLIC) 22
6.2.13 STATE INSTITUTIONAL CONTROL/ENGINEERING CONTROL REGISTRIES 22
6.2.14 TRIBAL DATABASES 22
6.2.15 OTHER DATABASES 22
6.2.16 DRY CLEANERS 25
6.2.17 UNMAPPABLE FACILITIES 25
6.3 LOCAL REGULATORY AGENCY RECORDS 25
7.0 VAPOR ENCROACHMENT SCREEN 27
8.0 SITE AND SURROUNDING AREA HISTORY 28
8.1 HISTORICAL SITE USAGE 28
8.1.1 AERIAL PHOTOGRAPH REVIEW 28
8.1.2 TOPOGRAPHIC MAP REVIEW 28
8.1.3 BUILDING DEPARTMENT RECORDS 29
8.1.4 CITY DIRECTORY REVIEW 29
8.1.5 SANBORN MAP REVIEW 30
8.1.6 CHAIN OF TITLE 30
8.2 HISTORICAL IMMEDIATELY SURROUNDING PROPERTY USAGE 30
8.2.1 AERIAL PHOTOGRAPH REVIEW 30
8.2.2 TOPOGRAPHIC MAP REVIEW 31
8.2.3 CITY DIRECTORIES 32
8.2.4 SANBORN MAP REVIEW 32
8.3 HISTORICAL USE SUMMARY 32

TABLE OF CONTENTS

9.0 SIGNIFICANT DATA GAPS 34
10.0 SUMMARY OF LIMITED SOIL ANALYSIS 35
11.0 CONCLUSIONS AND RECOMMENDATIONS 38
12.0 CERTIFICATIONS 39
13.0 REFERENCES 40

LIST OF APPENDICES

Appendix A: Figures
Appendix B: Supporting Documents
Appendix C: Photographs
Appendix D: Environmental Database Report
Appendix E: Vapor Encroachment Screening
Appendix F: Laboratory Test Results
Appendix G: Project Team Qualifications

1.0 EXECUTIVE SUMMARY

GEOTEK, INC. (GEOTEK) has performed a Phase I and Limited Phase II Environmental Site Assessment (ESA) for the subject property: the Vernola Ranch North Project (the "Site"), located in the City of Jurupa Valley, Riverside County, California. Our services were conducted in substantial conformance with the scope and limitations of the American Society of Testing and Materials (ASTM) E 1527-13, "*Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process*", which is approved to meet the requirements of the federal All Appropriate Inquiries (AAI) standards as set forth in the Code of Federal Regulations, Title 40, Section 312 (40 CFR 312), and GEOTEK Proposal No. P-0706821-CR, dated July 23, 2021. Any additions or deletions from our scope of services are discussed in the appropriate sections of this assessment.

A representative of GEOTEK conducted a Site reconnaissance on October 12, 2021. The weather was warm and the sky was clear. The irregular shaped Site is currently comprised of five (5) parcels of land (Riverside County Assessor's Parcel Numbers (APNs) 160-050-070; 160-050-063; 160-050-072; 160-050-067; and 160-050-068) and a portion of four (4) parcels of land (APNs 160-050-023; 160-050-073; 160-050-005; and 160-050-074) and encompasses a total of approximately 161.8 acres. The Site can generally be accessed from Bellegrave Avenue.

The Site is currently occupied by Vernola Ranch, an active corn field which is in turn utilized for grain. Structures located in the northern portion of the Site consist of two residential structures, two modular homes and three metal barns. The interiors of all the Site structures were not observed during our Site reconnaissance. Several storage areas were observed containing equipment and old machinery. Two water wells were observed in the northeastern portion of the Site.

Visual evidence of hazardous substances and wastes were not observed during our Site reconnaissance. Drums of what appeared to be waste oil were observed near the most northeastern barn structure along with stained soils below the wooden pallets that the drums were placed on. The stained soils should be cleaned to visual limits as a housekeeping measure Other visual indication of spills, leaks and stains were not observed. No pungent or acrid odors were observed emanating from the Site.

The Site is in an area largely characterized by residential development. The Site is bounded Bellegrave Avenue, followed by vacant land to the north. Pats Ranch Road, followed by Vernola Park (5211 Wineville Avenue), Skyview Events Community Center (5257 Wineville Avenue) and a residential development (Harvest Villages at Vernola Ranch) bound the Site to the east. A portion of the ranch (corn field), followed by a park and ride, followed by Limonite

Avenue, bound the Site to the south. Interstate 15, followed by two residential developments (Homecoming at Eastvale and Swan Lake Mobile Home Park) borders the Site to the west.

Based on readily available historic information, the Site appears to have been vacant land from at least 1931 until at least 1948. The Site appears to have been utilized for agriculture from at least 1953 until present day. Structures in the northern portion of the Site can first be observed in an aerial photograph dated 1985. The surrounding properties appear to historically have been utilized for agriculture, scattered residences or vacant from at least 1931 until at least 1967. Swan Lake Mobile Home Park can be observed in an aerial photograph dated 1975. Interstate 15 can be observed in an aerial photograph dated 1989. Homecoming at Eastvale can be observed in an aerial photograph dated 2006. Vernola Park is under construction in an aerial photograph dated 2009. Harvest Villages at Vernola Ranch can be observed in an aerial photograph dated 2016.

Historically, some agricultural sites have utilized pesticides that are currently considered a health risk and no longer used. This particular environmental concern was investigated by GEOTEK as part of this assessment. Near surface soil samples were collected from the Site and were analyzed for organo-chlorinated pesticides (EPA Method 8081) and arsenic (EPA Method 6010B). The laboratory testing concluded that organo-chlorinated pesticides and arsenic were not detected above regional screening levels (residential) in the soil samples tested. Based on this laboratory testing, it is our opinion that the historical agricultural use on the subject Site is not considered an environmental concern.

The Site appears on the environmental database report obtained for this assessment. The databases are the Federal Facility Index System (FINDS); SWEEPS UST, an underground storage tank listing that is no longer updated or maintained; EMI (Emissions Inventory Data); CERS (CalEPA Regulated Site Portal Data); Hazardous Waste Tracking System (HWTS), the state Facility and Management Data (HAZNET); and Underground Storage Tank (UST).

These listings are related to multiple former and current conditions documented at the Site regarding hazardous wastes. As there are no records of violations, spills, leaks, investigations, or clean-ups at the Site, these listings are not considered an environmental concern at the Site.

There are two (2) facilities listed on the database report within the various search distances specified by ASTM E 1527-13. Due to the facility status listings and/or locations, these facilities do not represent an environmental concern to the Site.

This Phase I and Limited Phase II Environmental Site Assessment has not revealed evidence of a recognized environmental condition or concern in connection with the subject Site. Stained soils associated with two (2) 55-gallon drums located in the northeast portion of the Site should be cleaned to visual limits as a housekeeping measure. No further investigation is required at this time.

This executive summary does not contain all the information that is found in the full report. The report should be read in its entirety to obtain a more complete understanding of the information provided and to aid in any decisions made or actions taken based on this information.

2.0 INTRODUCTION

GEOTEK, INC. (GEOTEK) has performed a Phase I and Limited Phase II Environmental Site Assessment (ESA) for the Vernola Ranch North Project (the "Site"), located in the City of Jurupa Valley, Riverside County, California.

2.1 PURPOSE

The purpose of this Phase I and Limited Phase II ESA was to identify and evaluate actual and potential environmental conditions involving the subject Site. It was not the purpose of this assessment to determine the degree or extent of contamination, if any, but rather the potential for contamination.

2.2 SCOPE OF WORK

The Phase I ESA is a general characterization of environmental concerns based on reasonably ascertainable information and observations. GEOTEK performed the Phase I and Limited Phase II ESA in substantial accordance with ASTM E 1527-13. The following services were provided for the assessment:

- A reconnaissance of the Site and surrounding properties to visually assess current utilization and indications of potential surface contamination. This was accomplished by driving the Site boundaries, and then traversing the Site until the entire Site had been surveyed.

- A reconnaissance of the surrounding area for approximately one-half mile was conducted, without entering the properties, making observations concerning property uses, conditions, and housekeeping.

- Interviews were conducted, either in person, via telephone, or via a written questionnaire(s) with the client representative, the seller's representative, and/or appropriate regulatory agency personnel.

- A review of the geologic and hydro-geologic settings was conducted using reasonably ascertainable public records and documents.

- An environmental database report was obtained from a data service provider. This database report compiles and locates documented "hazardous waste" facilities within specific minimum search distances as defined by ASTM E 1527-13. If necessary,

additional information on identified facilities was gathered by a file review at the appropriate federal, state, local, and/or tribal regulatory agency.

- A review of reasonably ascertainable historical records (including aerial photographs, topographic maps, building records, and city directories) was conducted to assess the historical land utilization and indications of potential contamination or sources of contamination for the Site.

- Collection of 20 near-surface soil samples for analysis of organochlorine pesticides in accordance with U.S. EPA Method 8081 and arsenic in accordance with U.S. EPA Method 6010B.

- This report was prepared, which relates the findings of this study and presents our conclusions and recommendations.

Specific items not included in this Scope of Services are water analysis, asbestos containing materials analysis, radon analysis, lead-based paint analysis, lead in drinking water, wetlands, regulatory compliance, cultural and historic resources, industrial hygiene, health and safety, ecological resources, endangered species, indoor air quality, vapor intrusion testing, high voltage power lines, and other items not within the scope of ASTM E 1527-13.

2.3 SIGNIFICANT ASSUMPTIONS

Specific assumptions by GEOTEK for this assessment include:

- GEOTEK had permission to access the Site grounds;

- The client has provided GEOTEK with available geotechnical or environmental reports for the Site;

- The client has provided GEOTEK with known current or historic uses of hazardous materials at the Site, or with other specialized knowledge of the environmental history of the Site and surrounding area;

- The client is not the sole and absolute source of information;

- Seller has provided proper and complete access to their knowledge, both written and verbal, and GEOTEK can rely on the information.

2.4 LIMITATIONS AND EXCEPTIONS

GEOTEK conducted a Phase I and Limited Phase II Environmental Site Assessment in substantial accordance with ASTM E 1527-13 and as authorized by Vernola Trust. This study does not include sampling of groundwater and/or materials on-site for environmental testing. This report is intended for the use of Vernola Trust. The contents should not be relied upon by any party other than the aforementioned without the express written consent of GEOTEK.

The findings, conclusions, and recommendations made in this report are based on the information that was made available to GEOTEK, in most instances from public records. The information is relevant to the date of our site work and should not be relied on to represent conditions at any later date. The opinions and conclusions expressed herein are based on information obtained during our assessment and on our experience and current standards of technical practice. GEOTEK makes no other warranties, either express or implied, concerning the completeness of the data furnished to us. GEOTEK cannot be responsible for conditions or consequences arising from relevant facts that were concealed, withheld, or not fully disclosed at the time our assessment was undertaken. GEOTEK is not responsible, nor liable for work, testing or recommendations performed or provided by others. This Phase I and Limited Phase II Environmental Site Assessment is not and should not be construed as a warranty or guarantee about the presence or absence of environmental hazards or contaminants, which may affect the subject site. Facts, conditions, and acceptable risk factors change with time; accordingly, this report should be viewed within this context.

Specific limitations to the scope of ASTM E 1527-13 due to contract limitations, availability of resources, and/or encountered Site conditions are discussed in the appropriate section(s) of this report.

2.5 SPECIAL TERMS AND CONDITIONS

This assessment report is presented as fulfilling the standard requirements of most financial institutions, governmental regulatory agencies, ASTM, and generally accepted industry standards and practices. Please refer to GEOTEK Proposal No. P-0706821-CR for complete terms and conditions for this assessment.

2.6 RELIANCE

This assessment has been prepared for the exclusive use and may be relied upon Vernola Trust and their successors and assignees and Lennar Homes. Third party reliance letters may be

issued upon request and upon the payment of the, then current, fee for such letters. All third parties relying on this report, by such reliance, agree to be bound by the General Conditions and Limitations agreed to by Vernola Trust. No reliance by any party is permitted without such agreement, regardless of the content of the reliance letter itself.

3.0 DESCRIPTION OF SITE AND SURROUNDING AREA

The objective of describing the Site and surrounding area is to document current conditions as observed and to obtain information which would indicate the likelihood of a recognized environmental condition in connection with the Site. A representative of GEOTEK conducted a Site reconnaissance on October 12, 2021. The weather was warm and the sky was clear. The Site can generally be accessed from Bellegrave Avenue.

3.1 SITE LOCATION AND LEGAL DESCRIPTION

The Site is located southwest of the intersection of Bellegrave Avenue and Pats Ranch Road and is addressed as 12080 Bellegrave Avenue in the City of Jurupa Valley, Riverside County, California. According to the U.S. Geological Survey (USGS) Corona North Quadrangle topographic map sheet (7.5-minute series), the Site is located in Section 18, Township 2 South, Range 6 West, San Bernardino Baseline and Meridian (see Figure 1 in Appendix A and documents in Appendix B). The irregular shaped Site is currently comprised of five (5) parcels of land (Riverside County Assessor's Parcel Numbers (APNs) 160-050-070; 160-050-063; 160-050-072; 160-050-067; and 160-050-068) and a portion of four (4) parcels of land (APNs 160-050-023; 160-050-073; 160-050-005; and 160-050-074) and encompasses a total of approximately 142 acres. Additional legal descriptions are provided in the Environmental Lien and AUL Search and a *Preliminary Report* (Stewart Title, 2021) included in Appendix B.

3.2 SITE AND VICINITY GENERAL CHARACTERISTICS

The Site is currently occupied by Vernola Ranch, an active corn field utilized for grain and associated structures. The Site is in an area largely characterized by residential development.

3.3 CURRENT PROPERTY USE

The Site is currently occupied by Vernola Ranch, an active corn field utilized for grain and associated structures.

3.4 SITE IMPROVEMENTS

Structures located in the northern portion of the Site consist of two residential structures, two modular homes and three metal barns. The interiors of all the Site structures were not observed during our Site reconnaissance. Several storage areas were observed containing equipment and old machinery. Photographs of the Site are included in Appendix C.

3.4.1 HAZARDOUS SUBSTANCES

Visual evidence of hazardous substances and wastes were not observed during our Site reconnaissance. Drums of what appeared to be waste oil were observed near the most northeastern barn structure along with stained soils below the wooden pallets that the drums were placed on. Stained soils should be cleaned to visual limits as a housekeeping measure. Other visual indication of spills, leaks and stains were not observed.

3.4.2 STORAGE TANKS

GEOTEK did not observe evidence of underground storage tanks (such as vent pipes, fill pipes, regular-shaped depressions, etc.) on the Site.

One (1) propane above-ground storage tank was observed during our Site reconnaissance. As propane is a gas at standard temperature and pressure, it is not considered to be an environmental concern to the Site.

3.4.3 POLY-CHLORINATED BIPHENYLS (PCBS)

GEOTEK did not observe suspect equipment (transformers, elevators, hydraulic lift mechanisms, trash compactors, etc.) which may contain PCBs on the Site.

3.4.4 CONTROLLED SUBSTANCES

GEOTEK consulted the U.S. Drug Enforcement Agency (DEA) website to cross-check the Site address against published facilities subject to DEA enforcement. The Site did not appear on the list of published facilities. A copy of the DEA printout is included in Appendix B.

GEOTEK did not observe evidence of illegal or controlled substances being used or manufactured at the Site.

3.4.5 INDICATIONS OF SOLID WASTE DISPOSAL

GEOTEK observed scattered various machinery and some debris on the Site. These items are intentionally stored at the Site. Waste disposal for the Site and Site area is provided by Burrtec Waste Industries.

3.4.6 UTILITY SUPPLY

Water and sewer services for the Site and area are provided by the Jurupa Community Services District. Electric service for the Site and area are provided by Southern California Edison. Natural gas services for the Site and area are provided by Southern California Gas Company.

3.4.7 DRAINAGE

Natural drainage at the Site is generally to the south, conforming to the natural topography in the area. Ponded water was not observed during our Site reconnaissance.

3.4.8 OTHER CONDITIONS OF CONCERN

Two (2) water wells were observed in the northeastern portion of the Site. These wells should be abandoned if no longer used in accordance with the local jurisdictional requirements. No other visual indication of other conditions of concern (drywells, cesspools, etc.) that would indicate a recognized environmental condition was observed during the Site reconnaissance.

3.4.9 INTERVIEWS

GEOTEK interviewed the following individuals while performing this assessment, in the form of completing a *User Questionnaire*:

- Mr. Richard Bondar (a representative of the current Site owner) partially completed a User Questionnaire.
- Mr. Chad Cleveland (a representative of the current Site user) partially completed a User Questionnaire?

Information from these interviews is incorporated into the appropriate sections of this report.

3.5 CURRENT ADJOINING PROPERTY USE

The Site is in an area largely characterized by residential development. The Site is bounded Bellegrave Avenue, followed by vacant land to the north. Pats Ranch Road, followed by Vernola Park (5211 Wineville Avenue), Skyview Events Community Center (5257 Wineville Avenue) and a residential development (Harvest Villages at Vernola Ranch) bound the Site to the east. A portion of the ranch (corn field), followed by a park and ride, followed by Limonite

Avenue, bound the Site to the south. Interstate 15, followed by two residential developments (Homecoming at Eastvale and Swan Lake Mobile Home Park) borders the Site to the west.

4.0 CLIENT PROVIDED INFORMATION

As a form of interview, Mr. Richard Bondar, a representative of the current Site owner and Mr. Chad Cleveland, a representative of the current site user, both partially completed a "User Questionnaire" for the Site in accordance with ASTM E 1527-13. Copies of the completed questionnaires are included in Appendix B.

4.1 ENVIRONMENTAL CLEAN UP LIENS

Mr. Bondar is not aware of any environmental clean-up liens at the Site.

4.2 ACTIVITY AND USE LIMITATIONS

Mr. Bondar is not aware of any activity use limitations at the Site.

4.3 SPECIALIZED KNOWLEDGE

Mr. Cleveland states "Pesticides for forage crops were applied as needed. No chemicals are/were stored on the property. A California Department of Pesticide Regulation licensed pest control advisor made all chemical application recommendations based on science, observation, chemical product label and laws/regulations. In addition, a licensed pest control operated performed all applications. Every chemical application was reported to and overseen by the Riverside County Agricultural Commissioner's Office."

4.4 PURCHASE PRICE

Mr. Bondar did not provide an answer when asked if the purchase price being paid for the Site reasonable reflects the fair market value of the Site.

4.5 COMMONLY KNOWN INFORMATION

Mr. Bondar states that he is aware of past uses of the Site but does not explain. Mr. Bondar states that he is aware of specific chemicals that are present or once were present at the Site and provides the single word "farmer". Mr. Bondar is not aware of any other commonly known or reasonably ascertainable information for the Site.

Mr. Cleveland states that he is aware that the past use of the property was "farming". Mr. Cleveland he is aware of specific chemicals that are present or once present at the property

and states "see attached for agricultural chemicals applied to growing crops". Mr. Cleveland is not aware of any other commonly known or reasonably ascertainable information for the Site.

4.6 Obvious Indicators of Contamination

Mr. Bondar and Mr. Cleveland both state that they are not aware of obvious indicators of a likely environmental impact at the Site.

4.7 Owner, Property Manager and Occupant Information

It is our understanding that Patrick Vernola, Trustee of the Chris McCabe Trustee created by the Anthony P. Vernola Trust U/D/T dated October 18, 2020, Bellatera Investments PA 13, LLC, a California limited liability company; Boomer Investments PA 13, LLC, a Delaware limited liability company; Shelina Investments PA 13, a California limited liability company; Sky Country Investment Co./East, LLC; Anthony P. Vernola, Trustee of the Anthony P. Vernola Trust under Trust Agreement dated October 18, 2000, and Anthony P. Vernola, Successor Trustee of the Pat and Mary Ann Vernola Trust – Marital Trust currently own and manage the Site. The Site is currently occupied by two (2) residence and the name of the occupants are unknown.

4.8 Reason for Performing Phase I and Limited Phase II ESA

This Phase I ESA was performed at the request of Vernola Trust as part of their due diligence for possible future improvements on the Site and to qualify for one of the Landowner Liability Protections offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2002.

4.9 Other User Provided Information

GeoTek was not provided with any additional information for the Site from an environmental perspective by Vernola Trust.

5.0 PROPERTY PHYSICAL SETTING

Surface and subsurface environments are of interest because they control the movement of water-born contaminants, which could be transported to and from the subject Site. GEOTEK reviewed information regarding the physical setting of the subject Site and immediately surrounding area.

5.1 REGIONAL GEOLOGY

The subject property is situated in the Peninsular Ranges geomorphic province. The Peninsular Ranges province is one of the largest geomorphic units in western North America. Basically, it extends roughly 975 miles from the north and extends from the Transverse Ranges geomorphic province to the tip of Baja California, from north to south. This province varies in width from about 30 to 100 miles. It is bounded on the west by the Pacific Ocean, on the south by the Gulf of California and on the east by the Colorado Desert Province.

The Peninsular Ranges are essentially a series of northwest-southeast oriented fault blocks. Several major fault zones are found in this province. The Elsinore Fault zone and the San Jacinto Fault zone trend northwest-southeast and are found in the near the middle of the province. The San Andreas Fault zone borders the northeasterly margin of the province.

5.2 LOCAL GEOLOGIC SETTING AND TOPOGRAPHY

The Site and Site area are understood to be underlain by alluvium (Morton, D.M. and Miller, F.K., 2006). Additional data regarding soil survey information for the Site and Site area is also included in Appendix B.

The Site and Site area can be considered as having relatively flat terrain. Based on the USGS topographic map for the area and other documents reviewed for this report, the elevation of the subject Site ranges from approximately 665 to 705 feet above mean sea level.

5.3 VICINITY SURFACE DRAINAGE

Natural drainage at the Site is interpreted to be to the south following the natural topography in the area. Storm water runoff does not appear to drain towards the Site from the adjacent properties due to existing streets and/or improvements.

According to the Federal Emergency Management Agency (FEMA), the Site is not located within a 100- or 500-year flood zone (see Appendix D).

5.4 HYDROGEOLOGY

According to a review of historical groundwater data (California Department of Water Resources and California State Water Resources Control Board groundwater well data [http://wdl.water.ca.gov and http://geotracker.waterboards.ca.gov]) and in-house information, depth to groundwater is greater than 50 feet below ground surface (bgs) in the general site area, with a flow direction to the south.

6.0 ENVIRONMENTAL REGULATORY RECORDS REVIEW

The records review is conducted to help identify known recognized environmental conditions at the Site and/or on adjacent or nearby properties which may have impacted the subject Site.

6.1 ENVIRONMENTAL DATABASE RECORDS SEARCH

GEOTEK obtained and reviewed an environmental database report of the federal and state environmental records specified by ASTM E 1527-13. The database report was provided by Environmental Data Resources, Inc. (EDR) of Shelton, Connecticut. Additionally, orphan or un-mappable sites listed by EDR were reviewed for the approximate minimum search distances noted and included in our discussion, if applicable. Refer to Appendix D for a copy of the database report.

ENVIRONMENTAL DATABASE	MINIMUM SEARCH DISTANCE	SITE	ADJACENT	TOTAL LISTED
U.S. Environmental Protection Agency (EPA) - National Priorities List (NPL), including delisted NPL	1.0 Mile	No	0	0
EPA – Superfund Enterprise Management System (SEMS), including archived sites (formerly CERCLIS)	0.5 Mile	No	0	0
EPA – Resource Conservation and Recovery Act (RCRA), Corrective Action Facilities (CORRACTS)	1.0 Mile	No	0	0
EPA – RCRA, Transportation, Storage, and Disposal facilities (TSD)	0.5 Mile	No	0	0
EPA - RCRA Generators	Site and Adjacent	No	0	0
EPA – Emergency Response Notification System (ERNS)	Site	No	N/A	0
Federal institutional control/engineering control registries	0.5 Mile	No	0	0
California Environmental Protection Agency (CEPA) – State Response Sites (Response, formerly Annual Work Plan and Bond Expenditure Plan)	1.0 Mile	No	0	0

ENVIRONMENTAL DATABASE	MINIMUM SEARCH DISTANCE	SITE	ADJACENT	TOTAL LISTED
CEPA – EnviroStor Database (formerly CALSITES)	0.5 Mile	No	0	1
CEPA – CHMIRS - California Hazardous Materials Information Reporting System	Site	No	No	0
CEPA - Solid Waste Fill/Landfill (SWF/LF), Solid Waste Assessment Test (SWAT)/Waste Management Unit Database System (WMUDS) and Recycling Facilities (SWRCY)	0.5 Mile	No	0	0
CEPA – Leaking Underground Storage Tanks (LUST)	0.5 Mile	No	0	1
CEPA – Underground Storage Tanks (UST), including historic USTs	Site and Adjacent	**Yes**	0	1
CEPA – Spills, Leaks, Investigations & Cleanup Cost Recovery Listing (SLIC)	0.5 Mile	No	0	0
State institutional control/engineering control registries	Site	No	N/A	0
Local and/or Tribal databases	Up To 1.0 Mile	No	0	0
Drycleaners	0.25 Mile	No	0	0
Other databases	Up to 1.0 Mile	**Yes**	0	0
Unmappable facilities	Up to 1.0 Mile	No	0	2

N/A – Not Applicable

6.2 Discussion of Regulatory Records

6.2.1 National Priority List

The National Priority List (NPL) is the EPA's list of confirmed or proposed Superfund sites. Our review of this data includes sites which have been delisted from the NPL. The NPL is searched for a 1.0-mile distance.

The Site does not appear on the NPL. There are no facilities on the NPL within 1.0-mile of the Site.

6.2.2 SUPERFUND ENTERPRISE MANAGEMENT SYSTEM

The Superfund Enterprise Management System (SEMS, formerly CERCLIS) is a compilation of sites that the EPA has investigated or is currently investigating for a release or threatened release of hazardous substances. Our review of SEMS sites includes archive (no further remedial action planned) facilities. The SEMS list is searched for a 0.5-mile distance.

The Site does not appear on the SEMS list. The Site does appear on the SEMS-ARCHIVE list.

There are no facilities on the SEMS list within 0.5-mile of the Site. There are no facilities on the SEMS-ARCHIVE list within 0.5-mile of the Site.

6.2.3 RESOURCE CONSERVATION AND RECOVERY ACT

The Resource Conservation and Recovery Act compile selective information on facilities which generate, transport, store, treat and or dispose of hazardous waste. RCRA facilities can be listed on one of three databases:

- *Corrective Action Facilities (CORRACTS)* are facilities undergoing corrective action. A corrective action order is issued pursuant to RCRA Section 3008(h) when there has been a release of hazardous waste or constituents into the environment from a RCRA facility. The CORRACTS list is searched for a 1.0-mile distance.

  The Site does not appear on the CORRACTS list. There are no facilities on the CORRACTS list within 1.0-mile of the Site.

- *Transportation, Storage, and Disposal Facilities (TSD)* includes facilities that transport, store or dispose of hazardous waste and are not listed on the RCRA Generators list. The TSD is searched for a 0.5-mile distance.

  The Site does not appear on the RCRA TSD list. There are no facilities on the RCRA TSD list within 0.5-mile of the Site.

- *Generators List* identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Generators database is a compilation by the EPA of reporting facilities that generate hazardous waste. The RCRA generators list is searched for the Site and adjacent properties.

The Site does not appear on the RCRA Generators list. There are no RCRA Generator facilities listed within 0.25 mile of the Site.

6.2.4 Emergency Response Notification System

The Emergency Response Notification System (ERNS) is a national database used to collect information on reported releases of oil or hazardous substances. The ERNS list is searched for the Site. The Site does not appear on the ERNS list.

6.2.5 Federal Institutional Control/Engineering Control Registries

The EPA maintains three (3) databases which list sites that have institutional and/or engineering controls in place as part of their operations. These databases are searched for a 0.5-mile distance.

The Site does not appear on these databases. There are no facilities on these databases within 0.5-mile of the Site.

6.2.6 State Response Sites

The State Response Sites (RESPONSE) records are the state equivalent to the federal National Priorities List (NPL) database. The RESPONSE is searched for a 1.0-mile distance.

The Site does not appear on the on the RESPONSE. There are no RESPONSE facilities listed within a 1.0-mile distance of the Site.

6.2.7 EnviroStor Database

The EnviroStor Database (EnviroStor, formerly CALSITES) records are the state equivalent to the federal SEMS database. EnviroStor is searched for a 0.5-mile distance.

The Site does not appear on the EnviroStor database.

There is one (1) EnviroStor facility within 0.5 mile of the Site. The facility is listed as Elementary School No. 17, located at Wineville Road/Bellegrave Avenue. The facility is listed as being located less than 0.125 (0.108) mile north-northeast of the Site. The status is listed as "no action required". The reason for this listing was a school investigation, which is required under California law. There were no contaminants found during the investigation. Based on

the status and findings of the investigation, this facility is not considered an environmental concern to the Site.

6.2.8 California Hazardous Material Incident Report System

The California Hazardous Material Incident Report Systems (CHMIRS) is a state database used to collect information on reported hazardous materials incidents (accidental leaks and spills). The CHMIRS list is searched for a 0.25-mile distance.

The Site does not appear on the CHMIRS list. There are no CHMIRS facilities located within 0.25 mile of the Site.

6.2.9 Solid Waste Facilities List

The Solid Waste Fill/Landfill (SWF/LF), Waste Management Unit Database System (WMUDS)/Solid Waste Assessment Test (SWAT), and Solid Waste Recycling Facilities (SWRCY) databases includes information pertaining to closed and open solid waste facilities operating in the state of California. The SWF/LF, WMUDS/SWAT and SWRCY databases are searched for a 0.5-mile distance.

The Site does not appear on the SWF/LF, WMUDS/SWAT or SWRCY lists.

There are no facilities on the SWF/LF, WMUDS/SWAT or SWRCY lists.

6.2.10 Leaking Underground Storage Tanks List

The California Leaking Underground Storage Tanks (LUST) list is a compilation of petroleum storage tank sites that have reported a release. The LUST list is searched for a 0.5-mile distance.

The Site does not appear on the LUST list.

There is one (1) facility listed as being on the LUST list within 0.5-mile of the Site. The facility is listed as Texaco Swan Lake, located at 2800 Hamner Avenue. The facility is listed as being located 0.25 to 0.5 (0.307) mile west-southwest of the Site. The facility status is listed as "completed-case closed". Due to listing status and location, this facility is not considered an environmental concern to the Site.

6.2.11 UNDERGROUND STORAGE TANKS LIST

The California Underground Storage Tank (UST) list is a compilation of petroleum storage tank sites that are registered with the state of California. The UST list is searched for the Site and adjacent properties.

The Site appears on the UST list. The facility is listed as Verona Ranch, located at 12080 Bellegrave Avenue. No additional information for this listing is provided in the database report.

GEOTEK contacted the County of Riverside Department of Environmental Health (DEH) regarding any underground or above ground storage tanks, hazardous material permits or business plans, emergency responses, spills, inspections, or other information of an environmental or hazardous nature. Upon review of the files located at the DEH, information was obtained that two (2) USTs were removed from the site on October 29, 2004. Additionally, based on review of an *Underground Storage Tank Closure Report*, prepared by The Reynolds Group and dated November 3, 2004 (The Reynolds Group, 2004), The Reynolds Group concluded the report by stating:

- One 10,000 gallon fiberglass coated steel diesel UST and one 8,000 gallon fiberglass coated steel gasoline UST, two dispensers and associated piping were removed from the Site.
- A total of eight soil samples were collected from the native soils beneath the USTs and dispensers and sent for laboratory analysis.
- All eight samples were "non-detect" for all analytes tested.
- Based on the field work performed and subsequent laboratory analytical results, The Reynolds Group recommend regulatory closure at this Site with respect to the subject USTs and dispensers and that a "closure" or "no further action" letter be issued to the permittee.

A "no further action" letter was provided for the Site on May 8, 2006 by the County of Riverside DEH (DEH, 2006). Copies of these documents are provided in Appendix B.

There are no facilities listed on the UST list within a 0.5-mile distance of the Site.

The Site does not appear on the HIST UST list. There are no facilities listed on the HIST UST list within a 0.5-mile distance of the Site.

6.2.12 Spills, Leaks, Investigation and Cleanup Cost Recovery Listing (SLIC)

The SLIC database is compiled by the CEPA California Regional Water Quality Control Board, San Ana Region. It is designed to protect and restore water quality from spills, leaks, and similar discharges. The SLIC is searched for a 0.5-mile distance.

The Site does not appear on the SLIC. There are no SLIC facilities listed within a 0.5-mile distance of the Site.

6.2.13 State Institutional Control/Engineering Control Registries

The State of California maintains institutional and engineering control databases or registries. This lists sites with engineering or institutional controls in place. Institutional controls include administrative measures intended to prevent exposure to contaminants remaining on site. Engineering controls include various forms of caps, building foundations, liners, and treatment methods. The State Institutional Control/Engineering Control Registries is searched for the Site.

The subject Site does not appear on the State Institutional Control/Engineering Control Registries.

6.2.14 Tribal Databases

Tribal governments are under the jurisdiction of the EPA for environmental concerns. Currently, the EPA Region 9 publishes LUST and UST information for tribes in Arizona, California, Hawaii, Nevada, and the Pacific Territories. The LUST database is searched for 0.5 mile, and the UST database is searched for 0.25 mile.

The Site does not appear on the Tribal LUST or UST databases. No facilities were identified on the Tribal LUST or UST databases within 0.5 mile of the Site

.

6.2.15 Other Databases

EDR compiles information from multiple federal, state, local, and proprietary databases. Most are secondary or tertiary or redundant. Facilities compiled on these other databases are evaluated based on the severity of the listing, distance, and location.

The Site appears on the environmental database report obtained for this assessment. The following table provides the site name, site address and each listing for the Site.

Facility Name	Address	Listing
Samuel P Lewis DBA Chino Welding and Assembly	12080 Bellegrave Avenue	FINDS
Vernola Ranch	12080 Bellegrave Avenue	FINDS
Samuel P Lewis DBA Chino Welding & Assembly	12080 Bellegrave Avenue	SWEEPS UST, EMI, CERS
Bernola Ranch	12080 Bellegrave Avenue	HWTS
Vernola Ranch	12080 Bellegrave Avenue	HAZNET, HWTS
Vernola Ranch	12080 Bellegrave Avenue	UST

- FINDS (Facility Index System/Facility Registry System) contains both facility information and "pointers" to other sources that contain more detail. The environmental interest type for the Samuel P Lewis DBA Chino Welding and Assembly facility is listed as "air emissions classification unknown". The description code is listed as "commercial and industrial machinery and equipment repair and maintenance".

  The supplemental interest for the Vernola Ranch facility is listed as "underground storage tank program". This database listing is discussed in Section 6.2.11 of this report.

- ECHO (Enforcement and Compliance History Information) provides integrated compliance and enforcement information. The compliance status is listed as "no violation identified".

- SWEEPS UST is an underground storage tank listing that is no longer updated or maintained. This database listing is discussed in Section 6.2.11 of this report.

- EMI (Emissions Inventory Data) lists toxics and criteria pollutant emissions data collected by local air pollution agencies. This database listing is associated with the welding facility that is no longer located at the Site.

- CERS (CalEPA Regulated Site Portal Data) lists environmentally regulated sites and facilities with activities that includes hazardous materials and waste, state and federal cleanups, impacted ground and surface waters and toxic materials. This database listing is associated with the welding facility that is no longer located at the Site.

- HWTS (Hazardous Waste Transporter Database) lists hazardous waste transporters. No other pertinent information is provided for the listing of Bernola Ranch or Vernola Ranch. The waste code for Vernola Ranch is listed as "aqueous solution with total organic residues less than 10 percent" and lists disposal method as "recycler".

- HAZNET is a facility and manifest database. The data is extracted from the copies of hazardous waste manifests received each year by the Department of Toxic Substance Control (DTSC). The waste code is listed as "aqueous solution with total organic residues less than 10 percent" and lists disposal method as "recycler".

- UST (Underground Storage Tank) is a list of sites with USTs. This database listing is discussed in Section 6.2.11 of this report

These listings are related to multiple former and current conditions documented at the Site regarding the hazardous wastes. As there are no records of violations, spills, leaks, investigations, or clean-ups at the Site, these listings are not considered an environmental concern at the Site.

Three (3) facilities are listed with EnviroStor that are located greater than 0.5-mile from the Site. All three (3) facilities are schools and have a status of "no further action" or "no action required".

There is one (1) facility listed with SCH in the database report.

There is one (1) facility listed with CERS HAZ WASTE in the database report.

There are five (5) facilities listed with PFAS in the database report.

There are two (2) facilities listed with RCRA NonGen/NLR in the database report.

There is one (1) facility listed with Cortese in the database report. The facility has a "completed-case closed" status.

There is one (1) facility listed with HIST CORTESE in the database report.

There is one (1) facility listed with Notify 65 in the database report.

There is one (1) facility listed with CIWQS in the database report.

These facilities are not considered to represent an environmental concern to the Site due to their distances, locations hydro-geologically down- or cross-gradient and/or their current regulatory status.

6.2.16 Dry Cleaners

The DRYCLEANERS list is compiled and provided by EDR. The DRYCLEANER database is searched for a 0.25-mile distance.

The Site does not appear on the DRYCLEANER list. There are no DRYCLEANER facilities listed within 0.25-mile of the Site.

6.2.17 Unmappable Facilities

GeoTek reviewed the listing of "orphan" or unmappable facilities in the database report.

There are two (2) unmapped facilities in the report. The first facility is listed as So Cal Gas/Ontario MGP located at "corner of Campus, Martland, Monterey and Mission in Ontario, California. Based on this firm's research, this facility is located approximately 7.3 feet to the northwest of the Site. The facility is listed with EDR MGP (Manufactured Gas Plants).

The second facility is listed as Milliken Sanitary Landfill, located at the intersection of Milliken Avenue and Mission Boulevard. Based on this firm's research, this facility is located approximately 3.8 miles northwest of the Site. The facility is listed with EnviroStor.

Due to the facility listings and locations, these facilities are not considered an environmental concern to the Site.

6.3 Local Regulatory Agency Records

GeoTek contacted the County of Riverside Fire and Sherriff Departments regarding underground or above ground storage tanks, hazardous material permits or business plans, emergency responses, spills, inspections, or other information of an environmental or hazardous nature.

Neither of these agencies had any information for the Site.

GEOTEK contacted the County of Riverside Department of Environmental Health (DEH) regarding hazardous materials. Upon review of the files located at the DEH, information was obtained that two (2) USTs were removed from the site on October 29, 2004. Additionally, based on review of an *Underground Storage Tank Closure Report*, prepared by The Reynolds Group and dated November 3, 2004 (The Reynolds Group, 2004), The Reynolds Group concluded the report by stating:

- One 10,000 gallon fiberglass coated steel diesel UST and one 8,000 gallon fiberglass coated steel gasoline UST, two dispensers and associated piping were removed from the Site.
- A total of eight soil samples were collected from the native soils beneath the USTs and dispensers and sent for laboratory analysis.
- All eight samples were "non-detect" for all analytes tested.
- Based on the field work performed and subsequent laboratory analytical results, The Reynolds Group recommend regulatory closure at this Site with respect to the subject USTs and dispensers and that a "closure" or "no further action" letter be issued to the permittee.

A "no further action" letter was provided for the Site on May 8, 2006 by the County of Riverside DEH (DEH, 2006). Copies of these documents are provided in Appendix B.

7.0 VAPOR ENCROACHMENT SCREEN

The purpose of a Vapor Encroachment Screen (VES) is to identify, to the extent feasible, if a Vapor Encroachment Condition (VEC) exists at the Site.

A Vapor Encroachment Screen Report was generated for the Site and Site area utilizing EDR's Vapor Encroachment Worksheet (see Appendix E). It was determined that there are no historical dry cleaners or auto stations within 600 feet and/or up gradient from the Site.

It is our opinion that a VEC in not likely to exist at the subject Site. The Vapor Encroachment Screen report is included in Appendix E.

8.0 SITE AND SURROUNDING AREA HISTORY

In order to construct the history of the Site and the surrounding area, GEOTEK reviewed reasonably ascertainable public documents, including aerial photographs, topographic maps, building records, city directories, fire insurance maps, and county assessor history records.

8.1 HISTORICAL SITE USAGE

8.1.1 AERIAL PHOTOGRAPH REVIEW

GEOTEK reviewed aerial photographs dated 1931, 1938, 1948, 1953, 1967, 1975, 1985, 1989, 1990, 1994, 2002, 2006, 2009, 2012, 2016 and 2021 (see Appendix B).

The Site appears to be vacant land in the 1931, 1938 and 1948 aerial photographs.

The northerly two-thirds of the Site appears to be utilized for agriculture in the 1953 aerial photograph.

The entire Site appears to be utilized for agriculture in the 1967 and 1975 aerial photographs.

A structure can be observed in the northeast portion of the Site in the 1985 aerial photograph. The northwest corner of the Site appears to be disturbed (no agriculture).

Almost all of the Site structures can be observed in the northern portion of the Site in the 1989 aerial photograph. The remainder of the Site is utilized for agriculture.

All the Site structures can be observed in the northern portion of the Site in the 1990 aerial photograph.

The Site appears similar to current conditions in the 1994, 2002, 2006, 2009, 2012, 2016 and 2021 aerial photographs.

A 2021 aerial photograph is utilized for Figure 2 (Appendix A).

8.1.2 TOPOGRAPHIC MAP REVIEW

GEOTEK reviewed the Corona Quadrangle (30-minute series), dated 1902; the Corona and Vicinity Quadrangle (7.5-minute series), dated 1942; the Cucamonga and Corona Quadrangles

(15-minute series), dated 1944/1947; the Guasti and Corona North Quadrangles (7.5-minute series), dated 1953/1954; the Guasti and Corona North Quadrangles (7.5-minute series), dated 1966/1967; the Guasti and Corona North Quadrangles (7.5-minute series), dated 1973; Guasti and Corona North Quadrangles (7.5-minute series), dated 1981; and the Corona North and Guasti Quadrangles (7.5-minute series), dated 2012 (see Appendix B).

The Site appears to be vacant land on the 1902, 1942, 1944/1947 and 1953/1954 topographic map sheets.

Two wells are depicted in the northern portion of the Site on the 1966/1967, 1973 and 1981 topographic map sheets.

The 2012 topographic map sheet shows little detail other than streets in the vicinity; however, the two wells can be observed on this map sheet as well.

A 2012 topographic map sheet is utilized for Figure 1 (Appendix A).

8.1.3 Building Department Records

GeoTek obtained a Building Permit Report from EDR. The report is included in Appendix B.

No permits were found from the Riverside County records searched from 1963 to 2021 in the Building Permit Report provided.

A Parcel Export was obtained from the County of Riverside website (Map My County v10 (countyofriverside.us). The report is included in Appendix B. Several permits were listed for the Site. These permits are not considered an environmental concern to the Site.

8.1.4 City Directory Review

GeoTek obtained The EDR – City Directory Image Report, as obtained from and provided by EDR, and included in Appendix B. Results of the review are provided below.

YEAR	SOURCE	ADDRESS	LISTING(S)
1995	EDR Digital Archive	12080 Bellegrave Avenue	Rogeli Castro Vernola Ranch

YEAR	SOURCE	ADDRESS	LISTING(S)
2000	EDR Digital Archive	12080 Bellegrave Avenue	Roberto S Acuna Regelio Castro Forever Living Natures Best Direct Incorporated
2005	EDR Digital Archive	12080 Bellegrave Avenue	Rogelio Castro
2010	EDR Digital Archive	12080 Bellegrave Avenue	Jacinto Bravo Vernola Ranch
2014	EDR Digital Archive	12080 Bellegrave Avenue	Jacinto Bravo McCune & Associates, Inc.
2017	EDR Digital Archive	12080 Bellegrave Avenue	McCune & Associates, Inc.

These listings are not considered an environmental concern to the Site.

8.1.5 Sanborn Map Review

Sanborn Fire Insurance Maps for the parcel were requested from EDR-Sanborn, which owns and maintains the largest and most complete collection of the maps. Source sheets were not available for the Site. The Sanborn Map Report is included in Appendix B.

8.1.6 Chain of Title

GeoTek has not received, nor was authorized to obtain Chain-of-Title documents for the Site.

8.2 Historical Immediately Surrounding Property Usage

8.2.1 Aerial Photograph Review

GeoTek reviewed aerial photographs dated 1931, 1938, 1948, 1953, 1967, 1975, 1985, 1989, 1990, 1994, 2002, 2006, 2009, 2012, 2016 and 2021 (see Appendix B).

The surrounding properties appear to be vacant land, utilized for agriculture or scattered residences in the 1931, 1938, 1948 and 1953 aerial photographs.

A dairy can be observed to the north of Bellegrave Avenue along with agriculture in the 1967 and 1985 aerial photographs. The properties to the east and south are utilized for agriculture. A structure can be observed to the west of the northwest corner of the Site. Swan Lake Mobile Home Park can be observed to the far west of the Site along with agriculture.

Interstate 15 can be observed to the west of the Site in the 1989 aerial photograph. A dairy can be observed to the north of Bellegrave Avenue and agriculture can be observed to the east and south.

The surrounding properties appear similar to the 1989 aerial photograph in the 1990, 1994 and 2002 aerial photographs.

Homecoming at Eastvale can be observed to the west of Interstate 15 in the 2006 aerial photograph. Vernola Park is being graded to the east of the Site.

The dairy to the north of Bellegrave appears to be vacated in the 2009 aerial photograph. Vernola Park is under construction.

Little to no changes can be observed in the 2012 aerial photograph.

Harvest Villages at Vernola Ranch is under construction to the east of the Site in the 2016 aerial photograph.

The surrounding properties appear similar to current conditions in the 2021 aerial photograph.

8.2.2 Topographic Map Review

GeoTek reviewed the Corona Quadrangle (30-minute series), dated 1902; the Corona and Vicinity Quadrangle (7.5-minute series), dated 1942; the Cucamonga and Corona Quadrangles (15-minute series), dated 1944/1947; the Guasti and Corona North Quadrangles (7.5-minute series), dated 1953/1954; the Guasti and Corona North Quadrangles (7.5-minute series), dated 1966/1967; the Guasti and Corona North Quadrangles (7.5-minute series), dated 1973; Guasti and Corona North Quadrangles (7.5-minute series), dated 1981; and the Corona North and Guasti Quadrangles (7.5-minute series), dated 2012 (see Appendix B).

The surrounding properties appear to be vacant land on the 1902 topographic map sheet.

Structures can be observed to the west and north of the Site on the 1942, 1944/1947 and 1953/1954 topographic map sheets. The remaining surrounding properties appear to be vacant land. Bellegrave Avenue can be observed to the north.

The Swan Lake Mobile Home Park can be observed to the far west on the 1966/1967, 1973 and 1981 topographic map sheets. Structures can be observed to the west and north. The properties to the east and south appear to be vacant land.

The 2012 maps show little detail other than streets in the vicinity.

The 2012 map is presented as Figure 1 in Appendix A.

8.2.3 CITY DIRECTORIES

GEOTEK has reviewed a City Directory Image report obtained from and provided by EDR for the Site and surrounding property addresses. The City Directory Image report provides information on several nearby property addresses. The listings do not appear to be an environmental concern to the Site.

8.2.4 SANBORN MAP REVIEW

Sanborn Maps for the Site were requested from EDR-Sanborn, which owns and maintains the largest and most complete collection of the maps. According to EDR, source sheets were not available for the property; therefore, it is not likely that source sheets would be available for the adjoining properties. The Sanborn Map Report is included in Appendix B.

8.3 HISTORICAL USE SUMMARY

Based on readily available historic information, the Site appears to have been vacant land from at least 1931 until at least 1948. The Site appears to have been utilized for agriculture from at least 1953 until present day. Structures in the northern portion of the Site can first be observed in an aerial photograph dated 1985. The surrounding properties appear to historically have been utilized for agriculture, scattered residences or vacant from at least 1931 until at least 1967. Swan Lake Mobile Home Park can be observed in an aerial photograph dated 1975. Interstate 15 can be observed in an aerial photograph dated 1989. Homecoming at Eastvale can be observed in an aerial photograph dated 2006. Vernola Park is under construction in an aerial photograph dated 2009. Harvest Villages at Vernola Ranch can be observed in an aerial photograph dated 2016.

Data gaps exist from 1902 to 1931, 1931 to 1938, 1954 to 1966 and 1994 to 2002 due to the limited records which are reasonably ascertainable in the local area. However, it is our opinion

that additional historic information, if it were to become available, is not likely to change the conclusions or recommendations of this assessment.

9.0 SIGNIFICANT DATA GAPS

No significant data gaps were discovered while performing this Phase I and Limited Phase II Environmental Site Assessment. Therefore, it is our opinion that sufficient information was obtained to identify current Site conditions and past Site usage.

Minor data gaps include:

- Gaps in the historic records from 1902 to 1931, 1931 to 1938, 1954 to 1966 and 1994 to 2002;

- GEOTEK has not received nor reviewed Chain-of-Title documents for the Site.

It is our opinion that additional information, if it were to become available, is not likely to change the conclusions or recommendations of this assessment.

10.0 SUMMARY OF LIMITED SOIL ANALYSIS

As the Site is occupied by agriculture (i.e., corn field), GEOTEK obtained soil samples from the Site for chemical analysis. Twenty soil samples were obtained from selected areas of the Site from a depth of up to approximately six (6) inches below the existing ground surface and submitted to a state certified laboratory for analysis of organo-chlorinated pesticides (OCP) in accordance with US EPA Test Method 8081A and arsenic in accordance with US EPA Test Method 6010B.

Analysis of the soil samples detected measurable quantities of the OCP constituent 4,4'-DDE in four (4) of the samples collected (Samples Nos. 2, 3, 13 and 16). The applicable results of the laboratory analysis are summarized in the following table:

OCP SUMMARY ANALYTICAL RESULTS

Sample	4,4'-DDE (ug/kg)
#1	ND (<5 ug/kg)
#2	7.1
#3	6.5
#4	ND (<5 ug/kg)
#5	ND (<5 ug/kg)
#6	ND (<5 ug/kg)
#7	ND (<5 ug/kg)
#8	ND (<20 ug/kg)
#9	ND (<20 ug/kg)
#10	ND (<10 ug/kg)
#11	ND (<10 ug/kg)
#12	ND (<10 ug/kg)
#13	6.9
#14	ND (<5 ug/kg)
#15	ND (<5 ug/kg)
#16	6.2
#17	ND (<5 ug/kg)
#18	ND (<5 ug/kg)
#19	ND (<5 ug/kg)
#20	ND (<5 ug/kg)
Screening Level	**2,000***

ug/kg = micrograms per kilogram
* = EPA Regional Screening Levels (RSLs) for residential soil, May 2021

The OCP constituent is in a concentration below the screening level for residential soils, as determined by EPA Regional Screening Level (RSL) for residential soil, May 2021 (TR=1E-06,

HQ=1.0). Analysis of the remaining OCP constituents in the soil samples tested were below the method detection limits.

Analysis of the soil samples detected measurable quantities of arsenic in all of the soil samples tested and collected. The applicable results of the laboratory analysis are summarized in the following table:

ARSENIC SUMMARY ANALYTICAL RESULTS – PLANNING AREA 2

Sample	Arsenic (mg/kg)
#1	4.4
#2	4.0
#3	4.0
#4	3.1
#5	3.5
#6	2.8
#7	2.0
#8	2.9
#9	4.3
#10	3.7
#11	4.2
#12	3.6
#13	3.4
#14	2.8
#15	5.5
#16	4.4
#17	3.8
#18	3.6
#19	2.5
#20	4.4
Screening Level	**0.11***

ug/kg = micrograms per kilogram
ND = Not Detected
* = DTSC Screening Levels (RSLs) for residential soil (June 2020)

EPA and the Department of Toxic Substance Control (DTSC) have acknowledged that naturally occurring arsenic in southern California typically exceeds the maximum, with levels recorded up to 12 mg/kg in many areas (https://www.dtsc.ca.gov/upload/Background-Arsenic.pdf). Therefore, it is our opinion that the arsenic detected is not the result of environmental contamination but is naturally occurring.

A copy of the laboratory report and Chain-of-Custody documentation are included in Appendix F.

Based on our investigation, GEOTEK is of the opinion that additional investigation is not necessary at the Site.

11.0 CONCLUSIONS AND RECOMMENDATIONS

GEOTEK has performed a Phase I and Limited Phase II Environmental Site Assessment (ESA) for the subject Site in substantial conformance with the scope and limitations of ASTM E 1527-13 and GEOTEK Proposal No. P-0706821-CR, dated July 23, 2021. Any exceptions to, or deletions from, this practice are described in the appropriate sections of this report.

This Phase I and Limited Phase II Environmental Site Assessment has not revealed evidence of a recognized environmental condition or concern in connection with the subject Site. Stained soils associated with two (2) 55-gallon drums located in the northeast portion of the Site should be cleaned up to visual limits as a housekeeping measure. No further investigation is required at this time.

12.0 CERTIFICATIONS

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject Site. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR 312.

The qualifications of the Project Team are included in Appendix G.

We appreciate this opportunity to be of service. If you have any questions, or if we can be of further service, please contact us at (951) 710-1160.

Sincerely,
GEOTEK, INC.

REGISTERED GEOLOGIST
EDWARD H. LaMONT
No. 1892
Exp.
Certified Engineering Geologist
STATE OF CALIFORNIA

Edward H. LaMont
Principal Geologist, CEG 1892
Exp. 07/31/2022

J. Michael Batten, CEM, REPA
Environmental Services Manager
Registered Environmental Property Assessor No. 113162
Expires 06/15/2022

Anna M. Scott
Project Geologist

G:\Projects\2901 to 2950\2903CR Vernola Trust Vernola Ranch North Jurupa Valley\Phase I ESA\2903CR Phase I and Limited Phase II Environmental Site Assessment Vernola Ranch North.DOC

13.0 REFERENCES

CALIFORNIA, STATE OF

- Morton, D.M. and Miller, F.K., 2006, "Geologic Map of the San Bernardino and Santa Ana 30' x 60' quadrangles, California," U.S. Geological Survey, Open-File Report OF-2006-1217, scale 1:100,000
- Water Resources, Department of Hydrologic Data

ENVIRONMENTAL DATA RESOURCES, INC.

- Aerial Photo Decade Package, Inquiry No. 6691091.11 dated October 5, 2021
- Building Permit Report, Inquiry No. 6691091.8, dated October 5, 2021
- Certified Sanborn Map Report, Inquiry No. 6691091.3, dated October 5, 2021
- City Directory Image Report, Inquiry No. 6691091.5, dated October 11, 2021
- Environmental Lien and AUL Search, Inquiry No. 6691091.7, October 6, 2021
- Historical Topo Map Report, Inquiry No. 6691091.4, dated October 5, 2021
- Property Tax Map Report, Inquiry No. 6691091.6, dated October 5, 2021
- Radius Map Report, Inquiry No. 6691091.2s, dated October 6, 2021
- Vapor Encroachment Screen Report, Inquiry No. 6691091.2s, dated October 18, 2021

RIVERSIDE, COUNTY OF


- Assessor's Office, Records Inquiry
- Department of Environmental Health, Records Inquiry
- Fire Department, Records Inquiry
- Sherriff Department, Records Inquiry

U.S. GOVERNMENT

- Drug Enforcement Agency
- Records inquiry, http://www.dea.gov/seizures

APPENDIX A

FIGURES



Vernola Trust
Vernola Ranch North Project
Jurupa Valley, Riverside County, California

Project No. 2903-CR

NORTH

Figure 1

Site Location and Topography Map

GEOTEK



Vernola Trust
Vernola Ranch North Project
Jurupa Valley, Riverside County, California

GeoTek Project No. 2903-CR

GEOTEK

Figure 2a

General Site Layout Map



Vernola Trust
Vernola Ranch North Project
Jurupa Valley, Riverside County, California

GeoTek Project No. 2903-CR

GEOTEK

Figure 2b

General Site Layout Map



Vernola Trust
Vernola Ranch North Project
Jurupa Valley, Riverside County, California

GeoTek Project No. 2903-CR

GEOTEK

Figure 3

Sample Location Map

APPENDIX B

SUPPORTING DOCUMENTS

Vernola Ranch North

12080 Bellegrave Avenue

Mira Loma, CA 91752

Inquiry Number: 6691091.11

October 05, 2021

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

10/05/21

Site Name:

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752
EDR Inquiry # 6691091.11

Client Name:

Geotek
1548 North Maple Street
Corona, CA 92880
Contact: Anna M. Scott

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2016	1"=750'	Flight Year: 2016	USDA/NAIP
2012	1"=750'	Flight Year: 2012	USDA/NAIP
2009	1"=750'	Flight Year: 2009	USDA/NAIP
2006	1"=750'	Flight Year: 2006	USDA/NAIP
2002	1"=750'	Acquisition Date: January 01, 2002	USGS/DOQQ
1994	1"=750'	Acquisition Date: June 01, 1994	USGS/DOQQ
1990	1"=750'	Flight Date: August 29, 1990	USDA
1989	1"=750'	Flight Date: August 03, 1989	USDA
1985	1"=750'	Flight Date: July 28, 1985	USDA
1975	1"=750'	Flight Date: August 01, 1975	USGS
1967	1"=750'	Flight Date: May 15, 1967	USDA
1953	1"=750'	Flight Date: February 02, 1953	USDA
1948	1"=750'	Flight Date: July 10, 1948	USGS
1938	1"=750'	Flight Date: June 14, 1938	USDA
1931	1"=750'	Flight Date: September 18, 1931	FAIR

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 6691091.11
YEAR: 2016
= 750'
N
EDR



INQUIRY #: 6691091.11


YEAR: 2012

= 750'

N

EDR


INQUIRY #: 6691091.11
YEAR: 2009
= 750'
N
EDR


INQUIRY #: 6691091.11
YEAR: 2006
= 750'
N
EDR



INQUIRY #: 6691091.11

YEAR: 2002

= 750'

N

EDR



INQUIRY #: 6691091.11

YEAR: 1994

= 750'

N

EDR




INQUIRY #: 6691091.11

YEAR: 1990

= 750'

N

EDR



INQUIRY #: 6691091.11

YEAR: 1989

= 750'

N

EDR



INQUIRY #: 6691091.11

YEAR: 1985

= 750'

N

EDR



INQUIRY #: 6691091.11

YEAR: 1975

= 750'

N

EDR



INQUIRY #: 6691091.11

YEAR: 1967

= 750'

N

EDR



INQUIRY #: 6691091.11

YEAR: 1953

= 750'

N

EDR




INQUIRY #: 6691091.11

YEAR: 1948

= 750'

N

EDR



INQUIRY #: 6691091.11

YEAR: 1938

= 750'

N

EDR



INQUIRY #: 6691091.11

YEAR: 1931

= 750'

N

EDR

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752

Inquiry Number: 6691091.8
October 05, 2021

EDR Building Permit Report

Target Property and Adjoining Properties

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

About This Report

Executive Summary

Findings

Glossary

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

ASTM and EPA Requirements

ASTM E 1527-13 lists building department records as a "standard historical source," as detailed in § 8.3.4.7: "Building Department Records - The term building department records means those records of the local government in which the property is located indicating permission of the local government to construct, alter, or demolish improvements on the property." ASTM also states that "Uses in the area surrounding the property shall be identified in the report, but this task is required only to the extent that this information is revealed in the course of researching the property itself."

EPA's Standards and Practices for All Appropriate Inquires (AAI) states: "§312.24: Reviews of historical sources of information. (a) Historical documents and records must be reviewed for the purposes of achieving the objectives and performance factors of §312.20(e) and (f). Historical documents and records may include, but are not limited to, aerial photographs, fire insurance maps, building department records, chain of title documents, and land use records."

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.

Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILD FAX PROPERTY HISTORY

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

A search of building department records was conducted by Environmental Data Resources, Inc (EDR) on behalf of Geotek on Oct 05, 2021.

TARGET PROPERTY

12080 Bellegrave Avenue
Mira Loma, CA 91752

SEARCH METHODS

EDR searches available lists for both the Target Property and Surrounding Properties.

RESEARCH SUMMARY

Building permits identified: **NO PERMITS IDENTIFIED**

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Name: JurisdictionName
Years: Years
Source: Source
Phone: Phone

BUILDING DEPARTMENT RECORDS SEARCHED

Name: Riverside County
Years: 1963-2021
Source: Riverside County, Building and Safety, LA QUINTA, CA
Phone: (951) 955-6742

TARGET PROPERTY FINDINGS

TARGET PROPERTY DETAIL

12080 Bellegrave Avenue
Mira Loma, CA 91752

No Permits Found

ADJOINING PROPERTY FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

No Permits Found

GLOSSARY

General Building Department concepts

- **ICC:** The International Code Council. The governing body for the building/development codes used by all jurisdictions who've adopted the ICC guidelines. MOST of the US has done this. Canada, Mexico, and other countries use ICC codes books and guides as well. There are a few states who have added guidelines to the ICC codes to better fit their needs. For example, California has added seismic retrofit requirements for most commercial structures.
- **Building Department (Permitting Authority, Building Codes, Inspections Department, Building and Inspections):** This is the department in a jurisdiction where an owner or contractor goes to obtain permits and inspections for building, tearing down, remodeling, adding to, re-roofing, moving or otherwise making changes to any structure, Residential or Commercial.
- **Jurisdiction:** This is the geographic area representing the properties over which a Permitting Authority has responsibility.
- **GC:** General Contractor. Usually the primary contractor hired for any Residential or Commercial construction work.
- **Sub:** Subordinate contracting companies or subcontractors. Usually a "trades" contractor working for the GC. These contractors generally have an area of expertise in which they are licensed like Plumbing, Electrical, Heating and Air systems, Gas Systems, Pools etc. (called "trades").
- **Journeymen:** Sub contractors who have their own personal licenses in one or more trades and work for different contracting companies, wherever they are needed or there is work.
- **HVAC (Mechanical, Heating & Air companies):** HVAC = Heating, Ventilation, and Air Conditioning.
- **ELEC (Electrical, TempPole, TPole, TPower, Temporary Power, Panel, AMP Change, Power Release):** Electrical permits can be pulled for many reasons. The most common reason is to increase the AMPs of power in an electrical power panel. This requires a permit in almost every jurisdiction. Other commons reason for Electrical permits is to insert a temporary power pole at a new construction site. Construction requires electricity, and in a new development, power has yet to be run to the lot. The temporary power pole is usually the very first permit pulled for new development. The power is released to the home owner when construction is complete and this sometimes takes the form of a Power Release permit or inspection.
- **"Pull" a permit:** To obtain and pay for a building permit.
- **CBO:** Chief Building Official
- **Planning Department:** The department in the development process where the building /structural plans are reviewed for their completeness and compliance with building codes
- **Zoning Department:** The department in the development process where the site plans are reviewed for their compliance with the regulations associated with the zoning district in which they are situated.
- **Zoning District:** A pre-determined geographic boundary within a jurisdiction where certain types of structures are permitted / prohibited. Examples are Residential structure, Commercial/Retail structures, Industrial/Manufacturing structures etc. Each zoning district has regulations associated with it like the sizes of the lots, the density of the structures on the lots, the number of parking spaces required for certain types of structures on the lots etc.
- **PIN (TMS, GIS ID, Parcel#):** Property Identification Number and Tax Map System number.
- **State Card (Business license):** A license card issued to a contractor to conduct business.
- **Building Inspector (Inspector):** The inspector is a building department employee that inspects building construction for compliance to codes.
- **C.O.:** Certificate of Occupancy. This is the end of the construction process and designates that the owners now have permission to occupy a structure after its building is complete. Sometimes also referred to as a Certificate of Compliance.

GLOSSARY

Permit Content Definitions

- Permit Number: The alphanumerical designation assigned to a permit for tracking within the building department system. Sometimes the permit number gives clues to its role, e.g. a "PL" prefix may designate a plumbing permit.
- Description: A field on the permit form that allows the building department to give a brief description of the work being done. More often than not, this is the most important field for EP's to find clues to the prior use (s) of the property.
- Permit Type: Generally a brief designation of the type of job being done. For example BLDG-RES, BLDG-COM, ELEC, MECH etc.

Sample Building Permit Data

Date: Nov 09, 2000
Permit Type: Bldg -
New Permit Number: 101000000405
Status: Valuation: $1,000,000.00
Contractor Company: OWNER-BUILDER
Contractor Name:

Description: New one store retail (SAV-ON) with drive-thru pharmacy. Certificate of Occupancy.

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752

Inquiry Number: 6691091.3
October 05, 2021

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

10/05/21

Site Name:

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752
EDR Inquiry # 6691091.3

Client Name:

Geotek
1548 North Maple Street
Corona, CA 92880
Contact: Anna M. Scott

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Geotek were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 9564-4A72-A242

PO # NA

Project 2903-CR

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: 9564-4A72-A242

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Geotek (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752

Inquiry Number: 6691091.5
October 11, 2021

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by infoUSA®

Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2017	☑	☑	EDR Digital Archive
2014	☑	☑	EDR Digital Archive
2010	☑	☑	EDR Digital Archive
2005	☑	☐	EDR Digital Archive
2000	☑	☐	EDR Digital Archive
1995	☑	☐	EDR Digital Archive
1992	☑	☐	EDR Digital Archive
1986	☐	☐	Haines Criss-Cross Directory
1980	☐	☐	Haines Criss-Cross Directory
1976	☐	☐	Haines Criss-Cross Directory
1971	☐	☐	Haines Criss-Cross Directory

FINDINGS

TARGET PROPERTY STREET

12080 Bellegrave Avenue
Mira Loma, CA 91752

Year	*CD Image*	*Source*	
BELLEGRAVE AV			
2000	pg A11	EDR Digital Archive	
BELLEGRAVE AVE			
2017	pg A1	EDR Digital Archive	
2014	pg A3	EDR Digital Archive	
2010	pg A6	EDR Digital Archive	
2005	pg A9	EDR Digital Archive	
2000	pg A12	EDR Digital Archive	
1995	pg A14	EDR Digital Archive	
1992	pg A16	EDR Digital Archive	
1986	-	Haines Criss-Cross Directory	Street not listed in Source
1980	-	Haines Criss-Cross Directory	Street not listed in Source
1976	-	Haines Criss-Cross Directory	Street not listed in Source
1971	-	Haines Criss-Cross Directory	Street not listed in Source

FINDINGS

CROSS STREETS

Year	*CD Image*	*Source*	
PATS RANCH RD			
2017	pg. A2	EDR Digital Archive	
2014	pg. A5	EDR Digital Archive	
2010	pg. A8	EDR Digital Archive	
2005	-	EDR Digital Archive	Target and Adjoining not listed in Source
2000	-	EDR Digital Archive	Target and Adjoining not listed in Source
1995	-	EDR Digital Archive	Target and Adjoining not listed in Source
1992	-	EDR Digital Archive	Target and Adjoining not listed in Source
1986	-	Haines Criss-Cross Directory	Street not listed in Source
1980	-	Haines Criss-Cross Directory	Street not listed in Source
1976	-	Haines Criss-Cross Directory	Street not listed in Source
1971	-	Haines Criss-Cross Directory	Street not listed in Source

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 2017

10234	LARA, FRANCISCO
10238	MARQUEZ, DAVID V
10240	CENTENO, STEVEN A
10242	CHRISLIP, ROGER W
10244	BELLI, SCOTT R
10246	SCOPEN, NANCEY
10247	ACMS
	ALJ CUSTOM WINDOW COVERINGS
	ALL AMERICAN PLUMBING
	DEPT CONSUMER AFFAIRS
	ESPARZA REAL ESTATE INC
	FASTENAL
	RAPTI FASHION
	RIGHT ANGLE SOLUTIONS INC
	ROADWAY ENGINEERING & CONTRACTING
	TSR INC
10248	BAIN, TOMMY M
10250	ELIFONZO, RAFAEL
10254	KREMER, BLAYD
10256	GARCIA, AMAIRANI
10274	PENA, GUADALUPE C
10294	CISNEROS, JUAN
10390	GOMEZ, GABRIEL
10396	GOLDEN RETREAT KENNELS
	NIELS, GREGORY
10520	SANTACRUZ, ANGELA
10530	WOLFE, GLORIA
10551	ESPERANZA PREGNANT MINOR PROGRAM
	JURUPA UNIFIED SCHOOL DISTRICT
	JURUPA VALLEY HIGH SCHOOL
10630	VENEGAS, JOSE A
10656	FEVALEAKI, SELETI D
10676	CASTILLEJO, RAUL
10696	BAZLEY, ROBERT J
10704	HERRERO, RIGOBERTO
10716	MACHADO, GERALD
10724	NUNEZ, JOSE M
10732	DUCHIMAZA, LUIS G
10830	FLORES, GABBY
10838	SHEETZ, JOHNEEN
10846	COLWELL, GARY L
10866	SANCHEZ, ROBERTO A
10886	TORRES, RICKY
11255	BONDAR, ORION
	BROWN, BRYAN K
11355	PHILLIPS, DONALD R
11611	TROOST HAY SALES
12080	MCCUNE & ASSOCIATES INC
12300	LEWIS OPERATING CO

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

PATS RANCH RD 2017

6205	CENTURY 21
	HEALTHSOURCE
	SALLY BEAUTY SUPPLY
	SERENITY MASSAGE SPA
	SPRINT
	THE FLAME BROILER
	WHOLESALE NUTRITION CENTER
6221	CARLS JR
6237	JOJOS PIZZA KITCHEN
	NAKHAPREECHA, PAVINEE L
	ONO HAWAIIAN BBQ
	PHILLYS BEST
	WABI SABI
6253	EMPIRE RESTAURANTS & CATERING LLC
	JAMBA JUICE
	PUDA INC
	SUBWAY
6269	DEL TACO
6285	DENNYS
6301	PETCO
6317	ROSS DRESS FOR LESS
6333	KIRKLANDS
6349	D M L K INC
	PAYLESS SHOESOURCE
6365	BED BATH & BEYOND
6381	MICHAELS
6413	BANK OF AMERICA ATM
	CHARTER COMMUNICATIONS
	LOWES
6429	FITNESS 19
6445	CHAMPION TAE KWON DO
	CHARLES ROGERS DDS
	DEEPIKA DHAMA DDS
	KUMON LEARNING CENTER
	MIRA LOMA DENTAL GROUP
	MIRA LOMA SMILES DENTISTRY
	SPORT CLIPS
6461	RED PERSIMMON NAILS & SPA
6477	BEVMO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 2014

10234	LARA, FRANCISCO
10236	OCCUPANT UNKNOWN,
10238	MARQUEZ, DAVID V
10240	MERCADO, TONI
10242	CHRISLIP, ROGER W
10244	LUNA, MICHAEL R
10246	ZWICKER, MICHAEL D
10247	ACMS
	ACP PUBLICATIONS & MARKE
	ALL AMERICAN PLUMBING
	DEPT CONSUMER AFFAIRS
	ESPARZA REAL ESTATE INC
	EVERGREEN ENVIROMENT INC
	FASTENAL
	RAPTI FASHION
	ROADWAY ENGINEERING & CONTRACTING
	TSR INC
10248	BAIN, TOMMY M
10250	ELIFONZO, RAFAEL
10252	SANMIGUEL, ELIZAEL S
10254	WOODHOUSE, ROBERT
10256	OCCUPANT UNKNOWN,
10274	PENA, ANGEL
10294	ARELLANO, GLORIA
10372	MAKAIMOKU, MICHAEL A
10390	GOMEZ, GABRIEL
10396	GOLDEN RETREAT KENNELS
	OCCUPANT UNKNOWN,
10516	OCCUPANT UNKNOWN,
10526	WOLFE, NOREEN P
10530	WOLFE, JENNIFER C
10551	ESPERANZA PREGNANT MINOR PROGRAM
	JURUPA VALLEY HIGH SCHOOL
10630	VENEGAS, JOSE A
10656	FEVALEAKI, SEINI
10676	RODRIGUEZ, ANDRES
10696	BAZLEY, ROBERT J
10704	MUNGUIA, JOSE
10716	MACHADO, ENERIO E
10724	RUBALCAVA, JOSE L
10830	MARTINEZ, DANIEL
10838	OCCUPANT UNKNOWN,
10846	COLWELL, GARY L
10866	SANCHEZ, ROBERTO A
10886	HOWSE, JOHN E
11255	BROWN, BRYAN K
	HUNTSINGER, JASON R
	LAURIE, BROWN
	SOSA, SERGIO
11355	OCCUPANT UNKNOWN,

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 2014 (Cont'd)

11571 HART, JACKIE D
11611 TROOST HAY SALES
11697 OCCUPANT UNKNOWN,
12036 COBLE, JENNIE
12041 VILLA, JOSE B
12080 BRAVO, JACINTO
MCCUNE & ASSOCIATES INC
12300 LEWIS OPERATING CO
12423 PLAA, MICHEL O

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

PATS RANCH RD 2014

6205	ELEMENTS THERAPEUTIC MASSAGE
	HEALTHSOURCE
	NORTH AMERICAN WIRELESS
	SALLY BEAUTY SUPPLY
	THE FLAME BROILER
6221	CARLS JR
6237	JOJOS PIZZA KITCHEN
	ONO HAWAIIAN BBQ
	PHILLYS BEST
	WABI SABI
6253	EMPIRE RESTURANTS & CATERING LLC D
	JAMBA JUICE
	JAMBA JUICE STORE NO 783
	SUBWAY SANDWICHES
6285	DENNYS
	FIVE GUYS BURGERS & FRIES
6301	PETCO
6317	ROSS DRESS FOR LESS
6333	KIRKLANDS
6349	D M L K INC
	PAYLESS SHOESOURCE
6365	BED BATH & BEYOND
6381	MICHAELS
6413	LOWES
	LOWES HOME IMPROVEMENT
6429	FITNESS 19
6445	DHAMA DEEPIKA DDS
	H&R BLOCK
	MIRA LOMA DENTAL GROUP
	MIRA LOMA SMILES
	ROGERS CHARLES DDS
	SPORT CLIPS
	SPORTS CLIPS
6461	RED PERSIMMON NAILS & SPA
6477	BEVMO 078

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 2010

10234 LARA, FRANCISCO
10236 BUSTILLOS, ANDY
10238 ORTEGA, RAMON E
10240 MERCADO, MARTIN
10242 CHRISLIP, ROGER W
10244 BELLI, SCOTT R
10246 MEATTEY, HAZEL M
10248 BAIN, TOMMY M
10250 BERNAL, MARIA S
10252 SANMIGUEL, ELIZAEL S
10254 BUSTAMANTE, KENNY A
10256 VILLA, MIGUEL A
10274 DIAZ, MARTIN
10294 GOMEZ, GUSTAVO
10372 JUN, JAE K
10390 OCCUPANT UNKNOWN,
10396 GOLDEN RETREAT KENNELS
OCCUPANT UNKNOWN,
10420 STANDARD READY MIX
10516 VICKERS, JEREMY
10520 RIVERA, R
10530 WOLFE, NOREEN P
10551 ESPERANZA PREGNANT MINOR PRGRM
JURUPA VALLEY HIGH SCHOOL
10630 VENEGAS, JOSE A
10656 FEVALEAKI, SELETI D
S F CONCRETE SPECIALIST
10676 ALMIRANTEARENA, MARTIN J
10696 BAZLEY, ROBERT J
10704 OCCUPANT UNKNOWN,
10716 MACHADO, ENERIO E
10724 NUNEZ, JOSE M
10830 ENGELSMA, JAMES
10838 OCCUPANT UNKNOWN,
10846 COLWELL, GARY L
10866 LEDEZMA, E
10886 HERNANDEZ, MAURICE A
10910 PAMPLONA, JOHN F
10918 TENORIO, ELISEO
11255 HUNTSINGER, JASON R
MINER, BRIAN
SOSA, SERGIO
11305 PALMER, LISA J
11355 DRYVA, RON
11611 OWENS, MINDA
TROOST HAY SALES
11697 OCCUPANT UNKNOWN,
12041 VILLA, JOSE B
12080 BRAVO, JACINTO
VERNOLA RANCH

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 2010 (Cont'd)

12300 LEWIS OPERATING CO
12423 PLAA, MICHEL O

Target Street	Cross Street	Source
-	✓	EDR Digital Archive

PATS RANCH RD 2010

6205	CITI FINANCIAL
6221	CARLS JR
6237	JOJOS PIZZA KITCHEN
	ONO HAWAIIAN BBQ
	SUNNY DONUT
6253	JAMBA JUICE
6269	DEL TACO
6301	PETCO
6317	ROSS DRESS FOR LESS
6333	KIRKLANDS
6349	PAYLESS SHOE SOURCE
	STATION Q
6365	BED BATH & BEYOND
6413	LOWES
6445	H&R BLOCK
	HOLLYWOOD TANS
	MIRA LOMA SMILES
	SPORT CLIPS
6461	RED PERSIMMON NAILS & SPA
6477	BEVMO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 2005

10234 LARA, FRANCISCO
10236 PEARCE, CECIL G
10238 MARQUEZ, DAVID V
10242 CHRISLIP, ROGER W
10244 BELLI, LOUIS R
10246 ZWICKER, ROSE
10250 BERNAL, MARIA
10252 SANMIGUEL, ELIZAEL S
10254 HALLING, VARDIE
10256 VILLA, MIGUEL A
10274 PENA, GUADALUPE C
10294 ACEVEDO, AMPARO
10390 OCCUPANT UNKNOWN,
10396 OCCUPANT UNKNOWN,
10420 STANDARD CONCRETE PRODUCTS
10496 OCCUPANT UNKNOWN,
10516 TOWNS, TIM
10520 GOMEZ, JESUS
10526 OCCUPANT UNKNOWN,
10530 WOLFE, GARRY T
10551 JURUPA VALLEY HIGH SCHOOL
10630 CASTANEDA, LETICIA
10656 FEVALEAKI, SELETI D
10676 ALMIRANTEARENA, JOSEPH R
10696 BAZLEY, ROBERT J
10704 VARGAS, TRINIDAD
10716 MACHADO, ENERIO E
10724 MARTINEZ, EDIS
10732 OCCUPANT UNKNOWN,
10830 OCCUPANT UNKNOWN,
10838 STRICKLAND, BLAINE C
10846 COLWELL, GARY L
10866 TORRES, MARIA R
10886 JUAREZ, EDUARDO T
10910 PAMPLONA, JOHN
10918 TENORIO, ELISEO
10968 OCCUPANT UNKNOWN,
11305 MEDEL, MARIA
11355 OCCUPANT UNKNOWN,
11537 OCCUPANT UNKNOWN,
11561 FULTON, DORA A
11571 CAMPBELL, TIMOTHY
TLC PEST CONTROL
11591 CL WILLIAMS GROUP LLC
WILLIAMS, JEREMIAH
11611 DELGADO, FELIPE
11697 RODRIGUEZ, LUIS
12000 VERNOLA RANCH
12041 VILLA, JOSE B
12071 MIRA LOMA THOROUGHBRED FARM

BELLEGRAVE AVE 2005 (Cont'd)

12080 CASTRO, ROGELIO
12423 PLAA, MICHEL
12451 GORZEMAN, SUSIE E

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AV 2000

9131	CATES, JEAN
9161	MENDOZA, TERESA
9340	TILGHMAN, RODGER W
9356	SMITH, C O
9475	ANAYA, S
9540	ESNARD, VICTOR

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 2000

9545	RAFAELS AUTO GLASS
9749	BELLEGRAVE TRUCK WASH
	DESTYNEE GENE ENTERPRISES LIMITED
	FITZGERALD TRUCKING
9875	LIVING LIGHT CHURCH OF GOD
10234	ZIMMERMAN, STEPHEN E
10236	PEARCE, CECIL G
	PEARCES BACKHOE SERVICE
10238	ORTEGA, RAMON
10240	SMYTH, WILLIAM
10242	CHRISLIP, ROGER
10244	BELLI, ANGELA
10248	OCCUPANT UNKNOWN,
10250	BERNAL, MARIA
10252	SANMIGUEL, ELIZAEL
10254	OCCUPANT UNKNOWN,
10256	VILLA, MIGUEL A
10274	STEPHENS, JAMES R
10294	MONTES, JOSE
10372	OCCUPANT UNKNOWN,
10390	GOMEZ, MARIA
10396	OCCUPANT UNKNOWN,
10420	CONCRETE MIXER REBUILDERS
	STANDARD READY MIX
10516	OCCUPANT UNKNOWN,
10520	NEAL, DAPHNE L
10526	LOGAN, JERRY B
10530	WOLFE, NOREEN
10551	ESPERANZA PREGNANT MINOR PROGRAM
	JURUPA UNIFIED SCHOOL DISTRICT PUBLIC SCHOOLS
	JURUPA VALLEY HIGH SCHOOL ASB
	LUNA ED
10622	KNIGHTS OF COLUMBUS
10630	CASTANEDA, LETICIA
10656	PUENTE, G J
10676	ALMIRANTEARENA, JOSEPH
10696	BAZLEY, R
10704	OCCUPANT UNKNOWN,
10716	MACHADO, ENERIO
10724	LAFFERTY, BARBARA J
10732	OCCUPANT UNKNOWN,
10738	OCCUPANT UNKNOWN,
10746	OCCUPANT UNKNOWN,
10830	OCCUPANT UNKNOWN,
10838	STRICKLAND, BLAINE
10846	COLWELL, GARY
10866	TORRES, MARIA R
10886	HERNANDEZ, MAURICE A
	PEREIRA, DAVID C
10918	OCCUPANT UNKNOWN,

BELLEGRAVE AVE 2000 (Cont'd)

10968 LOMELI, LUIS M
11255 HOEKSTRA, LOUIE
11305 OCCUPANT UNKNOWN,
11355 OCCUPANT UNKNOWN,
11375 HOEKSTRA, EDWARD
11561 TROOST, FRED
11571 TROOST, MAYNARD J
11591 OCCUPANT UNKNOWN,
11611 TROOST HAY SALES
WARRINER, JON E
12000 VERNOLA RANCH
12041 ALONZO, JUAN
12071 CARDENAS, JESUS
MIRA LOMA THOROUGHBRED FARM
NIXON CRAIG L
12080 ACUNA, ROBERTO S
CASTRO, ROGELIO
FOREVER LIVING
NATURES BEST DIRECT INCORPORATED
12419 OCCUPANT UNKNOWN,
12421 MOCHO, JEAN
12423 PLAA MICHEL
PLAA, MICHEL

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 1995

10236	PEARCES BACKHOE SVC
10246	OCCUPANT UNKNOWNN
10248	BROCK, DIANA
10250	CRISS, LEE R
10252	SANMIGUEL, ELIZAEL
10254	STINSON, JAMES D
10256	HOBGOOD, JAMES E
10274	OCCUPANT UNKNOWNN
10372	GARCIA, SALAZAR A
10390	OCCUPANT UNKNOWNN
10396	GOLDEN RETREAT KENNELS
	OCCUPANT UNKNOWNN
10420	BI RITE REDI MIX CONCRETE CORP
	MISSION CONCRETE PUMPING CORP
	STANDARD READY MIX
10516	DAVIS, BRIAN E
10520	OCCUPANT UNKNOWNN
10526	OCCUPANT UNKNOWNN
10530	OCCUPANT UNKNOWNN
10551	JURAPA VALLEY HIGH SCHOOL
	JURUPA VALLEY HIGH
10630	OCCUPANT UNKNOWNN
10656	LONGANECKER, DONALD F
10676	JOHNSON, RICHARD E
10696	BAZLEY, R
10704	OCCUPANT UNKNOWNN
10716	MACHADO, ENERIO
10724	LAFFERTY, BARBARA J
10746	CAMBIOS BELLEGRAVE NURSERY
10830	OCCUPANT UNKNOWNN
10838	OCCUPANT UNKNOWNN
10846	COLWELL, GARY
10886	RAMIREZ, F
10968	OCCUPANT UNKNOWNN
11255	HOEKSTRA, LOUIE
11305	OCCUPANT UNKNOWNN
11355	OCCUPANT UNKNOWNN
11375	HOEKSTRA, EDWARD
11537	OCCUPANT UNKNOWNN
11561	OCCUPANT UNKNOWNN
11571	TROOST, MAYNARD J
11591	BLEYENBERG, J
11611	TROOST, PHIL G
12041	MUNOZ, JOSE M
12071	ALTFILLISCH CONSTRUCTION CO
	MIRA LOMA THOROUGHBRED FARM
	SILVA ARTURA
	WIXON, ANN
12080	CASTRO, ROGELI
	VERNOLA RANCH

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 1995 (Cont'd)

12419 AVALOS, TORBIO
12421 MOCHO, JEAN
12423 PLAA, MICHEL
12451 GORZEMAN, JOE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

BELLEGRAVE AVE 1992

10055 MODICA, PHILIP

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752

Inquiry Number: 6691091.7
October 06, 2021

EDR Environmental Lien and AUL Search

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search

The EDR Environmental Lien and AUL Search Report provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address information to:

- search for parcel information and/or legal description;
- search for ownership information;
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc.;
- access a copy of the deed;
- search for environmental encumbering instrument(s) associated with the deed;
- provide a copy of any environmental encumbrance(s) based upon a review of key words in the instrument(s) (title, parties involved, and description); and
- provide a copy of the deed or cite documents reviewed.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search

TARGET PROPERTY INFORMATION

ADDRESS

12080 Bellegrave Avenue
Vernola Ranch North
Mira Loma, CA 91752

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

OTHER ACTIVITY AND USE LIMITATIONS (AULs)

AULs: Found ☐ Not Found ☒

RESEARCH SOURCE

Source 1:

Riverside Recorder
Riverside, CA

PROPERTY INFORMATION

Deed 1:

Type of Deed:	deed
Title is vested in:	Patrick Vernola Trustee
Title received from:	Patrick Vernola Trustee
Deed Dated	2/19/2019
Deed Recorded:	5/21/2019
Book:	NA
Page:	na
Volume:	na
Instrument:	na
Docket:	NA
Land Record Comments:	
Miscellaneous Comments:	
Legal Description:	See Exhibit
Legal Current Owner:	Patrick Vernola Trustee
Parcel # / Property Identifier:	160-050-070
Comments:	See Exhibit

Deed Exhibit 1

DOC # 2019-0177926
05/21/2019 02:12 PM Fees: $39.00
Page 1 of 6
Recorded in Official Records
County of Riverside
Peter Aldana
Assessor-County Clerk-Recorder

This document was electronically submitted to the County of Riverside for recording
Receipted by: ALYCIA #778

CHICAGO TITLE COMPANY
COMMERCIAL DIVISION

RECORDING REQUESTED BY

Chicago Title Company

WHEN RECORDED MAIL TO AND
MAIL TAX STATEMENTS TO:

Patrick Vernola
P.O. Box 217
Upland, CA 91784-0217
80102 909-996-3131

TRA: 028-114

Space above this line for Recorder's Use

APNs: 160-050-063, -067, -070 and -072

Documentary Transfer Tax: $0*

SIGNATURE

*No Consideration – This conveyance is exempt from the imposition of the documentary transfer tax because it is a transfer of an interest in real property in trust for the benefit of a person by reason of the death of a person (Revenue and Taxation Code Section 11930).

GRANT DEED

FOR VALUABLE CONSIDERATION, the receipt of which is hereby acknowledged, PATRICK VERNOLA, Successor Trustee of the Anthony P. Vernola Trust U/D/T dated October 18, 2000, as amended ("Grantor"), hereby grants to PATRICK VERNOLA, Trustee of the Chris McCabe Trust created by the Anthony P. Vernola Trust U/D/T dated October 18, 2000, as amended, all of Grantor's interest in that certain real property located in the City of Jurupa Valley, County of Riverside, State of California, legally described on Exhibit "A" attached hereto and made a part hereof.

Dated this 19th day of February 2019.

[Signature Page Follows.]

IN WITNESS WHEREOF, Grantor has executed this Grant Deed to be effective as of the date set forth above.

GRANTOR:

PATRICK VERNOLA, Successor Trustee
of the Anthony P. Vernola Trust U/D/T
dated October 18, 2000, as amended

A Notary Public or other officer completing this certificate verifies only the identity of the individual who signed the document to which this certificate is attached, and not the truthfulness, accuracy, or validity of that document.

State of California)
County of ORANGE)

On FEBRUARY 19, 2019, before me, MARTHA RAMIREZ,
(insert name and title of the officer)
Notary Public, personally appeared PATRICK VERNOLA,
who proved to me on the basis of satisfactory evidence to be the person(s) whose name(s) is/are subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their authorized capacity(ies), and that by his/her/their signature(s) on the instrument the person(s), or the entity upon behalf of which the person(s) acted, executed the instrument.

I certify under PENALTY OF PERJURY under the laws of the State of California that the foregoing paragraph is true and correct.

WITNESS my hand and official seal.

Signature _____ (Seal)

MARTHA RAMIREZ
Notary Public - California
Orange County
Commission # 2269939
My Comm. Expires Dec 31, 2022

2607/023520-0036
13302271

EXHIBIT "A"

LEGAL DESCRIPTION OF REAL PROPERTY

That certain real property situated in the City of Jurupa Valley, County of Riverside, State of California, described as follows:

PARCEL A:

THAT PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4833 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, TOGETHER WITH THAT PORTION OF THE WEST HALF OF FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, AS SHOWN BY MAP ON FILE IN BOOK 9, PAGE 33 OF MAPS, RECORDS OF SAN BERNARDINO COUNTY, CALIFORNIA, LYING IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, SAID PORTION BEING DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (59.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63, INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE NORTHEAST CORNER OF PARCEL 4;

THENCE NORTH 00° 23' 42' WEST ALONG SAID CENTERLINE OF PATS RANCH ROAD AND THE EASTERLY LINE OF SAID PARCEL 1, A DISTANCE OF 1213.88 FEET TO A POINT ON THE EASTERLY PROLONGATION OF THE WESTERLY BOUNDARY OF THAT CERTAIN 245.00 FOOT WIDE STRIP OF LAND DESCRIBED IN THE GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE TRUE POINT OF BEGINNING;

THENCE SOUTH 89° 39' 53" WEST ALONG SAID EASTERLY PROLONGATION AND SAID WESTERLY BOUNDARY, A DISTANCE OF 1427.88 FEET TO THE NORTHEAST CORNER OF PARCEL 4446-1 OF SUPERIOR COURT OF STATE OF CALIFORNIA CASE NO. 169015 PER DOCUMENT RECORDED FEBRUARY 1, 1988 AS INSTRUMENT NO. 28620 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE BEGINNING OF A NON-TANGENT CURVE CONCAVE WESTERLY, HAVING A RADIUS OF 6000.00 FEET, THE RADIAL LINE TO SAID POINT BEARS SOUTH 89° 47' 58" EAST;

THENCE NORTHERLY ALONG SAID CURVE, TO THE LEFT AND ALONG THE WESTERLY BOUNDARY OF SAID PARCEL 1, THROUGH A CENTRAL ANGLE OF 13° 05' 48", AN ARC DISTANCE OF 1371.48 FEET;

THENCE CONTINUING NORTHERLY ALONG SAID WESTERLY BOUNDARY OF PARCEL 1, NORTH 12° 54' 16" WEST, A DISTANCE OF 772.07 FEET TO AN ANGLE POINT ON SAID WESTERLY BOUNDARY;

THENCE CONTINUING NORTHERLY ALONG SAID WESTERLY BOUNDARY OF PARCEL 1 AND THE NORTHERLY AND EASTERLY BOUNDARY OF SAID PARCEL 1 THE FOLLOWING FOUR (4) COURSES AND DISTANCES:

1) NORTH 00° 04' 22" WEST, A DISTANCE OF 221.33 FEET TO AN ANGLE POINT THEREON;

2) NORTH 65° 18' 24" EAST, A DISTANCE OF 805.26 FEET TO AN ANGLE POINT THEREON;

3) NORTH 69° 10' 41" EAST, A DISTANCE OF 753.21 FEET TO AN ANGLE POINT THEREON;

4) SOUTH 20° 49' 19" EAST, A DISTANCE OF 487.81 FEET TO THE BEGINNING OF A TANGENT CURVE CONCAVE WESTERLY, HAVING A RADIUS OF 2000.00 FEET;

THENCE SOUTHEASTERLY ALONG SAID CURVE, TO THE RIGHT THROUGH A CENTRAL ANGLE OF 20° 25' 37" AN ARC DISTANCE OF 713.03 FEET;

THENCE CONTINUING ALONG SAID EASTERLY BOUNDARY OF PARCEL 1, SOUTH 00° 23' 42" EAST, A DISTANCE OF 1776.74 FEET TO THE TRUE POINT OF BEGINNING.

SAID LAND IS ALSO KNOWN AS PARCEL 2 AS SHOWN AND DESCRIBED IN THE NOTICE OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INSTRUMENT NO. 2016-154093 OF OFFICIAL RECORDS.

PARCEL B:

THAT PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4833 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620 OF OFFICIAL RECORDS, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026 OF OFFICIAL RECORDS, TOGETHER WITH A PORTION OF GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS AND ALSO A PORTION OF GRANT DEED RECORDED OCTOBER 5, 2007 AS INSTRUMENT NO. 2007-0623246 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, LYING IN FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, SAID PORTION BEING DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (59.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63, INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE

COUNTY, CALIFORNIA, SAID POINT BEING THE SOUTHEAST CORNER OF SAID PARCEL 1;

THENCE SOUTH 89° 36' 18" WEST ALONG THE SOUTHERLY BOUNDARY OF SAID PARCEL 1, A DISTANCE OF 389.30 FEET TO AN ANGLE POINT ON SAID SOUTHERLY BOUNDARY OF PARCEL 1, SAID ANGLE POINT BEING THE SOUTHERLY TERMINUS OF THAT CERTAIN DESCRIBED LINE HAVING A BEARING AND DISTANCE OF "NORTH 00° 08' 18" WEST, 522.34 FEET" IN SAID PARCEL 1;

THENCE NORTH 00° 08' 18" WEST ALONG SAID DESCRIBED LINE AND THE NORTHERLY PROLONGATION OF SAID DESCRIBED LINE, A DISTANCE OF 830.72 FEET TO THE TRUE POINT OF BEGINNING;

THENCE SOUTH 89° 51' 42" WEST, A DISTANCE OF 1047.38 FEET TO THE EASTERLY LINE OF PARCEL 4446-1 OF SUPERIOR COURT OF THE STATE OF CALIFORNIA CASE NO. 169015 PER DOCUMENT RECORDED FEBRUARY 1, 1988 AS INSTRUMENT NO. 28620 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA;

THENCE NORTH 00° 22' 20" EAST ALONG SAID EASTERLY LINE OF PARCEL 4446-1, A DISTANCE OF 362.01 FEET TO THE BEGINNING OF A TANGENT CURVE CONCAVE WESTERLY, HAVING A RADIUS OF 6000.00 FEET;

THENCE CONTINUING NORTHERLY ALONG SAID EASTERLY BOUNDARY OF PARCEL 4446-1 AND NORTHERLY ALONG SAID CURVE, TO THE LEFT, THROUGH A CENTRAL ANGLE OF 00° 10' 18", AN ARC DISTANCE OF 17.99 FEET TO THE NORTHEAST CORNER OF SAID PARCEL 4446-1;

THENCE NORTH 89° 39' 53" EAST ALONG THE WESTERLY BOUNDARY OF THAT CERTAIN 245.00 FOOT WIDE STRIP OF LAND DESCRIBED IN THE GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS AND THE EASTERLY PROLONGATION OF SAID 245.00 FOOT WIDE STRIP OF LAND, A DISTANCE OF 1427.88 FEET TO SAID CENTERLINE OF PATS RANCH ROAD;

THENCE SOUTH 00° 23' 42" EAST ALONG SAID CENTERLINE OF PATS RANCH ROAD, A DISTANCE OF 384.89 FEET;

THENCE SOUTH 89° 51' 42" WST, A DISTANCE OF 385.58 FEET TO THE TRUE POINT OF BEGINNING.

SAID LAND IS ALSO KNOWN AS PARCEL 3 AS SHOWN AND DESCRIBED IN THE NOTICE OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INSTRUMENT NO. 2016-154093 OF OFFICIAL RECORDS.

PARCEL C:

NON-EXCLUSIVE EASEMENTS FOR SURFACE DRAINAGE AND RIGHTS INCIDENTAL THERETO AND SUBJECT TO ALL THE TERMS, CONDITIONS AND PROVISIONS

THEREIN CONTAINED AS PROVIDED FOR IN THAT CERTAIN INSTRUMENT ENTITLED "CONSTRUCTION AND EASEMENT AGREEMENT" DATED JUNE 9, 2016 AND RECORDED JUNE 17, 2016 AS INSTRUMENT NO. 2016-249915, OF OFFICIAL RECORDS.

EXHIBIT "A"

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752

Inquiry Number: 6691091.4
October 05, 2021

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

10/05/21

Site Name:

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752
EDR Inquiry # 6691091.4

Client Name:

Geotek
1548 North Maple Street
Corona, CA 92880
Contact: Anna M. Scott

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Geotek were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA
Project: 2903-CR

Coordinates:

Latitude:	33.984882 33° 59' 6" North
Longitude:	-117.546146 -117° 32' 46" West
UTM Zone:	Zone 11 North
UTM X Meters:	449555.38
UTM Y Meters:	3760614.12
Elevation:	689.00' above sea level

Maps Provided:

2012
1981
1973
1966, 1967
1953, 1954
1944, 1947
1942
1902

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2012 Source Sheets




Corona North
2012
7.5-minute, 24000




Guasti
2012
7.5-minute, 24000

1981 Source Sheets



Guasti
1981
7.5-minute, 24000
Aerial Photo Revised 1978



Corona North
1981
7.5-minute, 24000
Aerial Photo Revised 1978

1973 Source Sheets



Guasti
1973
7.5-minute, 24000
Aerial Photo Revised 1973



Corona North
1973
7.5-minute, 24000
Aerial Photo Revised 1973

1966, 1967 Source Sheets



Guasti
1966
7.5-minute, 24000
Aerial Photo Revised 1966



Corona North
1967
7.5-minute, 24000
Aerial Photo Revised 1966

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1953, 1954 Source Sheets




Guasti
1953
7.5-minute, 24000
Aerial Photo Revised 1952



Corona North
1954
7.5-minute, 24000
Aerial Photo Revised 1952

1944, 1947 Source Sheets




CUCAMONGA
1944
15-minute, 50000



CORONA
1947
15-minute, 50000

1942 Source Sheets



Corona and Vicinity
1942
7.5-minute, 31680


1902 Source Sheets



Corona
1902
30-minute, 125000

Historical Topo Map

2012



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Corona North, 2012, 7.5-minute
N, Guasti, 2012, 7.5-minute

SITE NAME: Vernola Ranch North
ADDRESS: 12080 Bellegrave Avenue
Mira Loma, CA 91752
CLIENT: Geotek

N

Historical Topo Map

1981



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Corona North, 1981, 7.5-minute
N, Guasti, 1981, 7.5-minute

SITE NAME: Vernola Ranch North
ADDRESS: 12080 Bellegrave Avenue
Mira Loma, CA 91752
CLIENT: Geotek

N

Historical Topo Map

1973



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Corona North, 1973, 7.5-minute
N, Guasti, 1973, 7.5-minute

SITE NAME: Vernola Ranch North
ADDRESS: 12080 Bellegrave Avenue
Mira Loma, CA 91752
CLIENT: Geotek

N

Historical Topo Map

1966, 1967



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Corona North, 1967, 7.5-minute
N, Guasti, 1966, 7.5-minute

SITE NAME: Vernola Ranch North
ADDRESS: 12080 Bellegrave Avenue
Mira Loma, CA 91752
CLIENT: Geotek

N

Historical Topo Map

1953, 1954



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Corona North, 1954, 7.5-minute
N, Guasti, 1953, 7.5-minute

SITE NAME: Vernola Ranch North
ADDRESS: 12080 Bellegrave Avenue
Mira Loma, CA 91752
CLIENT: Geotek

N

Historical Topo Map

1944, 1947



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, CORONA, 1947, 15-minute
NW, CUCAMONGA, 1944, 15-minute

SITE NAME: Vernola Ranch North
ADDRESS: 12080 Bellegrave Avenue
Mira Loma, CA 91752
CLIENT: Geotek

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5


NW N NE
W E
SW S SE

TP, Corona and Vicinity, 1942, 7.5-minute

SITE NAME: Vernola Ranch North
ADDRESS: 12080 Bellegrave Avenue
Mira Loma, CA 91752
CLIENT: Geotek

N

UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Corona, 1902, 30-minute

SITE NAME: Vernola Ranch North
ADDRESS: 12080 Bellegrave Avenue
Mira Loma, CA 91752
CLIENT: Geotek

N

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752

Inquiry Number: 6691091.6
October 05, 2021

The EDR Property Tax Map Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Property Tax Map Report

Environmental Data Resources, Inc.'s EDR Property Tax Map Report is designed to assist environmental professionals in evaluating potential environmental conditions on a target property by understanding property boundaries and other characteristics. The report includes a search of available property tax maps, which include information on boundaries for the target property and neighboring properties, addresses, parcel identification numbers, as well as other data typically used in property location and identification.


Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.



Date	Old Number	New Number	Date	Old Number	New Number	Date	Old Number	New Number
1/1/1986	10	11,ST	3/7/2006	25	33-36	12/29/2015	53	PGS.36,41
3/1/1986	6	12-14	3/7/2006	15	37-40	1/7/2016	35	54,ST
1/1/1987	9,11	16	3/7/2006	3	41-42	1/7/2016	36	55,ST
1/1/1987	16	17-18	3/7/2006	33,37	43	4/12/2016	52	56,57
1/1/1987	8	19-20	3/7/2006	34,38	44	4/12/2016	55	58,59
1/1/1987	4	21-22	3/27/2006	40,42	45	12/7/2016	56	60,ST
1/1/1987	17,19	23	3/27/2006	39,41	46	12/7/2016	27	61-62
1/1/1987	18,20	24	1/29/2009	44	47,ST	12/7/2016	31	63-65
3/1/1990	1	25-26	1/29/2009	43	48,ST	12/7/2016	48	66-69
3/1/1990	7	27-28	1/29/2009	45	49,ST	12/7/2016	66,040-39	70
3/1/1990	24,28	29	1/29/2009	46	50,ST	12/7/2016	040-11	71
12/1/1996	12	30,ST	10/15/2014	49	PG.35,36	12/7/2016	61,64	72
5/1/1997	14,30	32	8/19/2015	47	51,ST	12/7/2016	62,65	73
4/1/2002	13	PG.3	12/29/2015	51	52,53	12/7/2016	50,69	74

Frank Green

Stewart Title Guaranty Company
Commercial Services (San Diego)
7676 Hazard Center Drive, Ste 1400
San Diego, CA 92108
(619) 398-8035 Phone
(619) 615-2389 Fax
fgreen@stewart.com

PRELIMINARY REPORT

Order No.	:	21000480570
Title Unit No.	:	48
Your File No.	:	
Buyer/Borrower Name	:	
Seller Name	:	SKY COUNTRY INV CO EAST, MGP X VERNOLA, and CHRIS MCCABE TRUST

Property Address: Multiple APNS, Riverside, CA 92505

In response to the above referenced application for a Policy of Title Insurance, Stewart Title Guaranty Company Commercial Services (San Diego) hereby reports that it is prepared to issue, or cause to be issued, as of the date hereof, a Stewart Title Guaranty Company Policy or Policies of Title Insurance describing the land and the estate or interest therein hereinafter set forth, insuring against loss which may be sustained by reason of any defect, lien or encumbrance not shown or referenced to as an Exception on Schedule B or not excluded from coverage pursuant to the printed Schedules, Conditions, and Stipulations of said Policy forms.

The printed Exceptions and Exclusions from the coverage and Limitations on covered Risks of said policy or policies are set forth in Exhibit A attached. The policy to be issued may contain an arbitration clause. When the Amount of Insurance is less than that set forth in the arbitration clause, all arbitrable matters shall be arbitrated at the option of either the Company or the Insured as the exclusive remedy of the parties. Limitations on Covered Risks applicable to the CLTA and ALTA Homeowner's Policies of Title Insurance which establish a Deductible Amount and a Maximum Dollar Limits of Liability for certain coverages are also set forth in Exhibit A. Copies of the policy forms should be read. They are available from the office which issued this report.

Please read the exceptions shown or referred to below and the exceptions and exclusions set forth in Exhibit A of this report carefully. The exceptions and exclusions are meant to provide you with notice of matters, which are not covered under the terms of the title insurance policy and should be carefully considered.

It is important to note that this preliminary report is not a written representation as to the condition of title and may not list all liens, defects, and encumbrances affecting title to the land.

This report, (and any supplements or amendments thereto) is issued solely for the purpose of facilitating the issuance of a policy of title insurance and no liability is assumed hereby. If it is desired that liability be assumed prior to the issuance of a policy of title insurance a binder or commitment should be requested.

Dated as of August 23, 2021 at 7:30 a.m.

Amendment No. FOUR

Frank Green, Title Officer

When replying, please contact: Frank Green, Title Officer

PRELIMINARY REPORT

The form of Policy of Title Insurance contemplated by this report is:

☒ CLTA Standard Coverage Policy

☐ CLTA/ALTA Homeowners Policy

☐ 2006 ALTA Owner's Policy

☒ 2006 ALTA Loan Policy

☐ ALTA Short Form Residential Loan Policy

☐

SCHEDULE A

The estate or interest in the land hereinafter described or referred to covered by this report is:

A fee as to Parcel(s) A and B of Division I, and A and B of Divisions II and III. An easement more particularly described below as to Parcel(s) C of Division I.

Title to said estate or interest at the date hereof is vested in:

Patrick Vernola, Trustee of The Chris McCabe Trust created by the Anthony P. Vernola Trust U/D/T dated October 18, 2000, Bellatera Investments PA 13, LLC, a California limited liability company; Boomer Investments PA 13, LLC, a Delaware limited liability company; and Shellina Investments PA 13, a California limited liability company, as to Division I;

Sky Country Investment Co./East, LLC, as to Division II A and B

Anthony P. Vernola, Trustee of The Anthony P. Vernola Trust under Trust Agreement dated October 18, 2000, and Anthony P. Vernola, Successor Trustee of The Pat and Mary Ann Vernola Trust - Marital Trust, as to Division III

LEGAL DESCRIPTION

The land referred to herein is situated in the State of California, County of Riverside, City of Riverside and described as follows:

DIVISION I:

PARCEL A:

THAT PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4133 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, TOGETHER WITH THAT PORTION OF THE WEST HALF OF FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, AS SHOWN BY MAP ON FILE IN BOOK 9, PAGE 33 OF MAPS, RECORDS OF SAN BERNARDINO COUNTY, CALIFORNIA, LYING IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, SAID PORTION BEING DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (59.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63, INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE NORTHEAST CORNER OF PARCEL 4;

THENCE NORTH 00° 23’ 42" WEST ALONG SAID CENTERLINE OF PATS RANCH ROAD AND THE EASTERLY LINE OF SAID PARCEL 1, A DISTANCE OF 1213.18 FEET TO A POINT ON THE EASTERLY PROLONGATION OF THE WESTERLY BOUNDARY OF THAT CERTAIN 245.00 FOOT WIDE STRIP OF LAND DESCRIBED IN THE GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE TRUE POINT OF BEGINNING;

THENCE SOUTH 89° 39’ 53" WEST ALONG SAID EASTERLY PROLONGATION AND SAID WESTERLY BOUNDARY, A DISTANCE OF 1427.88 FEET TO THE NORTHEAST CORNER OF PARCEL 4446-1 OF SUPERIOR COURT OF STATE OF CALIFORNIA CASE NO. 169015 PER DOCUMENT RECORDED FEBRUARY 1, 1988 AS INSTRUMENT NO. 28620 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE BEGINNING OF A NON-TANGENT CURVE CONCAVE WESTERLY. HAVING A RADIUS OF 6000.00 FEET, THE RADIAL LINE TO SAID POINT BEARS SOUTH 89° 47’ 51” EAST;

THENCE NORTHERLY ALONG SAID CURVE, TO THE LEFT AND ALONG THE WESTERLY BOUNDARY OF SAID PARCEL 1, THROUGH A CENTRAL ANGLE OF 13° 05' 48" AN ARC DISTANCE OF 1371.41 FEET;

THENCE CONTINUING NORTHERLY ALONG SAID WESTERLY BOUNDARY OF PARCEL 1, NORTH 12° 54' 16” WEST, A DISTANCE OF 772.07 FEET TO AN ANGLE POINT ON SAID WESTERLY BOUNDARY;

THENCE CONTINUING NORTHERLY ALONG SAID WESTERLY BOUNDARY OF PARCEL 1 AND THE NORTHERLY AND EASTERLY BOUNDARY OF SAID PARCEL 1 THE FOLLOWING FOUR (4) COURSES AND DISTANCES:

1) NORTH 00° 42’ 22” WEST, A DISTANCE OF 221.33 FEET TO AN ANGLE POINT THEREON;

2) NORTH 65° 18’ 24” EAST. A DISTANCE OF 805.26 FEET TO AN ANGLE POINT THEREON;

3) NORTH 69° 10’ 41” EAST, A DISTANCE OF 753.21 FEET TO AN ANGLE POINT THEREON;

4) SOUTH 20° 49’ 19" EAST, A DISTANCE OF 487.81 FEET TO THE BEGINNING OF A TANGENT CURVE CONCAVE WESTERLY, HAVING A RADIUS OF 2000.00 FEET;

THENCE SOUTHEASTERLY ALONG SAID CURVE, TO THE RIGHT THROUGH A CENTRAL ANGLE OF 20° 25’ 37” AN ARC DISTANCE OF 713.03 FEET;

THENCE CONITINUING ALONG SAID EASTERLY BOUNDARY OF PARCEL 1, SOUTH 00° 23’ 42” EAST, A DISTANCE OF 1776.74 FEET TO THE TRUE POINT OF BEGINNING.

SAID LAND IS ALSO KNOWN AS PARCEL 2 AS SHOWN AND DESCRIBED IN THE NOTICE OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INSTRUMENT NO. 2016-154093 OF OFFICIAL CORDS.

APN(s): 160-050-063 AND 160-050-070

PARCEL B:

THAT PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4133 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620, OF OFFICIAL RECORDS, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026, OF OFFICIAL RECORDS, TOGETHER WITH A PORTION OF GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS AND ALSO A PORTION OF GRANT DEED RECORDED OCTOBER 5, 2007 AS INSTRUMENT NO. 2007-0623246 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, LYING IN FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, SAID PORTION BEING DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (59.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63, INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE SOUTHEAST CORNER OF SAID PARCEL 1;

THENCE SOUTH 89° 36’ 18" WEST ALONG THE SOUTHERLY BOUNDARY OF SAID PARCEL 1, A DISTANCE OF 389.30 FEET TO AN ANGLE POINT ON SAID SOUTHERLY BOUNDARY OF PARCEL 1, SAID ANGLE POINT BEING THE SOUTHERLY TERMINUS OF THAT CERTAIN DESCRIBED LINE HAVING A BEARING AND DISTANCE OF "NORTH 00° 08’ 18" WEST, 522.34 FEET" IN SAID PARCEL 1;

THENCE NORTH 00° 08' 18" WEST ALONG SAID DESCRIBED LINE AND THE NORTHERLY PROLONGATION OF SAID DESCRIBED LINE, A DISTANCE OF 830.72 FEET TO THE TRUE POINT OF BEGINNING;

THENCE SOUTH 89° 51’ 42” WEST, A DISTANCE OF 1047.38 FEET TO THE EASTERLY LINE OF PARCEL 4446-1 OF SUPERIOR COURT OF THE STATE OF CALIFORNIA CASE NO. 169015 PER DOCUMENT RECORDED FEBRUARY 1, 1988 AS INSTRUMENT NO. 28620 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA;

THENCE NORTH 00° 22’ 20” EAST ALONG SAID EASTERLY LINE OF PARCEL 4446-1, A DISTANCE OF 362.01 FEET TO THE BEGINNING OF A TANGENT CURVE CONCAVE WESTERLY, HAVING A RADIUS OF 6000.00 FEET.

THENCE CONTINUING NORTHERLY ALONG SAID EASTERLY BOUNDARY OF PARCEL 4446-1 AND NORTHERLY ALONG SAID CURVE, TO THE LEFT, THROUGH A CENTRAL ANGLE OF 00° 10’ 18”, AN ARC DISTANCE OF 17.99 FEET TO THE NORTHEAST CORNER OF SAID PARCEL 4446-1;

THENCE NORTH 89° 39’ 53” EAST ALONG THE WESTERLY BOUNDARY OF THAT CERTAIN 245.00 FOOT WIDE STRIP OF LAND DESCRIBED IN THE GRANT DEED RLCORDED SEPTEMBER 17, 1968

AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS AND THE EASTERLY PROLONGATION OF SAID 245.00 FOOT WIDE STRIP OF LAND, A DISTANCE OF 1427.88 FEET TO SAID CENTERLINE OF PATS RANCH ROAD;

THENCE SOUTH 00° 23' 42" EAST ALONG SAID CENTERLINE OF PATS RANCH ROAD, A DISTANCE OF 384.89 FEET;

THENCE SOUTH 89° 51' 42" WEST, A DISTANCE OF 385.58 FEET TO THE TRUE POINT OF BEGINNING.

SAID LAND IS ALSO KNOWN AS PARCEL 3 AS SHOWN AND DESCRIBED IN THE NOTICE OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INSTRUMENT NO. 2016-154093, OF OFFICIAL RECORDS.

APN(s): 160-050-067 AND 160-050-072

PARCEL C:

NON-EXCLUSIVE EASEMENTS FOR SURFACE DRAINAGE AND RIGHTS INCIDENTAL THERETO AND SUBJECT TO ALL THE TERMS, CONDITIONS AND PROVISIONS THEREIN CONTAINED AS PROVIDED FOR IN THAT CERTAIN INSTRUMENT ENTITLED "CONSTRUCTION AND EASEMENT AGREEMENT DATED JUNE 9, 2016 AND RECORDED JUNE 17, 2016 AS INSTRUMENT NO. 2016-249915, OF OFFICIAL RECORDS.

DIVISION II:

PARCEL A:

PARCEL 4 OF NOTICE OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INSTRUMENT NO. 2016-0154093 OFFICIAL RECORDS DESCRIBED AS FOLLOWS:

THAT PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4833 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620 OF OFFICIAL RECORDS, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026, TOGETHER WITH A PORTION OF GRANT DEED INSTRUMENT NO. 89577 RECORDED SEPTEMBER 17, 1968 AND ALSO A PORTION OF GRANT DEED INSTRUMENT NO. 2007-0623246 RECORDED OCTOBER 5, 2007 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA LYING WITHIN FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, AS SHOWN BY MAP ON FILE IN BOOK 9, OF MAPS, AT PAGE 33 THEREOF, RECORDS OF SAN BERNARDINO COUNTY, CALIFORNIA, LYING IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, SAID PORTION BEING DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (59.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63 INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE SOUTHEAST COMER OF SAID PARCEL 1; THENCE SOUTH 89° 36' 18" WEST ALONG THE SOUTHERLY BOUNDARY OF SAID PARCEL 1, A DISTANCE OF 389.30 FEET TO AN ANGLE POINT ON SAID SOUTHERLY BOUNDARY OF PARCEL 1, SAID ANGLE POINT BEING THE SOUTHERLY TERMINUS OF THAT CERTAIN DESCRIBED LINE HAVING A BEARING AND DISTANCE OF NORTH 00° 08' 18" WEST, 522.34 FEET IN SAID PARCEL 1; THENCE NORTH 00° 08' 18" WEST ALONG SAID DESCRIBED LINE, A DISTANCE OF 522.34 FEET TO THE NORTHERLY TERMINUS OF SAID DESCRIBED LINE. SAID POINT BEING THE TRUE POINT OF BEGINNING:

THENCE NORTH 00° 08' 18" WEST ALONG THE NORTHERLY PROLONGATION OF SAID DESCRIBED LINE, A DISTANCE OF 308.39 FEET; THENCE LEAVING SAID NORTHERLY PROLONGATION, SOUTH 89° 51' 42" WEST, A DISTANCE OF 1047.38 FEET TO THE EASTERLY LINE OF PARCEL 4446-1 OF SUPERIOR COURT OF THE STATE OF CALIFORNIA CASE NO. 169015 PER

DOCUMENT RECORDED FEBRUARY 1, 1988 AS INSTRUMENT NO. 28620 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA; THENCE SOUTH 00° 22' 20" WEST ALONG SAID EASTERLY LINE OF PARCEL 4446-1, A DISTANCE OF 312.55 FEET TO A POINT ON THE SOUTHERLY LINE OF THE NORTHEAST QUARTER OF SAID FRACTIONAL SECTION 19, SAID POINT ALSO BEING THE SOUTHEAST CORNER OF SAID PARCEL 4446-1; THENCE NORTH 29° 38' 06" EAST ALONG SAID SOUTHERLY LINE OF THE NORTHEAST QUARTER OF FRACTIONAL SECTION 19, A DISTANCE OF 397.09 FEET TO THE WESTERLY BOUNDARY OF THAT CERTAIN 245.00 FOOT WIDE STRIP OF LAND DESCRIBED IN SAID GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA; THENCE SOUTH 00° 08' 05" EAST ALONG SAID WESTERLY BOUNDARY OF SAID 245.00 FOOT STRIP OF LAND, A DISTANCE OF 2638.39 FEET TO THE SOUTHERLY LINE OF SAID FRACTIONAL SECTION 19 THENCE NORTH 89° 35' 53" EAST ALONG SAID SOUTHERLY LINE OF FRACTIONAL SECTION 19, A DISTANCE OF 245.00 FEET TO THE EASTERLY BOUNDARY OF SAID 245.00 FOOT STRIP OF LAND: THENCE NORTH 00°08' 05" WEST ALONG SAID EASTERLY BOUNDARY OF THE 245.00 FOOT STRIP OF LAND, A DISTANCE OF 2638.23 FEET TO THE WESTERLY TERMINUS OF THAT CERTAIN COURSE DESCRIBED AS HAVING A BEARING AND DISTANCE OF "NORTH 89° 38' 06" EAST, 408.07 FEET" IN PARCEL 1 OF SAID LOT LINE ADJUSTMENT NO. 4233; THENCE NORTH 89° 38' EAST ALONG SAID DESCRIBED COURSE, A DISTANCE OF 408.07 FEET TO THE TRUE POINT OF BEGINNING.

APN(s): 160-050-73; 160-050-068

PARCEL B:

THE WEST HALF OF THE SOUTHEAST QUARTER OF SECTION 19, TOWNSHIP 2 SOUTH, RANGE 6 WEST, SAN BERNARDINO BASE AND MERIDIAN, AS SHOWN BY SECTIONIZED SURVEY OF THE JURUPA RANCHO, ON FILE IN BOOK 9 PAGE 33 OF MAPS, RECORDS OF SAN BERNARDINO COUNTY, CALIFORNIA

EXCEPTING THEREFROM THAT PORTION CONVEYED TO SOUTHERN CALIFORNIA EDISON COMPANY, A CORPORATION, BY DEED RECORDED DECEMBER 10, 1968 AS INSTRUMENT NO. 120541, OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA, DESCRIBED AS FOLLOWS:

A STRIP OF LAND 245 FEET WIDE, THE SIDE LINES OF SAID STRIP OF LAND 245 FEET WIDE, BEING 50 FEET EASTERLY. NORTHERLY AND EASTERLY AND 195 FEET WESTERLY, SOUTHERLY AND WESTERLY, MEASURED AT RIGHT ANGLES RESPECTIVELY, FROM THE SURVEYED REFERENCE LINE WHICH IS DESCRIBED AS FOLLOWS

BEGINNING AT A POINT IN THE NORTHERLY LINE OF FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 6 WEST, SAN BERNARDINO BASE AND MERIDIAN, SAID POINT BEING NORTH 89 DEGREES 41' 03" EAST, 1,295.11 FEET, MEASURED ALONG LAST MENTIONED NORTHERLY LINE FROM A FOUND 3 INCH IRON PIPE AND NAIL SET AT THE NORTHWEST CORNER OF SAID FRACTIONAL SECTION 19; THENCE SOUTH 00 DEGREES 15' 02" EAST, 1,784.91 FEET, MORE OR LESS, TO A POINT PARALLEL WITH AND 195 FEET NORTHERLY, MEASURED AT RIGHT ANGLES, FROM THE NORTHERLY LINE OF THE 126.039 ACRE PARCEL, AS SHOWN BY MAP ON FILE IN BOOK 7 PAGE 43 OF RECORDS OF SURVEY, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA; THENCE NORTH 89 DEGREES 25' 29" EAST, 2,293.60 FEET, MEASURED ALONG SAID PARALLEL LINE; THENCE SOUTH 00 DEGREES 22' 29" EAST, 3,525.41 FEET, MORE OR LESS, TO A POINT IN THE SOUTHERLY LINE OF FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 6 WEST, OF THE JURUPA RANCHO, SAID LAST MENTIONED POINT BEING SOUTH 89 DEGREES 21' 58" WEST, 1777.03 FEET, MEASURED ALONG LAST MENTIONED SOUTHERLY LINE FROM A FOUND 2 INCH BY 2 INCH STAKE WITH TACK SET AT THE SOUTHEAST CORNER OF SAID FRACTIONAL SECTION 19;

ALSO EXCEPTING THEREFROM THAT PORTION DESCRIBED IN DEEDS TO THE STATE OF CALIFORNIA. RECORDED SEPTEMBER 19, 1986 AS INSTRUMENT NOS. 230116 AND 230117 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA;

ALSO EXCEPTING THEREFROM THE SOUTH 20 FEET AND THE WEST 20 FEET OF THE SOUTHWEST QUARTER OF THE SOUTHWEST QUARTER OF THE SOUTHEAST QUARTER OF SAID SECTION 19, AS SET OUT IN DEED RECORDED NOVEMBER 22, 1976 AS INSTRUMENT NO. 179279 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA;

ALSO EXCEPTING THEREFROM THAT PORTION AS DESCRIBED IN THAT CERTAIN RIGHT OF WAY DEED RECORDED JUNE 25, 1935 IN BOOK 237, PAGE 40 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA.

APN: 160-050-005; 160-050-021 AND 160-050-023

DIVISION III:

ALL OF PARCEL 4 AND A PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4833 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620 OF OFFICIAL RECORDS, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, LYING IN FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, SAID PORTION BEING DESCRIBED AS FOLLOWS:

BEGINNING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (39.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63 INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE NORTHEAST CORNER OF SAID PARCEL 4;

THENCE SOUTH 00° 23' 42" EAST ALONG SAID CENTERLINE OF PATS RANCH ROAD AND THE EASTERLY LINE OF SAID PARCEL 4, A DISTANCE OF 2075.56 FEET TO THE SOUTHEAST CORNER OF SAID PARCEL 4; THENCE SOUTH 89° 35’ 53" WEST ALONG THE SOUTHERLY LINE OF SAID PARCEL 4, A DISTANCE OF 398.60 FEET TO THE SOUTHWEST CORNER OF SAID PARCEL 4;

THENCE NORTH 00° 01’ 18” WEST ALONG THE WESTERLY LINE OF SAID PARCEL 4, THE SOUTHERLY BOUNDARY OF SAID PARCEL 1 DESCRIBED AS HAVING A HEARING AND DISTANCE OF NORTH 00° 08’ 18" WEST, 522.34 FEET AND THE NORTHERLY PROLONGATION OF SAID DESCRIBED LINE, A DISTANCE OF 2906.35 FEET;

THENCE NORTH 89° 51’ 42” EAST, A DISTANCE OF 385.58 FEET TO SAID CENTERLINE OF PATS RANCH ROAD AND SAID EASTERLY LINE OF SAID PARCEL 1;

THENCE SOUTH 00° 23' 42" EAST ALONG SAID CENTERLINE OF PATS RANCH ROAD AND SAID EASTERLY LINE OF SAID PARCEL 1, A DISTANCE OF 828.98 FEET TO THE POINT OF BEGINNING.

SAID LAND BEING PARCEL 1 OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INTRUMENT NO. 2016-0154093 OFFICIAL RECORDS.

APN: 150-050-074

Division I - Parcel A - APN: 160-050-063 and 160-050-070
Division I - Parcel B - APN: 160-050-067 and 160-050-072

Division II - Parcel A - APN: 160-050-073 and 160-050-068
Division II - Parcel B - APN: 160-050-005; 160-050-021 and 160-050-023

Division III: APN: 160-050-074

(End of Legal Description)

THE MAP ATTACHED THROUGH THE HYPERLINK ABOVE IS BEING PROVIDED AS A COURTESY AND FOR INFORMATION PURPOSES ONLY; THIS MAP SHOULD NOT BE RELIED UPON. FURTHERMORE, THE PARCELS SET OUT ON THIS MAP MAY NOT COMPLY WITH LOCAL SUBDIVISION OR BUILDING ORDINANCES. THERE WILL BE NO LIABILITY, RESPONSIBILITY OR INDEMNIFICATION RELATED TO ANY MATTERS CONCERNING THE CONTENTS OR ACCURACY OF THE MAP.

SCHEDULE B

At the date hereof, exceptions to coverage in addition to the printed exceptions and exclusions contained in said policy or policies would be as follows:

Taxes:

A. Property taxes, which are a lien not yet due and payable, including any assessments collected with taxes, to be levied for the fiscal year 2021 - 2022.

B. The lien of supplemental taxes, if any, assessed pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the revenue and taxation code of the State of California.

C. Notice of special tax authorization recorded August 5, 2004 as Instrument No. 2004-0615557, of Official Records.

Exceptions:

1. Water rights, claims or title to water in or under the Land, whether or not shown by the public records.

2. Minerals of whatsoever kind, subsurface and surface substances, including but not limited to coal, lignite, oil, gas, uranium, clay, rock, sand and gravel in, on, under and that may be produced from the Land, together with all rights, privileges, and immunities relating thereto, whether or not appearing in the Public Records or listed in Schedule B. The Company makes no representation as to the present ownership of any such interests. There may be leases, grants, exceptions or reservations of interests that are not listed.

3. Any interests (including rights of the public) in and to any portion of the Land lying within roads, streets, alleys or highways.

THE FOLLOWING MATTERS AFFECTS DIVISION I

4. Easement(s) for the purpose(s) shown below and rights incidental thereto as condemned by an instrument,
   Entitled : Final Order of Condemnation
   Court : Superior
   Case No. : 169015
   Purpose : Utilities
   Recorded : February 2, 1988 as Instrument No. 28620, of Official Records
   Affects : A portion of said land as more particularly described in said document

5. The ownership of said land does not include rights of access to or from the street, highway, or freeway abutting said land, such rights having been relinquished by the document
   Recorded : February 2, 1988 as Instrument No. 28620, of Official Records
   Affects : A portion of said land as more particularly described in said document

6. Rights of the successor agency(ies) as to matters contained in the project plan recorded July 10, 1996 as Instrument No. 256410, of Official Records.

   The terms and provisions of said instrument have been modified by a document recorded July 16, 2007 as Instrument No. 2007-0459694, of Official Records.

7. Matters contained in document entitled Vernola Basin Reimbursement Agreement by and between

The Redevelopment Agency for the County of Riverside, a political subdivision of the State of California and Sky County Investment Co./East, LLC, a California limited liability company recorded July 6, 2005 as Instrument No. 2005-0536830, of Official Records.

Reference is hereby made to said document for full particulars.

8. Matters contained in document entitled Vernola Basin Reimbursement Agreement by The Redevelopment Agency of the County of Riverside recorded July 6, 2005 as Instrument No. 2005-0536832, of Official Records.

   Matters contained in document entitled Declaration to Establish Precise Amount of Reimbursement Obligation by Redevelopment Agency for the County of Riverside, a political subdivision of the State of California recorded July 18, 2013 as Instrument No. 2013-0348387 of Official Records.

9. Easement and rights incidental thereto for public road, drainage, public utility and public services to County of Riverside, as set forth in a document recorded September 17, 2008 as Instrument No. 2008-0507550, of Official Records.

10. Easement and rights incidental thereto for public road, drainage, public utility and public services to County of Riverside, as set forth in a document recorded recorded April 8, 2009 as Instrument No. 2009-0170542, of Official Records.

11. Matters contained in document entitled Construction and Easement Agreement by and between Sky Country Investment Co./East, LLC, a California limited liability company, Anthony P. Vernola, Trustee of The Anthony P. Vernola Trust U/D/T dated October 18, 2000, as amended, Anthony P. Vernola, Successor Trustee of The Pat and Mary Ann Vernola Trust - Marital Trust; APV Investment PA13, LLC, a California limited liability company; Bellatera Investments PA13, LLC, a California limited liability company; Boomer Investments PA13, LLC, a California limited liability company and Shellina Investments PA13, LLC, a California limited liability company recorded June 17, 2016 as Instrument No. 20160249915, of Official Records.

    Reference is hereby made to said document for full particulars.

12. Rights of parties in possession whether or not recorded in the public record.

13. Matters contained in Map Book 151, Page 39, of Records of Survey.

THE FOLLOWING MATTERS AFFECTS DIVISION II - PARCELS A AND B

14. A reservation of a strip of land of the uniform width of 20 feet on each side of all quarter section lines for public roads, electric railways, telephone lines, electric transmission lines, water conduits, drainage, et ux. as set out in deed executed by Rogers Development Company, recorded October 6, 1914 in Book 403, Page 189, of Deeds, Riverside County Records.

    Reference is hereby made to said document for full particulars.

15. Easement and rights incidental thereto for public highway and public utility to County of Riverside, as set forth in a document recorded June 25, 1935 in Book 237, Page 40 of Official Records.

16. Easement and rights incidental thereto for pipe lines to Southern Gas Company, an undivided 3/4 interest and Southern Counties Gas Company of California, an undivided 1/4 interest, as set forth in a document recorded December 18, 1950 in Book 1228, Page 488, of Official Records.

17. The ownership of said land does not include rights of access to or from the street, highway, or freeway abutting said land, such rights having been relinquished by the document.

Recorded : May 13, 1976 as Instrument No. 76-065887, of Official Records.
Affects : Said land adjacent to the highway

18. The ownership of said land does not include rights of access to or from the street, highway, or freeway abutting said land, such rights having been relinquished by the document.

    Recorded : September 19, 1986 as Instrument No. 86-230116, of Official Records.
    Affects : A portion of said land as more particularly described in said document

19. Easement and rights incidental thereto for utility to State of California, as set forth in a document recorded September 19, 1986 as Instrument No. 86-230118, of Official Records.

20. The ownership of said land does not include rights of access to or from the street, highway, or freeway abutting said land, such rights having been relinquished by the document.

    Recorded : February 2, 1988 as Instrument No. 86-28620, of Official Records.
    Affects : To the adjacent Freeway

21. Easement and rights incidental thereto for pipelines to Southern California Gas Company, as set forth in a document recorded January 6, 1994 as Instrument No. 94-007031, of Official Records.

22. Rights of the successor agency(ies) as to matters contained in the project plan recorded July 10, 1996 as Instrument No. 96-256410, of Official Records.

    The terms and provisions of said instrument have been modified by a document recorded July 16, 2007 as Instrument No. 2007-0459694, of Official Records.

23. Matters contained in document entitled Resolution No. 97-002 Approving and Amendment to the Fee Schedule of the Mira Loma Road and Bridge Benefit District (Amendment No. 1) recorded April 4, 1997 as Instrument No. 97-114479, of Official Records.

24. Matters contained in document entitled Memorandum of Agreement by and between Sky Country Investment Co./West, LLC, a California limited liability company and Lewis Investment Company, LLC, a California limited liability company recorded May 4, 2001 as Instrument No. 2001-194828, of Official Records.

25. Matters contained in document entitled Vernola Basin Reimbursement Agreement by and between The Redevelopment Agency for the County of Riverside, a political subdivision of the State of California and Sky Country Investment Co./East, LLC, a California limited liability company recorded July 6, 2005 as Instrument No. 2005-0536830, and July 6, 2005 as Instrument No. 2005-0536832, of Official Records.

    Matters contained in document entitled Agreement recorded July 18, 2013 as Instrument No. 2013-0348391, of Official Records and July 18, 2013 as Instrument no. 2013-348387, of Official Records

26. Matters contained in document entitled Site Designation Supplement to Master Lease and Sublease Agreement by and between STC One, LLC, a Delaware limited liability company, Global Signal Acquisitions II, LLC, a Delaware limited liability company and Sprint Telephony PCS, L.P., a Delaware Limited Partnership recorded January 4, 2006 as Instrument No. 2006-0005801, of Official Records.

27. Matters contained in document entitled Memorandum of License by and between Cingular Wireless, LLC, a Delaware limited liability company and Royal Street Communications, LLC, a Delaware limited liability company recorded April 13, 2007 as Instrument No. 2007-0250135, of Official Records.

28. Matters contained in an unrecorded lease dated April 26, 1996, executed by Sky Country Investment Co./East, LLC, a California limited liability company, as lessor and NCWPCS MPL 26 -

Year Sites Tower Holdings, LLC, a Delaware limited liability company, by and though its attorney in fact, CCATT LLC, a Delaware limited liability company, as lessee, as disclosed by Instrument No. December 30, 2015, recorded 2015-0562716, of Official Records.

Memorandum of Second Amendment to Ground Lease, recorded September 30, 2020 as Instrument No. 2020-0468004, of Official Records.

Current owner of leasehold and any other matters affecting the interest of the lessee are not set forth herein.

29. Matters contained in document entitled Construction and Easement Agreement by and between Sky Country Investment Co./East, LLC, a California limited liability company, Anthony P. Vernola, Trustee of The Anthony P. Vernola Trust U/D/T dated October 18, 2000, as amended, Anthony P. Vernola, Successor Trustee of The Pat and Mary Ann Vernola Trust - Marital Trust; APV Investment PA13, LLC, a California limited liability company; Bellatera Investments PA13, LLC, a California limited liability company; Boomer Investments PA13, LLC, a California limited liability company and Shellina Investments PA13, LLC, a California limited liability company recorded June 17, 2016 as Instrument No. 20160249915, of Official Records.

30. Matters contained in Map Book 151, Page 39, of Records of Survey.

31. Intentionally deleted.

32. Easement and rights incidental thereto for public utilities to Southern California Edison Company, a Corporation, as set forth in a document recorded February 27, 2019 as Instrument No. 2019-0066409, of Official Records.

32A. Easement and rights incidental thereto for pipe lines, ingress and egress and maintenance to Southern California Gas Company, as set forth in a document recorded January 21, 1958 in Book 2209 Page 463 of Official Records.

THE FOLLOWING MATTERS AFFECTS DIVISION III

33. Easement and rights incidental thereto for utilities to Southern Sierras Power Company, as set forth in a document recorded March 11, 1929 in Book 803, Page 111, of Deeds.

34. Easement and rights incidental thereto for right of way for pipe lines to Southern California Gas Company, an undivided three-quarters interest and Southern Counties Gas Company of California, an undivided one-quarter interest, as tenants in common, as set forth in a document recorded December 18, 1950 in Book 1228, Page 488, of Official Records.

35. Easement and rights incidental thereto for public road and drainage, including public utility and public services to The County of Riverside, as set forth in a document recorded September 17, 2008 as Instrument No. 2008-0507549, of Official Records.

36. Matters contained in document entitled "Declaration to Establish Precise Amount of Reimbursement Obligation" for Reimbursement of $2,516,182.00 by Redevelopment Agency of the County of Riverside, a political subdivision of the State of California recorded July 18, 2013 as Instrument No. 2013-0348391, of Official Records.

Reference is hereby made to said document for full particulars.

37. Matters contained in Map Book 151, Page 39, of Records of Survey.

38. Matters contained in document entitled Construction and Easement Agreement by and between Sky Country Investment Co./East, LLC, a California limited liability company, Anthony P. Vernola, Trustee of The Anthony P. Vernola Trust U/D/T dated October 18, 2000, as amended, Anthony P.

Vernola, Successor Trustee of The Pat and Mary Ann Vernola Trust - Marital Trust; APV Investment PA13, LLC, a California limited liability company; Bellatera Investments PA13, LLC, a California limited liability company; Boomer Investments PA13, LLC, a California limited liability company and Shellina Investments PA13, LLC, a California limited liability company recorded June 17, 2016 as Instrument No. 20160249915, of Official Records.

39. Easement and rights incidental thereto for permanent slope easement and temporary construction easement in Final Order of Condemnation Case No. 1801469, as set forth in a document recorded January 24, 2019 as Instrument No. 2019-0027140, of Official Records.

40. Easement granted to the State of California recorded September 19, 1986 as Instrument No. 1986-230117 of Official Records.

41. Unrecorded easement as shown on CalTrans Right of Way Map No. 77206-03 provided to the Title Company.

42. Rights or claims of parties in possession and easements or claims of easements not shown by the public records, conflicts in boundary lines, overlaps, shortage in area, encroachments, and any matters not of record which would be disclosed by an accurate survey or inspection of the Land.

    Matters contained therein affect: Division II - Parcel B

(End of Exceptions)

NOTES AND REQUIREMENTS

A. **THE FOLLOWING AFFECTS PARCEL A OF DIVISION I**

B. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $92,031.37
2nd Installment : $92,031.37
Parcel No. : 160-050-070
Code Area/Tracer No. : 028-029

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

C. Supplemental taxes for the fiscal year 2020-2021 issued pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the Revenue and Taxation Code of the State California:
1st Installment : $3,619.76
Status 1st : Paid
2nd Installment : $3,619.76
Status 2nd : Paid
Parcel No. : 160-050-070

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

D. Supplemental taxes for the fiscal year 2020-2021 issued pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the Revenue and Taxation Code of the State California:
1st Installment : $45,633.78
Status 1st : Paid
2nd Installment : $45,633.78
Status 2nd : Paid
Parcel No. : 160-050-070

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

E. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $8,887.62
2nd Installment : $8,887.62
Parcel No. : 160-050-063
Code Area/Tracer No. : 028-114

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

F. Supplemental taxes for the fiscal year 2020-2021 issued pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the Revenue and Taxation Code of the State California:
1st Installment : $17.82
Status 1st : Paid
2nd Installment : $17.82
Status 2nd : Paid
Parcel No. : 160-050-063

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

G. Supplemental taxes for the fiscal year 2020-2021 issued pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the Revenue and Taxation Code of the State California:
1st Installment : $184.05

Status 1st : Paid
2nd Installment : $184.05
Status 2nd : Paid
Parcel No. : 160-050-063

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

THE FOLLOWING AFFECTS PARCEL B OF DIVISION I

H. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $6,945.91
2nd Installment : $6,945.91
Parcel No. : 160-050-067
Code Area/Tracer No. : 028-029

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

I. Supplemental taxes for the fiscal year 2020-2021 issued pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the Revenue and Taxation Code of the State California:
1st Installment : $266.14
Status 1st : Paid
2nd Installment : $266.14
Status 2nd : Paid
Parcel No. : 160-050-067

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

J. Supplemental taxes for the fiscal year 2020-2021 issued pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the Revenue and Taxation Code of the State California:
1st Installment : $3,354.33
Status 1st : Paid
2nd Installment : $3,354.33
Status 2nd : Paid
Parcel No. : 160-050-067

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

K. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $7,443.43
2nd Installment : $7,443.43
Parcel No. : 160-050-072
Code Area/Tracer No. : 028-114

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

L. Supplemental taxes for the fiscal year 2020-2021 issued pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the Revenue and Taxation Code of the State California:
1st Installment : $170.21
Status 1st : Paid
2nd Installment : $170.21
Status 2nd : Paid
Parcel No. : 160-050-072

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

M. Supplemental taxes for the fiscal year 2020-2021 issued pursuant to the provisions of Chapter 3.5 (commencing with Section 75) of the Revenue and Taxation Code of the State California:
1st Installment : $2,130.79
Status 1st : Paid
2nd Installment : $2,130.79
Status 2nd : Paid
Parcel No. : 160-050-072

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

THE FOLLOWING AFFECTS PARCEL A OF DIVISION II

N. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $8,665.85
2nd Installment : $8,665.85
Parcel No. : 160-050-073
Code Area/Tracer No. : 028-114

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

O. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $7,023.06
2nd Installment : $7,023.06
Parcel No. : 160-050-068
Code Area/Tracer No. : 028-029

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

THE FOLLOWING AFFECTS PARCEL B OF DIVISION II

P. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $1,601.46
2nd Installment : $1,601.46
Parcel No. : 160-050-023
Code Area/Tracer No. : 028-114

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

Q. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $1,525.04
2nd Installment : $1,525.04
Parcel No. : 160-050-005
Code Area/Tracer No. : 028-114

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

R. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:
1st Installment : $418.52
2nd Installment : $418.52
Parcel No. : 160-050-021
Code Area/Tracer No. : 028-114

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

S. Intentionally deleted.

THE FOLLOWING AFFECTS DIVISION III

T. Property taxes for the fiscal year 2020 - 2021 shown below are paid. For proration purposes the amounts are:

1st Installment	: $4,828.22
2nd Installment	: $4,828.22
Parcel No.	: 160-050-074
Code Area/Tracer No.	: 028-029

Prior to recording, the final amount due for taxes must be confirmed with tax collector.

U. If title is to be insured in the trustee(s) of a trust or the trustee(s) act is to be insured, you must provide a full copy of the trust and any amendments thereto. In certain situations, you may be permitted to provide the STG Certification of Trust.

Please contact your title officer to discuss the above requirements.

The right is reserved to add requirements or additional items after completion of such review.

Trust: Anthony P. Vernola Trust

V. If title is to be insured in the trustee(s) of a trust or the trustee(s) act is to be insured, you must provide a full copy of the trust and any amendments thereto. In certain situations, you may be permitted to provide the STG Certification of Trust.

Please contact your title officer to discuss the above requirements.

The right is reserved to add requirements or additional items after completion of such review.

Trust: Chris McCabe Trust

W. In order to insure a conveyance, acquisition or encumbrance by the limited liability company named below, you must provide the following:

Limited liability company: Bellatera

a. A certified copy of the articles of organization (Form LLC-1), and any filed amendment (Form LLC-2) or restatement (Form LLC-10), if applicable.

b. A copy of the operating agreement and any amendments.

Additional requirements or items may be requested upon review of the required documents set forth above.

X. In order to insure a conveyance, acquisition or encumbrance by the limited liability company named below, you must provide the following:

Limited liability company: Boomer Investments

a. A certified copy of the articles of organization (Form LLC-1), and any filed amendment (Form LLC-2) or restatement (Form LLC-10), if applicable.

b. A copy of the operating agreement and any amendments.

Additional requirements or items may be requested upon review of the required documents set forth above.

Y. In order to insure a conveyance, acquisition or encumbrance by the limited liability company named below, you must provide the following:

Limited liability company: Shellina Investments

a. A certified copy of the articles of organization (Form LLC-1), and any filed amendment (Form LLC-2) or restatement (Form LLC-10), if applicable.

b. A copy of the operating agreement and any amendments.

Additional requirements or items may be requested upon review of the required documents set forth above.

Z. In order to insure a conveyance, acquisition or encumbrance by the limited liability company named below, you must provide the following:

Limited liability company: Sky Country Investment Co/East, LLC

a. A certified copy of the articles of organization (Form LLC-1), and any filed amendment (Form LLC-2) or restatement (Form LLC-10), if applicable.

b. A copy of the operating agreement and any amendments.

Additional requirements or items may be requested upon review of the required documents set forth above.

AA. If title is to be insured in the trustee(s) of a trust or the trustee(s) act is to be insured, you must provide a full copy of the trust and any amendments thereto. In certain situations, you may be permitted to provide the STG Certification of Trust.

Please contact your title officer to discuss the above requirements.

The right is reserved to add requirements or additional items after completion of such review.

Trust: The Anthony P. Vernola Trust under Trust Agreement dated October 18, 2000 and The Pat and Mary Ann Vernola Trust - Marital Trust

AB. Rights of parties in possession whether or not recorded in the public record.

AC. In order to insure, you must provide full copies of any unrecorded leases, together with all supplements, assignments and amendments. Additional requirements or items may be requested upon review of the required documents.

AD. If an inspection of the property is required and discloses any evidence of existing or recently completed work of improvement, either on-site or off-site, an exception for mechanic's liens will be included in the policy, unless all underwriting requirements for removal have been met and, prior to recording and closing, approval is issued by Stewart Title Guaranty Company.

AE. Please be advised that the search did not disclose any open deeds of trust. If you have knowledge of any outstanding obligations, please contact your title officer immediately for further review.

CALIFORNIA "GOOD FUNDS" LAW

California Insurance Code Section 12413.1 regulates the disbursement of escrow and sub-escrow funds by title companies. The law requires that funds be deposited in the title company escrow account and available for withdrawal prior to disbursement. Funds received by Stewart Title Guaranty Company Commercial Services (San Diego) via wire transfer may be disbursed upon receipt. Funds received via cashier's checks or teller checks drawn on a California Bank may be disbursed on the next business day after the day of deposit. If funds are received by any other means, recording and/or disbursement may be delayed, and you should contact your title or escrow officer. All escrow and sub-escrow funds received will be deposited with other escrow funds in one or more non-interest bearing escrow accounts in a financial institution selected by Stewart Title Guaranty Company Commercial Services (San Diego). Stewart Title Guaranty Company Commercial Services (San Diego) may receive certain direct or indirect benefits from the financial institution by reason of the deposit of such funds or the maintenance of such accounts with the financial institution, and Stewart Title Guaranty Company Commercial Services (San Diego) shall have no obligation to account to the depositing party in any manner for the value of, or to pay to such party, any benefit received by Stewart Title Guaranty Company Commercial Services (San Diego) . Such benefits shall be deemed additional compensation to Stewart Title Guaranty Company Commercial Services (San Diego) for its services in connection with the escrow or sub-escrow.

If any check submitted is dishonored upon presentation for payment, you are authorized to notify all principals and/or their respective agents of such nonpayment.

OWNER'S AFFIDAVIT AND INDEMNITY

Order Number: 21000480570
Address/Location: Multiple APNS, Riverside, CA 92505
APN:

In connection with the request of the Undersigned ("Affiant") for the preparation and issuance of insurance, Affiant makes the following statements and representations for the benefit of, and reliance by, title insurer STEWART TITLE GUARANTY COMPANY (hereafter referred to as "TITLE"):

1. Affiant owns and holds title to property described in Schedule A of the Preliminary Report or Commitment issued in connection with the above referenced Order Number (the "Property").

2. The Affiant's possession of the Property has been peaceful and undisturbed, and title thereto has never been disputed, questioned or rejected, nor has the issuance of title insurance ever been refused, except as follows: **(If none, please state "none")**

   _____

3. Other than the Affiant, there are no parties entitled to possession of the Property other than the following: **(If none, please state "none")**

   _____

4. There are no leases, licenses, options, rights of first refusal, or contracts to sell, affecting the Property, or any parties currently in possession, of the Property, except the following: **(If none, please state "none")**

   _____

5. All assessments, if any, by any association – owner, community or homeowner – are paid current or are not yet due and payable.

6. There are no pending contemplated repairs/improvements to the Property, except the following: **(If none, please state "none)**

   _____

7. There has been no construction, building materials, repairs, improvements, or remodeling performed, provided, furnished or delivered within the last 12 months, except as follows: **(If none, please state "none")**

   _____

8. Affiant is not aware of the existence of any of the following::
   a. Improvements encroaching into any easements or over any boundary lines of the Property.
   b. Adjoining property improvements encroaching onto the Property.
   c. Liens against the Property and/or judgments or tax liens against Affiant or any other property owner currently in title, except those described in the Preliminary Report or Commitment issued in connection with the above referenced Order Number.
   d. Outstanding claims or persons entitled to claims for mechanics' or materialman liens against the Property.
   e. Pending repairs/improvements to the adjacent street(s).
   f. Any pending litigation involving the Property, the Affiant or any other property owner currently in title.
   g. Recent improvements completed or being made to any common area(s) located within the subdivision in which the Property is located.
   h. Violations of any recorded covenants, conditions and/or restrictions imposed on the Property.
   i. Any pending assessments for Community Facility Districts.
   j. Any new, pending or existing obligation or loan including any improvements on the Property pursuant to the PACE or HERO program, or any other similar type program.
   k. Any use of the property for the production, sale, warehousing or transporting of fresh fruits, vegetables, livestock or poultry (e.g. supermarkets, restaurants, wineries, breweries and meat packing plants).

With regard to 8a.-8k, except as follows: **(If none, please state "none")**

9. No proceedings in bankruptcy or receivership have been instituted by or against the Affiant or any other property owner currently in title.

10. There are no unpaid utility type bills including but not limited to bills for water, sewer, hazardous waste, recycling, storm drain and/or rubbish and there are no liens related to such utilities from or on the Property, with the exception of the following: **(If none, please state "none")**

11. There are no financial obligations secured by trust deeds, mortgages, financing statements, vendor's liens, security agreements or otherwise, against the Property, except as set forth in the Preliminary Report, proforma and/or Commitment, and as set forth below: **(If none, please state "none")**

Creditor	Approximate Balance

12. There has been no harvesting or production of any oil, gas, geothermal materials or other minerals from or on the Property and there are no oil, gas, geothermal and/or mineral leases, licenses, options, rights of first refusal, and/or contracts to sell, affecting the mineral rights associated with the Property, or other parties currently in possession, of the mineral rights on the Property, except the following: **(If none, please state "none")**

13. Other than the Affiant, there are no other parties currently in possession of the Property, including but not limited to, any possessory interest associated with the harvesting of any oil, gas, geothermal materials or other minerals, except the following: **(If none, please state "none")**

This is a sworn affidavit and is made for the purpose of inducing TITLE to provide certain insurance coverage to a purchaser and/or lender, and the representations contained herein are material to such insurance coverage. The undersigned hereby indemnifies and holds TITLE harmless from any loss or damage, liability, costs, expenses and attorneys' fees which it may sustain under its policies of title insurance or commitments to the extent any representation contained herein is incorrect. The undersigned understands that TITLE may decide not to provide the requested title insurance despite the information and affirmations contained herein.

PLEASE READ, COMPLETE AND RESPOND TO ALL STATEMENTS CONTAINED IN THIS OWNER'S AFFIDAVIT AND INDEMNITY BEFORE SIGNING IN THE PRESENCE OF A NOTARY PUBLIC. THE NOTARY PUBLIC WILL EXECUTE THE ACKNOWLEDGMENT ON THE FOLLOWING PAGE. HOWEVER, IF YOU DO NOT UNDERSTAND OR HAVE ANY QUESTIONS ABOUT THIS AFFIDAVIT, YOU SHOULD SEEK THE ASSISTANCE OF YOUR INDEPENDENT FINANCIAL AND/OR LEGAL ADVISOR BEFORE SIGNING.

SKY COUNTRY INV CO EAST	MGP X VERNOLA

A notary public or other officer completing this certificate verifies only the identity of the individual who signed the document to which this certificate is attached and not the truthfulness, accuracy, or validity of that document.

State of California)
) ss.
County of _____)

Subscribed and sworn to (or affirmed) before me on this _____ day of _____, 20____, by _____, proved to me on the basis of satisfactory evidence to be the person(s) who appeared before me.

_____
Notary Signature

CERTIFICATION OF TRUST

(California Probate Code 18100.5)

IMPORTANT: THIS CERTIFICATION OF TRUST MUST BE FULLY COMPLETED

I/(We) * _____

(Name of Trustee(s))

Trustee(s) of the _____

(Name of Trust)

dated am providing the information set forth below at the request of Stewart Title Company, a Texas Corporation, and its agent, Stewart Title Guaranty Company - Commercial Services (hereinafter collectively called "Company")

WHEREAS, Company has been requested to issue a title insurance policy on the following described real property, more particularly described in Exhibit “A”, and
WHEREAS, Company has determined that the following information concerning the above named trust is necessary to ascertain whether it will be able to issue the requested policy of title insurance,
THEREFORE, acting in my capacity as trustee of the above named trust, I hereby certify and confirm to Company that the information set forth below is accurate and correct.

1. The _____
   (Name of Trust)
   is currently in existence and was created on _____
   (Date of Declaration of Trust)
2. The settlor(s) of the trust are: _____
3. The current trustee(s) of the trust is/are: * _____
4. The powers of the trustee(s) are: _____
5. The trust is a) revocable b) irrevocable (CIRCLE THE APPLICABLE CHOICE)
6. If the trust is revocable, the name of the person holding any power to revoke the trust: _____
7. If there are multiple trustees, the number of currently acting trustees' signature necessary to exercise the various powers of the trustee set forth above in Number 4 and the validity bind the trust. _____
8. The trust identification number (social security number or employer Tax ID): _____
9. The manner in which title to trust assets should be taken: _____

The undersigned trustee(s) hereby declare that the trust has not been revoked, modified, or amended in any manner which would cause the representations set forth herein above to be incorrect. This certification is being signed by all of the currently acting trustees and being executed in conformity with the provisions of California probate Code Section 18100.5, effective January 1, 1994 (Assembly Bill 1249, Chapter 530, Statutes of 1993).

The undersigned hereby certifies and declares the above to be true.

_____ _____

* *

A notary public or other officer completing this certificate verifies only the identity of the individual who signed the document to which this certificate is attached and not the truthfulness, accuracy, or validity of that document.

State of California)
)SS.
County of *)

On _____ before me, _____ , Notary Public, personally appeared _____ who proved to me on the basis of satisfactory evidence to be the person(s), whose name(s) is/are subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their authorized capacity(ies), and that by his/her/their signature(s) on the instrument the person(s) or the entity upon behalf of which the person(s) acted, executed the instrument.

I certify under PENALTY OF PERJURY under the laws of the State of California that the foregoing paragraph is true and correct.

WITNESS my hand and official seal.

Signature _____ (this area for official notarial seal)

Frank Green

Stewart Title Guaranty Company
Commercial Services (San Diego)
7676 Hazard Center Drive, Ste 1400
San Diego, CA 92108
(619) 398-8035 Phone
(619) 615-2389 Fax
fgreen@stewart.com

Date : September 01, 2021
Escrow Officer : Outside Closer
Escrow No. : 21000480570
Title Order No. : 21000480570
Property Address : Multiple APNS, Riverside, CA 92505

SELLER ACKNOWLEDGEMENT OF RECEIPT, UNDERSTANDING AND APPROVAL OF PRELIMINARY REPORT

The undersigned Seller(s) hereby acknowledge receipt of a copy of the Preliminary Report issued by Stewart Title Guaranty Company - Commercial Services under Order No. 21000480570, dated August 23, 2021 and hereby approves the legal description of subject property shown on Schedule A of the report.

Seller(s) Acknowledgement: Seller(s) herein warrant and confirm that, to Seller(s) knowledge, all Deeds of Trusts (e.g., mortgages, loans and lines of credit), liens, judgments and/or encumbrances affecting Seller(s) and subject property are reflected in the Preliminary Report. If not, Seller(s) will provide Escrow Holder with information to facilitate the pay-off and/or removal of any such items before or at the close of escrow.

The undersigned have received a copy of this acknowledgement as evidenced by the signature below.

Seller(s):

_____ _____
SKY COUNTRY INV CO EAST MGP X VERNOLA

_____
CHRIS MCCABE TRUST

Frank Green

Stewart Title Guaranty Company
Commercial Services (San Diego)
7676 Hazard Center Drive, Ste 1400
San Diego, CA 92108
(619) 398-8035 Phone
(619) 615-2389 Fax
fgreen@stewart.com

Date : September 01, 2021
Escrow Officer : Outside Closer
Escrow No. : 21000480570
Title Order No. : 21000480570
Property Address : Multiple APNS, Riverside, CA 92505

BUYER ACKNOWLEDGEMENT OF RECEIPT, UNDERSTANDING AND APPROVAL OF PRELIMINARY REPORT

The undersigned Buyer(s) hereby acknowledge receipt of a copy of the Preliminary Report issued by Stewart Title Guaranty Company - Commercial Services under Order No. 21000480570, dated August 23, 2021 and hereby approves the legal description of subject property shown on Schedule A of the report.

Buyer(s) Approval of Preliminary Report: Buyer(s) herein hereby approves Items * of Schedule B of the report to be included in the Policy of Title Insurance as exceptions when written. Further, Buyer(s) hereby acknowledge receipt and approval of the Covenants, Conditions and Restrictions, and any and all Schedule B exceptions detailed above, for example, easements, right-of-ways, and restrictions, if any.

The undersigned have received a copy of this acknowledgement as evidenced by the signature below.

Buyer(s):

EXHIBIT "A"

LEGAL DESCRIPTION

Order No.: 21000480570
Escrow No.: 21000480570

The land referred to herein is situated in the State of California, County of Riverside, City of Riverside and described as follows:

DIVISION I:

PARCEL A:

THAT PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4133 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, TOGETHER WITH THAT PORTION OF THE WEST HALF OF FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, AS SHOWN BY MAP ON FILE IN BOOK 9, PAGE 33 OF MAPS, RECORDS OF SAN BERNARDINO COUNTY, CALIFORNIA, LYING IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, SAID PORTION BEING DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (59.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63, INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE NORTHEAST CORNER OF PARCEL 4;

THENCE NORTH 00° 23’ 42" WEST ALONG SAID CENTERLINE OF PATS RANCH ROAD AND THE EASTERLY LINE OF SAID PARCEL 1, A DISTANCE OF 1213.18 FEET TO A POINT ON THE EASTERLY PROLONGATION OF THE WESTERLY BOUNDARY OF THAT CERTAIN 245.00 FOOT WIDE STRIP OF LAND DESCRIBED IN THE GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE TRUE POINT OF BEGINNING;

THENCE SOUTH 89° 39’ 53" WEST ALONG SAID EASTERLY PROLONGATION AND SAID WESTERLY BOUNDARY, A DISTANCE OF 1427.88 FEET TO THE NORTHEAST CORNER OF PARCEL 4446-1 OF SUPERIOR COURT OF STATE OF CALIFORNIA CASE NO. 169015 PER DOCUMENT RECORDED FEBRUARY 1, 1988 AS INSTRUMENT NO. 28620 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE BEGINNING OF A NON-TANGENT CURVE CONCAVE WESTERLY. HAVING A RADIUS OF 6000.00 FEET, THE RADIAL LINE TO SAID POINT BEARS SOUTH 89° 47’ 51” EAST;

THENCE NORTHERLY ALONG SAID CURVE, TO THE LEFT AND ALONG THE WESTERLY BOUNDARY OF SAID PARCEL 1, THROUGH A CENTRAL ANGLE OF 13° 05' 48" AN ARC DISTANCE OF 1371.41 FEET;

THENCE CONTINUING NORTHERLY ALONG SAID WESTERLY BOUNDARY OF PARCEL 1, NORTH 12° 54' 16” WEST, A DISTANCE OF 772.07 FEET TO AN ANGLE POINT ON SAID WESTERLY BOUNDARY;

THENCE CONTINUING NORTHERLY ALONG SAID WESTERLY BOUNDARY OF PARCEL 1 AND THE NORTHERLY AND EASTERLY BOUNDARY OF SAID PARCEL 1 THE FOLLOWING FOUR (4) COURSES AND DISTANCES:

1) NORTH 00° 42’ 22” WEST, A DISTANCE OF 221.33 FEET TO AN ANGLE POINT THEREON;

2) NORTH 65° 18’ 24” EAST. A DISTANCE OF 805.26 FEET TO AN ANGLE POINT THEREON;

3) NORTH 69° 10’ 41” EAST, A DISTANCE OF 753.21 FEET TO AN ANGLE POINT THEREON;

4) SOUTH 20° 49’ 19" EAST, A DISTANCE OF 487.81 FEET TO THE BEGINNING OF A TANGENT CURVE CONCAVE WESTERLY, HAVING A RADIUS OF 2000.00 FEET;

THENCE SOUTHEASTERLY ALONG SAID CURVE, TO THE RIGHT THROUGH A CENTRAL ANGLE OF 20° 25’ 37” AN ARC DISTANCE OF 713.03 FEET;

THENCE CONITINUING ALONG SAID EASTERLY BOUNDARY OF PARCEL 1, SOUTH 00° 23’ 42” EAST, A DISTANCE OF 1776.74 FEET TO THE TRUE POINT OF BEGINNING.

SAID LAND IS ALSO KNOWN AS PARCEL 2 AS SHOWN AND DESCRIBED IN THE NOTICE OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INSTRUMENT NO. 2016-154093 OF OFFICIAL CORDS.

APN(s): 160-050-063 AND 160-050-070

PARCEL B:

THAT PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4133 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620, OF OFFICIAL RECORDS, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026, OF OFFICIAL RECORDS, TOGETHER WITH A PORTION OF GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS AND ALSO A PORTION OF GRANT DEED RECORDED OCTOBER 5, 2007 AS INSTRUMENT NO. 2007-0623246 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, LYING IN FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, SAID PORTION BEING DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (59.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63, INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE SOUTHEAST CORNER OF SAID PARCEL 1;

THENCE SOUTH 89° 36’ 18" WEST ALONG THE SOUTHERLY BOUNDARY OF SAID PARCEL 1, A DISTANCE OF 389.30 FEET TO AN ANGLE POINT ON SAID SOUTHERLY BOUNDARY OF PARCEL 1, SAID ANGLE POINT BEING THE SOUTHERLY TERMINUS OF THAT CERTAIN DESCRIBED LINE HAVING A BEARING AND DISTANCE OF "NORTH 00° 08’ 18" WEST, 522.34 FEET" IN SAID PARCEL 1;

THENCE NORTH 00° 08' 18" WEST ALONG SAID DESCRIBED LINE AND THE NORTHERLY PROLONGATION OF SAID DESCRIBED LINE, A DISTANCE OF 830.72 FEET TO THE TRUE POINT OF BEGINNING;

THENCE SOUTH 89° 51’ 42” WEST, A DISTANCE OF 1047.38 FEET TO THE EASTERLY LINE OF PARCEL 4446-1 OF SUPERIOR COURT OF THE STATE OF CALIFORNIA CASE NO. 169015 PER DOCUMENT RECORDED FEBRUARY 1, 1988 AS INSTRUMENT NO. 28620 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA;

THENCE NORTH 00° 22’ 20” EAST ALONG SAID EASTERLY LINE OF PARCEL 4446-1, A DISTANCE

OF 362.01 FEET TO THE BEGINNING OF A TANGENT CURVE CONCAVE WESTERLY, HAVING A RADIUS OF 6000.00 FEET.

THENCE CONTINUING NORTHERLY ALONG SAID EASTERLY BOUNDARY OF PARCEL 4446-1 AND NORTHERLY ALONG SAID CURVE, TO THE LEFT, THROUGH A CENTRAL ANGLE OF 00° 10' 18", AN ARC DISTANCE OF 17.99 FEET TO THE NORTHEAST CORNER OF SAID PARCEL 4446-1;

THENCE NORTH 89° 39' 53" EAST ALONG THE WESTERLY BOUNDARY OF THAT CERTAIN 245.00 FOOT WIDE STRIP OF LAND DESCRIBED IN THE GRANT DEED RLCORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS AND THE EASTERLY PROLONGATION OF SAID 245.00 FOOT WIDE STRIP OF LAND, A DISTANCE OF 1427.88 FEET TO SAID CENTERLINE OF PATS RANCH ROAD;

THENCE SOUTH 00° 23' 42" EAST ALONG SAID CENTERLINE OF PATS RANCH ROAD, A DISTANCE OF 384.89 FEET;

THENCE SOUTH 89° 51' 42" WEST, A DISTANCE OF 385.58 FEET TO THE TRUE POINT OF BEGINNING.

SAID LAND IS ALSO KNOWN AS PARCEL 3 AS SHOWN AND DESCRIBED IN THE NOTICE OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INSTRUMENT NO. 2016-154093, OF OFFICIAL RECORDS.

APN(s): 160-050-067 AND 160-050-072

PARCEL C:

NON-EXCLUSIVE EASEMENTS FOR SURFACE DRAINAGE AND RIGHTS INCIDENTAL THERETO AND SUBJECT TO ALL THE TERMS, CONDITIONS AND PROVISIONS THEREIN CONTAINED AS PROVIDED FOR IN THAT CERTAIN INSTRUMENT ENTITLED "CONSTRUCTION AND EASEMENT AGREEMENT DATED JUNE 9, 2016 AND RECORDED JUNE 17, 2016 AS INSTRUMENT NO. 2016-249915, OF OFFICIAL RECORDS.

DIVISION II:

PARCEL A:

PARCEL 4 OF NOTICE OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INSTRUMENT NO. 2016-0154093 OFFICIAL RECORDS DESCRIBED AS FOLLOWS:

THAT PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4833 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620 OF OFFICIAL RECORDS, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026, TOGETHER WITH A PORTION OF GRANT DEED INSTRUMENT NO. 89577 RECORDED SEPTEMBER 17, 1968 AND ALSO A PORTION OF GRANT DEED INSTRUMENT NO. 2007-0623246 RECORDED OCTOBER 5, 2007 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA LYING WITHIN FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, AS SHOWN BY MAP ON FILE IN BOOK 9, OF MAPS, AT PAGE 33 THEREOF, RECORDS OF SAN BERNARDINO COUNTY, CALIFORNIA, LYING IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, SAID PORTION BEING DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (59.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63 INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID

POINT BEING THE SOUTHEAST COMER OF SAID PARCEL 1; THENCE SOUTH 89° 36’ 18” WEST ALONG THE SOUTHERLY BOUNDARY OF SAID PARCEL 1, A DISTANCE OF 389.30 FEET TO AN ANGLE POINT ON SAID SOUTHERLY BOUNDARY OF PARCEL 1, SAID ANGLE POINT BEING THE SOUTHERLY TERMINUS OF THAT CERTAIN DESCRIBED LINE HAVING A BEARING AND DISTANCE OF NORTH 00° 08’ 18” WEST, 522.34 FEET IN SAID PARCEL 1; THENCE NORTH 00° 08' 18” WEST ALONG SAID DESCRIBED LINE, A DISTANCE OF 522.34 FEET TO THE NORTHERLY TERMINUS OF SAID DESCRIBED LINE. SAID POINT BEING THE TRUE POINT OF BEGINNING:

THENCE NORTH 00° 08' 18" WEST ALONG THE NORTHERLY PROLONGATION OF SAID DESCRIBED LINE, A DISTANCE OF 308.39 FEET; THENCE LEAVING SAID NORTHERLY PROLONGATION, SOUTH 89° 51' 42" WEST, A DISTANCE OF 1047.38 FEET TO THE EASTERLY LINE OF PARCEL 4446-1 OF SUPERIOR COURT OF THE STATE OF CALIFORNIA CASE NO. 169015 PER DOCUMENT RECORDED FEBRUARY 1, 1988 AS INSTRUMENT NO. 28620 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA; THENCE SOUTH 00° 22’ 20” WEST ALONG SAID EASTERLY LINE OF PARCEL 4446-1, A DISTANCE OF 312.55 FEET TO A POINT ON THE SOUTHERLY LINE OF THE NORTHEAST QUARTER OF SAID FRACTIONAL SECTION 19, SAID POINT ALSO BEING THE SOUTHEAST CORNER OF SAID PARCEL 4446-1; THENCE NORTH 29° 38’ 06” EAST ALONG SAID SOUTHERLY LINE OF THE NORTHEAST QUARTER OF FRACTIONAL SECTION 19, A DISTANCE OF 397.09 FEET TO THE WESTERLY BOUNDARY OF THAT CERTAIN 245.00 FOOT WIDE STRIP OF LAND DESCRIBED IN SAID GRANT DEED RECORDED SEPTEMBER 17, 1968 AS INSTRUMENT NO. 89577 OF OFFICIAL RECORDS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA; THENCE SOUTH 00° 08' 05" EAST ALONG SAID WESTERLY BOUNDARY OF SAID 245.00 FOOT STRIP OF LAND, A DISTANCE OF 2638.39 FEET TO THE SOUTHERLY LINE OF SAID FRACTIONAL SECTION 19 THENCE NORTH 89° 35’ 53” EAST ALONG SAID SOUTHERLY LINE OF FRACTIONAL SECTION 19, A DISTANCE OF 245.00 FEET TO THE EASTERLY BOUNDARY OF SAID 245.00 FOOT STRIP OF LAND: THENCE NORTH 00°08’ 05” WEST ALONG SAID EASTERLY BOUNDARY OF THE 245.00 FOOT STRIP OF LAND, A DISTANCE OF 2638.23 FEET TO THE WESTERLY TERMINUS OF THAT CERTAIN COURSE DESCRIBED AS HAVING A BEARING AND DISTANCE OF "NORTH 89° 38' 06” EAST, 408.07 FEET" IN PARCEL 1 OF SAID LOT LINE ADJUSTMENT NO. 4233; THENCE NORTH 89° 38' EAST ALONG SAID DESCRIBED COURSE, A DISTANCE OF 408.07 FEET TO THE TRUE POINT OF BEGINNING.

APN(s): 160-050-73; 160-050-068

PARCEL B:

THE WEST HALF OF THE SOUTHEAST QUARTER OF SECTION 19, TOWNSHIP 2 SOUTH, RANGE 6 WEST, SAN BERNARDINO BASE AND MERIDIAN, AS SHOWN BY SECTIONIZED SURVEY OF THE JURUPA RANCHO, ON FILE IN BOOK 9 PAGE 33 OF MAPS, RECORDS OF SAN BERNARDINO COUNTY, CALIFORNIA

EXCEPTING THEREFROM THAT PORTION CONVEYED TO SOUTHERN CALIFORNIA EDISON COMPANY, A CORPORATION, BY DEED RECORDED DECEMBER 10, 1968 AS INSTRUMENT NO. 120541, OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA, DESCRIBED AS FOLLOWS:

A STRIP OF LAND 245 FEET WIDE, THE SIDE LINES OF SAID STRIP OF LAND 245 FEET WIDE, BEING 50 FEET EASTERLY. NORTHERLY AND EASTERLY AND 195 FEET WESTERLY, SOUTHERLY AND WESTERLY, MEASURED AT RIGHT ANGLES RESPECTIVELY, FROM THE SURVEYED REFERENCE LINE WHICH IS DESCRIBED AS FOLLOWS

BEGINNING AT A POINT IN THE NORTHERLY LINE OF FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 6 WEST, SAN BERNARDINO BASE AND MERIDIAN, SAID POINT BEING NORTH 89 DEGREES 41’ 03” EAST, 1,295.11 FEET, MEASURED ALONG LAST MENTIONED NORTHERLY LINE FROM A FOUND 3 INCH IRON PIPE AND NAIL SET AT THE NORTHWEST CORNER OF SAID FRACTIONAL SECTION 19; THENCE SOUTH 00 DEGREES 15’ 02” EAST, 1,784.91 FEET, MORE OR

LESS, TO A POINT PARALLEL WITH AND 195 FEET NORTHERLY, MEASURED AT RIGHT ANGLES, FROM THE NORTHERLY LINE OF THE 126.039 ACRE PARCEL, AS SHOWN BY MAP ON FILE IN BOOK 7 PAGE 43 OF RECORDS OF SURVEY, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA; THENCE NORTH 89 DEGREES 25' 29" EAST, 2,293.60 FEET, MEASURED ALONG SAID PARALLEL LINE; THENCE SOUTH 00 DEGREES 22' 29" EAST, 3,525.41 FEET, MORE OR LESS, TO A POINT IN THE SOUTHERLY LINE OF FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 6 WEST, OF THE JURUPA RANCHO, SAID LAST MENTIONED POINT BEING SOUTH 89 DEGREES 21' 58" WEST, 1777.03 FEET, MEASURED ALONG LAST MENTIONED SOUTHERLY LINE FROM A FOUND 2 INCH BY 2 INCH STAKE WITH TACK SET AT THE SOUTHEAST CORNER OF SAID FRACTIONAL SECTION 19;

ALSO EXCEPTING THEREFROM THAT PORTION DESCRIBED IN DEEDS TO THE STATE OF CALIFORNIA. RECORDED SEPTEMBER 19, 1986 AS INSTRUMENT NOS. 230116 AND 230117 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA;

ALSO EXCEPTING THEREFROM THE SOUTH 20 FEET AND THE WEST 20 FEET OF THE SOUTHWEST QUARTER OF THE SOUTHWEST QUARTER OF THE SOUTHEAST QUARTER OF SAID SECTION 19, AS SET OUT IN DEED RECORDED NOVEMBER 22, 1976 AS INSTRUMENT NO. 179279 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA;

ALSO EXCEPTING THEREFROM THAT PORTION AS DESCRIBED IN THAT CERTAIN RIGHT OF WAY DEED RECORDED JUNE 25, 1935 IN BOOK 237, PAGE 40 OF OFFICIAL RECORDS OF RIVERSIDE COUNTY, CALIFORNIA.

APN: 160-050-005; 160-050-021 AND 160-050-023

DIVISION III:

ALL OF PARCEL 4 AND A PORTION OF PARCEL 1 OF LOT LINE ADJUSTMENT NO. 4833 PER DOCUMENT RECORDED JUNE 6, 2005 AS INSTRUMENT NO. 2005-0478620 OF OFFICIAL RECORDS, RECORDS OF RIVERSIDE COUNTY, CALIFORNIA AND RE-RECORDED APRIL 25, 2006 AS INSTRUMENT NO. 2006-0296026 OF OFFICIAL RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, IN THE CITY OF JURUPA VALLEY, COUNTY OF RIVERSIDE, STATE OF CALIFORNIA, LYING IN FRACTIONAL SECTION 19, TOWNSHIP 2 SOUTH, RANGE 4 WEST, SAN BERNARDINO MERIDIAN, SAID PORTION BEING DESCRIBED AS FOLLOWS:

BEGINNING AT A POINT ON THE CENTERLINE OF PATS RANCH ROAD (39.00 FEET IN HALF WIDTH EASTERLY) AS SHOWN ON TRACT NO. 33428-1 ON FILE IN BOOK 441, PAGES 56 THROUGH 63 INCLUSIVE OF MAPS, RECORDS OF SAID RIVERSIDE COUNTY, CALIFORNIA, SAID POINT BEING THE NORTHEAST CORNER OF SAID PARCEL 4;

THENCE SOUTH 00° 23' 42" EAST ALONG SAID CENTERLINE OF PATS RANCH ROAD AND THE EASTERLY LINE OF SAID PARCEL 4, A DISTANCE OF 2075.56 FEET TO THE SOUTHEAST CORNER OF SAID PARCEL 4; THENCE SOUTH 89° 35' 53" WEST ALONG THE SOUTHERLY LINE OF SAID PARCEL 4, A DISTANCE OF 398.60 FEET TO THE SOUTHWEST CORNER OF SAID PARCEL 4;

THENCE NORTH 00° 01' 18" WEST ALONG THE WESTERLY LINE OF SAID PARCEL 4, THE SOUTHERLY BOUNDARY OF SAID PARCEL 1 DESCRIBED AS HAVING A HEARING AND DISTANCE OF NORTH 00° 08' 18" WEST, 522.34 FEET AND THE NORTHERLY PROLONGATION OF SAID DESCRIBED LINE, A DISTANCE OF 2906.35 FEET;

THENCE NORTH 89° 51' 42" EAST, A DISTANCE OF 385.58 FEET TO SAID CENTERLINE OF PATS RANCH ROAD AND SAID EASTERLY LINE OF SAID PARCEL 1;

THENCE SOUTH 00° 23' 42" EAST ALONG SAID CENTERLINE OF PATS RANCH ROAD AND SAID

EASTERLY LINE OF SAID PARCEL 1, A DISTANCE OF 828.98 FEET TO THE POINT OF BEGINNING.

SAID LAND BEING PARCEL 1 OF LOT LINE ADJUSTMENT NO. LLA 15-004, RECORDED APRIL 19, 2016 AS INTRUMENT NO. 2016-0154093 OFFICIAL RECORDS.

APN: 150-050-074

Division I - Parcel A - APN: 160-050-063 and 160-050-070
Division I - Parcel B - APN: 160-050-067 and 160-050-072

Division II - Parcel A - APN: 160-050-073 and 160-050-068
Division II - Parcel B - APN: 160-050-005; 160-050-021 and 160-050-023

Division III: APN: 160-050-074

(End of Legal Description)

AFFILIATED BUSINESS ARRANGEMENT DISCLOSURE STATEMENT

Date: September 01, 2021

Escrow No.: 21000480570

Property: Multiple APNS, Riverside, CA 92505

From: Stewart Title Guaranty Company - Commercial Services

This is to give you notice that Stewart Title Guaranty Company - Commercial Services ("Stewart Title") has a business relationship with Stewart Solutions, LLC, DBA – Stewart Specialty Insurance Services, LLC ("Stewart Insurance"). Stewart Information Services Corporation owns 100% of Stewart Insurance and Stewart Title of California. Because of this relationship, this referral may provide Stewart Title a financial or other benefit.

Set forth below is the estimated charge or range of charges for the settlement services listed. You are NOT required to use the listed provider(s) as a condition for purchase, sale, or refinance of the subject Property. THERE ARE FREQUENTLY OTHER SETTLEMENT SERVICE PROVIDERS AVAILABLE WITH SIMILAR SERVICES. YOU ARE FREE TO SHOP AROUND TO DETERMINE THAT YOU ARE RECEIVING THE BEST SERVICES AND THE BEST RATE FOR THESE SERVICES.

Stewart Insurance Settlement Service	***Charge or range of charges***
Hazard Insurance	$400.00 to $6,500.00
Home Warranty	$255.00 to $ 780.00
Natural Hazard Disclosure Report	$ 42.50 to $ 149.50

CALIFORNIA LAND TITLE ASSOCIATION

STANDARD COVERAGE POLICY – 1990
EXCLUSIONS FROM COVERAGE

The following matters are expressly excluded from the coverage of this policy and the Company will not pay loss or damage, costs, attorneys' fees or expenses which arise by reason of:

1. (a) Any law, ordinance or governmental regulation (including but not limited to building or zoning laws, ordinances, or regulations) restricting, regulating, prohibiting or relating (i) the occupancy, use, or enjoyment of the land; (ii) the character, dimensions or location of any improvement now or hereafter erected on the land; (iii) a separation in ownership or a change in the dimensions or area of the land or any parcel of which the land is or was a part; or (iv) environmental protection, or the effect of any violation of these laws, ordinances or governmental regulations, except to the extent that a notice of the enforcement thereof or a notice of a defect, lien, or encumbrance resulting from a violation or alleged violation affecting the land has been recorded in the public records at Date of Policy.
   (b) Any governmental police power not excluded by (a) above, except to the extent that a notice of the exercise thereof or notice of a defect, lien or encumbrance resulting from a violation or alleged violation affecting the land has been recorded in the public records at Date of Policy.

2. Rights of eminent domain unless notice of the exercise thereof has been recorded in the public records at Date of Policy, but not excluding from coverage any taking which has occurred prior to Date of Policy which would be binding on the rights of a purchaser for value without knowledge.

3. Defects, liens, encumbrances, adverse claims or other matters:
   (a) whether or not recorded in the public records at Date of Policy, but created, suffered, assumed or agreed to by the insured claimant;
   (b) not known to the Company, not recorded in the public records at Date of Policy, but known to the insured claimant and not disclosed in writing to the Company by the insured claimant prior to the date the insured claimant became an insured under this policy;
   (c) resulting in no loss or damage to the insured claimant;
   (d) attaching or created subsequent to Date of Policy; or
   (e) resulting in loss or damage which would not have been sustained if the insured claimant had paid value for the insured mortgage or for the estate or interest insured by this policy.

4. Unenforceability of the lien of the insured mortgage because of the inability or failure of the insured at Date of Policy, or the inability or failure of any subsequent owner of the indebtedness, to comply with the applicable doing business laws of the state in which the land is situated.

5. Invalidity or unenforceability of the lien of the insured mortgage, or claim thereof, which arises out of the transaction evidenced by the insured mortgage and is based upon usury or any consumer credit protection or truth in lending law.

6. Any claim, which arises out of the transaction vesting in the insured the estate of interest insured by this policy or the transaction creating the interest of the insured lender, by reason of the operation of federal bankruptcy, state insolvency or similar creditors' rights laws.

EXCEPTIONS FROM COVERAGE - SCHEDULE B, PART I

This policy does not insure against loss or damage (and the Company will not pay costs, attorneys' fees or expenses) which arise by reason of:

1. Taxes or assessments which are not shown as existing liens by the records of any taxing authority that levies taxes or assessments on real property or by the public records.

   Proceedings by a public agency which may result in taxes or assessments, or notices of such proceedings, whether or not shown by the records of such agency or by the public records.

2. Any facts, rights, interests, or claims which are not shown by the public records but which could be ascertained by an inspection of the land or which may be asserted by persons in possession thereof.

3. Easements, liens or encumbrances, or claims thereof, not shown by the public records.

4. Discrepancies, conflicts in boundary lines, shortage in area, encroachments, or any other facts which a correct survey would disclose, and which are not shown by the public records

5. (a) Unpatented mining claims; (b) reservations or exceptions in patents or in Acts authorizing the issuance thereof; (c) water rights, claims or title to water, whether or not the matters excepted under (a), (b) or (c) are shown by the public records.

6. Any lien or right to a lien for services, labor or material unless such lien is shown by the Public Records at Date of Policy

CLTA/ALTA HOMEOWNER'S POLICY OF TITLE INSURANCE (12-02-13)
EXCLUSIONS

In addition to the Exceptions in Schedule B, You are not insured against loss, costs, attorneys' fees, and expenses resulting from:

1. Governmental police power, and the existence or violation of those portions of any law or government regulation concerning:
   a. building;
   b. zoning;
   c. land use;
   d. improvements on the Land;
   e. land division;
   f. environmental protection.

This Exclusion does not limit the coverage described in Covered Risk 8.a., 14, 15, 16, 18, 19, 20, 23 or 27.

2. The failure of Your existing structures, or any part of them, to be constructed in accordance with applicable building codes. This Exclusion does not limit the coverage described in Covered Risk 14 or 15.
3. The right to take the Land by condemning it. This Exclusion does not limit the coverage described in Covered Risk 17.

4. Risks:
   a. that are created, allowed, or agreed to by You, whether or not they appear in the Public Records;
   b. that are Known to You at the Policy Date, but not to Us, unless they are recorded in the Public Records at the Policy Date;
   c. that result in no loss to You; or
   d. that first occur after the Policy Date - this does not limit the coverage described in Covered Risk 7, 8.e., 25, 26, 27 or 28.

5. Failure to pay value for Your Title.

6. Lack of a right:
   a. to any land outside the area specifically described and referred to in paragraph 3 of Schedule A; and
   b. in streets, alleys, or waterways that touch the Land.

This Exclusion does not limit the coverage described in Covered Risk 11 or 21.

7. The transfer of the Title to You is invalid as a preferential transfer or as a fraudulent transfer or conveyance under federal bankruptcy, state insolvency, or similar creditors' rights laws.

8. Contamination, explosion, fire, flooding, vibration, fracturing, earthquake, or subsidence.

9. Negligence by a person or an Entity exercising a right to extract or develop minerals, water, or any other substances.

LIMITATIONS ON COVERED RISKS

Your insurance for the following Covered Risks is limited on the Owner's Coverage Statement as follows:
* For Covered Risk 16, 18, 19, and 21 Your Deductible Amount and Our Maximum Dollar Limit of Liability shown in Schedule A.
The deductible amounts and maximum dollar limits shown on Schedule A are as follows:

	Your Deductible Amount	Our Maximum Dollar Limit of Liability
Covered Risk 16:	1% of Policy Amount or $2,500.00 (whichever is less)	$10,000.00
Covered Risk 18:	1% of Policy Amount or $5,000.00 (whichever is less)	$25,000.00
Covered Risk 19:	1% of Policy Amount or $5,000.00 (whichever is less)	$25,000.00
Covered Risk 21:	1% of Policy Amount or $2,500.00 (whichever is less)	$5,000.00

2006 ALTA LOAN POLICY (06-17-06)
EXCLUSIONS FROM COVERAGE

The following matters are expressly excluded from the coverage of this policy, and the Company will not pay loss or damage, costs, attorneys' fees, or expenses that arise by reason of:

1. (a) Any law, ordinance, permit, or governmental regulation (including those relating to building and zoning) restricting, regulating, prohibiting, or relating to
   (i) the occupancy, use, or enjoyment of the Land;
   (ii) the character, dimensions, or location of any improvement erected on the Land;
   (iii) the subdivision of land; or
   (iv) environmental protection;
   or the effect of any violation of these laws, ordinances, or governmental regulations. This Exclusion 1(a) does not modify or limit the coverage provided under Covered Risk 5.
   (b) Any governmental police power. This Exclusion 1(b) does not modify or limit the coverage provided under Covered Risk 6.

2. Rights of eminent domain. This Exclusion does not modify or limit the coverage provided under Covered Risk 7 or 8.

3. Defects, liens, encumbrances, adverse claims, or other matters
   (a) created, suffered, assumed, or agreed to by the Insured Claimant;
   (b) not Known to the Company, not recorded in the Public Records at Date of Policy, but Known to the Insured Claimant and not disclosed in writing to the Company by the Insured Claimant prior to the date the Insured Claimant became an Insured under this policy;
   (c) resulting in no loss or damage to the Insured Claimant;
   (d) attaching or created subsequent to Date of Policy (however, this does not modify or limit the coverage provided under Covered Risk 11, 13, or 14); or
   (e) resulting in loss or damage that would not have been sustained if the Insured Claimant had paid value for the Insured Mortgage.

4. Unenforceability of the lien of the Insured Mortgage because of the inability or failure of an Insured to comply with applicable doing-business laws of the state where the Land is situated.

5. Invalidity or unenforceability in whole or in part of the lien of the Insured Mortgage that arises out of the transaction evidenced by the Insured Mortgage and is based upon usury or any consumer credit protection or truth-in-lending law.

6. Any claim, by reason of the operation of federal bankruptcy, state insolvency, or similar creditors' rights laws, that the transaction creating the lien of the Insured Mortgage, is
   (a) a fraudulent conveyance or fraudulent transfer, or
   (b) a preferential transfer for any reason not stated in Covered Risk 13(b) of this policy.

7. Any lien on the Title for real estate taxes or assessments imposed by governmental authority and created or attaching between Date of Policy and the date of recording of the Insured Mortgage in the Public Records. This Exclusion does not modify or limit the coverage provided under Covered Risk 11(b).

The above policy form may be issued to afford either Standard Coverage or Extended Coverage. In addition to the above Exclusions from Coverage, the Exceptions from Coverage in a Standard Coverage policy will also include the following Exceptions from Coverage:

EXCEPTIONS FROM COVERAGE

Except as provided in Schedule B - Part II, this policy does not insure against loss or damage, and the Company will not pay costs, attorneys' fees or expenses, that arise by reason of:

PART I

1. (a) taxes or assessments which are not shown as existing liens by the records of any taxing authority that levies taxes or assessments on real property or by the public records.
   (b) proceedings by a public agency which may result in taxes or assessments, or notices of such proceedings, whether or not shown by the records of such agency or by the public records.

2. Any facts, rights, interests, or claims that are not shown by the Public Records but that could be ascertained by an inspection of the Land or that may be asserted by persons in possession of the Land.

3. Easements, liens or encumbrances, or claims thereof, which are not shown by the Public Records.

4. Any encroachment, encumbrance, violation, variation, or adverse circumstance affecting the Title that would be disclosed by an accurate and complete land survey of the Land and not shown by the Public Records.

5. (a) unpatented mining claims; (b) reservations or exceptions in patents or in Acts authorizing the issuance thereof; (c) water rights, claims or title to water, whether or not the matters excepted under (a), (b) or (c) are shown by the public records.

6. Any lien or right to a lien for services, labor or material unless such lien is shown by the Public Records at Date of Policy.

PART II

In addition to the matters set forth in Part I of this Schedule, the Title is subject to the following matters, and the Company insures against loss or damage sustained in the event that they are not subordinate to the lien of the Insured Mortgage:

2006 ALTA OWNER'S POLICY (06-17-06)
EXCLUSIONS FROM COVERAGE

The following matters are expressly excluded from the coverage of this policy, and the Company will not pay loss or damage, costs, attorneys' fees, or expenses that arise by reason of:

1. (a) Any law, ordinance, permit, or governmental regulation (including those relating to building and zoning) restricting, regulating, prohibiting, or relating to
   (i) the occupancy, use, or enjoyment of the Land;
   (ii) the character, dimensions, or location of any improvement erected on the Land;
   (iii) the subdivision of land; or
   (iv) environmental protection;
   or the effect of any violation of these laws, ordinances, or governmental regulations. This Exclusion 1(a) does not modify or limit the coverage provided under Covered Risk 5.
   (b) Any governmental police power. This Exclusion 1(b) does not modify or limit the coverage provided under Covered Risk 6.

2. Rights of eminent domain. This Exclusion does not modify or limit the coverage provided under Covered Risk 7 or 8.

3. Defects, liens, encumbrances, adverse claims, or other matters
   (a) created, suffered, assumed, or agreed to by the Insured Claimant;
   (b) not Known to the Company, not recorded in the Public Records at Date of Policy, but Known to the Insured Claimant and not disclosed in writing to the Company by the Insured Claimant prior to the date the Insured Claimant became an Insured under this policy;
   (c) resulting in no loss or damage to the Insured Claimant;
   (d) attaching or created subsequent to Date of Policy (however, this does not modify or limit the coverage provided under Covered Risk 9 and 10); or
   (e) resulting in loss or damage that would not have been sustained if the Insured Claimant had paid value for the Title.

4. Any claim, by reason of the operation of federal bankruptcy, state insolvency, or similar creditors' rights laws, that the transaction vesting the Title as shown in Schedule A, is
   (a) a fraudulent conveyance or fraudulent transfer; or
   (b) a preferential transfer for any reason not stated in Covered Risk 9 of this policy.

5. Any lien on the Title for real estate taxes or assessments imposed by governmental authority and created or attaching between Date of Policy and the date of recording of the deed or other instrument of transfer in the Public Records that vests Title as shown in Schedule A.

The above policy form may be issued to afford either Standard Coverage or Extended Coverage. In addition to the above Exclusions from Coverage, the Exceptions from Coverage in a Standard Coverage policy will also include the following Exceptions from Coverage:

EXCEPTIONS FROM COVERAGE

This policy does not insure against loss or damage (and the company will not pay costs, attorneys' fees or expenses) which arise by reason of:

1. Taxes or assessments which are not shown as existing liens by the records of any taxing authority that levies taxes or assessments on real property or by the public records.
   Proceedings by a public agency which may result in taxes or assessments, or notices of such proceedings, whether or not shown by the records of such agency or by the public records.

2. Any facts, rights, interests or claims which are not shown by the public records but which could be ascertained by an inspection of the land or by making inquiry of persons in possession thereof.

3. Easements, liens or encumbrances, or claims thereof, which are not shown by the public records.

4. Any encroachment, encumbrance, violation, variation, or adverse circumstance affecting the Title that would be disclosed by an accurate and complete land survey of the Land and that are not shown by the Public Records.

5. (a) unpatented mining claims; (b) reservations or exceptions in patents or in Acts authorizing the issuance thereof; (c) water rights, claims or title to water, whether or not the matters excepted under (a), (b) or (c) are shown by the public records.

6. Any lien or right to a lien for services, labor or material unless such lien is shown by the Public Records at Date of Policy..

ALTA EXPANDED COVERAGE RESIDENTIAL LOAN POLICY - ASSESSMENTS PRIORITY (04-02-15)
EXCLUSIONS FROM COVERAGE

The following matters are expressly excluded from the coverage of this policy and the Company will not pay loss or damage, costs, attorneys fees or expenses which arise by reason of:

1. a. Any law, ordinance or governmental regulation (including but not limited to building and zoning laws, ordinances, or regulations) restricting, regulating, prohibiting or relating to
   (i) the occupancy, use, or enjoyment of the Land;
   (ii) the character, dimensions or location of any improvement now or hereafter erected on the Land;
   (iii) the subdivision of land; or
   (iv) environmental protection

   or the effect of any violation of these laws, ordinances, or governmental regulations. This Exclusion 1(a) does not modify or limit the coverage provided under Covered Risk 5, 6, 13(c), 13(d), 14 or 16.
   b. Any governmental police power. This Exclusion 1(b) does not modify or limit the coverage provided under Covered Risk 5, 6, 13(c), 13(d), 14 or 16.

2. Rights of eminent domain. This Exclusion does not modify or limit the coverage provided under Covered Risk 7 or 8.

3. Defects, liens, encumbrances, adverse claims or other matters:

   (a) created, suffered, assumed or agreed to by the Insured Claimant;
   (b) not Known to the Company, not recorded in the Public Records at Date of Policy, but Known to the Insured Claimant and not disclosed in writing to the Company by the Insured Claimant prior to the date the Insured Claimant became an Insured under this policy;
   (c) resulting In no loss or damage to the Insured Claimant;
   (d) attaching or created subsequent to Date of Policy (however, this does not modify or limit the coverage provided under Covered Risk 11, 16, 17, 18, 19, 20, 21, 22, 23, 24, 27 or 28); or
   (e) resulting in loss or damage which would not have been sustained if the Insured Claimant had paid value for the Insured Mortgage.

4. Unenforceability of the lien of the Insured Mortgage because of the inability or failure of an Insured to comply with applicable doing-business laws of the state where the Land is situated.

5. Invalidity or unenforceability in whole or in part of the lien of the Insured Mortgage that arises out of the transaction evidenced by the Insured Mortgage and is based upon usury, or any consumer credit protection or truth-in-lending law. This Exclusion does not modify or limit the coverage provided in Covered Risk 26.

6. Any claim of invalidity, unenforceability or lack of priority of the lien of the Insured Mortgage as to Advances or modifications made after the Insured has Knowledge that the vestee shown in Schedule A is no longer the owner of the estate or interest covered by this policy. This Exclusion does not modify or limit the coverage provided in Covered Risk 11.

7. Any lien on the Title for real estate taxes or assessments imposed by governmental authority and created or attaching subsequent to Date of Policy. This Exclusion does not modify or limit the coverage provided in Covered Risk 11(b) or 25.

8. The failure of the residential structure, or any portion of it, to have been constructed before, on or after Date of Policy in accordance with applicable building codes. This Exclusion does not modify or limit the coverage provided in Covered Risk 5 or 6.

9. Any claim, by reason of the operation of federal bankruptcy, state insolvency, or similar creditors' rights laws, that the transaction creating the lien of the Insured Mortgage, is

   (a) a fraudulent conveyance or fraudulent transfer, or
   (b) a preferential transfer for any reason not stated in Covered Risk 27(b) of this policy.

10 Contamination, explosion, fire, flooding, vibration, fracturing, earthquake, or subsidence.

11. Negligence by a person or an Entity exercising a right to extract or develop minerals, water, or any other substances.

STG Privacy Notice
Stewart Title Companies

WHAT DO THE STEWART TITLE COMPANIES DO WITH YOUR PERSONAL INFORMATION?

Federal and applicable state law and regulations give consumers the right to limit some but not all sharing. Federal and applicable state law regulations also require us to tell you how we collect, share, and protect your personal information. Please read this notice carefully to understand how we use your personal information. This privacy notice is distributed on behalf of the Stewart Title Guaranty Company and its title affiliates (the Stewart Title Companies), pursuant to Title V of the Gramm-Leach-Bliley Act (GLBA).

The types of personal information we collect and share depend on the product or service that you have sought through us. This information can include social security numbers and driver's license number.

All financial companies, such as the Stewart Title Companies, need to share customers' personal information to run their everyday business—to process transactions and maintain customer accounts. In the section below, we list the reasons that we can share customers' personal information; the reasons that we choose to share; and whether you can limit this sharing.

Reasons we can share your personal information.	Do we share	Can you limit this sharing?
For our everyday business purposes— to process your transactions and maintain your account. This may include running the business and managing customer accounts, such as processing transactions, mailing, and auditing services, and responding to court orders and legal investigations.	Yes	No
For our marketing purposes— to offer our products and services to you.	Yes	No
For joint marketing with other financial companies	No	We don't share
For our affiliates' everyday business purposes— information about your transactions and experiences. Affiliates are companies related by common ownership or control. They can be financial and non-financial companies. *Our affiliates may include companies with a Stewart name; financial companies, such as Stewart Title Company*	Yes	No
For our affiliates' everyday business purposes— information about your creditworthiness.	No	We don't share
For our affiliates to market to you — For your convenience, Stewart has developed a means for you to opt out from its affiliates marketing even though such mechanism is not legally required.	Yes	Yes, send your first and last name, the email address used in your transaction, your Stewart file number and the Stewart office location that is handling your transaction by email to optout@stewart.com or fax to 1-800-335-9591.
For non-affiliates to market to you. Non-affiliates are companies not related by common ownership or control. They can be financial and non-financial companies.	No	We don't share

We may disclose your personal information to our affiliates or to non-affiliates as permitted by law. If you request a transaction with a non-affiliate, such as a third party insurance company, we will disclose your personal information to that non-affiliate. [We do not control their subsequent use of information, and suggest you refer to their privacy notices.]

SHARING PRACTICES

How often do the Stewart Title Companies notify me about their practices?	We must notify you about our sharing practices when you request a transaction.
How do the Stewart Title Companies protect my personal information?	To protect your personal information from unauthorized access and use, we use security measures that comply with federal law. These measures include computer, file, and building safeguards.
How do the Stewart Title Companies collect my personal information?	We collect your personal information, for example, when you ▪ request insurance-related services ▪ provide such information to us We also collect your personal information from others, such as the real estate agent or lender involved in your transaction, credit reporting agencies, affiliates or other companies.
What sharing can I limit?	Although federal and state law give you the right to limit sharing (e.g., opt out) in certain instances, we do not share your personal information in those instances.

Contact us: If you have any questions about this privacy notice, please contact us at: **Stewart Title Guaranty Company, 1360 Post Oak Blvd., Ste. 100, Privacy Officer, Houston, Texas 77056**

Privacy Notice for California Residents

Pursuant to the California Consumer Privacy Act of 2018 ("CCPA"), Stewart Information Services Corporation and its subsidiary companies (collectively, "Stewart") are providing this **Privacy Notice for California Residents** ("CCPA Notice"). This CCPA Notice supplements the information contained in Stewart's existing privacy notice and applies solely to all visitors, users and others who reside in the State of California or are considered California Residents ("consumers" or "you"). Terms used but not defined shall have the meaning ascribed to them in the CCPA.

Information Stewart Collects

Stewart collects information that identifies, relates to, describes, references, is capable of being associated with, or could reasonably be linked, directly or indirectly, with a particular consumer, household, or device. Most of the information that Stewart collects in the course of its regular business is already protected pursuant to the Gramm-Leach-Bliley Act (GLBA). Additionally, much of this information comes from government records or other information already in the public domain. Personal information under the CCPA does not include:

- Publicly available information from government records.
- Deidentified or aggregated consumer information.
- Certain personal information protected by other sector-specific federal or California laws, including but not limited to the Fair Credit Reporting Act (FCRA), GLBA and California Financial Information Privacy Act (FIPA).

Specifically, Stewart has collected the following categories of personal information from consumers within the last twelve (12) months:

Category	**Examples**	**Collected?**
A. Identifiers.	A real name, alias, postal address, unique personal identifier, online identifier, Internet Protocol address, email address, account name, Social Security number, driver's license number, passport number, or other similar identifiers.	YES
B. Personal information categories listed in the California Customer Records statute (Cal. Civ. Code § 1798.80(e)).	A name, signature, Social Security number, physical characteristics or description, address, telephone number, passport number, driver's license or state identification card number, insurance policy number, education, employment, employment history, bank account number, credit card number, debit card number, or any other financial information, medical information, or health insurance information. Some personal information included in this category may overlap with other categories.	YES
C. Protected classification characteristics under California or federal law.	Age (40 years or older), race, color, ancestry, national origin, citizenship, religion or creed, marital status, medical condition, physical or mental disability, sex (including gender, gender identity, gender expression, pregnancy or childbirth and related medical conditions), sexual orientation, veteran or military status, genetic information (including familial genetic information).	YES
D. Commercial information.	Records of personal property, products or services purchased, obtained, or considered, or other purchasing or consuming histories or tendencies.	YES
E. Biometric information.	Genetic, physiological, behavioral, and biological characteristics, or activity patterns used to extract a template or other identifier or identifying information, such as, fingerprints, faceprints, and voiceprints, iris or retina scans, keystroke, gait, or other physical patterns, and sleep, health, or exercise data.	YES
F. Internet or other similar network activity.	Browsing history, search history, information on a consumer's interaction with a website, application, or advertisement.	YES
G. Geolocation data.	Physical location or movements.	YES
H. Sensory data.	Audio, electronic, visual, thermal, olfactory, or similar information.	YES
I. Professional or employment-related information.	Current or past job history or performance evaluations.	YES
J. Non-public education information (per the Family Educational Rights and Privacy Act (20 U.S.C. Section 1232g, 34 C.F.R. Part 99)).	Education records directly related to a student maintained by an educational institution or party acting on its behalf, such as grades, transcripts, class lists, student schedules, student identification codes, student financial information, or student disciplinary records.	YES
K. Inferences drawn from other personal information.	Profile reflecting a person's preferences, characteristics, psychological trends, predispositions, behavior, attitudes, intelligence, abilities, and aptitudes.	YES

Stewart obtains the categories of personal information listed above from the following categories of sources:

- Directly and indirectly from customers, their designees or their agents (For example, realtors, lenders, attorneys, etc.)
- Directly and indirectly from activity on Stewart's website or other applications.
- From third-parties that interact with Stewart in connection with the services we provide.

Use of Personal Information

Stewart may use or disclose the personal information we collect for one or more of the following purposes:

- To fulfill or meet the reason for which the information is provided.
- To provide, support, personalize, and develop our website, products, and services.
- To create, maintain, customize, and secure your account with Stewart.
- To process your requests, purchases, transactions, and payments and prevent transactional fraud.
- To prevent and/or process claims.
- To assist third party vendors/service providers who complete transactions or perform services on Stewart's behalf.
- As necessary or appropriate to protect the rights, property or safety of Stewart, our customers or others.
- To provide you with support and to respond to your inquiries, including to investigate and address your concerns and monitor and improve our responses.
- To personalize your website experience and to deliver content and product and service offerings relevant to your interests, including targeted offers and ads through our website, third-party sites, and via email or text message (with your consent, where required by law).
- To help maintain the safety, security, and integrity of our website, products and services, databases and other technology assets, and business.
- To respond to law enforcement or regulator requests as required by applicable law, court order, or governmental regulations.
- Auditing for compliance with federal and state laws, rules and regulations.
- Performing services including maintaining or servicing accounts, providing customer service, processing or fulfilling orders and transactions, verifying customer information, processing payments, providing advertising or marketing services or other similar services.
- To evaluate or conduct a merger, divestiture, restructuring, reorganization, dissolution, or other sale or transfer of some or all of our assets, whether as a going concern or as part of bankruptcy, liquidation, or similar proceeding, in which personal information held by us is among the assets transferred.

Stewart will not collect additional categories of personal information or use the personal information we collected for materially different, unrelated, or incompatible purposes without providing you notice.

Disclosure of Personal Information to Affiliated Companies and Nonaffiliated Third Parties

Stewart does not sell your personal information to nonaffiliated third parties. Stewart may share your information with those you have designated as your agent in the course of your transaction (for example, a realtor or a lender). Stewart may disclose your personal information to a third party for a business purpose. Typically, when we disclose personal information for a business purpose, we enter a contract that describes the purpose and requires the recipient to both keep that personal information confidential and not use it for any purpose except performing the contract.

We share your personal information with the following categories of third parties:

- Service providers and vendors (For example, search companies, mobile notaries, and companies providing credit/debit card processing, billing, shipping, repair, customer service, auditing, marketing, etc.)
- Affiliated Companies
- Litigation parties and attorneys, as required by law.
- Financial rating organizations, rating bureaus and trade associations.
- Federal and State Regulators, law enforcement and other government entities

In the preceding twelve (12) months, Stewart has disclosed the following categories of personal information for a business purpose:

Category A: Identifiers
Category B: California Customer Records personal information categories
Category C: Protected classification characteristics under California or federal law
Category D: Commercial Information
Category E: Biometric Information
Category F: Internet or other similar network activity
Category G: Geolocation data
Category H: Sensory data
Category I: Professional or employment-related information
Category J: Non-public education information
Category K: Inferences

Consumer Rights and Choices

The CCPA provides consumers (California residents) with specific rights regarding their personal information. This section describes your CCPA rights and explains how to exercise those rights.

Access to Specific Information and Data Portability Rights

You have the right to request that Stewart disclose certain information to you about our collection and use of your personal information over the past 12 months. Once we receive and confirm your verifiable consumer request, Stewart will disclose to you:

- The categories of personal information Stewart collected about you.
- The categories of sources for the personal information Stewart collected about you.
- Stewart's business or commercial purpose for collecting that personal information.
- The categories of third parties with whom Stewart shares that personal information.
- The specific pieces of personal information Stewart collected about you (also called a data portability request).
- If Stewart disclosed your personal data for a business purpose, a listing identifying the personal information categories that each category of recipient obtained.

Deletion Request Rights

You have the right to request that Stewart delete any of your personal information we collected from you and retained, subject to certain exceptions. Once we receive and confirm your verifiable consumer request, Stewart will delete (and direct our service providers to delete) your personal information from our records, unless an exception applies.

Stewart may deny your deletion request if retaining the information is necessary for us or our service providers to:

1. Complete the transaction for which we collected the personal information, provide a good or service that you requested, take actions reasonably anticipated within the context of our ongoing business relationship with you, or otherwise perform our contract with you
2. Detect security incidents, protect against malicious, deceptive, fraudulent, or illegal activity, or prosecute those responsible for such activities.
3. Debug products to identify and repair errors that impair existing intended functionality.
4. Exercise free speech, ensure the right of another consumer to exercise their free speech rights, or exercise another right provided for by law.
5. Comply with the California Electronic Communications Privacy Act (Cal. Penal Code § 1546 *seq.*).
6. Engage in public or peer-reviewed scientific, historical, or statistical research in the public interest that adheres to all other applicable ethics and privacy laws, when the information's deletion may likely render impossible or seriously impair the research's achievement, if you previously provided informed consent.
7. Enable solely internal uses that are reasonably aligned with consumer expectations based on your relationship with us.
8. Comply with a legal obligation.
9. Make other internal and lawful uses of that information that are compatible with the context in which you provided it.

Exercising Access, Data Portability, and Deletion Rights

To exercise the access, data portability, and deletion rights described above, please submit a verifiable consumer request to us either:

- Calling us Toll Free at 1-866-571-9270
- Emailing us at Privacyrequest@stewart.com
- Visiting http://stewart.com/ccpa

Only you, or someone legally authorized to act on your behalf, may make a verifiable consumer request related to your personal information. You may also make a verifiable consumer request on behalf of your minor child.

To designate an authorized agent, please contact Stewart through one of the methods mentioned above.

You may only make a verifiable consumer request for access or data portability twice within a 12-month period. The verifiable consumer request must:

- Provide sufficient information that allows us to reasonably verify you are the person about whom we collected personal information or an authorized representative.
- Describe your request with sufficient detail that allows us to properly understand, evaluate, and respond to it.

Stewart cannot respond to your request or provide you with personal information if we cannot verify your identity or authority to make the request and confirm the personal information relates to you.

Making a verifiable consumer request does not require you to create an account with Stewart.

Response Timing and Format

We endeavor to respond to a verifiable consumer request within forty-five (45) days of its receipt. If we require more time (up to an additional 45 days), we will inform you of the reason and extension period in writing.

A written response will be delivered by mail or electronically, at your option.

Any disclosures we provide will only cover the 12-month period preceding the verifiable consumer request's receipt. The response we provide will also explain the reasons we cannot comply with a request, if applicable. For data portability requests, we will select a format to provide your personal information that is readily useable and should allow you to transmit the information from one entity to another entity without hindrance.

Stewart does not charge a fee to process or respond to your verifiable consumer request unless it is excessive, repetitive, or manifestly unfounded. If we determine that the request warrants a fee, we will tell you why we made that decision and provide you with a cost estimate before completing your request.

Non-Discrimination

Stewart will not discriminate against you for exercising any of your CCPA rights. Unless permitted by the CCPA, we will not:

- Deny you goods or services.
- Charge you a different prices or rates for goods or services, including through granting discounts or other benefits, or imposing penalties.
- Provide you a different level or quality of goods or services.
- Suggest that you may receive a different price or rate for goods or services or a different level or quality of goods or services.

Changes to Our Privacy Notice

Stewart reserves the right to amend this privacy notice at our discretion and at any time. When we make changes to this privacy notice, we will post the updated notice on Stewart's website and update the notice's effective date. **Your continued use of Stewart's website following the posting of changes constitutes your acceptance of such changes.**

Contact Information

If you have questions or comments about this notice, the ways in which Stewart collects and uses your information described here, your choices and rights regarding such use, or wish to exercise your rights under California law, please do not hesitate to contact us at:

Phone: Toll Free at 1-866-571-9270

Website: http://stewart.com/ccpa

Email: Privacyrequest@stewart.com

Postal Address: Stewart Information Services Corporation
Attn: Mary Thomas, Deputy Chief Compliance Officer
1360 Post Oak Blvd., Ste. 100, MC #14-1
Houston, TX 77056


Riverside County Parcel Report

APN(s):160050070,160050063,160050072,160050067,160050073,160050023,160050005,160050068,160050074

DISCLAIMER

Maps, permit information and data are to be used for reference purposes only. Map features are approximate, and are not necessarily accurate to surveying or engineering standards. The County of Riverside makes no warranty or guarantee as to the content (the source is often third party), accuracy, timeliness, or completeness of any of the data provided, and assumes no legal responsibility for the information contained on this map. Any use of this product with respect to accuracy and precision shall be the sole responsibility of the user.

MAPS/IMAGES



PARCEL

APN	160-050-005-9, 160-050-023-5, 160-050-063-1, 160-050-067-5, 160-050-068-6, 160-050-070-7, 160-050-072-9, 160-050-073-0, 160-050-074-1	Supervisorial District	KAREN SPIEGEL, DISTRICT 2
Previous APN	160050005 158020001, 158020006, 158020007, 158020008, more 160050023 160050009, 160050011, 160050017, 160050018, more 160050063 160050027, 160050031, 160050048 160050067 160050027, 160050031, 160050048 160050068 160050027, 160050031, 160050048 160050070 160040039, 160050066 160050072 160050061, 160050064 160050073 160050062, 160050065 160050074 160050050, 160050069	Township/Range	T2SR6W SEC 18 PSEC
Owner Name	NOT AVAILABLE ONLINE	Elevation	689 ft
Address		Thomas Bros. Map Page/Grid	PAGE: 683, GRID: E3 PAGE: 683, GRID: E4 PAGE: 683, GRID: F3

PAGE: 683, GRID: F4
PAGE: 683, GRID: F5

Mailing Address	160050005 P O BOX 1295 CORONA CA 92878 160050023 P O BOX 1295 CORONA CA 92878 160050063 PO BOX 217 UPLAND CA 91784 160050067 PO BOX 217 UPLAND CA 91784 160050068 P O BOX 1295 CORONA CA 92878 160050070 PO BOX 217 UPLAND CA 91784 160050072 PO BOX 217 UPLAND CA 91784 160050073 PO BOX 1295 CORONA CA 92878 160050074 PO BOX 2459 MISSION VIEJO CA 92690	Indian Tribal Land	NOT IN A TRIBAL LAND
Legal Description	160050005 Recorded Book/Page: / Subdivsion Name: Lot/Parcel: Block: Tract Number: 160050023 Recorded Book/Page: / Subdivsion Name: Lot/Parcel: Block:	City Boundary	JURUPA VALLEY

Tract Number:

160050063
Recorded Book/Page: /
Subdivsion Name:
Lot/Parcel:
Block:
Tract Number:

160050067
Recorded Book/Page: /
Subdivsion Name:
Lot/Parcel:
Block:
Tract Number:

160050068
Recorded Book/Page: /
Subdivsion Name:
Lot/Parcel:
Block:
Tract Number:

160050070
Recorded Book/Page: /
Subdivsion Name:
Lot/Parcel:
Block:
Tract Number:

160050072
Recorded Book/Page: /
Subdivsion Name:
Lot/Parcel:
Block:
Tract Number:

160050073
Recorded Book/Page: /
Subdivsion Name:
Lot/Parcel:
Block:
Tract Number:

160050074
Recorded Book/Page: /
Subdivsion Name:
Lot/Parcel:
Block:
Tract Number:

		City Spheres of influence	NOT IN A CITY SPHERE
Lot Size	160050005 Recorded lot size is 18.36 acres 160050023 Recorded lot size is 19.28 acres 160050063 Recorded lot size is 3.58 acres 160050067 Recorded lot size is 6.52 acres	March Joint Powers Authority	NOT IN THE JURISDICTION OF THE MARCH JOINT POWERS AUTHORITY

160050068
Recorded lot size is 2.89 acres

160050070
Recorded lot size is 87.04 acres

160050072
Recorded lot size is 5.29 acres

160050073
Recorded lot size is 19.42 acres

160050074
Recorded lot size is 22.26 acres

Property Characteristcs	160050005 Year Constructed: Baths: Bedrooms: Construction Type: Garage Type: Property Area (sq ft): Roof Type: Stories: Pool: NO Central Cool: NO Central Heat: NO 160050023 Year Constructed: Baths: Bedrooms: Construction Type: Garage Type: Property Area (sq ft): Roof Type: Stories: Pool: NO Central Cool: NO Central Heat: NO 160050063 Year Constructed: Baths: Bedrooms: Construction Type: Garage Type: Property Area (sq ft): Roof Type: Stories: Pool: NO Central Cool: NO Central Heat: NO 160050067 Year Constructed: Baths: Bedrooms: Construction Type: Garage Type: Property Area (sq ft): Roof Type: Stories: Pool: NO Central Cool: NO	County Service Area	NOT IN A COUNTY SERVICE AREA

Central Heat: NO

160050068
Year Constructed:
Baths:
Bedrooms:
Construction Type:
Garage Type:
Property Area (sq ft):
Roof Type:
Stories:
Pool: NO
Central Cool: NO
Central Heat: NO

160050070
Year Constructed: 1945
Baths:
Bedrooms:
Construction Type: Wood or Light Steel (D)
Garage Type:
Property Area (sq ft): 735
Roof Type:
Stories: 1
Pool: NO
Central Cool: NO
Central Heat: NO

160050070
Year Constructed: 1990
Baths:
Bedrooms:
Construction Type: Wood or Light Steel (D)
Garage Type:
Property Area (sq ft): 1560
Roof Type:
Stories:
Pool: NO
Central Cool: NO
Central Heat: NO

160050070
Year Constructed: 1990
Baths:
Bedrooms:
Construction Type: Wood or Light Steel (D)
Garage Type:
Property Area (sq ft): 966
Roof Type:
Stories: 1
Pool: NO
Central Cool: NO
Central Heat: NO

160050072
Year Constructed:
Baths:
Bedrooms:
Construction Type:
Garage Type:
Property Area (sq ft):
Roof Type:
Stories:
Pool: NO
Central Cool: NO
Central Heat: NO

160050073

Year Constructed:
Baths:
Bedrooms:
Construction Type:
Garage Type:
Property Area (sq ft):
Roof Type:
Stories:
Pool: NO
Central Cool: NO
Central Heat: NO

Annexation Date	2009-32-2 07/22/2010	LAFCO Case	2009-32-2 07/22/2010
Proposals	N/A		

PLANNING more...

Specific Plans	I-15 CORRIDOR #266	Historic Preservation Districts	NOT IN A HISTORIC PRESERVATION DISTRICT
Land Use Designations	CITY	Agricultural Preserve	NOT IN AN AGRICULTRAL PRESERVE
General Plan Policy Overlays	N/A		
Area Plan (RCIP)	Eastvale	Airport Influence Areas	NOT IN AN AIRPORT INFLUENCE AREA
General Plan Policy Areas	NOT IN A GENERAL PLAN POLICY AREA	Airport Compatibility Zones	NOT IN AN AIRPORT COMPATIBLITY AREA
Zoning Classifications (ORD. 348)	CHECK WITH THE CITY FOR MORE INFORMATION	Zoning Districts and Zoning Areas	PRADO-MIRA LOMA DIST
Zoning Overlays	EASTVALE	Community Advisory Councils	NOT IN A COMMUNITY ADVISORY COUNCIL

Residential Permit Stats

N/A

ENVIRONMENTAL more...

CVMSHCP (Coachella Valley Multi-Species Habitat Conservation Plan) Plan Area	NOT IN A COACHELLA VALLEY MSHCP FEE AREA	WRMSHCP (Western Riverside County Multi-Species Habitat Conservation Plan) Cell Group	NOT IN A CELL GROUP
CVMSHCP (Coachella Valley Multi-Species Habitat Conservation Plan) Conservation Area	NOT COACHELLA VALLEY CONSERVATION AREA	WRMSHCP Cell Number	NOT IN A CELL NUMBER
CVMSHCP Fluvial Sand Transport Special Provision Areas	NOT IN A FLUVIAL SAND TRANSPORT SPECIAL PROVISION AREA	HANS/ERP (Habitat Acquisition and Negotiation Strategy/Expedited Review Process)	NOT IN A HANS/ERP PROJECT
WRMSHCP (Western Riverside County Multi-Species Habitat Conservation Plan) Plan Area	WESTERN RIVERSIDE COUNTY	Vegetation (2005)	AGRICULTURE MAPPING UNIT URBAN OR DEVELOPMENT MAPPING UNIT

Fire

Fire Hazard Classification (Ord. 787)	NOT IN A FIRE HAZARD ZONE	Fire Responsibility Area	NOT IN A FIRE RESPONSIBILITY AREA

DEVELOPMENT FEES

CVMSHCP (Coachella Valley Multi-Species Habitat	NOT IN A COACHELLA	RBBD (Road & Bridge Benefit	MIRA LOMA ZONE E

Conservation Plan) Fee Area (Ord 875)	VALLEY MSHCP FEE AREA	District)	
WRMSHCP (Western Riverside County Multi-Species Habitat Conservation Plan) Fee Area (Ord. 810)	WESTERN RIVERSIDE COUNTY	DIF (Development Impact Fee Area Ord. 659)	EASTVALE, AREA 5
Western TUMF (Transportation Uniform Mitigation Fee Ord. 824)	IN OR PARTIALLY WITHIN A TUMF FEE AREA	SKR Fee Area (Stephenâ€™s Kagaroo Rat Ord. 663.10)	NOT IN THE SKR FEE AREA
Eastern TUMF (Transportation Uniform Mitigation Fee Ord. 673)	NOT IN THE EASTERN TUMF FEE AREA	DA (Development Agreements)	NOT IN A DEVELOPMENT AGREEMENT

TRANSPORTATION more...

Circulation Element Ultimate Right-of-Way	IN OR PARTIALLY WITHIN A CIRCULATION ELEMENT RIGHT-OF-WAY	Road Book Page	7 14C 14E
		Transportation Agreements	NOT IN A TRANS AGREEMENT
		CETAP (Community and Environmental Transportation Acceptability Process) Corridors	NOT IN A CETAP CORRIDOR

HYDROLOGY

Flood Plan Review	*MAYBE REQUIRED, CONTACT RIVERSIDE COUNTY FLOOD CONTROL TO VERIFY	Watershed	SANTA ANA RIVER
Water District	WESTERN MUNICIPAL WATER DISTRICT		
Flood Control District	RIVERSIDE COUNTY FLOOD CONTROL DISTRICT		

GEOLOGIC

Fault Zone	NOT IN A FAULT ZONE	Paleontological Sensitivity	HIGH SENSITIVITY (HIGH A): BASED ON GEOLOGIC FORMATIONS OR MAPPABLE ROCK UNITS THAT ARE ROCKS THAT CONTAIN FOSSILIZED BODY ELEMENTS, AND TRACE FOSSILS SUCH AS TRACKS, NESTS AND EGGS. THESE FOSSILS OCCUR ON OR BELOW THE SURFACE
Faults	NOT IN A FAULT LINE		
Liquefaction Potential	HIGH		
Subsidence	SUSCEPTIBLE		

MISCELLANEOUS

School District	JURUPA UNIFIED
Communities	MIRA LOMA
Lighting (Ord. 655)	NOT IN A PALOMAR OBSERVATORY ZONE
2010 Census Tract	406.07
Farmland	OTHER LANDS PRIME FARMLAND UNIQUE FARMLAND URBAN-BUILT UP LAND
Special Notes	NO SPECIAL NOTES
Tax Rate Areas	028029 - CITY OF JURUPA VALLEY 028029 - CO FREE LIBRARY 028029 - CO STRUCTURE FIRE PROTECTION 028029 - CSA 152 028029 - FLOOD CONTROL ADMIN 028029 - FLOOD CONTROL ZN 1 028029 - FLOOD CONTROL ZN 1 DS 028029 - GENERAL 028029 - GENERAL PURPOSE 028029 - INLAND EMPIRE JT(33,36)RES

028029 - JURUPA AREA REC & PK
028029 - JURUPA COMMUNITY SERVICE IMP 2
028029 - JURUPA COMMUNITY SERVICE IMP 3
028029 - JURUPA COMMUNITY SERVICES
028029 - JURUPA COMMUNITY SRV IMP 2 DS
028029 - JURUPA UNIFIED SCHOOL
028029 - JURUPA UNION JOINT-COMP UNIFIED
028029 - MWD WEST 1302999
028029 - NW MOSQUITO & VECTOR CNTL DIST
028029 - RIV CO REGIONAL PARK & OPEN SP
028029 - RIVERSIDE CITY COMMUNITY COLLEGE
028029 - RIVERSIDE CO OFC OF EDUCATION
028029 - SO. CALIF,JT(19,30,33,36,37,56)
028029 - WESTERN MUNICIPAL WATER
028114 - CITY OF JURUPA VALLEY
028114 - CO FREE LIBRARY
028114 - CO STRUCTURE FIRE PROTECTION
028114 - CSA 152
028114 - ERAF RDV
028114 - FLOOD CONTROL ADMIN
028114 - FLOOD CONTROL ZN 1
028114 - FLOOD CONTROL ZN 1 DS
028114 - GENERAL
028114 - GENERAL PURPOSE
028114 - INLAND EMPIRE JT(33,36)RES
028114 - JURUPA AREA REC & PK
028114 - JURUPA COMMUNITY SERVICE IMP 2
028114 - JURUPA COMMUNITY SERVICE IMP 3
028114 - JURUPA COMMUNITY SERVICES
028114 - JURUPA COMMUNITY SRV IMP 2 DS
028114 - JURUPA UNIFIED SCHOOL
028114 - JURUPA UNION JOINT-COMP UNIFIED
028114 - MWD WEST 1302999
028114 - NW MOSQUITO & VECTOR CNTL DIST
028114 - RDV JURUPA VALLEY AMND AB1290
028114 - RIV CO REGIONAL PARK & OPEN SP
028114 - RIVERSIDE CITY COMMUNITY COLLEGE
028114 - RIVERSIDE CO OFC OF EDUCATION
028114 - SO. CALIF,JT(19,30,33,36,37,56)
028114 - WESTERN MUNICIPAL WATER

Department of Enviromental Health Permits

Septic Permits

Record Id	Application Date	Plan Check Approved Date	Final Inspection Date	Approved Date
N/A	N/A	N/A	N/A	N/A

Well Water Permits

Record Id	PE	Permit Paid Date	Permit Approved Date	Well Finaled Date
WP0012078			02 Apr 2004	
WP0012422			12 Apr 2004	

PLUS PERMITS & CASES

Administrative Cases

Case	Case Description	Status
MT101024	T2SR6W SEC 19 (PP14738S1/BNR100072)	PAID
MT101025	T2SR6W SEC 19 (PP14738S1/BNR100072)	PAID
MT990736	PP15795	PAID

Building and Safety Cases

Case	Case Description	Status
026878	AGRIC REG / W ELEC (SEED PROCESSING) OK TO PC SEE FRANK T.	FINAL
028338	SUPPLEMENTAL TO PER#58555	FINAL
099025	AGRICULTURAL MACHINERY STORAGE BLDG PUBGR B-1 V-N 6000 105000	FINAL
103254	ADD CANOPY,60X50 TO STORAGE SHED PRCH PN V-N 3000 40470	FINAL
109246	INSTALL NEW GAS LINES - 450 SQ FT	FINAL
111218	RELOCATE PVT RANCH OFFICE BLDG MOVING PERMIT	FINAL
111720	RELOCAT PVT RANCH OFFICE BLDG OFF B-2 V-N 512 16998	FINAL
112510	AGRIC MOBILEHOME SITE PREP	FINAL
113151	MOBILEHOME INSTALLATION	FINAL
114018	AG-MH SITE PREP/MH #2	EXPIRED
115087	SEED PROCESSING STORAGE BLDG-NON-COMMERCIAL AGRIC M-3 V-N 14400 151200	FINAL
118754	MH INSTALLATION	FINAL
118760	SITE PREP - COMMERCIAL COACH - SEED OFFICE	EXPIRED
138878	TEMP USE PERM SERVICE	FINAL
264107	ELEC TO IRRIG PUMP	FINAL
374717	SPECIAL INSPECTION - SAFETY	FINAL
410433	60' MONOPOLE	FINAL
411988	JURUPA LAW ENFORCEMENT (RSA #45)	ISSUED
413890	UNMANNED CELLULAR MONOPOLE	FINAL
415897	JURUPA LAW ENFORCEMENT (RSA #45)	ISSUED
415965	COMMERCIAL COACH INSTALL PF UNMANNED	FINAL
415966	PERM FOUNDATION TO COMMERCIAL COACH	FINAL
416775	OVERTIME INSPECTION RE: 415966	FINAL
417155	SUPP PLANCHECK - ELECTRICAL	ISSUED
BEL000829	ELEC - NEXTEL CELLULAR SITE (REF BXX002177/000829)	FINAL
BEL010181	TWO FOOT DISH ON EXISTING MONOPOLE	FINAL
BEL050044	SERV UPGRADE TRANSFER SWITCH TO CELL SITE	FINAL
BEL071083	REPLACE DAMAGED METER PEDESTAL	FINAL
BHR000159	FOUNDATION ONLY FOR NEXTEL	FINAL
BHR110711	REQUEST FOR RECORDS	PAID
BNR000113	EQUIPMENT SHELTER ONLY	FINAL
BNR060186	4 CABINETS/6 ANTENNAS TO EXISTING POLE	EXPIRED
BNR080027	4 CABINETS/6 ANTENNAS TO EXIST POLE (EXP BNR060186	EXPIRED
BNR100072	4 CABINETS 6 ANTEANNAS TO EXIST POLE (BNR080027EXP CREATED PER SUZANNE GILLETTE	FINAL
BXX002177	CO-LOCATE 75' MONOPOLE W/ANTENNA (REF BNR000113)	FINAL
BXX982789	55' CELLULAR ANTENNA/6 CABINETS	FINAL
BZ298090	150 AMP SERVICE CHANGE	FINAL

Code Cases

Case	Case Description	Status
N/A	N/A	N/A

Fire Cases

Case	Case Description	Status
FHAZ0200137		Closed - Verified Non-Billable
FHAZ1005854		Closed - Verified Non-Billable
FHAZ1005855		Closed - Verified Non-Billable
FHAZ1005856		Closed - Verified Non-Billable
FHAZ1005858		Closed - Verified Non-Billable
FHAZ1005860		Closed - Verified Non-Billable
FHAZ1104384		Closed - Verified Non-Billable
FHAZ1104385		Closed - Verified Non-Billable
FPFST2000063	FPFST2000063- 20-JURV-1559 AT&T 845219	PLN CK APPROVED
FPWCS1900012	19-JURV-18351 CELL TOWER MOD	PLN CK APPROVED

Planning Cases

Case	Case Description	Status
AG00781	DIMINISHMENT NO 11 TO MIRA LOMA AG PRES 1 VIA NONR	APPROVED
CZ05619	CHANGE OF ZONE FROM W-1, A-2-10 AND R-T TO SP. CHANGE OF ZONE ON 701.3 ACRES FROM A-2-10, AND A-2 -20 TO C-P-S, C-O, R-1, R-2, R-3, I-P & R-5 EA 34371, EIR 340, SP 266, CGPA 242 SP 266, CZ 5619, CGPA 242, EIR 340, EA 34371	APPROVED
CZ06328	CHANGE OF ZONE TO IMPLEMENT SUB. CONF. 1 TO SP 266	APPROVED
EA34371	EA FOR CZ05619 GPA00242 SP00266 ENVIRONMENTAL ASSESSMENT FOR CZ 05619, GPA00242, S P 00266 EA 34371, EIR 340, SP 266, CGPA 242, CZ 5619	DENIED
EA36951	EA FOR GPA 416 ENVIRONMENTAL ASSESSMENT FOR GPA00416 EA 36951	APPROVED
EA37545	EA FOR PERSONAL COMMUNICATIONS SYSTEM	WITHDRAWN
EA37874	EA FOR PP16344 COMMUNICATIONS SITE	WITHDRAWN
GPA00242	AMEND OPEN SPACE & CONSERVATION MAP TO SP EA 34371, EIR 340, SP 266, CZ 5619AMEND THE OPEN SPACE AND CONSERVATION MAP	APPROVED
GPA00416	REALIGHMENT OF WINEVILLE ROAD EA 36951REALIGNMENTOF WINEVILLE ROAD	APPROVED
LLA04833	LL ADJ TO MATCH PLANNING AREA FOR SP 266	APPROVED
PAR00127	MICO RELAY FACILITY	APPROVED
PP14639	WIRELESS COMMUNICATION FACILITY ON A 400 SQ FT LEA SED AREA INSTALL 60' MONOPOLE/ANTENNA ARRAY W/ 2 EQUIP. CAB INETS FOR WIRELESS COMMUNICATIONS FACILITY. N/A. SP 266, CZ 5619.	APPROVED
PP14639S1	INCREASE HEIGHT TO 75 FT AND ADD ANTENNAS	APPROVED
PP14639S2	LOCATE A TEMPORARY GENERATOR W/IN THE EXISTING LEASE AREA FOR A PERIOD OF ONE YEAR.	APPROVED

PP14639S3	REQUEST TO PERMANATELY LOCATE A TEMPORARY GENERATO	APPROVED
PP14738	59' HIGH MONOPOLE/ANTENNA & EQUIPMENT BUILDING. THE PROPOSED EQUIPMENT BUILDING WILL BE UNMANNED A ND IS ESTIMATED TO BE 336 SQ. FT.	APPROVED
PP14738S1	COLLOCATE 6 ANTENNAS TO EXST POLE/EQUIPMENT CABINE TS FOR ROYAL STREET LLC	APPROVED
PP15795	UNMANNED PERSONAL COMMUNICATIONS SYSTEM 55'	APPROVED
PP16344	TELECOMMUNICATIONS SITE ON 19.28 ACRES (.029 DEV)	WITHDRAWN
PP22343	PLANNER REVIEW OF BNR060186	WITHDRAWN
SP00266	I-15 CORRIDOR SPECIFIC PLAN WITH RESIDENTIAL & COM MERCIAL USES. SP ON 701.3 ACRES WITH 2,210 DU'S ON 422.9 ACRES, 196.9 ACRES OF COMMERCIAL, * EA 34371, EIR 340, CGPA 242, CZ 5619 PM 26203	APPROVED
SP00266S1	SUBSTANTIAL CONFORMANCE TO SP00266SUBSTANTIAL CONFORMANCE NO. 1 TO SP 266	VOID

Survey Cases

Case	Case Description	Status
MAP33428		ISSUED
ROS18099	CHARGE A30393D, TASK 3270 RECORD OF SURVEY FOR RIVCO COUNTY SURVEY DIVISION LIMONITE & I-15 IN	RECORDED

Transportation Cases

Case	Case Description	Status
IPP14639	CONVERTED CASE TRACK DATA - MV30000	ASSIGNED

USER QUESTIONNAIRE

INTRODUCTION

In order to qualify for one of the *Landowner Liability Protections* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2002, the *user* must provide the following information (if available) to the *environmental professional.* Failure to provide this information could result in a determination that "*all appropriate inquiry*" is not complete.

(1) Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?

CIRCLE YES *or* NO

If yes, please explain in detail.

(2) Are you aware of any Act Use Limitations (AUL), such as *engineering controls*, land use restrictions or *institutional controls* that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law?

YES *or* NO

If yes, please explain.

(3) As the *user* of this Environmental Site Assessment (ESA) do you have any specialized knowledge or familiarity related to the *property* or nearby properties? For example, are you involved in the same line of business as the current or former *occupants* of the *property* or its neighboring *property,* so that you may have specific knowledge of the chemicals and processes used by this type of business?

YES *or* NO Pesticides for forage crops were applied as needed. No chemicals are/were stored on the property. A California Department of pesticide regulation licensed Pest Control Adviser made all chemical application recomendations based on science, observation, chemical product label, and laws/regs. In addition a licensed Pest Control Operated performed all applications. Every chemical application was reported to and overseen by the Riverside County Agricultural Commissioners Office.

If yes, please explain.

(4) Does the purchase price being paid for this *property* reasonably reflect the fair market value of the *property*?

YES *or* NO

If you believe that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?

YES *or* NO

If yes, please explain.

(5) Are you aware of commonly known or *reasonably* ascertainable information that would help the *environment professional* to identify conditions pinpointing releases or threaten releases of hazardous materials and/ or chemicals? For example, as user,

(a.) Do you know of any past uses of the *property*? YES or NO
Farming

(b.) Do you know of specific chemicals that are present or once were present at the *property*? YES or NO see attached for agricultural chemicals applied to growing crops.

(c.) Do you know of any chemical spills or any other chemical releases that have taken place at the *property*? YES or NO

(d.) Do you know of any environmental cleanups that have taken place at the *property*? YES or NO

If any yes, please explain.

(6) As the user of this Environmental Site Assessment (ESA), based on your knowledge and experience related to the *property* are there any *obvious* indicators that point to the presence or likely presence of a contamination at the *property*?

YES *or* NO

If yes, please explain.

Completed By Chad Cleveland 10/19/21
Print Name

Chemical Summary

Date Applied: 2016-06-01 - 2021-08-06
Grower: Cleveland, Chad

Choice Weather Master

of Site(s) - 2

Farm	Field	Total Acres Treated - 70		Total Amount Used - 7 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - ALFALFA - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	24	1	12.8 floz	2.4 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	46	1	12.8 floz	4.6 ga

LI 700

of Site(s) - 7

Farm	Field	Total Acres Treated - 492		Total Amount Used - 13.63 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	36	1	4 floz	1.13 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	80	1	4 floz	2.5 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	97	1	4 floz	3.03 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	100	1	3.2 floz	2.5 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	49	1	3.2 floz	1.23 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	50	1	3.2 floz	1.25 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	80	1	3.2 floz	2 ga

MSO Concentrate with Leci-Tech

of Site(s) - 1

Farm	Field	Total Acres Treated - 24		Total Amount Used - 4.8 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - ALFALFA - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	24	1	25.6 floz	4.8 ga

Makaze

of Site(s) - 11

Farm	Field	Total Acres Treated - 641		Total Amount Used - 210.13 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - ALFALFA - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	45	1	64 floz	22.5 ga
Lewis, Sam	18 - ALFALFA - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	47	1	64 floz	23.5 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	2	1	32 floz	0.5 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	36	1	32 floz	9 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	80	1	32 floz	20 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	97	1	32 floz	24.25 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	46	1	48 floz	17.25 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	47	1	48 floz	17.63 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	72	1	32 floz	18 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	75	1	48 floz	28.13 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	94	1	40 floz	29.38 ga

Makaze (CA)

of Site(s) - 2

Farm	Field	Total Acres Treated - 105		Total Amount Used - 26.25 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	25	1	32 floz	6.25 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	80	1	32 floz	20 ga

NutriSync Manganese

of Site(s) - 2

Farm	Field	Total Acres Treated - 99		Total Amount Used - 24.75 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	49	1	32 floz	12.25 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	50	1	32 floz	12.5 ga

Q-Min Mang 5.5%

of Site(s) - 2

Farm	Field	Total Acres Treated - 177		Total Amount Used - 44.25 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	80	1	32 floz	20 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	97	1	32 floz	24.25 ga

Qmin Manganese 5.5%

of Site(s) - 2

Farm	Field	Total Acres Treated - 109		Total Amount Used - 27.25 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	73	1	32 floz	18.25 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	36	1	32 floz	9 ga

Raptor(R) Herbicide

of Site(s) - 1

Farm	Field	Total Acres Treated - 24		Total Amount Used - 1.13 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - ALFALFA - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	24	1	6 floz	1.13 ga

Rifle (CA)

of Site(s) - 7

Farm	Field	Total Acres Treated - 492		Total Amount Used - 15.38 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	36	1	4 floz	1.13 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	80	1	4 floz	2.5 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	97	1	4 floz	3.03 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	100	1	4 floz	3.13 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	49	1	4 floz	1.53 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	50	1	4 floz	1.56 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	80	1	4 floz	2.5 ga

Weedone LV4 Solventless

of Site(s) - 7

Farm	Field	Total Acres Treated - 492		Total Amount Used - 123 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	36	1	32 floz	9 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	80	1	32 floz	20 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	97	1	32 floz	24.25 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	100	1	32 floz	25 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	49	1	32 floz	12.25 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	50	1	32 floz	12.5 ga
Lewis, Sam	18 - WHEAT - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	80	1	32 floz	20 ga

Widespread Max

of Site(s) - 6

Farm	Field	Total Acres Treated - 411		Total Amount Used - 5.19 ga	
		Treated Acres	# of Apps	Average Rate	Total Units
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	36	1	1.4 floz	0.4 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	47	1	1.6 floz	0.59 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	80	1	1.4 floz	0.88 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	73	1	2 floz	1.14 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	80	1	1.6 floz	1 ga
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	95	1	1.6 floz	1.19 ga

ZARA WSB (CA)

# of Site(s) - 1		Total Acres Treated - 73		Total Amount Used - 13.69 lb	
Farm	**Field**	**Treated Acres**	**# of Apps**	**Average Rate**	**Total Units**
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	73	1	3 oz	13.69 lb

Zeal(r) Miticide(1)

# of Site(s) - 3		Total Acres Treated - 163		Total Amount Used - 29.55 lb	
Farm	**Field**	**Treated Acres**	**# of Apps**	**Average Rate**	**Total Units**
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	36	1	2.9 oz	6.53 lb
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	47	1	2.9 oz	8.52 lb
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE	80	1	2.9 oz	14.5 lb

Zeal(r) WDG Miticide

# of Site(s) - 2		Total Acres Treated - 175		Total Amount Used - 32.81 lb	
Farm	**Field**	**Treated Acres**	**# of Apps**	**Average Rate**	**Total Units**
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	80	1	3 oz	15 lb
Lewis, Sam	18 - CORN FOR/FOD - MAP; - 11575 BELLEGRAVE,MIRA LOMA;SEE - 180 Acres	95	1	3 oz	17.81 lb

Powered by Agrian

© Copyright 2021, Agrian Inc.
All Rights Reserved.

Created on: 2021-08-06 11:26:33
by Glenn Feenstra (16075)

USER QUESTIONNAIRE

INTRODUCTION

In order to qualify for one of the *Landowner Liability Protections* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2002, the *user* must provide the following information (if available) to the *environmental professional.* Failure to provide this information could result in a determination that "*all appropriate inquiry*" is not complete.

(1) Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?

CIRCLE YES *or* NO

If yes, please explain in detail.

(2) Are you aware of any Act Use Limitations (AUL), such as *engineering controls*, land use restrictions or *institutional controls* that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law?

YES *or* NO

If yes, please explain.

(3) As the *user* of this Environmental Site Assessment (ESA) do you have any specialized knowledge or familiarity related to the *property* or nearby properties? For example, are you involved in the same line of business as the current or former *occupants* of the *property* or its neighboring *property*, so that you may have specific knowledge of the chemicals and processes used by this type of business?

YES *or* NO HAVE INFO GIVEN TO US BY FARMER

If yes, please explain.

(4) Does the purchase price being paid for this *property* reasonably reflect the fair market value of the *property*?

YES *or* NO

If you believe that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?

YES *or* NO

If yes, please explain.

(5) Are you aware of commonly known or *reasonably* ascertainable information that would help the *environment professional* to identify conditions pinpointing releases or threaten releases of hazardous materials and/ or chemicals? For example, as user,

(a.) Do you know of any past uses of the *property*? YES or NO

(b.) Do you know of specific chemicals that are present or once were present at the *property*? YES or NO FARMER

(c.) Do you know of any chemical spills or any other chemical releases that have taken place at the *property*? YES or NO

(d.) Do you know of any environmental cleanups that have taken place at the *property*? YES *or* NO

If any yes, please explain.

(6) As the user of this Environmental Site Assessment (ESA), based on your knowledge and experience related to the *property* are there any *obvious* indicators that point to the presence or likely presence of a contamination at the *property*?

YES *or* NO

If yes, please explain.

Completed By RICHARD BONDI
Print Name

COUNTY OF RIVERSIDE • COMMUNITY HEALTH AGENCY

DEPARTMENT OF ENVIRONMENTAL HEALTH

May 8 2006

[redacted]

RE: The removal of two (2) underground storage tanks (UST) at Vernola Ranch - 12080 Bellegrave Ave., Mira Loma (Permit # 04-315).

[redacted]

This Department is in receipt of soil sampling results taken from underneath UST's removed on October 29, 2004. It has been determined that no significant contamination exists and that no further site mitigation will be required (reference Chemical & Environmental Laboratories, Inc. analytical report dated November 1, 2004).

With the provision that the results obtained from soil sampling were accurate and properly handled, it is the position of this Department that no further action will be required at this location.

Be advised, that this letter does not relieve you of any responsibilities mandated under the California Health & Safety Code if additional or previously unidentified contamination is discovered at this same location.

If you have any questions regarding this matter, please feel free to contact me at (951) 358-5055.

Sincerely,

Sandy Bunchek

Sandy Bunchek,
Supervising Hazardous Materials Management Specialist

cc: Facility File # 81649

47-923 Oasis Street, Rm. E-4
Indio, CA 92201
Fax (760) 863-8303
(760) 863-8976

4065 County Circle Drive, Rm. 104
Riverside, CA 92503
Fax (951) 358-5017
(951) 358-5055

800 S. Sanderson Avenue, Rm. 200
Hemet, CA 92545
Fax (951) 766-7874
(951) 766-6524

12/10/04

County of Riverside
Department of Environmental Health
Hazardous Materials Management Division

UST Sample Analytical Review

The analytical results from all soil and groundwater samples collected at UST sites in Riverside County must be evaluated by the LOP staff to determine if follow-up action is required. These results must be submitted to the LOP staff ***within 5 days*** *of receipt by the HMMD.*

Copies of the following documents shall be attached to this form and forwarded by the HMMD Specialist to the area LOP staff for review:

- ✓ UST Closure Report or Field Log
- ____ UST Form A & B
- ✓ Analytical Report
- ✓ Chain of Custody
- ✓ Sample Receipt Form
- ✓ URR (if issued)

UNDERGROUND STORAGE TANK CLOSURE REPORT
REYNOLDS GROUP
11/3/04
8 SAMPLES = ND
MW

UST Facility Name: VERNOLA RANCH
Address: 12080 BELLEGRAVE AVE.
Facility/Company Contact Person: F. EDWARDS REYNOLDS, JR Phone #: (714) 730-5397

Sampling Date: 10/29/04
Reason for Sampling: REMOVAL
Sample Locations: Tank ✓ Piping ✓ Dispenser ✓ Other: ____
Contents in USTs: Gasoline ✓ Diesel ✓ Other: ____

LOP Staff Evaluation

Reviewed by: KELLY WINTERS Date: 11/24/04
Entered into LOP for Follow-up: Yes ____ No X
Justification:
SOIL SAMPLE RESULTS DO NOT INDICATE THE PRESENCE OF PETROLEUM HYDROCARBONS. NO FURTHER ACTION REQUIRED BY LOP STAFF AT THIS TIME.

KW

Rev. 5/14/03

THE
REYNOLDS GROUP
a California corporation

UNDERGROUND STORAGE TANK
CLOSURE REPORT

VERNOLA RANCH
12080 BELLEGRAVE AVENUE
MIRA LOMA, CALIFORNIA

COUNTY OF RIVERSIDE
DEPARTMENT OF ENVIRONMENTAL HEALTH
PERMIT NO: 04-315

November 3, 2004

TRG Job # 6634

Tel 714-730-5397
PO Box 1996, Tustin, California 92781-1996
250 El Camino Real, Suite 204, Tustin, California 92780-3656
Fax 714-730-6476
www.reynolds-group.com

UNDERGROUND STORAGE TANK
CLOSURE REPORT

VERNOLA RANCH
12080 BELLEGRAVE AVENUE
MIRA LOMA, CALIFORNIA

EXECUTIVE SUMMARY

This report summarizes the removal of one 10,000 gallon and one 8,000 gallon fiberglass coated steel underground storage tanks (UST), at Vernola Ranch, located at 12080 Bellegrave Avenue in Mira Loma, California (the Site, see Figure 1 – Site Location Map).

On October 29, 2004, one 10,000 gallon diesel and one 8,000 gallon gasoline fiberglass coated steel UST, two dispensers, and associated piping were removed from the Site. A total of eight soil samples were collected as directed by Inspector Bruce Bailey of the County of Riverside, Hazardous Materials Division. Three samples (TD-A, TD-A5 and TD-B) were collected from beneath the former diesel fuel UST, three samples (TG-A, TG-B and TG-B5) were collected from beneath the former gasoline UST, and one sample was collected from beneath each of the former dispenser locations (D-1 and D-2).

Laboratory analytical results for all eight soil samples were "non-detect" for all analytes tested.

Based on the field work performed and subsequent laboratory analytical results, we recommend regulatory closure at this Site with respect to the subject USTs and dispensers.

1.0 INTRODUCTION

1.1 Involved Parties

Anthony Vernola of Vernola Ranch (the Client) retained The Reynolds Group (TRG), the contractor and consultant, to remove the subject USTs. Regulatory oversight was provided by the County of Riverside Department of Environmental Health as represented by Inspector Bruce Bailey. JEM Industries, Inc. of Irvine, California, performed excavation, cleaned the USTs, disposed of the rinsate liquids, and hauled and disposed of the UST system. TRG managed the project, collected soil samples, and produced this UST Closure Report. Chemical and Environmental Laboratories (C&E) of Santa Fe Springs, California, provided laboratory analyses.

2.0 GENERAL SITE CHARACTERISTICS

2.1 Site Description

The subject Site is located on the south side of Bellegrave Avenue, just east of Interstate 15 in Mira Loma, California. The USTs and dispensers were located in the northern portion of the Property near an area used for truck parking and maintenance (see Figure 2 – Site Plot Plan with UST and Sample Locations).

2.2 Site Lithology

The native soil encountered during the excavation consisted of brown, fine to coarse sand. During the tank removal and excavation, groundwater was not encountered.

3.0 UST REMOVAL

3.1 Field Activities and Observations

Prior to beginning fieldwork, a UST closure permit was obtained from the County of Riverside Department of Environmental Health (see Appendix A).

Excavation activities began at 8:00 a.m. on October 28, 2004. The concrete surface above the USTs was removed and disposed. Pea gravel mixed with native soil was removed from around the tanks and stockpiled on Site. On October 29, residual liquids were pumped from the USTs and the insides of the tanks were triple rinsed. The gasoline UST was degassed according to AQMD Rule 1149, and rinsate liquids and solids from both tanks were removed and disposed at DeMenno Kerdoon, a certified transfer, storage and disposal (TSD) facility in Compton, California. A copy of the rinsate manifest is included in Appendix C.

The USTs were inerted with dry ice prior to removal from the excavation and then lifted with a crane at approximately 12:30 pm. onto a flatbed truck and transported to American Metal Recycling in Fontana, California where they were destroyed for scrap. The tank destruction certificate is included in Appendix C.

3.2 Soil Sampling Procedures and Rationale

A representative from TRG, working under the direct supervision of a Registered Civil Engineer, collected a total of 8 soil samples. The samples were collected at the direction of Inspector Bailey. Three soil samples were collected from below each of the former USTs as follows: sample TD-A was collected at two feet into native soil from beneath the south end of the former diesel UST and sample TD-A5 was collected from five feet into native soil at the same location; TD-B was collected at two feet into native soils below the north end of the former diesel UST; sample TG-A was collected from two feet into native soils below the south end of the former gasoline UST, and TG-B and TG-B5 were collected from two and five feet, respectively, into the native soils from the north end of the

former gasoline UST. Two soil samples were collected from beneath each of the two dispensers. D-1 was collected from below the former diesel dispenser, and D-2 was collected from below the former gasoline dispenser.

The soil samples were collected using a backhoe by forcing soil from the teeth of the backhoe bucket into stainless steel sampling sleeves until they were filled. The ends of the sleeves were covered with Teflon and capped with plastic caps. The sleeves were labeled with sample identification, date, and time of sample collection. The soil samples were retained on ice and transported with chain-of-custody documentation to Chemical & Environmental Laboratories of Santa Fe Springs, California.

Following the UST removal, the excavation was backfilled with the stockpiled pea gravel/soil mixture and imported fill sand, then capped at the surface with crushed rock.

3.3 Laboratory Analyses and Results

The four soil samples associated with the gasoline UST and dispenser (TG-A, TG-B, TG-B5, and D2) were analyzed by EPA Method 8015 modified for gasoline. The remaining four soil samples associated with the diesel UST and dispenser (TD-A, TD-A5 and TD-B, and D1) were analyzed by EPA Method 8015 modified for diesel. All eight soil samples were also analyzed for benzene, toluene, ethylbenzene, xylenes (BTEX), methyl tertiary butyl ether (MTBE) and oxygenated compounds by EPA Method 8260B. The analyses performed were those required by the County of Riverside Department of Environmental Health.

Laboratory analytical results for all of the eight soil samples were "non-detect" for all analyses tested. Soil sampling results are shown in Table 1 and Appendix B - Laboratory Report and Chain of Custody Documentation.

4.0 CONCLUSIONS & RECOMMENDATIONS

The following conclusions are based on the results of the fieldwork conducted at the Site and subsequent laboratory analyses:

- One 10,00 gallon fiberglass coated steel diesel UST and one 8,000 gallon fiberglass coated steel gasoline UST, two dispensers and associated piping were removed from the Site.

- A total of eight soil samples were collected and from the native soils beneath the USTs and dispensers and sent for laboratory analysis.

- All eight soil samples were "non-detect" for all analytes tested.

Based on the field work performed and subsequent laboratory analytical results, we recommend regulatory closure at this Site with respect to the subject USTs and dispensers and that a "closure" or "no further action" letter be issued to the permittee.

5.0 LIMITATIONS

This report is based on the information gathered during the course of the work as described in the text and references. Its validity is based on the available facts, circumstances, and data as of the date of the report and The Reynolds Group takes no responsibility for any subsequent changes in those facts, circumstances, and data.



THE REYNOLDS GROUP,
a California corporation by:

F. Edward Reynolds, Jr.
California Registered Civil Engineer #38677


Andrew Ewing
Project Manager

TABLE 1
SUMMARY OF SOIL SAMPLE RESULTS
VERNOLA RANCH
12080 BELLEGRAVE AVENUE, MIRA LOMA, CA

Sample I.D.	Date Sampled	EPA M8015G	EPA M8015D	EPA M8260B				
		TPH Gasoline (mg/kg)	TPH Diesel (mg/kg)	B (ug/kg)	T (ug/kg)	E (ug/kg)	X (ug/kg)	MTBE (ug/kg)
TD-A	10/29/04	<10	<10	<2	<2	<2	<2	<5
TD-A5	10/29/04	<10	<10	<2	<2	<2	<2	<5
TD-B	10/29/04	<10	<10	<2	<2	<2	<2	<5
TG-A	10/29/04	<10	<10	<2	<2	<2	<2	<5
TG-A5	10/29/04	<10	<10	<2	<2	<2	<2	<5
TG-B	10/29/04	<10	<10	<2	<2	<2	<2	<5
D-1	10/29/04	<10	<10	<2	<2	<2	<2	<5
D-2	10/29/04	<10	<10	<2	<2	<2	<2	<5

Notes: ND = Not Detected at Laboratory Reporting limit
TPH Gasoline = Total Petroleum Hydrocarbons as Gasoline
TPH Diesel = Total Petroleum Hydrocarbons as Diesel
MTBE = Methyl Tertiary Butyl Ether

B = Benzene
T = Toluene
E = Ethylbenzene
X = Xylenes



THE REYNOLDS GROUP ENVIRONMENTAL SERVICES	Site Name: 12080 Bellegrave Avenue Mira Loma, CA		PLOT PLAN WITH UST AND SOIL SAMPLE LOCATIONS
	Prepared By: The Reynolds Group	Project No: 6634 Vernola Date: October 2004	FIGURE 2

COUNTY OF RIVERSIDE COMMUNITY HEALTH AGENCY
DEPARTMENT OF ENVIRONMENTAL HEALTH

Underground Storage Tank Closure Application and Permit

A permit will be issued for closure or abandonment in place of UST when a work plan is submitted. In addition to this permit, all applicable permits required by the local fire department, building department, and the Air Quality Management District must be obtained and should be available for review at the closure site. **A WORK PLAN MUST BE SUBMITTED TO OBTAIN A PERMIT**. All tank closures must, at a minimum, comply with the California Underground Storage Tank Regulations and the appropriate section of the California Health and Safety Code.

81649
FACILITY NUMBER

04-315
PLAN CHECK NUMBER

NAME OF FACILITY	ADDRESS OF FACILITY	CITY	ZIP	PHONE NUMBER
Vernola Ranch	12080 Bellegrave Ave.	Nita Loma	91752	951-685-9352
NAME OF OWNER/OPERATOR	**ADDRESS OWNER/OPERATOR**	**CITY**	**ZIP**	**PHONE NUMBER**
Anthony Vernola	1604 N. Laurel	Upland	91786	
NAME OF CONTRACTOR/APPLICANT	**ADDRESS CONTRACTOR/APPLICANT**	**CITY**	**ZIP**	**PHONE NUMBER**
The Reynolds Group	250 El Camino Real	Tustin	92780	714-730-5397

CONTRACTOR'S LICENSE TYPE AND NUMBER (Including Hazardous Materials Certification)
A HAZB 659765

ANSWER THE FOLLOWING QUESTIONS DESCRIBING THE TANK(S) TO BE CLOSED OR ABANDONED. IF YOU HAVE MORE THAN FOUR (4) TANKS, PROVIDE INFORMATION ON AN ADDITIONAL FORM.

TANK INFORMATION:	TANK 1		TANK 2		TANK 3		TANK 4	
SINGLE/DOUBLE WALLED TANK/AGE	Single	–	Single	–				
SIZE OF TANK/TANK MATERIAL	10,000	Steel	8,000	Steel				
SUBSTANCE STORED/ SUSPECTED OF LEAKING	Diesel	NO	Gasoline	NO				

CIRCLE THE METHOD OF CLOSURE: (REMOVAL) **ABANDONMENT IN PLACE** **TEMPORARY CLOSURE**

UNDERGROUND TANK CLOSURE INSPECTIONS MUST BE SCHEDULED AT LEAST FIVE (5) BUSINESS DAYS IN ADVANCE.

RIVERSIDE (951) 358-5055 INDIO (760) 863-8976 HEMET (951) 766-6524

CONTRACTOR/APPLICANT SIGNATURE: _____ DATE: 10/18/04

PERMIT APPROVED BY **(Ensure Workplan is Attached)** : _____ DATE: _____

Please Make Your Check Payable To The County Of Riverside

AMOUNT ATTACHED $ 699.00 TRANSACTION/OCR NO. A1756203 CHECK NO. 011469

WORK PLAN SUBMITTED Bernd Schleicher, 10/18/04

****THIS PERMIT FOR CLOSURE IS VALID FOR 90 DAYS FROM THE DATE OF ISSUE.**

DOH-HEH-008 (Rev. 03/04) White-Applicant Canary-File Pink-Specialist

COS Form submitted ☐

County of Riverside Health Services Agency
Department of Environmental Health
Hazardous Materials Management Division
Underground Storage Tank Closure Report

Facility Name Vernola Ranch — Date 10/29/04
Facility Address 12080 Bellgrove Ave., Mira Loma — Plan Check # 04-315
Facility Contact Person see attached permit — Phone — Facility # 81649
Contractor The Reynolds Group — Phone — # of Tanks 2
HMMS Personnel Bruce Bailey — # of Tanks Remaining 0

REMOVAL

Tank #	Size	Contents	Appearance (Integrity)
1	8K	Gas	Good (DW Glosteel)
2	10K	Diesel	Good (DW Glosteel)

UST(s) Rinsed Yes
Rinsate Manifest # 23597766
Destination of Rinsate Demenno Kerdoon
Hazardous Waste Hauler JEM
UST(s) Inerted Yes
Destination of UST(s) Adams Steel
Certificate of Destruction Requested Yes


FACILITY MAP

Refer to Figure 2 attached

SAMPLE INFORMATION

Tank #	Sample #	Depth (below soil)	Description	Analysis
1	1F-2	2'	No	Refer to
	1F-5	5'	Discoloration	County
	1T-2	2'		Handout
				attached
2	2F-1	1'		
	2F-5	5'		
	2T-2	2'		
Disp. 1	1D-2	2'		
Disp. 2	2D-2	2'		

Depth to UST bottom 8.5 ft.
Depth to groundwater Possible Perched 20ft.
Samples sealed and chilled Yes
Chain of Custody Yes
CA Certified Lab Chemical Env.
Status of excavated materials
URR Issued N/A
Referred to LOP
ADDITIONAL COMMENTS:



THE REYNOLDS GROUP ENVIRONMENTAL SERVICES	Site Name: 12080 Bellegrave Avenue Mira Loma, CA	PLOT PLAN WITH UST LOCATIONS
	Prepared By: The Reynolds Group	Project No: 6634 Vernola Date: October 2004
		FIGURE 2

COUNTY OF RIVERSIDE COMMUNITY HEALTH AGENCY
DEPARTMENT OF ENVIRONMENTAL HEALTH

Underground Storage Tank Closure Application and Permit

A permit will be issued for closure or abandonment in place of UST when a work plan is submitted. In addition to this permit, all applicable permits required by the local fire department, building department, and the Air Quality Management District must be obtained and should be available for review at the closure site. **A WORK PLAN MUST BE SUBMITTED TO OBTAIN A PERMIT.** All tank closures must, at a minimum, comply with the California Underground Storage Tank Regulations and the appropriate section of the California Health and Safety Code.

81649
FACILITY NUMBER

04-315
PLAN CHECK NUMBER

NAME OF FACILITY	ADDRESS OF FACILITY	CITY	ZIP	PHONE NUMBER
Vernola Ranch	12080 Bellegrave Ave.	Nita Loma	91752	951-685-9352
NAME OF OWNER/OPERATOR	**ADDRESS OWNER/OPERATOR**	**CITY**	**ZIP**	**PHONE NUMBER**
Anthony Vernola	1604 N. Laurel	Upland	91786	
NAME OF CONTRACTOR/APPLICANT	**ADDRESS CONTRACTOR/APPLICANT**	**CITY**	**ZIP**	**PHONE NUMBER**
The Reynolds Group	250 El Camino Real	Tustin	92780	714-730-5397

CONTRACTOR'S LICENSE TYPE AND NUMBER (Including Hazardous Materials Certification)
A HAZB 659765

ANSWER THE FOLLOWING QUESTIONS DESCRIBING THE TANK(S) TO BE CLOSED OR ABANDONED. IF YOU HAVE MORE THAN FOUR (4) TANKS, PROVIDE INFORMATION ON AN ADDITIONAL FORM.

TANK INFORMATION:	TANK 1		TANK 2		TANK 3		TANK 4	
SINGLE/DOUBLE WALLED TANK/AGE	Single	—	Single	—				
SIZE OF TANK/TANK MATERIAL	10,000	Steel	8,000	Steel				
SUBSTANCE STORED/ SUSPECTED OF LEAKING	Diesel	NO	Gasoline	NO				

CIRCLE THE METHOD OF CLOSURE: (REMOVAL) **ABANDONMENT IN PLACE** **TEMPORARY CLOSURE**

UNDERGROUND TANK CLOSURE INSPECTIONS MUST BE SCHEDULED AT LEAST FIVE (5) BUSINESS DAYS IN ADVANCE.

RIVERSIDE (951) 358-5055 INDIO (760) 863-8976 HEMET (951) 766-6524

CONTRACTOR/APPLICANT SIGNATURE: _____ DATE: 10/18/04

PERMIT APPROVED BY **(Ensure Workplan is Attached)** : _____ DATE: _____

Please Make Your Check Payable To The County Of Riverside

AMOUNT ATTACHED $ 699.00 TRANSACTION/OCR NO. A1756203 CHECK NO. 011469

WORK PLAN SUBMITTED Bernd Schleicher, 10/18/04

****THIS PERMIT FOR CLOSURE IS VALID FOR 90 DAYS FROM THE DATE OF ISSUE.**

DOH-HEH-008 (Rev. 03/04)

White-Applicant Canary-File Pink-Specialist

APPENDIX C

PHOTOGRAPHS

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



1. View west from northeastern corner.



2. View south from northeastern corner.

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



3. View north from central northeastern area.



4. View west from central northeastern area.

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



5. View south from central northeastern area.



6. View north from central eastern area.

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



7. View east from central eastern area.




8. View south from central eastern area.

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California




9. View north from central east area.



10. View west from central east area.

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California




11. View south from central east area.



12. View north from southeastern area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California




13. View east from southeastern area.



14. View east from southwestern area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



15. View north from southwestern area.




16. View south from central western area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



17. View east from central western area.



18. View north from central western area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



19. View south from north central western area.




20. View east from north central western area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California




21. View north from north central western area.



22. View south from northwestern corner

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



23. View east from northwestern corner.




24. View north from northwestern corner

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



25. View east from northwestern area.




26. View northeast from northern area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



27. View east from northern area.



28. View northwest from northern area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



29. View north from northern area.



30. View west from northern area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California




31. View north from northern area.



32. View west from northern area

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California




33. View east from northern area.



34. View south from northern area

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



35. View west from northern area.



36. View of barrels and stained soil near barn in northeast corner of Site.

GEOTEK

PHOTOGRAPHS
Vernola Ranch North Project
Jurupa Valley, Riverside County, California



37. View of barrels and stained soil near barn in northeast corner of Site.

APPENDIX D

ENVIRONMENTAL DATABASE REPORT

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752

Inquiry Number: 6691091.2s
October 06, 2021

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	228
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-11
Physical Setting Source Map Findings	A-13
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

12080 BELLEGRAVE AVENUE
MIRA LOMA, CA 91752

COORDINATES

Latitude (North):	33.9848820 - 33° 59' 5.57''
Longitude (West):	117.5461460 - 117° 32' 46.12''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	449554.2
UTM Y (Meters):	3760419.8
Elevation:	689 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5640930 CORONA NORTH, CA
Version Date:	2012
North Map:	5620426 GUASTI, CA
Version Date:	2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140603
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
12080 BELLEGRAVE AVENUE
MIRA LOMA, CA 91752

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	SAMUEL P LEWIS DBA C	12080 BELLEGRAVE AV	FINDS		TP
A2	VERNOLA RANCH	12080 BELLEGRAVE AVE	FINDS		TP
A3	SAMUEL P LEWIS DBA C	12080 BELLEGRAVE AVE	SWEEPS UST, EMI, CERS		TP
A4	BERNOLA RANCH	12080 BELLGRAVE AVE	HWTS		TP
A5	VERNOLA RANCH	12080 BELLEGRAVE AVE	HAZNET, HWTS		TP
A6	VERNOLA RANCH	12080 BELLEGRAVE AVE	UST		TP
7	HARVEST	NW OF LIMONITE AVE A	CIWQS	Lower	1 ft.
8	ELEMENTARY SCHOOL NO	WINEVILLE ROAD/BELLG	ENVIROSTOR, SCH	Higher	568, 0.108, NNE
B9	KOHL'S INC - STORE #	12315 LIMONITE AVE	RCRA NonGen / NLR	Lower	859, 0.163, SSW
B10	KOHL'S INC - STORE #	12315 LIMONITE AVE	CERS HAZ WASTE, HAZNET, CERS, HWTS	Lower	859, 0.163, SSW
11	WELL II-7		PFAS	Higher	869, 0.165, NE
12	WELL II-8		PFAS	Higher	869, 0.165, ENE
13	HOMECOMING AT EASTVA	5464 W HOMECOMING CI	RCRA NonGen / NLR	Higher	1015, 0.192, NW
14	WELL II-6		PFAS	Higher	1279, 0.242, NNE
C15	SWAN LAKE TEXACO	5800 HAMMER AVENUE	Notify 65	Lower	1623, 0.307, WSW
C16	TEXACO SWAN LAKE	5800 HAMNER AVE	LUST, Cortese, HIST CORTESE, NPDES, CERS	Lower	1623, 0.307, WSW
17	WELL II-9A		PFAS	Higher	2359, 0.447, NNE
D18	WELL II-4		PFAS	Higher	2549, 0.483, WNW
19	PROPOSED ELEMENTARY	NORTH OF BELLEGRAVE	ENVIROSTOR, SCH	Higher	2668, 0.505, NE
D20	PROPOSED K-8 SCHOOL	5240 AND 5380 HAMNER	ENVIROSTOR, SCH	Higher	2693, 0.510, WNW
21	PROPOSED LOUIS VANDE	6715 WINEVILLE AVENU	ENVIROSTOR, SCH	Lower	4832, 0.915, SSE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
SAMUEL P LEWIS DBA C 12080 BELLEGRAVE AV MIRA LOMA, CA 91752	FINDS Registry ID:: 110041393202	N/A
VERNOLA RANCH 12080 BELLEGRAVE AVE MIRA LOMA, CA 91752	FINDS Registry ID:: 110065468185	N/A
SAMUEL P LEWIS DBA C 12080 BELLEGRAVE AVE MIRA LOMA, CA 91752	SWEEPS UST Status: A Tank Status: A Comp Number: 53932 EMI Facility Id: 150351 CERS	N/A
BERNOLA RANCH 12080 BELLGRAVE AVE MIRA LOMA, CA 91752	HWTS	N/A
VERNOLA RANCH 12080 BELLEGRAVE AVE MIRA LOMA, CA 91752	HAZNET GEPAID: CAC002583200 HWTS	N/A
VERNOLA RANCH 12080 BELLEGRAVE AVE MIRA LOMA, CA 91752	UST Database: UST, Date of Government Version: 06/03/2021 Facility Id: 81649	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL---------- National Priority List

EXECUTIVE SUMMARY

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-LQG ---------- RCRA - Large Quantity Generators
RCRA-SQG ---------- RCRA - Small Quantity Generators
RCRA-VSQG ---------- RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State- and tribal - equivalent NPL

RESPONSE ---------- State Response Sites

State and tribal landfill and/or solid waste disposal site lists

SWF/LF ---------- Solid Waste Information System

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
CPS-SLIC ---------- Statewide SLIC Cases

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing

AST ---------- Aboveground Petroleum Storage Tank Facilities
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal voluntary cleanup sites

VCP ---------- Voluntary Cleanup Program Properties
INDIAN VCP ---------- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

BROWNFIELDS ---------- Considered Brownfieds Sites Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT ---------- Waste Management Unit Database
SWRCY ---------- Recycler Database
HAULERS ---------- Registered Waste Tire Haulers Listing
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---------- Open Dump Inventory
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
HIST Cal-Sites ---------- Historical Calsites Database
CDL ---------- Clandestine Drug Labs
Toxic Pits ---------- Toxic Pits Cleanup Act Sites
US CDL ---------- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

HIST UST ---------- Hazardous Substance Storage Container Database
CA FID UST ---------- Facility Inventory Database
CERS TANKS ---------- California Environmental Reporting System (CERS) Tanks

Local Land Records

LIENS ---------- Environmental Liens Listing
LIENS 2 ---------- CERCLA Lien Information
DEED ---------- Deed Restriction Listing

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System
CHMIRS ---------- California Hazardous Material Incident Report System
LDS ---------- Land Disposal Sites Listing
MCS ---------- Military Cleanup Sites Listing

SPILLS 90 ..... SPILLS 90 data from FirstSearch

Other Ascertainable Records

FUDS ..... Formerly Used Defense Sites
DOD ..... Department of Defense Sites
SCRD DRYCLEANERS ..... State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ..... Financial Assurance Information
EPA WATCH LIST ..... EPA WATCH LIST
2020 COR ACTION ..... 2020 Corrective Action Program List
TSCA ..... Toxic Substances Control Act
TRIS ..... Toxic Chemical Release Inventory System
SSTS ..... Section 7 Tracking Systems
ROD ..... Records Of Decision
RMP ..... Risk Management Plans
RAATS ..... RCRA Administrative Action Tracking System
PRP ..... Potentially Responsible Parties
PADS ..... PCB Activity Database System
ICIS ..... Integrated Compliance Information System
FTTS ..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ..... Material Licensing Tracking System
COAL ASH DOE ..... Steam-Electric Plant Operation Data
COAL ASH EPA ..... Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ..... PCB Transformer Registration Database
RADINFO ..... Radiation Information Database
HIST FTTS ..... FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ..... Incident and Accident Data
CONSENT ..... Superfund (CERCLA) Consent Decrees
INDIAN RESERV ..... Indian Reservations
FUSRAP ..... Formerly Utilized Sites Remedial Action Program
UMTRA ..... Uranium Mill Tailings Sites
LEAD SMELTERS ..... Lead Smelter Sites
US AIRS ..... Aerometric Information Retrieval System Facility Subsystem
US MINES ..... Mines Master Index File
ABANDONED MINES ..... Abandoned Mines
DOCKET HWC ..... Hazardous Waste Compliance Docket Listing
ECHO ..... Enforcement & Compliance History Information
UXO ..... Unexploded Ordnance Sites
FUELS PROGRAM ..... EPA Fuels Program Registered Listing
CA BOND EXP. PLAN ..... Bond Expenditure Plan
CUPA Listings ..... CUPA Resources List
DRYCLEANERS ..... Cleaner Facilities
ENF ..... Enforcement Action Listing
Financial Assurance ..... Financial Assurance Information Listing
ICE ..... ICE
HWP ..... EnviroStor Permitted Facilities Listing
HWT ..... Registered Hazardous Waste Transporter Database
MINES ..... Mines Site Location Listing
MWMP ..... Medical Waste Management Program Listing
NPDES ..... NPDES Permits Listing
PEST LIC ..... Pesticide Regulation Licenses Listing
PROC ..... Certified Processors Database
UIC ..... UIC Listing
UIC GEO ..... UIC GEO (GEOTRACKER)

WASTEWATER PITS Oil Wastewater Pits Listing
WDS Waste Discharge System
WIP Well Investigation Program Case List
MILITARY PRIV SITES MILITARY PRIV SITES (GEOTRACKER)
PROJECT PROJECT (GEOTRACKER)
WDR Waste Discharge Requirements Listing
NON-CASE INFO NON-CASE INFO (GEOTRACKER)
OTHER OIL GAS OTHER OIL & GAS (GEOTRACKER)
PROD WATER PONDS PROD WATER PONDS (GEOTRACKER)
SAMPLING POINT SAMPLING POINT (GEOTRACKER)
WELL STIM PROJ Well Stimulation Project (GEOTRACKER)
MINES MRDS Mineral Resources Data System

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants
EDR Hist Auto EDR Exclusive Historical Auto Stations
EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF Recovered Government Archive Solid Waste Facilities List
RGA LUST Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

State- and tribal - equivalent CERCLIS

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information

that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 04/23/2021 has revealed that there are 4 ENVIROSTOR sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ELEMENTARY SCHOOL NO	***WINEVILLE ROAD/BELLG***	***NNE 0 - 1/8 (0.108 mi.)***	***8***	***17***
Facility Id: 33010071				
Status: No Action Required				
PROPOSED ELEMENTARY	***NORTH OF BELLEGRAVE***	***NE 1/2 - 1 (0.505 mi.)***	***19***	***217***
Facility Id: 60002063				
Status: No Further Action				
PROPOSED K-8 SCHOOL	***5240 AND 5380 HAMNER***	***WNW 1/2 - 1 (0.510 mi.)***	***D20***	***220***
Facility Id: 60000409				
Status: No Further Action				

Lower Elevation	Address	Direction / Distance	Map ID	Page
PROPOSED LOUIS VANDE	***6715 WINEVILLE AVENU***	***SSE 1/2 - 1 (0.915 mi.)***	***21***	***224***
Facility Id: 33020007				
Status: No Further Action				

State and tribal leaking storage tank lists

LUST: Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the LUST list, as provided by EDR, has revealed that there is 1 LUST site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TEXACO SWAN LAKE	***5800 HAMNER AVE***	***WSW 1/4 - 1/2 (0.307 mi.)***	***C16***	***144***
Database: LUST REG 8, Date of Government Version: 02/14/2005				
Database: LUST, Date of Government Version: 06/03/2021				
Database: RIVERSIDE CO. LUST, Date of Government Version: 06/29/2021				
Status: Completed - Case Closed				
Facility Status: Case Closed				
Facility Id: 89159				
Global Id: T0606500101				
Facility Status: 9				
Global ID: T0606500101				

EXECUTIVE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

SCH: This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category. depending on the level of threat to public health and safety or the. environment they pose.

A review of the SCH list, as provided by EDR, and dated 04/23/2021 has revealed that there is 1 SCH site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ELEMENTARY SCHOOL NO Facility Id: 33010071 Status: No Action Required	***WINEVILLE ROAD/BELLG***	***NNE 0 - 1/8 (0.108 mi.)***	***8***	***17***

CERS HAZ WASTE: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

A review of the CERS HAZ WASTE list, as provided by EDR, and dated 04/19/2021 has revealed that there is 1 CERS HAZ WASTE site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
KOHL'S INC - STORE #	***12315 LIMONITE AVE***	***SSW 1/8 - 1/4 (0.163 mi.)***	***B10***	***23***

PFAS: A listing of PFAS contaminated sites included in the GeoTracker database.

A review of the PFAS list, as provided by EDR, and dated 06/04/2021 has revealed that there are 5 PFAS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WELL II-7		NE 1/8 - 1/4 (0.165 mi.)	11	30
WELL II-8		ENE 1/8 - 1/4 (0.165 mi.)	12	64
WELL II-6		NNE 1/8 - 1/4 (0.242 mi.)	14	101
WELL II-9A		NNE 1/4 - 1/2 (0.447 mi.)	17	149
WELL II-4		WNW 1/4 - 1/2 (0.483 mi.)	D18	183

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/22/2021 has revealed that

there are 2 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HOMECOMING AT EASTVA EPA ID:: CAL000408912	5464 W HOMECOMING CI	NW 1/8 - 1/4 (0.192 mi.)	13	98

Lower Elevation	Address	Direction / Distance	Map ID	Page
KOHL'S INC - STORE # EPA ID:: CAL000356232	12315 LIMONITE AVE	SSW 1/8 - 1/4 (0.163 mi.)	B9	20

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 06/17/2021 has revealed that there is 1 Cortese site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TEXACO SWAN LAKE Cleanup Status: COMPLETED - CASE CLOSED	***5800 HAMNER AVE***	***WSW 1/4 - 1/2 (0.307 mi.)***	***C16***	***144***

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there is 1 HIST CORTESE site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
TEXACO SWAN LAKE Reg Id: 083301026T	***5800 HAMNER AVE***	***WSW 1/4 - 1/2 (0.307 mi.)***	***C16***	***144***

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

A review of the Notify 65 list, as provided by EDR, and dated 03/12/2021 has revealed that there is 1 Notify 65 site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SWAN LAKE TEXACO	5800 HAMMER AVENUE	WSW 1/4 - 1/2 (0.307 mi.)	C15	144

CIWQS: The California Integrated Water Quality System (CIWQS) is a computer system used by the State and Regional Water Quality Control Boards to track information about places of environmental interest, manage permits and other orders, track inspections, and manage violations and enforcement activities.

A review of the CIWQS list, as provided by EDR, and dated 05/19/2021 has revealed that there is 1

EXECUTIVE SUMMARY

CIWQS site within approximately 0.001 miles of the target property.


Lower Elevation	Address	Direction / Distance	Map ID	Page
HARVEST	NW OF LIMONITE AVE A	0 - 1/8 (0.000 mi.)	7	16

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 2 records.

Site Name	Database(s)
SO CAL GAS/ONTARIO MGP	EDR MGP
MILLIKEN SANITARY LANDFILL	ENVIROSTOR

OVERVIEW MAP - 6691091.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Vernola Ranch North	CLIENT:	Geotek
ADDRESS:	12080 Bellegrave Avenue Mira Loma CA 91752	CONTACT:	Anna M. Scott
LAT/LONG:	33.984882 / 117.546146	INQUIRY #:	6691091.2s
		DATE:	October 06, 2021 8:29 am

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 6691091.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

0 1/8 1/4 1/2 Miles

Indian Reservations BIA

County Boundary

Power transmission lines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands

Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Vernola Ranch North	CLIENT: Geotek
ADDRESS: 12080 Bellegrave Avenue Mira Loma CA 91752	CONTACT: Anna M. Scott INQUIRY #: 6691091.2s
LAT/LONG: 33.984882 / 117.546146	DATE: October 06, 2021 8:30 am

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	0	NR	NR	NR	0
RCRA-VSQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
State- and tribal - equivalent NPL								
RESPONSE	1.000		0	0	0	0	NR	0
State- and tribal - equivalent CERCLIS								
ENVIROSTOR	1.000		1	0	0	3	NR	4
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
LUST	0.500		0	0	1	NR	NR	1

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	0.500		0	0	0	NR	NR	0
CPS-SLIC	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250	1	0	0	NR	NR	NR	1
AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal voluntary cleanup sites								
VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
WMUDS/SWAT	0.500		0	0	0	NR	NR	0
SWRCY	0.500		0	0	0	NR	NR	0
HAULERS	0.001		0	NR	NR	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
HIST Cal-Sites	1.000		0	0	0	0	NR	0
SCH	0.250		1	0	NR	NR	NR	1
CDL	0.001		0	NR	NR	NR	NR	0
CERS HAZ WASTE	0.250		0	1	NR	NR	NR	1
Toxic Pits	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
PFAS	0.500		0	3	2	NR	NR	5
Local Lists of Registered Storage Tanks								
SWEEPS UST	0.250	1	0	0	NR	NR	NR	1
HIST UST	0.250		0	0	NR	NR	NR	0
CA FID UST	0.250		0	0	NR	NR	NR	0
CERS TANKS	0.250		0	0	NR	NR	NR	0
Local Land Records								
LIENS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	0.001		0	NR	NR	NR	NR	0
DEED	0.500		0	0	0	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
CHMIRS	0.001		0	NR	NR	NR	NR	0
LDS	0.001		0	NR	NR	NR	NR	0
MCS	0.001		0	NR	NR	NR	NR	0
SPILLS 90	0.001		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		0	2	NR	NR	NR	2
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001	2	0	NR	NR	NR	NR	2
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
ECHO	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
CA BOND EXP. PLAN	1.000		0	0	0	0	NR	0
Cortese	0.500		0	0	1	NR	NR	1
CUPA Listings	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
EMI	0.001	1	0	NR	NR	NR	NR	1
ENF	0.001		0	NR	NR	NR	NR	0
Financial Assurance	0.001		0	NR	NR	NR	NR	0
HAZNET	0.001	1	0	NR	NR	NR	NR	1
ICE	0.001		0	NR	NR	NR	NR	0
HIST CORTESE	0.500		0	0	1	NR	NR	1
HWP	1.000		0	0	0	0	NR	0
HWT	0.250		0	0	NR	NR	NR	0
MINES	0.250		0	0	NR	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
NPDES	0.001		0	NR	NR	NR	NR	0
PEST LIC	0.001		0	NR	NR	NR	NR	0
PROC	0.500		0	0	0	NR	NR	0
Notify 65	1.000		0	0	1	0	NR	1
UIC	0.001		0	NR	NR	NR	NR	0
UIC GEO	0.001		0	NR	NR	NR	NR	0
WASTEWATER PITS	0.500		0	0	0	NR	NR	0
WDS	0.001		0	NR	NR	NR	NR	0
WIP	0.250		0	0	NR	NR	NR	0
MILITARY PRIV SITES	0.001		0	NR	NR	NR	NR	0
PROJECT	0.001		0	NR	NR	NR	NR	0
WDR	0.001		0	NR	NR	NR	NR	0
CIWQS	0.001		1	NR	NR	NR	NR	1
CERS	0.001	1	0	NR	NR	NR	NR	1
NON-CASE INFO	0.001		0	NR	NR	NR	NR	0
OTHER OIL GAS	0.001		0	NR	NR	NR	NR	0
PROD WATER PONDS	0.001		0	NR	NR	NR	NR	0
SAMPLING POINT	0.001		0	NR	NR	NR	NR	0
WELL STIM PROJ	0.001		0	NR	NR	NR	NR	0
HWTS	TP	2	NR	NR	NR	NR	NR	2
MINES MRDS	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA LF	0.001		0	NR	NR	NR	NR	0
RGA LUST	0.001		0	NR	NR	NR	NR	0
- Totals --		9	3	6	6	3	0	27

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **SAMUEL P LEWIS DBA CHINO WELDING & ASSEM** **FINDS** **1014675681**
Target **12080 BELLEGRAVE AVE** **N/A**
Property **MIRA LOMA, CA 91752**

Site 1 of 6 in cluster A

Actual:
689 ft.

FINDS:
Registry ID: 110041393202

Click Here:

Environmental Interest/Information System:
AIR EMISSIONS CLASSIFICATION UNKNOWN

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A2 **VERNOLA RANCH** **FINDS** **1023257663**
Target **12080 BELLEGRAVE AVE** **N/A**
Property **MIRA LOMA, CA 91752**

Site 2 of 6 in cluster A

Actual:
689 ft.

FINDS:
Registry ID: 110065468185

Click Here:

Environmental Interest/Information System:
STATE MASTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A3 **SAMUEL P LEWIS DBA CHINO WELDING & ASSEM** **SWEEPS UST** **S106934062**
Target **12080 BELLEGRAVE AVE** **EMI** **N/A**
Property **MIRA LOMA, CA 91752** **CERS**

Site 3 of 6 in cluster A

Actual:
689 ft.

SWEEPS UST:

Name:	VENOLA RANCH
Address:	12080 BELLEGRAVE AVE
City:	MIRA LOMA
Status:	Active
Comp Number:	53932
Number:	3
Board Of Equalization:	Not reported
Referral Date:	10-31-90
Action Date:	10-31-90
Created Date:	10-31-90
Owner Tank Id:	Not reported
SWRCB Tank Id:	33-000-053932-000001
Tank Status:	A
Capacity:	8000
Active Date:	10-31-90
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	2

SAMUEL P LEWIS DBA CHINO WELDING & ASSEM (Continued) **S106934062**

Name:	VENOLA RANCH
Address:	12080 BELLEGRAVE AVE
City:	MIRA LOMA
Status:	Active
Comp Number:	53932
Number:	3
Board Of Equalization:	Not reported
Referral Date:	10-31-90
Action Date:	10-31-90
Created Date:	10-31-90
Owner Tank Id:	Not reported
SWRCB Tank Id:	33-000-053932-000002
Tank Status:	A
Capacity:	10000
Active Date:	10-31-90
Tank Use:	M.V. FUEL
STG:	P
Content:	DIESEL
Number Of Tanks:	Not reported

EMI:

Name:	SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address:	12080 BELLEGRAVE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Year:	2006
County Code:	33
Air Basin:	SC
Facility ID:	150351
Air District Name:	SC
SIC Code:	711
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.192560175054704595
Reactive Organic Gases Tons/Yr:	.109
Carbon Monoxide Emissions Tons/Yr:	13.734
NOX - Oxides of Nitrogen Tons/Yr:	8.159
SOX - Oxides of Sulphur Tons/Yr:	.002
Particulate Matter Tons/Yr:	.036
Part. Matter 10 Micrometers and Smllr Tons/Yr:	.035784

Name:	SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address:	12080 BELLEGRAVE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Year:	2007
County Code:	33
Air Basin:	SC
Facility ID:	150351
Air District Name:	SC
SIC Code:	711
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.192560175054704595
Reactive Organic Gases Tons/Yr:	.109
Carbon Monoxide Emissions Tons/Yr:	13.734
NOX - Oxides of Nitrogen Tons/Yr:	8.159

SAMUEL P LEWIS DBA CHINO WELDING & ASSEM (Continued) **S106934062**

SOX - Oxides of Sulphur Tons/Yr: .002
Particulate Matter Tons/Yr: .036
Part. Matter 10 Micrometers and Smllr Tons/Yr: .035784

Name: SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address: 12080 BELLEGRAVE AVE
City,State,Zip: MIRA LOMA, CA 91752
Year: 2008
County Code: 33
Air Basin: SC
Facility ID: 150351
Air District Name: SC
SIC Code: 7692
Air District Name: SOUTH COAST AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1.641137855579868708
Reactive Organic Gases Tons/Yr: .15
Carbon Monoxide Emissions Tons/Yr: 19.08
NOX - Oxides of Nitrogen Tons/Yr: 11.33
SOX - Oxides of Sulphur Tons/Yr: .003018
Particulate Matter Tons/Yr: .05
Part. Matter 10 Micrometers and Smllr Tons/Yr: .0497

Name: SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address: 12080 BELLEGRAVE AVE
City,State,Zip: MIRA LOMA, CA 91752
Year: 2009
County Code: 33
Air Basin: SC
Facility ID: 150351
Air District Name: SC
SIC Code: 7692
Air District Name: SOUTH COAST AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1.6411378555798599
Reactive Organic Gases Tons/Yr: 0.14999999999999999
Carbon Monoxide Emissions Tons/Yr: 19.079999999999998
NOX - Oxides of Nitrogen Tons/Yr: 11.33
SOX - Oxides of Sulphur Tons/Yr: 3.0200000000000001E-3
Particulate Matter Tons/Yr: 5.0000000000000003E-2
Part. Matter 10 Micrometers and Smllr Tons/Yr: 4.9700000000000001E-2

Name: SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address: 12080 BELLEGRAVE AVE
City,State,Zip: MIRA LOMA, CA 91752
Year: 2010
County Code: 33
Air Basin: SC
Facility ID: 150351
Air District Name: SC
SIC Code: 7692
Air District Name: SOUTH COAST AQMD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1.42286652078774

SAMUEL P LEWIS DBA CHINO WELDING & ASSEM (Continued) **S106934062**

Reactive Organic Gases Tons/Yr:	0.13005
Carbon Monoxide Emissions Tons/Yr:	16.44699
NOX - Oxides of Nitrogen Tons/Yr:	9.7710899999999992
SOX - Oxides of Sulphur Tons/Yr:	2.5999999999999999E-3
Particulate Matter Tons/Yr:	0.04335
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.0430899

Name:	SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address:	12080 BELLEGRAVE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Year:	2011
County Code:	33
Air Basin:	SC
Facility ID:	150351
Air District Name:	SC
SIC Code:	7692
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.2259299781
Reactive Organic Gases Tons/Yr:	0.11205
Carbon Monoxide Emissions Tons/Yr:	14.17059
NOX - Oxides of Nitrogen Tons/Yr:	8.41869
SOX - Oxides of Sulphur Tons/Yr:	0.00224
Particulate Matter Tons/Yr:	0.03735
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.0371259

Name:	SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address:	12080 BELLEGRAVE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Year:	2012
County Code:	33
Air Basin:	SC
Facility ID:	150351
Air District Name:	SC
SIC Code:	7692
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.7871991247
Reactive Organic Gases Tons/Yr:	0.16335
Carbon Monoxide Emissions Tons/Yr:	20.65833
NOX - Oxides of Nitrogen Tons/Yr:	12.27303
SOX - Oxides of Sulphur Tons/Yr:	0.00326
Particulate Matter Tons/Yr:	0.05445
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.0541233

Name:	SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address:	12080 BELLEGRAVE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Year:	2013
County Code:	33
Air Basin:	SC
Facility ID:	150351
Air District Name:	SC
SIC Code:	7692
Air District Name:	SOUTH COAST AQMD

SAMUEL P LEWIS DBA CHINO WELDING & ASSEM (Continued) **S106934062**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.6090809628
Reactive Organic Gases Tons/Yr:	0.14707
Carbon Monoxide Emissions Tons/Yr:	18.59977
NOX - Oxides of Nitrogen Tons/Yr:	11.05005
SOX - Oxides of Sulphur Tons/Yr:	0.00294
Particulate Matter Tons/Yr:	0.04902
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.04872588

Name:	SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address:	12080 BELLEGRAVE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Year:	2014
County Code:	33
Air Basin:	SC
Facility ID:	150351
Air District Name:	SC
SIC Code:	7623
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.3888292159
Reactive Organic Gases Tons/Yr:	0.1293
Carbon Monoxide Emissions Tons/Yr:	16.387
NOX - Oxides of Nitrogen Tons/Yr:	9.89753
SOX - Oxides of Sulphur Tons/Yr:	0.00258
Particulate Matter Tons/Yr:	0.0431
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0.0428414

CERS:

Name:	SAMUEL P LEWIS DBA CHINO WELDING & ASSEM
Address:	12080 BELLEGRAVE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Site ID:	491749
CERS ID:	110041393202
CERS Description:	US EPA Air Emission Inventory System (EIS)

A4 **BERNOLA RANCH** **HWTS** **S124559684**
Target **12080 BELLGRAVE AVE** **N/A**
Property **MIRA LOMA, CA 91752**

Site 4 of 6 in cluster A

Actual:
689 ft.

HWTS:

Name:	BERNOLA RANCH
Address:	12080 BELLGRAVE AVE
Address 2:	Not reported
City,State,Zip:	MIRA LOMA, CA 917520000
EPA ID:	CAC001470960
Inactive Date:	10/25/2000
Create Date:	04/15/1999
Last Act Date:	10/25/2000
Mailing Name:	CHERRY BURKE
Mailing Address:	12080 BELLGRAVE AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	MIRA LOMA, CA 917520000

BERNOLA RANCH (Continued) **S124559684**

Owner Name: BERNOLA RANCH
Owner Address: 12080 BELLGRAVE AVE
Owner Address 2: Not reported
Owner City,State,Zip: MIRA LOMA, CA 917520000
Contact Name: CAROL WALDNER/CONTR
Contact Address: 12080 BELLGRAVE AVE
Contact Address 2: Not reported
City,State,Zip: MIRA LOMA, CA 917520000

A5 **VERNOLA RANCH** **HAZNET** **S112941096**
Target **12080 BELLEGRAVE AVE** **HWTS** **N/A**
Property **MIRA LOMA, CA 91752**

Site 5 of 6 in cluster A

Actual:
689 ft.

HAZNET:
Name: VERNOLA RANCH
Address: 12080 BELLEGRAVE AVE
Address 2: Not reported
City,State,Zip: MIRA LOMA, CA 91752
Contact: ANTHONY VERNOLA
Telephone: 9516854352
Mailing Name: Not reported
Mailing Address: 12080 BELLEGRAVE AVE

Year: 2005
Gepaid: CAC002583200
TSD EPA ID: CAT080013352
CA Waste Code: 134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method: R01 - Recycler
Tons: 2.73

Year: 2004
Gepaid: CAC002583200
TSD EPA ID: CAT080013352
CA Waste Code: 134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method: -
Tons: 2.205

Additional Info:
Year: 2005
Gen EPA ID: CAC002583200

Shipment Date: 20050519
Creation Date: 8/17/2005 18:32:59
Receipt Date: 20050523
Manifest ID: 23597806
Trans EPA ID: CAR000053587
Trans Name: JEM INDUSTRIES INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAT080013352
Trans Name: DEMENNO KERDOON
TSDF Alt EPA ID: CAT080013352

VERNOLA RANCH (Continued) **S112941096**

TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	NONE
Meth Code:	R01 - Recycler
Quantity Tons:	2.73
Waste Quantity:	650
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2004
Gen EPA ID:	CAC002583200
Shipment Date:	20041029
Creation Date:	1/28/2005 18:31:06
Receipt Date:	20041104
Manifest ID:	23597766
Trans EPA ID:	CAR000053587
Trans Name:	JEM INDUSTRIES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	DEMENNO KERDOON
TSDF Alt EPA ID:	CAT080013352
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D001
Meth Code:	- Not reported
Quantity Tons:	2.205
Waste Quantity:	525
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HWTS:

Name:	VERNOLA RANCH
Address:	12080 BELLEGRAVE AVE
Address 2:	Not reported
City,State,Zip:	MIRA LOMA, CA 91752
EPA ID:	CAC002583200
Inactive Date:	06/21/2005
Create Date:	10/19/2004
Last Act Date:	06/21/2005
Mailing Name:	Not reported
Mailing Address:	12080 BELLEGRAVE AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	MIRA LOMA, CA 91752
Owner Name:	ANTHONY VERNOLA
Owner Address:	12080 BELLEGRAVE AVE

VERNOLA RANCH (Continued) **S112941096**

Owner Address 2:	Not reported
Owner City,State,Zip:	MIRA LOMA, CA 91752
Contact Name:	ANTHONY VERNOLA
Contact Address:	12080 BELLEGRAVE AVE
Contact Address 2:	Not reported
City,State,Zip:	MIRA LOMA, CA 91752
Name:	VERNOLA RANCH
Address:	12080 BELLEGRAVE AVE
Address 2:	Not reported
City,State,Zip:	MIRA LOMA, CA 917520000
EPA ID:	CAL000191701
Inactive Date:	06/30/2002
Create Date:	07/31/2000
Last Act Date:	04/24/2003
Mailing Name:	MGR
Mailing Address:	12080 BELLEGRAVE AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	MIRA LOMA, CA 917520000
Owner Name:	ANTHONY P VERNOLA
Owner Address:	12080 BELLEGRAVE
Owner Address 2:	Not reported
Owner City,State,Zip:	MIRA LOMA, CA 917520000
Contact Name:	CHERRIE BURKE/MGR
Contact Address:	12080 BELLEGRAVE AVE
Contact Address 2:	Not reported
City,State,Zip:	MIRA LOMA, CA 917520000

A6 **VERNOLA RANCH** **UST** **U002095767**
Target **12080 BELLEGRAVE AVE.** **N/A**
Property **MIRA LOMA, CA 91752**

Site 6 of 6 in cluster A

Actual:
689 ft.

UST:

Name:	VERNOLA RANCH
Address:	12080 BELLEGRAVE AVE.
City,State,Zip:	MIRA LOMA, CA 91752
Facility ID:	81649
Permitting Agency:	RIVERSIDE COUNTY
Latitude:	33.992228
Longitude:	-117.545281

---

7 **HARVEST** **CIWQS** **S113450185**
NW OF LIMONITE AVE AND WINEVILLE AVE **N/A**
< 1/8 **MIRA LOMA, CA 92509**
1 ft.

CIWQS:

Relative:
Lower

Actual:
686 ft.

Name:	HARVEST
Address:	NW OF LIMONITE AVE AND WINEVILLE AVE
City,State,Zip:	MIRA LOMA, CA 92509
Agency:	McCune and Associates Inc
Agency Address:	PO Box 1295, Corona, CA 92878
Place/Project Type:	Construction - Residential
SIC/NAICS:	Not reported

HARVEST (Continued) **S113450185**

Region:	8
Program:	CONSTW
Regulatory Measure Status:	Terminated
Regulatory Measure Type:	Storm water construction
Order Number:	2009-0009-DWQ
WDID:	8 33C366081
NPDES Number:	CAS000002
Adoption Date:	Not reported
Effective Date:	04/08/2013
Termination Date:	11/23/2015
Expiration/Review Date:	Not reported
Design Flow:	Not reported
Major/Minor:	Not reported
Complexity:	Not reported
TTWQ:	Not reported
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	33.98406
Longitude:	-117.545213

8
NNE
< 1/8
0.108 mi.
568 ft.

ELEMENTARY SCHOOL NO. 17 **ENVIROSTOR** **S118756715**
WINEVILLE ROAD/BELLGRAVE AVENUE **SCH** **N/A**
MIRA LOMA, CA 91752

Relative:
Higher

Actual:
695 ft.

ENVIROSTOR:

Name:	ELEMENTARY SCHOOL NO. 17
Address:	WINEVILLE ROAD/BELLGRAVE AVENUE
City,State,Zip:	MIRA LOMA, CA 91752
Facility ID:	33010071
Status:	No Action Required
Status Date:	10/04/2002
Site Code:	404382
Site Type:	School Investigation
Site Type Detailed:	School
Acres:	10
NPL:	NO
Regulatory Agencies:	DTSC
Lead Agency:	DTSC
Program Manager:	Not reported
Supervisor:	Shahir Haddad
Division Branch:	Southern California Schools & Brownfields Outreach
Assembly:	60
Senate:	31
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	School District
Latitude:	33.9904
Longitude:	-117.5422
APN:	NONE SPECIFIED
Past Use:	AGRICULTURAL - ROW CROPS
Potential COC:	Arsenic Aldrin DDT
Confirmed COC:	NONE SPECIFIED
Potential Description:	NMA
Alias Name:	ELEMENTARY SCHOOL #17
Alias Type:	Alternate Name

ELEMENTARY SCHOOL NO. 17 (Continued) **S118756715**

Alias Name:	JURUPA UNIFIED SCHOOL DISTRICT
Alias Type:	Alternate Name
Alias Name:	JURUPA USD-PROPOSED ELEM # 17 SCHOOL
Alias Type:	Alternate Name
Alias Name:	404382
Alias Type:	Project Code (Site Code)
Alias Name:	33010071
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	10/08/2002
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	10/04/2002
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Phase 1
Completed Date:	10/04/2002
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

SCH:

Name:	ELEMENTARY SCHOOL NO. 17
Address:	WINEVILLE ROAD/BELLGRAVE AVENUE
City,State,Zip:	MIRA LOMA, CA 91752
Facility ID:	33010071
Site Type:	School Investigation
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	10
National Priorities List:	NO
Cleanup Oversight Agencies:	DTSC
Lead Agency:	DTSC
Lead Agency Description:	* DTSC
Project Manager:	Not reported
Supervisor:	Shahir Haddad
Division Branch:	Southern California Schools & Brownfields Outreach
Site Code:	404382
Assembly:	60

ELEMENTARY SCHOOL NO. 17 (Continued) **S118756715**

Senate:	31
Special Program Status:	Not reported
Status:	No Action Required
Status Date:	10/04/2002
Restricted Use:	NO
Funding:	School District
Latitude:	33.9904
Longitude:	-117.5422
APN:	NONE SPECIFIED
Past Use:	AGRICULTURAL - ROW CROPS
Potential COC:	Arsenic, Arsenic, Aldrin, DDT
Confirmed COC:	NONE SPECIFIED
Potential Description:	NMA
Alias Name:	ELEMENTARY SCHOOL #17
Alias Type:	Alternate Name
Alias Name:	JURUPA UNIFIED SCHOOL DISTRICT
Alias Type:	Alternate Name
Alias Name:	JURUPA USD-PROPOSED ELEM # 17 SCHOOL
Alias Type:	Alternate Name
Alias Name:	404382
Alias Type:	Project Code (Site Code)
Alias Name:	33010071
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	10/08/2002
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Inspections/Visit (Non LUR)
Completed Date:	10/04/2002
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Phase 1
Completed Date:	10/04/2002
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

B9 **KOHL'S INC - STORE #1032** **RCRA NonGen / NLR** **1024827207**
SSW **12315 LIMONITE AVE** **CAL000356232**
1/8-1/4 **MIRA LOMA, CA 91752**
0.163 mi.
859 ft. **Site 1 of 2 in cluster B**

Relative: **Lower**
Actual: **674 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-06-04 00:00:00.0
Handler Name:	KOHL'S INC - STORE #1032	
Handler Address:		12315 LIMONITE AVE
Handler City,State,Zip:		MIRA LOMA, CA 91752
EPA ID:		CAL000356232
Contact Name:		RYAN PIEDOT
Contact Address:		W17000 RIDGEWOOD DR
Contact City,State,Zip:		MENOMONEE FALLS, WI 53051
Contact Telephone:		262-703-7019
Contact Fax:		Not reported
Contact Email:		RYAN.PIEDOT@KOHLS.COM
Contact Title:		SR MANAGER OF ENVIRONMENTAL COMPLIANCE
EPA Region:		09
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3156
Mailing City,State,Zip:		MILWAUKEE, WI 53201-0000
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		KOHL'S INC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

KOHL'S INC - STORE #1032 (Continued) **1024827207**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-06-09 16:19:23.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KOHL'S DEPARTMENT STORES
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	N56 W17000 RIDGEWOOD DR
Owner/Operator City,State,Zip:	MENOMONEE FALLS, WI 53051-0000
Owner/Operator Telephone:	262-703-7019
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	RYAN PIEDOT
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	N56 W17000 RIDGEWOOD DRIVE
Owner/Operator City,State,Zip:	MENOMONEE FALLS, WI 53051
Owner/Operator Telephone:	262-703-7019
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

KOHL'S INC - STORE #1032 (Continued) **1024827207**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	KOHL'S INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	N56 W17000 RIDGEWOOD DR
Owner/Operator City,State,Zip:	MENOMONEE FALLS, WI 53051
Owner/Operator Telephone:	262-703-7019
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2010-08-26 00:00:00.0
Handler Name:	KOHL'S DEPARTMENT STORES INC #1032
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2020-06-04 00:00:00.0
Handler Name:	KOHL'S INC - STORE #1032
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	45211
NAICS Description:	DEPARTMENT STORES

NAICS Code:	45221
NAICS Description:	DEPARTMENT STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

B10 **KOHL'S INC - STORE #1032** **CERS HAZ WASTE** **S118937075**
SSW **12315 LIMONITE AVE** **HAZNET** **N/A**
1/8-1/4 **MIRA LOMA, CA 91752** **CERS**
0.163 mi. **HWTS**
859 ft. **Site 2 of 2 in cluster B**

Relative:
Lower

Actual:
674 ft.

CERS HAZ WASTE:

Name:	KOHL'S, INC. - STORE #1032
Address:	12315 LIMONITE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Site ID:	275908
CERS ID:	10629625
CERS Description:	Hazardous Waste Generator

HAZNET:

Name:	KOHL'S DEPARTMENT STORES INC #1032
Address:	12315 LIMONITE AVE
Address 2:	Not reported
City,State,Zip:	MIRA LOMA, CA 532010000
Contact:	RYAN PIEDOT
Telephone:	2627037019
Mailing Name:	Not reported
Mailing Address:	P.O. BOX 3155
Year:	2019
Gepaid:	CAL000356232
TSD EPA ID:	CAD044429835
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.06100
Year:	2019
Gepaid:	CAL000356232
TSD EPA ID:	CAD028409019
CA Waste Code:	352 - Other organic solids
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.15000
Year:	2019
Gepaid:	CAL000356232
TSD EPA ID:	CAD008364432
CA Waste Code:	291 - Latex waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.15250
Year:	2019
Gepaid:	CAL000356232
TSD EPA ID:	CAD008364432
CA Waste Code:	281 - Adhesives
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.10050
Year:	2018
Gepaid:	CAL000356232
TSD EPA ID:	CAD044429835

KOHL'S INC - STORE #1032 (Continued) **S118937075**

CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.09400
Year:	2017
Gepaid:	CAL000356232
TSD EPA ID:	NED981723513
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.17
Year:	2016
Gepaid:	CAL000356232
TSD EPA ID:	NED981723513
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.12
Year:	2015
Gepaid:	CAL000356232
TSD EPA ID:	NED981723513
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.015

Additional Info:

Year:	2017
Gen EPA ID:	CAL000356232
Shipment Date:	20170613
Creation Date:	7/10/2018 18:30:28
Receipt Date:	20170623
Manifest ID:	010226385FLE
Trans EPA ID:	MAD039322250
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES INC
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.03
Waste Quantity:	60
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170411
Creation Date:	5/11/2018 18:34:42

KOHL'S INC - STORE #1032 (Continued) **S118937075**

Receipt Date:	20170417
Manifest ID:	010341343FLE
Trans EPA ID:	MAD039322250
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICE INC
Trans 2 EPA ID:	MOR000501973
Trans 2 Name:	R&R TRUCKING
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICE INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.11
Waste Quantity:	220
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20170207
Creation Date:	5/9/2018 18:31:57
Receipt Date:	20170210
Manifest ID:	010338091FLE
Trans EPA ID:	MAD039322250
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICE INC
Trans 2 EPA ID:	MOR000501973
Trans 2 Name:	R & R TRUCKING
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICE INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.03
Waste Quantity:	60
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2016
Gen EPA ID:	CAL000356232

Shipment Date:	20151020
Creation Date:	5/4/2016 22:16:02
Receipt Date:	20151026
Manifest ID:	008302667FLE
Trans EPA ID:	MAD039322250
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICE INC
Trans 2 EPA ID:	CAR000187922

KOHL'S INC - STORE #1032 (Continued) **S118937075**

Trans 2 Name:	RUST & SON'S TRUCKING INC
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICE INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.0125
Waste Quantity:	25
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20150818
Creation Date:	2/9/2016 22:16:04
Receipt Date:	20150824
Manifest ID:	008817523FLE
Trans EPA ID:	MAD039322250
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES INC
Trans 2 EPA ID:	NJD986607380
Trans 2 Name:	MAUMEE EXPRESS INC
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENV SERVICES INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.0025
Waste Quantity:	5
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2015
Gen EPA ID:	CAL000356232

Shipment Date:	20151020
Creation Date:	5/4/2016 22:16:02
Receipt Date:	20151026
Manifest ID:	008302667FLE
Trans EPA ID:	MAD039322250
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICE INC
Trans 2 EPA ID:	CAR000187922
Trans 2 Name:	RUST & SON'S TRUCKING INC
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICE INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported

KOHL'S INC - STORE #1032 (Continued) **S118937075**

Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.0125
Waste Quantity:	25
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20150818
Creation Date:	2/9/2016 22:16:04
Receipt Date:	20150824
Manifest ID:	008817523FLE
Trans EPA ID:	MAD039322250
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES INC
Trans 2 EPA ID:	NJD986607380
Trans 2 Name:	MAUMEE EXPRESS INC
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENV SERVICES INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.0025
Waste Quantity:	5
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

CERS:

Name:	KOHL'S, INC. - STORE #1032
Address:	12315 LIMONITE AVE
City,State,Zip:	MIRA LOMA, CA 91752
Site ID:	275908
CERS ID:	10629625
CERS Description:	Chemical Storage Facilities

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	08-30-2018
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Riverside County Department of Env Health
Eval Program:	HW
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	11-09-2015
Violations Found:	No

KOHL'S INC - STORE #1032 (Continued) **S118937075**

Eval Type:	Routine done by local agency
Eval Notes:	generator inspection @ Kohl's
Eval Division:	Riverside County Department of Env Health
Eval Program:	HW
Eval Source:	CERS

Coordinates:

Site ID:	275908
Facility Name:	Kohl's, Inc. - Store #1032
Env Int Type Code:	HWG
Program ID:	10629625
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	33.975270
Longitude:	-117.552070

Affiliation:

Affiliation Type Desc:	CUPA District
Entity Name:	Riverside Cnty Env Health
Entity Title:	Not reported
Affiliation Address:	4065 County Circle Drive, Room 104
Affiliation City:	Riverside
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92503
Affiliation Phone:	(951) 358-5055

Affiliation Type Desc:	Document Preparer
Entity Name:	Scott Smith
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	P.O. Box 3155
Affiliation City:	Milwaukee
Affiliation State:	WI
Affiliation Country:	Not reported
Affiliation Zip:	53201
Affiliation Phone:	Not reported

Affiliation Type Desc:	Identification Signer
Entity Name:	Ryan Piedot
Entity Title:	Sr. Manager of Environmental Compliance
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

KOHL'S INC - STORE #1032 (Continued) **S118937075**

Affiliation Type Desc:	Operator
Entity Name:	Kohl's, Inc. - Store #1032
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(262) 703-7019

Affiliation Type Desc:	Environmental Contact
Entity Name:	Ryan Piedot
Entity Title:	Not reported
Affiliation Address:	P.O. Box 3155
Affiliation City:	Milwaukee
Affiliation State:	WI
Affiliation Country:	Not reported
Affiliation Zip:	53201
Affiliation Phone:	Not reported

Affiliation Type Desc:	Legal Owner
Entity Name:	Kohl's, Inc.
Entity Title:	Not reported
Affiliation Address:	P.O. Box 3155
Affiliation City:	Milwaukee
Affiliation State:	WI
Affiliation Country:	United States
Affiliation Zip:	53201
Affiliation Phone:	(262) 703-7019

Affiliation Type Desc:	Parent Corporation
Entity Name:	Kohl's, Inc.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

HWTS:

Name:	KOHL'S INC - STORE #1032
Address:	12315 LIMONITE AVE
Address 2:	Not reported
City,State,Zip:	MIRA LOMA, CA 91752
EPA ID:	CAL000356232
Inactive Date:	Not reported
Create Date:	08/26/2010
Last Act Date:	08/13/2020
Mailing Name:	Not reported
Mailing Address:	PO BOX 3156
Mailing Address 2:	Not reported
Mailing City,State,Zip:	MILWAUKEE, WI 532010000
Owner Name:	KOHL'S INC
Owner Address:	N56 W17000 RIDGEWOOD DR
Owner Address 2:	Not reported

KOHL'S INC - STORE #1032 (Continued) **S118937075**

Owner City,State,Zip: MENOMONEE FALLS, WI 530510000
Contact Name: RYAN PIEDOT
Contact Address: N56 W17000 RIDGEWOOD DRIVE
Contact Address 2: Not reported
City,State,Zip: MENOMONEE FALLS, WI 53051

NAICS:
EPA ID: CAL000356232
Create Date: 2010-08-26 11:45:53.170
NAICS Code: 45211
NAICS Description: Department Stores
Issued EPA ID Date: 2010-08-26 11:45:53.17000
Inactive Date: Not reported
Facility Name: KOHL'S INC - STORE #1032
Facility Address: 12315 LIMONITE AVE
Facility Address 2: Not reported
Facility City: MIRA LOMA
Facility County: Not reported
Facility State: CA
Facility Zip: 91752

11
NE
1/8-1/4
0.165 mi.
869 ft.

Relative:
Higher

Actual:
694 ft.

WELL II-7 **PFAS** **S127520108**
JURUPA VALLEY, CA **N/A**

PFAS:
Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported

WELL II-7 (Continued) **S127520108**

City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported

WELL II-7 (Continued) **S127520108**

Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported

WELL II-7 (Continued) **S127520108**

Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported

WELL II-7 (Continued) **S127520108**

Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported

WELL II-7 (Continued) **S127520108**

Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported

WELL II-7 (Continued) **S127520108**

Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

WELL II-7 (Continued) **S127520108**

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals

WELL II-7 (Continued) **S127520108**

Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-7 (Continued) **S127520108**

Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989357
Longitude:	-117.541095
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989357
Longitude:	-117.541095
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA

WELL II-7 (Continued) **S127520108**

Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989357
Longitude:	-117.541095
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989357
Longitude:	-117.541095
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported

WELL II-7 (Continued) **S127520108**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-7 (Continued) **S127520108**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-7 (Continued) **S127520108**

Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989357
Longitude:	-117.541095
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989357
Longitude:	-117.541095
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported

WELL II-7 (Continued) **S127520108**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-7 (Continued) **S127520108**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-7 (Continued) **S127520108**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357

WELL II-7 (Continued) **S127520108**

Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-7 (Continued) **S127520108**

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-7 (Continued) **S127520108**

Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989357
Longitude:	-117.541095
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989357
Longitude:	-117.541095
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-7
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported

WELL II-7 (Continued) **S127520108**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-7 (Continued) **S127520108**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-7 (Continued) **S127520108**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-7 (Continued) **S127520108**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-7 (Continued) **S127520108**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-7 (Continued) **S127520108**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357

WELL II-7 (Continued) **S127520108**

Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-7 (Continued) **S127520108**

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-7 (Continued) **S127520108**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-7 (Continued) **S127520108**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-7 (Continued) **S127520108**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-7 (Continued) **S127520108**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-7 (Continued) **S127520108**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-7 (Continued) **S127520108**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-7 (Continued) **S127520108**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-7
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989357
Longitude: -117.541095
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

12
ENE
1/8-1/4
0.165 mi.
869 ft.

WELL II-8 **PFAS** **S127520101**
N/A

JURUPA VALLEY, CA

Relative:
Higher

Actual:
691 ft.

PFAS:
Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-8 (Continued) **S127520101**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-8 (Continued) **S127520101**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394

WELL II-8 (Continued) **S127520101**

Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-8 (Continued) **S127520101**

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-8 (Continued) **S127520101**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-8 (Continued) **S127520101**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-8 (Continued) **S127520101**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-8 (Continued) **S127520101**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-8 (Continued) **S127520101**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-8 (Continued) **S127520101**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-8 (Continued) **S127520101**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394

WELL II-8 (Continued) **S127520101**

Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-8 (Continued) **S127520101**

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-8 (Continued) **S127520101**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-8 (Continued) **S127520101**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-8 (Continued) **S127520101**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-8 (Continued) **S127520101**

Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.986394
Longitude:	-117.541066
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-8
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.986394
Longitude:	-117.541066
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-8
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported

WELL II-8 (Continued) **S127520101**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-8 (Continued) **S127520101**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-8 (Continued) **S127520101**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394

WELL II-8 (Continued) **S127520101**

Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-8 (Continued) **S127520101**

Name:	WELL II-8
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.986394
Longitude:	-117.541066
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-8
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.986394
Longitude:	-117.541066
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-8
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA

WELL II-8 (Continued) **S127520101**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-8 (Continued) **S127520101**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-8 (Continued) **S127520101**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-8 (Continued) **S127520101**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-8 (Continued) **S127520101**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-8 (Continued) **S127520101**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-8 (Continued) **S127520101**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394

WELL II-8 (Continued) **S127520101**

Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-8 (Continued) **S127520101**

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-8 (Continued) **S127520101**

Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.986394
Longitude:	-117.541066
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-8
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.986394
Longitude:	-117.541066
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-8
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported

WELL II-8 (Continued) **S127520101**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-8 (Continued) **S127520101**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-8
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.986394
Longitude: -117.541066
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

13
NW
1/8-1/4
0.192 mi.
1015 ft.

HOMECOMING AT EASTVALE APARTMENTS **RCRA NonGen / NLR** **1024850878**
5464 W HOMECOMING CIR **CAL000408912**
EASTVALE, CA 91752

Relative:
Higher

Actual:
698 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 2015-07-31 00:00:00.0
Handler Name: HOMECOMING AT EASTVALE APARTMENTS
Handler Address: 5464 W HOMECOMING CIR
Handler City,State,Zip: EASTVALE, CA 91752
EPA ID: CAL000408912
Contact Name: ALLEN BENNETT

HOMECOMING AT EASTVALE APARTMENTS (Continued) **1024850878**

Contact Address:	5464 W HOMECOMING CIR
Contact City,State,Zip:	EASTVALE, CA 91752
Contact Telephone:	909-360-9800
Contact Fax:	909-360-9801
Contact Email:	ALLEN.BENNETT@LEWISMC.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1156 N MOUNTAIN AVE
Mailing City,State,Zip:	UPLAND, CA 91786
Owner Name:	HOMECOMING II AT EASTVALE LLC
Owner Type:	Other
Operator Name:	ALLEN BENNETT
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking

HOMECOMING AT EASTVALE APARTMENTS (Continued) **1024850878**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-06 17:06:27.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ALLEN BENNETT
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	5464 W HOMECOMING CIR
Owner/Operator City,State,Zip:	EASTVALE, CA 91752
Owner/Operator Telephone:	909-360-9800
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	HOMECOMING II AT EASTVALE LLC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	5464 W HOMECOMING CIR
Owner/Operator City,State,Zip:	EASTVALE, CA 91752
Owner/Operator Telephone:	909-949-6717
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2015-07-31 00:00:00.0
Handler Name:	HOMECOMING AT EASTVALE APARTMENTS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

HOMECOMING AT EASTVALE APARTMENTS (Continued) **1024850878**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 53111
NAICS Description: LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

14
NNE
1/8-1/4
0.242 mi.
1279 ft.

WELL II-6 **PFAS** **S127520111**
JURUPA VALLEY, CA **N/A**

Relative:
Higher

Actual:
712 ft.

PFAS:
Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported

WELL II-6 (Continued) **S127520111**

Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083

WELL II-6 (Continued) **S127520111**

Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported

WELL II-6 (Continued) **S127520111**

Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported

WELL II-6 (Continued) **S127520111**

Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

WELL II-6 (Continued) **S127520111**

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals

WELL II-6 (Continued) **S127520111**

Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-6 (Continued) **S127520111**

Name:	WELL II-6
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.993696
Longitude:	-117.540961
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-6
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.993696
Longitude:	-117.540961
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-6
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA

WELL II-6 (Continued) **S127520111**

Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.993696
Longitude:	-117.540961
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-6
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.993696
Longitude:	-117.540961
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-6
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported

WELL II-6 (Continued) **S127520111**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-6 (Continued) **S127520111**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-6 (Continued) **S127520111**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-6 (Continued) **S127520111**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-6 (Continued) **S127520111**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-6 (Continued) **S127520111**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696

WELL II-6 (Continued) **S127520111**

Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-6 (Continued) **S127520111**

Name:	WELL II-6
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.993696
Longitude:	-117.540961
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-6
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.993696
Longitude:	-117.540961
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-6
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA

WELL II-6 (Continued) **S127520111**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-6 (Continued) **S127520111**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-6 (Continued) **S127520111**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-6 (Continued) **S127520111**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-6 (Continued) **S127520111**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-6 (Continued) **S127520111**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-6 (Continued) **S127520111**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696

WELL II-6 (Continued) **S127520111**

Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-6 (Continued) **S127520111**

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-6 (Continued) **S127520111**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-6 (Continued) **S127520111**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-6 (Continued) **S127520111**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-6 (Continued) **S127520111**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-6 (Continued) **S127520111**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-6 (Continued) **S127520111**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-6 (Continued) **S127520111**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696

WELL II-6 (Continued) **S127520111**

Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-6 (Continued) **S127520111**

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-6 (Continued) **S127520111**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-6 (Continued) **S127520111**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-6 (Continued) **S127520111**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-6 (Continued) **S127520111**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-6 (Continued) **S127520111**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-6 (Continued) **S127520111**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-6 (Continued) **S127520111**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696

WELL II-6 (Continued) **S127520111**

Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-6
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.993696
Longitude: -117.540961
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

C15 **SWAN LAKE TEXACO** **Notify 65** **S100178727**
WSW **5800 HAMMER AVENUE** **N/A**
1/4-1/2 **MIRA LOMA, CA 91752**
0.307 mi.
1623 ft. **Site 1 of 2 in cluster C**

Relative:
Lower

Actual:
677 ft.

NOTIFY 65:

Name:	SWAN LAKE TEXACO
Address:	5800 HAMMER AVENUE
City,State,Zip:	MIRA LOMA, CA 91752-1558
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

C16 **TEXACO SWAN LAKE** **LUST** **S103990108**
WSW **5800 HAMNER AVE** **Cortese** **N/A**
1/4-1/2 **MIRA LOMA, CA 92408** **HIST CORTESE**
0.307 mi. **NPDES**
1623 ft. **Site 2 of 2 in cluster C** **CERS**

Relative:
Lower

Actual:
677 ft.

LUST:

Name:	TEXACO SWAN LAKE
Address:	5800 HAMNER AVE
City,State,Zip:	MIRA LOMA, CA 92408
Lead Agency:	RIVERSIDE COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0606500101
Global Id:	T0606500101
Latitude:	33.9791212747641
Longitude:	-117.554013127647
Status:	Completed - Case Closed
Status Date:	12/12/1991
Case Worker:	RIV
RB Case Number:	083301026T
Local Agency:	RIVERSIDE COUNTY LOP
File Location:	Local Agency Warehouse
Local Case Number:	89159
Potential Media Affect:	Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0606500101
Contact Type:	Regional Board Caseworker
Contact Name:	ROSE SCOTT
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 MAIN STREET, SUITE 500
City:	RIVERSIDE
Email:	rose.scott@waterboards.ca.gov
Phone Number:	9513206375

Global Id:	T0606500101
Contact Type:	Local Agency Caseworker
Contact Name:	Riverside County LOP

TEXACO SWAN LAKE (Continued) **S103990108**

Organization Name: RIVERSIDE COUNTY LOP
Address: 3880 LEMON ST SUITE 200
City: RIVERSIDE
Email: Not reported
Phone Number: 9519558980

LUST:
Global Id: T0606500101
Action Type: RESPONSE
Date: 08/23/1988
Action: Unauthorized Release Form

Global Id: T0606500101
Action Type: ENFORCEMENT
Date: 03/08/2009
Action: File review - #RCDEH Upload Site File 9/11/2015

Global Id: T0606500101
Action Type: ENFORCEMENT
Date: 12/12/1991
Action: Closure/No Further Action Letter - #Site Closure

Global Id: T0606500101
Action Type: Other
Date: 08/08/1988
Action: Leak Reported

Global Id: T0606500101
Action Type: ENFORCEMENT
Date: 12/12/1991
Action: Closure/No Further Action Letter

Global Id: T0606500101
Action Type: ENFORCEMENT
Date: 03/27/1989
Action: Notice of Reimbursement

LUST:
Global Id: T0606500101
Status: Open - Case Begin Date
Status Date: 08/08/1988

Global Id: T0606500101
Status: Open - Site Assessment
Status Date: 09/26/1988

Global Id: T0606500101
Status: Open - Site Assessment
Status Date: 09/12/1989

Global Id: T0606500101
Status: Open - Remediation
Status Date: 02/15/1990

Global Id: T0606500101
Status: Completed - Case Closed

TEXACO SWAN LAKE (Continued) **S103990108**

Status Date: 12/12/1991

LUST REG 8:

Name:	TEXACO SERVICE STATION
Address:	5800 HAMNER AVE
City:	MIRA LOMA
Region:	8
County:	Riverside
Regional Board:	Santa Ana Region
Facility Status:	Case Closed
Case Number:	083301026T
Local Case Num:	89159
Case Type:	Soil only
Substance:	Gasoline
Qty Leaked:	Not reported
Abate Method:	No Action Required - incident is minor, requiring no remedial action
Cross Street:	BELLEGRAVE
Enf Type:	Not reported
Funding:	State Funds
How Discovered:	Tank Closure
How Stopped:	Not reported
Leak Cause:	UNK
Leak Source:	UNK
Global ID:	T0606500101
How Stopped Date:	Not reported
Enter Date:	9/26/1988
Date Confirmation of Leak Began:	Not reported
Date Preliminary Assessment Began:	9/12/1989
Discover Date:	Not reported
Enforcement Date:	Not reported
Close Date:	12/12/1991
Date Prelim Assessment Workplan Submitted:	Not reported
Date Pollution Characterization Began:	9/26/1988
Date Remediation Plan Submitted:	2/15/1990
Date Remedial Action Underway:	Not reported
Date Post Remedial Action Monitoring:	Not reported
Enter Date:	9/26/1988
GW Qualifies:	Not reported
Soil Qualifies:	Not reported
Operator:	Not reported
Facility Contact:	Not reported
Interim:	Not reported
Oversite Program:	LUST
Latitude:	33.9824966
Longitude:	-117.5583253
MTBE Date:	Not reported
Max MTBE GW:	Not reported
MTBE Concentration:	0
Max MTBE Soil:	Not reported
MTBE Fuel:	1
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
MTBE Class:	*
Staff:	RS
Staff Initials:	UNK
Lead Agency:	Local Agency
Local Agency:	33000L

TEXACO SWAN LAKE (Continued) **S103990108**

Hydr Basin #: UPPER SANTA ANA VALL
Beneficial: Not reported
Priority: Not reported
Cleanup Fund Id: Not reported
Work Suspended: Not reported
Summary: Not reported

RIVERSIDE CO. LUST:
Name: TEXACO SWAN LAKE
Address: 5800 HAMNER AVE
City,State,Zip: MIRA LOMA, CA
Region: RIVERSIDE
Facility ID: 89159
Employee: Boltinghous-LOP
Site Closed: Yes
Case Type: Soil only
Facility Status: closed/action completed
Casetype Decode: Soil only is impacted
Fstatus Decode: Closed/Action completed

CORTESE:
Name: TEXACO SWAN LAKE
Address: 5800 HAMNER AVE
City,State,Zip: MIRA LOMA, CA 92408
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0606500101
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HIST CORTESE:
edr_fname: TEXACO SERVICE STATION
edr_fadd1: 5800 HAMNER
City,State,Zip: MIRA LOMA, CA 91752
Region: CORTESE
Facility County Code: 33
Reg By: LTNKA
Reg Id: 083301026T

TEXACO SWAN LAKE (Continued) **S103990108**

NPDES:

Name:	SWAN LAKE MOBILE HOME PARK
Address:	5800 HAMNER AVENUE
City,State,Zip:	MIRA LOMA, CA 91752
Facility Status:	Not reported
NPDES Number:	Not reported
Region:	Not reported
Agency Number:	Not reported
Regulatory Measure ID:	Not reported
Place ID:	Not reported
Order Number:	Not reported
WDID:	8 33IN602086
Regulatory Measure Type:	Industrial
Program Type:	Not reported
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Discharge Address:	Not reported
Discharge Name:	Not reported
Discharge City:	Not reported
Discharge State:	Not reported
Discharge Zip:	Not reported
Status:	Undetermined
Status Date:	07/26/2012
Operator Name:	Swan Lake Mobile home Park
Operator Address:	5800 Hamner Avenue
Operator City:	Mira Loma
Operator State:	California
Operator Zip:	91752

CERS:

Name:	TEXACO SWAN LAKE
Address:	5800 HAMNER AVE
City,State,Zip:	MIRA LOMA, CA 92408
Site ID:	232020
CERS ID:	T0606500101
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	Riverside County LOP - RIVERSIDE COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	3880 LEMON ST SUITE 200
Affiliation City:	RIVERSIDE
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	9519558980

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	ROSE SCOTT - SANTA ANA RWQCB (REGION 8)
Entity Title:	Not reported
Affiliation Address:	3737 MAIN STREET, SUITE 500
Affiliation City:	RIVERSIDE
Affiliation State:	CA
Affiliation Country:	Not reported

TEXACO SWAN LAKE (Continued) **S103990108**

Affiliation Zip: Not reported
Affiliation Phone: 9513206375

17
NNE
1/4-1/2
0.447 mi.
2359 ft.

WELL II-9A **PFAS** **S127520115**
N/A

JURUPA VALLEY, CA

Relative:
Higher

Actual:
723 ft.

PFAS:

Name:	WELL II-9A
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.995231
Longitude:	-117.537882
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-9A
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

WELL II-9A (Continued) **S127520115**

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals

WELL II-9A (Continued) **S127520115**

Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-9A (Continued) **S127520115**

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-9A (Continued) **S127520115**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-9A (Continued) **S127520115**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-9A (Continued) **S127520115**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-9A (Continued) **S127520115**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-9A (Continued) **S127520115**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-9A (Continued) **S127520115**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-9A (Continued) **S127520115**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231

WELL II-9A (Continued) **S127520115**

Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-9A (Continued) **S127520115**

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-9A (Continued) **S127520115**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-9A (Continued) **S127520115**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-9A (Continued) **S127520115**

Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported

WELL II-9A (Continued) **S127520115**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-9A (Continued) **S127520115**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-9A (Continued) **S127520115**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-9A (Continued) **S127520115**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231

WELL II-9A (Continued) **S127520115**

Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-9A (Continued) **S127520115**

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-9A (Continued) **S127520115**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-9A (Continued) **S127520115**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-9A (Continued) **S127520115**

Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.995231
Longitude:	-117.537882
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-9A
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.995231
Longitude:	-117.537882
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-9A
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported

WELL II-9A (Continued) **S127520115**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-9A (Continued) **S127520115**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-9A (Continued) **S127520115**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-9A (Continued) **S127520115**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231

WELL II-9A (Continued) **S127520115**

Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-9A (Continued) **S127520115**

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-9A (Continued) **S127520115**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-9A (Continued) **S127520115**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.995231
Longitude: -117.537882
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-9A
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-9A (Continued) **S127520115**

Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.995231
Longitude:	-117.537882
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-9A
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.995231
Longitude:	-117.537882
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-9A
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported

WELL II-9A (Continued) **S127520115**

Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.995231
Longitude:	-117.537882
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

D18
WNW
1/4-1/2
0.483 mi.
2549 ft.

WELL II-4 **PFAS** **S127520107**
JURUPA VALLEY, CA **N/A**
Site 1 of 2 in cluster D

Relative: Higher

Actual: 698 ft.

PFAS:

Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported

WELL II-4 (Continued) **S127520107**

Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported

WELL II-4 (Continued) **S127520107**

Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported

WELL II-4 (Continued) **S127520107**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-4 (Continued) **S127520107**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-4 (Continued) **S127520107**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151

WELL II-4 (Continued) **S127520107**

Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-4 (Continued) **S127520107**

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-4 (Continued) **S127520107**

Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported

WELL II-4 (Continued) **S127520107**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-4 (Continued) **S127520107**

Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported

WELL II-4 (Continued) **S127520107**

Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported

WELL II-4 (Continued) **S127520107**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-4 (Continued) **S127520107**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-4 (Continued) **S127520107**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151

WELL II-4 (Continued) **S127520107**

Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-4 (Continued) **S127520107**

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-4 (Continued) **S127520107**

Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported

WELL II-4 (Continued) **S127520107**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-4 (Continued) **S127520107**

Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported

WELL II-4 (Continued) **S127520107**

Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported

WELL II-4 (Continued) **S127520107**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-4 (Continued) **S127520107**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-4 (Continued) **S127520107**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151

WELL II-4 (Continued) **S127520107**

Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-4 (Continued) **S127520107**

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA

WELL II-4 (Continued) **S127520107**

Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported

WELL II-4 (Continued) **S127520107**

Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported

WELL II-4 (Continued) **S127520107**

Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported

WELL II-4 (Continued) **S127520107**

Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083
Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported

WELL II-4 (Continued) **S127520107**

File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported

WELL II-4 (Continued) **S127520107**

Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported

WELL II-4 (Continued) **S127520107**

RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151

WELL II-4 (Continued) **S127520107**

Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

Name: WELL II-4
Address: Not reported
City,State,Zip: JURUPA VALLEY, CA
Envirostor ID: Not reported
Program Type: Not reported
Status: Not reported
Status Date: Not reported
Enviroscreen Score: Not reported
Site Code: Not reported
Global ID: W0603310083
Facility Region: Not reported
Lead Agency: Not reported
Case worker: Not reported
Local Agency: Not reported
Location Case Number: Not reported
File Location: Not reported
Potential Contaminants of Concern: Not reported
Potential Media Affected: Not reported
Site History: Not reported

Begin Date: Not reported
RB Case Number: Not reported
source_type: All PFAS Chemicals
Latitude: 33.989151
Longitude: -117.557874
Geo Tracker URL: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

WELL II-4 (Continued) **S127520107**

Name:	WELL II-4
Address:	Not reported
City,State,Zip:	JURUPA VALLEY, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0603310083
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Latitude:	33.989151
Longitude:	-117.557874
Geo Tracker URL:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=W0603310083

---

19 **PROPOSED ELEMENTARY SCHOOL NO. 17** **ENVIROSTOR** **S117038704**
NE **NORTH OF BELLEGRAVE AVE & JURUPA RD** **SCH** **N/A**
1/2-1 **JURUPA VALLEY, CA 91752**
0.505 mi.
2668 ft.

Relative:
Higher

Actual:
725 ft.

ENVIROSTOR:

Name:	PROPOSED ELEMENTARY SCHOOL NO. 17
Address:	NORTH OF BELLEGRAVE AVE & JURUPA RD
City,State,Zip:	JURUPA VALLEY, CA 91752
Facility ID:	60002063
Status:	No Further Action
Status Date:	04/20/2015
Site Code:	404901
Site Type:	School Investigation
Site Type Detailed:	School
Acres:	10.7
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Scarlett Zhai
Supervisor:	Shahir Haddad
Division Branch:	Southern California Schools & Brownfields Outreach
Assembly:	60
Senate:	31
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	School District
Latitude:	33.99566
Longitude:	-117.5370

PROPOSED ELEMENTARY SCHOOL NO. 17 (Continued) **S117038704**

APN: NONE SPECIFIED
Past Use: AGRICULTURAL - LIVESTOCK, AGRICULTURAL - ROW CROPS
Potential COC: Under Investigation Methane
Confirmed COC: Under Investigation
Potential Description: SOIL, SV
Alias Name: 404901
Alias Type: Project Code (Site Code)
Alias Name: 60002063
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement Application
Completed Date: 08/19/2014
Comments: EOP Application received by mail 08/19/14.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 08/19/2014
Comments: Background Phase I Report received w/ EOP application by mail on 08/19/14.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Tech Memo
Completed Date: 12/03/2014
Comments: Conditional approval of PEA Workplan was granted.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 04/20/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 04/29/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 09/23/2014
Comments: Amit signs EOA; fully executed EOA sent (FedEx) to District.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

PROPOSED ELEMENTARY SCHOOL NO. 17 (Continued) **S117038704**

SCH:

Name:	PROPOSED ELEMENTARY SCHOOL NO. 17
Address:	NORTH OF BELLEGRAVE AVE & JURUPA RD
City,State,Zip:	JURUPA VALLEY, CA 91752
Facility ID:	60002063
Site Type:	School Investigation
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	10.7
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Scarlett Zhai
Supervisor:	Shahir Haddad
Division Branch:	Southern California Schools & Brownfields Outreach
Site Code:	404901
Assembly:	60
Senate:	31
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	04/20/2015
Restricted Use:	NO
Funding:	School District
Latitude:	33.99566
Longitude:	-117.5370
APN:	NONE SPECIFIED
Past Use:	AGRICULTURAL - LIVESTOCK, AGRICULTURAL - ROW CROPS
Potential COC:	Under Investigation, Methane
Confirmed COC:	Under Investigation
Potential Description:	SOIL, SV
Alias Name:	404901
Alias Type:	Project Code (Site Code)
Alias Name:	60002063
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement Application
Completed Date:	08/19/2014
Comments:	EOP Application received by mail 08/19/14.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Other Report
Completed Date:	08/19/2014
Comments:	Background Phase I Report received w/ EOP application by mail on 08/19/14.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Tech Memo
Completed Date:	12/03/2014
Comments:	Conditional approval of PEA Workplan was granted.

PROPOSED ELEMENTARY SCHOOL NO. 17 (Continued) **S117038704**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	04/20/2015
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	04/29/2015
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	09/23/2014
Comments:	Amit signs EOA; fully executed EOA sent (FedEx) to District.

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

D20 **PROPOSED K-8 SCHOOL NO. 2** **ENVIROSTOR** **S108054398**
WNW **5240 AND 5380 HAMNER AVENUE** **SCH** **N/A**
1/2-1 **MIRA LOMA, CA 91752**
0.510 mi.
2693 ft. **Site 2 of 2 in cluster D**

Relative: **Higher**
Actual: **697 ft.**

ENVIROSTOR:

Name:	PROPOSED K-8 SCHOOL NO. 2
Address:	5240 AND 5380 HAMNER AVENUE
City,State,Zip:	MIRA LOMA, CA 91752
Facility ID:	60000409
Status:	No Further Action
Status Date:	02/23/2007
Site Code:	404718
Site Type:	School Investigation
Site Type Detailed:	School
Acres:	16
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Not reported
Supervisor:	Shahir Haddad
Division Branch:	Southern California Schools & Brownfields Outreach
Assembly:	60
Senate:	31
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	School District
Latitude:	33.99648

PROPOSED K-8 SCHOOL NO. 2 (Continued) **S108054398**

Longitude: -117.5583
APN: 160-020-006, 160-020-007
Past Use: AGRICULTURAL - ROW CROPS
Potential COC: Arsenic Chlordane DDD DDE DDT Lead Methane
Confirmed COC: 30001-NO 30004-NO 30006-NO 30007-NO 30008-NO 30013-NO 30015-NO
Potential Description: SOIL
Alias Name: 160-020-006
Alias Type: APN
Alias Name: 160-020-007
Alias Type: APN
Alias Name: 404718
Alias Type: Project Code (Site Code)
Alias Name: 60000409
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 10/25/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 10/27/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/15/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 10/18/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 11/02/2006
Comments: Conditional approval letter for the investigation was sent out to the District and their consultant.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 02/23/2007
Comments: PEA Report for the site was approved and no further action determination was rendered.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 02/23/2007

PROPOSED K-8 SCHOOL NO. 2 (Continued) **S108054398**

Comments: CRU memo for the site was completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/06/2007
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 09/26/2006
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

SCH:

Name: PROPOSED K-8 SCHOOL NO. 2
Address: 5240 AND 5380 HAMNER AVENUE
City,State,Zip: MIRA LOMA, CA 91752
Facility ID: 60000409
Site Type: School Investigation
Site Type Detail: School
Site Mgmt. Req.: NONE SPECIFIED
Acres: 16
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Not reported
Supervisor: Shahir Haddad
Division Branch: Southern California Schools & Brownfields Outreach
Site Code: 404718
Assembly: 60
Senate: 31
Special Program Status: Not reported
Status: No Further Action
Status Date: 02/23/2007
Restricted Use: NO
Funding: School District
Latitude: 33.99648
Longitude: -117.5583
APN: 160-020-006, 160-020-007
Past Use: AGRICULTURAL - ROW CROPS
Potential COC: Arsenic, Chlordane, DDD, DDE, DDT, Lead, Methane
Confirmed COC: 30001-NO, 30004-NO, 30006-NO, 30007-NO, 30008-NO, 30013-NO, 30015-NO
Potential Description: SOIL
Alias Name: 160-020-006

PROPOSED K-8 SCHOOL NO. 2 (Continued) **S108054398**

Alias Type: APN
Alias Name: 160-020-007
Alias Type: APN
Alias Name: 404718
Alias Type: Project Code (Site Code)
Alias Name: 60000409
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 10/25/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 10/27/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 11/15/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 10/18/2006
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 11/02/2006
Comments: Conditional approval letter for the investigation was sent out to the District and their consultant.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 02/23/2007
Comments: PEA Report for the site was approved and no further action determination was rendered.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 02/23/2007
Comments: CRU memo for the site was completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 02/06/2007
Comments: Not reported

PROPOSED K-8 SCHOOL NO. 2 (Continued) **S108054398**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	09/26/2006
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

21
SSE
1/2-1
0.915 mi.
4832 ft.

PROPOSED LOUIS VANDERMOLEN ES **ENVIROSTOR** **S108214075**
6715 WINEVILLE AVENUE **SCH** **N/A**
MIRA LOMA, CA 91752

Relative:
Lower

Actual:
652 ft.

ENVIROSTOR:

Name:	PROPOSED LOUIS VANDERMOLEN ES
Address:	6715 WINEVILLE AVENUE
City,State,Zip:	MIRA LOMA, CA 91752
Facility ID:	33020007
Status:	No Further Action
Status Date:	02/20/2007
Site Code:	404632
Site Type:	School Investigation
Site Type Detailed:	School
Acres:	9.96
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Rana Georges
Supervisor:	Shahir Haddad
Division Branch:	Southern California Schools & Brownfields Outreach
Assembly:	60
Senate:	31
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	School District
Latitude:	33.96540
Longitude:	-117.5421
APN:	NONE SPECIFIED
Past Use:	AGRICULTURAL - LIVESTOCK
Potential COC:	Methane
Confirmed COC:	30015-NO
Potential Description:	SOIL
Alias Name:	PROPOSED EASTVALE ES 4
Alias Type:	Alternate Name
Alias Name:	404632
Alias Type:	Project Code (Site Code)
Alias Name:	33020007
Alias Type:	Envirostor ID Number

PROPOSED LOUIS VANDERMOLEN ES (Continued) **S108214075**

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	02/20/2007
Comments:	CRU completed and signed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	06/02/2005
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Workplan
Completed Date:	10/04/2005
Comments:	WP conditional approval, response to comments received 10/28
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	02/06/2006
Comments:	DTSC issued a conditional approval letter for "Futher Action" along with comments. Distirct will submit an SSI to further investigate methane.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Workplan
Completed Date:	03/28/2006
Comments:	DTSC issued a conditional approval for the SSI Workplan, comments were issued.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Report
Completed Date:	01/25/2007
Comments:	DTSC approved the SSI Report (methane soil gas survey) for No Further Action.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Fieldwork
Completed Date:	11/29/2006
Comments:	Fieldwork completed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	School Cleanup Agreement
Completed Date:	03/22/2006
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported

PROPOSED LOUIS VANDERMOLEN ES (Continued) **S108214075**

Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

SCH:

Name:	PROPOSED LOUIS VANDERMOLEN ES
Address:	6715 WINEVILLE AVENUE
City,State,Zip:	MIRA LOMA, CA 91752
Facility ID:	33020007
Site Type:	School Investigation
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	9.96
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Rana Georges
Supervisor:	Shahir Haddad
Division Branch:	Southern California Schools & Brownfields Outreach
Site Code:	404632
Assembly:	60
Senate:	31
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	02/20/2007
Restricted Use:	NO
Funding:	School District
Latitude:	33.96540
Longitude:	-117.5421
APN:	NONE SPECIFIED
Past Use:	AGRICULTURAL - LIVESTOCK
Potential COC:	Methane
Confirmed COC:	30015-NO
Potential Description:	SOIL
Alias Name:	PROPOSED EASTVALE ES 4
Alias Type:	Alternate Name
Alias Name:	404632
Alias Type:	Project Code (Site Code)
Alias Name:	33020007
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	02/20/2007
Comments:	CRU completed and signed.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Environmental Oversight Agreement
Completed Date:	06/02/2005
Comments:	Not reported

PROPOSED LOUIS VANDERMOLEN ES (Continued) **S108214075**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Workplan
Completed Date:	10/04/2005
Comments:	WP conditional approval, response to comments received 10/28

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	02/06/2006
Comments:	DTSC issued a conditional approval letter for "Futher Action" along with comments. Distirct will submit an SSI to further investigate methane.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Workplan
Completed Date:	03/28/2006
Comments:	DTSC issued a conditional approval for the SSI Workplan, comments were issued.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Report
Completed Date:	01/25/2007
Comments:	DTSC approved the SSI Report (methane soil gas survey) for No Further Action.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Fieldwork
Completed Date:	11/29/2006
Comments:	Fieldwork completed.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	School Cleanup Agreement
Completed Date:	03/22/2006
Comments:	Not reported

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

Count: 2 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
ONTARIO	1009508586	SO CAL GAS/ONTARIO MGP	CORNER OF CAMPUS, MARTLAND, MO	91761	EDR MGP
ONTARIO	S101481941	MILLIKEN SANITARY LANDFILL	INTERSECTION: MILLIKEN AVE & M	91761	ENVIROSTOR

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/04/2021
Date Made Active in Reports: 08/31/2021
Number of Days to Update: 27

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/04/2021
Date Made Active in Reports: 08/31/2021
Number of Days to Update: 27

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/04/2021
Date Made Active in Reports: 08/31/2021
Number of Days to Update: 27

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 06/24/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/04/2021
Date Made Active in Reports: 08/31/2021
Number of Days to Update: 27

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/04/2021
Date Made Active in Reports: 08/31/2021
Number of Days to Update: 27

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/13/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 82

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 08/05/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/17/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/23/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/17/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 08/23/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/14/2021
Date Data Arrived at EDR: 06/17/2021
Date Made Active in Reports: 08/17/2021
Number of Days to Update: 61

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 09/21/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

State- and tribal - equivalent NPL

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 04/23/2021
Date Data Arrived at EDR: 04/23/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 07/22/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 04/23/2021
Date Data Arrived at EDR: 04/23/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 07/22/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/11/2021
Date Made Active in Reports: 07/27/2021
Number of Days to Update: 77

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

LUST REG 9: Leaking Underground Storage Tank Report

Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

LUST: Leaking Underground Fuel Tank Report (GEOTRACKER)

Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

LUST REG 8: Leaking Underground Storage Tanks

California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

LUST REG 7: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 5: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

LUST REG 4: Underground Storage Tank Leak List

Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 3: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List
Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

LUST REG 1: Active Toxic Site Investigation
Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 6L: Leaking Underground Storage Tank Case Listing
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 05/17/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/06/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 06/01/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

CPS-SLIC: Statewide SLIC Cases (GEOTRACKER)
Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35
Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36
Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11
Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17
Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/29/2021
Date Data Arrived at EDR: 02/17/2021
Date Made Active in Reports: 03/22/2021
Number of Days to Update: 33
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Varies

UST: Active UST Facilities
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82
Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Semi-Annually

UST CLOSURE: Proposed Closure of Underground Storage Tank (UST) Cases

UST cases that are being considered for closure by either the State Water Resources Control Board or the Executive Director have been posted for a 60-day public comment period. UST Case Closures being proposed for consideration by the State Water Resources Control Board. These are primarily UST cases that meet closure criteria under the decisional framework in State Water Board Resolution No. 92-49 and other Board orders. UST Case Closures proposed for consideration by the Executive Director pursuant to State Water Board Resolution No. 2012-0061. These are cases that meet the criteria of the Low-Threat UST Case Closure Policy. UST Case Closure Review Denials and Approved Orders.

Date of Government Version: 05/20/2021
Date Data Arrived at EDR: 06/04/2021
Date Made Active in Reports: 08/30/2021
Number of Days to Update: 87

Source: State Water Resources Control Board
Telephone: 916-327-7844
Last EDR Contact: 09/08/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

MILITARY UST SITES: Military UST Sites (GEOTRACKER)

Military ust sites

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

AST: Aboveground Petroleum Storage Tank Facilities

A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 07/06/2016
Date Data Arrived at EDR: 07/12/2016
Date Made Active in Reports: 09/19/2016
Number of Days to Update: 69

Source: California Environmental Protection Agency
Telephone: 916-327-5092
Last EDR Contact: 09/09/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/06/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/17/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 06/01/2021
Date Data Arrived at EDR: 06/11/2021
Date Made Active in Reports: 09/07/2021
Number of Days to Update: 88

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 06/11/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 06/22/2021
Date Made Active in Reports: 09/20/2021
Number of Days to Update: 90

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 06/17/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 04/23/2021
Date Data Arrived at EDR: 04/23/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 07/22/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Considered Brownfieds Sites Listing
A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 06/17/2021
Date Data Arrived at EDR: 06/17/2021
Date Made Active in Reports: 09/13/2021
Number of Days to Update: 88

Source: State Water Resources Control Board
Telephone: 916-323-7905
Last EDR Contact: 09/21/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/10/2021
Date Data Arrived at EDR: 06/10/2021
Date Made Active in Reports: 08/17/2021
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/14/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: Waste Management Unit Database
Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: No Update Planned

SWRCY: Recycler Database
A listing of recycling facilities in California.

Date of Government Version: 06/04/2021
Date Data Arrived at EDR: 06/04/2021
Date Made Active in Reports: 08/27/2021
Number of Days to Update: 84

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 09/08/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing
A listing of registered waste tire haulers.

Date of Government Version: 11/23/2020
Date Data Arrived at EDR: 11/23/2020
Date Made Active in Reports: 02/08/2021
Number of Days to Update: 77

Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land
A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/18/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 77

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: No Update Planned

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 04/23/2021
Date Data Arrived at EDR: 04/23/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 07/22/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 01/20/2021
Date Made Active in Reports: 04/08/2021
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Varies

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

CERS HAZ WASTE: CERS HAZ WASTE

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: CalEPA
Telephone: 916-323-2514
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/18/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 77

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

A listing of PFAS contaminated sites included in the GeoTracker database.

Date of Government Version: 06/04/2021
Date Data Arrived at EDR: 06/04/2021
Date Made Active in Reports: 08/27/2021
Number of Days to Update: 84

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/08/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SAN FRANCISCO AST: Aboveground Storage Tank Site Listing

Aboveground storage tank sites

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/07/2021
Date Made Active in Reports: 07/23/2021
Number of Days to Update: 77

Source: San Francisco County Department of Public Health
Telephone: 415-252-3896
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/14/2021
Data Release Frequency: Varies

CA FID UST: Facility Inventory Database

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CERS TANKS: California Environmental Reporting System (CERS) Tanks

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

Local Land Records

LIENS: Environmental Liens Listing

A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 05/27/2021
Date Data Arrived at EDR: 05/28/2021
Date Made Active in Reports: 08/20/2021
Number of Days to Update: 84

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/04/2021
Date Made Active in Reports: 08/31/2021
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Semi-Annually

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 05/28/2021
Date Made Active in Reports: 08/20/2021
Number of Days to Update: 84

Source: DTSC and SWRCB
Telephone: 916-323-3400
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/12/2021
Date Data Arrived at EDR: 09/13/2021
Date Made Active in Reports: 09/28/2021
Number of Days to Update: 15

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 09/13/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

CHMIRS: California Hazardous Material Incident Report System
California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 04/04/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Semi-Annually

LDS: Land Disposal Sites Listing (GEOTRACKER)
Land Disposal sites (Landfills) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82

Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing (GEOTRACKER)
Military sites (consisting of: Military UST sites; Military Privatized sites; and Military Cleanup sites [formerly known as DoD non UST]) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch
Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated
RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/22/2021
Date Data Arrived at EDR: 03/23/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/04/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 85

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 08/06/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/13/2021
Date Data Arrived at EDR: 09/15/2021
Date Made Active in Reports: 09/28/2021
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 08/06/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/17/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/16/2021
Number of Days to Update: 87

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 07/19/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/04/2021
Date Made Active in Reports: 08/31/2021
Number of Days to Update: 27

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/07/2021
Date Data Arrived at EDR: 05/13/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 07/14/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 12/30/2020
Date Data Arrived at EDR: 01/14/2021
Date Made Active in Reports: 03/05/2021
Number of Days to Update: 50

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/19/2020
Date Data Arrived at EDR: 01/08/2021
Date Made Active in Reports: 03/22/2021
Number of Days to Update: 73

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/08/2021
Date Data Arrived at EDR: 03/11/2021
Date Made Active in Reports: 05/11/2021
Number of Days to Update: 61

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/14/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 12/01/2020
Date Made Active in Reports: 02/09/2021
Number of Days to Update: 70

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 09/03/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 08/06/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 09/27/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 07/23/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2021
Date Data Arrived at EDR: 07/14/2021
Date Made Active in Reports: 07/16/2021
Number of Days to Update: 2
Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 151
Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 09/15/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546
Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 10/05/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3
Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 07/23/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74
Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/12/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 07/29/2021
Date Data Arrived at EDR: 08/04/2021
Date Made Active in Reports: 08/31/2021
Number of Days to Update: 27
Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/03/2021
Date Data Arrived at EDR: 05/25/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 78

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 06/30/2021
Date Data Arrived at EDR: 07/01/2021
Date Made Active in Reports: 09/28/2021
Number of Days to Update: 89

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 09/09/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/26/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/26/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 06/15/2021
Date Data Arrived at EDR: 06/16/2021
Date Made Active in Reports: 08/17/2021
Number of Days to Update: 62

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/14/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 05/05/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 08/17/2021
Number of Days to Update: 91

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 08/26/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 06/26/2021
Date Data Arrived at EDR: 07/01/2021
Date Made Active in Reports: 09/28/2021
Number of Days to Update: 89

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 10/05/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 77

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/07/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/14/2021
Date Data Arrived at EDR: 05/14/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 81

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/13/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Quarterly

CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6

Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CORTESE: "Cortese" Hazardous Waste & Substances Sites List

The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 06/17/2021
Date Data Arrived at EDR: 06/17/2021
Date Made Active in Reports: 09/14/2021
Number of Days to Update: 89

Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 09/21/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

CUPA LIVERMORE-PLEASANTON: CUPA Facility Listing

list of facilities associated with the various CUPA programs in Livermore-Pleasanton

Date of Government Version: 05/01/2019
Date Data Arrived at EDR: 05/14/2019
Date Made Active in Reports: 07/17/2019
Number of Days to Update: 64

Source: Livermore-Pleasanton Fire Department
Telephone: 925-454-2361
Last EDR Contact: 08/13/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Varies

DRYCLEAN AVAQMD: Antelope Valley Air Quality Management District Drycleaner Listing

A listing of dry cleaners in the Antelope Valley Air Quality Management District.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 05/26/2021
Date Made Active in Reports: 08/18/2021
Number of Days to Update: 84

Source: Antelope Valley Air Quality Management District
Telephone: 661-723-8070
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Varies

DRYCLEAN SOUTH COAST: South Coast Air Quality Management District Drycleaner Listing

A listing of dry cleaners in the South Coast Air Quality Management District

Date of Government Version: 05/18/2021
Date Data Arrived at EDR: 05/19/2021
Date Made Active in Reports: 08/05/2021
Number of Days to Update: 78

Source: South Coast Air Quality Management District
Telephone: 909-396-3211
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Varies

DRYCLEANERS: Cleaner Facilities

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 05/28/2021
Date Made Active in Reports: 08/20/2021
Number of Days to Update: 84

Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Annually

EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 06/10/2021
Date Made Active in Reports: 08/27/2021
Number of Days to Update: 78

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 09/17/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: Varies

ENF: Enforcement Action Listing

A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 04/16/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78

Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial Assurance information

Date of Government Version: 04/14/2021
Date Data Arrived at EDR: 04/15/2021
Date Made Active in Reports: 07/06/2021
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 05/13/2021
Date Data Arrived at EDR: 05/13/2021
Date Made Active in Reports: 07/26/2021
Number of Days to Update: 74

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 04/15/2020
Date Made Active in Reports: 07/02/2020
Number of Days to Update: 78

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Annually

ICE: ICE
Contains data pertaining to the Permitted Facilities with Inspections / Enforcements sites tracked in Envirostor.

Date of Government Version: 05/14/2021
Date Data Arrived at EDR: 05/14/2021
Date Made Active in Reports: 07/27/2021
Number of Days to Update: 74
Source: Department of Toxic Subsances Control
Telephone: 877-786-9427
Last EDR Contact: 08/13/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List
The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HWP: EnviroStor Permitted Facilities Listing
Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 05/14/2021
Date Data Arrived at EDR: 05/14/2021
Date Made Active in Reports: 07/27/2021
Number of Days to Update: 74
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 08/13/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Quarterly

HWT: Registered Hazardous Waste Transporter Database
A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 07/01/2021
Date Data Arrived at EDR: 07/01/2021
Date Made Active in Reports: 09/24/2021
Number of Days to Update: 85
Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 10/05/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Quarterly

MINES: Mines Site Location Listing
A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82
Source: Department of Conservation
Telephone: 916-322-1080
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing
The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/28/2021
Date Made Active in Reports: 08/20/2021
Number of Days to Update: 84
Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Varies

NPDES: NPDES Permits Listing
A listing of NPDES permits, including stormwater.

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/11/2021
Date Made Active in Reports: 07/27/2021
Number of Days to Update: 77
Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 08/13/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: Quarterly

PEST LIC: Pesticide Regulation Licenses Listing
A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 05/28/2021
Date Made Active in Reports: 08/20/2021
Number of Days to Update: 84
Source: Department of Pesticide Regulation
Telephone: 916-445-4038
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Quarterly

PROC: Certified Processors Database
A listing of certified processors.

Date of Government Version: 06/04/2021
Date Data Arrived at EDR: 06/04/2021
Date Made Active in Reports: 08/27/2021
Number of Days to Update: 84
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 09/08/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

NOTIFY 65: Proposition 65 Records
Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 03/12/2021
Date Data Arrived at EDR: 03/16/2021
Date Made Active in Reports: 06/01/2021
Number of Days to Update: 77
Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 08/26/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: No Update Planned

UIC: UIC Listing
A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/25/2021
Number of Days to Update: 83
Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

UIC GEO: Underground Injection Control Sites (GEOTRACKER)
Underground control injection sites

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82
Source: State Water Resource Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

WASTEWATER PITS: Oil Wastewater Pits Listing
Water officials discovered that oil producers have been dumping chemical-laden wastewater into hundreds of unlined pits that are operating without proper permits. Inspections completed by the Central Valley Regional Water Quality Control Board revealed the existence of previously unidentified waste sites. The water boards review found that more than one-third of the region's active disposal pits are operating without permission.

Date of Government Version: 02/11/2021
Date Data Arrived at EDR: 07/01/2021
Date Made Active in Reports: 09/29/2021
Number of Days to Update: 90

Source: RWQCB, Central Valley Region
Telephone: 559-445-5577
Last EDR Contact: 07/01/2021
Next Scheduled EDR Contact: 10/18/2021
Data Release Frequency: Varies

WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9

Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: No Update Planned

WIP: Well Investigation Program Case List
Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13

Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 09/14/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: No Update Planned

MILITARY PRIV SITES: Military Privatized Sites (GEOTRACKER)
Military privatized sites

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

PROJECT: Project Sites (GEOTRACKER)
Projects sites

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

WDR: Waste Discharge Requirements Listing
In general, the Waste Discharge Requirements (WDRs) Program (sometimes also referred to as the "Non Chapter 15 (Non 15) Program") regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. Exemptions from Title 27 may be granted for nine categories of discharges (e.g., sewage, wastewater, etc.) that meet, and continue to meet, the preconditions listed for each specific exemption. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 06/07/2021
Date Made Active in Reports: 08/27/2021
Number of Days to Update: 81

Source: State Water Resources Control Board
Telephone: 916-341-5810
Last EDR Contact: 09/08/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

CIWQS: California Integrated Water Quality System
The California Integrated Water Quality System (CIWQS) is a computer system used by the State and Regional Water Quality Control Boards to track information about places of environmental interest, manage permits and other orders, track inspections, and manage violations and enforcement activities.

Date of Government Version: 05/19/2021
Date Data Arrived at EDR: 05/19/2021
Date Made Active in Reports: 08/12/2021
Number of Days to Update: 85
Source: State Water Resources Control Board
Telephone: 866-794-4977
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Varies

CERS: CalEPA Regulated Site Portal Data

The CalEPA Regulated Site Portal database combines data about environmentally regulated sites and facilities in California into a single database. It combines data from a variety of state and federal databases, and provides an overview of regulated activities across the spectrum of environmental programs for any given location in California. These activities include hazardous materials and waste, state and federal cleanups, impacted ground and surface waters, and toxic materials

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 04/20/2021
Date Made Active in Reports: 07/07/2021
Number of Days to Update: 78
Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

NON-CASE INFO: Non-Case Information Sites (GEOTRACKER)

Non-Case Information sites

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

OTHER OIL GAS: Other Oil & Gas Projects Sites (GEOTRACKER)

Other Oil & Gas Projects sites

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

PROD WATER PONDS: Produced Water Ponds Sites (GEOTRACKER)

Produced water ponds sites

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

SAMPLING POINT: Sampling Point ? Public Sites (GEOTRACKER)

Sampling point - public sites

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/24/2021
Number of Days to Update: 82
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

WELL STIM PROJ: Well Stimulation Project (GEOTRACKER)

Includes areas of groundwater monitoring plans, a depiction of the monitoring network, and the facilities, boundaries, and subsurface characteristics of the oilfield and the features (oil and gas wells, produced water ponds, UIC wells, water supply wells, etc?) being monitored

Date of Government Version: 06/03/2021
Date Data Arrived at EDR: 06/03/2021
Date Made Active in Reports: 08/25/2021
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Varies

HWTS: Hazardous Waste Tracking System

DTSC maintains the Hazardous Waste Tracking System that stores ID number information since the early 1980s and manifest data since 1993. The system collects both manifest copies from the generator and destination facility.

Date of Government Version: 04/08/2021
Date Data Arrived at EDR: 04/09/2021
Date Made Active in Reports: 04/20/2021
Number of Days to Update: 11

Source: Department of Toxic Substances Control
Telephone: 916-324-2444
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/26/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Varies

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits

An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Semi-Annually

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Semi-Annually

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Department of Resources Recycling and Recovery
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

ALAMEDA COUNTY:

CS ALAMEDA: Contaminated Sites
A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 01/09/2019
Date Data Arrived at EDR: 01/11/2019
Date Made Active in Reports: 03/05/2019
Number of Days to Update: 53

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Semi-Annually

UST ALAMEDA: Underground Tanks
Underground storage tank sites located in Alameda county.

Date of Government Version: 06/29/2021
Date Data Arrived at EDR: 06/30/2021
Date Made Active in Reports: 09/22/2021
Number of Days to Update: 84

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA AMADOR: CUPA Facility List
Cupa Facility List

Date of Government Version: 08/05/2021
Date Data Arrived at EDR: 08/06/2021
Date Made Active in Reports: 09/17/2021
Number of Days to Update: 42

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA BUTTE: CUPA Facility Listing
Cupa facility list.

Date of Government Version: 04/21/2017
Date Data Arrived at EDR: 04/25/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 106

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA CALVERAS: CUPA Facility Listing
Cupa Facility Listing

Date of Government Version: 06/15/2021
Date Data Arrived at EDR: 06/16/2021
Date Made Active in Reports: 07/02/2021
Number of Days to Update: 16

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 09/14/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA COLUSA: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/06/2020
Date Data Arrived at EDR: 04/23/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 78

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Semi-Annually

CONTRA COSTA COUNTY:

SL CONTRA COSTA: Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 04/21/2021
Date Data Arrived at EDR: 04/22/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 81

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA DEL NORTE: CUPA Facility List
Cupa Facility list

Date of Government Version: 12/17/2020
Date Data Arrived at EDR: 01/28/2021
Date Made Active in Reports: 04/16/2021
Number of Days to Update: 78

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA EL DORADO: CUPA Facility List
CUPA facility list.

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/12/2021
Date Made Active in Reports: 07/26/2021
Number of Days to Update: 75

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA FRESNO: CUPA Resources List
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 04/09/2021
Date Data Arrived at EDR: 06/23/2021
Date Made Active in Reports: 09/17/2021
Number of Days to Update: 86

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Semi-Annually

GLENN COUNTY:

CUPA GLENN: CUPA Facility List
Cupa facility list

Date of Government Version: 01/22/2018
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 03/14/2018
Number of Days to Update: 49

Source: Glenn County Air Pollution Control District
Telephone: 830-934-6500
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: No Update Planned

HUMBOLDT COUNTY:

CUPA HUMBOLDT: CUPA Facility List
CUPA facility list.

Date of Government Version: 05/17/2021
Date Data Arrived at EDR: 05/18/2021
Date Made Active in Reports: 05/20/2021
Number of Days to Update: 2

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Semi-Annually

IMPERIAL COUNTY:

CUPA IMPERIAL: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/14/2021
Date Data Arrived at EDR: 04/15/2021
Date Made Active in Reports: 07/06/2021
Number of Days to Update: 82

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

INYO COUNTY:

CUPA INYO: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/03/2018
Date Made Active in Reports: 06/14/2018
Number of Days to Update: 72

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

KERN COUNTY:

CUPA KERN: CUPA Facility List
A listing of sites included in the Kern County Hazardous Material Business Plan.

Date of Government Version: 04/22/2021
Date Data Arrived at EDR: 04/30/2021
Date Made Active in Reports: 07/19/2021
Number of Days to Update: 80

Source: Kern County Public Health
Telephone: 661-321-3000
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

UST KERN: Underground Storage Tank Sites & Tank Listing
Kern County Sites and Tanks Listing.

Date of Government Version: 07/06/2021
Date Data Arrived at EDR: 08/12/2021
Date Made Active in Reports: 08/18/2021
Number of Days to Update: 6

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA KINGS: CUPA Facility List

A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 12/03/2020
Date Data Arrived at EDR: 01/26/2021
Date Made Active in Reports: 04/14/2021
Number of Days to Update: 78

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 09/07/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

LAKE COUNTY:

CUPA LAKE: CUPA Facility List

Cupa facility list

Date of Government Version: 05/10/2021
Date Data Arrived at EDR: 05/12/2021
Date Made Active in Reports: 07/26/2021
Number of Days to Update: 75

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 07/06/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

LASSEN COUNTY:

CUPA LASSEN: CUPA Facility List

Cupa facility list

Date of Government Version: 07/31/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 80

Source: Lassen County Environmental Health
Telephone: 530-251-8528
Last EDR Contact: 09/09/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

LOS ANGELES COUNTY:

AOCONCERN: Key Areas of Concerns in Los Angeles County

San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office. Date of Government Version: 3/30/2009 Exide Site area is a cleanup plan of lead-impacted soil surrounding the former Exide Facility as designated by the DTSC. Date of Government Version: 7/17/2017

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206

Source: N/A
Telephone: N/A
Last EDR Contact: 09/09/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

HMS LOS ANGELES: HMS: Street Number List
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 07/08/2021
Date Data Arrived at EDR: 07/09/2021
Date Made Active in Reports: 09/29/2021
Number of Days to Update: 82

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 09/30/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Semi-Annually

LF LOS ANGELES: List of Solid Waste Facilities
Solid Waste Facilities in Los Angeles County.

Date of Government Version: 07/09/2021
Date Data Arrived at EDR: 07/09/2021
Date Made Active in Reports: 09/29/2021
Number of Days to Update: 82

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

LF LOS ANGELES CITY: City of Los Angeles Landfills
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 01/01/2021
Date Data Arrived at EDR: 02/18/2021
Date Made Active in Reports: 05/10/2021
Number of Days to Update: 81

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 10/05/2021
Next Scheduled EDR Contact: 01/24/2022
Data Release Frequency: Varies

LOS ANGELES AST: Active & Inactive AST Inventory
A listing of active & inactive above ground petroleum storage tank site locations, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58

Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 09/24/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Varies

LOS ANGELES CO LF METHANE: Methane Producing Landfills
This data was created on April 30, 2012 to represent known disposal sites in Los Angeles County that may produce and emanate methane gas. The shapefile contains disposal sites within Los Angeles County that once accepted degradable refuse material. Information used to create this data was extracted from a landfill survey performed by County Engineers (Major Waste System Map, 1973) as well as historical records from CalRecycle, Regional Water Quality Control Board, and Los Angeles County Department of Public Health

Date of Government Version: 02/04/2021
Date Data Arrived at EDR: 04/16/2021
Date Made Active in Reports: 04/21/2021
Number of Days to Update: 5

Source: Los Angeles County Department of Public Works
Telephone: 626-458-6973
Last EDR Contact: 07/12/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: No Update Planned

LOS ANGELES HM: Active & Inactive Hazardous Materials Inventory
A listing of active & inactive hazardous materials facility locations, located in the City of Los Angeles.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 06/17/2021
Date Made Active in Reports: 06/28/2021
Number of Days to Update: 11

Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 09/24/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Varies

LOS ANGELES UST: Active & Inactive UST Inventory
A listing of active & inactive underground storage tank site locations and underground storage tank historical sites, located in the City of Los Angeles.

Date of Government Version: 04/19/2021
Date Data Arrived at EDR: 06/17/2021
Date Made Active in Reports: 09/14/2021
Number of Days to Update: 89
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 09/24/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Varies

SITE MIT LOS ANGELES: Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 05/26/2021
Date Data Arrived at EDR: 07/09/2021
Date Made Active in Reports: 09/29/2021
Number of Days to Update: 82
Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 07/09/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Annually

UST EL SEGUNDO: City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/10/2017
Number of Days to Update: 21
Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 07/06/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: No Update Planned

UST LONG BEACH: City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 04/22/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/27/2019
Number of Days to Update: 65
Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

UST TORRANCE: City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 02/02/2021
Date Data Arrived at EDR: 04/28/2021
Date Made Active in Reports: 07/13/2021
Number of Days to Update: 76
Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA MADERA: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 72
Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

MARIN COUNTY:

UST MARIN: Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 09/26/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/02/2018
Number of Days to Update: 29

Source: Public Works Department Waste Management
Telephone: 415-473-6647
Last EDR Contact: 09/23/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Semi-Annually

MENDOCINO COUNTY:

UST MENDOCINO: Mendocino County UST Database
A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 03/24/2021
Date Data Arrived at EDR: 04/07/2021
Date Made Active in Reports: 06/24/2021
Number of Days to Update: 78

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: Annually

MERCED COUNTY:

CUPA MERCED: CUPA Facility List
CUPA facility list.

Date of Government Version: 05/13/2021
Date Data Arrived at EDR: 05/14/2021
Date Made Active in Reports: 07/26/2021
Number of Days to Update: 73

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 08/09/2021
Next Scheduled EDR Contact: 11/28/2021
Data Release Frequency: Varies

MONO COUNTY:

CUPA MONO: CUPA Facility List
CUPA Facility List

Date of Government Version: 02/22/2021
Date Data Arrived at EDR: 03/02/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 78

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/06/3021
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA MONTEREY: CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 06/23/2021
Date Data Arrived at EDR: 06/23/2021
Date Made Active in Reports: 06/24/2021
Number of Days to Update: 1

Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 09/23/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Varies

NAPA COUNTY:

LUST NAPA: Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 03/02/2017
Number of Days to Update: 50

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: No Update Planned

UST NAPA: Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 09/05/2019
Date Data Arrived at EDR: 09/09/2019
Date Made Active in Reports: 10/31/2019
Number of Days to Update: 52

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA NEVADA: CUPA Facility List
CUPA facility list.

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 04/29/2021
Date Made Active in Reports: 07/15/2021
Number of Days to Update: 77

Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

ORANGE COUNTY:

IND_SITE ORANGE: List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 03/01/2021
Date Data Arrived at EDR: 04/30/2021
Date Made Active in Reports: 07/19/2021
Number of Days to Update: 80

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 07/29/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Annually

LUST ORANGE: List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 03/01/2021
Date Data Arrived at EDR: 05/03/2021
Date Made Active in Reports: 05/12/2021
Number of Days to Update: 9

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 04/29/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

UST ORANGE: List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 04/29/2021
Date Data Arrived at EDR: 04/30/2021
Date Made Active in Reports: 07/19/2021
Number of Days to Update: 80

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 07/29/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

PLACER COUNTY:

MS PLACER: Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 05/26/2021
Date Made Active in Reports: 06/01/2021
Number of Days to Update: 6
Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Semi-Annually

PLUMAS COUNTY:

CUPA PLUMAS: CUPA Facility List
Plumas County CUPA Program facilities.

Date of Government Version: 03/31/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/26/2019
Number of Days to Update: 64
Source: Plumas County Environmental Health
Telephone: 530-283-6355
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

RIVERSIDE COUNTY:

LUST RIVERSIDE: Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 06/29/2021
Date Data Arrived at EDR: 06/30/2021
Date Made Active in Reports: 07/14/2021
Number of Days to Update: 14
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 09/09/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: Quarterly

UST RIVERSIDE: Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 06/29/2021
Date Data Arrived at EDR: 06/30/2021
Date Made Active in Reports: 07/14/2021
Number of Days to Update: 14
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 09/09/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

CS SACRAMENTO: Toxic Site Clean-Up List
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 03/30/2021
Date Data Arrived at EDR: 04/01/2021
Date Made Active in Reports: 06/23/2021
Number of Days to Update: 83
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 09/28/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Quarterly

ML SACRAMENTO: Master Hazardous Materials Facility List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 03/30/2021
Date Data Arrived at EDR: 04/01/2021
Date Made Active in Reports: 06/25/2021
Number of Days to Update: 85
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 10/01/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Quarterly

SAN BENITO COUNTY:

CUPA SAN BENITO: CUPA Facility List
Cupa facility list

Date of Government Version: 04/28/2021
Date Data Arrived at EDR: 04/29/2021
Date Made Active in Reports: 05/03/2021
Number of Days to Update: 4

Source: San Benito County Environmental Health
Telephone: N/A
Last EDR Contact: 07/26/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

SAN BERNARDINO COUNTY:

PERMITS SAN BERNARDINO: Hazardous Material Permits
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 05/19/2021
Date Data Arrived at EDR: 05/19/2021
Date Made Active in Reports: 06/07/2021
Number of Days to Update: 19

Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

HMMD SAN DIEGO: Hazardous Materials Management Division Database
The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 05/28/2021
Date Data Arrived at EDR: 05/28/2021
Date Made Active in Reports: 08/20/2021
Number of Days to Update: 84

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Quarterly

LF SAN DIEGO: Solid Waste Facilities
San Diego County Solid Waste Facilities.

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 11/23/2020
Date Made Active in Reports: 02/08/2021
Number of Days to Update: 77

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

SAN DIEGO CO LOP: Local Oversight Program Listing
A listing of all LOP release sites that are or were under the County of San Diego's jurisdiction. Included are closed or transferred cases, open cases, and cases that did not have a case type indicated. The cases without a case type are mostly complaints; however, some of them could be LOP cases.

Date of Government Version: 07/14/2020
Date Data Arrived at EDR: 07/16/2020
Date Made Active in Reports: 09/29/2020
Number of Days to Update: 75

Source: Department of Environmental Health
Telephone: 858-505-6874
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

SAN DIEGO CO SAM: Environmental Case Listing
The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24
Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

CUPA SAN FRANCISCO CO: CUPA Facility Listing
Cupa facilities

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/07/2021
Date Made Active in Reports: 07/23/2021
Number of Days to Update: 77
Source: San Francisco County Department of Environmental Health
Telephone: 415-252-3896
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

LUST SAN FRANCISCO: Local Oversite Facilities
A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10
Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: No Update Planned

UST SAN FRANCISCO: Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/07/2021
Date Made Active in Reports: 07/23/2021
Number of Days to Update: 77
Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

UST SAN JOAQUIN: San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 06/22/2018
Date Data Arrived at EDR: 06/26/2018
Date Made Active in Reports: 07/11/2018
Number of Days to Update: 15
Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 09/09/2021
Next Scheduled EDR Contact: 12/27/2021
Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA SAN LUIS OBISPO: CUPA Facility List
Cupa Facility List.

Date of Government Version: 05/07/2021
Date Data Arrived at EDR: 05/11/2021
Date Made Active in Reports: 05/14/2021
Number of Days to Update: 3
Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

SAN MATEO COUNTY:

BI SAN MATEO: Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 02/20/2020
Date Data Arrived at EDR: 02/20/2020
Date Made Active in Reports: 04/24/2020
Number of Days to Update: 64
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 09/10/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Annually

LUST SAN MATEO: Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/29/2019
Date Data Arrived at EDR: 03/29/2019
Date Made Active in Reports: 05/29/2019
Number of Days to Update: 61
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 08/31/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA SANTA BARBARA: CUPA Facility Listing
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28
Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: No Update Planned

SANTA CLARA COUNTY:

CUPA SANTA CLARA: Cupa Facility List
Cupa facility list

Date of Government Version: 02/24/2021
Date Data Arrived at EDR: 02/26/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 82
Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

HIST LUST SANTA CLARA: HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22
Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LUST SANTA CLARA: LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014
Date Data Arrived at EDR: 03/05/2014
Date Made Active in Reports: 03/18/2014
Number of Days to Update: 13
Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 08/17/2021
Next Scheduled EDR Contact: 12/06/2021
Data Release Frequency: No Update Planned

SAN JOSE HAZMAT: Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 11/03/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 82

Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 07/27/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA SANTA CRUZ: CUPA Facility List
CUPA facility listing.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 05/23/2017
Number of Days to Update: 90

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA SHASTA: CUPA Facility List
Cupa Facility List.

Date of Government Version: 06/15/2017
Date Data Arrived at EDR: 06/19/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 51

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Varies

SOLANO COUNTY:

LUST SOLANO: Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 06/04/2019
Date Data Arrived at EDR: 06/06/2019
Date Made Active in Reports: 08/13/2019
Number of Days to Update: 68

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Quarterly

UST SOLANO: Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 06/22/2021
Date Data Arrived at EDR: 06/23/2021
Date Made Active in Reports: 09/17/2021
Number of Days to Update: 86

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 09/09/2021
Next Scheduled EDR Contact: 12/12/2021
Data Release Frequency: Quarterly

SONOMA COUNTY:

CUPA SONOMA: Cupa Facility List
Cupa Facility list

Date of Government Version: 07/02/2021
Date Data Arrived at EDR: 07/06/2021
Date Made Active in Reports: 07/14/2021
Number of Days to Update: 8

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 09/14/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Varies

LUST SONOMA: Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 06/30/2021
Date Data Arrived at EDR: 06/30/2021
Date Made Active in Reports: 09/24/2021
Number of Days to Update: 86

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 09/14/2021
Next Scheduled EDR Contact: 01/03/2022
Data Release Frequency: Quarterly

STANISLAUS COUNTY:

CUPA STANISLAUS: CUPA Facility List
Cupa facility list

Date of Government Version: 05/14/2021
Date Data Arrived at EDR: 05/17/2021
Date Made Active in Reports: 08/03/2021
Number of Days to Update: 78

Source: Stanislaus County Department of Ennvironmental Protection
Telephone: 209-525-6751
Last EDR Contact: 07/06/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Varies

SUTTER COUNTY:

UST SUTTER: Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 05/25/2021
Date Data Arrived at EDR: 05/26/2021
Date Made Active in Reports: 08/18/2021
Number of Days to Update: 84

Source: Sutter County Environmental Health Services
Telephone: 530-822-7500
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 12/13/2021
Data Release Frequency: Semi-Annually

TEHAMA COUNTY:

CUPA TEHAMA: CUPA Facility List
Cupa facilities

Date of Government Version: 01/13/2021
Date Data Arrived at EDR: 01/14/2021
Date Made Active in Reports: 04/06/2021
Number of Days to Update: 82

Source: Tehama County Department of Environmental Health
Telephone: 530-527-8020
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

TRINITY COUNTY:

CUPA TRINITY: CUPA Facility List
Cupa facility list

Date of Government Version: 04/14/2021
Date Data Arrived at EDR: 04/15/2021
Date Made Active in Reports: 07/06/2021
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 760-352-0381
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

TULARE COUNTY:

CUPA TULARE: CUPA Facility List
Cupa program facilities

Date of Government Version: 04/26/2021
Date Data Arrived at EDR: 04/28/2021
Date Made Active in Reports: 07/13/2021
Number of Days to Update: 76

Source: Tulare County Environmental Health Services Division
Telephone: 559-624-7400
Last EDR Contact: 08/24/2021
Next Scheduled EDR Contact: 11/15/2021
Data Release Frequency: Varies

TUOLUMNE COUNTY:

CUPA TUOLUMNE: CUPA Facility List
Cupa facility list

Date of Government Version: 04/23/2018
Date Data Arrived at EDR: 04/25/2018
Date Made Active in Reports: 06/25/2018
Number of Days to Update: 61

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 07/13/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Varies

VENTURA COUNTY:

BWT VENTURA: Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 03/29/2021
Date Data Arrived at EDR: 04/22/2021
Date Made Active in Reports: 07/12/2021
Number of Days to Update: 81

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

LF VENTURA: Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 09/23/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: No Update Planned

LUST VENTURA: Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 08/04/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: No Update Planned

MED WASTE VENTURA: Medical Waste Program List
To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 03/29/2021
Date Data Arrived at EDR: 04/21/2021
Date Made Active in Reports: 04/23/2021
Number of Days to Update: 2

Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 07/15/2021
Next Scheduled EDR Contact: 11/01/2021
Data Release Frequency: Quarterly

UST VENTURA: Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 05/26/2021
Date Data Arrived at EDR: 06/04/2021
Date Made Active in Reports: 08/27/2021
Number of Days to Update: 84
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 09/08/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Quarterly

YOLO COUNTY:

UST YOLO: Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 06/22/2021
Date Data Arrived at EDR: 06/28/2021
Date Made Active in Reports: 09/21/2021
Number of Days to Update: 85
Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 09/23/2021
Next Scheduled EDR Contact: 01/10/2022
Data Release Frequency: Annually

YUBA COUNTY:

CUPA YUBA: CUPA Facility List
CUPA facility listing for Yuba County.

Date of Government Version: 04/21/2021
Date Data Arrived at EDR: 04/22/2021
Date Made Active in Reports: 05/12/2021
Number of Days to Update: 20
Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 07/20/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 03/24/2021
Date Data Arrived at EDR: 05/11/2021
Date Made Active in Reports: 07/28/2021
Number of Days to Update: 78
Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 08/10/2021
Next Scheduled EDR Contact: 11/22/2021
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36
Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 10/05/2021
Next Scheduled EDR Contact: 01/17/2022
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 04/29/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 07/29/2021
Next Scheduled EDR Contact: 11/08/2021
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/07/2021
Next Scheduled EDR Contact: 10/25/2021
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 02/11/2021
Date Made Active in Reports: 02/24/2021
Number of Days to Update: 13

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 08/11/2021
Next Scheduled EDR Contact: 11/29/2021
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 09/01/2021
Next Scheduled EDR Contact: 12/20/2021
Data Release Frequency: Annually

Oil/Gas Pipelines

Source: Endeavor Business Media

Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data

Source: Endeavor Business Media

This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.
Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.
Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.
Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

VERNOLA RANCH NORTH
12080 BELLEGRAVE AVENUE
MIRA LOMA, CA 91752

TARGET PROPERTY COORDINATES

Latitude (North):	33.984882 - 33° 59' 5.58''
Longitude (West):	117.546146 - 117° 32' 46.13''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	449554.2
UTM Y (Meters):	3760419.8
Elevation:	689 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5640930 CORONA NORTH, CA
Version Date:	2012
North Map:	5620426 GUASTI, CA
Version Date:	2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
06065C0681G	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
06071C9375H	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
CORONA NORTH	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Cenozoic
System:	Quaternary
Series:	Quaternary
Code:	Q *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 6691091.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Vernola Ranch North	CLIENT:	Geotek
ADDRESS:	12080 Bellegrave Avenue Mira Loma CA 91752	CONTACT:	Anna M. Scott
LAT/LONG:	33.984882 / 117.546146	INQUIRY #:	6691091.2s
		DATE:	October 06, 2021 8:30 am

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: HILMAR

Soil Surface Texture: loamy fine sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	16 inches	loamy fine sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 7.8 Min: 6.1
2	16 inches	72 inches	sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 7.8 Min: 6.1

Soil Map ID: 2

Soil Component Name: RAMONA

Soil Surface Texture: sandy loam

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information

	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	14 inches	sandy loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 6.6
2	14 inches	22 inches	fine sandy loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 6.6
3	22 inches	68 inches	sandy clay loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 6.6
4	68 inches	74 inches	gravelly sandy loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand. COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 4 Min: 1.4	Max: 8.4 Min: 6.6

Soil Map ID: 3

Soil Component Name: HILMAR

Soil Surface Texture: loamy fine sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information

	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	16 inches	loamy fine sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 8.4 Min: 6.6
2	16 inches	72 inches	loamy fine sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 141 Min: 42	Max: 8.4 Min: 6.6

Soil Map ID: 4

Soil Component Name: HILMAR

Soil Surface Texture: loamy sand

Hydrologic Group: Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	16 inches	loamy sand	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 1.4 Min: 0.42	Max: 9.6 Min: 8.4
2	16 inches	22 inches	stratified very fine sandy loam to silt loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 1.4 Min: 0.42	Max: 9.6 Min: 8.4
3	22 inches	72 inches	stratified very fine sandy loam to silt loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), silt.	Max: 1.4 Min: 0.42	Max: 9.6 Min: 8.4

Soil Map ID: 5

Soil Component Name: DELHI

Soil Surface Texture: fine sand

Hydrologic Group: Class A - High infiltration rates. Soils are deep, well drained to excessively drained sands and gravels.

Soil Drainage Class: Somewhat excessively drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	9 inches	fine sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 42 Min: 14	Max: 7.8 Min: 6.1
2	9 inches	48 inches	sand	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 42 Min: 14	Max: 7.8 Min: 6.1
3	48 inches	59 inches	fine sandy loam	Granular materials (35 pct. or less passing No. 200), Stone Fragments, Gravel and Sand.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand.	Max: 42 Min: 14	Max: 7.8 Min: 6.1

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
D8	USGS40000139530	1/2 - 1 Mile WSW
18	USGS40000139537	1/2 - 1 Mile West

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

No PWS System Found

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
1	CADDW0000022140	1/4 - 1/2 Mile WSW
A2	CADDW0000001313	1/4 - 1/2 Mile ENE
A3	CAPFAS000001657	1/4 - 1/2 Mile ENE
B4	CADDW0000012203	1/4 - 1/2 Mile NE
B5	CAPFAS000000967	1/4 - 1/2 Mile NE
C6	CADDW0000008868	1/4 - 1/2 Mile West
C7	2582	1/4 - 1/2 Mile West
9	CADWR0000001457	1/2 - 1 Mile NNW
10	CADWR9000006301	1/2 - 1 Mile SSW
D11	2583	1/2 - 1 Mile WSW
E12	CADDW0000006675	1/2 - 1 Mile West
E13	CADDW0000017358	1/2 - 1 Mile West
14	CADDW0000021047	1/2 - 1 Mile SW
E15	2581	1/2 - 1 Mile West
F16	CADDW0000005428	1/2 - 1 Mile NNE
F17	CAPFAS000001333	1/2 - 1 Mile NNE
19	CADDW0000012206	1/2 - 1 Mile West
G20	CADDW0000004891	1/2 - 1 Mile WNW
G21	CAPFAS000000725	1/2 - 1 Mile WNW
H22	CADDW0000020701	1/2 - 1 Mile NE
H23	CAPFAS000000688	1/2 - 1 Mile NE
H24	CADWR0000019476	1/2 - 1 Mile NE
I25	CADDW0000013264	1/2 - 1 Mile West
I26	CAPFAS000000575	1/2 - 1 Mile West

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	CAOG14000006473	1/4 - 1/2 Mile West
2	CAOG14000006472	1/4 - 1/2 Mile NE

PHYSICAL SETTING SOURCE MAP - 6691091.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Vernola Ranch North	CLIENT:	Geotek
ADDRESS:	12080 Bellegrave Avenue Mira Loma CA 91752	CONTACT:	Anna M. Scott
		INQUIRY #:	6691091.2s
LAT/LONG:	33.984882 / 117.546146	DATE:	October 06, 2021 8:30 am

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation	Database	EDR ID Number
1 **WSW** **1/4 - 1/2 Mile** **Lower**	**CA WELLS**	**CADDW0000022140**
A2 **ENE** **1/4 - 1/2 Mile** **Higher**	**CA WELLS**	**CADDW0000001313**
A3 **ENE** **1/4 - 1/2 Mile** **Higher**	**CA WELLS**	**CAPFAS000001657**
B4 **NE** **1/4 - 1/2 Mile** **Higher**	**CA WELLS**	**CADDW0000012203**
B5 **NE** **1/4 - 1/2 Mile** **Higher**	**CA WELLS**	**CAPFAS000000967**
C6 **West** **1/4 - 1/2 Mile** **Lower**	**CA WELLS**	**CADDW0000008868**
C7 **West** **1/4 - 1/2 Mile** **Lower**	**CA WELLS**	**2582**

Seq:	2582	Prim sta c:	02S/06W-19E02 S
Frds no:	3310025010	County:	33
District:	14	User id:	WAT
System no:	3310025	Water type:	G
Source nam:	WELL 10	Station ty:	WELL/AMBNT
Latitude:	335903.4	Longitude:	1173314.2
Precision:	1	Status:	AR
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3310025	System nam:	Norco, City Of
Hqname:	Not Reported	Address:	P.O. BOX 428
City:	NORCO	State:	CA
Zip:	91760	Zip ext:	Not Reported
Pop serv:	24704	Connection:	6153
Area serve:	NORCO CITY		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D8
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000139530**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	002S006W19E002S	Type:	Well
Description:	Not Reported	HUC:	18070203
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	California Coastal Basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	345
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

9
NNW
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000001457**

10
SSW
1/2 - 1 Mile
Lower

CA WELLS **CADWR9000006301**

State Well #:	Not Reported	Station ID:	48082
Well Name:	CHINO-1207985	Basin Name:	Chino
Well Use:	Observation		
Well Type:	Part of a nested/multi-completion well		
Well Depth:	120	Well Completion Rpt #:	e023308

D11
WSW
1/2 - 1 Mile
Lower

CA WELLS **2583**

Seq:	2583	Prim sta c:	02S/06W-19E03 S
Frds no:	3310025011	County:	33
District:	14	User id:	WAT
System no:	3310025	Water type:	G
Source nam:	WELL 11	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	335856.6	Longitude:	1173318.3
Precision:	1	Status:	AR
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3310025	System nam:	Norco, City Of
Hqname:	Not Reported	Address:	P.O. BOX 428
City:	NORCO	State:	CA
Zip:	91760	Zip ext:	Not Reported
Pop serv:	24704	Connection:	6153

Area serve: NORCO CITY

E12
West
1/2 - 1 Mile
Lower

CA WELLS **CADDW0000006675**

E13
West
1/2 - 1 Mile
Lower

CA WELLS **CADDW0000017358**

14
SW
1/2 - 1 Mile
Lower

CA WELLS **CADDW0000021047**

E15
West
1/2 - 1 Mile
Lower

CA WELLS **2581**

Seq:	2581	Prim sta c:	02S/06W-19E01 S
Frds no:	3310025009	County:	33
District:	14	User id:	WAT
System no:	3310025	Water type:	G
Source nam:	WELL 09 - INACTIVE	Station ty:	WELL/AMBNT
Latitude:	335904.0	Longitude:	1173324.8
Precision:	1	Status:	IR
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	3310025	System nam:	Norco, City Of
Hqname:	Not Reported	Address:	P.O. BOX 428
City:	NORCO	State:	CA
Zip:	91760	Zip ext:	Not Reported
Pop serv:	24704	Connection:	6153
Area serve:	NORCO CITY		

F16
NNE
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000005428**

F17
NNE
1/2 - 1 Mile
Higher

CA WELLS **CAPFAS000001333**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
18 **West** **1/2 - 1 Mile** **Lower**	**FED USGS**	**USGS40000139537**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	002S006W19E001S	Type:	Well
Description:	Not Reported	HUC:	18070203
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	California Coastal Basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	370
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

---

19 **West** **1/2 - 1 Mile** **Lower**	**CA WELLS**	**CADDW0000012206**

G20 **WNW** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CADDW0000004891**

G21 **WNW** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CAPFAS000000725**

H22 **NE** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CADDW0000020701**

H23 **NE** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CAPFAS000000688**

H24 **NE** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CADWR0000019476**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation	Database	EDR ID Number
I25 **West** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CADDW0000013264**
I26 **West** **1/2 - 1 Mile** **Higher**	**CA WELLS**	**CAPFAS000000575**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
West
1/4 - 1/2 Mile

OIL_GAS **CAOG14000006473**

API #:	0406500137	Well #:	2
Well Status:	Plugged	Well Type:	Dry Hole
Lease Name:	Smith & Scott	Field Name:	Any Field
Area Name:	Any Area	GIS Source:	hud
Confidential Well:	N	Directionally Drilled:	N
Spud Date:	Not Reported		

2
NE
1/4 - 1/2 Mile

OIL_GAS **CAOG14000006472**

API #:	0406500136	Well #:	1
Well Status:	Plugged	Well Type:	Dry Hole
Lease Name:	Smith & Scott	Field Name:	Any Field
Area Name:	Any Area	GIS Source:	hud
Confidential Well:	N	Directionally Drilled:	N
Spud Date:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
91752	4	0

Federal EPA Radon Zone for RIVERSIDE County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 91752

Number of sites tested: 1

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.500 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

OTHER STATE DATABASE INFORMATION

Groundwater Ambient Monitoring & Assessment Program
State Water Resources Control Board
Telephone: 916-341-5577
The GAMA Program is Californias comprehensive groundwater quality monitoring program. GAMA collects data by testing the untreated, raw water in different types of wells for naturally-occurring and man-made chemicals. The GAMA data includes Domestic, Monitoring and Municipal well types from the following sources, Department of Water Resources, Department of Heath Services, EDF, Agricultural Lands, Lawrence Livermore National Laboratory, Department of Pesticide Regulation, United States Geological Survey, Groundwater Ambient Monitoring and Assessment Program and Local Groundwater Projects.

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Public Health
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

California Oil and Gas Well Locations
Source: Dept of Conservation, Geologic Energy Management Division
Telephone: 916-323-1779
Oil and Gas well locations in the state.

California Earthquake Fault Lines
Source: California Division of Mines and Geology
The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

RADON

State Database: CA Radon
Source: Department of Public Health
Telephone: 916-210-8558
Radon Database for California

PHYSICAL SETTING SOURCE RECORDS SEARCHED

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX E

VAPOR ENCROACHMENT SCREENING

GEOTEK

Vernola Ranch North
12080 Bellegrave Avenue
Mira Loma, CA 91752

Inquiry Number: 6691091.2s
October 18, 2021

EDR Vapor Encroachment Screen

Prepared using EDR's Vapor Encroachment Worksheet

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	**ES1**
Primary Map	**2**
Secondary Map	**3**
Map Findings	**4**
Record Sources and Currency	**GR-1**

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

The EDR Vapor Encroachment Worksheet enables EDR's customers to make certain online modifications that effects maps, text and calculations contained in this Report. As a result, maps, text and calculations contained in this Report may have been so modified. EDR has not taken any action to verify any such modifications, and this report and the findings set forth herein must be read in light of this fact. Environmental Data Resources shall not be responsible for any customer's decision to include or not include in any final report any records determined to be within the relevant minimum search distances.

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by EDR. The report was designed to assist parties seeking to meet the search requirements of the ASTM Standard Practice for Assessment of Vapor Encroachment into Structures on Property Involved in Real Estate Transactions (E 2600).

STANDARD ENVIRONMENTAL RECORDS	Default Area of Concern (Miles)*	property	1/10	> 1/10
Federal NPL site list	1.0	0	0	0
Federal Delisted NPL site list	1.0	0	0	0
Federal CERCLIS list	0.5	0	0	0
Federal CERCLIS NFRAP site list	0.5	0	0	0
Federal RCRA CORRACTS facilities list	1.0	0	0	0
Federal RCRA non-CORRACTS TSD facilities list	0.5	0	0	0
Federal RCRA generators list	0.25	0	0	0
Federal institutional controls / engineering controls registries	0.5	0	0	0
Federal ERNS list	0.001	0	0	-
State- and tribal - equivalent NPL	1.0	0	0	0
State- and tribal - equivalent CERCLIS	1.0	0	0	1
State and tribal landfill and/or solid waste disposal site lists	0.5	0	0	0
State and tribal leaking storage tank lists	0.5	0	0	0
State and tribal registered storage tank lists	0.25	1	0	0
State and tribal institutional control / engineering control registries	not searched	-	-	-
State and tribal voluntary cleanup sites	0.5	0	0	0
State and tribal Brownfields sites	0.5	0	0	0

ADDITIONAL ENVIRONMENTAL RECORDS				
Local Brownfield lists	0.5	0	0	0
Local Lists of Landfill / Solid Waste Disposal Sites	0.5	0	0	0
Local Lists of Hazardous waste / Contaminated Sites	1.0	0	0	4
Local Lists of Registered Storage Tanks	0.25	1	0	0
Local Land Records	0.5	0	0	0
Records of Emergency Release Reports	0.5	0	0	0
Other Ascertainable Records	1.0	5	1	0

EDR HIGH RISK HISTORICAL RECORDS				
EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	0.001	0	0	-

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	0.001	0	0	-

*The Default Area of Concern may be adjusted by the environmental professional using experience and professional judgement. Each category may include several databases, and each database may have a different distance. A list of individual databases is provided at the back of this report.

EXECUTIVE SUMMARY

TARGET PROPERTY INFORMATION

ADDRESS

VERNOLA RANCH NORTH
12080 BELLEGRAVE AVENUE
MIRA LOMA, CA 91752

COORDINATES

Latitude (North):	33.984882 - 33° 59′ 5.576477″
Longitude (West):	117.546146 - 117° 32′ 46.11328″
Elevation:	689 ft. above sea level

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records.

Site	Database(s)
SAMUEL P LEWIS DBA CHINO WELDING & ASSEM 12080 BELLEGRAVE AVE MIRA LOMA, CA 91752	FINDS Registry ID:: 110041393202
VERNOLA RANCH 12080 BELLEGRAVE AVE MIRA LOMA, CA 91752	FINDS Registry ID:: 110065468185
SAMUEL P LEWIS DBA CHINO WELDING & ASSEM 12080 BELLEGRAVE AVE MIRA LOMA, CA 91752	EMI Facility Id: 150351 CERS SWEEPS UST Status: A Comp Number: 53932 Tank Status: A
BERNOLA RANCH 12080 BELLGRAVE AVE MIRA LOMA, CA 917520000	HWTS
VERNOLA RANCH 12080 BELLEGRAVE AVE MIRA LOMA, CA 91752	HAZNET GEPAID: CAC002583200 HWTS
VERNOLA RANCH 12080 BELLEGRAVE AVE. MIRA LOMA, CA 91752	UST Facility Id: 81649

EXECUTIVE SUMMARY

SEARCH RESULTS

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
VERNOLA RANCH UST: UST	12080 BELLEGRAVE AVE.	Property	▲ A6	10
ELEMENTARY SCHOOL NO. 17 ENVIROSTOR: ENVIROSTOR SCH: SCH	WINEVILLE ROAD/BELLGRAVE AVENUE	1/10 - 1/3 NNE	▲ 8	10

ADDITIONAL ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
SAMUEL P LEWIS DBA CHINO WELDING & ASSEM FINDS: FINDS	12080 BELLEGRAVE AVE	Property	▲ A1	9
VERNOLA RANCH FINDS: FINDS	12080 BELLEGRAVE AVE	Property	▲ A2	9
SAMUEL P LEWIS DBA CHINO WELDING & ASSEM EMI: EMI CERS: CERS SWEEPS UST: SWEEPS UST	12080 BELLEGRAVE AVE	Property	▲ A3	9
BERNOLA RANCH HWTS: HWTS	12080 BELLGRAVE AVE	Property	▲ A4	9
VERNOLA RANCH HAZNET: HAZNET HWTS: HWTS	12080 BELLEGRAVE AVE	Property	▲ A5	10
HARVEST CIWQS: CIWQS	NW OF LIMONITE AVE AND WINEVILLE AVE	<1/10 SE	◆ 7	10
ELEMENTARY SCHOOL NO. 17 ENVIROSTOR: ENVIROSTOR SCH: SCH	WINEVILLE ROAD/BELLGRAVE AVENUE	1/10 - 1/3 NNE	▲ 8	10
WELL II-7 PFAS: PFAS	Not Reported	1/10 - 1/3 NE	▲ 9	10
WELL II-8 PFAS: PFAS	Not Reported	1/10 - 1/3 ENE	▲ 10	10
WELL II-6	Not Reported	1/10 - 1/3 NNE	▲ 11	11

EXECUTIVE SUMMARY

Name	Address	Dist/Dir	Map ID	Page
PFAS: PFAS				


EDR HIGH RISK HISTORICAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
Not Reported				

EDR RECOVERED GOVERNMENT ARCHIVES

Name	Address	Dist/Dir	Map ID	Page
Not Reported				

PRIMARY MAP - 6691091.2S



0 300 1/3 1/2 Miles


- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- County Boundary
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Vernola Ranch North	CLIENT: Geotek
ADDRESS: 12080 Bellegrave Avenue Mira Loma CA 91752	CONTACT: Anna M. Scott INQUIRY #: 6691091.2s
LAT/LONG: 33.984882 / 117.546146	DATE: October 06, 2021 8:29 am

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

SECONDARY MAP - 6691091.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

0 1/3 1/2 1 Miles

Indian Reservations BIA

County Boundary

Power transmission lines

Pipelines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands

Upgradient Area

Areas of Concern

N

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Vernola Ranch North	CLIENT:	Geotek
ADDRESS:	12080 Bellegrave Avenue Mira Loma CA 91752	CONTACT:	Anna M. Scott
LAT/LONG:	33.984882 / 117.546146	INQUIRY #:	6691091.2s
		DATE:	October 06, 2021 8:29 am

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS

LEGEND

FACILITY NAME **FACILITY ADDRESS, CITY, ST, ZIP**		EDR SITE ID NUMBER
◆ **MAP ID#**	Direction Distance Range (Distance feet / miles) Relative Elevation Feet Above Sea Level	ASTM 2600 Record Sources found in this report. Each database searched has been assigned to one or more categories. For detailed information about categorization, see the section of the report Records Searched and Currency.

Worksheet:

Comments:
Comments may be added on the online Vapor Encroachment Worksheet.

DATABASE ACRONYM: Applicable categories (A hoverbox with database description).

SAMUEL P LEWIS DBA CHINO WELDING & ASSEM 12080 BELLEGRAVE AVE, MIRA LOMA, CA, 91752		1014675681
▲ A1	Target Property 689 ft. Above Sea Level	Other Ascertainable Records

Worksheet:

VERNOLA RANCH 12080 BELLEGRAVE AVE, MIRA LOMA, CA, 91752		1023257663
▲ A2	Target Property 689 ft. Above Sea Level	Other Ascertainable Records

Worksheet:

SAMUEL P LEWIS DBA CHINO WELDING & ASSEM 12080 BELLEGRAVE AVE, MIRA LOMA, CA, 91752		S106934062
▲ A3	Target Property 689 ft. Above Sea Level	Local Lists of Registered Storage Tanks Other Ascertainable Records

Worksheet:

BERNOLA RANCH 12080 BELLGRAVE AVE, MIRA LOMA, CA, 917520000		S124559684
▲ A4	Target Property 689 ft. Above Sea Level	Other Ascertainable Records

Worksheet:

VERNOLA RANCH 12080 BELLEGRAVE AVE, MIRA LOMA, CA, 91752			S112941096
▲ A5	Target Property	689 ft. Above Sea Level	Other Ascertainable Records

Worksheet:

VERNOLA RANCH 12080 BELLEGRAVE AVE., MIRA LOMA, CA, 91752			U002095767
▲ A6	Target Property	689 ft. Above Sea Level	State and tribal registered storage tank lists

Worksheet:

HARVEST NW OF LIMONITE AVE AND WINEVILLE AVE, MIRA LOMA, CA, 92509			S113450185
◆ 7	SE <1/10	(0 ft. / 0 mi.)	Other Ascertainable Records
	3 ft. Lower Elevation	686 ft. Above Sea Level	

Worksheet:

ELEMENTARY SCHOOL NO. 17 WINEVILLE ROAD/BELLGRAVE AVENUE, MIRA LOMA, CA, 91752			S118756715
▲ 8	NNE 1/10 - 1/3	(568 ft. / 0.108 mi.)	State- and tribal - equivalent CERCLIS Local Lists of Hazardous waste / Contaminated Sites
	6 ft. Higher Elevation	695 ft. Above Sea Level	

Worksheet:

WELL II-7 Not Reported, JURUPA VALLEY, CA,			S127520108
▲ 9	NE 1/10 - 1/3	(869 ft. / 0.165 mi.)	Local Lists of Hazardous waste / Contaminated Sites
	5 ft. Higher Elevation	694 ft. Above Sea Level	

Worksheet:

WELL II-8 Not Reported, JURUPA VALLEY, CA,			S127520101
▲ 10	ENE 1/10 - 1/3	(869 ft. / 0.165 mi.)	Local Lists of Hazardous waste / Contaminated Sites
	2 ft. Higher Elevation	691 ft. Above Sea Level	

Worksheet:

MAP FINDINGS

WELL II-6 Not Reported, JURUPA VALLEY, CA,			S127520111
▲ 11	NNE 1/10 - 1/3	(1279 ft. / 0.242 mi.)	Local Lists of Hazardous waste / Contaminated Sites
	23 ft. Higher Elevation	712 ft. Above Sea Level	

Worksheet:

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
ENVIRONMENTAL RECORDS						
Federal NPL site list						
US	NPL	National Priority List	EPA	07/29/2021	08/04/2021	08/31/2021
US	Proposed NPL	Proposed National Priority List Sites	EPA	07/29/2021	08/04/2021	08/31/2021
US	NPL LIENS	Federal Superfund Liens	EPA	10/15/1991	02/02/1994	03/30/1994
Federal CERCLIS list						
US	SEMS	Superfund Enterprise Management System	EPA	07/29/2021	08/04/2021	08/31/2021
Federal RCRA CORRACTS facilities list						
US	CORRACTS	Corrective Action Report	EPA	03/22/2021	03/23/2021	05/19/2021
Federal RCRA TSD facilities list						
US	RCRA-TSDF	RCRA - Treatment, Storage and Disposal	Environmental Protection Agency	03/22/2021	03/23/2021	05/19/2021
Federal RCRA generators list						
US	RCRA-LQG	RCRA - Large Quantity Generators	Environmental Protection Agency	03/22/2021	03/23/2021	05/19/2021
US	RCRA-SQG	RCRA - Small Quantity Generators	Environmental Protection Agency	03/22/2021	03/23/2021	05/19/2021
US	RCRA-VSQG	RCRA - Very Small Quantity Generators (Formerly Conditionall	Environmental Protection Agency	03/22/2021	03/23/2021	05/19/2021
Federal institutional controls / engineering controls registries						
US	LUCIS	Land Use Control Information System	Department of the Navy	05/10/2021	05/13/2021	08/03/2021
US	US ENG CONTROLS	Engineering Controls Sites List	Environmental Protection Agency	05/17/2021	05/21/2021	08/11/2021
US	US INST CONTROLS	Institutional Controls Sites List	Environmental Protection Agency	05/17/2021	05/21/2021	08/11/2021
Federal ERNS list						
US	ERNS	Emergency Response Notification System	National Response Center, United States Coast	06/14/2021	06/17/2021	08/17/2021
State and tribal - equivalent NPL						
CA	RESPONSE	State Response Sites	Department of Toxic Substances Control	04/23/2021	04/23/2021	07/12/2021
State and tribal - equivalent CERCLIS						
CA	ENVIROSTOR	EnviroStor Database	Department of Toxic Substances Control	04/23/2021	04/23/2021	07/12/2021
State and tribal landfill / solid waste disposal						
CA	SWF/LF (SWIS)	Solid Waste Information System	Department of Resources Recycling and Recover	05/10/2021	05/11/2021	07/27/2021
State and tribal leaking storage tank lists						
CA	LUST REG 9	Leaking Underground Storage Tank Report	California Regional Water Quality Control Boa	03/01/2001	04/23/2001	05/21/2001
CA	LUST	Leaking Underground Fuel Tank Report (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	LUST REG 8	Leaking Underground Storage Tanks	California Regional Water Quality Control Boa	02/14/2005	02/15/2005	03/28/2005
CA	LUST REG 7	Leaking Underground Storage Tank Case Listing	California Regional Water Quality Control Boa	02/26/2004	02/26/2004	03/24/2004
CA	LUST REG 5	Leaking Underground Storage Tank Database	California Regional Water Quality Control Boa	07/01/2008	07/22/2008	07/31/2008
CA	LUST REG 4	Underground Storage Tank Leak List	California Regional Water Quality Control Boa	09/07/2004	09/07/2004	10/12/2004
CA	LUST REG 3	Leaking Underground Storage Tank Database	California Regional Water Quality Control Boa	05/19/2003	05/19/2003	06/02/2003

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
CA	LUST REG 2	Fuel Leak List	California Regional Water Quality Control Boa	09/30/2004	10/20/2004	11/19/2004
CA	LUST REG 1	Active Toxic Site Investigation	California Regional Water Quality Control Boa	02/01/2001	02/28/2001	03/29/2001
CA	LUST REG 6V	Leaking Underground Storage Tank Case Listing	California Regional Water Quality Control Boa	06/07/2005	06/07/2005	06/29/2005
CA	LUST REG 6L	Leaking Underground Storage Tank Case Listing	California Regional Water Quality Control Boa	09/09/2003	09/10/2003	10/07/2003
US	INDIAN LUST R1	Leaking Underground Storage Tanks on Indian Land	EPA Region 1	04/28/2021	06/11/2021	09/07/2021
US	INDIAN LUST R4	Leaking Underground Storage Tanks on Indian Land	EPA Region 4	05/28/2021	06/22/2021	09/20/2021
US	INDIAN LUST R6	Leaking Underground Storage Tanks on Indian Land	EPA Region 6	05/17/2021	06/11/2021	09/07/2021
US	INDIAN LUST R5	Leaking Underground Storage Tanks on Indian Land	EPA, Region 5	04/06/2021	06/11/2021	09/07/2021
US	INDIAN LUST R10	Leaking Underground Storage Tanks on Indian Land	EPA Region 10	04/27/2021	06/11/2021	09/07/2021
US	INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land	Environmental Protection Agency	05/27/2021	06/11/2021	09/07/2021
US	INDIAN LUST R8	Leaking Underground Storage Tanks on Indian Land	EPA Region 8	05/27/2021	06/11/2021	09/07/2021
US	INDIAN LUST R7	Leaking Underground Storage Tanks on Indian Land	EPA Region 7	06/01/2021	06/11/2021	09/07/2021
CA	CPS-SLIC	Statewide SLIC Cases (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	SLIC REG 1	Active Toxic Site Investigations	California Regional Water Quality Control Boa	04/03/2003	04/07/2003	04/25/2003
CA	SLIC REG 2	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	Regional Water Quality Control Board San Fran	09/30/2004	10/20/2004	11/19/2004
CA	SLIC REG 3	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	California Regional Water Quality Control Boa	05/18/2006	05/18/2006	06/15/2006
CA	SLIC REG 4	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	Region Water Quality Control Board Los Angele	11/17/2004	11/18/2004	01/04/2005
CA	SLIC REG 5	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	Regional Water Quality Control Board Central	04/01/2005	04/05/2005	04/21/2005
CA	SLIC REG 6V	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	Regional Water Quality Control Board, Victorv	05/24/2005	05/25/2005	06/16/2005
CA	SLIC REG 6L	SLIC Sites	California Regional Water Quality Control Boa	09/07/2004	09/07/2004	10/12/2004
CA	SLIC REG 7	SLIC List	California Regional Quality Control Board, Co	11/24/2004	11/29/2004	01/04/2005
CA	SLIC REG 8	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	California Region Water Quality Control Board	04/03/2008	04/03/2008	04/14/2008
CA	SLIC REG 9	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	California Regional Water Quality Control Boa	09/10/2007	09/11/2007	09/28/2007
State and tribal registered storage tank lists						
CA	UST	Active UST Facilities	SWRCB	06/03/2021	06/03/2021	08/24/2021
CA	MILITARY UST SITES	Military UST Sites (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	UST CLOSURE	Proposed Closure of Underground Storage Tank (UST) Cases	State Water Resources Control Board	05/20/2021	06/04/2021	08/30/2021
CA	AST	Aboveground Petroleum Storage Tank Facilities	California Environmental Protection Agency	07/06/2016	07/12/2016	09/19/2016
US	INDIAN UST R1	Underground Storage Tanks on Indian Land	EPA, Region 1	04/28/2021	06/11/2021	09/07/2021
US	INDIAN UST R10	Underground Storage Tanks on Indian Land	EPA Region 10	04/27/2021	06/11/2021	09/07/2021
US	INDIAN UST R5	Underground Storage Tanks on Indian Land	EPA Region 5	04/06/2021	06/11/2021	09/07/2021
US	INDIAN UST R8	Underground Storage Tanks on Indian Land	EPA Region 8	05/27/2021	06/11/2021	09/07/2021
US	INDIAN UST R9	Underground Storage Tanks on Indian Land	EPA Region 9	05/27/2021	06/11/2021	09/07/2021
US	INDIAN UST R6	Underground Storage Tanks on Indian Land	EPA Region 6	05/17/2021	06/11/2021	09/07/2021
US	INDIAN UST R7	Underground Storage Tanks on Indian Land	EPA Region 7	06/01/2021	06/11/2021	09/07/2021
US	INDIAN UST R4	Underground Storage Tanks on Indian Land	EPA Region 4	05/28/2021	06/22/2021	09/20/2021
US	FEMA UST	Underground Storage Tank Listing	FEMA	01/29/2021	02/17/2021	03/22/2021
State and tribal voluntary cleanup sites						
CA	VCP	Voluntary Cleanup Program Properties	Department of Toxic Substances Control	04/23/2021	04/23/2021	07/12/2021
US	INDIAN VCP R1	Voluntary Cleanup Priority Listing	EPA, Region 1	07/27/2015	09/29/2015	02/18/2016
US	INDIAN VCP R7	Voluntary Cleanup Priority Lisitng	EPA, Region 7	03/20/2008	04/22/2008	05/19/2008

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
State and tribal Brownfields sites						
CA	BROWNFIELDS	Considered Brownfieds Sites Listing	State Water Resources Control Board	06/17/2021	06/17/2021	09/13/2021
Other Records						
US	CONSENT	Superfund (CERCLA) Consent Decrees	Department of Justice, Consent Decree Library	06/30/2021	07/14/2021	07/16/2021
US	ROD	Records Of Decision	EPA	07/29/2021	08/04/2021	08/31/2021
US	LIENS 2	CERCLA Lien Information	Environmental Protection Agency	07/29/2021	08/04/2021	08/31/2021
CA	HIST CAL-SITES	Calsites Database	Department of Toxic Substance Control	08/08/2005	08/03/2006	08/24/2006
US	DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations	EPA, Region 9	01/12/2009	05/07/2009	09/21/2009
CA	SWRCY	Recycler Database	Department of Conservation	06/04/2021	06/04/2021	08/27/2021
CA	CA FID UST	Facility Inventory Database	California Environmental Protection Agency	10/31/1994	09/05/1995	09/29/1995
CA	HIST UST	Hazardous Substance Storage Container Database	State Water Resources Control Board	10/15/1990	01/25/1991	02/12/1991
CA	SAN FRANCISCO AST	Aboveground Storage Tank Site Listing	San Francisco County Department of Public Hea	05/06/2021	05/07/2021	07/23/2021
CA	SWEEPS UST	SWEEPS UST Listing	State Water Resources Control Board	06/01/1994	07/07/2005	08/11/2005
US	US FIN ASSUR	Financial Assurance Information	Environmental Protection Agency	09/13/2021	09/15/2021	09/28/2021
US	COAL ASH DOE	Steam-Electric Plant Operation Data	Department of Energy	12/31/2019	12/01/2020	02/09/2021
US	LEAD SMELTER 2	Lead Smelter Sites	American Journal of Public Health	04/05/2001	10/27/2010	12/02/2010
US	2020 COR ACTION	2020 Corrective Action Program List	Environmental Protection Agency	09/30/2017	05/08/2018	07/20/2018
US	FUSRAP	Formerly Utilized Sites Remedial Action Program	Department of Energy	08/08/2017	09/11/2018	09/14/2018
US	EPA WATCH LIST	EPA WATCH LIST	Environmental Protection Agency	08/30/2013	03/21/2014	06/17/2014
US	LEAD SMELTER 1	Lead Smelter Sites	Environmental Protection Agency	07/29/2021	08/04/2021	08/31/2021
US	US AIRS MINOR	Air Facility System Data	EPA	10/12/2016	10/26/2016	02/03/2017
US	US AIRS (AFS)	Aerometric Information Retrieval System Facility Subsystem (	EPA	10/12/2016	10/26/2016	02/03/2017
US	SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing	Environmental Protection Agency	01/01/2017	02/03/2017	04/07/2017
US	PCB TRANSFORMER	PCB Transformer Registration Database	Environmental Protection Agency	09/13/2019	11/06/2019	02/10/2020
US	COAL ASH EPA	Coal Combustion Residues Surface Impoundments List	Environmental Protection Agency	01/12/2017	03/05/2019	11/11/2019
US	US HIST CDL	National Clandestine Laboratory Register	Drug Enforcement Administration	05/18/2021	05/18/2021	08/03/2021
US	Delisted NPL	National Priority List Deletions	EPA	07/29/2021	08/04/2021	08/31/2021
US	SEMS-ARCHIVE	Superfund Enterprise Management System Archive	EPA	07/29/2021	08/04/2021	08/31/2021
US	RCRA NonGen / NLR	RCRA - Non Generators / No Longer Regulated	Environmental Protection Agency	03/22/2021	03/23/2021	05/19/2021
US	HMIRS	Hazardous Materials Information Reporting System	U.S. Department of Transportation	09/12/2021	09/13/2021	09/28/2021
US	DOT OPS	Incident and Accident Data	Department of Transporation, Office of Pipeli	01/02/2020	01/28/2020	04/17/2020
US	US CDL	Clandestine Drug Labs	Drug Enforcement Administration	05/18/2021	05/18/2021	08/03/2021
US	US BROWNFIELDS	A Listing of Brownfields Sites	Environmental Protection Agency	06/10/2021	06/10/2021	08/17/2021
US	DOD	Department of Defense Sites	USGS	12/31/2005	11/10/2006	01/11/2007
US	FEDLAND	Federal and Indian Lands	U.S. Geological Survey	04/02/2018	04/11/2018	11/06/2019
US	FUDS	Formerly Used Defense Sites	U.S. Army Corps of Engineers	05/04/2021	05/18/2021	08/11/2021
US	UMTRA	Uranium Mill Tailings Sites	Department of Energy	08/30/2019	11/15/2019	01/28/2020
US	ODI	Open Dump Inventory	Environmental Protection Agency	06/30/1985	08/09/2004	09/17/2004
US	US MINES	Mines Master Index File	Department of Labor, Mine Safety and Health A	05/03/2021	05/25/2021	08/11/2021
US	MINES VIOLATIONS	MSHA Violation Assessment Data	DOL, Mine Safety & Health Admi	06/30/2021	07/01/2021	09/28/2021
US	US MINES 2	Ferrous and Nonferrous Metal Mines Database Listing	USGS	05/06/2020	05/27/2020	08/13/2020
US	US MINES 3	Active Mines & Mineral Plants Database Listing	USGS	04/14/2011	06/08/2011	09/13/2011
US	PRP	Potentially Responsible Parties	EPA	12/30/2020	01/14/2021	03/05/2021
US	TRIS	Toxic Chemical Release Inventory System	EPA	12/31/2018	08/14/2020	11/04/2020
US	TSCA	Toxic Substances Control Act	EPA	12/31/2016	06/17/2020	09/10/2020

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA/Office of Prevention, Pesticides and Toxi	04/09/2009	04/16/2009	05/11/2009
US	FTTS INSP	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA	04/09/2009	04/16/2009	05/11/2009
US	HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HIST FTTS INSP	FIFRA/TSCA Tracking System Inspection & Enforcement Case Lis	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	SSTS	Section 7 Tracking Systems	EPA	04/19/2021	04/20/2021	07/16/2021
US	ICIS	Integrated Compliance Information System	Environmental Protection Agency	11/18/2016	11/23/2016	02/10/2017
US	PADS	PCB Activity Database System	EPA	11/19/2020	01/08/2021	03/22/2021
US	MLTS	Material Licensing Tracking System	Nuclear Regulatory Commission	03/08/2021	03/11/2021	05/11/2021
US	RADINFO	Radiation Information Database	Environmental Protection Agency	07/01/2019	07/01/2019	09/23/2019
US	FINDS	Facility Index System/Facility Registry System	EPA	05/05/2021	05/18/2021	08/17/2021
US	RAATS	RCRA Administrative Action Tracking System	EPA	04/17/1995	07/03/1995	08/07/1995
US	RMP	Risk Management Plans	Environmental Protection Agency	05/07/2021	05/13/2021	08/03/2021
US	BRS	Biennial Reporting System	EPA/NTIS	12/31/2017	06/22/2020	11/20/2020
US	PWS	Public Water System Data	EPA	12/17/2013	01/09/2014	10/15/2014
US	INDIAN RESERV	Indian Reservations	USGS	12/31/2014	07/14/2015	01/10/2017
US	INDIAN ODI	Report on the Status of Open Dumps on Indian Lands	Environmental Protection Agency	12/31/1998	12/03/2007	01/24/2008
US	IHS OPEN DUMPS	Open Dumps on Indian Land	Department of Health & Human Serivces, Indian	04/01/2014	08/06/2014	01/29/2015
US	ABANDONED MINES	Abandoned Mines	Department of Interior	06/15/2021	06/16/2021	08/17/2021
CA	CA BOND EXP. PLAN	Bond Expenditure Plan	Department of Health Services	01/01/1989	07/27/1994	08/02/1994
CA	CDL	Clandestine Drug Labs	Department of Toxic Substances Control	12/31/2019	01/20/2021	04/08/2021
CA	CHMIRS	California Hazardous Material Incident Report System	Office of Emergency Services	04/04/2021	04/20/2021	07/07/2021
CA	CORTESE	"Cortese" Hazardous Waste & Substances Sites List	CAL EPA/Office of Emergency Information	06/17/2021	06/17/2021	09/14/2021
CA	CUPA LIVERMORE-PLEASANTON	CUPA Facility Listing	Livermore-Pleasanton Fire Department	05/01/2019	05/14/2019	07/17/2019
CA	DEED	Deed Restriction Listing	DTSC and SWRCB	05/28/2021	05/28/2021	08/20/2021
CA	DRYCLEAN AVAQMD	Antelope Valley Air Quality Management District Drycleaner L	Antelope Valley Air Quality Management Distri	05/25/2021	05/26/2021	08/18/2021
CA	DRYCLEANERS	Cleaner Facilities	Department of Toxic Substance Control	05/25/2021	05/28/2021	08/20/2021
CA	DRYCLEAN SOUTH COAST	South Coast Air Quality Management District Drycleaner Listi	South Coast Air Quality Management District	05/18/2021	05/19/2021	08/05/2021
CA	EMI	Emissions Inventory Data	California Air Resources Board	12/31/2019	06/10/2021	08/27/2021
CA	ENF	Enforcement Action Listing	State Water Resoruces Control Board	04/16/2021	04/20/2021	07/07/2021
CA	Financial Assurance 1	Financial Assurance Information Listing	Department of Toxic Substances Control	04/14/2021	04/15/2021	07/06/2021
CA	Financial Assurance 2	Financial Assurance Information Listing	California Integrated Waste Management Board	05/13/2021	05/13/2021	07/26/2021
CA	HAULERS	Registered Waste Tire Haulers Listing	Integrated Waste Management Board	11/23/2020	11/23/2020	02/08/2021
CA	HAZNET	Facility and Manifest Data	California Environmental Protection Agency	12/31/2019	04/15/2020	07/02/2020
CA	HIST CORTESE	Hazardous Waste & Substance Site List	Department of Toxic Substances Control	04/01/2001	01/22/2009	04/08/2009
CA	HWP	EnviroStor Permitted Facilities Listing	Department of Toxic Substances Control	05/14/2021	05/14/2021	07/27/2021
CA	HWT	Registered Hazardous Waste Transporter Database	Department of Toxic Substances Control	07/01/2021	07/01/2021	09/24/2021
CA	ICE	ICE	Department of Toxic Subsances Control	05/14/2021	05/14/2021	07/27/2021
CA	LDS	Land Disposal Sites Listing (GEOTRACKER)	State Water Qualilty Control Board	06/03/2021	06/03/2021	08/24/2021
CA	LIENS	Environmental Liens Listing	Department of Toxic Substances Control	05/27/2021	05/28/2021	08/20/2021
CA	MCS	Military Cleanup Sites Listing (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	MINES	Mines Site Location Listing	Department of Conservation	06/03/2021	06/03/2021	08/24/2021
CA	MWMP	Medical Waste Management Program Listing	Department of Public Health	05/06/2021	05/28/2021	08/20/2021
CA	NPDES	NPDES Permits Listing	State Water Resources Control Board	05/10/2021	05/11/2021	07/27/2021
CA	PEST LIC	Pesticide Regulation Licenses Listing	Department of Pesticide Regulation	05/28/2021	05/28/2021	08/20/2021
CA	PROC	Certified Processors Database	Department of Conservation	06/04/2021	06/04/2021	08/27/2021
CA	NOTIFY 65	Proposition 65 Records	State Water Resources Control Board	03/12/2021	03/16/2021	06/01/2021
CA	SCH	School Property Evaluation Program	Department of Toxic Substances Control	04/23/2021	04/23/2021	07/12/2021

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
CA	SPILLS 90	SPILLS90 data from FirstSearch	FirstSearch	06/06/2012	01/03/2013	02/22/2013
CA	TOXIC PITS	Toxic Pits Cleanup Act Sites	State Water Resources Control Board	07/01/1995	08/30/1995	09/26/1995
CA	UIC	UIC Listing	Deaprtment of Conservation	06/03/2021	06/03/2021	08/25/2021
CA	WASTEWATER PITS	Oil Wastewater Pits Listing	RWQCB, Central Valley Region	02/11/2021	07/01/2021	09/29/2021
CA	WDS	Waste Discharge System	State Water Resources Control Board	06/19/2007	06/20/2007	06/29/2007
CA	WIP	Well Investigation Program Case List	Los Angeles Water Quality Control Board	07/03/2009	07/21/2009	08/03/2009
CA	WMUDS/SWAT	Waste Management Unit Database	State Water Resources Control Board	04/01/2000	04/10/2000	05/10/2000
CA	CIWQS	California Integrated Water Quality System	State Water Resources Control Board	05/19/2021	05/19/2021	08/12/2021
US	FEDERAL FACILITY	Federal Facility Site Information listing	Environmental Protection Agency	05/25/2021	06/24/2021	09/20/2021
CA	HWTS	Hazardous Waste Tracking System	Department of Toxic Substances Control	04/08/2021	04/09/2021	04/20/2021
US	MINES MRDS	Mineral Resources Data System	USGS	04/06/2018	10/21/2019	10/24/2019
US	UXO	Unexploded Ordnance Sites	Department of Defense	12/31/2018	07/02/2020	09/17/2020
CA	CERS TANKS	California Environmental Reporting System (CERS) Tanks	California Environmental Protection Agency	04/19/2021	04/20/2021	07/07/2021
CA	CERS	CalEPA Regulated Site Portal Data	California Environmental Protection Agency	04/19/2021	04/20/2021	07/07/2021
CA	CERS HAZ WASTE	CERS HAZ WASTE	CalEPA	04/19/2021	04/20/2021	07/07/2021
US	DOCKET HWC	Hazardous Waste Compliance Docket Listing	Environmental Protection Agency	05/06/2021	05/21/2021	08/11/2021
CA	PFAS	PFAS Contamination Site Location Listing	State Water Resources Control Board	06/04/2021	06/04/2021	08/27/2021
CA	WDR	Waste Discharge Requirements Listing	State Water Resources Control Board	06/07/2021	06/07/2021	08/27/2021
CA	WELL STIM PROJ	Well Stimulation Project (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/25/2021
CA	MILITARY PRIV SITES	Military Privatized Sites (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	UIC GEO	Underground Injection Control Sites (GEOTRACKER)	State Water Resource Control Board	06/03/2021	06/03/2021	08/24/2021
US	ECHO	Enforcement & Compliance History Information	Environmental Protection Agency	06/26/2021	07/01/2021	09/28/2021
US	FUELS PROGRAM	EPA Fuels Program Registered Listing	EPA	05/14/2021	05/14/2021	08/03/2021
CA	NON-CASE INFO	Non-Case Information Sites (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	OTHER OIL GAS	Other Oil & Gas Projects Sites (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	PROD WATER PONDS	Produced Water Ponds Sites (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	PROJECT	Project Sites (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
CA	SAMPLING POINT	Sampling Point ? Public Sites (GEOTRACKER)	State Water Resources Control Board	06/03/2021	06/03/2021	08/24/2021
HISTORICAL USE RECORDS						
US	EDR MGP	EDR Proprietary Manufactured Gas Plants	EDR, Inc.			
US	EDR Hist Auto	EDR Exclusive Historical Auto Stations	EDR, Inc.			
US	EDR Hist Cleaner	EDR Exclusive Historical Cleaners	EDR, Inc.			
CA	RGA LF	Recovered Government Archive Solid Waste Facilities List	Department of Resources Recycling and Recover		07/01/2013	01/13/2014
CA	RGA LUST	Recovered Government Archive Leaking Underground Storage Tan	State Water Resources Control Board		07/01/2013	12/30/2013

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
COUNTY RECORDS						
CA	CS ALAMEDA	Contaminated Sites	Alameda County Environmental Health Services	01/09/2019	01/11/2019	03/05/2019
CA	UST ALAMEDA	Underground Tanks	Alameda County Environmental Health Services	06/29/2021	06/30/2021	09/22/2021
CA	CUPA AMADOR	CUPA Facility List	Amador County Environmental Health	08/05/2021	08/06/2021	09/17/2021
CA	CUPA BUTTE	CUPA Facility Listing	Public Health Department	04/21/2017	04/25/2017	08/09/2017
CA	CUPA CALVERAS	CUPA Facility Listing	Calveras County Environmental Health	06/15/2021	06/16/2021	07/02/2021
CA	CUPA COLUSA	CUPA Facility List	Health & Human Services	04/06/2020	04/23/2020	07/10/2020
CA	SL CONTRA COSTA	Site List	Contra Costa Health Services Department	04/21/2021	04/22/2021	07/12/2021
CA	CUPA DEL NORTE	CUPA Facility List	Del Norte County Environmental Health Divisio	12/17/2020	01/28/2021	04/16/2021
CA	CUPA EL DORADO	CUPA Facility List	El Dorado County Environmental Management Dep	05/10/2021	05/12/2021	07/26/2021
CA	CUPA FRESNO	CUPA Resources List	Dept. of Community Health	04/09/2021	06/23/2021	09/17/2021
CA	CUPA GLENN	CUPA Facility List	Glenn County Air Pollution Control District	01/22/2018	01/24/2018	03/14/2018
CA	CUPA HUMBOLDT	CUPA Facility List	Humboldt County Environmental Health	05/17/2021	05/18/2021	05/20/2021
CA	CUPA IMPERIAL	CUPA Facility List	San Diego Border Field Office	04/14/2021	04/15/2021	07/06/2021
CA	CUPA INYO	CUPA Facility List	Inyo County Environmental Health Services	04/02/2018	04/03/2018	06/14/2018
CA	CUPA KERN	CUPA Facility List	Kern County Public Health	04/22/2021	04/30/2021	07/19/2021
CA	UST KERN	Underground Storage Tank Sites & Tank Listing	Kern County Environment Health Services Depar	07/06/2021	08/12/2021	08/18/2021
CA	CUPA KINGS	CUPA Facility List	Kings County Department of Public Health	12/03/2020	01/26/2021	04/14/2021
CA	CUPA LAKE	CUPA Facility List	Lake County Environmental Health	05/10/2021	05/12/2021	07/26/2021
CA	CUPA LASSEN	CUPA Facility List	Lassen County Environmental Health	07/31/2020	08/21/2020	11/09/2020
CA	AOCONCERN	Key Areas of Concerns in Los Angeles County		03/30/2009	03/31/2009	10/23/2009
CA	HMS LOS ANGELES	HMS: Street Number List	Department of Public Works	07/08/2021	07/09/2021	09/29/2021
CA	LF LOS ANGELES	List of Solid Waste Facilities	La County Department of Public Works	07/09/2021	07/09/2021	09/29/2021
CA	LF LOS ANGELES CITY	City of Los Angeles Landfills	Engineering & Construction Division	01/01/2021	02/18/2021	05/10/2021
CA	LOS ANGELES AST	Active & Inactive AST Inventory	Los Angeles Fire Department	06/01/2019	06/25/2019	08/22/2019
CA	LOS ANGELES CO LF METHANE	Methane Producing Landfills	Los Angeles County Department of Public Works	02/04/2021	04/16/2021	04/21/2021
CA	LOS ANGELES HM	Active & Inactive Hazardous Materials Inventory	Los Angeles Fire Department	04/19/2021	06/17/2021	06/28/2021
CA	LOS ANGELES UST	Active & Inactive UST Inventory	Los Angeles Fire Department	04/19/2021	06/17/2021	09/14/2021
CA	SITE MIT LOS ANGELES	Site Mitigation List	Community Health Services	05/26/2021	07/09/2021	09/29/2021
CA	UST EL SEGUNDO	City of El Segundo Underground Storage Tank	City of El Segundo Fire Department	01/21/2017	04/19/2017	05/10/2017
CA	UST LONG BEACH	City of Long Beach Underground Storage Tank	City of Long Beach Fire Department	04/22/2019	04/23/2019	06/27/2019
CA	UST TORRANCE	City of Torrance Underground Storage Tank	City of Torrance Fire Department	02/02/2021	04/28/2021	07/13/2021
CA	CUPA MADERA	CUPA Facility List	Madera County Environmental Health	08/10/2020	08/12/2020	10/23/2020
CA	UST MARIN	Underground Storage Tank Sites	Public Works Department Waste Management	09/26/2018	10/04/2018	11/02/2018
CA	UST MENDOCINO	Mendocino County UST Database	Department of Public Health	03/24/2021	04/07/2021	06/24/2021
CA	CUPA MERCED	CUPA Facility List	Merced County Environmental Health	05/13/2021	05/14/2021	07/26/2021
CA	CUPA MONO	CUPA Facility List	Mono County Health Department	02/22/2021	03/02/2021	05/19/2021
CA	CUPA MONTEREY	CUPA Facility Listing	Monterey County Health Department	06/23/2021	06/23/2021	06/24/2021
CA	LUST NAPA	Sites With Reported Contamination	Napa County Department of Environmental Manag	01/09/2017	01/11/2017	03/02/2017
CA	UST NAPA	Closed and Operating Underground Storage Tank Sites	Napa County Department of Environmental Manag	09/05/2019	09/09/2019	10/31/2019
CA	CUPA NEVADA	CUPA Facility List	Community Development Agency	04/28/2021	04/29/2021	07/15/2021
CA	IND_SITE ORANGE	List of Industrial Site Cleanups	Health Care Agency	03/01/2021	04/30/2021	07/19/2021
CA	LUST ORANGE	List of Underground Storage Tank Cleanups	Health Care Agency	03/01/2021	05/03/2021	05/12/2021
CA	UST ORANGE	List of Underground Storage Tank Facilities	Health Care Agency	04/29/2021	04/30/2021	07/19/2021
CA	MS PLACER	Master List of Facilities	Placer County Health and Human Services	05/25/2021	05/26/2021	06/01/2021
CA	CUPA PLUMAS	CUPA Facility List	Plumas County Environmental Health	03/31/2019	04/23/2019	06/26/2019

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
CA	LUST RIVERSIDE	Listing of Underground Tank Cleanup Sites	Department of Environmental Health	06/29/2021	06/30/2021	07/14/2021
CA	UST RIVERSIDE	Underground Storage Tank Tank List	Department of Environmental Health	06/29/2021	06/30/2021	07/14/2021
CA	CS SACRAMENTO	Toxic Site Clean-Up List	Sacramento County Environmental Management	03/30/2021	04/01/2021	06/23/2021
CA	ML SACRAMENTO	Master Hazardous Materials Facility List	Sacramento County Environmental Management	03/30/2021	04/01/2021	06/25/2021
CA	CUPA SAN BENITO	CUPA Facility List	San Benito County Environmental Health	04/28/2021	04/29/2021	05/03/2021
CA	PERMITS SAN BERNARDINO	Hazardous Material Permits	San Bernardino County Fire Department Hazardo	05/19/2021	05/19/2021	06/07/2021
CA	HMMD SAN DIEGO	Hazardous Materials Management Division Database	Hazardous Materials Management Division	05/28/2021	05/28/2021	08/20/2021
CA	LF SAN DIEGO	Solid Waste Facilities	Department of Health Services	10/01/2020	11/23/2020	02/08/2021
CA	SAN DIEGO CO LOP	Local Oversight Program Listing	Department of Environmental Health	07/14/2020	07/16/2020	09/29/2020
CA	SAN DIEGO CO SAM	Environmental Case Listing	San Diego County Department of Environmental	03/23/2010	06/15/2010	07/09/2010
CA	CUPA SAN FRANCISCO CO	CUPA Facility Listing	San Francisco County Department of Environmen	05/06/2021	05/07/2021	07/23/2021
CA	LUST SAN FRANCISCO	Local Oversite Facilities	Department Of Public Health San Francisco Cou	09/19/2008	09/19/2008	09/29/2008
CA	UST SAN FRANCISCO	Underground Storage Tank Information	Department of Public Health	05/06/2021	05/07/2021	07/23/2021
CA	UST SAN JOAQUIN	San Joaquin Co. UST	Environmental Health Department	06/22/2018	06/26/2018	07/11/2018
CA	CUPA SAN LUIS OBISPO	CUPA Facility List	San Luis Obispo County Public Health Departme	05/07/2021	05/11/2021	05/14/2021
CA	BI SAN MATEO	Business Inventory	San Mateo County Environmental Health Service	02/20/2020	02/20/2020	04/24/2020
CA	LUST SAN MATEO	Fuel Leak List	San Mateo County Environmental Health Service	03/29/2019	03/29/2019	05/29/2019
CA	CUPA SANTA BARBARA	CUPA Facility Listing	Santa Barbara County Public Health Department	09/08/2011	09/09/2011	10/07/2011
CA	CUPA SANTA CLARA	Cupa Facility List	Department of Environmental Health	02/24/2021	02/26/2021	05/19/2021
CA	HIST LUST SANTA CLARA	HIST LUST - Fuel Leak Site Activity Report	Santa Clara Valley Water District	03/29/2005	03/30/2005	04/21/2005
CA	LUST SANTA CLARA	LOP Listing	Department of Environmental Health	03/03/2014	03/05/2014	03/18/2014
CA	SAN JOSE HAZMAT	Hazardous Material Facilities	City of San Jose Fire Department	11/03/2020	11/05/2020	01/26/2021
CA	CUPA SANTA CRUZ	CUPA Facility List	Santa Cruz County Environmental Health	01/21/2017	02/22/2017	05/23/2017
CA	CUPA SHASTA	CUPA Facility List	Shasta County Department of Resource Manageme	06/15/2017	06/19/2017	08/09/2017
CA	LUST SOLANO	Leaking Underground Storage Tanks	Solano County Department of Environmental Man	06/04/2019	06/06/2019	08/13/2019
CA	UST SOLANO	Underground Storage Tanks	Solano County Department of Environmental Man	06/22/2021	06/23/2021	09/17/2021
CA	CUPA SONOMA	Cupa Facility List	County of Sonoma Fire & Emergency Services De	07/02/2021	07/06/2021	07/14/2021
CA	LUST SONOMA	Leaking Underground Storage Tank Sites	Department of Health Services	06/30/2021	06/30/2021	09/24/2021
CA	CUPA STANISLAUS	CUPA Facility List	Stanislaus County Department of Ennvironmenta	05/14/2021	05/17/2021	08/03/2021
CA	UST SUTTER	Underground Storage Tanks	Sutter County Environmental Health Services	05/25/2021	05/26/2021	08/18/2021
CA	CUPA TEHAMA	CUPA Facility List	Tehama County Department of Environmental Hea	01/13/2021	01/14/2021	04/06/2021
CA	CUPA TRINITY	CUPA Facility List	Department of Toxic Substances Control	04/14/2021	04/15/2021	07/06/2021
CA	CUPA TULARE	CUPA Facility List	Tulare County Environmental Health Services D	04/26/2021	04/28/2021	07/13/2021
CA	CUPA TUOLUMNE	CUPA Facility List	Divison of Environmental Health	04/23/2018	04/25/2018	06/25/2018
CA	BWT VENTURA	Business Plan, Hazardous Waste Producers, and Operating Unde	Ventura County Environmental Health Division	03/29/2021	04/22/2021	07/12/2021
CA	LF VENTURA	Inventory of Illegal Abandoned and Inactive Sites	Environmental Health Division	12/01/2011	12/01/2011	01/19/2012
CA	LUST VENTURA	Listing of Underground Tank Cleanup Sites	Environmental Health Division	05/29/2008	06/24/2008	07/31/2008
CA	MED WASTE VENTURA	Medical Waste Program List	Ventura County Resource Management Agency	03/29/2021	04/21/2021	04/23/2021
CA	UST VENTURA	Underground Tank Closed Sites List	Environmental Health Division	05/26/2021	06/04/2021	08/27/2021
CA	UST YOLO	Underground Storage Tank Comprehensive Facility Report	Yolo County Department of Health	06/22/2021	06/28/2021	09/21/2021
CA	CUPA YUBA	CUPA Facility List	Yuba County Environmental Health Department	04/21/2021	04/22/2021	05/12/2021

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX F

LABORATORY TEST RESULTS

Orange Coast Analytical, Inc.
3002 Dow, Suite 532, Tustin, CA 92780 (714) 832-0064 Fax (714) 832-0067
4620 E. Elwood, Suite 4, Phoenix, AZ 85040 (480) 736-0960 Fax (480) 736-0970

LABORATORY REPORT FORM

ORANGE COAST ANALYTICAL, INC.

3002 Dow Suite 532 Tustin, CA 92780

(714) 832-0064

Laboratory Certification (ELAP) No.:2576
Expiration Date: 2023
Los Angeles County Sanitation District Lab ID# 10206

Laboratory Director's Name:
Mark Noorani

Client:	GeoTek, Inc.
Laboratory Reference:	GTK 26431
Project Name:	Vernola Ranch North
Project Number:	2903-CR
Date Received:	10/13/2021
Date Reported:	10/19/2021
Chain of Custody Received:	☑
Analytical Method:	8081A, 6010B,

Mark Noorani, Laboratory Director

© This report may only be reproduced in full. Any partial reproduction of this report requires written permission from Orange Coast Analytical, Inc.

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Case Narrative

Sample Receipt:

All samples on the Chain of Custody were received by OCA at 2ºC, on ice.

Holding Times:

All samples were analyzed within required holding times unless otherwise noted in the data qualifier section of the report.

Analytical Methods:

Sample analysis was performed following the analytical methods listed on the cover page.

Data Qualifiers:

Within this report, data qualifiers may have been assigned to clarify deviations in common laboratory procedures or any divergence from laboratory QA/QC criteria. If a data qualifier has been used, it will appear in the back of the report along with its description. All method QA/QC criteria have been met unless otherwise noted in the data qualifier section.

Definition of Terms:

The definitions of common terms and acronyms used in the report have been placed at the back of the report to assist data users.

Comments:

None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Client Sample Summary

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#1	26431-001	10/13/2021	10/12/2021	Soil
#2	26431-002	10/13/2021	10/12/2021	Soil
#3	26431-003	10/13/2021	10/12/2021	Soil
#4	26431-004	10/13/2021	10/12/2021	Soil
#5	26431-005	10/13/2021	10/12/2021	Soil
#6	26431-006	10/13/2021	10/12/2021	Soil
#7	26431-007	10/13/2021	10/12/2021	Soil
#8	26431-008	10/13/2021	10/12/2021	Soil
#9	26431-009	10/13/2021	10/12/2021	Soil
#10	26431-010	10/13/2021	10/12/2021	Soil
#11	26431-011	10/13/2021	10/12/2021	Soil
#12	26431-012	10/13/2021	10/12/2021	Soil
#13	26431-013	10/13/2021	10/12/2021	Soil
#14	26431-014	10/13/2021	10/12/2021	Soil
#15	26431-015	10/13/2021	10/12/2021	Soil
#16	26431-016	10/13/2021	10/12/2021	Soil
#17	26431-017	10/13/2021	10/12/2021	Soil
#18	26431-018	10/13/2021	10/12/2021	Soil
#19	26431-019	10/13/2021	10/12/2021	Soil
#20	26431-020	10/13/2021	10/12/2021	Soil

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#1	26431-001	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 13:18	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	92

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#2	26431-002	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 13:34	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	7.1
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	94

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#3	26431-003	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 13:49	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	6.5
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	99

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#4	26431-004	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 14:04	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	98

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#5	26431-005	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 14:19	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	99

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#6	26431-006	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/18/2021 13:36	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	97

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#7	26431-007	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/18/2021 13:51	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	97

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#8	26431-008	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/18/2021 14:07	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<8.0
alpha-BHC	319-84-6	<20
beta-BHC	319-85-7	<20
gamma-BHC (Lindane)	58-89-9	<20
delta-BHC	319-86-8	<40
Chlordane	57-74-9	<120
4,4'-DDD	72-54-8	<40
4,4'-DDE	72-55-9	<20
4,4'-DDT	50-29-3	<40
Dieldrin	60-57-1	<8.0
Endosulfan I	959-98-8	<40
Endosulfan II	33213-65-9	<20
Endosulfan sulfate	1031-07-8	<40
Endrin	72-20-8	<40
Endrin aldehyde	7421-93-4	<40
Endrin ketone	53494-70-5	<20
Heptachlor	76-44-8	<8.0
Heptachlor epoxide	1024-57-3	<20
Methoxychlor	72-43-5	<40
Toxaphene	8001-35-2	<160

Surrogate:	% RC*
Decachlorobiphenyl	98

* Acceptable Recovery: 48-135 %

Dilution Factor: 4

Data Qualifiers: D1,

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#9	26431-009	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/18/2021 14:22	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<8.0
alpha-BHC	319-84-6	<20
beta-BHC	319-85-7	<20
gamma-BHC (Lindane)	58-89-9	<20
delta-BHC	319-86-8	<40
Chlordane	57-74-9	<120
4,4'-DDD	72-54-8	<40
4,4'-DDE	72-55-9	<20
4,4'-DDT	50-29-3	<40
Dieldrin	60-57-1	<8.0
Endosulfan I	959-98-8	<40
Endosulfan II	33213-65-9	<20
Endosulfan sulfate	1031-07-8	<40
Endrin	72-20-8	<40
Endrin aldehyde	7421-93-4	<40
Endrin ketone	53494-70-5	<20
Heptachlor	76-44-8	<8.0
Heptachlor epoxide	1024-57-3	<20
Methoxychlor	72-43-5	<40
Toxaphene	8001-35-2	<160

Surrogate:	% RC*
Decachlorobiphenyl	103

* Acceptable Recovery: 48-135 %

Dilution Factor: 4

Data Qualifiers: D1,

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#10	26431-010	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/18/2021 14:37	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<4.0
alpha-BHC	319-84-6	<10
beta-BHC	319-85-7	<10
gamma-BHC (Lindane)	58-89-9	<10
delta-BHC	319-86-8	<20
Chlordane	57-74-9	<60
4,4'-DDD	72-54-8	<20
4,4'-DDE	72-55-9	<10
4,4'-DDT	50-29-3	<20
Dieldrin	60-57-1	<4.0
Endosulfan I	959-98-8	<20
Endosulfan II	33213-65-9	<10
Endosulfan sulfate	1031-07-8	<20
Endrin	72-20-8	<20
Endrin aldehyde	7421-93-4	<20
Endrin ketone	53494-70-5	<10
Heptachlor	76-44-8	<4.0
Heptachlor epoxide	1024-57-3	<10
Methoxychlor	72-43-5	<20
Toxaphene	8001-35-2	<80

Surrogate:	% RC*
Decachlorobiphenyl	107

* Acceptable Recovery: 48-135 %

Dilution Factor: 2

Data Qualifiers: D1,

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#11	26431-011	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/18/2021 14:52	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<4.0
alpha-BHC	319-84-6	<10
beta-BHC	319-85-7	<10
gamma-BHC (Lindane)	58-89-9	<10
delta-BHC	319-86-8	<20
Chlordane	57-74-9	<60
4,4'-DDD	72-54-8	<20
4,4'-DDE	72-55-9	<10
4,4'-DDT	50-29-3	<20
Dieldrin	60-57-1	<4.0
Endosulfan I	959-98-8	<20
Endosulfan II	33213-65-9	<10
Endosulfan sulfate	1031-07-8	<20
Endrin	72-20-8	<20
Endrin aldehyde	7421-93-4	<20
Endrin ketone	53494-70-5	<10
Heptachlor	76-44-8	<4.0
Heptachlor epoxide	1024-57-3	<10
Methoxychlor	72-43-5	<20
Toxaphene	8001-35-2	<80

Surrogate:	% RC*
Decachlorobiphenyl	121

* Acceptable Recovery: 48-135 %

Dilution Factor: 2

Data Qualifiers: D1,

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#12	26431-012	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/18/2021 15:07	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<4.0
alpha-BHC	319-84-6	<10
beta-BHC	319-85-7	<10
gamma-BHC (Lindane)	58-89-9	<10
delta-BHC	319-86-8	<20
Chlordane	57-74-9	<60
4,4'-DDD	72-54-8	<20
4,4'-DDE	72-55-9	<10
4,4'-DDT	50-29-3	<20
Dieldrin	60-57-1	<4.0
Endosulfan I	959-98-8	<20
Endosulfan II	33213-65-9	<10
Endosulfan sulfate	1031-07-8	<20
Endrin	72-20-8	<20
Endrin aldehyde	7421-93-4	<20
Endrin ketone	53494-70-5	<10
Heptachlor	76-44-8	<4.0
Heptachlor epoxide	1024-57-3	<10
Methoxychlor	72-43-5	<20
Toxaphene	8001-35-2	<80

Surrogate:	% RC*
Decachlorobiphenyl	107

* Acceptable Recovery: 48-135 %

Dilution Factor: 2

Data Qualifiers: D1,

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#13	26431-013	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 14:34	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	6.9
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	86

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#14	26431-014	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 14:49	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	99

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#15	26431-015	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 15:05	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	97

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#16	26431-016	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 13:03	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	6.2
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	97

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#17	26431-017	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 15:20	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	111

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#18	26431-018	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 15:35	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	104

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#19	26431-019	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 15:50	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	95

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
#20	26431-020	10/13/2021 12:00	10/12/2021	10/13/2021 12:25	10/15/2021 16:05	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	86

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Organochlorine Pesticides (EPA 8081A)

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Date Extracted	Date Analyzed	Matrix
Method Blank	MBAV1013211			10/13/2021 12:25	10/15/2021 11:47	Soil

ANALYTE	CAS #	µg/kg
Aldrin	309-00-2	<2.0
alpha-BHC	319-84-6	<5.0
beta-BHC	319-85-7	<5.0
gamma-BHC (Lindane)	58-89-9	<5.0
delta-BHC	319-86-8	<10
Chlordane	57-74-9	<30
4,4'-DDD	72-54-8	<10
4,4'-DDE	72-55-9	<5.0
4,4'-DDT	50-29-3	<10
Dieldrin	60-57-1	<2.0
Endosulfan I	959-98-8	<10
Endosulfan II	33213-65-9	<5.0
Endosulfan sulfate	1031-07-8	<10
Endrin	72-20-8	<10
Endrin aldehyde	7421-93-4	<10
Endrin ketone	53494-70-5	<5.0
Heptachlor	76-44-8	<2.0
Heptachlor epoxide	1024-57-3	<5.0
Methoxychlor	72-43-5	<10
Toxaphene	8001-35-2	<40

Surrogate:	% RC*
Decachlorobiphenyl	106

* Acceptable Recovery: 48-135 %

Dilution Factor: 1

Data Qualifiers: None

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Metals

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#1	26431-001	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	4.4	mg/kg	10/13/21 16:30	10/14/21 15:17	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#2	26431-002	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	4.0	mg/kg	10/13/21 16:30	10/14/21 15:23	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#3	26431-003	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	4.0	mg/kg	10/13/21 16:30	10/14/21 15:25	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#4	26431-004	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	3.1	mg/kg	10/13/21 16:30	10/14/21 15:27	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#5	26431-005	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	3.5	mg/kg	10/13/21 16:30	10/14/21 15:29	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#6	26431-006	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	2.8	mg/kg	10/13/21 16:30	10/14/21 15:35	--	1

© Orange Coast Analytical, Inc

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Metals

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#7	26431-007	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	2.0	mg/kg	10/13/21 16:30	10/14/21 15:37	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#8	26431-008	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	2.9	mg/kg	10/13/21 16:30	10/14/21 15:39	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#9	26431-009	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	4.3	mg/kg	10/13/21 16:30	10/14/21 15:41	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#10	26431-010	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	3.7	mg/kg	10/13/21 16:30	10/14/21 15:43	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#11	26431-011	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	4.2	mg/kg	10/13/21 16:30	10/14/21 15:45	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#12	26431-012	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	3.6	mg/kg	10/13/21 16:30	10/14/21 15:47	--	1

© Orange Coast Analytical, Inc

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Metals

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#13	26431-013	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	3.4	mg/kg	10/13/21 16:30	10/14/21 15:49	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#14	26431-014	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	2.8	mg/kg	10/13/21 16:30	10/14/21 15:51	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#15	26431-015	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	5.5	mg/kg	10/13/21 16:30	10/14/21 15:53	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#16	26431-016	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	4.4	mg/kg	10/13/21 16:30	10/14/21 15:59	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#17	26431-017	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	3.8	mg/kg	10/13/21 16:30	10/14/21 16:01	--	1

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#18	26431-018	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	3.6	mg/kg	10/13/21 16:30	10/14/21 16:03	--	1

© Orange Coast Analytical, Inc

Ms. Anna Scott
GeoTek, Inc.
1548 N. Maple St
Corona, CA, 92880

Lab Reference #: GTK 26431
Project Name: Vernola Ranch North
Project #: 2903-CR

Metals

Client Sample ID	Lab Sample Number	Date Received	Date Sampled	Matrix
#19	26431-019	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	2.5	mg/kg	10/13/21 16:30	10/14/21 16:05	--	1

#20	26431-020	10/13/2021 12:00	10/12/2021	Soil

ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
Arsenic	6010B	4.4	mg/kg	10/13/21 16:30	10/14/21 16:07	--	1

Method Blank						Soil	
MB ID	ANALYTE	EPA Method	Result	Units	Date Extracted	Date Analyzed	Qual	DF
MBIR1013215	Arsenic	6010B	<2.0	mg/kg	10/13/21 16:30	10/14/21 15:11	--	1

© Orange Coast Analytical, Inc

QA/QC Report
for
Organochlorine Pesticides (EPA 8081A)
Reporting Units: ppb

Matrix Spike (MS) / Matrix Spike Duplicate (MSD)

Date of Extraction: 10/13/2021 12:25
Date of Analysis: 10/15/2021 12:33
Dup Date of Analysis: 10/15/2021 12:48
Laboratory Sample #: 26431-016
MS/MSD Qualifiers: None
Reference #: GTK 26431

Analyte	R1	Spike Conc.	MS	MSD	%MS	%MSD	RPD	ACP %MS	ACP RPD	Qual
Aldrin	0.00	20.0	16.7	18.1	84	91	8	46-130	30	--
alpha-BHC	0.00	20.0	15.0	16.7	75	84	11	30-130	30	--
beta-BHC	0.00	20.0	16.9	17.7	84	89	5	31-136	30	--
gamma-BHC (Lindane)	0.00	20.0	16.1	17.5	81	88	8	45-130	28	--
4,4'-DDD	0.00	20.0	21.2	22.4	106	112	6	49-150	26	--
4,4'-DDE	6.20	20.0	26.8	25.4	103	96	5	44-150	24	--
4,4'-DDT	0.00	20.0	24.3	24.7	121	124	2	50-150	22	--
delta-BHC	0.00	20.0	19.0	20.1	95	100	6	33-138	30	--
Dieldrin	0.00	20.0	19.1	19.6	96	98	3	49-130	25	--
Endosulfan I	0.00	20.0	19.3	20.3	96	101	5	47-130	30	--
Endosulfan II	0.00	20.0	20.6	21.8	103	109	6	30-150	30	--
Endosulfan sulfate	0.00	20.0	20.7	21.7	104	109	5	30-150	30	--
Endrin	0.00	20.0	19.7	21.6	99	108	9	52-133	25	--
Endrin Aldehyde	0.00	20.0	19.3	20.5	96	102	6	30-150	30	--
Endrin ketone	0.00	20.0	21.1	22.3	106	112	6	30-150	30	--
Heptachlor	0.00	20.0	17.0	18.5	85	93	8	46-130	30	--
Heptachlor epoxide	0.00	20.0	17.4	18.6	87	93	7	38-130	27	--
Methoxychlor	0.00	20.0	22.6	23.8	113	119	5	30-150	30	--

Surrogate Recoveries for Spike Samples

Surrogate (%RC)	MS	MSD	Qual
Decachlorobiphenyl	104	108	☐

LCS	LCSD	Qual
110	107	☐

ACP % RC
48-135

Laboratory Control Sample (LCS) / Laboratory Control Sample Duplicate (LCSD)

Date of Extraction: 10/13/2021 12:25
Date of Analysis: 10/15/2021 12:02
Dup Date of Analysis: 10/15/2021 12:18
Laboratory Sample #: AV1013211
LCS/LCSD Qualifiers: None

Analyte	Spike Conc.	LCS	LCSD	%LCS	%LCSD	RPD	ACP %LCS	ACP RPD	Qual
Aldrin	20.0	14.7	15.4	74	77	5	47-130	26	--
alpha-BHC	20.0	13.5	14.5	68	73	7	40-130	30	--
beta-BHC	20.0	17.9	17.6	89	88	2	40-130	30	--
gamma-BHC (Lindane)	20.0	14.7	15.0	74	75	2	46-130	26	--
4,4'-DDD	20.0	22.3	21.7	112	109	3	57-150	23	--
4,4'-DDE	20.0	20.2	19.3	101	96	5	48-143	24	--

QA/QC Report
for
Organochlorine Pesticides (EPA 8081A)

Reporting Units: ppb

Analyte	Spike Conc.	LCS	LCSD	%LCS	%LCSD	RPD	ACP %LCS	ACP RPD	Qual
4,4'-DDT	20.0	24.1	22.8	121	114	6	51-144	20	--
delta-BHC	20.0	19.9	19.1	100	96	4	43-130	23	--
Dieldrin	20.0	19.3	19.0	96	95	2	48-130	22	--
Endosulfan I	20.0	18.9	18.5	94	93	2	43-130	27	--
Endosulfan II	20.0	22.3	21.6	112	108	3	60-131	22	--
Endosulfan sulfate	20.0	23.8	22.6	119	113	5	54-139	25	--
Endrin	20.0	18.6	19.9	93	100	7	51-130	20	--
Endrin Aldehyde	20.0	20.2	19.5	101	98	4	40-138	30	--
Endrin ketone	20.0	22.9	22.1	114	111	4	47-132	28	--
Heptachlor	20.0	15.1	15.9	75	79	5	43-130	27	--
Heptachlor epoxide	20.0	16.9	16.7	84	84	1	40-130	30	--
Methoxychlor	20.0	25.2	23.8	126	119	6	53-140	26	--

QA/QC Report
for
Metals

Reference #: GTK 26431 Reporting units: ppm

Matrix Spike (MS) / Matrix Spike Duplicate (MSD) **6010B**

Laboratory Sample #: 26431-001 **Date of Extraction:** 10/13/21 16:30

Analyte	MS Date of Analysis	MSD Date of Analysis	R1	SPC CONC	MS	MSD	% MS	% MSD	RPD	ACP %MS	ACP RPD	Qualifiers
Arsenic	10/14/21 15:19	10/14/21 15:21	4.40	20.0	23.3	22.7	94	92	3	75-125	20	--

Laboratory Control Spike (LCS) / Laboratory Control Spike Duplicate (LCSD) **6010B**

Laboratory Sample #: IR1013215 **Date of Extraction:** 10/13/21 16:30

Analyte	LCS Date of Analysis	LCSD Date of Analysis		SPC CONC	LCS	LCSD	% LCS	% LCSD	RPD	ACP %LCS	ACP RPD	Qualifiers
Arsenic	10/14/21 15:13	10/14/21 15:15	--	20.0	19.1	19.1	96	96	0	80-120	20	--

Data Qualifier Definitions

Qualifier

D1 = Sample required dilution due to matrix.

Definition of terms:

R1	Result of unspiked laboratory sample used for matrix spike determination.
SP CONC (or Spike Conc.)	Spike concentration added to sample or blank
MS	Matrix Spike sample result
MSD	Matrix Spike Duplicate sample result
%MS	Percent recovery of MS: {(MS-R1) / SP CONC} x100
%MSD	Percent recovery of MSD: {(MSD-R1) / SP CONC} x 100
RPD (for MS/MSD)	Relative Percent Difference: {(MS-MSD) / (MS+MSD)} x 100 x 2
LCS	Laboratory Control Sample result
LCSD	Laboratory Control Sample Duplicate result
%LCS	Percent recovery of LCS: {(LCS) / SP CONC} x100
%LCSD	Percent recovery of LCSD: {(LCSD) / SP CONC} x 100
RPD (for LCS/LCSD)	Relative Percent Difference: {(LCS-LCSD) / (LCS+LCSD)} x 100 x 2
ACP %LCS	Acceptable percent recovery range for Laboratory Control Samples.
ACP %MS	Acceptable percent recovery range for Matrix Spike samples
ACP RPD	Acceptable Relative Percent Difference
D	Detectable, result must be greater than zero
Qual	A checked box indicates a data qualifier was utilized and/or required for this analyte see attached explanation.
ND	Analyte Not Detected

Analysis Request and Chain of Custody Record

Lab Job No: 26431
Page 1 of 2

ORANGE COAST ANALYTICAL, INC. www.ocalab.com

3002 Dow, Suite 532
Tustin, CA 92780
(714) 832-0064 Fax (714) 832-0067

4620 E. Elwood, Suite 4
Phoenix, AZ 85040
(480) 736-0960 Fax (480) 736-0970

REQUIRED TURN AROUND TIME: Standard: ✓ (Rush)
72 Hours:_____ 48 Hours:_____ 24 Hours:_____

CUSTOMER INFORMATION		PROJECT INFORMATION	
COMPANY:	Group Anna Scott	PROJECT NAME:	Vernola Ranch North
SEND REPORT TO:		NUMBER:	2903-CR
EMAIL:		ADDRESS:	Jurupa Valley
ADDRESS:			
		P.O. #:	
PHONE:	FAX:	SAMPLED BY:	AMS

SAMPLE ID	NO. OF CONTAINERS	SAMPLE DATE	SAMPLE TIME	SAMPLE MATRIX	CONTAINER TYPE	ANALYSIS REQUEST / PRESERVATIVE: 8081A Arsenic	REMARKS/PRECAUTIONS
#1	1	10/12	pm	soil	glass	/	
#2						/	
#3						/	
#4						/	
#5						/	
#6						/	
#7						/	
#8						/	
#9						/	
#10						/	
#11						/	
#12						/	
#13	↓	↓	↓	↓	↓	/	

Total No. of Samples: 20 Method of Shipment: Hand Delivery Preservative: 1 = Ice 2 = HCl 3 = HNO_3 4 = H_2SO_4 5 = NaOH 6 = Other

Relinquished By: Anna Scott	Date/Time: 10/13/21	Received By:	Date/Time: 10/13/21 12:00
Relinquished By:	Date/Time: 10/13/21 12:00	Received By:	Date/Time:
Relinquished By:	Date/Time:	Received For Lab By:	Date/Time: 10-13-21 1200

Sample Matrix:
GW - Groundwater
WW - Wastewater
SW - Stormwater
DW - Drinking Water
W - Water
SS - Soil/Solid
OT - Other

Sample Integrity: 2+0=2.2C
Intact:_____ On Ice: Yes / No @ 2+2=3 °C

By signing above, client acknowledges responsibility for payment of all services requested on this chain of custody form and any additional services provided in support of this project. Payment is due within 30 days of invoice date unless otherwise agreed upon, in writing, with Orange Coast Analytical, Inc. All samples remain the property of the client. A disposal fee may be imposed if client fails to pickup sample.

Analysis Request and Chain of Custody Record

Lab Job No: 26431
Page 2 of 2

ORANGE COAST ANALYTICAL, INC. www.ocalab.com

3002 Dow, Suite 532
Tustin, CA 92780
(714) 832-0064 Fax (714) 832-0067

4620 E. Elwood, Suite 4
Phoenix, AZ 85040
(480) 736-0960 Fax (480) 736-0970

REQUIRED TURN AROUND TIME: Standard: ✓
72 Hours: _____ 48 Hours: _____ 24 Hours: _____

CUSTOMER INFORMATION		PROJECT INFORMATION	
COMPANY:	GeoTek	PROJECT NAME:	Vernola Ranch North
SEND REPORT TO:	Anna Scott	NUMBER:	2903 - CR
EMAIL:		ADDRESS:	Jurupa Valley
ADDRESS:			
		P.O. #:	
PHONE:	FAX:	SAMPLED BY:	Am S

ANALYSIS REQUEST / PRESERVATIVE: 8081A, Asbestic

SAMPLE ID	NO. OF CONTAINERS	SAMPLE DATE	SAMPLE TIME	SAMPLE MATRIX	CONTAINER TYPE	REMARKS/PRECAUTIONS
#14	1	10/12	pm	soil	glass	
#15	↓	↓	↓	↓	↓	
#16						
#17						
#18						
#19						
#20						

Total No. of Samples: 20 Method of Shipment: Hand Delivery

Preservative: 1 = Ice 2 = HCl 3 = HNO_3 4 = H_2SO_4 5 = NaOH 6 = Other

Relinquished By:	Date/Time:	Received By:	Date/Time:
Am Scott	10/13/21	Dan Ft	10/13/21 12:00
Relinquished By:	Date/Time:	Received By:	Date/Time:
Dan Ft	10/13/21 1200		
Relinquished By:	Date/Time:	Received For Lab By:	Date/Time:
		Mark Mi OAS/LA	10-13-21 1200

Sample Matrix:
GW - Groundwater
WW - Wastewater
SW - Stormwater
DW - Drinking Water
W - Water
SS - Soil/Solid
OT - Other

Sample Integrity: 2 + 0 = 2.5°C
Intact: _____ On Ice: (Yes) No @ 2.5 °C

By signing above, client acknowledges responsibility for payment of all services requested on this chain of custody form and any additional services provided in support of this project. Payment is due within 30 days of invoice date unless otherwise agreed upon, in writing, with Orange Coast Analytical, Inc. All samples remain the property of the client. A disposal fee may be imposed if client fails to pickup sample

Sample Receipt Report

Laboratory Reference: **GTK 26431** Logged in by: HC

Received:	10/13/21 12:00	Company Name:	GeoTek, Inc.
Method of Shipment:	Hand Delivered	Project Manager:	Ms. Anna Scott
Shipping Container:	Cooler	Project Name:	Vernola Ranch North
# Shipping Containers:	1	Project #:	2903-CR

Sample Quantity

Chain of Custody		Complete ☑	Incomplete ☐	None ☐
Samples On Ice		Yes, Wet ☑	Yes, Blue ☐	No ☐
Observed Temp. (°C):	2	Thermometer ID: IR#3	Adjusted Temp.:	2+0=2
Shipping Intact		Yes ☑	N/A ☐	No ☐
Shipping Custody Seals Intact		Yes ☐	N/A ☑	No ☐
Samples Intact		Yes ☑		No ☐
Sample Custody Seals Intact		Yes ☐	N/A ☑	No ☐
Custody Seals Signed & Dated		Yes ☐	N/A ☑	No ☐
Proper Test Containers		Yes ☑		No ☐
Proper Test Preservations		Yes ☑		No ☐
Samples Within Hold Times		Yes ☑		No ☐
VOAs Have Zero Headspace		Yes ☐	N/A ☑	No ☐
Sample Labels		Complete ☑	Incomplete ☐	None ☐
Sample Information Matches COC		Yes ☑	N/A ☐	No ☐

Notes

Client Notified _____ By _____ On _____

APPENDIX G

PROJECT TEAM QUALIFICATIONS

Anna M. Scott

Project Geologist

Education

B.S., Geology, University of California, Riverside

Professional Experience

Ms. Anna Scott has over 30 years of geotechnical experience and has worked on or managed a wide range of geotechnical projects throughout southern California, including the High Desert, Inland Empire, Antelope Valley, Coachella Valley, Orange County and Bakersfield area. Her geotechnical experience has ranged from field and laboratory technician to field, staff and project geologist. Ms. Scott's responsibilities include preparation of proposals, preliminary geotechnical investigations, seismic studies, settlement monitor installation and studies, and field studies as a technician and geologist for large grading projects. Ms. Scott has performed Phase I and II ESAs for various property acquisitions and transfers throughout southern California.

Representative Project Experience

Ms. Scott has worked on numerous projects throughout southern California. Her experience includes working with various entities including the public and private sectors. Her vast knowledge includes geotechnical, environmental and materials services. This experience has been attained through small and large projects over the numerous years of her career.

Employment History

GeoTek, Inc., Riverside-Project Geologist, February 2005 – Present

GeoSoils, Inc., Santa Ana, September 1987 – February 2005

Edward H. LaMont, CEG, PG

Branch Manager

Areas of Expertise

Geotechnical Field Investigations
Grading and Earthwork Construction
Industry Standard of Care
Hillside, Liquefaction, Seismic Hazard, Fault Analyses and Forensic Studies.

Education

Bachelor of Science in Geology, Cal State University, Northridge

Registrations

Registered Geologist, PG 6025
Certified Engineering Geologist, CEG 1892

Certifications

OSHA 40-Hr HAZWOPER Training
OSHA 8-Hour Refresher
First Aid/CPR

Professional Affiliations

Association of Engineering Geologist
South Coast Geological Society
San Diego Association of Geologist
Inland Geological Society
BIA Riverside
BIA San Diego

Professional Experience

Mr. LaMont has been involved with numerous public works, residential and commercial earthwork projects across the southern California area. Many residential, commercial and public works projects have been successfully completed across southern and central California. Projects include liquefaction and subsidence studies, fault evaluations, commercial, residential, federal, FEMA levee certifications and military construction projects. These projects have generally included preliminary geotechnical evaluations, slope stability studies, review and design recommendations, street improvements construction and testing services, and project management.

In addition, Mr. LaMont has performed governmental review of geotechnical reports for the County of Orange. Mr. LaMont has also completed geotechnical studies for the Riverside County Flood Control and Cities of Banning, Chino, Corona, Palm Springs, Lancaster and Victorville, to name a few.

Representative Project Experience

Project experience has included residential and commercial developments, for various land developers including Melia Homes, Meritage Homes, Frontier Enterprises, D·R·Horton, Beazer Homes, KB Home, Integral Communities, IntraCorp, Shopoff, Shea Homes, etc. Mr. LaMont has also completed geotechnical investigations and performed project management for numerous residential tracts and commercial facilities all across Southern California.

Professional History

Branch Manager/Principal Geologist - Riverside GeoTek, Inc., 2004 to present

Vice President, Principal Geologist - GeoSoils, Inc., Santa Ana, 2003 to 2004

Geotechnical Reviewer, Engineering Geologist - County of Orange, 2001 to 2003.

Project Geologist - GeoSoils, Inc., Santa Ana, California, 1994 to 2001.

Staff/Project Geologist - GeoSoils, Inc., Carlsbad, California, 1988 to 1994.

J. MICHAEL BATTEN, CAC, CEM, REPA

Principal/Environmental Services Manager

Education

BS in Geology, California State University, Fresno 1988

Registrations

- Certified Asbestos Consultant (CA #95-1721)
- Licensed Asbestos Abatement Consultant (NV #IJPM0655)
- Certified Environmental Manager (NV #1782)
- Asbestos Professional Inspector (IL #100-11092)
- Registered Environmental Property Assessor (#113162))
- Certified Lead Inspector Assessor (CA #4358)
- Certified Lead Inspector (EPA #LBP-I-1162326-1)
- Certified Lead Risk Assessor (EPA #LBP-R-1162326-1)

Certifications

- AHERA Certified Asbestos Building Inspector, Management Planner, Project Designer, & Contractor/Supervisor
- EPA Accredited Lead-based Paint Inspector & Risk Assessor
- OSHA HAZWOPER certified worker & supervisor
- OSHA Construction Safety & Health (10-Hour)

Affiliations

- American Society of Testing and Materials
- National Registry of Environmental Professionals

Professional Experience

Mr. Batten has over 30 years of environmental experience, throughout which he has conducted and managed numerous environmental investigations, assessments, and remediations. He has prepared several NEPA assessments, USEPA EIS, and CEQA EIR reports. In addition, Mr. Batten has extensive experience in conducting asbestos and lead-based paint surveys and preparing management plans, including remediation design, for asbestos and lead present in buildings.

Project Experience

- **Phase I Environmental Site Assessments:** Mr. Batten has conducted more than 2,000 Phase I Environmental Site Assessments in 27 states, including Brownfield studies under USEPA grants.
- **Phase II Environmental Site Assessments:** Mr. Batten has conducted more than 150 Phase II Environmental Assessments, including Brownfield studies under USEPA grants.
- **Site Characterizations and Remediations:** Mr. Batten has experience conducting numerous site characterizations and remediations, including obtaining regulatory closure.
- **NEPA Studies:** Mr. Batten has conducted more than 200 NEPA studies, including Environmental Assessments, Environmental Impact Reports/Environmental Impact Studies, in eight states. The agencies involved include USEPA, FCC, BLM, National Park Service, and California EPA.
- **Asbestos Services:** Mr. Batten has conducted over 600 asbestos surveys in several states. He has also prepared numerous Asbestos Management Plans, prepared design plans, and monitored numerous abatement projects.
- **Lead-Based Paint Services:** Mr. Batten has conducted numerous Lead-Based Paint surveys.
- **Landfills**: Mr. Batten has conducted investigations and overseen remediations on landfills in Fresno, California and Henderson, Nevada.
- **Other Services:** Mr. Batten has been called upon to conduct less usual services on occasion, including mold consultation and investigation, radon studies, vapor intrusion studies, and indoor air quality studies.

J. MICHAEL BATTEN, continued…

Professional History

Environmental Services Manager. GeoTek, Inc., 2001 to present.

Director of Environmental Services. ATC Associates, Inc., 1999 to 2001.

Director of Operations. Hygienetics Environmental Services, Inc., 1997 to 1999.

Project Manager. AllWest Environmental, Inc., 1996 to 1997.

Project Manager. Citadel Environmental Services, Inc., 2/1996 to 9/1996.

Project Manager. Boelter Environmental consultants, 3/1995 to 9/1995.

Senior Staff Geologist. Converse Consultants, 1992 to 1995.

Staff Geologist. Converse Environmental West, 1991 to 1992.

Project Geologist. Krazan and Associates, 1990 to 1991.

Environmental Technician. Krazan and Associates, 1989 to 1990.

National Registry of Environmental Professionals

For

Environmental Certifications

This is to Certify that

Michael J Batten

having sucessfully demonstrated to the Academic Board of this organization the required level of knowledge and ability, is here by awarded the distinction of

Registered Environmental Property Assessor

together with all rights, benefits and privileges attached thereto and that the name and title of the aforementioned registrant is today placed upon the register of the organization.

Given under our hands on this 15 day of June, 2013.

Richard A Young

Executive Director

NREP

113162

Registrant Number

This Certificate is the property of the National Registry of Environmental Professionals and must, upon demand, be returned.

United States Environmental Protection Agency

This is to certify that



J M Batten

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as:

Inspector

In the Jurisdiction of:

All EPA Administered Lead-based Paint Activities Program States, Tribes and Territories

This certification is valid from the date of issuance and expires March 14, 2022

LBP-I-I162326-2

Certification #

December 08, 2018

Issued On

Adrienne Priselac, Manager, Toxics Office

Land Division

United States Environmental Protection Agency

This is to certify that



J M Batten

has fulfilled the requirements of the Toxic Substances Control Act (TSCA) Section 402, and has received certification to conduct lead-based paint activities pursuant to 40 CFR Part 745.226 as:

Risk Assessor

In the Jurisdiction of:

All EPA Administered Lead-based Paint Activities Program States, Tribes and Territories

This certification is valid from the date of issuance and expires March 14, 2022

LBP-R-I162326-2
Certification #

December 08, 2018
Issued On

Adrienne Priselac, Manager, Toxics Office
Land Division

STATE OF CALIFORNIA Gavin Newsom, Governor

DEPARTMENT OF INDUSTRIAL RELATIONS
Division of Occupational Safety and Health
Asbestos Certification & Training Unit
1750 Howe Avenue, Suite 460
Sacramento, CA 95825
(916) 574-2993 Office http://www.dir.ca.gov/dosh/asbestos.html acru@dir.ca.gov

505011721C **109** **115**

August 23, 2021

J. Michael Batten
8240 Edmond Street
Las Vegas NV 89139

Dear Certified Asbestos Consultant or Technician:

Enclosed is your certification card. **To maintain your certification, you must abide by the rules printed on the back of the certification card.**

Your certification is valid for a period of one year. If you wish to renew your certification, you must apply for renewal at least 60 days before the expiration date shown on your card. [8 CCR 341.15(h)(1)].

Please hold and do not send copies of your required AHERA refresher renewal certificates to our office until you apply for renewal of your certification.

Certificates must be kept current if you are actively working as a CAC or CSST. The grace period is only for those who are not actively working as an asbestos consultant or site surveillance technician.

Please notify our office via U.S. Postal Service or other carrier of any changes in your mailing or work address within 15 days of the change.

Sincerely,

Jeff Ferrell
Senior Safety Engineer

Attachment: Certification Card

cc: File

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant



Name **J. Michael Batten**
Certification No. **95-1721**
Expires on **10/27/22**
This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.

Renewal – Card Attached (Revised 06/2020)

STATE OF CALIFORNIA
DEPARTMENT OF PUBLIC HEALTH

LEAD-RELATED CONSTRUCTION CERTIFICATE

INDIVIDUAL:	CERTIFICATE TYPE:	NUMBER:	EXPIRATION DATE:
 **Michael Batten**	Lead Inspector/Assessor	LRC-00002629	11/17/2021

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD.

IDPH
ILLINOIS DEPARTMENT OF PUBLIC HEALTH

525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

MICHAEL BATTEN
8240 EDMOND STREET
LAS VEGAS, NV 89139

4/22/2021

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11092

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

IDPH
ILLINOIS DEPARTMENT OF PUBLIC HEALTH

ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 11092	**4/22/2021**	05/15/2022

MICHAEL BATTEN
8240 EDMOND STREET
LAS VEGAS, NV 89139
Environmental Health



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	4/19/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois Department of Public Health
This license is valid only when accompanied by a valid training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

State of Nevada

Department of Conservation and Natural Resources

Division of Environmental Protection

This is to certify that

MICHAEL BATTEN

having given satisfactory evidence of the necessary qualifications as required by the Nevada Revised Statute 459.400 to 459.600, inclusive, and Nevada Administrative Code 459.970 to 459.9729, inclusive, has been granted certification as a

Certified Environmental Manager

in the State of Nevada

In testimoney whereof, witness the signature of the Administrator and the Seal of the State of Nevada.

EM1782

Certification Number

08/31/2023

Expiration Date

Greg Lovato, Administrator

State of Nevada Department of Business & Industry

Industrial Relations (DIR)

STATE OF NEVADA
DEPARTMENT OF BUSINESS AND INDUSTRY
DIVISION OF INDUSTRIAL RELATIONS
Occupational Safety and Health Administration
Asbestos Control Program

Certifies That J. Michael Batten
Geotek Insite Inc.
is Licensed As Asbestos Abatement Consultant

License No. IJPM-655 Expiration Date 09/09/2021

Signature Of Licensee

M & C Environmental Training

Asbestos Inspector
Refresher Training Course

Michael Batten

Has successfully completed the Asbestos Inspector Refresher course approved by the California Division of Occupational Safety and Health for purposes of certification required by Title 8, Article 2.7, Chapter 3.2, Section 341.16 and the accreditation required under the Toxic Substances Control Act, Title II. Conducted by M&C Environmental Training Inc., P.O. Box 6419, Concord, California Tel. # (510 499-5646

Course Approval Number: CA-003-06

Location:	Concord, California	Expiration: March 4, 2022
Dates:	March 4, 2021	
Director of Training: John McGinnis		

Certificate Number 48873 IR

M & C Environmental Training

Asbestos Management Planner
Refresher Training Course

Michael Batten

Has successfully completed the Asbestos Management Planner Refresher course approved by the California Division of Occupational Safety and Health for purposes of certification required by Title 8, Article 2.7, Chapter 3.2, Section 341.16 and the accreditation required under the Toxic Substances Control Act, Title II. Conducted by M&C Environmental Training Inc., P.O. Box 6419, Concord, California. Tel. # (510) 499 - 5646

Course Approval Number: CA-003-08

Location:	Concord, California	Expiration: March 4, 2022
Dates:	March 4, 2021	
Director of Training: John McGinnis		

Certificate Number 48888 PR

M & C Environmental Training

Asbestos Contractor/Supervisor
Refresher Training Course

Michael Batten

Has successfully completed the Asbestos Contractor/Supervisor Refresher course approved by the California Division of Occupational Safety and Health for purposes of certification required by Title 8, Article 2.7, Chapter 3.2, Section 341.16 and the accreditation required under the Toxic Substances Control Act, Title II. Conducted by M&C Environmental Training Inc., P.O. Box 6419, Concord, California Tel. # (510) 499 - 5646

Course Approval Number: CA-003-04

Location:	**Concord, California**	**Expiration: Sept. 17, 2022**
Dates:	**Sept. 17, 2021**	
Director of Training: John McGinnis		

Certificate Number **49647 SR**

M & C Environmental Training

Asbestos Project Designer
Refresher Training Course

Michael Batten

Has successfully completed the Asbestos Project Designer Refresher course approved by the California Division of Occupational Safety and Health for purposes of certification required by Title 8, Article 2.7, Chapter 3.2, Section 341.16 and the accreditation required under the Toxic Substances Control Act, Title II. Conducted by M&C Environmental Training Inc., P.O. Box 6419, Concord, California. Tel. # (510) 499 - 5646

Course Approval Number: CA-003-10

Location:	**Concord, California**	**Expiration: Sept. 15, 2022**
Dates:	**Sept. 15, 2021**	
Director of Training: John McGinnis		

Certificate Number **49598 DR**

2020

OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 | (630) 655-3900 | www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Batten

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 8/10/2020

Exam Date: 8/10/2020

Expiration Date: 8/10/2021

Certificate Number: BIR2008101810

Kathy DeSalvo

Kathy DeSalvo, Director

OSHA 002340551

U.S. Department of Labor
Occupational Safety and Health Administration

Michael Batten

has successfully completed a 10-hour Occupational Safety and Health Training Course in

Construction Safety & Health

Kenner Costen (Trainer)

12/12/09 (Date)