Planning Division
CITY OF MOUNTAIN VIEW
Received on
Aug 9, 2021

PHASE I

ENVIRONMENTAL SITE ASSESSMENT

918 RICH AVENUE
SAN JOSE, CALIFORNIA

EIS, Inc. PROJECT #2103-1

February 16, 2020

PREPARED FOR:

Mr. Greg Xiong
Ardenview Homes, LLC
Los Altos, California, 94022

PREPARED BY:

ENVIRONMENTAL INVESTIGATION SERVICES, INC.
316 MID VALLEY CENTER #313
CARMEL, CA 93923 PH: 408.656.1032

Table of Contents

EXECUTIVE SUMMARY 4

1.0 INTRODUCTION 5

1.1 Purpose 5
1.2 Detailed Scope of Services 6
1.3 Limitations 6
1.4 Data Gaps 7
1.5 User Reliance 7

2.0 SITE RECONNAISANCE 7

2.1 Current Use of Subject Property 7
2.1.1 Hazardous Substances and Petroleum Products 8
2.1.2 Underground Storage Tanks (USTs) 8
2.1.3 Aboveground Storage Tanks (ASTs) 8
2.1.4 Liquid Waste 8
2.1.5 Solid Waste 8
2.1.6 Polychlorinated Biphenyls (PCBs) 8
2.1.7 Wells 8
2.2 Current Use of Adjoining Properties 8

3.0 USER PROVIDED INFORMATION 9

3.1 TItle Records 9
3.2 Environmental Liens or Activity & Use Limitations 9
3.3 Specialized Knowledge 9
3.4 Commonly Known or Reasonably Ascertainable Information 9
3.5 Valuation Reductions For Environmental Issues 10
3.6 Reasons for Performing Phase I 10

4.0 INTERVIEWS 10

4.1 Subject Property Owner/Key Site Manager 10
4.2 Tenant-Space Key Site Managers 10
4.3 Previous Owners, Operators, and Occupants 10
4.4 Nearby Property Owners and Occupants 10
4.5 Government Officials 10

5.0 RECORDS REVIEW 10

5.1 Physical Setting 10
5.1.1 Physiography 10
5.1.2 Geology 11
5.1.3 Hydrogeology 11
5.2 Sanborn Fire Insurance Maps 11
5.3 Aerial Photographs 11
5.4 Topographic Maps 13
5.5 City Directories 13
5.6 Regulatory Agencies 15
5.6.1 Tax Assessor 15
5.6.2 Building Department 16
5.6.3 Fire Department 16
5.6.4 Department of Environmental Health 16
5.6.5 State Water Resources Control Board 16

5.6.6 Department of Toxic Substances Control 17
5.7 PREVIOUS REPORTS 17
5.8 DATABASE REVIEW 17
6.0 NON-ASTM CONSIDERATIONS 20
6.1 ASBESTOS 20
6.2 LEAD-BASED PAINT 20
6.3 MOLD 20
6.4 RADON 20
6.5 WETLANDS 20
7.0 FINDINGS AND OPINIONS 21
8.0 CONCLUSION & RECOMMENDATIONS 22
9.0 SIGNATURE(S) OF ENVIRONMENTAL PROFESSIONAL(S) 23

Figures

1 Site Location Map
2 Site Detail Map

Photographs

Appendices

A Qualifications
B Sources Checked
D Fire Insurance Maps
E Aerial Photographs
F Database Report
G City Directories

EXECUTIVE SUMMARY

Environmental Investigation Services Inc. (EIS) has completed a Phase I Environmental Site Assessment (ESA) for the property addressed as 918 Rich Avenue, Mountain View, California with APN #189-33-028 (subject property).

This ESA was prepared in accordance with EIS's Proposal No. 2103-1 and ASTM Designation: E 1527-13 *Standard Practice for Environmental Site Assessments: Phase I ESA Process.* The work is limited to the services agreed to by Mr. Greg Xiong. The objective of this assessment was to evaluate the subject property for potential recognized environmental concerns, as outlined in the above-referenced standard. EIS's professional services have been performed using that degree of care and skill ordinarily exercised, under similar circumstances, by reputable environmental consultants practicing in the location of the subject property at the time of our investigation. This warranty is in lieu of all other warranties, expressed or implied. Exceptions to E 1527-13 and limitations encountered during this ESA are identified in the report.

The approximately 0.72-acre (31,456-square feet) subject property is undeveloped in preparation of multifamily residential redevelopment. The entirety of the subject property is covered with wood mulch and several moderately sized trees exist along the perimeter the parcel. The parcel is surrounded by an approximately 8-foot-tall wood fence on all sides, except for the Rich Avenue entrance, which has a chain link fence. The subject property is accesses via a gate off the Rich Avenue frontage. An inground electrical utility vault and a fire hydrant were identified between the subject property gate and Rich Avenue.

EIS identified obvious subject property uses from the present back to 1939, at which time the subject property appeared to be undeveloped pastureland. By 1948 a small structure was visible on the eastern portion of the subject property and was visible in aerial photographs until 2006. The subject property has remained undeveloped since 2006. A 2018 aerial photograph obtained from Google Earth shows (Figure 2) shows the subject property in use as an apparent storage yard with numerous containers along the perimeter and large soil stockpiles visible in the northwestern portion of the property.

Surrounding properties appeared to be in similar use as the subject property in 1939 with all adjoining properties undeveloped pastures, except for a large warehouse structure occupying the northwestern adjoining property, and orchards beyond in all directions. By 1948, a residence was visible on the southern adjoining property and a rectangular warehouse was visible on the northeastern adjoining property. By 1956, the western and southwestern adjoining properties were developed with structures roughly matching the current. The northeastern residential complex was developed by 1963, and the large warehouse on the northwestern adjoining property appeared to be in use as a lumber yard by 1963. The northwestern adjoining lumber yard was redeveloped to match the current by 1998. Notable occupants of the adjoining properties include a Chevron gas station (northwestern adjoining property, 1969-1972), and Blue Bird Dry Cleaners (northwestern adjoining property, 1996 to present).

EIS has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13. This assessment has revealed no evidence of recognized environmental conditions (RECs), historical recognized environmental conditions (HRECs), or controlled recognized environmental conditions (CRECs), or potential vapor intrusion concerns (PVICs) in connection with the subject property, except for the following:

- The presence of soil stockpiles in the northwestern portion of the subject property between June 2017 and July 2019 without any documentation as to the origin or use of the stockpiles represents a potential environmental concern.

- The various commercial uses of the northwestern adjoining properties, including dry cleaning and gas station, represent a potential vapor encroachment concern (PVEC).

Prior to redevelopment of subject property for residential uses, EIS recommends a Phase 2 subsurface investigation to address the potential environmental concern and vapor encroachment concern.

1.0 INTRODUCTION

Environmental Investigation Services Inc. (EIS) has completed a Phase I Environmental Site Assessment of a property addressed as Environmental Investigation Services Inc. (EIS) has completed a Phase I Environmental Site Assessment (ESA) for the property addressed as 918 Rich Avenue, Mountain View, California with APN #189-33-028 (subject property). Peter Littman, Environmental Professional, prepared this report according to ASTM Standard E 1527-13. Any deviations from the ASTM Standard are cited in the report. Mr. Littman's qualifications as an Environmental Professional are presented in Appendix A. EIS understands that this ESA is being conducted as part of a real estate transaction.

1.1 PURPOSE

The purpose of this Phase I Environmental Site Assessment was to identify, to the extent feasible pursuant to the processes prescribed herein, recognized environmental conditions in connection with the subject property. The term recognized environmental conditions refers to the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property. The term is not intended to include *de minimis* conditions that generally do not present a threat to human health or the environment and that generally would not be subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be *de minimis* are not recognized environmental conditions.

1.2 DETAILED SCOPE OF SERVICES

This Phase I Environmental Assessment (ESA) was prepared in accordance with EIS's Proposal No. 2103-1 with respect to the property addressed as Environmental Investigation Services Inc. (EIS) has completed a Phase I Environmental Site Assessment (ESA) for the property addressed as 918 Rich Avenue, Mountain View, California with APN #189-33-028. This investigation was conducted in general accordance with ASTM E 1527-13. The work conducted by EIS is limited to the services agreed to by Mr. Greg Xiong and no other services beyond those explicitly stated should be inferred or are implied. The objective of this assessment was to evaluate the subject property for potential recognized environmental concerns, as outlined in the above-referenced standard. EIS's professional services have been performed using that degree of care and skill ordinarily exercised, under similar circumstances, by reputable environmental consultants practicing in the location of the subject property at the time of our investigation. This warranty is in lieu of all other warranties, expressed or implied. This ESA includes the following parts: reconnaissance, interviews, records review, and evaluation. In addition, this ESA addresses the following non-ASTM considerations: asbestos, lead-based paint, mold, radon, and wetlands.

1.3 LIMITATIONS

Our professional judgment regarding the potential for environmental impacts is based on limited data and our investigation was not intended to be a definitive investigation of contamination at the subject property. Unless specifically set forth in our proposal, the scope of work did not include sampling of soil or groundwater, or a compliance audit pertaining to hazardous material use and storage, hazardous waste storage, or personnel health and safety training. In addition, this assessment did not include analyses of indoor air quality, asbestos, lead-based paint, formaldehyde, radon, or other hazardous materials.

Regarding any reviewed subsurface investigations and sampling and analysis data, our opinions are limited to specific areas and analytes evaluated. EIS will not be held accountable for detected analytes occurring at concentrations below laboratory detection limits. EIS does not warrant or guarantee that the subject property is suitable for any particular purpose or certify the subject property as "clean" or free from contamination. As with any assessment, it is possible that past or existing contamination remains undiscovered.

The professional opinions set forth in this report are based solely upon and limited to EIS's visual observations of the subject property and immediate vicinity, and upon EIS's interpretations of the readily available historical information, interviews with personnel knowledgeable about the subject property, and other readily available information (Appendix B). Consequently, this report is complete and accurate only to the extent that cited reports, agency information and recollections of persons interviewed are complete and accurate.

The opinions and recommendations in this report apply to observed conditions and features of the subject property, as they existed at the time of EIS's investigation. They

cannot necessarily apply to conditions and features of which EIS is unaware and has not had the opportunity to evaluate. Future regulatory modifications, agency interpretations, and/or policy changes may also affect the compliance status of the subject property. EIS has made no attempt to address future financial impacts to the site (e.g., reduced property values) as a result of potential on-site subsurface contamination.

1.4 DATA GAPS

EIS encountered no significant data gaps or limitations, except for the following:

- EIS identified obvious subject property uses from the present back to 1939, at which time the subject property appeared to be in agricultural use. This represents data failure since the timeline does not extend back to the earlier of first developed use or 1940. Based on EIS's experience, information about prior subject property uses is not reasonably ascertainable or likely to be useful. This data failure is therefore not a significant data gap.

1.5 USER RELIANCE

This Phase I Environmental Site Assessment was prepared for the sole and exclusive use of Mr. Greg Xiong. This report is intended exclusively for the purpose outlined herein for the subject property and is intended to be used in its entirety. No excerpts may be taken to be representative of the findings of this assessment. The scope of services performed in execution of this investigation may not be appropriate to satisfy other users, and any use or reuse of this document or its findings, or conclusions presented herein is at the sole risk of the user. This report is not a specification for further work.

2.0 SITE RECONNAISANCE

On February 4, 2021, Joseph Adams of EIS performed a visual reconnaissance of the subject property, adjoining properties, and surrounding areas to ascertain current and historical uses. Mr. Adams unaccompanied during his reconnaissance. The subject property was systematically traversed on foot; adjoining properties were observed from the subject property and from public thoroughfares. Photographs are appended. Figure 2 depicts the site plan.

2.1 CURRENT USE OF SUBJECT PROPERTY

The approximately 0.72-acre (31,456-square feet) subject property is undeveloped in preparation of multifamily residential redevelopment. The entirety of the subject property is covered with wood mulch and several moderately sized trees exist along the perimeter the parcel. The parcel is surrounded by an approximately 8-foot-tall wood fence on all sides, except for the Rich Avenue entrance, which has a chain link fence. The subject property is accesses via a gate off the Rich Avenue frontage. An inground electrical utility vault and a fire hydrant were identified between the subject property gate and Rich Avenue.

2.1.1 HAZARDOUS SUBSTANCES AND PETROLEUM PRODUCTS

EIS inspected the subject property for indications of the use, storage, or disposal of hazardous substances and petroleum products (e.g., manufacturing activities, drums, containers, stressed vegetation, stains, sheen, and heating/cooling systems). EIS observed no such indications.

2.1.2 UNDERGROUND STORAGE TANKS (USTS)

EIS inspected the subject property for indications of USTs (e.g., vent piping, dispensing equipment, pavement variations, and fill ports). EIS observed no such indications.

2.1.3 ABOVEGROUND STORAGE TANKS (ASTS)

EIS inspected the subject property for indications of ASTs (e.g., pavement bolts, containers, reservoirs, and generators). EIS observed no such indications.

2.1.4 LIQUID WASTE

EIS inspected the subject property for indications of liquid waste discharge sources (e.g., sumps, drains, clarifiers, pools of liquid, pits, ponds, lagoons, septic systems, wastewater, and storm water). EIS observed no such indications.

2.1.5 SOLID WASTE

EIS inspected the subject property for indications of solid waste disposal (e.g., mounding, depressions, fill material, bins, debris, and active human use). EIS observed no such indications, except for the following:

- Small, scattered plastic and glass litter were observed throughout the subject property.
- One large, rusted steel utility pole was identified in the western portion of the property.

2.1.6 POLYCHLORINATED BIPHENYLS (PCBS)

EIS inspected the subject property for indications of PCBs (e.g., transformers, capacitors, elevators, and lifts). EIS observed no such indications.

2.1.7 WELLS

EIS inspected the subject property for indications of supply, irrigation, monitor, injection, dry, abandoned, or other wells (e.g., protruding pipes, cover plates, pumps, small sheds, large water storage containers, and mounded grout). EIS observed no such indications.

2.2 CURRENT USE OF ADJOINING PROPERTIES

The adjoining and nearby properties generally consist of residential properties. The uses and features of the adjoining properties are described below.

- Northwestern Adjoining: Shopping Center (1039-1049 El Monte Ave.,)

- Northeastern Adjoining: Rich Avenue Apartments (912 Rich Avenue)
- Eastern Adjoining: Parkrich Avenue Apartments (959 Rich Avenue)
- Southwestern Adjoining: Lutheran Church, (1075 El Monte Ave.)
- Western Adjoining: Family Counselor Commercial (1059 El Monte Ave)
- Southern Adjoining: Residential Complex (920,932, 934 Rich Avenue)

3.0 USER PROVIDED INFORMATION

ASTM E1527-13 defines “User” as the party seeking to use Practice E1527 to complete an environmental site assessment of the subject property. EIS understands that Mr. Greg Xiong is the User as defined by ASTM E1527-13. ASTM E1527-13 specifies that certain tasks associated with identifying potential recognized environmental conditions at the subject property should be performed by the user and provided to the Environmental Professional (i.e., User Responsibilities). Mr. Xiong was provided with an Environmental Questionnaire and Disclosure Statement.

Based on EIS’s review of the User-provided information, no readily apparent evidence of potential recognized environmental conditions at the subject property was noted. Information obtained from the Owner Questionnaire is provided below.

3.1 TITLE RECORDS

EIS reviewed a Preliminary Title Report for the subject property completed by Lawyers Title Company and dated June 11, 2020. The subject property is identified by APN 189-33-028 and addressed as 918 Rich Avenue, Mountain View, CA. The current owner is listed as “Ardenview Homes, LLC, a California Limited Liability Company.”

3.2 ENVIRONMENTAL LIENS OR ACTIVITY & USE LIMITATIONS

There are no known environmental liens or activity and use limitations (AULs) associated with the subject property that the User is aware of.

3.3 SPECIALIZED KNOWLEDGE

The User provided no specialized, non-duplicative information pertaining to the subject property.

3.4 COMMONLY KNOWN OR REASONABLY ASCERTAINABLE INFORMATION

The User provided no relevant, non-duplicative information pertaining to the subject property.

3.5 VALUATION REDUCTIONS FOR ENVIRONMENTAL ISSUES

The User stated no valuation reduction for environmental issues.

3.6 REASONS FOR PERFORMING PHASE I

The Phase I is being performed as redevelopment project.

4.0 INTERVIEWS

4.1 SUBJECT PROPERTY OWNER/KEY SITE MANAGER

The subject property is an undeveloped lot with no structures or utilities. As such, EIS did not interview any site managers.

4.2 TENANT-SPACE KEY SITE MANAGERS

EIS did not interview any tenant-space key site managers.

4.3 PREVIOUS OWNERS, OPERATORS, AND OCCUPANTS

EIS identified no previous subject property owners, operators, and occupants.

4.4 NEARBY PROPERTY OWNERS AND OCCUPANTS

The subject property is not abandoned. Therefore, EIS did not interview nearby property owners and occupants.

4.5 GOVERNMENT OFFICIALS

EIS submitted a file review request to the Santa Clara County Consumer and Environmental Protection Agency (CEPA) on February 8, 2021. CEPA Staff responded on February 8, 2021 and notified EIS that their agency possessed no pesticide or herbicide records pertaining to the subject property.

5.0 RECORDS REVIEW

EIS reviewed records pertaining to the subject property. In addition, where practicable and relevant, EIS reviewed records indicating uses at adjoining properties and nearby properties or surrounding areas within approximate minimum search distances from the subject property.

5.1 PHYSICAL SETTING

5.1.1 PHYSIOGRAPHY

EIS reviewed the United States Geological Survey's (USGS) 2012 7.5-Minute Series Mountain View, California, Quadrangle Topographic Map. The ground surface elevation

at the subject property is approximately 100 feet above mean sea level (msl). The subject property is relatively flat. The closest surface water bodies are Permanente Creek located approximately 450-feet to the northeast of the subject property.

5.1.2 GEOLOGY

The subject property area is underlain by Quaternary-age, marine and nonmarine alluvium (CGS, 2010). Soils encountered during a subsurface investigation at a nearby site (1313 W. El Camino Real, Mountain View) approximately 900-feet east of the subject property consisted primarily of interbedded sandy gravel and sandy clay to an explored depth of 55-feet below ground surface (bgs) (EIS, 2020).

5.1.3 HYDROGEOLOGY

Estimated depth to groundwater at a nearby Site (1737 El Camino Real) located approximately 350-feet north of the subject property ranged from approximately 43 to 51-feet bgs, with an estimated easterly flow direction (RWQCB, 1994). The local groundwater flow direction and gradient under the subject property may be influenced naturally by zones of higher or lower permeability, or artificially by nearby groundwater pumping or recharge, and may deviate from the regional trend.

5.2 SANBORN FIRE INSURANCE MAPS

EIS requested Sanborn Fire Insurance Maps for the subject property, adjoining properties, and surrounding area from the Environmental Data Resources, Inc. (EDR) collection. According to EDR, such maps were not available (Appendix D).

5.3 AERIAL PHOTOGRAPHS

EIS reviewed aerial photographs for the years of 1939, 1948, 1950, 1956, 1963, 1968, 1974, 1982, 1991, 1998, 2006, 2009, 2012, and 2016 obtained from the EDR collection. The photographs are included in the appendices. Photograph descriptions for the subject property and adjoining properties follow.

Date	Aerial Photographs – Subject and Adjoining Properties
1939	The subject property and all adjoining properties appear to be undeveloped pasture. Orchards are visible nearby the subject property to the south and west. A large warehouse structure is visible on the northwestern adjoining property at the intersection of El Monte Avenue and W. El Camino Real. El Monte Avenue appears to be an unpaved road. Some residential and commercial structures are visible nearby north of El Camino Real. Permanente Creek is visible nearby to the east.
1948	The subject property now appears to be developed with a small structure with a dirt driveway off the Rich Avenue Frontage. Rich Avenue appears to be a dirt road. The southern adjoining property appears to be developed with a similar residential sized structure. El

	Monte Avenue appears to be paved and residential and commercial development has continued south of El Camino Real. Orchards are still prevalent in the surrounding area and a small stand of trees is visible on the southern adjoining property. A rectangular warehouse is visible on the northeastern adjoining property.
1950	The subject property and all adjoining properties appear generally unchanged from the 1948 photograph. In general, residential development is replacing orchards extensively north of El Camino Real and to the south and west of the subject property.
1956	The subject property appears unchanged from the 1950 photograph. The western adjoining commercial property appears to match the current. Additional warehouse sized structures are visible on the northeastern adjoining property. A rectangular warehouse structure is now visible on the southwestern adjoining property. In general, residential development has replaced the orchards in the surrounding area and only small relic orchards are visible.
1963	The subject property appears generally unchanged from the 1956 photograph. The northeastern and eastern adjoining properties appear to have been redeveloped to match the current residential complexes. A residence is now visible south of the subject property. Rich Avenue now appears to be paved and the surrounding road network roughly matches the current. An additional rectangular building is visible on the southwestern adjoining property. The northwestern adjoining property appears to be in use as a lumber yard with numerous rows of stacked lumber visible.
1968-1982	The subject property and all nearby and adjoining properties appear unchanged from the 1963 photograph.
1991	The subject property and all nearby and adjoining properties appear unchanged from the 1982 photograph, except the northwestern adjoining lumberyard appears to be in the process of being redeveloped.
1998-2016	The subject property and all nearby and adjoining properties appear generally unchanged from the 1991 photograph, except by 1998 the northwestern adjoining and southern adjoining properties have been redeveloped to match the current, and by 2006 the small structure on the subject property is no longer visible.
2018	Google Earth Aerial image from 2018, used as the base map for Figures 1 and 2, shows the subject property in use as a storage yard

	with numerous containers and trailers around the perimeter and large soil stockpiles in the northwestern portion of the subject property.

5.4 TOPOGRAPHIC MAPS

EIS reviewed topographic maps for the years of 1897, 1899, 1902, 1943, 1947,1953, 1961, 1968, 1973, 1980, 1995, 1997, and 2012 obtained from the EDR collection. Map descriptions follow.

Date	Topographic Maps – Subject Property and Adjoining Properties
1897-1902	The subject property and all adjoining properties appear as undeveloped vacant land or as residential.
1943-1947	The subject property and adjoining properties to the northeast, east, east, south, and west appear as undeveloped or residential uses. There appears to be a larger building on the northwest adjoining property.
1948	The subject property and adjoining properties to the northeast, east, east, south, and west appear as undeveloped or residential uses. There appears to be a larger building on the northwest adjoining property. The nearby surrounding area to the south, southwest, northwest, and west appear to be mixed use residences and orchards.
1953	The subject property and all nearby and adjoining properties appear generally unchanged from the 1948 map, except that the only orchards remaining are on the southern adjoining and nearby northwestern properties. The rest of surrounding area appears as residences.
1961-1997	The subject property and all nearby and adjoining properties appear generally unchanged from the 1953 map, except that all the surrounding properties appear residentially developed and one church adjacent to the southwest.
2012	No structures are depicted on this map, only the current road network is shown.

5.5 CITY DIRECTORIES

EIS reviewed an EDR City Directories report. The City Directories report is included in the appendices. Reviewed directories generally covered the years 1922 through 2017. Complete directory listings for the subject property and notable listings for adjoining and nearby properties are presented in the below tables.

Date	918 Rich Avenue (Subject Property)
1975-1996	No Listing for this address
1999-2014	Residential Listings

Date	912 Rich Avenue (Northeastern Adjoining)
1968-2017	Numerous residential listings
1962	Paul E. Stafford (Maureen A) Draftsman Lockheed

Date	959 Rich Avenue (Eastern Adjoining)
1968	Numerous residential listings
1975	Numerous residential listings, Kaiser Cement & Gypsum Corp.
1982-2017	Numerous residential listings

Date	920 Rich Ave. (Southern Adjoining)
1962-2017	Numerous Residential Listings

Date	932, 934 Rich Ave. (Southern Adjoining)
1962-1999	No Listing for this address
2001, 2004	Residential Listings
2006-2017	No Listing for this address

Date	1059 El Monte Ave. (Western Adjoining)
1957	Mcghie & Jones RPT S; Jensen Waiter MDO
1962	Bonar Barnett Phys; Meridith Richd Phys
1968	Bonar Barnett Phys; Logan Irving Dentist
1975	Bonar Barnett, MD; Mountain View Office, El Monte Lab
1982	Bonar Barnett, MD; Mountain View Office, El Monte Lab; Verant Dental lab; John Milburn MD
1986	Bonar Barnett, MD; Mountain View Office, El Monte Lab; Verant Dental lab; John Milburn MD; Silhoutte Dental Studio
1991	Verant Dental lab; Institute for interpersonal relations

2001	Monique Kane FCC; Sharon Pereira; Verant Dental Lab, Judith DQue, LMFT
2004-2009	Counselors and Dentists
2014-2017	Counselors

Date	1049 El Monte Ave. (northwestern Adjoining)
1975-1991	No listing for this address.
1999-2001	Bluebird Cleaners; Cellular One; Noah's Bagels; Occupant Unknown, Debra Langley
2004	Cellular One, Fitness Studio; Noah's Bagels; Occupant Unknown
2009	Bagel Street Café; Debrah Langley; Enki; Bluebird Cleaners & Laundry; Nest Bedding;
2014	Bagel Street Café; Patricia Takata; Enki; Bluebird Cleaners; Nest Bedding;
2017	Bagel Street Café; Luis Bail Bonds; Enki; Bluebird Cleaners; Jeannie Choi; Nest Bedding; Mares Garage Doors & Gates

Date	1075 El Monte Ave. (Southwestern Adjoining)
1957-1968	St Paul Lutheran Church,
1975-1991	St Paul Lutheran Church, Child Dev., Nursery School
1994	St Paul Lutheran Church, Child Dev., DBS Management
1999-2009	St Paul Lutheran Church, Child Dev.
2014-2017	St Paul Lutheran Church

5.6 REGULATORY AGENCIES

5.6.1 TAX ASSESSOR

EIS reviewed Santa Clara County Tax Assessor's Records online on January 26, 2021. According to information obtained from the assessor's website, the Assessor's Parcel Number (APN) for the subject property is 189-33-028. The parcel is approximately 0.72-acres in size and is addressed as 918 Rich Avenue, Mountain View, California. The last listed transfer date is 2/23/2009.

5.6.2 BUILDING DEPARTMENT

EIS submitted a records request to the City of Mountain View on February 8, 2020 to obtain information regarding the subject property. As of the publication date of this report, EIS has received no response from this department. If EIS obtains records of significance at a later date, an addendum summarizing new findings will be produced for this report.

5.6.3 FIRE DEPARTMENT

EIS submitted a records request to the City of Mountain View on February 8, 2020 to obtain information regarding the subject property. As of the publication date of this report, EIS has received no response from this department. If EIS obtains records of significance at a later date, an addendum summarizing new findings will be produced for this report.

5.6.4 DEPARTMENT OF ENVIRONMENTAL HEALTH

EIS submitted a file review request to the Santa Clara County Consumer and Environmental Protection Agency (CEPA) on February 8, 2021. As of the publication date of this report, EIS has received no response from this department. If EIS obtains records of significance at a later date, an addendum summarizing new findings will be produced for this report.

5.6.5 STATE WATER RESOURCES CONTROL BOARD

EIS reviewed the State Water Resources Control Board's (SWRCB's) GeoTracker database website on February 11, 2021 and found no records pertaining to the subject property.

Additionally, EIS reviewed the GeoTracker Database for sites located on adjoining properties or within 1/2-mile up- to cross-gradient of the subject property with cases involving soil or groundwater or potentially impacting the subject property. Records of significance are reviewed below:

Grossmans Mt. View – 1737 El Camino Real, Mountain View, CA (nearby to the north, ~400-feet cross-gradient).

- This case was opened on August 16, 1989 during the removal of a 550-gallon gasoline UST. Holes were observed in the tank and soil contamination was noted. 1,500 cubic yards of contaminated soil was excavated and removed in July 1992 and four groundwater monitoring wells were installed. This case was granted full regulatory closure on January 20, 1994.

The remaining five cleanup sites within ½-miles of the subject property are located southeast along W. El Camino Real, downgradient and across Permanente Creek from the subject property. Four of these sites, 1288 W El Camino Real, 1101 W. El Camino Real, and 1141 W. El Camino Real have all been granted full regulatory closure. The last site, 1313 El Camino Real, is an open solvent leak case. The most recent results from a

groundwater monitoring event in December 2020 show that the monitoring well closest to the subject property (approximately 1,200-feet southeast) had a detection of PCE below the applicable MCL of 5.0 µg/L.

5.6.6 DEPARTMENT OF TOXIC SUBSTANCES CONTROL

EIS reviewed the Department of Toxic Substance Control's (DTSC's) Envirostor database website on February 11, 2021 and found no records pertaining to the subject property.

Additionally, EIS reviewed the Envirostor database for sites located up- to cross-gradient of the subject property with cases involving groundwater or potentially impacting the subject property. EIS found no listings within one mile of the subject property.

5.7 PREVIOUS REPORTS

EIS was not provided any prior environmental reports conducted on the subject property.

5.8 DATABASE REVIEW

EIS reviewed a regulatory agency database search report prepared by EDR for information pertinent to the subject property and offsite facilities located within ASTM-specified search distances from the subject property. The database report is included in the appendices. The database report identifies 89 plotted sites, including the subject property, as well as the accessed databases for these sites and the dates when information was updated.

In evaluating whether or not a listed site poses a potential environmental concern to the subject property, EIS generally reviewed the distance of a site from the subject property, the site's hydrologic position relative to the subject property (up-, cross-, or down-gradient), and the regulatory status of any open/closed cases.

Agency List	Search Radius	Subject Property?	Number of Sites Within Radius	Number of Sites Warranting Detailed Discussion (Reason)
NPL	1 mile	No	0	0
DELISTED NPL	1/2 mile	No	0	0
SEMS/CERCLIS	1/2 mile	No	0	0

SEMS-ARCHIVE/CERCLISNFRAP	1/2 mile	No	0	0
RCRA CORRACTS	1 mile	No	3	0
RCRA LQG/SQG/CESQG/NLR	Site or Adjacent	No	3	1 (dry-cleaners)
US ENG CONTROLS	Site	No	0	0
US INST CONTROLS	Site	No	0	0
ERNS	Site	No	0	0
STATE/TRIBAL NPL	1 mile	Yes	3	0 (~1-mi cross gradient)
CA RESPONSE	1 mile	No	0	0
CA ENVIROSTOR	1 mile	No	0	0
STATE/TRIBAL SWF/LF	1/2 mile	No	0	0
STATE/TRIBAL REGISTERED STORAGE TANKS	Site or adjacent	No	1	1 (Distance, up to cross gradient)
STATE/TRIBAL LUST	1/2 mile	No	6	1 (Distance, cross-gradient)
STATE/TRIBAL VCP	1/2 mile	No	0	0
STATE/TRIBAL BROWNFIELD	1/2 mile	No	0	0
OTHER ENVIRONMENTAL RECORDS	100 feet	No	4	2 (Adjacent, cross-gradient)

No environmental liens appear to be on record against the subject property, based on review of the database search report. The following database listings were included for the subject property:

EIS identified the following database listings for adjoining or nearby properties located up- to cross-gradient of the subject property with cases involving groundwater or otherwise potentially impacting the subject property:

Blue Bird Cleaners – 1049 El Monte Avenue, Mountain View, CA (northwestern adjoining). CERS HAZWASTE, CERS, EDR HIST CLEANER, RCRA NONGEN/NLR, CUPA LISTING.

- Site occupant Blue Bird Cleaners is listed as a historical dry cleaner (1996 to present), hazardous waste generator, and chemical storage facility.
- HAZMAT inspection list minor violations related to HMBP submittals and list no violations during most recent March 2020 inspection. CUPA documents show facility operates one dry cleaning machine which utilizes DF-2000, a petroleum distillate-based solvent.

Franzman John Chevron – 1041 El Monte, Mountain View, CA (northwestern adjoining). EDR HIST AUTO.

- Site listed as a historical gasoline service station from 1969 to 1972. No further information available.

Grossmans Mountain View – 1737 El Camino Real, Mountain View, CA (nearby northern, ~530-feet up to cross-gradient). LUST, HIST LUST, CORTESE, HIST CORTESE, CERS.

- *See section 5.6.5 for a discussion of this listing.*

El Monte Chevron #376375 – 1010 El Monte Avenue, Mountain View, CA (nearby northwestern, ~530-feet up to cross-gradient). UST, CERS HAZWASTE, CERS TANKS, CUPA SANTA CLARA, HIST UST, SWEEPS UST, CA FID UST, RCRA NONGEN/NLR, EDR HIST AUTO.

- Site is listed as a gasoline service station, generator of hazardous wastes, handler of hazardous materials, and operator of underground storage tanks.
- Occupant Union Oil SS #3686 is listed as operating 3 USTs, one 10,000-gallon regular unleaded gasoline, one 10,000-gallon premium gasoline, and one 550-gallon waste oil UST. No releases or LUST cases identified – minor HMBP violation pertaining to employee training, failure to maintain inspection records and others. Facility returned to compliance for each noted infraction.
- Occupant Ricks Union 76 is listed as an EDR historical Auto business from 1999 to 2014.

EIS also researched the GeoTracker and Envirostor databases and found no additional adjoining or nearby properties located up- to cross-gradient of the subject property with

cases involving groundwater or otherwise potentially impacting the subject property except for those discussed in section 5.6.5 of this report.

6.0 NON-ASTM CONSIDERATIONS

6.1 ASBESTOS

The subject property is currently undeveloped but was developed with an historic structure which occupied the property between approximately 1948 to 2006. Because of the age of the structure, there is a potential that asbestos-containing materials (ACMs) were present in the building materials and could have impacted surficial site soils. Suspect ACMs were not observed during the site reconnaissance. However, prior to demolition or renovation of the building, it is recommended that an AHERA and State Certified Inspector Asbestos Consultant survey and test all suspect ACM that could potentially be disturbed by the work. If ACMs are found, have the Certified Asbestos Consultant prepare and implement work procedures and associated Operations and Maintenance (O&M) Plans, as applicable.

6.2 LEAD-BASED PAINT

The subject property is currently undeveloped but was developed with an historic structure which occupied the property between approximately 1948 to 2006. Though no structures stand at the subject property, demolition of the historic structure could potentially have impacted surficial site soils.

6.3 MOLD

The subject property is undeveloped and as such no mold evaluation was conducted.

6.4 RADON

Radon gas is a by-product of uranium. The gas forms as uranium molecules eject some protons and neutrons from their nuclei changing first into thorium, then radium, and finally radon. Radon tends to accumulate in uranium-rich metamorphic rocks, glacial moraines and till deposits derived from uranium-bearing rocks, marine organic shales, soils derived from carbonate rocks, and uranium-containing alluvial sediments deposited by rivers, deltas, lakes, etc. Outgassing of radon has not been identified as a problem in this region of Santa Clara County. According to radon survey results provided by the EDR, the subject property is located within Region 2 with average radon gas levels reported at 2 to 3 picocuries per liter of air (pCi/l). The level above which the U.S. Environmental Protection Agency recommends that action be taken to reduce radon levels is 4 pCi/l.

6.5 WETLANDS

EIS made visual observations for indications of the presence or potential presence of wetland areas on or immediately adjacent to the subject property. During reconnaissance, EIS observed no such indications of wetlands. No wetlands survey was performed. The

subject property and vicinity consist of fully developed urban land; no wetlands occur within the boundaries of the subject property or on the adjoining properties.

7.0 FINDINGS AND OPINIONS

Environmental Investigation Services Inc. (EIS) has completed a Phase I Environmental Site Assessment (ESA) for the property addressed as 918 Rich Avenue, Mountain View, California with APN #189-33-028 (subject property).

The approximately 0.72-acre (31,456-square feet) subject property is undeveloped in preparation of multifamily residential redevelopment. The entirety of the subject property is covered with wood mulch and several moderately sized trees exist along the perimeter the parcel. The parcel is surrounded by an approximately 8-foot-tall wood fence on all sides, except for the Rich Avenue entrance, which has a chain link fence. The subject property is accesses via a gate off the Rich Avenue frontage. An inground electrical utility vault and a fire hydrant were identified between the subject property gate and Rich Avenue.

EIS identified obvious subject property uses from the present back to 1939, at which time the subject property appeared to be undeveloped pastureland. By 1948 a small structure was visible on the eastern portion of the subject property and was visible in aerial photographs until 2006. The subject property has remained undeveloped since 2006. A 2018 aerial photograph obtained from Google Earth shows (Figure 2) shows the subject property in use as an apparent storage yard with numerous containers along the perimeter and large soil stockpiles visible in the northwestern portion of the property.

Surrounding properties appeared to be in similar use as the subject property in 1939 with all adjoining properties undeveloped pastures, except for a large warehouse structure occupying the northwestern adjoining property, and orchards beyond in all directions. By 1948, a residence was visible on the southern adjoining property and a rectangular warehouse was visible on the northeastern adjoining property. By 1956, the western and southwestern adjoining properties were developed with structures roughly matching the current. The northeastern residential complex was developed by 1963, and the large warehouse on the northwestern adjoining property appeared to be in use as a lumber yard by 1963. The northwestern adjoining lumber yard was redeveloped to match the current by 1998. Notable occupants of the adjoining properties include a Chevron gas station (northwestern adjoining property, 1969-1972), and Blue Bird Dry Cleaners (northwestern adjoining property, 1996 to present).

This ESA revealed the following notable findings:

- Aerial photographs of the subject property obtained from Google Earth show soil stockpiles in the northwestern portion of the subject property between at least June 2017 and July 2019. During this time period the subject property appeared to be in use as a construction storage yard with numerous storage containers along the perimeter. EIS has been unable to obtain any records indicating the

origin or use of the stockpiles. This finding represents a potential environmental concern.

- EIS identified the following notable tenants of adjoining properties: a dry-cleaning facility Bluebird cleaner (northwestern adjoining, ~25-years), Chevron Gas Station (northwestern adjoining, ~5-years). While no evidence of leaks, spills, or unauthorized releases was identified on these properties, minor CUPA inspection violations are noted for the dry cleaner property. At least one dry cleaning machine has been documented on the northwestern adjoining property, while multiple USTs were historically in use on the northwestern adjoining properties. The various historical commercial uses of the northwestern adjoining properties, including dry cleaning and gasoline station represent a potential vapor encroachment concern (PVEC).

- EIS identified one former lust case on a nearby property located within ¼ mile of the subject property. EIS found no evidence that this sit had impacted soil or groundwater resources located on the subject property. Additionally, this former LUST case has been granted full regulatory closure status from the Local Oversight Program. This finding is *de minimis*.

- The plotted and orphan facilities that were identified in the database search report within ¼ mile of the subject property are not expected to present an environmental concern to the subject property because: i) they only hold an operating permit (which does not imply a problem); ii) they are not required to perform further action; iii) the nature of the identified environmental concern does not suggest that the subject property would be impacted; or iv) based upon EIS's review, are too distant and/or hydraulically downgradient or cross-gradient relative to the subject property to reasonably affect it. This finding is *de minimis*.

8.0 CONCLUSION & RECOMMENDATIONS

EIS has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-13. This assessment has revealed no evidence of recognized environmental conditions (RECs), historical recognized environmental conditions (HRECs), or controlled recognized environmental conditions (CRECs), or potential vapor intrusion concerns (PVICs) in connection with the subject property, except for the following:

- The presence of soil stockpiles in the northwestern portion of the subject property between June 2017 and July 2019 without any documentation as to the origin or use of the stockpiles represents a potential environmental concern.

- The various commercial uses of the northwestern adjoining properties, including dry cleaning and gas station, represent a potential vapor encroachment concern (PVEC).

Prior to redevelopment of subject property for residential uses, EIS recommends a Phase 2 subsurface investigation to address the potential environmental concern and vapor encroachment concern.

9.0 SIGNATURE(S) OF ENVIRONMENTAL PROFESSIONAL(S)

"We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in 312.10 of 40 CFR 312" and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.




Peter Littman, Sr. Project Manager

PREPARED BY:

Environmental Investigation Services, Inc.
316 Mid Valley Center #313
Carmel, California 93923

FIGURES




Environmental Investigation Services, Inc.
316 Mid Valley Center #313
Carmel, California 93923
Ph: (408) 656-1032

Site Location Map

918 Rich Avenue, Mountain View, California

Figure: 1
EIS Project: 2103-1
February 3, 2021



Environmental Investigation Services, Inc.
316 Mid Valley Center #313
Carmel, California 93923
Ph: (408) 656-1032

Site Detail Map

918 Rich Avenue, Mountain View, California

Figure: 2
EIS Project: 2103-1
February 3, 2021

SITE PHOTOGRAPHS



Project No. 2103-1	**Description**	View to the west of subject property.	**1**
	Name	918 Rich Avenue, Mountain View, California	**Photo Date** February 4, 2021



Project No. 2103-1	**Description**	View to the east of Rich Avenue in the foreground and adjoining residential complex beyond.	**2**
	Name	918 Rich Avenue, Mountain View, California	**Photo Date** February 4, 2021



Project No. 2103-1	**Description**	View to the northwest of Rich Avenue in the foreground and the northeastern adjoining residential property beyond.	**3**
	Name	918 Rich Avenue, Mountain View, California	**Photo Date** February 4, 2021



Project No. 2103-1	**Description**	View to the southwest of adjoining residential property.	**4**
	Name	918 Rich Avenue, Mountain View, California	**Photo Date** February 4, 2021



Project No. 2103-1	Description	View to the northeast, over border wall, between the northwestern adjoining commercial complex and the subject property.	5
	Name	918 Rich Avenue, Mountain View, California	Photo Date February 4, 2021



Project No. 2103-1	Description	View to the west, over fence, of western adjoining commercial offices.	6
	Name	918 Rich Avenue, Mountain View, California	Photo Date February 4, 2021




Project No. 2103-1	Description	View to the southwest of adjoining church property.	7
	Name	918 Rich Avenue, Mountain View, California	Photo Date February 4, 2021



Project No. 2103-1	Description	View to the southeast, from northwest corner, of subject property.	8
	Name	918 Rich Avenue, Mountain View, California	Photo Date February 4, 2021



Project No. 2103-1	**Description**	View of abandoned utility pole along western fence at the subject property.	**9**
	Name	918 Rich Avenue, Mountain View, California	**Photo Date** February 4, 2021



Project No. 2103-1	**Description**	View of northwestern adjoining commercial shopping center (left) and dry-cleaner in northwestern adjoining commercial shopping center (right).	**10**
	Name	918 Rich Avenue, Mountain View, California	**Photo Date** February 4, 2021

APPENDIX A
QUALIFICATIONS

QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONAL(S)

Mr. Peter Littman, Project Manager has 25 years of experience managing environmental due diligence investigations as a Cal/EPA Registered Environmental Assessor (#03829) for property transactions including a large variety of commercial, industrial, and agricultural properties.

Mr. Littman excels at assessing property to determine whether further investigations are necessary to ensure compliance with laws or to complete due diligence and estimating the investigation and cleanup costs. He has successfully coordinated and completed numerous complex due diligence investigations within tight budget and time constraints.

Prior to forming EIS in 1996, Mr. Littman provided environmental consulting services for four years. As a Cal/EPA Registered Environmental Assessor, Mr. Littman has performed over 1,000 Phase 1 Environmental Assessments. As a project manager, he has completed over 200 soil and groundwater investigations, 60 tank removals, 25 soil remediation projects, 80 asbestos inspections, 50 lead paint inspections, and 30 Hazardous Material Management Plans. Mr. Littman has assisted clients in qualifying for the state tank fund and under guidance of professional staff has helped design site characterization and site remediation at tank fund sites.

As a project manager with C.E.T., Inc. he managed tank removal operations, soil and groundwater investigations, and Phase I assessments. He has also held a position as Corporate Health and Safety Officer for EVAX Technologies Inc., an Environmental Engineering/Contracting firm where he performed Phase I's and site safety plans for Hazardous Waste clean-up operations and conducted Federal OSHA 40 Hour Training Sessions. As a Health & Safety Officer he worked with a team designing underground tank removals, building decontamination of solvents, excavations, soil and groundwater sampling, and installation of remedial equipment.

Credentials

- Cal/EPA Registered Environmental Assessor REA #03829
- Federal OSHA Hazardous Waste Operation & Emergency Response 40 Hr and 8 Hr Supervisor

APPENDIX B
SOURCES CHECKED

SOURCES CHECKED

CONTACTS:

Agency and division/source:	Santa Clara County Tax Assessor's Office
Name/title of representative:	Staff
Location of agency:	70 W Hedding Street, San Jose, California
Agency telephone number:	(408) 299-5500

Agency and division/source:	Mountain View Building Department
Name/title of representative:	Staff
Location of agency:	500 Castro Street, Mountain View, California
Agency telephone number:	(650) 903-6313

Agency and division/source:	Mountain View City Clerk's Office
Name/title of representative:	Margarita Herrera
Location of agency:	500 Castro Street, Mountain View, California
Agency telephone number:	(650) 903-6641

Agency and division/source:	Santa Clara County Consumer and Environmental Protection Agency
Name/title of representative:	Melissa Belloso
Location of agency:	1533 Berger Drive Suite 200, San Jose, California
Agency telephone number:	(408) 918-3421

Agency and division/source:	California Regional Water Quality Control Board – San Francisco Bay Region
Name/title of representative:	Staff
Location of agency:	1515 Clay Street, Suite 1400, Oakland, California
Agency telephone number:	(510) 622-2430

Agency and division/source:	California Department of Toxic Substances Control
Name/title of representative:	Staff
Location of agency:	700 Heinz Avenue, Suite 200, Berkeley, California
Agency telephone number:	(510) 540-3003

REFERENCES:

Name of publication:	EDR Radius Map with GeoCheck
Author of publication:	Environmental Data Resources, Inc. (EDR)
Date of publication:	January 29, 2021
Name of publication:	EDR Aerial Photo Decade Report
Author of publication:	EDR
Date of publication:	January 29, 2021
Name of publication:	EDR Historical Topo Map Report
Author of publication:	EDR
Date of publication:	January 29, 2021
Name of publication:	EDR Sanborn®Map Report
Author of publication:	EDR
Date of publication:	January 29, 2021
Name of publication:	EDR City-Directory Image Report
Author of publication:	EDR
Date of publication:	January 29, 2021
Name of publication:	Groundwater Monitoring Report 4th Quarter 2020 – 1313-1346 El Camino Real, Mountain View, CA
Author of publication:	Environmental Investigation Services, Inc. (EIS)
Date of publication:	December 21, 2020
Name of Publication:	Case Closure Document – 1530 Blossom Hill Road, San Jose, CA, and Grossmans, 1737 El Camino Real, Mountain View, CA
Author of Publication:	California RWQCB
Date of Publication:	January 14, 1994

APPENDIX C
FIRE INSURANCE MAPS

Residential Property

918 Rich Avenue

Mountain View, CA 94040

Inquiry Number: 6348854.3

January 29, 2021

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

01/29/21

Site Name:

Residential Property
918 Rich Avenue
Mountain View, CA 94040
EDR Inquiry # 6348854.3

Client Name:

Env. Inv. Services, Inc.
9311 Holt Road
Carmel, CA 93923
Contact: Peter Littman

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Env. Inv. Services, Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # A945-486A-B488

PO # 2103-1

Project 2103-1

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: A945-486A-B488

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Env. Inv. Services, Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

APPENDIX D
AERIAL PHOTOGRAPHS

Residential Property

918 Rich Avenue

Mountain View, CA 94040

Inquiry Number: 6348854.8

January 29, 2021

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

01/29/21

Site Name:

Residential Property
918 Rich Avenue
Mountain View, CA 94040
EDR Inquiry # 6348854.8

Client Name:

Env. Inv. Services, Inc.
9311 Holt Road
Carmel, CA 93923
Contact: Peter Littman

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2016	1"=500'	Flight Year: 2016	USDA/NAIP
2012	1"=500'	Flight Year: 2012	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1998	1"=500'	Flight Date: August 27, 1998	USDA
1991	1"=500'	Acquisition Date: January 01, 1991	USGS/DOQQ
1982	1"=500'	Flight Date: July 05, 1982	USDA
1974	1"=500'	Flight Date: June 26, 1974	USGS
1968	1"=500'	Flight Date: June 14, 1968	USGS
1963	1"=500'	Flight Date: June 23, 1963	EDR Proprietary Aerial Viewpoint
1956	1"=500'	Flight Date: July 02, 1956	USDA
1950	1"=500'	Flight Date: April 03, 1950	USDA
1948	1"=500'	Acquisition Date: September 26, 1948	USGS/DOQQ
1939	1"=500'	Flight Date: July 31, 1939	USDA


When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.


Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2021 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 6348854.8
YEAR: 2016
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 2012
= 500'
N
EDR



INQUIRY #: 6348854.8
YEAR: 2009
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 2006
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1998
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1991
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1982
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1974
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1968
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1963
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1956
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1950
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1948
= 500'
N
EDR


INQUIRY #: 6348854.8
YEAR: 1939
= 500'
N
EDR

APPENDIX E
CITY DIRECTORIES

Residential Property
918 Rich Avenue
Mountain View, CA 94040

Inquiry Number: 6348854.5
January 29, 2021

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.


Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1922 through 2017. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 660 feet of the target property.

A summary of the information obtained is provided in the text of this report.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.



RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	Source	TP	Adjoining	Text Abstract	Source Image
2017	Cole Information Services	-	X	X	-
2014	Cole Information Services	X	X	X	-
2009	Cole Information Services	X	X	X	-
2006	Haines Company, Inc.	-	-	-	-
2004	Cole Information Services	-	X	X	-
2001	Haines Company, Inc.	-	X	X	-
2000	Haines Company	-	-	-	-
1999	Cole Information Services	X	X	X	-
1996	Pacific Bell	-	-	-	-
1994	Cole Information Services	-	X	X	-
1991	PACIFIC BELL WHITE PAGES	-	X	X	-
	Pacific Telephone	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1986	Pacific Bell	-	X	X	-
1985	Pacific Bell	-	X	X	-
1982	Pacific Telephone	-	X	X	-
1980	Pacific Telephone	-	-	-	-
1978	R. L. Polk & Co.	-	-	-	-
1975	Pacific Telephone	-	X	X	-
1974	R. L. Polk Co.	-	-	-	-
1970	R. L. Polk Co.	-	-	-	-
1968	R. L. Polk Co.	-	X	X	-
1966	R. L. POLK	-	-	-	-
1965	R. L. Polk Co.	-	-	-	-
1964	R. L. Polk Co.	-	-	-	-
1963	Pacific Telephone	-	-	-	-
1962	R. L. Polk & Co.	-	X	X	-
1960	R. L. Polk Co.	-	-	-	-
1957	Pacific Telephone	-	X	X	-
1955	R.L. Polk and Co Publishers	-	-	-	-
1950	R. L. Polk & Co.	-	X	X	-
1946	R. L. Polk Co.	-	-	-	-
1945	R. L. Polk Co.	-	-	-	-
1942	R.L. Polk	-	-	-	-
1940	R. L. Polk Co.	-	-	-	-
1936	R. L. Polk Co.	-	-	-	-
1935	R. L. Polk Co.	-	-	-	-
1931	R. L. Polk Co.	-	-	-	-
1930	R. L. Polk Co. of California	-	-	-	-
1926	R. L. Polk Co.	-	-	-	-
1925	R. L. Polk Co.	-	-	-	-
1922	R. L. Polk Co.	-	-	-	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	***Type***	***Findings***
1039 El Monte Ave.	Client Entered	
1059 El Monte Avenue	Client Entered	X
1075 El Monte Avenue	Client Entered	X
912 Rich Avenue	Client Entered	X
959 Rich Avenue	Client Entered	X
1039 El Monte Ave.	Client Entered	
1041 El Monte Ave.	Client Entered	
1043 El Monte Ave.	Client Entered	
1045 El Monte Ave.	Client Entered	
1047 El Monte Ave.	Client Entered	
1049 El Monte Ave.	Client Entered	

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

918 Rich Avenue
Mountain View, CA 94040

FINDINGS DETAIL

Target Property research detail.

RICH AVE

918 RICH AVE

Year	*Uses*	*Source*
2014	SUSAN UECKER	Cole Information Services
2009	SUSAN UECKER	Cole Information Services
1999	SUSAN UECKER	Cole Information Services

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

E EL CAMINO REAL

1495 E EL CAMINO REAL

Year	Uses	Source
1986	BICENTENNIAL GLASS COMPANY	Pacific Bell
1982	MC LEOD GLASS CO	Pacific Telephone
	BICENTENNIAL GLASS COMPANY	Pacific Telephone
1975	Prowse O Frank Jr Mc Leod Glass Co	Pacific Telephone
	Lawson R R Me Leod Glass Co	Pacific Telephone
1962	MCLEOD GLASS COMPANY (R BUD LAWSON) GLASS DEALERS REPLACEMENTS ALL TYPES OF	R. L. Polk & Co.

1524 E EL CAMINO REAL

Year	Uses	Source
1986	FORESEE S DESSERTS ETC	Pacific Bell

1528 E EL CAMINO REAL

Year	Uses	Source
1975	Internatl Nursery & Florist	Pacific Telephone
1962	INTERNATIONAL NURSERY (SALVATORE GERACIAICOHI VINCENT SALTAMAICHI SALVATORE	R. L. Polk & Co.
1957	INTERIRNATLONAL NURSERY & FLORIST	Pacific Telephone

1544 E EL CAMINO REAL

Year	Uses	Source
1986	DINO S AUTO CENTER	Pacific Bell

1550 E EL CAMINO REAL

Year	Uses	Source
1962	COLLINS GRACE MRS MGR DER GHLAN MOTEL	R. L. Polk & Co.
	COLLINS JOHN A (GRACE) MGR DER GHAN MOTEL	R. L. Polk & Co.
	DERGHAN MOTEL JOHN A AND MRS GRACE COLLINS MIGRS	R. L. Polk & Co.

FINDINGS

1561 E EL CAMINO REAL

Year	*Uses*	*Source*
1982	Henson Cled	Pacific Telephone
1975	Popovich Donald L And Company devlpmnt brkrs	Pacific Telephone
1962	ROBLEDA (WILLIAM R JELAVICH) GROWERS AND PACKERS OF CALIFORNIA FINEST FRUIT	R. L. Polk & Co.

1571 E EL CAMINO REAL

Year	*Uses*	*Source*
1986	Barhart Dan I	Pacific Bell
	CAMINO PARK APARTMENTS	Pacific Bell
	Coffman Paul	Pacific Bell
	Crain Cynthia	Pacific Bell
	Donlin James	Pacific Bell
	Fasulo Gene	Pacific Bell
	Hammack Fred T	Pacific Bell
	Hennen M	Pacific Bell
	King Linda A	Pacific Bell
	Kiss Inger C	Pacific Bell
	Kodama E	Pacific Bell
	Krlder Kenneth B	Pacific Bell
	Leggate Ralph J	Pacific Bell
	Poon Chiu Yong	Pacific Bell
	Redeker Rick	Pacific Bell
	Roth Coral	Pacific Bell
	Schirle Joan	Pacific Bell
	Schmidt John P	Pacific Bell
	Stahl Greg C	Pacific Bell
	Terman Fred	Pacific Bell
	Wasserman Ned	Pacific Bell
	Wilson James	Pacific Bell
	Wood Michael H	Pacific Bell
	CAMINO PARK APARTMENTS	Pacific Bell
	CRAIN CYNTHIA	Pacific Bell
	HAMMACK FRED T	Pacific Bell
	KING LINDA A	Pacific Bell
	POON CHIU YONG	Pacific Bell
	ROTH CORAL	Pacific Bell
	SANDERS REGINALD L	Pacific Bell

FINDINGS

Year	Uses	Source
1986	SCHIRLE JOAN	Pacific Bell
1982	Beall Genny C	Pacific Telephone
	t Beall Greg	Pacific Telephone
	Burks R A	Pacific Telephone
	Donliri James	Pacific Telephone
	Gump Tom	Pacific Telephone
	Katilivs G	Pacific Telephone
	Kissinger C	Pacific Telephone
	Mooney SD O	Pacific Telephone
	Ryan Thos P	Pacific Telephone
	Thomas Clay	Pacific Telephone
1975	Astrella Rocco D	Pacific Telephone
	Bergeron Harold	Pacific Telephone
	Bickers Robt K	Pacific Telephone
	Blecksmith Chas E	Pacific Telephone
	Borbons Ralph E	Pacific Telephone
	Bruner Clifton R	Pacific Telephone
	Cook S D	Pacific Telephone
	Davie Donald L	Pacific Telephone
	Dietrich Karen L	Pacific Telephone
	Hammack Fred T	Pacific Telephone
	Hanenburg Sandy J	Pacific Telephone
	Hanson Henry F	Pacific Telephone
	Kaispr Gerald A I	Pacific Telephone
	KAISER CEMENT & GYPSUM CORPORATION	Pacific Telephone
	Kennedy Michael R	Pacific Telephone
	Logan Tim	Pacific Telephone
	Mc Cray Russell B	Pacific Telephone
	Minafo Frank J	Pacific Telephone
	Randell Richard G	Pacific Telephone
	Roper Henry D	Pacific Telephone
	Rozemna M	Pacific Telephone
	Ruiz David	Pacific Telephone
	Schuster Jorgini	Pacific Telephone
	Spence N	Pacific Telephone
	Stojanovich Franja	Pacific Telephone
	Vigario Georgenia	Pacific Telephone

FINDINGS

1580 E EL CAMINO REAL

Year	Uses	Source
1986	STATE	Pacific Bell
	Barkey Stan	Pacific Bell
	Prospective Commodity Capital Fund	Pacific Bell
	FAITH CHRISTIAN COMMUNITY	Pacific Bell
	Bass Lewis atty	Pacific Bell
	Anderson Bob	Pacific Bell
	BAXTER GURIAN & MAZZEI INC ADVERTISING & MARKETING	Pacific Bell
	TRANSAMERICA FINANCIAL:SERVICES Contd	Pacific Bell
	PRENATAL DIAGNOSTICS INC	Pacific Bell
	FAITH CHRISTIAN COMMUNITY	Pacific Bell
	MARSDQN KEITH DC	Pacific Bell
	BASS SHARON MFCC	Pacific Bell
	ADVANCED FINANCIAL DESIGNS	Pacific Bell

1581 E EL CAMINO REAL

Year	Uses	Source
1986	A I Appliance	Pacific Bell
	A 1 Alarm Co	Pacific Bell
1975	Frosolone Realty	Pacific Telephone

1585 E EL CAMINO REAL

Year	Uses	Source
1986	Shot Errin	Pacific Bell
	Sborov Victor M MD	Pacific Bell
	Sly Randail L	Pacific Bell
1982	Nichols E	Pacific Telephone
	Tran Anh	Pacific Telephone

1601 E EL CAMINO REAL

Year	Uses	Source
1975	Thorsons Bonanza TV	Pacific Telephone
1957	CENTRAL PROPERTIES	Pacific Telephone

1603 E EL CAMINO REAL

Year	Uses	Source
1986	B FL	Pacific Bell
	BFM	Pacific Bell

FINDINGS

Year	Uses	Source
1986	S DC S	Pacific Bell
1962	ABBEY S UPHOLSTERY SHOP (FORREST ABBEY) REPAIRING REMODELING COMPLETE UPHOL	R. L. Polk & Co.

1615 E EL CAMINO REAL

Year	Uses	Source
1986	RENAISSANCE STUDIO	Pacific Bell
1982	RENAISSANCE STUDIO	Pacific Telephone

1620 E EL CAMINO REAL

Year	Uses	Source
1986	LOZARES BERNARD INS	Pacific Bell
	LOZARES CHRISTENSEN & POULS	Pacific Bell
1982	LOZARES CHRISTENSEN & POULS	Pacific Telephone

1622 E EL CAMINO REAL

Year	Uses	Source
1986	CRUISE CONNECTION	Pacific Bell
1975	Patrick Tom Ins	Pacific Telephone

1625 E EL CAMINO REAL

Year	Uses	Source
1986	COMPUTERLAND OF BELMONT	Pacific Bell

1665 E EL CAMINO REAL

Year	Uses	Source
1986	CASA CAMt NO MOTEL	Pacific Bell
1982	Patel Bitin P	Pacific Telephone

1670 E EL CAMINO REAL

Year	Uses	Source
1986	EGEBERG J E	Pacific Bell

1695 E EL CAMINO REAL

Year	Uses	Source
1957	LEE RICHARD S MD PALA ALTO MEDCL CINIC	Pacific Telephone

1701 E EL CAMINO REAL

Year	Uses	Source
1986	FITNESS STORE THE	Pacific Bell

FINDINGS

Year	Uses	Source
1975	Yin Yang Water Beds	Pacific Telephone
1962	FRANZESE ORNAMENTAL IRON WORKS (ANDREW FRANZESE)	R. L. Polk & Co.

1707 E EL CAMINO REAL

Year	Uses	Source
1975	Fields Limousine Service	Pacific Telephone
	Fields Wheel Chair Car	Pacific Telephone
	Fields Rental Service	Pacific Telephone

1709 E EL CAMINO REAL

Year	Uses	Source
1962	COUCH DOUG INC REALTOR GRETCHEN BUCHANAN SALES MANAGER A COMPLETE REAL ESTA	R. L. Polk & Co.

1710 E EL CAMINO REAL

Year	Uses	Source
1962	GREEN LUCILLE	R. L. Polk & Co.
	LANDERS EDITH	R. L. Polk & Co.
	LOWE STANLEY CUSTDN CHESTER F AWAIT HIGH SCH	R. L. Polk & Co.
	MOBILE MANOR (ROBT H KEMPLE) TRAILER PARK	R. L. Polk & Co.
	CADY ROBT	R. L. Polk & Co.

1711 E EL CAMINO REAL

Year	Uses	Source
1986	Daybreak	Pacific Bell
1962	WILLY S TAP-TONIC (WM MONGILLO) TAVERN	R. L. Polk & Co.

1741 E EL CAMINO REAL

Year	Uses	Source
1962	FURNITURE FARM (WIM J DALEY AND CLYDE BASS)	R. L. Polk & Co.

1749 E EL CAMINO REAL

Year	Uses	Source
1962	TRIANGLE GARAGE INC EZRA E JONES PRES	R. L. Polk & Co.

FINDINGS

EL CAMINO REAL

1501 EL CAMINO REAL

Year	*Uses*	*Source*
1950	MUDRICH S	R. L. Polk & Co.

1513 EL CAMINO REAL

Year	*Uses*	*Source*
1975	Payless Service Station	Pacific Telephone

1571 EL CAMINO REAL

Year	*Uses*	*Source*
1975	Wieferich Jas R	Pacific Telephone
	Fasulo Gene	Pacific Telephone

1580 EL CAMINO REAL

Year	*Uses*	*Source*
1950	MINKER JAS	R. L. Polk & Co.

1616 EL CAMINO REAL

Year	*Uses*	*Source*
1950	FIELD ELIZ MRS	R. L. Polk & Co.
	ALLEN MINNA	R. L. Polk & Co.
	CASTRO JOHN	R. L. Polk & Co.
	BUBB LOUISE MRS	R. L. Polk & Co.
	MOUNTAIN CHITTENDEN JESSIE	R. L. Polk & Co.
	COLBURN CHAS	R. L. Polk & Co.
	DORGAN MAY	R. L. Polk & Co.
	I CHRISTINA MRS	R. L. Polk & Co.
	HELD CLARA	R. L. Polk & Co.
	MORSE ANNABELLE	R. L. Polk & Co.
	DUCTS MARY MRS	R. L. Polk & Co.
	MGR	R. L. Polk & Co.
	RAPLEY JAS	R. L. Polk & Co.
	U MARY MRS	R. L. Polk & Co.
	U	R. L. Polk & Co.
	CHIQUITA PAUL	R. L. Polk & Co.
	BX EUREKA MRS	R. L. Polk & Co.

FINDINGS

1622 EL CAMINO REAL

Year	*Uses*	*Source*
1975	Lozares Bernard ins	Pacific Telephone

1711 EL CAMINO REAL

Year	*Uses*	*Source*
1975	Boogie Inn	Pacific Telephone

1735 EL CAMINO REAL

Year	*Uses*	*Source*
1950	BLDG MATLS	R. L. Polk & Co.

1745 EL CAMINO REAL

Year	*Uses*	*Source*
1950	LAUB MGR	R. L. Polk & Co.

EL CAMINO REAL E

1528 EL CAMINO REAL E

Year	*Uses*	*Source*
1968	INTERNATIONAL NURSERY	R. L. Polk Co.

1550 EL CAMINO REAL E

Year	*Uses*	*Source*
1968	DER GHAN MOTEL	R. L. Polk Co.

EL CAMINO REAL W

1495 EL CAMINO REAL W

Year	*Uses*	*Source*
1968	MC LEOD GLASS CO	R. L. Polk Co.

1513 EL CAMINO REAL W

Year	*Uses*	*Source*
1968	TRIANGLE GARAGE	R. L. Polk Co.

1544 EL CAMINO REAL W

Year	*Uses*	*Source*
1986	Dinos Auto Center	Pacific Bell
1968	MOTORCYCLE SALES & SERV	R. L. Polk Co.
	PENINSULA IMPORTS	R. L. Polk Co.
	HELI ARC WELDING	R. L. Polk Co.

FINDINGS

1561 EL CAMINO REAL W

Year	Uses	Source
1968	REAR HENSON CLEO	R. L. Polk Co.
	ROBLEDA PACKING CO FRUIT	R. L. Polk Co.

1571 EL CAMINO REAL W

Year	Uses	Source
1986	Sanders Reginald L	Pacific Bell
1975	Horlacher A	Pacific Telephone
	Beech David	Pacific Telephone

1580 EL CAMINO REAL W

Year	Uses	Source
1986	Sylvan Learning Center	Pacific Bell
	Bass Sharon MFCC	Pacific Bell
1968	BELLEVUE MOTEL	R. L. Polk Co.

1581 EL CAMINO REAL W

Year	Uses	Source
1968	KARLIN REALTY	R. L. Polk Co.

1585 EL CAMINO REAL W

Year	Uses	Source
1968	CORONADO MOTEL	R. L. Polk Co.

1601 EL CAMINO REAL W

Year	Uses	Source
1968	POLLOCK RADIO T V	R. L. Polk Co.
	CENTER SLS & REPR	R. L. Polk Co.
	SCHILLER JOSEPH	R. L. Polk Co.

1603 EL CAMINO REAL W

Year	Uses	Source
1968	THORSON POLLOCK T V CENTER	R. L. Polk Co.
	ANDREWS M S	R. L. Polk Co.

1615 EL CAMINO REAL W

Year	Uses	Source
1968	RENAISSANCE STUDIO FURN PEPR	R. L. Polk Co.

FINDINGS

1616 EL CAMINO REAL W

Year	Uses	Source
1975	Copper Wheel Restaurant	Pacific Telephone

1621 EL CAMINO REAL W

Year	Uses	Source
1968	COUCH DOUGLAS	R. L. Polk Co.
	INSURANCE INC	R. L. Polk Co.
	COUCH DOUG GENERAL	R. L. Polk Co.
	COUCH DOUG INC REAL EST	R. L. Polk Co.
	CONTRACTORS INC	R. L. Polk Co.

1622 EL CAMINO REAL W

Year	Uses	Source
1986	Cruise Connection	Pacific Bell

1665 EL CAMINO REAL W

Year	Uses	Source
1968	CASA CAMINO MOTEL	R. L. Polk Co.

1707 EL CAMINO REAL W

Year	Uses	Source
1968	FIELDS AMBULANCE SERVICE	R. L. Polk Co.
	SERVICE AUTOMOBILE RENTING	R. L. Polk Co.
	FIELDS LIMOSINE	R. L. Polk Co.

1709 EL CAMINO REAL W

Year	Uses	Source
1968	DELLA CRUZ MARIE	R. L. Polk Co.
	APARTMENTS	R. L. Polk Co.
	VACANT	R. L. Polk Co.
	RABELLIZSA NINA MRS	R. L. Polk Co.
	SARTOR IRENE MRS	R. L. Polk Co.

1711 EL CAMINO REAL W

Year	Uses	Source
1968	FITZGERALDS ISLAND TAVERN	R. L. Polk Co.

1737 EL CAMINO REAL W

Year	Uses	Source
1968	HUBBARD & JOHNSON	R. L. Polk Co.

FINDINGS

EL CAMINO RL W

1544 EL CAMINO RL W

Year	Uses	Source
1991	A 1 FOREIGN AUTO REPAIR & PARTS	Pacific Telephone

1561 EL CAMINO RL W

Year	Uses	Source
1991	COMFORT INN	Pacific Telephone

1580 EL CAMINO RL W

Year	Uses	Source
1991	CONTE WILLIAM J MD	Pacific Telephone
	BAXTER GURIAN & MAZZEI INC ADVERTISING	Pacific Telephone

1581 EL CAMINO RL W

Year	Uses	Source
1991	A 1 ALARM CO	Pacific Telephone
	A 1 APPLIANCE	Pacific Telephone
	A SHIVA GALLERY	Pacific Telephone

1603 EL CAMINO RL W

Year	Uses	Source
1991	C & ME ADVERTISING	Pacific Telephone

1605 EL CAMINO RL W

Year	Uses	Source
1991	C & ME DESIGN	Pacific Telephone
	ALLSTATE INSURANCE COMPANIES	Pacific Telephone

1615 EL CAMINO RL W

Year	Uses	Source
1991	RATIONAL BEHAVIOR	Pacific Telephone

1616 EL CAMINO RL W

Year	Uses	Source
1991	TONY ROMAS A PLACE FOR RIBS	Pacific Telephone

1621 EL CAMINO RL W

Year	Uses	Source
1991	BROKERS NETWORK	Pacific Telephone

Year	Uses	Source
1991	BROKERS FINANCIAL	Pacific Telephone
	TYECIN SYSTEMS INC	Pacific Telephone
	MOBLE HOUSE	Pacific Telephone
	MARSH PROPERTIES	Pacific Telephone

1622 EL CAMINO RL W

Year	Uses	Source
1991	A TIME FOR YOU HAIR STYLING BY EVELYN PULERA	Pacific Telephone
	A TIME FOR YOU	Pacific Telephone

1665 EL CAMINO RL W

Year	Uses	Source
1991	CASA CAMINO MOTEL	Pacific Telephone

EL CANRINO REAL W

1571 EL CANRINO REAL W

Year	Uses	Source
1975	Cipolla Sharon A	Pacific Telephone

EL MNTE AVE

1057 EL MNTE AVE

Year	Uses	Source
1975	Kirk Erie R marriage & family counsir	Pacific Telephone

EL MONTE AVE

1028 EL MONTE AVE

Year	Uses	Source
2001	XXXX	Haines Company, Inc.
1975	Centanni C Ken	Pacific Telephone

1030 EL MONTE AVE

Year	Uses	Source
2017	JONATHAN FIGDOR	Cole Information Services
	EMBEDDED MICRO	Cole Information Services
	PATRICIA KHOO	Cole Information Services
	HELEN LARSONWHA	Cole Information Services
	ROBERT LUPUL	Cole Information Services

FINDINGS

Year	Uses	Source
2017	MARK TSUCHIDA	Cole Information Services
	JOAN WITTMANN	Cole Information Services
	ANABEL ARIAS	Cole Information Services
	CHING TUNG	Cole Information Services
	DONGYUE ZHOU	Cole Information Services
	XIN YAN	Cole Information Services
	IAN COATS	Cole Information Services
	KIMBERLY DERVISH	Cole Information Services
	PAUL HARMS	Cole Information Services
	FRANCES PUELLO	Cole Information Services
	TATYANA SHISHKINA	Cole Information Services
	B XU	Cole Information Services
	GARY FRENZEL	Cole Information Services
	JOSETTE LANGEVINE	Cole Information Services
	JONATHAN MCGEE	Cole Information Services
	RENE BAHENA	Cole Information Services
	FERESHTEH AFKHAMI	Cole Information Services
	CARL BELL	Cole Information Services
	NINA DILLINGHAM	Cole Information Services
	INSUNG JOE	Cole Information Services
	DANIELA PETKOVA	Cole Information Services
	NATSUKO AKABA	Cole Information Services
	SHAHRIAR ILISLAMLOO	Cole Information Services
	DEAN LAMBERTON	Cole Information Services
	GEORGE MONACO	Cole Information Services
	YUJIE ZHOU	Cole Information Services
	JOHN BEITIA	Cole Information Services
	HELEN CRAIG	Cole Information Services
	KAILASAM DURAISWAMY	Cole Information Services
	STEPHEN HUANG	Cole Information Services
	JEREMY KERBY	Cole Information Services
	XIN ZHAO	Cole Information Services
	FABIO DEAMICIS	Cole Information Services
	ROBERT KENDALL	Cole Information Services
	DAISY PENA	Cole Information Services
	ISABELLE SCHINAS	Cole Information Services
	ANNIE TEPE	Cole Information Services
	THE VILLA MONTE	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2017	CYNTHIA HANNAN	Cole Information Services
2014	DEAN LAMBERTON	Cole Information Services
	MERRY PATAPOFF	Cole Information Services
	CAROLIN PURMANN	Cole Information Services
	STUART OLSON	Cole Information Services
	JOHN BEITIA	Cole Information Services
	PATRICIA EATON	Cole Information Services
	ROUJA PAKIMAN	Cole Information Services
	DAVID WILLIS	Cole Information Services
	FABIO DEAMICIS	Cole Information Services
	DAISY PENA	Cole Information Services
	KIM HYUNGBIN	Cole Information Services
	JONATHAN FIGDOR	Cole Information Services
	HELEN LARSONWHA	Cole Information Services
	ROBERT LUPUL	Cole Information Services
	JOAN WITTMANN	Cole Information Services
	MARK TSUCHIDA	Cole Information Services
	JULIE ROSE	Cole Information Services
	CHING TUNG	Cole Information Services
	HEATHER SCHWENN	Cole Information Services
	MIKE BAKH	Cole Information Services
	MAGGIE CASTILLO	Cole Information Services
	IAN COATS	Cole Information Services
	KIMBERLY DERVISH	Cole Information Services
	RONG FU	Cole Information Services
	FRANCES PUELLO	Cole Information Services
	ERIC GULBRANSEN	Cole Information Services
	TATYANA SHISHKINA	Cole Information Services
	RENE BAHENA	Cole Information Services
	GARY FRENZEL	Cole Information Services
	CARL BELL	Cole Information Services
	SHANNON CHASE	Cole Information Services
	VINCENT SCOPINO	Cole Information Services
	THE VILLA MONTE	Cole Information Services
2009	HYUNG KIM	Cole Information Services
	COAST AUTO INSURANCE SERVICES INC	Cole Information Services
	THOMAS PAMILLA	Cole Information Services
	R KARAGAH	Cole Information Services

FINDINGS

Year	Uses	Source
2009	DONNA LOWE	Cole Information Services
	STEVEN CONGER	Cole Information Services
	ERNEST HO	Cole Information Services
	LORRAINE FRAIN	Cole Information Services
	FABIO DEAMICIS	Cole Information Services
	JAMES CADY	Cole Information Services
	JEFFREY KENDALL	Cole Information Services
	MASAKI KATO	Cole Information Services
	ROBERT LUPUL	Cole Information Services
	JOAN WITTMANN	Cole Information Services
	HEATHER SCHWENN	Cole Information Services
	MARCO HOLLWEG	Cole Information Services
	K MEDEIROS	Cole Information Services
	TATYANA SHISHKINA	Cole Information Services
	JAMES ROWLES	Cole Information Services
	MICHAEL CHIU	Cole Information Services
	DANY GHANNAM	Cole Information Services
	PAM JONES	Cole Information Services
	Y SHIH	Cole Information Services
	SCOTT LAFLEUR	Cole Information Services
	ROBERT LARSON	Cole Information Services
	BISWAZIT NANDA	Cole Information Services
	PAUL JENNINGS	Cole Information Services
	GARY FRENZEL	Cole Information Services
	KATHLEEN HINES	Cole Information Services
	BARBARA DICKINSON	Cole Information Services
	ANNA WORONIECKA	Cole Information Services
	INSUNG JOE	Cole Information Services
	STEFANUS JASIN	Cole Information Services
	PMC SERVICES	Cole Information Services
	KHIN WIN	Cole Information Services
2004	KAREN PETERS	Cole Information Services
	NAPA VALLEY CAST STONE	Cole Information Services
	A STORCH	Cole Information Services
	JO TAMPAS	Cole Information Services
	YONGHOON CHOI	Cole Information Services
	BRENDAN COWLES	Cole Information Services
	ADEYINKA GBADEBO	Cole Information Services

FINDINGS

Year	Uses	Source
2004	NORA TAYLOR	Cole Information Services
	OAKS MITRA	Cole Information Services
	LORRAINE FRAIN	Cole Information Services
	CLAUDIA FRANCO	Cole Information Services
	FABIO DEAMICIS	Cole Information Services
	BARBARA GLOVER	Cole Information Services
	KA LING	Cole Information Services
	AGNIESZKA PATYKOWSKA	Cole Information Services
	TAJIB MIRZABEKOB	Cole Information Services
	SHAHLA ZADSAR	Cole Information Services
	P PAPAS	Cole Information Services
	JR BARNHART	Cole Information Services
	TITO TOVAR	Cole Information Services
	KRIS DONAHUE	Cole Information Services
	SCOTT LALONDE	Cole Information Services
	DAVID GRIFFITHS	Cole Information Services
	EMILY BURNS	Cole Information Services
	E SAITO	Cole Information Services
	RONALD POMERENKE	Cole Information Services
	JESSE BATTAGLIA	Cole Information Services
	W SCHUCK	Cole Information Services
	SHIRLEY KIM	Cole Information Services
	ANH TON	Cole Information Services
	VICKY DOMITROVICH	Cole Information Services
	HELEN MCDONOGH	Cole Information Services
	K MEDEIROS	Cole Information Services
	GREGORY SUH	Cole Information Services
	NATE KUCERA	Cole Information Services
	JOSH ROSE	Cole Information Services
	AMY CHRISTIAN	Cole Information Services
	PHYLLIS BUSSEY	Cole Information Services
	TATYANA SHISHKINA	Cole Information Services
	LAURA OKEEFE	Cole Information Services
	ANAND KUMAR	Cole Information Services
	HING LEE	Cole Information Services
	TOM CARTER	Cole Information Services
	TINA BIANCHI	Cole Information Services
	ERIC HAYES	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2004	JUSTIN SPRESTER	Cole Information Services
	ROBERT LARSON	Cole Information Services
	PAUL JENNINGS	Cole Information Services
	GARY FRENZEL	Cole Information Services
	MARK HERBERS	Cole Information Services
	NORMA SHEETS	Cole Information Services
2001	PENISTON Nethaniel	Haines Company, Inc.
	PRABHUSunil	Haines Company, Inc.
	PRUITTJennler J	Haines Company, Inc.
	RICEBowen LJr	Haines Company, Inc.
	SAWYER William R	Haines Company, Inc.
	SILLER David	Haines Company, Inc.
	SMYTH Bernard B	Haines Company, Inc.
	SOLEDeeann	Haines Company, Inc.
	SUSANTO Feltx	Haines Company, Inc.
	EL MONTE ARMS ARRIAGAAna	Haines Company, Inc.
	BLACKLaune	Haines Company, Inc.
	BRADLEYKathy	Haines Company, Inc.
	BYRON Alexander	Haines Company, Inc.
	CRAIGGlenn A	Haines Company, Inc.
	CURTISJoseph B	Haines Company, Inc.
	DIAZ Ferrero Jordi	Haines Company, Inc.
	FRENZELGary	Haines Company, Inc.
	FROSTMichael S	Haines Company, Inc.
	FUKINAGAAlex	Haines Company, Inc.
	GBAOEBOAdeyinka	Haines Company, Inc.
	HARRELL Slephen	Haines Company, Inc.
	HOHans H	Haines Company, Inc.
	HOYLE Ronald G	Haines Company, Inc.
	HUTSELL Brian	Haines Company, Inc.
	JACINTH Cory J	Haines Company, Inc.
	KAM Kennelh	Haines Company, Inc.
	KINDER Linda	Haines Company, Inc.
	KRISHNA Rabha	Haines Company, Inc.
	MACKBEEDuslin J	Haines Company, Inc.
	MACOSDAILYCOM	Haines Company, Inc.
	MSGRATHAn Ihony W	Haines Company, Inc.
	PELTONENJanne K	Haines Company, Inc.

FINDINGS

Year	Uses	Source
2001	THEVILLAMONTE	Haines Company, Inc.
	TROUMNeal	Haines Company, Inc.
	TSAI Eunice	Haines Company, Inc.
	VANDERWATERTim	Haines Company, Inc.
1999	DONNA LOWE	Cole Information Services
	ERNEST HO	Cole Information Services
	FABIO DEAMICIS	Cole Information Services
	JAMES CADY	Cole Information Services
	JEFFREY KENDALL	Cole Information Services
	GENE CASTILLO	Cole Information Services
	MASAKI KATO	Cole Information Services
	ROBERT LUPUL	Cole Information Services
	JOAN WITTMANN	Cole Information Services
	HEATHER SCHWENN	Cole Information Services
	MARCO HOLLWEG	Cole Information Services
	K MEDEIROS	Cole Information Services
	TATYANA SHISHKINA	Cole Information Services
	JAMES ROWLES	Cole Information Services
	DANY GHANNAM	Cole Information Services
	MICHAEL CHIU	Cole Information Services
	PAM JONES	Cole Information Services
	Y SHIH	Cole Information Services
	SCOTT LAFLEUR	Cole Information Services
	ROBERT LARSON	Cole Information Services
	BISWAZIT NANDA	Cole Information Services
	RUTH HABINA	Cole Information Services
	PAUL JENNINGS	Cole Information Services
	GARY FRENZEL	Cole Information Services
	BARBARA DICKINSON	Cole Information Services
	STEFANUS JASIN	Cole Information Services
	KATHLEEN HINES	Cole Information Services
	ANNA WORONIECKA	Cole Information Services
	INSUNG JOE	Cole Information Services
	EL MONTE ARMS APARTMENTS	Cole Information Services
	HYUNG KIM	Cole Information Services
	KHIN WIN	Cole Information Services
	THOMAS PAMILLA	Cole Information Services
	R KARAGAH	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
1999	STEVEN CONGER	Cole Information Services
	LORRAINE FRAIN	Cole Information Services
1994	AZIM, R	Cole Information Services
	BROWN, NOEL E	Cole Information Services
	HAYES, SMITH	Cole Information Services
	SCOTT, PAUL H	Cole Information Services
	FRY, ROY	Cole Information Services
	MYERS, N	Cole Information Services
	BANKS, MARK	Cole Information Services
	FORDERER, THOMAS J	Cole Information Services
	LOCHMANN, ADAM C	Cole Information Services
	KIM, TAE Y	Cole Information Services
	NATIONAL SPENDING & CREDIT	Cole Information Services
	EL MONTE ARMS APARTMENTS	Cole Information Services
	IMANISHI, MASAYUK	Cole Information Services
1986	Allen G L	Pacific Bell
	Anzalone Vincent	Pacific Bell
	Arnold P	Pacific Bell
	Belle Henry M	Pacific Bell
	Benson Wm	Pacific Bell
	Brodersen Henry K	Pacific Bell
	Charles Carolyn	Pacific Bell
	Davies Richard	Pacific Bell
	Davis Ron	Pacific Bell
	Dolph J Robert	Pacific Bell
	Garin Vladimir	Pacific Bell
	Kearney R L	Pacific Bell
	Killlan Joe A	Pacific Bell
	Ktlliany D	Pacific Bell
	Like L	Pacific Bell
	LIKE L	Pacific Bell
	KTLLIANY D	Pacific Bell
	Mackay E D	Pacific Bell
	Manley John P	Pacific Bell
	Pankonen D G	Pacific Bell
	Renner KM	Pacific Bell
	Secord N	Pacific Bell
	Yesh L A	Pacific Bell

FINDINGS

Year	Uses	Source
1986	ALLEN G L	Pacific Bell
	ANZALONE VINCENT	Pacific Bell
	ARNOLD P	Pacific Bell
	BELLE HENRY M	Pacific Bell
	BENSON WM	Pacific Bell
	BRODERSEN HENRY K	Pacific Bell
	CHARLES CAROLYN	Pacific Bell
	DAVIES RICHARD	Pacific Bell
	DAVIS RON	Pacific Bell
	DOLPH J ROBERT	Pacific Bell
	GARIN VLADIMIR	Pacific Bell
	KEARNEY R L	Pacific Bell
	KIRBY E	Pacific Bell
	MACKAY E D	Pacific Bell
	MANLEY JOHN P	Pacific Bell
	PANKONEN D G	Pacific Bell
	PERLOV ILYA	Pacific Bell
	RENNER KM	Pacific Bell
	SECORD N	Pacific Bell
	YESH L A	Pacific Bell
1982	Brodersen Henry K	Pacific Telephone
	Charles Carolyn	Pacific Telephone
	Cullenl Jas A	Pacific Telephone
	De Meules T	Pacific Telephone
	El Mionte Arms Apts	Pacific Telephone
	Fleury Dennis	Pacific Telephone
	Garin Vladimir	Pacific Telephone
	Gurevich Boris	Pacific Telephone
	Holdsworth J	Pacific Telephone
	Kearney RL	Pacific Telephone
	Kil liany D	Pacific Telephone
	Kirby L E	Pacific Telephone
	Like L	Pacific Telephone
	Lorish T	Pacific Telephone
	Mc Hugh G	Pacific Telephone
	Roe David M	Pacific Telephone
	Rush Brenda	Pacific Telephone
	Secord N	Pacific Telephone

FINDINGS

Year	Uses	Source
1982	Southland Russ G	Pacific Telephone
	Stevenson M	Pacific Telephone
	Uribes Ray	Pacific Telephone
	Perchla B	Pacific Telephone
1975	Bertolucci T	Pacific Telephone
	Bonnet Richard D Jr	Pacific Telephone
	Brodersen Henry K	Pacific Telephone
	Costa Sandy	Pacific Telephone
	Crego Richard R	Pacific Telephone
	De Busk N	Pacific Telephone
	Dellaiagglore Gllbert R	Pacific Telephone
	Donaldson C Mrs	Pacific Telephone
	Douglas Dean	Pacific Telephone
	Drewry Ann	Pacific Telephone
	Fox Michael Tone	Pacific Telephone
	Fox Peter C	Pacific Telephone
	Good W D	Pacific Telephone
	Gould E J	Pacific Telephone
	Hensley Jake P	Pacific Telephone
	Kirby L E	Pacific Telephone
	Lagmay Dionisia	Pacific Telephone
	Lauritzen Thor	Pacific Telephone
	Lawler D M	Pacific Telephone
	Levy Larry S	Pacific Telephone
	Partyka J	Pacific Telephone
	READ SEE ALSO REED REID	Pacific Telephone
	Read Scott	Pacific Telephone
	Rose Doris M	Pacific Telephone
	Schowalter Gil	Pacific Telephone
	Sccord N	Pacific Telephone
	Sewell H	Pacific Telephone
	Shiflet Hazel	Pacific Telephone
	Sparkman Erin	Pacific Telephone
	Stauber D A	Pacific Telephone
	Thurston H H Sr	Pacific Telephone
	Tyler A	Pacific Telephone
	Walen E C	Pacific Telephone
	Weinmann J C	Pacific Telephone

FINDINGS

Year	Uses	Source
1975	Yesh L A	Pacific Telephone
1968	EL MONTE ARMS APARTMENTS	R. L. Polk Co.
1962	BOIVIN KATHLEEN	R. L. Polk & Co.
	EL MONTE ARMS APARTMENTS EARL F FIELDS MGR	R. L. Polk & Co.
	JALONE MARY	R. L. Polk & Co.

1049 EL MONTE AVE

Year	Uses	Source
2017	BAGEL STREET CAFE	Cole Information Services
	LUIS BAIL BONDS	Cole Information Services
	ENKI	Cole Information Services
	BLUE BIRD CLEANERS	Cole Information Services
	JEANNIE CHOI	Cole Information Services
	NEST BEDDING	Cole Information Services
	MARES GARAGE DOORS & GATES	Cole Information Services
2014	ENKI	Cole Information Services
	BLUE BIRD CLEANERS	Cole Information Services
	BAGEL STREET CAFE	Cole Information Services
	PATRICIA TAKATA	Cole Information Services
	NEST BEDDING	Cole Information Services
2009	BLUE BIRD CLEANERS & LAUNDRY	Cole Information Services
	BAGEL STREET CAFE	Cole Information Services
	NOAHS BAGELS	Cole Information Services
	DEBRA LANGLEY	Cole Information Services
2004	CELLULAR ONE AUTHORIZED DEALER	Cole Information Services
	PACE YOURSELF FITNESS STUDIO	Cole Information Services
	NEW YORK NAOHS BAGELS	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
2001	EL MONTE AV 94040 C	Haines Company, Inc.
	DEALER NOAHS BAGELS	Haines Company, Inc.
	CELLULARONE	Haines Company, Inc.
	CELLULAR CNNCTN	Haines Company, Inc.
	BLUEBIRDCLEANERS	Haines Company, Inc.
1999	BLUE BIRD CLEANERS	Cole Information Services
	CELLULAR ONE AUTHORIZED DEALER CELLULAR CONNECTION	Cole Information Services
	CELLULAR CONNECTION INCORPORATED	Cole Information Services
	NOAHS BAGELS	Cole Information Services

FINDINGS

Year	Uses	Source
1999	DEBRA LANGLEY	Cole Information Services

1050 EL MONTE AVE

Year	Uses	Source
2001	ROURKELinda STARTECH	Haines Company, Inc.
1999	STARTECH ELECTRONICS INCORPORATED	Cole Information Services
1986	BESS MOORE NICOLAISEN INS AGENCY	Pacific Bell
	MVOORE NICOLAISEN BESS INS AGENCY	Pacific Bell
	NICOLAISEN BESS MOORE INS AGENCY	Pacific Bell
	Bess Moore Nicolaisen Ins Agency	Pacific Bell
	MVoore Nicolaisen Bess Ins Agency	Pacific Bell
	Nicolaisen Bess Moore Ins Agency	Pacific Bell
1982	Moore Nicolaisen Bess Ins Agency	Pacific Telephone
	Nicolaisen Bess Moore Ins Agency	Pacific Telephone
1975	Bess Ins Agency	Pacific Telephone
	SOMMERS INSURANCE AGENCY	Pacific Telephone
1968	BESS HERBERT F INS ACT	R. L. Polk Co.
	CASSIDY JOHN D REAL EST	R. L. Polk Co.
1962	BESS HERBERT F INS	R. L. Polk & Co.
	BESS HERBERT F INS	R. L. Polk & Co.

1057 EL MONTE AVE

Year	Uses	Source
2017	FIRST FOCUS LEARNING	Cole Information Services
	GREAT CARE DENTAL	Cole Information Services
	CURTIS CAHILL INS AGT	Cole Information Services
	DDS CHEN HEATHER	Cole Information Services
	JANETTE BLAND MD	Cole Information Services
2014	GREAT CARE DENTAL	Cole Information Services
	BLAND JANETTE MD	Cole Information Services
	DDS CHEN HEATHER	Cole Information Services
2009	STATE FARM INSURANCE	Cole Information Services
	CUNNINGHAM JAMES T DDS	Cole Information Services
2004	JAMES T CUNNINGHAM	Cole Information Services
	BERMAN CHERYL DR	Cole Information Services
	PENINSULA THERAPY CONSULTANTS	Cole Information Services
	CASSARA JOSEPH M DDS	Cole Information Services

FINDINGS

Year	Uses	Source
2001	DOS CUNNINGHAM JAS	Haines Company, Inc.
	GLASSNANCYMFT 650 691 N 774	Haines Company, Inc.
	NEVAREZ HORACE 8 L	Haines Company, Inc.
	OLSONKIMBERLY LMFCC 6 SATE FARM INS	Haines Company, Inc.
	SALES OFFICE	Haines Company, Inc.
	BERMANCHERYLDR E	Haines Company, Inc.
	CASSARA JOSEPH M	Haines Company, Inc.
1999	STAT FRM INS COMPANIES CONTD SALES OFFICES	Cole Information Services
	NEVAREZ HORACEL INS AGT	Cole Information Services
	CASSARA JOSEPH M DDS	Cole Information Services
	CUNNINGHAM JAMES T DDS	Cole Information Services
	WALTERS NANCY MS LMFC	Cole Information Services
	BERMAN CHERYL DR	Cole Information Services
1994	STATE FARM INSURANCE	Cole Information Services
	NANCY SAPERSTEIN	Cole Information Services
	LEONARD C FU DDS	Cole Information Services
	EL MONTE COUNSELING ASSOC	Cole Information Services
	MARIA AGANON FU DDS	Cole Information Services
	EL MONTE MEDICAL DENTAL	Cole Information Services
	ALEXANDRA GOTSCH	Cole Information Services
	NANCY WALTERS	Cole Information Services
	LARRY COMPAGNONI	Cole Information Services
	ERLE R KIRK PHD	Cole Information Services
	MARY ELLEN CULVER	Cole Information Services
	MARILYN SPONZA SWARTZ	Cole Information Services
1991	WALTERS NANCY MS LMFC	Pacific Telephone
	A STATE FARM INSURANCE COMPANIES	Pacific Telephone
	B FU LEONARD C DMD	Pacific Telephone
	C CUNNINGHAM JAMES T	Pacific Telephone
	D KIRK ERLE R PHD	Pacific Telephone
1986	Hook Lynne ONeill Ma Marriage Family & Child Consltng	Pacific Bell
	Walters Nancy MSLMFC	Pacific Bell
	AGANON FU MARIA DDS	Pacific Bell
	Billings Andrew Ph D	Pacific Bell
	Buelow Janet MS LMFCC	Pacific Bell
	Cunningham Jas T DOS	Pacific Bell

FINDINGS

Year	Uses	Source
1986	FU LEONARD C DMD	Pacific Bell
	Pither Bruce F Ph D	Pacific Bell
	STATE	Pacific Bell
	Mountain View	Pacific Bell
	STATE	Pacific Bell
	Mountain View	Pacific Bell
	AGANON FU MARIA DDS	Pacific Bell
	BILLINGS ANDREW PH D	Pacific Bell
	BUELOW JANET MS LMFCC	Pacific Bell
	CUNNINGHAM JAS T DOS	Pacific Bell
	FU LEONARD C DMD	Pacific Bell
	HOOK LYNNE ONEILL MA MARRIAGE FAMILY & CHILD CONSLTNG	Pacific Bell
	PITHER BRUCE F PH D	Pacific Bell
	STATE FARM INSURANCE COMPANIES	Pacific Bell
	SALES OFFICES	Pacific Bell
	WALTERS NANCY MSLMFC	Pacific Bell
1982	Fu Leonard C DMD	Pacific Telephone
	Pither Bruce F Ph D	Pacific Telephone
	State Farm Insurance Companies Agent Offices	Pacific Telephone
	Mountain View	Pacific Telephone
1975	Logan G Irving Dr	Pacific Telephone
	Sempervirens Fund	Pacific Telephone
	Tarqulnid Amadeus MSW licnsed cinici social wrkr	Pacific Telephone
1968	CARNEY WM R PHYS	R. L. Polk Co.
	CUNNINGHAM JAMES T DENTIST	R. L. Polk Co.
	LINDELOF ROBT D DENTIST	R. L. Polk Co.
	OLSEN DONALD W DENTIST	R. L. Polk Co.
1962	BROWN WENDELL E PHYS	R. L. Polk & Co.
	CARNEY WM R PHYS	R. L. Polk & Co.
	CARNEY WM R PHYS	R. L. Polk & Co.
	CUNNINGHAM JIS T (DEE A) DENTIST	R. L. Polk & Co.
	OLSEN DONALD W DENTIST	R. L. Polk & Co.
	OLSEN DONALD W DENTIST	R. L. Polk & Co.
	SENTER WIALTER P PHYS	R. L. Polk & Co.
1957	SENTER WALTER P MD	Pacific Telephone

FINDINGS

1059 EL MONTE AVE

Year	Uses	Source
2017	FIRST FOCUS LEARNING CENTERS	Cole Information Services
	SHARON PEREIRA MFT	Cole Information Services
	MONIQUE KANE MFT	Cole Information Services
	FIRST FOCUS LEARNING CENTERS	Cole Information Services
	SHARON PEREIRA MFT	Cole Information Services
	MONIQUE KANE MFT	Cole Information Services
2014	PEREIRA SHARON MFT	Cole Information Services
	1ST FOCUS LEARNING CENTERS	Cole Information Services
	KANE MONIQUE MFT	Cole Information Services
	KALEHZAN MICHELLE PHD	Cole Information Services
	PEREIRA SHARON MFT	Cole Information Services
	1ST FOCUS LEARNING CENTERS	Cole Information Services
	KANE MONIQUE MFT	Cole Information Services
	KALEHZAN MICHELLE PHD	Cole Information Services
2009	VERANT DENTAL LABORATORY INC	Cole Information Services
	MIO YAMASHITA M A ATR MFT	Cole Information Services
	JUDITH S DUQUE	Cole Information Services
	KANE MONIQUE MFT	Cole Information Services
	VERANT DENTAL LABORATORY INC	Cole Information Services
	MIO YAMASHITA M A ATR MFT	Cole Information Services
	JUDITH S DUQUE	Cole Information Services
	KANE MONIQUE MFT	Cole Information Services
2004	HANDLEY ISAKSEN ALICE PHD	Cole Information Services
	JUDITH S DUQUE	Cole Information Services
	VERANT DENTAL LAB INC	Cole Information Services
	SHARON PEREIRA	Cole Information Services
	JUDITH DUQUE	Cole Information Services
	PATRICIA FLECK	Cole Information Services
	HANDLEY ISAKSEN ALICE PHD	Cole Information Services
	JUDITH S DUQUE	Cole Information Services
	VERANT DENTAL LAB INC	Cole Information Services
	SHARON PEREIRA	Cole Information Services
	JUDITH DUQUE	Cole Information Services
	PATRICIA FLECK	Cole Information Services
2001	DDQUEJUDITHSLMFT	Haines Company, Inc.
	KANEMONIOUEMFCC MACKEYBETTYMFT	Haines Company, Inc.
	PEREIRASHARON 65089 M	Haines Company, Inc.

FINDINGS

Year	Uses	Source
2001	MFCC VERANT DENTAL LAB	Haines Company, Inc.
1999	OCCUPANT UNKNOWN	Cole Information Services
	KANE MONIQUE MFCC	Cole Information Services
	MCCREA JACK CADC	Cole Information Services
	DUQUE JUDITH S LMFCC	Cole Information Services
	FALGE ROGER LMFC	Cole Information Services
	VERANT DENTAL LABORATORY	Cole Information Services
	PEREIRA SHARON MFCC	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
	KANE MONIQUE MFCC	Cole Information Services
	MCCREA JACK CADC	Cole Information Services
	DUQUE JUDITH S LMFCC	Cole Information Services
	FALGE ROGER LMFC	Cole Information Services
	VERANT DENTAL LABORATORY	Cole Information Services
	PEREIRA SHARON MFCC	Cole Information Services
1994	VERANT DENTAL LAB	Cole Information Services
	MONIQUE KANE	Cole Information Services
	JACK MC CREA	Cole Information Services
	VERANT DENTAL LAB	Cole Information Services
	MONIQUE KANE	Cole Information Services
	JACK MC CREA	Cole Information Services
1991	A VERANT DENTAL LAB	Pacific Telephone
	B INSTITUTE FOR INTERPERSONAL RELATIONS	Pacific Telephone
1986	Silhouette Dental Studio	Pacific Bell
	Verant Dental Lab	Pacific Bell
	Mountain View Ofe	Pacific Bell
	Milburn John O DII MD	Pacific Bell
	Bonar Barnet E MD	Pacific Bell
	Mountain View Office	Pacific Bell
	BONAR BARNET E MD	Pacific Bell
	MOUNTAIN VIEW OFE	Pacific Bell
	SILHOUETTE DENTAL STUDIO	Pacific Bell
	VERANT DENTAL LAB	Pacific Bell
1982	Milburn John D III MD	Pacific Telephone
	Mountain View Ofc	Pacific Telephone
	Verant Dental Lab	Pacific Telephone
	Mountain View Office	Pacific Telephone
	Bonar Barnet E MD	Pacific Telephone

FINDINGS

Year	Uses	Source
1975	Bonar Barnet E MD	Pacific Telephone
	Mountain View Office	Pacific Telephone
	El Monte Medical Lab	Pacific Telephone
1968	BONAR BARNET E PHYS	R. L. Polk Co.
	LOGAN G IRVING DENTIST	R. L. Polk Co.
1962	BONAR BARNET E PHYS	R. L. Polk & Co.
	MEREDITH RICHD S PHYS	R. L. Polk & Co.
1957	MC GHIE & JONES RPT S	Pacific Telephone
	MC GHIE MARLEN D MC GHIE & JONES RPT S	Pacific Telephone

1061 EL MONTE AVE

Year	Uses	Source
2017	GEETA PIROUZNIA DDS	Cole Information Services
	MOUNTAIN VIEW SMILES	Cole Information Services
	SAPERSTEIN NANCY LMFT	Cole Information Services
	LAWRENCE COMPAGNONI MA	Cole Information Services
2014	PIROUZNIA GEETA DDS	Cole Information Services
	SAVIDES ANITA LCSW	Cole Information Services
	COMPAGNONI LAWRENCE MA	Cole Information Services
	MILES GARY PHD	Cole Information Services
	SAPERSTEIN NANCY LMFT	Cole Information Services
	GEETA PIROUZNIA	Cole Information Services
	LAWRENCE COMPAGNONI	Cole Information Services
	GARY MILES	Cole Information Services
2009	PIROUZNIA GEETA DDS	Cole Information Services
	HANDLEY ISAKSEN ALICE PHD	Cole Information Services
	COMPAGNONI LAWRENCE MA	Cole Information Services
	NANCY SAPERSTEIN LMFT	Cole Information Services
	BRUCE F PITHER PHD	Cole Information Services
	ABOUDARHAM JEAN FREDERIC	Cole Information Services
	ANITA SAVIDES LCSW	Cole Information Services
	CHARLES XUEREB MD	Cole Information Services
2004	DEBRA GOR	Cole Information Services
	SUSAN BORKIN	Cole Information Services
	LUCANNA M GREY	Cole Information Services
	COMPAGNONI LAWRENCE	Cole Information Services
	CHARLES XUEREB MD	Cole Information Services
	CLIFFORD RUTH PHD	Cole Information Services

FINDINGS

Year	Uses	Source
2004	GORDON DEBRA E PHD	Cole Information Services
	DR GEETA PIROUZNIA DDS	Cole Information Services
	CTR FOR PERSONAL GROWTH	Cole Information Services
	NANCY SAPERSTEIN	Cole Information Services
	CHARLES XUEREB	Cole Information Services
	LAWRENCE COMPAGNONI	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
2001	XUEREB CHARLES MD	Haines Company, Inc.
	THOMPSON JAS A DR	Haines Company, Inc.
	LMFCC SAVIDES ANITA LCSW	Haines Company, Inc.
	SAPERSTEIN NANCY	Haines Company, Inc.
	GREYLUCANNAMFCC 650 961 486 N PIROUZNIA GEETA D 0 S	Haines Company, Inc.
	LAWRENCE MA GORDON DEBRA E PHD	Haines Company, Inc.
	COMPAGNONI	Haines Company, Inc.
1999	OSGOOD CAROL LCSW	Cole Information Services
	GORDON DEBRA E PHD PSYCLGST	Cole Information Services
	COMPAGNONI LAWRENCE MA	Cole Information Services
	XUEREB CHARLES MD PSYCHIATRY	Cole Information Services
	SAVIDES ANITA LCSW	Cole Information Services
	BORRELLI SANDRA MFCC	Cole Information Services
	SPONZA MARILYN LMFCC	Cole Information Services
	THOMPSON JAMES ALDEN DR DNT	Cole Information Services
	PIROUZNIA GEETA DDS	Cole Information Services
1994	JAMES A THOMPSON DDS	Cole Information Services
	NANCY SAPERSTEIN	Cole Information Services
	CHARLES XUEREB MD	Cole Information Services
	ANITA SAVIDES	Cole Information Services
	MARY ELLEN CULVER	Cole Information Services
	MARILYN SPONZA	Cole Information Services
	LAWRENCE COMPAGNONI	Cole Information Services
	CAROL OSGOOD	Cole Information Services
	DEBRA GORDON PHD	Cole Information Services
1991	THOMPSON JAS ALDEN DR	Pacific Telephone
	A OSGOOD CAROL LCSW	Pacific Telephone
	B XUEREB CHARLES MD	Pacific Telephone
	B COMPAGNONI LAWRENCE MA	Pacific Telephone
	B SPONZA MARILYN LMFCC	Pacific Telephone

FINDINGS

Year	Uses	Source
1991	SAVIDES ANITA LCSW	Pacific Telephone
	SKLAR ALICE MFCC	Pacific Telephone
1986	EL CAMINO FAMILY	Pacific Bell
	Brown Wendell E MD Inc	Pacific Bell
	Savides Anita MSW	Pacific Bell
	Wishard Betty LCSW	Pacific Bell
	BROWN WENDELL E MD INC	Pacific Bell
	EL CAMINO FAMILY	Pacific Bell
	SAVIDES ANITA MSW	Pacific Bell
	WISHARD BETTY LCSW	Pacific Bell
1982	Savides Anita MSW	Pacific Telephone
	Wishard Betty LCSW	Pacific Telephone
	Brown Wendell E MD Inc	Pacific Telephone
1975	Brown Wendell E Dr Inc phy & sur	Pacific Telephone
	Das Chander P MD	Pacific Telephone
1968	BROWN WENDELL E PHYS	R. L. Polk Co.
	FURUKI MINORU ACCT	R. L. Polk Co.
1957	PRIEUR ARTHUR A DDS	Pacific Telephone

1065 EL MONTE AVE

Year	Uses	Source
1962	FURUKI MINORU PUB ACCT	R. L. Polk & Co.

1066 EL MONTE AVE

Year	Uses	Source
2014	TARA CARTER	Cole Information Services
2009	ROGER MORIMOTO	Cole Information Services
2004	MICHAEL CHOY	Cole Information Services
2001	CHOY Michael	Haines Company, Inc.
1999	ROGER MORIMOTO	Cole Information Services
1994	ALLENBY, V	Cole Information Services
1991	Allenby V	Pacific Telephone
1986	ALLENBY V	Pacific Bell
	Allenby V	Pacific Bell
1982	Allenby V	Pacific Telephone
1975	Allenby V	Pacific Telephone
1968	NO RETURN	R. L. Polk Co.
1962	HOLT JAS (LEONA) EMP FORD MTR CO	R. L. Polk & Co.
	CUNNINGHAM ALEX	R. L. Polk & Co.

FINDINGS

1075 EL MONTE AVE

Year	Uses	Source
2017	ST PAUL LUTHERAN CHURCH	Cole Information Services
	ST PAUL LUTHERAN CHURCH	Cole Information Services
2014	ST PAUL LUTHERAN CHURCH	Cole Information Services
	ST PAUL LUTHERAN CHURCH	Cole Information Services
2009	SAINT PAUL LUTHERAN CHILD DEV CENTER	Cole Information Services
	SAINT PAUL LUTHERAN CHILD DEV CENTER	Cole Information Services
2001	CHLD DVLP CTR	Haines Company, Inc.
	ST PAUL LUTHERAN	Haines Company, Inc.
	ST PAUL LUTHERAN CH	Haines Company, Inc.
	LUTHRNCHSTPAUL	Haines Company, Inc.
1999	LUTHERAN CHURCH ST PAUL MISSOURI SYNOD	Cole Information Services
	ST PAUL LUTHERAN CHILD DEVELOPMENT CENTER	Cole Information Services
	LUTHERAN CHURCH ST PAUL MISSOURI SYNOD	Cole Information Services
	ST PAUL LUTHERAN CHILD DEVELOPMENT CENTER	Cole Information Services
1994	DBS MANAGEMENT	Cole Information Services
	ST PAUL LUTHERAN CHILD DEV CTR	Cole Information Services
	ST PAUL LUTHERAN CHURCH	Cole Information Services
	DBS MANAGEMENT	Cole Information Services
	ST PAUL LUTHERAN CHILD DEV CTR	Cole Information Services
	ST PAUL LUTHERAN CHURCH	Cole Information Services
1991	ST PAUL LUTHERAN CHILD DEVELOPMENT CENTER	Pacific Telephone
	ST PAUL LUTHERAN CHURCH MISSOURI SYNOD	Pacific Telephone
1986	Mountain View Parent Nursery School	Pacific Bell
	Lutheran Church St Paul Missouri Synod	Pacific Bell
	LUTHERAN CHURCH ST PAUL MISSOURI SYNOD	Pacific Bell
	MOUNTAIN VIEW PARENT NURSERY SCHOOL	Pacific Bell
1982	ST NICHOLAS CATHOLIC CHURCH	Pacific Telephone
	St Paul Lutheran Church Missouri Synod	Pacific Telephone
	Lutheran Church St Paul Missouri Synod	Pacific Telephone
1975	St Paul Lutheran Church Missouri Synod	Pacific Telephone
	Lutheran Church St Paul Missouri Synod	Pacific Telephone

Year	Uses	Source
1975	Mountain View Parent Nursery School	Pacific Telephone
	ST PAUL INSURANCE AGENCY	Pacific Telephone
1968	SAINT PAUL LUTHERAN CHURCH	R. L. Polk Co.
1957	FISCHER RALPH REV ST PAUL LUTHERAN CHRCH	Pacific Telephone
	ST PAUL LUTHERAN CHURCH MISSOURI SYNOD	Pacific Telephone

1076 EL MONTE AVE

Year	Uses	Source
2014	SHALOM TSUR	Cole Information Services
2009	SHALOM TSUR	Cole Information Services
2004	SHALOM TSUR	Cole Information Services
2001	TSUR Shalom	Haines Company, Inc.
	0 TSURNilza	Haines Company, Inc.
	TSURBNilza	Haines Company, Inc.
	TSUR Shalom	Haines Company, Inc.
1999	SHALOM TSUR	Cole Information Services

1080 EL MONTE AVE

Year	Uses	Source
1999	OCCUPANT UNKNOWN	Cole Information Services

1095 EL MONTE AVE

Year	Uses	Source
2001	0 MAWilson	Haines Company, Inc.
1999	OCCUPANT UNKNOWN	Cole Information Services
1994	KLEAR KOVER	Cole Information Services
1991	KLEAR KOVER	Pacific Telephone
1986	KLEAR KOVER	Pacific Bell
	Klear Kover	Pacific Bell
1982	KLf AR KOVER	Pacific Telephone
1975	Klear Kover	Pacific Telephone
1968	MUNFORD ROY	R. L. Polk Co.

El Monte Avenue

1059 El Monte Avenue

Year	Uses	Source
2001	DDQUEJUDITHSLMFT	Haines Company, Inc.

FINDINGS

Year	Uses	Source
2001	KANEMONIOUEMFCC MACKEYBETTYMFT	Haines Company, Inc.
	PEREIRASHARON 65089 M	Haines Company, Inc.
	MFCC VERANT DENTAL LAB	Haines Company, Inc.
1991	A VERANT DENTAL LAB	Pacific Telephone
	B INSTITUTE FOR INTERPERSONAL RELATIONS	Pacific Telephone
1986	Bonar Barnet E MD	Pacific Bell
	Mountain View Office	Pacific Bell
	Milburn John O DII MD	Pacific Bell
	Mountain View Ofe	Pacific Bell
	Verant Dental Lab	Pacific Bell
	BONAR BARNET E MD	Pacific Bell
	MOUNTAIN VIEW OFE	Pacific Bell
	SILHOUETTE DENTAL STUDIO	Pacific Bell
	VERANT DENTAL LAB	Pacific Bell
	Silhouette Dental Studio	Pacific Bell
1982	Milburn John D III MD	Pacific Telephone
	Mountain View Ofc	Pacific Telephone
	Verant Dental Lab	Pacific Telephone
	Mountain View Office	Pacific Telephone
	Bonar Barnet E MD	Pacific Telephone
1975	Bonar Barnet E MD	Pacific Telephone
	Mountain View Office	Pacific Telephone
	El Monte Medical Lab	Pacific Telephone
1968	BONAR BARNET E PHYS	R. L. Polk Co.
	LOGAN G IRVING DENTIST	R. L. Polk Co.
1962	BONAR BARNET E PHYS	R. L. Polk & Co.
	MEREDITH RICHD S PHYS	R. L. Polk & Co.
1957	MC GHIE & JONES RPT S	Pacific Telephone
	MC GHIE MARLEN D MC GHIE & JONES RPT S	Pacific Telephone
	JENSEN WAITER N MDO	Pacific Telephone

1075 El Monte Avenue

Year	Uses	Source
2001	LUTHRNCHSTPAUL	Haines Company, Inc.
	ST PAUL LUTHERAN CH	Haines Company, Inc.
	ST PAUL LUTHERAN	Haines Company, Inc.
	CHLD DVLP CTR	Haines Company, Inc.

Year	Uses	Source
1991	ST PAUL LUTHERAN CHURCH MISSOURI SYNOD	Pacific Telephone
	ST PAUL LUTHERAN CHILD DEVELOPMENT CENTER	Pacific Telephone
1986	Lutheran Church St Paul Missouri Synod	Pacific Bell
	Mountain View Parent Nursery School	Pacific Bell
	LUTHERAN CHURCH ST PAUL MISSOURI SYNOD	Pacific Bell
	MOUNTAIN VIEW PARENT NURSERY SCHOOL	Pacific Bell
1982	Lutheran Church St Paul Missouri Synod	Pacific Telephone
	St Paul Lutheran Church Missouri Synod	Pacific Telephone
	ST NICHOLAS CATHOLIC CHURCH	Pacific Telephone
	Mountain View Parent Nursery School	Pacific Telephone
1975	Lutheran Church St Paul Missouri Synod	Pacific Telephone
	Mountain View Parent Nursery School	Pacific Telephone
	St Paul Lutheran Church Missouri Synod	Pacific Telephone
	ST PAUL INSURANCE AGENCY	Pacific Telephone
1968	SAINT PAUL LUTHERAN CHURCH	R. L. Polk Co.
1957	FISCHER RALPH REV ST PAUL LUTHERAN CHRCH	Pacific Telephone
	ST PAUL LUTHERAN CHURCH MISSOURI SYNOD	Pacific Telephone

EL MONTE CT

1030 EL MONTE CT

Year	Uses	Source
1986	MULLER ERIC	Pacific Bell

1057 EL MONTE CT

Year	Uses	Source
1957	WHEELER C C DR	Pacific Telephone

EL MONTE WAY

1030 EL MONTE WAY

Year	Uses	Source
1986	Kirby E	Pacific Bell
	Muller Eric	Pacific Bell
1982	Mc Donough Michael	Pacific Telephone
1975	Jones Jas R	Pacific Telephone

Year	Uses	Source
1975	Reed Burke B	Pacific Telephone

1057 EL MONTE WAY

Year	Uses	Source
1982	Kirk Erie R Ph D marriage & family counsir	Pacific Telephone
	NEVAREZ HORACE L ins agt	Pacific Telephone

1075 EL MONTE WAY

Year	Uses	Source
1982	Mountain View Parent Nursery School	Pacific Telephone

HIOLLINGSWORTIH DR

1610 HIOLLINGSWORTIH DR

Year	Uses	Source
1982	Collins O M	Pacific Telephone

HOILINGSWURTH DR

1571 HOILINGSWURTH DR

Year	Uses	Source
1982	Young Everett K	Pacific Telephone

HOL INASWORTH DR

1561 HOL INASWORTH DR

Year	Uses	Source
1986	Hoffacker Ron & Cindy	Pacific Bell

HOLINASWORTH DR

1561 HOLINASWORTH DR

Year	Uses	Source
1986	HOFFACKER RON & CINDY	Pacific Bell

HOLLINGSWORTH DR

1519 HOLLINGSWORTH DR

Year	Uses	Source
2017	KEVIN BEEDON	Cole Information Services
2014	OCCUPANT UNKNOWN	Cole Information Services

FINDINGS

Year	Uses	Source
2009	KEVIN BEEDON	Cole Information Services
2004	KEVIN BEEDON	Cole Information Services
2001	SODNERTDaryl	Haines Company, Inc.
1999	KEVIN BEEDON	Cole Information Services
1991	Fritz Paul L	Pacific Telephone
	Fritz Paul & Kathy	Pacific Telephone
1986	FRITZ PAUL L	Pacific Bell
	Fritz Paul L	Pacific Bell
	Fritz Paul & Kathy	Pacific Bell
	FRITZ PAUL & KATHY	Pacific Bell
1968	FRITZ HERBERT C	R. L. Polk Co.
1957	FRITZ HERBERT C	Pacific Telephone

1524 HOLLINGSWORTH DR

Year	Uses	Source
2017	PATRICK SHEEHAN	Cole Information Services
2014	PATRICK SHEEHAN	Cole Information Services
2009	JOHN SHEEHAN	Cole Information Services
2004	JOHN SHEEHAN	Cole Information Services
2001	SSEEHANJohn	Haines Company, Inc.
1999	JOHN SHEEHAN	Cole Information Services
1982	Kundmueller Joseph	Pacific Telephone
1968	BELL FRED L	R. L. Polk Co.

1533 HOLLINGSWORTH DR

Year	Uses	Source
2017	GREG ROMBACH	Cole Information Services
2014	GREG ROMBACH	Cole Information Services
2009	GREG ROMBACH	Cole Information Services
2004	MYRNA ROMBACH	Cole Information Services
2001	ROMBACHMHS	Haines Company, Inc.
1999	GREG ROMBACH	Cole Information Services
1994	ROMBACH, M H	Cole Information Services
1986	Rombach M H	Pacific Bell
	ROMBACH M H	Pacific Bell
1982	Rombach M H	Pacific Telephone

FINDINGS

1536 HOLLINGSWORTH DR

Year	Uses	Source
2017	RUTH VRANAS	Cole Information Services
2014	RUTH VRANAS	Cole Information Services
2009	RUTH VRANAS	Cole Information Services
2004	GLENN VRANAS	Cole Information Services
2001	SVRANASRulh	Haines Company, Inc.
1999	RUTH VRANAS	Cole Information Services
1994	GARCIA, ROD	Cole Information Services
1991	Garcia Rod	Pacific Telephone
1986	Garcia Rod	Pacific Bell
	GARCIA ROD	Pacific Bell
1982	Garcia Rod	Pacific Telephone
1975	Garcia Rod	Pacific Telephone
1968	GARCIA ROD Y	R. L. Polk Co.
1957	WILLIAMS HAROLD	Pacific Telephone

1541 HOLLINGSWORTH DR

Year	Uses	Source
2017	SMITA SHUKLA	Cole Information Services
2014	SMITA SHUKLA	Cole Information Services
2009	SMITA SITARAM	Cole Information Services
2004	SMITA SITARAM	Cole Information Services
2001	SITARAMM	Haines Company, Inc.
	SITARAMM	Haines Company, Inc.
1999	SMITA SITARAM	Cole Information Services
1994	CERVANTES, EDWIN	Cole Information Services
	GORDON, KATHRYN	Cole Information Services
1991	Gordon Kathryn	Pacific Telephone
1986	Bostwick Russell E	Pacific Bell
	BOSTWICK RUSSELL E	Pacific Bell
1982	Bostwick Russell E	Pacific Telephone
1968	BOSTWICK RUSSELL	R. L. Polk Co.
1962	BOSTWICK RUSSELL (IRENE) ELEC SUPVR KANE ENG CO	R. L. Polk & Co.
1957	BOSTWICK RUSSELL E	Pacific Telephone

1548 HOLLINGSWORTH DR

Year	Uses	Source
2017	WILLIAM COY	Cole Information Services

FINDINGS

Year	Uses	Source
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	WILLIAM COY	Cole Information Services
2004	WILLIAM COY	Cole Information Services
2001	COYWiltram	Haines Company, Inc.
1999	WILLIAM COY	Cole Information Services
1986	MISSIRNIN RONALD	Pacific Bell
	Missirnin Ronald	Pacific Bell
1982	Boberg Richard	Pacific Telephone
1975	Johnson Ellyn	Pacific Telephone
1968	JOHNSON ELLYN MRS	R. L. Polk Co.
1962	JOHNSON LEROY D (ELLYN) GUARD	R. L. Polk & Co.
1957	JOHNSON LE ROY D	Pacific Telephone
	BARNETT WALLACE B	Pacific Telephone

1555 HOLLINGSWORTH DR

Year	Uses	Source
2017	LIH YIIN	Cole Information Services
2014	YU CHENGPIN	Cole Information Services
2009	YU CHENGPIN	Cole Information Services
2004	YU CHENGPIN	Cole Information Services
2001	SCOHN George 3D	Haines Company, Inc.
1999	YU CHENGPIN	Cole Information Services
	GEORGE COHN	Cole Information Services
1994	COHN, GEORGE III	Cole Information Services
1991	Cohn George III	Pacific Telephone
1986	Dermon John & Linder	Pacific Bell
	DERMON JOHN & LINDER	Pacific Bell
1982	Dermon John & Linder	Pacific Telephone
1975	Schmitke Ray	Pacific Telephone
1968	BINGHAM DAVID	R. L. Polk Co.
1962	LAVIN WMI (ROSALIE) TCHR MENLO HIGH SCH	R. L. Polk & Co.
1957	LAVIN WM J	Pacific Telephone

1560 HOLLINGSWORTH DR

Year	Uses	Source
2017	RYAN MCLEAN	Cole Information Services
2014	THOMAS CONDY	Cole Information Services
2004	RICHARD CONDY	Cole Information Services

FINDINGS

Year	Uses	Source
2001	SKOMOKimberly	Haines Company, Inc.
	KOMO Manhew	Haines Company, Inc.
1968	FARANDA VINCENTINA MRS	R. L. Polk Co.
1962	FARONDA PHILLIP (JENNIE)	R. L. Polk & Co.
	FARONDA PHILIP STUDT	R. L. Polk & Co.
	FARONDA JANET STUDT	R. L. Polk & Co.

1561 HOLLINGSWORTH DR

Year	Uses	Source
2017	DOUGLAS ATLER	Cole Information Services
2014	DOUGLAS ATLER	Cole Information Services
2009	DOUGLAS ATLER	Cole Information Services
2004	DOUGLAS ATLER	Cole Information Services
2001	SATLER Doug	Haines Company, Inc.
	ATLER Betsy	Haines Company, Inc.
1999	DOUGLAS ATLER	Cole Information Services
1991	Hoffacker Ron & Cindy	Pacific Telephone
1982	Hoffacker Ron & Cindy	Pacific Telephone
1968	NO RETURN	R. L. Polk Co.
1962	FREEDMAN DON S (BETTY)	R. L. Polk & Co.
1957	FREEDMAN DON S	Pacific Telephone

1571 HOLLINGSWORTH DR

Year	Uses	Source
2017	WILLIAM SEGALLA	Cole Information Services
2014	MICHAEL HULFACTOR	Cole Information Services
2009	DECISIONTREND RESEARCH LLC	Cole Information Services
	MICHAEL HULFACTOR	Cole Information Services
2004	MICHAEL HULFACTOR	Cole Information Services
	HULFACTOR MICHAEL PH	Cole Information Services
2001	HULFACTOR Michael C	Haines Company, Inc.
1999	MICHAEL HULFACTOR	Cole Information Services
1994	YOUNG, EVERETT K	Cole Information Services
1991	Young Everett K	Pacific Telephone
1986	Young Everett K	Pacific Bell
	YOUNG EVERETT K	Pacific Bell
1975	Young Everett K	Pacific Telephone
1968	YOUNG EVERETT K	R. L. Polk Co.

FINDINGS

Year	Uses	Source
1962	YOUNG EVERETT K (MARIA PALM VARIETY)	R. L. Polk & Co.

1572 HOLLINGSWORTH DR

Year	Uses	Source
2017	LEI MENG	Cole Information Services
2014	YU CHANG	Cole Information Services
2009	YU CHANG	Cole Information Services
2001	SCHANGChing	Haines Company, Inc.
1999	YU CHANG	Cole Information Services
1986	Harmon J R	Pacific Bell
	HARMON J R	Pacific Bell
1982	Harmon Raymond K	Pacific Telephone
1975	Harmon Raymond K	Pacific Telephone
1968	FACCHIN JOHN B	R. L. Polk Co.

1586 HOLLINGSWORTH DR

Year	Uses	Source
2017	MIROSLAV SHVERDIN	Cole Information Services
2014	YELENA NABUTOVSKY	Cole Information Services
2009	BERTNER MCDOUGLE	Cole Information Services
2004	BERTNER MCDOUGLE	Cole Information Services
2001	SMCDOUGLEBertner	Haines Company, Inc.
1999	BERTNER MCDOUGLE	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
1994	MCDOUGLE, WILLIE B	Cole Information Services
1991	Mc Dougle Willie Belle	Pacific Telephone
1982	Mc Oougle Willie Belle	Pacific Telephone
1968	MC DOUGLE BERTNER T	R. L. Polk Co.
1962	MCDOUGALL JAS E ELK POELECTN HEWLETT-PACKARD	R. L. Polk & Co.
1957	MC DOUGLE B T	Pacific Telephone

1598 HOLLINGSWORTH DR

Year	Uses	Source
2017	KIP REPSCHER	Cole Information Services
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	STEPHANIE NEFF	Cole Information Services
2004	OCCUPANT UNKNOWN	Cole Information Services
2001	SSHOGUISTDaoid	Haines Company, Inc.

Year	Uses	Source
1999	STEPHANIE NEFF	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
1991	Yamamoto Steve	Pacific Telephone
1982	King Kenneth J	Pacific Telephone
1975	King Kenneth J	Pacific Telephone
1968	FLEISCHMANN JAMES K	R. L. Polk Co.
1962	FLEISCHMAINN JAS K I(BEVERLY) PERSONNEL DIR SOU PAC	R. L. Polk & Co.
1957	FLEISCHMANN J R	Pacific Telephone

1604 HOLLINGSWORTH DR

Year	Uses	Source
2014	WALTER JOLLA	Cole Information Services
2009	THERESA LOLLA	Cole Information Services
2004	EMILIO LOLLA	Cole Information Services
2001	SLOLLAEmilto	Haines Company, Inc.
1999	THERESA LOLLA	Cole Information Services
1968	LOLLA EMILIO A	R. L. Polk Co.
1962	LOLLA EMILIO (DOROTAHY) METAL POLISHER	R. L. Polk & Co.
1957	MAGILLRICHARD D	Pacific Telephone

1605 HOLLINGSWORTH DR

Year	Uses	Source
2017	NANCY LEM	Cole Information Services
2014	NANCY LEM	Cole Information Services
2009	NANCY LEM	Cole Information Services
2004	NANCY LEM	Cole Information Services
2001	LEM Nancy	Haines Company, Inc.
1999	NANCY LEM	Cole Information Services
1991	INFO SEARCH	Pacific Telephone
1968	NO RETURN	R. L. Polk Co.
1962	DICKSON COHIN (BARBARA) ENG PRECISION (SAN CARLOS)	R. L. Polk & Co.

1608 HOLLINGSWORTH DR

Year	Uses	Source
2017	RAYMOND CAULEY	Cole Information Services
2014	MICHAEL CAULEY	Cole Information Services
2009	RICHARD CAULEY	Cole Information Services
2004	RICHARD CAULEY	Cole Information Services

FINDINGS

Year	Uses	Source
2001	CAULEYM	Haines Company, Inc.
1999	RICHARD CAULEY	Cole Information Services
1968	NUNES BRUCE A	R. L. Polk Co.
1962	NELSON ROY A (ELSA J)	R. L. Polk & Co.

1610 HOLLINGSWORTH DR

Year	Uses	Source
2017	XAVIER WARTELLE	Cole Information Services
2014	XAVIER WARTELLE	Cole Information Services
2009	XAVIER WARTELLE	Cole Information Services
2004	OPAL COLLINS	Cole Information Services
2001	COLLINSOM	Haines Company, Inc.
	COLLINSOM	Haines Company, Inc.
1999	OPAL COLLINS	Cole Information Services
	XAVIER WARTELLE	Cole Information Services
1994	COLLINS, OPAL M	Cole Information Services
1991	Phillips Norene	Pacific Telephone
	Collins O M	Pacific Telephone
1986	Collins O M	Pacific Bell
1982	Collins DL	Pacific Telephone
1975	Collins Lee R	Pacific Telephone
1968	COLLINS LEE R	R. L. Polk Co.
1962	COLLINS BELLE	R. L. Polk & Co.
	COLLINS LEE R (OPAL) MGR B & H EQUIP	R. L. Polk & Co.

1613 HOLLINGSWORTH DR

Year	Uses	Source
2017	MICHAEL FEIN	Cole Information Services
2014	MICHAEL FEIN	Cole Information Services
2009	MICHAEL FEIN	Cole Information Services
2004	MICHAEL FEIN	Cole Information Services
2001	SFE 1 N Michael E	Haines Company, Inc.
	SFE 1 NMarcoa	Haines Company, Inc.
1999	MICHAEL FEIN	Cole Information Services
1968	BECKER WARREN M	R. L. Polk Co.
1962	ZOLK GEO (DOROTHY) CARP ICKA CONSTN (MENLO PARK)	R. L. Polk & Co.
1957	MC CLUNG ALAN	Pacific Telephone

FINDINGS

1614 HOLLINGSWORTH DR

Year	Uses	Source
2017	ELISA TREVINO	Cole Information Services
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	PENG WANG	Cole Information Services
2004	PENG WANG	Cole Information Services
2001	MILLERHM	Haines Company, Inc.
1999	PENG WANG	Cole Information Services
1994	MILLER, HORACE M	Cole Information Services
1991	Miller H M	Pacific Telephone
1986	Miller H M	Pacific Bell
	MILLER H M	Pacific Bell
1982	Miller H M	Pacific Telephone
1975	Miller H M	Pacific Telephone
1968	MILLER HORACE M	R. L. Polk Co.
1962	MILLER HORACE (ETHEL) SUPT AMES LABY	R. L. Polk & Co.
1957	MILLER H M	Pacific Telephone

1616 HOLLINGSWORTH DR

Year	Uses	Source
2014	MARIENNE MURPHY	Cole Information Services
2009	MARIENNE MURPHY	Cole Information Services
1999	MARIENNE MURPHY	Cole Information Services

1617 HOLLINGSWORTH DR

Year	Uses	Source
2017	DAVID TUCKER	Cole Information Services
2014	DAVID TUCKER	Cole Information Services
2009	DAVID TUCKER	Cole Information Services
2004	DAVID TUCKER	Cole Information Services
2001	STUCKER	Haines Company, Inc.
	STUCKER T	Haines Company, Inc.
1999	DAVID TUCKER	Cole Information Services
1994	THOMPSON, ANDREW D	Cole Information Services
1968	KALLIO MIKKO	R. L. Polk Co.
1962	KALLIO MIKKO (MIRJAMI) CARP	R. L. Polk & Co.

1618 HOLLINGSWORTH DR

Year	Uses	Source
2014	MICHAEL MURPHY	Cole Information Services

FINDINGS

Year	Uses	Source
2009	SUSAN MURPHY	Cole Information Services
2004	SUSAN MURPHY	Cole Information Services
2001	SMURPHYTim	Haines Company, Inc.
	SMURPHYTim	Haines Company, Inc.
1999	SUSAN MURPHY	Cole Information Services
1994	MURPHY, TIM	Cole Information Services
1991	Murphy Tim	Pacific Telephone
1982	Parachou Martin	Pacific Telephone
1975	Johnson Floyd O	Pacific Telephone
1968	JOHNSON FLOYD	R. L. Polk Co.

1625 HOLLINGSWORTH DR

Year	Uses	Source
2017	EDWARD COLLINS	Cole Information Services
2014	EDWARD COLLINS	Cole Information Services
2009	VERDE CRISTAL	Cole Information Services
	EDWARD COLLINS	Cole Information Services
2004	THELMA DIMARIA	Cole Information Services
2001	SDIMARIAT	Haines Company, Inc.
1999	EDWARD COLLINS	Cole Information Services
1994	DIMARIA, T	Cole Information Services
1991	Collins Ed & Francl	Pacific Telephone
1986	MORTON H	Pacific Bell
	Morton H	Pacific Bell
1982	Morton Agnes	Pacific Telephone
1968	01D MARIA THELMA MRS	R. L. Polk Co.
1962	DIMARIA PETER F (THELMA) REAL EST	R. L. Polk & Co.
1957	DIMARIA PETER F	Pacific Telephone

1626 HOLLINGSWORTH DR

Year	Uses	Source
2017	ROBERT BAILO	Cole Information Services
	BRIAN SCHAMBER	Cole Information Services
	JUDI HENSLEY	Cole Information Services
	RICHAR LUNDGREN	Cole Information Services
2014	JUDI HENSLEY	Cole Information Services
	RICHAR LUNDGREN	Cole Information Services
	ROBERT BAILO	Cole Information Services
	BRIAN SCHAMBER	Cole Information Services

FINDINGS

Year	Uses	Source
2009	RICHARD LUNDGREN	Cole Information Services
2004	RICHARD LUNDGREN	Cole Information Services
	AVERY CLEARY	Cole Information Services
	JUDITH FANCHER	Cole Information Services
2001	LUNDGREN Richard	Haines Company, Inc.
	LUNDGREN Deborah	Haines Company, Inc.
1999	RICHARD LUNDGREN	Cole Information Services
1994	LUNDGREN, RICHARD	Cole Information Services
1986	LUNDGREN RICHARD & DEBORAH	Pacific Bell
	LUNDGREN RICHARD	Pacific Bell
	Lundgren Richard	Pacific Bell
	Lundgren Richard & Deborah	Pacific Bell
1968	SIMONETTI JOSEPH	R. L. Polk Co.
1962	KOKIOS CHARLOTTE	R. L. Polk & Co.

1633 HOLLINGSWORTH DR

Year	Uses	Source
2017	VALERIE REED	Cole Information Services
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	SAMUEL STEPHENSON	Cole Information Services
2004	ALBORZ SATELLITE TV	Cole Information Services
	FAISHID SAFAI	Cole Information Services
2001	AHMADIQumars	Haines Company, Inc.
	SSTEPHENSON Samuel	Haines Company, Inc.
1999	SAMUEL STEPHENSON	Cole Information Services
1994	SAFAIFARD, FARSAID	Cole Information Services
	AHMADI, QUMARS	Cole Information Services
	STEPHENSON, SAM	Cole Information Services
1991	Stephenson Sam & Tula	Pacific Telephone
	Safalfard Farshld	Pacific Telephone
1986	STEPHENSON DAVID	Pacific Bell
	Stephenson David	Pacific Bell
1982	Stephenson David	Pacific Telephone
1975	Stephenson Russell V Jr	Pacific Telephone
	Stephenson Sam	Pacific Telephone
1968	STEPHENSON SAM	R. L. Polk Co.
1962	STEPHENSON SAM (TULA) ENG WESTINGHOUSE (SUNNYVALE)	R. L. Polk & Co.
1957	STEPHENSON S H	Pacific Telephone

FINDINGS

1634 HOLLINGSWORTH DR

Year	*Uses*	*Source*
2017	MATTHEW SUCHERMAN	Cole Information Services
2014	TRACY YOSTEN	Cole Information Services
2004	DOROTHY BENOIT	Cole Information Services
2001	SEENDITDoro Ihy	Haines Company, Inc.
1982	Benoit Geo R	Pacific Telephone
	Benoit Jodi M	Pacific Telephone
1975	Benoit Geo R	Pacific Telephone
	Benoit D J J	Pacific Telephone
1968	BENOIT GEO R	R. L. Polk Co.
1962	BENOIT GEO R (DOROTHY CALDWELL & BENOIT)	R. L. Polk & Co.
1957	BENOIT GEO R	Pacific Telephone

1640 HOLLINGSWORTH DR

Year	*Uses*	*Source*
2017	FRANZ OCH	Cole Information Services
2014	FRANZ OCH	Cole Information Services
2009	JOANNE BENNETT	Cole Information Services
2004	JOANNE BENNETT	Cole Information Services
2001	SBENNETTWm R	Haines Company, Inc.
1999	JOANNE BENNETT	Cole Information Services
1994	BENNETT, WILLIAM R	Cole Information Services
1991	Bennett Wm R	Pacific Telephone
1986	Bennett Wm R	Pacific Bell
	BENNETT WM R	Pacific Bell
1982	Bennett Wm R	Pacific Telephone
1975	Bennett Wm R	Pacific Telephone
1968	BENNETT WM R	R. L. Polk Co.
1962	BENNETT WM R (JOANNE B) OFC WKR DOLE CORP	R. L. Polk & Co.
	BENNETT JOIANNE B MRS TCHR	R. L. Polk & Co.

1641 HOLLINGSWORTH DR

Year	*Uses*	*Source*
2014	GLEN HICKS	Cole Information Services
2009	GLEN HICKS	Cole Information Services
2004	GLEN HICKS	Cole Information Services
2001	SHICKSGlen	Haines Company, Inc.
1999	GLEN HICKS	Cole Information Services

FINDINGS

Year	Uses	Source
1982	Knight Robt S	Pacific Telephone
1968	KNIGHT R S	R. L. Polk Co.
1962	OLSEN OLUF L (MAUDE M)	R. L. Polk & Co.

1649 HOLLINGSWORTH DR

Year	Uses	Source
2014	JONATHAN MOOSER	Cole Information Services
2009	ELANOR THORN	Cole Information Services
2004	ELANOR THORN	Cole Information Services
2001	THORN Eleanor	Haines Company, Inc.
1999	ELANOR THORN	Cole Information Services
1991	Thorn August R	Pacific Telephone
1986	Thorn August R	Pacific Bell
	THORN AUGUST R	Pacific Bell
1982	Thorn August R	Pacific Telephone
1975	Thorn August R	Pacific Telephone
1968	THORN AUG R	R. L. Polk Co.
1962	THORN AUG R (ELEANOR) MACH MCBRIDE CO	R. L. Polk & Co.
	THORN ELEANOR MRS BKBNDR PACIFIC PRESS	R. L. Polk & Co.

1652 HOLLINGSWORTH DR

Year	Uses	Source
2017	DAVID ZINN	Cole Information Services
2014	DAVID ZINN	Cole Information Services
2009	JANIS ZINN	Cole Information Services
2004	JANIS ZINN	Cole Information Services
2001	ORNEJanis	Haines Company, Inc.
	ZINN Howard	Haines Company, Inc.
	ZINNJans	Haines Company, Inc.
1999	JANIS ZINN	Cole Information Services
1994	ORNE, JANIS	Cole Information Services
	ZINN, HOWARD	Cole Information Services
1991	Zinn Howard & Janis	Pacific Telephone
1986	RUBENSTEIN MARTIN	Pacific Bell
	Rubenstein Martin	Pacific Bell
1982	Rubensteln Martin	Pacific Telephone
1968	RAGNO FRED	R. L. Polk Co.
1962	RAGNO FRED (IRMA) ELK JOHN S IPA	R. L. Polk & Co.

FINDINGS

1668 HOLLINGSWORTH DR

Year	*Uses*	*Source*
2017	VALERY POLISHCHUK	Cole Information Services
2014	WEI DACHEN	Cole Information Services
2009	WEI DACHEN	Cole Information Services
2004	IRVING MILLER	Cole Information Services
	MOUNTAIN VIEW DATA INC	Cole Information Services
1999	WEI DACHEN	Cole Information Services

HOLLNGSVRTH DR

1649 HOLLNGSVRTH DR

Year	*Uses*	*Source*
1957	THORN AUGUST R	Pacific Telephone

HOLLNGSWRTH DR

1519 HOLLNGSWRTH DR

Year	*Uses*	*Source*
1975	Fritz Paul L	Pacific Telephone

1541 HOLLNGSWRTH DR

Year	*Uses*	*Source*
1975	Bostwick Russell E	Pacific Telephone

HOLLNQGSWRTH DR

1625 HOLLNQGSWRTH DR

Year	*Uses*	*Source*
1975	Di Maria T M	Pacific Telephone

KATHY WAY

1127 KATHY WAY

Year	*Uses*	*Source*
2017	BRENT CRANE	Cole Information Services
2014	BRENT CRANE	Cole Information Services
2009	OCCUPANT UNKNOWN	Cole Information Services
2004	BRENT CRANE	Cole Information Services
2001	BLOOM H	Haines Company, Inc.
1999	OCCUPANT UNKNOWN	Cole Information Services

FINDINGS

Year	Uses	Source
1994	BLOOM, LYMAN C	Cole Information Services
1991	Bloom L C Cdr	Pacific Telephone
1986	BLOOM L C CDR	Pacific Bell
	Bloom L C Cdr	Pacific Bell
1982	Bloom L C Cdr	Pacific Telephone
1975	Bloom L C Cdr	Pacific Telephone
1968	8 LOOM LYMON Y	R. L. Polk Co.
1962	BLOOM LYMON (HELEN) COORDINATOR LOCKHEED	R. L. Polk & Co.
	BLOOM RICHID STUDT	R. L. Polk & Co.

1132 KATHY WAY

Year	Uses	Source
2017	JAMES RUSSELL	Cole Information Services
2014	JAMES RUSSELL	Cole Information Services
2009	JAMES RUSSELL	Cole Information Services
2004	JAMES RUSSELL	Cole Information Services
2001	SRUSSELLJames J	Haines Company, Inc.
1999	JAMES RUSSELL	Cole Information Services
1994	RUSSELL, JAMES J	Cole Information Services
1975	Freels Jeffrey	Pacific Telephone
1968	CROWELL MORTIMER Y	R. L. Polk Co.
1962	CROWELL MORTIMER (LOUISE)	R. L. Polk & Co.

1139 KATHY WAY

Year	Uses	Source
2017	LUCA DEALFARO	Cole Information Services
2014	OCCUPANT UNKNOWN	Cole Information Services
2009	LUCA DEALFARO	Cole Information Services
2004	FRANCOISE BEAUFAYS	Cole Information Services
2001	DEALFAROLuca	Haines Company, Inc.
1999	OCCUPANT UNKNOWN	Cole Information Services
	LUCA DEALFARO	Cole Information Services
1986	Connolly Jack	Pacific Bell
	CONNOLLY JACK	Pacific Bell
1982	Connolly J M	Pacific Telephone
	f Cpnnolly Jack	Pacific Telephone
1975	Caprorn A W	Pacific Telephone
1968	CAPRON ARTH W	R. L. Polk Co.

Year	Uses	Source
1962	CAPRON DIANNE STUDT	R. L. Polk & Co.
1957	CAPRON A W	Pacific Telephone

1146 KATHY WAY

Year	Uses	Source
2017	JOHN GANN	Cole Information Services
2014	JOHN GANN	Cole Information Services
2009	JOHN GANN	Cole Information Services
2004	OCCUPANT UNKNOWN	Cole Information Services
	CHESAPEAKE TECHNOLOGY INC	Cole Information Services
2001	GANNJohn T	Haines Company, Inc.
1999	JOHN GANN	Cole Information Services
1994	GANN, JOHN T	Cole Information Services
1991	Gann John T	Pacific Telephone
1986	AD SKI JOS H	Pacific Bell
	Ad ski Jos H	Pacific Bell
1982	Adamski Jos H	Pacific Telephone
1975	Adamski Jos H	Pacific Telephone
1968	ADAMSKZ JOSEPH H	R. L. Polk Co.
1962	ADAMSKI WANDA MRS RECPT MT VIEW CHIROPRACTIC CENTER	R. L. Polk & Co.

1158 KATHY WAY

Year	Uses	Source
2017	MARK ALEXANDER	Cole Information Services
2014	MARK ALEXANDER	Cole Information Services
2009	TAL ALEXANDER	Cole Information Services
2004	EUGENE ALEXANDER	Cole Information Services
2001	ALEXANDER Tal	Haines Company, Inc.
1999	TAL ALEXANDER	Cole Information Services
1994	ALEXANDER, TAL	Cole Information Services
1991	Alexander Tal	Pacific Telephone
1986	Alexander Tal	Pacific Bell
	Alexander Mark	Pacific Bell
	ALEXANDER TAL	Pacific Bell
	ALEXANDER MARK	Pacific Bell
1982	Alexander Tal	Pacific Telephone
	Alexander Kevin	Pacific Telephone
1975	Alexander Tal	Pacific Telephone

Year	Uses	Source
1962	SAYERS GERALD (SHIRLEY) LITHO PACIFIC PRESS	R. L. Polk & Co.
1957	MC CORMICK S M REV	Pacific Telephone

MARIPOSA AVE

726 MARIPOSA AVE

Year	Uses	Source
1986	Stienstra Robert & Eleanor	Pacific Bell

772 MARIPOSA AVE

Year	Uses	Source
1957	SCHOMER JAS W	Pacific Telephone
	MARKER RALPH D	Pacific Telephone
	ANTLE BOB V	Pacific Telephone
	JONES RON L	Pacific Telephone

N EL MONTE AVE

1059 N EL MONTE AVE

Year	Uses	Source
1957	JENSEN WAITER N MDO	Pacific Telephone

1065 N EL MONTE AVE

Year	Uses	Source
1975	Furuki Minoru pub acct	Pacific Telephone

RICH AV MV

959 RICH AV MV

Year	Uses	Source
1975	Sears M	Pacific Telephone

RICH AV MVW

1047 RICH AV MVW

Year	Uses	Source
1975	Young Ethron T II	Pacific Telephone

FINDINGS

RICH AVE

900 RICH AVE

Year	Uses	Source
1982	Bryant Melvin P	Pacific Telephone
	Dickey Leonard H	Pacific Telephone

905 RICH AVE

Year	Uses	Source
1975	Anthney Larry	Pacific Telephone

908 RICH AVE

Year	Uses	Source
2017	BRYCE ANZELMO	Cole Information Services
	LAURA CARLYLE	Cole Information Services
	TYLER CURTIS	Cole Information Services
	JUSTIN MORALES	Cole Information Services
	SHUBHANAN BAKRE	Cole Information Services
	VICENTE LEE	Cole Information Services
2014	PAYAM PAKZAD	Cole Information Services
	OLAWALE OGUNWALE	Cole Information Services
	JOHN MCGEHEE	Cole Information Services
	JUSTIN MORALES	Cole Information Services
	CARL DANIEL	Cole Information Services
	SHUBHANAN BAKRE	Cole Information Services
2009	RENIE HENCHY	Cole Information Services
	DEVELYNNE ELLIOTT	Cole Information Services
	CARL DANIEL	Cole Information Services
	LARS MINSAAS	Cole Information Services
	MARK MARTEL	Cole Information Services
2004	ROBERT MORTENSEN	Cole Information Services
	RENIE HENCHY	Cole Information Services
	ADAM WAGNER	Cole Information Services
	DONALD HARRIS	Cole Information Services
	RAGHU BINDIGENAVALE	Cole Information Services
	THIERRY OMNES	Cole Information Services
	MARY PETROSSI	Cole Information Services
2001	MAYDWELL George	Haines Company, Inc.
	APARTMENTS BALEPURPrashanl N	Haines Company, Inc.
	BINDIGENAVALERaghu	Haines Company, Inc.

FINDINGS

Year	Uses	Source
2001	DUNLAP Micheal	Haines Company, Inc.
	LONG Roger S	Haines Company, Inc.
	TOYWinslon	Haines Company, Inc.
1999	MARK MARTEL	Cole Information Services
	RENIE HENCHY	Cole Information Services
	DEVELYNNE ELLIOTT	Cole Information Services
	CARL DANIEL	Cole Information Services
	GEORGE MAYDWELL	Cole Information Services
1994	BARRIGA, HUMBERT	Cole Information Services
1986	BRYANT MELVIN P	Pacific Bell
	DICKEY LEONARD H	Pacific Bell
	DROOR FRIDA	Pacific Bell
	STARR K & S	Pacific Bell
	WIRSHING STEVEN	Pacific Bell
	Bryant Melvin P	Pacific Bell
	Dickey Leonard H	Pacific Bell
	Droor Frida	Pacific Bell
	Starr K & S	Pacific Bell
	Wirshing Steven	Pacific Bell
1982	Droor Frida	Pacific Telephone
1975	Andrus Donald N	Pacific Telephone
	Block M I	Pacific Telephone
	Bryant Melvin P	Pacific Telephone
	Joe B K	Pacific Telephone
1968	PETERSON JOHN M	R. L. Polk Co.
	MOORE JOHN W	R. L. Polk Co.
	WYNNE GEO F	R. L. Polk Co.
	PEAVEY B	R. L. Polk Co.
	JACKSON JOHN W	R. L. Polk Co.
	MANSOLILLO L	R. L. Polk Co.
	Apts Contd	R. L. Polk Co.
	JOHNSON HAROLD L	R. L. Polk Co.
	MOORE KEN	R. L. Polk Co.
	WEAR RICHD	R. L. Polk Co.
	APARTMENTS	R. L. Polk Co.

910 RICH AVE

Year	Uses	Source
2017	MELISSA MCCRACKEN	Cole Information Services

FINDINGS

Year	Uses	Source
2017	YEVGENIY SELEZNEV	Cole Information Services
	ALLISON IPSON	Cole Information Services
	QING HAN	Cole Information Services
	FARIBA HAKAMI	Cole Information Services
	SUSHMIT KUMAR	Cole Information Services
2014	YEVGENIY SELEZNEV	Cole Information Services
	MITCHELL CAMPBELL	Cole Information Services
2009	CHRISTOPHER STEVENS	Cole Information Services
	ANTHONY MAROON	Cole Information Services
	STEVE CHIEN	Cole Information Services
2004	CHRISTOPHER STEVENS	Cole Information Services
	DUANE SNIDER	Cole Information Services
	DAVI ABDALLAH	Cole Information Services
	SIMON WISE	Cole Information Services
	SURESH PISHARODY	Cole Information Services
	CHRISTINE MUSSER	Cole Information Services
	FENG LI	Cole Information Services
2001	APARTMENTS BECKERMANIor J	Haines Company, Inc.
	LIFeng	Haines Company, Inc.
	MUSSERMC	Haines Company, Inc.
	STEVENS Chrsolpher	Haines Company, Inc.
	WISE Simon	Haines Company, Inc.
1999	ANTHONY MAROON	Cole Information Services
	STEVE CHIEN	Cole Information Services
	CHRISTOPHER STEVENS	Cole Information Services
1986	Jobe Steve	Pacific Bell
	Pham Dinh Q	Pacific Bell
	Sanders John L	Pacific Bell
	JOBE STEVE	Pacific Bell
	PHAM DINH Q	Pacific Bell
	SANDERS JOHN L	Pacific Bell
1982	Barack Ron	Pacific Telephone
	Campista A	Pacific Telephone
	Sanders John L	Pacific Telephone
1975	Eaton Wm F	Pacific Telephone
	Guardin Richard D	Pacific Telephone
	Henrich V L	Pacific Telephone
	Thames Gay	Pacific Telephone

FINDINGS

Year	Uses	Source
1968	APARTMENTS	R. L. Polk Co.
	EATDN WM F	R. L. Polk Co.
	SMOOT MARGT W	R. L. Polk Co.
	DIAS CLYDE F JR	R. L. Polk Co.
	CUMMINGS PAUL	R. L. Polk Co.
	BURDICK ROBT	R. L. Polk Co.
	MORRILL CHARLES R	R. L. Polk Co.
	BECKERS W R	R. L. Polk Co.
	KELLY JAMES	R. L. Polk Co.
	RODERICK E D	R. L. Polk Co.

911 RICH AVE

Year	Uses	Source
1986	KNOX BONNY & LOULSE	Pacific Bell
	Knox Bonny & Loulse	Pacific Bell

912 RICH AVE

Year	Uses	Source
2017	GEORGE FAULKNOR	Cole Information Services
	CHRISTOPHER CONLEY	Cole Information Services
	KAJA MYERS	Cole Information Services
	LIUJING XING	Cole Information Services
	SHIH CHIU	Cole Information Services
	PAUL GALLO	Cole Information Services
	AMAR PARIKH	Cole Information Services
	ROBERTO ACOSTA	Cole Information Services
	LAUREL FEE	Cole Information Services
	GEORGE FAULKNOR	Cole Information Services
	CHRISTOPHER CONLEY	Cole Information Services
	KAJA MYERS	Cole Information Services
	LIUJING XING	Cole Information Services
	SHIH CHIU	Cole Information Services
	PAUL GALLO	Cole Information Services
	AMAR PARIKH	Cole Information Services
	ROBERTO ACOSTA	Cole Information Services
	LAUREL FEE	Cole Information Services
2014	BRAD IJAMS	Cole Information Services
	GEORGE FAULKNOR	Cole Information Services
	CHRISTOPHER CONLEY	Cole Information Services

FINDINGS

Year	Uses	Source
2014	TANYA SPANGLER	Cole Information Services
	PAUL GALLO	Cole Information Services
	NAOMI BANCROFT	Cole Information Services
	SHIH CHIU	Cole Information Services
	BOB GRIFFIN	Cole Information Services
	BRAD IJAMS	Cole Information Services
	GEORGE FAULKNOR	Cole Information Services
	CHRISTOPHER CONLEY	Cole Information Services
	TANYA SPANGLER	Cole Information Services
	PAUL GALLO	Cole Information Services
	NAOMI BANCROFT	Cole Information Services
	SHIH CHIU	Cole Information Services
	BOB GRIFFIN	Cole Information Services
2009	SHIH CHIU	Cole Information Services
	NANCY BARNETT	Cole Information Services
	HEATHER BUSBY	Cole Information Services
	RICH AVENUE APARTMENTS	Cole Information Services
	KELLY GRIFFIN	Cole Information Services
	LOURDES PALMA	Cole Information Services
	GEORGE FAULKNOR	Cole Information Services
	SHIH CHIU	Cole Information Services
	NANCY BARNETT	Cole Information Services
	HEATHER BUSBY	Cole Information Services
	RICH AVENUE APARTMENTS	Cole Information Services
	KELLY GRIFFIN	Cole Information Services
	LOURDES PALMA	Cole Information Services
	GEORGE FAULKNOR	Cole Information Services
2004	RON SIPES	Cole Information Services
	RICH AVE APT	Cole Information Services
	DIANE LOWE	Cole Information Services
	HEATHER BUSBY	Cole Information Services
	RICHARD LLOYD	Cole Information Services
	IVICA MIKEC	Cole Information Services
	JOANNA PECK	Cole Information Services
	MICHAEL STOCKER	Cole Information Services
	GEORGE FAULKNOR	Cole Information Services
	MIRIAM MELO	Cole Information Services
	RON SIPES	Cole Information Services

FINDINGS

Year	Uses	Source
2004	RICH AVE APT	Cole Information Services
	DIANE LOWE	Cole Information Services
	HEATHER BUSBY	Cole Information Services
	RICHARD LLOYD	Cole Information Services
	IVICA MIKEC	Cole Information Services
	JOANNA PECK	Cole Information Services
	MICHAEL STOCKER	Cole Information Services
	GEORGE FAULKNOR	Cole Information Services
	MIRIAM MELO	Cole Information Services
2001	RICHAVAPTS BABANorman N	Haines Company, Inc.
	BUSBY H	Haines Company, Inc.
	FAULKNOR George	Haines Company, Inc.
	SGALLOPaul MCCOYJim	Haines Company, Inc.
	MIKEC vica	Haines Company, Inc.
	RICH AVENUE	Haines Company, Inc.
1999	GEORGE FAULKNOR	Cole Information Services
	LOURDES PALMA	Cole Information Services
	KELLY GRIFFIN	Cole Information Services
	HEATHER BUSBY	Cole Information Services
	SHIH CHIU	Cole Information Services
	NANCY BARNETT	Cole Information Services
	GEORGE FAULKNOR	Cole Information Services
	LOURDES PALMA	Cole Information Services
	KELLY GRIFFIN	Cole Information Services
	NANCY BARNETT	Cole Information Services
	SHIH CHIU	Cole Information Services
	HEATHER BUSBY	Cole Information Services
1991	Contd	Pacific Telephone
1986	Barriga Humberto	Pacific Bell
	Eggers Harold W	Pacific Bell
	Lee Diane	Pacific Bell
	Piller J E	Pacific Bell
	BARRIGA HUMBERTO	Pacific Bell
	EGGERS HAROLD W	Pacific Bell
	KENDALL P	Pacific Bell
	LEE DIANE	Pacific Bell
	PILLER J E	Pacific Bell
1982	Carter David M	Pacific Telephone

FINDINGS

Year	Uses	Source
1982	Loggins CD	Pacific Telephone
	Pfenninger Johannes	Pacific Telephone
	Piler JE	Pacific Telephone
	Rosskopf Kathy A	Pacific Telephone
	Works FH	Pacific Telephone
1975	Halterman Chas G	Pacific Telephone
	Kennedy C	Pacific Telephone
	Lemke Jos	Pacific Telephone
	Oglesbee RW	Pacific Telephone
	Sturgeon Fraiaces	Pacific Telephone
	Sturgeon H B	Pacific Telephone
	Uh Hong Sun	Pacific Telephone
1968	STURGEON H B	R. L. Polk Co.
	GERARD JAMES	R. L. Polk Co.
	GRATON I S	R. L. Polk Co.
	MACHNICK J JR	R. L. Polk Co.
	NAIL ORVAL	R. L. Polk Co.
	SUMMERFIELD L	R. L. Polk Co.
	NEVINS RON	R. L. Polk Co.
	TRESSEL RONALD	R. L. Polk Co.
	SWANSON CRAIG H	R. L. Polk Co.
	APARTMENTS	R. L. Polk Co.
1962	STAFFORD PAUL E (MAUREEN A) DRFTSMN LOCKHEED	R. L. Polk & Co.

914 RICH AVE

Year	Uses	Source
2017	KEVIN TULLY	Cole Information Services
	SHANNA HILL	Cole Information Services
	DAVANH PHETKHAMCHANH	Cole Information Services
2014	KRISTIN ANDERSON	Cole Information Services
	SHANNA HILL	Cole Information Services
	SCOTT ALLEN	Cole Information Services
	MEGAN HAMILTON	Cole Information Services
	NAVEEN RAMADASAN	Cole Information Services
2009	LOIS LEE	Cole Information Services
	WALLACE EMETT	Cole Information Services
	MARK DODD	Cole Information Services
2004	SRINIVASA KODALI	Cole Information Services

FINDINGS

Year	Uses	Source
2004	JING LIU	Cole Information Services
	TALAYEH NIKPAY	Cole Information Services
	BARBARA KOSIC	Cole Information Services
	PAULA MITCHELL	Cole Information Services
	MENG MANTASOOT	Cole Information Services
	ILYA MUSICANTE	Cole Information Services
2001	MURRAY Rebecca	Haines Company, Inc.
1999	LOIS LEE	Cole Information Services
	WALLACE EMETT	Cole Information Services
	MARK DODD	Cole Information Services
1986	Brand Isia	Pacific Bell
	Little Marie	Pacific Bell
	BRAND ISIA	Pacific Bell
	LITTLE MARIE	Pacific Bell
1982	Barnard Tim	Pacific Telephone
	Brand Isla Cox & Associates Inc realtors	Pacific Telephone
	Res	Pacific Telephone
	Lane Alan P	Pacific Telephone
1975	BRAND ISLA Altos Realty Investment Corp	Pacific Telephone
	Res	Pacific Telephone
	Denhard Christopher F	Pacific Telephone
	i Denicoly Hugo A	Pacific Telephone
	Mikesell Elmer L	Pacific Telephone
	Torres Carlos	Pacific Telephone
1968	WOOD ARTH J	R. L. Polk Co.
	CORNEZ ARNOLD	R. L. Polk Co.
	SHAAKE K C	R. L. Polk Co.
	KENNEDY C	R. L. Polk Co.
	SPEAKMAN DON G	R. L. Polk Co.
	BRAND ISLA MRS	R. L. Polk Co.
	SCHEIDIXNG MERMAN G	R. L. Polk Co.
	MENGE W C	R. L. Polk Co.
	I LORD GEO	R. L. Polk Co.
	APARTMENTS	R. L. Polk Co.

915 RICH AVE

Year	Uses	Source
1999	OCCUPANT UNKNOWN	Cole Information Services

FINDINGS

920 RICH AVE

Year	Uses	Source
2017	XIULAN ZHOU	Cole Information Services
2014	KEYI LU	Cole Information Services
2009	KEYI LIU	Cole Information Services
2004	OCCUPANT UNKNOWN	Cole Information Services
2001	HOKei LIU lhsn	Haines Company, Inc.
1999	KEYI LIU	Cole Information Services
1991	Cacciaguidi Geno A & Kim	Pacific Telephone
1986	Ginner Greg	Pacific Bell
	GINNER GREG	Pacific Bell
1982	Meyerott J Royce	Pacific Telephone
1975	M eyerott J Royce	Pacific Telephone
1968	LECONTE MARCEL	R. L. Polk Co.
1962	LECONTE ELIZ OFC WKR PAC	R. L. Polk & Co.
	LECONTE MARCEL (ANNA)	R. L. Polk & Co.

922 RICH AVE

Year	Uses	Source
2017	ANILKUMAR PANNIKKAT	Cole Information Services
2014	ANILKUMAR PANNIKKAT	Cole Information Services
2009	OCCUPANT UNKNOWN	Cole Information Services
2004	DAVID NAKAMURA	Cole Information Services
2001	SVANWOUDENBERScoll	Haines Company, Inc.
1999	OCCUPANT UNKNOWN	Cole Information Services

930 RICH AVE

Year	Uses	Source
2001	XU Daniel	Haines Company, Inc.

932 RICH AVE

Year	Uses	Source
2001	YOUNG Robort	Haines Company, Inc.

934 RICH AVE

Year	Uses	Source
2004	HARRY BRATT	Cole Information Services

936 RICH AVE

Year	Uses	Source
2004	NEIL YOUK	Cole Information Services

FINDINGS

Year	Uses	Source
2001	KAMENScott YOUK Heather	Haines Company, Inc.
	YOUKNeil	Haines Company, Inc.

938 RICH AVE

Year	Uses	Source
2009	DAN SHARONI	Cole Information Services
2004	DAN SHARONI	Cole Information Services
2001	SHARONIDan	Haines Company, Inc.
1999	DAN SHARONI	Cole Information Services

939 RICH AVE

Year	Uses	Source
2017	DANIEL OPINE	Cole Information Services
	ROBERT BARBER	Cole Information Services
	LINA SAMPAYO	Cole Information Services
2014	DANIEL OPINE	Cole Information Services
	LINA SAMPAYO	Cole Information Services
	ROBERT BARBER	Cole Information Services
2009	HECTOR BALMACEDA	Cole Information Services
	DANIEL OPINE	Cole Information Services
	LINA SAMPAYO	Cole Information Services
2004	ANTONIA BARRAGN	Cole Information Services
2001	YADAVSun Ol	Haines Company, Inc.
1999	HECTOR BALMACEDA	Cole Information Services
	DANIEL OPINE	Cole Information Services
	LINA SAMPAYO	Cole Information Services
1986	Alcasar Jose L	Pacific Bell
	ALCASAR JOSE L	Pacific Bell
1982	Alcasar Jose L	Pacific Telephone
	Valencia Doroteo	Pacific Telephone
	Valencia Geronimo	Pacific Telephone
1975	Zuniga Luis A	Pacific Telephone
1968	PAULEY THOS	R. L. Polk Co.
	FARNUM ROST	R. L. Polk Co.
	ARNOLD CHARLES A	R. L. Polk Co.
	VACANT	R. L. Polk Co.
	APARTMENTS	R. L. Polk Co.
1962	ESERINI MICHI C MGR ESERINI S RICHFIELD SERV	R. L. Polk & Co.

FINDINGS

940 RICH AVE

Year	Uses	Source
2004	SCOTT TRAPPE	Cole Information Services

942 RICH AVE

Year	Uses	Source
2001	GFREED Bryan	Haines Company, Inc.

959 RICH AVE

Year	Uses	Source
2017	PAUL JAMES	Cole Information Services
	PARKRICH APARTMENTS	Cole Information Services
	KENNEDY TURNER	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	DANIELLE LAMUTIS	Cole Information Services
	MICHAEL MACDONALD	Cole Information Services
	MONICA MARTIN	Cole Information Services
	CHONG CHAN	Cole Information Services
	SHELBI KELLY	Cole Information Services
	DAN KERR	Cole Information Services
	HERVEY LEE	Cole Information Services
	TIMOTHY WOOTEN	Cole Information Services
	KAILIANG CHEN	Cole Information Services
	JOSE LOPEZ	Cole Information Services
	SANDRA NARVAEZ	Cole Information Services
	CHRISTOPHER PROUNH	Cole Information Services
	SOHEIL FEIZI	Cole Information Services
	PAUL PHROMTHONG	Cole Information Services
	ANASTASSIYA BEREZHNAYA	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	ROHAN SAINI	Cole Information Services
	PAUL JAMES	Cole Information Services
	PARKRICH APARTMENTS	Cole Information Services
	KENNEDY TURNER	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	DANIELLE LAMUTIS	Cole Information Services
	MICHAEL MACDONALD	Cole Information Services
	MONICA MARTIN	Cole Information Services
	CHONG CHAN	Cole Information Services
	SHELBI KELLY	Cole Information Services

FINDINGS

Year	Uses	Source
2017	DAN KERR	Cole Information Services
	HERVEY LEE	Cole Information Services
	TIMOTHY WOOTEN	Cole Information Services
	KAILIANG CHEN	Cole Information Services
	JOSE LOPEZ	Cole Information Services
	SANDRA NARVAEZ	Cole Information Services
	CHRISTOPHER PROUNH	Cole Information Services
	SOHEIL FEIZI	Cole Information Services
	PAUL PHROMTHONG	Cole Information Services
	ANASTASSIYA BEREZHNAYA	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	ROHAN SAINI	Cole Information Services
2014	PARKRICH APARTMENTS	Cole Information Services
	AFAGH AZIZI	Cole Information Services
	SKIPTON DRULIAS	Cole Information Services
	ROHAN SAINI	Cole Information Services
	KEITH RUTHERFORD	Cole Information Services
	ANDREW CRUTCHFIELD	Cole Information Services
	CINDIECLAIRE CRUZ	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	SIMON EDWARDSSON	Cole Information Services
	DARRELL SORENSON	Cole Information Services
	RAO JAYANT	Cole Information Services
	MICHAEL MACDONALD	Cole Information Services
	MONICA MARTIN	Cole Information Services
	LATISHA BRIGGS	Cole Information Services
	P SORENSEN	Cole Information Services
	THOMAS HEGARTY	Cole Information Services
	DAN KERR	Cole Information Services
	HERVEY LEE	Cole Information Services
	KRISTEN ANNIS	Cole Information Services
	BONNIE SARMIENTO	Cole Information Services
	DAVANH PHETKHAMCHANH	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	JOHN JANSEN	Cole Information Services
	BLANCHE KATZ	Cole Information Services
	JAKI RIEGSECKER	Cole Information Services
	PARKRICH APARTMENTS	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2014	AFAGH AZIZI	Cole Information Services
	SKIPTON DRULIAS	Cole Information Services
	KEITH RUTHERFORD	Cole Information Services
	ROHAN SAINI	Cole Information Services
	ANDREW CRUTCHFIELD	Cole Information Services
	CINDIECLAIRE CRUZ	Cole Information Services
	SIMON EDWARDSSON	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	RAO JAYANT	Cole Information Services
	MICHAEL MACDONALD	Cole Information Services
	MONICA MARTIN	Cole Information Services
	DARRELL SORENSON	Cole Information Services
	LATISHA BRIGGS	Cole Information Services
	P SORENSEN	Cole Information Services
	THOMAS HEGARTY	Cole Information Services
	DAN KERR	Cole Information Services
	HERVEY LEE	Cole Information Services
	KRISTEN ANNIS	Cole Information Services
	BONNIE SARMIENTO	Cole Information Services
	DAVANH PHETKHAMCHANH	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	JOHN JANSEN	Cole Information Services
	BLANCHE KATZ	Cole Information Services
	JAKI RIEGSECKER	Cole Information Services
2009	HOIYI NG	Cole Information Services
	RAO JAYANT	Cole Information Services
	ALBERT KATZ	Cole Information Services
	ADRIAN MORALES	Cole Information Services
	BECKY BUNDY	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	GREGORY RONIN	Cole Information Services
	TAMRA ALLEN	Cole Information Services
	ROCIO BUSTILLO	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	EDMUND ASHBURNER	Cole Information Services
	CHRISTOPHER PROUNH	Cole Information Services
	JOELMA LAUER	Cole Information Services
	JESSICA LIU	Cole Information Services

FINDINGS

Year	Uses	Source
2009	ARMIN PARANG	Cole Information Services
	TSZYAN AUYEUNG	Cole Information Services
	LUCY CHENH	Cole Information Services
	MALONE TITO	Cole Information Services
	RAO JAYANT	Cole Information Services
	BECKY BUNDY	Cole Information Services
	MALONE TITO	Cole Information Services
	ALBERT KATZ	Cole Information Services
	ADRIAN MORALES	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	GREGORY RONIN	Cole Information Services
	TAMRA ALLEN	Cole Information Services
	ROCIO BUSTILLO	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	EDMUND ASHBURNER	Cole Information Services
	CHRISTOPHER PROUNH	Cole Information Services
	JOELMA LAUER	Cole Information Services
	ARMIN PARANG	Cole Information Services
	JESSICA LIU	Cole Information Services
	LUCY CHENH	Cole Information Services
	TSZYAN AUYEUNG	Cole Information Services
	HOIYI NG	Cole Information Services
2004	THE LEATHER CONNECTION	Cole Information Services
	JOHN BROZMAN	Cole Information Services
	DAVID SISSON	Cole Information Services
	ASUKA KINOSHITA	Cole Information Services
	DUANE LABES	Cole Information Services
	CONNIE JONG	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	GREGORY KNIGHT	Cole Information Services
	ROCHELLE STAMPER	Cole Information Services
	PAUL BURRI	Cole Information Services
	W MAHU	Cole Information Services
	THERESA HOWER	Cole Information Services
	LIONEL TERRY	Cole Information Services
	SHAAHIN ABDOLLAHI	Cole Information Services
	STEVE ALLEY	Cole Information Services
	KARENDELL LOGAN	Cole Information Services

FINDINGS

Year	Uses	Source
2004	NEELAM KUMARI	Cole Information Services
	JOELMA LAUER	Cole Information Services
	T BREMNER	Cole Information Services
	LAURA SCOTT	Cole Information Services
	ANDREW HORNE	Cole Information Services
	MARK MOLINA	Cole Information Services
	BARBARA MYKSIN	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	JOHN JANSEN	Cole Information Services
	GREEN MILL FILMWORKS	Cole Information Services
	THE LEATHER CONNECTION	Cole Information Services
	JOHN BROZMAN	Cole Information Services
	DAVID SISSON	Cole Information Services
	ASUKA KINOSHITA	Cole Information Services
	DUANE LABES	Cole Information Services
	CONNIE JONG	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	GREGORY KNIGHT	Cole Information Services
	W MAHU	Cole Information Services
	ROCHELLE STAMPER	Cole Information Services
	THERESA HOWER	Cole Information Services
	LIONEL TERRY	Cole Information Services
	PAUL BURRI	Cole Information Services
	SHAAHIN ABDOLLAHI	Cole Information Services
	STEVE ALLEY	Cole Information Services
	NEELAM KUMARI	Cole Information Services
	JOELMA LAUER	Cole Information Services
	KARENDELL LOGAN	Cole Information Services
	T BREMNER	Cole Information Services
	LAURA SCOTT	Cole Information Services
	ANDREW HORNE	Cole Information Services
	MARK MOLINA	Cole Information Services
	BARBARA MYKSIN	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	JOHN JANSEN	Cole Information Services
	GREEN MILL FILMWORKS	Cole Information Services
2001	APARTMENTS ALLEY SIeve	Haines Company, Inc.
	BRIGGSE	Haines Company, Inc.

FINDINGS

Year	Uses	Source
2001	CASSELPG	Haines Company, Inc.
	FIRSCHING Brian N	Haines Company, Inc.
	GRAYM	Haines Company, Inc.
	GREATMANCra Ig	Haines Company, Inc.
	GRIENERTifany Slar	Haines Company, Inc.
	GUGLi ELMELLIOavid L	Haines Company, Inc.
	KNIGHTGregory H	Haines Company, Inc.
	LABESDA	Haines Company, Inc.
	LOPEZAbraham ASr	Haines Company, Inc.
	OMCCARTHY Oobed MERCER Johnalan	Haines Company, Inc.
	MIMSShawn M	Haines Company, Inc.
	MYKSINB	Haines Company, Inc.
	RUGGIERIFAJr	Haines Company, Inc.
	SHEHAndres	Haines Company, Inc.
	SISSON Davrd 650 96 B 2956	Haines Company, Inc.
	SUSAKI Masami	Haines Company, Inc.
	TERRY Lionel Lamonl	Haines Company, Inc.
	TERRYLionel Lamoni	Haines Company, Inc.
	VAINSENCHER Kalra	Haines Company, Inc.
1999	EDMUND ASHBURNER	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	ROCIO BUSTILLO	Cole Information Services
	TAMRA ALLEN	Cole Information Services
	GREGORY RONIN	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	BECKY BUNDY	Cole Information Services
	P CASSEL	Cole Information Services
	ADRIAN MORALES	Cole Information Services
	ALBERT KATZ	Cole Information Services
	MALONE TITO	Cole Information Services
	RAO JAYANT	Cole Information Services
	HOIYI NG	Cole Information Services
	LUCY CHENH	Cole Information Services
	TSZYAN AUYEUNG	Cole Information Services
	ARMIN PARANG	Cole Information Services
	JESSICA LIU	Cole Information Services
	JOELMA LAUER	Cole Information Services
	CHRISTOPHER PROUNH	Cole Information Services

FINDINGS

Year	Uses	Source
1999	EDMUND ASHBURNER	Cole Information Services
	PHILIP CASSEL	Cole Information Services
	ROCIO BUSTILLO	Cole Information Services
	TAMRA ALLEN	Cole Information Services
	GREGORY RONIN	Cole Information Services
	BRIAN FIRSCHING	Cole Information Services
	ADRIAN MORALES	Cole Information Services
	ALBERT KATZ	Cole Information Services
	MALONE TITO	Cole Information Services
	RAO JAYANT	Cole Information Services
	HOIYI NG	Cole Information Services
	BECKY BUNDY	Cole Information Services
	P CASSEL	Cole Information Services
	TSZYAN AUYEUNG	Cole Information Services
	LUCY CHENH	Cole Information Services
	JESSICA LIU	Cole Information Services
	ARMIN PARANG	Cole Information Services
	JOELMA LAUER	Cole Information Services
	CHRISTOPHER PROUNH	Cole Information Services
1994	TREE WORKS	Cole Information Services
	GHAYOUMI, FARIBOR	Cole Information Services
	NEUHUYS, MICHELE	Cole Information Services
	FORGET, FRANCOI	Cole Information Services
	GRAY, M	Cole Information Services
	LUGGIERO, ANTHONY	Cole Information Services
	MOSCON, MICHAEL H	Cole Information Services
	TOUBLANC, DOMINIQ G	Cole Information Services
	OWENS, ROSS	Cole Information Services
	LUGOD, GALILEO	Cole Information Services
	YANG, HELEN	Cole Information Services
	RANDO, S	Cole Information Services
	MERCER, J	Cole Information Services
	TREE WORKS	Cole Information Services
	GHAYOUMI, FARIBOR	Cole Information Services
	NEUHUYS, MICHELE	Cole Information Services
	FORGET, FRANCOI	Cole Information Services
	GRAY, M	Cole Information Services
	MERCER, J	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
1994	MOSCON, MICHAEL H	Cole Information Services
	LUGGIERO, ANTHONY	Cole Information Services
	OWENS, ROSS	Cole Information Services
	LUGOD, GALILEO	Cole Information Services
	YANG, HELEN	Cole Information Services
	RANDO, S	Cole Information Services
	TOUBLANC, DOMINIQ G	Cole Information Services
1986	ALLEN GREGORY H	Pacific Bell
	APRIL ROBT E	Pacific Bell
	BOATWRIGHT RICHARD	Pacific Bell
	CANNON ROBT J	Pacific Bell
	CASSEL P G	Pacific Bell
	CRAWFORD J R	Pacific Bell
	EBY RW	Pacific Bell
	FELLHAUER HANS	Pacific Bell
	HALE M A	Pacific Bell
	HULLIFISH CHARLES	Pacific Bell
	JACKSON RICK	Pacific Bell
	MAJORS CHAS L	Pacific Bell
	MARTIN VINCENT	Pacific Bell
	MASTERS A	Pacific Bell
	MC GARRY TIMOTHY	Pacific Bell
	POWELL AUBRUN L	Pacific Bell
	RUGGIERI F A JR	Pacific Bell
	SEAVEY MERLE L	Pacific Bell
	STOKES ROBERT	Pacific Bell
	WORONICZ GEORGE	Pacific Bell
	Allen Gregory H	Pacific Bell
	April Robt E	Pacific Bell
	Boatwright Richard	Pacific Bell
	Cannon Robt J	Pacific Bell
	Cassel P G	Pacific Bell
	Crawford J R	Pacific Bell
	Eby RW	Pacific Bell
	Fellhauer Hans	Pacific Bell
	Hale M A	Pacific Bell
	Hullifish Charles	Pacific Bell
	Jackson Rick	Pacific Bell

FINDINGS

Year	*Uses*	*Source*
1986	Majors Chas L	Pacific Bell
	Martin Vincent	Pacific Bell
	Masters A	Pacific Bell
	Mc Garry Timothy	Pacific Bell
	Powell Bill	Pacific Bell
	Ruggieri F A Jr	Pacific Bell
	Seavey Merle L	Pacific Bell
	Stokes Robert	Pacific Bell
	Woronicz George	Pacific Bell
1982	Allen Gregory H	Pacific Telephone
	Berndt J	Pacific Telephone
	Bradt G C	Pacific Telephone
	Cannon Robt J	Pacific Telephone
	Cassel P G	Pacific Telephone
	Chen Douglas	Pacific Telephone
	Duffy Kevin	Pacific Telephone
	Erskine Timothy J	Pacific Telephone
	Ferguson L	Pacific Telephone
	Fleet Dick	Pacific Telephone
	Hansen W	Pacific Telephone
	Hanson Jas	Pacific Telephone
	Jackson Rick	Pacific Telephone
	Jones Greg	Pacific Telephone
	Keber Gus E	Pacific Telephone
	Majors Chas L	Pacific Telephone
	Martin Vincent	Pacific Telephone
	Mclntyre Jeff	Pacific Telephone
	Nielson Rex H	Pacific Telephone
	Powell W	Pacific Telephone
	Ruggieri F AJr	Pacific Telephone
	Sanders L J	Pacific Telephone
	Seavey Merle L	Pacific Telephone
	Stokes Robert	Pacific Telephone
	Tani Fred T	Pacific Telephone
1975	Guderjohn Robt	Pacific Telephone
	Hockberger Phillip	Pacific Telephone
	Johnstone W Parnell	Pacific Telephone
	KAISER CEMENT & GYPSUM CORPORATION	Pacific Telephone

FINDINGS

Year	Uses	Source
1975	Kaiser Jas E	Pacific Telephone
	Kwong M	Pacific Telephone
	Lilly Donald C	Pacific Telephone
	Lincoln Jas F	Pacific Telephone
	Lopez Henry Martin	Pacific Telephone
	Majors Chas L	Pacific Telephone
	Mc Caffrey K	Pacific Telephone
	Mudra Charlotte	Pacific Telephone
	Nunez Maria	Pacific Telephone
	Peters Lawrence F	Pacific Telephone
	Peterschmidt Greg A	Pacific Telephone
	Ramirez John	Pacific Telephone
	Riddell P E	Pacific Telephone
	Ruiderman Jerome	Pacific Telephone
	Ruggieri F A Jr	Pacific Telephone
	Stewart John M	Pacific Telephone
	Swett Geoffrey	Pacific Telephone
	Turner R M	Pacific Telephone
	Albert Emilie	Pacific Telephone
	Allen Gregory H	Pacific Telephone
	April Robt E	Pacific Telephone
	B a Banfield Jas E	Pacific Telephone
	Daniels David M	Pacific Telephone
	Donovan C	Pacific Telephone
	Fanucci P	Pacific Telephone
	Grogan Wm L	Pacific Telephone
1968	INCERTI MARION	R. L. Polk Co.
	NANCE MELVIN W	R. L. Polk Co.
	YAEGER CAROL A	R. L. Polk Co.
	OLSON ERI C	R. L. Polk Co.
	VIRAY LUISITA	R. L. Polk Co.
	MATTSON M DIANE	R. L. Polk Co.
	JOHNSON SCOTT D	R. L. Polk Co.
	YORENT ELIZ	R. L. Polk Co.
	DUNCAN GEO T	R. L. Polk Co.
	WELLMAN HARRY N	R. L. Polk Co.
	QUILICI CATHY	R. L. Polk Co.
	ALBERT EMMI	R. L. Polk Co.

FINDINGS

Year	Uses	Source
1968	DE JOHN BAPTISTE	R. L. Polk Co.
	BURGERT JEAN	R. L. Polk Co.
	JOHNSTONE WM P	R. L. Polk Co.
	DRAKE PAUL	R. L. Polk Co.
	HANSEN SHARON	R. L. Polk Co.
	SEEGFRIED CHARLES	R. L. Polk Co.
	SCHMIDT GERLINDE	R. L. Polk Co.
	PARK WEST APARTMENTS	R. L. Polk Co.
	HALSTEAD HENRY H	R. L. Polk Co.
	LAU GLENN	R. L. Polk Co.
	MUDRA CHARLOTTE MRS	R. L. Polk Co.
	JUNTTI HAROLD	R. L. Polk Co.
	SCHWILLING JOE E	R. L. Polk Co.
	MC EWER DICY	R. L. Polk Co.
	KASKI BEN	R. L. Polk Co.
	MAGLENTY RUDY	R. L. Polk Co.
	FERRARI DIANA	R. L. Polk Co.
	TCHRAKIAN PATK S	R. L. Polk Co.
	VACANT	R. L. Polk Co.
	PAULSON TERRY	R. L. Polk Co.
	k 2 LARSEN DAVID W	R. L. Polk Co.
	MORSE LINDA	R. L. Polk Co.
	CHUNG DAVID S	R. L. Polk Co.
	BROOKS H RANDALL	R. L. Polk Co.
	HUTCHINSON R	R. L. Polk Co.
	GANES THOS E	R. L. Polk Co.
	HABERMAN HERMAN	R. L. Polk Co.
	TINKER GORDON	R. L. Polk Co.
	LUCIDO FRANK	R. L. Polk Co.
	WALTER WM R	R. L. Polk Co.
	SCHRADER VALKIER H	R. L. Polk Co.
	SPRING HENRY H	R. L. Polk Co.
	MAJORS C L	R. L. Polk Co.
	BARRIE ROSE A	R. L. Polk Co.
	GIANOTTI GREGORY J	R. L. Polk Co.
	KEMP GEOFF K	R. L. Polk Co.
	LARRIEV DENNIE R	R. L. Polk Co.
	BURROUGHS GERALYN	R. L. Polk Co.

FINDINGS

Year	Uses	Source
1968	PHILIPPI CARL W	R. L. Polk Co.

1047 RICH AVE

Year	Uses	Source
2017	HENRIETTA SIH	Cole Information Services
	BRIAN KARABATS	Cole Information Services
	RHONDA REYES	Cole Information Services
	PRIYA KANU	Cole Information Services
	LEO WILKES	Cole Information Services
	MANMAYA TAMANG	Cole Information Services
	THACH NGUYEN	Cole Information Services
	VUJEN LAMA	Cole Information Services
	KHOA NGUYEN	Cole Information Services
	NICOLE MITCHELL	Cole Information Services
	NEIL ROGERS	Cole Information Services
2014	ELSA WILKES	Cole Information Services
	CELIA ROBLES	Cole Information Services
	JOSUE ROMERO	Cole Information Services
	GREG RABIROFF	Cole Information Services
	SANGEETA TAMANG	Cole Information Services
	MAKISI KALOAMATUNGI	Cole Information Services
	LOBSANG GYALTSEN	Cole Information Services
	JILLIAN MCLAUGHLIN	Cole Information Services
2009	KAREN JUAN	Cole Information Services
	DONALD LAM	Cole Information Services
	PATRRICIA MARTINEZ	Cole Information Services
	BRIAN KARABATS	Cole Information Services
2004	JAVIER VEGA	Cole Information Services
	SAUL MORALES	Cole Information Services
	EVA BASTIDA	Cole Information Services
	RONNIE PERKINS	Cole Information Services
	JOHN BLASE	Cole Information Services
	XIAOHONG ZHENG	Cole Information Services
	CELIA ROBLES	Cole Information Services
2001	APARTMENTS GARDNERHe Arb	Haines Company, Inc.
	GOMEZElva	Haines Company, Inc.
	HERNANDEZZoila	Haines Company, Inc.
	NAWBATT Leila E	Haines Company, Inc.
	GSHUEHHenrre Oa YANG Guang Hong	Haines Company, Inc.

FINDINGS

Year	Uses	Source
1999	PATRRICIA MARTINEZ	Cole Information Services
	BRIAN KARABATS	Cole Information Services
	KAREN JUAN	Cole Information Services
	DONALD LAM	Cole Information Services
1994	RYU, HYUNTA	Cole Information Services
1986	ARIAS ROSEALLNDA	Pacific Bell
	FUENTES JUAN E	Pacific Bell
	PERCHIA BILLIE JO	Pacific Bell
	PHONG PHU	Pacific Bell
	TRUONG VAN	Pacific Bell
	VILLARUEL ROLANDO	Pacific Bell
	YANGI KICHARD	Pacific Bell
	AYLARD VERN E	Pacific Bell
	Arias Roseallnda	Pacific Bell
	Aylard Vern E	Pacific Bell
	Fuentes Juan E	Pacific Bell
	Perchia Billie Jo	Pacific Bell
	Phong Phu	Pacific Bell
	Truong Van	Pacific Bell
	Villaruel Rolando	Pacific Bell
	Yangi Kichard	Pacific Bell
1982	Aylard Vern E	Pacific Telephone
	Bracken Kevin S	Pacific Telephone
	Duarte Raymond	Pacific Telephone
	DU ALL PRECISION MACHINING &	Pacific Telephone
	Huth John H	Pacific Telephone
	Rice Peter V	Pacific Telephone
	Rickard S	Pacific Telephone
	Rolas Alexander	Pacific Telephone
	Soderquist Steven M	Pacific Telephone
1975	Slawik Geo A	Pacific Telephone
	Slavinskis Peteris E	Pacific Telephone
	Rickard S	Pacific Telephone
	Raymann Dan I T	Pacific Telephone
	Aylard Vern E	Pacific Telephone
	De Wolf Geo	Pacific Telephone
	Fuentes Juan	Pacific Telephone
	Huth John H	Pacific Telephone

FINDINGS

Year	Uses	Source
1975	Janotiis Ken	Pacific Telephone
1968	JOHNSON JO ANN MRS	R. L. Polk Co.
	VACANT	R. L. Polk Co.
	PHILLIP ANITA	R. L. Polk Co.
	BLICKENSOERFER J	R. L. Polk Co.
	BRUFF FLOSSIE	R. L. Polk Co.
	ESPRIELIA L	R. L. Polk Co.
	PRICE RICK	R. L. Polk Co.
	HAGOOD C	R. L. Polk Co.
	SYSIN A P	R. L. Polk Co.
	NO RETURN	R. L. Polk Co.
	ANO A	R. L. Polk Co.
	REIS D	R. L. Polk Co.
	CLARK G L	R. L. Polk Co.
	SLAWIK GEO A	R. L. Polk Co.
	APARTMENTS	R. L. Polk Co.

1049 RICH AVE

Year	Uses	Source
1999	OCCUPANT UNKNOWN	Cole Information Services

1077 RICH AVE

Year	Uses	Source
2017	STEVE SHISLER	Cole Information Services
	NIKHIL NAIR	Cole Information Services
	LAURA VONKAMPEN	Cole Information Services
2014	SALLY MENDIOLA	Cole Information Services
	STEVE SHISLER	Cole Information Services
	NIKHIL NAIR	Cole Information Services
	STEVEN CURTIS	Cole Information Services
	CHRISTINA RVDOLL	Cole Information Services
2009	STEVE SHISLER	Cole Information Services
	STEVEN CURTIS	Cole Information Services
2004	STEVE MEININGER	Cole Information Services
2001	RUSH Shawn	Haines Company, Inc.
	OFRYKMAN Evelyn MEININGER Sleve M	Haines Company, Inc.
1999	STEVEN CURTIS	Cole Information Services
	STEVE SHISLER	Cole Information Services
1986	Spivey Ron	Pacific Bell

Year	Uses	Source
1986	SPIVEY RON	Pacific Bell
1975	Upton Blake	Pacific Telephone
	Doubleday J	Pacific Telephone
	Bartholomew Robt L	Pacific Telephone
1968	GIFFIN LAURA E	R. L. Polk Co.
	APARTMENTS	R. L. Polk Co.
	ANDREWS SPENCER B	R. L. Polk Co.
	ROSIA C E	R. L. Polk Co.
	HANCOCK HAROLD C	R. L. Polk Co.
	WAGNER LARRY	R. L. Polk Co.

Rich Avenue

912 Rich Avenue

Year	Uses	Source
2001	RICHAVAPTS BABANorman N	Haines Company, Inc.
	BUSBY H	Haines Company, Inc.
	FAULKNOR George	Haines Company, Inc.
	SGALLOPaul MCCOYJim	Haines Company, Inc.
	MIKEC vica	Haines Company, Inc.
	RICH AVENUE	Haines Company, Inc.
1991	Contd	Pacific Telephone
1986	Barriga Humberto	Pacific Bell
	Eggers Harold W	Pacific Bell
	Lee Diane	Pacific Bell
	Piller J E	Pacific Bell
	BARRIGA HUMBERTO	Pacific Bell
	EGGERS HAROLD W	Pacific Bell
	KENDALL P	Pacific Bell
	LEE DIANE	Pacific Bell
	PILLER J E	Pacific Bell
1982	Carter David M	Pacific Telephone
	Loggins CD	Pacific Telephone
	Pfenninger Johannes	Pacific Telephone
	Piler JE	Pacific Telephone
	Rosskopf Kathy A	Pacific Telephone
	Works FH	Pacific Telephone
1975	Halterman Chas G	Pacific Telephone
	Kennedy C	Pacific Telephone

FINDINGS

Year	Uses	Source
1975	Lemke Jos	Pacific Telephone
	Oglesbee RW	Pacific Telephone
	Sturgeon Fraiaces	Pacific Telephone
	Sturgeon H B	Pacific Telephone
	Uh Hong Sun	Pacific Telephone
1968	APARTMENTS	R. L. Polk Co.
	STURGEON H B	R. L. Polk Co.
	GERARD JAMES	R. L. Polk Co.
	GRATON I S	R. L. Polk Co.
	MACHNICK J JR	R. L. Polk Co.
	NAIL ORVAL	R. L. Polk Co.
	SUMMERFIELD L	R. L. Polk Co.
	NEVINS RON	R. L. Polk Co.
	TRESSEL RONALD	R. L. Polk Co.
	SWANSON CRAIG H	R. L. Polk Co.
1962	STAFFORD PAUL E (MAUREEN A) DRFTSMN LOCKHEED	R. L. Polk & Co.

959 Rich Avenue

Year	Uses	Source
2001	APARTMENTS ALLEY Sleve	Haines Company, Inc.
	BRIGGSE	Haines Company, Inc.
	CASSELPG	Haines Company, Inc.
	FIRSCHING Brian N	Haines Company, Inc.
	GRAYM	Haines Company, Inc.
	GREATMANCra Ig	Haines Company, Inc.
	GRIENERTifany Slar	Haines Company, Inc.
	GUGLi ELMELLIOavid L	Haines Company, Inc.
	KNIGHTGregory H	Haines Company, Inc.
	LABESDA	Haines Company, Inc.
	LOPEZAbraham ASr	Haines Company, Inc.
	OMCCARTHY Oobed MERCER Johnalan	Haines Company, Inc.
	MIMSShawn M	Haines Company, Inc.
	MYKSINB	Haines Company, Inc.
	RUGGIERIFAJr	Haines Company, Inc.
	SHEHAndres	Haines Company, Inc.
	SISSON Davrd 650 96 B 2956	Haines Company, Inc.
	SUSAKI Masami	Haines Company, Inc.
	TERRY Lionel Lamonl	Haines Company, Inc.

FINDINGS

Year	Uses	Source
2001	TERRYLionel Lamoni	Haines Company, Inc.
	VAINSENCHER Kalra	Haines Company, Inc.
1986	Allen Gregory H	Pacific Bell
	April Robt E	Pacific Bell
	Boatwright Richard	Pacific Bell
	Cannon Robt J	Pacific Bell
	Cassel P G	Pacific Bell
	Crawford J R	Pacific Bell
	Eby RW	Pacific Bell
	Fellhauer Hans	Pacific Bell
	Hale M A	Pacific Bell
	Hullifish Charles	Pacific Bell
	Jackson Rick	Pacific Bell
	Majors Chas L	Pacific Bell
	Martin Vincent	Pacific Bell
	Masters A	Pacific Bell
	Mc Garry Timothy	Pacific Bell
	Powell Bill	Pacific Bell
	Ruggieri F A Jr	Pacific Bell
	Seavey Merle L	Pacific Bell
	Stokes Robert	Pacific Bell
	Woronicz George	Pacific Bell
	ALLEN GREGORY H	Pacific Bell
	APRIL ROBT E	Pacific Bell
	BOATWRIGHT RICHARD	Pacific Bell
	CANNON ROBT J	Pacific Bell
	CASSEL P G	Pacific Bell
	CRAWFORD J R	Pacific Bell
	EBY RW	Pacific Bell
	FELLHAUER HANS	Pacific Bell
	HALE M A	Pacific Bell
	HULLIFISH CHARLES	Pacific Bell
	JACKSON RICK	Pacific Bell
	MAJORS CHAS L	Pacific Bell
	MARTIN VINCENT	Pacific Bell
	MASTERS A	Pacific Bell
	MC GARRY TIMOTHY	Pacific Bell
	POWELL AUBRUN L	Pacific Bell

FINDINGS

Year	Uses	Source
1986	RUGGIERI F A JR	Pacific Bell
	SEAVEY MERLE L	Pacific Bell
	STOKES ROBERT	Pacific Bell
	WORONICZ GEORGE	Pacific Bell
1982	Allen Gregory H	Pacific Telephone
	Berndt J	Pacific Telephone
	Bradt G C	Pacific Telephone
	Cannon Robt J	Pacific Telephone
	Cassel P G	Pacific Telephone
	Chen Douglas	Pacific Telephone
	Duffy Kevin	Pacific Telephone
	Erskine Timothy J	Pacific Telephone
	Ferguson L	Pacific Telephone
	Fleet Dick	Pacific Telephone
	Hansen W	Pacific Telephone
	Hanson Jas	Pacific Telephone
	Jackson Rick	Pacific Telephone
	Jones Greg	Pacific Telephone
	Keber Gus E	Pacific Telephone
	Majors Chas L	Pacific Telephone
	Martin Vincent	Pacific Telephone
	Mclntyre Jeff	Pacific Telephone
	Nielson Rex H	Pacific Telephone
	Powell W	Pacific Telephone
	Ruggieri F AJr	Pacific Telephone
	Sanders L J	Pacific Telephone
	Seavey Merle L	Pacific Telephone
	Stokes Robert	Pacific Telephone
	Tani Fred T	Pacific Telephone
1975	Sears M	Pacific Telephone
	Albert Emilie	Pacific Telephone
	Allen Gregory H	Pacific Telephone
	April Robt E	Pacific Telephone
	B a Banfield Jas E	Pacific Telephone
	Daniels David M	Pacific Telephone
	Donovan C	Pacific Telephone
	Fanucci P	Pacific Telephone
	Grogan Wm L	Pacific Telephone

FINDINGS

Year	Uses	Source
1975	Guderjohn Robt	Pacific Telephone
	Hockberger Phillip	Pacific Telephone
	Johnstone W Parnell	Pacific Telephone
	Kaiser Jas E	Pacific Telephone
	KAISER CEMENT & GYPSUM CORPORATION	Pacific Telephone
	Kwong M	Pacific Telephone
	Lilly Donald C	Pacific Telephone
	Lincoln Jas F	Pacific Telephone
	Lopez Henry Martin	Pacific Telephone
	Majors Chas L	Pacific Telephone
	Mc Caffrey K	Pacific Telephone
	Mudra Charlotte	Pacific Telephone
	Nunez Maria	Pacific Telephone
	Peters Lawrence F	Pacific Telephone
	Peterschmidt Greg A	Pacific Telephone
	Ramirez John	Pacific Telephone
	Riddell P E	Pacific Telephone
	Ruiderman Jerome	Pacific Telephone
	Ruggieri F A Jr	Pacific Telephone
	Stewart John M	Pacific Telephone
	Swett Geoffrey	Pacific Telephone
	Turner R M	Pacific Telephone
1968	PARK WEST APARTMENTS	R. L. Polk Co.
	HALSTEAD HENRY H	R. L. Polk Co.
	LAU GLENN	R. L. Polk Co.
	MUDRA CHARLOTTE MRS	R. L. Polk Co.
	JUNTTI HAROLD	R. L. Polk Co.
	SCHWILLING JOE E	R. L. Polk Co.
	MC EWER DICY	R. L. Polk Co.
	KASKI BEN	R. L. Polk Co.
	MAGLENTY RUDY	R. L. Polk Co.
	FERRARI DIANA	R. L. Polk Co.
	TCHRAKIAN PATK S	R. L. Polk Co.
	VACANT	R. L. Polk Co.
	PAULSON TERRY	R. L. Polk Co.
	k 2 LARSEN DAVID W	R. L. Polk Co.
	MORSE LINDA	R. L. Polk Co.
	CHUNG DAVID S	R. L. Polk Co.

FINDINGS

Year	Uses	Source
1968	BROOKS H RANDALL	R. L. Polk Co.
	HUTCHINSON R	R. L. Polk Co.
	GANES THOS E	R. L. Polk Co.
	HABERMAN HERMAN	R. L. Polk Co.
	TINKER GORDON	R. L. Polk Co.
	LUCIDO FRANK	R. L. Polk Co.
	WALTER WM R	R. L. Polk Co.
	SCHRADER VALKIER H	R. L. Polk Co.
	SPRING HENRY H	R. L. Polk Co.
	MAJORS C L	R. L. Polk Co.
	BARRIE ROSE A	R. L. Polk Co.
	GIANOTTI GREGORY J	R. L. Polk Co.
	KEMP GEOFF K	R. L. Polk Co.
	LARRIEV DENNIE R	R. L. Polk Co.
	BURROUGHS GERALYN	R. L. Polk Co.
	PHILIPPI CARL W	R. L. Polk Co.
	INCERTI MARION	R. L. Polk Co.
	NANCE MELVIN W	R. L. Polk Co.
	YAEGER CAROL A	R. L. Polk Co.
	OLSON ERI C	R. L. Polk Co.
	VIRAY LUISITA	R. L. Polk Co.
	MATTSON M DIANE	R. L. Polk Co.
	JOHNSON SCOTT D	R. L. Polk Co.
	YORENT ELIZ	R. L. Polk Co.
	DUNCAN GEO T	R. L. Polk Co.
	WELLMAN HARRY N	R. L. Polk Co.
	QUILICI CATHY	R. L. Polk Co.
	ALBERT EMMI	R. L. Polk Co.
	DE JOHN BAPTISTE	R. L. Polk Co.
	BURGERT JEAN	R. L. Polk Co.
	JOHNSTONE WM P	R. L. Polk Co.
	DRAKE PAUL	R. L. Polk Co.
	HANSEN SHARON	R. L. Polk Co.
	SEEGFRIED CHARLES	R. L. Polk Co.
	SCHMIDT GERLINDE	R. L. Polk Co.

RICH PL

932 RICH PL

Year	Uses	Source
2001	ABEHirami	Haines Company, Inc.

934 RICH PL

Year	Uses	Source
2001	GBRATTHarry	Haines Company, Inc.
	GBRATTElizabelh	Haines Company, Inc.

940 RICH PL

Year	Uses	Source
2001	STRAPPESco S	Haines Company, Inc.

W EL CAMINO REAL

1495 W EL CAMINO REAL

Year	Uses	Source
2017	WILLMAN CARRIE & LAWSON BROS CARPET	Cole Information Services
	A SEQUOIA EMERGENCY WATER RESTORATIO	Cole Information Services
	THE RUG CENTER	Cole Information Services
	BRAZILIAN JIUJITSU INC	Cole Information Services
2014	CHARLENE LOCKE	Cole Information Services
	A SEQUOIA EMERGENCY WATER RESTORATIO	Cole Information Services
	SEQUOIA RUG CLEANERS	Cole Information Services
	RALPH GARCIE JIUJITSU	Cole Information Services
	WILLMAN CARRIE & LAWSON BROS CARPET	Cole Information Services
	GRACIE JIUJITSU	Cole Information Services
	LAWSON BROS CARPET RUG DRAPERY & UP	Cole Information Services
2009	BRAZILIAN JIU JITSU INC	Cole Information Services
	CARRIE WILLMAN & LAWSON BROTHERS	Cole Information Services
	SEQUOIA CARPET RUG UPHOLSTERY & DRAP	Cole Information Services
	SEQUOIA CLEANING INC	Cole Information Services
2004	LWSN BRTHR CRPT & UPHLSTRY CLN	Cole Information Services
	WILLMAN CARRIE & LAWSON BRTHR	Cole Information Services

FINDINGS

Year	Uses	Source
2001	ASEQUOIAEMER	Haines Company, Inc.
	CARPET&UPHOL CLNRS SEOUOIACRPTRG	Haines Company, Inc.
	UPHL 4 DRPRY WILLMANC&LAWSON	Haines Company, Inc.
	BROSCRPTRUG	Haines Company, Inc.
	CARPET&UPHOL CLNRS LAWSONBROS	Haines Company, Inc.
	GUASCHJames LAWSONBROS	Haines Company, Inc.
	JUJITSU	Haines Company, Inc.
	GRACIESYSTEMS	Haines Company, Inc.
	WATER RSTRTN BRAZILIANJIU JITSU	Haines Company, Inc.
1999	BRAZILIAN JUJITSU INCORPORATED	Cole Information Services
	LAWSON BROTHERS CPT RUG DRAP & UPHOLSTERY CLEANERS	Cole Information Services
	GRACIE SYSTEMS JIU JITSU	Cole Information Services
	SEQUOIA CARPET RUG UPHOLSTERY & DRAPERY CLEANERS	Cole Information Services
	WILLMAN CARRIE & LAWSON BROTHERS CPT RUG DRAP & UPHLS	Cole Information Services
	GRACIE SYSTEMS JUJITSU	Cole Information Services
1994	MARCO ROMERO FITNESS & DANCE	Cole Information Services
	MOSES FERRERS KARATE	Cole Information Services
1975	MC LEOD GLASS CO	Pacific Telephone

1513 W EL CAMINO REAL

Year	Uses	Source
2001	XXXX	Haines Company, Inc.

1544 W EL CAMINO REAL

Year	Uses	Source
2017	FOREIGN AUTO REPAIR	Cole Information Services
	A1 FOREIGN AUTO REPAIR	Cole Information Services
2014	A1 FOREIGN AUTO	Cole Information Services
	FOREIGN AUTO REPAIR	Cole Information Services
2009	A1 FOREIGN AUTO	Cole Information Services
2004	JOHN KELEMEN	Cole Information Services
	A 1 FOREIGN AUTO	Cole Information Services
	FORIEGN AUTO REPAIR	Cole Information Services
2001	FOREIGN AUTO REPAIR	Haines Company, Inc.
	A 1 FRGNAUTORPR	Haines Company, Inc.
	KELEMENJohn	Haines Company, Inc.

FINDINGS

Year	Uses	Source
1999	A 1 FOREIGN AUTO REPAIR	Cole Information Services
	FORIEGN AUTO REPAIR	Cole Information Services
1994	A 1 FOREIGN AUTO REPAIR & PART	Cole Information Services
1982	Internationnll Auto Body Inc	Pacific Telephone

1560 W EL CAMINO REAL

Year	Uses	Source
2001	XXXX	Haines Company, Inc.

1561 W EL CAMINO REAL

Year	Uses	Source
2017	AFFORDABLE TV REPAIR	Cole Information Services
	HOLIDAY INN EXPRESS MOUNTAIN VIEWS	Cole Information Services
	COMFORT INN	Cole Information Services
2014	HOLIDAY INN EXPRESS MOUNTAIN VIEW	Cole Information Services
	COMFORT INN MOUNTAIN VIEW	Cole Information Services
2009	COMFORT INN	Cole Information Services
	CHIRAG INVESTMENT CO	Cole Information Services
2004	COMFORT INN	Cole Information Services
2001	COMFORTINN	Haines Company, Inc.
	COMFORTINN	Haines Company, Inc.
1999	COMFORT INN	Cole Information Services
1994	COMFORT INN	Cole Information Services
1975	ROBLEDA PACKING CO	Pacific Telephone

1564 W EL CAMINO REAL

Year	Uses	Source
2009	TERRY MORROW	Cole Information Services
1999	TERRY MORROW	Cole Information Services

1571 W EL CAMINO REAL

Year	Uses	Source
2017	FLAVIA SEQUEIRA	Cole Information Services
	LORI SCHMID	Cole Information Services
	SHORELINE VILLAGE APARTMENTS	Cole Information Services
	HIDDEN GARDEN APARTMENTS	Cole Information Services
	AKI NAKAMURA	Cole Information Services
	DEREK WILMARTH	Cole Information Services
	GRACIELA GOMEZ	Cole Information Services

FINDINGS

Year	Uses	Source
2017	WALIDAH IMARISHA	Cole Information Services
	SOMASUNDARI KUPPUSAMY	Cole Information Services
	JUSTIN SMITH	Cole Information Services
	XIMING WANG	Cole Information Services
	JOSE CALLIRGOS	Cole Information Services
	MARK GALU	Cole Information Services
	MARIE JOHNSON	Cole Information Services
	TOM MARGETIS	Cole Information Services
	DHANYA MATHEW	Cole Information Services
	KEISUKE NISHIMOTO	Cole Information Services
	NAINA THANGARAJ	Cole Information Services
	JAMES DALTON	Cole Information Services
	RITWICK GHOSH	Cole Information Services
	LARRY MARCUSON	Cole Information Services
	JOSEPHINE ROBINSON	Cole Information Services
	KAR LUM	Cole Information Services
	SANDRA UNTHANK	Cole Information Services
	JASON VICE	Cole Information Services
	BRUCE WONG	Cole Information Services
	ARLEEN KOONTZ	Cole Information Services
	LAURA LINE	Cole Information Services
	PAT MCGARRY	Cole Information Services
	MARIA TORRE	Cole Information Services
	MARIA WOJAKOWSKI	Cole Information Services
	CATHY HUSTON	Cole Information Services
	LYNN PETERSON	Cole Information Services
	POOJA SHASTRY	Cole Information Services
	JOSEPHINE VINCENT	Cole Information Services
	URVASHI REDDY	Cole Information Services
	DEBBIE BESSON	Cole Information Services
	VIRGINIA CHAN	Cole Information Services
	JOHN PORTER	Cole Information Services
	CHEN ZHANG	Cole Information Services
2014	HIDDEN GARDEN APARTMENTS	Cole Information Services
	AARON WILSON	Cole Information Services
	PRISCILA MIGLIORINI	Cole Information Services
	MICHELLE ROBINSON	Cole Information Services
	SAMANTHA HOUANGVILAY	Cole Information Services

FINDINGS

Year	Uses	Source
2014	JUNE FONSECA	Cole Information Services
	STEVEN HERRIN	Cole Information Services
	MICHELLE MCMANIGILL	Cole Information Services
	FRANK DOWSE	Cole Information Services
	MARIA WOJAKOWSKI	Cole Information Services
	ANDREW ROBERTSON	Cole Information Services
	BETTY CHAO	Cole Information Services
	BRETT HICKOK	Cole Information Services
	CATHY HUSTON	Cole Information Services
	JUDY WILKINS	Cole Information Services
	LYNN PETERSON	Cole Information Services
	EDWARD ROUNDS	Cole Information Services
	DEBBIE BESSON	Cole Information Services
	ERIN DARING	Cole Information Services
	STEPHANIE HANSON	Cole Information Services
	FLAVIA SEQUEIRA	Cole Information Services
	FERDY PALMA	Cole Information Services
	URVASHI REDDY	Cole Information Services
	XIAOMIN YUAN	Cole Information Services
	MARION JOHNSON	Cole Information Services
	AKI NAKAMURA	Cole Information Services
	BRENT REMMERT	Cole Information Services
	PIROUZ ZARRINKHAT	Cole Information Services
	GENEVIEVE LARON	Cole Information Services
	LUCIA MARTINEZ	Cole Information Services
	HAN ZHOU	Cole Information Services
	SCHMITT SOMBAT	Cole Information Services
	IAN KLIER	Cole Information Services
	JAMES DALTON	Cole Information Services
	MARY LANOZA	Cole Information Services
2009	AKI NAKAMURA	Cole Information Services
	ALLEN M LEE A PROFESSIONAL LAW	Cole Information Services
	JASSON SCHROCK	Cole Information Services
	TERRY KLINE	Cole Information Services
	LOISE DARING	Cole Information Services
	LEE ALLEN	Cole Information Services
	RUSSELL KASHIAN	Cole Information Services
	CHANDRA HALL	Cole Information Services

FINDINGS

Year	*Uses*	*Source*
2009	RICHARD LIEBERMAN	Cole Information Services
	CHERIF ABBES	Cole Information Services
	MICHELLE ROBINSON	Cole Information Services
	LARRY MARCUSON	Cole Information Services
	NIDIA SORTO	Cole Information Services
	DONALD MANCINI	Cole Information Services
	PETER MCCLUSKEY	Cole Information Services
	MARILYN VANGASTEL	Cole Information Services
	ISIDRO RUIZ	Cole Information Services
	TAMARA DANOYAN	Cole Information Services
	MELISSA CASTRO	Cole Information Services
	WILLIAM MAHONEY	Cole Information Services
	JANET LAMB	Cole Information Services
	CATHERINE MEGILL	Cole Information Services
	KAZUE MILLER	Cole Information Services
	JAVIER HERNANDEZ	Cole Information Services
	CATHY HUSTON	Cole Information Services
	LYNN PETERSON	Cole Information Services
	RICARDO BEAS	Cole Information Services
	ALLEN LEE	Cole Information Services
	FLAVIA SEQUEIRA	Cole Information Services
	URVASHI REDDY	Cole Information Services
	JACQUELINE LUNA	Cole Information Services
	TERESA YOUNG	Cole Information Services
	DEBBIE BESSON	Cole Information Services
	SHARON GRIZEY	Cole Information Services
2004	CALLUM MCARTHUR	Cole Information Services
	TRINIDAD AMEZCUA	Cole Information Services
	YEADI SURUKANTI	Cole Information Services
	MICHEL HINTON	Cole Information Services
	CATHY HUSTON	Cole Information Services
	MICHAEL GEBRETSADIK	Cole Information Services
	JUAN CASTRO	Cole Information Services
	LYNN PETERSON	Cole Information Services
	DAVE ZIEGLER	Cole Information Services
	ELIZA KELLY	Cole Information Services
	MALIK MUHAMMAD	Cole Information Services
	FLAVIA SEQUEIRA	Cole Information Services

FINDINGS

Year	Uses	Source
2004	AMIR RIAZ	Cole Information Services
	BRIAN RODRIGUES	Cole Information Services
	CHRISTINA HERNANDEZ	Cole Information Services
	ANIL BANARIYA	Cole Information Services
	LEATHER COSAS	Cole Information Services
	A2WIN PRO	Cole Information Services
	CARLOS RIEGLER	Cole Information Services
	STEPHEN TAYLOR	Cole Information Services
	CRISTINA GARCIA	Cole Information Services
	AKI NAKAMURA	Cole Information Services
	HEATHER BRADY	Cole Information Services
	YUNLEI DUAN	Cole Information Services
	KERWIN KASSULKER	Cole Information Services
	KENTARO OZAKI	Cole Information Services
	LILY ESPINOZA	Cole Information Services
	MICHAEL LUNDAY	Cole Information Services
	M POGAN	Cole Information Services
	HUGO VERGARA	Cole Information Services
	DAVID AZCUETA	Cole Information Services
	RAMA SATRABINA	Cole Information Services
	ANNA TROGEN	Cole Information Services
	DARRYL TALBOT	Cole Information Services
	RICHARD LIEBERMAN	Cole Information Services
	DANIEL WHITE	Cole Information Services
	A BROWN	Cole Information Services
	MARIE ALI	Cole Information Services
	A AGUILAR	Cole Information Services
	LARRY MARCUSON	Cole Information Services
	SANTOSH KUMAR	Cole Information Services
	SYLVIE FIRESTONE	Cole Information Services
	ALYSSA ROSSO	Cole Information Services
	BITEW TISASE	Cole Information Services
	KAHO TAM	Cole Information Services
	PAULA GOMEZ	Cole Information Services
	BOBBY GEORGE	Cole Information Services
	SAIA LEAFA	Cole Information Services
	JULIO PECOS	Cole Information Services
	PETER MCCLUSKEY	Cole Information Services

FINDINGS

Year	Uses	Source
2004	DOROTHY GLUSKER	Cole Information Services
	HONG DUAN	Cole Information Services
	GREG MALVEAUX	Cole Information Services
	PATRICIA SKEGGS	Cole Information Services
	MARK THOMAS	Cole Information Services
	RAKESH PANCHAL	Cole Information Services
	D PETRI	Cole Information Services
	CISSY JONES	Cole Information Services
	RAMA SATRABOINA	Cole Information Services
2001	SHRIVER Krslen	Haines Company, Inc.
	SASAKI Galen H	Haines Company, Inc.
	PETERSONLynn	Haines Company, Inc.
	PEREZMartin	Haines Company, Inc.
	MEDINA Maria Drana	Haines Company, Inc.
	MCCLUSKEY Peter	Haines Company, Inc.
	MODISanlay	Haines Company, Inc.
	HIDDEN GARDEN APTS AMAHENDRA	Haines Company, Inc.
	Muppalaneni B AMEZCA Trinidad	Haines Company, Inc.
	CHAKRABORTYParag	Haines Company, Inc.
	CHIEUNG Harry	Haines Company, Inc.
	DOLOVITCHENYJLadlsl 6 SO	Haines Company, Inc.
	FAHNANSTIELJOhnr E	Haines Company, Inc.
	FALCONich	Haines Company, Inc.
	FATEMI Alshin	Haines Company, Inc.
	GARCIACnslila	Haines Company, Inc.
	GULERIAAlay	Haines Company, Inc.
	GUOingchun	Haines Company, Inc.
	HERNANDEY Michael	Haines Company, Inc.
	HIDDEN GARDEN	Haines Company, Inc.
	IDAShinrchi	Haines Company, Inc.
	JARAMILLOJul Ian	Haines Company, Inc.
	KH 06 Vijay	Haines Company, Inc.
	LASHGARI Kamran	Haines Company, Inc.
	LEDEZMA Henberdo	Haines Company, Inc.
	MALVEAUXGreg	Haines Company, Inc.
	MALVEAUXGOe O	Haines Company, Inc.
	MAHOMUD MS	Haines Company, Inc.
	MANZANO Isabel	Haines Company, Inc.

FINDINGS

Year	Uses	Source
2001	Panavol ZHANG Yonglrang	Haines Company, Inc.
	YOUNGYUNPITATKUL	Haines Company, Inc.
	TALBOTDarryl	Haines Company, Inc.
	SURUKANTIYeadi	Haines Company, Inc.
	SURUKANTIYadi R	Haines Company, Inc.
1999	CAMINO PARK APARTMENTS	Cole Information Services
	DAS SATYEN	Cole Information Services
	DEBBIE BESSON	Cole Information Services
	TERESA YOUNG	Cole Information Services
	JACQUELINE LUNA	Cole Information Services
	URVASHI REDDY	Cole Information Services
	FLAVIA SEQUEIRA	Cole Information Services
	ALLEN LEE	Cole Information Services
	RICARDO BEAS	Cole Information Services
	LYNN PETERSON	Cole Information Services
	CATHY HUSTON	Cole Information Services
	JAVIER HERNANDEZ	Cole Information Services
	KAZUE MILLER	Cole Information Services
	CATHERINE MEGILL	Cole Information Services
	PARIS MANNION	Cole Information Services
	JANET LAMB	Cole Information Services
	WILLIAM MAHONEY	Cole Information Services
	MELISSA CASTRO	Cole Information Services
	TAMARA DANOYAN	Cole Information Services
	ISIDRO RUIZ	Cole Information Services
	AKI NAKAMURA	Cole Information Services
	JASSON SCHROCK	Cole Information Services
	TERRY KLINE	Cole Information Services
	LOISE DARING	Cole Information Services
	SHARON GRIZEY	Cole Information Services
	LEE ALLEN	Cole Information Services
	RUSSELL KASHIAN	Cole Information Services
	CHANDRA HALL	Cole Information Services
	RICHARD LIEBERMAN	Cole Information Services
	CHERIF ABBES	Cole Information Services
	LARRY MARCUSON	Cole Information Services
	NIDIA SORTO	Cole Information Services
	MICHELLE ROBINSON	Cole Information Services

FINDINGS

Year	Uses	Source
1999	DONALD MANCINI	Cole Information Services
	PETER MCCLUSKEY	Cole Information Services
	MARILYN VANGASTEL	Cole Information Services
1994	EASOW, JOSHUA	Cole Information Services
	FARSHIAN, MAHMOUD A	Cole Information Services
	JOHNSON, ENA C	Cole Information Services
	CHO, RAE	Cole Information Services
	CAMINO PARK APARTMENTS	Cole Information Services
	FAHNANSTIEL, JOHN E	Cole Information Services
	ANTON, KC	Cole Information Services
	SAUNDERS, DONNA	Cole Information Services
	CONNORS, PATRICK	Cole Information Services
	BRIDGES, DEREK	Cole Information Services
1982	Bitot DM	Pacific Telephone
	Belotaky William A Wilhelm Thompson Wentholt &	Pacific Telephone
1975	Brindley Robt	Pacific Telephone
	Burke Brian D	Pacific Telephone
	CAMINO PARK APARTMENTS	Pacific Telephone
	Drake J	Pacific Telephone
	Green B	Pacific Telephone
	Hall G C	Pacific Telephone
	Matt A David	Pacific Telephone
	Usher T R	Pacific Telephone

1580 W EL CAMINO REAL

Year	Uses	Source
2017	SOCIOMETRICS CORP	Cole Information Services
	ZICASSO	Cole Information Services
	AMY YENPING LEE DDS	Cole Information Services
	MCCALLUM W D MD INC	Cole Information Services
	CHIROPRACTIC	Cole Information Services
	BFS LANDSCAPE ARCHITECTS	Cole Information Services
	AMY LEE DDS	Cole Information Services
	BOCEK & ASSOCIATES CPA	Cole Information Services
	LU JENNY C DDS FAMILY DENTISTRY	Cole Information Services
	RAJ ABHYANKER	Cole Information Services
2014	MCCALLUM W D MD INC	Cole Information Services
	YEH MING DDS PHD	Cole Information Services

FINDINGS

Year	Uses	Source
2014	CHAN CHIROPRACTIC	Cole Information Services
	LEE AMY YENPING DDS	Cole Information Services
	LU JENNY C DDS FAMILY DENTISTRY	Cole Information Services
2009	NAIL STUDIO INC	Cole Information Services
	FIDELITY AMERISURANCE INSURANCE	Cole Information Services
	NORTHERN CALIFORNIA DRUG TESTING CLI	Cole Information Services
	BOCEK & ASSOCIATES CPA	Cole Information Services
	RAJ ABHYANKER LLP	Cole Information Services
	EGHDAMI MERSEDEH DC	Cole Information Services
	CHOI KIM & PARK LLP	Cole Information Services
	ALLSTATE JILL KHIEW LO	Cole Information Services
	PENINSULA PRENATAL DIAGNOSTICS	Cole Information Services
	PROSTHETIC SOLUTIONS	Cole Information Services
	YEH MING DDS PHD	Cole Information Services
	PRE PAID LEGAL SERVICES	Cole Information Services
	LEE AMY YEN PING DDS	Cole Information Services
	MCCALLUM W D MD INC	Cole Information Services
	LOS ALTOS SOFTWARE TEST HOUSE	Cole Information Services
	PORTNOV COMPUTER SCHOOL	Cole Information Services
2004	ALLSTATE INSURANCE	Cole Information Services
	OS ALTOS SOFTWARE TSTNG HOUSE INC	Cole Information Services
	PROSTHETIC SOLUTIONS	Cole Information Services
	PENINSULA PRENATAL DIAGNOSTICS	Cole Information Services
	LU JENNY C DDS FAMILY DNTSTRY	Cole Information Services
	LEE AMY YEN PING DDS	Cole Information Services
	EGHDAMI CHIROPRACTIC CLINIC	Cole Information Services
2001	FAMILY DENTSTRY MCCALLUMWDMD	Haines Company, Inc.
	TESTING HSE LUJENNYCDDS	Haines Company, Inc.
	TESTING HSE LOS ALTOS SOFIWARE	Haines Company, Inc.
	LOS ALTOS SOFTWARE	Haines Company, Inc.
	KHIEWLOJILL	Haines Company, Inc.
	MANAGEMENT GSISOFTWAREINC	Haines Company, Inc.
	GRASSI INVESTMENT	Haines Company, Inc.
	DC GHOS 9 SOFTWARE INC	Haines Company, Inc.
	EGHDAMIMERSEDEH	Haines Company, Inc.
	BUILDING ALLSTATEINS	Haines Company, Inc.
	COMPASS PNTTRAVEL	Haines Company, Inc.

FINDINGS

Year	Uses	Source
1999	COMPASS POINT TRAVEL NETWORK TRAIN TRAVEL	Cole Information Services
	LOS ALTOS SOFTWARE TESTING HOUSE	Cole Information Services
	COMPASS POINT TRAVEL NETWORK BUSINESS TRAVEL	Cole Information Services
	CLUB MED EXPR AGENCY COMPASS PT TRVL NETWORK	Cole Information Services
	AURA INSURANCE SERVICES	Cole Information Services
	ROYAL ALLIANCE ASSOCIATES	Cole Information Services
	HENG HAI INTERNATL INCORPORATED	Cole Information Services
	TRAVEL NETWORK COMPASS POINT TRAVEL NETWORK	Cole Information Services
	LOS ALTOS SOFTWARE TESTING HOUSE THE	Cole Information Services
	CONTE WILLIAM J MD	Cole Information Services
	SOARES & ASSOCIATES INSURANCE	Cole Information Services
	COMPASS PT TRVL NETWORK GEN & VACATION TRVL	Cole Information Services
	CONTE W J MD	Cole Information Services
	PRENATAL DIAGNOSTICS INCORPORATED	Cole Information Services
	ALLSTATE INSURANCE COMPANIES SALES OFFICES	Cole Information Services
	MCCALLUM W D MD INCORPORATED	Cole Information Services
	CUSTOMERCAST	Cole Information Services
	SPEECHNET INCORPORATED	Cole Information Services
	KHIEW LO JILL INS	Cole Information Services
1994	PRENATAL DIAGNOSTICS INC	Cole Information Services
	MONTGOMERY, JACKLYN	Cole Information Services
	COMNWLTH CREDIT UN	Cole Information Services
	SYLVAN LEARNING CTR	Cole Information Services
	DRAPER & LIEW INC	Cole Information Services
	ADVANTAGE BUSINESS EXCHANGE	Cole Information Services
	AMTRAK AUTHORIZED TRAVEL AGCY	Cole Information Services
	JEMCO FINANCIAL SVC	Cole Information Services
1986	JOHNSON & ASSOCIATES INC	Pacific Bell
	JOHNSON & ASSOCIATES INC	Pacific Bell
1985	JOHNSON & ASSOCIATES PERSONNEL SEARCH SPECIALISTS	Pacific Bell

FINDINGS

1581 W EL CAMINO REAL

Year	Uses	Source
2017	FIRST COMMUNITY HOUSING	Cole Information Services
	SHARON KING	Cole Information Services
	DILL JANET	Cole Information Services
2004	A 1 APPLIANCE	Cole Information Services
	JESSIE RELOJ	Cole Information Services
2001	A 1 APPLIANCE	Haines Company, Inc.
	SHARRISON Harold	Haines Company, Inc.
	A SHIVA GALLERY	Haines Company, Inc.
1999	A 1 APPLIANCE	Cole Information Services
	SHIVA GALLERY	Cole Information Services
1994	SHIVA GALLERY	Cole Information Services
	A 1 APPLIANCE	Cole Information Services
	A 1 ALARM CO	Cole Information Services
1986	Shiva Gallery	Pacific Bell

1585 W EL CAMINO REAL

Year	Uses	Source
2017	1585 STUDIOS	Cole Information Services
	MARK MOURITSEN	Cole Information Services
	RAY LOZANO	Cole Information Services
	RICHARD WARNER	Cole Information Services
	DYLAN MOORE	Cole Information Services
	DIANE SMRKOVSKY	Cole Information Services
	ADELAIDE ROJAS	Cole Information Services
2014	DIANE SMRKOVSKY	Cole Information Services
	DENNIS LENCH	Cole Information Services
	RICHARD WARNER	Cole Information Services
	SUSAN BRITO	Cole Information Services
2009	DENNIS LENCH	Cole Information Services
	ANDREA DIXON	Cole Information Services
2004	FELIPA DELACRUZ	Cole Information Services
	JOSEFINA KENERY	Cole Information Services
	FLORENCIA MONIS	Cole Information Services
	DIZALYN HORTELANO	Cole Information Services
	EGBERTO MANALO	Cole Information Services
2001	MANALOEgberto Z	Haines Company, Inc.
1999	DENNIS LENCH	Cole Information Services
	ANDREA DIXON	Cole Information Services

FINDINGS

1600 W EL CAMINO REAL

Year	Uses	Source
1999	HOME SAVINGS OF AMERICA MENLO PARK	Cole Information Services
1986	SIRLOIN & BREW UNLIMITED	Pacific Bell

1601 W EL CAMINO REAL

Year	Uses	Source
1975	BONANZA TV CENTER	Pacific Telephone
1957	ALAIMO REALTY	Pacific Telephone

1603 W EL CAMINO REAL

Year	Uses	Source
1999	ALEXANDER TESHIN ASSOCIATES INCORPORATED	Cole Information Services
1994	LEE MC COY & ASSOC	Cole Information Services

1605 W EL CAMINO REAL

Year	Uses	Source
2017	PETER FORSTER MD	Cole Information Services
	LONGEVITY ACUPUNCTURE & HERBS	Cole Information Services
2014	LONGEVITY ACUPUNCTURE & HERBS	Cole Information Services
2009	SCHOLA CANTORUM	Cole Information Services
	WILLIAMS CHARLES CIVIL ENGINEER	Cole Information Services
	PERSONALIZED PLACEMENTS AGENCY	Cole Information Services
	SUN ACUPUNCTURE CLINIC	Cole Information Services
2004	EDIT IT VIDEO	Cole Information Services
	CHARLES WILLIAM REG CIVIL ENG	Cole Information Services
	SCHOLA CANTORUM	Cole Information Services
1999	WILLIAMS CHARLES	Cole Information Services
	SCHOLA CANTORUM	Cole Information Services
1994	ALLSTATE INSURANCE	Cole Information Services
1991	C & ME ADVERTISING	PACIFIC BELL WHITE PAGES

1612 W EL CAMINO REAL

Year	Uses	Source
2001	XXXX	Haines Company, Inc.

1615 W EL CAMINO REAL

Year	Uses	Source
2001	EDIT IT VIDEO	Haines Company, Inc.

Year	Uses	Source
2001	ATTIC TREASURES	Haines Company, Inc.
	WILLIAMSCHARLES	Haines Company, Inc.
	PERSONLZD	Haines Company, Inc.
	PLACEMENT AGENCY SCHOLACANTORUM	Haines Company, Inc.
1991	UP & RUNNING COMPUTER SERVICES	PACIFIC BELL WHITE PAGES
1975	RENAISSANCE STUDIO	Pacific Telephone

1616 W EL CAMINO REAL

Year	Uses	Source
2017	JOHNY ROSENSTEIN	Cole Information Services
	JEROME TURNBULL	Cole Information Services
	CHRISTOPHER DUNDER	Cole Information Services
	AUSTINS	Cole Information Services
	ZCON BUILDERS	Cole Information Services
	ASHLEY HAZELTON	Cole Information Services
2014	AUSTINS CATERING SERVICE	Cole Information Services
	AUSTINS	Cole Information Services
2004	AUSTINS BARBEQUE & TAVERN	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
2001	AUSTINS CATERING	Haines Company, Inc.
	SERVICE	Haines Company, Inc.
1999	AUSTINS CATERING SERVICE	Cole Information Services
1994	TONY ROMAS	Cole Information Services

1620 W EL CAMINO REAL

Year	Uses	Source
2004	OCCUPANT UNKNOWN	Cole Information Services
2001	DOLLAR RENT A CAR	Haines Company, Inc.
1999	MV SPA	Cole Information Services
1994	M V SPA	Cole Information Services
1991	LOZARES BERNARD INS	PACIFIC BELL WHITE PAGES

1621 W EL CAMINO REAL

Year	Uses	Source
2017	RENIAC INC	Cole Information Services
	ROBERT CHANG INSURANCE AGENCY	Cole Information Services
	YOUNG EXPRESS TRAVEL	Cole Information Services
2009	GINI SYSTEMS	Cole Information Services
	ALCE PARTNERS	Cole Information Services

Year	Uses	Source
2009	ACQIS TECHNOLOGY INC	Cole Information Services
2004	ACQIS TECHNOLOGY INC	Cole Information Services
2001	ACQIS TECHNOLOGY	Haines Company, Inc.
	SILICON VLY ZHANG HUI	Haines Company, Inc.
	PROFSNLTUTORNG SV	Haines Company, Inc.
	A COISTECHNOLOGY	Haines Company, Inc.
1999	ROMPHI INTERNATIONAL ARCHL STRL & GEN CONSTRCTN	Cole Information Services
	U S CREDIT SERVICES	Cole Information Services
1975	TRADEWINDS TRAVEL SERVICE	Pacific Telephone

1622 W EL CAMINO REAL

Year	Uses	Source
2014	EL Y ELLA	Cole Information Services
2009	EL Y ELLA FULL SERVICE HAIR SALON	Cole Information Services
2001	XXXX	Haines Company, Inc.
1999	VONDA	Cole Information Services
	GOMEZ VONDA K	Cole Information Services
	HART RUTH	Cole Information Services
	PRECISION HAIR DESIGN OWNER DONNA WITTRY	Cole Information Services
	PRECISION HAIR DESIGN VONDA K GOMEZ	Cole Information Services
	PRECISION HAIR DESIGN STYLIST RUTH HART	Cole Information Services
1994	A TIME FOR YOU HAIRSTYLING	Cole Information Services
	A TIME FOR YOU	Cole Information Services
1975	LOZARES PATRICK CHRISTENSEN & POULS ins	Pacific Telephone

1662 W EL CAMINO REAL

Year	Uses	Source
2001	XXXX	Haines Company, Inc.

1663 W EL CAMINO REAL

Year	Uses	Source
1999	OCCUPANT UNKNOWN	Cole Information Services

1665 W EL CAMINO REAL

Year	Uses	Source
2017	SUPER 8 MOUNTAIN VIEW	Cole Information Services

FINDINGS

Year	Uses	Source
2017	AUTHORIZED APPLIANCE REPAIR COMPANY	Cole Information Services
2014	SUPER 8 MOUNTAIN VIEW	Cole Information Services
	SUPER 8	Cole Information Services
2004	SUPER 8 MOTEL	Cole Information Services
2001	PATELBipin SUPER 8 MOTEL	Haines Company, Inc.
1999	CASA CAMINO MOTEL	Cole Information Services
	SUPER 8 MOTEL	Cole Information Services
1994	CASA CAMINO MOTEL	Cole Information Services
1975	CASA CAMINO MOTEL	Pacific Telephone

1675 W EL CAMINO REAL

Year	Uses	Source
1999	OCCUPANT UNKNOWN	Cole Information Services

1701 W EL CAMINO REAL

Year	Uses	Source
2004	OCCUPANT UNKNOWN	Cole Information Services
2001	ALDENS FURNITURE	Haines Company, Inc.
	FIELD Edward MOUNTN VW ANTIOUES	Haines Company, Inc.
1999	MOUNTAIN VIEW ANTIQUES	Cole Information Services
	OCCUPANT UNKNOWN	Cole Information Services
	CONSIGN	Cole Information Services
1994	ALDENS ANYTHING ANTIQUE	Cole Information Services

1707 W EL CAMINO REAL

Year	Uses	Source
2001	IELD Edward	Haines Company, Inc.
	FIELD Edward MOUNTN VW ANTIOUES	Haines Company, Inc.
	CLASSIC PET GROOMG	Haines Company, Inc.
1999	CLASSIC PET GROOMING	Cole Information Services
1994	CLASSIC PET GROOMING	Cole Information Services
1975	MTVI EW LOS ALTOS AMBULANCE	Pacific Telephone
	SEVYICE	Pacific Telephone
	LOS ALTOS MT VIEW AMBULANCE SERVICE	Pacific Telephone
	FIELDS AMBULANCE SERVICE	Pacific Telephone
	EL CAMINO AMBULANCE SERVICE	Pacific Telephone

FINDINGS

1709 W EL CAMINO REAL

Year	Uses	Source
2004	OCCUPANT UNKNOWN	Cole Information Services
2001	XXXX	Haines Company, Inc.
1994	FIELDS MEDICAL	Cole Information Services

1711 W EL CAMINO REAL

Year	Uses	Source
2017	SAMIS PIZZA	Cole Information Services
	F8 QUICKCUT	Cole Information Services
2014	SAMIS PIZZA	Cole Information Services
	SUSHI HACHI JAPANESE RESTAURANT	Cole Information Services
	F 8 QUICKCUT	Cole Information Services
2009	MV CUSTOM TAILORS	Cole Information Services
2004	OCCUPANT UNKNOWN	Cole Information Services
2001	DAY BREAK	Haines Company, Inc.
1999	DAY BREAK BAR & GRILL	Cole Information Services
1994	DAYBREAK	Cole Information Services
1982	Daybreak	Pacific Telephone

1737 W EL CAMINO REAL

Year	Uses	Source
2001	XXXX	Haines Company, Inc.
1991	HUBBARD & JOHNSON LUMBER & BUILDING MATERIALS	PACIFIC BELL WHITE PAGES

1745 W EL CAMINO REAL

Year	Uses	Source
1957	MONTI ERCOLE MONTI S RSTRNT	Pacific Telephone

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
1028 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1030 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1030 EL MONTE AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1030 EL MONTE CT	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1030 EL MONTE WAY	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1039 El Monte Ave.	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1039 El Monte Ave.	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1041 El Monte Ave.	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1043 El Monte Ave.	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1045 El Monte Ave.	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1047 El Monte Ave.	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1047 RICH AV MVW	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1047 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1047 RICH AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1049 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1049 EL MONTE AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1049 El Monte Ave.	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1049 RICH AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1050 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1050 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1057 EL MNTE AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1057 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1057 EL MONTE AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1057 EL MONTE CT	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1057 EL MONTE WAY	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1059 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1059 EL MONTE AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1059 EL MONTE AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1059 El Monte Avenue	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1059 N EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1061 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1061 EL MONTE AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1065 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1065 N EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1066 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1066 EL MONTE AVE	2017, 2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1075 EL MONTE AVE	2006, 2004, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1075 EL MONTE AVE	2006, 2004, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1075 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1075 El Monte Avenue	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1075 EL MONTE WAY	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1076 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1076 EL MONTE AVE	2017, 2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1077 RICH AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1077 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1080 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1095 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1095 EL MONTE AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1127 KATHY WAY	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1127 KATHY WAY	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1132 KATHY WAY	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1132 KATHY WAY	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1139 KATHY WAY	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1139 KATHY WAY	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1146 KATHY WAY	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1146 KATHY WAY	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1158 KATHY WAY	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1158 KATHY WAY	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1495 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1495 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1495 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1495 W EL CAMINO REAL	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1501 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1513 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1513 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1513 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1519 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1519 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1519 HOLLNGSWRTH DR	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1524 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1524 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1524 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1528 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1528 EL CAMINO REAL E	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1533 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1533 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1536 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1536 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1541 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1541 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1541 HOLLNGSWRTH DR	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1544 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1544 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1544 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1544 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1544 W EL CAMINO REAL	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1548 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1548 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1550 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1550 EL CAMINO REAL E	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1555 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1555 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1560 HOLLINGSWORTH DR	2009, 2006, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1560 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1560 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1561 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1561 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1561 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1561 HOL INASWORTH DR	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1561 HOLINASWORTH DR	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1561 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1561 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1561 W EL CAMINO REAL	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1561 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1564 W EL CAMINO REAL	2017, 2014, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 EL CANRINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 HOILINGSWURTH DR	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1982, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 W EL CAMINO REAL	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1571 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1572 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1572 HOLLINGSWORTH DR	2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1580 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1580 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1580 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1580 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1580 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1580 W EL CAMINO REAL	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1581 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1581 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1581 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1581 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1581 W EL CAMINO REAL	2014, 2009, 2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1585 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1585 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1585 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1585 W EL CAMINO REAL	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1586 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1586 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1598 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1986, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1598 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1600 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1600 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1601 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1601 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1601 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1603 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1603 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1603 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1603 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1604 HOLLINGSWORTH DR	2017, 2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1604 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1605 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1605 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1605 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1605 W EL CAMINO REAL	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1605 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1608 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1608 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1610 HIOLLINGSWORTIH DR	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1610 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1610 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1612 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1613 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1613 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1614 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1614 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1615 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1615 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1615 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1615 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1616 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1616 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1616 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1616 HOLLINGSWORTH DR	2017, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1616 W EL CAMINO REAL	2009, 2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1616 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1617 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1617 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1618 HOLLINGSWORTH DR	2017, 2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1618 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1986, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1620 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1620 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1620 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1621 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1621 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1621 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1621 W EL CAMINO REAL	2014, 2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1622 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1622 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1622 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1622 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1622 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1622 W EL CAMINO REAL	2017, 2006, 2004, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1625 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1625 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1625 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1625 HOLLNQGSWRTH DR	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1626 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1626 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1633 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1633 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1634 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1634 HOLLINGSWORTH DR	2009, 2006, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1640 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1640 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1641 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1641 HOLLINGSWORTH DR	2017, 2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1649 HOLLINGSWORTH DR	2017, 2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1649 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1649 HOLLNGSVRTH DR	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1652 HOLLINGSWORTH DR	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1652 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1662 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1663 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1665 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1665 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1665 EL CAMINO RL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1665 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1665 W EL CAMINO REAL	2009, 2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1668 HOLLINGSWORTH DR	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1670 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1675 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1695 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1701 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1701 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1701 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1707 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1707 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1707 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1707 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1709 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1709 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1709 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1709 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2001, 2000, 1999, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1710 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1711 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1711 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1711 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1711 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1711 W EL CAMINO REAL	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1735 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1737 EL CAMINO REAL W	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1737 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1741 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1745 EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1745 W EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
1749 E EL CAMINO REAL	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
726 MARIPOSA AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
772 MARIPOSA AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
900 RICH AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
905 RICH AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
908 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
908 RICH AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
910 RICH AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
910 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
911 RICH AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
912 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
912 RICH AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
912 RICH AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
912 Rich Avenue	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
914 RICH AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
914 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
915 RICH AVE	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
920 RICH AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
920 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
922 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
922 RICH AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
930 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
932 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
932 RICH PL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
934 RICH AVE	2017, 2014, 2009, 2006, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
934 RICH PL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
936 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
936 RICH AVE	2017, 2014, 2009, 2006, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
938 RICH AVE	2017, 2014, 2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
938 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
939 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
939 RICH AVE	2006, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
940 RICH AVE	2017, 2014, 2009, 2006, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
940 RICH PL	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
942 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
959 RICH AV MV	2017, 2014, 2009, 2006, 2004, 2001, 2000, 1999, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
959 RICH AVE	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
959 RICH AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
959 RICH AVE	2006, 2001, 2000, 1996, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922
959 Rich Avenue	2017, 2014, 2009, 2006, 2004, 2000, 1999, 1996, 1994, 1991, 1985, 1980, 1978, 1974, 1970, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
918 Rich Avenue	2017, 2006, 2004, 2001, 2000, 1996, 1994, 1991, 1986, 1985, 1982, 1980, 1978, 1975, 1974, 1970, 1968, 1966, 1965, 1964, 1963, 1962, 1960, 1957, 1955, 1950, 1946, 1945, 1942, 1940, 1936, 1935, 1931, 1930, 1926, 1925, 1922

APPENDIX F
DATABASE REPORT

Residential Property
918 Rich Avenue
Mountain View, CA 94040

Inquiry Number: 6348854.2s
January 29, 2021

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	305
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

918 RICH AVENUE
MOUNTAIN VIEW, CA 94040

COORDINATES

Latitude (North):	37.3893350 - 37° 23' 21.60''
Longitude (West):	122.0944180 - 122° 5' 39.90''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	580165.3
UTM Y (Meters):	4138244.5
Elevation:	105 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5641106 MOUNTAIN VIEW, CA
Version Date:	2012
South Map:	5640178 CUPERTINO, CA
Version Date:	2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140608
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
918 RICH AVENUE
MOUNTAIN VIEW, CA 94040

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
1	SPIEKER COMPANIES IN	959 RICH AVENUE #20	RCRA NonGen / NLR	Lower	84, 0.016, ESE
A2	DR PIROUZNIA DENTAL	1061 EL MONTE AV C	CUPA Listings	Higher	149, 0.028, West
A3	JAMES T CUNNINGHAM D	1057 EL MONTE AV C	CUPA Listings	Higher	149, 0.028, West
A4	JOSEPH M CASSARA DDS	1057 EL MONTE AV B	CUPA Listings	Higher	149, 0.028, West
B5	CVS PHARMACY #9346	1041 EL MONTE AVENUE	CERS HAZ WASTE, CERS	Lower	211, 0.040, NNW
B6	CVS PHARMACY # 9346	1041 EL MONTE AVENUE	RCRA-LQG, FINDS, ECHO, CUPA Listings	Lower	211, 0.040, NNW
B7	LONG'S DRUG STORE #3	1041 EL MONTE AV	CUPA Listings	Lower	211, 0.040, NNW
B8	FRANZMAN JOHN CHEVRO	1041 EL MONTE	EDR Hist Auto	Lower	211, 0.040, NNW
C9	B&H EQUIPMENT RENTAL	904 RICH AVE	RCRA-SQG, FINDS, ECHO	Lower	213, 0.040, NE
A10	BLUE BIRD CLEANERS	1049 EL MONTE AVENUE	CERS HAZ WASTE, CERS	Lower	285, 0.054, WNW
A11	BLUE BIRD CLEANERS &	1049 EL MONTE AVE ST	EDR Hist Cleaner	Lower	285, 0.054, WNW
A12	BLUE BIRD CLEANERS	1049 EL MONTE AVE	RCRA NonGen / NLR	Lower	285, 0.054, WNW
A13	BLUE BIRD CLEANERS	1049 EL MONTE AV A	CUPA Listings	Lower	285, 0.054, WNW
C14	BP PATEL	1665 W EL CAMINO REA	EDR Hist Auto	Lower	311, 0.059, NE
B15	MINUTEMAN PRESS	1039 EL MONTE AV L	CUPA Listings	Lower	329, 0.062, North
B16	PRECISION CAMERAS	1039 EL MONTE AV K	CUPA Listings	Lower	329, 0.062, North
B17	MINUTEMAN PRESS	1039 EL MONTE AV L	CUPA Listings	Lower	329, 0.062, North
C18	1711 W EL CAMINO LLC	1711 W EL CAMINO REA	RCRA NonGen / NLR	Lower	334, 0.063, NNE
19	GROSSMANS MT. VIEW	1737 EL CAMINO REAL	LUST, HIST LUST, Cortese, HIST CORTESE, CERS	Lower	424, 0.080, North
D20	TRIANGLE GARAGE INC	1513 EL CAMINO REAL	EDR Hist Auto	Lower	519, 0.098, East
E21	EL MONTE CHEVRON SIT	1010 EL MONTE AVENUE	UST	Lower	531, 0.101, NW
E22	EL MONTE CHEVRON SIT	1010 EL MONTE AVENUE	CERS HAZ WASTE, CERS TANKS, CERS	Lower	531, 0.101, NW
E23	CONOCO PHILLIPS COMP	1010 EL MONTE AV	CUPA Listings	Lower	531, 0.101, NW
E24	UNION OIL SS# 3686	1010 EL MONTE AVE	HIST UST	Lower	531, 0.101, NW
E25	UNION OIL SS #3686	1010 EL MONTE	SWEEPS UST, HIST UST, CA FID UST, CUPA Listings	Lower	531, 0.101, NW
E26	ELMONTE CHEVRON	1010 EL MONTE	RCRA NonGen / NLR	Lower	531, 0.101, NW
E27	RICKS UNION 76	1010 EL MONTE	EDR Hist Auto	Lower	531, 0.101, NW
D28	PRENATAL DIAGNOSTICS	1580 W EL CAMINO REA	RCRA-SQG, FINDS, ECHO	Lower	572, 0.108, ENE
D29	JENNY LU, DDS	1580 W EL CAMINO REA	RCRA NonGen / NLR	Lower	572, 0.108, ENE
D30	PRENATAL DIAGNOSTICS	1580 W EL CAMINO REA	CUPA Listings	Lower	572, 0.108, ENE
D31	YEN-PING LEE DDS, MS	1580 W EL CAMINO REA	RCRA NonGen / NLR	Lower	572, 0.108, ENE
D32	JENNY LU DDS	1580 W EL CAMINO REA	CUPA Listings	Lower	572, 0.108, ENE
D33	MCLOED GLASS COMPANY	1495 W EL CAMINO REA	HIST UST	Lower	655, 0.124, East
D34	MCLOED GLASS COMPANY	1495 W EL CAMINO REA	SWEEPS UST, CA FID UST	Lower	655, 0.124, East
E35	LINDELL CHIROPRACTIC	998 EL MONTE AV	CUPA Listings	Lower	658, 0.125, NW
F36	YULAN M. LEWIS	725 MARIPOSA AVE. #3	RCRA NonGen / NLR	Lower	680, 0.129, ENE
F37	PRITHI TRIVEDI	725 MARIPOSA AVE UNI	RCRA NonGen / NLR	Lower	680, 0.129, ENE
F38	FLORENCE TING	725 MARIPOSA AVE #10	RCRA NonGen / NLR	Lower	680, 0.129, ENE
D39	A-1 FOREIGN AUTO RPR	1544 W EL CAMINO REA	RCRA NonGen / NLR	Lower	710, 0.134, ENE

MAPPED SITES SUMMARY

Target Property Address:
918 RICH AVENUE
MOUNTAIN VIEW, CA 94040

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
D40	A-1 FOREIGN AUTO	1544 EL CAMINO REAL	CERS HAZ WASTE, CERS	Lower	710, 0.134, ENE
D41	A-1 FOREIGN AUTO	1544 W EL CAMINO REA	CUPA Listings	Lower	710, 0.134, ENE
42	SANDRA CARRICO	1843 ANTHONY CT	RCRA NonGen / NLR	Higher	773, 0.146, WNW
43	CHIROPRACTIC PERFORM	1411 EL CAMINO REAL	CUPA Listings	Lower	789, 0.149, East
44	EZZY SCHUSTERMAN	1758 MARICH WAY	RCRA NonGen / NLR	Lower	884, 0.167, NW
G45	BEACON STATION #588	1820 W EL CAMINO REA	HIST UST	Lower	977, 0.185, NNW
G46	BEACON STATION #588	1820 EL CAMINO REAL	SWEEPS UST, HIST UST, CA FID UST	Lower	977, 0.185, NNW
H47	MARIPOSA APARTMENTS	660 MARIPOSA AVE	RCRA NonGen / NLR	Lower	1016, 0.192, NE
H48	MARIPOSA APARTMENTS	660 MARIPOSA AVE	RCRA NonGen / NLR	Lower	1016, 0.192, NE
H49	BRIDGE HOUSING CORPO	660 MARIPOSA AVE	RCRA NonGen / NLR	Lower	1016, 0.192, NE
50	JERRY KWOK	659 SPARGUR DR	RCRA NonGen / NLR	Higher	1024, 0.194, SW
I51	OFFICE DEPOT 869	910 EL MONTE AVE	RCRA NonGen / NLR	Lower	1036, 0.196, NNW
I52	OFFICE DEPOT #869	910 EL MONTE AV	CERS HAZ WASTE, CUPA Listings, HAZNET, HWTS	Lower	1036, 0.196, NNW
G53	DEAN'S FOREIGN CAR	1901 W EL CAMINO REA	CUPA Listings	Lower	1052, 0.199, NNW
J54	PRASAD PARIMI	1332 PARK DR	RCRA NonGen / NLR	Higher	1122, 0.213, ESE
55	BETTY EVANS	771 PALO ALTO AVE	RCRA NonGen / NLR	Lower	1167, 0.221, East
I56	WALGREENS #13948	1905 W EL CAMINO REA	CERS HAZ WASTE, CUPA Listings, CERS	Lower	1197, 0.227, NNW
I57	WALGREENS #13948	1905 W EL CAMINO REA	RCRA-SQG	Lower	1197, 0.227, NNW
J58	1313 EL CAMINO REAL	1313 EL CAMINO REAL	RCRA-SQG	Lower	1199, 0.227, ESE
J59	@ HOME LLC	1313 EL CAMINO REAL	RCRA NonGen / NLR	Lower	1199, 0.227, ESE
J60	@HOME LLC	1313-1347 W EL CAMIN	CPS-SLIC, CERS	Lower	1199, 0.227, ESE
61	DAN ASKARI	633 SPARGUR DR.	RCRA NonGen / NLR	Higher	1279, 0.242, WSW
K62	CAMINO DENTAL GROUP	1328 W EL CAMINO REA	CUPA Listings	Lower	1290, 0.244, East
K63	CAMINO DENTAL GROUP	1328 W EL CAMINO REA	RCRA NonGen / NLR	Lower	1290, 0.244, East
K64	STROM PROPERTIES	1328 W. EL CAMINO RE	RCRA NonGen / NLR	Lower	1290, 0.244, East
K65	SHELL	1288 EL CAMINO REAL	HIST CORTESE	Lower	1523, 0.288, East
K66	SHELL OIL CO	1288 EL CAMINO	RCRA-SQG, LUST, HIST LUST, SWEEPS UST, HIST UST,...	Lower	1523, 0.288, East
K67	FELIPE C. SONGCO	1288 W EL CAMINO REA	LUST, HIST UST, CUPA Listings	Lower	1523, 0.288, East
L68	JIFFY LUBE #2342	1141 W EL CAMINO REA	LUST, HIST LUST, AST, Cortese, CUPA Listings	Higher	1802, 0.341, ESE
L69	JOE'S FOREIGN CAR	1141 EL CAMINO REAL	HIST CORTESE	Higher	1802, 0.341, ESE
L70	CAMINO CAR WASH	1101 EL CAMINO REAL	HIST CORTESE	Higher	1967, 0.373, ESE
L71	CAMINO CAR WASH	1101 W EL CAMINO REA	LUST, CPS-SLIC, HIST LUST, SWEEPS UST, CA FID UST,...	Higher	1967, 0.373, ESE
L72	CAMINO CAR WASH	1101 W EL CAMINO REA	LUST, HIST UST, DEED, CERS	Higher	1967, 0.373, ESE
73	FLUFF DRY CLEANING	801-819 WEST EL CAMI	ENVIROSTOR, VCP	Higher	3045, 0.577, ESE
74	SATAKE NURSERY	1079 MARILYN	ENVIROSTOR, LUST, VCP, HIST CORTESE, CIWQS	Higher	3197, 0.605, SSE
75	DLC CASTRO	1172 CASTRO STREET	ENVIROSTOR, HIST CORTESE	Higher	3294, 0.624, SE
M76	JASCO CHEM CORP	1710 VILLA ST	Delisted NPL, SEMS, RCRA-SQG, US ENG CONTROLS, US...	Lower	3431, 0.650, NNE
M77	JASCO CHEMICAL CORP.	1710 VILLA ST	ENVIROSTOR, HIST UST, ENF, CIWQS, CERS	Lower	3431, 0.650, NNE
M78	JASCO CHEMICAL CO	1710 VILLA STREET	HIST Cal-Sites	Lower	3431, 0.650, NNE

MAPPED SITES SUMMARY

Target Property Address:
918 RICH AVENUE
MOUNTAIN VIEW, CA 94040

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
M79	JASCO CHEMICAL CORPO	1710 VILLA STREET	CA BOND EXP. PLAN, EMI	Lower	3431, 0.650, NNE
80	FORMER PLATINUM CLEA	2290 WEST EL CAMINO	ENVIROSTOR, VCP	Lower	4001, 0.758, NW
N81	FREMONT LAUNDRY	990 VILLA STREET	ENVIROSTOR, VCP	Lower	4259, 0.807, ENE
82	LOS ALTOS HS	201 ALMOND AVE	RCRA-SQG, ENVIROSTOR, SCH, CERS HAZ WASTE, FINDS,..	Higher	4276, 0.810, WSW
N83	TIED HOUSE BREWING S	954 VILLA STREET	ENVIROSTOR, VCP	Lower	4303, 0.815, ENE
N84	EVELYN AVENUE PARKIN	SOUTHEAST CORNER OF	ENVIROSTOR, VCP	Lower	4482, 0.849, ENE
O85	SYMTRON CORP MOUNTAI	2235 MORA DR	RCRA-SQG, RESPONSE, ENVIROSTOR, FINDS, ECHO, CERS	Lower	5012, 0.949, NNW
O86	MORA DRIVE	2221-2291 MORA DRIVE	ENVIROSTOR, VCP, DEED	Lower	5135, 0.973, NNW
87	SHELL SERVICE STATIO	110 N RENGSTORFF	RCRA-SQG, LUST, HIST LUST, SWEEPS UST, HIST UST,...	Lower	5164, 0.978, North
O88	PLESSEY #3	2256 MORA DRIVE	RESPONSE, ENVIROSTOR, CERS	Lower	5227, 0.990, NNW
O89	PLESSEY #2	2251, 2257, 2283 AND	RESPONSE, ENVIROSTOR, CERS	Lower	5238, 0.992, NNW

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-VSQG ---------- RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

EXECUTIVE SUMMARY

State and tribal landfill and/or solid waste disposal site lists

SWF/LF ---------- Solid Waste Information System

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing
AST ---------- Aboveground Petroleum Storage Tank Facilities
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing
VCP ---------- Voluntary Cleanup Program Properties

State and tribal Brownfields sites

BROWNFIELDS ---------- Considered Brownfieds Sites Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT ---------- Waste Management Unit Database
SWRCY ---------- Recycler Database
HAULERS ---------- Registered Waste Tire Haulers Listing
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---------- Open Dump Inventory
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
SCH ---------- School Property Evaluation Program
CDL ---------- Clandestine Drug Labs
Toxic Pits ---------- Toxic Pits Cleanup Act Sites
US CDL ---------- National Clandestine Laboratory Register
PFAS ---------- PFAS Contamination Site Location Listing

Local Land Records

LIENS ---------- Environmental Liens Listing
LIENS 2 ---------- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---------- Hazardous Materials Information Reporting System

CHMIRS	California Hazardous Material Incident Report System
LDS	Land Disposal Sites Listing
MCS	Military Cleanup Sites Listing
SPILLS 90	SPILLS 90 data from FirstSearch

Other Ascertainable Records

FUDS	Formerly Used Defense Sites
DOD	Department of Defense Sites
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR	Financial Assurance Information
EPA WATCH LIST	EPA WATCH LIST
2020 COR ACTION	2020 Corrective Action Program List
TSCA	Toxic Substances Control Act
TRIS	Toxic Chemical Release Inventory System
SSTS	Section 7 Tracking Systems
RMP	Risk Management Plans
RAATS	RCRA Administrative Action Tracking System
PRP	Potentially Responsible Parties
PADS	PCB Activity Database System
ICIS	Integrated Compliance Information System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
FUSRAP	Formerly Utilized Sites Remedial Action Program
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US AIRS	Aerometric Information Retrieval System Facility Subsystem
US MINES	Mines Master Index File
ABANDONED MINES	Abandoned Mines
FINDS	Facility Index System/Facility Registry System
ECHO	Enforcement & Compliance History Information
UXO	Unexploded Ordnance Sites
DOCKET HWC	Hazardous Waste Compliance Docket Listing
FUELS PROGRAM	EPA Fuels Program Registered Listing
DRYCLEANERS	Cleaner Facilities
EMI	Emissions Inventory Data
ENF	Enforcement Action Listing
Financial Assurance	Financial Assurance Information Listing
HAZNET	Facility and Manifest Data
ICE	ICE
HWP	EnviroStor Permitted Facilities Listing
HWT	Registered Hazardous Waste Transporter Database
MINES	Mines Site Location Listing
MWMP	Medical Waste Management Program Listing
NPDES	NPDES Permits Listing
PEST LIC	Pesticide Regulation Licenses Listing

PROC Certified Processors Database
HAZMAT Hazardous Material Facilities
UIC UIC Listing
UIC GEO UIC GEO (GEOTRACKER)
WASTEWATER PITS Oil Wastewater Pits Listing
WDS Waste Discharge System
WIP Well Investigation Program Case List
MILITARY PRIV SITES MILITARY PRIV SITES (GEOTRACKER)
PROJECT PROJECT (GEOTRACKER)
WDR Waste Discharge Requirements Listing
CIWQS California Integrated Water Quality System
CERS CERS
NON-CASE INFO NON-CASE INFO (GEOTRACKER)
OTHER OIL GAS OTHER OIL & GAS (GEOTRACKER)
PROD WATER PONDS PROD WATER PONDS (GEOTRACKER)
SAMPLING POINT SAMPLING POINT (GEOTRACKER)
WELL STIM PROJ Well Stimulation Project (GEOTRACKER)
HWTS Hazardous Waste Tracking System
MINES MRDS Mineral Resources Data System

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF Recovered Government Archive Solid Waste Facilities List
RGA LUST Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal Delisted NPL site list

Delisted NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may deleted from the NPL where no further response is appropriate.

A review of the Delisted NPL list, as provided by EDR, and dated 10/28/2020 has revealed that there is 1 Delisted NPL site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
JASCO CHEM CORP	***1710 VILLA ST***	***NNE 1/2 - 1 (0.650 mi.)***	***M76***	***185***

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/14/2020 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY # 9346 EPA ID:: CAR000059337	***1041 EL MONTE AVENUE***	***NNW 0 - 1/8 (0.040 mi.)***	***B6***	***15***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/14/2020 has revealed that there are 4 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
B&H EQUIPMENT RENTAL EPA ID:: CAD981616105	***904 RICH AVE***	***NE 0 - 1/8 (0.040 mi.)***	***C9***	***26***
PRENATAL DIAGNOSTICS EPA ID:: CAD982497745	***1580 W EL CAMINO REA***	***ENE 0 - 1/8 (0.108 mi.)***	***D28***	***61***
WALGREENS #13948 EPA ID:: CAL000375888	1905 W EL CAMINO REA	NNW 1/8 - 1/4 (0.227 mi.)	I57	124
1313 EL CAMINO REAL	1313 EL CAMINO REAL	ESE 1/8 - 1/4 (0.227 mi.)	J58	129

State- and tribal - equivalent NPL

RESPONSE: Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

A review of the RESPONSE list, as provided by EDR, has revealed that there are 3 RESPONSE sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SYMTRON CORP MOUNTAI	***2235 MORA DR***	***NNW 1/2 - 1 (0.949 mi.)***	***O85***	***254***
Database: RESPONSE, Date of Government Version: 10/26/2020 Status: No Further Action Facility Id: 43360124				
PLESSEY #3	***2256 MORA DRIVE***	***NNW 1/2 - 1 (0.990 mi.)***	***O88***	***299***
Database: RESPONSE, Date of Government Version: 10/26/2020 Status: No Further Action Facility Id: 43360135				
PLESSEY #2	***2251, 2257, 2283 AND***	***NNW 1/2 - 1 (0.992 mi.)***	***O89***	***302***
Database: RESPONSE, Date of Government Version: 10/26/2020 Status: No Further Action Facility Id: 43360131				

State- and tribal - equivalent CERCLIS

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 10/26/2020 has revealed that there are 13 ENVIROSTOR sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FLUFF DRY CLEANING	***801-819 WEST EL CAMI***	***ESE 1/2 - 1 (0.577 mi.)***	***73***	***173***
Facility Id: 60001528 Status: Active				
SATAKE NURSERY	***1079 MARILYN***	***SSE 1/2 - 1 (0.605 mi.)***	***74***	***179***
Facility Id: 60000834 Status: No Further Action				
DLC CASTRO	***1172 CASTRO STREET***	***SE 1/2 - 1 (0.624 mi.)***	***75***	***184***
Facility Id: 43010009 Status: No Further Action				
LOS ALTOS HS	***201 ALMOND AVE***	***WSW 1/2 - 1 (0.810 mi.)***	***82***	***229***

Facility Id: 60002914
Status: Active

Lower Elevation	Address	Direction / Distance	Map ID	Page
JASCO CHEMICAL CORP.	***1710 VILLA ST***	***NNE 1/2 - 1 (0.650 mi.)***	***M77***	***202***
Facility Id: 43280119				
Status: Refer: RWQCB				
FORMER PLATINUM CLEA	***2290 WEST EL CAMINO***	***NW 1/2 - 1 (0.758 mi.)***	***80***	***211***
Facility Id: 60002117				
Status: Certified				
FREMONT LAUNDRY	***990 VILLA STREET***	***ENE 1/2 - 1 (0.807 mi.)***	***N81***	***219***
Facility Id: 60001426				
Status: Active				
TIED HOUSE BREWING S	***954 VILLA STREET***	***ENE 1/2 - 1 (0.815 mi.)***	***N83***	***246***
Facility Id: 60002038				
Status: Active				
EVELYN AVENUE PARKIN	***SOUTHEAST CORNER OF***	***ENE 1/2 - 1 (0.849 mi.)***	***N84***	***250***
Facility Id: 60000745				
Status: No Further Action				
SYMTRON CORP MOUNTAI	***2235 MORA DR***	***NNW 1/2 - 1 (0.949 mi.)***	***O85***	***254***
Facility Id: 43360124				
Status: No Further Action				
MORA DRIVE	***2221-2291 MORA DRIVE***	***NNW 1/2 - 1 (0.973 mi.)***	***O86***	***262***
Facility Id: 60002502				
Status: Active				
PLESSEY #3	***2256 MORA DRIVE***	***NNW 1/2 - 1 (0.990 mi.)***	***O88***	***299***
Facility Id: 43360135				
Status: No Further Action				
PLESSEY #2	***2251, 2257, 2283 AND***	***NNW 1/2 - 1 (0.992 mi.)***	***O89***	***302***
Facility Id: 43360131				
Status: No Further Action				

State and tribal leaking storage tank lists

LUST: Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the LUST list, as provided by EDR, has revealed that there are 6 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JIFFY LUBE #2342	***1141 W EL CAMINO REA***	***ESE 1/4 - 1/2 (0.341 mi.)***	***L68***	***158***
Database: LUST REG 2, Date of Government Version: 09/30/2004				
Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014				
Database: LUST, Date of Government Version: 09/08/2020				
Status: Completed - Case Closed				
Facility Status: Case Closed				

Date Closed: 02/03/2000
Global Id: T0608500779
SCVWD ID: 06S2W28C02F
date9: 2/3/2000

CAMINO CAR WASH ***1101 W EL CAMINO REA*** ***ESE 1/4 - 1/2 (0.373 mi.)*** ***L71*** ***163***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014
Facility Status: Pollution Characterization
Date Closed: 10/01/2004
SCVWD ID: 06S2W28C03F

CAMINO CAR WASH ***1101 W EL CAMINO REA*** ***ESE 1/4 - 1/2 (0.373 mi.)*** ***L72*** ***167***
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Global Id: T0608501970

Lower Elevation	Address	Direction / Distance	Map ID	Page

GROSSMANS MT. VIEW ***1737 EL CAMINO REAL*** ***N 0 - 1/8 (0.080 mi.)*** ***19*** ***40***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Facility Status: Case Closed
Date Closed: 01/20/1994
Global Id: T0608500738
SCVWD ID: 06S2W21N01F
date9: 1/20/1994

SHELL OIL CO ***1288 EL CAMINO*** ***E 1/4 - 1/2 (0.288 mi.)*** ***K66*** ***144***
Database: LUST REG 2, Date of Government Version: 09/30/2004
Database: LUST SANTA CLARA, Date of Government Version: 03/03/2014
Facility Status: Case Closed
Date Closed: 06/25/1996
SCVWD ID: 06S2W28C01F
date9: 6/25/1996

FELIPE C. SONGCO ***1288 W EL CAMINO REA*** ***E 1/4 - 1/2 (0.288 mi.)*** ***K67*** ***156***
Database: LUST, Date of Government Version: 09/08/2020
Status: Completed - Case Closed
Global Id: T0608501251

CPS-SLIC: Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the CPS-SLIC list, as provided by EDR, has revealed that there are 2 CPS-SLIC sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page

CAMINO CAR WASH ***1101 W EL CAMINO REA*** ***ESE 1/4 - 1/2 (0.373 mi.)*** ***L71*** ***163***
Database: CPS-SLIC, Date of Government Version: 09/08/2020
Facility Status: Completed - Case Closed

Global Id: T10000005942

Lower Elevation	Address	Direction / Distance	Map ID	Page
@HOME LLC	***1313-1347 W EL CAMIN***	***ESE 1/8 - 1/4 (0.227 mi.)***	***J60***	***135***
Database: CPS-SLIC, Date of Government Version: 09/08/2020 Facility Status: Open - Site Assessment Global Id: T10000010030				

HIST LUST: A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

A review of the HIST LUST list, as provided by EDR, and dated 03/29/2005 has revealed that there are 4 HIST LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JIFFY LUBE #2342 SCVWD ID: 06S2W28C02	***1141 W EL CAMINO REA***	***ESE 1/4 - 1/2 (0.341 mi.)***	***L68***	***158***
CAMINO CAR WASH SCVWD ID: 06S2W28C03	***1101 W EL CAMINO REA***	***ESE 1/4 - 1/2 (0.373 mi.)***	***L71***	***163***

Lower Elevation	Address	Direction / Distance	Map ID	Page
GROSSMANS MT. VIEW SCVWD ID: 06S2W21N01	***1737 EL CAMINO REAL***	***N 0 - 1/8 (0.080 mi.)***	***19***	***40***
SHELL OIL CO SCVWD ID: 06S2W28C01	***1288 EL CAMINO***	***E 1/4 - 1/2 (0.288 mi.)***	***K66***	***144***

State and tribal registered storage tank lists

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, has revealed that there is 1 UST site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
EL MONTE CHEVRON SIT	1010 EL MONTE AVENUE	NW 0 - 1/8 (0.101 mi.)	E21	44
Database: UST, Date of Government Version: 09/08/2020 Facility Id: 1111 Facility Id: 1618				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

HIST Cal-Sites: Formerly known as ASPIS, this database contains both known and potential hazardous substance sites. The source is the California Department of Toxic Substance Control. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

A review of the HIST Cal-Sites list, as provided by EDR, and dated 08/08/2005 has revealed that there is 1 HIST Cal-Sites site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
JASCO CHEMICAL CO	1710 VILLA STREET	NNE 1/2 - 1 (0.650 mi.)	M78	208

CERS HAZ WASTE: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

A review of the CERS HAZ WASTE list, as provided by EDR, and dated 10/19/2020 has revealed that there are 6 CERS HAZ WASTE sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY #9346	***1041 EL MONTE AVENUE***	***NNW 0 - 1/8 (0.040 mi.)***	***B5***	***12***
BLUE BIRD CLEANERS	***1049 EL MONTE AVENUE***	***WNW 0 - 1/8 (0.054 mi.)***	***A10***	***30***
EL MONTE CHEVRON SIT	***1010 EL MONTE AVENUE***	***NW 0 - 1/8 (0.101 mi.)***	***E22***	***44***
A-1 FOREIGN AUTO	***1544 EL CAMINO REAL***	***ENE 1/8 - 1/4 (0.134 mi.)***	***D40***	***81***
OFFICE DEPOT #869	***910 EL MONTE AV***	***NNW 1/8 - 1/4 (0.196 mi.)***	***I52***	***109***
WALGREENS #13948	***1905 W EL CAMINO REA***	***NNW 1/8 - 1/4 (0.227 mi.)***	***I56***	***120***

Local Lists of Registered Storage Tanks

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 3 SWEEPS UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNION OIL SS #3686 Status: A Tank Status: A Comp Number: 8114	***1010 EL MONTE***	***NW 0 - 1/8 (0.101 mi.)***	***E25***	***54***
MCLOED GLASS COMPANY Comp Number: 65512	***1495 W EL CAMINO REA***	***E 0 - 1/8 (0.124 mi.)***	***D34***	***70***
BEACON STATION #588 Comp Number: 38867	***1820 EL CAMINO REAL***	***NNW 1/8 - 1/4 (0.185 mi.)***	***G46***	***91***

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 5 HIST UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNION OIL SS# 3686 Facility Id: 00000061446	1010 EL MONTE AVE	NW 0 - 1/8 (0.101 mi.)	E24	54
UNION OIL SS #3686 Facility Id: 00000008114	***1010 EL MONTE***	***NW 0 - 1/8 (0.101 mi.)***	***E25***	***54***
MCLOED GLASS COMPANY Facility Id: 00000065512	1495 W EL CAMINO REA	E 0 - 1/8 (0.124 mi.)	D33	69
BEACON STATION #588 Facility Id: 00000038867	1820 W EL CAMINO REA	NNW 1/8 - 1/4 (0.185 mi.)	G45	90
BEACON STATION #588	***1820 EL CAMINO REAL***	***NNW 1/8 - 1/4 (0.185 mi.)***	***G46***	***91***

CA FID UST: The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.

A review of the CA FID UST list, as provided by EDR, and dated 10/31/1994 has revealed that there are 3 CA FID UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
UNION OIL SS #3686 Facility Id: 43006934 Status: A	***1010 EL MONTE***	***NW 0 - 1/8 (0.101 mi.)***	***E25***	***54***
MCLOED GLASS COMPANY Facility Id: 43001731 Status: I	***1495 W EL CAMINO REA***	***E 0 - 1/8 (0.124 mi.)***	***D34***	***70***
BEACON STATION #588 Facility Id: 43011924 Status: I	***1820 EL CAMINO REAL***	***NNW 1/8 - 1/4 (0.185 mi.)***	***G46***	***91***

CERS TANKS: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

A review of the CERS TANKS list, as provided by EDR, and dated 10/19/2020 has revealed that there is 1 CERS TANKS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
EL MONTE CHEVRON SIT	***1010 EL MONTE AVENUE***	***NW 0 - 1/8 (0.101 mi.)***	***E22***	***44***

Local Land Records

DEED: The use of recorded land use restrictions is one of the methods the DTSC uses to protect the public from unsafe exposures to hazardous substances and wastes .

A review of the DEED list, as provided by EDR, and dated 08/31/2020 has revealed that there is 1 DEED

site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CAMINO CAR WASH	***1101 W EL CAMINO REA***	***ESE 1/4 - 1/2 (0.373 mi.)***	***L72***	***167***
Status: COMPLETED - CASE CLOSED Envirostor ID: T0608501970				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/14/2020 has revealed that there are 23 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SANDRA CARRICO EPA ID:: CAC003008592	1843 ANTHONY CT	WNW 1/8 - 1/4 (0.146 mi.)	42	85
JERRY KWOK EPA ID:: CAC003045611	659 SPARGUR DR	SW 1/8 - 1/4 (0.194 mi.)	50	104
PRASAD PARIMI EPA ID:: CAC003039294	1332 PARK DR	ESE 1/8 - 1/4 (0.213 mi.)	J54	115
DAN ASKARI	633 SPARGUR DR.	WSW 1/8 - 1/4 (0.242 mi.)	61	136
Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
SPIEKER COMPANIES IN	959 RICH AVENUE #20	ESE 0 - 1/8 (0.016 mi.)	1	9
BLUE BIRD CLEANERS EPA ID:: CAL000177467	1049 EL MONTE AVE	WNW 0 - 1/8 (0.054 mi.)	A12	34
1711 W EL CAMINO LLC EPA ID:: CAP000152413	1711 W EL CAMINO REA	NNE 0 - 1/8 (0.063 mi.)	C18	38
ELMONTE CHEVRON EPA ID:: CAL912612806	1010 EL MONTE	NW 0 - 1/8 (0.101 mi.)	E26	57
JENNY LU, DDS EPA ID:: CAL000105441	1580 W EL CAMINO REA	ENE 0 - 1/8 (0.108 mi.)	D29	64
YEN-PING LEE DDS, MS EPA ID:: CAL000290011	1580 W EL CAMINO REA	ENE 0 - 1/8 (0.108 mi.)	D31	66
YULAN M. LEWIS EPA ID:: CAC003000722	725 MARIPOSA AVE. #3	ENE 1/8 - 1/4 (0.129 mi.)	F36	71
PRITHI TRIVEDI EPA ID:: CAC003010682	725 MARIPOSA AVE UNI	ENE 1/8 - 1/4 (0.129 mi.)	F37	73
FLORENCE TING	725 MARIPOSA AVE #10	ENE 1/8 - 1/4 (0.129 mi.)	F38	76
A-1 FOREIGN AUTO RPR EPA ID:: CAL000065867	1544 W EL CAMINO REA	ENE 1/8 - 1/4 (0.134 mi.)	D39	78
EZZY SCHUSTERMAN	1758 MARICH WAY	NW 1/8 - 1/4 (0.167 mi.)	44	87
MARIPOSA APARTMENTS	660 MARIPOSA AVE	NE 1/8 - 1/4 (0.192 mi.)	H47	94

EPA ID:: CAC003056279				
MARIPOSA APARTMENTS EPA ID:: CAC003038483	660 MARIPOSA AVE	NE 1/8 - 1/4 (0.192 mi.)	H48	96
BRIDGE HOUSING CORPO EPA ID:: CAC003037534	660 MARIPOSA AVE	NE 1/8 - 1/4 (0.192 mi.)	H49	101
OFFICE DEPOT 869 EPA ID:: CAL000421200	910 EL MONTE AVE	NNW 1/8 - 1/4 (0.196 mi.)	I51	106
BETTY EVANS EPA ID:: CAC003052494	771 PALO ALTO AVE	E 1/8 - 1/4 (0.221 mi.)	55	118
@ HOME LLC	1313 EL CAMINO REAL	ESE 1/8 - 1/4 (0.227 mi.)	J59	132
CAMINO DENTAL GROUP EPA ID:: CAL000152537	1328 W EL CAMINO REA	E 1/8 - 1/4 (0.244 mi.)	K63	139
STROM PROPERTIES EPA ID:: CAC002996861	1328 W. EL CAMINO RE	E 1/8 - 1/4 (0.244 mi.)	K64	141

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 10/28/2020 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
JASCO CHEM CORP EPA ID:: CAD009103318	***1710 VILLA ST***	***NNE 1/2 - 1 (0.650 mi.)***	***M76***	***185***

CA BOND EXP. PLAN: Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

A review of the CA BOND EXP. PLAN list, as provided by EDR, and dated 01/01/1989 has revealed that there is 1 CA BOND EXP. PLAN site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
JASCO CHEMICAL CORPO	***1710 VILLA STREET***	***NNE 1/2 - 1 (0.650 mi.)***	***M79***	***210***

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 06/22/2020 has revealed that there are 4 Cortese sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JIFFY LUBE #2342 Cleanup Status: COMPLETED - CASE CLOSED	***1141 W EL CAMINO REA***	***ESE 1/4 - 1/2 (0.341 mi.)***	***L68***	***158***
CAMINO CAR WASH Cleanup Status: COMPLETED - CASE CLOSED	***1101 W EL CAMINO REA***	***ESE 1/4 - 1/2 (0.373 mi.)***	***L71***	***163***

Lower Elevation	Address	Direction / Distance	Map ID	Page
GROSSMANS MT. VIEW	***1737 EL CAMINO REAL***	***N 0 - 1/8 (0.080 mi.)***	***19***	***40***

Cleanup Status: COMPLETED - CASE CLOSED

SHELL OIL CO ***1288 EL CAMINO*** ***E 1/4 - 1/2 (0.288 mi.)*** ***K66*** ***144***
Cleanup Status: COMPLETED - CASE CLOSED

CUPA Listings: A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

A review of the CUPA Listings list, as provided by EDR, has revealed that there are 20 CUPA Listings sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DR PIROUZNIA DENTAL	1061 EL MONTE AV C	W 0 - 1/8 (0.028 mi.)	A2	11
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
JAMES T CUNNINGHAM D	1057 EL MONTE AV C	W 0 - 1/8 (0.028 mi.)	A3	11
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
JOSEPH M CASSARA DDS	1057 EL MONTE AV B	W 0 - 1/8 (0.028 mi.)	A4	12
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY # 9346	***1041 EL MONTE AVENUE***	***NNW 0 - 1/8 (0.040 mi.)***	***B6***	***15***
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
LONG'S DRUG STORE #3	1041 EL MONTE AV	NNW 0 - 1/8 (0.040 mi.)	B7	26
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
BLUE BIRD CLEANERS	1049 EL MONTE AV A	WNW 0 - 1/8 (0.054 mi.)	A13	36
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
MINUTEMAN PRESS	1039 EL MONTE AV L	N 0 - 1/8 (0.062 mi.)	B15	37
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
PRECISION CAMERAS	1039 EL MONTE AV K	N 0 - 1/8 (0.062 mi.)	B16	37
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
MINUTEMAN PRESS	1039 EL MONTE AV L	N 0 - 1/8 (0.062 mi.)	B17	37
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
CONOCO PHILLIPS COMP	1010 EL MONTE AV	NW 0 - 1/8 (0.101 mi.)	E23	53
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
UNION OIL SS #3686	***1010 EL MONTE***	***NW 0 - 1/8 (0.101 mi.)***	***E25***	***54***
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
PRENATAL DIAGNOSTICS	1580 W EL CAMINO REA	ENE 0 - 1/8 (0.108 mi.)	D30	66
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
JENNY LU DDS	1580 W EL CAMINO REA	ENE 0 - 1/8 (0.108 mi.)	D32	69
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
LINDELL CHIROPRACTIC	998 EL MONTE AV	NW 0 - 1/8 (0.125 mi.)	E35	71
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
A-1 FOREIGN AUTO	1544 W EL CAMINO REA	ENE 1/8 - 1/4 (0.134 mi.)	D41	84
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
CHIROPRACTIC PERFORM	1411 EL CAMINO REAL	E 1/8 - 1/4 (0.149 mi.)	43	87
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
OFFICE DEPOT #869	***910 EL MONTE AV***	***NNW 1/8 - 1/4 (0.196 mi.)***	***I52***	***109***
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				

Lower Elevation	Address	Direction / Distance	Map ID	Page
DEAN'S FOREIGN CAR	1901 W EL CAMINO REA	NNW 1/8 - 1/4 (0.199 mi.)	G53	115
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
WALGREENS #13948	***1905 W EL CAMINO REA***	***NNW 1/8 - 1/4 (0.227 mi.)***	***I56***	***120***
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				
CAMINO DENTAL GROUP	1328 W EL CAMINO REA	E 1/8 - 1/4 (0.244 mi.)	K62	139
Database: CUPA SANTA CLARA, Date of Government Version: 08/20/2020				

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 4 HIST CORTESE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JOE'S FOREIGN CAR	1141 EL CAMINO REAL	ESE 1/4 - 1/2 (0.341 mi.)	L69	162
Reg Id: 43-0753				
CAMINO CAR WASH	1101 EL CAMINO REAL	ESE 1/4 - 1/2 (0.373 mi.)	L70	162
Reg Id: 43-2146				

Lower Elevation	Address	Direction / Distance	Map ID	Page
GROSSMANS MT. VIEW	***1737 EL CAMINO REAL***	***N 0 - 1/8 (0.080 mi.)***	***19***	***40***
Reg Id: 43-0709				
SHELL	1288 EL CAMINO REAL	E 1/4 - 1/2 (0.288 mi.)	K65	144
Reg Id: 43-1273				

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

A review of the Notify 65 list, as provided by EDR, and dated 12/07/2020 has revealed that there is 1 Notify 65 site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
SHELL SERVICE STATIO	***110 N RENGSTORFF***	***N 1/2 - 1 (0.978 mi.)***	***87***	***284***

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR

researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 4 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FRANZMAN JOHN CHEVRO	1041 EL MONTE	NNW 0 - 1/8 (0.040 mi.)	B8	26
BP PATEL	1665 W EL CAMINO REA	NE 0 - 1/8 (0.059 mi.)	C14	36
TRIANGLE GARAGE INC	1513 EL CAMINO REAL	E 0 - 1/8 (0.098 mi.)	D20	44
RICKS UNION 76	1010 EL MONTE	NW 0 - 1/8 (0.101 mi.)	E27	60

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there is 1 EDR Hist Cleaner site within approximately 0.125 miles of the target property.


Lower Elevation	Address	Direction / Distance	Map ID	Page
BLUE BIRD CLEANERS &	1049 EL MONTE AVE ST	WNW 0 - 1/8 (0.054 mi.)	A11	33

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 5 records.

Site Name	Database(s)
BEST BUY #0685	CERS HAZ WASTE
SAN FRANCISCO BAY	SEMS-ARCHIVE
COVINGTON PIPELINE PROJECT	CPS-SLIC
HILLVIEW MAINTENANCE YARD	ENVIROSTOR
MOUNTAIN VIEW LANDFILL GAS RECOVER	ENVIROSTOR

OVERVIEW MAP - 6348854.2S



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Residential Property	CLIENT: Env. Inv. Services, Inc.
ADDRESS: 918 Rich Avenue Mountain View CA 94040	CONTACT: Peter Littman INQUIRY #: 6348854.2s
LAT/LONG: 37.389335 / 122.094418	DATE: January 29, 2021 1:20 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 6348854.2S



0 1/16 1/8 1/4 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Residential Property	CLIENT: Env. Inv. Services, Inc.
ADDRESS: 918 Rich Avenue Mountain View CA 94040	CONTACT: Peter Littman INQUIRY #: 6348854.2s
LAT/LONG: 37.389335 / 122.094418	DATE: January 29, 2021 1:23 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	1	NR	1
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		1	0	NR	NR	NR	1
RCRA-SQG	0.250		2	2	NR	NR	NR	4
RCRA-VSQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
State- and tribal - equivalent NPL								
RESPONSE	1.000		0	0	0	3	NR	3
State- and tribal - equivalent CERCLIS								
ENVIROSTOR	1.000		0	0	0	13	NR	13
State and tribal landfill and/or solid waste disposal site lists								
SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
LUST	0.500		1	0	5	NR	NR	6

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	0.500		0	0	0	NR	NR	0
CPS-SLIC	0.500		0	1	1	NR	NR	2
HIST LUST	0.500		1	0	3	NR	NR	4
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250		1	0	NR	NR	NR	1
AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
State and tribal voluntary cleanup sites								
INDIAN VCP	0.500		0	0	0	NR	NR	0
VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
WMUDS/SWAT	0.500		0	0	0	NR	NR	0
SWRCY	0.500		0	0	0	NR	NR	0
HAULERS	0.001		0	NR	NR	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
HIST Cal-Sites	1.000		0	0	0	1	NR	1
SCH	0.250		0	0	NR	NR	NR	0
CDL	0.001		0	NR	NR	NR	NR	0
CERS HAZ WASTE	0.250		3	3	NR	NR	NR	6
Toxic Pits	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
PFAS	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
SWEEPS UST	0.250		2	1	NR	NR	NR	3
HIST UST	0.250		3	2	NR	NR	NR	5
CA FID UST	0.250		2	1	NR	NR	NR	3
CERS TANKS	0.250		1	0	NR	NR	NR	1
Local Land Records								
LIENS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	0.001		0	NR	NR	NR	NR	0
DEED	0.500		0	0	1	NR	NR	1
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
CHMIRS	0.001		0	NR	NR	NR	NR	0
LDS	0.001		0	NR	NR	NR	NR	0
MCS	0.001		0	NR	NR	NR	NR	0
SPILLS 90	0.001		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		6	17	NR	NR	NR	23
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	1	NR	1
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001		0	NR	NR	NR	NR	0
ECHO	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
CA BOND EXP. PLAN	1.000		0	0	0	1	NR	1
Cortese	0.500		1	0	3	NR	NR	4
CUPA Listings	0.250		14	6	NR	NR	NR	20

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
EMI	0.001		0	NR	NR	NR	NR	0
ENF	0.001		0	NR	NR	NR	NR	0
Financial Assurance	0.001		0	NR	NR	NR	NR	0
HAZNET	0.001		0	NR	NR	NR	NR	0
ICE	0.001		0	NR	NR	NR	NR	0
HIST CORTESE	0.500		1	0	3	NR	NR	4
HWP	1.000		0	0	0	0	NR	0
HWT	0.250		0	0	NR	NR	NR	0
MINES	0.250		0	0	NR	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
NPDES	0.001		0	NR	NR	NR	NR	0
PEST LIC	0.001		0	NR	NR	NR	NR	0
PROC	0.500		0	0	0	NR	NR	0
Notify 65	1.000		0	0	0	1	NR	1
HAZMAT	0.250		0	0	NR	NR	NR	0
UIC	0.001		0	NR	NR	NR	NR	0
UIC GEO	0.001		0	NR	NR	NR	NR	0
WASTEWATER PITS	0.500		0	0	0	NR	NR	0
WDS	0.001		0	NR	NR	NR	NR	0
WIP	0.250		0	0	NR	NR	NR	0
MILITARY PRIV SITES	0.001		0	NR	NR	NR	NR	0
PROJECT	0.001		0	NR	NR	NR	NR	0
WDR	0.001		0	NR	NR	NR	NR	0
CIWQS	0.001		0	NR	NR	NR	NR	0
CERS	0.001		0	NR	NR	NR	NR	0
NON-CASE INFO	0.001		0	NR	NR	NR	NR	0
OTHER OIL GAS	0.001		0	NR	NR	NR	NR	0
PROD WATER PONDS	0.001		0	NR	NR	NR	NR	0
SAMPLING POINT	0.001		0	NR	NR	NR	NR	0
WELL STIM PROJ	0.001		0	NR	NR	NR	NR	0
HWTS	TP		NR	NR	NR	NR	NR	0
MINES MRDS	0.001		0	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		4	NR	NR	NR	NR	4
EDR Hist Cleaner	0.125		1	NR	NR	NR	NR	1
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA LF	0.001		0	NR	NR	NR	NR	0
RGA LUST	0.001		0	NR	NR	NR	NR	0
- Totals --		0	44	33	16	21	0	114

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

1
ESE
< 1/8
0.016 mi.
84 ft.

SPIEKER COMPANIES INC
959 RICH AVENUE #20
MOUNTAIN VIEW, CA 94040

RCRA NonGen / NLR **1026477343**
CAC003083185

Relative:
Lower

Actual:
104 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-09-10 00:00:00.0
Handler Name:	SPIEKER COMPANIES INC	
Handler Address:		959 RICH AVENUE #20
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94040
EPA ID:		CAC003083185
Contact Name:		PAM CHEN
Contact Address:		1020 CORPORATION WAY #202
Contact City,State,Zip:		PALO ALTO, CA 94303
Contact Telephone:		650-387-7562
Contact Fax:		Not reported
Contact Email:		NICOLE@ENV-REM.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1020 CORPORATION WAY #202
Mailing City,State,Zip:		PALO ALTO, CA 94303
Owner Name:		SPIEKER COMPANIES INC
Owner Type:		Other
Operator Name:		PAM CHEN
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

SPIEKER COMPANIES INC (Continued) **1026477343**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-09-20 14:39:33.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PAM CHEN
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1020 CORPORATION WAY #202
Owner/Operator City,State,Zip:	PALO ALTO, CA 94303
Owner/Operator Telephone:	650-387-7562
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SPIEKER COMPANIES INC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1020 CORPORATION WAY #202
Owner/Operator City,State,Zip:	PALO ALTO, CA 94303
Owner/Operator Telephone:	650-387-7562
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SPIEKER COMPANIES INC (Continued) **1026477343**

Historic Generators:
Receive Date: 2020-09-10 00:00:00.0
Handler Name: SPIEKER COMPANIES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A2 **DR PIROUZNIA DENTAL OFFICE DDS** **CUPA Listings** **S121473505**
West **1061 EL MONTE AV C** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.028 mi.
149 ft. **Site 1 of 7 in cluster A**

Relative: Higher
Actual: 106 ft.

CUPA SANTA CLARA:
Name: DR PIROUZNIA DENTAL OFFICE DDS
Address: 1061 EL MONTE AV C
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: SANTA CLARA
PE#: 2271
Program Description: SILVER WASTE ONLY <100 KG/YR
Latitude: 37.389674
Longitude: -122.095799
Record ID: PR0381153
Facility ID: FA0259323

A3 **JAMES T CUNNINGHAM DDS** **CUPA Listings** **S121473666**
West **1057 EL MONTE AV C** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.028 mi.
149 ft. **Site 2 of 7 in cluster A**

Relative: Higher
Actual: 106 ft.

CUPA SANTA CLARA:
Name: JAMES T CUNNINGHAM DDS
Address: 1057 EL MONTE AV C
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: SANTA CLARA

JAMES T CUNNINGHAM DDS (Continued) **S121473666**

PE#: 2271
Program Description: SILVER WASTE ONLY <100 KG/YR
Latitude: 37.389863
Longitude: -122.095794
Record ID: PR0380923
Facility ID: FA0259857

A4 **JOSEPH M CASSARA DDS** **CUPA Listings** **S121473493**
West **1057 EL MONTE AV B** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.028 mi.
149 ft. **Site 3 of 7 in cluster A**

Relative: **Higher**
Actual: **106 ft.**

CUPA SANTA CLARA:
Name: JOSEPH M CASSARA DDS
Address: 1057 EL MONTE AV B
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: SANTA CLARA
PE#: 2271
Program Description: SILVER WASTE ONLY <100 KG/YR
Latitude: 37.389863
Longitude: -122.095794
Record ID: PR0379876
Facility ID: FA0259240

B5 **CVS PHARMACY #9346** **CERS HAZ WASTE** **S121753518**
NNW **1041 EL MONTE AVENUE** **CERS** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.040 mi.
211 ft. **Site 1 of 7 in cluster B**

Relative: **Lower**
Actual: **102 ft.**

CERS HAZ WASTE:
Name: CVS PHARMACY #9346
Address: 1041 EL MONTE AVENUE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 23197
CERS ID: 10076683
CERS Description: Hazardous Waste Generator

Name: CVS PHARMACY #9346
Address: 1041 EL MONTE AVENUE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 23197
CERS ID: 10076683
CERS Description: RCRA LQ HW Generator

CERS:
Name: CVS PHARMACY #9346
Address: 1041 EL MONTE AVENUE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 23197
CERS ID: 10076683
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 23197

CVS PHARMACY #9346 (Continued) **S121753518**

Site Name: CVS Pharmacy #9346
Violation Date: 06-13-2017
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: RCRA Large Quantity Generator Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 09/13/2017. DOCUMENTATION A MATERIAL IS NOT A WASTE Pharmacy utilizes Genco for return distribution of pharmaceuticals. No logs available for review identifying non-credit worthy returns. Provide this documentation to support the claim that the material is not a waste. Claims that a certain material is not a waste or is conditionally exempt from regulation, must be supported by documents demonstrating that there is a known market or disposition for the material, and that they meet the terms of the exclusion or exemption. Demonstration includes providing appropriate documentation supporting the claim that a material is not a waste, or is exempt from regulation. [CCR 66261.3(g)]. NOTE: Violation escalated to class II violation due to continuously failing to provide these reports over the past 4 months worth of inspections at CVS pharmacies.
Violation Division: Santa Clara County Environmental Health
Violation Program: HWLQG
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-13-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Stand-alone store and pharmacy. Store generates various hazardous wastes. Store inventory includes many hazardous materials that, if and when they become wastes, would be state or federal hazardous wastes. Examples include: Aerosols (sunscreen, pesticide, muscle rub, skin protectants, insecticides, Cleaning (eg corrosive CLR, Lime away), beauty products containing hydrogen peroxide, zinc based skin protectants, metal containing vitamins, phenol containing throat spray, rubbing alcohol, etc. Store personnel utilize a barcode scanning technology to sort expired/damaged/spilled products at least weekly. The pharmacy generates waste pharmaceuticals and examples of potential RCRA hazardous wastes include: insulin (cresol), Warfarin, Selenium. CVS has a barcode scanning system directing pharmacy staff where to place unwanted pharmaceuticals. Pharmacy utilizes Genco for return distribution of pharmaceuticals. No logs available for review identifying non-credit worthy (see [Truncated]
Eval Division: Santa Clara County Environmental Health
Eval Program: HWLQG
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-28-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: No Violations
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

CVS PHARMACY #9346 (Continued) **S121753518**

Eval Date:	08-05-2013
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	HMRRP
Eval Source:	CERS

Affiliation:

Affiliation Type Desc:	Environmental Contact
Entity Name:	Verisk 3E, Regulatory Services/CVS
Entity Title:	Not reported
Affiliation Address:	3207 Grey Hawk Court, Suite 200
Affiliation City:	Carlsbad
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92010
Affiliation Phone:	Not reported

Affiliation Type Desc:	CUPA District
Entity Name:	Santa Clara County Environmental Health
Entity Title:	Not reported
Affiliation Address:	1555 Berger Drive, Suite 300
Affiliation City:	San Jose
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95112-2716
Affiliation Phone:	(408) 918-3400

Affiliation Type Desc:	Document Preparer
Entity Name:	Crystalyn Dogui-is, Agent for Longs Drug Stores California, L.L.C.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Identification Signer
Entity Name:	Crystalyn Dogui-is, Agent for Longs Drug Stores California, L.L.C.
Entity Title:	Regulatory Compliance Coordinator II, Verisk 3E
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Legal Owner
Entity Name:	Longs Drug Stores California, L.L.C.
Entity Title:	Not reported
Affiliation Address:	One CVS Drive
Affiliation City:	Woonsocket
Affiliation State:	RI
Affiliation Country:	United States
Affiliation Zip:	02895

CVS PHARMACY #9346 (Continued) **S121753518**

Affiliation Phone:	(401) 765-1500
Affiliation Type Desc:	Property Owner
Entity Name:	Longs Drug Stores California, L.L.C.
Entity Title:	Not reported
Affiliation Address:	1 CVS Drive
Affiliation City:	Woonsocket
Affiliation State:	RI
Affiliation Country:	United States
Affiliation Zip:	02895
Affiliation Phone:	(401) 765-1500
Affiliation Type Desc:	Parent Corporation
Entity Name:	CVS Health
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	CVS Health, Attn: Dianne E. Durand, Licensing, 1 CVS Dr.- MC1160
Affiliation City:	Woonsocket
Affiliation State:	RI
Affiliation Country:	Not reported
Affiliation Zip:	02895
Affiliation Phone:	Not reported
Affiliation Type Desc:	Operator
Entity Name:	Longs Drug Stores California, L.L.C.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(417) 862-3333

B6 **CVS PHARMACY # 9346** **RCRA-LQG** **1001815696**
NNW **1041 EL MONTE AVENUE** **FINDS** **CAR000059337**
< 1/8 **MOUNTAIN VIEW, CA 94040** **ECHO**
0.040 mi. **CUPA Listings**
211 ft. **Site 2 of 7 in cluster B**

Relative: **Lower**
Actual: **102 ft.**

RCRA-LQG:

Date Form Received by Agency:	2020-02-17 00:00:00.0
Handler Name:	CVS PHARMACY # 9346
Handler Address:	1041 EL MONTE AVENUE
Handler City,State,Zip:	MOUNTAIN VIEW, CA 94040-0000
EPA ID:	CAR000059337
Contact Name:	NICOLE WILKINSON
Contact Address:	CVS DRIVE
Contact City,State,Zip:	WOONSOCKET, RI 02895

CVS PHARMACY # 9346 (Continued) **1001815696**

Contact Telephone:	401-770-7132
Contact Fax:	Not reported
Contact Email:	NICOLE.WILKINSON@CVSHEALTH.COM
Contact Title:	DIRECTOR CORPORATE ENVIRONMENTAL
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2019
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	CVS DRIVE MC2340
Mailing City,State,Zip:	WOONSOCKET, RI 02895
Owner Name:	LONGS DRUG STORES CALIFORNIA, L.L.C
Owner Type:	Private
Operator Name:	LONGS DRUG STORES CALIFORNIA, L.L.C
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CVS PHARMACY # 9346 (Continued) **1001815696**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-08-27 13:27:23.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D003
Waste Description:	REACTIVE WASTE
Waste Code:	D004
Waste Description:	ARSENIC
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY

CVS PHARMACY # 9346 (Continued) **1001815696**

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D016
Waste Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Waste Code: D018
Waste Description: BENZENE

Waste Code: D022
Waste Description: CHLOROFORM

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: D025
Waste Description: P-CRESOL

Waste Code: D026
Waste Description: CRESOL

Waste Code: D027
Waste Description: 1,4-DICHLOROBENZENE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D039
Waste Description: TETRACHLOROETHYLENE

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P012
Waste Description: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

Waste Code: P042
Waste Description: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P081
Waste Description: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

CVS PHARMACY # 9346 (Continued) **1001815696**

Waste Code: U002
Waste Description: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U031
Waste Description: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U044
Waste Description: CHLOROFORM (OR) METHANE, TRICHLORO-

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U059
Waste Description: 5,12-NAPHTHACENEDIONE, 8-ACETYL-10-[(3-AMINO-2,3,6-TRIDEOXY)-ALPHA-L-LYXO-HEXOPYRANOSYL)OXY]-7,8,9,10-TETRAHYDRO-6,8,11-TRIHYDROXY-1-METHOXY-, (8S-CIS)- (OR) DAUNOMYCIN

Waste Code: U070
Waste Description: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

Waste Code: U072
Waste Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Waste Code: U089
Waste Description: DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-

Waste Code: U122
Waste Description: FORMALDEHYDE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U132
Waste Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U151
Waste Description: MERCURY

CVS PHARMACY # 9346 (Continued) **1001815696**

Waste Code: U154
Waste Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U188
Waste Description: PHENOL

Waste Code: U200
Waste Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Waste Code: U201
Waste Description: 1,3-BENZENEDIOL (OR) RESORCINOL

Waste Code: U204
Waste Description: SELENIOUS ACID (OR) SELENIUM DIOXIDE

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Waste Code: U206
Waste Description: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

Waste Code: U210
Waste Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Waste Code: U279
Waste Description: U279

Waste Code: U411
Waste Description: U411

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: LONGS DRUG STORES CALIFORNIA, L.L.C
Legal Status: Private
Date Became Current: 1998-12-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: ONE CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895
Owner/Operator Telephone: 401-765-1500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: NICOLE.WILKINSON@CVSHEALTH.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: LONGS DRUG STORES CALIFORNIA, L.L.C
Legal Status: Private
Date Became Current: 1998-12-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: ONE CVS DR
Owner/Operator City,State,Zip: WOONSOCKET, RI 02895

CVS PHARMACY # 9346 (Continued) **1001815696**

Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	NICOLE.WILKINSON@CVSHEALTH.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name:	LONGS DRUG STORES C A
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	141 N CIVIC DR
Owner/Operator City,State,Zip:	WALNUT CREEK, CA 94596
Owner/Operator Telephone:	925-210-6999
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	LONGS DRUG STORES CALIFORNIA LLC
Legal Status:	Private
Date Became Current:	1998-12-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	ONE CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	LONGS DRUG STORES CALIFORNIA, L.L.C
Legal Status:	Private
Date Became Current:	2008-10-22 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DRIVE
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	CORPORATEENVIRONMENTALTEAM@CVSHEALTH.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name:	LONGS DRUG STORES CALIFORNIA, LLC
Legal Status:	Private
Date Became Current:	2008-10-22 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	LONGS DRUG STORES CALIFORNIA, L.L.C
Legal Status:	Private
Date Became Current:	2008-10-22 00:00:00.

CVS PHARMACY # 9346 (Continued) **1001815696**

Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DRIVE
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	CORPORATEENVIRONMENTALTEAM@CVSHEALTH.COM
Owner/Operator Indicator:	Operator
Owner/Operator Name:	LONGS DRUG STORES CALIFORNIA LLC
Legal Status:	Private
Date Became Current:	2008-10-22 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	LONGS DRUG STORES CALIFORNIA, L.L.C
Legal Status:	Private
Date Became Current:	2008-10-22 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	LONGS DRUG STORES CALIFORNIA, L.L.C
Legal Status:	Private
Date Became Current:	1998-12-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	1 CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	LONGS DRUG STORES CALIFORNIA, LLC
Legal Status:	Private
Date Became Current:	1998-12-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	ONE CVS DR
Owner/Operator City,State,Zip:	WOONSOCKET, RI 02895
Owner/Operator Telephone:	401-765-1500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CVS PHARMACY # 9346 (Continued) **1001815696**

Historic Generators:

Receive Date:	2014-03-01 00:00:00.0
Handler Name:	CVS PHARMACY #9346
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2016-08-29 00:00:00.0
Handler Name:	CVS PHARMACY #9346
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2018-03-01 00:00:00.0
Handler Name:	CVS PHARMACY # 9346
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	2020-02-17 00:00:00.0
Handler Name:	CVS PHARMACY # 9346
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	1999-11-19 00:00:00.0
Handler Name:	LONGS DRUG STORE NO 346
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported

CVS PHARMACY # 9346 (Continued) **1001815696**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2013-01-03 00:00:00.0
Handler Name: CVS PHARMACY NO 9346
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 446110
NAICS Description: PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 2017-06-13 00:00:00.0
Actual Return to Compliance Date: 2017-09-13 00:00:00.0
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

CVS PHARMACY # 9346 (Continued) **1001815696**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	2017-06-13 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	Not reported
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	2017-09-13 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110002931043

Click Here:

Environmental Interest/Information System:

California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
STATE MASTER
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001815696
Registry ID:	110002931043
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002931043
Name:	CVS PHARMACY # 9346
Address:	1041 EL MONTE AVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040

CVS PHARMACY # 9346 (Continued) **1001815696**

CUPA SANTA CLARA:

Name:	CVS PHARMACY #9346
Address:	1041 EL MONTE AV
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	Not reported
Program Description:	GENERATES 100 KG YR TO <5 TONS/YR (RCRA LQG)
Latitude:	37.390102
Longitude:	-122.094576
Record ID:	PR0392652
Facility ID:	FA0265860

B7 **LONG'S DRUG STORE #346** **CUPA Listings** **S121468894**
NNW **1041 EL MONTE AV** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.040 mi.
211 ft. **Site 3 of 7 in cluster B**

Relative: **Lower**

Actual: **102 ft.**

CUPA SANTA CLARA:

Name:	LONG'S DRUG STORE #346
Address:	1041 EL MONTE AV
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2206
Program Description:	GENERATES 5 TO <25 TONS/YR
Latitude:	37.390757
Longitude:	-122.095807
Record ID:	PR0365338
Facility ID:	FA0203383

B8 **FRANZMAN JOHN CHEVRON SERVICE** **EDR Hist Auto** **1020218317**
NNW **1041 EL MONTE** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.040 mi.
211 ft. **Site 4 of 7 in cluster B**

Relative: **Lower**

Actual: **102 ft.**

EDR Hist Auto

Year:	Name:	Type:
1969	FRANZMAN JOHN CHEVRON SERVICE	Gasoline Service Stations
1970	FRANZMAN JOHN CHEVRON SERVICE	Gasoline Service Stations
1971	FRANZMAN JOHN CHEVRON SERVICE	Gasoline Service Stations
1972	FRANZMAN JOHN CHEVRON SERVICE	Gasoline Service Stations

C9 **B&H EQUIPMENT RENTAL** **RCRA-SQG** **1000112876**
NE **904 RICH AVE** **FINDS** **CAD981616105**
< 1/8 **MOUNTAIN VIEW, CA 94040** **ECHO**
0.040 mi.
213 ft. **Site 1 of 3 in cluster C**

Relative: **Lower**

Actual: **102 ft.**

RCRA-SQG:

Date Form Received by Agency:		1996-09-01 00:00:00.0
Handler Name:	B&H EQUIPMENT RENTAL	
Handler Address:		904 RICH AVE

B&H EQUIPMENT RENTAL (Continued) **1000112876**

Handler City,State,Zip:	MOUNTAIN VIEW, CA 94040
EPA ID:	CAD981616105
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	2
Mailing Address:	2246 EL CAMINO REAL
Mailing City,State,Zip:	MT VIEW, CA 94040
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	NOT REQUIRED
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

B&H EQUIPMENT RENTAL (Continued) **1000112876**

TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:26:37.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	KEN CHEGWIN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1996-09-01 00:00:00.0
Handler Name: B&H EQUIPMENT RENTAL	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

B&H EQUIPMENT RENTAL (Continued) **1000112876**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1986-12-04 00:00:00.0
Handler Name: B&H EQUIPMENT RENTAL	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110002725258

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000112876
Registry ID:	110002725258
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002725258
Name:	B&H EQUIPMENT RENTAL
Address:	904 RICH AVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040

A10 **BLUE BIRD CLEANERS** **CERS HAZ WASTE** **S121795413**
WNW **1049 EL MONTE AVENUE UNIT A** **CERS** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.054 mi.
285 ft. **Site 4 of 7 in cluster A**

Relative:
Lower

Actual:
104 ft.

CERS HAZ WASTE:

Name:	BLUE BIRD CLEANERS
Address:	1049 EL MONTE AVENUE UNIT A
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Site ID:	99180
CERS ID:	10344172
CERS Description:	Hazardous Waste Generator

CERS:

Name:	BLUE BIRD CLEANERS
Address:	1049 EL MONTE AVENUE UNIT A
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Site ID:	99180
CERS ID:	10344172
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	99180
Site Name:	Blue Bird Cleaners
Violation Date:	06-28-2016
Citation:	HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 08/24/2016. Update inventory for waste as well (DF 2000, torch, etc.).
Violation Division:	Mountain View Fire Department
Violation Program:	HMRRP
Violation Source:	CERS

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	03-01-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Onsite for routine inspection, noted the following: -Storage and Label of hydrocarbon filter/lint waste container in good condition -Manifests available for review onsite -ER Plan completed today -Training appears adequate and owner Charley Yi is familiar with requirements No violations observed today, thank you.
Eval Division:	Santa Clara County Environmental Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	03-03-2020
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	On-site to conduct a hazardous waste generator inspection. Facility is a dry cleaner that utilizes one dry cleaning machine that utilizes DF-2000 dry cleaning solvent. The dry cleaning machine uses filters to reuse the solvent, and facility will top off the machine with fresh

BLUE BIRD CLEANERS (Continued) **S121795413**

solvent as needed. Mr. Yi will change out three of the filters from the machine approximately every 3 months and dispose of the filters contaminated with DF-2000 as hazardous waste. Facility also utilizes a spot cleaning table with spot cleaning chemicals including hydrogen peroxide (30%) and RustGo (5-12% Hydrogen Fluoride). Mr. Yi states that he will typically use small amounts of spotting chemical, water and then will use the air gun to dry the fabric, and that no liquid is collected in the spotting table's collection container. When asked how the RustGo is utilized, Mr. Yi stated that he applies the RustGo to a Q-tip and uses it to blot the stain. Observed the following containers containing [Truncated]

Eval Division: Santa Clara County Environmental Health
Eval Program: HW
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-28-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-02-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: No violations
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 07-20-2016
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-05-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 08-11-2016
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department

BLUE BIRD CLEANERS (Continued) **S121795413**

Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 08-24-2016
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: All Violations Corrected
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Affiliation:
Affiliation Type Desc: CUPA District
Entity Name: Santa Clara County Environmental Health
Entity Title: Not reported
Affiliation Address: 1555 Berger Drive, Suite 300
Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Parent Corporation
Entity Name: Blue Bird Cleaners
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: Tarlton Properties-Ruth Farrell
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: United States
Affiliation Zip: Not reported
Affiliation Phone: (650) 330-3600

Affiliation Type Desc: Environmental Contact
Entity Name: Charley Yi
Entity Title: Not reported
Affiliation Address: 1049-A El Monte Avenue
Affiliation City: Mountain View
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94040
Affiliation Phone: Not reported

Affiliation Type Desc: Operator
Entity Name: Charley Yi
Entity Title: Not reported
Affiliation Address: Not reported

BLUE BIRD CLEANERS (Continued) **S121795413**

Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(650) 691-1077
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	1049-A El Monte Avenue
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	94040
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	Charley Yi
Entity Title:	Not reported
Affiliation Address:	60 W. 42nd Avenue
Affiliation City:	San Mateo
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94403
Affiliation Phone:	(650) 341-7869

A11 **BLUE BIRD CLEANERS & LAUNDRY** **EDR Hist Cleaner** **1019940655**
WNW **1049 EL MONTE AVE STE A** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.054 mi.
285 ft. **Site 5 of 7 in cluster A**

Relative: EDR Hist Cleaner
Lower

Actual:
104 ft.

Year:	Name:	Type:
1996	BLUE BIRD CLEANERS	Drycleaning Plants, Except Rugs
1997	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1998	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1999	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2000	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2001	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2002	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2003	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2004	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2005	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2006	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2007	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2008	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2009	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2010	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2011	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2012	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2013	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2014	BLUE BIRD CLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs

A12 **BLUE BIRD CLEANERS** **RCRA NonGen / NLR** **1024796593**
WNW **1049 EL MONTE AVE** **CAL000177467**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.054 mi.
285 ft. **Site 6 of 7 in cluster A**

Relative: **Lower**
Actual: **104 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		1995-11-14 00:00:00.0
Handler Name:	BLUE BIRD CLEANERS	
Handler Address:		1049 EL MONTE AVE
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94040-0000
EPA ID:		CAL000177467
Contact Name:		CHARLEY C. YI
Contact Address:		1049-A EL MONTE AVE
Contact City,State,Zip:		MOUNTAIN VIEW, CA 94040
Contact Telephone:		650-691-1077
Contact Fax:		Not reported
Contact Email:		ROUMEEYI@YAHOO.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1049-A EL MONTE AVE
Mailing City,State,Zip:		MOUNTAIN VIEW, CA 94040-2320
Owner Name:		CHARLEY C. YI
Owner Type:		Other
Operator Name:		CHARLEY C. YI
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

BLUE BIRD CLEANERS (Continued) **1024796593**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 15:43:58.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CHARLEY C. YI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1049-A EL MONTE AVE
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040-0000
Owner/Operator Telephone:	650-691-1077
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CHARLEY C. YI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1049-A EL MONTE AVE
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-691-1077
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

BLUE BIRD CLEANERS (Continued) **1024796593**

Historic Generators:
- Receive Date: 1995-11-14 00:00:00.0
- Handler Name: BLUE BIRD CLEANERS
- Federal Waste Generator Description: Not a generator, verified
- State District Owner: Not reported
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Code: 56299
- NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

A13 **BLUE BIRD CLEANERS** **CUPA Listings** **S112345445**
WNW **1049 EL MONTE AV A** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.054 mi.
285 ft. **Site 7 of 7 in cluster A**

Relative: **Lower**

Actual: **104 ft.**

CUPA SANTA CLARA:
- Name: BLUE BIRD CLEANERS
- Address: 1049 EL MONTE AV A
- City,State,Zip: MOUNTAIN VIEW, CA 94040
- Region: SANTA CLARA
- PE#: 2205
- Program Description: GENERATES 100 KG YR TO <5 TONS/YR
- Latitude: 37.390226
- Longitude: -122.095759
- Record ID: PR0366316
- Facility ID: FA0251953

C14 **BP PATEL** **EDR Hist Auto** **1022146351**
NE **1665 W EL CAMINO REAL** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.059 mi.
311 ft. **Site 2 of 3 in cluster C**

Relative: **Lower**

Actual: **99 ft.**

EDR Hist Auto

Year:	Name:	Type:
2014	BP PATEL	Gasoline Service Stations, NEC

B15 **MINUTEMAN PRESS** **CUPA Listings** **S121472386**
North **1039 EL MONTE AV L** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.062 mi.
329 ft. **Site 5 of 7 in cluster B**

Relative: CUPA SANTA CLARA:
Lower

Name:	MINUTEMAN PRESS
Address:	1039 EL MONTE AV L
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2202
Program Description:	GENERATES < 100 KG/YR
Latitude:	37.390762
Longitude:	-122.095801
Record ID:	PR0365713
Facility ID:	FA0253630

Actual:
99 ft.

B16 **PRECISION CAMERAS** **CUPA Listings** **S121468891**
North **1039 EL MONTE AV K** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.062 mi.
329 ft. **Site 6 of 7 in cluster B**

Relative: CUPA SANTA CLARA:
Lower

Name:	PRECISION CAMERAS
Address:	1039 EL MONTE AV K
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2272
Program Description:	SILVER WASTE ONLY 100+ KG/YR & < 100 KG/MO
Latitude:	37.390762
Longitude:	-122.095801
Record ID:	PR0317821
Facility ID:	FA0203372

Actual:
99 ft.

B17 **MINUTEMAN PRESS** **CUPA Listings** **S121473502**
North **1039 EL MONTE AV L** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.062 mi.
329 ft. **Site 7 of 7 in cluster B**

Relative: CUPA SANTA CLARA:
Lower

Name:	MINUTEMAN PRESS
Address:	1039 EL MONTE AV L
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2205
Program Description:	GENERATES 100 KG YR TO <5 TONS/YR
Latitude:	37.390762
Longitude:	-122.095801
Record ID:	PR0379942
Facility ID:	FA0259306

Actual:
99 ft.

C18 **1711 W EL CAMINO LLC** **RCRA NonGen / NLR** **1025880072**
NNE **1711 W EL CAMINO REAL** **CAP000152413**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.063 mi.
334 ft. **Site 3 of 3 in cluster C**

Relative: **Lower**
Actual: **100 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2004-04-20 00:00:00.0
Handler Name:	1711 W EL CAMINO LLC	
Handler Address:		1711 W EL CAMINO REAL
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94040
EPA ID:		CAP000152413
Contact Name:		JANETTE SAMMARTINO
Contact Address:		350 CALIFORNIA ST
Contact City,State,Zip:		SAN FRANCISCO, CA 94104
Contact Telephone:		415-263-7403
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		350 CALIFORNIA ST
Mailing City,State,Zip:		SAN FRANCISCO, CA 94104
Owner Name:		1711 W EL CAMINO LLC
Owner Type:		Private
Operator Name:		1711 W EL CAMINO LLC
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

1711 W EL CAMINO LLC (Continued) **1025880072**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2004-08-02 14:21:29.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	1711 W EL CAMINO LLC
Legal Status:	Private
Date Became Current:	2004-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	350 CALIFORNIA ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94104
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	1711 W EL CAMINO LLC
Legal Status:	Private
Date Became Current:	2004-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

1711 W EL CAMINO LLC (Continued) **1025880072**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2004-04-20 00:00:00.0
Handler Name: 1711 W EL CAMINO LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 53112
NAICS Description: LESSORS OF NONRESIDENTIAL BUILDINGS (EXCEPT MINIWAREHOUSES)

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

19 **GROSSMANS MT. VIEW** **LUST** **S103472934**
North **1737 EL CAMINO REAL** **HIST LUST** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040** **Cortese**
0.080 mi. **HIST CORTESE**
424 ft. **CERS**

Relative:
Lower

Actual:
99 ft.

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 06S2W21N01f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: 8/16/1989
Pollution Characterization Began: 8/15/1990
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: 8/3/1992

LUST SANTA CLARA:
Name: GROSSMANS MT. VIEW

GROSSMANS MT. VIEW (Continued) **S103472934**

Address: 1737 EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA
Region: SANTA CLARA
SCVWD ID: 06S2W21N01F
Date Closed: 01/20/1994
EDR Link ID: 06S2W21N01F

LUST:
Name: GROSSMANS MT. VIEW
Address: 1737 EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Lead Agency: SANTA CLARA COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500738
Global Id: T0608500738
Latitude: 37.3907203726205
Longitude: -122.094540596008
Status: Completed - Case Closed
Status Date: 01/20/1994
Case Worker: UST
RB Case Number: Not reported
Local Agency: SANTA CLARA COUNTY LOP
File Location: All Files are on GeoTracker or in the Local Agency Database
Local Case Number: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0608500738
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500738
Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300
City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:
Global Id: T0608500738
Action Type: ENFORCEMENT
Date: 01/20/1994
Action: Closure/No Further Action Letter

Global Id: T0608500738
Action Type: Other
Date: 09/25/1989
Action: Leak Reported

GROSSMANS MT. VIEW (Continued) **S103472934**

Global Id: T0608500738
Action Type: ENFORCEMENT
Date: 11/04/1991
Action: Notice of Responsibility - #40130

Global Id: T0608500738
Action Type: REMEDIATION
Date: 07/02/1992
Action: Excavation

Global Id: T0608500738
Action Type: RESPONSE
Date: 10/04/1993
Action: Other Report / Document

LUST:
Global Id: T0608500738
Status: Open - Case Begin Date
Status Date: 08/16/1989

Global Id: T0608500738
Status: Open - Site Assessment
Status Date: 08/16/1989

Global Id: T0608500738
Status: Open - Site Assessment
Status Date: 08/15/1990

Global Id: T0608500738
Status: Open - Verification Monitoring
Status Date: 08/03/1992

Global Id: T0608500738
Status: Completed - Case Closed
Status Date: 01/20/1994

HIST LUST SANTA CLARA:
Name: Grossmans Mt. View
Address: 1737 El Camino Real
City: Mountain View
Region: SANTA CLARA
Region Code: 2
SCVWD ID: 06S2W21N01
Oversite Agency: SCVWD
Date Listed: 1990-01-01 00:00:00
Closed Date: 1994-01-20 00:00:00

CORTESE:
Name: GROSSMANS MT. VIEW
Address: 1737 EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0608500738
Site/Facility Type: LUST CLEANUP SITE

GROSSMANS MT. VIEW (Continued) **S103472934**

Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	GROSSMANS MT VIEW
edr_fadd1:	1737 EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	CORTESE
Facility County Code:	43
Reg By:	LTNKA
Reg Id:	43-0709

CERS:

Name:	GROSSMANS MT. VIEW
Address:	1737 EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Site ID:	246370
CERS ID:	T0608500738
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	UST CASE WORKER - SANTA CLARA COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	1555 Berger Drive, Suite 300
Affiliation City:	SAN JOSE
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	4089183400

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)
Entity Title:	Not reported
Affiliation Address:	1515 CLAY ST SUITE 1400
Affiliation City:	OAKLAND
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

D20 **TRIANGLE GARAGE INC** **EDR Hist Auto** **1022201837**
East **1513 EL CAMINO REAL** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.098 mi.
519 ft. **Site 1 of 11 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: Year: Name: Type:
99 ft. 1969 TRIANGLE GARAGE INC Gasoline Service Stations
1970 TRIANGLE GARAGE INC Gasoline Service Stations

E21 **EL MONTE CHEVRON SITE#376375** **UST** **U003779198**
NW **1010 EL MONTE AVENUE** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.101 mi.
531 ft. **Site 1 of 8 in cluster E**

Relative: UST:
Lower
Actual: Name: EL MONTE CHEVRON SITE#376375
101 ft. Address: 1010 EL MONTE AVENUE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Facility ID: 1111
Permitting Agency: Santa Clara County Environmental Health
Latitude: 37.39053
Longitude: -122.09622

Name: EL MONTE 76 SERVICE #253686
Address: 1010 EL MONTE AVE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Facility ID: 1618
Permitting Agency: MOUNTAIN VIEW, CITY OF
Latitude: 37.39188
Longitude: -122.09487

E22 **EL MONTE CHEVRON SITE#376375** **CERS HAZ WASTE** **S121772830**
NW **1010 EL MONTE AVENUE** **CERS TANKS** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040** **CERS**
0.101 mi.
531 ft. **Site 2 of 8 in cluster E**

Relative: CERS HAZ WASTE:
Lower
Actual: Name: EL MONTE CHEVRON SITE#376375
101 ft. Address: 1010 EL MONTE AVENUE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 392093
CERS ID: 10343827
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: EL MONTE CHEVRON SITE#376375
Address: 1010 EL MONTE AVENUE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 392093
CERS ID: 10343827
CERS Description: Underground Storage Tank

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

CERS:

Name:	EL MONTE CHEVRON SITE#376375
Address:	1010 EL MONTE AVENUE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Site ID:	392093
CERS ID:	10343827
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-12-2016
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Returned to compliance on 06/07/2016. Provide records.
Violation Division:	Mountain View Fire Department
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-18-2018
Citation:	23 CCR 16 2715(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(e)
Violation Description:	Failure to maintain a copy of the designated operator monthly inspections for the last 12 months on-site or off-site at a readily available location, if approved by the UPA.
Violation Notes:	Returned to compliance on 07/02/2018.
Violation Division:	Mountain View Fire Department
Violation Program:	UST
Violation Source:	CERS

Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-12-2016
Citation:	23 CCR 16 2715 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715
Violation Description:	The owner/operator has failed to comply with one or more of the following: to maintain a copy of the designated operator monthly inspections for the last 12 months and/or maintain a list of trained employees on-site or off-site at a readily available location, if approved by the CUPA.
Violation Notes:	Returned to compliance on 06/07/2016. Provide Records.
Violation Division:	Mountain View Fire Department
Violation Program:	UST
Violation Source:	CERS

Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	03-18-2015
Citation:	23 CCR 16 2643(b)(5) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2643(b)(5)
Violation Description:	Failure to conduct the 0.2 gallons per hour continuous in tank leak

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

	detection test.
Violation Notes:	Returned to compliance on 03/25/2015.
Violation Division:	Mountain View Fire Department
Violation Program:	UST
Violation Source:	CERS
Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-29-2019
Citation:	HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34
Violation Description:	Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.
Violation Notes:	Returned to compliance on 06/26/2019. The certificate of financial responsibility for this tank has not been updated since 2017. Update this form with a current date.
Violation Division:	Mountain View Fire Department
Violation Program:	UST
Violation Source:	CERS
Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-10-2017
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description:	Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements:Monitor at least hourly.Be capable of detecting a release of 3.0 gallons per hour at 10 p.s.i.g. Restrict or shut off the flow of product through the piping when a leak is detected.
Violation Notes:	Returned to compliance on 06/06/2017. Line leak detector on 91 sump did not restrict flow when a 3 gallon per hour leak was detected. Repair or replace line leak detector.
Violation Division:	Mountain View Fire Department
Violation Program:	UST
Violation Source:	CERS
Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-20-2015
Citation:	HSC 6.95 25508.1(a)-(e) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(e)
Violation Description:	Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name.
Violation Notes:	Returned to compliance on 07/06/2015.
Violation Division:	Mountain View Fire Department
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-29-2019
Citation:	23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23,

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

	Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description:	Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1,- 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October- 1,- 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.
Violation Notes:	Returned to compliance on 06/26/2019.
Violation Division:	Mountain View Fire Department
Violation Program:	UST
Violation Source:	CERS
Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-29-2019
Citation:	HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description:	Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes:	Returned to compliance on 06/26/2019. The HMBP has not been updated between January 1st and May 1st and therefore the permit has expired for this facility. Update HMBP in order to renew the permit.
Violation Division:	Mountain View Fire Department
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-12-2016
Citation:	HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Description:	Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.
Violation Notes:	Returned to compliance on 06/07/2016. Submit all 4 program elements right away.
Violation Division:	Mountain View Fire Department
Violation Program:	HMRRP
Violation Source:	CERS

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

Site ID:	392093
Site Name:	El Monte Chevron Site#376375
Violation Date:	05-18-2018
Citation:	HSC 6.7 Multiple - California Health and Safety Code, Chapter 6.7, Section(s) Multiple
Violation Description:	UST Program -General - Must include violation description, proper statute and regulation citation in the "comment" section.
Violation Notes:	Returned to compliance on 07/02/2018. Training - General (23 CCR 16 Multiple; HSC 6.7 Multiple).
Violation Division:	Mountain View Fire Department
Violation Program:	UST
Violation Source:	CERS

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	03-18-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Other/Unknown
Eval Date:	03-25-2015
Violations Found:	No
Eval Type:	Other, not routine, done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-10-2017
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	No violations.
Eval Division:	Mountain View Fire Department
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-10-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	UST
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-12-2016
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	HMRRP

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-12-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-15-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Replace G AlarmG bulb on Veeder Root panel
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-15-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Replace G AlarmG bulb on Veeder Root panel
Eval Division: Mountain View Fire Department
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-18-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-18-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-20-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: UST
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

Eval Date:	05-20-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-26-2020
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-29-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-29-2019
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not reported
Eval Division:	Mountain View Fire Department
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Other/Unknown
Eval Date:	06-06-2017
Violations Found:	No
Eval Type:	Other, not routine, done by local agency
Eval Notes:	All violations corrected.
Eval Division:	Mountain View Fire Department
Eval Program:	UST
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	06-07-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Onsite for routine inspection, noted the following: -Storage containers are in good condition -Labels on containers are adequate and used oil dolly was updated today -Manifests are available for review onsite; note: waste oil accumulation is in used oil dolly and underground tank (500 gallons) -Emergency Procedures and Training appear adequate at this time. No violations were noted today, thank you.
Eval Division:	Santa Clara County Environmental Health
Eval Program:	HW

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 06-07-2016
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: All Violations Corrected
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 06-07-2016
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: All Violations Corrected
Eval Division: Mountain View Fire Department
Eval Program: UST
Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 06-26-2019
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 06-26-2019
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: UST
Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 07-02-2018
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: UST
Eval Source: CERS

Affiliation:
Affiliation Type Desc: Legal Owner
Entity Name: Hassan Khaziri
Entity Title: Not reported
Affiliation Address: 1010 El Monte Avenue
Affiliation City: Mountain View
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94040
Affiliation Phone: (650) 964-3600

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

Affiliation Type Desc:	Identification Signer
Entity Name:	Hassan Khaziri
Entity Title:	owner
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	1010 El Monte Avenue
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	94040
Affiliation Phone:	Not reported

Affiliation Type Desc:	UST Tank Owner
Entity Name:	Hassan Khaziri
Entity Title:	Not reported
Affiliation Address:	1010 El Monte Avenue
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94040
Affiliation Phone:	(650) 964-3600

Affiliation Type Desc:	CUPA District
Entity Name:	Santa Clara County Environmental Health
Entity Title:	Not reported
Affiliation Address:	1555 Berger Drive, Suite 300
Affiliation City:	San Jose
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95112-2716
Affiliation Phone:	(408) 918-3400

Affiliation Type Desc:	Environmental Contact
Entity Name:	Hassan Khaziri
Entity Title:	Not reported
Affiliation Address:	1010 El Monte Avenue
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	94040
Affiliation Phone:	Not reported

Affiliation Type Desc:	Operator
Entity Name:	Hassan Khaziri
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported

EL MONTE CHEVRON SITE#376375 (Continued) **S121772830**

Affiliation Zip:	Not reported
Affiliation Phone:	(650) 964-3600
Affiliation Type Desc:	Parent Corporation
Entity Name:	El Monte Chevron #376375
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner
Entity Name:	Hassan Khaziri
Entity Title:	Not reported
Affiliation Address:	1010 El Monte Avenue
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94040
Affiliation Phone:	(650) 964-3600
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	Hassan Khaziri
Entity Title:	Not reported
Affiliation Address:	1010 El Monte Avenue
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94040
Affiliation Phone:	(650) 964-3600
Affiliation Type Desc:	UST Tank Operator
Entity Name:	Hassan Khaziri
Entity Title:	Not reported
Affiliation Address:	1010 El Monte Avenue
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94040
Affiliation Phone:	(650) 964-3600

E23 **CONOCO PHILLIPS COMPANY253686/3686** **CUPA Listings** **S121468888**
NW **1010 EL MONTE AV** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.101 mi.
531 ft. **Site 3 of 8 in cluster E**

Relative: CUPA SANTA CLARA:
Lower

Name:	CONOCO PHILLIPS COMPANY253686/3686
Address:	1010 EL MONTE AV
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2205
Program Description:	GENERATES 100 KG YR TO <5 TONS/YR
Latitude:	37.390397

Actual:
101 ft.

CONOCO PHILLIPS COMPANY253686/3686 (Continued) **S121468888**

Longitude: -122.096075
Record ID: PR0312918
Facility ID: FA0203354

E24 **UNION OIL SS# 3686** **HIST UST** **U001594340**
NW **1010 EL MONTE AVE** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.101 mi.
531 ft. **Site 4 of 8 in cluster E**

Relative: **Lower**
Actual: **101 ft.**

HIST UST:

Name:	UNION OIL SS# 3686
Address:	1010 EL MONTE AVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000061446
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	GHOLAM REZA REZAEE
Telephone:	4159643600
Owner Name:	UNION OIL CO.
Owner Address:	1 CALIFORNIS ST., SUITE 2700
Owner City,St,Zip:	SAN FRANCISCO, CA 94111
Total Tanks:	0001
Tank Num:	001
Container Num:	3686-10-1
Year Installed:	Not reported
Tank Capacity:	00000000
Tank Used for:	WASTE
Type of Fuel:	Not reported
Container Construction Thickness:	6
Leak Detection:	Visual

E25 **UNION OIL SS #3686** **SWEEPS UST** **1000167131**
NW **1010 EL MONTE** **HIST UST** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040** **CA FID UST**
0.101 mi. **CUPA Listings**
531 ft. **Site 5 of 8 in cluster E**

Relative: **Lower**
Actual: **101 ft.**

SWEEPS UST:

Name:	UNION OIL SS #3686
Address:	1010 EL MONTE
City:	MOUNTAIN VIEW
Status:	Active
Comp Number:	8114
Number:	9
Board Of Equalization:	44-000051
Referral Date:	05-04-92
Action Date:	05-04-92
Created Date:	10-13-88
Owner Tank Id:	3686-1-1
SWRCB Tank Id:	43-005-008114-000001
Tank Status:	A

UNION OIL SS #3686 (Continued) **1000167131**

Capacity: 10000
Active Date: 01-06-94
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 3

Name: UNION OIL SS #3686
Address: 1010 EL MONTE
City: MOUNTAIN VIEW
Status: Active
Comp Number: 8114
Number: 9
Board Of Equalization: 44-000051
Referral Date: 05-04-92
Action Date: 05-04-92
Created Date: 10-13-88
Owner Tank Id: 3686-2-1
SWRCB Tank Id: 43-005-008114-000002
Tank Status: A
Capacity: 10000
Active Date: 01-06-94
Tank Use: M.V. FUEL
STG: P
Content: SUPER UNLEADED
Number Of Tanks: Not reported

Name: UNION OIL SS #3686
Address: 1010 EL MONTE
City: MOUNTAIN VIEW
Status: Active
Comp Number: 8114
Number: 9
Board Of Equalization: 44-000051
Referral Date: 05-04-92
Action Date: 05-04-92
Created Date: 10-13-88
Owner Tank Id: 3686-4-1
SWRCB Tank Id: 43-005-008114-000003
Tank Status: A
Capacity: 550
Active Date: 01-06-94
Tank Use: OIL
STG: W
Content: WASTE OIL
Number Of Tanks: Not reported

HIST UST:
Name: UNION OIL SS 3686
Address: 1010 EL MONTE AVENUE
City,State,Zip: MOUNTAIN VIEW, CA 94040
File Number: 00020A53
URL: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/00020A53.pdf
Region: STATE
Facility ID: 00000008114
Facility Type: Gas Station
Other Type: Not reported

UNION OIL SS #3686 (Continued) **1000167131**

Contact Name:	GHOLAM REZA REZAEE
Telephone:	4159643600
Owner Name:	UNION OIL CO.
Owner Address:	1 CALIFORNIA ST. SUITE 2700
Owner City,St,Zip:	SAN FRANCISCO, CA 94111
Total Tanks:	0003
Tank Num:	001
Container Num:	3686-1-1
Year Installed:	1980
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10
Tank Num:	001
Container Num:	3686-1-1
Year Installed:	1980
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10
Tank Num:	002
Container Num:	3686-2-1
Year Installed:	1980
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10
Tank Num:	002
Container Num:	3686-2-1
Year Installed:	1980
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10
Tank Num:	003
Container Num:	3686-4-1
Year Installed:	Not reported
Tank Capacity:	00000550
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	3686-4-1
Year Installed:	Not reported
Tank Capacity:	00000550
Tank Used for:	WASTE

UNION OIL SS #3686 (Continued) **1000167131**

Type of Fuel: WASTE OIL
Container Construction Thickness: Not reported
Leak Detection: Stock Inventor

Click here for Geo Tracker PDF:

CA FID UST:
Facility ID: 43006934
Regulated By: UTNKA
Regulated ID: 00008114
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4159643600
Mail To: Not reported
Mailing Address: 1010 EL MONTE
Mailing Address 2: Not reported
Mailing City,St,Zip: MOUNTAIN VIEW 94040
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

CUPA SANTA CLARA:
Name: EL MONTE CHEVRON SITE#376375
Address: 1010 EL MONTE AV
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: SANTA CLARA
PE#: 2205
Program Description: GENERATES 100 KG YR TO <5 TONS/YR
Latitude: 37.390397
Longitude: -122.096075
Record ID: PR0381244
Facility ID: FA0260137

E26 **ELMONTE CHEVRON** **RCRA NonGen / NLR** **1024875450**
NW **1010 EL MONTE** **CAL912612806**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.101 mi.
531 ft. **Site 6 of 8 in cluster E**

Relative: RCRA NonGen / NLR:
Lower
Date Form Received by Agency: 1991-09-18 00:00:00.0
Actual: Handler Name: ELMONTE CHEVRON
101 ft. Handler Address: 1010 EL MONTE
Handler City,State,Zip: MOUNTAIN VIEW, CA 94040-0000
EPA ID: CAL912612806
Contact Name: HASSAN KHAZIRI
Contact Address: 1010 EL MONTE AVE
Contact City,State,Zip: MOUNTAIN VIEW, CA 94040
Contact Telephone: 650-964-3600
Contact Fax: 650-964-3600
Contact Email: HASSANKHAZIRI@YAHOO.COM
Contact Title: Not reported
EPA Region: 09

ELMONTE CHEVRON (Continued) **1024875450**

Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1010 EL MONTE AVE
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94040-2321
Owner Name:	HASSAN KHAZIRI
Owner Type:	Other
Operator Name:	HASSAN KHAZIRI
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No

ELMONTE CHEVRON (Continued) **1024875450**

Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-07 19:39:03.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	HASSAN KHAZIRI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1010 EL MONTE AVE
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040-2321
Owner/Operator Telephone:	650-964-3600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	HASSAN KHAZIRI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1010 EL MONTE AVE
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-964-3600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1991-09-18 00:00:00.0
Handler Name: ELMONTE CHEVRON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	44719
NAICS Description:	OTHER GASOLINE STATIONS

ELMONTE CHEVRON (Continued) **1024875450**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

E27 **RICKS UNION 76** **EDR Hist Auto** **1021487777**
NW **1010 EL MONTE** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.101 mi.
531 ft. **Site 7 of 8 in cluster E**

Relative: EDR Hist Auto
Lower

Actual:
101 ft.

Year:	Name:	Type:
1975	RICKS UNION 76	Gasoline Service Stations
1976	RICKS UNION 76	Gasoline Service Stations
1977	RICKS UNION 76	Gasoline Service Stations
1978	RICKS UNION 76	Gasoline Service Stations
1979	RICKS UNION 76	Gasoline Service Stations
1980	RICKS UNION 76	Gasoline Service Stations
1982	RICKS UNION 76	Gasoline Service Stations
1983	RICKS UNION 76	Gasoline Service Stations
1990	EL MONTE UNION SVC	Elementary And Secondary Schools, NEC
1991	EL MONTE UNION SVC	Elementary And Secondary Schools, NEC
1992	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
1993	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
1994	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
1995	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
1996	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
1997	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
1998	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
1999	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
2000	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
2001	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
2002	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
2003	EL MONTE UNION SERVICE	Elementary And Secondary Schools, NEC
2004	EL MONTE UNION SERVICE	Gasoline Service Stations
2005	EL MONTE UNION SERVICE	Gasoline Service Stations
2006	EL MONTE UNION SERVICE	Gasoline Service Stations
2007	EL MONTE UNION SERVICE	Gasoline Service Stations
2008	EL MONTE UNION SERVICE	Gasoline Service Stations
2009	EL MONTE UNION SERVICE	Gasoline Service Stations
2010	EL MONTE UNION SERVICE	Gasoline Service Stations
2011	EL MONTE UNION SERVICE	Gasoline Service Stations
2012	EL MONTE UNION SERVICE	Gasoline Service Stations
2013	EL MONTE UNION SERVICE	Gasoline Service Stations
2014	EL MONTE UNION SERVICE	Gasoline Service Stations

D28 ENE < 1/8 0.108 mi. 572 ft. **PRENATAL DIAGNOSTICS INC**
1580 W EL CAMINO REAL SUITE 2
MOUNTAIN VIEW, CA 94040
Site 2 of 11 in cluster D

Database(s): RCRA-SQG, FINDS, ECHO
EDR ID Number: 1000307547
EPA ID Number: CAD982497745

Relative: Lower
Actual: 99 ft.

RCRA-SQG:

Date Form Received by Agency:	1990-02-02 00:00:00.0
Handler Name:	PRENATAL DIAGNOSTICS INC
Handler Address:	1580 W EL CAMINO REAL SUITE 2
Handler City,State,Zip:	MOUNTAIN VIEW, CA 94040
EPA ID:	CAD982497745
Contact Name:	ENVIRONMENTAL MANAGER
Contact Address:	1580 W EL CAMINO REAL SUITE 2
Contact City,State,Zip:	MOUNTAIN VIEW, CA 94040
Contact Telephone:	415-966-8599
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Other
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	2
Mailing Address:	1580 W EL CAMINO REAL SUITE 2
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner Name:	WILLIAM J CONTE
Owner Type:	Private
Operator Name:	NOT REQUIRED
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

PRENATAL DIAGNOSTICS INC (Continued) **1000307547**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:34:33.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WILLIAM J CONTE
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

PRENATAL DIAGNOSTICS INC (Continued) **1000307547**

Historic Generators:
Receive Date: 1990-02-02 00:00:00.0
Handler Name: PRENATAL DIAGNOSTICS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 62231
NAICS Description: SPECIALTY (EXCEPT PSYCHIATRIC AND SUBSTANCE ABUSE) HOSPITALS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110002832132

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000307547
Registry ID: 110002832132
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002832132
Name: PRENATAL DIAGNOSTICS INC
Address: 1580 W EL CAMINO REAL SUITE 2
City,State,Zip: MOUNTAIN VIEW, CA 94040

D29 **JENNY LU, DDS** **RCRA NonGen / NLR** **1024791442**
ENE **1580 W EL CAMINO REAL #3** **CAL000105441**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.108 mi.
572 ft. **Site 3 of 11 in cluster D**

Relative: **Lower**
Actual: **99 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		1999-03-25 00:00:00.0
Handler Name:	JENNY LU, DDS	
Handler Address:		1580 W EL CAMINO REAL #3
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94040-0000
EPA ID:		CAL000105441
Contact Name:		JENNY LU, DDS
Contact Address:		1580 W EL CAMINO REAL STE 3
Contact City,State,Zip:		MOUNTAIN VIEW, CA 94040
Contact Telephone:		650-625-8337
Contact Fax:		650-625-8339
Contact Email:		JENNY_LU_DDS@SBCGLOBAL.NET
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1580 W EL CAMINO REAL STE 3
Mailing City,State,Zip:		MOUNTAIN VIEW, CA 94040-2461
Owner Name:		JENNY LU, DDS
Owner Type:		Other
Operator Name:		JENNY LU, DDS
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

JENNY LU, DDS (Continued) **1024791442**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 15:42:28.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	JENNY LU, DDS
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1580 W EL CAMINO REAL STE 3
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-625-8337
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JENNY LU, DDS
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1580 W EL CAMINO REAL STE 3
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040-2461
Owner/Operator Telephone:	650-625-8337
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

JENNY LU, DDS (Continued) **1024791442**

Historic Generators:
Receive Date: 1999-03-25 00:00:00.0
Handler Name: JENNY LU, DDS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 42145
NAICS Description: MEDICAL, DENTAL, AND HOSPITAL EQUIPMENT AND SUPPLIES WHOLESALERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D30 **PRENATAL DIAGNOSTICS INC** **CUPA Listings** **S121468938**
ENE **1580 W EL CAMINO REAL 2** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.108 mi.
572 ft. **Site 4 of 11 in cluster D**

Relative: **Lower**
Actual: **99 ft.**

CUPA SANTA CLARA:
Name: PRENATAL DIAGNOSTICS INC
Address: 1580 W EL CAMINO REAL 2
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: SANTA CLARA
PE#: 2205
Program Description: GENERATES 100 KG YR TO <5 TONS/YR
Latitude: 37.390062
Longitude: -122.092117
Record ID: PR0313560
Facility ID: FA0203540

D31 **YEN-PING LEE DDS, MS. INC.** **RCRA NonGen / NLR** **1024810499**
ENE **1580 W EL CAMINO REAL STE 7** **CAL000290011**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.108 mi.
572 ft. **Site 5 of 11 in cluster D**

Relative: **Lower**
Actual: **99 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 2005-01-04 00:00:00.0
Handler Name: YEN-PING LEE DDS, MS. INC.
Handler Address: 1580 W EL CAMINO REAL STE 7
Handler City,State,Zip: MOUNTAIN VIEW, CA 94040

YEN-PING LEE DDS, MS. INC. (Continued) **1024810499**

EPA ID:	CAL000290011
Contact Name:	MING YEH
Contact Address:	2225 GRANT ROAD
Contact City,State,Zip:	LOS ALTOS, CA 94024
Contact Telephone:	650-938-8858
Contact Fax:	650-938-8857
Contact Email:	DRYEH@SBCGLOBAL.NET
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	2225 GRANT ROAD
Mailing City,State,Zip:	LOS ALTOS, CA 94024-0000
Owner Name:	YEN PING LEE
Owner Type:	Other
Operator Name:	MING YEH
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

YEN-PING LEE DDS, MS. INC. (Continued) **1024810499**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 20:26:17.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	MING YEH
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2225 GRANT ROAD
Owner/Operator City,State,Zip:	LOS ALTOS, CA 94024
Owner/Operator Telephone:	650-938-8858
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	YEN PING LEE
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2225 GRANT ROAD
Owner/Operator City,State,Zip:	LOS ALTOS, CA 94024-0000
Owner/Operator Telephone:	650-938-8858
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2005-01-04 00:00:00.0
Handler Name: YEN-PING LEE DDS, MS. INC.	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

YEN-PING LEE DDS, MS. INC. (Continued) **1024810499**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	62121
NAICS Description:	OFFICES OF DENTISTS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

D32 **JENNY LU DDS** **CUPA Listings** **S107145858**
ENE **1580 W EL CAMINO REAL 3** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.108 mi.
572 ft. **Site 6 of 11 in cluster D**

Relative: **Lower**
Actual: **99 ft.**

CUPA SANTA CLARA:

Name:	JENNY LU DDS
Address:	1580 W EL CAMINO REAL 3
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2240
Program Description:	GENERATES < 10 GAL/YR
Latitude:	37.3902821
Longitude:	-122.0928354
Record ID:	PR0388843
Facility ID:	FA0263855

D33 **MCLOED GLASS COMPANY** **HIST UST** **U001594326**
East **1495 W EL CAMINO REAL** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.124 mi.
655 ft. **Site 7 of 11 in cluster D**

Relative: **Lower**
Actual: **103 ft.**

HIST UST:

Name:	MCLOED GLASS COMPANY
Address:	1495 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000065512
Facility Type:	Other
Other Type:	GLASS
Contact Name:	Not reported
Telephone:	4159675763
Owner Name:	MCLOED GLASS COMPANY
Owner Address:	1495 W. EL CAMINO REAL

MCLOED GLASS COMPANY (Continued) **U001594326**

Owner City,St,Zip: MOUNTAIN VIEW, CA 94040
Total Tanks: 0001

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00000500
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: 3/16
Leak Detection: Stock Inventor

D34 **MCLOED GLASS COMPANY** **SWEEPS UST** **S101623006**
East **1495 W EL CAMINO REAL** **CA FID UST** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.124 mi.
655 ft. **Site 8 of 11 in cluster D**

Relative:
Lower

Actual:
103 ft.

SWEEPS UST:
Name: MCLOED GLASS COMPANY
Address: 1495 W EL CAMINO REAL
City: MOUNTAIN VIEW
Status: Not reported
Comp Number: 65512
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 43-005-065512-000001
Tank Status: Not reported
Capacity: 500
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: REG UNLEADED
Number Of Tanks: 1

CA FID UST:
Facility ID: 43001731
Regulated By: UTNKI
Regulated ID: 00065512
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4159675763
Mail To: Not reported
Mailing Address: 1495 W EL CAMINO REAL
Mailing Address 2: Not reported
Mailing City,St,Zip: MOUNTAIN VIEW 94040
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Inactive

E35 **LINDELL CHIROPRACTIC** **CUPA Listings** **S115813055**
NW **998 EL MONTE AV** **N/A**
< 1/8 **MOUNTAIN VIEW, CA 94040**
0.125 mi.
658 ft. **Site 8 of 8 in cluster E**

Relative: CUPA SANTA CLARA:
Lower

Actual: Name:	LINDELL CHIROPRACTIC
98 ft. Address:	998 EL MONTE AV
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2271
Program Description:	SILVER WASTE ONLY <100 KG/YR
Latitude:	37.3909746
Longitude:	-122.0962267
Record ID:	PR0414863
Facility ID:	FA0274291

F36 **YULAN M. LEWIS** **RCRA NonGen / NLR** **1024780760**
ENE **725 MARIPOSA AVE. #304** **CAC003000722**
1/8-1/4 **MOUNTAIN VIEW, CA 94041**
0.129 mi.
680 ft. **Site 1 of 3 in cluster F**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:		2019-02-12 00:00:00.0
98 ft. Handler Name:	YULAN M. LEWIS	
Handler Address:		725 MARIPOSA AVE. #304
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94041
EPA ID:		CAC003000722
Contact Name:		YULAN M. LEWIS
Contact Address:		274 REDWOOD SHORES PARKWAY #PMB4
Contact City,State,Zip:		REDWOOD CITY, CA 94065
Contact Telephone:		650-996-5236
Contact Fax:		Not reported
Contact Email:		TIFFANY.RELIANCE@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		274 REDWOOD SHORES PARKWAY #PMB4
Mailing City,State,Zip:		REDWOOD CITY, CA 94065
Owner Name:		YULAN M. LEWIS
Owner Type:		Other
Operator Name:		YULAN M. LEWIS
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

YULAN M. LEWIS (Continued) **1024780760**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-02-22 19:41:27.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	YULAN M. LEWIS
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	274 REDWOOD SHORES PARKWAY #PMB4
Owner/Operator City,State,Zip:	REDWOOD CITY, CA 94065

YULAN M. LEWIS (Continued) **1024780760**

Owner/Operator Telephone: 650-996-5236
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: YULAN M. LEWIS
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 274 REDWOOD SHORES PARKWAY #PMB4
Owner/Operator City,State,Zip: REDWOOD CITY, CA 94065
Owner/Operator Telephone: 650-996-5236
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2019-02-12 00:00:00.0
Handler Name: YULAN M. LEWIS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F37 **PRITHI TRIVEDI** **RCRA NonGen / NLR** **1025831125**
ENE **725 MARIPOSA AVE UNIT 204** **CAC003010682**
1/8-1/4 **MOUNTAIN VIEW, CA 94041**
0.129 mi.
680 ft. **Site 2 of 3 in cluster F**

Relative: RCRA NonGen / NLR:
Lower Date Form Received by Agency: 2019-04-17 00:00:00.0
Actual: Handler Name: PRITHI TRIVEDI
98 ft. Handler Address: 725 MARIPOSA AVE UNIT 204
Handler City,State,Zip: MOUNTAIN VIEW, CA 94041
EPA ID: CAC003010682
Contact Name: PRITHI TRIVEDI
Contact Address: 725 MARIPOSA AVE UNIT 204

PRITHI TRIVEDI (Continued) **1025831125**

Contact City,State,Zip:	MOUNTAIN VIEW, CA 94041
Contact Telephone:	408-810-0782
Contact Fax:	Not reported
Contact Email:	PRITHI.TRIVEDI@GMAIL.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	725 MARIPOSA AVE UNIT 204
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94041
Owner Name:	PRITHI TRIVEDI
Owner Type:	Other
Operator Name:	PRITHI TRIVEDI
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

PRITHI TRIVEDI (Continued) **1025831125**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-06-26 18:52:23.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PRITHI TRIVEDI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	725 MARIPOSA AVE UNIT 204
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94041
Owner/Operator Telephone:	408-810-0782
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PRITHI TRIVEDI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	725 MARIPOSA AVE UNIT 204
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94041
Owner/Operator Telephone:	408-810-0782
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2019-04-17 00:00:00.0
Handler Name: PRITHI TRIVEDI	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

PRITHI TRIVEDI (Continued) **1025831125**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F38 **FLORENCE TING** **RCRA NonGen / NLR** **1026161671**
ENE **725 MARIPOSA AVE #108** **CAC003061654**
1/8-1/4 **MOUNTAIN VIEW, CA 94041**
0.129 mi.
680 ft. **Site 3 of 3 in cluster F**

Relative: **Lower**
Actual: **98 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-03-27 00:00:00.0
Handler Name:	FLORENCE TING	
Handler Address:		725 MARIPOSA AVE #108
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94041-1869
EPA ID:		CAC003061654
Contact Name:		FLORENCE TING
Contact Address:		725 MARIPOSA AVE #108
Contact City,State,Zip:		MOUNTAIN VIEW, CA 94041-1869
Contact Telephone:		650-210-0085
Contact Fax:		Not reported
Contact Email:		NICOLE@ENV-REM.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		725 MARIPOSA AVE #108
Mailing City,State,Zip:		MOUNTAIN VIEW, CA 94041-1869
Owner Name:		FLORENCE TING
Owner Type:		Other
Operator Name:		FLORENCE TING
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

FLORENCE TING (Continued) **1026161671**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-08 18:59:19.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FLORENCE TING
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	725 MARIPOSA AVE #108
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94041-1869

FLORENCE TING (Continued) **1026161671**

Owner/Operator Telephone: 650-210-0085
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: FLORENCE TING
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 725 MARIPOSA AVE #108
Owner/Operator City,State,Zip: MOUNTAIN VIEW, CA 94041-1869
Owner/Operator Telephone: 650-210-0085
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2020-03-27 00:00:00.0
Handler Name: FLORENCE TING
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D39 **A-1 FOREIGN AUTO RPR** **RCRA NonGen / NLR** **1024789486**
ENE **1544 W EL CAMINO REAL** **CAL000065867**
1/8-1/4 **MOUNTAIN VIEW, CA 94041**
0.134 mi.
710 ft. **Site 9 of 11 in cluster D**

Relative: **Lower**
Actual: **99 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 1992-03-11 00:00:00.0
Handler Name: A-1 FOREIGN AUTO RPR
Handler Address: 1544 W EL CAMINO REAL
Handler City,State,Zip: MOUNTAIN VIEW, CA 94041-0000
EPA ID: CAL000065867
Contact Name: KATHY KELEMEN
Contact Address: 1544 W EL CAMINO REAL

A-1 FOREIGN AUTO RPR (Continued) **1024789486**

Contact City,State,Zip:	MT VIEW, CA 94040
Contact Telephone:	650-966-8231
Contact Fax:	000-000-0000
Contact Email:	A1FOREIGN@YAHOO.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1544 W EL CAMINO REAL
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94040-0000
Owner Name:	JOHN KELEMEN
Owner Type:	Other
Operator Name:	KATHY KELEMEN
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No

A-1 FOREIGN AUTO RPR (Continued) **1024789486**

Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-05 15:41:55.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JOHN KELEMEN
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1544 W EL CAMINO REAL
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040-2451
Owner/Operator Telephone:	650-966-8231
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	KATHY KELEMEN
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1544 W EL CAMINO REAL
Owner/Operator City,State,Zip:	MT VIEW, CA 94040
Owner/Operator Telephone:	650-966-8231
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1992-03-11 00:00:00.0
Handler Name: A-1 FOREIGN AUTO RPR	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

A-1 FOREIGN AUTO RPR (Continued) **1024789486**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D40 A-1 FOREIGN AUTO **CERS HAZ WASTE S121753359**
ENE 1544 EL CAMINO REAL WEST **CERS N/A**
1/8-1/4 MOUNTAIN VIEW, CA 94040
0.134 mi.
710 ft. Site 10 of 11 in cluster D

Relative:
Lower

Actual:
99 ft.

CERS HAZ WASTE:
Name: A-1 FOREIGN AUTO
Address: 1544 EL CAMINO REAL WEST
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 2289
CERS ID: 10346284
CERS Description: Hazardous Waste Generator

CERS:
Name: A-1 FOREIGN AUTO
Address: 1544 EL CAMINO REAL WEST
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 2289
CERS ID: 10346284
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 2289
Site Name: A-1 Foreign Auto
Violation Date: 12-16-2015
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description: Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes: Returned to compliance on 12/22/2015. Make sure hazardous waste labels are affixed to the primary hazradous waste container; observed 2 x 55 gallon drums of used oil in the shed without proper accumulation start date on the label, however, the label affixed to the wall included the start date of accumulation.
Violation Division: Santa Clara County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 2289

A-1 FOREIGN AUTO (Continued) **S121753359**

Site Name:	A-1 Foreign Auto
Violation Date:	12-16-2015
Citation:	HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections
Violation Description:	Haz Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 12/22/2015. 2 x 55 gallon used oil drums in shed were open. 1 x 55 gallon waste coolant drum was open in the shed.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	03-03-2020
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	On-site to conduct a routine hazardous waste generator inspection. Facility is an auto repair shop that performs oil changes, coolant flushes and other auto repair services. Facility generates used oil, waste antifreeze and drained used oil filters, and paper filter waste. Facility also maintains a parts washer that is maintained by Cintas. According to the shop mechanic Nick, Cintas services the machine by topping off the parts washer fluid and does not replace the fluid unless the entire parts washer needs to be repaired by Cintas. A walkthrough of the hazardous waste storage area, dumpsters, yard, and shop was conducted during this inspection. Observed the following containers accumulating hazardous wastes: 3 x 55 gal drums of used oil in the hazardous waste storage area 1 x 55 gal drum of waste antifreeze in the hazardous waste storage area 1 x 55 gal drum of drained used oil filters located in the shop 1 x 55 gal drum of paper filters located in the shop 1 x 30 [Truncated]
Eval Division:	Santa Clara County Environmental Health
Eval Program:	HW
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-10-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	No Violations.
Eval Division:	Mountain View Fire Department
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	09-21-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	No Violations.
Eval Division:	Mountain View Fire Department
Eval Program:	HMRRP
Eval Source:	CERS

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-07-2013
Violations Found:	No
Eval Type:	Routine done by local agency

A-1 FOREIGN AUTO (Continued) **S121753359**

Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-16-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Santa Clara County Environmental Health
Eval Program: HW
Eval Source: CERS

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 1544 West El Camino Real
Affiliation City: Mountain View
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94040
Affiliation Phone: Not reported

Affiliation Type Desc: Operator
Entity Name: John & Kathy Kelemen
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (650) 966-8231

Affiliation Type Desc: Parent Corporation
Entity Name: A-1 Foreign Auto
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Property Owner
Entity Name: John & Kathy Kelemen
Entity Title: Not reported
Affiliation Address: 1544 West El Camino Real
Affiliation City: Mountain View
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94040
Affiliation Phone: (650) 964-4408

Affiliation Type Desc: CUPA District
Entity Name: Santa Clara County Environmental Health

A-1 FOREIGN AUTO (Continued) **S121753359**

Entity Title:	Not reported
Affiliation Address:	1555 Berger Drive, Suite 300
Affiliation City:	San Jose
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95112-2716
Affiliation Phone:	(408) 918-3400
Affiliation Type Desc:	Environmental Contact
Entity Name:	Kathy Kelemen
Entity Title:	Not reported
Affiliation Address:	1544 West El Camino Real
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	94040
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	kathy kelemen
Entity Title:	owner
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	John & Kathy Kelemen
Entity Title:	Not reported
Affiliation Address:	1544 West El Camino Real
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94040
Affiliation Phone:	(650) 966-8231

D41 **A-1 FOREIGN AUTO** **CUPA Listings** **S105722678**
ENE **1544 W EL CAMINO REAL** **N/A**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.134 mi.
710 ft. **Site 11 of 11 in cluster D**

Relative: **Lower**

Actual: **99 ft.**

CUPA SANTA CLARA:

Name:	A-1 FOREIGN AUTO
Address:	1544 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2205
Program Description:	GENERATES 100 KG YR TO <5 TONS/YR
Latitude:	37.389899
Longitude:	-122.091781
Record ID:	PR0313836
Facility ID:	FA0203528

42 WNW 1/8-1/4 0.146 mi. 773 ft. | **SANDRA CARRICO**
1843 ANTHONY CT
MOUNTAIN VIEW, CA 94040 | **RCRA NonGen / NLR** | **1025829038 / CAC003008592**

Relative: Higher
Actual: 105 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		2019-04-03 00:00:00.0
Handler Name:	SANDRA CARRICO	
Handler Address:		1843 ANTHONY CT
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94040
EPA ID:		CAC003008592
Contact Name:		SANDRA CARRICO
Contact Address:		1843 ANTHONY CT
Contact City,State,Zip:		MOUNTAIN VIEW, CA 94040
Contact Telephone:		650-996-7799
Contact Fax:		Not reported
Contact Email:		ELIZABETH.GARCIA@SYNERGYCOMPANIES.ORG
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1843 ANTHONY CT
Mailing City,State,Zip:		MOUNTAIN VIEW, CA 94040
Owner Name:		SANDRA CARRICO
Owner Type:		Other
Operator Name:		SANDRA CARRICO
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

SANDRA CARRICO (Continued) **1025829038**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-06-26 18:51:43.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SANDRA CARRICO
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1843 ANTHONY CT
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-996-7799
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	SANDRA CARRICO
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1843 ANTHONY CT
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-996-7799
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SANDRA CARRICO (Continued) **1025829038**

Historic Generators:
Receive Date: 2019-04-03 00:00:00.0
Handler Name: SANDRA CARRICO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

43
East
1/8-1/4
0.149 mi.
789 ft.

CHIROPRACTIC PERFORMANCE CENTER
1411 EL CAMINO REAL B
MOUNTAIN VIEW, CA 94040

CUPA Listings **S121472807**
N/A

Relative:
Lower

Actual:
102 ft.

CUPA SANTA CLARA:
Name: CHIROPRACTIC PERFORMANCE CENTER
Address: 1411 EL CAMINO REAL B
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: SANTA CLARA
PE#: 2271
Program Description: SILVER WASTE ONLY <100 KG/YR
Latitude: 37.38884
Longitude: -122.090636
Record ID: PR0317631
Facility ID: FA0255985

44
NW
1/8-1/4
0.167 mi.
884 ft.

EZZY SCHUSTERMAN
1758 MARICH WAY
MOUNTAIN VIEW, CA 94040

RCRA NonGen / NLR **1026167390**
CAC003067431

Relative:
Lower

Actual:
100 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 2020-05-19 00:00:00.0
Handler Name: EZZY SCHUSTERMAN
Handler Address: 1758 MARICH WAY
Handler City,State,Zip: MOUNTAIN VIEW, CA 94040

EZZY SCHUSTERMAN (Continued) **1026167390**

EPA ID:	CAC003067431
Contact Name:	EZZY SCHUSTERMAN
Contact Address:	1758 MARICH WAY
Contact City,State,Zip:	MOUNTAIN VIEW, CA 94040
Contact Telephone:	917-602-5432
Contact Fax:	Not reported
Contact Email:	ROSAMARTINEZ@ALLIANCE-ENVIRO.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1758 MARICH WAY
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner Name:	EZZY SCHUSTERMAN
Owner Type:	Other
Operator Name:	EZZY SCHUSTERMAN
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

EZZY SCHUSTERMAN (Continued) **1026167390**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-06-08 20:36:12.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	EZZY SCHUSTERMAN
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1758 MARICH WAY
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	917-602-5432
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	EZZY SCHUSTERMAN
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1758 MARICH WAY
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	917-602-5432
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-05-19 00:00:00.0
Handler Name: EZZY SCHUSTERMAN	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

EZZY SCHUSTERMAN (Continued) **1026167390**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G45 **BEACON STATION #588** **HIST UST** **U001594303**
NNW **1820 W EL CAMINO REAL** **N/A**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.185 mi.
977 ft. **Site 1 of 3 in cluster G**

Relative: **Lower**
Actual: **94 ft.**

HIST UST:
Name: BEACON STATION #588
Address: 1820 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000038867
Facility Type: Gas Station
Other Type: Not reported
Contact Name: TIM ROBERTSON
Telephone: 2095820241
Owner Name: BEACON OIL COMPANY
Owner Address: 525 W. THIRD STREET
Owner City,St,Zip: HANFORD, CA 93230
Total Tanks: 0005

Tank Num: 001
Container Num: #588-2
Year Installed: 1969
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: .025
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: #588-3
Year Installed: 1969
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: .025

BEACON STATION #588 (Continued) **U001594303**

Leak Detection: Stock Inventor

Tank Num: 003
Container Num: #588-4
Year Installed: 1969
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Container Construction Thickness: .025
Leak Detection: Stock Inventor

Tank Num: 004
Container Num: #588-5
Year Installed: 1969
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: WASTE OIL
Container Construction Thickness: 14
Leak Detection: None

Tank Num: 005
Container Num: #588-6
Year Installed: 1969
Tank Capacity: 00000010
Tank Used for: Not reported
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: None

G46 **BEACON STATION #588** **SWEEPS UST** **S101622990**
NNW **1820 EL CAMINO REAL WEST** **HIST UST** **N/A**
1/8-1/4 **MOUNTAIN VIEW, CA 94040** **CA FID UST**
0.185 mi.
977 ft. **Site 2 of 3 in cluster G**

Relative: **Lower**
Actual: **94 ft.**

SWEEPS UST:
Name: BEACON STATION #588
Address: 1820 EL CAMINO REAL WEST
City: MOUNTAIN VIEW
Status: Not reported
Comp Number: 38867
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 43-005-038867-000001
Tank Status: Not reported
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: 4

Name: BEACON STATION #588
Address: 1820 EL CAMINO REAL WEST

BEACON STATION #588 (Continued) **S101622990**

City:	MOUNTAIN VIEW
Status:	Not reported
Comp Number:	38867
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	43-005-038867-000002
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	BEACON STATION #588
Address:	1820 EL CAMINO REAL WEST
City:	MOUNTAIN VIEW
Status:	Not reported
Comp Number:	38867
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	43-005-038867-000003
Tank Status:	Not reported
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	BEACON STATION #588
Address:	1820 EL CAMINO REAL WEST
City:	MOUNTAIN VIEW
Status:	Not reported
Comp Number:	38867
Number:	Not reported
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	43-005-038867-000004
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	OIL
STG:	WASTE
Content:	WASTE OIL
Number Of Tanks:	Not reported

BEACON STATION #588 (Continued) **S101622990**

HIST UST:

Name:	BEACON STATION 588
Address:	1820 EL CAMINO REAL WEST
City,State,Zip:	MOUNTAIN VIEW, CA 94040
File Number:	0002CE8D
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002CE8D.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

CA FID UST:

Facility ID:	43011924
Regulated By:	UTNKI
Regulated ID:	00038867
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	2095820241
Mail To:	Not reported
Mailing Address:	525 W 003RD ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MOUNTAIN VIEW 94040
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Inactive

H47 **MARIPOSA APARTMENTS** **RCRA NonGen / NLR** **1026049531**
NE **660 MARIPOSA AVE** **CAC003056279**
1/8-1/4 **MOUNTAIN VIEW, CA 94041**
0.192 mi.
1016 ft. **Site 1 of 3 in cluster H**

Relative: **Lower**
Actual: **93 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-02-18 00:00:00.0
Handler Name:	MARIPOSA APARTMENTS	
Handler Address:		660 MARIPOSA AVE
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94041
EPA ID:		CAC003056279
Contact Name:		VICTOR FERNANDEZ
Contact Address:		1900 S. NORFOLK STREET
Contact City,State,Zip:		SAN MATEO, CA 94403
Contact Telephone:		650-931-3400
Contact Fax:		Not reported
Contact Email:		VFERNANDEZ@PROMETHEUSREG.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1900 S. NORFOLK STREET
Mailing City,State,Zip:		SAN MATEO, CA 94403
Owner Name:		MARIPOSA CLUB APARTMENTS I, LP
Owner Type:		Other
Operator Name:		VICTOR FERNANDEZ
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

MARIPOSA APARTMENTS (Continued) **1026049531**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-03-06 18:10:53.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	VICTOR FERNANDEZ
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1900 S. NORFOLK STREET
Owner/Operator City,State,Zip:	SAN MATEO, CA 94403
Owner/Operator Telephone:	650-931-3400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MARIPOSA CLUB APARTMENTS I, LP
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1900 S. NORFOLK STREET
Owner/Operator City,State,Zip:	SAN MATEO, CA 94403
Owner/Operator Telephone:	650-931-3400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

MARIPOSA APARTMENTS (Continued) **1026049531**

Historic Generators:
- Receive Date: 2020-02-18 00:00:00.0
- Handler Name: MARIPOSA APARTMENTS
- Federal Waste Generator Description: Not a generator, verified
- State District Owner: Not reported
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Code: 53111
- NAICS Description: LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

H48 **MARIPOSA APARTMENTS** **RCRA NonGen / NLR** **1025857995**
NE **660 MARIPOSA AVE** **CAC003038483**
1/8-1/4 **MOUNTAIN VIEW, CA 94041**
0.192 mi.
1016 ft. **Site 2 of 3 in cluster H**

Relative: **Lower**
Actual: **93 ft.**

RCRA NonGen / NLR:
- Date Form Received by Agency: 2019-10-14 00:00:00.0
- Handler Name: MARIPOSA APARTMENTS
- Handler Address: 660 MARIPOSA AVE
- Handler City,State,Zip: MOUNTAIN VIEW, CA 94041
- EPA ID: CAC003038483
- Contact Name: VICTOR FERNANDEZ
- Contact Address: 1900 S NORFOLK ST
- Contact City,State,Zip: SAN MATEO, CA 94403
- Contact Telephone: 650-931-3400
- Contact Fax: Not reported
- Contact Email: VFERNANDEZ@PROMETHEUSREG.COM
- Contact Title: Not reported
- EPA Region: 09
- Land Type: Not reported
- Federal Waste Generator Description: Not a generator, verified
- Non-Notifier: Not reported
- Biennial Report Cycle: Not reported
- Accessibility: Not reported
- Active Site Indicator: Not reported
- State District Owner: Not reported
- State District: Not reported
- Mailing Address: 1900 S NORFOLK ST
- Mailing City,State,Zip: SAN MATEO, CA 94403
- Owner Name: MARIPOSA CLUB APARTMENTS I, LP

MARIPOSA APARTMENTS (Continued) **1025857995**

Owner Type:	Other
Operator Name:	VICTOR FERNANDEZ
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-10-21 14:11:28.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

MARIPOSA APARTMENTS (Continued) **1025857995**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: VICTOR FERNANDEZ
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1900 S NORFOLK ST
Owner/Operator City,State,Zip: SAN MATEO, CA 94403
Owner/Operator Telephone: 650-931-3400
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MARIPOSA CLUB APARTMENTS I, LP
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1900 S NORFOLK ST
Owner/Operator City,State,Zip: SAN MATEO, CA 94403
Owner/Operator Telephone: 650-931-3400
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2019-10-14 00:00:00.0
Handler Name: MARIPOSA APARTMENTS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 531110
NAICS Description: LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Date Form Received by Agency: 2020-09-11 00:00:00.0
Handler Name: MARIPOSA APARTMENTS

MARIPOSA APARTMENTS (Continued) **1025857995**

Handler Address:	660 MARIPOSA AVE
Handler City,State,Zip:	MOUNTAIN VIEW, CA 94041
EPA ID:	CAC003083277
Contact Name:	VICTOR FERNANDEZ
Contact Address:	1900 S. NORFOLK STREET
Contact City,State,Zip:	SAN MATEO, CA 94403
Contact Telephone:	650-931-3400
Contact Fax:	Not reported
Contact Email:	VFERNANDEZ@PROMETHEUSREG.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1900 S. NORFOLK STREET
Mailing City,State,Zip:	SAN MATEO, CA 94403
Owner Name:	MARIPOSA CLUB APARTMENTS I, LP
Owner Type:	Other
Operator Name:	VICTOR FERNANDEZ
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No

MARIPOSA APARTMENTS (Continued) **1025857995**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-09-20 14:39:34.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	VICTOR FERNANDEZ
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1900 S. NORFOLK STREET
Owner/Operator City,State,Zip:	SAN MATEO, CA 94403
Owner/Operator Telephone:	650-931-3400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MARIPOSA CLUB APARTMENTS I, LP
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1900 S. NORFOLK STREET
Owner/Operator City,State,Zip:	SAN MATEO, CA 94403
Owner/Operator Telephone:	650-931-3400
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-09-11 00:00:00.0
Handler Name: MARIPOSA APARTMENTS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No

MARIPOSA APARTMENTS (Continued) **1025857995**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 53111
NAICS Description: LESSORS OF RESIDENTIAL BUILDINGS AND DWELLINGS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

H49 **BRIDGE HOUSING CORPORATION C/O BRAD WIBLIN** **RCRA NonGen / NLR** **1025857124**
NE **660 MARIPOSA AVE** **CAC003037534**
1/8-1/4 **MOUNTAIN VIEW, CA 94041**
0.192 mi.
1016 ft. **Site 3 of 3 in cluster H**

Relative: **Lower**
Actual: **93 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 2019-10-07 00:00:00.0
Handler Name: BRIDGE HOUSING CORPORATION C/O BRAD WIBLIN
Handler Address: 660 MARIPOSA AVE
Handler City,State,Zip: MOUNTAIN VIEW, CA 94041-1867
EPA ID: CAC003037534
Contact Name: BRIDGE HOUSING CORPORATION C/O BRA
Contact Address: 600 CALIFORNIA ST
Contact City,State,Zip: SAN FRANCISCO, CA 94108
Contact Telephone: 415-989-1111
Contact Fax: Not reported
Contact Email: ADELENEV@CVECORP.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Not reported
State District: Not reported
Mailing Address: 600 CALIFORNIA ST
Mailing City,State,Zip: SAN FRANCISCO, CA 94108
Owner Name: BRIDGE HOUSING CORPORATION C/O BRA
Owner Type: Other
Operator Name: BRIDGE HOUSING CORPORATION C/O BRA
Operator Type: Other
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No

BRIDGE HOUSING CORPORATION C/O BRAD WIBLIN (Continued) **1025857124**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-10-11 18:28:55.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BRIDGE HOUSING CORPORATION C/O BRA

BRIDGE HOUSING CORPORATION C/O BRAD WIBLIN (Continued) **1025857124**

Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	600 CALIFORNIA ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94108
Owner/Operator Telephone:	415-989-1111
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	BRIDGE HOUSING CORPORATION C/O BRA
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	600 CALIFORNIA ST
Owner/Operator City,State,Zip:	SAN FRANCISCO, CA 94108
Owner/Operator Telephone:	415-989-1111
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2019-10-07 00:00:00.0
Handler Name:	BRIDGE HOUSING CORPORATION C/O BRAD WIBLIN
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

50
SW
1/8-1/4
0.194 mi.
1024 ft.

JERRY KWOK
659 SPARGUR DR
LOS ALTOS, CA 94022

RCRA NonGen / NLR

1025864776
CAC003045611

Relative:
Higher

Actual:
115 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		2019-12-03 00:00:00.0
Handler Name:	JERRY KWOK	
Handler Address:		659 SPARGUR DR
Handler City,State,Zip:		LOS ALTOS, CA 94022-2366
EPA ID:		CAC003045611
Contact Name:		JERRY KWOK
Contact Address:		659 SPARGUR DR
Contact City,State,Zip:		LOS ALTOS, CA 94022-2366
Contact Telephone:		408-507-3291
Contact Fax:		Not reported
Contact Email:		LIZDUENAS@ALLIANCE-ENVIRO.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		659 SPARGUR DR
Mailing City,State,Zip:		LOS ALTOS, CA 94022-2366
Owner Name:		JERRY KWOK
Owner Type:		Other
Operator Name:		JERRY KWOK
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

JERRY KWOK (Continued) **1025864776**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-12-06 16:31:17.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	JERRY KWOK
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	659 SPARGUR DR
Owner/Operator City,State,Zip:	LOS ALTOS, CA 94022-2366
Owner/Operator Telephone:	408-507-3291
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	JERRY KWOK
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	659 SPARGUR DR
Owner/Operator City,State,Zip:	LOS ALTOS, CA 94022-2366
Owner/Operator Telephone:	408-507-3291
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

JERRY KWOK (Continued) **1025864776**

Historic Generators:
Receive Date: 2019-12-03 00:00:00.0
Handler Name: JERRY KWOK
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I51 **OFFICE DEPOT 869** **RCRA NonGen / NLR** **1024856843**
NNW **910 EL MONTE AVE** **CAL000421200**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.196 mi.
1036 ft. **Site 1 of 4 in cluster I**

Relative:
Lower

Actual:
95 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 2016-10-14 00:00:00.0
Handler Name: OFFICE DEPOT 869
Handler Address: 910 EL MONTE AVE
Handler City,State,Zip: MOUNTAIN VIEW, CA 94040
EPA ID: CAL000421200
Contact Name: ANA FERNANDEZ
Contact Address: 6600 N MILITARY TRAIL C456
Contact City,State,Zip: BOCA RATON, FL 33496
Contact Telephone: 561-438-7903
Contact Fax: 561-438-8916
Contact Email: ANA.FERNANDEZ@OFFICEDEPOT.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: 6600 N MILITARY TRAIL C456
Mailing City,State,Zip: BOCA RATON, FL 33496-0000
Owner Name: OFFICE DEPOT INC

OFFICE DEPOT 869 (Continued) **1024856843**

Owner Type:	Other
Operator Name:	ANA FERNANDEZ
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2018-09-07 19:35:10.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

OFFICE DEPOT 869 (Continued) **1024856843**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: OFFICE DEPOT INC
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 6600 N MILITARY TRAIL
Owner/Operator City,State,Zip: BOCA RATON, FL 33496
Owner/Operator Telephone: 561-438-4800
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ANA FERNANDEZ
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 6600 N MILITARY TRAIL C456
Owner/Operator City,State,Zip: BOCA RATON, FL 33496
Owner/Operator Telephone: 561-438-7903
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2016-10-14 00:00:00.0
Handler Name: OFFICE DEPOT 869
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 45321
NAICS Description: OFFICE SUPPLIES AND STATIONERY STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I52 **OFFICE DEPOT #869** **CERS HAZ WASTE** **S121782438**
NNW **910 EL MONTE AV** **CUPA Listings** **N/A**
1/8-1/4 **MOUNTAIN VIEW, CA 94040** **HAZNET**
0.196 mi. **HWTS**
1036 ft. **Site 2 of 4 in cluster I**

Relative:
Lower

Actual:
95 ft.

CERS HAZ WASTE:

Name:	OFFICE DEPOT #869
Address:	910 EL MONTE AVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Site ID:	426274
CERS ID:	10706833
CERS Description:	Hazardous Waste Generator

Coordinates:

Site ID:	426274
Facility Name:	Office Depot #869
Env Int Type Code:	HWG
Program ID:	10706833
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.
Latitude:	37.392090
Longitude:	-122.096570

Affiliation:

Affiliation Type Desc:	Legal Owner
Entity Name:	Office Depot, Inc.
Entity Title:	Not reported
Affiliation Address:	6600 N. Military Trail
Affiliation City:	Boca Raton
Affiliation State:	FL
Affiliation Country:	United States
Affiliation Zip:	33496
Affiliation Phone:	(561) 438-4800

Affiliation Type Desc:	Parent Corporation
Entity Name:	Office Depot, Inc.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

Affiliation Type Desc:	Property Owner
Entity Name:	Barber Family Properties LLC
Entity Title:	Not reported
Affiliation Address:	16794 Alioto Drive
Affiliation City:	Grass Valley
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95949
Affiliation Phone:	(530) 272-8141

Affiliation Type Desc:	Document Preparer
Entity Name:	John Storlie
Entity Title:	Not reported
Affiliation Address:	Not reported

OFFICE DEPOT #869 (Continued) **S121782438**

Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Environmental Contact
Entity Name:	Wendi Lane
Entity Title:	Not reported
Affiliation Address:	6600 N. Military Trail, Mail Code C492
Affiliation City:	Boca Raton
Affiliation State:	FL
Affiliation Country:	Not reported
Affiliation Zip:	33496
Affiliation Phone:	Not reported
Affiliation Type Desc:	CUPA District
Entity Name:	Santa Clara County Environmental Health
Entity Title:	Not reported
Affiliation Address:	1555 Berger Drive, Suite 300
Affiliation City:	San Jose
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95112-2716
Affiliation Phone:	(408) 918-3400
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	6600 N. Military Trail C415P
Affiliation City:	Boca Raton
Affiliation State:	FL
Affiliation Country:	Not reported
Affiliation Zip:	33496
Affiliation Phone:	Not reported
Affiliation Type Desc:	Identification Signer
Entity Name:	John Storlie
Entity Title:	Consultant acting for Office Depot
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Operator
Entity Name:	Office Depot, Inc.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(650) 964-8249

OFFICE DEPOT #869 (Continued) **S121782438**

CUPA SANTA CLARA:

Name:	OFFICE DEPOT #869
Address:	910 EL MONTE AV
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2202
Program Description:	GENERATES < 100 KG/YR
Latitude:	37.3921785
Longitude:	-122.0966595
Record ID:	PR0432649
Facility ID:	FA0288540

HAZNET:

Name:	OFFICE DEPOT 869
Address:	910 EL MONTE AVE
Address 2:	Not reported
City,State,Zip:	MOUNTAIN VIEW, CA 334960000
Contact:	WENDI LANE
Telephone:	5614385558
Mailing Name:	Not reported
Mailing Address:	6600 N MILITARY TRAIL C492
Year:	2019
Gepaid:	CAL000421200
TSD EPA ID:	NVD980895338
CA Waste Code:	214 - Unspecified solvent mixture
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.00850
Year:	2019
Gepaid:	CAL000421200
TSD EPA ID:	CAD008364432
CA Waste Code:	122 - Alkaline solution without metals pH >= 12.5
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.00300
Year:	2019
Gepaid:	CAL000421200
TSD EPA ID:	AZR000515924
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.05700
Year:	2019
Gepaid:	CAL000421200
TSD EPA ID:	NVD980895338
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.00250
Year:	2018
Gepaid:	CAL000421200

OFFICE DEPOT #869 (Continued) **S121782438**

TSD EPA ID: NVD980895338
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.00150

Year: 2018
Gepaid: CAL000421200
TSD EPA ID: CAD008364432
CA Waste Code: 122 - Alkaline solution without metals pH >= 12.5
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.03350

Year: 2017
Gepaid: CAL000421200
TSD EPA ID: NVD980895338
CA Waste Code: 331 - Off-specification, aged or surplus organics
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.002

Year: 2017
Gepaid: CAL000421200
TSD EPA ID: CAD008364432
CA Waste Code: 331 - Off-specification, aged or surplus organics
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0205

Year: 2017
Gepaid: CAL000421200
TSD EPA ID: CAD008364432
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0015

Year: 2017
Gepaid: CAL000421200
TSD EPA ID: NVD980895338
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0005

Click this hyperlink while viewing on your computer to access additional CA HAZNET: detail in the EDR Site Report.

Additional Info:
Year: 2017
Gen EPA ID: CAL000421200

Shipment Date: 20171026
Creation Date: 8/27/2018 18:30:14
Receipt Date: 20171117

OFFICE DEPOT #869 (Continued) **S121782438**

Manifest ID:	010833647FLE
Trans EPA ID:	MNS000110924
Trans Name:	STERICYCLE SPECIALTY WASTE SOLUTIONS INC
Trans 2 EPA ID:	NED986382133
Trans 2 Name:	SMITH SYSTEMS TRANSPORTATION
TSDF EPA ID:	CAD008364432
Trans Name:	RHO CHEM LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	214 - Unspecified solvent mixture
RCRA Code:	D035
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0015
Waste Quantity:	3
Quantity Unit:	P
Additional Code 1:	D001
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20171026
Creation Date:	8/27/2018 18:30:14
Receipt Date:	20171117
Manifest ID:	010833647FLE
Trans EPA ID:	MNS000110924
Trans Name:	STERICYCLE SPECIALTY WASTE SOLUTIONS INC
Trans 2 EPA ID:	NED986382133
Trans 2 Name:	SMITH SYSTEMS TRANSPORTATION
TSDF EPA ID:	CAD008364432
Trans Name:	RHO CHEM LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0205
Waste Quantity:	41
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170501
Creation Date:	5/12/2018 18:32:44
Receipt Date:	20170504
Manifest ID:	009158744FLE
Trans EPA ID:	MNS000110924
Trans Name:	STERICYCLE SPECIALTY WASTE SOLUTIONS INC
Trans 2 EPA ID:	NED986382133
Trans 2 Name:	SMITH SYSTEM
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMN LLC

OFFICE DEPOT #869 (Continued) **S121782438**

TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	214 - Unspecified solvent mixture
RCRA Code:	D035
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0005
Waste Quantity:	1
Quantity Unit:	P
Additional Code 1:	D001
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170501
Creation Date:	5/12/2018 18:32:44
Receipt Date:	20170504
Manifest ID:	009158744FLE
Trans EPA ID:	MNS000110924
Trans Name:	STERICYCLE SPECIALTY WASTE SOLUTIONS INC
Trans 2 EPA ID:	NED986382133
Trans 2 Name:	SMITH SYSTEM
TSDF EPA ID:	NVD980895338
Trans Name:	21ST CENTURY EMN LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D035
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.002
Waste Quantity:	4
Quantity Unit:	P
Additional Code 1:	D001
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HWTS:

Name:	OFFICE DEPOT 869
Address:	910 EL MONTE AVE
Address 2:	Not reported
City,State,Zip:	MOUNTAIN VIEW, CA 94040
EPA ID:	CAL000421200
Inactive Date:	Not reported
Create Date:	10/14/2016
Last Act Date:	07/29/2020
Mailing Name:	Not reported
Mailing Address:	6600 N MILITARY TRAIL C492
Mailing Address 2:	Not reported
Mailing City,State,Zip:	BOCA RATON, FL 334960000
Owner Name:	OFFICE DEPOT INC
Owner Address:	6600 N MILITARY TRAIL
Owner Address 2:	Not reported
Owner City,State,Zip:	BOCA RATON, FL 33496

OFFICE DEPOT #869 (Continued) **S121782438**

Contact Name: WENDI LANE
Contact Address: 6600 N MILITARY TRAIL C492
Contact Address 2: Not reported
City,State,Zip: BOCA RATON, FL 33496

NAICS:
EPA ID: CAL000421200
Create Date: 2016-10-14 15:38:27.457
NAICS Code: 45321
NAICS Description: Office Supplies and Stationery Stores
Issued EPA ID Date: 2016-10-14 15:38:27.40700
Inactive Date: Not reported
Facility Name: OFFICE DEPOT 869
Facility Address: 910 EL MONTE AVE
Facility Address 2: Not reported
Facility City: MOUNTAIN VIEW
Facility County: Not reported
Facility State: CA
Facility Zip: 94040

G53 **DEAN'S FOREIGN CAR** **CUPA Listings** **S121472034**
NNW **1901 W EL CAMINO REAL** **N/A**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.199 mi.
1052 ft. **Site 3 of 3 in cluster G**

Relative:
Lower

Actual:
93 ft.

CUPA SANTA CLARA:
Name: DEAN'S FOREIGN CAR
Address: 1901 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: SANTA CLARA
PE#: 2205
Program Description: GENERATES 100 KG YR TO <5 TONS/YR
Latitude: 37.392826
Longitude: -122.096476
Record ID: PR0366309
Facility ID: FA0251950

J54 **PRASAD PARIMI** **RCRA NonGen / NLR** **1025858764**
ESE **1332 PARK DR** **CAC003039294**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.213 mi.
1122 ft. **Site 1 of 4 in cluster J**

Relative:
Higher

Actual:
105 ft.

RCRA NonGen / NLR:
Date Form Received by Agency: 2019-10-17 00:00:00.0
Handler Name: PRASAD PARIMI
Handler Address: 1332 PARK DR
Handler City,State,Zip: MOUNTAIN VIEW, CA 94040
EPA ID: CAC003039294
Contact Name: PRASAD PARIMI
Contact Address: 1332 PARK DR
Contact City,State,Zip: MOUNTAIN VIEW, CA 94040
Contact Telephone: 650-279-0919
Contact Fax: Not reported
Contact Email: SHACARRAHENDERSON@ALLIANCE-ENVIRO.COM

PRASAD PARIMI (Continued) **1025858764**

Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1332 PARK DR
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner Name:	PRASAD PARIMI
Owner Type:	Other
Operator Name:	PRASAD PARIMI
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported

PRASAD PARIMI (Continued) **1025858764**

Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-10-21 14:11:40.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	PRASAD PARIMI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1332 PARK DR
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-279-0919
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	PRASAD PARIMI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1332 PARK DR
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-279-0919
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2019-10-17 00:00:00.0
Handler Name: PRASAD PARIMI	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

PRASAD PARIMI (Continued) **1025858764**

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

---

55 East 1/8-1/4 0.221 mi. 1167 ft.

BETTY EVANS
771 PALO ALTO AVE
MOUNTAIN VIEW, CA 94041

RCRA NonGen / NLR **1026046037** **CAC003052494**

Relative: Lower

Actual: 100 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-01-23 00:00:00.0
Handler Name:	BETTY EVANS	
Handler Address:		771 PALO ALTO AVE
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94041
EPA ID:		CAC003052494
Contact Name:		BETTY EVANS
Contact Address:		771 PALO ALTO AVE
Contact City,State,Zip:		MOUNTAIN VIEW, CA 94041
Contact Telephone:		650-390-3480
Contact Fax:		Not reported
Contact Email:		JOHN@DGRESIDENTIALBUILDERS.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		771 PALO ALTO AVE
Mailing City,State,Zip:		MOUNTAIN VIEW, CA 94041
Owner Name:		BETTY EVANS
Owner Type:		Other
Operator Name:		BETTY EVANS
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No

BETTY EVANS (Continued) **1026046037**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-02-10 17:53:02.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	BETTY EVANS
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	771 PALO ALTO AVE
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94041
Owner/Operator Telephone:	650-390-3480
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

BETTY EVANS (Continued) **1026046037**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: BETTY EVANS
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 771 PALO ALTO AVE
Owner/Operator City,State,Zip: MOUNTAIN VIEW, CA 94041
Owner/Operator Telephone: 650-390-3480
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2020-01-23 00:00:00.0
Handler Name: BETTY EVANS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I56 **WALGREENS #13948** **CERS HAZ WASTE** **S109435458**
NNW **1905 W EL CAMINO REAL** **CUPA Listings** **N/A**
1/8-1/4 **MOUNTAIN VIEW, CA 94040** **CERS**
0.227 mi.
1197 ft. **Site 3 of 4 in cluster I**

Relative:
Lower

Actual:
93 ft.

CERS HAZ WASTE:
Name: WALGREENS #13948
Address: 1905 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 84160
CERS ID: 10348318
CERS Description: Hazardous Waste Generator

CUPA SANTA CLARA:
Name: WALGREENS #13948

WALGREENS #13948 (Continued) **S109435458**

Address: 1905 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: SANTA CLARA
PE#: 2202
Program Description: GENERATES < 100 KG/YR
Latitude: 37.392782
Longitude: -122.096269
Record ID: PR0402804
Facility ID: FA0270583

CERS:
Name: WALGREENS #13948
Address: 1905 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 84160
CERS ID: 10348318
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 84160
Site Name: Walgreens #13948
Violation Date: 08-03-2016
Citation: HSC 6.95 25508.1(a)-(f) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(f)
Violation Description: Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name. A substantial change in the handler's operations that requires modification to any portion of the business plan.
Violation Notes: Returned to compliance on 09/19/2016. Update inventory to include flammable gas and update annual waste amounts for all hazardous waste.
Violation Division: Mountain View Fire Department
Violation Program: HMRRP
Violation Source: CERS

Site ID: 84160
Site Name: Walgreens #13948
Violation Date: 09-10-2019
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description: Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.
Violation Notes: Ensure that all employees that handle hazardous materials/hazardous waste have been provided annual hazardous communications training.
Violation Division: Mountain View Fire Department
Violation Program: HMRRP
Violation Source: CERS

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-03-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported

WALGREENS #13948 (Continued) **S109435458**

Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-05-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-10-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Other/Unknown
Eval Date: 09-19-2016
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: All Violations Corrected.
Eval Division: Mountain View Fire Department
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-09-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: On-site to perform a routine Hazardous Waste Generator inspection. A walk-through of Walgreens' back storage area and pharmacy was conducted with store manager, Devangi Patel. Noted the following: Back Storage Area: > Non-saleable returns and broken/ damaged items are placed in a central bin. Shift leads are trained in hazardous waste management and segregate the items nightly into the appropriate hazardous waste tote bins via a scan system and posted informational guide. > Bins are categorized as follows: - Toxics (4) - Universal Waste - Reactive Waste - Ignitable Waste - Corrosive Basic - Corrosive Acidic Pharmacy: > 1 tote bin for non-P-listed wastes > 1 tote bin for P-listed wastes NOTE: OBSERVED 2 SMALL BOTTLES OF WARFARIN IN THE NON-P-LISTED BIN. THESE ITEMS WERE REMOVED AND PLACED INTO THE P-LISTED BIN. ENSURE THAT ALL WARFARIN PRODUCTS ARE PLACED IN THE P-LISTED BIN AND TRAIN RE/TRAIN STAFF AS NECESSARY. State ID: CAL000375888 is [Truncated]
Eval Division: Santa Clara County Environmental Health
Eval Program: HW
Eval Source: CERS

Coordinates:
Site ID: 84160
Facility Name: Walgreens #13948

WALGREENS #13948 (Continued) **S109435458**

Env Int Type Code: HWG
Program ID: 10348318
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.
Latitude: 37.392570
Longitude: -122.096620

Affiliation:
Affiliation Type Desc: Identification Signer
Entity Name: Crystalyn Dogui-is, on behalf of Walgreen Co.
Entity Title: Regulatory Compliance Coordinator II, Verisk 3E
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Parent Corporation
Entity Name: Walgreens
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: CUPA District
Entity Name: Santa Clara County Environmental Health
Entity Title: Not reported
Affiliation Address: 1555 Berger Drive, Suite 300
Affiliation City: San Jose
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95112-2716
Affiliation Phone: (408) 918-3400

Affiliation Type Desc: Property Owner
Entity Name: LWC PARTNERSHIP
Entity Title: Not reported
Affiliation Address: 660 WOODSIDE DR
Affiliation City: Woodside
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94062
Affiliation Phone: (650) 364-3142

Affiliation Type Desc: Document Preparer
Entity Name: Crystalyn Dogui-is, On behalf of Walgreen Co.
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

WALGREENS #13948 (Continued) **S109435458**

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	Verisk 3E, Regulatory Dept./Walgreen Co., 3207 Grey Hawk Ct, Ste 200
Affiliation City:	Carlsbad
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92010
Affiliation Phone:	Not reported
Affiliation Type Desc:	Environmental Contact
Entity Name:	Verisk 3E, Regulatory Department/ Walgreen Co.
Entity Title:	Not reported
Affiliation Address:	3207 Grey Hawk Ct, Ste 200
Affiliation City:	Carlsbad
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92010
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	Walgreen Co.
Entity Title:	Not reported
Affiliation Address:	200 Wilmot Rd
Affiliation City:	Deerfield
Affiliation State:	IL
Affiliation Country:	United States
Affiliation Zip:	60015
Affiliation Phone:	(847) 914-2264
Affiliation Type Desc:	Operator
Entity Name:	Walgreen Co.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(847) 914-2264

I57 **WALGREENS #13948** **RCRA-SQG** **1016954670**
NNW **1905 W EL CAMINO REAL** **CAL000375888**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.227 mi.
1197 ft. **Site 4 of 4 in cluster I**

Relative: **Lower**
Actual: **93 ft.**

RCRA-SQG:

Date Form Received by Agency:		2020-07-30 00:00:00.0
Handler Name:	WALGREENS #13948	
Handler Address:		1905 W EL CAMINO REAL
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94040
EPA ID:		CAL000375888
Contact Name:		AMBER DURKIN
Contact Address:		WILMOT RD, 5TH FL, MS#1450
Contact City,State,Zip:		DEERFIELD, IL 60015
Contact Telephone:		847-964-8816
Contact Fax:		760-918-4025

WALGREENS #13948 (Continued) **1016954670**

Contact Email:	AMBER.DURKIN@WALGREENS.COM
Contact Title:	APS SAFETY MANAGER, NON-RETAIL / SUPPLY CHAIN
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2019
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	GREYHAWK CT. SUITE 200
Mailing City,State,Zip:	CARLSBAD, CA 92010
Owner Name:	LWC PARTNERSHIP
Owner Type:	Private
Operator Name:	WALGREEN CO.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

WALGREENS #13948 (Continued) **1016954670**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-10-07 17:40:14.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D005
Waste Description:	BARIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D009
Waste Description:	MERCURY
Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D016
Waste Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Waste Code:	D022
Waste Description:	CHLOROFORM
Waste Code:	D024
Waste Description:	M-CRESOL
Waste Code:	P001
Waste Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

WALGREENS #13948 (Continued) **1016954670**

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: U034
Waste Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U165
Waste Description: NAPHTHALENE

Waste Code: U188
Waste Description: PHENOL

Waste Code: U205
Waste Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: WALGREEN CO
Legal Status: Private
Date Became Current: 2012-05-04 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WALGREEN CO.
Legal Status: Private
Date Became Current: 2012-05-04 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 200 WILMONT RD.
Owner/Operator City,State,Zip: DEERFIELD, IL 60015
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: LWC PARTNERSHIP
Legal Status: Private
Date Became Current: 2012-04-02 00:00:00.
Date Ended Current: Not reported

WALGREENS #13948 (Continued) **1016954670**

Owner/Operator Address:	660 WOODSIDE DR
Owner/Operator City,State,Zip:	WOODSIDE, CA 94062
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	WALGREEN CO
Legal Status:	Private
Date Became Current:	2012-05-04 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	200 WILMOT RD
Owner/Operator City,State,Zip:	DEERFIELD, IL 60015
Owner/Operator Telephone:	847-914-2264
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	WALGREEN CO.
Legal Status:	Private
Date Became Current:	2012-05-04 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	LWC PARTNERSHIP
Legal Status:	Private
Date Became Current:	2012-04-02 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	660 WOODSIDE DR
Owner/Operator City,State,Zip:	WOODSIDE, CA 94062
Owner/Operator Telephone:	650-364-3142
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2014-06-09 00:00:00.0
Handler Name: WALGREENS #13948	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

WALGREENS #13948 (Continued) **1016954670**

Receive Date: 2016-04-12 00:00:00.0
Handler Name: WALGREENS #13948
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2020-07-30 00:00:00.0
Handler Name: WALGREENS #13948
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 44611
NAICS Description: PHARMACIES AND DRUG STORES

NAICS Code: 446110
NAICS Description: PHARMACIES AND DRUG STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

J58 **1313 EL CAMINO REAL** **RCRA-SQG** **1026171526**
ESE **1313 EL CAMINO REAL** **CAR000307348**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.227 mi.
1199 ft. **Site 2 of 4 in cluster J**

Relative: **Lower**
Actual: **104 ft.**

RCRA-SQG:
Date Form Received by Agency: 2020-04-23 00:00:00.0
Handler Name: 1313 EL CAMINO REAL
Handler Address: 1313 EL CAMINO REAL
Handler City,State,Zip: MOUNTAIN VIEW, CA 94040
EPA ID: CAR000307348
Contact Name: MIKE MOINEE
Contact Address: PARK DRIVE
Contact City,State,Zip: MOUNTAIN VIEW, CA 94040
Contact Telephone: 949-233-1014

1313 EL CAMINO REAL (Continued) **1026171526**

Contact Fax:	Not reported
Contact Email:	NMOINEE@GMAIL.COM
Contact Title:	PROJECT MANAGER
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	PARK DRIVE
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner Name:	@ HOME LLC
Owner Type:	Private
Operator Name:	@ HOME LLC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

1313 EL CAMINO REAL (Continued) **1026171526**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-24 14:20:53.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	@ HOME LLC
Legal Status:	Private
Date Became Current:	2020-04-23 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	1368 PARK DRIVE
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-796-8504
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	PAFEHER@GMAIL.COM

Owner/Operator Indicator:	Owner
Owner/Operator Name:	@ HOME LLC
Legal Status:	Private
Date Became Current:	2020-04-23 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	1368 PARK DRIVE
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-796-8504
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	PAFEHER@GMAIL.COM

1313 EL CAMINO REAL (Continued) **1026171526**

Historic Generators:
- Receive Date: 2020-04-23 00:00:00.0
- Handler Name: 1313 EL CAMINO REAL
- Federal Waste Generator Description: Small Quantity Generator
- State District Owner: Not reported
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: No
- Recognized Trader Exporter: No
- Spent Lead Acid Battery Importer: No
- Spent Lead Acid Battery Exporter: No
- Current Record: Yes
- Non Storage Recycler Activity: No
- Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
- NAICS Code: 562910
- NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

J59 **@ HOME LLC** **RCRA NonGen / NLR** **1026170621**
ESE **1313 EL CAMINO REAL** **CAL000454187**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.227 mi.
1199 ft. **Site 3 of 4 in cluster J**

Relative: **Lower**
Actual: **104 ft.**

RCRA NonGen / NLR:
- Date Form Received by Agency: 2020-04-28 00:00:00.0
- Handler Name: @ HOME LLC
- Handler Address: 1313 EL CAMINO REAL
- Handler City,State,Zip: MOUNTAIN VIEW, CA 94040
- EPA ID: CAL000454187
- Contact Name: MIKE MOINEE
- Contact Address: 1368 PARK DR
- Contact City,State,Zip: MOUNTAIN VIEW, CA 94040
- Contact Telephone: 949-233-1014
- Contact Fax: Not reported
- Contact Email: NMOINEE@GMAIL.COM
- Contact Title: Not reported
- EPA Region: 09
- Land Type: Not reported
- Federal Waste Generator Description: Not a generator, verified
- Non-Notifier: Not reported
- Biennial Report Cycle: Not reported
- Accessibility: Not reported
- Active Site Indicator: Not reported
- State District Owner: Not reported
- State District: Not reported
- Mailing Address: 1368 PARK DR
- Mailing City,State,Zip: MOUNTAIN VIEW, CA 94040
- Owner Name: Not reported

@ HOME LLC (Continued) **1026170621**

Owner Type:	Not reported
Operator Name:	@ HOME LLC
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-28 14:14:41.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No

@ HOME LLC (Continued) **1026170621**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: MIKE MOINEE
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1368 PARK DR
Owner/Operator City,State,Zip: MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone: 949-233-1014
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: @ HOME LLC
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1368 PARK DR
Owner/Operator City,State,Zip: MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone: 949-233-1014
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: @ HOME LLC
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1368 PARK DR
Owner/Operator City,State,Zip: MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone: 949-233-1014
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2020-04-28 00:00:00.0
Handler Name: @ HOME LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 2020-04-15 00:00:00.0
Handler Name: @ HOME LLC

@ HOME LLC (Continued) **1026170621**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	562910
NAICS Description:	REMEDIATION SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

J60 **@HOME LLC** **CPS-SLIC S119777517**
ESE **1313-1347 W EL CAMINO REAL** **CERS N/A**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.227 mi.
1199 ft. **Site 4 of 4 in cluster J**

Relative: **Lower**

Actual: **104 ft.**

CPS-SLIC:

Name:	@HOME LLC
Address:	1313-1347 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	01/01/2020
Global Id:	T10000010030
Lead Agency:	SANTA CLARA COUNTY LOP
Lead Agency Case Number:	2017-04s
Latitude:	37.38829
Longitude:	-122.08981
Case Type:	Cleanup Program Site
Case Worker:	AC
Local Agency:	SANTA CLARA COUNTY LOP
RB Case Number:	Not reported
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Other Groundwater (uses other than drinking water), Soil, Soil Vapor
Potential Contaminants of Concern:	Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Vinyl chloride
Site History:	Property had a dry cleaner business for many years and ceased operations in 2007. Soil and soil vapor sampling reported high levels of PCE well above environmental screening criteria and present a risk to human health. The maximum concentration of PCE reported was 4,650,000 micrograms per cubic meter (a%g/m3) at 15 feet below grade. Additional investigation is needed to define the extent of contamination prior to developing a remedy. Site is currently planned for redevelopment.

@HOME LLC (Continued) **S119777517**

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	@HOME LLC
Address:	1313-1347 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Site ID:	416454
CERS ID:	T10000010030
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	AARON COSTA - SANTA CLARA COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	1555 Berger Drive, Suite 300
Affiliation City:	SAN JOSE
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	4089181954

---

61 **DAN ASKARI** **RCRA NonGen / NLR** **1026488104**
WSW **633 SPARGUR DR.** **CAC003094309**
1/8-1/4 **LOS ALTOS, CA 94022**
0.242 mi.
1279 ft.

Relative: **Higher**
Actual: **118 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:		2020-11-23 00:00:00.0
Handler Name:	DAN ASKARI	
Handler Address:		633 SPARGUR DR.
Handler City,State,Zip:		LOS ALTOS, CA 94022
EPA ID:		CAC003094309
Contact Name:		DAN ASKARI
Contact Address:		633 SPARGUR DR.
Contact City,State,Zip:		LOS ALTOS, CA 94022
Contact Telephone:		408-209-3111
Contact Fax:		Not reported
Contact Email:		DANASKARI@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		633 SPARGUR DR.
Mailing City,State,Zip:		LOS ALTOS, CA 94022
Owner Name:		DAN ASKARI
Owner Type:		Other
Operator Name:		DAN ASKARI
Operator Type:		Other
Short-Term Generator Activity:		No

DAN ASKARI (Continued) **1026488104**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-11-30 19:32:43.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

DAN ASKARI (Continued) **1026488104**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DAN ASKARI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	633 SPARGUR DR.
Owner/Operator City,State,Zip:	LOS ALTOS, CA 94022
Owner/Operator Telephone:	408-209-3111
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	DAN ASKARI
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	633 SPARGUR DR.
Owner/Operator City,State,Zip:	LOS ALTOS, CA 94022
Owner/Operator Telephone:	408-209-3111
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2020-11-23 00:00:00.0
Handler Name: DAN ASKARI	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

K62 **CAMINO DENTAL GROUP** **CUPA Listings** **S112345516**
East **1328 W EL CAMINO REAL 1** **N/A**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.244 mi.
1290 ft. **Site 1 of 6 in cluster K**

Relative: CUPA SANTA CLARA:
Lower

Name:	CAMINO DENTAL GROUP
Address:	1328 W EL CAMINO REAL 1
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2240
Program Description:	GENERATES < 10 GAL/YR
Latitude:	37.388734
Longitude:	-122.08944
Record ID:	PR0330465
Facility ID:	FA0230445

Actual:
103 ft.

K63 **CAMINO DENTAL GROUP** **RCRA NonGen / NLR** **1025866046**
East **1328 W EL CAMINO REAL #1** **CAL000152537**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.244 mi.
1290 ft. **Site 2 of 6 in cluster K**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:		1996-04-29 00:00:00.0
Handler Name:	CAMINO DENTAL GROUP	
Handler Address:		1328 W EL CAMINO REAL #1
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94040-0000
EPA ID:		CAL000152537
Contact Name:		SHEILA TAN
Contact Address:		936 RINCON ST
Contact City,State,Zip:		MOUNTAIN VIEW, CA 94040
Contact Telephone:		650-962-8773
Contact Fax:		650-962-8464
Contact Email:		CAMINODENTAL@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		1328 W EL CAMINO REAL STE #1
Mailing City,State,Zip:		MOUNTAIN VIEW, CA 94040-0000
Owner Name:		SHEILA TAN, DDS, INC.
Owner Type:		Other
Operator Name:		SHEILA TAN
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		Yes
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

Actual:
103 ft.

CAMINO DENTAL GROUP (Continued) **1025866046**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-06-27 15:48:46.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SHEILA TAN, DDS, INC.
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1328 W EL CAMINO REAL STE #1
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040-0000

CAMINO DENTAL GROUP (Continued) **1025866046**

Owner/Operator Telephone: 650-962-8773
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SHEILA TAN
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 936 RINCON ST
Owner/Operator City,State,Zip: MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone: 650-962-8773
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 1996-04-29 00:00:00.0
Handler Name: CAMINO DENTAL GROUP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 62121
NAICS Description: OFFICES OF DENTISTS

NAICS Code: 621210
NAICS Description: OFFICES OF DENTISTS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

K64 **STROM PROPERTIES** **RCRA NonGen / NLR** **1024776924**
East **1328 W. EL CAMINO REAL, SUITE 2** **CAC002996861**
1/8-1/4 **MOUNTAIN VIEW, CA 94040**
0.244 mi.
1290 ft. **Site 3 of 6 in cluster K**

Relative: RCRA NonGen / NLR:
Lower Date Form Received by Agency: 2019-01-16 00:00:00.0
Actual: Handler Name: STROM PROPERTIES
103 ft. Handler Address: 1328 W. EL CAMINO REAL, SUITE 2
Handler City,State,Zip: MOUNTAIN VIEW, CA 94040

STROM PROPERTIES (Continued) **1024776924**

EPA ID:	CAC002996861
Contact Name:	ROGER STROM
Contact Address:	1328 W. EL CAMINO REAL, SUITE 2
Contact City,State,Zip:	MOUNTAIN VIEW, CA 94040
Contact Telephone:	650-324-8255
Contact Fax:	650-324-2386
Contact Email:	ROGERLSTROM@GMAIL.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	1328 W. EL CAMINO REAL, SUITE 2
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner Name:	STROM PROPERTIES
Owner Type:	Other
Operator Name:	ROGER STROM
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

STROM PROPERTIES (Continued) **1024776924**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2019-02-22 19:40:07.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROGER STROM
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1328 W. EL CAMINO REAL, SUITE 2
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-324-8255
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	STROM PROPERTIES
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1328 W. EL CAMINO REAL, SUITE 2
Owner/Operator City,State,Zip:	MOUNTAIN VIEW, CA 94040
Owner/Operator Telephone:	650-324-8255
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2019-01-16 00:00:00.0
Handler Name: STROM PROPERTIES	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

STROM PROPERTIES (Continued) **1024776924**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

K65 **SHELL** **HIST CORTESE** **S103627424**
East **1288 EL CAMINO REAL** **N/A**
1/4-1/2 **MOUNTAIN VIEW, CA 94041**
0.288 mi.
1523 ft. **Site 4 of 6 in cluster K**

Relative:
Lower

Actual:
102 ft.

HIST CORTESE:
edr_fname: SHELL
edr_fadd1: 1288 EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94041
Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1273

K66 **SHELL OIL CO** **RCRA-SQG** **1000288028**
East **1288 EL CAMINO** **LUST** **CAD981401789**
1/4-1/2 **MOUNTAIN VIEW, CA 94041** **HIST LUST**
0.288 mi. **SWEEPS UST**
1523 ft. **Site 5 of 6 in cluster K** **HIST UST**
CA FID UST

Relative:
Lower

Actual:
102 ft.

FINDS
ECHO
Cortese
HAZNET
CERS
HWTS

RCRA-SQG:
Date Form Received by Agency: 1998-04-08 00:00:00.0
Handler Name: SHELL OIL CO
Handler Address: 1288 EL CAMINO
Handler City,State,Zip: MOUNTAIN VIEW, CA 94041
EPA ID: CAD981401789
Contact Name: SONDRA BIENVENU
Contact Address: P O BOX 4453
Contact City,State,Zip: HOUSTON, TX 77210-4453
Contact Telephone: 713-241-2258

SHELL OIL CO (Continued) **1000288028**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	P O BOX 4453
Mailing City,State,Zip:	HOUSTON, TX 77210-4453
Owner Name:	EQUILON ENTERPRISES LLC
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

SHELL OIL CO (Continued) **1000288028**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-10-07 16:37:52.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	EQUILON ENTERPRISES LLC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	P O BOX 4453
Owner/Operator City,State,Zip:	HOUSTON, TX 77210-4453
Owner/Operator Telephone:	713-241-2258
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1996-09-01 00:00:00.0
Handler Name: SHELL OIL CO	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No

SHELL OIL CO (Continued) **1000288028**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1998-04-08 00:00:00.0
Handler Name: SHELL OIL CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1992-02-24 00:00:00.0
Handler Name: SHELL STATION 204 5208 2603
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 4471
NAICS Description: GASOLINE STATIONS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Case Closed
Case Number: 06S2W28C01f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST

SHELL OIL CO (Continued) **1000288028**

Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: 6/8/1989
Pollution Characterization Began: 2/20/1992
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:
Name: SHELL
Address: 1288 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA
Region: SANTA CLARA
SCVWD ID: 06S2W28C01F
Date Closed: 06/25/1996
EDR Link ID: 06S2W28C01F

HIST LUST SANTA CLARA:
Name: Shell
Address: 1288 W El Camino Real
City: Mountain View
Region: SANTA CLARA
Region Code: 2
SCVWD ID: 06S2W28C01
Oversite Agency: SCVWD
Date Listed: 1988-01-01 00:00:00
Closed Date: 1996-06-25 00:00:00

SWEEPS UST:
Name: SHELL
Address: 1288 W EL CAMINO REAL
City: MOUNTAIN VIEW
Status: Active
Comp Number: 28565
Number: 9
Board Of Equalization: 44-026003
Referral Date: 09-26-91
Action Date: 09-26-91
Created Date: 10-13-88
Owner Tank Id: 1
SWRCB Tank Id: 43-005-028565-000001
Tank Status: A
Capacity: 12000
Active Date: 09-26-91
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 4

Name: SHELL
Address: 1288 W EL CAMINO REAL
City: MOUNTAIN VIEW
Status: Active
Comp Number: 28565
Number: 9
Board Of Equalization: 44-026003
Referral Date: 09-26-91

SHELL OIL CO (Continued) **1000288028**

Action Date:	09-26-91
Created Date:	10-13-88
Owner Tank Id:	2
SWRCB Tank Id:	43-005-028565-000002
Tank Status:	A
Capacity:	550
Active Date:	01-06-94
Tank Use:	OIL
STG:	W
Content:	WASTE OIL
Number Of Tanks:	Not reported

Name:	SHELL
Address:	1288 W EL CAMINO REAL
City:	MOUNTAIN VIEW
Status:	Active
Comp Number:	28565
Number:	9
Board Of Equalization:	44-026003
Referral Date:	09-26-91
Action Date:	09-26-91
Created Date:	10-13-88
Owner Tank Id:	3
SWRCB Tank Id:	43-005-028565-000003
Tank Status:	A
Capacity:	12000
Active Date:	01-06-94
Tank Use:	M.V. FUEL
STG:	P
Content:	SUPER UNLEADED
Number Of Tanks:	Not reported

Name:	SHELL
Address:	1288 W EL CAMINO REAL
City:	MOUNTAIN VIEW
Status:	Active
Comp Number:	28565
Number:	9
Board Of Equalization:	44-026003
Referral Date:	09-26-91
Action Date:	09-26-91
Created Date:	10-13-88
Owner Tank Id:	4
SWRCB Tank Id:	43-005-028565-000004
Tank Status:	A
Capacity:	12000
Active Date:	01-06-94
Tank Use:	M.V. FUEL
STG:	P
Content:	SUPER REGULA
Number Of Tanks:	Not reported

HIST UST:

Name:	FELIPE C SANGCO
Address:	1288 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94041
File Number:	000208E8

SHELL OIL CO (Continued) **1000288028**

URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/000208E8.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

CA FID UST:

Facility ID:	43001291
Regulated By:	UTNKA
Regulated ID:	00028565
Cortese Code:	Not reported
SIC Code:	Not reported
Facility Phone:	4159640213
Mail To:	Not reported
Mailing Address:	1288 W EL CAMINO REAL
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MOUNTAIN VIEW 94041
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Status:	Active

FINDS:

Registry ID: 110002695076

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

SHELL OIL CO (Continued) **1000288028**

ECHO:

Envid:	1000288028
Registry ID:	110002695076
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002695076
Name:	SHELL OIL CO
Address:	1288 EL CAMINO
City,State,Zip:	MOUNTAIN VIEW, CA 94041

CORTESE:

Name:	SHELL
Address:	1288 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94041
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0608501251
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HAZNET:

Name:	AU ENERGY-MOUNTAIN VIEW SHELL
Address:	1288 W EL CAMINO REAL
Address 2:	Not reported
City,State,Zip:	MOUNTAIN VIEW, CA 940402402
Contact:	JORGE IZEPPI
Telephone:	5102703457
Mailing Name:	Not reported
Mailing Address:	41805 ALBRAE ST
Year:	2017
Gepaid:	CAL000350848
TSD EPA ID:	CAD028409019
CA Waste Code:	352 - Other organic solids
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.005
Year:	2014
Gepaid:	CAL000350848
TSD EPA ID:	UTD981552177
CA Waste Code:	352 - Other organic solids

SHELL OIL CO (Continued) **1000288028**

Disposal Method:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.0075
Year:	2013
Gepaid:	CAL000350848
TSD EPA ID:	CAD980887418
CA Waste Code:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0834
Year:	2013
Gepaid:	CAL000350848
TSD EPA ID:	CAD980887418
CA Waste Code:	352 - Other organic solids
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.035

Additional Info:

Year:	2013
Gen EPA ID:	CAL000350848
Shipment Date:	20131227
Creation Date:	3/21/2014 22:15:11
Receipt Date:	20131230
Manifest ID:	012525078JJK
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	EVERGREEN OIL INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D018
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0225
Waste Quantity:	45
Quantity Unit:	P
Additional Code 1:	D001
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20131227
Creation Date:	3/21/2014 22:15:11
Receipt Date:	20131230
Manifest ID:	012525078JJK
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported

SHELL OIL CO (Continued) **1000288028**

TSDF EPA ID:	CAD980887418
Trans Name:	EVERGREEN OIL INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D018
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0125
Waste Quantity:	25
Quantity Unit:	P
Additional Code 1:	D001
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130305
Creation Date:	4/22/2013 22:15:05
Receipt Date:	20130306
Manifest ID:	010829862JJK
Trans EPA ID:	CAD982413262
Trans Name:	EVERGREEN ENVIRONMENTAL SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD980887418
Trans Name:	EVERGREEN OIL INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	D018
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0834
Waste Quantity:	20
Quantity Unit:	G
Additional Code 1:	D001
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2017
Gen EPA ID:	CAL000350848
Shipment Date:	20170705
Creation Date:	6/27/2018 18:30:19
Receipt Date:	20170707
Manifest ID:	012296384JJK
Trans EPA ID:	CAR000163097
Trans Name:	K-VAC ENVIRONMENTAL SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD028409019
Trans Name:	CROSBY & OVERTON
TSDF Alt EPA ID:	Not reported

SHELL OIL CO (Continued) **1000288028**

TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D018
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.005
Waste Quantity:	10
Quantity Unit:	P
Additional Code 1:	D001
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2014
Gen EPA ID:	CAL000350848
Shipment Date:	20140404
Creation Date:	10/2/2014 22:15:00
Receipt Date:	20140429
Manifest ID:	003518584SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS
TSDF EPA ID:	UTD981552177
Trans Name:	CLEAN HARBORS ARAGONITE LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	D018
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.0075
Waste Quantity:	15
Quantity Unit:	P
Additional Code 1:	D001
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

CERS:

Name:	SHELL
Address:	1288 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94041
Site ID:	221015
CERS ID:	T0608501251
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	UST CASE WORKER - SANTA CLARA COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	1555 Berger Drive, Suite 300
Affiliation City:	SAN JOSE
Affiliation State:	CA

SHELL OIL CO (Continued) **1000288028**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker
Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)
Entity Title: Not reported
Affiliation Address: 1515 CLAY ST SUITE 1400
Affiliation City: OAKLAND
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

HWTS:
Name: AU ENERGY-MOUNTAIN VIEW SHELL
Address: 1288 W EL CAMINO REAL
Address 2: Not reported
City,State,Zip: MOUNTAIN VIEW, CA 940402402
EPA ID: CAL000350848
Inactive Date: Not reported
Create Date: 03/15/2010
Last Act Date: 07/07/2020
Mailing Name: Not reported
Mailing Address: 41805 ALBRAE ST
Mailing Address 2: Not reported
Mailing City,State,Zip: FREMONT, CA 945383120
Owner Name: AU ENERGY LLC
Owner Address: 41805 ALBRAE ST
Owner Address 2: Not reported
Owner City,State,Zip: FREMONT, CA 945383120
Contact Name: JORGE IZEPPI
Contact Address: 41805 ALBRAE ST
Contact Address 2: Not reported
City,State,Zip: FREMONT, CA 94538

NAICS:
EPA ID: CAL000350848
Create Date: 2010-03-15 13:05:21.007
NAICS Code: 44719
NAICS Description: Other Gasoline Stations
Issued EPA ID Date: 2010-03-15 13:05:20.69300
Inactive Date: Not reported
Facility Name: AU ENERGY-MOUNTAIN VIEW SHELL
Facility Address: 1288 W EL CAMINO REAL
Facility Address 2: Not reported
Facility City: MOUNTAIN VIEW
Facility County: Not reported
Facility State: CA
Facility Zip: 940402402

K67 **FELIPE C. SONGCO** **LUST** **U001594346**
East **1288 W EL CAMINO REAL** **HIST UST** **N/A**
1/4-1/2 **MOUNTAIN VIEW, CA 94041** **CUPA Listings**
0.288 mi.
1523 ft. **Site 6 of 6 in cluster K**

Relative:
Lower

Actual:
102 ft.

LUST:

Name:	SHELL
Address:	1288 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94041
Lead Agency:	SANTA CLARA COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501251
Global Id:	T0608501251
Latitude:	37.3884962176043
Longitude:	-122.088612072797
Status:	Completed - Case Closed
Status Date:	06/25/1996
Case Worker:	UST
RB Case Number:	Not reported
Local Agency:	SANTA CLARA COUNTY LOP
File Location:	All Files are on GeoTracker or in the Local Agency Database
Local Case Number:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0608501251
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608501251
Contact Type:	Local Agency Caseworker
Contact Name:	UST CASE WORKER
Organization Name:	SANTA CLARA COUNTY LOP
Address:	1555 Berger Drive, Suite 300
City:	SAN JOSE
Email:	Not reported
Phone Number:	4089183400

LUST:

Global Id:	T0608501251
Action Type:	Other
Date:	04/03/1987
Action:	Leak Reported

Global Id:	T0608501251
Action Type:	ENFORCEMENT
Date:	06/25/1996
Action:	Closure/No Further Action Letter

Global Id:	T0608501251
Action Type:	RESPONSE

FELIPE C. SONGCO (Continued) **U001594346**

Date: 06/25/1996
Action: Other Report / Document

Global Id: T0608501251
Action Type: ENFORCEMENT
Date: 01/29/1991
Action: Notice of Responsibility - #40065

Global Id: T0608501251
Action Type: REMEDIATION
Date: 08/05/1987
Action: Excavation

LUST:
Global Id: T0608501251
Status: Open - Case Begin Date
Status Date: 04/03/1987

Global Id: T0608501251
Status: Open - Site Assessment
Status Date: 06/08/1989

Global Id: T0608501251
Status: Open - Site Assessment
Status Date: 02/20/1992

Global Id: T0608501251
Status: Completed - Case Closed
Status Date: 06/25/1996

HIST UST:
Name: FELIPE C. SONGCO
Address: 1288 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94041
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000028565
Facility Type: Gas Station
Other Type: Not reported
Contact Name: FELIPE C. SONGCO
Telephone: 4159640213
Owner Name: SHELL OIL COMPANY
Owner Address: P.O. BOX 4848
Owner City,St,Zip: ANAHEIM, CA 92803
Total Tanks: 0004

Tank Num: 001
Container Num: 1
Year Installed: 1972
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor, 10

FELIPE C. SONGCO (Continued) **U001594346**

Tank Num:	002
Container Num:	2
Year Installed:	1972
Tank Capacity:	00000550
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	12
Leak Detection:	Stock Inventor, 10

Tank Num:	003
Container Num:	3
Year Installed:	1972
Tank Capacity:	00008000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, 10

Tank Num:	004
Container Num:	4
Year Installed:	1972
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, 10

CUPA SANTA CLARA:

Name:	MOUNTAIN VIEW SHELL #143
Address:	1288 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2240
Program Description:	GENERATES < 10 GAL/YR
Latitude:	37.388675
Longitude:	-122.08852
Record ID:	PR0381326
Facility ID:	FA0260199

L68 **JIFFY LUBE #2342** **LUST** **S101309028**
ESE **1141 W EL CAMINO REAL** **HIST LUST** **N/A**
1/4-1/2 **MOUNTAIN VIEW, CA 94040** **AST**
0.341 mi. **Cortese**
1802 ft. **Site 1 of 5 in cluster L** **CUPA Listings**

Relative:
Higher

Actual:
105 ft.

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Case Closed
Case Number:	06S2W28C02f
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	8/3/1987

JIFFY LUBE #2342 (Continued) **S101309028**

Pollution Characterization Began: 9/17/1990
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:
Name: JOE'S FOREIGN AUTO
Address: 1141 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA
Region: SANTA CLARA
SCVWD ID: 06S2W28C02F
Date Closed: 02/03/2000
EDR Link ID: 06S2W28C02F

LUST:
Name: JOE'S FOREIGN AUTO
Address: 1141 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Lead Agency: SANTA CLARA COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608500779
Global Id: T0608500779
Latitude: 37.387424
Longitude: -122.086514
Status: Completed - Case Closed
Status Date: 02/03/2000
Case Worker: UST
RB Case Number: Not reported
Local Agency: SANTA CLARA COUNTY LOP
File Location: All Files are on GeoTracker or in the Local Agency Database
Local Case Number: Not reported
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0608500779
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608500779
Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300
City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:
Global Id: T0608500779

JIFFY LUBE #2342 (Continued) **S101309028**

Action Type: Other
Date: 11/06/1986
Action: Leak Reported

Global Id: T0608500779
Action Type: ENFORCEMENT
Date: 02/03/2000
Action: Closure/No Further Action Letter

Global Id: T0608500779
Action Type: RESPONSE
Date: 01/21/1999
Action: Other Report / Document

Global Id: T0608500779
Action Type: ENFORCEMENT
Date: 09/17/1990
Action: Notice of Responsibility - #40066

LUST:
Global Id: T0608500779
Status: Open - Case Begin Date
Status Date: 11/06/1986

Global Id: T0608500779
Status: Open - Site Assessment
Status Date: 08/03/1987

Global Id: T0608500779
Status: Open - Site Assessment
Status Date: 09/17/1990

Global Id: T0608500779
Status: Completed - Case Closed
Status Date: 02/03/2000

HIST LUST SANTA CLARA:
Name: Joe's Foreign Auto
Address: 1141 W El Camino Real
City: Mountain View
Region: SANTA CLARA
Region Code: 2
SCVWD ID: 06S2W28C02
Oversite Agency: SCVWD
Date Listed: 1987-01-01 00:00:00
Closed Date: 2000-02-03 00:00:00

AST:
Name: JIFFY LUBE #2342
Address: 1141 EL CAMINO REAL WEST
City/Zip: MOUNTAIN VIEW,94040
Certified Unified Program Agencies: Not reported
Owner: M.C., LLC
Total Gallons: Not reported
CERSID: 10344622

JIFFY LUBE #2342 (Continued) **S101309028**

Facility ID:	1086
Business Name:	M.C. LLC
Phone:	650-962-9016
Fax:	Not reported
Mailing Address:	1422 Edinger Ave., Suite 150
Mailing Address City:	Tustin
Mailing Address State:	CA
Mailing Address Zip Code:	92780
Operator Name:	M.C. LLC
Operator Phone:	714-444-4940
Owner Phone:	714-444-4940
Owner Mail Address:	1422 Edinger Ave., Suite 150
Owner State:	CA
Owner Zip Code:	92780
Owner Country:	United States
Property Owner Name:	John & Antonina Zoria
Property Owner Phone:	Not reported
Property Owner Mailing Address:	3487 McKee Rd Ste 54
Property Owner City:	San Jose
Property Owner Stat :	CA
Property Owner Zip Code:	95127
Property Owner Country:	United States
EPAID:	CAL000336640

CORTESE:

Name:	JOE'S FOREIGN AUTO
Address:	1141 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0608500779
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

CUPA SANTA CLARA:

Name:	JIFFY LUBE #2342
Address:	1141 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2011

JIFFY LUBE #2342 (Continued) **S101309028**

Program Description:	APSA FACILITY-SPCC TEMPLATE (<10,000 GAL CAP)
Latitude:	37.387343
Longitude:	-122.087905
Record ID:	PR0399578
Facility ID:	FA0263856
Name:	JIFFY LUBE #2342
Address:	1141 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	SANTA CLARA
PE#:	2206
Program Description:	GENERATES 5 TO <25 TONS/YR
Latitude:	37.387343
Longitude:	-122.087905
Record ID:	PR0388844
Facility ID:	FA0263856

L69 **JOE'S FOREIGN CAR** **HIST CORTESE** **S103983032**
ESE **1141 EL CAMINO REAL** **N/A**
1/4-1/2 **MOUNTAIN VIEW, CA**
0.341 mi.
1802 ft. **Site 2 of 5 in cluster L**

Relative: **Higher**
Actual: **105 ft.**

HIST CORTESE:

edr_fname:	JOE'S FOREIGN CAR
edr_fadd1:	1141 EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA
Region:	CORTESE
Facility County Code:	43
Reg By:	LTNKA
Reg Id:	43-0753

L70 **CAMINO CAR WASH** **HIST CORTESE** **S104565532**
ESE **1101 EL CAMINO REAL** **N/A**
1/4-1/2 **MOUNTAIN VIEW, CA 94046**
0.373 mi.
1967 ft. **Site 3 of 5 in cluster L**

Relative: **Higher**
Actual: **106 ft.**

HIST CORTESE:

edr_fname:	CAMINO CAR WASH
edr_fadd1:	1101 EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94046
Region:	CORTESE
Facility County Code:	43
Reg By:	LTNKA
Reg Id:	43-2146

L71
ESE
1/4-1/2
0.373 mi.
1967 ft.

Relative:
Higher

Actual:
106 ft.

CAMINO CAR WASH
1101 W EL CAMINO REAL
MOUNTAIN VIEW, CA 94040

Site 4 of 5 in cluster L

LUST **S101623061**
CPS-SLIC **N/A**
HIST LUST
SWEEPS UST
CA FID UST
Cortese

LUST REG 2:

Region:	2
Facility Id:	Not reported
Facility Status:	Pollution Characterization
Case Number:	06S2W28C03f
How Discovered:	Not reported
Leak Cause:	Not reported
Leak Source:	Not reported
Date Leak Confirmed:	Not reported
Oversight Program:	LUST
Prelim. Site Assesment Wokplan Submitted:	Not reported
Preliminary Site Assesment Began:	12/18/1995
Pollution Characterization Began:	12/18/1995
Pollution Remediation Plan Submitted:	Not reported
Date Remediation Action Underway:	Not reported
Date Post Remedial Action Monitoring Began:	Not reported

LUST SANTA CLARA:

Name:	CAMINO CAR WASH
Address:	1101 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA
Region:	SANTA CLARA
SCVWD ID:	06S2W28C03F
Date Closed:	10/01/2004
EDR Link ID:	06S2W28C03F

CPS-SLIC:

Name:	HARV'S CAR WASH
Address:	1101 W. EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	04/01/2018
Global Id:	T10000005942
Lead Agency:	SANTA CLARA COUNTY LOP
Lead Agency Case Number:	06S2W28C04s
Latitude:	37.387219
Longitude:	-122.0874397
Case Type:	Cleanup Program Site
Case Worker:	GOR
Local Agency:	SANTA CLARA COUNTY LOP
RB Case Number:	Not reported
File Location:	Not reported
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Lead, Polynuclear aromatic hydrocarbons (PAHs)
Site History:	Former car wash with LUFT case, which was closed on 10/1/04. In April 2013, sampling was conducted at the site and found lead and benzo(a)pyrene present in soil samples that exceeded residential standards. PCE and Benzene in soil vapor at 5 and 10 feet. Site being redeveloped residentially with below grade parking.

CAMINO CAR WASH (Continued) **S101623061**

Click here to access the California GeoTracker records for this facility:

HIST LUST SANTA CLARA:
Name: Camino Car Wash
Address: 1101 W El Camino Real
City: Mountain View
Region: SANTA CLARA
Region Code: 2
SCVWD ID: 06S2W28C03
Oversite Agency: SCVWD
Date Listed: 1996-08-01 00:00:00
Closed Date: 2004-10-01 00:00:00

SWEEPS UST:
Name: CAMINO CAR WASH
Address: 1101 W EL CAMINO REAL
City: MOUNTAIN VIEW
Status: Active
Comp Number: 9841
Number: 9
Board Of Equalization: 44-007379
Referral Date: 07-28-92
Action Date: 10-01-92
Created Date: 10-13-88
Owner Tank Id: 1
SWRCB Tank Id: 43-005-009841-000001
Tank Status: A
Capacity: 12000
Active Date: 07-01-85
Tank Use: M.V. FUEL
STG: P
Content: DIESEL
Number Of Tanks: 5

Name: CAMINO CAR WASH
Address: 1101 W EL CAMINO REAL
City: MOUNTAIN VIEW
Status: Active
Comp Number: 9841
Number: 9
Board Of Equalization: 44-007379
Referral Date: 07-28-92
Action Date: 10-01-92
Created Date: 10-13-88
Owner Tank Id: 2
SWRCB Tank Id: 43-005-009841-000002
Tank Status: A
Capacity: 12000
Active Date: 07-01-85
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: CAMINO CAR WASH

CAMINO CAR WASH (Continued) **S101623061**

Address: 1101 W EL CAMINO REAL
City: MOUNTAIN VIEW
Status: Active
Comp Number: 9841
Number: 9
Board Of Equalization: 44-007379
Referral Date: 07-28-92
Action Date: 10-01-92
Created Date: 10-13-88
Owner Tank Id: 3
SWRCB Tank Id: 43-005-009841-000003
Tank Status: A
Capacity: 10000
Active Date: 07-01-85
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: CAMINO CAR WASH
Address: 1101 W EL CAMINO REAL
City: MOUNTAIN VIEW
Status: Active
Comp Number: 9841
Number: 9
Board Of Equalization: 44-007379
Referral Date: 07-28-92
Action Date: 10-01-92
Created Date: 10-13-88
Owner Tank Id: 4
SWRCB Tank Id: 43-005-009841-000004
Tank Status: A
Capacity: 10000
Active Date: 07-01-85
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: CAMINO CAR WASH
Address: 1101 W EL CAMINO REAL
City: MOUNTAIN VIEW
Status: Active
Comp Number: 9841
Number: 9
Board Of Equalization: 44-007379
Referral Date: 07-28-92
Action Date: 10-01-92
Created Date: 10-13-88
Owner Tank Id: 5
SWRCB Tank Id: 43-005-009841-000005
Tank Status: A
Capacity: 8000
Active Date: 07-01-85
Tank Use: M.V. FUEL
STG: P
Content: LEADED

CAMINO CAR WASH (Continued) **S101623061**

Number Of Tanks: Not reported

CA FID UST:
Facility ID: 43012181
Regulated By: UTNKA
Regulated ID: 00009841
Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4159677788
Mail To: Not reported
Mailing Address: P O BOX
Mailing Address 2: Not reported
Mailing City,St,Zip: MOUNTAIN VIEW 94046
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

CORTESE:
Name: CAMINO CAR WASH
Address: 1101 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0608501970
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

L72 **CAMINO CAR WASH** **LUST** **U001594453**
ESE **1101 W EL CAMINO REAL** **HIST UST** **N/A**
1/4-1/2 **MOUNTAIN VIEW, CA 94046** **DEED**
0.373 mi. **CERS**
1967 ft. **Site 5 of 5 in cluster L**

Relative:
Higher

Actual:
106 ft.

LUST:

Name:	CAMINO CAR WASH
Address:	1101 W EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Lead Agency:	SANTA CLARA COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501970
Global Id:	T0608501970
Latitude:	37.387116
Longitude:	-122.087513
Status:	Completed - Case Closed
Status Date:	10/01/2004
Case Worker:	UST
RB Case Number:	Not reported
Local Agency:	SANTA CLARA COUNTY LOP
File Location:	All Files are on GeoTracker or in the Local Agency Database
Local Case Number:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0608501970
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

Global Id:	T0608501970
Contact Type:	Local Agency Caseworker
Contact Name:	UST CASE WORKER
Organization Name:	SANTA CLARA COUNTY LOP
Address:	1555 Berger Drive, Suite 300
City:	SAN JOSE
Email:	Not reported
Phone Number:	4089183400

LUST:

Global Id:	T0608501970
Action Type:	ENFORCEMENT
Date:	06/03/2005
Action:	Other Report

Global Id:	T0608501970
Action Type:	Other
Date:	05/04/1996
Action:	Leak Reported

Global Id:	T0608501970
Action Type:	RESPONSE

CAMINO CAR WASH (Continued) **U001594453**

Date: 09/22/2000
Action: Soil and Water Investigation Workplan

Global Id: T0608501970
Action Type: RESPONSE
Date: 12/02/2000
Action: Soil and Water Investigation Workplan

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 08/05/1996
Action: Notice of Responsibility - #40067

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 01/06/1999
Action: Staff Letter - #29387

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 08/25/2000
Action: Staff Letter - #29396

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 06/12/2002
Action: Staff Letter - #37993

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 07/24/2001
Action: Staff Letter - #29409

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 05/19/2004
Action: Deed Restriction / Land Use Restriction / Covenant

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 10/18/2000
Action: Staff Letter - #29398

Global Id: T0608501970
Action Type: RESPONSE
Date: 09/13/1996
Action: Other Report / Document

Global Id: T0608501970
Action Type: RESPONSE
Date: 06/03/2005
Action: Other Report / Document

Global Id: T0608501970
Action Type: RESPONSE
Date: 10/17/2008
Action: Other Report / Document

CAMINO CAR WASH (Continued) **U001594453**

Global Id: T0608501970
Action Type: RESPONSE
Date: 10/28/1995
Action: Soil and Water Investigation Report

Global Id: T0608501970
Action Type: RESPONSE
Date: 05/17/2001
Action: Other Report / Document

Global Id: T0608501970
Action Type: RESPONSE
Date: 01/01/1996
Action: Correspondence

Global Id: T0608501970
Action Type: RESPONSE
Date: 01/23/1996
Action: Preliminary Site Assessment Report

Global Id: T0608501970
Action Type: RESPONSE
Date: 08/14/2003
Action: Other Report / Document

Global Id: T0608501970
Action Type: RESPONSE
Date: 05/13/1997
Action: Monitoring Report - Quarterly

Global Id: T0608501970
Action Type: RESPONSE
Date: 12/12/2001
Action: Remedial Progress Report

Global Id: T0608501970
Action Type: RESPONSE
Date: 03/18/1996
Action: Unauthorized Release Form

Global Id: T0608501970
Action Type: RESPONSE
Date: 08/15/1996
Action: Other Workplan

Global Id: T0608501970
Action Type: RESPONSE
Date: 05/14/1996
Action: Tank Removal Report / UST Sampling Report

Global Id: T0608501970
Action Type: RESPONSE
Date: 07/24/2001
Action: Other Report / Document

Global Id: T0608501970
Action Type: REMEDIATION

CAMINO CAR WASH (Continued) **U001594453**

Date: 06/01/2001
Action: Excavation

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 04/11/1998
Action: Staff Letter - #29382

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 09/28/2000
Action: Staff Letter - #29400

Global Id: T0608501970
Action Type: ENFORCEMENT
Date: 02/13/2001
Action: Staff Letter - #29406

Global Id: T0608501970
Action Type: RESPONSE
Date: 07/15/1998
Action: Monitoring Report - Quarterly

Global Id: T0608501970
Action Type: RESPONSE
Date: 03/15/1999
Action: Soil and Water Investigation Report

Global Id: T0608501970
Action Type: RESPONSE
Date: 12/27/2000
Action: Soil and Water Investigation Report

Global Id: T0608501970
Action Type: RESPONSE
Date: 08/09/2002
Action: Remedial Progress Report

Global Id: T0608501970
Action Type: RESPONSE
Date: 10/31/2001
Action: Soil and Water Investigation Report

Global Id: T0608501970
Action Type: RESPONSE
Date: 02/13/2001
Action: Soil and Water Investigation Workplan

LUST:
Global Id: T0608501970
Status: Open - Case Begin Date
Status Date: 12/18/1995

Global Id: T0608501970
Status: Open - Site Assessment
Status Date: 12/18/1995

CAMINO CAR WASH (Continued) **U001594453**

Global Id: T0608501970
Status: Completed - Case Closed
Status Date: 10/01/2004

HIST UST:
Name: CAMINO CAR WASH
Address: 1101 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94046
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000009841
Facility Type: Gas Station
Other Type: Not reported
Contact Name: Not reported
Telephone: 4159677788
Owner Name: ROGER WOODWARD
Owner Address: 1101 EL CAMINO REAL
Owner City,St,Zip: MT. VIEW, CA 94040
Total Tanks: 0005

Tank Num: 001
Container Num: 1
Year Installed: 1981
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Container Construction Thickness: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 002
Container Num: 2
Year Installed: 1979
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 003
Container Num: 3
Year Installed: 1975
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: Not reported
Leak Detection: Visual, Stock Inventor

Tank Num: 004
Container Num: 4
Year Installed: 1969
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: Not reported
Leak Detection: Visual, Stock Inventor

CAMINO CAR WASH (Continued) **U001594453**

Tank Num: 005
Container Num: 5
Year Installed: 1969
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: Not reported
Leak Detection: Visual, Stock Inventor

DEED:
Name: CAMINO CAR WASH
Address: 1101 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Envirostor ID: T0608501970
Area: Not reported
Sub Area: Not reported
Site Type: LUFT
Status: COMPLETED - CASE CLOSED
Agency: SWRCB
Covenant Uploaded: Y
Deed Date(s): 05/19/2004
File Name: Geotracker Land Use/Deed Restrictions

CERS:
Name: CAMINO CAR WASH
Address: 1101 W EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 187596
CERS ID: T0608501970
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: UST CASE WORKER - SANTA CLARA COUNTY LOP
Entity Title: Not reported
Affiliation Address: 1555 Berger Drive, Suite 300
Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089183400

Affiliation Type Desc: Regional Board Caseworker
Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)
Entity Title: Not reported
Affiliation Address: 1515 CLAY ST SUITE 1400
Affiliation City: OAKLAND
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

73
ESE
1/2-1
0.577 mi.
3045 ft.

FLUFF DRY CLEANING
801-819 WEST EL CAMINO REAL
MOUNTAIN VIEW, CA 94040

ENVIROSTOR VCP **S118353708 N/A**

Relative: Higher

Actual: 107 ft.

ENVIROSTOR:

Name:	FLUFF DRY CLEANING
Address:	801-819 WEST EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Facility ID:	60001528
Status:	Active
Status Date:	10/29/2014
Site Code:	201912
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	0.4
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Jovanne Villamater
Supervisor:	Cheryl Prowell
Division Branch:	Cleanup Berkeley
Assembly:	24
Senate:	13
Special Program:	CLRRA Liability Immunity (AB 389)
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.38578
Longitude:	-122.0845
APN:	NONE SPECIFIED
Past Use:	DRY CLEANING
Potential COC:	Tetrachloroethylene (PCE
Confirmed COC:	Tetrachloroethylene (PCE
Potential Description:	SOIL, SV
Alias Name:	201912
Alias Type:	Project Code (Site Code)
Alias Name:	60001528
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	06/24/2011
Comments:	DTSC sent a letter to the site owner/applicant providing notification that DTSC was determined to be the appropriate lead agency after consulting with the Regional Water Quality Control Board, as required by the Memorandum of Agreement.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	02/27/2009
Comments:	Benchmark requested that DTSC make a determination that no further action is required for the site. Enclosures to the letter included post-soil removal sampling results, a site characterization report, and waste profile report.

FLUFF DRY CLEANING (Continued) **S118353708**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: California Land Reuse and Revitalization Agreement
Completed Date: 05/26/2015
Comments: California Land Use and Revitalization Act Agreement between CV Mountain View, LLC and DTSC was fully executed on May 26, 2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Responsible Agency Review
Completed Date: 09/30/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2016
Comments: DTSC letter with oversight cost estimate for fiscal year 2016/2017

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/09/2017
Comments: DTSC oversight cost estimate for fiscal year 2017/2018 (July 1, 2017 - June 30, 2018)

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/04/2018
Comments: DTSC annual oversight cost estimate for fiscal year 2018/2019

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/05/2020
Comments: Due to COVID-19 Pandemic, Annual Cost Estimate transmitted via email on 10/05/2020.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/11/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 06/20/2011
Comments: DTSC received an application requesting oversight of further investigation of the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 10/29/2014
Comments: Not reported

FLUFF DRY CLEANING (Continued) **S118353708**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 08/05/2015
Comments: The Community Profile provides a description of the Site and the community in which it is located, helps DTSC to determine potential community interest in the investigation and cleanup activities at the Site, and recommends future public participation activities.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: AB 389 Response Plan
Completed Date: 10/01/2015
Comments: The Response Plan selects installation of a vapor mitigation system, which includes a passive venting system and a vapor barrier, as the response action for the site. The planned development project is expected to include excavation of soil to 13 feet below the entire footprint of the building that is to be constructed to accommodate a subterranean parking lot.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 08/06/2015
Comments: A fact sheet was mailed to the community and interested parties on August 5, 2015 to announce the public comment period on the Draft Response Plan to be held from August 7 through September 8, 2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 08/06/2015
Comments: A public notice was published in Palo Alto Daily newspaper on August 7, 2015 to announce the public comment period for the Draft Response Plan to be held from August 7 through September 8, 2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 04/20/2017
Comments: Vapor mitigation system installation completed on 04/20/2017. Final inspection of installed vapor mitigation system performed on 04/20/2017.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Design
Completed Date: 10/12/2015
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Land Use Restriction
Future Due Date: 2021
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification

FLUFF DRY CLEANING (Continued) **S118353708**

Future Due Date: 2022
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Removal Action Completion Report
Schedule Due Date: 01/31/2021
Schedule Revised Date: Not reported

VCP:
Name: FLUFF DRY CLEANING
Address: 801-819 WEST EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Facility ID: 60001528
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 0.4
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Jovanne Villamater
Supervisor: Cheryl Prowell
Division Branch: Cleanup Berkeley
Site Code: 201912
Assembly: 24
Senate: 13
Special Programs Code: CLRRA Liability Immunity (AB 389)
Status: Active
Status Date: 10/29/2014
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.38578 / -122.0845
APN: NONE SPECIFIED
Past Use: DRY CLEANING
Potential COC: 30022
Confirmed COC: 30022
Potential Description: SOIL, SV
Alias Name: 201912
Alias Type: Project Code (Site Code)
Alias Name: 60001528
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 06/24/2011
Comments: DTSC sent a letter to the site owner/applicant providing notification that DTSC was determined to be the appropriate lead agency after consulting with the Regional Water Quality Control Board, as required by the Memorandum of Agreement.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 02/27/2009
Comments: Benchmark requested that DTSC make a determination that no further

FLUFF DRY CLEANING (Continued) **S118353708**

action is required for the site. Enclosures to the letter included post-soil removal sampling results, a site characterization report, and waste profile report.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: California Land Reuse and Revitalization Agreement
Completed Date: 05/26/2015
Comments: California Land Use and Revitalization Act Agreement between CV Mountain View, LLC and DTSC was fully executed on May 26, 2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Responsible Agency Review
Completed Date: 09/30/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2016
Comments: DTSC letter with oversight cost estimate for fiscal year 2016/2017

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/09/2017
Comments: DTSC oversight cost estimate for fiscal year 2017/2018 (July 1, 2017 - June 30, 2018)

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/04/2018
Comments: DTSC annual oversight cost estimate for fiscal year 2018/2019

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/05/2020
Comments: Due to COVID-19 Pandemic, Annual Cost Estimate transmitted via email on 10/05/2020.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/11/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 06/20/2011
Comments: DTSC received an application requesting oversight of further investigation of the site.

Completed Area Name: PROJECT WIDE

FLUFF DRY CLEANING (Continued) **S118353708**

Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 10/29/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 08/05/2015
Comments: The Community Profile provides a description of the Site and the community in which it is located, helps DTSC to determine potential community interest in the investigation and cleanup activities at the Site, and recommends future public participation activities.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: AB 389 Response Plan
Completed Date: 10/01/2015
Comments: The Response Plan selects installation of a vapor mitigation system, which includes a passive venting system and a vapor barrier, as the response action for the site. The planned development project is expected to include excavation of soil to 13 feet below the entire footprint of the building that is to be constructed to accommodate a subterranean parking lot.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 08/06/2015
Comments: A fact sheet was mailed to the community and interested parties on August 5, 2015 to announce the public comment period on the Draft Response Plan to be held from August 7 through September 8, 2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 08/06/2015
Comments: A public notice was published in Palo Alto Daily newspaper on August 7, 2015 to announce the public comment period for the Draft Response Plan to be held from August 7 through September 8, 2015.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 04/20/2017
Comments: Vapor mitigation system installation completed on 04/20/2017. Final inspection of installed vapor mitigation system performed on 04/20/2017.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Design
Completed Date: 10/12/2015
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported

FLUFF DRY CLEANING (Continued) **S118353708**

Future Document Type:	Land Use Restriction
Future Due Date:	2021
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	Certification
Future Due Date:	2022
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Removal Action Completion Report
Schedule Due Date:	01/31/2021
Schedule Revised Date:	Not reported

---

74 **SATAKE NURSERY** **ENVIROSTOR** **S104541863**
SSE **1079 MARILYN** **LUST** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94040** **VCP**
0.605 mi. **HIST CORTESE**
3197 ft. **CIWQS**

Relative: Higher

Actual: 125 ft.

ENVIROSTOR:

Name:	SATAKE NURSERY
Address:	1079 MARILYN DRIVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Facility ID:	60000834
Status:	No Further Action
Status Date:	11/03/2008
Site Code:	Not reported
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	6.38
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Not reported
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Assembly:	24
Senate:	13
Special Program:	Voluntary Cleanup Program
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.38079
Longitude:	-122.0911
APN:	189-28-051, 189-28-054
Past Use:	AGRICULTURAL - ORCHARD, EQUIPMENT/INSTRUMENT REPAIR, FUEL - VEHICLE STORAGE/ REFUELING, NURSERY
Potential COC:	Arsenic DDT Lead TPH-diesel Cadmium and compounds
Confirmed COC:	30024-NO Cadmium and compounds Arsenic DDT Lead
Potential Description:	SOIL
Alias Name:	SummerHill Homes
Alias Type:	Alternate Name
Alias Name:	189-28-051
Alias Type:	APN
Alias Name:	189-28-054
Alias Type:	APN
Alias Name:	T0608501205
Alias Type:	GeoTracker Global ID
Alias Name:	60000834

SATAKE NURSERY (Continued) **S104541863**

Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 05/19/2008
Comments: DTSC review of the Phase I Report completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 10/31/2008
Comments: No Further Action issued based on information provided.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 04/11/2008
Comments: VCA executed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 11/05/2008
Comments: Project activities completed.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

LUST SANTA CLARA:
Name: SATAKE NURSERY
Address: 1079 MARILYN AVE
City,State,Zip: MOUNTAIN VIEW, CA
Region: SANTA CLARA
SCVWD ID: 06S2W28L01F
Date Closed: 01/17/1992
EDR Link ID: 06S2W28L01F

LUST:
Name: SATAKE NURSERY
Address: 1079 MARILYN AVE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Lead Agency: SANTA CLARA COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501205
Global Id: T0608501205
Latitude: 37.380848699715
Longitude: -122.092373371124
Status: Completed - Case Closed

SATAKE NURSERY (Continued) **S104541863**

Status Date: 01/17/1992
Case Worker: UST
RB Case Number: Not reported
Local Agency: SANTA CLARA COUNTY LOP
File Location: All Files are on GeoTracker or in the Local Agency Database
Local Case Number: Not reported
Potential Media Affect: Soil
Potential Contaminants of Concern: Diesel
Site History: Not reported

LUST:
Global Id: T0608501205
Contact Type: Regional Board Caseworker
Contact Name: Regional Water Board
Organization Name: SAN FRANCISCO BAY RWQCB (REGION 2)
Address: 1515 CLAY ST SUITE 1400
City: OAKLAND
Email: Not reported
Phone Number: Not reported

Global Id: T0608501205
Contact Type: Local Agency Caseworker
Contact Name: UST CASE WORKER
Organization Name: SANTA CLARA COUNTY LOP
Address: 1555 Berger Drive, Suite 300
City: SAN JOSE
Email: Not reported
Phone Number: 4089183400

LUST:
Global Id: T0608501205
Action Type: Other
Date: 02/20/1990
Action: Leak Reported

Global Id: T0608501205
Action Type: ENFORCEMENT
Date: 06/01/1990
Action: Notice of Responsibility - #40068

Global Id: T0608501205
Action Type: ENFORCEMENT
Date: 01/17/1992
Action: Closure/No Further Action Letter

Global Id: T0608501205
Action Type: RESPONSE
Date: 02/20/1990
Action: Other Report / Document

Global Id: T0608501205
Action Type: REMEDIATION
Date: 01/18/1991
Action: Excavation

LUST:
Global Id: T0608501205

SATAKE NURSERY (Continued) **S104541863**

Status: Open - Case Begin Date
Status Date: 02/20/1990

Global Id: T0608501205
Status: Open - Site Assessment
Status Date: 06/28/1990

Global Id: T0608501205
Status: Completed - Case Closed
Status Date: 01/17/1992

VCP:
Name: SATAKE NURSERY
Address: 1079 MARILYN DRIVE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Facility ID: 60000834
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 6.38
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Not reported
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Site Code: Not reported
Assembly: 24
Senate: 13
Special Programs Code: Voluntary Cleanup Program
Status: No Further Action
Status Date: 11/03/2008
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.38079 / -122.0911
APN: 189-28-051, 189-28-054
Past Use: AGRICULTURAL - ORCHARD, EQUIPMENT/INSTRUMENT REPAIR, FUEL - VEHICLE STORAGE/ REFUELING, NURSERY
Potential COC: 30001, 30008, 30013, 30024, 30108
Confirmed COC: 30024-NO,30108,30001,30008,30013
Potential Description: SOIL
Alias Name: SummerHill Homes
Alias Type: Alternate Name
Alias Name: 189-28-051
Alias Type: APN
Alias Name: 189-28-054
Alias Type: APN
Alias Name: T0608501205
Alias Type: GeoTracker Global ID
Alias Name: 60000834
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

SATAKE NURSERY (Continued) **S104541863**

Completed Document Type: Other Report
Completed Date: 05/19/2008
Comments: DTSC review of the Phase I Report completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 10/31/2008
Comments: No Further Action issued based on information provided.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 04/11/2008
Comments: VCA executed

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 11/05/2008
Comments: Project activities completed.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

HIST CORTESE:
edr_fname: SATAKE NURSERY
edr_fadd1: 1079 MARILYN
City,State,Zip: MOUNTAIN VIEW, CA 94040
Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1226

CIWQS:
Name: MARILYN DRIVE PROJECT STORMWATER OUTFALL TO PERMANENTE CREEK
Address: 1079 MARILYN DR
City,State,Zip: MOUNTAIN VIEW, CA 94041
Agency: Summerhill Homes
Agency Address: 777 S California Ave, Palo Alto, CA 94304
Place/Project Type: Construction - Residential
SIC/NAICS: Not reported
Region: 2
Program: CONSTW
Regulatory Measure Status: Terminated
Regulatory Measure Type: Storm water construction
Order Number: 2009-0009-DWQ
WDID: 2 43C352774
NPDES Number: CAS000002

SATAKE NURSERY (Continued) **S104541863**

Adoption Date:	Not reported
Effective Date:	07/29/2008
Termination Date:	12/14/2012
Expiration/Review Date:	Not reported
Design Flow:	Not reported
Major/Minor:	Not reported
Complexity:	Not reported
TTWQ:	Not reported
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	Not reported
Longitude:	Not reported

75
SE
1/2-1
0.624 mi.
3294 ft.

DLC CASTRO **ENVIROSTOR** **S100851971**
1172 CASTRO STREET **HIST CORTESE** **N/A**
MOUNTAIN VIEW, CA 94040

Relative:
Higher

Actual:
119 ft.

ENVIROSTOR:

Name:	DLC CASTRO
Address:	1172 CASTRO STREET
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Facility ID:	43010009
Status:	No Further Action
Status Date:	04/04/1996
Site Code:	200338
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	2.7
NPL:	NO
Regulatory Agencies:	SMBRP, CITY OF MOUNTAIN VIEW
Lead Agency:	CITY OF MOUNTAIN VIEW
Program Manager:	Denise Tsuji
Supervisor:	Denise Tsuji
Division Branch:	Cleanup Berkeley
Assembly:	24
Senate:	13
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.38220
Longitude:	-122.0865
APN:	189-61-023
Past Use:	AGRICULTURAL - ROW CROPS
Potential COC:	DDT
Confirmed COC:	DDT
Potential Description:	SOIL
Alias Name:	189-61-023
Alias Type:	APN
Alias Name:	200338
Alias Type:	Project Code (Site Code)
Alias Name:	43010009
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE

DLC CASTRO (Continued) **S100851971**

Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 06/30/1993
Comments: Former 100 by 300 foot orchard developed with commercial offices under City permit which conditioned approval on preparation of a PEA Report. PEA that was prepared indicated 1-3 ppm DDT in top 6 inches of soil. Subsequently, City of Mountain View oversaw soil removal by developer.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 06/29/1990
Comments: Completed Site Screening. The property is presently a residential parcel in an area of mixed land use. The site was an orchard with a home, other buildings, and a storage shed. Sample results showed DDT, DDD, and DDE. in surface soil exceeding the TTLC. The developer proposed to excavate soil, encapsulate under a soil cap, and asphalt concrete paving. Residual soil sampled to confirm decontamination.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Inspections/Visit (Non LUR)
Completed Date: 09/08/1995
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

HIST CORTESE:
edr_fname: DLC CASTRO
edr_fadd1: 1172 CASTRO
City,State,Zip: MOUNTAIN VIEW, CA
Region: CORTESE
Facility County Code: 43
Reg By: CALSI
Reg Id: 43010009

M76 **JASCO CHEM CORP** **Delisted NPL** **1000175646**
NNE **1710 VILLA ST** **SEMS** **CAD009103318**
1/2-1 **MOUNTAIN VIEW, CA 94043** **RCRA-SQG**
0.650 mi. **US ENG CONTROLS**
3431 ft. **Site 1 of 4 in cluster M** **US INST CONTROLS**
ROD
Relative: **PRP**
Lower

Actual: Delisted NPL:
68 ft. EPA Region: 9
EPA ID: CAD009103318
Site ID: 901126

JASCO CHEM CORP (Continued) **1000175646**

Name: JASCO CHEMICAL CORP.
Address: 1710 VILLA ST
City,State,Zip: MOUNTAIN VIEW, CA 94041
Federal Description: N
Latitude: 37.3988
Longitude: -122.0882
Deleted Date: 2020-09-30 00:00:00

SEMS:
Site ID: 0901126
EPA ID: CAD009103318
Name: JASCO CHEMICAL CORP.
Address: 1710 VILLA ST
Address 2: Not reported
City,State,Zip: MOUNTAIN VIEW, CA 94041
Cong District: 14,18
FIPS Code: 06085
Latitude: +37.398800
Longitude: -122.088200
FF: N
NPL: Deleted from the Final NPL
Non NPL Status: Not reported

SEMS Detail:
Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N
OU: 00
Action Code: ND
Action Name: DELETION
SEQ: 1
Start Date: 2020-05-27 05:00:00
Finish Date: 9/30/2020 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: 1987-06-01 04:00:00
Finish Date: 6/1/1987 4:00:00 AM
Qual: H
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318

JASCO CHEM CORP (Continued) **1000175646**

Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	FE
Action Name:	5 YEAR
SEQ:	1
Start Date:	2006-12-12 05:00:00
Finish Date:	9/28/2007 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	TA
Action Name:	TECH ASSIST
SEQ:	1
Start Date:	2011-03-03 05:00:00
Finish Date:	3/3/2011 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	NP
Action Name:	PROPOSED
SEQ:	1
Start Date:	1988-06-24 04:00:00
Finish Date:	6/24/1988 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	CR
Action Name:	CI
SEQ:	1
Start Date:	1988-04-20 04:00:00
Finish Date:	7/1/1988 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

JASCO CHEM CORP (Continued) **1000175646**

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	NF
Action Name:	NPL FINL
SEQ:	1
Start Date:	1989-10-04 04:00:00
Finish Date:	10/4/1989 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	2
Start Date:	1991-04-11 04:00:00
Finish Date:	4/11/1991 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	RS
Action Name:	RV ASSESS
SEQ:	1
Start Date:	1990-09-19 04:00:00
Finish Date:	9/19/1990 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	01
Action Code:	AR
Action Name:	ADMIN REC
SEQ:	1
Start Date:	1991-03-01 05:00:00
Finish Date:	5/22/1992 4:00:00 AM

JASCO CHEM CORP (Continued) **1000175646**

Qual:	E
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	1986-10-01 04:00:00
Finish Date:	10/1/1986 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	FE
Action Name:	5 YEAR
SEQ:	2
Start Date:	2012-09-28 05:00:00
Finish Date:	9/28/2012 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	01
Action Code:	RO
Action Name:	ROD
SEQ:	1
Start Date:	1992-09-30 04:00:00
Finish Date:	9/30/1992 4:00:00 AM
Qual:	R
Current Action Lead:	EPA Perf
Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	00
Action Code:	PA
Action Name:	PA

JASCO CHEM CORP (Continued) **1000175646**

SEQ: 1
Start Date: 1986-12-01 05:00:00
Finish Date: 12/1/1986 5:00:00 AM
Qual: L
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N
OU: 00
Action Code: CM
Action Name: PCOR
SEQ: 1
Start Date: 2002-09-20 04:00:00
Finish Date: 9/20/2002 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N
OU: 00
Action Code: HR
Action Name: HAZRANK
SEQ: 1
Start Date: 1987-06-01 04:00:00
Finish Date: 6/1/1987 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N
OU: 00
Action Code: TU
Action Name: NOID
SEQ: 1
Start Date: 2020-05-26 05:00:00
Finish Date: 9/30/2020 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N

JASCO CHEM CORP (Continued) **1000175646**

OU: 00
Action Code: CQ
Action Name: CLSOUT R
SEQ: 1
Start Date: 2018-09-30 05:00:00
Finish Date: 3/31/2019 5:00:00 AM
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N
OU: 00
Action Code: CR
Action Name: CI
SEQ: 2
Start Date: 2020-05-14 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N
OU: 00
Action Code: AR
Action Name: ADMIN REC
SEQ: 2
Start Date: 2020-05-11 05:00:00
Finish Date: Not reported
Qual: Not reported
Current Action Lead: EPA Perf

Region: 09
Site ID: 0901126
EPA ID: CAD009103318
Site Name: JASCO CHEMICAL CORP.
NPL: D
FF: N
OU: 00
Action Code: MA
Action Name: ST COOP
SEQ: 1
Start Date: 1989-09-15 04:00:00
Finish Date: 9/15/1989 4:00:00 AM
Qual: Not reported
Current Action Lead: EPA Ovrsght

Region: 09
Site ID: 0901126
EPA ID: CAD009103318

JASCO CHEM CORP (Continued) **1000175646**

Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	01
Action Code:	TS
Action Name:	TRTSTUDY
SEQ:	1
Start Date:	1994-06-15 04:00:00
Finish Date:	2/1/1998 5:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	01
Action Code:	BD
Action Name:	PRP RI/FS
SEQ:	1
Start Date:	1988-12-21 05:00:00
Finish Date:	9/30/1992 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	01
Action Code:	BE
Action Name:	PRP RD
SEQ:	1
Start Date:	1992-12-16 05:00:00
Finish Date:	7/31/1996 4:00:00 AM
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

Region:	09
Site ID:	0901126
EPA ID:	CAD009103318
Site Name:	JASCO CHEMICAL CORP.
NPL:	D
FF:	N
OU:	01
Action Code:	BF
Action Name:	PRP RA
SEQ:	1
Start Date:	1996-07-31 04:00:00
Finish Date:	9/9/2002 4:00:00 AM
Qual:	FR
Current Action Lead:	EPA Ovrsght

JASCO CHEM CORP (Continued) **1000175646**

RCRA-SQG:

Date Form Received by Agency:		1996-09-01 00:00:00.0
Handler Name:	JASCO CHEM CORP	
Handler Address:		1710 VILLA ST
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94043
EPA ID:		CAD009103318
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		CA
State District:		2
Mailing Address:		DRAWER J
Mailing City,State,Zip:		MOUNTAIN VIEW, CA 94043
Owner Name:		Not reported
Owner Type:		Not reported
Operator Name:		NOT REQUIRED
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported

JASCO CHEM CORP (Continued) **1000175646**

202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:23:33.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1996-09-01 00:00:00.0
Handler Name: JASCO CHEM CORP	

JASCO CHEM CORP (Continued) **1000175646**

Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1980-08-18 00:00:00.0
Handler Name: JASCO CHEM CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 32551
NAICS Description: PAINT AND COATING MANUFACTURING

NAICS Code: 325998
NAICS Description: ALL OTHER MISCELLANEOUS CHEMICAL PRODUCT AND PREPARATION MANUFACTURING

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SIte:
Name: JASCO CHEMICAL CORP.
Address: 1710 VILLA ST
Address 2: Not reported
City,State,Zip: MOUNTAIN VIEW, CA 94041
Event Code: Not reported
Action Taken Date: 09/26/2012
EPA ID: CAD009103318
Action Name: Explanation of Significant Differences
Action ID: 2
Operable Unit: 01
Contaminated Media: Groundwater
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2012

JASCO CHEM CORP (Continued) **1000175646**

NPL Status: Deleted from the Final NPL
Superfund Alternative Agreement: N
Latitude: +37.398800
Longitude: -122.088200

Media:
EPA ID: CAD009103318
Contaminated Media: Groundwater
Action ID: 1
Operable Unit: 01
Action Name: Explanation of Significant Differences
Action Taken Date: 09/13/2002
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2002
NPL Status: Deleted from the Final NPL
Superfund Alternative Agreement: N
Latitude: +37.398800
Longitude: -122.088200

EPA ID: CAD009103318
Contaminated Media: Soil
Action ID: 1
Operable Unit: 01
Action Name: Explanation of Significant Differences
Action Taken Date: 09/13/2002
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2002
NPL Status: Deleted from the Final NPL
Superfund Alternative Agreement: N
Latitude: +37.398800
Longitude: -122.088200

EPA ID: CAD009103318
Contaminated Media: Groundwater
Action ID: 1
Operable Unit: 01
Action Name: Explanation of Significant Differences
Action Taken Date: 09/13/2002
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 2002
NPL Status: Deleted from the Final NPL
Superfund Alternative Agreement: N
Latitude: +37.398800
Longitude: -122.088200

EPA ID: CAD009103318

JASCO CHEM CORP (Continued) **1000175646**

Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Explanation of Significant Differences
Action Taken Date:	09/13/2002
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2002
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Groundwater
Action ID:	2
Operable Unit:	01
Action Name:	Explanation of Significant Differences
Action Taken Date:	09/26/2012
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2012
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported

JASCO CHEM CORP (Continued) **1000175646**

Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL

JASCO CHEM CORP (Continued) **1000175646**

Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Groundwater
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Groundwater

JASCO CHEM CORP (Continued) **1000175646**

Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

EPA ID:	CAD009103318
Contaminated Media:	Soil
Action ID:	1
Operable Unit:	01
Action Name:	Record of Decision
Action Taken Date:	09/30/1992
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	1992
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

US INST CONTROLS:

Name:	JASCO CHEMICAL CORP.
Address:	1710 VILLA ST
Address 2:	Not reported
City,State,Zip:	MOUNTAIN VIEW, CA 94041
EPA ID:	CAD009103318
Action Name:	Explanation of Significant Differences
Action ID:	1
Operable Unit:	01
Actual Date:	09/13/2002
Contaminated Media:	Groundwater
Event Code:	Not reported
Contact Name:	Not reported
Contact Telephone:	Not reported
Event:	Not reported
Federal Facility:	N
Fiscal Year:	2002
NPL Status:	Deleted from the Final NPL
Superfund Alternative Agreement:	N
Latitude:	+37.398800
Longitude:	-122.088200

Name:	JASCO CHEMICAL CORP.
Address:	1710 VILLA ST

JASCO CHEM CORP (Continued) **1000175646**

Address 2: Not reported
City,State,Zip: MOUNTAIN VIEW, CA 94041
EPA ID: CAD009103318
Action Name: Record of Decision
Action ID: 1
Operable Unit: 01
Actual Date: 09/30/1992
Contaminated Media: Groundwater
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 1992
NPL Status: Deleted from the Final NPL
Superfund Alternative Agreement: N
Latitude: +37.398800
Longitude: -122.088200

Name: JASCO CHEMICAL CORP.
Address: 1710 VILLA ST
Address 2: Not reported
City,State,Zip: MOUNTAIN VIEW, CA 94041
EPA ID: CAD009103318
Action Name: Record of Decision
Action ID: 1
Operable Unit: 01
Actual Date: 09/30/1992
Contaminated Media: Soil
Event Code: Not reported
Contact Name: Not reported
Contact Telephone: Not reported
Event: Not reported
Federal Facility: N
Fiscal Year: 1992
NPL Status: Deleted from the Final NPL
Superfund Alternative Agreement: N
Latitude: +37.398800
Longitude: -122.088200

ROD:
Name: JASCO CHEMICAL CORP.
Address: 1710 VILLA ST
City,State,Zip: MOUNTAIN VIEW, CA 94041
EPA ID: CAD009103318
RG: 9
Site ID: 901126
Action: GOVT ESD
Operable Unit Number: OVERALL SITE
SEQ ID: 1
Action Completion: 2002-09-13 00:00:00
NPL Status: Final
Non NPL Status: Not reported

Name: JASCO CHEMICAL CORP.
Address: 1710 VILLA ST
City,State,Zip: MOUNTAIN VIEW, CA 94041

JASCO CHEM CORP (Continued) **1000175646**

EPA ID:	CAD009103318
RG:	9
Site ID:	901126
Action:	GOVT ESD
Operable Unit Number:	OVERALL SITE
SEQ ID:	2
Action Completion:	2012-09-26 00:00:00
NPL Status:	Final
Non NPL Status:	Not reported

Name:	JASCO CHEMICAL CORP.
Address:	1710 VILLA ST
City,State,Zip:	MOUNTAIN VIEW, CA 94041
EPA ID:	CAD009103318
RG:	9
Site ID:	901126
Action:	GOVT ROD for PRP Remedy
Operable Unit Number:	OVERALL SITE
SEQ ID:	1
Action Completion:	1992-09-30 00:00:00
NPL Status:	Final
Non NPL Status:	Not reported

PRP:

PRP Name:	CAROL JEAN ANTHONY
	CAROL JEAN ANTHONY
	CAROL JEAN ANTHONY
	HARRY M. ANTHONY
	HARRY M. ANTHONY
	HARRY M. ANTHONY
	JASCO CHEMICAL
	JASCO CHEMICAL
	JASCO CHEMICAL
	JASCO CHEMICAL

M77 **JASCO CHEMICAL CORP.** **ENVIROSTOR** **U001594367**
NNE **1710 VILLA ST** **HIST UST** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94042** **ENF**
0.650 mi. **CIWQS**
3431 ft. **Site 2 of 4 in cluster M** **CERS**

Relative:
Lower

Actual:
68 ft.

ENVIROSTOR:

Name:	JASCO CHEMICAL CO
Address:	1710 VILLA STREET
City,State,Zip:	MOUNTAIN VIEW, CA 94041
Facility ID:	43280119
Status:	Refer: RWQCB
Status Date:	01/10/1990
Site Code:	Not reported
Site Type:	Federal Superfund
Site Type Detailed:	State Response or NPL
Acres:	2.05
NPL:	DELISTED
Regulatory Agencies:	US EPA
Lead Agency:	US EPA
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned

JASCO CHEMICAL CORP. (Continued) **U001594367**

Division Branch: Cleanup Berkeley
Assembly: 24
Senate: 13
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not reported
Latitude: 37.39892
Longitude: -122.0890
APN: 154-02-001
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: JASCO CHEMICAL CORPORATION
Alias Type: Alternate Name
Alias Name: 154-02-001
Alias Type: APN
Alias Name: CAD009103318
Alias Type: EPA Identification Number
Alias Name: 110001197259
Alias Type: EPA (FRS #)
Alias Name: T0608592706
Alias Type: GeoTracker Global ID
Alias Name: P23081
Alias Type: PCode
Alias Name: 43280119
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: National Priority List Delisting Document
Completed Date: 12/27/2018
Comments: DTSC concurs with delisting site from NPL.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

HIST UST:
Name: JASCO CHEMICAL CORP.
Address: 1710 VILLA ST
City,State,Zip: MOUNTAIN VIEW, CA 94042
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000008412
Facility Type: Other
Other Type: MANUFACTURER
Contact Name: JAY KANANI

JASCO CHEMICAL CORP. (Continued) **U001594367**

Telephone:	4159686005
Owner Name:	JASCO CHEMICAL CORP.
Owner Address:	P. O. BOX J
Owner City,St,Zip:	MOUNTAIN VIEW, CA 94042
Total Tanks:	0009
Tank Num:	001
Container Num:	ONE
Year Installed:	1976
Tank Capacity:	00012000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Groundwater Monitoring Well
Tank Num:	002
Container Num:	TWO
Year Installed:	1976
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Groundwater Monitoring Well
Tank Num:	003
Container Num:	THREE
Year Installed:	1976
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Groundwater Monitoring Well
Tank Num:	004
Container Num:	FOUR
Year Installed:	1976
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Groundwater Monitoring Well
Tank Num:	005
Container Num:	FIVE
Year Installed:	1976
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Groundwater Monitoring Well
Tank Num:	006
Container Num:	SIX
Year Installed:	1976
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported

JASCO CHEMICAL CORP. (Continued) **U001594367**

Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 007
Container Num: SEVEN
Year Installed: 1976
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 008
Container Num: EIGHT
Year Installed: 1976
Tank Capacity: 00005000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

Tank Num: 009
Container Num: NINE
Year Installed: Not reported
Tank Capacity: 00000500
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Container Construction Thickness: Not reported
Leak Detection: Groundwater Monitoring Well

ENF:
Name: 1710 VILLA ST., JASCO CHEMICAL
Address: 1710 VILLA
City,State,Zip: MOUNTAIN VIEW, CA 94041
Region: 2
Facility Id: 201774
Agency Name: Jasco Chemical Corporation
Place Type: Facility
Place Subtype: Groundwater Cleanup Site
Facility Type: All other facilities
Agency Type: Privately-Owned Business
Of Agencies: 1
Place Latitude: 37.398002
Place Longitude: -122.089466
SIC Code 1: 2851
SIC Desc 1: Paints, Varnishes, Lacquers, Enamels, and Allied Products
SIC Code 2: Not reported
SIC Desc 2: Not reported
SIC Code 3: Not reported
SIC Desc 3: Not reported
NAICS Code 1: Not reported
NAICS Desc 1: Not reported
NAICS Code 2: Not reported
NAICS Desc 2: Not reported
NAICS Code 3: Not reported
NAICS Desc 3: Not reported
Of Places: 1

JASCO CHEMICAL CORP. (Continued) **U001594367**

Source Of Facility:	Reg Meas
Design Flow:	0.0648
Threat To Water Quality:	2
Complexity:	B
Pretreatment:	N - POTW does not have EPA approved pretreatment prog.
Facility Waste Type:	Not reported
Facility Waste Type 2:	Not reported
Facility Waste Type 3:	Not reported
Facility Waste Type 4:	Not reported
Program:	NPDNONMUNIPRCS
Program Category1:	NPDESWW
Program Category2:	NPDESWW
# Of Programs:	1
WDID:	2 438210001
Reg Measure Id:	183046
Reg Measure Type:	Enrollee
Region:	2
Order #:	R2-2004-0055
Npdes# CA#:	CAG912003
Major-Minor:	Minor
Npdes Type:	Not reported
Reclamation:	N - No
Dredge Fill Fee:	Not reported
301H:	Not reported
Application Fee Amt Received:	1000
Status:	Historical
Status Date:	09/14/2005
Effective Date:	11/13/1997
Expiration/Review Date:	07/20/1999
Termination Date:	09/14/2005
WDR Review - Amend:	Not reported
WDR Review - Revise/Renew:	Not reported
WDR Review - Rescind:	Not reported
WDR Review - No Action Required:	Not reported
WDR Review - Pending:	Not reported
WDR Review - Planned:	Not reported
Status Enrollee:	Y
Individual/General:	I
Fee Code:	62 - Treatment system to meet priority pollutant limit Category 1
Direction/Voice:	Passive
Enforcement Id(EID):	239361
Region:	2
Order / Resolution Number:	R2-2001-0075
Enforcement Action Type:	Admin Civil Liability
Effective Date:	10/15/2001
Adoption/Issuance Date:	Not reported
Achieve Date:	Not reported
Termination Date:	Not reported
ACL Issuance Date:	Not reported
EPL Issuance Date:	Not reported
Status:	Historical
Title:	Enforcement - 2 438210001
Description:	Exceeded PCE limit of 5.0 ppb (at 29 ppb and 41 ppb).
Program:	NPDNONMUNIPRCS
Latest Milestone Completion Date:	10/31/2001
# Of Programs1:	1
Total Assessment Amount:	6000

JASCO CHEMICAL CORP. (Continued) **U001594367**

Initial Assessed Amount:	0
Liability $ Amount:	6000
Project $ Amount:	0
Liability $ Paid:	6000
Project $ Completed:	0
Total $ Paid/Completed Amount:	6000

CIWQS:

Name:	1710 VILLA ST., JASCO CHEMICAL
Address:	1710 VILLA
City,State,Zip:	MOUNTAIN VIEW, CA 94041
Agency:	Jasco Chemical Corporation
Agency Address:	Po Box 1180, Mountain View, CA 94042-1180
Place/Project Type:	Groundwater Cleanup Site
SIC/NAICS:	2851
Region:	2
Program:	NPDNONMUNIPRCS
Regulatory Measure Status:	Historical
Regulatory Measure Type:	Enrollee
Order Number:	R2-2004-0055
WDID:	2 438210001
NPDES Number:	CAG912003
Adoption Date:	Not reported
Effective Date:	11/13/1997
Termination Date:	09/14/2005
Expiration/Review Date:	07/20/1999
Design Flow:	0.0648
Major/Minor:	Minor
Complexity:	B
TTWQ:	2
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	37.398002
Longitude:	-122.089466

CERS:

Name:	1710 VILLA ST., JASCO CHEMICAL
Address:	1710 VILLA
City,State,Zip:	MOUNTAIN VIEW, CA 94041
Site ID:	348264
CERS ID:	201774
CERS Description:	NPDES Wastewater and Stormwater

Violations:

Site ID:	348264
Site Name:	1710 Villa St., JASCO Chemical
Violation Date:	04-23-2001
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	An effluent sample contained 41 ppb PCE exceeded 5.0 ppb limit in Order No. 99-051.
Violation Division:	Water Boards
Violation Program:	NPDNONMUNI
Violation Source:	CIWQS

Site ID:	348264
Site Name:	1710 Villa St., JASCO Chemical

JASCO CHEMICAL CORP. (Continued) **U001594367**

Violation Date:	04-23-2001
Citation:	California Water Code
Violation Description:	Not reported
Violation Notes:	An effluent sample contained 29 ppb PCE exceeded 5.0 ppb limit in Order No. 99-051.
Violation Division:	Water Boards
Violation Program:	NPDNONMUNI
Violation Source:	CIWQS

Enforcement Action:

Site ID:	348264
Site Name:	1710 Villa St., JASCO Chemical
Site Address:	1710 VILLA
Site City:	MOUNTAIN VIEW
Site Zip:	94041
Enf Action Date:	10-15-2001
Enf Action Type:	Administrative Enforcement with Penality
Enf Action Description:	Administrative Enforcement with Civil Liability (Penality)
Enf Action Notes:	Not reported
Enf Action Division:	Water Boards
Enf Action Program:	UNSPEC
Enf Action Source:	CIWQS

M78 **JASCO CHEMICAL CO** **HIST Cal-Sites** **1000175630**
NNE **1710 VILLA STREET** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94041**
0.650 mi.
3431 ft. **Site 3 of 4 in cluster M**

Relative:
Lower

Actual:
68 ft.

Calsite:

Name:	JASCO CHEMICAL CO
Address:	1710 VILLA STREET
City:	MOUNTAIN VIEW
Region:	BERKELEY
Facility ID:	43280119
Facility Type:	NPRP
Type:	NPL SITE, RP-FUNDED
Branch:	NC
Branch Name:	NORTH COAST
File Name:	Not reported
State Senate District:	01101990
Status:	DOES NOT REQUIRE DTSC ACTION. REFERRED TO REGIONAL WATER QUALITY CONTROL BOARD (RWQCB) LEAD
Status Name:	PROPERTY/SITE REFERRED TO RWQCB
Lead Agency:	ENVIRONMENTAL PROTECTION AGENCY
NPL:	Listed
SIC Code:	28
SIC Name:	MANU - CHEMICALS & ALLIED PRODUCTS
Access:	Not reported
Cortese:	Not reported
Hazardous Ranking Score:	Not reported
Date Site Hazard Ranked:	Not reported
Groundwater Contamination:	Confirmed
Staff Member Responsible for Site:	Not reported
Supervisor Responsible for Site:	Not reported
Region Water Control Board:	Not reported

JASCO CHEMICAL CO (Continued) **1000175630**

Region Water Control Board Name:	Not reported
Lat/Long Direction:	Not reported
Lat/Long (dms):	0 0 0 / 0 0 0
Lat/long Method:	Not reported
Lat/Long Description:	Not reported
State Assembly District Code:	22
State Senate District Code:	13
Facility ID:	Not reported
Activity:	Not reported
Activity Name:	Not reported
AWP Code:	Not reported
Proposed Budget:	Not reported
AWP Completion Date:	Not reported
Revised Due Date:	Not reported
Comments Date:	Not reported
Est Person-Yrs to complete:	Not reported
Estimated Size:	Not reported
Request to Delete Activity:	Not reported
Activity Status:	Not reported
Definition of Status:	Not reported
Liquids Removed (Gals):	Not reported
Liquids Treated (Gals):	Not reported
Action Included Capping:	Not reported
Well Decommissioned:	Not reported
Action Included Fencing:	Not reported
Removal Action Certification:	Not reported
Activity Comments:	Not reported
For Commercial Reuse:	Not reported
For Industrial Reuse:	Not reported
For Residential Reuse:	Not reported
Unknown Type:	Not reported
Alternate Address:	1710 VILLA STREET
Alternate City,St,Zip:	MOUNTAIN VIEW, CA 95246
Alternate Address:	1710 VILLA STREET
Alternate City,St,Zip:	MOUNTAIN VIEW, CA 94041
Background Info:	Not reported
Comments Date:	07251991
Comments:	Groundwater is contaminated with VOCs, phenols, and diesel
Comments Date:	07251991
Comments:	fuel. Soil contains VOCs and diesel fuel. Surface water is
Comments Date:	07251991
Comments:	contaminated with VOCs and PCP. People may face a health
Comments Date:	07251991
Comments:	threat if they inhale contaminated vapors or drink/touch
Comments Date:	07251991
Comments:	contaminated groundwater.
ID Name:	BEP DATABASE PCODE
ID Value:	P23081
ID Name:	EPA IDENTIFICATION NUMBER
ID Value:	CAD009103318
Alternate Name:	JASCO CHEMICAL CORPORATION
Alternate Name:	JASCO CHEMICAL CO
Alternate Name:	Not reported
Special Programs Code:	Not reported
Special Programs Name:	Not reported

M79 **JASCO CHEMICAL CORPORATION** **CA BOND EXP. PLAN** **S105960435**
NNE **1710 VILLA STREET** **EMI** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 95246**
0.650 mi.
3431 ft. **Site 4 of 4 in cluster M**

Relative: **Lower**
Actual: **68 ft.**

CA BOND EXP. PLAN:

Reponsible Party:	NPL SITE CLEANUP WORKPLAN
Project Revenue Source Company:	Not reported
Project Revenue Source Addr:	Not reported
Project Revenue Source City,St,Zip:	Not reported
Project Revenue Source Desc:	This site has been proposed for listing on the NPL. It is expected that the RP will remediate this site with oversight by EPA. DHS will perform a limited role of oversight and monitoring of the remedial activities at this site. DHS has budgeted $50,000 for oversight and monitoring costs. DHS will recover 100 percent of direct costs plus staff costs and overhead related to the project.
Site Description:	The Jasco Chemical Corporation has formulated chemical products at this 2.05-acre site in Mountain View since 1976. The site is bordered on the northeast by the Central Expressway and Southern Pacific Railroad, and on the remaining sides by residential units. The facility handles and stores numerous chemicals onsite in underground tanks and 55 gallon drums.
Hazardous Waste Desc:	The contaminants detected in the soil and ground water onsite include trichloroethane (TCA), dichloroethane (DCA), dichloroethylene (DCE), phenol and methylene chloride (MCL).
Threat To Public Health & Env:	Within a 3-mile radius of the site there are approximately 199,000 people who depend on ground water as a source of drinking water. Contaminants have migrated at least 10 feet beyond the property boundary, as evidenced by the detection of DCA and TCA in an offsite well. Mountain View wells #17 and #10 are located within 1,500 feet and 3,100 feet of the site, respectively.
Site Activity Status:	Investigations at the site were initiated in 1984. Both soil and ground water contamination has been detected onsite. Discharges of surface runoff from the rear of the facility appear to be a major source of contaminants. Up to 11,000 parts per million (ppm) paint thinner was detected in soil samples taken near a runoff outfall. Jasco Chemical has been extracting contaminated ground water from one well since February, 1987.

EMI:

Name:	JASCO CHEMICAL CORPORATION
Address:	1710 VILLA STREET
City,State,Zip:	MOUNTAIN VIEW, CA 95246
Year:	1990
County Code:	43
Air Basin:	SF
Facility ID:	5477
Air District Name:	BA
SIC Code:	2869
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	JASCO CHEMICAL CORPORATION
Address:	1710 VILLA STREET

JASCO CHEMICAL CORPORATION (Continued) **S105960435**

City,State,Zip:	MOUNTAIN VIEW, CA 95246
Year:	1993
County Code:	43
Air Basin:	SF
Facility ID:	5477
Air District Name:	BA
SIC Code:	2869
Air District Name:	BAY AREA AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

80
NW
1/2-1
0.758 mi.
4001 ft.

FORMER PLATINUM CLEANERS **ENVIROSTOR** **S113068127**
2290 WEST EL CAMINO REAL **VCP** **N/A**
MOUNTAIN VIEW, CA 94040

Relative:
Lower

Actual:
83 ft.

ENVIROSTOR:

Name:	FORMER PLATINUM CLEANERS
Address:	2290 WEST EL CAMINO REAL
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Facility ID:	60002117
Status:	Certified
Status Date:	02/23/2018
Site Code:	202021
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	1.55
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Jayantha Randeni
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Assembly:	24
Senate:	13
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Responsible Party
Latitude:	37.39749
Longitude:	-122.1047
APN:	148-36-17, 14836017
Past Use:	DRY CLEANING
Potential COC:	Tetrachloroethylene (PCE
Confirmed COC:	Tetrachloroethylene (PCE
Potential Description:	IA, SOIL, SV
Alias Name:	El Camino Village, LLC
Alias Type:	Alternate Name
Alias Name:	148-36-17
Alias Type:	APN

FORMER PLATINUM CLEANERS (Continued) **S113068127**

Alias Name: 14836017
Alias Type: APN
Alias Name: 202021
Alias Type: Project Code (Site Code)
Alias Name: 60002117
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 10/02/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 09/24/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 12/15/2014
Comments: The Phase I Environmental Site Assessment was conducted to identify recognized environmental conditions at the Site. The findings and conclusions of the Report were based on the results of a reconnaissance-level site visit and review of available and pertinent background information. This assessment was completed prior to DTSC becoming involved at the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 12/15/2014
Comments: The Additional Phase II Environmental Assessment report presents the results of subsurface soil-gas, soil, and groundwater sampling that was performed to evaluate the lateral and vertical extent of impact from PCE and other volatile organic compounds. These investigations were completed prior to DTSC becoming involved at the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pre-HARP Form
Completed Date: 06/04/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 12/12/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 03/02/2016
Comments: Not reported

FORMER PLATINUM CLEANERS (Continued) **S113068127**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/06/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/28/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 02/23/2018
Comments: DTSC certified that all appropriate response actions have been completed, that all acceptable engineering practices were implemented and that no further removal action is necessary.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pilot/Treatability Study Report
Completed Date: 12/18/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 05/29/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 07/02/2015
Comments: The soil gas sampling included in the Additional Site Characterization Workplan was repeated due to leakage in the sampling equipment that occurred during the first sampling event.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 09/04/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 03/04/2016
Comments: Soil vapor extraction is identified in the Removal Action Workplan as

FORMER PLATINUM CLEANERS (Continued) **S113068127**

the selected remedy for the Site to address tetrachloroethene and trichloroethene in soil vapor at the site and on an adjacent property.
Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 01/26/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 01/26/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 03/02/2017
Comments: The soil vapor extraction system operated continuously on the site from April 2016 through October 2016. There was a 47-day shutdown for rebound assessment that followed and the system was briefly operated in December 2016 and January 2017. DTSC approved decommissioning of the soil vapor extraction system in a March 9, 2017 letter.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pilot/Treatability Study Report
Completed Date: 01/15/2015
Comments: The Second Vapor-Extraction Pilot-Study Evaluation report presents the results of a soil vapor extraction pilot study that was conducted using one multi-phase extraction well for 8 days and 2 extraction wells for 7 days. This study was completed prior to DTSC becoming involved at the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 01/11/2018
Comments: The soil vapor extraction system operated from April 2016 to January 2017 and sampling showed that the removal action goal for PCE in soil gas for residential development at the Site has been achieved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 05/17/2017
Comments: The Soil Management Plan provides procedures for managing potentially contaminated soil excavated for the subterranean parking garage of the proposed development project.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 03/10/2017
Comments: The report summarizes soil gas remediation activities at the Site

FORMER PLATINUM CLEANERS (Continued) **S113068127**

since the soil vapor extraction (SVE) system was initially started in April 2016. A total of 16.7 pounds of tetrachloroethylene (PCE) was removed by the SVE system and soil gas concentrations beneath the Site are below the removal goal of 3,900 micrograms per cubic meter established for residential development.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/17/2017
Comments: The Plan summarizes the results of soil sampling conducted at the Site to profile for disposal and/or reuse the soil that will be generated as part of the excavation required for the proposed subterranean parking garage.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 10/31/2017
Comments: Excavation was completed for the subterranean parking garage that is part of the development occurring on the Site.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: FORMER PLATINUM CLEANERS
Address: 2290 WEST EL CAMINO REAL
City,State,Zip: MOUNTAIN VIEW, CA 94040
Facility ID: 60002117
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 1.55
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Jayantha Randeni
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Site Code: 202021
Assembly: 24
Senate: 13
Special Programs Code: Not reported
Status: Certified
Status Date: 02/23/2018
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.39749 / -122.1047

FORMER PLATINUM CLEANERS (Continued) **S113068127**

APN:	148-36-17, 14836017
Past Use:	DRY CLEANING
Potential COC:	30022
Confirmed COC:	30022
Potential Description:	IA, SOIL, SV
Alias Name:	El Camino Village, LLC
Alias Type:	Alternate Name
Alias Name:	148-36-17
Alias Type:	APN
Alias Name:	14836017
Alias Type:	APN
Alias Name:	202021
Alias Type:	Project Code (Site Code)
Alias Name:	60002117
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Application
Completed Date:	10/02/2014
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Community Profile
Completed Date:	09/24/2015
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Phase 1
Completed Date:	12/15/2014
Comments:	The Phase I Environmental Site Assessment was conducted to identify recognized environmental conditions at the Site. The findings and conclusions of the Report were based on the results of a reconnaissance-level site visit and review of available and pertinent background information. This assessment was completed prior to DTSC becoming involved at the Site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	12/15/2014
Comments:	The Additional Phase II Environmental Assessment report presents the results of subsurface soil-gas, soil, and groundwater sampling that was performed to evaluate the lateral and vertical extent of impact from PCE and other volatile organic compounds. These investigations were completed prior to DTSC becoming involved at the Site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Pre-HARP Form
Completed Date:	06/04/2015
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

FORMER PLATINUM CLEANERS (Continued) **S113068127**

Completed Document Type: Standard Voluntary Agreement
Completed Date: 12/12/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 03/02/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/06/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/28/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 02/23/2018
Comments: DTSC certified that all appropriate response actions have been completed, that all acceptable engineering practices were implemented and that no further removal action is necessary.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/26/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pilot/Treatability Study Report
Completed Date: 12/18/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 05/29/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 07/02/2015
Comments: The soil gas sampling included in the Additional Site Characterization Workplan was repeated due to leakage in the sampling equipment that occurred during the first sampling event.

Completed Area Name: PROJECT WIDE

FORMER PLATINUM CLEANERS (Continued) **S113068127**

Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 09/04/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 03/04/2016
Comments: Soil vapor extraction is identified in the Removal Action Workplan as the selected remedy for the Site to address tetrachloroethene and trichloroethene in soil vapor at the site and on an adjacent property.
Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 01/26/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 01/26/2016
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 03/02/2017
Comments: The soil vapor extraction system operated continuously on the site from April 2016 through October 2016. There was a 47-day shutdown for rebound assessment that followed and the system was briefly operated in December 2016 and January 2017. DTSC approved decommissioning of the soil vapor extraction system in a March 9, 2017 letter.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pilot/Treatability Study Report
Completed Date: 01/15/2015
Comments: The Second Vapor-Extraction Pilot-Study Evaluation report presents the results of a soil vapor extraction pilot study that was conducted using one multi-phase extraction well for 8 days and 2 extraction wells for 7 days. This study was completed prior to DTSC becoming involved at the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 01/11/2018
Comments: The soil vapor extraction system operated from April 2016 to January 2017 and sampling showed that the removal action goal for PCE in soil gas for residential development at the Site has been achieved.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan

FORMER PLATINUM CLEANERS (Continued) **S113068127**

Completed Date: 05/17/2017
Comments: The Soil Management Plan provides procedures for managing potentially contaminated soil excavated for the subterranean parking garage of the proposed development project.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 03/10/2017
Comments: The report summarizes soil gas remediation activities at the Site since the soil vapor extraction (SVE) system was initially started in April 2016. A total of 16.7 pounds of tetrachloroethylene (PCE) was removed by the SVE system and soil gas concentrations beneath the Site are below the removal goal of 3,900 micrograms per cubic meter established for residential development.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/17/2017
Comments: The Plan summarizes the results of soil sampling conducted at the Site to profile for disposal and/or reuse the soil that will be generated as part of the excavation required for the proposed subterranean parking garage.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 10/31/2017
Comments: Excavation was completed for the subterranean parking garage that is part of the development occurring on the Site.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

N81 **FREMONT LAUNDRY** **ENVIROSTOR** **S110769675**
ENE **990 VILLA STREET** **VCP** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94041**
0.807 mi.
4259 ft. **Site 1 of 3 in cluster N**

Relative: **Lower**
Actual: **73 ft.**

ENVIROSTOR:
Name: FREMONT LAUNDRY
Address: 990 VILLA STREET
City,State,Zip: MOUNTAIN VIEW, CA 94041
Facility ID: 60001426
Status: Active
Status Date: 12/20/2018
Site Code: 202137
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup

FREMONT LAUNDRY (Continued) **S110769675**

Acres:	0.3
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Jayantha Randeni
Supervisor:	Cheryl Prowell
Division Branch:	Cleanup Berkeley
Assembly:	24
Senate:	13
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	EPA Grant
Latitude:	37.39473
Longitude:	-122.0809
APN:	15815024
Past Use:	DRY CLEANING, LAUNDRY SERVICES
Potential COC:	Tetrachloroethylene (PCE
Confirmed COC:	30022-NO
Potential Description:	OTH, SOIL
Alias Name:	15815024
Alias Type:	APN
Alias Name:	201898
Alias Type:	Project Code (Site Code)
Alias Name:	202137
Alias Type:	Project Code (Site Code)
Alias Name:	60001426
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	PA/SI Site Screening
Completed Date:	06/30/2011
Comments:	The Site Screening concludes the site is a potential source of PCE impacts to groundwater and a Preliminary Endangerment Assessment should be performed.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	08/27/2014
Comments:	Letter to owner informing of contamination at the site.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	08/29/2014
Comments:	Owner email to DTSC.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	PA/SI Reassessment
Completed Date:	01/26/2015
Comments:	Reassessment conducted by DTSC on EPA's behalf to determine if the site should be considered for the National Priorities List. DTSC concluded that DTSC is the primary cleanup agency but EPA will periodically review the progress towards cleanup as DTSC and the

FREMONT LAUNDRY (Continued) **S110769675**

property owner are negotiating an agreement to oversee environmental investigation and cleanup.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/05/2014
Comments: DTSC response to Owner.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/19/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/11/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/23/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: California Land Reuse and Revitalization Agreement
Completed Date: 05/22/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 09/11/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 05/14/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/11/2015
Comments: The Results of Sub-Slab Soil Vapor Assessment report presents the findings of a sub-slab soil vapor assessment that was performed by the Site owner to determine whether former operations by Austin's Fremont Laundry impacted the Site. Sub-slab sampling of soil vapor was performed at six locations in the building that occupies the Site. Elevated concentrations of tetrachloroethene (PCE) were detected in the soil vapor samples. The highest PCE concentrations were detected on the eastern side of the building and were about an

FREMONT LAUNDRY (Continued) **S110769675**

order of magnitude lower on the western side of the building.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 04/14/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 12/15/2017
Comments: Request for Agency Oversight Application submitted by Four Corners Properties Investment Company, LLC to DTSC. The party decided not to proceed with the project.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 01/11/2019
Comments: Villa Street LP submitted a Request for Agency Oversight Application/Supplemental California Land Reuse and Revitalization Act Application to DTSC.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 12/28/2018
Comments: The report report recommends removal of impacted soil at the location of the former dry cleaning equipment and preparation of a vapor intrusion mitigation Response Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 08/07/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 07/25/2019
Comments: The Report documents site assessment activities performed in March and April 2017 and excavation activities performed in November of 2018.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: AB 389 Response Plan
Completed Date: 09/11/2019
Comments: The remedy proposed in the Response Plan includes active sub-slab vapor depressurization system, soil management plan, operation and maintenance plan and a land use covenant to restrict the groundwater.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets

FREMONT LAUNDRY (Continued) **S110769675**

Completed Date: 07/31/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 07/31/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 05/20/2020
Comments: The report summarizes the response actions completed at the Site, including details of the operation of the active sub slab depressurization system (SSDS), and presents post SSDS indoor air sampling results that demonstrates that the SSDS is operating as designed and is acting to mitigate vapor intrusion risk to the building.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan
Completed Date: 09/18/2020
Comments: The OM&M Plan provides instructions for operation and maintenance of sub-slab depressurization system (SSDS), and SSDS monitoring schedule.
Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Financial Assurance Documentation
Completed Date: 09/03/2020
Comments: FA cost estimate approved by Branch chief.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 07/11/2019
Comments: The Tenant Improvement Soil Management Plan provides guidelines for appropriate health and safety precautions during tenant improvement construction activities for on-site construction workers who may encounter soil that could contain residual chemicals, provides procedures during construction activities for management of residual chemicals present in soil and soil vapor at the Site, and provide procedures for management of unknown conditions including subsurface structures, if encountered.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 10/04/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 10/15/2020

FREMONT LAUNDRY (Continued) **S110769675**

Comments: The SMP provides provide administrative and work protocols to protect human health and the environment during potential future redevelopment activities and post occupancy sub-slab activities such as utility repairs and concrete replacement for on site construction workers.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/25/2020
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Land Use Restriction
Future Due Date: 2021
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification
Future Due Date: 2021
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: FREMONT LAUNDRY
Address: 990 VILLA STREET
City,State,Zip: MOUNTAIN VIEW, CA 94041
Facility ID: 60001426
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 0.3
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Jayantha Randeni
Supervisor: Cheryl Prowell
Division Branch: Cleanup Berkeley
Site Code: 202137
Assembly: 24
Senate: 13
Special Programs Code: Not reported
Status: Active
Status Date: 12/20/2018
Restricted Use: NO
Funding: EPA Grant
Lat/Long: 37.39473 / -122.0809
APN: 15815024
Past Use: DRY CLEANING, LAUNDRY SERVICES
Potential COC: 30022
Confirmed COC: 30022-NO
Potential Description: OTH, SOIL
Alias Name: 15815024

FREMONT LAUNDRY (Continued) **S110769675**

Alias Type: APN
Alias Name: 201898
Alias Type: Project Code (Site Code)
Alias Name: 202137
Alias Type: Project Code (Site Code)
Alias Name: 60001426
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: PA/SI Site Screening
Completed Date: 06/30/2011
Comments: The Site Screening concludes the site is a potential source of PCE impacts to groundwater and a Preliminary Endangerment Assessment should be performed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/27/2014
Comments: Letter to owner informing of contamination at the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 08/29/2014
Comments: Owner email to DTSC.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: PA/SI Reassessment
Completed Date: 01/26/2015
Comments: Reassessment conducted by DTSC on EPA's behalf to determine if the site should be considered for the National Priorities List. DTSC concluded that DTSC is the primary cleanup agency but EPA will periodically review the progress towards cleanup as DTSC and the property owner are negotiating an agreement to oversee environmental investigation and cleanup.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/05/2014
Comments: DTSC response to Owner.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/19/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/11/2014
Comments: Not reported

FREMONT LAUNDRY (Continued) **S110769675**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/23/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: California Land Reuse and Revitalization Agreement
Completed Date: 05/22/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Notice of Exemption
Completed Date: 09/11/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Assessment Report
Completed Date: 05/14/1991
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 06/11/2015
Comments: The Results of Sub-Slab Soil Vapor Assessment report presents the findings of a sub-slab soil vapor assessment that was performed by the Site owner to determine whether former operations by Austin's Fremont Laundry impacted the Site. Sub-slab sampling of soil vapor was performed at six locations in the building that occupies the Site. Elevated concentrations of tetrachloroethene (PCE) were detected in the soil vapor samples. The highest PCE concentrations were detected on the eastern side of the building and were about an order of magnitude lower on the western side of the building.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 04/14/2017
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 12/15/2017
Comments: Request for Agency Oversight Application submitted by Four Corners Properties Investment Company, LLC to DTSC. The party decided not to proceed with the project.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 01/11/2019
Comments: Villa Street LP submitted a Request for Agency Oversight

FREMONT LAUNDRY (Continued) **S110769675**

Application/Supplemental California Land Reuse and Revitalization Act Application to DTSC.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 12/28/2018
Comments: The report report recommends removal of impacted soil at the location of the former dry cleaning equipment and preparation of a vapor intrusion mitigation Response Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 08/07/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 07/25/2019
Comments: The Report documents site assessment activities performed in March and April 2017 and excavation activities performed in November of 2018.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: AB 389 Response Plan
Completed Date: 09/11/2019
Comments: The remedy proposed in the Response Plan includes active sub-slab vapor depressurization system, soil management plan, operation and maintenance plan and a land use covenant to restrict the groundwater.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 07/31/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 07/31/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Action Completion Report
Completed Date: 05/20/2020
Comments: The report summarizes the response actions completed at the Site, including details of the operation of the active sub slab depressurization system (SSDS), and presents post SSDS indoor air sampling results that demonstrates that the SSDS is operating as designed and is acting to mitigate vapor intrusion risk to the building.

Completed Area Name: PROJECT WIDE

FREMONT LAUNDRY (Continued) **S110769675**

Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan
Completed Date: 09/18/2020
Comments: The OM&M Plan provides instructions for operation and maintenance of sub-slab depressurization system (SSDS), and SSDS monitoring schedule.
Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Financial Assurance Documentation
Completed Date: 09/03/2020
Comments: FA cost estimate approved by Branch chief.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 07/11/2019
Comments: The Tenant Improvement Soil Management Plan provides guidelines for appropriate health and safety precautions during tenant improvement construction activities for on-site construction workers who may encounter soil that could contain residual chemicals, provides procedures during construction activities for management of residual chemicals present in soil and soil vapor at the Site, and provide procedures for management of unknown conditions including subsurface structures, if encountered.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 10/04/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 10/15/2020
Comments: The SMP provides provide administrative and work protocols to protect human health and the environment during potential future redevelopment activities and post occupancy sub-slab activities such as utility repairs and concrete replacement for on site construction workers.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/25/2020
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Land Use Restriction
Future Due Date: 2021
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification
Future Due Date: 2021
Schedule Area Name: Not reported

FREMONT LAUNDRY (Continued) **S110769675**

Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

82
WSW
1/2-1
0.810 mi.
4276 ft.

Relative:
Higher

Actual:
144 ft.

LOS ALTOS HS
201 ALMOND AVE
LOS ALTOS, CA 94022

RCRA-SQG **1000101636**
ENVIROSTOR **CAD981693864**
SCH
CERS HAZ WASTE
FINDS
ECHO
CUPA Listings
NPDES
CIWQS
CERS

RCRA-SQG:

Date Form Received by Agency:		1986-12-29 00:00:00.0
Handler Name:	LOS ALTOS HS	
Handler Address:		201 ALMOND AVE
Handler City,State,Zip:		LOS ALTOS, CA 94022
EPA ID:		CAD981693864
Contact Name:		ENVIRONMENTAL MANAGER
Contact Address:		201 ALMOND AVE
Contact City,State,Zip:		LOS ALTOS, CA 94022
Contact Telephone:		415-940-4666
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Other
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		CA
State District:		2
Mailing Address:		201 ALMOND AVE
Mailing City,State,Zip:		LOS ALTOS, CA 94022
Owner Name:		MT VIEW LOS ALTOS DIST
Owner Type:		Private
Operator Name:		NOT REQUIRED
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

LOS ALTOS HS (Continued) **1000101636**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:31:07.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	MT VIEW LOS ALTOS DIST
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator

LOS ALTOS HS (Continued) **1000101636**

Owner/Operator Name: NOT REQUIRED
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, ME 99999
Owner/Operator Telephone: 415-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 1986-12-29 00:00:00.0
Handler Name: LOS ALTOS HS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 61111
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ENVIROSTOR:
Name: LOS ALTOS HIGH SCHOOL EXPANSION
Address: 201 ALMOND AVENUE
City,State,Zip: LOS ALTOS, CA 94022
Facility ID: 60002914
Status: Active
Status Date: 12/06/2019
Site Code: 204320
Site Type: School Cleanup
Site Type Detailed: School
Acres: 2
NPL: NO
Regulatory Agencies: SANTA CLARA COUNTY
Lead Agency: SANTA CLARA COUNTY
Program Manager: Letitia Shen
Supervisor: Jose Salcedo
Division Branch: Northern California Schools & Santa Susana
Assembly: 24
Senate: 13

LOS ALTOS HS (Continued) **1000101636**

Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not Applicable
Latitude: 37.38692
Longitude: -122.1092
APN: NONE SPECIFIED
Past Use: AGRICULTURAL - ROW CROPS, UNDERGROUND STORAGE TANKS, SCHOOL - HIGH SCHOOL
Potential COC: Lead Naturally Occurring Asbestos (NOA TPH-diesel TPH-MOTOR OIL Dieldrin Polychlorinated biphenyls (PCBs
Confirmed COC: 30013-NO 30018-NO 30024-NO 3002502-NO 30207-NO 40002-NO
Potential Description: SOIL, SV
Alias Name: 204320
Alias Type: Project Code (Site Code)
Alias Name: 60002914
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement Application
Completed Date: 12/12/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/18/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 05/26/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 06/05/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 08/19/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 01/29/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: School Cleanup Agreement

LOS ALTOS HS (Continued) **1000101636**

Completed Date:	09/16/2020
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Pre-HARP Form
Completed Date:	06/05/2020
Comments:	Not reported
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	Removal Action Completion Report
Future Due Date:	2021
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	Certification
Future Due Date:	2021
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Removal Action Workplan
Schedule Due Date:	04/15/2021
Schedule Revised Date:	Not reported
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Supplemental Site Investigation Report
Schedule Due Date:	04/16/2021
Schedule Revised Date:	Not reported
Schedule Area Name:	PROJECT WIDE
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Preliminary Endangerment Assessment Report
Schedule Due Date:	10/13/2020
Schedule Revised Date:	Not reported

SCH:

Name:	LOS ALTOS HIGH SCHOOL EXPANSION
Address:	201 ALMOND AVENUE
City,State,Zip:	LOS ALTOS, CA 94022
Facility ID:	60002914
Site Type:	School Cleanup
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	2
National Priorities List:	NO
Cleanup Oversight Agencies:	SANTA CLARA COUNTY
Lead Agency:	SANTA CLARA COUNTY
Lead Agency Description:	SANTA CLARA COUNTY
Project Manager:	Letitia Shen
Supervisor:	Jose Salcedo
Division Branch:	Northern California Schools & Santa Susana
Site Code:	204320
Assembly:	24
Senate:	13
Special Program Status:	Not reported
Status:	Active
Status Date:	12/06/2019
Restricted Use:	NO

LOS ALTOS HS (Continued) **1000101636**

Funding: Not Applicable
Latitude: 37.38692
Longitude: -122.1092
APN: NONE SPECIFIED
Past Use: AGRICULTURAL - ROW CROPS, UNDERGROUND STORAGE TANKS, SCHOOL - HIGH SCHOOL
Potential COC: Lead, Naturally Occurring Asbestos (NOA, TPH-diesel, TPH-MOTOR OIL, Dieldrin, Polychlorinated biphenyls (PCBs
Confirmed COC: 30013-NO, 30018-NO, 30024-NO, 3002502-NO, 30207-NO, 40002-NO
Potential Description: SOIL, SV
Alias Name: 204320
Alias Type: Project Code (Site Code)
Alias Name: 60002914
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement Application
Completed Date: 12/12/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 12/18/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 05/26/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 06/05/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 08/19/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 01/29/2020
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: School Cleanup Agreement
Completed Date: 09/16/2020
Comments: Not reported

LOS ALTOS HS (Continued) **1000101636**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pre-HARP Form
Completed Date: 06/05/2020
Comments: Not reported

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Removal Action Completion Report
Future Due Date: 2021
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification
Future Due Date: 2021
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Removal Action Workplan
Schedule Due Date: 04/15/2021
Schedule Revised Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Supplemental Site Investigation Report
Schedule Due Date: 04/16/2021
Schedule Revised Date: Not reported
Schedule Area Name: PROJECT WIDE
Schedule Sub Area Name: Not reported
Schedule Document Type: Preliminary Endangerment Assessment Report
Schedule Due Date: 10/13/2020
Schedule Revised Date: Not reported

CERS HAZ WASTE:
Name: LOS ALTOS HIGH SCHOOL
Address: 201 ALMOND AV
City,State,Zip: LOS ALTOS, CA 94022
Site ID: 45044
CERS ID: 10348729
CERS Description: Hazardous Waste Generator

FINDS:
Registry ID: 110002755395

Click Here:

Environmental Interest/Information System:
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
STATE MASTER

LOS ALTOS HS (Continued) **1000101636**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000101636
Registry ID:	110002755395
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002755395
Name:	LOS ALTOS HS
Address:	201 ALMOND AVE
City,State,Zip:	LOS ALTOS, CA 94022

CUPA SANTA CLARA:

Name:	LOS ALTOS HIGH SCHOOL
Address:	201 ALMOND AV
City,State,Zip:	LOS ALTOS, CA 94022
Region:	SANTA CLARA
PE#:	2205
Program Description:	GENERATES 100 KG YR TO <5 TONS/YR
Latitude:	37.385149
Longitude:	-122.109318
Record ID:	PR0315349
Facility ID:	FA0201525

Name:	LOS ALTOS HIGH SCHOOL
Address:	201 ALMOND AV
City,State,Zip:	LOS ALTOS, CA 94022
Region:	SANTA CLARA
PE#:	Not reported
Program Description:	HMBP FACILITY, 7-9 CHEMICALS
Latitude:	37.385149
Longitude:	-122.109318
Record ID:	PR0369494
Facility ID:	FA0201525

NPDES:

Name:	LOS ALTOS HIGH SCHOOL
Address:	201 ALMOND AVENUE
City,State,Zip:	LOS ALTOS, CA 94022
Facility Status:	Active
NPDES Number:	CAS000002
Region:	2
Agency Number:	0
Regulatory Measure ID:	513314
Place ID:	Not reported
Order Number:	2009-0009-DWQ
WDID:	2 43C388232
Regulatory Measure Type:	Enrollee
Program Type:	Construction
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	09/30/2019
Termination Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Discharge Address:	1299 Bryant Avenue
Discharge Name:	Mountain View Los Altos High School District
Discharge City:	Mountain View
Discharge State:	California

LOS ALTOS HS (Continued) **1000101636**

Discharge Zip:	94040
Status:	Not reported
Status Date:	Not reported
Operator Name:	Not reported
Operator Address:	Not reported
Operator City:	Not reported
Operator State:	Not reported
Operator Zip:	Not reported
Name:	LOS ALTOS HIGH SCHOOL
Address:	201 ALMOND AVENUE
City,State,Zip:	LOS ALTOS, CA 94022
Facility Status:	Not reported
NPDES Number:	Not reported
Region:	Not reported
Agency Number:	Not reported
Regulatory Measure ID:	Not reported
Place ID:	Not reported
Order Number:	Not reported
WDID:	2 43C388232
Regulatory Measure Type:	Construction
Program Type:	Not reported
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Discharge Address:	Not reported
Discharge Name:	Not reported
Discharge City:	Not reported
Discharge State:	Not reported
Discharge Zip:	Not reported
Status:	Active
Status Date:	09/30/2019
Operator Name:	Mountain View Los Altos High School District
Operator Address:	1299 Bryant Avenue
Operator City:	Mountain View
Operator State:	California
Operator Zip:	94040

CIWQS:

Name:	LOS ALTOS HIGH SCHOOL
Address:	201 ALMOND AVENUE
City,State,Zip:	LOS ALTOS, CA 94022
Agency:	Mountain View Los Altos High School District
Agency Address:	1299 Bryant Avenue, Mountain View, CA 94040
Place/Project Type:	Construction - Other: School
SIC/NAICS:	Not reported
Region:	2
Program:	CONSTW
Regulatory Measure Status:	Active
Regulatory Measure Type:	Storm water construction
Order Number:	2009-0009-DWQ
WDID:	2 43C388232
NPDES Number:	CAS000002
Adoption Date:	Not reported
Effective Date:	09/30/2019
Termination Date:	Not reported

LOS ALTOS HS (Continued) **1000101636**

Expiration/Review Date:	Not reported
Design Flow:	Not reported
Major/Minor:	Not reported
Complexity:	Not reported
TTWQ:	Not reported
Enforcement Actions within 5 years:	0
Violations within 5 years:	0
Latitude:	37.38681
Longitude:	-122.10877

CERS:

Name:	LOS ALTOS HIGH SCHOOL
Address:	201 ALMOND AV
City,State,Zip:	LOS ALTOS, CA 94022
Site ID:	45044
CERS ID:	10348729
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-23-2019
Citation:	40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.31
Violation Description:	Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water which could threaten human health or the environment.
Violation Notes:	Returned to compliance on 06/04/2019. Robotics lab had various metal (aluminum) cuttings and turnings on the floor. Many aluminum alloys contain hazardous levels of metals. PLEASE ENSURE THAT METAL SCRAPS ARE SWEPT FROM THE FLOOR AND CONTAINERIZED FOR MANAGEMENT AS SCRAP METAL. Behind robotics, observed a containment structure which previously held drums of used oil in which the containment tray had residual used oil, and which was open to the environment and rain.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS

Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Haz Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 05/23/2016. Cal Code Regs, section 66268.7. LDR does not properly reflect the wastes shipped. LDR waste codes did not match waste codes on the manifests.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS

Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	22 CCR 12 66262.40(c) - California Code of Regulations, Title 22,

LOS ALTOS HS (Continued) **1000101636**

Chapter 12, Section(s) 66262.40(c)
Violation Description: Failure to determine if the waste generated is a hazardous waste and to maintain analysis results for three years.
Violation Notes: Returned to compliance on 05/23/2016. 1x15 gallon steel drum marked 80W90 oil along fence in area adjacent to bike storage behind auto tech. Drum is full of unknown contents. Indicated that animal carcasses are being disposed of as biohazardous wastes. PLEASE EXPLAIN HOW THE CARCASSES ARE BIOHAZARDOUS, AND IF NOT, PLEASE MAKE WASTE DETERMINATION ON CARCASSES SINCE THEY ARE FORMALDEHYDE FIXED.
Violation Division: Santa Clara County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 45044
Site Name: LOS ALTOS HIGH SCHOOL
Violation Date: 05-16-2016
Citation: 40 CFR 1 265.35 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.35
Violation Description: Failure to maintain aisle space to allow the unobstructed movement of personnel, fire protection, spill control equipment, and decontamination equipment to any area of facility operation in an emergency, unless it can be demonstrated to the Department that aisle space is not needed for any of these purposes.
Violation Notes: Returned to compliance on 05/23/2016. Eyewash and spill materials were not readily available due to storage of biohazardous bin and chemical cart in the science prep area.
Violation Division: Santa Clara County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 45044
Site Name: LOS ALTOS HIGH SCHOOL
Violation Date: 05-23-2019
Citation: 22 CCR 12 66262.11 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.11
Violation Description: Failure to determine if wastes generated are hazardous waste by using generator knowledge or applying testing method.
Violation Notes: Returned to compliance on 06/04/2019. Site disposes of ethidium bromide gels and media in test tubes contaminated with ethidium bromide as medical waste. PLEASE DEMONSTRATE HOW THE ETHIDIUM BROMIDE MEDIA CONTAINS LESS THAN 0.4% ETHIDIUM BROMIDE BY WEIGHT OR BEGIN MANAGING AS HAZARDOUS WASTE. Site disposes of fetal pigs with preservative as medical (biohaz) waste. Please explain why the specimens either meet the definition of "biohazardous waste" (according to Health and Safety Code 117690) or how they are not hazardous waste and how excess solutions in the shipping bags is managed. IF NEITHER OF THE PREVIOUS CONDITIONS CAN BE MET, BEGIN MANAGING AS HAZARDOUS WASTE. Observed a 3 gallon blue poly carboy in the robotics lab containing a unknown liquid. IDENTIFY THE LIQUID AND MANAGE ACCORDINGLY.
Violation Division: Santa Clara County Environmental Health
Violation Program: HW
Violation Source: CERS

Site ID: 45044
Site Name: LOS ALTOS HIGH SCHOOL
Violation Date: 05-23-2019

LOS ALTOS HS (Continued) **1000101636**

Citation:	HSC 6.5 25200.3.1(b) - California Health and Safety Code, Chapter 6.5, Section(s) 25200.3.1(b)
Violation Description:	Failure of the owner or operator managing laboratory hazardous waste in a laboratory accumulation area to comply with the quantity limitations, management, training, or documentation requirements.
Violation Notes:	Returned to compliance on 06/04/2019. Observed 2 gal carboy of "waste with metals" with start date of 11/1/18, 2 gallon carboy of "waste" with start date of 4/28/09 in chemistry areas.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130
Violation Description:	Failure to properly handle, manage, label, and recycle used oil and fuel filters.
Violation Notes:	Returned to compliance on 05/23/2016. Noted bucket holding filters not marked.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130
Violation Description:	Failure to properly handle, manage, label, and recycle used oil and fuel filters.
Violation Notes:	Returned to compliance on 05/23/2016. Records of disposal of filters not provided at time of inspection.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-23-2019
Citation:	HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Inventory reported does not include approximately 500 cubic feet of Carbon Dioxide (compressed gas, largest 200 cuft, 2 in sciences, 3 small in tractor shed), 80 gal liquid carbon dioxide (liquid, largest 80 gal, pool shed) Additionally, the used oil and coolant in the auto repair can be removed since this activity is no longer done. Line item for "bleach" can be removed, is duplicative of "sodium hypochlorite" entry.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS

LOS ALTOS HS (Continued) **1000101636**

Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Submitted inventory does not properly account for the correct chemical name of "oxidizer". Submittal notes chemical compound as bleach and at 600 gallons. Actual chemical storage is 60 liters of liquid Carbon dioxide. Also noted storage of 16 x 5 gallon containers of latex paint in pool maintenance room that are not disclosed on inventory. Please also amend reporting of LPG from cubic feet to gallons (purchased and stored as a liquid). Noted 63 gallons onsite.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS

Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	40 CFR 1 265.174 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.174
Violation Description:	Failure to inspect hazardous waste storage areas at least weekly.
Violation Notes:	Returned to compliance on 05/23/2016. inspections of storage areas at auto tech not being done with enough detail to prevent violations, s noted by oil in containment under drums and label on filter drum not being accessible for inspection.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS

Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-23-2019
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 06/04/2019. 2 gal poly carboy marked "waste" and missing hazardous properties of waste (chemistry hood). 2 gal carboy of calcium chloride missing properties of waste on label (main science corridor).
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS

Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description:	Failure to complete and electronically submit a site map with all

LOS ALTOS HS (Continued) **1000101636**

	required content.
Violation Notes:	Returned to compliance on 07/25/2017. map submitted does not accurately reflect layout of campus. Building added in 2014 in which hazardous materials are stored was not reflected on map submitted in 2016 CERS submittal.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HMRRP
Violation Source:	CERS
Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Haz Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 05/23/2016. Copies of receipts for pick up of used oil and antifreeze not provided at time of inspection.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-23-2019
Citation:	HSC 6.5 25200.3.1 (c) - California Health and Safety Code, Chapter 6.5, Section(s) 25200.3.1 (c)
Violation Description:	Failure to treat laboratory hazardous waste according to all of the following requirements: 1) treated in containers and follow published procedures, 2) at a location as close as practical, and within 10 days, 3) single batch quantity limit to be 5 gallons or 18 kg, 4) waste from a single procedure or from the same laboratory process, 5) performed by trained personnel, 6) training records are maintained for 3 years, 7) waste and residuals are managed according to applicable requirements, and 8) records are made available for inspection.
Violation Notes:	Returned to compliance on 06/04/2019. Chemistry teacher stated that various acid and base materials were mixed to neutralize them. Neutralization of smaller quantities of acid wastes is held for longer than 10 days after generation, and is not conducted by a person with training records demonstrating that they have awareness of the process. ALL CONDITIONS BELOW MUST BE MET FOR TREATMENT OF WASTE (NEUTRALIZATION OF WASTES < pH OF 2 OR >12.5)
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS
Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130
Violation Description:	Failure to properly handle, manage, label, and recycle used oil and fuel filters.
Violation Notes:	Returned to compliance on 05/23/2016. Mixing cased and uncased filters in same drum, and mixing in oily debris (cardboard) with this waste. Also noted one 5 gallon bucket open with filters resting in it at auto tech.
Violation Division:	Santa Clara County Environmental Health

LOS ALTOS HS (Continued) **1000101636**

Violation Program:	HW
Violation Source:	CERS
Site ID:	45044
Site Name:	LOS ALTOS HIGH SCHOOL
Violation Date:	05-16-2016
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 05/23/2016. Various beakers of waste in chemistry classroom hoods not marked with any information except contents. Various materials removed from service, stored in hood identified as waste storage area not marked. 2x15 gallon photo fix waste containers in dark room not marked with start dates. Container in hood of room 701 for lab wastes marked with old date of 8/20/13. Need to redate upon each subsequent reuse of container.
Violation Division:	Santa Clara County Environmental Health
Violation Program:	HW
Violation Source:	CERS

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-16-2016
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	CERS ID10348729 Last filing: 2/11/16 Inventory substantially matches inventory submitted except as noted above. Have below reportable thresholds of nitrogen, carbon dioxide (compressed gas), fertilizer, gas, diesel (at greater than consumer or lab sizes)
Eval Division:	Santa Clara County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	05-16-2016
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspection is both routine compliance inspection as well as follow up to green business review request. The following areas were visisted/inspected: auto tech, science, photography, art, theater, kitchen, tractor/grounds Noted box of materials in auto tech indicated as having been removed from shelf, needing to be sorted to determine if usable. STRONGLY RECOMMEND SORTING AND STORING AS SOON AS POSSIBLE. Noted various aerosol cans on grounds and in trashcans (removed, see below). STRONGLY RECOMMEND HAVING ONE BUCKET OR BOX DESIGNATED FOR AEROSOL CAN PLACEMENT BY STUDENTS, WITH TEACHER RESPONSIBLE FOR SORTING AND MANAGEMENT FROM THAT POINT FORWARD. DID DISCUSS MANAGEMENT OF AEROSOLS WITH AUTO AND ART TEACHERS-- MUST BE COMPLETELY EMPTY BEFORE RECYCLING OR PUNCTURING. IF NOT, MANAGE AS UNIVERSAL WASTE. Generator copies of manifests are being sent to the State by contractor, noted with check mark on service agreement sheet. OBSERVATION- NOTED ONLY SHIPMENT OF ACID AND [Truncated]
Eval Division:	Santa Clara County Environmental Health
Eval Program:	HW

LOS ALTOS HS (Continued) **1000101636**

Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-23-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: CERS ID 10348729 submittals 4/15&18/2019, 7/117/18, 7/26/17 map reviewed and complete Emergency plan rejected due to use of old format which does not address all required elements Training plan complete Please provide a copy of your employee emergency response/evacuation training log from 2018-2019 school year.
Eval Division: Santa Clara County Environmental Health
Eval Program: HMRRP
Eval Source: CERS

Eval General Type: Compliance Evaluation Inspection
Eval Date: 05-23-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: ID number CAD981693864, active as of date of inspection Inspection took place on 5/22, report delivered electronically on 5/23.
Inspection was jointly conducted for compliance and as check for green business program eligibility. Areas of school inspected included: robotics lab (former auto repair), science common area (shared bio, biochem, chemistry), art, photography, food prep/cafeteria, grounds maintenance shed, theatre and pool room. -- auto repair ceased at this school, replaced by robotics lab. Art is acrylic and water color paint and drawing only; no ceramics or metal working; grounds maintenance equipment is now serviced offsite by third party. Observed various excess chemistries (both developer and "hypo cheaner") which instructor noted is not slated for use and should be disposed of. Also had two bottles (part A and B) or cyanotype solutions that were deemed to be non-usable (contains ammonium di-chromate at 1.25%/12,500 ppm; regulatory level for chrome is 5 [Truncated]
Eval Division: Santa Clara County Environmental Health
Eval Program: HW
Eval Source: CERS

Affiliation:
Affiliation Type Desc: Document Preparer
Entity Name: Irene Aguilar
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Affiliation Type Desc: Operator
Entity Name: Irene Aguilar
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported

LOS ALTOS HS (Continued) **1000101636**

Affiliation Phone:	(650) 940-4666
Affiliation Type Desc:	Environmental Contact
Entity Name:	Irene Aguilar
Entity Title:	Not reported
Affiliation Address:	1299 Bryant Avenue
Affiliation City:	Mountain View
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	94040
Affiliation Phone:	Not reported
Affiliation Type Desc:	CUPA District
Entity Name:	Santa Clara County Environmental Health
Entity Title:	Not reported
Affiliation Address:	1555 Berger Drive, Suite 300
Affiliation City:	San Jose
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95112-2716
Affiliation Phone:	(408) 918-3400
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	1299 BRYANT AV
Affiliation City:	MOUNTAIN VIEW
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	94040
Affiliation Phone:	Not reported
Affiliation Type Desc:	Property Owner
Entity Name:	Mountain View Los Altos High School District
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	United States
Affiliation Zip:	Not reported
Affiliation Phone:	(650) 940-4666
Affiliation Type Desc:	Identification Signer
Entity Name:	Irene Aguilar
Entity Title:	Associate Superintendent Business Services
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported
Affiliation Type Desc:	Legal Owner
Entity Name:	Mountain View-Los Altos Union High School Dist.
Entity Title:	Not reported
Affiliation Address:	1299 Bryant Avenue
Affiliation City:	Mountain View

LOS ALTOS HS (Continued) **1000101636**

Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94040
Affiliation Phone: (650) 940-4666

Affiliation Type Desc: Parent Corporation
Entity Name: LOS ALTOS HIGH SCHOOL
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Name: LOS ALTOS HIGH SCHOOL
Address: 201 ALMOND AVENUE
City,State,Zip: LOS ALTOS, CA 94022
Site ID: 558020
CERS ID: 876115
CERS Description: Construction Storm Water

Affiliation:
Affiliation Type Desc: Owner/Operator
Entity Name: Mountain View Los Altos High School District
Entity Title: Operator
Affiliation Address: 1299 Bryant Avenue
Affiliation City: Mountain View
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94040
Affiliation Phone: Not reported

N83 **TIED HOUSE BREWING SITE** **ENVIROSTOR** **S117038684**
ENE **954 VILLA STREET** **VCP** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94041**
0.815 mi.
4303 ft. **Site 2 of 3 in cluster N**

Relative:
Lower

Actual:
73 ft.

ENVIROSTOR:
Name: TIED HOUSE BREWING SITE
Address: 954 VILLA STREET
City,State,Zip: MOUNTAIN VIEW, CA 94041
Facility ID: 60002038
Status: Active
Status Date: 01/23/2017
Site Code: 202011
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 0.27
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Jayantha Randeni
Supervisor: Cheryl Prowell
Division Branch: Cleanup Berkeley

TIED HOUSE BREWING SITE (Continued) **S117038684**

Assembly: 24
Senate: 13
Special Program: Voluntary Cleanup Program
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.39472
Longitude: -122.0806
APN: NONE SPECIFIED
Past Use: DRY CLEANING
Potential COC: Tetrachloroethylene (PCE Trichloroethylene (TCE
Confirmed COC: Tetrachloroethylene (PCE Trichloroethylene (TCE
Potential Description: IA, OTH, SV
Alias Name: 202011
Alias Type: Project Code (Site Code)
Alias Name: 60002038
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/10/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 03/28/2017
Comments: The Minkoff Group entered into a Voluntary Cleanup Agreement with DTSC to oversee site characterization activities.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 07/25/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 07/25/2014
Comments: Soil vapor and sub-slab PCE concentrations exceed screening levels.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 02/07/2017
Comments: Request for Agency Oversight Application received by DTSC from The Minkoff Group.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 04/21/2017
Comments: The Work Plan proposes soil, groundwater and soil vapor sampling from eight locations.

TIED HOUSE BREWING SITE (Continued) **S117038684**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Fieldwork
Completed Date:	04/28/2017
Comments:	Field work completed according to the DTSC-approved Site Investigation Work Plan.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Site Characterization Report
Completed Date:	03/23/2018
Comments:	The purpose of the Phase II site characterization was to assess halogenated volatile organic compounds previously detected in soil, groundwater, and soil vapor in support of the proposed redevelopment. Sampling results indicated that PCE is the primary constituent of concern detected in soil, groundwater, and soil vapor detected at concentrations exceeding human health risk-based screening levels for a commercial/industrial scenario.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Voluntary Cleanup Agreement Termination Notification
Completed Date:	11/21/2019
Comments:	VCA with Minkoff Group was terminated.

Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

VCP:

Name:	TIED HOUSE BREWING SITE
Address:	954 VILLA STREET
City,State,Zip:	MOUNTAIN VIEW, CA 94041
Facility ID:	60002038
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	0.27
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Jayantha Randeni
Supervisor:	Cheryl Prowell
Division Branch:	Cleanup Berkeley
Site Code:	202011
Assembly:	24
Senate:	13
Special Programs Code:	Voluntary Cleanup Program
Status:	Active
Status Date:	01/23/2017

TIED HOUSE BREWING SITE (Continued) **S117038684**

Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.39472 / -122.0806
APN: NONE SPECIFIED
Past Use: DRY CLEANING
Potential COC: 30022, 30027
Confirmed COC: 30022,30027
Potential Description: IA, OTH, SV
Alias Name: 202011
Alias Type: Project Code (Site Code)
Alias Name: 60002038
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 09/10/2015
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 03/28/2017
Comments: The Minkoff Group entered into a Voluntary Cleanup Agreement with DTSC to oversee site characterization activities.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 07/25/2014
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 07/25/2014
Comments: Soil vapor and sub-slab PCE concentrations exceed screening levels.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 02/07/2017
Comments: Request for Agency Oversight Application received by DTSC from The Minkoff Group.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Workplan
Completed Date: 04/21/2017
Comments: The Work Plan proposes soil, groundwater and soil vapor sampling from eight locations.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fieldwork
Completed Date: 04/28/2017
Comments: Field work completed according to the DTSC-approved Site

TIED HOUSE BREWING SITE (Continued) **S117038684**

Investigation Work Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 03/23/2018
Comments: The purpose of the Phase II site characterization was to assess halogenated volatile organic compounds previously detected in soil, groundwater, and soil vapor in support of the proposed redevelopment. Sampling results indicated that PCE is the primary constituent of concern detected in soil, groundwater, and soil vapor detected at concentrations exceeding human health risk-based screening levels for a commercial/industrial scenario.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement Termination Notification
Completed Date: 11/21/2019
Comments: VCA with Minkoff Group was terminated.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

N84 **EVELYN AVENUE PARKING LOT** **ENVIROSTOR** **S108936078**
ENE **SOUTHEAST CORNER OF EVELYN AVENUE AND FRANKLIN STREET** **VCP** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94039**
0.849 mi.
4482 ft. **Site 3 of 3 in cluster N**

Relative: **Lower**
Actual: **72 ft.**

ENVIROSTOR:
Name: EVELYN AVENUE PARKING LOT
Address: SOUTHEAST CORNER OF EVELYN AVENUE AND FRANKLIN STREET
City,State,Zip: MOUNTAIN VIEW, CA 94039
Facility ID: 60000745
Status: No Further Action
Status Date: 04/08/2009
Site Code: 201769
Site Type: Voluntary Cleanup
Site Type Detailed: Voluntary Cleanup
Acres: 1.03
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Assembly: 24
Senate: 13
Special Program: Voluntary Cleanup Program
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED

EVELYN AVENUE PARKING LOT (Continued) **S108936078**

Funding: Responsible Party
Latitude: 37.39539
Longitude: -122.0803
APN: 158-15-025
Past Use: DRY CLEANING
Potential COC: Tetrachloroethylene (PCE
Confirmed COC: Tetrachloroethylene (PCE
Potential Description: OTH, SV
Alias Name: 158-15-025
Alias Type: APN
Alias Name: 110033616380
Alias Type: EPA (FRS #)
Alias Name: 201769
Alias Type: Project Code (Site Code)
Alias Name: 60000745
Alias Type: Envirostor ID Number

Completed Info:

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Characterization Report
Completed Date: 05/30/2008
Comments: The Request for Oversight Agreement contained the Subsurface and Additional Subsurface Investigation Reports. They are added here.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Risk Assessment Report
Completed Date: 04/08/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 04/08/2009
Comments: DTSC approved No Further Action as long as the Site development conforms with the structural layout as evaluated in the Risk Evaluation Report and in accordance with the City's Downtown Precise Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Consultative Service Agreement
Completed Date: 04/24/2008
Comments: Final signed Consultative Services Agreement dated April 24, 2008

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 12/23/2011
Comments: Memo to DTSC Cost Recovery Unit requesting closeout of site because work has been completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation Workplan
Completed Date: 10/17/2008
Comments: Not reported

EVELYN AVENUE PARKING LOT (Continued) **S108936078**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Risk Assessment Report
Completed Date: 08/18/2010
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

VCP:
Name: EVELYN AVENUE PARKING LOT
Address: SOUTHEAST CORNER OF EVELYN AVENUE AND FRANKLIN STREET
City,State,Zip: MOUNTAIN VIEW, CA 94039
Facility ID: 60000745
Site Type: Voluntary Cleanup
Site Type Detail: Voluntary Cleanup
Site Mgmt. Req.: NONE SPECIFIED
Acres: 1.03
National Priorities List: NO
Cleanup Oversight Agencies: SMBRP
Lead Agency: SMBRP
Lead Agency Description: DTSC - Site Cleanup Program
Project Manager: Not reported
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Site Code: 201769
Assembly: 24
Senate: 13
Special Programs Code: Voluntary Cleanup Program
Status: No Further Action
Status Date: 04/08/2009
Restricted Use: NO
Funding: Responsible Party
Lat/Long: 37.39539 / -122.0803
APN: 158-15-025
Past Use: DRY CLEANING
Potential COC: 30022
Confirmed COC: 30022
Potential Description: OTH, SV
Alias Name: 158-15-025
Alias Type: APN
Alias Name: 110033616380
Alias Type: EPA (FRS #)
Alias Name: 201769
Alias Type: Project Code (Site Code)
Alias Name: 60000745
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE

EVELYN AVENUE PARKING LOT (Continued) **S108936078**

Completed Sub Area Name:	Not reported
Completed Document Type:	Site Characterization Report
Completed Date:	05/30/2008
Comments:	The Request for Oversight Agreement contained the Subsurface and Additional Subsurface Investigation Reports. They are added here.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Risk Assessment Report
Completed Date:	04/08/2009
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	04/08/2009
Comments:	DTSC approved No Further Action as long as the Site development conforms with the structural layout as evaluated in the Risk Evaluation Report and in accordance with the City's Downtown Precise Plan.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Consultative Service Agreement
Completed Date:	04/24/2008
Comments:	Final signed Consultative Services Agreement dated April 24, 2008
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Cost Recovery Closeout Memo
Completed Date:	12/23/2011
Comments:	Memo to DTSC Cost Recovery Unit requesting closeout of site because work has been completed.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Remedial Investigation Workplan
Completed Date:	10/17/2008
Comments:	Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Risk Assessment Report
Completed Date:	08/18/2010
Comments:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

O85 **SYMTRON CORP MOUNTAIN VIEW DIV** **RCRA-SQG** **1000420286**
NNW **2235 MORA DR** **RESPONSE** **CAD000819821**
1/2-1 **MOUNTAIN VIEW, CA 94040** **ENVIROSTOR**
0.949 mi. **FINDS**
5012 ft. **Site 1 of 4 in cluster O** **ECHO**
CERS

Relative:
Lower

Actual:
57 ft.

RCRA-SQG:

Date Form Received by Agency:	1996-09-01 00:00:00.0
Handler Name:	SYMTRON CORP MOUNTAIN VIEW DIV
Handler Address:	2235 MORA DR
Handler City,State,Zip:	MOUNTAIN VIEW, CA 94040
EPA ID:	CAD000819821
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	CA
State District:	2
Mailing Address:	2415 E CHARLSTON RD
Mailing City,State,Zip:	MOUNTAIN VIEW, CA 94043
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	NOT REQUIRED
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline

SYMTRON CORP MOUNTAIN VIEW DIV (Continued) **1000420286**

Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-06-27 03:22:27.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NOT REQUIRED
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SYMTRON CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SYMTRON CORP MOUNTAIN VIEW DIV (Continued) **1000420286**

Historic Generators:

Receive Date:	1996-09-01 00:00:00.0
Handler Name:	SYMTRON CORP MOUNTAIN VIEW DIV
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1980-08-27 00:00:00.0
Handler Name:	SYMTRON CORP MOUNTAIN VIEW DIV
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1992-03-31 00:00:00.0
Handler Name:	SYMTRON CORPORATION
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	334412
NAICS Description:	BARE PRINTED CIRCUIT BOARD MANUFACTURING

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

RESPONSE:

Name:	SYMTRON CORP.
Address:	2235-2245 MORA DR.
City,State,Zip:	MOUNTAIN VIEW, CA 94040

SYMTRON CORP MOUNTAIN VIEW DIV (Continued) **1000420286**

Facility ID:	43360124
Site Type:	State Response
Site Type Detail:	State Response or NPL
Acres:	0.59
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Not reported
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Site Code:	200315
Site Mgmt. Req.:	NONE SPECIFIED
Assembly:	24
Senate:	13
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	06/29/2001
Restricted Use:	NO
Funding:	Responsible Party
Latitude:	37.40244
Longitude:	-122.1008
APN:	147-54-016, 147-54-017, 147-54-018, 147-54-019, 148-33-017
Past Use:	MANUFACTURING - OTHER
Potential COC :	Lead Tetrachloroethylene (PCE Trichloroethylene (TCE
Confirmed COC:	Lead Tetrachloroethylene (PCE Trichloroethylene (TCE
Potential Description:	OTH
Alias Name:	ELEXSYS INTERNATIONAL
Alias Type:	Alternate Name
Alias Name:	SANMINA CORPORATION
Alias Type:	Alternate Name
Alias Name:	SYMTRON CORP.
Alias Type:	Alternate Name
Alias Name:	147-54-016
Alias Type:	APN
Alias Name:	147-54-017
Alias Type:	APN
Alias Name:	147-54-018
Alias Type:	APN
Alias Name:	147-54-019
Alias Type:	APN
Alias Name:	148-33-017
Alias Type:	APN
Alias Name:	CAD000819821
Alias Type:	EPA Identification Number
Alias Name:	110033618912
Alias Type:	EPA (FRS #)
Alias Name:	200315
Alias Type:	Project Code (Site Code)
Alias Name:	43360124
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Remedial Investigation / Feasibility Study
Completed Date:	06/29/2001
Comments:	Completed RIFS. The results did not indicate a groundwater contamination source on the property.

SYMTRON CORP MOUNTAIN VIEW DIV (Continued) **1000420286**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/10/1995
Comments: Completed RA. Approximately 1.5 cubic yards of soil was excavated and disposed off-site. The building was steam cleaned. In addition, 3 cubic yards of ground concrete was disposed off-site as part of the removal of the concrete sump and clarifer.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 11/13/1992
Comments: Approved PEA. Shallow soil samples showed copper as high as 7,900 ppm and lead as high as 2,000 ppm. Other metal contaminants were also found in soil along with tetrachloroethylene as high as 940 ppm, and 1,1,1-TCA as high as 440 ppm. Although Symtron is located in an area known to have have groundwater problems, no groundwater investigation was conducted.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 09/24/1991
Comments: Completed Site Screening. Copper,lead and volatile organics have been detected in the soil. Site referred to DTSC by Mountain View Fire Department. 2227 Mora Drive address housed Symtron's hazardous materials storage area where acids, bases, oxidizers, & flammable liquids, as well as copper animated plates, were kept. 2235 Mora housed offices, photo darkroom, wet and dry quality control labs, and process operations. 2245 Mora operations included copper etching and black oxide operations & clean rooms used for Symtron's dry process. Symtron operated an onsite waste water treatment plant. Treated waste water and effluent went directly to the Mountain View sewer via an inground sump which served as a final clarifier. Closure sampling was conducted in March 1991 and included soil concrete chip, and wipe samples. Copper was detected as high as 7,900 ppm and 1,600 ppm in soil and concrete chip samples respectively. Lead was detected as high as 1,000 ppm in soil. Volatile organic compounds (VOCs) all tested below 1 ppm.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 09/27/2012
Comments: Presents results of soil samples collected from this site, and soil and soil gas results from adjacent sites. This work not conducted under DTSC oversight.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Unilateral Order (I/SE, RAO, CAO, EPA AO)
Completed Date: 01/16/1997
Comments: Issued IS&E Order to Elexsys International which was later acquired by Sanmina Corporation requiring site investigation and if appropriate, site remediation.

SYMTRON CORP MOUNTAIN VIEW DIV (Continued) **1000420286**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 12/02/2011
Comments: Close cost recovery account.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Name: SYMTRON CORP.
Address: 2235-2245 MORA DR.
City,State,Zip: MOUNTAIN VIEW, CA 94040
Facility ID: 43360124
Status: No Further Action
Status Date: 06/29/2001
Site Code: 200315
Site Type: State Response
Site Type Detailed: State Response or NPL
Acres: 0.59
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Assembly: 24
Senate: 13
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.40244
Longitude: -122.1008
APN: 147-54-016, 147-54-017, 147-54-018, 147-54-019, 148-33-017
Past Use: MANUFACTURING - OTHER
Potential COC: Lead Tetrachloroethylene (PCE Trichloroethylene (TCE
Confirmed COC: Lead Tetrachloroethylene (PCE Trichloroethylene (TCE
Potential Description: OTH
Alias Name: ELEXSYS INTERNATIONAL
Alias Type: Alternate Name
Alias Name: SANMINA CORPORATION
Alias Type: Alternate Name
Alias Name: SYMTRON CORP.
Alias Type: Alternate Name
Alias Name: 147-54-016
Alias Type: APN
Alias Name: 147-54-017
Alias Type: APN
Alias Name: 147-54-018

SYMTRON CORP MOUNTAIN VIEW DIV (Continued) **1000420286**

Alias Type: APN
Alias Name: 147-54-019
Alias Type: APN
Alias Name: 148-33-017
Alias Type: APN
Alias Name: CAD000819821
Alias Type: EPA Identification Number
Alias Name: 110033618912
Alias Type: EPA (FRS #)
Alias Name: 200315
Alias Type: Project Code (Site Code)
Alias Name: 43360124
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Remedial Investigation / Feasibility Study
Completed Date: 06/29/2001
Comments: Completed RIFS. The results did not indicate a groundwater contamination source on the property.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/10/1995
Comments: Completed RA. Approximately 1.5 cubic yards of soil was excavated and disposed off-site. The building was steam cleaned. In addition, 3 cubic yards of ground concrete was disposed off-site as part of the removal of the concrete sump and clarifer.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 11/13/1992
Comments: Approved PEA. Shallow soil samples showed copper as high as 7,900 ppm and lead as high as 2,000 ppm. Other metal contaminants were also found in soil along with tetrachloroethylene as high as 940 ppm, and 1,1,1-TCA as high as 440 ppm. Although Symtron is located in an area known to have have groundwater problems, no groundwater investigation was conducted.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Site Screening
Completed Date: 09/24/1991
Comments: Completed Site Screening. Copper,lead and volatile organics have been detected in the soil. Site referred to DTSC by Mountain View Fire Department. 2227 Mora Drive address housed Symtron's hazardous materials storage area where acids, bases, oxidizers, & flammable liquids, as well as copper animated plates, were kept. 2235 Mora housed offices, photo darkroom, wet and dry quality control labs, and process operations. 2245 Mora operations included copper etching and black oxide operations & clean rooms used for Symtron's dry process. Symtron operated an onsite waste water treatment plant. Treated waste water and effluent went directly to the Mountain View sewer via an inground sump which served as a final clarifier. Closure sampling was conducted in March 1991 and included soil concrete chip, and wipe

SYMTRON CORP MOUNTAIN VIEW DIV (Continued) **1000420286**

samples. Copper was detected as high as 7,900 ppm and 1,600 ppm in soil and concrete chip samples respectively. Lead was detected as high as 1,000 ppm in soil. Volatile organic compounds (VOCs) all tested below 1 ppm.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Other Report
Completed Date: 09/27/2012
Comments: Presents results of soil samples collected from this site, and soil and soil gas results from adjacent sites. This work not conducted under DTSC oversight.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Unilateral Order (I/SE, RAO, CAO, EPA AO)
Completed Date: 01/16/1997
Comments: Issued IS&E Order to Elexsys International which was later acquired by Sanmina Corporation requiring site investigation and if appropriate, site remediation.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 12/02/2011
Comments: Close cost recovery account.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

FINDS:
Registry ID: 110002146375

Click Here:

Environmental Interest/Information System:
California Department of Toxic Substances Control EnviroStor System (DTSC-EnviroStor) is an online search and Geographic Information System (GIS) tool for identifying sites that have known contamination or sites for which there may be reasons to investigate further. The EnviroStor database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites.
US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

SYMTRON CORP MOUNTAIN VIEW DIV (Continued) **1000420286**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000420286
Registry ID:	110002146375
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002146375
Name:	SYMTRON CORP
Address:	2235 MORA DR.
City,State,Zip:	MOUNTAIN VIEW, CA 94040

CERS:

Name:	SYMTRON CORP.
Address:	2235-2245 MORA DR.
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Site ID:	343695
CERS ID:	43360124
CERS Description:	State Response

Affiliation:

Affiliation Type Desc:	Supervisor
Entity Name:	MARK PIROS
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	Not reported

O86 **MORA DRIVE** **ENVIROSTOR** **S120714345**
NNW **2221-2291 MORA DRIVE** **VCP** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94040** **DEED**
0.973 mi.
5135 ft. **Site 2 of 4 in cluster O**

Relative:
Lower

Actual:
54 ft.

ENVIROSTOR:

Name:	MORA DRIVE
Address:	2221-2291 MORA DRIVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Facility ID:	60002502
Status:	Active
Status Date:	04/27/2017
Site Code:	202139
Site Type:	Voluntary Cleanup
Site Type Detailed:	Voluntary Cleanup
Acres:	4
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Henry Wong
Supervisor:	John Karachewski

MORA DRIVE (Continued) **S120714345**

Division Branch: Cleanup Berkeley
Assembly: , 24
Senate: , 13
Special Program: Voluntary Cleanup Program
Restricted Use: YES
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.40279
Longitude: -122.1020
APN: 14833009, 14833010, 14833013, 14833014, 14833015, 14833016, 14833017, 14833018, 14833019
Past Use: MANUFACTURING - ELECTRONIC
Potential COC: Tetrachloroethylene (PCE Trichloroethylene (TCE
Confirmed COC: Tetrachloroethylene (PCE Trichloroethylene (TCE
Potential Description: SV
Alias Name: 14833009
Alias Type: APN
Alias Name: 14833010
Alias Type: APN
Alias Name: 14833013
Alias Type: APN
Alias Name: 14833014
Alias Type: APN
Alias Name: 14833015
Alias Type: APN
Alias Name: 14833016
Alias Type: APN
Alias Name: 14833017
Alias Type: APN
Alias Name: 14833018
Alias Type: APN
Alias Name: 14833019
Alias Type: APN
Alias Name: 202139
Alias Type: Project Code (Site Code)
Alias Name: 60002502
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 04/27/2017
Comments: Application for a Voluntary Cleanup Agreement requesting DTSC to provide review and approval of a Site Management Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 05/19/2017
Comments: The Site Management Plan (SMP) establishes general protocols for handling soil, soil vapor, and groundwater during utility line removal, soil excavation, and future construction at the Mora Drive site. The SMP includes the Health and Safety Plan as Appendix A and a separate SMP for the future city park as Appendix B.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

MORA DRIVE (Continued) **S120714345**

Completed Document Type: Voluntary Cleanup Agreement Termination Notification
Completed Date: 09/19/2017
Comments: The Voluntary Cleanup Agreement s (VCA) scope of work specifies that DTSC review and provide comments on the Site Management Plan. Since DTSC completed the Site Management Plan review process, the VCA s scope of work is fulfilled. DTSC notified Lennar that the VCA will be terminated on October 19, 2017.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 07/03/2019
Comments: Lennar had prepared the Vapor Intrusion Mitigation Plan (VIMP) dated May 28, 2017 and DTSC approved such plan on May 31, 2017. The 2019 VIMP updates certain design elements and supersedes the 2017 VIMP. The VIMP describes the design and installation of a vapor intrusion mitigation system beneath every new building within the 5.2-acre Mora Drive project area.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 06/28/2019
Comments: DTSC approved a Removal Action Workplan (RAW) for the site on June 8, 2019. The RAW requires (a) installation of vapor intrusion mitigation systems (VIMS) beneath all new building foundations and (b) execution of a land use covenant to restrict extraction of groundwater or installing of wells without DTSC s approval and construction of any building without installation of the DTSC-approved VIMS. In accordance with CEQA, DTSC approved the Notice of Determination in support of DTSC s discretionary decision on the RAW.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 05/10/2019
Comments: DTSC mailed the Community Update on 5/10/2019 to approximately 550 addresses on the project's mailing list announcing the 30-day public comment period for the Removal Action Workplan to begin on 5/14/2019.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 05/13/2019
Comments: DTSC published a Public Notice on the 5/13/2019 printed version of the Mercury News announcing that the 30-day public comment period for the Removal Action Workplan will begin on 5/14/2019.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan
Completed Date: 07/03/2019
Comments: The Operation and Maintenance Plan outlines the inspection, maintenance, and monitoring program for maintaining the proper function of the vapor intrusion mitigation systems for buildings within the 4.5-acre residential area currently owned by Lennar.

MORA DRIVE (Continued) **S120714345**

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	09/24/2019
Comments:	DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 1 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for Building 1 consistent with the Operation and Maintenance Plan.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Phase I Environmental Site Assessment, September 17, 2012
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Preliminary Data Gap Evaluation, September 27, 2012
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Indoor Air Investigation Report, Towne Court Property, September 17, 2013
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Phase I Environmental Site Assessment, October 24, 2014
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Phase II Subsurface Investigation Report and Proposed Remedial Plan, September 1, 2015
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Groundwater Wells Destruction Reports, October 16, 2015
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Groundwater and Soil Vapor Wells Destruction Reports, November 5, 2015 Not reported
Completed Area Name:	PROJECT WIDE

MORA DRIVE (Continued) **S120714345**

Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/30/2018
Comments: Post Demolition Soil Gas Investigation Report and Recommendations for Future Soil Excavation Activities, October 13, 2016

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/30/2018
Comments: Soil Gas Sampling, April 27, 2017

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/30/2018
Comments: June 2017 Soil Excavation Summary, Site status Update and Anticipated Future Activities, September 12, 2017

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 02/27/2020
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 11 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 05/06/2019
Comments: The Community Profile provides the public with a description of the Site and the community in which it is located, and helps DTSC determine potential community interest in the cleanup, and recommends future public participation activities for the cleanup. In addition, the Community Profile also describes community demographics and land uses in areas surrounding the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 10/15/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system (SSVS) at Building 5 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for Building 5 consistent with the Operation and Maintenance Plan (O&M Plan), and (c) had converted the passive SSVS to active sub-slab depressurization system for Building 5 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

MORA DRIVE (Continued) **S120714345**

Completed Document Type: Removal Action Completion Report
Completed Date: 11/13/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing passive sub-slab venting systems (SSVS) at Buildings 3, 4, and 6 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan (O&M Plan), and (c) had converted the passive SSVS to active sub-slab depressurization systems for Buildings 3, 4, and 6 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 11/21/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting systems at Buildings 19, 20, and 21 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 09/19/2019
Comments: Previously, Lennar had prepared two Vapor Intrusion Mitigation Plan (VIMP) versions dated May 28, 2017 and June 28, 2019; and DTSC approved these plans on May 31, 2017 and July 3, 2019, respectively. The September 18, 2019 VIMP updates certain design elements and supersedes the earlier VIMP versions. The VIMP describes the design and installation of a vapor intrusion mitigation system beneath every new building within the 5.2-acre Mora Drive project area.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan Amendment
Completed Date: 09/19/2019
Comments: Previously, Lennar had prepared the Operation and Maintenance Plan (O&M Plan) dated June 28, 2019; and DTSC approved such plan on July 3, 2019. The September 18, 2019 O&M Plan updates certain design elements and supersedes the previous O&M Plan. The O&M Plan outlines the inspection, maintenance, and monitoring program for maintaining the proper function of the vapor intrusion mitigation systems for buildings within the 4.5-acre residential area currently owned by Lennar.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 12/17/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing passive sub-slab venting system (SSVS) at Buildings 2, 7, 24, and 25 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air,

MORA DRIVE (Continued) **S120714345**

and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan (O&M Plan), and (c) had converted the passive SSVS to active sub-slab depressurization system for Buildings 2, 7, 24, and 25 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/07/2020
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 9 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject building consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/16/2020
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Buildings 10, 17, and 18 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/16/2020
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Buildings 16 and 22 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 05/19/2017
Comments: The Voluntary Cleanup Agreement establishes DTSC’s role and the project proponent’s responsibility in the oversight activity identified in the scope of work, which includes the review of a site management plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 08/02/2019
Comments: DTSC executed and recorded the Land Use Covenant and Agreement, Environmental Restrictions (LUC), Santa Clara County Series Number 24246045, for the Mora Drive project, also known as the Estancia residential development, comprising of approximately 4.53 acres. In general, the LUC prohibits Building any structures intended for human

MORA DRIVE (Continued) **S120714345**

occupancy without an engineered vapor intrusion mitigation system approved by DTSC; Construction of any groundwater well without prior DTSC written approval; Extraction, utilization, or consumption of groundwater without prior DTSC written approval; Conducting activity that may alter, interfere with, or otherwise affect the integrity or effectiveness of, or the access to, the groundwater monitoring wells without prior DTSC written approval; Conducting activity that may alter, interfere with, or otherwise affect the integrity or effectiveness of, or the access to, any vapor intrusion mitigation systems as it pertains to each building on the property without prior DTSC written approval; and Conducting any sub-slab construction work or modification of vapor barriers and sub-slab venting systems associated with vapor intrusion mitigation systems installed at the property without prior DTSC written approval.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 06/19/2018
Comments: DTSC and Lennar executed the Voluntary Cleanup Agreement, Docket No. HSA-FY17/18-136, for overseeing activities performed at the project site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Responsible Agency Review
Completed Date: 06/28/2019
Comments: DTSC approved a Removal Action Workplan (RAW) for the site on June 8, 2019. The RAW requires (a) installation of vapor intrusion mitigation systems (VIMS) beneath all new building foundations and (b) execution of a land use covenant to restrict extraction of groundwater or installation of wells without DTSC s approval and construction of any building without installation of the DTSC-approved VIMS. In accordance with CEQA, DTSC approved the Notice of Determination in support of DTSC s discretionary decision on the RAW.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 09/24/2019
Comments: DTSC issued the Removal Action Certification for Building 1 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 1 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for Building 1 consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operation & Maintenance Order/Agreement
Completed Date: 08/02/2019
Comments: DTSC executed an Operation and Maintenance Agreement with Lennar for (a) implementation of the DTSC-approved Vapor Intrusion Mitigation Plan dated 6/28/19, (b) operation and maintenance of the installed vapor intrusion mitigation system as specified in the DTSC-approved

MORA DRIVE (Continued) **S120714345**

Operation and Maintenance Plan dated 6/28/19, and (c) reimbursement of DTSC oversight costs.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 07/03/2019
Comments: On May 14, 2019, DTSC started the 30‐day public comment period requesting comments on the draft RAW. During the public comment period DTSC received comments via emails and a comment letter. DTSC prepared the Responsiveness Summary responding to public comments.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 10/22/2019
Comments: The cost estimate projects hours to be incurred (by staff classification) for planned oversight activities in fiscal year 2019/2020, which starts July 1, 2019 and ends June 30, 2020, and identifies the personnel labor rates.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Pre-HARP Form
Completed Date: 06/23/2020
Comments: The HARP is for site visit on 6/23/2020.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 11/13/2019
Comments: DTSC issued the Removal Action Certification for Buildings 3, 4, and 6 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting systems (SSVS) at Buildings 3, 4, and 6 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan (O&M Plan), (c) had converted the passive SSVS to active sub-slab depressurization systems for Buildings 3, 4, and 6 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan, and (d) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/07/2020
Comments: DTSC issued the Removal Action Certification for Building 9 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 9 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject building consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE

MORA DRIVE (Continued) **S120714345**

Completed Sub Area Name: Not reported
Completed Document Type: Post HARP Form
Completed Date: 06/23/2020
Comments: The Post HARP is for the 6/23/2020 site visit.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 04/30/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 10/15/2019
Comments: DTSC issued the Removal Action Certification for Building 5 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system (SSVS) at Building 5 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for Building 5 consistent with the Operation and Maintenance Plan (O&M Plan), (c) had converted the passive SSVS to active sub-slab depressurization system for Building 5 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan, and (d) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2020
Comments: The cost estimate projects hours to be incurred (by staff classification) for planned oversight activities in fiscal year 2020/2021, which started July 1, 2020 and ends June 30, 2021, and identifies the personnel labor rates.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/16/2020
Comments: DTSC issued the Removal Action Certification for Buildings 10, 17, and 18 attesting that Lennar (a) had implemented the removal action by installing passive sub-slab venting systems at Buildings 10, 17, and 18 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/16/2020
Comments: DTSC issued the Removal Action Certification for Buildings 16 and 22 attesting that Lennar (a) had implemented the removal action by installing passive sub-slab venting systems at Buildings 16 and 22 in accordance with the Removal Action Workplan and Vapor Intrusion

MORA DRIVE (Continued) **S120714345**

Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 02/27/2020
Comments: DTSC issued the Removal Action Certification for Building 11 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 11 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject building consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 12/17/2019
Comments: DTSC issued the Removal Action Certification for Buildings 2, 7, 24, and 25 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system (SSVS) at Buildings 2, 7, 24, and 25 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan (O&M Plan), (c) had converted the passive SSVS to active sub-slab depressurization system for Buildings 2, 7, 24, and 25 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan, and (d) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 07/03/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 11/21/2019
Comments: DTSC issued the Removal Action Certification for Buildings 19, 20, and 21 attesting that Lennar (a) had implemented the removal action by installing passive sub-slab venting systems at Buildings 19, 20, and 21 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports

MORA DRIVE (Continued) **S120714345**

Future Due Date:	2024
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	Removal Action Completion Report
Future Due Date:	2021
Future Area Name:	PROJECT WIDE
Future Sub Area Name:	Not reported
Future Document Type:	Certification
Future Due Date:	2021
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

VCP:

Name:	MORA DRIVE
Address:	2221-2291 MORA DRIVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Facility ID:	60002502
Site Type:	Voluntary Cleanup
Site Type Detail:	Voluntary Cleanup
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	4
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Henry Wong
Supervisor:	John Karachewski
Division Branch:	Cleanup Berkeley
Site Code:	202139
Assembly:	, 24
Senate:	, 13
Special Programs Code:	Voluntary Cleanup Program
Status:	Active
Status Date:	04/27/2017
Restricted Use:	YES
Funding:	Responsible Party
Lat/Long:	37.40279 / -122.1020
APN:	14833009, 14833010, 14833013, 14833014, 14833015, 14833016, 14833017, 14833018, 14833019
Past Use:	MANUFACTURING - ELECTRONIC
Potential COC:	30022, 30027
Confirmed COC:	30022,30027
Potential Description:	SV
Alias Name:	14833009
Alias Type:	APN
Alias Name:	14833010
Alias Type:	APN
Alias Name:	14833013
Alias Type:	APN
Alias Name:	14833014
Alias Type:	APN
Alias Name:	14833015
Alias Type:	APN
Alias Name:	14833016

MORA DRIVE (Continued) **S120714345**

Alias Type: APN
Alias Name: 14833017
Alias Type: APN
Alias Name: 14833018
Alias Type: APN
Alias Name: 14833019
Alias Type: APN
Alias Name: 202139
Alias Type: Project Code (Site Code)
Alias Name: 60002502
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Application
Completed Date: 04/27/2017
Comments: Application for a Voluntary Cleanup Agreement requesting DTSC to provide review and approval of a Site Management Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Soils Management Plan
Completed Date: 05/19/2017
Comments: The Site Management Plan (SMP) establishes general protocols for handling soil, soil vapor, and groundwater during utility line removal, soil excavation, and future construction at the Mora Drive site. The SMP includes the Health and Safety Plan as Appendix A and a separate SMP for the future city park as Appendix B.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Voluntary Cleanup Agreement Termination Notification
Completed Date: 09/19/2017
Comments: The Voluntary Cleanup Agreement s (VCA) scope of work specifies that DTSC review and provide comments on the Site Management Plan. Since DTSC completed the Site Management Plan review process, the VCA s scope of work is fulfilled. DTSC notified Lennar that the VCA will be terminated on October 19, 2017.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Workplan
Completed Date: 07/03/2019
Comments: Lennar had prepared the Vapor Intrusion Mitigation Plan (VIMP) dated May 28, 2017 and DTSC approved such plan on May 31, 2017. The 2019 VIMP updates certain design elements and supersedes the 2017 VIMP. The VIMP describes the design and installation of a vapor intrusion mitigation system beneath every new building within the 5.2-acre Mora Drive project area.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Workplan
Completed Date: 06/28/2019
Comments: DTSC approved a Removal Action Workplan (RAW) for the site on June 8, 2019. The RAW requires (a) installation of vapor intrusion mitigation systems (VIMS) beneath all new building foundations and (b) execution

MORA DRIVE (Continued) **S120714345**

of a land use covenant to restrict extraction of groundwater or installing of wells without DTSC s approval and construction of any building without installation of the DTSC-approved VIMS. In accordance with CEQA, DTSC approved the Notice of Determination in support of DTSC s discretionary decision on the RAW.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Fact Sheets
Completed Date: 05/10/2019
Comments: DTSC mailed the Community Update on 5/10/2019 to approximately 550 addresses on the project's mailing list announcing the 30-day public comment period for the Removal Action Workplan to begin on 5/14/2019.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Public Notice
Completed Date: 05/13/2019
Comments: DTSC published a Public Notice on the 5/13/2019 printed version of the Mercury News announcing that the 30-day public comment period for the Removal Action Workplan will begin on 5/14/2019.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan
Completed Date: 07/03/2019
Comments: The Operation and Maintenance Plan outlines the inspection, maintenance, and monitoring program for maintaining the proper function of the vapor intrusion mitigation systems for buildings within the 4.5-acre residential area currently owned by Lennar.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 09/24/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 1 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for Building 1 consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/30/2018
Comments: Phase I Environmental Site Assessment, September 17, 2012

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report
Completed Date: 04/30/2018
Comments: Preliminary Data Gap Evaluation, September 27, 2012

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Technical Report

MORA DRIVE (Continued) **S120714345**

Completed Date:	04/30/2018
Comments:	Indoor Air Investigation Report, Towne Court Property, September 17, 2013
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Phase I Environmental Site Assessment, October 24, 2014
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Phase II Subsurface Investigation Report and Proposed Remedial Plan, September 1, 2015
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Groundwater Wells Destruction Reports, October 16, 2015
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Groundwater and Soil Vapor Wells Destruction Reports, November 5, 2015 Not reported
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Post Demolition Soil Gas Investigation Report and Recommendations for Future Soil Excavation Activities, October 13, 2016
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	Soil Gas Sampling, April 27, 2017
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Technical Report
Completed Date:	04/30/2018
Comments:	June 2017 Soil Excavation Summary, Site status Update and Anticipated Future Activities, September 12, 2017
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	02/27/2020
Comments:	DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 11 in accordance with the Removal Action Workplan and Vapor Intrusion

MORA DRIVE (Continued) **S120714345**

Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Community Profile
Completed Date: 05/06/2019
Comments: The Community Profile provides the public with a description of the Site and the community in which it is located, and helps DTSC determine potential community interest in the cleanup, and recommends future public participation activities for the cleanup. In addition, the Community Profile also describes community demographics and land uses in areas surrounding the Site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 10/15/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system (SSVS) at Building 5 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for Building 5 consistent with the Operation and Maintenance Plan (O&M Plan), and (c) had converted the passive SSVS to active sub-slab depressurization system for Building 5 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 11/13/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing passive sub-slab venting systems (SSVS) at Buildings 3, 4, and 6 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan (O&M Plan), and (c) had converted the passive SSVS to active sub-slab depressurization systems for Buildings 3, 4, and 6 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 11/21/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting systems at Buildings 19, 20, and 21 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported

MORA DRIVE (Continued) **S120714345**

Completed Document Type: Technical Workplan
Completed Date: 09/19/2019
Comments: Previously, Lennar had prepared two Vapor Intrusion Mitigation Plan (VIMP) versions dated May 28, 2017 and June 28, 2019; and DTSC approved these plans on May 31, 2017 and July 3, 2019, respectively. The September 18, 2019 VIMP updates certain design elements and supersedes the earlier VIMP versions. The VIMP describes the design and installation of a vapor intrusion mitigation system beneath every new building within the 5.2-acre Mora Drive project area.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Operations and Maintenance Plan Amendment
Completed Date: 09/19/2019
Comments: Previously, Lennar had prepared the Operation and Maintenance Plan (O&M Plan) dated June 28, 2019; and DTSC approved such plan on July 3, 2019. The September 18, 2019 O&M Plan updates certain design elements and supersedes the previous O&M Plan. The O&M Plan outlines the inspection, maintenance, and monitoring program for maintaining the proper function of the vapor intrusion mitigation systems for buildings within the 4.5-acre residential area currently owned by Lennar.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 12/17/2019
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing passive sub-slab venting system (SSVS) at Buildings 2, 7, 24, and 25 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan (O&M Plan), and (c) had converted the passive SSVS to active sub-slab depressurization system for Buildings 2, 7, 24, and 25 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/07/2020
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 9 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject building consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/16/2020
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Buildings 10, 17, and 18 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent

MORA DRIVE (Continued) **S120714345**

with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Removal Action Completion Report
Completed Date: 01/16/2020
Comments: DTSC concluded that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Buildings 16 and 22 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan and (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 05/19/2017
Comments: The Voluntary Cleanup Agreement establishes DTSC's role and the project proponent's responsibility in the oversight activity identified in the scope of work, which includes the review of a site management plan.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Land Use Restriction
Completed Date: 08/02/2019
Comments: DTSC executed and recorded the Land Use Covenant and Agreement, Environmental Restrictions (LUC), Santa Clara County Series Number 24246045, for the Mora Drive project, also known as the Estancia residential development, comprising of approximately 4.53 acres. In general, the LUC prohibits Building any structures intended for human occupancy without an engineered vapor intrusion mitigation system approved by DTSC; Construction of any groundwater well without prior DTSC written approval; Extraction, utilization, or consumption of groundwater without prior DTSC written approval; Conducting activity that may alter, interfere with, or otherwise affect the integrity or effectiveness of, or the access to, the groundwater monitoring wells without prior DTSC written approval; Conducting activity that may alter, interfere with, or otherwise affect the integrity or effectiveness of, or the access to, any vapor intrusion mitigation systems as it pertains to each building on the property without prior DTSC written approval; and Conducting any sub-slab construction work or modification of vapor barriers and sub-slab venting systems associated with vapor intrusion mitigation systems installed at the property without prior DTSC written approval.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Standard Voluntary Agreement
Completed Date: 06/19/2018
Comments: DTSC and Lennar executed the Voluntary Cleanup Agreement, Docket No. HSA-FY17/18-136, for overseeing activities performed at the project site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: CEQA - Responsible Agency Review

MORA DRIVE (Continued) **S120714345**

Completed Date:	06/28/2019
Comments:	DTSC approved a Removal Action Workplan (RAW) for the site on June 8, 2019. The RAW requires (a) installation of vapor intrusion mitigation systems (VIMS) beneath all new building foundations and (b) execution of a land use covenant to restrict extraction of groundwater or installation of wells without DTSC s approval and construction of any building without installation of the DTSC-approved VIMS. In accordance with CEQA, DTSC approved the Notice of Determination in support of DTSC s discretionary decision on the RAW.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Certification
Completed Date:	09/24/2019
Comments:	DTSC issued the Removal Action Certification for Building 1 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 1 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for Building 1 consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Operation & Maintenance Order/Agreement
Completed Date:	08/02/2019
Comments:	DTSC executed an Operation and Maintenance Agreement with Lennar for (a) implementation of the DTSC-approved Vapor Intrusion Mitigation Plan dated 6/28/19, (b) operation and maintenance of the installed vapor intrusion mitigation system as specified in the DTSC-approved Operation and Maintenance Plan dated 6/28/19, and (c) reimbursement of DTSC oversight costs.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Correspondence
Completed Date:	07/03/2019
Comments:	On May 14, 2019, DTSC started the 30‐day public comment period requesting comments on the draft RAW. During the public comment period DTSC received comments via emails and a comment letter. DTSC prepared the Responsiveness Summary responding to public comments.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Annual Oversight Cost Estimate
Completed Date:	10/22/2019
Comments:	The cost estimate projects hours to be incurred (by staff classification) for planned oversight activities in fiscal year 2019/2020, which starts July 1, 2019 and ends June 30, 2020, and identifies the personnel labor rates.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Pre-HARP Form
Completed Date:	06/23/2020
Comments:	The HARP is for site visit on 6/23/2020.

MORA DRIVE (Continued) **S120714345**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 11/13/2019
Comments: DTSC issued the Removal Action Certification for Buildings 3, 4, and 6 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting systems (SSVS) at Buildings 3, 4, and 6 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan (O&M Plan), (c) had converted the passive SSVS to active sub-slab depressurization systems for Buildings 3, 4, and 6 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan, and (d) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/07/2020
Comments: DTSC issued the Removal Action Certification for Building 9 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 9 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject building consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Post HARP Form
Completed Date: 06/23/2020
Comments: The Post HARP is for the 6/23/2020 site visit.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 04/30/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 10/15/2019
Comments: DTSC issued the Removal Action Certification for Building 5 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system (SSVS) at Building 5 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for Building 5 consistent with the Operation and Maintenance Plan (O&M Plan), (c) had converted the passive SSVS to active sub-slab depressurization system for Building 5 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan, and (d) had implemented the required institutional control remedy for the site.

MORA DRIVE (Continued) **S120714345**

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Annual Oversight Cost Estimate
Completed Date: 09/30/2020
Comments: The cost estimate projects hours to be incurred (by staff classification) for planned oversight activities in fiscal year 2020/2021, which started July 1, 2020 and ends June 30, 2021, and identifies the personnel labor rates.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/16/2020
Comments: DTSC issued the Removal Action Certification for Buildings 10, 17, and 18 attesting that Lennar (a) had implemented the removal action by installing passive sub-slab venting systems at Buildings 10, 17, and 18 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 01/16/2020
Comments: DTSC issued the Removal Action Certification for Buildings 16 and 22 attesting that Lennar (a) had implemented the removal action by installing passive sub-slab venting systems at Buildings 16 and 22 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 02/27/2020
Comments: DTSC issued the Removal Action Certification for Building 11 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system at Building 11 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject building consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 12/17/2019
Comments: DTSC issued the Removal Action Certification for Buildings 2, 7, 24, and 25 attesting that Lennar (a) had implemented the removal action by installing a passive sub-slab venting system (SSVS) at Buildings 2, 7, 24, and 25 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air,

MORA DRIVE (Continued) **S120714345**

indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan (O&M Plan), (c) had converted the passive SSVS to active sub-slab depressurization system for Buildings 2, 7, 24, and 25 pursuant to the Bay Area Air Quality Management District s Temporary Permit to Operate and O&M Plan, and (d) had implemented the required institutional control remedy for the site.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Correspondence
Completed Date: 07/03/2019
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Certification
Completed Date: 11/21/2019
Comments: DTSC issued the Removal Action Certification for Buildings 19, 20, and 21 attesting that Lennar (a) had implemented the removal action by installing passive sub-slab venting systems at Buildings 19, 20, and 21 in accordance with the Removal Action Workplan and Vapor Intrusion Mitigation Plan, (b) had performed ambient air, indoor air, and sub-slab gas sampling events for the subject buildings consistent with the Operation and Maintenance Plan, and (c) had implemented the required institutional control remedy for the site.

Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: 5 Year Review Reports
Future Due Date: 2024
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Removal Action Completion Report
Future Due Date: 2021
Future Area Name: PROJECT WIDE
Future Sub Area Name: Not reported
Future Document Type: Certification
Future Due Date: 2021
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

DEED:
Name: MORA DRIVE
Address: 2221-2291 MORA DRIVE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Envirostor ID: 60002502
Area: PROJECT WIDE
Sub Area: Not reported
Site Type: VOLUNTARY CLEANUP
Status: ACTIVE
Agency: Not reported
Covenant Uploaded: Not reported
Deed Date(s): Not reported

MORA DRIVE (Continued) **S120714345**

File Name: Envirostor Land Use Restrictions

87
North
1/2-1
0.978 mi.
5164 ft.

Relative:
Lower

Actual:
53 ft.

SHELL SERVICE STATION
110 N RENGSTORFF
MOUNTAIN VIEW, CA 94040

RCRA-SQG **1000288537**
LUST **CAD980675961**
HIST LUST
SWEEPS UST
HIST UST
CA FID UST
Cortese
CUPA Listings
HIST CORTESE
Notify 65
CERS

RCRA-SQG:

Date Form Received by Agency:		2001-08-15 00:00:00.0
Handler Name:	SHELL SERVICE STATION	
Handler Address:		110 N RENGSTORFF
Handler City,State,Zip:		MOUNTAIN VIEW, CA 94040
EPA ID:		CAD980675961
Contact Name:		SONDRA BIENVENU
Contact Address:		P O BOX 2648
Contact City,State,Zip:		HOUTON, TX 77252-2648
Contact Telephone:		713-241-5036
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		P O BOX 2648
Mailing City,State,Zip:		HOUTON, TX 77252-2648
Owner Name:		EQUILON ENTERPRISES L L C
Owner Type:		Private
Operator Name:		Not reported
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported

SHELL SERVICE STATION (Continued) **1000288537**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2002-10-07 16:37:42.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	EQUILON ENTERPRISES L L C
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	P O BOX 2648
Owner/Operator City,State,Zip:	HOUTON, TX 77252-2648
Owner/Operator Telephone:	713-241-5036
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

SHELL SERVICE STATION (Continued) **1000288537**

Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2001-08-15 00:00:00.0
Handler Name: SHELL SERVICE STATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LUST REG 2:
Region: 2
Facility Id: Not reported
Facility Status: Pollution Characterization
Case Number: 06S2W17R01f
How Discovered: Not reported
Leak Cause: Not reported
Leak Source: Not reported
Date Leak Confirmed: Not reported
Oversight Program: LUST
Prelim. Site Assesment Wokplan Submitted: Not reported
Preliminary Site Assesment Began: 1/14/1983
Pollution Characterization Began: 11/10/1988
Pollution Remediation Plan Submitted: Not reported
Date Remediation Action Underway: Not reported
Date Post Remedial Action Monitoring Began: Not reported

LUST SANTA CLARA:
Name: SHELL
Address: 110 RENGSTORFF AVE
City,State,Zip: MOUNTAIN VIEW, CA
Region: SANTA CLARA
SCVWD ID: 06S2W17R01F
Date Closed: Not reported
EDR Link ID: 06S2W17R01F

LUST:
Name: SHELL - 110 N RENGSTORFF

SHELL SERVICE STATION (Continued) **1000288537**

Address:	110 N. RENGSTORFF AVE.
City,State,Zip:	MOUNTAIN VIEW, CA 94043
Lead Agency:	SANTA CLARA COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608501243
Global Id:	T0608501243
Latitude:	37.403680988
Longitude:	-122.09744
Status:	Completed - Case Closed
Status Date:	04/15/2015
Case Worker:	AC
RB Case Number:	19-049
Local Agency:	SANTA CLARA COUNTY LOP
File Location:	All Files are on GeoTracker or in the Local Agency Database
Local Case Number:	06S2W17R01f
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Benzene, Diesel, Gasoline, MTBE / TBA / Other Fuel Oxygenates, Toluene, Total Petroleum Hydrocarbons (TPH), Xylene
Site History:	The site is currently an active Shell-branded service station located on the northwest corner at the intersection of North Rengstorff and Central Expressway. The station facilities consist of a small kiosk, a car wash, three fuel dispenser islands and four underground storage tanks (USTs). Remediation has been conducted since 1991 to address contamination associated with leaking USTs. Remediation activities included excavation of 1,800 cubic yards of soil, soil vapor extraction, and groundwater extraction. Case closure was previously issued by the County of Santa Clara DEH on April 11, 2005, and fifteen of the twenty existing monitoring wells were destroyed. Remaining wells were maintained by Shell as part of an ongoing groundwater assessment program. The case was re-opened in August 2006 and groundwater extraction resumed until June 2008.

LUST:

Global Id:	T0608501243
Contact Type:	Local Agency Caseworker
Contact Name:	AARON COSTA
Organization Name:	SANTA CLARA COUNTY LOP
Address:	1555 Berger Drive, Suite 300
City:	SAN JOSE
Email:	aaron.costa@cep.sccgov.org
Phone Number:	4089181954

Global Id:	T0608501243
Contact Type:	Regional Board Caseworker
Contact Name:	Regional Water Board
Organization Name:	SAN FRANCISCO BAY RWQCB (REGION 2)
Address:	1515 CLAY ST SUITE 1400
City:	OAKLAND
Email:	Not reported
Phone Number:	Not reported

LUST:

Global Id:	T0608501243
Action Type:	ENFORCEMENT
Date:	11/10/2010
Action:	Staff Letter

SHELL SERVICE STATION (Continued) **1000288537**

Global Id: T0608501243
Action Type: RESPONSE
Date: 04/30/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/30/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 12/05/2013
Action: Staff Letter

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 07/29/2009
Action: Staff Letter

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 08/08/2014
Action: Staff Letter

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 02/19/2014
Action: Staff Letter

Global Id: T0608501243
Action Type: Other
Date: 08/03/1988
Action: Leak Reported

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 11/06/2014
Action: Notification - Public Notice of Case Closure

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 04/15/2015
Action: Closure/No Further Action Letter

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/15/1999
Action: Monitoring Report - Quarterly

Global Id: T0608501243
Action Type: RESPONSE
Date: 04/28/1997
Action: Monitoring Report - Quarterly

Global Id: T0608501243
Action Type: RESPONSE

SHELL SERVICE STATION (Continued) **1000288537**

Date: 06/20/2014
Action: Site Assessment Report

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 01/07/2015
Action: Staff Letter

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/31/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608501243
Action Type: RESPONSE
Date: 04/10/2015
Action: Well Destruction Report

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 04/11/2005
Action: Closure/No Further Action Letter

Global Id: T0608501243
Action Type: RESPONSE
Date: 06/11/1988
Action: Monitoring Report - Quarterly

Global Id: T0608501243
Action Type: RESPONSE
Date: 04/25/1996
Action: Monitoring Report - Quarterly

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/13/2008
Action: Monitoring Report - Quarterly

Global Id: T0608501243
Action Type: RESPONSE
Date: 03/14/1989
Action: Other Workplan

Global Id: T0608501243
Action Type: RESPONSE
Date: 08/03/1988
Action: Unauthorized Release Form

Global Id: T0608501243
Action Type: RESPONSE
Date: 07/31/1996
Action: Other Report / Document

Global Id: T0608501243
Action Type: RESPONSE
Date: 07/28/1988
Action: Other Report / Document

SHELL SERVICE STATION (Continued) **1000288537**

Global Id: T0608501243
Action Type: RESPONSE
Date: 01/01/1989
Action: Correspondence

Global Id: T0608501243
Action Type: RESPONSE
Date: 11/14/1991
Action: Other Report / Document

Global Id: T0608501243
Action Type: RESPONSE
Date: 11/20/2012
Action: Other Report / Document

Global Id: T0608501243
Action Type: RESPONSE
Date: 01/14/1983
Action: Soil and Water Investigation Report

Global Id: T0608501243
Action Type: RESPONSE
Date: 04/30/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/30/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608501243
Action Type: RESPONSE
Date: 04/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/28/2011
Action: Soil and Water Investigation Report

Global Id: T0608501243
Action Type: RESPONSE
Date: 01/01/2006
Action: Correspondence

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/20/2006
Action: Monitoring Report - Quarterly

Global Id: T0608501243
Action Type: RESPONSE
Date: 08/02/2002
Action: Monitoring Report - Quarterly

Global Id: T0608501243
Action Type: RESPONSE

SHELL SERVICE STATION (Continued) **1000288537**

Date: 09/12/2006
Action: Other Workplan

Global Id: T0608501243
Action Type: RESPONSE
Date: 05/02/2005
Action: Well Destruction Report

Global Id: T0608501243
Action Type: RESPONSE
Date: 01/18/2000
Action: NPDES / WDR Reports

Global Id: T0608501243
Action Type: RESPONSE
Date: 06/03/2005
Action: Other Report / Document

Global Id: T0608501243
Action Type: RESPONSE
Date: 11/20/1990
Action: Tank Removal Report / UST Sampling Report

Global Id: T0608501243
Action Type: RESPONSE
Date: 01/28/1993
Action: Interim Remedial Action Report

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/18/1964
Action: Other Report / Document

Global Id: T0608501243
Action Type: RESPONSE
Date: 11/26/2013
Action: Other Report / Document

Global Id: T0608501243
Action Type: RESPONSE
Date: 09/28/1988
Action: Site Assessment Report

Global Id: T0608501243
Action Type: RESPONSE
Date: 06/15/2006
Action: Other Report / Document

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/31/2012
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0608501243
Action Type: RESPONSE
Date: 11/01/2013
Action: Other Report / Document - Regulator Responded

SHELL SERVICE STATION (Continued) **1000288537**

Global Id: T0608501243
Action Type: RESPONSE
Date: 02/14/2014
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0608501243
Action Type: RESPONSE
Date: 06/20/2014
Action: Request for Closure - Regulator Responded

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 03/25/1991
Action: Notice of Responsibility - #40116

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 05/02/1991
Action: Staff Letter - #19250

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 04/11/2005
Action: Closure/No Further Action Letter - #501140

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 08/31/1999
Action: Staff Letter - #30239

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 04/21/1997
Action: Staff Letter - #30232

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 06/03/2005
Action: Other Report

Global Id: T0608501243
Action Type: Other
Date: 07/11/1988
Action: Leak Discovery

Global Id: T0608501243
Action Type: RESPONSE
Date: 10/31/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608501243
Action Type: RESPONSE
Date: 04/30/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0608501243
Action Type: REMEDIATION

SHELL SERVICE STATION (Continued) **1000288537**

Date: 09/20/1991
Action: Excavation

Global Id: T0608501243
Action Type: REMEDIATION
Date: 09/20/1991
Action: Free Product Removal

Global Id: T0608501243
Action Type: REMEDIATION
Date: 09/20/1991
Action: Pump & Treat (P&T) Groundwater

Global Id: T0608501243
Action Type: REMEDIATION
Date: 09/20/1991
Action: Soil Vapor Extraction (SVE)

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 11/21/2012
Action: Staff Letter

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 11/20/2012
Action: Notice of Responsibility

Global Id: T0608501243
Action Type: ENFORCEMENT
Date: 09/13/2013
Action: Staff Letter

Global Id: T0608501243
Action Type: Other
Date: 12/01/1982
Action: Leak Stopped

LUST:
Global Id: T0608501243
Status: Open - Case Begin Date
Status Date: 01/14/1983

Global Id: T0608501243
Status: Open - Site Assessment
Status Date: 01/14/1983

Global Id: T0608501243
Status: Open - Site Assessment
Status Date: 11/10/1988

Global Id: T0608501243
Status: Completed - Case Closed
Status Date: 04/11/2005

Global Id: T0608501243
Status: Open - Reopen Case

SHELL SERVICE STATION (Continued) **1000288537**

Status Date: 06/22/2006

Global Id: T0608501243
Status: Open - Site Assessment
Status Date: 10/06/2006

Global Id: T0608501243
Status: Open - Verification Monitoring
Status Date: 08/16/2012

Global Id: T0608501243
Status: Open - Eligible for Closure
Status Date: 08/19/2014

Global Id: T0608501243
Status: Completed - Case Closed
Status Date: 04/15/2015

HIST LUST SANTA CLARA:
Name: Shell
Address: 110 N Rengstorff Ave
City: Mountain View
Region: SANTA CLARA
Region Code: 2
SCVWD ID: 06S2W17R01
Oversite Agency: SCVWD
Date Listed: 1990-01-01 00:00:00
Closed Date: Not reported

SWEEPS UST:
Name: SHELL OIL COMPANY
Address: 110 N RENGSTORFF AVE
City: MOUNTAIN VIEW
Status: Active
Comp Number: 56732
Number: 9
Board Of Equalization: 44-000074
Referral Date: 07-01-85
Action Date: Not reported
Created Date: 10-13-88
Owner Tank Id: 1
SWRCB Tank Id: 43-005-056732-000001
Tank Status: A
Capacity: 12000
Active Date: 09-26-91
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 4

Name: SHELL OIL COMPANY
Address: 110 N RENGSTORFF AVE
City: MOUNTAIN VIEW
Status: Active
Comp Number: 56732

SHELL SERVICE STATION (Continued) **1000288537**

Number: 9
Board Of Equalization: 44-000074
Referral Date: 07-01-85
Action Date: Not reported
Created Date: 10-13-88
Owner Tank Id: 2
SWRCB Tank Id: 43-005-056732-000002
Tank Status: A
Capacity: 12000
Active Date: 01-06-94
Tank Use: M.V. FUEL
STG: P
Content: SUPER UNLEAD
Number Of Tanks: Not reported

Name: SHELL OIL COMPANY
Address: 110 N RENGSTORFF AVE
City: MOUNTAIN VIEW
Status: Active
Comp Number: 56732
Number: 9
Board Of Equalization: 44-000074
Referral Date: 07-01-85
Action Date: Not reported
Created Date: 10-13-88
Owner Tank Id: 3
SWRCB Tank Id: 43-005-056732-000003
Tank Status: A
Capacity: 12000
Active Date: 01-06-94
Tank Use: M.V. FUEL
STG: P
Content: SUPER UNLEAD
Number Of Tanks: Not reported

Name: SHELL OIL COMPANY
Address: 110 N RENGSTORFF AVE
City: MOUNTAIN VIEW
Status: Active
Comp Number: 56732
Number: 9
Board Of Equalization: 44-000074
Referral Date: 07-01-85
Action Date: Not reported
Created Date: 10-13-88
Owner Tank Id: 4
SWRCB Tank Id: 43-005-056732-000004
Tank Status: A
Capacity: 12000
Active Date: 09-26-91
Tank Use: M.V. FUEL
STG: P
Content: DIESEL
Number Of Tanks: Not reported

HIST UST:
Name: SHELL OIL COMPANY

SHELL SERVICE STATION (Continued) **1000288537**

Address:	110 N RENGSTORFF AVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
File Number:	000208F5
URL:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/000208F5.pdf
Region:	STATE
Facility ID:	00000056732
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	SHELL OIL COMPANY
Telephone:	4159648529
Owner Name:	SHELL OIL COMPANY
Owner Address:	P.O. BOX 4848
Owner City,St,Zip:	ANAHEIM, CA 92803
Total Tanks:	0004
Tank Num:	001
Container Num:	1
Year Installed:	1983
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, Groundwater Monitoring Well, 10
Tank Num:	002
Container Num:	2
Year Installed:	1983
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, Groundwater Monitoring Well, 10
Tank Num:	003
Container Num:	3
Year Installed:	1983
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, Groundwater Monitoring Well, 10
Tank Num:	004
Container Num:	4
Year Installed:	1983
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	1/4
Leak Detection:	Stock Inventor, Groundwater Monitoring Well, 10

Click here for Geo Tracker PDF:

CA FID UST:

Facility ID:	43001282
Regulated By:	UTNKA
Regulated ID:	00056732

SHELL SERVICE STATION (Continued) **1000288537**

Cortese Code: Not reported
SIC Code: Not reported
Facility Phone: 4159648529
Mail To: Not reported
Mailing Address: 110 N RENGSTORFF AVE
Mailing Address 2: Not reported
Mailing City,St,Zip: MOUNTAIN VIEW 94040
Contact: Not reported
Contact Phone: Not reported
DUNs Number: Not reported
NPDES Number: Not reported
EPA ID: Not reported
Comments: Not reported
Status: Active

CORTESE:
Name: SHELL - 110 N RENGSTORFF
Address: 110 N. RENGSTORFF AVE.
City,State,Zip: MOUNTAIN VIEW, CA 94043
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0608501243
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

CUPA SANTA CLARA:
Name: RENGSTORFF SHELL #144
Address: 110 N RENGSTORFF AV
City,State,Zip: MOUNTAIN VIEW, CA 94043
Region: SANTA CLARA
PE#: 2240
Program Description: GENERATES < 10 GAL/YR
Latitude: 37.403858
Longitude: -122.097149
Record ID: PR0381316
Facility ID: FA0260193

HIST CORTESE:
edr_fname: SHELL
edr_fadd1: 110 RENGSTORFF

SHELL SERVICE STATION (Continued) **1000288537**

City,State,Zip: MOUNTAIN VIEW, CA 94043
Region: CORTESE
Facility County Code: 43
Reg By: LTNKA
Reg Id: 43-1265

NOTIFY 65:
Name: SHELL STATION
Address: 110 RENGSTORFF
City,State,Zip: MOUNTAIN VIEW, CA 91351
Date Reported: Not reported
Staff Initials: Not reported
Board File Number: Not reported
Facility Type: Not reported
Discharge Date: Not reported
Issue Date: Not reported
Incident Description: Not reported
Global ID: Not reported
Status: Not reported

CERS:
Name: SHELL - 110 N RENGSTORFF
Address: 110 N. RENGSTORFF AVE.
City,State,Zip: MOUNTAIN VIEW, CA 94043
Site ID: 233778
CERS ID: T0608501243
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: AARON COSTA - SANTA CLARA COUNTY LOP
Entity Title: Not reported
Affiliation Address: 1555 Berger Drive, Suite 300
Affiliation City: SAN JOSE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 4089181954

Affiliation Type Desc: Regional Board Caseworker
Entity Name: Regional Water Board - SAN FRANCISCO BAY RWQCB (REGION 2)
Entity Title: Not reported
Affiliation Address: 1515 CLAY ST SUITE 1400
Affiliation City: OAKLAND
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

O88 **PLESSEY #3** **RESPONSE** **S102804169**
NNW **2256 MORA DRIVE** **ENVIROSTOR** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94040** **CERS**
0.990 mi.
5227 ft. **Site 3 of 4 in cluster O**

Relative:
Lower

Actual:
54 ft.

RESPONSE:

Name:	PLESSEY #3
Address:	2256 MORA DRIVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Facility ID:	43360135
Site Type:	State Response
Site Type Detail:	State Response or NPL
Acres:	0.17
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Not reported
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Site Code:	201358
Site Mgmt. Req.:	NONE SPECIFIED
Assembly:	24
Senate:	13
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	10/05/2001
Restricted Use:	NO
Funding:	Responsible Party
Latitude:	37.40309
Longitude:	-122.1012
APN:	147-54-024, 147-54-025, 148-33-021
Past Use:	MANUFACTURING - ELECTRONIC
Potential COC :	Tetrachloroethylene (PCE Trichloroethylene (TCE
Confirmed COC:	Tetrachloroethylene (PCE Trichloroethylene (TCE
Potential Description:	OTH
Alias Name:	PLESSEY #3
Alias Type:	Alternate Name
Alias Name:	147-54-024
Alias Type:	APN
Alias Name:	147-54-025
Alias Type:	APN
Alias Name:	148-33-021
Alias Type:	APN
Alias Name:	110033611624
Alias Type:	EPA (FRS #)
Alias Name:	201358
Alias Type:	Project Code (Site Code)
Alias Name:	43360135
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Unilateral Order (I/SE, RAO, CAO, EPA AO)
Completed Date:	11/28/2000
Comments:	Issued I&SE Order.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported

PLESSEY #3 (Continued) **S102804169**

Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 10/15/2001
Comments: Completed PEA. Cleanup of this site will be addressed as part of the Plessey Micro Science site cleanup. Contaminated groundwater will be extracted from 2 onsite wells and treated with an air stripper and carbon adsorption constructed at the PMS site.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Name: PLESSEY #3
Address: 2256 MORA DRIVE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Facility ID: 43360135
Status: No Further Action
Status Date: 10/05/2001
Site Code: 201358
Site Type: State Response
Site Type Detailed: State Response or NPL
Acres: 0.17
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Assembly: 24
Senate: 13
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.40309
Longitude: -122.1012
APN: 147-54-024, 147-54-025, 148-33-021
Past Use: MANUFACTURING - ELECTRONIC
Potential COC: Tetrachloroethylene (PCE Trichloroethylene (TCE
Confirmed COC: Tetrachloroethylene (PCE Trichloroethylene (TCE
Potential Description: OTH
Alias Name: PLESSEY #3
Alias Type: Alternate Name
Alias Name: 147-54-024
Alias Type: APN
Alias Name: 147-54-025
Alias Type: APN
Alias Name: 148-33-021
Alias Type: APN
Alias Name: 110033611624
Alias Type: EPA (FRS #)

PLESSEY #3 (Continued) **S102804169**

Alias Name: 201358
Alias Type: Project Code (Site Code)
Alias Name: 43360135
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Unilateral Order (I/SE, RAO, CAO, EPA AO)
Completed Date: 11/28/2000
Comments: Issued I&SE Order.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 10/15/2001
Comments: Completed PEA. Cleanup of this site will be addressed as part of the Plessey Micro Science site cleanup. Contaminated groundwater will be extracted from 2 onsite wells and treated with an air stripper and carbon adsorption constructed at the PMS site.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

CERS:
Name: PLESSEY #3
Address: 2256 MORA DRIVE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 341536
CERS ID: 43360135
CERS Description: State Response

Affiliation:
Affiliation Type Desc: Supervisor
Entity Name: MARK PIROS
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

O89 **PLESSEY #2** **RESPONSE** **S103883832**
NNW **2251, 2257, 2283 AND 2287 MORA DRIVE** **ENVIROSTOR** **N/A**
1/2-1 **MOUNTAIN VIEW, CA 94040** **CERS**
0.992 mi.
5238 ft. **Site 4 of 4 in cluster O**

Relative:
Lower

Actual:
55 ft.

RESPONSE:

Name:	PLESSEY #2
Address:	2251, 2257, 2283 AND 2287 MORA DRIVE
City,State,Zip:	MOUNTAIN VIEW, CA 94040
Facility ID:	43360131
Site Type:	State Response
Site Type Detail:	State Response or NPL
Acres:	0.43
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Not reported
Supervisor:	Mark Piros
Division Branch:	Cleanup Berkeley
Site Code:	201102
Site Mgmt. Req.:	NONE SPECIFIED
Assembly:	24
Senate:	13
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	05/15/2002
Restricted Use:	NO
Funding:	Responsible Party
Latitude:	37.40301
Longitude:	-122.1023
APN:	147-54-010, 147-54-011, 147-54-012, 147-54-014, 147-54-015
Past Use:	MANUFACTURING - ELECTRONIC
Potential COC :	Tetrachloroethylene (PCE Trichloroethylene (TCE
Confirmed COC:	Tetrachloroethylene (PCE Trichloroethylene (TCE
Potential Description:	OTH
Alias Name:	PLESSEY #2
Alias Type:	Alternate Name
Alias Name:	147-54-010
Alias Type:	APN
Alias Name:	147-54-011
Alias Type:	APN
Alias Name:	147-54-012
Alias Type:	APN
Alias Name:	147-54-014
Alias Type:	APN
Alias Name:	147-54-015
Alias Type:	APN
Alias Name:	110033611615
Alias Type:	EPA (FRS #)
Alias Name:	201102
Alias Type:	Project Code (Site Code)
Alias Name:	43360131
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Preliminary Endangerment Assessment Report
Completed Date:	10/09/2001

PLESSEY #2 (Continued) **S103883832**

Comments: Completed PEA. Phase 2 Remedial Investigation Report submitted. Soil and grab groundwater samples taken along the main sewer line. The results did not indicate a contamination source on the property.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

ENVIROSTOR:
Name: PLESSEY #2
Address: 2251, 2257, 2283 AND 2287 MORA DRIVE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Facility ID: 43360131
Status: No Further Action
Status Date: 05/15/2002
Site Code: 201102
Site Type: State Response
Site Type Detailed: State Response or NPL
Acres: 0.43
NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Not reported
Supervisor: Mark Piros
Division Branch: Cleanup Berkeley
Assembly: 24
Senate: 13
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Responsible Party
Latitude: 37.40301
Longitude: -122.1023
APN: 147-54-010, 147-54-011, 147-54-012, 147-54-014, 147-54-015
Past Use: MANUFACTURING - ELECTRONIC
Potential COC: Tetrachloroethylene (PCE Trichloroethylene (TCE
Confirmed COC: Tetrachloroethylene (PCE Trichloroethylene (TCE
Potential Description: OTH
Alias Name: PLESSEY #2
Alias Type: Alternate Name
Alias Name: 147-54-010
Alias Type: APN
Alias Name: 147-54-011
Alias Type: APN
Alias Name: 147-54-012
Alias Type: APN
Alias Name: 147-54-014
Alias Type: APN
Alias Name: 147-54-015
Alias Type: APN
Alias Name: 110033611615

PLESSEY #2 (Continued) **S103883832**

Alias Type: EPA (FRS #)
Alias Name: 201102
Alias Type: Project Code (Site Code)
Alias Name: 43360131
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 10/09/2001
Comments: Completed PEA. Phase 2 Remedial Investigation Report submitted. Soil and grab groundwater samples taken along the main sewer line. The results did not indicate a contamination source on the property.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

CERS:
Name: PLESSEY #2
Address: 2251, 2257, 2283 AND 2287 MORA DRIVE
City,State,Zip: MOUNTAIN VIEW, CA 94040
Site ID: 341535
CERS ID: 43360131
CERS Description: State Response

Affiliation:
Affiliation Type Desc: Supervisor
Entity Name: MARK PIROS
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: Not reported

Count: 5 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
LOS ALTOS	S125242582	HILLVIEW MAINTENANCE YARD	ADJACENT TO 97 HILLVIEW AVE NR	94022	ENVIROSTOR
LOS ALTOS	S125952667	COVINGTON PIPELINE PROJECT	SOUTH EL MONTE AVENUE AND FOOT	94022	CPS-SLIC
MOUNTAIN VIEW	S101482408	MOUNTAIN VIEW LANDFILL GAS RECOVER	BETW CHARLESTON SLOUGH & STEVE	94042	ENVIROSTOR
MOUNTAIN VIEW	S125742963	BEST BUY #0685	715 EL CAMINO REAL EAST	94040	CERS HAZ WASTE
MOUNTAIN VIEW	1003879002	SAN FRANCISCO BAY	MOUNTAIN VIEW	94042	SEMS-ARCHIVE

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 04/03/2019
Date Data Arrived at EDR: 04/05/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/23/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/06/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/11/2020
Number of Days to Update: 82

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/18/2020
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/18/2020
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/15/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 7

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

State- and tribal - equivalent NPL

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 10/26/2020
Date Data Arrived at EDR: 10/26/2020
Date Made Active in Reports: 01/13/2021
Number of Days to Update: 79

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/26/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 10/26/2020
Date Data Arrived at EDR: 10/26/2020
Date Made Active in Reports: 01/13/2021
Number of Days to Update: 79

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/26/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Quarterly

State and tribal landfill and/or solid waste disposal site lists

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 11/09/2020
Date Data Arrived at EDR: 11/10/2020
Date Made Active in Reports: 01/14/2021
Number of Days to Update: 65

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 11/10/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

LUST REG 9: Leaking Underground Storage Tank Report

Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

LUST REG 3: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 1: Active Toxic Site Investigation

Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List

Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks

California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

LUST: Leaking Underground Fuel Tank Report (GEOTRACKER)

Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

LUST REG 4: Underground Storage Tank Leak List

Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 5: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

LUST REG 7: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 6L: Leaking Underground Storage Tank Case Listing

For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/29/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/26/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 78
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/15/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

CPS-SLIC: Statewide SLIC Cases (GEOTRACKER)
Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35
Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36
Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11
Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17
Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 07/21/2020
Date Data Arrived at EDR: 09/03/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 83
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

UST CLOSURE: Proposed Closure of Underground Storage Tank (UST) Cases
UST cases that are being considered for closure by either the State Water Resources Control Board or the Executive Director have been posted for a 60-day public comment period. UST Case Closures being proposed for consideration by the State Water Resources Control Board. These are primarily UST cases that meet closure criteria under the decisional framework in State Water Board Resolution No. 92-49 and other Board orders. UST Case Closures proposed for consideration by the Executive Director pursuant to State Water Board Resolution No. 2012-0061. These are cases that meet the criteria of the Low-Threat UST Case Closure Policy. UST Case Closure Review Denials and Approved Orders.

Date of Government Version: 09/03/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/03/2020
Number of Days to Update: 86

Source: State Water Resources Control Board
Telephone: 916-327-7844
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

MILITARY UST SITES: Military UST Sites (GEOTRACKER)
Military ust sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

UST: Active UST Facilities
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Semi-Annually

AST: Aboveground Petroleum Storage Tank Facilities
A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 07/06/2016
Date Data Arrived at EDR: 07/12/2016
Date Made Active in Reports: 09/19/2016
Number of Days to Update: 69

Source: California Environmental Protection Agency
Telephone: 916-327-5092
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/03/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/29/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/26/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 78

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 12/16/2020
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Properties
Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 10/26/2020
Date Data Arrived at EDR: 10/26/2020
Date Made Active in Reports: 01/13/2021
Number of Days to Update: 79

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/26/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Quarterly

State and tribal Brownfields sites

BROWNFIELDS: Considered Brownfieds Sites Listing
A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 09/21/2020
Date Data Arrived at EDR: 09/22/2020
Date Made Active in Reports: 12/11/2020
Number of Days to Update: 80

Source: State Water Resources Control Board
Telephone: 916-323-7905
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/14/2020
Date Data Arrived at EDR: 09/15/2020
Date Made Active in Reports: 12/10/2020
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 12/11/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: Waste Management Unit Database
Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 01/25/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: No Update Planned

SWRCY: Recycler Database
A listing of recycling facilities in California.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing
A listing of registered waste tire haulers.

Date of Government Version: 05/28/2020
Date Data Arrived at EDR: 05/29/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 75

Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/25/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Varies

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land
A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 10/30/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 03/18/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 10/26/2020
Date Data Arrived at EDR: 10/26/2020
Date Made Active in Reports: 01/13/2021
Number of Days to Update: 79

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/26/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 06/30/2019
Date Data Arrived at EDR: 05/28/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

CERS HAZ WASTE: CERS HAZ WASTE

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80

Source: CalEPA
Telephone: 916-323-2514
Last EDR Contact: 01/20/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Quarterly

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 03/18/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

A listing of PFAS contaminated sites included in the GeoTracker database.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

UST MENDOCINO: Mendocino County UST Database

A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 05/20/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/06/2020
Number of Days to Update: 78

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Annually

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SAN FRANCISCO AST: Aboveground Storage Tank Site Listing
Aboveground storage tank sites

Date of Government Version: 11/05/2020
Date Data Arrived at EDR: 11/06/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 81

Source: San Francisco County Department of Public Health
Telephone: 415-252-3896
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

CA FID UST: Facility Inventory Database
The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CERS TANKS: California Environmental Reporting System (CERS) Tanks
List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 01/20/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Quarterly

Local Land Records

LIENS: Environmental Liens Listing
A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 08/26/2020
Date Data Arrived at EDR: 08/28/2020
Date Made Active in Reports: 11/17/2020
Number of Days to Update: 81

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Semi-Annually

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 81
Source: DTSC and SWRCB
Telephone: 916-323-3400
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 09/20/2020
Date Data Arrived at EDR: 09/22/2020
Date Made Active in Reports: 12/14/2020
Number of Days to Update: 83
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 09/30/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80
Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 01/20/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Semi-Annually

LDS: Land Disposal Sites Listing (GEOTRACKER)

Land Disposal sites (Landfills) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing (GEOTRACKER)

Military sites (consisting of: Military UST sites; Military Privatized sites; and Military Cleanup sites [formerly known as DoD non UST]) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/14/2020
Date Data Arrived at EDR: 12/17/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 09/29/2020
Date Data Arrived at EDR: 11/17/2020
Date Made Active in Reports: 01/25/2021
Number of Days to Update: 69

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/15/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/07/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 09/21/2020
Date Data Arrived at EDR: 09/22/2020
Date Made Active in Reports: 12/14/2020
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 11/02/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 11/06/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/21/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 11/02/2020
Date Data Arrived at EDR: 11/12/2020
Date Made Active in Reports: 01/25/2021
Number of Days to Update: 74

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 04/27/2020
Date Data Arrived at EDR: 05/06/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 34
Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

PADS: PCB Activity Database System
PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/09/2019
Date Data Arrived at EDR: 10/11/2019
Date Made Active in Reports: 12/20/2019
Number of Days to Update: 70
Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System
The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/05/2020
Date Data Arrived at EDR: 08/10/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 59
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 01/15/2020
Number of Days to Update: 42
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 11/30/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/06/2021
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/27/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2020
Date Data Arrived at EDR: 10/08/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 88

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 151

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 12/23/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 11/06/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/20/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 01/14/2021
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/03/2020
Date Data Arrived at EDR: 11/23/2020
Date Made Active in Reports: 01/25/2021
Number of Days to Update: 63

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 11/24/2020
Date Data Arrived at EDR: 11/30/2020
Date Made Active in Reports: 01/25/2021
Number of Days to Update: 56

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 11/24/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/16/2020
Date Data Arrived at EDR: 09/17/2020
Date Made Active in Reports: 12/10/2020
Number of Days to Update: 84

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 12/10/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/04/2020
Date Data Arrived at EDR: 12/01/2020
Date Made Active in Reports: 01/25/2021
Number of Days to Update: 55

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 77

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/15/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing
A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71
Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information
ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 10/03/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 90
Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 11/13/2020
Date Data Arrived at EDR: 11/13/2020
Date Made Active in Reports: 01/25/2021
Number of Days to Update: 73
Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Quarterly

CA BOND EXP. PLAN: Bond Expenditure Plan
Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6
Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/04/2020
Number of Days to Update: 74
Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 12/17/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

CUPA LIVERMORE-PLEASANTON: CUPA Facility Listing
list of facilities associated with the various CUPA programs in Livermore-Pleasanton

Date of Government Version: 05/01/2019
Date Data Arrived at EDR: 05/14/2019
Date Made Active in Reports: 07/17/2019
Number of Days to Update: 64
Source: Livermore-Pleasanton Fire Department
Telephone: 925-454-2361
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

DRYCLEAN AVAQMD: Antelope Valley Air Quality Management District Drycleaner Listing
A listing of dry cleaners in the Antelope Valley Air Quality Management District.

Date of Government Version: 08/25/2020
Date Data Arrived at EDR: 08/26/2020
Date Made Active in Reports: 11/13/2020
Number of Days to Update: 79

Source: Antelope Valley Air Quality Management District
Telephone: 661-723-8070
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

DRYCLEAN SOUTH COAST: South Coast Air Quality Management District Drycleaner Listing
A listing of dry cleaners in the South Coast Air Quality Management District

Date of Government Version: 08/19/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 09/04/2020
Number of Days to Update: 14

Source: South Coast Air Quality Management District
Telephone: 909-396-3211
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

DRYCLEANERS: Cleaner Facilities
A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 08/06/2020
Date Data Arrived at EDR: 08/28/2020
Date Made Active in Reports: 11/17/2020
Number of Days to Update: 81

Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Annually

EMI: Emissions Inventory Data
Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 08/28/2020
Number of Days to Update: 73

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Varies

ENF: Enforcement Action Listing
A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 10/16/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80

Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 01/20/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing
Financial Assurance information

Date of Government Version: 10/13/2020
Date Data Arrived at EDR: 10/14/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 01/22/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 08/05/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 79

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 11/04/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 04/15/2020
Date Made Active in Reports: 07/02/2020
Number of Days to Update: 78

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 01/05/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Annually

ICE: ICE

Contains data pertaining to the Permitted Facilities with Inspections / Enforcements sites tracked in Envirostor.

Date of Government Version: 08/17/2020
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 80

Source: Department of Toxic Subsances Control
Telephone: 877-786-9427
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List

The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HWP: EnviroStor Permitted Facilities Listing

Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 08/17/2020
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Quarterly

HWT: Registered Hazardous Waste Transporter Database

A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 10/05/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 12/23/2020
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 01/05/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Quarterly

MINES: Mines Site Location Listing
A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: Department of Conservation
Telephone: 916-322-1080
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing
The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 81
Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

NPDES: NPDES Permits Listing
A listing of NPDES permits, including stormwater.

Date of Government Version: 11/09/2020
Date Data Arrived at EDR: 11/10/2020
Date Made Active in Reports: 01/27/2021
Number of Days to Update: 78
Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Quarterly

PEST LIC: Pesticide Regulation Licenses Listing
A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 81
Source: Department of Pesticide Regulation
Telephone: 916-445-4038
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

PROC: Certified Processors Database
A listing of certified processors.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

NOTIFY 65: Proposition 65 Records
Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 12/07/2020
Date Data Arrived at EDR: 12/09/2020
Date Made Active in Reports: 12/10/2020
Number of Days to Update: 1
Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 12/07/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UIC: UIC Listing
A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84
Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

UIC GEO: Underground Injection Control Sites (GEOTRACKER)
Underground control injection sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resource Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

WASTEWATER PITS: Oil Wastewater Pits Listing
Water officials discovered that oil producers have been dumping chemical-laden wastewater into hundreds of unlined pits that are operating without proper permits. Inspections completed by the Central Valley Regional Water Quality Control Board revealed the existence of previously unidentified waste sites. The water boards review found that more than one-third of the region's active disposal pits are operating without permission.

Date of Government Version: 11/19/2019
Date Data Arrived at EDR: 01/07/2020
Date Made Active in Reports: 03/09/2020
Number of Days to Update: 62
Source: RWQCB, Central Valley Region
Telephone: 559-445-5577
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9
Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: No Update Planned

WIP: Well Investigation Program Case List
Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13
Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: No Update Planned

MILITARY PRIV SITES: Military Privatized Sites (GEOTRACKER)
Military privatized sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

PROJECT: Project Sites (GEOTRACKER)
Projects sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

WDR: Waste Discharge Requirements Listing

In general, the Waste Discharge Requirements (WDRs) Program (sometimes also referred to as the "Non Chapter 15 (Non 15) Program") regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. Exemptions from Title 27 may be granted for nine categories of discharges (e.g., sewage, wastewater, etc.) that meet, and continue to meet, the preconditions listed for each specific exemption. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84

Source: State Water Resources Control Board
Telephone: 916-341-5810
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

CIWQS: California Integrated Water Quality System

The California Integrated Water Quality System (CIWQS) is a computer system used by the State and Regional Water Quality Control Boards to track information about places of environmental interest, manage permits and other orders, track inspections, and manage violations and enforcement activities.

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 81

Source: State Water Resources Control Board
Telephone: 866-794-4977
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

CERS: CalEPA Regulated Site Portal Data

The CalEPA Regulated Site Portal database combines data about environmentally regulated sites and facilities in California into a single database. It combines data from a variety of state and federal databases, and provides an overview of regulated activities across the spectrum of environmental programs for any given location in California. These activities include hazardous materials and waste, state and federal cleanups, impacted ground and surface waters, and toxic materials

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/19/2020
Date Made Active in Reports: 01/07/2021
Number of Days to Update: 80

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 01/20/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

NON-CASE INFO: Non-Case Information Sites (GEOTRACKER)

Non-Case Information sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

OTHER OIL GAS: Other Oil & Gas Projects Sites (GEOTRACKER)

Other Oil & Gas Projects sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

PROD WATER PONDS: Produced Water Ponds Sites (GEOTRACKER)
Produced water ponds sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

SAMPLING POINT: Sampling Point ? Public Sites (GEOTRACKER)
Sampling point - public sites

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

WELL STIM PROJ: Well Stimulation Project (GEOTRACKER)
Includes areas of groundwater monitoring plans, a depiction of the monitoring network, and the facilities, boundaries, and subsurface characteristics of the oilfield and the features (oil and gas wells, produced water ponds, UIC wells, water supply wells, etc?) being monitored

Date of Government Version: 09/08/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 11/30/2020
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 12/04/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Varies

HWTS: Hazardous Waste Tracking System
DTSC maintains the Hazardous Waste Tracking System that stores ID number information since the early 1980s and manifest data since 1993. The system collects both manifest copies from the generator and destination facility.

Date of Government Version: 10/13/2020
Date Data Arrived at EDR: 10/14/2020
Date Made Active in Reports: 11/03/2020
Number of Days to Update: 20
Source: Department of Toxic Substances Control
Telephone: 916-324-2444
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3
Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29
Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits
An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Department of Resources Recycling and Recovery
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

ALAMEDA COUNTY:

CS ALAMEDA: Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 01/09/2019
Date Data Arrived at EDR: 01/11/2019
Date Made Active in Reports: 03/05/2019
Number of Days to Update: 53

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

UST ALAMEDA: Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 12/23/2020
Number of Days to Update: 78

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA AMADOR: CUPA Facility List
Cupa Facility List

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/22/2020
Date Made Active in Reports: 01/12/2021
Number of Days to Update: 82

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA BUTTE: CUPA Facility Listing
Cupa facility list.

Date of Government Version: 04/21/2017
Date Data Arrived at EDR: 04/25/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 106

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA CALVERAS: CUPA Facility Listing
Cupa Facility Listing

Date of Government Version: 12/15/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 12/24/2020
Number of Days to Update: 8

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA COLUSA: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/06/2020
Date Data Arrived at EDR: 04/23/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 78

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Semi-Annually

CONTRA COSTA COUNTY:

SL CONTRA COSTA: Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/22/2020
Date Made Active in Reports: 01/13/2021
Number of Days to Update: 83

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 01/25/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA DEL NORTE: CUPA Facility List
Cupa Facility list

Date of Government Version: 06/08/2020
Date Data Arrived at EDR: 08/13/2020
Date Made Active in Reports: 10/22/2020
Number of Days to Update: 70

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 01/25/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA EL DORADO: CUPA Facility List
CUPA facility list.

Date of Government Version: 10/22/2020
Date Data Arrived at EDR: 11/03/2020
Date Made Active in Reports: 01/20/2021
Number of Days to Update: 78

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 01/25/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA FRESNO: CUPA Resources List
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 10/02/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 77

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 01/15/2021
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Semi-Annually

GLENN COUNTY:

CUPA GLENN: CUPA Facility List
Cupa facility list

Date of Government Version: 01/22/2018
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 03/14/2018
Number of Days to Update: 49

Source: Glenn County Air Pollution Control District
Telephone: 830-934-6500
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: No Update Planned

HUMBOLDT COUNTY:

CUPA HUMBOLDT: CUPA Facility List
CUPA facility list.

Date of Government Version: 08/13/2020
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 80

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Semi-Annually

IMPERIAL COUNTY:

CUPA IMPERIAL: CUPA Facility List
Cupa facility list.

Date of Government Version: 10/14/2020
Date Data Arrived at EDR: 10/15/2020
Date Made Active in Reports: 01/05/2021
Number of Days to Update: 82

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

INYO COUNTY:

CUPA INYO: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/03/2018
Date Made Active in Reports: 06/14/2018
Number of Days to Update: 72

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

KERN COUNTY:

CUPA KERN: CUPA Facility List
A listing of sites included in the Kern County Hazardous Material Business Plan.

Date of Government Version: 10/29/2020
Date Data Arrived at EDR: 10/30/2020
Date Made Active in Reports: 01/15/2021
Number of Days to Update: 77

Source: Kern County Public Health
Telephone: 661-321-3000
Last EDR Contact: 01/15/2021
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

UST KERN: Underground Storage Tank Sites & Tank Listing
Kern County Sites and Tanks Listing.

Date of Government Version: 01/19/2021
Date Data Arrived at EDR: 01/21/2021
Date Made Active in Reports: 01/28/2021
Number of Days to Update: 7

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA KINGS: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 05/11/2020
Date Data Arrived at EDR: 05/12/2020
Date Made Active in Reports: 07/27/2020
Number of Days to Update: 76

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 01/25/2021
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

LAKE COUNTY:

CUPA LAKE: CUPA Facility List
Cupa facility list

Date of Government Version: 08/13/2020
Date Data Arrived at EDR: 08/13/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 71

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 01/11/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Varies

LASSEN COUNTY:

CUPA LASSEN: CUPA Facility List
Cupa facility list

Date of Government Version: 07/31/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 80

Source: Lassen County Environmental Health
Telephone: 530-251-8528
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

LOS ANGELES COUNTY:

AOCONCERN: Key Areas of Concerns in Los Angeles County
San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office. Date of Government Version: 3/30/2009 Exide Site area is a cleanup plan of lead-impacted soil surrounding the former Exide Facility as designated by the DTSC. Date of Government Version: 7/17/2017

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206

Source: N/A
Telephone: N/A
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: No Update Planned

HMS LOS ANGELES: HMS: Street Number List
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 10/19/2020
Date Data Arrived at EDR: 10/20/2020
Date Made Active in Reports: 01/12/2021
Number of Days to Update: 84

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 01/04/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Semi-Annually

LF LOS ANGELES: List of Solid Waste Facilities
Solid Waste Facilities in Los Angeles County.

Date of Government Version: 10/09/2020
Date Data Arrived at EDR: 10/09/2020
Date Made Active in Reports: 12/29/2020
Number of Days to Update: 81

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 01/12/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Varies

LF LOS ANGELES CITY: City of Los Angeles Landfills
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 80

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 01/11/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Varies

LOS ANGELES AST: Active & Inactive AST Inventory
A listing of active & inactive above ground petroleum storage tank site locations, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

LOS ANGELES CO LF METHANE: Methane Producing Landfills
This data was created on April 30, 2012 to represent known disposal sites in Los Angeles County that may produce and emanate methane gas. The shapefile contains disposal sites within Los Angeles County that once accepted degradable refuse material. Information used to create this data was extracted from a landfill survey performed by County Engineers (Major Waste System Map, 1973) as well as historical records from CalRecycle, Regional Water Quality Control Board, and Los Angeles County Department of Public Health

Date of Government Version: 04/30/2012
Date Data Arrived at EDR: 04/17/2019
Date Made Active in Reports: 05/29/2019
Number of Days to Update: 42
Source: Los Angeles County Department of Public Works
Telephone: 626-458-6973
Last EDR Contact: 01/15/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: No Update Planned

LOS ANGELES HM: Active & Inactive Hazardous Materials Inventory
A listing of active & inactive hazardous materials facility locations, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

LOS ANGELES UST: Active & Inactive UST Inventory
A listing of active & inactive underground storage tank site locations and underground storage tank historical sites, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/18/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

SITE MIT LOS ANGELES: Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 07/20/2020
Date Data Arrived at EDR: 10/09/2020
Date Made Active in Reports: 12/29/2020
Number of Days to Update: 81
Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 01/12/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Annually

UST EL SEGUNDO: City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/10/2017
Number of Days to Update: 21
Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 10/07/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: No Update Planned

UST LONG BEACH: City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 04/22/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/27/2019
Number of Days to Update: 65

Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

UST TORRANCE: City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 09/11/2020
Date Data Arrived at EDR: 10/07/2020
Date Made Active in Reports: 12/23/2020
Number of Days to Update: 77

Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA MADERA: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 72

Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

MARIN COUNTY:

UST MARIN: Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 09/26/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/02/2018
Number of Days to Update: 29

Source: Public Works Department Waste Management
Telephone: 415-473-6647
Last EDR Contact: 12/21/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Semi-Annually

MERCED COUNTY:

CUPA MERCED: CUPA Facility List
CUPA facility list.

Date of Government Version: 07/28/2020
Date Data Arrived at EDR: 07/30/2020
Date Made Active in Reports: 07/31/2020
Number of Days to Update: 1

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

MONO COUNTY:

CUPA MONO: CUPA Facility List
CUPA Facility List

Date of Government Version: 08/20/2020
Date Data Arrived at EDR: 08/24/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 77

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 11/15/2020
Next Scheduled EDR Contact: 03/08/3021
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA MONTEREY: CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 07/13/2020
Date Data Arrived at EDR: 07/15/2020
Date Made Active in Reports: 07/31/2020
Number of Days to Update: 16

Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 12/21/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Varies

NAPA COUNTY:

LUST NAPA: Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 03/02/2017
Number of Days to Update: 50

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

UST NAPA: Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 09/05/2019
Date Data Arrived at EDR: 09/09/2019
Date Made Active in Reports: 10/31/2019
Number of Days to Update: 52

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA NEVADA: CUPA Facility List
CUPA facility list.

Date of Government Version: 10/26/2020
Date Data Arrived at EDR: 10/28/2020
Date Made Active in Reports: 01/15/2021
Number of Days to Update: 79

Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 01/25/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Varies

ORANGE COUNTY:

IND_SITE ORANGE: List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 09/01/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 82

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/02/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Annually

LUST ORANGE: List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 09/01/2020
Date Data Arrived at EDR: 11/06/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 81

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/02/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

UST ORANGE: List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 09/01/2020
Date Data Arrived at EDR: 11/03/2020
Date Made Active in Reports: 01/21/2021
Number of Days to Update: 79

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 11/03/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

PLACER COUNTY:

MS PLACER: Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 11/24/2020
Date Data Arrived at EDR: 11/24/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 1

Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Semi-Annually

PLUMAS COUNTY:

CUPA PLUMAS: CUPA Facility List
Plumas County CUPA Program facilities.

Date of Government Version: 03/31/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/26/2019
Number of Days to Update: 64

Source: Plumas County Environmental Health
Telephone: 530-283-6355
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

RIVERSIDE COUNTY:

LUST RIVERSIDE: Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 10/06/2020
Date Data Arrived at EDR: 10/07/2020
Date Made Active in Reports: 11/03/2020
Number of Days to Update: 27

Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Quarterly

UST RIVERSIDE: Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 10/06/2020
Date Data Arrived at EDR: 10/07/2020
Date Made Active in Reports: 11/03/2020
Number of Days to Update: 27
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

CS SACRAMENTO: Toxic Site Clean-Up List
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 02/18/2020
Date Data Arrived at EDR: 03/31/2020
Date Made Active in Reports: 06/15/2020
Number of Days to Update: 76
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

ML SACRAMENTO: Master Hazardous Materials Facility List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 02/24/2020
Date Data Arrived at EDR: 03/31/2020
Date Made Active in Reports: 06/17/2020
Number of Days to Update: 78
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 12/30/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: Quarterly

SAN BENITO COUNTY:

CUPA SAN BENITO: CUPA Facility List
Cupa facility list

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 10/30/2020
Date Made Active in Reports: 01/15/2021
Number of Days to Update: 77
Source: San Benito County Environmental Health
Telephone: N/A
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

SAN BERNARDINO COUNTY:

PERMITS SAN BERNARDINO: Hazardous Material Permits
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 08/04/2020
Date Data Arrived at EDR: 08/05/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 82
Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

HMMD SAN DIEGO: Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 08/31/2020
Date Data Arrived at EDR: 08/31/2020
Date Made Active in Reports: 11/23/2020
Number of Days to Update: 84

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

LF SAN DIEGO: Solid Waste Facilities

San Diego County Solid Waste Facilities.

Date of Government Version: 04/18/2018
Date Data Arrived at EDR: 04/24/2018
Date Made Active in Reports: 06/19/2018
Number of Days to Update: 56

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

SAN DIEGO CO LOP: Local Oversight Program Listing

A listing of all LOP release sites that are or were under the County of San Diego's jurisdiction. Included are closed or transferred cases, open cases, and cases that did not have a case type indicated. The cases without a case type are mostly complaints; however, some of them could be LOP cases.

Date of Government Version: 07/14/2020
Date Data Arrived at EDR: 07/16/2020
Date Made Active in Reports: 09/29/2020
Number of Days to Update: 75

Source: Department of Environmental Health
Telephone: 858-505-6874
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

SAN DIEGO CO SAM: Environmental Case Listing

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24

Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

CUPA SAN FRANCISCO CO: CUPA Facility Listing

Cupa facilities

Date of Government Version: 11/05/2020
Date Data Arrived at EDR: 11/06/2020
Date Made Active in Reports: 01/27/2021
Number of Days to Update: 82

Source: San Francisco County Department of Environmental Health
Telephone: 415-252-3896
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

LUST SAN FRANCISCO: Local Oversite Facilities

A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10

Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: No Update Planned

UST SAN FRANCISCO: Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 11/05/2020
Date Data Arrived at EDR: 11/06/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 81

Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

SAN JOAQUIN COUNTY:

UST SAN JOAQUIN: San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 06/22/2018
Date Data Arrived at EDR: 06/26/2018
Date Made Active in Reports: 07/11/2018
Number of Days to Update: 15

Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 12/09/2020
Next Scheduled EDR Contact: 03/29/2021
Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA SAN LUIS OBISPO: CUPA Facility List
Cupa Facility List.

Date of Government Version: 07/27/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 75

Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

SAN MATEO COUNTY:

BI SAN MATEO: Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 02/20/2020
Date Data Arrived at EDR: 02/20/2020
Date Made Active in Reports: 04/24/2020
Number of Days to Update: 64

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 12/11/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Annually

LUST SAN MATEO: Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/29/2019
Date Data Arrived at EDR: 03/29/2019
Date Made Active in Reports: 05/29/2019
Number of Days to Update: 61

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 12/01/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA SANTA BARBARA: CUPA Facility Listing
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28

Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: No Update Planned

SANTA CLARA COUNTY:

CUPA SANTA CLARA: Cupa Facility List
Cupa facility list

Date of Government Version: 08/20/2020
Date Data Arrived at EDR: 08/20/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 81

Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

HIST LUST SANTA CLARA: HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22

Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LUST SANTA CLARA: LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014
Date Data Arrived at EDR: 03/05/2014
Date Made Active in Reports: 03/18/2014
Number of Days to Update: 13

Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

SAN JOSE HAZMAT: Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 11/03/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 82

Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA SANTA CRUZ: CUPA Facility List
CUPA facility listing.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 05/23/2017
Number of Days to Update: 90

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA SHASTA: CUPA Facility List
Cupa Facility List.

Date of Government Version: 06/15/2017
Date Data Arrived at EDR: 06/19/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 51

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

SOLANO COUNTY:

LUST SOLANO: Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 06/04/2019
Date Data Arrived at EDR: 06/06/2019
Date Made Active in Reports: 08/13/2019
Number of Days to Update: 68

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 06/03/2019
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

UST SOLANO: Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 08/25/2020
Date Data Arrived at EDR: 08/26/2020
Date Made Active in Reports: 09/16/2020
Number of Days to Update: 21

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 12/03/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

SONOMA COUNTY:

CUPA SONOMA: Cupa Facility List
Cupa Facility list

Date of Government Version: 12/15/2020
Date Data Arrived at EDR: 12/16/2020
Date Made Active in Reports: 12/23/2020
Number of Days to Update: 7

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Varies

LUST SONOMA: Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 09/18/2020
Date Data Arrived at EDR: 09/22/2020
Date Made Active in Reports: 12/14/2020
Number of Days to Update: 83

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 12/15/2020
Next Scheduled EDR Contact: 04/05/2021
Data Release Frequency: Quarterly

STANISLAUS COUNTY:

CUPA STANISLAUS: CUPA Facility List
Cupa facility list

Date of Government Version: 10/01/2020
Date Data Arrived at EDR: 10/06/2020
Date Made Active in Reports: 12/22/2020
Number of Days to Update: 77

Source: Stanislaus County Department of Ennvironmental Protection
Telephone: 209-525-6751
Last EDR Contact: 01/11/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Varies

SUTTER COUNTY:

UST SUTTER: Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 08/25/2020
Date Data Arrived at EDR: 08/26/2020
Date Made Active in Reports: 11/17/2020
Number of Days to Update: 83

Source: Sutter County Environmental Health Services
Telephone: 530-822-7500
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Semi-Annually

TEHAMA COUNTY:

CUPA TEHAMA: CUPA Facility List
Cupa facilities

Date of Government Version: 08/11/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 75

Source: Tehama County Department of Environmental Health
Telephone: 530-527-8020
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

TRINITY COUNTY:

CUPA TRINITY: CUPA Facility List
Cupa facility list

Date of Government Version: 10/14/2020
Date Data Arrived at EDR: 10/15/2020
Date Made Active in Reports: 01/05/2021
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 760-352-0381
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

TULARE COUNTY:

CUPA TULARE: CUPA Facility List
Cupa program facilities

Date of Government Version: 10/30/2020
Date Data Arrived at EDR: 11/03/2020
Date Made Active in Reports: 01/20/2021
Number of Days to Update: 78

Source: Tulare County Environmental Health Services Division
Telephone: 559-624-7400
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

TUOLUMNE COUNTY:

CUPA TUOLUMNE: CUPA Facility List
Cupa facility list

Date of Government Version: 04/23/2018
Date Data Arrived at EDR: 04/25/2018
Date Made Active in Reports: 06/25/2018
Number of Days to Update: 61

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Varies

VENTURA COUNTY:

BWT VENTURA: Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 09/28/2020
Date Data Arrived at EDR: 10/22/2020
Date Made Active in Reports: 01/12/2021
Number of Days to Update: 82
Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 01/19/2021
Next Scheduled EDR Contact: 05/02/2021
Data Release Frequency: Quarterly

LF VENTURA: Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 12/21/2020
Next Scheduled EDR Contact: 04/12/2021
Data Release Frequency: No Update Planned

LUST VENTURA: Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: No Update Planned

MED WASTE VENTURA: Medical Waste Program List
To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 09/28/2020
Date Data Arrived at EDR: 10/22/2020
Date Made Active in Reports: 01/12/2021
Number of Days to Update: 82
Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 01/20/2021
Next Scheduled EDR Contact: 05/03/2021
Data Release Frequency: Quarterly

UST VENTURA: Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 08/26/2020
Date Data Arrived at EDR: 09/08/2020
Date Made Active in Reports: 12/01/2020
Number of Days to Update: 84
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 12/08/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Quarterly

YOLO COUNTY:

UST YOLO: Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 12/21/2020
Date Data Arrived at EDR: 12/23/2020
Date Made Active in Reports: 01/04/2021
Number of Days to Update: 12
Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 12/20/2020
Next Scheduled EDR Contact: 04/11/2021
Data Release Frequency: Annually

YUBA COUNTY:

CUPA YUBA: CUPA Facility List
CUPA facility listing for Yuba County.

Date of Government Version: 08/06/2020
Date Data Arrived at EDR: 08/07/2020
Date Made Active in Reports: 10/26/2020
Number of Days to Update: 80

Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 01/25/2021
Next Scheduled EDR Contact: 05/10/2021
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 10/20/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 13

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/08/2021
Next Scheduled EDR Contact: 04/19/2021
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 04/29/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/30/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/11/2021
Next Scheduled EDR Contact: 04/26/2021
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 10/02/2019
Date Made Active in Reports: 12/10/2019
Number of Days to Update: 69

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 12/03/2020
Next Scheduled EDR Contact: 03/22/2021
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

RESIDENTIAL PROPERTY
918 RICH AVENUE
MOUNTAIN VIEW, CA 94040

TARGET PROPERTY COORDINATES

Latitude (North):	37.389335 - 37° 23' 21.61''
Longitude (West):	122.094418 - 122° 5' 39.90''
Universal Tranverse Mercator:	Zone 10
UTM X (Meters):	580165.3
UTM Y (Meters):	4138244.5
Elevation:	105 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5641106 MOUNTAIN VIEW, CA
Version Date:	2012
South Map:	5640178 CUPERTINO, CA
Version Date:	2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NNE

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
06085C0038H	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
06085C0039H	FEMA FIRM Flood data
06085C0201H	FEMA FIRM Flood data
06085C0202H	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
MOUNTAIN VIEW	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Location Relative to TP:	1 - 2 Miles SW
Site Name:	Hillview Maintenance Yard
Site EPA ID Number:	CAD982400202
Groundwater Flow Direction:	NE ON A REGIONAL BASIS, WITH LOCAL FLOW CONDITIONS INFLUENCED BY PUMPING.
Inferred Depth to Water:	100 feet to 120 feet.
Hydraulic Connection:	Information is not available about the hydraulic connection between aquifers under the site.
Sole Source Aquifer:	No information about a sole source aquifer is available
Data Quality:	Information is inferred in the CERCLIS investigation report(s)

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW

* ©1996 Site--specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
G27	1/2 - 1 Mile NNW	NE
1G	1/2 - 1 Mile NNW	NE

For additional site information, refer to Physical Setting Source Map Findings.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Cenozoic
System:	Quaternary
Series:	Quaternary
Code:	Q *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Stratifed Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name:	BOTELLA
Soil Surface Texture:	clay loam
Hydrologic Group:	Class B - Moderate infiltration rates. Deep and moderately deep, moderately well and well drained soils with moderately coarse textures.
Soil Drainage Class:	Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel:	MODERATE
Depth to Bedrock Min:	> 60 inches
Depth to Bedrock Max:	> 60 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	9 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.60 Min: 0.20	Max: 7.30 Min: 5.60
2	9 inches	41 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 0.60 Min: 0.20	Max: 7.80 Min: 5.60
3	41 inches	76 inches	sandy clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	COARSE-GRAINED SOILS, Sands, Sands with fines, Clayey sand.	Max: 0.60 Min: 0.20	Max: 7.80 Min: 5.60

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: No Other Soil Types

Surficial Soil Types: No Other Soil Types

Shallow Soil Types: No Other Soil Types

Deeper Soil Types: No Other Soil Types

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
C15	USGS40000182869	1/2 - 1 Mile WNW
F21	USGS40000182665	1/2 - 1 Mile WSW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
11	CA4400500	1/2 - 1 Mile ESE

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
1	CADWR0000007045	1/4 - 1/2 Mile West
A2	CAEDF0000106832	1/2 - 1 Mile NNE
B3	6899	1/2 - 1 Mile SW
B4	6906	1/2 - 1 Mile SW
B5	6896	1/2 - 1 Mile SW
B6	6878	1/2 - 1 Mile SW
B7	6897	1/2 - 1 Mile SW
A8	CAEDF0000134715	1/2 - 1 Mile North
A9	CAEDF0000088693	1/2 - 1 Mile NNE
10	CADWR0000015878	1/2 - 1 Mile SSW
12	CADWR0000026753	1/2 - 1 Mile West
C13	CADDW0000021813	1/2 - 1 Mile WNW
C14	CAUSGSN00012487	1/2 - 1 Mile WNW
C16	CALLNL000000471	1/2 - 1 Mile WNW
D17	6862	1/2 - 1 Mile SE
D18	6891	1/2 - 1 Mile SE
E19	CADWR0000023207	1/2 - 1 Mile SW
20	6881	1/2 - 1 Mile North
F22	CALLNL000000463	1/2 - 1 Mile WSW
F23	CAUSGSN00014864	1/2 - 1 Mile WSW
F24	CADDW0000020379	1/2 - 1 Mile WSW
D25	CADDW0000016963	1/2 - 1 Mile SE
E26	CADDW0000004051	1/2 - 1 Mile SW
28	CADDW0000016706	1/2 - 1 Mile SE
G29	CADDW0000011795	1/2 - 1 Mile NNW
G30	CADDW0000022202	1/2 - 1 Mile NNW
31	CADDW0000015921	1/2 - 1 Mile North
H32	CAEDF0000107948	1/2 - 1 Mile NE
H33	CAEDF0000055135	1/2 - 1 Mile NE
H34	CAEDF0000116484	1/2 - 1 Mile NE
I35	6877	1/2 - 1 Mile NNW
I36	6874	1/2 - 1 Mile NNW
I37	6876	1/2 - 1 Mile NNW
38	CADDW0000009093	1/2 - 1 Mile NE
J39	CADWR0000003625	1/2 - 1 Mile South

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
J40	CADWR0000006219	1/2 - 1 Mile South
K41	CADDW0000015734	1/2 - 1 Mile South
42	CADWR0000011075	1/2 - 1 Mile SW
K43	CADDW0000022525	1/2 - 1 Mile South
L44	CADWR0000011775	1/2 - 1 Mile West
45	CADWR0000005785	1/2 - 1 Mile NW
L46	CALLNL000000546	1/2 - 1 Mile West
L47	CADDW0000019497	1/2 - 1 Mile West
M48	CAEDF0000013025	1/2 - 1 Mile North
N49	CADWR0000029790	1/2 - 1 Mile NNE
N50	CADWR0000028365	1/2 - 1 Mile NNE
M51	CAEDF0000126257	1/2 - 1 Mile North
M52	CAEDF0000062004	1/2 - 1 Mile North
M53	CAEDF0000128703	1/2 - 1 Mile North
M54	CAEDF0000049488	1/2 - 1 Mile North
M55	CAEDF0000082500	1/2 - 1 Mile North
M56	CAEDF0000126711	1/2 - 1 Mile North

PHYSICAL SETTING SOURCE MAP - 6348854.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Residential Property	CLIENT:	Env. Inv. Services, Inc.
ADDRESS:	918 Rich Avenue Mountain View CA 94040	CONTACT:	Peter Littman
		INQUIRY #:	6348854.2s
LAT/LONG:	37.389335 / 122.094418	DATE:	January 29, 2021 1:23 pm

Copyright © 2021 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
West
1/4 - 1/2 Mile
Higher

CA WELLS **CADWR0000007045**

Well ID:	06S02W29A001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W29A001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W29A001M&store_num=		
GeoTracker Data:	Not Reported		

A2
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000106832**

Well ID:	T10000005158-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000005158&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000005158&assigned_name=MW-3		

B3
SW
1/2 - 1 Mile
Higher

CA WELLS **6899**

Seq:	6899	Prim sta c:	06S/02W-32D01 M
Frds no:	4310001024	County:	43
District:	05	User id:	HEN
System no:	4310001	Water type:	G
Source nam:	WELL 104-02	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372300.0	Longitude:	1220600.0
Precision:	5	Status:	AU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	4310001	System nam:	Cwsc Los Altos Suburban
Hqname:	CALIFORNIA WTR SERV CO	Address:	949 B Street
City:	Los Altos	State:	CA
Zip:	94024	Zip ext:	Not Reported
Pop serv:	53940	Connection:	17895
Area serve:	LOS ALTOS		

Sample date:	23-JAN-18	Finding:	2.934
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	13-JUN-17	Finding:	2.936
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	15-JUN-16	Finding:	7.5
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	12.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	0.49
Chemical:	TURBIDITY, LABORATORY	Report units:	NTU
Dlr:	0.1		
Sample date:	15-JUN-16	Finding:	410.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	0.11
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)	Report units:	MG/L
Dlr:	0.1		
Sample date:	15-JUN-16	Finding:	44.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	15-JUN-16	Finding:	100.
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	2.1
Chemical:	POTASSIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	59.
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	24.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	49.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	220.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	1.2
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	15-JUN-16	Finding:	180.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	18.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported

Dlr:	0.		
Sample date:	15-JUN-16	Finding:	720.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	15-JUN-16	Finding:	150.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	20-JUL-15	Finding:	1.
Chemical:	TOTAL TRIHALOMETHANES	Report units:	UG/L
Dlr:	0.		
Sample date:	04-JUN-15	Finding:	7.2
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	04-JUN-15	Finding:	19.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	05-MAR-15	Finding:	18.8
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	05-MAR-15	Finding:	6.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	14-JAN-15	Finding:	18.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	14-JAN-15	Finding:	0.99
Chemical:	RADIUM 228 MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	14-JAN-15	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	18-DEC-14	Finding:	18.4
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	18-DEC-14	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	02-SEP-14	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	04-JUN-14	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	04-DEC-13	Finding:	6.7
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		

Sample date:	05-SEP-13	Finding:	7.19
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	18-JUN-13	Finding:	1.2
Chemical:	CHROMIUM, HEXAVALENT	Report units:	UG/L
Dlr:	1.		
Sample date:	03-JUN-13	Finding:	7.45
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	310.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	13.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	0.12
Chemical:	TURBIDITY, LABORATORY	Report units:	NTU
Dlr:	0.1		
Sample date:	12-MAR-13	Finding:	9.8
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	12-MAR-13	Finding:	0.85
Chemical:	LANGELIER INDEX @ 60 C	Report units:	Not Reported
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	460.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	46.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	12-MAR-13	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	18.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	18.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	770.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US

Dlr:	0.		
Sample date:	12-MAR-13	Finding:	8.
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	370.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	380.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	83.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	42.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	29.
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	12-MAR-13	Finding:	60.
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	19-DEC-12	Finding:	0.46
Chemical:	RADIUM 226 MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	19-DEC-12	Finding:	0.79
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	04-DEC-12	Finding:	6.7
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	05-SEP-12	Finding:	7.15
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	04-JUN-12	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	07-MAR-12	Finding:	7.4
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		

B4
SW
1/2 - 1 Mile
Higher

CA WELLS **6906**

Seq:	6906	Prim sta c:	06S/02W-34G02 M
Frds no:	4310001037	County:	43

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

District:	05	User id:	HEN
System no:	4310001	Water type:	G
Source nam:	ZANETTI WELL	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372300.0	Longitude:	1220600.0
Precision:	5	Status:	AU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	4310001	System nam:	Cwsc Los Altos Suburban
Hqname:	CALIFORNIA WTR SERV CO	Address:	949 B Street
City:	Los Altos	State:	CA
Zip:	94024	Zip ext:	Not Reported
Pop serv:	53940	Connection:	17895
Area serve:	LOS ALTOS		

Sample date:	20-FEB-18	Finding:	3.795
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	28-NOV-17	Finding:	2.6
Chemical:	CHROMIUM, HEXAVALENT	Report units:	UG/L
Dlr:	1.		

Sample date:	14-NOV-17	Finding:	3.787
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	16-AUG-17	Finding:	3.801
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	16-MAY-17	Finding:	3.734
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	14-FEB-17	Finding:	3.811
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	05-DEC-16	Finding:	4.065
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	15-NOV-16	Finding:	4.107
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	10-AUG-16	Finding:	0.22
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		

Sample date:	10-AUG-16	Finding:	1.3
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		

Sample date:	10-AUG-16	Finding:	18.7
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		

Sample date:	10-AUG-16	Finding:	7.5

Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	10-AUG-16	Finding:	19.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	10-AUG-16	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	460.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	0.22
Chemical:	LANGELIER INDEX @ 60 C	Report units:	Not Reported
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	0.28
Chemical:	TURBIDITY, LABORATORY	Report units:	NTU
Dlr:	0.1		
Sample date:	09-AUG-16	Finding:	12.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	180.
Chemical:	BARIUM	Report units:	UG/L
Dlr:	100.		
Sample date:	09-AUG-16	Finding:	0.14
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)	Report units:	MG/L
Dlr:	0.1		
Sample date:	09-AUG-16	Finding:	46.
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	26.
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	30.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	110.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	390.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	4.
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	09-AUG-16	Finding:	330.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		

Sample date:	09-AUG-16	Finding:	270.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	7.3
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	760.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	19.1
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	09-AUG-16	Finding:	54.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	17-MAY-16	Finding:	3.877
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	08-FEB-16	Finding:	4.55
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	16-NOV-15	Finding:	6.313
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	11-AUG-15	Finding:	34.523
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	16-JUN-15	Finding:	33.651
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	27-MAY-15	Finding:	17.2
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	27-MAY-15	Finding:	7.
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	10-MAR-15	Finding:	24.256
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	04-FEB-15	Finding:	7.6
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	04-FEB-15	Finding:	17.2
Chemical:	SOURCE TEMPERATURE C	Report units:	C

Dlr:	0.		
Sample date:	16-DEC-14	Finding:	20.032
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	04-NOV-14	Finding:	18.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	04-NOV-14	Finding:	8.8
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	16-SEP-14	Finding:	33.819
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	06-AUG-14	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	08-MAY-14	Finding:	6.8
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	10-MAR-14	Finding:	31.253
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	05-FEB-14	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	10-DEC-13	Finding:	20.923
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	05-NOV-13	Finding:	6.59
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	22-OCT-13	Finding:	3.
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	22-OCT-13	Finding:	4.
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	06-AUG-13	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	12-JUN-13	Finding:	2.6
Chemical:	CHROMIUM, HEXAVALENT	Report units:	UG/L
Dlr:	1.		
Sample date:	13-MAY-13	Finding:	6.9
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		

Sample date:	08-MAY-13	Finding:	7.7
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	07-FEB-13	Finding:	7.1
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	170.
Chemical:	BARIUM	Report units:	UG/L
Dlr:	100.		
Sample date:	16-JAN-13	Finding:	0.11
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)	Report units:	MG/L
Dlr:	0.1		
Sample date:	16-JAN-13	Finding:	46.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	16-JAN-13	Finding:	440.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	0.95
Chemical:	LANGELIER INDEX @ 60 C	Report units:	Not Reported
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	730.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	13.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	0.12
Chemical:	TURBIDITY, LABORATORY	Report units:	NTU
Dlr:	0.1		
Sample date:	16-JAN-13	Finding:	8.1
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	270.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	330.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	350.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	95.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	28.
Chemical:	MAGNESIUM	Report units:	MG/L

Dlr:	0.		
Sample date:	16-JAN-13	Finding:	45.
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	16-JAN-13	Finding:	23.
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	05-NOV-12	Finding:	7.2
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	07-AUG-12	Finding:	7.4
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	02-MAY-12	Finding:	7.1
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	27-FEB-12	Finding:	7.63
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		

B5
SW
1/2 - 1 Mile
Higher

CA WELLS 6896

Seq:	6896	Prim sta c:	06S/02W-29J02 M
Frds no:	4310001025	County:	43
District:	05	User id:	HEN
System no:	4310001	Water type:	G
Source nam:	WELL 107-01 - DESTROYED	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372300.0	Longitude:	1220600.0
Precision:	4	Status:	DS
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	4310001	System nam:	Cwsc Los Altos Suburban
Hqname:	CALIFORNIA WTR SERV CO	Address:	949 B Street
City:	Los Altos	State:	CA
Zip:	94024	Zip ext:	Not Reported
Pop serv:	53940	Connection:	17895
Area serve:	LOS ALTOS		

B6
SW
1/2 - 1 Mile
Higher

CA WELLS 6878

Seq:	6878	Prim sta c:	06S/02W-20L03 M
Frds no:	4310001030	County:	43
District:	05	User id:	HEN
System no:	4310001	Water type:	G
Source nam:	WELL 119-03	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Latitude:	372300.0	Longitude:	1220600.0
Precision:	5	Status:	AU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	4310001	System nam:	Cwsc Los Altos Suburban
Hqname:	CALIFORNIA WTR SERV CO	Address:	949 B Street
City:	Los Altos	State:	CA
Zip:	94024	Zip ext:	Not Reported
Pop serv:	53940	Connection:	17895
Area serve:	LOS ALTOS		

Sample date:	23-JAN-18	Finding:	3.913
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	06-DEC-17	Finding:	3.988
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	12-SEP-17	Finding:	3.903
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	09-AUG-17	Finding:	1.6
Chemical:	CHROMIUM, HEXAVALENT	Report units:	UG/L
Dlr:	1.		

Sample date:	13-JUN-17	Finding:	3.894
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	15-MAR-17	Finding:	3.872
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	05-DEC-16	Finding:	3.777
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	21-SEP-16	Finding:	3.87
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	20-JUN-16	Finding:	3.785
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	23-MAR-16	Finding:	28.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		

Sample date:	23-MAR-16	Finding:	440.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		

Sample date:	23-MAR-16	Finding:	0.73
Chemical:	LANGELIER INDEX @ 60 C	Report units:	Not Reported
Dlr:	0.		

Sample date:	23-MAR-16	Finding:	0.14
Chemical:	TURBIDITY, LABORATORY	Report units:	NTU
Dlr:	0.1		
Sample date:	23-MAR-16	Finding:	13.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	43.
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	26.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	84.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	320.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	3.5
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	23-MAR-16	Finding:	360.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	290.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	7.6
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	780.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	23-MAR-16	Finding:	42.
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	30-NOV-15	Finding:	3.924
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	04-JUN-15	Finding:	7.6
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	04-JUN-15	Finding:	21.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	05-MAR-15	Finding:	20.3
Chemical:	SOURCE TEMPERATURE C	Report units:	C

Dlr:	0.		
Sample date:	05-MAR-15	Finding:	6.6
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	18-DEC-14	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	18-DEC-14	Finding:	19.4
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	02-SEP-14	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	04-JUN-14	Finding:	20.373
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	04-JUN-14	Finding:	7.2
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	10-MAR-14	Finding:	20.533
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	05-MAR-14	Finding:	7.5
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	16-DEC-13	Finding:	1.8
Chemical:	CHROMIUM, HEXAVALENT	Report units:	UG/L
Dlr:	1.		
Sample date:	10-DEC-13	Finding:	23.832
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	04-DEC-13	Finding:	6.7
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	18-SEP-13	Finding:	23.915
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	05-SEP-13	Finding:	7.19
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	19-JUN-13	Finding:	23.707
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	18-JUN-13	Finding:	1.9
Chemical:	CHROMIUM, HEXAVALENT	Report units:	UG/L
Dlr:	1.		

Sample date:	03-JUN-13	Finding:	7.23
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	18.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	13.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	0.36
Chemical:	TURBIDITY, LABORATORY	Report units:	NTU
Dlr:	0.1		
Sample date:	13-MAR-13	Finding:	1.
Chemical:	LANGELIER INDEX @ 60 C	Report units:	Not Reported
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	440.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	32.
Chemical:	MANGANESE	Report units:	UG/L
Dlr:	20.		
Sample date:	13-MAR-13	Finding:	41.
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	44.
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	24.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	80.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	300.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	360.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	300.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	8.2
Chemical:	PH, LABORATORY	Report units:	Not Reported

Dlr:	0.		
Sample date:	13-MAR-13	Finding:	740.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	18.
Chemical:	SOURCE TEMPERATURE C	Report units:	C
Dlr:	0.		
Sample date:	13-MAR-13	Finding:	26.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	19-DEC-12	Finding:	0.39
Chemical:	RADIUM 226 MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	19-DEC-12	Finding:	0.15
Chemical:	RADIUM 226 COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	19-DEC-12	Finding:	2.9
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	19-DEC-12	Finding:	3.1
Chemical:	GROSS ALPHA	Report units:	PCI/L
Dlr:	3.		
Sample date:	19-DEC-12	Finding:	3.
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	04-DEC-12	Finding:	21.113
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	04-DEC-12	Finding:	7.1
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	11-SEP-12	Finding:	24.349
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	05-SEP-12	Finding:	7.49
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		
Sample date:	06-JUN-12	Finding:	24.846
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	04-JUN-12	Finding:	7.3
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		

Sample date:	13-MAR-12	Finding:	22.96
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	07-MAR-12	Finding:	7.8
Chemical:	PH, FIELD	Report units:	Not Reported
Dlr:	0.		

B7
SW
1/2 - 1 Mile
Higher

CA WELLS **6897**

Seq:	6897	Prim sta c:	06S/02W-29K05 M
Frds no:	4310001026	County:	43
District:	05	User id:	HEN
System no:	4310001	Water type:	G
Source nam:	WELL 108-01 - INACTIVE	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372300.0	Longitude:	1220600.0
Precision:	8	Status:	IU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	4310001	System nam:	Cwsc Los Altos Suburban
Hqname:	CALIFORNIA WTR SERV CO	Address:	949 B Street
City:	Los Altos	State:	CA
Zip:	94024	Zip ext:	Not Reported
Pop serv:	53940	Connection:	17895
Area serve:	LOS ALTOS		

A8
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000134715**

Well ID:	T10000005158-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000005158&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000005158&assigned_name=MW-1		

A9
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000088693**

Well ID:	T10000005158-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000005158&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000005158&assigned_name=MW-2		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

10
SSW
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000015878**

Well ID:	06S02W28M001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W28M001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W28M001M&store_num=		
GeoTracker Data:	Not Reported		

11
ESE
1/2 - 1 Mile
Higher

FRDS PWS **CA4400500**

PWS ID:	CA4400500	PWS type:	System Owner/Responsible Party
PWS name:	CALABASAS WATER CORP	PWS address:	Not Reported
PWS city:	MOUNTAIN VIEW	PWS state:	CA
PWS zip:	94040	PWS ID:	CA4400500
Activity status:	Active	Date system activated:	7706
Date system deactivated:	Not Reported	Retail population:	00000026
System name:	CALABASAS WATER CORP	System address:	CALABASAS WATER CORP
System address:	CALABASAS RD	System city:	WATSONVILLE
System state:	CA	System zip:	95076
Population served:	Under 101 Persons	Treatment:	Untreated
Latitude:	372309	Longitude:	1220458

12
West
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000026753**

Well ID:	06S02W29B002M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W29B002M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W29B002M&store_num=		
GeoTracker Data:	Not Reported		

C13
WNW
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000021813**

Well ID:	4310001-030	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 119-03	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310001-030&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C14
WNW
1/2 - 1 Mile
Higher

CA WELLS **CAUSGSN00012487**

Well ID:	USGS-372332122062101	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-372332122062101	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-372332122062101&store_num=		
GeoTracker Data:	Not Reported		

C15
WNW
1/2 - 1 Mile
Higher

FED USGS **USGS40000182869**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	006S002W20L003M	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	California Coastal Basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19600429	Well Depth:	504
Well Depth Units:	ft	Well Hole Depth:	805
Well Hole Depth Units:	ft		

C16
WNW
1/2 - 1 Mile
Higher

CA WELLS **CALLNL000000471**

Well ID:	100964	Well Type:	MUNICIPAL
Source:	Lawrence Livermore National Laboratory		
Other Name:	06S/02W-20L03 M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	Not Reported		
GeoTracker Data:	Not Reported		

Chemical:	Helium-3/Helium-4	Results:	.00000145184
Units:	atom ratio	Date:	11/20/2001
Chemical:	Helium-4	Results:	.000000275826
Units:	cm3STP/g	Date:	11/20/2001
Chemical:	Neon	Results:	.00000111976
Units:	cm3STP/g	Date:	11/20/2001
Chemical:	Argon	Results:	.000497232
Units:	cm3STP/g	Date:	11/20/2001

Chemical:	Krypton	Results:	.000000756909
Units:	cm3STP/g	Date:	11/20/2001
Chemical:	Tritium (Hydrogen 3)	Results:	2.94
Units:	pCi/L	Date:	05/31/2002

D17
SE
1/2 - 1 Mile
Higher

CA WELLS 6862

Seq:	6862	Prim sta c:	06S/02W-17R01 M
Frds no:	4310007006	County:	43
District:	05	User id:	HEN
System no:	4310007	Water type:	G
Source nam:	WELL 10 ALMA	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372300.0	Longitude:	1220500.0
Precision:	5	Status:	AU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	4310007	System nam:	City Of Mountain View
Hqname:	Not Reported	Address:	231 NORTH WHISMAN ROAD
City:	MOUNTAIN VIEW	State:	CA
Zip:	94043	Zip ext:	Not Reported
Pop serv:	69000	Connection:	15069
Area serve:	MOUNTAIN VIEW		

D18
SE
1/2 - 1 Mile
Higher

CA WELLS 6891

Seq:	6891	Prim sta c:	06S/02W-28D01 M
Frds no:	4310007002	County:	43
District:	05	User id:	HEN
System no:	4310007	Water type:	G
Source nam:	WELL 04 EL MONTE - ABANDONED	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372300.0	Longitude:	1220500.0
Precision:	4	Status:	AB
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	4310007	System nam:	City Of Mountain View
Hqname:	Not Reported	Address:	231 NORTH WHISMAN ROAD
City:	MOUNTAIN VIEW	State:	CA
Zip:	94043	Zip ext:	Not Reported
Pop serv:	69000	Connection:	15069
Area serve:	MOUNTAIN VIEW		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E19
SW
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000023207**

Well ID:	06S02W29J002M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W29J002M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W29J002M&store_num=		
GeoTracker Data:	Not Reported		

20
North
1/2 - 1 Mile
Lower

CA WELLS **6881**

Seq:	6881	Prim sta c:	06S/02W-21D08 M
Frds no:	4310007009	County:	43
District:	05	User id:	HEN
System no:	4310007	Water type:	G
Source nam:	WELL 17 RECREATION	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372359.0	Longitude:	1220539.0
Precision:	2	Status:	AU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	4310007	System nam:	City Of Mountain View
Hqname:	Not Reported	Address:	231 NORTH WHISMAN ROAD
City:	MOUNTAIN VIEW	State:	CA
Zip:	94043	Zip ext:	Not Reported
Pop serv:	69000	Connection:	15069
Area serve:	MOUNTAIN VIEW		

Sample date:	04-FEB-14	Finding:	25.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		

Sample date:	06-NOV-13	Finding:	24.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		

Sample date:	14-AUG-13	Finding:	29.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		

Sample date:	21-MAY-13	Finding:	0.15
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)	Report units:	MG/L
Dlr:	0.1		

Sample date:	21-MAY-13	Finding:	26.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		

Sample date:	15-NOV-12	Finding:	27.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L

Dlr:	2.		
Sample date:	07-AUG-12	Finding:	32.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	29-MAY-12	Finding:	25.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		

F21
WSW
1/2 - 1 Mile
Higher

FED USGS **USGS40000182665**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	006S002W29B002M	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	California Coastal Basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	695
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

F22
WSW
1/2 - 1 Mile
Higher

CA WELLS **CALLNL000000463**

Well ID:	100965	Well Type:	MUNICIPAL
Source:	Lawrence Livermore National Laboratory		
Other Name:	06S/02W-29B02 M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	Not Reported		
GeoTracker Data:	Not Reported		
Chemical:	Helium-3/Helium-4	Results:	.00000153447
Units:	atom ratio	Date:	11/20/2001
Chemical:	Xenon	Results:	.00000000289569
Units:	cm3STP/g	Date:	11/20/2001
Chemical:	Helium-4	Results:	.00000015009
Units:	cm3STP/g	Date:	11/20/2001
Chemical:	Krypton	Results:	.000000110575
Units:	cm3STP/g	Date:	11/20/2001
Chemical:	Tritium (Hydrogen 3)	Results:	2.2
Units:	pCi/L	Date:	02/28/2002

Chemical:	Argon	Results:	.000488038
Units:	cm3STP/g	Date:	11/20/2001
Chemical:	Neon	Results:	.000000609745
Units:	cm3STP/g	Date:	11/20/2001

F23
WSW **CA WELLS** **CAUSGSN00014864**
1/2 - 1 Mile
Higher

Well ID:	USGS-372303122062101	Well Type:	UNK
Source:	United States Geological Survey		
Other Name:	USGS-372303122062101	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=USGSNEW&samp_date=&global_id=&assigned_name=USGS-372303122062101&store_num=		
GeoTracker Data:	Not Reported		

F24
WSW **CA WELLS** **CADDW0000020379**
1/2 - 1 Mile
Higher

Well ID:	4310001-029	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 116-01	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310001-029&store_num=		
GeoTracker Data:	Not Reported		

D25
SE **CA WELLS** **CADDW0000016963**
1/2 - 1 Mile
Higher

Well ID:	4310007-002	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 04 EL MONTE - ABANDONED		
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310007-002&store_num=		
GeoTracker Data:	Not Reported		

E26
SW **CA WELLS** **CADDW0000004051**
1/2 - 1 Mile
Higher

Well ID:	4310001-026	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 108-01 - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310001-026&store_num=		

GeoTracker Data: Not Reported

G27
NNW
1/2 - 1 Mile
Lower

AQUIFLOW **50011**

Site ID:	41-1012
Groundwater Flow:	NE
Shallow Water Depth:	8.26
Deep Water Depth:	11.52
Average Water Depth:	Not Reported
Date:	10/27/1998

28
SE
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000016706**

Well ID:	4310007-029	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 23	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310007-029&store_num=		
GeoTracker Data:	Not Reported		

G29
NNW
1/2 - 1 Mile
Lower

CA WELLS **CADDW0000011795**

Well ID:	4310001-039	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	NLA CUTTER - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310001-039&store_num=		
GeoTracker Data:	Not Reported		

G30
NNW
1/2 - 1 Mile
Lower

CA WELLS **CADDW0000022202**

Well ID:	4310001-044	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	NLA MOSHER 02 - DESTROYED	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310001-044&store_num=		
GeoTracker Data:	Not Reported		

31
North
1/2 - 1 Mile
Lower

CA WELLS **CADDW0000015921**

Well ID:	4310007-009	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL NO. 17 - INACTIVE	GAMA PFAS Testing:	Not Reported

Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310007-009&store_num=
GeoTracker Data: Not Reported

H32
NE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000107948**

Well ID:	T10000000686-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		

Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000686&assigned_name=MW-3&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000686&assigned_name=MW-3

H33
NE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000055135**

Well ID:	T10000000686-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		

Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000686&assigned_name=MW-1&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000686&assigned_name=MW-1

H34
NE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000116484**

Well ID:	T10000000686-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		

Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000686&assigned_name=MW-2&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000686&assigned_name=MW-2

I35
NNW
1/2 - 1 Mile
Lower

CA WELLS **6877**

Seq:	6877	Prim sta c:	06S/02W-20L02 M
Frds no:	4310001044	County:	43
District:	05	User id:	HEN
System no:	4310001	Water type:	G
Source nam:	NLA MOSHER 02 - DESTROYED	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372400.0	Longitude:	1220600.0

Precision:	4	Status:	DS
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	4310001	System nam:	Cwsc Los Altos Suburban
Hqname:	CALIFORNIA WTR SERV CO	Address:	949 B Street
City:	Los Altos	State:	CA
Zip:	94024	Zip ext:	Not Reported
Pop serv:	53940	Connection:	17895
Area serve:	LOS ALTOS		

I36
NNW
1/2 - 1 Mile
Lower

CA WELLS 6874

Seq:	6874	Prim sta c:	06S/02W-20F03 M
Frds no:	4310001039	County:	43
District:	05	User id:	HEN
System no:	4310001	Water type:	G
Source nam:	NLA CUTTER - DESTROYED	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372400.0	Longitude:	1220600.0
Precision:	8	Status:	DS
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	4310001	System nam:	Cwsc Los Altos Suburban
Hqname:	CALIFORNIA WTR SERV CO	Address:	949 B Street
City:	Los Altos	State:	CA
Zip:	94024	Zip ext:	Not Reported
Pop serv:	53940	Connection:	17895
Area serve:	LOS ALTOS		

I37
NNW
1/2 - 1 Mile
Lower

CA WELLS 6876

Seq:	6876	Prim sta c:	06S/02W-20L01 M
Frds no:	4310001043	County:	43
District:	05	User id:	HEN
System no:	4310001	Water type:	G
Source nam:	NLA MOSHER 01 - DESTROYED	Station ty:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Latitude:	372400.0	Longitude:	1220600.0
Precision:	4	Status:	DS
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	4310001	System nam:	Cwsc Los Altos Suburban
Hqname:	CALIFORNIA WTR SERV CO	Address:	949 B Street
City:	Los Altos	State:	CA
Zip:	94024	Zip ext:	Not Reported
Pop serv:	53940	Connection:	17895
Area serve:	LOS ALTOS		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

38
NE
1/2 - 1 Mile
Lower

CA WELLS **CADDW0000009093**

Well ID:	4310007-016	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 22	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310007-016&store_num=		
GeoTracker Data:	Not Reported		

J39
South
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000003625**

Well ID:	06S02W28N001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W28N001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W28N001M&store_num=		
GeoTracker Data:	Not Reported		

J40
South
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000006219**

Well ID:	06S02W28N002M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W28N002M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W28N002M&store_num=		
GeoTracker Data:	Not Reported		

K41
South
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000015734**

Well ID:	4310001-006	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 004-02 - INACTIVE	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310001-006&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

42
SW
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000011075**

Well ID:	06S02W29K005M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W29K005M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W29K005M&store_num=		
GeoTracker Data:	Not Reported		

K43
South
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000022525**

Well ID:	4310001-005	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 004-01 - INACTIVE	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310001-005&store_num=		
GeoTracker Data:	Not Reported		

L44
West
1/2 - 1 Mile
Higher

CA WELLS **CADWR0000011775**

Well ID:	06S02W29C002M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W29C002M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W29C002M&store_num=		
GeoTracker Data:	Not Reported		

45
NW
1/2 - 1 Mile
Lower

CA WELLS **CADWR0000005785**

Well ID:	06S02W20G002M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W20G002M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W20G002M&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

L46
West
1/2 - 1 Mile
Higher

CA WELLS **CALLNL000000546**

Well ID:	101155	Well Type:	MUNICIPAL
Source:	Lawrence Livermore National Laboratory		
Other Name:	06S/02W-20N01 M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	Not Reported		
GeoTracker Data:	Not Reported		

Chemical:	Helium-3/Helium-4	Results:	.0000014935
Units:	atom ratio	Date:	04/04/2002

Chemical:	Helium-4	Results:	.000000255233
Units:	cm3STP/g	Date:	04/04/2002

Chemical:	Argon	Results:	.000814042
Units:	cm3STP/g	Date:	04/04/2002

Chemical:	Tritium (Hydrogen 3)	Results:	9.14
Units:	pCi/L	Date:	01/03/2002

L47
West
1/2 - 1 Mile
Higher

CA WELLS **CADDW0000019497**

Well ID:	4310001-028	Well Type:	MUNICIPAL
Source:	Department of Health Services		
Other Name:	WELL 115-01	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=4310001-028&store_num=		
GeoTracker Data:	Not Reported		

M48
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000013025**

Well ID:	T0608501243-MW-22R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-22R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608501243&assigned_name=MW-22R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608501243&assigned_name=MW-22R		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

N49
NNE
1/2 - 1 Mile
Lower

CA WELLS **CADWR0000029790**

Well ID:	06S02W21B001M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W21B001M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W21B001M&store_num=		
GeoTracker Data:	Not Reported		

N50
NNE
1/2 - 1 Mile
Lower

CA WELLS **CADWR0000028365**

Well ID:	06S02W21B002M	Well Type:	UNK
Source:	Department of Water Resources		
Other Name:	06S02W21B002M	GAMA PFAS Testing:	Not Reported
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DWR&samp_date=&global_id=&assigned_name=06S02W21B002M&store_num=		
GeoTracker Data:	Not Reported		

M51
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000126257**

Well ID:	T0608501243-MW-22	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608501243&assigned_name=MW-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608501243&assigned_name=MW-22		

M52
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000062004**

Well ID:	T0608501243-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608501243&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608501243&assigned_name=MW-14		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

M53
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000128703**

Well ID:	T0608501243-MW-24R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-24R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608501243&assigned_name=MW-24R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608501243&assigned_name=MW-24R		

M54
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000049488**

Well ID:	T0608501243-MW-24	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608501243&assigned_name=MW-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608501243&assigned_name=MW-24		

M55
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000082500**

Well ID:	T0608501243-MW-25	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-25
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608501243&assigned_name=MW-25&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608501243&assigned_name=MW-25		

M56
North
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000126711**

Well ID:	T0608501243-MW-25R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-25R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608501243&assigned_name=MW-25R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608501243&assigned_name=MW-25R		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
1G **NNW** **1/2 - 1 Mile** **Lower**	Site ID:	41-1012	**AQUIFLOW**	**50011**
	Groundwater Flow:	NE		
	Shallow Water Depth:	8.26		
	Deep Water Depth:	11.52		
	Average Water Depth:	Not Reported		
	Date:	10/27/1998		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
94040	35	0

Federal EPA Radon Zone for SANTA CLARA County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 94040

Number of sites tested: 3

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.600 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

OTHER STATE DATABASE INFORMATION

Groundwater Ambient Monitoring & Assessment Program
State Water Resources Control Board
Telephone: 916-341-5577
The GAMA Program is Californias comprehensive groundwater quality monitoring program. GAMA collects data by testing the untreated, raw water in different types of wells for naturally-occurring and man-made chemicals. The GAMA data includes Domestic, Monitoring and Municipal well types from the following sources, Department of Water Resources, Department of Heath Services, EDF, Agricultural Lands, Lawrence Livermore National Laboratory, Department of Pesticide Regulation, United States Geological Survey, Groundwater Ambient Monitoring and Assessment Program and Local Groundwater Projects.

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Public Health
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

California Oil and Gas Well Locations
Source: Dept of Conservation, Geologic Energy Management Division
Telephone: 916-323-1779
Oil and Gas well locations in the state.

California Earthquake Fault Lines
Source: California Division of Mines and Geology
The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

RADON

State Database: CA Radon
Source: Department of Public Health
Telephone: 916-210-8558
Radon Database for California

PHYSICAL SETTING SOURCE RECORDS SEARCHED

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

PHASE II LIMITED SUBSURFACE INVESTIGATION REPORT

918 RICH AVENUE
MOUNTAIN VIEW, CALIFORNIA

Planning Division
City of Mountain View
Received on
Dec 9, 2021

EIS, Inc. PROJECT #213-2

November 3, 2021

PREPARED FOR:

Mr. Greg Xiong
Ardenview Homes, LLC
Los Altos, California 94022

PREPARED BY:

ENVIRONMENTAL INVESTIGATION SERVICES, INC.
PH:408.656.1032

Table of Contents

1.0 Introduction 3
2.0 Background and Site Setting 3
3.0 GENERAL Scope of Work Outline 4
4.0 Temporary Soil Borings 5
4.1 Pre-Field Activities 5
4.2 Boring Installation and Sampling 5
4.3 Soil Vapor Sample Collection 5
4.4 Completion Activities 6
5.0 Laboratory Analyses 7
6.0 Findings 7
6.1 Geologic and Hydrologic Conditions 7
6.2 Soil Analytical Results 7
6.3 Soil Vapor Analytical Results 9
7.0 Quality Assurance/Quality Control 9
8.0 Conclusions 9
9.0 Recommendations 11
10.0 Limitations 11

Attachments:

Figures
Figure 1 – Site Location Map
Figure 2 - Boring Location Map

Tables
Table 1a – Soil Analytical Results Summary – TPH & VOCs
Table 1b – Soil Analytical Results Summary – PCBs & SVOCs
Table 1c – Soil Analytical Results Summary – Metals & Asbestos
Table 1d – Soil Analytical Results Summary – OCPs
Table 1e – Soil Analytical Results Summary – pH
Table 2 – Soil Vapor Analytical Results Summary

Appendices
Appendix A – Soil Boring Logs
Appendix B – Soil Vapor Field Logs
Appendix C – Soil Analytical Report
Appendix D – Soil Vapor Analytical Report

1.0 INTRODUCTION

Environmental Investigation Services, Inc. (EIS) appreciates the opportunity to work on the Rich Avenue project located at 918 Rich Avenue, Mountain View, California (the Site). A site map is presented as Figure 1. It is EIS's understanding that the subject Site is slated for residential redevelopment. A previous Phase I Environmental Site Assessment (ESA), completed by EIS for the Site in February 2021, identified a potential environmental concern and a potential vapor encroachment concern (PVEC) (see Section 2.0). The objective of this current investigation was to investigate these potential environmental concerns and determine if the Site has been adversely environmentally impacted by their presence. The details and results of the investigation are presented, herein.

2.0 BACKGROUND AND SITE SETTING

The approximately 0.72-acre (31,456-square feet) subject property is undeveloped in preparation of multifamily residential redevelopment. The entirety of the subject property is unpaved and undeveloped and several moderately sized trees exist along the perimeter the parcel. The parcel is surrounded by an approximately 8-foot-tall wood fence on all sides, except for the Rich Avenue entrance, which has a chain link fence. The subject property is accessed via a gate off the Rich Avenue frontage. An in-ground electrical utility vault and a fire hydrant were identified between the subject property gate and Rich Avenue.

EIS' Phase I ESA prepared February 2021 (EIS, 2021) identified obvious subject property uses from the present back to 1939, at which time the subject property appeared to be undeveloped pastureland. By 1948 a small structure was visible on the eastern portion of the subject property and was visible in aerial photographs until 2006. The subject property has remained undeveloped since 2006. A 2018 aerial photograph obtained from Google Earth shows showed the subject property in use as an apparent storage yard with numerous containers along the perimeter and large soil stockpiles visible in the northwestern portion of the property.

Surrounding properties appeared to be in similar use as the subject property in 1939 with all adjoining properties undeveloped pastures, except for a large warehouse structure occupying the northwestern adjoining property, and orchards beyond in all directions. By 1948, a residence was visible on the southern adjoining property and a rectangular warehouse was visible on the northeastern adjoining property. By 1956, the western and southwestern adjoining properties were developed with structures roughly matching the current. The northeastern residential complex was developed by 1963, and the large warehouse on the northwestern adjoining property appeared to be in use as a lumber

yard by 1963. The northwestern adjoining lumber yard was redeveloped to match the current by 1998. Notable occupants of the adjoining properties include a Chevron gas station (northwestern adjoining property, 1969-1972), and Blue Bird Dry Cleaners (northwestern adjoining property, 1996 to present).

This previous Phase I ESA revealed the following environmental concerns in connection with the subject property:

- The presence of soil stockpiles in the northwestern portion of the subject property between June 2017 and July 2019 without any documentation as to the origin or use of the stockpiles represents a potential environmental concern.

- The various commercial uses of the northwestern adjoining properties, including dry cleaning and gas station, represent a potential vapor encroachment concern (PVEC).

Prior to redevelopment of subject property for residential uses, EIS recommended a Phase 2 subsurface investigation to address the potential environmental concern and vapor encroachment concern. Based upon these findings this current investigation was initiated. The details of the investigation, including the sampling activities, analytical results, and findings of the investigation, are presented herein.

3.0 GENERAL SCOPE OF WORK OUTLINE

EIS completed the following tasks to meet general investigation requirements:

- Notified USA North of the proposed boring locations to clear potential conflicts with underground utilities.
- Contracted with a licensed C-57 drilling contractor to advance soil borings using truck-mounted Geoprobe equipment.
- Advanced three temporary borings (SB-1 through SB-3) in the locations depicted on Figure 2. Soil borings were advanced to approximately 2.5-feet below ground surface (bgs) in order to collect soil samples. A total of 6 soil samples were collected and retained for laboratory analysis. Selected samples were analyzed for total petroleum hydrocarbons (TPH) as gasoline, diesel, and motor oil range organics (GRO, DRO, & MRO), volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), organochlorine pesticides (OCPs), polychlorinated biphenyls (PCBs), Cam-17 metals, asbestos, and pH. Due to soil sample volume limitations, analyses for GRO, DRO, and MRO, VOCs, SVOCs, OCPs, PCBs, and Cam-17 metals were run on the shallow (0.5-1.0-feet bgs) samples while bulk asbestos and pH analyses were run on the corresponding deeper (2.0-2.5-feet bgs) samples.

- Advanced three temporary 5.5-foot soil vapor borings (SV-1 through SV-3) in the approximate locations depicted on Figure 2. Each of these borings was converted into temporary soil vapor wells for the collection of soil vapor samples.
- Analyzed soil vapor samples for GRO and VOCs.
- Transferred soil and soil vapor samples to a State-certified laboratory under chain of custody documentation. The samples were analyzed for select constituents by the appropriate USEPA methods.
- Prepared this professional technical report to present the sampling activities, analytical results, and findings of the investigation.

4.0 TEMPORARY SOIL BORINGS

4.1 PRE-FIELD ACTIVITIES

Prior to all drilling work, the Site was delineated with white marking paint and Underground Service Alert was contacted at least two working days (48 hours) prior to boring advancement, as required by law, for utility line location and marking.

4.2 BORING INSTALLATION AND SAMPLING

EIS advanced a total of three soil borings for the current investigation using truck-mounted Geoprobe™ equipment. SB-1 through SB-3 were advanced for the purpose of soil sample collection. EIS contracted with Environmental Control Associates (ECA), a California-licensed C-57 drilling contractor (Lic. No. 655970), to advance the borings. The drilling equipment was cleaned prior to drilling and prior to leaving the Site. The borings were advanced by hydraulically pushing the Geoprobe sampling device to the desired sampling depths. The boring locations are shown on Figure 2. Soil encountered in boreholes was logged using Unified Soil Classification System (USCS) guidelines for texture, relative moisture content, odor, and other observable characteristics. Soil boring logs are provided as Appendix A.

The soil borings SB-1 through SB-3 were advanced to approximate depths of 2.5-feet bgs for the purpose of collecting soil samples at approximate depths of 0.5-1.0 and 2.0-2.5-feet bgs. A total of six soil samples were collected, two from each boring, in clean acetate sample liners with minimum headspace, sealed with Teflon sheets and plastic end-caps at both ends. All samples were labeled, logged onto chain-of-custody forms, and transported in a chilled ice chest on crushed ice to the laboratory.

4.3 SOIL VAPOR SAMPLE COLLECTION

Soil gas sampling was conducted following the general guidelines provided in the Department of Toxic Substances Control's (DTSC's) "Guidance for the Evaluation and

Mitigation of Subsurface Vapor Intrusion to Indoor Air" (DTSC, 2011) and "Advisory – Active Soil Gas Investigations" (DTSC et al, 2015).

EIS installed three temporary five-foot soil vapor sampling points (SV-1 through SV-3) in individual borings along the northern boundary of the Site. The approximate sampling locations are shown on Figure 2. Five-foot soil vapor sampling points SV-1 through SV-3) were installed by hydraulically advancing a two-inch core barrel through the unpaved ground surface to the desired sampling depth of approximately 5.5-feet bgs. Each soil vapor sampling point consisted of one preassembled soil vapor sampling tip connected to a length of polypropylene (Nylaflow®) tubing that extended approximately 2-feet above the surface to facilitate sample collection. The sampling tip was set midway within a 1-foot-thick sand-pack interval at the base of the boring, then topped with a 6-inch-thick interval of dry bentonite chips, followed by an interval of hydrated bentonite chips extending to the surface.

Each soil gas sample was collected using a SUMA® canister supplied by the contracted laboratory. Prior to the collection of a sample, the soil gas sampling point was purged of approximately three well volumes of air (soil gas) from the probe and tubing associated with the point using a 60-milliliter syringe attached to the Teflon tubing of the soil gas well. Once the well had been purged, a sample collection SUMA® canister was attached to the Teflon tubing of the sampling point, the initial negative pressure of the canister was measured (and recorded), and soil gas was delivered to the canister from the well until a negative pressure of about five-inches of Hg was noted on the vacuum gauge on the sample collection SUMA® canister. All vacuum readings were documented on the chain of custody record and field sampling logs. Soil gas samples were kept at ambient temperatures and transported to the laboratory under chain of custody record. Leak testing was performed during sample collection using isopropyl alcohol (IPA) as a leak-check compound. This was accomplished by applying IPA with a clean towel to all aboveground fittings in the sampling train and placing an IPA-saturated towel adjacent to the borehole and beneath the sampling shroud. Soil vapor sampling locations are depicted on Figure 2. Soil vapor field sampling logs are provided as Appendix B.

4.4 COMPLETION ACTIVITIES

All drill cuttings and equipment decontamination wash and rinse water were transported off-site in sealed containers by ECA for proper disposal. Upon completion of all sampling activities, the soil borings were backfilled to ground surface using neat cement grout. Surface patching activities complied with local regulations to repair paved surfaces to original condition.

5.0 LABORATORY ANALYSES

EIS used BC Laboratories, Inc. located in Bakersfield, California as the selected analytical laboratory for the soil, groundwater, and soil vapor samples. A total of 6 soil samples were transferred to BC Laboratories, Inc. and selected samples were analyzed for the following:

- TPH-GRO/DRO/MRO by USEPA 8015 (all 1-foot bgs samples)
- VOCs by USEPA Method 8260B (all 1-foot bgs samples)
- OCPs by USEPA Method 8081 (all 1-foot bgs samples)
- PCBs by USEPA Method 8082 (all 1-foot bgs samples)
- SVOCs by USEPA Method 8270 (all 1-foot bgs samples)
- CAM-17 Metals by USEPA Method 6060 (all 1-foot bgs samples)
- Bulk Asbestos by USEPA Method 600/R-93-116 (all 2.5-foot bgs samples)
- pH by USEPA Method 9045D (all 2.5-foot bgs samples)

A total of three soil vapor samples collected from the soil borings SV-1 through SV-3 were transferred to BC Laboratories, Inc. and samples analyzed for the following:

- TPH-GRO and VOCs by USEPA Method TO-15.

6.0 FINDINGS

6.1 GEOLOGIC AND HYDROLOGIC CONDITIONS

Native soils and sediments encountered in the borings generally consisted of dark yellowish brown to yellowish brown silty sands with varying amounts of gravel to a total explored depth of 5.5-feet bgs. An approximately 2-foot thick lens of clayey sand was encountered from 2-4-feet bgs in boring SV-3, and small pieces of mulch were encountered at variable depths in several of the borings. Groundwater was not encountered in any of the borings advanced during the completion of this investigation. A more detailed description of the encountered subsurface materials are depicted on the boring logs (Appendix A).

6.2 SOIL ANALYTICAL RESULTS

Soil samples were collected from borings SB-1 through SB-3 at approximate depths of 0.5-1.0 and 2.0-2.5-feet bgs. Soil analytical results are provided in Appendix C and summarized in Tables 1a through 1e. Analytical results were compared to Regional Water Quality Control Board (RWQCB) Environmental Screening Levels (ESLs) for residential and commercial/industrial use, as well as construction worker safety (RWQCB, 2019 Rev.

2). By definition, any detected concentration below its applicable ESL can be assumed to not pose a significant threat to human health, water resources, or the environment. Similarly, the presence of a chemical at concentrations in excess of an ESL does not necessarily indicate adverse effects on human health or the environment, rather that additional evaluation is warranted (RWQCB, 2019). Analyzed parameters were not detected in the soil samples above laboratory method detection limits (MDLs), except as follows:

- Arsenic was detected in analyzed soil samples SB-1-1, SB-2-1, and SB-3-1 at concentrations ranging from 2.6 to 4.2 mg/kg, which all exceed the most conservative residential ESL of 0.067 mg/kg.
- Cobalt was detected in analyzed soil samples SB-1-1 and SB-2-1 at concentrations of 24 and 24 mg/kg, respectively, which slightly exceed the most conservative residential ESL of 23 mg/kg.
- Nickel was detected in analyzed soil sample SB-1-1 at a concentration of 87 mg/kg, which slightly exceeds the most conservative construction worker health ESL of 86 mg/kg.
- Chromium was detected in all analyzed soil samples at concentrations ranging from 79 to 120 mg/kg. There are no established ESLs for chromium.
- Additional CAM-17 metals analytes antimony, barium, beryllium, copper, lead, mercury, molybdenum, silver, vanadium, and zinc were detected in various analyzed soil samples at concentrations well below their most conservative applied ESLs.
- DRO was detected in analyzed soil samples SB-1-1, SB-2-1, and SB-3-1 at concentrations ranging from 2.5 to 11 milligrams per kilogram (mg/kg), which are well below the most conservative residential ESL of 260 mg/kg.
- MRO was detected in analyzed soil samples SB-1-1, SB-2-1, and SB-3-1 at concentrations ranging from 29 to 160 mg/kg, which are well below the most conservative residential ESL of 260 mg/kg.
- PCB-1260 was detected in analyzed soil samples SB-1-1 and SB-3-1 at concentrations of 0.0087 and 0.044 mg/kg, respectively, which are well below the most conservative residential ESL of 0.23 mg/kg.
- OCP analytes Chlordane, 4,4'-DDD, 4,4'-DDE, 4,4'-DDT, and Dieldrin were detected in various analyzed soil samples at concentrations well below the their most conservative applied ESLs.
- pH results for analyzed soil samples SB-1-2.5, SB-2-2.5, and SB-3-2.5 ranged from 7.56 to 7.73, which are all within the range of naturally occurring soil pH.

6.3 SOIL VAPOR ANALYTICAL RESULTS

Soil vapor analytical results are provided in Appendix D and summarized in Table 2. Soil vapor results were compared to RWQCB ESLs for residential and commercial/industrial land use (RWQCB, 2019 Rev. 2).

- Benzene was detected in analyzed soil vapor sample SV-2 at a concentration of 20 µg/m^3, which exceeds the residential and commercial/industrial ESLs of 3.2 µg/m^3 and 14 µg/m^3, respectively.
- Additional VOC analytes GRO, acetone, methyl ethyl ketone, and methyl isobutyl ketone were detected in various analyzed soil vapor samples at concentration well below even their most conservative applied ESLs.
- Additional VOC analytes ethanol and propylene were also detected in various analyzed soil vapor samples. However, these analytes do not have established ESLs.

7.0 QUALITY ASSURANCE/QUALITY CONTROL

The analytical laboratory reports were reviewed by EIS. EIS verified that the holding times for each analytical method were achieved and that the laboratory achieved the specific data quality objectives for the selected analytical method. A review of the data validation process indicates that the laboratories completed QA/QC activities required for the samples such as blanks, lab control samples, matrix spikes, and duplicates. The QA/QC parameters for the samples were within acceptable limits and suggest that the data is useful for its intended purpose. In addition, the tracer compound isopropyl alcohol (IPA) was used to monitor the soil vapor probes and sample trains for leaks. IPA was detected in all analyzed soil vapor samples at low concentrations ranging from 12 to 40 µg/m^3. These detections represent a breakthrough of less than 1% which verifies the representativeness of the samples.

8.0 CONCLUSIONS

On October 19, 2021 EIS advanced a total of three exploratory soil borings (SB-1 through SB-3) to a depth of approximately 2.5-feet bgs as well as three soil vapor borings (SV-1 through SV-3) to a depth of approximately 5.5-feet bgs across the Site to collect soil and soil vapor samples. Based on the results of the current investigation EIS makes the following conclusions:

- Native soils and sediments encountered in the borings generally consisted of dark yellowish brown to yellowish brown silty sands with varying amounts of gravel to a total explored depth of 5.5-feet bgs. An approximately 2-foot thick lens of clayey sand was encountered from 2-4-feet bgs in boring SV-3, and small pieces of mulch were encountered at variable depths in several of the borings. Groundwater was not encountered in any of the borings advanced during the completion of this investigation.
- Benzene was detected in soil vapor sample SV-2 at a concentration of 20 µg/m^3, which exceeds the residential and commercial/industrial ESLs of 2.3 and 14 µg/m^3, respectively. EIS notes that benzene was not detected in any other soil or soil vapor samples collected during this investigation. As such, EIS concludes that benzene contamination in Site soil vapor appears highly localized to the immediate vicinity of SV-2. This finding represents a potential environmental concern.

- Cobalt was detected in analyzed soil samples SB-1-1 and SB-2-1 at concentrations of 24 and 24 mg/kg, respectively, which slightly exceed the most conservative residential ESL of 23 mg/kg. Additionally, nickel was detected in analyzed soil sample SB-1-1 at a concentration of 87 mg/kg, which slightly exceeds the most conservative construction worker health ESL of 86 mg/kg. Although these concentrations exceed the most conservative applied ESLs, the exceedances do not appear continuous and widespread and do not appear indicative of gross contamination of shallow soils at the Site. These findings represent a potential environmental concern.
- Arsenic was detected in analyzed soil samples SB-1-1, SB-2-1, and SB-3-1 at concentrations ranging from 2.6 to 4.2 mg/kg, which all exceed the most conservative residential ESL of 0.067 mg/kg. However, the detected arsenic concentrations are typical of background arsenic concentrations in the region. A study that analyzed regional soils in the San Francisco Bay Area reported the upper range of arsenic in soils to be 11 mg/kg (Duverge, 2011). Another study in the region found the upper background concentration for arsenic in soil to be 24 mg/kg (LBNL, 2009). EIS notes that the California Environmental Protection Agency (Cal EPA) and other agencies within California typically do not require cleanup of naturally occurring chemicals or metal species to less than background concentrations. Therefore, EIS concludes that the above-ESL arsenic detections are typical of background concentrations in the region and do not represent a significant environmental concern.

- Asbestos was not detected in any of the analyzed soil samples and soil pH values fall within the naturally occurring range of soil pH. These findings do not represent a significant environmental concern.

9.0 RECOMMENDATIONS

Based upon the findings of this investigation, EIS presents the following recommendations:

- Site soil vapor appears to be slightly impacted with benzene in the immediate vicinity of SV-2 and no on-site source or distribution has been identified. Following the conclusion of site redevelopment activities, confirmation indoor and outdoor air sampling may be warranted.

- Due to the slightly elevated cobalt and nickel concentrations found in soil during this investigation, EIS recommends that construction workers be made aware of any potential contamination that may be encountered during redevelopment of the property. Appropriate risk management strategies should be employed, including (but not limited to) dust control and proper usage of personal protective equipment (PPE) during activities which may disturb soils in the vicinity of the soil borings. If excessive amounts of soil are to be excavated and disposed of off-site, additional waste characterization sampling may be required prior to landfill acceptance.

10.0 LIMITATIONS

This report has been prepared specifically for the Site located at 918 Rich Avenue, Mountain View, California. The investigation was completed according to current state and local agency suggested guidance. The interpretations, conclusions, and recommendations made herein are based on the data and analysis for the samples collected on-site. Conditions at the Site can change over time and the use of this report by third parties is entirely at their own risk.

The soil borings can only present information accurately on the area directly at the point of the boring. They give a general indication of the condition of the Site but will not serve as a basis for a guarantee of non-contamination of the site. The conclusions and professional opinions presented are developed in accordance with generally accepted practice as outlined in applied standard guidance documents referenced in this report.

The chemical analysis results are based on data collected at the sampling locations only, therefore EIS cannot have complete knowledge of the underlying conditions. Conditions at the Site will change with time due to natural processes or the works of man.


Please note that reports of contamination must be submitted to the agencies in a timely manner. This report has been prepared for the sole use of our Clients. This report shall not be relied upon by or transferred to any other party, or used for any other purpose, without the express written authorization of our Client. EIS is not responsible for errors

neither in contract laboratory analysis and reporting, nor for information not available, nor unreported or unknown sources of Site contamination during the course of the study. Accordingly, the findings of this report will apply to the present conditions only; the opinions expressed therein are subject to revisions in consideration of new information, and no warranties are expressed or implied therein.

Please contact EIS at (408) 656-1032 if you have any questions regarding this report.
Sincerely,

Environmental Investigation Services, Inc.





Forrest Cook, PG #8201, exp 9/22
Professional Geologist

Lawrence Bush
Staff Geologist – G.I.T #1331

References

California Department of Toxic Substances Control and California Environmental Protection Agency (DTSC), 2011. *Final Guidance for the Evaluation and Mitigation of Subsurface Vapor Intrusion to Indoor Air (Vapor Intrusion Guidance)*. October 2011.


California Department of Toxic Substances Control and California Environmental Protection Agency (DTSC), February, 2020. *Supplemental Guidance: Screening and Evaluating Vapor Intrusion – Draft for Public Comments*.

California Environmental Protection Agency, Department of Toxic Substances Control, Los Angeles Regional Water Quality Control Board, and San Francisco Regional Water Quality Control Board (DTSC et al), 2015. *Advisory: Active Soil Gas Investigations*. July 2015.

Diamond, David, 2009, Lawrence Berkeley National Laboratory, *Analysis of Background Distribution of Metals in Soil at Lawrence Berkeley National Laboratory*, May 4, 2009.

San Francisco Bay Regional Water Quality Control Board (RWQCB), 2019, *Final, User's Guide Derivation and Application of Environmental Screening Levels*. January 2019, Rev. 2.

FIGURES




Environmental Investigation Services, Inc.
316 Mid Valley Center #313
Carmel, California 93923
Ph: (408) 656-1032

Site Location Map

918 Rich Avenue, Mountain View, California

Figure: 1
EIS Project: 2103-1
February 3, 2021



Environmental Investigation Services, Inc.
316 Mid Valley Center #313
Carmel, California 93923
Ph: (408) 656-1032

Boring Location Map

918 Rich Avenue, Mountain View, California

Figure: 2
EIS Project: 2103-2
November 2, 2021

TABLES

TABLE 1a
Soil Analytical Results Summary - TPH, VOCs
918 Rich Avenue, Mountain View, California
Project No. 2103-2

Sample ID	Sample Date	Sample Depth (ft)	TPH			VOCs
			GRO	DRO	MRO	All VOCs
SB-1-1	10/19/2021	0.5-1	<1	**3.1** A52	**29** A57	ND
SB-2-1	10/19/2021	0.5-1	<1	**2.5** A52	**33** A57	ND
SB-3-1	10/19/2021	0.5-1	<5 A10	**11** A10, A52	**160** A10, A57	ND
RWQCB ESLs (res)			**430**	**260**	**12,000**	**Various**
RWQCB ESLs (com/ind)			**2,000**	**1,200**	**180,000**	**Various**
RWQCB ESLs (Construction Worker)			**1,800**	**1,100**	**54,000**	**Various**

Notes:
TPH = total petroleum hydrocarbons
GRO/DRO/MRO= gasoline/diesel/motor oil range organics.
Sample results reported in milligrams per kilogram (mg/kg).
Bolded value denotes analyte detected
<1.0 = not detected above analytical laboratory Method Detection Limit (MDL)
VOCs analyzed by USEPA Method 8260B
GRO/DRO/MRO analyzed by USEPA Method 8015B.
J = Estimated Value
A10 = Detection and quantitation limits were raised due to matrix interference
A52 = Chromatogram not typical of Diesel
A57 = Chromatogram not typical of motor oil.
RWQCB ESL = SF Bay Regional Water Quality Control Board Environmental Screening Level (January 2019, Rev 2).

TABLE 1b
Soil Analytical Results Summary - PCBs, SVOCs
918 Rich Avenue, Mountain View, California
Project No. 2103-2

Sample ID	Sample Date	Sample Depth (ft)	PCBs		SVOCs
			PCB-1260	Other PCBs	SVOCs
SB-1-1	10/19/2021	0.5-1	**0.0087 J**	**All ND**	ND
SB-2-1	10/19/2021	0.5-1	<0.018 A10	**All ND**	ND
SB-3-1	10/19/2021	0.5-1	**0.044 J**, A10	**All ND**	ND
RWQCB ESLs (res) Cancer Risk			**0.23**	**Varies**	**Varies**
RWQCB ESLs (com/ind) Cancer Risk			**0.94**	**Varies**	**Varies**
RWQCB ESLs (Construction Worker) Cancer Risk			**5.5**	**Varies**	**Varies**

Notes:
PCB = polychlorinated biphenyl
SVOC = semivolatile organic compound
Sample results reported in milligrams per kilogram (mg/kg).
Bolded value denotes analyte detected
<7.2 = not detected above analytical laboratory Method Detection Limit (MDL)
PCB as analyzed by USEPA Method 8082
SVOCs as analyzed by USEPA Method 8270C
J = Estimated Value
A10 = Detection and quantitation limits were raised due to matrix interference
RWQCB ESL = SF Bay Regional Water Quality Control Board Environmental Screening Level (January 2019, Rev 2).

TABLE 1c
Soil Analytical Results Summary - Metals, Asbestos
918 Rich Avenue, Mountain View, California
Project No. 2103-2

Sample ID	Sample Date	Sample Depth (ft)	CAM 17 Metals															Asbestos
			Antimony	Arsenic	Barium	Beryllium	Cadmium	Chromium*	Cobalt	Copper	Lead	Mercury	Molybdenum	Nickel	Silver	Vanadium	Zinc	Other analyzed CAM 17 Metals	
SB-1-1	10/19/2021	0.5-1	**1.9 J**	**2.6**	**130**	**0.31 J**	**0.58**	**120**	**24**	**56**	**7.8**	**0.069 J**	**0.43 J**	**87**	**0.15 J**	**100**	**57**	ND	NA
SB-1-2.5	10/19/2021	2-2.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	**ND**
SB-2-1	10/19/2021	0.5-1	**1.7 J**	**3.7**	**150**	**0.32 J**	**0.61**	**120**	**24**	**55**	**17**	**0.15 J**	**0.5 J**	**84**	**0.41**	**100**	**61**	ND	NA
SB-2-2.5	10/19/2021	2-2.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	**ND**
SB-3-1	10/19/2021	0.5-1	**0.57 J**	**4.2**	**180**	**0.26 J**	**0.5**	**79**	**16**	**41**	**17**	**0.079 J**	**0.54 J**	**60**	**0.12 J**	**70**	**65**	ND	NA
SB-3-2.5	10/19/2021	2-2.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	**ND**
RWQCB ESLs (Res)			**11**	**0.067**	**15,000**	**16**	**78**	**NE**	**23**	**3,100**	**80**	**13**	**390**	**820**	**390**	**390**	**23,000**	**Varies**	**NE**
RWQCB ESLs (Com/ind)			**160**	**0.31**	**220,000**	**230**	**1,100**	**NE**	**350**	**47,000**	**320**	**190**	**5,800**	**11,000**	**5,800**	**5,800**	**350,000**	**Varies**	**NE**
RWQCB ESLs (Construction Worker)			**50**	**0.98**	**3,000**	**27**	**51**	**NE**	**28**	**14,000**	**160**	**44**	**1,800**	**86**	**1,800**	**470**	**110,000**	**Varies**	**NE**

Notes:
Sample results reported in milligrams per kilogram (mg/kg).
<5.0 = not detected above analytical laboratory Method Detection Limit (MDL)
CAM 17 Metals analyzed by USEPA Method 6010B/7471A
Asbestos analyzed by USEPA Method 600/R-93/116
Bolded value denotes analyte detected
Shaded value denotes exceedance of applied ESL or exceedance of generally accepted California background level for arsenic (11 mg/kg)
NA = not analyzed
ND = not detected
RWQCB ESLs = SF Bay Regional Water Quality Control Board Environmental Screening Level (January 2019, Rev 2).
The listed ESLs are based on Direct Exposure, Human Health Risk Levels for residential, commercial/industrial, and construction worker safety scenarios (Table S-1).
NE = ESL not established

TABLE 1d
Soil Analytical Results Summary - OCPs
918 Rich Avenue, Mountain View, California
Project No. 2103-2

Sample ID	Sample Date	Sample Depth (ft)	OCPs						
			Chlordane	4,4'-DDD	4,4'-DDE	4,4'-DDT	Dieldrin	Toxaphene	Other Analyzed OCPs
SB-1-1	10/19/2021	0.5-1	<0.005	**0.0007 J**	**0.019**	**0.0035**	**0.0009 J**	**0.031 J**	ND
SB-2-1	10/19/2021	0.5-1	<0.01	**0.00074 J**	<0.00095	**0.0016 J**	<0.00036	**<0.014**	ND
SB-3-1	10/19/2021	0.5-1	**0.037 J**	**0.0033 J**	**0.0018 J**	**0.0053**	**0.0077**	**<0.014**	**ND**
RWQCB ESLs (res)			**0.48**	**2.7**	**1.8**	**1.9**	**0.037**	**0.51**	**Varies**
RWQCB ESLs (com/ind)			**2.2**	**12**	**8.3**	**8.5**	**0.16**	**2.2**	**Varies**
RWQCB ESLs (construction worker)			**14**	**81**	**57**	**57**	**1.1**	**14**	**Varies**

Notes:
OCP = organochlorine pesticides
Sample results reported in micrograms per cubic meter (µg/m3).
Bolded value = analyte detected above laboratory method detection limit
<320 = not detected above analytical laboratory Method Detection Limit (MDL)
NE = ESL not established
OCPs analyzed by USEPA Method 8081A
J = Estimated Value
Detection and quantation limits are raised due to matrix interference (Lab Qualifier A10) for all samples.
RWQCB ESL = SF Bay Regional Water Quality Control Board Environmental Screening Level (January 2019, Rev 2).

TABLE 1e
Soil Analytical Results Summary - pH
918 Rich Avenue, Mountain View, California
Project No. 2103-2

Sample ID	Sample Date	Sample Depth (ft)	pH	Temperature
SB-1-2.5	10/19/2021	2-2.5	7.73	25.1
SB-2-2.5	10/19/2021	2-2.5	7.56	25.1
SB-3-2.5	10/19/2021	2-2.5	7.69	25.4
RWQCB ESLs (res)			**NE**	**--**
RWQCB ESLs (com/ind)			**NE**	**--**

Notes:
pH results reported in pH units
Temperature values reported in degress celcius
NE = ESL not established
pH analyzed by USEPA Method 9045D
all pH results reported on a 1:1 dilution of sample (lab qualifier pH1:1)
RWQCB ESL = SF Bay Regional Water Quality Control Board Environmental Screening Level (January 2019, Rev 2).

TABLE 2
Soil Vapor Analytical Results Summary
918 Rich Avenue, Mountain View, California
Project No. 2103-2

Sample ID	Sample Date	Sample Depth (ft)	TPH	VOCs											Leak Check	
			GRO	Benzene	Toluene	Ethylbenzene	Total Xylenes	Acetone	Ethanol	Methyl ethyl ketone	Methyl isobutyl ketone	Propylene	PCE	TCE	Isopropyl Alcohol	% Breakthrough
SV-1	10/19/2021	5.0	**2,500 J**	<3.5	<4.6	<5.4	<15	**79 J**	<7.1	<3.2	15 J	**24 J**	<8.4	<9.1	**12 J**	<1
SV-2	10/19/2021	5.0	**910 J**	**20 J**	<4.7	<5.6	<16	**170**	<7.4	<3.3	<4.6	<4.4	<8.8	<9.4	**40**	<1
SV-3	10/19/2021	5.0	**1,100 J**	<3.7	<4.8	<5.6	<16	**160**	**110**	**22 J**	<4.6	**99**	<8.8	<9.5	**23 J**	<1
RWQCB ESLs (res)			**20,000**	**3.2**	**10,000**	**37**	**3,500**	**1,100,000**	**NE**	**170,000**	**100,000**	**NE**	**15**	**16**	**NE**	**--**
RWQCB ESLs (com/ind)			**83,000**	**14**	**44,000**	**160**	**15,000**	**4,500,000**	**NE**	**730,000**	**440,000**	**NE**	**67**	**100**	**NE**	**--**

Notes:
TPH = total petroleum hydrocarbons
VOCs = Volatile Organic Compounds
GRO = gasoline range organics.
PCE = tetrachloroethene
TCE = trichloroethene
Sample results reported in micrograms per cubic meter (µg/m3).
Bolded value = analyte detected above laboratory method detection limit
Shaded value = exceedence of one or more ESL
<320 = not detected above analytical laboratory Method Detection Limit (MDL)
NE = ESL not established
TPH and VOCs analyzed by USEPA Method TO-15.
J = Estimated Value
Detection and quantation limits are raised due to sample dilution (Lab Qualifier A01) for all samples.
RWQCB ESL = SF Bay Regional Water Quality Control Board Environmental Screening Level (January 2019, Rev 2).

APPENDIX A

SOIL BORING LOGS

Environmental Investigation Services, Inc.
316 Mid Valley Center #313, Carmel, California 93923
Ph: (408) 656-1032

Well Number

SB-1

SOIL BORING LOG

Project Name: **Rich Ave.**
Site Location: **918 Rich Avenue, Mountain View, CA**
Job Number: **2103-2**
Dates Drilled: **10/19/2021**
Logged By: **L. Bush** Reviewed By: **F. Cook**

Drilling Company: **ECA**
Boring Dia: **2"**
Boring Depth: **2.5**
Method of Drilling: **Geoprobe DPT**
Sampling Method: **Dual-Core**

Water level during drilling **Not Encountered** Water level in completed boring **Not Encountered**

Depth	Lithology	USCS	Soil Description	Sample ID (PID)	Boring Completion	Description
0		SP	SILTY SAND, dark yellowish brown, estimated dense, damp, fine grained sand, some gravels up to 1-inch diameter	SB-1-1		Cement Grout
-1						
-2				SB-1-2.5		

Notes: BOH = 2.5'

Environmental Investigation Services, Inc.
316 Mid Valley Center #313, Carmel, California 93923
Ph: (408) 656-1032

Well Number

SB-2

SOIL BORING LOG

Project Name: **Rich Ave.**
Site Location: **918 Rich Avenue, Mountain View, CA**
Job Number: **2103-2**
Dates Drilled: **10/19/2021**
Logged By: **L. Bush** Reviewed By: **F. Cook**

Drilling Company: **ECA**
Boring Dia: **2"**
Boring Depth: **2.5**
Method of Drilling: **Geoprobe DPT**
Sampling Method: **Dual-Core**

Water level during drilling **Not Encountered** Water level in completed boring **Not Encountered**

Depth	Lithology	USCS	Soil Description	Sample ID (PID)	Boring Completion	Description
0		SP	SILTY SAND, dark yellowish brown, estimated dense, damp, fine grained sand, some gravels up to 1/2-inch diameter, few rootlets	SB-2-1		Cement Grout
-1						
-2				SB-2-2.5		

Notes: BOH = 2.5'

Environmental Investigation Services, Inc.
316 Mid Valley Center #313, Carmel, California 93923
Ph: (408) 656-1032

Well Number

SB-3

SOIL BORING LOG

Project Name: **Rich Ave.**
Site Location: **918 Rich Avenue, Mountain View, CA**
Job Number: **2103-2**
Dates Drilled: **10/19/2021**
Logged By: **L. Bush** Reviewed By: **F. Cook**

Drilling Company: **ECA**
Boring Dia: **2"**
Boring Depth: **2.5**
Method of Drilling: **Geoprobe DPT**
Sampling Method: **Dual-Core**

Water level during drilling **Not Encountered** Water level in completed boring **Not Encountered**

Depth	Lithology	USCS	Soil Description	Sample ID (PID)	Boring Completion	Description
0		SP	SILTY SAND, dark yellowish brown, estimated dense, damp, fine grained sand, some gravels up to 1/2-inch diameter, few mulch fragments	SB-3-1		Cement Grout
-1						
-2				SB-3-2.5		

Notes: BOH = 2.5'

Environmental Investigation Services, Inc.
316 Mid Valley Center #313, Carmel, California 93923
Ph: (408) 656-1032

Well Number

SV-1

SOIL BORING LOG

Project Name: **Rich Ave.**
Site Location: **918 Rich Avenue, Mountain View, CA**
Job Number: **2103-2**
Dates Drilled: **10/19/2021**
Logged By: **L. Bush** Reviewed By: **F. Cook**

Drilling Company: **ECA**
Boring Dia: **2"**
Boring Depth: **5.5**
Method of Drilling: **Geoprobe DPT**
Sampling Method: **Dual-Core**

Water level during drilling **Not Encountered** Water level in completed boring **Not Encountered**

Depth	Lithology	USCS	Soil Description	Sample ID (PID)	Boring Completion	Description
0		SP	SILTY SAND, dark yellowish brown, estimated dense, damp, fine grained sand, some gravels up to 1-inch diameter			
-1						
-2			Becomes yellowish brown, dry			Bentonite
-3						
-4						
-5						Soil Vapor Probe midway in sand pack

Notes: BOH = 5.5'

Environmental Investigation Services, Inc.
316 Mid Valley Center #313, Carmel, California 93923
Ph: (408) 656-1032

Well Number

SV-2

SOIL BORING LOG

Project Name: **Rich Ave.**
Site Location: **918 Rich Avenue, Mountain View, CA**
Job Number: **2103-2**
Dates Drilled: **10/19/2021**
Logged By: **L. Bush** Reviewed By: **F. Cook**

Drilling Company: **ECA**
Boring Dia: **2"**
Boring Depth: **5.5**
Method of Drilling: **Geoprobe DPT**
Sampling Method: **Dual-Core**

Water level during drilling **Not Encountered** Water level in completed boring **Not Encountered**

Depth	Lithology	USCS	Soil Description	Sample ID (PID)	Boring Completion	Description
0		SP	SILTY SAND, dark yellowish brown, estimated dense, damp, fine grained sand, some gravels up to 1-inch diameter, some rootlets			
-1						
-2						Bentonite
-3			Becomes yellowish brown, dry			
-4						
-5						Soil Vapor Probe midway in sand pack

Notes: BOH = 5.5'

Environmental Investigation Services, Inc.
316 Mid Valley Center #313, Carmel, California 93923
Ph: (408) 656-1032

Well Number

SV-3

SOIL BORING LOG

Project Name: **Rich Ave.**
Site Location: **918 Rich Avenue, Mountain View, CA**
Job Number: **2103-2**
Dates Drilled: **10/19/2021**
Logged By: **L. Bush** Reviewed By: **F. Cook**

Drilling Company: **ECA**
Boring Dia: **2"**
Boring Depth: **5.5**
Method of Drilling: **Geoprobe DPT**
Sampling Method: **Dual-Core**

Water level during drilling **Not Encountered** Water level in completed boring **Not Encountered**

Depth	Lithology	USCS	Soil Description	Sample ID (PID)	Boring Completion	Description
0		SP	SILTY SAND, dark yellowish brown, estimated dense, damp, fine grained sand, some gravels up to 1/4-inch diameter, some rootlets			
-1						
-2		SP	CLAYEY SAND, moderate brown, estimated very dense, damp, some rootlets and brick fragments			Bentonite
-3						
-4		SP	SILTY SAND, yellowish brown, estimated dense, dry, some gravels and mulch fragments up to 1/2-inch diameter			
-5						Soil Vapor Probe midway in sand pack

Notes: BOH = 5.5'

APPENDIX B

SOIL VAPOR FIELD LOGS

Soil Vapor Well Purging and Sampling Form

Well No. SV-1

Project Name: Rich Ave.	Project No. 22103-2	Date: 10/19/21
Project Address, City, County: 918 Rich Ave., Mountain View, CA		

PURGING AND SAMPLING INSTRUMENTATION AND METHOD

Water Level Meter (Model/ID)	Interface probe (Model/ID)
Water Quality Meter (Model/ID)	Decontamination Method
Purging Method(s) _____ Summa _____ Vacuum Truck _____ Submersible Pump __X__ 60 ml syringe	
Sampling Method(s) ___x___ Summa Canister _____ Disposal Bailer _____ Other	

BOREHOLE AND WELL CASING VOLUME INFORMATION

Borehole Diameter (Circle) 5/8" (2") 6" 8"	Casing Diameter (Circle) (3/16")
	Casing Multiplier (CM) (mL/foot) 5.42

MONITORING MEASUREMENTS

Depth to Free Product (feet)	Casing Volume (CV)
Depth to Water (DTW) (feet)	_____ WD x CM _____ _____ CV (mL) x 3.0 CV (mL) _____
Total Well Depth (WD) (feet) 5.5	5.42 ml x (6.5 ft) + 206 ( ) ml = 241 ml Times 3 for 3 well volumes total
Water Column (WC) (feet)	X3 = 723 ml or 12 syringes
Free Product Thickness (feet)	Free Product Purged (gal)

PURGING DATA

Time (24 hr)									
mL Purged									
He % in shroud									
~~He % out~~									
Sample Time	1126	1127	1128	1129	1130	1132			
~~He % in shroud~~									
Hg "	-28	-25	-20	-15	-10	-5			
Purge Start Hg								Can ID	10469
Purge End Hg								Flow ID	1344

SAMPLING DATA

Sample ID	Time	Quantity	Volume	Type	Filtered	Preserved	Analysis

FIELD PERSONNEL

Field Technician Representative(s):	Subcontractor:
Signature	Date:

Environmental Investigation Services, Inc.
316 Mid Valley Center #313
Carmel, California 93923

Set - 0915

Soil Vapor Well Purging and Sampling Form

Well No. SV-2

Project Name: Rich Ave.	Project No. 22103-2	Date: 10/19/21
Project Address, City, County: 918 Rich Ave., Mountain View, CA		

PURGING AND SAMPLING INSTRUMENTATION AND METHOD

Water Level Meter (Model/ID)	Interface probe (Model/ID)
Water Quality Meter (Model/ID)	Decontamination Method
Purging Method(s) _____ Summa _____ Vacuum Truck _____ Submersible Pump X 60 ml syringe	
Sampling Method(s) x Summa Canister _____ Disposal Bailer _____ Other	

BOREHOLE AND WELL CASING VOLUME INFORMATION

Borehole Diameter (Circle) 5/8" (2") 6" 8"	Casing Diameter (Circle) (3/16")
	Casing Multiplier (CM) (mL/foot) 5.42

MONITORING MEASUREMENTS

Depth to Free Product (feet)	Casing Volume (CV)
Depth to Water (DTW) (feet)	_____ WD x CM _____ _____ CV (mL) x 3.0 CV (mL) _____
Total Well Depth (WD) (feet) 5.5	5.42 ml x (6.5 ft) + 206 (1)ml = 241 ml Times 3 for 3 well volumes total
Water Column (WC) (feet)	x3 = 723 ml or 12 syringes
Free Product Thickness (feet)	Free Product Purged (gal)

PURGING DATA

Time (24 hr)									
mL Purged									
He % in shroud									
~~He % out~~									
Sample Time	1139	1140	1142	1143	1144	(1146)			
~~He % in shroud~~									
Hg "	-27	-25	-20	-15	-10	-5			
Purge Start Hg								Can ID	10406
Purge End Hg								Flow ID	1514

SAMPLING DATA

Sample ID	Time	Quantity	Volume	Type	Filtered	Preserved	Analysis

FIELD PERSONNEL

Field Technician Representative(s):	Subcontractor:
Signature	Date:

Environmental Investigation Services, Inc.
316 Mid Valley Center #313
Carmel, California 93923

Set: 0930

Soil Vapor Well Purging and Sampling Form

Well No. SV-3

Project Name: Rich Ave.	Project No. 22103-2	Date: 10/19/21
Project Address, City, County: 918 Rich Ave., Mountain View, CA		

PURGING AND SAMPLING INSTRUMENTATION AND METHOD

Water Level Meter (Model/ID)	Interface probe (Model/ID)
Water Quality Meter (Model/ID)	Decontamination Method
Purging Method(s) _____ Summa _____ Vacuum Truck _____ Submersible Pump	X 60 ml syringe
Sampling Method(s) x Summa Canister _____ Disposal Bailer _____ Other	

BOREHOLE AND WELL CASING VOLUME INFORMATION

Borehole Diameter (Circle) 5/8" (2") 6" 8"	Casing Diameter (Circle) (3/16")
	Casing Multiplier (CM) (mL/foot) 5.42

MONITORING MEASUREMENTS

Depth to Free Product (feet) /	Casing Volume (CV)
Depth to Water (DTW) (feet) /	_____ WD x CM _____ _____ CV (mL) x 3.0 CV (mL) _____
Total Well Depth (WD) (feet) 5.5	5.42 ml x (6.5 ft) + 206 (\ )ml = 241 ml Times 3 for 3 well volumes total
Water Column (WC) (feet) /	x3 = 723 ml or 10 Syringes
Free Product Thickness (feet) /	Free Product Purged (gal)

PURGING DATA

Time (24 hr)									
mL Purged									
He % in shroud									
~~He % in shroud~~									
Sample Time	1153	1153	1154	1156	1157	(1159)			
~~He % in shroud~~									
Hg "	-27	-25	-20	-15	-10	-5			
Purge Start Hg								Can ID	6436
Purge End Hg								Flow ID	1282

SAMPLING DATA

Sample ID	Time	Quantity	Volume	Type	Filtered	Preserved	Analysis

FIELD PERSONNEL

Field Technician Representative(s):	Subcontractor:
Signature	Date:

Environmental Investigation Services, Inc.
316 Mid Valley Center #313
Carmel, California 93923

Set 0950

APPENDIX C

SOIL ANALYTICAL REPORT

Date of Report: 11/01/2021

Lawrence Bush

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Client Project:	2103-2 918 Rich Avenue, Mountain View, CA
BCL Project:	Soil Samples
BCL Work Order:	2132975
Invoice ID:	B433055

Enclosed are the results of analyses for samples received by the laboratory on 10/19/2021. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Contact Person: Ragen Schallock
Client Service Rep

Stuart Buttram
Technical Director

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Table of Contents

Sample Information

Case Narrative.... 4
Chain of Custody and Cooler Receipt form.... 17
Laboratory / Client Sample Cross Reference.... 19

Sample Results

2132975-01 - SB-1-1

Organochlorine Pesticides (EPA Method 8081A).... 20
PCB Analysis (EPA Method 8082).... 21
Volatile Organic Analysis (EPA Method 8260B).... 22
Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C).... 25
Total Petroleum Hydrocarbons.... 28
Total Concentrations (TTLC).... 29

2132975-02 - SB-1-2.5

Chemical Analysis.... 30

2132975-03 - SB-2-1

Organochlorine Pesticides (EPA Method 8081A).... 31
PCB Analysis (EPA Method 8082).... 32
Volatile Organic Analysis (EPA Method 8260B).... 33
Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C).... 36
Total Petroleum Hydrocarbons.... 39
Total Concentrations (TTLC).... 40

2132975-04 - SB-2-2.5

Chemical Analysis.... 41

2132975-05 - SB-3-1

Organochlorine Pesticides (EPA Method 8081A).... 42
PCB Analysis (EPA Method 8082).... 43
Volatile Organic Analysis (EPA Method 8260B).... 44
Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C).... 47
Total Petroleum Hydrocarbons.... 50
Total Concentrations (TTLC).... 51

2132975-06 - SB-3-2.5

Chemical Analysis.... 52

Quality Control Reports

Organochlorine Pesticides (EPA Method 8081A)

Method Blank Analysis.... 53
Laboratory Control Sample.... 54
Precision and Accuracy.... 55

PCB Analysis (EPA Method 8082)

Method Blank Analysis.... 56
Laboratory Control Sample.... 57
Precision and Accuracy.... 58

Volatile Organic Analysis (EPA Method 8260B)

Method Blank Analysis.... 59
Laboratory Control Sample.... 61
Precision and Accuracy.... 62

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

Method Blank Analysis.... 63
Laboratory Control Sample.... 66
Precision and Accuracy.... 67

Total Petroleum Hydrocarbons

Method Blank Analysis.... 69
Laboratory Control Sample.... 70
Precision and Accuracy.... 71

Chemical Analysis

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Table of Contents

Method Blank Analysis..... 72
Laboratory Control Sample..... 73
Precision and Accuracy..... 74
Total Concentrations (TTLC)
Method Blank Analysis..... 75
Laboratory Control Sample..... 76
Precision and Accuracy..... 77
Subcontract Reports
WO_2132975_sub_EMSLA.pdf..... 79
Notes
Notes and Definitions..... 80

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Receipt

COC Number:

Samples received refrigerated to 2.6 °C

Sample List

Lab Number	Date/Time Sampled	Sample Name
2132975-01	10/19/2021 10:14	SB-1-1
2132975-02	10/19/2021 10:15	SB-1-2.5
2132975-03	10/19/2021 10:09	SB-2-1
2132975-04	10/19/2021 10:10	SB-2-2.5
2132975-05	10/19/2021 10:04	SB-3-1
2132975-06	10/19/2021 10:05	SB-3-2.5

Requested Analysis

EPA-6010B (TTLC), EPA-7471A (TTLC), EPA-8015B, EPA-8081A, EPA-8082, EPA-8260B, EPA-8270C, EPA-9045D

Sample	Analyte	Flag

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample		Analyte	Flag
2132975-01	EPA-6010B (TTLC)	Chromium	S11
2132975-01	EPA-6010B (TTLC)	Nickel	S11
2132975-01	EPA-6010B (TTLC)	Thallium	A10
2132975-01	EPA-8015B	TPH - Diesel (C13 - C22)	A52
2132975-01	EPA-8015B	TPH - Motor Oil (C23 - C36)	A57
2132975-01	EPA-8081A	Aldrin	A10
2132975-01	EPA-8081A	alpha-BHC	A10
2132975-01	EPA-8081A	beta-BHC	A10
2132975-01	EPA-8081A	delta-BHC	A10
2132975-01	EPA-8081A	gamma-BHC (Lindane)	A10
2132975-01	EPA-8081A	Chlordane (Technical)	A10
2132975-01	EPA-8081A	4,4'-DDD	A10
2132975-01	EPA-8081A	4,4'-DDE	A10
2132975-01	EPA-8081A	4,4'-DDT	A10
2132975-01	EPA-8081A	Dieldrin	A10
2132975-01	EPA-8081A	Endosulfan I	A10
2132975-01	EPA-8081A	Endosulfan II	A10
2132975-01	EPA-8081A	Endosulfan sulfate	A10
2132975-01	EPA-8081A	Endrin	A10
2132975-01	EPA-8081A	Endrin aldehyde	A10
2132975-01	EPA-8081A	Heptachlor	A10
2132975-01	EPA-8081A	Heptachlor epoxide	A10
2132975-01	EPA-8081A	Methoxychlor	A10
2132975-01	EPA-8081A	Toxaphene	A10
2132975-01	EPA-8081A	TCMX (Surrogate)	A10
2132975-01	EPA-8081A	Decachlorobiphenyl (Surrogate)	A10
2132975-01	EPA-8270C	Acenaphthene	A10
2132975-01	EPA-8270C	Acenaphthylene	A10
2132975-01	EPA-8270C	Aldrin	A10
2132975-01	EPA-8270C	Aniline	A10
2132975-01	EPA-8270C	Anthracene	A10
2132975-01	EPA-8270C	Benzidine	A10
2132975-01	EPA-8270C	Benzo[a]anthracene	A10
2132975-01	EPA-8270C	Benzo[b]fluoranthene	A10
2132975-01	EPA-8270C	Benzo[k]fluoranthene	A10
2132975-01	EPA-8270C	Benzo[a]pyrene	A10
2132975-01	EPA-8270C	Benzo[g,h,i]perylene	A10
2132975-01	EPA-8270C	Benzoic acid	A10
2132975-01	EPA-8270C	Benzyl alcohol	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample		Analyte	Flag
2132975-01	EPA-8270C	Benzyl butyl phthalate	A10
2132975-01	EPA-8270C	alpha-BHC	A10
2132975-01	EPA-8270C	beta-BHC	A10
2132975-01	EPA-8270C	delta-BHC	A10
2132975-01	EPA-8270C	gamma-BHC (Lindane)	A10
2132975-01	EPA-8270C	bis(2-Chloroethoxy)methane	A10
2132975-01	EPA-8270C	bis(2-Chloroethyl) ether	A10
2132975-01	EPA-8270C	bis(2-Chloroisopropyl)ether	A10
2132975-01	EPA-8270C	bis(2-Ethylhexyl)phthalate	A10
2132975-01	EPA-8270C	4-Bromophenyl phenyl ether	A10
2132975-01	EPA-8270C	4-Chloroaniline	A10
2132975-01	EPA-8270C	2-Chloronaphthalene	A10
2132975-01	EPA-8270C	4-Chlorophenyl phenyl ether	A10
2132975-01	EPA-8270C	Chrysene	A10
2132975-01	EPA-8270C	4,4'-DDD	A10
2132975-01	EPA-8270C	4,4'-DDE	A10
2132975-01	EPA-8270C	4,4'-DDT	A10
2132975-01	EPA-8270C	Dibenzo[a,h]anthracene	A10
2132975-01	EPA-8270C	Dibenzofuran	A10
2132975-01	EPA-8270C	1,2-Dichlorobenzene	A10
2132975-01	EPA-8270C	1,3-Dichlorobenzene	A10
2132975-01	EPA-8270C	1,4-Dichlorobenzene	A10
2132975-01	EPA-8270C	3,3-Dichlorobenzidine	A10
2132975-01	EPA-8270C	Dieldrin	A10
2132975-01	EPA-8270C	Diethyl phthalate	A10
2132975-01	EPA-8270C	Dimethyl phthalate	A10
2132975-01	EPA-8270C	Di-n-butyl phthalate	A10
2132975-01	EPA-8270C	2,4-Dinitrotoluene	A10
2132975-01	EPA-8270C	2,6-Dinitrotoluene	A10
2132975-01	EPA-8270C	Di-n-octyl phthalate	A10
2132975-01	EPA-8270C	1,2-Diphenylhydrazine	A10
2132975-01	EPA-8270C	Endosulfan I	A10
2132975-01	EPA-8270C	Endosulfan II	A10
2132975-01	EPA-8270C	Endosulfan sulfate	A10
2132975-01	EPA-8270C	Endrin	A10
2132975-01	EPA-8270C	Endrin aldehyde	A10
2132975-01	EPA-8270C	Fluoranthene	A10
2132975-01	EPA-8270C	Fluorene	A10
2132975-01	EPA-8270C	Heptachlor	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample		Analyte	Flag
2132975-01	EPA-8270C	Heptachlor epoxide	A10
2132975-01	EPA-8270C	Hexachlorobenzene	A10
2132975-01	EPA-8270C	Hexachlorobutadiene	A10
2132975-01	EPA-8270C	Hexachlorocyclopentadiene	A10
2132975-01	EPA-8270C	Hexachloroethane	A10
2132975-01	EPA-8270C	Indeno[1,2,3-cd]pyrene	A10
2132975-01	EPA-8270C	Isophorone	A10
2132975-01	EPA-8270C	2-Methylnaphthalene	A10
2132975-01	EPA-8270C	Naphthalene	A10
2132975-01	EPA-8270C	2-Naphthylamine	A10
2132975-01	EPA-8270C	2-Nitroaniline	A10
2132975-01	EPA-8270C	3-Nitroaniline	A10
2132975-01	EPA-8270C	4-Nitroaniline	A10
2132975-01	EPA-8270C	Nitrobenzene	A10
2132975-01	EPA-8270C	N-Nitrosodimethylamine	A10
2132975-01	EPA-8270C	N-Nitrosodi-N-propylamine	A10
2132975-01	EPA-8270C	N-Nitrosodiphenylamine	A10
2132975-01	EPA-8270C	Phenanthrene	A10
2132975-01	EPA-8270C	Pyrene	A10
2132975-01	EPA-8270C	1,2,4-Trichlorobenzene	A10
2132975-01	EPA-8270C	4-Chloro-3-methylphenol	A10
2132975-01	EPA-8270C	2-Chlorophenol	A10
2132975-01	EPA-8270C	2,4-Dichlorophenol	A10
2132975-01	EPA-8270C	2,4-Dimethylphenol	A10
2132975-01	EPA-8270C	4,6-Dinitro-2-methylphenol	A10
2132975-01	EPA-8270C	2,4-Dinitrophenol	A10
2132975-01	EPA-8270C	2-Methylphenol	A10
2132975-01	EPA-8270C	3- & 4-Methylphenol	A10
2132975-01	EPA-8270C	2-Nitrophenol	A10
2132975-01	EPA-8270C	4-Nitrophenol	A10
2132975-01	EPA-8270C	Pentachlorophenol	A10
2132975-01	EPA-8270C	Phenol	A10
2132975-01	EPA-8270C	2,4,5-Trichlorophenol	A10
2132975-01	EPA-8270C	2,4,6-Trichlorophenol	A10
2132975-01	EPA-8270C	2-Fluorophenol (Surrogate)	A10
2132975-01	EPA-8270C	Phenol-d5 (Surrogate)	A10
2132975-01	EPA-8270C	Nitrobenzene-d5 (Surrogate)	A10
2132975-01	EPA-8270C	2-Fluorobiphenyl (Surrogate)	A10
2132975-01	EPA-8270C	2,4,6-Tribromophenol (Surrogate)	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample	Analyte		Flag
2132975-01	EPA-8270C	p-Terphenyl-d14 (Surrogate)	A10
2132975-02	EPA-9045D	pH	pH1:1
2132975-03	EPA-6010B (TTLC)	Chromium	S11
2132975-03	EPA-6010B (TTLC)	Nickel	S11
2132975-03	EPA-6010B (TTLC)	Thallium	A10
2132975-03	EPA-8015B	TPH - Diesel (C13 - C22)	A52
2132975-03	EPA-8015B	TPH - Motor Oil (C23 - C36)	A57
2132975-03	EPA-8081A	Aldrin	A10
2132975-03	EPA-8081A	alpha-BHC	A10
2132975-03	EPA-8081A	beta-BHC	A10
2132975-03	EPA-8081A	delta-BHC	A10
2132975-03	EPA-8081A	gamma-BHC (Lindane)	A10
2132975-03	EPA-8081A	Chlordane (Technical)	A10
2132975-03	EPA-8081A	4,4'-DDD	A10
2132975-03	EPA-8081A	4,4'-DDE	A10
2132975-03	EPA-8081A	4,4'-DDT	A10
2132975-03	EPA-8081A	Dieldrin	A10
2132975-03	EPA-8081A	Endosulfan I	A10
2132975-03	EPA-8081A	Endosulfan II	A10
2132975-03	EPA-8081A	Endosulfan sulfate	A10
2132975-03	EPA-8081A	Endrin	A10
2132975-03	EPA-8081A	Endrin aldehyde	A10
2132975-03	EPA-8081A	Heptachlor	A10
2132975-03	EPA-8081A	Heptachlor epoxide	A10
2132975-03	EPA-8081A	Methoxychlor	A10
2132975-03	EPA-8081A	Toxaphene	A10
2132975-03	EPA-8081A	TCMX (Surrogate)	A10
2132975-03	EPA-8081A	Decachlorobiphenyl (Surrogate)	A10
2132975-03	EPA-8082	PCB-1016	A10
2132975-03	EPA-8082	PCB-1221	A10
2132975-03	EPA-8082	PCB-1232	A10
2132975-03	EPA-8082	PCB-1242	A10
2132975-03	EPA-8082	PCB-1248	A10
2132975-03	EPA-8082	PCB-1254	A10
2132975-03	EPA-8082	PCB-1260	A10
2132975-03	EPA-8082	Total PCB's (Summation)	A10
2132975-03	EPA-8082	Decachlorobiphenyl (Surrogate)	A10
2132975-03	EPA-8270C	Acenaphthene	A10
2132975-03	EPA-8270C	Acenaphthylene	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample		Analyte	Flag
2132975-03	EPA-8270C	Aldrin	A10
2132975-03	EPA-8270C	Aniline	A10
2132975-03	EPA-8270C	Anthracene	A10
2132975-03	EPA-8270C	Benzidine	A10
2132975-03	EPA-8270C	Benzo[a]anthracene	A10
2132975-03	EPA-8270C	Benzo[b]fluoranthene	A10
2132975-03	EPA-8270C	Benzo[k]fluoranthene	A10
2132975-03	EPA-8270C	Benzo[a]pyrene	A10
2132975-03	EPA-8270C	Benzo[g,h,i]perylene	A10
2132975-03	EPA-8270C	Benzoic acid	A10
2132975-03	EPA-8270C	Benzyl alcohol	A10
2132975-03	EPA-8270C	Benzyl butyl phthalate	A10
2132975-03	EPA-8270C	alpha-BHC	A10
2132975-03	EPA-8270C	beta-BHC	A10
2132975-03	EPA-8270C	delta-BHC	A10
2132975-03	EPA-8270C	gamma-BHC (Lindane)	A10
2132975-03	EPA-8270C	bis(2-Chloroethoxy)methane	A10
2132975-03	EPA-8270C	bis(2-Chloroethyl) ether	A10
2132975-03	EPA-8270C	bis(2-Chloroisopropyl)ether	A10
2132975-03	EPA-8270C	bis(2-Ethylhexyl)phthalate	A10
2132975-03	EPA-8270C	4-Bromophenyl phenyl ether	A10
2132975-03	EPA-8270C	4-Chloroaniline	A10
2132975-03	EPA-8270C	2-Chloronaphthalene	A10
2132975-03	EPA-8270C	4-Chlorophenyl phenyl ether	A10
2132975-03	EPA-8270C	Chrysene	A10
2132975-03	EPA-8270C	4,4'-DDD	A10
2132975-03	EPA-8270C	4,4'-DDE	A10
2132975-03	EPA-8270C	4,4'-DDT	A10
2132975-03	EPA-8270C	Dibenzo[a,h]anthracene	A10
2132975-03	EPA-8270C	Dibenzofuran	A10
2132975-03	EPA-8270C	1,2-Dichlorobenzene	A10
2132975-03	EPA-8270C	1,3-Dichlorobenzene	A10
2132975-03	EPA-8270C	1,4-Dichlorobenzene	A10
2132975-03	EPA-8270C	3,3-Dichlorobenzidine	A10
2132975-03	EPA-8270C	Dieldrin	A10
2132975-03	EPA-8270C	Diethyl phthalate	A10
2132975-03	EPA-8270C	Dimethyl phthalate	A10
2132975-03	EPA-8270C	Di-n-butyl phthalate	A10
2132975-03	EPA-8270C	2,4-Dinitrotoluene	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample		Analyte	Flag
2132975-03	EPA-8270C	2,6-Dinitrotoluene	A10
2132975-03	EPA-8270C	Di-n-octyl phthalate	A10
2132975-03	EPA-8270C	1,2-Diphenylhydrazine	A10
2132975-03	EPA-8270C	Endosulfan I	A10
2132975-03	EPA-8270C	Endosulfan II	A10
2132975-03	EPA-8270C	Endosulfan sulfate	A10
2132975-03	EPA-8270C	Endrin	A10
2132975-03	EPA-8270C	Endrin aldehyde	A10
2132975-03	EPA-8270C	Fluoranthene	A10
2132975-03	EPA-8270C	Fluorene	A10
2132975-03	EPA-8270C	Heptachlor	A10
2132975-03	EPA-8270C	Heptachlor epoxide	A10
2132975-03	EPA-8270C	Hexachlorobenzene	A10
2132975-03	EPA-8270C	Hexachlorobutadiene	A10
2132975-03	EPA-8270C	Hexachlorocyclopentadiene	A10
2132975-03	EPA-8270C	Hexachloroethane	A10
2132975-03	EPA-8270C	Indeno[1,2,3-cd]pyrene	A10
2132975-03	EPA-8270C	Isophorone	A10
2132975-03	EPA-8270C	2-Methylnaphthalene	A10
2132975-03	EPA-8270C	Naphthalene	A10
2132975-03	EPA-8270C	2-Naphthylamine	A10
2132975-03	EPA-8270C	2-Nitroaniline	A10
2132975-03	EPA-8270C	3-Nitroaniline	A10
2132975-03	EPA-8270C	4-Nitroaniline	A10
2132975-03	EPA-8270C	Nitrobenzene	A10
2132975-03	EPA-8270C	N-Nitrosodimethylamine	A10
2132975-03	EPA-8270C	N-Nitrosodi-N-propylamine	A10
2132975-03	EPA-8270C	N-Nitrosodiphenylamine	A10
2132975-03	EPA-8270C	Phenanthrene	A10
2132975-03	EPA-8270C	Pyrene	A10
2132975-03	EPA-8270C	1,2,4-Trichlorobenzene	A10
2132975-03	EPA-8270C	4-Chloro-3-methylphenol	A10
2132975-03	EPA-8270C	2-Chlorophenol	A10
2132975-03	EPA-8270C	2,4-Dichlorophenol	A10
2132975-03	EPA-8270C	2,4-Dimethylphenol	A10
2132975-03	EPA-8270C	4,6-Dinitro-2-methylphenol	A10
2132975-03	EPA-8270C	2,4-Dinitrophenol	A10
2132975-03	EPA-8270C	2-Methylphenol	A10
2132975-03	EPA-8270C	3- & 4-Methylphenol	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample		Analyte	Flag
2132975-03	EPA-8270C	2-Nitrophenol	A10
2132975-03	EPA-8270C	4-Nitrophenol	A10
2132975-03	EPA-8270C	Pentachlorophenol	A10
2132975-03	EPA-8270C	Phenol	A10
2132975-03	EPA-8270C	2,4,5-Trichlorophenol	A10
2132975-03	EPA-8270C	2,4,6-Trichlorophenol	A10
2132975-03	EPA-8270C	2-Fluorophenol (Surrogate)	A10
2132975-03	EPA-8270C	Phenol-d5 (Surrogate)	A10
2132975-03	EPA-8270C	Nitrobenzene-d5 (Surrogate)	A10
2132975-03	EPA-8270C	2-Fluorobiphenyl (Surrogate)	A10
2132975-03	EPA-8270C	2,4,6-Tribromophenol (Surrogate)	A10
2132975-03	EPA-8270C	p-Terphenyl-d14 (Surrogate)	A10
2132975-04	EPA-9045D	pH	pH1:1
2132975-05	EPA-6010B (TTLC)	Chromium	S11
2132975-05	EPA-6010B (TTLC)	Nickel	S11
2132975-05	EPA-6010B (TTLC)	Thallium	A10
2132975-05	EPA-8015B	TPH - Gasoline (C4-C12)	A10
2132975-05	EPA-8015B	TPH - Diesel (C13 - C22)	A10
2132975-05	EPA-8015B	TPH - Diesel (C13 - C22)	A52
2132975-05	EPA-8015B	TPH - Motor Oil (C23 - C36)	A10
2132975-05	EPA-8015B	TPH - Motor Oil (C23 - C36)	A57
2132975-05	EPA-8015B	Tetracosane (Surrogate)	A10
2132975-05	EPA-8081A	Aldrin	A10
2132975-05	EPA-8081A	alpha-BHC	A10
2132975-05	EPA-8081A	beta-BHC	A10
2132975-05	EPA-8081A	delta-BHC	A10
2132975-05	EPA-8081A	gamma-BHC (Lindane)	A10
2132975-05	EPA-8081A	Chlordane (Technical)	A10
2132975-05	EPA-8081A	4,4'-DDD	A10
2132975-05	EPA-8081A	4,4'-DDE	A10
2132975-05	EPA-8081A	4,4'-DDT	A10
2132975-05	EPA-8081A	Dieldrin	A10
2132975-05	EPA-8081A	Endosulfan I	A10
2132975-05	EPA-8081A	Endosulfan II	A10
2132975-05	EPA-8081A	Endosulfan sulfate	A10
2132975-05	EPA-8081A	Endrin	A10
2132975-05	EPA-8081A	Endrin aldehyde	A10
2132975-05	EPA-8081A	Heptachlor	A10
2132975-05	EPA-8081A	Heptachlor epoxide	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample		Analyte	Flag
2132975-05	EPA-8081A	Methoxychlor	A10
2132975-05	EPA-8081A	Toxaphene	A10
2132975-05	EPA-8081A	TCMX (Surrogate)	A10
2132975-05	EPA-8081A	Decachlorobiphenyl (Surrogate)	A10
2132975-05	EPA-8082	PCB-1016	A10
2132975-05	EPA-8082	PCB-1221	A10
2132975-05	EPA-8082	PCB-1232	A10
2132975-05	EPA-8082	PCB-1242	A10
2132975-05	EPA-8082	PCB-1248	A10
2132975-05	EPA-8082	PCB-1254	A10
2132975-05	EPA-8082	PCB-1260	A10
2132975-05	EPA-8082	Total PCB's (Summation)	A10
2132975-05	EPA-8082	Decachlorobiphenyl (Surrogate)	A10
2132975-05	EPA-8270C	Acenaphthene	A10
2132975-05	EPA-8270C	Acenaphthylene	A10
2132975-05	EPA-8270C	Aldrin	A10
2132975-05	EPA-8270C	Aniline	A10
2132975-05	EPA-8270C	Anthracene	A10
2132975-05	EPA-8270C	Benzidine	A10
2132975-05	EPA-8270C	Benzo[a]anthracene	A10
2132975-05	EPA-8270C	Benzo[b]fluoranthene	A10
2132975-05	EPA-8270C	Benzo[k]fluoranthene	A10
2132975-05	EPA-8270C	Benzo[a]pyrene	A10
2132975-05	EPA-8270C	Benzo[g,h,i]perylene	A10
2132975-05	EPA-8270C	Benzoic acid	A10
2132975-05	EPA-8270C	Benzyl alcohol	A10
2132975-05	EPA-8270C	Benzyl butyl phthalate	A10
2132975-05	EPA-8270C	alpha-BHC	A10
2132975-05	EPA-8270C	beta-BHC	A10
2132975-05	EPA-8270C	delta-BHC	A10
2132975-05	EPA-8270C	gamma-BHC (Lindane)	A10
2132975-05	EPA-8270C	bis(2-Chloroethoxy)methane	A10
2132975-05	EPA-8270C	bis(2-Chloroethyl) ether	A10
2132975-05	EPA-8270C	bis(2-Chloroisopropyl)ether	A10
2132975-05	EPA-8270C	bis(2-Ethylhexyl)phthalate	A10
2132975-05	EPA-8270C	4-Bromophenyl phenyl ether	A10
2132975-05	EPA-8270C	4-Chloroaniline	A10
2132975-05	EPA-8270C	2-Chloronaphthalene	A10
2132975-05	EPA-8270C	4-Chlorophenyl phenyl ether	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample Qualifier Summary

Sample		Analyte	Flag
2132975-05	EPA-8270C	Chrysene	A10
2132975-05	EPA-8270C	4,4'-DDD	A10
2132975-05	EPA-8270C	4,4'-DDE	A10
2132975-05	EPA-8270C	4,4'-DDT	A10
2132975-05	EPA-8270C	Dibenzo[a,h]anthracene	A10
2132975-05	EPA-8270C	Dibenzofuran	A10
2132975-05	EPA-8270C	1,2-Dichlorobenzene	A10
2132975-05	EPA-8270C	1,3-Dichlorobenzene	A10
2132975-05	EPA-8270C	1,4-Dichlorobenzene	A10
2132975-05	EPA-8270C	3,3-Dichlorobenzidine	A10
2132975-05	EPA-8270C	Dieldrin	A10
2132975-05	EPA-8270C	Diethyl phthalate	A10
2132975-05	EPA-8270C	Dimethyl phthalate	A10
2132975-05	EPA-8270C	Di-n-butyl phthalate	A10
2132975-05	EPA-8270C	2,4-Dinitrotoluene	A10
2132975-05	EPA-8270C	2,6-Dinitrotoluene	A10
2132975-05	EPA-8270C	Di-n-octyl phthalate	A10
2132975-05	EPA-8270C	1,2-Diphenylhydrazine	A10
2132975-05	EPA-8270C	Endosulfan I	A10
2132975-05	EPA-8270C	Endosulfan II	A10
2132975-05	EPA-8270C	Endosulfan sulfate	A10
2132975-05	EPA-8270C	Endrin	A10
2132975-05	EPA-8270C	Endrin aldehyde	A10
2132975-05	EPA-8270C	Fluoranthene	A10
2132975-05	EPA-8270C	Fluorene	A10
2132975-05	EPA-8270C	Heptachlor	A10
2132975-05	EPA-8270C	Heptachlor epoxide	A10
2132975-05	EPA-8270C	Hexachlorobenzene	A10
2132975-05	EPA-8270C	Hexachlorobutadiene	A10
2132975-05	EPA-8270C	Hexachlorocyclopentadiene	A10
2132975-05	EPA-8270C	Hexachloroethane	A10
2132975-05	EPA-8270C	Indeno[1,2,3-cd]pyrene	A10
2132975-05	EPA-8270C	Isophorone	A10
2132975-05	EPA-8270C	2-Methylnaphthalene	A10
2132975-05	EPA-8270C	Naphthalene	A10
2132975-05	EPA-8270C	2-Naphthylamine	A10
2132975-05	EPA-8270C	2-Nitroaniline	A10
2132975-05	EPA-8270C	3-Nitroaniline	A10
2132975-05	EPA-8270C	4-Nitroaniline	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample		Analyte	Flag
Sample Qualifier Summary			
2132975-05	EPA-8270C	Nitrobenzene	A10
2132975-05	EPA-8270C	N-Nitrosodimethylamine	A10
2132975-05	EPA-8270C	N-Nitrosodi-N-propylamine	A10
2132975-05	EPA-8270C	N-Nitrosodiphenylamine	A10
2132975-05	EPA-8270C	Phenanthrene	A10
2132975-05	EPA-8270C	Pyrene	A10
2132975-05	EPA-8270C	1,2,4-Trichlorobenzene	A10
2132975-05	EPA-8270C	4-Chloro-3-methylphenol	A10
2132975-05	EPA-8270C	2-Chlorophenol	A10
2132975-05	EPA-8270C	2,4-Dichlorophenol	A10
2132975-05	EPA-8270C	2,4-Dimethylphenol	A10
2132975-05	EPA-8270C	4,6-Dinitro-2-methylphenol	A10
2132975-05	EPA-8270C	2,4-Dinitrophenol	A10
2132975-05	EPA-8270C	2-Methylphenol	A10
2132975-05	EPA-8270C	3- & 4-Methylphenol	A10
2132975-05	EPA-8270C	2-Nitrophenol	A10
2132975-05	EPA-8270C	4-Nitrophenol	A10
2132975-05	EPA-8270C	Pentachlorophenol	A10
2132975-05	EPA-8270C	Phenol	A10
2132975-05	EPA-8270C	2,4,5-Trichlorophenol	A10
2132975-05	EPA-8270C	2,4,6-Trichlorophenol	A10
2132975-05	EPA-8270C	2-Fluorophenol (Surrogate)	A10
2132975-05	EPA-8270C	Phenol-d5 (Surrogate)	A10
2132975-05	EPA-8270C	Nitrobenzene-d5 (Surrogate)	A10
2132975-05	EPA-8270C	2-Fluorobiphenyl (Surrogate)	A10
2132975-05	EPA-8270C	2,4,6-Tribromophenol (Surrogate)	A10
2132975-05	EPA-8270C	p-Terphenyl-d14 (Surrogate)	A10
2132975-06	EPA-9045D	pH	pH1:1

Holding Times

All holding time requirements were met.

Method Blanks

B122837-BLK2	EPA-6010B (TTLC)	Chromium	0.82390 mg/kg
B122837-BLK2	EPA-6010B (TTLC)	Nickel	0.56592 mg/kg
B122837-BLK2	EPA-6010B (TTLC)	Zinc	0.51890 mg/kg
B122837-BLK2	EPA-6010B (TTLC)	Chromium	M01
B122837-BLK2	EPA-6010B (TTLC)	Nickel	M01

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Sample		Analyte	Flag
Matrix Spikes			
B122699-MS1	EPA-8015B	TPH - Diesel (C13 - C22)	A10
B122699-MS1	EPA-8015B	TPH - Diesel (C13 - C22)	Q03
B122699-MS1	EPA-8015B	Tetracosane (Surrogate)	A10
B122699-MSD1	EPA-8015B	TPH - Diesel (C13 - C22)	A10
B122699-MSD1	EPA-8015B	TPH - Diesel (C13 - C22)	Q03
B122699-MSD1	EPA-8015B	Tetracosane (Surrogate)	A10
B122837-DUP2	EPA-6010B (TTLC)	Lead	A02
B122837-MS2	EPA-6010B (TTLC)	Barium	A03
B122837-MSD2	EPA-6010B (TTLC)	Barium	A03
B122837-MSD2	EPA-6010B (TTLC)	Selenium	Q03
B122999-MS1	EPA-8082	PCB-1016	Q03
B122999-MS1	EPA-8082	PCB-1260	Q03
B122999-MS1	EPA-8082	Decachlorobiphenyl (Surrogate)	S09
B122999-MSD1	EPA-8082	PCB-1016	Q03
B122999-MSD1	EPA-8082	PCB-1260	Q03
B122999-MSD1	EPA-8082	Decachlorobiphenyl (Surrogate)	S09

LCS

The LCS recoveries are within QC limits.

Discussion

Ragen,

Sorry to be even more difficult, but I have just been informed that we want to actually analyze the deeper samples for the other two analyses (pH and asbestos). So to recap:

" The shallow samples (identified by BC as -1, -3, and -5 on the COC) should be analyzed for everything except pH and asbestos.
" The deeper samples (identified by BC as -2, -4, and -6 on the COC) should be analyzed for pH and asbestos only.

Feel free to call me if this is unclear and once again I apologize for being difficult on this one.

Best,

Lawrence Bush - Staff Geologist, G.I.T. #1331
Environmental Investigation Services, Inc.
Cell: (408) 609-6380

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Case Narrative

Summary of Flags

A02	The difference between duplicate readings is less than the quantitation limit.
A03	The sample concentration was more than 4 times the spike level.
A10	Detection and quantitation limits were raised due to matrix interference.
A52	Chromatogram not typical of diesel.
A57	Chromatogram not typical of motor oil.
M01	Analyte detected in the Method Blank at or above the PQL.
pH1:1	pH result reported on a 1:1 dilution of sample
Q03	Matrix spike recovery(s) was(were) not within the control limits.
S09	The surrogate recovery for this compound was not within the control limits.
S11	The analyte in the Method Blank is greater than the laboratory PQL but the sample result is greater than 10 times the Method Blank.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

BC LABORATORIES
4100 Atlas Court Bakersfield, Ca. 93308
(661) 327-4911 • FAX (661) 327-1918 • www.bclabs.com

Chain of Custody

RUSH!

* Required Fields 21-32975 TEMP:

Client/Company Name *:	Report Attention *:	Phone * #:	FAX #
Environmental Investigation Services, Inc. (EIS)	Lawrence Bush	408 609-6380	
Address *	**City ***	**State ***	**Zip ***
316 Mid Valley Center #313	Carmel	CA	93923
Project Information:		**PO #** 2103-2	**BCL Quote #**
918 Fitch Avenue, Mountain View, CA			
Sampler Name Printed / Signature		**QC Request**	**Result Request ** Surcharge**
Lawrence Bush		☑ STD ☐ Level II	☑ STD ☒ 1 Day** ☐ 2 Day** ☐ 3 Day**

Carbon Copies: CDHS ☐ Fresno Co ☐ EPA ☐ Merced Co ☐ Tulare Co ☐ Other:

Regulatory Compliance Electronic Data Transfer: Y ☐ N ☑ System No. *

Matrix Types: RSW = Raw Surface Water CFW = Chlorinated Finished Water CWW = Chlorinated Waste Water BW = Bottled Water RGW = Raw Ground Water FW = Finished Water WW = Waste Water SW = Storm Water DW = Drinking Water SO = Solid

ANALYSIS REQUESTED

Sample #	# Bottles	Sampled Date	Sampled Time	Sample Description / Location ^	Matrix *	Comments / Station Code	8015 (TPH-g/d/mo)	8260 VOCs	8081 OCPs	8082 PCBs	8270 SVOCs	6020 CAM 17 Metals	Bulk Asbestos 600/R-93/116	9045D pH
-1		10/19/21	1014	SB-1-1	Soil		X	X	X	X	X	X	~~X~~	~~X~~
-2			1015	SB-1-2.5		HOLD							X	X
-3			1009	SB-2-1			X	X	X	X	X	X	~~X~~	~~X~~
-4			1010	SB-2-2.5		HOLD							X	X
-5			1004	SB-3-1			X	X	X	X	X	X	~~X~~	~~X~~
-6		↓	1005	SB-3-2.5	↓	HOLD							X	X

RRS 10/20/21

CHK BY DISTRIBUTION SUB OUT

Relinquished by: (Signature and Printed Name)	Company	Date	Time	Received by (Signature and Print Name)	Company
PETER WILLETS	E.I.S	10/19/21	1315	PBNS	P/BCL 10/19/21 1315
PBNS	P/BCL	10/19/21	1401	Frances Espinoza	BC/AD 10-19-21 1401
Received for Lab by: (Signature and Printed Name)		Date	Time	Payment Received at Delivery:	
Frances Espinoza Frances Espinoza		10/19/21	2215	Date: Amount: Check/Cash/Card PIA # Init.	

Shipping Method: CAO UPS GSO WALK-IN SJVC FED EX OTHER

Cooling Method: WET BLUE NONE

Packing Material:

Note: 5 day turn-around.
10/19/21 2215

REL. Frances Espinoza 10-19-21 1830
10/19/21 1830

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Chain of Custody and Cooler Receipt Form for 2132975 Page 2 of 2

BC LABORATORIES INC. COOLER RECEIPT FORM Page 1 Of 1

Submission #: 21-32975

SHIPPING INFORMATION
Fed Ex ☐ UPS ☐ GSO / GLS ☐ Hand Delivery ☐
BC Lab Field Service ☑ Other ☐ (Specify)_____

SHIPPING CONTAINER
Ice Chest ☑ None ☐ Box ☐
Other ☐ (Specify)_____

FREE LIQUID
YES ☑ NO ☐
(W) S

Refrigerant: Ice ☑ Blue Ice ☐ None ☐ Other ☐ Comments:

Custody Seals Ice Chest ☐ Intact? Yes ☐ No ☐ Containers ☐ Intact? Yes ☐ No ☐ None ☑ Comments:

All samples received? Yes ☑ No ☐ All samples containers intact? Yes ☑ No ☐ Description(s) match COC? Yes ☑ No ☐

COC Received ☑ YES ☐ NO

Emissivity: 0.95 Container: Amber Thermometer ID: 108

Temperature: (A) 2.4 °C / (C) 2.6 °C

Date/Time 10/19/21

Analyst Init FE 2215

SAMPLE CONTAINERS	SAMPLE NUMBERS 1	2	3	4	5	6	7	8	9	10
QT PE UNPRES										
4oz / 8oz / 16oz PE UNPRES										
2oz Cr^{+6}										
QT INORGANIC CHEMICAL METALS										
INORGANIC CHEMICAL METALS 4oz / 8oz / 16oz										
PT CYANIDE										
PT NITROGEN FORMS										
PT TOTAL SULFIDE										
2oz. NITRATE / NITRITE										
PT TOTAL ORGANIC CARBON										
PT CHEMICAL OXYGEN DEMAND										
PtA PHENOLICS										
40ml VOA VIAL TRAVEL BLANK										
40ml VOA VIAL										
QT EPA 1664B										
PT ODOR										
RADIOLOGICAL										
BACTERIOLOGICAL										
40 ml VOA VIAL- 504										
QT EPA 508/608.3/8081A										
QT EPA 515.1/8151A										
QT EPA 525.2										
QT EPA 525.2 TRAVEL BLANK										
40ml EPA 547										
40ml EPA 531.1										
8oz EPA 548.1										
QT EPA 549.2										
QT EPA 8015M										
QT EPA 8270C										
8oz / 16oz / 32oz AMBER										
8oz / 16oz / 32oz JAR										
SOIL SLEEVE plastic	A	A	A	A	A	A				
PCB VIAL										
PLASTIC BAG										
TEDLAR BAG										
FERROUS IRON										
ENCORE										
SMART KIT										
SUMMA CANISTER										

Comments:

Sample Numbering Completed By: EJA Date/Time: 10/20/21 1030

A = Actual / C = Corrected

Rev 22 04/13/21

[S:\WPDocs\WordPerfect\LAB_DOCS\FORMS\SAMREC rev 20]

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Laboratory / Client Sample Cross Reference

Laboratory	Client Sample Information			
2132975-01	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 10:14
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SB-1-1	**Lab Matrix:**	Solids
	Sampled By:	Lawrence Bush	**Sample Type:**	Soil
2132975-02	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 10:15
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SB-1-2.5	**Lab Matrix:**	Solids
	Sampled By:	Lawrence Bush	**Sample Type:**	Soil
2132975-03	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 10:09
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SB-2-1	**Lab Matrix:**	Solids
	Sampled By:	Lawrence Bush	**Sample Type:**	Soil
2132975-04	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 10:10
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SB-2-2.5	**Lab Matrix:**	Solids
	Sampled By:	Lawrence Bush	**Sample Type:**	Soil
2132975-05	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 10:04
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SB-3-1	**Lab Matrix:**	Solids
	Sampled By:	Lawrence Bush	**Sample Type:**	Soil
2132975-06	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 10:05
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SB-3-2.5	**Lab Matrix:**	Solids
	Sampled By:	Lawrence Bush	**Sample Type:**	Soil

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Organochlorine Pesticides (EPA Method 8081A)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Aldrin	ND	mg/kg	0.0025	0.000090	EPA-8081A	1.4	A10	1
alpha-BHC	ND	mg/kg	0.0025	0.00019	EPA-8081A		A10	1
beta-BHC	ND	mg/kg	0.0025	0.00024	EPA-8081A		A10	1
delta-BHC	ND	mg/kg	0.0025	0.00018	EPA-8081A		A10	1
gamma-BHC (Lindane)	ND	mg/kg	0.0025	0.000090	EPA-8081A	4.0	A10	1
Chlordane (Technical)	ND	mg/kg	0.25	0.0050	EPA-8081A	2.5	A10	1
4,4'-DDD	**0.00070**	**mg/kg**	**0.0025**	**0.00032**	**EPA-8081A**	1.0	**J,A10**	1
4,4'-DDE	**0.019**	**mg/kg**	**0.0025**	**0.00048**	**EPA-8081A**	1.0	**A10**	1
4,4'-DDT	**0.0035**	**mg/kg**	**0.0025**	**0.00020**	**EPA-8081A**	1.0	**A10**	1
Dieldrin	**0.00090**	**mg/kg**	**0.0025**	**0.00018**	**EPA-8081A**	8.0	**J,A10**	1
Endosulfan I	ND	mg/kg	0.0025	0.00010	EPA-8081A		A10	1
Endosulfan II	ND	mg/kg	0.0025	0.00017	EPA-8081A		A10	1
Endosulfan sulfate	ND	mg/kg	0.0025	0.00013	EPA-8081A		A10	1
Endrin	ND	mg/kg	0.0025	0.00032	EPA-8081A	0.2	A10	1
Endrin aldehyde	ND	mg/kg	0.0025	0.000090	EPA-8081A		A10	1
Heptachlor	ND	mg/kg	0.0025	0.00043	EPA-8081A	4.7	A10	1
Heptachlor epoxide	ND	mg/kg	0.0025	0.000085	EPA-8081A		A10	1
Methoxychlor	ND	mg/kg	0.0025	0.00047	EPA-8081A	100	A10	1
Toxaphene	**0.031**	**mg/kg**	**0.25**	**0.0070**	**EPA-8081A**	5	**J,A10**	1
TCMX (Surrogate)	76.1	%	20 - 130 (LCL - UCL)		EPA-8081A		A10	1
Decachlorobiphenyl (Surrogate)	79.2	%	40 - 130 (LCL - UCL)		EPA-8081A		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8081A	10/21/21 17:30	10/22/21 14:24	HKS	GC-17	5.068	B122973	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

PCB Analysis (EPA Method 8082)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
PCB-1016	ND	mg/kg	0.010	0.0023	EPA-8082	50		1
PCB-1221	ND	mg/kg	0.010	0.0033	EPA-8082	50		1
PCB-1232	ND	mg/kg	0.010	0.0026	EPA-8082	50		1
PCB-1242	ND	mg/kg	0.010	0.0015	EPA-8082	50		1
PCB-1248	ND	mg/kg	0.010	0.0021	EPA-8082	50		1
PCB-1254	ND	mg/kg	0.010	0.0016	EPA-8082	50		1
PCB-1260	**0.0087**	**mg/kg**	**0.010**	**0.0018**	**EPA-8082**	50	**J**	1
Total PCB's (Summation)	**0.0087**	**mg/kg**	**0.010**	**0.0050**	**EPA-8082**	50	**J**	1
Decachlorobiphenyl (Surrogate)	66.7	%	40 - 120 (LCL - UCL)		EPA-8082			1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8082	10/21/21 16:00	10/22/21 10:15	HKS	GC-14	1.007	B122999	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Benzene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
Bromobenzene	ND	mg/kg	0.0050	0.00087	EPA-8260B			1
Bromochloromethane	ND	mg/kg	0.0050	0.00081	EPA-8260B			1
Bromodichloromethane	ND	mg/kg	0.0050	0.00078	EPA-8260B			1
Bromoform	ND	mg/kg	0.0050	0.00070	EPA-8260B			1
Bromomethane	ND	mg/kg	0.0050	0.0017	EPA-8260B			1
n-Butylbenzene	ND	mg/kg	0.0050	0.00076	EPA-8260B			1
sec-Butylbenzene	ND	mg/kg	0.0050	0.00071	EPA-8260B			1
tert-Butylbenzene	ND	mg/kg	0.0050	0.00085	EPA-8260B			1
Carbon tetrachloride	ND	mg/kg	0.0050	0.00078	EPA-8260B			1
Chlorobenzene	ND	mg/kg	0.0050	0.00077	EPA-8260B			1
Chloroethane	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
Chloroform	ND	mg/kg	0.0050	0.00090	EPA-8260B			1
Chloromethane	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
2-Chlorotoluene	ND	mg/kg	0.0050	0.00087	EPA-8260B			1
4-Chlorotoluene	ND	mg/kg	0.0050	0.00070	EPA-8260B			1
Dibromochloromethane	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,2-Dibromo-3-chloropropane	ND	mg/kg	0.0050	0.00096	EPA-8260B			1
1,2-Dibromoethane	ND	mg/kg	0.0050	0.00082	EPA-8260B			1
Dibromomethane	ND	mg/kg	0.0050	0.0014	EPA-8260B			1
1,2-Dichlorobenzene	ND	mg/kg	0.0050	0.00079	EPA-8260B			1
1,3-Dichlorobenzene	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
1,4-Dichlorobenzene	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
Dichlorodifluoromethane	ND	mg/kg	0.0050	0.00079	EPA-8260B			1
1,1-Dichloroethane	ND	mg/kg	0.0050	0.00064	EPA-8260B			1
1,2-Dichloroethane	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
1,1-Dichloroethene	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
cis-1,2-Dichloroethene	ND	mg/kg	0.0050	0.00054	EPA-8260B			1
trans-1,2-Dichloroethene	ND	mg/kg	0.0050	0.0037	EPA-8260B			1
1,2-Dichloropropane	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,3-Dichloropropane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
2,2-Dichloropropane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
1,1-Dichloropropene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
cis-1,3-Dichloropropene	ND	mg/kg	0.0050	0.00058	EPA-8260B			1
trans-1,3-Dichloropropene	ND	mg/kg	0.0050	0.00066	EPA-8260B			1
Ethylbenzene	ND	mg/kg	0.0050	0.00069	EPA-8260B			1
Hexachlorobutadiene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
Isopropylbenzene	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
p-Isopropyltoluene	ND	mg/kg	0.0050	0.00059	EPA-8260B			1
Methylene chloride	ND	mg/kg	0.010	0.0011	EPA-8260B			1
Methyl t-butyl ether	ND	mg/kg	0.0050	0.00056	EPA-8260B			1
Naphthalene	ND	mg/kg	0.0050	0.00099	EPA-8260B			1
n-Propylbenzene	ND	mg/kg	0.0050	0.00071	EPA-8260B			1
Styrene	ND	mg/kg	0.0050	0.00062	EPA-8260B			1
1,1,1,2-Tetrachloroethane	ND	mg/kg	0.0050	0.00095	EPA-8260B			1
1,1,2,2-Tetrachloroethane	ND	mg/kg	0.0050	0.00084	EPA-8260B			1
Tetrachloroethene	ND	mg/kg	0.0050	0.00097	EPA-8260B			1
Toluene	ND	mg/kg	0.0050	0.00069	EPA-8260B			1
1,2,3-Trichlorobenzene	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
1,2,4-Trichlorobenzene	ND	mg/kg	0.0050	0.0014	EPA-8260B			1
1,1,1-Trichloroethane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
1,1,2-Trichloroethane	ND	mg/kg	0.0050	0.00094	EPA-8260B			1
Trichloroethene	ND	mg/kg	0.0050	0.00074	EPA-8260B	2040		1
Trichlorofluoromethane	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
1,2,3-Trichloropropane	ND	mg/kg	0.0050	0.0019	EPA-8260B			1
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	mg/kg	0.0050	0.0010	EPA-8260B			1
1,2,4-Trimethylbenzene	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,3,5-Trimethylbenzene	ND	mg/kg	0.0050	0.00066	EPA-8260B			1
Vinyl chloride	ND	mg/kg	0.0050	0.00059	EPA-8260B			1
Total Xylenes	ND	mg/kg	0.010	0.0025	EPA-8260B			1
p- & m-Xylenes	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
o-Xylene	ND	mg/kg	0.0050	0.00093	EPA-8260B			1
1,2-Dichloroethane-d4 (Surrogate)	101	%	70 - 121 (LCL - UCL)		EPA-8260B			1
Toluene-d8 (Surrogate)	98.8	%	81 - 117 (LCL - UCL)		EPA-8260B			1
4-Bromofluorobenzene (Surrogate)	96.8	%	74 - 121 (LCL - UCL)		EPA-8260B			1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	
1	EPA-8260B	10/20/21 15:55	10/20/21 18:23	RCC	MS-V17	1	B122675	EPA 5030 Soil MS

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Acenaphthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Acenaphthylene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Aldrin	ND	mg/kg	1.0	0.067	EPA-8270C	1.4	A10	1
Aniline	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
Anthracene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzidine	ND	mg/kg	30	0.093	EPA-8270C		A10	1
Benzo[a]anthracene	ND	mg/kg	1.0	0.077	EPA-8270C		A10	1
Benzo[b]fluoranthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzo[k]fluoranthene	ND	mg/kg	1.0	0.082	EPA-8270C		A10	1
Benzo[a]pyrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzo[g,h,i]perylene	ND	mg/kg	1.0	0.13	EPA-8270C		A10	1
Benzoic acid	ND	mg/kg	5.0	0.14	EPA-8270C		A10	1
Benzyl alcohol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzyl butyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
alpha-BHC	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
beta-BHC	ND	mg/kg	1.0	0.075	EPA-8270C		A10	1
delta-BHC	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
gamma-BHC (Lindane)	ND	mg/kg	1.0	0.067	EPA-8270C	4.0	A10	1
bis(2-Chloroethoxy)methane	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
bis(2-Chloroethyl) ether	ND	mg/kg	1.0	0.097	EPA-8270C		A10	1
bis(2-Chloroisopropyl)ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
bis(2-Ethylhexyl)phthalate	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
4-Bromophenyl phenyl ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chloroaniline	ND	mg/kg	1.0	0.15	EPA-8270C		A10	1
2-Chloronaphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chlorophenyl phenyl ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Chrysene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4,4'-DDD	ND	mg/kg	1.0	0.067	EPA-8270C	1.0	A10	1
4,4'-DDE	ND	mg/kg	1.0	0.068	EPA-8270C	1.0	A10	1
4,4'-DDT	ND	mg/kg	1.0	0.067	EPA-8270C	1.0	A10	1
Dibenzo[a,h]anthracene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Dibenzofuran	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
1,3-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,4-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3,3-Dichlorobenzidine	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
Dieldrin	ND	mg/kg	1.0	0.077	EPA-8270C	8.0	A10	1
Diethyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Dimethyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Di-n-butyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dinitrotoluene	ND	mg/kg	1.0	0.085	EPA-8270C		A10	1
2,6-Dinitrotoluene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Di-n-octyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2-Diphenylhydrazine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Endosulfan I	ND	mg/kg	2.0	0.088	EPA-8270C		A10	1
Endosulfan II	ND	mg/kg	2.0	0.088	EPA-8270C		A10	1
Endosulfan sulfate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Endrin	ND	mg/kg	2.0	0.086	EPA-8270C	0.2	A10	1
Endrin aldehyde	ND	mg/kg	5.0	0.070	EPA-8270C		A10	1
Fluoranthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Fluorene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Heptachlor	ND	mg/kg	1.0	0.067	EPA-8270C	4.7	A10	1
Heptachlor epoxide	ND	mg/kg	1.0	0.13	EPA-8270C		A10	1
Hexachlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Hexachlorobutadiene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Hexachlorocyclopentadiene	ND	mg/kg	1.0	0.15	EPA-8270C		A10	1
Hexachloroethane	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Indeno[1,2,3-cd]pyrene	ND	mg/kg	1.0	0.069	EPA-8270C		A10	1
Isophorone	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2-Methylnaphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Naphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2-Naphthylamine	ND	mg/kg	30	0.36	EPA-8270C		A10	1
2-Nitroaniline	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3-Nitroaniline	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
4-Nitroaniline	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
Nitrobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
N-Nitrosodimethylamine	ND	mg/kg	1.0	0.40	EPA-8270C		A10	1
N-Nitrosodi-N-propylamine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
N-Nitrosodiphenylamine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Phenanthrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Pyrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2,4-Trichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chloro-3-methylphenol	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
2-Chlorophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dichlorophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dimethylphenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4,6-Dinitro-2-methylphenol	ND	mg/kg	5.0	0.067	EPA-8270C		A10	1
2,4-Dinitrophenol	ND	mg/kg	5.0	0.067	EPA-8270C		A10	1
2-Methylphenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3- & 4-Methylphenol	ND	mg/kg	2.0	0.14	EPA-8270C		A10	1
2-Nitrophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Nitrophenol	ND	mg/kg	2.0	0.18	EPA-8270C		A10	1
Pentachlorophenol	ND	mg/kg	2.0	0.17	EPA-8270C	17	A10	1
Phenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4,5-Trichlorophenol	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
2,4,6-Trichlorophenol	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
2-Fluorophenol (Surrogate)	65.6	%	20 - 130 (LCL - UCL)		EPA-8270C		A10	1
Phenol-d5 (Surrogate)	60.9	%	30 - 130 (LCL - UCL)		EPA-8270C		A10	1
Nitrobenzene-d5 (Surrogate)	68.1	%	30 - 130 (LCL - UCL)		EPA-8270C		A10	1
2-Fluorobiphenyl (Surrogate)	62.1	%	30 - 140 (LCL - UCL)		EPA-8270C		A10	1
2,4,6-Tribromophenol (Surrogate)	39.4	%	20 - 150 (LCL - UCL)		EPA-8270C		A10	1
p-Terphenyl-d14 (Surrogate)	52.0	%	30 - 150 (LCL - UCL)		EPA-8270C		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8270C	10/22/21 08:00	10/22/21 21:41	CMM	MS-B2	9.867	B123094	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Petroleum Hydrocarbons

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
TPH - Gasoline (C4-C12)	ND	mg/kg	4.0	1.0	EPA-8015B	ND		1
TPH - Diesel (C13 - C22)	**3.1**	**mg/kg**	**2.0**	**0.77**	**EPA-8015B**	ND	**A52**	1
TPH - Motor Oil (C23 - C36)	**29**	**mg/kg**	**4.0**	**1.8**	**EPA-8015B**	ND	**A57**	1
Tetracosane (Surrogate)	94.3	%	20 - 145 (LCL - UCL)		EPA-8015B			1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8015B	10/21/21 15:00	10/22/21 10:53	BUP	GC-19	1.014	B122699	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Concentrations (TTLC)

BCL Sample ID: 2132975-01 | **Client Sample Name:** SB-1-1, 10/19/2021 10:14:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Antimony	**1.9**	**mg/kg**	**5.0**	**0.33**	**EPA-6010B**	500	**J**	1
Arsenic	**2.6**	**mg/kg**	**1.0**	**0.40**	**EPA-6010B**	500		1
Barium	**130**	**mg/kg**	**0.50**	**0.18**	**EPA-6010B**	10000		1
Beryllium	**0.31**	**mg/kg**	**0.50**	**0.047**	**EPA-6010B**	75	**J**	1
Cadmium	**0.58**	**mg/kg**	**0.50**	**0.052**	**EPA-6010B**	100		1
Chromium	**120**	**mg/kg**	**0.50**	**0.050**	**EPA-6010B**	2500	**S11**	1
Cobalt	**24**	**mg/kg**	**2.5**	**0.098**	**EPA-6010B**	8000		1
Copper	**56**	**mg/kg**	**1.0**	**0.050**	**EPA-6010B**	2500		1
Lead	**7.8**	**mg/kg**	**2.5**	**0.41**	**EPA-6010B**	1000		1
Mercury	**0.069**	**mg/kg**	**0.16**	**0.016**	**EPA-7471A**	20	**J**	2
Molybdenum	**0.43**	**mg/kg**	**2.5**	**0.050**	**EPA-6010B**	3500	**J**	1
Nickel	**87**	**mg/kg**	**0.50**	**0.15**	**EPA-6010B**	2000	**S11**	1
Selenium	ND	mg/kg	1.0	0.98	EPA-6010B	100		1
Silver	**0.15**	**mg/kg**	**0.50**	**0.067**	**EPA-6010B**	500	**J**	1
Thallium	ND	mg/kg	50	6.4	EPA-6010B	700	A10	3
Vanadium	**100**	**mg/kg**	**0.50**	**0.11**	**EPA-6010B**	2400		1
Zinc	**57**	**mg/kg**	**2.5**	**0.087**	**EPA-6010B**	5000		1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-6010B	10/21/21 06:30	10/21/21 17:31	JCC	PE-OP3	1	B122837	EPA 3050B
2	EPA-7471A	10/25/21 08:25	10/25/21 11:37	TMT	CETAC3	0.977	B123042	EPA 7471A
3	EPA-6010B	10/21/21 06:30	10/22/21 18:17	JCC	PE-OP3	10	B122837	EPA 3050B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Chemical Analysis

BCL Sample ID: 2132975-02 | **Client Sample Name:** SB-1-2.5, 10/19/2021 10:15:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
pH	**7.73**	**pH Units**	**0.05**	**0.05**	**EPA-9045D**	ND	**pH1:1**	1
pH Measurement Temperature	**25.1**	**C**	**0.1**	**0.1**	**EPA-9045D**	ND		1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-9045D	10/28/21 11:30	10/28/21 11:30	RT1	MANUAL	1	B123604	EPA 9045

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Organochlorine Pesticides (EPA Method 8081A)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Aldrin	ND	mg/kg	0.0050	0.00018	EPA-8081A	1.4	A10	1
alpha-BHC	ND	mg/kg	0.0050	0.00038	EPA-8081A		A10	1
beta-BHC	ND	mg/kg	0.0050	0.00048	EPA-8081A		A10	1
delta-BHC	ND	mg/kg	0.0050	0.00037	EPA-8081A		A10	1
gamma-BHC (Lindane)	ND	mg/kg	0.0050	0.00018	EPA-8081A	4.0	A10	1
Chlordane (Technical)	ND	mg/kg	0.50	0.010	EPA-8081A	2.5	A10	1
4,4'-DDD	**0.00074**	**mg/kg**	**0.0050**	**0.00064**	**EPA-8081A**	1.0	**J,A10**	1
4,4'-DDE	ND	mg/kg	0.0050	0.00095	EPA-8081A	1.0	A10	1
4,4'-DDT	**0.0016**	**mg/kg**	**0.0050**	**0.00040**	**EPA-8081A**	1.0	**J,A10**	1
Dieldrin	ND	mg/kg	0.0050	0.00036	EPA-8081A	8.0	A10	1
Endosulfan I	ND	mg/kg	0.0050	0.00020	EPA-8081A		A10	1
Endosulfan II	ND	mg/kg	0.0050	0.00034	EPA-8081A		A10	1
Endosulfan sulfate	ND	mg/kg	0.0050	0.00026	EPA-8081A		A10	1
Endrin	ND	mg/kg	0.0050	0.00065	EPA-8081A	0.2	A10	1
Endrin aldehyde	ND	mg/kg	0.0050	0.00018	EPA-8081A		A10	1
Heptachlor	ND	mg/kg	0.0050	0.00086	EPA-8081A	4.7	A10	1
Heptachlor epoxide	ND	mg/kg	0.0050	0.00017	EPA-8081A		A10	1
Methoxychlor	ND	mg/kg	0.0050	0.00094	EPA-8081A	100	A10	1
Toxaphene	ND	mg/kg	0.50	0.014	EPA-8081A	5	A10	1
TCMX (Surrogate)	77.3	%	20 - 130 (LCL - UCL)		EPA-8081A		A10	1
Decachlorobiphenyl (Surrogate)	75.5	%	40 - 130 (LCL - UCL)		EPA-8081A		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8081A	10/21/21 17:30	10/22/21 14:38	HKS	GC-17	9.868	B122973	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

PCB Analysis (EPA Method 8082)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
PCB-1016	ND	mg/kg	0.10	0.023	EPA-8082	50	A10	1
PCB-1221	ND	mg/kg	0.10	0.033	EPA-8082	50	A10	1
PCB-1232	ND	mg/kg	0.10	0.026	EPA-8082	50	A10	1
PCB-1242	ND	mg/kg	0.10	0.015	EPA-8082	50	A10	1
PCB-1248	ND	mg/kg	0.10	0.021	EPA-8082	50	A10	1
PCB-1254	ND	mg/kg	0.10	0.016	EPA-8082	50	A10	1
PCB-1260	ND	mg/kg	0.10	0.018	EPA-8082	50	A10	1
Total PCB's (Summation)	ND	mg/kg	0.10	0.050	EPA-8082	50	A10	1
Decachlorobiphenyl (Surrogate)	83.3	%	40 - 120 (LCL - UCL)		EPA-8082		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8082	10/21/21 16:00	10/22/21 10:27	HKS	GC-14	10.101	B122999	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Benzene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
Bromobenzene	ND	mg/kg	0.0050	0.00087	EPA-8260B			1
Bromochloromethane	ND	mg/kg	0.0050	0.00081	EPA-8260B			1
Bromodichloromethane	ND	mg/kg	0.0050	0.00078	EPA-8260B			1
Bromoform	ND	mg/kg	0.0050	0.00070	EPA-8260B			1
Bromomethane	ND	mg/kg	0.0050	0.0017	EPA-8260B			1
n-Butylbenzene	ND	mg/kg	0.0050	0.00076	EPA-8260B			1
sec-Butylbenzene	ND	mg/kg	0.0050	0.00071	EPA-8260B			1
tert-Butylbenzene	ND	mg/kg	0.0050	0.00085	EPA-8260B			1
Carbon tetrachloride	ND	mg/kg	0.0050	0.00078	EPA-8260B			1
Chlorobenzene	ND	mg/kg	0.0050	0.00077	EPA-8260B			1
Chloroethane	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
Chloroform	ND	mg/kg	0.0050	0.00090	EPA-8260B			1
Chloromethane	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
2-Chlorotoluene	ND	mg/kg	0.0050	0.00087	EPA-8260B			1
4-Chlorotoluene	ND	mg/kg	0.0050	0.00070	EPA-8260B			1
Dibromochloromethane	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,2-Dibromo-3-chloropropane	ND	mg/kg	0.0050	0.00096	EPA-8260B			1
1,2-Dibromoethane	ND	mg/kg	0.0050	0.00082	EPA-8260B			1
Dibromomethane	ND	mg/kg	0.0050	0.0014	EPA-8260B			1
1,2-Dichlorobenzene	ND	mg/kg	0.0050	0.00079	EPA-8260B			1
1,3-Dichlorobenzene	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
1,4-Dichlorobenzene	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
Dichlorodifluoromethane	ND	mg/kg	0.0050	0.00079	EPA-8260B			1
1,1-Dichloroethane	ND	mg/kg	0.0050	0.00064	EPA-8260B			1
1,2-Dichloroethane	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
1,1-Dichloroethene	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
cis-1,2-Dichloroethene	ND	mg/kg	0.0050	0.00054	EPA-8260B			1
trans-1,2-Dichloroethene	ND	mg/kg	0.0050	0.0037	EPA-8260B			1
1,2-Dichloropropane	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,3-Dichloropropane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
2,2-Dichloropropane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
1,1-Dichloropropene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
cis-1,3-Dichloropropene	ND	mg/kg	0.0050	0.00058	EPA-8260B			1
trans-1,3-Dichloropropene	ND	mg/kg	0.0050	0.00066	EPA-8260B			1
Ethylbenzene	ND	mg/kg	0.0050	0.00069	EPA-8260B			1
Hexachlorobutadiene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
Isopropylbenzene	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
p-Isopropyltoluene	ND	mg/kg	0.0050	0.00059	EPA-8260B			1
Methylene chloride	ND	mg/kg	0.010	0.0011	EPA-8260B			1
Methyl t-butyl ether	ND	mg/kg	0.0050	0.00056	EPA-8260B			1
Naphthalene	ND	mg/kg	0.0050	0.00099	EPA-8260B			1
n-Propylbenzene	ND	mg/kg	0.0050	0.00071	EPA-8260B			1
Styrene	ND	mg/kg	0.0050	0.00062	EPA-8260B			1
1,1,1,2-Tetrachloroethane	ND	mg/kg	0.0050	0.00095	EPA-8260B			1
1,1,2,2-Tetrachloroethane	ND	mg/kg	0.0050	0.00084	EPA-8260B			1
Tetrachloroethene	ND	mg/kg	0.0050	0.00097	EPA-8260B			1
Toluene	ND	mg/kg	0.0050	0.00069	EPA-8260B			1
1,2,3-Trichlorobenzene	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
1,2,4-Trichlorobenzene	ND	mg/kg	0.0050	0.0014	EPA-8260B			1
1,1,1-Trichloroethane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
1,1,2-Trichloroethane	ND	mg/kg	0.0050	0.00094	EPA-8260B			1
Trichloroethene	ND	mg/kg	0.0050	0.00074	EPA-8260B	2040		1
Trichlorofluoromethane	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
1,2,3-Trichloropropane	ND	mg/kg	0.0050	0.0019	EPA-8260B			1
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	mg/kg	0.0050	0.0010	EPA-8260B			1
1,2,4-Trimethylbenzene	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,3,5-Trimethylbenzene	ND	mg/kg	0.0050	0.00066	EPA-8260B			1
Vinyl chloride	ND	mg/kg	0.0050	0.00059	EPA-8260B			1
Total Xylenes	ND	mg/kg	0.010	0.0025	EPA-8260B			1
p- & m-Xylenes	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
o-Xylene	ND	mg/kg	0.0050	0.00093	EPA-8260B			1
1,2-Dichloroethane-d4 (Surrogate)	103	%	70 - 121 (LCL - UCL)		EPA-8260B			1
Toluene-d8 (Surrogate)	98.1	%	81 - 117 (LCL - UCL)		EPA-8260B			1
4-Bromofluorobenzene (Surrogate)	93.8	%	74 - 121 (LCL - UCL)		EPA-8260B			1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	
1	EPA-8260B	10/20/21 15:55	10/20/21 18:44	RCC	MS-V17	1	B122675	EPA 5030 Soil MS

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Acenaphthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Acenaphthylene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Aldrin	ND	mg/kg	1.0	0.067	EPA-8270C	1.4	A10	1
Aniline	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
Anthracene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzidine	ND	mg/kg	30	0.093	EPA-8270C		A10	1
Benzo[a]anthracene	ND	mg/kg	1.0	0.077	EPA-8270C		A10	1
Benzo[b]fluoranthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzo[k]fluoranthene	ND	mg/kg	1.0	0.082	EPA-8270C		A10	1
Benzo[a]pyrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzo[g,h,i]perylene	ND	mg/kg	1.0	0.13	EPA-8270C		A10	1
Benzoic acid	ND	mg/kg	5.0	0.14	EPA-8270C		A10	1
Benzyl alcohol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzyl butyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
alpha-BHC	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
beta-BHC	ND	mg/kg	1.0	0.075	EPA-8270C		A10	1
delta-BHC	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
gamma-BHC (Lindane)	ND	mg/kg	1.0	0.067	EPA-8270C	4.0	A10	1
bis(2-Chloroethoxy)methane	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
bis(2-Chloroethyl) ether	ND	mg/kg	1.0	0.097	EPA-8270C		A10	1
bis(2-Chloroisopropyl)ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
bis(2-Ethylhexyl)phthalate	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
4-Bromophenyl phenyl ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chloroaniline	ND	mg/kg	1.0	0.15	EPA-8270C		A10	1
2-Chloronaphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chlorophenyl phenyl ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Chrysene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4,4'-DDD	ND	mg/kg	1.0	0.067	EPA-8270C	1.0	A10	1
4,4'-DDE	ND	mg/kg	1.0	0.068	EPA-8270C	1.0	A10	1
4,4'-DDT	ND	mg/kg	1.0	0.067	EPA-8270C	1.0	A10	1
Dibenzo[a,h]anthracene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Dibenzofuran	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
1,3-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,4-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3,3-Dichlorobenzidine	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
Dieldrin	ND	mg/kg	1.0	0.077	EPA-8270C	8.0	A10	1
Diethyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Dimethyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Di-n-butyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dinitrotoluene	ND	mg/kg	1.0	0.085	EPA-8270C		A10	1
2,6-Dinitrotoluene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Di-n-octyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2-Diphenylhydrazine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Endosulfan I	ND	mg/kg	2.0	0.088	EPA-8270C		A10	1
Endosulfan II	ND	mg/kg	2.0	0.088	EPA-8270C		A10	1
Endosulfan sulfate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Endrin	ND	mg/kg	2.0	0.086	EPA-8270C	0.2	A10	1
Endrin aldehyde	ND	mg/kg	5.0	0.070	EPA-8270C		A10	1
Fluoranthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Fluorene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Heptachlor	ND	mg/kg	1.0	0.067	EPA-8270C	4.7	A10	1
Heptachlor epoxide	ND	mg/kg	1.0	0.13	EPA-8270C		A10	1
Hexachlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Hexachlorobutadiene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Hexachlorocyclopentadiene	ND	mg/kg	1.0	0.15	EPA-8270C		A10	1
Hexachloroethane	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Indeno[1,2,3-cd]pyrene	ND	mg/kg	1.0	0.069	EPA-8270C		A10	1
Isophorone	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2-Methylnaphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Naphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2-Naphthylamine	ND	mg/kg	30	0.36	EPA-8270C		A10	1
2-Nitroaniline	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3-Nitroaniline	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
4-Nitroaniline	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
Nitrobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
N-Nitrosodimethylamine	ND	mg/kg	1.0	0.40	EPA-8270C		A10	1
N-Nitrosodi-N-propylamine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
N-Nitrosodiphenylamine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Phenanthrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Pyrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2,4-Trichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chloro-3-methylphenol	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
2-Chlorophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dichlorophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dimethylphenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4,6-Dinitro-2-methylphenol	ND	mg/kg	5.0	0.067	EPA-8270C		A10	1
2,4-Dinitrophenol	ND	mg/kg	5.0	0.067	EPA-8270C		A10	1
2-Methylphenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3- & 4-Methylphenol	ND	mg/kg	2.0	0.14	EPA-8270C		A10	1
2-Nitrophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Nitrophenol	ND	mg/kg	2.0	0.18	EPA-8270C		A10	1
Pentachlorophenol	ND	mg/kg	2.0	0.17	EPA-8270C	17	A10	1
Phenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4,5-Trichlorophenol	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
2,4,6-Trichlorophenol	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
2-Fluorophenol (Surrogate)	86.9	%	20 - 130 (LCL - UCL)		EPA-8270C		A10	1
Phenol-d5 (Surrogate)	79.7	%	30 - 130 (LCL - UCL)		EPA-8270C		A10	1
Nitrobenzene-d5 (Surrogate)	88.1	%	30 - 130 (LCL - UCL)		EPA-8270C		A10	1
2-Fluorobiphenyl (Surrogate)	78.5	%	30 - 140 (LCL - UCL)		EPA-8270C		A10	1
2,4,6-Tribromophenol (Surrogate)	55.4	%	20 - 150 (LCL - UCL)		EPA-8270C		A10	1
p-Terphenyl-d14 (Surrogate)	58.1	%	30 - 150 (LCL - UCL)		EPA-8270C		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8270C	10/22/21 08:00	10/22/21 22:07	CMM	MS-B2	9.763	B123094	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Petroleum Hydrocarbons

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
TPH - Gasoline (C4-C12)	ND	mg/kg	4.0	1.0	EPA-8015B	ND		1
TPH - Diesel (C13 - C22)	**2.5**	**mg/kg**	**2.0**	**0.77**	**EPA-8015B**	ND	**A52**	1
TPH - Motor Oil (C23 - C36)	**33**	**mg/kg**	**4.0**	**1.8**	**EPA-8015B**	ND	**A57**	1
Tetracosane (Surrogate)	69.0	%	20 - 145 (LCL - UCL)		EPA-8015B			1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8015B	10/21/21 15:00	10/22/21 11:22	BUP	GC-19	1.014	B122699	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Concentrations (TTLC)

BCL Sample ID: 2132975-03 | **Client Sample Name:** SB-2-1, 10/19/2021 10:09:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Antimony	**1.7**	**mg/kg**	**5.0**	**0.33**	**EPA-6010B**	500	**J**	1
Arsenic	**3.7**	**mg/kg**	**1.0**	**0.40**	**EPA-6010B**	500		1
Barium	**150**	**mg/kg**	**0.50**	**0.18**	**EPA-6010B**	10000		1
Beryllium	**0.32**	**mg/kg**	**0.50**	**0.047**	**EPA-6010B**	75	**J**	1
Cadmium	**0.61**	**mg/kg**	**0.50**	**0.052**	**EPA-6010B**	100		1
Chromium	**120**	**mg/kg**	**0.50**	**0.050**	**EPA-6010B**	2500	**S11**	1
Cobalt	**24**	**mg/kg**	**2.5**	**0.098**	**EPA-6010B**	8000		1
Copper	**55**	**mg/kg**	**1.0**	**0.050**	**EPA-6010B**	2500		1
Lead	**17**	**mg/kg**	**2.5**	**0.41**	**EPA-6010B**	1000		1
Mercury	**0.15**	**mg/kg**	**0.16**	**0.016**	**EPA-7471A**	20	**J**	2
Molybdenum	**0.50**	**mg/kg**	**2.5**	**0.050**	**EPA-6010B**	3500	**J**	1
Nickel	**84**	**mg/kg**	**0.50**	**0.15**	**EPA-6010B**	2000	**S11**	1
Selenium	ND	mg/kg	1.0	0.98	EPA-6010B	100		1
Silver	**0.41**	**mg/kg**	**0.50**	**0.067**	**EPA-6010B**	500	**J**	1
Thallium	ND	mg/kg	50	6.4	EPA-6010B	700	A10	3
Vanadium	**100**	**mg/kg**	**0.50**	**0.11**	**EPA-6010B**	2400		1
Zinc	**61**	**mg/kg**	**2.5**	**0.087**	**EPA-6010B**	5000		1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-6010B	10/21/21 06:30	10/21/21 17:33	JCC	PE-OP3	0.962	B122837	EPA 3050B
2	EPA-7471A	10/25/21 08:25	10/25/21 11:39	TMT	CETAC3	0.962	B123042	EPA 7471A
3	EPA-6010B	10/21/21 06:30	10/22/21 18:20	JCC	PE-OP3	9.615	B122837	EPA 3050B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Chemical Analysis

BCL Sample ID: 2132975-04 | **Client Sample Name:** SB-2-2.5, 10/19/2021 10:10:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
pH	**7.56**	**pH Units**	**0.05**	**0.05**	**EPA-9045D**	ND	**pH1:1**	1
pH Measurement Temperature	**25.1**	**C**	**0.1**	**0.1**	**EPA-9045D**	ND		1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-9045D	10/28/21 11:30	10/28/21 11:30	RT1	MANUAL	1	B123604	EPA 9045

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Organochlorine Pesticides (EPA Method 8081A)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Aldrin	ND	mg/kg	0.0050	0.00018	EPA-8081A	1.4	A10	1
alpha-BHC	ND	mg/kg	0.0050	0.00038	EPA-8081A		A10	1
beta-BHC	ND	mg/kg	0.0050	0.00048	EPA-8081A		A10	1
delta-BHC	ND	mg/kg	0.0050	0.00037	EPA-8081A		A10	1
gamma-BHC (Lindane)	ND	mg/kg	0.0050	0.00018	EPA-8081A	4.0	A10	1
Chlordane (Technical)	**0.037**	**mg/kg**	**0.50**	**0.010**	**EPA-8081A**	2.5	**J,A10**	1
4,4'-DDD	**0.0033**	**mg/kg**	**0.0050**	**0.00064**	**EPA-8081A**	1.0	**J,A10**	1
4,4'-DDE	**0.0018**	**mg/kg**	**0.0050**	**0.00095**	**EPA-8081A**	1.0	**J,A10**	1
4,4'-DDT	**0.0053**	**mg/kg**	**0.0050**	**0.00040**	**EPA-8081A**	1.0	**A10**	1
Dieldrin	**0.0077**	**mg/kg**	**0.0050**	**0.00036**	**EPA-8081A**	8.0	**A10**	1
Endosulfan I	ND	mg/kg	0.0050	0.00020	EPA-8081A		A10	1
Endosulfan II	ND	mg/kg	0.0050	0.00034	EPA-8081A		A10	1
Endosulfan sulfate	ND	mg/kg	0.0050	0.00026	EPA-8081A		A10	1
Endrin	ND	mg/kg	0.0050	0.00065	EPA-8081A	0.2	A10	1
Endrin aldehyde	ND	mg/kg	0.0050	0.00018	EPA-8081A		A10	1
Heptachlor	ND	mg/kg	0.0050	0.00086	EPA-8081A	4.7	A10	1
Heptachlor epoxide	ND	mg/kg	0.0050	0.00017	EPA-8081A		A10	1
Methoxychlor	ND	mg/kg	0.0050	0.00094	EPA-8081A	100	A10	1
Toxaphene	ND	mg/kg	0.50	0.014	EPA-8081A	5	A10	1
TCMX (Surrogate)	103	%	20 - 130 (LCL - UCL)		EPA-8081A		A10	1
Decachlorobiphenyl (Surrogate)	88.1	%	40 - 130 (LCL - UCL)		EPA-8081A		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8081A	10/21/21 17:30	10/22/21 14:53	HKS	GC-17	10.067	B122973	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

PCB Analysis (EPA Method 8082)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
PCB-1016	ND	mg/kg	0.10	0.023	EPA-8082	50	A10	1
PCB-1221	ND	mg/kg	0.10	0.033	EPA-8082	50	A10	1
PCB-1232	ND	mg/kg	0.10	0.026	EPA-8082	50	A10	1
PCB-1242	ND	mg/kg	0.10	0.015	EPA-8082	50	A10	1
PCB-1248	ND	mg/kg	0.10	0.021	EPA-8082	50	A10	1
PCB-1254	ND	mg/kg	0.10	0.016	EPA-8082	50	A10	1
PCB-1260	**0.044**	**mg/kg**	**0.10**	**0.018**	**EPA-8082**	50	**J,A10**	1
Total PCB's (Summation)	ND	mg/kg	0.10	0.050	EPA-8082	50	A10	1
Decachlorobiphenyl (Surrogate)	83.3	%	40 - 120 (LCL - UCL)		EPA-8082		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8082	10/21/21 16:00	10/22/21 10:38	HKS	GC-14	10.135	B122999	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Benzene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
Bromobenzene	ND	mg/kg	0.0050	0.00087	EPA-8260B			1
Bromochloromethane	ND	mg/kg	0.0050	0.00081	EPA-8260B			1
Bromodichloromethane	ND	mg/kg	0.0050	0.00078	EPA-8260B			1
Bromoform	ND	mg/kg	0.0050	0.00070	EPA-8260B			1
Bromomethane	ND	mg/kg	0.0050	0.0017	EPA-8260B			1
n-Butylbenzene	ND	mg/kg	0.0050	0.00076	EPA-8260B			1
sec-Butylbenzene	ND	mg/kg	0.0050	0.00071	EPA-8260B			1
tert-Butylbenzene	ND	mg/kg	0.0050	0.00085	EPA-8260B			1
Carbon tetrachloride	ND	mg/kg	0.0050	0.00078	EPA-8260B			1
Chlorobenzene	ND	mg/kg	0.0050	0.00077	EPA-8260B			1
Chloroethane	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
Chloroform	ND	mg/kg	0.0050	0.00090	EPA-8260B			1
Chloromethane	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
2-Chlorotoluene	ND	mg/kg	0.0050	0.00087	EPA-8260B			1
4-Chlorotoluene	ND	mg/kg	0.0050	0.00070	EPA-8260B			1
Dibromochloromethane	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,2-Dibromo-3-chloropropane	ND	mg/kg	0.0050	0.00096	EPA-8260B			1
1,2-Dibromoethane	ND	mg/kg	0.0050	0.00082	EPA-8260B			1
Dibromomethane	ND	mg/kg	0.0050	0.0014	EPA-8260B			1
1,2-Dichlorobenzene	ND	mg/kg	0.0050	0.00079	EPA-8260B			1
1,3-Dichlorobenzene	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
1,4-Dichlorobenzene	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
Dichlorodifluoromethane	ND	mg/kg	0.0050	0.00079	EPA-8260B			1
1,1-Dichloroethane	ND	mg/kg	0.0050	0.00064	EPA-8260B			1
1,2-Dichloroethane	ND	mg/kg	0.0050	0.00073	EPA-8260B			1
1,1-Dichloroethene	ND	mg/kg	0.0050	0.0011	EPA-8260B			1
cis-1,2-Dichloroethene	ND	mg/kg	0.0050	0.00054	EPA-8260B			1
trans-1,2-Dichloroethene	ND	mg/kg	0.0050	0.0037	EPA-8260B			1
1,2-Dichloropropane	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,3-Dichloropropane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
2,2-Dichloropropane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
1,1-Dichloropropene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
cis-1,3-Dichloropropene	ND	mg/kg	0.0050	0.00058	EPA-8260B			1
trans-1,3-Dichloropropene	ND	mg/kg	0.0050	0.00066	EPA-8260B			1
Ethylbenzene	ND	mg/kg	0.0050	0.00069	EPA-8260B			1
Hexachlorobutadiene	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
Isopropylbenzene	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
p-Isopropyltoluene	ND	mg/kg	0.0050	0.00059	EPA-8260B			1
Methylene chloride	ND	mg/kg	0.010	0.0011	EPA-8260B			1
Methyl t-butyl ether	ND	mg/kg	0.0050	0.00056	EPA-8260B			1
Naphthalene	ND	mg/kg	0.0050	0.00099	EPA-8260B			1
n-Propylbenzene	ND	mg/kg	0.0050	0.00071	EPA-8260B			1
Styrene	ND	mg/kg	0.0050	0.00062	EPA-8260B			1
1,1,1,2-Tetrachloroethane	ND	mg/kg	0.0050	0.00095	EPA-8260B			1
1,1,2,2-Tetrachloroethane	ND	mg/kg	0.0050	0.00084	EPA-8260B			1
Tetrachloroethene	ND	mg/kg	0.0050	0.00097	EPA-8260B			1
Toluene	ND	mg/kg	0.0050	0.00069	EPA-8260B			1
1,2,3-Trichlorobenzene	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
1,2,4-Trichlorobenzene	ND	mg/kg	0.0050	0.0014	EPA-8260B			1
1,1,1-Trichloroethane	ND	mg/kg	0.0050	0.00067	EPA-8260B			1
1,1,2-Trichloroethane	ND	mg/kg	0.0050	0.00094	EPA-8260B			1
Trichloroethene	ND	mg/kg	0.0050	0.00074	EPA-8260B	2040		1
Trichlorofluoromethane	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
1,2,3-Trichloropropane	ND	mg/kg	0.0050	0.0019	EPA-8260B			1
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	mg/kg	0.0050	0.0010	EPA-8260B			1
1,2,4-Trimethylbenzene	ND	mg/kg	0.0050	0.00080	EPA-8260B			1
1,3,5-Trimethylbenzene	ND	mg/kg	0.0050	0.00066	EPA-8260B			1
Vinyl chloride	ND	mg/kg	0.0050	0.00059	EPA-8260B			1
Total Xylenes	ND	mg/kg	0.010	0.0025	EPA-8260B			1
p- & m-Xylenes	ND	mg/kg	0.0050	0.0015	EPA-8260B			1
o-Xylene	ND	mg/kg	0.0050	0.00093	EPA-8260B			1
1,2-Dichloroethane-d4 (Surrogate)	104	%	70 - 121 (LCL - UCL)		EPA-8260B			1
Toluene-d8 (Surrogate)	97.4	%	81 - 117 (LCL - UCL)		EPA-8260B			1
4-Bromofluorobenzene (Surrogate)	92.0	%	74 - 121 (LCL - UCL)		EPA-8260B			1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	
1	EPA-8260B	10/20/21 15:55	10/20/21 19:06	RCC	MS-V17	1	B122675	EPA 5030 Soil MS

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Acenaphthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Acenaphthylene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Aldrin	ND	mg/kg	1.0	0.067	EPA-8270C	1.4	A10	1
Aniline	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
Anthracene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzidine	ND	mg/kg	30	0.093	EPA-8270C		A10	1
Benzo[a]anthracene	ND	mg/kg	1.0	0.077	EPA-8270C		A10	1
Benzo[b]fluoranthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzo[k]fluoranthene	ND	mg/kg	1.0	0.082	EPA-8270C		A10	1
Benzo[a]pyrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzo[g,h,i]perylene	ND	mg/kg	1.0	0.13	EPA-8270C		A10	1
Benzoic acid	ND	mg/kg	5.0	0.14	EPA-8270C		A10	1
Benzyl alcohol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Benzyl butyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
alpha-BHC	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
beta-BHC	ND	mg/kg	1.0	0.075	EPA-8270C		A10	1
delta-BHC	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
gamma-BHC (Lindane)	ND	mg/kg	1.0	0.067	EPA-8270C	4.0	A10	1
bis(2-Chloroethoxy)methane	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
bis(2-Chloroethyl) ether	ND	mg/kg	1.0	0.097	EPA-8270C		A10	1
bis(2-Chloroisopropyl)ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
bis(2-Ethylhexyl)phthalate	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
4-Bromophenyl phenyl ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chloroaniline	ND	mg/kg	1.0	0.15	EPA-8270C		A10	1
2-Chloronaphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chlorophenyl phenyl ether	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Chrysene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4,4'-DDD	ND	mg/kg	1.0	0.067	EPA-8270C	1.0	A10	1
4,4'-DDE	ND	mg/kg	1.0	0.068	EPA-8270C	1.0	A10	1
4,4'-DDT	ND	mg/kg	1.0	0.067	EPA-8270C	1.0	A10	1
Dibenzo[a,h]anthracene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Dibenzofuran	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
1,3-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,4-Dichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3,3-Dichlorobenzidine	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
Dieldrin	ND	mg/kg	1.0	0.077	EPA-8270C	8.0	A10	1
Diethyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Dimethyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Di-n-butyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dinitrotoluene	ND	mg/kg	1.0	0.085	EPA-8270C		A10	1
2,6-Dinitrotoluene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Di-n-octyl phthalate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2-Diphenylhydrazine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Endosulfan I	ND	mg/kg	2.0	0.088	EPA-8270C		A10	1
Endosulfan II	ND	mg/kg	2.0	0.088	EPA-8270C		A10	1
Endosulfan sulfate	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Endrin	ND	mg/kg	2.0	0.086	EPA-8270C	0.2	A10	1
Endrin aldehyde	ND	mg/kg	5.0	0.070	EPA-8270C		A10	1
Fluoranthene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Fluorene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Heptachlor	ND	mg/kg	1.0	0.067	EPA-8270C	4.7	A10	1
Heptachlor epoxide	ND	mg/kg	1.0	0.13	EPA-8270C		A10	1
Hexachlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Hexachlorobutadiene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Hexachlorocyclopentadiene	ND	mg/kg	1.0	0.15	EPA-8270C		A10	1
Hexachloroethane	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Indeno[1,2,3-cd]pyrene	ND	mg/kg	1.0	0.069	EPA-8270C		A10	1
Isophorone	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2-Methylnaphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Naphthalene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2-Naphthylamine	ND	mg/kg	30	0.36	EPA-8270C		A10	1
2-Nitroaniline	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3-Nitroaniline	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
4-Nitroaniline	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
Nitrobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
N-Nitrosodimethylamine	ND	mg/kg	1.0	0.40	EPA-8270C		A10	1
N-Nitrosodi-N-propylamine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
N-Nitrosodiphenylamine	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Phenanthrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
Pyrene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
1,2,4-Trichlorobenzene	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Chloro-3-methylphenol	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
2-Chlorophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dichlorophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4-Dimethylphenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4,6-Dinitro-2-methylphenol	ND	mg/kg	5.0	0.067	EPA-8270C		A10	1
2,4-Dinitrophenol	ND	mg/kg	5.0	0.067	EPA-8270C		A10	1
2-Methylphenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
3- & 4-Methylphenol	ND	mg/kg	2.0	0.14	EPA-8270C		A10	1
2-Nitrophenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
4-Nitrophenol	ND	mg/kg	2.0	0.18	EPA-8270C		A10	1
Pentachlorophenol	ND	mg/kg	2.0	0.17	EPA-8270C	17	A10	1
Phenol	ND	mg/kg	1.0	0.067	EPA-8270C		A10	1
2,4,5-Trichlorophenol	ND	mg/kg	2.0	0.11	EPA-8270C		A10	1
2,4,6-Trichlorophenol	ND	mg/kg	2.0	0.067	EPA-8270C		A10	1
2-Fluorophenol (Surrogate)	62.7	%	20 - 130 (LCL - UCL)		EPA-8270C		A10	1
Phenol-d5 (Surrogate)	61.8	%	30 - 130 (LCL - UCL)		EPA-8270C		A10	1
Nitrobenzene-d5 (Surrogate)	65.6	%	30 - 130 (LCL - UCL)		EPA-8270C		A10	1
2-Fluorobiphenyl (Surrogate)	58.4	%	30 - 140 (LCL - UCL)		EPA-8270C		A10	1
2,4,6-Tribromophenol (Surrogate)	42.3	%	20 - 150 (LCL - UCL)		EPA-8270C		A10	1
p-Terphenyl-d14 (Surrogate)	54.6	%	30 - 150 (LCL - UCL)		EPA-8270C		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8270C	10/22/21 08:00	10/22/21 22:32	CMM	MS-B2	9.500	B123094	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Petroleum Hydrocarbons

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
TPH - Gasoline (C4-C12)	ND	mg/kg	20	5.0	EPA-8015B	ND	A10	1
TPH - Diesel (C13 - C22)	**11**	**mg/kg**	**10**	**3.8**	**EPA-8015B**	ND	**A10,A52**	1
TPH - Motor Oil (C23 - C36)	**160**	**mg/kg**	**20**	**9.0**	**EPA-8015B**	ND	**A10,A57**	1
Tetracosane (Surrogate)	60.1	%	20 - 145 (LCL - UCL)		EPA-8015B		A10	1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-8015B	10/21/21 15:00	10/22/21 12:46	BUP	GC-19	5.051	B122699	EPA 3550B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Concentrations (TTLC)

BCL Sample ID: 2132975-05 | **Client Sample Name:** SB-3-1, 10/19/2021 10:04:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	TTLC Limits	Lab Quals	Run #
Antimony	**0.57**	**mg/kg**	**5.0**	**0.33**	**EPA-6010B**	500	**J**	1
Arsenic	**4.2**	**mg/kg**	**1.0**	**0.40**	**EPA-6010B**	500		1
Barium	**180**	**mg/kg**	**0.50**	**0.18**	**EPA-6010B**	10000		1
Beryllium	**0.26**	**mg/kg**	**0.50**	**0.047**	**EPA-6010B**	75	**J**	1
Cadmium	**0.50**	**mg/kg**	**0.50**	**0.052**	**EPA-6010B**	100		1
Chromium	**79**	**mg/kg**	**0.50**	**0.050**	**EPA-6010B**	2500	**S11**	1
Cobalt	**16**	**mg/kg**	**2.5**	**0.098**	**EPA-6010B**	8000		1
Copper	**41**	**mg/kg**	**1.0**	**0.050**	**EPA-6010B**	2500		1
Lead	**17**	**mg/kg**	**2.5**	**0.41**	**EPA-6010B**	1000		1
Mercury	**0.079**	**mg/kg**	**0.16**	**0.016**	**EPA-7471A**	20	**J**	2
Molybdenum	**0.54**	**mg/kg**	**2.5**	**0.050**	**EPA-6010B**	3500	**J**	1
Nickel	**60**	**mg/kg**	**0.50**	**0.15**	**EPA-6010B**	2000	**S11**	1
Selenium	ND	mg/kg	1.0	0.98	EPA-6010B	100		1
Silver	**0.12**	**mg/kg**	**0.50**	**0.067**	**EPA-6010B**	500	**J**	1
Thallium	ND	mg/kg	50	6.4	EPA-6010B	700	A10	3
Vanadium	**70**	**mg/kg**	**0.50**	**0.11**	**EPA-6010B**	2400		1
Zinc	**65**	**mg/kg**	**2.5**	**0.087**	**EPA-6010B**	5000		1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-6010B	10/21/21 06:30	10/21/21 17:35	JCC	PE-OP3	0.952	B122837	EPA 3050B
2	EPA-7471A	10/25/21 08:25	10/25/21 11:42	TMT	CETAC3	0.962	B123042	EPA 7471A
3	EPA-6010B	10/21/21 06:30	10/22/21 18:24	JCC	PE-OP3	9.524	B122837	EPA 3050B

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Chemical Analysis

BCL Sample ID: 2132975-06 | **Client Sample Name:** SB-3-2.5, 10/19/2021 10:05:00AM, Lawrence Bush

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
pH	**7.69**	**pH Units**	**0.05**	**0.05**	**EPA-9045D**	ND	**pH1:1**	1
pH Measurement Temperature	**25.4**	**C**	**0.1**	**0.1**	**EPA-9045D**	ND		1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-9045D	10/28/21 11:30	10/28/21 11:30	RT1	MANUAL	1	B123604	EPA 9045

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Organochlorine Pesticides (EPA Method 8081A)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B122973						
Aldrin	B122973-BLK1	ND	mg/kg	0.00050	0.000018	
alpha-BHC	B122973-BLK1	ND	mg/kg	0.00050	0.000038	
beta-BHC	B122973-BLK1	ND	mg/kg	0.00050	0.000048	
delta-BHC	B122973-BLK1	ND	mg/kg	0.00050	0.000037	
gamma-BHC (Lindane)	B122973-BLK1	ND	mg/kg	0.00050	0.000018	
Chlordane (Technical)	B122973-BLK1	ND	mg/kg	0.050	0.0010	
4,4'-DDD	B122973-BLK1	ND	mg/kg	0.00050	0.000064	
4,4'-DDE	B122973-BLK1	ND	mg/kg	0.00050	0.000095	
4,4'-DDT	B122973-BLK1	ND	mg/kg	0.00050	0.000040	
Dieldrin	B122973-BLK1	ND	mg/kg	0.00050	0.000036	
Endosulfan I	B122973-BLK1	ND	mg/kg	0.00050	0.000020	
Endosulfan II	B122973-BLK1	ND	mg/kg	0.00050	0.000034	
Endosulfan sulfate	B122973-BLK1	ND	mg/kg	0.00050	0.000026	
Endrin	B122973-BLK1	ND	mg/kg	0.00050	0.000065	
Endrin aldehyde	B122973-BLK1	ND	mg/kg	0.00050	0.000018	
Heptachlor	B122973-BLK1	ND	mg/kg	0.00050	0.000086	
Heptachlor epoxide	B122973-BLK1	ND	mg/kg	0.00050	0.000017	
Methoxychlor	B122973-BLK1	ND	mg/kg	0.00050	0.000094	
Toxaphene	B122973-BLK1	ND	mg/kg	0.050	0.0014	
TCMX (Surrogate)	**B122973-BLK1**	**81.7**	%	**20 - 130 (LCL - UCL)**		
Decachlorobiphenyl (Surrogate)	**B122973-BLK1**	**77.6**	%	**40 - 130 (LCL - UCL)**		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Organochlorine Pesticides (EPA Method 8081A)

Quality Control Report - Laboratory Control Sample

Constituent	QC Sample ID	Type	Result	Spike Level	Units	Percent Recovery	RPD	Control Limits Percent Recovery	Control Limits RPD	Lab Quals
QC Batch ID: B122973										
Aldrin	B122973-BS1	LCS	0.0048792	0.0049505	mg/kg	98.6		70 - 130		
gamma-BHC (Lindane)	B122973-BS1	LCS	0.0047317	0.0049505	mg/kg	95.6		60 - 140		
4,4'-DDT	B122973-BS1	LCS	0.0048686	0.0049505	mg/kg	98.3		60 - 140		
Dieldrin	B122973-BS1	LCS	0.0048677	0.0049505	mg/kg	98.3		70 - 130		
Endrin	B122973-BS1	LCS	0.0064188	0.0049505	mg/kg	130		60 - 140		
Heptachlor	B122973-BS1	LCS	0.0049904	0.0049505	mg/kg	101		60 - 140		
TCMX (Surrogate)	B122973-BS1	LCS	0.0083660	0.0099010	mg/kg	84.5		20 - 130		
Decachlorobiphenyl (Surrogate)	B122973-BS1	LCS	0.015536	0.019802	mg/kg	78.5		40 - 130		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Organochlorine Pesticides (EPA Method 8081A)

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B122973	Used client sample: N										
Aldrin	MS	2132530-22	ND	0.0050689	0.0049669	mg/kg		102		50 - 140	
	MSD	2132530-22	ND	0.0050530	0.0050336	mg/kg	0.3	100	30	50 - 140	
gamma-BHC (Lindane)	MS	2132530-22	ND	0.0049805	0.0049669	mg/kg		100		50 - 140	
	MSD	2132530-22	ND	0.0048799	0.0050336	mg/kg	2.0	96.9	30	50 - 140	
4,4'-DDT	MS	2132530-22	ND	0.0052387	0.0049669	mg/kg		105		50 - 140	
	MSD	2132530-22	ND	0.0052191	0.0050336	mg/kg	0.4	104	30	50 - 140	
Dieldrin	MS	2132530-22	ND	0.0051066	0.0049669	mg/kg		103		40 - 140	
	MSD	2132530-22	ND	0.0050718	0.0050336	mg/kg	0.7	101	30	40 - 140	
Endrin	MS	2132530-22	ND	0.0068993	0.0049669	mg/kg		139		50 - 150	
	MSD	2132530-22	ND	0.0068685	0.0050336	mg/kg	0.4	136	30	50 - 150	
Heptachlor	MS	2132530-22	ND	0.0051546	0.0049669	mg/kg		104		60 - 140	
	MSD	2132530-22	ND	0.0051554	0.0050336	mg/kg	0.0	102	30	60 - 140	
TCMX (Surrogate)	MS	2132530-22	ND	0.0086513	0.0099338	mg/kg		87.1		20 - 130	
	MSD	2132530-22	ND	0.0086067	0.010067	mg/kg	0.5	85.5		20 - 130	
Decachlorobiphenyl (Surrogate)	MS	2132530-22	ND	0.017138	0.019868	mg/kg		86.3		40 - 130	
	MSD	2132530-22	ND	0.016816	0.020134	mg/kg	1.9	83.5		40 - 130	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

PCB Analysis (EPA Method 8082)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B122999						
PCB-1016	B122999-BLK1	ND	mg/kg	0.010	0.0023	
PCB-1221	B122999-BLK1	ND	mg/kg	0.010	0.0033	
PCB-1232	B122999-BLK1	ND	mg/kg	0.010	0.0026	
PCB-1242	B122999-BLK1	ND	mg/kg	0.010	0.0015	
PCB-1248	B122999-BLK1	ND	mg/kg	0.010	0.0021	
PCB-1254	B122999-BLK1	ND	mg/kg	0.010	0.0016	
PCB-1260	B122999-BLK1	ND	mg/kg	0.010	0.0018	
Total PCB's (Summation)	B122999-BLK1	ND	mg/kg	0.010	0.0050	
Decachlorobiphenyl (Surrogate)	**B122999-BLK1**	**70.0**	%	**40 - 120 (LCL - UCL)**		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

PCB Analysis (EPA Method 8082)

Quality Control Report - Laboratory Control Sample

Constituent	QC Sample ID	Type	Result	Spike Level	Units	Percent Recovery	RPD	Control Limits Percent Recovery	Control Limits RPD	Lab Quals
QC Batch ID: B122999										
PCB-1016	B122999-BS1	LCS	0.070946	0.084459	mg/kg	84.0		60 - 120		
	B122999-BSD1	LCSD	0.088411	0.082781	mg/kg	107	21.9	60 - 120	30	
PCB-1260	B122999-BS1	LCS	0.067568	0.084459	mg/kg	80.0		60 - 120		
	B122999-BSD1	LCSD	0.080795	0.082781	mg/kg	97.6	17.8	60 - 120	30	
Decachlorobiphenyl (Surrogate)	B122999-BS1	LCS	0.014527	0.020270	mg/kg	71.7		40 - 120		
	B122999-BSD1	LCSD	0.017219	0.019868	mg/kg	86.7	17.0	40 - 120		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

PCB Analysis (EPA Method 8082)

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B122999	Used client sample: N										
PCB-1016	MS	**2132753-02**	**ND**	**0.029245**	**0.23585**	**mg/kg**		**12.4**		**60 - 120**	**Q03**
	MSD	**2132753-02**	**ND**	**0.029703**	**0.24752**	**mg/kg**	**1.6**	**12.0**	**30**	**60 - 120**	**J,Q03**
PCB-1260	MS	**2132753-02**	**ND**	**0.025472**	**0.23585**	**mg/kg**		**10.8**		**60 - 120**	**J,Q03**
	MSD	**2132753-02**	**ND**	**0.022772**	**0.24752**	**mg/kg**	**11.2**	**9.2**	**30**	**60 - 120**	**J,Q03**
Decachlorobiphenyl (Surrogate)	MS	**2132753-02**	**ND**	**0.0056604**	**0.056604**	**mg/kg**		**10.0**		**40 - 120**	**S09**
	MSD	**2132753-02**	**ND**	**0.0049505**	**0.059406**	**mg/kg**	**13.4**	**8.3**		**40 - 120**	**S09**

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B122675						
Benzene	B122675-BLK1	ND	mg/kg	0.0050	0.00067	
Bromobenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00087	
Bromochloromethane	B122675-BLK1	ND	mg/kg	0.0050	0.00081	
Bromodichloromethane	B122675-BLK1	ND	mg/kg	0.0050	0.00078	
Bromoform	B122675-BLK1	ND	mg/kg	0.0050	0.00070	
Bromomethane	B122675-BLK1	ND	mg/kg	0.0050	0.0017	
n-Butylbenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00076	
sec-Butylbenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00071	
tert-Butylbenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00085	
Carbon tetrachloride	B122675-BLK1	ND	mg/kg	0.0050	0.00078	
Chlorobenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00077	
Chloroethane	B122675-BLK1	ND	mg/kg	0.0050	0.0011	
Chloroform	B122675-BLK1	ND	mg/kg	0.0050	0.00090	
Chloromethane	B122675-BLK1	ND	mg/kg	0.0050	0.0011	
2-Chlorotoluene	B122675-BLK1	ND	mg/kg	0.0050	0.00087	
4-Chlorotoluene	B122675-BLK1	ND	mg/kg	0.0050	0.00070	
Dibromochloromethane	B122675-BLK1	ND	mg/kg	0.0050	0.00080	
1,2-Dibromo-3-chloropropane	B122675-BLK1	ND	mg/kg	0.0050	0.00096	
1,2-Dibromoethane	B122675-BLK1	ND	mg/kg	0.0050	0.00082	
Dibromomethane	B122675-BLK1	ND	mg/kg	0.0050	0.0014	
1,2-Dichlorobenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00079	
1,3-Dichlorobenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00073	
1,4-Dichlorobenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00073	
Dichlorodifluoromethane	B122675-BLK1	ND	mg/kg	0.0050	0.00079	
1,1-Dichloroethane	B122675-BLK1	ND	mg/kg	0.0050	0.00064	
1,2-Dichloroethane	B122675-BLK1	ND	mg/kg	0.0050	0.00073	
1,1-Dichloroethene	B122675-BLK1	ND	mg/kg	0.0050	0.0011	
cis-1,2-Dichloroethene	B122675-BLK1	ND	mg/kg	0.0050	0.00054	
trans-1,2-Dichloroethene	B122675-BLK1	ND	mg/kg	0.0050	0.0037	
1,2-Dichloropropane	B122675-BLK1	ND	mg/kg	0.0050	0.00080	
1,3-Dichloropropane	B122675-BLK1	ND	mg/kg	0.0050	0.00067	
2,2-Dichloropropane	B122675-BLK1	ND	mg/kg	0.0050	0.00067	
1,1-Dichloropropene	B122675-BLK1	ND	mg/kg	0.0050	0.00067	
cis-1,3-Dichloropropene	B122675-BLK1	ND	mg/kg	0.0050	0.00058	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B122675						
trans-1,3-Dichloropropene	B122675-BLK1	ND	mg/kg	0.0050	0.00066	
Ethylbenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00069	
Hexachlorobutadiene	B122675-BLK1	ND	mg/kg	0.0050	0.00067	
Isopropylbenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00080	
p-Isopropyltoluene	B122675-BLK1	ND	mg/kg	0.0050	0.00059	
Methylene chloride	B122675-BLK1	ND	mg/kg	0.010	0.0011	
Methyl t-butyl ether	B122675-BLK1	ND	mg/kg	0.0050	0.00056	
Naphthalene	B122675-BLK1	ND	mg/kg	0.0050	0.00099	
n-Propylbenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00071	
Styrene	B122675-BLK1	ND	mg/kg	0.0050	0.00062	
1,1,1,2-Tetrachloroethane	B122675-BLK1	ND	mg/kg	0.0050	0.00095	
1,1,2,2-Tetrachloroethane	B122675-BLK1	ND	mg/kg	0.0050	0.00084	
Tetrachloroethene	B122675-BLK1	ND	mg/kg	0.0050	0.00097	
Toluene	B122675-BLK1	ND	mg/kg	0.0050	0.00069	
1,2,3-Trichlorobenzene	B122675-BLK1	ND	mg/kg	0.0050	0.0015	
1,2,4-Trichlorobenzene	B122675-BLK1	ND	mg/kg	0.0050	0.0014	
1,1,1-Trichloroethane	B122675-BLK1	ND	mg/kg	0.0050	0.00067	
1,1,2-Trichloroethane	B122675-BLK1	ND	mg/kg	0.0050	0.00094	
Trichloroethene	B122675-BLK1	ND	mg/kg	0.0050	0.00074	
Trichlorofluoromethane	B122675-BLK1	ND	mg/kg	0.0050	0.0015	
1,2,3-Trichloropropane	B122675-BLK1	ND	mg/kg	0.0050	0.0019	
1,1,2-Trichloro-1,2,2-trifluoroethane	B122675-BLK1	ND	mg/kg	0.0050	0.0010	
1,2,4-Trimethylbenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00080	
1,3,5-Trimethylbenzene	B122675-BLK1	ND	mg/kg	0.0050	0.00066	
Vinyl chloride	B122675-BLK1	ND	mg/kg	0.0050	0.00059	
Total Xylenes	B122675-BLK1	ND	mg/kg	0.010	0.0025	
p- & m-Xylenes	B122675-BLK1	ND	mg/kg	0.0050	0.0015	
o-Xylene	B122675-BLK1	ND	mg/kg	0.0050	0.00093	
1,2-Dichloroethane-d4 (Surrogate)	**B122675-BLK1**	**91.8**	%	**70 - 121 (LCL - UCL)**		
Toluene-d8 (Surrogate)	**B122675-BLK1**	**99.4**	%	**81 - 117 (LCL - UCL)**		
4-Bromofluorobenzene (Surrogate)	**B122675-BLK1**	**98.7**	%	**74 - 121 (LCL - UCL)**		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

Quality Control Report - Laboratory Control Sample

Constituent	QC Sample ID	Type	Result	Spike Level	Units	Percent Recovery	RPD	Control Limits Percent Recovery	Control Limits RPD	Lab Quals
QC Batch ID: B122675										
Benzene	B122675-BS1	LCS	0.10681	0.12500	mg/kg	85.4		70 - 130		
Bromodichloromethane	B122675-BS1	LCS	0.12331	0.12500	mg/kg	98.6		70 - 130		
Chlorobenzene	B122675-BS1	LCS	0.11748	0.12500	mg/kg	94.0		70 - 130		
Chloroethane	B122675-BS1	LCS	0.12406	0.12500	mg/kg	99.2		70 - 130		
1,4-Dichlorobenzene	B122675-BS1	LCS	0.11447	0.12500	mg/kg	91.6		70 - 130		
1,1-Dichloroethane	B122675-BS1	LCS	0.10793	0.12500	mg/kg	86.3		70 - 130		
1,1-Dichloroethene	B122675-BS1	LCS	0.11464	0.12500	mg/kg	91.7		70 - 130		
Toluene	B122675-BS1	LCS	0.12186	0.12500	mg/kg	97.5		70 - 130		
Trichloroethene	B122675-BS1	LCS	0.11594	0.12500	mg/kg	92.8		70 - 130		
1,2-Dichloroethane-d4 (Surrogate)	B122675-BS1	LCS	0.044870	0.050000	mg/kg	89.7		70 - 121		
Toluene-d8 (Surrogate)	B122675-BS1	LCS	0.050730	0.050000	mg/kg	101		81 - 117		
4-Bromofluorobenzene (Surrogate)	B122675-BS1	LCS	0.050770	0.050000	mg/kg	102		74 - 121		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Volatile Organic Analysis (EPA Method 8260B)

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B122675	Used client sample: N										
Benzene	MS	2132530-22	ND	0.10697	0.12500	mg/kg		85.6		70 - 130	
	MSD	2132530-22	ND	0.11134	0.12500	mg/kg	4.0	89.1	20	70 - 130	
Bromodichloromethane	MS	2132530-22	ND	0.12589	0.12500	mg/kg		101		70 - 130	
	MSD	2132530-22	ND	0.12963	0.12500	mg/kg	2.9	104	20	70 - 130	
Chlorobenzene	MS	2132530-22	ND	0.11998	0.12500	mg/kg		96.0		70 - 130	
	MSD	2132530-22	ND	0.12076	0.12500	mg/kg	0.6	96.6	20	70 - 130	
Chloroethane	MS	2132530-22	ND	0.12534	0.12500	mg/kg		100		70 - 130	
	MSD	2132530-22	ND	0.12952	0.12500	mg/kg	3.3	104	20	70 - 130	
1,4-Dichlorobenzene	MS	2132530-22	ND	0.11817	0.12500	mg/kg		94.5		70 - 130	
	MSD	2132530-22	ND	0.11700	0.12500	mg/kg	1.0	93.6	20	70 - 130	
1,1-Dichloroethane	MS	2132530-22	ND	0.10825	0.12500	mg/kg		86.6		70 - 130	
	MSD	2132530-22	ND	0.11341	0.12500	mg/kg	4.7	90.7	20	70 - 130	
1,1-Dichloroethene	MS	2132530-22	ND	0.11510	0.12500	mg/kg		92.1		70 - 130	
	MSD	2132530-22	ND	0.12005	0.12500	mg/kg	4.2	96.0	20	70 - 130	
Toluene	MS	2132530-22	ND	0.12256	0.12500	mg/kg		98.0		70 - 130	
	MSD	2132530-22	ND	0.12646	0.12500	mg/kg	3.1	101	20	70 - 130	
Trichloroethene	MS	2132530-22	ND	0.11666	0.12500	mg/kg		93.3		70 - 130	
	MSD	2132530-22	ND	0.11921	0.12500	mg/kg	2.2	95.4	20	70 - 130	
1,2-Dichloroethane-d4 (Surrogate)	MS	2132530-22	ND	0.044460	0.050000	mg/kg		88.9		70 - 121	
	MSD	2132530-22	ND	0.045340	0.050000	mg/kg	2.0	90.7		70 - 121	
Toluene-d8 (Surrogate)	MS	2132530-22	ND	0.050670	0.050000	mg/kg		101		81 - 117	
	MSD	2132530-22	ND	0.050570	0.050000	mg/kg	0.2	101		81 - 117	
4-Bromofluorobenzene (Surrogate)	MS	2132530-22	ND	0.051250	0.050000	mg/kg		102		74 - 121	
	MSD	2132530-22	ND	0.050070	0.050000	mg/kg	2.3	100		74 - 121	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B123094						
Acenaphthene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Acenaphthylene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Aldrin	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Aniline	B123094-BLK1	ND	mg/kg	0.20	0.011	
Anthracene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Benzidine	B123094-BLK1	ND	mg/kg	3.0	0.0093	
Benzo[a]anthracene	B123094-BLK1	ND	mg/kg	0.10	0.0077	
Benzo[b]fluoranthene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Benzo[k]fluoranthene	B123094-BLK1	ND	mg/kg	0.10	0.0082	
Benzo[a]pyrene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Benzo[g,h,i]perylene	B123094-BLK1	ND	mg/kg	0.10	0.013	
Benzoic acid	B123094-BLK1	ND	mg/kg	0.50	0.014	
Benzyl alcohol	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Benzyl butyl phthalate	B123094-BLK1	ND	mg/kg	0.10	0.0067	
alpha-BHC	B123094-BLK1	ND	mg/kg	0.10	0.0067	
beta-BHC	B123094-BLK1	ND	mg/kg	0.10	0.0075	
delta-BHC	B123094-BLK1	ND	mg/kg	0.10	0.0067	
gamma-BHC (Lindane)	B123094-BLK1	ND	mg/kg	0.10	0.0067	
bis(2-Chloroethoxy)methane	B123094-BLK1	ND	mg/kg	0.10	0.0067	
bis(2-Chloroethyl) ether	B123094-BLK1	ND	mg/kg	0.10	0.0097	
bis(2-Chloroisopropyl)ether	B123094-BLK1	ND	mg/kg	0.10	0.0067	
bis(2-Ethylhexyl)phthalate	B123094-BLK1	ND	mg/kg	0.20	0.0067	
4-Bromophenyl phenyl ether	B123094-BLK1	ND	mg/kg	0.10	0.0067	
4-Chloroaniline	B123094-BLK1	ND	mg/kg	0.10	0.015	
2-Chloronaphthalene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
4-Chlorophenyl phenyl ether	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Chrysene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
4,4'-DDD	B123094-BLK1	ND	mg/kg	0.10	0.0067	
4,4'-DDE	B123094-BLK1	ND	mg/kg	0.10	0.0068	
4,4'-DDT	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Dibenzo[a,h]anthracene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Dibenzofuran	B123094-BLK1	ND	mg/kg	0.10	0.0067	
1,2-Dichlorobenzene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
1,3-Dichlorobenzene	B123094-BLK1	ND	mg/kg	0.10	0.0067	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B123094						
1,4-Dichlorobenzene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
3,3-Dichlorobenzidine	B123094-BLK1	ND	mg/kg	0.20	0.0067	
Dieldrin	B123094-BLK1	ND	mg/kg	0.10	0.0077	
Diethyl phthalate	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Dimethyl phthalate	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Di-n-butyl phthalate	B123094-BLK1	ND	mg/kg	0.10	0.0067	
2,4-Dinitrotoluene	B123094-BLK1	ND	mg/kg	0.10	0.0085	
2,6-Dinitrotoluene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Di-n-octyl phthalate	B123094-BLK1	ND	mg/kg	0.10	0.0067	
1,2-Diphenylhydrazine	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Endosulfan I	B123094-BLK1	ND	mg/kg	0.20	0.0088	
Endosulfan II	B123094-BLK1	ND	mg/kg	0.20	0.0088	
Endosulfan sulfate	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Endrin	B123094-BLK1	ND	mg/kg	0.20	0.0086	
Endrin aldehyde	B123094-BLK1	ND	mg/kg	0.50	0.0070	
Fluoranthene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Fluorene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Heptachlor	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Heptachlor epoxide	B123094-BLK1	ND	mg/kg	0.10	0.013	
Hexachlorobenzene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Hexachlorobutadiene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Hexachlorocyclopentadiene	B123094-BLK1	ND	mg/kg	0.10	0.015	
Hexachloroethane	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Indeno[1,2,3-cd]pyrene	B123094-BLK1	ND	mg/kg	0.10	0.0069	
Isophorone	B123094-BLK1	ND	mg/kg	0.10	0.0067	
2-Methylnaphthalene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Naphthalene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
2-Naphthylamine	B123094-BLK1	ND	mg/kg	3.0	0.036	
2-Nitroaniline	B123094-BLK1	ND	mg/kg	0.10	0.0067	
3-Nitroaniline	B123094-BLK1	ND	mg/kg	0.20	0.0067	
4-Nitroaniline	B123094-BLK1	ND	mg/kg	0.20	0.011	
Nitrobenzene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
N-Nitrosodimethylamine	B123094-BLK1	ND	mg/kg	0.10	0.040	
N-Nitrosodi-N-propylamine	B123094-BLK1	ND	mg/kg	0.10	0.0067	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B123094						
N-Nitrosodiphenylamine	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Phenanthrene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
Pyrene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
1,2,4-Trichlorobenzene	B123094-BLK1	ND	mg/kg	0.10	0.0067	
4-Chloro-3-methylphenol	B123094-BLK1	ND	mg/kg	0.20	0.0067	
2-Chlorophenol	B123094-BLK1	ND	mg/kg	0.10	0.0067	
2,4-Dichlorophenol	B123094-BLK1	ND	mg/kg	0.10	0.0067	
2,4-Dimethylphenol	B123094-BLK1	ND	mg/kg	0.10	0.0067	
4,6-Dinitro-2-methylphenol	B123094-BLK1	ND	mg/kg	0.50	0.0067	
2,4-Dinitrophenol	B123094-BLK1	ND	mg/kg	0.50	0.0067	
2-Methylphenol	B123094-BLK1	ND	mg/kg	0.10	0.0067	
3- & 4-Methylphenol	B123094-BLK1	ND	mg/kg	0.20	0.014	
2-Nitrophenol	B123094-BLK1	ND	mg/kg	0.10	0.0067	
4-Nitrophenol	B123094-BLK1	ND	mg/kg	0.20	0.018	
Pentachlorophenol	B123094-BLK1	ND	mg/kg	0.20	0.017	
Phenol	B123094-BLK1	ND	mg/kg	0.10	0.0067	
2,4,5-Trichlorophenol	B123094-BLK1	ND	mg/kg	0.20	0.011	
2,4,6-Trichlorophenol	B123094-BLK1	ND	mg/kg	0.20	0.0067	
2-Fluorophenol (Surrogate)	**B123094-BLK1**	**80.1**	%	**20 - 130 (LCL - UCL)**		
Phenol-d5 (Surrogate)	**B123094-BLK1**	**80.0**	%	**30 - 130 (LCL - UCL)**		
Nitrobenzene-d5 (Surrogate)	**B123094-BLK1**	**78.8**	%	**30 - 130 (LCL - UCL)**		
2-Fluorobiphenyl (Surrogate)	**B123094-BLK1**	**78.3**	%	**30 - 140 (LCL - UCL)**		
2,4,6-Tribromophenol (Surrogate)	**B123094-BLK1**	**73.0**	%	**20 - 150 (LCL - UCL)**		
p-Terphenyl-d14 (Surrogate)	**B123094-BLK1**	**64.5**	%	**30 - 150 (LCL - UCL)**		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

Quality Control Report - Laboratory Control Sample

Constituent	QC Sample ID	Type	Result	Spike Level	Units	Percent Recovery	RPD	Control Limits Percent Recovery	Control Limits RPD	Lab Quals
QC Batch ID: B123094										
Acenaphthene	B123094-BS1	LCS	1.1045	1.6667	mg/kg	66.3		50 - 130		
1,4-Dichlorobenzene	B123094-BS1	LCS	1.4190	1.6667	mg/kg	85.1		50 - 130		
2,4-Dinitrotoluene	B123094-BS1	LCS	1.5886	1.6667	mg/kg	95.3		50 - 130		
Hexachlorobenzene	B123094-BS1	LCS	1.4022	1.6667	mg/kg	84.1		40 - 130		
Hexachlorobutadiene	B123094-BS1	LCS	1.2916	1.6667	mg/kg	77.5		50 - 130		
Hexachloroethane	B123094-BS1	LCS	1.4174	1.6667	mg/kg	85.0		50 - 130		
Nitrobenzene	B123094-BS1	LCS	1.4398	1.6667	mg/kg	86.4		50 - 130		
N-Nitrosodi-N-propylamine	B123094-BS1	LCS	1.1388	1.6667	mg/kg	68.3		40 - 120		
Pyrene	B123094-BS1	LCS	1.3223	1.6667	mg/kg	79.3		40 - 150		
1,2,4-Trichlorobenzene	B123094-BS1	LCS	1.4771	1.6667	mg/kg	88.6		50 - 120		
4-Chloro-3-methylphenol	B123094-BS1	LCS	1.1916	1.6667	mg/kg	71.5		50 - 130		
2-Chlorophenol	B123094-BS1	LCS	1.1807	1.6667	mg/kg	70.8		50 - 130		
2-Methylphenol	B123094-BS1	LCS	1.1629	1.6667	mg/kg	69.8		50 - 130		
3- & 4-Methylphenol	B123094-BS1	LCS	2.3536	3.3333	mg/kg	70.6		50 - 130		
4-Nitrophenol	B123094-BS1	LCS	0.98967	1.6667	mg/kg	59.4		30 - 130		
Pentachlorophenol	B123094-BS1	LCS	1.0299	1.6667	mg/kg	61.8		20 - 130		
Phenol	B123094-BS1	LCS	1.1332	1.6667	mg/kg	68.0		40 - 120		
2,4,6-Trichlorophenol	B123094-BS1	LCS	1.1735	1.6667	mg/kg	70.4		50 - 130		
2-Fluorophenol (Surrogate)	B123094-BS1	LCS	0.97878	1.3333	mg/kg	73.4		20 - 130		
Phenol-d5 (Surrogate)	B123094-BS1	LCS	0.95073	1.3333	mg/kg	71.3		30 - 130		
Nitrobenzene-d5 (Surrogate)	B123094-BS1	LCS	0.97647	1.3333	mg/kg	73.2		30 - 130		
2-Fluorobiphenyl (Surrogate)	B123094-BS1	LCS	0.96393	1.3333	mg/kg	72.3		30 - 140		
2,4,6-Tribromophenol (Surrogate)	B123094-BS1	LCS	0.92037	1.3333	mg/kg	69.0		20 - 150		
p-Terphenyl-d14 (Surrogate)	B123094-BS1	LCS	0.41778	0.66667	mg/kg	62.7		30 - 150		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B123094	Used client sample: N										
Acenaphthene	MS	2132530-31	ND	1.1729	1.6722	mg/kg		70.1		30 - 140	
	MSD	2132530-31	ND	1.0744	1.6502	mg/kg	8.8	65.1	30	30 - 140	
1,4-Dichlorobenzene	MS	2132530-31	ND	1.5629	1.6722	mg/kg		93.5		50 - 130	
	MSD	2132530-31	ND	1.3810	1.6502	mg/kg	12.4	83.7	30	50 - 130	
2,4-Dinitrotoluene	MS	2132530-31	ND	1.6505	1.6722	mg/kg		98.7		50 - 130	
	MSD	2132530-31	ND	1.5466	1.6502	mg/kg	6.5	93.7	30	50 - 130	
Hexachlorobenzene	MS	2132530-31	ND	1.4609	1.6722	mg/kg		87.4		50 - 130	
	MSD	2132530-31	ND	1.3001	1.6502	mg/kg	11.6	78.8	30	50 - 130	
Hexachlorobutadiene	MS	2132530-31	ND	1.4184	1.6722	mg/kg		84.8		50 - 130	
	MSD	2132530-31	ND	1.2380	1.6502	mg/kg	13.6	75.0	30	50 - 130	
Hexachloroethane	MS	2132530-31	ND	1.5361	1.6722	mg/kg		91.9		50 - 130	
	MSD	2132530-31	ND	1.4054	1.6502	mg/kg	8.9	85.2	30	50 - 130	
Nitrobenzene	MS	2132530-31	ND	1.5676	1.6722	mg/kg		93.7		30 - 120	
	MSD	2132530-31	ND	1.4156	1.6502	mg/kg	10.2	85.8	30	30 - 120	
N-Nitrosodi-N-propylamine	MS	2132530-31	ND	1.2127	1.6722	mg/kg		72.5		20 - 130	
	MSD	2132530-31	ND	1.2203	1.6502	mg/kg	0.6	74.0	30	20 - 130	
Pyrene	MS	2132530-31	ND	1.3475	1.6722	mg/kg		80.6		40 - 140	
	MSD	2132530-31	ND	1.3138	1.6502	mg/kg	2.5	79.6	30	40 - 140	
1,2,4-Trichlorobenzene	MS	2132530-31	ND	1.6241	1.6722	mg/kg		97.1		50 - 130	
	MSD	2132530-31	ND	1.4287	1.6502	mg/kg	12.8	86.6	30	50 - 130	
4-Chloro-3-methylphenol	MS	2132530-31	ND	1.2575	1.6722	mg/kg		75.2		50 - 130	
	MSD	2132530-31	ND	1.2050	1.6502	mg/kg	4.3	73.0	30	50 - 130	
2-Chlorophenol	MS	2132530-31	ND	1.2716	1.6722	mg/kg		76.0		50 - 130	
	MSD	2132530-31	ND	1.2130	1.6502	mg/kg	4.7	73.5	30	50 - 130	
2-Methylphenol	MS	2132530-31	ND	1.2552	1.6722	mg/kg		75.1		50 - 130	
	MSD	2132530-31	ND	1.2402	1.6502	mg/kg	1.2	75.2	30	50 - 130	
3- & 4-Methylphenol	MS	2132530-31	ND	2.5017	3.3445	mg/kg		74.8		50 - 130	
	MSD	2132530-31	ND	2.5386	3.3003	mg/kg	1.5	76.9	30	50 - 130	
4-Nitrophenol	MS	2132530-31	ND	1.0435	1.6722	mg/kg		62.4		30 - 140	
	MSD	2132530-31	ND	0.99081	1.6502	mg/kg	5.2	60.0	30	30 - 140	
Pentachlorophenol	MS	2132530-31	ND	1.0030	1.6722	mg/kg		60.0		30 - 130	
	MSD	2132530-31	ND	0.93222	1.6502	mg/kg	7.3	56.5	30	30 - 130	
Phenol	MS	2132530-31	ND	1.2167	1.6722	mg/kg		72.8		40 - 150	
	MSD	2132530-31	ND	1.1771	1.6502	mg/kg	3.3	71.3	30	40 - 150	
2,4,6-Trichlorophenol	MS	2132530-31	ND	1.2498	1.6722	mg/kg		74.7		50 - 130	
	MSD	2132530-31	ND	1.1435	1.6502	mg/kg	8.9	69.3	30	50 - 130	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Base Neutral and Acid Extractables Organic Analysis (EPA Method 8270C)

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B123094	Used client sample: N										
2-Fluorophenol (Surrogate)	MS	2132530-31	ND	1.0201	1.3378	mg/kg		76.3		20 - 130	
	MSD	2132530-31	ND	0.99209	1.3201	mg/kg	2.8	75.2		20 - 130	
Phenol-d5 (Surrogate)	MS	2132530-31	ND	0.99398	1.3378	mg/kg		74.3		30 - 130	
	MSD	2132530-31	ND	1.0052	1.3201	mg/kg	1.1	76.1		30 - 130	
Nitrobenzene-d5 (Surrogate)	MS	2132530-31	ND	1.0040	1.3378	mg/kg		75.0		30 - 130	
	MSD	2132530-31	ND	1.0193	1.3201	mg/kg	1.5	77.2		30 - 130	
2-Fluorobiphenyl (Surrogate)	MS	2132530-31	ND	0.98562	1.3378	mg/kg		73.7		30 - 140	
	MSD	2132530-31	ND	0.92934	1.3201	mg/kg	5.9	70.4		30 - 140	
2,4,6-Tribromophenol (Surrogate)	MS	2132530-31	ND	0.91371	1.3378	mg/kg		68.3		20 - 150	
	MSD	2132530-31	ND	0.85507	1.3201	mg/kg	6.6	64.8		20 - 150	
p-Terphenyl-d14 (Surrogate)	MS	2132530-31	ND	0.40736	0.66890	mg/kg		60.9		30 - 150	
	MSD	2132530-31	ND	0.41233	0.66007	mg/kg	1.2	62.5		30 - 150	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Petroleum Hydrocarbons

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B122699						
TPH - Gasoline (C4-C12)	B122699-BLK1	ND	mg/kg	4.0	1.0	
TPH - Diesel (C13 - C22)	B122699-BLK1	ND	mg/kg	2.0	0.77	
TPH - Motor Oil (C23 - C36)	B122699-BLK1	ND	mg/kg	4.0	1.8	
Tetracosane (Surrogate)	**B122699-BLK1**	**58.5**	%	**20 - 145 (LCL - UCL)**		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Petroleum Hydrocarbons

Quality Control Report - Laboratory Control Sample

Constituent	QC Sample ID	Type	Result	Spike Level	Units	Percent Recovery	RPD	Control Limits Percent Recovery	Control Limits RPD	Lab Quals
QC Batch ID: B122699										
TPH - Diesel (C13 - C22)	B122699-BS1	LCS	13.648	16.779	mg/kg	81.3		64 - 124		
	B122699-BSD1	LCSD	13.531	16.502	mg/kg	82.0	0.9	64 - 124	30	
Tetracosane (Surrogate)	B122699-BS1	LCS	0.69166	0.67114	mg/kg	103		20 - 145		
	B122699-BSD1	LCSD	0.69736	0.66007	mg/kg	106	0.8	20 - 145		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Petroleum Hydrocarbons

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B122699	Used client sample: N										
TPH - Diesel (C13 - C22)	MS	**2132753-01**	**2.5799**	**9.0915**	**16.779**	**mg/kg**		**38.8**		**52 - 131**	**A10,Q03**
	MSD	**2132753-01**	**2.5799**	**10.506**	**16.835**	**mg/kg**	**14.4**	**47.1**	**30**	**52 - 131**	**A10,Q03**
Tetracosane (Surrogate)	MS	2132753-01	ND	0.33024	0.67114	mg/kg		49.2		20 - 145	A10
	MSD	2132753-01	ND	0.45901	0.67340	mg/kg	32.6	68.2		20 - 145	A10

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Chemical Analysis

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B123604						
pH	B123604-BLK1	ND	pH Units	0.05	0.05	
pH Measurement Temperature	B123604-BLK1	ND	C	0.1	0.1	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Chemical Analysis

Quality Control Report - Laboratory Control Sample

Constituent	QC Sample ID	Type	Result	Spike Level	Units	Percent Recovery	RPD	Control Limits Percent Recovery	Control Limits RPD	Lab Quals
QC Batch ID: B123604										
pH	B123604-BS1	LCS	4.0330	4.0000	pH Units	101		95 - 105		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Chemical Analysis

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B123604	Used client sample: N										
pH	DUP	2132667-01	6.0640	6.0540		pH Units	0.2		20		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Concentrations (TTLC)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B122837						
Antimony	B122837-BLK2	ND	mg/kg	5.0	0.33	
Arsenic	B122837-BLK2	ND	mg/kg	1.0	0.40	
Barium	B122837-BLK2	ND	mg/kg	0.50	0.18	
Beryllium	B122837-BLK2	ND	mg/kg	0.50	0.047	
Cadmium	B122837-BLK2	ND	mg/kg	0.50	0.052	
Chromium	**B122837-BLK2**	**0.82390**	**mg/kg**	**0.50**	**0.050**	**M01**
Cobalt	B122837-BLK2	ND	mg/kg	2.5	0.098	
Copper	B122837-BLK2	ND	mg/kg	1.0	0.050	
Lead	B122837-BLK2	ND	mg/kg	2.5	0.41	
Molybdenum	B122837-BLK2	ND	mg/kg	2.5	0.050	
Nickel	**B122837-BLK2**	**0.56592**	**mg/kg**	**0.50**	**0.15**	**M01**
Selenium	B122837-BLK2	ND	mg/kg	1.0	0.98	
Silver	B122837-BLK2	ND	mg/kg	0.50	0.067	
Thallium	B122837-BLK2	ND	mg/kg	5.0	0.64	
Vanadium	B122837-BLK2	ND	mg/kg	0.50	0.11	
Zinc	**B122837-BLK2**	**0.51890**	**mg/kg**	**2.5**	**0.087**	**J**
QC Batch ID: B123042						
Mercury	B123042-BLK1	ND	mg/kg	0.16	0.016	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Concentrations (TTLC)

Quality Control Report - Laboratory Control Sample

Constituent	QC Sample ID	Type	Result	Spike Level	Units	Percent Recovery	RPD	Control Limits Percent Recovery	Control Limits RPD	Lab Quals
QC Batch ID: B122837										
Antimony	B122837-BS2	LCS	95.467	100.00	mg/kg	95.5		75 - 125		
Arsenic	B122837-BS2	LCS	17.366	20.000	mg/kg	86.8		75 - 125		
Barium	B122837-BS2	LCS	104.60	100.00	mg/kg	105		75 - 125		
Beryllium	B122837-BS2	LCS	9.4461	10.000	mg/kg	94.5		75 - 125		
Cadmium	B122837-BS2	LCS	9.8297	10.000	mg/kg	98.3		75 - 125		
Chromium	B122837-BS2	LCS	98.233	100.00	mg/kg	98.2		75 - 125		
Cobalt	B122837-BS2	LCS	97.100	100.00	mg/kg	97.1		75 - 125		
Copper	B122837-BS2	LCS	97.724	100.00	mg/kg	97.7		75 - 125		
Lead	B122837-BS2	LCS	103.49	100.00	mg/kg	103		75 - 125		
Molybdenum	B122837-BS2	LCS	98.377	100.00	mg/kg	98.4		75 - 125		
Nickel	B122837-BS2	LCS	96.221	100.00	mg/kg	96.2		75 - 125		
Selenium	B122837-BS2	LCS	17.122	20.000	mg/kg	85.6		75 - 125		
Silver	B122837-BS2	LCS	9.5298	10.000	mg/kg	95.3		75 - 125		
Thallium	B122837-BS2	LCS	116.69	100.00	mg/kg	117		75 - 125		
Vanadium	B122837-BS2	LCS	96.305	100.00	mg/kg	96.3		75 - 125		
Zinc	B122837-BS2	LCS	96.704	100.00	mg/kg	96.7		75 - 125		
QC Batch ID: B123042										
Mercury	B123042-BS1	LCS	0.88000	0.80000	mg/kg	110		80 - 120		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Concentrations (TTLC)

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B122837	Used client sample: N										
Antimony	DUP	2132754-14	ND	ND		mg/kg			20		
	MS	2132754-14	ND	17.840	100.00	mg/kg		17.8		16 - 119	J
	MSD	2132754-14	ND	19.347	100.00	mg/kg	8.1	19.3	20	16 - 119	J
Arsenic	DUP	2132754-14	8.2078	9.2831		mg/kg	12.3		20		
	MS	2132754-14	8.2078	23.304	20.000	mg/kg		75.5		75 - 125	
	MSD	2132754-14	8.2078	23.218	20.000	mg/kg	0.4	75.1	20	75 - 125	
Barium	DUP	**2132754-14**	**612.02**	**617.56**		**mg/kg**	**0.9**		**20**		
	MS	**2132754-14**	**612.02**	**866.64**	**100.00**	**mg/kg**		**255**		**75 - 125**	**A03**
	MSD	**2132754-14**	**612.02**	**684.25**	**100.00**	**mg/kg**	**23.5**	**72.2**	**20**	**75 - 125**	**A03**
Beryllium	DUP	2132754-14	0.28625	0.31181		mg/kg	8.5		20		J
	MS	2132754-14	0.28625	8.9727	10.000	mg/kg		86.9		75 - 125	
	MSD	2132754-14	0.28625	8.8501	10.000	mg/kg	1.4	85.6	20	75 - 125	
Cadmium	DUP	2132754-14	0.62545	0.75208		mg/kg	18.4		20		J
	MS	2132754-14	0.62545	9.6635	10.000	mg/kg		90.4		75 - 125	
	MSD	2132754-14	0.62545	9.4296	10.000	mg/kg	2.5	88.0	20	75 - 125	
Chromium	DUP	2132754-14	55.151	48.306		mg/kg	13.2		20		
	MS	2132754-14	55.151	143.79	100.00	mg/kg		88.6		75 - 125	
	MSD	2132754-14	55.151	135.24	100.00	mg/kg	6.1	80.1	20	75 - 125	
Cobalt	DUP	2132754-14	11.832	11.510		mg/kg	2.8		20		J
	MS	2132754-14	11.832	99.585	100.00	mg/kg		87.8		75 - 125	
	MSD	2132754-14	11.832	98.562	100.00	mg/kg	1.0	86.7	20	75 - 125	
Copper	DUP	2132754-14	33.974	33.087		mg/kg	2.6		20		
	MS	2132754-14	33.974	121.91	100.00	mg/kg		87.9		75 - 125	
	MSD	2132754-14	33.974	118.55	100.00	mg/kg	2.8	84.6	20	75 - 125	
Lead	DUP	**2132754-14**	**17.701**	**55.473**		**mg/kg**	**103**		**20**		**A02**
	MS	**2132754-14**	**17.701**	**107.40**	**100.00**	**mg/kg**		**89.7**		**75 - 125**	
	MSD	**2132754-14**	**17.701**	**106.81**	**100.00**	**mg/kg**	**0.6**	**89.1**	**20**	**75 - 125**	
Molybdenum	DUP	2132754-14	1.6459	1.9157		mg/kg	15.2		20		J
	MS	2132754-14	1.6459	83.478	100.00	mg/kg		81.8		75 - 125	
	MSD	2132754-14	1.6459	82.538	100.00	mg/kg	1.1	80.9	20	75 - 125	
Nickel	DUP	2132754-14	65.484	61.169		mg/kg	6.8		20		
	MS	2132754-14	65.484	149.43	100.00	mg/kg		83.9		75 - 125	
	MSD	2132754-14	65.484	142.37	100.00	mg/kg	4.8	76.9	20	75 - 125	
Selenium	DUP	**2132754-14**	**ND**	**ND**		**mg/kg**			**20**		
	MS	**2132754-14**	**ND**	**15.849**	**20.000**	**mg/kg**		**79.2**		**75 - 125**	
	MSD	**2132754-14**	**ND**	**13.292**	**20.000**	**mg/kg**	**17.5**	**66.5**	**20**	**75 - 125**	**Q03**
Silver	DUP	2132754-14	ND	ND		mg/kg			20		
	MS	2132754-14	ND	8.2727	10.000	mg/kg		82.7		75 - 125	
	MSD	2132754-14	ND	8.0168	10.000	mg/kg	3.1	80.2	20	75 - 125	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Total Concentrations (TTLC)

Quality Control Report - Precision & Accuracy

Constituent	Type	Source Sample ID	Source Result	Result	Spike Added	Units	RPD	Percent Recovery	Control Limits RPD	Control Limits Percent Recovery	Lab Quals
QC Batch ID: B122837	Used client sample: N										
Thallium	DUP	2132754-14	ND	ND		mg/kg			20		
	MS	2132754-14	ND	87.796	100.00	mg/kg		87.8		75 - 125	
	MSD	2132754-14	ND	91.465	100.00	mg/kg	4.1	91.5	20	75 - 125	
Vanadium	DUP	2132754-14	62.678	61.399		mg/kg	2.1		20		
	MS	2132754-14	62.678	154.97	100.00	mg/kg		92.3		75 - 125	
	MSD	2132754-14	62.678	149.47	100.00	mg/kg	3.6	86.8	20	75 - 125	
Zinc	DUP	2132754-14	90.276	99.338		mg/kg	9.6		20		
	MS	2132754-14	90.276	189.86	100.00	mg/kg		99.6		75 - 125	
	MSD	2132754-14	90.276	179.56	100.00	mg/kg	5.6	89.3	20	75 - 125	
QC Batch ID: B123042	Used client sample: N										
Mercury	DUP	2133050-01	ND	ND		mg/kg			20		
	MS	2133050-01	ND	0.76290	0.80645	mg/kg		94.6		80 - 120	
	MSD	2133050-01	ND	0.76935	0.80645	mg/kg	0.8	95.4	20	80 - 120	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

EMSL Analytical, Inc.
464 McCormick Street San Leandro, CA 94577
Phone/Fax: (510) 895-3675 / (510) 895-3680
http://www.EMSL.com / sanleandrolab@emsl.com

EMSL Order: 092116626
Customer ID: BCLA50
Customer PO: 2132975
Project ID:

Attention: Ragen Schallock
BC Laboratories, Inc.
4100 Atlas Court
Bakersfield, CA 93308

Project: 2132975

Phone: (661) 327-4911
Fax: (661) 327-1918
Received: 10/25/2021 10:00 AM
Analysis Date: 10/26/2021
Collected: 10/19/2021

Test Report: PLM Analysis of Bulk Samples for Asbestos via EPA 600/R-93/116 Method with CARB 435 Prep (Milling) Level A for 0.25% Target Analytical Sensitivity

			Non-Asbestos		Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
2132975-02 *092116626-0001*	SOIL	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2132975-04 *092116626-0002*	SOIL	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2132975-06 *092116626-0003*	SOIL	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Analyst(s)
Gavin Lee (3)

Cecilia Yu, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. Some samples may contain asbestos fibers present in dimensions below PLM resolution limits. EMSL suggests that samples reported as <0.25% or none detected undergo additional analysis via TEM.

Samples analyzed by EMSL Analytical, Inc San Leandro, CA

Initial report from: 10/26/2021 16:16:46

ASB_PLMPC_0006_0003 Printed 10/26/2021 4:16:54PM

Page 1 of 1

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 11/01/2021 11:59
Project: Soil Samples
Project Number: 2103-2 918 Rich Avenue, Mountain View, CA
Project Manager: Lawrence Bush

Notes And Definitions

J	Estimated Value (CLP Flag)
MDL	Method Detection Limit
ND	Analyte Not Detected
PQL	Practical Quantitation Limit
A02	The difference between duplicate readings is less than the quantitation limit.
A03	The sample concentration was more than 4 times the spike level.
A10	Detection and quantitation limits were raised due to matrix interference.
A52	Chromatogram not typical of diesel.
A57	Chromatogram not typical of motor oil.
M01	Analyte detected in the Method Blank at or above the PQL.
pH1:1	pH result reported on a 1:1 dilution of sample
Q03	Matrix spike recovery(s) was(were) not within the control limits.
S09	The surrogate recovery for this compound was not within the control limits.
S11	The analyte in the Method Blank is greater than the laboratory PQL but the sample result is greater than 10 times the Method Blank.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

APPENDIX D

SOIL VAPOR ANALYTICAL REPORT

Date of Report: 10/26/2021

Lawrence Bush

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Client Project:	2103-02 Rich Avenue
BCL Project:	Air Samples (No EDF)
BCL Work Order:	2132929
Invoice ID:	B432513

Enclosed are the results of analyses for samples received by the laboratory on 10/19/2021. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Contact Person: Ragen Schallock
Client Service Rep

Stuart Buttram
Technical Director

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Table of Contents

Sample Information

Chain of Custody and Cooler Receipt form 3
Laboratory / Client Sample Cross Reference 5

Sample Results

2132929-01 - SV-1

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP) 6

2132929-02 - SV-2

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP) 9

2132929-03 - SV-3

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP) 12

Quality Control Reports

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

Method Blank Analysis 15
Laboratory Control Sample 18

Notes

Notes and Definitions 19

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Summa COC

MAI Work Order # _____

BC LABORATORIES, INC.

4100 Atlas Court, Bakersfield, Ca. 93308
Telephone: (661) 321-4911 / Fax: (661) 327-1918
www.bclabs.com

CHAIN OF CUSTODY RECORD STAT

Turn Around Time: 1 Day Rush | 2 Day Rush | 3 Day Rush | ~~RUSH~~ | Quote #
J-Flag / MDL | ESL | Bottle Order #
Delivery Format: PDF ● | GeoTracker EDF | EDD | Detect Summary

Report To: Lawrence Bush — Bill To: EIS, INC.
Company: ENVIRONMENTAL INVESTIGATION SERVICES, INC.
Email: LAWRENCE@EIS1.NET — 21-32929
Alt Email: pwillits@eis1.net — Tele: 408-609-6381
Project Name: Rich Ave. — Project#: 2103-2
Project Location: 518 Rich Ave., Mountain View, CA — PO #
Sampler Signature

Analysis Requested

Helium Shroud SN#
Leak Check Default is IPA
Helium Leak Check %
● IPA, Norflurane, 1,1-difluroethane µg/m3
Other (Specify)

	SAMPLE ID Location / Field Point	Sampling Start Date	Sampling Start Time	End Time	Canister SN#	Sample Kit / Manifold #	VOCs TO-15 (µg/m³) - See Notes	VOCs TO-17 (µg/m³) - See Notes	8010 by TO-15 (µg/m³)	TPH(g) (µg/m³) TO-15	TPH(ss) (µg/m³)	LEED: (inc. 4PCH, Formaldehyde, CO, Total VOCs)	Fixed Gas (CO_2, Methane, Ethane, Ethylene, Acetylene/Propane, CO) %	Fixed Gas (O_2, N_2) %	APH: Aliphatic and/or Aromatic (circle one) µg/m³	Matrix: Soilgas	Matrix: Indoor Air	Canister Pressure / Vacuum: Initial	Canister Pressure / Vacuum: Final
-1	SV-1	10/19/21	1126	1132	10469	1344	X			X						X		-28	-5
-2	SV-2	↓	1139	1146	10406	1514	X			X						X		-27	-5
-3	SV-3	↓	1153	1159	6436	1292	X			X						X		-27	-5

**MAI clients MUST disclose any dangerous chemicals known to be present in their submitted samples in concentrations that may cause immediate harm or serious future health endangerment as a result of brief, gloved, open air, sample handling by MAI staff. Non-disclosure incurs an immediate $250 surcharge and the client is subject to full legal liability for harm suffered. Thank you for your understanding and for allowing us to work safely.

Relinquished By / Company Name	Date	Time	Received By / Company Name	Date	Time	Comments / Instructions
E.I.S	10/11/21	1315	PBel	10/19/21	1315	If possible, please
PBel	10/19/21	1401	Tony Brown	10/19-21	1401	analyze w/ 5 day
Tony Brown	10/19-21	1830		10/19/21	1830	turn-around
	10/19/21	2215	Francoespinoza	10/19/21	2215	

Client will be charged $56 for each unused Summa canister.

Page 1 of 1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Chain of Custody and Cooler Receipt Form for 2132929 Page 2 of 2

BC LABORATORIES INC. COOLER RECEIPT FORM Page 1 Of 1

Submission #: 2132929

SHIPPING INFORMATION
Fed Ex ☐ UPS ☐ GSO / GLS ☐ Hand Delivery ☐
BC Lab Field Service ☑ Other ☐ (Specify)_____

SHIPPING CONTAINER
Ice Chest ☑ None ☐ Box ☐
Other ☐ (Specify)_____

FREE LIQUID
YES ☐ NO ☑
W / S

Refrigerant: Ice ☐ Blue Ice ☐ None ☑ Other ☐ Comments:

Custody Seals: Ice Chest ☐ Intact? Yes ☐ No ☐ | Containers ☑ Intact? Yes ☑ No ☐ | None ☐ Comments:

All samples received? Yes ☑ No ☐ All samples containers intact? Yes ☑ No ☐ Description(s) match COC? Yes ☑ No ☐

COC Received ☑ YES ☐ NO

Emissivity: _____ Container: SUMMA CANISTER Thermometer ID: _____

Temperature: (A) room °C / (C) Temp °C

Date/Time 10/19/21 2245

Analyst Init FE

SAMPLE CONTAINERS	SAMPLE NUMBERS 1	2	3	4	5	6	7	8	9	10
QT PE UNPRES										
4oz / 8oz / 16oz PE UNPRES										
2oz Cr+6										
QT INORGANIC CHEMICAL METALS										
INORGANIC CHEMICAL METALS 4oz / 8oz / 16oz										
PT CYANIDE										
PT NITROGEN FORMS										
PT TOTAL SULFIDE										
2oz. NITRATE / NITRITE										
PT TOTAL ORGANIC CARBON										
PT CHEMICAL OXYGEN DEMAND										
PtA PHENOLICS										
40ml VOA VIAL TRAVEL BLANK										
40ml VOA VIAL										
QT EPA 1664B										
PT ODOR										
RADIOLOGICAL										
BACTERIOLOGICAL										
40 ml VOA VIAL- 504										
QT EPA 508/608.3/8081A										
QT EPA 515.1/8151A										
QT EPA 525.2										
QT EPA 525.2 TRAVEL BLANK										
40ml EPA 547										
40ml EPA 531.1										
8oz EPA 548.1										
QT EPA 549.2										
QT EPA 8015M										
QT EPA 8270C										
8oz / 16oz / 32oz AMBER										
8oz / 16oz / 32oz JAR										
SOIL SLEEVE										
PCB VIAL										
PLASTIC BAG										
TEDLAR BAG										
FERROUS IRON										
ENCORE										
SMART KIT										
SUMMA CANISTER										

DISTRIBUTION
SUB-OUT
CHK BY

Comments:
Sample Numbering Completed By: RRE Date/Time: 10/19/21 2300
A = Actual / C = Corrected

Rev 22 04/13/21
(S:\WPDocs\WordPerfect\LAB_DOCS\FORMS\SAMREC rev 29)

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Laboratory / Client Sample Cross Reference

Laboratory	Client Sample Information			
2132929-01	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 11:32
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SV-1	**Lab Matrix:**	Air
	Sampled By:	client	**Sample Type:**	Vapor or Air
2132929-02	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 11:46
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SV-2	**Lab Matrix:**	Air
	Sampled By:	client	**Sample Type:**	Vapor or Air
2132929-03	**COC Number:**	---	**Receive Date:**	10/19/2021 22:15
	Project Number:	---	**Sampling Date:**	10/19/2021 11:59
	Sampling Location:	---	**Sample Depth:**	---
	Sampling Point:	SV-3	**Lab Matrix:**	Air
	Sampled By:	client	**Sample Type:**	Vapor or Air

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-01 | **Client Sample Name:** SV-1, 10/19/2021 11:32:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
Acetone	**79**	**ug/m3**	**84**	**7.3**	**EPA-TO-15**	ND	**J,A01**	1
Acrylonitrile	ND	ug/m3	34	4.6	EPA-TO-15	ND	A01	1
Allyl chloride	ND	ug/m3	34	4.7	EPA-TO-15	ND	A01	1
t-Amyl Methyl ether	ND	ug/m3	84	5.2	EPA-TO-15	ND	A01	1
Benzene	ND	ug/m3	34	3.5	EPA-TO-15	ND	A01	1
Benzyl chloride	ND	ug/m3	170	4.4	EPA-TO-15	ND	A01	1
Bromodichloromethane	ND	ug/m3	84	7.6	EPA-TO-15	ND	A01	1
Bromoform	ND	ug/m3	170	15	EPA-TO-15	ND	A01	1
Bromomethane	ND	ug/m3	34	7.9	EPA-TO-15	ND	A01	1
1,3-Butadiene	ND	ug/m3	34	3.7	EPA-TO-15	ND	A01	1
t-Butyl alcohol	ND	ug/m3	84	12	EPA-TO-15	ND	A01	1
Carbon disulfide	ND	ug/m3	34	3.2	EPA-TO-15	ND	A01	1
Carbon tetrachloride	ND	ug/m3	84	7.6	EPA-TO-15	ND	A01	1
Chlorobenzene	ND	ug/m3	84	6.8	EPA-TO-15	ND	A01	1
Chloroethane	ND	ug/m3	34	9.0	EPA-TO-15	ND	A01	1
Chloroform	ND	ug/m3	84	9.1	EPA-TO-15	ND	A01	1
Chloromethane	ND	ug/m3	34	3.5	EPA-TO-15	ND	A01	1
Cyclohexane	ND	ug/m3	34	6.4	EPA-TO-15	ND	A01	1
Dibromochloromethane	ND	ug/m3	84	7.3	EPA-TO-15	ND	A01	1
1,2-Dibromo-3-chloropropane	ND	ug/m3	84	29	EPA-TO-15	ND	A01	1
1,2-Dibromoethane	ND	ug/m3	84	9.8	EPA-TO-15	ND	A01	1
Dibromomethane	ND	ug/m3	84	9.6	EPA-TO-15	ND	A01	1
1,2-Dichlorobenzene	ND	ug/m3	84	8.4	EPA-TO-15	ND	A01	1
1,3-Dichlorobenzene	ND	ug/m3	84	5.2	EPA-TO-15	ND	A01	1
1,4-Dichlorobenzene	ND	ug/m3	84	8.4	EPA-TO-15	ND	A01	1
Dichlorodifluoromethane	ND	ug/m3	84	7.6	EPA-TO-15	ND	A01	1
1,1-Dichloroethane	ND	ug/m3	84	3.9	EPA-TO-15	ND	A01	1
1,2-Dichloroethane	ND	ug/m3	84	4.4	EPA-TO-15	ND	A01	1
1,1-Dichloroethene	ND	ug/m3	84	5.2	EPA-TO-15	ND	A01	1
cis-1,2-Dichloroethene	ND	ug/m3	34	5.4	EPA-TO-15	ND	A01	1
trans-1,2-Dichloroethene	ND	ug/m3	34	4.6	EPA-TO-15	ND	A01	1
1,2-Dichloropropane	ND	ug/m3	84	5.4	EPA-TO-15	ND	A01	1
cis-1,3-Dichloropropene	ND	ug/m3	84	5.1	EPA-TO-15	ND	A01	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-01 | **Client Sample Name:** SV-1, 10/19/2021 11:32:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
trans-1,3-Dichloropropene	ND	ug/m3	84	6.8	EPA-TO-15	ND	A01	1
1,2-Dichloro-1,1,2,2-tetrafluoroethane	ND	ug/m3	84	15	EPA-TO-15	ND	A01	1
1,1-Difluoroethane	ND	ug/m3	84	34	EPA-TO-15	ND	A01	1
Diisopropyl ether	ND	ug/m3	84	6.6	EPA-TO-15	ND	A01	1
1,4-Dioxane	ND	ug/m3	34	5.6	EPA-TO-15	ND	A01	1
Ethanol	ND	ug/m3	34	7.1	EPA-TO-15	ND	A01	1
Ethyl acetate	ND	ug/m3	34	5.6	EPA-TO-15	ND	A01	1
Ethylbenzene	ND	ug/m3	84	5.4	EPA-TO-15	ND	A01	1
1-Ethyl-4-methylbenzene	ND	ug/m3	84	5.1	EPA-TO-15	ND	A01	1
Ethyl t-butyl ether	ND	ug/m3	84	5.6	EPA-TO-15	ND	A01	1
n-Heptane	ND	ug/m3	34	5.7	EPA-TO-15	ND	A01	1
Hexachlorobutadiene	ND	ug/m3	170	25	EPA-TO-15	ND	A01	1
Hexachloroethane	ND	ug/m3	34	12	EPA-TO-15	ND	A01	1
Hexane	ND	ug/m3	84	3.4	EPA-TO-15	ND	A01	1
2-Hexanone	ND	ug/m3	84	4.9	EPA-TO-15	ND	A01	1
Isooctane	ND	ug/m3	84	5.9	EPA-TO-15	ND	A01	1
Isopropyl alcohol	**12**	**ug/m3**	**34**	**5.4**	**EPA-TO-15**	ND	**J,A01**	1
Methylene chloride	ND	ug/m3	170	6.8	EPA-TO-15	ND	A01	1
Methyl ethyl ketone	ND	ug/m3	34	3.2	EPA-TO-15	ND	A01	1
Methyl iodide	ND	ug/m3	170	9.8	EPA-TO-15	ND	A01	1
Methyl isobutyl ketone	**15**	**ug/m3**	**84**	**4.4**	**EPA-TO-15**	ND	**J,A01**	1
Methyl t-butyl ether	ND	ug/m3	34	4.7	EPA-TO-15	ND	A01	1
Naphthalene	ND	ug/m3	340	24	EPA-TO-15	ND	A01	1
Propylene	**24**	**ug/m3**	**34**	**4.2**	**EPA-TO-15**	ND	**J,A01**	1
Styrene	ND	ug/m3	84	4.1	EPA-TO-15	ND	A01	1
1,1,1,2-Tetrachloroethane	ND	ug/m3	84	10	EPA-TO-15	ND	A01	1
1,1,2,2-Tetrachloroethane	ND	ug/m3	84	7.9	EPA-TO-15	ND	A01	1
Tetrachloroethene	ND	ug/m3	84	8.4	EPA-TO-15	ND	A01	1
1,1,1,2-Tetrafluoroethane	ND	ug/m3	84	11	EPA-TO-15	ND	A01	1
Tetrahydrofuran	ND	ug/m3	34	4.6	EPA-TO-15	ND	A01	1
Toluene	ND	ug/m3	34	4.6	EPA-TO-15	ND	A01	1
1,2,4-Trichlorobenzene	ND	ug/m3	170	14	EPA-TO-15	ND	A01	1
1,1,1-Trichloroethane	ND	ug/m3	84	6.6	EPA-TO-15	ND	A01	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-01 | **Client Sample Name:** SV-1, 10/19/2021 11:32:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
1,1,2-Trichloroethane	ND	ug/m3	84	10	EPA-TO-15	ND	A01	1
Trichloroethene	ND	ug/m3	84	9.1	EPA-TO-15	ND	A01	1
Trichlorofluoromethane	ND	ug/m3	84	7.9	EPA-TO-15	ND	A01	1
1,2,3-Trichloropropane	ND	ug/m3	84	8.1	EPA-TO-15	ND	A01	1
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	ug/m3	84	9.3	EPA-TO-15	ND	A01	1
1,2,4-Trimethylbenzene	ND	ug/m3	84	6.8	EPA-TO-15	ND	A01	1
1,3,5-Trimethylbenzene	ND	ug/m3	84	6.8	EPA-TO-15	ND	A01	1
Vinyl acetate	ND	ug/m3	34	5.6	EPA-TO-15	ND	A01	1
Vinyl bromide	ND	ug/m3	84	5.4	EPA-TO-15	ND	A01	1
Vinyl chloride	ND	ug/m3	34	6.6	EPA-TO-15	ND	A01	1
p- & m-Xylenes	ND	ug/m3	84	10	EPA-TO-15	ND	A01	1
o-Xylene	ND	ug/m3	84	5.1	EPA-TO-15	ND	A01	1
Total Xylenes	ND	ug/m3	170	15	EPA-TO-15	ND	A01	1
Total Petroleum Hydrocarbons	**2500**	**ug/m3**	**3400**	**350**	**EPA-TO-15**	ND	**J,A01**	1
4-Bromofluorobenzene (Surrogate)	99.7	%	70 - 130 (LCL - UCL)		EPA-TO-15			1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-TO-15	10/22/21 10:08	10/23/21 15:56	BEP	MS-A1	16.900	B123008	EPA TO-15

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-02 | **Client Sample Name:** SV-2, 10/19/2021 11:46:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
Acetone	**170**	**ug/m3**	**88**	**7.5**	**EPA-TO-15**	ND	**A01**	1
Acrylonitrile	ND	ug/m3	35	4.7	EPA-TO-15	ND	A01	1
Allyl chloride	ND	ug/m3	35	4.9	EPA-TO-15	ND	A01	1
t-Amyl Methyl ether	ND	ug/m3	88	5.4	EPA-TO-15	ND	A01	1
Benzene	**20**	**ug/m3**	**35**	**3.7**	**EPA-TO-15**	ND	**J,A01**	1
Benzyl chloride	ND	ug/m3	180	4.6	EPA-TO-15	ND	A01	1
Bromodichloromethane	ND	ug/m3	88	7.9	EPA-TO-15	ND	A01	1
Bromoform	ND	ug/m3	180	15	EPA-TO-15	ND	A01	1
Bromomethane	ND	ug/m3	35	8.2	EPA-TO-15	ND	A01	1
1,3-Butadiene	ND	ug/m3	35	3.8	EPA-TO-15	ND	A01	1
t-Butyl alcohol	ND	ug/m3	88	12	EPA-TO-15	ND	A01	1
Carbon disulfide	ND	ug/m3	35	3.3	EPA-TO-15	ND	A01	1
Carbon tetrachloride	ND	ug/m3	88	7.9	EPA-TO-15	ND	A01	1
Chlorobenzene	ND	ug/m3	88	7.0	EPA-TO-15	ND	A01	1
Chloroethane	ND	ug/m3	35	9.3	EPA-TO-15	ND	A01	1
Chloroform	ND	ug/m3	88	9.4	EPA-TO-15	ND	A01	1
Chloromethane	ND	ug/m3	35	3.7	EPA-TO-15	ND	A01	1
Cyclohexane	ND	ug/m3	35	6.6	EPA-TO-15	ND	A01	1
Dibromochloromethane	ND	ug/m3	88	7.5	EPA-TO-15	ND	A01	1
1,2-Dibromo-3-chloropropane	ND	ug/m3	88	30	EPA-TO-15	ND	A01	1
1,2-Dibromoethane	ND	ug/m3	88	10	EPA-TO-15	ND	A01	1
Dibromomethane	ND	ug/m3	88	10	EPA-TO-15	ND	A01	1
1,2-Dichlorobenzene	ND	ug/m3	88	8.8	EPA-TO-15	ND	A01	1
1,3-Dichlorobenzene	ND	ug/m3	88	5.4	EPA-TO-15	ND	A01	1
1,4-Dichlorobenzene	ND	ug/m3	88	8.8	EPA-TO-15	ND	A01	1
Dichlorodifluoromethane	ND	ug/m3	88	7.9	EPA-TO-15	ND	A01	1
1,1-Dichloroethane	ND	ug/m3	88	4.0	EPA-TO-15	ND	A01	1
1,2-Dichloroethane	ND	ug/m3	88	4.6	EPA-TO-15	ND	A01	1
1,1-Dichloroethene	ND	ug/m3	88	5.4	EPA-TO-15	ND	A01	1
cis-1,2-Dichloroethene	ND	ug/m3	35	5.6	EPA-TO-15	ND	A01	1
trans-1,2-Dichloroethene	ND	ug/m3	35	4.7	EPA-TO-15	ND	A01	1
1,2-Dichloropropane	ND	ug/m3	88	5.6	EPA-TO-15	ND	A01	1
cis-1,3-Dichloropropene	ND	ug/m3	88	5.2	EPA-TO-15	ND	A01	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-02 | **Client Sample Name:** SV-2, 10/19/2021 11:46:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
trans-1,3-Dichloropropene	ND	ug/m3	88	7.0	EPA-TO-15	ND	A01	1
1,2-Dichloro-1,1,2,2-tetrafluoroethane	ND	ug/m3	88	16	EPA-TO-15	ND	A01	1
1,1-Difluoroethane	ND	ug/m3	88	35	EPA-TO-15	ND	A01	1
Diisopropyl ether	ND	ug/m3	88	6.8	EPA-TO-15	ND	A01	1
1,4-Dioxane	ND	ug/m3	35	5.8	EPA-TO-15	ND	A01	1
Ethanol	ND	ug/m3	35	7.4	EPA-TO-15	ND	A01	1
Ethyl acetate	ND	ug/m3	35	5.8	EPA-TO-15	ND	A01	1
Ethylbenzene	ND	ug/m3	88	5.6	EPA-TO-15	ND	A01	1
1-Ethyl-4-methylbenzene	ND	ug/m3	88	5.2	EPA-TO-15	ND	A01	1
Ethyl t-butyl ether	ND	ug/m3	88	5.8	EPA-TO-15	ND	A01	1
n-Heptane	ND	ug/m3	35	6.0	EPA-TO-15	ND	A01	1
Hexachlorobutadiene	ND	ug/m3	180	26	EPA-TO-15	ND	A01	1
Hexachloroethane	ND	ug/m3	35	13	EPA-TO-15	ND	A01	1
Hexane	ND	ug/m3	88	3.5	EPA-TO-15	ND	A01	1
2-Hexanone	ND	ug/m3	88	5.1	EPA-TO-15	ND	A01	1
Isooctane	ND	ug/m3	88	6.1	EPA-TO-15	ND	A01	1
Isopropyl alcohol	**40**	**ug/m3**	**35**	**5.6**	**EPA-TO-15**	ND	**A01**	1
Methylene chloride	ND	ug/m3	180	7.0	EPA-TO-15	ND	A01	1
Methyl ethyl ketone	ND	ug/m3	35	3.3	EPA-TO-15	ND	A01	1
Methyl iodide	ND	ug/m3	180	10	EPA-TO-15	ND	A01	1
Methyl isobutyl ketone	ND	ug/m3	88	4.6	EPA-TO-15	ND	A01	1
Methyl t-butyl ether	ND	ug/m3	35	4.9	EPA-TO-15	ND	A01	1
Naphthalene	ND	ug/m3	350	24	EPA-TO-15	ND	A01	1
Propylene	ND	ug/m3	35	4.4	EPA-TO-15	ND	A01	1
Styrene	ND	ug/m3	88	4.2	EPA-TO-15	ND	A01	1
1,1,1,2-Tetrachloroethane	ND	ug/m3	88	11	EPA-TO-15	ND	A01	1
1,1,2,2-Tetrachloroethane	ND	ug/m3	88	8.2	EPA-TO-15	ND	A01	1
Tetrachloroethene	ND	ug/m3	88	8.8	EPA-TO-15	ND	A01	1
1,1,1,2-Tetrafluoroethane	ND	ug/m3	88	12	EPA-TO-15	ND	A01	1
Tetrahydrofuran	ND	ug/m3	35	4.7	EPA-TO-15	ND	A01	1
Toluene	ND	ug/m3	35	4.7	EPA-TO-15	ND	A01	1
1,2,4-Trichlorobenzene	ND	ug/m3	180	14	EPA-TO-15	ND	A01	1
1,1,1-Trichloroethane	ND	ug/m3	88	6.8	EPA-TO-15	ND	A01	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-02 | **Client Sample Name:** SV-2, 10/19/2021 11:46:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
1,1,2-Trichloroethane	ND	ug/m3	88	11	EPA-TO-15	ND	A01	1
Trichloroethene	ND	ug/m3	88	9.4	EPA-TO-15	ND	A01	1
Trichlorofluoromethane	ND	ug/m3	88	8.2	EPA-TO-15	ND	A01	1
1,2,3-Trichloropropane	ND	ug/m3	88	8.4	EPA-TO-15	ND	A01	1
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	ug/m3	88	9.6	EPA-TO-15	ND	A01	1
1,2,4-Trimethylbenzene	ND	ug/m3	88	7.0	EPA-TO-15	ND	A01	1
1,3,5-Trimethylbenzene	ND	ug/m3	88	7.0	EPA-TO-15	ND	A01	1
Vinyl acetate	ND	ug/m3	35	5.8	EPA-TO-15	ND	A01	1
Vinyl bromide	ND	ug/m3	88	5.6	EPA-TO-15	ND	A01	1
Vinyl chloride	ND	ug/m3	35	6.8	EPA-TO-15	ND	A01	1
p- & m-Xylenes	ND	ug/m3	88	11	EPA-TO-15	ND	A01	1
o-Xylene	ND	ug/m3	88	5.2	EPA-TO-15	ND	A01	1
Total Xylenes	ND	ug/m3	180	16	EPA-TO-15	ND	A01	1
Total Petroleum Hydrocarbons	**910**	**ug/m3**	**3500**	**370**	**EPA-TO-15**	ND	**J,A01**	1
4-Bromofluorobenzene (Surrogate)	96.2	%	70 - 130 (LCL - UCL)		EPA-TO-15			1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-TO-15	10/22/21 10:08	10/23/21 16:24	BEP	MS-A1	17.500	B123008	EPA TO-15

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-03 | **Client Sample Name:** SV-3, 10/19/2021 11:59:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
Acetone	**160**	**ug/m3**	**88**	**7.6**	**EPA-TO-15**	ND	**A01**	1
Acrylonitrile	ND	ug/m3	35	4.8	EPA-TO-15	ND	A01	1
Allyl chloride	ND	ug/m3	35	4.9	EPA-TO-15	ND	A01	1
t-Amyl Methyl ether	ND	ug/m3	88	5.5	EPA-TO-15	ND	A01	1
Benzene	ND	ug/m3	35	3.7	EPA-TO-15	ND	A01	1
Benzyl chloride	ND	ug/m3	180	4.6	EPA-TO-15	ND	A01	1
Bromodichloromethane	ND	ug/m3	88	7.9	EPA-TO-15	ND	A01	1
Bromoform	ND	ug/m3	180	15	EPA-TO-15	ND	A01	1
Bromomethane	ND	ug/m3	35	8.3	EPA-TO-15	ND	A01	1
1,3-Butadiene	ND	ug/m3	35	3.9	EPA-TO-15	ND	A01	1
t-Butyl alcohol	ND	ug/m3	88	12	EPA-TO-15	ND	A01	1
Carbon disulfide	ND	ug/m3	35	3.3	EPA-TO-15	ND	A01	1
Carbon tetrachloride	ND	ug/m3	88	7.9	EPA-TO-15	ND	A01	1
Chlorobenzene	ND	ug/m3	88	7.0	EPA-TO-15	ND	A01	1
Chloroethane	ND	ug/m3	35	9.3	EPA-TO-15	ND	A01	1
Chloroform	ND	ug/m3	88	9.5	EPA-TO-15	ND	A01	1
Chloromethane	ND	ug/m3	35	3.7	EPA-TO-15	ND	A01	1
Cyclohexane	ND	ug/m3	35	6.7	EPA-TO-15	ND	A01	1
Dibromochloromethane	ND	ug/m3	88	7.6	EPA-TO-15	ND	A01	1
1,2-Dibromo-3-chloropropane	ND	ug/m3	88	30	EPA-TO-15	ND	A01	1
1,2-Dibromoethane	ND	ug/m3	88	10	EPA-TO-15	ND	A01	1
Dibromomethane	ND	ug/m3	88	10	EPA-TO-15	ND	A01	1
1,2-Dichlorobenzene	ND	ug/m3	88	8.8	EPA-TO-15	ND	A01	1
1,3-Dichlorobenzene	ND	ug/m3	88	5.5	EPA-TO-15	ND	A01	1
1,4-Dichlorobenzene	ND	ug/m3	88	8.8	EPA-TO-15	ND	A01	1
Dichlorodifluoromethane	ND	ug/m3	88	7.9	EPA-TO-15	ND	A01	1
1,1-Dichloroethane	ND	ug/m3	88	4.0	EPA-TO-15	ND	A01	1
1,2-Dichloroethane	ND	ug/m3	88	4.6	EPA-TO-15	ND	A01	1
1,1-Dichloroethene	ND	ug/m3	88	5.5	EPA-TO-15	ND	A01	1
cis-1,2-Dichloroethene	ND	ug/m3	35	5.6	EPA-TO-15	ND	A01	1
trans-1,2-Dichloroethene	ND	ug/m3	35	4.8	EPA-TO-15	ND	A01	1
1,2-Dichloropropane	ND	ug/m3	88	5.6	EPA-TO-15	ND	A01	1
cis-1,3-Dichloropropene	ND	ug/m3	88	5.3	EPA-TO-15	ND	A01	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-03 | **Client Sample Name:** SV-3, 10/19/2021 11:59:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
trans-1,3-Dichloropropene	ND	ug/m3	88	7.0	EPA-TO-15	ND	A01	1
1,2-Dichloro-1,1,2,2-tetrafluoroethane	ND	ug/m3	88	16	EPA-TO-15	ND	A01	1
1,1-Difluoroethane	ND	ug/m3	88	35	EPA-TO-15	ND	A01	1
Diisopropyl ether	ND	ug/m3	88	6.9	EPA-TO-15	ND	A01	1
1,4-Dioxane	ND	ug/m3	35	5.8	EPA-TO-15	ND	A01	1
Ethanol	**110**	**ug/m3**	**35**	**7.4**	**EPA-TO-15**	ND	**A01**	1
Ethyl acetate	ND	ug/m3	35	5.8	EPA-TO-15	ND	A01	1
Ethylbenzene	ND	ug/m3	88	5.6	EPA-TO-15	ND	A01	1
1-Ethyl-4-methylbenzene	ND	ug/m3	88	5.3	EPA-TO-15	ND	A01	1
Ethyl t-butyl ether	ND	ug/m3	88	5.8	EPA-TO-15	ND	A01	1
n-Heptane	ND	ug/m3	35	6.0	EPA-TO-15	ND	A01	1
Hexachlorobutadiene	ND	ug/m3	180	26	EPA-TO-15	ND	A01	1
Hexachloroethane	ND	ug/m3	35	13	EPA-TO-15	ND	A01	1
Hexane	ND	ug/m3	88	3.5	EPA-TO-15	ND	A01	1
2-Hexanone	ND	ug/m3	88	5.1	EPA-TO-15	ND	A01	1
Isooctane	ND	ug/m3	88	6.2	EPA-TO-15	ND	A01	1
Isopropyl alcohol	**23**	**ug/m3**	**35**	**5.6**	**EPA-TO-15**	ND	**J,A01**	1
Methylene chloride	ND	ug/m3	180	7.0	EPA-TO-15	ND	A01	1
Methyl ethyl ketone	**22**	**ug/m3**	**35**	**3.3**	**EPA-TO-15**	ND	**J,A01**	1
Methyl iodide	ND	ug/m3	180	10	EPA-TO-15	ND	A01	1
Methyl isobutyl ketone	ND	ug/m3	88	4.6	EPA-TO-15	ND	A01	1
Methyl t-butyl ether	ND	ug/m3	35	4.9	EPA-TO-15	ND	A01	1
Naphthalene	ND	ug/m3	350	25	EPA-TO-15	ND	A01	1
Propylene	**99**	**ug/m3**	**35**	**4.4**	**EPA-TO-15**	ND	**A01**	1
Styrene	ND	ug/m3	88	4.2	EPA-TO-15	ND	A01	1
1,1,1,2-Tetrachloroethane	ND	ug/m3	88	11	EPA-TO-15	ND	A01	1
1,1,2,2-Tetrachloroethane	ND	ug/m3	88	8.3	EPA-TO-15	ND	A01	1
Tetrachloroethene	ND	ug/m3	88	8.8	EPA-TO-15	ND	A01	1
1,1,1,2-Tetrafluoroethane	ND	ug/m3	88	12	EPA-TO-15	ND	A01	1
Tetrahydrofuran	ND	ug/m3	35	4.8	EPA-TO-15	ND	A01	1
Toluene	ND	ug/m3	35	4.8	EPA-TO-15	ND	A01	1
1,2,4-Trichlorobenzene	ND	ug/m3	180	14	EPA-TO-15	ND	A01	1
1,1,1-Trichloroethane	ND	ug/m3	88	6.9	EPA-TO-15	ND	A01	1

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

BCL Sample ID: 2132929-03 | **Client Sample Name:** SV-3, 10/19/2021 11:59:00AM, client

Constituent	Result	Units	PQL	MDL	Method	MB Bias	Lab Quals	Run #
1,1,2-Trichloroethane	ND	ug/m3	88	11	EPA-TO-15	ND	A01	1
Trichloroethene	ND	ug/m3	88	9.5	EPA-TO-15	ND	A01	1
Trichlorofluoromethane	ND	ug/m3	88	8.3	EPA-TO-15	ND	A01	1
1,2,3-Trichloropropane	ND	ug/m3	88	8.4	EPA-TO-15	ND	A01	1
1,1,2-Trichloro-1,2,2-trifluoroethane	ND	ug/m3	88	9.7	EPA-TO-15	ND	A01	1
1,2,4-Trimethylbenzene	ND	ug/m3	88	7.0	EPA-TO-15	ND	A01	1
1,3,5-Trimethylbenzene	ND	ug/m3	88	7.0	EPA-TO-15	ND	A01	1
Vinyl acetate	ND	ug/m3	35	5.8	EPA-TO-15	ND	A01	1
Vinyl bromide	ND	ug/m3	88	5.6	EPA-TO-15	ND	A01	1
Vinyl chloride	ND	ug/m3	35	6.9	EPA-TO-15	ND	A01	1
p- & m-Xylenes	ND	ug/m3	88	11	EPA-TO-15	ND	A01	1
o-Xylene	ND	ug/m3	88	5.3	EPA-TO-15	ND	A01	1
Total Xylenes	ND	ug/m3	180	16	EPA-TO-15	ND	A01	1
Total Petroleum Hydrocarbons	**1100**	**ug/m3**	**3500**	**370**	**EPA-TO-15**	ND	**J,A01**	1
4-Bromofluorobenzene (Surrogate)	97.9	%	70 - 130 (LCL - UCL)		EPA-TO-15			1

Run #	Method	Prep Date	Run Date/Time	Analyst	Instrument	Dilution	QC Batch ID	Prep Method
1	EPA-TO-15	10/22/21 10:08	10/23/21 16:53	BEP	MS-A1	17.600	B123008	EPA TO-15

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B123008						
Acetone	B123008-BLK1	ND	ug/m3	5.0	0.43	
Acrylonitrile	B123008-BLK1	ND	ug/m3	2.0	0.27	
Allyl chloride	B123008-BLK1	ND	ug/m3	2.0	0.28	
t-Amyl Methyl ether	B123008-BLK1	ND	ug/m3	5.0	0.31	
Benzene	B123008-BLK1	ND	ug/m3	2.0	0.21	
Benzyl chloride	B123008-BLK1	ND	ug/m3	10	0.26	
Bromodichloromethane	B123008-BLK1	ND	ug/m3	5.0	0.45	
Bromoform	B123008-BLK1	ND	ug/m3	10	0.86	
Bromomethane	B123008-BLK1	ND	ug/m3	2.0	0.47	
1,3-Butadiene	B123008-BLK1	ND	ug/m3	2.0	0.22	
t-Butyl alcohol	B123008-BLK1	ND	ug/m3	5.0	0.70	
Carbon disulfide	B123008-BLK1	ND	ug/m3	2.0	0.19	
Carbon tetrachloride	B123008-BLK1	ND	ug/m3	5.0	0.45	
Chlorobenzene	B123008-BLK1	ND	ug/m3	5.0	0.40	
Chloroethane	B123008-BLK1	ND	ug/m3	2.0	0.53	
Chloroform	B123008-BLK1	ND	ug/m3	5.0	0.54	
Chloromethane	B123008-BLK1	ND	ug/m3	2.0	0.21	
Cyclohexane	B123008-BLK1	ND	ug/m3	2.0	0.38	
Dibromochloromethane	B123008-BLK1	ND	ug/m3	5.0	0.43	
1,2-Dibromo-3-chloropropane	B123008-BLK1	ND	ug/m3	5.0	1.7	
1,2-Dibromoethane	B123008-BLK1	ND	ug/m3	5.0	0.58	
Dibromomethane	B123008-BLK1	ND	ug/m3	5.0	0.57	
1,2-Dichlorobenzene	B123008-BLK1	ND	ug/m3	5.0	0.50	
1,3-Dichlorobenzene	B123008-BLK1	ND	ug/m3	5.0	0.31	
1,4-Dichlorobenzene	B123008-BLK1	ND	ug/m3	5.0	0.50	
Dichlorodifluoromethane	B123008-BLK1	ND	ug/m3	5.0	0.45	
1,1-Dichloroethane	B123008-BLK1	ND	ug/m3	5.0	0.23	
1,2-Dichloroethane	B123008-BLK1	ND	ug/m3	5.0	0.26	
1,1-Dichloroethene	B123008-BLK1	ND	ug/m3	5.0	0.31	
cis-1,2-Dichloroethene	B123008-BLK1	ND	ug/m3	2.0	0.32	
trans-1,2-Dichloroethene	B123008-BLK1	ND	ug/m3	2.0	0.27	
1,2-Dichloropropane	B123008-BLK1	ND	ug/m3	5.0	0.32	
cis-1,3-Dichloropropene	B123008-BLK1	ND	ug/m3	5.0	0.30	
trans-1,3-Dichloropropene	B123008-BLK1	ND	ug/m3	5.0	0.40	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B123008						
1,2-Dichloro-1,1,2,2-tetrafluoroethane	B123008-BLK1	ND	ug/m3	5.0	0.91	
1,1-Difluoroethane	B123008-BLK1	ND	ug/m3	5.0	2.0	
Diisopropyl ether	B123008-BLK1	ND	ug/m3	5.0	0.39	
1,4-Dioxane	B123008-BLK1	ND	ug/m3	2.0	0.33	
Ethanol	B123008-BLK1	ND	ug/m3	2.0	0.42	
Ethyl acetate	B123008-BLK1	ND	ug/m3	2.0	0.33	
Ethylbenzene	B123008-BLK1	ND	ug/m3	5.0	0.32	
1-Ethyl-4-methylbenzene	B123008-BLK1	ND	ug/m3	5.0	0.30	
Ethyl t-butyl ether	B123008-BLK1	ND	ug/m3	5.0	0.33	
n-Heptane	B123008-BLK1	ND	ug/m3	2.0	0.34	
Hexachlorobutadiene	B123008-BLK1	ND	ug/m3	10	1.5	
Hexachloroethane	B123008-BLK1	ND	ug/m3	2.0	0.73	
Hexane	B123008-BLK1	ND	ug/m3	5.0	0.20	
2-Hexanone	B123008-BLK1	ND	ug/m3	5.0	0.29	
Isooctane	B123008-BLK1	ND	ug/m3	5.0	0.35	
Isopropyl alcohol	B123008-BLK1	ND	ug/m3	2.0	0.32	
Methylene chloride	B123008-BLK1	ND	ug/m3	10	0.40	
Methyl ethyl ketone	B123008-BLK1	ND	ug/m3	2.0	0.19	
Methyl iodide	B123008-BLK1	ND	ug/m3	10	0.58	
Methyl isobutyl ketone	B123008-BLK1	ND	ug/m3	5.0	0.26	
Methyl t-butyl ether	B123008-BLK1	ND	ug/m3	2.0	0.28	
Naphthalene	B123008-BLK1	ND	ug/m3	20	1.4	
Propylene	B123008-BLK1	ND	ug/m3	2.0	0.25	
Styrene	B123008-BLK1	ND	ug/m3	5.0	0.24	
1,1,1,2-Tetrachloroethane	B123008-BLK1	ND	ug/m3	5.0	0.61	
1,1,2,2-Tetrachloroethane	B123008-BLK1	ND	ug/m3	5.0	0.47	
Tetrachloroethene	B123008-BLK1	ND	ug/m3	5.0	0.50	
1,1,1,2-Tetrafluoroethane	B123008-BLK1	ND	ug/m3	5.0	0.67	
Tetrahydrofuran	B123008-BLK1	ND	ug/m3	2.0	0.27	
Toluene	B123008-BLK1	ND	ug/m3	2.0	0.27	
1,2,4-Trichlorobenzene	B123008-BLK1	ND	ug/m3	10	0.82	
1,1,1-Trichloroethane	B123008-BLK1	ND	ug/m3	5.0	0.39	
1,1,2-Trichloroethane	B123008-BLK1	ND	ug/m3	5.0	0.61	
Trichloroethene	B123008-BLK1	ND	ug/m3	5.0	0.54	

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

Quality Control Report - Method Blank Analysis

Constituent	QC Sample ID	MB Result	Units	PQL	MDL	Lab Quals
QC Batch ID: B123008						
Trichlorofluoromethane	B123008-BLK1	ND	ug/m3	5.0	0.47	
1,2,3-Trichloropropane	B123008-BLK1	ND	ug/m3	5.0	0.48	
1,1,2-Trichloro-1,2,2-trifluoroethane	B123008-BLK1	ND	ug/m3	5.0	0.55	
1,2,4-Trimethylbenzene	B123008-BLK1	ND	ug/m3	5.0	0.40	
1,3,5-Trimethylbenzene	B123008-BLK1	ND	ug/m3	5.0	0.40	
Vinyl acetate	B123008-BLK1	ND	ug/m3	2.0	0.33	
Vinyl bromide	B123008-BLK1	ND	ug/m3	5.0	0.32	
Vinyl chloride	B123008-BLK1	ND	ug/m3	2.0	0.39	
p- & m-Xylenes	B123008-BLK1	ND	ug/m3	5.0	0.61	
o-Xylene	B123008-BLK1	ND	ug/m3	5.0	0.30	
Total Xylenes	B123008-BLK1	ND	ug/m3	10	0.91	
Total Petroleum Hydrocarbons	B123008-BLK1	ND	ug/m3	200	21	
4-Bromofluorobenzene (Surrogate)	**B123008-BLK1**	**94.5**	%	**70 - 130 (LCL - UCL)**		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Volatile Organic Compounds by GC/MS (EPA Method TO-15 at STP)

Quality Control Report - Laboratory Control Sample

Constituent	QC Sample ID	Type	Result	Spike Level	Units	Percent Recovery	RPD	Control Limits Percent Recovery	Control Limits RPD	Lab Quals
QC Batch ID: B123008										
Benzene	B123008-BS1	LCS	17.725	15.974	ug/m3	111		70 - 130		
	B123008-BSD1	LCSD	17.242	15.974	ug/m3	108	2.8	70 - 130	30	
Chloroform	B123008-BS1	LCS	26.717	24.413	ug/m3	109		70 - 130		
	B123008-BSD1	LCSD	26.258	24.413	ug/m3	108	1.7	70 - 130	30	
Ethylbenzene	B123008-BS1	LCS	24.594	21.711	ug/m3	113		70 - 130		
	B123008-BSD1	LCSD	24.411	21.711	ug/m3	112	0.7	70 - 130	30	
Tetrachloroethene	B123008-BS1	LCS	34.652	33.913	ug/m3	102		70 - 130		
	B123008-BSD1	LCSD	34.401	33.913	ug/m3	101	0.7	70 - 130	30	
Toluene	B123008-BS1	LCS	20.123	18.842	ug/m3	107		70 - 130		
	B123008-BSD1	LCSD	20.297	18.842	ug/m3	108	0.9	70 - 130	30	
Trichloroethene	B123008-BS1	LCS	27.551	26.869	ug/m3	103		70 - 130		
	B123008-BSD1	LCSD	27.481	26.869	ug/m3	102	0.3	70 - 130	30	
Trichlorofluoromethane	B123008-BS1	LCS	29.912	28.092	ug/m3	106		70 - 130		
	B123008-BSD1	LCSD	29.811	28.092	ug/m3	106	0.3	70 - 130	30	
1,1,2-Trichloro-1,2,2-trifluoroethane	B123008-BS1	LCS	41.131	38.318	ug/m3	107		70 - 130		
	B123008-BSD1	LCSD	40.226	38.318	ug/m3	105	2.2	70 - 130	30	
Vinyl chloride	B123008-BS1	LCS	14.202	12.781	ug/m3	111		70 - 130		
	B123008-BSD1	LCSD	14.603	12.781	ug/m3	114	2.8	70 - 130	30	
p- & m-Xylenes	B123008-BS1	LCS	46.556	43.421	ug/m3	107		70 - 130		
	B123008-BSD1	LCSD	46.574	43.421	ug/m3	107	0.0	70 - 130	30	
o-Xylene	B123008-BS1	LCS	23.100	21.711	ug/m3	106		70 - 130		
	B123008-BSD1	LCSD	23.443	21.711	ug/m3	108	1.5	70 - 130	30	
Total Xylenes	B123008-BS1	LCS	69.656	65.132	ug/m3	107		70 - 130		
	B123008-BSD1	LCSD	70.017	65.132	ug/m3	108	0.5	70 - 130	30	
4-Bromofluorobenzene (Surrogate)	B123008-BS1	LCS	77.0	71.6	ug/m3	108		70 - 130		
	B123008-BSD1	LCSD	76.9	71.6	ug/m3	107	0.1	70 - 130		

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

Environmental Investigation Services
316 Mid Valley Ctr #313
Carmel, CA 93923

Reported: 10/26/2021 15:07
Project: Air Samples (No EDF)
Project Number: 2103-02 Rich Avenue
Project Manager: Lawrence Bush

Notes And Definitions

J	Estimated Value (CLP Flag)
MDL	Method Detection Limit
ND	Analyte Not Detected
PQL	Practical Quantitation Limit
A01	Detection and quantitation limits are raised due to sample dilution.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.
All results listed in this report are for the exclusive use of the submitting party. BC Laboratories, Inc. assumes no responsibility for report alteration, separation, detachment or third party interpretation.

CORNERSTONE EARTH GROUP

Date:	June 7, 2022
Project No.:	118-135-1
Prepared For:	Mr. Tyler Rogers **DAVID J. POWERS & ASSOCIATES, INC.** 1736 Franklin Street, Suite 400 Oakland, CA 94612
Re:	Environmental Document Review 918 Rich Avenue Mountain View, California

Dear Mr. Rogers:

Per your request, Cornerstone Earth Group, Inc. (Cornerstone) is pleased to present this letter summarizing our review of the provided environmental reports for 918 Rich Avenue in Mountain View, California (Site). This letter was prepared for David J. Powers & Associates in accordance with our January 24, 2022, agreement.

Project Background

We understand that David J. Powers is providing California Environmental Quality Act (CEQA) support to redevelop the approximately 0.72-acre Site. The proposed residential building would be 59,060 square feet, four-stories tall (up to 53½ feet) and include one-level of subterranean parking. The project proposes 29 units: seven residential units on the first, second, and fourth floors, and eight residential units on the third floor. Eight of the residential units would be one-bedrooms condos, while the remaining units would be two-bedrooms condos. Each unit would have a small private patio ranging from approximately 60 to 474 square feet in size. In addition, approximately 17,811 square feet of common amenity space would be provided in the form of an entry plaza and rooftop deck.

The Site currently is undeveloped and covered with wood mulch and several moderately sized trees exist along the perimeter the parcel. The parcel is surrounded by an approximately 8-foot-tall wood fence on all sides, except for the Rich Avenue entrance, which has a chain link fence. The Site is accesses via a gate off the Rich Avenue frontage.

Documents Reviewed

This letter briefly summarizes selected information obtained from the following reports:

- Environmental Investigation Services, Inc. (EIS). February 16, 2020[sic][1]. *Phase I Environmental Site Assessment, 918 Rich Avenue, Mountain View, California*
- Environmental Investigation Services, Inc. (EIS). November 3, 2021. *Phase II Limited Subsurface Investigation Report, 918 Rich Avenue, Mountain View, California*

For complete details, please refer directly to the original reports.

[1] The Phase I report was completed in February 2021 based dates referenced in the report and as stated in the 2021 Subsurface Investigation Report.

Site History

Based on the information reviewed, the Site consisted of undeveloped pastureland during the 1930s. By 1948 a small structure was present on the eastern portion of the Site. A search of Mountain View Building Department records by Cornerstone identified permits dated in 2000 for the demolition of an approximately 300 square foot barn and a storage shed. The Site subsequently has remained as undeveloped land. EIS (2020) noted that a 2018 aerial photograph obtained from Google Earth shows the Site in use as an apparent construction storage yard with storage containers and soil stockpiles located on the northwestern portion of the Site. Occupants of adjoining properties were noted to include a Chevron gasoline station (northwestern adjoining property, 1969-1972)[2] and Blue Bird Dry Cleaners (northwestern adjoining property, 1996 to present).

EIS (2020) identified the presence of undocumented soil stockpiles as a potential environmental concern. The adjoining dry cleaning and gasoline station businesses were identified as a potential vapor encroachment concern. ESI noted, however, that no records of leaks, spills, or unauthorized releases were identified at these businesses.

Soil and Soil Vapor Sampling

EIS conducted a subsurface investigation in 2021 to evaluate potential impacts to soil quality from the prior on-Site stockpiles, and to evaluate if the adjacent dry cleaning business and former nearby gasoline station had impacted soil vapor quality.

Six soil samples were collected from three borings located in the vicinity of the former soil stockpiles that were advanced to a depth of approximately 2½ feet. Selected samples were analyzed for total petroleum hydrocarbons (TPH) as gasoline, diesel, and motor oil, volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), organochlorine pesticides (OCPs), polychlorinated biphenyls (PCBs), Cam-17 metals, asbestos, and pH.

Soil vapor samples were collected form three temporary approximately 5½ foot deep soil vapor wells (SV-1 through SV-3). The soil vapor samples were analyzed for TPH as gasoline and VOCs.

Soil Quality

Detected concentrations of petroleum hydrocarbons, OCPs and PCBs in the soil samples did not exceed the Water Board's residential environmental screening levels (ESLs[3]). No VOCs, SVOCs or asbestos were detected in the soil samples. Cobalt was detected in soil at up to 24 mg/kg, which marginally exceeds the residential ESL of 23 mg/kg. Nickel was detected in soil at up to 87 mg/kg, which marginally exceeds the construction worker ESL of 86 mg/kg. Detected arsenic concentrations (up to 4.2 mg/kg) also were above its ESLs.

[2] Based on Cornerstone's review of the historical aerial photographs, the gasoline station did not border the Site, but was located approximately 175 feet to the northwest, fronting El Monte Avenue.

[3] Environmental Screening Levels (ESLs) established by the Water Board (January 2019) are used to screen sites for potential human health concerns where releases of chemicals have occurred. These screening levels are risk-based concentrations derived from standardized equations combining exposure information assumptions with toxicity data. Under most circumstances, the presence of a chemical at concentrations below the corresponding screening level can be assumed not to pose a significant health risk.

Soil Vapor Quality

Benzene was detected in one of the three soil vapor samples at a concentration of 20 µg/m^3, which exceeds the residential ESL of 2.3 µg/m^3. EIS stated that this finding represents a potential environmental concern and indicated that following the conclusion of Site redevelopment activities, confirmation indoor and outdoor air sampling may be warranted. VOCs typically associated with dry cleaning activities (*e.g.*, tetrachloroethene [PCE]) were not detected in soil vapor.

Conclusions and Recommendations

Based on the information obtained during this study, Cornerstone concludes and recommends the following:

- The reported soil sampling data indicates that soil quality at the Site was not significantly impacted by the former undocumented soil stockpiles. Although concentrations of cobalt, nickel and arsenic were noted to exceed established ESLs, the reported concentrations appear typical of natural background/ambient concentrations[4]. Naturally occurring background concentrations of these metals, amongst others, in soil often exceed their respective screening levels. Cal/EPA generally does not require cleanup of soil to below background concentrations.

- Benzene was detected in one of the three soil vapor samples at a concentration above its residential ESL. Based on the Site history, benzene in soil vapor does not appear to be the result of a specific on-Site spill or release. Benzene is naturally occurring and can be found in ambient air, water and soil; it is also found in the environment due to human activities, especially in urban environments. Based on our experience, benzene often is sporadically detected in shallow soil vapor samples at properties even though a source is not apparent; these detections could, in part, be associated with ambient air conditions in an urban environment.

  Petroleum hydrocarbons and related VOCs (*i.e.*, benzene, toluene, ethylbenzene, and xylenes) readily biodegrade under aerobic conditions. The Water Board's 2019 ESL User's Guide indicates the published ESLs for petroleum constituents do not account for bio-attenuation and therefore can be overly conservative if bio-attenuation is adequately reducing petroleum vapor concentrations. Furthermore, the planned residential units will be constructed on top of a below grade/ventilated parking structure, which significantly reduces the potential for vapor intrusion.

Based on the above, it is unlikely that benzene in soil vapor would result in a significant adverse impact to the planned use of the Site.

---

[4] Bradford et.al. March 1996. *Background Concentrations of Trace and Major Elements in California Soils*. (reported background concentration ranges: cobalt 2.7-46.9 mg/kg; nickel 9-509 mg/kg).

Duverge, Dylan Jacques. December 2011. *Establishing Background Arsenic in Soil of the Urbanized San Francisco Bay Region.* (concluded that the mean and upper estimate [the 99th percentile] for background arsenic levels in the San Francisco Bay Region are 4.61 mg/kg and 11 mg/kg, respectively)


Limitations

Cornerstone performed this investigation to support David J. Powers & Associates in the evaluation of the referenced Site. Conclusions presented in this letter are based on limited, readily available information. This letter, an instrument of professional service, was prepared for the sole use of David J. Powers & Associates and may not be reproduced or distributed without written authorization from Cornerstone. It is valid for 180 days. Cornerstone makes no warranty, expressed or implied, except that our services have been performed in accordance with the environmental principles generally accepted at this time and location.

We thank you for this opportunity to work with you on this important project. Should you have any questions, please contact us at your convenience.

Sincerely,

Cornerstone Earth Group, Inc.



Ron L. Helm, C.E.G.
Senior Principal Geologist