
Phase I Environmental Site Assessment
7410 Waite Drive
La Mesa, California



Prepared For:
Helix Environmental Planning Inc.
7578 El Cajon Boulevard
La Mesa, California 91942

Prepared By:
The Bodhi Group, Inc.

May 2023
Project No. 9152001

THE BODHI GROUP
INNOVATING | SUSTAINING | SOLVING

May 9, 2023
Project No. 9152001

Ms. Erin Gustafson, AICP
Environmental Project Manager II
Helix Environmental Planning Inc.
7578 El Cajon Boulevard
La Mesa, California 91942

Subject: Phase I Environmental Site Assessment
7410 Waite Drive
La Mesa, California

Dear Ms. Gustafson,

We are pleased to submit this Phase I Environmental Site Assessment for the property at 7410 Waite Drive in La Mesa, California. This Report evaluates the presence of hazardous materials and provides recommendations based on the findings for the planned City of La Mesa public park on this property.

Respectfully submitted,

THE BODHI GROUP, INC.

Sree Gopinath, P.E.
Principal Engineer

REGISTERED PROFESSIONAL ENGINEER
SREEKUMAR GOPINATH
NO. C057987
EXP. 06/30/2024
CIVIL
STATE OF CALIFORNIA

1076 Broadway, Suite B • El Cajon • California • 92021 • Phone (858) 513-1469 • Fax (858) 513-1609

Email info@thebodhigroup.com • Website www.thebodhigroup.com

TABLE OF CONTENTS

Page

EXECUTIVE SUMMARY 1

1. INTRODUCTION 3
   - 1.1. Purpose 3
   - 1.2. Scope of Services 3
   - 1.3. Significant Assumptions 4
   - 1.4. Limitations and Exceptions 4
   - 1.5. Special Terms and Conditions 5
   - 1.6. User Reliance 5

2. SITE DESCRIPTION 6
   - 2.1. Location and Description 6
   - 2.2. Site and Vicinity General Characteristics 6
   - 2.3. Current Use of the Site 6
   - 2.4. Current Uses of Adjoining Properties 6

3. USER-PROVIDED INFORMATION 7
   - 3.1. Title Records 7
   - 3.2. Environmental Liens or Activity and Use Limitations 7
   - 3.3. Specialized Knowledge 7
   - 3.4. Commonly Known or Reasonably Ascertainable Information 7
   - 3.5. Valuation Reduction for Environmental Issues 7
   - 3.6. Owner, Property Manager, and Occupant Information 8
   - 3.7. Reason for Performing Phase I ESA 8

4. RECORDS REVIEW 9
   - 4.1. Standard Environmental Record Sources 9
     - 4.1.1. Subject Site 11
     - 4.1.2. Adjacent Properties Listed in the EDR Report 12
     - 4.1.3. Non-Geocoded (Unmapped) Listings 14
   - 4.2. Regulatory Files Search 14
     - 4.2.1. County of San Diego Department of Environmental Health 15
     - 4.2.2. San Diego Regional Water Quality Control Board 15
     - 4.2.3. California Department of Toxic Substances Control 15
     - 4.2.4. California Department of Resources Recycling and Recovery 15
   - 4.3. Physical Setting Sources 15
     - 4.3.1. Topography 15
     - 4.3.2. Site Geology 15
     - 4.3.3. Surface Waters 15
     - 4.3.4. Groundwater 16
   - 4.4. Historical Use Information on the Site and Adjoining Properties 16
     - 4.4.1. Sanborn Fire Insurance Maps 16
     - 4.4.2. Historical Aerial Photographs 16
     - 4.4.3. Historical Topographic Maps 17
     - 4.4.4. Reverse City Directories 17
     - 4.4.5. Building Department Records 17

5. SITE RECONNAISSANCE 18

5.1. Methodology and Limiting Conditions 18
5.2. General Site Setting 18
5.3. Site Observations 18
6. CONCLUSIONS 23
6.1. Recognized Environmental Conditions 23
6.1.1. Former Underground Storage Tanks 23
6.1.2. Historical Operations as a Road Station 23
6.2. De Minimis Conditions 24
7. RECOMMENDATIONS 25
8. DEVIATIONS/DATA GAPS 26
9. REFERENCES 27
10. SIGNATURE AND QUALIFICATIONS 28
11. LIMITATIONS 29

Figures

Figure 1 – Site Location Map
Figure 2 – Site Plan

Tables

Table 1 – Current Uses of Adjoining Properties
Table 2 – Assessor's Parcel Number and Ownership
Table 3 – Standard Environmental Databases
Table 4 – Adjacent Property EDR Listings
Table 5 – On-Site Observations

Appendices

Appendix A – Site Photographs
Appendix B – Environmental Database Report

EXECUTIVE SUMMARY

The Site, with an address of 7410 Waite Drive in La Mesa, California consists of 1 parcel, totaling approximately 3 acres. The Site is owned by the City of La Mesa; the San Diego County Tax Assessor's Parcel Number is 474-500-15-00. The Site is located at the northwest corner of the intersection of Waite Drive and Murray Hill Road near State Route 94. The Site was historically used as the San Diego County Lemon Grove Road Station from the early 1900s until 1974. All former structures related to the Road Station were removed from the Site in the mid-1990s. The Site is currently unoccupied. The City of La Mesa is planning to develop the Site as a public park.

A review of a 2012 Phase I Environmental Site Assessment (ESA) and research done for this ESA have identified Site conditions listed below.

- In 1994, two underground storage tanks (USTs) and one fuel dispenser island were removed from the Site. Soils impacted with petroleum hydrocarbons were discovered during the UST removal. The San Diego County Department of Environmental Health (DEH) opened an unauthorized release case (Case #H04820-001). Soil and groundwater investigations and remediation were completed at the site between June 2000 and January 2011. In a No Further Action (NFA) letter dated December 1, 2011, the DEH stated that case oversight had been completed based on the commercial use designation of the property, and that corrective action should be reviewed if the land use changes.
- The Site was listed in 16 of the databases a total of 24 times in the search reported in the Environmental Database Report (EDR). None of the adjacent properties were reported in the EDR Report.
- A review of historical aerial photographs, historical topographic maps, reverse city directories, and Sanborn© fire insurance maps indicates that the Site was occupied with structures as early as 1944. The structures remained in place until 1994. The surrounding areas were historically vacant prior to the early 1940s. The area to the south of the site was developed with residential housing in the 1940s. The area to the west and northwest of the site was developed with residential housing in the 1960s. The area to the east of the Site was developed with residential housing beginning in 2005.

During a recent Site reconnaissance, the features listed below were noted at the Site.

- Two small concrete pads are located along the southern boundary of the Site.
- Three concrete pads of varying sizes are located along the western boundary of the Site.
- One large, rectangular concrete pad is located in the center/southern porting of the Site. This pad contains the remnants of a hydraulic lift.
- One concrete structure, previously referred to as a loading dock (Dudek, 2012). Based on the dimensions and shape of the structure, and the previous use of the Site, The Bodhi Group concluded that this structure was likely used as a maintenance/service bay for vehicles and small equipment.
- The Site is partially covered by degraded asphalt.
- There is a 10" diameter PVC pipe installed vertically into the ground. This pipe contains a 2" PVC riser inside of it. Based on the review of previous Site maps, these pipes are remnants of a previous fire hose riser.

Based on a review of previous investigations and research conducted for this ESA, several Recognized Environmental Conditions (RECs) were identified for this Project and are listed below.

- Construction work may encounter contamination from the former USTs and potentially expose construction workers and the public. Excavated soil and extracted groundwater from construction

dewatering impacted by releases from the former USTs may be considered a waste and will require special handling and proper disposal.

- Construction work may encounter contamination from historical use of the Site as a road station (i.e., vehicle maintenance, storage of materials contaminated with waste oil, and releases of chemicals from the hydraulic lift and former transformers). Similar to releases from the USTs, there could be potential exposure to workers and the public. Wastes generated from earthwork will require special handling and disposal.

Recommendations to address these RECs are listed below.

- Preparation and implementation of health and safety plans that are protective of workers and the public during construction.
- Preparation and implementation of Soil and Groundwater Management Plans that will guide the identification of contaminated materials during construction, and their proper handling and disposal in accordance with federal and state regulations.
- The Soil Management Plan may include representative sampling of soil prior to construction to evaluate if chemicals-of-concern are present in the surface and shallow soil at concentrations that may present a risk to the future use of the Site as a public park and if contamination may be encountered during construction that requires special handling and disposal.
- Enrolling the Site in the DEH Voluntary Assistance Program for regulatory oversight of the preparation and implementation of the plans listed above in order to achieve regulatory closure of the RECs identified in this ESA and reduce liability to the City of La Mesa.

1. INTRODUCTION

The Bodhi Group, Inc. (Bodhi Group) has prepared this Phase I Environmental Site Assessment (ESA) for the City of La Mesa's future public park on an approximately 3-acre parcel at 7410 Waite Drive in the City of La Mesa, San Diego County (Site). The San Diego County Tax Assessor's Parcel Number (APN) for the Site is 474-500-15-00 and is located at the northwest corner of the intersection of Waite Drive and Murray Hill Road (Figures 1 and 2).

The City of La Mesa had previously commissioned a Phase I ESA of the Site in 2012 (Dudek, 2012). The Bodhi Group, Inc. was subcontracted by Helix Environmental Planning, Inc. (Helix, "client") on behalf of the City of La Mesa to prepare this Phase I ESA as an update to the previous 2012 ESA.

1.1. Purpose

The purpose of this Phase I ESA is to review the 2012 ESA and to verify or update Recognized Environmental Conditions (RECs) that may potentially impact the Project. In accordance with the ASTM International (ASTM) "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process," Standard Practice E1527-13, RECs are defined as "the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment." De minimis conditions (DMCs) are not RECs as they do not present a threat to human health or the environment and generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. DMCs may potentially identify requirements that require a safety plan, worker and community notification, and construction measures to mitigate potential risks to human health and the environment.

1.2. Scope of Services

The following services were provided for this assessment:

- Review the 2012 Phase I ESA and verify whether the RECs identified in that ESA continue to be valid and if there are other RECs that need to be identified.
- Review of physical setting and background information for the Site (e.g., topographic and geologic maps).
- Site reconnaissance to document potential hazardous materials handling, storage, and disposal practices, areas of possibly contaminated surficial soil or surface water, possible sources of polychlorinated biphenyls (PCBs), underground and aboveground storage tanks (USTs and ASTs, respectively), and other possible sources of contamination.
- Review of federal, state, tribal, and local regulatory agency databases for the Site, the immediately adjacent parcels, and for properties located within a specified radius of the Site. The databases document locations of known hazardous waste sites, landfills, leaking underground storage tanks (LUSTs), permitted facilities that utilize USTs, and permitted facilities that use, store, or dispose of hazardous materials and wastes.
- Review of reasonably ascertainable local regulatory agency files for the Site, as applicable.
- Review of historical information for the Site and the immediately adjacent parcels, such as Sanborn fire insurance maps, historical aerial photographs, reverse street directories, and building permit records, as available and reasonably ascertainable.
- A search for engineering or institutional controls associated with the Site.

- A search of historical RECs for unrestricted residential use standards.
- Evaluate the potential for vapor intrusion (VI) of gas phase volatile organic compounds (VOCs) into structures, as applicable.
- Prepare this Phase I ESA report, summarizing findings and providing opinions and conclusions related to the previous 2012 Phase I ESA and whether previously identified RECs should be updated or if there are new RECs for the Site.

1.3. Significant Assumptions

This Phase I ESA was conducted in accordance with ASTM guidelines for the performance of such assessment and does not constitute an exhaustive assessment of the Site. No other warranties either expressed or implied, are made. The evaluations, analyses, and opinions contained herein should not be taken as representations regarding subsurface conditions or the actual value of the Site. Subsurface conditions may differ from the conditions implied by the surficial observations and can only be reliably evaluated through comprehensive Site investigation, including the collection and analyses of subsurface media samples.

Documentation and data provided by the client, other interested third parties, or from the public domain, and referred to in the preparation of this assessment, are assumed to be complete and correct and have been used and referenced with the understanding that the Bodhi Group assumes no responsibility or liability for their accuracy. The conclusions contained herein are based upon such information and documentation and on our observations of Site conditions, as they existed on the date of the Site inspection. Because Site conditions may change significantly over a short period of time and additional data may become available, data reported, and conclusions drawn in this report are limited to current conditions and may not be relied upon on a significantly later date or if changes occurred at the Site.

1.4. Limitations and Exceptions

Reasonable efforts have been made during this assessment to uncover evidence of features of potential environmental concern that may potentially impact the Project. “Reasonable efforts” are limited to information gained from visual observation of unobstructed areas, recorded database information held in public record, and available information gathered from interviews. Such methods may not identify subsurface equipment that may have been hidden from view due to paving, construction or debris pile storage, or incorrect/incomplete information from sources.

This assessment was not an environmental compliance audit. While some observations and discussion in this report may address conditions and/or operations that may be regulated, the regulatory compliance of those conditions and/or operations is outside the scope of this investigation. Nothing in this report constitutes a legal opinion or legal advice. For information regarding specific individual or organizational liability, the Bodhi Group recommends consultation with independent legal counsel.

This ESA does not address non-scope ASTM considerations including, but not limited to: asbestos containing materials, radon, lead in drinking water, wetlands, protected environments and habitat, threatened or endangered species, industrial hygiene concerns, human health risk assessment, indoor air quality, high voltage power lines, geotechnical conditions, cultural and historical resources, health and safety, and mold.

1.5. Special Terms and Conditions

No special terms and conditions between the Bodhi Group and the client pertinent to the findings of this ESA or methodology used to complete this assessment are noted. The Bodhi Group does not have a financial interest in the Site.

1.6. User Reliance

This report was prepared for use solely and exclusively by the client and the City of La Mesa, California. The report is not for the use or benefit of, nor may it be relied upon by, any other person or entity for any purpose without the advance written consent of the Bodhi Group. The Bodhi Group makes no representation to any third party except that it has used the degree of care and skill ordinarily exercised by a reasonable prudent environmental professional in the same community and in the same time frame given the same or similar facts and circumstances. No other use or disclosure is intended or authorized by the Bodhi Group. In the preparation of this ESA, the Bodhi Group has used the degree of care and skill ordinarily exercised by a reasonably prudent environmental professional in the same community and in the same time frame given the same or similar facts and circumstances. No other warranties are made to any third party, either expressed or implied.

2. SITE DESCRIPTION

This section describes the Site and its physical attributes.

2.1. Location and Description

The Site with the address of 7410 Waite Drive, La Mesa, California is comprised of a single parcel identified with APN 474-500-15-00 and is approximately 3-acres in size, located 0.1 mile north of State Route 94. The Site is located on the northwest corner of the intersection of Waite Drive and Murray Hill Road.

2.2. Site and Vicinity General Characteristics

According to the 2012 ESA (Dudek, 2012), the Site was historically used by the County of San Diego as the Lemon Grove Road Station from the 1910s until 1974. The Site has been vacant since 1974. All former structures related to the Road Station were removed from the Site in the mid-1990s.

The Site is bordered on all sides by chain-link fencing and retains some concrete pads and footings from previous structures. The Site is currently owned by the City of La Mesa. The City plans to develop the Site into a public park.

Surrounding and adjacent parcels are primarily developed as residential housing. There are a few parcels north and east of the Site that remain vacant. The use of adjacent properties at the time of this report is discussed in Section 2.4.

2.3. Current Use of the Site

On March 16, 2023, a representative of the Bodhi Group performed a visual inspection of the Site and adjoining properties. The Site, as previously noted, is currently vacant, but retains some concrete pads and evidence of its former use as a San Diego County Lemon Grove Road Station. (see photos in Appendix A).

2.4. Current Uses of Adjoining Properties

Adjacent properties and their current uses are described in the following table and are labeled on Figure 2. Photographs of the Site and adjacent properties are included in Appendix A.

Table 1 – Current Uses of Adjoining Properties

Direction	Adjoining Property Use
North	Open space and residential properties were located north of the Site.
South	Residential properties were located south of the Site.
East	Residential properties were located east of the Site.
West	Residential properties were located west of the Site.

3. USER-PROVIDED INFORMATION

The following sections summarize information obtained from the client.

3.1. Title Records

Title records were not reviewed for this assessment. Based on information provided by the client and verified by records from the County of San Diego Tax Assessor's office, the Site is owned by the City of La Mesa.

Table 2 – Assessor Parcel Number and Ownership

APN	Owner
474-500-15-00	City of La Mesa

3.2. Environmental Liens or Activity and Use Limitations

According to the 2012 ESA (Dudek, 2012), the City of La Mesa is not aware of environmental cleanup liens filed or recorded against the Site, or of activity and use limitations in place at the Site. Environmental lien and Activity and Use Limitations (AUL) databases were also researched as part of the Environmental Data Resources Inc. (EDR) Radius Report discussed in Section 4.1. No environmental liens or AULs were found for the Site or the immediately adjacent properties.

3.3. Specialized Knowledge

In 1994, two USTs and one fuel dispenser island were removed from the Site. Soils impacted with petroleum hydrocarbons were discovered during the UST removal prompting the San Diego County Department of Environmental Health (DEH) to initiate an unauthorized release case (Case #H04820-001). Soil and groundwater investigations and remediation were completed at the site between June 2000 and January 2011. Refer to Sections 4.1.1 and 5.3 of this report for further details of the soil, groundwater and vapor investigation and the remedial action completed.

In a No Further Action (NFA) letter dated December 1, 2011, the DEH stated that case oversight had been completed based on the commercial use designation of the property, and that corrective action should be reviewed if the land use changes.

In the 2012 ESA, the presence of a hydraulic lift and the remnants of a loading dock or maintenance/service bay were identified on the Site (Dudek, 2012). These items are discussed in further detail in Sections 4.1.1 and 5.3 of this report.

3.4. Commonly Known or Reasonably Ascertainable Information

According to the 2012 ESA, the City of La Mesa was not aware of commonly known or reasonably ascertainable information indicative of releases or threatened releases of hazardous wastes or materials at the Site.

3.5. Valuation Reduction for Environmental Issues

Monetary valuation was not performed for this assessment.

3.6. Owner, Property Manager, and Occupant Information

The Site parcel is currently vacant and is owned by the City of La Mesa. Table 2 above lists the ownership by APN.

3.7. Reason for Performing Phase I ESA

The Bodhi Group has been retained to conduct this Phase I ESA to identify RECs that may potentially impact the redevelopment of the Site as a municipal park.

4. RECORDS REVIEW

The following sections summarize records reviewed for the Site.

4.1. Standard Environmental Record Sources

The Bodhi Group obtained and reviewed an environmental database search conducted by EDR, dated February 2023 (EDR, 2023a-e). The environmental databases searched ("standard environmental record sources") and their corresponding search radii were equal to or greater than the minimum search distances specified by ASTM E1527-21 (ASTM, 2021). Properties within specific search radii and identified on environmental databases are listed in Table 3. Further details and descriptions of the databases reviewed by EDR are provided in the environmental database report in Appendix B.

Table 3 –Standard Environmental Databases

Database Name	Search Radius (Mile)	Number of Mapped Listings
FEDERAL DATABASES		
National Priority List (NPL)	1.0	0
Proposed NPL	1.0	0
NPL Liens	1.0	0
Delisted NPL	1.0	0
SEMS (Superfund Enterprise Management System; formerly Comprehensive Environmental Response Compensation and Liability Information System)	0.5	0
SEMS-ARCHIVE (Superfund Enterprise Management System Archive)	0.5	0
FEDERAL FACILITY (Federal Facility Site Information listing)	0.5	0
RCRA Corrective Action Sites (CORRACTS)	1.0	0
RCRA Treatment Storage and Disposal Facilities (TSDF)	0.5	0
RCRA – Large Quantity Generator (LQG)	0.25	2
RCRA – Small Quantity Generator (SQG)	0.25	3
RCRA – Very Small Quantity Generator (VSQG)	0.25	0
Federal Engineering Controls	0.5	0
Federal Institutional Controls	0.5	0
Land Use Control Information System (LUCIS)	0.5	0
Federal Emergency Response Notification System (ERNS)	Site	0

Table 3 –Standard Environmental Databases

Database Name	Search Radius (Mile)	Number of Mapped Listings
STATE/TRIBAL DATABASES		
State-and Tribal- equivalent NPL	1.0	0
State- and Tribal- hazardous waste facilities	1.0	5
State and Tribal Landfill and/or Solid Waste Disposal Sites/Recyclers	0.5	0
State and Tribal LUSTs	0.5	31
State Spills, Leaks, Investigation and Cleanup (SLIC)	0.5	17
San Diego County Site Assessment and Mitigation (SAM) Cases	0.5	18
Indian LUST	0.5	0
State and Tribal Registered UST	0.25	5
State and Tribal Registered ASTs	0.25	0
Drycleaners	0.25	0
Indian Voluntary Cleanup Sites (VCP)	0.5	0
State VCP	0.5	0
US Brownfields	0.5	0
Local Land Records – Liens	Site	0
Recycling Facilities in California Database (SWRCY)	0.5	1
San Diego County Hazardous Materials Management Division (HMMD)	0.001	1
California Environmental Reporting System (CERS)	Site	1
California Environmental Reporting System – Hazardous Waste Inventory (CERS HAZ WASTE)	0.25	8
Statewide Environmental Evaluation and Planning System (SWEEPS) UST	0.25	6
Hazardous Substance Storage Container Database (HIST UST)	0.25	5
California Environmental Reporting System – Tank Inventory (CERS TANKS)	0.25	3
RCRA NonGen / NLR	0.25	25

Table 3 –Standard Environmental Databases

Database Name	Search Radius (Mile)	Number of Mapped Listings
CalEPA Cortese List	0.50	17
CalEPA Historical Cortese List	0.50	12
Database of California Department of Toxic Substances Control manifests (HAZNET)	Site	3
EPA Facility Index System (FINDS)	Site	2
EPA Enforcement and Compliance Online (ECHO) database	Site	1
San Diego County Local Oversight Program (LOP)	Site	1
Database of California Department of Toxic Substances Control Hazardous Waste Tracking System (HWTS)	Site	3
Recovered Government Archive (RGA) LUST	Site	4
Listing of all Proposition 65 incidents reported to the California Regional Water Quality Control Board (Notify 65)	1.0	2

4.1.1. Subject Site

The Site is listed in the EDR Database Report in 16 of the databases a total of 24 times. The sixteen databases featuring the Site were SD Co. SAM, SD Co. HMMD, SD Co. LOP, SWEEPS UST, LUST, HIST UST, HIST LUST, RGA LUST (4 listings), HAZNET (2 listings), HWTS (3 listings), FINDS (2 listings), RCRA-SQG, ECHO, (2 listings), CORTESE, HIST CORTESE, and CERS. The site appears in these databases under various names, including “COUNTY OF SD – FLEET OPS LEM”, “SD CNTY GEN SVCS AUTO SVC”, “LEMON GROVE SERVICE STATION”, and “FLEET OPERATIONS LEMON GROVE”.

The earliest listing of the site (HAZNET, HWTS) in the database search is for the 1984, 1985 and 1986 disposal of 1.04 tons, 1.6 tons and 0.8 tons, respectively, of “waste oil and mixed oil”. The next database listings (HAZNET, HWTS) are for the 1991 disposal of waste that was categorized as “household waste”. The 1991 entries indicate that approximately 6.9 tons of a solid waste were transported to a transfer station for disposal, and approximately 0.07 tons of liquid were transported for treatment tank disposal.

The remaining database listings for the Site pertain to the existence and removal of one 8,000-gallon, single walled, unleaded fuel UST and one 1,000-gallon, single walled, diesel fuel UST used. Both USTs and one dispenser island were removed from the site on February 2, 1994. Previous reports available on the State Water Resources Control Board’s (SWRCB) Geotracker website noted that “the removed tanks appeared corroded, and that petroleum hydrocarbon odors and staining were observed in the excavation

for the gasoline tank. No odors or staining were observed in the excavation for the diesel tank" (Leighton, 2008). Based on the observed contamination, the DEH opened a Local Oversight Program (LOP) unauthorized release case for oversight of the assessment and remediation of the UST releases.

Between April 2000 and October 2007, site assessment activities were completed, including the installation of seven groundwater monitoring wells and two additional soil borings. To address the soil contamination, approximately 371 cubic yards of petroleum hydrocarbon impacted soil was excavated and removed from the Site in June 2007 for disposal at the Otay Landfill. Oxygen Release Compound® was added to the clean material used to backfill the excavation to continue treating residual hydrocarbons. Based on the results of the confirmation samples collected from the excavation bottom and sidewalls, the soil contamination was determined to be limited to the Site. The case summary in the EDR Database search noted that the consultant estimated that approximately 30 cubic yards of petroleum impacted soil remained at the Site in the area of the former dispensers (EDR, 2023a; Dudek, 2012).

Groundwater was monitored at the Site between June 2000 and January 2011 (SCS, 2011). Based on the results of these monitoring events, it was determined that the dissolved-phase plume of hydrocarbons was adequately defined with the leading edge of the plume extending approximately 50 feet south of the Site. The human health risk analysis concluded that the residual soil and groundwater contamination will not impact human health, the environment, or nearby sensitive receptors (SCS, 2011). The DEH concurred with this conclusion and closed the UST oversight case for the Site based on current site use and conditions (a commercial site without occupied buildings) on December 1, 2011 (DEH, 2011). The case closure report summary that accompanied the closure letter indicated that corrective action should be reviewed if the land use changes.

4.1.2. Adjacent Properties Listed in the EDR Report

The following table summarizes all properties were listed on the EDR Database Report less than 1/8 mile from the Site. Sites located between 1/8 and 1 mile from the Site that have open regulatory oversight or cleanup actions, or indications that they may pose a potential source of impact to the Site are also summarized in the following table.

Table 4 – Adjacent Property EDR Listings

Facility Name/Address	Distance/ Direction from Site	Database	Summary
Steve McElfresh/3743 Harris Street	<1/8 mile southwest	RCRA NonGen NLR	The database listing was last updated in January 2022. It indicates "not a generator, verified" and "no violations found". No further details were provided by the database.
Roberta Slater/3743 Harris Street	<1/8 mile southwest	RCRA NonGen NLR	The database listing was last updated in January 2022. It indicates "not a generator, verified" and "no violations found". No further details were provided by the database.
Bruce Baraw/3889 Harris Street	<1/8 mile north-northwest	RCRA NonGen NLR	The database listing was generated in February 2021. It indicates "not a generator, verified" and "no violations found". No further details were provided by the database.

Table 4 – Adjacent Property EDR Listings

Facility Name/Address	Distance/ Direction from Site	Database	Summary
Kevin Ferree/3775 Citrus Street	<1/8 mile west-southwest	RCRA NonGen NLR	The database listing was generated in September 2020. It indicates “not a generator, verified” and “no violations found”. No further details were provided by the database.
Diana Lauifi/3766 Citrus Street	<1/8 mile west-southwest	RCRA NonGen NLR	The database listing was generated in September 2019. It indicates “not a generator, verified” and “no violations found”. No further details were provided by the database.
Pedro&Maria Fajardo/3760 Citrus Street	<1/8 mile west-southwest	RCRA NonGen NLR	The database listing was generated in February 2020. It indicates “not a generator, verified” and “no violations found”. No further details were provided by the database.
Joan Sanchez/3736 Citrus Street	<1/8 mile west-southwest	RCRA NonGen NLR	The database listing was generated in September 2018. It indicates “not a generator, verified” and “no violations found”. No further details were provided by the database.
Family Health Center of San Diego/7580 North Avenue	1/8-1/4 mile south east	CPS-SLIC; CERS;	According to the database reports, this has an open San Diego County LOP site assessment (case number DEH2016-LSAM-000366). This property was formerly used as an auto-repair/mechanic facility. The Family Health Center of San Diego proposed to demolish the formerly used structures and redevelop the property as a parking lot. The case has an open Soil Management Plan in place from 2016 to manage any contaminated soils encountered during these activities. A preliminary soil investigation identified contaminants including Aroclor-1260 (PCBs; 1 sample), total petroleum hydrocarbons (2 samples), and elevated concentrations of barium, lead and arsenic.
USA Petroleum Company #246/7505 Broadway	1/4 – 1/2 mile south-southeast	LUST; HIST UST; HIST Cortese; San Diego Co. SAM; San Diego Co. HMMD; SWEEPS UST; Cortese; San Diego Co. LOP; CERS	This site is an active retail fueling station with an open San Diego County LOP investigation and remediation of an unauthorized petroleum hydrocarbon release that was reported in 1989 (Case #H03292-001). Remediation efforts at the site have included a dual phase extraction system, which began operation in May 2002. In the most recent report submitted for the site, (September 27, 2022), the consultant (Montrose Environmental) recommended regulatory case closure and the implementation of a “Post Closure Monitoring and Maintenance Plan”.

Table 4 – Adjacent Property EDR Listings

Facility Name/Address	Distance/ Direction from Site	Database	Summary
Tosco 76 #3699; 7593 Broadway	1/4 – 1/2 mile southeast	LUST, CPS-SLIC, SWEEPS UST, CERS	This site has a closed DEH LOP case for the cleanup of an unauthorized petroleum hydrocarbon release. The case was closed in 2002. In 2013, this site entered into the Voluntary Assistance Program (VAP, Case #DEH2013-LSAM-000175) for the review and approval of a liquid boot barrier to prevent the intrusion of petroleum hydrocarbon vapors into a proposed building. This case remains open with no new updates since 2013.
Palomar Cleaners; 7870 Broadway	1/2 – 1 mile east-southeast	RCRA-SQG; ENVIROSTOR; San Diego Co. SAM; CPS-SLIC, San Diego Co. HMMD; FINDS, ECHO, DRYCLEANERS EMI; HAZNET; CERS; HWTS	This property was a drycleaning business from the 1940s to 2016. Site assessments have identified that this property has been impacted by one or more releases of tetrachloroethene (PCE), which has affected soil and groundwater and has migrated offsite in a downgradient direction. “The impacted groundwater may pose a human health risk to building occupants on and offsite through the vapor intrusion pathway”. A Cleanup and Abatement Order No. R9-2019-0036 was issued on May 9, 2019. The most recent site assessment (2021) concluded that the groundwater gradient is carrying these contaminants to the south-southwest.
Sonka Trust Property; 3065 Lemon Grove Avenue	1/2 – 1 mile southeast	ENVIROSTOR; LUST; San Diego Co. SAM; CPS-SLIC; San Diego HMMD; Cortese; San Diego Co. LOP, CERS	This property is listed in the database as having an open San Diego Co. Voluntary Assistance Program case (#H38970-002). This site historically had a retail fueling station. During re-development activities, stained soils with petroleum hydrocarbon odors were discovered. The site was entered into the Voluntary Assistance Program in 2006. The site is currently in the public notification stage of the closure process.

None of the sites discussed in Table 4 present a REC for the Site based on one of more of the following factors: distance, relative location based on direction of groundwater flow (i.e., downgradient or crossgradient), and media affected.

4.1.3. Non-Geocoded (Unmapped) Listings

This portion of the regulatory database report includes properties for which regulatory agencies did not report sufficient address information to be plotted by EDR. There were no unmapped properties reported in the database search.

4.2. Regulatory Files Search

This section discusses findings from a review of State and Local regulatory agency files.

4.2.1. County of San Diego Department of Environmental Health

A search of the DEH public records returned numerous documents, including permit copies, work plans and technical reports related to the unauthorized petroleum release and cleanup efforts completed at the Site. Refer to Section 4.1.1 above for a summary of those efforts.

4.2.2. San Diego Regional Water Quality Control Board

A review of the SWRCB's Geotracker website indicated that the Site has a closed LUST case with the DEH LOP (Case #H04820-001). The website includes copies of reports, maps and laboratory analytical results generated during the site assessment and remediation activities. Refer to Section 4.1.1 above for a summary of the case. No adjacent properties were listed in the Geotracker database. All open cases within a 1-mile search radius of the Site were summarized in Table 4 in Section 4.1.2, above.

4.2.3. California Department of Toxic Substances Control

A review of the California Department of Toxic Substances Control (DTSC) Envirostor website did not identify Federal Superfund, State Response, Voluntary Cleanup, Evaluation, Corrective Action, Tiered Permit, or other types of sites regulated by DTSC at or near the Site.

4.2.4. California Department of Resources Recycling and Recovery

A review of California Department of Resources Recycling and Recovery (CalRecycle)'s Solid Waste Information System did not show any disposal sites mapped at or near the Site.

4.3. Physical Setting Sources

The following sections include discussions of topographic, geologic, and hydrogeologic conditions in the vicinity of the Site, based upon the referenced document review and/or our visual reconnaissance of the Site.

4.3.1. Topography

Based on a review of United States Geological Survey (USGS), 7.5-minute topographic series, National City, California quadrangle map, the approximate elevation at the Site is approximately 471 feet above mean sea level (USGS, 2018). The site slopes downward from the northeast towards the southwest.

4.3.2. Site Geology

Based on a review of the Geologic Map of the National City 7.5-minute Quadrangle and reports of previous site investigations, the Site is underlain by "decomposed and competent elements of igneous and metavolcanics that comprise the Santiago Peak Volcanics" (Leighton, 2008). During a 2009 site investigation, "fill soils were encountered at the Site at depths ranging from the surface to 12 ft bgs. Linda Vista Formation soils were found to underlie the fill soil and consist of primarily dense, fine to medium grained silty sand from approximately 5 to 21 feet bgs, which is then underlain by competent bedrock of the Santiago Peak Volcanics" (Leighton, 2009).

4.3.3. Surface Waters

Surface water bodies are not located on the Site. The nearest surface water body is the Chollas Reservoir, located approximately 1.5 miles west-southwest of the Site (Figure 1). Other surface water bodies located

near the Site are Lake Murray located approximately 2.5 miles north of the Site, and Sweetwater Reservoir located approximately 4.5 miles south-southeast of the Site.

4.3.4. Groundwater

According to the San Diego Regional Water Quality Control Board's Basin Plan Map, the Site is located within the Chollas Hydrologic Sub-Area (HSA) of the San Diego Mesa Hydrologic Area (HA) of the Pueblo San Diego Hydrologic Unit (HU). Groundwater in this HSA does not have any designated beneficial uses (Water Board, 1994).

Previous environmental investigations indicate that the depth to groundwater at the Site has ranged from 4 to 20 ft bgs (Dudek, 2012). Based on previous investigations, groundwater flow on the subject property is generally towards the south or southwest.

4.4. Historical Use Information on the Site and Adjoining Properties

The following sections summarize the results of our review of historical records for the Site and adjoining properties.

4.4.1. Sanborn Fire Insurance Maps

Sanborn® fire insurance maps were requested from EDR (EDR, 2023c). There is no map coverage for the Site and vicinity. EDR's Certified Sanborn Map Report is provided in Appendix B.

4.4.2. Historical Aerial Photographs

The Bodhi Group reviewed aerial photographs from 1949, 1953, 1964, 1966, 1970, 1979, 1985, 1989, 1994, 1995, 1996, 2002, 2005, 2009, 2012, 2016, and 2020 from EDR (EDR, 2023d) and Google Earth. The aerial photographs reviewed are included in Appendix B.

The 1949 photograph shows the Site developed with two rectangular structures located in the central to southern portion of the parcel. Two smaller structures are present on the western boundary of the parcel, along with what appear to be several smaller structures or staging areas for storage. There is also a structure located in the southeast corner of the Site. The Site is bounded to the south by Waite Drive and to the east by Murray Hill Road. The property to the north, east and west of the Site is undeveloped, and to the south is developed with residential structures.

In the 1953, 1964 and 1966 photographs, the Site appears relatively unchanged. The surrounding area has undergone substantial residential development to the north, south and west of the Site. In the 1964 photograph, State Route 94 has been developed approximately 0.1 mile south of the Site.

In the 1970 photograph, the northern of the two rectangular structures in the center of the parcel has been demolished. The surrounding areas to the north, west and south continue have continued to show residential and commercial expansion.

In the 1979 photograph, the rectangular structure in the center of the property remains, but the structures along the western boundary of the parcel and in the southeast corner of the parcel appear to have been removed.

In the 1985, 1989 and 1994 photographs, the Site remains relatively unchanged. The surrounding areas continue to experience residential and commercial expansion.

The Site is not fully mapped in the 1995 photograph. The 1996 and 2002 photographs are both color-infrared photographs. They both show that all structures and any vehicles and storage areas have been removed from the Site, although the concrete pads from the structures remain. The 2005 through 2020 photographs show the site as relatively unchanged. The residential housing tract to the east of the Site is under development in the 2005 photograph, and the surrounding area is relatively unchanged from the 2009 photograph though the 2020 photograph.

4.4.3. Historical Topographic Maps

The Bodhi Group reviewed historical topographic maps provided by EDR for the years 1903/1904 (composite map), 1930, 1942/1944 (composite map), 1947, 1953, 1967, 1975, 1991, 1994/1996 (composite map), 2012, 2015, and 2018 (EDR, 2023b). The 1903/1904 composite map shows the Site as vacant. There are no roads in the vicinity of the Site. The map does show roads and structures to the south-southeast of the Site in the City of Lemon Grove. The 1930 map shows the site in a similar condition with expanding development to the south of the Site. The 1942/1944 composite map shows five structures on the Site, as well as Waite Drive bordering the site to the south, and Murray Hill Road as a dirt road bordering the site to the east. The Site was in an unmapped portion of the 1947 map. The 1953, 1967 and 1975 maps are consistent with the aerial photograph review. The 1991 map does not show the presence of structures on the Site, which appeared to still be present in the aerial photo review as of the 1994 photograph. The 2012, 2015, and 2018 maps are consistent with the aerial photograph review. The topographic maps reviewed for this ESA are provided in Appendix B.

4.4.4. Reverse City Directories

EDR conducted a search of available city directory data for the Site and adjoining properties (EDR, 2023e). Addresses for Waite Drive were reviewed for years 1972 to 2020. The Site address does not appear with a phone number or other identifying information in any of the searches. The majority of listings in the surrounding area were residential. Site or surrounding property listings do not present an environmental concern at this time. A copy of the city directory abstract report is provided in Appendix B.

4.4.5. Building Department Records

Building department records were searched from the County of San Diego online database on March 21, 2023 for the Site parcel number. No records were returned for the search.

5. SITE RECONNAISSANCE

The objective of the Site reconnaissance was to obtain information indicating the likelihood of RECs that may potentially impact the Project. Ms. Natalie Krage of the Bodhi Group performed the Site reconnaissance on March 16, 2023. Photographic documentation is provided in Appendix A.

5.1. Methodology and Limiting Conditions

The Site reconnaissance consisted of walking on accessible portions of the Site and viewing adjacent properties and easements. There were no physical limitations during the Site reconnaissance.

5.2. General Site Setting

At the time of the Site reconnaissance, the Site was occupied by concrete pads and footings from demolished buildings, asphalt and dirt access ways and natural vegetation. It was bounded on all four sides by a chain-link fence (see photos in Appendix A).

5.3. Site Observations

The site reconnaissance observations identified two potential environmental concerns at the Site. A description of each concern is described as follows:

- Hydraulic Lift – The remnants of a hydraulic lift were observed in the eastern portion of the concrete pad from one of the former buildings on the Site. In 2011, Dudek performed a limited soil vapor investigation to evaluate VOC concentrations in soil vapor near the former USTs and the former buildings. No VOCs were detected in the samples collected in the vicinity of the former USTs. The soil vapor sample collected near the former hydraulic lift indicated concentrations of benzene and toluene in the soil vapor at concentrations of 0.12 µg/L and 2.2 µg/L, respectively. Dudek used the benzene concentration to estimate the human health risk using the San Diego County DEH Vapor Risk Model. The estimated risk (for indoor air) under the residential scenario was 2.28 x 10-7, which is less than the de minimus cancer risk of 1 x 10-6. No indication of further investigation of the hydraulic lift has been found during the preparation of this report. The presence of hydrocarbons in the vapor sample indicate that at least some level of soil contamination has occurred near the hydraulic lift. In addition to hydrocarbons, some hydraulic fluids manufactured prior to 1984 contained polychlorinated biphenyls (PCBs). Since this hydraulic lift was likely used in support of the maintenance operations at the site for several decades prior to 1984, the presence of PCBs cannot be ruled out without further investigation.
- Concrete Structure – Located in the east-central portion of the property is a concrete structure that the Dudek investigation previously referred to as a loading dock. However, given the dimensions and shape of the structure, its close proximity to the hydraulic lift, and the previous use of the site, The Bodhi Group concluded that it was more likely the remnants of a maintenance/service bay for vehicles or small machinery. As such, the presence of motor vehicle fluids (i.e. oil, brake/transmission fluid etc.) in the soils beneath the bays cannot be ruled out without further investigation.

Table 5 below provides a checklist of common Site observations relative to potential environmental concerns.

Table 5 – On-Site Observations

Conditions	Observed or Noted	Comments	Significant Concern?
Hazardous Substances/Petroleum Products	N	Not Observed	N
Waste Generation/Storage/Disposal	N	Not Observed	N
ASTs	N	Not Observed	N
Potential Evidence of USTs	N	Regulatory and database searches indicated the former presence of a fueling system. All documentation indicated that the system components have been removed. No evidence of any remaining UST components was observed during the site reconnaissance.	N
Potential PCB-Containing Equipment	Y	There are remnants of a hydraulic lift located in what is presumed to be a former mechanical maintenance area on the property. Prior to 1984 some hydraulic fluids did contain PCBs.	Y
Chemical/Petroleum Odors	N	Not Observed	N
Concrete Patches/Pads	Y	There are several concrete pads remaining on the Site. There is a large, rectangular concrete pad in the central portion of the Site which is the location of one of the former structures on the Site. The remnants of a hydraulic lift were observed in the eastern portion of this pad. There are two small, square concrete pads along the southern boundary of the Site.	Y

Table 5 – On-Site Observations

Conditions	Observed or Noted	Comments	Significant Concern?
		These may be remnant from utility installations. If either of these pads were used for electrical transformers, contamination with PCBs in the surrounding shallow soils is possible. There are three concrete pads of varying size along the western boundary of the Site. These coincide with the locations of structures observed in the historical aerial photographs. There is a concrete structure in the central portion of the Site that previous investigations have speculated may be the remnants of a loading dock (Dudek, 2012). However, based on the height and shape of the structure and the previous use of the Site, the Bodhi Group believes that this is more likely the remnants of a former maintenance/service bay for vehicles or small equipment.	
Pools of Liquid	N	Not Observed	N
Sewage Discharge Pipes	N	Not Observed	N
Floor Drains/Sumps	N	Not Observed	N
Hydraulic Elevator	Y	As mentioned above, the remnants of a hydraulic lift were observed on the eastern edge of one of the rectangular concrete patches.	Y

Table 5 – On-Site Observations

Conditions	Observed or Noted	Comments	Significant Concern?
Wells	N	The database review and records search for the Site indicated that 7 groundwater monitoring wells had previously been installed at the site. Records indicated that all have since been abandoned, and no evidence was observed that they are still in existence.	N
Drums	N	Not Observed	N
Unidentified Substance Containers	Y	Some miscellaneous debris was observed onsite, including an empty container of motor vehicle oil and an empty container of spray adhesive. These types of containers were minimal in number and no evidence was observed that their contents were released or disposed of on the Site.	N
Stained Soil or Pavement	N	Not Observed	N
Stressed Vegetation	N	Not Observed	N
Pits, Ponds, or Lagoons	Y	The natural drainage course was bermed near the Site's southern boundary, presumably in an attempt to control stormwater discharge into the storm drain. The site reconnaissance inspection was performed following a 2-day rain event, and water was observed ponding behind the sandbag berm. Additionally, the presence of the remnants of a hydraulic lift	Y

Table 5 – On-Site Observations

Conditions	Observed or Noted	Comments	Significant Concern?
		on the Site indicates that there is a pit beneath it that houses the lift components.	
Wastewater Discharge Disposal Systems	N	Not Observed	N
Septic Systems/Cesspools	N	Not Observed	N
Municipal Solid Waste Disposal Areas	N	Not Observed	N
Other Conditions	Y	There were pallets of bricks, sections of chain link fence and one section each of concrete and metal piping being stored on/near the concrete pads along the western boundary of the Site. What appeared to be pieces of a large eucalyptus tree were stockpiled on the western edge of the large rectangular concrete pad in the center of the Site. There is a 10”-diameter PVC pipe (approximately 8 feet tall) vertically installed in the ground northeast of the rectangular concrete patches in the center of the Site. There is a 2”-diameter PVC riser inside of the 10” pipe. According to a site map provided by the City of La Mesa, these pipes are remnants from a fire hose riser.	N

6. CONCLUSIONS

Conclusions from the review of the 2012 ESA (Dudek, 2012), other documents related to the former USTs (Leighton, 2008; SCS, 2011), and researched performed by under this ESA are summarized below.

6.1. Recognized Environmental Conditions

This section summarizes conditions at the Site that are considered RECs.

6.1.1. Former Underground Storage Tanks

Releases from the former 8,000-gallon gasoline UST and former 1,000-gallon diesel UST have resulted in impacts to soil, groundwater, and soil gas in the southern portion of the Site. The most recent publicly-available groundwater data is from January 2011, which indicates total petroleum hydrocarbon (TPH) contamination in the gasoline range at 17,000 µg/L; diesel range TPH at 3,300 µg/L; benzene at 1,000 µg/L; toluene at 2,900 µg/L; ethylbenzene at 1,200 µg/L; and xylenes at 4,600 µg/L. These detections were in groundwater encountered at approximately 4 feet below ground surface (bgs). The DEH closed the case considering these concentrations based on the long-term use of the Site for commercial-industrial purposes. While these concentrations may be suitable for use of the Site as a public park, there may be short-term exposure of construction workers to these chemicals because of the shallow depth of groundwater and any groundwater extracted for construction dewatering will require special handling and proper disposal. In addition, residual contamination from the former UST releases, while limited in soil, may be encountered during construction in this area (southern portion of the Site). Vapor forming chemicals from the UST releases can also accumulate in trenches excavated for construction, including utilities, potentially exposing construction workers to these chemicals. For these reasons, residual contamination from the former USTs is considered a REC.

6.1.2. Historical Operations as a Road Station

Research from this ESA and a review of the 2012 ESA identified past use of the Site for storage of construction materials, including waste oil, and the maintenance of vehicles from the early 1900s to approximately 1974. The duration of historical site operations that covers a period when there were no environmental laws or regulations may have resulted in chemical releases that contaminated shallow soil and groundwater at the Site. These potential chemical impacts were identified as metals and PAHs in the 2012 ESA. In addition to metals and PAHs, TPH may have impacted the subsurface from former vehicle operations as well as the storage of oil and waste oil at the Site (Dudek, 2012). Historically, waste oil may have contained polychlorinated biphenyls (PCBs), which may also have been released at the Site. Hydraulic fluids may also have contained PCBs and may have leaked into the Site soil. PCBs may also have been present in former transformers, which may have leaked and impacted shallow soil at the Site.

As part of the 2012 ESA, soil vapor samples were collected from the Site. Benzene was detected at a concentration of 0.12 µg/L and toluene at 2.2 µg/L. The vapor intrusion risk assessment from 2012 calculated risks that were determined to be acceptable based on these concentrations. However, the methods to calculate vapor intrusion risks have changed, including the attenuation factor that relates subsurface vapor concentrations to indoor air concentrations. Vapor intrusion risks calculated with current methods may indicate higher risks from vapor forming chemicals at the Site. Because there are no occupied structures planned for the public park, the vapor intrusion pathway is considered incomplete for this Project and therefore, may not be of concern to future use of the Site as a public park. However, there

is the potential for vapor forming chemicals to volatilize from the shallow groundwater and accumulate in construction trenches excavated for utilities potentially exposing construction workers in these trenches.

For the reasons stated above, the former use of the Site as a road station is considered a REC.

6.2. De Minimis Conditions

The following Site conditions may be present that may require mitigation measures during construction.

- Treated wood at the Site (i.e., wooden utility poles or other wood structures) may include chemicals such as chromate, copper, arsenic, pentachlorophenol, and creosote. Treated wood waste from the Site may require special handling and disposal under California Assembly Bill 332 under alternative management standards (that also provides relief from the more stringent hazardous waste disposal requirements).
- Painted surfaces at the Site may contain hazardous levels of paint (e.g., painted posts, curbs, striping, etc.). These painted surfaces may require special demolition, management, and disposal.
- Potential presence of asbestos containing materials and lead-based paint in soil from former structures or in underground utilities at the Site, if encountered during Site construction.

7. RECOMMENDATIONS

Recommendations to address the RECs identified in the previous section are listed below.

- Preparation and implementation of Worker and Community Health and Safety Plans that identify procedures for protecting workers and members of the public during construction. The plans will provide procedures for monitoring the potential for exposure of workers and the public to chemicals-of-concern from RECs at the Site during construction. The monitoring may include construction fence-line air sampling and monitoring of air in construction trenches.
- Preparation and implementation of Soil and Groundwater Management Plans that describe procedures for the identification and handling of contaminated soil and groundwater during construction, proper on-Site management of excavated soil and extracted groundwater, and disposal of the waste at permitted facilities in compliance with state and federal regulations.
- The Soil Management Plan may include representative sampling of surface and shallow soil for metals, TPH, PAHs, and PCBs in advance of construction to evaluate if chemicals-of-concern are present at concentrations that may present a risk to the future use of the Site as a public park and if contamination may be encountered during construction that requires special handling and disposal.
- The City of La Mesa may consider enrolling the Site in the DEH VAP for regulatory oversight of the preparation and implementation of the plans specified above. Enrolling in the VAP will assure the City that the recommendations are implemented in accordance with regulatory requirements and final regulatory closure of the RECs listed above will reduce future liability to the City.

8. DEVIATIONS/DATA GAPS

Deletions or deviations were not noted during this assessment. Title records for the Site were not reviewed for this assessment based on the information required by the client. Since no environmental liens or activity and use limitations were found, it is assumed for the purposes of this assessment that the title records would not reveal evidence of RECs associated with the Site. Therefore, the lack of review of title records is not considered to be a significant data gap that would affect the ability of the environmental professional to identify conditions indicative of releases or threatened releases for this Phase I ESA. No significant data gaps that would affect the ability of the environmental professional to identify conditions indicative of releases or threatened releases were encountered during this Phase I ESA.

9. REFERENCES

ASTM International (ASTM), 2021, Standard Practices for Environmental Site Assessments: Phase I Environmental Site Assessment Process, Designation No. E 1527-21.

County of San Diego, Department of Environmental Health (DEH), 2011, Unauthorized Release #H04820-001, Lemon Grove Road Station, 7410 Waite Drive, La Mesa, California, dated: December 1.

Dudek, 2012, Phase I Environmental Site Assessment, 7410 Waite Drive, La Mesa, California, APN 474-500-15-00, dated June 2012.

Environmental Data Resources, Inc. (EDR), 2023a, Radius Map™ Report with Geocheck®: dated March 13.

Environmental Data Resources, Inc. (EDR), 2023b, Historical Topographic Map Report: dated March 10.

Environmental Data Resources, Inc. (EDR), 2023c, Certified Sanborn Map Report: dated March 10.

Environmental Data Resources, Inc. (EDR), 2023d, Aerial Photo Decade Package: dated March 10.

Environmental Data Resources, Inc. (EDR), 2023e, EDR-City Directory Image Report: dated March 16.

Leighton, 2008. Second and Third Quarter 2008 Groundwater Monitoring Report and Site Conceptual Model Update, dated December 29.

San Diego Geographic Information Systems (SANGIS), 2023, County of San Diego Tax Assessors Parcels and Other Shapefiles http://www.sangis.org/.

San Diego Regional Water Quality Control Board (Water Board), 1994, Water Quality Control Plan for the San Diego Basin (9), dated: September 8, with amendments effective on or before May 17, 2016.

SCS Engineers, 2011. Groundwater Monitoring Report 4Q2010 & 1Q2011, Lemon Grove Road Station, 7410 Waite Drive, La Mesa, California, dated: July 15.

United States Geological Survey, 2018, National City, California: 7.5-minute series (topographic), Scale 1:24,000.

10. SIGNATURE AND QUALIFICATIONS

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined by §312.10 of 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all-appropriate-inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.



Sree Gopinath
Principal Engineer

11. LIMITATIONS

This report was prepared in general accordance with current regulatory guidelines and the standard-of-care exercised by environmental consultants preparing similar documents in the project area. No warranty, expressed or implied, is made regarding the professional opinions presented in this document. Variations in Site conditions will exist and conditions not observed or described in this document could be encountered during subsequent activities and Site work. Please also note that this document did not include an evaluation of geotechnical conditions or potential geologic hazards.

The conclusions, opinions, and recommendations regarding environmental conditions, as presented in this document, are based on an analysis of observed Site conditions and the referenced sources. Further assessment of environmental conditions at the Site may be accomplished by a more comprehensive assessment.

It should be understood that the conditions of a Site will change with time as a result of natural processes and the activities of man at the subject Site or nearby Sites. In addition, changes to the applicable laws, regulations, codes, and standards of practice may occur due to government action or the broadening of knowledge. The findings of this document may, therefore, be invalidated over time, in part or in whole, by changes over which the author has no control.

This document is intended to be used only in its entirety. No portion of the document, by itself, is designed to completely represent any aspect of the project described herein. The author should be contacted if the reader requires any additional information, or has questions regarding content, interpretations presented, or completeness of this document.

Data presented in this report should not be relied on for bidding purposes. This document is intended exclusively for use by the client. Any use or reuse of the findings, conclusions, and/or recommendations of this document by parties other than the client is undertaken at said parties' sole risk.

FIGURES



	Project No. 9152001	**Site Location Map**	THE BODHI GROUP
N W E S	Date: 04/2023		
0 500 1,000 Feet	Drawn By: SG	**7410 Waite Drive La Mesa, California**	Figure 1



Legend

× — Fence

Former monitoring wells associated with the UST case

N
W E
S

0 30 60 Feet

Project No. 9152001

Date: 04/2023

Drawn By: SG

Site Plan

7410 Waite Drive
La Mesa, California

Figure 2

THE BODHI GROUP
INNOVATING | SUSTAINING | SOLVING

APPENDIX A
SITE PHOTOGRAPHS



Site Overview (From northeast corner facing southwest)



Small concrete pad #1 at southern boundary of Site



Small concrete pad #2 at southern boundary of Site



Berm for stormwater runoff control



Concrete pad #1 at western boundary of Site (concrete and metal pipe pieces in background)



Concrete and metal sections of pipe (eucalyptus tree pieces stockpiled in background)



Concrete pad #2 at western boundary of the Site (beneath litter layer at the base of the pepper tree)



Concrete pad #3 at western boundary of the Site with pallets of bricks and sections of fence



Northern boundary of the Site (facing east) with degraded asphalt



Northern boundary of the Site (facing northwest) with degraded asphalt



10”-diameter pipe present on Site



2” riser inside of 10” outer casing



Former maintenance/service bays



Former maintenance/service bays



Large, rectangular concrete pad; former hydraulic lift; stockpile of eucalyptus tree pieces



Former hydraulic lift



Stockpile of eucalyptus tree pieces



Gravel drive/entrance to Site

APPENDIX B
ENVIRONMENTAL DATABASE REPORT

LA Mesa Park Site
7410 Waite Drive
LA Mesa, CA 91941

Inquiry Number: 7276918.2s
March 13, 2023

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	733
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-13
Physical Setting Source Map Findings	A-15
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527-21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

7410 WAITE DRIVE
LA MESA, CA 91941

COORDINATES

Latitude (North):	32.7468930 - 32ˆ 44' 48.81''
Longitude (West):	117.0383010 - 117ˆ 2' 17.88''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	496411.8
UTM Y (Meters):	3623038.5
Elevation:	471 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	11993860 NATIONAL CITY, CA
Version Date:	2018
North Map:	11993858 LA MESA, CA
Version Date:	2018

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20140530
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
7410 WAITE DRIVE
LA MESA, CA 91941

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	LEMON GROVE STATION-	7410 WAITE DRIVE	HIST UST, HAZNET, HWTS		TP
A2	COUNTY OF SAN DIEGO	7410 WAITE DR	HAZNET, HWTS		TP
A3	COUNTY OF SD-FLEET O	7410 WAITE DR	RGA LUST		TP
A4	S D CNTY GEN SVCS AU	7410 WAITE DR	RGA LUST		TP
A5	LEMON GROVE SERVICE	7410 WAITE DR	HWTS		TP
A6	FLEET OPERATIONS LEM	7410 WAITE DR	RGA LUST		TP
A7	S D CNTY GEN SVCS AU	7410 WAITE DR	FINDS		TP
A8	LEMON GROVE SERVICE	7410 WAITE DR	RCRA-SQG, HIST UST, FINDS, ECHO		TP
A9	COUNTY OF SD-FLEET O	7410 WAITE DR	RGA LUST		TP
A10	FLEET OPERATIONS LEM	7410 WAITE DR	LUST		TP
A11	S D CNTY GEN SVCS AU	7410 WAITE DR	LUST, SAN DIEGO CO. SAM, San Diego Co. HMMD,...		TP
A12	1X COUNTY OF SAN DIE	7400 WAITE DRIVE	HAZNET, HWTS	Lower	2, 0.000,
B13	STEVE MCELFRESH	3743 HARRIS ST.	RCRA NonGen / NLR	Lower	202, 0.038, SW
B14	ROBERTA SLATER	3743 HARRIS ST.	RCRA NonGen / NLR	Lower	202, 0.038, SW
15	BRUCE BARAW	3889 HARRIS STREET	RCRA NonGen / NLR	Higher	309, 0.059, NNW
C16	KEVIN FERREE	3775 CITRUS STREET	RCRA NonGen / NLR	Lower	519, 0.098, WSW
C17	DIANDRA LAUIFI	3766 CITRUS ST	RCRA NonGen / NLR	Lower	623, 0.118, WSW
C18	PEDRO& MARIA FAJARDO	3760 CITRUS STREET	RCRA NonGen / NLR	Lower	636, 0.120, WSW
C19	JOAN SANCHEZ	3736 CITRUS ST.	RCRA NonGen / NLR	Lower	655, 0.124, WSW
D20	WESTSTAR LANDSCAPE	3553 HARRIS ST	RCRA NonGen / NLR	Lower	827, 0.157, SSW
D21	VIKING FENCE AT0236	3529 HARRIS ST	San Diego Co. HMMD, SWEEPS UST	Lower	931, 0.176, SSW
E22	FOOD 4 LESS FUEL CEN	7428 BROADWAY	UST	Lower	955, 0.181, SSE
E23	FOOD 4 LESS FUEL CEN	7428 BROADWAY	San Diego Co. HMMD, CERS HAZ WASTE, CERS TANKS,...	Lower	955, 0.181, SSE
E24	FOOD 4 LESS - FUEL C	7428 BROADWAY	RCRA-LQG	Lower	955, 0.181, SSE
D25	JOE YOUSIF	3521 HARRIS ST.	RCRA NonGen / NLR	Lower	960, 0.182, SSW
F26	PAUL EK	3590 CITRUS STREET	RCRA NonGen / NLR	Lower	961, 0.182, SW
D27	JOE YOUSIF	3515-3521 HARRIS ST	RCRA NonGen / NLR	Lower	978, 0.185, SSW
G28	LEMON GROVE VETERINA	7572 NORTH AVE	San Diego Co. HMMD, CERS HAZ WASTE, CERS	Lower	1029, 0.195, SE
E29	PRONTO AUTO REPAIR	7385 LEMON AVE	San Diego Co. HMMD, CERS HAZ WASTE, HAZNET, CERS,...	Lower	1037, 0.196, South
E30	PRONTO AUTO REPAIR	7385 LEMON AVE	RCRA NonGen / NLR	Lower	1037, 0.196, South
E31	INTERNATIONAL AUTO S	7385 LEMON AVE	RCRA-SQG, FINDS, ECHO	Lower	1037, 0.196, South
D32	W.E. WALTERS & SONS	3494 HARRIS ST	San Diego Co. HMMD, SWEEPS UST	Lower	1048, 0.198, SSW
F33	PORTILLO CONCRETE IN	3527 CITRUS ST	RCRA NonGen / NLR	Lower	1052, 0.199, SSW
G34	FHCSD PARKING LOT -	7580 NORTH AVENUE	CPS-SLIC, CERS	Lower	1069, 0.202, SE
D35	A&A COLLEX EXPERTS I	3463 HARRIS ST	RCRA NonGen / NLR	Lower	1073, 0.203, South
D36	COLLISION EXPERTS	3463 HARRIS ST STE A	CERS HAZ WASTE, HAZNET, CERS, HWTS	Lower	1073, 0.203, South
D37	COLLISION EXPERTS	3463 HARRIS ST STE A	RCRA NonGen / NLR	Lower	1073, 0.203, South
H38	ARCO STATION	3775 MASSACHUSETTS A	LUST	Lower	1128, 0.214, WSW
H39	ALIA PETROLEUM INC.	3775 MASSACHUSETTS A	RCRA NonGen / NLR	Lower	1128, 0.214, WSW

MAPPED SITES SUMMARY

Target Property Address:
7410 WAITE DRIVE
LA MESA, CA 91941

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
H40	ARCO #01710	3775 MASSACHUSETTS A	SAN DIEGO CO. SAM, FINDS, Cortese	Lower	1128, 0.214, WSW
H41	ARCO #01710	3775 MASSACHUSETTS A	LUST, CPS-SLIC, San Diego Co. HMMD, CERS HAZ...	Lower	1128, 0.214, WSW
H42	PRESTIGE STATIONS IN	3775 MASSACHUSETTS A	HIST UST	Lower	1128, 0.214, WSW
H43	ALIA PETROLEUM INC.	3775 MASSACHUSETTS A	UST	Lower	1128, 0.214, WSW
H44	ARCO FACILITY NO 017	3775 MASSACHUSETTS A	RCRA NonGen / NLR, FINDS, ECHO	Lower	1128, 0.214, WSW
H45	AMACA PROPERTIES LLC	3775 MASSACHUSETTS A	UST	Lower	1128, 0.214, WSW
H46	ARCO #1710	3775 MASSACHUSETTS A	UST	Lower	1128, 0.214, WSW
H47	PRESTIGE STATIONS IN	3775 MASSACHUSETTS A	SWEEPS UST	Lower	1128, 0.214, WSW
H48	ARCO STATION #1710	3775 MASSACHUSETTS A	LUST	Lower	1128, 0.214, WSW
G49	MODERN AUTO REPAIR	7586 NORTH AVE	RCRA NonGen / NLR	Lower	1138, 0.216, SE
G50	MODERN AUTO REPAIR	7586 NORTH AVE	RCRA NonGen / NLR	Lower	1138, 0.216, SE
G51	SUPERIOR SMOG AND TU	7586 NORTH AVE	San Diego Co. HMMD, CERS HAZ WASTE	Lower	1138, 0.216, SE
G52	SUPERIOR SMOG AND TU	7586 NORTH AVE	RCRA NonGen / NLR	Lower	1138, 0.216, SE
53	DEBBIE TERRELL	3951 APORE STREET	RCRA NonGen / NLR	Higher	1147, 0.217, NE
I54	PP-CA LP DBA SAN DIE	7368 BROADWAY STE A	RCRA NonGen / NLR	Lower	1176, 0.223, South
I55	SAN DIEGO PET HOSPIT	7368 BROADWAY	San Diego Co. HMMD, CERS HAZ WASTE	Lower	1176, 0.223, South
J56	LEMON GROVE AUTO	3463-3465 CITRUS STR	ENVIROSTOR	Lower	1230, 0.233, SSW
J57	LEMON GROVE AUTO	3465 CITRUS ST	LUST, SAN DIEGO CO. SAM, CPS-SLIC, San Diego Co....	Lower	1231, 0.233, SSW
I58	LEMON GROVE U-RENT	7370 BROADWAY	HIST UST	Lower	1260, 0.239, South
I59	LEMON GROVE U RENT	7370 BROADWAY	San Diego Co. HMMD, SWEEPS UST	Lower	1260, 0.239, South
K60	ANGIES TOWING INC DB	7620 NORTH AVE	RCRA NonGen / NLR	Lower	1279, 0.242, ESE
K61	CHARLIES AUTO BRAKE	7620 N AVE	RCRA-SQG, FINDS, ECHO	Lower	1279, 0.242, ESE
K62	BONK'S GENERAL AUTOM	7620 NORTH AVE	RCRA NonGen / NLR	Lower	1279, 0.242, ESE
L63	CENTRE CITY SHELL 2	3810 MASSACHUSETTS A	SWEEPS UST, HIST UST	Lower	1319, 0.250, West
L64	SHELL	3810 MASSACHUSETTS A	San Diego Co. HMMD, CERS HAZ WASTE, CERS TANKS,...	Lower	1319, 0.250, West
L65	CENTER CITY SHELL	3810 MASSACHUSETTS A	UST	Lower	1319, 0.250, West
L66	SHELL	3810 MASSACHUSETTS A	LUST	Lower	1319, 0.250, West
L67	SHELL SERVICE STATIO	3810 MASSACHUSETSS /	RCRA-LQG	Lower	1319, 0.250, West
L68	CENTRE CITY SHELL	3810 MASSACHUSETTS A	RCRA NonGen / NLR	Lower	1319, 0.250, West
L69	SHELL	3810 MASSACHUSETTS A	SAN DIEGO CO. SAM, Cortese	Lower	1319, 0.250, West
70	FOOD 4 LESS STORE #3	7420 BROADWAY ST	SWRCY, San Diego Co. HMMD, CERS HAZ WASTE, CERS	Lower	1327, 0.251, South
71	CORRAL FORD	3470 VISTA AV	LUST, SAN DIEGO CO. SAM, San Diego Co. HMMD,...	Lower	1435, 0.272, SW
72	COMMERCIAL PROPERTY	7666 NORTH AVENUE	CPS-SLIC, CERS	Lower	1494, 0.283, ESE
M73	USA PETROLEUM COMPAN	7505 BROADWAY	LUST, HIST UST, HIST CORTESE	Lower	1503, 0.285, SSE
M74	USA PETROLEUM	7505 BROADWAY	LUST, SAN DIEGO CO. SAM, San Diego Co. HMMD,...	Lower	1503, 0.285, SSE
M75	SAN DIEGO GLASS & PA	7551 BROADWAY	LUST, San Diego Co. HMMD, SWEEPS UST, HIST UST,...	Lower	1580, 0.299, SSE
M76	SAN DIEGO GLASS AND	7551 BROADWAY	LUST, HIST CORTESE	Lower	1580, 0.299, SSE
M77	SAN DIEGO GLASS AND	7551 BROADWAY	SAN DIEGO CO. SAM, HIST UST, SAN DIEGO CO LOP	Lower	1580, 0.299, SSE
N78	ECONO LUBE N TUNE	7608 BROADWAY	Cortese, HAZNET, HWTS	Lower	1692, 0.320, SE

MAPPED SITES SUMMARY

Target Property Address:
7410 WAITE DRIVE
LA MESA, CA 91941

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
N79	WORLD OIL ENVIRONMEN	7608 BROADWAY	RCRA-SQG, LUST, SAN DIEGO CO. SAM, CPS-SLIC, San...	Lower	1692, 0.320, SE
O80		7656 LEMON ST	Notify 65	Lower	1706, 0.323, SE
P81	CORRAL FORD	7220 BROADWAY	LUST, SWEEPS UST, HIST UST, RCRA NonGen / NLR,...	Lower	1736, 0.329, SW
N82	UNOCAL SERVICE STATI	7593 BROADWAY	LUST, HIST CORTESE	Lower	1750, 0.331, SE
N83	UNION OIL SERVICE ST	7593 BROADWAY	LUST, CPS-SLIC, HIST UST	Lower	1750, 0.331, SE
N84	SAN DIEGO MOTORS	7593 BROADWAY	SAN DIEGO CO. SAM, San Diego Co. HMMD, Cortese,...	Lower	1750, 0.331, SE
N85	TOSCO 76 #3699	7593 BROADWAY	LUST, CPS-SLIC, SWEEPS UST, CERS	Lower	1750, 0.331, SE
P86	MOBIL SERVICE STATIO	7204 BROADWAY	LUST	Lower	1789, 0.339, SW
P87	THOMAS F DAVISON	7204 BROADWAY	LUST, CPS-SLIC, HIST UST, SAN DIEGO CO LOP	Lower	1789, 0.339, SW
P88	DAVES MOBIL OIL STN	7204 BROADWAY	RCRA-SQG, SAN DIEGO CO. SAM, San Diego Co. HMMD,...	Lower	1789, 0.339, SW
N89	7-ELEVEN FOOD STORE	7607 BROADWAY	SAN DIEGO CO. SAM, UST, San Diego Co. HMMD, SWEEPS...	Lower	1831, 0.347, SE
N90	7-ELEVEN FOOD STORE	7607 BROADWAY	LUST, HIST UST, CERS	Lower	1831, 0.347, SE
N91	7-ELEVEN STORE NO 24	7607 BROADWAY	LUST	Lower	1831, 0.347, SE
P92	SHELL	7180 BROADWAY	LUST, San Diego Co. HMMD, EMI, HIST CORTESE, CERS	Lower	1843, 0.349, SW
P93	TEXACO REFINING AND	7180 BROADWAY	SAN DIEGO CO. SAM, UST, SWEEPS UST, Cortese	Lower	1843, 0.349, SW
P94	SHELL	7180 BROADWAY	LUST, CPS-SLIC, FINDS, ECHO, SAN DIEGO CO LOP,...	Lower	1843, 0.349, SW
P95	91739	7209 BROADWAY	LUST, CPS-SLIC, CERS HAZ WASTE, HIST UST, CERS...	Lower	1844, 0.349, SW
P96	CHEVRON	7209 BROADWAY	LUST, SAN DIEGO CO. SAM, San Diego Co. HMMD,...	Lower	1844, 0.349, SW
O97	CULLIGAN WATER / U.S	3536 OLIVE STREET	LUST	Lower	1866, 0.353, ESE
O98	CULLIGAN WATER CONDI	3536 OLIVE ST	LUST, SAN DIEGO CO. SAM, CERS HAZ WASTE, SWEEPS...	Lower	1866, 0.353, ESE
Q99	CITRONICA II	3595 OLIVE AVENUE	CPS-SLIC, CERS	Lower	1977, 0.374, ESE
Q100	CULLIGEN WATER CONDI	3515 OLIVE	LUST, CPS-SLIC, Cortese, HIST CORTESE, HAZNET, SAN...	Lower	1990, 0.377, ESE
Q101	CULLIGEN WATER CONDI	3515 OLIVE ST	LUST	Lower	1990, 0.377, ESE
Q102	LEMON GROVE AVENUE R	7750 NORTH AVENUE	CPS-SLIC, CERS	Lower	1999, 0.379, ESE
R103	WALGREENS #12915	7195 BROADWAY	LUST, CERS HAZ WASTE, Cortese, HAZNET, SAN DIEGO...	Lower	2073, 0.393, SW
R104	ROCK LIQUOR, 7161 BR	7161 BROADWAY	SAN DIEGO CO. SAM, CPS-SLIC, CERS	Lower	2115, 0.401, SW
S105	MAIN STREET PROMENAD	3466-3530 MAIN ST	CPS-SLIC, CERS	Lower	2267, 0.429, ESE
S106	LEMON GROVE PROPERTY	7770 BROADWAY	LUST, SAN DIEGO CO. SAM, San Diego Co. HMMD,...	Lower	2306, 0.437, SE
107	HONDA OF LEMON GROVE	3611 LEMON GROVE AV	SAN DIEGO CO. SAM, CPS-SLIC, CERS	Higher	2391, 0.453, East
108	WELLS FARGO BANK	7060 BROADWAY	SAN DIEGO CO. SAM, CPS-SLIC, San Diego Co. HMMD,...	Lower	2562, 0.485, WSW
109	PALOMAR CLEANERS	7870 BROADWAY	RCRA-SQG, ENVIROSTOR, SAN DIEGO CO. SAM, CPS-SLIC,...	Lower	2856, 0.541, ESE
110	HELIX CHARTER HIGH S	7323 UNIVERSITY AVEN	ENVIROSTOR, LUST, SCH, Cortese, HIST CORTESE,...	Lower	3057, 0.579, North
111	SONKA TRUST PROPERTY	3065 LEMON GROVE AV	ENVIROSTOR, LUST, SAN DIEGO CO. SAM, CPS-SLIC, San...	Lower	3352, 0.635, SE
112	COMMERCIAL SHOPPING	7006-7020 UNIVERSITY	ENVIROSTOR	Lower	3854, 0.730, NW
113	7-ELEVEN STORE #1745	7733 PALM AVENUE	HIST UST, Notify 65	Lower	4665, 0.884, SSE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 9 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
LEMON GROVE STATION- 7410 WAITE DRIVE LA MESA, CA 92041	HIST UST HAZNET GEPAID: CAL000117335 HWTS	N/A
COUNTY OF SAN DIEGO 7410 WAITE DR LA MESA, CA 92041	HAZNET GEPAID: CAX000079574 HWTS	N/A
COUNTY OF SD-FLEET O 7410 WAITE DR SAN DIEGO, CA	RGA LUST	N/A
S D CNTY GEN SVCS AU 7410 WAITE DR LA MESA, CA	RGA LUST	N/A
LEMON GROVE SERVICE 7410 WAITE DR LAMESA, CA 92041	HWTS	N/A
FLEET OPERATIONS LEM 7410 WAITE DR LEMON GROVE, CA	RGA LUST	N/A
S D CNTY GEN SVCS AU 7410 WAITE DR LA MESA, CA 91941	FINDS Registry ID:: 110066233294	N/A
LEMON GROVE SERVICE 7410 WAITE DR LA MESA, CA 91941	RCRA-SQG EPA ID:: CAD981694979 HIST UST Facility Id: 00000044130 FINDS Registry ID:: 110006474207 ECHO Registry ID: 110006474207	CAD981694979
COUNTY OF SD-FLEET O 7410 WAITE DR LA MESA, CA	RGA LUST	N/A

EXECUTIVE SUMMARY

FLEET OPERATIONS LEM
7410 WAITE DR
LEMON GROVE, CA 91945

LUST N/A
Database: LUST REG 9, Date of Government Version: 03/01/2001
Case Number: 9UT2686
Status: Preliminary site assessment underway

S D CNTY GEN SVCS AU
7410 WAITE DR
LA MESA, CA 91941

LUST N/A
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T0607301436

SAN DIEGO CO. SAM
Case Number: H04820-001
Facility Status: Remedial Investigation

San Diego Co. HMMD
SWEEPS UST
Status: A
Tank Status: A
Comp Number: 4820

Cortese
Cleanup Status: COMPLETED - CASE CLOSED

HIST CORTESE
Reg Id: 9UT1966

SAN DIEGO CO LOP
CERS

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing

SEMS Superfund Enterprise Management System

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF RCRA - Treatment, Storage and Disposal

Lists of Federal RCRA generators

RCRA-VSQG RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

Federal institutional controls / engineering controls registries

LUCIS Land Use Control Information System
US ENG CONTROLS Engineering Controls Sites List
US INST CONTROLS Institutional Controls Sites List

Federal ERNS list

ERNS Emergency Response Notification System

Lists of state- and tribal (Superfund) equivalent sites

RESPONSE State Response Sites

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF Solid Waste Information System

Lists of state and tribal leaking storage tanks

INDIAN LUST Leaking Underground Storage Tanks on Indian Land

Lists of state and tribal registered storage tanks

FEMA UST Underground Storage Tank Listing
AST Aboveground Petroleum Storage Tank Facilities
INDIAN UST Underground Storage Tanks on Indian Land

Lists of state and tribal voluntary cleanup sites

INDIAN VCP Voluntary Cleanup Priority Listing
VCP Voluntary Cleanup Program Properties

Lists of state and tribal brownfield sites

BROWNFIELDS Considered Brownfieds Sites Listing

EXECUTIVE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT ..... Waste Management Unit Database
HAULERS ..... Registered Waste Tire Haulers Listing
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands
ODI ..... Open Dump Inventory
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ..... Delisted National Clandestine Laboratory Register
HIST Cal-Sites ..... Historical Calsites Database
SCH ..... School Property Evaluation Program
CDL ..... Clandestine Drug Labs
Toxic Pits ..... Toxic Pits Cleanup Act Sites
US CDL ..... National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

CA FID UST ..... Facility Inventory Database

Local Land Records

LIENS ..... Environmental Liens Listing
LIENS 2 ..... CERCLA Lien Information
DEED ..... Deed Restriction Listing

Records of Emergency Release Reports

HMIRS ..... Hazardous Materials Information Reporting System
CHMIRS ..... California Hazardous Material Incident Report System
LDS ..... Land Disposal Sites Listing
MCS ..... Military Cleanup Sites Listing
SPILLS 90 ..... SPILLS 90 data from FirstSearch

Other Ascertainable Records

FUDS ..... Formerly Used Defense Sites
DOD ..... Department of Defense Sites
SCRD DRYCLEANERS ..... State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ..... Financial Assurance Information
EPA WATCH LIST ..... EPA WATCH LIST
2020 COR ACTION ..... 2020 Corrective Action Program List
TSCA ..... Toxic Substances Control Act
TRIS ..... Toxic Chemical Release Inventory System
SSTS ..... Section 7 Tracking Systems

EXECUTIVE SUMMARY

ROD	Records Of Decision
RMP	Risk Management Plans
RAATS	RCRA Administrative Action Tracking System
PRP	Potentially Responsible Parties
PADS	PCB Activity Database System
ICIS	Integrated Compliance Information System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
FUSRAP	Formerly Utilized Sites Remedial Action Program
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US AIRS	Aerometric Information Retrieval System Facility Subsystem
US MINES	Mines Master Index File
ABANDONED MINES	Abandoned Mines
DOCKET HWC	Hazardous Waste Compliance Docket Listing
UXO	Unexploded Ordnance Sites
FUELS PROGRAM	EPA Fuels Program Registered Listing
PFAS NPL	Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES	Federal Sites PFAS Information
PFAS TSCA	PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR	PFAS Contamination Site Location Listing
PFAS WQP	Ambient Environmental Sampling for PFAS
PFAS NPDES	Clean Water Act Discharge Monitoring Information
PFAS ECHO	Facilities in Industries that May Be Handling PFAS Listing
PFAS ECHO FIRE TRAINING	Facilities in Industries that May Be Handling PFAS Listing
PFAS PART 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing
PFAS	PFAS Contamination Site Location Listing
AQUEOUS FOAM	Former Fire Training Facility Assessments Listing
CA BOND EXP. PLAN	Bond Expenditure Plan
CUPA Listings	CUPA Resources List
DRYCLEANERS	Cleaner Facilities
EMI	Emissions Inventory Data
ENF	Enforcement Action Listing
Financial Assurance	Financial Assurance Information Listing
ICE	ICE
HWP	EnviroStor Permitted Facilities Listing
HWT	Registered Hazardous Waste Transporter Database
MINES	Mines Site Location Listing
MWMP	Medical Waste Management Program Listing
NPDES	NPDES Permits Listing
PEST LIC	Pesticide Regulation Licenses Listing
PROC	Certified Processors Database
UIC	UIC Listing
UIC GEO	UIC GEO (GEOTRACKER)

WASTEWATER PITS Oil Wastewater Pits Listing
WDS Waste Discharge System
WIP Well Investigation Program Case List
MILITARY PRIV SITES MILITARY PRIV SITES (GEOTRACKER)
PROJECT PROJECT (GEOTRACKER)
WDR Waste Discharge Requirements Listing
CIWQS California Integrated Water Quality System
NON-CASE INFO NON-CASE INFO (GEOTRACKER)
OTHER OIL GAS OTHER OIL & GAS (GEOTRACKER)
PROD WATER PONDS PROD WATER PONDS (GEOTRACKER)
SAMPLING POINT SAMPLING POINT (GEOTRACKER)
WELL STIM PROJ Well Stimulation Project (GEOTRACKER)
MINES MRDS Mineral Resources Data System

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants
EDR Hist Auto EDR Exclusive Historical Auto Stations
EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 11/21/2022 has revealed that there are 2

RCRA-LQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FOOD 4 LESS - FUEL C EPA ID:: CAR000259994	7428 BROADWAY	SSE 1/8 - 1/4 (0.181 mi.)	E24	113
SHELL SERVICE STATIO EPA ID:: CAR000075556	3810 MASSACHUSETSS /	W 1/8 - 1/4 (0.250 mi.)	L67	361

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 11/21/2022 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
INTERNATIONAL AUTO S EPA ID:: CAD981984560	***7385 LEMON AVE***	***S 1/8 - 1/4 (0.196 mi.)***	***E31***	***142***
CHARLIES AUTO BRAKE EPA ID:: CAD983609652	***7620 N AVE***	***ESE 1/8 - 1/4 (0.242 mi.)***	***K61***	***289***

Lists of state- and tribal hazardous waste facilities

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 10/24/2022 has revealed that there are 5 ENVIROSTOR sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LEMON GROVE AUTO Facility Id: 37750004 Status: Refer: 1248 Local Agency	3463-3465 CITRUS STR	SSW 1/8 - 1/4 (0.233 mi.)	J56	277
PALOMAR CLEANERS Facility Id: 37720040 Status: Refer: 1248 Local Agency	***7870 BROADWAY***	***ESE 1/2 - 1 (0.541 mi.)***	***109***	***678***
HELIX CHARTER HIGH S Facility Id: 60000862 Status: No Further Action	***7323 UNIVERSITY AVEN***	***N 1/2 - 1 (0.579 mi.)***	***110***	***713***
SONKA TRUST PROPERTY	***3065 LEMON GROVE AV***	***SE 1/2 - 1 (0.635 mi.)***	***111***	***721***

Facility Id: 37000055
Status: Refer: 1248 Local Agency

COMMERCIAL SHOPPING Facility Id: 37150013 Status: Refer: 1248 Local Agency	7006-7020 UNIVERSITY	NW 1/2 - 1 (0.730 mi.)	112	730

Lists of state and tribal leaking storage tanks

SAN DIEGO CO. SAM: The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

A review of the SAN DIEGO CO. SAM list, as provided by EDR, and dated 03/23/2010 has revealed that there are 17 SAN DIEGO CO. SAM sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HONDA OF LEMON GROVE Case Number: H01540-001 Facility Status: Preliminary Assessment	***3611 LEMON GROVE AV***	***E 1/4 - 1/2 (0.453 mi.)***	***107***	***676***

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARCO #01710 Case Number: H13041-001 Case Number: H13041-002 Case Number: H13041-003 Facility Status: Closed Case	***3775 MASSACHUSETTS A***	***WSW 1/8 - 1/4 (0.214 mi.)***	***H40***	***171***
LEMON GROVE AUTO Case Number: H36873-001 Case Number: H36873-002 Facility Status: Post Remedial Monitoring Facility Status: Closed Case	***3465 CITRUS ST***	***SSW 1/8 - 1/4 (0.233 mi.)***	***J57***	***278***
SHELL Case Number: H12440-001 Case Number: H12440-002 Facility Status: Remedial Investigation Facility Status: Closed Case	***3810 MASSACHUSETTS A***	***W 1/8 - 1/4 (0.250 mi.)***	***L69***	***367***
CORRAL FORD Case Number: H12503-001 Facility Status: Closed Case	***3470 VISTA AV***	***SW 1/4 - 1/2 (0.272 mi.)***	***71***	***393***
USA PETROLEUM Case Number: H03292-001 Facility Status: Remedial Action (Clean-Up)	***7505 BROADWAY***	***SSE 1/4 - 1/2 (0.285 mi.)***	***M74***	***409***
SAN DIEGO GLASS AND Case Number: H20567-001 Facility Status: Closed Case	***7551 BROADWAY***	***SSE 1/4 - 1/2 (0.299 mi.)***	***M77***	***422***
WORLD OIL ENVIRONMEN Case Number: H14708-001 Case Number: H14708-002	***7608 BROADWAY***	***SE 1/4 - 1/2 (0.320 mi.)***	***N79***	***425***

Facility Status: Closed Case

SAN DIEGO MOTORS	***7593 BROADWAY***	***SE 1/4 - 1/2 (0.331 mi.)***	***N84***	***456***
Case Number: H13304-001				
Case Number: H13304-002				
Facility Status: Closed Case				
DAVES MOBIL OIL STN	***7204 BROADWAY***	***SW 1/4 - 1/2 (0.339 mi.)***	***P88***	***469***
Case Number: H12538-001				
Case Number: H12538-002				
Facility Status: Closed Case				
7-ELEVEN FOOD STORE	***7607 BROADWAY***	***SE 1/4 - 1/2 (0.347 mi.)***	***N89***	***478***
Case Number: H20571-001				
Facility Status: Closed Case				
TEXACO REFINING AND	***7180 BROADWAY***	***SW 1/4 - 1/2 (0.349 mi.)***	***P93***	***530***
Case Number: H12684-001				
Case Number: H12684-002				
Case Number: H12684-003				
Case Number: H12684-004				
Case Number: H12684-005				
**Additional key fields are available in the Map Findings section*				
Facility Status: Remedial Investigation				
Facility Status: Closed Case				
CHEVRON	***7209 BROADWAY***	***SW 1/4 - 1/2 (0.349 mi.)***	***P96***	***578***
Case Number: H12922-001				
Case Number: H12922-002				
Facility Status: Closed Case				
CULLIGAN WATER CONDI	***3536 OLIVE ST***	***ESE 1/4 - 1/2 (0.353 mi.)***	***O98***	***626***
Case Number: H20784-001				
Case Number: H20784-002				
Facility Status: Closed Case				
ROCK LIQUOR, 7161 BR	***7161 BROADWAY***	***SW 1/4 - 1/2 (0.401 mi.)***	***R104***	***668***
Case Number: H39746-001				
Facility Status: Leak Being Confirmed				
LEMON GROVE PROPERTY	***7770 BROADWAY***	***SE 1/4 - 1/2 (0.437 mi.)***	***S106***	***672***
Case Number: H35627-001				
Facility Status: Closed Case				
WELLS FARGO BANK	***7060 BROADWAY***	***WSW 1/4 - 1/2 (0.485 mi.)***	***108***	***677***
Case Number: H35324-001				
Facility Status: Closed Case				

LUST: Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the LUST list, as provided by EDR, has revealed that there are 29 LUST sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARCO STATION	3775 MASSACHUSETTS A	WSW 1/8 - 1/4 (0.214 mi.)	H38	168
Database: LUST REG 9, Date of Government Version: 03/01/2001				
Case Number: 9UT1455				

Status: Remediation Plan

ARCO #01710	***3775 MASSACHUSETTS A***	***WSW 1/8 - 1/4 (0.214 mi.)***	***H41***	***173***
Database: LUST, Date of Government Version: 12/02/2022 Status: Completed - Case Closed Global Id: T0607300280 Global Id: T0607302300				
ARCO STATION #1710	3775 MASSACHUSETTS A	WSW 1/8 - 1/4 (0.214 mi.)	H48	248
Database: LUST REG 9, Date of Government Version: 03/01/2001 Case Number: 9UT3531 Status: Preliminary site assessment workplan submitted				
LEMON GROVE AUTO	***3465 CITRUS ST***	***SSW 1/8 - 1/4 (0.233 mi.)***	***J57***	***278***
Database: LUST REG 9, Date of Government Version: 03/01/2001 Database: LUST, Date of Government Version: 12/02/2022 Case Number: 9UT3987 Status: Completed - Case Closed Status: Preliminary site assessment workplan submitted Global Id: T0607399203				
SHELL	3810 MASSACHUSETTS A	W 1/8 - 1/4 (0.250 mi.)	L66	355
Database: LUST, Date of Government Version: 12/02/2022 Status: Completed - Case Closed Global Id: T06019780340 Global Id: T0607338887				
CORRAL FORD	***3470 VISTA AV***	***SW 1/4 - 1/2 (0.272 mi.)***	***71***	***393***
Database: LUST, Date of Government Version: 12/02/2022 Status: Completed - Case Closed Global Id: T0607301486				
USA PETROLEUM COMPAN	***7505 BROADWAY***	***SSE 1/4 - 1/2 (0.285 mi.)***	***M73***	***398***
Database: LUST, Date of Government Version: 12/02/2022 Case Number: 9UT1368 Status: Open - Remediation Status: Preliminary site assessment underway Global Id: T0607300209				
USA PETROLEUM	***7505 BROADWAY***	***SSE 1/4 - 1/2 (0.285 mi.)***	***M74***	***409***
Database: LUST REG 9, Date of Government Version: 03/01/2001				
SAN DIEGO GLASS & PA	***7551 BROADWAY***	***SSE 1/4 - 1/2 (0.299 mi.)***	***M75***	***417***
Database: LUST, Date of Government Version: 12/02/2022 Status: Completed - Case Closed Global Id: T0607302808				
SAN DIEGO GLASS AND	***7551 BROADWAY***	***SSE 1/4 - 1/2 (0.299 mi.)***	***M76***	***421***
Database: LUST REG 9, Date of Government Version: 03/01/2001 Case Number: 9UT51 Closed Date: 12/17/96 Status: Case Closed				
WORLD OIL ENVIRONMEN	***7608 BROADWAY***	***SE 1/4 - 1/2 (0.320 mi.)***	***N79***	***425***
Database: LUST REG 9, Date of Government Version: 03/01/2001 Database: LUST, Date of Government Version: 12/02/2022 Case Number: 9UT688 Closed Date: 1/31/90 Status: Completed - Case Closed Status: Case Closed Global Id: T0607302957				
CORRAL FORD	***7220 BROADWAY***	***SW 1/4 - 1/2 (0.329 mi.)***	***P81***	***439***
Database: LUST REG 9, Date of Government Version: 03/01/2001				

Case Number: 9UT2731
Closed Date: 1/14/95
Status: Case Closed

UNOCAL SERVICE STATI ***7593 BROADWAY*** ***SE 1/4 - 1/2 (0.331 mi.)*** ***N82*** ***453***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Case Number: 9UT671
Closed Date: 2/16/88
Status: Case Closed

UNION OIL SERVICE ST ***7593 BROADWAY*** ***SE 1/4 - 1/2 (0.331 mi.)*** ***N83*** ***454***
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T0607399191

TOSCO 76 #3699 ***7593 BROADWAY*** ***SE 1/4 - 1/2 (0.331 mi.)*** ***N85*** ***463***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Case Number: 9UT3970
Status: Preliminary site assessment workplan submitted

MOBIL SERVICE STATIO 7204 BROADWAY SW 1/4 - 1/2 (0.339 mi.) P86 466
Database: LUST REG 9, Date of Government Version: 03/01/2001
Case Number: 9UT322
Closed Date: 8/23/96
Status: Case Closed

THOMAS F DAVISON ***7204 BROADWAY*** ***SW 1/4 - 1/2 (0.339 mi.)*** ***P87*** ***467***
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T0607301977

7-ELEVEN FOOD STORE ***7607 BROADWAY*** ***SE 1/4 - 1/2 (0.347 mi.)*** ***N90*** ***482***
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T0607391309

7-ELEVEN STORE NO 24 7607 BROADWAY SE 1/4 - 1/2 (0.347 mi.) N91 485
Database: LUST REG 9, Date of Government Version: 03/01/2001
Case Number: 9UT4090
Status: Preliminary site assessment underway

SHELL ***7180 BROADWAY*** ***SW 1/4 - 1/2 (0.349 mi.)*** ***P92*** ***486***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Case Number: 9UT543
Closed Date: 3/4/87
Status: Case Closed

SHELL ***7180 BROADWAY*** ***SW 1/4 - 1/2 (0.349 mi.)*** ***P94*** ***535***
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T0608127577

91739 ***7209 BROADWAY*** ***SW 1/4 - 1/2 (0.349 mi.)*** ***P95*** ***548***
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T0607301425

CHEVRON ***7209 BROADWAY*** ***SW 1/4 - 1/2 (0.349 mi.)*** ***P96*** ***578***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Case Number: 9UT2676
Status: Preliminary site assessment underway

CULLIGAN WATER / U.S 3536 OLIVE STREET ESE 1/4 - 1/2 (0.353 mi.) O97 625
Database: LUST REG 9, Date of Government Version: 03/01/2001

Case Number: 9UT4100
Status: Preliminary site assessment underway

CULLIGAN WATER CONDI ***3536 OLIVE ST*** ***ESE 1/4 - 1/2 (0.353 mi.)*** ***O98*** ***626***
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T0607391318

CULLIGEN WATER CONDI ***3515 OLIVE*** ***ESE 1/4 - 1/2 (0.377 mi.)*** ***Q100*** ***634***
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T0607300254

CULLIGEN WATER CONDI 3515 OLIVE ST ESE 1/4 - 1/2 (0.377 mi.) Q101 644
Database: LUST REG 9, Date of Government Version: 03/01/2001
Case Number: 9UT142
Closed Date: 9/22/95
Status: Case Closed

WALGREENS #12915 ***7195 BROADWAY*** ***SW 1/4 - 1/2 (0.393 mi.)*** ***R103*** ***645***
Database: LUST, Date of Government Version: 12/02/2022
Status: Completed - Case Closed
Global Id: T10000002225

LEMON GROVE PROPERTY ***7770 BROADWAY*** ***SE 1/4 - 1/2 (0.437 mi.)*** ***S106*** ***672***
Database: LUST REG 9, Date of Government Version: 03/01/2001
Database: LUST, Date of Government Version: 12/02/2022
Case Number: 9UT3140
Closed Date: 5/17/96
Status: Completed - Case Closed
Status: Case Closed
Global Id: T0607301909

CPS-SLIC: Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the CPS-SLIC list, as provided by EDR, has revealed that there are 17 CPS-SLIC sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HONDA OF LEMON GROVE	***3611 LEMON GROVE AV***	***E 1/4 - 1/2 (0.453 mi.)***	***107***	***676***

Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: SLT19775610

Lower Elevation	Address	Direction / Distance	Map ID	Page
FHCSD PARKING LOT -	***7580 NORTH AVENUE***	***SE 1/8 - 1/4 (0.202 mi.)***	***G34***	***149***

Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Open - Site Assessment
Global Id: T10000008740

ARCO #01710 ***3775 MASSACHUSETTS A*** ***WSW 1/8 - 1/4 (0.214 mi.)*** ***H41*** ***173***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed

Global Id: T0608128337

LEMON GROVE AUTO ***3465 CITRUS ST*** ***SSW 1/8 - 1/4 (0.233 mi.)*** ***J57*** ***278***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T06019701630

COMMERCIAL PROPERTY ***7666 NORTH AVENUE*** ***ESE 1/4 - 1/2 (0.283 mi.)*** ***72*** ***397***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Open - Site Assessment
Global Id: T10000007719

WORLD OIL ENVIRONMEN ***7608 BROADWAY*** ***SE 1/4 - 1/2 (0.320 mi.)*** ***N79*** ***425***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T0608199117

UNION OIL SERVICE ST ***7593 BROADWAY*** ***SE 1/4 - 1/2 (0.331 mi.)*** ***N83*** ***454***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T0607302939

TOSCO 76 #3699 ***7593 BROADWAY*** ***SE 1/4 - 1/2 (0.331 mi.)*** ***N85*** ***463***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Open - Site Assessment
Global Id: T10000004737

THOMAS F DAVISON ***7204 BROADWAY*** ***SW 1/4 - 1/2 (0.339 mi.)*** ***P87*** ***467***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T0608118033

SHELL ***7180 BROADWAY*** ***SW 1/4 - 1/2 (0.349 mi.)*** ***P94*** ***535***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T0608116355
Global Id: T0608149780
Global Id: T0607302834
Global Id: T0608103864
Global Id: T0608184911

91739 ***7209 BROADWAY*** ***SW 1/4 - 1/2 (0.349 mi.)*** ***P95*** ***548***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T0608193347

CITRONICA II ***3595 OLIVE AVENUE*** ***ESE 1/4 - 1/2 (0.374 mi.)*** ***Q99*** ***633***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Open - Site Assessment
Global Id: T10000004536

CULLIGEN WATER CONDI ***3515 OLIVE*** ***ESE 1/4 - 1/2 (0.377 mi.)*** ***Q100*** ***634***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T10000006534

LEMON GROVE AVENUE R ***7750 NORTH AVENUE*** ***ESE 1/4 - 1/2 (0.379 mi.)*** ***Q102*** ***644***
Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T10000000415

ROCK LIQUOR, 7161 BR ***7161 BROADWAY*** ***SW 1/4 - 1/2 (0.401 mi.)*** ***R104*** ***668***
Database: CPS-SLIC, Date of Government Version: 12/02/2022

Facility Status: Completed - Case Closed
Global Id: T10000001807

MAIN STREET PROMENAD	***3466-3530 MAIN ST***	***ESE 1/4 - 1/2 (0.429 mi.)***	***S105***	***669***

Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T10000004282

WELLS FARGO BANK	***7060 BROADWAY***	***WSW 1/4 - 1/2 (0.485 mi.)***	***108***	***677***

Database: CPS-SLIC, Date of Government Version: 12/02/2022
Facility Status: Completed - Case Closed
Global Id: T0608104733

Lists of state and tribal registered storage tanks

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, has revealed that there are 5 UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FOOD 4 LESS FUEL CEN	7428 BROADWAY	SSE 1/8 - 1/4 (0.181 mi.)	E22	48
Database: UST, Date of Government Version: 12/02/2022 Facility Id: 37-000-000798				
ALIA PETROLEUM INC.	3775 MASSACHUSETTS A	WSW 1/8 - 1/4 (0.214 mi.)	H43	239
Database: UST, Date of Government Version: 12/02/2022 Facility Id: 37-000-207982				
AMACA PROPERTIES LLC	3775 MASSACHUSETTS A	WSW 1/8 - 1/4 (0.214 mi.)	H45	243
Database: UST, Date of Government Version: 12/02/2022 Facility Id: 37-000-207982				
ARCO #1710	3775 MASSACHUSETTS A	WSW 1/8 - 1/4 (0.214 mi.)	H46	244
Database: UST, Date of Government Version: 12/02/2022 Facility Id: H13041				
CENTER CITY SHELL	3810 MASSACHUSETTS A	W 1/8 - 1/4 (0.250 mi.)	L65	354
Database: UST, Date of Government Version: 12/02/2022 Facility Id: 37-000-208832				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: A listing of recycling facilities in California.

A review of the SWRCY list, as provided by EDR, and dated 12/02/2022 has revealed that there is 1 SWRCY site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FOOD 4 LESS STORE #3	***7420 BROADWAY ST***	***S 1/4 - 1/2 (0.251 mi.)***	***70***	***369***
Cert Id: RC295745.001				

Local Lists of Hazardous waste / Contaminated Sites

CERS HAZ WASTE: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

A review of the CERS HAZ WASTE list, as provided by EDR, and dated 01/05/2023 has revealed that there are 8 CERS HAZ WASTE sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FOOD 4 LESS FUEL CEN	***7428 BROADWAY***	***SSE 1/8 - 1/4 (0.181 mi.)***	***E23***	***49***
LEMON GROVE VETERINA	***7572 NORTH AVE***	***SE 1/8 - 1/4 (0.195 mi.)***	***G28***	***124***
PRONTO AUTO REPAIR	***7385 LEMON AVE***	***S 1/8 - 1/4 (0.196 mi.)***	***E29***	***127***
COLLISION EXPERTS	***3463 HARRIS ST STE A***	***S 1/8 - 1/4 (0.203 mi.)***	***D36***	***152***
ARCO #01710	***3775 MASSACHUSETTS A***	***WSW 1/8 - 1/4 (0.214 mi.)***	***H41***	***173***
SUPERIOR SMOG AND TU	***7586 NORTH AVE***	***SE 1/8 - 1/4 (0.216 mi.)***	***G51***	***254***
SAN DIEGO PET HOSPIT	***7368 BROADWAY***	***S 1/8 - 1/4 (0.223 mi.)***	***I55***	***274***
SHELL	***3810 MASSACHUSETTS A***	***W 1/8 - 1/4 (0.250 mi.)***	***L64***	***297***

Local Lists of Registered Storage Tanks

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 5 SWEEPS UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
VIKING FENCE AT0236	***3529 HARRIS ST***	***SSW 1/8 - 1/4 (0.176 mi.)***	***D21***	***47***
Status: A				
Comp Number: 4919				
W.E. WALTERS & SONS	***3494 HARRIS ST***	***SSW 1/8 - 1/4 (0.198 mi.)***	***D32***	***145***
Status: A				
Comp Number: 5592				
PRESTIGE STATIONS IN	3775 MASSACHUSETTS A	WSW 1/8 - 1/4 (0.214 mi.)	H47	245
Status: A				
Tank Status: A				
Comp Number: 13041				
LEMON GROVE U RENT	***7370 BROADWAY***	***S 1/8 - 1/4 (0.239 mi.)***	***I59***	***285***
Status: A				
Comp Number: 12151				
CENTRE CITY SHELL 2	***3810 MASSACHUSETTS A***	***W 1/8 - 1/4 (0.250 mi.)***	***L63***	***294***

Status: A
Tank Status: A
Comp Number: 12440

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 3 HIST UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
PRESTIGE STATIONS IN Facility Id: 00000026612	3775 MASSACHUSETTS A	WSW 1/8 - 1/4 (0.214 mi.)	H42	238
LEMON GROVE U-RENT Facility Id: 00000067245	7370 BROADWAY	S 1/8 - 1/4 (0.239 mi.)	I58	284
CENTRE CITY SHELL 2 Facility Id: 00000056628	***3810 MASSACHUSETTS A***	***W 1/8 - 1/4 (0.250 mi.)***	***L63***	***294***

CERS TANKS: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

A review of the CERS TANKS list, as provided by EDR, and dated 01/06/2023 has revealed that there are 3 CERS TANKS sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FOOD 4 LESS FUEL CEN	***7428 BROADWAY***	***SSE 1/8 - 1/4 (0.181 mi.)***	***E23***	***49***
ARCO #01710	***3775 MASSACHUSETTS A***	***WSW 1/8 - 1/4 (0.214 mi.)***	***H41***	***173***
SHELL	***3810 MASSACHUSETTS A***	***W 1/8 - 1/4 (0.250 mi.)***	***L64***	***297***

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 11/21/2022 has revealed that there are 25 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BRUCE BARAW EPA ID:: CAC003100295	3889 HARRIS STREET	NNW 0 - 1/8 (0.059 mi.)	15	32
DEBBIE TERRELL EPA ID:: CAC003020827	3951 APORE STREET	NE 1/8 - 1/4 (0.217 mi.)	53	269

Lower Elevation	Address	Direction / Distance	Map ID	Page
STEVE MCELFRESH	3743 HARRIS ST.	SW 0 - 1/8 (0.038 mi.)	B13	27

EPA ID:: CAC003155962				
ROBERTA SLATER EPA ID:: CAC003155499	3743 HARRIS ST.	SW 0 - 1/8 (0.038 mi.)	B14	29
KEVIN FERREE EPA ID:: CAC003081971	3775 CITRUS STREET	WSW 0 - 1/8 (0.098 mi.)	C16	34
DIANDRA LAUIFI EPA ID:: CAC003032180	3766 CITRUS ST	WSW 0 - 1/8 (0.118 mi.)	C17	37
PEDRO& MARIA FAJARDO EPA ID:: CAC003051533	3760 CITRUS STREET	WSW 0 - 1/8 (0.120 mi.)	C18	39
JOAN SANCHEZ EPA ID:: CAC002978312	3736 CITRUS ST.	WSW 0 - 1/8 (0.124 mi.)	C19	42
WESTSTAR LANDSCAPE EPA ID:: CAL000245004	3553 HARRIS ST	SSW 1/8 - 1/4 (0.157 mi.)	D20	44
JOE YOUSIF EPA ID:: CAC003123891	3521 HARRIS ST.	SSW 1/8 - 1/4 (0.182 mi.)	D25	116
PAUL EK EPA ID:: CAC003162561	3590 CITRUS STREET	SW 1/8 - 1/4 (0.182 mi.)	F26	119
JOE YOUSIF EPA ID:: CAC003131552	3515-3521 HARRIS ST	SSW 1/8 - 1/4 (0.185 mi.)	D27	121
PRONTO AUTO REPAIR EPA ID:: CAL000267951	7385 LEMON AVE	S 1/8 - 1/4 (0.196 mi.)	E30	139
PORTILLO CONCRETE IN EPA ID:: CAL000361316	3527 CITRUS ST	SSW 1/8 - 1/4 (0.199 mi.)	F33	146
A&A COLLEX EXPERTS I EPA ID:: CAL000375401	3463 HARRIS ST	S 1/8 - 1/4 (0.203 mi.)	D35	150
COLLISION EXPERTS EPA ID:: CAL000333199	3463 HARRIS ST STE A	S 1/8 - 1/4 (0.203 mi.)	D37	166
ALIA PETROLEUM INC. EPA ID:: CAL000409613	3775 MASSACHUSETTS A	WSW 1/8 - 1/4 (0.214 mi.)	H39	169
ARCO FACILITY NO 017 EPA ID:: CAR000105551	***3775 MASSACHUSETTS A***	***WSW 1/8 - 1/4 (0.214 mi.)***	***H44***	***240***
MODERN AUTO REPAIR EPA ID:: CAC002979403	7586 NORTH AVE	SE 1/8 - 1/4 (0.216 mi.)	G49	249
MODERN AUTO REPAIR EPA ID:: CAL000439823	7586 NORTH AVE	SE 1/8 - 1/4 (0.216 mi.)	G50	251
SUPERIOR SMOG AND TU EPA ID:: CAL000463552	7586 NORTH AVE	SE 1/8 - 1/4 (0.216 mi.)	G52	267
PP-CA LP DBA SAN DIE EPA ID:: CAL000466725	7368 BROADWAY STE A	S 1/8 - 1/4 (0.223 mi.)	I54	272
ANGIES TOWING INC DB EPA ID:: CAL000471384	7620 NORTH AVE	ESE 1/8 - 1/4 (0.242 mi.)	K60	286
BONK'S GENERAL AUTOM EPA ID:: CAL000081770	7620 NORTH AVE	ESE 1/8 - 1/4 (0.242 mi.)	K62	292
CENTRE CITY SHELL EPA ID:: CAL000335218	3810 MASSACHUSETTS A	W 1/8 - 1/4 (0.250 mi.)	L68	365

EXECUTIVE SUMMARY

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 12/14/2022 has revealed that there are 16 Cortese sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARCO #01710	***3775 MASSACHUSETTS A***	***WSW 1/8 - 1/4 (0.214 mi.)***	***H40***	***171***
Cleanup Status: COMPLETED - CASE CLOSED				
LEMON GROVE AUTO	***3465 CITRUS ST***	***SSW 1/8 - 1/4 (0.233 mi.)***	***J57***	***278***
Cleanup Status: COMPLETED - CASE CLOSED				
SHELL	***3810 MASSACHUSETTS A***	***W 1/8 - 1/4 (0.250 mi.)***	***L69***	***367***
Cleanup Status: COMPLETED - CASE CLOSED				
CORRAL FORD	***3470 VISTA AV***	***SW 1/4 - 1/2 (0.272 mi.)***	***71***	***393***
Cleanup Status: COMPLETED - CASE CLOSED				
USA PETROLEUM	***7505 BROADWAY***	***SSE 1/4 - 1/2 (0.285 mi.)***	***M74***	***409***
Cleanup Status: OPEN - REMEDIATION				
SAN DIEGO GLASS & PA	***7551 BROADWAY***	***SSE 1/4 - 1/2 (0.299 mi.)***	***M75***	***417***
Cleanup Status: COMPLETED - CASE CLOSED				
ECONO LUBE N TUNE	***7608 BROADWAY***	***SE 1/4 - 1/2 (0.320 mi.)***	***N78***	***423***
Cleanup Status: COMPLETED - CASE CLOSED				
SAN DIEGO MOTORS	***7593 BROADWAY***	***SE 1/4 - 1/2 (0.331 mi.)***	***N84***	***456***
Cleanup Status: COMPLETED - CASE CLOSED				
DAVES MOBIL OIL STN	***7204 BROADWAY***	***SW 1/4 - 1/2 (0.339 mi.)***	***P88***	***469***
Cleanup Status: COMPLETED - CASE CLOSED				
7-ELEVEN FOOD STORE	***7607 BROADWAY***	***SE 1/4 - 1/2 (0.347 mi.)***	***N89***	***478***
Cleanup Status: COMPLETED - CASE CLOSED				
TEXACO REFINING AND	***7180 BROADWAY***	***SW 1/4 - 1/2 (0.349 mi.)***	***P93***	***530***
Cleanup Status: COMPLETED - CASE CLOSED				
CHEVRON	***7209 BROADWAY***	***SW 1/4 - 1/2 (0.349 mi.)***	***P96***	***578***
Cleanup Status: COMPLETED - CASE CLOSED				
CULLIGAN WATER CONDI	***3536 OLIVE ST***	***ESE 1/4 - 1/2 (0.353 mi.)***	***O98***	***626***
Cleanup Status: COMPLETED - CASE CLOSED				
CULLIGEN WATER CONDI	***3515 OLIVE***	***ESE 1/4 - 1/2 (0.377 mi.)***	***Q100***	***634***
Cleanup Status: COMPLETED - CASE CLOSED				
WALGREENS #12915	***7195 BROADWAY***	***SW 1/4 - 1/2 (0.393 mi.)***	***R103***	***645***
Cleanup Status: COMPLETED - CASE CLOSED				
LEMON GROVE PROPERTY	***7770 BROADWAY***	***SE 1/4 - 1/2 (0.437 mi.)***	***S106***	***672***
Cleanup Status: COMPLETED - CASE CLOSED				

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there are 11 HIST CORTESE sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
ARCO #01710	***3775 MASSACHUSETTS A***	***WSW 1/8 - 1/4 (0.214 mi.)***	***H41***	***173***

Reg Id: 9UT3531 Reg Id: 9UT1455				
USA PETROLEUM COMPAN Reg Id: 9UT1368	***7505 BROADWAY***	***SSE 1/4 - 1/2 (0.285 mi.)***	***M73***	***398***
SAN DIEGO GLASS AND Reg Id: 9UT51	***7551 BROADWAY***	***SSE 1/4 - 1/2 (0.299 mi.)***	***M76***	***421***
WORLD OIL ENVIRONMEN Reg Id: 9UT688	***7608 BROADWAY***	***SE 1/4 - 1/2 (0.320 mi.)***	***N79***	***425***
CORRAL FORD Reg Id: 9UT2731	***7220 BROADWAY***	***SW 1/4 - 1/2 (0.329 mi.)***	***P81***	***439***
UNOCAL SERVICE STATI Reg Id: 9UT671	***7593 BROADWAY***	***SE 1/4 - 1/2 (0.331 mi.)***	***N82***	***453***
DAVES MOBIL OIL STN Reg Id: 9UT322	***7204 BROADWAY***	***SW 1/4 - 1/2 (0.339 mi.)***	***P88***	***469***
SHELL Reg Id: 9UT543	***7180 BROADWAY***	***SW 1/4 - 1/2 (0.349 mi.)***	***P92***	***486***
CHEVRON Reg Id: 9UT2676	***7209 BROADWAY***	***SW 1/4 - 1/2 (0.349 mi.)***	***P96***	***578***
CULLIGEN WATER CONDI Reg Id: 9UT142	***3515 OLIVE***	***ESE 1/4 - 1/2 (0.377 mi.)***	***Q100***	***634***
LEMON GROVE PROPERTY Reg Id: 9UT3140	***7770 BROADWAY***	***SE 1/4 - 1/2 (0.437 mi.)***	***S106***	***672***

HAZNET: The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000-1,000,000 annually, representing approximately 350,000-500,000 shipments. Data from non-California manifests & continuation sheets are not included at the present time. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, & disposal method. The source is the Department of Toxic Substance Control is the agency. This database begins with calendar year 1993.

A review of the HAZNET list, as provided by EDR, and dated 12/31/2021 has revealed that there is 1 HAZNET site within approximately 0.001 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
1X COUNTY OF SAN DIE GEPAID: CAH777000137	***7400 WAITE DRIVE***	***0 - 1/8 (0.000 mi.)***	***A12***	***26***

Notify 65: Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.


A review of the Notify 65 list, as provided by EDR, and dated 12/07/2022 has revealed that there are 2 Notify 65 sites within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	7656 LEMON ST	SE 1/4 - 1/2 (0.323 mi.)	O80	439
7-ELEVEN STORE #1745	***7733 PALM AVENUE***	***SSE 1/2 - 1 (0.884 mi.)***	***113***	***731***

EXECUTIVE SUMMARY

There were no unmapped sites in this report.

OVERVIEW MAP - 7276918.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	LA Mesa Park Site	CLIENT:	Bodhi Group
ADDRESS:	7410 Waite Drive LA Mesa CA 91941	CONTACT:	Natalie Krage
LAT/LONG:	32.746893 / 117.038301	INQUIRY #:	7276918.2s
		DATE:	March 13, 2023 8:39 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 7276918.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

0 1/16 1/8 1/4 Miles

Indian Reservations BIA

Power transmission lines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory

State Wetlands

Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	LA Mesa Park Site	CLIENT:	Bodhi Group
ADDRESS:	7410 Waite Drive LA Mesa CA 91941	CONTACT:	Natalie Krage
		INQUIRY #:	7276918.2s
LAT/LONG:	32.746893 / 117.038301	DATE:	March 13, 2023 8:40 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	2	NR	NR	NR	2
RCRA-SQG	0.250	1	0	2	NR	NR	NR	3
RCRA-VSQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
Lists of state- and tribal (Superfund) equivalent sites								
RESPONSE	1.000		0	0	0	0	NR	0
Lists of state- and tribal hazardous waste facilities								
ENVIROSTOR	1.000		0	1	0	4	NR	5
Lists of state and tribal landfills and solid waste disposal facilities								
SWF/LF	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Lists of state and tribal leaking storage tanks								
SAN DIEGO CO. SAM	0.500	1	0	3	14	NR	NR	18
LUST	0.500	2	0	5	24	NR	NR	31
INDIAN LUST	0.500		0	0	0	NR	NR	0
CPS-SLIC	0.500		0	3	14	NR	NR	17
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250		0	5	NR	NR	NR	5
AST	0.250		0	0	NR	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
Lists of state and tribal voluntary cleanup sites								
INDIAN VCP	0.500		0	0	0	NR	NR	0
VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
WMUDS/SWAT	0.500		0	0	0	NR	NR	0
SWRCY	0.500		0	0	1	NR	NR	1
HAULERS	0.001		0	NR	NR	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
HIST Cal-Sites	1.000		0	0	0	0	NR	0
SCH	0.250		0	0	NR	NR	NR	0
CDL	0.001		0	NR	NR	NR	NR	0
San Diego Co. HMMD	0.001	1	0	NR	NR	NR	NR	1
CERS HAZ WASTE	0.250		0	8	NR	NR	NR	8
Toxic Pits	1.000		0	0	0	0	NR	0
US CDL	0.001		0	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
SWEEPS UST	0.250	1	0	5	NR	NR	NR	6
HIST UST	0.250	2	0	3	NR	NR	NR	5
CERS TANKS	0.250		0	3	NR	NR	NR	3

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
CA FID UST	0.250		0	0	NR	NR	NR	0
Local Land Records								
LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
DEED	0.500		0	0	0	NR	NR	0
Records of Emergency Release Reports								
HMIRS	0.001		0	NR	NR	NR	NR	0
CHMIRS	0.001		0	NR	NR	NR	NR	0
LDS	0.001		0	NR	NR	NR	NR	0
MCS	0.001		0	NR	NR	NR	NR	0
SPILLS 90	0.001		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		7	18	NR	NR	NR	25
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	0.001	2	0	NR	NR	NR	NR	2
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
ECHO	0.001	1	0	NR	NR	NR	NR	1
UXO	1.000		0	0	0	0	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	0	NR	NR	NR	0
PFAS ECHO FIRE TRAINING	0.250		0	0	NR	NR	NR	0
PFAS PART 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
PFAS	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM	TP		NR	NR	NR	NR	NR	0
CA BOND EXP. PLAN	1.000		0	0	0	0	NR	0
Cortese	0.500	1	0	3	13	NR	NR	17
CUPA Listings	0.250		0	0	NR	NR	NR	0
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
EMI	0.001		0	NR	NR	NR	NR	0
ENF	0.001		0	NR	NR	NR	NR	0
Financial Assurance	0.001		0	NR	NR	NR	NR	0
ICE	0.001		0	NR	NR	NR	NR	0
HIST CORTESE	0.500	1	0	1	10	NR	NR	12
HWP	1.000		0	0	0	0	NR	0
HWT	0.250		0	0	NR	NR	NR	0
HAZNET	0.001	2	1	NR	NR	NR	NR	3
MINES	0.250		0	0	NR	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
NPDES	0.001		0	NR	NR	NR	NR	0
PEST LIC	0.001		0	NR	NR	NR	NR	0
PROC	0.500		0	0	0	NR	NR	0
Notify 65	1.000		0	0	1	1	NR	2
UIC	0.001		0	NR	NR	NR	NR	0
UIC GEO	0.001		0	NR	NR	NR	NR	0
WASTEWATER PITS	0.500		0	0	0	NR	NR	0
WDS	0.001		0	NR	NR	NR	NR	0
WIP	0.250		0	0	NR	NR	NR	0
MILITARY PRIV SITES	0.001		0	NR	NR	NR	NR	0
PROJECT	0.001		0	NR	NR	NR	NR	0
WDR	0.001		0	NR	NR	NR	NR	0
SAN DIEGO CO LOP	0.001	1	0	NR	NR	NR	NR	1
CIWQS	0.001		0	NR	NR	NR	NR	0
CERS	0.001	1	0	NR	NR	NR	NR	1
NON-CASE INFO	0.001		0	NR	NR	NR	NR	0
OTHER OIL GAS	0.001		0	NR	NR	NR	NR	0
PROD WATER PONDS	0.001		0	NR	NR	NR	NR	0
SAMPLING POINT	0.001		0	NR	NR	NR	NR	0
WELL STIM PROJ	0.001		0	NR	NR	NR	NR	0
HWTS	TP	3	NR	NR	NR	NR	NR	3
MINES MRDS	0.001		0	NR	NR	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.000		0	0	0	0	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA LF	0.001		0	NR	NR	NR	NR	0
RGA LUST	0.001	4	0	NR	NR	NR	NR	4
- Totals --		24	8	62	77	5	0	176

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **LEMON GROVE STATION-COUNTY** **HIST UST** **S113066979**
Target **7410 WAITE DRIVE** **HAZNET** **N/A**
Property **LA MESA, CA 92041** **HWTS**

Site 1 of 12 in cluster A

Actual:
471 ft.

HIST UST:

Name:	LEMON GROVE STATION-COUNTY
Address:	7410 WAITE DRIVE
City,State,Zip:	LA MESA, CA 92041
File Number:	0002b01c
URL:	https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002b01c.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

HAZNET:

Name:	COUNTY OF SAN DIEGO/PUBLIC WORKS
Address:	7410 WAITE DR
Address 2:	Not reported
City,State,Zip:	LA MESA, CA 920410000
Contact:	GORDEN MARTINEZ MS 0337/SPEC
Telephone:	6194955920
Mailing Name:	Not reported
Mailing Address:	5555 OVERLAND AVE
Year:	1994
Gepaid:	CAL000117335
TSD EPA ID:	CAT080013352
CA Waste Code:	241 - Tank bottom waste
Disposal Method:	R01 - Recycler
Tons:	1.251

Additional Info:

Year:	1994
Gen EPA ID:	CAL000117335
Shipment Date:	19940202
Creation Date:	10/19/1995 0:00:00

LEMON GROVE STATION-COUNTY (Continued) **S113066979**

Receipt Date:	19941028
Manifest ID:	93050910
Trans EPA ID:	CAD981427511
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080013352
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	241 - Tank bottom waste 251 Still bottoms with halogenated organics
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	1.251
Waste Quantity:	300
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HWTS:

Name:	COUNTY OF SAN DIEGO/PUBLIC WORKS
Address:	7410 WAITE DR
Address 2:	Not reported
City,State,Zip:	LA MESA, CA 92041
EPA ID:	CAL000117335
Inactive Date:	06/30/1998
Create Date:	02/02/1994
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	5555 OVERLAND AVE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SAN DIEGO, CA 921231219
Owner Name:	COUNTY OF SAN DIEGO PUB WORKS
Owner Address:	5555 OVERLAND AVE
Owner Address 2:	Not reported
Owner City,State,Zip:	SAN DIEGO, CA 921231219
Contact Name:	GORDEN MARTINEZ MS 0337/SPEC
Contact Address:	INACT PER 98VQ FINAL NOTICE
Contact Address 2:	Not reported
City,State,Zip:	SAN DIEGO, CA 921231219
Facility Status:	Inactive
Facility Type:	PERMANENT
Category:	STATE
Latitude:	32.825494
Longitude:	-116.925674

A2 **COUNTY OF SAN DIEGO (SERVICE FACILITY)** **HAZNET** **S123774959**
Target **7410 WAITE DR** **HWTS** **N/A**
Property **LA MESA, CA 92041**

Site 2 of 12 in cluster A

Actual:
471 ft.

HAZNET:

Name:	COUNTY OF SAN DIEGO (SERVICE FACILITY)
Address:	7410 WAITE DR
Address 2:	Not reported
City,State,Zip:	LA MESA, CA 920410000
Contact:	UNDELIVERABLE SURVEY 2-1-95 HJ
Telephone:	6194605232
Mailing Name:	Not reported
Mailing Address:	--
Year:	1986
Gepaid:	CAX000079574
TSD EPA ID:	CAT080013352
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	R01 - Recycler
Tons:	0.8131
Year:	1985
Gepaid:	CAX000079574
TSD EPA ID:	Not reported
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	-
Tons:	0.9382
Year:	1985
Gepaid:	CAX000079574
TSD EPA ID:	CAT080013352
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	R01 - Recycler
Tons:	0.7297
Year:	1984
Gepaid:	CAX000079574
TSD EPA ID:	CAD008352890
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	R01 - Recycler
Tons:	1.0425

HWTS:

Name:	COUNTY OF SAN DIEGO (SERVICE FACILITY)
Address:	7410 WAITE DR
Address 2:	Not reported
City,State,Zip:	LA MESA, CA 92041
EPA ID:	CAX000079574
Inactive Date:	04/30/1986
Create Date:	05/10/1984
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	Not reported
Mailing Address 2:	Not reported
Mailing City,State,Zip:	LA MESA, CA 920410000
Owner Name:	Not reported

COUNTY OF SAN DIEGO (SERVICE FACILITY) (Continued) **S123774959**

Owner Address:	Not reported
Owner Address 2:	Not reported
Owner City,State,Zip:	Not reported
Contact Name:	UNDELIVERABLE SURVEY 2-1-95 HJ
Contact Address:	Not reported
Contact Address 2:	Not reported
City,State,Zip:	Not reported
Facility Status:	Inactive
Facility Type:	PERMANENT
Category:	STATE
Latitude:	32.825494
Longitude:	-116.925674

A3 **COUNTY OF SD-FLEET OPS LEM** **RGA LUST** **S114607344**
Target **7410 WAITE DR** **N/A**
Property **SAN DIEGO, CA**

Site 3 of 12 in cluster A

Actual: **471 ft.**

RGA LUST:

Name:	COUNTY OF SD-FLEET OPS LEM
Address:	7410 WAITE DR
City:	SAN DIEGO
State:	SAN DIEGO

2004 COUNTY OF SD-FLEET OPS LEM 7410 WAITE DR

A4 **S D CNTY GEN SVCS AUTO SVC** **RGA LUST** **S114679677**
Target **7410 WAITE DR** **N/A**
Property **LA MESA, CA**

Site 4 of 12 in cluster A

Actual: **471 ft.**

RGA LUST:

Name:	S D CNTY GEN SVCS AUTO SVC
Address:	7410 WAITE DR
City:	LA MESA
State:	LA MESA

2012 S D CNTY GEN SVCS AUTO SVC 7410 WAITE DR

Name:	S D CNTY GEN SVCS AUTO SVC
Address:	7410 WAITE DR
City:	LA MESA
State:	LA MESA

2011 S D CNTY GEN SVCS AUTO SVC 7410 WAITE DR

Name:	S D CNTY GEN SVCS AUTO SVC
Address:	7410 WAITE DR
City:	LA MESA
State:	LA MESA

2010 S D CNTY GEN SVCS AUTO SVC 7410 WAITE DR

Name:	S D CNTY GEN SVCS AUTO SVC
Address:	7410 WAITE DR
City:	LA MESA
State:	LA MESA

2009 S D CNTY GEN SVCS AUTO SVC 7410 WAITE DR

Name:	S D CNTY GEN SVCS AUTO SVC
Address:	7410 WAITE DR
City:	LA MESA

S D CNTY GEN SVCS AUTO SVC (Continued) **S114679677**

State: LA MESA
2008 S D CNTY GEN SVCS AUTO SVC 7410 WAITE DR
Name: S D CNTY GEN SVCS AUTO SVC
Address: 7410 WAITE DR
City: LA MESA
State: LA MESA
2007 S D CNTY GEN SVCS AUTO SVC 7410 WAITE DR
Name: S D CNTY GEN SVCS AUTO SVC
Address: 7410 WAITE DR
City: LA MESA
State: LA MESA
2006 S D CNTY GEN SVCS AUTO SVC 7410 WAITE DR
Name: S D CNTY GEN SVCS AUTO SVC
Address: 7410 WAITE DR
City: LA MESA
State: LA MESA
2005 S D CNTY GEN SVCS AUTO SVC 7410 WAITE DR

A5 **LEMON GROVE SERVICE STATION** **HWTS** **S124747622**
Target Property **7410 WAITE DR** **N/A**
LAMESA, CA 92041

Site 5 of 12 in cluster A

Actual: 471 ft.

HWTS:

Name:	LEMON GROVE SERVICE STATION
Address:	7410 WAITE DR
Address 2:	Not reported
City,State,Zip:	LAMESA, CA 92041
EPA ID:	CAD981694979
Inactive Date:	01/01/1995
Create Date:	04/10/1987
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	5555 DUERLAND AVE MS 019
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SAN DIEGO, CA 921230000
Owner Name:	Not reported
Owner Address:	Not reported
Owner Address 2:	Not reported
Owner City,State,Zip:	Not reported
Contact Name:	CANCEL PER SURVEY 1-27-95 LC
Contact Address:	Not reported
Contact Address 2:	Not reported
City,State,Zip:	Not reported
Facility Status:	Inactive
Facility Type:	PERMANENT
Category:	FEDERAL
Latitude:	32.746736
Longitude:	-117.037544

A6 **FLEET OPERATIONS LEMON GROVE** **RGA LUST** **S114620950**
Target Property **7410 WAITE DR** **N/A**
LEMON GROVE, CA

Site 6 of 12 in cluster A

Actual: 471 ft.

RGA LUST:

Name:	FLEET OPERATIONS LEMON GROVE		
Address:	7410 WAITE DR		
City:	LEMON GROVE		
State:	LEMON GROVE		
	2002	FLEET OPERATIONS LEMON GROVE	7410 WAITE DR
Name:	FLEET OPERATIONS LEMON GROVE		
Address:	7410 WAITE DR		
City:	LEMON GROVE		
State:	LEMON GROVE		
	2001	FLEET OPERATIONS LEMON GROVE	7410 WAITE DR
Name:	FLEET OPERATIONS LEMON GROVE		
Address:	7410 WAITE DR		
City:	LEMON GROVE		
State:	LEMON GROVE		
	2000	FLEET OPERATIONS LEMON GROVE	7410 WAITE DR
Name:	FLEET OPERATIONS LEMON GROVE		
Address:	7410 WAITE DR		
City:	LEMON GROVE		
State:	LEMON GROVE		
	1998	FLEET OPERATIONS LEMON GROVE	7410 WAITE DR
Name:	FLEET OPERATIONS LEMON GROVE		
Address:	7410 WAITE DR		
City:	LEMON GROVE		
State:	LEMON GROVE		
	1997	FLEET OPERATIONS LEMON GROVE	7410 WAITE DR
Name:	FLEET OPERATIONS LEMON GROVE		
Address:	7410 WAITE DR		
City:	LEMON GROVE		
State:	LEMON GROVE		
	1996	FLEET OPERATIONS LEMON GROVE	7410 WAITE DR
Name:	FLEET OPERATIONS LEMON GROVE		
Address:	7410 WAITE DR		
City:	LEMON GROVE		
State:	LEMON GROVE		
	1995	FLEET OPERATIONS LEMON GROVE	7410 WAITE DR
Name:	FLEET OPERATIONS LEMON GROVE		
Address:	7410 WAITE DR		
City:	LEMON GROVE		
State:	LEMON GROVE		
	1994	FLEET OPERATIONS LEMON GROVE	7410 WAITE DR

A7 **S D CNTY GEN SVCS AUTO SVC (LEMON GROVE ROAD STATI** **FINDS** **1023328902**
Target Property **7410 WAITE DR** **N/A**
LA MESA, CA 91941

Site 7 of 12 in cluster A

Actual: 471 ft.

FINDS:
Registry ID: 110066233294

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:

S D CNTY GEN SVCS AUTO SVC (LEMON GROVE ROAD STATION) (Continued) **1023328902**

STATE MASTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A8 **LEMON GROVE SERVICE STATION** **RCRA-SQG** **1000336853**
Target **7410 WAITE DR** **HIST UST** **CAD981694979**
Property **LA MESA, CA 91941** **FINDS**
ECHO

Site 8 of 12 in cluster A

Actual:
471 ft.

RCRA Listings:

Date Form Received by Agency:		19861230
Handler Name:	LEMON GROVE SERVICE STATION	
Handler Address:		7410 WAITE DR
Handler City,State,Zip:		LA MESA, CA 91941
EPA ID:		CAD981694979
Contact Name:		ENVIRONMENTAL MANAGER
Contact Address:		7410 WAITE DR
Contact City,State,Zip:		LA MESA, CA 92041
Contact Telephone:		619-565-5444
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Other
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		CA
State District:		4
Mailing Address:		5555 DUERLAND AVE MS 019
Mailing City,State,Zip:		SAN DIEGO, CA 92123
Owner Name:	COUNTY OF SAN DIEGO	
Owner Type:		Private
Operator Name:	NOT REQUIRED	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported

LEMON GROVE SERVICE STATION (Continued) **1000336853**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20020627
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NOT REQUIRED	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: COUNTY OF SAN DIEGO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999

LEMON GROVE SERVICE STATION (Continued) **1000336853**

Owner/Operator Telephone: 415-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19861230
Handler Name: LEMON GROVE SERVICE STATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

HIST UST:
Name: LEMON GROVE STATION-COUNTY
Address: 7410 WAITE DR
City,State,Zip: LA MESA, CA 92041
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000044130
Facility Type: Gas Station
Other Type: Not reported
Contact Name: DON MADISON (565-5444)
Telephone: 6194605232
Owner Name: COUNTY OF SAN DIEGO
Owner Address: 5555 OVERLAND AVE.
Owner City,St,Zip: SAN DIEGO, CA 92123
Total Tanks: 0002

Tank Num: 001
Container Num: GS012
Year Installed: Not reported
Tank Capacity: 00008000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: Not reported
Leak Detection: None

LEMON GROVE SERVICE STATION (Continued) **1000336853**

Tank Num:	002
Container Num:	GS013
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	None

FINDS:
Registry ID: 110006474207

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000336853
Registry ID:	110006474207
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006474207
Name:	LEMON GROVE SERVICE STATION
Address:	7410 WAITE DR
City,State,Zip:	LA MESA, CA 91941

A9 **COUNTY OF SD-FLEET OPS LEM GRV** **RGA LUST** **S114607343**
Target **7410 WAITE DR** **N/A**
Property **LA MESA, CA**

Site 9 of 12 in cluster A

Actual: **471 ft.**

RGA LUST:

Name:	COUNTY OF SD-FLEET OPS LEM GRV
Address:	7410 WAITE DR
City:	LA MESA
State:	LA MESA

2003 COUNTY OF SD-FLEET OPS LEM GRV 7410 WAITE DR

A10 **FLEET OPERATIONS LEMON GROVE** **LUST** **S102430034**
Target **7410 WAITE DR** **N/A**
Property **LEMON GROVE, CA 91945**

Site 10 of 12 in cluster A

Actual: **471 ft.**

LUST REG 9:

Region:	9
Status:	Preliminary site assessment underway
Case Number:	9UT2686
Local Case:	H04820-001

FLEET OPERATIONS LEMON GROVE (Continued) **S102430034**

Substance:	Gasoline
Qty Leaked:	Not reported
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Tank
Cause:	Corrosion
Lead Agency:	Local Agency
Case Type:	Other ground water affected
Date Found:	02/02/1994
Date Stopped:	02/02/1994
Confirm Date:	02/02/1994
Submit Workplan:	2/25/94
Prelim Assess:	03/02/1994
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	02/02/1994
Enforce Date:	Not reported
Closed Date:	Not reported
Enforce Type:	Not reported
Pilot Program:	LOP
Basin Number:	908.22
GW Depth:	12
Beneficial Use:	No Beneficial groundwater use
NPDES Number:	Not reported
Priority:	2B
File Dispn:	File discarded, case closed
Interim Remedial Actions:	Not reported
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

A11 **S D CNTY GEN SVCS AUTO SVC** **LUST** **S101301743**
Target **7410 WAITE DR** **SAN DIEGO CO. SAM** **N/A**
Property **LA MESA, CA 91941** **San Diego Co. HMMD**
SWEEPS UST
Site 11 of 12 in cluster A **Cortese**
HIST CORTESE
Actual: **SAN DIEGO CO LOP**
471 ft. **CERS**

LUST:

Name:	S D CNTY GEN SVCS AUTO SVC (LEMON GROVE ROAD STATION)
Address:	7410 WAITE DR
City,State,Zip:	LA MESA, CA 91941
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301436
Global Id:	T0607301436
Latitude:	32.746486174
Longitude:	-117.038307225
Status:	Completed - Case Closed
Status Date:	12/01/2011
Case Worker:	JS
RB Case Number:	9UT2686
Local Agency:	SAN DIEGO COUNTY LOP

S D CNTY GEN SVCS AUTO SVC (Continued) **S101301743**

File Location: Local Agency
Local Case Number: H04820-001
Potential Media Affect: Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern: Gasoline
Site History: On February 2, 1994, two steel underground storage tanks (USTs) were removed. Soil samples were collected and analyzed under the direction of DEH. Free product was observed in the UST pit by the DEH inspector. Based on laboratory results, case H04820-001 was opened on February 25, 1994. Between April 2000 and October 2007, seven groundwater monitoring wells (MW-1 through MW-7) were installed and two soil borings were advanced (B-1 and B-2). In June 2007, as part of a Corrective Action Plan, 371 cubic yards of soil was excavated and disposed at the Otay Landfill. A total of 36 confirmation soil samples were collected. 1,075 pounds of Oxygen Releasing Compound was added to clean material used to backfill the excavation. Based on soil excavation and assessment activities, soil contamination is limited to the site. The consultant estimates approximately 30 cubic yards of petroleum hydrocarbon impacted soil remains at the site in the area of the former dispensers. Between June 2000 and November 2008, the groundwater was monitored and sampled. The groundwater monitoring events demonstrate that groundwater flow is generally to the south with a westerly component at a gradient of approximately 0.11 foot per foot. Offsite well MW-5 has experienced artesian or near artesian conditions since 2005. Dissolved-phase concentrations in MW-5 have been below laboratory detection limits for all analytes for the last four sampling events. The dissolved-phase plume is adequately defined with the leading edge of the plume extending approximately 50 feet south of the site. In the hot well (MW-6), the benzene concentration is stable and demonstrating an overall decreasing trend. The consultant estimates that benzene will reach its Maximum Contaminant Level by 2066. Historically, free product was not observed in any monitoring wells. The residual soil and groundwater contamination will not impact human health, the environment, or nearby sensitive receptors. Based on available data, DEH concurs with the consultant s conclusions.

LUST:
Global Id: T0607301436
Contact Type: Local Agency Caseworker
Contact Name: JON SENAHA
Organization Name: SAN DIEGO COUNTY LOP
Address: P.O. Box 129261
City: San Diego
Email: jon.senaha@sdcounty.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607301436
Action Type: ENFORCEMENT
Date: 02/10/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607301436
Action Type: ENFORCEMENT
Date: 08/25/2011
Action: Technical Correspondence / Assistance / Other

S D CNTY GEN SVCS AUTO SVC (Continued) **S101301743**

Global Id:	T0607301436
Action Type:	Other
Date:	02/02/1994
Action:	Leak Discovery
Global Id:	T0607301436
Action Type:	ENFORCEMENT
Date:	12/09/2008
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607301436
Action Type:	ENFORCEMENT
Date:	06/30/2010
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0607301436
Action Type:	Other
Date:	02/02/1994
Action:	Leak Began
Global Id:	T0607301436
Action Type:	Other
Date:	02/02/1994
Action:	Leak Reported
Global Id:	T0607301436
Action Type:	ENFORCEMENT
Date:	02/25/1994
Action:	Notice of Responsibility
Global Id:	T0607301436
Action Type:	RESPONSE
Date:	06/25/2010
Action:	Monitoring Report - Other
Global Id:	T0607301436
Action Type:	REMEDIATION
Date:	06/18/2007
Action:	Excavation
Global Id:	T0607301436
Action Type:	ENFORCEMENT
Date:	12/01/2011
Action:	Closure/No Further Action Letter
Global Id:	T0607301436
Action Type:	Other
Date:	02/02/1994
Action:	Leak Stopped
Global Id:	T0607301436
Action Type:	RESPONSE
Date:	08/20/2009
Action:	CAP/RAP - Other Report - Regulator Responded
Global Id:	T0607301436
Action Type:	RESPONSE

S D CNTY GEN SVCS AUTO SVC (Continued) **S101301743**

Date: 07/15/2011
Action: Monitoring Report - Quarterly - Regulator Responded

Global Id: T0607301436
Action Type: ENFORCEMENT
Date: 07/14/2009
Action: Letter - Notice

LUST:
Global Id: T0607301436
Status: Open - Case Begin Date
Status Date: 02/02/1994

Global Id: T0607301436
Status: Open - Remediation
Status Date: 07/13/2000

Global Id: T0607301436
Status: Open - Site Assessment
Status Date: 07/07/2009

Global Id: T0607301436
Status: Completed - Case Closed
Status Date: 12/01/2011

SAN DIEGO CO. SAM:
Name: S D CNTY GEN SVCS AUTO SVC
Address: 7410 WAITE DR
City,State,Zip: LA MESA, CA 91941
Case Number: H04820-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 7/13/2000
Date Began: 2/2/1994

HMMD SAN DIEGO:
Name: S D CNTY GEN SVCS AUTO SVC
Address: 7410 WAITE DR
City,State,Zip: LA MESA, CA 91941
Permit Number: 104820
Business Type: Not reported
EPA Id Number: CAX000079574
APN: 474-500-15-00
Last HMMD Inspection: 06/30/1992
Facility Telephone: 460-5232
Permit Status: INAC
Permit Expiration: Not reported
Date Last Updated: 11/02/2012
Facility Owner: COUNTY OF SAN DIEGO/FLEET OPER
Facility Mailing Address: 5555 OVERLAND AV MS: O19
Facility Mailing City: LA MESA
Facility Mailing State: CA
Facility Mailing Zip: 91941-

S D CNTY GEN SVCS AUTO SVC (Continued) **S101301743**

UST Owner:	COUNTY OF SAN DIEGO/FLEET OPER
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 104820 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	104820
Tank Type:	SINGLE WALL
Additional Id:	GS012
Capacity Gallons:	8000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1994-02-02 00:00:00
Year Installed:	Not reported
Pipe Type:	SINGLE WALL
Delivery System:	SUCTION
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 104820 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	104820
Tank Type:	SINGLE WALL
Additional Id:	GS013
Capacity Gallons:	1000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	REMOVED
Remove Close Date:	1994-02-02 00:00:00
Year Installed:	Not reported
Pipe Type:	SINGLE WALL
Delivery System:	SUCTION
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

SWEEPS UST:

Name:	S D CNTY GEN SVCS AUTO SVC
Address:	7410 WAITE DR
City:	LA MESA
Status:	Active
Comp Number:	4820
Number:	9
Board Of Equalization:	44-022109
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-004820-000001

S D CNTY GEN SVCS AUTO SVC (Continued) **S101301743**

Tank Status:	A
Capacity:	8000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	2

Name:	S D CNTY GEN SVCS AUTO SVC
Address:	7410 WAITE DR
City:	LA MESA
Status:	Active
Comp Number:	4820
Number:	9
Board Of Equalization:	44-022109
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-004820-000002
Tank Status:	A
Capacity:	1000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	OTHER
Number Of Tanks:	Not reported

CORTESE:

Name:	S D CNTY GEN SVCS AUTO SVC (LEMON GROVE ROAD STATION)
Address:	7410 WAITE DR
City,State,Zip:	LA MESA, CA 91941
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607301436
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	FLEET OPERATIONS LEMON GR

S D CNTY GEN SVCS AUTO SVC (Continued) **S101301743**

edr_fadd1: 7410 WAITE
City,State,Zip: LA MESA, CA 92041
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT1966

SAN DIEGO CO LOP:
Name: S D CNTY GEN SVCS AUTO SVC
Address: 7410 WAITE DR
City,State,Zip: LA MESA, CA 91941
Record ID: DEH1994-LSAM-H04820-001
Record Status: Completed
Opened Date: 02/02/1994
Parcel Number: 474-500-15-00
Case Type: LOP - Local Oversight Program
Historical Name: COUNTY OF SD-FLEET OPS LEM GRV
SWRCB Global ID: T0607301436
Funding: S - LOP State Fund
Lead Agency: DEH/SAM
Lead Agency Date: 02/02/1994
Census Tract: 145.00
Community: La Mesa
Jurisdiction: LA MESA
Watershed Basin Number: 908.22
Water Purveyor: LA MESA
Fire Agency: LA MESA
Latitude: 32.7468886
Longitude: -117.0382893
X MapCoord: 6319284.246
Y MapCoord: 1852480.971

CERS:
Name: S D CNTY GEN SVCS AUTO SVC (LEMON GROVE ROAD STATION)
Address: 7410 WAITE DR
City,State,Zip: LA MESA, CA 91941
Site ID: 193240
CERS ID: T0607301436
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

A12 **1X COUNTY OF SAN DIEGO** **HAZNET** **S123762763**
7400 WAITE DRIVE **HWTS** **N/A**
< 1/8 **LA MESA, CA 91941**
0.000 mi.
2 ft. **Site 12 of 12 in cluster A**

Relative:
Lower

Actual:
461 ft.

HAZNET:

Name:	1X COUNTY OF SAN DIEGO
Address:	7400 WAITE DRIVE
Address 2:	Not reported
City,State,Zip:	LA MESA, CA 919410000
Contact:	GITA MONDAL, INTERN
Telephone:	6193382410
Mailing Name:	Not reported
Mailing Address:	1255 IMPERIAL AVENUE
Year:	1991
Gepaid:	CAH777000137
TSD EPA ID:	CAT080010101
CA Waste Code:	612 - Household waste
Disposal Method:	T01 - Treatment, Tank
Tons:	0.0702
Year:	1991
Gepaid:	CAH777000137
TSD EPA ID:	CAT080010101
CA Waste Code:	612 - Household waste
Disposal Method:	H01 - Transfer Station
Tons:	6.8963

HWTS:

Name:	1X COUNTY OF SAN DIEGO
Address:	7400 WAITE DRIVE
Address 2:	Not reported
City,State,Zip:	LA MESA, CA 91941
EPA ID:	CAH777000137
Inactive Date:	12/19/2000
Create Date:	04/09/1991
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	1255 IMPERIAL AVENUE
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SAN DIEGO, CA 921860000
Owner Name:	CO. OF SAN DIEGO/ENVIR. HEALTH
Owner Address:	Not reported
Owner Address 2:	Not reported
Owner City,State,Zip:	Not reported
Contact Name:	GITA MONDAL, INTERN
Contact Address:	COLLECTIN DATE 4-17-91
Contact Address 2:	Not reported
City,State,Zip:	Not reported
Facility Status:	Inactive
Facility Type:	PERMANENT
Category:	STATE
Latitude:	32.746311
Longitude:	-117.037521

B13 **STEVE MCELFRESH** **RCRA NonGen / NLR** **1027083783**
SW **3743 HARRIS ST.** **CAC003155962**
< 1/8 **LA MESA, CA 91941**
0.038 mi.
202 ft. **Site 1 of 2 in cluster B**

Relative: **Lower**

Actual: **447 ft.**

RCRA Listings:

Date Form Received by Agency:		20220107
Handler Name:	STEVE MCELFRESH	
Handler Address:		3743 HARRIS ST.
Handler City,State,Zip:		LA MESA, CA 91941
EPA ID:		CAC003155962
Contact Name:		STEVE MCELFRESH
Contact Address:		3743 HARRIS ST.
Contact City,State,Zip:		LA MESA, CA 91941
Contact Telephone:		619-955-3004
Contact Fax:		Not reported
Contact Email:		SDABATEMENT@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3743 HARRIS ST.
Mailing City,State,Zip:		LA MESA, CA 91941
Owner Name:	STEVE MCELFRESH	
Owner Type:		Other
Operator Name:	STEVE MCELFRESH	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

STEVE MCELFRESH (Continued) **1027083783**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20220110
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: STEVE MCELFRESH	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3743 HARRIS ST.
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	619-955-3004
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: STEVE MCELFRESH	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3743 HARRIS ST.
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	619-955-3004
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

STEVE MCELFRESH (Continued) **1027083783**

Historic Generators:
Receive Date: 20220107
Handler Name: STEVE MCELFRESH
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B14 **ROBERTA SLATER** **RCRA NonGen / NLR** **1027083343**
SW **3743 HARRIS ST.** **CAC003155499**
< 1/8 **SAN DIEGO, CA 91941**
0.038 mi.
202 ft. **Site 2 of 2 in cluster B**

Relative: **Lower**
Actual: **447 ft.**

RCRA Listings:
Date Form Received by Agency: 20220105
Handler Name: ROBERTA SLATER
Handler Address: 3743 HARRIS ST.
Handler City,State,Zip: SAN DIEGO, CA 91941
EPA ID: CAC003155499
Contact Name: ROBERTA SLATER
Contact Address: 3743 HARRIS ST.
Contact City,State,Zip: SAN DIEGO, CA 91941
Contact Telephone: 619-955-3004
Contact Fax: Not reported
Contact Email: SDABATEMENT@GMAIL.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Not reported
State District: Not reported
Mailing Address: 3743 HARRIS ST.
Mailing City,State,Zip: SAN DIEGO, CA 91941
Owner Name: ROBERTA SLATER

ROBERTA SLATER (Continued) **1027083343**

Owner Type:		Other
Operator Name:	ROBERTA SLATER	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	
Handler Date of Last Change:		20220105
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

ROBERTA SLATER (Continued) **1027083343**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: ROBERTA SLATER
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3743 HARRIS ST.
Owner/Operator City,State,Zip: SAN DIEGO, CA 91941
Owner/Operator Telephone: 619-955-3004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROBERTA SLATER
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3743 HARRIS ST.
Owner/Operator City,State,Zip: SAN DIEGO, CA 91941
Owner/Operator Telephone: 619-955-3004
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20220105
Handler Name: ROBERTA SLATER
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

15
NNW
< 1/8
0.059 mi.
309 ft.

BRUCE BARAW
3889 HARRIS STREET
LA MESA, CA 91941

RCRA NonGen / NLR

1026712088
CAC003100295

Relative:
Higher

Actual:
471 ft.

RCRA Listings:

Date Form Received by Agency:		20210111
Handler Name:	BRUCE BARAW	
Handler Address:		3889 HARRIS STREET
Handler City,State,Zip:		LA MESA, CA 91941
EPA ID:		CAC003100295
Contact Name:		BRUCE BARAW
Contact Address:		3889 HARRIS STREET
Contact City,State,Zip:		LA MESA, CA 91941
Contact Telephone:		619-251-9018
Contact Fax:		Not reported
Contact Email:		INFO@OPTIMALSOLUTIONSINC.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3889 HARRIS STREET
Mailing City,State,Zip:		LA MESA, CA 91941
Owner Name:	BRUCE BARAW	
Owner Type:		Other
Operator Name:	BRUCE BARAW	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

BRUCE BARAW (Continued) **1026712088**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20210226
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: BRUCE BARAW	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3889 HARRIS STREET
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	619-251-9018
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: BRUCE BARAW	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3889 HARRIS STREET
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	619-251-9018
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

BRUCE BARAW (Continued) **1026712088**

Historic Generators:
Receive Date: 20210111
Handler Name: BRUCE BARAW
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C16 **KEVIN FERREE** **RCRA NonGen / NLR** **1026476180**
WSW **3775 CITRUS STREET** **CAC003081971**
< 1/8 **LA MESA, CA 91941**
0.098 mi.
519 ft. **Site 1 of 4 in cluster C**

Relative:
Lower

Actual:
453 ft.

RCRA Listings:
Date Form Received by Agency: 20200901
Handler Name: KEVIN FERREE
Handler Address: 3775 CITRUS STREET
Handler City,State,Zip: LA MESA, CA 91941
EPA ID: CAC003081971
Contact Name: KEVIN FERREE
Contact Address: 3775 CITRUS STREET
Contact City,State,Zip: LA MESA, CA 91941
Contact Telephone: 619-229-6135
Contact Fax: Not reported
Contact Email: CINDYEDWARDS@ALLIANCE-ENVIRO.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Not reported
State District: Not reported
Mailing Address: 3775 CITRUS STREET
Mailing City,State,Zip: LA MESA, CA 91941
Owner Name: KEVIN FERREE

KEVIN FERREE (Continued) **1026476180**

Owner Type:		Other
Operator Name:	KEVIN FERREE	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	
Handler Date of Last Change:		20200904
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

KEVIN FERREE (Continued) **1026476180**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: KEVIN FERREE
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3775 CITRUS STREET
Owner/Operator City,State,Zip: LA MESA, CA 91941
Owner/Operator Telephone: 619-229-6135
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: KEVIN FERREE
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3775 CITRUS STREET
Owner/Operator City,State,Zip: LA MESA, CA 91941
Owner/Operator Telephone: 619-229-6135
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20200901
Handler Name: KEVIN FERREE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C17 **DIANDRA LAUIFI** **RCRA NonGen / NLR** **1025852033**
WSW **3766 CITRUS ST** **CAC003032180**
< 1/8 **LA MESA, CA 91941**
0.118 mi.
623 ft. **Site 2 of 4 in cluster C**

Relative: **Lower**

Actual: **457 ft.**

RCRA Listings:

Date Form Received by Agency:		20190903
Handler Name:	DIANDRA LAUIFI	
Handler Address:		3766 CITRUS ST
Handler City,State,Zip:		LA MESA, CA 91941-7611
EPA ID:		CAC003032180
Contact Name:		DIANDRA LAUIFI
Contact Address:		3766 CITRUS ST
Contact City,State,Zip:		LA MESA, CA 91941-7611
Contact Telephone:		619-322-5534
Contact Fax:		Not reported
Contact Email:		DIANDRALAUIFI@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3766 CITRUS ST
Mailing City,State,Zip:		LA MESA, CA 91941-7611
Owner Name:	DIANDRA LAUIFI	
Owner Type:		Other
Operator Name:	DIANDRA LAUIFI	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

DIANDRA LAUIFI (Continued) **1025852033**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20190910
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: DIANDRA LAUIFI	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3766 CITRUS ST
Owner/Operator City,State,Zip:	LA MESA, CA 91941-7611
Owner/Operator Telephone:	619-322-5534
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: DIANDRA LAUIFI	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3766 CITRUS ST
Owner/Operator City,State,Zip:	LA MESA, CA 91941-7611
Owner/Operator Telephone:	619-322-5534
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DIANDRA LAUIFI (Continued) **1025852033**

Historic Generators:
Receive Date: 20190903
Handler Name: DIANDRA LAUIFI
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C18 **PEDRO& MARIA FAJARDO** **RCRA NonGen / NLR** **1026045159**
WSW **3760 CITRUS STREET** **CAC003051533**
< 1/8 **LA MESA, CA 91941**
0.120 mi.
636 ft. **Site 3 of 4 in cluster C**

Relative: **Lower**

Actual: **456 ft.**

RCRA Listings:
Date Form Received by Agency: 20200116
Handler Name: PEDRO& MARIA FAJARDO
Handler Address: 3760 CITRUS STREET
Handler City,State,Zip: LA MESA, CA 91941
EPA ID: CAC003051533
Contact Name: PEDRO& MARIA FAJARDO
Contact Address: 3760 CITRUS STREET
Contact City,State,Zip: LA MESA, CA 91941
Contact Telephone: 619-340-7669
Contact Fax: Not reported
Contact Email: LRIVERO@APEX411.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Not reported
State District: Not reported
Mailing Address: 3760 CITRUS STREET
Mailing City,State,Zip: LA MESA, CA 91941
Owner Name: PEDRO& MARIA FAJARDO

PEDRO& MARIA FAJARDO (Continued) **1026045159**

Owner Type:		Other
Operator Name:	PEDRO& MARIA FAJARDO	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	
Handler Date of Last Change:		20200210
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

PEDRO& MARIA FAJARDO (Continued) **1026045159**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: PEDRO& MARIA FAJARDO
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3760 CITRUS STREET
Owner/Operator City,State,Zip: LA MESA, CA 91941
Owner/Operator Telephone: 619-340-7669
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PEDRO& MARIA FAJARDO
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3760 CITRUS STREET
Owner/Operator City,State,Zip: LA MESA, CA 91941
Owner/Operator Telephone: 619-340-7669
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20200116
Handler Name: PEDRO& MARIA FAJARDO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C19 **JOAN SANCHEZ** **RCRA NonGen / NLR** **1024758470**
WSW **3736 CITRUS ST.** **CAC002978312**
< 1/8 **LA MESA, CA 91941**
0.124 mi.
655 ft. **Site 4 of 4 in cluster C**

Relative: **Lower**
Actual: **457 ft.**

RCRA Listings:

Date Form Received by Agency:		20180830
Handler Name:	JOAN SANCHEZ	
Handler Address:		3736 CITRUS ST.
Handler City,State,Zip:		LA MESA, CA 91941
EPA ID:		CAC002978312
Contact Name:		JOAN SANCHEZ
Contact Address:		3736 CITRUS ST.
Contact City,State,Zip:		LA MESA, CA 91941
Contact Telephone:		858-625-0003
Contact Fax:		Not reported
Contact Email:		SDABATEMENT@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3736 CITRUS ST.
Mailing City,State,Zip:		LA MESA, CA 91941
Owner Name:	JOAN SANCHEZ	
Owner Type:		Other
Operator Name:	JOAN SANCHEZ	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

JOAN SANCHEZ (Continued) **1024758470**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20180905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOAN SANCHEZ	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3736 CITRUS ST.
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	858-625-0003
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOAN SANCHEZ	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3736 CITRUS ST.
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	858-625-0003
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

JOAN SANCHEZ (Continued) **1024758470**

Historic Generators:
Receive Date: 20180830
Handler Name: JOAN SANCHEZ
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D20 **WESTSTAR LANDSCAPE** **RCRA NonGen / NLR** **1025866510**
SSW **3553 HARRIS ST** **CAL000245004**
1/8-1/4 **LEMON GROVE, CA 91945**
0.157 mi.
827 ft. **Site 1 of 8 in cluster D**

Relative:
Lower

Actual:
433 ft.

RCRA Listings:
Date Form Received by Agency: 20020301
Handler Name: WESTSTAR LANDSCAPE
Handler Address: 3553 HARRIS ST
Handler City,State,Zip: LEMON GROVE, CA 91945-0000
EPA ID: CAL000245004
Contact Name: MARK VASQUEZ
Contact Address: 3553 HARRIS ST
Contact City,State,Zip: LEMON GROVE, CA 91945-0000
Contact Telephone: 619-697-2957
Contact Fax: 619-697-9438
Contact Email: WEBSTER@WSL.SDCOXMAIL.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: 3553 HARRIS ST
Mailing City,State,Zip: LEMON GROVE, CA 91945-0000
Owner Name: MARK, JOHN, & PHIL VASQUEZ

WESTSTAR LANDSCAPE (Continued) **1025866510**

Owner Type:		Other
Operator Name:	MARK VASQUEZ	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		Yes
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	
Handler Date of Last Change:		20190627
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

WESTSTAR LANDSCAPE (Continued) **1025866510**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: MARK, JOHN, & PHIL VASQUEZ
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3553 HARRIS ST
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945-0000
Owner/Operator Telephone: 619-697-2957
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: MARK VASQUEZ
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3553 HARRIS ST
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945-0000
Owner/Operator Telephone: 619-697-2957
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20020301
Handler Name: WESTSTAR LANDSCAPE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D21 **VIKING FENCE AT0236** **San Diego Co. HMMD** **S104746058**
SSW **3529 HARRIS ST** **SWEEPS UST** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945**
0.176 mi.
931 ft. **Site 2 of 8 in cluster D**

Relative:
Lower

Actual:
427 ft.

HMMD SAN DIEGO:

Name:	VIKING FENCE AT0236
Address:	3529 HARRIS ST
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	104919
Business Type:	Not reported
EPA Id Number:	Not reported
APN:	479-052-06-00
Last HMMD Inspection:	Not reported
Facility Telephone:	Not reported
Permit Status:	INAC
Permit Expiration:	Not reported
Date Last Updated:	11/02/2012
Facility Owner:	VIKING FENCE
Facility Mailing Address:	3529 HARRIS ST
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945-1522
UST Owner:	VIKING FENCE
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 104919 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	104919
Tank Type:	SINGLE WALL
Additional Id:	AT0236-1
Capacity Gallons:	1000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1987-01-12 00:00:00
Year Installed:	1971-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

SWEEPS UST:

Name:	VIKING FENCE AT0236
Address:	3529 HARRIS ST
City:	LEMON GROVE
Status:	Not reported
Comp Number:	4919
Number:	Not reported
Board Of Equalization:	Not reported

VIKING FENCE AT0236 (Continued) **S104746058**

Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-004919-000001
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	1

Name:	VIKING FENCE AT0236
Address:	3529 HARRIS ST
City:	LEMON GROVE
Status:	Active
Comp Number:	4919
Number:	9
Board Of Equalization:	Not reported
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported
STG:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

E22 **FOOD 4 LESS FUEL CENTER #318** **UST** **U004261866**
SSE **7428 BROADWAY** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945**
0.181 mi.
955 ft. **Site 1 of 6 in cluster E**

Relative: **Lower**

Actual: **426 ft.**

UST:

Name:	FOOD 4 LESS FUEL CENTER #318
Address:	7428 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Facility ID:	37-000-000798
Permitting Agency:	San Diego County Department of Environmental Health
CERSID:	10230532
Latitude:	32.7437600
Longitude:	-117.037500
Owner type:	Not reported
Facility type:	Not reported
Num of inuse ust:	Not reported
Num of closed ust:	Not reported
Num of oos ust:	Not reported
Epa region:	Not reported
Tribal lands:	Not reported
Tank owner name:	Not reported
Tank owner mailing address:	Not reported
Tank owner mailing city:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **U004261866**

Tank owner mailing zip:	Not reported
Tank owner mailing state:	Not reported
Tank operator name:	Not reported
Tank operator mailing address:	Not reported
Tank operator mailing city:	Not reported
Tank operator mailing zip:	Not reported
Tank operator mailing state:	Not reported
Tankidnumber:	Not reported
Tank status:	Not reported
Tank configuration:	Not reported
Tank closure date:	Not reported
Tank installation date:	Not reported
Tank num of compartments:	Not reported
Tank contents:	Not reported
Tank capacity gallons:	Not reported
Tank type:	Not reported
Tank pc construction:	Not reported
Tank pwpiping construction:	Not reported
Tank piping type:	Not reported
Tank piping construction:	Not reported
Tank sacrificial anode:	Not reported
Tank cp impressed current:	Not reported
Tank cp shutoff:	Not reported
Tank alarms:	Not reported
Tank ball float:	Not reported
Tank spill bucket:	Not reported

E23
SSE
1/8-1/4
0.181 mi.
955 ft.

Relative:
Lower

Actual:
426 ft.

FOOD 4 LESS FUEL CENTER #318
7428 BROADWAY
LEMON GROVE, CA 91945

Site 2 of 6 in cluster E

San Diego Co. HMMD **S119095687**
CERS HAZ WASTE **N/A**
CERS TANKS
HAZNET
CERS
HWTS

HMMD SAN DIEGO:

Name:	FOOD 4 LESS FUEL CENTER #318
Address:	7428 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAR000259994
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-463-4774
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	10/29/2022
Facility Owner:	Not reported
Facility Mailing Address:	P.O. BOX 54143, LOS ANGELES, CA 90054
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	Y
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Generate Medical Waste: Not reported

Inspection Violation:

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-000798
Program Element: Hazardous Waste Generator
Inspection Type: Routine
Inspection Number: 7009199
Return To Compliance Date: Not reported
Nov: Not reported
Violation Classification: Not reported
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2022-10-29T02:15:14.000
Inspection Date: 2022-09-16T00:00:00.000
Violation Code: HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS AND LQGS

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-000798
Program Element: Underground Storage Tank
Inspection Type: Routine
Inspection Number: 5963450
Return To Compliance Date: 2018-09-06T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: 22010-NT2508-2
Container/Tank Id: Not reported
Last Update: 2022-10-29T02:15:14.000
Inspection Date: 2018-09-06T13:18:29.000
Violation Code: 2060020 (RP) Failure to comply with one or more of the following: Failure to install or maintain a liquid-tight spill bucket, have a minimum capacity of 5 gallons, have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container, and/or be resistant to galvanic corrosion. 23 CCR 2635(b), 2665

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-000798
Program Element: Underground Storage Tank
Inspection Type: Routine
Inspection Number: 5715791
Return To Compliance Date: 2017-12-28T00:00:00.000
Nov: No
Violation Classification: Not reported
Underground Storage Tank Id: 32010-NT2508-3
Container/Tank Id: Not reported
Last Update: 2022-10-29T02:15:14.000
Inspection Date: 2017-09-06T12:34:00.000
Violation Code: 2030036 (RP) Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity; and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 2635(b)(2), 2665

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	7009199
Return To Compliance Date:	2022-10-27T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2022-09-16T00:00:00.000
Violation Code:	1010004 Chemical inventory incomplete or not submitted in CERS. HSC 25505(a)(1); 25507(a); 25508.1(a-b); 19 CCR 2654 (a) or (d)

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6798192
Return To Compliance Date:	2021-09-29T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	32010-NT2508-3
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2021-09-29T00:00:00.000
Violation Code:	2030043 (TCR 9d) Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained in accordance with manufacturer's instructions. 23 CCR 2638(a), 2641(j)

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	7009199
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Inspection Date:	2022-09-16T00:00:00.000
Violation Code:	HMD0001 RECORD KEEPING/OPERATIONAL REQUIREMENTS
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	7009199
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2022-09-16T00:00:00.000
Violation Code:	HMD0000 UST PRESSURIZED PIPING (DW) REQUIREMENTS
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6232574
Return To Compliance Date:	2019-09-27T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	2010-NT2508-1
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2019-09-12T00:00:00.000
Violation Code:	2030002 (TCR 9d) Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.). 23 CCR 2638(a)(b), 2651(j), 2715(f).
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	7009199
Return To Compliance Date:	2022-09-16T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	2010-NT2508-1
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2022-09-16T00:00:00.000
Violation Code:	2030025 (TCR 9d) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: 1) Monitored with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch within an hour. 2) Restrict

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6232574
Return To Compliance Date:	2019-09-27T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	2010-NT2508-1
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2019-09-12T00:00:00.000
Violation Code:	2060020 (TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	7009199
Return To Compliance Date:	Not reported
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2022-09-16T00:00:00.000
Violation Code:	HMD0138 Manifest signed by the TSDF not available for inspection. 22 CCR 66262.40(a); HSC 25185(a)(4)

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6232574
Return To Compliance Date:	2019-09-12T00:00:00.000
Nov:	No
Violation Classification:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Underground Storage Tank Id:	2010-NT2508-1
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2019-09-12T00:00:00.000
Violation Code:	2030043 (TCR 9d) Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly. 23 CCR 2638(a), 2641(j)
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6798192
Return To Compliance Date:	2021-09-29T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	2010-NT2508-1
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2021-09-29T00:00:00.000
Violation Code:	2030036 (TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. 6. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. 7. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. 8. Inspected within 30 days after a repair to the overfill prevention equipment. 9. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 10. Inspected by a certified UST service technician. 11. Maintain records of overfill prevention equipment inspection for 36 months. 23 CCR 2635(c)(1), 2635(d), 2637.2(a-c), 2665, 2712(b)(1)(G)
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	7009199
Return To Compliance Date:	Not reported
Nov:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2022-09-16T00:00:00.000
Violation Code:	HMD0000 UST TANK (DW/SW) - REQUIREMENT
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	7009199
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2022-09-16T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS MATERIALS REQUIREMENTS
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	7009199
Return To Compliance Date:	2022-09-16T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	2010-NT2508-1
Container/Tank Id:	Not reported
Last Update:	2022-10-29T02:15:14.000
Inspection Date:	2022-09-16T00:00:00.000
Violation Code:	2060020 (TCR 9a) Failure to meet one or more of the following requirements: 1) Install or maintain a liquid-tight spill container. 2) Have a minimum capacity of 5 gallons. 3) Have a functional drain valve or other method for the removal of liquid from the spill container. 4) Be resistant to galvanic corrosion. 5) Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. 6) Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 7) Tested by a certified UST service technician. 8) Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

UST DTL:

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	FOOD 4 LESS

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Tankid:	3
Tank Status:	SEE FILE
Date Ust Permanently Closed:	09/28/2017
Tank Use:	Motor Vehicle Fueling
Piping System Type:	Pressure
Last Updated:	2017-09-29T00:46:47.000
Tank Capacityin Gallons:	10000
Tank Contents:	Diesel
Type Of Tank:	Double Wall

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	FOOD 4 LESS
Tankid:	2010-NT2508-1
Tank Status:	SEE FILE
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-10-29T02:15:18.000
Tank Capacityin Gallons:	20000
Tank Contents:	Regular Unleaded
Type Of Tank:	Double Wall

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	FOOD 4 LESS
Tankid:	1
Tank Status:	SEE FILE
Date Ust Permanently Closed:	09/28/2017
Tank Use:	Motor Vehicle Fueling
Piping System Type:	Pressure
Last Updated:	2017-09-29T00:46:47.000
Tank Capacityin Gallons:	20000
Tank Contents:	Regular Unleaded
Type Of Tank:	Double Wall

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	FOOD 4 LESS
Tankid:	2
Tank Status:	SEE FILE
Date Ust Permanently Closed:	09/28/2017
Tank Use:	Motor Vehicle Fueling
Piping System Type:	Pressure
Last Updated:	2017-09-29T00:46:47.000
Tank Capacityin Gallons:	8000
Tank Contents:	Premium Unleaded
Type Of Tank:	Double Wall

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	FOOD 4 LESS
Tankid:	22010-NT2508-2
Tank Status:	SEE FILE
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-10-29T02:15:18.000
Tank Capacityin Gallons:	8000
Tank Contents:	Premium Unleaded
Type Of Tank:	Double Wall

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-000798
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	FOOD 4 LESS
Tankid:	32010-NT2508-3
Tank Status:	SEE FILE
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-10-29T02:15:18.000
Tank Capacityin Gallons:	10000
Tank Contents:	Diesel
Type Of Tank:	Double Wall

Waste and Materials:

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0158970
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-06-06T02:34:54.000
Chemical Name:	GASOLINE
Common Name:	GASOLINE (GRADES: REGULAR & PREMIUM)
Case Number:	86290-81-5

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0158971
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-06-06T02:34:54.000
Chemical Name:	DIESEL
Common Name:	DIESEL
Case Number:	68476-34-6

Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Active Permit: Y
Child Record Id: DEH2017-HWAST-0134741
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-06-06T02:34:54.000
Chemical Name: Not reported
Common Name: WASTE ABSORBENT & SPENT DISPENSER FUEL FILTERS
Case Number: Not reported

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0233896
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-09-17T01:11:20.000
Chemical Name: GASOLINE
Common Name: GASOLINE (GRADES: REGULAR & PREMIUM)
Case Number: 86290-81-5

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0203942
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-09-17T01:11:20.000
Chemical Name: Not reported
Common Name: WASTE ABSORBENT & SPENT DISPENSER FUEL FILTERS
Case Number: Not reported

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0203943
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-09-17T01:11:20.000
Chemical Name: Not reported
Common Name: SUMP WASTE CLEANUP, TEST WATER
Case Number: Not reported

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0276253
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-08-19T01:59:48.000
Chemical Name: GASOLINE
Common Name: GASOLINE (GRADES: REGULAR & PREMIUM)
Case Number: 86290-81-5

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0276254

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2021-08-19T01:59:48.000
Chemical Name:	DIESEL
Common Name:	DIESEL
Case Number:	68476-34-6
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HWAST-0244505
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2021-08-19T01:59:49.000
Chemical Name:	Not reported
Common Name:	WASTE ABSORBENT & SPENT DISPENSER FUEL FILTERS
Case Number:	Not reported
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0116808
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2017-09-21T02:34:05.000
Chemical Name:	GASOLINE
Common Name:	GASOLINE (GRADES: REGULAR & PREMIUM)
Case Number:	86290-81-5
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HCHEM-0116809
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2017-09-21T02:34:05.000
Chemical Name:	DIESEL
Common Name:	DIESEL
Case Number:	68476-34-6
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2016-HWAST-0098142
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-09-21T02:34:05.000
Chemical Name:	Not reported
Common Name:	WASTE ABSORBENT & SPENT DISPENSER FUEL FILTERS
Case Number:	Not reported
Record ID:	DEH2014-HUPFP-000798
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HCHEM-0344024
Trade Secret:	N
Hazardous Material Type:	Pure

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Last Updated: 2022-10-29T02:15:18.000
Chemical Name: GASOLINE
Common Name: GASOLINE (GRADES: REGULAR & PREMIUM)
Case Number: 86290-81-5

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0344025
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-29T02:15:18.000
Chemical Name: DIESEL
Common Name: DIESEL
Case Number: 68476-34-6

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311575
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-10-29T02:15:18.000
Chemical Name: Not reported
Common Name: WASTE ABSORBENT & SPENT DISPENSER FUEL FILTERS
Case Number: Not reported

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311576
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-10-29T02:15:18.000
Chemical Name: Not reported
Common Name: SUMP WASTE CLEAN-UP, TEST WATER
Case Number: Not reported

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0233897
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-09-17T01:11:20.000
Chemical Name: DIESEL
Common Name: DIESEL
Case Number: 68476-34-6

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0342398
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-15T00:55:01.000
Chemical Name: GASOLINE

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Common Name: GASOLINE (GRADES: REGULAR & PREMIUM)
Case Number: 86290-81-5

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0342399
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-10-15T00:55:01.000
Chemical Name: DIESEL
Common Name: DIESEL
Case Number: 68476-34-6

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0309824
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-10-15T00:55:01.000
Chemical Name: Not reported
Common Name: WASTE ABSORBENT & SPENT DISPENSER FUEL FILTERS
Case Number: Not reported

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0197378
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-12-01T00:52:30.000
Chemical Name: GASOLINE
Common Name: GASOLINE (GRADES: REGULAR & PREMIUM)
Case Number: 86290-81-5

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0197379
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-12-01T00:52:30.000
Chemical Name: DIESEL
Common Name: DIESEL
Case Number: 68476-34-6

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0169994
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-12-01T00:52:30.000
Chemical Name: Not reported
Common Name: WASTE ABSORBENT & SPENT DISPENSER FUEL FILTERS
Case Number: Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0309718
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-09-23T02:31:36.000
Chemical Name: GASOLINE
Common Name: GASOLINE (GRADES: REGULAR & PREMIUM)
Case Number: 86290-81-5

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0309719
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-09-23T02:31:36.000
Chemical Name: DIESEL
Common Name: DIESEL
Case Number: 68476-34-6

Record ID: DEH2014-HUPFP-000798
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0277700
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-09-23T02:31:36.000
Chemical Name: Not reported
Common Name: WASTE ABSORBENT & SPENT DISPENSER FUEL FILTERS
Case Number: Not reported

CERS HAZ WASTE:
Name: FOOD 4 LESS FUEL CENTER #318
Address: 7428 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 30896
CERS ID: 10230532
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: FOOD 4 LESS FUEL CENTER #318
Address: 7428 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 30896
CERS ID: 10230532
CERS Description: Underground Storage Tank

HAZNET:
Name: FOOD 4 LESS FUEL CENTER #318
Address: 7428 BROADWAY
Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 91945
Contact: MATTHEW EATON

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Telephone:	3108844016
Mailing Name:	Not reported
Mailing Address:	PO BOX 80842
Year:	2021
Gepaid:	CAR000259994
TSD EPA ID:	NVT330010000
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0885
Year:	2021
Gepaid:	CAR000259994
TSD EPA ID:	NVT330010000
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.026
Year:	2021
Gepaid:	CAR000259994
TSD EPA ID:	NVT330010000
CA Waste Code:	352 - Other organic solids
Disposal Method:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.359
Year:	2020
Gepaid:	CAR000259994
TSD EPA ID:	NVT330010000
CA Waste Code:	221 - Waste oil and mixed oil
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0575
Year:	2020
Gepaid:	CAR000259994
TSD EPA ID:	NVT330010000
CA Waste Code:	352 - Other organic solids
Disposal Method:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.628
Year:	2019
Gepaid:	CAR000259994
TSD EPA ID:	CAT080013352
CA Waste Code:	241 - Tank bottom waste
Disposal Method:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.16680
Year:	2019
Gepaid:	CAR000259994
TSD EPA ID:	NVT330010000
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

	Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.10650
Year:	2019
Gepaid:	CAR000259994
TSD EPA ID:	NVT330010000
CA Waste Code:	352 - Other organic solids
Disposal Method:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.56400
Year:	2019
Gepaid:	CAR000259994
TSD EPA ID:	CAT080013352
CA Waste Code:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.18765
Year:	2018
Gepaid:	CAR000259994
TSD EPA ID:	NVT330010000
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.06350

Click this hyperlink while viewing on your computer to access
6 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:

Year:	2021
Gen EPA ID:	CAR000259994
Shipment Date:	9/9/2020
Creation Date:	9/29/2020
Receipt Date:	9/22/2020
Manifest ID:	021572164JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.022
Waste Quantity:	44
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/8/2020
Receipt Date:	9/29/2020
Manifest ID:	022023332JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0325
Waste Quantity:	65
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	8/26/2020
Creation Date:	9/18/2020
Receipt Date:	9/11/2020
Manifest ID:	021572078JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	8/12/2020
Creation Date:	9/1/2020
Receipt Date:	8/18/2020
Manifest ID:	020593282JJK

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0325
Waste Quantity:	65
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	7/8/2020
Creation Date:	7/23/2020
Receipt Date:	7/16/2020
Manifest ID:	021198004JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0265
Waste Quantity:	53
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	7/23/2020
Creation Date:	8/12/2020
Receipt Date:	7/30/2020
Manifest ID:	021198080JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.026
Waste Quantity:	52
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	6/8/2020
Creation Date:	6/25/2020
Receipt Date:	6/18/2020
Manifest ID:	020593103JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.049
Waste Quantity:	98
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	6/23/2020
Creation Date:	7/15/2020
Receipt Date:	7/2/2020
Manifest ID:	020593383JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0205
Waste Quantity:	41

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	5/5/2020
Creation Date:	5/21/2020
Receipt Date:	5/14/2020
Manifest ID:	020593602JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.027
Waste Quantity:	54
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	5/19/2020
Creation Date:	6/4/2020
Receipt Date:	5/28/2020
Manifest ID:	021199903JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0425
Waste Quantity:	85
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Additional Info:

Year:	2020
Gen EPA ID:	CAR000259994
Shipment Date:	9/9/2020
Creation Date:	9/29/2020
Receipt Date:	9/22/2020
Manifest ID:	021572164JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.022
Waste Quantity:	44
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/8/2020
Receipt Date:	9/29/2020
Manifest ID:	022023332JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0325
Waste Quantity:	65
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	8/26/2020
Creation Date:	9/18/2020
Receipt Date:	9/11/2020

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Manifest ID:	021572078JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.018
Waste Quantity:	36
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	8/12/2020
Creation Date:	9/1/2020
Receipt Date:	8/18/2020
Manifest ID:	020593282JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0325
Waste Quantity:	65
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	7/8/2020
Creation Date:	7/23/2020
Receipt Date:	7/16/2020
Manifest ID:	021198004JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0265
Waste Quantity:	53
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	7/23/2020
Creation Date:	8/12/2020
Receipt Date:	7/30/2020
Manifest ID:	021198080JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.026
Waste Quantity:	52
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	6/8/2020
Creation Date:	6/25/2020
Receipt Date:	6/18/2020
Manifest ID:	020593103JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.049

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Waste Quantity:	98
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	6/23/2020
Creation Date:	7/15/2020
Receipt Date:	7/2/2020
Manifest ID:	020593383JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	MOD095038998
Trans 2 Name:	BED ROCK INC DBA TRI STATE MOTOR TRANSIT CO
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0205
Waste Quantity:	41
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	5/5/2020
Creation Date:	5/21/2020
Receipt Date:	5/14/2020
Manifest ID:	020593602JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.027
Waste Quantity:	54
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Shipment Date:	5/19/2020
Creation Date:	6/4/2020
Receipt Date:	5/28/2020
Manifest ID:	021199903JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY NEVADA, INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0425
Waste Quantity:	85
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Detail Two:

Year:	2020
EM Manifest ID:	3cd4f9bb-7dd8-4631-91dc-7b24a12a3cac
Shipment Date:	9/9/2020
Receipt Date:	9/22/2020
Manifest Number:	021572164JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	800-451-8346
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MOD095038998
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2020
EM Manifest ID:	3cd4f9bb-7dd8-4631-91dc-7b24a12a3cac
Generator EPA ID:	CAR000259994
Shipment Date:	2020-09-09

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Manifest Number:	021572164JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02200
Quantity Waste:	44.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	484a88f8-3f11-4c10-8f2b-85745245c5d9
Shipment Date:	9/23/2020
Receipt Date:	9/29/2020
Manifest Number:	022023332JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	800-451-8346
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MOD095038998
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2020
EM Manifest ID:	484a88f8-3f11-4c10-8f2b-85745245c5d9
Generator EPA ID:	CAR000259994
Shipment Date:	2020-09-23
Manifest Number:	022023332JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.03250
Quantity Waste:	65.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	32beb802-a9ef-416a-b80d-63343029e4ae
Shipment Date:	8/26/2020

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Receipt Date:	9/11/2020
Manifest Number:	021572078JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	800-451-8346
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MOD095038998
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2020
EM Manifest ID:	32beb802-a9ef-416a-b80d-63343029e4ae
Generator EPA ID:	CAR000259994
Shipment Date:	2020-08-26
Manifest Number:	021572078JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.01800
Quantity Waste:	36.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	7b76c7e2-dddf-4eef-8dd7-e66ae0bddb49
Shipment Date:	8/12/2020
Receipt Date:	8/18/2020
Manifest Number:	020593282JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	800-451-8346
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MOD095038998
Transporter 2 Emergency Number:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF EPA ID: NVT330010000
TSDF Name: US ECOLOGY NEVADA, INC
TSDF Address 1: HWY 95 11 MI S OF BEATTY
TSDF Address 2: Not reported
TSDF City: BEATTY
TSDF Zip: 89003
TSDF Telephone: 800-839-3975

State:
Year: 2020
EM Manifest ID: 7b76c7e2-dddf-4eef-8dd7-e66ae0bddb49
Generator EPA ID: CAR000259994
Shipment Date: 2020-08-12
Manifest Number: 020593282JJK
Line Number: 1
Method Code: H132
Quantity Tons: 0.03250
Quantity Waste: 65.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Fiber or plastic boxes, cartons, cases
Quantity Type: Pounds
State Code: 352

Year: 2020
EM Manifest ID: c93395eb-0dc8-4cb1-a4b0-ff95bdd81470
Shipment Date: 7/23/2020
Receipt Date: 7/30/2020
Manifest Number: 021198080JJK
Generator EPA ID: CAR000259994
Name: FOOD 4 LESS - FUEL CENTER #318
Address: BROADWAY
Address 2: Not reported
City: LEMON GROVE
Zip: 91945
Telephone: 800-451-8346
Contact: Not reported
Contact Telephone: 800-451-8346
Transporter 1 EPA ID: MIK435642742
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MOD095038998
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: NVT330010000
TSDF Name: US ECOLOGY NEVADA, INC
TSDF Address 1: HWY 95 11 MI S OF BEATTY
TSDF Address 2: Not reported
TSDF City: BEATTY
TSDF Zip: 89003
TSDF Telephone: 800-839-3975

State:
Year: 2020
EM Manifest ID: c93395eb-0dc8-4cb1-a4b0-ff95bdd81470
Generator EPA ID: CAR000259994
Shipment Date: 2020-07-23
Manifest Number: 021198080JJK
Line Number: 1

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Method Code:	H132
Quantity Tons:	0.02600
Quantity Waste:	52.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	5e939d89-3201-4115-9f0f-3e2165d0e453
Shipment Date:	6/23/2020
Receipt Date:	7/2/2020
Manifest Number:	020593383JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	800-451-8346
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MOD095038998
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2020
EM Manifest ID:	5e939d89-3201-4115-9f0f-3e2165d0e453
Generator EPA ID:	CAR000259994
Shipment Date:	2020-06-23
Manifest Number:	020593383JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02050
Quantity Waste:	41.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	1092515
Shipment Date:	2/13/2020
Receipt Date:	2/28/2020
Manifest Number:	020771662JJK

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	ALR000007237
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2020
EM Manifest ID:	1092515
Generator EPA ID:	CAR000259994
Shipment Date:	2020-02-13
Manifest Number:	020771662JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.00950
Quantity Waste:	19.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	1092515
Generator EPA ID:	CAR000259994
Shipment Date:	2020-02-13
Manifest Number:	020771662JJK
Line Number:	2
Method Code:	H132
Quantity Tons:	0.04150
Quantity Waste:	83.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	02521165-3842-44a8-831a-1a3972d067ae
Shipment Date:	12/8/2020
Receipt Date:	12/17/2020
Manifest Number:	022022812JJK

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	800-451-8346
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MOD095038998
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2020
EM Manifest ID:	02521165-3842-44a8-831a-1a3972d067ae
Generator EPA ID:	CAR000259994
Shipment Date:	2020-12-08
Manifest Number:	022022812JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.00550
Quantity Waste:	11.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2020
EM Manifest ID:	b8dee7d4-78d7-4ffa-8993-79dc89051b39
Shipment Date:	12/2/2020
Receipt Date:	12/10/2020
Manifest Number:	022435060JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	800-451-8346
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MOD095038998
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Address 1: HWY 95 11 MI S OF BEATTY
TSDF Address 2: Not reported
TSDF City: BEATTY
TSDF Zip: 89003
TSDF Telephone: 800-839-3975

State:
Year: 2020
EM Manifest ID: b8dee7d4-78d7-4ffa-8993-79dc89051b39
Generator EPA ID: CAR000259994
Shipment Date: 2020-12-02
Manifest Number: 022435060JJK
Line Number: 1
Method Code: H132
Quantity Tons: 0.02650
Quantity Waste: 53.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Fiber or plastic boxes, cartons, cases
Quantity Type: Pounds
State Code: 352

Year: 2020
EM Manifest ID: b8dee7d4-78d7-4ffa-8993-79dc89051b39
Generator EPA ID: CAR000259994
Shipment Date: 2020-12-02
Manifest Number: 022435060JJK
Line Number: 2
Method Code: H141
Quantity Tons: 0.05750
Quantity Waste: 115.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 221

Year: 2020
EM Manifest ID: 6bb8ae6b-1cb8-4096-b477-2285bacdfe9f
Shipment Date: 10/6/2020
Receipt Date: 10/15/2020
Manifest Number: 021573518JJK
Generator EPA ID: CAR000259994
Name: FOOD 4 LESS - FUEL CENTER #318
Address: BROADWAY
Address 2: Not reported
City: LEMON GROVE
Zip: 91945
Telephone: 800-451-8346
Contact: Not reported
Contact Telephone: 800-451-8346
Transporter 1 EPA ID: MIK435642742
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MOD095038998
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: NVT330010000
TSDF Name: US ECOLOGY NEVADA, INC

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2020
EM Manifest ID:	6bb8ae6b-1cb8-4096-b477-2285bacdfe9f
Generator EPA ID:	CAR000259994
Shipment Date:	2020-10-06
Manifest Number:	021573518JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02850
Quantity Waste:	57.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Detail Two:

Year:	2019
EM Manifest ID:	482283
Shipment Date:	7/24/2019
Receipt Date:	8/1/2019
Manifest Number:	020260453JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2019
EM Manifest ID:	482283
Generator EPA ID:	CAR000259994
Shipment Date:	2019-07-24
Manifest Number:	020260453JJK
Line Number:	1
Method Code:	H132

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Quantity Tons:	0.03100
Quantity Waste:	62.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2019
EM Manifest ID:	d9d9e23b-df1a-40bf-9e0e-9f48e5b17a05
Shipment Date:	7/10/2019
Receipt Date:	7/26/2019
Manifest Number:	020267336JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2019
EM Manifest ID:	d9d9e23b-df1a-40bf-9e0e-9f48e5b17a05
Generator EPA ID:	CAR000259994
Shipment Date:	2019-07-10
Manifest Number:	020267336JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02200
Quantity Waste:	44.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2019
EM Manifest ID:	018856679JJK20180627_D_1
Shipment Date:	6/27/2018
Receipt Date:	7/5/2018
Manifest Number:	018856679JJK
Generator EPA ID:	CAR000259994

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Name:	FOOD 4 LESS 318-703 - FUEL CEN
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY INC
TSDF Address 1:	Not reported
TSDF Address 2:	Not reported
TSDF City:	Not reported
TSDF Zip:	Not reported
TSDF Telephone:	Not reported

State:

Year:	2019
EM Manifest ID:	018856679JJK20180627_D_1
Generator EPA ID:	CAR000259994
Shipment Date:	2018-06-27
Manifest Number:	018856679JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02950
Quantity Waste:	59.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	352

Year:	2019
EM Manifest ID:	787096
Shipment Date:	6/26/2019
Receipt Date:	7/9/2019
Manifest Number:	020266453JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2019
EM Manifest ID:	787096
Generator EPA ID:	CAR000259994
Shipment Date:	2019-06-26
Manifest Number:	020266453JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.03350
Quantity Waste:	67.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2019
EM Manifest ID:	39d7cb61-8d9f-45e9-83df-e49a65090c60
Shipment Date:	5/22/2019
Receipt Date:	5/30/2019
Manifest Number:	020260728JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2019
EM Manifest ID:	39d7cb61-8d9f-45e9-83df-e49a65090c60
Generator EPA ID:	CAR000259994
Shipment Date:	2019-05-22
Manifest Number:	020260728JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02250
Quantity Waste:	45.000000

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2019
EM Manifest ID:	608900
Shipment Date:	4/11/2019
Receipt Date:	4/25/2019
Manifest Number:	020260622JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2019
EM Manifest ID:	608900
Generator EPA ID:	CAR000259994
Shipment Date:	2019-04-11
Manifest Number:	020260622JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.04150
Quantity Waste:	83.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2019
EM Manifest ID:	325858
Shipment Date:	3/19/2019
Receipt Date:	4/2/2019
Manifest Number:	020260552JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	ALR000007237
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2019
EM Manifest ID:	325858
Generator EPA ID:	CAR000259994
Shipment Date:	2019-03-19
Manifest Number:	020260552JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02850
Quantity Waste:	57.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2019
EM Manifest ID:	288788
Shipment Date:	2/7/2019
Receipt Date:	2/13/2019
Manifest Number:	019623785JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2019
EM Manifest ID:	288788
Generator EPA ID:	CAR000259994
Shipment Date:	2019-02-07
Manifest Number:	019623785JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02600
Quantity Waste:	52.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2019
EM Manifest ID:	301167
Shipment Date:	2/20/2019
Receipt Date:	3/8/2019
Manifest Number:	019623844JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2019
EM Manifest ID:	301167
Generator EPA ID:	CAR000259994
Shipment Date:	2019-02-20
Manifest Number:	019623844JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02150
Quantity Waste:	43.000000
Quantity Unit:	P
Number of Containers:	1

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 352

Year: 2019
EM Manifest ID: 218005
Shipment Date: 12/11/2018
Receipt Date: 12/18/2018
Manifest Number: 019623781JJK
Generator EPA ID: CAR000259994
Name: FOOD 4 LESS - FUEL CENTER #318
Address: 7428 BROADWAY
Address 2: Not reported
City: LEMON GROVE
Zip: 91945
Telephone: 800-451-8346
Contact: Not reported
Contact Telephone: 310-884-4016
Transporter 1 EPA ID: MIK435642742
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: ALR000007237
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: NVT330010000
TSDF Name: US ECOLOGY NEVADA, INC
TSDF Address 1: HWY 95 11 MI S OF BEATTY
TSDF Address 2: Not reported
TSDF City: BEATTY
TSDF Zip: 89003
TSDF Telephone: 800-839-3975

State:
Year: 2019
EM Manifest ID: 218005
Generator EPA ID: CAR000259994
Shipment Date: 2018-12-11
Manifest Number: 019623781JJK
Line Number: 1
Method Code: H132
Quantity Tons: 0.02950
Quantity Waste: 59.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 352

Detail Two:
Year: 2018
EM Manifest ID: 017601452JJK20170928_D_1
Shipment Date: 9/28/2017
Receipt Date: 10/11/2017
Manifest Number: 017601452JJK
Generator EPA ID: CAR000259994
Name: FOOD 4 LESS 318-703 - FUEL CEN
Address: Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	ALR000007237
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY INC
TSDF Address 1:	Not reported
TSDF Address 2:	Not reported
TSDF City:	Not reported
TSDF Zip:	Not reported
TSDF Telephone:	Not reported

Federal:

Year:	2018
EM Manifest ID:	017601452JJK20170928_D_1
Generator EPA ID:	CAR000259994
Shipment Date:	2017-09-28
Manifest Number:	017601452JJK
Line Number:	1
Method Code:	H141
Quantity Tons:	0.07600
Quantity Waste:	152.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
Federal Code:	D018

State:

Year:	2018
EM Manifest ID:	017601452JJK20170928_D_1
Generator EPA ID:	CAR000259994
Shipment Date:	2017-09-28
Manifest Number:	017601452JJK
Line Number:	1
Method Code:	H141
Quantity Tons:	0.07600
Quantity Waste:	152.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	331

Year:	2018
EM Manifest ID:	017601452JJK20170928_D_1
Generator EPA ID:	CAR000259994
Shipment Date:	2017-09-28
Manifest Number:	017601452JJK
Line Number:	2
Method Code:	H132

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Quantity Tons:	0.00650
Quantity Waste:	13.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	352

Year:	2018
EM Manifest ID:	152183
Shipment Date:	9/25/2018
Receipt Date:	10/15/2018
Manifest Number:	019623725JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2018
EM Manifest ID:	152183
Generator EPA ID:	CAR000259994
Shipment Date:	2018-09-25
Manifest Number:	019623725JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02500
Quantity Waste:	50.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2018
EM Manifest ID:	017601430JJK20170913_D_1
Shipment Date:	9/13/2017
Receipt Date:	10/2/2017
Manifest Number:	017601430JJK
Generator EPA ID:	CAR000259994

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Name:	FOOD 4 LESS 318-703 - FUEL CEN
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	ALR000007237
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY INC
TSDF Address 1:	Not reported
TSDF Address 2:	Not reported
TSDF City:	Not reported
TSDF Zip:	Not reported
TSDF Telephone:	Not reported

State:

Year:	2018
EM Manifest ID:	017601430JJK20170913_D_1
Generator EPA ID:	CAR000259994
Shipment Date:	2017-09-13
Manifest Number:	017601430JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02300
Quantity Waste:	46.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	352

Year:	2018
EM Manifest ID:	123991
Shipment Date:	9/10/2018
Receipt Date:	10/1/2018
Manifest Number:	019623685JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Address 2: Not reported
TSDF City: BEATTY
TSDF Zip: 89003
TSDF Telephone: 800-839-3975

Federal:
Year: 2018
EM Manifest ID: 123991
Generator EPA ID: CAR000259994
Shipment Date: 2018-09-10
Manifest Number: 019623685JJK
Line Number: 2
Method Code: H141
Quantity Tons: 0.06350
Quantity Waste: 127.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
Federal Code: D018

State:
Year: 2018
EM Manifest ID: 123991
Generator EPA ID: CAR000259994
Shipment Date: 2018-09-10
Manifest Number: 019623685JJK
Line Number: 1
Method Code: H132
Quantity Tons: 0.02150
Quantity Waste: 43.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 352

Year: 2018
EM Manifest ID: 123991
Generator EPA ID: CAR000259994
Shipment Date: 2018-09-10
Manifest Number: 019623685JJK
Line Number: 2
Method Code: H141
Quantity Tons: 0.06350
Quantity Waste: 127.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 331

Year: 2018
EM Manifest ID: 82680
Shipment Date: 8/22/2018
Receipt Date: 9/6/2018

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Manifest Number:	018583611JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY NEVADA, INC
TSDF Address 1:	HWY 95 11 MI S OF BEATTY
TSDF Address 2:	Not reported
TSDF City:	BEATTY
TSDF Zip:	89003
TSDF Telephone:	800-839-3975

State:

Year:	2018
EM Manifest ID:	82680
Generator EPA ID:	CAR000259994
Shipment Date:	2018-08-22
Manifest Number:	018583611JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.02250
Quantity Waste:	45.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Metal drums, barrels, kegs
Quantity Type:	Pounds
State Code:	352

Year:	2018
EM Manifest ID:	81195
Shipment Date:	7/25/2018
Receipt Date:	8/9/2018
Manifest Number:	018866225JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS - FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945
Telephone:	800-451-8346
Contact:	Not reported
Contact Telephone:	310-884-4016
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	MIK435642742
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Name: US ECOLOGY NEVADA, INC
TSDF Address 1: HWY 95 11 MI S OF BEATTY
TSDF Address 2: Not reported
TSDF City: BEATTY
TSDF Zip: 89003
TSDF Telephone: 800-839-3975

State:
Year: 2018
EM Manifest ID: 81195
Generator EPA ID: CAR000259994
Shipment Date: 2018-07-25
Manifest Number: 018866225JJK
Line Number: 1
Method Code: H132
Quantity Tons: 0.02900
Quantity Waste: 58.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Metal drums, barrels, kegs
Quantity Type: Pounds
State Code: 352

Year: 2018
EM Manifest ID: 017601226JJK20170725_D_1
Shipment Date: 7/25/2017
Receipt Date: 8/3/2017
Manifest Number: 017601226JJK
Generator EPA ID: CAR000259994
Name: FOOD 4 LESS 318-703 - FUEL CEN
Address: Not reported
Address 2: Not reported
City: Not reported
Zip: Not reported
Telephone: Not reported
Contact: Not reported
Contact Telephone: Not reported
Transporter 1 EPA ID: MIK435642742
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: ALR000007237
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: NVT330010000
TSDF Name: US ECOLOGY INC
TSDF Address 1: Not reported
TSDF Address 2: Not reported
TSDF City: Not reported
TSDF Zip: Not reported
TSDF Telephone: Not reported

State:
Year: 2018
EM Manifest ID: 017601226JJK20170725_D_1
Generator EPA ID: CAR000259994
Shipment Date: 2017-07-25
Manifest Number: 017601226JJK
Line Number: 1
Method Code: H132

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Quantity Tons:	0.01750
Quantity Waste:	35.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	352

Year:	2018
EM Manifest ID:	016030692JJK20170711_D_1
Shipment Date:	7/11/2017
Receipt Date:	7/19/2017
Manifest Number:	016030692JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS 318-703 - FUEL CEN
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	ALR000007237
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY INC
TSDF Address 1:	Not reported
TSDF Address 2:	Not reported
TSDF City:	Not reported
TSDF Zip:	Not reported
TSDF Telephone:	Not reported

State:

Year:	2018
EM Manifest ID:	016030692JJK20170711_D_1
Generator EPA ID:	CAR000259994
Shipment Date:	2017-07-11
Manifest Number:	016030692JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.00450
Quantity Waste:	9.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	352

Year:	2018
EM Manifest ID:	016030385JJK20170627_D_1
Shipment Date:	6/27/2017
Receipt Date:	7/3/2017
Manifest Number:	016030385JJK
Generator EPA ID:	CAR000259994

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Name:	FOOD 4 LESS 318-703 - FUEL CEN
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	ALR000007237
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY INC
TSDF Address 1:	Not reported
TSDF Address 2:	Not reported
TSDF City:	Not reported
TSDF Zip:	Not reported
TSDF Telephone:	Not reported

State:

Year:	2018
EM Manifest ID:	016030385JJK20170627_D_1
Generator EPA ID:	CAR000259994
Shipment Date:	2017-06-27
Manifest Number:	016030385JJK
Line Number:	1
Method Code:	H132
Quantity Tons:	0.01350
Quantity Waste:	27.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	NULL
Quantity Type:	NULL
State Code:	352

Year:	2018
EM Manifest ID:	016030407JJK20170616_D_1
Shipment Date:	6/16/2017
Receipt Date:	6/26/2017
Manifest Number:	016030407JJK
Generator EPA ID:	CAR000259994
Name:	FOOD 4 LESS 318-703 - FUEL CEN
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	MIK435642742
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	ALR000007237
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	NVT330010000
TSDF Name:	US ECOLOGY INC
TSDF Address 1:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

TSDF Address 2: Not reported
TSDF City: Not reported
TSDF Zip: Not reported
TSDF Telephone: Not reported

State:
Year: 2018
EM Manifest ID: 016030407JJK20170616_D_1
Generator EPA ID: CAR000259994
Shipment Date: 2017-06-16
Manifest Number: 016030407JJK
Line Number: 1
Method Code: H132
Quantity Tons: 0.02750
Quantity Waste: 55.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: NULL
Quantity Type: NULL
State Code: 352

Additional Info:
Year: 2017
Gen EPA ID: CAR000259994

Shipment Date: 20171227
Creation Date: 10/16/2018 18:30:53
Receipt Date: 20180116
Manifest ID: 017602997JJK
Trans EPA ID: MIK435642742
Trans Name: EQ INDUSTRIAL SERVICES
Trans 2 EPA ID: ALR000007237
Trans 2 Name: ACTION RESOURCES INC
TSDF EPA ID: NVT330010000
Trans Name: US ECOLOGY INC
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 352 - Other organic solids
RCRA Code: Not reported
Meth Code: H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons: 0.012
Waste Quantity: 24
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 20171213
Creation Date: 10/16/2018 18:31:15
Receipt Date: 20171220
Manifest ID: 017601498JJK
Trans EPA ID: MIK435642742
Trans Name: EQ INDUSTRIAL SERVICES

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.013
Waste Quantity:	26
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20171116
Creation Date:	7/20/2018 18:30:10
Receipt Date:	20171129
Manifest ID:	017602792JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.015
Waste Quantity:	30
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20171026
Creation Date:	10/16/2018 18:31:43
Receipt Date:	20171106
Manifest ID:	017602596JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.006
Waste Quantity:	12
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20171012
Creation Date:	7/10/2018 18:30:24
Receipt Date:	20171024
Manifest ID:	017602734JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0085
Waste Quantity:	17
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170928
Creation Date:	7/11/2018 18:30:30
Receipt Date:	20171011
Manifest ID:	017601452JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0065
Waste Quantity:	13
Quantity Unit:	P
Additional Code 1:	Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170928
Creation Date:	7/11/2018 18:30:30
Receipt Date:	20171011
Manifest ID:	017601452JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D018
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.076
Waste Quantity:	152
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170913
Creation Date:	7/11/2018 18:32:18
Receipt Date:	20171002
Manifest ID:	017601430JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.023
Waste Quantity:	46
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170725
Creation Date:	8/2/2018 18:30:33

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Receipt Date:	20170803
Manifest ID:	017601226JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0175
Waste Quantity:	35
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20170711
Creation Date:	7/6/2018 18:30:51
Receipt Date:	20170719
Manifest ID:	016030692JJK
Trans EPA ID:	MIK435642742
Trans Name:	EQ INDUSTRIAL SERVICES
Trans 2 EPA ID:	ALR000007237
Trans 2 Name:	ACTION RESOURCES INC
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0045
Waste Quantity:	9
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

CERS:

Name:	FOOD 4 LESS FUEL CENTER #318
Address:	7428 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	30896
CERS ID:	10230532
CERS Description:	Chemical Storage Facilities

Violations:

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-06-2017
Citation:	23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description:	Failure of the overfill prevention system to meet one of the following requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.
Violation Notes:	Returned to compliance on 12/28/2017. Inspection Sequence ID:5715791;Tank ID:32010-NT2508-3,22010-NT2508-2;Violation Description:(RP) Failure of the overfill prevention system to meet one of the following requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity; and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 23 CCR 2635(b)(2), 2665
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,

Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-16-2022
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 12/07/2022. Inspection Sequence ID:7009199;Violation:HMD0138 Manifest signed by the TSDF not available for inspection. 22 CCR 66262.40(a); HSC 25185(a)(4)
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,

Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-29-2021
Citation:	23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)
Violation Description:	Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.
Violation Notes:	Returned to compliance on 09/29/2021. Inspection Sequence

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

	ID:6798192;Tank ID:32010-NT2508-3;Violation Description:(TCR 9d) Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained in accordance with manufacturer's instructions. 23 CCR 2638(a), 2641(j)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-16-2022
Citation:	HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 10/27/2022. Inspection Sequence ID:7009199
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-12-2019
Citation:	23 CCR 16 2715(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(f)
Violation Description:	Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.).
Violation Notes:	Returned to compliance on 09/27/2019. Inspection Sequence ID:6232574;Tank ID:2010-NT2508-1,22010-NT2508-2,32010-NT2508-3;Violation Description:(TCR 9d) Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.). 23 CCR 2638(a)(b), 2651(j), 2715(f).
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-12-2019
Citation:	HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description:	"Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Violation Notes:	Returned to compliance on 09/27/2019. Inspection Sequence ID:6232574;Tank ID:2010-NT2508-1;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-12-2019
Citation:	23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)
Violation Description:	Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.
Violation Notes:	Returned to compliance on 09/12/2019. Inspection Sequence ID:6232574;Tank ID:2010-NT2508-1,22010-NT2508-2;Violation Description:(TCR 9d) Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly. 23 CCR 2638(a), 2641(j)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-06-2018
Citation:	23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Description:	Failure to comply with one or more of the following: Failure to install or maintain a liquid-tight spill bucket. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container. Be resistant to galvanic corrosion.
Violation Notes:	Returned to compliance on 09/06/2018. Inspection Sequence ID:5963450;Tank ID:22010-NT2508-2;Violation Description:(RP) Failure to comply with one or more of the following: Failure to install or maintain a liquid-tight spill bucket, have a minimum capacity of 5 gallons, have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container, and/or be resistant to galvanic corrosion. 23 CCR 2635(b), 2665
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-29-2021

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Citation:	23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description:	Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.
Violation Notes:	Returned to compliance on 09/29/2021. Inspection Sequence ID:6798192;Tank ID:2010-NT2508-1,22010-NT2508-2,32010-NT2508-3;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requireme
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	30896
Site Name:	Food 4 Less Fuel Center #318
Violation Date:	09-16-2022
Citation:	HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description:	"Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "

Violation Notes: Returned to compliance on 09/16/2022. Inspection Sequence ID:7009199;Tank ID:2010-NT2508-1,32010-NT2508-3;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: 1) Install or maintain a liquid-tight spill container. 2) Have a minimum capacity of 5 gallons. 3) Have a functional drain valve or other method for the removal of liquid from the spill container. 4) Be resistant to galvanic corrosion. 5) Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. 6) Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 7) Tested by a certified UST service technician. 8) Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 30896
Site Name: Food 4 Less Fuel Center #318
Violation Date: 09-16-2022
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description: Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.
Violation Notes: Returned to compliance on 09/16/2022. Inspection Sequence ID:7009199;Tank ID:2010-NT2508-1;Violation Description:(TCR 9d) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: 1) Monitored with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch within an hour. 2) Restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-06-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5715791
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Eval Date: 09-06-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5963450
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-06-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5963450
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-08-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5488450
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-10-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fernandez Juan Inspection ID:5116926
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 09-16-2020
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: "No On-site Inspection" Inspector: Villena Elaine Inspection ID:6494533
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-16-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:7009199
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-06-2017
Violations Found: Yes

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5715791
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-08-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5488450
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-09-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5127077
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-12-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6232574
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-12-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6232574
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-16-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:7009199
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-16-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:7009199
Eval Division: San Diego County Department of Env Health

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-29-2021
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chavarin Yvonne Inspection ID:6798192
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-09-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5127077
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-10-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fernandez Juan Inspection ID:5116926
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-12-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6232574
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-06-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5715791
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-06-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5963450
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-08-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5488450
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-09-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5127077
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-10-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fernandez Juan Inspection ID:5116926
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Coordinates:
Site ID: 30896
Facility Name: Food 4 Less Fuel Center #318
Env Int Type Code: HWG
Program ID: 10230532
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.743760
Longitude: -117.037500

Affiliation:
Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Affiliation Type Desc: Operator
Entity Name: FOOD 4 LESS
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Affiliation Phone:	(310) 884-9000,
Affiliation Type Desc:	Document Preparer
Entity Name:	BELSHIRE ENVIRONMENTAL SERVICES, INC.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Legal Owner
Entity Name:	FOOD 4 LESS
Entity Title:	Not reported
Affiliation Address:	P.O. BOX 54143
Affiliation City:	LOS ANGELES
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90054
Affiliation Phone:	(310) 884-9000,
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	FOOD 4 LESS
Entity Title:	Not reported
Affiliation Address:	1100 W ARTESIA BLVD.
Affiliation City:	COMPTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90220
Affiliation Phone:	(310) 884-9000,
Affiliation Type Desc:	UST Tank Operator
Entity Name:	FOOD 4 LESS
Entity Title:	Not reported
Affiliation Address:	1100 W ARTESIA BLVD.
Affiliation City:	COMPTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90220
Affiliation Phone:	(310) 884-9000,
Affiliation Type Desc:	Parent Corporation
Entity Name:	Ralphs Grocery Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Environmental Contact
Entity Name:	CHARLES COUSAR
Entity Title:	Not reported
Affiliation Address:	P.O. BOX 54143
Affiliation City:	LOS ANGELES

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90054
Affiliation Phone:	,
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	1100 W ARTESIA BLVD.
Affiliation City:	COMPTON
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90220
Affiliation Phone:	,
Affiliation Type Desc:	Identification Signer
Entity Name:	CHARLES COUSAR
Entity Title:	FOOD 4 LESS DIVISION FUEL MANAGER
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Property Owner
Entity Name:	FOOD 4 LESS
Entity Title:	Not reported
Affiliation Address:	1100 W ARTESIA BLVD.
Affiliation City:	COMPTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90220
Affiliation Phone:	(310) 884-9000,
Affiliation Type Desc:	UST Permit Applicant
Entity Name:	CHARLES COUSAR
Entity Title:	FOOD 4 LESS DIVISION FUEL MANAGER
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(310) 884-4011,
Affiliation Type Desc:	UST Tank Owner
Entity Name:	FOOD 4 LESS
Entity Title:	Not reported
Affiliation Address:	1100 W ARTESIA BLVD.
Affiliation City:	COMPTON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90220
Affiliation Phone:	(310) 884-9000,

FOOD 4 LESS FUEL CENTER #318 (Continued) **S119095687**

HWTS:

Name:	FOOD 4 LESS FUEL CENTER #318
Address:	7428 BROADWAY
Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 91945
EPA ID:	CAR000259994
Inactive Date:	Not reported
Create Date:	04/18/2016
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	PO BOX 80842
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SEATTLE, WA 98108
Owner Name:	RALPHS GROCERY CO
Owner Address:	PO BOX 80842
Owner Address 2:	Not reported
Owner City,State,Zip:	SEATTLE, WA 98108
Contact Name:	MATTHEW EATON
Contact Address:	1100 W. ARTESIA BLVD.
Contact Address 2:	Not reported
City,State,Zip:	COMPTON, CA 90220
Facility Status:	Active
Facility Type:	PERMANENT
Category:	FEDERAL
Latitude:	32.7429
Longitude:	-117.037701

NAICS:

EPA ID:	CAR000259994
Create Date:	2016-04-18 16:03:30.967
NAICS Code:	44711
NAICS Description:	Gasoline Stations with Convenience Stores
Issued EPA ID Date:	2016-04-18 16:03:30.94000
Inactive Date:	Not reported
Facility Name:	FOOD 4 LESS FUEL CENTER #318
Facility Address:	7428 BROADWAY
Facility Address 2:	Not reported
Facility City:	LEMON GROVE
Facility County:	Not reported
Facility State:	CA
Facility Zip:	91945

E24 **FOOD 4 LESS - FUEL CENTER #318** **RCRA-LQG** **1018273798**
SSE **7428 BROADWAY** **CAR000259994**
1/8-1/4 **LEMON GROVE, CA 91945**
0.181 mi.
955 ft. **Site 3 of 6 in cluster E**

Relative: **Lower**

Actual: **426 ft.**

RCRA Listings:

Date Form Received by Agency:	20160404
Handler Name:	FOOD 4 LESS - FUEL CENTER #318
Handler Address:	7428 BROADWAY
Handler City,State,Zip:	LEMON GROVE, CA 91945
EPA ID:	CAR000259994
Contact Name:	SHERRIE WALTERS
Contact Address:	W ARTESIA BLVD
Contact City,State,Zip:	COMPTON, CA 90220

FOOD 4 LESS - FUEL CENTER #318 (Continued) **1018273798**

Contact Telephone:	310-884-4016
Contact Fax:	Not reported
Contact Email:	SHERRIE.WALTERS@RALPHS.COM
Contact Title:	MANAGER ENVIRONMENTAL AFFAIRS
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	W ARTESIA BLVD
Mailing City,State,Zip:	COMPTON, CA 90220
Owner Name:	KROGER COMPANY (FOOD 4 LESS)
Owner Type:	Private
Operator Name:	RALPHS GROCERY COMPANY
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

FOOD 4 LESS - FUEL CENTER #318 (Continued) **1018273798**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20160418
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: KROGER COMPANY (FOOD 4 LESS)	
Legal Status:	Private
Date Became Current:	20061109
Date Ended Current:	Not reported
Owner/Operator Address:	1100 W ARTESIA BLVD
Owner/Operator City,State,Zip:	COMPTON, CA 90220
Owner/Operator Telephone:	310-884-9000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: RALPHS GROCERY COMPANY	
Legal Status:	Private
Date Became Current:	20111005
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20160404
Handler Name: FOOD 4 LESS - FUEL CENTER #318	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Not reported

FOOD 4 LESS - FUEL CENTER #318 (Continued) **1018273798**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	447110
NAICS Description:	GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

D25 **JOE YOUSIF** **RCRA NonGen / NLR** **1026811432**
SSW **3521 HARRIS ST.** **CAC003123891**
1/8-1/4 **LEMON GROVE, CA 91945**
0.182 mi.
960 ft. **Site 3 of 8 in cluster D**

Relative: **Lower**
Actual: **426 ft.**

RCRA Listings:

Date Form Received by Agency:		20210610
Handler Name:	JOE YOUSIF	
Handler Address:		3521 HARRIS ST.
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAC003123891
Contact Name:		JOE YOUSIF
Contact Address:		3521 HARRIS ST.
Contact City,State,Zip:		LEMON GROVE, CA 91945
Contact Telephone:		619-241-6561
Contact Fax:		Not reported
Contact Email:		SDABATEMENT@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3521 HARRIS ST.
Mailing City,State,Zip:		LEMON GROVE, CA 91945
Owner Name:	JOE YOUSIF	
Owner Type:		Other
Operator Name:	JOE YOUSIF	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No

JOE YOUSIF (Continued) **1026811432**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20210618
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:
Owner/Operator Indicator: Operator

JOE YOUSIF (Continued) **1026811432**

Owner/Operator Name: JOE YOUSIF
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3521 HARRIS ST.
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945
Owner/Operator Telephone: 619-241-6561
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JOE YOUSIF
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3521 HARRIS ST.
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945
Owner/Operator Telephone: 619-241-6561
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20210610
Handler Name: JOE YOUSIF
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F26 **PAUL EK** **RCRA NonGen / NLR** **1027090064**
SW **3590 CITRUS STREET** **CAC003162561**
1/8-1/4 **LEMON GROVE, CA 91945**
0.182 mi.
961 ft. **Site 1 of 2 in cluster F**

Relative: **Lower**
Actual: **445 ft.**

RCRA Listings:

Date Form Received by Agency:		20220218
Handler Name:	PAUL EK	
Handler Address:		3590 CITRUS STREET
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAC003162561
Contact Name:		PAUL EK
Contact Address:		3590 CITRUS STREET
Contact City,State,Zip:		LEMON GROVE, CA 91945
Contact Telephone:		619-436-8703
Contact Fax:		Not reported
Contact Email:		LRIVERO@APEX411.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3590 CITRUS STREET
Mailing City,State,Zip:		LEMON GROVE, CA 91945
Owner Name:	PAUL EK	
Owner Type:		Other
Operator Name:	PAUL EK	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

PAUL EK (Continued) **1027090064**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20220223
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: PAUL EK	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3590 CITRUS STREET
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945
Owner/Operator Telephone:	619-436-8703
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: PAUL EK	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3590 CITRUS STREET
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945
Owner/Operator Telephone:	619-436-8703
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

PAUL EK (Continued) **1027090064**

Historic Generators:
Receive Date: 20220218
Handler Name: PAUL EK
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D27 **JOE YOUSIF** **RCRA NonGen / NLR** **1026818751**
SSW **3515-3521 HARRIS ST** **CAC003131552**
1/8-1/4 **LEMON GROVE, CA 91945**
0.185 mi.
978 ft. **Site 4 of 8 in cluster D**

Relative: **Lower**
Actual: **425 ft.**

RCRA Listings:
Date Form Received by Agency: 20210728
Handler Name: JOE YOUSIF
Handler Address: 3515-3521 HARRIS ST
Handler City,State,Zip: LEMON GROVE, CA 91945
EPA ID: CAC003131552
Contact Name: JOE YOUSIF
Contact Address: 3515-3521 HARRIS ST
Contact City,State,Zip: LEMON GROVE, CA 91945
Contact Telephone: 619-241-6561
Contact Fax: Not reported
Contact Email: SDABATEMENT@GMAIL.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Not reported
State District: Not reported
Mailing Address: 3515-3521 HARRIS ST
Mailing City,State,Zip: LEMON GROVE, CA 91945
Owner Name: JOE YOUSIF

JOE YOUSIF (Continued) **1026818751**

Owner Type:		Other
Operator Name:	JOE YOUSIF	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	
Handler Date of Last Change:		20210730
Recognized Trader-Importer:		No
Recognized Trader-Exporter:		No
Importer of Spent Lead Acid Batteries:		No
Exporter of Spent Lead Acid Batteries:		No
Recycler Activity Without Storage:		No
Manifest Broker:		No

JOE YOUSIF (Continued) **1026818751**

Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: JOE YOUSIF
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3515-3521 HARRIS ST
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945
Owner/Operator Telephone: 619-241-6561
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JOE YOUSIF
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3515-3521 HARRIS ST
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945
Owner/Operator Telephone: 619-241-6561
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20210728
Handler Name: JOE YOUSIF
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G28 **LEMON GROVE VETERINARY HOSP** **San Diego Co. HMMD** **S123406764**
SE **7572 NORTH AVE** **CERS HAZ WASTE** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945** **CERS**
0.195 mi.
1029 ft. **Site 1 of 6 in cluster G**

Relative:
Lower

Actual:
456 ft.

HMMD SAN DIEGO:

Name:	LEMON GROVE VETERINARY HOSP
Address:	7572 NORTH AVE
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CA1000170365
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	6194630301
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	08/09/2022
Facility Owner:	Not reported
Facility Mailing Address:	7572 NORTH AVE, LEMON GROVE, CA 91945
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	N
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2002-HUPFP-150387
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-150387
Program Element:	Medical Waste
Inspection Type:	Status Verification
Inspection Number:	5068728
Return To Compliance Date:	2014-07-16T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-09T00:00:00.000
Inspection Date:	2014-07-11T15:43:00.000
Violation Code:	4306 Full sharps container stored >30 days at >0 Degrees Celsius. 118285(c)

Waste and Materials:

Record ID:	DEH2002-HUPFP-150387
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2014-HWAST-0028909
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2022-08-09T02:33:32.000
Chemical Name:	Sharps waste

LEMON GROVE VETERINARY HOSP (Continued) **S123406764**

Common Name: sharps waste
Case Number: Not reported

Record ID: DEH2002-HUPFP-150387
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2014-HWAST-0028910
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-08-09T02:33:32.000
Chemical Name: silver waste
Common Name: silver waste
Case Number: Not reported

CERS HAZ WASTE:
Name: LEMON GROVE VETERINARY HOSP
Address: 7572 NORTH AVE
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 43981
CERS ID: 10361236
CERS Description: Hazardous Waste Generator

CERS:
Name: LEMON GROVE VETERINARY HOSP
Address: 7572 NORTH AVE
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 43981
CERS ID: 10361236
CERS Description: Chemical Storage Facilities

Evaluation:
Eval General Type: Other/Unknown
Eval Date: 07-11-2014
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Inspector: Fitzmaurice Mark Inspection ID:5068728
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Coordinates:
Site ID: 43981
Facility Name: LEMON GROVE VETERINARY HOSP
Env Int Type Code: HWG
Program ID: 10361236
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.744800
Longitude: -117.034940

Affiliation:
Affiliation Type Desc: Document Preparer
Entity Name: Anilkumar Bettegowda
Entity Title: Not reported
Affiliation Address: Not reported

LEMON GROVE VETERINARY HOSP (Continued) **S123406764**

Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Legal Owner
Entity Name:	Anilkumar Bettegowda
Entity Title:	Not reported
Affiliation Address:	7572 NORTH AVE
Affiliation City:	LEMON GROVE
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91945
Affiliation Phone:	(619) 463-0301,
Affiliation Type Desc:	Environmental Contact
Entity Name:	Anilkumar Bettegowda
Entity Title:	Not reported
Affiliation Address:	7572 NORTH AVE
Affiliation City:	LEMON GROVE
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91945
Affiliation Phone:	,
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	7572 North Avenue
Affiliation City:	Lemon Grove
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91945
Affiliation Phone:	,
Affiliation Type Desc:	Identification Signer
Entity Name:	Anil Bettegowda
Entity Title:	President, Gowda Veterinary, Inc.
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Operator
Entity Name:	Anil Bettegowda
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 463-0301,
Affiliation Type Desc:	Parent Corporation

LEMON GROVE VETERINARY HOSP (Continued) **S123406764**

Entity Name:	Lemon Grove Veterinary Hospital
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Property Owner
Entity Name:	JACQUELYN BURNS
Entity Title:	Not reported
Affiliation Address:	7572 NORTH AVE
Affiliation City:	LEMON GROVE
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91945
Affiliation Phone:	(619) 415-9323,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,

E29 **PRONTO AUTO REPAIR** **San Diego Co. HMMD** **S104747507**
South **7385 LEMON AVE** **CERS HAZ WASTE** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945** **HAZNET**
0.196 mi. **CERS**
1037 ft. **Site 4 of 6 in cluster E** **HWTS**

Relative: **Lower**

Actual: **423 ft.**

HMMD SAN DIEGO:

Name:	PRONTO AUTO REPAIR
Address:	7385 LEMON AV
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	207389
Business Type:	6HK26
EPA Id Number:	CAL000257951
APN:	DEH-112816
Last HMMD Inspection:	02/04/2010
Facility Telephone:	619-461-3914
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	PRONTO AUTO REPAIR
Facility Mailing Address:	7385 LEMON AV
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported

PRONTO AUTO REPAIR (Continued) **S104747507**

Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):

Permit Number: 207389
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 213 HYDROCARBON SOLVENTS
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 207389
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 207389
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: ANTIFREEZE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 207389
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: USED LEAD ACID BATTERIES
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 207389
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: VORTEX
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 207389
Update Date: 11/02/2012
Inspection Date: 05/05/2008
Violation Code: 6HV0225
Violation: ACCUMULATED HW>180 OR >270 DAYS
Violation Citation: Accumulated waste too long (>180 or 270 days). 66262.34(d), CFR

PRONTO AUTO REPAIR (Continued) **S104747507**

262.34(e)&(f), &/or 25201(a) [>90 days for AHW waste]
Activity: ACTIVE

Name: ENGINE CITY
Address: 7385 LEMON AV
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 112816
Business Type: 6HK26
EPA Id Number: Not reported
APN: DEH-112816
Last HMMD Inspection: 06/16/1999
Facility Telephone: 619-465-6678
Permit Status: INAC
Permit Expiration: 08/31/1999
Date Last Updated: 11/02/2012
Facility Owner: HONG NGUYEN
Facility Mailing Address: 7385 LEMON AV
Facility Mailing City: LEMON GROVE
Facility Mailing State: CA
Facility Mailing Zip: 91945-1523
UST Owner: Not reported
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Name: PRONTO AUTO REPAIR
Address: 7385 LEMON AVE
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: Not reported
Business Type: Not reported
EPA Id Number: CAL000267951
APN: Not reported
Last HMMD Inspection: Not reported
Facility Telephone: 619-461-3914
Permit Status: Permit Renewed
Permit Expiration: Not reported
Date Last Updated: 03/01/2022
Facility Owner: Not reported
Facility Mailing Address: 7385 LEMON AV, LEMON GROVE, CA 91945
Facility Mailing City: Not reported
Facility Mailing State: Not reported
Facility Mailing Zip: Not reported
UST Owner: N
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: N
Generate Medical Waste: Not reported

Inspection Violation:
Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y

PRONTO AUTO REPAIR (Continued) **S104747507**

Facility Id Number:	37-000-207389
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5879748
Return To Compliance Date:	2018-04-10T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-03-01T00:00:00.000
Inspection Date:	2018-04-02T07:35:00.000
Violation Code:	HMD0226 Did not accumulate waste in a container or tank. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2)

Record ID:	DEH2006-HUPFP-207389
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207389
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5395731
Return To Compliance Date:	2016-04-25T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-03-01T00:00:00.000
Inspection Date:	2016-04-05T08:45:00.000
Violation Code:	1010006 HMBP not updated to reflect inventory changes or facility information. HSC 25508.1(a-e)

Record ID:	DEH2006-HUPFP-207389
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207389
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5879748
Return To Compliance Date:	2018-04-10T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-03-01T00:00:00.000
Inspection Date:	2018-04-02T07:35:00.000
Violation Code:	1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Record ID:	DEH2006-HUPFP-207389
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207389
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6412772

PRONTO AUTO REPAIR (Continued) **S104747507**

Return To Compliance Date:	2021-04-27T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-03-01T00:00:00.000
Inspection Date:	2021-04-27T06:54:18.000
Violation Code:	1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Record ID:	DEH2006-HUPFP-207389
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207389
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5879748
Return To Compliance Date:	2018-04-10T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-03-01T00:00:00.000
Inspection Date:	2018-04-02T07:35:00.000
Violation Code:	3030004 Failed to properly manage, store, label &/or recycle used oil filters &/or used fuel filters. HSC 25250.22; 22 CCR 66266.130

Record ID:	DEH2006-HUPFP-207389
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207389
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5395731
Return To Compliance Date:	2016-05-03T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-03-01T00:00:00.000
Inspection Date:	2016-04-05T08:45:00.000
Violation Code:	1020002 Initial and/or annual employee training not conducted for hazardous materials management and/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4)

Waste and Materials:

Record ID:	DEH2006-HUPFP-207389
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HWAST-0268065
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2022-03-01T02:32:11.000
Chemical Name:	WASTE 213 Hydrocarbon Solvents
Common Name:	PARTS WASHER

PRONTO AUTO REPAIR (Continued) **S104747507**

Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0268066
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-01T02:32:11.000
Chemical Name: WASTE 221 WASTE OIL & MIXED OIL
Common Name: USED OIL
Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0268067
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-01T02:32:11.000
Chemical Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Common Name: WASTE ANTIFREEZE
Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0268068
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-01T02:32:11.000
Chemical Name: Used Oil saturated absorbent
Common Name: Used Oil saturated absorbent
Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0081409
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-03-02T02:30:17.000
Chemical Name: WASTE 221 WASTE OIL & MIXED OIL
Common Name: USED OIL
Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151833
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-04-29T04:04:33.000
Chemical Name: WASTE 213 Hydrocarbon Solvents
Common Name: PARTS WASHER
Case Number: Not reported

PRONTO AUTO REPAIR (Continued) **S104747507**

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151834
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-04-29T04:04:33.000
Chemical Name: WASTE 221 WASTE OIL & MIXED OIL
Common Name: USED OIL
Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151835
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-04-29T04:04:33.000
Chemical Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Common Name: WASTE ANTIFREEZE
Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151836
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-04-29T04:04:33.000
Chemical Name: Used Oil Filters (Drained)
Common Name: Used Oil Filters (Drained)
Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0081408
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-03-02T02:30:17.000
Chemical Name: WASTE 213 Hydrocarbon Solvents
Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2006-HUPFP-207389
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0081410
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-03-02T02:30:17.000
Chemical Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Common Name: WASTE ANTIFREEZE
Case Number: Not reported

PRONTO AUTO REPAIR (Continued) **S104747507**

CERS HAZ WASTE:
Name: PRONTO AUTO REPAIR
Address: 7385 LEMON AVE
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 59023
CERS ID: 10361404
CERS Description: Hazardous Waste Generator

HAZNET:
Name: PRONTO AUTO REPAIR
Address: 7385 LEMON AVE
Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 91945
Contact: FRANCISCO J FLORES
Telephone: 6194613914
Mailing Name: Not reported
Mailing Address: 7385 LEMON AVE

Year: 2019
Gepaid: CAL000267951
TSD EPA ID: CAL000330453
CA Waste Code: 352 - Other organic solids
Disposal Method: H010 - Metals Recovery Including Retoring,Smelting,Chemicals,Ect
Tons: 0.15000

CERS:
Name: PRONTO AUTO REPAIR
Address: 7385 LEMON AVE
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 59023
CERS ID: 10361404
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 59023
Site Name: PRONTO AUTO REPAIR
Violation Date: 04-27-2021
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 04/27/2021. Inspection Sequence ID:6412772
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 59023
Site Name: PRONTO AUTO REPAIR
Violation Date: 04-05-2016
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a

PRONTO AUTO REPAIR (Continued) **S104747507**

hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes: Returned to compliance on 05/03/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 59023
Site Name: PRONTO AUTO REPAIR
Violation Date: 04-05-2016
Citation: HSC 6.95 25508.1(a)-(e) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(e)
Violation Description: Failure to electronically update business plan within 30 days of any one of the following events: A 100 percent or more increase in the quantity of a previously disclosed material. Any handling of a previously undisclosed hazardous materials at or above reportable quantities. A change of business address, business ownership, or business name.
Violation Notes: Returned to compliance on 04/25/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 59023
Site Name: PRONTO AUTO REPAIR
Violation Date: 04-02-2018
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes: Returned to compliance on 04/10/2018. Inspection Sequence ID:5879748;Violation:HMD0226 Did not accumulate waste in a container or tank. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2)
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 59023
Site Name: PRONTO AUTO REPAIR
Violation Date: 04-02-2018
Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22
Violation Description: Failure to properly manage used oil and/or fuel filters in accordance with the requirements.
Violation Notes: Returned to compliance on 04/10/2018. Inspection Sequence ID:5879748
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 59023
Site Name: PRONTO AUTO REPAIR
Violation Date: 04-02-2018
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description: Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

PRONTO AUTO REPAIR (Continued) **S104747507**

Violation Notes: Returned to compliance on 04/10/2018. Inspection Sequence ID:5879748
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-02-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5879748
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-02-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5879748
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-05-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5395731
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2021
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Moreau Marie Inspection ID:6412772
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-05-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5395731
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Moreau Marie Inspection ID:6412772
Eval Division: San Diego County Department of Env Health

PRONTO AUTO REPAIR (Continued) **S104747507**

Eval Program: HW
Eval Source: CERS,

Coordinates:
Site ID: 59023
Facility Name: PRONTO AUTO REPAIR
Env Int Type Code: HWG
Program ID: 10361404
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.743520
Longitude: -117.038260

Affiliation:
Affiliation Type Desc: Legal Owner
Entity Name: fransisco flores
Entity Title: Not reported
Affiliation Address: 7385 LEMON AVE
Affiliation City: LEMON GROVE
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91945
Affiliation Phone: (619) 461-3914,

Affiliation Type Desc: Operator
Entity Name: FRANCISCO FLORES
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 461-3914,

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Affiliation Type Desc: Environmental Contact
Entity Name: FRANCISCO FLORES
Entity Title: Not reported
Affiliation Address: 7385 LEMON AVE
Affiliation City: LEMON GROVE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91945
Affiliation Phone: ,

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address

PRONTO AUTO REPAIR (Continued) **S104747507**

Entity Title: Not reported
Affiliation Address: 7385 LEMON AVE
Affiliation City: LEMON GROVE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91945
Affiliation Phone: ,

Affiliation Type Desc: Parent Corporation
Entity Name: PRONTO AUTO REPAIR
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Document Preparer
Entity Name: Francisco Flores
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: FRANCISCO FLORES
Entity Title: OWNER
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

HWTS:
Name: PRONTO AUTO REPAIR
Address: 7385 LEMON AVE
Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 91945
EPA ID: CAL000267951
Inactive Date: Not reported
Create Date: 03/19/2003
Last Act Date: Not reported
Mailing Name: Not reported
Mailing Address: 7385 LEMON AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: LEMON GROVE, CA 91945
Owner Name: FRANCISCO FLORES
Owner Address: 7385 LEMON AVE
Owner Address 2: Not reported
Owner City,State,Zip: LEMON GROVE, CA 919450000
Contact Name: FRANCISCO J FLORES

PRONTO AUTO REPAIR (Continued) **S104747507**

Contact Address:	7385 LEMON AVE
Contact Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 91945
Facility Status:	Active
Facility Type:	PERMANENT
Category:	STATE
Latitude:	32.743472
Longitude:	-117.038352

NAICS:

EPA ID:	CAL000267951
Create Date:	2003-03-19 14:07:38.077
NAICS Code:	811111
NAICS Description:	General Automotive Repair
Issued EPA ID Date:	2003-03-19 14:07:38.01300
Inactive Date:	Not reported
Facility Name:	PRONTO AUTO REPAIR
Facility Address:	7385 LEMON AVE
Facility Address 2:	Not reported
Facility City:	LEMON GROVE
Facility County:	Not reported
Facility State:	CA
Facility Zip:	91945

E30 **PRONTO AUTO REPAIR** **RCRA NonGen / NLR** **1024806259**
South **7385 LEMON AVE** **CAL000267951**
1/8-1/4 **LEMON GROVE, CA 91945**
0.196 mi.
1037 ft. **Site 5 of 6 in cluster E**

Relative: **Lower**

Actual: **423 ft.**

RCRA Listings:

Date Form Received by Agency:		20030319
Handler Name:	PRONTO AUTO REPAIR	
Handler Address:		7385 LEMON AVE
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAL000267951
Contact Name:		FRANCISCO J FLORES
Contact Address:		7385 LEMON AVE
Contact City,State,Zip:		LEMON GROVE, CA 91945-0000
Contact Telephone:		619-461-3914
Contact Fax:		999-999-9999
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		7385 LEMON AVE
Mailing City,State,Zip:		LEMON GROVE, CA 91945
Owner Name:	FRANCISCO FLORES	
Owner Type:		Other
Operator Name:	FRANCISCO J FLORES	

PRONTO AUTO REPAIR (Continued) **1024806259**

Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20180905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

PRONTO AUTO REPAIR (Continued) **1024806259**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: FRANCISCO J FLORES	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7385 LEMON AVE
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945-0000
Owner/Operator Telephone:	619-461-3914
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: FRANCISCO FLORES	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7385 LEMON AVE
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945-0000
Owner/Operator Telephone:	619-461-3914
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20030319
Handler Name: PRONTO AUTO REPAIR	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811111
NAICS Description:	GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

E31 **INTERNATIONAL AUTO SVC** **RCRA-SQG** **1000217007**
South **7385 LEMON AVE** **FINDS** **CAD981984560**
1/8-1/4 **LEMON GROVE, CA 91945** **ECHO**
0.196 mi.
1037 ft. **Site 6 of 6 in cluster E**

Relative: **Lower**
Actual: **423 ft.**

RCRA Listings:

Date Form Received by Agency:		19960901
Handler Name:	INTERNATIONAL AUTO SVC	
Handler Address:		7385 LEMON AVE
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAD981984560
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		CA
State District:		4
Mailing Address:		7385 LENON AVE
Mailing City,State,Zip:		LEMON GROVE, CA 92045
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	NOT REQUIRED	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

INTERNATIONAL AUTO SVC (Continued) **1000217007**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20020627
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MOHAMMOD J GHODS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NOT REQUIRED	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

INTERNATIONAL AUTO SVC (Continued) **1000217007**

Historic Generators:
Receive Date: 19960901
Handler Name: INTERNATIONAL AUTO SVC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870330
Handler Name: INTERNATIONAL AUTO SVC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110006475368

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000217007

INTERNATIONAL AUTO SVC (Continued) **1000217007**

Registry ID:	110006475368
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006475368
Name:	INTERNATIONAL AUTO SVC
Address:	7385 LEMON AVE
City,State,Zip:	LEMON GROVE, CA 91945

D32 **W.E. WALTERS & SONS** **San Diego Co. HMMD** **S104746205**
SSW **3494 HARRIS ST** **SWEEPS UST** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945**
0.198 mi.
1048 ft. **Site 5 of 8 in cluster D**

Relative:
Lower

Actual:
424 ft.

HMMD SAN DIEGO:

Name:	W.E. WALTERS & SONS
Address:	3494 HARRIS ST
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	105592
Business Type:	6HK70
EPA Id Number:	Not reported
APN:	479-051-33-00
Last HMMD Inspection:	04/07/1992
Facility Telephone:	619-460-1755
Permit Status:	INAC
Permit Expiration:	04/07/1992
Date Last Updated:	11/02/2012
Facility Owner:	WILLIAM E WALTERS
Facility Mailing Address:	PO BOX 857
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91946-
UST Owner:	CONTRERAS BROS CONSTRUCTION CO
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 105592 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	105592
Tank Type:	SINGLE WALL
Additional Id:	Not reported
Capacity Gallons:	2000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1987-01-12 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

W.E. WALTERS & SONS (Continued) **S104746205**

SWEEPS UST:

Name:	W.E. WALTERS & SONS
Address:	3494 HARRIS ST
City:	LEMON GROVE
Status:	Not reported
Comp Number:	5592
Number:	Not reported
Board Of Equalization:	44-022245
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-005592-000001
Tank Status:	Not reported
Capacity:	2000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	1

Name:	W.E. WALTERS & SONS
Address:	3494 HARRIS ST
City:	LEMON GROVE
Status:	Active
Comp Number:	5592
Number:	9
Board Of Equalization:	44-022245
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported
STG:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

F33 **PORTILLO CONCRETE INC** **RCRA NonGen / NLR** **1024828862**
SSW **3527 CITRUS ST** **CAL000361316**
1/8-1/4 **LEMON GROVE, CA 91945**
0.199 mi.
1052 ft. **Site 2 of 2 in cluster F**

Relative: **Lower**

Actual: **437 ft.**

RCRA Listings:

Date Form Received by Agency:		20110301
Handler Name:	PORTILLO CONCRETE INC	
Handler Address:		3527 CITRUS ST
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAL000361316
Contact Name:		TINA PORTILLO
Contact Address:		3527 CITRUS ST
Contact City,State,Zip:		LEMON GROVE, CA 91945
Contact Telephone:		619-466-4639

PORTILLO CONCRETE INC (Continued) **1024828862**

Contact Fax:		619-466-4685
Contact Email:		TPORTILLO@PORTILLOCONCRETEINC.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3527 CITRUS ST
Mailing City,State,Zip:		LEMON GROVE, CA 91945-0000
Owner Name:	PORTILLO CONCRETE INC	
Owner Type:		Other
Operator Name:	TINA PORTILLO	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A

PORTILLO CONCRETE INC (Continued) **1024828862**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20180905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PORTILLO CONCRETE INC	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3527 CITRUS ST
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945-0000
Owner/Operator Telephone:	619-466-4639
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: TINA PORTILLO	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3527 CITRUS ST
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945
Owner/Operator Telephone:	619-466-4639
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20110301
Handler Name: PORTILLO CONCRETE INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

PORTILLO CONCRETE INC (Continued) **1024828862**

List of NAICS Codes and Descriptions:
NAICS Code: 23411
NAICS Description: HIGHWAY AND STREET CONSTRUCTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G34 **FHCSD PARKING LOT - 7580 NORTH AVENUE** **CPS-SLIC S118504845**
SE **7580 NORTH AVENUE** **CERS N/A**
1/8-1/4 **LEMON GROVE, CA 91945**
0.202 mi.
1069 ft. **Site 2 of 6 in cluster G**

Relative:
Lower

Actual:
456 ft.

CPS-SLIC:
Name: FHCSD PARKING LOT - 7580 NORTH AVENUE
Address: 7580 NORTH AVENUE
City,State,Zip: LEMON GROVE, CA 91945
Region: STATE
Facility Status: **Open - Site Assessment**
Status Date: 03/30/2016
Global Id: T10000008740
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: DEH2016-LSAM-000366
Latitude: 32.74481
Longitude: -117.03477
Case Type: Cleanup Program Site
Case Worker: EM
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: Not reported
File Location: Not reported
Potential Media Affected: Not reported
Potential Contaminants of Concern: Not reported
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

CERS:
Name: FHCSD PARKING LOT - 7580 NORTH AVENUE
Address: 7580 NORTH AVENUE
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 367118
CERS ID: T10000008740
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: EWAN MOFFAT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported

FHCSD PARKING LOT - 7580 NORTH AVENUE (Continued) **S118504845**

Affiliation Zip: Not reported
Affiliation Phone: ,

D35 **A&A COLLEX EXPERTS INC DBA COLLISION EXPERTS** **RCRA NonGen / NLR** **1024834616**
South **3463 HARRIS ST** **CAL000375401**
1/8-1/4 **LEMON GROVE, CA 91945**
0.203 mi.
1073 ft. **Site 6 of 8 in cluster D**

Relative: **Lower**
Actual: **422 ft.**

RCRA Listings:

Date Form Received by Agency:	20120619
Handler Name:	A&A COLLEX EXPERTS INC DBA COLLISION EXPERTS
Handler Address:	3463 HARRIS ST
Handler City,State,Zip:	LEMON GROVE, CA 91945
EPA ID:	CAL000375401
Contact Name:	AUDAY SHAMOON
Contact Address:	3463 HARRIS ST
Contact City,State,Zip:	LEMON GROVE, CA 91945
Contact Telephone:	619-466-5266
Contact Fax:	619-466-5211
Contact Email:	COLLEX2@YAHOO.COM
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	3463 HARRIS ST
Mailing City,State,Zip:	LEMON GROVE, CA 91945-0000
Owner Name:	A&A COLLEX EXPERTS INC
Owner Type:	Other
Operator Name:	AUDAY SHAMOON
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported

A&A COLLEX EXPERTS INC DBA COLLISION EXPERTS (Continued) **1024834616**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20180906
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: A&A COLLEX EXPERTS INC	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	1540 CORTE DE LAS PIEDRAS
Owner/Operator City,State,Zip:	EL CAJON, CA 92019-0000
Owner/Operator Telephone:	619-466-5266
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: AUDAY SHAMOON	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3463 HARRIS ST
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945

A&A COLLEX EXPERTS INC DBA COLLISION EXPERTS (Continued) **1024834616**

Owner/Operator Telephone: 619-466-5266
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20120619
Handler Name: A&A COLLEX EXPERTS INC DBA COLLISION EXPERTS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811121
NAICS Description: AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

D36 **COLLISION EXPERTS** **CERS HAZ WASTE** **S113152832**
South **3463 HARRIS ST STE A** **HAZNET** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945** **CERS**
0.203 mi. **HWTS**
1073 ft. **Site 7 of 8 in cluster D**

Relative: **Lower**
Actual: **422 ft.**

CERS HAZ WASTE:
Name: COLLISION EXPERTS
Address: 3463 HARRIS ST STE A
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 107346
CERS ID: 10361383
CERS Description: Hazardous Waste Generator

HAZNET:
Name: COLLISION EXPERTS
Address: 3463 HARRIS ST STE A
Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 919451542
Contact: AUDAY SHAMOON
Telephone: 6194665266
Mailing Name: Not reported
Mailing Address: 3463 HARRIS ST STE A

Year: 2021

COLLISION EXPERTS (Continued) **S113152832**

Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.0432

Year: 2020
Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.288

Year: 2020
Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 133 - Aqueous solution with total organic residues 10 percent or more
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.1251

Year: 2019
Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.15120

Year: 2018
Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.25200

Year: 2018
Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 133 - Aqueous solution with total organic residues 10 percent or more
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.12510

Year: 2017
Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.216

Year: 2016
Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 214 - Unspecified solvent mixture
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.468

Year: 2012

COLLISION EXPERTS (Continued) **S113152832**

Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 133 - Aqueous solution with total organic residues 10 percent or more
Disposal Method: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons: 0.11676

Year: 2012
Gepaid: CAL000333199
TSD EPA ID: CAD008252405
CA Waste Code: 352 - Other organic solids
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.1

Click this hyperlink while viewing on your computer to access
1 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:
Year: 2021
Gen EPA ID: CAL000333199

Shipment Date: 3/10/2020
Creation Date: 4/1/2020
Receipt Date: 3/10/2020
Manifest ID: 021745935JJK
Trans EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES INC
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 214 - Unspecified solvent mixture
RCRA Code: D001,F003,F005
Meth Code: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons: 0.18
Waste Quantity: 50
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 3/10/2020
Creation Date: 4/1/2020
Receipt Date: 3/10/2020
Manifest ID: 021745935JJK
Trans EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES INC
TSDF Alt EPA ID: Not reported

COLLISION EXPERTS (Continued) **S113152832**

TSDF Alt Name: Not reported
Waste Code Description: 133 - Aqueous solution with 10% or more total organic residues
RCRA Code: Not reported
Meth Code: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons: 0.1251
Waste Quantity: 30
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 11/12/2020
Creation Date: 11/20/2020
Receipt Date: 11/12/2020
Manifest ID: 020873976JJK
Trans EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES INC
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 214 - Unspecified solvent mixture
RCRA Code: D001,F003,F005
Meth Code: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons: 0.108
Waste Quantity: 30
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 2020
Gen EPA ID: CAL000333199

Shipment Date: 3/10/2020
Creation Date: 4/1/2020
Receipt Date: 3/10/2020
Manifest ID: 021745935JJK
Trans EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES INC
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES INC
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 214 - Unspecified solvent mixture
RCRA Code: D001,F003,F005
Meth Code: H061 - Fuel Blending Prior To Energy Recovery At Another Site

COLLISION EXPERTS (Continued) **S113152832**

Quantity Tons:	0.18
Waste Quantity:	50
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	3/10/2020
Creation Date:	4/1/2020
Receipt Date:	3/10/2020
Manifest ID:	021745935JJK
Trans EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	133 - Aqueous solution with 10% or more total organic residues
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.1251
Waste Quantity:	30
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	11/12/2020
Creation Date:	11/20/2020
Receipt Date:	11/12/2020
Manifest ID:	020873976JJK
Trans EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	214 - Unspecified solvent mixture
RCRA Code:	D001,F003,F005
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	0.108
Waste Quantity:	30
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

COLLISION EXPERTS (Continued) **S113152832**

Additional Info:

Year:	2017
Gen EPA ID:	CAL000333199
Shipment Date:	20171115
Creation Date:	7/28/2018 18:34:05
Receipt Date:	20171115
Manifest ID:	017007854JJK
Trans EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	214 - Unspecified solvent mixture
RCRA Code:	F005
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	0.054
Waste Quantity:	15
Quantity Unit:	G
Additional Code 1:	F003
Additional Code 2:	D001
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170822
Creation Date:	8/2/2018 18:30:37
Receipt Date:	20170823
Manifest ID:	017004281JJK
Trans EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	214 - Unspecified solvent mixture
RCRA Code:	F005
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	0.054
Waste Quantity:	15
Quantity Unit:	G
Additional Code 1:	F003
Additional Code 2:	D001
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20170602
Creation Date:	7/13/2018 18:30:14
Receipt Date:	20170602
Manifest ID:	016998033JJK
Trans EPA ID:	CAD008252405

COLLISION EXPERTS (Continued) **S113152832**

Trans Name: PACIFIC RESOURCE RECOVERY SERVICES
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 214 - Unspecified solvent mixture
RCRA Code: F005
Meth Code: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons: 0.054
Waste Quantity: 15
Quantity Unit: G
Additional Code 1: F003
Additional Code 2: D001
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 20170308
Creation Date: 5/11/2018 18:31:59
Receipt Date: 20170309
Manifest ID: 016241423JJK
Trans EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 214 - Unspecified solvent mixture
RCRA Code: F005
Meth Code: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons: 0.054
Waste Quantity: 15
Quantity Unit: G
Additional Code 1: F003
Additional Code 2: D001
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 2016
Gen EPA ID: CAL000333199

Shipment Date: 20151222
Creation Date: 10/3/2016 18:30:34
Receipt Date: 20151222
Manifest ID: 014546098JJK
Trans EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY SERVICES

COLLISION EXPERTS (Continued) **S113152832**

TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 214 - Unspecified solvent mixture
RCRA Code: F005
Meth Code: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons: 0.054
Waste Quantity: 15
Quantity Unit: G
Additional Code 1: F003
Additional Code 2: D001
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 2012
Gen EPA ID: CAL000333199

Shipment Date: 20121221
Creation Date: 5/14/2013 22:15:27
Receipt Date: 20121221
Manifest ID: 010723212JJK
Trans EPA ID: CAR000194837
Trans Name: PACIFIC COAST LACQUER
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 133 - Aqueous solution with 10% or more total organic residues
RCRA Code: Not reported
Meth Code: H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons: 0.11676
Waste Quantity: 28
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 20120315
Creation Date: 8/29/2012 22:15:17
Receipt Date: 20120316
Manifest ID: 009821866JJK
Trans EPA ID: CAR000194837
Trans Name: PACIFIC COAST LACQUER
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008252405
Trans Name: PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 352 - Other organic solids
RCRA Code: F005
Meth Code: H141 - Storage, Bulking, And/Or Transfer Off Site--No

COLLISION EXPERTS (Continued) **S113152832**

	Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.1
Waste Quantity:	200
Quantity Unit:	P
Additional Code 1:	F003
Additional Code 2:	D001
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2011
Gen EPA ID:	CAL000333199
Shipment Date:	20111006
Creation Date:	3/22/2012 20:30:33
Receipt Date:	20111006
Manifest ID:	008713314JJK
Trans EPA ID:	CAR000194837
Trans Name:	PACIFIC COAST LACQUER
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	F005
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.1
Waste Quantity:	200
Quantity Unit:	P
Additional Code 1:	F003
Additional Code 2:	D001
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20110707
Creation Date:	12/20/2011 18:30:24
Receipt Date:	20110708
Manifest ID:	008662088JJK
Trans EPA ID:	CAR000194837
Trans Name:	PACIFIC COAST LACQUER
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	F005
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.05
Waste Quantity:	100

COLLISION EXPERTS (Continued) **S113152832**

Quantity Unit:	P
Additional Code 1:	F003
Additional Code 2:	D001
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20110210
Creation Date:	7/14/2011 18:30:34
Receipt Date:	20110211
Manifest ID:	007419128JJK
Trans EPA ID:	CAR000194837
Trans Name:	PACIFIC COAST LACQUER
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	F005
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.1
Waste Quantity:	200
Quantity Unit:	P
Additional Code 1:	F003
Additional Code 2:	D001
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

CERS:

Name:	COLLISION EXPERTS
Address:	3463 HARRIS ST STE A
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	107346
CERS ID:	10361383
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	107346
Site Name:	COLLISION EXPERTS
Violation Date:	08-30-2017
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Returned to compliance on 10/04/2017.
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	107346
Site Name:	COLLISION EXPERTS

COLLISION EXPERTS (Continued) **S113152832**

Violation Date: 08-31-2015
Citation: 19 CCR 6.95 25508(a)(1) - California Code of Regulations, Title 19, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.
Violation Notes: Returned to compliance on 07/08/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 107346
Site Name: COLLISION EXPERTS
Violation Date: 08-31-2015
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes: Returned to compliance on 07/08/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-31-2022
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chua Jean Inspection ID:6987425
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-30-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5730483
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-30-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Moreau Marie Inspection ID:6250602
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-31-2022
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Chua Jean Inspection ID:6987425
Eval Division: San Diego County Department of Env Health

COLLISION EXPERTS (Continued) **S113152832**

Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-30-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5730483
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-31-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Griffin Donelle Inspection ID:4089814
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-30-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Moreau Marie Inspection ID:6250602
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-31-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Griffin Donelle Inspection ID:4089814
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Affiliation:
Affiliation Type Desc: Legal Owner
Entity Name: A&A COLLEX EXPERTS INC
Entity Title: Not reported
Affiliation Address: 3463 HARRIS ST #A
Affiliation City: LEMON GROVE
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91945
Affiliation Phone: (619) 466-5266,

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported

COLLISION EXPERTS (Continued) **S113152832**

Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Affiliation Type Desc: Document Preparer
Entity Name: AUDAY SHAMOON
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: AUDAY SHAMOON
Entity Title: OWNER
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: COLLISION EXPERTS
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 466-5266,

Affiliation Type Desc: Parent Corporation
Entity Name: COLLISION EXPERTS
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Environmental Contact
Entity Name: AUDAY SHAMOON
Entity Title: Not reported
Affiliation Address: 3463 HARRIS ST #A
Affiliation City: LEMON GROVE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91945
Affiliation Phone: ,

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 3463 HARRIS ST #A

COLLISION EXPERTS (Continued) **S113152832**

Affiliation City: LEMON GROVE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91945
Affiliation Phone: ,

HWTS:
Name: COLLISION EXPERTS
Address: 3463 HARRIS ST STE A
Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 91945
EPA ID: CAL000333199
Inactive Date: 06/30/2021
Create Date: 06/02/2008
Last Act Date: Not reported
Mailing Name: Not reported
Mailing Address: 3463 HARRIS ST STE A
Mailing Address 2: Not reported
Mailing City,State,Zip: LEMON GROVE, CA 919451542
Owner Name: ANDY YONO
Owner Address: 3855 AVOCADO BLVD
Owner Address 2: Not reported
Owner City,State,Zip: LA MESA, CA 919417382
Contact Name: AUDAY SHAMOON
Contact Address: 3463 HARRIS ST
Contact Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 91945
Facility Status: Inactive
Facility Type: PERMANENT
Category: STATE
Latitude: 32.74335
Longitude: -117.039325

NAICS:
EPA ID: CAL000333199
Create Date: 2008-06-02 09:23:49.417
NAICS Code: 811121
NAICS Description: Automotive Body, Paint, and Interior Repair and Maintenance
Issued EPA ID Date: 2008-06-02 09:23:49.40000
Inactive Date: Not reported
Facility Name: COLLISION EXPERTS
Facility Address: 3463 HARRIS ST STE A
Facility Address 2: Not reported
Facility City: LEMON GROVE
Facility County: Not reported
Facility State: CA
Facility Zip: 919451542

D37 **COLLISION EXPERTS** **RCRA NonGen / NLR** **1026489745**
South **3463 HARRIS ST STE A** **CAL000333199**
1/8-1/4 **LEMON GROVE, CA 91945**
0.203 mi.
1073 ft. **Site 8 of 8 in cluster D**

Relative: **Lower**
Actual: **422 ft.**

RCRA Listings:

Date Form Received by Agency:		20080602
Handler Name:	COLLISION EXPERTS	
Handler Address:		3463 HARRIS ST STE A
Handler City,State,Zip:		LEMON GROVE, CA 91945-1542
EPA ID:		CAL000333199
Contact Name:		AUDAY SHAMOON
Contact Address:		3463 HARRIS ST
Contact City,State,Zip:		LEMON GROVE, CA 91945
Contact Telephone:		619-466-5266
Contact Fax:		619-466-5211
Contact Email:		COLLEX2@YAHOO.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3463 HARRIS ST STE A
Mailing City,State,Zip:		LEMON GROVE, CA 91945-1542
Owner Name:	ANDY YONO	
Owner Type:		Other
Operator Name:	AUDAY SHAMOON	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

COLLISION EXPERTS (Continued) **1026489745**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20200710
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ANDY YONO	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3855 AVOCADO BLVD
Owner/Operator City,State,Zip:	LA MESA, CA 91941-7382
Owner/Operator Telephone:	619-660-1100
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: AUDAY SHAMOON	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3463 HARRIS ST
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945
Owner/Operator Telephone:	619-466-5266
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

COLLISION EXPERTS (Continued) **1026489745**

Historic Generators:
Receive Date: 20080602
Handler Name: COLLISION EXPERTS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811121
NAICS Description: AUTOMOTIVE BODY, PAINT, AND INTERIOR REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

H38 **ARCO STATION** **LUST** **S101301730**
WSW **3775 MASSACHUSETTS AVE** **N/A**
1/8-1/4 **LA MESA, CA 92041**
0.214 mi.
1128 ft. **Site 1 of 11 in cluster H**

Relative:
Lower

Actual:
455 ft.

LUST REG 9:
Region: 9
Status: Remediation Plan
Case Number: 9UT1455
Local Case: H13041-002
Substance: Gasoline
Qty Leaked: 0
Abate Method: Not reported
Local Agency: San Diego
How Found: Tank Test
How Stopped: Close Tank
Source: Tank
Cause: Corrosion
Lead Agency: Local Agency
Case Type: Other ground water affected
Date Found: 05/15/1988
Date Stopped: 05/15/1988
Confirm Date: 03/15/1988
Submit Workplan: 5/15/88
Prelim Assess: 12/09/1988
Desc Pollution: Not reported
Remed Plan: 01/20/1989
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 03/23/1988

ARCO STATION (Continued) **S101301730**

Enforce Date: Not reported
Closed Date: Not reported
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 908.22
GW Depth: 8'
Beneficial Use: No Beneficial groundwater use
NPDES Number: Not reported
Priority: 2B
File Dispn: File discarded, case closed
Interim Remedial Actions: Yes
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

H39 **ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO** **RCRA NonGen / NLR** **1024851265**
WSW **3775 MASSACHUSETTS AVE** **CAL000409613**
1/8-1/4 **LA MESA, CA 91941**
0.214 mi.
1128 ft. **Site 2 of 11 in cluster H**

Relative: **Lower**
Actual: **455 ft.**

RCRA Listings:

Date Form Received by Agency:		20150824
Handler Name:	ALIA PETROLEUM INC. DBA	MASSACHUSETTS ARCO
Handler Address:		3775 MASSACHUSETTS AVE
Handler City,State,Zip:		LA MESA, CA 91941
EPA ID:		CAL000409613
Contact Name:		AKRAM DAOUD
Contact Address:		12093 CALLE DE MEDIO
Contact City,State,Zip:		EL CAJON, CA 92019
Contact Telephone:		619-697-8174
Contact Fax:		619-697-7318
Contact Email:		AKDAOUD@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3775 MASSACHUSETTS AVE
Mailing City,State,Zip:		LA MESA, CA 91941
Owner Name:	ALIA PETROLEUM INC.	
Owner Type:		Other
Operator Name:	AKRAM DAOUD	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No

ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO (Continued) **1024851265**

Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20180906
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: AKRAM DAOUD	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	12093 CALLE DE MEDIO
Owner/Operator City,State,Zip:	EL CAJON, CA 92019
Owner/Operator Telephone:	619-697-8174
Owner/Operator Telephone Ext:	Not reported

ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO (Continued) **1024851265**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ALIA PETROLEUM INC.
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3775 MASSACHUSETTS AVE
Owner/Operator City,State,Zip: LA MESA, CA 91941
Owner/Operator Telephone: 619-697-8174
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20150824
Handler Name: ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44719
NAICS Description: OTHER GASOLINE STATIONS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

H40 **ARCO #01710** **SAN DIEGO CO. SAM** **1008242534**
WSW **3775 MASSACHUSETTS AV** **FINDS** **N/A**
1/8-1/4 **LA MESA, CA 91941** **Cortese**
0.214 mi.
1128 ft. **Site 3 of 11 in cluster H**

Relative:
Lower

Actual:
455 ft.

SAN DIEGO CO. SAM:
Name: ARCO #1710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 919417637
Case Number: H13041-001
Agency: DEH Site Assessment & Mitigation
Funding: **Non Billable**
Facility Type: Failed Integrity Test
Facility Status: Closed Case
Date: 2/25/1988

ARCO #01710 (Continued) **1008242534**

Date Began: 1/30/1987

Name: ARCO #1710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 919417637
Case Number: H13041-002
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Closed Case
Date: 6/10/2003
Date Began: 3/24/1988

Name: ARCO #1710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 919417637
Case Number: H13041-003
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Closed Case
Date: 6/10/2003
Date Began: 8/11/1997

FINDS:
Registry ID: 110021344516

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
HAZARDOUS AIR POLLUTANT MAJOR
STATE MASTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CORTESE:
Name: ARCO #1710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 919417637
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607300280
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported

ARCO #01710 (Continued) **1008242534**

Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open
Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 919417637
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607302300
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

H41 **ARCO #01710** **LUST** **S103656204**
WSW **3775 MASSACHUSETTS AV** **CPS-SLIC** **N/A**
1/8-1/4 **LA MESA, CA 91941** **San Diego Co. HMMD**
0.214 mi. **CERS HAZ WASTE**
1128 ft. **Site 4 of 11 in cluster H** **CERS TANKS**
EMI
Relative: **HIST CORTESE**
Lower **HAZNET**
Actual: **SAN DIEGO CO LOP**
455 ft. **CERS**
HWTS

LUST:

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 919417637
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607300280
Global Id:	T0607300280
Latitude:	32.74582
Longitude:	-117.042486
Status:	Completed - Case Closed
Status Date:	06/10/2003
Case Worker:	Not reported
RB Case Number:	9UT1455
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	H13041-002

ARCO #01710 (Continued) **S103656204**

Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607300280
Action Type: ENFORCEMENT
Date: 06/10/2003
Action: Closure/No Further Action Letter

Global Id: T0607300280
Action Type: Other
Date: 03/24/1988
Action: Leak Began

Global Id: T0607300280
Action Type: Other
Date: 03/24/1988
Action: Leak Discovery

Global Id: T0607300280
Action Type: Other
Date: 03/23/1988
Action: Leak Reported

Global Id: T0607300280
Action Type: Other
Date: 03/23/1988
Action: Leak Stopped

LUST:
Global Id: T0607300280
Status: Open - Case Begin Date
Status Date: 03/23/1988

Global Id: T0607300280
Status: Completed - Case Closed
Status Date: 06/10/2003

Name: ARCO #1710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 919417637
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302300
Global Id: T0607302300
Latitude: 32.7459535
Longitude: -117.0426431
Status: Completed - Case Closed
Status Date: 06/10/2003
Case Worker: Not reported
RB Case Number: 9UT3531
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H13041-003
Potential Media Affect: Other Groundwater (uses other than drinking water)

ARCO #01710 (Continued) **S103656204**

Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607302300
Action Type: Other
Date: 08/11/1997
Action: Leak Discovery

Global Id: T0607302300
Action Type: ENFORCEMENT
Date: 06/10/2003
Action: Closure/No Further Action Letter

Global Id: T0607302300
Action Type: Other
Date: 08/11/1997
Action: Leak Began

Global Id: T0607302300
Action Type: Other
Date: 08/11/1997
Action: Leak Reported

Global Id: T0607302300
Action Type: ENFORCEMENT
Date: 09/17/1997
Action: Notice of Responsibility

Global Id: T0607302300
Action Type: Other
Date: 08/11/1997
Action: Leak Stopped

LUST:
Global Id: T0607302300
Status: Open - Case Begin Date
Status Date: 08/11/1997

Global Id: T0607302300
Status: Completed - Case Closed
Status Date: 06/10/2003

CPS-SLIC:
Name: ARCO #1710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 919417637
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 02/25/1988
Global Id: T0608128337
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H13041-001
Latitude: 32.745806
Longitude: -117.042488
Case Type: Cleanup Program Site

ARCO #01710 (Continued) **S103656204**

Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Under Investigation
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

HMMD SAN DIEGO:

Name:	LA MESA NINE DIAMONDS, LLC
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	207982
Business Type:	6HK28
EPA Id Number:	CAL000324548
APN:	474-581-01-00
Last HMMD Inspection:	08/16/2012
Facility Telephone:	619-697-8174
Permit Status:	OPEN
Permit Expiration:	11/30/2012
Date Last Updated:	11/02/2012
Facility Owner:	LA MESA NINE DIAMONDS, LLC
Facility Mailing Address:	7213 ROMERO DR
Facility Mailing City:	LA JOLLA
Facility Mailing State:	CA
Facility Mailing Zip:	92037
UST Owner:	LA MESA NINE DIAMONDS, LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	207982
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 113041 T007
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	207982
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 113041 T008
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	207982
Update Date:	11/02/2012

ARCO #01710 (Continued) **S103656204**

Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 113041 T008
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: SUPER UNLEADED
Other Information: UNDERGROUND TANK 113041 T006 REGULAR LEADED
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: WATER & FUEL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED FUEL FILTERS & ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/02/2011
Violation Code: 6HV3109
Violation: NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation: Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/02/2011
Violation Code: 6HV3191
Violation: NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation: Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/16/2012
Violation Code: 6HV3105

ARCO #01710 (Continued) **S103656204**

Violation:	NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation:	Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3114
Violation:	2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation:	Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)

ARCO #01710 (Continued) **S103656204**

Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 05/08/2007
Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 113041 T006
Last Update: 2012-11-02 14:17:38
Permit Number: 207982
Tank Type: DOUBLE WALL
Additional Id: 6 REGULAR LEADED RT1924, RT5096
Capacity Gallons: 12000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1988-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 113041 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 207982
Tank Type: DOUBLE WALL
Additional Id: RT1924, RT5096
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1988-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 113041 T008
Last Update: 2012-11-02 14:17:38
Permit Number: 207982
Tank Type: DOUBLE WALL
Additional Id: RT1924, RT5096
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1988-01-01 00:00:00

ARCO #01710 (Continued) **S103656204**

Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name: LA MESA NINE DIAMONDS, LLC
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Permit Number: 207982
Business Type: 6HK28
EPA Id Number: CAL000324548
APN: 474-581-01-00
Last HMMD Inspection: 08/16/2012
Facility Telephone: 619-697-8174
Permit Status: OPEN
Permit Expiration: 11/30/2012
Date Last Updated: 11/02/2012
Facility Owner: LA MESA NINE DIAMONDS, LLC
Facility Mailing Address: 7213 ROMERO DR
Facility Mailing City: LA JOLLA
Facility Mailing State: CA
Facility Mailing Zip: 92037
UST Owner: LA MESA NINE DIAMONDS, LLC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 113041 T007
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 113041 T008
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 113041 T008
Material Waste: Material
Hazardous Categories 1: FIRE

ARCO #01710 (Continued) **S103656204**

Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: SUPER UNLEADED
Other Information: UNDERGROUND TANK 113041 T006 REGULAR LEADED
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: WATER & FUEL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED FUEL FILTERS & ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/02/2011
Violation Code: 6HV3109
Violation: NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation: Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/02/2011
Violation Code: 6HV3191
Violation: NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation: Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/16/2012
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity: ACTIVE

ARCO #01710 (Continued) **S103656204**

Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3114
Violation:	2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation:	Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/08/2007

ARCO #01710 (Continued) **S103656204**

Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 113041 T006
Last Update: 2012-11-02 14:17:38
Permit Number: 207982
Tank Type: DOUBLE WALL
Additional Id: 6 REGULAR LEADED RT1924, RT5096
Capacity Gallons: 12000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1988-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 113041 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 207982
Tank Type: DOUBLE WALL
Additional Id: RT1924, RT5096
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1988-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 113041 T008
Last Update: 2012-11-02 14:17:38
Permit Number: 207982
Tank Type: DOUBLE WALL
Additional Id: RT1924, RT5096
Capacity Gallons: 12000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1988-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

ARCO #01710 (Continued) **S103656204**

Name:	ARCO FACILITY NO. 1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	113041
Business Type:	6HK28
EPA Id Number:	CAR000105551
APN:	474-581-01-00
Last HMMD Inspection:	05/09/2006
Facility Telephone:	619-697-8174
Permit Status:	CHNG
Permit Expiration:	01/31/2007
Date Last Updated:	11/02/2012
Facility Owner:	BP WEST COAST PRODUCTS LLC
Facility Mailing Address:	PO BOX 6038
Facility Mailing City:	ARTESIA
Facility Mailing State:	CA
Facility Mailing Zip:	90702-6038
UST Owner:	BP WEST COAST PRODUCTS LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 113041 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000001
Capacity Gallons:	6000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1961-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 113041 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000002
Capacity Gallons:	4000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1988-02-08 00:00:00
Year Installed:	1961-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY

ARCO #01710 (Continued) **S103656204**

MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 113041 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000003
Capacity Gallons:	4000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1961-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 113041 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000004
Capacity Gallons:	6000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1988-02-08 00:00:00
Year Installed:	1973-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	PRESSURE
Monitor Code:	07
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 113041 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000005
Capacity Gallons:	280
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1961-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 113041 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	DOUBLE WALL

ARCO #01710 (Continued) **S103656204**

Additional Id:	6 REGULAR LEADED RT1924
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 113041 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	DOUBLE WALL
Additional Id:	RT1924
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 113041 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	DOUBLE WALL
Additional Id:	RT1924
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAL000409613
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-697-8174

ARCO #01710 (Continued) **S103656204**

Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	09/30/2022
Facility Owner:	Not reported
Facility Mailing Address:	3775 MASSACHUSETTS AVE., LA MESA, CA 91941
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	Y
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	HMD0000 UST PRESSURIZED PIPING (DW) REQUIREMENTS

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection
Inspection Number:	5772749
Return To Compliance Date:	2017-09-29T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2017-08-03T10:43:00.000
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5160999
Return To Compliance Date:	2015-08-13T00:00:00.000

ARCO #01710 (Continued) **S103656204**

Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	22460
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2015-08-06T10:25:00.000
Violation Code:	2030026 Failure of line leak detector to detect a leak and/or failure of audible and visual alarm. 23 CCR 2636(f)(2)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5939500
Return To Compliance Date:	2018-08-02T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	22461
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2018-08-02T12:25:00.000
Violation Code:	2030018 (RD) Failure of the double-walled pressurized piping to be continuously monitored with a system that activates an audible and visual alarm or stops flow at dispenser when a leak is detected. 23 CCR 2636(f)(1)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6207290
Return To Compliance Date:	2019-08-16T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	22461
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2019-08-16T14:40:24.000
Violation Code:	2030025 (TCR 9d) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly. with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5939500
Return To Compliance Date:	2018-08-02T00:00:00.000

ARCO #01710 (Continued) **S103656204**

Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	22461
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2018-08-02T12:25:00.000
Violation Code:	2030025 (RD) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly. with the capability of detecting a release of 3.0 gallons per hour leak at 10 p.s.i.g. and restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6207290
Return To Compliance Date:	2019-08-16T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	22460
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2019-08-16T14:40:24.000
Violation Code:	2030036 (TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. 6. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. 7. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. 8. Inspected within 30 days after a repair to the overfill prevention equipment. 9. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 10. Inspected by a certified UST service technician. 11. Maintain records of overfill prevention equipment inspection for 36 months. 23 CCR 2635(c)(1), 2635(d), 2637.2(a-c), 2665, 2712(b)(1)(G)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982

ARCO #01710 (Continued) **S103656204**

Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	2022-08-12T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	22461
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	2030025 (TCR 9d) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: 1) Monitored with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch within an hour. 2) Restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	2022-08-10T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	22460
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	2030036 (TCR 9b)Failure to comply with one or more of the following overfill prevention equipment requirements: 1) Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or 2) Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or 3) Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or 4) Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5) Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. 6) Perform an inspection at least once every 36 months, at installation and every 36 months thereafter. 7) Inspected within 30 days after a repair to the overfill prevention equipment. 8) Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. 9) Inspected by a certified UST service technician. 10) Maintain records of overfill prevention equipment inspection for 36 months. 23 CCR 2635(c)(1), 2635(d), 2637.2(a-c), 2665, 2712(b)(1)(G)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed

ARCO #01710 (Continued) **S103656204**

Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5160999
Return To Compliance Date:	2015-08-30T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2015-08-06T10:25:00.000
Violation Code:	3010002 Failed to obtain and/or maintain an active EPA ID. 22 CCR 66262.12

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	3030007 Failed to properly label/date hazardous waste container &/or tank. 22 CCR 66262.34(f)

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	3030058 Failed to mark date on empty container larger than 5 gallons &/or properly manage it within one year. 22 CCR 66261.7

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported

ARCO #01710 (Continued) **S103656204**

Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	3030010 Failed to properly dispose of hazardous waste within 180 days (or 270 days if waste is transported over 200 miles). 22 CCR 66262.34(d); HSC 6.5 25123.3(h)(1)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	1010003 Business activities &/or Business Owner/Operator page not complete or accurate in CERS. 19 CCR 2652(a)(1); SDCC 68.904(b); HSC 25508(a)(1), 25508(a)(3)
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6207290
Return To Compliance Date:	2019-08-16T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	22461
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2019-08-16T14:40:24.000
Violation Code:	2060020 (TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed

ARCO #01710 (Continued) **S103656204**

Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	1010004 Chemical inventory incomplete or not submitted in CERS. HSC 25505(a)(1); 25507(a); 25508.1(a-b); 19 CCR 2654 (a) or (d)

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS ONLY

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6702672
Return To Compliance Date:	2021-09-20T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	22460
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2021-08-16T00:00:00.000
Violation Code:	2030013 (TCR 12) Failure to comply with one or more of the following Designated Operator (DO) inspection requirements: Conduct the DO visual inspection at least once every 30 days. Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented.Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). The

ARCO #01710 (Continued) **S103656204**

owner/operator sign and date the Designated Underground Storage Tank Operator Visual Inspection Report within 72 hours of being provided a signed copy. 23 CCR 2716 (a-e)

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	1010005 Site map not submitted in CERS or not sufficient. HSC 25505(a)(2); 25508.1(f); 19 CCR 2652(a)(3)

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6702672
Return To Compliance Date:	2021-08-16T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	22461
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2021-08-16T00:00:00.000
Violation Code:	2060020 (TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	Not reported

ARCO #01710 (Continued) **S103656204**

Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	HMD0001 STORAGE AND HANDLING
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	HMD0000 UST TANK (DW/SW) - REQUIREMENT
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6987457
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-09-30T00:00:00.000
Inspection Date:	2022-08-10T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS MATERIALS REQUIREMENTS

UST DTL:

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	ALIA PETROLEUM LLC
Tankid:	22460
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-09-30T02:34:22.000
Tank Capacityin Gallons:	12000
Tank Contents:	Premium Unleaded
Type Of Tank:	Double Wall
Record ID:	DEH2007-HUPFP-207982

ARCO #01710 (Continued) **S103656204**

Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	ALIA PETROLEUM LLC
Tankid:	22462
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-09-30T02:34:22.000
Tank Capacityin Gallons:	12000
Tank Contents:	Regular Unleaded
Type Of Tank:	Double Wall

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-207982
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	ALIA PETROLEUM LLC
Tankid:	22461
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-09-30T02:34:22.000
Tank Capacityin Gallons:	12000
Tank Contents:	Regular Unleaded
Type Of Tank:	Double Wall

Waste and Materials:

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0149936
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-01-16T16:00:15.000
Chemical Name:	REGULAR UNLEADED
Common Name:	UNDERGROUND TANK 113041 T008
Case Number:	8006-61-9

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0149937
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2018-01-16T16:00:15.000
Chemical Name:	REGULAR UNLEADED
Common Name:	UNDERGROUND TANK 113041 T007
Case Number:	8006-61-9

Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y

ARCO #01710 (Continued) **S103656204**

Child Record Id: DEH2017-HCHEM-0149938
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-01-16T16:00:15.000
Chemical Name: SUPER UNLEADED
Common Name: UNDERGROUND TANK 113041 T006 REGULAR LEADED
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0128320
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-01-16T16:00:15.000
Chemical Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name: WATER & FUEL
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0128321
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-01-16T16:00:15.000
Chemical Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Common Name: USED FUEL FILTERS & ABSORBENT
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0181275
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-09-05T02:35:42.000
Chemical Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Common Name: USED FUEL FILTERS & ABSORBENT
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0208860
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-09-05T02:35:42.000
Chemical Name: REGULAR UNLEADED
Common Name: UNDERGROUND TANK 113041 T008
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0208861
Trade Secret: N

ARCO #01710 (Continued) **S103656204**

Hazardous Material Type:	Pure
Last Updated:	2019-09-05T02:35:42.000
Chemical Name:	REGULAR UNLEADED
Common Name:	UNDERGROUND TANK 113041 T007
Case Number:	8006-61-9
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0208862
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2019-09-05T02:35:42.000
Chemical Name:	SUPER UNLEADED
Common Name:	UNDERGROUND TANK 113041 T006 REGULAR LEADED
Case Number:	8006-61-9
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HWAST-0181274
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-09-05T02:35:42.000
Chemical Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name:	WATER & FUEL
Case Number:	Not reported
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0306476
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2022-09-30T02:34:22.000
Chemical Name:	SUPER UNLEADED
Common Name:	UNDERGROUND TANK 113041 T006 UNLEADED
Case Number:	8006-61-9
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0234695
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2020-08-06T01:42:46.000
Chemical Name:	REGULAR UNLEADED
Common Name:	UNDERGROUND TANK 113041 T007
Case Number:	8006-61-9
Record ID:	DEH2007-HUPFP-207982
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0234696
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2020-08-06T01:42:46.000

ARCO #01710 (Continued) **S103656204**

Chemical Name: SUPER UNLEADED
Common Name: UNDERGROUND TANK 113041 T006 REGULAR LEADED
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0204896
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-08-06T01:42:46.000
Chemical Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Common Name: USED FUEL FILTERS & ABSORBENT
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0234694
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-08-06T01:42:46.000
Chemical Name: REGULAR UNLEADED
Common Name: UNDERGROUND TANK 113041 T008
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0276209
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-04-02T02:45:14.000
Chemical Name: REGULAR UNLEADED
Common Name: UNDERGROUND TANK 113041 T008
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0276210
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-04-02T02:45:14.000
Chemical Name: REGULAR UNLEADED
Common Name: UNDERGROUND TANK 113041 T007
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0276211
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-04-02T02:45:14.000
Chemical Name: SUPER UNLEADED
Common Name: UNDERGROUND TANK 113041 T006 REGULAR LEADED

ARCO #01710 (Continued) **S103656204**

Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0244487
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-04-02T02:45:14.000
Chemical Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name: WATER & FUEL
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0244488
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-04-02T02:45:14.000
Chemical Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Common Name: USED FUEL FILTERS & ABSORBENT
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0274206
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-09-30T02:34:22.000
Chemical Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name: WATER & FUEL
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0274207
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-09-30T02:34:22.000
Chemical Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Common Name: USED FUEL FILTERS & ABSORBENT
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189819
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-26T23:34:08.000
Chemical Name: REGULAR UNLEADED
Common Name: UNDERGROUND TANK 113041 T008
Case Number: 8006-61-9

ARCO #01710 (Continued) **S103656204**

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189820
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-26T23:34:08.000
Chemical Name: REGULAR UNLEADED
Common Name: UNDERGROUND TANK 113041 T007
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0189821
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-26T23:34:08.000
Chemical Name: SUPER UNLEADED
Common Name: UNDERGROUND TANK 113041 T006 REGULAR LEADED
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0164286
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-26T23:34:08.000
Chemical Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name: WATER & FUEL
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0164287
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-26T23:34:08.000
Chemical Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Common Name: USED FUEL FILTERS & ABSORBENT
Case Number: Not reported

Record ID: DEH2007-HUPFP-207982
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0204895
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-08-06T01:42:46.000
Chemical Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Common Name: WATER & FUEL
Case Number: Not reported

Name: LA MESA NINE DIAMONDS, LLC

ARCO #01710 (Continued) **S103656204**

Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	207982
Business Type:	6HK28
EPA Id Number:	CAL000324548
APN:	474-581-01-00
Last HMMD Inspection:	08/16/2012
Facility Telephone:	619-697-8174
Permit Status:	OPEN
Permit Expiration:	11/30/2012
Date Last Updated:	11/02/2012
Facility Owner:	LA MESA NINE DIAMONDS, LLC
Facility Mailing Address:	7213 ROMERO DR
Facility Mailing City:	LA JOLLA
Facility Mailing State:	CA
Facility Mailing Zip:	92037
UST Owner:	LA MESA NINE DIAMONDS, LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	207982
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 113041 T007
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	207982
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 113041 T008
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	207982
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 113041 T008
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	207982
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	SUPER UNLEADED
Other Information:	UNDERGROUND TANK 113041 T006 REGULAR LEADED
Material Waste:	Material

ARCO #01710 (Continued) **S103656204**

Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: WATER & FUEL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED FUEL FILTERS & ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/02/2011
Violation Code: 6HV3109
Violation: NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation: Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/02/2011
Violation Code: 6HV3191
Violation: NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation: Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/16/2012
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 05/11/2009
Violation Code: 6HV3114
Violation: 2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation: Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity: ACTIVE

ARCO #01710 (Continued) **S103656204**

Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/08/2007
Violation Code:	6HV3255
Violation:	SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation:	Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity:	ACTIVE

UST:

UST Name:	UNDERGROUND TANK 113041 T006
Last Update:	2012-11-02 14:17:38

ARCO #01710 (Continued) **S103656204**

Permit Number:	207982
Tank Type:	DOUBLE WALL
Additional Id:	6 REGULAR LEADED RT1924, RT5096
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 113041 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	207982
Tank Type:	DOUBLE WALL
Additional Id:	RT1924, RT5096
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 113041 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	207982
Tank Type:	DOUBLE WALL
Additional Id:	RT1924, RT5096
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	ARCO FACILITY NO. 1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	113041
Business Type:	6HK28
EPA Id Number:	CAR000105551
APN:	474-581-01-00

ARCO #01710 (Continued) **S103656204**

Last HMMD Inspection:	05/09/2006
Facility Telephone:	619-697-8174
Permit Status:	CHNG
Permit Expiration:	01/31/2007
Date Last Updated:	11/02/2012
Facility Owner:	BP WEST COAST PRODUCTS LLC
Facility Mailing Address:	PO BOX 6038
Facility Mailing City:	ARTESIA
Facility Mailing State:	CA
Facility Mailing Zip:	90702-6038
UST Owner:	BP WEST COAST PRODUCTS LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 113041 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000001
Capacity Gallons:	6000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1961-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 113041 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000002
Capacity Gallons:	4000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1988-02-08 00:00:00
Year Installed:	1961-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 113041 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000003

ARCO #01710 (Continued) **S103656204**

Capacity Gallons:	4000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	Not reported
Year Installed:	1961-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR
UST Name:	UNDERGROUND TANK 113041 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000004
Capacity Gallons:	6000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1988-02-08 00:00:00
Year Installed:	1973-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	PRESSURE
Monitor Code:	07
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY
UST Name:	UNDERGROUND TANK 113041 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	SINGLE WALL
Additional Id:	0000000005
Capacity Gallons:	280
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1961-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.
UST Name:	UNDERGROUND TANK 113041 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	DOUBLE WALL
Additional Id:	6 REGULAR LEADED RT1924
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00

ARCO #01710 (Continued) **S103656204**

Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 113041 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	DOUBLE WALL
Additional Id:	RT1924
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 113041 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	113041
Tank Type:	DOUBLE WALL
Additional Id:	RT1924
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	LA MESA NINE DIAMONDS, LLC
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	207982
Business Type:	6HK28
EPA Id Number:	CAL000324548
APN:	474-581-01-00
Last HMMD Inspection:	08/16/2012
Facility Telephone:	619-697-8174
Permit Status:	OPEN
Permit Expiration:	11/30/2012
Date Last Updated:	11/02/2012
Facility Owner:	LA MESA NINE DIAMONDS, LLC
Facility Mailing Address:	7213 ROMERO DR
Facility Mailing City:	LA JOLLA
Facility Mailing State:	CA

ARCO #01710 (Continued) **S103656204**

Facility Mailing Zip: 92037
UST Owner: LA MESA NINE DIAMONDS, LLC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 113041 T007
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 113041 T008
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 113041 T008
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: SUPER UNLEADED
Other Information: UNDERGROUND TANK 113041 T006 REGULAR LEADED
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information: WATER & FUEL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 207982
Update Date: 11/02/2012
Case Number: Not reported

ARCO #01710 (Continued) **S103656204**

Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED FUEL FILTERS & ABSORBENT
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/02/2011
Violation Code: 6HV3109
Violation: NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation: Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/02/2011
Violation Code: 6HV3191
Violation: NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation: Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 08/16/2012
Violation Code: 6HV3105
Violation: NO CURRENT FINANCIAL RESPONSIBILITY
Violation Citation: Current evidence of financial responsibility not available. 25292.2(a), 25299.33; 2809
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 05/11/2009
Violation Code: 6HV3114
Violation: 2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation: Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 05/11/2009
Violation Code: 6HV3104
Violation: FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation: CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity: ACTIVE

Permit Number: 207982
Update Date: 11/02/2012
Inspection Date: 05/11/2009
Violation Code: 6HV3107
Violation: MONITORING PROCEDURES NOT AVAIL/TO HMD

ARCO #01710 (Continued) **S103656204**

Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/11/2009
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity:	ACTIVE
Permit Number:	207982
Update Date:	11/02/2012
Inspection Date:	05/08/2007
Violation Code:	6HV3255
Violation:	SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation:	Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity:	ACTIVE

UST:

UST Name:	UNDERGROUND TANK 113041 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	207982
Tank Type:	DOUBLE WALL
Additional Id:	6 REGULAR LEADED RT1924, RT5096
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

ARCO #01710 (Continued) **S103656204**

UST Name:	UNDERGROUND TANK 113041 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	207982
Tank Type:	DOUBLE WALL
Additional Id:	RT1924, RT5096
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 113041 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	207982
Tank Type:	DOUBLE WALL
Additional Id:	RT1924, RT5096
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1988-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

CERS HAZ WASTE:

Name:	ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Site ID:	42706
CERS ID:	10360585
CERS Description:	Hazardous Waste Generator

CERS TANKS:

Name:	ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Site ID:	42706
CERS ID:	10360585
CERS Description:	Underground Storage Tank

EMI:

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 920410000
Year:	2000

ARCO #01710 (Continued) **S103656204**

County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 920410000
Year:	2001
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 920410000
Year:	2002
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #1710

ARCO #01710 (Continued) **S103656204**

Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 920410000
Year:	2003
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	3
Reactive Organic Gases Tons/Yr:	3
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 920410000
Year:	2004
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.5451426
Reactive Organic Gases Tons/Yr:	2.5451426
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 920410000
Year:	2005
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.5451426
Reactive Organic Gases Tons/Yr:	2.5451426
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

ARCO #01710 (Continued) **S103656204**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 920410000
Year:	2006
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 920410000
Year:	2007
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2008
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	0

ARCO #01710 (Continued) **S103656204**

NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: ARCO #01710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Year: 2009
County Code: 37
Air Basin: SD
Facility ID: 3813
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 4.5800000000000001
Reactive Organic Gases Tons/Yr: 4.5800000000000001
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: ARCO #01710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Year: 2010
County Code: 37
Air Basin: SD
Facility ID: 3813
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 4.5800000000000001
Reactive Organic Gases Tons/Yr: 4.5800000000000001
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: ARCO #01710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Year: 2011
County Code: 37
Air Basin: SD
Facility ID: 3813
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

ARCO #01710 (Continued) **S103656204**

Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2012
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2013
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2014
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541

ARCO #01710 (Continued) **S103656204**

Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2015
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2016
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2017
County Code:	37
Air Basin:	SD

ARCO #01710 (Continued) **S103656204**

Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2018
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2019
County Code:	37
Air Basin:	SD
Facility ID:	3813
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	4.58
Reactive Organic Gases Tons/Yr:	4.58
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

HIST CORTESE:

edr_fname:	ARCO STATION #1710
edr_fadd1:	3775 MASSACHUSETTS

ARCO #01710 (Continued) **S103656204**

City,State,Zip: LA MESA, CA 92041
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT3531

edr_fname: ARCO STATION
edr_fadd1: 3775 MASSACHUSETTS
City,State,Zip: LA MESA, CA 92041
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT1455

HAZNET:
Name: ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Address: 3775 MASSACHUSETTS AVE
Address 2: Not reported
City,State,Zip: LA MESA, CA 91941
Contact: AKRAM DAOUD
Telephone: 6196978174
Mailing Name: Not reported
Mailing Address: 3775 MASSACHUSETTS AVE

Year: 2018
Gepaid: CAL000409613
TSD EPA ID: CAT080013352
CA Waste Code: 223 - Unspecified oil-containing waste
Disposal Method: H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.62550

Year: 2017
Gepaid: CAL000409613
TSD EPA ID: AZR000515924
CA Waste Code: 352 - Other organic solids
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 1.5

Year: 2016
Gepaid: CAL000409613
TSD EPA ID: CAT080013352
CA Waste Code: 223 - Unspecified oil-containing waste
Disposal Method: H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons: 0.6672

Detail Two:
Year: 2018
EM Manifest ID: 016757974JJK20170310_D_1
Shipment Date: 3/10/2017
Receipt Date: 3/20/2017
Manifest Number: 016757974JJK
Generator EPA ID: CAL000409613

ARCO #01710 (Continued) **S103656204**

Name:	MASSACHUSETTS ARCO
Address:	Not reported
Address 2:	Not reported
City:	Not reported
Zip:	Not reported
Telephone:	Not reported
Contact:	Not reported
Contact Telephone:	Not reported
Transporter 1 EPA ID:	CAD028277036
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	CAR000175422
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	AZR000515924
TSDF Name:	YUMA YES LLC
TSDF Address 1:	Not reported
TSDF Address 2:	Not reported
TSDF City:	Not reported
TSDF Zip:	Not reported
TSDF Telephone:	Not reported

State:

Year:	2018
EM Manifest ID:	016757974JJK20170310_D_1
Generator EPA ID:	CAL000409613
Shipment Date:	2017-03-10
Manifest Number:	016757974JJK
Line Number:	1
Method Code:	H141
Quantity Tons:	1.50000
Quantity Waste:	3000.000000
Quantity Unit:	P
Number of Containers:	6
Type of Container:	NULL
Quantity Type:	NULL
State Code:	352

Additional Info:

Year:	2017
Gen EPA ID:	CAL000409613
Shipment Date:	20170310
Creation Date:	5/12/2018 18:32:04
Receipt Date:	20170320
Manifest ID:	016757974JJK
Trans EPA ID:	CAD028277036
Trans Name:	ASBURY ENVIRONMENTAL SERVICES
Trans 2 EPA ID:	CAR000175422
Trans 2 Name:	WORLDWIDE RECOVERY SYSTEM INC
TSDF EPA ID:	AZR000515924
Trans Name:	YUMA YES LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)

ARCO #01710 (Continued) **S103656204**

Quantity Tons:	1.5
Waste Quantity:	3000
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

SAN DIEGO CO LOP:

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Record ID:	DEH1988-LSAM-H13041-002
Record Status:	Completed
Opened Date:	03/23/1988
Parcel Number:	474-581-01-00
Case Type:	LOP - Local Oversight Program
Historical Name:	ARCO 1710
SWRCB Global ID:	T0607300280
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	03/24/1988
Census Tract:	145.00
Community:	La Mesa
Jurisdiction:	LA MESA
Watershed Basin Number:	908.22
Water Purveyor:	LA MESA
Fire Agency:	LA MESA
Latitude:	32.7458224
Longitude:	-117.0424694
X MapCoord:	6317992.496
Y MapCoord:	1852065.254

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Record ID:	DEH1997-LSAM-H13041-003
Record Status:	Completed
Opened Date:	08/11/1997
Parcel Number:	474-581-01-00
Case Type:	LOP - Local Oversight Program
Historical Name:	ARCO 1710
SWRCB Global ID:	T0607302300
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	08/11/1997
Census Tract:	145.00
Community:	La Mesa
Jurisdiction:	LA MESA
Watershed Basin Number:	908.22
Water Purveyor:	LA MESA
Fire Agency:	LA MESA
Latitude:	32.7458224
Longitude:	-117.0424694
X MapCoord:	6317992.496
Y MapCoord:	1852065.254

ARCO #01710 (Continued) **S103656204**

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Record ID:	DEH1987-LSAM-H13041-001
Record Status:	Completed
Opened Date:	01/30/1987
Parcel Number:	474-581-01-00
Case Type:	FIT - Failed Integrity Test
Historical Name:	PRESTIGE STATIONS INC #695
SWRCB Global ID:	T0608128337
Funding:	N - Non-Billable
Lead Agency:	DEH/SAM
Lead Agency Date:	01/30/1987
Census Tract:	145.00
Community:	La Mesa
Jurisdiction:	LA MESA
Watershed Basin Number:	908.22
Water Purveyor:	LA MESA
Fire Agency:	LA MESA
Latitude:	32.7458224
Longitude:	-117.0424694
X MapCoord:	6317992.496
Y MapCoord:	1852065.254

CERS:

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 919417637
Site ID:	194450
CERS ID:	T0607302300
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Name:	ARCO #01710
Address:	3775 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941-7637
Site ID:	451926
CERS ID:	110021344516
CERS Description:	US EPA Air Emission Inventory System (EIS)

Name:	ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Site ID:	42706
CERS ID:	10360585
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-06-2015
Citation:	22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Description:	Failure to obtain and/or maintain an Active EPA ID.
Violation Notes:	Returned to compliance on 08/30/2015. Inspection Sequence ID:5160999
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,

ARCO #01710 (Continued) **S103656204**

Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-10-2022
Citation:	23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description:	Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.
Violation Notes:	Returned to compliance on 08/10/2022. Inspection Sequence ID:6987457;Tank ID:22460,22461,22462;Violation Description:(TCR 9b)Failure to comply with one or more of the following overfill prevention equipment requirements: 1) Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or 2) Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or 3) Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or 4) Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5) Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipme
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,

Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-16-2019
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description:	Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release

ARCO #01710 (Continued) **S103656204**

	of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.
Violation Notes:	Returned to compliance on 08/16/2019. Inspection Sequence ID:6207290;Tank ID:22461;Violation Description:(TCR 9d) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly. with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-02-2018
Citation:	23 CCR 16 2636(f)(1) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(1)
Violation Description:	Failure of the double-walled pressurized piping to be continuously monitored with a system that activates an audible and visual alarm or stops flow at the dispenser when a leak is detected.
Violation Notes:	Returned to compliance on 08/02/2018. Inspection Sequence ID:5939500;Tank ID:22461;Violation Description:(RD) Failure of the double-walled pressurized piping to be continuously monitored with a system that activates an audible and visual alarm or stops flow at dispenser when a leak is detected. 23 CCR 2636(f)(1)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-06-2015
Citation:	23 CCR 16 2666(c) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2666(c)
Violation Description:	Failure of line leak detector to detect a leak and/or failure of audible and visual alarm.
Violation Notes:	Returned to compliance on 08/13/2015. Inspection Sequence ID:5160999;Tank ID:22460,22461;Violation Description:Failure of line leak detector to detect a leak and/or failure of audible and visual alarm. 23 CCR 2636(f)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-16-2021
Citation:	HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description:	"Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container.

ARCO #01710 (Continued) **S103656204**

Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "

Violation Notes: Returned to compliance on 08/16/2021. Inspection Sequence ID:6702672;Tank ID:22461;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 42706
Site Name: Alia Petroleum Inc. dba Massachusetts Arco
Violation Date: 08-10-2022
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description: Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes: Inspection Sequence ID:6987457
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 42706
Site Name: Alia Petroleum Inc. dba Massachusetts Arco
Violation Date: 08-03-2017
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description: Business Plan Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 09/29/2017. Inspection Sequence ID:5772749;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 42706
Site Name: Alia Petroleum Inc. dba Massachusetts Arco
Violation Date: 08-10-2022
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

ARCO #01710 (Continued) **S103656204**

Violation Notes:	Inspection Sequence ID:6987457
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-10-2022
Citation:	HSC 6.95 25508(a)(3 - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3
Violation Description:	Failure to report program data electronically.
Violation Notes:	Inspection Sequence ID:6987457
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-10-2022
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description:	Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.
Violation Notes:	Inspection Sequence ID:6987457;Tank ID:22461,22462;Violation Description:(TCR 9d) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: 1) Monitored with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch within an hour. 2) Restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-10-2022
Citation:	HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Description:	Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes:	Inspection Sequence ID:6987457
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,

ARCO #01710 (Continued) **S103656204**

Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-02-2018
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description:	Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 p.s.i.g. and restrict or shut off the flow of product through the piping when a leak is detected.
Violation Notes:	Returned to compliance on 08/02/2018. Inspection Sequence ID:5939500;Tank ID:22461;Violation Description:(RD) Failure of the line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly. with the capability of detecting a release of 3.0 gallons per hour leak at 10 p.s.i.g. and restrict or shut off the flow of product through the piping when a leak is detected. 23 CCR 2636(f)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,

Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-10-2022
Citation:	HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Inspection Sequence ID:6987457
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,

Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-10-2022
Citation:	22 CCR 11 66261.7 - California Code of Regulations, Title 22, Chapter 11, Section(s) 66261.7
Violation Description:	Failure to manage empty containers greater than 5 gallons in capacity that previously held a hazardous material/waste in accordance with 22 CCR 11 66261.7 including but not limited to the following: (e)(2)By reclaiming its scrap value onsite or shipping the container or inner liner to a person who reclaims its scrap value; or (3) By reconditioning or re manufacturing the container or inner liner onsite for subsequent reuse, or shipping the container or inner liner to a person who reconditions or re-manufactures the container or inner liner; or (4) By shipping the container or inner liner to a supplier or to another intermediate collection location for accumulation prior to managing the container or inner liner pursuant to subsections (e)(2) or (e)(3) of 22 CCR 11 66261.7; or (i) By shipping the container or inner liner back to the supplier for the purpose of being refilled. (f) A container or an inner liner removed from a container larger than five gallons in capacity which is managed pursuant to subsection (e) of 22 CCR 11 66261.7 shall be marked with the date it has been emptied and shall be managed within one year of being emptied.
Violation Notes:	Inspection Sequence ID:6987457

ARCO #01710 (Continued) **S103656204**

Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-16-2019
Citation:	23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Description:	Failure to comply with one or more of the following overfill prevention equipment requirements: Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018. For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter. For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter. Inspected within 30 days after a repair to the overfill prevention equipment. Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Inspected by a certified UST service technician. Maintain records of overfill prevention equipment inspection for 36 months.
Violation Notes:	Returned to compliance on 08/16/2019. Inspection Sequence ID:6207290;Tank ID:22460,22461,22462;Violation Description:(TCR 9b) Failure to comply with one or more of the following overfill prevention equipment requirements: 1. Alert the transfer operator when the tank is 90% full by restricting the flow into the tank or triggering an audible and visual alarm; or 2. Restrict delivery of flow to the tank at least 30m before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95% of capacity and activate an audible alarm at least 5m before the tank overfills; or 3. Provide positive shut-off of flow to the tank when the tank is filled to no more than 95% of capacity; or 4. Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling. 5. Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prev
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	42706
Site Name:	Alia Petroleum Inc. dba Massachusetts Arco
Violation Date:	08-16-2021
Citation:	23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter

ARCO #01710 (Continued) **S103656204**

16, Section(s) 2716(e)

Violation Description: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.

Violation Notes: Returned to compliance on 09/20/2021. Inspection Sequence ID:6702672;Tank ID:22460,22461,22462;Violation Description:(TCR 12) Failure to comply with one or more of the following Designated Operator (DO) inspection requirements: Conduct the DO visual inspection at least once every 30 days. Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented.Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). The owner/operator sign and date the Designated Underground Storage Tank Operator Visual Inspection Report within 72 hours

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 42706
Site Name: Alia Petroleum Inc. dba Massachusetts Arco
Violation Date: 08-16-2019
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2

Violation Description: "Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "

Violation Notes: Returned to compliance on 08/16/2019. Inspection Sequence ID:6207290;Tank ID:22461;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion.

ARCO #01710 (Continued) **S103656204**

Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5939500
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-03-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5772749
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-04-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5467433
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-10-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6987457
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-11-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Khan Steven Inspection ID:4977847
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

ARCO #01710 (Continued) **S103656204**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-16-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:6207290
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-16-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:6207290
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5939500
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-04-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5467433
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-06-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5160999
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-06-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5160999
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-10-2022
Violations Found: Yes

ARCO #01710 (Continued) **S103656204**

Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6987457
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-11-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Khan Steven Inspection ID:4977847
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-11-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Khan Steven Inspection ID:4977847
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-06-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5160999
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-10-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6987457
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-16-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:6207290
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-16-2021
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6702672
Eval Division: San Diego County Department of Env Health

ARCO #01710 (Continued) **S103656204**

Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5939500
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-03-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5772749
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-03-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5772749
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 08-04-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5467433
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 08-05-2020
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: "No On-site Inspection" Inspector: Villena Elaine Inspection ID:6478874
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Coordinates:
Site ID: 42706
Facility Name: Alia Petroleum Inc. dba Massachusetts Arco
Env Int Type Code: HWG
Program ID: 10360585
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.745820

ARCO #01710 (Continued) **S103656204**

Longitude: -117.042470

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 3775 MASSACHUSETTS AVE.
Affiliation City: LA MESA
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 91941
Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: ALIA PETROLEUM LLC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 571-0018,

Affiliation Type Desc: Property Owner
Entity Name: AMACA PROPERTIES LLC
Entity Title: Not reported
Affiliation Address: 2940 LYTTON AVE
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 92110
Affiliation Phone: (619) 654-4443,

Affiliation Type Desc: Parent Corporation
Entity Name: LA MESA NINE DIAMONDS, LLC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: UST Permit Applicant
Entity Name: AKRAM DAOUD
Entity Title: OPERATOR
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 571-0018,

Affiliation Type Desc: UST Property Owner Name
Entity Name: AMACA PROPERITIES LLC.
Entity Title: Not reported
Affiliation Address: 2940 LYTTON AVE.

ARCO #01710 (Continued) **S103656204**

Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92110
Affiliation Phone:	(619) 654-4443,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,
Affiliation Type Desc:	Document Preparer
Entity Name:	TIM MONTIJO
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	UST Tank Owner
Entity Name:	AMACA PROPERITIES LLC.
Entity Title:	Not reported
Affiliation Address:	2940 LYTTON AVE.
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92110
Affiliation Phone:	(619) 654-4443,
Affiliation Type Desc:	Environmental Contact
Entity Name:	Tim Montijo
Entity Title:	Not reported
Affiliation Address:	P{O Box 1872
Affiliation City:	Escondido
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92033
Affiliation Phone:	,
Affiliation Type Desc:	Legal Owner
Entity Name:	AMACA PROPERTIES LLC
Entity Title:	Not reported
Affiliation Address:	2940 LYTTON AVE.
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92110
Affiliation Phone:	(619) 654-4443,
Affiliation Type Desc:	UST Tank Operator

ARCO #01710 (Continued) **S103656204**

Entity Name: AKRAM DAOUD (ALIA PROPERITIES LLC)
Entity Title: Not reported
Affiliation Address: 3775 MASSACHUSETTS AVE
Affiliation City: LA MESA
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91941
Affiliation Phone: (619) 571-0018,

Name: ARCO #1710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 919417637
Site ID: 194450
CERS ID: T0607300280
CERS Description: Leaking Underground Storage Tank Cleanup Site

Name: ARCO #1710
Address: 3775 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 919417637
Site ID: 194450
CERS ID: T0608128337
CERS Description: Cleanup Program Site

HWTS:
Name: ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Address: 3775 MASSACHUSETTS AVE
Address 2: Not reported
City,State,Zip: LA MESA, CA 91941
EPA ID: CAL000409613
Inactive Date: Not reported
Create Date: 08/24/2015
Last Act Date: Not reported
Mailing Name: Not reported
Mailing Address: 3775 MASSACHUSETTS AVE
Mailing Address 2: Not reported
Mailing City,State,Zip: LA MESA, CA 91941
Owner Name: ALIA PETROLEUM INC.
Owner Address: 3775 MASSACHUSETTS AVE
Owner Address 2: Not reported
Owner City,State,Zip: LA MESA, CA 91941
Contact Name: AKRAM DAOUD
Contact Address: 12371 CALLE ALBARA #6
Contact Address 2: Not reported
City,State,Zip: EL CAJON, CA 92019
Facility Status: Active
Facility Type: PERMANENT
Category: STATE
Latitude: 32.745807
Longitude: -117.042489

NAICS:
EPA ID: CAL000409613
Create Date: 2015-08-24 10:42:09.633
NAICS Code: 44719
NAICS Description: Other Gasoline Stations
Issued EPA ID Date: 2015-08-24 10:42:09.63000

ARCO #01710 (Continued) **S103656204**

Inactive Date:	Not reported
Facility Name:	ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Facility Address:	3775 MASSACHUSETTS AVE
Facility Address 2:	Not reported
Facility City:	LA MESA
Facility County:	Not reported
Facility State:	CA
Facility Zip:	91941

H42 **PRESTIGE STATIONS INC 695** **HIST UST** **U001571825**
WSW **3775 MASSACHUSETTS AVE** **N/A**
1/8-1/4 **LA MESA, CA 92041**
0.214 mi.
1128 ft. **Site 5 of 11 in cluster H**

Relative: **Lower**

Actual: **455 ft.**

HIST UST:

Name:	PRESTIGE STATIONS INC 695
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 92041
File Number:	0002aba3
URL:	https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002aba3.pdf
Region:	STATE
Facility ID:	00000026612
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	0000000000
Owner Name:	ARCO PETROLEUM PRODUCTS CO.
Owner Address:	515 SOUTH FLOWER STREET
Owner City,St,Zip:	LOS ANGELES, CA 90071
Total Tanks:	0005
Tank Num:	001
Container Num:	0000000001
Year Installed:	1961
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	0000240
Leak Detection:	Stock Inventor, 10
Tank Num:	002
Container Num:	0000000002
Year Installed:	1961
Tank Capacity:	00004000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	0000167
Leak Detection:	Stock Inventor, 10
Tank Num:	003
Container Num:	0000000003
Year Installed:	1961
Tank Capacity:	00004000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	0000167

PRESTIGE STATIONS INC 695 (Continued) **U001571825**

Leak Detection: Stock Inventor, 10

Tank Num: 004
Container Num: 0000000004
Year Installed: 1973
Tank Capacity: 00006000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Container Construction Thickness: 0000240
Leak Detection: Stock Inventor, 10

Tank Num: 005
Container Num: 0000000005
Year Installed: 1961
Tank Capacity: 00000280
Tank Used for: PRODUCT
Type of Fuel: WASTE OIL
Container Construction Thickness: 0000093
Leak Detection: Stock Inventor

Click here for Geo Tracker PDF:

H43 **ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO** **UST** **U004274010**
WSW **3775 MASSACHUSETTS AVE** **N/A**
1/8-1/4 **LA MESA, CA 91941**
0.214 mi.
1128 ft. **Site 6 of 11 in cluster H**

Relative: **Lower**

Actual: **455 ft.**

UST:
Name: ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO
Address: 3775 MASSACHUSETTS AVE
City,State,Zip: LA MESA, CA 91941
Facility ID: 37-000-207982
Permitting Agency: San Diego County Department of Environmental Health
CERSID: 10360585
Latitude: 32.7458200
Longitude: -117.042470
Owner type: Not reported
Facility type: Not reported
Num of inuse ust: Not reported
Num of closed ust: Not reported
Num of oos ust: Not reported
Epa region: Not reported
Tribal lands: Not reported
Tank owner name: Not reported
Tank owner mailing address: Not reported
Tank owner mailing city: Not reported
Tank owner mailing zip: Not reported
Tank owner mailing state: Not reported
Tank operator name: Not reported
Tank operator mailing address: Not reported
Tank operator mailing city: Not reported
Tank operator mailing zip: Not reported
Tank operator mailing state: Not reported
Tankidnumber: Not reported
Tank status: Not reported
Tank configuration: Not reported
Tank closure date: Not reported

ALIA PETROLEUM INC. DBA MASSACHUSETTS ARCO (Continued) **U004274010**

Tank installation date:	Not reported
Tank num of compartments:	Not reported
Tank contents:	Not reported
Tank capacity gallons:	Not reported
Tank type:	Not reported
Tank pc construction:	Not reported
Tank pwpiping construction:	Not reported
Tank piping type:	Not reported
Tank piping construction:	Not reported
Tank sacrificial anode:	Not reported
Tank cp impressed current:	Not reported
Tank cp shutoff:	Not reported
Tank alarms:	Not reported
Tank ball float:	Not reported
Tank spill bucket:	Not reported

H44 **ARCO FACILITY NO 01710** **RCRA NonGen / NLR** **1004678146**
WSW **3775 MASSACHUSETTS AVE** **FINDS** **CAR000105551**
1/8-1/4 **LA MESA, CA 91941** **ECHO**
0.214 mi.
1128 ft. **Site 7 of 11 in cluster H**

Relative: **Lower**
Actual: **455 ft.**

RCRA Listings:

Date Form Received by Agency:		20061213
Handler Name:	ARCO FACILITY NO 01710	
Handler Address:		3775 MASSACHUSETTS AVE
Handler City,State,Zip:		LA MESA, CA 91941
EPA ID:		CAR000105551
Contact Name:		JACKIE DOUGHERTY
Contact Address:		PO BOX 80249
Contact City,State,Zip:		RANCHO SANTA MARGARITA, CA 92688
Contact Telephone:		949-460-5200
Contact Fax:		Not reported
Contact Email:		JACKIE@BELSHIRE.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Private
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		PO BOX 80249
Mailing City,State,Zip:		RANCHO SANTA MARGARITA, CA 92688
Owner Name:	B P WEST COAST PRODUCTS LLC	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No

ARCO FACILITY NO 01710 (Continued) **1004678146**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20070807
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018

ARCO FACILITY NO 01710 (Continued) **1004678146**

Waste Description: BENZENE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: B P WEST COAST PRODUCTS LLC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: P O BOX 6038
Owner/Operator City,State,Zip: ARTESIA, CA 90702-6038
Owner/Operator Telephone: 714-690-2425
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: B P WEST COAST PRODUCTS LLC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: P O BOX 6038
Owner/Operator City,State,Zip: ARTESIA, CA 90702-6038
Owner/Operator Telephone: 714-690-2425
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20020528
Handler Name: ARCO FACILITY NO 01710
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20061213
Handler Name: ARCO FACILITY NO 01710
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

ARCO FACILITY NO 01710 (Continued) **1004678146**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110012220499

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004678146
Registry ID:	110012220499
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012220499
Name:	ARCO FACILITY NO 01710
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941

H45 **AMACA PROPERTIES LLC** **UST** **U004347450**
WSW **3775 MASSACHUSETTS AVE** **N/A**
1/8-1/4 **LA MESA, CA 91941**
0.214 mi.
1128 ft. **Site 8 of 11 in cluster H**

Relative: **Lower**
Actual: **455 ft.**

UST:

Name:	AMACA PROPERTIES LLC
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Facility ID:	37-000-207982
Permitting Agency:	San Diego County Department of Environme
CERSID:	Not reported
Latitude:	32.74582
Longitude:	-117.04247
Owner type:	Not reported
Facility type:	Not reported
Num of inuse ust:	Not reported
Num of closed ust:	Not reported
Num of oos ust:	Not reported
Epa region:	Not reported
Tribal lands:	Not reported

AMACA PROPERTIES LLC (Continued) **U004347450**

Tank owner name:	Not reported
Tank owner mailing address:	Not reported
Tank owner mailing city:	Not reported
Tank owner mailing zip:	Not reported
Tank owner mailing state:	Not reported
Tank operator name:	Not reported
Tank operator mailing address:	Not reported
Tank operator mailing city:	Not reported
Tank operator mailing zip:	Not reported
Tank operator mailing state:	Not reported
Tankidnumber:	Not reported
Tank status:	Not reported
Tank configuration:	Not reported
Tank closure date:	Not reported
Tank installation date:	Not reported
Tank num of compartments:	Not reported
Tank contents:	Not reported
Tank capacity gallons:	Not reported
Tank type:	Not reported
Tank pc construction:	Not reported
Tank pwpiping construction:	Not reported
Tank piping type:	Not reported
Tank piping construction:	Not reported
Tank sacrificial anode:	Not reported
Tank cp impressed current:	Not reported
Tank cp shutoff:	Not reported
Tank alarms:	Not reported
Tank ball float:	Not reported
Tank spill bucket:	Not reported

H46 **ARCO #1710** **UST** **U004355979**
WSW **3775 MASSACHUSETTS AVE** **N/A**
1/8-1/4 **LA MESA, CA 91941**
0.214 mi.
1128 ft. **Site 9 of 11 in cluster H**

Relative: **Lower**

Actual: **455 ft.**

UST:

Name:	ARCO #1710
Address:	3775 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Facility ID:	H13041
Permitting Agency:	SAN DIEGO COUNTY
CERSID:	Not reported
Latitude:	32.747148
Longitude:	-117.0411152
Owner type:	Not reported
Facility type:	Not reported
Num of inuse ust:	Not reported
Num of closed ust:	Not reported
Num of oos ust:	Not reported
Epa region:	Not reported
Tribal lands:	Not reported
Tank owner name:	Not reported
Tank owner mailing address:	Not reported
Tank owner mailing city:	Not reported
Tank owner mailing zip:	Not reported
Tank owner mailing state:	Not reported
Tank operator name:	Not reported

ARCO #1710 (Continued) **U004355979**

Tank operator mailing address:	Not reported
Tank operator mailing city:	Not reported
Tank operator mailing zip:	Not reported
Tank operator mailing state:	Not reported
Tankidnumber:	Not reported
Tank status:	Not reported
Tank configuration:	Not reported
Tank closure date:	Not reported
Tank installation date:	Not reported
Tank num of compartments:	Not reported
Tank contents:	Not reported
Tank capacity gallons:	Not reported
Tank type:	Not reported
Tank pc construction:	Not reported
Tank pwpiping construction:	Not reported
Tank piping type:	Not reported
Tank piping construction:	Not reported
Tank sacrificial anode:	Not reported
Tank cp impressed current:	Not reported
Tank cp shutoff:	Not reported
Tank alarms:	Not reported
Tank ball float:	Not reported
Tank spill bucket:	Not reported

H47 **PRESTIGE STATIONS INC #695** **SWEEPS UST** **S106930878**
WSW **3775 MASSACHUSETTS AVE 1710** **N/A**
1/8-1/4 **LA MESA, CA 91941**
0.214 mi.
1128 ft. **Site 10 of 11 in cluster H**

Relative: **Lower**

Actual: **455 ft.**

SWEEPS UST:

Name:	PRESTIGE STATIONS INC #695
Address:	3775 MASSACHUSETTS AVE 1710
City:	LA MESA
Status:	Not reported
Comp Number:	13041
Number:	Not reported
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013041-000001
Tank Status:	Not reported
Capacity:	6000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	5

Name:	PRESTIGE STATIONS INC #695
Address:	3775 MASSACHUSETTS AVE 1710
City:	LA MESA
Status:	Not reported
Comp Number:	13041
Number:	Not reported
Board Of Equalization:	44-000506

PRESTIGE STATIONS INC #695 (Continued) **S106930878**

Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013041-000002
Tank Status:	Not reported
Capacity:	4000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	PRESTIGE STATIONS INC #695
Address:	3775 MASSACHUSETTS AVE 1710
City:	LA MESA
Status:	Not reported
Comp Number:	13041
Number:	Not reported
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013041-000003
Tank Status:	Not reported
Capacity:	4000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	PRESTIGE STATIONS INC #695
Address:	3775 MASSACHUSETTS AVE 1710
City:	LA MESA
Status:	Not reported
Comp Number:	13041
Number:	Not reported
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013041-000004
Tank Status:	Not reported
Capacity:	6000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	PRESTIGE STATIONS INC #695
Address:	3775 MASSACHUSETTS AVE 1710
City:	LA MESA
Status:	Not reported

PRESTIGE STATIONS INC #695 (Continued) **S106930878**

Comp Number:	13041
Number:	Not reported
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013041-000005
Tank Status:	Not reported
Capacity:	280
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	PRODUCT
Content:	Not reported
Number Of Tanks:	Not reported

Name:	PRESTIGE STATIONS INC #695
Address:	3775 MASSACHUSETTS AVE 1710
City:	LA MESA
Status:	Active
Comp Number:	13041
Number:	9
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013041-000006
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	LEADED
Number Of Tanks:	3

Name:	PRESTIGE STATIONS INC #695
Address:	3775 MASSACHUSETTS AVE 1710
City:	LA MESA
Status:	Active
Comp Number:	13041
Number:	9
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013041-000007
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	PRESTIGE STATIONS INC #695

PRESTIGE STATIONS INC #695 (Continued) **S106930878**

Address:	3775 MASSACHUSETTS AVE 1710
City:	LA MESA
Status:	Active
Comp Number:	13041
Number:	9
Board Of Equalization:	44-000506
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013041-000008
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

H48 **ARCO STATION #1710** **LUST** **S100929801**
WSW **3775 MASSACHUSETTS AVE** **N/A**
1/8-1/4 **LA MESA, CA 92041**
0.214 mi.
1128 ft. **Site 11 of 11 in cluster H**

Relative: **Lower**

Actual: **455 ft.**

LUST REG 9:

Region:	9
Status:	Preliminary site assessment workplan submitted
Case Number:	9UT3531
Local Case:	H13041-003
Substance:	Unleaded Gasoline
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Other Means
How Stopped:	Not reported
Source:	Piping
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Soil only
Date Found:	08/11/1997
Date Stopped:	08/11/1997
Confirm Date:	08/11/1997
Submit Workplan:	9/17/97
Prelim Assess:	/ /
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	08/11/1997
Enforce Date:	9/17/97
Closed Date:	Not reported
Enforce Type:	SEL
Pilot Program:	LOP
Basin Number:	908.22
GW Depth:	Not reported
Beneficial Use:	No Beneficial groundwater use
NPDES Number:	Not reported

ARCO STATION #1710 (Continued) **S100929801**

Priority: Low priority. Priority ranking can change over time.
File Dispn: Administratively opened on database, however no file physically exists
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

G49 **MODERN AUTO REPAIR** **RCRA NonGen / NLR** **1024759555**
SE **7586 NORTH AVE** **CAC002979403**
1/8-1/4 **LEMON GROVE, CA 91945**
0.216 mi.
1138 ft. **Site 3 of 6 in cluster G**

Relative: **Lower**
Actual: **454 ft.**

RCRA Listings:

Date Form Received by Agency:		20180907
Handler Name:	MODERN AUTO REPAIR	
Handler Address:		7586 NORTH AVE
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAC002979403
Contact Name:		AMNER GARCIA
Contact Address:		7586 NORTH AVE
Contact City,State,Zip:		LEMON GROVE, CA 91945
Contact Telephone:		858-222-7599
Contact Fax:		Not reported
Contact Email:		MODERNAUTOREPAIR@HOTMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		7586 NORTH AVE
Mailing City,State,Zip:		LEMON GROVE, CA 91945
Owner Name:	AMNER GARCIA	
Owner Type:		Other
Operator Name:	AMNER GARCIA	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported

MODERN AUTO REPAIR (Continued) **1024759555**

Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20181001
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: AMNER GARCIA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7586 NORTH AVE
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945
Owner/Operator Telephone:	858-222-7599
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: AMNER GARCIA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported

MODERN AUTO REPAIR (Continued) **1024759555**

Owner/Operator Address: 7586 NORTH AVE
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945
Owner/Operator Telephone: 858-222-7599
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180907
Handler Name: MODERN AUTO REPAIR
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G50 **MODERN AUTO REPAIR** **RCRA NonGen / NLR** **1024871179**
SE **7586 NORTH AVE** **CAL000439823**
1/8-1/4 **LEMON GROVE, CA 91945**
0.216 mi.
1138 ft. **Site 4 of 6 in cluster G**

Relative: **Lower**

Actual: **454 ft.**

RCRA Listings:
Date Form Received by Agency: 20181015
Handler Name: MODERN AUTO REPAIR
Handler Address: 7586 NORTH AVE
Handler City,State,Zip: LEMON GROVE, CA 91945
EPA ID: CAL000439823
Contact Name: AMNER GARCIA
Contact Address: 7586 NORTH AVE
Contact City,State,Zip: LEMON GROVE, CA 91945
Contact Telephone: 858-222-7599
Contact Fax: Not reported
Contact Email: MODERNAUTOREPAIR@HOTMAIL.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported

MODERN AUTO REPAIR (Continued) **1024871179**

Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		7586 NORTH AVE
Mailing City,State,Zip:		LEMON GROVE, CA 91945
Owner Name:	AMNER GARCIA	
Owner Type:		Other
Operator Name:	AMNER GARCIA	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	

MODERN AUTO REPAIR (Continued) **1024871179**

Handler Date of Last Change:	20181120
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: AMNER GARCIA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7586 NORTH AVE
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945
Owner/Operator Telephone:	858-222-7599
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: AMNER GARCIA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7586 NORTH AVE
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945
Owner/Operator Telephone:	858-222-7599
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20181015
Handler Name: MODERN AUTO REPAIR	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	811111
NAICS Description:	GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:

Violations:	No Violations Found

MODERN AUTO REPAIR (Continued) **1024871179**

Evaluation Action Summary:
Evaluations: No Evaluations Found

G51 **SUPERIOR SMOG AND TUNE** **San Diego Co. HMMD** **S127596118**
SE **7586 NORTH AVE** **CERS HAZ WASTE** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945**
0.216 mi.
1138 ft. **Site 5 of 6 in cluster G**

Relative:
Lower

Actual:
454 ft.

HMMD SAN DIEGO:

Name:	SUPERIOR SMOG AND TUNE
Address:	7586 NORTH AVE
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAL000303308
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	6194692112
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	08/06/2022
Facility Owner:	Not reported
Facility Mailing Address:	7319 BROADWAY, LEMON GROVE, CA 91945
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	N
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2022-02-04T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS MATERIALS REQUIREMENTS

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	2022-07-16T00:00:00.000
Nov:	Yes
Violation Classification:	Class I
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2022-02-04T00:00:00.000
Violation Code:	HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.904; 68.905; 68.907.1

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator
Inspection Type:	Initial Inspection
Inspection Number:	6078145
Return To Compliance Date:	2018-10-04T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2018-10-02T00:00:00.000
Violation Code:	HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.905

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5695237
Return To Compliance Date:	2018-04-23T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2017-07-07T16:38:00.000
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	2022-04-26T00:00:00.000
Nov:	Yes
Violation Classification:	Class I
Underground Storage Tank Id:	Not reported

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2022-02-04T00:00:00.000
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.904; 68.905; 68.906, 68.907; 68.907.1
Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5695237
Return To Compliance Date:	2018-04-23T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2017-07-07T16:38:00.000
Violation Code:	HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. HSC 25404.1; SDCC 68.905
Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator
Inspection Type:	Initial Inspection
Inspection Number:	6078145
Return To Compliance Date:	2018-10-04T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2018-10-02T00:00:00.000
Violation Code:	3030030 Failed to maintain &/or operate facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents. 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(4), 265.31
Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator
Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2022-02-04T00:00:00.000
Violation Code:	HMD0001 RECORD KEEPING/OPERATIONAL REQUIREMENTS

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator
Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2022-02-04T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS ONLY

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator
Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2022-02-04T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS WASTE REQUIREMENTS FOR SQGS AND LQGS

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator
Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	2022-03-29T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2022-02-04T00:00:00.000
Violation Code:	3030017 Failed to properly close hazardous waste container(s). 22 CCR 66262.34(d)(2); 40 CFR 262.34(d)(2), 265.173

Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Waste Generator
Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	2022-03-24T00:00:00.000

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2022-02-04T00:00:00.000
Violation Code:	HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)
Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	5695237
Return To Compliance Date:	2017-09-01T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2017-07-07T16:38:00.000
Violation Code:	1020002 Initial &/or annual employee training not conducted for hazardous materials management &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)
Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection
Inspection Number:	6078145
Return To Compliance Date:	2018-10-04T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T01:32:37.000
Inspection Date:	2018-10-02T00:00:00.000
Violation Code:	HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907
Record ID:	DEH2002-HUPFP-113871
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-113871
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection
Inspection Number:	6751411
Return To Compliance Date:	2022-03-29T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Container/Tank Id: Not reported
Last Update: 2022-08-06T01:32:37.000
Inspection Date: 2022-02-04T00:00:00.000
Violation Code: 1020002 Initial &/or annual employee training not conducted in safety procedures for a hazardous material release or threatened release &/or employee training records not available or not maintained for 3 years. HSC 25505(a)(4); 19 CCR 2659(b)

Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-113871
Program Element: Hazardous Materials Release Response Plans
Inspection Type: Initial Inspection
Inspection Number: 6751411
Return To Compliance Date: 2022-03-24T00:00:00.000
Nov: No
Violation Classification: Class II
Underground Storage Tank Id: Not reported
Container/Tank Id: Not reported
Last Update: 2022-08-06T01:32:37.000
Inspection Date: 2022-02-04T00:00:00.000
Violation Code: 1010002 HMBP not submitted in CERS within the required timeframe. HSC 25508(a)(1); 27 CCR 15188(a),(b),(d)

Waste and Materials:
Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2015-HCHEM-0068559
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2016-10-18T02:30:45.000
Chemical Name: Motor Oil
Common Name: Automatic Transmission Fluid - Dexron III
Case Number: Not reported

Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2015-HWAST-0052857
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2016-10-18T02:30:45.000
Chemical Name: WASTE 221 WASTE OIL & MIXED OIL
Common Name: WASTE 221 WASTE OIL & MIXED OIL
Case Number: Not reported

Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2015-HWAST-0052858
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2016-10-18T02:30:45.000
Chemical Name: WASTE 121 ALKALINE SOL'N WITH METALS
Common Name: HOT TANK SOLUTION-OILY

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Case Number: Not reported

Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2015-HWAST-0052859
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2016-10-18T02:30:45.000
Chemical Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0325472
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-08-06T01:32:37.000
Chemical Name: Not reported
Common Name: Motor Oil
Case Number: Not reported

Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0325473
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-08-06T01:32:37.000
Chemical Name: Ethylene Glycol
Common Name: Ethylene Glycol
Case Number: 107-21-1

Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0292331
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-08-06T01:32:37.000
Chemical Name: Not reported
Common Name: Used Oil Filters (Paper)
Case Number: Not reported

Record ID: DEH2002-HUPFP-113871
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0292332
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-08-06T01:32:37.000
Chemical Name: Not reported
Common Name: Used Oil Filters (Metal)
Case Number: Not reported

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

CERS HAZ WASTE:

Name:	SUPERIOR SMOG AND TUNE
Address:	7586 NORTH AVE
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	576548
CERS ID:	10361281
CERS Description:	Hazardous Waste Generator

Violations:

Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	02-04-2022
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 07/16/2022. Inspection Sequence ID:6751411;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.904; 68.905; 68.907.1
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	10-02-2018
Citation:	40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.31
Violation Description:	Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to air, soil, or surface water which could threaten human health or the environment.
Violation Notes:	Returned to compliance on 10/04/2018. Inspection Sequence ID:6078145
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	07-07-2017
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Returned to compliance on 09/01/2017. Inspection Sequence ID:5695237
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	02-04-2022
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5,

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

	Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Operations/Maintenance - General
Violation Notes:	Returned to compliance on 03/24/2022. Inspection Sequence ID:6751411;Violation:HMD0152 Failed to report &/or update the required inventory information for hazardous waste(s) generated at the facility in CERS. SDCC 68.904(a)(2)
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	07-07-2017
Citation:	HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description:	Business Plan Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 04/23/2018. Inspection Sequence ID:5695237;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	02-04-2022
Citation:	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Description:	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Violation Notes:	Returned to compliance on 03/29/2022. Inspection Sequence ID:6751411
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	02-04-2022
Citation:	HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description:	Business Plan Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 04/26/2022. Inspection Sequence ID:6751411;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.904; 68.905; 68.906, 68.907; 68.907.1
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	10-02-2018
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Administration/Documentation -

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

	General
Violation Notes:	Returned to compliance on 10/04/2018. Inspection Sequence ID:6078145;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.905
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	02-04-2022
Citation:	40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description:	Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes:	Returned to compliance on 03/29/2022. Inspection Sequence ID:6751411
Violation Division:	San Diego County Department of Env Health
Violation Program:	HW
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	10-02-2018
Citation:	HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description:	Business Plan Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 10/04/2018. Inspection Sequence ID:6078145;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	02-04-2022
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.
Violation Notes:	Returned to compliance on 03/24/2022. Inspection Sequence ID:6751411
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	576548
Site Name:	Superior Smog and Tune
Violation Date:	07-07-2017
Citation:	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description:	Hazardous Waste Generator Program - Administration/Documentation -

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

General
Violation Notes: Returned to compliance on 04/23/2018. Inspection Sequence ID:5695237;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. HSC 25404.1; SDCC 68.905
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-09-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Griffin Donelle Inspection ID:4098300
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-02-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Griffin Donelle Inspection ID:6078145
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-02-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Griffin Donelle Inspection ID:6078145
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-07-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kieu Bridget Inspection ID:5695237
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-09-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Griffin Donelle Inspection ID:4098300
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-04-2022

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Zakaria MaryAnn Inspection ID:6751411
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 07-07-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kieu Bridget Inspection ID:5695237
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-04-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Zakaria MaryAnn Inspection ID:6751411
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Coordinates:
Site ID: 576548
Facility Name: Superior Smog and Tune
Env Int Type Code: HMBP
Program ID: 10361281
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.744580
Longitude: -117.034610

Affiliation:
Affiliation Type Desc: Environmental Contact
Entity Name: PATTY BROWN
Entity Title: Not reported
Affiliation Address: 13465 Camino Canada #106-312
Affiliation City: El Cajon
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92021
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: Juan Mendoza
Entity Title: Owner
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Affiliation Type Desc:	Legal Owner
Entity Name:	Juan Mendoza
Entity Title:	Not reported
Affiliation Address:	7319 BROADWAY
Affiliation City:	LEMON GROVE
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91945
Affiliation Phone:	(619) 469-2112,

Affiliation Type Desc:	Parent Corporation
Entity Name:	Superior Smog & Tune
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	Document Preparer
Entity Name:	Juan Mendoza
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	7586 NORTH AVENUE
Affiliation City:	LEMON GROVE
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91945
Affiliation Phone:	,

Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,

Affiliation Type Desc:	Operator
Entity Name:	Juan Mendoza
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported

SUPERIOR SMOG AND TUNE (Continued) **S127596118**

Affiliation Zip: Not reported
Affiliation Phone: (619) 838-4967,

G52 **SUPERIOR SMOG AND TUNE** **RCRA NonGen / NLR** **1026828556**
SE **7586 NORTH AVE** **CAL000463552**
1/8-1/4 **LEMON GROVE, CA 91945**
0.216 mi.
1138 ft. **Site 6 of 6 in cluster G**

Relative: **Lower**
Actual: **454 ft.**

RCRA Listings:

Date Form Received by Agency:		20210621
Handler Name:	SUPERIOR SMOG AND TUNE	
Handler Address:		7586 NORTH AVE
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAL000463552
Contact Name:		JUAN MENDOZA
Contact Address:		763 CONCEPCION AVE
Contact City,State,Zip:		SPRING VALLEY, CA 91977
Contact Telephone:		619-469-2112
Contact Fax:		619-469-2113
Contact Email:		SUPERIOR1963@GMAIL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		763 CONCEPCION AVE
Mailing City,State,Zip:		SPRING VALLEY, CA 91977
Owner Name:	JUAN MENDOZA	
Owner Type:		Other
Operator Name:	JUAN MENDOZA	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported

SUPERIOR SMOG AND TUNE (Continued) **1026828556**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20210630
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JUAN MENDOZA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	763 CONCEPCION AVE
Owner/Operator City,State,Zip:	SPRING VALLEY, CA 91977
Owner/Operator Telephone:	619-838-4967
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JUAN MENDOZA	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	763 CONCEPCION AVE
Owner/Operator City,State,Zip:	SPRING VALLEY, CA 91977

SUPERIOR SMOG AND TUNE (Continued) **1026828556**

Owner/Operator Telephone: 619-469-2112
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20210621
Handler Name: SUPERIOR SMOG AND TUNE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

53
NE
1/8-1/4
0.217 mi.
1147 ft.

DEBBIE TERRELL
3951 APORE STREET
LA MESA, CA 91941

RCRA NonGen / NLR **1025841222**
CAC003020827

Relative:
Higher

Actual:
568 ft.

RCRA Listings:
Date Form Received by Agency: 20190621
Handler Name: DEBBIE TERRELL
Handler Address: 3951 APORE STREET
Handler City,State,Zip: LA MESA, CA 91941
EPA ID: CAC003020827
Contact Name: DEBBIE TERRELL
Contact Address: 3951 APORE STREET
Contact City,State,Zip: LA MESA, CA 91941
Contact Telephone: 774-238-1588
Contact Fax: Not reported
Contact Email: CINDYEDWARDS@ALLIANCE-ENVIRO.COM
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities

DEBBIE TERRELL (Continued) **1025841222**

State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3951 APORE STREET
Mailing City,State,Zip:		LA MESA, CA 91941
Owner Name:	DEBBIE TERRELL	
Owner Type:		Other
Operator Name:	DEBBIE TERRELL	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	
Handler Date of Last Change:		20190729
Recognized Trader-Importer:		No

DEBBIE TERRELL (Continued) **1025841222**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: DEBBIE TERRELL	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3951 APORE STREET
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	774-238-1588
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: DEBBIE TERRELL	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3951 APORE STREET
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	774-238-1588
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20190621
Handler Name: DEBBIE TERRELL	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56299
NAICS Description:	ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

DEBBIE TERRELL (Continued) **1025841222**

Evaluation Action Summary:
Evaluations: No Evaluations Found

I54 **PP-CA LP DBA SAN DIEGO PET HOSPITAL** **RCRA NonGen / NLR** **1027093169**
South **7368 BROADWAY STE A** **CAL000466725**
1/8-1/4 **LEMON GROVE, CA 91945**
0.223 mi.
1176 ft. **Site 1 of 4 in cluster I**

Relative: **Lower**

Actual: **419 ft.**

RCRA Listings:

Date Form Received by Agency:		20211110
Handler Name:	PP-CA LP DBA SAN DIEGO PET HOSPITAL	
Handler Address:		7368 BROADWAY STE A
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAL000466725
Contact Name:		TRACY MILES
Contact Address:		7368 BROADWAY STE A
Contact City,State,Zip:		LEMON GROVE, CA 91945
Contact Telephone:		619-462-6600
Contact Fax:		512-870-9394
Contact Email:		LEGAL@PATHWAYVETS.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		800 W CESAR CHAVEZ ST B100
Mailing City,State,Zip:		AUSTIN, TX 78701
Owner Name:	PP-CA LP	
Owner Type:		Other
Operator Name:	TRACY MILES	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N

PP-CA LP DBA SAN DIEGO PET HOSPITAL (Continued) **1027093169**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20211115
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PP-CA LP	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	330 N BRAND BLVD
Owner/Operator City,State,Zip:	GLENDALE, CA 91230
Owner/Operator Telephone:	512-225-2814
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: TRACY MILES	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7368 BROADWAY STE A

PP-CA LP DBA SAN DIEGO PET HOSPITAL (Continued) **1027093169**

Owner/Operator City,State,Zip: LEMON GROVE, CA 91945
Owner/Operator Telephone: 619-462-6600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20211110
Handler Name: PP-CA LP DBA SAN DIEGO PET HOSPITAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 541940
NAICS Description: VETERINARY SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

I55 **SAN DIEGO PET HOSPITAL** **San Diego Co. HMMD** **S106066366**
South **7368 BROADWAY** **CERS HAZ WASTE** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945**
0.223 mi.
1176 ft. **Site 2 of 4 in cluster I**

Relative:
Lower

Actual:
419 ft.

HMMD SAN DIEGO:
Name: SAN DIEGO PET HOSPITAL
Address: 7368 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 150481
Business Type: 6HK10
EPA Id Number: CAL000112441
APN: 479-052-15-00
Last HMMD Inspection: 08/14/2006
Facility Telephone: 619-462-6600
Permit Status: CHNG
Permit Expiration: 12/31/2007
Date Last Updated: 11/02/2012
Facility Owner: MICHAEL JAY CLARK DVM
Facility Mailing Address: 7368 BROADWAY A
Facility Mailing City: LEMON GROVE
Facility Mailing State: CA
Facility Mailing Zip: 91945-1512
UST Owner: Not reported

SAN DIEGO PET HOSPITAL (Continued) **S106066366**

Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

CERS HAZ WASTE:
Name: SAN DIEGO PET HOSPITAL
Address: 7368 BROADWAY STE A
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 64455
CERS ID: 10361416
CERS Description: Hazardous Waste Generator

Violations:
Site ID: 64455
Site Name: SAN DIEGO PET HOSPITAL
Violation Date: 10-13-2021
Citation: 22 CCR 12 66262.11 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.11
Violation Description: Failure to determine if wastes generated are hazardous waste by using generator knowledge or applying testing method.
Violation Notes: Returned to compliance on 10/20/2021. Inspection Sequence ID:6797855
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Site ID: 64455
Site Name: SAN DIEGO PET HOSPITAL
Violation Date: 10-13-2021
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 04/06/2022. Inspection Sequence ID:6797855;Violation:HMD0150 Failed to submit complete and accurate Facility Information in CERS. 27 CCR 15188(b-c); SDCC 68.904(b)
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 10-13-2021
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Velediaz Belinda Inspection ID:6797855
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported

SAN DIEGO PET HOSPITAL (Continued) **S106066366**

Affiliation Address:	7368 Broadway Suite 4
Affiliation City:	Lemon Grove
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91945
Affiliation Phone:	,
Affiliation Type Desc:	Operator
Entity Name:	Tracy Miles
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(619) 462-6600,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,
Affiliation Type Desc:	Legal Owner
Entity Name:	Pathway Partners
Entity Title:	Not reported
Affiliation Address:	800 W Cesar Chavez St. B-100
Affiliation City:	Austin
Affiliation State:	TX
Affiliation Country:	United States
Affiliation Zip:	78701
Affiliation Phone:	(619) 462-6600,
Affiliation Type Desc:	Environmental Contact
Entity Name:	Tracy Miles
Entity Title:	Not reported
Affiliation Address:	7368 Broadway Ste A
Affiliation City:	Lemon Grove
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91945
Affiliation Phone:	,
Affiliation Type Desc:	Parent Corporation
Entity Name:	SAN DIEGO PET HOSPITAL
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

SAN DIEGO PET HOSPITAL (Continued) **S106066366**

Affiliation Type Desc:	Document Preparer
Entity Name:	Lindsay DiPaolo, EHT
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

J56 **LEMON GROVE AUTO** **ENVIROSTOR** **S106797738**
SSW **3463-3465 CITRUS STREET** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945**
0.233 mi.
1230 ft. **Site 1 of 2 in cluster J**

Relative: **Lower**
Actual: **424 ft.**

ENVIROSTOR:

Name:	LEMON GROVE AUTO
Address:	3463-3465 CITRUS STREET
City,State,Zip:	LEMON GROVE, CA 91945
Facility ID:	37750004
Status:	Refer: 1248 Local Agency
Status Date:	08/11/2004
Site Code:	Not reported
Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Referred - Not Assigned
Division Branch:	Cleanup Cypress
Assembly:	79
Senate:	38
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	Not Applicable
Latitude:	32.74327
Longitude:	-117.0402
APN:	NONE SPECIFIED
Past Use:	NONE SPECIFIED
Potential COC:	NONE SPECIFIED
Confirmed COC:	NONE SPECIFIED
Potential Description:	NONE SPECIFIED
Alias Name:	T06019701630
Alias Type:	GeoTracker Global ID
Alias Name:	T0607399203
Alias Type:	GeoTracker Global ID
Alias Name:	37750004
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	Not reported
Completed Sub Area Name:	Not reported
Completed Document Type:	Not reported

LEMON GROVE AUTO (Continued) **S106797738**

Completed Date: Not reported
Comments: Not reported

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

J57 **LEMON GROVE AUTO** **LUST** **S102625814**
SSW **3465 CITRUS ST** **SAN DIEGO CO. SAM** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945** **CPS-SLIC**
0.233 mi. **San Diego Co. HMMD**
1231 ft. **Site 2 of 2 in cluster J** **Cortese**
SAN DIEGO CO LOP
Relative: **CERS**
Lower

Actual: LUST:
424 ft.

Name: LEMON GROVE AUTO
Address: 3465 CITRUS ST
City,State,Zip: LEMON GROVE, CA 91945
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607399203
Global Id: T0607399203
Latitude: 32.7432906
Longitude: -117.0406865
Status: Completed - Case Closed
Status Date: 09/20/2004
Case Worker: Not reported
RB Case Number: 9UT3987
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H36873-001
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:

Global Id: T0607399203
Action Type: ENFORCEMENT
Date: 09/20/2004
Action: Closure/No Further Action Letter

Global Id: T0607399203
Action Type: Other
Date: 09/14/1999
Action: Leak Began

Global Id: T0607399203
Action Type: Other
Date: 09/14/1999
Action: Leak Reported

LEMON GROVE AUTO (Continued) **S102625814**

Global Id: T0607399203
Action Type: Other
Date: 09/14/1999
Action: Leak Stopped

Global Id: T0607399203
Action Type: Other
Date: 09/14/1999
Action: Leak Discovery

LUST:
Global Id: T0607399203
Status: Open - Case Begin Date
Status Date: 09/14/1999

Global Id: T0607399203
Status: Completed - Case Closed
Status Date: 09/20/2004

LUST REG 9:
Region: 9
Status: Preliminary site assessment workplan submitted
Case Number: 9UT3987
Local Case: H36873-001
Substance: Gasoline
Qty Leaked: 0
Abate Method: Remove Free Product - remove floating product from water table
Local Agency: San Diego
How Found: Tank Closure
How Stopped: Close Tank
Source: Tank
Cause: Corrosion
Lead Agency: Local Agency
Case Type: Soil only
Date Found: 09/24/1999
Date Stopped: 09/24/1999
Confirm Date: 09/14/1999
Submit Workplan: 10/5/99
Prelim Assess: / /
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 09/14/1999
Enforce Date: Not reported
Closed Date: Not reported
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 908.22
GW Depth: Not reported
Beneficial Use: No Beneficial groundwater use
NPDES Number: Not reported
Priority: 2A
File Dispn: Not reported
Interim Remedial Actions: Not reported

LEMON GROVE AUTO (Continued) **S102625814**

Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

SAN DIEGO CO. SAM:

Name:	LEMON GROVE AUTO
Address:	3465 CITRUS ST
City,State,Zip:	LEMON GROVE, CA 91945
Case Number:	H36873-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**LOP - Federal Fund**
Facility Type:	GW With No Beneficial Use Designation
Facility Status:	Closed Case
Date:	9/20/2004
Date Began:	9/14/1999

Name:	LEMON GROVE AUTO
Address:	3465 CITRUS ST
City,State,Zip:	LEMON GROVE, CA 91945
Case Number:	H36873-002
Agency:	DEH Site Assessment & Mitigation
Funding:	**XV**
Facility Type:	GW With No Beneficial Use Designation
Facility Status:	Post Remedial Monitoring
Date:	8/9/2004
Date Began:	Not reported

CPS-SLIC:

Name:	LEMON GROVE AUTO
Address:	3465 CITRUS ST
City,State,Zip:	LEMON GROVE, CA 91945
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	01/18/2018
Global Id:	T06019701630
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H36873-002
Latitude:	32.7433
Longitude:	-117.040663
Case Type:	Cleanup Program Site
Case Worker:	JC
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	The Department of Environmental Health (DEH), Site Assessment and Mitigation Program, reviewed the Voluntary Assistance Program (VAP) files related to the above-referenced case. VAP Case #H36873-002 was opened in August 2004, when an application was submitted to continue groundwater cleanup of contamination associated with Unauthorized Release Case H36873-001. On November 16, 2006, the RP no longer wanted to pursue further groundwater remediation on your property. In a letter dated January 25, 2007, DEH stated that VAP Case H36873-002 would remain open until the four abandoned groundwater monitoring wells were properly destroyed under DEH permit. To date, DEH has no record that the wells have been properly destroyed. DEH is hereby

LEMON GROVE AUTO (Continued) **S102625814**

administratively closing VAP Case #H36873-002 and referring the abandoned monitoring well issue to the DEH Monitoring Well Program.

Click here to access the California GeoTracker records for this facility:

HMMD SAN DIEGO:

Name:	GART WATKINS/E G WATKINS L T
Address:	3465 CITRUS ST
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	136873
Business Type:	Not reported
EPA Id Number:	Not reported
APN:	479-051-22-00
Last HMMD Inspection:	03/24/1999
Facility Telephone:	619-462-7950
Permit Status:	INAC
Permit Expiration:	Not reported
Date Last Updated:	11/02/2012
Facility Owner:	EUGENE G WATKINS LIVING TRUST
Facility Mailing Address:	3465 CITRUS ST
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945-
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 136873 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	136873
Tank Type:	UNKNOWN
Additional Id:	AT4503 UNKNOWN
Capacity Gallons:	2000
UST Contents:	Not reported
Other Content Info:	GASOLINE(TYPE UNKNOWN)
Reg Status:	REMOVED
Remove Close Date:	1999-09-27 00:00:00
Year Installed:	Not reported
Pipe Type:	UNKNOWN
Delivery System:	Not reported
Monitor Code:	Not reported
UST Monitor Method:	Not reported

UST Name:	UNDERGROUND TANK 136873 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	136873
Tank Type:	UNKNOWN
Additional Id:	AT4503 UNKNOWN
Capacity Gallons:	1000
UST Contents:	Not reported
Other Content Info:	GASOLINE(TYPE UNKNOWN)
Reg Status:	REMOVED

LEMON GROVE AUTO (Continued) **S102625814**

Remove Close Date: 1999-09-27 00:00:00
Year Installed: Not reported
Pipe Type: UNKNOWN
Delivery System: Not reported
Monitor Code: Not reported
UST Monitor Method: Not reported

UST Name: UNDERGROUND TANK 136873 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 136873
Tank Type: UNKNOWN
Additional Id: AT4503 UNKNOWN
Capacity Gallons: 1000
UST Contents: Not reported
Other Content Info: GASOLINE(TYPE UNKNOWN)
Reg Status: REMOVED
Remove Close Date: 1999-09-27 00:00:00
Year Installed: Not reported
Pipe Type: UNKNOWN
Delivery System: Not reported
Monitor Code: Not reported
UST Monitor Method: Not reported

Name: QUALITY MUFFLER, BRAKE & TUNE
Address: 3465 CITRUS ST
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 103539
Business Type: 6HK18
EPA Id Number: Not reported
APN: 479-051-22-00
Last HMMD Inspection: 01/02/2002
Facility Telephone: 619-469-2112
Permit Status: INAC
Permit Expiration: 05/31/2003
Date Last Updated: 11/02/2012
Facility Owner: HENRY CASTANEDA
Facility Mailing Address: 7319 BROADWAY
Facility Mailing City: LEMON GROVE
Facility Mailing State: CA
Facility Mailing Zip: 91945-
UST Owner: Not reported
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

CORTESE:
Name: LEMON GROVE AUTO
Address: 3465 CITRUS ST
City,State,Zip: LEMON GROVE, CA 91945
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607399203
Site/Facility Type: LUST CLEANUP SITE

LEMON GROVE AUTO (Continued) **S102625814**

Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

SAN DIEGO CO LOP:

Name:	LEMON GROVE AUTO
Address:	3465 CITRUS ST
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1999-LSAM-H36873-001
Record Status:	Completed
Opened Date:	09/14/1999
Parcel Number:	479-051-22-00
Case Type:	LOP - Local Oversight Program
Historical Name:	LEMON GROVE AUTO
SWRCB Global ID:	T0607399203
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	09/14/1999
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7432702
Longitude:	-117.0402851
X MapCoord:	6318663.182
Y MapCoord:	1851140.649

CERS:

Name:	LEMON GROVE AUTO
Address:	3465 CITRUS ST
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	197593
CERS ID:	T06019701630
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	JAMES CLAY - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego

LEMON GROVE AUTO (Continued) **S102625814**

Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: LEMON GROVE AUTO
Address: 3465 CITRUS ST
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 197593
CERS ID: T0607399203
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JAMES CLAY - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

I58 **LEMON GROVE U-RENT** **HIST UST** **U001571851**
South **7370 BROADWAY** **N/A**
1/8-1/4 **LEMON GROVE, CA 92045**
0.239 mi.
1260 ft. **Site 3 of 4 in cluster I**

Relative: HIST UST:
Lower Name: LEMON GROVE U-RENT
Actual: Address: 7370 BROADWAY
420 ft. City,State,Zip: LEMON GROVE, CA 92045
File Number: 0002b666
URL: https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002b666.pdf
Region: STATE
Facility ID: 00000067245
Facility Type: Other
Other Type: EQUIPMENT RENTAL
Contact Name: GREG SMITH
Telephone: 6194648806
Owner Name: LEMON GROVE U-RENT
Owner Address: 7370 BROADWAY
Owner City,St,Zip: LEMON GROVE, CA 92045
Total Tanks: 0001

Tank Num: 001
Container Num: 1
Year Installed: 1976
Tank Capacity: 00000550
Tank Used for: WASTE
Type of Fuel: 2
Container Construction Thickness: X
Leak Detection: Stock Inventor

LEMON GROVE U-RENT (Continued) **U001571851**

Click here for Geo Tracker PDF:

I59 **LEMON GROVE U RENT** **San Diego Co. HMMD** **S104747207**
South **7370 BROADWAY** **SWEEPS UST** **N/A**
1/8-1/4 **LEMON GROVE, CA 91945**
0.239 mi.
1260 ft. **Site 4 of 4 in cluster I**

Relative: **Lower**

Actual: **420 ft.**

HMMD SAN DIEGO:

Name:	LEMON GROVE U RENT
Address:	7370 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	112151
Business Type:	6HK18
EPA Id Number:	CAL000024040
APN:	479-052-12-00
Last HMMD Inspection:	04/30/1997
Facility Telephone:	619-464-8806
Permit Status:	INAC
Permit Expiration:	04/30/1997
Date Last Updated:	11/02/2012
Facility Owner:	GREG SMITH
Facility Mailing Address:	7370 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945-1512
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 112151 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	112151
Tank Type:	SINGLE WALL
Additional Id:	01
Capacity Gallons:	550
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1990-12-06 00:00:00
Year Installed:	Not reported
Pipe Type:	SINGLE WALL
Delivery System:	SUCTION
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

SWEEPS UST:

Name:	LEMON GROVE U RENT
Address:	7370 BROADWAY
City:	LEMON GROVE
Status:	Not reported

LEMON GROVE U RENT (Continued) **S104747207**

Comp Number:	12151
Number:	Not reported
Board Of Equalization:	44-022523
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012151-000001
Tank Status:	Not reported
Capacity:	550
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	1

Name:	LEMON GROVE U RENT
Address:	7370 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	12151
Number:	9
Board Of Equalization:	44-022523
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported
STG:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

K60 **ANGIES TOWING INC DBA QUALITY TOWING** **RCRA NonGen / NLR** **1027467076**
ESE **7620 NORTH AVE** **CAL000471384**
1/8-1/4 **LEMON GROVE, CA 91945**
0.242 mi.
1279 ft. **Site 1 of 3 in cluster K**

Relative: RCRA Listings:
Lower

Date Form Received by Agency:	20220616
Handler Name:	ANGIES TOWING INC DBA QUALITY TOWING
Handler Address:	7620 NORTH AVE
Handler City,State,Zip:	LEMON GROVE, CA 91945
EPA ID:	CAL000471384
Contact Name:	KEVIN DINHA
Contact Address:	7620 NORTH AVE
Contact City,State,Zip:	LEMON GROVE, CA 91945
Contact Telephone:	619-922-0276
Contact Fax:	619-460-8444
Contact Email:	KEVIN@QAULITYTOWING.NET
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified

Actual:
456 ft.

ANGIES TOWING INC DBA QUALITY TOWING (Continued) **1027467076**

Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		8280 BROADWAY
Mailing City,State,Zip:		LEMON GROVE, CA 91945
Owner Name:	ANGIES TOWING INC	
Owner Type:		Other
Operator Name:	KEVIN DINHA	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No

ANGIES TOWING INC DBA QUALITY TOWING (Continued) **1027467076**

Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20220620
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: KEVIN DINHA
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 7620 NORTH AVE
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945
Owner/Operator Telephone: 619-922-0276
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ANGIES TOWING INC
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 8280 BROADWAY
Owner/Operator City,State,Zip: LEMON GROVE, CA 91945
Owner/Operator Telephone: 619-212-1508
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20220616
Handler Name: ANGIES TOWING INC DBA QUALITY TOWING
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 811198
NAICS Description: ALL OTHER AUTOMOTIVE REPAIR AND MAINTENANCE

ANGIES TOWING INC DBA QUALITY TOWING (Continued) **1027467076**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

K61 **CHARLIES AUTO BRAKE AND WHEEL ALLIGNMENT** **RCRA-SQG** **1000596972**
ESE **7620 N AVE** **FINDS** **CAD983609652**
1/8-1/4 **LEMON GROVE, CA 91945** **ECHO**
0.242 mi.
1279 ft. **Site 2 of 3 in cluster K**

Relative:
Lower

Actual:
456 ft.

RCRA Listings:

Date Form Received by Agency:	19911028
Handler Name:	CHARLIES AUTO BRAKE AND WHEEL ALLIGNMENT
Handler Address:	7620 N AVE
Handler City,State,Zip:	LEMON GROVE, CA 91945
EPA ID:	CAD983609652
Contact Name:	CHUCK CARVAJAL
Contact Address:	7620 N AVE
Contact City,State,Zip:	LEMON GROVE, CA 91945
Contact Telephone:	619-460-4682
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	09
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	7620 N AVE
Mailing City,State,Zip:	LEMON GROVE, CA 91945
Owner Name:	CARVAJAL CHUCK
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported

CHARLIES AUTO BRAKE AND WHEEL ALLIGNMENT (Continued) **1000596972**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20020627
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CARVAJAL CHUCK	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7620 N AVE
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945
Owner/Operator Telephone:	619-460-4682
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19911028

CHARLIES AUTO BRAKE AND WHEEL ALLIGNMENT (Continued) **1000596972**

Handler Name: CHARLIES AUTO BRAKE AND WHEEL ALLIGNMENT
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811118
NAICS Description: OTHER AUTOMOTIVE MECHANICAL AND ELECTRICAL REPAIR AND MAINTENANCE

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110002863571

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000596972
Registry ID: 110002863571
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110002863571
Name: CHARLIES AUTO BRAKE AND WHEEL ALLIGNMENT
Address: 7620 N AVE
City,State,Zip: LEMON GROVE, CA 91945

K62 **BONK'S GENERAL AUTOMOTIVE REPAIR** **RCRA NonGen / NLR** **1025865820**
ESE **7620 NORTH AVE** **CAL000081770**
1/8-1/4 **LEMON GROVE, CA 91945**
0.242 mi.
1279 ft. **Site 3 of 3 in cluster K**

Relative: **Lower**

Actual: **456 ft.**

RCRA Listings:

Date Form Received by Agency:		19921221
Handler Name:	BONK'S GENERAL AUTOMOTIVE REPAIR	
Handler Address:		7620 NORTH AVE
Handler City,State,Zip:		LEMON GROVE, CA 91945-0000
EPA ID:		CAL000081770
Contact Name:		JOSEPH BONK
Contact Address:		7620 NORTH AVE
Contact City,State,Zip:		LEMON GROVE, CA 91945-0000
Contact Telephone:		619-697-1233
Contact Fax:		000-000-0000
Contact Email:		BONKSAUTO@AOL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		7620 NORTH AVE
Mailing City,State,Zip:		LEMON GROVE, CA 91945-1628
Owner Name:	JOSEPH BONK	
Owner Type:		Other
Operator Name:	JOSEPH BONK	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		Yes
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

BONK'S GENERAL AUTOMOTIVE REPAIR (Continued) **1025865820**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20190627
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOSEPH BONK	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7620 NORTH AVE
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945-1628
Owner/Operator Telephone:	619-697-1233
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOSEPH BONK	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	7620 NORTH AVE
Owner/Operator City,State,Zip:	LEMON GROVE, CA 91945-0000
Owner/Operator Telephone:	619-697-1233
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

BONK'S GENERAL AUTOMOTIVE REPAIR (Continued) **1025865820**

Historic Generators:
- Receive Date: 19921221
- Handler Name: BONK'S GENERAL AUTOMOTIVE REPAIR
- Federal Waste Generator Description: Not a generator, verified
- State District Owner: Not reported
- Large Quantity Handler of Universal Waste: No
- Recognized Trader Importer: Not reported
- Recognized Trader Exporter: Not reported
- Spent Lead Acid Battery Importer: Not reported
- Spent Lead Acid Battery Exporter: Not reported
- Current Record: Yes
- Non Storage Recycler Activity: Not reported
- Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
- NAICS Code: 56299
- NAICS Description: ALL OTHER WASTE MANAGEMENT SERVICES

Facility Has Received Notices of Violations:
- Violations: No Violations Found

Evaluation Action Summary:
- Evaluations: No Evaluations Found

L63 **CENTRE CITY SHELL 2** **SWEEPS UST U001571797**
West **3810 MASSACHUSETTS AVE** **HIST UST N/A**
1/8-1/4 **LA MESA, CA 92041**
0.250 mi.
1319 ft. **Site 1 of 7 in cluster L**

Relative: **Lower**

Actual: **458 ft.**

SWEEPS UST:
- Name: CENTRE CITY SHELL #2
- Address: 3810 MASSACHUSETTS AVE
- City: LA MESA
- Status: Not reported
- Comp Number: 12440
- Number: Not reported
- Board Of Equalization: 44-000074
- Referral Date: Not reported
- Action Date: Not reported
- Created Date: Not reported
- Owner Tank Id: Not reported
- SWRCB Tank Id: 37-000-012440-000004
- Tank Status: Not reported
- Capacity: 550
- Active Date: Not reported
- Tank Use: PETROLEUM
- STG: WASTE
- Content: Not reported
- Number Of Tanks: 1

- Name: CENTRE CITY SHELL #2
- Address: 3810 MASSACHUSETTS AVE
- City: LA MESA
- Status: Active

CENTRE CITY SHELL 2 (Continued) **U001571797**

Comp Number: 12440
Number: 9
Board Of Equalization: 44-000074
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012440-000001
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 4

Name: CENTRE CITY SHELL #2
Address: 3810 MASSACHUSETTS AVE
City: LA MESA
Status: Active
Comp Number: 12440
Number: 9
Board Of Equalization: 44-000074
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012440-000002
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: CENTRE CITY SHELL #2
Address: 3810 MASSACHUSETTS AVE
City: LA MESA
Status: Active
Comp Number: 12440
Number: 9
Board Of Equalization: 44-000074
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012440-000003
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: CENTRE CITY SHELL #2

CENTRE CITY SHELL 2 (Continued) **U001571797**

Address:	3810 MASSACHUSETTS AVE
City:	LA MESA
Status:	Active
Comp Number:	12440
Number:	9
Board Of Equalization:	44-000074
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012440-000005
Tank Status:	A
Capacity:	550
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	W
Content:	Not reported
Number Of Tanks:	Not reported

HIST UST:

Name:	CENTRE CITY SHELL 2
Address:	3810 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 92041
File Number:	0002f2da
URL:	https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002f2da.pdf
Region:	STATE
Facility ID:	00000056628
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	BRYCE V. GHARRING
Telephone:	6194609194
Owner Name:	SHELL OIL CO
Owner Address:	511 NORTH BROOKHURST
Owner City,St,Zip:	ANAHEIM, CA 92803
Total Tanks:	0003
Tank Num:	001
Container Num:	1
Year Installed:	1981
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Vapor Sniff Well
Tank Num:	002
Container Num:	2
Year Installed:	1981
Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Vapor Sniff Well
Tank Num:	003
Container Num:	3
Year Installed:	1981

CENTRE CITY SHELL 2 (Continued) **U001571797**

Tank Capacity:	00010000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	Vapor Sniff Well

Click here for Geo Tracker PDF:

L64 **SHELL** **San Diego Co. HMMD** **S104747331**
West **3810 MASSACHUSETTS AV** **CERS HAZ WASTE** **N/A**
1/8-1/4 **LA MESA, CA 91941** **CERS TANKS**
0.250 mi. **EMI**
1319 ft. **Site 2 of 7 in cluster L** **CERS**

Relative:
Lower

Actual:
458 ft.

HMMD SAN DIEGO:

Name:	CENTER CITY SHELL
Address:	3810 MASSACHUSETTS AVE
City,State,Zip:	LA MESA, CA 91941
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAL000335218
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-460-9194
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	08/06/2022
Facility Owner:	Not reported
Facility Mailing Address:	3810 MASSACHUSETTS AV, LA MESA, CA 91941
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	Y
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5238043
Return To Compliance Date:	2016-02-10T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	0
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2016-01-08T15:23:00.000
Violation Code:	2030043 (RD) Failure of the leak detection equipment to be properly programmed or properly operated. 23 CCR 2632, 2634, 2636, 2666

SHELL (Continued) **S104747331**

Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6849592
Return To Compliance Date:	2022-01-25T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	31686
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2022-01-25T00:00:00.000
Violation Code:	2030048 (TCR 9d) Failure to conduct secondary containment testing, or one or more of the following requirements: Perform the test of the secondary containment system upon installation, within six months of installation, and every 36 months thereafter. Perform the test of a secondary containment component within 30 days of a repair or discontinuing vacuum, pressure or hydrostatic monitoring. Use a procedure that demonstrates the system works as well as at installation. Use applicable manufacturer guidelines, industry codes, engineering standard, or professional engineer approval. Performed by a certified service technician. Maintain records of secondary containment testing for 36 months. 23 CCR 2637(a-d), 2712(b)(1)(F)

Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6388908
Return To Compliance Date:	2020-03-01T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2020-01-29T00:00:00.000
Violation Code:	1010005 Site map not submitted in CERS or not sufficient. HSC 25505(a)(2); 25508.1(f); 19 CCR 2652(a)(3)

Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6056662
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2019-01-08T00:00:00.000

SHELL (Continued) **S104747331**

Violation Code:	2030074 Failure to submit the "Monitoring System Certification Form" to the CUPA within 30 days of completion of the test. 23 CCR 2638(c-d)
Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6056662
Return To Compliance Date:	2019-01-09T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	2013-348-1
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2019-01-08T00:00:00.000
Violation Code:	2030065 (RD) Failure to maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring. HSC 25290.1(e); 23 CCR 2630(d)
Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6388908
Return To Compliance Date:	2020-03-01T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	31686
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2020-01-29T00:00:00.000
Violation Code:	2030013 (TCR 12) Failure to comply with one or more of the following designated operator (DO) monthly inspection requirements: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR, 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days. 23CCR 2716 (a-e)
Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed

SHELL (Continued) **S104747331**

Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5126715
Return To Compliance Date:	2015-01-14T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	31687
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2015-01-14T00:00:00.000
Violation Code:	2030043 Failure of the leak detection equipment to be properly programmed or properly operated. 23 CCR 16 2632, 2634, 2636, 2666

Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Routine
Inspection Number:	6388908
Return To Compliance Date:	2020-03-01T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2020-01-29T00:00:00.000
Violation Code:	1010008 HMBP not certified annually as complete and accurate in CERS. HSC 25508(a)(1)(A), 25508.2, 19 CCR 2654(b)

Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6056662
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-06T00:00:00.000
Inspection Date:	2019-01-08T00:00:00.000
Violation Code:	2010012 Failure to maintain UST records in sufficient detail to enable the CUPA to determine whether the UST systems are in compliance. HSC 25293

Record ID:	DEH2007-HUPFP-208832
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-208832
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5126715

SHELL (Continued) **S104747331**

Return To Compliance Date: 2016-02-08T00:00:00.000
Nov: No
Violation Classification: Not reported
Underground Storage Tank Id: 20133481
Container/Tank Id: Not reported
Last Update: 2022-08-06T00:00:00.000
Inspection Date: 2015-01-14T00:00:00.000
Violation Code: 2030026 Failure of line leak detector to detect a leak and/or failure of audible and visual alarm. 23 CCR 16 2636(f)(2), 2666.

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-208832
Program Element: Underground Storage Tank
Inspection Type: Routine
Inspection Number: 6056662
Return To Compliance Date: 2019-01-09T00:00:00.000
Nov: No
Violation Classification: Not reported
Underground Storage Tank Id: 2013-348-1
Container/Tank Id: Not reported
Last Update: 2022-08-06T00:00:00.000
Inspection Date: 2019-01-08T00:00:00.000
Violation Code: 2030015 Failure to demonstrate to the CUPA that the equipment and methods used to monitor the UST system are certified by an independent third-party as complying with the standards set forth in 23 CCR 2643(f). 23 CCR 16 2630(d), 2643(f), 2644.1(a)(2)

UST DTL:
Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-208832
Facility Type (Ust Facility): Motor Vehicle Fueling
Tank Owner Name: TEXAS STREET SHELL SERVICES, INC
Tankid: 2013-348-1
Tank Status: SEE FILE
Date Ust Permanently Closed: Not reported
Tank Use: 1a
Piping System Type: Pressure
Last Updated: 2022-08-06T02:31:48.000
Tank Capacityin Gallons: 10000
Tank Contents: E85
Type Of Tank: Double Wall

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-208832
Facility Type (Ust Facility): Motor Vehicle Fueling
Tank Owner Name: TEXAS STREET SHELL SERVICES, INC
Tankid: 2013-348-2
Tank Status: Active
Date Ust Permanently Closed: Not reported
Tank Use: 1a
Piping System Type: Pressure

SHELL (Continued) **S104747331**

Last Updated: 2022-08-06T02:31:48.000
Tank Capacityin Gallons: 5000
Tank Contents: Diesel
Type Of Tank: Double Wall

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-208832
Facility Type (Ust Facility): Motor Vehicle Fueling
Tank Owner Name: TEXAS STREET SHELL SERVICES, INC
Tankid: 31686
Tank Status: Active
Date Ust Permanently Closed: Not reported
Tank Use: 1a
Piping System Type: Pressure
Last Updated: 2022-08-06T02:31:48.000
Tank Capacityin Gallons: 20000
Tank Contents: Regular Unleaded
Type Of Tank: Double Wall

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-208832
Facility Type (Ust Facility): Motor Vehicle Fueling
Tank Owner Name: TEXAS STREET SHELL SERVICES, INC
Tankid: 31687
Tank Status: Active
Date Ust Permanently Closed: Not reported
Tank Use: 1a
Piping System Type: Pressure
Last Updated: 2022-08-06T02:31:48.000
Tank Capacityin Gallons: 12000
Tank Contents: Premium Unleaded
Type Of Tank: Double Wall

Waste and Materials:
Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0244519
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0244520
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: Propane

SHELL (Continued) **S104747331**

Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0244521
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0244522
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: Ethanol 70%
Common Name: Ethanol
Case Number: 64-17-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0244523
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 86290-81-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0244524
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: Motor Oil
Common Name: Motor Oil
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0215373
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Common Name: New and Waste Antifreeze
Case Number: Not reported

SHELL (Continued) **S104747331**

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0215374
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: PARTS WASHER
Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0215375
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: Lubricating oils, used
Common Name: Used lubricating oils
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0215376
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-01-30T06:14:00.000
Chemical Name: Waste Oil Absorbent
Common Name: Waste Oil Absorbent
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0318363
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: Ethanol 70%
Common Name: Ethanol
Case Number: 64-17-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0285318
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Common Name: New and Waste Antifreeze
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed

SHELL (Continued) **S104747331**

Active Permit: Y
Child Record Id: DEH2022-HWAST-0285319
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: PARTS WASHER
Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0285320
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: Waste Oil Absorbent
Common Name: Waste Oil Absorbent
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0285321
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: Lubricating oils, used
Common Name: Used lubricating oils
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130105
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T11:47:48.000
Chemical Name: Ethanol 70%
Common Name: Ethanol
Case Number: 64-17-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0312269
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-11-10T00:56:07.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0312270

SHELL (Continued) **S104747331**

Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-11-10T00:56:07.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0312271
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-11-10T00:56:07.000
Chemical Name: Motor Oil
Common Name: Motor Oil
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0312272
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-11-10T00:56:07.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0312273
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-11-10T00:56:07.000
Chemical Name: Ethanol 70%
Common Name: Ethanol
Case Number: 64-17-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0279966
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-11-10T00:56:07.000
Chemical Name: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Common Name: New and Waste Antifreeze
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0279967
Trade Secret: N
Hazardous Material Type: Not reported

SHELL (Continued) **S104747331**

Last Updated: 2021-11-10T00:56:07.000
Chemical Name: PARTS WASHER
Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0279968
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-11-10T00:56:07.000
Chemical Name: Waste Oil Absorbent
Common Name: Waste Oil Absorbent
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0287337
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: Ethanol 70%
Common Name: Ethanol
Case Number: 64-17-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0287338
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 86290-81-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0256187
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Common Name: New and Waste Antifreeze
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0256188
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: PARTS WASHER

SHELL (Continued) **S104747331**

Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0256189
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: Waste Oil Absorbent
Common Name: Waste Oil Absorbent
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0256190
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: Lubricating oils, used
Common Name: Used lubricating oils
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130102
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T11:47:48.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130103
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T11:47:48.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130104
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T11:47:48.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

SHELL (Continued) **S104747331**

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0130106
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2018-10-25T11:47:48.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 86290-81-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0108532
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T11:47:48.000
Chemical Name: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Common Name: ENGINE COOLANT
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0108533
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T11:47:48.000
Chemical Name: PARTS WASHER
Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0108534
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T11:47:48.000
Chemical Name: Lubricating oils, used
Common Name: Used lubricating oils
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0204032
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-08-16T02:33:15.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed

SHELL (Continued) **S104747331**

Active Permit: Y
Child Record Id: DEH2019-HCHEM-0204033
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-08-16T02:33:15.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0204034
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-08-16T02:33:15.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0204035
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-08-16T02:33:15.000
Chemical Name: Ethanol 70%
Common Name: Ethanol
Case Number: 64-17-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0204036
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2019-08-16T02:33:15.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 86290-81-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0176039
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-08-16T02:33:15.000
Chemical Name: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Common Name: ENGINE COOLANT
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0176040

SHELL (Continued) **S104747331**

Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-08-16T02:33:15.000
Chemical Name: PARTS WASHER
Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0176041
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-08-16T02:33:15.000
Chemical Name: Lubricating oils, used
Common Name: Used lubricating oils
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0249744
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 86290-81-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0249745
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: Ethanol 70%
Common Name: Ethanol
Case Number: 64-17-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0249746
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0249747
Trade Secret: N
Hazardous Material Type: Mixture

SHELL (Continued) **S104747331**

Last Updated: 2020-12-29T02:31:15.000
Chemical Name: Motor Oil
Common Name: Motor Oil
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0249748
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0249749
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220882
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: Lubricating oils, used
Common Name: Used lubricating oils
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220883
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: Waste Oil Absorbent
Common Name: Waste Oil Absorbent
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220884
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: PARTS WASHER

SHELL (Continued) **S104747331**

Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220885
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-12-29T02:31:15.000
Chemical Name: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Common Name: New and Waste Antifreeze
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0279969
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-11-10T00:56:07.000
Chemical Name: Lubricating oils, used
Common Name: Used lubricating oils
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0318359
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0318360
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0318361
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: Motor Oil
Common Name: Motor Oil
Case Number: Not reported

SHELL (Continued) **S104747331**

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0287333
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0287335
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: Motor Oil
Common Name: Motor Oil
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0287336
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0287334
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-08-10T02:39:51.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0284335
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 8006-61-9

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed

SHELL (Continued) **S104747331**

Active Permit: Y
Child Record Id: DEH2021-HCHEM-0284336
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: Propane
Common Name: Liquefied Petroleum Gas (lpg)
Case Number: 74-98-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0284337
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: Motor Oil
Common Name: Motor Oil
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0284338
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0284339
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: Ethanol 70%
Common Name: Ethanol
Case Number: 64-17-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0284340
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: Gasoline
Common Name: Gasoline
Case Number: 86290-81-5

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0252824

SHELL (Continued) **S104747331**

Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Common Name: New and Waste Antifreeze
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0252825
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: PARTS WASHER
Common Name: PARTS WASHER
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0252826
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: Waste Oil Absorbent
Common Name: Waste Oil Absorbent
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0252827
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-01-21T01:53:15.000
Chemical Name: Lubricating oils, used
Common Name: Used lubricating oils
Case Number: Not reported

Record ID: DEH2007-HUPFP-208832
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0318362
Trade Secret: N
Hazardous Material Type: Pure
Last Updated: 2022-08-06T02:31:48.000
Chemical Name: Diesel Fuel No. 2
Common Name: Diesel Fuel No. 2
Case Number: 68476-34-6

Name: CENTER CITY SHELL
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Permit Number: 208832
Business Type: 6HK29

SHELL (Continued) **S104747331**

EPA Id Number: CAL000335218
APN: 474-470-10-00
Last HMMD Inspection: 11/10/2011
Facility Telephone: 619-460-9194
Permit Status: OPEN
Permit Expiration: 09/30/2013
Date Last Updated: 11/02/2012
Facility Owner: TEXAS STREET SHELL SERVICES, INC
Facility Mailing Address: 3810 MASSACHUSETTS AV
Facility Mailing City: LA MESA
Facility Mailing State: CA
Facility Mailing Zip: 91941
UST Owner: PBNB LLC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 208832
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 112440 T007
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 74-98-6
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 112440 T006
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832

SHELL (Continued) **S104747331**

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL & GAS FILTER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 208832
Update Date: 11/02/2012
Inspection Date: 11/24/2010
Violation Code: 6HV3115
Violation: NO 2NDARY CONTAINMT. TEST/REPAIRS
Violation Citation: Secondary containment testing not completed (passed) for all components &/or repairs to secondary containment components not completed. 25284.1, 25291(a)(2); 2637
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 112440 T006
Last Update: 2012-11-02 14:17:38
Permit Number: 208832
Tank Type: DOUBLE WALL
Additional Id: NT2359, RT3407, RT4630
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-06-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 112440 T007

SHELL (Continued) **S104747331**

Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407, RT4630
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 208832 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	SINGLE WALL
Additional Id:	AT5414
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2009-06-10 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

Name:	CENTER CITY SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	208832
Business Type:	6HK29
EPA Id Number:	CAL000335218
APN:	474-470-10-00
Last HMMD Inspection:	11/10/2011
Facility Telephone:	619-460-9194
Permit Status:	OPEN
Permit Expiration:	09/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	TEXAS STREET SHELL SERVICES, INC
Facility Mailing Address:	3810 MASSACHUSETTS AV
Facility Mailing City:	LA MESA
Facility Mailing State:	CA
Facility Mailing Zip:	91941
UST Owner:	PBNB LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported

SHELL (Continued) **S104747331**

Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 112440 T007
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 74-98-6
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 112440 T006
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832

SHELL (Continued) **S104747331**

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL & GAS FILTER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 208832
Update Date: 11/02/2012
Inspection Date: 11/24/2010
Violation Code: 6HV3115
Violation: NO 2NDARY CONTAINMT. TEST/REPAIRS
Violation Citation: Secondary containment testing not completed (passed) for all components &/or repairs to secondary containment components not completed. 25284.1, 25291(a)(2); 2637
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 112440 T006
Last Update: 2012-11-02 14:17:38
Permit Number: 208832
Tank Type: DOUBLE WALL
Additional Id: NT2359, RT3407, RT4630
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-06-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 112440 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 208832
Tank Type: DOUBLE WALL
Additional Id: NT2359, RT3407, RT4630
Capacity Gallons: 12000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2003-06-05 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 208832 T008
Last Update: 2012-11-02 14:17:38

SHELL (Continued) **S104747331**

Permit Number:	208832
Tank Type:	SINGLE WALL
Additional Id:	AT5414
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2009-06-10 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

Name:	CENTER CITY SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	208832
Business Type:	6HK29
EPA Id Number:	CAL000335218
APN:	474-470-10-00
Last HMMD Inspection:	11/10/2011
Facility Telephone:	619-460-9194
Permit Status:	OPEN
Permit Expiration:	09/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	TEXAS STREET SHELL SERVICES, INC
Facility Mailing Address:	3810 MASSACHUSETTS AV
Facility Mailing City:	LA MESA
Facility Mailing State:	CA
Facility Mailing Zip:	91941
UST Owner:	PBNB LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	208832
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUND TANK 112440 T007
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	208832
Update Date:	11/02/2012
Case Number:	74-98-6
Name:	PROPANE
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE

SHELL (Continued) **S104747331**

Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 112440 T006
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL & GAS FILTER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 208832
Update Date: 11/02/2012
Inspection Date: 11/24/2010
Violation Code: 6HV3115
Violation: NO 2NDARY CONTAINMT. TEST/REPAIRS
Violation Citation: Secondary containment testing not completed (passed) for all components &/or repairs to secondary containment components not completed. 25284.1, 25291(a)(2); 2637
Activity: ACTIVE

SHELL (Continued) **S104747331**

UST:

UST Name:	UNDERGROUND TANK 112440 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407, RT4630
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112440 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407, RT4630
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 208832 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	SINGLE WALL
Additional Id:	AT5414
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2009-06-10 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

Name:	CENTER CITY SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	112440

SHELL (Continued) **S104747331**

Business Type:	6HK29
EPA Id Number:	CAD982043168
APN:	474-470-10-00
Last HMMD Inspection:	08/07/2007
Facility Telephone:	619-460-9194
Permit Status:	CHNG
Permit Expiration:	12/31/2008
Date Last Updated:	11/02/2012
Facility Owner:	SHELL OIL COMPANY
Facility Mailing Address:	20945 S. WILMINGTON AVE
Facility Mailing City:	CARSON
Facility Mailing State:	CA
Facility Mailing Zip:	90810
UST Owner:	EQUILON ENTERPRISES LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 112440 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112440 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112440 T001
Last Update:	2012-11-02 14:17:38

SHELL (Continued) **S104747331**

Permit Number:	112440
Tank Type:	SINGLE WALL
Additional Id:	1/NT2359
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2003-05-22 00:00:00
Year Installed:	1981-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	13
UST Monitor Method:	SW TANK W/ CERT ATG SW PRESSURE PIPE W/ SHUTOFF LLD + CERT ATG: IN-TANK TEST MONTHLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 112440 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	SINGLE WALL
Additional Id:	2/NT2359
Capacity Gallons:	10000
UST Contents:	MIDGRADE UNLEADED
Other Content Info:	PLUS UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2003-05-22 00:00:00
Year Installed:	1981-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	13
UST Monitor Method:	SW TANK W/ CERT ATG SW PRESSURE PIPE W/ SHUTOFF LLD + CERT ATG: IN-TANK TEST MONTHLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 112440 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	SINGLE WALL
Additional Id:	3/NT2359
Capacity Gallons:	10000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	SUPER UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2003-05-22 00:00:00
Year Installed:	1981-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	13
UST Monitor Method:	SW TANK W/ CERT ATG SW PRESSURE PIPE W/ SHUTOFF LLD + CERT ATG: IN-TANK TEST MONTHLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 112440 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	SINGLE WALL
Additional Id:	NT0252
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL

SHELL (Continued) **S104747331**

Reg Status:	REMOVED
Remove Close Date:	1987-01-12 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.
UST Name:	UNDERGROUND TANK 112440 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	DOUBLE WALL
Additional Id:	4/AT5151
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2005-04-04 00:00:00
Year Installed:	1985-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	GRAVITY
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.
Name:	CENTER CITY SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	208832
Business Type:	6HK29
EPA Id Number:	CAL000335218
APN:	474-470-10-00
Last HMMD Inspection:	11/10/2011
Facility Telephone:	619-460-9194
Permit Status:	OPEN
Permit Expiration:	09/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	TEXAS STREET SHELL SERVICES, INC
Facility Mailing Address:	3810 MASSACHUSETTS AV
Facility Mailing City:	LA MESA
Facility Mailing State:	CA
Facility Mailing Zip:	91941
UST Owner:	PBNB LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	208832
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUND TANK 112440 T007

SHELL (Continued) **S104747331**

Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 74-98-6
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 112440 T006
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL & GAS FILTER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

SHELL (Continued) **S104747331**

Violations Active Permits:

Permit Number:	208832
Update Date:	11/02/2012
Inspection Date:	11/24/2010
Violation Code:	6HV3115
Violation:	NO 2NDARY CONTAINMT. TEST/REPAIRS
Violation Citation:	Secondary containment testing not completed (passed) for all components &/or repairs to secondary containment components not completed. 25284.1, 25291(a)(2); 2637
Activity:	ACTIVE

UST:

UST Name:	UNDERGROUND TANK 112440 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407, RT4630
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112440 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407, RT4630
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 208832 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	SINGLE WALL
Additional Id:	AT5414
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2009-06-10 00:00:00

SHELL (Continued) **S104747331**

Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

Name: CENTER CITY SHELL
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Permit Number: 208832
Business Type: 6HK29
EPA Id Number: CAL000335218
APN: 474-470-10-00
Last HMMD Inspection: 11/10/2011
Facility Telephone: 619-460-9194
Permit Status: OPEN
Permit Expiration: 09/30/2013
Date Last Updated: 11/02/2012
Facility Owner: TEXAS STREET SHELL SERVICES, INC
Facility Mailing Address: 3810 MASSACHUSETTS AV
Facility Mailing City: LA MESA
Facility Mailing State: CA
Facility Mailing Zip: 91941
UST Owner: PBNB LLC
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 208832
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 112440 T007
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 74-98-6
Name: PROPANE
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 208832
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 112440 T006
Material Waste: Material

SHELL (Continued) **S104747331**

Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 135 UNSPECIFIED AQUEOUS SOL'N
Other Information: PARTS WASHER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 343 UNSPEC ORGANIC LIQUID MIXTURE
Other Information: USED ANTIFREEZE/GLYCOLS & 1 NEW AF
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 208832
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL & GAS FILTER
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 208832
Update Date: 11/02/2012
Inspection Date: 11/24/2010
Violation Code: 6HV3115
Violation: NO 2NDARY CONTAINMT. TEST/REPAIRS
Violation Citation: Secondary containment testing not completed (passed) for all components &/or repairs to secondary containment components not completed. 25284.1, 25291(a)(2); 2637
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 112440 T006
Last Update: 2012-11-02 14:17:38
Permit Number: 208832
Tank Type: DOUBLE WALL
Additional Id: NT2359, RT3407, RT4630

SHELL (Continued) **S104747331**

Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112440 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407, RT4630
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 208832 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	208832
Tank Type:	SINGLE WALL
Additional Id:	AT5414
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2009-06-10 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

Name:	CENTER CITY SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Permit Number:	112440
Business Type:	6HK29
EPA Id Number:	CAD982043168
APN:	474-470-10-00
Last HMMD Inspection:	08/07/2007
Facility Telephone:	619-460-9194
Permit Status:	CHNG

SHELL (Continued) **S104747331**

Permit Expiration:	12/31/2008
Date Last Updated:	11/02/2012
Facility Owner:	SHELL OIL COMPANY
Facility Mailing Address:	20945 S. WILMINGTON AVE
Facility Mailing City:	CARSON
Facility Mailing State:	CA
Facility Mailing Zip:	90810
UST Owner:	EQUILON ENTERPRISES LLC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 112440 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112440 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	DOUBLE WALL
Additional Id:	NT2359, RT3407
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2003-06-05 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112440 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	SINGLE WALL
Additional Id:	1/NT2359
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED

SHELL (Continued) **S104747331**

Reg Status:	REMOVED
Remove Close Date:	2003-05-22 00:00:00
Year Installed:	1981-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	13
UST Monitor Method:	SW TANK W/ CERT ATG SW PRESSURE PIPE W/ SHUTOFF LLD + CERT ATG: IN-TANK TEST MONTHLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR
UST Name:	UNDERGROUND TANK 112440 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	SINGLE WALL
Additional Id:	2/NT2359
Capacity Gallons:	10000
UST Contents:	MIDGRADE UNLEADED
Other Content Info:	PLUS UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2003-05-22 00:00:00
Year Installed:	1981-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	13
UST Monitor Method:	SW TANK W/ CERT ATG SW PRESSURE PIPE W/ SHUTOFF LLD + CERT ATG: IN-TANK TEST MONTHLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR
UST Name:	UNDERGROUND TANK 112440 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	SINGLE WALL
Additional Id:	3/NT2359
Capacity Gallons:	10000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	SUPER UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2003-05-22 00:00:00
Year Installed:	1981-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	13
UST Monitor Method:	SW TANK W/ CERT ATG SW PRESSURE PIPE W/ SHUTOFF LLD + CERT ATG: IN-TANK TEST MONTHLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR
UST Name:	UNDERGROUND TANK 112440 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	112440
Tank Type:	SINGLE WALL
Additional Id:	NT0252
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1987-01-12 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90

SHELL (Continued) **S104747331**

UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name: UNDERGROUND TANK 112440 T005
Last Update: 2012-11-02 14:17:38
Permit Number: 112440
Tank Type: DOUBLE WALL
Additional Id: 4/AT5151
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 2005-04-04 00:00:00
Year Installed: 1985-01-01 00:00:00
Pipe Type: Not reported
Delivery System: GRAVITY
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

CERS HAZ WASTE:
Name: CENTER CITY SHELL
Address: 3810 MASSACHUSETTS AVE
City,State,Zip: LA MESA, CA 91941
Site ID: 389629
CERS ID: 10360594
CERS Description: Hazardous Waste Generator

CERS TANKS:
Name: CENTER CITY SHELL
Address: 3810 MASSACHUSETTS AVE
City,State,Zip: LA MESA, CA 91941
Site ID: 389629
CERS ID: 10360594
CERS Description: Underground Storage Tank

EMI:
Name: SHELL OIL / LA MESA
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Year: 1999
County Code: 37
Air Basin: SD
Facility ID: 1280
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2
Reactive Organic Gases Tons/Yr: 2
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0

SHELL (Continued) **S104747331**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Name:	SHELL OIL / LA MESA
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2000
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL OIL / LA MESA
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2001
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL OIL / LA MESA
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2002
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0

SHELL (Continued) **S104747331**

NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: SHELL OIL LA MESA
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Year: 2003
County Code: 37
Air Basin: SD
Facility ID: 1280
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2
Reactive Organic Gases Tons/Yr: 2
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: SHELL OIL LA MESA
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Year: 2004
County Code: 37
Air Basin: SD
Facility ID: 1280
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 1.7280158
Reactive Organic Gases Tons/Yr: 1.7280158
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: SHELL OIL LA MESA
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Year: 2005
County Code: 37
Air Basin: SD
Facility ID: 1280
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

SHELL (Continued) **S104747331**

Total Organic Hydrocarbon Gases Tons/Yr:	1.7280158
Reactive Organic Gases Tons/Yr:	1.7280158
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2006
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 94607
Year:	2007
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2008
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541

SHELL (Continued) **S104747331**

Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2009
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.9299999999999999
Reactive Organic Gases Tons/Yr:	1.9299999999999999
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2010
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.9299999999999999
Reactive Organic Gases Tons/Yr:	1.9299999999999999
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2011
County Code:	37
Air Basin:	SD

SHELL (Continued) **S104747331**

Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2012
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2013
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941

SHELL (Continued) **S104747331**

Year:	2014
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2015
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2016
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

SHELL (Continued) **S104747331**

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2017
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2018
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Year:	2019
County Code:	37
Air Basin:	SD
Facility ID:	1280
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.93
Reactive Organic Gases Tons/Yr:	1.93
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported

SHELL (Continued) **S104747331**

Particulate Matter Tons/Yr: Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr: Not reported

CERS:
Name: CENTER CITY SHELL
Address: 3810 MASSACHUSETTS AVE
City,State,Zip: LA MESA, CA 91941
Site ID: 389629
CERS ID: 10360594
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 389629
Site Name: CENTER CITY SHELL
Violation Date: 01-25-2022
Citation: 23 CCR 16 2712(b)(1)(F) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(F)
Violation Description: "Failure to conduct secondary containment testing, or one or more of the following requirements: Perform the test of the secondary containment system upon installation, within six months of installation and every 36 months thereafter. Perform the test of a secondary containment component within 30 days of a repair or discontinuing vacuum, pressure or hydrostatic monitoring. Use a procedure that demonstrates the system works as well as at installation. Use applicable manufacturer guidelines, industry codes, engineering standard, or professional engineer approval. Performed by a certified service technician. Maintain records of secondary containment testing for 36 months."
Violation Notes: Returned to compliance on 01/25/2022. Inspection Sequence ID:6849592;Tank ID:31686,31687;Violation Description:(TCR 9d) Failure to conduct secondary containment testing, or one or more of the following requirements: Perform the test of the secondary containment system upon installation, within six months of installation, and every 36 months thereafter. Perform the test of a secondary containment component within 30 days of a repair or discontinuing vacuum, pressure or hydrostatic monitoring. Use a procedure that demonstrates the system works as well as at installation. Use applicable manufacturer guidelines, industry codes, engineering standard, or professional engineer approval. Performed by a certified service technician. Maintain records of secondary containment testing for 36 months. 23 CCR 2637(a-d), 2712(b)(1)(F)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 389629
Site Name: CENTER CITY SHELL
Violation Date: 01-08-2019
Citation: HSC 6.7 25290.1(e)2 - California Health and Safety Code, Chapter 6.7, Section(s) 25290.1(e)2
Violation Description: Failure to maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring.
Violation Notes: Returned to compliance on 01/09/2019. Inspection Sequence ID:6056662;Tank ID:2013-348-1;Violation Description:(RD) Failure to

SHELL (Continued) **S104747331**

maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring. HSC 25290.1(e); 23 CCR 2630(d)

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 389629
Site Name: CENTER CITY SHELL
Violation Date: 01-29-2020
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes: Returned to compliance on 03/01/2020. Inspection Sequence ID:6388908
Violation Division: San Diego County Department of Env Health
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 389629
Site Name: CENTER CITY SHELL
Violation Date: 01-29-2020
Citation: 23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Description: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.
Violation Notes: Returned to compliance on 03/01/2020. Inspection Sequence ID:6388908;Tank ID:31686,31687,2013-348-1 ,2013-348-2;Violation Description:(TCR 12) Failure to comply with one or more of the following designated operator (DO) monthly inspection requirements: For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in

SHELL (Continued) **S104747331**

accordance with 23 CCR, 2715(c). For desi
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 389629
Site Name: CENTER CITY SHELL
Violation Date: 01-14-2015
Citation: 23 CCR 16 2632, 2634, 2636, 2666 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632, 2634, 2636, 2666
Violation Description: Failure of the leak detection equipment to be properly programmed or properly operated.
Violation Notes: Returned to compliance on 01/08/2016. Inspection Sequence ID:5126715;Tank ID:31687,31687,20133481,20133482;Violation Description:Failure of the leak detection equipment to be properly programmed or properly operated. 23 CCR 16 2632, 2634, 2636, 2666
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 389629
Site Name: CENTER CITY SHELL
Violation Date: 01-08-2019
Citation: 23 CCR 16 2644.1(a)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2644.1(a)(2)
Violation Description: Failure to demonstrate to the UPA that the equipment and methods used to monitor the UST system are certified by an independent third-party as complying with the standards set forth in 23 CCR 2643(f).
Violation Notes: Returned to compliance on 01/09/2019. Inspection Sequence ID:6056662;Tank ID:2013-348-1;Violation Description:Failure to demonstrate to the CUPA that the equipment and methods used to monitor the UST system are certified by an independent third-party as complying with the standards set forth in 23 CCR 2643(f). 23 CCR 16 2630(d), 2643(f), 2644.1(a)(2)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 389629
Site Name: CENTER CITY SHELL
Violation Date: 01-08-2019
Citation: 23 CCR 16 2638(d) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2638(d)
Violation Description: Failure to submit the Monitoring System Certification Form to the UPA within 30 days of completion of the test.
Violation Notes: Returned to compliance on 02/05/2019. Inspection Sequence ID:6056662;Tank ID:31686,31687,2013-348-1 ,2013-348-2;Violation Description:Failure to submit the "Monitoring System Certification Form" to the CUPA within 30 days of completion of the test. 23 CCR 2638(c-d)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 389629
Site Name: CENTER CITY SHELL
Violation Date: 01-08-2019

SHELL (Continued) **S104747331**

Citation:	HSC 6.7 25293 - California Health and Safety Code, Chapter 6.7, Section(s) 25293
Violation Description:	Failure to maintain UST records in sufficient detail to enable the UPA to determine whether the UST systems are in compliance.
Violation Notes:	Returned to compliance on 02/05/2019. Inspection Sequence ID:6056662;Tank ID:31686,31687,2013-348-1 ,2013-348-2;Violation Description:Failure to maintain UST records in sufficient detail to enable the CUPA to determine whether the UST systems are in compliance. HSC 25293
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	389629
Site Name:	CENTER CITY SHELL
Violation Date:	01-08-2016
Citation:	23 CCR 16 2632, 2634, 2636, 2666 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632, 2634, 2636, 2666
Violation Description:	Failure of the leak detection equipment to be properly programmed or properly operated.
Violation Notes:	Returned to compliance on 02/10/2016. Inspection Sequence ID:5238043;Tank ID:0,0;Violation Description:(RD) Failure of the leak detection equipment to be properly programmed or properly operated. 23 CCR 2632, 2634, 2636, 2666
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	389629
Site Name:	CENTER CITY SHELL
Violation Date:	01-14-2015
Citation:	23 CCR 16 2666(c) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2666(c)
Violation Description:	Failure of line leak detector to detect a leak and/or failure of audible and visual alarm.
Violation Notes:	Returned to compliance on 02/08/2016. Inspection Sequence ID:5126715;Tank ID:20133481;Violation Description:Failure of line leak detector to detect a leak and/or failure of audible and visual alarm. 23 CCR 16 2636(f)(2), 2666.
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	389629
Site Name:	CENTER CITY SHELL
Violation Date:	01-29-2020
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Returned to compliance on 03/01/2020. Inspection Sequence ID:6388908
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,

Evaluation:

Eval General Type:	Compliance Evaluation Inspection

SHELL (Continued) **S104747331**

Eval Date: 01-04-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5831602
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-04-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5831602
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-06-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5562935
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:6056662
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-27-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Khan Steven Inspection ID:4968782
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-29-2020
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6388908
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-08-2016
Violations Found: No
Eval Type: Routine done by local agency

SHELL (Continued) **S104747331**

Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5238043
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-08-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:6056662
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-14-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5126715
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-14-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5126715
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-25-2022
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6849592
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-27-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Khan Steven Inspection ID:4968782
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-29-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6388908
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP

SHELL (Continued) **S104747331**

Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-06-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5562935
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-04-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:5831602
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-06-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5562935
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-08-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5238043
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-08-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5238043
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Archer Veronica Inspection ID:6056662
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection

SHELL (Continued) **S104747331**

Eval Date: 01-14-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Garchitorena Bobby Inspection ID:5126715
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-20-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fernandez Juan Inspection ID:6589174
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-27-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Khan Steven Inspection ID:4968782
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-29-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6388908
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Coordinates:
Site ID: 389629
Facility Name: CENTER CITY SHELL
Env Int Type Code: HMBP
Program ID: 10360594
Coord Name: Not reported
Ref Point Type Desc: Unknown,
Latitude: 32.746640
Longitude: -117.043140

Affiliation:
Affiliation Type Desc: Operator
Entity Name: TEXAS STREET SHELL SERVICES, INC
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 460-9194,

SHELL (Continued) **S104747331**

Affiliation Type Desc:	Property Owner
Entity Name:	P B N B L L C
Entity Title:	Not reported
Affiliation Address:	3810 MASSACHUSETTS AVE
Affiliation City:	LA MESA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91941
Affiliation Phone:	(619) 460-9194,
Affiliation Type Desc:	UST Property Owner Name
Entity Name:	P B N B L L C
Entity Title:	Not reported
Affiliation Address:	3810 MASSACHUSETTS AVE
Affiliation City:	LA MESA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91941
Affiliation Phone:	(619) 460-9194,
Affiliation Type Desc:	UST Tank Owner
Entity Name:	TEXAS STREET SHELL SERVICES, INC
Entity Title:	Not reported
Affiliation Address:	3810 MASSACHUSETTS AV
Affiliation City:	LA MESA
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91941
Affiliation Phone:	(619) 460-9194,
Affiliation Type Desc:	Document Preparer
Entity Name:	Thomas Kirklen
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	3810 MASSACHUSETTS AVENUE
Affiliation City:	LA MESA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91941
Affiliation Phone:	,
Affiliation Type Desc:	Identification Signer
Entity Name:	Thomas Kirklen
Entity Title:	ASST. MANAGER
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported

SHELL (Continued) **S104747331**

Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Legal Owner
Entity Name: TEXAS STREET SHELL SERVICES, INC
Entity Title: Not reported
Affiliation Address: 3810 MASSACHUSETTS AVENUE
Affiliation City: LA MESA
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91941
Affiliation Phone: (619) 460-9194,

Affiliation Type Desc: UST Tank Operator
Entity Name: CENTER CITY SHELL
Entity Title: Not reported
Affiliation Address: 3818 MASSACHUSETTS AVENUE
Affiliation City: LA MESA
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 91941
Affiliation Phone: (619) 460-9194,

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Affiliation Type Desc: Environmental Contact
Entity Name: Tim Montijo
Entity Title: Not reported
Affiliation Address: PO BOX 1872
Affiliation City: Escondido
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92033
Affiliation Phone: ,

Affiliation Type Desc: Parent Corporation
Entity Name: CENTER CITY SHELL
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: UST Permit Applicant
Entity Name: ATTN: BILL CLARK
Entity Title: ASST MANAGER
Affiliation Address: Not reported

SHELL (Continued) **S104747331**

Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 460-9194,

Name: SHELL
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Site ID: 232022
CERS ID: T0607338887
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: SHELL OIL / LA MESA
Address: 3810 MASSACHUSETTS AVENUE
City,State,Zip: LA MESA, CA 91941-7640
Site ID: 493790
CERS ID: 110013858860
CERS Description: US EPA Air Emission Inventory System (EIS)

Affiliation:
Affiliation Type Desc: Environmental Contact
Entity Name: GARY V WING
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA SAN DIEGO CNTY LOP
Entity Title: Not reported
Affiliation Address: POBOX 129261
Affiliation City: SANDIEGO
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: SHELL
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941

SHELL (Continued) **S104747331**

Site ID: 232022
CERS ID: T06019780340
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

L65 **CENTER CITY SHELL** **UST** **U003789345**
West **3810 MASSACHUSETTS AVE** **N/A**
1/8-1/4 **LA MESA, CA 91941**
0.250 mi.
1319 ft. **Site 3 of 7 in cluster L**

Relative: **Lower**
Actual: **458 ft.**

UST:
Name: CENTER CITY SHELL
Address: 3810 MASSACHUSETTS AVE
City,State,Zip: LA MESA, CA 91941
Facility ID: 37-000-208832
Permitting Agency: San Diego County Department of Environmental Health
CERSID: 10360594
Latitude: 32.7413000
Longitude: -117.045000
Owner type: Not reported
Facility type: Not reported
Num of inuse ust: Not reported
Num of closed ust: Not reported
Num of oos ust: Not reported
Epa region: Not reported
Tribal lands: Not reported
Tank owner name: Not reported
Tank owner mailing address: Not reported
Tank owner mailing city: Not reported
Tank owner mailing zip: Not reported
Tank owner mailing state: Not reported
Tank operator name: Not reported
Tank operator mailing address: Not reported
Tank operator mailing city: Not reported
Tank operator mailing zip: Not reported
Tank operator mailing state: Not reported
Tankidnumber: Not reported
Tank status: Not reported
Tank configuration: Not reported
Tank closure date: Not reported
Tank installation date: Not reported
Tank num of compartments: Not reported
Tank contents: Not reported
Tank capacity gallons: Not reported
Tank type: Not reported
Tank pc construction: Not reported

CENTER CITY SHELL (Continued) **U003789345**

Tank pwpiping construction:	Not reported
Tank piping type:	Not reported
Tank piping construction:	Not reported
Tank sacrificial anode:	Not reported
Tank cp impressed current:	Not reported
Tank cp shutoff:	Not reported
Tank alarms:	Not reported
Tank ball float:	Not reported
Tank spill bucket:	Not reported

L66 **SHELL** **LUST** **S104582036**
West **3810 MASSACHUSETTS AV** **N/A**
1/8-1/4 **LA MESA, CA 91941**
0.250 mi.
1319 ft. **Site 4 of 7 in cluster L**

Relative:
Lower

Actual:
458 ft.

LUST:

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T06019780340
Global Id:	T06019780340
Latitude:	32.7504028667604
Longitude:	-117.043069749738
Status:	Completed - Case Closed
Status Date:	01/25/2010
Case Worker:	JS
RB Case Number:	Not reported
Local Agency:	SAN DIEGO COUNTY LOP
File Location:	Local Agency
Local Case Number:	H12440-002
Potential Media Affect:	Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	In May 2003, three gasoline USTs were removed and soil samples were collected and analyzed. Based on analytical results, case H12440-001 was opened. In April 2005, a 550-gallon waste oil UST was removed and soil samples were collected and anayzed. Based on analytical results, case H12440-002 was opened. In January 2010, DEH consolidated cased H12440-001 & H12440-002. Please refer to case H12440-001 for technical reports and correspondences for both cases.

LUST:

Global Id:	T06019780340
Contact Type:	Local Agency Caseworker
Contact Name:	JON SENAHA
Organization Name:	SAN DIEGO COUNTY LOP
Address:	P.O. Box 129261
City:	San Diego
Email:	jon.senaha@sdcounty.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T06019780340
Action Type:	ENFORCEMENT
Date:	07/09/2008
Action:	Technical Correspondence / Assistance / Other

SHELL (Continued) **S104582036**

Global Id: T06019780340
Action Type: Other
Date: 04/04/2005
Action: Leak Began

Global Id: T06019780340
Action Type: ENFORCEMENT
Date: 08/23/2006
Action: Notice of Responsibility

Global Id: T06019780340
Action Type: Other
Date: 07/21/2005
Action: Leak Reported

Global Id: T06019780340
Action Type: ENFORCEMENT
Date: 08/31/2009
Action: Letter - Notice

Global Id: T06019780340
Action Type: ENFORCEMENT
Date: 01/13/2010
Action: Closure/No Further Action Letter

Global Id: T06019780340
Action Type: ENFORCEMENT
Date: 07/14/2009
Action: Letter - Notice

Global Id: T06019780340
Action Type: Other
Date: 04/04/2005
Action: Leak Discovery

Global Id: T06019780340
Action Type: Other
Date: 04/04/2005
Action: Leak Stopped

LUST:
Global Id: T06019780340
Status: Open - Case Begin Date
Status Date: 04/04/2005

Global Id: T06019780340
Status: Open - Site Assessment
Status Date: 08/16/2005

Global Id: T06019780340
Status: Completed - Case Closed
Status Date: 01/25/2010

Name: SHELL
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941

SHELL (Continued) **S104582036**

Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607338887
Global Id:	T0607338887
Latitude:	32.7465156679727
Longitude:	-117.043141
Status:	Completed - Case Closed
Status Date:	10/08/2013
Case Worker:	JS
RB Case Number:	Not reported
Local Agency:	SAN DIEGO COUNTY LOP
File Location:	Local Agency
Local Case Number:	H12440-001
Potential Media Affect:	Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern:	Gasoline
Site History:	Comments: The Site is located at 3810 Massachusetts Avenue, at the northwest corner of the intersection of Massachusetts Avenue and Waite Drive in La Mesa, California. This Site is an operational Shell-branded Service Station. The Site has two underground storage tanks (USTs), four dispenser islands; two station buildings with multiple service bays, an above ground waste-oil tank, and an above ground propane tank. Residential housing is adjacent and west of the Site. Residential and commercial properties lie east and south of the Site across Massachusetts Avenue and Waite Drive. There is a residential apartment complex to the west of the Site and houses to the east across Massachusetts Avenue. Plum Health Care Center, a nursing home, is located across Waite Drive to the south. In May 2003, DEH personnel oversaw the removal and replacement of the USTs, dispensers, and associated product lines at the Site. Three 10,000-gallon USTs were removed and replaced with one 12,000-gallon and one 20,000-gallon double-walled fiberglass UST in the southern portion of the Site. The UST cavity was over-excavated to between 17.5 and 19 feet below grade and additional confirmation samples were collected. Based on the analytical results of soil sampling, DEH opened Unauthorized Release Case H12440-001. Subsequent assessment demonstrated that soil contamination from this release is limited. The sources of the majority of hydrocarbons in soil appear to be the former gasoline USTs, the former northeast dispenser island, and the former waste oil UST. Hydrocarbon and oxygenate concentrations in soils within the saturated zone south of the Site were generally low; however, TBA was detected at 6.0 mg/kg in MW-8 at 21.5 feet bg. This sample is located at the water table and is likely due to high concentrations of TBA in groundwater. The total residual petroleum hydrocarbon mass of TPH greater than 100 mg/kg in soil is estimated to be approximately 290 cubic yards. In March 2007, vapor probes VP-1 through VP-7 were installed and a soil vapor survey was conducted. The results of the soil vapor sampling concluded that there was no risk to occupants of the station building; however, additional soil vapor sampling was required to evaluate the risks to the residence to the west and the Plum Health Care Center to the south. In August 2009, soil vapor probes VP-8 through VP-13 were installed. Soil vapor probes VP-8 through VP-13 were installed off Site to evaluate soil vapor concentrations near Plum Health Care Center to the south. The potential risk from soil vapor intrusion to indoor air was evaluated and it was determined that it was below the DEH carcinogenic target level of 1 x 10-6. In August 2010, soil vapor probe VP-14 was installed to evaluate soil vapor concentrations near the adjacent

SHELL (Continued) **S104582036**

apartment complex to the west. The potential risk from soil vapor intrusion to indoor air was evaluated and determined that it was below the DEH carcinogenic target level of 1 x10-6. Twelve groundwater monitoring wells have been installed at the Site. Groundwater was monitored and sampled at the Site between April 2004 and January 2013. Separate-phase hydrocarbons (SPH) have never been present at the Site. Although the benzene dissolved-phase groundwater plume is largely confined to the southwest corner of the Site, the MTBE dissolved-phase groundwater plume extends down-gradient across Waite Drive. The 94 Freeway is located down-gradient of MW-10 and MW-11 preventing additional groundwater assessment in that direction. Groundwater in the vicinity of the Site is designated as non-beneficial. A Corrective Action Plan (CAP) was submitted on October 23, 2012 requesting case closure. The Public Participation process for the above-referenced CAP was completed. The public comment period ended on June 21, 2013. DEH received no comments. According to the environmental consultant s registered professional, the Site presents no significant risk to human health and the environment. DEH concurs with this conclusion.

LUST:
Global Id: T0607338887
Contact Type: Local Agency Caseworker
Contact Name: JON SENAHA
Organization Name: SAN DIEGO COUNTY LOP
Address: P.O. Box 129261
City: San Diego
Email: jon.senaha@sdcounty.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607338887
Action Type: RESPONSE
Date: 10/28/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607338887
Action Type: RESPONSE
Date: 04/30/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0607338887
Action Type: RESPONSE
Date: 06/24/2013
Action: Correspondence

Global Id: T0607338887
Action Type: RESPONSE
Date: 05/17/2013
Action: Correspondence

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 06/02/2003
Action: Notice of Responsibility

Global Id: T0607338887

SHELL (Continued) **S104582036**

Action Type: ENFORCEMENT
Date: 05/22/2012
Action: File review

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 07/18/2013
Action: Notice of Responsibility

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 07/18/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607338887
Action Type: Other
Date: 05/22/2003
Action: Leak Began

Global Id: T0607338887
Action Type: Other
Date: 05/22/2003
Action: Leak Reported

Global Id: T0607338887
Action Type: RESPONSE
Date: 09/19/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0607338887
Action Type: RESPONSE
Date: 03/26/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 04/11/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 05/24/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 07/18/2013
Action: Notification - Preclosure

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 10/08/2013
Action: Closure/No Further Action Letter

Global Id: T0607338887
Action Type: RESPONSE
Date: 10/28/2009

SHELL (Continued) **S104582036**

Action: Monitoring Report - Semi-Annually

Global Id: T0607338887
Action Type: RESPONSE
Date: 04/20/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607338887
Action Type: RESPONSE
Date: 06/18/2013
Action: Correspondence

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 01/13/2010
Action: Letter - Notice

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 01/30/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607338887
Action Type: Other
Date: 05/22/2003
Action: Leak Stopped

Global Id: T0607338887
Action Type: RESPONSE
Date: 07/28/2009
Action: Monitoring Report - Quarterly

Global Id: T0607338887
Action Type: RESPONSE
Date: 01/25/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0607338887
Action Type: RESPONSE
Date: 02/29/2012
Action: Soil and Water Investigation Report - Regulator Responded

Global Id: T0607338887
Action Type: RESPONSE
Date: 10/23/2012
Action: CAP/RAP - Other Report - Regulator Responded

Global Id: T0607338887
Action Type: RESPONSE
Date: 02/14/2013
Action: Other Report / Document - Regulator Responded

Global Id: T0607338887
Action Type: ENFORCEMENT
Date: 07/14/2009
Action: Letter - Notice

SHELL (Continued) **S104582036**

Global Id: T0607338887
Action Type: Other
Date: 05/22/2003
Action: Leak Discovery

Global Id: T0607338887
Action Type: RESPONSE
Date: 04/24/2009
Action: Monitoring Report - Quarterly

Global Id: T0607338887
Action Type: RESPONSE
Date: 04/29/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607338887
Action Type: RESPONSE
Date: 10/28/2011
Action: Monitoring Report - Semi-Annually

LUST:
Global Id: T0607338887
Status: Open - Case Begin Date
Status Date: 05/22/2003

Global Id: T0607338887
Status: Open - Remediation
Status Date: 02/09/2004

Global Id: T0607338887
Status: Open - Site Assessment
Status Date: 07/07/2009

Global Id: T0607338887
Status: Open - Eligible for Closure
Status Date: 07/11/2013

Global Id: T0607338887
Status: Completed - Case Closed
Status Date: 10/08/2013

Global Id: T0607338887
Status: Open - Eligible for Closure
Status Date: 10/08/2013

L67 **SHELL SERVICE STATION** **RCRA-LQG** **1004675651**
West **3810 MASSACHUSETSS / WAITE** **CAR000075556**
1/8-1/4 **LA MESA, CA 92041**
0.250 mi.
1319 ft. **Site 5 of 7 in cluster L**

Relative: RCRA Listings:
Lower
Date Form Received by Agency: 20040226
Actual: Handler Name: SHELL SERVICE STATION
458 ft. Handler Address: 3810 MASSACHUSETSS / WAITE
Handler City,State,Zip: LA MESA, CA 92041

SHELL SERVICE STATION (Continued) **1004675651**

EPA ID:		CAR000075556
Contact Name:		GARY V WING
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		714-731-8337
Contact Fax:		Not reported
Contact Email:		GVWING@SHELLOPUS.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Private
Federal Waste Generator Description:		Large Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		2003
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		SHELL OIL PRODUCTS US
Mailing City,State,Zip:		HOUSTON, TX 77067-2508
Owner Name:	EQUILON ENTERPRISES LLC DBA SHELL OIL PR	
Owner Type:		Private
Operator Name:	SHELL OIL PRODUCTS US	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No

SHELL SERVICE STATION (Continued) **1004675651**

TSDFs Only Subject to CA under Discretionary Auth Universe: No
Corrective Action Priority Ranking: No NCAPS ranking
Environmental Control Indicator: No
Institutional Control Indicator: No
Human Exposure Controls Indicator: N/A
Groundwater Controls Indicator: N/A
Operating TSDF Universe: Not reported
Full Enforcement Universe: Not reported
Significant Non-Complier Universe: No
Unaddressed Significant Non-Complier Universe: No
Addressed Significant Non-Complier Universe: No
Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 20041203
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D018
Waste Description: BENZENE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: EQUILON ENT L L C
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: P O BOX 2099
Owner/Operator City,State,Zip: HOUSTON, TX 77252-2099
Owner/Operator Telephone: 713-241-5036
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EQUILON ENTERPRISES LLC DBA SHELL OIL PR
Legal Status: Private
Date Became Current: 19980801
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 2648
Owner/Operator City,State,Zip: HOUSTON, TX 77252
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported

SHELL SERVICE STATION (Continued) **1004675651**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SHELL OIL PRODUCTS US
Legal Status: Private
Date Became Current: 19980801
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20000615
Handler Name: SHELL SVC STATION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040226
Handler Name: SHELL SERVICE STATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44711
NAICS Description: GASOLINE STATIONS WITH CONVENIENCE STORES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

L68 **CENTRE CITY SHELL** **RCRA NonGen / NLR** **1024820884**
West **3810 MASSACHUSETTS AVE** **CAL000335218**
1/8-1/4 **LA MESA, CA 91941**
0.250 mi.
1319 ft. **Site 6 of 7 in cluster L**

Relative: **Lower**

Actual: **458 ft.**

RCRA Listings:

Date Form Received by Agency:		20080806
Handler Name:	CENTRE CITY SHELL	
Handler Address:		3810 MASSACHUSETTS AVE
Handler City,State,Zip:		LA MESA, CA 91941-7640
EPA ID:		CAL000335218
Contact Name:		WILLIAM CLARK
Contact Address:		3810 MASSACHUSETTS AVE
Contact City,State,Zip:		LA MESA, CA 91941
Contact Telephone:		619-460-9194
Contact Fax:		619-460-5908
Contact Email:		BCSHELL@AOL.COM
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		3810 MASSACHUSETTS AVE
Mailing City,State,Zip:		LA MESA, CA 91941-0000
Owner Name:	TEXAS ST SHELL SERVICES INC	
Owner Type:		Other
Operator Name:	WILLIAM CLARK	
Operator Type:		Other
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		Yes
Universal Waste Destination Facility:		Yes
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		N
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported

CENTRE CITY SHELL (Continued) **1024820884**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20180905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: TEXAS ST SHELL SERVICES INC	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3810 MASSACHUSETTS AVE
Owner/Operator City,State,Zip:	LA MESA, CA 91941-0000
Owner/Operator Telephone:	619-460-9194
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: WILLIAM CLARK	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	3810 MASSACHUSETTS AVE
Owner/Operator City,State,Zip:	LA MESA, CA 91941
Owner/Operator Telephone:	619-460-9194
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

CENTRE CITY SHELL (Continued) **1024820884**

Historic Generators:
Receive Date: 20080806
Handler Name: CENTRE CITY SHELL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44719
NAICS Description: OTHER GASOLINE STATIONS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

L69 **SHELL** **SAN DIEGO CO. SAM** **S106874196**
West **3810 MASSACHUSETTS AV** **Cortese** **N/A**
1/8-1/4 **LA MESA, CA 91941**
0.250 mi.
1319 ft. **Site 7 of 7 in cluster L**

Relative:
Lower

Actual:
458 ft.

SAN DIEGO CO. SAM:
Name: SHELL
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Case Number: H12440-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Remedial Investigation
Date: 2/9/2004
Date Began: 5/22/2003

Name: SHELL
Address: 3810 MASSACHUSETTS AV
City,State,Zip: LA MESA, CA 91941
Case Number: H12440-002
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 1/25/2010
Date Began: 4/4/2005

CORTESE:

SHELL (Continued) **S106874196**

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T06019780340
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

Name:	SHELL
Address:	3810 MASSACHUSETTS AV
City,State,Zip:	LA MESA, CA 91941
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607338887
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

70
South
1/4-1/2
0.251 mi.
1327 ft.

FOOD 4 LESS STORE #318
7420 BROADWAY ST
LEMON GROVE, CA 91945

SWRCY
San Diego Co. HMMD
CERS HAZ WASTE
CERS

S102798634
N/A

Relative:
Lower

Actual:
426 ft.

SWRCY:

Name:	PONCE RECYCLING
Address:	7420 BROADWAY ST
City,State,Zip:	LEMON GROVE, CA 91945
Reg Id:	Not reported
Cert Id:	RC295745.001
Mailing Address:	5425 W 64th St
Mailing City:	Los Angeles
Mailing State:	CA
Mailing Zip Code:	90056
Website:	Not reported
Email:	ponceрecycling@aol.com
Phone Number:	(323) 533-4862
Rural:	N
Operation Begin Date:	02/25/2020
Aluminium:	Not reported
Glass:	Not reported
Plastic:	Not reported
Bimetal:	Not reported
Hours of Operation:	Mon - Sat 9:00 am - 5:00 pm; Sun Closed
Organization ID:	Not reported
Organization Name:	Ponce Recycling Inc

HMMD SAN DIEGO:

Name:	FOOD 4 LESS FUEL CENTER # 318
Address:	7420 BROADWAY ST
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	211215
Business Type:	6HK29
EPA Id Number:	CAL000349596
APN:	480-021-93-00
Last HMMD Inspection:	09/27/2011
Facility Telephone:	619-463-4774
Permit Status:	OPEN
Permit Expiration:	05/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	RALPHS GROCERY CO
Facility Mailing Address:	PO BOX 54143
Facility Mailing City:	LOS ANGELES
Facility Mailing State:	CA
Facility Mailing Zip:	90054-0143
UST Owner:	FOOD 4 LESS
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	211215
Update Date:	11/02/2012
Case Number:	68476-34-6

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Name:	DIESEL FUEL
Other Information:	UNDERGROUND TANK 211215 T002 DIESEL FUEL
Material Waste:	Material
Hazardous Categories 1:	CHRONIC
Hazardous Categories 2:	Not reported
Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUN TANK 211215 TANK 003 PREMIUM UNLEADED
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported
Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 211215 T001 REGULAR UNLEADED
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported
Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 122 ALKALINE SOL'N W/OUT METALS
Other Information:	CORROSIVE BASES
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	WATER & FUEL
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 141 OFF-SPEC,AGED,SURPL INORGANICS
Other Information:	RETURNS & BROKEN ITEMS - CORROSIVES
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 214 UNSPEC SOLVENT MIXTURE
Other Information:	AEROSOLS
Material Waste:	Waste

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211215
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 331 OFF-SPEC,AGED,SURPLUS ORGANICS
Other Information: RETURNS & BROKEN ITEMS - FLAMMABLES
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211215
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: FUEL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211215
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 791 LIQUIDS WITH PH <OR= 2
Other Information: CORROSIVE ACIDIC
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a) & 25160.2(b)(3)
Activity: ACTIVE

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0228
Violation: CONTAINER NOT KEPT CLOSED
Violation Citation: Failed to keep container closed. CFR 265.173
Activity: ACTIVE

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0217
Violation: HAZMAT CON. NOT REPACKAGED WI 96 HRS.
Violation Citation: Failed to repackage damaged/deteriorated hazardous material container within 96 hours. 25124(b)(3)(B) & 66262.34(f)
Activity: ACTIVE

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0227
Violation: HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation: Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity: ACTIVE

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0231
Violation: INCOMPATIBLE HW NOT PROPERLY SEPARATED
Violation Citation: Failed to properly separate incompatible wastes. CFR 265.177
Activity: ACTIVE

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0229
Violation: HW CONTAINERS NOT INSPECTED WEEKLY
Violation Citation: Failed to conduct weekly inspections. CFR 265.174
Activity: ACTIVE

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0409
Violation: NO SPILL/FIRE CONTROL EQUIPMENT
Violation Citation: Spill/fire control equip not available for small quantity generator of hazardous waste. CFR 265.32(c)
Activity: ACTIVE

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0304
Violation: WASTE DETERMINATION NOT MADE
Violation Citation: Generator of a waste has not determined if that waste is a hazardous waste as defined by law. CCR 66262.11 & 66260.200(c)
Activity: ACTIVE

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0407
Violation: EMPLOYEE TRAINING NOT ADEQUATE
Violation Citation: Employee training program for small quantity generator of hazardous waste is inadequate. CFR 262.34(d)(5)(iii)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 211215 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 211215
Tank Type: DOUBLE WALL

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Additional Id:	NT2508
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2011-06-28 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

UST Name:	UNDERGROUND TANK 211215 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	211215
Tank Type:	DOUBLE WALL
Additional Id:	NT2508
Capacity Gallons:	10000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2011-06-28 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

UST Name:	UNDERGROUND TANK 211215 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	211215
Tank Type:	DOUBLE WALL
Additional Id:	NT2508
Capacity Gallons:	8000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2011-06-28 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

Name:	FOOD 4 LESS FUEL CENTER # 318
Address:	7420 BROADWAY ST
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	211215
Business Type:	6HK29
EPA Id Number:	CAL000349596
APN:	480-021-93-00
Last HMMD Inspection:	09/27/2011
Facility Telephone:	619-463-4774

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Permit Status:	OPEN
Permit Expiration:	05/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	RALPHS GROCERY CO
Facility Mailing Address:	PO BOX 54143
Facility Mailing City:	LOS ANGELES
Facility Mailing State:	CA
Facility Mailing Zip:	90054-0143
UST Owner:	FOOD 4 LESS
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	211215
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL FUEL
Other Information:	UNDERGROUND TANK 211215 T002 DIESEL FUEL
Material Waste:	Material
Hazardous Categories 1:	CHRONIC
Hazardous Categories 2:	Not reported

Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUN TANK 211215 TANK 003 PREMIUM UNLEADED
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported

Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 211215 T001 REGULAR UNLEADED
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	Not reported

Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 122 ALKALINE SOL'N W/OUT METALS
Other Information:	CORROSIVE BASES
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	211215
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 134 AQUEOUS SOL'N W/LESS 10% ORG
Other Information:	WATER & FUEL

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211215
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 141 OFF-SPEC,AGED,SURPL INORGANICS
Other Information: RETURNS & BROKEN ITEMS - CORROSIVES
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211215
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 214 UNSPEC SOLVENT MIXTURE
Other Information: AEROSOLS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211215
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 331 OFF-SPEC,AGED,SURPLUS ORGANICS
Other Information: RETURNS & BROKEN ITEMS - FLAMMABLES
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211215
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: FUEL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 211215
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 791 LIQUIDS WITH PH <OR= 2
Other Information: CORROSIVE ACIDIC
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0135
Violation: MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation: Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a)

FOOD 4 LESS STORE #318 (Continued) **S102798634**

	& 25160.2(b)(3)
Activity:	ACTIVE
Permit Number:	211215
Update Date:	11/02/2012
Inspection Date:	01/22/2010
Violation Code:	6HV0228
Violation:	CONTAINER NOT KEPT CLOSED
Violation Citation:	Failed to keep container closed. CFR 265.173
Activity:	ACTIVE
Permit Number:	211215
Update Date:	11/02/2012
Inspection Date:	01/22/2010
Violation Code:	6HV0217
Violation:	HAZMAT CON. NOT REPACKAGED WI 96 HRS.
Violation Citation:	Failed to repackage damaged/deteriorated hazardous material container within 96 hours. 25124(b)(3)(B) & 66262.34(f)
Activity:	ACTIVE
Permit Number:	211215
Update Date:	11/02/2012
Inspection Date:	01/22/2010
Violation Code:	6HV0227
Violation:	HAZWASTE TANK/CONTAINER W/O LABEL/DATE
Violation Citation:	Failed to properly label/date hazardous waste container &/or tank. 66262.34(f)
Activity:	ACTIVE
Permit Number:	211215
Update Date:	11/02/2012
Inspection Date:	01/22/2010
Violation Code:	6HV0231
Violation:	INCOMPATIBLE HW NOT PROPERLY SEPARATED
Violation Citation:	Failed to properly separate incompatible wastes. CFR 265.177
Activity:	ACTIVE
Permit Number:	211215
Update Date:	11/02/2012
Inspection Date:	01/22/2010
Violation Code:	6HV0229
Violation:	HW CONTAINERS NOT INSPECTED WEEKLY
Violation Citation:	Failed to conduct weekly inspections. CFR 265.174
Activity:	ACTIVE
Permit Number:	211215
Update Date:	11/02/2012
Inspection Date:	01/22/2010
Violation Code:	6HV0409
Violation:	NO SPILL/FIRE CONTROL EQUIPMENT
Violation Citation:	Spill/fire control equip not available for small quantity generator of hazardous waste. CFR 265.32(c)
Activity:	ACTIVE
Permit Number:	211215
Update Date:	11/02/2012
Inspection Date:	01/22/2010

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Violation Code: 6HV0304
Violation: WASTE DETERMINATION NOT MADE
Violation Citation: Generator of a waste has not determined if that waste is a hazardous waste as defined by law. CCR 66262.11 & 66260.200(c)
Activity: ACTIVE

Permit Number: 211215
Update Date: 11/02/2012
Inspection Date: 01/22/2010
Violation Code: 6HV0407
Violation: EMPLOYEE TRAINING NOT ADEQUATE
Violation Citation: Employee training program for small quantity generator of hazardous waste is inadequate. CFR 262.34(d)(5)(iii)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 211215 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 211215
Tank Type: DOUBLE WALL
Additional Id: NT2508
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2011-06-28 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 40
UST Monitor Method: DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

UST Name: UNDERGROUND TANK 211215 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 211215
Tank Type: DOUBLE WALL
Additional Id: NT2508
Capacity Gallons: 10000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2011-06-28 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 40
UST Monitor Method: DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

UST Name: UNDERGROUND TANK 211215 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 211215
Tank Type: DOUBLE WALL
Additional Id: NT2508
Capacity Gallons: 8000
UST Contents: PREMIUM UNLEADED

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2011-06-28 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

Name:	FOOD 4 LESS STORE #318
Address:	7420 BROADWAY ST
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAL000325854
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	6194634774
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	11/03/2022
Facility Owner:	Not reported
Facility Mailing Address:	P.O. Box 54143, Los Angeles, CA 90054
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	N
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-211215
Program Element:	Hazardous Waste Generator
Inspection Type:	Routine
Inspection Number:	5923207
Return To Compliance Date:	2018-03-22T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-11-03T00:36:32.000
Inspection Date:	2018-03-21T07:36:00.000
Violation Code:	HMD0138 Manifest signed by the TSDF not available for inspection. 22 CCR 66262.40(a); HSC 25185(a)(4)

UST DTL:

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Active Permit:	Y
Facility Id Number:	37-000-211215
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	Ralphs Grocery Company
Tankid:	97414
Tank Status:	Void
Date Ust Permanently Closed:	Not reported
Tank Use:	01
Piping System Type:	01
Last Updated:	2022-11-03T00:36:37.000
Tank Capacityin Gallons:	8000
Tank Contents:	1B
Type Of Tank:	02

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-211215
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	Ralphs Grocery Company
Tankid:	97412
Tank Status:	Void
Date Ust Permanently Closed:	Not reported
Tank Use:	01
Piping System Type:	01
Last Updated:	2022-11-03T00:36:37.000
Tank Capacityin Gallons:	20000
Tank Contents:	1A
Type Of Tank:	02

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-211215
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	Ralphs Grocery Company
Tankid:	97413
Tank Status:	Void
Date Ust Permanently Closed:	Not reported
Tank Use:	01
Piping System Type:	01
Last Updated:	2022-11-03T00:36:37.000
Tank Capacityin Gallons:	10000
Tank Contents:	Diesel
Type Of Tank:	02

Waste and Materials:

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HCHEM-0175175
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2018-03-23T01:51:10.000
Chemical Name:	Lead Acid Batteries
Common Name:	Lead Acid Batteries
Case Number:	Not reported

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0149764
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-03-23T01:51:10.000
Chemical Name:	Waste Toxics
Common Name:	Waste Toxics
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0149765
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-03-23T01:51:10.000
Chemical Name:	Waste Flammables
Common Name:	Waste Flammables
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0149766
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-03-23T01:51:10.000
Chemical Name:	Waste Aerosols
Common Name:	Waste Aerosols
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0149767
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-03-23T01:51:10.000
Chemical Name:	Waste Corrosive Acid
Common Name:	Waste Corrosive Acid
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0149768
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-03-23T01:51:10.000
Chemical Name:	Waste P-listed
Common Name:	Waste P-listed
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0149769
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-03-23T01:51:10.000
Chemical Name:	Waste Bleach
Common Name:	Waste Bleach
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HWAST-0149770
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2018-03-23T01:51:10.000
Chemical Name:	Waste Corrosive Bases
Common Name:	Waste Corrosive Bases
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0210591
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2019-05-14T02:32:43.000
Chemical Name:	Refrigerant R407A
Common Name:	R-407A
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HWAST-0182859
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-05-14T02:32:43.000
Chemical Name:	Waste Aerosols
Common Name:	Waste Aerosols
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HWAST-0182860
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2019-05-14T02:32:43.000
Chemical Name:	Waste Corrosive Acid
Common Name:	Waste Corrosive Acid
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HWAST-0182861

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-05-14T02:32:43.000
Chemical Name: Waste Corrosive Bases
Common Name: Waste Corrosive Bases
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0182862
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-05-14T02:32:43.000
Chemical Name: Waste Bleach
Common Name: Waste Bleach
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0182863
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-05-14T02:32:43.000
Chemical Name: Waste Toxics
Common Name: Waste Toxics
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0182864
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-05-14T02:32:43.000
Chemical Name: Variable
Common Name: Variable
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0182865
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-05-14T02:32:43.000
Chemical Name: Waste Pharmaceuticals not P-listed
Common Name: Waste Pharmaceuticals not P-listed
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0182866
Trade Secret: N
Hazardous Material Type: Not reported

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Last Updated: 2019-05-14T02:32:43.000
Chemical Name: Medical Waste - Sharps
Common Name: Medical Waste - Sharps
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0182867
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-05-14T02:32:43.000
Chemical Name: Waste Flammables
Common Name: Waste Flammable
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0344398
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Refrigerant R407A
Common Name: R-407A
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311730
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Waste Toxics
Common Name: Waste Toxics
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311731
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Waste Flammables
Common Name: Waste Flammable
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311732
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Waste Pharmaceuticals not P-listed

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Common Name: Waste Pharmaceuticals not P-listed
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311733
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Waste Bleach
Common Name: Waste Bleach
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311734
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Waste Corrosive Acid
Common Name: Waste Corrosive Acid
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311735
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Waste Aerosols
Common Name: Waste Aerosols
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311736
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Medical Waste - Sharps
Common Name: Medical Waste - Sharps
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0311737
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-11-03T00:36:36.000
Chemical Name: Waste Corrosive Bases
Common Name: Waste Corrosive Bases
Case Number: Not reported

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HCHEM-0132445
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2017-05-24T01:20:54.000
Chemical Name:	Liquified Petroleum Gas
Common Name:	Propane
Case Number:	74-98-6

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0110832
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-05-24T01:20:54.000
Chemical Name:	Waste Toxics
Common Name:	Waste Toxics
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0110833
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-05-24T01:20:54.000
Chemical Name:	Waste Flammable Liquids
Common Name:	Waste Flammable Liquids
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0110834
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-05-24T01:20:54.000
Chemical Name:	Waste Corrosive Bases
Common Name:	Waste Corrosive Bases
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0110835
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-05-24T01:20:54.000
Chemical Name:	Waste Corrosive Acid
Common Name:	Waste Corrosive Acid
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0110836
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-05-24T01:20:54.000
Chemical Name:	Waste Bleach
Common Name:	Waste Bleach
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2017-HWAST-0110837
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2017-05-24T01:20:54.000
Chemical Name:	Waste Aerosols
Common Name:	Waste Aerosols
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HWAST-0220074
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2022-05-27T02:32:38.000
Chemical Name:	Waste Flammables
Common Name:	Waste Flammable
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0210589
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2019-05-14T02:32:43.000
Chemical Name:	Chlorodifluoromethane
Common Name:	R-22
Case Number:	75-45-6

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2019-HCHEM-0210590
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2019-05-14T02:32:43.000
Chemical Name:	R-404A
Common Name:	R-404A
Case Number:	Not reported

Record ID:	DEH2009-HUPFP-211215
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2018-HCHEM-0176592

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-10-25T21:23:47.000
Chemical Name: Lead Acid Batteries
Common Name: Lead Acid Batteries
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151306
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T21:23:47.000
Chemical Name: Waste Toxics
Common Name: Waste Toxics
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151307
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T21:23:47.000
Chemical Name: Waste Flammables
Common Name: Waste Flammables
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151308
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T21:23:47.000
Chemical Name: Waste Aerosols
Common Name: Waste Aerosols
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151309
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T21:23:47.000
Chemical Name: Waste Corrosive Acid
Common Name: Waste Corrosive Acid
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151310
Trade Secret: N
Hazardous Material Type: Not reported

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Last Updated: 2018-10-25T21:23:47.000
Chemical Name: Waste P-listed
Common Name: Waste P-listed
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151311
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T21:23:47.000
Chemical Name: Waste Bleach
Common Name: Waste Bleach
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0151312
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-10-25T21:23:47.000
Chemical Name: Waste Corrosive Bases
Common Name: Waste Corrosive Bases
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0249030
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-05-27T02:32:38.000
Chemical Name: Refrigerant R407A
Common Name: R-407A
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220073
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-05-27T02:32:38.000
Chemical Name: Waste Toxics
Common Name: Waste Toxics
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220075
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-05-27T02:32:38.000
Chemical Name: Waste Pharmaceuticals not P-listed

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Common Name: Waste Pharmaceuticals not P-listed
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220076
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-05-27T02:32:38.000
Chemical Name: Waste Bleach
Common Name: Waste Bleach
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220077
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-05-27T02:32:38.000
Chemical Name: Waste Corrosive Acid
Common Name: Waste Corrosive Acid
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220078
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-05-27T02:32:38.000
Chemical Name: Waste Aerosols
Common Name: Waste Aerosols
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220079
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-05-27T02:32:38.000
Chemical Name: Medical Waste - Sharps
Common Name: Medical Waste - Sharps
Case Number: Not reported

Record ID: DEH2009-HUPFP-211215
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0220080
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-05-27T02:32:38.000
Chemical Name: Waste Corrosive Bases
Common Name: Waste Corrosive Bases
Case Number: Not reported

FOOD 4 LESS STORE #318 (Continued) **S102798634**

CERS HAZ WASTE:
Name: FOOD 4 LESS STORE #318
Address: 7420 BROADWAY ST
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 30862
CERS ID: 10160559
CERS Description: Hazardous Waste Generator

CERS:
Name: FOOD 4 LESS STORE #318
Address: 7420 BROADWAY ST
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 30862
CERS ID: 10160559
CERS Description: Chemical Storage Facilities

Violations:
Site ID: 30862
Site Name: Food 4 Less Store #318
Violation Date: 03-21-2018
Citation: HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Violation Description: Hazardous Waste Generator Program - Administration/Documentation - General
Violation Notes: Returned to compliance on 03/22/2018. Inspection Sequence ID:5923207;Violation:HMD0138 Manifest signed by the TSDF not available for inspection. 22 CCR 66262.40(a); HSC 25185(a)(4)
Violation Division: San Diego County Department of Env Health
Violation Program: HW
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Moreau Marie Inspection ID:6407437
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-19-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4796658
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5923207
Eval Division: San Diego County Department of Env Health

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-08-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5395766
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5923207
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-27-2021
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Moreau Marie Inspection ID:6407437
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-08-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5395766
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-19-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4796658
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 09-19-2013
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4796658
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Affiliation:

Affiliation Type Desc:	Environmental Contact
Entity Name:	Edward Idian
Entity Title:	Not reported
Affiliation Address:	P.O. Box 54143
Affiliation City:	Los Angeles
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90054-0143
Affiliation Phone:	,

Affiliation Type Desc:	Identification Signer
Entity Name:	Edward Idian
Entity Title:	Env Affairs Specialist
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	Parent Corporation
Entity Name:	Ralphs Grocery Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	Property Owner
Entity Name:	GCA Realty, New Victoria,
Entity Title:	Not reported
Affiliation Address:	2100 N. Ocean Blvd. - Apt
Affiliation City:	Fort Lauderdale
Affiliation State:	FL
Affiliation Country:	United States
Affiliation Zip:	33305
Affiliation Phone:	(718) 353-3900,

Affiliation Type Desc:	Legal Owner
Entity Name:	Ralphs Grocery Company
Entity Title:	Not reported
Affiliation Address:	P.O. Box 54143
Affiliation City:	Los Angeles
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	90054-0143
Affiliation Phone:	(310) 884-9000,

Affiliation Type Desc:	Document Preparer
Entity Name:	Ralphs Grocery Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported

FOOD 4 LESS STORE #318 (Continued) **S102798634**

Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	P.O. Box 54143
Affiliation City:	Los Angeles
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	90054-0143
Affiliation Phone:	,
Affiliation Type Desc:	Operator
Entity Name:	Ralphs Grocery Company
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(310) 884-9000,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,

71
SW
1/4-1/2
0.272 mi.
1435 ft.

Relative:
Lower

Actual:
425 ft.

CORRAL FORD **LUST** **S104747365**
3470 VISTA AV **SAN DIEGO CO. SAM** **N/A**
LEMON GROVE, CA 91945 **San Diego Co. HMMD**
Cortese
SAN DIEGO CO LOP
CERS

LUST:

Name:	CORRAL FORD
Address:	3470 VISTA AV
City,State,Zip:	LEMON GROVE, CA 919451501
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301486
Global Id:	T0607301486
Latitude:	32.7425965
Longitude:	-117.0423351
Status:	Completed - Case Closed
Status Date:	01/14/1995
Case Worker:	Not reported
RB Case Number:	9UT2731
Local Agency:	Not reported
File Location:	Local Agency

CORRAL FORD (Continued) **S104747365**

Local Case Number: H12503-001
Potential Media Affect: Soil
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

LUST:
Global Id: T0607301486
Action Type: Other
Date: 03/31/1994
Action: Leak Discovery

Global Id: T0607301486
Action Type: Other
Date: 03/31/1994
Action: Leak Began

Global Id: T0607301486
Action Type: Other
Date: 03/31/1994
Action: Leak Reported

Global Id: T0607301486
Action Type: Other
Date: 03/31/1994
Action: Leak Stopped

LUST:
Global Id: T0607301486
Status: Open - Case Begin Date
Status Date: 03/31/1994

Global Id: T0607301486
Status: Completed - Case Closed
Status Date: 01/14/1995

SAN DIEGO CO. SAM:
Name: CORRAL FORD
Address: 3470 VISTA AV
City,State,Zip: LEMON GROVE, CA 919451501
Case Number: H12503-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 1/14/1995
Date Began: 3/31/1994

HMMD SAN DIEGO:
Name: CORRAL FORD
Address: 3470 VISTA AV
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 112503
Business Type: 6HK27
EPA Id Number: CAD055699128
APN: 479-041-18-00

CORRAL FORD (Continued) **S104747365**

Last HMMD Inspection: 07/17/1998
Facility Telephone: 619-466-2174
Permit Status: INAC
Permit Expiration: 07/17/1998
Date Last Updated: 11/02/2012
Facility Owner: L R CAMP
Facility Mailing Address: 6828 FEDERAL BL
Facility Mailing City: LEMON GROVE
Facility Mailing State: CA
Facility Mailing Zip: 91945-
UST Owner: L R CAMP
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

UST:
UST Name: UNDERGROUND TANK 112503 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 112503
Tank Type: SINGLE WALL
Additional Id: 1
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: MOTOR OIL
Reg Status: REMOVED
Remove Close Date: 1994-03-31 00:00:00
Year Installed: Not reported
Pipe Type: SINGLE WALL
Delivery System: SUCTION
Monitor Code: 07
UST Monitor Method: SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name: UNDERGROUND TANK 112503 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 112503
Tank Type: SINGLE WALL
Additional Id: 2
Capacity Gallons: 550
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1994-03-31 00:00:00
Year Installed: Not reported
Pipe Type: SINGLE WALL
Delivery System: Not reported
Monitor Code: 07
UST Monitor Method: SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

CORTESE:
Name: CORRAL FORD
Address: 3470 VISTA AV

CORRAL FORD (Continued) **S104747365**

City,State,Zip:	LEMON GROVE, CA 919451501
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607301486
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

SAN DIEGO CO LOP:

Name:	CORRAL FORD
Address:	3470 VISTA AVE
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1994-LSAM-H12503-001
Record Status:	Completed
Opened Date:	03/31/1994
Parcel Number:	479-041-18-00
Case Type:	LOP - Local Oversight Program
Historical Name:	CORRAL FORD
SWRCB Global ID:	T0607301486
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	04/07/1994
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7432895
Longitude:	-117.0422912
X MapCoord:	6317994.083
Y MapCoord:	1851260.691

CERS:

Name:	CORRAL FORD
Address:	3470 VISTA AV
City,State,Zip:	LEMON GROVE, CA 919451501
Site ID:	251572
CERS ID:	T0607301486
CERS Description:	Leaking Underground Storage Tank Cleanup Site

72
ESE
1/4-1/2
0.283 mi.
1494 ft.

COMMERCIAL PROPERTY
7666 NORTH AVENUE
LEMON GROVE, CA 92071

CPS-SLIC **S118172403**
CERS **N/A**

Relative:
Lower

Actual:
466 ft.

CPS-SLIC:

Name:	COMMERCIAL PROPERTY
Address:	7666 NORTH AVENUE
City,State,Zip:	LEMON GROVE, CA 92071
Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	09/25/2015
Global Id:	T10000007719
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	DEH2015-LSAM-000328
Latitude:	32.74518
Longitude:	-117.03298
Case Type:	Cleanup Program Site
Case Worker:	EM
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Not reported
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Diesel, Gasoline
Site History:	The site property is approximately 0.46 acres in size and is currently designated for commercial use. There is a steel automotive service bay building located in the southwest corner of the property and the northern portion of the property is vacant. There are no proposed plans for redevelopment, property improvement, or change in site use. The Phase I Environmental Site Assessment (ESA) report, dated September 29, 2004 and completed by SECOR, summarizes results of the site investigation to assess the presence or likely presence of any recognizable environmental concerns on the subject property. On February 17 and 22, 2005, SECOR completed a limited Phase II ESA at the subject site. The investigation consisted of the collection of shallow soil and soil vapor samples onsite to evaluate potential subsurface impacts resulting from the former construction yard, former underground storage tank (UST), and former automotive body shop. Five shallow soil samples to approximately 1.5 feet below ground surface (bgs) and three soil vapor samples to approximately 5 feet bgs were collected. Total Recoverable Petroleum Hydrocarbon (TRPH) concentrations of up to 25,000 milligrams per kilograms (mg/kg) were detected in the soil samples. Volatile organic compound (VOC) constituents were not detected above their respective laboratory reporting limits in any of the soil vapor samples. On February 6, 2015, EnviroApplications, Inc. (EAI) oversaw the advancement of 20 soil borings (SB-1 through SB-20) to depths of 5 feet bgs. A total of 39 soil samples were collected of which 28 samples were analyzed for petroleum hydrocarbons. Two samples (SB-11 & SB-15) underwent additional analysis for VOCs, CA Title 22 metals, and PCBs. Based on the analytical results, petroleum hydrocarbons were detected above the laboratory reporting limit in 14 of 28 samples with soil impacts >1,000 milligrams per kilogram (mg/kg) located in the northern aspect of the property. Arsenic concentrations of 15 mg/kg and 19 mg/kg were detected in samples SB-11-5 and SB-15-5, respectively. No VOCs or PCBs were detected. Depth to groundwater onsite is estimated to range between 20 feet to 25 feet bgs with groundwater not being encountered during the course

COMMERCIAL PROPERTY (Continued) **S118172403**

of the investigation. Based on the subsurface environmental investigations, low toxicity of the contaminant type in the shallow subsurface soils, and current site usage, EAI recommends the impacted soils be allowed to be left in place. The consultant recommends no further action and for DEH to administer case closure. DEH concurs with the aforementioned and closure of the case.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	COMMERCIAL PROPERTY
Address:	7666 NORTH AVENUE
City,State,Zip:	LEMON GROVE, CA 92071
Site ID:	358357
CERS ID:	T10000007719
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	EWAN MOFFAT - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

M73 **USA PETROLEUM COMPANY 246** **LUST** **U001571859**
SSE **7505 BROADWAY** **HIST UST** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045** **HIST CORTESE**
0.285 mi.
1503 ft. **Site 1 of 5 in cluster M**

Relative: **Lower**
Actual: **437 ft.**

LUST:

Name:	USA GASOLINE CORP #246
Address:	7505 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451605
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607300209
Global Id:	T0607300209
Latitude:	32.7424286
Longitude:	-117.0361518
Status:	Open - Remediation
Status Date:	04/07/2020
Case Worker:	LT
RB Case Number:	9UT1368
Local Agency:	Not reported
File Location:	Regional Board
Local Case Number:	Not reported
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	This case was opened based on the discovery of petroleum contaminated soil and groundwater during a Site Assessment which was reported to the DEH on March 31, 1989. Soil was reported to contain concentrations of total petroleum hydrocarbons of 11,400 mg/kg. Free

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

product was observed in one boring (B-1). Benzene was also reported in groundwater at a concentration of 3,960 ug/l. There are currently 16 monitoring wells and 9 recovery wells associated with the site. Groundwater sampling was initiated in 1989 and is currently conducted on a semi-annual basis. Free product has been detected in several of the wells associated with the site beginning in 1990. A dual-phase extraction remediation system has been operating at the site since May 2002. This system was designed to remove soil vapor and groundwater from thirteen wells using a thermal oxidizer with a liquid ring pump. Soil vapors are treated and discharged in accordance with a San Diego County Air Pollution County District Permit No. 976049. Initially, extracted groundwater was stored temporarily on-site and then transported and disposed off-site. In 2007, the consultant received a Wastewater Discharge permit to discharge to the sanitary sewer. Please see ESI for additional information.

LUST:
Global Id: T0607300209
Contact Type: Regional Board Caseworker
Contact Name: LALITHA THOTAKURA
Organization Name: SAN DIEGO RWQCB (REGION 9)
Address: 2375 NORTHSIDE DRIVE, SUITE 100
City: SAN DIEGO
Email: lalitha.thotakura@waterboards.ca.gov
Phone Number: 6195213002

LUST:
Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 02/23/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 01/04/2011
Action: Letter - Notice

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 07/22/2010
Action: Staff Letter

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 05/30/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 05/31/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 12/20/2013
Action: Technical Correspondence / Assistance / Other

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 12/20/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 04/26/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 08/18/2010
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607300209
Action Type: RESPONSE
Date: 08/17/2015
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 07/30/2017
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 04/18/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 12/21/2018
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 08/15/2017
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 06/25/2015
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 06/27/2019
Action: Referral to Regional Board

Global Id: T0607300209
Action Type: Other
Date: 03/31/1989
Action: Leak Began

Global Id: T0607300209
Action Type: Other

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Date: 03/31/1989
Action: Leak Discovery

Global Id: T0607300209
Action Type: Other
Date: 03/31/1989
Action: Leak Reported

Global Id: T0607300209
Action Type: RESPONSE
Date: 01/23/2012
Action: Correspondence

Global Id: T0607300209
Action Type: RESPONSE
Date: 07/30/2012
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 02/26/2009
Action: Notice of Responsibility

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 04/22/2010
Action: Letter - Notice

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 01/28/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 10/07/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 07/09/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 12/21/2018
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 04/27/2018
Action: Email Correspondence

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 12/11/2019
Action: Staff Letter

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 03/04/2020
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 09/17/2019
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 04/22/2020
Action: Email Correspondence

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 05/19/2020
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 10/02/2020
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: RESPONSE
Date: 05/18/2016
Action: Pilot Study / Treatability Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 03/10/2016
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 10/18/2018
Action: Well Installation Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 10/15/2019
Action: Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 02/03/2021
Action: Other Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 06/29/2020
Action: Response to Comments - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Date: 10/18/2018
Action: Other Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 01/21/2020
Action: Other Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 12/08/2017
Action: Pilot Study/ Treatability Report - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 06/05/2017
Action: Other Report / Document - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 09/05/2017
Action: Site Assessment Report - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 08/24/2016
Action: Other Report / Document - Regulator Responded

Global Id: T0607300209
Action Type: REMEDIATION
Date: 05/20/1996
Action: Excavation

Global Id: T0607300209
Action Type: REMEDIATION
Date: 05/23/2002
Action: Dual Phase Extraction

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 11/22/2011
Action: File review

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 08/27/2015
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 09/09/2016
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 10/11/2016
Action: Technical Correspondence / Assistance / Other

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 02/01/2016
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 06/27/2019
Action: Referral to Regional Board

Global Id: T0607300209
Action Type: Other
Date: 03/31/1989
Action: Leak Stopped

Global Id: T0607300209
Action Type: RESPONSE
Date: 03/30/2009
Action: Pilot Study / Treatability Workplan

Global Id: T0607300209
Action Type: RESPONSE
Date: 07/11/2022
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 07/08/2021
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 07/29/2022
Action: Remedial Progress Report

Global Id: T0607300209
Action Type: RESPONSE
Date: 07/29/2022
Action: Monitoring Report - Other

Global Id: T0607300209
Action Type: RESPONSE
Date: 10/21/2021
Action: Monitoring Report - Other

Global Id: T0607300209
Action Type: RESPONSE
Date: 02/16/2022
Action: Monitoring Report - Other

Global Id: T0607300209
Action Type: RESPONSE
Date: 02/01/2022
Action: Monitoring Report - Quarterly

Global Id: T0607300209
Action Type: RESPONSE

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Date: 09/15/2016
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 12/15/2021
Action: Monitoring Report - Other

Global Id: T0607300209
Action Type: RESPONSE
Date: 09/30/2021
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 02/28/2022
Action: Monitoring Report - Other

Global Id: T0607300209
Action Type: RESPONSE
Date: 05/24/2022
Action: Monitoring Report - Other

Global Id: T0607300209
Action Type: RESPONSE
Date: 04/04/2013
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 04/11/2022
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 04/18/2013
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 11/01/2012
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 11/04/2013
Action: Soil and Water Investigation Workplan - Addendum - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 11/05/2013
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 04/21/2014
Action: Monitoring Report - Quarterly - Regulator Responded

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Global Id: T0607300209
Action Type: RESPONSE
Date: 01/15/2014
Action: Other Workplan - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 09/17/2014
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0607300209
Action Type: RESPONSE
Date: 05/29/2015
Action: Well Installation Report - Regulator Responded

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 04/03/1989
Action: Notice of Responsibility

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 02/24/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 07/09/2009
Action: Letter - Notice

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 12/02/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 04/23/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 10/07/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 02/11/2016
Action: Site Visit / Inspection / Sampling

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 02/16/2016
Action: Technical Correspondence / Assistance / Other

Global Id: T0607300209
Action Type: ENFORCEMENT

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Date: 04/27/2018
Action: Email Correspondence

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 03/09/2021
Action: Other Report

Global Id: T0607300209
Action Type: ENFORCEMENT
Date: 07/22/2022
Action: Staff Letter

Global Id: T0607300209
Action Type: RESPONSE
Date: 04/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 10/30/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 01/30/2018
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 03/14/2017
Action: Correspondence

Global Id: T0607300209
Action Type: RESPONSE
Date: 01/02/2020
Action: Well Installation Report

Global Id: T0607300209
Action Type: RESPONSE
Date: 12/31/2019
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 01/30/2019
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 01/08/2021
Action: Monitoring Report - Semi-Annually

Global Id: T0607300209
Action Type: RESPONSE
Date: 06/01/2020
Action: Monitoring Report - Semi-Annually

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Global Id: T0607300209
Action Type: RESPONSE
Date: 07/30/2018
Action: Monitoring Report - Semi-Annually

LUST:
Global Id: T0607300209
Status: Open - Case Begin Date
Status Date: 03/31/1989

Global Id: T0607300209
Status: Open - Remediation
Status Date: 06/08/2000

Global Id: T0607300209
Status: Open - Verification Monitoring
Status Date: 08/18/2014

Global Id: T0607300209
Status: Open - Remediation
Status Date: 04/07/2020

HIST UST:
Name: USA PETROLEUM COMPANY 246
Address: 7505 BROADWAY
City,State,Zip: LEMON GROVE, CA 92045
File Number: 0002f52f
URL: https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002f52f.pdf
Region: STATE
Facility ID: 00000001977
Facility Type: Gas Station
Other Type: Not reported
Contact Name: DEAN SHRUM
Telephone: 2138294383
Owner Name: USA PETROLEUM COMPANY
Owner Address: P.O.BOX 1839
Owner City,St,Zip: SANTA MONICA, CA 90406
Total Tanks: 0004

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: UNLEADED
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: REGULAR
Container Construction Thickness: 1/4

USA PETROLEUM COMPANY 246 (Continued) **U001571859**

Leak Detection: Stock Inventor

Tank Num: 003
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00012000
Tank Used for: PRODUCT
Type of Fuel: PREMIUM
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor

Tank Num: 004
Container Num: 4
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: DIESEL
Container Construction Thickness: 1/4
Leak Detection: Stock Inventor

Click here for Geo Tracker PDF:

HIST CORTESE:
edr_fname: USA PETROLEUM
edr_fadd1: 7505 BROADWAY
City,State,Zip: LEMON GROVE, CA 92045
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT1368

M74 **USA PETROLEUM** **LUST** **S105032495**
SSE **7505 BROADWAY** **SAN DIEGO CO. SAM** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045** **San Diego Co. HMMD**
0.285 mi. **SWEEPS UST**
1503 ft. **Site 2 of 5 in cluster M** **Cortese**
SAN DIEGO CO LOP
Relative: Lower **CERS**

Actual: 437 ft.

LUST:
No Details: No Details

SAN DIEGO CO. SAM:
Name: USA GASOLINE CORP #246
Address: 7505 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451605
Case Number: H03292-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Remedial Action (Clean-Up)
Date: 1/30/2002
Date Began: 3/31/1989

HMMD SAN DIEGO:
Name: USA GASOLINE CORP #246
Address: 7505 BROADWAY

USA PETROLEUM (Continued) **S105032495**

City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	103292
Business Type:	6HK28
EPA Id Number:	CAL000079037
APN:	480-081-23-00
Last HMMD Inspection:	09/07/2006
Facility Telephone:	619-464-6901
Permit Status:	CHNG
Permit Expiration:	02/29/2008
Date Last Updated:	11/02/2012
Facility Owner:	USA GASOLINE CORP
Facility Mailing Address:	905 RANCHO CONEJO BL
Facility Mailing City:	NEWBURY PARK
Facility Mailing State:	CA
Facility Mailing Zip:	91320-1716
UST Owner:	USA PETROLEUM CORP #246
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 103292 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	SINGLE WALL
Additional Id:	1
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1996-05-20 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name:	UNDERGROUND TANK 103292 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	SINGLE WALL
Additional Id:	2
Capacity Gallons:	12000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1996-05-20 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

USA PETROLEUM (Continued) **S105032495**

UST Name:	UNDERGROUND TANK 103292 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	15000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1996-05-20 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name:	UNDERGROUND TANK 103292 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	DOUBLE WALL
Additional Id:	NT1811, RT3186
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1996-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31C
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/STAND ALONE SENSOR

UST Name:	UNDERGROUND TANK 103292 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	DOUBLE WALL
Additional Id:	NT1811, RT3186
Capacity Gallons:	12000
UST Contents:	MIDGRADE UNLEADED
Other Content Info:	MIDGRADE UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	1996-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	31C
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/STAND ALONE SENSOR

UST Name:	UNDERGROUND TANK 103292 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	DOUBLE WALL
Additional Id:	NT1811, RT3186
Capacity Gallons:	12000

USA PETROLEUM (Continued) **S105032495**

UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1996-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31C
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/STAND ALONE SENSOR

UST Name: UNDERGROUND TANK 103292 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 103292
Tank Type: DOUBLE WALL
Additional Id: NT1811, RT3186
Capacity Gallons: 8000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1996-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31C
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/STAND ALONE SENSOR

Name: USA GASOLINE CORP #246
Address: 7505 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 103292
Business Type: 6HK28
EPA Id Number: CAL000079037
APN: 480-081-23-00
Last HMMD Inspection: 09/07/2006
Facility Telephone: 619-464-6901
Permit Status: CHNG
Permit Expiration: 02/29/2008
Date Last Updated: 11/02/2012
Facility Owner: USA GASOLINE CORP
Facility Mailing Address: 905 RANCHO CONEJO BL
Facility Mailing City: NEWBURY PARK
Facility Mailing State: CA
Facility Mailing Zip: 91320-1716
UST Owner: USA PETROLEUM CORP #246
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

UST:
UST Name: UNDERGROUND TANK 103292 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 103292

USA PETROLEUM (Continued) **S105032495**

Tank Type:	SINGLE WALL
Additional Id:	1
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1996-05-20 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR
UST Name:	UNDERGROUND TANK 103292 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	SINGLE WALL
Additional Id:	2
Capacity Gallons:	12000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1996-05-20 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR
UST Name:	UNDERGROUND TANK 103292 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	15000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1996-05-20 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR
UST Name:	UNDERGROUND TANK 103292 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	103292
Tank Type:	DOUBLE WALL
Additional Id:	NT1811, RT3186
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE

USA PETROLEUM (Continued) **S105032495**

Remove Close Date: Not reported
Year Installed: 1996-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31C
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/STAND ALONE SENSOR

UST Name: UNDERGROUND TANK 103292 T005
Last Update: 2012-11-02 14:17:38
Permit Number: 103292
Tank Type: DOUBLE WALL
Additional Id: NT1811, RT3186
Capacity Gallons: 12000
UST Contents: MIDGRADE UNLEADED
Other Content Info: MIDGRADE UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1996-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31C
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/STAND ALONE SENSOR

UST Name: UNDERGROUND TANK 103292 T006
Last Update: 2012-11-02 14:17:38
Permit Number: 103292
Tank Type: DOUBLE WALL
Additional Id: NT1811, RT3186
Capacity Gallons: 12000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1996-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31C
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/STAND ALONE SENSOR

UST Name: UNDERGROUND TANK 103292 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 103292
Tank Type: DOUBLE WALL
Additional Id: NT1811, RT3186
Capacity Gallons: 8000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 1996-01-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 31C
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ DRY TANK ANNULAR; POSITIVE SHUT-OFF &

USA PETROLEUM (Continued) **S105032495**

FAILSAFE, 3.0LLD; UDC W/STAND ALONE SENSOR

SWEEPS UST:

Name:	USA PETROLEUM CORP #246
Address:	7505 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	3292
Number:	9
Board Of Equalization:	44-021828
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-003292-000001
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	3

Name:	USA PETROLEUM CORP #246
Address:	7505 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	3292
Number:	9
Board Of Equalization:	44-021828
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-003292-000002
Tank Status:	A
Capacity:	12000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	LEADED
Number Of Tanks:	Not reported

Name:	USA PETROLEUM CORP #246
Address:	7505 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	3292
Number:	9
Board Of Equalization:	44-021828
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-003292-000003
Tank Status:	A

USA PETROLEUM (Continued) **S105032495**

Capacity:	15000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported

CORTESE:

Name:	USA GASOLINE CORP #246
Address:	7505 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451605
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607300209
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	OPEN - REMEDIATION
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

SAN DIEGO CO LOP:

Name:	USA GASOLINE CORP #246
Address:	7505 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1989-LSAM-H03292-001
Record Status:	Completed
Opened Date:	03/31/1989
Parcel Number:	480-081-23-00
Case Type:	LOP - Local Oversight Program
Historical Name:	USA GASOLINE 246 LEMON GROVE
SWRCB Global ID:	T0607300209
Funding:	S - LOP State Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	03/31/1989
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7423204
Longitude:	-117.0360740
X MapCoord:	6319955.295

USA PETROLEUM (Continued) **S105032495**

Y MapCoord: 1850790.594

CERS:
Name: USA GASOLINE CORP #246
Address: 7505 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451605
Site ID: 246655
CERS ID: T0607300209
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: LALITHA THOTAKURA - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213002,

M75 **SAN DIEGO GLASS & PAINT COMPAN** **LUST** **U001571855**
SSE **7551 BROADWAY** **San Diego Co. HMMD** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **SWEEPS UST**
0.299 mi. **HIST UST**
1580 ft. **Site 3 of 5 in cluster M** **Cortese**
CERS

Relative:
Lower

Actual:
435 ft.

LUST:
Name: SAN DIEGO GLASS & PAINT COMPAN
Address: 7551 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451605
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302808
Global Id: T0607302808
Latitude: 32.74233
Longitude: -117.035586
Status: Completed - Case Closed
Status Date: 12/17/1996
Case Worker: Not reported
RB Case Number: 9UT51
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H20567-001
Potential Media Affect: Soil
Potential Contaminants of Concern: Kerosene
Site History: Not reported

LUST:
Global Id: T0607302808
Action Type: ENFORCEMENT
Date: 12/17/1996
Action: Closure/No Further Action Letter

Global Id: T0607302808
Action Type: Other

SAN DIEGO GLASS & PAINT COMPAN (Continued) **U001571855**

Date: 11/20/1986
Action: Leak Began

Global Id: T0607302808
Action Type: Other
Date: 11/20/1986
Action: Leak Discovery

Global Id: T0607302808
Action Type: Other
Date: 12/11/1986
Action: Leak Reported

Global Id: T0607302808
Action Type: ENFORCEMENT
Date: 12/11/1986
Action: Notice of Responsibility

Global Id: T0607302808
Action Type: Other
Date: 12/11/1986
Action: Leak Stopped

Global Id: T0607302808
Action Type: ENFORCEMENT
Date: 10/29/1996
Action: Closure/No Further Action Letter - #H20567-001

LUST:
Global Id: T0607302808
Status: Open - Case Begin Date
Status Date: 11/20/1986

Global Id: T0607302808
Status: Completed - Case Closed
Status Date: 12/17/1996

HMMD SAN DIEGO:
Name: SAN DIEGO GLASS & PAINT COMPAN
Address: 7551 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 120567
Business Type: Not reported
EPA Id Number: Not reported
APN: 480-081-22-00
Last HMMD Inspection: Not reported
Facility Telephone: 619-463-4438
Permit Status: INAC
Permit Expiration: 06/30/2002
Date Last Updated: 11/02/2012
Facility Owner: SAN DIEGO GLASS & PAINT COMPAN
Facility Mailing Address: P O BOX 991
Facility Mailing City: SAN DIEGO
Facility Mailing State: CA
Facility Mailing Zip: 92112-0991

SAN DIEGO GLASS & PAINT COMPAN (Continued) **U001571855**

UST Owner:	SAN DIEGO GLASS & PAINT COMPAN
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 120567 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	120567
Tank Type:	SINGLE WALL
Additional Id:	1
Capacity Gallons:	1000
UST Contents:	Not reported
Other Content Info:	SEE FILE FOR CONTENTS
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

SWEEPS UST:

Name:	SAN DIEGO GLASS & PAINT COMPAN
Address:	7551 BROADWAY
City:	LEMON GROVE
Status:	Not reported
Comp Number:	20567
Number:	Not reported
Board Of Equalization:	44-021644
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-020567-000001
Tank Status:	Not reported
Capacity:	1000
Active Date:	Not reported
Tank Use:	CHEMICAL
STG:	PRODUCT
Content:	Not reported
Number Of Tanks:	1

HIST UST:

Name:	SAN DIEGO GLASS & PAINT COMPAN
Address:	7551 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000014922
Facility Type:	Other

SAN DIEGO GLASS & PAINT COMPAN (Continued) **U001571855**

Other Type:	RETAIL HOME CENTER C
Contact Name:	WAYNE SMITH-MANAGER
Telephone:	6194634438
Owner Name:	SAN DIEGO GLASS & PAINT COMPAN
Owner Address:	1827 MAIN STREET
Owner City,St,Zip:	SAN DIEGO, CA 92113
Total Tanks:	0001
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00001000
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

CORTESE:

Name:	SAN DIEGO GLASS & PAINT COMPAN
Address:	7551 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451605
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607302808
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

CERS:

Name:	SAN DIEGO GLASS & PAINT COMPAN
Address:	7551 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451605
Site ID:	251118
CERS ID:	T0607302808
CERS Description:	Leaking Underground Storage Tank Cleanup Site

M76 **SAN DIEGO GLASS AND PAINT** **LUST** **S104164151**
SSE **7551 BROADWAY** **HIST CORTESE** **N/A**
1/4-1/2 **LEMON GROVE, CA 92113**
0.299 mi.
1580 ft. **Site 4 of 5 in cluster M**

Relative:
Lower

Actual:
435 ft.

LUST REG 9:

Region:	9
Status:	Case Closed
Case Number:	9UT51
Local Case:	H20567-001
Substance:	Kerosene
Qty Leaked:	Not reported
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Tank
Cause:	Corrosion
Lead Agency:	Local Agency
Case Type:	Other ground water affected
Date Found:	11/20/1986
Date Stopped:	11/20/1986
Confirm Date:	01/30/1987
Submit Workplan:	Not reported
Prelim Assess:	02/02/1987
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	12/11/1986
Enforce Date:	Not reported
Closed Date:	12/17/96
Enforce Type:	Not reported
Pilot Program:	LOP
Basin Number:	908.22
GW Depth:	8
Beneficial Use:	No Beneficial groundwater use
NPDES Number:	Not reported
Priority:	2B
File Dispn:	File discarded, case closed
Interim Remedial Actions:	Yes
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

HIST CORTESE:

edr_fname:	SAN DIEGO GLASS AND PAINT
edr_fadd1:	7551 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92113
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT51

M77 **SAN DIEGO GLASS AND PAINT COMPAN** **SAN DIEGO CO. SAM** **S108407222**
SSE **7551 BROADWAY** **HIST UST** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045** **SAN DIEGO CO LOP**
0.299 mi.
1580 ft. **Site 5 of 5 in cluster M**

Relative:
Lower

Actual:
435 ft.

SAN DIEGO CO. SAM:

Name:	SAN DIEGO GLASS & PAINT COMPAN
Address:	7551 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451605
Case Number:	H20567-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**LOP - Federal Fund**
Facility Type:	Soils Only
Facility Status:	Closed Case
Date:	12/17/1996
Date Began:	11/20/1986

HIST UST:

Name:	SAN DIEGO GLASS AND PAINT COMPAN
Address:	7551 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
File Number:	0002f289
URL:	https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002f289.pdf
Region:	Not reported
Facility ID:	Not reported
Facility Type:	Not reported
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	Not reported
Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported

Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

SAN DIEGO CO LOP:

Name:	SAN DIEGO GLASS & PAINT COMPAN
Address:	7551 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1986-LSAM-H20567-001
Record Status:	Completed
Opened Date:	12/11/1986
Parcel Number:	480-081-22-00
Case Type:	LOP - Local Oversight Program
Historical Name:	SAN DIEGO GLASS AND PAINT
SWRCB Global ID:	T0607302808
Funding:	F - LOP Federal Fund

SAN DIEGO GLASS AND PAINT COMPAN (Continued) **S108407222**

Lead Agency:	DEH/SAM
Lead Agency Date:	10/10/1990
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7423295
Longitude:	-117.0355861
X MapCoord:	6320105.472
Y MapCoord:	1850792.300

N78 **ECONO LUBE N TUNE** **Cortese** **S113025904**
SE **7608 BROADWAY** **HAZNET** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **HWTS**
0.320 mi.
1692 ft. **Site 1 of 9 in cluster N**

Relative: **Lower**

Actual: **439 ft.**

CORTESE:

Name:	ECONO LUBE N TUNE
Address:	7608 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451606
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607302957
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HAZNET:

Name:	ECONO LUBE N TUNE
Address:	7608 BROADWAY
Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 919451606
Contact:	BUENA VISTA, LEMON GROVE LTD
Telephone:	Not reported
Mailing Name:	Not reported
Mailing Address:	7608 BROADWAY
Year:	1999
Gepaid:	CAL000012761

ECONO LUBE N TUNE (Continued) **S113025904**

TSD EPA ID:	AZC980813022
CA Waste Code:	134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method:	R01 - Recycler
Tons:	0.84

Additional Info:

Year:	1999
Gen EPA ID:	CAL000012761
Shipment Date:	19990325
Creation Date:	5/27/1999 0:00:00
Receipt Date:	19990330
Manifest ID:	98707839
Trans EPA ID:	CAL000011205
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	AZC980813022
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.84
Waste Quantity:	200
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

HWTS:

Name:	ECONO LUBE N TUNE
Address:	7608 BROADWAY
Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 91945
EPA ID:	CAL000012761
Inactive Date:	06/30/2002
Create Date:	11/14/1989
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	7608 BROADWAY
Mailing Address 2:	Not reported
Mailing City,State,Zip:	LEMON GROVE, CA 919451606
Owner Name:	HYUNG LEE OWNER
Owner Address:	7608 BROADWAY
Owner Address 2:	Not reported
Owner City,State,Zip:	LEMON GROVE, CA 919451606
Contact Name:	BUENA VISTA, LEMON GROVE LTD
Contact Address:	7608 BROADWAY
Contact Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 919451606

ECONO LUBE N TUNE (Continued) **S113025904**

Facility Status:	Inactive
Facility Type:	PERMANENT
Category:	STATE
Latitude:	32.742718
Longitude:	-117.034077

N79 **WORLD OIL ENVIRONMENTAL SERVICES** **RCRA-SQG** **1000317961**
SE **7608 BROADWAY** **LUST** **CAD981371792**
1/4-1/2 **LEMON GROVE, CA 91945** **SAN DIEGO CO. SAM**
0.320 mi. **CPS-SLIC**
1692 ft. **Site 2 of 9 in cluster N** **San Diego Co. HMMD**
SWEEPS UST
Relative: **FINDS**
Lower **ECHO**
HIST CORTESE
Actual:
439 ft.

RCRA Listings:

Date Form Received by Agency:		19960901
Handler Name:	ECONO LUBE N TUNE	
Handler Address:		7608 BROADWAY
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAD981371792
Contact Name:		Not reported
Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		CA
State District:		4
Mailing Address:		7608 BRAODWAY
Mailing City,State,Zip:		LEMON GROVE, CA 92045
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	NOT REQUIRED	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20020917
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JASPER ANTHONY SPANO	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Owner/Operator Name: NOT REQUIRED
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, ME 99999
Owner/Operator Telephone: 415-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19960901
Handler Name: ECONO LUBE N TUNE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860131
Handler Name: ECONO LUBE N TUNE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19930331
Actual Return to Compliance Date: 19940901
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19940901
Actual Return to Compliance Date: 19990901
Return to Compliance Qualifier: Not Resolved
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19911113
Actual Return to Compliance Date:	19930331
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19930331
Evaluation Responsible Agency:	State Contractor/Grantee
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19940901
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Evaluation Date:	19940901
Evaluation Responsible Agency:	State Contractor/Grantee
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19990901
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19911113
Evaluation Responsible Agency:	State Contractor/Grantee
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R9STA
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19930331
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

LUST:

Name:	ECONO LUBE N TUNE
Address:	7608 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451606
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607302957
Global Id:	T0607302957
Latitude:	32.742944
Longitude:	-117.03398
Status:	Completed - Case Closed
Status Date:	01/31/1990
Case Worker:	Not reported
RB Case Number:	9UT688
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	H14708-001
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Waste Oil / Motor / Hydraulic / Lubricating
Site History:	Not reported

LUST:

Global Id:	T0607302957
Action Type:	Other
Date:	12/02/1986
Action:	Leak Began

Global Id:	T0607302957
Action Type:	Other
Date:	12/02/1986

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Action: Leak Discovery

Global Id: T0607302957
Action Type: Other
Date: 12/02/1986
Action: Leak Reported

Global Id: T0607302957
Action Type: Other
Date: 12/02/1986
Action: Leak Stopped

LUST:
Global Id: T0607302957
Status: Open - Case Begin Date
Status Date: 12/02/1986

Global Id: T0607302957
Status: Completed - Case Closed
Status Date: 01/31/1990

LUST REG 9:
Region: 9
Status: Case Closed
Case Number: 9UT688
Local Case: H14708-001
Substance: Waste Oil
Qty Leaked: Not reported
Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site
Local Agency: San Diego
How Found: Tank Closure
How Stopped: Close Tank
Source: Tank
Cause: Corrosion
Lead Agency: Local Agency
Case Type: Other ground water affected
Date Found: 11/26/1986
Date Stopped: 12/02/1986
Confirm Date: 12/02/1986
Submit Workplan: Not reported
Prelim Assess: 04/13/1987
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 12/02/1986
Enforce Date: Not reported
Closed Date: 1/31/90
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 908.22
GW Depth: 5
Beneficial Use: No Beneficial groundwater use
NPDES Number: Not reported

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Priority: Medium priority
File Dispn: File discarded, case closed
Interim Remedial Actions: Yes
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

SAN DIEGO CO. SAM:
Name: ECONO LUBE N TUNE
Address: 7608 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451606
Case Number: H14708-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Closed Case
Date: 1/31/1990
Date Began: 12/2/1986

Name: ECONO LUBE N TUNE
Address: 7608 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451606
Case Number: H14708-002
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Closed Case
Date: 1/30/2002
Date Began: 5/30/1996

CPS-SLIC:
Name: ECONO LUBE N TUNE
Address: 7608 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451606
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 01/30/2002
Global Id: T0608199117
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H14708-002
Latitude: 32.742961
Longitude: -117.033981
Case Type: Cleanup Program Site
Case Worker: SW
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

HMMD SAN DIEGO:
Name: ECONO LUBE N TUNE
Address: 7608 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Permit Number:	207947
Business Type:	6HK26
EPA Id Number:	CAL000289893
APN:	480-042-22-00
Last HMMD Inspection:	05/15/2007
Facility Telephone:	619-461-6333
Permit Status:	INAC
Permit Expiration:	04/30/2008
Date Last Updated:	11/02/2012
Facility Owner:	ECONO LUBE N TUNE
Facility Mailing Address:	7608 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 114708 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	207947
Tank Type:	DOUBLE WALL
Additional Id:	01
Capacity Gallons:	500
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	CLOSED
Remove Close Date:	1999-03-29 00:00:00
Year Installed:	1986-01-01 00:00:00
Pipe Type:	UNKNOWN
Delivery System:	GRAVITY
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

Name:	ECONO LUBE N TUNE
Address:	7608 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	207947
Business Type:	6HK26
EPA Id Number:	CAL000289893
APN:	480-042-22-00
Last HMMD Inspection:	05/15/2007
Facility Telephone:	619-461-6333
Permit Status:	INAC
Permit Expiration:	04/30/2008
Date Last Updated:	11/02/2012
Facility Owner:	ECONO LUBE N TUNE
Facility Mailing Address:	7608 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

UST:
UST Name: UNDERGROUND TANK 114708 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 207947
Tank Type: DOUBLE WALL
Additional Id: 01
Capacity Gallons: 500
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1999-03-29 00:00:00
Year Installed: 1986-01-01 00:00:00
Pipe Type: UNKNOWN
Delivery System: GRAVITY
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

Name: ECONO LUBE N TUNE
Address: 7608 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 207947
Business Type: 6HK26
EPA Id Number: CAL000289893
APN: 480-042-22-00
Last HMMD Inspection: 05/15/2007
Facility Telephone: 619-461-6333
Permit Status: INAC
Permit Expiration: 04/30/2008
Date Last Updated: 11/02/2012
Facility Owner: ECONO LUBE N TUNE
Facility Mailing Address: 7608 BROADWAY
Facility Mailing City: LEMON GROVE
Facility Mailing State: CA
Facility Mailing Zip: 91945
UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

UST:
UST Name: UNDERGROUND TANK 114708 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 207947
Tank Type: DOUBLE WALL
Additional Id: 01

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Capacity Gallons: 500
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1999-03-29 00:00:00
Year Installed: 1986-01-01 00:00:00
Pipe Type: UNKNOWN
Delivery System: GRAVITY
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

Name: ECONO LUBE N TUNE
Address: 7608 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 207947
Business Type: 6HK26
EPA Id Number: CAL000289893
APN: 480-042-22-00
Last HMMD Inspection: 05/15/2007
Facility Telephone: 619-461-6333
Permit Status: INAC
Permit Expiration: 04/30/2008
Date Last Updated: 11/02/2012
Facility Owner: ECONO LUBE N TUNE
Facility Mailing Address: 7608 BROADWAY
Facility Mailing City: LEMON GROVE
Facility Mailing State: CA
Facility Mailing Zip: 91945
UST Owner: Not reported
Handle Regulated Hazmat: Y
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

UST:
UST Name: UNDERGROUND TANK 114708 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 207947
Tank Type: DOUBLE WALL
Additional Id: 01
Capacity Gallons: 500
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1999-03-29 00:00:00
Year Installed: 1986-01-01 00:00:00
Pipe Type: UNKNOWN
Delivery System: GRAVITY
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

Name: ECONO LUBE N TUNE

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Address:	7608 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	114708
Business Type:	6HK26
EPA Id Number:	CAD981371792
APN:	480-042-22-00
Last HMMD Inspection:	04/16/2004
Facility Telephone:	619-461-6333
Permit Status:	INAC
Permit Expiration:	02/28/2005
Date Last Updated:	11/02/2012
Facility Owner:	KIRAN SHAH
Facility Mailing Address:	7608 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945-
UST Owner:	ECONO LUBE N TUNE INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Violations Inactive Permits:

Permit Number:	114708
Update Date:	11/02/2012
Inspection Date:	04/16/2004
Violation Code:	6HV0131
Violation:	UPF Permit NOT OBTAINED for HAZWASTE
Violation Citation:	A Unified Program Facility permit has not been obtained for the generation of hazardous waste. 68.905
Activity:	Inactive Permit

Permit Number:	114708
Update Date:	11/02/2012
Inspection Date:	04/16/2004
Violation Code:	6HV1001
Violation:	NO UPF PERMIT FOR HAZMATS
Violation Citation:	A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity:	Inactive Permit

Permit Number:	114708
Update Date:	11/02/2012
Inspection Date:	04/16/2004
Violation Code:	6HV0210
Violation:	DID NOT CLEAN SPILL TO FLOOR
Violation Citation:	Failure to clean up hazardous waste off of floor surface. 66262.10b
Activity:	Inactive Permit

Permit Number:	114708
Update Date:	11/02/2012
Inspection Date:	04/16/2004
Violation Code:	6HV0135
Violation:	MANIFESTS/RECEIPTS FOR 3 YEARS NOT ONSIT
Violation Citation:	Hazardous waste manifests/receipts for 3 years are not maintained onsite to document proper disposal of hazardous waste. CCR 66262.40(a)

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

& 25160.2(b)(3)
Activity: Inactive Permit

Permit Number: 114708
Update Date: 11/02/2012
Inspection Date: 04/16/2004
Violation Code: 6HV0201
Violation: WASTE CONTAINER NOT CLOSED
Violation Citation: Hazardous waste containers are not kept closed while in storage. CCR 66265.173(a)
Activity: Inactive Permit

Permit Number: 114708
Update Date: 11/02/2012
Inspection Date: 04/16/2004
Violation Code: 6HV0202
Violation: WASTE CONTAINER W/O LABELS
Violation Citation: Hazardous waste containers &/or tanks are missing labels, accumulation date and/or are improperly labeled. CCR 66262.34(a)(2); 66262.34(a)(3) & 66262.34(f)
Activity: Inactive Permit

Permit Number: 114708
Update Date: 11/02/2012
Inspection Date: 04/16/2004
Violation Code: 6HV1004
Violation: HMBP NOT SUBMITTED TO HMD
Violation Citation: Hazardous Materials Handler has not submitted a completed Business Plan to the HMMD. HSC 25505(a)
Activity: Inactive Permit

UST:
UST Name: UNDERGROUND TANK 114708 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 114708
Tank Type: DOUBLE WALL
Additional Id: 01
Capacity Gallons: 500
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: CLOSED
Remove Close Date: 1999-03-29 00:00:00
Year Installed: 1986-01-01 00:00:00
Pipe Type: UNKNOWN
Delivery System: GRAVITY
Monitor Code: 21
UST Monitor Method: DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

SWEEPS UST:
Name: ECONO LUBE N TUNE
Address: 7608 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 14708

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Number: 9
Board Of Equalization: 44-022883
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-014708-000001
Tank Status: A
Capacity: 550
Active Date: Not reported
Tank Use: PETROLEUM
STG: P
Content: Not reported
Number Of Tanks: 1

FINDS:
Registry ID: 110006469507

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
STATE MASTER
Registry ID: 110071257701

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000317961
Registry ID: 110006469507
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110006469507
Name: ECONO LUBE N TUNE
Address: 7608 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945

HIST CORTESE:
edr_fname: ECONO-LUBE
edr_fadd1: 7608 BROADWAY
City,State,Zip: LEMON GROVE, CA 92045
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA

WORLD OIL ENVIRONMENTAL SERVICES (Continued) **1000317961**

Reg Id: 9UT688

O80 **Notify 65** **S100178257**
SE **7656 LEMON ST** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945**
0.323 mi.
1706 ft. **Site 1 of 3 in cluster O**

Relative:
Lower

Actual:
448 ft.

NOTIFY 65:

Name:	Not reported
Address:	7656 LEMON ST
City,State,Zip:	LEMON GROVE, CA 91945-1619
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

P81 **CORRAL FORD** **LUST** **1000353335**
SW **7220 BROADWAY** **SWEEPS UST** **CAD055699128**
1/4-1/2 **LEMON GROVE, CA 91945** **HIST UST**
0.329 mi. **RCRA NonGen / NLR**
1736 ft. **Site 1 of 9 in cluster P** **FINDS**
ECHO

Relative:
Lower

HIST CORTESE
HAZNET

Actual:
414 ft.

HWTS

LUST REG 9:

Region:	9
Status:	Case Closed
Case Number:	9UT2731
Local Case:	H12503-001
Substance:	Waste Oil
Qty Leaked:	Not reported
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Tank
Cause:	Corrosion
Lead Agency:	Local Agency
Case Type:	Aquifer affected
Date Found:	03/31/1994
Date Stopped:	03/31/1994
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	03/31/1994
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported

CORRAL FORD (Continued) **1000353335**

Began Monitor: Not reported
Release Date: 04/07/1994
Enforce Date: Not reported
Closed Date: 1/14/95
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 909.21
GW Depth: 8
Beneficial Use: Municipal groundwater use
NPDES Number: Not reported
Priority: 2B
File Dispn: File discarded, case closed
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

SWEEPS UST:
Name: CORRAL FORD
Address: 7220 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12503
Number: 9
Board Of Equalization: 44-022586
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012503-000001
Tank Status: A
Capacity: 550
Active Date: Not reported
Tank Use: OIL
STG: P
Content: Not reported
Number Of Tanks: 2

Name: CORRAL FORD
Address: 7220 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12503
Number: 9
Board Of Equalization: 44-022586
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012503-000002
Tank Status: A
Capacity: 550
Active Date: Not reported
Tank Use: PETROLEUM
STG: W
Content: Not reported
Number Of Tanks: Not reported

CORRAL FORD (Continued) **1000353335**

HIST UST:

Name:	CORRAL FORD
Address:	7220 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
File Number:	0002b00a
URL:	https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002b00a.pdf
Region:	STATE
Facility ID:	00000068712
Facility Type:	Other
Other Type:	AUTO DEALER
Contact Name:	WARREN ECKER
Telephone:	6194657220
Owner Name:	CORRAL FORD
Owner Address:	7220 BROADWAY
Owner City,St,Zip:	LEMON GROVE, CA 92045
Total Tanks:	0002
Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	PRODUCT
Type of Fuel:	Not reported
Container Construction Thickness:	X
Leak Detection:	Visual, Stock Inventor
Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00000500
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	Visual

Click here for Geo Tracker PDF:

RCRA Listings:

Date Form Received by Agency:		19990907
Handler Name:	CORRAL FORD	
Handler Address:		7220 BROADWAY
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAD055699128
Contact Name:		MIKE OGDEN
Contact Address:		6828 FEDERAL BLVD
Contact City,State,Zip:		LEMON GROVE, CA 91945
Contact Telephone:		619-582-1900
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Other
Federal Waste Generator Description:		Not a generator, verified
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported

CORRAL FORD (Continued) **1000353335**

Active Site Indicator:		Not reported
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		7220 BROADWAY
Mailing City,State,Zip:		LEMON GROVE, CA 92045
Owner Name:	CUNNINGHAM	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking
Environmental Control Indicator:		No
Institutional Control Indicator:		No
Human Exposure Controls Indicator:		N/A
Groundwater Controls Indicator:		N/A
Operating TSDF Universe:		Not reported
Full Enforcement Universe:		Not reported
Significant Non-Complier Universe:		No
Unaddressed Significant Non-Complier Universe:		No
Addressed Significant Non-Complier Universe:		No
Significant Non-Complier With a Compliance Schedule Universe:		No
Financial Assurance Required:	Not reported	
Handler Date of Last Change:		20020917

CORRAL FORD (Continued) **1000353335**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CUNNINGHAM	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NOT REQUIRED	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19960901
Handler Name: CORRAL FORD	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19990907
Handler Name: CORRAL FORD	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CORRAL FORD (Continued) **1000353335**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44111
NAICS Description: NEW CAR DEALERS

Facility Has Received Notices of Violation:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19921210
Actual Return to Compliance Date: 19971210
Return to Compliance Qualifier: Not Resolved
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19921210
Evaluation Responsible Agency: State Contractor/Grantee
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R9STA
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19971210

CORRAL FORD (Continued) **1000353335**

Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110006467395

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000353335
Registry ID:	110006467395
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006467395
Name:	CORRAL FORD
Address:	7220 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945

HIST CORTESE:

edr_fname:	CORRAL FORD
edr_fadd1:	7220 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT2731

HAZNET:

Name:	CORRAL FORD
Address:	7220 BROADWAY
Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 919450000
Contact:	WARREN ECKER
Telephone:	6195821900
Mailing Name:	Not reported
Mailing Address:	6828 FEDERAL BLVD
Year:	1997
Gepaid:	CAD055699128
TSD EPA ID:	CAD008302903
CA Waste Code:	461 - Paint sludge
Disposal Method:	R01 - Recycler
Tons:	0.3752

CORRAL FORD (Continued) **1000353335**

Year: 1996
Gepaid: CAD055699128
TSD EPA ID: CAD008302903
CA Waste Code: 461 - Paint sludge
Disposal Method: R01 - Recycler
Tons: 0.4586

Year: 1995
Gepaid: CAD055699128
TSD EPA ID: CAD008302903
CA Waste Code: 461 - Paint sludge
Disposal Method: R01 - Recycler
Tons: 0.221

Year: 1995
Gepaid: CAD055699128
TSD EPA ID: CAT080010101
CA Waste Code: 291 - Latex waste
Disposal Method: H01 - Transfer Station
Tons: 0.0125

Year: 1994
Gepaid: CAD055699128
TSD EPA ID: CAD008302903
CA Waste Code: 461 - Paint sludge
Disposal Method: R01 - Recycler
Tons: 0.2293

Year: 1994
Gepaid: CAD055699128
TSD EPA ID: CAD028409019
CA Waste Code: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method: -
Tons: 1.251

Year: 1994
Gepaid: CAD055699128
TSD EPA ID: CAD028409019
CA Waste Code: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.)
Disposal Method: T01 - Treatment, Tank
Tons: 1.4595

Year: 1994
Gepaid: CAD055699128
TSD EPA ID: CAD008302903
CA Waste Code: 461 - Paint sludge
Disposal Method: -
Tons: 0.2293

Year: 1993
Gepaid: CAD055699128
TSD EPA ID: CAD008302903
CA Waste Code: 461 - Paint sludge
Disposal Method: -
Tons: 0.2293

Year: 1993

CORRAL FORD (Continued) **1000353335**

Gepaid:	CAD055699128
TSD EPA ID:	CAD008302903
CA Waste Code:	461 - Paint sludge
Disposal Method:	R01 - Recycler
Tons:	0.2919

Click this hyperlink while viewing on your computer to access
14 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:

Year:	1997
Gen EPA ID:	CAD055699128
Shipment Date:	19970820
Creation Date:	12/11/1997 0:00:00
Receipt Date:	19970822
Manifest ID:	96733752
Trans EPA ID:	CAD980675789
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008302903
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	461 - Paint sludge
RCRA Code:	F003
Meth Code:	R01 - Recycler
Quantity Tons:	0.1459
Waste Quantity:	35
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19970617
Creation Date:	12/4/1997 0:00:00
Receipt Date:	19970620
Manifest ID:	96809148
Trans EPA ID:	CAD980675789
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008302903
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD008302903
TSDF Alt Name:	Not reported
Waste Code Description:	461 - Paint sludge
RCRA Code:	F003
Meth Code:	R01 - Recycler
Quantity Tons:	0.2293
Waste Quantity:	55
Quantity Unit:	G
Additional Code 1:	Not reported

CORRAL FORD (Continued) **1000353335**

Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 1996
Gen EPA ID: CAD055699128

Shipment Date: 19960717
Creation Date: 5/20/1997 0:00:00
Receipt Date: 19960719
Manifest ID: 95730854
Trans EPA ID: CAD980675789
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008302903
Trans Name: Not reported
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 461 - Paint sludge
RCRA Code: F003
Meth Code: R01 - Recycler
Quantity Tons: 0.2293
Waste Quantity: 55
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 19960221
Creation Date: 10/10/1996 0:00:00
Receipt Date: 19960222
Manifest ID: 96223301
Trans EPA ID: CAD980675789
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008302903
Trans Name: Not reported
TSDF Alt EPA ID: CAD008302903
TSDF Alt Name: Not reported
Waste Code Description: 461 - Paint sludge
RCRA Code: F003
Meth Code: R01 - Recycler
Quantity Tons: 0.2293
Waste Quantity: 55
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

CORRAL FORD (Continued) **1000353335**

Additional Info:

Year:	1995
Gen EPA ID:	CAD055699128
Shipment Date:	19951228
Creation Date:	7/29/1996 0:00:00
Receipt Date:	19951228
Manifest ID:	95467933
Trans EPA ID:	Not reported
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT080010101
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	291 - Latex waste
RCRA Code:	Not reported
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.0125
Waste Quantity:	3
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19950620
Creation Date:	4/2/1996 0:00:00
Receipt Date:	19950621
Manifest ID:	95622254
Trans EPA ID:	CAD980675789
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008302903
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD008302903
TSDF Alt Name:	Not reported
Waste Code Description:	461 - Paint sludge
RCRA Code:	F003
Meth Code:	R01 - Recycler
Quantity Tons:	0.221
Waste Quantity:	53
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	1994
Gen EPA ID:	CAD055699128

CORRAL FORD (Continued) **1000353335**

Shipment Date:	19940817
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940819
Manifest ID:	93451507
Trans EPA ID:	CAD980675789
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008302903
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD008302903
TSDF Alt Name:	Not reported
Waste Code Description:	461 - Paint sludge
RCRA Code:	F003
Meth Code:	R01 - Recycler
Quantity Tons:	0.2293
Waste Quantity:	55
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19940607
Creation Date:	3/26/1996 0:00:00
Receipt Date:	19940609
Manifest ID:	93111875
Trans EPA ID:	CAD982525024
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD028409019
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD028409019
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	D001
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	0.2085
Waste Quantity:	50
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	19940606
Creation Date:	3/26/1996 0:00:00
Receipt Date:	Not reported
Manifest ID:	93111876
Trans EPA ID:	CAD982525024
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD028409019

CORRAL FORD (Continued) **1000353335**

Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	D001
Meth Code:	- Not reported
Quantity Tons:	1.251
Waste Quantity:	300
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940331
Creation Date:	10/5/1995 0:00:00
Receipt Date:	19940406
Manifest ID:	93270955
Trans EPA ID:	CAD982525024
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD028409019
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	D001
Meth Code:	T01 - Treatment, Tank
Quantity Tons:	1.251
Waste Quantity:	300
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	19940119
Creation Date:	9/14/1995 0:00:00
Receipt Date:	Not reported
Manifest ID:	93342093
Trans EPA ID:	CAD980675789
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008302903
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	461 - Paint sludge
RCRA Code:	F003
Meth Code:	- Not reported
Quantity Tons:	0.2293
Waste Quantity:	55
Quantity Unit:	G

CORRAL FORD (Continued) **1000353335**

Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Additional Info:
Year: 1993
Gen EPA ID: CAD055699128

Shipment Date: 19930617
Creation Date: 9/9/1995 0:00:00
Receipt Date: 19930622
Manifest ID: 93154808
Trans EPA ID: CAD980675789
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008302903
Trans Name: Not reported
TSDF Alt EPA ID: CAD008302903
TSDF Alt Name: Not reported
Waste Code Description: 461 - Paint sludge
RCRA Code: F003
Meth Code: R01 - Recycler
Quantity Tons: 0.2919
Waste Quantity: 70
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 19930217
Creation Date: 9/6/1995 0:00:00
Receipt Date: Not reported
Manifest ID: 92340136
Trans EPA ID: CAD980675789
Trans Name: Not reported
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008302903
Trans Name: Not reported
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 461 - Paint sludge
RCRA Code: Not reported
Meth Code: - Not reported
Quantity Tons: 0.2293
Waste Quantity: 55
Quantity Unit: G
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

CORRAL FORD (Continued) **1000353335**

HWTS:

Name:	CORRAL FORD
Address:	7220 BROADWAY
Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 91945
EPA ID:	CAD055699128
Inactive Date:	06/30/1998
Create Date:	04/10/1987
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	6828 FEDERAL BLVD
Mailing Address 2:	Not reported
Mailing City,State,Zip:	LEMON GROVE, CA 919451314
Owner Name:	CORRAL FORD
Owner Address:	6828 FEDERAL BLVD
Owner Address 2:	Not reported
Owner City,State,Zip:	LEMON GROVE, CA 919451314
Contact Name:	WARREN ECKER
Contact Address:	INACT PER 98VQ FINAL NOTICE
Contact Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 919451314
Facility Status:	Inactive
Facility Type:	PERMANENT
Category:	FEDERAL
Latitude:	32.742648
Longitude:	-117.042518

N82 **UNOCAL SERVICE STATION** **LUST** **S102440255**
SE **7593 BROADWAY** **HIST CORTESE** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045**
0.331 mi.
1750 ft. **Site 3 of 9 in cluster N**

Relative: **Lower**
Actual: **435 ft.**

LUST REG 9:

Region:	9
Status:	Case Closed
Case Number:	9UT671
Local Case:	H13304-001
Substance:	0
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Other Source
Cause:	Overfill
Lead Agency:	Local Agency
Case Type:	Soil only
Date Found:	05/04/1987
Date Stopped:	05/04/1987
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	11/02/1987
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported

UNOCAL SERVICE STATION (Continued) **S102440255**

Release Date: 05/05/1987
Enforce Date: Not reported
Closed Date: 2/16/88
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 908.22
GW Depth: Not reported
Beneficial Use: Not reported
NPDES Number: Not reported
Priority: Low priority. Priority ranking can change over time.
File Dispn: File discarded, case closed
Interim Remedial Actions: Yes
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

HIST CORTESE:
edr_fname: UNOCAL SERVICE STATION
edr_fadd1: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 92045
Region: CORTESE
Facility County Code: 37
Reg By: LTNKA
Reg Id: 9UT671

N83 **UNION OIL SERVICE STATION 369** **LUST** **U001571858**
SE **7593 BROADWAY** **CPS-SLIC** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045** **HIST UST**
0.331 mi.
1750 ft. **Site 4 of 9 in cluster N**

Relative: **Lower**
Actual: **435 ft.**

LUST:
Name: SAN DIEGO MOTORS
Address: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451605
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607399191
Global Id: T0607399191
Latitude: 32.7422958855044
Longitude: -117.034455986005
Status: Completed - Case Closed
Status Date: 03/01/2002
Case Worker: Not reported
RB Case Number: 9UT3970
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H13304-002
Potential Media Affect: Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern: Waste Oil / Motor / Hydraulic / Lubricating
Site History: Not reported

LUST:
Global Id: T0607399191
Action Type: ENFORCEMENT
Date: 03/01/2002
Action: Closure/No Further Action Letter

Global Id: T0607399191

UNION OIL SERVICE STATION 369 (Continued) **U001571858**

Action Type: Other
Date: 06/02/1999
Action: Leak Began

Global Id: T0607399191
Action Type: Other
Date: 06/08/1999
Action: Leak Reported

Global Id: T0607399191
Action Type: Other
Date: 06/02/1999
Action: Leak Stopped

Global Id: T0607399191
Action Type: Other
Date: 06/02/1999
Action: Leak Discovery

LUST:
Global Id: T0607399191
Status: Open - Case Begin Date
Status Date: 06/02/1999

Global Id: T0607399191
Status: Completed - Case Closed
Status Date: 03/01/2002

CPS-SLIC:
Name: SAN DIEGO MOTORS
Address: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451605
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 02/16/1988
Global Id: T0607302939
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H13304-001
Latitude: 32.742346
Longitude: -117.034541
Case Type: Cleanup Program Site
Case Worker: Not reported
Local Agency: Not reported
RB Case Number: 9UT671
File Location: Local Agency
Potential Media Affected: Not reported
Potential Contaminants of Concern: Not reported
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

HIST UST:
Name: UNION OIL SERVICE STATION 369
Address: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 92045

UNION OIL SERVICE STATION 369 (Continued) **U001571858**

File Number:	0002f494
URL:	https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002f494.pdf
Region:	STATE
Facility ID:	00000017838
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	HARRY D. SLADWICK
Telephone:	6194615132
Owner Name:	UNION OIL COMPANY OF CALIFORNI
Owner Address:	123 CAMINO DELA REINA
Owner City,St,Zip:	SAN DIEGO, CA 92108
Total Tanks:	0003
Tank Num:	001
Container Num:	3699-34
Year Installed:	1954
Tank Capacity:	00000280
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	None
Tank Num:	002
Container Num:	3699-22
Year Installed:	1980
Tank Capacity:	00012000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10
Tank Num:	003
Container Num:	3699-11
Year Installed:	1980
Tank Capacity:	00012000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor, 10

Click here for Geo Tracker PDF:

N84 **SAN DIEGO MOTORS** **SAN DIEGO CO. SAM** **S105112887**
SE **7593 BROADWAY** **San Diego Co. HMMD** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **Cortese**
0.331 mi. **SAN DIEGO CO LOP**
1750 ft. **Site 5 of 9 in cluster N** **CERS**
HWTS

Relative:
Lower

Actual:
435 ft.

SAN DIEGO CO. SAM:

Name:	SAN DIEGO MOTORS
Address:	7593 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451605
Case Number:	H13304-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	Soils Only
Facility Status:	Closed Case

SAN DIEGO MOTORS (Continued) **S105112887**

Date: 2/16/1988
Date Began: 5/5/1987

Name: SAN DIEGO MOTORS
Address: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451605
Case Number: H13304-002
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Closed Case
Date: 3/1/2002
Date Began: 6/2/1999

HMMD SAN DIEGO:
Name: SAN DIEGO MOTORS
Address: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 113304
Business Type: 6HK18
EPA Id Number: CAL000260081
APN: 480-081-07-00
Last HMMD Inspection: 06/14/2011
Facility Telephone: 619-469-2696
Permit Status: EXPR
Permit Expiration: 09/30/2012
Date Last Updated: 11/02/2012
Facility Owner: RAHIM ZADEH/ALI RAZA HASHEMI
Facility Mailing Address: 7593 BROADWAY
Facility Mailing City: LEMON GROVE
Facility Mailing State: AZ
Facility Mailing Zip: 91945-1605
UST Owner: TOSCO, INC.
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 113304
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 221 WASTE OIL & MIXED OIL
Other Information: USED OIL TO AUTO ZONE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 113304
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported

SAN DIEGO MOTORS (Continued) **S105112887**

Hazardous Categories 2: Not reported

UST:

UST Name: UNDERGROUND TANK 113304 T001
Last Update: 2012-11-02 14:17:38
Permit Number: 113304
Tank Type: SINGLE WALL
Additional Id: 3699-34
Capacity Gallons: 280
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1986-11-08 00:00:00
Year Installed: 1954-01-01 00:00:00
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 07
UST Monitor Method: SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name: UNDERGROUND TANK 113304 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 113304
Tank Type: SINGLE WALL
Additional Id: 3699-22
Capacity Gallons: 10000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: 1999-02-06 00:00:00
Year Installed: 1980-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 02
UST Monitor Method: SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANNUALLY

UST Name: UNDERGROUND TANK 113304 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 113304
Tank Type: SINGLE WALL
Additional Id: 3699-11
Capacity Gallons: 10000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: REMOVED
Remove Close Date: 1999-02-06 00:00:00
Year Installed: 1980-01-01 00:00:00
Pipe Type: SINGLE WALL
Delivery System: PRESSURE
Monitor Code: 02
UST Monitor Method: SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANNUALLY

UST Name: UNDERGROUND TANK 113304 T004
Last Update: 2012-11-02 14:17:38
Permit Number: 113304

SAN DIEGO MOTORS (Continued) **S105112887**

Tank Type:	DOUBLE WALL
Additional Id:	4
Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1999-02-06 00:00:00
Year Installed:	1987-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	GRAVITY
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

Name:	SAN DIEGO MOTORS
Address:	7593 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	113304
Business Type:	6HK18
EPA Id Number:	CAL000260081
APN:	480-081-07-00
Last HMMD Inspection:	06/14/2011
Facility Telephone:	619-469-2696
Permit Status:	EXPR
Permit Expiration:	09/30/2012
Date Last Updated:	11/02/2012
Facility Owner:	RAHIM ZADEH/ALI RAZA HASHEMI
Facility Mailing Address:	7593 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	AZ
Facility Mailing Zip:	91945-1605
UST Owner:	TOSCO, INC.
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	113304
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 221 WASTE OIL & MIXED OIL
Other Information:	USED OIL TO AUTO ZONE
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	113304
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 888 USED OIL FILTERS
Other Information:	Not reported
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

SAN DIEGO MOTORS (Continued) **S105112887**

UST:

UST Name:	UNDERGROUND TANK 113304 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	113304
Tank Type:	SINGLE WALL
Additional Id:	3699-34
Capacity Gallons:	280
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1954-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	07
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 113304 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	113304
Tank Type:	SINGLE WALL
Additional Id:	3699-22
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1999-02-06 00:00:00
Year Installed:	1980-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	02
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 113304 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	113304
Tank Type:	SINGLE WALL
Additional Id:	3699-11
Capacity Gallons:	10000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1999-02-06 00:00:00
Year Installed:	1980-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	02
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/ RESTRICTIVE LLD W/ SIRS: SIR DATA ANALYSIS MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 113304 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	113304
Tank Type:	DOUBLE WALL
Additional Id:	4

SAN DIEGO MOTORS (Continued) **S105112887**

Capacity Gallons:	550
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1999-02-06 00:00:00
Year Installed:	1987-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	GRAVITY
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

CORTESE:

Name:	SAN DIEGO MOTORS
Address:	7593 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451605
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607399191
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

SAN DIEGO CO LOP:

Name:	SAN DIEGO MOTORS
Address:	7593 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1999-LSAM-H13304-002
Record Status:	Completed
Opened Date:	06/08/1999
Parcel Number:	480-081-07-00
Case Type:	LOP - Local Oversight Program
Historical Name:	TOSCO 76 #3699
SWRCB Global ID:	T0607399191
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	06/23/1999
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE

SAN DIEGO MOTORS (Continued) **S105112887**

Watershed Basin Number: 908.22
Water Purveyor: HELIX WATER DISTRICT LAND
Fire Agency: HELIX WATER DISTRICT LAND
Latitude: 32.7423458
Longitude: -117.0345421
X MapCoord: 6320426.834
Y MapCoord: 1850795.922

CERS:
Name: SAN DIEGO MOTORS
Address: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451605
Site ID: 192164
CERS ID: T0607302939
CERS Description: Cleanup Program Site

Name: SAN DIEGO MOTORS
Address: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451605
Site ID: 192164
CERS ID: T0607399191
CERS Description: Leaking Underground Storage Tank Cleanup Site

HWTS:
Name: SAN DIEGO MOTORS
Address: 7593 BROADWAY
Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 91945
EPA ID: CAL000260081
Inactive Date: 06/30/2008
Create Date: 10/01/2002
Last Act Date: Not reported
Mailing Name: Not reported
Mailing Address: 7593 BROADWAY
Mailing Address 2: Not reported
Mailing City,State,Zip: LEMON GROVE, CA 919450000
Owner Name: SAN DIEGO MOTORS INC
Owner Address: 7593 BROADWAY
Owner Address 2: Not reported
Owner City,State,Zip: LEMON GROVE, CA 919450000
Contact Name: HASSAN RAHIMZADEH
Contact Address: 7593 BROADWAY
Contact Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 919450000
Facility Status: Inactive
Facility Type: PERMANENT
Category: STATE
Latitude: 32.742491
Longitude: -117.034387

NAICS:
EPA ID: CAL000260081
Create Date: 2002-10-01 10:54:13.280
NAICS Code: 44112
NAICS Description: Used Car Dealers
Issued EPA ID Date: 2002-10-01 10:54:13.25000
Inactive Date: 2008-06-30 00:00:00

SAN DIEGO MOTORS (Continued) **S105112887**

Facility Name:	SAN DIEGO MOTORS
Facility Address:	7593 BROADWAY
Facility Address 2:	Not reported
Facility City:	LEMON GROVE
Facility County:	Not reported
Facility State:	CA
Facility Zip:	919450000

N85 **TOSCO 76 #3699** **LUST** **S104234312**
SE **7593 BROADWAY** **CPS-SLIC** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **SWEEPS UST**
0.331 mi. **CERS**
1750 ft. **Site 6 of 9 in cluster N**

Relative:
Lower

Actual:
435 ft.

LUST REG 9:

Region:	9
Status:	Preliminary site assessment workplan submitted
Case Number:	9UT3970
Local Case:	H13304-002
Substance:	Gasoline
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Unknown
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Soil only
Date Found:	06/02/1999
Date Stopped:	06/02/1999
Confirm Date:	06/23/1999
Submit Workplan:	9/2/99
Prelim Assess:	/ /
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	06/08/1999
Enforce Date:	Not reported
Closed Date:	Not reported
Enforce Type:	Not reported
Pilot Program:	LOP
Basin Number:	908.22
GW Depth:	Not reported
Beneficial Use:	No Beneficial groundwater use
NPDES Number:	Not reported
Priority:	Not reported
File Dispn:	Not reported
Interim Remedial Actions:	Not reported
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

CPS-SLIC:

Name:	7593 BROADWAY
Address:	7593 BROADWAY

TOSCO 76 #3699 (Continued) **S104234312**

City,State,Zip:	LEMON GROVE, CA 91945
Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	05/07/2013
Global Id:	T10000004737
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	DEH2013-LSAM-000175
Latitude:	32.7423929975055
Longitude:	-117.034513056278
Case Type:	Cleanup Program Site
Case Worker:	EM
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	This is a new VAP Case. This section will be updated as data is received.

Click here to access the California GeoTracker records for this facility:

SWEEPS UST:

Name:	UNOCAL SERV STATION #3699
Address:	7593 BROADWAY
City:	LEMON GROVE
Status:	Not reported
Comp Number:	13304
Number:	Not reported
Board Of Equalization:	44-000051
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013304-000001
Tank Status:	Not reported
Capacity:	280
Active Date:	Not reported
Tank Use:	PETROLEUM
STG:	WASTE
Content:	Not reported
Number Of Tanks:	1

Name:	UNOCAL SERV STATION #3699
Address:	7593 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	13304
Number:	9
Board Of Equalization:	44-000051
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-013304-000002
Tank Status:	A
Capacity:	10000
Active Date:	Not reported

TOSCO 76 #3699 (Continued) **S104234312**

Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 3

Name: UNOCAL SERV STATION #3699
Address: 7593 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 13304
Number: 9
Board Of Equalization: 44-000051
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-013304-000003
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: UNOCAL SERV STATION #3699
Address: 7593 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 13304
Number: 9
Board Of Equalization: 44-000051
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-013304-000004
Tank Status: A
Capacity: 550
Active Date: Not reported
Tank Use: PETROLEUM
STG: W
Content: Not reported
Number Of Tanks: Not reported

CERS:
Name: 7593 BROADWAY
Address: 7593 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 229940
CERS ID: T10000004737
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: EWAN MOFFAT - SAN DIEGO COUNTY LOP
Entity Title: Not reported

TOSCO 76 #3699 (Continued) **S104234312**

Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

P86 **MOBIL SERVICE STATION #18-EH2** **LUST** **S100470412**
SW **7204 BROADWAY** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045**
0.339 mi.
1789 ft. **Site 2 of 9 in cluster P**

Relative: **Lower**
Actual: **411 ft.**

LUST REG 9:

Region:	9
Status:	Case Closed
Case Number:	9UT322
Local Case:	H12538-001
Substance:	Gasoline
Qty Leaked:	21000
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	New Tank
Source:	Piping
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Aquifer affected
Date Found:	04/15/1987
Date Stopped:	04/15/1987
Confirm Date:	04/15/1987
Submit Workplan:	Not reported
Prelim Assess:	04/16/1993
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	04/27/1987
Enforce Date:	4/15/87
Closed Date:	8/23/96
Enforce Type:	SEL
Pilot Program:	LOP
Basin Number:	909.12
GW Depth:	7’
Beneficial Use:	Municipal groundwater use
NPDES Number:	Not reported
Priority:	1B
File Dispn:	Not reported
Interim Remedial Actions:	Yes
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

P87 **THOMAS F DAVISON** **LUST** **U001571857**
SW **7204 BROADWAY** **CPS-SLIC** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045** **HIST UST**
0.339 mi. **SAN DIEGO CO LOP**
1789 ft. **Site 3 of 9 in cluster P**

Relative:
Lower

Actual:
411 ft.

LUST:

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451501
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301977
Global Id:	T0607301977
Latitude:	32.7426407
Longitude:	-117.0423203
Status:	Completed - Case Closed
Status Date:	08/23/1996
Case Worker:	Not reported
RB Case Number:	9UT322
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	H12538-001
Potential Media Affect:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

LUST:

Global Id:	T0607301977
Action Type:	ENFORCEMENT
Date:	08/19/1996
Action:	Closure/No Further Action Letter - #H12538-001

Global Id:	T0607301977
Action Type:	ENFORCEMENT
Date:	08/23/1996
Action:	Closure/No Further Action Letter

Global Id:	T0607301977
Action Type:	ENFORCEMENT
Date:	04/15/1987
Action:	Notice of Responsibility

LUST:

Global Id:	T0607301977
Status:	Open - Case Begin Date
Status Date:	04/15/1987

Global Id:	T0607301977
Status:	Completed - Case Closed
Status Date:	08/23/1996

CPS-SLIC:

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451501
Region:	STATE
Facility Status:	**Completed - Case Closed**

THOMAS F DAVISON (Continued) **U001571857**

Status Date:	05/20/1998
Global Id:	T0608118033
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H12538-002
Latitude:	32.7428362403249
Longitude:	-117.042498965607
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

HIST UST:

Name:	THOMAS F DAVISON
Address:	7204 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
File Number:	0002f017
URL:	https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002f017.pdf
Region:	STATE
Facility ID:	00000039238
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	Not reported
Telephone:	6194657077
Owner Name:	MOBIL OIL CORPORATION
Owner Address:	612 S. FLOWER STREET
Owner City,St,Zip:	LOS ANGELES, CA 90017
Total Tanks:	0004

Tank Num:	001
Container Num:	1
Year Installed:	Not reported
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

Tank Num:	002
Container Num:	2
Year Installed:	Not reported
Tank Capacity:	00005000
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

Tank Num:	003
Container Num:	3
Year Installed:	Not reported
Tank Capacity:	00005000
Tank Used for:	PRODUCT

THOMAS F DAVISON (Continued) **U001571857**

Type of Fuel:	PREMIUM
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor
Tank Num:	004
Container Num:	4
Year Installed:	Not reported
Tank Capacity:	00000280
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Container Construction Thickness:	Not reported
Leak Detection:	Stock Inventor

Click here for Geo Tracker PDF:

SAN DIEGO CO LOP:

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1987-LSAM-H12538-001
Record Status:	Completed
Opened Date:	04/15/1987
Parcel Number:	479-041-18-00
Case Type:	LOP - Local Oversight Program
Historical Name:	MOBIL
SWRCB Global ID:	T0607301977
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	04/15/1987
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7432895
Longitude:	-117.0422912
X MapCoord:	6317994.083
Y MapCoord:	1851260.691

P88 **DAVES MOBIL OIL STN** **RCRA-SQG** **1000221223**
SW **7204 BROADWAY** **SAN DIEGO CO. SAM** **CAD981377914**
1/4-1/2 **LEMON GROVE, CA 91945** **San Diego Co. HMMD**
0.339 mi. **SWEEPS UST**
1789 ft. **Site 4 of 9 in cluster P** **FINDS**
ECHO
Relative: **Cortese**
Lower **HIST CORTESE**
CERS
Actual:
411 ft.

RCRA Listings:

Date Form Received by Agency:		19960901
Handler Name:	DAVES MOBIL OIL STN	
Handler Address:		7204 BROADWAY
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAD981377914
Contact Name:		Not reported

DAVES MOBIL OIL STN (Continued) **1000221223**

Contact Address:		Not reported
Contact City,State,Zip:		Not reported
Contact Telephone:		Not reported
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Not reported
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		CA
State District:		4
Mailing Address:		7204 BROADWAY
Mailing City,State,Zip:		LEMON GROVE, CA 91945
Owner Name:	Not reported	
Owner Type:		Not reported
Operator Name:	NOT REQUIRED	
Operator Type:		Private
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking

DAVES MOBIL OIL STN (Continued) **1000221223**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20020627
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MOBIL OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: NOT REQUIRED	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, ME 99999
Owner/Operator Telephone:	415-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19960901
Handler Name: DAVES MOBIL OIL STN	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	CA
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No

DAVES MOBIL OIL STN (Continued) **1000221223**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860131
Handler Name: DAVES MOBIL OIL STN
Federal Waste Generator Description: Large Quantity Generator
State District Owner: CA
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

SAN DIEGO CO. SAM:
Name: DAVES MOBIL
Address: 7204 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451501
Case Number: H12538-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 8/23/1996
Date Began: 4/15/1987

Name: DAVES MOBIL
Address: 7204 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451501
Case Number: H12538-002
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 5/20/1998
Date Began: Not reported

HMMD SAN DIEGO:
Name: DAVES MOBIL
Address: 7204 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 112538

DAVES MOBIL OIL STN (Continued) **1000221223**

Business Type:	Not reported
EPA Id Number:	CAD981371914
APN:	479-041-18-00
Last HMMD Inspection:	06/24/1986
Facility Telephone:	619-465-7077
Permit Status:	INAC
Permit Expiration:	Not reported
Date Last Updated:	11/02/2012
Facility Owner:	THOMAS F. DAVIDSON
Facility Mailing Address:	7204 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945-1501
UST Owner:	MOBIL OIL CORP
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 112538 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	112538
Tank Type:	SINGLE WALL
Additional Id:	AT0844-1
Capacity Gallons:	5000
UST Contents:	LEADED
Other Content Info:	LEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1978-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name:	UNDERGROUND TANK 112538 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	112538
Tank Type:	SINGLE WALL
Additional Id:	AT0844-2
Capacity Gallons:	5000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1962-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name:	UNDERGROUND TANK 112538 T003
Last Update:	2012-11-02 14:17:38

DAVES MOBIL OIL STN (Continued) **1000221223**

Permit Number:	112538
Tank Type:	SINGLE WALL
Additional Id:	AT0844-3
Capacity Gallons:	5000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	1962-01-01 00:00:00
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

UST Name:	UNDERGROUND TANK 112538 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	112538
Tank Type:	SINGLE WALL
Additional Id:	AT0844-4
Capacity Gallons:	6000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1986-11-08 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION.

UST Name:	UNDERGROUND TANK 112538 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	112538
Tank Type:	SINGLE WALL
Additional Id:	1
Capacity Gallons:	5000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1987-01-12 00:00:00
Year Installed:	1962-01-01 00:00:00
Pipe Type:	SINGLE WALL
Delivery System:	PRESSURE
Monitor Code:	10
UST Monitor Method:	SW TANK DW PRESSURE PIPE W/POS SHUTOFF LLD W/DAILY RECONCILE OR WEEKLY GAUGE: TNK TEST ANN, PIPE TEST ANN 0.1 GAL/HR OR MO 0.2 GAL/HR

SWEEPS UST:

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City:	LEMON GROVE
Status:	Not reported
Comp Number:	12538
Number:	Not reported

DAVES MOBIL OIL STN (Continued) **1000221223**

Board Of Equalization:	44-000400
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012538-000001
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	LEADED
Number Of Tanks:	5

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City:	LEMON GROVE
Status:	Not reported
Comp Number:	12538
Number:	Not reported
Board Of Equalization:	44-000400
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012538-000002
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City:	LEMON GROVE
Status:	Not reported
Comp Number:	12538
Number:	Not reported
Board Of Equalization:	44-000400
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012538-000003
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City:	LEMON GROVE

DAVES MOBIL OIL STN (Continued) **1000221223**

Status:	Not reported
Comp Number:	12538
Number:	Not reported
Board Of Equalization:	44-000400
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012538-000004
Tank Status:	Not reported
Capacity:	6000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City:	LEMON GROVE
Status:	Not reported
Comp Number:	12538
Number:	Not reported
Board Of Equalization:	44-000400
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012538-000005
Tank Status:	Not reported
Capacity:	5000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	PRODUCT
Content:	REG UNLEADED
Number Of Tanks:	Not reported

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	12538
Number:	9
Board Of Equalization:	44-000400
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	Not reported
Tank Status:	Not reported
Capacity:	Not reported
Active Date:	Not reported
Tank Use:	Not reported
STG:	Not reported
Content:	Not reported
Number Of Tanks:	Not reported

DAVES MOBIL OIL STN (Continued) **1000221223**

FINDS:
Registry ID: 110006469669

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
STATE MASTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000221223
Registry ID:	110006469669
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006469669
Name:	DAVES MOBIL OIL STN
Address:	7204 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945

CORTESE:

Name:	DAVES MOBIL
Address:	7204 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451501
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607301977
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	MOBIL SERVICE STATION #18
edr_fadd1:	7204 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Region:	CORTESE
Facility County Code:	37

DAVES MOBIL OIL STN (Continued) **1000221223**

Reg By: LTNKA
Reg Id: 9UT322

CERS:
Name: DAVES MOBIL
Address: 7204 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451501
Site ID: 206381
CERS ID: T0607301977
CERS Description: Leaking Underground Storage Tank Cleanup Site

Name: DAVES MOBIL
Address: 7204 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451501
Site ID: 206381
CERS ID: T0608118033
CERS Description: Cleanup Program Site

N89 **7-ELEVEN FOOD STORE #24013** **SAN DIEGO CO. SAM** **U003937312**
SE **7607 BROADWAY** **UST** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **San Diego Co. HMMD**
0.347 mi. **SWEEPS UST**
1831 ft. **Site 7 of 9 in cluster N** **Cortese**
SAN DIEGO CO LOP

Relative:
Lower

Actual:
436 ft.

SAN DIEGO CO. SAM:
Name: 7-ELEVEN FOOD STORE #24013
Address: 7607 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451607
Case Number: H20571-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: GW With No Beneficial Use Designation
Facility Status: Closed Case
Date: 5/16/2005
Date Began: 4/13/2000

UST:
Name: 7-ELEVEN FOOD STORE #24013
Address: 7607 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Facility ID: H20571
Permitting Agency: SAN DIEGO COUNTY
CERSID: Not reported
Latitude: 32.743744
Longitude: -117.032604
Owner type: Not reported
Facility type: Not reported
Num of inuse ust: Not reported
Num of closed ust: Not reported
Num of oos ust: Not reported
Epa region: Not reported
Tribal lands: Not reported
Tank owner name: Not reported
Tank owner mailing address: Not reported
Tank owner mailing city: Not reported
Tank owner mailing zip: Not reported

7-ELEVEN FOOD STORE #24013 (Continued) **U003937312**

Tank owner mailing state:	Not reported
Tank operator name:	Not reported
Tank operator mailing address:	Not reported
Tank operator mailing city:	Not reported
Tank operator mailing zip:	Not reported
Tank operator mailing state:	Not reported
Tankidnumber:	Not reported
Tank status:	Not reported
Tank configuration:	Not reported
Tank closure date:	Not reported
Tank installation date:	Not reported
Tank num of compartments:	Not reported
Tank contents:	Not reported
Tank capacity gallons:	Not reported
Tank type:	Not reported
Tank pc construction:	Not reported
Tank pwpiping construction:	Not reported
Tank piping type:	Not reported
Tank piping construction:	Not reported
Tank sacrificial anode:	Not reported
Tank cp impressed current:	Not reported
Tank cp shutoff:	Not reported
Tank alarms:	Not reported
Tank ball float:	Not reported
Tank spill bucket:	Not reported

HMMD SAN DIEGO:

Name:	7-ELEVEN FOOD STORE #24013
Address:	7607 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	120571
Business Type:	6HK28
EPA Id Number:	CAD981407471
APN:	480-105-01-00
Last HMMD Inspection:	05/29/2003
Facility Telephone:	619-469-8667
Permit Status:	INAC
Permit Expiration:	06/30/2004
Date Last Updated:	11/02/2012
Facility Owner:	7-ELEVEN, INC.
Facility Mailing Address:	PO BOX 711
Facility Mailing City:	DALLAS
Facility Mailing State:	TX
Facility Mailing Zip:	75221-
UST Owner:	7-ELEVE, INC.
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

UST:

UST Name:	UNDERGROUND TANK 120571 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	120571
Tank Type:	SINGLE WALL

7-ELEVEN FOOD STORE #24013 (Continued) **U003937312**

Additional Id:	RT1432/AT4953
Capacity Gallons:	9816
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2003-09-11 00:00:00
Year Installed:	1983-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 120571 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	120571
Tank Type:	SINGLE WALL
Additional Id:	RT1432/AT4953
Capacity Gallons:	9816
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2003-09-11 00:00:00
Year Installed:	1983-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 120571 T003
Last Update:	2012-11-02 14:17:38
Permit Number:	120571
Tank Type:	SINGLE WALL
Additional Id:	RT1432/AT4953
Capacity Gallons:	9816
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2003-09-11 00:00:00
Year Installed:	1983-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

SWEEPS UST:

Name:	7-ELEVEN FOOD STORE #24013
Address:	7607 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	20571
Number:	9
Board Of Equalization:	44-002251
Referral Date:	Not reported

7-ELEVEN FOOD STORE #24013 (Continued) **U003937312**

Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020571-000001
Tank Status: A
Capacity: 9816
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 3

Name: 7-ELEVEN FOOD STORE #24013
Address: 7607 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 20571
Number: 9
Board Of Equalization: 44-002251
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020571-000002
Tank Status: A
Capacity: 9816
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: 7-ELEVEN FOOD STORE #24013
Address: 7607 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 20571
Number: 9
Board Of Equalization: 44-002251
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020571-000003
Tank Status: A
Capacity: 9816
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

CORTESE:
Name: 7-ELEVEN FOOD STORE #24013
Address: 7607 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451607
Region: CORTESE

7-ELEVEN FOOD STORE #24013 (Continued) **U003937312**

Envirostor Id:	Not reported
Global ID:	T0607391309
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

SAN DIEGO CO LOP:

Name:	7-ELEVEN FOOD STORE #24013
Address:	7607 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH2000-LSAM-H20571-001
Record Status:	Completed
Opened Date:	04/13/2000
Parcel Number:	480-105-01-00
Case Type:	LOP - Local Oversight Program
Historical Name:	7-11 FOOD STORE
SWRCB Global ID:	T0607391309
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	09/05/2000
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7423948
Longitude:	-117.0339533
X MapCoord:	6320607.271
Y MapCoord:	1850810.926

N90 **7-ELEVEN FOOD STORE 24013** **LUST** **1000281983**
SE **7607 BROADWAY** **HIST UST** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045** **CERS**
0.347 mi.
1831 ft. **Site 8 of 9 in cluster N**

Relative: LUST:
Lower

Name:	7-ELEVEN FOOD STORE #24013
Address:	7607 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451607
Lead Agency:	SAN DIEGO COUNTY LOP

Actual:
436 ft.

7-ELEVEN FOOD STORE 24013 (Continued) **1000281983**

Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607391309
Global Id:	T0607391309
Latitude:	32.7424584224979
Longitude:	-117.033976614475
Status:	Completed - Case Closed
Status Date:	05/16/2005
Case Worker:	JC
RB Case Number:	9UT4090
Local Agency:	SAN DIEGO COUNTY LOP
File Location:	Local Agency
Local Case Number:	H20571-001
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607391309
Contact Type:	Local Agency Caseworker
Contact Name:	JAMES CLAY
Organization Name:	SAN DIEGO COUNTY LOP
Address:	P.O. Box 129261
City:	San Diego
Email:	james.clay@sdcounty.ca.gov
Phone Number:	Not reported

LUST:

Global Id:	T0607391309
Action Type:	ENFORCEMENT
Date:	05/20/2005
Action:	Closure/No Further Action Letter

Global Id:	T0607391309
Action Type:	Other
Date:	04/13/2000
Action:	Leak Began

Global Id:	T0607391309
Action Type:	Other
Date:	04/13/2000
Action:	Leak Reported

Global Id:	T0607391309
Action Type:	ENFORCEMENT
Date:	10/11/2000
Action:	Notice of Responsibility

Global Id:	T0607391309
Action Type:	Other
Date:	04/13/2000
Action:	Leak Stopped

Global Id:	T0607391309
Action Type:	Other
Date:	04/13/2000
Action:	Leak Discovery

7-ELEVEN FOOD STORE 24013 (Continued) **1000281983**

LUST:

Global Id:	T0607391309
Status:	Open - Case Begin Date
Status Date:	04/13/2000
Global Id:	T0607391309
Status:	Completed - Case Closed
Status Date:	05/16/2005

HIST UST:

Name:	7-ELEVEN FOOD STORE 24013
Address:	7607 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
File Number:	0002f3cd
URL:	https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002f3cd.pdf
Region:	STATE
Facility ID:	00000010214
Facility Type:	Gas Station
Other Type:	Not reported
Contact Name:	JAMES SARTAIN
Telephone:	6194642711
Owner Name:	THE SOUTHLAND CORPORATION
Owner Address:	7839 UNIVERSITY AVENUE
Owner City,St,Zip:	LA MESA, CA 92041
Total Tanks:	0003
Tank Num:	001
Container Num:	24013-1
Year Installed:	1983
Tank Capacity:	00009816
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	0.30
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	24013-2
Year Installed:	1983
Tank Capacity:	00009816
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	0.30
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	24013-3
Year Installed:	1983
Tank Capacity:	00009816
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	0.30
Leak Detection:	Stock Inventor

7-ELEVEN FOOD STORE 24013 (Continued) **1000281983**

Click here for Geo Tracker PDF:

CERS:

Name:	7-ELEVEN FOOD STORE #24013
Address:	7607 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451607
Site ID:	250808
CERS ID:	T0607391309
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	JAMES CLAY - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

N91 **7-ELEVEN STORE NO 24013** **LUST** **S104826031**
SE **7607 BROADWAY** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945**
0.347 mi.
1831 ft. **Site 9 of 9 in cluster N**

Relative:
Lower

Actual:
436 ft.

LUST REG 9:

Region:	9
Status:	Preliminary site assessment underway
Case Number:	9UT4090
Local Case:	H20571-001
Substance:	Gasoline
Qty Leaked:	Not reported
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Other Means
How Stopped:	Other Means
Source:	Piping
Cause:	Other Cause
Lead Agency:	Local Agency
Case Type:	Soil only
Date Found:	04/13/2000
Date Stopped:	04/13/2000
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	10/11/2000
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	04/13/2000
Enforce Date:	Not reported
Closed Date:	Not reported
Enforce Type:	Not reported
Pilot Program:	LOP
Basin Number:	908.22

7-ELEVEN STORE NO 24013 (Continued) **S104826031**

GW Depth: Not reported
Beneficial Use: No Beneficial groundwater use
NPDES Number: Not reported
Priority: Not reported
File Dispn: Administratively opened on database, however no file physically exists
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

P92 **SHELL** **LUST** **S102438821**
SW **7180 BROADWAY** **San Diego Co. HMMD** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **EMI**
0.349 mi. **HIST CORTESE**
1843 ft. **Site 5 of 9 in cluster P** **CERS**

Relative:
Lower

Actual:
411 ft.

LUST REG 9:
Region: 9
Status: Case Closed
Case Number: 9UT543
Local Case: H12684-001
Substance: 0
Qty Leaked: 0
Abate Method: Not reported
Local Agency: San Diego
How Found: Tank Closure
How Stopped: Close Tank
Source: Other Source
Cause: Overfill
Lead Agency: Local Agency
Case Type: Other ground water affected
Date Found: 09/08/1986
Date Stopped: 09/08/1986
Confirm Date: / /
Submit Workplan: Not reported
Prelim Assess: / /
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 09/08/1986
Enforce Date: Not reported
Closed Date: 3/4/87
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 908.22
GW Depth: 6’
Beneficial Use: No Beneficial groundwater use
NPDES Number: Not reported
Priority: Low priority. Priority ranking can change over time.
File Dispn: File discarded, case closed
Interim Remedial Actions: Yes
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

HMMD SAN DIEGO:
Name: BROADWAY 76
Address: 7180 BROADWAY

SHELL (Continued) **S102438821**

City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 209344
Business Type: 6HK29
EPA Id Number: CAL000323323
APN: 479-021-11-00
Last HMMD Inspection: 11/08/2011
Facility Telephone: 619-464-5161
Permit Status: OPEN
Permit Expiration: 02/28/2013
Date Last Updated: 11/02/2012
Facility Owner: RAAD ATTISHA
Facility Mailing Address: 7180 BROADWAY
Facility Mailing City: LEMON GROVE
Facility Mailing State: CA
Facility Mailing Zip: 91945
UST Owner: CALIFORNIA FINEST OIL CO
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: N
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 209344
Update Date: 11/02/2012
Case Number: 67-63-8
Name: BLENDED EMULSIFIER
Other Information: CAR WASH WAX-POLISHER
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL
Other Information: UNDERGROUND TANK 112684 T009
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 68476-85-7
Name: LPG
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 8002-05-9
Name: OILS, LUBRICATING
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE

SHELL (Continued) **S102438821**

Hazardous Categories 2: ACUTE

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: PETROLEUM HYDROCARBON
Other Information: WASTE OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 112684 T007
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 112684 T008
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: MIXTURE
Name: SOLVENT
Other Information: HIGH PRESSURE SOAP
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information: OIL/WATER SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: WASTE RADIATOR FLUID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344

SHELL (Continued) **S102438821**

Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: WASTE GASOLINE FILTERS - INTERFLUID RECYCLING
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 09/11/2008
Violation Code: 6HV1001
Violation: NO UPF PERMIT FOR HAZMATS
Violation Citation: A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/02/2009
Violation Code: 6HV3116
Violation: NO YRLY CERT. FOR CONTIN. MONITOR
Violation Citation: Annual certification for continuous monitoring system not completed (new tanks). 25284.1(a)(4)(C); 2630(d), 2638
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/02/2009
Violation Code: 6HV3193
Violation: NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation: Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008

SHELL (Continued) **S102438821**

Violation Code:	6HV3101
Violation:	UPF PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current UPF permit not obtained/not available. 25284; 68.905, 68.1003, 68.1005
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3102
Violation:	OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O.

SHELL (Continued) **S102438821**

	not ICC certified. 2715 (a)(b)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3164
Violation:	MONITOR EQUIP NOT PER MANUF. SPECS
Violation Citation:	All monitoring equipment not installed, calibrated, operated, and/or maintained per manufacturer instructions. 2638(a), 2641(j)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012

SHELL (Continued) **S102438821**

Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012

SHELL (Continued) **S102438821**

Inspection Date: 05/21/2008
Violation Code: 6HV1002
Violation: HMBP NOT ESTABISHED/IMPLEMENTED.
Violation Citation: Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/18/2010
Violation Code: 6HV3114
Violation: 2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation: Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 112684 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT4784,RT5282
Capacity Gallons: 12000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2004-02-02 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 112684 T008
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT3650, RT3885, RT4784,RT5282
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2004-02-02 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 112684 T009
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT4784,RT5282
Capacity Gallons: 10000

SHELL (Continued) **S102438821**

UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2004-02-02 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name: BROADWAY 76
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 209344
Business Type: 6HK29
EPA Id Number: CAL000323323
APN: 479-021-11-00
Last HMMD Inspection: 11/08/2011
Facility Telephone: 619-464-5161
Permit Status: OPEN
Permit Expiration: 02/28/2013
Date Last Updated: 11/02/2012
Facility Owner: RAAD ATTISHA
Facility Mailing Address: 7180 BROADWAY
Facility Mailing City: LEMON GROVE
Facility Mailing State: CA
Facility Mailing Zip: 91945
UST Owner: CALIFORNIA FINEST OIL CO
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 209344
Update Date: 11/02/2012
Case Number: 67-63-8
Name: BLENDED EMULSIFIER
Other Information: CAR WASH WAX-POLISHER
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL
Other Information: UNDERGROUND TANK 112684 T009
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012

SHELL (Continued) **S102438821**

Case Number:	68476-85-7
Name:	LPG
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	PRESSURE RELEASE
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	8002-05-9
Name:	OILS, LUBRICATING
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	PETROLEUM HYDROCARBON
Other Information:	WASTE OIL
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUND TANK 112684 T007
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 112684 T008
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	MIXTURE
Name:	SOLVENT
Other Information:	HIGH PRESSURE SOAP
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information:	OIL/WATER SLUDGE

SHELL (Continued) **S102438821**

Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: WASTE RADIATOR FLUID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: WASTE GASOLINE FILTERS - INTERFLUID RECYCLING
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 09/11/2008
Violation Code: 6HV1001
Violation: NO UPF PERMIT FOR HAZMATS
Violation Citation: A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/02/2009
Violation Code: 6HV3116
Violation: NO YRLY CERT. FOR CONTIN. MONITOR
Violation Citation: Annual certification for continuous monitoring system not completed (new tanks). 25284.1(a)(4)(C); 2630(d), 2638

SHELL (Continued) **S102438821**

Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	11/02/2009
Violation Code:	6HV3193
Violation:	NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation:	Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3101
Violation:	UPF PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current UPF permit not obtained/not available. 25284; 68.905, 68.1003, 68.1005
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3102
Violation:	OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	209344

SHELL (Continued) **S102438821**

Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3164
Violation:	MONITOR EQUIP NOT PER MANUF. SPECS
Violation Citation:	All monitoring equipment not installed, calibrated, operated, and/or maintained per manufacturer instructions. 2638(a), 2641(j)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional.

SHELL (Continued) **S102438821**

2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)

SHELL (Continued) **S102438821**

Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV1002
Violation: HMBP NOT ESTABISHED/IMPLEMENTED.
Violation Citation: Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/18/2010
Violation Code: 6HV3114
Violation: 2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation: Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 112684 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT4784,RT5282
Capacity Gallons: 12000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2004-02-02 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 112684 T008
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT3650, RT3885, RT4784,RT5282
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE

SHELL (Continued) **S102438821**

Remove Close Date:	Not reported
Year Installed:	2004-02-02 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112684 T009
Last Update:	2012-11-02 14:17:38
Permit Number:	209344
Tank Type:	DOUBLE WALL
Additional Id:	NT2361, RT3403, RT4784,RT5282
Capacity Gallons:	10000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2004-02-02 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	BROADWAY 76
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	209344
Business Type:	6HK29
EPA Id Number:	CAL000323323
APN:	479-021-11-00
Last HMMD Inspection:	11/08/2011
Facility Telephone:	619-464-5161
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	RAAD ATTISHA
Facility Mailing Address:	7180 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945
UST Owner:	CALIFORNIA FINEST OIL CO
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	N
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	67-63-8
Name:	BLENDED EMULSIFIER
Other Information:	CAR WASH WAX-POLISHER
Material Waste:	Material

SHELL (Continued) **S102438821**

Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL
Other Information: UNDERGROUND TANK 112684 T009
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 68476-85-7
Name: LPG
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 8002-05-9
Name: OILS, LUBRICATING
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: PETROLEUM HYDROCARBON
Other Information: WASTE OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 112684 T007
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 112684 T008
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

SHELL (Continued) **S102438821**

Permit Number: 209344
Update Date: 11/02/2012
Case Number: MIXTURE
Name: SOLVENT
Other Information: HIGH PRESSURE SOAP
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information: OIL/WATER SLUDGE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information: WASTE RADIATOR FLUID
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: WASTE GASOLINE FILTERS - INTERFLUID RECYCLING
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 209344
Update Date: 11/02/2012

SHELL (Continued) **S102438821**

Inspection Date:	09/11/2008
Violation Code:	6HV1001
Violation:	NO UPF PERMIT FOR HAZMATS
Violation Citation:	A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	11/02/2009
Violation Code:	6HV3116
Violation:	NO YRLY CERT. FOR CONTIN. MONITOR
Violation Citation:	Annual certification for continuous monitoring system not completed (new tanks). 25284.1(a)(4)(C); 2630(d), 2638
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	11/02/2009
Violation Code:	6HV3193
Violation:	NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation:	Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3101
Violation:	UPF PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current UPF permit not obtained/not available. 25284; 68.905, 68.1003, 68.1005
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3102
Violation:	OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD

SHELL (Continued) **S102438821**

Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3164
Violation:	MONITOR EQUIP NOT PER MANUF. SPECS
Violation Citation:	All monitoring equipment not installed, calibrated, operated, and/or maintained per manufacturer instructions. 2638(a), 2641(j)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	ACTIVE

SHELL (Continued) **S102438821**

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411

SHELL (Continued) **S102438821**

Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV1002
Violation: HMBP NOT ESTABISHED/IMPLEMENTED.
Violation Citation: Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/18/2010
Violation Code: 6HV3114
Violation: 2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation: Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 112684 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT4784,RT5282
Capacity Gallons: 12000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2004-02-02 00:00:00
Pipe Type: DOUBLE WALL

SHELL (Continued) **S102438821**

Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 112684 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	209344
Tank Type:	DOUBLE WALL
Additional Id:	NT2361, RT3403, RT3650, RT3885, RT4784,RT5282
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2004-02-02 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF
UST Name:	UNDERGROUND TANK 112684 T009
Last Update:	2012-11-02 14:17:38
Permit Number:	209344
Tank Type:	DOUBLE WALL
Additional Id:	NT2361, RT3403, RT4784,RT5282
Capacity Gallons:	10000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2004-02-02 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	BROADWAY 76
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	209344
Business Type:	6HK29
EPA Id Number:	CAL000323323
APN:	479-021-11-00
Last HMMD Inspection:	11/08/2011
Facility Telephone:	619-464-5161
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	RAAD ATTISHA
Facility Mailing Address:	7180 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945

SHELL (Continued) **S102438821**

UST Owner: CALIFORNIA FINEST OIL CO
Handle Regulated Hazmat: Y
Own Or Operate UST: Y
Subject To APSA: Not reported
Generate Haz Waste: Y
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Inventory Active Permits (not SQG Medical):
Permit Number: 209344
Update Date: 11/02/2012
Case Number: 67-63-8
Name: BLENDED EMULSIFIER
Other Information: CAR WASH WAX-POLISHER
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 68476-34-6
Name: DIESEL
Other Information: UNDERGROUND TANK 112684 T009
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 68476-85-7
Name: LPG
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: PRESSURE RELEASE

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 8002-05-9
Name: OILS, LUBRICATING
Other Information: Not reported
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: ACUTE

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: PETROLEUM HYDROCARBON
Other Information: WASTE OIL
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED

SHELL (Continued) **S102438821**

Other Information:	UNDERGROUND TANK 112684 T007
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 112684 T008
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	MIXTURE
Name:	SOLVENT
Other Information:	HIGH PRESSURE SOAP
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information:	OIL/WATER SLUDGE
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information:	WASTE RADIATOR FLUID
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information:	WASTE GASOLINE FILTERS - INTERFLUID RECYCLING
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported
Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 444 USED BATTERIES
Other Information:	Not reported
Material Waste:	Waste
Hazardous Categories 1:	Not reported

SHELL (Continued) **S102438821**

Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 09/11/2008
Violation Code: 6HV1001
Violation: NO UPF PERMIT FOR HAZMATS
Violation Citation: A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/02/2009
Violation Code: 6HV3116
Violation: NO YRLY CERT. FOR CONTIN. MONITOR
Violation Citation: Annual certification for continuous monitoring system not completed (new tanks). 25284.1(a)(4)(C); 2630(d), 2638
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/02/2009
Violation Code: 6HV3193
Violation: NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation: Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3101
Violation: UPF PERMIT NOT CURRENT/ONSITE
Violation Citation: Current UPF permit not obtained/not available. 25284; 68.905, 68.1003, 68.1005
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3102
Violation: OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation: Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity: ACTIVE

SHELL (Continued) **S102438821**

Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3164
Violation:	MONITOR EQUIP NOT PER MANUF. SPECS
Violation Citation:	All monitoring equipment not installed, calibrated, operated, and/or maintained per manufacturer instructions. 2638(a), 2641(j)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008

SHELL (Continued) **S102438821**

Violation Code: 6HV3192
Violation: NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation: Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

SHELL (Continued) **S102438821**

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV1002
Violation: HMBP NOT ESTABISHED/IMPLEMENTED.
Violation Citation: Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/18/2010
Violation Code: 6HV3114
Violation: 2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation: Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity: ACTIVE

SHELL (Continued) **S102438821**

UST:

UST Name:	UNDERGROUND TANK 112684 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	209344
Tank Type:	DOUBLE WALL
Additional Id:	NT2361, RT3403, RT4784,RT5282
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2004-02-02 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112684 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	209344
Tank Type:	DOUBLE WALL
Additional Id:	NT2361, RT3403, RT3650, RT3885, RT4784,RT5282
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2004-02-02 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name:	UNDERGROUND TANK 112684 T009
Last Update:	2012-11-02 14:17:38
Permit Number:	209344
Tank Type:	DOUBLE WALL
Additional Id:	NT2361, RT3403, RT4784,RT5282
Capacity Gallons:	10000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2004-02-02 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

Name:	BROADWAY 76
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	209344

SHELL (Continued) **S102438821**

Business Type:	6HK29
EPA Id Number:	CAL000323323
APN:	479-021-11-00
Last HMMD Inspection:	11/08/2011
Facility Telephone:	619-464-5161
Permit Status:	OPEN
Permit Expiration:	02/28/2013
Date Last Updated:	11/02/2012
Facility Owner:	RAAD ATTISHA
Facility Mailing Address:	7180 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945
UST Owner:	CALIFORNIA FINEST OIL CO
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	N
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	67-63-8
Name:	BLENDED EMULSIFIER
Other Information:	CAR WASH WAX-POLISHER
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	68476-34-6
Name:	DIESEL
Other Information:	UNDERGROUND TANK 112684 T009
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	68476-85-7
Name:	LPG
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	PRESSURE RELEASE

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	8002-05-9
Name:	OILS, LUBRICATING
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	ACUTE

SHELL (Continued) **S102438821**

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	PETROLEUM HYDROCARBON
Other Information:	WASTE OIL
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUND TANK 112684 T007
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 112684 T008
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	MIXTURE
Name:	SOLVENT
Other Information:	HIGH PRESSURE SOAP
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 222 OIL/WATER SEPARATION SLUDGE
Other Information:	OIL/WATER SLUDGE
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 342 ORGANIC LIQUIDS W/METALS
Other Information:	WASTE RADIATOR FLUID
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	209344
Update Date:	11/02/2012
Case Number:	Not reported

SHELL (Continued) **S102438821**

Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: WASTE GASOLINE FILTERS - INTERFLUID RECYCLING
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 444 USED BATTERIES
Other Information: Not reported
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 209344
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 888 USED OIL FILTERS
Other Information: USED OIL FILTERS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 09/11/2008
Violation Code: 6HV1001
Violation: NO UPF PERMIT FOR HAZMATS
Violation Citation: A Unified Program Facility permit has not been obtained for hazardous materials. 68.905
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/02/2009
Violation Code: 6HV3116
Violation: NO YRLY CERT. FOR CONTIN. MONITOR
Violation Citation: Annual certification for continuous monitoring system not completed (new tanks). 25284.1(a)(4)(C); 2630(d), 2638
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/02/2009
Violation Code: 6HV3193
Violation: NO TRAINING/RECORD INCOMPLETE-NOT ONSITE
Violation Citation: Facility employee(s) are not trained, training records are incomplete, and/or not onsite. 2715(f)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3101
Violation: UPF PERMIT NOT CURRENT/ONSITE

SHELL (Continued) **S102438821**

Violation Citation:	Current UPF permit not obtained/not available. 25284; 68.905, 68.1003, 68.1005
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3102
Violation:	OPER. PERMIT NOT CURRENT/ONSITE
Violation Citation:	Current Operating Permit not available at facility. 25284(a), 25286(a); 2712(i); 68.1003
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3104
Violation:	FORMS A & B NOT AVAIL./SUBMITTED
Violation Citation:	CUPA UST form(s) A and/or B not available/complete/submitted to HMD. 25286(a); 2711
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3107
Violation:	MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation:	Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3108
Violation:	UST ER RESPONSE PLAN NOT COMPLETE/AVAIL
Violation Citation:	Emergency Response Plan is not available/complete. 25289(b); 2632(b), 2634(e), 2641(h)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3109
Violation:	NO SCALED PLOT PLAN AVAIL/TO HMD
Violation Citation:	Scaled Plot plan showing tank, piping & equipment location not available/complete/submitted to HMD. 2711(a)(8), 2632(d)(1) (C)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3191
Violation:	NO D.O. CERT/NOTIFICATION/CHANGE
Violation Citation:	Designated Operator Notification/Change form not submitted and/or D.O. not ICC certified. 2715 (a)(b)
Activity:	ACTIVE

SHELL (Continued) **S102438821**

Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3164
Violation:	MONITOR EQUIP NOT PER MANUF. SPECS
Violation Citation:	All monitoring equipment not installed, calibrated, operated, and/or maintained per manufacturer instructions. 2638(a), 2641(j)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3192
Violation:	NO D.O INSPECTION/INCOMPL;NO REPORTS
Violation Citation:	Designated Operator monthly inspection not conducted or incomplete; or DO inspection reports not onsite 2715 (c)(d)(e)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3257
Violation:	2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation:	Secondary containment system components not liquid free. 2631(d)(4)
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	209344
Update Date:	11/02/2012
Inspection Date:	05/21/2008
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL

SHELL (Continued) **S102438821**

Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3268
Violation: UST SYSTEM NOT PRODUCT TIGHT
Violation Citation: UST system not product tight (for tank installs on or after 7/1/03). 25290.1(c), 25290.2 (c)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 05/21/2008
Violation Code: 6HV1002
Violation: HMBP NOT ESTABISHED/IMPLEMENTED.

SHELL (Continued) **S102438821**

Violation Citation: Hazardous materials handler has not established/implemented a business plan. HSC 25503.5(a)
Activity: ACTIVE

Permit Number: 209344
Update Date: 11/02/2012
Inspection Date: 11/18/2010
Violation Code: 6HV3114
Violation: 2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation: Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 112684 T007
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT4784,RT5282
Capacity Gallons: 12000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2004-02-02 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 112684 T008
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT3650, RT3885, RT4784,RT5282
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2004-02-02 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 30A
UST Monitor Method: DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

UST Name: UNDERGROUND TANK 112684 T009
Last Update: 2012-11-02 14:17:38
Permit Number: 209344
Tank Type: DOUBLE WALL
Additional Id: NT2361, RT3403, RT4784,RT5282
Capacity Gallons: 10000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE

SHELL (Continued) **S102438821**

Remove Close Date:	Not reported
Year Installed:	2004-02-02 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	30A
UST Monitor Method:	DW TANK, DW PRESSURIZED PIPE W/ WET TANK ANNULAR; POSITIVE SHUT-OFF & FAILSAFE, 3.0LLD; UDC W/ POSITIVE SHUT-OFF

EMI:

Name:	TEXACO / BROADWAY
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Year:	2000
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	TEXACO / BROADWAY
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Year:	2001
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	TEXACO / BROADWAY
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Year:	2002
County Code:	37
Air Basin:	SD
Facility ID:	4580

SHELL (Continued) **S102438821**

Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	TEXACO BROADWAY
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Year:	2003
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	TEXACO BROADWAY
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Year:	2004
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.1013622
Reactive Organic Gases Tons/Yr:	2.1013622
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	TEXACO BROADWAY
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Year:	2005

SHELL (Continued) **S102438821**

County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.1013622
Reactive Organic Gases Tons/Yr:	2.1013622
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Year:	2006
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 945770000
Year:	2007
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL

SHELL (Continued) **S102438821**

Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2008
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2009
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.1100000000000001
Reactive Organic Gases Tons/Yr:	1.1100000000000001
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2010
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.1100000000000001
Reactive Organic Gases Tons/Yr:	1.1100000000000001
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

SHELL (Continued) **S102438821**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2011
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2012
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2013
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	0

SHELL (Continued) **S102438821**

NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2014
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2015
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2016
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported

SHELL (Continued) **S102438821**

Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2017
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2018
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2019
County Code:	37
Air Basin:	SD
Facility ID:	4580
Air District Name:	SD
SIC Code:	5541

SHELL (Continued) **S102438821**

Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.11
Reactive Organic Gases Tons/Yr:	1.11
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

HIST CORTESE:

edr_fname:	TEXACO U.S.A
edr_fadd1:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT543

CERS:

Name:	SHELL
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	466649
CERS ID:	110018967803
CERS Description:	US EPA Air Emission Inventory System (EIS)

Affiliation:

Affiliation Type Desc:	Environmental Contact
Entity Name:	SONDRA BIENVENU
Entity Title:	Not reported
Affiliation Address:	POBOX 2099 T S P 1501
Affiliation City:	HOUSTON
Affiliation State:	TX
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

P93 **TEXACO REFINING AND MARKETING** **SAN DIEGO CO. SAM** **U003789372**
SW **7180 BROADWAY** **UST** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **SWEEPS UST**
0.349 mi. **Cortese**
1843 ft. **Site 6 of 9 in cluster P**

Relative:
Lower

Actual:
411 ft.

SAN DIEGO CO. SAM:

Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451401
Case Number:	H12684-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	Soils Only
Facility Status:	Closed Case
Date:	3/4/1987
Date Began:	9/8/1986

TEXACO REFINING AND MARKETING (Continued) **U003789372**

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Case Number: H12684-002
Agency: DEH Site Assessment & Mitigation
Funding: **Non Billable**
Facility Type: Failed Integrity Test
Facility Status: Closed Case
Date: 9/18/1987
Date Began: 8/10/1987

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Case Number: H12684-003
Agency: DEH Site Assessment & Mitigation
Funding: **Non Billable**
Facility Type: Failed Integrity Test
Facility Status: Closed Case
Date: 5/19/1989
Date Began: 12/5/1988

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Case Number: H12684-004
Agency: DEH Site Assessment & Mitigation
Funding: **Non Billable**
Facility Type: Failed Integrity Test
Facility Status: Closed Case
Date: 9/6/1989
Date Began: 1/11/1989

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Case Number: H12684-005
Agency: DEH Site Assessment & Mitigation
Funding: **Non Billable**
Facility Type: Failed Integrity Test
Facility Status: Closed Case
Date: 5/17/1991
Date Began: 3/6/1991

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Case Number: H12684-006
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Remedial Investigation
Date: 11/19/2002
Date Began: 4/17/2001

UST:
Name: TEXACO REFINING AND MARKETING

TEXACO REFINING AND MARKETING (Continued) **U003789372**

Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Facility ID:	H12684
Permitting Agency:	SAN DIEGO COUNTY
CERSID:	Not reported
Latitude:	32.744272
Longitude:	-117.041905
Owner type:	Not reported
Facility type:	Not reported
Num of inuse ust:	Not reported
Num of closed ust:	Not reported
Num of oos ust:	Not reported
Epa region:	Not reported
Tribal lands:	Not reported
Tank owner name:	Not reported
Tank owner mailing address:	Not reported
Tank owner mailing city:	Not reported
Tank owner mailing zip:	Not reported
Tank owner mailing state:	Not reported
Tank operator name:	Not reported
Tank operator mailing address:	Not reported
Tank operator mailing city:	Not reported
Tank operator mailing zip:	Not reported
Tank operator mailing state:	Not reported
Tankidnumber:	Not reported
Tank status:	Not reported
Tank configuration:	Not reported
Tank closure date:	Not reported
Tank installation date:	Not reported
Tank num of compartments:	Not reported
Tank contents:	Not reported
Tank capacity gallons:	Not reported
Tank type:	Not reported
Tank pc construction:	Not reported
Tank pwpiping construction:	Not reported
Tank piping type:	Not reported
Tank piping construction:	Not reported
Tank sacrificial anode:	Not reported
Tank cp impressed current:	Not reported
Tank cp shutoff:	Not reported
Tank alarms:	Not reported
Tank ball float:	Not reported
Tank spill bucket:	Not reported

SWEEPS UST:

Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City:	LEMON GROVE
Status:	Not reported
Comp Number:	12684
Number:	Not reported
Board Of Equalization:	44-000217
Referral Date:	Not reported
Action Date:	Not reported
Created Date:	Not reported
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012684-000001

TEXACO REFINING AND MARKETING (Continued) **U003789372**

Tank Status: Not reported
Capacity: 550
Active Date: Not reported
Tank Use: PETROLEUM
STG: WASTE
Content: Not reported
Number Of Tanks: 1

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12684
Number: 9
Board Of Equalization: 44-000217
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012684-000002
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: 5

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12684
Number: 9
Board Of Equalization: 44-000217
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012684-000003
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12684
Number: 9
Board Of Equalization: 44-000217
Referral Date: Not reported
Action Date: 06-26-92

TEXACO REFINING AND MARKETING (Continued) **U003789372**

Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012684-000004
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: Not reported

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12684
Number: 9
Board Of Equalization: 44-000217
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012684-000005
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: OTHER
Number Of Tanks: Not reported

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12684
Number: 9
Board Of Equalization: 44-000217
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012684-000006
Tank Status: A
Capacity: 550
Active Date: Not reported
Tank Use: PETROLEUM
STG: W
Content: Not reported
Number Of Tanks: Not reported

CORTESE:
Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Region: CORTESE
Envirostor Id: Not reported

TEXACO REFINING AND MARKETING (Continued) **U003789372**

Global ID:	T0608127577
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

P94 **SHELL** **LUST** **1008152892**
SW **7180 BROADWAY** **CPS-SLIC** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **FINDS**
0.349 mi. **ECHO**
1843 ft. **Site 7 of 9 in cluster P** **SAN DIEGO CO LOP**
CERS

Relative:
Lower

Actual:
411 ft.

LUST:

Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451401
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0608127577
Global Id:	T0608127577
Latitude:	32.742951
Longitude:	-117.043253
Status:	Completed - Case Closed
Status Date:	12/20/2013
Case Worker:	JS
RB Case Number:	Not reported
Local Agency:	SAN DIEGO COUNTY LOP
File Location:	Local Agency
Local Case Number:	H12684-006
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	Comments: The Site is a former Shell-branded service station located on the northwest corner of the intersection of Broadway and Massachusetts Avenue in Lemon Grove, California. The Site is currently a 76-branded service station with three fuel underground storage tanks (USTs), six fuel dispensers with associated product piping, a car wash, and a station building with three service bays. In April 2001, soil sampling was conducted during the removal and replacement of product piping and dispensers. Soil was remedially excavated to between 3 and 5 feet below grade (fbg). Soil sampling conducted beneath the dispensers and piping indicates that a release occurred, and Unauthorized Release Case DEH2001-LSAM-H12684-006 was opened on May 16, 2001. In March 2004, during station upgrade

SHELL (Continued) **1008152892**

activities, soil sampling was conducted during replacement of the USTs and product piping. Impacted soil was remedially excavated to between 6 and 7 fbg. Subsequent assessment demonstrated that hydrocarbons and oxygenates in soil are localized around the dispenser islands and USTs. The total residual petroleum hydrocarbon mass of TPH greater than 100 mg/kg in soil is estimated to be approximately 590 cubic yards. In July and November 2008, a soil vapor survey was conducted using soil vapor probes VP-1 though VP-4 located around the perimeter of the station building. The risk to station workers from vapor intrusion to indoor air was evaluated using the DEH Site Assessment and Mitigation Vapor Risk Model to estimate the potential risk to human health from benzene, ethylbenzene, naphthalene and MTBE vapors volatilizing and migrating into the station building. The risk from vapor intrusion was calculated at a total carcinogenic risk of 8.80 x 10-7, which is below the 10-6 target. It was concluded that there is no risk to human health from vapor intrusion to indoor air in the station building. Eleven groundwater monitoring wells have been installed at the Site. Groundwater was monitored and sampled at the Site between April 2002 and April 2013. Separate-phase hydrocarbons have never been present at the Site. Groundwater in the vicinity of the Site is designated as non-beneficial. Monitoring has indicated that the contaminant plumes are decreasing to stable; have been decreasing in extent (as the result of natural attenuation); and are collapsing in on their cores. Hydrocarbons are generally concentrated northeast of the dispensers and west of the dispensers. Oxygenates are located in the vicinity of the USTs and dispenser islands. A Corrective Action Plan (CAP) was submitted on July 31, 2012 requesting case closure. The Public Participation process for the above-referenced CAP was completed. The public comment period ended on June 21, 2013. According to the environmental consultant s registered professional, the Site presents no significant risk to human health and the environment. DEH concurs with this conclusion.

LUST:
Global Id: T0608127577
Contact Type: Local Agency Caseworker
Contact Name: JON SENAHA
Organization Name: SAN DIEGO COUNTY LOP
Address: P.O. Box 129261
City: San Diego
Email: jon.senaha@sdcounty.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 08/08/2013
Action: Notification - Preclosure

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 12/20/2013
Action: Closure/No Further Action Letter

Global Id: T0608127577
Action Type: RESPONSE

SHELL (Continued) **1008152892**

Date: 01/26/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608127577
Action Type: RESPONSE
Date: 06/18/2013
Action: Correspondence

Global Id: T0608127577
Action Type: RESPONSE
Date: 05/17/2013
Action: Correspondence

Global Id: T0608127577
Action Type: RESPONSE
Date: 06/24/2013
Action: Correspondence

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 08/17/2010
Action: Technical Correspondence / Assistance / Other

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 01/29/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 04/30/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 08/08/2013
Action: Staff Letter

Global Id: T0608127577
Action Type: Other
Date: 04/17/2001
Action: Leak Began

Global Id: T0608127577
Action Type: Other
Date: 05/02/2001
Action: Leak Reported

Global Id: T0608127577
Action Type: RESPONSE
Date: 01/25/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0608127577
Action Type: RESPONSE
Date: 05/22/2013
Action: Monitoring Report - Semi-Annually

SHELL (Continued) **1008152892**

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 05/21/2001
Action: Notice of Responsibility

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 03/10/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0608127577
Action Type: RESPONSE
Date: 07/10/2009
Action: Monitoring Report - Quarterly

Global Id: T0608127577
Action Type: RESPONSE
Date: 04/08/2009
Action: Monitoring Report - Quarterly

Global Id: T0608127577
Action Type: RESPONSE
Date: 07/25/2008
Action: Monitoring Report - Quarterly

Global Id: T0608127577
Action Type: RESPONSE
Date: 03/11/2009
Action: Site Assessment Report

Global Id: T0608127577
Action Type: RESPONSE
Date: 06/25/2010
Action: Monitoring Report - Semi-Annually

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 10/15/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0608127577
Action Type: Other
Date: 05/02/2001
Action: Leak Stopped

Global Id: T0608127577
Action Type: RESPONSE
Date: 07/15/2009
Action: Other Workplan

Global Id: T0608127577
Action Type: RESPONSE
Date: 12/23/2009
Action: Monitoring Report - Semi-Annually

Global Id: T0608127577
Action Type: RESPONSE

SHELL (Continued) **1008152892**

Date: 06/04/2010
Action: Site Assessment Report

Global Id: T0608127577
Action Type: RESPONSE
Date: 12/01/2011
Action: Monitoring Report - Semi-Annually

Global Id: T0608127577
Action Type: RESPONSE
Date: 03/12/2013
Action: CAP/RAP - Other Report - Regulator Responded

Global Id: T0608127577
Action Type: RESPONSE
Date: 08/29/2012
Action: CAP/RAP - Other Report - Regulator Responded

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 05/18/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0608127577
Action Type: ENFORCEMENT
Date: 07/14/2009
Action: Letter - Notice

Global Id: T0608127577
Action Type: Other
Date: 04/17/2001
Action: Leak Discovery

Global Id: T0608127577
Action Type: RESPONSE
Date: 01/22/2009
Action: Monitoring Report - Quarterly

Global Id: T0608127577
Action Type: RESPONSE
Date: 07/26/2011
Action: Monitoring Report - Semi-Annually

LUST:
Global Id: T0608127577
Status: Open - Case Begin Date
Status Date: 04/17/2001

Global Id: T0608127577
Status: Open - Remediation
Status Date: 11/19/2002

Global Id: T0608127577
Status: Open - Site Assessment
Status Date: 05/18/2009

Global Id: T0608127577

SHELL (Continued) **1008152892**

Status: Open - Eligible for Closure
Status Date: 07/11/2013

Global Id: T0608127577
Status: Completed - Case Closed
Status Date: 12/20/2013

Global Id: T0608127577
Status: Open - Eligible for Closure
Status Date: 12/20/2013

CPS-SLIC:
Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 05/19/1989
Global Id: T0608116355
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H12684-003
Latitude: 32.7429726577431
Longitude: -117.043158586374
Case Type: Cleanup Program Site
Case Worker: Not reported
Local Agency: Not reported
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Under Investigation
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 09/18/1987
Global Id: T0608149780
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H12684-002
Latitude: 32.74282827246
Longitude: -117.043291623548
Case Type: Cleanup Program Site
Case Worker: Not reported
Local Agency: Not reported
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Not reported
Potential Contaminants of Concern: Not reported
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

SHELL (Continued) **1008152892**

Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451401
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	03/04/1987
Global Id:	T0607302834
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H12684-001
Latitude:	32.7428660521654
Longitude:	-117.043153262767
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	9UT543
File Location:	Local Agency
Potential Media Affected:	Not reported
Potential Contaminants of Concern:	Not reported
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451401
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	05/17/1991
Global Id:	T0608103864
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H12684-005
Latitude:	32.7428993421066
Longitude:	-117.043266874407
Case Type:	Cleanup Program Site
Case Worker:	Not reported
Local Agency:	Not reported
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Under Investigation
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451401
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	09/06/1989
Global Id:	T0608184911
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H12684-004
Latitude:	32.742914903658
Longitude:	-117.043458993783
Case Type:	Cleanup Program Site
Case Worker:	Not reported

SHELL (Continued) **1008152892**

Local Agency: Not reported
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Under Investigation
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

FINDS:
Registry ID: 110018967803

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
HAZARDOUS AIR POLLUTANT MAJOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1008152892
Registry ID: 110018967803
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110018967803
Name: SHELL
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945

SAN DIEGO CO LOP:
Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Record ID: DEH1991-LSAM-H12684-005
Record Status: Completed
Opened Date: 04/11/1991
Parcel Number: 479-021-11-00
Case Type: FIT - Failed Integrity Test
Historical Name: TEXACO USA
SWRCB Global ID: T0608103864
Funding: N - Non-Billable
Lead Agency: DEH/SAM
Lead Agency Date: 04/11/1991
Census Tract: 144.00
Community: Lemon Grove
Jurisdiction: LEMON GROVE
Watershed Basin Number: 908.22
Water Purveyor: HELIX WATER DISTRICT LAND

SHELL (Continued) **1008152892**

Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7429233
Longitude:	-117.0432537
X MapCoord:	6317749.648
Y MapCoord:	1851028.468
Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH2001-LSAM-H12684-006
Record Status:	Completed
Opened Date:	05/02/2001
Parcel Number:	479-021-11-00
Case Type:	LOP - Local Oversight Program
Historical Name:	TEXACO/BROADWAY L.G. 7180
SWRCB Global ID:	T0608127577
Funding:	S - LOP State Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	04/17/2001
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7429233
Longitude:	-117.0432537
X MapCoord:	6317749.648
Y MapCoord:	1851028.468
Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1987-LSAM-H12684-002
Record Status:	Completed
Opened Date:	08/10/1987
Parcel Number:	479-021-11-00
Case Type:	FIT - Failed Integrity Test
Historical Name:	TEXACO
SWRCB Global ID:	T0608149780
Funding:	N - Non-Billable
Lead Agency:	DEH/SAM
Lead Agency Date:	08/10/1987
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7429233
Longitude:	-117.0432537
X MapCoord:	6317749.648
Y MapCoord:	1851028.468
Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945

SHELL (Continued) **1008152892**

Record ID:	DEH1989-LSAM-H12684-003
Record Status:	Completed
Opened Date:	03/07/1989
Parcel Number:	479-021-11-00
Case Type:	FIT - Failed Integrity Test
Historical Name:	TEXACO
SWRCB Global ID:	T0608116355
Funding:	N - Non-Billable
Lead Agency:	DEH/SAM
Lead Agency Date:	03/07/1989
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7429233
Longitude:	-117.0432537
X MapCoord:	6317749.648
Y MapCoord:	1851028.468

Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1989-LSAM-H12684-004
Record Status:	Completed
Opened Date:	08/15/1989
Parcel Number:	479-021-11-00
Case Type:	FIT - Failed Integrity Test
Historical Name:	TEXACO
SWRCB Global ID:	T0608184911
Funding:	N - Non-Billable
Lead Agency:	DEH/SAM
Lead Agency Date:	08/18/1989
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7429233
Longitude:	-117.0432537
X MapCoord:	6317749.648
Y MapCoord:	1851028.468

CERS:

Name:	TEXACO REFINING AND MARKETING
Address:	7180 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451401
Site ID:	201800
CERS ID:	T0608103864
CERS Description:	Cleanup Program Site

Coordinates:

Site ID:	201800
Facility Name:	TEXACO REFINING AND MARKETING
Env Int Type Code:	CPS

SHELL (Continued) **1008152892**

Program ID: T0607302834
Coord Name: Not reported
Ref Point Type Desc: Unknown,
Latitude: 32.742866
Longitude: -117.043153

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Site ID: 201800
CERS ID: T0607302834
CERS Description: Cleanup Program Site

Coordinates:
Site ID: 201800
Facility Name: TEXACO REFINING AND MARKETING
Env Int Type Code: CPS
Program ID: T0607302834
Coord Name: Not reported
Ref Point Type Desc: Unknown,
Latitude: 32.742866
Longitude: -117.043153

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Site ID: 201800
CERS ID: T0608116355
CERS Description: Cleanup Program Site

Coordinates:
Site ID: 201800
Facility Name: TEXACO REFINING AND MARKETING

SHELL (Continued) **1008152892**

Env Int Type Code: CPS
Program ID: T0607302834
Coord Name: Not reported
Ref Point Type Desc: Unknown,
Latitude: 32.742866
Longitude: -117.043153

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Site ID: 201800
CERS ID: T0608184911
CERS Description: Cleanup Program Site

Coordinates:
Site ID: 201800
Facility Name: TEXACO REFINING AND MARKETING
Env Int Type Code: CPS
Program ID: T0607302834
Coord Name: Not reported
Ref Point Type Desc: Unknown,
Latitude: 32.742866
Longitude: -117.043153

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Site ID: 201800
CERS ID: T0608127577
CERS Description: Leaking Underground Storage Tank Cleanup Site

Coordinates:
Site ID: 201800

SHELL (Continued) **1008152892**

Facility Name: TEXACO REFINING AND MARKETING
Env Int Type Code: CPS
Program ID: T0607302834
Coord Name: Not reported
Ref Point Type Desc: Unknown,
Latitude: 32.742866
Longitude: -117.043153

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: TEXACO REFINING AND MARKETING
Address: 7180 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451401
Site ID: 201800
CERS ID: T0608149780
CERS Description: Cleanup Program Site

Coordinates:
Site ID: 201800
Facility Name: TEXACO REFINING AND MARKETING
Env Int Type Code: CPS
Program ID: T0607302834
Coord Name: Not reported
Ref Point Type Desc: Unknown,
Latitude: 32.742866
Longitude: -117.043153

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JON SENAHA - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

P95 **91739** **LUST** **U001571837**
SW **7209 BROADWAY** **CPS-SLIC** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045** **CERS HAZ WASTE**
0.349 mi. **HIST UST**
1844 ft. **Site 8 of 9 in cluster P** **CERS TANKS**
SAN DIEGO CO LOP
Relative: **CERS**
Lower

Actual: **410 ft.**

LUST:

Name:	CHEVRON STATION #91739
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301425
Global Id:	T0607301425
Latitude:	32.7421264633153
Longitude:	-117.042362683265
Status:	Completed - Case Closed
Status Date:	08/16/2004
Case Worker:	Not reported
RB Case Number:	9UT2676
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	H12922-002
Potential Media Affect:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607301425
Action Type:	Other
Date:	01/27/1994
Action:	Leak Discovery

Global Id:	T0607301425
Action Type:	Other
Date:	01/27/1994
Action:	Leak Began

Global Id:	T0607301425
Action Type:	Other
Date:	01/27/1994
Action:	Leak Reported

Global Id:	T0607301425
Action Type:	ENFORCEMENT
Date:	02/04/1994
Action:	Notice of Responsibility

Global Id:	T0607301425
Action Type:	ENFORCEMENT
Date:	08/06/2004
Action:	Closure/No Further Action Letter

Global Id:	T0607301425
Action Type:	Other
Date:	01/27/1994
Action:	Leak Stopped

91739 (Continued) **U001571837**

LUST:
Global Id: T0607301425
Status: Open - Case Begin Date
Status Date: 01/27/1994

Global Id: T0607301425
Status: Completed - Case Closed
Status Date: 08/16/2004

CPS-SLIC:
Name: CHEVRON STATION #91739
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451502
Region: STATE
Facility Status: Completed - Case Closed
Status Date: 08/15/1994
Global Id: T0608193347
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H12922-001
Latitude: 32.742078
Longitude: -117.042466
Case Type: Cleanup Program Site
Case Worker: SW
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

CERS HAZ WASTE:
Name: CHEVRON STATION #91739
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451502
Site ID: 104940
CERS ID: 10361194
CERS Description: Hazardous Waste Generator

HIST UST:
Name: 91739
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 92045
File Number: 0002ae1e
URL: https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002ae1e.pdf
Region: STATE
Facility ID: 00000062120
Facility Type: Gas Station
Other Type: Not reported
Contact Name: HAGEMAN,LARRY
Telephone: 6194634525
Owner Name: CHEVRON U.S.A. INC.
Owner Address: 575 MARKET

91739 (Continued) **U001571837**

Owner City,St,Zip: SAN FRANCISCO, CA 94105
Total Tanks: 0004

Tank Num: 001
Container Num: 1
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: 0000370
Leak Detection: Stock Inventor

Tank Num: 002
Container Num: 2
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: 0000370
Leak Detection: Stock Inventor

Tank Num: 003
Container Num: 3
Year Installed: Not reported
Tank Capacity: 00010000
Tank Used for: PRODUCT
Type of Fuel: Not reported
Container Construction Thickness: 0000370
Leak Detection: Stock Inventor

Tank Num: 004
Container Num: 4
Year Installed: Not reported
Tank Capacity: 00001000
Tank Used for: WASTE
Type of Fuel: Not reported
Container Construction Thickness: 0000370
Leak Detection: Stock Inventor

Click here for Geo Tracker PDF:

CERS TANKS:
Name: CHEVRON STATION #91739
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451502
Site ID: 104940
CERS ID: 10361194
CERS Description: Underground Storage Tank

SAN DIEGO CO LOP:
Name: CHEVRON STATION #91739
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Record ID: DEH1994-LSAM-H12922-002
Record Status: Completed
Opened Date: 01/27/1994

91739 (Continued) **U001571837**

Parcel Number:	479-081-01-00
Case Type:	LOP - Local Oversight Program
Historical Name:	CHEVRON #9-1739
SWRCB Global ID:	T0607301425
Funding:	S - LOP State Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	02/02/1994
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7420270
Longitude:	-117.0424655
X MapCoord:	6317989.116
Y MapCoord:	1850708.969

CERS:

Name:	CHEVRON STATION #91739
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Site ID:	104940
CERS ID:	10361194
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	104940
Site Name:	CHEVRON STATION #91739
Violation Date:	03-21-2014
Citation:	23 CCR 16 2715(c)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)(2)
Violation Description:	Failure to comply with one or more of the following: maintain the spill bucket in good condition, containment free of debris/liquid, and/or to remove the contents of the spill bucket when a release/leak/spill was observed.
Violation Notes:	Returned to compliance on 03/21/2014. Inspection Sequence ID:4964701;Tank ID:35134,35858;Violation Description:Failure to comply with one or more of the following: maintain the spill bucket in good condition, containment free of debris/liquid, and/or to remove the contents of the spill bucket when a release/leak/spill was observed. 23 CCR 16 2635(b), 2715(c)(2).
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,

Site ID:	104940
Site Name:	CHEVRON STATION #91739
Violation Date:	02-09-2018
Citation:	23 CCR 16 2632(c)(2)(A)&(B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632(c)(2)(A)&(B)
Violation Description:	Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system.
Violation Notes:	Returned to compliance on 02/09/2018. Inspection Sequence ID:5832884;Tank ID:35134,35135,35868;Violation Description:(RD) Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system. 23 CCR

91739 (Continued) **U001571837**

2631(g), 2632(c)(2)(A-B)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-23-2021
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description: "Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "
Violation Notes: Returned to compliance on 01/13/2022. Inspection Sequence ID:6602830;Tank ID:35134,35135,35868;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-08-2019
Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)
Violation Description: Failure to have an approved UST Monitoring Plan.
Violation Notes: Returned to compliance on 03/12/2019. Inspection Sequence ID:6084758;Tank ID:35134,35135,35868;Violation Description:Failure to have an approved UST Monitoring Plan. 23 CCR 2632(d)(1), 2634(d), 2641(h)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-08-2019
Citation: HSC 6.7 25290.1(e)2 - California Health and Safety Code, Chapter 6.7, Section(s) 25290.1(e)2
Violation Description: Failure to maintain the interstitial space such that a breach in the

91739 (Continued) **U001571837**

primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring.

Violation Notes: Returned to compliance on 06/13/2019. Inspection Sequence ID:6084758;Tank ID:35135;Violation Description:(RD) Failure to maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring. HSC 25290.1(e); 23 CCR 2630(d)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 03-06-2015
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description: Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs.
Violation Notes: Returned to compliance on 03/13/2015. Inspection Sequence ID:5089191;Tank ID:35134,35135;Violation Description:Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs. 23 CCR 16 2636(f)(2).
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-26-2016
Citation: 23 CCR 16 2636(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)
Violation Description: Failure to continuously monitor the interstitial space of the tank, piping and/or sumps sump such that the leak detection activates an audible/visual alarm when a leak is detected.
Violation Notes: Returned to compliance on 02/26/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-22-2017
Citation: 23 CCR 16 2631(g), 2632(c)(2)(A) & (B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2631(g), 2632(c)(2)(A) & (B)
Violation Description: Failure of the double-walled interstitial space of the tank to be continuously monitored with an audible and visual alarm.

91739 (Continued) **U001571837**

Violation Notes: Returned to compliance on 02/22/2017. Inspection Sequence ID:5595331;Tank ID:35134,35135,35868;Violation Description:(RD) Failure to continuously monitor the interstitial space of the tank, piping and/or sumps such that the leak detection activates an audible/visual alarm when a leak is detected. 23 CCR 2631(g), 2632(c)(2)(A)&(B), 2633(c), 2636(f)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-26-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5301687
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-06-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5089191
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6084758
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6084758
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection

91739 (Continued) **U001571837**

Eval Date: 02-09-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5832884
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-16-2022
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6866612
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-18-2020
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6388895
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-09-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5832884
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-23-2021
Violations Found: Yes
Eval Type: Routine done by local agency

91739 (Continued) **U001571837**

Eval Notes: Inspector: Villena Elaine Inspection ID:6602830
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-26-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5301687
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-08-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6084758
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-09-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5832884
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-26-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5301687
Eval Division: San Diego County Department of Env Health
Eval Program: HW

91739 (Continued) **U001571837**

Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-06-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5089191
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-06-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5089191
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Coordinates:
Site ID: 104940
Facility Name: CHEVRON STATION #91739
Env Int Type Code: HWG
Program ID: 10361194
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.742030
Longitude: -117.042460

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: P.O. Box 6004 Attn: HES Permit Desk
Affiliation City: SAN RAMON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94583
Affiliation Phone: ,

Affiliation Type Desc: Parent Corporation
Entity Name: CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported

91739 (Continued) **U001571837**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: UST Permit Applicant
Entity Name: DEBORAH ROWE
Entity Title: RETAIL HES
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (925) 842-9002,

Affiliation Type Desc: Document Preparer
Entity Name: Pedro R. Carranza
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Environmental Contact
Entity Name: Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title: Not reported
Affiliation Address: P.O. Box 6004 Attn: HES Permit Desk
Affiliation City: SAN RAMON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94583
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: Pedro R. Carranza
Entity Title: RETAIL HES SPECIALIST
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: CHEVRON STATION #91739
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 463-4525,

Affiliation Type Desc: UST Property Owner Name
Entity Name: CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title: Not reported

91739 (Continued) **U001571837**

Affiliation Address:	P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	SCOTT WELDON - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	UST Tank Operator
Entity Name:	CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title:	Not reported
Affiliation Address:	P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,
Affiliation Type Desc:	Legal Owner
Entity Name:	Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title:	Not reported
Affiliation Address:	P.O. Box 6004 Attn: HES Permit Desk
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	Property Owner
Entity Name:	Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title:	Not reported
Affiliation Address:	P.O. Box 6004 Attn: HES Permit Desk
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,

91739 (Continued) **U001571837**

Affiliation Type Desc:	UST Tank Owner
Entity Name:	CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title:	Not reported
Affiliation Address:	P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Name:	CHEVRON STATION #91739
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Site ID:	104940
CERS ID:	T0607301425
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Violations:

Site ID:	104940
Site Name:	CHEVRON STATION #91739
Violation Date:	03-21-2014
Citation:	23 CCR 16 2715(c)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)(2)
Violation Description:	Failure to comply with one or more of the following: maintain the spill bucket in good condition, containment free of debris/liquid, and/or to remove the contents of the spill bucket when a release/leak/spill was observed.
Violation Notes:	Returned to compliance on 03/21/2014. Inspection Sequence ID:4964701;Tank ID:35134,35858;Violation Description:Failure to comply with one or more of the following: maintain the spill bucket in good condition, containment free of debris/liquid, and/or to remove the contents of the spill bucket when a release/leak/spill was observed. 23 CCR 16 2635(b), 2715(c)(2).
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	104940
Site Name:	CHEVRON STATION #91739
Violation Date:	02-09-2018
Citation:	23 CCR 16 2632(c)(2)(A)&(B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632(c)(2)(A)&(B)
Violation Description:	Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system.
Violation Notes:	Returned to compliance on 02/09/2018. Inspection Sequence ID:5832884;Tank ID:35134,35135,35868;Violation Description:(RD) Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system. 23 CCR 2631(g), 2632(c)(2)(A-B)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	104940
Site Name:	CHEVRON STATION #91739
Violation Date:	02-23-2021
Citation:	HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7,

91739 (Continued) **U001571837**

Section(s) 25284.2

Violation Description: "Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "

Violation Notes: Returned to compliance on 01/13/2022. Inspection Sequence ID:6602830;Tank ID:35134,35135,35868;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-08-2019
Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)

Violation Description: Failure to have an approved UST Monitoring Plan.

Violation Notes: Returned to compliance on 03/12/2019. Inspection Sequence ID:6084758;Tank ID:35134,35135,35868;Violation Description:Failure to have an approved UST Monitoring Plan. 23 CCR 2632(d)(1), 2634(d), 2641(h)

Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-08-2019
Citation: HSC 6.7 25290.1(e)2 - California Health and Safety Code, Chapter 6.7, Section(s) 25290.1(e)2

Violation Description: Failure to maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring.

Violation Notes: Returned to compliance on 06/13/2019. Inspection Sequence ID:6084758;Tank ID:35135;Violation Description:(RD) Failure to maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the

91739 (Continued) **U001571837**

environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring. HSC 25290.1(e); 23 CCR 2630(d)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 03-06-2015
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Description: Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs.
Violation Notes: Returned to compliance on 03/13/2015. Inspection Sequence ID:5089191;Tank ID:35134,35135;Violation Description:Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs. 23 CCR 16 2636(f)(2).
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-26-2016
Citation: 23 CCR 16 2636(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)
Violation Description: Failure to continuously monitor the interstitial space of the tank, piping and/or sumps sump such that the leak detection activates an audible/visual alarm when a leak is detected.
Violation Notes: Returned to compliance on 02/26/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-22-2017
Citation: 23 CCR 16 2631(g), 2632(c)(2)(A) & (B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2631(g), 2632(c)(2)(A) & (B)
Violation Description: Failure of the double-walled interstitial space of the tank to be continuously monitored with an audible and visual alarm.
Violation Notes: Returned to compliance on 02/22/2017. Inspection Sequence ID:5595331;Tank ID:35134,35135,35868;Violation Description:(RD) Failure to continuously monitor the interstitial space of the tank, piping and/or sumps such that the leak detection activates an audible/visual alarm when a leak is detected. 23 CCR 2631(g), 2632(c)(2)(A)&(B), 2633(c), 2636(f)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

91739 (Continued) **U001571837**

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-26-2016
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5301687
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS,

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	03-06-2015
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Kiener Michael Inspection ID:5089191
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS,

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	03-21-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS,

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-08-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: LaPel Daniel Inspection ID:6084758
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS,

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-08-2019
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: LaPel Daniel Inspection ID:6084758
Eval Division:	San Diego County Department of Env Health
Eval Program:	HW
Eval Source:	CERS,

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-09-2018
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: LaPel Daniel Inspection ID:5832884
Eval Division:	San Diego County Department of Env Health
Eval Program:	UST
Eval Source:	CERS,

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-16-2022

91739 (Continued) **U001571837**

Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6866612
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-18-2020
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6388895
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-09-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5832884
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-23-2021
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6602830
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-26-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5301687

91739 (Continued) **U001571837**

Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-08-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6084758
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-09-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5832884
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-26-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5301687
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-06-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5089191
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

91739 (Continued) **U001571837**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-06-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5089191
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Coordinates:
Site ID: 104940
Facility Name: CHEVRON STATION #91739
Env Int Type Code: HWG
Program ID: 10361194
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.742030
Longitude: -117.042460

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: P.O. Box 6004 Attn: HES Permit Desk
Affiliation City: SAN RAMON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94583
Affiliation Phone: ,

Affiliation Type Desc: Parent Corporation
Entity Name: CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: UST Permit Applicant
Entity Name: DEBORAH ROWE
Entity Title: RETAIL HES
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported

91739 (Continued) **U001571837**

Affiliation Zip: Not reported
Affiliation Phone: (925) 842-9002,

Affiliation Type Desc: Document Preparer
Entity Name: Pedro R. Carranza
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Environmental Contact
Entity Name: Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title: Not reported
Affiliation Address: P.O. Box 6004 Attn: HES Permit Desk
Affiliation City: SAN RAMON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94583
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: Pedro R. Carranza
Entity Title: RETAIL HES SPECIALIST
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: CHEVRON STATION #91739
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 463-4525,

Affiliation Type Desc: UST Property Owner Name
Entity Name: CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title: Not reported
Affiliation Address: P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City: SAN RAMON
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94583
Affiliation Phone: (925) 842-9002,

Affiliation Type Desc: Local Agency Caseworker
Entity Name: SCOTT WELDON - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261

91739 (Continued) **U001571837**

Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	UST Tank Operator
Entity Name:	CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title:	Not reported
Affiliation Address:	P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,
Affiliation Type Desc:	Legal Owner
Entity Name:	Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title:	Not reported
Affiliation Address:	P.O. Box 6004 Attn: HES Permit Desk
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	Property Owner
Entity Name:	Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title:	Not reported
Affiliation Address:	P.O. Box 6004 Attn: HES Permit Desk
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	UST Tank Owner
Entity Name:	CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title:	Not reported
Affiliation Address:	P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,

91739 (Continued) **U001571837**

Name: CHEVRON STATION #91739
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451502
Site ID: 104940
CERS ID: T0608193347
CERS Description: Cleanup Program Site

Violations:
Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 03-21-2014
Citation: 23 CCR 16 2715(c)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)(2)
Violation Description: Failure to comply with one or more of the following: maintain the spill bucket in good condition, containment free of debris/liquid, and/or to remove the contents of the spill bucket when a release/leak/spill was observed.
Violation Notes: Returned to compliance on 03/21/2014. Inspection Sequence ID:4964701;Tank ID:35134,35858;Violation Description:Failure to comply with one or more of the following: maintain the spill bucket in good condition, containment free of debris/liquid, and/or to remove the contents of the spill bucket when a release/leak/spill was observed. 23 CCR 16 2635(b), 2715(c)(2).
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-09-2018
Citation: 23 CCR 16 2632(c)(2)(A)&(B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632(c)(2)(A)&(B)
Violation Description: Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system.
Violation Notes: Returned to compliance on 02/09/2018. Inspection Sequence ID:5832884;Tank ID:35134,35135,35868;Violation Description:(RD) Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system. 23 CCR 2631(g), 2632(c)(2)(A-B)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-23-2021
Citation: HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2
Violation Description: "Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of five gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container. Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. "

91739 (Continued) **U001571837**

Violation Notes:	Returned to compliance on 01/13/2022. Inspection Sequence ID:6602830;Tank ID:35134,35135,35868;Violation Description:(TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	104940
Site Name:	CHEVRON STATION #91739
Violation Date:	02-08-2019
Citation:	23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)
Violation Description:	Failure to have an approved UST Monitoring Plan.
Violation Notes:	Returned to compliance on 03/12/2019. Inspection Sequence ID:6084758;Tank ID:35134,35135,35868;Violation Description:Failure to have an approved UST Monitoring Plan. 23 CCR 2632(d)(1), 2634(d), 2641(h)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	104940
Site Name:	CHEVRON STATION #91739
Violation Date:	02-08-2019
Citation:	HSC 6.7 25290.1(e)2 - California Health and Safety Code, Chapter 6.7, Section(s) 25290.1(e)2
Violation Description:	Failure to maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring.
Violation Notes:	Returned to compliance on 06/13/2019. Inspection Sequence ID:6084758;Tank ID:35135;Violation Description:(RD) Failure to maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring. HSC 25290.1(e); 23 CCR 2630(d)
Violation Division:	San Diego County Department of Env Health
Violation Program:	UST
Violation Source:	CERS,
Site ID:	104940
Site Name:	CHEVRON STATION #91739
Violation Date:	03-06-2015
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)

91739 (Continued) **U001571837**

Violation Description: Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs.
Violation Notes: Returned to compliance on 03/13/2015. Inspection Sequence ID:5089191;Tank ID:35134,35135;Violation Description:Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs. 23 CCR 16 2636(f)(2).
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-26-2016
Citation: 23 CCR 16 2636(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)
Violation Description: Failure to continuously monitor the interstitial space of the tank, piping and/or sumps sump such that the leak detection activates an audible/visual alarm when a leak is detected.
Violation Notes: Returned to compliance on 02/26/2016.
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Site ID: 104940
Site Name: CHEVRON STATION #91739
Violation Date: 02-22-2017
Citation: 23 CCR 16 2631(g), 2632(c)(2)(A) & (B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2631(g), 2632(c)(2)(A) & (B)
Violation Description: Failure of the double-walled interstitial space of the tank to be continuously monitored with an audible and visual alarm.
Violation Notes: Returned to compliance on 02/22/2017. Inspection Sequence ID:5595331;Tank ID:35134,35135,35868;Violation Description:(RD) Failure to continuously monitor the interstitial space of the tank, piping and/or sumps such that the leak detection activates an audible/visual alarm when a leak is detected. 23 CCR 2631(g), 2632(c)(2)(A)&(B), 2633(c), 2636(f)
Violation Division: San Diego County Department of Env Health
Violation Program: UST
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-26-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5301687
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

91739 (Continued) **U001571837**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-06-2015
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5089191
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6084758
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-08-2019
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6084758
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-09-2018
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5832884
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-16-2022
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6866612
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-18-2020
Violations Found: No

91739 (Continued) **U001571837**

Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6388895
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-09-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5832884
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-23-2021
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Villena Elaine Inspection ID:6602830
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-26-2016
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5301687
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division: San Diego County Department of Env Health

91739 (Continued) **U001571837**

Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-08-2019
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:6084758
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-09-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: LaPel Daniel Inspection ID:5832884
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-22-2017
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5595331
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-26-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5301687
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-06-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5089191
Eval Division: San Diego County Department of Env Health
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-06-2015
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Kiener Michael Inspection ID:5089191
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

91739 (Continued) **U001571837**

Eval General Type: Compliance Evaluation Inspection
Eval Date: 03-21-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Inspector: Fuentecilla Carmel Inspection ID:4964701
Eval Division: San Diego County Department of Env Health
Eval Program: UST
Eval Source: CERS,

Coordinates:
Site ID: 104940
Facility Name: CHEVRON STATION #91739
Env Int Type Code: HWG
Program ID: 10361194
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.742030
Longitude: -117.042460

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: P.O. Box 6004 Attn: HES Permit Desk
Affiliation City: SAN RAMON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94583
Affiliation Phone: ,

Affiliation Type Desc: Parent Corporation
Entity Name: CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: UST Permit Applicant
Entity Name: DEBORAH ROWE
Entity Title: RETAIL HES
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (925) 842-9002,

Affiliation Type Desc: Document Preparer
Entity Name: Pedro R. Carranza
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported

91739 (Continued) **U001571837**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Environmental Contact
Entity Name: Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title: Not reported
Affiliation Address: P.O. Box 6004 Attn: HES Permit Desk
Affiliation City: SAN RAMON
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 94583
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: Pedro R. Carranza
Entity Title: RETAIL HES SPECIALIST
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: CHEVRON STATION #91739
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (619) 463-4525,

Affiliation Type Desc: UST Property Owner Name
Entity Name: CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title: Not reported
Affiliation Address: P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City: SAN RAMON
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 94583
Affiliation Phone: (925) 842-9002,

Affiliation Type Desc: Local Agency Caseworker
Entity Name: SCOTT WELDON - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: UST Tank Operator
Entity Name: CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title: Not reported

91739 (Continued) **U001571837**

Affiliation Address:	P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,
Affiliation Type Desc:	Legal Owner
Entity Name:	Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title:	Not reported
Affiliation Address:	P.O. Box 6004 Attn: HES Permit Desk
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	Property Owner
Entity Name:	Chevron Products Company (a Chevron U.S.A. Inc. division)
Entity Title:	Not reported
Affiliation Address:	P.O. Box 6004 Attn: HES Permit Desk
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,
Affiliation Type Desc:	UST Tank Owner
Entity Name:	CHEVRON PRODUCTS COMPANY (A DIVISION OF CHEVRON U.S.A. INC.)
Entity Title:	Not reported
Affiliation Address:	P.O. BOX 6004, ATTN: PERMIT DESK
Affiliation City:	SAN RAMON
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	94583
Affiliation Phone:	(925) 842-9002,

P96 **CHEVRON** **LUST** **S102427537**
SW **7209 BROADWAY** **SAN DIEGO CO. SAM** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **San Diego Co. HMMD**
0.349 mi. **SWEEPS UST**
1844 ft. **Site 9 of 9 in cluster P** **Cortese**
EMI
Relative: **HIST CORTESE**
Lower

Actual: **410 ft.**

LUST REG 9:

Region:	9
Status:	Preliminary site assessment underway
Case Number:	9UT2676
Local Case:	H12922-002
Substance:	Gasoline
Qty Leaked:	0
Abate Method:	Not reported
Local Agency:	San Diego
How Found:	Not reported
How Stopped:	Not reported
Source:	Unknown
Cause:	Unknown
Lead Agency:	Local Agency
Case Type:	Other ground water affected
Date Found:	01/27/1994
Date Stopped:	01/27/1994
Confirm Date:	/ /
Submit Workplan:	Not reported
Prelim Assess:	02/02/1994
Desc Pollution:	Not reported
Remed Plan:	/ /
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	02/07/1994
Enforce Date:	Not reported
Closed Date:	Not reported
Enforce Type:	Not reported
Pilot Program:	LOP
Basin Number:	908.22
GW Depth:	Not reported
Beneficial Use:	No Beneficial groundwater use
NPDES Number:	Not reported
Priority:	2B
File Dispn:	File discarded, case closed
Interim Remedial Actions:	No
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

SAN DIEGO CO. SAM:

Name:	CHEVRON STATION #91739
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Case Number:	H12922-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	Soils Only
Facility Status:	Closed Case
Date:	8/15/1994
Date Began:	8/18/1993

CHEVRON (Continued) **S102427537**

Name:	CHEVRON STATION #91739
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Case Number:	H12922-002
Agency:	DEH Site Assessment & Mitigation
Funding:	**POP**
Facility Type:	GW With No Beneficial Use Designation
Facility Status:	Closed Case
Date:	8/16/2004
Date Began:	1/27/1994

HMMD SAN DIEGO:

Name:	CHEVRON STATION #91739
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	Not reported
Business Type:	Not reported
EPA Id Number:	CAD981369937
APN:	Not reported
Last HMMD Inspection:	Not reported
Facility Telephone:	619-463-4525
Permit Status:	Permit Renewed
Permit Expiration:	Not reported
Date Last Updated:	08/30/2022
Facility Owner:	Not reported
Facility Mailing Address:	P.O. Box 6004 Attn: HES Permit Desk, SAN RAMON, CA 94583
Facility Mailing City:	Not reported
Facility Mailing State:	Not reported
Facility Mailing Zip:	Not reported
UST Owner:	Y
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	N
Generate Medical Waste:	Not reported

Inspection Violation:

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5301687
Return To Compliance Date:	2016-02-26T00:00:00.000
Nov:	No
Violation Classification:	Class I
Underground Storage Tank Id:	35868
Container/Tank Id:	Not reported
Last Update:	2022-08-30T01:26:53.000
Inspection Date:	2016-02-26T11:58:58.000
Violation Code:	2030016 (RD) Failure to continuously monitor the interstitial space of the tank, piping and/or sumps such that the leak detection activates an audible/visual alarm when a leak is detected. 23 CCR 2631(g), 2632(c)(2)(A)&(B), 2633(c), 2636(f)

CHEVRON (Continued) **S102427537**

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6602830
Return To Compliance Date:	2022-01-13T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	35134
Container/Tank Id:	Not reported
Last Update:	2022-08-30T01:26:53.000
Inspection Date:	2021-02-23T00:00:00.000
Violation Code:	2060020 (TCR 9a) Failure to meet one or more of the following requirements: Install or maintain a liquid-tight spill container. Have a minimum capacity of 5 gallons. Have a functional drain valve or other method for the removal of liquid from the spill container. Be resistant to galvanic corrosion. Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container, tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer. Tested by a certified UST service technician. Maintain records of spill containment testing for 36 months. 23 CCR 2635(b), 2637.1(a-c), 2665(a-b), 2712(b)(1)(F); HSC 25284.2

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	4964701
Return To Compliance Date:	2014-03-21T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	35134
Container/Tank Id:	Not reported
Last Update:	2022-08-30T01:26:53.000
Inspection Date:	2014-03-21T15:03:00.000
Violation Code:	2030054 Failure to comply with one or more of the following: maintain the spill bucket in good condition, containment free of debris/liquid, and/or to remove the contents of the spill bucket when a release/leak/spill was observed. 23 CCR 16 2635(b), 2715(c)(2).

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5595331
Return To Compliance Date:	2017-02-22T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	35134

CHEVRON (Continued) **S102427537**

Container/Tank Id:	Not reported
Last Update:	2022-08-30T01:26:53.000
Inspection Date:	2017-02-22T14:46:22.000
Violation Code:	2030016 (RD) Failure to continuously monitor the interstitial space of the tank, piping and/or sumps such that the leak detection activates an audible/visual alarm when a leak is detected. 23 CCR 2631(g), 2632(c)(2)(A)&(B), 2633(c), 2636(f)
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6084758
Return To Compliance Date:	2019-06-13T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	35135
Container/Tank Id:	Not reported
Last Update:	2022-08-30T01:26:53.000
Inspection Date:	2019-02-08T00:00:00.000
Violation Code:	2030065 (RD) Failure to maintain the interstitial space such that a breach in the primary or secondary containment is detected before the liquid or vapor phase of the hazardous substance stored in the UST tank is released into the environment, i.e., vapor, pressure, hydrostatic (VPH) monitoring. HSC 25290.1(e); 23 CCR 2630(d)
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5089191
Return To Compliance Date:	2015-03-13T00:00:00.000
Nov:	No
Violation Classification:	Not reported
Underground Storage Tank Id:	35134
Container/Tank Id:	Not reported
Last Update:	2022-08-30T01:26:53.000
Inspection Date:	2015-03-06T00:00:00.000
Violation Code:	2030025 Failure of the pressurized piping to meet one or more of the following requirements: monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour, and will restrict the flow of product through the piping or trigger an alarm when a release occurs. 23 CCR 16 2636(f)(2).
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	5832884
Return To Compliance Date:	2018-02-09T00:00:00.000
Nov:	No

CHEVRON (Continued) **S102427537**

Violation Classification:	Class II
Underground Storage Tank Id:	35134
Container/Tank Id:	Not reported
Last Update:	2022-08-30T01:26:53.000
Inspection Date:	2018-02-09T12:51:58.000
Violation Code:	2030016 (RD) Failure to continuously monitor the interstitial space of a double-walled tank with an audible and visual alarm system. 23 CCR 2631(g), 2632(c)(2)(A-B)
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Program Element:	Underground Storage Tank
Inspection Type:	Routine
Inspection Number:	6084758
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-08-30T01:26:53.000
Inspection Date:	2019-02-08T00:00:00.000
Violation Code:	2010013 Failure to have an approved UST Monitoring Plan. 23 CCR 2632(d)(1), 2634(d), 2641(h)

UST DTL:

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	CHEVRON STATION #91739
Tankid:	35868
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-08-30T01:27:00.000
Tank Capacityin Gallons:	6000
Tank Contents:	Biodiesel B6 - B99
Type Of Tank:	Double Wall
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-112922
Facility Type (Ust Facility):	Motor Vehicle Fueling
Tank Owner Name:	CHEVRON STATION #91739
Tankid:	35135
Tank Status:	Active
Date Ust Permanently Closed:	Not reported
Tank Use:	1a
Piping System Type:	Pressure
Last Updated:	2022-08-30T01:27:00.000
Tank Capacityin Gallons:	14000
Tank Contents:	Premium Unleaded

CHEVRON (Continued) **S102427537**

Type Of Tank: Double Wall

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Facility Id Number: 37-000-112922
Facility Type (Ust Facility): Motor Vehicle Fueling
Tank Owner Name: CHEVRON STATION #91739
Tankid: 35134
Tank Status: Active
Date Ust Permanently Closed: Not reported
Tank Use: 1a
Piping System Type: Pressure
Last Updated: 2022-08-30T01:27:00.000
Tank Capacityin Gallons: 20000
Tank Contents: Regular Unleaded
Type Of Tank: Double Wall

Waste and Materials:
Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227745
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-03-05T03:56:01.000
Chemical Name: Unleaded Gasoline - Petroleum Hydrocarbons
Common Name: Unleaded Gasoline - Petroleum Hydrocarbons
Case Number: 86290-81-5

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227747
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-03-05T03:56:01.000
Chemical Name: Alkaline Presoak 105 - Carwash Maintenance Product
Common Name: Alkaline Presoak 105 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197546
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-03-05T03:56:01.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0267632
Trade Secret: N

CHEVRON (Continued) **S102427537**

Hazardous Material Type: Mixture
Last Updated: 2021-03-13T12:01:39.000
Chemical Name: Low pH Cleaner 203 - Carwash Maintenance Product
Common Name: Low pH Cleaner 203 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0300510
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-05-29T00:42:19.000
Chemical Name: Unleaded Gasoline - Petroleum Hydrocarbons
Common Name: Unleaded Gasoline - Petroleum Hydrocarbons
Case Number: 86290-81-5

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0300511
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-05-29T00:42:19.000
Chemical Name: Diesel Fuel - Middle Distillates
Common Name: Diesel Fuel - Middle Distillates
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0300512
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-05-29T00:42:19.000
Chemical Name: Alkaline Presoak 105 - Carwash Maintenance Product
Common Name: Alkaline Presoak 105 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0300513
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-05-29T00:42:19.000
Chemical Name: Low pH Cleaner 203 - Carwash Maintenance Product
Common Name: Low pH Cleaner 203 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0268214
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-05-29T00:42:19.000

CHEVRON (Continued) **S102427537**

Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0268215
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-05-29T00:42:19.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0268216
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-05-29T00:42:19.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HCHEM-0103988
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2017-02-28T02:32:42.000
Chemical Name: Blue Coral Hi pH 3692 - Carwash Presoak
Common Name: Blue Coral Hi pH 3692 - Carwash Presoak
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0085918
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-28T02:32:42.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0085919
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-28T02:32:42.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads

CHEVRON (Continued) **S102427537**

Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2016-HWAST-0085920
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2017-02-28T02:32:42.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227748
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-03-05T03:56:01.000
Chemical Name: Low pH Cleaner 204 - Carwash Maintenance Product
Common Name: Low pH Cleaner 204 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197545
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-03-05T03:56:01.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HWAST-0197547
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-03-05T03:56:01.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0267630
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-03-13T12:01:39.000
Chemical Name: Diesel Fuel - Middle Distillates
Common Name: Diesel Fuel - Middle Distillates
Case Number: 68476-34-6

CHEVRON (Continued) **S102427537**

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HWAST-0237973
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2021-03-13T12:01:39.000
Chemical Name:	Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name:	Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HCHEM-0264286
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2020-05-19T01:15:42.000
Chemical Name:	Unleaded Gasoline - Petroleum Hydrocarbons
Common Name:	Unleaded Gasoline - Petroleum Hydrocarbons
Case Number:	86290-81-5

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HCHEM-0264287
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2020-05-19T01:15:42.000
Chemical Name:	Diesel Fuel - Middle Distillates
Common Name:	Diesel Fuel - Middle Distillates
Case Number:	68476-34-6

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HCHEM-0264288
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2020-05-19T01:15:42.000
Chemical Name:	Alkaline Presoak 105 - Carwash Maintenance Product
Common Name:	Alkaline Presoak 105 - Carwash Maintenance Product
Case Number:	Mixture

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2020-HCHEM-0264289
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2020-05-19T01:15:42.000
Chemical Name:	Low pH Cleaner 204 - Carwash Maintenance Product
Common Name:	Low pH Cleaner 204 - Carwash Maintenance Product
Case Number:	Mixture

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed

CHEVRON (Continued) **S102427537**

Active Permit: Y
Child Record Id: DEH2020-HWAST-0234843
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-05-19T01:15:43.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0234844
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-05-19T01:15:43.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0234845
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2020-05-19T01:15:43.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2019-HCHEM-0227746
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2020-03-05T03:56:01.000
Chemical Name: Diesel Fuel - Middle Distillates
Common Name: Diesel Fuel - Middle Distillates
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0267631
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-03-13T12:01:39.000
Chemical Name: Alkaline Presoak 105 - Carwash Maintenance Product
Common Name: Alkaline Presoak 105 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0237971

CHEVRON (Continued) **S102427537**

Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-03-13T12:01:39.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0309241
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-02-17T01:05:17.000
Chemical Name: Unleaded Gasoline - Petroleum Hydrocarbons
Common Name: Unleaded Gasoline - Petroleum Hydrocarbons
Case Number: 86290-81-5

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0277284
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-02-17T01:05:17.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0277285
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-02-17T01:05:17.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0277286
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-02-17T01:05:17.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0301502
Trade Secret: N
Hazardous Material Type: Mixture

CHEVRON (Continued) **S102427537**

Last Updated:	2021-06-12T02:27:00.000
Chemical Name:	Unleaded Gasoline - Petroleum Hydrocarbons
Common Name:	Unleaded Gasoline - Petroleum Hydrocarbons
Case Number:	86290-81-5
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0301503
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2021-06-12T02:27:00.000
Chemical Name:	Diesel Fuel - Middle Distillates
Common Name:	Diesel Fuel - Middle Distillates
Case Number:	68476-34-6
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0301504
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2021-06-12T02:27:00.000
Chemical Name:	Alkaline Presoak 105 - Carwash Maintenance Product
Common Name:	Alkaline Presoak 105 - Carwash Maintenance Product
Case Number:	Mixture
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HCHEM-0301505
Trade Secret:	N
Hazardous Material Type:	Mixture
Last Updated:	2021-06-12T02:27:00.000
Chemical Name:	Low pH Cleaner 203 - Carwash Maintenance Product
Common Name:	Low pH Cleaner 203 - Carwash Maintenance Product
Case Number:	Mixture
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HWAST-0269295
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2021-06-12T02:27:01.000
Chemical Name:	Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name:	Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number:	Not reported
Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2021-HWAST-0269296
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2021-06-12T02:27:01.000
Chemical Name:	Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads

CHEVRON (Continued) **S102427537**

Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HWAST-0269297
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-06-12T02:27:01.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0183913
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-20T01:23:26.000
Chemical Name: Unleaded Gasoline - Petroleum Hydrocarbons
Common Name: Unleaded Gasoline - Petroleum Hydrocarbons
Case Number: 86290-81-5

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0183914
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-20T01:23:26.000
Chemical Name: Diesel Fuel - Middle Distillates
Common Name: Diesel Fuel - Middle Distillates
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0158201
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-04-20T01:23:27.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0158202
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-04-20T01:23:27.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

CHEVRON (Continued) **S102427537**

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HCHEM-0267629
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2021-03-13T12:01:39.000
Chemical Name: Unleaded Gasoline - Petroleum Hydrocarbons
Common Name: Unleaded Gasoline - Petroleum Hydrocarbons
Case Number: 86290-81-5

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323388
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-11T01:10:01.000
Chemical Name: Unleaded Gasoline - Petroleum Hydrocarbons
Common Name: Unleaded Gasoline - Petroleum Hydrocarbons
Case Number: 86290-81-5

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323389
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-11T01:10:01.000
Chemical Name: Alkaline Presoak 105 - Carwash Maintenance Product
Common Name: Alkaline Presoak 105 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323390
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-11T01:10:01.000
Chemical Name: Low pH Cleaner 203 - Carwash Maintenance Product
Common Name: Low pH Cleaner 203 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0323391
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-03-11T01:10:01.000
Chemical Name: R80/B20 - Renewable Diesel Biodiesel Blend
Common Name: R80/B20 - Renewable Diesel Biodiesel Blend
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed

CHEVRON (Continued) **S102427537**

Active Permit: Y
Child Record Id: DEH2022-HWAST-0290467
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-11T01:10:02.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0290468
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-11T01:10:02.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0290469
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-03-11T01:10:02.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0183915
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-20T01:23:26.000
Chemical Name: Alkaline Presoak 105 - Carwash Maintenance Product
Common Name: Alkaline Presoak 105 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HCHEM-0183916
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2019-04-20T01:23:26.000
Chemical Name: Low pH Cleaner 204 - Carwash Maintenance Product
Common Name: Low pH Cleaner 204 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2018-HWAST-0158200

CHEVRON (Continued) **S102427537**

Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2019-04-20T01:23:27.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0143138
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-04-09T16:55:14.000
Chemical Name: Petroleum Hydrocarbons
Common Name: Unleaded Gasoline
Case Number: 86290-81-5

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0143139
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-04-09T16:55:14.000
Chemical Name: Middle Distillates
Common Name: Diesel Fuel
Case Number: 68476346

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HCHEM-0143140
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2018-04-09T16:55:14.000
Chemical Name: Blue Coral Hi pH 3692 - Carwash Presoak
Common Name: Blue Coral Hi pH 3692 - Carwash Presoak
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0121801
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-04-09T16:55:14.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0121802
Trade Secret: N
Hazardous Material Type: Not reported

CHEVRON (Continued) **S102427537**

Last Updated: 2018-04-09T16:55:14.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2017-HWAST-0121803
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2018-04-09T16:55:14.000
Chemical Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name: Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2020-HWAST-0237972
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2021-03-13T12:01:39.000
Chemical Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name: Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0309242
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-02-17T01:05:17.000
Chemical Name: Diesel Fuel - Middle Distillates
Common Name: Diesel Fuel - Middle Distillates
Case Number: 68476-34-6

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0309243
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-02-17T01:05:17.000
Chemical Name: Alkaline Presoak 105 - Carwash Maintenance Product
Common Name: Alkaline Presoak 105 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2021-HCHEM-0309244
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-02-17T01:05:17.000
Chemical Name: Low pH Cleaner 203 - Carwash Maintenance Product

CHEVRON (Continued) **S102427537**

Common Name: Low pH Cleaner 203 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0339380
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-08-30T01:26:59.000
Chemical Name: Unleaded Gasoline - Petroleum Hydrocarbons
Common Name: Unleaded Gasoline - Petroleum Hydrocarbons
Case Number: 86290-81-5

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0339381
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-08-30T01:26:59.000
Chemical Name: Alkaline Presoak 105 - Carwash Maintenance Product
Common Name: Alkaline Presoak 105 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0339382
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-08-30T01:26:59.000
Chemical Name: Low pH Cleaner 203 - Carwash Maintenance Product
Common Name: Low pH Cleaner 203 - Carwash Maintenance Product
Case Number: Mixture

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HCHEM-0339383
Trade Secret: N
Hazardous Material Type: Mixture
Last Updated: 2022-08-30T01:26:59.000
Chemical Name: R80/B20 - Renewable Diesel Biodiesel Blend
Common Name: R80/B20 - Renewable Diesel Biodiesel Blend
Case Number: Not reported

Record ID: DEH2002-HUPFP-112922
Permit Status: Permit Renewed
Active Permit: Y
Child Record Id: DEH2022-HWAST-0306823
Trade Secret: N
Hazardous Material Type: Not reported
Last Updated: 2022-08-30T01:27:00.000
Chemical Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Common Name: Spill Bucket/Sump Water - Waste Gasoline/Water
Case Number: Not reported

CHEVRON (Continued) **S102427537**

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HWAST-0306824
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2022-08-30T01:27:00.000
Chemical Name:	Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Common Name:	Absorbent Spill Pads - Waste Polypropylene Absorbent Spill Pads
Case Number:	Not reported

Record ID:	DEH2002-HUPFP-112922
Permit Status:	Permit Renewed
Active Permit:	Y
Child Record Id:	DEH2022-HWAST-0306825
Trade Secret:	N
Hazardous Material Type:	Not reported
Last Updated:	2022-08-30T01:27:00.000
Chemical Name:	Used Filters, Hoses and Nozzles - Waste Metal Solids
Common Name:	Used Filters, Hoses and Nozzles - Waste Metal Solids
Case Number:	Not reported

Name:	CHEVRON STATION #91739
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	112922
Business Type:	6HK28
EPA Id Number:	CAD981369937
APN:	479-081-01-00
Last HMMD Inspection:	03/02/2012
Facility Telephone:	619-463-4525
Permit Status:	OPEN
Permit Expiration:	03/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	CHEVRON PRODUCTS COMPANY
Facility Mailing Address:	PO BOX 6004
Facility Mailing City:	SAN RAMON
Facility Mailing State:	CA
Facility Mailing Zip:	94583
UST Owner:	CHEVRON USA INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	112922
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	DIESEL
Other Information:	UNDERGROUND TANK 112922 T006
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

CHEVRON (Continued) **S102427537**

Permit Number: 112922
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: PREMIUM UNLEADED
Other Information: UNDERGROUND TANK 112922 T007
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 112922
Update Date: 11/02/2012
Case Number: Not reported
Name: PRESOAK 1000 PINA COLADA
Other Information: SOAP
Material Waste: Material
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 112922
Update Date: 11/02/2012
Case Number: 8006-61-9
Name: REGULAR UNLEADED
Other Information: UNDERGROUND TANK 112922 T005
Material Waste: Material
Hazardous Categories 1: FIRE
Hazardous Categories 2: Not reported

Permit Number: 112922
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 213 HYDROCARBON SOLVENTS
Other Information: FUEL/H2O WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 112922
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED FUEL FILTERS/FILTER RECYCLING SVCS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/20/2007
Violation Code: 6HV3107
Violation: MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation: Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012

CHEVRON (Continued) **S102427537**

Inspection Date: 09/20/2007
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/20/2007
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/20/2007
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3152
Violation: ALL MAINT/MONITOR RECORDS NOT AVAILABLE
Violation Citation: All maintenance/monitoring/calibration/ repair records not available. 25293; 2712 (b)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012

CHEVRON (Continued) **S102427537**

Inspection Date: 02/21/2003
Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3258
Violation: SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation: Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3258
Violation: SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation: Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3258
Violation: SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation: Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity: ACTIVE

CHEVRON (Continued) **S102427537**

Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	11/03/2004
Violation Code:	6HV3114
Violation:	2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation:	Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	11/03/2004
Violation Code:	6HV3160
Violation:	UST SYSTEM REPAIRS NOT PROPERLY DONE
Violation Citation:	UST system repair(s) not completed properly. 25292.1(c); 2660 (a)(k)(l)(m)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	11/03/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	03/10/2009
Violation Code:	6HV3255
Violation:	SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation:	Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	03/10/2009
Violation Code:	6HV1009
Violation:	HMBP: INADEQUATE SITE MAP
Violation Citation:	Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	03/02/2012
Violation Code:	6HV3256
Violation:	NO FUNCTIONAL DRAIN BOX/BACKUP
Violation Citation:	Fill box drain not functional and backup system is not available. 2635(b)(1)(C)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012

CHEVRON (Continued) **S102427537**

Inspection Date: 03/02/2012
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 03/02/2012
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 03/02/2012
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3251
Violation: MONITOR IN ALARM AT START OF INSPECTION
Violation Citation: Monitor in alarm at beginning of inspection. Alarm not investigated, recorded or reported. 2632 (c)(2)(B), 2650(e)(3)&(4), 2630(d)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3251
Violation: MONITOR IN ALARM AT START OF INSPECTION
Violation Citation: Monitor in alarm at beginning of inspection. Alarm not investigated, recorded or reported. 2632 (c)(2)(B), 2650(e)(3)&(4), 2630(d)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3251
Violation: MONITOR IN ALARM AT START OF INSPECTION
Violation Citation: Monitor in alarm at beginning of inspection. Alarm not investigated, recorded or reported. 2632 (c)(2)(B), 2650(e)(3)&(4), 2630(d)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL

CHEVRON (Continued) **S102427537**

Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

UST:
UST Name: UNDERGROUND TANK 112922 T011
Last Update: 2012-11-02 14:17:38
Permit Number: 112922
Tank Type: DOUBLE WALL
Additional Id: NT2443 (POST JULY 1, 2004 INSTALLATION); RT4841
Capacity Gallons: 6000
UST Contents: DIESEL
Other Content Info: DIESEL
Reg Status: ACTIVE
Remove Close Date: Not reported
Year Installed: 2005-04-01 00:00:00
Pipe Type: DOUBLE WALL
Delivery System: PRESSURE
Monitor Code: 40
UST Monitor Method: DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

UST Name: UNDERGROUND TANK 112922 T009
Last Update: 2012-11-02 14:17:38
Permit Number: 112922
Tank Type: DOUBLE WALL
Additional Id: NT2443 (POST JULY 1, 2004 INSTALLATION); RT4841
Capacity Gallons: 20000
UST Contents: REGULAR UNLEADED

CHEVRON (Continued) **S102427537**

Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2005-04-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM
UST Name:	UNDERGROUND TANK 112922 T010
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	NT2443 (POST JULY 1, 2004 INSTALLATION); RT4841
Capacity Gallons:	14000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUIM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2005-04-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM
UST Name:	UNDERGROUND TANK 112922 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	006/NT2443
Capacity Gallons:	12000
UST Contents:	MIDGRADE UNLEADED
Other Content Info:	MIDGRADE UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2005-05-04 00:00:00
Year Installed:	1994-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.
UST Name:	UNDERGROUND TANK 112922 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	007/NT2443
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2005-05-04 00:00:00
Year Installed:	1994-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE

CHEVRON (Continued) **S102427537**

Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.
UST Name:	UNDERGROUND TANK 112922 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	AT4819
Capacity Gallons:	1000
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2003-01-27 00:00:00
Year Installed:	1994-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	GRAVITY
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.
UST Name:	UNDERGROUND TANK 112922 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	SINGLE WALL
Additional Id:	AT4819
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1994-07-02 00:00:00
Year Installed:	Not reported
Pipe Type:	LINED TRENCH
Delivery System:	PRESSURE
Monitor Code:	90
UST Monitor Method:	NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION
UST Name:	UNDERGROUND TANK 112922 T002
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	SINGLE WALL
Additional Id:	2 PLUS CONTENTS
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1994-07-02 00:00:00
Year Installed:	Not reported
Pipe Type:	LINED TRENCH
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR
UST Name:	UNDERGROUND TANK 112922 T003
Last Update:	2012-11-02 14:17:38

CHEVRON (Continued) **S102427537**

Permit Number:	112922
Tank Type:	SINGLE WALL
Additional Id:	3
Capacity Gallons:	10000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	REMOVED
Remove Close Date:	1994-07-02 00:00:00
Year Installed:	Not reported
Pipe Type:	LINED TRENCH
Delivery System:	PRESSURE
Monitor Code:	05
UST Monitor Method:	SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name:	UNDERGROUND TANK 112922 T004
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	SINGLE WALL
Additional Id:	4
Capacity Gallons:	1000
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	1994-07-02 00:00:00
Year Installed:	Not reported
Pipe Type:	Not reported
Delivery System:	Not reported
Monitor Code:	07
UST Monitor Method:	SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 112922 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	005/ RT2772/NT2443
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2005-05-04 00:00:00
Year Installed:	1994-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.

Name:	CHEVRON STATION #91739
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	112922
Business Type:	6HK28
EPA Id Number:	CAD981369937
APN:	479-081-01-00

CHEVRON (Continued) **S102427537**

Last HMMD Inspection:	03/02/2012
Facility Telephone:	619-463-4525
Permit Status:	OPEN
Permit Expiration:	03/31/2013
Date Last Updated:	11/02/2012
Facility Owner:	CHEVRON PRODUCTS COMPANY
Facility Mailing Address:	PO BOX 6004
Facility Mailing City:	SAN RAMON
Facility Mailing State:	CA
Facility Mailing Zip:	94583
UST Owner:	CHEVRON USA INC
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Y
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	112922
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	DIESEL
Other Information:	UNDERGROUND TANK 112922 T006
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	112922
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	PREMIUM UNLEADED
Other Information:	UNDERGROUND TANK 112922 T007
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	112922
Update Date:	11/02/2012
Case Number:	Not reported
Name:	PRESOAK 1000 PINA COLADA
Other Information:	SOAP
Material Waste:	Material
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	112922
Update Date:	11/02/2012
Case Number:	8006-61-9
Name:	REGULAR UNLEADED
Other Information:	UNDERGROUND TANK 112922 T005
Material Waste:	Material
Hazardous Categories 1:	FIRE
Hazardous Categories 2:	Not reported

Permit Number:	112922
Update Date:	11/02/2012
Case Number:	Not reported

CHEVRON (Continued) **S102427537**

Name: WASTE 213 HYDROCARBON SOLVENTS
Other Information: FUEL/H2O WASTE
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Permit Number: 112922
Update Date: 11/02/2012
Case Number: Not reported
Name: WASTE 352 ORGANIC SOLIDS (OTHER)
Other Information: USED FUEL FILTERS/FILTER RECYCLING SVCS
Material Waste: Waste
Hazardous Categories 1: Not reported
Hazardous Categories 2: Not reported

Violations Active Permits:
Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/20/2007
Violation Code: 6HV3107
Violation: MONITORING PROCEDURES NOT AVAIL/TO HMD
Violation Citation: Monitoring procedures not available/complete/submitted to HMD 2632(b)& (d), 2634(d), 2641(h), 2711(a)(9)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/20/2007
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/20/2007
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/20/2007
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012

CHEVRON (Continued) **S102427537**

Inspection Date: 02/21/2003
Violation Code: 6HV3152
Violation: ALL MAINT/MONITOR RECORDS NOT AVAILABLE
Violation Citation: All maintenance/monitoring/calibration/ repair records not available. 25293; 2712 (b)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 02/21/2003
Violation Code: 6HV3257
Violation: 2NDRY CONTAINMENT NOT LIQUID FREE
Violation Citation: Secondary containment system components not liquid free. 2631(d)(4)
Activity: ACTIVE

CHEVRON (Continued) **S102427537**

Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	02/21/2003
Violation Code:	6HV3258
Violation:	SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation:	Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	02/21/2003
Violation Code:	6HV3258
Violation:	SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation:	Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	02/21/2003
Violation Code:	6HV3258
Violation:	SENSORS NOT AT LOW POINT OR ADEQUATELY
Violation Citation:	Sensors not placed adequately and/or at low point in sumps. 2641(a), 25291(a)(7)(C)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	11/03/2004
Violation Code:	6HV3114
Violation:	2NDRY CONT TEST NOT DONE/SENT TO CUPA
Violation Citation:	Secondary containment testing not done at 6/36 months and/or not sent to CUPA within 30 days. 25284.1; 2637(a)&(e)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	11/03/2004
Violation Code:	6HV3160
Violation:	UST SYSTEM REPAIRS NOT PROPERLY DONE
Violation Citation:	UST system repair(s) not completed properly. 25292.1(c); 2660 (a)(k)(l)(m)
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	11/03/2004
Violation Code:	6HV3263
Violation:	MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation:	Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity:	ACTIVE
Permit Number:	112922
Update Date:	11/02/2012
Inspection Date:	03/10/2009

CHEVRON (Continued) **S102427537**

Violation Code: 6HV3255
Violation: SPILL CONTAIN. NOT DRY/IN GOOD CONDITION
Violation Citation: Spill container is not in good condition and/or liquid free. 2635(b)(1), 2636(a)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 03/10/2009
Violation Code: 6HV1009
Violation: HMBP: INADEQUATE SITE MAP
Violation Citation: Business Plan does not have a site map which provides sufficient or complete information for emergency response agencies. HSC 25509(a)(5) & 25505(a)(2)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 03/02/2012
Violation Code: 6HV3256
Violation: NO FUNCTIONAL DRAIN BOX/BACKUP
Violation Citation: Fill box drain not functional and backup system is not available. 2635(b)(1)(C)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 03/02/2012
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 03/02/2012
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 03/02/2012
Violation Code: 6HV3252
Violation: AUDIO&VISUAL ALARMS NOT WORKING OK
Violation Citation: All audible and/or visual alarms not functioning properly. 2632(c)(2)(B), 2636(f)(1)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3251
Violation: MONITOR IN ALARM AT START OF INSPECTION

CHEVRON (Continued) **S102427537**

Violation Citation: Monitor in alarm at beginning of inspection. Alarm not investigated, recorded or reported. 2632 (c)(2)(B), 2650(e)(3)&(4), 2630(d)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3251
Violation: MONITOR IN ALARM AT START OF INSPECTION
Violation Citation: Monitor in alarm at beginning of inspection. Alarm not investigated, recorded or reported. 2632 (c)(2)(B), 2650(e)(3)&(4), 2630(d)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3251
Violation: MONITOR IN ALARM AT START OF INSPECTION
Violation Citation: Monitor in alarm at beginning of inspection. Alarm not investigated, recorded or reported. 2632 (c)(2)(B), 2650(e)(3)&(4), 2630(d)
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3263
Violation: MONITOR SYSTEM NOT ALL FUNCTIONAL
Violation Citation: Monitoring system components &/or devices are not all functional. 2630, 2641(j), 2632
Activity: ACTIVE

Permit Number: 112922
Update Date: 11/02/2012
Inspection Date: 09/05/2006
Violation Code: 6HV3411
Violation: LLD NOT INSTALLED/NOT FUNCTIONAL
Violation Citation: DOUBLE WALLED PRESSURIZED PIPING-Including Under Dispenser Containment (UDC):Line leak detector is not installed, not functional, or not tested. 2636(f)(2), 25284.1(a)(4)(C), 2641(j)

CHEVRON (Continued) **S102427537**

Activity: ACTIVE

UST:

UST Name:	UNDERGROUND TANK 112922 T011
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	NT2443 (POST JULY 1, 2004 INSTALLATION); RT4841
Capacity Gallons:	6000
UST Contents:	DIESEL
Other Content Info:	DIESEL
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2005-04-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

UST Name:	UNDERGROUND TANK 112922 T009
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	NT2443 (POST JULY 1, 2004 INSTALLATION); RT4841
Capacity Gallons:	20000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2005-04-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

UST Name:	UNDERGROUND TANK 112922 T010
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	NT2443 (POST JULY 1, 2004 INSTALLATION); RT4841
Capacity Gallons:	14000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUIM UNLEADED
Reg Status:	ACTIVE
Remove Close Date:	Not reported
Year Installed:	2005-04-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	40
UST Monitor Method:	DW TANK DW PRESSURIZED PIPE W/INTERSTITIAL HYDROSTATIC TANK, SUMPS & UDCs; PIPING UNDER CONSTANT VACUUM, WITH SHUT-OFF & ALARM

UST Name:	UNDERGROUND TANK 112922 T006
Last Update:	2012-11-02 14:17:38
Permit Number:	112922

CHEVRON (Continued) **S102427537**

Tank Type:	DOUBLE WALL
Additional Id:	006/NT2443
Capacity Gallons:	12000
UST Contents:	MIDGRADE UNLEADED
Other Content Info:	MIDGRADE UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2005-05-04 00:00:00
Year Installed:	1994-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.

UST Name:	UNDERGROUND TANK 112922 T007
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	007/NT2443
Capacity Gallons:	12000
UST Contents:	PREMIUM UNLEADED
Other Content Info:	PREMIUM UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2005-05-04 00:00:00
Year Installed:	1994-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.

UST Name:	UNDERGROUND TANK 112922 T008
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	AT4819
Capacity Gallons:	1000
UST Contents:	Not reported
Other Content Info:	WASTE OIL
Reg Status:	REMOVED
Remove Close Date:	2003-01-27 00:00:00
Year Installed:	1994-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	GRAVITY
Monitor Code:	21
UST Monitor Method:	DW TANK DW SUCTION AND/ OR GRAVITY PIPING WITH INTERSTITIAL MONITORS: INTERSTITIAL.

UST Name:	UNDERGROUND TANK 112922 T001
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	SINGLE WALL
Additional Id:	AT4819
Capacity Gallons:	10000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED

CHEVRON (Continued) **S102427537**

Remove Close Date: 1994-07-02 00:00:00
Year Installed: Not reported
Pipe Type: LINED TRENCH
Delivery System: PRESSURE
Monitor Code: 90
UST Monitor Method: NO MONITORING ALTERNATIVE SELECTED. VERIFY AND ENTER MONITORING ALTERNATIVE DURING INSPECTION

UST Name: UNDERGROUND TANK 112922 T002
Last Update: 2012-11-02 14:17:38
Permit Number: 112922
Tank Type: SINGLE WALL
Additional Id: 2 PLUS CONTENTS
Capacity Gallons: 10000
UST Contents: REGULAR UNLEADED
Other Content Info: REGULAR UNLEADED
Reg Status: REMOVED
Remove Close Date: 1994-07-02 00:00:00
Year Installed: Not reported
Pipe Type: LINED TRENCH
Delivery System: PRESSURE
Monitor Code: 05
UST Monitor Method: SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name: UNDERGROUND TANK 112922 T003
Last Update: 2012-11-02 14:17:38
Permit Number: 112922
Tank Type: SINGLE WALL
Additional Id: 3
Capacity Gallons: 10000
UST Contents: PREMIUM UNLEADED
Other Content Info: PREMIUM UNLEADED
Reg Status: REMOVED
Remove Close Date: 1994-07-02 00:00:00
Year Installed: Not reported
Pipe Type: LINED TRENCH
Delivery System: PRESSURE
Monitor Code: 05
UST Monitor Method: SW TANK DW PIPE W/ POS SHUTOFF-ALARM ON LLD W/ SIRS:SIR ANALY MONTHLY, TANK TEST BIENNIALLY, PIPE TEST ANN 0.1 G/HR OR MO 0.2 G/HR

UST Name: UNDERGROUND TANK 112922 T004
Last Update: 2012-11-02 14:17:38
Permit Number: 112922
Tank Type: SINGLE WALL
Additional Id: 4
Capacity Gallons: 1000
UST Contents: Not reported
Other Content Info: WASTE OIL
Reg Status: REMOVED
Remove Close Date: 1994-07-02 00:00:00
Year Installed: Not reported
Pipe Type: Not reported
Delivery System: Not reported
Monitor Code: 07
UST Monitor Method: SW TANK SW PRESSURE PIPE W/RESTRICTIVE LLD W/DAILY RECONCILIATION OR

CHEVRON (Continued) **S102427537**

WEEKLY GAUGING: TANK AND PIPE TEST ANNUALLY

UST Name:	UNDERGROUND TANK 112922 T005
Last Update:	2012-11-02 14:17:38
Permit Number:	112922
Tank Type:	DOUBLE WALL
Additional Id:	005/ RT2772/NT2443
Capacity Gallons:	12000
UST Contents:	REGULAR UNLEADED
Other Content Info:	REGULAR UNLEADED
Reg Status:	REMOVED
Remove Close Date:	2005-05-04 00:00:00
Year Installed:	1994-01-01 00:00:00
Pipe Type:	DOUBLE WALL
Delivery System:	PRESSURE
Monitor Code:	20
UST Monitor Method:	DW TANK DW PRESSURE PIPE W/ SHUT OFF AND ALARM ON LINE LEAK DETECTOR: INTERSTITIAL.

SWEEPS UST:

Name:	LARRYS CHEVRON SERVICE
Address:	7209 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	12922
Number:	9
Board Of Equalization:	44-022667
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012922-000001
Tank Status:	A
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	4

Name:	LARRYS CHEVRON SERVICE
Address:	7209 BROADWAY
City:	LEMON GROVE
Status:	Active
Comp Number:	12922
Number:	9
Board Of Equalization:	44-022667
Referral Date:	Not reported
Action Date:	06-26-92
Created Date:	02-29-88
Owner Tank Id:	Not reported
SWRCB Tank Id:	37-000-012922-000002
Tank Status:	A
Capacity:	10000
Active Date:	Not reported
Tank Use:	M.V. FUEL

CHEVRON (Continued) **S102427537**

STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: LARRYS CHEVRON SERVICE
Address: 7209 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12922
Number: 9
Board Of Equalization: 44-022667
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012922-000003
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: LEADED
Number Of Tanks: Not reported

Name: LARRYS CHEVRON SERVICE
Address: 7209 BROADWAY
City: LEMON GROVE
Status: Active
Comp Number: 12922
Number: 9
Board Of Equalization: 44-022667
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-012922-000004
Tank Status: A
Capacity: 1000
Active Date: Not reported
Tank Use: PETROLEUM
STG: W
Content: Not reported
Number Of Tanks: Not reported

CORTESE:
Name: CHEVRON STATION #91739
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 919451502
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607301425
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported

CHEVRON (Continued) **S102427537**

Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

EMI:

Name:	CHEVRON / LEMON GROVE
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Year:	1999
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON / LEMON GROVE
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Year:	2000
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON / LEMON GROVE
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502

CHEVRON (Continued) **S102427537**

Year:	2001
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON / LEMON GROVE
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Year:	2002
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON LEMON GROVE
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Year:	2003
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

CHEVRON (Continued) **S102427537**

Name:	CHEVRON LEMON GROVE
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Year:	2004
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.8651136
Reactive Organic Gases Tons/Yr:	1.8651136
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON LEMON GROVE
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Year:	2005
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.8651136
Reactive Organic Gases Tons/Yr:	1.8651136
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451502
Year:	2006
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

CHEVRON (Continued) **S102427537**

Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: CHEVRON
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 945010000
Year: 2007
County Code: 37
Air Basin: SD
Facility ID: 4501
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2.96
Reactive Organic Gases Tons/Yr: 2.96
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: CHEVRON
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Year: 2008
County Code: 37
Air Basin: SD
Facility ID: 4501
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2.96
Reactive Organic Gases Tons/Yr: 2.96
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: CHEVRON
Address: 7209 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Year: 2009
County Code: 37
Air Basin: SD
Facility ID: 4501
Air District Name: SD
SIC Code: 5541
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 2.96
Reactive Organic Gases Tons/Yr: 2.96

CHEVRON (Continued) **S102427537**

Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2010
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2011
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2012
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported

CHEVRON (Continued) **S102427537**

Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2013
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2014
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2015
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD

CHEVRON (Continued) **S102427537**

SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2016
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2017
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2018
County Code:	37

CHEVRON (Continued) **S102427537**

Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	CHEVRON
Address:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2019
County Code:	37
Air Basin:	SD
Facility ID:	4501
Air District Name:	SD
SIC Code:	5541
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2.96
Reactive Organic Gases Tons/Yr:	2.96
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

HIST CORTESE:

edr_fname:	CHEVRON SERVICE STA #9-17
edr_fadd1:	7209 BROADWAY
City,State,Zip:	LEMON GROVE, CA 92045
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT2676

O97 **CULLIGAN WATER / U.S. FILTER** **LUST** **S104816342**
ESE **3536 OLIVE STREET** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945**
0.353 mi.
1866 ft. **Site 2 of 3 in cluster O**

Relative:
Lower

Actual:
454 ft.

LUST REG 9:

Region:	9
Status:	Preliminary site assessment underway
Case Number:	9UT4100
Local Case:	H20784-002
Substance:	Gasoline
Qty Leaked:	Not reported

CULLIGAN WATER / U.S. FILTER (Continued) **S104816342**

Abate Method: Not reported
Local Agency: San Diego
How Found: Other Means
How Stopped: Other Means
Source: Tank
Cause: Overfill
Lead Agency: Local Agency
Case Type: Soil only
Date Found: 11/16/2000
Date Stopped: / /
Confirm Date: / /
Submit Workplan: Not reported
Prelim Assess: 11/16/2000
Desc Pollution: Not reported
Remed Plan: / /
Remed Action: Not reported
Began Monitor: Not reported
Release Date: 11/16/2000
Enforce Date: Not reported
Closed Date: Not reported
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 908.22
GW Depth: Not reported
Beneficial Use: MUNBU
NPDES Number: Not reported
Priority: Not reported
File Dispn: Administratively opened on database, however no file physically exists
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

O98 **CULLIGAN WATER CONDITIONING OF** **LUST** **U001571842**
ESE **3536 OLIVE ST** **SAN DIEGO CO. SAM** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **CERS HAZ WASTE**
0.353 mi. **SWEEPS UST**
1866 ft. **Site 3 of 3 in cluster O** **HIST UST**
Cortese
Relative: **SAN DIEGO CO LOP**
Lower **CERS**

Actual:
454 ft.

LUST:
Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City,State,Zip: LEMON GROVE, CA 91945
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607391318
Global Id: T0607391318
Latitude: 32.7437894722572
Longitude: -117.032418251038
Status: Completed - Case Closed
Status Date: 03/19/2008
Case Worker: JC
RB Case Number: Not reported
Local Agency: SAN DIEGO COUNTY LOP
File Location: Local Agency
Local Case Number: H20784-002

CULLIGAN WATER CONDITIONING OF (Continued) **U001571842**

Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607391318
Contact Type: Local Agency Caseworker
Contact Name: JAMES CLAY
Organization Name: SAN DIEGO COUNTY LOP
Address: P.O. Box 129261
City: San Diego
Email: james.clay@sdcounty.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607391318
Action Type: Other
Date: 11/16/2000
Action: Leak Began

Global Id: T0607391318
Action Type: Other
Date: 11/30/2000
Action: Leak Reported

Global Id: T0607391318
Action Type: ENFORCEMENT
Date: 12/06/2000
Action: Notice of Responsibility

Global Id: T0607391318
Action Type: ENFORCEMENT
Date: 03/21/2008
Action: Closure/No Further Action Letter

Global Id: T0607391318
Action Type: Other
Date: 11/16/2000
Action: Leak Stopped

Global Id: T0607391318
Action Type: Other
Date: 11/16/2000
Action: Leak Discovery

LUST:
Global Id: T0607391318
Status: Open - Case Begin Date
Status Date: 11/16/2000

Global Id: T0607391318
Status: Completed - Case Closed
Status Date: 03/19/2008

SAN DIEGO CO. SAM:

CULLIGAN WATER CONDITIONING OF (Continued) **U001571842**

Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City,State,Zip: LEMON GROVE, CA 91945
Case Number: H20784-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 9/22/1995
Date Began: 8/12/1986

Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City,State,Zip: LEMON GROVE, CA 91945
Case Number: H20784-002
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - State Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 3/19/2008
Date Began: 11/16/2000

CERS HAZ WASTE:
Name: SPEEDY BUMPER REPAIR
Address: 3536 OLIVE ST STE A
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 618190
CERS ID: 10913287
CERS Description: Hazardous Waste Generator

SWEEPS UST:
Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City: LEMON GROVE
Status: Not reported
Comp Number: 20784
Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020784-000002
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: 2

Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City: LEMON GROVE
Status: Not reported
Comp Number: 20784

CULLIGAN WATER CONDITIONING OF (Continued) **U001571842**

Number: Not reported
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: Not reported
Created Date: Not reported
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020784-000003
Tank Status: Not reported
Capacity: 1000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: PRODUCT
Content: LEADED
Number Of Tanks: Not reported

Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City: LEMON GROVE
Status: Active
Comp Number: 20784
Number: 9
Board Of Equalization: Not reported
Referral Date: Not reported
Action Date: 06-26-92
Created Date: 02-29-88
Owner Tank Id: Not reported
SWRCB Tank Id: 37-000-020784-000001
Tank Status: A
Capacity: 10000
Active Date: Not reported
Tank Use: M.V. FUEL
STG: P
Content: REG UNLEADED
Number Of Tanks: 1

HIST UST:
Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City,State,Zip: LEMON GROVE, CA 92045
File Number: 0002b077
URL: https://documents.geotracker.waterboards.ca.gov/ustpdfs/pdf/0002b077.pdf
Region: STATE
Facility ID: 00000051653
Facility Type: Other
Other Type: Not reported
Contact Name: LAURANCE W. CLARK
Telephone: 6194638837
Owner Name: CULLIGAN WATER CONDITIONING OF
Owner Address: 3515 OLIVE ST.
Owner City,St,Zip: LEMON GROVE, CA 92045
Total Tanks: 0001

Tank Num: 001
Container Num: #1
Year Installed: 1984
Tank Capacity: 00010000
Tank Used for: PRODUCT

CULLIGAN WATER CONDITIONING OF (Continued) **U001571842**

Type of Fuel: UNLEADED
Container Construction Thickness: .167
Leak Detection: Stock Inventor, Vapor Sniff Well, Groundwater Monitoring Well, 10

Click here for Geo Tracker PDF:

CORTESE:
Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City,State,Zip: LEMON GROVE, CA 91945
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607391318
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

SAN DIEGO CO LOP:
Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City,State,Zip: LEMON GROVE, CA 91945
Record ID: DEH2000-LSAM-H20784-002
Record Status: Completed
Opened Date: 11/30/2000
Parcel Number: 480-043-17-00
Case Type: LOP - Local Oversight Program
Historical Name: CULLIGAN WATER CONDITIONING
SWRCB Global ID: T0607391318
Funding: S - LOP State Fund
Lead Agency: DEH/SAM
Lead Agency Date: 11/16/2000
Census Tract: 144.00
Community: Lemon Grove
Jurisdiction: LEMON GROVE
Watershed Basin Number: 908.22
Water Purveyor: HELIX WATER DISTRICT LAND
Fire Agency: HELIX WATER DISTRICT LAND
Latitude: 32.7438267
Longitude: -117.0318203
X MapCoord: 6321267.407
Y MapCoord: 1851320.341

CULLIGAN WATER CONDITIONING OF (Continued) **U001571842**

CERS:
Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 208157
CERS ID: T0607391318
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JAMES CLAY - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: CULLIGAN WATER CONDITIONING OF
Address: 3536 OLIVE ST
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 208157
CERS ID: T0607300254
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: JAMES CLAY - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Name: SPEEDY BUMPER REPAIR
Address: 3536 OLIVE ST STE A
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 618190
CERS ID: 10913287
CERS Description: Chemical Storage Facilities

Affiliation:
Affiliation Type Desc: Document Preparer
Entity Name: Sky Murphy
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer

CULLIGAN WATER CONDITIONING OF (Continued) **U001571842**

Entity Name:	Vicente Marin
Entity Title:	Owner
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Legal Owner
Entity Name:	Vicente Marin
Entity Title:	Not reported
Affiliation Address:	3536 Olive St Ste A
Affiliation City:	Lemon Grove
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	91945
Affiliation Phone:	(858) 910-8415,
Affiliation Type Desc:	Operator
Entity Name:	Vicente Marin
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(858) 910-8415,
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	3536 Olive St Ste A
Affiliation City:	Lemon Grove
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91945
Affiliation Phone:	,
Affiliation Type Desc:	Parent Corporation
Entity Name:	Speedy Bumper Repair
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Environmental Contact
Entity Name:	Vicente Marin
Entity Title:	Not reported
Affiliation Address:	3536 Olive St Ste A
Affiliation City:	Lemon Grove
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	91945

CULLIGAN WATER CONDITIONING OF (Continued) **U001571842**

Affiliation Phone: ,

Affiliation Type Desc: CUPA District
Entity Name: San Diego County Env Health Qlty
Entity Title: Not reported
Affiliation Address: PO Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 92112-9261
Affiliation Phone: (858) 505-6880,

Q99 **CITRONICA II** **CPS-SLIC S112833006**
ESE **3595 OLIVE AVENUE** **CERS N/A**
1/4-1/2 **LEMON GROVE, CA 91945**
0.374 mi.
1977 ft. **Site 1 of 4 in cluster Q**

Relative: **Lower**

Actual: **458 ft.**

CPS-SLIC:
Name: CITRONICA II
Address: 3595 OLIVE AVENUE
City,State,Zip: LEMON GROVE, CA 91945
Region: STATE
Facility Status: **Open - Site Assessment**
Status Date: 01/09/2013
Global Id: T10000004536
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: DEH2013-LSAM-000156
Latitude: 32.744367006306
Longitude: -117.031774520874
Case Type: Cleanup Program Site
Case Worker: EM
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Soil
Potential Contaminants of Concern: Arsenic
Site History: This is a new VAP case. This section will be updated as data is received.

Click here to access the California GeoTracker records for this facility:

CERS:
Name: CITRONICA II
Address: 3595 OLIVE AVENUE
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 239357
CERS ID: T10000004536
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: EWAN MOFFAT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA

CITRONICA II (Continued) **S112833006**

Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Q100 **CULLIGEN WATER CONDITIONI** **LUST** **S100850130**
ESE **3515 OLIVE** **CPS-SLIC** **N/A**
1/4-1/2 **LEMON GROVE, CA 92045** **Cortese**
0.377 mi. **HIST CORTESE**
1990 ft. **Site 2 of 4 in cluster Q** **HAZNET**
SAN DIEGO CO LOP
Relative: **CERS**
Lower **HWTS**

Actual:
455 ft.

LUST:
Name: CULLIGAN WATER CONDITIONING OF
Address: 3515 OLIVE ST
City,State,Zip: LEMON GROVE, CA 91945
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607300254
Global Id: T0607300254
Latitude: 32.7440607356059
Longitude: -117.031500112759
Status: Completed - Case Closed
Status Date: 09/22/1995
Case Worker: Not reported
RB Case Number: 9UT142
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H20784-001
Potential Media Affect: Aquifer used for drinking water supply
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607300254
Action Type: Other
Date: 08/12/1986
Action: Leak Began

Global Id: T0607300254
Action Type: Other
Date: 08/12/1986
Action: Leak Discovery

Global Id: T0607300254
Action Type: Other
Date: 08/12/1986
Action: Leak Reported

Global Id: T0607300254
Action Type: ENFORCEMENT
Date: 08/13/1986
Action: Notice of Responsibility

Global Id: T0607300254
Action Type: Other

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

Date: 08/12/1986
Action: Leak Stopped

Global Id: T0607300254
Action Type: ENFORCEMENT
Date: 09/22/1995
Action: Closure/No Further Action Letter

LUST:
Global Id: T0607300254
Status: Open - Case Begin Date
Status Date: 08/12/1986

Global Id: T0607300254
Status: Completed - Case Closed
Status Date: 09/22/1995

CPS-SLIC:
Name: CITYMARK LEMON GROVE
Address: 3515 OLIVE STREET
City,State,Zip: LEMON GROVE, CA 91945
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 03/28/2017
Global Id: T10000006534
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: DEH2015-LSAM-000287
Latitude: 32.7440313572619
Longitude: -117.031839655225
Case Type: Cleanup Program Site
Case Worker: EP
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern: Dichloroethene (DCE), Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Arsenic, Copper, Lead, Zinc, Total Petroleum Hydrocarbons (TPH)
Site History: The site property is approximately 1.14 acres in size and consists of one parcel of land identified by Assessor Parcel Number (APN) 480-043-42. The property was previously comprised of six contiguous parcels of land identified as 3515 and 3541 Olive Street and 3466 to 3530 Main Street in Lemon Grove, CA. The APNs associated with the six former parcels were 480-043-17, -18, -30, -31, -33, and -37. The property is currently zoned for commercial use. CityMark L. G., LLC is in the process of redeveloping the site to an 84-unit, four-level residential apartment complex with the ground floor used as a parking level and the three floors over the ground floor parking used for residential apartment units. The structure will comprise a total of approximately 126,624 square feet (ft), with approximately 32,089 ft of parking at grade and 94,535 ft for the occupied residential floors. The Phase I Environmental Site Assessment (ESA) report, dated July 18, 2014 and completed by SCS Engineers (SCS), summarizes results of the site investigation to assess the presence or likely presence of any recognizable environmental concerns on the subject

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

property. Based on the ESA report, SCS recommended further investigation of potential metal-bearing and petroleum hydrocarbon-impacted soil, and of VOC-impacted groundwater at the site. On July, 21, 2014, SCS advanced seven soil borings (B1 through B7) to depths ranging from 0.5 to 5 feet below ground surface (bgs) to assess the extent of the constituents of concern (CoCs) in the shallow soil at the site. Twenty-six soil samples were obtained and analyzed for total petroleum hydrocarbons and select metals. The results of this investigation were reported in the Limited Phase II Soil Sampling report dated September 9, 2014. A Soil Management Plan dated July 8, 2015, and completed by SCS, proposed the following: Per geotechnical requirements, the upper 2 feet of soil are required to be removed and recompacted for the purpose of the construction of the proposed project. Approximately 2,177 cubic yards (yd) of cut and 820 yd of fill are proposed, with approximately 1,357 yd of soil export proposed. Petroleum hydrocarbon and metal-impacted soil will be mitigated based on risk-driven remediation required by future land uses, to protect workers, and to control the proposed soil export and offsite reuse of soil deemed to be a waste. An onsite Soil Management Zone (SMZ) is proposed for the consolidation of petroleum hydrocarbon-bearing soil at the discretion of the responsible party. The location of the SMZ has been designated in a proposed parking area that is not proposed to have occupied areas built above ground surface. A Property Closure Report dated February 24, 2017, and completed by SCS, reported the following: Approximately 250 yd of petroleum hydrocarbon-bearing soil were placed and compacted as fill material in the SMZ. The SMZ is located within the courtyard area of the new project, where no subsurface utilities exist. It measures approximately 41 feet by 41 feet with the petroleum hydrocarbon-bearing soil buried approximately 4 feet below subgrade to 8 feet below subgrade with an approximately 4-foot clean soil layer above and approximately 4- to 6-inch thick concrete cap. Approximately 1,500 yd of arsenic-bearing soil were exported offsite for use as fill soil on expansion of an adjacent State Highway 94 off-ramp to Lemon Grove Avenue. The Lemon Grove Avenue Realignment Project is located at 7750 North Avenue and is under regulatory oversight of the San Diego RWQCB as case number 2090026, Global ID T10000000415. Approximately 200 yd of petroleum hydrocarbon-bearing soil were exported and disposed at the Otay Landfill on July 25, 2016. Approximately 170 yd of elevated arsenic-bearing soil were exported and disposed at the Otay Landfill between February 6, 2017 and February 23, 2017. Three-foot wide clean soil buffers were used within onsite unpaved utility trenches. The only exception was an approximately 15- to 20-foot long sewer lateral in the southwest portion of the site which only had a 2-foot wide clean soil buffer. On May 23 and June 14, 2016, six confirmation soil samples (C-1 through C-6) were collected from the subgrade elevation from the three APNs requested by DEH. Laboratory results report that only concentrations of arsenic exceeded the residential RSLs. Depth to groundwater onsite ranges between 8 feet to 26 feet bgs with depth to groundwater reported to be 14.41 feet bgs in the immediate vicinity of the SMZ. SCS concludes the dissolved chlorinated hydrocarbon plume is stable and is adequately assessed. In addition, the plume does not constitute a significant threat to the non-beneficial groundwater use at the site and vicinity. The groundwater monitoring, sampling, and assessment was completed under VAP case, H39803-001, Main Street Promenade, 3492 to 3510 Main Street, Lemon Grove, CA 91945. SCS

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

concludes that the site s current configuration and condition are protective of human health and the environment. The consultant recommends no further action and for DEH to administer case closure. DEH concurs with the aforementioned and closure of the case.

Click here to access the California GeoTracker records for this facility:

CORTESE:

Name:	CULLIGAN WATER CONDITIONING OF
Address:	3515 OLIVE ST
City,State,Zip:	LEMON GROVE, CA 91945
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607300254
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	CULLIGEN WATER CONDITIONI
edr_fadd1:	3515 OLIVE
City,State,Zip:	LEMON GROVE, CA 92045
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT142

HAZNET:

Name:	CULLIGAN WATER
Address:	3515 OLIVE ST
Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 919451738
Contact:	JACK CALE
Telephone:	8774285544
Mailing Name:	Not reported
Mailing Address:	885 GATEWAY CENTER WAY
Year:	2013
Gepaid:	CAC002738896
TSD EPA ID:	NVT330010000
CA Waste Code:	223 - Unspecified oil-containing waste

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

Disposal Method:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.0875
Year:	2013
Gepaid:	CAC002738896
TSD EPA ID:	CAD008252405
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Tons:	0.11
Year:	2013
Gepaid:	CAC002738896
TSD EPA ID:	NVT330010000
CA Waste Code:	291 - Latex waste
Disposal Method:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Tons:	0.125
Year:	2013
Gepaid:	CAC002738896
TSD EPA ID:	NVT330010000
CA Waste Code:	181 - Other inorganic solid waste
Disposal Method:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Tons:	0.0425

Additional Info:

Year:	2013
Gen EPA ID:	CAC002738896
Shipment Date:	20130812
Creation Date:	1/24/2017 18:31:06
Receipt Date:	20130904
Manifest ID:	008431224JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERVICES
TSDF EPA ID:	ARD069748192
Trans Name:	CLEAN HARBORS (DORADO)
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	F005
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.009
Waste Quantity:	18
Quantity Unit:	P
Additional Code 1:	F003
Additional Code 2:	D001
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130812

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

Creation Date:	1/24/2017 18:31:06
Receipt Date:	20130904
Manifest ID:	008431224JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERVICES
TSDF EPA ID:	ARD069748192
Trans Name:	CLEAN HARBORS (DORADO)
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	141 - Off-specification, aged, or surplus inorganics
RCRA Code:	D002
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.003
Waste Quantity:	6
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20130812
Creation Date:	1/24/2017 18:31:06
Receipt Date:	20130904
Manifest ID:	008431224JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERVICES
TSDF EPA ID:	ARD069748192
Trans Name:	CLEAN HARBORS (DORADO)
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	141 - Off-specification, aged, or surplus inorganics
RCRA Code:	D002
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.015
Waste Quantity:	30
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20130812
Creation Date:	1/24/2017 18:31:06
Receipt Date:	20130904
Manifest ID:	008431224JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERVICES
TSDF EPA ID:	ARD069748192
Trans Name:	CLEAN HARBORS (DORADO)

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	141 - Off-specification, aged, or surplus inorganics
RCRA Code:	D002
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.0175
Waste Quantity:	35
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130812
Creation Date:	1/18/2014 22:15:06
Receipt Date:	20130821
Manifest ID:	008431227JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008252405
Trans Name:	PACIFIC RESOURCE RECOVERY SERVICES
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	F005
Meth Code:	H061 - Fuel Blending Prior To Energy Recovery At Another Site
Quantity Tons:	0.11
Waste Quantity:	220
Quantity Unit:	P
Additional Code 1:	F003
Additional Code 2:	D001
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130812
Creation Date:	1/7/2014 22:15:06
Receipt Date:	20130822
Manifest ID:	008431226JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.025
Waste Quantity:	50
Quantity Unit:	P

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130812
Creation Date:	1/7/2014 22:15:06
Receipt Date:	20130822
Manifest ID:	008431226JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	223 - Unspecified oil-containing waste
RCRA Code:	Not reported
Meth Code:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons:	0.0875
Waste Quantity:	175
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130812
Creation Date:	1/7/2014 22:15:06
Receipt Date:	20130822
Manifest ID:	008431226JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	291 - Latex waste
RCRA Code:	Not reported
Meth Code:	H039 - Other Recovery Of Reclamation For Reuse Including Acid Regeneration, Organics Recovery Ect
Quantity Tons:	0.125
Waste Quantity:	250
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130812

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

Creation Date:	1/7/2014 22:15:06
Receipt Date:	20130822
Manifest ID:	008431226JJK
Trans EPA ID:	CAD981412356
Trans Name:	PACIFIC TRANS ENV SERVICES INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	US ECOLOGY
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	181 - Other inorganic solid waste Organics
RCRA Code:	Not reported
Meth Code:	H132 - Landfill Or Surface Impoundment That Will Be Closed As Landfill(To Include On-Site Treatment And/Or Stabilization)
Quantity Tons:	0.0175
Waste Quantity:	35
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

SAN DIEGO CO LOP:

Name:	CULLIGAN WATER CONDITIONING OF
Address:	3515 - 3517 OLIVE ST
City,State,Zip:	LEMON GROVE, CA 91945-1738
Record ID:	DEH1986-LSAM-H20784-001
Record Status:	Completed
Opened Date:	08/12/1986
Parcel Number:	480-043-17-00
Case Type:	LOP - Local Oversight Program
Historical Name:	CULLIGAN WATER CONDITIONING
SWRCB Global ID:	T0607300254
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	08/13/1986
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7438267
Longitude:	-117.0318203
X MapCoord:	6321267.407
Y MapCoord:	1851320.341

CERS:

Name:	CITYMARK LEMON GROVE
Address:	3515 OLIVE STREET
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	275250
CERS ID:	T10000006534
CERS Description:	Cleanup Program Site

CULLIGEN WATER CONDITIONI (Continued) **S100850130**

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	ED PAREDES - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	8585056806,

HWTS:

Name:	CULLIGAN WATER
Address:	3515 OLIVE ST
Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 91945
EPA ID:	CAC002738896
Inactive Date:	10/31/2013
Create Date:	08/01/2013
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	885 GATEWAY CENTER WAY
Mailing Address 2:	Not reported
Mailing City,State,Zip:	SAN DIEGO, CA 921024541
Owner Name:	CRH CALIFORNIA WATER DBA CULLIGAN W
Owner Address:	885 GATEWAY CENTER WAY
Owner Address 2:	Not reported
Owner City,State,Zip:	SAN DIEGO, CA 921024541
Contact Name:	JACK CALE
Contact Address:	3515 OLIVE ST
Contact Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 919451738
Facility Status:	Inactive
Facility Type:	TEMPORARY
Category:	STATE
Latitude:	32.743956
Longitude:	-117.032073

NAICS:

EPA ID:	CAC002738896
Create Date:	2013-08-01 09:26:14.950
NAICS Code:	312112
NAICS Description:	Bottled Water Manufacturing
Issued EPA ID Date:	2013-08-01 09:26:14.97000
Inactive Date:	2013-10-31 09:26:14.95000
Facility Name:	CULLIGAN WATER
Facility Address:	3515 OLIVE ST
Facility Address 2:	Not reported
Facility City:	LEMON GROVE
Facility County:	Not reported
Facility State:	CA
Facility Zip:	919451738

Q101 **CULLIGEN WATER CONDITIONING** **LUST** **S102428529**
ESE **3515 OLIVE ST** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945**
0.377 mi.
1990 ft. **Site 3 of 4 in cluster Q**

Relative: **Lower**
Actual: **455 ft.**

LUST REG 9:

Region:	9
Status:	Case Closed
Case Number:	9UT142
Local Case:	H20784-001
Substance:	Gasoline
Qty Leaked:	0
Abate Method:	Excavate and Dispose - remove contaminated soil and dispose in approved site
Local Agency:	San Diego
How Found:	Tank Closure
How Stopped:	Close Tank
Source:	Tank
Cause:	Corrosion
Lead Agency:	Local Agency
Case Type:	Other ground water affected
Date Found:	08/12/1986
Date Stopped:	08/12/1986
Confirm Date:	08/12/1986
Submit Workplan:	Not reported
Prelim Assess:	12/11/1996
Desc Pollution:	Not reported
Remed Plan:	09/21/1987
Remed Action:	Not reported
Began Monitor:	Not reported
Release Date:	08/12/1986
Enforce Date:	8/13/86
Closed Date:	9/22/95
Enforce Type:	SEL
Pilot Program:	LOP
Basin Number:	908.22
GW Depth:	1.1’
Beneficial Use:	NBNAB
NPDES Number:	Not reported
Priority:	1C
File Dispn:	File discarded, case closed
Interim Remedial Actions:	Yes
Cleanup and Abatement order Number:	Not reported
Waste Discharge Requirement Number:	Not reported

Q102 **LEMON GROVE AVENUE REALIGNMENT PROJECT** **CPS-SLIC** **S109277165**
ESE **7750 NORTH AVENUE** **CERS** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945**
0.379 mi.
1999 ft. **Site 4 of 4 in cluster Q**

Relative: **Lower**
Actual: **462 ft.**

CPS-SLIC:

Name:	LEMON GROVE AVENUE REALIGNMENT PROJECT
Address:	7750 NORTH AVENUE
City,State,Zip:	LEMON GROVE, CA 91945
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	05/19/2021
Global Id:	T10000000415

LEMON GROVE AVENUE REALIGNMENT PROJECT (Continued) **S109277165**

Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	Not reported
Latitude:	32.7449310007874
Longitude:	-117.031420469284
Case Type:	Cleanup Program Site
Case Worker:	BKM
Local Agency:	Not reported
RB Case Number:	2090026
File Location:	Regional Board
Potential Media Affected:	Soil
Potential Contaminants of Concern:	Arsenic
Site History:	Initial documents submitted 08/13/2008. Follow up report to be submitted June 2009.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	LEMON GROVE AVENUE REALIGNMENT PROJECT
Address:	7750 NORTH AVENUE
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	223137
CERS ID:	T10000000415
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	BRIAN K. McDANIEL - SAN DIEGO RWQCB (REGION 9)
Entity Title:	Not reported
Affiliation Address:	2375 NORTHSIDE DRIVE, SUITE 100
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	6195215897,

R103 **WALGREENS #12915** **LUST** **S110376299**
SW **7195 BROADWAY** **CERS HAZ WASTE** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **Cortese**
0.393 mi. **HAZNET**
2073 ft. **Site 1 of 2 in cluster R** **SAN DIEGO CO LOP**
CERS

Relative:
Lower

Actual:
409 ft.

LUST:

Name:	FORMER BILL'S SELF SERVICE
Address:	7195 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T10000002225
Global Id:	T10000002225
Latitude:	32.742147
Longitude:	-117.043216
Status:	Completed - Case Closed
Status Date:	10/16/2014
Case Worker:	CF
RB Case Number:	Not reported
Local Agency:	SAN DIEGO COUNTY LOP

WALGREENS #12915 (Continued) **S110376299**

File Location: Local Agency
Local Case Number: 106900-001
Potential Media Affect: Under Investigation
Potential Contaminants of Concern: Benzene, Toluene, Diesel, Gasoline
Site History: The site of a former service station on the southwest corner of Broadway and Massachusetts Avenue in Lemon Grove was re-developed as a Walgreen s Store in 2012. The service station was reportedly in operation from approximately 1953 to 1974. The station was demolished in the mid-to-late 1970s, and a new building was constructed on the property in 1979-1980 that was occupied by tenants, including a laundromat and a shoe store. Redevelopment of the property commenced in November 2011 with the demolishing of the building and removal of the asphalt pavement. A limited site assessment was performed on the property in January 2010 that included a geophysical survey, the advancement of six borings, and the collection of soil and soil vapor samples. Underground storage tanks (USTs) were not detected on the property. The borings were advanced to a maximum depth of 21.5 feet below ground surface (bgs) and a total of eight soil samples were collected. Groundwater was not encountered. Soil vapor samples were collected from each boring. Analytical results for the soil and soil vapor samples indicated impacts by petroleum hydrocarbons. The aromatic hydrocarbons benzene, toluene, ethylbenzene, and xylenes were detected in soil samples collected from one boring to a maximum depth of 10 feet bgs. Benzene, toluene, or ethylbenzene were detected in one or more soil vapor samples collected at a depth of 5 feet bgs. The maximum detected concentrations of benzene and toluene exceeded their respective commercial California Human Health Screening Levels (CHHSLs) of 122 and 378,000 micrograms per cubic meter (g/m3). Volatile organic compounds (VOCs) indicative of degraded gasoline (e.g., n-propyl benzene, trimethybenzene) were detected in both the soil and soil vapor samples. DEH opened an unauthorized release case (#106900-001) on June 29, 2010, based on the analytical results. A limited soil vapor risk evaluation for a commercial scenario was performed using January 2010 soil vapor sample results, the plans for the proposed Walgreen s Store, and the modified Johnson and Ettinger model. However, the maximum benzene concentration was detected beneath the proposed parking lot above petroleum-hydrocarbon-impacted soil, not beneath the store building. Using the maximum detected benzene concentration, the benzene non-carcinogenic risk (i.e., hazard index) was calculated to be 2.8, which exceeds the threshold value of 1.0. The carcinogenic risk for benzene was calculated to be 8.1 x 10-4, which exceeds the de minimis value of 1 x 10-6. To be conservative, Walgreen s elected to install a vapor barrier beneath the slab foundation for the store in May 2012. Eight exploratory trenches were excavated at the site concurrent with pre-construction grading. Soil samples were collected from the trenches at depths of 8, 10, and 12 feet bgs. Additional soil samples were collected at depths of 4, 6, and 14 feet bgs in one trench. Gasoline and diesel-impacted soil was encountered in three of the trenches located in the northeastern portion of the site at depths of 8 to 14 feet bgs. The consultant estimated the volume of impacted soil remaining in place to be 750 cubic yards. During grading activities to level the southern portion of the property, a second area of petroleum hydrocarbon-impacted soil was encountered within two feet of original grade. Based on visual observation, the impacted soil was removed and disposed to a licensed landfill. Three groundwater monitoring wells were installed in the parking areas of the site in August 2013 after

WALGREENS #12915 (Continued) **S110376299**

completion of the Walgreen s Store building. Groundwater samples were collected during two monitoring and sampling events held on September 17, 2012 and November 21, 2013. Analytical results for the samples confirmed that groundwater had been impacted by gasoline, diesel, BTEX and the fuel oxygenates tert-butyl alcohol (TBA) and di-isopropyl ether (DIPE). A Corrective Action Plan (CAP) for the site was submitted to DEH on March 14, 2014, and approved on July 17, 2014. Based on the location of the site in a hydrologic area with no beneficial uses for groundwater and mitigation of human health risk by installation of a vapor barrier beneath the Walgreen s Store, the consultant (Apex Companies, LLC) recommends no further action and case closure. DEH concurs with these recommendations.

LUST:
Global Id: T10000002225
Contact Type: Local Agency Caseworker
Contact Name: CAROL FENNER
Organization Name: SAN DIEGO COUNTY LOP
Address: P.O. Box 129261
City: San Diego
Email: carol.fenner@sdcounty.ca.gov
Phone Number: Not reported

LUST:
Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 06/15/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 05/18/2011
Action: Letter - Notice

Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 12/14/2012
Action: Technical Correspondence / Assistance / Other

Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 12/04/2013
Action: Letter - Notice

Global Id: T10000002225
Action Type: Other
Date: 07/01/2010
Action: Leak Reported

Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 10/04/2013
Action: Letter - Notice

Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 10/04/2013

WALGREENS #12915 (Continued) **S110376299**

Action: Technical Correspondence / Assistance / Other

Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 10/16/2014
Action: Closure/No Further Action Letter

Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 07/17/2014
Action: Technical Correspondence / Assistance / Other

Global Id: T10000002225
Action Type: Other
Date: 07/01/2010
Action: Leak Stopped

Global Id: T10000002225
Action Type: RESPONSE
Date: 06/03/2011
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T10000002225
Action Type: RESPONSE
Date: 10/29/2012
Action: Site Assessment Report - Regulator Responded

Global Id: T10000002225
Action Type: RESPONSE
Date: 01/06/2014
Action: CAP/RAP - Feasibility Study Report - Regulator Responded

Global Id: T10000002225
Action Type: ENFORCEMENT
Date: 07/13/2010
Action: Letter - Notice

Global Id: T10000002225
Action Type: Other
Date: 04/30/2010
Action: Leak Discovery

LUST:
Global Id: T10000002225
Status: Open - Case Begin Date
Status Date: 07/01/2010

Global Id: T10000002225
Status: Open - Site Assessment
Status Date: 07/01/2010

Global Id: T10000002225
Status: Open - Eligible for Closure
Status Date: 05/14/2014

Global Id: T10000002225
Status: Completed - Case Closed

WALGREENS #12915 (Continued) **S110376299**

Status Date: 10/16/2014

CERS HAZ WASTE:
Name: WALGREENS #12915
Address: 7195 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 84141
CERS ID: 10361527
CERS Description: Hazardous Waste Generator

CORTESE:
Name: FORMER BILL'S SELF SERVICE
Address: 7195 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Region: CORTESE
Envirostor Id: Not reported
Global ID: T10000002225
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported
Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

HAZNET:
Name: WALGREENS #12915
Address: 7195 BROADWAY
Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 91945
Contact: AMBER DURKIN
Telephone: 7606028700
Mailing Name: Not reported
Mailing Address: P.O. BOX 901

Year: 2021
Gepaid: CAR000307967
TSD EPA ID: CAD008364432
CA Waste Code: 331 - Off-specification, aged or surplus organics
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.2125

Year: 2021

WALGREENS #12915 (Continued) **S110376299**

Gepaid:	CAR000307967
TSD EPA ID:	CAD008364432
CA Waste Code:	311 - Pharmaceutical waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.111
Year:	2021
Gepaid:	CAR000307967
TSD EPA ID:	NVD980895338
CA Waste Code:	311 - Pharmaceutical waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.001
Year:	2021
Gepaid:	CAR000307967
TSD EPA ID:	CAD008364432
CA Waste Code:	352 - Other organic solids
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.3695
Year:	2021
Gepaid:	CAR000307967
TSD EPA ID:	CAD008364432
CA Waste Code:	122 - Alkaline solution without metals pH >= 12.5
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0055
Year:	2020
Gepaid:	CAR000307967
TSD EPA ID:	AZR000515924
CA Waste Code:	331 - Off-specification, aged or surplus organics
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.038
Year:	2020
Gepaid:	CAR000307967
TSD EPA ID:	CAD008364432
CA Waste Code:	311 - Pharmaceutical waste
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.0485
Year:	2020
Gepaid:	CAR000307967
TSD EPA ID:	CAD008364432
CA Waste Code:	131 - Aqueous solution (2 < pH < 12.5) containing reactive anions ...
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.006
Year:	2020
Gepaid:	CAR000307967

WALGREENS #12915 (Continued) **S110376299**

TSD EPA ID: CAD008364432
CA Waste Code: 791 - Liquids with pH <= 2
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.0015

Year: 2020
Gepaid: CAR000307967
TSD EPA ID: AZR000515924
CA Waste Code: 352 - Other organic solids
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.078

Click this hyperlink while viewing on your computer to access
2 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:
Year: 2021
Gen EPA ID: CAR000307967

Shipment Date: 9/23/2020
Creation Date: 10/5/2020
Receipt Date: 10/2/2020
Manifest ID: 014942239FLE
Trans EPA ID: MNS000110924
Trans Name: Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008364432
Trans Name: Rho Chem LLC
TSDF Alt EPA ID: Not reported
TSDF Alt Name: Not reported
Waste Code Description: 311 - Pharmaceutical waste
RCRA Code: D007,D010
Meth Code: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons: 0.0025
Waste Quantity: 5
Quantity Unit: P
Additional Code 1: Not reported
Additional Code 2: Not reported
Additional Code 3: Not reported
Additional Code 4: Not reported
Additional Code 5: Not reported

Shipment Date: 9/23/2020
Creation Date: 10/5/2020
Receipt Date: 10/2/2020
Manifest ID: 014942239FLE
Trans EPA ID: MNS000110924
Trans Name: Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID: Not reported
Trans 2 Name: Not reported
TSDF EPA ID: CAD008364432
Trans Name: Rho Chem LLC

WALGREENS #12915 (Continued) **S110376299**

TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0615
Waste Quantity:	123
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	311 - Pharmaceutical waste
RCRA Code:	P075
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0005
Waste Quantity:	1
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	311 - Pharmaceutical waste
RCRA Code:	D005,D022,D024,
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.02

WALGREENS #12915 (Continued) **S110376299**

Waste Quantity:	40
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.001
Waste Quantity:	2
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0015
Waste Quantity:	3
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

WALGREENS #12915 (Continued) **S110376299**

Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.035
Waste Quantity:	70
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	311 - Pharmaceutical waste
RCRA Code:	P001
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0005
Waste Quantity:	1
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	7/23/2020
Creation Date:	7/31/2020
Receipt Date:	7/30/2020
Manifest ID:	014942060FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported

WALGREENS #12915 (Continued) **S110376299**

Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.033
Waste Quantity:	66
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	7/23/2020
Creation Date:	7/31/2020
Receipt Date:	7/30/2020
Manifest ID:	014942060FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.075
Waste Quantity:	150
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2020
Gen EPA ID:	CAR000307967

Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC

WALGREENS #12915 (Continued) **S110376299**

TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.035
Waste Quantity:	70
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0015
Waste Quantity:	3
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	331 - Off-specification, aged, or surplus organics
RCRA Code:	D001
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.001

WALGREENS #12915 (Continued) **S110376299**

Waste Quantity:	2
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	311 - Pharmaceutical waste
RCRA Code:	D005,D022,D024,
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.02
Waste Quantity:	40
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	311 - Pharmaceutical waste
RCRA Code:	P075
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0005
Waste Quantity:	1
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

WALGREENS #12915 (Continued) **S110376299**

Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0615
Waste Quantity:	123
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	311 - Pharmaceutical waste
RCRA Code:	D007,D010
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0025
Waste Quantity:	5
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	9/23/2020
Creation Date:	10/5/2020
Receipt Date:	10/2/2020
Manifest ID:	014942239FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported

WALGREENS #12915 (Continued) **S110376299**

Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	311 - Pharmaceutical waste
RCRA Code:	P001
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0005
Waste Quantity:	1
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	7/23/2020
Creation Date:	7/31/2020
Receipt Date:	7/30/2020
Manifest ID:	014942060FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	352 - Other organic solids
RCRA Code:	Not reported
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.075
Waste Quantity:	150
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	7/23/2020
Creation Date:	7/31/2020
Receipt Date:	7/30/2020
Manifest ID:	014942060FLE
Trans EPA ID:	MNS000110924
Trans Name:	Stericycle Specialty Waste Solutions Inc
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD008364432
Trans Name:	Rho Chem LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	131 - Aqueous solution (2 < pH < 12.5) containing reactive anions (azide, bromate, chlorate, cyanide, fluoride, hypochlorite, nitrite,

WALGREENS #12915 (Continued) **S110376299**

	perchlorate, and sulfide anions
RCRA Code:	D001
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.001
Waste Quantity:	2
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Detail Two:

Year:	2020
EM Manifest ID:	15465f95-823f-467b-aac8-b252da747b3b
Shipment Date:	5/19/2020
Receipt Date:	5/26/2020
Manifest Number:	014360353FLE
Generator EPA ID:	CAR000307967
Name:	WALGREENS #12915
Address:	7195 BROADWAY
Address 2:	Not reported
City:	LEMON GROVE
Zip:	91945-1408
Telephone:	877-577-2669
Contact:	Not reported
Contact Telephone:	619-433-0172
Transporter 1 EPA ID:	MNS000110924
Transporter 1 Emergency Number:	Not reported
Transporter 2 EPA ID:	CAR000175422
Transporter 2 Emergency Number:	Not reported
TSDF EPA ID:	AZR000515924
TSDF Name:	YUMA YES WASTE TRANSFER FACILITY
TSDF Address 1:	2730 E 13TH ST
TSDF Address 2:	Not reported
TSDF City:	YUMA
TSDF Zip:	85365-1901
TSDF Telephone:	Not reported

State:

Year:	2020
EM Manifest ID:	15465f95-823f-467b-aac8-b252da747b3b
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360353FLE
Line Number:	1
Method Code:	H141
Quantity Tons:	0.03800
Quantity Waste:	76.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiberboard or plastic drums, barrels, kegs
Quantity Type:	Pounds
State Code:	331

Year:	2020

WALGREENS #12915 (Continued) **S110376299**

EM Manifest ID: 15465f95-823f-467b-aac8-b252da747b3b
Generator EPA ID: CAR000307967
Shipment Date: 2020-05-19
Manifest Number: 014360353FLE
Line Number: 2
Method Code: H141
Quantity Tons: 0.07800
Quantity Waste: 156.000000
Quantity Unit: P
Number of Containers: 2
Type of Container: Fiberboard or plastic drums, barrels, kegs
Quantity Type: Pounds
State Code: 352

Year: 2020
EM Manifest ID: 6faf20ee-142c-455b-a981-cbc9329000bf
Shipment Date: 5/19/2020
Receipt Date: 6/1/2020
Manifest Number: 014360352FLE
Generator EPA ID: CAR000307967
Name: WALGREEN
Address: 7195 BROADWAY
Address 2: Not reported
City: LEMON GROVE
Zip: 91945-1408
Telephone: 877-577-2669
Contact: Not reported
Contact Telephone: 323-776-6233
Transporter 1 EPA ID: MNS000110924
Transporter 1 Emergency Number: Not reported
Transporter 2 EPA ID: MNS000110924
Transporter 2 Emergency Number: Not reported
TSDF EPA ID: CAD008364432
TSDF Name: Rho Chem LLC
TSDF Address 1: 425 Isis Ave.
TSDF Address 2: Not reported
TSDF City: Inglewood
TSDF Zip: 90301
TSDF Telephone: Not reported

Federal:
Year: 2020
EM Manifest ID: 6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID: CAR000307967
Shipment Date: 2020-05-19
Manifest Number: 014360352FLE
Line Number: 1
Method Code: H141
Quantity Tons: 0.00400
Quantity Waste: 8.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Fiber or plastic boxes, cartons, cases
Quantity Type: Pounds
Federal Code: D001

Year: 2020

WALGREENS #12915 (Continued) **S110376299**

EM Manifest ID:	6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360352FLE
Line Number:	2
Method Code:	H141
Quantity Tons:	0.00200
Quantity Waste:	4.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
Federal Code:	D001

Year:	2020
EM Manifest ID:	6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360352FLE
Line Number:	3
Method Code:	H141
Quantity Tons:	0.00100
Quantity Waste:	2.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
Federal Code:	D001

Year:	2020
EM Manifest ID:	6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360352FLE
Line Number:	4
Method Code:	H141
Quantity Tons:	0.00450
Quantity Waste:	9.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
Federal Code:	D007

Year:	2020
EM Manifest ID:	6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360352FLE
Line Number:	4
Method Code:	H141
Quantity Tons:	0.00450
Quantity Waste:	9.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds

WALGREENS #12915 (Continued) **S110376299**

Federal Code: D010

Year: 2020
EM Manifest ID: 6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID: CAR000307967
Shipment Date: 2020-05-19
Manifest Number: 014360352FLE
Line Number: 5
Method Code: H141
Quantity Tons: 0.00050
Quantity Waste: 1.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Fiber or plastic boxes, cartons, cases
Quantity Type: Pounds
Federal Code: P075

Year: 2020
EM Manifest ID: 6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID: CAR000307967
Shipment Date: 2020-05-19
Manifest Number: 014360352FLE
Line Number: 6
Method Code: H141
Quantity Tons: 0.00050
Quantity Waste: 1.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Fiber or plastic boxes, cartons, cases
Quantity Type: Pounds
Federal Code: P001

State:
Year: 2020
EM Manifest ID: 6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID: CAR000307967
Shipment Date: 2020-05-19
Manifest Number: 014360352FLE
Line Number: 1
Method Code: H141
Quantity Tons: 0.00400
Quantity Waste: 8.000000
Quantity Unit: P
Number of Containers: 1
Type of Container: Fiber or plastic boxes, cartons, cases
Quantity Type: Pounds
State Code: 331

Year: 2020
EM Manifest ID: 6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID: CAR000307967
Shipment Date: 2020-05-19
Manifest Number: 014360352FLE
Line Number: 2
Method Code: H141
Quantity Tons: 0.00200
Quantity Waste: 4.000000

WALGREENS #12915 (Continued) **S110376299**

Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
State Code:	331
Year:	2020
EM Manifest ID:	6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360352FLE
Line Number:	3
Method Code:	H141
Quantity Tons:	0.00100
Quantity Waste:	2.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
State Code:	131
Year:	2020
EM Manifest ID:	6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360352FLE
Line Number:	4
Method Code:	H141
Quantity Tons:	0.00450
Quantity Waste:	9.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
State Code:	311
Year:	2020
EM Manifest ID:	6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360352FLE
Line Number:	5
Method Code:	H141
Quantity Tons:	0.00050
Quantity Waste:	1.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
State Code:	311
Year:	2020
EM Manifest ID:	6faf20ee-142c-455b-a981-cbc9329000bf
Generator EPA ID:	CAR000307967
Shipment Date:	2020-05-19
Manifest Number:	014360352FLE
Line Number:	6

WALGREENS #12915 (Continued) **S110376299**

Method Code:	H141
Quantity Tons:	0.00050
Quantity Waste:	1.000000
Quantity Unit:	P
Number of Containers:	1
Type of Container:	Fiber or plastic boxes, cartons, cases
Quantity Type:	Pounds
State Code:	311

SAN DIEGO CO LOP:

Name:	FORMER BILL'S SELF SERVICE
Address:	7195 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH2010-LSAM-106900-001
Record Status:	Completed
Opened Date:	06/24/2010
Parcel Number:	479-070-12-00
Case Type:	LOP - Local Oversight Program
Historical Name:	FORMER BILL'S SELF SERVICE
SWRCB Global ID:	T10000002225
Funding:	S - LOP State Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	06/29/2010
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	UNKNOWN
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7421474
Longitude:	-117.0432155
X MapCoord:	6317758.943
Y MapCoord:	1850735.820

CERS:

Name:	WALGREENS #12915
Address:	7195 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	84141
CERS ID:	10361527
CERS Description:	Chemical Storage Facilities

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	11-18-2020
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Moreau Marie Inspection ID:6412784
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS,

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	07-16-2013
Violations Found:	No
Eval Type:	Routine done by local agency

WALGREENS #12915 (Continued) **S110376299**

Eval Notes: Inspector: Schiess Romina Inspection ID:4094229
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 11-18-2020
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Moreau Marie Inspection ID:6412784
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 11-18-2020
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Moreau Marie Inspection ID:6412784
Eval Division: San Diego County Department of Env Health
Eval Program: HWLQG
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 04-02-2018
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow VikkiT. Inspection ID:5918494
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 06-01-2016
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Inspector: Denslow Vikki Inspection ID:5395784
Eval Division: San Diego County Department of Env Health
Eval Program: HW
Eval Source: CERS,

Coordinates:
Site ID: 84141
Facility Name: WALGREENS #12915
Env Int Type Code: HWG
Program ID: 10361527
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 32.742140
Longitude: -117.043210

Affiliation:
Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: Walgreen Co. P.O. Box 901

WALGREENS #12915 (Continued) **S110376299**

Affiliation City:	Deerfield
Affiliation State:	IL
Affiliation Country:	Not reported
Affiliation Zip:	60015
Affiliation Phone:	,
Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,
Affiliation Type Desc:	Environmental Contact
Entity Name:	3E, Regulatory Department/Walgreen Co.
Entity Title:	Not reported
Affiliation Address:	3207 Grey Hawk Court, Suite 200
Affiliation City:	Carlsbad
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92010
Affiliation Phone:	,
Affiliation Type Desc:	Operator
Entity Name:	Walgreen Co.
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(847) 226-3207,
Affiliation Type Desc:	Parent Corporation
Entity Name:	Walgreens
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,
Affiliation Type Desc:	Legal Owner
Entity Name:	Walgreen Co.
Entity Title:	Not reported
Affiliation Address:	200 Wilmot Road
Affiliation City:	Deerfield
Affiliation State:	IL
Affiliation Country:	United States
Affiliation Zip:	60015
Affiliation Phone:	(847) 226-3207,
Affiliation Type Desc:	Property Owner

WALGREENS #12915 (Continued) **S110376299**

Entity Name: WG Lemon Grove CA Landlord LLC
Entity Title: Not reported
Affiliation Address: 20 Community Place, 3rd Floor
Affiliation City: Morristown
Affiliation State: NJ
Affiliation Country: United States
Affiliation Zip: 07960
Affiliation Phone: (973) 539-1415,

Affiliation Type Desc: Document Preparer
Entity Name: Erin Deiotte, on behalf of Walgreen Co.
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: Erin Deiotte, on behalf of Walgreen Co.
Entity Title: Regulatory Compliance Specialist, 3E
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

R104 **ROCK LIQUOR, 7161 BROADWAY ST., LEMON GR** **SAN DIEGO CO. SAM** **S110169017**
SW **7161 BROADWAY** **CPS-SLIC** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **CERS**
0.401 mi.
2115 ft. **Site 2 of 2 in cluster R**

Relative:
Lower

Actual:
410 ft.

SAN DIEGO CO. SAM:
Name: ROCK LIQUOR, 7161 BROADWAY ST., LEMON GR
Address: 7161 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Case Number: H39746-001
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: Soils Only
Facility Status: Leak Being Confirmed
Date: 12/8/2009
Date Began: Not reported

CPS-SLIC:
Name: ROCK LIQUOR
Address: 7161 BROADWAY AV
City,State,Zip: LEMON GROVE, CA 91945
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 07/25/2013
Global Id: T10000001807
Lead Agency: SAN DIEGO COUNTY LOP

ROCK LIQUOR, 7161 BROADWAY ST., LEMON GR (Continued) **S110169017**

Lead Agency Case Number:	H39746-001
Latitude:	32.7419918215194
Longitude:	-117.043644315344
Case Type:	Cleanup Program Site
Case Worker:	VAP
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Not reported
Potential Media Affected:	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern:	Diesel, Gasoline
Site History:	Not reported

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	ROCK LIQUOR
Address:	7161 BROADWAY AV
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	229348
CERS ID:	T10000001807
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	Voluntary Assistance Program (VAP) - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

S105 **MAIN STREET PROMENADE** **CPS-SLIC** **S121475982**
ESE **3466-3530 MAIN ST** **CERS** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945**
0.429 mi.
2267 ft. **Site 1 of 2 in cluster S**

Relative:
Lower

Actual:
452 ft.

CPS-SLIC:

Name:	MAIN STREET PROMENADE
Address:	3466-3530 MAIN ST
City,State,Zip:	LEMON GROVE, CA 91945
Region:	STATE
Facility Status:	**Completed - Case Closed**
Status Date:	01/18/2018
Global Id:	T10000004282
Lead Agency:	SAN DIEGO COUNTY LOP
Lead Agency Case Number:	H39803-001
Latitude:	32.7434826557711
Longitude:	-117.031452655792
Case Type:	Cleanup Program Site
Case Worker:	EP
Local Agency:	SAN DIEGO COUNTY LOP
RB Case Number:	Not reported
File Location:	Local Agency
Potential Media Affected:	Other Groundwater (uses other than drinking water), Soil

MAIN STREET PROMENADE (Continued) **S121475982**

Potential Contaminants of Concern: Dichloroethene (DCE), Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Chlordane, DDD / DDE / DDT, Arsenic, Copper, Lead, Zinc, Benzene, Ethylbenzene, Total Petroleum Hydrocarbons (TPH), Xylene

Site History: The site property originally consisted of six parcels of land identified by Assessor Parcel Numbers (APNs) 480-043-07, -08, -09, -10, -11, and -12 occupying addresses 3466 to 3530 Main Street in Lemon Grove, CA. The parcels associated with APNs 480-043-08, -09, -10, -11, and -12 were merged and became 480-043-27 and -31. This property was originally owned by the City of Lemon Grove. Eventually, these parcels along with the parcels associated with the CityMark L. G., LLC (CityMark) redevelopment project merged and became one parcel, APN 480-043-42. This project was managed under VAP case DEH2015-LSAM-000287, CityMark Lemon Grove. This VAP case was originally opened for the investigation and mitigation related to the installation of new utilities and road improvements associated with the land owned by the City of Lemon Grove. The investigation identified chlorinated hydrocarbon impacts to soil and groundwater which were associated with a former dry cleaners located on the City owned property. The City retained the responsibility for the chlorinated hydrocarbon impacts when the land was transferred to CityMark. CityMark has redeveloped the site to an 84-unit, four-level residential apartment complex with the ground floor used as a parking level and the three floors over the ground floor parking used for residential apartment units. The structure comprises a total of approximately 126,624 square feet (ft), with approximately 32,089 ft of parking at grade and 94,535 ft for the occupied residential floors. The property occupies 1.14 acres of land and is zoned commercial. The Phase I Environmental Site Assessment (ESA) report, dated August 11, 2011 and completed by SCS Engineers (SCS), summarizes results of the site investigation to assess the presence or likely presence of any recognizable environmental concerns on the subject property. Based on the ESA report, SCS recommended a soil vapor survey/human health risk assessment; further investigation of potential metal-bearing, petroleum hydrocarbon-impacted, and organochlorine pesticide (OCP) impacted soil; and an assessment of the potential of volatile organic compound (VOC) impacted groundwater at the site. On November 1, 2011 and January 30, 2012, SCS directed the excavation of 13 shallow backhoe slices (A1 through A13) to approximate depths of 5 to 8 feet below ground surface (bgs). Forty soil samples were collected and analyzed for total petroleum hydrocarbons (TPH), VOCs, and Title 22 metals. Fourteen soil vapor samples (SV1 through SV14) were collected on October 31, 2011 to assess potential soil vapor health risk at the site. Based on the cumulative estimated cancer risk for benzene, ethylbenzene, PCE, and TCE of 1.462 E-07, there is a low likelihood that a significant human health risk exists onsite due to soil vapor intrusion. The value of 1.46 E-07 is below the threshold of 1.00 E-06 for excess cancer risk. On November 1 and 21, 2011, 17 soil borings (SB1 through SB17) were drilled and/or hand augered. Fifty-six samples were collected and analyzed for TPH, VOCs, metals, and OCP. To assess the vertical extent of lead and arsenic in the soil associated with historic land uses, on January 31, 2012 SCS directed the excavation of 3 additional backhoe slices (NP1 through NP3) to depths of approximately 3 feet bgs. Twelve soil samples were obtained and analyzed. From August 6 through 8, 2012, SCS directed the excavation of trenches to remove metal-bearing soil from the areas of proposed utilities. Eighteen

MAIN STREET PROMENADE (Continued) **S121475982**

confirmation soil samples (C1-C13, P1-P4, SS1-SS3) were obtained from trench bottoms, sidewalls, and from soil stockpiles to depths of approximately 4 feet bgs, and analyzed for lead and arsenic. On July, 21, 2014, SCS advanced seven soil borings (B1 through B7) to depths ranging from 0.5 to 5 feet bgs to assess the extent of the constituents of concern (CoCs) in the shallow soil at the site. Twenty-six soil samples were obtained and analyzed for total petroleum hydrocarbons and select metals. The results of this investigation were reported in the Limited Phase II Soil Sampling report dated September 9, 2014. The Soil Management Plan and Property Closure Report indicated below are referenced in VAP case DEH2015-LSAM-000287 CityMark. A Soil Management Plan dated July 8, 2015, and completed by SCS, proposed the following: Per geotechnical requirements, the upper 2 feet of soil are required to be removed and recompacted for the purpose of the construction of the proposed project. Approximately 2,177 cubic yards (yd) of cut and 820 yd of fill are proposed, with approximately 1,357 yd of soil export proposed. Petroleum hydrocarbon and metal-impacted soil will be mitigated based on risk-driven remediation required by future land uses, to protect workers, and to control the proposed soil export and offsite reuse of soil deemed to be a waste. An onsite Soil Management Zone (SMZ) is proposed for the consolidation of petroleum hydrocarbon-bearing soil at the discretion of the responsible party. The location of the SMZ has been designated in a proposed parking area that is not proposed to have occupied areas built above ground surface. A Property Closure Report dated February 24, 2017, and completed by SCS, reported the following: Approximately 250 yd of petroleum hydrocarbon-bearing soil were placed and compacted as fill material in the SMZ. The SMZ is located within the courtyard area of the new project, where no subsurface utilities exist. It measures approximately 41 feet by 41 feet with the petroleum hydrocarbon-bearing soil buried approximately 4 feet below subgrade to 8 feet below subgrade with an approximately 4-foot clean soil layer above and approximately 4- to 6-inch thick concrete cap. Approximately 1,500 yd of arsenic-bearing soil were exported offsite for use as fill soil on expansion of an adjacent State Highway 94 off-ramp to Lemon Grove Avenue. The Lemon Grove Avenue Realignment Project is located at 7750 North Avenue and is under regulatory oversight of the San Diego RWQCB as case number 2090026, Global ID T10000000415. Approximately 200 yd of petroleum hydrocarbon-bearing soil were exported and disposed at the Otay Landfill on July 25, 2016. Approximately 170 yd of elevated arsenic-bearing soil were exported and disposed at the Otay Landfill between February 6, 2017 and February 23, 2017. Three-foot wide clean soil buffers were used within onsite unpaved utility trenches. The only exception was an approximately 15- to 20-foot long sewer lateral in the southwest portion of the site which only had a 2-foot wide clean soil buffer. On May 23 and June 14, 2016, six confirmation soil samples (C-1 through C-6) were collected from the subgrade elevation from the three APNs requested by DEH. Laboratory results report that only concentrations of arsenic exceeded the residential RSLs. Depth to groundwater onsite ranges between 8 feet to 26 feet bgs with depth to groundwater reported to be 14.41 feet bgs in the immediate vicinity of the SMZ. SCS concludes the dissolved chlorinated hydrocarbon plume is stable and is adequately assessed. In addition, the plume does not constitute a threat to the non-beneficial groundwater use at the site and vicinity. SCS concludes that the site s current configuration and

MAIN STREET PROMENADE (Continued) **S121475982**

condition are protective of human health and the environment. The consultant recommends no further action and for DEH to administer case closure. DEH concurs with the aforementioned and closure of the case.

Click here to access the California GeoTracker records for this facility:

CERS:

Name:	MAIN STREET PROMENADE
Address:	3466-3530 MAIN ST
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	238997
CERS ID:	T10000004282
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	ED PAREDES - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	SAN DIEGO
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	8585056806,

S106 **LEMON GROVE PROPERTY** **LUST** **S102444685**
SE **7770 BROADWAY** **SAN DIEGO CO. SAM** **N/A**
1/4-1/2 **LEMON GROVE, CA 91945** **San Diego Co. HMMD**
0.437 mi. **Cortese**
2306 ft. **Site 2 of 2 in cluster S** **HIST CORTESE**
SAN DIEGO CO LOP
Relative: **CERS**
Lower

Actual: **449 ft.**

LUST:

Name:	LEMON GROVE PROPERTY
Address:	7770 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Lead Agency:	SAN DIEGO COUNTY LOP
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301909
Global Id:	T0607301909
Latitude:	32.743093
Longitude:	-117.031316
Status:	Completed - Case Closed
Status Date:	05/17/1996
Case Worker:	Not reported
RB Case Number:	9UT3140
Local Agency:	Not reported
File Location:	Local Agency
Local Case Number:	H35627-001
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Gasoline
Site History:	Not reported

LUST:

Global Id:	T0607301909

LEMON GROVE PROPERTY (Continued) **S102444685**

Action Type: ENFORCEMENT
Date: 05/17/1996
Action: Closure/No Further Action Letter

Global Id: T0607301909
Action Type: Other
Date: 12/31/1957
Action: Leak Began

Global Id: T0607301909
Action Type: Other
Date: 12/31/1957
Action: Leak Discovery

Global Id: T0607301909
Action Type: Other
Date: 01/26/1996
Action: Leak Reported

Global Id: T0607301909
Action Type: Other
Date: 12/31/1957
Action: Leak Stopped

LUST:
Global Id: T0607301909
Status: Open - Case Begin Date
Status Date: 01/26/1996

Global Id: T0607301909
Status: Completed - Case Closed
Status Date: 05/17/1996

LUST REG 9:
Region: 9
Status: Case Closed
Case Number: 9UT3140
Local Case: H35627-001
Substance: Gasoline
Qty Leaked: 0
Abate Method: No Action Required - incident is minor, requiring no remedial action
Local Agency: San Diego
How Found: Not reported
How Stopped: Not reported
Source: Unknown
Cause: Not reported
Lead Agency: Local Agency
Case Type: Other ground water affected
Date Found: 01/22/1996
Date Stopped: 12/31/1957
Confirm Date: / /
Submit Workplan: Not reported
Prelim Assess: 01/26/1996
Desc Pollution: Not reported
Remed Plan: / /

LEMON GROVE PROPERTY (Continued) **S102444685**

Remed Action: 2/14/96
Began Monitor: Not reported
Release Date: 01/26/1996
Enforce Date: Not reported
Closed Date: 5/17/96
Enforce Type: Not reported
Pilot Program: LOP
Basin Number: 908.22
GW Depth: 11.5
Beneficial Use: No Beneficial groundwater use
NPDES Number: Not reported
Priority: Low priority. Priority ranking can change over time.
File Dispn: Administratively opened on database, however no file physically exists
Interim Remedial Actions: Not reported
Cleanup and Abatement order Number: Not reported
Waste Discharge Requirement Number: Not reported

SAN DIEGO CO. SAM:
Name: LEMON GROVE PROPERTY
Address: 7770 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Case Number: H35627-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: Drinking Water Aquifer Impacted
Facility Status: Closed Case
Date: 5/17/1996
Date Began: 12/31/1957

HMMD SAN DIEGO:
Name: LEMON GROVE PROPERTY
Address: 7770 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 135627
Business Type: Not reported
EPA Id Number: Not reported
APN: 480-043-13-00
Last HMMD Inspection: Not reported
Facility Telephone: Not reported
Permit Status: INAC
Permit Expiration: 04/27/2002
Date Last Updated: 11/02/2012
Facility Owner: HOME SAVINGS OF AMERICA
Facility Mailing Address: 4900 RIVERGRADE RD
Facility Mailing City: IRWINDALE
Facility Mailing State: CA
Facility Mailing Zip: 91706-
UST Owner: Not reported
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Not reported
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

LEMON GROVE PROPERTY (Continued) **S102444685**

CORTESE:

Name:	LEMON GROVE PROPERTY
Address:	7770 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607301909
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	LEMON GROVE PROPERTY
edr_fadd1:	7770 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT3140

SAN DIEGO CO LOP:

Name:	LEMON GROVE PROPERTY
Address:	7770 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH1996-LSAM-H35627-001
Record Status:	Completed
Opened Date:	01/26/1996
Parcel Number:	480-043-13-00
Case Type:	LOP - Local Oversight Program
Historical Name:	LEMON GROVE PROPERTY
SWRCB Global ID:	T0607301909
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	02/12/1996
Census Tract:	144.00
Community:	Lemon Grove
Jurisdiction:	LEMON GROVE
Watershed Basin Number:	908.22
Water Purveyor:	HELIX WATER DISTRICT LAND
Fire Agency:	HELIX WATER DISTRICT LAND
Latitude:	32.7430972

LEMON GROVE PROPERTY (Continued) **S102444685**

Longitude: -117.0313303
X MapCoord: 6321416.078
Y MapCoord: 1851053.796

CERS:
Name: LEMON GROVE PROPERTY
Address: 7770 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 226610
CERS ID: T0607301909
CERS Description: Leaking Underground Storage Tank Cleanup Site

---

107 East 1/4-1/2 0.453 mi. 2391 ft.
HONDA OF LEMON GROVE
3611 LEMON GROVE AV
LEMLEMON GROVE, CA 91945
SAN DIEGO CO. SAM **S108430871**
CPS-SLIC **N/A**
CERS

Relative: Higher
Actual: 483 ft.

SAN DIEGO CO. SAM:
Name: HONDA OF LEMON GROVE
Address: 3611 LEMON GROVE AV
City,State,Zip: LEMLEMON GROVE, CA 91945
Case Number: H01540-001
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: Soils Only
Facility Status: Preliminary Assessment
Date: 2/1/2007
Date Began: 2/1/2007

CPS-SLIC:
Name: HONDA OF LEMON GROVE
Address: 3611 LEMON GROVE AV
City,State,Zip: LEMON GROVE, CA 91945
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 09/16/2010
Global Id: SLT19775610
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H01540-001
Latitude: 32.7319941
Longitude: -117.0337401
Case Type: Cleanup Program Site
Case Worker: CB
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Not reported
Potential Contaminants of Concern: Not reported
Site History: Voluntary Assitance Case H01540-001 was open following a request to mitigate lead impacted soil.

Click here to access the California GeoTracker records for this facility:

CERS:
Name: HONDA OF LEMON GROVE

HONDA OF LEMON GROVE (Continued) **S108430871**

Address: 3611 LEMON GROVE AV
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 191957
CERS ID: SLT19775610
CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: CRAIG BURNETT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 8585056978,

108
WSW
1/4-1/2
0.485 mi.
2562 ft.

WELLS FARGO BANK
7060 BROADWAY
LEMON GROVE, CA 91945

SAN DIEGO CO. SAM
CPS-SLIC
San Diego Co. HMMD
CERS

S104754955
N/A

Relative:
Lower

Actual:
408 ft.

SAN DIEGO CO. SAM:
Name: WELLS FARGO BANK
Address: 7060 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Case Number: H35324-001
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 12/6/1996
Date Began: 12/22/1994

CPS-SLIC:
Name: WELLS FARGO BANK
Address: 7060 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Region: STATE
Facility Status: **Completed - Case Closed**
Status Date: 12/06/1996
Global Id: T0608104733
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H35324-001
Latitude: 32.7428219
Longitude: -117.046059
Case Type: Cleanup Program Site
Case Worker: Not reported
Local Agency: Not reported
RB Case Number: Not reported
File Location: Local Agency
Potential Media Affected: Not reported
Potential Contaminants of Concern: Not reported
Site History: Not reported

WELLS FARGO BANK (Continued) **S104754955**

Click here to access the California GeoTracker records for this facility:

HMMD SAN DIEGO:

Name:	WELLS FARGO BANK
Address:	7060 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	135324
Business Type:	Not reported
EPA Id Number:	Not reported
APN:	479-021-03-00
Last HMMD Inspection:	Not reported
Facility Telephone:	Not reported
Permit Status:	INAC
Permit Expiration:	Not reported
Date Last Updated:	11/02/2012
Facility Owner:	WELLS FARGO BANK
Facility Mailing Address:	333 S GRAND AV
Facility Mailing City:	LOS ANGELES
Facility Mailing State:	CA
Facility Mailing Zip:	90071-
UST Owner:	Not reported
Handle Regulated Hazmat:	Not reported
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Not reported
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

CERS:

Name:	WELLS FARGO BANK
Address:	7060 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	198568
CERS ID:	T0608104733
CERS Description:	Cleanup Program Site

109
ESE
1/2-1
0.541 mi.
2856 ft.

Relative:
Lower

Actual:
455 ft.

PALOMAR CLEANERS
7870 BROADWAY
LEMON GROVE, CA 91945

RCRA-SQG **1001022994**
ENVIROSTOR **CAR000003384**
SAN DIEGO CO. SAM
CPS-SLIC
San Diego Co. HMMD
FINDS
ECHO
DRYCLEANERS
EMI
HAZNET
CERS
HWTS

RCRA Listings:

Date Form Received by Agency:		19950607
Handler Name:	PALOMAR CLEANERS	
Handler Address:		7870 BROADWAY
Handler City,State,Zip:		LEMON GROVE, CA 91945
EPA ID:		CAR000003384
Contact Name:		LARRY PEREZ

PALOMAR CLEANERS (Continued) **1001022994**

Contact Address:		7870 BROADWAY
Contact City,State,Zip:		LEMON GROVE, CA 91945
Contact Telephone:		619-466-4145
Contact Fax:		Not reported
Contact Email:		Not reported
Contact Title:		Not reported
EPA Region:		09
Land Type:		Private
Federal Waste Generator Description:		Small Quantity Generator
Non-Notifier:		Not reported
Biennial Report Cycle:		Not reported
Accessibility:		Not reported
Active Site Indicator:		Handler Activities
State District Owner:		Not reported
State District:		Not reported
Mailing Address:		BROADWAY
Mailing City,State,Zip:		LEMON GROVE, CA 91945
Owner Name:	PALOMAR LAUNDRY AND LINEN INC	
Owner Type:		Private
Operator Name:	Not reported	
Operator Type:		Not reported
Short-Term Generator Activity:		No
Importer Activity:		No
Mixed Waste Generator:		No
Transporter Activity:		No
Transfer Facility Activity:		No
Recycler Activity with Storage:		No
Small Quantity On-Site Burner Exemption:		No
Smelting Melting and Refining Furnace Exemption:		No
Underground Injection Control:		No
Off-Site Waste Receipt:		No
Universal Waste Indicator:		No
Universal Waste Destination Facility:		No
Federal Universal Waste:		No
Active Site Fed-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site Converter Treatment storage and Disposal Facility:		Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:		Not reported
Active Site State-Reg Handler:		---
Federal Facility Indicator:		Not reported
Hazardous Secondary Material Indicator:		NN
Sub-Part K Indicator:		Not reported
Commercial TSD Indicator:		No
Treatment Storage and Disposal Type:		Not reported
2018 GPRA Permit Baseline:		Not on the Baseline
2018 GPRA Renewals Baseline:		Not on the Baseline
Permit Renewals Workload Universe:		Not reported
Permit Workload Universe:		Not reported
Permit Progress Universe:		Not reported
Post-Closure Workload Universe:		Not reported
Closure Workload Universe:		Not reported
202 GPRA Corrective Action Baseline:		No
Corrective Action Workload Universe:		No
Subject to Corrective Action Universe:		No
Non-TSDFs Where RCRA CA has Been Imposed Universe:		No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:		No
TSDFs Only Subject to CA under Discretionary Auth Universe:		No
Corrective Action Priority Ranking:		No NCAPS ranking

PALOMAR CLEANERS (Continued) **1001022994**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required: Not reported	
Handler Date of Last Change:	20000915
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: PALOMAR LAUNDRY AND LINEN INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2221 LAS PALMAS DR STE F
Owner/Operator City,State,Zip:	CARLSBAD, CA 92009-1528
Owner/Operator Telephone:	619-438-0224
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950607
Handler Name: PALOMAR CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

PALOMAR CLEANERS (Continued) **1001022994**

Evaluation Action Summary:
Evaluations: No Evaluations Found

ENVIROSTOR:
Name: PALOMAR CLEANERS
Address: 7870 BROADWAY
City,State,Zip: LEMON GROVE, CA 92025
Facility ID: 37720040
Status: Refer: 1248 Local Agency
Status Date: 07/27/2000
Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: 0
NPL: NO
Regulatory Agencies: SAN DIEGO COUNTY
Lead Agency: SAN DIEGO COUNTY
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Cypress
Assembly: 79
Senate: 38
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not Applicable
Latitude: 32.74309
Longitude: -117.0292
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: T0608121884
Alias Type: GeoTracker Global ID
Alias Name: 37720040
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: SB 1248 Notification
Completed Date: 07/27/2000
Comments: SB 1248 SAN DIEGO COUNTY

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

PALOMAR CLEANERS (Continued) **1001022994**

SAN DIEGO CO. SAM:

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451801
Case Number:	H10987-001
Agency:	DEH Site Assessment & Mitigation
Funding:	**Private - VAP**
Facility Type:	Drinking Water Aquifer Impacted
Facility Status:	Preliminary Assessment
Date:	7/24/2000
Date Began:	7/21/2000

CPS-SLIC:

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945-1801
Region:	STATE
Facility Status:	**Open - Site Assessment**
Status Date:	11/29/2021
Global Id:	T0608121884
Lead Agency:	SAN DIEGO RWQCB (REGION 9)
Lead Agency Case Number:	H10987-001
Latitude:	32.7430789303866
Longitude:	-117.029267209822
Case Type:	Cleanup Program Site
Case Worker:	SS
Local Agency:	Not reported
RB Case Number:	31002
File Location:	All Files are on GeoTracker or in the Local Agency Database
Potential Media Affected:	Indoor Air, Other Groundwater (uses other than drinking water), Soil Vapor
Potential Contaminants of Concern:	Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE)
Site History:	The property was an active dry cleaner business from the 1940s until 2016. Environmental assessments were performed at the site on behalf of the property owner between 2000 and 2002 and also in 1995. The site has been impacted by one or more releases of tetrachloroethene (PCE), which has affected soil and groundwater and has migrated off site in a downgradient direction. The impacted groundwater may pose a human health risk to building occupants on and off site through the vapor intrusion pathway. Additional work is required to further characterize the extent of PCE contamination at the site and assess the potential risk to human health. Assessment work started in 2017 using SB 445 funding in the form of a grant. A Cleanup and Abatement Order No. R9-2019-0036 was issued on May 9, 2019. Additional Assessment work is planned for 2021.

Click here to access the California GeoTracker records for this facility:

HMMD SAN DIEGO:

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Permit Number:	110987
Business Type:	6HK53
EPA Id Number:	CAR000003384

PALOMAR CLEANERS (Continued) **1001022994**

APN:	480-111-23-00
Last HMMD Inspection:	07/25/2011
Facility Telephone:	619-466-4145
Permit Status:	OPEN
Permit Expiration:	09/30/2013
Date Last Updated:	11/02/2012
Facility Owner:	SUE VINCK
Facility Mailing Address:	7870 BROADWAY
Facility Mailing City:	LEMON GROVE
Facility Mailing State:	CA
Facility Mailing Zip:	91945-1801
UST Owner:	Not reported
Handle Regulated Hazmat:	Y
Own Or Operate UST:	Not reported
Subject To APSA:	Not reported
Generate Haz Waste:	Y
Treat Haz Waste:	Not reported
Generate Medical Waste:	Not reported

Inventory Active Permits (not SQG Medical):

Permit Number:	110987
Update Date:	11/02/2012
Case Number:	127-18-4
Name:	PERCHLOROETHYLENE
Other Information:	Not reported
Material Waste:	Material
Hazardous Categories 1:	ACUTE
Hazardous Categories 2:	CHRONIC

Permit Number:	110987
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 251 STILL BOTTOMS W/HALOG ORGANICS
Other Information:	Not reported
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Permit Number:	110987
Update Date:	11/02/2012
Case Number:	Not reported
Name:	WASTE 351 ORGANIC SOLIDS WITH HALOGENS
Other Information:	FILTERS AND LINT
Material Waste:	Waste
Hazardous Categories 1:	Not reported
Hazardous Categories 2:	Not reported

Violations Active Permits:

Permit Number:	110987
Update Date:	11/02/2012
Inspection Date:	01/29/2003
Violation Code:	6HV0401
Violation:	TRAINING RECORDS UNAVAILABLE
Violation Citation:	Personnel training records are not maintained to document compliance with requirements for current and former employees. CCR 66265.16(d)&(e)
Activity:	ACTIVE

PALOMAR CLEANERS (Continued) **1001022994**

FINDS:
Registry ID: 110002906473

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
California Hazardous Waste Tracking System - Datamart (HWTS-DATAMART) provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
HAZARDOUS AIR POLLUTANT MAJOR
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
STATE MASTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001022994
Registry ID:	110002906473
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110002906473
Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945

DRYCLEANERS:

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919451801
EPA Id:	CAR000003384
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial
Create Date:	12/08/1995
Facility Active:	No
Inactive Date:	06/30/2015
Facility Addr2:	Not reported
Owner Name:	SUE VINCK
Owner Address:	2256 DURASNO LN
Owner Address 2:	Not reported
Owner Telephone:	6199874132
Contact Name:	SUE VINCK
Contact Address:	2256 DURASNO LN
Contact Address 2:	Not reported
Contact Telephone:	6199874132
Contact Fax:	6194664146
Mailing Name:	Not reported
Mailing Address 1:	7870 BROADWAY
Mailing Address 2:	Not reported
Mailing City:	LEMON GROVE
Mailing State:	CA

PALOMAR CLEANERS (Continued) **1001022994**

Mailing Zip:	919451801
Owner Fax:	6194664146
Region Code:	4
Latitude:	32.74281
Longitude:	-117.02939

EMI:

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919450000
Year:	1999
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919450000
Year:	2000
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919450000
Year:	2001
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD

PALOMAR CLEANERS (Continued) **1001022994**

Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919450000
Year:	2002
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919450000
Year:	2003
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919450000
Year:	2004
County Code:	37
Air Basin:	SD
Facility ID:	577

PALOMAR CLEANERS (Continued) **1001022994**

Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.51975
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919450000
Year:	2005
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 919450000
Year:	2006
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 94538
Year:	2007

PALOMAR CLEANERS (Continued) **1001022994**

County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.23
Reactive Organic Gases Tons/Yr:	.160678
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2008
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2009
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.23000000000000001
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS

PALOMAR CLEANERS (Continued) **1001022994**

Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2010
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.23000000000000001
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2011
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2012
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

PALOMAR CLEANERS (Continued) **1001022994**

Part. Matter 10 Micrometers and Smllr Tons/Yr:0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2013
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2014
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2015
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0

PALOMAR CLEANERS (Continued) **1001022994**

NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: PALOMAR CLEANERS
Address: 7870 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Year: 2016
County Code: 37
Air Basin: SD
Facility ID: 577
Air District Name: SD
SIC Code: 7216
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0.23
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: Not reported
NOX - Oxides of Nitrogen Tons/Yr: Not reported
SOX - Oxides of Sulphur Tons/Yr: Not reported
Particulate Matter Tons/Yr: Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr: Not reported

Name: PALOMAR CLEANERS
Address: 7870 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Year: 2017
County Code: 37
Air Basin: SD
Facility ID: 577
Air District Name: SD
SIC Code: 7216
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0.23
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: Not reported
NOX - Oxides of Nitrogen Tons/Yr: Not reported
SOX - Oxides of Sulphur Tons/Yr: Not reported
Particulate Matter Tons/Yr: Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr: Not reported

Name: PALOMAR CLEANERS
Address: 7870 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Year: 2018
County Code: 37
Air Basin: SD
Facility ID: 577
Air District Name: SD
SIC Code: 7216
Air District Name: SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

PALOMAR CLEANERS (Continued) **1001022994**

Total Organic Hydrocarbon Gases Tons/Yr:	0.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945
Year:	2019
County Code:	37
Air Basin:	SD
Facility ID:	577
Air District Name:	SD
SIC Code:	7216
Air District Name:	SAN DIEGO COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.23
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

HAZNET:

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
Address 2:	Not reported
City,State,Zip:	LEMON GROVE, CA 919451801
Contact:	SUE VINCK
Telephone:	6199874132
Mailing Name:	Not reported
Mailing Address:	7870 BROADWAY
Year:	2015
Gepaid:	CAR000003384
TSD EPA ID:	NED981723513
CA Waste Code:	741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons:	0.585
Year:	2015
Gepaid:	CAR000003384
TSD EPA ID:	NED981723513
CA Waste Code:	741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Tons:	0.75
Year:	2014
Gepaid:	CAR000003384
TSD EPA ID:	CAD044429835
CA Waste Code:	741 - Liquids with halogenated organic compounds >= 1,000 Mg./L

PALOMAR CLEANERS (Continued) **1001022994**

Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.3

Year: 2013
Gepaid: CAR000003384
TSD EPA ID: CAT000613893
CA Waste Code: 741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.535

Year: 2011
Gepaid: CAR000003384
TSD EPA ID: CAT000613893
CA Waste Code: 741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.6

Year: 2010
Gepaid: CAR000003384
TSD EPA ID: CAT000613893
CA Waste Code: 741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.625

Year: 2007
Gepaid: CAR000003384
TSD EPA ID: CAT000613893
CA Waste Code: 741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.2275

Year: 2006
Gepaid: CAR000003384
TSD EPA ID: CAT000613893
CA Waste Code: 741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Tons: 0.3625

Year: 2004
Gepaid: CAR000003384
TSD EPA ID: CAT000613893
CA Waste Code: 741 - Liquids with halogenated organic compounds >= 1,000 Mg./L
Disposal Method: H01 - Transfer Station
Tons: 0.745

Year: 2003
Gepaid: CAR000003384
TSD EPA ID: NVR000076158
CA Waste Code: 134 - Aqueous solution with total organic residues less than 10 percent
Disposal Method: R01 - Recycler

PALOMAR CLEANERS (Continued) **1001022994**

Tons: Not reported

Click this hyperlink while viewing on your computer to access
16 additional CA HAZNET: record(s) in the EDR Site Report.

Additional Info:

Year:	2015
Gen EPA ID:	CAR000003384
Shipment Date:	20151123
Creation Date:	5/12/2016 10:00:16
Receipt Date:	20151202
Manifest ID:	005071292SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERV INC
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.24
Waste Quantity:	480
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20151123
Creation Date:	5/12/2016 10:00:16
Receipt Date:	20151202
Manifest ID:	005071292SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERV INC
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.135
Waste Quantity:	270
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

PALOMAR CLEANERS (Continued) **1001022994**

Shipment Date:	20150916
Creation Date:	4/7/2016 22:15:27
Receipt Date:	20151009
Manifest ID:	005017170SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERV INC
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.25
Waste Quantity:	500
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20150916
Creation Date:	4/7/2016 22:15:27
Receipt Date:	20151009
Manifest ID:	005017170SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERV INC
TSDF EPA ID:	NED981723513
Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H040 - Incineration--Thermal Destruction Other Than Use As A Fuel
Quantity Tons:	0.125
Waste Quantity:	250
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20150216
Creation Date:	8/10/2015 22:15:28
Receipt Date:	20150223
Manifest ID:	004507385SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERV INC
TSDF EPA ID:	NED981723513

PALOMAR CLEANERS (Continued) **1001022994**

Trans Name:	CLEAN HARBORS ENVIRONMENTAL SERVICES IN
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.585
Waste Quantity:	1170
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2014
Gen EPA ID:	CAR000003384
Shipment Date:	20140429
Creation Date:	7/11/2014 22:15:07
Receipt Date:	20140516
Manifest ID:	004233560SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERV INC
TSDF EPA ID:	CAD044429835
Trans Name:	CLEAN HARBORS WILMINGTON LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.15
Waste Quantity:	300
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20140429
Creation Date:	7/11/2014 22:15:07
Receipt Date:	20140516
Manifest ID:	004233560SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	MAD039322250
Trans 2 Name:	CLEAN HARBORS ENV SERV INC
TSDF EPA ID:	CAD044429835
Trans Name:	CLEAN HARBORS WILMINGTON LLC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported

PALOMAR CLEANERS (Continued) **1001022994**

Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.15
Waste Quantity:	300
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2013
Gen EPA ID:	CAR000003384
Shipment Date:	20131108
Creation Date:	3/26/2014 22:15:09
Receipt Date:	20131111
Manifest ID:	003933827SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.15
Waste Quantity:	300
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20131108
Creation Date:	3/26/2014 22:15:09
Receipt Date:	20131111
Manifest ID:	003933827SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No

PALOMAR CLEANERS (Continued) **1001022994**

	Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.1
Waste Quantity:	200
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130320
Creation Date:	7/17/2013 22:15:13
Receipt Date:	20130327
Manifest ID:	003653987SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.09
Waste Quantity:	180
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20130320
Creation Date:	7/17/2013 22:15:13
Receipt Date:	20130327
Manifest ID:	003653987SKS
Trans EPA ID:	TXR000081205
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.195
Waste Quantity:	390
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007

PALOMAR CLEANERS (Continued) **1001022994**

Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2011
Gen EPA ID:	CAR000003384
Shipment Date:	20111005
Creation Date:	3/26/2012 20:30:13
Receipt Date:	20111014
Manifest ID:	002882929SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.3
Waste Quantity:	600
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D029
Additional Code 4:	D007
Additional Code 5:	Not reported
Shipment Date:	20110526
Creation Date:	10/19/2011 18:30:52
Receipt Date:	20110601
Manifest ID:	002580932SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.3
Waste Quantity:	600
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D029
Additional Code 4:	D007
Additional Code 5:	Not reported

PALOMAR CLEANERS (Continued) **1001022994**

Additional Info:

Year:	2010
Gen EPA ID:	CAR000003384
Shipment Date:	20100730
Creation Date:	1/26/2011 18:30:09
Receipt Date:	20100804
Manifest ID:	003336164FLE
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.625
Waste Quantity:	1250
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D029
Additional Code 4:	D007
Additional Code 5:	Not reported

Additional Info:

Year:	2007
Gen EPA ID:	CAR000003384
Shipment Date:	20070604
Creation Date:	12/20/2007 18:30:41
Receipt Date:	20070608
Manifest ID:	000247495SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.095
Waste Quantity:	190
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported

PALOMAR CLEANERS (Continued) **1001022994**

Additional Code 5:	Not reported
Shipment Date:	20070604
Creation Date:	12/20/2007 18:30:41
Receipt Date:	20070608
Manifest ID:	000247495SKS
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.1325
Waste Quantity:	265
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2006
Gen EPA ID:	CAR000003384
Shipment Date:	20060919
Creation Date:	3/30/2007 13:31:11
Receipt Date:	20060926
Manifest ID:	001052013JJK
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.0975
Waste Quantity:	195
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20060919

PALOMAR CLEANERS (Continued) **1001022994**

Creation Date:	3/30/2007 13:31:11
Receipt Date:	20060926
Manifest ID:	001052013JJK
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H141 - Storage, Bulking, And/Or Transfer Off Site--No Treatment/Reovery (H010-H129) Or (H131-H135)
Quantity Tons:	0.265
Waste Quantity:	530
Quantity Unit:	P
Additional Code 1:	D040
Additional Code 2:	D039
Additional Code 3:	D007
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2004
Gen EPA ID:	CAR000003384
Shipment Date:	20041102
Creation Date:	1/11/2005 18:30:51
Receipt Date:	20041110
Manifest ID:	23707943
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.09
Waste Quantity:	180
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20041102
Creation Date:	1/11/2005 18:30:51
Receipt Date:	20041110
Manifest ID:	23707943
Trans EPA ID:	TXR000050930

PALOMAR CLEANERS (Continued) **1001022994**

Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.19
Waste Quantity:	380
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20040616
Creation Date:	10/15/2004 15:16:06
Receipt Date:	20040618
Manifest ID:	23348491
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002
Meth Code:	H01 - Transfer Station
Quantity Tons:	0.375
Waste Quantity:	750
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20040616
Creation Date:	10/15/2004 15:16:06
Receipt Date:	20040618
Manifest ID:	23348491
Trans EPA ID:	TXR000050930
Trans Name:	SAFETY-KLEEN SYSTEMS INC
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAT000613893
Trans Name:	SAFETY-KLEEN SYSTEMS INC
TSDF Alt EPA ID:	CAT000613893
TSDF Alt Name:	Not reported
Waste Code Description:	741 - Liquids with halogenated organic compounds > 1000 mg/l
RCRA Code:	F002

PALOMAR CLEANERS (Continued) **1001022994**

Meth Code:	H01 - Transfer Station
Quantity Tons:	0.09
Waste Quantity:	180
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2003
Gen EPA ID:	CAR000003384
Shipment Date:	20030821
Creation Date:	8/3/2004 7:33:04
Receipt Date:	20030902
Manifest ID:	22692799
Trans EPA ID:	CAD981375983
Trans Name:	TECHNICHEM INC
Trans 2 EPA ID:	CAD981375983
Trans 2 Name:	TECHNICHEM INC
TSDF EPA ID:	NVR000076158
Trans Name:	RESOLVENT INC
TSDF Alt EPA ID:	NVR000076158
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030821
Creation Date:	8/3/2004 7:33:04
Receipt Date:	20030902
Manifest ID:	22692799
Trans EPA ID:	CAD981375983
Trans Name:	TECHNICHEM INC
Trans 2 EPA ID:	CAD981375983
Trans 2 Name:	TECHNICHEM INC
TSDF EPA ID:	NVR000076158
Trans Name:	RESOLVENT INC
TSDF Alt EPA ID:	NVR000076158
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	F002
Meth Code:	R01 - Recycler
Quantity Tons:	0.17
Waste Quantity:	340
Quantity Unit:	P
Additional Code 1:	Not reported

PALOMAR CLEANERS (Continued) **1001022994**

Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030821
Creation Date:	8/3/2004 7:33:04
Receipt Date:	20030902
Manifest ID:	22692799
Trans EPA ID:	CAD981375983
Trans Name:	TECHNICHEM INC
Trans 2 EPA ID:	CAD981375983
Trans 2 Name:	TECHNICHEM INC
TSDF EPA ID:	NVR000076158
Trans Name:	RESOLVENT INC
TSDF Alt EPA ID:	NVR000076158
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	F002
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030821
Creation Date:	8/3/2004 7:33:04
Receipt Date:	20030902
Manifest ID:	22692799
Trans EPA ID:	CAD981375983
Trans Name:	TECHNICHEM INC
Trans 2 EPA ID:	CAD981375983
Trans 2 Name:	TECHNICHEM INC
TSDF EPA ID:	NVR000076158
Trans Name:	RESOLVENT INC
TSDF Alt EPA ID:	NVR000076158
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030327
Creation Date:	1/5/2007 18:30:44
Receipt Date:	20030407
Manifest ID:	22304266

PALOMAR CLEANERS (Continued) **1001022994**

Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVR000076158
Trans Name:	Not reported
TSDF Alt EPA ID:	NVR000076158
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20030327
Creation Date:	1/5/2007 18:30:44
Receipt Date:	20030407
Manifest ID:	22304266
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVR000076158
Trans Name:	Not reported
TSDF Alt EPA ID:	NVR000076158
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	F002
Meth Code:	R01 - Recycler
Quantity Tons:	0.21
Waste Quantity:	420
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Shipment Date:	20030327
Creation Date:	1/5/2007 18:30:44
Receipt Date:	20030407
Manifest ID:	22304266
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVR000076158
Trans Name:	Not reported
TSDF Alt EPA ID:	NVR000076158
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg

PALOMAR CLEANERS (Continued) **1001022994**

RCRA Code:	F002
Meth Code:	R01 - Recycler
Quantity Tons:	0.09591
Waste Quantity:	23
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20030327
Creation Date:	1/5/2007 18:30:44
Receipt Date:	20030407
Manifest ID:	22304266
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVR000076158
Trans Name:	Not reported
TSDF Alt EPA ID:	NVR000076158
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

Additional Info:

Year:	2002
Gen EPA ID:	CAR000003384
Shipment Date:	20021217
Creation Date:	3/31/2003 18:31:15
Receipt Date:	20021220
Manifest ID:	21852347
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981375983
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	F002
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	G

PALOMAR CLEANERS (Continued) **1001022994**

Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20021217
Creation Date:	3/31/2003 18:31:15
Receipt Date:	20021220
Manifest ID:	21852347
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981375983
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20021217
Creation Date:	3/31/2003 18:31:15
Receipt Date:	20021220
Manifest ID:	21852347
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981375983
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	F002
Meth Code:	R01 - Recycler
Quantity Tons:	0.2
Waste Quantity:	400
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20021217
Creation Date:	3/31/2003 18:31:15
Receipt Date:	20021220

PALOMAR CLEANERS (Continued) **1001022994**

Manifest ID:	21852347
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981375983
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20021024
Creation Date:	2/7/2003 18:31:45
Receipt Date:	20021107
Manifest ID:	21852046
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981375983
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	F002
Meth Code:	R01 - Recycler
Quantity Tons:	0.21
Waste Quantity:	420
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20021024
Creation Date:	2/7/2003 18:31:45
Receipt Date:	20021107
Manifest ID:	21852046
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981375983
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported

PALOMAR CLEANERS (Continued) **1001022994**

Waste Code Description:	751 - Solids or sludge with halogenated organic comp. > 1000 mg/kg
RCRA Code:	F002
Meth Code:	R01 - Recycler
Quantity Tons:	0.05004
Waste Quantity:	12
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20021024
Creation Date:	2/7/2003 18:31:45
Receipt Date:	20021107
Manifest ID:	21852046
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981375983
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	D039
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20021024
Creation Date:	2/7/2003 18:31:45
Receipt Date:	20021107
Manifest ID:	21852046
Trans EPA ID:	CAD981375983
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD981375983
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	213 - Hydrocarbon solvents (benzene, hexane, Stoddard, etc.
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	Not reported
Waste Quantity:	Not reported
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported

PALOMAR CLEANERS (Continued) **1001022994**

Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20020717
Creation Date:	3/12/2003 18:31:29
Receipt Date:	20020726
Manifest ID:	21278143
Trans EPA ID:	CA0000970392
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	611 - Contaminated soil from site clean-ups
RCRA Code:	F002
Meth Code:	D80 - Disposal, Land Fill
Quantity Tons:	1.05
Waste Quantity:	2100
Quantity Unit:	P
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported
Shipment Date:	20020717
Creation Date:	3/12/2003 18:31:29
Receipt Date:	20020726
Manifest ID:	21278143
Trans EPA ID:	CA0000970392
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	NVT330010000
Trans Name:	Not reported
TSDF Alt EPA ID:	Not reported
TSDF Alt Name:	Not reported
Waste Code Description:	134 - Aqueous solution with <10% total organic residues
RCRA Code:	F002
Meth Code:	D99 - Disposal, Other
Quantity Tons:	0.315
Waste Quantity:	75
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

CERS:

Name:	PALOMAR CLEANERS
Address:	7870 BROADWAY
City,State,Zip:	LEMON GROVE, CA 91945-1801
Site ID:	200736
CERS ID:	T0608121884

PALOMAR CLEANERS (Continued) **1001022994**

CERS Description: Cleanup Program Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: SASHA SMIRENSKY - SAN DIEGO RWQCB (REGION 9)
Entity Title: Not reported
Affiliation Address: 2375 Northside Dr,
Affiliation City: SAN DIEGO
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: 6195213358,

Name: PALOMAR CLEANERS
Address: 7870 BROADWAY
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 485941
CERS ID: 110002906473
CERS Description: US EPA Air Emission Inventory System (EIS)

Affiliation:
Affiliation Type Desc: Environmental Contact
Entity Name: CARLOS BARRADAS
Entity Title: Not reported
Affiliation Address: 6738 SALIZAR ST
Affiliation City: SANDIEGO
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Regional Board Caseworker
Entity Name: SARAH A MEARON SAN DIEGO RWQCB REGN 9
Entity Title: Not reported
Affiliation Address: 2375 NORTHSIDE DRIVENA SUITE 100
Affiliation City: SANDIEGO
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Environmental Contact
Entity Name: LARRY PEREZ
Entity Title: Not reported
Affiliation Address: 7870 BROADWAY
Affiliation City: LEMONGROVE
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

HWTS:
Name: PALOMAR CLEANERS
Address: 7870 BROADWAY
Address 2: Not reported
City,State,Zip: LEMON GROVE, CA 91945

PALOMAR CLEANERS (Continued) **1001022994**

EPA ID:	CAR000003384
Inactive Date:	06/30/2015
Create Date:	12/08/1995
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	7870 BROADWAY
Mailing Address 2:	Not reported
Mailing City,State,Zip:	LEMON GROVE, CA 919451801
Owner Name:	SUE VINCK
Owner Address:	2256 DURASNO LN
Owner Address 2:	Not reported
Owner City,State,Zip:	SPRING VALLEY, CA 919777127
Contact Name:	SUE VINCK
Contact Address:	2256 DURASNO LN
Contact Address 2:	Not reported
City,State,Zip:	SPRING VALLEY, CA 919777127
Facility Status:	Inactive
Facility Type:	PERMANENT
Category:	FEDERAL
Latitude:	32.74281
Longitude:	-117.02939

NAICS:

EPA ID:	CAR000003384
Create Date:	2002-03-14 16:36:30.000
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
Issued EPA ID Date:	1995-12-08 00:00:00
Inactive Date:	2015-06-30 00:00:00
Facility Name:	PALOMAR CLEANERS
Facility Address:	7870 BROADWAY
Facility Address 2:	Not reported
Facility City:	LEMON GROVE
Facility County:	Not reported
Facility State:	CA
Facility Zip:	919451801

110
North
1/2-1
0.579 mi.
3057 ft.

Relative:
Lower

Actual:
431 ft.

HELIX CHARTER HIGH SCHOOL
7323 UNIVERSITY AVENUE
LA MESA, CA 91944

ENVIROSTOR **S103670769**
LUST **N/A**
SCH
Cortese
HIST CORTESE
NPDES
CIWQS
HWTS

ENVIROSTOR:

Name:	HELIX CHARTER HIGH SCHOOL
Address:	7323 UNIVERSITY AVENUE
City,State,Zip:	LA MESA, CA 91944
Facility ID:	60000862
Status:	No Further Action
Status Date:	11/04/2009
Site Code:	404789
Site Type:	School Investigation
Site Type Detailed:	School
Acres:	1

HELIX CHARTER HIGH SCHOOL (Continued) **S103670769**

NPL: NO
Regulatory Agencies: SMBRP
Lead Agency: SMBRP
Program Manager: Angela Garcia
Supervisor: Shahir Haddad
Division Branch: Southern California Schools & Brownfields Outreach
Assembly: 79
Senate: 38
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: School District
Latitude: 32.7543
Longitude: -117.0367
APN: 4741811900, 475-050-06-00
Past Use: AGRICULTURAL - ORCHARD, SCHOOL - HIGH SCHOOL
Potential COC: Under Investigation
Confirmed COC: NONE SPECIFIED
Potential Description: UE
Alias Name: 4741811900
Alias Type: APN
Alias Name: 475-050-06-00
Alias Type: APN
Alias Name: 404789
Alias Type: Project Code (Site Code)
Alias Name: 60000862
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Tech Memo
Completed Date: 03/09/2009
Comments: Approval letter issued with the condition that the District incorporates comments enclosed with the letter (previously emailed 2/19/09) during fieldwork and/or in SSI.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Tech Memo
Completed Date: 04/13/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Supplemental Site Investigation Report
Completed Date: 10/08/2009
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 06/27/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1

HELIX CHARTER HIGH SCHOOL (Continued) **S103670769**

Completed Date: 04/09/2008
Comments: DTSC determined that a preliminary environmental assessment was required based on review of the Phase I

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 02/05/2009
Comments: Notified by District on Jan. 20, 2009 that it plans to conduct SSI. PEA FA letter completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 09/17/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 06/13/2008
Comments: Signed Agreement sent (FedEx) to District on June 24, 2008.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 10/12/2009
Comments: DTSC prepared project close out Cost Recovery Unit Memorandum.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

LUST:
Name: HELIX HIGH SCHOOL
Address: 7323 UNIVERSITY AV
City,State,Zip: LA MESA, CA 919416055
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607301091
Global Id: T0607301091
Latitude: 32.7559557
Longitude: -117.0398162
Status: Completed - Case Closed
Status Date: 12/28/2006
Case Worker: EM
RB Case Number: 9UT2321
Local Agency: SAN DIEGO COUNTY LOP
File Location: Local Agency
Local Case Number: H20561-001
Potential Media Affect: Soil

HELIX CHARTER HIGH SCHOOL (Continued) **S103670769**

Potential Contaminants of Concern: Heating Oil / Fuel Oil
Site History: Not reported

LUST:
Global Id: T0607301091
Contact Type: Local Agency Caseworker
Contact Name: EWAN MOFFAT
Organization Name: SAN DIEGO COUNTY LOP
Address: P.O. Box 129261
City: San Diego
Email: ewan.moffat@sdcounty.ca.gov
Phone Number: Not reported

LUST:
Global Id: T0607301091
Action Type: Other
Date: 09/02/1992
Action: Leak Discovery

Global Id: T0607301091
Action Type: Other
Date: 09/02/1992
Action: Leak Began

Global Id: T0607301091
Action Type: Other
Date: 09/02/1992
Action: Leak Reported

Global Id: T0607301091
Action Type: ENFORCEMENT
Date: 12/08/1992
Action: Notice of Responsibility

Global Id: T0607301091
Action Type: Other
Date: 09/02/1992
Action: Leak Stopped

Global Id: T0607301091
Action Type: ENFORCEMENT
Date: 12/29/2006
Action: Closure/No Further Action Letter

LUST:
Global Id: T0607301091
Status: Open - Case Begin Date
Status Date: 09/02/1992

Global Id: T0607301091
Status: Completed - Case Closed
Status Date: 12/28/2006

SCH:

HELIX CHARTER HIGH SCHOOL (Continued) **S103670769**

Name:	HELIX CHARTER HIGH SCHOOL
Address:	7323 UNIVERSITY AVENUE
City,State,Zip:	LA MESA, CA 91944
Facility ID:	60000862
Site Type:	School Investigation
Site Type Detail:	School
Site Mgmt. Req.:	NONE SPECIFIED
Acres:	1
National Priorities List:	NO
Cleanup Oversight Agencies:	SMBRP
Lead Agency:	SMBRP
Lead Agency Description:	DTSC - Site Cleanup Program
Project Manager:	Angela Garcia
Supervisor:	Shahir Haddad
Division Branch:	Southern California Schools & Brownfields Outreach
Site Code:	404789
Assembly:	79
Senate:	38
Special Program Status:	Not reported
Status:	No Further Action
Status Date:	11/04/2009
Restricted Use:	NO
Funding:	School District
Latitude:	32.7543
Longitude:	-117.0367
APN:	4741811900, 475-050-06-00
Past Use:	AGRICULTURAL - ORCHARD, SCHOOL - HIGH SCHOOL
Potential COC:	Under Investigation
Confirmed COC:	NONE SPECIFIED
Potential Description:	UE
Alias Name:	4741811900
Alias Type:	APN
Alias Name:	475-050-06-00
Alias Type:	APN
Alias Name:	404789
Alias Type:	Project Code (Site Code)
Alias Name:	60000862
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Tech Memo
Completed Date:	03/09/2009
Comments:	Approval letter issued with the condition that the District incorporates comments enclosed with the letter (previously emailed 2/19/09) during fieldwork and/or in SSI.

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Tech Memo
Completed Date:	04/13/2009
Comments:	Not reported

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Supplemental Site Investigation Report
Completed Date:	10/08/2009

HELIX CHARTER HIGH SCHOOL (Continued) **S103670769**

Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Workplan
Completed Date: 06/27/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Phase 1
Completed Date: 04/09/2008
Comments: DTSC determined that a preliminary environmental assessment was required based on review of the Phase I

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Preliminary Endangerment Assessment Report
Completed Date: 02/05/2009
Comments: Notified by District on Jan. 20, 2009 that it plans to conduct SSI. PEA FA letter completed.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 09/17/2008
Comments: Not reported

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Environmental Oversight Agreement
Completed Date: 06/13/2008
Comments: Signed Agreement sent (FedEx) to District on June 24, 2008.

Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: Cost Recovery Closeout Memo
Completed Date: 10/12/2009
Comments: DTSC prepared project close out Cost Recovery Unit Memorandum.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

CORTESE:
Name: HELIX HIGH SCHOOL
Address: 7323 UNIVERSITY AV
City,State,Zip: LA MESA, CA 919416055
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0607301091

HELIX CHARTER HIGH SCHOOL (Continued) **S103670769**

Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

HIST CORTESE:

edr_fname:	HELIX HIGH SCHOOL
edr_fadd1:	7323 UNIVERSITY
City,State,Zip:	LA MESA, CA 91941
Region:	CORTESE
Facility County Code:	37
Reg By:	LTNKA
Reg Id:	9UT2321

NPDES:

Name:	GUHSD HELIX HS PHASE 3 4 & 5A
Address:	7323 UNIVERSITY AVE
City,State,Zip:	LA MESA, CA 91942
Facility Status:	Not reported
NPDES Number:	Not reported
Region:	Not reported
Agency Number:	Not reported
Regulatory Measure ID:	Not reported
Place ID:	Not reported
Order Number:	Not reported
WDID:	Not reported
Regulatory Measure Type:	Construction
Program Type:	Not reported
Adoption Date Of Regulatory Measure:	Not reported
Effective Date Of Regulatory Measure:	Not reported
Termination Date Of Regulatory Measure:	Not reported
Expiration Date Of Regulatory Measure:	Not reported
Discharge Address:	Not reported
Discharge Name:	Not reported
Discharge City:	Not reported
Discharge State:	Not reported
Discharge Zip:	Not reported
Status:	Returned
Status Date:	07/19/2016
Operator Name:	Grossmont Union High School District
Operator Address:	1100 Murray Drive
Operator City:	El Cajon

HELIX CHARTER HIGH SCHOOL (Continued) **S103670769**

Operator State: California
Operator Zip: 92020

CIWQS:
Name: HELIX HIGH SCHOOL PAC
Address: 7323 UNIVERSITY AVE
City,State,Zip: LA MESA, CA 91941
Agency: Grossmont Union High School District
Agency Address: 1100 Murray Drive, El Cajon, CA 92020
Place/Project Type: Construction - Other: Educational Facility
SIC/NAICS: Not reported
Region: 9
Program: CONSTW
Regulatory Measure Status: Terminated
Regulatory Measure Type: Storm water construction
Order Number: 2009-0009-DWQ
WDID: 9 37C362830
NPDES Number: CAS000002
Adoption Date: Not reported
Effective Date: 01/19/2012
Termination Date: 10/31/2014
Expiration/Review Date: Not reported
Design Flow: Not reported
Major/Minor: Not reported
Complexity: Not reported
TTWQ: Not reported
Enforcement Actions within 5 years: 0
Violations within 5 years: 0
Latitude: 32.75598
Longitude: -117.03971

HWTS:
Name: GROSSMONT UHSD - HELIX
Address: 7323 UNIVERSITY AVE
Address 2: Not reported
City,State,Zip: LA MESA, CA 92041
EPA ID: CAD981458516
Inactive Date: Not reported
Create Date: 04/10/1987
Last Act Date: Not reported
Mailing Name: Not reported
Mailing Address: PO BOX 1043
Mailing Address 2: Not reported
Mailing City,State,Zip: LA MESA, CA 919441043
Owner Name: GROSSMONT UNION HIGH SCH DIST
Owner Address: PO BOX 1043
Owner Address 2: Not reported
Owner City,State,Zip: LA MESA, CA 919441043
Contact Name: DANIEL NEESEN
Contact Address: PO BOX 1043
Contact Address 2: Not reported
City,State,Zip: LA MESA, CA 919441043
Facility Status: Active
Facility Type: PERMANENT
Category: STATE
Latitude: 32.749771

HELIX CHARTER HIGH SCHOOL (Continued) **S103670769**

Longitude: -117.119904

NAICS:

EPA ID: CAD981458516
Create Date: 2006-03-27 16:36:26.000
NAICS Code: 61111
NAICS Description: Elementary and Secondary Schools
Issued EPA ID Date: 1987-04-10 00:00:00
Inactive Date: Not reported
Facility Name: GROSSMONT UHSD - HELIX
Facility Address: 7323 UNIVERSITY AVE
Facility Address 2: Not reported
Facility City: LA MESA
Facility County: Not reported
Facility State: CA
Facility Zip: 920410000

111
SE
1/2-1
0.635 mi.
3352 ft.

Relative:
Lower

Actual:
441 ft.

SONKA TRUST PROPERTY
3065 LEMON GROVE AV
LEMON GROVE, CA 91945

ENVIROSTOR **S106065786**
LUST **N/A**
SAN DIEGO CO. SAM
CPS-SLIC
San Diego Co. HMMD
Cortese
SAN DIEGO CO LOP
CERS

ENVIROSTOR:

Name: SONKA TRUST
Address: 3065 LEMON GROVE AVENUE
City,State,Zip: LEMON GROVE, CA 91945
Facility ID: 37000055
Status: Refer: 1248 Local Agency
Status Date: 02/01/2000
Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: 0
NPL: NO
Regulatory Agencies: SAN DIEGO COUNTY
Lead Agency: SAN DIEGO COUNTY
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Cypress
Assembly: 79
Senate: 38
Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not Applicable
Latitude: 32.73914
Longitude: -117.0306
APN: 40827105, 40827108
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 40827105

SONKA TRUST PROPERTY (Continued) **S106065786**

Alias Type: APN
Alias Name: 40827108
Alias Type: APN
Alias Name: 37000055
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: SB 1248 Notification
Completed Date: 02/01/2000
Comments: DTSC is not involved with this project.

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

LUST:
Name: SONKA TRUST PROPERTY
Address: 3065 LEMON GROVE AV
City,State,Zip: LEMON GROVE, CA 91945
Lead Agency: SAN DIEGO COUNTY LOP
Case Type: LUST Cleanup Site
Geo Track: http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0607399231
Global Id: T0607399231
Latitude: 32.739441
Longitude: -117.03052
Status: Completed - Case Closed
Status Date: 03/01/2001
Case Worker: Not reported
RB Case Number: 9UT4033
Local Agency: Not reported
File Location: Local Agency
Local Case Number: H38970-001
Potential Media Affect: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

LUST:
Global Id: T0607399231
Action Type: ENFORCEMENT
Date: 03/01/2001
Action: Closure/No Further Action Letter

Global Id: T0607399231
Action Type: Other
Date: 01/24/2000
Action: Leak Began

Global Id: T0607399231
Action Type: Other
Date: 01/14/2000

SONKA TRUST PROPERTY (Continued) **S106065786**

Action: Leak Reported

Global Id: T0607399231
Action Type: Other
Date: 01/24/2000
Action: Leak Discovery

LUST:
Global Id: T0607399231
Status: Open - Case Begin Date
Status Date: 01/14/2000

Global Id: T0607399231
Status: Completed - Case Closed
Status Date: 03/01/2001

SAN DIEGO CO. SAM:
Name: SONKA TRUST PROPERTY
Address: 3065 LEMON GROVE AV
City,State,Zip: LEMON GROVE, CA 91945
Case Number: H38970-001
Agency: DEH Site Assessment & Mitigation
Funding: **LOP - Federal Fund**
Facility Type: Soils Only
Facility Status: Closed Case
Date: 3/1/2001
Date Began: 1/24/2000

Name: SONKA TRUST PROPERTY
Address: 3065 LEMON GROVE AV
City,State,Zip: LEMON GROVE, CA 91945
Case Number: H38970-002
Agency: DEH Site Assessment & Mitigation
Funding: **Private - VAP**
Facility Type: Soils Only
Facility Status: Preliminary Assessment
Date: 11/22/2006
Date Began: Not reported

CPS-SLIC:
Name: SONKA TRUST PROPERTY
Address: 3065 LEMON GROVE AV
City,State,Zip: LEMON GROVE, CA 91945
Region: STATE
Facility Status: **Open - Site Assessment**
Status Date: 11/22/2006
Global Id: SLT19796830
Lead Agency: SAN DIEGO COUNTY LOP
Lead Agency Case Number: H38970-002
Latitude: 32.7392385687089
Longitude: -117.030463516533
Case Type: Cleanup Program Site
Case Worker: EM
Local Agency: SAN DIEGO COUNTY LOP
RB Case Number: Not reported

SONKA TRUST PROPERTY (Continued) **S106065786**

File Location: Local Agency
Potential Media Affected: Soil
Potential Contaminants of Concern: Gasoline
Site History: Not reported

Click here to access the California GeoTracker records for this facility:

HMMD SAN DIEGO:

Name: SONKA TRUST PROPERTY
Address: 3065 LEMON GROVE AV
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: 138970
Business Type: Not reported
EPA Id Number: Not reported
APN: 480-271-05-00
Last HMMD Inspection: Not reported
Facility Telephone: Not reported
Permit Status: INAC
Permit Expiration: Not reported
Date Last Updated: 11/02/2012
Facility Owner: Not reported
Facility Mailing Address: Not reported
Facility Mailing City: Not reported
Facility Mailing State: Not reported
Facility Mailing Zip: Not reported
UST Owner: Not reported
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: Not reported
Treat Haz Waste: Not reported
Generate Medical Waste: Not reported

Name: POPEYES13683
Address: 3065 LEMON GROVE AVE
City,State,Zip: LEMON GROVE, CA 91945
Permit Number: Not reported
Business Type: Not reported
EPA Id Number: Not reported
APN: Not reported
Last HMMD Inspection: Not reported
Facility Telephone: (951) 239-3505
Permit Status: Permit Renewed
Permit Expiration: Not reported
Date Last Updated: 11/16/2022
Facility Owner: Not reported
Facility Mailing Address: 41760 Ivy street ste#201, Murrieta, CA 92562
Facility Mailing City: Not reported
Facility Mailing State: Not reported
Facility Mailing Zip: Not reported
UST Owner: N
Handle Regulated Hazmat: Not reported
Own Or Operate UST: Not reported
Subject To APSA: Not reported
Generate Haz Waste: N
Treat Haz Waste: N
Generate Medical Waste: Not reported

SONKA TRUST PROPERTY (Continued) **S106065786**

Inspection Violation:

Record ID:	DEH2022-HUPFP-007337
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-007337
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection
Inspection Number:	6896818
Return To Compliance Date:	2022-10-28T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-11-16T00:00:00.000
Inspection Date:	2022-10-05T00:00:00.000
Violation Code:	1010017 HMBP not readily available to facility personnel or the CUPA. HSC 25505(c)

Record ID:	DEH2022-HUPFP-007337
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-007337
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection
Inspection Number:	6896818
Return To Compliance Date:	2022-10-28T00:00:00.000
Nov:	No
Violation Classification:	Minor
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-11-16T00:00:00.000
Inspection Date:	2022-10-05T00:00:00.000
Violation Code:	1010005 Site map not submitted in CERS or not sufficient. HSC 25505(a)(2); 25508.1(f); 19 CCR 2652(a)(3)

Record ID:	DEH2022-HUPFP-007337
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-007337
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection
Inspection Number:	6896818
Return To Compliance Date:	Not reported
Nov:	Not reported
Violation Classification:	Not reported
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-11-16T00:00:00.000
Inspection Date:	2022-10-05T00:00:00.000
Violation Code:	HMD0000 HAZARDOUS MATERIALS REQUIREMENTS

Record ID:	DEH2022-HUPFP-007337
Permit Status:	Permit Renewed
Active Permit:	Y
Facility Id Number:	37-000-007337
Program Element:	Hazardous Materials Release Response Plans
Inspection Type:	Initial Inspection

SONKA TRUST PROPERTY (Continued) **S106065786**

Inspection Number:	6896818
Return To Compliance Date:	2022-11-02T00:00:00.000
Nov:	No
Violation Classification:	Class II
Underground Storage Tank Id:	Not reported
Container/Tank Id:	Not reported
Last Update:	2022-11-16T00:00:00.000
Inspection Date:	2022-10-05T00:00:00.000
Violation Code:	HMD1005 Emergency contact not provided or current in CERS. HSC 25508.1(f); SDCC 68.904(b)

Waste and Materials:

Record ID:	DEH2022-HUPFP-007337
Permit Status:	Issued
Active Permit:	Y
Child Record Id:	DEH2022-HCHEM-0344715
Trade Secret:	N
Hazardous Material Type:	Pure
Last Updated:	2022-11-05T02:46:15.000
Chemical Name:	Carbon Dioxide
Common Name:	Carbon Dioxide
Case Number:	124-38-9

CORTESE:

Name:	SONKA TRUST PROPERTY
Address:	3065 LEMON GROVE AV
City,State,Zip:	LEMON GROVE, CA 91945
Region:	CORTESE
Envirostor Id:	Not reported
Global ID:	T0607399231
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

SAN DIEGO CO LOP:

Name:	SONKA TRUST PROPERTY
Address:	3065 LEMON GROVE AVE
City,State,Zip:	LEMON GROVE, CA 91945
Record ID:	DEH2000-LSAM-H38970-001
Record Status:	Completed

SONKA TRUST PROPERTY (Continued) **S106065786**

Opened Date:	01/14/2000
Parcel Number:	480-271-05-00
Case Type:	LOP - Local Oversight Program
Historical Name:	SONKA TRUST PROPERTIES
SWRCB Global ID:	T0607399231
Funding:	F - LOP Federal Fund
Lead Agency:	DEH/SAM
Lead Agency Date:	01/24/2000
Census Tract:	144.00
Community:	Not reported
Jurisdiction:	Not reported
Watershed Basin Number:	908.22
Water Purveyor:	Not reported
Fire Agency:	Not reported
Latitude:	Not reported
Longitude:	Not reported
X MapCoord:	Not reported
Y MapCoord:	Not reported

CERS:

Name:	SONKA TRUST PROPERTY
Address:	3065 LEMON GROVE AV
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	187750
CERS ID:	SLT19796830
CERS Description:	Cleanup Program Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	EWAN MOFFAT - SAN DIEGO COUNTY LOP
Entity Title:	Not reported
Affiliation Address:	P.O. Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Name:	POPEYES13683
Address:	3065 LEMON GROVE AVE
City,State,Zip:	LEMON GROVE, CA 91945
Site ID:	598209
CERS ID:	10887487
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	598209
Site Name:	Popeyes13683
Violation Date:	10-05-2022
Citation:	HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Description:	Failure to complete and electronically submit a site map with all required content.
Violation Notes:	Returned to compliance on 10/28/2022. Inspection Sequence ID:6896818
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,

SONKA TRUST PROPERTY (Continued) **S106065786**

Site ID:	598209
Site Name:	Popeyes13683
Violation Date:	10-05-2022
Citation:	HSC 6.95 25505(c) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(c)
Violation Description:	Failure to have a business plan readily available to personnel of the business or the unified program facility with responsibilities for emergency response or training.
Violation Notes:	Returned to compliance on 10/28/2022. Inspection Sequence ID:6896818
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,

Site ID:	598209
Site Name:	Popeyes13683
Violation Date:	10-05-2022
Citation:	HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Description:	Business Plan Program - Administration/Documentation - General
Violation Notes:	Returned to compliance on 11/02/2022. Inspection Sequence ID:6896818;Violation:HMD1005 Emergency contact not provided or current in CERS. HSC 25508.1(f); SDCC 68.904(b)
Violation Division:	San Diego County Department of Env Health
Violation Program:	HMRRP
Violation Source:	CERS,

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	10-05-2022
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Inspector: Aka Jr Wilfred Inspection ID:6896818
Eval Division:	San Diego County Department of Env Health
Eval Program:	HMRRP
Eval Source:	CERS,

Coordinates:

Site ID:	598209
Facility Name:	Popeyes13683
Env Int Type Code:	HMBP
Program ID:	10887487
Coord Name:	Not reported
Ref Point Type Desc:	Center of a facility or station.,
Latitude:	32.739220
Longitude:	-117.030450

Affiliation:

Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not reported
Affiliation Address:	41760 Ivy street ste#201
Affiliation City:	Murrieta
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92562
Affiliation Phone:	,

SONKA TRUST PROPERTY (Continued) **S106065786**

Affiliation Type Desc:	Identification Signer
Entity Name:	Marcelle Meshreky
Entity Title:	Administrative Analyst
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	Legal Owner
Entity Name:	DMSD Cajun Eats LLC
Entity Title:	Not reported
Affiliation Address:	41760 Ivy street ste#201
Affiliation City:	Murrieta
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	92562
Affiliation Phone:	(951) 239-3505,

Affiliation Type Desc:	Parent Corporation
Entity Name:	DMSD Cajun Eats
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	CUPA District
Entity Name:	San Diego County Env Health Qlty
Entity Title:	Not reported
Affiliation Address:	PO Box 129261
Affiliation City:	San Diego
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	92112-9261
Affiliation Phone:	(858) 505-6880,

Affiliation Type Desc:	Document Preparer
Entity Name:	Marcelle Meshreky
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	Environmental Contact
Entity Name:	OSCAR MATHIEU
Entity Title:	Not reported
Affiliation Address:	41760 Ivy street ste#201
Affiliation City:	Murrieta
Affiliation State:	CA
Affiliation Country:	Not reported

SONKA TRUST PROPERTY (Continued) **S106065786**

Affiliation Zip: 92562
Affiliation Phone: ,

Affiliation Type Desc: Operator
Entity Name: DMSD Cajun Eats LLC.
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: (951) 239-3505,

Name: SONKA TRUST PROPERTY
Address: 3065 LEMON GROVE AV
City,State,Zip: LEMON GROVE, CA 91945
Site ID: 187750
CERS ID: T0607399231
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Local Agency Caseworker
Entity Name: EWAN MOFFAT - SAN DIEGO COUNTY LOP
Entity Title: Not reported
Affiliation Address: P.O. Box 129261
Affiliation City: San Diego
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

112
NW
1/2-1
0.730 mi.
3854 ft.

COMMERCIAL SHOPPING CENTER #119 **ENVIROSTOR** **S106893846**
7006-7020 UNIVERSITY AVE. **N/A**
LA MESA, CA 91941

Relative:
Lower

Actual:
425 ft.

ENVIROSTOR:
Name: COMMERCIAL SHOPPING CENTER #119
Address: 7006-7020 UNIVERSITY AVE.
City,State,Zip: LA MESA, CA 91941
Facility ID: 37150013
Status: Refer: 1248 Local Agency
Status Date: 12/26/2000
Site Code: Not reported
Site Type: Evaluation
Site Type Detailed: Evaluation
Acres: Not reported
NPL: NO
Regulatory Agencies: NONE SPECIFIED
Lead Agency: NONE SPECIFIED
Program Manager: Not reported
Supervisor: Referred - Not Assigned
Division Branch: Cleanup Cypress
Assembly: 79
Senate: 38

COMMERCIAL SHOPPING CENTER #119 (Continued) **S106893846**

Special Program: Not reported
Restricted Use: NO
Site Mgmt Req: NONE SPECIFIED
Funding: Not Applicable
Latitude: 32.75548
Longitude: -117.0470
APN: NONE SPECIFIED
Past Use: NONE SPECIFIED
Potential COC: NONE SPECIFIED
Confirmed COC: NONE SPECIFIED
Potential Description: NONE SPECIFIED
Alias Name: 37150013
Alias Type: Envirostor ID Number

Completed Info:
Completed Area Name: PROJECT WIDE
Completed Sub Area Name: Not reported
Completed Document Type: SB 1248 Notification
Completed Date: 12/26/2000
Comments: SB 1248 San Diego County

Future Area Name: Not reported
Future Sub Area Name: Not reported
Future Document Type: Not reported
Future Due Date: Not reported
Schedule Area Name: Not reported
Schedule Sub Area Name: Not reported
Schedule Document Type: Not reported
Schedule Due Date: Not reported
Schedule Revised Date: Not reported

---

113 **7-ELEVEN STORE #17450** **HIST UST** **1000281921**
SSE **7733 PALM AVENUE** **Notify 65** **N/A**
1/2-1 **LEMON GROVE, CA 91945**
0.884 mi.
4665 ft.

Relative: **Lower**
Actual: **400 ft.**

HIST UST:
Name: 7-ELEVEN FOOD STORE #17450
Address: 7733 PALM ST
City,State,Zip: LEMON GROVE, CA 92045
File Number: Not reported
URL: Not reported
Region: STATE
Facility ID: 00000010191
Facility Type: Gas Station
Other Type: Not reported
Contact Name: ROBERT WILLCOXSON
Telephone: 6194642711
Owner Name: THE SOUTHLAND CORPORATION
Owner Address: 7839 UNIVERSITY AVENUE
Owner City,St,Zip: LA MESA, CA 92041
Total Tanks: 0003

Tank Num: 001
Container Num: 17450-1
Year Installed: 1975
Tank Capacity: 00009940

7-ELEVEN STORE #17450 (Continued) **1000281921**

Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	0.25
Leak Detection:	Stock Inventor
Tank Num:	002
Container Num:	17450-2
Year Installed:	1975
Tank Capacity:	00009940
Tank Used for:	PRODUCT
Type of Fuel:	REGULAR
Container Construction Thickness:	0.25
Leak Detection:	Stock Inventor
Tank Num:	003
Container Num:	17450-3
Year Installed:	1975
Tank Capacity:	00006000
Tank Used for:	PRODUCT
Type of Fuel:	PREMIUM
Container Construction Thickness:	0.25
Leak Detection:	Stock Inventor

NOTIFY 65:

Name:	7-ELEVEN STORE #17450
Address:	7733 PALM AVENUE
City,State,Zip:	LEMON GROVE, CA 91945-2952
Date Reported:	Not reported
Staff Initials:	Not reported
Board File Number:	Not reported
Facility Type:	Not reported
Discharge Date:	Not reported
Issue Date:	Not reported
Incident Description:	Not reported
Global ID:	Not reported
Status:	Not reported

Count: 0 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
		NO SITES FOUND			

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 01/25/2023
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 25

Source: EPA
Telephone: N/A
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 01/25/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 26

Source: EPA
Telephone: N/A
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 01/25/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 26

Source: EPA
Telephone: N/A
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 12/20/2022
Date Data Arrived at EDR: 12/21/2022
Date Made Active in Reports: 03/10/2023
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 01/25/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 26

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 01/25/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 26

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 11/02/2022
Date Data Arrived at EDR: 11/08/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 63

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 02/03/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/16/2022
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/21/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/16/2022
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 85

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/21/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/12/2022
Date Data Arrived at EDR: 12/14/2022
Date Made Active in Reports: 12/19/2022
Number of Days to Update: 5

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

Lists of state- and tribal (Superfund) equivalent sites

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 10/24/2022
Date Data Arrived at EDR: 10/24/2022
Date Made Active in Reports: 01/12/2023
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/24/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 10/24/2022
Date Data Arrived at EDR: 10/24/2022
Date Made Active in Reports: 01/12/2023
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/24/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Quarterly

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 11/03/2022
Date Data Arrived at EDR: 11/03/2022
Date Made Active in Reports: 01/25/2023
Number of Days to Update: 83

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 02/07/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

LUST REG 3: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST REG 4: Underground Storage Tank Leak List
Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 6L: Leaking Underground Storage Tank Case Listing
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 7: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks
California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

LUST REG 9: Leaking Underground Storage Tank Report
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

LUST: Leaking Underground Fuel Tank Report (GEOTRACKER)
Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/22/2023
Number of Days to Update: 82

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

LUST REG 2: Fuel Leak List

Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

LUST REG 1: Active Toxic Site Investigation

Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 5: Leaking Underground Storage Tank Database

Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 10/19/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/26/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 10/14/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 11/23/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87
Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 11/23/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 10/14/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/23/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64
Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

CPS-SLIC: Statewide SLIC Cases (GEOTRACKER)
Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/22/2023
Number of Days to Update: 82
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22

Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35
Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36
Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11
Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17
Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 10/14/2021
Date Data Arrived at EDR: 11/05/2021
Date Made Active in Reports: 02/01/2022
Number of Days to Update: 88
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

MILITARY UST SITES: Military UST Sites (GEOTRACKER)
Military ust sites

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

UST CLOSURE: Proposed Closure of Underground Storage Tank (UST) Cases

UST cases that are being considered for closure by either the State Water Resources Control Board or the Executive Director have been posted for a 60-day public comment period. UST Case Closures being proposed for consideration by the State Water Resources Control Board. These are primarily UST cases that meet closure criteria under the decisional framework in State Water Board Resolution No. 92-49 and other Board orders. UST Case Closures proposed for consideration by the Executive Director pursuant to State Water Board Resolution No. 2012-0061. These are cases that meet the criteria of the Low-Threat UST Case Closure Policy. UST Case Closure Review Denials and Approved Orders.

Date of Government Version: 11/28/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/23/2023
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 916-327-7844
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

UST: Active UST Facilities

Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/22/2023
Number of Days to Update: 82

Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Semi-Annually

AST: Aboveground Petroleum Storage Tank Facilities

A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 07/06/2016
Date Data Arrived at EDR: 07/12/2016
Date Made Active in Reports: 09/19/2016
Number of Days to Update: 69

Source: California Environmental Protection Agency
Telephone: 916-327-5092
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 06/26/2023
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/23/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 10/14/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/23/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 10/19/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 11/23/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 11/23/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 10/14/2022
Date Data Arrived at EDR: 12/06/2022
Date Made Active in Reports: 03/03/2023
Number of Days to Update: 87

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2022
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/16/2022
Number of Days to Update: 64

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

Lists of state and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 10/24/2022
Date Data Arrived at EDR: 10/24/2022
Date Made Active in Reports: 01/12/2023
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/24/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Quarterly

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/13/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Considered Brownfieds Sites Listing

A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 12/14/2022
Date Data Arrived at EDR: 12/14/2022
Date Made Active in Reports: 03/07/2023
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 916-323-7905
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/10/2022
Date Made Active in Reports: 03/10/2022
Number of Days to Update: 0

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 12/07/2022
Next Scheduled EDR Contact: 03/27/2023
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: Waste Management Unit Database

Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: No Update Planned

SWRCY: Recycler Database
A listing of recycling facilities in California.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/22/2023
Number of Days to Update: 82

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing
A listing of registered waste tire haulers.

Date of Government Version: 11/16/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 02/13/2023
Number of Days to Update: 83

Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 02/15/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations
A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory
An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land
A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 01/06/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 8

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/02/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: No Update Planned

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 10/24/2022
Date Data Arrived at EDR: 10/24/2022
Date Made Active in Reports: 01/12/2023
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/24/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2022
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 71

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

CERS HAZ WASTE: CERS HAZ WASTE

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

Date of Government Version: 01/05/2023
Date Data Arrived at EDR: 01/06/2023
Date Made Active in Reports: 01/11/2023
Number of Days to Update: 5

Source: CalEPA
Telephone: 916-323-2514
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 01/06/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 8

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/02/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SAN FRANCISCO AST: Aboveground Storage Tank Site Listing

Aboveground storage tank sites

Date of Government Version: 11/03/2022
Date Data Arrived at EDR: 11/07/2022
Date Made Active in Reports: 01/24/2023
Number of Days to Update: 78

Source: San Francisco County Department of Public Health
Telephone: 415-252-3896
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

CA FID UST: Facility Inventory Database

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CERS TANKS: California Environmental Reporting System (CERS) Tanks
List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

Date of Government Version: 01/06/2023
Date Data Arrived at EDR: 01/06/2023
Date Made Active in Reports: 01/11/2023
Number of Days to Update: 5
Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 10/17/2022
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Quarterly

Local Land Records

LIENS: Environmental Liens Listing
A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 08/23/2022
Date Data Arrived at EDR: 08/24/2022
Date Made Active in Reports: 11/14/2022
Number of Days to Update: 82
Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 01/25/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 26
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Semi-Annually

DEED: Deed Restriction Listing
Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 11/28/2022
Date Data Arrived at EDR: 11/29/2022
Date Made Active in Reports: 02/13/2023
Number of Days to Update: 76
Source: DTSC and SWRCB
Telephone: 916-323-3400
Last EDR Contact: 02/28/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/13/2022
Date Data Arrived at EDR: 12/14/2022
Date Made Active in Reports: 03/10/2023
Number of Days to Update: 86
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 08/02/2022
Date Data Arrived at EDR: 10/17/2022
Date Made Active in Reports: 01/04/2023
Number of Days to Update: 79

Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Semi-Annually

LDS: Land Disposal Sites Listing (GEOTRACKER)

Land Disposal sites (Landfills) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81

Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing (GEOTRACKER)

Military sites (consisting of: Military UST sites; Military Privatized sites; and Military Cleanup sites [formerly known as DoD non UST]) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 11/21/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 11/01/2022
Date Data Arrived at EDR: 11/10/2022
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 91

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/14/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 02/02/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 12/13/2022
Date Data Arrived at EDR: 12/14/2022
Date Made Active in Reports: 03/10/2023
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 01/30/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 02/03/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/12/2022
Next Scheduled EDR Contact: 03/27/2023
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 100

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/16/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 10/17/2022
Date Data Arrived at EDR: 10/18/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 84

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/18/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/25/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 26

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 14

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2022
Date Data Arrived at EDR: 01/20/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 64

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/04/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 10/26/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 12/05/2022
Number of Days to Update: 13
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/22/2022
Number of Days to Update: 84
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 03/03/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 02/27/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 02/03/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 12/20/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/24/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2022
Date Data Arrived at EDR: 10/21/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 81

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 03/02/2022
Date Made Active in Reports: 03/25/2022
Number of Days to Update: 23

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 07/26/2021
Date Data Arrived at EDR: 07/27/2021
Date Made Active in Reports: 10/22/2021
Number of Days to Update: 87

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/30/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/13/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/25/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 26

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 11/07/2022
Date Data Arrived at EDR: 11/17/2022
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 85

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/22/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 11/29/2022
Date Data Arrived at EDR: 11/30/2022
Date Made Active in Reports: 12/22/2022
Number of Days to Update: 22

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 02/23/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/24/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/24/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/20/2022
Date Data Arrived at EDR: 12/20/2022
Date Made Active in Reports: 03/10/2023
Number of Days to Update: 80

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/01/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 08/03/2022
Date Data Arrived at EDR: 08/25/2022
Date Made Active in Reports: 10/24/2022
Number of Days to Update: 60

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 02/28/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 11/09/2021
Date Data Arrived at EDR: 10/20/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 82

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/09/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/25/2022
Date Data Arrived at EDR: 09/30/2022
Date Made Active in Reports: 12/22/2022
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 01/04/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/24/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 11/10/2022
Date Data Arrived at EDR: 11/10/2022
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 91

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/14/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 07/08/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 123

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 01/10/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 01/23/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 01/03/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS ECHO FIRE TRAINING: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS PART 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 10/26/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 02/23/2022
Date Data Arrived at EDR: 03/31/2022
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 222

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

A listing of PFAS contaminated sites included in the GeoTracker database.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/23/2023
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

AQUEOUS FOAM: Former Fire Training Facility Assessments Listing

Airports shown on this list are those believed to use Aqueous Film Forming Foam (AFFF), and certified by the Federal Aviation Administration (FAA) under Title 14, Code of Federal Regulations (CFR), Part 139 (14 CFR Part 139). This list was created by SWRCB using information available from the FAA. Location points shown are from the latitude and longitude listed on the FAA airport master record.

Date of Government Version: 09/06/2022
Date Data Arrived at EDR: 09/06/2022
Date Made Active in Reports: 10/26/2022
Number of Days to Update: 50

Source: State Water Resources Control Board
Telephone: 916-341-5455
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6

Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CORTESE: "Cortese" Hazardous Waste & Substances Sites List

The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 12/14/2022
Date Data Arrived at EDR: 12/14/2022
Date Made Active in Reports: 03/07/2023
Number of Days to Update: 83

Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

CUPA LIVERMORE-PLEASANTON: CUPA Facility Listing

list of facilities associated with the various CUPA programs in Livermore-Pleasanton

Date of Government Version: 12/07/2021
Date Data Arrived at EDR: 05/09/2022
Date Made Active in Reports: 05/17/2022
Number of Days to Update: 8

Source: Livermore-Pleasanton Fire Department
Telephone: 925-454-2361
Last EDR Contact: 02/10/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: Varies

DRYCLEANERS: Cleaner Facilities

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 08/27/2021
Date Data Arrived at EDR: 09/01/2021
Date Made Active in Reports: 11/19/2021
Number of Days to Update: 79

Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 01/24/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Annually

DRYCLEAN AVAQMD: Antelope Valley Air Quality Management District Drycleaner Listing

A listing of dry cleaners in the Antelope Valley Air Quality Management District.

Date of Government Version: 11/14/2022
Date Data Arrived at EDR: 11/14/2022
Date Made Active in Reports: 02/01/2023
Number of Days to Update: 79

Source: Antelope Valley Air Quality Management District
Telephone: 661-723-8070
Last EDR Contact: 02/23/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Varies

DRYCLEAN SOUTH COAST: South Coast Air Quality Management District Drycleaner Listing

A listing of dry cleaners in the South Coast Air Quality Management District

Date of Government Version: 11/17/2022
Date Data Arrived at EDR: 11/30/2022
Date Made Active in Reports: 02/14/2023
Number of Days to Update: 76

Source: South Coast Air Quality Management District
Telephone: 909-396-3211
Last EDR Contact: 02/15/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Varies

EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/13/2022
Date Made Active in Reports: 08/30/2022
Number of Days to Update: 78

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 12/15/2022
Next Scheduled EDR Contact: 03/27/2023
Data Release Frequency: Varies

ENF: Enforcement Action Listing

A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 10/17/2022
Date Data Arrived at EDR: 10/19/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 83

Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 01/18/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial Assurance information

Date of Government Version: 10/12/2022
Date Data Arrived at EDR: 10/12/2022
Date Made Active in Reports: 12/29/2022
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 11/08/2022
Date Data Arrived at EDR: 11/23/2022
Date Made Active in Reports: 02/13/2023
Number of Days to Update: 82

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 02/03/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: Varies

ICE: ICE

Contains data pertaining to the Permitted Facilities with Inspections / Enforcements sites tracked in Envirostor.

Date of Government Version: 11/10/2022
Date Data Arrived at EDR: 11/10/2022
Date Made Active in Reports: 02/01/2023
Number of Days to Update: 83

Source: Department of Toxic Subsances Control
Telephone: 877-786-9427
Last EDR Contact: 02/14/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List

The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HWP: EnviroStor Permitted Facilities Listing

Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 11/10/2022
Date Data Arrived at EDR: 11/10/2022
Date Made Active in Reports: 02/01/2023
Number of Days to Update: 83

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 02/14/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Quarterly

HWT: Registered Hazardous Waste Transporter Database

A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 10/03/2022
Date Data Arrived at EDR: 10/03/2022
Date Made Active in Reports: 12/15/2022
Number of Days to Update: 73

Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 01/04/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Quarterly

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 07/05/2022
Date Made Active in Reports: 09/19/2022
Number of Days to Update: 76

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Annually

MINES: Mines Site Location Listing
A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/22/2023
Number of Days to Update: 82
Source: Department of Conservation
Telephone: 916-322-1080
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing
The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 10/31/2022
Date Data Arrived at EDR: 11/29/2022
Date Made Active in Reports: 02/14/2023
Number of Days to Update: 77
Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 02/28/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Varies

NPDES: NPDES Permits Listing
A listing of NPDES permits, including stormwater.

Date of Government Version: 11/03/2022
Date Data Arrived at EDR: 11/03/2022
Date Made Active in Reports: 01/25/2023
Number of Days to Update: 83
Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 02/07/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: Quarterly

PEST LIC: Pesticide Regulation Licenses Listing
A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 11/28/2022
Date Data Arrived at EDR: 11/29/2022
Date Made Active in Reports: 02/14/2023
Number of Days to Update: 77
Source: Department of Pesticide Regulation
Telephone: 916-445-4038
Last EDR Contact: 02/28/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Quarterly

PROC: Certified Processors Database
A listing of certified processors.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/22/2023
Number of Days to Update: 82
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

NOTIFY 65: Proposition 65 Records
Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 12/07/2022
Date Data Arrived at EDR: 12/07/2022
Date Made Active in Reports: 03/01/2023
Number of Days to Update: 84
Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 06/26/2023
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

UIC: UIC Listing
A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/22/2023
Number of Days to Update: 82
Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

UIC GEO: Underground Injection Control Sites (GEOTRACKER)
Underground control injection sites

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81
Source: State Water Resource Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

WASTEWATER PITS: Oil Wastewater Pits Listing
Water officials discovered that oil producers have been dumping chemical-laden wastewater into hundreds of unlined pits that are operating without proper permits. Inspections completed by the Central Valley Regional Water Quality Control Board revealed the existence of previously unidentified waste sites. The water boards review found that more than one-third of the region's active disposal pits are operating without permission.

Date of Government Version: 02/11/2021
Date Data Arrived at EDR: 07/01/2021
Date Made Active in Reports: 09/29/2021
Number of Days to Update: 90
Source: RWQCB, Central Valley Region
Telephone: 559-445-5577
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9
Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 02/13/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: No Update Planned

WIP: Well Investigation Program Case List
Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13
Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 12/13/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: No Update Planned

MILITARY PRIV SITES: Military Privatized Sites (GEOTRACKER)
Military privatized sites

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

PROJECT: Project Sites (GEOTRACKER)
Projects sites

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

WDR: Waste Discharge Requirements Listing

In general, the Waste Discharge Requirements (WDRs) Program (sometimes also referred to as the "Non Chapter 15 (Non 15) Program") regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. Exemptions from Title 27 may be granted for nine categories of discharges (e.g., sewage, wastewater, etc.) that meet, and continue to meet, the preconditions listed for each specific exemption. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/23/2023
Number of Days to Update: 83

Source: State Water Resources Control Board
Telephone: 916-341-5810
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

CIWQS: California Integrated Water Quality System

The California Integrated Water Quality System (CIWQS) is a computer system used by the State and Regional Water Quality Control Boards to track information about places of environmental interest, manage permits and other orders, track inspections, and manage violations and enforcement activities.

Date of Government Version: 11/28/2022
Date Data Arrived at EDR: 11/29/2022
Date Made Active in Reports: 02/13/2023
Number of Days to Update: 76

Source: State Water Resources Control Board
Telephone: 866-794-4977
Last EDR Contact: 02/28/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Varies

CERS: CalEPA Regulated Site Portal Data

The CalEPA Regulated Site Portal database combines data about environmentally regulated sites and facilities in California into a single database. It combines data from a variety of state and federal databases, and provides an overview of regulated activities across the spectrum of environmental programs for any given location in California. These activities include hazardous materials and waste, state and federal cleanups, impacted ground and surface waters, and toxic materials

Date of Government Version: 01/05/2023
Date Data Arrived at EDR: 01/06/2023
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 4

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

NON-CASE INFO: Non-Case Information Sites (GEOTRACKER)

Non-Case Information sites

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

OTHER OIL GAS: Other Oil & Gas Projects Sites (GEOTRACKER)

Other Oil & Gas Projects sites

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

PROD WATER PONDS: Produced Water Ponds Sites (GEOTRACKER)
Produced water ponds sites

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

SAMPLING POINT: Sampling Point ? Public Sites (GEOTRACKER)
Sampling point - public sites

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

WELL STIM PROJ: Well Stimulation Project (GEOTRACKER)
Includes areas of groundwater monitoring plans, a depiction of the monitoring network, and the facilities, boundaries, and subsurface characteristics of the oilfield and the features (oil and gas wells, produced water ponds, UIC wells, water supply wells, etc?) being monitored

Date of Government Version: 12/02/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/21/2023
Number of Days to Update: 81
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Varies

PCS: Permit Compliance System
PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55
Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

HWTS: Hazardous Waste Tracking System
DTSC maintains the Hazardous Waste Tracking System that stores ID number information since the early 1980s and manifest data since 1993. The system collects both manifest copies from the generator and destination facility.

Date of Government Version: 04/05/2022
Date Data Arrived at EDR: 04/05/2022
Date Made Active in Reports: 04/26/2022
Number of Days to Update: 21
Source: Department of Toxic Substances Control
Telephone: 916-324-2444
Last EDR Contact: 01/03/2023
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 08/23/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 98
Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 02/24/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Varies

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Varies

PCS INACTIVE: Listing of Inactive PCS Permits
An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations
EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners
EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Department of Resources Recycling and Recovery
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

ALAMEDA COUNTY:

CS ALAMEDA: Contaminated Sites

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 01/09/2019
Date Data Arrived at EDR: 01/11/2019
Date Made Active in Reports: 03/05/2019
Number of Days to Update: 53

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

UST ALAMEDA: Underground Tanks

Underground storage tank sites located in Alameda county.

Date of Government Version: 09/28/2022
Date Data Arrived at EDR: 09/29/2022
Date Made Active in Reports: 12/14/2022
Number of Days to Update: 76

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA AMADOR: CUPA Facility List
Cupa Facility List

Date of Government Version: 07/22/2022
Date Data Arrived at EDR: 07/27/2022
Date Made Active in Reports: 08/01/2022
Number of Days to Update: 5

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA BUTTE: CUPA Facility Listing
Cupa facility list.

Date of Government Version: 04/21/2017
Date Data Arrived at EDR: 04/25/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 106

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA CALVERAS: CUPA Facility Listing
Cupa Facility Listing

Date of Government Version: 12/13/2022
Date Data Arrived at EDR: 12/15/2022
Date Made Active in Reports: 12/21/2022
Number of Days to Update: 6

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 12/13/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA COLUSA: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/06/2020
Date Data Arrived at EDR: 04/23/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 78

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Semi-Annually

CONTRA COSTA COUNTY:

SL CONTRA COSTA: Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 10/20/2022
Date Data Arrived at EDR: 10/21/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 81

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA DEL NORTE: CUPA Facility List
Cupa Facility list

Date of Government Version: 05/04/2022
Date Data Arrived at EDR: 05/06/2022
Date Made Active in Reports: 07/28/2022
Number of Days to Update: 83

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 02/03/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA EL DORADO: CUPA Facility List
CUPA facility list.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/09/2022
Date Made Active in Reports: 09/01/2022
Number of Days to Update: 23

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA FRESNO: CUPA Resources List
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 06/28/2021
Date Data Arrived at EDR: 12/21/2021
Date Made Active in Reports: 03/03/2022
Number of Days to Update: 72

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 12/29/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Semi-Annually

GLENN COUNTY:

CUPA GLENN: CUPA Facility List
Cupa facility list

Date of Government Version: 01/22/2018
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 03/14/2018
Number of Days to Update: 49

Source: Glenn County Air Pollution Control District
Telephone: 830-934-6500
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: No Update Planned

HUMBOLDT COUNTY:

CUPA HUMBOLDT: CUPA Facility List
CUPA facility list.

Date of Government Version: 08/12/2021
Date Data Arrived at EDR: 08/12/2021
Date Made Active in Reports: 11/08/2021
Number of Days to Update: 88

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Semi-Annually

IMPERIAL COUNTY:

CUPA IMPERIAL: CUPA Facility List
Cupa facility list.

Date of Government Version: 10/11/2022
Date Data Arrived at EDR: 10/12/2022
Date Made Active in Reports: 12/29/2022
Number of Days to Update: 78

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

INYO COUNTY:

CUPA INYO: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/03/2018
Date Made Active in Reports: 06/14/2018
Number of Days to Update: 72

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

KERN COUNTY:

CUPA KERN: CUPA Facility List
A listing of sites included in the Kern County Hazardous Material Business Plan.

Date of Government Version: 10/03/2022
Date Data Arrived at EDR: 10/05/2022
Date Made Active in Reports: 12/16/2022
Number of Days to Update: 72

Source: Kern County Public Health
Telephone: 661-321-3000
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

UST KERN: Underground Storage Tank Sites & Tank Listing
Kern County Sites and Tanks Listing.

Date of Government Version: 10/03/2022
Date Data Arrived at EDR: 10/05/2022
Date Made Active in Reports: 12/16/2022
Number of Days to Update: 72

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA KINGS: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 12/03/2020
Date Data Arrived at EDR: 01/26/2021
Date Made Active in Reports: 04/14/2021
Number of Days to Update: 78

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

LAKE COUNTY:

CUPA LAKE: CUPA Facility List
Cupa facility list

Date of Government Version: 11/04/2022
Date Data Arrived at EDR: 11/07/2022
Date Made Active in Reports: 01/25/2023
Number of Days to Update: 79

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 01/09/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

LASSEN COUNTY:

CUPA LASSEN: CUPA Facility List
Cupa facility list

Date of Government Version: 07/31/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 80

Source: Lassen County Environmental Health
Telephone: 530-251-8528
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

LOS ANGELES COUNTY:

AOCONCERN: Key Areas of Concerns in Los Angeles County
San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office. Date of Government Version: 3/30/2009 Exide Site area is a cleanup plan of lead-impacted soil surrounding the former Exide Facility as designated by the DTSC. Date of Government Version: 7/17/2017

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206

Source: N/A
Telephone: N/A
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 06/26/2023
Data Release Frequency: No Update Planned

HMS LOS ANGELES: HMS: Street Number List
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 10/03/2022
Date Data Arrived at EDR: 10/04/2022
Date Made Active in Reports: 12/15/2022
Number of Days to Update: 72

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Semi-Annually

LF LOS ANGELES: List of Solid Waste Facilities
Solid Waste Facilities in Los Angeles County.

Date of Government Version: 10/07/2022
Date Data Arrived at EDR: 10/07/2022
Date Made Active in Reports: 12/21/2022
Number of Days to Update: 75

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 01/10/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

LF LOS ANGELES CITY: City of Los Angeles Landfills
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 01/21/2022
Date Made Active in Reports: 04/11/2022
Number of Days to Update: 80

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

LOS ANGELES AST: Active & Inactive AST Inventory
A listing of active & inactive above ground petroleum storage tank site locations, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/13/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Varies

LOS ANGELES CO LF METHANE: Methane Producing Landfills
This data was created on April 30, 2012 to represent known disposal sites in Los Angeles County that may produce and emanate methane gas. The shapefile contains disposal sites within Los Angeles County that once accepted degradable refuse material. Information used to create this data was extracted from a landfill survey performed by County Engineers (Major Waste System Map, 1973) as well as historical records from CalRecycle, Regional Water Quality Control Board, and Los Angeles County Department of Public Health

Date of Government Version: 01/10/2022
Date Data Arrived at EDR: 01/12/2022
Date Made Active in Reports: 04/04/2022
Number of Days to Update: 82
Source: Los Angeles County Department of Public Works
Telephone: 626-458-6973
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: No Update Planned

LOS ANGELES HM: Active & Inactive Hazardous Materials Inventory
A listing of active & inactive hazardous materials facility locations, located in the City of Los Angeles.

Date of Government Version: 11/01/2022
Date Data Arrived at EDR: 12/14/2022
Date Made Active in Reports: 03/07/2023
Number of Days to Update: 83
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Varies

LOS ANGELES UST: Active & Inactive UST Inventory
A listing of active & inactive underground storage tank site locations and underground storage tank historical sites, located in the City of Los Angeles.

Date of Government Version: 11/01/2022
Date Data Arrived at EDR: 12/14/2022
Date Made Active in Reports: 03/07/2023
Number of Days to Update: 83
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/14/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Varies

SITE MIT LOS ANGELES: Site Mitigation List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 05/26/2021
Date Data Arrived at EDR: 07/09/2021
Date Made Active in Reports: 09/29/2021
Number of Days to Update: 82
Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Annually

UST EL SEGUNDO: City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/10/2017
Number of Days to Update: 21
Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 01/05/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: No Update Planned

UST LONG BEACH: City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 04/22/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/27/2019
Number of Days to Update: 65

Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

UST TORRANCE: City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 10/18/2022
Date Data Arrived at EDR: 10/19/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 83

Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA MADERA: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 72

Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

MARIN COUNTY:

UST MARIN: Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 09/26/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/02/2018
Number of Days to Update: 29

Source: Public Works Department Waste Management
Telephone: 415-473-6647
Last EDR Contact: 12/19/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Semi-Annually

MENDOCINO COUNTY:

UST MENDOCINO: Mendocino County UST Database
A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 09/22/2021
Date Data Arrived at EDR: 11/18/2021
Date Made Active in Reports: 11/22/2021
Number of Days to Update: 4

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 02/15/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Annually

MERCED COUNTY:

CUPA MERCED: CUPA Facility List
CUPA facility list.

Date of Government Version: 02/15/2022
Date Data Arrived at EDR: 02/17/2022
Date Made Active in Reports: 05/11/2022
Number of Days to Update: 83

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 01/31/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

MONO COUNTY:

CUPA MONO: CUPA Facility List
CUPA Facility List

Date of Government Version: 02/22/2021
Date Data Arrived at EDR: 03/02/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 78

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 02/15/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA MONTEREY: CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 10/04/2021
Date Data Arrived at EDR: 10/06/2021
Date Made Active in Reports: 12/29/2021
Number of Days to Update: 84

Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 02/03/2023
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Varies

NAPA COUNTY:

LUST NAPA: Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 03/02/2017
Number of Days to Update: 50

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 02/15/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: No Update Planned

UST NAPA: Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 09/05/2019
Date Data Arrived at EDR: 09/09/2019
Date Made Active in Reports: 10/31/2019
Number of Days to Update: 52

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 02/15/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA NEVADA: CUPA Facility List
CUPA facility list.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 10/27/2022
Date Made Active in Reports: 01/18/2023
Number of Days to Update: 83

Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Varies

ORANGE COUNTY:

IND_SITE ORANGE: List of Industrial Site Cleanups
Petroleum and non-petroleum spills.

Date of Government Version: 05/24/2022
Date Data Arrived at EDR: 08/09/2022
Date Made Active in Reports: 10/28/2022
Number of Days to Update: 80

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 01/31/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Annually

LUST ORANGE: List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 04/08/2022
Date Data Arrived at EDR: 05/18/2022
Date Made Active in Reports: 08/03/2022
Number of Days to Update: 77

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 01/31/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Quarterly

UST ORANGE: List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 05/24/2022
Date Data Arrived at EDR: 08/01/2022
Date Made Active in Reports: 10/20/2022
Number of Days to Update: 80

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 01/31/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Quarterly

PLACER COUNTY:

MS PLACER: Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 08/26/2022
Date Data Arrived at EDR: 08/29/2022
Date Made Active in Reports: 11/15/2022
Number of Days to Update: 78

Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 02/13/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Semi-Annually

PLUMAS COUNTY:

CUPA PLUMAS: CUPA Facility List
Plumas County CUPA Program facilities.

Date of Government Version: 03/31/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/26/2019
Number of Days to Update: 64

Source: Plumas County Environmental Health
Telephone: 530-283-6355
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

RIVERSIDE COUNTY:

LUST RIVERSIDE: Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 09/22/2022
Date Data Arrived at EDR: 09/26/2022
Date Made Active in Reports: 12/09/2022
Number of Days to Update: 74

Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 06/26/2023
Data Release Frequency: Quarterly

UST RIVERSIDE: Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 09/22/2022
Date Data Arrived at EDR: 09/26/2022
Date Made Active in Reports: 12/09/2022
Number of Days to Update: 74

Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 06/26/2023
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

CS SACRAMENTO: Toxic Site Clean-Up List
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 06/18/2021
Date Data Arrived at EDR: 09/28/2021
Date Made Active in Reports: 12/14/2021
Number of Days to Update: 77

Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 12/21/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

ML SACRAMENTO: Master Hazardous Materials Facility List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 11/07/2022
Date Data Arrived at EDR: 12/09/2022
Date Made Active in Reports: 03/01/2023
Number of Days to Update: 82

Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 12/09/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Quarterly

SAN BENITO COUNTY:

CUPA SAN BENITO: CUPA Facility List
Cupa facility list

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 10/28/2022
Date Made Active in Reports: 01/18/2023
Number of Days to Update: 82

Source: San Benito County Environmental Health
Telephone: N/A
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

SAN BERNARDINO COUNTY:

PERMITS SAN BERNARDINO: Hazardous Material Permits
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 11/18/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 80

Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 01/30/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

HMMD SAN DIEGO: Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 11/28/2022
Date Data Arrived at EDR: 11/29/2022
Date Made Active in Reports: 02/14/2023
Number of Days to Update: 77

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 02/28/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Quarterly

LF SAN DIEGO: Solid Waste Facilities

San Diego County Solid Waste Facilities.

Date of Government Version: 10/27/2021
Date Data Arrived at EDR: 03/04/2022
Date Made Active in Reports: 05/31/2022
Number of Days to Update: 88

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

SAN DIEGO CO LOP: Local Oversight Program Listing

A listing of all LOP release sites that are or were under the County of San Diego's jurisdiction. Included are closed or transferred cases, open cases, and cases that did not have a case type indicated. The cases without a case type are mostly complaints; however, some of them could be LOP cases.

Date of Government Version: 07/22/2021
Date Data Arrived at EDR: 10/19/2021
Date Made Active in Reports: 01/13/2022
Number of Days to Update: 86

Source: Department of Environmental Health
Telephone: 858-505-6874
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

SAN DIEGO CO SAM: Environmental Case Listing

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24

Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 02/23/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

CUPA SAN FRANCISCO CO: CUPA Facility Listing

Cupa facilities

Date of Government Version: 11/03/2022
Date Data Arrived at EDR: 11/07/2022
Date Made Active in Reports: 01/25/2023
Number of Days to Update: 79

Source: San Francisco County Department of Environmental Health
Telephone: 415-252-3896
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

LUST SAN FRANCISCO: Local Oversite Facilities
A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10

Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: No Update Planned

UST SAN FRANCISCO: Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 11/03/2022
Date Data Arrived at EDR: 11/07/2022
Date Made Active in Reports: 01/24/2023
Number of Days to Update: 78

Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Quarterly

SAN FRANCISO COUNTY:

SAN FRANCISCO MAHER: Maher Ordinance Property Listing
a listing of properties that fall within a Maher Ordinance, for all of San Francisco

Date of Government Version: 10/11/2022
Date Data Arrived at EDR: 10/14/2022
Date Made Active in Reports: 01/04/2023
Number of Days to Update: 82

Source: San Francisco Planning
Telephone: 628-652-7483
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

SAN JOAQUIN COUNTY:

UST SAN JOAQUIN: San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 06/22/2018
Date Data Arrived at EDR: 06/26/2018
Date Made Active in Reports: 07/11/2018
Number of Days to Update: 15

Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 03/09/2023
Next Scheduled EDR Contact: 06/26/2023
Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA SAN LUIS OBISPO: CUPA Facility List
Cupa Facility List.

Date of Government Version: 11/08/2022
Date Data Arrived at EDR: 11/09/2022
Date Made Active in Reports: 02/01/2023
Number of Days to Update: 84

Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

SAN MATEO COUNTY:

BI SAN MATEO: Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 02/20/2020
Date Data Arrived at EDR: 02/20/2020
Date Made Active in Reports: 04/24/2020
Number of Days to Update: 64
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 03/10/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Annually

LUST SAN MATEO: Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/29/2019
Date Data Arrived at EDR: 03/29/2019
Date Made Active in Reports: 05/29/2019
Number of Days to Update: 61
Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 03/02/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA SANTA BARBARA: CUPA Facility Listing
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28
Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: No Update Planned

SANTA CLARA COUNTY:

CUPA SANTA CLARA: Cupa Facility List
Cupa facility list

Date of Government Version: 10/28/2022
Date Data Arrived at EDR: 11/01/2022
Date Made Active in Reports: 01/20/2023
Number of Days to Update: 80
Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

HIST LUST SANTA CLARA: HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22
Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LUST SANTA CLARA: LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014
Date Data Arrived at EDR: 03/05/2014
Date Made Active in Reports: 03/18/2014
Number of Days to Update: 13
Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 02/15/2023
Next Scheduled EDR Contact: 06/05/2023
Data Release Frequency: No Update Planned

SAN JOSE HAZMAT: Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 11/03/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 82

Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Annually

SANTA CRUZ COUNTY:

CUPA SANTA CRUZ: CUPA Facility List
CUPA facility listing.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 05/23/2017
Number of Days to Update: 90

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA SHASTA: CUPA Facility List
Cupa Facility List.

Date of Government Version: 06/15/2017
Date Data Arrived at EDR: 06/19/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 51

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 02/09/2023
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Varies

SOLANO COUNTY:

LUST SOLANO: Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 06/04/2019
Date Data Arrived at EDR: 06/06/2019
Date Made Active in Reports: 08/13/2019
Number of Days to Update: 68

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 02/23/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Quarterly

UST SOLANO: Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 09/15/2021
Date Data Arrived at EDR: 09/16/2021
Date Made Active in Reports: 12/09/2021
Number of Days to Update: 84

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 02/23/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Quarterly

SONOMA COUNTY:

CUPA SONOMA: Cupa Facility List
Cupa Facility list

Date of Government Version: 07/02/2021
Date Data Arrived at EDR: 07/06/2021
Date Made Active in Reports: 07/14/2021
Number of Days to Update: 8

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 12/13/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Varies

LUST SONOMA: Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 06/30/2021
Date Data Arrived at EDR: 06/30/2021
Date Made Active in Reports: 09/24/2021
Number of Days to Update: 86

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 12/13/2022
Next Scheduled EDR Contact: 04/03/2023
Data Release Frequency: Quarterly

STANISLAUS COUNTY:

CUPA STANISLAUS: CUPA Facility List
Cupa facility list

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/10/2022
Date Made Active in Reports: 05/04/2022
Number of Days to Update: 83

Source: Stanislaus County Department of Ennvironmental Protection
Telephone: 209-525-6751
Last EDR Contact: 01/09/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Varies

SUTTER COUNTY:

UST SUTTER: Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 08/03/2022
Date Data Arrived at EDR: 08/25/2022
Date Made Active in Reports: 11/14/2022
Number of Days to Update: 81

Source: Sutter County Environmental Health Services
Telephone: 530-822-7500
Last EDR Contact: 02/23/2023
Next Scheduled EDR Contact: 06/12/2023
Data Release Frequency: Semi-Annually

TEHAMA COUNTY:

CUPA TEHAMA: CUPA Facility List
Cupa facilities

Date of Government Version: 11/17/2022
Date Data Arrived at EDR: 11/21/2022
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 81

Source: Tehama County Department of Environmental Health
Telephone: 530-527-8020
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

TRINITY COUNTY:

CUPA TRINITY: CUPA Facility List
Cupa facility list

Date of Government Version: 10/11/2022
Date Data Arrived at EDR: 10/12/2022
Date Made Active in Reports: 12/29/2022
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 760-352-0381
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

TULARE COUNTY:

CUPA TULARE: CUPA Facility List
Cupa program facilities

Date of Government Version: 10/07/2022
Date Data Arrived at EDR: 10/07/2022
Date Made Active in Reports: 12/21/2022
Number of Days to Update: 75

Source: Tulare County Environmental Health Services Division
Telephone: 559-624-7400
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/15/2023
Data Release Frequency: Varies

TUOLUMNE COUNTY:

CUPA TUOLUMNE: CUPA Facility List
Cupa facility list

Date of Government Version: 04/23/2018
Date Data Arrived at EDR: 04/25/2018
Date Made Active in Reports: 06/25/2018
Number of Days to Update: 61

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 01/13/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Varies

VENTURA COUNTY:

BWT VENTURA: Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 09/26/2022
Date Data Arrived at EDR: 10/19/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 83

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Quarterly

LF VENTURA: Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 12/19/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: No Update Planned

LUST VENTURA: Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37

Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 02/02/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: No Update Planned

MED WASTE VENTURA: Medical Waste Program List
To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 09/26/2022
Date Data Arrived at EDR: 10/20/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 82

Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 01/17/2023
Next Scheduled EDR Contact: 05/01/2023
Data Release Frequency: Quarterly

UST VENTURA: Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 11/28/2022
Date Data Arrived at EDR: 12/02/2022
Date Made Active in Reports: 02/23/2023
Number of Days to Update: 83
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 03/07/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Quarterly

YOLO COUNTY:

UST YOLO: Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 09/21/2022
Date Data Arrived at EDR: 09/30/2022
Date Made Active in Reports: 12/14/2022
Number of Days to Update: 75
Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 12/19/2022
Next Scheduled EDR Contact: 04/10/2023
Data Release Frequency: Annually

YUBA COUNTY:

CUPA YUBA: CUPA Facility List
CUPA facility listing for Yuba County.

Date of Government Version: 10/25/2022
Date Data Arrived at EDR: 10/26/2022
Date Made Active in Reports: 10/31/2022
Number of Days to Update: 5
Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 01/20/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/16/2022
Date Data Arrived at EDR: 11/16/2022
Date Made Active in Reports: 02/06/2023
Number of Days to Update: 82
Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/10/2023
Next Scheduled EDR Contact: 05/22/2023
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36
Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 12/28/2022
Next Scheduled EDR Contact: 04/17/2023
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/27/2023
Next Scheduled EDR Contact: 05/08/2023
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/06/2023
Next Scheduled EDR Contact: 04/24/2023
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/13/2022
Next Scheduled EDR Contact: 05/29/2023
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/06/2023
Next Scheduled EDR Contact: 06/19/2023
Data Release Frequency: Annually

Oil/Gas Pipelines

Source: Endeavor Business Media

Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data

Source: Endeavor Business Media

This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.
Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.
Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.
Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.
Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

LA MESA PARK SITE
7410 WAITE DRIVE
LA MESA, CA 91941

TARGET PROPERTY COORDINATES

Latitude (North):	32.746893 - 32ˆ 44’ 48.81’’
Longitude (West):	117.038301 - 117ˆ 2’ 17.88’’
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	496411.8
UTM Y (Meters):	3623038.5
Elevation:	471 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	11993860 NATIONAL CITY, CA
Version Date:	2018
North Map:	11993858 LA MESA, CA
Version Date:	2018

EDR’s GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
06073C1910G	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
06073C1643J	FEMA FIRM Flood data
06073C1644H	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
NATIONAL CITY	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
F40	1/4 - 1/2 Mile SE	WSW
L106	1/2 - 1 Mile ESE	SW
1G	1/4 - 1/2 Mile SE	WSW
2G	1/2 - 1 Mile ESE	SW

For additional site information, refer to Physical Setting Source Map Findings.

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Mesozoic
System:	Lower Jurassic and Upper Triassic
Series:	Lower Mesozoic
Code:	lMze *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Eugeosynclinal Deposits

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 7276918.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	LA Mesa Park Site	CLIENT:	Bodhi Group
ADDRESS:	7410 Waite Drive LA Mesa CA 91941	CONTACT:	Natalie Krage
		INQUIRY #:	7276918.2s
LAT/LONG:	32.746893 / 117.038301	DATE:	March 13, 2023 8:40 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: REDDING

Soil Surface Texture: gravelly loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	14 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: Min:	Max: Min:
2	14 inches	29 inches	gravelly clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: Min:	Max: Min:
3	29 inches	44 inches	indurated	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: Min:	Max: Min:

Soil Map ID: 2

Soil Component Name: FRIANT

Soil Surface Texture: fine sandy loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 30 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: Min:	Max: Min:
2	3 inches	11 inches	sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: Min:	Max: Min:
3	11 inches	16 inches	unweathered bedrock	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: Min:	Max: Min:

Soil Map ID: 3

Soil Component Name: OLIVENHAIN

Soil Surface Texture: cobbly loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	9 inches	cobbly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14 Min: 4	Max: 5.5 Min: 5.1
2	9 inches	42 inches	very cobbly clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14 Min: 4	Max: 5.5 Min: 5.1
3	42 inches	59 inches	cobbly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14 Min: 4	Max: 5.5 Min: 5.1

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
P124	USGS40000129682	1/2 - 1 Mile SW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	CAEDF0000078518	0 - 1/8 Mile South
A2	CAEDF0000032094	0 - 1/8 Mile South
A3	CAEDF0000059750	0 - 1/8 Mile SSW
A4	CAEDF0000022386	0 - 1/8 Mile SSW
A5	CAEDF0000075549	0 - 1/8 Mile SSW
A6	CAEDF0000131916	0 - 1/8 Mile SSW
A7	CAEDF0000109859	0 - 1/8 Mile SSW
B8	CAEDF0000081004	1/8 - 1/4 Mile WSW
B9	CAEDF0000138951	1/8 - 1/4 Mile West
B10	CAEDF0000133320	1/8 - 1/4 Mile WSW
B11	CAEDF0000103498	1/8 - 1/4 Mile WSW
B12	CAEDF0000080353	1/8 - 1/4 Mile WSW
B13	CAEDF0000015696	1/8 - 1/4 Mile West
B14	CAEDF0000106311	1/4 - 1/2 Mile WSW
B15	CAEDF0000062687	1/4 - 1/2 Mile WSW
B16	CAEDF0000141257	1/4 - 1/2 Mile WSW
B17	CAEDF0000065066	1/4 - 1/2 Mile WSW
C18	CAEDF0000086772	1/4 - 1/2 Mile West
B19	CAEDF0000083014	1/4 - 1/2 Mile WSW
C20	CAEDF0000023384	1/4 - 1/2 Mile West
C21	CAEDF0000119337	1/4 - 1/2 Mile West
C22	CAEDF0000116988	1/4 - 1/2 Mile West
C23	CAEDF0000131614	1/4 - 1/2 Mile West
C24	CAEDF0000015190	1/4 - 1/2 Mile West
C25	CAEDF0000104990	1/4 - 1/2 Mile West
C26	CAEDF0000124362	1/4 - 1/2 Mile West
C27	CAEDF0000121488	1/4 - 1/2 Mile West
D28	CAEDF0000091120	1/4 - 1/2 Mile SSE
D29	CAEDF0000047678	1/4 - 1/2 Mile SSE
E30	CAEDF0000125532	1/4 - 1/2 Mile WSW
D31	CAEDF0000112170	1/4 - 1/2 Mile SSE
D32	CAEDF0000072741	1/4 - 1/2 Mile SSE
D33	CAEDF0000011893	1/4 - 1/2 Mile SSE
E34	CAEDF0000141135	1/4 - 1/2 Mile SW
D35	CAEDF0000037393	1/4 - 1/2 Mile SSE
D36	CAEDF0000106913	1/4 - 1/2 Mile SSE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
D37	CAEDF0000081930	1/4 - 1/2 Mile SSE
D38	CAEDF0000126173	1/4 - 1/2 Mile SSE
D39	CAEDF0000090074	1/4 - 1/2 Mile SSE
D41	CAEDF0000000941	1/4 - 1/2 Mile SSE
G42	CAEDF0000084314	1/4 - 1/2 Mile SW
F43	CAEDF0000118496	1/4 - 1/2 Mile SE
G44	CAEDF0000127978	1/4 - 1/2 Mile SW
G45	CAEDF0000087092	1/4 - 1/2 Mile SW
G46	CAEDF0000012626	1/4 - 1/2 Mile SW
G47	CAEDF0000001196	1/4 - 1/2 Mile SW
G48	CAEDF0000054056	1/4 - 1/2 Mile SW
F49	CAEDF0000087648	1/4 - 1/2 Mile SE
F50	CAEDF0000099553	1/4 - 1/2 Mile SE
F51	CAEDF0000018506	1/4 - 1/2 Mile SE
G52	CAEDF0000058037	1/4 - 1/2 Mile SW
G53	CAEDF0000134631	1/4 - 1/2 Mile SW
G54	CAEDF0000080219	1/4 - 1/2 Mile SW
F55	CAEDF0000017115	1/4 - 1/2 Mile SE
F56	CAEDF0000090137	1/4 - 1/2 Mile SE
F57	CAEDF0000101830	1/4 - 1/2 Mile SE
G58	CAEDF0000052401	1/4 - 1/2 Mile SW
G59	CAEDF0000114873	1/4 - 1/2 Mile SW
H60	CAEDF0000102006	1/4 - 1/2 Mile SE
H61	CAEDF0000115939	1/4 - 1/2 Mile ESE
G62	CAEDF0000089987	1/4 - 1/2 Mile SW
H63	CAEDF0000050648	1/4 - 1/2 Mile ESE
G64	CAEDF0000083821	1/4 - 1/2 Mile SW
H65	CAEDF0000088969	1/4 - 1/2 Mile ESE
H66	CAEDF0000085035	1/4 - 1/2 Mile ESE
G67	CAEDF0000014717	1/4 - 1/2 Mile SW
H68	CAEDF0000131440	1/4 - 1/2 Mile ESE
G69	CAEDF0000004239	1/4 - 1/2 Mile SW
G70	CAEDF0000021458	1/4 - 1/2 Mile SW
G71	CAEDF0000076404	1/4 - 1/2 Mile SW
G72	CAEDF0000040333	1/4 - 1/2 Mile SW
H73	CAEDF0000070912	1/4 - 1/2 Mile ESE
G74	CAEDF0000057713	1/4 - 1/2 Mile SW
G75	CAEDF0000083525	1/4 - 1/2 Mile SW
I76	CAEDF0000015673	1/2 - 1 Mile SW
I77	CAEDF0000075006	1/2 - 1 Mile SW
I78	CAEDF0000021155	1/2 - 1 Mile SW
I79	CAEDF0000035771	1/2 - 1 Mile SW
J80	CAEDF0000051536	1/2 - 1 Mile ESE
J81	CAEDF0000066038	1/2 - 1 Mile ESE
J82	CAEDF0000004537	1/2 - 1 Mile ESE
J83	CAEDF0000090866	1/2 - 1 Mile ESE
J84	CAEDF0000102026	1/2 - 1 Mile ESE
J85	CAEDF0000084469	1/2 - 1 Mile ESE
J86	CAEDF0000065014	1/2 - 1 Mile ESE
J87	CAEDF0000021469	1/2 - 1 Mile ESE
J88	CAEDF0000128875	1/2 - 1 Mile ESE
K89	CAEDF0000113311	1/2 - 1 Mile SE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
J90	CAEDF0000061458	1/2 - 1 Mile ESE
K91	CAEDF0000057718	1/2 - 1 Mile ESE
J92	CAEDF0000124975	1/2 - 1 Mile ESE
J93	CAEDF0000127861	1/2 - 1 Mile ESE
J94	CAEDF0000100616	1/2 - 1 Mile ESE
J95	CAEDF0000010390	1/2 - 1 Mile ESE
J96	CAEDF0000094567	1/2 - 1 Mile ESE
K97	CAEDF0000063670	1/2 - 1 Mile ESE
L98	CAEDF0000132275	1/2 - 1 Mile ESE
L99	CAEDF0000135294	1/2 - 1 Mile ESE
M100	CAEDF0000132934	1/2 - 1 Mile SE
L101	CAEDF0000038882	1/2 - 1 Mile ESE
L102	CAEDF0000085686	1/2 - 1 Mile ESE
L103	CAEDF0000097211	1/2 - 1 Mile ESE
L104	CAEDF0000018015	1/2 - 1 Mile ESE
L105	CAEDF0000123332	1/2 - 1 Mile ESE
M107	CAEDF0000010320	1/2 - 1 Mile SE
L108	CAEDF0000047781	1/2 - 1 Mile ESE
L109	CAEDF0000130989	1/2 - 1 Mile ESE
M110	CAEDF0000095753	1/2 - 1 Mile SE
L111	CAEDF0000012361	1/2 - 1 Mile ESE
L112	CAEDF0000093037	1/2 - 1 Mile ESE
L113	CAEDF0000058634	1/2 - 1 Mile ESE
N114	CAEDF0000059640	1/2 - 1 Mile ESE
L115	CAEDF0000143183	1/2 - 1 Mile ESE
L116	CAEDF0000082671	1/2 - 1 Mile ESE
O117	CAEDF0000047057	1/2 - 1 Mile ESE
O118	CAEDF0000099195	1/2 - 1 Mile ESE
O119	CAEDF0000052075	1/2 - 1 Mile ESE
L120	CAEDF0000073911	1/2 - 1 Mile ESE
O121	CAEDF0000142896	1/2 - 1 Mile ESE
O122	CAEDF0000112685	1/2 - 1 Mile ESE
O123	CAEDF0000102567	1/2 - 1 Mile ESE
L125	CAEDF0000118690	1/2 - 1 Mile ESE
O126	CAEDF0000089204	1/2 - 1 Mile ESE
O127	CAEDF0000094862	1/2 - 1 Mile ESE
O128	CAEDF0000139187	1/2 - 1 Mile ESE
O129	CAEDF0000141554	1/2 - 1 Mile ESE
O130	CAEDF0000131912	1/2 - 1 Mile ESE
O131	CAEDF0000068492	1/2 - 1 Mile ESE
O132	CAEDF0000006358	1/2 - 1 Mile ESE
O133	CAEDF0000099403	1/2 - 1 Mile ESE
O134	CAEDF0000117206	1/2 - 1 Mile ESE
O135	CAEDF0000097161	1/2 - 1 Mile ESE
O136	CAEDF0000065095	1/2 - 1 Mile ESE
O137	CAEDF0000090257	1/2 - 1 Mile ESE
O138	CAEDF0000021303	1/2 - 1 Mile ESE
O139	CAEDF0000000746	1/2 - 1 Mile ESE
O140	CAEDF0000066244	1/2 - 1 Mile ESE
P141	CADWR9000000264	1/2 - 1 Mile SW
O142	CAEDF0000051765	1/2 - 1 Mile ESE
O143	CAEDF0000053337	1/2 - 1 Mile ESE

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
O144	CAEDF0000112521	1/2 - 1 Mile ESE
O145	CAEDF0000138472	1/2 - 1 Mile ESE
O146	CAEDF0000095254	1/2 - 1 Mile ESE
O147	CAEDF0000023827	1/2 - 1 Mile ESE
O148	CAEDF0000007839	1/2 - 1 Mile ESE
O149	CAEDF0000006838	1/2 - 1 Mile ESE
O150	CAEDF0000141153	1/2 - 1 Mile ESE
O151	CAEDF0000137229	1/2 - 1 Mile ESE
O152	CAEDF0000049787	1/2 - 1 Mile ESE
Q153	CAEDF0000116718	1/2 - 1 Mile ESE
O154	CAEDF0000140091	1/2 - 1 Mile ESE
O155	CAEDF0000096016	1/2 - 1 Mile ESE
N156	CAEDF0000110722	1/2 - 1 Mile ESE
O157	CAEDF0000101247	1/2 - 1 Mile ESE
O158	CAEDF0000063508	1/2 - 1 Mile ESE
O159	CAEDF0000033605	1/2 - 1 Mile ESE
Q160	CAEDF0000098018	1/2 - 1 Mile ESE
O161	CAEDF0000065227	1/2 - 1 Mile ESE
O162	CAEDF0000087836	1/2 - 1 Mile ESE
O163	CAEDF0000130027	1/2 - 1 Mile ESE
O164	CAEDF0000109636	1/2 - 1 Mile ESE
O165	CAEDF0000088377	1/2 - 1 Mile ESE
O166	CAEDF0000133460	1/2 - 1 Mile ESE
Q167	CAEDF0000126528	1/2 - 1 Mile ESE
O168	CAEDF0000020794	1/2 - 1 Mile ESE
O169	CAEDF0000046814	1/2 - 1 Mile ESE
Q170	CAEDF0000080131	1/2 - 1 Mile ESE
Q171	CAEDF0000047477	1/2 - 1 Mile ESE
Q172	CAEDF0000067017	1/2 - 1 Mile ESE
O173	CAEDF0000070256	1/2 - 1 Mile ESE
O174	CAEDF0000140592	1/2 - 1 Mile ESE
Q175	CAEDF0000005441	1/2 - 1 Mile ESE
O176	CAEDF0000105426	1/2 - 1 Mile ESE
Q177	CAEDF0000104576	1/2 - 1 Mile ESE
Q178	CAEDF0000076022	1/2 - 1 Mile ESE
Q179	CAEDF0000018416	1/2 - 1 Mile ESE
O180	CAEDF0000036233	1/2 - 1 Mile ESE
O181	CAEDF0000002536	1/2 - 1 Mile ESE
Q182	CAEDF0000007736	1/2 - 1 Mile ESE
Q183	CAEDF0000136472	1/2 - 1 Mile ESE
Q184	CAEDF0000134665	1/2 - 1 Mile ESE
Q185	CAEDF0000115673	1/2 - 1 Mile ESE
Q186	CAEDF0000129180	1/2 - 1 Mile ESE
Q187	CAEDF0000131339	1/2 - 1 Mile ESE
Q188	CAEDF0000040110	1/2 - 1 Mile ESE
Q189	CAEDF0000036772	1/2 - 1 Mile ESE
190	CAEDF0000012749	1/2 - 1 Mile ESE
R191	CAEDF0000063188	1/2 - 1 Mile SSE
R192	CAEDF0000064180	1/2 - 1 Mile SSE
R193	CAEDF0000036181	1/2 - 1 Mile SSE
R194	CAEDF0000005886	1/2 - 1 Mile SSE
R195	CAEDF0000000602	1/2 - 1 Mile SSE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
R196	CAEDF0000117872	1/2 - 1 Mile SSE
R197	CAEDF0000079426	1/2 - 1 Mile SSE
R198	CAEDF0000020141	1/2 - 1 Mile SSE
S199	CAEDF0000129474	1/2 - 1 Mile NNE
S200	CAEDF0000004320	1/2 - 1 Mile NNE
S201	CAEDF0000078646	1/2 - 1 Mile NNE
S202	CAEDF0000074433	1/2 - 1 Mile NNE
S203	CAEDF0000138917	1/2 - 1 Mile NNE
S204	CAEDF0000020173	1/2 - 1 Mile NNE
S205	CAEDF0000135090	1/2 - 1 Mile NNE

PHYSICAL SETTING SOURCE MAP - 7276918.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	LA Mesa Park Site	CLIENT:	Bodhi Group
ADDRESS:	7410 Waite Drive LA Mesa CA 91941	CONTACT:	Natalie Krage
LAT/LONG:	32.746893 / 117.038301	INQUIRY #:	7276918.2s
		DATE:	March 13, 2023 8:40 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
South
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000078518**

Well ID:	T0607301436-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301436&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301436&assigned_name=MW-2		

A2
South
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000032094**

Well ID:	T0607301436-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301436&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301436&assigned_name=MW-6		

A3
SSW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000059750**

Well ID:	T0607301436-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301436&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301436&assigned_name=MW-1		

A4
SSW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000022386**

Well ID:	T0607301436-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301436&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301436&assigned_name=MW-7		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A5
SSW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000075549**

Well ID:	T0607301436-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301436&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301436&assigned_name=MW-3		

A6
SSW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000131916**

Well ID:	T0607301436-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301436&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301436&assigned_name=MW-4		

A7
SSW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000109859**

Well ID:	T0607301436-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301436&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301436&assigned_name=MW-5		

B8
WSW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000081004**

Well ID:	T0607302300-E-13	Well Type:	MONITORING
Source:	EDF	Other Name:	E-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-13		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B9
West
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000138951**

Well ID:	T0607302300-E-12	Well Type:	MONITORING
Source:	EDF	Other Name:	E-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-12		

B10
WSW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000133320**

Well ID:	T0607302300-E-2	Well Type:	MONITORING
Source:	EDF	Other Name:	E-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-2		

B11
WSW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000103498**

Well ID:	T0607302300-E-3	Well Type:	MONITORING
Source:	EDF	Other Name:	E-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-3		

B12
WSW
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000080353**

Well ID:	T0607302300-E-1	Well Type:	MONITORING
Source:	EDF	Other Name:	E-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-1		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B13
West
1/8 - 1/4 Mile
Lower

CA WELLS **CAEDF0000015696**

Well ID:	T0607302300-E-11	Well Type:	MONITORING
Source:	EDF	Other Name:	E-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-11		

B14
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000106311**

Well ID:	T0607302300-E-5	Well Type:	MONITORING
Source:	EDF	Other Name:	E-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-5		

B15
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000062687**

Well ID:	T0607302300-E-7	Well Type:	MONITORING
Source:	EDF	Other Name:	E-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-7		

B16
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000141257**

Well ID:	T0607302300-E-6	Well Type:	MONITORING
Source:	EDF	Other Name:	E-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B17
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000065066**

Well ID:	T0607302300-E-4	Well Type:	MONITORING
Source:	EDF	Other Name:	E-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-4		

C18
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000086772**

Well ID:	T0607338887-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-3		

B19
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000083014**

Well ID:	T0607302300-E-8	Well Type:	MONITORING
Source:	EDF	Other Name:	E-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-8		

C20
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000023384**

Well ID:	T0607338887-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C21
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000119337**

Well ID:	T0607338887-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-4		

C22
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000116988**

Well ID:	T0607338887-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-1		

C23
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000131614**

Well ID:	T0607338887-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-7		

C24
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000015190**

Well ID:	T0607338887-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C25
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000104990**

Well ID:	T0607338887-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-8		

C26
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000124362**

Well ID:	T0607338887-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-5		

C27
West
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000121488**

Well ID:	T0607338887-MW-9	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607338887&assigned_name=MW-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607338887&assigned_name=MW-9		

D28
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000091120**

Well ID:	T0607300209-MW-10-P	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10-P
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-10-P&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-10-P		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D29
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000047678**

Well ID:	T0607300209-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-3		

E30
WSW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000125532**

Well ID:	T0607302300-E-15	Well Type:	MONITORING
Source:	EDF	Other Name:	E-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-15		

D31
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000112170**

Well ID:	T0607300209-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-2		

D32
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000072741**

Well ID:	T0607300209-MW-20	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-20
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-20&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-20		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D33
SSE **CA WELLS** **CAEDF0000011893**
1/4 - 1/2 Mile
Lower

Well ID:	T0607300209-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-7		

E34
SW **CA WELLS** **CAEDF0000141135**
1/4 - 1/2 Mile
Lower

Well ID:	T0607302300-E-16	Well Type:	MONITORING
Source:	EDF	Other Name:	E-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302300&assigned_name=E-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302300&assigned_name=E-16		

D35
SSE **CA WELLS** **CAEDF0000037393**
1/4 - 1/2 Mile
Lower

Well ID:	T0607300209-MW-11-P	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11-P
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-11-P&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-11-P		

D36
SSE **CA WELLS** **CAEDF0000106913**
1/4 - 1/2 Mile
Lower

Well ID:	T0607300209-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

D37
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000081930**

Well ID:	T0607300209-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-1		

D38
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000126173**

Well ID:	T0607300209-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-4		

D39
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000090074**

Well ID:	T0607300209-MW-9-P	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-9-P
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-9-P&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-9-P		

F40
SE
1/4 - 1/2 Mile
Lower

AQUIFLOW **55092**

Site ID:	Not Reported
Groundwater Flow:	WSW
Shallow Water Depth:	Not Reported
Deep Water Depth:	Not Reported
Average Water Depth:	5.5
Date:	11/16/1989

D41
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000000941**

Well ID:	T0607300209-MW-12-P	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12-P

GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300209&assigned_name=MW-12-P&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300209&assigned_name=MW-12-P

G42
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000084314**

Well ID: T0608127577-MW-10 Well Type: MONITORING
Source: EDF Other Name: MW-10
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-10&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-10

F43
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000118496**

Well ID: T0607391309-MW-5 Well Type: MONITORING
Source: EDF Other Name: MW-5
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391309&assigned_name=MW-5&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391309&assigned_name=MW-5

G44
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000127978**

Well ID: T0608127577-MW-9 Well Type: MONITORING
Source: EDF Other Name: MW-9
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-9&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-9

G45
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000087092**

Well ID: T0608127577-MW-3 Well Type: MONITORING
Source: EDF Other Name: MW-3
GAMA PFAS Testing: Not Reported
Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-3&store_num=

GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-3

G46
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000012626**

Well ID:	T0607302834-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302834&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302834&assigned_name=MW-3		

G47
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000001196**

Well ID:	T0608127577-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-6		

G48
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000054056**

Well ID:	T0607301425-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301425&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301425&assigned_name=MW-4		

F49
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000087648**

Well ID:	T0607391309-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391309&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391309&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

F50
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000099553**

Well ID:	T0607391309-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391309&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391309&assigned_name=MW-3		

F51
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000018506**

Well ID:	T0607391309-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391309&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391309&assigned_name=MW-4		

G52
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000058037**

Well ID:	T0608127577-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-2		

G53
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000134631**

Well ID:	T0607302834-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302834&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302834&assigned_name=MW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G54
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000080219**

Well ID:	T0607301425-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301425&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301425&assigned_name=MW-2		

F55
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000017115**

Well ID:	T0607391309-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391309&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391309&assigned_name=MW-2		

F56
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000090137**

Well ID:	T0607391309-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391309&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391309&assigned_name=MW-1		

F57
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000101830**

Well ID:	T0607391309-MW-3B	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3B
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391309&assigned_name=MW-3B&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391309&assigned_name=MW-3B		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G58
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000052401**

Well ID:	T0608127577-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-4		

G59
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000114873**

Well ID:	T0607302834-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302834&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302834&assigned_name=MW-4		

H60
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000102006**

Well ID:	T0607391318-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391318&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391318&assigned_name=MW-7		

H61
ESE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000115939**

Well ID:	T0607391318-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391318&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391318&assigned_name=MW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G62
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000089987**

Well ID:	T0608127577-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-5		

H63
ESE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000050648**

Well ID:	T0607391318-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391318&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391318&assigned_name=MW-3		

G64
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000083821**

Well ID:	T0608127577-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-7		

H65
ESE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000088969**

Well ID:	T0607391318-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391318&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391318&assigned_name=MW-5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

H66
ESE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000085035**

Well ID:	T0607391318-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391318&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391318&assigned_name=MW-1		

G67
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000014717**

Well ID:	T0607301425-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607301425&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607301425&assigned_name=MW-3		

H68
ESE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000131440**

Well ID:	T0607391318-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391318&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391318&assigned_name=MW-8		

G69
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000004239**

Well ID:	T0608127577-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-8		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G70
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000021458**

Well ID:	T10000002225-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000002225&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000002225&assigned_name=MW-1		

G71
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000076404**

Well ID:	T0607302834-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607302834&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607302834&assigned_name=MW-1		

G72
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000040333**

Well ID:	T0608127577-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608127577&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608127577&assigned_name=MW-1		

H73
ESE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000070912**

Well ID:	T0607391318-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391318&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391318&assigned_name=MW-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G74
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000057713**

Well ID:	T10000002225-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000002225&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000002225&assigned_name=MW-2		

G75
SW
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000083525**

Well ID:	T10000002225-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000002225&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000002225&assigned_name=MW-3		

I76
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000015673**

Well ID:	T0607300124-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300124&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300124&assigned_name=MW3		

I77
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000075006**

Well ID:	T0607300124-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300124&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300124&assigned_name=MW5		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

I78
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000021155**

Well ID:	T0607300124-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300124&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300124&assigned_name=MW1		

I79
SW
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000035771**

Well ID:	T0607300124-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300124&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300124&assigned_name=MW2		

J80
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000051536**

Well ID:	T0608121884-MW2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608121884&assigned_name=MW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608121884&assigned_name=MW2		

J81
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000066038**

Well ID:	T0608121884-MW3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608121884&assigned_name=MW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608121884&assigned_name=MW3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J82
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000004537**

Well ID:	T0608121884-MW1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608121884&assigned_name=MW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608121884&assigned_name=MW1		

J83
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000090866**

Well ID:	T0608121884-MW8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608121884&assigned_name=MW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608121884&assigned_name=MW8		

J84
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000102026**

Well ID:	T0607300726-H-24	Well Type:	MONITORING
Source:	EDF	Other Name:	H-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-24		

J85
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000084469**

Well ID:	T0608121884-MW4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608121884&assigned_name=MW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608121884&assigned_name=MW4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J86
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000065014**

Well ID:	T0607300726-H-23	Well Type:	MONITORING
Source:	EDF	Other Name:	H-23
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-23&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-23		

J87
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000021469**

Well ID:	T0608121884-MW6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608121884&assigned_name=MW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608121884&assigned_name=MW6		

J88
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000128875**

Well ID:	T0608121884-MW5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608121884&assigned_name=MW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608121884&assigned_name=MW5		

K89
SE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000113311**

Well ID:	T0607300726-MW-63	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-63
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-63&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-63		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J90
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000061458**

Well ID:	T0607300726-H-16	Well Type:	MONITORING
Source:	EDF	Other Name:	H-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-16		

K91
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000057718**

Well ID:	T0607300726-H-22	Well Type:	MONITORING
Source:	EDF	Other Name:	H-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-22		

J92
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000124975**

Well ID:	T0608121884-MW7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0608121884&assigned_name=MW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0608121884&assigned_name=MW7		

J93
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000127861**

Well ID:	T0607300726-H-21	Well Type:	MONITORING
Source:	EDF	Other Name:	H-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-21		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

J94
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000100616**

Well ID:	T0607300726-H-17	Well Type:	MONITORING
Source:	EDF	Other Name:	H-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-17		

J95
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000010390**

Well ID:	T0607300873-ETMW14	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW14		

J96
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000094567**

Well ID:	T0607300726-ETMW14	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=ETMW14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=ETMW14		

K97
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000063670**

Well ID:	T0607300726-H-19	Well Type:	MONITORING
Source:	EDF	Other Name:	H-19
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-19&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-19		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

L98
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000132275**

Well ID:	T0607300726-H-18	Well Type:	MONITORING
Source:	EDF	Other Name:	H-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-18		

L99
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000135294**

Well ID:	T0607300873-ETMW12	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW12		

M100
SE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000132934**

Well ID:	T0607391318-MW-2A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607391318&assigned_name=MW-2A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607391318&assigned_name=MW-2A		

L101
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000038882**

Well ID:	T0607300726-H-20	Well Type:	MONITORING
Source:	EDF	Other Name:	H-20
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-20&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-20		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

L102
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000085686**

Well ID:	T0607300873-ETMW15	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW15		

L103
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097211**

Well ID:	T0607300726-ETMW15	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=ETMW15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=ETMW15		

L104
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000018015**

Well ID:	T0607300726-MW-55	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-55
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-55&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-55		

L105
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000123332**

Well ID:	T0607300873-ETMW10	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW10		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

			Database	EDR ID Number
L106 **ESE** **1/2 - 1 Mile** **Lower**	Site ID:	9UT2130	**AQUIFLOW**	**37930**
	Groundwater Flow:	SW		
	Shallow Water Depth:	Not Reported		
	Deep Water Depth:	Not Reported		
	Average Water Depth:	20		
	Date:	10/14/1991		

M107
SE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000010320**

Well ID:	SLT19796830-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SLT19796830&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SLT19796830&assigned_name=MW-1		

L108
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000047781**

Well ID:	T0607300873-ETMW11	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW11		

L109
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000130989**

Well ID:	T0607300726-MW-54	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-54
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-54&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-54		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

M110
SE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000095753**

Well ID:	SLT19796830-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=SLT19796830&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=SLT19796830&assigned_name=MW-2		

L111
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000012361**

Well ID:	T0607300873-MW-43	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-43
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=MW-43&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=MW-43		

L112
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000093037**

Well ID:	T0607300873-MW-48	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-48
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=MW-48&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=MW-48		

L113
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000058634**

Well ID:	T0607300873-MW-42	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-42
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=MW-42&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=MW-42		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

N114
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000059640**

Well ID:	T0607300726-MW-53	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-53
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-53&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-53		

L115
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000143183**

Well ID:	T0607300873-MW-41	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-41
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=MW-41&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=MW-41		

L116
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000082671**

Well ID:	T0607300873-ETMW5	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW5		

O117
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000047057**

Well ID:	T0607300873-MW-49	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-49
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=MW-49&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=MW-49		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O118
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000099195**

Well ID:	T0607300873-ETMW8	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW8		

O119
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000052075**

Well ID:	T0607300873-ETVW4	Well Type:	MONITORING
Source:	EDF	Other Name:	ETVW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETVW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETVW4		

L120
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000073911**

Well ID:	T0607300873-ETMW4	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW4		

O121
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000142896**

Well ID:	T0607300873-ETMW2	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O122
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000112685**

Well ID:	T0607300873-DPE-2	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=DPE-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=DPE-2		

O123
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000102567**

Well ID:	T0607300726-DPE-2	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=DPE-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=DPE-2		

P124
SW
1/2 - 1 Mile
Lower

FED USGS **USGS40000129682**

Organization ID:	USGS-CA		
Organization Name:	USGS California Water Science Center		
Monitor Location:	016S002W36E001S	Type:	Well
Description:	Not Reported	HUC:	Not Reported
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	California Coastal Basin aquifers		
Formation Type:	Not Reported	Aquifer Type:	Not Reported
Construction Date:	19911127	Well Depth:	Not Reported
Well Depth Units:	Not Reported	Well Hole Depth:	1204
Well Hole Depth Units:	ft		

L125
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000118690**

Well ID:	T0607300726-MW-52	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-52
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-52&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-52		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O126
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000089204**

Well ID:	T0607300873-DPE-1	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=DPE-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=DPE-1		

O127
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000094862**

Well ID:	T0607300873-ETVW6	Well Type:	MONITORING
Source:	EDF	Other Name:	ETVW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETVW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETVW6		

O128
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000139187**

Well ID:	T0607300726-DPE-1	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=DPE-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=DPE-1		

O129
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000141554**

Well ID:	T0607300873-MW-22	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-22
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=MW-22&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=MW-22		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O130
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000131912**

Well ID:	T0607300873-ETVW2	Well Type:	MONITORING
Source:	EDF	Other Name:	ETVW2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETVW2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETVW2		

O131
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000068492**

Well ID:	T0607300873-ETVW1	Well Type:	MONITORING
Source:	EDF	Other Name:	ETVW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETVW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETVW1		

O132
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000006358**

Well ID:	T0607300873-ETMW6	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW6		

O133
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000099403**

Well ID:	T0607300726-ETMW6	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=ETMW6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=ETMW6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O134
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000117206**

Well ID:	T0607300873-ETVW5	Well Type:	MONITORING
Source:	EDF	Other Name:	ETVW5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETVW5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETVW5		

O135
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000097161**

Well ID:	T0607300873-ETMW3	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW3		

O136
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000065095**

Well ID:	T0607300873-ETVW10	Well Type:	MONITORING
Source:	EDF	Other Name:	ETVW10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETVW10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETVW10		

O137
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000090257**

Well ID:	T0607300726-DPE-4	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=DPE-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=DPE-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O138
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000021303**

Well ID:	T0607300873-DPE-4	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=DPE-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=DPE-4		

O139
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000000746**

Well ID:	T0607300873-MW-21	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-21
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=MW-21&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=MW-21		

O140
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000066244**

Well ID:	T0607300873-ETMW9	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW9		

P141
SW
1/2 - 1 Mile
Lower

CA WELLS **CADWR9000000264**

State Well #:	16S02W36E001S	Station ID:	24927
Well Name:	Not Reported	Basin Name:	Not Reported
Well Use:	Unknown	Well Type:	Unknown
Well Depth:	0	Well Completion Rpt #:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O142
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000051765**

Well ID:	T0607300726-MW-13	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-13		

O143
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000053337**

Well ID:	T0607300873-ETVW7	Well Type:	MONITORING
Source:	EDF	Other Name:	ETVW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETVW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETVW7		

O144
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000112521**

Well ID:	T0607300873-ETMW7	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW7		

O145
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000138472**

Well ID:	T0607300873-DPE-3	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=DPE-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=DPE-3		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O146
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000095254**

Well ID:	T0607300726-DPE-3	Well Type:	MONITORING
Source:	EDF	Other Name:	DPE-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=DPE-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=DPE-3		

O147
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000023827**

Well ID:	T0607300873-ETVW3	Well Type:	MONITORING
Source:	EDF	Other Name:	ETVW3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETVW3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETVW3		

O148
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000007839**

Well ID:	T0607300726-MW-23	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-23
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-23&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-23		

O149
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000006838**

Well ID:	T0607300726-MW-27	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-27
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-27&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-27		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O150
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000141153**

Well ID:	T0607300873-ETMW1	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW1		

O151
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000137229**

Well ID:	T0607300726-MW-24	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-24
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-24&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-24		

O152
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000049787**

Well ID:	T0607300726-MW-12	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-12
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-12&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-12		

Q153
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000116718**

Well ID:	T0607300726-MW-50	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-50
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-50&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-50		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O154
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000140091**

Well ID:	T0607300726-MW-16	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-16
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-16&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-16		

O155
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000096016**

Well ID:	T0607300726-MW-15	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-15
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-15&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-15		

N156
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000110722**

Well ID:	T0607300726-MW-60	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-60
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-60&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-60		

O157
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000101247**

Well ID:	T0607300726-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-11		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O158
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000063508**

Well ID:	T0607300726-MW-19	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-19
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-19&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-19		

O159
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000033605**

Well ID:	T0607300726-MW-29	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-29
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-29&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-29		

Q160
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000098018**

Well ID:	T0607300726-MW-30	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-30
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-30&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-30		

O161
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000065227**

Well ID:	T0607300726-MW-14	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-14
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-14&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-14		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O162
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000087836**

Well ID:	T0607300726-MW-26	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-26
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-26&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-26		

O163
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000130027**

Well ID:	T0607300726-MW-17	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-17
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-17&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-17		

O164
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000109636**

Well ID:	T0607300726-MW-28	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-28
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-28&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-28		

O165
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000088377**

Well ID:	T0607300726-MW-25	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-25
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-25&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-25		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O166
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000133460**

Well ID:	T0607300726-MW-20	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-20
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-20&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-20		

Q167
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000126528**

Well ID:	T0607300726-MW-51	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-51
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-51&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-51		

O168
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000020794**

Well ID:	T0607300726-MW-35	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-35
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-35&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-35		

O169
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000046814**

Well ID:	T0607300726-MW-18	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-18
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-18&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-18		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q170
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000080131**

Well ID:	T0607300726-MW-36	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-36
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-36&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-36		

Q171
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000047477**

Well ID:	T0607300726-MW-31	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-31
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-31&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-31		

Q172
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000067017**

Well ID:	T0607300726-MW-61	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-61
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-61&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-61		

O173
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000070256**

Well ID:	T0607300726-MW-32	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-32
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-32&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-32		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

O174
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000140592**

Well ID:	T0607300726-MW-59	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-59
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-59&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-59		

Q175
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000005441**

Well ID:	T0607300726-MW-45	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-45
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-45&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-45		

O176
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000105426**

Well ID:	T0607300726-MW-33	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-33
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-33&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-33		

Q177
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000104576**

Well ID:	T0607300726-MW-37	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-37
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-37&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-37		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q178
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000076022**

Well ID:	T0607300726-MW-57	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-57
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-57&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-57		

Q179
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000018416**

Well ID:	T0607300726-H-25	Well Type:	MONITORING
Source:	EDF	Other Name:	H-25
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-25&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-25		

O180
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000036233**

Well ID:	T0607300726-ETMW13	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=ETMW13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=ETMW13		

O181
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000002536**

Well ID:	T0607300873-ETMW13	Well Type:	MONITORING
Source:	EDF	Other Name:	ETMW13
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300873&assigned_name=ETMW13&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300873&assigned_name=ETMW13		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q182
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000007736**

Well ID:	T0607300726-MW-58	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-58
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-58&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-58		

Q183
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000136472**

Well ID:	T0607300726-MW-34A	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-34A
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-34A&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-34A		

Q184
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000134665**

Well ID:	T0607300726-MW-56	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-56
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-56&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-56		

Q185
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000115673**

Well ID:	T0607300726-MW-47	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-47
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-47&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-47		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

Q186
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000129180**

Well ID:	T0607300726-MW-46	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-46
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-46&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-46		

Q187
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000131339**

Well ID:	T0607300726-H-26	Well Type:	MONITORING
Source:	EDF	Other Name:	H-26
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-26&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-26		

Q188
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000040110**

Well ID:	T0607300726-MW-62	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-62
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=MW-62&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=MW-62		

Q189
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000036772**

Well ID:	T0607300726-H-28	Well Type:	MONITORING
Source:	EDF	Other Name:	H-28
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-28&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-28		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

190
ESE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000012749**

Well ID:	T0607300726-H-27	Well Type:	MONITORING
Source:	EDF	Other Name:	H-27
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300726&assigned_name=H-27&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300726&assigned_name=H-27		

R191
SSE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000063188**

Well ID:	T0607300345-MW-10	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-10
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300345&assigned_name=MW-10&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300345&assigned_name=MW-10		

R192
SSE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000064180**

Well ID:	T0607300345-MW-11	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-11
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300345&assigned_name=MW-11&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300345&assigned_name=MW-11		

R193
SSE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000036181**

Well ID:	T0607300345-GT-6	Well Type:	MONITORING
Source:	EDF	Other Name:	GT-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300345&assigned_name=GT-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300345&assigned_name=GT-6		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

R194
SSE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000005886**

Well ID:	T0607300345-GT-1	Well Type:	MONITORING
Source:	EDF	Other Name:	GT-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300345&assigned_name=GT-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300345&assigned_name=GT-1		

R195
SSE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000000602**

Well ID:	T0607300345-GT-7	Well Type:	MONITORING
Source:	EDF	Other Name:	GT-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300345&assigned_name=GT-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300345&assigned_name=GT-7		

R196
SSE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000117872**

Well ID:	T0607300345-GT-9	Well Type:	MONITORING
Source:	EDF	Other Name:	GT-9
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300345&assigned_name=GT-9&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300345&assigned_name=GT-9		

R197
SSE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000079426**

Well ID:	T0607300345-GT-4	Well Type:	MONITORING
Source:	EDF	Other Name:	GT-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300345&assigned_name=GT-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300345&assigned_name=GT-4		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

R198
SSE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000020141**

Well ID:	T0607300345-GT-5	Well Type:	MONITORING
Source:	EDF	Other Name:	GT-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0607300345&assigned_name=GT-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0607300345&assigned_name=GT-5		

S199
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000129474**

Well ID:	T10000000069-GW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	GW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000069&assigned_name=GW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000069&assigned_name=GW-3		

S200
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000004320**

Well ID:	T10000000069-GW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	GW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000069&assigned_name=GW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000069&assigned_name=GW-1		

S201
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000078646**

Well ID:	T10000000069-GW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	GW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000069&assigned_name=GW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000069&assigned_name=GW-2		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

S202
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000074433**

Well ID:	T10000000069-GW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	GW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000069&assigned_name=GW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000069&assigned_name=GW-4		

S203
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000138917**

Well ID:	T10000000069-GW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	GW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000069&assigned_name=GW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000069&assigned_name=GW-5		

S204
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000020173**

Well ID:	T10000000069-GW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	GW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000069&assigned_name=GW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000069&assigned_name=GW-7		

S205
NNE
1/2 - 1 Mile
Lower

CA WELLS **CAEDF0000135090**

Well ID:	T10000000069-GW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	GW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T10000000069&assigned_name=GW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T10000000069&assigned_name=GW-6		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID Direction Distance Elevation			Database	EDR ID Number
1G **SE** **1/4 - 1/2 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	Not Reported WSW Not Reported Not Reported 5.5 11/16/1989	**AQUIFLOW**	**55092**
2G **ESE** **1/2 - 1 Mile** **Lower**	Site ID: Groundwater Flow: Shallow Water Depth: Deep Water Depth: Average Water Depth: Date:	9UT2130 SW Not Reported Not Reported 20 10/14/1991	**AQUIFLOW**	**37930**

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
91941	16	0

Federal EPA Radon Zone for SAN DIEGO County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for SAN DIEGO COUNTY, CA

Number of sites tested: 30

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.677 pCi/L	100%	0%	0%
Living Area - 2nd Floor	0.400 pCi/L	100%	0%	0%
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

OTHER STATE DATABASE INFORMATION

Groundwater Ambient Monitoring & Assessment Program
State Water Resources Control Board
Telephone: 916-341-5577
The GAMA Program is Californias comprehensive groundwater quality monitoring program. GAMA collects data by testing the untreated, raw water in different types of wells for naturally-occurring and man-made chemicals. The GAMA data includes Domestic, Monitoring and Municipal well types from the following sources, Department of Water Resources, Department of Heath Services, EDF, Agricultural Lands, Lawrence Livermore National Laboratory, Department of Pesticide Regulation, United States Geological Survey, Groundwater Ambient Monitoring and Assessment Program and Local Groundwater Projects.

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Public Health
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

California Oil and Gas Well Locations
Source: Dept of Conservation, Geologic Energy Management Division
Telephone: 916-323-1779
Oil and Gas well locations in the state.

California Earthquake Fault Lines
Source: California Division of Mines and Geology
The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

RADON

State Database: CA Radon
Source: Department of Public Health
Telephone: 916-210-8558
Radon Database for California

PHYSICAL SETTING SOURCE RECORDS SEARCHED

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

Â© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

LA Mesa Park Site
7410 Waite Drive
LA Mesa, CA 91941

Inquiry Number: 7276918.4
March 10, 2023

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

03/10/23

Site Name:	Client Name:
LA Mesa Park Site	Bodhi Group
7410 Waite Drive	1076 Broadway, Suite B
LA Mesa, CA 91941	EL CAJON, CA 92021
EDR Inquiry # 7276918.4	Contact: Natalie Krage

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Bodhi Group were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# 9152001

Project: La Mesa Park Site

Coordinates:

Latitude:	32.746893 32° 44' 49" North
Longitude:	-117.038301 -117° 2' 18" West
UTM Zone:	Zone 11 North
UTM X Meters:	496411.90
UTM Y Meters:	3623228.70
Elevation:	462.13' above sea level

Maps Provided:

2018	1947
2015	1942, 1944
2012	1930
1994, 1996	1903, 1904
1991	
1975	
1967	
1953	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2018 Source Sheets




National City
2018
7.5-minute, 24000




La Mesa
2018
7.5-minute, 24000

2015 Source Sheets




National City
2015
7.5-minute, 24000




La Mesa
2015
7.5-minute, 24000

2012 Source Sheets



National City
2012
7.5-minute, 24000



La Mesa
2012
7.5-minute, 24000

1994, 1996 Source Sheets



La Mesa
1994
7.5-minute, 24000
Aerial Photo Revised 1994



National City
1996
7.5-minute, 24000
Aerial Photo Revised 1996

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1991 Source Sheets



SAN DIEGO
1991
15-minute, 50000

1975 Source Sheets



La Mesa
1975
7.5-minute, 24000
Aerial Photo Revised 1975



National City
1975
7.5-minute, 24000
Aerial Photo Revised 1975

1967 Source Sheets



National City
1967
7.5-minute, 24000
Aerial Photo Revised 1966



La Mesa
1967
7.5-minute, 24000
Aerial Photo Revised 1966

1953 Source Sheets



La Mesa
1953
7.5-minute, 24000
Aerial Photo Revised 1950



National City
1953
7.5-minute, 24000
Aerial Photo Revised 1950

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1947 Source Sheets



La Mesa
1947
7.5-minute, 24000

1942, 1944 Source Sheets



La Mesa
1942
7.5-minute, 31680



National City
1944
7.5-minute, 31680

1930 Source Sheets



La Jolla
1930
15-minute, 62500



San Diego
1930
15-minute, 62500

1903, 1904 Source Sheets




La Jolla
1903
15-minute, 62500



San Diego
1904
15-minute, 62500

Historical Topo Map

2018



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, National City, 2018, 7.5-minute
N, La Mesa, 2018, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N

Historical Topo Map

2015



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, National City, 2015, 7.5-minute
N, La Mesa, 2015, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N

Historical Topo Map

2012



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, National City, 2012, 7.5-minute
N, La Mesa, 2012, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N

Historical Topo Map

1994, 1996



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5


NW N NE
W E
SW S SE

TP, National City, 1996, 7.5-minute
N, La Mesa, 1994, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N

UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, SAN DIEGO, 1991, 15-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, National City, 1975, 7.5-minute
N, La Mesa, 1975, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, National City, 1967, 7.5-minute
N, La Mesa, 1967, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N

Historical Topo Map

1953



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, National City, 1953, 7.5-minute
N, La Mesa, 1953, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N

Historical Topo Map

1947



UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


N, La Mesa, 1947, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N

Historical Topo Map

1942, 1944



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, National City, 1944, 7.5-minute
N, La Mesa, 1942, 7.5-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Diego, 1930, 15-minute
NW, La Jolla, 1930, 15-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, San Diego, 1904, 15-minute
NW, La Jolla, 1903, 15-minute

SITE NAME: LA Mesa Park Site
ADDRESS: 7410 Waite Drive
LA Mesa, CA 91941
CLIENT: Bodhi Group

N

LA Mesa Park Site
7410 Waite Drive
LA Mesa, CA 91941

Inquiry Number: 7276918.3
March 10, 2023

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

03/10/23

Site Name:

LA Mesa Park Site
7410 Waite Drive
LA Mesa, CA 91941
EDR Inquiry # 7276918.3

Client Name:

Bodhi Group
1076 Broadway, Suite B
EL CAJON, CA 92021
Contact: Natalie Krage

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Bodhi Group were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 8D85-4E2E-8A07

PO # 9152001

Project La Mesa Park Site

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: 8D85-4E2E-8A07

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Bodhi Group (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

LA Mesa Park Site

7410 Waite Drive

LA Mesa, CA 91941

Inquiry Number: 7276918.8

March 10, 2023

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

03/10/23

Site Name:

LA Mesa Park Site
7410 Waite Drive
LA Mesa, CA 91941
EDR Inquiry # 7276918.8

Client Name:

Bodhi Group
1076 Broadway, Suite B
EL CAJON, CA 92021
Contact: Natalie Krage

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2020	1"=500'	Flight Year: 2020	USDA/NAIP
2016	1"=500'	Flight Year: 2016	USDA/NAIP
2012	1"=500'	Flight Year: 2012	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2005	1"=500'	Flight Year: 2005	USDA/NAIP
2002	1"=500'	Acquisition Date: January 01, 2002	USGS/DOQQ
1996	1"=500'	Acquisition Date: January 01, 1996	USGS/DOQQ
1995	1"=500'	Acquisition Date: January 01, 1995	USGS/DOQQ
1994	1"=500'	Acquisition Date: January 01, 1994	USGS/DOQQ
1989	1"=500'	Flight Date: August 14, 1989	USDA
1985	1"=500'	Flight Date: August 05, 1985	USDA
1979	1"=500'	Flight Date: January 27, 1979	EDR Proprietary Landiscor
1970	1"=500'	Flight Date: March 06, 1970	EDR Proprietary Landiscor
1966	1"=500'	Flight Date: November 02, 1966	USGS
1964	1"=500'	Flight Date: April 07, 1964	USDA
1953	1"=500'	Flight Date: April 14, 1953	USDA
1949	1"=500'	Flight Date: February 16, 1949	USDA

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.



INQUIRY #: 7276918.8

YEAR: 2020

= 500'

N

EDR


INQUIRY #: 7276918.8
YEAR: 2016
= 500'
N
EDR


INQUIRY #: 7276918.8
YEAR: 2012
= 500'
N
EDR


INQUIRY #: 7276918.8
YEAR: 2009
= 500'
N
EDR


INQUIRY #: 7276918.8
YEAR: 2005
= 500'
N
EDR


INQUIRY #: 7276918.8
YEAR: 2002
= 500'
N
EDR



INQUIRY #: 7276918.8

YEAR: 1996

= 500'

N

EDR



UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED

INQUIRY #: 7276918.8

YEAR: 1995

= 500'

N

EDR

UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED



INQUIRY #: 7276918.8

YEAR: 1994

= 500'

N

EDR


INQUIRY #: 7276918.8
YEAR: 1989
= 500'
N
EDR



INQUIRY #: 7276918.8

YEAR: 1985

= 500'

N

EDR


INQUIRY #: 7276918.8
YEAR: 1979
= 500'
N
EDR



INQUIRY #: 7276918.8


YEAR: 1970

= 500'

N

EDR


INQUIRY #: 7276918.8
YEAR: 1966
= 500'
N
EDR


INQUIRY #: 7276918.8
YEAR: 1964
= 500'
N
EDR


INQUIRY #: 7276918.8
YEAR: 1953
= 500'
N
EDR



INQUIRY #: 7276918.8

YEAR: 1949

= 500'

N

EDR

LA Mesa Park Site
7410 Waite Drive
LA Mesa, CA 91941

Inquiry Number: 7276918.5
March 16, 2023

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available business directory data at approximately five year intervals.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	*Target Street*	*Cross Street*	*Source*
2020	☑	☐	EDR Digital Archive
2017	☑	☐	Cole Information
2014	☑	☐	Cole Information
2010	☑	☐	Cole Information
2005	☑	☐	Cole Information
2000	☑	☐	Cole Information
1995	☑	☐	Cole Information
1992	☑	☐	Cole Information
1986	☑	☐	Haines Criss-Cross Directory
1982	☑	☐	Haines Criss-Cross Directory
1979	☑	☐	Haines Criss-Cross Directory
1975	☐	☐	Haines Criss-Cross Directory
1971	☐	☐	Haines Criss-Cross Directory
1965	☐	☐	Polk's City Directory
1960	☐	☐	Polk's City Directory
1955	☐	☐	Polk's City Directory

FINDINGS

TARGET PROPERTY STREET

7410 Waite Drive
LA Mesa, CA 91941

Year	*CD Image*	*Source*	
WAITE DR			
2020	pg A1	EDR Digital Archive	
2017	pg A2	Cole Information	
2014	pg A3	Cole Information	
2010	pg A4	Cole Information	
2005	pg A5	Cole Information	
2000	pg A6	Cole Information	
1995	pg A7	Cole Information	
1992	pg A8	Cole Information	
1986	pg A9	Haines Criss-Cross Directory	
1982	pg A10	Haines Criss-Cross Directory	
1982	pg A11	Haines Criss-Cross Directory	
1979	pg A12	Haines Criss-Cross Directory	
1975	-	Haines Criss-Cross Directory	Street not listed in Source
1971	-	Haines Criss-Cross Directory	Street not listed in Source
1965	-	Polk's City Directory	Street not listed in Source
1960	-	Polk's City Directory	Street not listed in Source
1955	-	Polk's City Directory	Street not listed in Source

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

WAITE DR 2020

7302	JUDY GUENON
	MICHAEL GUENON
	PAULA GUENON
	VIRGINIA GUENON
7310	LAURA MORENO
	URSULA PAULUS
7318	ISABEL ALONSO
	OMAR ALONSO
	RACHAEL ALONSO
7326	MARY FOUGERON
7329	ELEANOR MARTIN
	VIRGINIA BLAZIER
7334	ELVIS DAM
7342	RODOLFO RUELAS
	SANDRA RODRIGUEZ
7343	CONCRETE CONNECTION
7369	CHERISE WAID
	DEBORAH WAID
7373	TRACEY JUDGE
7375	MONICA FEIJO
7383	GARY SMITH
	SHELLY SMITH
7391	CATHERINE SMILEY
	JENNIFER SMILEY
7397	DAVID WILLNER
	RODOLFO GARCIA
7407	DEBORAH SMITH
	JANET ROUSE
	MAJED ZIARA
	THUY TRUONG
	UELE FEATO
7425	SHELLEY LAMBERTH
7452	BRANDON PERRY
	MOLLY PERRY
7456	HOLLI ELLISON
	LARRY CRON
	SOPHON NHONG
7458	MALISA BURCHELL
7460	JEREMY VANWULVEN
	MARGARET VANWULVEN
	SHANNON VAN WULVEN
7468	JOSE LIZAOLA
	MARIA LIZAOLA

Target Street	Cross Street	Source
✓	-	Cole Information

WAITE DR 2017

7236	BRADY, JASON A
7244	ANDRADE, TIFFANY T
7252	SMITH, TURIANA H
7260	SALAS, JULIO C
7268	PRIETO, BRANDON
7269	JASIENIECKI, JOHNATHAN
7275	LE, KHANH S
7276	OWEN, THOMAS D
	SUPERIOR COVERINGS
7302	GUENON, PAUL H
7310	MORENO, GUSTAVO G
7311	MACKEY, LINDA
	ORTEGA, HERMOJENES
7315	FLORES, DARLEENE
7318	ALONSO, OMAR N
7326	FOUGERON, NICHOLE L
7329	MARTIN, ELEANOR H
7334	DAM, ELVIS C
7342	EASON, ALTON T
7343	MORAN, PATRICIA J
7345	EASON, ALTON T
7367	YEE, BONNIE
7369	WAID, DEBBIE L
7373	WOLVERTON, JAMES C
7375	FEIJO, MONICA V
7389	RUBY, CYNTHIA P
7391	SMILEY, CATHERINE R
7407	ZIARI, MAJED
7425	BROD, MICHELE J
	GARCIA, MARIA G
	GOMEZ, CATALINA
	JEFFERSON-JR, ANDREW
	LAMBERTH, DANIEL F
	RAMIREZ, DIEGO
	TAGUIAM, ANN M
	WALKER, ELLIOT
	WILLIAMS, RACHEL
7448	CRABTREE, O
7452	PERRY, BRANDON J
7456	NHONG, SOPHON
7458	WARREN, STEPHANIE
7460	VANWULVEN, SHANNON D
7468	LIZAOLA, JOSE G

Target Street	Cross Street	Source
✓	-	Cole Information

WAITE DR 2014

7236	OCCUPANT UNKNOWN,
7244	HOANG, PHUC K
7252	ERAUTT, EDWARD L
7260	RAMSEY, JENNA C
7268	POST, WAYNE L
7269	JASIENIECKI, JOHNATHAN
7275	LETAN, NHAT
7276	OWEN, THOMAS D
	SUPERIOR COVERINGS
7302	GUENON, PAUL H
7310	PAULUS, URSULA L
7311	BYRD, STEPHANIE
	ORTEGA, HERMOJENES
7315	MARTINEZ, L
7318	ISABEL, ALONSO
7326	FOUGERON, NICHOLE L
7329	MARTIN, ELEANOR H
7334	DAM, ELVIS C
7342	RODRIGUEZ, ANGEL D
7343	MORAN, PATRICIA J
7345	BIRDSALL, ERIC E
7367	OCCUPANT UNKNOWN,
7369	WAID, DEBBIE L
7375	WATSON, WILLIAM
7389	RUBY, CYNTHIA P
7391	SMILEY, CATHERINE R
7397	ORTEGA, JENNIFER U
7399	SOLIS, VERONICA
7407	ZIARI, MAJED
7425	BARRON, BRUCE E
	BAYLOR, ANNETTE C
	CHAVEZ, MARCELLIA A
	COLLINS, LEEROY W
	COPELAND, MARLON D
	LAMBERTH, DANIEL F
	LARA, MELISSA
	PACHECO, JONATHAN T
	RUBIO, EMMANUEL
7440	TAYLOR, BECKY S
7448	CRABTREE, O
7452	PERRY, BRANDON J
7456	JIMENEZ, LINA
7458	WHITAKER, GLENN O
7460	VANWULVEN, SHANNON D
7468	LIZAOLA, JOSE G

Target Street	Cross Street	Source
✓	-	Cole Information

WAITE DR 2010

7236	OCCUPANT UNKNOWN,
7244	VO, LANH N
7252	ERAUTT, EDWARD L
7260	RAMSEY, JENNA
7268	OCCUPANT UNKNOWN,
7269	VALDEZ, EDDIE
7275	LEKHANH, S
7276	OWEN, THOMAS D
	SUPERIOR COVERINGS
7302	GUENON, PAUL H
7310	PAULUS, URSULA L
7311	TRUONG, ANH
7315	MARTINEZ, L
7318	ALONSO, OMAR N
7326	FOUGERON, AUGUSIUS F
7329	MARTIN, ELEANOR H
7334	DAM, ELVIS C
7342	RODRIGUEZ, SANDRA F
7343	MORAN, PATRICIA J
7345	HOLMES, NANCY M
7367	LANZA, NANNETTE M
7369	WAID, ANTHONY
7373	OCCUPANT UNKNOWN,
7375	OUELLETTE, JASON L
7383	VAZQUEZ, MARGARITA
7389	ORLANDO, ROSALIE M
7391	SMILEY, SCOTT
7397	FUENTES, JOSE
7399	GARCIA, RODOLFO C
7407	DOMINGUEZ, JEANNIE
	JACKSON, TANISHA
	JOHNSON, SHIRLEY L
7425	BURCIAGA, ERIC
	FAIR, BRITTNEY
	HERZOG, SUSAN M
	JAMESON, POLLYANNA S
	LAMBERTH, DANIEL F
	LANGRECK, JERRY A
	SALAZAR, JOANN M
	SMITH, WAYNE
	WALKER, ELLIOT
	WHITE, CYNTHIAETTA
7440	TAYLOR, ARLENE L
7448	CRABTREE, O
7452	PERRY, MOLLY
7456	CRON, CHIE M
7458	CRON, NICHOLE
7460	VANWULVEN, MARGARET M
7468	LIZAOLA, JOSE G

Target Street	Cross Street	Source
✓	-	Cole Information

WAITE DR 2005

7236	BRADY, JASON A
7244	LY, QUY
7252	ERAUTT, EDWARD L
7260	FRANCIS, AGUSTINA
7268	OCCUPANT UNKNOWN,
7275	STANPHILL, SCOTT D
7276	OWEN, THOMAS D
7302	GUENON, PAUL H
7310	MORENO, LAURA P
7311	HENNING, LARRY
	SANDOVAL, JULIA
	SD GIRLFRIEND CLUB
7315	MARTINEZ, NORBERT D
7318	ALONSO, OMAR
7326	FOUGERON, AUGUSIUS F
7329	BLAZIER, VIRGINIA
7334	DAM, ELVIS C
7342	RODRIGUEZ, SANDRA F
7343	MORAN, PATRICIA J
7345	EASON, ALTON T
7367	LANZA, NANNETTE M
7369	OCCUPANT UNKNOWN,
7373	OCCUPANT UNKNOWN,
7375	OUELLETTE, NATALIE
7383	OCCUPANT UNKNOWN,
7389	ORLANDO, ROSALIE M
7399	GARCIA, RODOLFO
7425	AHCHIN, RAYLENE M
	BLACK BEAR PET CARE
	DOCKERY, DENIS
	EDGE, AUDRA
	HERZOG, SUSAN M
	HUFFER, JERAMY
	LOWRY, CHRISTA L
	OSUNA, TANYA I
	PEREZ, ELVIRA B
	RAINEY, BONNIE L
7440	TAYLOR, JOHN R
7448	CRABTREE, VIRGINIA M
7452	BURDIN, YURIY
7456	CRON, WILLIAM B
7458	CRON, NICHOLE
7460	HOUSE, GRADY J
7468	HERNANDEZ, MARIA R

Target Street	Cross Street	Source
✓	-	Cole Information

WAITE DR 2000

7236	BRADY, WILLIAM E
7244	PHAM, DUC D
7252	ERAUTT, EDWARD
7260	OCCUPANT UNKNOWN,
7268	MEYER, R W
7269	FULLER, BARBARA A
7275	WERDICK, GREG E
7302	GUENON, PAUL H
7310	MCGEE, ALBERT R
7311	COOK, KACIE
7315	GRIBBLE, LEE A
7318	ALONSO, OMAR
7326	OCCUPANT UNKNOWN,
7329	BUSSEY, CHARLES G
7334	DAM, ELVIS
7342	RODRIGUEZ, SANDRA F
7345	HOLMES, NANCY M
7367	COTA, LAURENE S
7369	WAID, RAYMOND M
7375	PRYOR, NANCY A
7383	PASSIGLIA, CARL J
7389	JABAGAT, ISAGNI V
	ORLANDO, ROSALIE M
7391	OCCUPANT UNKNOWN,
7397	OCCUPANT UNKNOWN,
7399	OCCUPANT UNKNOWN,
7407	OCCUPANT UNKNOWN,
7425	BAYLOR, JOHN
	BYICE, JAMES R
	GAFFORD, LAMEL K
	GAMBLE, CARL A
	HELLER, LISA M
	MORRISON, V L
	ROGERS, BRIAN E
	SILVA, ROBERT
7440	TAYLOR, JOHN R
7448	OCCUPANT UNKNOWN,
7456	CRON, WILLIAM
7460	HOUSE, GRADY F
7468	MONA, HADEER

Target Street	Cross Street	Source
✓	-	Cole Information

WAITE DR 1995

7244	OCCUPANT UNKNOWNN
7252	ERAUTT, EDWARD
7260	OCCUPANT UNKNOWNN
7268	MEYER, R W
7269	OCCUPANT UNKNOWNN
7275	WERDICK, GREG E
7276	OCCUPANT UNKNOWNN
7302	GUENON, PAUL H
7310	MCGEE, ALBERT R
7311	COOK, KATHY
	MOANEY, ELLEN W
7315	OCCUPANT UNKNOWNN
7318	ALONSO, OMAR
7326	FOUGERON, A F JR
7329	GIBBONS, LAURA A
7334	TEASDALE, WALTER F
7342	LAIGHTON, MARION L
7343	OCCUPANT UNKNOWNN
7345	OCCUPANT UNKNOWNN
7367	LAU, LAURIE A
7369	OCCUPANT UNKNOWNN
7373	PROSPAL, KRISTI L
7381	OCCUPANT UNKNOWNN
7383	OCCUPANT UNKNOWNN
7389	TACHIQUIN, LUIS
7391	MAFNAS, ALICE S
7397	OCCUPANT UNKNOWNN
7399	DAVIS, KARIN
7425	GOMEZ, J
	JENSEN, JEFF
	WILLIAMS, CELESTE
7440	TAYLOR, JOHN R
7448	CRABTREE, V M
7452	LEE, V J
7456	OCCUPANT UNKNOWNN
7460	HOUSE, GRADY F
7468	ENGLERT, VELMA

Target Street	Cross Street	Source
✓	-	Cole Information

WAITE DR 1992

7252	ERAUTT, EDWARD
7268	MEYER, R W
7276	EUGENIO, FREDDIE
7302	GUENON, PAUL H
7310	MCGEE, ALBERT R JR
7318	HANSON, CHRIS
7326	FOUGERON, A F JR
7334	TEASDALE, WALTER F
7369	SMITH, HELEN D
7389	TACHIQUIN, LUIS
7425	GHANIZA, SHOAID
	GUTIERREZ, MARIO
	NEAL, BRUCE A
	TAPP, LEZLIE
7440	TAYLOR, JOHN R
7448	CRABTREE, BASIL G
7460	HOUSE, GRADY F
7468	ENGLERT, VELMA

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

WAITE DR 1986

7204	XXXX	00	
7220	XXXX	00	
7228	NICHOLSON L W	697-6242	2
7235	FLORES ALEX	463-9569	5
	FLORES JOAN	463-9569	
7236	XXXX	00	
7237	XXXX	00	
7244	DANIELS CARLOS	697-7473	+6
	ROBBINS DONNA	589-8298	4
7245	OSWALT THOS L	465-8719	
7252	ERAUTT EDW	469-8157	
7260	ALEXANDER JAS T	465-9493	
7268	MEYER A W	469-3217	
7269	MILLER DAVID A	469-2795	S
7275	XXXX	00	
7302	GUENON PAUL H	460-6938	
	GUENON PAULA L	465-8482	3
7310	MCGEE ALBERT A JR	466-2913	
7311	KRAMER JIM	698-0499	+6
7315	XXXX	00	
7318	XXXX	00	
7326	FOUGERON A F JR	463-2420	
7334	TEASDALE WALTER F	466-7471	
7342	HAWLEY BRADLEY A	465-3916	0
7343	XXXX	00	
7345	COOLEY H L	461-3137	
7367	XXXX	00	
7369	SMITH HELEN DUDA	466-3431	
7373	PERKINS EDWARD M	463-2616	4
7375	CLOUSE J A	697-9119	
	CLOUSE SHERRY	697-9119	3
7383	SOSNA DAVID	464-1479	3
7389	TACHIOUIN LUIS	461-8737	9
7389½	DOBBINS A W	465-2567	0
7391	XXXX	00	
7397	DOWLING S	461-4357	1
7407A	HEIDT K	698-9142	+6
7410	XXXX	00	
7425	GOLDSBY G	464-8157	S
	RODRIGUEZ MARY J	697-7355	4
7440	TAYLOR JOHN A	465-6218	
7448	CRABTREE BASIL G	466-4962	
7452	LEE DAHL E	463-9532	
7456	XXXX	00	
7460	HOUSE GRADY F	465-1716	
7468	ENGLERT VELMA	466-7396	
	* 5 BUS	176 RES	53 NEW

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

WAITE DR 1982

7204	XXXX	00	
7220	XXXX	00	
7228	NICHOLSON L W	697-6242	+2
7235	GORDON CAROLYN D	697-93[illegible]1	+2
7236	XXXX	00	
7237	XXXX	00	
7244	KJELDGAARD PETER D	462 3613	1
7245	OSWALT THOS L	465 8719	
7252	ERAUTT EDW	469-8[illegible]57	
7260	ALEXANDER JAS T	465-9493	
7268	MEYER R W	469 3217	
7269	XXXX	00	
7275	XXXX	00	
7302	GUENON PAUL H	460-6938	[illegible]
7310	MCGEE ALBERT R JR	466-29[illegible]	
7311	KELTGEN B	697-5[illegible]80	[illegible]
7315	XXXX	00	
7318	JUSTICE WM P	697-1749	[illegible]
7326	FOUGERON A F JR	463 2420	
7334	TEASDALE WALTER F	466-7471	
7342	HAWLEY BRADLEY R	465-3[illegible]6	[illegible]
7343	LUNSFORD GEORGIA V	462 5499	5
7345	COOLEY H L	461-3[illegible]37	
7369	SMITH HELEN OLIDA	466-3431	
7373	PERKINS EDW M	463-2616	
7375	MACMILLAN T O	465-1[illegible]85	8
7333	JONES ROBT L	697 66[illegible]2	+2
7389	TACHIOUIN LUIS	461 8[illegible]7	3
7389½	DORBINS A W	465 2567	0
7391	XXXX	00	
7397	DOWLING S	461-4357	1
7407	XXXX	00	
7410	XXXX	00	
7425	APARTMENTS		
3	BOISELLE H	462-6830	1
12	CARDER R	697-[illegible]098	1
	ELS RANDALL	461-14[illegible]S	+2
11	ENGELKE BRUCE K	697-08[illegible]6	1
	MONTALVO J D	469 0750	+2
	OMUFER MICHAEL	69[illegible] 9525	1
	SANDERS R JR	46[illegible] 9845	+2

S & CO INC

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

WAITE DR 1982

WAITE DR 92041 CONT

	WILLIAMS J	465-5559 +2
7425		
7440	TAYLOR JOHN R	465-6218
7448	CRABTREE BASIL G	466-4962 3
7452	LEE DANL E	463-9532 5
7456	XXXX	00
7460	HOUSE GRADY F	465-1716
7468	ENGLERT VELMA	466-7396

* 4 BUS 207 RES 82 NEW

Target Street	Cross Street	Source
✓	-	Haines Criss-Cross Directory

WAITE DR 1979

7204	XXXX	00
7220	SCHNEIDER A J	466-0123 0
7228	NICHOLSON L W	462-6472 6
7235	BUCKINGHAM M K	464-8759 8
7236	BRADY W E	466-0912
7237	XXXX	00
7244	MCKENZIE GERALD T	466-7065 6
7245	OSWALT THOS L	465-8719
7252	ERAUTT EDW	469-8157
	ERAUTT SUZY	563-8088+9
7260	ALEXANDER ILEESE	465-9493
	ALEXANDER JAS T	465-9493 1
7268	MEYER R W	469-3217
7269	XXXX	00
7275	WERDICK GREG	463-6359 5
7302	GUENON PAUL H	460-6938 5
7310	MCGEE ALBERT R JR	466-2913
7311	PENDLETON DAYNA	469-2674+9
7315	XXXX	00
7318	JUSTICE WM P	897-1749+9
7326	FOUGERON A F JR	463-2420
7334	TEASDALE WALTER F	466-7471
7342	XXXX	00
7343	LUNSFORD GEORGIA V	462-5499 5
7345	COOLEY H L	461-3137 0
7369	SMITH HELEN DUDA	465-3431
7373	PERKINS EDW M	463-2616
7375	MACMILLAN T O	465-1185 8
7383	ARMSTRONG BILLY D	460-6980 8
7389	TACHIQUIN LLIS	461-8737+9
7391	LINGER T J	697-1789+9
7397	XXXX	00
7407	ARANDA VIRGINIA	697-1293+9
7410	XXXX	00
7425	APARTMENTS	
	ELKINS LARRY E	462-5593 8
	KALANI KIM	469-2666 8
	LONG STEVE	462-8119+9
3	MORELAND BILLY	460-4783 7
	PREUSS WM A JR	462-3168 8
	SMITH PATRICIA	466-1524 8
	TEEMS WILLIAM	463-7691+9
7425		
7440	TAYLOR JOHN R	465-8218
7448	CRABTREE BASIL G	466-4962 3
7452	LEE DANL E	463-9532 5
7456	ALLSWORTH WM EARL	466-0627 5
7458	CARLSON BEN	462-0941 4
7460	HOUSE GRADY F	465-1716
7468	ENGLERT VELMA MRS	466-7396
★	4 BUS 210 RES	88 NEW

COPYRIGHT HAINES & CO INC INF