Appendix E:

Phase I Environmental Site Assessment

THIS PAGE INTENTIONALLY LEFT BLANK

Phase I Environmental Site Assessment

Lemee Lane Property
APN 013-011-003-000
Mariposa, California 95338

April 10, 2026

Prepared for:

Mariposa County Public Works

Prepared by:

PROVOST&PRITCHARD
CONSULTING GROUP

455 W. Fir Avenue
Clovis, California 93611

1542-26-001 ESA

COPYRIGHT 2026 by PROVOST & PRITCHARD CONSULTING GROUP
ALL RIGHTS RESERVED

Provost & Pritchard Consulting Group expressly reserves its common law copyright and other applicable property rights to this document. This document is not to be reproduced, changed, or copied in any form or manner whatsoever, nor are they to be assigned to a third party without first obtaining the written permission and consent of Provost & Pritchard Consulting Group In the event of unauthorized reuse of the information contained herein by a third party, the third party shall hold the firm of Provost & Pritchard Consulting Group harmless, and shall bear the cost of Provost & Pritchard Consulting Group's legal fees associated with defending and enforcing these rights.

Environmental Professional Statement

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in § 312.10 of 40 C.F.R. § 312. We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject Property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set for in 40 C.F.R. Part 312.

April 9, 2026

Darylyn Tachella
Principal Geologist

Stephanie Gillaspy, EIT
Principal Environmental Professional

David Norman
Principal Environmental Professional

Table of Contents

Executive Summary 1
1 Introduction 1
1.1 Reasons for Performing ESA 1
1.2 Detailed Scope of Services 1
1.3 Common Acronyms 2
1.4 Significant Assumptions and Exceptions 2
1.5 Limitations 2
1.6 User Reliance 3
1.7 Site Description 3
1.8 Owners, Property Manager, and Occupant Information 3
2 User Responsibilities 3
2.1 Environmental Liens or Activity and Use Limitations 3
2.2 User Knowledge 3
3 Records Review 3
3.1 Physical Setting Resources 3
3.1.1 USGS Topographic Maps 4
3.1.2 Geological Conditions 4
3.1.3 USDA Soil Survey 4
3.2 Standard Government Environmental Records Sources 4
3.2.1 Standard Records Findings 4
3.2.2 Vapor Encroachment Screen 5
3.2.3 Mariposa County Certified Unified Program Agency 5
3.2.4 California Geologic Energy Management Division 5
3.2.5 Department of Toxic Substances Control 5
3.2.6 Regional Water Quality Control Board 5
3.3 Standard Historical Resources 6
3.3.1 Aerial Photographs 6
3.3.2 Topographic Maps 6
3.3.3 City Directories 6
3.3.4 Sanborn Fire Insurance Maps 6
3.3.5 Building Department Records 6
3.3.6 Mariposa County Assessor’s Office 6
3.4 Uses of the Property 6
3.5 Uses of the Adjoining Properties 7
4 Site Reconnaissance 7

4.1 Methodology and Limiting Conditions 7
4.2 Observations 7
4.3 Exterior Observations 8
4.4 Interior Observations 8
5 Interviews 8
5.1 Interview with Key Site Manager 8
5.2 Interviews with Occupants 8
5.3 Interviews with Past Owners, Operators, and Occupants 8
5.4 Interviews with Local Government Officials 8
6 Findings and Opinion 9
6.1 Data Gaps 9
7 Conclusions 9
8 References 9
9 Environmental Professionals Resumes 10

List of Appendices

Appendix A Figures
Appendix B User Responsibilities
Appendix C Government Environmental Records
Appendix D Historical Records
Appendix E Site Reconnaissance Photographs
Appendix F Interviews

Executive Summary

- This Phase I Environmental Site Assessment Report has been prepared for Mariposa County for the Lemee Lane project property located east of Highway 49 and south of Frank Wilson Rd in Mariposa, California (Vicinity Map). The property is identified as Mariposa County APN 013-011-003-000.
- The property is and has historically generally been undeveloped except for the use of a small former foundation of unknown use.
- The Property is not listed on environmental databases searched.
- Site reconnaissance was conducted on March 30, 2026.
- Interview questionnaires completed by the current owner and prospective buyer do not indicate environmental concerns.
- Provost & Pritchard has performed this ESA in general conformance with the scope and limitations of ASTM E 1527-21. This assessment has revealed the following potential RECs, controlled RECs, or significant data gaps, other than the noted end dumped pile, in connection with the Property:
    - The unknown use of the concrete pad in the southwest corner of the property could indicate a previous well onsite. If discovered to be an abandoned well, it should be destroyed properly according to State and Local regulations.

1 Introduction

This Phase I Environmental Site Assessment Report (ESA) has been prepared for Mariposa County (County) for the Lemee Lane project property (Property), located near Highway 49, Frank Wilson Road, and Lemee Lane (Vicinity Map, Appendix A). The Property has Mariposa County assessor's parcel number 013-011-003-000. This ESA was performed in accordance with the scope and limitations of the American Society of Testing and Materials (ASTM) Standard Practice for Phase 1 Environmental Site Assessment Process E1527-21. This ESA was conducted to assess the environmental condition of commercial real estate taking into account commonly known and reasonably ascertainable information. The ESA was limited to the area identified on the Site Map in Appendix A.

The objective of this ESA is to assist the client in understanding recognized environmental conditions associated with the site's past and current use. Recognized Environmental Condition (REC) is defined as "(1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

Historical Recognized Environmental Condition (HREC) is defined by the ASTM Standard Practice E1527-21 as "a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls".

Business Environmental Risks (BER) include risks which can have a material environmental or environmentally driven impact on the business associated with the current or planned use of commercial real estate, not necessarily related to those environmental issues required to be investigated in the standard ASTM scope. BERs may affect the liabilities and financial obligations of the client, the health and safety of site occupants, and the value and marketability of the subject property.

In addition, this ESA has also noted the presence of housekeeping and other conditions which ASTM identifies as "non-scope considerations" that may create a BER as defined above. Housekeeping conditions, a type of a BER, are generally considered de minimis conditions that in general do not present a threat to human health or the environment and generally would not be the subject of an enforcement action if brought to the attention of government agencies but could require regulatory permitting.

1.1 Reasons for Performing ESA

This ESA was conducted to assist Mariposa County in developing information about the environmental condition of the Property and to meet the criteria of the All Appropriate Inquiry (AAI) standard in regard to previous ownership, uses, and environmental conditions of the Property for the purposes of possibly qualifying for some level certain landowner liability protections under Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) or a Bonafide Purchaser as available to public agencies. .

1.2 Detailed Scope of Services

The ESA process consisted of:

a. A review and evaluation of state and federal (i.e., U.S. EPA) environmental databases that list sites of potential impact within specified search distances;

b. A review and evaluation of reasonably ascertainable local agency records and environmental databases for historical and current documentation pertaining to the site;

c. A review and evaluation of historical use information, including aerial photographs and maps (e.g., USGS, fire insurance, etc.), tax improvement records, city directories, and building department permit records;

d. Interviews with clients and government officials, as appropriate;

e. Site reconnaissance to determine current and past uses and conditions of both the property and adjoining properties;

f. Preparation of a report detailing findings, and conclusions generated from components 'a' through 'd'.

1.3 Common Acronyms

APN:	Assessor's parcel number
AST:	Above-ground storage tank
ASTM:	American Society for Testing and Materials
CUPA:	Certified Unified Program Agency
DTSC:	California Department of Toxic Substance Control
DWR:	California Department of Water Resources
EDR:	Environmental Data Resources Inc.
EPA:	United States Environmental Protection Agency
ESA:	Environmental site assessment
P&P:	Provost & Pritchard Consulting Group
REC:	Recognized environmental condition
RWQCB:	Regional Water Quality Control Board
USDA:	United States Department of Agriculture
USGS:	United States Geological Survey
UST:	Underground storage tank

1.4 Significant Assumptions and Exceptions

The ESA is designed in principle to be a cost-effective overview of a site, which should identify indications of RECs that are observable, or recorded in readily available public records. Evaluation of the Property is limited to information available through public sources, interviews, and firsthand observation. Judgments leading to opinions and recommendations are made without a complete knowledge of subsurface conditions. Findings and recommendations are made in review of information that was prepared or provided by others. This report assumed that the information provided is accurate and correct. P&P assumes that cases closed by regulatory agencies do not continue to represent a threat of groundwater impacts or vapor migration or intrusion. Additional research beyond that required by ASTM E1527-21 may yield additional information.

1.5 Limitations

Land use, site conditions (both onsite and offsite) and other factors will change over time. Since site activities and regulations could change at any time after the completion of this report, the observations, findings, and opinions can be considered valid only as of the date of the site visit.

P&P's professional services were performed consistent with generally accepted environmental principles and practices in California at the time the services were performed. Judgments leading to conclusions and recommendations are made without a complete knowledge of subsurface conditions.

No environmental site assessment can wholly eliminate uncertainty regarding the potential for recognized environmental conditions in connection with a property. Performance of the practice outlined in ASTM E1527-21 is intended to reduce, but not eliminate, uncertainty regarding the potential for recognized environmental conditions in connection with a property, and this practice recognizes reasonable limits of time and cost.

Therefore, no warranty or guarantee is expressed or implied.

1.6 User Reliance

This report has been prepared for the sole benefit of Mariposa County. Any other person or entity without the express written consent of Provost & Pritchard Consulting Group and/or Mariposa County may not rely upon this report.

1.7 Site Description

The site description includes information that identifies the physical setting of the site in relation to the surrounding area. Table 1 describes the General Site Characteristics.

Table 1 General Site Characteristics

ADDRESS & ASSESSOR'S PARCEL NUMBER	No address assigned. 013-011-003-000
APPROXIMATE SIZE	The project Property is approximately 2.3 acres.
LOCATION	The Property is located primarily within Highway 49, Frank Wilson Road, and Lemee Lane.
ZONING	GC (General Commercial)
LEGAL DESCRIPTION	The Property is described as portions of Section 15 in Township 5 South, Range 18 East, Mount Diablo Base and Meridian in the County of Mariposa.

1.8 Owners, Property Manager, and Occupant Information

The project Property is owned and managed by Thomas and Lori Ritter Trust.

2 User Responsibilities

2.1 Environmental Liens or Activity and Use Limitations

Transaction-Related Title Insurance Documentation (ex. Preliminary Title Report) was not provided by the User in order to search for environmental liens and activity and use limitations (AULs). Instead, environmental liens and activity and AULs were searched for by EDR. The search is dated March 18, 2026. No environmental liens or other activity and use limitations (AULs) were reported in the EDR Environmental Lien and AUL Search. See Appendix B.

2.2 User Knowledge

A user questionnaire was completed by Mr. Robert Stark of Mariposa County, included in Appendix B. Specialized or actual knowledge of environmental concerns, commonly known or reasonably ascertainable information of environmental concerns, or significantly lower purchase price were not indicated in the questionnaire answers.

3 Records Review

The purpose of the records review is to obtain and review records that would help to identify recognized environmental conditions in connection with the Property.

3.1 Physical Setting Resources

The geologic and hydrologic conditions beneath the Property were researched to evaluate whether hazardous substances are likely to migrate into groundwater or soil beneath the site, either from on or off-site sources.

3.1.1 USGS Topographic Maps

USGS 7.5-minute topographic maps of the Feliciana Mountain, Mariposa, Bear Valley and Catheys Valley quadrangles from 1896-97, 1900, 1903, 1909, 1912, 1947-48, 1981, 1992, 2004, 2012, 2015, 2018, and 2021 were reviewed for the Property and surrounding area from the EDR Historical Topo Map Report in Appendix D.

The Property is located in a mountainous area with a central low point. The property and surrounding area are undeveloped from 1896 through 1912. In the 1947 topo map, the surrounding area is developed with residential and commercial. The Mariposa Ranger Station is shown in the 1946 topo map directly north of the property.

Development is mapped in the surrounding area beginning in 1946.

3.1.2 Geological Conditions

The site is located in the foothills of the Sierra Nevada Mountain range. The western Sierra foothills area is underlain by folded and faulted metasedimentary and metavolcanic rocks of Paleozoic and Mesozoic ages (the subjacent series) upon which isolated erosional remnants of a formerly extensive capping of Tertiary volcanic conglomerate and tuff (the superjacent series) lie with angular unconformity. Bedding and metamorphic planar structures in the subjacent rocks dip steeply and generally trend parallel to one another and to the crest of the adjacent Sierra Nevada. Bedding in the Tertiary rocks' dips gently to the - west (Duffield and Sharp, 1975).

The Sierra Nevada is a tilted fault block nearly 400 miles long. Its east face is a high, rugged fault scarp that contrasts sharply with its gentle western slope. The massive granites of the higher elevations are modified by glacial sculpting, forming such scenic features as Yosemite Valley. Many west-flowing rivers cut deeply into the western slope. The high crest of the range culminates in Mt. Whitney with an elevation of 14,495 feet above sea level. The older metamorphic bedrock, in places still partly capped by much younger Tertiary volcanic rocks, contains gold-bearing veins associated with the northwest-trending Mother Lode (California Geological Survey, Department of Conservation).

Ultramafic rocks are known the be present in the general area and appropriate maps should be reviewed to assess the potential presence of naturally occurring asbestos (NOA) on the property.

3.1.3 USDA Soil Survey

The USDA Soil Survey Map indicates that the site's soils are primarily composed of loam. This soil type generally has slow infiltration rates and tend to be silt-clay like in consistency. A soils map and description of the units is included in the GeoCheck section of the EDR Radius Map Report in Appendix C.

3.2 Standard Government Environmental Records Sources

Provost & Pritchard contracted with a commercial database service, Environmental Data Resources (EDR), to review the standard government environmental record sources within the appropriate ASTM minimum search distance from the Property. The list of government records searched and the search distance are listed in the Map Findings Summary of the EDR Radius Map™ Report, included in Appendix C. The dates of the versions of government records searched are listed in the Government Records Searched/ Data Currency Tracking section of the EDR Radius Map™ Report. Findings of the EDR Radius Map™ Report are discussed in 3.2.1.

Additional state and local agency records were also reviewed by Provost & Pritchard and discussed in sections 3.3.6 through **Error! Reference source not found.** Records obtained or correspondence with agencies are included in Appendix C.

3.2.1 Standard Records Findings

If the subject property or any of the adjoining properties is identified on one or more of the standard government environmental record resources, pertinent regulatory files and/or records associated with the listing are reviewed below.

3.2.1.1 Subject Property

The government records provided in the EDR Radius Map™ Report for review were compiled on March 12, 2026. The Property is not listed on the state or federal databases searched in the EDR Radius Map™ Report.

3.2.1.2 Adjoining Properties

Two adjoining sites are listed in the EDR Radius Map™ Report. A property to the north is listed at 5366 State Highway 49 is listed in the RCRA, HIST UST, HWTS, LUST, Cortese, HAZNET, EMI, CERS, SWEEPS, E MANIFEST, and AST. The 5366 Highway 49 is listed as Cal-Fire, Dept of Forestry and Fire, Mariposa Headquarters Firefighting, CDF Mariposa, Mariposa Ranger Unit, Cal Fire Mariposa.

The adjoining property to the southeast is the Mariposa County Health and Human Services Agency at 5300 Highway 49 is listed on the RCRA NonGen/NLR and E Manifest. No violations or evaluations were found.

3.2.2 Vapor Encroachment Screen

The EDR Vapor Encroachment Screen was designed to assist parties seeking to meet the search requirements of the ASTM Standard Practice for Assessment of Vapor Encroachment into Structures on Property involved in Real Estate Transactions (E-2600-10). A Vapor Encroachment Screen was prepared on April 7, 2026 using EDR's Vapor Encroachment Worksheet and is included in Appendix C. The Screen indicates that vapor encroachment conditions (VECs) do not exist for the Property. This is based on the presence or absence of hazardous substances, proximity to the Property, groundwater flow, and geologic barriers or pathways. Given there are no hazardous substances identified in the search radius by EDR, the no VEC results seems reasonable.

No vapor encroachment screen can wholly eliminate uncertainty regarding VECs. Screening is intended to reduce, but not eliminate, uncertainty regarding whether a VEC exists in connection with a property. Further, findings regarding VECs do not determine whether a REC is or is not present.

3.2.3 Mariposa County Certified Unified Program Agency

The Unified Program regulates hazardous waste and hazardous materials by ensuring consistency throughout the state regarding the implementation of administrative requirements, permits, inspections, and enforcement at the local regulatory level. CalEPA oversees the statewide implementation of the Unified Program and its 81 certified local agencies, known as Certified Unified Program Agencies (CUPAs), which apply regulatory standards established by State agencies. The CUPA for the County of Mariposa is the Environmental Health Services Division. Records were requested on April 7, 2026, and not received during the preparation of this report.

3.2.4 California Geologic Energy Management Division

The State of California Geologic Energy Management Division (CalGEM, formerly DOGGR) maintains the Well Finder web site with maps showing the locations of oil and gas wells the department has records of. The CalGEM website was reviewed on April 7, 2026. A review of the oil and gas maps contains no records of oil or gas wells drilled in the area of the Property, as shown on the map in Appendix C.

3.2.5 Department of Toxic Substances Control

EnviroStor is the Department of Toxic Substances Control's (DTSC) data management system for tracking our cleanup, permitting, enforcement and investigation efforts at hazardous waste facilities and sites with known contamination or sites where there may be reasons to investigate further. The EnviroStor website was reviewed on April 7, 2026. A review of the EnviroStor website indicates that no records exist for this Property, as shown on the map in Appendix C.

3.2.6 Regional Water Quality Control Board

GeoTracker is the California State Water Resources Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

GeoTracker portals retrieve records and view integrated data sets from multiple State Water Board programs and other agencies. The GeoTracker website was reviewed on April 7, 2026. A review of the GeoTracker website indicates that no records exist for this Property, as shown on the map in Appendix C.

3.3 Standard Historical Resources

The objective of compiling and analyzing historical information and developing a history of the previous uses of the Property, adjoining properties, and surrounding area is to help identify the likelihood of past uses having led to RECs in connection with the Property. Historical records reviewed are included in Appendix D. The following standard historical sources were reviewed to identify past use back to at least 1940, or when first developed.

3.3.1 Aerial Photographs

The EDR Aerial Photo Decade Package in Appendix D includes aerial photographs from years 1945, 1959, 1972, 1978, 1984, 1993, 1998, 2006, 2009, 2012, 2016, 2020, and 2024.

In the aerial photo from 1945 the Property appears to be occupied primarily by trees. The Property appears relatively unchanged in the aerial photographs from 1945 through 1998. Some trees were removed in the 2006 aerial photograph. Lemee Lane is visible in the 2009 aerial along the western boundary. The Mariposa County Health and Human Services building is shown in the 2012 aerial photograph. No changes are visible between 2012 and 2024 aerial photographs.

3.3.2 Topographic Maps

USGS topographic maps are discussed in 3.1.1.

3.3.3 City Directories

The EDR-City Directory Image Report in Appendix D provides directory listings for years 1974, 1977, 1981, 1985, 1992, 1995, 2000, 2005, 2010, 2014, 2017, 2022, and 2024. The Property does not have an assigned address.

Adjoining properties listed on Lemee Lane listed at 5362 Lemee Lane include Mother Lode job training, Job Connection Mariposa in 2014, Mariposa County Department of Child Support Services in 2017, Mariposa County Behavioral, Job Connection Mariposa, Mariposa County Department of Child Support Services, and Johnathan Harry in 2022, and Mariposa County Department of Child Support Services, Amy Olson, and Mary Ellen McRae in 2024.

3.3.4 Sanborn Fire Insurance Maps

The EDR Certified Sanborn® Map Report in Appendix D indicates fire insurance maps covering the Property are not available.

3.3.5 Building Department Records

No building permits were found for the Property in the EDR Building Permit Report in Appendix D. Historic aerial photographs and topographic maps also do not indicate the past presence of buildings.

3.3.6 Mariposa County Assessor's Office

Information for the Mariposa County assessor parcel numbers (APNs) on the Property are shown in property details from ParcelQuest and tax assessors map included in Appendix D.

3.4 Uses of the Property

Based on historical records reviewed, the obvious uses of the Property back to initial development include unoccupied through at least 2006. The current owner has owned the property for 18 years and has used the site for hay storage for the local feed store.

3.5 Uses of the Adjoining Properties

Based on aerial imagery, topographic maps, city directory listings, and database listings reviewed, properties surrounding the subject Property have historically been primarily undeveloped property, a fire station and Mariposa County Health and Human Services Department.

4 Site Reconnaissance

4.1 Methodology and Limiting Conditions

An escorted by Robert Stark, Mariposa County, site reconnaissance was conducted on March 30, 2026 by Stephanie Gillaspy of Provost & Pritchard Consulting Group to document the physical setting of the site, verify information obtained from the agency records (if available), and obtain site-specific information where no records were available. The objective of a site reconnaissance is to collect information and make observations to help identify RECs in connection with the subject property.

Table 2 lists the observations noted during the site reconnaissance. The photographs of the Property are in Appendix E.

4.2 Observations

The site is currently not developed. There is a culvert in the middle of the property to drain water from the site to off site near the intersection of Lemee Lane and Frank Wilson Road (picture 5, 7, 32). There is an unknown concrete foundation in the southwest corner of the property (pictures 15-18).

Table 2 Features, Activities, Uses, and Conditions

Item	Observation
Current use(s) of the Property	Undeveloped
Past use(s) of the Property	None identified.
Geologic, hydrogeologic, hydrologic, & topographic conditions	
Structures & other improvements	No structures onsite.
Foundations of former structures	Unknown use concrete foundation (pictures 15-18)
Roads	Lemee Lane, Frank Wilson Rd, and Highway 49
Potable water supply	Water pressure tank on edge of property. Not certain which side of the property line it is on (pic 20). No well identified.
Septic or sewage disposal system	None observed.
Hazardous substances and petroleum products in connection with identified uses	None observed.
Hazardous substances and petroleum products not in connection with identified uses	None observed.
Underground storage tanks	None observed.
Aboveground storage tanks	None observed.
Odors	None observed.
Pools of liquids or standing surface water	None observed.
Drums, totes, & intermediate bulk containers	None observed.
Electrical or hydraulic equipment suspected to contain PCBs	None observed.
Heating/Cooling	N/A, no structures.
Stains or corrosion on floors, walls, or	N/A, no structures.

Item	Observation
ceilings	
Drains and sumps	Culvert to drain water from site to off site. (pics 5, 7, and 32).
Pits, ponds, or lagoons	None observed.
Stained soils or pavement	None observed.
Stressed vegetation (from something other than insufficient water)	None observed.
Solid waste and wastewater	Unknown end dumped pile with overgrown grass and observation of the material or below the pile were not possible.
Wells (including dry wells, domestic, irrigation, injection, monitoring, abandoned, or other wells)	Pressure tank (pic 19-20).
Current and past uses of adjoining properties	
North	Frank Wilson Rd, Forest Service Fire Station
West	Lemee Lane, residential
East	Piertra Lane, Wicked Mead Inc Winery
South	Highway 49, Mariposa County Health and Human Services Dept

4.3 Exterior Observations

The periphery of the property was observed to evaluate evidence of an avenue for the disposal of hazardous substance or petroleum products. No pathway was observed.

4.4 Interior Observations

Not applicable as there are no structures on the Property.

5 Interviews

5.1 Interview with Key Site Manager

A key site manager is defined as a person having good knowledge of the uses and physical characteristics of the subject Property. For this Property, Mr and Mrs. Tom and Lori Ritter, are considered a key site manager and completed an interview questionnaire include in Appendix F. The questionnaire is dated March 10, 2026 and indicates the Ritter;s have owned the property for 18 years. No indication was made regarding environmental concerns for the property.

5.2 Interviews with Occupants

Not applicable as there are no occupants.

5.3 Interviews with Past Owners, Operators, and Occupants

Contacts for interviews with past owners, operators, and occupants were not identified.

5.4 Interviews with Local Government Officials

Local agencies were contacted for records and not interviewed.

6 Findings and Opinion

The Property has undeveloped land since at least 1940. Surrounding properties have historically been mainly Forest Service fire station, Mariposa County Health and Human Services department offices, residential and undeveloped property.

Records review revealed the Property is not listed on the databases searched. Two adjoining sites are listed in the EDR Radius Map™ Report. A property to the north is listed at 5366 State Highway 49 is listed in the RCRA, HIST UST, HWTS, LUST, Cortese, HAZNET, EMI, CERS, SWEEPS, E MANIFEST, and AST. The 5366 Highway 49 is listed as Cal-Fire, Dept of Forestry and Fire, Mariposa Headquarters Firefighting, CDF Mariposa, Mariposa Ranger Unit, Cal Fire Mariposa.

The adjoining property to the southeast is the Mariposa County Health and Human Services Agency at 5300 Highway 49 is listed on the RCRA NonGen/NLR and E Manifest. No violations or evaluations were found. Contamination is not indicated in the records. Due to distance and the nature of the closest database listings, these properties are not suspected to be RECs for the subject Property.

Site reconnaissance revealed that the Property is currently undeveloped. There is a storm drain culvert near the middle of the property draining offsite at the northwest corner of the property. There is a former concrete foundation at the southwest corner of the property. The use of the foundation is unknown.

An interview questionnaire completed by the current landowner confirmed that the Property has been unoccupied for the 18 years of owning the property. The questionnaire answers revealed no knowledge of environmental concern.

The EDR Vapor Encroachment Screen was designed to assist parties seeking to meet the search requirements of the ASTM Standard Practice for Assessment of Vapor Encroachment into Structures on Property involved in Real Estate Transactions (E-2600-10). The Screen indicates that vapor encroachment conditions do not exist for the Property.

6.1 **Data Gaps**

A data gap is a lack of or inability to obtain information required by ASTM E1527-21 despite good faith efforts to gather such information.

Aerial photographs and topographic maps provided were not at an interval of five years.

These data gaps are not suspected to affect the ability to identify RECs and so are not considered significant.

The end dumped pile of unknown material which is overgrown with weeds restricted P&Ps ability to observed it contents or below the pile. This represents a Data Gap the does not allow P&P to provide an opinion concerning the present or absence of a REC in this area.

7 Conclusions

We have performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM E1527-21 of the Ritter Property in Mariposa County, California. Any exceptions to, or deletions from, this practice are described in Section 1.4of this report. This assessment has revealed the following potential RECs, controlled RECs, or significant data gaps, other than the noted end dumped pile, in connection with the Property:

- The unknown use of the concrete pad in the southwest corner of the property could indicate a previous well onsite. If discovered to be an abandoned well, it should be destroyed properly according to State and Local regulations.

8 References

California Department of Conservation, Geologic Energy Management Division. Well Finder. https://www.conservation.ca.gov/calgem/Pages/WellFinder.aspx

California Department of Water Resources (DWR). 2003. California's Groundwater Bulletin 118, San Joaquin River Hydrologic Region, San Joaquin Valley Groundwater Basin, Delta Mendota Subbasin.

California Department of Toxic Substances Control. EnviroStor. https://www.envirostor.dtsc.ca.gov/public/

California State Water Resources Control Board. GeoTracker. https://geotracker.waterboards.ca.gov/

CalEPA. Regulated Site Portal, nSite. https://siteportal.calepa.ca.gov/nsite/map

Croft, MG, and Gordon, GV. 1968. Geology, Hydrology, and Quality of Water in the Hanford-Visalia Area, San Joaquin Valley, California. USGS Open-File Report.

Environmental Data Resources, Inc. (EDR), 6 Armstrong Road, Shelton, CT 06484.

Harden, DR. 1998. California Geology. Second edition. Prentice Hall.

UC Davis. SoilWeb Apps. https://casoilresource.lawr.ucdavis.edu/soilweb-apps/

9 Environmental Professionals Resumes

Darylyn Tachella, PG

Senior Geologist

Education

- ✓ B.S. Geology
  California State University, Fresno
- ✓ Mathematics Major Coursework,
  California Polytechnic State University,
  San Luis Obispo
- ✓ A.S. Liberal Studies – Mathematics &
  Science, Cuesta College, San Luis
  Obispo, California

Registration/Certifications

- ✓ Professional Geologist, California, #9661
- ✓ HAZWOPER (40 hours)

Affiliations

- ✓ Member, AEHS Foundation

Areas of Expertise

- ✓ Environmental Science
- ✓ Lithologic Logging
- ✓ Geologic Mapping

EST. 1968
PROVOST& PRITCHARD
CONSULTING GROUP
An Employee Owned Company

Professional Summary

Darylyn Tachella is a senior geologist at Provost & Pritchard with 9 years of experience in the field of environmental engineering. She has experience in soil characterization, soil and groundwater sampling, environmental remediation, drainage and percolation investigation, and well installations. She is practiced in project coordination, in-field judgment calls, and report preparation.

Relevant Experience

Environmental Site Assessment: Phase I and Phase II, Various Clients, Associate Geologist – Ms. Tachella has conducted over 75 Phase I and Phase II Environmental Site Assessments (ESA). The Phase I work includes historical records search, site reconnaissance, and report preparation. Phase II work includes sampling plans, sample collection, and reporting findings.

610 Pacheco Boulevard Environmental Site Assessment, City of Los Banos, California, Project Geologist – Ms. Tachella conducted a Phase I Environmental Site Assessment (ESA) at the site. Based on the findings of the Phase I ESA, the City requested a Phase II ESA. Ms. Tachella conducted the Phase II work, including soil and soil vapor sampling at the site and a report of the findings.

Stockton Avenue Rehabilitation Project Initial Site Assessment, City of Ripon, Associate Geologist – Ms. Tachella conducted an Initial Site Assessment (ISA) for the City of Ripon for a street rehabilitation project. The goal of the ISA was to identify the potential for hazardous materials or waste before the rehabilitation project was underway. The scope of work included database and historical records reviews, site reconnaissance, and a report of findings. The report was submitted to Caltrans by the client and subsequently approved.

Colony-Hoff Traffic Signal Project Initial Site Assessment, City of Ripon, Associate Geologist & Project Manager – After the Stockton Avenue ISA, Ms. Tachella conducted and managed another ISA for the City of Ripon for a traffic signal installation project. The goal of the ISA was to identify the potential for hazardous materials or waste before the rehabilitation project was underway. The scope of work included database and historical records reviews, site reconnaissance, and a report of findings. The report was submitted to Caltrans by the client and subsequently approved.

Bridge Rehabilitation Project Hazardous Materials Memo, City of Madera, Associate Geologist – Ms. Tachella prepared a hazardous materials technical memorandum for a bridge rehabilitation project for the City of Madera. The memo provided information on hazardous materials and waste that would potentially be encountered during the rehabilitation project. It also provided recommendations on the management of hazardous materials or waste if encountered or generated.

Former Pacheco Oil Site, Kosmont Companies, Madera County, California, Associate Geologist – Ms. Tachella assited with the cleanup services of a former oil site located in Merced County. The project includes groundwater well installation, sampling and reporting, remediation of arsenic and hydrocarbons in the soil and groundwater. Site closure has been requested of the regulator.

Los Banos Rail Trail Arsenic Remediation, Kosmont Companies, Los Banos, California, Project Geologist – Ms. Tachella assisted with assessment and cleanup of soil conditions as it relates to arsenic affected soil along the Rail Trail corridor park. The site consists of miles of trail with varying soil conditions.

Work at the site included coordination with the Regional Water Quality Control Board (RWQCB), extensive soil sampling for analysis, data evaluation and reporting, excavation of impacted soils, development of a soil management plan, and the development of land use covenants, ultimately leading to No Further Action Determinations from the RWQCB.

DJR (Johnston) Ranch Remediation, Sun Pacific Farming, Dinuba, California, Project Manager – Ms. Tachella is the project manager and technical lead for the former aboveground storage tank site. Work on the project has included review of previous technical report, additional soil and groundwater assessment, and preparation and implementation of a Corrective Action Plan. The project is currently undergoing remediation with groundwater and soil gas monitoring.

PCE Assessment and Cleanup, City of Merced, California, Associate Geologist – Ms. Tachella is assisting with the quarterly reporting required as part of the PCE (dry cleaning solvent) soil and groundwater cleanup program involving six dry cleaners in the downtown area of the City of Merced. The reporting consists of intensive quality assurance/quality control reviews of data gathered by others, quarterly generation of perchloroethylene (PCE) isopleths and groundwater maps for several identified aquifer zones, and hydrographs for shallow zone wells. Quarterly PCE and groundwater data is analyzed with respect to hydrostratigraphical setting, monitoring well construction details, and historical data to determine trends. The report is prepared on behalf of the City of Merced and is submitted to the Central Valley Regional Water Quality Control Board.

Proposition 1 Planning Grant, Downtown Turlock PCE Project, City of Turlock, Associate Geologist – Ms. Tachella was part of a team that conducted remedial investigation (RI) and a feasibility study (FS) for PCE contamination in groundwater in the Downtown Turlock area. Provost & Pritchard assisted the City of Turlock with securing a Proposition 1 Groundwater Cleanup planning grant for approximately $1,500,000 for the RI/FS. The RI consisted of the drilling, installation, and sampling of more than 30 new shallow and deep groundwater monitoring wells, 75 passive soil gas samplers, and 52 active soil gas probes. Based on the data from the RI, Provost & Pritchard prepared the FS. The FS compiled the data into a conceptual site model (CSM), which allowed for an interpretation of the PCE releases. The CSM informed the evaluation of many remedial alternatives, resulting in the selection of a hybrid approach which will address site specific source cleanup, the reduction of indoor health risk, localized pump & treatment of impacted groundwater, and the drilling of two new City Supply wells with wellhead treatment as part of a hydraulic containment strategy.

Groundwater Recharge Soil Investigation, Various Clients, Associate Geologist – Ms. Tachella has assisted on various soil investigations for siting of groundwater recharge ponds. The work has generally included site selection, soil logging, and reporting findings and recommendations.

Seepage Management for San Joaquin River Restoration Program, United States Bureau of Reclamation, CDM Smith, Merced County, California, Associate Geologist – Ms. Tachella assisted the U.S. Bureau of Reclamation and the prime contractor staff in seepage management support on the San Joaquin River and bypasses. The scope of work generally includes site evaluations, baseline monitoring, and preliminary and 60% project designs. Specific work has included monitoring of shallow groundwater wells, review of data collection methods reports, agronomic evaluations, preparation of geologic logs and soil sampling from monitor wells and hydraulic conductivity testing, and preparation of appraisal level designs for farms impacted by seepage due to restoration flows.

Wawona Wastewater Treatment Plant, Architectural Resources Group, Yosemite National Park, Associate Geologist – Ms. Tachella assisted on the field investigation for the siting of the treated waste water disposal system. Ms. Tachella was involved with the preliminary soil logging, installation of groundwater piezometers, in-situ percolation testing, and groundwater level data collection.

Crows Landing Industrial Business Park Test Wells, E-Pur, Stanislaus County, California, Associate Geologist – Ms. Tachella assisted with the groundwater supply exploration for a proposed business park near Crows Landing. The work included preliminary hydrogeologic investigation, exploratory drilling, installation of 6 test wells, and water quality and production testing. Ms. Tachella was involved with preliminary research, litholigic logging of exploratory boreholes, and testing of aquifer production and water quality in the test wells.

Well 7 Design, Riverdale Public Utilities District, Riverdale, California, Associate Geologist – Ms. Tachella assisted with the exploration and testing for a municipal well in Riverdale, California. The well was installed to provide higher quality water to the community of Riverdale. This project involved geologic logging of soils, test well installation, zone testing of water quality, and final well installation. Ms. Tachella's responsibilities included geologic logging, construction oversight of the test well, water quality sampling of test well zones, and well pump testing of the final well.

Stephanie Gillaspy, EIT

Project Manager

Education

- ✓ Master's in Business Administration, University of Phoenix, Fresno, California
- ✓ B.S. Environmental Engineering, University of California, Riverside

Registration/Certifications

- ✓ Engineer-in-Training, California #122205
- ✓ HAZWOPER (40 hours)

Areas of Expertise

- ✓ Phase I & II Environmental Site Assessments
- ✓ Groundwater Assessments
- ✓ Remediation Systems
- ✓ Reports of Waste Discharge
- ✓ Site Plan Reviews

EST. 1968
PROVOST& PRITCHARD
CONSULTING GROUP
An Employee Owned Company

Professional Summary

Stephanie Gillaspy is an assistant engineer and environmental specialist at Provost & Pritchard, with over 16 years of experience in project management, RWQCB compliance and permitting, environmental assessment and remediation field activities. She is knowledgeable of regulatory issues with the RWQCB, the SJVAPCD, and Central Valley cities and counties. Ms. Gillaspy has worked extensively with the RWQCB since the beginning of her career, knows many of the RWQCB staff, and understands how they regulate.

She has completed over 150 Phase I and Phase II environmental site assessments including field experience, and planning experience in the preparation of site plan review documents. Ms. Gillaspy is an excellent project manager with skills in managing schedule, budget, and project teams, and has a great track record of delivering numerous quality deliverables for clients and helping to navigate complex permitting processes.

She also was involved with the creation in 2009 of a weekly training program internal to Provost & Pritchard titled the University of Provost. She has served as 'chancellor' since its inception, spearheading the scheduling of presenter and student signups, follow-up class quizzes, and an awards program based on level of participation. The longevity of the program is testament to its popularity among the employees.

Relevant Experience

Phase I ESA for Future Municipal Well Sites, City of Fresno, California, Project Manager – Ms. Gillaspy was responsible for overseeing the preparation of four Phase I ESAs for the City of Fresno's Water Division. The property assessed was for future municipal well sites on San Madele Avenue, Bullard Avenue, Sussex Avenue and Weber Avenue. The San Madele and Bullard Avenue sites contained houses to be demolished if the test well produced sufficient clean water. The houses were in good condition but built in the late 1970s, so lead-based paint and asbestos-containing materials testing was recommended before the demolition of the house. The Sussex Avenue property was an empty lot between businesses. The Weber Avenue property was a gas station constructed in the 1960s. No records indicated that the underground storage tanks were removed. Ground Penetrating Radar (GPR) was recommended to locate underground storage tanks. All four Phase Is were completed within a short time frame and under budget.

Phase I ESA for Treat Property, City of Merced, California, Project Manager – Ms. Gillaspy was responsible for the preparation of an All Appropriate Inquiry (Phase I ESA) for property the City of Merced was in the process of purchasing for the expansion of Yosemite Avenue at the intersection with Highway 59. Multiple APNs assigned to the property over the years made it difficult to track down historical records. An unused water well was located onsite and recommended to be properly destroyed prior to construction of the road expansion.

Phase II & Phase III PCE Remediation System Optimization and Groundwater Monitoring and Reporting in Downtown Turlock, City of Turlock, California, Environmental Specialist – Ms. Gillaspy provided environmental services for this optimization project in order to increase the rate of removal of perchloroethylene (PCE) contamination in the groundwater by increasing the pump rate of the City's existing remediation system's shallow tray

air stripper. Further, this project includes associated groundwater monitoring over a three-year period to assess the effectiveness of the remediation system by measuring concentrations of PCE, TCE, and other related breakdown chemicals within downtown Turlock. Provost & Pritchard is currently in the second year of this three-year project.

R Street TPH and Related Compounds Environmental Assessment & Remedial Services, Kosmont Companies, Merced, California, Environmental Specialist – Ms. Gillaspy is currently providing environmental assessment, cost analyses, feasibility and remedial services for the City of Merced's Redevelopment Agency at the R Street TPH site (including a 1,000 foot MTBE plume) project. Key tasks included project management; invoicing, scheduling and coordination of subcontractors and field crews, and quarterly reporting. Also included were preparation of water quality studies associated with City Well No. 5; preparation of work plans and permits for drilling and monitoring well installation; health and safety plans; traffic control plans; conducting quarterly groundwater sampling; and air quality sampling. She is also responsible for coordinating communication with the RWQCB, the preparation of a focused feasibility study, the preparation of the Final Remedial Plan (FRP), and implementation of the selected remedial option for the project site.

Hartley Slough Site Mitigation, City of Merced, California, Project Manager – Ms. Gillaspy is leading the environmental mitigation services tasks provided to the City of Merced in connection with the Hartley Slough Solid Waste Facility. The project site is located southeast of the former City of Merced Municipal Dump Site The dump site ceased operation and was closed over in the mid 1970's. Today, the dump site is closed and surrounded by a chain-link fence for site security and is periodically inspected by the Merced County Division of Environmental Health's (MCDEH) Local Enforcement Agency solid waste program staff. MCDEH staff observed debris at the ground surface during a site inspection of the adjacent closed solid waste facility in 2009, prompting the need to construct a cover for the former dump site. The project includes the design of the cover as well as the excavation of the top 12 inches of soil that may have been impacted by debris. An environmental document was also prepared as part of the project to assess the environmental impacts on the site.

Phase I & II Environmental Site Assessments, Industrial Building, Fresno, California, Project Manager – Ms. Gillaspy led the project team responsible for the completion of Phase I and II ESAs of a 50,000-square-foot industrial property located adjacent to railroad tracks in Fresno, California. The owner provided Phase I ESA and Phase II ESA to our client which identified RECs on site that appeared to warrant further investigation. Additional areas of concern were identified after a site visit and review of the Phase I and II. Ms. Gillaspy recommended that soil samples up to 20 feet below ground surface should be collected and analyzed for petroleum hydrocarbons and Stoddard solvents at several locations due to the potential of releases based on the historical use and businesses identified in the area. A lead-based paint and asbestos containing materials survey were also recommended and completed within the project timeline. Additional investigation into the onsite underground storage tank (UST) was completed by discussion closure options with the Fresno County Environmental Health Department. Based on the location of the UST, the best option for abandonment was in-place closure once it has been verified the soil was clean surrounding the UST. Geoprobe drilling down to 20 feet below ground surface soil samples were collected for this investigation. Chemicals of concerns were identified in additional locations identified in the Phase II ESA provided by the owner. Upon receiving the laboratory results for the drilling, our client decided against purchasing the property due to future liability.

Phase I ESA, Academy Ranch, Clovis, California, Project Manager – Ms. Gillaspy conducted a Phase I ESA for property located southeast of McKinley Avenue and Academy Avenue in Fresno County. Academy Ranch is in the process of purchasing the parcel and was in need of a Phase I.

Fresno County Environmental Landfill Project, Project Manager

Upon working with Fresno County Environmental Health Division on another project, we were approached by FCEH to develop a database that could easily show the landfills in northeast Fresno near Palm and Nees Ave. Numerous landfills were nearly on top of each other and no historical information was easily accessible. Extensive research was done on each landfill to show maps, project history as well as current APNs that could be impacted by the landfills. P&P staff developed a GIS platform that could easily show if any APN in the area could have been impacted by the landfills in the area. The GIS platform was well received by Fresno County and it now part of their internal website.

Palm Bluffs West, TCE Investigation, Project Manager

Upon discovery of the Camp Pinedale incinerator on the property during a Phase I investigation, soil gas sampling was completed to estimate volume and a soil vapor extraction system has been installed and operated to remove Trichloroethylene (TCE) from the site. The incinerator was unknown to the current owner so P&P staff have been working with the owner in the remediation stages.

Phase I ESA for Future Municipal Well Sites, City of Fresno, California, Project Manager – Ms. Gillaspy was responsible for overseeing the preparation of four Phase I ESAs for the City of Fresno's Water Division. The property assessed was for future municipal well sites on San Madele Avenue, Bullard Avenue, Sussex Avenue and Weber Avenue. The San Madele and Bullard Avenue sites contained houses to be demolished if the test well produced sufficient clean water. The houses were in good condition but built in the late 1970s, so lead-based paint and asbestos-containing materials testing was recommended before the demolition of the house. The Sussex Avenue property was an empty lot between businesses. The Weber Avenue property was a gas station constructed in the 1960s. No records indicated that the underground storage tanks were removed. Ground Penetrating Radar (GPR) was recommended to locate underground storage tanks. All four Phase Is were completed within a short time frame and under budget.

Phase I ESA for Treat Property, City of Merced, California, Project Manager – Ms. Gillaspy was responsible for the preparation of an All Appropriate Inquiry (Phase I ESA) for property the City of Merced was in the process of purchasing for the expansion of Yosemite Avenue at the intersection with Highway 59. Multiple APNs assigned to the property over the years made it difficult to track down historical records. An unused water well was located onsite and recommended to be properly destroyed prior to construction of the road expansion.

Phase II & Phase III PCE Remediation System Optimization and Groundwater Monitoring and Reporting in Downtown Turlock, City of Turlock, California, Environmental Specialist – Ms. Gillaspy provided environmental services for this optimization project in order to increase the rate of removal of perchloroethylene (PCE) contamination in the groundwater by increasing the pump rate of the City's existing remediation system's shallow tray air stripper. Further, this project includes associated groundwater monitoring over a three-year period to assess the effectiveness of the remediation system by measuring concentrations of PCE, TCE, and other related breakdown chemicals within downtown Turlock. Provost & Pritchard is currently in the second year of this three-year project.

Phase I ESA along Dakota Avenue, Community Regional Medical Center, Fresno, California, Project Manager – Ms. Gillaspy was responsible for conducting a Phase I ESA at 1925 E. Dakota Avenue on the Community Regional Medical Center campus in Fresno. Historical records indicated a UST was onsite in the 1970's but further investigation found the UST had been properly removed with clean soil samples. An additional lead based paint and asbestos containing materials survey was recommended based on the age of the property.

Phase I & II Environmental Site Assessments, Industrial Building, Fresno, California, Project Manager – Ms. Gillaspy led the project team responsible for the completion of Phase I and II ESAs of a 50,000-square-foot industrial property located adjacent to railroad tracks in Fresno, California. The owner provided Phase I ESA and Phase II ESA to our client which identified RECs on site that appeared to warrant further investigation. Additional areas of concern were identified after a site visit and review of the Phase I and II. Ms. Gillaspy recommended that soil samples up to 20 feet below ground surface should be collected and analyzed for petroleum hydrocarbons and Stoddard solvents at several locations due to the potential of releases based on the historical use and businesses identified in the area. A lead-based paint and asbestos containing materials survey were also recommended and completed within the project timeline. Additional investigation into the onsite underground storage tank (UST) was completed by discussion closure options with the Fresno County Environmental Health Department. Based on the location of the UST, the best option for abandonment was in-place closure once it has been verified the soil was clean surrounding the UST. Geoprobe drilling down to 20 feet below ground surface soil samples were collected for this investigation. Chemicals of concerns were identified in additional locations identified in the Phase II ESA provided by the owner. Upon receiving the laboratory results for the drilling, our client decided against purchasing the property due to future liability.

Phase I Environmental Site Assessment, Gateway Village, Madera, California, Environmental Specialist – Ms. Gillaspy was responsible for the completion of an environmental site assessment for a proposed master-planned community covering over 2,000 acres.

Phase I Environmental Site Assessment, Ito Packing Company, Reedley, California, Environmental Specialist – This project consisted of completing an environmental site assessment for an existing packing plant. Historical underground storage tanks were removed prior to permits. Ms. Gillaspy worked closely with the client to complete the report in a short timeframe.

Phase I Environmental Site Assessment, Kings River Resorts, Inc, Kingsburg, California, Environmental Specialist – Ms. Gillaspy completed an environmental site assessment for an existing recreational vehicle park along the Kings River. She worked closely with the client to complete the report in a short timeframe.

Kings County Site Plan Review, Southeast Ranch, Stratford, California, Environmental Specialist – Ms. Gillaspy was responsible for project planning and completing a site plan review application to Kings County standards. She also completed the report of waste discharge for the client for submittal to the Regional Water Quality Control Board. A preliminary nutrient management plan and a waste management plan were completed. The project included perched groundwater constraints.

Kings County Site Plan Review, John L. Fragoso & Sons Dairy, Hanford, California, Project Manager – Ms. Gillaspy was responsible for project planning and completing a site plan review application for an expanding dairy to the Kings County standards. She also completed the report of waste discharge for the client for submittal to the Regional Water Quality Control Board. During this project, a preliminary nutrient management plan and waste management plan were completed.

Water Supply Study, White Paper, City of Clovis, California, Project Engineer – Ms. Gillaspy assisted the project manager in completing a water supply study report for the City of Clovis. Project responsibilities also included the preparation of Power Point slides for presentations to the City.

Report of Waste Discharge, Riverstone (formerly known as Gateway Village), County of Madera, California, Project Engineer – Ms. Gillaspy prepared a report of waste discharge for submittal to the Regional Water Quality Control Board. The report included water balance calculations to determine nutrient loading, percolation rates, and storage capacities.

Groundwater Monitoring Network Plan, Ito Packing Company, Reedley, California, Project Engineer – Ms. Gillaspy worked with the Regional Water Quality Control Board to obtain approval for a monitoring well network plan for land disposal area. The project included the installation of three monitoring wells on-site, and completion of a post-construction report for the monitoring well.

Phase II Environmental Site Assessment, Rosendahl Dehydrator, Caruthers, California, Environmental Specialist – This project consisted of the completion of an environmental site assessment and cleanup of diesel impacted soils. Ms. Gillaspy's project responsibilities included coordination with the Regional Water Quality Control Board to complete cleanup of the site in less than two months.

Report of Waste Discharge, Batth Dehydrator, Caruthers, California, Project Manager – Ms. Gillaspy provided regulatory compliance assistance to the client in a short timeframe in order to guarantee financing for purchase of the dehydrator. In order to achieve this, a new waste discharge permit was needed. While working with the Regional Water Quality Control Board, the report of waste discharge was deemed complete within 30 days of submittal.

Report of Waste Discharge, Sunview Cold Storage, Kern County, California, Project Manager – Ms. Gillaspy was responsible for Regional Water Quality Control Board compliance for adding a reverse osmosis unit to a system operation. The report included water balance calculations to determine nutrient loading rates for associated cropland.

Groundwater Monitoring Network Plan, Del Rey Packing, Del Rey, California, Project Manager – Ms. Gillaspy worked with the Regional Water Quality Control Board to obtain approval for a monitoring well network plan for a land disposal area. The project included installation of three monitoring wells on-site and completion of a post-construction report for the monitoring well.

Kings County Site Plan Review, David teVelde Dairy, Hanford, California, Project Manager – Ms. Gillaspy was responsible for project planning and completing a site plan review application to the Kings County standards. During this project, Ms. Gillaspy completed an updated a report of waste discharge for the client for submittal to the Regional Water Quality Control Board. The project included 100-year flood zone issues. A preliminary nutrient management plan and waste management plan were also completed.

Kings County Site Plan Review, Lakeview Calf Ranch, Hanford, California, Project Manager – Ms. Gillaspy was responsible for project planning and completing a site plan review application to the Kings County standards. As part of this project, a report of waste discharge was completed for client for submittal to the Regional Water Quality Control Board. A preliminary nutrient management plan and waste management plan were also completed.

Underground Storage Tank Cleanup, Redevelopment Agency, City of Merced, California, Project Manager – This project consists of the clean-up of impacted groundwater and soil, and maintenance of the soil vapor extraction (SVE) system operation. Ms. Gillaspy has been responsible for coordination of the installation of a new ozone sparge system with multiple subcontractors. In addition, she has maintained constant contact with the client throughout the process, and performs quarterly groundwater monitoring and prepares reports for the Regional Water Quality Control Board. Ms. Gillaspy also prepared a feasibility study, a final remediation plan, and remediation system updates.

PCE Remediation and Reporting, Seven Dry Cleaners, City of Merced, California, Project Manager – Based on the Regional Water Quality Control Board settlement agreement with the City of Merced, seven different dry cleaner sites were evaluated to determine the level of importance to remediate the impact of perchloroethylene (PCE). Working closely with the City of Merced's annual work plan, Parkway Cleaners was determined to be the highest importance for remediation. The SVE system was upgraded to include more vapor wells, and an ozone sparge system was installed. The SVE wells were added to the operation in December 2009, and ozone sparge wells will be added accordingly. Quarterly monitoring reports and sampling are also coordinated and submitted to the Regional Water Quality Control Board.

Phase I & II Environmental Site Assessments for Crop Dusting Facility, Western Fresno County, California, Technical Reviewer – Ms. Gillaspy is currently providing technical oversight and reviews for a Phase I ESA and a limited Phase II ESA for a western agriculture aviation property in western Fresno County. The property includes a crop dusting airport and runway. Based on the history of the site, soil samples were taken in areas of potential contamination. Significant detections for Toxaphene and Endosulfan were found in various places. Price estimates were calculated to estimate the approximate cost to clean up the contaminants of concern.

Preliminary Environmental Assessment (PEA) for Proposed New Elementary School Site, Sanger Unified School District, Sanger, California, Ms. Gillaspy was involved with the scoping and implementation of a PEA work plan and subsequently prepared the draft PEA for the proposed school site on a rural residence and farm property. This work incorporated Incremental Sampling Mythology (ISM) for former structural areas of the site. Potential chemicals of concern included organochlorine pesticides (OCP) and select metals. Over 545 soil samples were collected on the 12 acres The draft PEA concluded that the reported chemical concentrations are not at hazardous levels nor do they exceed health-risk based screening levels. Consequently, a No Further Action determination will be pursed from the DTSC. The draft PEA was made available for public review by the School District. A final PEA was submitted to DTSC for their final approval.

Tulare Lakes Basin Water Study, County of Tulare, California, Assistant Engineer – Ms. Gillaspy is providing assistance with the development of pilot reports, including implementation strategies and recommendations for establishing and upgrading water and wastewater infrastructure in disadvantaged communities within the Tulare Lake Basin. The Tulare Lake Basin encompasses disadvantaged communities within the four counties of Kern, Kings, Tulare, and Fresno. The plan addresses various potential solutions to secure safe and affordable drinking water along with adequate and affordable wastewater treatment and disposal systems for these communities.

David Norman

Environmental Specialist

Education

- ✓ B.S. Geology, San Jose State University, California
- ✓ B.A. Management & Organizational Development, Fresno Pacific University, California

Registration/Certifications

- ✓ HAZWOPER (40 hours)

Affiliations

- ✓ National Water Well Association
- ✓ Mountain Counties Water Resources Association
- ✓ Groundwater Resources Association

Areas of Expertise

- ✓ Expert Witness in Site Assessments
- ✓ Groundwater Monitoring
- ✓ Groundwater Quality
- ✓ Environmental Site Assessments
- ✓ Environmental Remediation
- ✓ Brownfields Studies
- ✓ Environmental Science
- ✓ Public Outreach

EST. 1968
PROVOST& PRITCHARD
CONSULTING GROUP
An Employee Owned Company

Professional Summary

Dave Norman has over 30 years of experience providing environmental and engineering consulting services for clients throughout California. His expertise encompasses regulatory compliance, site assessments, human health risk assessments, and remedial action. In addition, he has managed a wide range of Brownfields and redevelopment projects for many small to medium-sized cities in the central valley. Brownfields projects have ranged from significant gasoline impacts requiring assessment and remediation to the simultaneous assessment and cleanup of seven dry cleaner sites. Mr. Norman has extensive experience with a wide range of environmental assessment and compliance for project sites such as processing locations for a large winery organization, former firing ranges, burn dumps, and landfills. He also has experience with civil and development projects including pavement assessments and management plans for Yosemite National Park.

Mr. Norman has represented clients in front of city councils and county counsels, school boards, and state and federal agencies such as the U.S. Environmental Protection Agency, Regional Water Quality Control Board (RWQCB) and California Department of Toxic Substance Control (DTSC).

Relevant Experience

Phase I, Phase II and Risk Assessments

Phase I Environmental Site Assessment for San Madele Well Site, City of Fresno, California, Technical Reviewer – Mr. Norman provided technical oversight and reviews for the preparation of a Phase I environmental site assessment (ESA) for the City of Fresno's Water Division. The property assessed was for a new domestic well site on San Madele Avenue. The house was to be demolished if the test well drilled produced sufficient clean water. Recommendations were given based on the plan for the house. The house was in good condition but built in 1979, so lead-based paint and asbestos containing materials testing was recommended before the demolition of the house. The Phase I ESA was completed within a short timeframe and under budget.

Phase I & II Environmental Site Assessments for Crop Dusting Facility, Western Fresno County, California, Technical Reviewer – Mr. Norman is currently providing technical oversight and reviews for a Phase I ESA and a limited Phase II ESA for a western agriculture aviation property in western Fresno County. The property includes a crop dusting airport and runway. Based on the history of the site, soil samples were taken in areas of potential contamination. Significant detections for Toxaphene and Endosulfan were found in various places. Price estimates were calculated to estimate the approximate cost to clean up the contaminants of concern.

Phase I & II Environmental Site Assessments, Marl Springs, Mojave National Preserve, Mojave, California, Project Manager – Mr. Norman was responsible for completing a Phase I and II ESA and a human health risk assessment of a historic mine. The Marl Springs area of the Mojave National Preserve is the site of the only potable water supply for over 100 miles. The spring was used by early California explorers and mule trains to rest and water horses. Marl Springs is also the site of historic gold and silver mining. The Mojave National Preserve discovered that lead and other heavy metals were present in elevated concentrations requiring further action. The main concerns were whether the concentrations were a human or ecological risk to visitors and

the endangered desert tortoise that occupied the park. A human health risk assessment was conducted. In addition, a visitor study to evaluate the visitor travel patterns through the area was conducted. The combination of both studies was used to develop a site specific exposure scenario which showed that the exposure thresholds for lead and other heavy metals were below human health risk levels, and the ecologic risk was low for the desert tortoise and other animals because the limited uptake of metals by native plants was insignificant.

Hazardous Waste Evaluations, Red Fir Maintenance Facility, Sequoia National Park, California, Project Manager – Mr. Norman conducted several soil assessments at the Red Fir facility in support of a waste management program to evaluate potential locations for historic dumping of waste chemicals and hydrocarbons. As a result of the assessments, the area was cleared of potential remediation or other actions.

Phase II Environmental Site Assessment, Health Risk Assessment and Site Closure, Zymex Industries, Merced, California, Project Manager – Zymex Industries was interested in purchasing a parcel of land at the Airport Redevelopment Business Park from the City of Merced to construct a new tomato processing plant. The parcel and surrounding area was the location of the former Merced Rod and Game Club. For over 50 years, skeet and trap shooting was conducted at the site. Elevated concentrations of lead from the accumulations of lead shot and bullets were detected at the site after the City had conducted several remediation efforts. Mr. Norman assisted the client with formulating an agreement with the DTSC to provide oversight for a self-directed assessment, human health risk assessment and site closure through the department's voluntary cleanup program. Over 75 samples were collected and analyzed for lead, nickel and other compounds associated with clay pigeons and ammunition. On the basis of the results, a human health risk assessment was prepared finding no significant increase in risk. The DTSC issued a site closure letter free of title restrictions and the tomato packing plant was constructed.

Pollution Prevention Planning, Sequoia and Kings Canyon National Park, California, Project Manager, Lead Technical Writer – For this project, Mr. Norman focused on documenting and evaluating the waste streams for the Sequoia and Kings Canyon National Parks and developing waste minimization strategies, recycling opportunities and waste reuse plans. All of the parks' facilities including maintenance, water treatment and wastewater treatment facilities, and former landfill sites were reviewed for chemical and non-chemical waste. The project resulted in the publishing of park-wide Pollution Prevention Opportunity Assessment, and the implementation of new waste minimization programs including a one-pound propane cylinder disposal education program.

Total Petroleum Hydrocarbon Soil Assessment, Sequoia National Park, Crystal Cave, California, Project Manager– Crystal Cave is one of many naturally sensitive caves located in the Sequoia and Kings Canyon National Parks, and is one of only two open to the public for guided tours. In the early 1900s, the park installed a generator to provide electric power to a lighting system. Due to its remote location and difficult access all fuel was hand carried to the site. In the 1940s, an in-ground power line was installed and the generator was removed from service but left in place. Over the years the generator deteriorated and the remaining fuel and oil leaked from its tanks. In 2005, the park dismantled the generator and removed it by hand. During the process impacted soil was encountered underneath and surrounding the generator. Mr. Norman assisted the park in assessing the extent of impact and negotiated with the local county to allow for the impacted soil to be removed slowly (bucket by bucket) during the closed season and stored to later use in asphalt for park road projects. Over two closed (winter) seasons the soil was removed and the project was closed by the county. All equipment, including waste, samplers and replacement soil, was hand carried to the site in buckets with a 20 pound weight limit.

Environmental Assessment & Remedial Services, City of Merced, California, Principal-in-Charge – Mr. Norman is responsible for overseeing environmental assessment and remedial services for the City of Merced's R Street leaking UST assessment, remediation and site closure project. Project responsibilities include project and funding management (Brownfields Cleanup Grant, UST Fund and city redevelopment funds), quarterly monitoring and reporting, communication with the RWQCB, preparation of a focused feasibility study, groundwater monitoring, and the preparation of the final remedial plan (FRP) and implementation of the selected remedial remedy for the project site. The site is comprised of two gasoline stations and a total petroleum hydrocarbons (TPH) and methyl tert-butyl ether (MTBE) plume over half a mile in length. The remedial action includes the installation and operations of two soil vapor extraction (SVE) and ozone injection systems.

Appendix A Figures

Vicinity Map

Site Map



Vicinity Map

Frank Wilson Road, Mariposa CA - Phase I ESA

PROVOST& PRITCHARD

3/23/2026 \\EgnyteDrive\Clients\Mariposa County-1542\154226001-Phase I Mariposa Co\400 GIS\Map\Phase1_Maps.aprx



0 50 100

US Feet

Site Map

Frank Wilson Road, Mariposa CA - Phase I ESA

PROVOST& PRITCHARD

3/23/2026 \\EgnyteDrive\Clients\Mariposa County-1542\154226001-Phase I Mariposa Co\400 GIS\Map\Phase1_Maps.aprx

Appendix B User Responsibilities

EDR Environmental Lien and AUL Search

User Questionnaire

MARIPOSA COUNTY
FRANK WILSON RD
MARIPOSA, CA 95338

Inquiry Number: 8280255.8S
MARCH 18, 2026

EDR Environmental Lien and AUL Search 1980

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search 1980

The EDR Environmental Lien and AUL Search 1980 Report provides results from a search of available land title records for environmental cleanup liens and other activity and use limitations (AULS), such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address information to:

- search for parcel number and/or legal description
- search for ownership information filed between 1980 and present
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc
- search for publicly available environmental encumbering instrument(s) filed between 1980 and present
- provide a copy of any environmental encumbrance(s)
- provide a copy of the current deed when available

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer – Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC and AFX Research, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search 1980

TARGET PROPERTY INFORMATION

ADDRESS

MARIPOSA COUNTY
FRANK WILSON RD
MARIPOSA, CA 95338

PROPERTY DESCRIPTION

Current Owner: THOMAS P. RITTER, LORI L. RITTER
Legal Description: AS RECORDED IN THE DEED ATTACHED.
Property Identifier(s): 013-011-0030
General Comments: NA

FINDINGS SUMMARY

ADDITIONAL DETAILS MAY BE FOUND IN THE 'FINDINGS DETAIL' SECTION.

Parcel: 013-011-0030

Environmental Lien: ☐ Found ☒ Not Found

Other Activity and Use Limitations (AUL): ☐ Found ☒ Not Found

HISTORICAL CHAIN OF TITLE FROM 1980

RECORDED	INSTRUMENT	GRANTEE	GRANTOR
05/05/2011	20111601	THE RITTER FAMILY TRUST	THOMAS P. RITTER, LORI L. RITTER
01/18/2007	2070354	THOMAS P. RITTER, LORI L. RITTER	THE DAVID ANTHONY AND HEIDI YVONNE RADANOVICH TRUS
04/29/2005	2052960	THE MARK A. RADANOVICH AND CHRISTINE D. RADANOVICH	MARK A. RADANOVICH, CHRISTINE D. RADANOVICH
09/26/2003	2036913	DAVID A. RADENOVICH, HEIDI Y. RADENOVICH	THE KENNETH MARI AND LAMERNA MARI 1990 TRUST
09/15/1994	944827	THE DAVID ANTHONY AND HEIDI Y. RADANOVICH TRUST (2	THE LULA BELLE HOULIHAN REVOCABLE LIVING TRUST
05/18/1992	923309	THE LULABELLE HOULIHAN REVOCABLE LIVING TRUST	LULABELLE HOULIHAN
05/18/1992	923308	THE LULABELLE HOULIHAN REVOCABLE LIVING TRUST	LULABELLE HOULIHAN
08/24/1990	995409	THE KENNETH MARI AND LAMEIRA MARI 1990 TRUST	KENNETH MARI, LAMEMA MARI

RESEARCH SOURCES

JUDICIAL RECORDS ***NOT*** SEARCHED. BASED ON AVAILABLE INFORMATION EVALUATED BY THE TITLE SEARCH PROFESSIONAL, THE JURISDICTION ***DOES NOT*** REQUIRE A SEARCH OF JUDICIAL RECORDS IN ORDER TO IDENTIFY ENVIRONMENTAL LIENS.

Source 1: MARIPOSA COUNTY RECORDER'S OFFICE
Source 2: MARIPOSA COUNTY ASSESSOR'S OFFICE
Source 3: CALIFORNIA ENVIRONMENTAL PROTECTION AGENCY
Source 4: UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Examiner's Note: PUBLIC RECORDS OF MARIPOSA COUNTY, CA WERE SEARCHED FROM JANUARY 1, 1980 TO MARCH 3, 2026, AND NO OTHER DEEDS VESTING TITLE IN THE SUBJECT PROPERTY WERE FOUND OF RECORD DURING THE PERIOD SEARCHED.

EDR Environmental Lien and AUL Search 1980

FINDINGS DETAIL

Parcel: 013-011-0030

ENVIRONMENTAL LIEN

Environmental Lien: ☐ Found ☒ Not Found

Comments: NONE IDENTIFIED.

EDR Environmental Lien and AUL Search 1980

OTHER ACTIVITY AND USE LIMITATIONS (AULS)

Other AULs: ☐ Found ☒ Not Found

Comments: NONE IDENTIFIED.

EDR Environmental Lien and AUL Search 1980

HISTORICAL CHAIN OF TITLE FROM 1980

CHAIN 1

Type of Deed:	GRANT DEED
Title is vested in:	THE RITTER FAMILY TRUST
Title received from:	THOMAS P. RITTER, LORI L. RITTER
Date Executed:	05/03/2011
Date Recorded:	05/05/2011
Book:	NA
Page:	NA
Instrument#:	20111601
Land Record Comments:	

CHAIN 2

Type of Deed:	GRANT DEED
Title is vested in:	THOMAS P. RITTER, LORI L. RITTER
Title received from:	THE DAVID ANTHONY AND HEIDI YVONNE RADANOVICH TRUST (2/3 INTEREST), THE MARK A. RADANOVICH AND CHRISTINE D. RADANOVICH 2005 REVOCABLE FAMILY TRUST (1/3)
Date Executed:	01/16/2007
Date Recorded:	01/18/2007
Book:	NA
Page:	NA
Instrument#:	2070354
Land Record Comments:	

CHAIN 3

Type of Deed:	GRANT DEED
Title is vested in:	THE MARK A. RADANOVICH AND CHRISTINE D. RADANOVICH 2005 REVOCABLE FAMILY TRUST
Title received from:	MARK A. RADANOVICH, CHRISTINE D. RADANOVICH
Date Executed:	04/20/2005
Date Recorded:	04/29/2005
Book:	NA
Page:	NA
Instrument#:	2052960
Land Record Comments:	

CHAIN 4

Type of Deed:	GRANT DEED
Title is vested in:	DAVID A. RADENOVICH, HEIDI Y. RADENOVICH
Title received from:	THE KENNETH MARI AND LAMERNA MARI 1990 TRUST
Date Executed:	09/15/2003
Date Recorded:	09/26/2003
Book:	NA
Page:	NA
Instrument#:	2036913
Land Record Comments:	

EDR Environmental Lien and AUL Search 1980

CHAIN 5

Type of Deed:	GRANT DEED
Title is vested in:	THE DAVID ANTHONY AND HEIDI Y. RADANOVICH TRUST (2/3 INTEREST), MARK A. RADANOVICH & CHRISTINE D. RADANOVICH (1/3)
Title received from:	THE LULA BELLE HOULIHAN REVOCABLE LIVING TRUST
Date Executed:	09/07/1994
Date Recorded:	09/15/1994
Book:	NA
Page:	NA
Instrument#:	944827
Land Record Comments:	

CHAIN 6

Type of Deed:	QUITCLAIM DEED
Title is vested in:	THE LULABELLE HOULIHAN REVOCABLE LIVING TRUST
Title received from:	LULABELLE HOULIHAN
Date Executed:	05/18/1992
Date Recorded:	05/18/1992
Book:	NA
Page:	NA
Instrument#:	923309
Land Record Comments:	

CHAIN 7

Type of Deed:	QUIT CLAIM DEED
Title is vested in:	THE LULABELLE HOULIHAN REVOCABLE LIVING TRUST
Title received from:	LULABELLE HOULIHAN
Date Executed:	05/18/1992
Date Recorded:	05/18/1992
Book:	NA
Page:	NA
Instrument#:	923308
Land Record Comments:	

CHAIN 8

Type of Deed:	GRANT DEED
Title is vested in:	THE KENNETH MARI AND LAMEIRA MARI 1990 TRUST
Title received from:	KENNETH MARI, LAMEMA MARI
Date Executed:	08/23/1990
Date Recorded:	08/24/1990
Book:	NA
Page:	NA
Instrument#:	995409
Land Record Comments:	RESEARCH CONDUCTED BACK TO 1980. THIS IS THE OLDEST DEED OF RECORD FOUND POST DECEMBER 31, 1979 (BETWEEN 01/01/1980 AND 08/24/1990).

EDR Environmental Lien and AUL Search 1980

MISCELLANEOUS INSTRUMENTS

Comments: NONE IDENTIFIED.

EDR Environmental Lien and AUL Search 1980

DEED EXHIBIT

– Recorder
Mariposa Co Official Records
Recorded at the request of
Public

LJ
5/05/2011
9:15 AM

DOC#: 20111601

00020111601

Titles: 1 Pages: 4

Fees	23.00
Taxes	0.00
Others	0.00
PAID	$23.00

RECORDING REQUESTED BY:
JAMISON & CHAPPEL

AND WHEN RECORDED MAIL TO:

JAMISON & CHAPPEL
P.O. Box 517
Oakhurst, CA 93644

Notice: This conveyance is to a trust not pursuant to a sale and is exempt from tax and the undersigned are the declarants and trustees on the effective date of this instrument. **R&T 11930.**

SPACE ABOVE FOR RECORDER'S USE

GRANT DEED

THE UNDERSIGNED GRANTOR(s) DECLARE(s): The undersigned grantor declares there is no documentary tax.
Documentary Transfer Tax is $ -0-
Unincorporated area of
Parcel No. 013-011-003
□ computed on full value of interest or property conveyed, or
□ computed on full value less value of liens or encumbrances remaining at time of sale, and

FOR NO CONSIDERATION, **Thomas P. Ritter and Lori L. Ritter, husband and wife, as joint tenants**

hereby grants to **THOMAS RITTER and LORI RITTER, Trustees of The Ritter Family Trust, dated May 3, 2011,**

the following described real property in the County of Mariposa, State of California:

See Exhibit A, attached hereto.

DATED: May 3RD, 2011.

Thomas P Ritter
TOM RITTER

Lori Ritter
LORI RITTER

Mail Tax Statements To: Thomas & Lori Ritter, P.O. Box 1965, Mariposa, CA 95338

L:\WILL-TRU\Ritter.GrantDeed.Mariposa.wpd

EXHIBIT A
TO
GRANT DEED
(Ritter Family Trust)

All that certain real property situated in the County of Mariposa, State of California, more particularly described as follows:

A TRACT OF LAND SITUATED IN A PORTION OF PROJECTED SECTION 15, TOWNSHIP 5 SOUTH, RANGE 18 EAST, M.D.B.&M., RANCHO LAS MARIPOSAS, MARIPOSA COUNTY, STATE OF CALIFORNIA, SAID TRACT OF LAND BEING MORE PARTICULARLY DESCRIBED AS FOLLOWS:

BEGINNING AT THE EASTERNMOST CORNER OF THAT CERTAIN REAL PROPERTY CONVEYED TO DAVID A. RADANOVICH AND HEIDI Y. RADANOVICH, TRUSTEES AND MARK A. RADANOVICH AND CHRISTINE D. RADANOVICH BY GRANT DEED RECORDED September 15, 1994, AS DOCUMENT NO. 944827, MARIPOSA COUNTY OFFICIAL RECORDS; THENCE S. 49° 16' 24" W. ALONG THE SOUTHEASTERLY LINE OF SAID CERTAIN REAL PROPERTY FOR 326.82 FEET TO A POINT ON A NON-TANGENT CURVE, CONCAVE TO THE NORTHEAST, HAVING A RADIUS OF 175.00 FEET, TO SAID POINT A RADIAL LINE BEARS S. 67° 23' 33" W.; THENCE LEAVING THE SOUTHEASTERLY LINE OF SAID CERTAIN REAL PROPERTY NORTHWESTERLY ALONG SAID CURVE, THROUGH A CENTRAL ANGLE OF 07° 49' 47", AN ARC DISTANCE OF 23.91 FEET TO THE POINT OF TANGENCY; THENCE N. 14° 46' 40" W. FOR 45.00 FEET TO THE BEGINNING OF A TANGENT CURVE, CONCAVE TO THE SOUTHWEST, HAVING A RADIUS OF 175.00 FEET; THENCE NORTHWESTERLY ALONG SAID CURVE, THROUGH A CENTRAL ANGLE OF 55° 40' 13", AN ARC DISTANCE OF 170.04 FEET TO THE POINT OF TANGENCY; THENCE N. 70° 26' 53" W. FOR 57.27 FEET TO A POINT ON THE SOUTHEASTERLY LINE OF THAT CERTAIN PARCEL OF LAND CONVEYED TO THE COUNTY OF MARIPOSA BY ROAD DEED RECORDED December 8, 1954, IN VOLUME 48 OF OFFICIAL RECORDS AT PAGE 535, MARIPOSA COUNTY RECORDS; THENCE N. 31° 31' 20" E. ALONG THE SOUTHEASTERLY LINE OF SAID PARCEL OF LAND FOR 72.00 FEET TO A POINT ON THE NORTHWESTERLY LINE OF SAID CERTAIN REAL PROPERTY; THENCE N. 62° 04' 19" E. ALONG THE NORTHWESTERLY LINE OF SAID CERTAIN REAL PROPERTY FOR 272.09 FEET TO THE NORTHERNMOST CORNER THEREOF; THENCE S. 40° 15' 09" E. ALONG THE NORTHEASTERLY LINE OF SAID CERTAIN REAL PROPERTY FOR 237.37 FEET, MORE OR LESS, TO THE POINT OF BEGINNING.

TOGETHER WITH ALL THAT CERTAIN REAL PROPERTY CONVEYED TO DAVID A. RADANOVICH AND HEIDI Y. RADANOVICH, TRUSTEES AND MARK A. RADANOVICH AND CHRISTINE D. RADANOVICH BY GRANT DEED RECORDED September 26, 2003, AS DOCUMENT NO. 2036913, MARIPOSA COUNTY OFFICIAL RECORDS, SAID CERTAIN REAL PROPERTY BEING DESCRIBED IN SAID GRANT DEED AS FOLLOWS:

THAT PORTION OF LOT 4 AS SHOWN ON THAT MAP OF MARI PLAZA, MAP NO. 2493, MARIPOSA COUNTY RECORDS, DESCRIBED AS FOLLOWS:

BEGINNING AT THE NORTHWESTERLY CORNER OF SAID LOT 4; THENCE N. 69° 24' 31" E., ALONG THE NORTHERLY LINE OF SAID LOT 4, 154.11 FEET; THENCE S 05° 13' 29" E. 79.49 FEET; THENCE S. 09°32' 52" E. 190.10 FEET TO A POINT ON THE SOUTHWESTERLY LINE OF SAID LOT 4; THENCE N. 40° 45' 00" W. ALONG SAID SOUTHWESTERLY LINE 280.40 FEET TO THE POINT OF BEGINNING.

ALSO TOGETHER WITH A NON-EXCLUSIVE EASEMENT FOR PUBLIC ROAD AND UTILITY PURPOSES ON, OVER, ACROSS AND UNDER A STRIP OF LAND SITUATED IN A PORTION OF SAID CERTAIN REAL PROPERTY, SAID STRIP OF LAND HAVING A UNIFORM WIDTH OF 30.00 FEET, THE NORTHEASTERLY LINE OF SAID STRIP OF LAND BEING THE SOUTHWESTERLY LINE OF THE HEREIN DESCRIBED TRACT OF LAND.

RESERVING THEREFROM, AS AN APPURTENANCE TO THE REMAINING LANDS OF THE GRANTOR, OR ANY PORTION THEREOF, AND TO ALL THAT CERTAIN PARCEL OF LAND CONVEYED TO DAVID ANTHONY RADANOVICH AND HEIDI YVONNE RADANOVICH, TRUSTEES BY GRANT DEED RECORDED December 27, 2004, AS DOCUMENT NO. 2048031, MARIPOSA COUNTY OFFICIAL RECORDS, OR ANY PORTION THEREOF, A NON-EXCLUSIVE EASEMENT FOR PUBLIC ROAD AND UTILITY PURPOSES ON, OVER, ACROSS AND UNDER A STRIP OF LAND SITUATED IN A PORTION OF SAID CERTAIN REAL PROPERTY, SAID STRIP OF LAND HAVING A UNIFORM WIDTH OF 30.00 FEET, THE SOUTHWESTERLY LINE OF SAID STRIP OF LAND BEING THE SOUTHWESTERLY LINE OF THE HEREIN ABOVE-DESCRIBED TRACT OF LAND.

APN: 013-011-003

L:\WILL-TRU\Ritter.GrantDeed.Mariposa.wpd

NOTARIAL ACKNOWLEDGMENT

State of California)
) ss.
County of MADERA)

On May 3, 2011, before me, Eileen R. Jackson , Notary Public, personally appeared **THOMAS P. RITTER and LORI L. RITTER** , who proved to me on the basis of satisfactory evidence to be the persons whose names are subscribed to the within instrument and acknowledged to me that they executed the same in their authorized capacities, and that by their signatures on the instrument the persons, or the entity upon behalf of which the persons acted, executed the instrument.

I certify under Penalty of Perjury under the laws of the State of California that the foregoing paragraph is true and correct.

WITNESS my hand and official seal.

EILEEN R JACKSON
COMM. # 1799768
NOTARY PUBLIC-CALIFORNIA
MADERA COUNTY
MY COMM. EXP. JUNE 27, 2012

Signature of Notary

[SEAL]

L:\FORMS\NotaryAcknowlegment2008.wpd

END OF DOCUMENT 4

-Recorder Barbara
Mariposa Co Official Records 1/18/2007
Recorded at the request of 13:40:15
INTER COUNTY TITLE COMPANY

DOCUMENT: **2070354** Titles: 1/ Pages: 3

Fees ... 13.00
Taxes ... 319.00
Other ...
AMT PAID 332.00

When recorded mail to:
Thomas P. Ritter and Lori L. Ritter
P.O. Box 1965
Mariposa, Ca 95338

Mail Tax Statements to above

Above Space for Recorder's Use only

The undersigned declares Documentary Transfer Tax is: $ 319.00
X Computed on the full value, or ____ Computed on the full value less liens and encumbrances
File No. M22244 APN: 013-011-003

Grant Deed

For Valuable Consideration, receipt of which is hereby acknowledged,
David A. Radanovich and Heidi Y. Radanovich, Trustees of the David Anthony and Heidi Yvonne Radanovich Trust dated August 3, 1990, as to an undivided 2/3 interest and Mark A. Radanovich and Christine D. Radanovich, individually and as Trustees of the Mark A. Radanovich and Christine D. Radanovich 2005 Revocable Family Trust, as to an undivided one-third (1/3) interest.

Hereby Grants To:
Thomas P. Ritter and Lori L. Ritter, husband and wife, as joint tenants

All that certain Real Property in the unincorporated area of the County of Mariposa, State of California as more particularly described in the Legal Description attached hereto

Dated: Jan. 16, 2007

David A. Radanovich, Trustee

Heidi Y. Radanovich, Trustee

Mark A. Radanovich, Trustee

Christine D. Radanovich, Trustee

State of CA
County of Mariposa

On Jan. 16, 2007, before me Tamra Coburn, Notary, personally appeared David A. Radanovich, Heidi Y. Radanovich, Mark A. Radanovich, Christine D. Radanovich personally known to me (or proved to me on the basis of satisfactory evidence) to be the person(s) whose name(s) is/are subscribed to the within instrument and acknowledged to me that he/she/they executed the same in his/her/their authorized capacity(ies) and that by his/her/their signature(s) on the instrument, the person(s) or entity upon behalf of which the person(s) acted, executed the instrument.

WITNESS my hand and official seal

TAMRA COBURN
Commission # 1445352
Notary Public - California
Mariposa County
My Comm. Expires Oct 13, 2007

2070354

PROPERTY DESCRIPTION

All that certain real property situated in the county of Mariposa , State of California, more particularly described as follows:

A TRACT OF LAND SITUATED IN A PORTION OF PROJECTED SECTION 15, TOWNSHIP 5 SOUTH, RANGE 18 EAST, M.D.B.&M., RANCHO LAS MARIPOSAS, MARIPOSA COUNTY, STATE OF CALIFORNIA, SAID TRACT OF LAND BEING MORE PARTICULARLY DESCRIBED AS FOLLOWS:

BEGINNING AT THE EASTERNMOST CORNER OF THAT CERTAIN REAL PROPERTY CONVEYED TO DAVID A RADANOVICH AND HEIDI Y. RADANOVICH, TRUSTEES AND MARK A RADANOVICH AND CHRISTINE D. RADANOVICH BY GRANT DEED RECORDED September 15, 1994 AS DOCUMENT NO. 944827, MARIPOSA COUNTY OFFICIAL RECORDS, THENCE S.49° 16' 24" W., ALONG THE SOUTHEASTERLY LINE OF SAID CERTAIN REAL PROPERTY FOR 326.82 FEET TO A POINT ON A NON-TANGENT CURVE, CONCAVE TO THE NORTHEAST, HAVING A RADIUS OF 175.00 FEET, TO SAID POINT A RADIAL LINE BEARS S.67° 23' 33" W; THENCE LEAVING THE SOUTHEASTERLY LINE OF SAID CERTAIN REAL PROPERTY, NORTHWESTERLY ALONG SAID CURVE, THROUGH A CENTRAL ANGLE OF 07° 49' 47", AN ARC DISTANCE OF 23.91 FEET TO THE POINT OF TANGENCY; THENCE N.14° 46'40" W., FOR 45.00 FEET TO THE BEGINNING OF A TANGENT CURVE, CONCAVE TO THE SOUTHWEST, HAVING A RADIUS OF 175.00 FEET; THENCE NORTHWESTERLY ALONG SAID CURVE, THROUGH A CENTRAL ANGLE OF 55° 40' 13", AN ARC DISTANCE OF 170.04 FEET TO THE POINT OF TANGENCY; THENCE N.70° 26' 53" W., FOR 57.27 FEET TO A POINT ON THE SOUTHEASTERLY LINE OF THAT CERTAIN PARCEL OF LAND CONVEYED TO THE COUNTY OF MARIPOSA BY ROAD DEED RECORDED December 8, 1954 IN VOLUME 48 OFFICIAL RECORDS AT PAGE 535, MARIPOSA COUNTY RECORDS, THENCE N.31° 31' 20" E., ALONG THE SOUTHEASTERLY LINE OF SAID PARCEL OF LAND, FOR 72.00 FEET TO A POINT ON THE NORTHWESTERLY LINE OF SAID CERTAIN REAL PROPERTY, THENCE N.62° 04' 19" E., ALONG THE NORTHWESTERLY LINE OF SAID CERTAIN REAL PROPERTY, FOR 272.09 FEET TO THE NORTHERNMOST CORNER THEREOF; THENCE S.40° 15' 09" E., ALONG THE NORTHEASTERLY LINE OF SAID CERTAIN REAL PROPERTY, FOR 237.37 FEET, MORE OR LESS, TO THE POINT OF BEGINNING.

TOGETHER WITH ALL THAT CERTAIN REAL PROPERTY CONVEYED TO DAVID A. RADANOVICH AND HEIDI Y. RADANOVICH, TRUSTEES AND MARK A. RADANOVICH AND CHRISTINE D. RADANOVICH BY GRANT DEED RECORDED September 26, 2003 AS DOCUMENT NO. 2036913, MARIPOSA COUNTY OFFICIAL RECORDS, SAID CERTAIN REAL PROPERTY BEING DESCRIBED IN SAID GRANT DEED AS FOLLOWS:

THAT PORTION OF LOT 4 AS SHOWN ON THAT MAP OF MARI PLAZA, MAP NO. 2493, MARIPOSA COUNTY RECORDS, DESCRIBED AS FOLLOWS:

BEGINNING AT THE NORTHWESTERLY CORNER OF SAID LOT 4; THENCE N.69° 24' 31" E., ALONG THE NORTHERLY LINE OF SAID LOT 4, 154.11 FEET; THENCE S.05° 13' 29" E., 79.49 FEET; THENCE S.09° 32' 52" E., 190.10 FEET TO A POINT ON THE SOUTHWESTERLY LINE OF SAID LOT 4; THENCE N.40° 45' 00" W., ALONG SAID SOUTHWESTERLY LINE 280.40 FEET TO THE POINT OF BEGINNING.

ALSO TOGETHER WITH A NON-EXCLUSIVE EASEMENT FOR PUBLIC ROAD AND UTILITY PURPOSES ON, OVER, ACROSS AND UNDER A STRIP OF LAND SITUATED IN A PORTION OF SAID CERTAIN REAL PROPERTY, SAID STRIP OF LAND HAVING A UNIFORM WIDTH OF 30.00 FEET, THE NORTHEASTERLY LINE OF SAID STRIP OF LAND BEING THE SOUTHWESTERLY LINE OF THE HEREIN DESCRIBED TRACT OF LAND.

RESERVING THEREFROM, AS AN APPURTENANCE TO THE REMAINING LANDS OF THE

GRANTOR, OR ANY PORTION THEREOF, AND TO ALL THAT CERTAIN PARCEL OF LAND CONVEYED TO DAVID ANTHONY RADANOVICH AND HEIDI YVONNE RADANOVICH, TRUSTEES BY GRANT DEED RECORDED December 27, 2004 AS DOCUMENT NO. 2048031, MARIPOSA COUNTY OFFICIAL RECORDS, OR ANY PORTION THEREOF, A NON-EXCLUSIVE EASEMENT FOR PUBLIC ROAD AND UTILITY PURPOSES ON, OVER, ACROSS AND UNDER A STRIP OF LAND SITUATED IN A PORTION OF SAID CERTAIN REAL PROPERTY, SAID STRIP OF LAND HAVING A UNIFORM WIDTH OF 30.00 FEET, THE SOUTHWESTERLY LINE OF SAID STRIP OF LAND BEING THE SOUTHWESTERLY LINE OF THE HEREIN ABOVE-DESCRIBED TRACT OF LAND.

END OF [illegible] 3

PROVOST&PRITCHARD
CONSULTING GROUP

455 W Fir Ave, Clovis, CA 93611 • (559) 449-2700
www.provostandpritchard.com

PHASE I ENVIRONMENTAL SITE ASSESSMENT—USER QUESTIONNAIRE

Property Name/Address: Ritter Property; unassigned; APN: 013-011-003
Completed by Mr./Mrs.: Robert Stark Date: 03/10/2026
Company: County of Mariposa Relation with Site: County property manager
Address: 5100 Bullion St., Mariposa, CA 95306; PO Box 784 Mariposa, 95306
Telephone: (209) 347-3255 E-mail: rstark@mariposacounty.gov

INTERVIEW QUESTIONS

1) What is the reason for performing the Phase I ESA? Conducting a Phase 1 is a Condition of a current option to purchase agreement.

2) What are the past, current, and/or planned uses for the Property (if known)? Planned/Intended use: EV Parking lot ~~of~~ w/ solar and chargers for County Vehicles

3) Are there existing or proposed structures on the site? None currently, only structure planned is overhead Solar

4) Will sensitive receptors (ex. children, elderly, people in poor health) occupy the Property? No

5) Are you aware of any environmental cleanup liens against the Property that are filed or recorded under federal, state, or tribal law? None that we are aware of.

6) Are you aware of any activity and land use limitations (ex. engineering controls), land use restrictions, or institutional controls in place at the Property or have been filed or recorded? None, Zoned as General Commercial

7) Do you know of specific chemicals that are or were once present at the Property? None that we are aware of.

8) Do you have any specialized knowledge or experience of the chemicals and processes used on the Property or nearby properties? No

9) Do you know of spills, chemical releases, or environmental cleanups that have taken place at the Property? No

10) Does the purchase price being paid for this Property reasonably reflect the fair market value? Yes, purchase price is determined by an appraisal conducted by and independent appraiser.

11) Based on your knowledge and experience related to the Property, are there any obvious indicators that point to the presence or likely presence of contamination? None that we are aware of. To our knowledge it has always been vacant & unimproved.

Engineering • Structural • Geostructural • Surveying • Planning • Environmental • GIS • Construction Services • Hydrogeology • Consulting
Clovis • Visalia • Bakersfield • Modesto • Los Banos • Chico • Sacramento • Sonora • San Luis Obispo • Riverside • Camarillo • Boise, ID

Appendix C Government Environmental Records

EDR Radius Map Report

EDR Vapor Encroachment Screen

County Environmental Health Department

California Geologic Energy Management Division

Department of Toxic Substances Control

Regional Water Quality Control Board

San Joaquin Valley Air Pollution Control District

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338

Inquiry Number: 8280255.2s
March 12, 2026

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

LIGHTBOX LIVE

Open LightBox Live to access data, tools, and advanced analytics in one online platform.

http://www.web.edrnet.com/ordering/switchboard/login.aspx?s=goto_lightbox&pguid=C2CBC85F-555E-4A27-B4DA-77EDF84D241D

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	9
Orphan Summary	73
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-12
Physical Setting Source Map Findings	A-14
Physical Setting Source Records Searched	PSGR-1

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 23), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

FRANK WILSON RD
MARIPOSA, CA 95338

COORDINATES

Latitude (North):	37.5004860 - 37° 30' 1.74''
Longitude (West):	119.9846980 - 119° 59' 4.91''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	236146.4
UTM Y (Meters):	4154376.8
Elevation:	2139 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	50003925 FELICIANA MOUNTAIN, CA
Version Date:	2021
Southeast Map:	50003934 MARIPOSA, CA
Version Date:	2021
Southwest Map:	50003774 CATHEYS VALLEY, CA
Version Date:	2021
Northwest Map:	50003760 BEAR VALLEY, CA
Version Date:	2021

AERIAL PHOTOGRAPHY IN THIS REPORT

Photo Year:	2024
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
FRANK WILSON RD
MARIPOSA, CA 95338

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	CAL-FIRE	5366 HWY. 49 N.	RCRA NonGen / NLR	Higher	788, 0.149, NW
A2	DEPT OF FORESTRY & F	5366 STATE HIGHWAY 4	RCRA NonGen / NLR	Higher	788, 0.149, NW
A3	MARIPOSA HDQS FF S	5366 HWY 49 N	HIST UST, HWTS, HAZNET	Higher	788, 0.149, NW
A4	CDF MARIPOSA	5366 HIGHWAY 49 N	LUST, Cortese, EMI, CERS	Higher	788, 0.149, NW
A5	MARIPOSA RANGER UNIT	5366 49	HIST CORTESE	Higher	788, 0.149, NW
A6	MARIPOSA FOREST FIRE	5366 N HWY 49	SWEEPS UST	Higher	788, 0.149, NW
A7	DEPT OF FORESTRY & F	5366 STATE HIGHWAY 4	E MANIFEST	Higher	788, 0.149, NW
A8	MARIPOSA RANGER UNIT	5366 HIGHWAY 49 N	UST FINDER RELEASE	Higher	788, 0.149, NW
A9	CDF MARIPOSA STATION	5366 STATE HIGHWAY 4	E MANIFEST	Higher	788, 0.149, NW
A10	CAL FIRE MARIPOSA	5366 STATE HIGHWAY 4	AST	Higher	788, 0.149, NW
A11	CAL-FIRE	5366 HWY. 49 N.	E MANIFEST	Higher	788, 0.149, NW
A12	MARIPOSA HDQS F.F.S.	5366 STATE HIGHWAY 4	HIST UST	Higher	788, 0.149, NW
A13	CAL FIRE MARIPOSA	5366 STATE HIGHWAY 4	CERS HAZ WASTE, CERS TANKS, CERS	Higher	788, 0.149, NW
B14	MARIPOSA COUNTY HEAL	5300 HWY 49N	RCRA NonGen / NLR	Lower	1064, 0.202, SE
B15	MARIPOSA COUNTY HEAL	5300 HIGHWAY 49 N	E MANIFEST	Lower	1064, 0.202, SE
16	IW WELL 07		PFAS	Lower	1300, 0.246, SSE
17	JOHN C. FREMONT HOSP	5189 HOSPITAL ROAD	ENVIROSTOR	Higher	1752, 0.332, East
C18	CHP-MARIPOSA	5264 HWY 49 N	UST FINDER RELEASE	Lower	1927, 0.365, SE
C19	CHP-MARIPOSA	5264 HWY 49 N	LUST, Cortese, CERS	Lower	1927, 0.365, SE
20	CHP-MARIPOSA	5246 HWY 49 N	LUST	Lower	2454, 0.465, SE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL ---- National Priority List
Proposed NPL ---- Proposed National Priority List Sites
NPL LIENS ---- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---- Federal Facility Site Information listing
SEMS ---- Superfund Enterprise Management System

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE ---- Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS ---- Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---- RCRA - Treatment, Storage and Disposal

Lists of Federal RCRA generators

RCRA-LQG ---- RCRA - Large Quantity Generators
RCRA-SQG ---- RCRA - Small Quantity Generators
RCRA-VSQG ---- RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

Federal institutional controls / engineering controls registries

LUCIS ---- Land Use Control Information System

US ENG CONTROLS ..... Engineering Controls Sites List
US INST CONTROLS ..... Institutional Controls Sites List

Federal ERNS list

ERNS ..... Emergency Response Notification System

Lists of state- and tribal (Superfund) equivalent sites

RESPONSE ..... State Response Sites

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF ..... Solid Waste Information System

Lists of state and tribal leaking storage tanks

INDIAN LUST ..... Leaking Underground Storage Tanks on Indian Land
CPS-SLIC ..... Statewide SLIC Cases

Lists of state and tribal registered storage tanks

FEMA UST ..... Underground Storage Tank Listing
UST ..... Active UST Facilities
INDIAN UST ..... Underground Storage Tanks on Indian Land

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ..... Voluntary Cleanup Priority Listing
VCP ..... Voluntary Cleanup Program Properties

Lists of state and tribal brownfield sites

BROWNFIELDS ..... Considered Brownfieds Sites Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT ..... Waste Management Unit Database
SWRCY ..... Recycler Database
HAULERS ..... Registered Waste Tire Haulers Listing
INDIAN ODI ..... Report on the Status of Open Dumps on Indian Lands
ODI ..... Open Dump Inventory
DEBRIS REGION 9 ..... Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ..... Delisted National Clandestine Laboratory Register

HIST Cal-Sites ---- Historical Calsites Database
SCH ---- School Property Evaluation Program
CDL ---- Clandestine Drug Labs
Toxic Pits ---- Toxic Pits Cleanup Act Sites
US CDL ---- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

CA FID UST ---- Facility Inventory Database

Local Land Records

LIENS ---- Environmental Liens Listing
LIENS 2 ---- CERCLA Lien Information
DEED ---- Deed Restriction Listing

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
CHMIRS ---- California Hazardous Material Incident Report System
LDS ---- Land Disposal Sites Listing
MCS ---- Military Cleanup Sites Listing
SPILLS 90 ---- SPILLS 90 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
FUSRAP ---- Formerly Utilized Sites Remedial Action Program
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites

EXECUTIVE SUMMARY

US AIRS	Aerometric Information Retrieval System Facility Subsystem
US MINES	Mines Master Index File
ABANDONED MINES	Abandoned Mines
MINES MRDS	Mineral Resources Data System
FINDS	Facility Index System/Facility Registry System
DOCKET HWC	Hazardous Waste Compliance Docket Listing
UXO	Unexploded Ordnance Sites
ECHO	Enforcement & Compliance History Information
FUELS PROGRAM	EPA Fuels Program Registered Listing
PFAS NPL	Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES	Federal Sites PFAS Information
PFAS TRIS	List of PFAS Added to the TRI
PFAS TSCA	PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR	PFAS Contamination Site Location Listing
PFAS WQP	Ambient Environmental Sampling for PFAS
PFAS PROJECT	NORTHEASTERN UNIVERSITY PFAS PROJECT
PFAS NPDES	Clean Water Act Discharge Monitoring Information
PFAS ECHO	Facilities in Industries that May Be Handling PFAS Listing
PFAS ECHO FIRE TRAIN	Facilities in Industries that May Be Handling PFAS Listing
PFAS PT 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing
BIOSOLIDS	ICIS-NPDES Biosolids Facility Data
UST FINDER	UST Finder Database
AQUEOUS FOAM	Former Fire Training Facility Assessments Listing
CA BOND EXP. PLAN	Bond Expenditure Plan
CHROME PLATING	Chrome Plating Facilities Listing
CUPA Listings	CUPA Resources List
DRYCLEANERS	Cleaner Facilities
EMI	Emissions Inventory Data
ENF	Enforcement Action Listing
Financial Assurance	Financial Assurance Information Listing
ICE	Inspection, Compliance and Enforcement
HWP	EnviroStor Permitted Facilities Listing
HWT	Registered Hazardous Waste Transporter Database
HWTS	Hazardous Waste Tracking System
HAZNET	Facility and Manifest Data
MINES	Mines Site Location Listing
MWMP	Medical Waste Management Program Listing
NPDES	NPDES Permits Listing
PEST LIC	Pesticide Regulation Licenses Listing
PROC	Certified Processors Database
Notify 65	Proposition 65 Records
HAZMAT	Hazardous Material Facilities
UIC	UIC Listing
UIC GEO	UIC GEO (GEOTRACKER)
WASTEWATER PITS	Oil Wastewater Pits Listing
WDS	Waste Discharge System
WIP	Well Investigation Program Case List
MILITARY PRIV SITES	MILITARY PRIV SITES (GEOTRACKER)
PROJECT	PROJECT (GEOTRACKER)
WDR	Waste Discharge Requirements Listing
CIWQS	California Integrated Water Quality System
CERS	CERS
NON-CASE INFO	NON-CASE INFO (GEOTRACKER)

OTHER OIL GAS OTHER OIL & GAS (GEOTRACKER)
PROD WATER PONDS PROD WATER PONDS (GEOTRACKER)
SAMPLING POINT SAMPLING POINT (GEOTRACKER)
WELL STIM PROJ Well Stimulation Project (GEOTRACKER)

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants
EDR Hist Auto EDR Exclusive Historical Auto Stations
EDR Hist Cleaner EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF Recovered Government Archive Solid Waste Facilities List
RGA LUST Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of state- and tribal hazardous waste facilities

ENVIROSTOR: The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 10/20/2025 has revealed that there is 1 ENVIROSTOR site within approximately 1 mile of the target property.

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JOHN C. FREMONT HOSP Facility Id: 22800001 Status: No Action Required	5189 HOSPITAL ROAD	E 1/4 - 1/2 (0.332 mi.)	17	63

Lists of state and tribal leaking storage tanks

LUST: Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

A review of the LUST list, as provided by EDR, has revealed that there are 3 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CDF MARIPOSA Database: LUST REG 5, Date of Government Version: 07/01/2008 Database: LUST, Date of Government Version: 11/24/2025 Status: Completed - Case Closed Status: Remediation Plan Global Id: T0604300083	***5366 HIGHWAY 49 N***	***NW 1/8 - 1/4 (0.149 mi.)***	***A4***	***15***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHP-MARIPOSA Database: LUST, Date of Government Version: 11/24/2025 Status: Completed - Case Closed Global Id: T0604391798	***5264 HWY 49 N***	***SE 1/4 - 1/2 (0.365 mi.)***	***C19***	***65***
CHP-MARIPOSA Database: LUST REG 5, Date of Government Version: 07/01/2008 Status: Preliminary site assessment underway	5246 HWY 49 N	SE 1/4 - 1/2 (0.465 mi.)	20	72

Lists of state and tribal registered storage tanks

AST: A listing of aboveground storage tank petroleum storage tank locations.

A review of the AST list, as provided by EDR, has revealed that there is 1 AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CAL FIRE MARIPOSA Database: AST, Date of Government Version: 07/06/2016	5366 STATE HIGHWAY 4	NW 1/8 - 1/4 (0.149 mi.)	A10	39

EXECUTIVE SUMMARY

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

CERS HAZ WASTE: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

A review of the CERS HAZ WASTE list, as provided by EDR, and dated 10/13/2025 has revealed that there is 1 CERS HAZ WASTE site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CAL FIRE MARIPOSA	***5366 STATE HIGHWAY 4***	***NW 1/8 - 1/4 (0.149 mi.)***	***A13***	***43***

Local Lists of Registered Storage Tanks

SWEEPS UST: Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there is 1 SWEEPS UST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARIPOSA FOREST FIRE Status: A Tank Status: A Comp Number: 19923	5366 N HWY 49	NW 1/8 - 1/4 (0.149 mi.)	A6	34

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 2 HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARIPOSA HDQS FF S	***5366 HWY 49 N***	***NW 1/8 - 1/4 (0.149 mi.)***	***A3***	***13***
MARIPOSA HDQS F.F.S. Facility Id: 00000019923	5366 STATE HIGHWAY 4	NW 1/8 - 1/4 (0.149 mi.)	A12	42

CERS TANKS: List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

A review of the CERS TANKS list, as provided by EDR, and dated 10/13/2025 has revealed that there is 1 CERS TANKS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CAL FIRE MARIPOSA	***5366 STATE HIGHWAY 4***	***NW 1/8 - 1/4 (0.149 mi.)***	***A13***	***43***

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 11/30/2025 has revealed that there are 3 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CAL-FIRE EPA ID:: CAC003277030	5366 HWY. 49 N.	NW 1/8 - 1/4 (0.149 mi.)	A1	9
DEPT OF FORESTRY & F EPA ID:: CAL000059136	5366 STATE HIGHWAY 4	NW 1/8 - 1/4 (0.149 mi.)	A2	11

Lower Elevation	Address	Direction / Distance	Map ID	Page
MARIPOSA COUNTY HEAL EPA ID:: CAL000453328	5300 HWY 49N	SE 1/8 - 1/4 (0.202 mi.)	B14	50

UST FINDER RELEASE: US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

A review of the UST FINDER RELEASE list, as provided by EDR, and dated 06/08/2023 has revealed that there are 2 UST FINDER RELEASE sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARIPOSA RANGER UNIT	5366 HIGHWAY 49 N	NW 1/8 - 1/4 (0.149 mi.)	A8	37

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHP-MARIPOSA	5264 HWY 49 N	SE 1/4 - 1/2 (0.365 mi.)	C18	64

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 11/30/2025 has revealed that there are 4 E MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DEPT OF FORESTRY & F	5366 STATE HIGHWAY 4	NW 1/8 - 1/4 (0.149 mi.)	A7	35
CDF MARIPOSA STATION	5366 STATE HIGHWAY 4	NW 1/8 - 1/4 (0.149 mi.)	A9	38
CAL-FIRE	5366 HWY. 49 N.	NW 1/8 - 1/4 (0.149 mi.)	A11	40

Lower Elevation	Address	Direction / Distance	Map ID	Page
MARIPOSA COUNTY HEAL	5300 HIGHWAY 49 N	SE 1/8 - 1/4 (0.202 mi.)	B15	52

EXECUTIVE SUMMARY

PFAS: A listing of PFAS sites included in the Envirostor and GeoTracker databases. Locations of potential sources of per - and polyfluoroalkyl substances (PFAS). This does not mean that PFAS has been produced, used, or discharged at these sites.

A review of the PFAS list, as provided by EDR, and dated 11/25/2025 has revealed that there is 1 PFAS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
IW WELL 07		SSE 1/8 - 1/4 (0.246 mi.)	16	55

Cortese: The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

A review of the Cortese list, as provided by EDR, and dated 12/08/2025 has revealed that there are 2 Cortese sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CDF MARIPOSA	***5366 HIGHWAY 49 N***	***NW 1/8 - 1/4 (0.149 mi.)***	***A4***	***15***
Cleanup Status: COMPLETED - CASE CLOSED				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHP-MARIPOSA	***5264 HWY 49 N***	***SE 1/4 - 1/2 (0.365 mi.)***	***C19***	***65***
Cleanup Status: COMPLETED - CASE CLOSED				

HIST CORTESE: The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

A review of the HIST CORTESE list, as provided by EDR, and dated 04/01/2001 has revealed that there is 1 HIST CORTESE site within approximately 0.5 miles of the target property.


Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MARIPOSA RANGER UNIT	5366 49	NW 1/8 - 1/4 (0.149 mi.)	A5	34
Reg Id: 5T22000127				

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 1 records.

Site Name	Database(s)
JUNK YARD - VIC HALL	ENVIROSTOR

OVERVIEW MAP - 8280255.2S



0 1/4 1/2 1 Miles


- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Mariposa County	CLIENT:	Provost & Pritchard Eng. Group
ADDRESS:	Frank Wilson Rd Mariposa CA 95338	CONTACT:	Stephanie Gillaspy
LAT/LONG:	37.500486 / 119.984698	INQUIRY #:	8280255.2s
		DATE:	March 12, 2026 7:22 pm

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 8280255.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

Sensitive Receptors

National Priority List Sites

Dept. Defense Sites

0 1/16 1/8 1/4 Miles

Indian Reservations BIA

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Mariposa County	CLIENT:	Provost & Pritchard Eng. Group
ADDRESS:	Frank Wilson Rd Mariposa CA 95338	CONTACT:	Stephanie Gillaspy
		INQUIRY #:	8280255.2s
LAT/LONG:	37.500486 / 119.984698	DATE:	March 12, 2026 7:27 pm

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	0	0	NR	0
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		0	0	NR	NR	NR	0
RCRA-VSQG	0.250		0	0	NR	NR	NR	0
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal (Superfund) equivalent sites								
RESPONSE	1.000		0	0	0	0	NR	0
Lists of state- and tribal hazardous waste facilities								
ENVIROSTOR	1.000		0	0	1	0	NR	1
Lists of state and tribal landfills and solid waste disposal facilities								
SWF/LF	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Lists of state and tribal leaking storage tanks								
LUST	0.500		0	1	2	NR	NR	3
INDIAN LUST	0.500		0	0	0	NR	NR	0
CPS-SLIC	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250		0	0	NR	NR	NR	0
AST	0.250		0	1	NR	NR	NR	1
INDIAN UST	0.250		0	0	NR	NR	NR	0
Lists of state and tribal voluntary cleanup sites								
INDIAN VCP	0.500		0	0	0	NR	NR	0
VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
BROWNFIELDS	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
WMUDS/SWAT	0.500		0	0	0	NR	NR	0
SWRCY	0.500		0	0	0	NR	NR	0
HAULERS	TP		NR	NR	NR	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
HIST Cal-Sites	1.000		0	0	0	0	NR	0
SCH	0.250		0	0	NR	NR	NR	0
CDL	TP		NR	NR	NR	NR	NR	0
Toxic Pits	1.000		0	0	0	0	NR	0
CERS HAZ WASTE	0.250		0	1	NR	NR	NR	1
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
SWEEPS UST	0.250		0	1	NR	NR	NR	1
HIST UST	0.250		0	2	NR	NR	NR	2
CERS TANKS	0.250		0	1	NR	NR	NR	1
CA FID UST	0.250		0	0	NR	NR	NR	0
Local Land Records								
LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	TP		NR	NR	NR	NR	NR	0
DEED	0.500		0	0	0	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
CHMIRS	TP		NR	NR	NR	NR	NR	0
LDS	TP		NR	NR	NR	NR	NR	0
MCS	TP		NR	NR	NR	NR	NR	0
SPILLS 90	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		0	3	NR	NR	NR	3
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	0	NR	NR	NR	0
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	TP		NR	NR	NR	NR	NR	0
UST FINDER RELEASE	0.500		0	1	1	NR	NR	2
UST FINDER	0.250		0	0	NR	NR	NR	0
E MANIFEST	0.250		0	4	NR	NR	NR	4
PFAS	0.250		0	1	NR	NR	NR	1
AQUEOUS FOAM	0.250		0	0	NR	NR	NR	0
CA BOND EXP. PLAN	1.000		0	0	0	0	NR	0
CHROME PLATING	0.500		0	0	0	NR	NR	0
Cortese	0.500		0	1	1	NR	NR	2
CUPA Listings	0.250		0	0	NR	NR	NR	0
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
EMI	TP		NR	NR	NR	NR	NR	0
ENF	TP		NR	NR	NR	NR	NR	0
Financial Assurance	TP		NR	NR	NR	NR	NR	0
ICE	TP		NR	NR	NR	NR	NR	0
HIST CORTESE	0.500		0	1	0	NR	NR	1
HWP	1.000		0	0	0	0	NR	0
HWT	0.250		0	0	NR	NR	NR	0
HWTS	TP		NR	NR	NR	NR	NR	0
HAZNET	TP		NR	NR	NR	NR	NR	0
MINES	0.250		0	0	NR	NR	NR	0
MWMP	0.250		0	0	NR	NR	NR	0
NPDES	TP		NR	NR	NR	NR	NR	0
PEST LIC	TP		NR	NR	NR	NR	NR	0
PROC	0.500		0	0	0	NR	NR	0
Notify 65	1.000		0	0	0	0	NR	0
HAZMAT	0.250		0	0	NR	NR	NR	0
UIC	TP		NR	NR	NR	NR	NR	0
UIC GEO	TP		NR	NR	NR	NR	NR	0
WASTEWATER PITS	0.500		0	0	0	NR	NR	0
WDS	TP		NR	NR	NR	NR	NR	0
WIP	0.250		0	0	NR	NR	NR	0
MILITARY PRIV SITES	TP		NR	NR	NR	NR	NR	0
PROJECT	TP		NR	NR	NR	NR	NR	0
WDR	TP		NR	NR	NR	NR	NR	0
CIWQS	TP		NR	NR	NR	NR	NR	0
CERS	TP		NR	NR	NR	NR	NR	0
NON-CASE INFO	TP		NR	NR	NR	NR	NR	0
OTHER OIL GAS	TP		NR	NR	NR	NR	NR	0
PROD WATER PONDS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
SAMPLING POINT	TP		NR	NR	NR	NR	NR	0
WELL STIM PROJ	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		0	NR	NR	NR	NR	0
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
RGA LF	TP		NR	NR	NR	NR	NR	0
RGA LUST	TP		NR	NR	NR	NR	NR	0
- Totals --		0	0	18	5	0	0	23

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
NW
1/8-1/4
0.149 mi.
788 ft.

CAL-FIRE
5366 HWY. 49 N.
MARIPOSA, CA 95338

Site 1 of 13 in cluster A

RCRA NonGen / NLR

1031049863
CAC003277030

Relative:
Higher

Actual:
2195 ft.

RCRA Listings:

Date Form Received by Agency:	20240607
Handler Name:	Cal-Fire
Handler Address:	5366 Hwy. 49 N.
Handler City,State,Zip:	MARIPOSA, CA 95338
EPA ID:	CAC003277030
Contact Name:	Not reported
Contact Address:	5366 HWY. 49 N.
Contact City,State,Zip:	MARIPOSA, CA 95338
Contact Telephone:	559-706-8820
Contact Fax:	Not reported
Contact Email:	KEN.RUSSELL@FIRE.CA.GOV
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CAL-FIRE (Continued) **1031049863**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20240918
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: CAL-FIRE	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	5366 HWY. 49 N.
Owner/Operator City,State,Zip:	MARIPOSA, CA 95338
Owner/Operator Telephone:	559-706-8820
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CAL-FIRE	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	5366 HWY. 49 N.
Owner/Operator City,State,Zip:	MARIPOSA, CA 95338
Owner/Operator Telephone:	559-706-8820
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20240308
Handler Name: CAL-FIRE	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

CAL-FIRE (Continued) **1031049863**

Receive Date: 20240607
Handler Name: CAL-FIRE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: All Other Waste Management Services

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A2 **DEPT OF FORESTRY & FIRE** **RCRA NonGen / NLR** **1024789092**
NW **5366 STATE HIGHWAY 49 N** **CAL000059136**
1/8-1/4 **MARIPOSA, CA 95338**
0.149 mi.
788 ft. **Site 2 of 13 in cluster A**

Relative:
Higher

Actual:
2195 ft.

RCRA Listings:
Date Form Received by Agency: 19920224
Handler Name: Dept Of Forestry & Fire
Handler Address: 5366 State Highway 49 N
Handler City,State,Zip: MARIPOSA, CA 95338-9503
EPA ID: CAL000059136
Contact Name: LALA RUKH
Contact Address: P.O. BOX 944246
Contact City,State,Zip: SACRAMENTO, CA 94244-2460
Contact Telephone: 916-445-0418
Contact Fax: Not reported
Contact Email: LALA.RUKH@FIRE.CA.GOV
Contact Title: Not reported
EPA Region: 09
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Not reported
State District: Not reported
Mailing Address: 210 W SAN JACINTO AVE
Mailing City,State,Zip: PERRIS, CA 92570-0000
Owner Name: Calif Dept Of Forestry & Fire Protc
Owner Type: Other

DEPT OF FORESTRY & FIRE (Continued) **1024789092**

Operator Name:	Lala Rukh
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180905
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CALIF DEPT OF FORESTRY & FIRE PROTC
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	210 W SAN JACINTO AVE
Owner/Operator City,State,Zip:	PERRIS, CA 92570-0000
Owner/Operator Telephone:	951-940-6900
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

DEPT OF FORESTRY & FIRE (Continued) **1024789092**

Owner/Operator Indicator: Operator
Owner/Operator Name: LALA RUKH
Legal Status: Other
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: P.O. BOX 944246
Owner/Operator City,State,Zip: SACRAMENTO, CA 94244-2460
Owner/Operator Telephone: 916-445-0418
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19920224
Handler Name: DEPT OF FORESTRY & FIRE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56299
NAICS Description: All Other Waste Management Services

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

A3 **MARIPOSA HDQS FF S** **HIST UST** **S112905534**
NW **5366 HWY 49 N** **HWTS** **N/A**
1/8-1/4 **MARIPOSA, CA 95338** **HAZNET**
0.149 mi.
788 ft. **Site 3 of 13 in cluster A**

Relative:
Higher

Actual:
2195 ft.

HIST UST:
Name: MARIPOSA HDQS FF S
Address: 5366 HWY 49 N
City,State,Zip: MARIPOSA, CA 95338
File Number: 00029490

URL:
Region: Not reported
Facility ID: Not reported
Facility Type: Not reported
Other Type: Not reported
Contact Name: Not reported
Telephone: Not reported

MARIPOSA HDQS FF S (Continued) **S112905534**

Owner Name:	Not reported
Owner Address:	Not reported
Owner City,St,Zip:	Not reported
Total Tanks:	Not reported
Tank Num:	Not reported
Container Num:	Not reported
Year Installed:	Not reported
Tank Capacity:	Not reported
Tank Used for:	Not reported
Type of Fuel:	Not reported
Container Construction Thickness:	Not reported
Leak Detection:	Not reported

Click here for Geo Tracker PDF:

HWTS:

Name:	MARIPOSA RANGER UNIT HEADQUARTERS
Address:	5366 HWY 49 NORTH
Address 2:	Not reported
City,State,Zip:	MARIPOSA, CA 95338
EPA ID:	CAC002225721
Inactive Date:	10/25/2000
Create Date:	02/16/2000
Last Act Date:	Not reported
Mailing Name:	Not reported
Mailing Address:	1102 Q STREET STE 4400
Mailing Address 2:	SA
Mailing City,State,Zip:	CA 958146511
Owner Name:	CAL STATE DEPT OF FORESTRY
Owner Address:	1102 Q STREET STE 4400
Owner Address 2:	Not reported
Owner City,State,Zip:	SACRAMENTO, CA 958146511
Owner Phone:	Not reported
Owner Fax:	Not reported
Contact Name:	JOHN ROBBINS/REP
Contact Address:	1102 Q STREET STE 4400
Contact Address 2:	Not reported
City,State,Zip:	SACRAMENTO, CA 958146511
Contact Phone:	Not reported
Contact Fax:	Not reported
Facility Status:	Inactive
Facility Type:	TEMPORARY
Category:	STATE
Latitude:	37.501919
Longitude:	-119.9884

HAZNET:

Name:	MARIPOSA RANGER UNIT HEADQUARTERS
Address:	5366 HWY 49 NORTH
Address 2:	Not reported
City,State,Zip:	MARIPOSA, CA 953380000
Contact:	JOHN ROBBINS/REP
Telephone:	2099662116
Mailing Name:	Not reported
Mailing Address:	1102 Q STREET STE 4400

MARIPOSA HDQS FF S (Continued) **S112905534**

Year:	2000
Gepaid:	CAC002225721
TSD EPA ID:	CAD099452708
CA Waste Code:	223 - Unspecified oil-containing waste
Disposal Method:	R01 - Recycler
Tons:	0.417

Additional Information:

Year:	2000
Gen EPA ID:	CAC002225721
Shipment Date:	20000314
Creation Date:	5/17/2000 0:00:00
Receipt Date:	20000320
Manifest ID:	98374080
Trans EPA ID:	CAL000827878
Trans Name:	Not reported
Trans 2 EPA ID:	Not reported
Trans 2 Name:	Not reported
TSDF EPA ID:	CAD099452708
Trans Name:	Not reported
TSDF Alt EPA ID:	CAD099452708
TSDF Alt Name:	Not reported
Waste Code Description:	223 - Unspecified oil-containing waste
RCRA Code:	Not reported
Meth Code:	R01 - Recycler
Quantity Tons:	0.417
Waste Quantity:	100
Quantity Unit:	G
Additional Code 1:	Not reported
Additional Code 2:	Not reported
Additional Code 3:	Not reported
Additional Code 4:	Not reported
Additional Code 5:	Not reported

A4 **CDF MARIPOSA** **LUST** **S105033936**
NW **5366 HIGHWAY 49 N** **Cortese** **N/A**
1/8-1/4 **MARIPOSA, CA 95338** **EMI**
0.149 mi. **CERS**
788 ft. **Site 4 of 13 in cluster A**

Relative:
Higher

Actual:
2195 ft.

LUST:

Name:	MARIPOSA RANGER UNIT HEADQUARTERS
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site

Geo Track:

Global Id:	T0604300083
Latitude:	37.500712521403
Longitude:	-119.986474514008
Status:	Completed - Case Closed
Status Date:	12/30/2019
Case Worker:	BJL
RB Case Number:	5T22000127

CDF MARIPOSA (Continued) **S105033936**

Local Agency:	MARIPOSA COUNTY
File Location:	Regional Board
Local Case Number:	Not reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Diesel
EPA Region:	9
Coordinate Source:	Manual Entry on Screens
Cuf Case:	Not reported
Quantity Released Gallons:	Not reported
Begin Date:	Not reported
Leak Reported Date:	Not reported
How Discovered:	Not reported
How Discovered Description:	Not reported
Discharge Source:	Not reported
Discharge Cause:	Not reported
Stop Method:	Not reported
Stop Description:	Not reported
No Further Action Date:	Not reported
CA Water Watershed Name:	Not reported
Dwr Groundwater Subbasin Name:	Not reported
Disadvantaged Community:	Not reported
CA Enviroscreen 3 Score:	Not reported
CA Enviroscreen 4 Score:	Not reported
Military DOD Site:	Not reported
Facility Project Subtype:	Not reported
RWQCB Region:	Not reported
Site History:	The case was opened following an unauthorized release from an underground storage tank system at the subject site. Corrective action is underway as directed by the CVRWQCB. Corrective action may consist of preliminary site investigation, planning and implementation of remedial action, verification monitoring, or a combination thereof. A summary of the site history is available by clicking on either the

LUST:

Global Id:	T0604300083
Contact Type:	Regional Board Caseworker - Primary Caseworker
Contact Name:	BENJAMIN LEHMANN
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 Sun Center Drive #200
City:	RANCHO CORDOVA
Email:	benjamin.lehmann@waterboards.ca.gov
Phone Number:	9164644760

Global Id:	T0604300083
Contact Type:	Local Agency Caseworker
Contact Name:	KERRI GIBBONS
Organization Name:	MARIPOSA COUNTY
Address:	Not reported
City:	r5 UNKNOWN
Email:	Not reported
Phone Number:	Not reported

LUST:

Global Id:	T0604300083
Action Type:	Other
Date:	03/02/2000

CDF MARIPOSA (Continued) **S105033936**

Action: Leak Discovery

Global Id: T0604300083
Action Type: RESPONSE
Date: 04/30/2004
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: RESPONSE
Date: 01/30/2006
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0604300083
Action Type: RESPONSE
Date: 03/15/2004
Action: Other Report / Document

Global Id: T0604300083
Action Type: RESPONSE
Date: 12/19/2013
Action: Removal Action Complete

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 04/07/2003
Action: Staff Letter - #5-01-712

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 09/24/2003
Action: * Verbal Communication

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 09/26/2003
Action: Site Visit / Inspection / Sampling

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 05/25/2018
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 09/17/2019
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 12/30/2019
Action: Closure/No Further Action Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 03/28/2019
Action: Staff Letter

CDF MARIPOSA (Continued) **S105033936**

Global Id: T0604300083
Action Type: RESPONSE
Date: 12/30/2003
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: RESPONSE
Date: 01/03/2003
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0604300083
Action Type: RESPONSE
Date: 02/19/2003
Action: Preliminary Site Assessment Report

Global Id: T0604300083
Action Type: RESPONSE
Date: 11/01/2010
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: RESPONSE
Date: 07/30/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0604300083
Action Type: RESPONSE
Date: 06/30/2013
Action: Other Report / Document

Global Id: T0604300083
Action Type: RESPONSE
Date: 09/06/2013
Action: Remedial Progress Report

Global Id: T0604300083
Action Type: RESPONSE
Date: 02/01/2011
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 10/10/2002
Action: Staff Letter - #5-01-712

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 12/19/2002
Action: Staff Letter - #5-01-712

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 07/30/2002
Action: Staff Letter - #5-01-712

Global Id: T0604300083
Action Type: ENFORCEMENT

CDF MARIPOSA (Continued) **S105033936**

Date: 01/07/2014
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 01/27/2015
Action: Email Correspondence

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 03/14/2014
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 07/31/2015
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 05/27/2014
Action: Email Correspondence

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 12/07/2018
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 01/27/2016
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 04/11/2017
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 05/25/2018
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 01/19/2018
Action: Staff Letter

Global Id: T0604300083
Action Type: Other
Date: 03/09/2000
Action: Leak Reported

Global Id: T0604300083
Action Type: RESPONSE
Date: 11/01/2009
Action: Monitoring Report - Quarterly

CDF MARIPOSA (Continued) **S105033936**

Global Id: T0604300083
Action Type: RESPONSE
Date: 01/03/2003
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0604300083
Action Type: RESPONSE
Date: 02/27/2003
Action: Other Workplan

Global Id: T0604300083
Action Type: RESPONSE
Date: 12/08/2006
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0604300083
Action Type: RESPONSE
Date: 08/01/2010
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: RESPONSE
Date: 02/15/2017
Action: Request for Closure - Regulator Responded

Global Id: T0604300083
Action Type: REMEDIATION
Date: 10/07/2013
Action: Excavation

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 06/06/2007
Action: Verbal Communication

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 03/25/2010
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 03/26/2010
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 05/06/2010
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 02/24/2011
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT

CDF MARIPOSA (Continued) **S105033936**

Date: 05/19/2011
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 12/08/2010
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 09/03/2010
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 08/16/2011
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 06/03/2013
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 03/13/2013
Action: Staff Letter

Global Id: T0604300083
Action Type: RESPONSE
Date: 03/17/2003
Action: Pilot Study / Treatability Workplan

Global Id: T0604300083
Action Type: RESPONSE
Date: 02/01/2010
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: RESPONSE
Date: 01/16/2006
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: RESPONSE
Date: 01/31/2006
Action: Corrective Action Plan / Remedial Action Plan

Global Id: T0604300083
Action Type: RESPONSE
Date: 12/15/2005
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: RESPONSE
Date: 12/08/2005
Action: Other Report / Document

CDF MARIPOSA (Continued) **S105033936**

Global Id: T0604300083
Action Type: RESPONSE
Date: 11/21/2005
Action: Other Workplan

Global Id: T0604300083
Action Type: RESPONSE
Date: 08/01/2012
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0604300083
Action Type: RESPONSE
Date: 02/01/2013
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0604300083
Action Type: RESPONSE
Date: 05/07/2012
Action: Corrective Action Plan / Remedial Action Plan - Regulator Responded

Global Id: T0604300083
Action Type: RESPONSE
Date: 04/15/2013
Action: Corrective Action Plan / Remedial Action Plan - Addendum - Regulator Responded

Global Id: T0604300083
Action Type: RESPONSE
Date: 12/26/2014
Action: Well Installation Workplan - Regulator Responded

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 10/21/2005
Action: Staff Letter

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 10/26/2006
Action: Verbal Communication

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 05/17/2006
Action: Verbal Communication

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 11/18/2005
Action: 13267 Requirement

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 11/01/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0604300083
Action Type: ENFORCEMENT

CDF MARIPOSA (Continued) **S105033936**

Date: 04/03/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 08/28/2007
Action: Verbal Communication

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 04/29/2009
Action: Verbal Enforcement

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 01/29/2003
Action: Staff Letter - #5-01-712

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 01/25/2008
Action: Verbal Communication

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 12/24/2008
Action: Technical Correspondence / Assistance / Other

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 09/15/2009
Action: Technical Correspondence / Assistance / Other

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 11/25/2009
Action: Staff Letter

Global Id: T0604300083
Action Type: Other
Date: 03/02/2000
Action: Leak Stopped

Global Id: T0604300083
Action Type: RESPONSE
Date: 05/01/2010
Action: Monitoring Report - Quarterly

Global Id: T0604300083
Action Type: RESPONSE
Date: 06/30/2003
Action: Soil and Water Investigation Report

Global Id: T0604300083
Action Type: RESPONSE
Date: 02/14/2011
Action: CAP/RAP - Feasibility Study Report - Regulator Responded

CDF MARIPOSA (Continued) **S105033936**

Global Id: T0604300083
Action Type: RESPONSE
Date: 05/01/2011
Action: Monitoring Report - Quarterly - Regulator Responded

Global Id: T0604300083
Action Type: RESPONSE
Date: 08/01/2011
Action: Monitoring Report - Quarterly - Regulator Responded

Global Id: T0604300083
Action Type: RESPONSE
Date: 12/01/2011
Action: Monitoring Report - Semi-Annually - Regulator Responded

Global Id: T0604300083
Action Type: RESPONSE
Date: 02/05/2019
Action: Request for Closure - Regulator Responded

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 09/25/2002
Action: Meeting

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 01/13/2003
Action: Meeting

Global Id: T0604300083
Action Type: ENFORCEMENT
Date: 02/17/2004
Action: Staff Letter

LUST:
Global Id: T0604300083
Status: Open - Case Begin Date
Status Date: 03/02/2000

Global Id: T0604300083
Status: Open - Site Assessment
Status Date: 03/09/2000

Global Id: T0604300083
Status: Open - Site Assessment
Status Date: 07/19/2001

Global Id: T0604300083
Status: Open - Site Assessment
Status Date: 10/18/2001

Global Id: T0604300083
Status: Open - Remediation
Status Date: 12/12/2002

Global Id: T0604300083

CDF MARIPOSA (Continued) **S105033936**

Status: Open - Remediation
Status Date: 02/21/2003

Global Id: T0604300083
Status: Open - Remediation
Status Date: 01/30/2006

Global Id: T0604300083
Status: Open - Verification Monitoring
Status Date: 01/27/2016

Global Id: T0604300083
Status: Open - Eligible for Closure
Status Date: 09/17/2019

Global Id: T0604300083
Status: Completed - Case Closed
Status Date: 12/30/2019

LUST REG 5:
Name: MARIPOSA RANGER UNIT HEADQUARTERS
Address: 5366 HIGHWAY 49 N
City: MARIPOSA
Region: 5
Status: Remediation Plan
Case Number: 5T22000127
Case Type: Drinking Water Aquifer affected
Substance: DIESEL
Staff Initials: WWG
Lead Agency: Regional
Program: LUST
MTBE Code: 6

CORTESE:
Name: MARIPOSA RANGER UNIT HEADQUARTERS
Address: 5366 HIGHWAY 49 N
City,State,Zip: MARIPOSA, CA 95338
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0604300083
Site/Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Status Date: Not reported
Site Code: Not reported
Latitude: Not reported
Longitude: Not reported
Owner: Not reported
Enf Type: Not reported
Swat R: Not reported
Flag: active
Order No: Not reported
Waste Discharge System No: Not reported
Effective Date: Not reported
Region 2: Not reported
WID Id: Not reported

CDF MARIPOSA (Continued) **S105033936**

Solid Waste Id No: Not reported
Waste Management Uit Name: Not reported
File Name: Active Open

EMI:

Name: CDF MARIPOSA
Address: 5366 HIGHWAY 49 N
City,State,Zip: MARIPOSA, CA 953380000
Year: 2002
County Code: 22
Air Basin: MC
Facility ID: 28
Air District Name: MPA
SIC Code: 851
Air District Name: MARIPOSA COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: CDF MARIPOSA
Address: 5366 HIGHWAY 49 N
City,State,Zip: MARIPOSA, CA 953380000
Year: 2003
County Code: 22
Air Basin: MC
Facility ID: 28
Air District Name: MPA
SIC Code: 851
Air District Name: MARIPOSA COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: 0
NOX - Oxides of Nitrogen Tons/Yr: 0
SOX - Oxides of Sulphur Tons/Yr: 0
Particulate Matter Tons/Yr: 0
Part. Matter 10 Micrometers and Smllr Tons/Yr: 0

Name: CDF MARIPOSA
Address: 5366 HIGHWAY 49 N
City,State,Zip: MARIPOSA, CA 953380000
Year: 2004
County Code: 22
Air Basin: MC
Facility ID: 28
Air District Name: MPA
SIC Code: 851
Air District Name: MARIPOSA COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported

CDF MARIPOSA (Continued) **S105033936**

Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 953380000
Year:	2005
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 953380000
Year:	2006
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95691
Year:	2007
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851

CDF MARIPOSA (Continued) **S105033936**

Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2008
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2009
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2010
County Code:	22
Air Basin:	MC

CDF MARIPOSA (Continued) **S105033936**

Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2011
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2012
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338

CDF MARIPOSA (Continued) **S105033936**

Year:	2013
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2014
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2015
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

CDF MARIPOSA (Continued) **S105033936**

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2016
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2017
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2018
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported

CDF MARIPOSA (Continued) **S105033936**

Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2019
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2020
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not reported
NOX - Oxides of Nitrogen Tons/Yr:	Not reported
SOX - Oxides of Sulphur Tons/Yr:	Not reported
Particulate Matter Tons/Yr:	Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2021
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0

CDF MARIPOSA (Continued) **S105033936**

Carbon Monoxide Emissions Tons/Yr: Not reported
NOX - Oxides of Nitrogen Tons/Yr: Not reported
SOX - Oxides of Sulphur Tons/Yr: Not reported
Particulate Matter Tons/Yr: Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr: Not reported

Name: CDF MARIPOSA
Address: 5366 HIGHWAY 49 N
City,State,Zip: MARIPOSA, CA 95338
Year: 2022
County Code: 22
Air Basin: MC
Facility ID: 28
Air District Name: MPA
SIC Code: 851
Air District Name: MARIPOSA COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0
Reactive Organic Gases Tons/Yr: 0
Carbon Monoxide Emissions Tons/Yr: Not reported
NOX - Oxides of Nitrogen Tons/Yr: Not reported
SOX - Oxides of Sulphur Tons/Yr: Not reported
Particulate Matter Tons/Yr: Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr: Not reported

Name: CDF MARIPOSA
Address: 5366 HIGHWAY 49 N
City,State,Zip: MARIPOSA, CA 95338
Year: 2023
County Code: 22
Air Basin: MC
Facility ID: 28
Air District Name: MPA
SIC Code: 851
Air District Name: MARIPOSA COUNTY APCD
Community Health Air Pollution Info System: Not reported
Consolidated Emission Reporting Rule: Not reported
Total Organic Hydrocarbon Gases Tons/Yr: 0.35
Reactive Organic Gases Tons/Yr: 0.30975
Carbon Monoxide Emissions Tons/Yr: Not reported
NOX - Oxides of Nitrogen Tons/Yr: Not reported
SOX - Oxides of Sulphur Tons/Yr: Not reported
Particulate Matter Tons/Yr: Not reported
Part. Matter 10 Micrometers and Smllr Tons/Yr: Not reported

CERS:
Name: MARIPOSA RANGER UNIT HEADQUARTERS
Address: 5366 HIGHWAY 49 N
City,State,Zip: MARIPOSA, CA 95338
Site ID: 862103
CERS ID: T0604300083
CERS Description: Leaking Underground Storage Tank Cleanup Site

Affiliation:
Affiliation Type Desc: Regional Board Caseworker
Entity Name: BENJAMIN LEHMANN - CENTRAL VALLEY RWQCB (REGION 5S)

CDF MARIPOSA (Continued) **S105033936**

Entity Title:	Not reported
Affiliation Address:	11020 Sun Center Drive #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	9164644760,
Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	KERRI GIBBONS - MARIPOSA COUNTY
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	r5 UNKNOWN
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

A5 **MARIPOSA RANGER UNIT HEAD** **HIST CORTESE** **S105024876**
NW **5366 49** **N/A**
1/8-1/4 **MARIPOSA, CA 95338**
0.149 mi.
788 ft. **Site 5 of 13 in cluster A**

Relative: HIST CORTESE:
Higher

Actual: edr_fname:	MARIPOSA RANGER UNIT HEAD
2195 ft. edr_fadd1:	5366 49
City,State,Zip:	MARIPOSA, CA 95338
Region:	CORTESE
Facility County Code:	22
Reg By:	LTNKA
Reg Id:	5T22000127

A6 **MARIPOSA FOREST FIRE STATION** **SWEEPS UST** **S106929130**
NW **5366 N HWY 49** **N/A**
1/8-1/4 **MARIPOSA, CA 95338**
0.149 mi.
788 ft. **Site 6 of 13 in cluster A**

Relative: SWEEPS UST:
Higher

Actual: Name:	MARIPOSA FOREST FIRE STATION
2195 ft. Address:	5366 N HWY 49
City:	MARIPOSA
Status:	Active
Comp Number:	19923
Number:	6
Board Of Equalization:	44-032062
Referral Date:	12-17-91
Action Date:	09-23-92
Created Date:	02-29-88
Owner Tank Id:	F-MAR-02
SWRCB Tank Id:	22-000-019923-000001
Tank Status:	A
Capacity:	2000
Active Date:	12-17-91

MARIPOSA FOREST FIRE STATION (Continued) **S106929130**

Tank Use:	M.V. FUEL
STG:	P
Content:	REG UNLEADED
Number Of Tanks:	2
Name:	MARIPOSA FOREST FIRE STATION
Address:	5366 N HWY 49
City:	MARIPOSA
Status:	Active
Comp Number:	19923
Number:	6
Board Of Equalization:	44-032062
Referral Date:	12-17-91
Action Date:	09-23-92
Created Date:	02-29-88
Owner Tank Id:	F-MAR-01
SWRCB Tank Id:	22-000-019923-000002
Tank Status:	A
Capacity:	550
Active Date:	12-17-91
Tank Use:	M.V. FUEL
STG:	P
Content:	DIESEL
Number Of Tanks:	Not reported

A7 **DEPT OF FORESTRY & FIRE** **E MANIFEST** **1032005274**
NW **5366 STATE HIGHWAY 49 N** **N/A**
1/8-1/4 **MARIPOSA, CA 95338**
0.149 mi.
788 ft. **Site 7 of 13 in cluster A**

Relative: **Higher**

Actual: **2195 ft.**

E MANIFEST:

Manifest Tracking Number:	022517050JJK
Last Updated Date:	20210505
Shipped Date:	20210325
Received Date:	20210407
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CAL000059136
Generator Name:	Dept Of Forestry & Fire
Generator Location Street Number:	Not reported
Generator Location Street 1:	5366 STATE HIGHWAY 49 N
Generator Location Street 2:	Not reported
Generator Location City:	MARIPOSA
Generator Location State:	CA
Generator Location Zip:	95338-9503
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	5366 STATE HIGHWAY 49 N
Generator Mail Street 2:	Not reported
Generator Mail City:	MARIPOSA
Generator Mail Zip:	95338-9503
Generator Mail State:	CA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	AZR000521146
Designated Facility Name:	Yuma Yes 2 Waste Transfer Station
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	STE 105

DEPT OF FORESTRY & FIRE (Continued) **1032005274**

Designated Facility Mail Street 2: 2621 GREEN RIVER RD
Designated Facility Mail City: CORONA
Designated Facility Mail Zip: 92882
Designated Facility Mail State: CA
Designated Facility Location Street Number: Not reported
Designated Facility Location Street 1: 6500 S US HIGHWAY 95
Designated Facility Location Street 2: Not reported
Designated Facility Location City: YUMA
Designated Facility Location Zip: 85365
Designated Facility Location State: AZ
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:
Manifest Tracking Number: 022517050JJK
Transporter Line Number: 1
Transporter EPA ID: CAR000272302
Transporter Name: American Valley Waste Oil Inc

Manifest Tracking Number: 022517050JJK
Transporter Line Number: 2
Transporter EPA ID: CAR000175422
Transporter Name: Worldwide Recovery System Inc

Waste Line:
Manifest Tracking Number: 022517050JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: N
U.S. DOT ID Number: Not reported
U.S. DOT Description: Not reported
Non-Hazardous Waste Description: Non-Rcra Hazardous Waste Solid (Absorbents, Paper Oil Filters & Debris)
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 180
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.09
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.09
Waste Quantity, in Kilograms: 81.632706
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 81.632706
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported

DEPT OF FORESTRY & FIRE (Continued) **1032005274**

Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	81.632706
Quantity Non Haz Tons:	0.09
State Waste Codes:	CA-352

A8 **MARIPOSA RANGER UNIT HEADQUARTERS** **UST FINDER RELEASE** **1029018516**
NW **5366 HIGHWAY 49 N** **N/A**
1/8-1/4 **MARIPOSA, CA 95338**
0.149 mi.
788 ft. **Site 8 of 13 in cluster A**

Relative: **Higher**

Actual: **2195 ft.**

UST FINDER RELEASE:

Object ID:	54458
Facility ID:	Not reported
Lust ID:	CAT0604300083
Name:	MARIPOSA RANGER UNIT HEADQUARTERS
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Address Match Type:	PointAddress
Reported Date:	Not reported
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	30
Domestic Wells within 1500ft:	6
Land Use:	Developed, Low Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	CA2210942_54742
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	180400011502
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	9
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-119.98815
Y Coord:	37.50174
Latitude:	37.5017399999999
Longitude:	-119.98815

A9
NW
1/8-1/4
0.149 mi.
788 ft.

CDF MARIPOSA STATION
5366 STATE HIGHWAY 49 N
MARIPOSA, CA 95338

Site 9 of 13 in cluster A

E MANIFEST | **1031920989** | **N/A**

Relative:
Higher

Actual:
2195 ft.

E MANIFEST:

Manifest Tracking Number:	006960234SKS
Last Updated Date:	20190827
Shipped Date:	20190711
Received Date:	20190730
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CAL000059136
Generator Name:	Cdf Mariposa Station
Generator Location Street Number:	Not reported
Generator Location Street 1:	5366 STATE HIGHWAY 49 N
Generator Location Street 2:	Not reported
Generator Location City:	MARIPOSA
Generator Location State:	CA
Generator Location Zip:	95338
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	5366 State Highway 49 N
Generator Mail Street 2:	Not reported
Generator Mail City:	Mariposa
Generator Mail Zip:	95338
Generator Mail State:	CA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	ORQ000025197
Designated Facility Name:	Thermo Fluids, Inc.
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	12533 SE Carpenter Drive
Designated Facility Mail City:	Clackamas
Designated Facility Mail Zip:	97015
Designated Facility Mail State:	OR
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	12533 SE Carpenter Drive
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Clackamas
Designated Facility Location Zip:	97015
Designated Facility Location State:	OR
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006960234SKS
Transporter Line Number:	1
Transporter EPA ID:	TXR000081205
Transporter Name:	Safety-Kleen Systems, Inc.
Manifest Tracking Number:	006960234SKS
Transporter Line Number:	2
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.
Manifest Tracking Number:	006960234SKS

CDF MARIPOSA STATION (Continued) **1031920989**

Transporter Line Number: 3
Transporter EPA ID: MOD095038998
Transporter Name: Bed Rock Inc Dba Tri State Motor Transit Co

Waste Line:
Manifest Tracking Number: 006960234SKS
Waste Line Number: 1
U.S. DOT Hazardous Indicator: N
U.S. DOT ID Number: Not reported
U.S. DOT Description: Not reported
Non-Hazardous Waste Description: None, Non-Rcra Hazardous Waste, Solid (Drained/Undrained Used Oil Filters), N/A, None
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 250
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.125
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.125
Waste Quantity, in Kilograms: 113.37875
Acute Waste Quantity, in Kilograms: 0
Non-Acute Waste Quantity, in Kilorgrams: 113.37875
Management Method Code: H141
Management Method Description: STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator: N
Quantity Discrepancy Indicator: N
Waste Type Discrepancy Indicator: N
Waste Density: Not reported
Waste Density Unit of Measure Code: Not reported
Waste Density Unit of Measure Description: Not reported
Form Code: Not reported
Form Code Description: Not reported
Source Code: Not reported
Source Code Description: Not reported
Waste Minimization Code: Not reported
Waste Minimization Code Description: Not reported
Consent Number: Not reported
EPA Waste Indicator: N
Federal Waste Codes: Not reported
Quantity Haz Kg: 0
Quantity Haz Tons: 0
Quantity Non Haz Kg: 113.37875
Quantity Non Haz Tons: 0.125
State Waste Codes: CA-223

A10 **CAL FIRE MARIPOSA** **AST** **A100418045**
NW **5366 STATE HIGHWAY 49 N** **N/A**
1/8-1/4 **MARIPOSA, CA 95338**
0.149 mi.
788 ft. **Site 10 of 13 in cluster A**

Relative: AST:
Higher
Name: CAL FIRE MARIPOSA
Actual: Address: 5366 STATE HIGHWAY 49 N
2195 ft. City/Zip: MARIPOSA,95338

CAL FIRE MARIPOSA (Continued) **A100418045**

Certified Unified Program Agencies:	Not reported
Owner:	State of California
Total Gallons:	Not reported
CERSID:	10197982
Facility ID:	Not reported
Business Name:	CAL FIRE MMU
Phone:	209-966-3622
Fax:	209-966-4513
Mailing Address:	5366 Hwy 49 North
Mailing Address City:	Mariposa
Mailing Address State:	CA
Mailing Address Zip Code:	95338
Operator Name:	CAL FIRE Mariposa Station
Operator Phone:	209-966-4700
Owner Phone:	209-966-3622
Owner Mail Address:	5366 Hwy 49 North
Owner State:	CA
Owner Zip Code:	95338
Owner Country:	United States
Property Owner Name:	Not reported
Property Owner Phone:	Not reported
Property Owner Mailing Address:	Not reported
Property Owner City:	Not reported
Property Owner Stat :	Not reported
Property Owner Zip Code:	Not reported
Property Owner Country:	Not reported
EPAID:	CAL000059136

A11 **CAL-FIRE** **E MANIFEST** **1031910761**
NW **5366 HWY. 49 N.** **N/A**
1/8-1/4 **MARIPOSA, CA 95338**
0.149 mi.
788 ft. **Site 11 of 13 in cluster A**

Relative:
Higher

Actual:
2195 ft.

E MANIFEST:

Manifest Tracking Number:	100093333ELC
Last Updated Date:	20240410
Shipped Date:	20240408
Received Date:	20240409
Manifest Status:	Signed
Submission Type:	FullElectronic
Origin Type:	Web
Generator EPA ID:	CAC003277030
Generator Name:	Cal-Fire
Generator Location Street Number:	Not reported
Generator Location Street 1:	5366 HWY. 49 N.
Generator Location Street 2:	Not reported
Generator Location City:	MARIPOSA
Generator Location State:	CA
Generator Location Zip:	95338
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	5366 HWY. 49 N.
Generator Mail Street 2:	Not reported
Generator Mail City:	MARIPOSA
Generator Mail Zip:	95338
Generator Mail State:	CA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	CAD982042475

CAL-FIRE (Continued) **1031910761**

Designated Facility Name:	Recology Hay Road
Designated Facility Mail Street Number:	235
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	N FIRST ST
Designated Facility Mail City:	DIXON
Designated Facility Mail Zip:	95620
Designated Facility Mail State:	CA
Designated Facility Location Street Number:	6426
Designated Facility Location Street 1:	HAY RD
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	VACAVILLE
Designated Facility Location Zip:	95687
Designated Facility Location State:	CA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	100093333ELC
Transporter Line Number:	1
Transporter EPA ID:	CAL000354470
Transporter Name:	Cve Contracting Group Inc.

Waste Line:

Manifest Tracking Number:	100093333ELC
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA2212
U.S. DOT Description:	Rq,Na2212,Asbestos,9,Pgiii
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	BA
Container Type Description:	Burlap, cloth, paper, or plastic bags
Waste Quantity:	1
Quantity Unit of Measure Code:	Y
Quantity Unit of Measure Description:	Cubic Yards
Waste Quantity, in Tons:	0.84
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.84
Waste Quantity, in Kilograms:	761.9052
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	761.9052
Management Method Code:	H132
Management Method Description:	LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported

CAL-FIRE (Continued) **1031910761**

Consent Number:	Not reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not reported
Quantity Haz Kg:	Not reported
Quantity Haz Tons:	Not reported
Quantity Non Haz Kg:	761.9052
Quantity Non Haz Tons:	0.84
State Waste Codes:	CA-151

A12 **MARIPOSA HDQS F.F.S.** **HIST UST** **U001606370**
NW **5366 STATE HIGHWAY 49 N** **N/A**
1/8-1/4 **MARIPOSA, CA 95338**
0.149 mi.
788 ft. **Site 12 of 13 in cluster A**

Relative:
Higher

Actual:
2195 ft.

HIST UST:

Name:	MARIPOSA HDQS F.F.S.
Address:	5366 STATE HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
File Number:	Not reported
URL:	Not reported
Region:	STATE
Facility ID:	00000019923
Facility Type:	Other
Other Type:	STATE GOVERNMENT
Contact Name:	GLENN MICHAEL SFR-I
Telephone:	2099663622
Owner Name:	CALIF. DEPT. OF FORESTRY
Owner Address:	1416 NINTH ST.
Owner City,St,Zip:	SACRAMENTO, CA 95814
Total Tanks:	0002
Tank Num:	001
Container Num:	4200-T01
Year Installed:	1982
Tank Capacity:	00002000
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Container Construction Thickness:	10
Leak Detection:	None
Tank Num:	002
Container Num:	4200-T02
Year Installed:	1966
Tank Capacity:	00000550
Tank Used for:	PRODUCT
Type of Fuel:	DIESEL
Container Construction Thickness:	Not reported
Leak Detection:	None

A13
NW
1/8-1/4
0.149 mi.
788 ft.

CAL FIRE MARIPOSA
5366 STATE HIGHWAY 49 N
MARIPOSA, CA 95338

Site 13 of 13 in cluster A

CERS HAZ WASTE
CERS TANKS
CERS

S121737111
N/A

Relative:
Higher

Actual:
2195 ft.

CERS HAZ WASTE:

Name:	CAL FIRE MARIPOSA
Address:	5366 STATE HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Site ID:	101436
CERS ID:	10197982
CERS Description:	Hazardous Waste Generator

CERS TANKS:

Name:	CAL FIRE MARIPOSA
Address:	5366 STATE HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Site ID:	101436
CERS ID:	10197982
CERS Description:	Aboveground Petroleum Storage

CERS:

Name:	CAL FIRE MARIPOSA
Address:	5366 STATE HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Site ID:	101436
CERS ID:	10197982
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to comply with one or more of the following requirements: 1. Have record of inspections and integrity tests signed by the appropriate supervisor or inspector. 2. Keep written procedures and records of inspections and integrity tests for at least three years. 3. Keep comparison records.
Violation Notes:	Returned to compliance on 03/30/2017. Records of inspections must be kept and available for 3 years.
Violation Division:	Mariposa County Public Health Department
Violation Program:	APSA
Violation Source:	CERS,

Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to provide the following training to all oil-handling personnel: 1. Operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations. 5. Contents of the SPCC Plan.
Violation Notes:	Returned to compliance on 03/30/2017. Training is required annually per SPCC Plan. No records of training since 2012 were available.

CAL FIRE MARIPOSA (Continued) **S121737111**

Violation Division:	Mariposa County Public Health Department
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	01-22-2020
Citation:	HSC 6.5 25160(b)(1)(C) - California Health and Safety Code, Chapter 6.5, Section(s) 25160(b)(1)(C)
Violation Description:	Failure to send a legible copy of each hazardous waste manifest to the Department within 30 days of each shipment of hazardous waste.
Violation Notes:	Observation: The generator failed to determine the status of a uniform hazardous waste manifested shipment within 35 days from the date the waste was shipped, and/or to submit an exception report to DTSC if a signed copy of the manifest isn't received within 45 days of the date the waste was accepted by the intitial transporter. CORRECTIVE ACTION: Submit documentation to the CUPA demonstrating that the generator has determined the status of the hazardous waste manifest shipment for [LIST MANIFESTS], or a copy of the exception report submitted to DTSC, if applicable.
Violation Division:	Mariposa County Public Health Department
Violation Program:	HW
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes:	Returned to compliance on 06/13/2017. OBSERVATION: The facility has not annually reviewed and certified that the business plan is complete, accurate, and up-to-date. CORRECTIVE ACTION: Review, revise, and certify the business plan electronically in the California Environmental Reporting System (CERS).
Violation Division:	Mariposa County Public Health Department
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Description:	Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes:	Returned to compliance on 03/10/2017. Please dispose of used antifreeze and flammable liquid in smaller drum outside of shop. Used

CAL FIRE MARIPOSA (Continued) **S121737111**

oil filters need to be disposed of as well.
Violation Division: Mariposa County Public Health Department
Violation Program: HW
Violation Source: CERS,

Site ID: 101436
Site Name: CAL FIRE Mariposa
Violation Date: 12-16-2014
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes: Returned to compliance on 03/23/2015. Please continue to update the inventory: argon gas quantity and location, Solvent -dewaxed, kerosene etc.
Violation Division: Mariposa County Public Health Department
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 101436
Site Name: CAL FIRE Mariposa
Violation Date: 02-28-2017
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes: Returned to compliance on 06/13/2017. Please update inventory in CERS. Need to remove solvent and flares. Please add 55 gallon drum of bar oil to inventory location #16.
Violation Division: Mariposa County Public Health Department
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 101436
Site Name: CAL FIRE Mariposa
Violation Date: 02-28-2017
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description: Failure to include in the SPCC plan and document discharge prevention briefings for oil-handling personnel at least once a year, including, but not limited to, known discharges, failures, and malfunctioning components.
Violation Notes: Returned to compliance on 03/30/2017. No records of annual spill prevention briefings were available. Need to determine if briefings may be covered by some other training topic.
Violation Division: Mariposa County Public Health Department
Violation Program: APSA
Violation Source: CERS,

Site ID: 101436
Site Name: CAL FIRE Mariposa
Violation Date: 01-22-2020
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description: Failure to complete and electronically submit hazardous material

CAL FIRE MARIPOSA (Continued) **S121737111**

inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes: Returned to compliance on 01/22/2020. OBSERVATION: Facility must update inventory to include correct quantities of oxygen onsite. also must update to iclude waste oil and waste antifreeze CORRECTIVE ACTION: Complete and electronically submit the chemical inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Division: Mariposa County Public Health Department
Violation Program: HMRRP
Violation Source: CERS,

Site ID: 101436
Site Name: CAL FIRE Mariposa
Violation Date: 02-28-2017
Citation: 40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description: Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes: Returned to compliance on 08/14/2017. OBSERVATION: Used antifreeze container was open with a funnel in it.. All hazardous waste containers shall be closed at all times except when adding or removing waste. CORRECTIVE ACTION: Immediately close these containers and ensure all hazardous waste containers are closed when not adding or removing waste.
Violation Division: Mariposa County Public Health Department
Violation Program: HW
Violation Source: CERS,

Site ID: 101436
Site Name: CAL FIRE Mariposa
Violation Date: 12-16-2014
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description: Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes: Returned to compliance on 08/09/2017. Please label all containers of hazardous waste with CA Hazardous Waste labels (used antifreeze, waste parts cleaner solvent)
Violation Division: Mariposa County Public Health Department
Violation Program: HW
Violation Source: CERS,

Evaluation:
Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-22-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mariposa County Public Health Department
Eval Program: HW

CAL FIRE MARIPOSA (Continued) **S121737111**

Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-28-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mariposa County Public Health Department
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 05-19-2015
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Not reported
Eval Division: Mariposa County Public Health Department
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-22-2020
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mariposa County Public Health Department
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 01-22-2020
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mariposa County Public Health Department
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-16-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Overall very well maintained facility.
Eval Division: Mariposa County Public Health Department
Eval Program: HMRRP
Eval Source: CERS,

Eval General Type: Other/Unknown
Eval Date: 05-19-2015
Violations Found: No
Eval Type: Other, not routine, done by local agency
Eval Notes: Not reported
Eval Division: Mariposa County Public Health Department
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection

CAL FIRE MARIPOSA (Continued) **S121737111**

Eval Date: 12-16-2014
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: We will need to see all manifests for hazardous waste shipments for the last three years in order to determine whether the facility is in compliance. Please attach an identifying label to the kerosene drum. Please manage used absorbent as hazardous waste.
Eval Division: Mariposa County Public Health Department
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-28-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Not reported
Eval Division: Mariposa County Public Health Department
Eval Program: APSA
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 02-28-2017
Violations Found: Yes
Eval Type: Routine done by local agency
Eval Notes: Ensure that empty containers are labeled empty with the date emptied and managed with in one year. (Reuse or scrap metal)
Eval Division: Mariposa County Public Health Department
Eval Program: HW
Eval Source: CERS,

Eval General Type: Compliance Evaluation Inspection
Eval Date: 12-16-2014
Violations Found: No
Eval Type: Routine done by local agency
Eval Notes: We will need to see the records for inspections testing and training for the aboveground tank program in order to determine whether the facility is in compliance.
Eval Division: Mariposa County Public Health Department
Eval Program: APSA
Eval Source: CERS,

Coordinates:
Site ID: 101436
Facility Name: CAL FIRE Mariposa
Env Int Type Code: HWG
Program ID: 10197982
Coord Name: Not reported
Ref Point Type Desc: Center of a facility or station.,
Latitude: 37.502960
Longitude: -119.987130

Affiliation:
Affiliation Type Desc: Document Preparer
Entity Name: Brandon Wedge
Entity Title: Not reported
Affiliation Address: Not reported

CAL FIRE MARIPOSA (Continued) **S121737111**

Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title: Not reported
Affiliation Address: 5366 Hwy 49 North
Affiliation City: Mariposa
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95338
Affiliation Phone: ,

Affiliation Type Desc: Identification Signer
Entity Name: Brandon Wedge
Entity Title: Fire Captain
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Legal Owner
Entity Name: STATE OF CALIFORNIA
Entity Title: Not reported
Affiliation Address: 5366 Hwy 49 North
Affiliation City: Mariposa
Affiliation State: CA
Affiliation Country: United States
Affiliation Zip: 95338
Affiliation Phone: (209) 966-3622,

Affiliation Type Desc: Parent Corporation
Entity Name: Cal Fire MMU
Entity Title: Not reported
Affiliation Address: Not reported
Affiliation City: Not reported
Affiliation State: Not reported
Affiliation Country: Not reported
Affiliation Zip: Not reported
Affiliation Phone: ,

Affiliation Type Desc: Environmental Contact
Entity Name: DUTY OFFICER
Entity Title: Not reported
Affiliation Address: 5366 Highway 49 North
Affiliation City: Mariposa
Affiliation State: CA
Affiliation Country: Not reported
Affiliation Zip: 95338
Affiliation Phone: ,

Affiliation Type Desc: Operator

CAL FIRE MARIPOSA (Continued) **S121737111**

Entity Name:	CAL FIRE Mariposa Station
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	Not reported
Affiliation State:	Not reported
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	(209) 966-4700,
Affiliation Type Desc:	CUPA District
Entity Name:	Mariposa County Public Health Department
Entity Title:	Not reported
Affiliation Address:	5100 Bullion Street
Affiliation City:	Mariposa
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	95338
Affiliation Phone:	(209) 966-2220,

B14 **MARIPOSA COUNTY HEALTH DEPARTMENT** **RCRA NonGen / NLR** **1026057135**
SE **5300 HWY 49N** **CAL000453328**
1/8-1/4 **MARIPOSA, CA 95338**
0.202 mi.
1064 ft. **Site 1 of 2 in cluster B**

Relative: **Lower**

Actual: **2101 ft.**

RCRA Listings:

Date Form Received by Agency:	20200306
Handler Name:	Mariposa County Health Department
Handler Address:	5300 Hwy 49n
Handler City,State,Zip:	MARIPOSA, CA 95338
EPA ID:	CAL000453328
Contact Name:	MARGARITA KING
Contact Address:	5300 HWY 49N
Contact City,State,Zip:	MARIPOSA, CA 95338
Contact Telephone:	209-742-1352
Contact Fax:	209-966-4929
Contact Email:	MARGARITAKING@MARIPOSASCOUNTY.ORG
Contact Title:	Not reported
EPA Region:	09
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	5300 HWY 49N
Mailing City,State,Zip:	MARIPOSA, CA 95338
Owner Name:	Mariposa County Health Department
Owner Type:	Other
Operator Name:	Margarita King
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

MARIPOSA COUNTY HEALTH DEPARTMENT (Continued) **1026057135**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200306
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MARIPOSA COUNTY HEALTH DEPARTMENT	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	5300 HWY 49N
Owner/Operator City,State,Zip:	MARIPOSA, CA 95338
Owner/Operator Telephone:	209-966-3689
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MARGARITA KING	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	5300 HWY 49N

MARIPOSA COUNTY HEALTH DEPARTMENT (Continued) **1026057135**

Owner/Operator City,State,Zip: MARIPOSA, CA 95338
Owner/Operator Telephone: 209-742-1352
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20200306
Handler Name: MARIPOSA COUNTY HEALTH DEPARTMENT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 923120
NAICS Description: Administration Of Public Health Programs

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

B15 **MARIPOSA COUNTY HEALTH AND HUM** **E MANIFEST** **1032163792**
SE **5300 HIGHWAY 49 N** **N/A**
1/8-1/4 **MARIPOSA, CA 95338**
0.202 mi.
1064 ft. **Site 2 of 2 in cluster B**

Relative: E MANIFEST:
Lower
Actual: Manifest Tracking Number: 200913539CLE
2101 ft. Last Updated Date: 20241001
Shipped Date: 20240827
Received Date: 20240919
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: CAL000453328
Generator Name: Mariposa County Health And Hum
Generator Location Street Number: Not reported
Generator Location Street 1: 5300 HIGHWAY 49 N
Generator Location Street 2: Not reported
Generator Location City: MARIPOSA
Generator Location State: CA
Generator Location Zip: 95338
Generator Mail Street Number: Not reported
Generator Mail Street 1: 5300 HIGHWAY 49 N
Generator Mail Street 2: Not reported

MARIPOSA COUNTY HEALTH AND HUM (Continued) **1032163792**

Generator Mail City:	MARIPOSA
Generator Mail Zip:	95338
Generator Mail State:	CA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NVD980895338
Designated Facility Name:	21st Century Environmental Mgmt Of Nv, Llc
Designated Facility Mail Street Number:	2095
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	NEWLANDS DR. EAST
Designated Facility Mail City:	FERNLEY
Designated Facility Mail Zip:	89436
Designated Facility Mail State:	NV
Designated Facility Location Street Number:	2095
Designated Facility Location Street 1:	NEWLANDS DR. EAST
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	FERNLEY
Designated Facility Location Zip:	89436
Designated Facility Location State:	NV
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Manifest Tracking Number:	200374193CLE
Last Updated Date:	20230314
Shipped Date:	20230207
Received Date:	20230303
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CAL000453328
Generator Name:	Mariposa County Health And Hum
Generator Location Street Number:	Not reported
Generator Location Street 1:	5300 HIGHWAY 49 N
Generator Location Street 2:	Not reported
Generator Location City:	MARIPOSA
Generator Location State:	CA
Generator Location Zip:	95338
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	5300 Highway 49 N
Generator Mail Street 2:	Not reported
Generator Mail City:	Mariposa
Generator Mail Zip:	95338
Generator Mail State:	CA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	NVD980895338
Designated Facility Name:	21st Century Environmental Management Of Nevada, Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	2095 Newlands Drive East
Designated Facility Mail City:	Fernley
Designated Facility Mail Zip:	89408
Designated Facility Mail State:	NV
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	2095 Newlands Drive East
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Fernley
Designated Facility Location Zip:	89408

MARIPOSA COUNTY HEALTH AND HUM (Continued) **1032163792**

Designated Facility Location State:	NV
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N
Manifest Tracking Number:	015627979FLE
Last Updated Date:	20210506
Shipped Date:	20210401
Received Date:	20210422
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CAL000453328
Generator Name:	Mariposa County Health And Hum
Generator Location Street Number:	Not reported
Generator Location Street 1:	5300 HIGHWAY 49 N
Generator Location Street 2:	Not reported
Generator Location City:	MARIPOSA
Generator Location State:	CA
Generator Location Zip:	95338
Generator Mail Street Number:	Not reported
Generator Mail Street 1:	5300 Highway 49 N
Generator Mail Street 2:	Not reported
Generator Mail City:	Mariposa
Generator Mail Zip:	95338
Generator Mail State:	CA
Generator Contact Company Name:	Not reported
Designated Facility EPA ID:	CAD980884183
Designated Facility Name:	Gem Rancho Cordova Llc
Designated Facility Mail Street Number:	Not reported
Designated Facility Mail Street 1:	Not reported
Designated Facility Mail Street 2:	11855 White Rock Road
Designated Facility Mail City:	Rancho Cordova
Designated Facility Mail Zip:	95742
Designated Facility Mail State:	CA
Designated Facility Location Street Number:	Not reported
Designated Facility Location Street 1:	11855 White Rock Road
Designated Facility Location Street 2:	Not reported
Designated Facility Location City:	Rancho Cordova
Designated Facility Location Zip:	95742
Designated Facility Location State:	CA
Designated Facility Contact Company Name:	Not reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	015627979FLE
Transporter Line Number:	1
Transporter EPA ID:	MNS000110924
Transporter Name:	Clean Earth Specialty Waste Solutions

Waste Line:

Manifest Tracking Number:	015627979FLE
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	UN3248

MARIPOSA COUNTY HEALTH AND HUM (Continued) **1032163792**

U.S. DOT Description:	Un3248, Waste Medicine, Liquid, Flammable, Toxic, N.O.S. (Alcohol, Phenol), 3 (6.1), Pg Ii, (Ltd Qty), Erg#131
Non-Hazardous Waste Description:	Not reported
Number of Containers:	1
Container Type Code:	DF
Container Type Description:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	8
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.004
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.004
Waste Quantity, in Kilograms:	3.6281202
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	3.6281202
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001, D005, D007, D022, D024
Quantity Haz Kg:	3.6281202
Quantity Haz Tons:	0.004
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	CA-311

---

16 **IW WELL 07** **PFAS** **S132758133**
SSE **N/A**
1/8-1/4 **MARIPOSA, CA**
0.246 mi.
1300 ft.

Relative: **Lower**

Actual: **2073 ft.**

PFAS:

Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported

IW WELL 07 (Continued) **S132758133**

Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Perfluoroheptanesulfonic acid
Qualifier:	<
Value:	1.7
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported
Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Perfluorohexanoic acid
Qualifier:	=
Value:	1.7
Reporting Limit:	1.7

IW WELL 07 (Continued) **S132758133**

Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Nonafluoro-3,6-dioxaheptanoic acid (NFDHA)
Qualifier:	<
Value:	1.7
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported

IW WELL 07 (Continued) **S132758133**

Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Perfluorobutanesulfonic acid
Qualifier:	=
Value:	2.5
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	2.5
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

IW WELL 07 (Continued) **S132758133**

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Perfluorobutanoic acid
Qualifier:	<
Value:	1.7
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Qualifier:	<
Value:	1.7
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW

IW WELL 07 (Continued) **S132758133**

Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	4,8-Dioxa-3H-perfluorononanoic acid
Qualifier:	<
Value:	1.7
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001

IW WELL 07 (Continued) **S132758133**

Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Adsorbable Organic Fluorine (AOF)
Qualifier:	<
Value:	690
Reporting Limit:	690
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL: Not reported	
Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Perfluoro(2-ethoxyethane) sulfonic acid (PFEESA)

IW WELL 07 (Continued) **S132758133**

Qualifier:	<
Value:	1.7
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Name:	IW WELL 07
Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported

Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Perfluoro-3-methoxypropanoic acid (PFMPA)
Qualifier:	<
Value:	1.7
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Name:	IW WELL 07

IW WELL 07 (Continued) **S132758133**

Address:	Not reported
City,State,Zip:	MARIPOSA, CA
Envirostor ID:	Not reported
Program Type:	Not reported
Status:	Not reported
Status Date:	Not reported
Enviroscreen Score:	Not reported
Site Code:	Not reported
Global ID:	W0602210001
Facility Region:	Not reported
Lead Agency:	Not reported
Case worker:	Not reported
Local Agency:	Not reported
Location Case Number:	Not reported
File Location:	Not reported
Potential Contaminants of Concern:	Not reported
Potential Media Affected:	Not reported
Site History:	Not reported
Begin Date:	Not reported
RB Case Number:	Not reported
source_type:	All PFAS Chemicals
Location ID:	CA2210001_013_013
Matrix:	Liquid
Chemical:	Perfluoropentanoic acid
Qualifier:	=
Value:	2.3
Reporting Limit:	1.7
Detection Limit:	Not reported
Lab Notes:	Not reported
Quarterly Running Annual Average:	Not reported
Units:	NG/L
Date:	9/10/2024
Field Pt Class:	PUBW
Site Use:	Drinking Water Wells
Site Type:	DDW Well
Latitude:	37.496964
Longitude:	-119.982388
Geo Tracker URL:	Not reported

Click this hyperlink while viewing on your computer to access
6 additional CA PFAS: record(s) in the EDR Site Report.

17
East
1/4-1/2
0.332 mi.
1752 ft.

JOHN C. FREMONT HOSPITAL
5189 HOSPITAL ROAD
MARIPOSA, CA 95338

ENVIROSTOR **S118756632**
N/A

Relative:
Higher

Actual:
2211 ft.

ENVIROSTOR:

Name:	JOHN C. FREMONT HOSPITAL
Address:	5189 HOSPITAL ROAD
City,State,Zip:	MARIPOSA, CA 95338
Facility ID:	22800001
Status:	No Action Required
Status Date:	06/13/1994
Site Code:	100450
Site Type:	Calmortgage

JOHN C. FREMONT HOSPITAL (Continued) **S118756632**

Site Type Detailed:	Calmortgage
Acres:	0
NPL:	NO
Regulatory Agencies:	SMBRP
Lead Agency:	SMBRP
Program Manager:	Not reported
Supervisor:	Juan Peng
Division Branch:	Cleanup Sacramento
Assembly:	08
Senate:	04
Special Program:	Not reported
Restricted Use:	NO
Site Mgmt Req:	NONE SPECIFIED
Funding:	CalMortgage
Latitude:	37.50025
Longitude:	-119.9777
APN:	NONE SPECIFIED
Past Use:	NONE
Potential COC:	NONE SPECIFIED No Contaminants found
Confirmed COC:	No Contaminants found
Potential Description:	NMA
Alias Name:	100450
Alias Type:	Project Code (Site Code)
Alias Name:	22800001
Alias Type:	Envirostor ID Number

Completed Info:

Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Phase 1
Completed Date:	06/13/1994
Comments:	Pursuant to the MOU, DTSC has prepared a Phase I Environmental Assessment for the John C. Fremont Hospital, an acute care hospital located in the community of Mariposa. The hospital serves the entire county of Mariposa. A Phase I Report was prepared by DTSC and concluded that no action was needed for this property; there is no contamination on the property.
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Name:	Not reported
Schedule Document Type:	Not reported
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported

C18 **CHP-MARIPOSA** **UST FINDER RELEASE** **1028935394**
SE **5264 HWY 49 N** **N/A**
1/4-1/2 **MARIPOSA, CA 95338**
0.365 mi.
1927 ft. **Site 1 of 2 in cluster C**

Relative: **Lower**

Actual: **2096 ft.**

UST FINDER RELEASE:

Object ID:	54467
Facility ID:	Not reported
Lust ID:	CAT0604391798

CHP-MARIPOSA (Continued) **1028935394**

Name:	CHP-MARIPOSA
Address:	5264 HWY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Address Match Type:	PointAddress
Reported Date:	Not reported
Status:	No Further Action
Substance:	Not reported
Population within 1500ft:	259
Domestic Wells within 1500ft:	95
Land Use:	Developed, Low Intensity
Within SPA:	No
SPA PWS Facility ID:	Not reported
SPA Water Type:	Not reported
SPA Facility Type:	Not reported
SPA HUC12:	Not reported
Within WHPA:	Yes
WHPA PWS Facility ID:	CA2210001_14903
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well
WHPA HUC12:	180400011502
Within 100yr Floodplain:	No
Tribe:	Not reported
EPA Region:	9
NFA Letter 1:	Not reported
NFA Letter 2:	Not reported
NFA Letter 3:	Not reported
NFA Letter 4:	Not reported
Closed With Residual Contaminate:	Not reported
Coordinate Source:	Geocode
X Coord:	-119.98018
Y Coord:	37.4959000000001
Latitude:	37.4958999999999
Longitude:	-119.98018

C19 **CHP-MARIPOSA** **LUST** **S113804495**
SE **5264 HWY 49 N** **Cortese** **N/A**
1/4-1/2 **MARIPOSA, CA 95338** **CERS**
0.365 mi.
1927 ft. **Site 2 of 2 in cluster C**

Relative:
Lower

Actual:
2096 ft.

LUST:

Name:	CHP-MARIPOSA
Address:	5264 HWY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site

Geo Track:

Global Id:	T0604391798
Latitude:	37.4964140009465
Longitude:	-119.979844093323
Status:	Completed - Case Closed
Status Date:	01/06/2017
Case Worker:	CTF
RB Case Number:	Not reported
Local Agency:	MARIPOSA COUNTY
File Location:	Not reported
Local Case Number:	Not reported

CHP-MARIPOSA (Continued) **S113804495**

Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	MTBE / TBA / Other Fuel Oxygenates, Gasoline
EPA Region:	9
Coordinate Source:	Manual Entry on Screens
Cuf Case:	Not reported
Quantity Released Gallons:	Not reported
Begin Date:	Not reported
Leak Reported Date:	Not reported
How Discovered:	Not reported
How Discovered Description:	Not reported
Discharge Source:	Not reported
Discharge Cause:	Not reported
Stop Method:	Not reported
Stop Description:	Not reported
No Further Action Date:	Not reported
CA Water Watershed Name:	Not reported
Dwr Groundwater Subbasin Name:	Not reported
Disadvantaged Community:	Not reported
CA Enviroscreen 3 Score:	Not reported
CA Enviroscreen 4 Score:	Not reported
Military DOD Site:	Not reported
Facility Project Subtype:	Not reported
RWQCB Region:	Not reported
Site History:	The case was opened following an unauthorized release from an underground storage tank system at the subject site. Corrective action is underway as directed by the CVRWQCB. Corrective action may consist of preliminary site investigation, planning and implementation of remedial action, verification monitoring, or a combination thereof. A summary of the site history is available by clicking on either the

LUST:

Global Id:	T0604391798
Contact Type:	Regional Board Caseworker - Primary Caseworker
Contact Name:	CHRISTOPHER FLOWER
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 Sun Center Drive Suite 200
City:	RANCHO CORDOVA
Email:	chris.flower@waterboards.ca.gov
Phone Number:	9164644836

Global Id:	T0604391798
Contact Type:	Local Agency Caseworker
Contact Name:	KERRI GIBBONS
Organization Name:	MARIPOSA COUNTY
Address:	Not reported
City:	r5 UNKNOWN
Email:	Not reported
Phone Number:	Not reported

LUST:

Global Id:	T0604391798
Action Type:	RESPONSE
Date:	10/15/2006
Action:	Other Report / Document

Global Id:	T0604391798

CHP-MARIPOSA (Continued) **S113804495**

Action Type: RESPONSE
Date: 09/13/2013
Action: Sensitive Receptor Survey Report

Global Id: T0604391798
Action Type: RESPONSE
Date: 11/01/2011
Action: Monitoring Report - Quarterly

Global Id: T0604391798
Action Type: RESPONSE
Date: 11/01/2012
Action: Monitoring Report - Quarterly

Global Id: T0604391798
Action Type: RESPONSE
Date: 05/01/2012
Action: Monitoring Report - Quarterly

Global Id: T0604391798
Action Type: RESPONSE
Date: 08/01/2013
Action: Monitoring Report - Semi-Annually

Global Id: T0604391798
Action Type: RESPONSE
Date: 01/31/2015
Action: Monitoring Report - Other

Global Id: T0604391798
Action Type: RESPONSE
Date: 02/01/2013
Action: Monitoring Report - Quarterly

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 08/13/2014
Action: Staff Letter

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 08/05/2015
Action: Email Correspondence

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 10/15/2015
Action: Staff Letter

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 01/06/2017
Action: Closure/No Further Action Letter

Global Id: T0604391798
Action Type: Other
Date: 10/27/2004

CHP-MARIPOSA (Continued) **S113804495**

Action: Leak Reported

Global Id: T0604391798
Action Type: RESPONSE
Date: 04/21/2006
Action: Other Report / Document

Global Id: T0604391798
Action Type: RESPONSE
Date: 06/06/2006
Action: Soil and Water Investigation Report

Global Id: T0604391798
Action Type: RESPONSE
Date: 09/03/2015
Action: Request for Closure - Regulator Responded

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 03/08/2011
Action: Notice of Violation

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 03/22/2011
Action: Technical Correspondence / Assistance / Other

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 05/03/2012
Action: Staff Letter

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 07/09/2013
Action: File review

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 05/22/2013
Action: Staff Letter

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 07/30/2013
Action: Technical Correspondence / Assistance / Other

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 07/10/2013
Action: Staff Letter

Global Id: T0604391798
Action Type: RESPONSE
Date: 12/30/2005
Action: Soil and Water Investigation Workplan

CHP-MARIPOSA (Continued) **S113804495**

Global Id: T0604391798
Action Type: RESPONSE
Date: 08/01/2012
Action: Monitoring Report - Quarterly

Global Id: T0604391798
Action Type: RESPONSE
Date: 06/28/2013
Action: Soil and Water Investigation Workplan - Regulator Responded

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 09/14/2005
Action: Warning Letter

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 03/06/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 02/05/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 08/28/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 11/01/2006
Action: Technical Correspondence / Assistance / Other

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 07/16/2007
Action: Technical Correspondence / Assistance / Other

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 03/26/2009
Action: File review

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 07/31/2009
Action: Staff Letter

Global Id: T0604391798
Action Type: Other
Date: 04/26/2004
Action: Leak Discovery

Global Id: T0604391798
Action Type: RESPONSE

CHP-MARIPOSA (Continued) **S113804495**

Date: 02/28/2005
Action: Soil and Water Investigation Workplan

Global Id: T0604391798
Action Type: RESPONSE
Date: 02/28/2005
Action: Other Report / Document

Global Id: T0604391798
Action Type: RESPONSE
Date: 04/28/2007
Action: Soil and Water Investigation Report

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 03/11/2005
Action: * Verbal Communication

Global Id: T0604391798
Action Type: ENFORCEMENT
Date: 12/28/2004
Action: Staff Letter

LUST:
Global Id: T0604391798
Status: Open - Case Begin Date
Status Date: 04/26/2004

Global Id: T0604391798
Status: Open - Site Assessment
Status Date: 10/27/2004

Global Id: T0604391798
Status: Open - Site Assessment
Status Date: 06/07/2006

Global Id: T0604391798
Status: Open - Remediation
Status Date: 07/01/2014

Global Id: T0604391798
Status: Open - Eligible for Closure
Status Date: 06/06/2016

Global Id: T0604391798
Status: Completed - Case Closed
Status Date: 01/06/2017

CORTESE:
Name: CHP-MARIPOSA
Address: 5264 HWY 49 N
City,State,Zip: MARIPOSA, CA 95338
Region: CORTESE
Envirostor Id: Not reported
Global ID: T0604391798

CHP-MARIPOSA (Continued) **S113804495**

Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not reported
Site Code:	Not reported
Latitude:	Not reported
Longitude:	Not reported
Owner:	Not reported
Enf Type:	Not reported
Swat R:	Not reported
Flag:	active
Order No:	Not reported
Waste Discharge System No:	Not reported
Effective Date:	Not reported
Region 2:	Not reported
WID Id:	Not reported
Solid Waste Id No:	Not reported
Waste Management Uit Name:	Not reported
File Name:	Active Open

CERS:

Name:	CHP-MARIPOSA
Address:	5264 HWY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Site ID:	851341
CERS ID:	T0604391798
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	KERRI GIBBONS - MARIPOSA COUNTY
Entity Title:	Not reported
Affiliation Address:	Not reported
Affiliation City:	r5 UNKNOWN
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	,

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	CHRISTOPHER FLOWER - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not reported
Affiliation Address:	11020 Sun Center Drive Suite 200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not reported
Affiliation Zip:	Not reported
Affiliation Phone:	9164644836,

20
SE
1/4-1/2
0.465 mi.
2454 ft.

CHP-MARIPOSA
5246 HWY 49 N
MARIPOSA, CA 95338

LUST

S106716636
N/A

Relative:
Lower

Actual:
2099 ft.

LUST REG 5:

Name:	CHP-MARIPOSA
Address:	5246 HWY 49 N
City:	MARIPOSA
Region:	5
Status:	Preliminary site assessment underway
Case Number:	5T22000135
Case Type:	Drinking Water Aquifer affected
Substance:	GASOLINE
Staff Initials:	WWG
Lead Agency:	Regional
Program:	LUST
MTBE Code:	N/A

Count: 1 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
MARIPOSA	S100181611	JUNK YARD - VIC HALL	OFF OF SCHAEFER ROAD, E OF HIG	95338	ENVIROSTOR

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: N/A
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: N/A
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: N/A
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 12/10/2025
Date Data Arrived at EDR: 12/10/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 64

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 12/10/2025
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 12/03/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/03/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/03/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/03/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/03/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 03/11/2025
Date Data Arrived at EDR: 04/02/2025
Date Made Active in Reports: 06/24/2025
Number of Days to Update: 83

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 11/11/2025
Date Made Active in Reports: 11/12/2025
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/17/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/30/2025
Date Data Arrived at EDR: 11/11/2025
Date Made Active in Reports: 11/12/2025
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/17/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/01/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 66

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 12/08/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

Lists of state- and tribal (Superfund) equivalent sites

RESPONSE: State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 10/20/2025
Date Data Arrived at EDR: 10/20/2025
Date Made Active in Reports: 01/08/2026
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/16/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 10/20/2025
Date Data Arrived at EDR: 10/20/2025
Date Made Active in Reports: 01/08/2026
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/16/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Quarterly

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inve ntory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 11/03/2025
Date Data Arrived at EDR: 11/03/2025
Date Made Active in Reports: 01/27/2026
Number of Days to Update: 85

Source: Department of Resources Recycling and Recovery
Telephone: 916-341-6320
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

LUST REG 5: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El Dorado, Fresno, Glenn, Kern, Kings, Lake, Lassen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Sacramento, San Joaquin, Shasta, Solano, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.

Date of Government Version: 07/01/2008
Date Data Arrived at EDR: 07/22/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 9

Source: California Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-4834
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

LUST REG 7: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004
Date Data Arrived at EDR: 02/26/2004
Date Made Active in Reports: 03/24/2004
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Telephone: 760-776-8943
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 8: Leaking Underground Storage Tanks
California Regional Water Quality Control Board Santa Ana Region (8). For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/14/2005
Date Data Arrived at EDR: 02/15/2005
Date Made Active in Reports: 03/28/2005
Number of Days to Update: 41

Source: California Regional Water Quality Control Board Santa Ana Region (8)
Telephone: 909-782-4496
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

LUST REG 4: Underground Storage Tank Leak List
Los Angeles, Ventura counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35

Source: California Regional Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6710
Last EDR Contact: 09/06/2011
Next Scheduled EDR Contact: 12/19/2011
Data Release Frequency: No Update Planned

LUST REG 3: Leaking Underground Storage Tank Database
Leaking Underground Storage Tank locations. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties.

Date of Government Version: 05/19/2003
Date Data Arrived at EDR: 05/19/2003
Date Made Active in Reports: 06/02/2003
Number of Days to Update: 14

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-542-4786
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

LUST REG 2: Fuel Leak List
Leaking Underground Storage Tank locations. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Clara, Solano, Sonoma counties.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: California Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-622-2433
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

LUST REG 6L: Leaking Underground Storage Tank Case Listing
For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 09/09/2003
Date Data Arrived at EDR: 09/10/2003
Date Made Active in Reports: 10/07/2003
Number of Days to Update: 27

Source: California Regional Water Quality Control Board Lahontan Region (6)
Telephone: 530-542-5572
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST REG 1: Active Toxic Site Investigation
Del Norte, Humboldt, Lake, Mendocino, Modoc, Siskiyou, Sonoma, Trinity counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1)
Telephone: 707-570-3769
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

LUST REG 6V: Leaking Underground Storage Tank Case Listing
Leaking Underground Storage Tank locations. Inyo, Kern, Los Angeles, Mono, San Bernardino counties.

Date of Government Version: 06/07/2005
Date Data Arrived at EDR: 06/07/2005
Date Made Active in Reports: 06/29/2005
Number of Days to Update: 22

Source: California Regional Water Quality Control Board Victorville Branch Office (6)
Telephone: 760-241-7365
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

LUST: Leaking Underground Fuel Tank Report (GEOTRACKER)
Leaking Underground Storage Tank (LUST) Sites included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: see region list
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

LUST REG 9: Leaking Underground Storage Tank Report
Orange, Riverside, San Diego counties. For more current information, please refer to the State Water Resources Control Board's LUST database.

Date of Government Version: 03/01/2001
Date Data Arrived at EDR: 04/23/2001
Date Made Active in Reports: 05/21/2001
Number of Days to Update: 28

Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-637-5595
Last EDR Contact: 09/26/2011
Next Scheduled EDR Contact: 01/09/2012
Data Release Frequency: No Update Planned

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/12/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 69

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 11/21/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

CPS-SLIC: Statewide SLIC Cases (GEOTRACKER)

Cleanup Program Sites (CPS; also known as Site Cleanups [SC] and formerly known as Spills, Leaks, Investigations, and Cleanups [SLIC] sites) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 80

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

SLIC REG 1: Active Toxic Site Investigations

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1)
Telephone: 707-576-2220
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/30/2004
Date Data Arrived at EDR: 10/20/2004
Date Made Active in Reports: 11/19/2004
Number of Days to Update: 30

Source: Regional Water Quality Control Board San Francisco Bay Region (2)
Telephone: 510-286-0457
Last EDR Contact: 09/19/2011
Next Scheduled EDR Contact: 01/02/2012
Data Release Frequency: No Update Planned

SLIC REG 3: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/18/2006
Date Data Arrived at EDR: 05/18/2006
Date Made Active in Reports: 06/15/2006
Number of Days to Update: 28

Source: California Regional Water Quality Control Board Central Coast Region (3)
Telephone: 805-549-3147
Last EDR Contact: 07/18/2011
Next Scheduled EDR Contact: 10/31/2011
Data Release Frequency: No Update Planned

SLIC REG 4: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/17/2004
Date Data Arrived at EDR: 11/18/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 47

Source: Region Water Quality Control Board Los Angeles Region (4)
Telephone: 213-576-6600
Last EDR Contact: 07/01/2011
Next Scheduled EDR Contact: 10/17/2011
Data Release Frequency: No Update Planned

SLIC REG 5: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/01/2005
Date Data Arrived at EDR: 04/05/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 16

Source: Regional Water Quality Control Board Central Valley Region (5)
Telephone: 916-464-3291
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 6V: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 05/24/2005
Date Data Arrived at EDR: 05/25/2005
Date Made Active in Reports: 06/16/2005
Number of Days to Update: 22
Source: Regional Water Quality Control Board, Victorville Branch
Telephone: 619-241-6583
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 6L: SLIC Sites
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/07/2004
Date Data Arrived at EDR: 09/07/2004
Date Made Active in Reports: 10/12/2004
Number of Days to Update: 35
Source: California Regional Water Quality Control Board, Lahontan Region
Telephone: 530-542-5574
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SLIC REG 7: SLIC List
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004
Date Data Arrived at EDR: 11/29/2004
Date Made Active in Reports: 01/04/2005
Number of Days to Update: 36
Source: California Regional Quality Control Board, Colorado River Basin Region
Telephone: 760-346-7491
Last EDR Contact: 08/01/2011
Next Scheduled EDR Contact: 11/14/2011
Data Release Frequency: No Update Planned

SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2008
Date Data Arrived at EDR: 04/03/2008
Date Made Active in Reports: 04/14/2008
Number of Days to Update: 11
Source: California Region Water Quality Control Board Santa Ana Region (8)
Telephone: 951-782-3298
Last EDR Contact: 09/12/2011
Next Scheduled EDR Contact: 12/26/2011
Data Release Frequency: No Update Planned

SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing
The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 09/10/2007
Date Data Arrived at EDR: 09/11/2007
Date Made Active in Reports: 09/28/2007
Number of Days to Update: 17
Source: California Regional Water Quality Control Board San Diego Region (9)
Telephone: 858-467-2980
Last EDR Contact: 08/08/2011
Next Scheduled EDR Contact: 11/21/2011
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 06/06/2025
Date Data Arrived at EDR: 08/26/2025
Date Made Active in Reports: 11/12/2025
Number of Days to Update: 78
Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 12/23/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

MILITARY UST SITES: Military UST Sites (GEOTRACKER)
Military ust sites

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

UST: Active UST Facilities
Active UST facilities gathered from the local regulatory agencies

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/13/2026
Number of Days to Update: 80

Source: SWRCB
Telephone: 916-341-5851
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Semi-Annually

UST CLOSURE: Proposed Closure of Underground Storage Tank (UST) Cases
UST cases that are being considered for closure by either the State Water Resources Control Board or the Executive Director have been posted for a 60-day public comment period. UST Case Closures being proposed for consideration by the State Water Resources Control Board. These are primarily UST cases that meet closure criteria under the decisional framework in State Water Board Resolution No. 92-49 and other Board orders. UST Case Closures proposed for consideration by the Executive Director pursuant to State Water Board Resolution No. 2012-0061. These are cases that meet the criteria of the Low-Threat UST Case Closure Policy. UST Case Closure Review Denials and Approved Orders.

Date of Government Version: 11/20/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/13/2026
Number of Days to Update: 80

Source: State Water Resources Control Board
Telephone: 916-327-7844
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

AST: Aboveground Petroleum Storage Tank Facilities
A listing of aboveground storage tank petroleum storage tank locations.

Date of Government Version: 07/06/2016
Date Data Arrived at EDR: 07/12/2016
Date Made Active in Reports: 09/19/2016
Number of Days to Update: 69

Source: California Environmental Protection Agency
Telephone: 916-327-5092
Last EDR Contact: 03/04/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 11/21/2025
Date Data Arrived at EDR: 12/11/2025
Date Made Active in Reports: 02/19/2026
Number of Days to Update: 70

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

Lists of state and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 12/03/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Properties
Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 10/20/2025
Date Data Arrived at EDR: 10/20/2025
Date Made Active in Reports: 01/08/2026
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/16/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Quarterly

Lists of state and tribal brownfield sites

BROWNFIELDS: Considered Brownfieds Sites Listing
A listing of sites the SWRCB considers to be Brownfields since these are sites have come to them through the MOA Process.

Date of Government Version: 12/08/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 80

Source: State Water Resources Control Board
Telephone: 916-323-7905
Last EDR Contact: 12/08/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites
Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/02/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/10/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

WMUDS/SWAT: Waste Management Unit Database

Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Date of Government Version: 04/01/2000
Date Data Arrived at EDR: 04/10/2000
Date Made Active in Reports: 05/10/2000
Number of Days to Update: 30

Source: State Water Resources Control Board
Telephone: 916-227-4448
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

SWRCY: Recycler Database

A listing of recycling facilities in California.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/13/2026
Number of Days to Update: 80

Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

HAULERS: Registered Waste Tire Haulers Listing

A listing of registered waste tire haulers.

Date of Government Version: 11/13/2025
Date Data Arrived at EDR: 11/17/2025
Date Made Active in Reports: 11/19/2025
Number of Days to Update: 2

Source: Integrated Waste Management Board
Telephone: 916-341-6422
Last EDR Contact: 02/05/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/22/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024
Date Data Arrived at EDR: 11/13/2024
Date Made Active in Reports: 11/19/2024
Number of Days to Update: 6

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/20/2025
Next Scheduled EDR Contact: 03/02/2026
Data Release Frequency: No Update Planned

HIST CAL-SITES: Calsites Database

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005
Date Data Arrived at EDR: 08/03/2006
Date Made Active in Reports: 08/24/2006
Number of Days to Update: 21

Source: Department of Toxic Substance Control
Telephone: 916-323-3400
Last EDR Contact: 02/23/2009
Next Scheduled EDR Contact: 05/25/2009
Data Release Frequency: No Update Planned

SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 10/20/2025
Date Data Arrived at EDR: 10/20/2025
Date Made Active in Reports: 01/08/2026
Number of Days to Update: 80

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/16/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2022
Date Data Arrived at EDR: 03/21/2024
Date Made Active in Reports: 06/12/2024
Number of Days to Update: 83

Source: Department of Toxic Substances Control
Telephone: 916-255-6504
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

CERS HAZ WASTE: California Environmental Reporting System Hazardous Waste

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, and RCRA LQ HW Generator programs.

Date of Government Version: 10/13/2025
Date Data Arrived at EDR: 10/13/2025
Date Made Active in Reports: 12/18/2025
Number of Days to Update: 66

Source: CalEPA
Telephone: 916-323-2514
Last EDR Contact: 01/13/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Quarterly

TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995
Date Data Arrived at EDR: 08/30/1995
Date Made Active in Reports: 09/26/1995
Number of Days to Update: 27

Source: State Water Resources Control Board
Telephone: 916-227-4364
Last EDR Contact: 01/26/2009
Next Scheduled EDR Contact: 04/27/2009
Data Release Frequency: No Update Planned

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/04/2025
Date Data Arrived at EDR: 06/02/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 71

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/19/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994
Date Data Arrived at EDR: 07/07/2005
Date Made Active in Reports: 08/11/2005
Number of Days to Update: 35

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/03/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HIST UST: Hazardous Substance Storage Container Database

The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.

Date of Government Version: 10/15/1990
Date Data Arrived at EDR: 01/25/1991
Date Made Active in Reports: 02/12/1991
Number of Days to Update: 18

Source: State Water Resources Control Board
Telephone: 916-341-5851
Last EDR Contact: 07/26/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SAN FRANCISCO AST: Aboveground Storage Tank Site Listing

Aboveground storage tank sites

Date of Government Version: 01/27/2026
Date Data Arrived at EDR: 01/27/2026
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 30

Source: San Francisco County Department of Public Health
Telephone: 415-252-3896
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

CERS TANKS: California Environmental Reporting System (CERS) Tanks

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs.

Date of Government Version: 10/13/2025
Date Data Arrived at EDR: 10/13/2025
Date Made Active in Reports: 12/17/2025
Number of Days to Update: 65

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 01/13/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Quarterly

CA FID UST: Facility Inventory Database

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994
Date Data Arrived at EDR: 09/05/1995
Date Made Active in Reports: 09/29/1995
Number of Days to Update: 24

Source: California Environmental Protection Agency
Telephone: 916-341-5851
Last EDR Contact: 12/28/1998
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Environmental Liens Listing

A listing of property locations with environmental liens for California where DTSC is a lien holder.

Date of Government Version: 11/20/2025
Date Data Arrived at EDR: 11/20/2025
Date Made Active in Reports: 02/09/2026
Number of Days to Update: 81

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 03/04/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Semi-Annually

DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 11/19/2025
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 02/04/2026
Number of Days to Update: 77

Source: DTSC and SWRCB
Telephone: 916-323-3400
Last EDR Contact: 02/24/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/07/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 66
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 12/08/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

CHMIRS: California Hazardous Material Incident Report System
California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 01/08/2026
Date Made Active in Reports: 01/09/2026
Number of Days to Update: 1
Source: Office of Emergency Services
Telephone: 916-845-8400
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Semi-Annually

LDS: Land Disposal Sites Listing (GEOTRACKER)
Land Disposal sites (Landfills) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/10/2026
Number of Days to Update: 78
Source: State Water Qualilty Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

MCS: Military Cleanup Sites Listing (GEOTRACKER)
Military sites (consisting of: Military UST sites; Military Privatized sites; and Military Cleanup sites [formerly known as DoD non UST]) included in GeoTracker. GeoTracker is the Water Boards data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 80
Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

SPILLS 90: SPILLS90 data from FirstSearch
Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 06/06/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/22/2013
Number of Days to Update: 50
Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated
RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/03/2025
Date Made Active in Reports: 12/10/2025
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: (415) 495-8895
Last EDR Contact: 12/03/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 10/22/2025
Date Data Arrived at EDR: 11/06/2025
Date Made Active in Reports: 01/12/2026
Number of Days to Update: 67

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/10/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 12/23/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 01/29/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 12/07/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/05/2026
Number of Days to Update: 59

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 12/08/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88
Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73
Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283
Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 03/23/2026
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 11/10/2025
Date Made Active in Reports: 01/29/2026
Number of Days to Update: 80
Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/12/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 01/12/2026
Date Data Arrived at EDR: 01/13/2026
Date Made Active in Reports: 03/05/2026
Number of Days to Update: 51
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 01/13/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 01/30/2026
Date Data Arrived at EDR: 02/02/2026
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 10

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 01/01/2026
Date Data Arrived at EDR: 01/14/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 06/26/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 28

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 08/12/2025
Date Data Arrived at EDR: 09/30/2025
Date Made Active in Reports: 11/24/2025
Number of Days to Update: 55

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 12/23/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 01/26/2026
Date Data Arrived at EDR: 01/27/2026
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 29

Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 01/29/2026
Number of Days to Update: 71

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 02/20/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 02/20/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 01/29/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 12/09/2025
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 12/31/2025
Date Data Arrived at EDR: 01/20/2026
Date Made Active in Reports: 03/05/2026
Number of Days to Update: 44
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/20/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2025
Date Data Arrived at EDR: 12/12/2025
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 75

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/15/2026
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 12/08/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 12/17/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 05/15/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 75

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/12/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 12/26/2025
Date Data Arrived at EDR: 01/05/2026
Date Made Active in Reports: 01/22/2026
Number of Days to Update: 17

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 03/02/2026
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/08/2025
Date Data Arrived at EDR: 08/18/2025
Date Made Active in Reports: 11/12/2025
Number of Days to Update: 86

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/13/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 01/01/2026
Date Data Arrived at EDR: 01/06/2026
Date Made Active in Reports: 01/07/2026
Number of Days to Update: 1

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 84

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 02/19/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 12/04/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 69

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/11/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 11/07/2025
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 02/05/2026
Number of Days to Update: 78

Source: EPA
Telephone: (415) 947-8000
Last EDR Contact: 02/20/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 12/13/2025
Date Data Arrived at EDR: 12/17/2025
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 12/17/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 07/31/2025
Date Data Arrived at EDR: 08/14/2025
Date Made Active in Reports: 11/04/2025
Number of Days to Update: 82

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/05/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 11/06/2025
Date Data Arrived at EDR: 11/06/2025
Date Made Active in Reports: 01/12/2026
Number of Days to Update: 67

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/10/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 11/12/2024
Date Data Arrived at EDR: 07/21/2025
Date Made Active in Reports: 10/13/2025
Number of Days to Update: 84

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 01/07/2026
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/19/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/19/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 08/21/2025
Date Data Arrived at EDR: 12/04/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 70

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 03/05/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 03/05/2026
Number of Days to Update: 77

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 12/18/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: No Update Planned

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data

The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 01/10/2026
Date Data Arrived at EDR: 01/15/2026
Date Made Active in Reports: 03/05/2026
Number of Days to Update: 49

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 01/15/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

UST FINDER: UST Finder Database

EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories . UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 02/05/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database

US EPA’s UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA’s Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protecton Agency
Telephone: 202-564-0394
Last EDR Contact: 03/05/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Semi-Annually

E MANIFEST: Hazardous Waste Electronic Manifest System

EPA established a national system for tracking hazardous waste shipments electronically. This system, known as ?e-Manifest,? will modernize the nation?s cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 11/30/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 12/19/2025
Number of Days to Update: 14

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 12/05/2025
Next Scheduled EDR Contact: 04/30/2026
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

A listing of PFAS sites included in the Envirostor and GeoTracker databases. Locations of potential sources of per - and polyfluoroalkyl substances (PFAS). This does not mean that PFAS has been produced, used, or discharged at these sites.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/13/2026
Number of Days to Update: 80

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

AQUEOUS FOAM: Former Fire Training Facility Assessments Listing

Airports shown on this list are those believed to use Aqueous Film Forming Foam (AFFF), and certified by the Federal Aviation Administration (FAA) under Title 14, Code of Federal Regulations (CFR), Part 139 (14 CFR Part 139). This list was created by SWRCB using information available from the FAA. Location points shown are from the latitude and longitude listed on the FAA airport master record.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/17/2026
Number of Days to Update: 84

Source: State Water Resources Control Board
Telephone: 916-341-5455
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989
Date Data Arrived at EDR: 07/27/1994
Date Made Active in Reports: 08/02/1994
Number of Days to Update: 6

Source: Department of Health Services
Telephone: 916-255-2118
Last EDR Contact: 05/31/1994
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

CHROME PLATING: Chrome Plating Facilities Listing

This listing represents chrome plating facilities the California State Water Resources Control Board staff identified as possibly being a source of Per- and polyfluoroalkyl substance (PFAS) contamination. Sites and locations were identified by staff with the Division of Water Quality in the California State Water Board. Data was collected from the CA Air Resources Board 2013 and 2018 - Cr VI emission survey, CA Emission Inventory, CA HAZ Waste discharge database and by reviewing storm water permits. Former chrome plating sites are also included that are open site investigation or remediation cases with the Regional Water Quality Control Boards and the Department of Toxic Substances Control.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/17/2026
Number of Days to Update: 84

Source: State Water Resources Control Board
Telephone: 916-341-5455
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

CORTESE: "Cortese" Hazardous Waste & Substances Sites List
The sites for the list are designated by the State Water Resource Control Board (LUST), the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites).

Date of Government Version: 12/08/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 79

Source: CAL EPA/Office of Emergency Information
Telephone: 916-323-3400
Last EDR Contact: 12/08/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Quarterly

CUPA LIV-PLE: CUPA Facility Listing
list of facilities associated with the various CUPA programs in Livermore-Pleasanton

Date of Government Version: 09/19/2024
Date Data Arrived at EDR: 11/05/2024
Date Made Active in Reports: 01/31/2025
Number of Days to Update: 87

Source: Livermore-Pleasanton Fire Department
Telephone: 925-454-2361
Last EDR Contact: 02/05/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

DRYCLEAN MENDOCINO: Mendocino County Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Mendocino County Air Quality Management District.

Date of Government Version: 08/26/2024
Date Data Arrived at EDR: 09/03/2024
Date Made Active in Reports: 11/13/2024
Number of Days to Update: 71

Source: Mendocino County Air Quality Management District
Telephone: 707-463-4354
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN SACRAMENTO: Sacramento Metropolitan Air Quality Management DistrictDrycleaner Facility Listing
A listing of drycleaner facility locations, for the Sacramento Metropolitan Air Quality Management District.

Date of Government Version: 09/03/2024
Date Data Arrived at EDR: 09/05/2024
Date Made Active in Reports: 11/13/2024
Number of Days to Update: 69

Source: Sacramento Metropolitan Air Quality Management District
Telephone: 916-874-3958
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN IMPERIAL: Imperial County Air Pollution Control District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Imperial County Air Pollution Control District

Date of Government Version: 10/02/2024
Date Data Arrived at EDR: 10/03/2024
Date Made Active in Reports: 12/20/2024
Number of Days to Update: 78

Source: Imperial County Air Pollution Control District
Telephone: 442-265-1800
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN PLACER: Placer County Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Placer County Air Quality Management District.

Date of Government Version: 05/15/2023
Date Data Arrived at EDR: 05/17/2023
Date Made Active in Reports: 08/14/2023
Number of Days to Update: 89

Source: Placer County Air Quality Management District
Telephone: 530-745-2335
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN LAKE: Lake County Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Lake County Air Quality Management District,

Date of Government Version: 02/15/2024
Date Data Arrived at EDR: 02/16/2024
Date Made Active in Reports: 05/02/2024
Number of Days to Update: 76
Source: Lake County Air Quality Management District
Telephone: 707-263-7000
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEANERS: Cleaner Facilities
A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 11/20/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/17/2026
Number of Days to Update: 84
Source: Department of Toxic Substance Control
Telephone: 916-327-4498
Last EDR Contact: 02/18/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Annually

DRYCLEAN AVAQMD: Antelope Valley Air Quality Management District Drycleaner Listing
A listing of dry cleaners in the Antelope Valley Air Quality Management District.

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/17/2026
Number of Days to Update: 84
Source: Antelope Valley Air Quality Management District
Telephone: 661-723-8070
Last EDR Contact: 02/18/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Varies

DRYCLEAN SAN JOAQUIN: San Joaquin Valley Air Pollution Control District District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the San Joaquin Valley Air Pollution Control District.

Date of Government Version: 05/05/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 07/28/2025
Number of Days to Update: 82
Source: San Joaquin Valley Air Pollution Control District
Telephone: 559-230-6001
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN GRANT: Grant Recipients List
Assembly Bill 998 (AB 998) established the Non-Toxic Dry Cleaning Incentive Program to provide financial assistance to the dry cleaning industry to switch from systems using perchloroethylene (Perc), an identified toxic air contaminant and potential human carcinogen, to non-toxic and non-smog forming alternatives.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 01/26/2024
Date Made Active in Reports: 04/16/2024
Number of Days to Update: 81
Source: California Air Resources Board
Telephone: 916-323-0006
Last EDR Contact: 01/22/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

DRYCLEAN SAN DIEGO: San Diego County Air Pollution Control District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the San Diego County Air Pollution Control District.

Date of Government Version: 05/02/2025
Date Data Arrived at EDR: 05/08/2025
Date Made Active in Reports: 07/28/2025
Number of Days to Update: 81
Source: San Diego County Air Pollution Control District
Telephone: 858-586-2616
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN BAY AREA: Bay Area Air Quality Management District Drycleaner Facility Listing
Bay Area Air Quality Management District Drycleaner Facility Listing.

Date of Government Version: 06/05/2025
Date Data Arrived at EDR: 06/11/2025
Date Made Active in Reports: 08/20/2025
Number of Days to Update: 70
Source: Bay Area Air Quality Management District
Telephone: 415-516-1916
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN SOUTH COAST: South Coast Air Quality Management District Drycleaner Listing
A listing of dry cleaners in the South Coast Air Quality Management District

Date of Government Version: 11/12/2025
Date Data Arrived at EDR: 11/14/2025
Date Made Active in Reports: 02/03/2026
Number of Days to Update: 81
Source: South Coast Air Quality Management District
Telephone: 909-396-3211
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

DRYCLEAN N SONOMA: Norther Sonoma County County Air Pollution Control District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Northern Sonoma County Air Pollution Control District.,

Date of Government Version: 08/23/2024
Date Data Arrived at EDR: 08/26/2024
Date Made Active in Reports: 11/05/2024
Number of Days to Update: 71
Source: Santa Barbara County Air Pollution Control District
Telephone: 707-433-5911
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN SHASTA: Shasta County Air Quality Management District District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Shasta County Air Quality Management District.

Date of Government Version: 08/29/2024
Date Data Arrived at EDR: 09/05/2024
Date Made Active in Reports: 11/13/2024
Number of Days to Update: 69
Source: Shasta County Air Quality Management District
Telephone: 530-225-5674
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN TEHAMA: Tehama County Air Pollution Control District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Tehama County Air Pollution Control District.

Date of Government Version: 04/24/2019
Date Data Arrived at EDR: 04/24/2019
Date Made Active in Reports: 05/01/2023
Number of Days to Update: 1468
Source: Tehama County Air Pollution Control District
Telephone: 530-527-3717
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN FEATHER RVR: Feather River Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Feather River Air Quality Management District.

Date of Government Version: 03/08/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 06/05/2023
Number of Days to Update: 88
Source: Feather River Air Quality Management District
Telephone: 530-634-7659
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN N COAST: North Coast Unified Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the North Coast Unified Air Quality Management District.

Date of Government Version: 11/30/2016
Date Data Arrived at EDR: 04/19/2019
Date Made Active in Reports: 05/01/2023
Number of Days to Update: 1473
Source: North Coast Unified Air Quality Management District
Telephone: 707-443-3093
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN SANTA BARB: Santa Barbara County Air Pollution Control District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Santa Barbara County Air Pollution Control District.

Date of Government Version: 02/19/2019
Date Data Arrived at EDR: 04/17/2019
Date Made Active in Reports: 05/01/2023
Number of Days to Update: 1475
Source: Santa Barbara County Air Pollution Control District
Telephone: 805-961-8867
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN GLENN: Glenn County Air Pollution Control District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Glenn County Air Pollution Control District.

Date of Government Version: 08/26/2024
Date Data Arrived at EDR: 08/28/2024
Date Made Active in Reports: 11/13/2024
Number of Days to Update: 77
Source: Glenn County Air Pollution Control District
Telephone: 530-934-6500
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN YOLO-SOLANO: Yolo-Solano Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Yolo-Solano Air Quality Management District.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 05/15/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 75
Source: Yolo-Solano Air Quality Management District
Telephone: 530-757-3650
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN VENTURA: Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Ventura County Air Pollution Control District.

Date of Government Version: 05/05/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 83
Source: Ventura County Air Pollution Control District
Telephone: 805-645-1421
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN SAN LUIS OB: San Luis Obispo County Air Pollution Control District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the San Luis Obispo County Air Pollution Control District.

Date of Government Version: 05/02/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 83
Source: San Luis Obispo County Air Pollution Control District
Telephone: 805-781-5756
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN MONTERY BAY: Monterey Bay Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Monterey Bay Air Quality Management District.

Date of Government Version: 04/15/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 83
Source: Monterey Bay Air Quality Management District
Telephone: 831-647-9411
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN BUTTE: Butte County Air Quality Management DistrictDrycleaner Facility Listing
Butte County Air Quality Management DistrictDrycleaner Facility Listing.

Date of Government Version: 04/03/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 83
Source: Butte County Air Quality Management District
Telephone: 530-332-9400
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN EAST KERN: Eastern Kern Air Pollution Control District District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Eastern Kern Air Pollution Control District.

Date of Government Version: 08/21/2024
Date Data Arrived at EDR: 08/22/2024
Date Made Active in Reports: 11/05/2024
Number of Days to Update: 75

Source: Eastern Kern Air Pollution Control District
Telephone: 661-862-9684
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN MOJAVE: Mojave Desert Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Mojave Desert Air Quality Management District.

Date of Government Version: 05/02/2025
Date Data Arrived at EDR: 05/02/2025
Date Made Active in Reports: 07/18/2025
Number of Days to Update: 77

Source: Mojave Desert Air Quality Management District
Telephone: 760-245-1661
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN AMADOR: Amador Air District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Amador Air Quality Management District

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 04/27/2023
Date Made Active in Reports: 07/13/2023
Number of Days to Update: 77

Source: Amador Air Quality Management District
Telephone: 209-257-0112
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN N SIERRA: Northern Sierra Air Quality Management District Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Northern Sierra Air Quality Management District,

Date of Government Version: 08/22/2024
Date Data Arrived at EDR: 08/22/2024
Date Made Active in Reports: 11/05/2024
Number of Days to Update: 75

Source: Northern Sierra Air Quality Management District
Telephone: 530-274-9350
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

DRYCLEAN CALAVERAS: Calaveras County Environmental Management Agency Drycleaner Facility Listing
A listing of drycleaner facility locations, for the Calaveras County Environmental Management Agency.

Date of Government Version: 06/17/2019
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 05/01/2023
Number of Days to Update: 1412

Source: Calaveras County Environmental Management Agency
Telephone: 209-754-6399
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 09/16/2019
Data Release Frequency: Varies

EMI: Emissions Inventory Data
Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 03/11/2025
Date Made Active in Reports: 05/23/2025
Number of Days to Update: 73

Source: California Air Resources Board
Telephone: 916-322-2990
Last EDR Contact: 12/11/2025
Next Scheduled EDR Contact: 03/23/2026
Data Release Frequency: Varies

ENF: Enforcement Action Listing
A listing of Water Board Enforcement Actions. Formal is everything except Oral/Verbal Communication, Notice of Violation, Expedited Payment Letter, and Staff Enforcement Letter.

Date of Government Version: 10/13/2025
Date Data Arrived at EDR: 10/14/2025
Date Made Active in Reports: 01/07/2026
Number of Days to Update: 85

Source: State Water Resoruces Control Board
Telephone: 916-445-9379
Last EDR Contact: 01/13/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

FIN ASSURANCE 1: Financial Assurance Information Listing
Financial Assurance information

Date of Government Version: 10/07/2025
Date Data Arrived at EDR: 10/08/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-255-3628
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

FIN ASSURANCE 2: Financial Assurance Information Listing
A listing of financial assurance information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 11/07/2025
Date Data Arrived at EDR: 11/13/2025
Date Made Active in Reports: 02/03/2026
Number of Days to Update: 82

Source: California Integrated Waste Management Board
Telephone: 916-341-6066
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Varies

ICE: Inspection, Compliance and Enforcement
Contains data pertaining to the Permitted Facilities with Inspections / Enforcements sites tracked in Envirostor.

Date of Government Version: 11/06/2025
Date Data Arrived at EDR: 11/06/2025
Date Made Active in Reports: 01/27/2026
Number of Days to Update: 82

Source: Department of Toxic Subsances Control
Telephone: 877-786-9427
Last EDR Contact: 02/10/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Quarterly

HIST CORTESE: Hazardous Waste & Substance Site List
The sites for the list are designated by the State Water Resource Control Board [LUST], the Integrated Waste Board [SWF/LS], and the Department of Toxic Substances Control [CALSITES]. This listing is no longer updated by the state agency.

Date of Government Version: 04/01/2001
Date Data Arrived at EDR: 01/22/2009
Date Made Active in Reports: 04/08/2009
Number of Days to Update: 76

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 01/22/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

HWP: EnviroStor Permitted Facilities Listing
Detailed information on permitted hazardous waste facilities and corrective action ("cleanups") tracked in EnviroStor.

Date of Government Version: 11/06/2025
Date Data Arrived at EDR: 11/06/2025
Date Made Active in Reports: 01/27/2026
Number of Days to Update: 82

Source: Department of Toxic Substances Control
Telephone: 916-323-3400
Last EDR Contact: 02/10/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Quarterly

HWT: Registered Hazardous Waste Transporter Database
A listing of hazardous waste transporters. In California, unless specifically exempted, it is unlawful for any person to transport hazardous wastes unless the person holds a valid registration issued by DTSC. A hazardous waste transporter registration is valid for one year and is assigned a unique registration number.

Date of Government Version: 12/16/2025
Date Data Arrived at EDR: 12/17/2025
Date Made Active in Reports: 12/22/2025
Number of Days to Update: 5

Source: Department of Toxic Substances Control
Telephone: 916-440-7145
Last EDR Contact: 12/17/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Quarterly

HWTS: Hazardous Waste Tracking System

DTSC maintains the Hazardous Waste Tracking System that stores ID number information since the early 1980s and manifest data since 1993. The system collects both manifest copies from the generator and destination facility.

Date of Government Version: 12/17/2025
Date Data Arrived at EDR: 12/23/2025
Date Made Active in Reports: 01/07/2026
Number of Days to Update: 15

Source: Department of Toxic Substances Control
Telephone: 916-324-2444
Last EDR Contact: 12/15/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method. This database begins with calendar year 1993.

Date of Government Version: 12/31/2024
Date Data Arrived at EDR: 09/30/2025
Date Made Active in Reports: 12/22/2025
Number of Days to Update: 83

Source: California Environmental Protection Agency
Telephone: 916-255-1136
Last EDR Contact: 12/23/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Annually

MINES: Mines Site Location Listing

A listing of mine site locations from the Office of Mine Reclamation.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 79

Source: Department of Conservation
Telephone: 916-322-1080
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

MWMP: Medical Waste Management Program Listing

The Medical Waste Management Program (MWMP) ensures the proper handling and disposal of medical waste by permitting and inspecting medical waste Offsite Treatment Facilities (PDF) and Transfer Stations (PDF) throughout the state. MWMP also oversees all Medical Waste Transporters.

Date of Government Version: 11/05/2025
Date Data Arrived at EDR: 11/26/2025
Date Made Active in Reports: 02/12/2026
Number of Days to Update: 78

Source: Department of Public Health
Telephone: 916-558-1784
Last EDR Contact: 02/24/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Varies

NPDES: NPDES Permits Listing

A listing of NPDES permits, including stormwater.

Date of Government Version: 11/03/2025
Date Data Arrived at EDR: 11/03/2025
Date Made Active in Reports: 01/27/2026
Number of Days to Update: 85

Source: State Water Resources Control Board
Telephone: 916-445-9379
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: Quarterly

PEST LIC: Pesticide Regulation Licenses Listing

A listing of licenses and certificates issued by the Department of Pesticide Regulation. The DPR issues licenses and/or certificates to: Persons and businesses that apply or sell pesticides; Pest control dealers and brokers; Persons who advise on agricultural pesticide applications.

Date of Government Version: 11/19/2025
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 02/09/2026
Number of Days to Update: 82

Source: Department of Pesticide Regulation
Telephone: 916-445-4038
Last EDR Contact: 02/24/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Quarterly

PROC: Certified Processors Database
A listing of certified processors.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/13/2026
Number of Days to Update: 80
Source: Department of Conservation
Telephone: 916-323-3836
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

NOTIFY 65: Proposition 65 Records
Listings of all Proposition 65 incidents reported to counties by the State Water Resources Control Board and the Regional Water Quality Control Board. This database is no longer updated by the reporting agency.

Date of Government Version: 12/01/2025
Date Data Arrived at EDR: 12/02/2025
Date Made Active in Reports: 12/05/2025
Number of Days to Update: 3
Source: State Water Resources Control Board
Telephone: 916-445-3846
Last EDR Contact: 12/01/2025
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: No Update Planned

SAN JOSE HAZMAT: Hazardous Material Facilities
Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 11/03/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 01/26/2021
Number of Days to Update: 82
Source: City of San Jose Fire Department
Telephone: 408-535-7694
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Annually

UIC: UIC Listing
A listing of wells identified as underground injection wells, in the California Oil and Gas Wells database.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/13/2026
Number of Days to Update: 80
Source: Deaprtment of Conservation
Telephone: 916-445-2408
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

UIC GEO: Underground Injection Control Sites (GEOTRACKER)
Underground control injection sites

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79
Source: State Water Resource Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

WASTEWATER PITS: Oil Wastewater Pits Listing
Water officials discovered that oil producers have been dumping chemical-laden wastewater into hundreds of unlined pits that are operating without proper permits. Inspections completed by the Central Valley Regional Water Quality Control Board revealed the existence of previously unidentified waste sites. The water boards review found that more than one-third of the region's active disposal pits are operating without permission.

Date of Government Version: 02/11/2021
Date Data Arrived at EDR: 07/01/2021
Date Made Active in Reports: 09/29/2021
Number of Days to Update: 90
Source: RWQCB, Central Valley Region
Telephone: 559-445-5577
Last EDR Contact: 12/23/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Varies

WDS: Waste Discharge System
Sites which have been issued waste discharge requirements.

Date of Government Version: 06/19/2007
Date Data Arrived at EDR: 06/20/2007
Date Made Active in Reports: 06/29/2007
Number of Days to Update: 9

Source: State Water Resources Control Board
Telephone: 916-341-5227
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: No Update Planned

WIP: Well Investigation Program Case List

Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 07/03/2009
Date Data Arrived at EDR: 07/21/2009
Date Made Active in Reports: 08/03/2009
Number of Days to Update: 13

Source: Los Angeles Water Quality Control Board
Telephone: 213-576-6726
Last EDR Contact: 03/11/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: No Update Planned

MILITARY PRIV SITES: Military Privatized Sites (GEOTRACKER)

Military privatized sites

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

PROJECT: Project Sites (GEOTRACKER)

Projects sites

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

WDR: Waste Discharge Requirements Listing

In general, the Waste Discharge Requirements (WDRs) Program (sometimes also referred to as the "Non Chapter 15 (Non 15) Program") regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. Exemptions from Title 27 may be granted for nine categories of discharges (e.g., sewage, wastewater, etc.) that meet, and continue to meet, the preconditions listed for each specific exemption. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Date of Government Version: 11/25/2025
Date Data Arrived at EDR: 11/25/2025
Date Made Active in Reports: 02/13/2026
Number of Days to Update: 80

Source: State Water Resources Control Board
Telephone: 916-341-5810
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

CIWQS: California Integrated Water Quality System

The California Integrated Water Quality System (CIWQS) is a computer system used by the State and Regional Water Quality Control Boards to track information about places of environmental interest, manage permits and other orders, track inspections, and manage violations and enforcement activities.

Date of Government Version: 11/19/2025
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 02/04/2026
Number of Days to Update: 77

Source: State Water Resources Control Board
Telephone: 866-794-4977
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Varies

CERS: CalEPA Regulated Site Portal Data

The CalEPA Regulated Site Portal database combines data about environmentally regulated sites and facilities in California into a single database. It combines data from a variety of state and federal databases, and provides an overview of regulated activities across the spectrum of environmental programs for any given location in California. These activities include hazardous materials and waste, state and federal cleanups, impacted ground and surface waters, and toxic materials

Date of Government Version: 10/13/2025
Date Data Arrived at EDR: 10/13/2025
Date Made Active in Reports: 12/17/2025
Number of Days to Update: 65

Source: California Environmental Protection Agency
Telephone: 916-323-2514
Last EDR Contact: 01/13/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

NON-CASE INFO: Non-Case Information Sites (GEOTRACKER)
Non-Case Information sites

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

OTHER OIL GAS: Other Oil & Gas Projects Sites (GEOTRACKER)
Other Oil & Gas Projects sites

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

PROD WATER PONDS: Produced Water Ponds Sites (GEOTRACKER)
Produced water ponds sites

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

SAMPLING POINT: Sampling Point ? Public Sites (GEOTRACKER)
Sampling point - public sites

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

WELL STIM PROJ: Well Stimulation Project (GEOTRACKER)
Includes areas of groundwater monitoring plans, a depiction of the monitoring network, and the facilities, boundaries, and subsurface characteristics of the oilfield and the features (oil and gas wells, produced water ponds, UIC wells, water supply wells, etc?) being monitored

Date of Government Version: 11/24/2025
Date Data Arrived at EDR: 11/24/2025
Date Made Active in Reports: 02/11/2026
Number of Days to Update: 79

Source: State Water Resources Control Board
Telephone: 866-480-1028
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants
The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Resources Recycling and Recovery in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/13/2014
Number of Days to Update: 196

Source: Department of Resources Recycling and Recovery
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the State Water Resources Control Board in California.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: State Water Resources Control Board
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

COUNTY RECORDS

ALAMEDA COUNTY:

CS ALAMEDA: Contaminated Sites
A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 01/09/2019
Date Data Arrived at EDR: 01/11/2019
Date Made Active in Reports: 03/05/2019
Number of Days to Update: 53

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 12/15/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Semi-Annually

UST ALAMEDA: Underground Tanks
Underground storage tank sites located in Alameda county.

Date of Government Version: 12/26/2023
Date Data Arrived at EDR: 12/26/2023
Date Made Active in Reports: 03/19/2024
Number of Days to Update: 84

Source: Alameda County Environmental Health Services
Telephone: 510-567-6700
Last EDR Contact: 12/15/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Semi-Annually

AMADOR COUNTY:

CUPA AMADOR: CUPA Facility List
Cupa Facility List

Date of Government Version: 04/27/2023
Date Data Arrived at EDR: 04/27/2023
Date Made Active in Reports: 07/13/2023
Number of Days to Update: 77

Source: Amador County Environmental Health
Telephone: 209-223-6439
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

BUTTE COUNTY:

CUPA BUTTE: CUPA Facility Listing
Cupa facility list.

Date of Government Version: 04/21/2017
Date Data Arrived at EDR: 04/25/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 106

Source: Public Health Department
Telephone: 530-538-7149
Last EDR Contact: 12/15/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: No Update Planned

CALVERAS COUNTY:

CUPA CALVERAS: CUPA Facility Listing
Cupa Facility Listing

Date of Government Version: 12/04/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 82

Source: Calveras County Environmental Health
Telephone: 209-754-6399
Last EDR Contact: 03/11/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

COLUSA COUNTY:

CUPA COLUSA: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/06/2020
Date Data Arrived at EDR: 04/23/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 78

Source: Health & Human Services
Telephone: 530-458-0396
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Semi-Annually

CONTRA COSTA COUNTY:

SL CONTRA COSTA: Site List
List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 10/17/2025
Date Data Arrived at EDR: 10/21/2025
Date Made Active in Reports: 01/09/2026
Number of Days to Update: 80

Source: Contra Costa Health Services Department
Telephone: 925-646-2286
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Semi-Annually

DEL NORTE COUNTY:

CUPA DEL NORTE: CUPA Facility List
Cupa Facility list

Date of Government Version: 02/05/2025
Date Data Arrived at EDR: 02/12/2025
Date Made Active in Reports: 05/02/2025
Number of Days to Update: 79

Source: Del Norte County Environmental Health Division
Telephone: 707-465-0426
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

EL DORADO COUNTY:

CUPA EL DORADO: CUPA Facility List
CUPA facility list.

Date of Government Version: 08/08/2022
Date Data Arrived at EDR: 08/09/2022
Date Made Active in Reports: 09/01/2022
Number of Days to Update: 23

Source: El Dorado County Environmental Management Department
Telephone: 530-621-6623
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

FRESNO COUNTY:

CUPA FRESNO: CUPA Resources List
Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 06/28/2021
Date Data Arrived at EDR: 12/21/2021
Date Made Active in Reports: 03/03/2022
Number of Days to Update: 72

Source: Dept. of Community Health
Telephone: 559-445-3271
Last EDR Contact: 12/09/2025
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Semi-Annually

GLENN COUNTY:

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CUPA GLENN: CUPA Facility List
Cupa facility list

Date of Government Version: 01/22/2018
Date Data Arrived at EDR: 01/24/2018
Date Made Active in Reports: 03/14/2018
Number of Days to Update: 49

Source: Glenn County Air Pollution Control District
Telephone: 830-934-6500
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: No Update Planned

HUMBOLDT COUNTY:

CUPA HUMBOLDT: CUPA Facility List
CUPA facility list.

Date of Government Version: 08/12/2021
Date Data Arrived at EDR: 08/12/2021
Date Made Active in Reports: 11/08/2021
Number of Days to Update: 88

Source: Humboldt County Environmental Health
Telephone: N/A
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Semi-Annually

IMPERIAL COUNTY:

CUPA IMPERIAL: CUPA Facility List
Cupa facility list.

Date of Government Version: 10/08/2025
Date Data Arrived at EDR: 10/08/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 76

Source: San Diego Border Field Office
Telephone: 760-339-2777
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

INYO COUNTY:

CUPA INYO: CUPA Facility List
Cupa facility list.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/03/2018
Date Made Active in Reports: 06/14/2018
Number of Days to Update: 72

Source: Inyo County Environmental Health Services
Telephone: 760-878-0238
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

KERN COUNTY:

CUPA KERN: CUPA Facility List
A listing of sites included in the Kern County Hazardous Material Business Plan.

Date of Government Version: 10/22/2025
Date Data Arrived at EDR: 10/23/2025
Date Made Active in Reports: 01/16/2026
Number of Days to Update: 85

Source: Kern County Public Health
Telephone: 661-321-3000
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

UST KERN: Underground Storage Tank Sites & Tank Listing
Kern County Sites and Tanks Listing.

Date of Government Version: 10/22/2025
Date Data Arrived at EDR: 10/23/2025
Date Made Active in Reports: 01/14/2026
Number of Days to Update: 83

Source: Kern County Environment Health Services Department
Telephone: 661-862-8700
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Quarterly

KINGS COUNTY:

CUPA KINGS: CUPA Facility List

A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 12/03/2020
Date Data Arrived at EDR: 01/26/2021
Date Made Active in Reports: 04/14/2021
Number of Days to Update: 78

Source: Kings County Department of Public Health
Telephone: 559-584-1411
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

LAKE COUNTY:

CUPA LAKE: CUPA Facility List

Cupa facility list

Date of Government Version: 01/28/2025
Date Data Arrived at EDR: 01/29/2025
Date Made Active in Reports: 04/15/2025
Number of Days to Update: 76

Source: Lake County Environmental Health
Telephone: 707-263-1164
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Varies

LASSEN COUNTY:

CUPA LASSEN: CUPA Facility List

Cupa facility list

Date of Government Version: 07/31/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/09/2020
Number of Days to Update: 80

Source: Lassen County Environmental Health
Telephone: 530-251-8528
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

LOS ANGELES COUNTY:

AOCONCERN: Key Areas of Concerns in Los Angeles County

San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office. Date of Government Version: 3/30/2009 Exide Site area is a cleanup plan of lead-impacted soil surrounding the former Exide Facility as designated by the DTSC. Date of Government Version: 7/17/2017

Date of Government Version: 03/30/2009
Date Data Arrived at EDR: 03/31/2009
Date Made Active in Reports: 10/23/2009
Number of Days to Update: 206

Source: N/A
Telephone: N/A
Last EDR Contact: 03/04/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

HMS LOS ANGELES: HMS: Street Number List
Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 12/18/2025
Date Data Arrived at EDR: 12/18/2025
Date Made Active in Reports: 12/22/2025
Number of Days to Update: 4

Source: Department of Public Works
Telephone: 626-458-3517
Last EDR Contact: 12/15/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Semi-Annually

LF LOS ANGELES: List of Solid Waste Facilities
Solid Waste Facilities in Los Angeles County.

Date of Government Version: 10/06/2025
Date Data Arrived at EDR: 10/07/2025
Date Made Active in Reports: 12/23/2025
Number of Days to Update: 77

Source: La County Department of Public Works
Telephone: 818-458-5185
Last EDR Contact: 01/06/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Varies

LF LOS ANGELES CITY: City of Los Angeles Landfills
Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 10/03/2024
Date Made Active in Reports: 12/17/2024
Number of Days to Update: 75

Source: Engineering & Construction Division
Telephone: 213-473-7869
Last EDR Contact: 01/05/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Varies

LOS ANGELES AST: Active & Inactive AST Inventory
A listing of active & inactive above ground petroleum storage tank site locations, located in the City of Los Angeles.

Date of Government Version: 06/01/2019
Date Data Arrived at EDR: 06/25/2019
Date Made Active in Reports: 08/22/2019
Number of Days to Update: 58

Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 03/11/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Varies

LOS ANGELES CO LF METHANE: Methane Producing Landfills
This data was created on April 30, 2012 to represent known disposal sites in Los Angeles County that may produce and emanate methane gas. The shapefile contains disposal sites within Los Angeles County that once accepted degradable refuse material. Information used to create this data was extracted from a landfill survey performed by County Engineers (Major Waste System Map, 1973) as well as historical records from CalRecycle, Regional Water Quality Control Board, and Los Angeles County Department of Public Health

Date of Government Version: 05/14/2024
Date Data Arrived at EDR: 07/09/2024
Date Made Active in Reports: 09/27/2024
Number of Days to Update: 80

Source: Los Angeles County Department of Public Works
Telephone: 626-458-6973
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: No Update Planned

LOS ANGELES HM: Active & Inactive Hazardous Materials Inventory
A listing of active & inactive hazardous materials facility locations, located in the City of Los Angeles.

Date of Government Version: 12/01/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 80

Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/08/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Varies

LOS ANGELES UST: Active & Inactive UST Inventory
A listing of active & inactive underground storage tank site locations and underground storage tank historical sites, located in the City of Los Angeles.

Date of Government Version: 12/01/2025
Date Data Arrived at EDR: 12/08/2025
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 80
Source: Los Angeles Fire Department
Telephone: 213-978-3800
Last EDR Contact: 12/08/2025
Next Scheduled EDR Contact: 03/30/2026
Data Release Frequency: Varies

SITE MIT LOS ANGELES: Site Mitigation LA County List
Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 04/29/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/03/2025
Number of Days to Update: 85
Source: Community Health Services
Telephone: 323-890-7806
Last EDR Contact: 07/10/2025
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Annually

UST EL SEGUNDO: City of El Segundo Underground Storage Tank
Underground storage tank sites located in El Segundo city.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/10/2017
Number of Days to Update: 21
Source: City of El Segundo Fire Department
Telephone: 310-524-2236
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

UST LONG BEACH: City of Long Beach Underground Storage Tank
Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 04/22/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/27/2019
Number of Days to Update: 65
Source: City of Long Beach Fire Department
Telephone: 562-570-2563
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

UST TORRANCE: City of Torrance Underground Storage Tank
Underground storage tank sites located in the city of Torrance.

Date of Government Version: 07/16/2025
Date Data Arrived at EDR: 07/17/2025
Date Made Active in Reports: 10/09/2025
Number of Days to Update: 84
Source: City of Torrance Fire Department
Telephone: 310-618-2973
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Semi-Annually

MADERA COUNTY:

CUPA MADERA: CUPA Facility List
A listing of sites included in the county's Certified Unified Program Agency database. California's Secretary for Environmental Protection established the unified hazardous materials and hazardous waste regulatory program as required by chapter 6.11 of the California Health and Safety Code. The Unified Program consolidates the administration, permits, inspections, and enforcement activities.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/12/2020
Date Made Active in Reports: 10/23/2020
Number of Days to Update: 72
Source: Madera County Environmental Health
Telephone: 559-675-7823
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

MARIN COUNTY:

UST MARIN: Underground Storage Tank Sites
Currently permitted USTs in Marin County.

Date of Government Version: 09/26/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/02/2018
Number of Days to Update: 29

Source: Public Works Department Waste Management
Telephone: 415-473-6647
Last EDR Contact: 12/09/2025
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Semi-Annually

MENDOCINO COUNTY:

UST MENDOCINO: Mendocino County UST Database
A listing of underground storage tank locations in Mendocino County.

Date of Government Version: 09/22/2021
Date Data Arrived at EDR: 11/18/2021
Date Made Active in Reports: 11/22/2021
Number of Days to Update: 4

Source: Department of Public Health
Telephone: 707-463-4466
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Annually

MERCED COUNTY:

CUPA MERCED: CUPA Facility List
CUPA facility list.

Date of Government Version: 11/10/2025
Date Data Arrived at EDR: 11/14/2025
Date Made Active in Reports: 02/03/2026
Number of Days to Update: 81

Source: Merced County Environmental Health
Telephone: 209-381-1094
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

MONO COUNTY:

CUPA MONO: CUPA Facility List
CUPA Facility List

Date of Government Version: 02/22/2021
Date Data Arrived at EDR: 03/02/2021
Date Made Active in Reports: 05/19/2021
Number of Days to Update: 78

Source: Mono County Health Department
Telephone: 760-932-5580
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Varies

MONTEREY COUNTY:

CUPA MONTEREY: CUPA Facility Listing
CUPA Program listing from the Environmental Health Division.

Date of Government Version: 09/25/2025
Date Data Arrived at EDR: 09/26/2025
Date Made Active in Reports: 10/08/2025
Number of Days to Update: 12

Source: Monterey County Health Department
Telephone: 831-796-1297
Last EDR Contact: 01/05/2026
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Varies

NAPA COUNTY:

LUST NAPA: Sites With Reported Contamination
A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 03/02/2017
Number of Days to Update: 50

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: No Update Planned

UST NAPA: Closed and Operating Underground Storage Tank Sites
Underground storage tank sites located in Napa county.

Date of Government Version: 09/05/2019
Date Data Arrived at EDR: 09/09/2019
Date Made Active in Reports: 10/31/2019
Number of Days to Update: 52

Source: Napa County Department of Environmental Management
Telephone: 707-253-4269
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: No Update Planned

NEVADA COUNTY:

CUPA NEVADA: CUPA Facility List
CUPA facility list.

Date of Government Version: 10/22/2025
Date Data Arrived at EDR: 10/23/2025
Date Made Active in Reports: 01/14/2026
Number of Days to Update: 83

Source: Community Development Agency
Telephone: 530-265-1467
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

ORANGE COUNTY:

IND_SITE ORANGE: List of Industrial Site Cleanups Orange County
Petroleum and non-petroleum spills.

Date of Government Version: 10/23/2025
Date Data Arrived at EDR: 10/24/2025
Date Made Active in Reports: 01/15/2026
Number of Days to Update: 83

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Annually

LUST ORANGE: List of Underground Storage Tank Cleanups
Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 10/24/2025
Date Data Arrived at EDR: 10/28/2025
Date Made Active in Reports: 01/15/2026
Number of Days to Update: 79

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 10/22/2025
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Quarterly

UST ORANGE: List of Underground Storage Tank Facilities
Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 04/29/2025
Date Data Arrived at EDR: 04/30/2025
Date Made Active in Reports: 07/17/2025
Number of Days to Update: 78

Source: Health Care Agency
Telephone: 714-834-3446
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: No Update Planned

PLACER COUNTY:

MS PLACER: Master List of Facilities
List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 11/19/2025
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 02/09/2026
Number of Days to Update: 82
Source: Placer County Health and Human Services
Telephone: 530-745-2363
Last EDR Contact: 02/18/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Semi-Annually

PLUMAS COUNTY:

CUPA PLUMAS: CUPA Facility List
Plumas County CUPA Program facilities.

Date of Government Version: 03/31/2019
Date Data Arrived at EDR: 04/23/2019
Date Made Active in Reports: 06/26/2019
Number of Days to Update: 64
Source: Plumas County Environmental Health
Telephone: 530-283-6355
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

RIVERSIDE COUNTY:

LUST RIVERSIDE: Listing of Underground Tank Cleanup Sites
Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 06/11/2024
Date Data Arrived at EDR: 06/12/2024
Date Made Active in Reports: 06/27/2024
Number of Days to Update: 15
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 03/04/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Quarterly

UST RIVERSIDE: Underground Storage Tank Tank List
Underground storage tank sites located in Riverside county.

Date of Government Version: 12/05/2025
Date Data Arrived at EDR: 12/05/2025
Date Made Active in Reports: 12/09/2025
Number of Days to Update: 4
Source: Department of Environmental Health
Telephone: 951-358-5055
Last EDR Contact: 03/04/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Quarterly

SACRAMENTO COUNTY:

CS SACRAMENTO: Toxic Site Clean-Up List
List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 11/07/2022
Date Data Arrived at EDR: 12/21/2022
Date Made Active in Reports: 03/16/2023
Number of Days to Update: 85
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 12/09/2025
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Quarterly

ML SACRAMENTO: Master Hazardous Materials Facility List
Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 11/07/2022
Date Data Arrived at EDR: 12/09/2022
Date Made Active in Reports: 03/01/2023
Number of Days to Update: 82
Source: Sacramento County Environmental Management
Telephone: 916-875-8406
Last EDR Contact: 12/09/2025
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Quarterly

SAN BENITO COUNTY:

CUPA SAN BENITO: CUPA Facility List
Cupa facility list

Date of Government Version: 10/23/2025
Date Data Arrived at EDR: 10/24/2025
Date Made Active in Reports: 01/14/2026
Number of Days to Update: 82

Source: San Benito County Environmental Health
Telephone: N/A
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

SAN BERNARDINO COUNTY:

PERMITS SAN BERNARDINO: Hazardous Material Permits
This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 11/18/2025
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 02/09/2026
Number of Days to Update: 82

Source: San Bernardino County Fire Department Hazardous Materials Division
Telephone: 909-387-3041
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Quarterly

SAN DIEGO COUNTY:

HMMD SAN DIEGO: Hazardous Materials Management Division Database
The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 11/19/2025
Date Data Arrived at EDR: 11/19/2025
Date Made Active in Reports: 02/05/2026
Number of Days to Update: 78

Source: Hazardous Materials Management Division
Telephone: 619-338-2268
Last EDR Contact: 02/24/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: Quarterly

LF SAN DIEGO: Solid Waste Facilities
San Diego County Solid Waste Facilities.

Date of Government Version: 10/01/2024
Date Data Arrived at EDR: 01/15/2025
Date Made Active in Reports: 03/28/2025
Number of Days to Update: 72

Source: Department of Health Services
Telephone: 619-338-2209
Last EDR Contact: 01/09/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

SAN DIEGO CO LOP: Local Oversight Program Listing
A listing of all LOP release sites that are or were under the County of San Diego's jurisdiction. Included are closed or transferred cases, open cases, and cases that did not have a case type indicated. The cases without a case type are mostly complaints; however, some of them could be LOP cases.

Date of Government Version: 07/22/2021
Date Data Arrived at EDR: 10/19/2021
Date Made Active in Reports: 01/13/2022
Number of Days to Update: 86

Source: Department of Environmental Health
Telephone: 858-505-6874
Last EDR Contact: 01/07/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

SAN DIEGO CO SAM: Environmental Case Listing
The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 03/23/2010
Date Data Arrived at EDR: 06/15/2010
Date Made Active in Reports: 07/09/2010
Number of Days to Update: 24
Source: San Diego County Department of Environmental Health
Telephone: 619-338-2371
Last EDR Contact: 02/18/2026
Next Scheduled EDR Contact: 06/08/2026
Data Release Frequency: No Update Planned

SAN FRANCISCO COUNTY:

CUPA SAN FRANCISCO CO: CUPA Facility Listing
Cupa facilities

Date of Government Version: 01/27/2026
Date Data Arrived at EDR: 01/27/2026
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 30
Source: San Francisco County Department of Environmental Health
Telephone: 415-252-3896
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

LUST SAN FRANCISCO: Local Oversite Facilities
A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/19/2008
Date Data Arrived at EDR: 09/19/2008
Date Made Active in Reports: 09/29/2008
Number of Days to Update: 10
Source: Department Of Public Health San Francisco County
Telephone: 415-252-3920
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: No Update Planned

UST SAN FRANCISCO: Underground Storage Tank Information
Underground storage tank sites located in San Francisco county.

Date of Government Version: 01/27/2026
Date Data Arrived at EDR: 01/27/2026
Date Made Active in Reports: 02/26/2026
Number of Days to Update: 30
Source: Department of Public Health
Telephone: 415-252-3920
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Quarterly

SAN FRANCISO COUNTY:

SAN FRANCISCO MAHER: Maher Ordinance Property Listing
A listing of properties that fall within a Maher Ordinance, for all of San Francisco. The Maher Ordinance requires San Francisco Department of Public Health (DPH) oversight for the characterization and mitigation of hazardous substances found in soil, soil vapor, and groundwater in areas designated within the Maher map. The Maher map includes areas with current or historical industrial use or zoning; areas within 100 feet of current or historical underground tanks; filled former Bay, marsh, or creek areas; or areas within 150 feet of a current or former elevated highway. City of San Francisco Planning.

Date of Government Version: 08/12/2025
Date Data Arrived at EDR: 10/14/2025
Date Made Active in Reports: 01/09/2026
Number of Days to Update: 87
Source: San Francisco Planning
Telephone: 628-652-7483
Last EDR Contact: 01/13/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

SAN JOAQUIN COUNTY:

UST SAN JOAQUIN: San Joaquin Co. UST
A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 06/22/2018
Date Data Arrived at EDR: 06/26/2018
Date Made Active in Reports: 07/11/2018
Number of Days to Update: 15

Source: Environmental Health Department
Telephone: N/A
Last EDR Contact: 03/04/2026
Next Scheduled EDR Contact: 06/22/2026
Data Release Frequency: Semi-Annually

SAN LUIS OBISPO COUNTY:

CUPA SAN LUIS OBISPO: CUPA Facility List
Cupa Facility List.

Date of Government Version: 11/04/2025
Date Data Arrived at EDR: 11/05/2025
Date Made Active in Reports: 11/14/2025
Number of Days to Update: 9

Source: San Luis Obispo County Public Health Department
Telephone: 805-781-5596
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

SAN MATEO COUNTY:

BI SAN MATEO: Business Inventory
List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 02/20/2020
Date Data Arrived at EDR: 02/20/2020
Date Made Active in Reports: 04/24/2020
Number of Days to Update: 64

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 02/25/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Annually

LUST SAN MATEO: Fuel Leak List
A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 03/29/2019
Date Data Arrived at EDR: 03/29/2019
Date Made Active in Reports: 05/29/2019
Number of Days to Update: 61

Source: San Mateo County Environmental Health Services Division
Telephone: 650-363-1921
Last EDR Contact: 02/25/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Semi-Annually

SANTA BARBARA COUNTY:

CUPA SANTA BARBARA: CUPA Facility Listing
CUPA Program Listing from the Environmental Health Services division.

Date of Government Version: 09/08/2011
Date Data Arrived at EDR: 09/09/2011
Date Made Active in Reports: 10/07/2011
Number of Days to Update: 28

Source: Santa Barbara County Public Health Department
Telephone: 805-686-8167
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: No Update Planned

SANTA CLARA COUNTY:

CUPA SANTA CLARA: Cupa Facility List
Cupa facility list

Date of Government Version: 11/07/2025
Date Data Arrived at EDR: 11/10/2025
Date Made Active in Reports: 01/29/2026
Number of Days to Update: 80

Source: Department of Environmental Health
Telephone: 408-918-1973
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

HIST LUST SANTA CLARA: HIST LUST - Fuel Leak Site Activity Report
A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005
Date Data Arrived at EDR: 03/30/2005
Date Made Active in Reports: 04/21/2005
Number of Days to Update: 22

Source: Santa Clara Valley Water District
Telephone: 408-265-2600
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

LUST SANTA CLARA: LOP Listing
A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/03/2014
Date Data Arrived at EDR: 03/05/2014
Date Made Active in Reports: 03/18/2014
Number of Days to Update: 13

Source: Department of Environmental Health
Telephone: 408-918-3417
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: No Update Planned

SANTA CRUZ COUNTY:

CUPA SANTA CRUZ: CUPA Facility List
CUPA facility listing.

Date of Government Version: 01/21/2017
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 05/23/2017
Number of Days to Update: 90

Source: Santa Cruz County Environmental Health
Telephone: 831-464-2761
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

SITE MIT SANTA CRUZ: Site Mitigation Santa Cruz County List
Sites may become contaminated with toxic chemicals through illegal dumping or disposal, from leaking underground storage tanks, or through industrial or commercial activities.The goal of the site mitigation program is to protect the public health and the environment while facilitating completion of contaminated site clean-up projects in a timely manner.

Date of Government Version: 12/03/2018
Date Data Arrived at EDR: 06/23/2023
Date Made Active in Reports: 07/13/2023
Number of Days to Update: 20

Source: Santa Cruz Environmental Health Services
Telephone: 831-454-2761
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

SHASTA COUNTY:

CUPA SHASTA: CUPA Facility List
Cupa Facility List.

Date of Government Version: 06/15/2017
Date Data Arrived at EDR: 06/19/2017
Date Made Active in Reports: 08/09/2017
Number of Days to Update: 51

Source: Shasta County Department of Resource Management
Telephone: 530-225-5789
Last EDR Contact: 02/04/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Varies

SOLANO COUNTY:

LUST SOLANO: Leaking Underground Storage Tanks
A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 06/04/2019
Date Data Arrived at EDR: 06/06/2019
Date Made Active in Reports: 08/13/2019
Number of Days to Update: 68

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Quarterly

UST SOLANO: Underground Storage Tanks
Underground storage tank sites located in Solano county.

Date of Government Version: 09/15/2021
Date Data Arrived at EDR: 09/16/2021
Date Made Active in Reports: 12/09/2021
Number of Days to Update: 84

Source: Solano County Department of Environmental Management
Telephone: 707-784-6770
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Quarterly

SONOMA COUNTY:

CUPA SONOMA: Cupa Facility List
Cupa Facility list

Date of Government Version: 07/02/2021
Date Data Arrived at EDR: 07/06/2021
Date Made Active in Reports: 07/14/2021
Number of Days to Update: 8

Source: County of Sonoma Fire & Emergency Services Department
Telephone: 707-565-1174
Last EDR Contact: 03/11/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Varies

LUST SONOMA: Leaking Underground Storage Tank Sites
A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 06/30/2021
Date Data Arrived at EDR: 06/30/2021
Date Made Active in Reports: 09/24/2021
Number of Days to Update: 86

Source: Department of Health Services
Telephone: 707-565-6565
Last EDR Contact: 03/11/2026
Next Scheduled EDR Contact: 06/29/2026
Data Release Frequency: Quarterly

STANISLAUS COUNTY:

CUPA STANISLAUS: CUPA Facility List
Cupa facility list

Date of Government Version: 02/08/2022
Date Data Arrived at EDR: 02/10/2022
Date Made Active in Reports: 05/04/2022
Number of Days to Update: 83

Source: Stanislaus County Department of Ennvironmental Protection
Telephone: 209-525-6751
Last EDR Contact: 12/20/2025
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Varies

SUTTER COUNTY:

UST SUTTER: Underground Storage Tanks
Underground storage tank sites located in Sutter county.

Date of Government Version: 07/23/2025
Date Data Arrived at EDR: 10/08/2025
Date Made Active in Reports: 12/24/2025
Number of Days to Update: 77

Source: Sutter County Environmental Health Services
Telephone: 530-822-7500
Last EDR Contact: 02/11/2026
Next Scheduled EDR Contact: 06/01/2026
Data Release Frequency: Semi-Annually

TEHAMA COUNTY:

CUPA TEHAMA: CUPA Facility List
Cupa facilities

Date of Government Version: 11/12/2025
Date Data Arrived at EDR: 11/12/2025
Date Made Active in Reports: 01/29/2026
Number of Days to Update: 78

Source: Tehama County Department of Environmental Health
Telephone: 530-527-8020
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

TRINITY COUNTY:

CUPA TRINITY: CUPA Facility List
Cupa facility list

Date of Government Version: 04/09/2025
Date Data Arrived at EDR: 04/10/2025
Date Made Active in Reports: 06/27/2025
Number of Days to Update: 78

Source: Department of Toxic Substances Control
Telephone: 760-352-0381
Last EDR Contact: 01/08/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

TULARE COUNTY:

CUPA TULARE: CUPA Facility List
Cupa program facilities

Date of Government Version: 10/07/2022
Date Data Arrived at EDR: 10/07/2022
Date Made Active in Reports: 12/21/2022
Number of Days to Update: 75

Source: Tulare County Environmental Health Services Division
Telephone: 559-624-7400
Last EDR Contact: 01/21/2026
Next Scheduled EDR Contact: 05/11/2026
Data Release Frequency: Varies

TUOLUMNE COUNTY:

CUPA TUOLUMNE: CUPA Facility List
Cupa facility list

Date of Government Version: 04/23/2018
Date Data Arrived at EDR: 04/25/2018
Date Made Active in Reports: 06/25/2018
Number of Days to Update: 61

Source: Divison of Environmental Health
Telephone: 209-533-5633
Last EDR Contact: 01/27/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Varies

VENTURA COUNTY:

BWT VENTURA: Business Plan, Hazardous Waste Producers, and Operating Underground Tanks
The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 09/30/2025
Date Data Arrived at EDR: 10/24/2025
Date Made Active in Reports: 01/14/2026
Number of Days to Update: 82

Source: Ventura County Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Quarterly

LF VENTURA: Inventory of Illegal Abandoned and Inactive Sites
Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 12/01/2011
Date Data Arrived at EDR: 12/01/2011
Date Made Active in Reports: 01/19/2012
Number of Days to Update: 49
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 12/09/2025
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: No Update Planned

LUST VENTURA: Listing of Underground Tank Cleanup Sites
Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 05/29/2008
Date Data Arrived at EDR: 06/24/2008
Date Made Active in Reports: 07/31/2008
Number of Days to Update: 37
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 01/28/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: No Update Planned

MED WASTE VENTURA: Medical Waste Program List
To protect public health and safety and the environment from potential exposure to disease causing agents, the Environmental Health Division Medical Waste Program regulates the generation, handling, storage, treatment and disposal of medical waste throughout the County.

Date of Government Version: 09/30/2025
Date Data Arrived at EDR: 10/28/2025
Date Made Active in Reports: 01/15/2026
Number of Days to Update: 79
Source: Ventura County Resource Management Agency
Telephone: 805-654-2813
Last EDR Contact: 01/04/2026
Next Scheduled EDR Contact: 04/27/2026
Data Release Frequency: Quarterly

UST VENTURA: Underground Tank Closed Sites List
Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 11/26/2025
Date Data Arrived at EDR: 12/04/2025
Date Made Active in Reports: 02/25/2026
Number of Days to Update: 83
Source: Environmental Health Division
Telephone: 805-654-2813
Last EDR Contact: 03/03/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Quarterly

YOLO COUNTY:

UST YOLO: Underground Storage Tank Comprehensive Facility Report
Underground storage tank sites located in Yolo county.

Date of Government Version: 12/09/2025
Date Data Arrived at EDR: 12/10/2025
Date Made Active in Reports: 03/03/2026
Number of Days to Update: 83
Source: Yolo County Department of Health
Telephone: 530-666-8646
Last EDR Contact: 12/09/2025
Next Scheduled EDR Contact: 04/06/2026
Data Release Frequency: Annually

YUBA COUNTY:

CUPA YUBA: CUPA Facility List
CUPA facility listing for Yuba County.

Date of Government Version: 10/23/2025
Date Data Arrived at EDR: 10/24/2025
Date Made Active in Reports: 01/15/2026
Number of Days to Update: 83
Source: Yuba County Environmental Health Department
Telephone: 530-749-7523
Last EDR Contact: 01/14/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/02/2025
Date Data Arrived at EDR: 11/03/2025
Date Made Active in Reports: 01/23/2026
Number of Days to Update: 81

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/03/2026
Next Scheduled EDR Contact: 05/18/2026
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 12/15/2025
Next Scheduled EDR Contact: 04/13/2026
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/22/2026
Next Scheduled EDR Contact: 05/04/2026
Data Release Frequency: No Update Planned

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 12/29/2025
Next Scheduled EDR Contact: 04/20/2026
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/05/2026
Next Scheduled EDR Contact: 05/25/2026
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 02/25/2026
Next Scheduled EDR Contact: 06/15/2026
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Licensed Facilities
Source: Department of Social Services
Telephone: 916-657-4041

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

MARIPOSA COUNTY
FRANK WILSON RD
MARIPOSA, CA 95338

TARGET PROPERTY COORDINATES

Latitude (North):	37.500486 - 37° 30' 1.75''
Longitude (West):	119.984698 - 119° 59' 4.91''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	236146.4
UTM Y (Meters):	4154376.8
Elevation:	2139 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	50003925 FELICIANA MOUNTAIN, CA
Version Date:	2021
Southeast Map:	50003934 MARIPOSA, CA
Version Date:	2021
Southwest Map:	50003774 CATHEYS VALLEY, CA
Version Date:	2021
Northwest Map:	50003760 BEAR VALLEY, CA
Version Date:	2021

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 2139 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
06043C0588C	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
06043C0575C	FEMA FIRM Flood data
06043C0600C	FEMA FIRM Flood data
06043C0750C	FEMA FIRM Flood data
06043C0751C	FEMA FIRM Flood data
06043C0752C	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
FELICIANA MOUNTAIN	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Paleozoic
System:	Permian
Series:	Ultramafic rocks
Code:	uM *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Plutonic and Intrusive Rocks

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 8280255.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Mariposa County	CLIENT:	Provost & Pritchard Eng. Group
ADDRESS:	Frank Wilson Rd Mariposa CA 95338	CONTACT:	Stephanie Gillaspy
LAT/LONG:	37.500486 / 119.984698	INQUIRY #:	8280255.2s
		DATE:	March 12, 2026 7:29 pm

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: BLASINGAME

Soil Surface Texture: loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.42 Min: 0.01	Max: Min:
2	3 inches	35 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.42 Min: 0.01	Max: Min:
3	35 inches	40 inches	weathered bedrock	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.42 Min: 0.01	Max: Min:

Soil Map ID: 2

Soil Component Name: BLASINGAME

Soil Surface Texture: loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information

	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.42 Min: 0.01	Max: Min:
2	3 inches	35 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.42 Min: 0.01	Max: Min:
3	35 inches	40 inches	weathered bedrock	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.42 Min: 0.01	Max: Min:

Soil Map ID: 3

Soil Component Name: AUBURN

Soil Surface Texture: loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:
2	3 inches	16 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:
3	16 inches	20 inches	unweathered bedrock	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:

Soil Map ID: 4

Soil Component Name: AUBURN

Soil Surface Texture: loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Low

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:
2	3 inches	16 inches	loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:
3	16 inches	20 inches	unweathered bedrock	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	Not reported	Max: 0.01 Min: 0	Max: Min:

Soil Map ID: 5

Soil Component Name: RIVERWASH

Soil Surface Texture: extremely gravelly sand

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Partially hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 31 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	extremely gravelly sand	Not reported	Not reported	Max: Min:	Max: Min:
2	5 inches	59 inches		Not reported	Not reported	Max: Min:	Max: Min:

Soil Map ID: 6

Soil Component Name: HENNEKE

Soil Surface Texture: very gravelly loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Moderate

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	1 inches	very gravelly loam	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	Not reported	Max: 0.42 Min: 0.01	Max: Min:
2	1 inches	11 inches	extremely cobbly clay	Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	Not reported	Max: 0.42 Min: 0.01	Max: Min:

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
3	11 inches	14 inches		Granular materials (35 pct. or less passing No. 200), Silty, or Clayey Gravel and Sand.	Not reported	Max: 0.42 Min: 0.01	Max: Min:

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A1	CAEDF0000044005	0 - 1/8 Mile WSW
A2	CAEDF0000118305	0 - 1/8 Mile SW
A3	CAEDF0000137466	0 - 1/8 Mile West
A4	CAEDF0000143326	0 - 1/8 Mile WSW
A5	CAEDF0000043234	0 - 1/8 Mile West
A6	CAEDF0000042740	0 - 1/8 Mile West
A7	CAEDF0000032473	0 - 1/8 Mile West
A8	CAEDF0000019777	0 - 1/8 Mile WSW
A9	CAEDF0000077506	0 - 1/8 Mile West
A10	CAEDF0000014664	0 - 1/8 Mile West
11	CADDW2000016366	1/4 - 1/2 Mile SSE
B12	CADDW2000008700	1/4 - 1/2 Mile SSE
B13	6391	1/4 - 1/2 Mile SSE
C14	CAEDF0000007250	1/4 - 1/2 Mile SE
C15	CAEDF0000099680	1/4 - 1/2 Mile SE
C16	CAEDF0000088541	1/4 - 1/2 Mile SE
C17	CAEDF0000118349	1/4 - 1/2 Mile SE
C18	6388	1/4 - 1/2 Mile SE
C19	6386	1/4 - 1/2 Mile SE
C20	6390	1/4 - 1/2 Mile SE
C21	6389	1/4 - 1/2 Mile SE
22	CADDW2000009472	1/4 - 1/2 Mile SE
D23	6385	1/4 - 1/2 Mile East
C24	CADDW2000009445	1/4 - 1/2 Mile SE
D25	CADDW2000023004	1/2 - 1 Mile East
E26	6082	1/2 - 1 Mile ESE
E27	6080	1/2 - 1 Mile East
E28	CADDW2000019108	1/2 - 1 Mile ESE
E29	6081	1/2 - 1 Mile East
F30	CADDW2000001408	1/2 - 1 Mile East
F31	CADDW2000009066	1/2 - 1 Mile East
G32	6387	1/2 - 1 Mile SSE
G33	CADDW2000000864	1/2 - 1 Mile SSE
34	16063	1/2 - 1 Mile NNW
H35	6394	1/2 - 1 Mile SSE
H36	CADDW2000008636	1/2 - 1 Mile SSE
37	CADDW2000020313	1/2 - 1 Mile WNW
38	6393	1/2 - 1 Mile SE

PHYSICAL SETTING SOURCE MAP - 8280255.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake Fault Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- GI Indeterminate Groundwater Flow at Location
- GV Groundwater Flow Varies at Location
- HD Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	Mariposa County	CLIENT:	Provost & Pritchard Eng. Group
ADDRESS:	Frank Wilson Rd Mariposa CA 95338	CONTACT:	Stephanie Gillaspy
LAT/LONG:	37.500486 / 119.984698	INQUIRY #:	8280255.2s
		DATE:	March 12, 2026 7:29 pm

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A1
WSW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000044005**

Well ID:	T0604300083-MW-6	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-6
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-6&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-6		

A2
SW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000118305**

Well ID:	T0604300083-MW-8	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-8
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-8&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-8		

A3
West
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000137466**

Well ID:	T0604300083-MW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-3		

A4
WSW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000143326**

Well ID:	T0604300083-MW-7	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-7
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-7&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-7		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A5
West
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000043234**

Well ID:	T0604300083-MW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-2
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-2&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-2		

A6
West
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000042740**

Well ID:	T0604300083-MW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-1		

A7
West
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000032473**

Well ID:	T0604300083-MW-1R	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-1R
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-1R&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-1R		

A8
WSW
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000019777**

Well ID:	T0604300083-MW-5	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-5
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-5&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-5		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

A9
West
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000077506**

Well ID:	T0604300083-IW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	IW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=IW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=IW-1		

A10
West
0 - 1/8 Mile
Lower

CA WELLS **CAEDF0000014664**

Well ID:	T0604300083-MW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	MW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604300083&assigned_name=MW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604300083&assigned_name=MW-4		

11
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CADDW2000016366**

GAMA:

Well ID:	CA2210001_010_010	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-010
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_010_010&store_num=		
GeoTracker Data:	Not Reported		

B12
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **CADDW2000008700**

GAMA:

Well ID:	CA2210001_013_013	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-013
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_013_013&store_num=		
GeoTracker Data:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B13
SSE
1/4 - 1/2 Mile
Lower

CA WELLS **6391**

Seq:	6391	Prim sta c:	05S/18E-15K01 M
Frds no:	2210001013	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL IW 07	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372948.0	Longitude:	1195852.0
Precision:	3	Status:	AU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

Sample date:	30-MAY-17	Finding:	330.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		

Sample date:	30-MAY-17	Finding:	1.
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	31-MAY-16	Finding:	1.49
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		

Sample date:	31-MAY-16	Finding:	0.11
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		

Sample date:	31-MAY-16	Finding:	1.4
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		

Sample date:	20-MAY-15	Finding:	430.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		

Sample date:	20-MAY-15	Finding:	12.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		

Sample date:	20-MAY-15	Finding:	7.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		

Sample date:	20-MAY-15	Finding:	260.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		

Sample date:	20-MAY-15	Finding:	17.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	20-MAY-15	Finding:	7.1
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	8.8
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	30.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	36.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	210.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	240.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	200.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	7.4
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	05-MAY-14	Finding:	420.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	05-MAY-14	Finding:	7.
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	03-JUN-13	Finding:	5.9
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	21-MAY-12	Finding:	210.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	170.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	7.
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	380.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US

Dlr:	0.		
Sample date:	21-MAY-12	Finding:	4.6
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	21-MAY-12	Finding:	240.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	12.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	21-MAY-12	Finding:	7.
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	8.5
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	190.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	28.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	2.
Chemical:	ODOR THRESHOLD @ 60 C	Report units:	TON
Dlr:	1.		
Sample date:	21-MAY-12	Finding:	31.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		

C14
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000007250**

Well ID:	T0604391798-KMW-1	Well Type:	MONITORING
Source:	EDF	Other Name:	KMW-1
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604391798&assigned_name=KMW-1&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604391798&assigned_name=KMW-1		

C15
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000099680**

Well ID:	T0604391798-KMW-2	Well Type:	MONITORING
Source:	EDF	Other Name:	KMW-2
GAMA PFAS Testing:	Not Reported		

Groundwater Quality Data: https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604391798&assigned_name=KMW-2&store_num=
GeoTracker Data: https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604391798&assigned_name=KMW-2

C16
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000088541**

Well ID:	T0604391798-KMW-3	Well Type:	MONITORING
Source:	EDF	Other Name:	KMW-3
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604391798&assigned_name=KMW-3&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604391798&assigned_name=KMW-3		

C17
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CAEDF0000118349**

Well ID:	T0604391798-KMW-4	Well Type:	MONITORING
Source:	EDF	Other Name:	KMW-4
GAMA PFAS Testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=EDF&samp_date=&global_id=T0604391798&assigned_name=KMW-4&store_num=		
GeoTracker Data:	https://geotracker.waterboards.ca.gov/profile_report.asp?cmd=MWEDFResults&global_id=T0604391798&assigned_name=KMW-4		

C18
SE
1/4 - 1/2 Mile
Lower

CA WELLS **6388**

Seq:	6388	Prim sta c:	05S/18E-15J03 M
Frds no:	2210001018	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL IW 03 (STILL GREENAMYERS)-INACTIVE		
Station ty:	WELL/AMBNT/MUN/INTAKE	Latitude:	372944.0
Longitude:	1195846.0	Precision:	3
Status:	IR	Comment 1:	AT IDLE WHEELS MHP, 5277 HYW 49 N, MARIPO
Comment 2:	Not Reported	Comment 3:	Not Reported
Comment 4:	Not Reported	Comment 5:	Not Reported
Comment 6:	Not Reported	Comment 7:	Not Reported
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

Map ID
Direction
Distance
Elevation

	Database	EDR ID Number
C19 **SE** **1/4 - 1/2 Mile** **Lower**	**CA WELLS**	**6386**

Seq:	6386	Prim sta c:	05S/18E-15J01 M
Frds no:	2210001007	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL IW 01	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372944.0	Longitude:	1195846.0
Precision:	3	Status:	AR
Comment 1:	@ IDLE WHEELS MHP, 2577 HWY 49 N, MARIPOSA		
Comment 2:	Not Reported	Comment 3:	Not Reported
Comment 4:	Not Reported	Comment 5:	Not Reported
Comment 6:	Not Reported	Comment 7:	Not Reported
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		
Sample date:	30-MAY-17	Finding:	440.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	30-MAY-17	Finding:	3.
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	31-MAY-16	Finding:	2.4
Chemical:	NITRATE (AS N)	Report units:	MG/L
Dlr:	0.4		
Sample date:	31-MAY-16	Finding:	0.191
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	31-MAY-16	Finding:	1.49
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	37.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	200.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	230.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	190.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		

Sample date:	20-MAY-15	Finding:	7.4
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	410.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	27.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	9.3
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	17.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	20-MAY-15	Finding:	260.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	8.4
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	20-MAY-15	Finding:	12.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		
Sample date:	20-MAY-15	Finding:	7.8
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	05-MAY-14	Finding:	420.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	05-MAY-14	Finding:	9.4
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	07-APR-14	Finding:	9.2
Chemical:	NITRATE (AS NO3)	Report units:	MG/L
Dlr:	2.		
Sample date:	21-MAY-12	Finding:	18.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	21-MAY-12	Finding:	9.1
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	10.
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	31.
Chemical:	MAGNESIUM	Report units:	MG/L

Dlr:	0.		
Sample date:	21-MAY-12	Finding:	40.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	230.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	240.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	190.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	7.
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	450.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	21-MAY-12	Finding:	7.2
Chemical:	ZINC	Report units:	UG/L
Dlr:	50.		
Sample date:	21-MAY-12	Finding:	300.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		

C20
SE
1/4 - 1/2 Mile
Lower

CA WELLS 6390

Seq:	6390	Prim sta c:	05S/18E-15J05 M
Frds no:	2210001006	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL 05 (STILL GREENAMYERS) - INACTIVE		
Station ty:	WELL/AMBNT/MUN/INTAKE	Latitude:	372944.0
Longitude:	1195846.0	Precision:	3
Status:	IU	Comment 1:	AT IDLE WHEELS MHP, 5277 HWY 49 N, MARIPO
Comment 2:	Not Reported	Comment 3:	Not Reported
Comment 4:	Not Reported	Comment 5:	Not Reported
Comment 6:	Not Reported	Comment 7:	Not Reported
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

C21
SE
1/4 - 1/2 Mile
Lower

CA WELLS **6389**

Seq:	6389	Prim sta c:	05S/18E-15J04 M
Frds no:	2210001010	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL IW 04 - HOWARD	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372944.0	Longitude:	1195846.0
Precision:	3	Status:	AR
Comment 1:	AT IDLE WHEELS MHP, 2577 HWY 49 N, MARIPOSA.		
Comment 2:	Not Reported	Comment 3:	Not Reported
Comment 4:	Not Reported	Comment 5:	Not Reported
Comment 6:	Not Reported	Comment 7:	Not Reported
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

22
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CADDW2000009472**

GAMA:

Well ID:	CA2210001_007_007	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-007
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_007_007&store_num=		
GeoTracker Data:	Not Reported		

D23
East
1/4 - 1/2 Mile
Higher

CA WELLS **6385**

Seq:	6385	Prim sta c:	05S/18E-14E04 M
Frds no:	2210001014	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL 04	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372959.0	Longitude:	1195832.0
Precision:	3	Status:	AU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported

Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

C24
SE
1/4 - 1/2 Mile
Lower

CA WELLS **CADDW2000009445**

GAMA:

Well ID:	CA2210001_018_018	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-018
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_018_018&store_num=		
GeoTracker Data:	Not Reported		

D25
East
1/2 - 1 Mile
Higher

CA WELLS **CADDW2000023004**

GAMA:

Well ID:	CA2210001_014_014	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-014
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_014_014&store_num=		
GeoTracker Data:	Not Reported		

E26
ESE
1/2 - 1 Mile
Higher

CA WELLS **6082**

Seq:	6082	Prim sta c:	05S/08E-14E03 M
Frds no:	2210001004	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL 03	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372955.0	Longitude:	1195825.0
Precision:	2	Status:	AU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

E27
East
1/2 - 1 Mile
Higher

CA WELLS **6080**

Seq:	6080	Prim sta c:	05S/08E-14E01 M
Frds no:	2210001002	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL 01 - ABANDONED	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372958.0	Longitude:	1195823.0
Precision:	2	Status:	AB
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

E28
ESE
1/2 - 1 Mile
Higher

CA WELLS **CADDW2000019108**

GAMA:

Well ID:	CA2210001_004_004	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-004
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_004_004&store_num=		
GeoTracker Data:	Not Reported		

E29
East
1/2 - 1 Mile
Higher

CA WELLS **6081**

Seq:	6081	Prim sta c:	05S/08E-14E02 M
Frds no:	2210001003	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL 02 - ABANDONED	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372956.0	Longitude:	1195823.0
Precision:	2	Status:	AB
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported

Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

F30
East
1/2 - 1 Mile
Higher

CA WELLS **CADDW2000001408**

GAMA:

Well ID:	CA2210001_002_002	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-002
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_002_002&store_num=		
GeoTracker Data:	Not Reported		

F31
East
1/2 - 1 Mile
Higher

CA WELLS **CADDW2000009066**

GAMA:

Well ID:	CA2210001_003_003	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-003
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_003_003&store_num=		
GeoTracker Data:	Not Reported		

G32
SSE
1/2 - 1 Mile
Lower

CA WELLS **6387**

Seq:	6387	Prim sta c:	05S/18E-15J02 M
Frds no:	2210001017	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL IW 02 (STILL GREENAMYERS)-INACTIVE		
Station ty:	WELL/AMBNT/MUN/INTAKE	Latitude:	372924.0
Longitude:	1195846.0	Precision:	3
Status:	IR	Comment 1:	AT IDLE WHEELS MHP, 5277 HWY 49 N, MARIPO
Comment 2:	Not Reported	Comment 3:	Not Reported
Comment 4:	Not Reported	Comment 5:	Not Reported
Comment 6:	Not Reported	Comment 7:	Not Reported
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

G33
SSE
1/2 - 1 Mile
Lower

CA WELLS **CADDW2000000864**

GAMA:

Well ID:	CA2210001_017_017	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-017
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_017_017&store_num=		
GeoTracker Data:	Not Reported		

34
NNW
1/2 - 1 Mile
Higher

CA WELLS **16063**

Seq:	16063	Prim sta c:	2610001-015
Frds no:	2610001015	County:	26
District:	13	User id:	TAN
System no:	2610001	Water type:	G
Source nam:	WELL 15	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	373040.0	Longitude:	1195920.0
Precision:	3	Status:	AR
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	2610001	System nam:	Mammoth Cwd
Hqname:	Not Reported	Address:	P.O. BOX 597
City:	MAMMOTH LAKES	State:	CA
Zip:	93546	Zip ext:	Not Reported
Pop serv:	5000	Connection:	3103
Area serve:	MAMMOTH LAKES		

Sample date:	06-MAR-18	Finding:	9.1
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		

Sample date:	01-FEB-18	Finding:	9.
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		

Sample date:	09-JAN-18	Finding:	9.2
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		

Sample date:	12-DEC-17	Finding:	49.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		

Sample date:	12-DEC-17	Finding:	0.48
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		

Sample date:	12-DEC-17	Finding:	9.4

Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	07-NOV-17	Finding:	9.2
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	10-OCT-17	Finding:	7.5
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	12-SEP-17	Finding:	0.46
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	12-SEP-17	Finding:	49.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	12-SEP-17	Finding:	8.8
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	11-JUL-17	Finding:	9.7
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	15-JUN-17	Finding:	50.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	15-JUN-17	Finding:	0.46
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	15-JUN-17	Finding:	8.3
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	10-MAY-17	Finding:	9.3
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	12-APR-17	Finding:	9.3
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	09-MAR-17	Finding:	7.9
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	09-MAR-17	Finding:	53.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	09-MAR-17	Finding:	0.45
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	18-JAN-17	Finding:	9.6
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		

Sample date:	15-DEC-16	Finding:	0.54
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	15-DEC-16	Finding:	52.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	15-DEC-16	Finding:	7.8
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	01-NOV-16	Finding:	8.3
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	06-OCT-16	Finding:	8.4
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	08-SEP-16	Finding:	0.55
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	08-SEP-16	Finding:	52.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	08-SEP-16	Finding:	7.2
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	08-SEP-16	Finding:	150.
Chemical:	IRON	Report units:	UG/L
Dlr:	100.		
Sample date:	11-AUG-16	Finding:	19.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	170.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	0.4
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)	Report units:	MG/L
Dlr:	0.1		
Sample date:	11-AUG-16	Finding:	7.6
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	11-AUG-16	Finding:	1.3
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	4.2
Chemical:	POTASSIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	21.
Chemical:	SODIUM	Report units:	MG/L

Dlr:	0.		
Sample date:	11-AUG-16	Finding:	4.6
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	88.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	250.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	7.6
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	120.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	11-AUG-16	Finding:	150.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	28-JUL-16	Finding:	9.3
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	23-JUN-16	Finding:	0.49
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	23-JUN-16	Finding:	9.1
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	23-JUN-16	Finding:	56.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	19-MAY-16	Finding:	9.7
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	15-MAR-16	Finding:	0.58
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	15-MAR-16	Finding:	59.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	10-DEC-15	Finding:	58.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	10-DEC-15	Finding:	0.62
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		

Sample date:	10-SEP-15	Finding:	59.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	10-SEP-15	Finding:	0.62
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	11-JUN-15	Finding:	0.5
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	11-JUN-15	Finding:	58.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	09-APR-15	Finding:	8.3
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	12-MAR-15	Finding:	7.6
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	12-MAR-15	Finding:	56.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	12-MAR-15	Finding:	0.58
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	10-SEP-14	Finding:	1.04
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	10-SEP-14	Finding:	1.29
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	13-MAY-14	Finding:	45.6
Chemical:	TRITIUM	Report units:	PCI/L
Dlr:	1000.		
Sample date:	13-MAY-14	Finding:	264.
Chemical:	TRITIUM COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	13-MAY-14	Finding:	434.
Chemical:	TRITIUM MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	27-MAR-14	Finding:	9.3
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	19-FEB-14	Finding:	54.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	18-DEC-13	Finding:	0.5
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L

Dlr:	0.		
Sample date:	18-DEC-13	Finding:	49.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	18-DEC-13	Finding:	7.
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	13-NOV-13	Finding:	8.1
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		
Sample date:	11-SEP-13	Finding:	0.52
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	11-SEP-13	Finding:	57.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	0.4
Chemical:	FLUORIDE (F) (NATURAL-SOURCE)	Report units:	MG/L
Dlr:	0.1		
Sample date:	28-AUG-13	Finding:	320.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	7.6
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	160.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	190.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	110.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	5.7
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	22.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	28.
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	5.
Chemical:	POTASSIUM	Report units:	MG/L
Dlr:	0.		

Sample date:	28-AUG-13	Finding:	2.1
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	28-AUG-13	Finding:	14.
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	28-AUG-13	Finding:	230.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	11-JUL-13	Finding:	57.
Chemical:	SILICA	Report units:	MG/L
Dlr:	0.		
Sample date:	11-JUL-13	Finding:	0.52
Chemical:	PHOSPHATE (AS PO4)	Report units:	UG/L
Dlr:	0.		
Sample date:	13-JUN-13	Finding:	120.
Chemical:	IRON	Report units:	UG/L
Dlr:	100.		
Sample date:	11-DEC-12	Finding:	9.6
Chemical:	ARSENIC	Report units:	UG/L
Dlr:	2.		

H35
SSE **CA WELLS 6394**
1/2 - 1 Mile
Lower

Seq:	6394	Prim sta c:	05S/18E-23D02 M
Frds no:	2210001016	County:	22
District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	MPUD 05 - INACTIVE	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372924.0	Longitude:	1195836.0
Precision:	3	Status:	IU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		
System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		
Sample date:	31-MAY-16	Finding:	1.49
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	31-MAY-16	Finding:	0.191
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	24-NOV-15	Finding:	340.

Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	12-AUG-15	Finding:	0.156
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	12-AUG-15	Finding:	0.392
Chemical:	RADIUM 228 COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	12-AUG-15	Finding:	0.324
Chemical:	RADIUM 226 COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	12-AUG-15	Finding:	1.52
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	5.5e-002
Chemical:	GROSS ALPHA COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	190.
Chemical:	TOTAL DISSOLVED SOLIDS	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	0.12
Chemical:	TURBIDITY, LABORATORY	Report units:	NTU
Dlr:	0.1		
Sample date:	13-MAY-15	Finding:	12.
Chemical:	AGGRSSIVE INDEX (CORROSIVITY)	Report units:	Not Reported
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	2.22
Chemical:	GROSS ALPHA MDA95	Report units:	PCI/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	4.5
Chemical:	SULFATE	Report units:	MG/L
Dlr:	0.5		
Sample date:	13-MAY-15	Finding:	2.
Chemical:	CHLORIDE	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	7.8
Chemical:	SODIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	22.
Chemical:	MAGNESIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	34.
Chemical:	CALCIUM	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	180.
Chemical:	HARDNESS (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		

Sample date:	13-MAY-15	Finding:	210.
Chemical:	BICARBONATE ALKALINITY	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	170.
Chemical:	ALKALINITY (TOTAL) AS CACO3	Report units:	MG/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	7.5
Chemical:	PH, LABORATORY	Report units:	Not Reported
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	340.
Chemical:	SPECIFIC CONDUCTANCE	Report units:	US
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	0.235
Chemical:	RADIUM 226 COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		
Sample date:	13-MAY-15	Finding:	0.359
Chemical:	RADIUM 228 COUNTING ERROR	Report units:	PCI/L
Dlr:	0.		

H36
SSE
1/2 - 1 Mile
Lower

CA WELLS **CADDW2000008636**

GAMA:

Well ID:	CA2210001_016_016	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210001-016
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210001_016_016&store_num=		
GeoTracker Data:	Not Reported		

37
WNW
1/2 - 1 Mile
Higher

CA WELLS **CADDW2000020313**

GAMA:

Well ID:	CA2210942_002_002	Well Type:	MUNICIPAL
Source:	DDW	Other Names:	2210942-002
GAMA Pfas testing:	Not Reported		
Groundwater Quality Data:	https://gamagroundwater.waterboards.ca.gov/gama/gamamap/public/GamaDataDisplay.asp?dataset=DHS&samp_date=&global_id=&assigned_name=CA2210942_002_002&store_num=		
GeoTracker Data:	Not Reported		

38
SE
1/2 - 1 Mile
Lower

CA WELLS **6393**

Seq:	6393	Prim sta c:	05S/18E-23D01 M
Frds no:	2210001011	County:	22

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

District:	11	User id:	AGE
System no:	2210001	Water type:	G
Source nam:	WELL IW 05 - INACTIVE	Station ty:	WELL/AMBNT/MUN/INTAKE
Latitude:	372921.0	Longitude:	1195824.0
Precision:	3	Status:	IU
Comment 1:	Not Reported	Comment 2:	Not Reported
Comment 3:	Not Reported	Comment 4:	Not Reported
Comment 5:	Not Reported	Comment 6:	Not Reported
Comment 7:	Not Reported		

System no:	2210001	System nam:	Mariposa Pud
Hqname:	Not Reported	Address:	P O BOX 494
City:	MARIPOSA	State:	Not Reported
Zip:	95338	Zip ext:	Not Reported
Pop serv:	2000	Connection:	449
Area serve:	IDLE WHEELS MHP		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: CA Radon

Radon Test Results

Zipcode	Num Tests	> 4 pCi/L
95338	26	1

Federal EPA Radon Zone for MARIPOSA County: 2

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 95338

Number of sites tested: 7

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	1.000 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetland Inventory
Source: Department of Fish and Wildlife
Telephone: 916-445-0411

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

OTHER STATE DATABASE INFORMATION

Groundwater Ambient Monitoring & Assessment Program
State Water Resources Control Board
Telephone: 916-341-5577
The GAMA Program is Californias comprehensive groundwater quality monitoring program. GAMA collects data by testing the untreated, raw water in different types of wells for naturally-occurring and man-made chemicals. The GAMA data includes Domestic, Monitoring and Municipal well types from the following sources, Department of Water Resources, Department of Heath Services, EDF, Agricultural Lands, Lawrence Livermore National Laboratory, Department of Pesticide Regulation, United States Geological Survey, Groundwater Ambient Monitoring and Assessment Program and Local Groundwater Projects.

Water Well Database
Source: Department of Water Resources
Telephone: 916-651-9648

California Drinking Water Quality Database
Source: Department of Public Health
Telephone: 916-324-2319
The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

California Oil and Gas Well Locations
Source: Dept of Conservation, Geologic Energy Management Division
Telephone: 916-323-1779
Oil and Gas well locations in the state.

Orphan Well Prioritization Listing
California Department of Conservation
Telephone: 916-445-9686
Includes locations of wells included in the California State Well Plugging and Sealing Project, managed by CalGEM (California Geologic Energy Management Division).

Geothermal Wells Listing
Department of Conservation
Telephone: 916-445-9686
Geothermal well means a well constructed to extract or return water to the ground after it has been used for heating or cooling purposes. Geothermal wells in California (except for wells on federal leases which are administered by the Bureau of Land Management) are permitted, drilled, operated, and permanently sealed and closed (plugged and abandoned) under requirements and procedures administered by the Geothermal Section of the Department of Conservations Geologic Energy Management Division (CalGEM, formerly DOGGR).

PHYSICAL SETTING SOURCE RECORDS SEARCHED

California Earthquake Fault Lines
Source: California Division of Mines and Geology
The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

RADON

State Database: CA Radon
Source: Department of Public Health
Telephone: 916-210-8558
Radon Database for California

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

California Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338

Inquiry Number: 8280255.2s
April 7, 2026

EDR Vapor Encroachment Screen

Prepared using EDR's Vapor Encroachment Worksheet

EDR® Environmental Data Resources Inc

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	**ES1**
Primary Map	**2**
Secondary Map	**3**
Map Findings	**4**
Record Sources and Currency	**GR-1**

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

The EDR Vapor Encroachment Worksheet enables EDR's customers to make certain online modifications that effects maps, text and calculations contained in this Report. As a result, maps, text and calculations contained in this Report may have been so modified. EDR has not taken any action to verify any such modifications, and this report and the findings set forth herein must be read in light of this fact. Environmental Data Resources shall not be responsible for any customer's decision to include or not include in any final report any records determined to be within the relevant minimum search distances.

This report contains information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANYSUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this report "AS IS". Any analyses, estimates, ratings, or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can produce information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2026 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by EDR. The report was designed to assist parties seeking to meet the search requirements of the ASTM Standard Practice for Assessment of Vapor Encroachment into Structures on Property Involved in Real Estate Transactions (E 2600).

STANDARD ENVIRONMENTAL RECORDS	Default Area of Concern (Miles)*	property	1/10	> 1/10
Lists of Federal NPL (Superfund) sites	1.0	0	0	0
Lists of Federal Delisted NPL sites	1.0	0	0	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders	0.5	0	0	0
Lists of Federal CERCLA sites with NFRAP	0.5	0	0	0
Lists of Federal RCRA facilities undergoing Corrective Action	1.0	0	0	0
Lists of Federal RCRA TSD facilities	0.5	0	0	0
Lists of Federal RCRA generators	0.25	0	0	0
Federal institutional controls / engineering controls registries	0.5	0	0	0
Federal ERNS list	property	0	-	-
Lists of state- and tribal (Superfund) equivalent sites	1.0	0	0	0
Lists of state- and tribal hazardous waste facilities	1.0	0	0	0
Lists of state and tribal landfills and solid waste disposal facilities	0.5	0	0	0
Lists of state and tribal leaking storage tanks	0.5	0	0	1
Lists of state and tribal registered storage tanks	0.25	0	0	0
State and tribal institutional control / engineering control registries	not searched	-	-	-
Lists of state and tribal voluntary cleanup sites	0.5	0	0	0
Lists of state and tribal brownfield sites	0.5	0	0	0

ADDITIONAL ENVIRONMENTAL RECORDS				
Local Brownfield lists	0.5	0	0	0
Local Lists of Landfill / Solid Waste Disposal Sites	0.5	0	0	0
Local Lists of Hazardous waste / Contaminated Sites	1.0	0	0	1
Local Lists of Registered Storage Tanks	0.25	0	0	1
Local Land Records	0.5	0	0	0
Records of Emergency Release Reports	0.5	0	0	0
Other Ascertainable Records	1.0	0	0	7

EDR HIGH RISK HISTORICAL RECORDS				
EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	property	0	-	-

EXECUTIVE SUMMARY

EDR RECOVERED GOVERNMENT ARCHIVES

EDR Exclusive Records	1.0	0	0	0
Exclusive Recovered Govt. Archives	property	0	-	-

*The Default Area of Concern may be adjusted by the environmental professional using experience and professional judgement. Each category may include several databases, and each database may have a different distance. A list of individual databases is provided at the back of this report.

EXECUTIVE SUMMARY

TARGET PROPERTY INFORMATION

ADDRESS

MARIPOSA COUNTY
FRANK WILSON RD
MARIPOSA, CA 95338

COORDINATES

Latitude (North):	37.500486 - 37° 30′ 1.7440796″
Longitude (West):	119.984698 - 119° 59′ 4.9035645″
Elevation:	2139 ft. above sea level

EXECUTIVE SUMMARY

SEARCH RESULTS

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
CDF MARIPOSA Cortese: CORTESE EMI: EMI CERS: CERS LUST: LUST	5366 HIGHWAY 49 N	1/10 - 1/3 NW	▲ A1	8

ADDITIONAL ENVIRONMENTAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
CDF MARIPOSA Cortese: CORTESE EMI: EMI CERS: CERS LUST: LUST	5366 HIGHWAY 49 N	1/10 - 1/3 NW	▲ A1	8
MARIPOSA RANGER UNIT HEAD HIST CORTESE: HIST CORTESE	5366 49	1/10 - 1/3 NW	▲ A2	29
DEPT OF FORESTRY & FIRE E MANIFEST: E MANIFEST	5366 STATE HIGHWAY 49 N	1/10 - 1/3 NW	▲ A3	30
MARIPOSA RANGER UNIT HEADQUARTERS UST FINDER RELEASE: UST FINDER RELEASE	5366 HIGHWAY 49 N	1/10 - 1/3 NW	▲ A4	32
CDF MARIPOSA STATION E MANIFEST: E MANIFEST	5366 STATE HIGHWAY 49 N	1/10 - 1/3 NW	▲ A5	33
CAL-FIRE E MANIFEST: E MANIFEST	5366 HWY. 49 N.	1/10 - 1/3 NW	▲ A6	35
CAL FIRE MARIPOSA CERS TANKS: CERS TANKS CERS HAZ WASTE: CERS HAZ WASTE CERS: CERS	5366 STATE HIGHWAY 49 N	1/10 - 1/3 NW	▲ A7	37


EDR HIGH RISK HISTORICAL RECORDS

Name	Address	Dist/Dir	Map ID	Page
Not Reported				

EDR RECOVERED GOVERNMENT ARCHIVES

Name	Address	Dist/Dir	Map ID	Page
Not Reported				

PRIMARY MAP - 8280255.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Mariposa County	CLIENT:	Provost & Pritchard Eng. Group
ADDRESS:	Frank Wilson Rd Mariposa CA 95338	CONTACT:	Stephanie Gillaspy
		INQUIRY #:	8280255.2s
LAT/LONG:	37.500486 / 119.984698	DATE:	March 12, 2026 7:24 pm

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

SECONDARY MAP - 8280255.2S



0 1/3 1/2 1 Miles

- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands
- Upgradient Area
- Areas of Concern

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Mariposa County	CLIENT:	Provost & Pritchard Eng. Group
ADDRESS:	Frank Wilson Rd Mariposa CA 95338	CONTACT:	Stephanie Gillaspy
		INQUIRY #:	8280255.2s
LAT/LONG:	37.500486 / 119.984698	DATE:	March 12, 2026 7:16 pm

Copyright © 2026 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS

LEGEND

FACILITY NAME **FACILITY ADDRESS, CITY, ST, ZIP**		EDR SITE ID NUMBER
◆ **MAP ID#**	Direction Distance Range (Distance feet / miles) Relative Elevation Feet Above Sea Level	ASTM 2600 Record Sources found in this report. Each database searched has been assigned to one or more categories. For detailed information about categorization, see the section of the report Records Searched and Currency.

Worksheet:

Comments:
Comments may be added on the online Vapor Encroachment Worksheet.

DATABASE ACRONYM: Applicable categories (A hoverbox with database description).

CDF MARIPOSA 5366 HIGHWAY 49 N, MARIPOSA, CA, 95338			S105033936
▲ A1	NW 1/10 - 1/3	(788 ft. / 0.149 mi.)	Lists of state and tribal leaking storage tanks Other Ascertainable Records
	56 ft. Higher Elevation	2195 ft. Above Sea Level	

Worksheet:

LUST: Lists of state and tribal leaking storage tanks

Name:	MARIPOSA RANGER UNIT HEADQUARTERS
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Lead Agency:	CENTRAL VALLEY RWQCB (REGION 5S)
Case Type:	LUST Cleanup Site
Geo Track:	http://geotracker.waterboards.ca.gov/profile_report.asp?global_id=T0604300083
Global Id:	T0604300083
Latitude:	37.500712521403
Longitude:	-119.986474514008
Status:	Completed - Case Closed
Status Date:	12/30/2019
Case Worker:	BJL
RB Case Number:	5T22000127
Local Agency:	MARIPOSA COUNTY
File Location:	Regional Board
Local Case Number:	Not Reported
Potential Media Affect:	Aquifer used for drinking water supply
Potential Contaminants of Concern:	Diesel
EPA Region:	9
Coordinate Source:	Manual Entry on Screens
Cuf Case:	Not Reported
Quantity Released Gallons:	Not Reported
Begin Date:	Not Reported
Leak Reported Date:	Not Reported

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

How Discovered:	Not Reported
How Discovered Description:	Not Reported
Discharge Source:	Not Reported
Discharge Cause:	Not Reported
Stop Method:	Not Reported
Stop Description:	Not Reported
No Further Action Date:	Not Reported
CA Water Watershed Name:	Not Reported
Dwr Groundwater Subbasin Name:	Not Reported
Disadvantaged Community:	Not Reported
CA Enviroscreen 3 Score:	Not Reported
CA Enviroscreen 4 Score:	Not Reported
Military DOD Site:	Not Reported
Facility Project Subtype:	Not Reported
RWQCB Region:	Not Reported
Site History:	The case was opened following an unauthorized release from an underground storage tank system at the subject site. Corrective action is underway as directed by the CVRWQCB. Corrective action may consist of preliminary site investigation, planning and implementation of remedial action, verification monitoring, or a combination thereof. A summary of the site history is available by clicking on either the

LUST:

Global Id:	T0604300083
Contact Type:	Regional Board Caseworker - Primary Caseworker
Contact Name:	BENJAMIN LEHMANN
Organization Name:	CENTRAL VALLEY RWQCB (REGION 5S)
Address:	11020 Sun Center Drive #200
City:	RANCHO CORDOVA
Email:	benjamin.lehmann@waterboards.ca.gov
Phone Number:	9164644760

Global Id:	T0604300083
Contact Type:	Local Agency Caseworker
Contact Name:	KERRI GIBBONS
Organization Name:	MARIPOSA COUNTY
Address:	Not Reported
City:	r5 UNKNOWN
Email:	Not Reported
Phone Number:	Not Reported

LUST:

Global Id:	T0604300083
Action Type:	Other
Date:	03/02/2000
Action:	Leak Discovery

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Action Type:	RESPONSE
Date:	04/30/2004
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	01/30/2006
Action:	Corrective Action Plan / Remedial Action Plan
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	03/15/2004
Action:	Other Report / Document
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	12/19/2013
Action:	Removal Action Complete
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	04/07/2003
Action:	Staff Letter - #5-01-712
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	09/24/2003
Action:	* Verbal Communication
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	09/26/2003
Action:	Site Visit / Inspection / Sampling
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	05/25/2018
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	09/17/2019
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	12/30/2019
Action:	Closure/No Further Action Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	03/28/2019
Action:	Staff Letter

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Action Type:	RESPONSE
Date:	12/30/2003
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	01/03/2003
Action:	Corrective Action Plan / Remedial Action Plan
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	02/19/2003
Action:	Preliminary Site Assessment Report
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	11/01/2010
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	07/30/2013
Action:	Monitoring Report - Semi-Annually
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	06/30/2013
Action:	Other Report / Document
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	09/06/2013
Action:	Remedial Progress Report
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	02/01/2011
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	10/10/2002
Action:	Staff Letter - #5-01-712
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	12/19/2002
Action:	Staff Letter - #5-01-712
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	07/30/2002
Action:	Staff Letter - #5-01-712

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	01/07/2014
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	01/27/2015
Action:	Email Correspondence
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	03/14/2014
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	07/31/2015
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	05/27/2014
Action:	Email Correspondence
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	12/07/2018
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	01/27/2016
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	04/11/2017
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	05/25/2018
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	01/19/2018
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	Other
Date:	03/09/2000
Action:	Leak Reported

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Action Type:	RESPONSE
Date:	11/01/2009
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	01/03/2003
Action:	Corrective Action Plan / Remedial Action Plan
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	02/27/2003
Action:	Other Workplan
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	12/08/2006
Action:	Corrective Action Plan / Remedial Action Plan
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	08/01/2010
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	02/15/2017
Action:	Request for Closure - Regulator Responded
Global Id:	T0604300083
Action Type:	REMEDIATION
Date:	10/07/2013
Action:	Excavation
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	06/06/2007
Action:	Verbal Communication
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	03/25/2010
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	03/26/2010
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	05/06/2010
Action:	Staff Letter

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	02/24/2011
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	05/19/2011
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	12/08/2010
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	09/03/2010
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	08/16/2011
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	06/03/2013
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	03/13/2013
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	03/17/2003
Action:	Pilot Study / Treatability Workplan
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	02/01/2010
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	01/16/2006
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	01/31/2006
Action:	Corrective Action Plan / Remedial Action Plan

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Action Type:	RESPONSE
Date:	12/15/2005
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	12/08/2005
Action:	Other Report / Document
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	11/21/2005
Action:	Other Workplan
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	08/01/2012
Action:	Monitoring Report - Semi-Annually - Regulator Responded
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	02/01/2013
Action:	Monitoring Report - Semi-Annually - Regulator Responded
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	05/07/2012
Action:	Corrective Action Plan / Remedial Action Plan - Regulator Responded
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	04/15/2013
Action:	Corrective Action Plan / Remedial Action Plan - Addendum - Regulator Responded
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	12/26/2014
Action:	Well Installation Workplan - Regulator Responded
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	10/21/2005
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	10/26/2006
Action:	Verbal Communication
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	05/17/2006
Action:	Verbal Communication

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	11/18/2005
Action:	13267 Requirement
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	11/01/2006
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	04/03/2006
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	08/28/2007
Action:	Verbal Communication
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	04/29/2009
Action:	Verbal Enforcement
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	01/29/2003
Action:	Staff Letter - #5-01-712
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	01/25/2008
Action:	Verbal Communication
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	12/24/2008
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	09/15/2009
Action:	Technical Correspondence / Assistance / Other
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	11/25/2009
Action:	Staff Letter
Global Id:	T0604300083
Action Type:	Other
Date:	03/02/2000
Action:	Leak Stopped

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Action Type:	RESPONSE
Date:	05/01/2010
Action:	Monitoring Report - Quarterly
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	06/30/2003
Action:	Soil and Water Investigation Report
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	02/14/2011
Action:	CAP/RAP - Feasibility Study Report - Regulator Responded
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	05/01/2011
Action:	Monitoring Report - Quarterly - Regulator Responded
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	08/01/2011
Action:	Monitoring Report - Quarterly - Regulator Responded
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	12/01/2011
Action:	Monitoring Report - Semi-Annually - Regulator Responded
Global Id:	T0604300083
Action Type:	RESPONSE
Date:	02/05/2019
Action:	Request for Closure - Regulator Responded
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	09/25/2002
Action:	Meeting
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	01/13/2003
Action:	Meeting
Global Id:	T0604300083
Action Type:	ENFORCEMENT
Date:	02/17/2004
Action:	Staff Letter

LUST:

Global Id:	T0604300083
Status:	Open - Case Begin Date
Status Date:	03/02/2000

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Global Id:	T0604300083
Status:	Open - Site Assessment
Status Date:	03/09/2000
Global Id:	T0604300083
Status:	Open - Site Assessment
Status Date:	07/19/2001
Global Id:	T0604300083
Status:	Open - Site Assessment
Status Date:	10/18/2001
Global Id:	T0604300083
Status:	Open - Remediation
Status Date:	12/12/2002
Global Id:	T0604300083
Status:	Open - Remediation
Status Date:	02/21/2003
Global Id:	T0604300083
Status:	Open - Remediation
Status Date:	01/30/2006
Global Id:	T0604300083
Status:	Open - Verification Monitoring
Status Date:	01/27/2016
Global Id:	T0604300083
Status:	Open - Eligible for Closure
Status Date:	09/17/2019
Global Id:	T0604300083
Status:	Completed - Case Closed
Status Date:	12/30/2019

LUST REG 5:

Name:	MARIPOSA RANGER UNIT HEADQUARTERS
Address:	5366 HIGHWAY 49 N
City:	MARIPOSA
Region:	5
Status:	Remediation Plan
Case Number:	5T22000127
Case Type:	Drinking Water Aquifer affected
Substance:	DIESEL
Staff Initials:	WWG
Lead Agency:	Regional
Program:	LUST
MTBE Code:	6

CORTESE: Other Ascertainable Records

Name:	MARIPOSA RANGER UNIT HEADQUARTERS

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Region:	CORTESE
Envirostor Id:	Not Reported
Global ID:	T0604300083
Site/Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Status Date:	Not Reported
Site Code:	Not Reported
Latitude:	Not Reported
Longitude:	Not Reported
Owner:	Not Reported
Enf Type:	Not Reported
Swat R:	Not Reported
Flag:	active
Order No:	Not Reported
Waste Discharge System No:	Not Reported
Effective Date:	Not Reported
Region 2:	Not Reported
WID Id:	Not Reported
Solid Waste Id No:	Not Reported
Waste Management Uit Name:	Not Reported
File Name:	Active Open

EMI: Other Ascertainable Records

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 953380000
Year:	2002
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

City,State,Zip:	MARIPOSA, CA 953380000
Year:	2003
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 953380000
Year:	2004
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 953380000
Year:	2005
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 953380000
Year:	2006
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95691
Year:	2007
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2008
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2009
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2010
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2011
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0
Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

City,State,Zip:	MARIPOSA, CA 95338
Year:	2012
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2013
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2014
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2015
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers and Smllr Tons/Yr:	0

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2016
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not Reported
NOX - Oxides of Nitrogen Tons/Yr:	Not Reported
SOX - Oxides of Sulphur Tons/Yr:	Not Reported
Particulate Matter Tons/Yr:	Not Reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not Reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2017
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not Reported
NOX - Oxides of Nitrogen Tons/Yr:	Not Reported
SOX - Oxides of Sulphur Tons/Yr:	Not Reported
Particulate Matter Tons/Yr:	Not Reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not Reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2018
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not Reported
NOX - Oxides of Nitrogen Tons/Yr:	Not Reported
SOX - Oxides of Sulphur Tons/Yr:	Not Reported

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Particulate Matter Tons/Yr:	Not Reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not Reported
Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2019
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not Reported
NOX - Oxides of Nitrogen Tons/Yr:	Not Reported
SOX - Oxides of Sulphur Tons/Yr:	Not Reported
Particulate Matter Tons/Yr:	Not Reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not Reported
Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2020
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not Reported
NOX - Oxides of Nitrogen Tons/Yr:	Not Reported
SOX - Oxides of Sulphur Tons/Yr:	Not Reported
Particulate Matter Tons/Yr:	Not Reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not Reported
Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

City,State,Zip:	MARIPOSA, CA 95338
Year:	2021
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not Reported
NOX - Oxides of Nitrogen Tons/Yr:	Not Reported
SOX - Oxides of Sulphur Tons/Yr:	Not Reported
Particulate Matter Tons/Yr:	Not Reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not Reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2022
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA
SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	Not Reported
NOX - Oxides of Nitrogen Tons/Yr:	Not Reported
SOX - Oxides of Sulphur Tons/Yr:	Not Reported
Particulate Matter Tons/Yr:	Not Reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not Reported

Name:	CDF MARIPOSA
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Year:	2023
County Code:	22
Air Basin:	MC
Facility ID:	28
Air District Name:	MPA

CDF MARIPOSA, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

SIC Code:	851
Air District Name:	MARIPOSA COUNTY APCD
Community Health Air Pollution Info System:	Not Reported
Consolidated Emission Reporting Rule:	Not Reported
Total Organic Hydrocarbon Gases Tons/Yr:	0.35
Reactive Organic Gases Tons/Yr:	0.30975
Carbon Monoxide Emissions Tons/Yr:	Not Reported
NOX - Oxides of Nitrogen Tons/Yr:	Not Reported
SOX - Oxides of Sulphur Tons/Yr:	Not Reported
Particulate Matter Tons/Yr:	Not Reported
Part. Matter 10 Micrometers and Smllr Tons/Yr:	Not Reported

CERS: Other Ascertainable Records

Name:	MARIPOSA RANGER UNIT HEADQUARTERS
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Site ID:	862103
CERS ID:	T0604300083
CERS Description:	Leaking Underground Storage Tank Cleanup Site

Affiliation:

Affiliation Type Desc:	Regional Board Caseworker
Entity Name:	BENJAMIN LEHMANN - CENTRAL VALLEY RWQCB (REGION 5S)
Entity Title:	Not Reported
Affiliation Address:	11020 Sun Center Drive #200
Affiliation City:	RANCHO CORDOVA
Affiliation State:	CA
Affiliation Country:	Not Reported
Affiliation Zip:	Not Reported
Affiliation Phone:	9164644760,
Affiliation Type Desc:	Local Agency Caseworker
Entity Name:	KERRI GIBBONS - MARIPOSA COUNTY
Entity Title:	Not Reported
Affiliation Address:	Not Reported
Affiliation City:	r5 UNKNOWN
Affiliation State:	CA
Affiliation Country:	Not Reported
Affiliation Zip:	Not Reported
Affiliation Phone:	,

MARIPOSA RANGER UNIT HEAD 5366 49, MARIPOSA, CA, 95338			S105024876
▲ A2	NW 1/10 - 1/3	(788 ft. / 0.149 mi.)	Other Ascertainable Records
	56 ft. Higher Elevation	2195 ft. Above Sea Level	

Worksheet:

HIST CORTESE: Other Ascertainable Records

edr_fname:	MARIPOSA RANGER UNIT HEAD
edr_fadd1:	5366 49
City,State,Zip:	MARIPOSA, CA 95338
Region:	CORTESE
Facility County Code:	22
Reg By:	LTNKA
Reg Id:	5T22000127

DEPT OF FORESTRY & FIRE 5366 STATE HIGHWAY 49 N, MARIPOSA, CA, 95338-9503			1032005274
▲ A3	NW 1/10 - 1/3	(788 ft. / 0.149 mi.)	Other Ascertainable Records
	56 ft. Higher Elevation	2195 ft. Above Sea Level	

Worksheet:

E MANIFEST: Other Ascertainable Records

Manifest Tracking Number:	022517050JJK
Last Updated Date:	20210505
Shipped Date:	20210325
Received Date:	20210407
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CAL000059136
Generator Name:	Dept Of Forestry & Fire
Generator Location Street Number:	Not Reported
Generator Location Street 1:	5366 STATE HIGHWAY 49 N
Generator Location Street 2:	Not Reported
Generator Location City:	MARIPOSA
Generator Location State:	CA
Generator Location Zip:	95338-9503
Generator Mail Street Number:	Not Reported
Generator Mail Street 1:	5366 STATE HIGHWAY 49 N
Generator Mail Street 2:	Not Reported
Generator Mail City:	MARIPOSA
Generator Mail Zip:	95338-9503
Generator Mail State:	CA
Generator Contact Company Name:	Not Reported
Designated Facility EPA ID:	AZR000521146
Designated Facility Name:	Yuma Yes 2 Waste Transfer Station
Designated Facility Mail Street Number:	Not Reported
Designated Facility Mail Street 1:	STE 105
Designated Facility Mail Street 2:	2621 GREEN RIVER RD
Designated Facility Mail City:	CORONA
Designated Facility Mail Zip:	92882

DEPT OF FORESTRY & FIRE, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338-9503 (Continued)

Designated Facility Mail State:	CA
Designated Facility Location Street Number:	Not Reported
Designated Facility Location Street 1:	6500 S US HIGHWAY 95
Designated Facility Location Street 2:	Not Reported
Designated Facility Location City:	YUMA
Designated Facility Location Zip:	85365
Designated Facility Location State:	AZ
Designated Facility Contact Company Name:	Not Reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	022517050JJK
Transporter Line Number:	1
Transporter EPA ID:	CAR000272302
Transporter Name:	American Valley Waste Oil Inc

Manifest Tracking Number:	022517050JJK
Transporter Line Number:	2
Transporter EPA ID:	CAR000175422
Transporter Name:	Worldwide Recovery System Inc

Waste Line:

Manifest Tracking Number:	022517050JJK
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not Reported
U.S. DOT Description:	Not Reported
Non-Hazardous Waste Description:	Non-Rcra Hazardous Waste Solid (Absorbents, Paper Oil Filters & Debris)
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	180
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.09
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.09
Waste Quantity, in Kilograms:	81.632706
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	81.632706
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not Reported

DEPT OF FORESTRY & FIRE, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338-9503 (Continued)

Waste Density Unit of Measure Code:	Not Reported
Waste Density Unit of Measure Description:	Not Reported
Form Code:	Not Reported
Form Code Description:	Not Reported
Source Code:	Not Reported
Source Code Description:	Not Reported
Waste Minimization Code:	Not Reported
Waste Minimization Code Description:	Not Reported
Consent Number:	Not Reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not Reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	81.632706
Quantity Non Haz Tons:	0.09
State Waste Codes:	CA-352

MARIPOSA RANGER UNIT HEADQUARTERS
5366 HIGHWAY 49 N, MARIPOSA, CA, 95338 1029018516

▲ A4	NW 1/10 - 1/3	(788 ft. / 0.149 mi.)	Other Ascertainable Records
	56 ft. Higher Elevation	2195 ft. Above Sea Level	

Worksheet:

UST FINDER RELEASE: Other Ascertainable Records

Object ID:	54458
Facility ID:	Not Reported
Lust ID:	CAT0604300083
Name:	MARIPOSA RANGER UNIT HEADQUARTERS
Address:	5366 HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Address Match Type:	PointAddress
Reported Date:	Not Reported
Status:	No Further Action
Substance:	Not Reported
Population within 1500ft:	30
Domestic Wells within 1500ft:	6
Land Use:	Developed, Low Intensity
Within SPA:	No
SPA PWS Facility ID:	Not Reported
SPA Water Type:	Not Reported
SPA Facility Type:	Not Reported
SPA HUC12:	Not Reported
Within WHPA:	Yes
WHPA PWS Facility ID:	CA2210942_54742
WHPA Water Type:	GW - Ground water
WHPA Facility Type:	WL - Well

MARIPOSA RANGER UNIT HEADQUARTERS, 5366 HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

WHPA HUC12:	180400011502
Within 100yr Floodplain:	No
Tribe:	Not Reported
EPA Region:	9
NFA Letter 1:	Not Reported
NFA Letter 2:	Not Reported
NFA Letter 3:	Not Reported
NFA Letter 4:	Not Reported
Closed With Residual Contaminate:	Not Reported
Coordinate Source:	Geocode
X Coord:	-119.98815
Y Coord:	37.50174
Latitude:	37.5017399999999
Longitude:	-119.98815

CDF MARIPOSA STATION 5366 STATE HIGHWAY 49 N, MARIPOSA, CA, 95338			1031920989
▲ A5	NW 1/10 - 1/3	(788 ft. / 0.149 mi.)	Other Ascertainable Records
	56 ft. Higher Elevation	2195 ft. Above Sea Level	

Worksheet:

E MANIFEST: Other Ascertainable Records

Manifest Tracking Number:	006960234SKS
Last Updated Date:	20190827
Shipped Date:	20190711
Received Date:	20190730
Manifest Status:	Signed
Submission Type:	DataImage5Copy
Origin Type:	Service
Generator EPA ID:	CAL000059136
Generator Name:	Cdf Mariposa Station
Generator Location Street Number:	Not Reported
Generator Location Street 1:	5366 STATE HIGHWAY 49 N
Generator Location Street 2:	Not Reported
Generator Location City:	MARIPOSA
Generator Location State:	CA
Generator Location Zip:	95338
Generator Mail Street Number:	Not Reported
Generator Mail Street 1:	5366 State Highway 49 N
Generator Mail Street 2:	Not Reported
Generator Mail City:	Mariposa
Generator Mail Zip:	95338
Generator Mail State:	CA
Generator Contact Company Name:	Not Reported
Designated Facility EPA ID:	ORQ000025197
Designated Facility Name:	Thermo Fluids, Inc.

CDF MARIPOSA STATION, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Designated Facility Mail Street Number:	Not Reported
Designated Facility Mail Street 1:	Not Reported
Designated Facility Mail Street 2:	12533 SE Carpenter Drive
Designated Facility Mail City:	Clackamas
Designated Facility Mail Zip:	97015
Designated Facility Mail State:	OR
Designated Facility Location Street Number:	Not Reported
Designated Facility Location Street 1:	12533 SE Carpenter Drive
Designated Facility Location Street 2:	Not Reported
Designated Facility Location City:	Clackamas
Designated Facility Location Zip:	97015
Designated Facility Location State:	OR
Designated Facility Contact Company Name:	Not Reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	006960234SKS
Transporter Line Number:	1
Transporter EPA ID:	TXR000081205
Transporter Name:	Safety-Kleen Systems, Inc.
Manifest Tracking Number:	006960234SKS
Transporter Line Number:	2
Transporter EPA ID:	MAD039322250
Transporter Name:	Clean Harbors Environmental Services, Inc.
Manifest Tracking Number:	006960234SKS
Transporter Line Number:	3
Transporter EPA ID:	MOD095038998
Transporter Name:	Bed Rock Inc Dba Tri State Motor Transit Co

Waste Line:

Manifest Tracking Number:	006960234SKS
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	N
U.S. DOT ID Number:	Not Reported
U.S. DOT Description:	Not Reported
Non-Hazardous Waste Description:	None, Non-Rcra Hazardous Waste, Solid (Drained/Undrained Used Oil Filters), N/A, None
Number of Containers:	1
Container Type Code:	DM
Container Type Description:	Metal drums, barrels, kegs
Waste Quantity:	250
Quantity Unit of Measure Code:	P
Quantity Unit of Measure Description:	Pounds
Waste Quantity, in Tons:	0.125
Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.125

CDF MARIPOSA STATION, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Waste Quantity, in Kilograms:	113.37875
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	113.37875
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not Reported
Waste Density Unit of Measure Code:	Not Reported
Waste Density Unit of Measure Description:	Not Reported
Form Code:	Not Reported
Form Code Description:	Not Reported
Source Code:	Not Reported
Source Code Description:	Not Reported
Waste Minimization Code:	Not Reported
Waste Minimization Code Description:	Not Reported
Consent Number:	Not Reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not Reported
Quantity Haz Kg:	0
Quantity Haz Tons:	0
Quantity Non Haz Kg:	113.37875
Quantity Non Haz Tons:	0.125
State Waste Codes:	CA-223

CAL-FIRE
5366 HWY. 49 N., MARIPOSA, CA, 95338 1031910761

▲ A6	NW 1/10 - 1/3	(788 ft. / 0.149 mi.)	Other Ascertainable Records
	56 ft. Higher Elevation	2195 ft. Above Sea Level	

Worksheet:

E MANIFEST: Other Ascertainable Records

Manifest Tracking Number:	100093333ELC
Last Updated Date:	20240410
Shipped Date:	20240408
Received Date:	20240409
Manifest Status:	Signed
Submission Type:	FullElectronic
Origin Type:	Web
Generator EPA ID:	CAC003277030
Generator Name:	Cal-Fire
Generator Location Street Number:	Not Reported
Generator Location Street 1:	5366 HWY. 49 N.
Generator Location Street 2:	Not Reported
Generator Location City:	MARIPOSA

CAL-FIRE, 5366 HWY. 49 N., MARIPOSA, CA 95338 (Continued)

Generator Location State:	CA
Generator Location Zip:	95338
Generator Mail Street Number:	Not Reported
Generator Mail Street 1:	5366 HWY. 49 N.
Generator Mail Street 2:	Not Reported
Generator Mail City:	MARIPOSA
Generator Mail Zip:	95338
Generator Mail State:	CA
Generator Contact Company Name:	Not Reported
Designated Facility EPA ID:	CAD982042475
Designated Facility Name:	Recology Hay Road
Designated Facility Mail Street Number:	235
Designated Facility Mail Street 1:	Not Reported
Designated Facility Mail Street 2:	N FIRST ST
Designated Facility Mail City:	DIXON
Designated Facility Mail Zip:	95620
Designated Facility Mail State:	CA
Designated Facility Location Street Number:	6426
Designated Facility Location Street 1:	HAY RD
Designated Facility Location Street 2:	Not Reported
Designated Facility Location City:	VACAVILLE
Designated Facility Location Zip:	95687
Designated Facility Location State:	CA
Designated Facility Contact Company Name:	Not Reported
Manifest Residue Indicator:	N
Rejection Indicator:	N

Transporter:

Manifest Tracking Number:	100093333ELC
Transporter Line Number:	1
Transporter EPA ID:	CAL000354470
Transporter Name:	Cve Contracting Group Inc.

Waste Line:

Manifest Tracking Number:	100093333ELC
Waste Line Number:	1
U.S. DOT Hazardous Indicator:	Y
U.S. DOT ID Number:	NA2212
U.S. DOT Description:	Rq,Na2212,Asbestos,9,Pgiii
Non-Hazardous Waste Description:	Not Reported
Number of Containers:	1
Container Type Code:	BA
Container Type Description:	Burlap, cloth, paper, or plastic bags
Waste Quantity:	1
Quantity Unit of Measure Code:	Y
Quantity Unit of Measure Description:	Cubic Yards
Waste Quantity, in Tons:	0.84

CAL-FIRE, 5366 HWY. 49 N., MARIPOSA, CA 95338 (Continued)

Acute Waste Quantity, in Tons:	0
Non-Acute Waste Quantity, in Tons:	0.84
Waste Quantity, in Kilograms:	761.9052
Acute Waste Quantity, in Kilograms:	0
Non-Acute Waste Quantity, in Kilorgrams:	761.9052
Management Method Code:	H132
Management Method Description:	LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not Reported
Waste Density Unit of Measure Code:	Not Reported
Waste Density Unit of Measure Description:	Not Reported
Form Code:	Not Reported
Form Code Description:	Not Reported
Source Code:	Not Reported
Source Code Description:	Not Reported
Waste Minimization Code:	Not Reported
Waste Minimization Code Description:	Not Reported
Consent Number:	Not Reported
EPA Waste Indicator:	N
Federal Waste Codes:	Not Reported
Quantity Haz Kg:	Not Reported
Quantity Haz Tons:	Not Reported
Quantity Non Haz Kg:	761.9052
Quantity Non Haz Tons:	0.84
State Waste Codes:	CA-151

CAL FIRE MARIPOSA
5366 STATE HIGHWAY 49 N, MARIPOSA, CA, 95338 S121737111

▲ A7	NW 1/10 - 1/3	(788 ft. / 0.149 mi.)	Local Lists of Hazardous waste / Contaminated Sites Local Lists of Registered Storage Tanks Other Ascertainable Records
	56 ft. Higher Elevation	2195 ft. Above Sea Level	

Worksheet:

CERS HAZ WASTE: Local Lists of Hazardous waste / Contaminated Sites

Name:	CAL FIRE MARIPOSA
Address:	5366 STATE HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Site ID:	101436
CERS ID:	10197982
CERS Description:	Hazardous Waste Generator

CERS TANKS: Local Lists of Registered Storage Tanks

Name:	CAL FIRE MARIPOSA
Address:	5366 STATE HIGHWAY 49 N

CAL FIRE MARIPOSA, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

City,State,Zip:	MARIPOSA, CA 95338
Site ID:	101436
CERS ID:	10197982
CERS Description:	Aboveground Petroleum Storage

CERS: Other Ascertainable Records

Name:	CAL FIRE MARIPOSA
Address:	5366 STATE HIGHWAY 49 N
City,State,Zip:	MARIPOSA, CA 95338
Site ID:	101436
CERS ID:	10197982
CERS Description:	Chemical Storage Facilities

Violations:

Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to comply with one or more of the following requirements: 1. Have record of inspections and integrity tests signed by the appropriate supervisor or inspector. 2. Keep written procedures and records of inspections and integrity tests for at least three years. 3. Keep comparison records.
Violation Notes:	Returned to compliance on 03/30/2017. Records of inspections must be kept and available for 3 years.
Violation Division:	Mariposa County Public Health Department
Violation Program:	APSA
Violation Source:	CERS,

Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to provide the following training to all oil-handling personnel: 1. Operation and maintenance of equipment to prevent discharges. 2. Discharge procedure protocols. 3. Applicable pollution control laws, rules, and regulations. 4. General facility operations. 5. Contents of the SPCC Plan.
Violation Notes:	Returned to compliance on 03/30/2017. Training is required annually per SPCC Plan. No records of training since 2012 were available.
Violation Division:	Mariposa County Public Health Department
Violation Program:	APSA
Violation Source:	CERS,

Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	01-22-2020
Citation:	HSC 6.5 25160(b)(1)(C) - California Health and Safety Code, Chapter 6.5, Section(s) 25160(b)(1)(C)
Violation Description:	Failure to send a legible copy of each hazardous waste manifest to the Department within 30 days of each shipment of hazardous waste.
Violation Notes:	Observation: The generator failed to determine the status of a uniform hazardous waste manifested shipment within 35 days from the date the waste was shipped, and/or to submit an exception report to DTSC if a signed copy of the manifest isn't received within 45 days of the date the waste was accepted by the intitial transporter. CORRECTIVE ACTION: Submit documentation to the CUPA demonstrating that the generator has determined the status of the hazardous waste manifest shipment for [LIST MANIFESTS], or a copy of the exception report submitted to DTSC, if applicable.
Violation Division:	Mariposa County Public Health Department
Violation Program:	HW
Violation Source:	CERS,

CAL FIRE MARIPOSA, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.
Violation Notes:	Returned to compliance on 06/13/2017. OBSERVATION: The facility has not annually reviewed and certified that the business plan is complete, accurate, and up-to-date. CORRECTIVE ACTION: Review, revise, and certify the business plan electronically in the California Environmental Reporting System (CERS).
Violation Division:	Mariposa County Public Health Department
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Description:	Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met: (1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms. (2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f). (3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.
Violation Notes:	Returned to compliance on 03/10/2017. Please dispose of used antifreeze and flammable liquid in smaller drum outside of shop. Used oil filters need to be disposed of as well.
Violation Division:	Mariposa County Public Health Department
Violation Program:	HW
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	12-16-2014
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 03/23/2015. Please continue to update the inventory: argon gas quantity and location, Solvent -dewaxed, kerosene etc.
Violation Division:	Mariposa County Public Health Department
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 06/13/2017. Please update inventory in CERS. Need to remove solvent and flares. Please add 55 gallon drum of bar oil to inventory location #16.
Violation Division:	Mariposa County Public Health Department
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017

CAL FIRE MARIPOSA, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Citation:	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Description:	Failure to include in the SPCC plan and document discharge prevention briefings for oil-handling personnel at least once a year, including, but not limited to, known discharges, failures, and malfunctioning components.
Violation Notes:	Returned to compliance on 03/30/2017. No records of annual spill prevention briefings were available. Need to determine if briefings may be covered by some other training topic.
Violation Division:	Mariposa County Public Health Department
Violation Program:	APSA
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	01-22-2020
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Description:	Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Notes:	Returned to compliance on 01/22/2020. OBSERVATION: Facility must update inventory to include correct quantities of oxygen onsite. also must update to iclude waste oil and waste antifreeze CORRECTIVE ACTION: Complete and electronically submit the chemical inventory information for all reportable hazardous materials on site at or above reportable quantities.
Violation Division:	Mariposa County Public Health Department
Violation Program:	HMRRP
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	02-28-2017
Citation:	40 CFR 1 265.173 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.173
Violation Description:	Failure to meet the following container management requirements: (a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste. (b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.
Violation Notes:	Returned to compliance on 08/14/2017. OBSERVATION: Used antifreeze container was open with a funnel in it.. All hazardous waste containers shall be closed at all times except when adding or removing waste. CORRECTIVE ACTION: Immediately close these containers and ensure all hazardous waste containers are closed when not adding or removing waste.
Violation Division:	Mariposa County Public Health Department
Violation Program:	HW
Violation Source:	CERS,
Site ID:	101436
Site Name:	CAL FIRE Mariposa
Violation Date:	12-16-2014
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Description:	Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.
Violation Notes:	Returned to compliance on 08/09/2017. Please label all containers of hazardous waste with CA Hazardous Waste labels (used antifreeze, waste parts cleaner solvent)
Violation Division:	Mariposa County Public Health Department
Violation Program:	HW
Violation Source:	CERS,

Evaluation:

Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-22-2020

CAL FIRE MARIPOSA, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not Reported
Eval Division:	Mariposa County Public Health Department
Eval Program:	HW
Eval Source:	CERS,
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-28-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not Reported
Eval Division:	Mariposa County Public Health Department
Eval Program:	HMRRP
Eval Source:	CERS,
Eval General Type:	Other/Unknown
Eval Date:	05-19-2015
Violations Found:	No
Eval Type:	Other, not routine, done by local agency
Eval Notes:	Not Reported
Eval Division:	Mariposa County Public Health Department
Eval Program:	HMRRP
Eval Source:	CERS,
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-22-2020
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	Not Reported
Eval Division:	Mariposa County Public Health Department
Eval Program:	APSA
Eval Source:	CERS,
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	01-22-2020
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not Reported
Eval Division:	Mariposa County Public Health Department
Eval Program:	HMRRP
Eval Source:	CERS,
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	12-16-2014
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Overall very well maintained facility.
Eval Division:	Mariposa County Public Health Department
Eval Program:	HMRRP
Eval Source:	CERS,
Eval General Type:	Other/Unknown

CAL FIRE MARIPOSA, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Eval Date:	05-19-2015
Violations Found:	No
Eval Type:	Other, not routine, done by local agency
Eval Notes:	Not Reported
Eval Division:	Mariposa County Public Health Department
Eval Program:	APSA
Eval Source:	CERS,
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	12-16-2014
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	We will need to see all manifests for hazardous waste shipments for the last three years in order to determine whether the facility is in compliance. Please attach an identifying label to the kerosene drum. Please manage used absorbent as hazardous waste.
Eval Division:	Mariposa County Public Health Department
Eval Program:	HW
Eval Source:	CERS,
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-28-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Not Reported
Eval Division:	Mariposa County Public Health Department
Eval Program:	APSA
Eval Source:	CERS,
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	02-28-2017
Violations Found:	Yes
Eval Type:	Routine done by local agency
Eval Notes:	Ensure that empty containers are labeled empty with the date emptied and managed with in one year. (Reuse or scrap metal)
Eval Division:	Mariposa County Public Health Department
Eval Program:	HW
Eval Source:	CERS,
Eval General Type:	Compliance Evaluation Inspection
Eval Date:	12-16-2014
Violations Found:	No
Eval Type:	Routine done by local agency
Eval Notes:	We will need to see the records for inspections testing and training for the aboveground tank program in order to determine whether the facility is in compliance.
Eval Division:	Mariposa County Public Health Department
Eval Program:	APSA
Eval Source:	CERS,

Coordinates:

Site ID:	101436
Facility Name:	CAL FIRE Mariposa
Env Int Type Code:	HWG
Program ID:	10197982

CAL FIRE MARIPOSA, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Coord Name:	Not Reported
Ref Point Type Desc:	Center of a facility or station.,
Latitude:	37.502960
Longitude:	-119.987130

Affiliation:

Affiliation Type Desc:	Document Preparer
Entity Name:	Brandon Wedge
Entity Title:	Not Reported
Affiliation Address:	Not Reported
Affiliation City:	Not Reported
Affiliation State:	Not Reported
Affiliation Country:	Not Reported
Affiliation Zip:	Not Reported
Affiliation Phone:	,
Affiliation Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	Not Reported
Affiliation Address:	5366 Hwy 49 North
Affiliation City:	Mariposa
Affiliation State:	CA
Affiliation Country:	Not Reported
Affiliation Zip:	95338
Affiliation Phone:	,
Affiliation Type Desc:	Identification Signer
Entity Name:	Brandon Wedge
Entity Title:	Fire Captain
Affiliation Address:	Not Reported
Affiliation City:	Not Reported
Affiliation State:	Not Reported
Affiliation Country:	Not Reported
Affiliation Zip:	Not Reported
Affiliation Phone:	,
Affiliation Type Desc:	Legal Owner
Entity Name:	STATE OF CALIFORNIA
Entity Title:	Not Reported
Affiliation Address:	5366 Hwy 49 North
Affiliation City:	Mariposa
Affiliation State:	CA
Affiliation Country:	United States
Affiliation Zip:	95338
Affiliation Phone:	(209) 966-3622,
Affiliation Type Desc:	Parent Corporation
Entity Name:	Cal Fire MMU
Entity Title:	Not Reported
Affiliation Address:	Not Reported
Affiliation City:	Not Reported

CAL FIRE MARIPOSA, 5366 STATE HIGHWAY 49 N, MARIPOSA, CA 95338 (Continued)

Affiliation State:	Not Reported
Affiliation Country:	Not Reported
Affiliation Zip:	Not Reported
Affiliation Phone:	,
Affiliation Type Desc:	Environmental Contact
Entity Name:	DUTY OFFICER
Entity Title:	Not Reported
Affiliation Address:	5366 Highway 49 North
Affiliation City:	Mariposa
Affiliation State:	CA
Affiliation Country:	Not Reported
Affiliation Zip:	95338
Affiliation Phone:	,
Affiliation Type Desc:	Operator
Entity Name:	CAL FIRE Mariposa Station
Entity Title:	Not Reported
Affiliation Address:	Not Reported
Affiliation City:	Not Reported
Affiliation State:	Not Reported
Affiliation Country:	Not Reported
Affiliation Zip:	Not Reported
Affiliation Phone:	(209) 966-4700,
Affiliation Type Desc:	CUPA District
Entity Name:	Mariposa County Public Health Department
Entity Title:	Not Reported
Affiliation Address:	5100 Bullion Street
Affiliation City:	Mariposa
Affiliation State:	CA
Affiliation Country:	Not Reported
Affiliation Zip:	95338
Affiliation Phone:	(209) 966-2220,

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
ENVIRONMENTAL RECORDS						
Federal NPL site list						
US	NPL	National Priority List	EPA	12/26/2025	01/05/2026	01/22/2026
US	Proposed NPL	Proposed National Priority List Sites	EPA	12/26/2025	01/05/2026	01/22/2026
US	NPL LIENS	Federal Superfund Liens	EPA	10/15/1991	02/02/1994	03/30/1994
Federal CERCLIS list						
US	SEMS	Superfund Enterprise Management System	EPA	12/26/2025	01/05/2026	01/22/2026
Federal RCRA CORRACTS facilities list						
US	CORRACTS	Corrective Action Report	EPA	11/30/2025	12/03/2025	12/10/2025
Federal RCRA TSD facilities list						
US	RCRA-TSDF	RCRA - Treatment, Storage and Disposal	Environmental Protection Agency	11/30/2025	12/03/2025	12/10/2025
Federal RCRA generators list						
US	RCRA-LQG	RCRA - Large Quantity Generators	Environmental Protection Agency	11/30/2025	12/03/2025	12/10/2025
US	RCRA-SQG	RCRA - Small Quantity Generators	Environmental Protection Agency	11/30/2025	12/03/2025	12/10/2025
US	RCRA-VSQG	RCRA - Very Small Quantity Generators (Formerly Conditionall	Environmental Protection Agency	11/30/2025	12/03/2025	12/10/2025
Federal institutional controls / engineering controls registries						
US	LUCIS	Land Use Control Information System	Department of the Navy	03/11/2025	04/02/2025	06/24/2025
US	US ENG CONTROLS	Engineering Controls Sites List	Environmental Protection Agency	10/30/2025	11/11/2025	11/12/2025
US	US INST CONTROLS	Institutional Controls Sites List	Environmental Protection Agency	10/30/2025	11/11/2025	11/12/2025
Federal ERNS list						
US	ERNS	Emergency Response Notification System	National Response Center, United States Coast	12/01/2025	12/08/2025	02/12/2026
State and tribal - equivalent NPL						
CA	RESPONSE	State Response Sites	Department of Toxic Substances Control	10/20/2025	10/20/2025	01/08/2026
State and tribal - equivalent CERCLIS						
CA	ENVIROSTOR	EnviroStor Database	Department of Toxic Substances Control	10/20/2025	10/20/2025	01/08/2026
State and tribal landfill / solid waste disposal						
CA	SWF/LF (SWIS)	Solid Waste Information System	Department of Resources Recycling and Recover	11/03/2025	11/03/2025	01/27/2026
State and tribal leaking storage tank lists						
CA	LUST REG 5	Leaking Underground Storage Tank Database	California Regional Water Quality Control Boa	07/01/2008	07/22/2008	07/31/2008
CA	LUST REG 7	Leaking Underground Storage Tank Case Listing	California Regional Water Quality Control Boa	02/26/2004	02/26/2004	03/24/2004
CA	LUST REG 8	Leaking Underground Storage Tanks	California Regional Water Quality Control Boa	02/14/2005	02/15/2005	03/28/2005
CA	LUST REG 4	Underground Storage Tank Leak List	California Regional Water Quality Control Boa	09/07/2004	09/07/2004	10/12/2004
CA	LUST REG 3	Leaking Underground Storage Tank Database	California Regional Water Quality Control Boa	05/19/2003	05/19/2003	06/02/2003
CA	LUST REG 2	Fuel Leak List	California Regional Water Quality Control Boa	09/30/2004	10/20/2004	11/19/2004
CA	LUST REG 1	Active Toxic Site Investigation	California Regional Water Quality Control Boa	02/01/2001	02/28/2001	03/29/2001

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
CA	LUST REG 6V	Leaking Underground Storage Tank Case Listing	California Regional Water Quality Control Boa	06/07/2005	06/07/2005	06/29/2005
CA	LUST	Leaking Underground Fuel Tank Report (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026
CA	LUST REG 6L	Leaking Underground Storage Tank Case Listing	California Regional Water Quality Control Boa	09/09/2003	09/10/2003	10/07/2003
CA	LUST REG 9	Leaking Underground Storage Tank Report	California Regional Water Quality Control Boa	03/01/2001	04/23/2001	05/21/2001
US	INDIAN LUST R10	Leaking Underground Storage Tanks on Indian Land	EPA Region 10	11/21/2025	12/11/2025	02/19/2026
US	INDIAN LUST R8	Leaking Underground Storage Tanks on Indian Land	EPA Region 8	11/21/2025	12/11/2025	02/19/2026
US	INDIAN LUST R5	Leaking Underground Storage Tanks on Indian Land	EPA, Region 5	11/21/2025	12/11/2025	02/19/2026
US	INDIAN LUST R6	Leaking Underground Storage Tanks on Indian Land	EPA Region 6	11/21/2025	12/11/2025	02/19/2026
US	INDIAN LUST R7	Leaking Underground Storage Tanks on Indian Land	EPA Region 7	11/21/2025	12/12/2025	02/19/2026
US	INDIAN LUST R1	Leaking Underground Storage Tanks on Indian Land	EPA Region 1	11/21/2025	12/11/2025	02/19/2026
US	INDIAN LUST R4	Leaking Underground Storage Tanks on Indian Land	EPA Region 4	11/21/2025	12/11/2025	02/19/2026
US	INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land	Environmental Protection Agency	11/21/2025	12/11/2025	02/19/2026
CA	CPS-SLIC	Statewide SLIC Cases (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/12/2026
CA	SLIC REG 1	Active Toxic Site Investigations	California Regional Water Quality Control Boa	04/03/2003	04/07/2003	04/25/2003
CA	SLIC REG 2	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	Regional Water Quality Control Board San Fran	09/30/2004	10/20/2004	11/19/2004
CA	SLIC REG 3	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	California Regional Water Quality Control Boa	05/18/2006	05/18/2006	06/15/2006
CA	SLIC REG 4	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	Region Water Quality Control Board Los Angele	11/17/2004	11/18/2004	01/04/2005
CA	SLIC REG 5	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	Regional Water Quality Control Board Central	04/01/2005	04/05/2005	04/21/2005
CA	SLIC REG 6V	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	Regional Water Quality Control Board, Victorv	05/24/2005	05/25/2005	06/16/2005
CA	SLIC REG 6L	SLIC Sites	California Regional Water Quality Control Boa	09/07/2004	09/07/2004	10/12/2004
CA	SLIC REG 7	SLIC List	California Regional Quality Control Board, Co	11/24/2004	11/29/2004	01/04/2005
CA	SLIC REG 8	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	California Region Water Quality Control Board	04/03/2008	04/03/2008	04/14/2008
CA	SLIC REG 9	Spills, Leaks, Investigation & Cleanup Cost Recovery Listing	California Regional Water Quality Control Boa	09/10/2007	09/11/2007	09/28/2007
State and tribal registered storage tank lists						
CA	UST	Active UST Facilities	SWRCB	11/25/2025	11/25/2025	02/13/2026
CA	MILITARY UST SITES	Military UST Sites (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026
CA	UST CLOSURE	Proposed Closure of Underground Storage Tank (UST) Cases	State Water Resources Control Board	11/20/2025	11/25/2025	02/13/2026
CA	AST	Aboveground Petroleum Storage Tank Facilities	California Environmental Protection Agency	07/06/2016	07/12/2016	09/19/2016
US	INDIAN UST R10	Underground Storage Tanks on Indian Land	EPA Region 10	11/21/2025	12/11/2025	02/19/2026
US	INDIAN UST R8	Underground Storage Tanks on Indian Land	EPA Region 8	11/21/2025	12/11/2025	02/19/2026
US	INDIAN UST R9	Underground Storage Tanks on Indian Land	EPA Region 9	11/21/2025	12/11/2025	02/19/2026
US	INDIAN UST R4	Underground Storage Tanks on Indian Land	EPA Region 4	11/21/2025	12/11/2025	02/19/2026
US	INDIAN UST R1	Underground Storage Tanks on Indian Land	EPA, Region 1	11/21/2025	12/11/2025	02/19/2026
US	INDIAN UST R7	Underground Storage Tanks on Indian Land	EPA Region 7	11/21/2025	12/11/2025	02/19/2026
US	INDIAN UST R5	Underground Storage Tanks on Indian Land	EPA Region 5	11/21/2025	12/11/2025	02/19/2026
US	INDIAN UST R6	Underground Storage Tanks on Indian Land	EPA Region 6	11/21/2025	12/11/2025	02/19/2026
US	FEMA UST	Underground Storage Tank Listing	FEMA	06/06/2025	08/26/2025	11/12/2025
State and tribal voluntary cleanup sites						
US	INDIAN VCP R7	Voluntary Cleanup Priority Lisitng	EPA, Region 7	03/20/2008	04/22/2008	05/19/2008
US	INDIAN VCP R1	Voluntary Cleanup Priority Listing	EPA, Region 1	07/27/2015	09/29/2015	02/18/2016
CA	VCP	Voluntary Cleanup Program Properties	Department of Toxic Substances Control	10/20/2025	10/20/2025	01/08/2026

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
State and tribal Brownfields sites						
CA	BROWNFIELDS	Considered Brownfieds Sites Listing	State Water Resources Control Board	12/08/2025	12/08/2025	02/26/2026
Other Records						
US	CONSENT	Superfund (CERCLA) Consent Decrees	Department of Justice, Consent Decree Library	09/30/2025	12/12/2025	02/25/2026
US	ROD	Records Of Decision	EPA	01/30/2026	02/02/2026	02/12/2026
US	LIENS 2	CERCLA Lien Information	Environmental Protection Agency	12/26/2025	01/05/2026	01/22/2026
CA	HIST CAL-SITES	Calsites Database	Department of Toxic Substance Control	08/08/2005	08/03/2006	08/24/2006
US	DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations	EPA, Region 9	01/12/2009	05/07/2009	09/21/2009
CA	SWRCY	Recycler Database	Department of Conservation	11/25/2025	11/25/2025	02/13/2026
CA	CA FID UST	Facility Inventory Database	California Environmental Protection Agency	10/31/1994	09/05/1995	09/29/1995
CA	HIST UST	Hazardous Substance Storage Container Database	State Water Resources Control Board	10/15/1990	01/25/1991	02/12/1991
CA	SAN FRANCISCO AST	Aboveground Storage Tank Site Listing	San Francisco County Department of Public Hea	01/27/2026	01/27/2026	02/26/2026
CA	SWEEPS UST	SWEEPS UST Listing	State Water Resources Control Board	06/01/1994	07/07/2005	08/11/2005
US	SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing	Environmental Protection Agency	07/30/2021	02/03/2023	02/10/2023
US	US HIST CDL	National Clandestine Laboratory Register	Drug Enforcement Administration	04/04/2025	06/02/2025	08/12/2025
US	PCB TRANSFORMER	PCB Transformer Registration Database	Environmental Protection Agency	09/13/2019	11/06/2019	02/10/2020
US	US AIRS MINOR	Air Facility System Data	EPA	10/12/2016	10/26/2016	02/03/2017
US	US FIN ASSUR	Financial Assurance Information	Environmental Protection Agency	12/07/2025	12/08/2025	02/05/2026
US	US AIRS (AFS)	Aerometric Information Retrieval System Facility Subsystem (	EPA	10/12/2016	10/26/2016	02/03/2017
US	LEAD SMELTER 2	Lead Smelter Sites	American Journal of Public Health	04/05/2001	10/27/2010	12/02/2010
US	COAL ASH EPA	Coal Combustion Residues Surface Impoundments List	Environmental Protection Agency	01/12/2017	03/05/2019	11/11/2019
US	FUSRAP	Formerly Utilized Sites Remedial Action Program	Department of Energy	03/03/2023	03/03/2023	06/09/2023
US	2020 COR ACTION	2020 Corrective Action Program List	Environmental Protection Agency	09/30/2017	05/08/2018	07/20/2018
US	COAL ASH DOE	Steam-Electric Plant Operation Data	Department of Energy	12/31/2024	11/19/2025	01/29/2026
US	LEAD SMELTER 1	Lead Smelter Sites	Environmental Protection Agency	12/26/2025	01/05/2026	01/22/2026
US	EPA WATCH LIST	EPA Watch List	Environmental Protection Agency	08/30/2013	03/21/2014	06/17/2014
US	Delisted NPL	National Priority List Deletions	EPA	12/26/2025	01/05/2026	01/22/2026
US	SEMS-ARCHIVE	Superfund Enterprise Management System Archive	EPA	12/26/2025	01/05/2026	01/22/2026
US	RCRA NonGen / NLR	RCRA - Non Generators / No Longer Regulated	Environmental Protection Agency	11/30/2025	12/03/2025	12/10/2025
US	HMIRS	Hazardous Materials Information Reporting System	U.S. Department of Transportation	12/07/2025	12/08/2025	02/12/2026
US	DOT OPS	Incident and Accident Data	Department of Transporation, Office of Pipeli	12/31/2025	01/20/2026	03/05/2026
US	US CDL	Clandestine Drug Labs	Drug Enforcement Administration	04/04/2025	06/02/2025	08/12/2025
US	US BROWNFIELDS	A Listing of Brownfields Sites	Environmental Protection Agency	12/02/2025	12/03/2025	02/12/2026
US	DOD	Department of Defense Sites	USGS	06/07/2021	07/13/2021	03/09/2022
US	FEDLAND	Federal and Indian Lands	U.S. Geological Survey	04/02/2018	04/11/2018	11/06/2019
US	FUDS	Formerly Used Defense Sites	U.S. Army Corps of Engineers	10/22/2025	11/06/2025	01/12/2026
US	UMTRA	Uranium Mill Tailings Sites	Department of Energy	05/15/2025	05/15/2025	07/29/2025
US	ODI	Open Dump Inventory	Environmental Protection Agency	06/30/1985	08/09/2004	09/17/2004
US	MINES VIOLATIONS	MSHA Violation Assessment Data	DOL, Mine Safety & Health Admi	01/01/2026	01/06/2026	01/07/2026
US	US MINES	Mines Master Index File	Department of Labor, Mine Safety and Health A	08/08/2025	08/18/2025	11/12/2025
US	US MINES 2	Ferrous and Nonferrous Metal Mines Database Listing	USGS	04/08/2025	05/20/2025	08/12/2025
US	US MINES 3	Active Mines & Mineral Plants Database Listing	USGS	04/14/2011	06/08/2011	09/13/2011
US	PRP	Potentially Responsible Parties	EPA	06/26/2025	07/01/2025	07/29/2025
US	TRIS	Toxic Chemical Release Inventory System	EPA	12/31/2024	11/10/2025	01/29/2026
US	TSCA	Toxic Substances Control Act	EPA	12/31/2020	06/14/2022	03/24/2023

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA/Office of Prevention, Pesticides and Toxi	04/09/2009	04/16/2009	05/11/2009
US	FTTS INSP	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA	04/09/2009	04/16/2009	05/11/2009
US	HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HIST FTTS INSP	FIFRA/TSCA Tracking System Inspection & Enforcement Case Lis	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	SSTS	Section 7 Tracking Systems	EPA	01/12/2026	01/13/2026	03/05/2026
US	ICIS	Integrated Compliance Information System	Environmental Protection Agency	11/18/2016	11/23/2016	02/10/2017
US	PADS	PCB Activity Database System	EPA	08/12/2025	09/30/2025	11/24/2025
US	MLTS	Material Licensing Tracking System	Nuclear Regulatory Commission	01/26/2026	01/27/2026	02/25/2026
US	RADINFO	Radiation Information Database	Environmental Protection Agency	07/01/2019	07/01/2019	09/23/2019
US	FINDS	Facility Index System/Facility Registry System	EPA	11/07/2025	11/19/2025	02/05/2026
US	RAATS	RCRA Administrative Action Tracking System	EPA	04/17/1995	07/03/1995	08/07/1995
US	RMP	Risk Management Plans	Environmental Protection Agency	01/01/2026	01/14/2026	01/22/2026
US	BRS	Biennial Reporting System	EPA/NTIS	12/31/2023	02/19/2025	03/07/2025
US	PWS	Public Water System Data	EPA	12/17/2013	01/09/2014	10/15/2014
US	INDIAN RESERV	Indian Reservations	USGS	12/31/2014	07/14/2015	01/10/2017
US	INDIAN ODI	Report on the Status of Open Dumps on Indian Lands	Environmental Protection Agency	12/31/1998	12/03/2007	01/24/2008
US	IHS OPEN DUMPS	Open Dumps on Indian Land	Department of Health & Human Serivces, Indian	02/07/2024	11/13/2024	11/19/2024
US	ABANDONED MINES	Abandoned Mines	Department of Interior	12/04/2025	12/05/2025	02/12/2026
CA	CA BOND EXP. PLAN	Bond Expenditure Plan	Department of Health Services	01/01/1989	07/27/1994	08/02/1994
CA	CDL	Clandestine Drug Labs	Department of Toxic Substances Control	12/31/2022	03/21/2024	06/12/2024
CA	CHMIRS	California Hazardous Material Incident Report System	Office of Emergency Services	11/30/2025	01/08/2026	01/09/2026
CA	CORTESE	"Cortese" Hazardous Waste & Substances Sites List	CAL EPA/Office of Emergency Information	12/08/2025	12/08/2025	02/25/2026
CA	CUPA LIV-PLE	CUPA Facility Listing	Livermore-Pleasanton Fire Department	09/19/2024	11/05/2024	01/31/2025
CA	DEED	Deed Restriction Listing	DTSC and SWRCB	11/19/2025	11/19/2025	02/04/2026
CA	DRYCLEAN AVAQMD	Antelope Valley Air Quality Management District Drycleaner L	Antelope Valley Air Quality Management Distri	11/24/2025	11/25/2025	02/17/2026
CA	DRYCLEANERS	Cleaner Facilities	Department of Toxic Substance Control	11/20/2025	11/25/2025	02/17/2026
CA	DRYCLEAN LAKE	Lake County Air Quality Management District Drycleaner Facil	Lake County Air Quality Management District	02/15/2024	02/16/2024	05/02/2024
CA	DRYCLEAN MENDOCINO	Mendocino County Air Quality Management District Drycleaner	Mendocino County Air Quality Management Distr	08/26/2024	09/03/2024	11/13/2024
CA	DRYCLEAN SACRAMENTO	Sacramento Metropolitan Air Quality Management DistrictDrycl	Sacramento Metropolitan Air Quality Managemen	09/03/2024	09/05/2024	11/13/2024
CA	DRYCLEAN IMPERIAL	Imperial County Air Pollution Control District Drycleaner Fa	Imperial County Air Pollution Control Distric	10/02/2024	10/03/2024	12/20/2024
CA	DRYCLEAN PLACER	Placer County Air Quality Management District Drycleaner Fac	Placer County Air Quality Management District	05/15/2023	05/17/2023	08/14/2023
CA	DRYCLEAN CALAVERAS	Calaveras County Environmental Management Agency Drycleaner	Calaveras County Environmental Management Age	06/17/2019	06/19/2019	05/01/2023
CA	DRYCLEAN N COAST	North Coast Unified Air Quality Management District Dryclean	North Coast Unified Air Quality Management Di	11/30/2016	04/19/2019	05/01/2023
CA	DRYCLEAN SANTA BARB	Santa Barbara County Air Pollution Control District Dryclean	Santa Barbara County Air Pollution Control Di	02/19/2019	04/17/2019	05/01/2023
CA	DRYCLEAN TEHAMA	Tehama County Air Pollution Control District Drycleaner Faci	Tehama County Air Pollution Control District	04/24/2019	04/24/2019	05/01/2023
CA	DRYCLEAN SHASTA	Shasta County Air Quality Management District District Drycl	Shasta County Air Quality Management District	08/29/2024	09/05/2024	11/13/2024
CA	DRYCLEAN SAN JOAQUIN	San Joaquin Valley Air Pollution Control District District D	San Joaquin Valley Air Pollution Control Dist	05/05/2025	05/07/2025	07/28/2025
CA	DRYCLEAN GRANT	Grant Recipients List	California Air Resources Board	12/31/2021	01/26/2024	04/16/2024
CA	DRYCLEAN SOUTH COAST	South Coast Air Quality Management District Drycleaner Listi	South Coast Air Quality Management District	11/12/2025	11/14/2025	02/03/2026
CA	DRYCLEAN SAN DIEGO	San Diego County Air Pollution Control District Drycleaner F	San Diego County Air Pollution Control Distri	05/02/2025	05/08/2025	07/28/2025
CA	DRYCLEAN BAY AREA	Bay Area Air Quality Management District Drycleaner Facility	Bay Area Air Quality Management District	06/05/2025	06/11/2025	08/20/2025
CA	DRYCLEAN N SONOMA	Norther Sonoma County County Air Pollution Control District	Santa Barbara County Air Pollution Control Di	08/23/2024	08/26/2024	11/05/2024
CA	DRYCLEAN FEATHER RVR	Feather River Air Quality Management District Drycleaner Fac	Feather River Air Quality Management District	03/08/2023	03/09/2023	06/05/2023
CA	DRYCLEAN GLENN	Glenn County Air Pollution Control District Drycleaner Facil	Glenn County Air Pollution Control District	08/26/2024	08/28/2024	11/13/2024
CA	DRYCLEAN YOLO-SOLANO	Yolo-Solano Air Quality Management District Drycleaner Facil	Yolo-Solano Air Quality Management District	05/15/2025	05/15/2025	07/29/2025
CA	DRYCLEAN VENTURA	Drycleaner Facility Listing	Ventura County Air Pollution Control District	05/05/2025	05/07/2025	07/29/2025
CA	DRYCLEAN SAN LUIS OB	San Luis Obispo County Air Pollution Control District Drycle	San Luis Obispo County Air Pollution Control	05/02/2025	05/07/2025	07/29/2025

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
CA	DRYCLEAN MONTERY BAY	Monterey Bay Air Quality Management District Drycleaner Faci	Monterey Bay Air Quality Management District	04/15/2025	05/07/2025	07/29/2025
CA	DRYCLEAN BUTTE	Butte County Air Quality Management DistrictDrycleaner Facil	Butte County Air Quality Management District	04/03/2025	05/07/2025	07/29/2025
CA	DRYCLEAN EAST KERN	Eastern Kern Air Pollution Control District District Dryclea	Eastern Kern Air Pollution Control District	08/21/2024	08/22/2024	11/05/2024
CA	DRYCLEAN MOJAVE	Mojave Desert Air Quality Management District Drycleaner Fac	Mojave Desert Air Quality Management District	05/02/2025	05/02/2025	07/18/2025
CA	DRYCLEAN N SIERRA	Northern Sierra Air Quality Management District Drycleaner F	Northern Sierra Air Quality Management Distri	08/22/2024	08/22/2024	11/05/2024
CA	DRYCLEAN AMADOR	Amador Air District Drycleaner Facility Listing	Amador Air Quality Management District	04/26/2023	04/27/2023	07/13/2023
CA	EMI	Emissions Inventory Data	California Air Resources Board	12/31/2023	03/11/2025	05/23/2025
CA	ENF	Enforcement Action Listing	State Water Resoruces Control Board	10/13/2025	10/14/2025	01/07/2026
CA	FIN ASSURANCE 1	Financial Assurance Information Listing	Department of Toxic Substances Control	10/07/2025	10/08/2025	12/23/2025
CA	FIN ASSURANCE 2	Financial Assurance Information Listing	California Integrated Waste Management Board	11/07/2025	11/13/2025	02/03/2026
CA	HAULERS	Registered Waste Tire Haulers Listing	Integrated Waste Management Board	11/13/2025	11/17/2025	11/19/2025
CA	HAZNET	Facility and Manifest Data	California Environmental Protection Agency	12/31/2024	09/30/2025	12/22/2025
CA	HIST CORTESE	Hazardous Waste & Substance Site List	Department of Toxic Substances Control	04/01/2001	01/22/2009	04/08/2009
CA	HWP	EnviroStor Permitted Facilities Listing	Department of Toxic Substances Control	11/06/2025	11/06/2025	01/27/2026
CA	HWT	Registered Hazardous Waste Transporter Database	Department of Toxic Substances Control	12/16/2025	12/17/2025	12/22/2025
CA	ICE	Inspection, Compliance and Enforcement	Department of Toxic Subsances Control	11/06/2025	11/06/2025	01/27/2026
CA	LDS	Land Disposal Sites Listing (GEOTRACKER)	State Water Qualilty Control Board	11/24/2025	11/24/2025	02/10/2026
CA	LIENS	Environmental Liens Listing	Department of Toxic Substances Control	11/20/2025	11/20/2025	02/09/2026
CA	MCS	Military Cleanup Sites Listing (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/12/2026
CA	MINES	Mines Site Location Listing	Department of Conservation	11/25/2025	11/25/2025	02/12/2026
CA	MWMP	Medical Waste Management Program Listing	Department of Public Health	11/05/2025	11/26/2025	02/12/2026
CA	NPDES	NPDES Permits Listing	State Water Resources Control Board	11/03/2025	11/03/2025	01/27/2026
CA	PEST LIC	Pesticide Regulation Licenses Listing	Department of Pesticide Regulation	11/19/2025	11/19/2025	02/09/2026
CA	PROC	Certified Processors Database	Department of Conservation	11/25/2025	11/25/2025	02/13/2026
CA	NOTIFY 65	Proposition 65 Records	State Water Resources Control Board	12/01/2025	12/02/2025	12/05/2025
CA	SAN JOSE HAZMAT	Hazardous Material Facilities	City of San Jose Fire Department	11/03/2020	11/05/2020	01/26/2021
CA	SCH	School Property Evaluation Program	Department of Toxic Substances Control	10/20/2025	10/20/2025	01/08/2026
CA	SPILLS 90	SPILLS90 data from FirstSearch	FirstSearch	06/06/2012	01/03/2013	02/22/2013
CA	TOXIC PITS	Toxic Pits Cleanup Act Sites	State Water Resources Control Board	07/01/1995	08/30/1995	09/26/1995
CA	UIC	UIC Listing	Deaprtment of Conservation	11/25/2025	11/25/2025	02/13/2026
CA	WASTEWATER PITS	Oil Wastewater Pits Listing	RWQCB, Central Valley Region	02/11/2021	07/01/2021	09/29/2021
CA	WDS	Waste Discharge System	State Water Resources Control Board	06/19/2007	06/20/2007	06/29/2007
CA	WIP	Well Investigation Program Case List	Los Angeles Water Quality Control Board	07/03/2009	07/21/2009	08/03/2009
CA	WMUDS/SWAT	Waste Management Unit Database	State Water Resources Control Board	04/01/2000	04/10/2000	05/10/2000
US	BIOSOLIDS	ICIS-NPDES Biosolids Facility Data	Environmental Protection Agency	01/10/2026	01/15/2026	03/05/2026
US	AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing	Environmental Protection Agency	12/17/2025	12/18/2025	03/05/2026
US	PFAS ECHO	Facilities in Industries that May Be Handling PFAS Listing	Environmental Protection Agency	12/17/2025	12/18/2025	12/23/2025
US	PFAS WQP	Ambient Environmental Sampling for PFAS	Environmental Protection Agency	12/17/2025	12/18/2025	01/07/2026
US	PFAS ECHO FIRE TRAIN	Facilities in Industries that May Be Handling PFAS Listing	Environmental Protection Agency	12/17/2025	12/18/2025	12/23/2025
CA	CERS HAZ WASTE	California Environmental Reporting System Hazardous Waste	CalEPA	10/13/2025	10/13/2025	12/18/2025
CA	HWTS	Hazardous Waste Tracking System	Department of Toxic Substances Control	12/17/2025	12/23/2025	01/07/2026
US	FUELS PROGRAM	EPA Fuels Program Registered Listing	EPA	11/06/2025	11/06/2025	01/12/2026
US	PFAS PT 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing	Environmental Protection Agency	12/17/2025	12/18/2025	12/23/2025
US	PCS	Permit Compliance System	EPA, Office of Water	12/16/2016	01/06/2017	03/10/2017
US	ECHO	Enforcement & Compliance History Information	Environmental Protection Agency	12/13/2025	12/17/2025	02/25/2026
CA	MILITARY PRIV SITES	Military Privatized Sites (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026
CA	NON-CASE INFO	Non-Case Information Sites (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
CA	OTHER OIL GAS	Other Oil & Gas Projects Sites (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026
CA	PROD WATER PONDS	Produced Water Ponds Sites (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026
CA	SAMPLING POINT	Sampling Point ? Public Sites (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026
CA	UIC GEO	Underground Injection Control Sites (GEOTRACKER)	State Water Resource Control Board	11/24/2025	11/24/2025	02/11/2026
CA	WELL STIM PROJ	Well Stimulation Project (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026
CA	CERS	CalEPA Regulated Site Portal Data	California Environmental Protection Agency	10/13/2025	10/13/2025	12/17/2025
CA	CERS TANKS	California Environmental Reporting System (CERS) Tanks	California Environmental Protection Agency	10/13/2025	10/13/2025	12/17/2025
CA	PROJECT	Project Sites (GEOTRACKER)	State Water Resources Control Board	11/24/2025	11/24/2025	02/11/2026
CA	CIWQS	California Integrated Water Quality System	State Water Resources Control Board	11/19/2025	11/19/2025	02/04/2026
US	DOCKET HWC	Hazardous Waste Compliance Docket Listing	Environmental Protection Agency	05/06/2021	05/21/2021	08/11/2021
US	E MANIFEST	Hazardous Waste Electronic Manifest System	Environmental Protection Agency	11/30/2025	12/05/2025	12/19/2025
US	MINES MRDS	Mineral Resources Data System	USGS	06/04/2024	11/22/2024	02/18/2025
US	UXO	Unexploded Ordnance Sites	Department of Defense	07/31/2025	08/14/2025	11/04/2025
US	FEDERAL FACILITY	Federal Facility Site Information listing	Environmental Protection Agency	12/10/2025	12/10/2025	02/12/2026
US	PFAS PROJECT	NORTHEASTERN UNIVERSITY PFAS PROJECT	Social Science Environmental Health Research	08/21/2025	12/04/2025	02/12/2026
CA	AQUEOUS FOAM	Former Fire Training Facility Assessments Listing	State Water Resources Control Board	11/25/2025	11/25/2025	02/17/2026
CA	CHROME PLATING	Chrome Plating Facilities Listing	State Water Resources Control Board	11/25/2025	11/25/2025	02/17/2026
US	PFAS ATSDR	PFAS Contamination Site Location Listing	Department of Health & Human Services	11/12/2024	07/21/2025	10/13/2025
US	PFAS NPDES	Clean Water Act Discharge Monitoring Information	Environmental Protection Agency	12/17/2025	12/19/2025	12/23/2025
US	PFAS FEDERAL SITES	Federal Sites PFAS Information	Environmental Protection Agency	12/17/2025	12/18/2025	12/23/2025
US	PFAS NPL	Superfund Sites with PFAS Detections Information	Environmental Protection Agency	12/17/2025	12/18/2025	12/23/2025
CA	PFAS	PFAS Contamination Site Location Listing	State Water Resources Control Board	11/25/2025	11/25/2025	02/13/2026
CA	WDR	Waste Discharge Requirements Listing	State Water Resources Control Board	11/25/2025	11/25/2025	02/13/2026
US	PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing	Environmental Protection Agency	12/17/2025	12/18/2025	12/23/2025
US	PFAS TRIS	List of PFAS Added to the TRI	Environmental Protection Agency	12/17/2025	12/18/2025	12/23/2025
US	PFAS TSCA	PFAS Manufacture and Imports Information	Environmental Protection Agency	12/17/2025	12/18/2025	12/23/2025
US	UST FINDER	UST Finder Database	Environmental Protection Agency	06/08/2023	10/04/2023	01/18/2024
US	UST FINDER RELEASE	UST Finder Releases Database	Environmental Protecton Agency	06/08/2023	10/31/2023	01/18/2024

HISTORICAL USE RECORDS

US	EDR MGP	EDR Proprietary Manufactured Gas Plants	EDR, Inc.			
US	EDR Hist Auto	EDR Exclusive Historical Auto Stations	EDR, Inc.			
US	EDR Hist Cleaner	EDR Exclusive Historical Cleaners	EDR, Inc.			
CA	RGA LF	Recovered Government Archive Solid Waste Facilities List	Department of Resources Recycling and Recover		07/01/2013	01/13/2014
CA	RGA LUST	Recovered Government Archive Leaking Underground Storage Tan	State Water Resources Control Board		07/01/2013	12/30/2013

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
COUNTY RECORDS						
CA	CS ALAMEDA	Contaminated Sites	Alameda County Environmental Health Services	01/09/2019	01/11/2019	03/05/2019
CA	UST ALAMEDA	Underground Tanks	Alameda County Environmental Health Services	12/26/2023	12/26/2023	03/19/2024
CA	CUPA AMADOR	CUPA Facility List	Amador County Environmental Health	04/27/2023	04/27/2023	07/13/2023
CA	CUPA BUTTE	CUPA Facility Listing	Public Health Department	04/21/2017	04/25/2017	08/09/2017
CA	CUPA CALVERAS	CUPA Facility Listing	Calveras County Environmental Health	12/04/2025	12/05/2025	02/25/2026
CA	CUPA COLUSA	CUPA Facility List	Health & Human Services	04/06/2020	04/23/2020	07/10/2020
CA	SL CONTRA COSTA	Site List	Contra Costa Health Services Department	10/17/2025	10/21/2025	01/09/2026
CA	CUPA DEL NORTE	CUPA Facility List	Del Norte County Environmental Health Divisio	02/05/2025	02/12/2025	05/02/2025
CA	CUPA EL DORADO	CUPA Facility List	El Dorado County Environmental Management Dep	08/08/2022	08/09/2022	09/01/2022
CA	CUPA FRESNO	CUPA Resources List	Dept. of Community Health	06/28/2021	12/21/2021	03/03/2022
CA	CUPA GLENN	CUPA Facility List	Glenn County Air Pollution Control District	01/22/2018	01/24/2018	03/14/2018
CA	CUPA HUMBOLDT	CUPA Facility List	Humboldt County Environmental Health	08/12/2021	08/12/2021	11/08/2021
CA	CUPA IMPERIAL	CUPA Facility List	San Diego Border Field Office	10/08/2025	10/08/2025	12/23/2025
CA	CUPA INYO	CUPA Facility List	Inyo County Environmental Health Services	04/02/2018	04/03/2018	06/14/2018
CA	CUPA KERN	CUPA Facility List	Kern County Public Health	10/22/2025	10/23/2025	01/16/2026
CA	UST KERN	Underground Storage Tank Sites & Tank Listing	Kern County Environment Health Services Depar	10/22/2025	10/23/2025	01/14/2026
CA	CUPA KINGS	CUPA Facility List	Kings County Department of Public Health	12/03/2020	01/26/2021	04/14/2021
CA	CUPA LAKE	CUPA Facility List	Lake County Environmental Health	01/28/2025	01/29/2025	04/15/2025
CA	CUPA LASSEN	CUPA Facility List	Lassen County Environmental Health	07/31/2020	08/21/2020	11/09/2020
CA	AOCONCERN	Key Areas of Concerns in Los Angeles County		03/30/2009	03/31/2009	10/23/2009
CA	HMS LOS ANGELES	HMS: Street Number List	Department of Public Works	12/18/2025	12/18/2025	12/22/2025
CA	LF LOS ANGELES	List of Solid Waste Facilities	La County Department of Public Works	10/06/2025	10/07/2025	12/23/2025
CA	LF LOS ANGELES CITY	City of Los Angeles Landfills	Engineering & Construction Division	12/31/2023	10/03/2024	12/17/2024
CA	LOS ANGELES AST	Active & Inactive AST Inventory	Los Angeles Fire Department	06/01/2019	06/25/2019	08/22/2019
CA	LOS ANGELES CO LF METHANE	Methane Producing Landfills	Los Angeles County Department of Public Works	05/14/2024	07/09/2024	09/27/2024
CA	LOS ANGELES HM	Active & Inactive Hazardous Materials Inventory	Los Angeles Fire Department	12/01/2025	12/08/2025	02/26/2026
CA	LOS ANGELES UST	Active & Inactive UST Inventory	Los Angeles Fire Department	12/01/2025	12/08/2025	02/26/2026
CA	SITE MIT LOS ANGELES	Site Mitigation LA County List	Community Health Services	04/29/2025	07/10/2025	10/03/2025
CA	UST EL SEGUNDO	City of El Segundo Underground Storage Tank	City of El Segundo Fire Department	01/21/2017	04/19/2017	05/10/2017
CA	UST LONG BEACH	City of Long Beach Underground Storage Tank	City of Long Beach Fire Department	04/22/2019	04/23/2019	06/27/2019
CA	UST TORRANCE	City of Torrance Underground Storage Tank	City of Torrance Fire Department	07/16/2025	07/17/2025	10/09/2025
CA	CUPA MADERA	CUPA Facility List	Madera County Environmental Health	08/10/2020	08/12/2020	10/23/2020
CA	UST MARIN	Underground Storage Tank Sites	Public Works Department Waste Management	09/26/2018	10/04/2018	11/02/2018
CA	UST MENDOCINO	Mendocino County UST Database	Department of Public Health	09/22/2021	11/18/2021	11/22/2021
CA	CUPA MERCED	CUPA Facility List	Merced County Environmental Health	11/10/2025	11/14/2025	02/03/2026
CA	CUPA MONO	CUPA Facility List	Mono County Health Department	02/22/2021	03/02/2021	05/19/2021
CA	CUPA MONTEREY	CUPA Facility Listing	Monterey County Health Department	09/25/2025	09/26/2025	10/08/2025
CA	LUST NAPA	Sites With Reported Contamination	Napa County Department of Environmental Manag	01/09/2017	01/11/2017	03/02/2017
CA	UST NAPA	Closed and Operating Underground Storage Tank Sites	Napa County Department of Environmental Manag	09/05/2019	09/09/2019	10/31/2019
CA	CUPA NEVADA	CUPA Facility List	Community Development Agency	10/22/2025	10/23/2025	01/14/2026
CA	IND_SITE ORANGE	List of Industrial Site Cleanups Orange County	Health Care Agency	10/23/2025	10/24/2025	01/15/2026
CA	LUST ORANGE	List of Underground Storage Tank Cleanups	Health Care Agency	10/24/2025	10/28/2025	01/15/2026
CA	UST ORANGE	List of Underground Storage Tank Facilities	Health Care Agency	04/29/2025	04/30/2025	07/17/2025
CA	MS PLACER	Master List of Facilities	Placer County Health and Human Services	11/19/2025	11/19/2025	02/09/2026
CA	CUPA PLUMAS	CUPA Facility List	Plumas County Environmental Health	03/31/2019	04/23/2019	06/26/2019

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
CA	LUST RIVERSIDE	Listing of Underground Tank Cleanup Sites	Department of Environmental Health	06/11/2024	06/12/2024	06/27/2024
CA	UST RIVERSIDE	Underground Storage Tank Tank List	Department of Environmental Health	12/05/2025	12/05/2025	12/09/2025
CA	CS SACRAMENTO	Toxic Site Clean-Up List	Sacramento County Environmental Management	11/07/2022	12/21/2022	03/16/2023
CA	ML SACRAMENTO	Master Hazardous Materials Facility List	Sacramento County Environmental Management	11/07/2022	12/09/2022	03/01/2023
CA	CUPA SAN BENITO	CUPA Facility List	San Benito County Environmental Health	10/23/2025	10/24/2025	01/14/2026
CA	PERMITS SAN BERNARDINO	Hazardous Material Permits	San Bernardino County Fire Department Hazardo	11/18/2025	11/19/2025	02/09/2026
CA	HMMD SAN DIEGO	Hazardous Materials Management Division Database	Hazardous Materials Management Division	11/19/2025	11/19/2025	02/05/2026
CA	LF SAN DIEGO	Solid Waste Facilities	Department of Health Services	10/01/2024	01/15/2025	03/28/2025
CA	SAN DIEGO CO LOP	Local Oversight Program Listing	Department of Environmental Health	07/22/2021	10/19/2021	01/13/2022
CA	SAN DIEGO CO SAM	Environmental Case Listing	San Diego County Department of Environmental	03/23/2010	06/15/2010	07/09/2010
CA	CUPA SAN FRANCISCO CO	CUPA Facility Listing	San Francisco County Department of Environmen	01/27/2026	01/27/2026	02/26/2026
CA	LUST SAN FRANCISCO	Local Oversite Facilities	Department Of Public Health San Francisco Cou	09/19/2008	09/19/2008	09/29/2008
CA	UST SAN FRANCISCO	Underground Storage Tank Information	Department of Public Health	01/27/2026	01/27/2026	02/26/2026
CA	SAN FRANCISCO MAHER	Maher Ordinance Property Listing	San Francisco Planning	08/12/2025	10/14/2025	01/09/2026
CA	UST SAN JOAQUIN	San Joaquin Co. UST	Environmental Health Department	06/22/2018	06/26/2018	07/11/2018
CA	CUPA SAN LUIS OBISPO	CUPA Facility List	San Luis Obispo County Public Health Departme	11/04/2025	11/05/2025	11/14/2025
CA	BI SAN MATEO	Business Inventory	San Mateo County Environmental Health Service	02/20/2020	02/20/2020	04/24/2020
CA	LUST SAN MATEO	Fuel Leak List	San Mateo County Environmental Health Service	03/29/2019	03/29/2019	05/29/2019
CA	CUPA SANTA BARBARA	CUPA Facility Listing	Santa Barbara County Public Health Department	09/08/2011	09/09/2011	10/07/2011
CA	CUPA SANTA CLARA	Cupa Facility List	Department of Environmental Health	11/07/2025	11/10/2025	01/29/2026
CA	HIST LUST SANTA CLARA	HIST LUST - Fuel Leak Site Activity Report	Santa Clara Valley Water District	03/29/2005	03/30/2005	04/21/2005
CA	LUST SANTA CLARA	LOP Listing	Department of Environmental Health	03/03/2014	03/05/2014	03/18/2014
CA	CUPA SANTA CRUZ	CUPA Facility List	Santa Cruz County Environmental Health	01/21/2017	02/22/2017	05/23/2017
CA	SITE MIT SANTA CRUZ	Site Mitigation Santa Cruz County List	Santa Cruz Environmental Health Services	12/03/2018	06/23/2023	07/13/2023
CA	CUPA SHASTA	CUPA Facility List	Shasta County Department of Resource Manageme	06/15/2017	06/19/2017	08/09/2017
CA	LUST SOLANO	Leaking Underground Storage Tanks	Solano County Department of Environmental Man	06/04/2019	06/06/2019	08/13/2019
CA	UST SOLANO	Underground Storage Tanks	Solano County Department of Environmental Man	09/15/2021	09/16/2021	12/09/2021
CA	CUPA SONOMA	Cupa Facility List	County of Sonoma Fire & Emergency Services De	07/02/2021	07/06/2021	07/14/2021
CA	LUST SONOMA	Leaking Underground Storage Tank Sites	Department of Health Services	06/30/2021	06/30/2021	09/24/2021
CA	CUPA STANISLAUS	CUPA Facility List	Stanislaus County Department of Ennvironmenta	02/08/2022	02/10/2022	05/04/2022
CA	UST SUTTER	Underground Storage Tanks	Sutter County Environmental Health Services	07/23/2025	10/08/2025	12/24/2025
CA	CUPA TEHAMA	CUPA Facility List	Tehama County Department of Environmental Hea	11/12/2025	11/12/2025	01/29/2026
CA	CUPA TRINITY	CUPA Facility List	Department of Toxic Substances Control	04/09/2025	04/10/2025	06/27/2025
CA	CUPA TULARE	CUPA Facility List	Tulare County Environmental Health Services D	10/07/2022	10/07/2022	12/21/2022
CA	CUPA TUOLUMNE	CUPA Facility List	Divison of Environmental Health	04/23/2018	04/25/2018	06/25/2018
CA	BWT VENTURA	Business Plan, Hazardous Waste Producers, and Operating Unde	Ventura County Environmental Health Division	09/30/2025	10/24/2025	01/14/2026
CA	LF VENTURA	Inventory of Illegal Abandoned and Inactive Sites	Environmental Health Division	12/01/2011	12/01/2011	01/19/2012
CA	LUST VENTURA	Listing of Underground Tank Cleanup Sites	Environmental Health Division	05/29/2008	06/24/2008	07/31/2008
CA	MED WASTE VENTURA	Medical Waste Program List	Ventura County Resource Management Agency	09/30/2025	10/28/2025	01/15/2026
CA	UST VENTURA	Underground Tank Closed Sites List	Environmental Health Division	11/26/2025	12/04/2025	02/25/2026
CA	UST YOLO	Underground Storage Tank Comprehensive Facility Report	Yolo County Department of Health	12/09/2025	12/10/2025	03/03/2026
CA	CUPA YUBA	CUPA Facility List	Yuba County Environmental Health Department	10/23/2025	10/24/2025	01/15/2026


GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

California Geologic Energy Management Division – CalGEM
(https://www.conservation.ca.gov/calgem/Pages/WellFinder.aspx)




https://us-partner-integrations.egnyte.com/msoffice/wopi/files/94f119e8-0c6c-4e2a-8a39-5a87fb8f5211/WOPIServiceId_TP_EGNYTE_PLUS/WOPIUserId_73.ppeng.egnyte.com/CalGEM.docx

Department of Toxic Substances Control – EnviroStor (http://www.envirostor.dtsc.ca.gov/public/)



https://us-partner-integrations.egnyte.com/msoffice/wopi/files/70910ff4-b6b3-4205-9215-46d6ddd1b48c/WOPIServiceId_TP_EGNYTE_PLUS/WOPIUserId_73.ppeng.egnyte.com/DTSC EnviroStor.docx

Regional Water Quality Control Board – GeoTracker (http://geotracker.waterboards.ca.gov/default.asp)



Appendix D Historical Records

EDR Aerial Photo Decade Package

EDR Historical Topo Map Report

EDR-City Directory Image Report

EDR Certified Sanborn Map Report

EDR Building Permit Report

County Tax Assessor Records

ParcelQuest Property Detail Report

EDR Property Tax Map Report

Mariposa County

Frank Wilson Rd

Mariposa, CA 95338

Inquiry Number: 8280255.11

March 13, 2026

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

03/13/26

Site Name:

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338
EDR Inquiry # 8280255.11

Client Name:

Provost & Pritchard Eng. Group
455 W. Fir Ave
Clovis, CA 93611
Contact: Stephanie Gillaspy

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2024	1"=500'	Flight Year: 2024	USDA/NAIP
2020	1"=500'	Flight Year: 2020	USDA/NAIP
2016	1"=500'	Flight Year: 2016	USDA/NAIP
2012	1"=500'	Flight Year: 2012	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1998	1"=500'	Acquisition Date: August 20, 1998	USGS/DOQQ
1993	1"=500'	Flight Year: 1993	USGS/DOQQ
1984	1"=500'	Flight Date: September 14, 1984	USDA
1978	1"=500'	Flight Date: July 11, 1978	USGS
1972	1"=500'	Flight Date: September 11, 1972	USGS
1959	1"=500'	Flight Date: June 06, 1959	USGS
1945	1"=500'	Flight Date: October 19, 1945	USGS

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.

Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.



INQUIRY #: 8280255.11

YEAR: 2024

= 500'

N

EDR


INQUIRY #: 8280255.11
YEAR: 2020
= 500'
N
EDR


INQUIRY #: 8280255.11
YEAR: 2016
= 500'
N
EDR



INQUIRY #: 8280255.11

YEAR: 2012

= 500'

N

EDR


INQUIRY #: 8280255.11
YEAR: 2009
= 500'
N
EDR



INQUIRY #: 8280255.11

YEAR: 2006

= 500'

N

EDR


INQUIRY #: 8280255.11
YEAR: 1998
= 500'
N
EDR



UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED

INQUIRY #: 8280255.11

YEAR: 1993

= 500'

N

EDR

UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED



INQUIRY #: 8280255.11

YEAR: 1984

= 500'

N

EDR



INQUIRY #: 8280255.11

YEAR: 1978

= 500'

N

EDR



INQUIRY #: 8280255.11

YEAR: 1972

= 500'

N

EDR



INQUIRY #: 8280255.11

YEAR: 1959

= 500'

N

EDR



INQUIRY #: 8280255.11

YEAR: 1945

= 500'

N

EDR

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338

Inquiry Number: 8280255.4
March 12, 2026

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

03/12/26

Site Name:

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338
EDR Inquiry # 8280255.4

Client Name:

Provost & Pritchard Eng. Group
455 W. Fir Ave
Clovis, CA 93611
Contact: Stephanie Gillaspy

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Provost & Pritchard Eng. Group were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# 1542-26-001 ESA
Project: Mariposa County

Coordinates:

Latitude:	37.500486 37° 30' 2" North
Longitude:	-119.984698 -119° 59' 5" West
UTM Zone:	Zone 11 North
UTM X Meters:	236152.87
UTM Y Meters:	4154581.03
Elevation:	2137.27' above sea level

Maps Provided:

2021	1947
2018	1912
2015	1909
2012	1903
2004	1900
1992	1896, 1897
1981	
1948	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.


2021 Source Sheets



Feliciana Mountain
2021
7.5-minute, 24000



Mariposa
2021
7.5-minute, 24000



Bear Valley
2021
7.5-minute, 24000



Catheys Valley
2021
7.5-minute, 24000


2018 Source Sheets




Feliciana Mountain
2018
7.5-minute, 24000



Mariposa
2018
7.5-minute, 24000




Bear Valley
2018
7.5-minute, 24000




Catheys Valley
2018
7.5-minute, 24000


2015 Source Sheets



Feliciana Mountain
2015
7.5-minute, 24000



Mariposa
2015
7.5-minute, 24000



Bear Valley
2015
7.5-minute, 24000



Catheys Valley
2015
7.5-minute, 24000

2012 Source Sheets



Feliciana Mountain
2012
7.5-minute, 24000



Mariposa
2012
7.5-minute, 24000



Bear Valley
2012
7.5-minute, 24000



Catheys Valley
2012
7.5-minute, 24000

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2004 Source Sheets



Feliciana Mountain
2004
7.5-minute, 24000
Aerial Photo Revised 1998

1992 Source Sheets



Feliciana Mtn.
1992
7.5-minute, 24000
Aerial Photo Revised 1978

1981 Source Sheets



Feliciana Mtn.
1981
7.5-minute, 24000
Aerial Photo Revised 1978



Catheys Valley
1981
7.5-minute, 24000
Aerial Photo Revised 1978




Mariposa
1981
7.5-minute, 24000
Aerial Photo Revised 1978




CATHEYS VALLEY
1981
7.5-minute, 24000

1948 Source Sheets



Bear Valley
1948
7.5-minute, 24000



Feliciana Mtn.
1948
7.5-minute, 24000
Aerial Photo Revised 1945

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1947 Source Sheets



Feliciana Mtn.
1947
7.5-minute, 24000
Aerial Photo Revised 1945



Bear Valley
1947
7.5-minute, 24000



Mariposa
1947
7.5-minute, 24000

1912 Source Sheets



Mariposa
1912
30-minute, 125000

1909 Source Sheets



Yosemite
1909
30-minute, 125000

1903 Source Sheets



Yosemite
1903
30-minute, 125000

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1900 Source Sheets



Yosemite
1900
30-minute, 125000


1896, 1897 Source Sheets



Sonora
1896
30-minute, 125000




Sonora
1897
30-minute, 125000



Yosemite
1897
30-minute, 125000

Historical Topo Map

2021



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Feliciana Mountain, 2021, 7.5-minute
SE, Mariposa, 2021, 7.5-minute
SW, Catheys Valley, 2021, 7.5-minute
NW, Bear Valley, 2021, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Feliciana Mountain, 2018, 7.5-minute
SE, Mariposa, 2018, 7.5-minute
SW, Catheys Valley, 2018, 7.5-minute
NW, Bear Valley, 2018, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Feliciana Mountain, 2015, 7.5-minute
SE, Mariposa, 2015, 7.5-minute
SW, Catheys Valley, 2015, 7.5-minute
NW, Bear Valley, 2015, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N

Historical Topo Map

2012



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Feliciana Mountain, 2012, 7.5-minute
SE, Mariposa, 2012, 7.5-minute
SW, Catheys Valley, 2012, 7.5-minute
NW, Bear Valley, 2012, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



UNMAPPED

This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Feliciana Mountain, 2004, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



UNMAPPED

This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Feliciana Mtn., 1992, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Feliciana Mtn., 1981, 7.5-minute
SE, Mariposa, 1981, 7.5-minute
SW, Catheys Valley, 1981, 7.5-minute
SW, CATHEYS VALLEY, 1981, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED
UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED UNMAPPED

This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Feliciana Mtn., 1948, 7.5-minute
NW, Bear Valley, 1948, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5


NW N NE
W E
SW S SE

TP, Feliciana Mtn., 1947, 7.5-minute
SE, Mariposa, 1947, 7.5-minute
NW, Bear Valley, 1947, 7.5-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group


N

UNMAPPED



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5



SE, Mariposa, 1912, 30-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group


N



UNMAPPED

This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5



TP, Yosemite, 1909, 30-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



UNMAPPED

This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Yosemite, 1903, 30-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Yosemite, 1900, 30-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N



UNMAPPED

This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Yosemite, 1897, 30-minute
NW, Sonora, 1896, 30-minute
NW, Sonora, 1897, 30-minute

SITE NAME: Mariposa County
ADDRESS: Frank Wilson Rd
Mariposa, CA 95338
CLIENT: Provost & Pritchard Eng. Group

N

LIGHTBOX

LightBox City Directory Report

Mariposa County

Frank Wilson Rd

Mariposa, CA 95338

Inquiry Number: 8280255.5

March 12, 2026

TABLE OF CONTENTS

LIGHTBOX LIVE

Open LightBox Live to access data, tools, and advanced analytics in one online platform.
https://lightbox.live/environmental/analysis/c2cbc85f-555e-4a27-b4da-77edf84d241d

SECTION

Executive Summary ---------- page 1

Findings ---------- page 3

Thank you for your business.
Please contact LightBox at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to LightBox Parent, L.P. ("LightBox"). The user of this Report accepts this Report "AS IS" and "AS AVAILABLE". NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. LIGHTBOX SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, ACCURACY, COMPLETENESS, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL LIGHTBOX, ITS AFFILIATES, LICENSORS, OR SERVICE PROVIDERS BE LIABLE FOR ANY DAMAGES OF ANY KIND, WHETHER DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, SPECIAL, EXEMPLARY, OR PUNITIVE, ARISING FROM OR RELATING TO THIS REPORT OR ITS USE. IF LIABILITY CANNOT BE EXCLUDED UNDER APPLICABLE LAW, IT IS STRICTLY LIMITED TO THE AMOUNT PAID FOR THE REPORT, IF ANY, BY THE USER OF THE REPORT. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright by LightBox Parent, L.P. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of LightBox or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of LightBox Parent, L.P. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

The LightBox City Directory Report is designed to assist environmental professionals in evaluating potential liabilities on select properties resulting from past activities. The report includes a search of available business directory data at approximately five-year intervals.

SOURCES

Through agreements with major city directory publishers, including Cole Information, InfoUSA, and Bresser, as well as our own collections (Haines & Stewart), the LightBox City Directory Report offers comprehensive national coverage.

LightBox is authorized to reproduce and redistribute all works featured in this report. The purchaser of this LightBox City Directory Report may include it in their final report(s).

This report includes a search of the following sources:

Year	Source
2024	Cole Information
2022	Cole Information
2017	Cole Information, Data Axle
2014	Cole Information, Data Axle
2010	Cole Information, Data Axle
2005	Cole Information, Data Axle
2000	Cole Information, Data Axle
1995	Cole Information
1992	Cole Information
1985	Haines
1981	Haines
1977	Haines
1974	Haines

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

No results found for target property.

FINDINGS

This section includes records sorted by street then year.

STREETS

Bella Sienna
CA-49
Farfalla Cir
Lemee Ln
Mari Way
Pietra Ln
State Hwy 49 N

BELLA SIENNA

2014 Cole Information

5203	OCCUPANT UNKNOWN
5207	OCCUPANT UNKNOWN
5209	OCCUPANT UNKNOWN
5213	OCCUPANT UNKNOWN
5215	OCCUPANT UNKNOWN
5219	OCCUPANT UNKNOWN
5221	OCCUPANT UNKNOWN

BELLA SIENNA

2010 Cole Information

5203	OCCUPANT UNKNOWN
5207	OCCUPANT UNKNOWN
5209	OCCUPANT UNKNOWN
5213	OCCUPANT UNKNOWN
5215	OCCUPANT UNKNOWN
5219	OCCUPANT UNKNOWN
5221	OCCUPANT UNKNOWN

FINDINGS

CA-49

2017 Data Axle

5352	FIRST BAPTIST CHURCH

CA-49

2014 Cole Information

5352	1ST BAPTIST CHURCH JOHN TRUJILLO

CA-49

2010 Cole Information

5352	JOHN TRUJILLO

CA-49

2010 Data Axle

5352	FIRST BAPTIST CHURCH


CA-49

1985 Haines



CA-49

1981 Haines



FINDINGS

FARFALLA CIR

2024 Cole Information

5273	DAVID R ISAACS

FARFALLA CIR

2022 Cole Information

5273	Carl B Williams

FARFALLA CIR

2017 Cole Information

5273	BUD MUNCK

FARFALLA CIR

2014 Cole Information

5273	BUD MUNCK

FARFALLA CIR

2010 Cole Information

5273	BRIAN R WILLIAMS

FINDINGS

LEMEE LN

2024 Cole Information

5362	Marips Cnty Dpt Cld Sprt Srvcs
	Amy Olson
	Mary Ellen Mcrae

LEMEE LN

2022 Cole Information

5362	MARIPOSA COUNTY BEHAVIORAL
	JOB CONNECTION MARIPOSA
	MARIPS CNTY DPT CLD SPRT SRVCS
	JONATHAN L HARRY

LEMEE LN

2017 Cole Information

5362	MARIPS CNTY DPT CLD SPRT SRVCS

LEMEE LN

2014 Cole Information

5362	MOTHER LODE JOB TRAINING
	JOB CONNECTION MARIPOSA

FINDINGS

MARI WAY

2024 Cole Information

5045	CHERYL A DUNBAR
5049	JEFFREY A MUNDLE

MARI WAY

2022 Cole Information

5045	Cheryl Dunbar
5049	Jeffrey A Mundle

MARI WAY

2017 Cole Information

5045	CHERYL DUNBAR
5049	CARLTON A LEONARD

MARI WAY

2014 Cole Information

5045	OCCUPANT UNKNOWN
5049	OCCUPANT UNKNOWN

MARI WAY

2010 Cole Information

5045	HARRY R BOOTH
5049	OCCUPANT UNKNOWN

FINDINGS

PIETRA LN

2024 Cole Information

5336	ALFRED F KUDELA

PIETRA LN

2014 Cole Information

5336	OCCUPANT UNKNOWN
5340	OCCUPANT UNKNOWN

PIETRA LN

2010 Cole Information

5336	OCCUPANT UNKNOWN
5340	OCCUPANT UNKNOWN

FINDINGS

STATE HWY 49 N

2024 Cole Information

5320	Shannon J Leduc Cpa
	Community Health Centers Amer
	Native Sltons Fmly Gidance Ctr
	Roger Stephens Engineering Inc
	Lerner Lcsw Donna A
	Horisons Unlimited
	Ste 2 California Assn Realtors Inc
	SHANNON D LEDUC
5326	CURTIS WILCOX
5335	JIM LEONARD
	NOELLE OSTERHOUT
	SETH GOODMAN
5345	CALEB CHANEY
5346	ELLEN VERRINDER
5366	Califrnia Dept For Fire Prtcti
	Califrnia Dept For Fire Prtcti
	City Of Madera
5371	Thomas G Wieg
5379	Mariposa County Jail

STATE HWY 49 N

2022 Cole Information

5320	Ste 2 BOYER BUSINESS CENTER
	HABITAT FOR HUMANITY
	THOMAS WIEG DDS FACD
	Ste 1 HORISONS UNLIMITED
	SHANNON J LEDUC CPA
	Ste 5 YOSEMITE NETWORK
	Ste 3 GAIL WOODWARD
	Ste 1B YOSEMITE FORENSIC CONSULTANTS
	ERIC A OSTER CPA
	Ste 3 PROFESSIONAL GROUP
	ROCK 104
	Ste 7 HABITAT FOR HUMANITY INTERNATIONAL
	Ste 5 YOSEMITE WEDDINGS

STATE HWY 49 N

2022 (cont.) Cole Information

5320	Ste 2 ARIZONA BEST REAL ESTATE
	Ste 1 MARIPOSA COUNTY BOARD OF REALT
	Ste 2 MARIPOSA COUNTY BOARD OF REALTORS
5326	Curtis Wilcox
5335	Apt A Noelle Osterhout
5345	CALEB CHANEY ROOFING
	Caleb Chaney
5346	Ellen Verrinder
5366	STATE OF CALIFORNIA FORESTRY & FIRE PROTECTION DEPT
	TSR CONSULTING
	FORESTRY & FIRE PROTECTION
	MARIPOSA FOREST FIRE STATION
	MADERA COUNTY FIRE DEPARTMENT
	COUNTY OF MADERA
5371	KAREN WATANAKEEREE DDS
	YOSEMITE DENTAL CARE
5379	MARIPOSA COUNTY JAIL AND DETENTION FACILITY

STATE HWY 49 N

2017 Cole Information

5320	STEPHENS ROGER ENGINEERING
	HABITAT FOR HMNITY MRPOSA CNTY
5346	SANTIAGO GARCIA
5366	FORESTRY AND FIRE PROTECTION
5379	MARIPOSA COUNTY JAIL

STATE HWY 49 N

2017 Data Axle

5371	Unit A MOUNTAIN CRISIS SVC
	YOSEMITE DENTAL CARE
	WOODWARD, GAIL

FINDINGS

STATE HWY 49 N

2014 Cole Information

5320	Ste 3 HORISONS UNLIMITED
	BOYER BUSINESS CENTER
	WIEG THOMAS DDS FACD
	Ste 4 YOSEMITE MARIPOSA COUNTY TOURISM BUR
	STEPHENS ROGER ENGINEERING
	OSTER ERIC A CPA
	ROGER STEPHENS
	PEGGY SEARS
5335B	OCCUPANT UNKNOWN
5346	JESSE M VERRINDER
5366	TSR INC
	STATE OF CALIFORNIA
5371	MOUNTAIN CRISIS SERVICES
	OCCUPANT UNKNOWN

STATE HWY 49 N

2014 Data Axle

5336	JOB CONNECTION MARIPOSA
5379	MARIPOSA COUNTY JAIL

STATE HWY 49 N

2010 Cole Information

5320	Ste 5 YOSEMITE NETWORK
	Unit 6A OSTER ERIC A
	Ste 3 THOMAS WIEG INC
	Ste 4 YOSEMITEMARIPOSA COUNTY
	Ste 5 IRON MOUNTAIN
	Ste 2 MARIPOSA COUNTY BOARDREALTORS
	Ste 7 HABITAT FOR HUMANITY
	ROCK 104
	KENNETH F MARI
5335	OCCUPANT UNKNOWN

STATE HWY 49 N

2010 (cont.) Cole Information

5335	KEITH MCGUIRE
5345	CHANEY PAINTING
	CRAIG B CHANEY
5366	MARIPOSA FOREST FIRE STATION
	FORESTRY & FIRE PROTECTION
	MADERA COUNTY FIRE DEPT
5371	SPITZERS PHYSICAL THERAPY
	OCCUPANT UNKNOWN
5393	OCCUPANT UNKNOWN

STATE HWY 49 N

2010 Data Axle

5379	MARIPOSA COUNTY JAIL

STATE HWY 49 N

2005 Cole Information

5320	Ste 5 MARIPOSA YOSEMITE NET HSMC
	Ste 2 MARIPOSA COUNTY BOARD OF REALTORS IN
5335	OCCUPANT UNKNOWN
5345	CHANEY PAINTING
	CRAIG B CHANEY
5346	OCCUPANT UNKNOWN
5366	CA DEPT FORESTRY & FIRE PROTECTION
5371	YOSEMITE BANK ADMINISTRATIVE HEADQUA

STATE HWY 49 N

2005 Data Axle

5379	MARIPOSA COUNTY JAIL

FINDINGS

STATE HWY 49 N

2000 Cole Information

5320	STONECUTTER DESIGN
	DAHLEM STEVEN W ATTORNEY AT LAW
	Ste 1 DAHLEM STEVEN W ATTORNEY AT LAW
	IRON MOUNTAIN SYSTEMS NETWORK ACCESS
	IRON MOUNTAIN SYSTEMS
	WIEG THOMAS DDS
	STARCHMAN DONALD J ATTORNEY AT LAW
5366	MADERA CO FIRE DEPARTMENT
	CALIFORNIA STAT OF FOR & FIRE PROTECT DEPARTMENT
5371	YOSEMITE BANK ADMINISTRATIVE HEADQUARTERS

STATE HWY 49 N

2000 Data Axle

5379	MARIPOSA COUNTY JAIL

STATE HWY 49 N

1995 Cole Information

5320	MARI CONSTRUCTION
	STARCHMAN LAW OFFICES
	THOMAS WIEG DDS
	IRON MOUNTAIN SOFTWARE
	BOYERS TEMPORARY PERSONNEL
	BOYER BUSINESS CTR
5345	KEARNEY, BRYAN L
5346	LONG, ROBERT R
5366	MARIPOSA COUNTY ADMINISTRATION


STATE HWY 49 N

1992 Cole Information

5320	MARI CONSTRUCTION
	UNITD WAY MARIPOSA
5345	KEARNEY, BRYAN L
5346	HOULIHAN, JOHN T
5366	MARIPOSA CO FIRE
	CA ST FRSTRY&FIRE
5371	YOSEMITE BK HDQ

STATE HWY 49 N


1985 Haines



	5326	XXXX	00
3	5335	MACKINO MARY	966-2098 +5
5		OSBORNE DOLLY P	966-2057 +5
1	5345	EASLEY HOYLE	966-3114 9
1	5346	HOULIHAN JOHN T	966-2104 6
1	5352	CASARETTO A	742-6154 4
0	5366	CUTTER DAVID A	966-2548 0
5		MCCULLY JACK D	966-2582
5	5393	PETERSON JOHN A	966-5416 8

STATE HWY 49 N

1981 Haines



5326	XXXX	00
5328	XXXX	00
5345	EASLEY HOYLE	966-3114 9
5346	HOULIHAN JOHN T	966-2104 6
5352	MAYNARD SUSAN	966-5945 +1
5366	CUTTER DAVID A	966-2548 0
	MCCULLY JACK D	966-2582
5393	PETERSON JOHN A	966-5416 8

STATE HWY 49 N

1977 Haines




5326	STRICKLAND ROY	966-5478+7
5335	FOURNIER EUGENE	966-2133 6

FINDINGS

STATE HWY 49 N

1977 (cont.) Haines



```
5345 GIBBONS THOMAS E     966-2819 6
5346 HOULIHAN JOHN T      966-2104 6
5366 KILLEBREW THOMAS     966-2516+7
     MCCULLEY JACK D      966-2582
     WEATHERFORD FRANK    966-2181 6
```

STATE HWY 49 N

1974 Haines



```
5366 MCCULLEY JACK D      966-2582
     TURNER JAMES D       966-3988
```

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338

Inquiry Number: 8280255.3
March 12, 2026

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

03/12/26

Site Name:

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338
EDR Inquiry # 8280255.3

Client Name:

Provost & Pritchard Eng. Group
455 W. Fir Ave
Clovis, CA 93611
Contact: Stephanie Gillaspy

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Provost & Pritchard Eng. Group were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # F267-4048-959F

PO # 1542-26-001 ESA

Project Mariposa County

UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.

Sanborn® Library search results

Certification #: F267-4048-959F

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Provost & Pritchard Eng. Group (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2026 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338

Inquiry Number: 8280255.7
March 12, 2026

EDR Building Permit Report

Target Property and Adjoining Properties

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Building Permit Report: Search Documentation

3/12/26

Site Name:
Mariposa County
Frank Wilson Rd
Mariposa, CA 95338

EDR Inquiry # 8280255.7

Client Name:
Provost & Pritchard Eng.
455 W. Fir Ave
Clovis, CA 93611

Contact: Stephanie Gillaspy

Search Documentation

DATA GAP

The complete collection of Building Permit data available to EDR has been searched, and as of 3/12/26, EDR does not have access to building permits in the city where your target property is located (Mariposa, CA).

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED ORIMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THEMAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALLRISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OFERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL,INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLYLIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risklevels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providingany facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by anenvironmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to beconstrued as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.


Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILD FAX PROPERTY HISTORY

PARCELQUEST



© 2015 ParcelQuest www.parcelquest.com (888) 217-8999

PARCELQUEST
LIST 1
DETAIL

1 Property Address: *UNASSIGNED* MARIPOSA CA 95338

Ownership

County:	**MARIPOSA**
Assessor:	**TAMMIE GUENTHART**
Parcel # (APN):	**013-011-003-000**
Parcel Status:	**ACTIVE**
Owner Name:	**RITTER THOMAS & LORI TR**
Mailing Address:	**PO BOX 1965 MARIPOSA CA 95338**
Legal Description:	**2.31 ACRES**

Assessment

Total Value:	**$388,530**	Tax Rate Area:	**051-027**	PQ Zoning Code:	
Land Value:	**$388,530**	Year Assd:	**2025**	PQ Zoning Type:	
Impr Value:		Census Tract:		PQ Zoning Jurisdiction:	
Other Value:		Use Code:	**VCNT**	PQ Zoning Description:	
% Improved:	**0%**	Use Type:	**VACANT**		
Exempt Amt:					
Exempt Type:					

Sale History

	Sale 1	Sale 2	Sale 3	Transfer
Document Date:	**08/29/2007**	**01/18/2007**		**08/29/2007**
Document Number:	**2007R0000135**	**2007R0000354**		**2007R0000135**
Document Type:	**GRANT DEED**	**GRANT DEED**		
Transfer Amount:	**$290,000**	**$290,000**		
Price/SqFt:				
Seller (Grantor):				

Property Characteristics

Bedrooms:		Fireplace:		Units:	
Baths (Full):		A/C:		Stories:	
Baths (Half):		Heating:		Quality:	
Total Rooms:		Pool:		Building Class:	
Bldg/Liv Area:		Park Type:		Condition:	
Lot Acres:	**2.310**	Spaces:		Site Influence:	
Lot SqFt:	**100,623**	Garage SqFt:		Timber Preserve:	
Year Built:				Ag Preserve:	
Effective Year:					

Mariposa County
Frank Wilson Rd
Mariposa, CA 95338

Inquiry Number: 8280255.6
March 12, 2026

The EDR Property Tax Map Report

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Property Tax Map Report

Environmental Data Resources, Inc.'s EDR Property Tax Map Report is designed to assist environmental professionals in evaluating potential environmental conditions on a target property by understanding property boundaries and other characteristics. The report includes a search of available property tax maps, which include information on boundaries for the target property and neighboring properties, addresses, parcel identification numbers, as well as other data typically used in property location and identification.

NO COVERAGE

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2022 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Appendix E Site Reconnaissance Photographs



0 50 100

US Feet

Photo Location Map

Frank Wilson Road, Mariposa CA - Phase I ESA

PROVOST& PRITCHARD

3/31/2026 G:\Mariposa County-1542\154226001-Phase I Mariposa Co\400 GIS\Map\Phase1_Maps.aprx

PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
1

Date and Time:
3/31/2026 9:39:19 AM

Latitude: 37.501017

Longitude:
-119.984507

Description:
Looking southwest from off property. Overgrown and unknown end dumped pile of unknown materials.



PROVOST&
PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
2

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500948

Longitude:
-119.984784

Description:
Looking south



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
3

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500893

Longitude:
-119.984945

Description:
Adjacent to site looking at site. Unknown riser pipes off the property.



PROVOST&
PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
4

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500467

Longitude:
-119.985399

Description:
Looking east



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
5

Date and Time:
3/31/2026 9:39:19 AM

Latitude: 37.50044

Longitude:
-119.985429

Description: Looking east and plastic corrugated culvert drainage pipe



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
6

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500443

Longitude:
-119.98542

Description:
Drain at Lemee Ln and Frank Wilson Rd



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
7

Date and Time:
3/31/2026 9:39:19 AM

Latitude: 37.500436

Longitude:
-119.985433

Description: Storm Drain Out-fall (plastic corrugated culvert drainage pipe)



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
8

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500539

Longitude:
-119.984395

Description:
Looking northwest



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
9

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500357

Longitude:
-119.984644

Description:
Looking north



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
10

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500234

Longitude:
-119.984865

Description:
Looking east



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
11

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500234

Longitude:
-119.984805

Description:
Looking north



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
12

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500093

Longitude:
-119.984862

Description:
Looking south



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
13

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500091

Longitude:
-119.984806

Description:
Looking north



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
14

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500113

Longitude:
-119.984755

Description:
Looking west towards Lemme Rd



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
15

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500142

Longitude:
-119.984685

Description:
Former foundation



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
16

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.50015

Longitude:
-119.984664

Description:
Former foundation



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
17

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500162

Longitude:
-119.984645

Description:
Former foundation



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
18

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500147

Longitude:
-119.98466

Description:
Former foundation



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label: 19

Date and Time:
3/31/2026 9:39:19 AM

Latitude: 37.50013

Longitude:
-119.984435

Description: Telephone and possible pressure tank for potable water



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label: 20

Date and Time:
3/31/2026 9:39:19 AM

Latitude: 37.500276

Longitude:
-119.984245

Description:
South edge of property and back flow preventer for domestic water supply



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
21

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500282

Longitude:
-119.984235

Description:
Looking northwest



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
22

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500281

Longitude:
-119.984224

Description:
Looking northeast



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
23

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500315

Longitude:
-119.984288

Description:
Looking southeast



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
24

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500463

Longitude:
-119.98428

Description:
Looking northeast



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
25

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500459

Longitude:
-119.984277

Description:
Looking northwest



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
26

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500464

Longitude:
-119.984266

Description:
Looking west



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
27

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500691

Longitude:
-119.984458

Description:
Looking east



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
28

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500697

Longitude:
-119.984451

Description:
Looking southwest



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
29

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500702

Longitude:
-119.984458

Description:
Looking south



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
30

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.5007

Longitude:
-119.984466

Description:
Looking east



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
31

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.50062

Longitude:
-119.984568

Description:
Looking north



PROVOST&
PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label: 32

Date and Time:
3/31/2026 9:39:19 AM

Latitude: 37.500676

Longitude:
-119.984627

Description: Storm drain)plastic currugated culvert drain pipe.



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
33

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500626

Longitude:
-119.984745

Description:
Looking southwest



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
34

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500586

Longitude:
-119.985035

Description:
Looking south



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
35

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.5006

Longitude:
-119.985049

Description:
Looking west towards Highway 49



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
36

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500601

Longitude:
-119.985055

Description:
Looking east



PROVOST& PRITCHARD

Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
37

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.50033

Longitude:
-119.985156

Description:
Looking north



Mariposa County - Frank Wilson Road ESA

Site Assessment Photos

Point Label:
38

Date and Time:
3/31/2026 9:39:19 AM

Latitude:
37.500331

Longitude:
-119.985218

Description:
Looking east



Appendix F Interviews

Phase I ESA Owner or Occupant Questionnaire

PROVOST&PRITCHARD
CONSULTING GROUP

455 W Fir Ave, Clovis, CA 93611 • (559) 449-2700
www.provostandpritchard.com

PHASE I ENVIRONMENTAL SITE ASSESSMENT QUESTIONNAIRE—OWNER OR OCCUPANT

Date: 3-10-2026

Site Name/Address: Lemee Lane UNASSIGNED 013-011-003-000

Completed by Mr./Mrs.: MR&MRS Tom&Lori Ritter

Company: _____ Relation with Site: OWNERS

Address: 3137 Triangle Park Rd Mariposa Ca 95338

Telephone: 209 742 6613 E-mail: thomasritter1965@gmail.com

Someone better associated with site? NO Telephone: 209 742-5107
209 617-7754

INTERVIEW QUESTIONS

1) How long have you been associated with this site? 18 YRS

2) Are there structures on the site? For what purpose(s)? NO

3) What are the current and past site uses? During what time periods? NONE

4) Any aboveground or underground storage tanks associated with the site? (E.g. Fuel or Fertilizer tanks) If yes, the purpose? NO

5) Any hazardous materials use, storage, spills, or leaks (including used oil or antifreeze) currently or in the past? NO

6) Any past clean-up operations? Due to regulatory action or not? NO

7) Any current or past pesticide mixing facilities on the site? NO

8) Any buried materials (including buried trash, engine parts) or burn areas on the site? NO

9) Any irrigation wells, domestic wells, monitoring wells, or dry wells on the site (active or abandoned)? NO

PROVOST&PRITCHARD
CONSULTING GROUP

455 W Fir Ave, Clovis, CA 93611 • (559) 449-2700
www.**provost**and**pritchard**.com

10) Any waste treatment or discharges on the site? NO

11) Any septic tanks/leach fields? NO

12) City water or private well? NO City sewer or private septic? NO

13) Any disposal ponds or storm water retention basins? NO

14) Any adjacent property environmental concerns (E.g. Gas Stations, Industrial Facilities)? NO

Engineering • Structural • Geostructural • Surveying • Planning • Environmental • GIS • Construction Services • Hydrogeology • Consulting
Clovis • Visalia • Bakersfield • Modesto • Los Banos • Chico • Sacramento • Sonora • San Luis Obispo • Riverside • Camarillo • Boise, ID

THIS PAGE INTENTIONALLY LEFT BLANK