

From: [Tod Elliott](#)
To: [Laura Hall](#)
Subject: Belmont
Date: Tuesday, July 16, 2024 2:21:52 PM
Attachments: [IMG_2848.jpg](#)
[IMG_2849.jpg](#)
[IMG_2850.jpg](#)
[IMG_2851.jpg](#)
[IMG_2852.jpg](#)
[IMG_2853.jpg](#)
[IMG_2854.jpg](#)
[IMG_2855.jpg](#)
[IMG_2856.jpg](#)
[IMG_2857.jpg](#)
[IMG_2858.jpg](#)

Elliott 07-16-2024 site inspection

Observed was evidence of soil saturation, sprinklers and hoses on site with no detectable signs of sediment departure, erosion wattles had been installed around the perimeter of the downhill slopes of the project site. Perimeter fence elevation to the adjacent streets (east, west, and south side) of the project has been reduced to a 4' maximum. I have confirmed with Annje Dodd that prior of October 15th or 72 hours of any rain forecast event of 40% that further erosion control measures would need to be implemented around the perimeter; track out rock and concrete washout pit will need be required prior of the next phase of construction,



FIRE
EXIT
DO NOT BLOCK

Jul 16, 2024 at 9:18 AM











Jul 16, 2024 10:10 AM



2024年9月10日 9:10 AM





Jul 16, 2024 at 9:16 AM



Jul 14, 2024 at 9:16 AM

