

Project Name	Location	Date	Time of Noise Measurement
BELF 002	9903 Flower Street, Bellflower, CA 90706	May 21, 2025	1:30 PM
Noise Meter Readings (SORTED):	Comments	Maximum Value:	80.6
80.6		L99:	76.7
76.7		L90:	68.2
73.9		L75:	64.8
72.6		Median:	61.9
72.1		Minimum Value:	53.8
71.8		Average:	62.9
71.7			
71.1			
70.0			
68.2			
67.9			
67.8			
66.6			
65.9			
65.7			
65.5			
65.5			
65.5			
65.2			
65.2			
65.2			
65.0			
64.8			
64.8			
64.7			
64.6			
64.6			
64.2			
64.2			
64.0			
64.0			
64.0			
64.0			
64.0			
63.7			
63.6			
63.2			
63.0			
62.9			
62.8			
62.8			
62.8			
62.8			
62.8			
62.6			
62.4			
62.1			
62.0			
61.9			

61.9	
61.8	
61.8	
61.7	
61.6	
61.4	
61.4	
61.3	
61.2	
61.2	
61.1	
61.1	
61.1	
61.1	
60.8	
60.8	
60.8	
60.8	
60.7	
60.7	
60.7	
60.4	
60.4	
60.3	
60.1	
60.0	
60.0	
59.9	
59.9	
59.9	
59.7	
59.7	
59.6	
59.2	
59.2	
59.1	
59.0	
59.0	
58.9	
58.8	
58.8	
58.8	
58.6	
58.6	
58.5	
58.5	
58.5	
58.2	
57.8	
57.8	
53.8	