

PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT

9822 Russell Avenue
Garden Grove, California 92844

Report Date
July 8, 2025

Site Inspection Date
July 2, 2025

Partner Project No.
25-500978.1

Client Reference No.
500978

Prepared for:
Melia Homes
9860 Irvine Center Drive
Irvine, California 92618

July 8, 2025

Mr. Chad Brown
Melia Homes
9860 Irvine Center Drive
Irvine, California 92618

Subject: Phase I Environmental Site Assessment
9822 Russell Avenue
Garden Grove, California 92844
Partner Project No. 25-500978.1

Dear Chad Brown,

Partner Engineering and Science, Inc. (Partner) is pleased to provide this Phase I Environmental Site Assessment (Phase I ESA) report of the abovementioned address (the "subject property"). This assessment was performed in conformance with the scope and limitations as detailed in the ASTM Practice E1527-21 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process and Client Agreement.

This assessment included a site reconnaissance as well as research and interviews with representatives of the public, property ownership, site manager, and regulatory agencies. An assessment was made, conclusions stated, and recommendations outlined.

We appreciate your trust in Partner and the opportunity to provide environmental services to you. If you have any questions concerning this report, or if we can assist you in any other matter, please contact me at (949) 481-9818.

Sincerely,

Robert Vaughn
National Client Manager

EXECUTIVE SUMMARY

Partner Engineering and Science, Inc. (Partner) has performed a Phase I Environmental Site Assessment (ESA) in accordance with the scope of work and limitations of ASTM Practice E1527-21, the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (AAI) (40 CFR Part 312) and set forth by Melia Homes for the property located at 9822 Russell Avenue in Garden Grove, Orange County, California (the "subject property"). The Phase I Environmental Site Assessment is designed to provide Melia Homes with an assessment concerning environmental conditions (limited to those issues identified in the report) as they exist at the subject property.

Property Description

The subject property is located on the south side of Russell Avenue and east side of Kerry Street within a residential and commercial area of Orange County, California. Please refer to the table below for further description of the subject property:

SUBJECT PROPERTY DATA

Address(es):	9822 Russell Avenue, Garden Grove, California
Property Use:	Commercial
Land Acreage (Ac):	1.81
Number of Buildings:	Three
Number of Floors:	Church (One): Preschool (One and Two)
Gross Building Area (SF):	21,100
Net Rentable Area (SF):	21,100
Date of Construction:	Circa 1955
Parcel Number:	098-081-19
Type of Construction:	Wood-framed on a concrete slab-on-grade foundation
Current Tenants:	Iglesia de Cristo de Restauracion and Orangefield Child Development Center
Site Assessment Performed By:	Reese Davis of Partner
Site Assessment Conducted On:	July 8, 2025
Regulatory Radius Report Date:	June 16, 2025
Lien Search Date:	N/A
Report Date:	July 8, 2025
FOIAs Date:	June 2025
Groundwater Flow Direction (Inferred):	South
Estimated Depth to Groundwater (Feet bgs):	12 to 23

The subject property is currently occupied by Iglesia de Cristo de Restauracion and Orangefield Child Development Center. Onsite operations consist of a church and preschool. In addition to the current structures, the subject property is also improved with asphalt-paved parking areas, associated landscaping, a playground, and partial perimeter fencing.

According to available historical sources, the subject property was formerly unimproved land as early as 1896; agricultural land by 1938; and developed with the current structures by 1955. Tenants on the subject property have included various churches since the 1950s and a preschool since the 2010s.

The adjoining properties are tabulated below:

ADJOINING PROPERTIES

Direction	Land Use/Occupant
North:	Russell Avenue followed by an apartment complex (9801 and 9811 Russell Avenue), and three single-family residences (9831, 9841, and 9861 Russell Avenue)
Northeast:	Russell Avenue followed by a single-family residence (9871 Russell Avenue)
East:	Sunnyside Elementary School (9972 Russell Avenue)
Southeast:	Sunnyside Elementary School (9972 Russell Avenue)
South:	Single-family residence (13412 Kerry Street) and Orange County Chinese Christian Assembly Church (9881 Trask Avenue)
Southwest :	Intersection of Kerry Street and Dakota Avenue to the southwest followed by a single-family residence (9782 Dakota Avenue)
West:	Kerry Street, followed by two single-family residences (9781 and 9782 Russell Avenue)
Northwest:	Intersection of Russell Avenue and Kerry Street followed by a single-family residence (13352 Kerry Street)

Findings and Opinions

Recognized Environmental Condition

A recognized environmental condition (REC) refers to the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

- Partner did not identify any RECs during the course of this assessment.

Controlled Recognized Environmental Condition

A controlled recognized environmental condition (CREC) refers to a REC affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, activity and use limitations or other property use limitations).

- Partner did not identify any CRECs during the course of this assessment.

Historical Recognized Environmental Condition

A historical recognized environmental condition (HREC) refers to a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations).

- Partner did not identify any HRECs during the course of this assessment.

Business Environmental Risk

A Business Environmental Risk (BER) is a risk which can have a material environmental or environmentally driven impact on the business associated with the current or planned use of commercial real estate, not necessarily related to those environmental issues required to be investigated in this practice. The following was identified during the course of this assessment:

- Due to the age of the subject property buildings, there is a potential that asbestos-containing material (ACM) and lead-based paint (LBP) are present. Should these materials be replaced, the identified suspect ACMs would need to be sampled to confirm the presence or absence of asbestos prior to any renovation or demolition activities to prevent potential exposure to workers and building occupants.

Significant Data Gaps

No significant data gaps affecting the ability of the Environmental Professional to identify a REC were encountered during this assessment.

Conclusions and Recommendations

Partner has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E1527-21 of 9822 Russell Avenue in Garden Grove, Orange County, California (the "subject property"). Any exceptions to, or deletions from, this practice are described in Section 1.5 of this report.

This assessment has revealed no evidence of RECs, CRECs, or HRECs in connection with the subject property; however, one BER was identified. Based on the conclusions of this assessment, Partner recommends the following:

- An Operations and Maintenance (O&M) Program should be implemented in order to safely manage the suspect ACMs and LBP located at the subject property.

TABLE OF CONTENTS

1.0	INTRODUCTION.....	1
1.1	Purpose.....	1
1.2	Scope of Work.....	1
1.3	Limitations.....	2
1.4	User Reliance.....	2
1.5	Limiting Conditions.....	3
2.0	SITE DESCRIPTION.....	4
2.1	Site Location and Legal Description.....	4
2.2	Current Property Use.....	4
2.3	Current Use of Adjoining Properties.....	4
2.4	Physical Setting Sources.....	5
2.4.1	Topography.....	5
2.4.2	Hydrology.....	5
2.4.3	Geology/Soils.....	6
2.4.4	Flood Zone Information.....	7
3.0	HISTORICAL INFORMATION.....	8
3.1	Aerial Photograph Review.....	8
3.2	Fire Insurance Maps.....	9
3.3	City Directories.....	9
3.4	Historical Topographic Maps.....	14
4.0	REGULATORY RECORDS REVIEW.....	16
4.1	Regulatory Agencies.....	16
4.2	Mapped Database Records Search.....	20
4.2.1	Regulatory Database Summary.....	20
4.2.2	Subject Property Listings.....	22
4.2.3	Adjoining Property Listings.....	22
4.2.4	Surrounding Area Listings of Sites of Concern.....	22
4.2.5	Unplottable Listings.....	23
5.0	USER PROVIDED INFORMATION AND INTERVIEWS.....	24
5.1	Interviews.....	24
5.1.1	Interview with Owner.....	24
5.1.2	Interview with Report User.....	24
5.1.3	Interview with Key Site Manager.....	25
5.1.4	Interviews with Past Owners, Operators and Occupants.....	25
5.2	User Provided Information.....	25
5.2.1	Title Records, Environmental Liens, and AULs.....	25
5.2.2	Specialized Knowledge.....	25
5.2.3	Actual Knowledge of the User.....	25
5.2.4	Valuation Reduction for Environmental Issues.....	25
5.2.5	Commonly Known or Reasonably Ascertainable Information.....	25
5.2.6	Previous Reports and Other Provided Documentation.....	25
6.0	SITE RECONNAISSANCE.....	26
6.1	General Site Characteristics.....	26
6.1.1	Solid Waste Disposal.....	26
6.1.2	Sewage Discharge and Disposal.....	26
6.1.3	Stormwater and Surface Water Drainage.....	26
6.1.4	Source of Heating and Cooling.....	26

6.1.5	Wells and Cisterns.....	27
6.1.6	Wastewater.....	27
6.1.7	Septic Systems.....	27
6.1.8	Additional Site Observations.....	27
6.2	Potential Environmental Hazards.....	27
6.2.1	Hazardous Substances and Petroleum Products Used or Stored at the Site.....	27
6.2.2	Aboveground & Underground Hazardous Substance or Petroleum Product Storage Tanks (ASTs/USTs).....	27
6.2.3	Evidence of Releases.....	27
6.2.4	Polychlorinated Biphenyls (PCBs).....	27
6.2.5	Strong, Pungent or Noxious Odors.....	27
6.2.6	Pools of Liquid.....	27
6.2.7	Drains, Sumps and Clarifiers.....	27
6.2.8	Pits, Ponds and Lagoons.....	27
6.2.9	Stressed Vegetation.....	28
6.2.10	Additional Potential Environmental Hazards and Emerging Contaminants.....	28
6.3	Non-ASTM Services.....	28
6.3.1	Asbestos-Containing Materials (ACMs).....	28
6.3.2	Lead-Based Paint (LBP).....	29
6.3.3	Radon.....	29
6.3.4	Lead in Drinking Water.....	29
6.3.5	Microbial Growth.....	30
6.3.6	Wetlands.....	30
6.4	Adjoining Property Reconnaissance.....	30
6.4.1	Hazardous Substances and Petroleum Products Used or Stored at the Site.....	30
6.4.2	ASTs/USTs for Hazardous Substances or Petroleum Products.....	30
6.4.3	Evidence of Releases.....	30
6.4.4	PCBs.....	30
6.4.5	Strong, Pungent, or Noxious Odors.....	30
6.4.6	Pools of Liquid.....	31
6.4.7	Drains, Sumps, and Clarifiers.....	31
6.4.8	Pits, Ponds, and Lagoons.....	31
6.4.9	Stressed Vegetation.....	31
6.4.10	Additional Potential Environmental Hazards and Emerging Contaminants.....	31
7.0	VAPOR ENCROACHMENT CONDITIONS.....	32
8.0	FINDINGS AND CONCLUSIONS.....	33
9.0	SIGNATURES OF ENVIRONMENTAL PROFESSIONALS.....	35
10.0	REFERENCES.....	36

FIGURES

- Figure 1:** Site Location Map
Figure 2: Site Plan
Figure 3: Topographic Map

APPENDICES

- Appendix A:** Site Photographs
Appendix B: Historical/Regulatory Documentation

Appendix C: Regulatory Database Report
Appendix D: Qualifications

ACRONYM LIST

Ac	Acre
AAI	All Appropriate Inquiries
AMSD	Approximate Minimum Search Distance
AOC	Area of Concern
ACM	Asbestos Containing Material
APN	Assessor Parcel Number
AST	Aboveground Storage Tank
AUL	Activity and Use Limitation
AIRS	Aerometric Information Retrieval System
AFS	Air Facility System
ALT FUELS	Alternate Fueling Stations
ASTM	American Society for Testing and Materials
BGS	Below Ground Surface
BER	Business Environmental Risk
BRS	EPA Biennial Reporting System
COC	Chemical of Concern
CREC	Controlled Recognized Environmental Condition
CDL	Clandestine Drug Lab
CERCLIS	Comprehensive Environmental Response, Compensation and Liability Information System
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CESQG	Conditionally Exempt Small Quantity Generator
CORRACTS	RCRA Corrective Action Sites
ERIS	Environmental Risk Information Services
ERNS	Emergency Response Notification System
ECHO	Enforcement and Compliance History Online
FRP	Fiberglass Reinforced Plastic
FIM	Fire Insurance Map
FOIA	Freedom of Information Action
FINDS	Facility Index Database System
FRS	Facility Registry Service
FRP	Facility Response Plan
FIFRA	Federal Insecticide, Fungicide, and Rodenticide Act
FUDS	Formally Used Defense Site
FTTS	FIFRA/TSCA Tracking System
FTTS INSP	Inspection Case Listing
FUSRAP	Formerly Utilized Sites Remedial Action Program
FEMA	Federal Emergency Management Agency
HUD	U.S. Department of Housing and Urban Development
HSWA	Hazardous and Solid Waste Amendments
HVAC	Heating, Ventilation and Air Conditioning
HREC	Historical Recognized Environmental Condition
IODI	Open Dumps on Indian Lands
IHW	Industrial Hazardous Waste
IC/EC or INST/ENG	Institutional Control/Engineering Control
ICIS	Integrated Compliance Information System
LUCIS	Land Use Control Information System U.S. Department of the Navy
LQG	Large Quantity Generator
LPST	Leaking Petroleum Storage Tank
LST	Leaking Storage Tank
LUST	Leaking Underground Storage Tank

LBP	Lead-Based Paint
MSL	Mean Sea Level
MMMP	Mold, Moisture, and Mitigation Plan
MGP	Manufactured Gas Plant
MINES	Mines Master Index File
MLTS	Material Licensing Tracking System
HMIRS	Hazardous Materials Information Reporting System
MRDS	Mineral Resource Data System
NPL	National Priorities List
NCDL	National Clandestine Drug Labs
NPDES	National Pollutant Discharge Elimination System
NFRAP	No Further Remedial Action Planned
NonGen	Non Generator
NonGen/NLR	Non Generator/No Longer Regulated
ND	None Detected
NESHAP	National Emission Standards for Hazardous Air Pollutants
NWI	National Wetlands Inventory
NFA	No Further Action
N/A	Not Applicable
NOV	Notice of Violation
NTC	Notice To Comply
NRC	Nuclear Regulatory Commission
ODI	Inventory of Open Dumps
OWS	Oil-Water Separator
OSHA	Occupational Safety and Health Administration
O&M	Operations and Maintenance
PTO	Permit to Operate
Phase I ESA	Phase I Environmental Site Assessment
pCi/L	picoCuries per Liter
PHMSA	Pipeline and Hazardous Materials Safety Administration
PCB	Polychlorinated Biphenyl
PACM	Presumed Asbestos Containing Material
PFAS	Perfluoroalkyl and Polyfluoroalkyl Substances
PFOA	perfluorooctanoic acid
PFOS	Perfluorooctane sulfonic acid
REFN	Petroleum Refineries
PRP	Potentially Responsible Party
PST	Petroleum Storage Tank
ROD	Record of Decision
RGA	Recovered Government Archive
RCRA	Resource Conservation and Recovery Act
RCRIS	Resource Conservation Recovery Information System
REC	Recognized Environmental Condition
SF	Square Foot/Feet
SSA	Superfund Alternative Agreement
SSTS	Section Seven Tracking System
SQG	Small Quantity Generator
SMCRA	Office of Surface Mining Reclamation and Enforcement
SWF/LF	Solid Waste Facility/Landfill
SWRCY	Solid Waste Recycling Facility
SCRD	State Coalition for the Remediation of Drycleaners
SHWS	State Hazardous Waste Sites

SEMS	Superfund Enterprise Management Site
TANKS	Aboveground and Unregulated Tanks
TRIS	Toxic Chemicals Release Inventory System
TSCA	Toxic Substances Control Act
TSDF	Transfer, Storage and Disposal Facility
USDOE	United States Department of Energy
USDOT	United States Department of Transportation
USEPA	United States Environmental Protection Agency
USFWS	United States Fish and Wildlife Service
USGS	United States Geological Survey
UST	Underground Storage Tank
UIC	Underground Injection Control
VEC	Vapor Encroachment Condition
VSQG	Very Small Quantity Generator
VCP	Voluntary Cleanup Program

1.0 INTRODUCTION

Partner Engineering and Science, Inc. (Partner) has performed a Phase I Environmental Site Assessment (ESA) in conformance with the scope and limitations of ASTM Practice E1527-21 and the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (AAI) (40 CFR Part 312) for the property located at 9822 Russell Avenue in Garden Grove, Orange County, California (the “subject property”). Any exceptions to, or deletions from, this scope of work are described in the report.

1.1 Purpose

The purpose of this ESA is to identify existing or potential Recognized Environmental Conditions (as defined by ASTM Standard E1527-21) affecting the subject property that: 1) constitute or result in a material violation or a potential material violation of any applicable environmental law; 2) impose any material constraints on the operation of the subject property or require a material change in the use thereof; 3) require clean-up, remedial action or other response with respect to Hazardous Substances or Petroleum Products on or affecting the subject property under any applicable environmental law; 4) may affect the value of the subject property; and 5) may require specific actions to be performed with regard to such conditions and circumstances. The information contained in the ESA Report will be used by Client to: 1) evaluate its legal and financial liabilities for transactions related to foreclosure, purchase, sale, loan origination, loan workout or seller financing; 2) evaluate the subject property's overall development potential, the associated market value and the impact of applicable laws that restrict financial and other types of assistance for the future development of the subject property; and/or 3) determine whether specific actions are required to be performed prior to the foreclosure, purchase, sale, loan origination, loan workout or seller financing of the subject property.

This ESA was performed to permit the User to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on scope of Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. §9601) liability (hereinafter, the “landowner liability protections,” or “LLPs”). ASTM Standard E1527-21 constitutes “all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice” as defined at 42 U.S.C. §9601(35)(B).

1.2 Scope of Work

The scope of work for this ESA is in accordance with and to the extent necessary to achieve the goal of the requirements set forth in the ASTM Standard E1527-21. This assessment included: 1) a property and adjoining site reconnaissance; 2) interviews with key personnel; 3) a review of historical sources; 4) a review of regulatory agency records; and 5) a review of a regulatory database report provided by a third-party vendor. Partner contacted local agencies, such as environmental health departments, fire departments and building departments to obtain readily ascertainable information to determine any current and/or former hazardous substances usage, storage and/or releases of hazardous substances on the subject property. Additionally, Partner researched readily available information on the presence of activity and use limitations (AULs) at these agencies. As defined by ASTM E1527-21, AULs include both legal (that is, institutional) and physical (that is, engineering) controls that may include legal or physical restrictions or limitations on the use of, or access to, a site or facility: 1) to reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil, soil vapor, groundwater, or surface water on the subject property; or 2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. These legal or physical restrictions, which may include institutional and/or engineering controls (IC/ECs), are intended to prevent adverse impacts to individuals or populations that may be exposed to hazardous substances and petroleum products in the soil, soil vapor, groundwater, and/or surface water on a property.

If requested by Client, this report may also include the identification, discussion of, and/or limited sampling of asbestos-containing materials (ACMs), lead-based paint (LBP), mold, and/or radon.

1.3 Limitations

Partner warrants that the findings and conclusions contained herein were accomplished in accordance with the methodologies set forth in the Scope of Work. These methodologies are described as representing good commercial and customary practice for conducting an ESA of a property for the purpose of identifying recognized environmental conditions. There is a possibility that even with the proper application of these methodologies there may exist on the subject property conditions that could not be identified within the scope of the assessment or which were not reasonably identifiable from the available information. Partner believes that the information obtained from the record review and the interviews concerning the subject property is reliable. However, Partner cannot and does not warrant or guarantee that the information provided by these other sources is accurate or complete. The conclusions and findings set forth in this report are strictly limited in time and scope to the date of the evaluations. The conclusions presented in the report are based solely on the services described therein, and not on scientific tasks or procedures beyond the scope of agreed-upon services or the time and budgeting restraints imposed by the Client. No other warranties are implied or expressed.

Some of the information provided in this report is based upon personal interviews, and research of available documents, records, and maps held by the appropriate government and private agencies. This report is subject to the limitations of historical documentation, availability, and accuracy of pertinent records, and the personal recollections of those persons contacted.

This practice does not address requirements of any state or local laws or of any federal laws other than the all appropriate inquiry provisions of the LLPs. Further, this report does not intend to address all of the compliance and safety concerns, if any, associated with the subject property.

Environmental concerns, which are beyond the scope of a Phase I ESA as defined by ASTM include the following: ACMs, LBP, radon, and lead in drinking water. These issues may affect environmental risk at the subject property and may warrant discussion and/or assessment; however, are considered non-scope issues. If specifically requested by the Client, these non-scope issues are discussed in Section 6.3.

1.4 User Reliance

Melia Homes (herein referred to as Client) engaged Partner to perform this assessment in accordance with an agreement governing the nature, scope and purpose of the work as well as other matters critical to the engagement. All reports, both verbal and written, are for the sole use and benefit of Client. Either verbally or in writing, third parties may come into possession of this report or all or part of the information generated as a result of this work. In the absence of a written agreement with Partner granting such rights, no third parties shall have rights of recourse or recovery whatsoever under any course of action against Partner, its officers, employees, vendors, successors or assigns. Any such unauthorized user shall be responsible to protect, indemnify and hold Partner, Client and their respective officers, employees, vendors, successors and assigns harmless from any and all claims, damages, losses, liabilities, expenses (including reasonable attorneys' fees) and costs attributable to such Use. Unauthorized use of this report shall constitute acceptance of and commitment to these responsibilities, which shall be irrevocable and shall apply regardless of the cause of action or legal theory pled or asserted. Additional legal penalties may apply.

This report has been completed under specific Terms and Conditions relating to scope, relying parties, limitations of liability, indemnification, dispute resolution, and other factors relevant to any reliance on this report. Any parties relying on this report do so having accepted the Terms and Conditions for which this report was completed. A copy of Partner's standard Terms and Conditions can be found at <http://www.partneresi.com/terms-and-conditions.php>.

1.5 Limiting Conditions

The findings and conclusions contain all the limitations inherent in these methodologies that are referred to in ASTM Practice E1527-21.

Specific limitations and exceptions to this ESA are more specifically set forth below:

- Interviews with past or current owners, operators and occupants were not reasonably ascertainable and thus constitute a data gap. Based on information obtained from other historical sources, this data gap is not expected to alter the findings of this assessment.
- Partner was unable to determine the property use at 5-year intervals when the use of the subject property changed, which constitutes a data gap. Partner reviewed all standard historical sources and conducted appropriate interviews. This data gap is not expected to alter the findings of this assessment.

Due to time constraints associated with this report, the Client has requested the report despite the above-listed limitations.

2.0 SITE DESCRIPTION

2.1 Site Location and Legal Description

The subject property at 9822 Russell Avenue in Garden Grove, California is located on the south side of Russell Avenue and east side of Kerry Street. According to the Orange County Assessor, the subject property is legally described as S TWP 5 RGE 10 SEC 6 SEC 6 T 5 R 10 S 226 FT N 256 FT E 5 AC SW1/4. According to Orange County Assessor and Preliminary Title Report, ownership has been vested in Iglesia de Cristo de Restauracion since 2006.

Please refer to Figure 1: Site Location Map, Figure 2: Site Plan, Figure 3: Topographic Map, and Appendix A: Site Photographs for the location and site characteristics of the subject property.

2.2 Current Property Use

The subject property is currently occupied by Iglesia de Cristo de Restauracion and Orangefield Child Development Center. Onsite operations consist of a church and preschool. The subject property consists of three buildings: one church with a second-story mezzanine level and a preschool consisting of two buildings (one one-story and one two-story) located on the west and northwest side of the property. In addition to the current structures, the subject property is also improved with asphalt-paved parking areas, associated landscaping, a playground, and partial perimeter fencing.

The subject property is designated "R-1-7" for Single-Family Residential development by the City of Garden Grove, which is intended to provide for the establishment and promotion of single-family detached residences on individual lots and compatible associated activities. R-1-7 requires a minimum of 7,200 square feet lot area.

2.3 Current Use of Adjoining Properties

The subject property is located within a residential and commercial area of Orange County, California. During the vicinity reconnaissance, Partner observed the land uses on adjoining properties as defined in ASTM Practice E1527-21 as any real property or properties the border of which is contiguous or partially contiguous with that of the property, or that would be contiguous or partially contiguous with that of the property but for a street, road, or other public thoroughfare separating them. The adjoining properties are tabulated below:

ADJOINING PROPERTIES

Direction	Land Use/Occupant
North:	Russell Avenue followed by an apartment complex (9801 and 9811 Russell Avenue), and three single-family residences (9831, 9841, and 9861 Russell Avenue)
Northeast:	Russell Avenue followed by a single-family residence (9871 Russell Avenue)
East:	Sunnyside Elementary School (9972 Russell Avenue)
Southeast:	Sunnyside Elementary School (9972 Russell Avenue)
South:	Single-family residence (13412 Kerry Street) and Orange County Chinese Christian Assembly Church (9881 Trask Avenue)
Southwest :	Intersection of Kerry Street and Dakota Avenue to the southwest followed by a single-family residence (9782 Dakota Avenue)

ADJOINING PROPERTIES

West:	Kerry Street, followed by two single-family residences (9781 and 9782 Russell Avenue)
Northwest:	Intersection of Russell Avenue and Kerry Street followed by a single-family residence (13352 Kerry Street)

2.4 Physical Setting Sources

2.4.1 Topography

TOPOGRAPHIC DATA SUMMARY

Quadrangle Year:	2022
Quadrangle Name:	Anaheim, CA
Source:	USGS 7.5 Minute Topographic Map
Elevation (Feet):	74
Slope Direction:	Southwest
Slope Degree:	Gentle

A copy of the most recent topographic map is included as Figure 3 of this report.

2.4.2 Hydrology

While under natural and undisturbed conditions shallow groundwater flow most frequently follows the topography of the land surface, natural or man-made features can affect flow direction, and the presumed flow may not match the actual flow directions at the subject property and vicinity.

HYDROLOGY DATA SUMMARY

Groundwater Flow Direction:	South
Groundwater Flow Source:	A previous subsurface investigation conducted on a nearby property (Arco #629, 13482 Brookhurst- Case # 95UT062)
Estimated Depth to Groundwater (Feet bgs):	12 to 23
Estimated Depth Source:	A previous subsurface investigation conducted on a nearby property (Arco #629, 13482 Brookhurst- Case # 95UT062)
Closest Body of Surface Water Name:	East Garden Grove Wintersburg Channel
Closest Body of Surface Water Distance (Miles):	2
Closest Body of Surface Water Direction:	Southeast

HYDROLOGY DATA SUMMARY

Water System Operator:	City of Garden Grove Public Works Department, Water Services Division
Shallow Groundwater Use:	Not used for domestic purposes
Source of Drinking Water:	Surface water imported from the Metropolitan Water District of Southern California and groundwater from eleven (11) wells in the Orange County groundwater basin

2.4.3 *Geology/Soils*

GEOLOGY AND SOIL DATA SUMMARY

Physiographic Province:	The subject property is situated within the Peninsular Ranges Physiographic Province of California. This province is characterized by a series of ranges that are separated by longitudinal valleys, trending northwest to southeast, subparallel to faults branching from the San Andreas Fault.
Geologic Unit Description:	The uppermost geologic formation underlying the soils at the subject property is the Pleistocene to Holocene age Quaternary alluvium and marine deposits unit. This formation consists of coarse-detrital as the primary rock type, and the unit is described as alluvium, lake, playa, and terrace deposits that are unconsolidated and semi-consolidated.
Geologic Data Source:	United States Department of Agriculture (USDA) Natural Resources Conservation Service Web Soil Survey
Soil Series Name:	Metz loamy sand
Soil Series Description:	Metz loamy sand is a well-drained soil typically formed in alluvial deposits derived from granitic and sedimentary rock sources. It has a sandy texture with a loamy component that provides moderate water retention while allowing for rapid permeability. This soil type generally exhibits low shrink-swell potential and minimal runoff, making it less prone to erosion. Slopes range from 0 to 2 percent.

2.4.4 *Flood Zone Information*

FLOOD ZONE DATA SUMMARY

Source:	Federal Emergency Management Agency
Community Panel No.	06059C0139J

FLOOD ZONE DATA SUMMARY

FIRM Date:	December 3, 2009
Zone Designation:	Zone X (shaded); defined as moderate risk areas within the 0.2-percent-annual-chance floodplain, areas of 1-percent-annual-chance flooding where average depths are less than 1 foot, areas of 1-percent-annual-chance flooding where the contributing drainage area is less than 1 square mile, and areas protected from the 1-percent-annual-chance flood by a levee.

A copy of the reviewed flood map is included in Appendix B of this report.

3.0 HISTORICAL INFORMATION

Partner obtained historical use information about the subject property from a variety of sources. A chronological listing of the historical data found is summarized in the table below:

HISTORICAL USE INFORMATION

Years	Resource	Description/Use
1896-1935	Topographic Maps	Unimproved Land
1938-1953	Aerial Photographs, Topographic Maps	Agricultural Land
1955-Present	Aerial Photographs, City Directories, Client-Provided Information, Interviews, Topographic Maps	Church, Classroom Buildings; Tenants Include various churches since 1955 and pre-schools since at least 2010

Tenants on the subject property have included various churches since the 1950s and a preschool since the 2010s.

No potential environmental concerns were identified in association with the current or former use of the subject property.

3.1 Aerial Photograph Review

Partner obtained available aerial photographs of the subject property and surrounding area from Environmental Risk Information Services (ERIS) on June 18, 2025. The inferred uses of the subject property and adjoining properties as interpreted from the aerial photographs in Appendix B are tabulated below:

Date: **1938** Scale: **1"=500'**

Subject Property: Appears to be agricultural land

North: Appears to be agricultural land

East: Appears to be agricultural land

South: Appears to be agricultural land

West: Appears to be agricultural land

Date: **1947** Scale: **1"=500'**

Subject Property: No significant changes visible

North: Appears to be unimproved, vacant land

East: No significant changes visible

South: No significant changes visible

West: No significant changes visible

Date: **1953**

Scale: **1"=500'**

Subject No significant changes visible
Property:

North: Appears to be partially developed with residences

East: Appears to be partially developed with the current elementary school

South: No significant changes visible

West: No significant changes visible

Date: **1963, 1972, 1981, 1987, 1995, 2005, 2009, 2010, 2012, 2014, 2016, 2018, 2020, 2022, 2024**

Scale: **1"=500'**

Subject Appears to be developed with the current buildings
Property:

North: Appears to be residentially developed across a street

East: Appears to be developed with the current elementary school

South: Appears to be developed with a residence and the current church building

West: Appears to be residentially developed across a street

Copies of select aerial photographs are included in Appendix B of this report.

3.2 Fire Insurance Maps

Partner reviewed the collection of fire insurance maps (FIMs) from ERIS on June 15, 2025. FIM coverage was not available for the subject property.

A copy of the no coverage letter is included in Appendix B of this report.

3.3 City Directories

Partner reviewed historical city directories obtained from ERIS on June 23, 2025 for past names and businesses that were listed for the subject property and adjoining properties. The findings are tabulated below:

SUBJECT PROPERTY SUMMARY

City Directory Search for 9822 Russell Ave (Subject Property)

Year(s)	Occupant Listed
1955	G Gr Church of Christ
1958	G Gr Church of Christ
1964	Church of Christ
1967	Church of Christ
1970	Church of Christ Christian
1975	Church of Christ

1981	Gardn Grv Ch God
1986	Cornerstone Christn 537 4850, Gardn Gry Chrsth Ch 537 4190
1991	Bethel Missionry Ch, Gardn Grv Chrstn Ch, Cornerstone Christn
1996	Cornerstone Christn, Gardn Grv Chrstn Ch
2001	Cornerstone Christn, Cross County Vtnmse Chrstn Ch, Cross County Christian Church
2003	Bethel Missionary Church, Cross County Vietnamese Chrstn, Cross County Christian Church
2008	Iglesia De Cristo MIlf
2012	Sunflower Preschool
2016	Sunflower Preschool, Development Center Orange, Iglesia De Cristo MIlf
2020	Sunflower Preschool, Development Center Orange, Iglesia De Cristo MIlf
2023	Sunflower Preschool, Development Center Orange, Iglesia De Cristo MIlf
2024	Sunflower Preschool, Development Center Orange, Iglesia De Cristo MIlf

Based on the city directory review, no environmentally sensitive listings were identified for the subject property address(es).

ADJOINING PROPERTY SUMMARY

City Directory Search for 9801 Russell Ave (Adjoining Property)

Year(s)	Occupant Listed
1958	Apartment
1964	Apartment, Lanpherie D
1967	Faust M, Braughton C, Irwin W F, Clifton S, Building
1981	Singh Gora, Telles Danl J, Kean Daniel K, Nguyen Nuong
1986	Singh Gora 638 1174, Nguyễn Hoa Thi 636 1381, Nguyễn Nuong 638 7594
1991	Nguyen Van
1996	Nguyen Van, Phạm Dinh
2001	Bui Lan, Bernth Harold, Lương Hoa
2003	Dinh Pham
2008	Lan Bui, Hien Luong
2016	Nina Le, Trung Luong, Todd Le
2020	Nina Le
2023	Nina Le
2024	Hardwin Huynh

City Directory Search for 9811 Russell Ave (Adjoining Property)

Year(s)	Occupant Listed
1958	Apartment, Ayersman Raymond E, Humlie J Virginia, Taylor Kenneth E
1964	Apartment, A□ Lautenschlager T, Giraldi M J, Riddle R L
1967	Hill T, Carlsen M J, Apartment
1970	Bruce Wm L Jr, Emmons Lynn A
1981	Bui Muon Van, Nguyen Thanh
1986	Bui Muon Van 534 0436, Nguyễn Nga Ghi 636 2113, Nguyễn Thanh 636 4347, Dang Thuoi T 638 9357
1991	Dang Thuoi T
1996	Dang Thuoi T, Nguyễn Trung M
2001	Dang Thuoi T
2003	Thuoi Thi Dang
2008	Thuoi T Dang
2016	Lan Nguyen, Jacqueline Nguyen, Jimmy Huynh
2020	Lan Nguyen, Jacqueline Nguyen, Jimmy Huynh
2023	Lan Nguyen, Jacqueline Nguyen, Jimmy Huynh
2024	Allen Luong, Jacqueline Nguyen

City Directory Search for 9831 Russell Ave (Adjoining Property)

Year(s)	Occupant Listed
1958	Apartment, Jeffers James J, Coffino Rita
1964	Aparthent, Canterbury H L, Kaletka H W, Magness We
1967	Pena H, Wilson B J, Riley M J, Apartment
1970	Gray Lenore, Riley Mary Jane
1975	Fox Steven
1981	Rudden K
1986	Audden K 534 8096, Tran Charlie 537 0823
1991	Bui Laura, Đặng Hung Phi, Hồ Thanh Van
1996	Lê Dung Dinh
2001	Tan Ca, • Đình Hoà, Nguyen Chin H, Nguyễn Ho, Huynh Nhan, Chung Don
2008	Ca Tan, Nhuan N Huynh

2020	Dat Trieu
2023	Dat Trieu

City Directory Search for 9841 Russell Ave (Adjoining Property)

Year(s)	Occupant Listed
1955	Henley Albert
1958	Henley Albert
1964	Carnes D, Henley Albert
1967	Carnes D, Henley Albert
1981	Pfaff Walter H
1986	Pfaff Walter H 638 9127
1991	Xxxx
1996	Xxxx
2001	Kim Hạng
2012	Marvin Kim
2016	Nathan Kim
2020	Nathan Kim
2023	Nathan Kim

City Directory Search for 9861 Russell Ave (Adjoining Property)

Year(s)	Occupant Listed
1955	Final C E
1958	Final C E
1964	Hayne a Jr
1967	Schultz H
1970	Miller Dan
1975	Krogman Danl L
1981	Krogman Danl L
1986	Krogman Danl L 534 8411
1991	Krogman Dan L
1996	Krogman Dan ! L
2001	Krogman Dani L
2008	Daniel L Krogman

2012 Jorge Aguilar, Roberto Lozano, Jose Hernandez

City Directory Search for 9972 Russell Ave (Adjoining Property)

Year(s)	Occupant Listed
1955	Sunnyside School
1958	Sunnyside School
1964	Sunnyside Elem Schl
1975	Southwest Garden Grove Little League
1981	Dowling David L, Southwest Grdn Grve, Sunnyside Elem Sc
1986	Sunnyside Elem Sc 538 6158, Southwest Grdn Grve 638 0463
1991	Sunnyside Elem Sc, Southwest Grdn Grve
1996	Sunnyside Elem Sc, Southwest Grdn Grv
2001	Sunnyside Elementary School, Southwest Gardn 71 Grv Little Lge
2003	Southwest Gg Little League, Sunnyside Elementary School
2008	Sunnyside Elementary School
2012	Sunnyside Elementary School
2016	Sunnyside Elementary School
2020	Sunnyside Elementary School
2023	Sunnyside Elementary School
2024	Sunnyside Elementary School

City Directory Search for 9881 Trask Ave (Adjoining Property)

Year(s)	Occupant Listed
1964	Presbyterian Church
1967	Presbyterian Church
1970	Orthodox Presbyterian Church
1975	Orthodox Presbyterian Church
1981	Presbytern Oath Ch, Orthdox Prsbytrn Ch
1986	Gardn Gry Ortho Ch, Presbyterian Ort Ch, Peninsula Chrstn Sc
1991	Gardn Grv Ortho Ch, Presby Orthodox Ch, Peninsula Chrstn Sc
1996	Gardn Grv Ortho Ch, Presby Orthodox Ch, Peninsula Chrstn Sc
2001	Orange Co Chnse Chrstn Asmbly
2003	Kings Mission, Orange County Chinese Christin

2008	Orange County Chinese Church
2012	Orange County Church
2016	Orange County Church
2020	Orange County Church
2023	Orange County Church
2024	Orange County Church

Based on the city directory review, no environmentally sensitive listings were identified for the adjoining property addresses.

Copies of reviewed city directories are included in Appendix B of this report.

3.4 Historical Topographic Maps

Partner reviewed historical topographic maps obtained from ERIS on June 15, 2025. The following inferred uses of the subject property and adjoining properties interpreted from topographic maps in Appendix B and are tabulated below:

Date: **1896, 1898, 1901, 1935, 1942, 1949, 1950**

Subject	No structural development depicted
Property:	
North:	No structural development depicted
East:	No structural development depicted
South:	No structural development depicted
West:	No structural development depicted

Date: **1965, 1972, 1981**

Subject	Depicted as developed with three building structures labeled as a church
Property:	
North:	Shaded to depict urban development, across Russell Avenue
East:	Developed with a small cluster of buildings labeled "Sunnyside School"
South:	Partially shaded to depict urban development; one building is also depicted, labeled as a church
West:	Shaded to depict urban development, across Kerry Street

Date: **2015, 2018, 2022**

Subject	No site-specific features are depicted
Property:	
North:	Only roadways are shown and no site-specific features are depicted
East:	Only roadways are shown and no site-specific features are depicted
South:	Only roadways are shown and no site-specific features are depicted

West: Only roadways are shown and no site-specific features are depicted

Copies of reviewed topographic maps are included in Appendix B of this report.

4.0 REGULATORY RECORDS REVIEW

4.1 Regulatory Agencies

State Department

REGULATORY AGENCY DATA

Name of Agency: California Environmental Protection Agency (CalEPA)
Point of Contact: 1001 I Street, Sacramento, CA 95814
Agency Address: 1001 I Street, Sacramento, CA 95814
Agency Phone Number: (916) 323-2514
Date of Contact: June 25, 2025
Method of Communication: Online Research

Summary of Communication:

No records regarding hazardous substance use, storage or releases, or the presence of USTs and AULs on the subject property were on file with the CalEPA.

Health Department

REGULATORY AGENCY DATA

Name of Agency: Orange County Health Care Agency (OCHCA)- Environmental Health Division
Point of Contact: Public Record Request
(<https://orangecounty.nextrequest.com/requests/new>)
Agency Address: 1241 E. Dyer Road, Suite 120, Santa Ana, CA 92701
Agency Phone Number: 714-433-6000
Date of Contact: June 25, 2025
Method of Communication: Online Request Form

Summary of Communication:

As of the date of this report, Partner has not received a response from the OCHCA for inclusion in this report.

Fire Department

REGULATORY AGENCY DATA

Name of Agency: Orange County Fire Authority (OCFA)- Community Risk Reduction
Point of Contact: OCFA Email (CRTK@ocfa.org)
Agency Address: 1 Fire Authority Road, Irvine, CA 92602
Agency Phone Number: 714-573-6040

Date of Contact: June 25, 2025

Method of Communication: Online Request Form

Summary of Communication:

The OCFA provided Partner with a Fire Safety Inspection form dated June 3, 2025. The inspection noted two permits: Permit AL1R for "Liquefied Petroleum Gas Reissuance" and "Permit AP23R for "Assembly, >300 Occupants- Reissuance". No violations were noted.

Building Department

REGULATORY AGENCY DATA

Name of Agency: Garden Grove Building and Safety Department

Point of Contact: Building Permits Archive
(<https://ch.ggcity.org/permits/permits/search>)

Agency Address: 11222 Acacia Parkway, Garden Grove, CA 92840

Agency Phone Number: 714-741-5307

Date of Contact: June 25, 2025

Method of Communication: Online Research

Summary of Communication:

Records were available for review, as further discussed in the following table.

Building Records Reviewed for 9822 Russell Avenue (Subject Property)

Year(s)	Owner/Occupant/Address	Description
1980	9822 Russell Avenue	Permit - PLUMBING
1980	9822 Russell Avenue	Permit - BUILDING ALTERATIONS TO OTHER BUILDINGS
1980	9822 Russell Avenue	Permit - ELECTRIC
1981	9822 Russell Avenue	Permit - HEATING/AC
1981	9822 Russell Avenue	Permit - ALTERATIONS TO OTHER BUILDINGS. BUILDING ALTERATIONS TO OTHER BUILDINGS
1981	9822 Russell Avenue	Permit - Electrical
1981	9822 Russell Avenue	Permit - PLUMBING
1983	9822 Russell Avenue	Permit - BUILDING ALTERATIONS TO OTHER BUILDINGS
1987	9822 Russell Avenue	Permit - BUILDING REPAIRS
1989	9822 Russell Avenue	Permit - REPAIRS, REROOF W/COMP SHINGLES
1994	9822 Russell Avenue	Building Permit - MISCELLANEOUS.

		DIRECTIONAL SIGN
2011	9822 Russell Avenue	Permit- WROUGHT IRON FENCE BETWEEN (E)WOOD COLUMNS 110' X 5' IN FRONT OF PARKING AREA AT PRESCHOOL
2019	9822 Russell Avenue	Banner Permit - for Orangefield Child Development Center, not to exceed 60 days per year
2019	9822 Russell Avenue	Banner Permit/Special Event Sales Permit

Planning Department

REGULATORY AGENCY DATA

Name of Agency: Planning Department
Point of Contact: Online Zoning Map (<https://ggcity.org/maps/zoning-land-use/>)
Agency Address: 11222 Acacia Parkway, Garden Grove, CA 92840
Agency Phone Number: 714-741-5312
Date of Contact: June 25, 2025
Method of Communication: Online Research

Summary of Communication:

According to reviewed online documents, the subject property is zoned "R-1-7" for Single-Family Residential development by the City of Garden Grove, which is intended to provide for the establishment and promotion of single-family detached residences on individual lots and compatible associated activities. R-1-7 requires a minimum of 7,200 square feet lot area.

Oil & Gas Exploration

REGULATORY AGENCY DATA

Name of Agency: California Geologic Energy Management Division (CalGEM)
Point of Contact: Well Finder
(<https://maps.conservation.ca.gov/doggr/wellfinder/>)
Agency Address: 715 P Street, MS 1900, Sacramento, CA 95814
Agency Phone Number: (916) 445-9686
Date of Contact: June 25, 2025
Method of Communication: Online Research

Summary of Communication:

According to CalGEM, no oil or gas wells are located on or adjoining to the subject property.

Assessor's Office

REGULATORY AGENCY DATA

Name of Agency: Orange County Assessor
Point of Contact: Parcel Quest (<https://assr.parcelquest.com/Home>)
Agency Address: 500 South Main Street, 2nd Floor, Orange, CA 92868
Agency Phone Number: 714-834-2727
Date of Contact: June 25, 2025
Method of Communication: Online Research

Summary of Communication:

According to records reviewed, the subject property is identified by APN 098-081-19, totals 1.806-acres, and was last sold in 2006.

Air Pollution Control Agency

REGULATORY AGENCY DATA

Name of Agency: South Coast Air Quality Management District (SCAQMD)
Point of Contact: Online Database
(<https://scaqmd-online.maps.arcgis.com/apps/webappviewer/index.html?id=70dd0045e66243488b3f1ae32405cc0a>)
Agency Address: 21865 Copley Drive, Diamond Bar, CA 91765
Agency Phone Number: 909-396-2000
Date of Contact: June 25, 2025
Method of Communication: Online Research

Summary of Communication:

No Permits to Operate (PTO), Notices of Violation (NOV), or Notices to Comply (NTC) or the presence of AULs, dry cleaning machines, or USTs were on file for the subject property with the AQMD.

Regional Water Quality Agency

REGULATORY AGENCY DATA

Name of Agency: Regional Water Quality Control Board (RWQCB)- Santa Ana Region
Point of Contact: GeoTracker (<https://geotracker.waterboards.ca.gov/>)
Agency Address: 3737 Main Street, Suite 500, Riverside, CA 92501
Agency Phone Number: (951) 782-4130
Date of Contact: June 25, 2025
Method of Communication: Online Research

Summary of Communication:

No records regarding hazardous substance use, storage or releases, or the presence of USTs and AULs on the subject property were on file with the RWQCB.

Department of Toxic Substances Control

REGULATORY AGENCY DATA

Name of Agency:	Department of Toxic Substances Control (DTSC)
Point of Contact:	HWTS Database (https://hwts.dtsc.ca.gov/search) EnviroStor Database https://www.envirostor.dtsc.ca.gov/public/
Agency Address:	1001 I Street, Sacramento, CA 95814
Agency Phone Number:	916-551-1313
Date of Contact:	June 25, 2025
Method of Communication:	Online Research

Summary of Communication:

The DTSC Hazardous Waste Tracking System (HWTS) was researched for hazardous waste manifest data submitted to the California DTSC. No listings were identified for the subject property. The EnviroStor database is the DTSC's data management system for tracking cleanup, permitting, enforcement, and investigation efforts at hazardous waste facilities and sites with known contamination or sites where there may be reason to investigate further. No records were identified for the subject property address on the EnviroStor database.

Copies of pertinent documents are included in Appendix B of this report.

4.2 Mapped Database Records Search

The regulatory database report provided by ERIS documents the listing of sites identified on federal, state, county, city, and tribal (when applicable) standard source environmental databases within the approximate minimum search distance (AMSD) specified by ASTM Practice E1527-21. The data from these sources are updated as these data are released and integrated into one database. The information contained in this report was compiled from publicly available sources.

The environmental database information is used to identify environmental concerns in connection with the subject property. The listings also serve to identify the known indications of the storage, use, generation, disposal, or release of hazardous substance at the subject property and the potential for contaminants to migrate onto the subject property from off-site sources in groundwater or soil in the form of liquids or vapor.

Using the ASTM definition of migration, Partner considers the migration of hazardous substances or petroleum products in any form onto the subject property during the evaluation of each site listed on the radius report, which includes solid, liquid, and vapor.

4.2.1 Regulatory Database Summary

The following table lists the sites as categorized by the regulatory database within the prescribed AMSD. The locations of the sites are plotted utilizing a geographic information system, which geocodes the site addresses. The accuracy of the geocoded locations is approximately +/-300 feet.

DATABASE REPORT DATA

Database	AMSD Radius (mile)	Subject Property	Listings Identified	
			Adjoining Properties	Surrounding Area Sites of Concern
Federal NPL	1.00	N	N	N
Delisted NPL Site	0.50	N	N	N
Federal SEMS Site	0.50	N	N	N
Federal SEMS-ARCHIVE	0.50	N	N	N
Federal RCRA CORRACTS Facility	1.00	N	N	N
Federal RCRA TSDF Facility	0.50	N	N	N
Federal RCRA Generators Site (LQG, SQG, VSQG, CESQG)	Subject and Adjoining	N	N	N
Federal IC/EC Registries	Subject Property	N	N	N
Federal ERNS Site	Subject Property	N	N	N
Federal PFAS Facility	0.50	N	N	N
State/Tribal Equivalent NPL	1.00	N	N	N
State/Tribal Equivalent CERCLIS	1.00	N	N	N
State/Tribal Landfill/Solid Waste Disposal Site	0.50	N	N	N
State/Tribal Leaking Storage Tank Site (LUST/LPST)	0.50	N	N	N
State/Tribal Registered Storage Tank Sites (UST/AST)	Subject and Adjoining	N	N	N
State/Tribal IC/EC Registries	Subject and Adjoining	N	N	N
State/Tribal Voluntary Cleanup Sites (VCP)	0.50	N	N	N

State/Tribal Spills	0.25	N	N	N
Federal Brownfield Sites	0.50	N	N	N
State Brownfield Sites	0.50	N	N	N
State PFAS Facility	0.50	N	N	N
RCRA Non-Generators (RCRA NON GEN)	Subject and Adjoining	N	Y	N

4.2.2 **Subject Property Listings**

The subject property was not identified in the regulatory database report.

4.2.3 **Adjoining Property Listings**

One adjoining property to the east of the subject property was identified as an RCRA Non-Generator (RCRA NON GEN) site in the regulatory database report, as discussed below:

ADJOINING PROPERTY DATABASE LISTING

Property Name:	Sunnyside Elementary School
Address:	9972 Russell Avenue
Direction:	East
Hydrological Gradient:	Cross-Gradient
Database Listing:	RCRA NON GEN
Substance Involved:	Asbestos

Discussion

:

The adjoining Sunnyside Elementary School is listed in the RCRA NON GEN database under USEPA identification number CAC003292523, classifying it as a verified non-generator of hazardous waste in 2024. According to the California Department of Toxic Substances Control Hazardous Waste Tracking System database, the recorded waste generated was asbestos in 2014. The removal and proper handling of asbestos is a routine and regulated activity that does not represent an environmental concern when conducted in accordance with applicable standards. Based on the absence of reported violations, spills, or releases, the presence of regulatory oversight, and the limited historical waste generation, this listing is not expected to represent a significant environmental concern for the subject property, and it is unlikely that a regulatory file review for this site would alter the findings of this assessment.

Based on the findings, vapor migration is not considered an environmental concern at this time.

4.2.4 **Surrounding Area Listings of Sites of Concern**

No sites of concern are identified in the regulatory database report.

Based on the findings, vapor migration is not considered an environmental concern at this time.

4.2.5 *Unplottable Listings*

No unplottable listings of concern are identified in the regulatory database report.

A copy of the regulatory database report is included in Appendix C of this report.

5.0 USER PROVIDED INFORMATION AND INTERVIEWS

In order to qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the *Brownfields Amendments*), the *User* must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. The *User* should provide the following information to the *environmental professional*. Failure to provide this information could result in a determination that *all appropriate inquiries* is not complete. The *User* is asked to provide information or knowledge of the following:

- Review Title and Judicial Records for Environmental Liens and AULs
- Specialized Knowledge or Experience of the User
- Actual Knowledge of the User
- Reason for Significantly Lower Purchase Price
- Commonly Known or *Reasonably Ascertainable* information
- Degree of Obviousness
- Reason for Preparation of this Phase I ESA

Fulfillment of these user responsibilities is key to qualification for the identified defenses to CERCLA liability. Partner requested our Client to provide information to satisfy User Responsibilities as identified in Section 6 of the ASTM guidance.

Pursuant to ASTM Practice E1527-21, Partner requested the following site information from Melia Homes (User of this report).

USER RESPONSIBILITIES

Item	Provided By User
AAI User Questionnaire	Yes
Title Records, Environmental Liens, and AULs	Yes
Specialized Knowledge	No
Actual Knowledge	No
Valuation Reduction for Environmental Issues	No
Identification of Key Site Manager	Yes
Reason for Performing Phase I ESA	Yes
Prior Environmental Reports	No

5.1 Interviews

5.1.1 Interview with Owner

The owner of the subject property since 2006, identified as Iglesia de Cristo de Restauracion, was not available to be interviewed at the time of the assessment.

5.1.2 Interview with Report User

Chad Lonski, report user, was not aware of any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the subject property; any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products

in, on, or from the subject property; or any notices from a governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.

5.1.3 Interview with Key Site Manager

Ms. Yolanda Martinez, key site manager, indicated that they had no information pertaining to any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the subject property; any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the subject property; or any notices from a governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.

The key site manager further stated that there are no USTs, ASTs, clarifiers, oil/water separators, groundwater monitoring wells, or hazardous substance use/storage/generation on the subject property to the best of their knowledge.

5.1.4 Interviews with Past Owners, Operators and Occupants

Interviews with past owners, operators, and occupants were not conducted since information regarding the potential for contamination at the subject property was obtained from other sources.

5.2 User Provided Information

5.2.1 Title Records, Environmental Liens, and AULs

Partner was provided with a Preliminary Title Report for review as part of this assessment prepared by Fidelity National Title Company for the subject property.

Copies of pertinent pages are included in Appendix B of this report.

5.2.2 Specialized Knowledge

The User did not have specialized knowledge of environmental conditions associated with the subject property at the time of the assessment.

5.2.3 Actual Knowledge of the User

The User was not aware of environmental liens and/or AULs encumbering the subject property or in connection with the subject property at the time of the assessment.

5.2.4 Valuation Reduction for Environmental Issues

The User was not aware of any reductions in property value due to environmental issues.

5.2.5 Commonly Known or Reasonably Ascertainable Information

The User did not provide information that is commonly known or reasonably ascertainable within the local community about the subject property at the time of the assessment.

5.2.6 Previous Reports and Other Provided Documentation

No previous reports or other pertinent documentation was provided to Partner for review during the course of this assessment.

6.0 SITE RECONNAISSANCE

The weather at the time of the site visit was mostly sunny. Refer to Section 1.5 for limitations encountered during the field reconnaissance and Sections 2.1 and 2.2 for subject property operations. The table below provides the site assessment details:

SITE ASSESSMENT DATA

Site Assessment Performed By: Reese Davis

Site Assessment Conducted On: July 2, 2025

The table below provides the subject property personnel interviewed during the field reconnaissance:

SITE VISIT PERSONNEL FOR 9822 RUSSELL AVENUE (SUBJECT PROPERTY)

Name	Title/Role	Contact Number	Site Walk*
Yolanda Martinez	Iglesia de Cristo de Restauracion	714-537-0235	Yes

* Accompanied Partner during the field reconnaissance activities and provided information pertaining to the current operations and maintenance of the subject property

No potential environmental concerns were identified during the onsite reconnaissance.

6.1 General Site Characteristics

6.1.1 Solid Waste Disposal

Solid waste generated at the subject property is disposed of in a commercial dumpster located on the south side of the subject property. An independent solid waste disposal contractor, Republic Services, removes solid waste from the subject property. Solid waste generated at the subject property includes household-type waste. No evidence of illegal dumping of solid waste was observed during the Partner site reconnaissance.

6.1.2 Sewage Discharge and Disposal

Sanitary discharges on the subject property are directed into the municipal sanitary sewer system. The City of Garden Grove Public Works Department services the subject property vicinity. No wastewater treatment facilities were observed or reported on the subject property. No septic systems were observed or reported on the subject property.

6.1.3 Stormwater and Surface Water Drainage

Stormwater is removed from the subject property primarily by sheet flow action across the paved surfaces towards stormwater drains located in the public right of way and via ground infiltration on the subject property. No drywells were identified on the subject property.

6.1.4 Source of Heating and Cooling

Heating and cooling systems as well as domestic hot water equipment are fueled by electricity and natural gas provided by Southern California Edison (SCE). The mechanical system is comprised of natural gas furnaces and wall-mounted electrical air conditioning units. Hot water is provided by individual natural gas water heaters.

6.1.5 Wells and Cisterns

No aboveground evidence of wells or cisterns was observed during the site reconnaissance.

6.1.6 Wastewater

Domestic wastewater generated at the subject property is disposed by means of the sanitary sewer system. No industrial processes are currently performed at the subject property.

6.1.7 Septic Systems

No septic systems were observed or reported on the subject property.

6.1.8 Additional Site Observations

No additional general site characteristics were observed during the site reconnaissance.

6.2 Potential Environmental Hazards

6.2.1 Hazardous Substances and Petroleum Products Used or Stored at the Site

No evidence of the use of reportable quantities of hazardous substances was observed on the subject property.

Small quantities of general maintenance supplies were found to be properly labeled and stored at the time of the assessment with no signs of leaks, stains, or spills. The storage and use of maintenance supplies does not appear to pose a significant threat to the environmental integrity of the subject property at this time.

6.2.2 Aboveground & Underground Hazardous Substance or Petroleum Product Storage Tanks (ASTs/USTs)

No evidence of current or former ASTs or USTs was observed during the site reconnaissance.

6.2.3 Evidence of Releases

No spills, stains, or other indications that a surficial release has occurred at the subject property were observed.

6.2.4 Polychlorinated Biphenyls (PCBs)

No potential PCB-containing equipment (transformers, oil-filled switches, hoists, lifts, dock levelers, hydraulic elevators, etc.) was observed on the subject property during Partner's reconnaissance.

6.2.5 Strong, Pungent or Noxious Odors

No strong, pungent or noxious odors were evident during the site reconnaissance.

6.2.6 Pools of Liquid

No pools of liquid were observed on the subject property during the site reconnaissance.

6.2.7 Drains, Sumps and Clarifiers

No drains, sumps, or clarifiers, other than those associated with storm water removal, were observed on the subject property during the site reconnaissance.

6.2.8 Pits, Ponds and Lagoons

No pits, ponds, or lagoons were observed on the subject property.

6.2.9 Stressed Vegetation

No stressed vegetation was observed on the subject property.

6.2.10 Additional Potential Environmental Hazards and Emerging Contaminants

Partner evaluated the current subject property use during the site reconnaissance for potential environmental hazards, including Per- and Polyfluoroalkyl Substances (PFAS) impacts to the subject property. Based on the site observations, likely PFAS impacts to the subject property based on current use were not identified. Based on this information, PFAS are not considered an environmental concern at this time.

No additional environmental hazards, including landfill activities or radiological hazards, were observed.

6.3 Non-ASTM Services

6.3.1 Asbestos-Containing Materials (ACMs)

Asbestos is the name given to a number of naturally occurring, fibrous silicate minerals mined for their useful properties such as thermal insulation, chemical and thermal stability, and high tensile strength. The Occupational Safety and Health Administration (OSHA) regulation 29 CFR 1926.1101 requires certain construction materials to be presumed to contain asbestos, for purposes of this regulation. All thermal system insulation (TSI), surfacing material, and asphalt/vinyl flooring that are present in a building that have not been appropriately tested are “presumed asbestos-containing material” (PACM).

A limited, visual survey of areas accessible from ground level for the presence of suspect ACM at the subject property was conducted. The objective of this visual survey was to note the presence and condition of suspect ACM listed by EPA, OSHA, and other regulatory and recognized sources as suspect ACM and/or considered friable or non-friable. Please refer to the table below for identified suspect ACM:

SUSPECT ACMs

Suspect ACM	Location	Friable Yes/No	Physical Condition
Drywall Systems, Floor Tiles, Floor Tile Mastic, Fiberglass Insulation	Throughout Building Interior	No	Good
Stucco	Throughout Building Exterior, Throughout Building Interior	Yes	Good

Prior to disturbance, Partner recommends a comprehensive asbestos survey of the property be completed to determine the presence, condition, friability and likely future condition of suspect or confirmed ACM. All suspect materials must be handled as ACM according to local, state and federal regulations until the results of sampling and analysis indicate the material is a non-ACM. According to the US EPA, ACM that is intact and in good condition can, in general, be managed safely in-place under an Operations and Maintenance (O&M) Program until removal is dictated by renovation, demolition, or deteriorating material condition.

Partner was not provided building plans or specifications for review, which may have been useful in determining areas likely to have used ACM.

6.3.2 Lead-Based Paint (LBP)

Lead is a highly toxic metal that affects virtually every system of the body. LBP is defined as any paint, varnish, stain, or other applied coating that has 1 mg/cm² (or 5,000 µg/g or 0.5% by weight) or more of lead. Congress passed the Residential Lead-Based Paint Hazard Reduction Act of 1992, also known as “Title X,” to protect families from exposure to lead from paint, dust, and soil. Under Section 1017 of Title X, intact LBP on most walls and ceilings is not considered a “hazard,” although the condition of the paint should be monitored and maintained to ensure that it does not become deteriorated. Further, Section 1018 of this law directed the Housing and Urban Development (HUD) and the US EPA to require the disclosure of known information on LBP and LBP hazards before the sale or lease of most housing built before 1978.

Due to the commercial nature of use of the subject property, LBP was not considered within the scope of this assessment.

6.3.3 Radon

Radon is a colorless, odorless, naturally occurring, radioactive, inert, gaseous element formed by radioactive decay of radium (Ra) atoms. The US EPA has prepared a map to assist National, State, and local organizations to target their resources and to implement radon-resistant building codes. The map divides the country into three Radon Zones, according to the table below:

EPA RADON ZONES

EPA Zones	Average Predicted Radon Levels	Potential
Zone 1	Exceed 4.0 pCi/L	Highest
Zone 2	Between 2.0 and 4.0 pCi/L	Moderate
Zone 3	Less than 2.0 pCi/L	Low

It is important to note that the EPA has found homes with elevated levels of radon in all three zones, and the US EPA recommends site-specific testing in order to determine radon levels at a specific location. However, the map does give a valuable indication of the propensity of radon gas accumulation in structures.

Review of the US EPA Map of Radon Zones places the subject property in Zone 3. Based upon the radon zone classification, radon is not considered an environmental concern.

6.3.4 Lead in Drinking Water

LEAD IN DRINKING WATER SUMMARY

Water System Operator:	City of Garden Grove Public Works Department, Water Services Division
Source of Drinking Water:	Surface water imported from the Metropolitan Water District of Southern California and groundwater from eleven (11) wells in the Orange County groundwater basin
Year of Annual Water Quality Report:	2024
Compliance Status:	Water supplied is in compliance with all State and Federal regulations pertaining to drinking water standards for lead.

Water sampling was not conducted to verify water quality.

6.3.5 Microbial Growth

Molds are microscopic organisms found virtually everywhere, indoors and outdoors. Mold will grow and multiply under the right conditions, needing only sufficient moisture (e.g. in the form of very high humidity, condensation, or water from a leaking pipe, etc.) and organic material (e.g., ceiling tile, drywall, paper, or natural fiber carpet padding).

Partner observed accessible, interior areas of the subject property buildings for significant evidence of microbial growth with the exceptions detailed in Section 1.5 of this report; however, this assessment should not be used as a microbial survey or inspection. Additionally, this limited assessment was not designed to assess all areas of potential microbial growth that may be affected by microbial growth on the subject property. Rather, it is intended to give the client an indication as to whether or not conspicuous (based on observed areas) microbial growth is present at the subject property. This evaluation did not include a review of pipe chases, mechanical systems, or areas behind enclosed walls and ceilings.

No obvious indications of water damage or microbial growth were observed during Partner's visual assessment.

6.3.6 Wetlands

The subject property does not appear to be a designated wetland area based on information obtained from the United States Fish and Wildlife Service's Online Wetlands Mapper; however, a comprehensive wetlands survey would be required in order to formally determine actual wetlands on the subject property. No settling ponds, lagoons, surface impoundments, wetlands or natural catch basins were observed at the subject property during this assessment.

6.4 Adjoining Property Reconnaissance

The adjoining property reconnaissance consisted of observing the adjoining properties from the subject property premises.

6.4.1 Hazardous Substances and Petroleum Products Used or Stored at the Site

No hazardous substances or petroleum products were observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.2 ASTs/USTs for Hazardous Substances or Petroleum Products

No ASTs or USTs for hazardous substances/petroleum products were observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.3 Evidence of Releases

No evidence of a release was observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.4 PCBs

No PCB containing materials were observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.5 Strong, Pungent, or Noxious Odors

No strong, pungent, or noxious odors were observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.6 Pools of Liquid

No pools of liquid were observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.7 Drains, Sumps, and Clarifiers

No drains, sumps, or clarifiers were observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.8 Pits, Ponds, and Lagoons

No pits, ponds, or lagoons were observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.9 Stressed Vegetation

No stressed vegetation was observed on adjoining properties during the limited adjoining property reconnaissance.

6.4.10 Additional Potential Environmental Hazards and Emerging Contaminants

Partner evaluated the current adjoining property use/uses during the site reconnaissance for potential environmental hazards, including PFAS impacts to the subject property. Based on observations made from the subject property borders, likely emerging contaminants and PFAS impacts to the subject property from current adjoining property use/uses were not identified. Based on this information, PFAS are not considered an environmental concern.

No additional environmental hazards were observed on adjoining properties during the limited adjoining property reconnaissance.

7.0 VAPOR ENCROACHMENT CONDITIONS

Partner conducted a limited non-intrusive vapor screening on the subject property to identify, to the extent feasible, the potential for vapor encroachment conditions (VECs) in connection with the subject property. This included consideration of chemicals of concern (COC) that may migrate as vapors into the subsurface of the subject property as a result of contaminated soil and groundwater on or near the property.

This screening utilized readily available data sources previously discussed in this Phase I ESA that includes:

- the physical setting of the subject property (Section 2.4),
- standard historical sources for the subject property, adjoining, and surrounding area (Section 3.0),
- known or potentially contaminated sites as identified from information from regulatory agencies and sites on Federal, State, tribal and local databases (Section 4.0), and
- information from the site reconnaissance (Section 6.0) of the subject property and observations of the surrounding properties.

The results of our data collection, reconnaissance, and analysis are tabulated below:

POTENTIAL FOR VAPOR ENCROACHMENT TO IMPACT THE SUBJECT PROPERTY

Area of Concern	Likely or Known VEC to Subject Property
Subject Property Existing Operations or Conditions (Sections 2.0 and 6.0)	None identified that impact the subject property.
Historical Uses of the Subject Property (Section 3.0)	None identified that impact the subject property.
Adjoining Property Operations or Existing Conditions (Sections 2.3 and 6.4)	None identified that impact the subject property.
Historical Uses of Adjoining Properties or Nearby Properties (Section 3.0)	None identified that impact the subject property.
Regulatory Review of sites identified on Federal, State, tribal and Local Environmental Databases which were located in the AMSD (Section 4.0)	None identified that impact the subject property.

Based on the findings of the limited non-intrusive vapor screening, vapor intrusion is unlikely to be an issue of concern in connection with the existing structures on the subject property. As such, no further assessment is recommended.

8.0 FINDINGS AND CONCLUSIONS

Findings and Opinions

Recognized Environmental Condition

A recognized environmental condition (REC) refers to the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment; the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment.

- Partner did not identify any RECs during the course of this assessment.

Controlled Recognized Environmental Condition

A controlled recognized environmental condition (CREC) refers to a REC affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, activity and use limitations or other property use limitations).

- Partner did not identify any CRECs during the course of this assessment.

Historical Recognized Environmental Condition

A historical recognized environmental condition (HREC) refers to a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations).

- Partner did not identify any HRECs during the course of this assessment.

Business Environmental Risk

A Business Environmental Risk (BER) is a risk which can have a material environmental or environmentally driven impact on the business associated with the current or planned use of commercial real estate, not necessarily related to those environmental issues required to be investigated in this practice. The following was identified during the course of this assessment:

- Due to the age of the subject property buildings, there is a potential that asbestos-containing material (ACM) and lead-based paint (LBP) are present. Should these materials be replaced, the identified suspect ACMs would need to be sampled to confirm the presence or absence of asbestos prior to any renovation or demolition activities to prevent potential exposure to workers and building occupants.

Significant Data Gaps

No significant data gaps affecting the ability of the Environmental Professional to identify a REC were encountered during this assessment.

Conclusions and Recommendations

Partner has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E1527-21 of 9822 Russell Avenue in Garden Grove, Orange County, California (the "subject property"). Any exceptions to, or deletions from, this practice are described in Section 1.5 of this report.

This assessment has revealed no evidence of RECs, CRECs, or HRECs in connection with the subject property; however, one BER was identified. Based on the conclusions of this assessment, Partner recommends the following:

- An Operations and Maintenance (O&M) Program should be implemented in order to safely manage the suspect ACMs and LBP located at the subject property.

9.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

Partner has performed a Phase I Environmental Site Assessment of the property located at 9822 Russell Avenue in Garden Grove, Orange County, California in conformance with the scope and limitations of the protocol and the limitations stated earlier in this report. Exceptions to or deletions from this protocol are discussed earlier in this report.

By signing below, Partner declares that, to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in §312.10 of 40 CFR §312. Partner has the specific qualifications based on education, training, and experience to assess a *property* of the nature, history, and setting of the subject *property*. Partner has developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Reviewed By:

Richard Kim
Environmental Professional

10.0 REFERENCES

American Society for Testing and Materials, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM Designation: E1527-21

Environmental Risk Information Services (ERIS), City Directory, Fire Insurance Maps, Historic Aerials, Physical Setting Report, Radius Report, Topographic Maps, June 2025

Federal Emergency Management Agency, Federal Insurance Administration, National Flood Insurance Program, Flood Insurance Map, accessed via the internet, June 2025

United States Department of Agriculture, Natural Resources Conservation Service, Web Soil Survey, accessed via the internet, June 2025

United States Environmental Protection Agency, EPA Map of Radon Zones (Document EPA-402-R-93-071), accessed via the internet, June 2025

United States Fish and Wildlife Service, National Wetlands Inventory, accessed via the internet, June 2025

United States Geological Survey, accessed via the internet, June 2025

United States Geological Survey Topographic Map 2022, 7.5-minute series, accessed via the internet, June 2025

FIGURES

1: Site Location Map

2: Site Plan

3: Topographic Map

Drawing Not To Scale

KEY:
Subject Property

FIGURE 1: SITE LOCATION MAP
Project No. 25-500978.1




FIGURE 2: SITE PLAN
Project No. 25-500978.1

USGS 7.5-Minute *Anaheim, CA* Quadrangle
Created: 2022

KEY:
Subject Property

APPENDIX A: SITE PHOTOGRAPHS

1. The church viewed from Russell Avenue

2. South side of the church

3. West side of the church

4. Covered walkway between the church and the preschool

5. Outdoor area between church and preschool

6. View of the preschool building

7. Preschool offices

8. Eastern view of the preschool building

9. South side of the two-story portion of the preschool building

10. Preschool playground west of the building

11. Maintenance storage shed

12. Parking lot at the eastern portion of the subject property

13. Parking lot at the southern portion of the subject property

14. Lobby for the church

15. Sanctuary area of the church

16. Church office

17. Church hallway

18. Church bathroom

19. Stairs to upper level of the church

20. Preschool cafeteria

21. Conference room in the preschool

22. Preschool kitchen

23. Preschool restroom

24. Preschool classroom

25. Preschool classroom

26. Interior of the maintenance shed

27. Stairwell to second floor of preschool

28. Second floor hallway of the preschool

29. 2nd floor preschool room

30. Wall-mounted air conditioning unit

31. Sink and janitorial area in the church

32. Fiberglass insulation and HVAC

33. HVAC system

34. HVAC equipment

35. Location of water heater at the south side of the preschool building

36. Dumpster at the south side of the subject property

- 37. Sunnyside Elementary School (9972 Russel Avenue) to the east of the subject property
- 38. Orange County Chinese Christian Assembly church and parking lot (9881 Trask Avenue) to the south of the subject property
- 39. Kerry Street and Dakota Avenue intersection to the southwest
- 40. Apartment complex (9801 and 9811 Russell Avenue) across Russell Avenue to the north
- 41. 9781 Dakota Avenue, a single-family residence, across Kerry Street to the west

APPENDIX B: HISTORICAL/REGULATORY DOCUMENTATION

Project Property: 9822 Russell Avenue
9822 Russell Avenue GARDEN GROVE CA 92844
Project No: 25-500978.1
Requested By: Partner Engineering and Science, Inc.
Order No: 25061300823
Date Completed: June 15, 2025

Please note that no information was found for your site or adjacent properties.



CITY DIRECTORY

Project Property: *9822 Russell Avenue
9822 Russell Avenue
GARDEN GROVE, CA 92844*

Project No: *25-500978.1*

Requested By: *Partner Engineering and Science, Inc.*

Order No: *25061300823*

Date Completed: *June 23, 2025*

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com

June 23, 2025
RE: CITY DIRECTORY RESEARCH
9822 Russell Avenue
GARDEN GROVE, CA 92844

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:

9775-10000 of Russell Ave
9775-10000 of Trask Ave

Search Notes:

Search Results Summary

Date	Source	Comment
2024	DIGITAL BUSINESS DIRECTORY	
2023	DIGITAL BUSINESS DIRECTORY	
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2008	DIGITAL BUSINESS DIRECTORY	
2003	DIGITAL BUSINESS DIRECTORY	
2001	HAINES	
1996	HAINES	
1991	HAINES	
1986	HAINES	
1981	HAINES	
1975	PACIFIC TELEPHONE	
1970	PACIFIC TELEPHONE	
1967	PACIFIC TELEPHONE	
1964	PACIFIC TELEPHONE	
1958	PACIFIC TELEPHONE	
1955	PACIFIC TELEPHONE	
1951	LUSKEYS	

RUSSELL AVE

9801 HARDWIN HUYNH...RESIDENTIAL
9811 ALLEN LUONG...RESIDENTIAL
9811 JACQUELINE NGUYEN...RESIDENTIAL
9822 DEVELOPMENT CENTER ORANGE...CHILD CARE SERVICE
9822 IGLESIA DE CRISTO MLLF...CHURCHES
9822 SUNFLOWER PRESCHOOL...CHILD CARE SERVICE
9871 DEBRA HILLESTAD...RESIDENTIAL
9871 STACEY MICHAEL...RESIDENTIAL
9881 C RAMIREZ...RESIDENTIAL
9881 HILARIA URBINA...RESIDENTIAL
9893 CYNTHIA LUU...RESIDENTIAL
9921 ANDY DANG...RESIDENTIAL
9921 CHRISTINE NGUYEN...RESIDENTIAL
9931 HAI HA...RESIDENTIAL
9941 LAN NGUYEN...RESIDENTIAL
9943 BAY HUYNH...RESIDENTIAL
9951 LUZ REYNOSO...RESIDENTIAL
9953 FLORENCE STEGNER...RESIDENTIAL
9953 MIKE'S POOL & SPA SVC...SPAS - HEALTH
9972 SUNNYSIDE ELEMENTARY SCHOOL...SCHOOLS

TRASK AVE

9881 ORANGE COUNTY CHURCH...CHURCHES
9898 RUSSELL WESTBROOK HYUNDAI-GDN...NEW CAR DEALERS
9898 UNION DODGE...NEW CAR DEALERS
9898 WEST VALLEY CHRYSLER JEEP...AUTOMOBILES PICK-UP TRUCKS & VANS

RUSSELL AVE

9801 NINA LE...RESIDENTIAL
 9811 JACQUELINE NGUYEN...RESIDENTIAL
 9811 JIMMY HUYNH...RESIDENTIAL
 9811 LAN NGUYEN...RESIDENTIAL
 9822 DEVELOPMENT CENTER ORANGE...CHILD CARE SERVICE
 9822 IGLESIA DE CRISTO MLLF...CHURCHES
 9822 SUNFLOWER PRESCHOOL...CHILD CARE SERVICE
 9831 DAT TRIEU...RESIDENTIAL
 9841 NATHAN KIM...RESIDENTIAL
 9871 DEBRA HILLESTAD...RESIDENTIAL
 9881 C RAMIREZ...RESIDENTIAL
 9881 HILARIA URBINA...RESIDENTIAL
 9881 IGNACIO URBINA...RESIDENTIAL
 9891 NGUYEN LAU...RESIDENTIAL
 9921 ANDY DANG...RESIDENTIAL
 9921 CHRISTINE NGUYEN...RESIDENTIAL
 9921 LICH VU...RESIDENTIAL
 9931 HAI HA...RESIDENTIAL
 9941 LAN NGUYEN...RESIDENTIAL
 9951 HOA NGUYEN...RESIDENTIAL
 9953 FLORENCE STEGNER...RESIDENTIAL
 9972 SUNNYSIDE ELEMENTARY SCHOOL...SCHOOLS
 9972 SUNNYSIDE ELEMENTARY SCHOOL...SCHOOLSUNIVERSITIES & COLLEGES
 ACADEMIC

TRASK AVE

9881 ORANGE COUNTY CHURCH...RELIGIOUS ORGANIZATIONS
 9881 ORANGE COUNTY CHURCH...CHURCHES
 9898 RUSSELL WESTBROOK HYUNDAI GDN...AUTOMOBILE DEALERS-NEW CARS

RUSSELL AVE

9801 NINA LE...*RESIDENTIAL*
 9811 JACQUELINE NGUYEN...*RESIDENTIAL*
 9811 JIMMY HUYNH...*RESIDENTIAL*
 9811 LAN NGUYEN...*RESIDENTIAL*
 9822 DEVELOPMENT CENTER ORANGE...*CHILD CARE SERVICE*
 9822 IGLESIA DE CRISTO MLLF...*CHURCHES*
 9822 SUNFLOWER PRESCHOOL...*CHILD CARE SERVICE*
 9831 DAT TRIEU...*RESIDENTIAL*
 9841 NATHAN KIM...*RESIDENTIAL*
 9871 DEBRA HILLESTAD...*RESIDENTIAL*
 9881 C RAMIREZ...*RESIDENTIAL*
 9881 HILARIA URBINA...*RESIDENTIAL*
 9881 IGNACIO URBINA...*RESIDENTIAL*
 9891 NGUYEN LAU...*RESIDENTIAL*
 9921 ANDY DANG...*RESIDENTIAL*
 9921 CHRISTINE NGUYEN...*RESIDENTIAL*
 9921 LICH VU...*RESIDENTIAL*
 9931 HAI HA...*RESIDENTIAL*
 9941 LAN NGUYEN...*RESIDENTIAL*
 9951 HOA NGUYEN...*RESIDENTIAL*
 9953 MICHAEL STEGNER...*RESIDENTIAL*
 9972 SUNNYSIDE ELEMENTARY SCHOOL...*SCHOOLS**SUNIVERSITIES & COLLEGES*
ACADEMIC
 9972 SUNNYSIDE ELEMENTARY SCHOOL...*SCHOOLS*

TRASK AVE

9881 ORANGE COUNTY CHURCH...*RELIGIOUS ORGANIZATIONS*
 9881 ORANGE COUNTY CHURCH...*CHURCHES*
 9898 RUSSELL WESTBROOK HYUNDAI-GDN...*AUTOMOBILE DEALERS-NEW CARS*

RUSSELL AVE

9801 NINA LE...RESIDENTIAL
 9801 TODD LE...RESIDENTIAL
 9801 TRUNG LUONG...RESIDENTIAL
 9811 JACQUELINE NGUYEN...RESIDENTIAL
 9811 JIMMY HUYNH...RESIDENTIAL
 9811 LAN NGUYEN...RESIDENTIAL
 9822 DEVELOPMENT CENTER ORANGE...CHILD CARE SERVICE
 9822 IGLESIA DE CRISTO MLLF...CHURCHES
 9822 SUNFLOWER PRESCHOOL...CHILD CARE SERVICE
 9841 NATHAN KIM...RESIDENTIAL
 9871 DEBRA HILLESTAD...RESIDENTIAL
 9871 TIMOTHY HILLESTAD...RESIDENTIAL
 9881 C RAMIREZ...RESIDENTIAL
 9881 HILARIA URBINA...RESIDENTIAL
 9881 IGNACIO URBINA...RESIDENTIAL
 9881 JOANNA URBINA...RESIDENTIAL
 9921 ANDY DANG...RESIDENTIAL
 9921 CHRISTINE NGUYEN...RESIDENTIAL
 9921 LICH VU...RESIDENTIAL
 9931 HAI HA...RESIDENTIAL
 9941 LAN NGUYEN...RESIDENTIAL
 9951 HOA NGUYEN...RESIDENTIAL
 9953 MICHAEL STEGNER...RESIDENTIAL
 9972 SUNNYSIDE ELEMENTARY SCHOOL...SCHOOLS

TRASK AVE

9881 ORANGE COUNTY CHURCH...RELIGIOUS ORGANIZATIONS
 9881 ORANGE COUNTY CHURCH...CHURCHES
 9898 UNION DODGE...AUTOMOBILE DEALERS-NEW CARS

RUSSELL AVE

9782 **JI LEE**...*RESIDENTIAL*
9782 **OK LEE**...*RESIDENTIAL*
9822 **SUNFLOWER PRESCHOOL**...*CHILD CARE SERVICE*
9841 **MARVIN KIM**...*RESIDENTIAL*
9861 **JORGE AGUILAR**...*RESIDENTIAL*
9861 **JOSE HERNANDEZ**...*RESIDENTIAL*
9861 **ROBERTO LOZANO**...*RESIDENTIAL*
9881 **CARLOS CASTRO**...*RESIDENTIAL*
9881 **HILARIA URBINA**...*RESIDENTIAL*
9881 **IGNACIO URBINA**...*RESIDENTIAL*
9881 **JOANNA URBINA**...*RESIDENTIAL*
9881 **URBINA IGNACIO**...*RESIDENTIAL*
9921 **ANDY DANG**...*RESIDENTIAL*
9972 **SUNNYSIDE ELEMENTARY SCHOOL**...*SCHOOLS*

TRASK AVE

9881 **ORANGE COUNTY CHURCH**...*CHURCHES*
9898 **GARDEN GROVE HYUNDAI**...*AUTOMOBILE DEALERS-NEW CARS*

RUSSELL AVE

9782	OK J LEE...RESIDENTIAL
9801	HIEH LUONG...RESIDENTIAL
9801	LAN BUI...RESIDENTIAL
9811	THUOI T DANG...RESIDENTIAL
9822	IGLESIA DE CRISTO MLLF...RELIGIOUS ORGANIZ
9831	CA TAN...RESIDENTIAL
9831	NHUAH N HUYNH...RESIDENTIAL
9861	DANIEL L KROGMAN...RESIDENTIAL
9891	DAWN HAWKINS...RESIDENTIAL
9891	EV VERTICAL BLIND...MFG DRAPERY HARDWARE/BLINDS
9911	HONG LE...RESIDENTIAL
9911	NGHI HOANG...RESIDENTIAL
9921	XUAN NGUYEN...RESIDENTIAL
9931	CHIN H NGUYEN...RESIDENTIAL
9931	HOAHUU NGUYEN...RESIDENTIAL
9972	SUNNYSIDE ELEMENTARY SCHOOL...ELEMENT, SECON SCHL

TRASK AVE

9881	ORANGE COUNTY CHINESE CHURCH...RELIGIOUS ORGANIZ
9898	UNION DODGE INC...NEW & USED CAR DLRS
9898	UNION DODGE INC...GENERAL AUTO REPAIR RET NEW/USED AUTOMOBILES
9898	UNION DODGE PRE-OWNED CTR...USED CAR DEALERS

RUSSELL AVE

9782 CHOON E LEE...*RESIDENTIAL*
9801 DINH PHAM...*RESIDENTIAL*
9811 THUOI THI DANG...*RESIDENTIAL*
9822 BETHEL MISSIONARY CHURCH
9822 CROSS COUNTY CHRISTIAN CHURCH
9822 CROSS COUNTY VIETNAMESE CHRSTN
9881 GERALD E LAND...*RESIDENTIAL*
9891 WILLIAM WAGONER...*RESIDENTIAL*
9921 KEITH B MACK...*RESIDENTIAL*
9931 KEITH & KIMBERLY BARKER...*RESIDENTIAL*
9941 THAO X DINH...*RESIDENTIAL*
9951 GHULAM SAKHI...*RESIDENTIAL*
9972 SOUTHWEST GG LITTLE LEAGUE
9972 SUNNYSIDE ELEMENTARY SCHOOL...*PUBLIC ELEMENTARY AND
SECONDARY SCHOOLS*

TRASK AVE

9881 KINGS MISSION
9881 ORANGE COUNTY CHINESE CHRISTIN
9898 UNION DODGE INC

RUSSELL AVE

9772 CHONG SANG UP
9772 CHUNG SUNG H
9772 KIM JIMMY
9782 LEE ON JOE
9801 BERNTH HAROLD
9801 BUI LAN
9801 LƯƠNG HOA
9811 DANG THUOI T
9822 CORNERSTONE CHRISTN
9822 CROSS COUNTY CHRISTIAN CHURCH
9822 CROSS COUNTY VTNMSE CHRSTN CH
9831 CHUNG DON
9831 HUYNH NHAN
9831 NGUYEN CHIN H
9831 NGUYỄN HO
9831 TAN CA
9831 • ĐÌNH HOÀ
9841 KIM HANG
9861 KROGMAN DANI L
9871 HILLESTAD TIMOTHY
9881 URBINA IGNACIO
9891 DENHAM MONDE
9891 HAWKINS DAWN
9893 XXXX
9911 HOANG NGHỊ
9911 LE HONG
9921 NGUYỄN XU
9921 OKHA PHAN
9941 STEGNER JOHN
9943 XXXXX
9951 XXXXX
9953 XXXX
9972 SOUTHWEST GARDN 71 GRV LITTLE LGE
9972 SUNNYSIDE ELEMENTARY SCHOOL
10011 AHN YOUNG

TRASK AVE

9670 TOYOTA OF GARDN GRV KOREAN DPT
9838 UNION DODGE INC
9881 ORANGE CO CHNSE CHRSTN ASMBLY
10041 SEXTONS AUTOMOTIVE

RUSSELL AVE

9772	CHONG SANG UP
9782	LEE CHOON EOP
9801	NGUYEN VAN
9801	PHAM DINH
9811	DANG THUOI T
9811	NGUYEN TRUNG M
9822	CORNERSTONE CHRISTN
9822	GARDN GRV CHRSTN CH
9831	LE DUNG DINH
9841	XXXX
9861	KROGMAN DAN ! L
9871	HILLSTAD TIMOTHY
9881	LAND GERALD E
9891	WAGONER WILLIAM
9893	XXXX
9911	XXXX
9921	MACK KEITH B
9931	BARKER KEITH
9931	BARKER KIMBERLY
9941	DINH THEO XUÂN
9943	XXXX
9951	SAKHI GHULAM
9953	XXXX
9972	SOUTHWEST GRDN GRV
9972	SUNNYSIDE ELEM SC
10011	XXXX

TRASK AVE

9666	QUALITY NISSAN
9666	QUALITY NISSAN PART
9881	GARDN GRV ORTHO CH
9881	PENINSULA CHRSTN SC
9881	PRESBY ORTHODOX CH
9898	PATTERSON DODGE
9898	PATTERSON DODGE PRT
10041	S&S BOOK DSTRBTRS

RUSSELL AVE

9762	DAVEY EDW W
9782	XXXX
9801	NGUYEN VAN
9811	DANG THUOI T
9822	BETHEL MISSIONRY CH
9822	CORNERSTONE CHRISTN
9822	GARDN GRV CHRSTN CH
9831	BUI LAURA
9831	DANG HUNG PHI
9831	HÒ THANH VAN
9841	XXXX
9861	KROGMAN DAN L
9871	HILLESTAD JOB T
9881	LAND GERALD E
9891	WAGONER ELDEN
9891	WAGONER WILLIAM
9893	XXXX
9911	MACK KEITH V
9921	WYMAN ROBERT O
9931	BARKER KEITH
9931	BARKER KIMBERLY
9931	NELSON JOHN
9941	SLOYER CHRISTINE
9941	SLOYER GARY
9943	DAVIS DANI M
9951	XXXX
9953	XXXX
9972	SOUTHWEST GRDN GRVE
9972	SUNNYSIDE ELEM SC
10011	TORRES MANUEL

TRASK AVE

9666	GARDN GRV DODG LSNG
9666	GARDN GRV DODGE
9666	GARON GRV HYUNDAI
9881	GARDN GRV ORTHO CH
9881	PENINSULA CHRSTN SC
9881	PRESBY ORTHODOX CH
9898	GARDN GRV MITSUBSHI
10041	SEXTONS AUTOMOTIVE

RUSSELL AVE

9772 TENHOFF TOM W 534-1262
9782 HIGGINS J 638-3030
9801 NGUYỄN NUONG 638-7594
9801 NGUYỄN HOA THI 636-1381
9801 SINGH GORA 638-1174
9811 BUI MUON VAN 534-0436
9811 DANG THUOI T 638-9357
9811 NGUYỄN NGÀ GHI 636-2113
9811 NGUYỄN THANH 636-4347
9822 CORNERSTONE CHRISTN 537-4850
9822 GARDN GRY CHRSTH CH 537-4190
9831 AUDDEN K 534-8096
9831 TRAN CHARLIE 537-0823
9841 PFAFF WALTER H 638-9127
9861 KROGMAN DANL L 534-8411
9871 HILLESTAD JOS T 537-8039
9881 LAND GERALD E 638-9980
9891 WAGONER ELDEN 530-4051
9893 HILLESTAD TJ 636-6278
9911 KAPILOFF GERALD 636-6718
9911 SHAW JAMES 539-7424
9921 HOBBS B PAUL 530-6490
9921 MORRIS TIM 534-5356
9931 XXXX
9941 SLOYER CHRISTINE 638-9337
9941 SLOYER GARY 638-9337
9943 DAVIS DANL M 638-3743
9951 XXXX
9953 XXXX
9972 SOUTHWEST GRDN GRVE 638-0463
9972 SUNNYSIDE ELEM SC 538-6158
10011 XXXX

TRASK AVE

9463 XXXX
9881 GARDN GRY ORTHO CH
9881 PENINSULA CHRSTN SC
9881 PRESBYTERAN ORT CH
10041 SEXTONS AUTOMOTIVE

RUSSELL AVE

9782	SAMPLES JOHN C
9801	KEAN DANIEL K
9801	NGUYEN NUONG
9801	SINGH GORA
9801	TELLES DANL J
9811	BUI MUON VAN
9811	NGUYEN THANH
9822	GARDN GRV CH GOD
9831	RUDDEN K
9841	PFAFF WALTER H
9861	KROGMAN DANL L
9871	HILLESTAD JOS T
9881	LAND GERALD E
9881	XXXX
9893	XXXX
9911	BAKER CARL R
9911	HILLS RICHARD O
9911	HUNTER JAS
9921	BAUNNER GARY
9921	HOLMES RUSSELL F
9931	XXXX
9941	XXXX
9943	XXXX
9951	HARGIS THEODORE
9953	XXXX
9972	DOWLING DAVID L
9972	SOUTHWEST GRDN GRVE
9972	SUNNYSIDE ELEM SC
10011	XXXX

TRASK AVE

9463	XXXX
9881	ORTHODOX PRSBYTRN CH
9881	PRESBYTERN OATH CH
10041	SEXTONS AUTOMOTIVE

RUSSELL AVE

9772	DOWLING DAVID L
9822	CHURCH OF CHRIST
9831	FOX STEVEN
9861	KROGMAN DAN L
9871	HILLESTAD JOS T
9881	LAND GERALD E
9921	ALLEN MIKE
9921	SMITH BRIAN
9931	ROBINSON FRANK
9972	SOUTHWEST GARDEN GROVE LITTLE LEAGUE
10022	DE MAN BEAUTY SALON

TRASK AVE

9461	SOUZA SEBASTIAN
9881	ORTHODOX PRESBYTERIAN CHURCH
10041	KENNA TIMOTHY

RUSSELL AVE

9772	GRAY LENORE
9811	BRUCE WM L JR
9811	EMMONS LYNN A
9822	CHURCH OF CHRIST CHRISTIAN
9831	GRAY LENORE
9831	RILEY MARY JANE
9861	MILLER DAN
9871	HILLESTAD JOS T
9881	SCOTT J E
9891	DENHAM JAS A
9893	REMINGTON C J
9921	WARRELL BRAD H
9921	WILLARD JESS S
9931	ROBINSON FRANK
9943	BUTTERFASS KEN
10021	BRENNAN PATRICK

TRASK AVE

9461	SOUZA SEBASTIAN
9881	ORTHODOX PRESBYTERIAN CHURCH
10041	SEXTON'S AUTOMOTIVE

RUSSELL AVE

9772 GRAY L
9801 BRAUGHTON C
9801 BUILDING
9801 CLIFTON S
9801 FAUST M
9801 IRWIN W F
9811 APARTMENT
9811 CARLSEN M J
9811 HILL T
9822 CHURCH OF CHRIST
9831 APARTMENT
9831 PENA H
9831 RILEY M J
9831 WILSON B J
9841 CARNES D
9841 HENLEY ALBERT
9861 SCHULTZ H
9871 HILLESTAD J T
9881 SCOTT JANET E
9891 STEPHENS H
9893 COX S A
9911 CHAFFEE T L
9921 BUILDING
9921 DURR C J
9921 LANGELL B
9931 ROBINSON FRANK
9943 BUTTERFASS K
10022 DEMAN BEAUTY SALON

TRASK AVE

9461 SOUZA SEBASTIAN
9881 PRESBYTERIAN CHURCH
10051 OXENREIDER FLOYD S

RUSSELL AVE

9772 LYONS LLOYD G
9801 APARTMENT
9801 LANPHERIE D
9811 APARTMENT
9811 A □ LAUTENSCHLAGER T
9811 GIRALDI M J
9811 RIDDLE R L
9822 CHURCH OF CHRIST
9831 APARTHENT
9831 CANTERBERRY H L
9831 KALETKA H W
9831 MAGNESS WE
9841 CARNES D
9841 HENLEY ALBERT
9861 HAYNE A JR
9871 HILLESTAD JY
9881 SCOTT JANET E
9911 CHAFFEE T L
9931 ROBINSON FRANK
9941 JOHNSON V
9943 MYERS ORVILLE
9951 BAILEY J F
9953 MACK R W
9972 SUNNYSIDE ELEM SCHL
10012 STAFFORD JB

TRASK AVE

9461 SOUZA SEBASTIAN
9881 PRESBYTERIAN CHURCH
10041 HOLTE WARREN

RUSSELL AVE

9772 USAB E M
9782 DEAN RUBY L
9801 APARTMENT
9811 APARTMENT
9811 AYERSMAN RAYMOND E
9811 HUMLIE J VIRGINIA
9811 TAYLOR KENNETH E
9822 G GR CHURCH OF CHRIST
9831 APARTMENT
9831 COFFINO RITA
9831 JEFFERS JAMES J
9841 HENLEY ALBERT
9861 FINAL C E
9871 HILLESTAD J T
9891 O DONNELL FRANKLIN P
9891 SCOTT JOSEPH R
9911 CHAFFEE T L
9931 ROBINSON FRANK
9941 LEHMANN FELIX P JR
9943 VAUGHN JERRY
9953 SAEHLENOU HARRY
9972 SUNNYSIDE SCHOOL
10012 TRIMMELL R H

TRASK AVE

9463 MENDES MANUEL S
9852 GARDEN GROVE FARMS
10011 TURNER J

RUSSELL AVE

9772	LYONS L G
9782	DEAN RUBY L
9822	G GR CHURCH OF CHRIST
9841	HENLEY ALBERT
9861	FINAL C E
9871	HILLESTAD J T
9881	CRANFILL J
9891	O DONNELL FRANKLIN P
9911	CHAFFEE T L
9931	ROBINSON FRANK
9953	MAY E W
9972	SUNNYSIDE SCHOOL
10012	TRIMMELL R H

TRASK AVE

9463	MENDES MANUEL S
9852	GARDEN GROVE FARMS
10041	HOPKINS H N

RUSSELL AVE

STREET NOT LISTED

TRASK AVE

9762	VACANT
9832	GUTIERREZ DAVID
9852	GRDN GR FARMS LIVESTOCK FEEDERS GRDN G
9852	RENKEN ED .GRDN GR
10011	NIGHTINGALE AJ CONCRETE



HISTORICAL AERIALS

Project Property: 9822 Russell Avenue
9822 Russell Avenue
GARDEN GROVE CA 92844

Project No: 25-500978.1

Requested By: Partner Engineering and Science, Inc.

Order No: 25061300823

Date Completed: June 18, 2025

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
1938	Agricultural Stabilization & Conserv. Service	1" = 500'	
1947	Fairchild	1" = 500'	
1953	Agricultural Stabilization & Conserv. Service	1" = 500'	
1963	United States Geological Survey	1" = 500'	
1972	United States Geological Survey	1" = 500'	
1981	Private	1" = 500'	
1987	United States Geological Survey	1" = 500'	
1995	United States Geological Survey	1" = 500'	
2005	United States Department of Agriculture	1" = 500'	
2009	United States Department of Agriculture	1" = 500'	
2010	United States Department of Agriculture	1" = 500'	
2012	United States Department of Agriculture	1" = 500'	
2014	United States Department of Agriculture	1" = 500'	
2016	United States Department of Agriculture	1" = 500'	
2018	United States Department of Agriculture	1" = 500'	
2020	United States Department of Agriculture	1" = 500'	
2022	United States Department of Agriculture	1" = 500'	
2024	Maxar Technologies	1" = 500'	


Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com

500
Feet

**Subject
Property**



Year: 1938
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER

500
Feet

**Subject
Property**



Year: 1947
Source: FAIRCHILD
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER

500
Feet

**Subject
Property**



Year: 1953
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER

500
Feet

**Subject
Property**



Year: 1963
Source: USGS
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER

500
Feet

**Subject
Property**



Year: 1972
Source: USGS
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER

500
Feet

**Subject
Property**




Year: 1981
Source: Private
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER



**Subject
Property**




Year: 1987
Source: USGS
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER



**Subject
Property**



Year: 1995
Source: USGS
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER

500
Feet

**Subject
Property**



Year: 2005
Source: USDA
Scale: 1" = 500'
Comment:


Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER

500
Feet

**Subject
Property**




Year: 2009
Source: USDA
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER



Year: 2010
Source: USDA
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823



500
Feet

**Subject
Property**




Year: 2012
Source: USDA
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER




Year: 2014
Source: USDA
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER




Year: 2016
Source: USDA
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823





Year: 2018
Source: USDA
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823



500
Feet

**Subject
Property**



Year: 2020
Source: USDA
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER

500
Feet

**Subject
Property**




Year: 2022
Source: USDA
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823

PARTNER



Year: 2024
Source: MAXAR
Scale: 1" = 500'
Comment:

Address: 9822 Russell Avenue, GARDEN GROVE, CA
Approx Center: -117.95774689,33.76820027

Order No: 25061300823





TOPOGRAPHIC MAPS

Project Property: 9822 Russell Avenue

9822 Russell Avenue
GARDEN GROVE CA 92844

Project No: 25-500978.1

Requested By: Partner Engineering and Science, Inc.

Order No: 25061300823

Date Completed: June 15, 2025

We have searched USGS collections of current topographic maps and historical topographic maps for the project property. Below is a list of maps found for the project property and adjacent area. Maps are from 7.5 and 15 minute topographic map series, if available.

Year	Map Series
1896	15
1898	15
1901	15
1935	7.5
1942	15
1949	7.5
1950	7.5
1965	7.5
1972	7.5
1974	7.5
1981	7.5
2015	7.5
2018	7.5
2022	7.5

Topographic Map Symbolology for the maps may be available in the following documents:

Pre-1947

[Page 223 of 1918 Topographic Instructions](#)

[Page 130 of 1928 Topographic Instructions](#)

1947-2009

[Topographic Map Symbols](#)

2009-present

[US Topo Map Symbols](#)


Topographic Maps included in this report are produced by the USGS and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc.(in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS', using Topographic Maps produced by the USGS. This maps contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com



1896

Available Quadrangle(s): Anaheim, CA
Santa Ana, CA

Order No. 25061300823



1898

Available Quadrangle(s): Anaheim, CA
Santa Ana, CA


Order No. 25061300823



1901


Available Quadrangle(s): Anaheim, CA
Santa Ana, CA

Order No. 25061300823



Available Quadrangle(s): Garden Grove, CA
Newport Beach, CA

Order No. 25061300823




1942

(1-1942)
Aerial Photo Year: 1939

(2-1942)
Aerial Photo Year: 1939

Available Quadrangle(s): Anaheim, CA(2-1942)
Santa Ana, CA(1-1942)

Order No. 25061300823




1949

(1-1949)
Aerial Photo Year: 1947

(2-1949)
Aerial Photo Year: 1947

Available Quadrangle(s): Anaheim, CA(1-1949)
Newport Beach, CA(2-1949)

Order No. 25061300823




1950

(1-1949)
Aerial Photo Year: 1947

(2-1950)
Aerial Photo Year: 1947


Available Quadrangle(s): Anaheim, CA⁽²⁻¹⁹⁵⁰⁾
Newport Beach, CA⁽¹⁻¹⁹⁴⁹⁾

Order No. 25061300823



Available Quadrangle(s): Anaheim, CA(1-1965)
Newport Beach, CA(2-1965)

Order No. 25061300823




1972

(1-1972) Aerial Photo Year: 1972
 Photo Revision Year: 1972

(2-1972) Aerial Photo Year: 1972
 Photo Revision Year: 1972

Available Quadrangle(s): Anaheim, CA(1-1972)
 Newport Beach, CA(2-1972)

Order No. 25061300823



1974


(1-1972)
Aerial Photo Year: 1972
Photo Revision Year: 1972

(2-1974)
Aerial Photo Year: 1974

(3-1974)
Aerial Photo Year: 1974

Available Quadrangle(s): Anaheim, CA⁽²⁻¹⁹⁷⁴⁾
Newport Beach, CA⁽¹⁻¹⁹⁷²⁾
Costa Mesa, CA⁽³⁻¹⁹⁷⁴⁾

Order No. 25061300823




1981

(1-1974) Aerial Photo Year: 1974
 (2-1981) Aerial Photo Year: 1963
 (3-1981) Aerial Photo Year: 1978
 Photo Revision Year: 1981

Available Quadrangle(s): Anaheim, CA(2-1981)
 Costa Mesa, CA(1-1974)
 Newport Beach, CA(3-1981)


Order No. 25061300823



2015

Available Quadrangle(s): Anaheim, CA
Newport Beach, CA


Order No. 230613000823



2018

Available Quadrangle(s): Anaheim, CA
Newport Beach, CA


Order No. 25061300823



2022

Available Quadrangle(s): Anaheim, CA
Newport Beach, CA

Order No. 230613j00823



Outlook

Re: 9822 Russell Avenue [#795590]

From Planning Help <planning@ci.garden-grove.ca.us>

Date Tue 7/1/2025 2:35 PM

To Davis, Reese <reese.davis@partneresi.com>

CAUTION: This message originated from outside the Partner organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Reese Davis,

Thank you for your inquiry.

The number value at the end of the R-1 zoning designation refers to the minimum lot size for the zoning district. For example, the "7" in R-1-7 requires a minimum 7,200 SF lot area per the R-1 Single Family Development Standards Table identified in the Garden Grove Municipal Code (GGMC).

If you have any other inquiries please do not hesitate to contact us.

Regards,

City of Garden Grove | Planning Services Division
11222 Acacia Pkwy, Garden Grove, CA 92840
(714) 741-5312
Planning Contact Portal

Regards,

Zachary Hernandez

Planning Aide I Planning Services Department
City of Garden Grove
11222 Acacia Parkway
Garden Grove, CA 92840
zacharyh@ggcity.org

We hope this response has sufficiently answered your questions. If not, please do not send another email. Instead, reply to this email.

Zone R-1
Designation R-1-7

Zone R-1
Designation R-1-7

PUD-103-82

PUD-110-96

PUD-110-96



ORANGE COUNTY FIRE AUTHORITY

Prevention Field Services

1 Fire Authority Road

Irvine, CA 92602

CRTK@ocfa.org

RECORDS REQUEST INVOICE



To: Reese Davis – Partner ESI

Number of Pages (including cover): 1

Date: 6/30/2025

COMMENTS: The information you requested for 9822 RUSSELL AV in the city of GARDEN GROVE is ready. Your fee for this request is \$2.50.

***** PAY ONLINE! *** To ensure I receive a copy of the receipt, please use the link provided in the email only (do not use previously saved payment links)**

If you prefer not to pay online, please send a check payable to ORANGE COUNTY FIRE AUTHORITY and a **SELF-ADDRESSED, STAMPED ENVELOPE** to: *Orange County Fire Authority, Atten: Iris Vicent/Prevention Field Services, 1 Fire Authority Rd, Irvine CA 92602* and the records will be mailed to you. If you prefer your records to be emailed to you, please send payment only and indicate the email address you would like the records sent to.



Orange County Fire Authority
Public Records Request - Fire Safety Inspection
06/30/2025
1 Fire Authority Road • Irvine, CA 92602 • 714-573-6000

Filter: Address: 9822 RUSSELL AVE GARDEN GROVE, CA, Historical Inspection Included

Business Records At: 9822 RUSSELL AVE GARDEN GROVE, CA 92844

Bid#: 124299

DBA: IGLESIA DE CRISTO DE RESTAURACION

Status: Active

9822 RUSSELL AVE, GARDEN GROVE, CA 92844

Last Inspection Date: 06/03/2025

Inspection Type: Routine Inspection

Business Type: Church, mosque, synagogue, temple, chapel

No Violations Noted - BID:124299

Permits - BID:124299

Bldg	Permit #	Permit Description	Issued Date	Exp. Date	Occ. Load
	AL1R	Liquefied Petroleum Gas Reissuance	06/03/2025		
	AP23R	Assembly, >300 Occupants - Reissuance	06/03/2025		450

RUSSELL

9822

1

STREET NAME

ADDRESS

APT. NO.

CARD NO.

081-2 BUILDING PERMIT

Department of Building
B. C. Adams
Director

CITY OF
GARDEN GROVE

ZONING AND BUILDING

Use Zone R-4 Variance No. C-435
Map No. 18-08 Main Use ✓ Acc. Use X
Set Back - C/L ST 50 C/L ST 55
Side Yard RF 14' Projection —
Side Yard LI 120 Projection —
Rear Yard — No Parking Sp. Req'd. 159
Zoning Approved By — Date —
Group B-3 Type V Plan Ck. 11
Remarks: —

INSPECTION RECORD

APPROVAL	DATE	INSPECTOR
Foundation and Location	<u>5/9/57</u>	<u>W. K. M.</u>
Reinforcing	<u>—</u>	<u>—</u>
Roof Shig.	<u>4/25/57</u>	<u>W. K. M.</u>
Roof. Frame	<u>3/1/57</u>	<u>W. K. M.</u>
Lot or Drywall	<u>5/2/57</u>	<u>W. K. M.</u>
Plas. Brown Cl.	<u>6/13/57</u>	<u>W. K. M.</u>
Final	<u>7-5-57</u>	<u>W. K. M.</u>
Utility Release	<u>—</u>	<u>—</u>

Remarks:

FEES

Building Permit	\$ <u>40.00</u>	Rec'd By <u>W. K. M.</u> Date <u>5-5-57</u>
Plan Check	\$ <u>20.00</u>	Rec'd By <u>W. K. M.</u>

Permit Authorized By W. K. M. Date 5/15/57

Routing: #1 Bldg. Inspector #2 Office File #3 Statistics #4 Owner

For Applicant to Fill In

Job Address 9822 Russell St. Permit No. 106
Lot No. — Blk. No. —

Please Attach Notes & Drawings (2 Copies)

Owner CHURCH OF CHRIST
Owner's Address 9822 Russell Street
Description of Work NEW CONCRETE
Use of REINFORCED CONCRETE
Building SUN ROOM
Area of Building 360. Valuation \$ 22,000.00
Arch. or E. E. C. C. C. C. Address 15715 Rossmore
Eng. W. K. M.
Contractor OWNER Address 5071 E.

I hereby acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and State laws regulating building construction.

I hereby certify that I am properly registered with and/or licensed as required by the City of Garden Grove and/or State of California, or that I am the legal owner of the above described property, and I certify that in the performance of the work for which this permit is issued I shall not employ any person in violation of the workman's compensation laws of the State of California.

Signature of CHURCH OF CHRIST Date 5/9/57
Permittee W. K. M.

Address 9822 Russell
VALIDATION BY CASHIER

Plan Check

Bldg. Pl.

RELOCATION

PRESENT BLDG. ADDRESS Context: Mrs. RONALD
MOVING CONTRACTOR NEWMAN
ADDRESS 401 B. ON DEVELOPMENT CO.
G. E. R. S. WOOD - GARFIELD

INSPECTION	DATE	REC'D
INSPECTION	DATE	REC'D
REB	REC'D	BY
SURETY	DATE	REC'D
CASH DEP.	DATE	REC'D
RELOCATION AUTHORIZED BY	DATE	BY

CERTIFICATE OF OCCUPANCY

2

DEPARTMENT OF BUILDING

B. C. ADAMS, Director

CITY OF GARDEN GROVE

11391 ACACIA

JOB ADDRESS 3002 Main St PERMIT NO. 200

USE OF BUILDING Day School GROUP D-3 TYPE 2

USE ZONE D-1 APPROVED BY D. B. Smith DATE 2-23-57

ZONING REMARKS

Floor load sign installed per Section 2308 Yes ☐ No ☐

Room capacity sign installed per section 3301 (1) Yes ☐ No ☐

The above described building has been inspected and found to comply with the provisions of the Uniform Building Code.

ISSUED TO City of Garden Grove ADDRESS 3002 Main St

Authorized By D. B. Smith DATE 2-23-57

Notice! Post in a Conspicuous Place on the Premises

DATE 5-12-17 OUR PLUMBING NO. 6214

Handwritten
CITY HLDG. PERMIT NO. 106

OWNER'S NAME St. Luke's Church of Christ

JOB ADDRESS 2222 Spruce

LOT NO.

DATE PLUMBING APPROVED 5-14-17

GARDEN GROVE SANITARY DISTRICT

By G. E. Kennedy

BUILDING PERMIT

Department of Building
D. C. Adams
Director

CITY OF
GARDEN GROVE

ZONING AND BUILDING

Map No. APO Var. No.
Use Zone R-1 Main Use ☒ Arc. Use
St. Set Back - PL PL
Side Yard Rt Projection
Side Yard Lt Projection
Rear Yard No. Parking Sp. Req'd.
Zoning Approved By DR Date 5/20/59
Group B Type 1 Plan Ck. DR
Remarks: Plans attached
See attached letter

INSPECTION RECORD

APPROVAL	DATE	INSPECTOR
Foundation <u>EC</u> and Location <u>BACK</u>		
Reinforcing		
Roof Shing.		
Rough Frame		
Lath or Drywall		
Plas. Brown Cr.		
Final	<u>10-15-62</u>	<u>W. E. —</u>
Utility Release		

Remarks:

Fees

Building Permit	\$ <u>1.00</u>	Rec'd By
Plan Check	\$ <u>—</u>	Rec'd By

Remarks:

Permit Authorized By DR Date 5/20/59

Routing: #1 Bldg. Inspector #2 Office File #3 Statistics #4 Owner

For Applicant to Fill in (Use Ink)

Job Address 9822 Russell St Permit No. 6358

Lot No. Tract No. Blk. No.

Please Attach Notes & Records (2 Copies)

Owner Church of Christ

Address 9822 Russell St

Description of Work

Use of Building Remodel Toilet

Area of Building — Valuation \$ 75.00

Arch. or Engr. Address

Contractor Owner Phone

Address

I hereby acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and State laws regulating building construction.

I hereby certify that I am properly registered with and/or licensed as required by the City of Garden Grove and/or State of California, or that I am the legal owner of the above described property, and I certify that in the performance of the work for which this permit is issued I shall not employ any person in violation of the workmen's compensation laws of the State of California.

Signature of Permittee DR Date 5-20-59

Address Lic. No.

PUBLIC WORKS

Street Imp. By Date

RELOCATION

PRESENT BLDG. ADDRESS

MOVING CONTRACTOR

ADDRESS

INSPECTION FEE

SURETY

CASH DEP.

RELOCATION AUTHORIZED BY

DATE REC'D BY

DATE REC'D BY

DATE REC'D BY

DATE REC'D BY

DATE REC'D BY

PLOT PLAN

Department of Building
B. C. Adams
Director

CITY OF
GARDEN GROVE

Job
Address

9822 Russell

Permit Number


6358

Lot

Tract

Blk.

DIMENSION PLOT PLAN COMPLETELY SHOWING
ALL DIMS. ON THE LOT AND THEIR USE



INSTALL 1 3/4" SOLID SLAB DOOR

I certify the information furnished hereon is complete and correct. By _____ Date _____

Routing: 31 Building Inspector

32 Office File

33 Owner

BUILDING PERMIT

Department of Building

B. C. ADAMS, Director

CITY OF
GARDEN GROVE

ZONING AND BUILDING C-267

Use Zone R1 Main Use 1 Acc. Use 1 Var. No. C-425

St. Set Back - 12' PL R5' PL

N Side Yard 16' Projection

S Side Yard 30' Projection

Rear Yard 20' No Parking Sp. Reqd. 126

Zoning Approved By RDP Date 9-21-61

Group B-2 Type VTH Plan Ck. ECM

Remarks:

INSPECTION RECORD

AF/VAL	DATE	INSPECTOR
Foundation and Location <u>SLC</u>	<u>11-20-61</u>	<u>SLC</u>
Reinforcing		
Roof Shtg.		
Rough Frame		
Loth or Drywall		
Flas. Brown Ct.		
Other		
Land Use		
Final		
Utility Release		

FEES

Plan ECM Building Permit \$128.00
Check 7-41 \$64.00
Bond \$ Expiration Date 10-20-61

Permit Authorized By JS Date 10-20-61

Routing: #1 Bldg. Inspector #2 Office File #3 Statistics #4 Owner

For Applicant to Fill in (Use Ink) PC-6117

Job 9522 Russell Permit No. 16931

Address 1123 W. North St. Anaheim

Lot No. Tract No. Blk No.

Please Attach Photos & Bounds (2 Copies)

Owner Church of Christ (Christian)

Owner's Address 1123 W. North St.

Description of Work New ☒ Add'n ☐ Remodel ☐ Relocate ☐

Use of Building Sanctuary

Area of Building 6800 sq. ft. Valuation \$ 54,500.00

Validation OCT 30-61 11 001 100 128.00

Arch. or Engr. A. TURNER Address

Contractor AL. MAHONEY Phone Kp 5-7995

Address 1123 W. North St. Anaheim

I hereby acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and State laws regulating building construction.
I hereby certify that I am properly registered with and/or licensed as required by the City of Garden Grove and/or State of California, or that I am the legal owner of the above described property, and I certify that in the performance of the work for which this permit is issued I shall not employ any person in violation of the workmen's compensation laws of the State of California.

Signature of Permittee Paul H. Miller Date 5/7/61

Address Lic. No.

RELOCATION

PRESENT BLDG. ADDRESS

MOVING CONTRACTOR ADDRESS

PUBLIC WORKS

Street Address OK By OK 8-7-61

Record of Survey REQUIRED PROVIDED

R/W Dedication REQUIRED PROVIDED

Bonds REQUIRED PROVIDED

Encroachment Permit REQUIRED PROVIDED

Remarks

DEWING

7/2/62
Bldg ok except door Balto on porch
Hole on main Entry South entry
Fire hood in storage area from furnace
Room. Stair well to be prop of furnace Room
with separation at mezz level
Fire hood + separation to stairs & S
shown on plan -

10 parking spaces & masonry fence
separates bty.


B-5 1111 1111

BUILDING RECORD

7.

Permit Number
16931
PC 611
DIR.

Lat Trock



13 Owner *Khaf/Ken* Date

1

For Applicant to Fill in (Use Ink)

262/2

BIL. No.

Church of Christ

9822 Russe

City Lic. No.

JUN 27-62 11 061 H *** 4.00

Recd. Ballantyne Dated 27 Jan 62

9712 562400N J.S.

INSPECTOR

UTILITY CO, NOTIFIED

Permit Authorized By

Date 6-22-62

Bldg. Permit #/

PLUMBING PERMIT

Department of Building
B. C. Adams
Director

JE 7-4200

CITY OF
GARDEN GROVE

PERMIT FEES

No.	TYPE OF FIXTURE OR ITEM	EACH	\$	PER
7	Water Closet (Toilet)	\$1.00	7	00
	Bath Tub	1.00		
	Shower	1.00		
9	Lavatory (Wash Basin)	1.00	9	00
1	Kitchen Sink	1.00	1	00
	Garbage Disposal	1.00		
1	Laundry Tub or Tray	1.00	1	00
2	Water Heater	1.50	3	50
	Slop Sink	1.00		
5	Floor Sink	1.00	5	00
	Floor Drain	1.00		
	Dish Washer	1.00		
1	Drinking Fountain	1.00	1	00
1	Urinal	1.00	1	00
1	Gas System 4 Outlets	1.00	1	00
	House Sewer	1.00		
	Lawn Sprinklers	2.00		
	Swimming Pool Piping	1.00		
	Sand Traps	1.00		
	Automatic Washing Mach.	1.00		
	Water Softeners	1.50		
	Backwash	1.50		

Issuance of Permit

2 00

TOTAL FEE

\$ 31.50

Permit Authorized By *SEA*

Date *11-15-61*

Routing: #1 Plumbing Inspector

#2 Office File

#3 Owner

Bldg. Permit # *16931*

For Applicant to Fill in (Use Ink)

Job *9822 RUSSELL*
Address *ST.*

Permit No. *24244*
24244

Lot No. Tract No. Blk. No.

Owner *Church Christ*

Owner's Address *9822 Russell*

Plumbing Contractor *J. H. Burns*

Contractor's Address *549 S. P. ST.*

Phone *KE 54866* City Lic. No.

Use of Bldg. *Church*

New Bldg. ☒ Old Bldg. ☒ *SANCTUARY*

Validation *NOV 15-61 11 000 H-44431501*

I hereby acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and State laws regulating plumbing.

I hereby certify that I am properly registered with and/or licensed as required by the City of Garden Grove and/or State of California, or that I am the legal owner of the above described property, and I certify that in the performance of the work for which this permit is issued I shall not employ any person in violation of the workmen's compensation laws of the State of California.

Signature of Permittee *J. H. Burns* Date *Nov 14/61*

Address

APPROVALS DATE INSPECTOR

SOIL PIPING

GROUND PLUMBING *11-23-61 R. 9910*

ROUGH PLUMBING *3-16-62 R. 9910*

GAS PIPING

GAS VENT

SEPTIC TANK or Cesspool

SEWER

GAS TEST *6-22-62 R. 9910*

MAIN DRAIN AND VACUUM LINES

WATER HEATER

BACKWASH

FINAL *7-11-62 R. 9910*

UTILITY CO. NOTIFIED

Red spot of the

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

W. L. F. L. - W. L. F. L.

9/15/60

UNITED STATES DEPARTMENT OF JUSTICE

CRIMINAL DIVISION

NEW YORK OFFICE

MAILED 10/1/60

RECEIVED

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

10/1/60

BLANKING PERMIT

1

UTILITY CO. NOTIFIED

#1 INSPECTOR #2 OFFICE FILE #3 OWNER

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

Unit 1 5000

ELECTRIC PERMIT

Department of Building
B. C. Adams
Director

CITY OF
GARDEN GROVE
JE 7-4200

LOT NO.

TRACT NO.

	NUMBER	EA.	FEE
New Residence Sq. Ft.		.01	
Residential Garage Sq. Ft.		.005	
Services		1.00	
Meters		1.00	
Fixtures 1st 20		.20	4.00
Fixtures, Additional		.10	8.70
Fixtures, Mercury Vapor		1.00	
Outlets, 1st 20		.20	4.00
Outlets, Additional		.10	3.50
Any Pole		2.00	
Dryer		1.00	
Dishwasher		1.00	
Furnace		1.00	
Garbage Disposal		1.00	
Fan		1.00	
Heater Inc. 1650 W	2	.50	1.00
Domestic Range		1.00	
Domestic Oven		1.00	
Motors—Not Over 1 H.P.	4	1.00	4.00
Motors Over 1 Not Over 3 H.P.	1	1.50	1.50
Motors Over 3 Not Over 8		2.00	
Motors Over 8 Not Over 15		2.50	
If Not Listed Above, See Code			
2		1.00	12.00

Permit Fee

2.00

Total Fee

30.30

Authorized

Applicant Fill in (use ink)
Job Address

Electric Permit No.

9822 RUSSELL ST. 16347

Owner CHURCH OF CHRIST
Owner's Address 9822 RUSSELL ST.

New Bldg. ☒ Old Bldg. ☐ Use—

Electrical Contr. FEM ELECTRIC CO.

Address 702 S. Los Angeles ST.

Phone KES-6410 State License No. 145775

Validation NOV 20-61 11 002 M 44333.30

I hereby acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and State laws regulating electrical wiring.

I hereby certify that I am properly registered with and/or licensed as required by the City of Garden Grove and/or State of California, or that I am the legal owner of the above described property, and I certify that the performance of the work for which this permit is issued I shall not employ any person in violation of the workmen's compensation laws of the State of California.

Signature of Permittee

Date 11-20-61

SIGNS

One Sign—I Transformer	2.00
Additional Sign, Same Location	1.00
Additional Transf. or flashers, Time Clock	1.00
Lamp Holding Devices, 1st 20	.05
Lamp Holding Devices, Next 100	.03
Sign and I Transformer, Moved	
Altering or Changing Lettering	
For Connecting (Hook-up)	
Permit Fee	2.00

Total Fee

Date

Inspector

Conduit

Wiring

Fixtures

U. G.

Sign Footing

Final

Utility Notified

Service Size, Amp.

Wire

Conduit

Inspection Permit No.

GARDEN GROVE CHURCH of CHRIST

(CHRISTIAN CHURCH)

RICHARD L. MILLER, MINISTER

DAVID W. WEAD, MIN. OF ED.

2822 RUSSELL STREET

GARDEN GROVE, CALIFORNIA

P. O. BOX 185

JEFFERSON 7-4190


June 27, 1962

Mr. Barney Adams
Building Dept.
City of Garden Grove

Dear Mr. Adams:

This letter is an acknowledgment to your office that at such time as traffic congestion makes it necessary, and it is requested by the City of Garden Grove, this congregation will conform to the letter of the zoning ordinance by providing eleven additional off-street parking spaces for our church facilities.

Very sincerely,


Richard L. Miller,
Minister

"Giving diligence to keep the unity of the Spirit in the bond of peace." Eph. 4:3

RUSSELL		9822		2
STREET NAME		ADDRESS	APT. NO.	CARD NO.

Tense waves

THESE WAVE

8-15-62

CHURCH OF CHRIST.
9822 Russell

(L 5)

No. 1 - 5' FENCE - ^{100'} IN COMPLETE SOUTH PL.
(East Pl) SCHOOL
FENCE REQUIRE ?

No. 2. ^{42 spaces} OFF STREET IMPROVEMENTS ARE
BETWEEN NEW SANCTUARY AND
EXISTING CHURCH EDUCATION PLDS.

No. 3. Panic HARD REQUIRED AT
(1st) DOOR. (NO) 4 DOOR. }
Main entrance NO 4 DOOR }
=

No. 4 FIRE DOORS - (2)

K - DOOR REMOVED TO FITTING OF
STAIRS PER MENDENHALL

PASTOR

DICK MILLER

August 22, 1962

Re: ~~Dist. William~~
~~Chamber of Commerce~~
~~9000 Highway 1~~
~~Garden Grove, California~~

Re: C-260
C-435

Dear Sirs:

In reference to building permits 6350 and 16931 which have
not received final building approval.

Please advise this Department within 7 days, in writing, when
you agree to complete these permits.

Yours very truly,

William K. Miller
Senior Building Inspector

WKS:ha

GARDEN GROVE CHURCH of CHRIST

(CHRISTIAN CHURCH)

RICHARD L. MILLER, MINISTER
DAVID W. WEAD, MIN. OF ED.

9822 RUSSELL STREET

GARDEN GROVE, CALIFORNIA

P. O. BOX 185
August 26, 1962

JEFFERSON 7-4190

Mr. William E. Miller,
Senior Building Inspector
City of Garden Grove, 11391 Acacia St.
Garden Grove, California

Dear Mr. Miller:

This letter is in reference to your correspondence of August 22, 1962 regarding C-269 and C-435. We realize that this problem regarding permits 6358 and 16931 is current and it will receive prompt attention.

We have not been able to have a building committee meeting to appropriate the needed funds but this situation will be handled within a matter of days and the contractor will be instructed to make the necessary changes.

Thank you very much for your patience and understanding with regard to this matter.

Very sincerely,

Richard L. Miller
Richard L. Miller, minister

RLM/dw

Received
8-31-62

"Giving diligence to keep the unity of the Spirit in the bond of peace." Eph. 4:3

October 1, 1962

Reverend Richard L. Miller
Garden Grove Church of Christ
5822 Russell Street
Garden Grove, California


Dear Reverend Miller:

Your letter of September 20th requesting one-year extension of time for construction of a wall on the south side of the Church property and for completion of Church parking lot at 5822 Russell Street was considered by the Garden Grove City Council on September 25th.

This is to advise you that the Council did approve your request for one-year extension of time for completion of these two items.

Very truly yours,

CITY OF GARDEN GROVE


CITY CLERK

GW:rs

cc: Building Department

September 7, 1962

Mr. Richard L. Miller
City Council Member
San Francisco, California

Dear Sir:

I have reviewed the entire file on the construction of the proposed building at 1022 Divisadero Street.

The site has not been completed in accordance with the ordinance and the approved plans. It will be necessary to complete construction of the building and parking, in accordance with the approved plans. And to remove the illegal exit hardware at the main entrance and to complete the exit in accordance with the approved plans. The building is situated on the site in accordance with the Division Building Code. It will be necessary to remove all trees and the main entrance, the exit doors before the building is occupied. The safety of the occupants is at stake and it is necessary that the illegal exits be corrected before the building is used for any purpose.

The elimination of fencing and required parking can be done only under a variance procedure. This Department has previously taken a liberal approach, allowing a few weeks or months for the completion of such facilities when the situation warranted. The Department does not have the authority to make exceptions to the zoning ordinance and we refer you to the various provisions thereof for the elimination of required parking be justified.

Your immediate attention to these matters will be greatly appreciated.

Kindly notify this office in writing within seven days of the action you intend to take regarding the fencing and parking. We request you to place on the site hardware at the safety of occupants of the building is at stake.

Very truly yours,

Richard L. Miller
Director
Department of Planning and Development

GARDEN GROVE CHURCH OF CHRIST

CHRISTIAN CHURCH OF GARDEN GROVE

RICHARD L. MILLER, MINISTER
DAVID W. WEAD, ASST. MIN.

2022 RUSSELL STREET

GARDEN GROVE, CALIFORNIA

P. O. BOX 185

JEFFERSON 7-4190

October 7, 1963

THE CITY COUNCIL
Garden Grove, California

Gentlemen and Mrs. Barr:

We are writing at this time pursuant to your letter of October 3, 1963 in which you suggest we submit a revised letter concerning the block wall and the parking area on our church property.

In our previous letter we made a request for an extension of one year for construction of the block wall. This request was made because our compliance to the requirement at this time would impose an extremely difficult financial burden upon the congregation. In another twelve months our constituency will be larger and all the extra bills and unforeseen expenses of occupancy of the new building will be paid. It will then be possible for us to make a successful appeal for funds for the construction of the wall.


In earlier correspondence an appeal was made for an extension of time for the 11 or 12 additional parking spaces until there was a need for them. We endeavored to give full assurance that at such time as they were needed we would remove the lawns, landscaping, sprinkling system, etc. and put them in. Our request for extension with regard to this requirement is made primarily on the basis of three important considerations:

- (1) The esthetic beauty of the church grounds would be greatly affected. The courtyard between the buildings is beautifully landscaped.
- (2) The need for these 11 or 12 spaces has not yet been apparent even on such days of large attendance such as Easter Sunday and Christmas. Only last Sunday we had a capacity attendance of 388 in one service and prompted by the present concern over this matter an actual count was made of the empty spaces in the parking lot now provided. It was discovered there were 48 empty spaces in spite of the large attendance.
- (3) A safety factor is involved which, undoubtedly, should be a prime consideration. The Educational Building on the south side of the area involved houses a nursery and classrooms for preschool through sixth grade. These children, in spite of supervision, will be darting across to the church sanctuary which is situated on the north side of the courtyard. With automobiles backing in and out of the area a distinct danger would be created.

We believe it would be a shame to destroy the landscaped beauty of the courtyard and a tragedy to produce a safety hazard for the Sunday School children for want of 11 or 12 more black-topped parking spaces when fully 1/3 to 1/2 of our existing paved parking remains unused. We therefore ask that an extension be granted until such time as the space is actually needed for its required use.

Again we wish to thank you for your very thoughtful consideration of this matter and would prayerfully request a favorable decision.

Very Sincerely,



Richard L. Miller, Minister

"Giving diligence to keep the unity of the Spirit in the bond of peace." Eph. 4:3

City of Carlin, Nev.
INTER-DEPARTMENTAL MEMORANDUM

To:	HARRY R. PIERCE	From:	STEWART C. MILLER
Dept:	BUILDING	Dept:	BUILDING
Subject:	CHURCH OF CHRIST - 9822 RUSSELL ST. EXTENSION OF EXISTING ONE YEAR EXEMPTION FOR COMPLIANCE OF OFF-STREET PARKING AND BLOCK WALL.		
Date:	OCTOBER 7, 1962		

A brief review of this project is as follows:

On October 10, 1961 we issued a permit for the construction of a sanctuary. The sanctuary has 370 fixed seats and 39 fixed seats in chairs left. Our Code requires one space per three fixed seats, therefore minimum required parking 126 spaces which is what the approved plan provided - the minimum of 126 spaces. This permit also required a masonry fence contemplated in the Municipal Code between this lot and adjoining residential property. Final inspections on this project was commenced during the month of June, 1962.

On June 27, the minister of this church, Richard L. Miller sent our department a letter stating that they would put in the additional off-street parking spaces when required to do so by the City of Carlin. There - twelve was what was required.

On August 22, 1962, our department notified Reverend Miller in writing that he had not received final inspection on his building. We requested him to notify our department within seven days that he intended to complete the permit issued.

On August 26, 1962 Reverend Miller answered by stating that they would have a building committee meeting to appropriate the necessary funds and that the situation would be taken care within a matter of days.

On September 7, 1962 Mr. Adams of our department wrote a letter to Reverend Miller stating they were utilizing a building that had illegal locking devices on their exit doors, a required fence had not been installed, that the required off-street parking had not been provided, and that the site had not been surveyed in accordance with Ordinances or the approved plan. Mr. Adams advised Reverend Miller that if he did not wish to comply with the requirements on the fence that he could apply through the Planning Department on a variance procedure. This letter again requested Reverend Miller to reply within seven days on the above.

On September 20, 1962, Reverend Miller wrote directly to the City Council c/o Mayor Harold requesting a year extension on the parking and fence requirements. On October 1, 1962, he was notified by the City Clerk that the Council had granted a one year extension, the locking devices were changed to comply with F.D.C.

SUMMARY:

The requirements for off-street parking and the fence have been known by this church for two years dated from the date of issue of permit. These requirements are shown on all approved plot maps and on the permit itself. The parking requirements are the same imposed on all churches having been constructed in Garden Grove in the past few years and there have been many. I see no justification for requiring several churches to provide one minimum and not requiring this specific one. This has been a hardship for all of them I am sure-but they have provided them.

The fence is also a requirement of our Municipal Code and again has been provided by all churches having been built in the past few years. Moreover, another delay after two years knowledge of its requirement serves no useful purpose. Therefore, it is suggested that this fence be installed or that as suggested in Mr. Lemo's letter of September 7, 1962, a variance be requested for waiver or bonding as provided in the Municipal Code.

Stewart G. Miller

cc:

cc: W.R. Miller - Senior Building Inspector

Mr. Dudley Lapham

City Administrator

Block Wall and Parking for
Garden Grove Church of Christ

Harry E. Peirce

Building

October 11, 1963

I see no objection to an extension of one year for construction of the block wall since we have received no complaints from the adjacent property owner concerning the lack of the wall. However, I would recommend that the request be granted as a final extension.

Concerning the 12 parking spaces which are required by the Municipal Code, it is my opinion that they should be provided at this time. The aesthetic and safety considerations referred to in Rev. Miller's letter should have been taken into account in the original design and of course, these problems can still be surmounted by the acquisition of adjoining property. I believe the point raised concerning "no apparent need" to be an invalid one since, if property owners were permitted to provide the required number of parking spaces only when they believe the need for off-street parking is apparent, the intent of the off-street parking regulations would soon be negated and the enforcement of these regulations under such a provision would be an impossible task.

Harry E. Peirce

js

cc: Elaine Martin
✓ Stewart Miller

HRT

September 18, 1963

Reverend Richard L. Miller
Garden Grove Church of Christ
2022 Russell Street
Garden Grove, California

Dear Sir:

Reference is made to your letter of September 20, 1962 in which you requested from the City Council a one year extension to complete your required parking area and a block wall fence. On October 1, 1962 you were notified by letter from the City Clerk that the City Council had approved your request for a one year extension on September 25, 1962.

This letter is a reminder that your requested time extension expires on September 25, 1963 at which time we are to make an inspection for compliance. The extension of time for one year to complete your original permit was a time requested by you. This in essence was your guarantee to the City Council that you would comply on or before the date you specified. Therefore, it is anticipated that our inspection on September 26, 1963 will indicate that compliance has been accomplished.

Very truly yours,

Stewart O. Miller
Zoning Technician

cc

cc: Owen Lerner - City Clerk
Harry W. Fairco - Director Building Dept.
William K. Miller - Senior Building Inspector

June 18, 1964

Reverend Richard L. Miller
Garden Grove Church of Christ
5127 Russell Street
Garden Grove, California

Dear Sir:

Your request to the City Council for waiver of eleven parking spaces has been referred to this department for review.

Recently, the Planning Department prepared an amendment to the Municipal Code which permits churches to count curbside parking spaces as contributing to required off-street parking.

The Planning Commission has recommended approval of this amendment, which will be considered by the City Council on July 7, 1964. Should the Council adopt the amendment, your requested waiver will be unnecessary.

We will advise you of the Council's action.

Yours very truly,

James C. Cropper

James C. Cropper
Assistant Planning Director

cc: 1

cc: Planning Department
cc: [unclear]

GARDEN GROVE CHURCH of CHRIST

(CHRISTIAN CHURCH)

RICHARD L. MILLER, MINISTER

GARY H. DAVIS, YOUTH MINISTER

3522 RUSSELL STREET

GARDEN GROVE, CALIFORNIA, 92642

P. O. BOX 185

JEFFERSON 7-4190

APR 15 10 12 AM '64

April 15, 1964

City Council of Garden Grove
11391 Acacia
Garden Grove, California

Dear Sirs:

We deeply appreciated the six month delay for construction of a block wall along the portion of our parking lot that borders an R-1 property. This wall was completed about March 1 of this year.

Our previous letter asked, in addition to this delay, a waiver of the requirement for eleven more parking spaces. It has been found that even on days of largest attendance, such as Easter Sunday, March 29, our present off-street parking provision is more than adequate, there being several parking stalls left unused. We would therefore petition the council's consideration of our request for waiver of these eleven spaces.

Earlier correspondence has shown in detail other reasons for our request. Should this correspondence not be readily available for your reconsideration, we would be most happy to reassemble those facts in another letter.

The city has been very considerate and very generous and we are extremely grateful.

Respectfully,

Richard L. Miller
Richard L. Miller

RL:m

"Giving diligence to keep the unity of the Spirit in the bond of peace." Eph. 4:3

April 8, 1964

Reverend Richard Miller
Garden Grove Church of Christ
3522 Gastell Street
Garden Grove, California

Dear Mr. Miller:

Reference is made to the City Council meeting of October 15, 1963 in which you requested a six month extension of time to comply with the off-street parking and fencing requirements. I wish to advise you that the six month extension terminated March 15, 1964.

Our inspector, Mr. Len Miller, will make an inspection of the property on April 13, 1964 unless you would prefer another date. If you prefer a different date, please contact Mr. Len Miller or myself prior to said date.

Sincerely yours,

Stewart D. Miller
City Engineer

cc

cc: Owen Benson - City Clerk
Harry H. Faires - Director Building & Safety
Ken Miller - ex. Building Inspector

9822 Russell

October 18, 1963

Reverend Richard L. Miller
Garden Grove Church of Christ
Post Office Box 146
Garden Grove, California

Dear Reverend Miller:

I am pleased to confirm the action of the Garden Grove City Council taken October 15, 1963, on request of the Church for an extension of time to comply with the requirements of construction of a block wall along a portion of the southerly boundary of the Church parking lot and for compliance with parking requirements.

The City Council did grant a six-month extension of time for completion of these two items.

Very truly yours,

CITY OF GARDEN GROVE

Ed W. Irwin
Ed W. Irwin
CITY CLERK

Building Department

RUSSELL		009822			3
STREET NAME		ADDRESS		APT. NO.	CARD NO.

September 19, 1963

Reverend Richard L. Miller
Newman Grove Church of Christ
8710 Marshall Street
Carson, California

Dear Sir:

Reference is made to your letter of September 20, 1962 in which you requested from the City Council a one year extension to complete your proposed parking area and a block wall fence. On October 1, 1962 you were notified by letter from the City Clerk that the City Council had approved your request for a one year extension on September 27, 1962.

This letter is a reminder that your requested one year extension expires on September 27, 1963 at which time we are to make an inspection for compliance. The extension of time for one year to complete your original permit was a time requested by you. This in addition was your guarantee to the City Council that you could comply on or before the date you requested. Therefore, it is anticipated that any inspection on September 27, 1963 will indicate that your plans have been accomplished.

Very truly yours,

Richard L. Miller
City Engineer

cc

City Engineer - City Clerk

City Engineer - Director of Public Works

City Engineer - Mayor's Office

APPLICATION FOR A BUILDING PERMIT

DEPARTMENT OF BUILDING, GARDEN GROVE, CALIF.

LOOSE 1-10-1-0 INFORMATION PROVIDED BY BLDG. DEPT.

EXTERIOR WALL MATERIAL ROOF FRAMING MATERIAL

PARTITIONING MATERIAL ROOF COVERING MATERIAL

LOT WIDTH LOT DEPTH NO. OF EXISTING BLDGS. ON LOT

USE ZONE R-1 FIRE ZONE OCC. PANG TYPE

RECD SET BACKS 2-6' To E HOLE

SITE PLAN NO. USE PERMIT OR VARIANCE NO. PARK SPACES REQD.

Zoning Approved By ECM Date 2-16-66

Remarks: PLAN ATTACHED

PUBLIC WORKS

Street Address By REQUIRED PROVIDED

Record of Survey

R/W Dedication

Bonds

Encroachment Permit

Remarks

INSPECTION RECORD

APPROVAL DATE INSPECTOR

Foundation and Location

Reinforcing

Roof Shtg.

Rough Frame

Lath or Drywall

Plas Brown Ct.

Other

Land Use

Final

Utility Release

VALUATION NOTE: VALUE LABOR, MAT. \$ 550

FEE

Plan Check \$ 2.50 Building Permit \$ 5.00
Bond \$ Expiration Date

Permit Authorized By ECM Date 2-16-66

INSTRUCTION: USE TYPEWRITER OR BALL POINT PEN, PRESS FIRMLY. BE SURE ALL COPIES ARE LEGIBLE. NO ERASURES PERMITTED. A DOUBLE FEE WILL BE CHARGED IF WORK IS STARTED BEFORE PERMIT IS ISSUED.

Job Address

9812 Russell St

Permit No.

014355 A

Lot No.

Tract No.

Blk No.

CONTRACTOR

9812 Russell St

STATE LIC. NO.

MAILING ADDRESS

TEL. NO.

ARCH.

TE 7-4190

ENGR.

STATE LIC. NO.

MAILING ADDRESS

TEL. NO.

OWNER

Church of Christ

TEL. NO.

TE 7-4190

MAILING ADDRESS

NEW ☒ ADD'N ☐ ALTER ☐ REPAIR ☐ DEMOLISH ☐

FLOOR AREA (SQ. FT.)

NO. OF STORIES

NO. OF DWELLING UNITS

PRESENT BLDG. USE

PROPOSED BLDG. USE

Validation

DESCRIBE WORK TO BE DONE

POLE SIGN

OWNER-BUILDER PERMIT RESTRICTIONS: An owner-builder must reside within the building for which this permit is issued, (accessory buildings excepted). Said building may not contain more than 3 dwelling units. Otherwise, this permit can be issued only to a contractor licensed in the State of California and a business license must be procured from the City of Garden Grove.

WORKMEN'S COMPENSATION INSURANCE REQUIREMENTS: A certificate or duplicate thereof of workmen's compensation insurance must be on file with the City of Garden Grove prior to the issuance of this permit unless: 1. This permit is for less than \$100 valuation or, 2. The applicant qualifies as an owner-builder and signs the statement below.

I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the workmen's compensation laws of California.

SIGNATURE: Church of Christ
108 Adams Avenue
Chairman Board of Justices

FOR CERTIFICATE ON FILE

APPLICANT'S CERTIFICATION: I have carefully read and examined the above application and find the same to be true and correct. All provisions of the laws and ordinances of the City of Garden Grove and State of California will be complied with whether specified herein or not.

Signature of Permittee

Date

BUS. LIC. NO.

Address

RELOCATION

PRESENT BLDG. ADDRESS

MOVING CONTRACTOR

ADDRESS

PLOT PLAN

Department of Building

CITY OF
GARDEN GROVE

Job Address

9822 RUSSELL

Permit Number

14355A


Lot

Tract

Blk.

S-2997

DIMENSION PLOT PLAN COMPLETELY SHOWING
ALL BLDGS. ON THE LOT AND THEIR USE



CHURCH
BLDG

CHURCH BLDG

SECTION OF
5' SIGN
NO PROJECTION

RUSSELL ST

I certify the information herein is complete and correct.
Routing: 1 Building Inspector 2 Office File -3 Owner

Church of Christ
By W. H. H. H. H. H. Date 2-16-66

The North 256 feet of the East 378 feet of that part of the South half of the Southeast quarter of the Northeast quarter of Section 6, Township 5 South, Range 10 West, in Rancho Las Bolsas, as said Northeast quarter of Section 6 is shown on a map of Tract 1539, recorded in book 45, pages 29 to 31 inclusive, Miscellaneous Maps, records of said County, lying West of the East 10 acres of said South half;

Except therefrom that portion lying within the land described in deed to George M. Thomas and Naomi Ruth Thomas, husband and wife, as joint tenants, recorded January 6, 1953, in book 2432, page 164, Official Records.

NOTE: Said land is described on the County Tax Assessment Roll for the fiscal year 1964-65 as A. P. No. 98-081-19; CA 18-035.

CITY OF GARDEN GROVE

TO: MR. LAPHAM, MR. PERROE, MR. HEANDY DATE: 9-25-63 1963

FROM: MR. LAPHAM, MR. PERROE, MR. HEANDY

SUBJECT: & MR. LAPHAM
SUBJECT: & MR. PERROE

REFERENCE: REFERENCE:

- ☐ FOR YOUR APPROVAL/SIGNATURE
☐ AS YOUR REQUEST
☒ PLEASE RETURN/HANDLE
☐ PLEASE ACKNOWLEDGE

The attached request was considered by City Council 9-24-63
and deferred one week for review and recommendation.
and deferred one week for review and recommendation.

Please review and forward any reports you may have on this
matter to Mr. Lapham so that this may be listed for further
consideration by City Council 10-1-63.

See attached letter from Stewart
FROM: Gwen

M
H
C
C
R
A
M

GARDEN GROVE CHURCH OF CHRIST
(CHRISTIAN CHURCH)

9822 RUSSELL STREET

GARDEN GROVE, CALIFORNIA

P. O. BOX 185

JEFFERSON 7-4190

RICHARD L. MILLER, MINISTER
DAVID W. WEAD, MIN. OF ED.

September 20, 1962

RECEIVED
CITY OF GARDEN GROVE
SEP 19 3 25 PM '62

The City Council
c/o George B. Harold, Mayor
11391 Acacia Street
Garden Grove, California


Dear Sirs:

I am writing with regard to the completion of our building program and asking that the council give consideration to a completion of one item of this program.

We are asking a delay of one year for the construction of a wall approximately 175 feet in length on the south side of our property for the completion of our parking.

We have completed and have passed inspection on all other items concerning this building program. Your favorable consideration of this item will be deeply appreciated.

Very Sincerely,



Richard L. Miller, minister

"Giving diligence to keep the unity of the Spirit in the bond of peace." Eph. 4:3

GARDEN GROVE CHURCH OF CHRIST

(CHRISTIAN CHURCH OF GARDEN GROVE)

RICHARD L. MILLER, MINISTER
DAVID W. WEAD, ASST. MIN.

8222 RUSSELL STREET

GARDEN GROVE, CALIFORNIA

P. O. BOX 185

JEFFERSON 7.4100

SEP 23 8 51 AM '63

September 21, 1963

City Council
Garden Grove, California
c/o Owen Wisner, City Clerk

Dear Gentlemen and Mrs. Barr:

Being aware of the fact that the time is drawing near for our compliance to the requirement of the construction of a block wall along approximately one-half of the southerly boundary of our church parking lot, we respectfully request of the council an extension for a period of one year.

The financial strain necessitated upon the congregation by the construction of this wall would be extremely difficult to bear at this time. We would appreciate very much your favorable consideration of this request.

Thanking you very much, I remain,

Sincerely yours,

Richard L. Miller
Richard L. Miller
Minister

RIM:m

"Giving diligence to keep the unity of the Spirit in the bond of peace." Eph. 4:3

GARDEN GROVE CHURCH of CHRIST

(CHRISTIAN CHURCH)

RICHARD L. MILLER, MINISTER
BEN GALLUP, MIN. OF ED.

9822 RUSSELL STREET

GARDEN GROVE, CALIFORNIA

P. O. BOX 185

JEFFERSON 7-4190

Address: 9822 Russell St. Garden Grove, California

Legal description of Land:

The North 256 feet of the east 378 feet of that part of the south half of the south east quarter of the northeast quarter of section 6, township 5 south, range 10 west in the Rancho Las Bolsas, county of Orange, state of California, as said northeast quarter of section 6 is shown on a map of tract no. 1539 recorded in Book 44, pages 29-31 inclusive of miscellaneous maps, records of said county, lying west of the east 10 acres of said south half.

Except therefrom that portion thereof lying within the land described in deed to: George M. Thomas and Naomi Ruth Thomas, Husband and Wife as Joint Tenants, Recorded January 6, 1953 in Book 2432, Page 164, Official Records.

CITY OF GARDEN GROVE

TO: Cline Martin & Harry R. Irce

DATE 10-8-63 196

SUBJECT:

☐ FOR YOUR APPROVAL/SIGNATURE

☐ AS YOU REQUESTED

REFERENCE:

☐ PLEASE RETURN/HANDLE

☐ PLEASE ACKNOWLEDGE

Would you please review the attached and submit any comments that you may have on the request to Mr. Lapham by Friday morning, 10-11-63...as this matter will be placed on the City Council Agenda of 10-15-63.

MEMOGRAM

Thanks -- Gwen

FROM

GENERAL TESTING & INSPECTION INCORPORATED

LUMBER INSPECTION FIELDWORK CONSULTATION LABORATORY

2019 N. KILPATRICK

P. O. BOX 5622

PORTLAND 17, OREGON

BUller 5-3631

REPORT AND CERTIFICATE
of the Continuous Inspection of the
of the Laminated Structural Members

Date Dec. 28, 1961
No. 6-5420-15

FOR: CHURCH OF CHRIST, Gooder Group, California
FOR: CHURCH OF CHRIST, A. L. MAHONEY
A. L. MAHONEY

AT: TIMBER STRUCTURES, INC.
P. O. Box 3782, Portland, Oregon

Their No. 611787

- 2 A-1 7" x 15" & Var. - 32' 10" x 4" EE bay/220' 0" span of 20' 6" var. lams 9' 6" Radius
2 A-2 7" x 15" & Var. - 33' 22 1/2" EE bay/220' 0" span of 20' 6" var. lams 9' 6" Radius
6 A-3 7" x 15" & Var. - 33' 6" x 18" EE bay/220' 0" span of 20' 6" var. lams 3/4" 9' 6" Radius
1 C-1 1 1/2" taper to 4" square - 36' 0" off 7 lams 1 1/2" x 5/8" No Comer

SPECIFICATIONS: Finish For AITC ARCHITECTURAL Appearance Data:

LUMBER - ALL DOUGLAS FIR GRADED IN ACCORDANCE WITH W. C. L. A.

ROLES IS & W. C. L. A. & U. S. C. SPECS FOR GLULAM MBRS.

Spec. Combo #5 All lams Select Structural. Slope of grain top & bottom 10% 1:16 except C-1 All lams full length

Moisture 7-16% 5% Max Ver Scarfs 1:10 well scatter in
Glue C-1 Exterior, MII-A-397-B, tension area
Special Bal. Casein, MM-A-125

All lams full length
grain slope top & bottom
10% full length
all lams full length
scarf 1:10 well scattered
Moisture 7-16%
MII-A-397-B
MM-A-125

MARKED	LUMBER	TEMPERATURE	GLUE	ASSEMBLY	OPEN-CLOSED	CURK	CLAMP	REMARKS
NO.	NO.	° F	WT.	BY-PULIN CLAMP				
(1) A-1	5	7-12-61 53° 52' 64" 10"	95#	8:00 9:00 9:00	40 60	12 1/2	115#	2.1
(2) A-2	5	7-12-61 53° 52' 64" 10"	95#	9:25 10:05 10:35	35 60	12 1/2	115#	2.1
(1) C-1	5	7-12-61 53° 52' 64" 10"	95#	1:00 1:30 2:00	25 55	11 1/2	115#	2.1
(2) A-1 (3) A-2	5	7-12-61 53° 52' 64" 10"	95#	8:00 8:40 9:05	40 65	12 1/2	115#	2.1

THIS IS TO CERTIFY THAT THE WORKMANSHIP, LUMBER AND GLUE IN THE BUILT-UP MEMBERS AS COVERED BY THIS REPORT WERE CONTINUOUSLY INSPECTED BY THE INSPECTOR AND FOUND TO BE IN ACCORDANCE WITH THE SPECIFICATIONS AND CODES.

per Timber Structures, Inc. 311-661787. See also specifications for Structural Glued Laminated Lumber 19600

UNIFORM BUILDING CODE

COUNTERSIGNED
THIS CERTIFICATE REFERS ONLY TO THE FORM & CONDITION OF THE MATERIALS INSPECTED AND DOES NOT COVER THE DESIGN OR THE LOADS OR THE STRUCTURE TO WHICH IT IS APPLIED. IT IS NOT VALID UNLESS COUNTERSIGNED BY AN AUTHORIZED OFFICIAL OF THE BUILDING DEPARTMENT.

INSPECTOR

DATE 5-24-62 OUR SEWER NO. 8426-L

BUILDING PERMIT NO. 16731

OWNER'S NAME Church of Christ

JOB ADDRESS 9822 Russell

LOT NO. _____

DATE SEWER APPROVED 5-28-62

GARDEN GROVE SANITARY DISTRICT

By P. C. [Signature]

APPLICATION FOR A BUILDING PERMIT

DEPARTMENT OF BUILDING, GARDEN GROVE, CALIF.

CONTRACT INFORMATION PROVIDED BY BLDG. DEPT.

EXTERIOR WALL MATERIAL WOOD	ROOF FRAMING MATERIAL WOOD
PARTITIONING MATERIAL WOOD	ROOF COVERING MATERIAL COMPO
LOT WIDTH 226'	LOT DEPTH 335'
NO. OF EXISTING BLDGS ON LOT 3	
USE ZONE R-1	PARE ZONE 3
REG. SET BACKS 1-1	DEPT. PANCE 63'6"
TYPE II	REAR -
USE PLAN NO	USE PERMIT OR VARIATION NO
PARK SPACES -	

Zoning Approved By *Sam* Date **6-8-65**

Remarks: **PLANS**

PUBLIC WORKS

Street Address **CR** By *J. L.*

Record of Survey

R. V. Dedication

Bonds

Encroachment Permit

Remarks

INSPECTION RECORD

APPROVAL	DATE	INSPECTOR
Foundation and Location	9-1-65	<i>John</i>
Reinforcing	9-2-65	<i>John</i>
Roof Shgt.	11-17-65	<i>John</i>
Rough Frame	12-10-65	<i>John</i>
Lath or Drywall	2-2-66	<i>John</i>
Fins Brown Ct.		
Other		
Land Use		
Final	2-16-66	<i>John</i>
Utility Release	2-17-66	<i>John</i>

VALUATION NOTE **\$127,000**

\$10.65 FEES

Plan Check **\$82.75** Building Permit **\$16.50**
Bond **\$** Inspection **\$**

Permit Authorized By *John* Date **8-23-65**

INSTRUCTION: USE TYPEWRITER OR BALL POINT PEN. PRESS FIRMLY. BE SURE ALL COPIES ARE LEGIBLE. NO ERASURES PERMITTED. A DOUBLE FEE WILL BE CHARGED IF WORK IS STARTED BEFORE PERMIT IS ISSUED.

Job Address **9822 RUSSEL ST.** Permit No. **011351A**

Lot No. **1539** Tract No. **1539** Bk No. **PC-1250**

CONTRACTOR **A. L. MAHONEY** STATE LIC. NO. **178001**
MAILING ADDRESS **1153 ST. NORTH ANAHEIM** TEL. NO. **571-7993**
KARL JAMES R. WILDE STATE LIC. NO. **1899**
MAILING ADDRESS **12522 BROOKHURST** TEL. NO. **539-8973**
OWNER **CHURCH OF CHRIST** TEL. NO. **9822 RUSSEL ST.**

NEW ☐ ADD'N ☒ ALTER ☒ REPAIR ☐ DEMOLISH ☐

FLOOR AREA **5162** NO. OF STORIES **2** NO. OF DWELLING UNITS **2**
PROPOSED BLDG. USE **AUG 23 1965** ***165.50

Validation **ADD. MAY 20 1965 TO 11 083 M ***82.75**
DESCRIBE WORK TO BE DONE **SOCIAL HALL PLUS INTERIOR ALTERATION TO EXISTING CLASSROOMS**

OWNER-BUILDER PERMIT RESTRICTIONS. An owner-builder must reside within the building for which this permit is issued. (Accessory buildings excepted). Said building may not contain more than 3 dwelling units. Otherwise, this permit may be issued only to a contractor licensed in the State of California and a business license must be procured from the City of Garden Grove.

WORKMEN'S COMPENSATION INSURANCE REQUIREMENTS: A certificate or duplicate thereof of workmen's compensation insurance must be on file with the City of Garden Grove prior to the issuance of this permit unless: 1. This permit is for less than \$100 valuation or 2. The applicant qualifies as an owner-builder and signs the statement below.

I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the workmen's compensation laws of California.

SIGNATURE *A. L. Mahoney*

DATE ON FILE

APPROVAL CERTIFICATION: I have read and examined the above application and find the same to be true and correct. All provisions of the laws and ordinances of the City of Garden Grove and State of California will be complied with whether speaking here or not.

Signature of Permittee **Date**

Address **RELOCATION**

PREPARED BY **ADDRESS**
ALLIANCE
MOVING CONTRACTOR

7-7-65

Footings on w end of Exst. Bldg & 2'4" footing inside
OK to Pour A.D.

11-30-65

OK to wrap exterior of new building A.D.

12-6-65

OK to cover arcade sheathing OK. A.D.

PLOT PLAN

Department of Building

CITY OF
GARDEN GROVE

Job Address

9822 RUSSELL STREET

Permit Number

11351

Lot

Tract

Blk.

1539

DIMENSION PLOT PLAN COMPLETELY SHOWING
ALL BLDGS. ON THE LOT AND THEIR USE



RUSSELL STREET

16274 STREET

16274

EXIST SANCTUARY
FIXED SEATING 312

EXISTING
CLASS ROOM

EXISTING CL. RM.

15 CARS

PARKING

15 CARS

15 CARS

15 CARS

NEW ADDITION
2 STORY
2546 EACH FLOOR

20 CARS

33 CARS

I certify the information hereon is complete and correct.
Routing: 1 Building Inspector 2 Office File 3 Owner

By

Date

RUSSELL

009822

4

STREET

NAME

ADDRESS

APT. NO.

CARD NO.

ELECTRICAL PERMIT

DEPARTMENT OF INDUSTRIAL AND LABOR

Identify man's E. Battery switch
also see Panel Breakers

3-7-66

~~Strom~~

Identify man's E. Battery switch
also see Panel Breakers
9-1-6

PLUMBING PERMIT

Department of Building

CITY OF
GARDEN GROVE

PERMIT FEES

NO.	TYPE OF FIXTURE OR ITEM	EACH	\$ FEE
3	Water Closet (Toilet)	\$1.50	4 50
	Bath Tub	1.50	
	Shower	1.50	
1	Lavatory (Wash Basin)	1.50	3 00
2	Kitchen Sink	1.50	3 00
2	Garbage Disposal	1.50	3 00
1	Laundry Tub or Tray	1.50	
1	Water Heater	1.50	1 50
1	Slop Sink	1.50	1 50
	Floor Sink	1.50	
	Floor Drain	1.50	
	Dish Washer	1.50	
2	Drinking Fountain	1.50	3 00
1	Urinal	1.50	1 50
1	Gas System — Outlets	1.50	1 50
	House Sewer	1.50	
	Lawn Sprinklers (Single Dwelling Only)	2.00	
	Swimming Pool Piping	1.50	
	Sand Traps	1.50	
	Automatic Washing Mach.	1.50	
	Water Softeners	1.50	
	Backwash — Trap	1.50	
	Water Lateral	1.50	
	Backflow Protective Devices	2.00	

Issuance of Permit 2 00

TOTAL FEE \$ 21 50

Permit Authorized By

Date

ROUTING: 1 Plumbing Inspector 2 Statistics 3 Owner 4 Office File

For Applicant to Fill In (Use ink)

Job

Address 9822 Russell

Permit No.

011503

Lot No.

Tract No.

Blk. No.

Owner

Church of Christ

Owner's Address

9822 Russell

Plumbing Contractor

W. L. Bonnis

Contractor's Address

549 So. Anaheim Blvd.

Phone 535-4840

City Lic. No.

Use of Bldg.

Church

New Bldg. ☒

Old Bldg. ☐

Validation

011503-65

TT 032 M 24.50

I hereby acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and State laws regulating plumbing.

I hereby certify that I am properly registered with and/or licensed as required by the City of Garden Grove and/or State of California, or that I am the legal owner of the above described property, and I certify that in the performance of the work for which this permit is issued I shall not employ any person in violation of the workmen's compensation laws of the State of California.

Signature of Permittee

W. L. Bonnis

Date 8-30-65

Address

APPROVALS

DATE

INSPECTOR

SOIL PIPING

GROUND PLUMBING

ROUGH PLUMBING

12-9-65 R 770

GAS PIPING

GAS VENT

SEPTIC TANK or Cesspool

SEWER

GAS TEST

MAIN DRAIN AND VACUUM LINES

WATER HEATER

BACKWASH

WATER LATERAL

FINAL

UTILITY CO. NOTIFIED

8-17-66 CR

Bldg. Permit 1195

HEATING, VENTILATING, REFRIGERATION & AIR-CONDITIONING PERMIT

1

DEPARTMENT OF BUILDING
HARRY R. PEIRCE, DIRECTOR
537-4200

CITY OF
GARDEN GROVE

FOR APPLICANT TO FILL IN (USE INK)

JOB ADDRESS

PERMIT NO.

9822 Russell St. 012685 A

PERMIT FEES

NUMBER	TYPE OF FIXTURE OR ITEM	EACH	FEE
	FURNACE — RESIDENTIAL	1.00	
	WARM AIR OUTLET	.25	
	FURNACE VENTS	1.00	
	GAS PIPING — OUTLETS	1.00	
3	COMMERCIAL HEATING	2.00	6.00
12	COMMERCIAL WARM AIR OUTLETS	.50	6.00
5	COMMERCIAL FURNACE VENTS	2.00	6.00
	EXHAUST OUTLETS	1.00	
	REPAIR, ALTERATION OR ADDITION TO HEATING SYSTEM	1.00	
	VENTILATION SYSTEM	3.00	
	RESTAURANT KITCHEN HOOD	3.00	
	CONDENSING UNIT 20 H.P. OR LESS	2.00	
	CONDENSING UNIT TO 50 H.P.	5.00	
	CONDENSING UNIT OVER 50 H.P.	10.00	
	REPAIR OR ALTERATION TO REFRIGERATION SYSTEM	3.00	
	EVAPORATIVE COOLERS	1.00	

LOT NO.

TRACT NO.

OWNER

OWNER'S ADDRESS

CONTRACTOR

CONTRACTOR'S ADDRESS

PHONE

CITY LIC NO.

USE OF BUILDING

NEW BUILDING

OLD BUILDING

VALIDATION

OCT 29-65 11 229 M ****19.00

I hereby acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and State laws regulating plumbing. I hereby certify that I am properly registered with and/or licensed as required by the City of Garden Grove and/or State of California, or that I am the legal owner of the above described property, and I certify that in the performance of the work for which this permit is issued I shall not employ any person in violation of the workmen's compensation laws of the State of California.

SIGNATURE OF PERMITTEE

DATE

ADDRESS

APPROVAL

DATE

INSPECTOR

FURNACE

REGISTER OUTLETS

FURNACE VENTS

GAS PIPING

DUCTS

EXHAUST OUTLETS

RESTAURANT KITCHEN HOOD

VENTILATION SYSTEM

CONDENSING UNIT 20 H.P. OR LESS

CONDENSING UNIT 50 H.P.

CONDENSING UNIT OVER 50 H.P.

ISSUANCE OF PERMIT

1.00

TOTAL FEE

\$ 12.00

PERMIT AUTHORIZED BY

DATE

ROUTING

BUILDING PERMITTING

FINAL

#1 INSPECTOR

#2000-05-01

#3000-05-01

TOTAL FEE \$12.00

HEATING, VENTILATING, REFRIGERATION & AIR CONDITIONING PERMIT

DEPARTMENT OF BUILDING
HARRY R. REIRCE - DIRECTOR
237-4200

CITY OF
GARDEN GROVE

FOR APPLICANT TO FILL IN (USE INK)

013482

PERMIT NO.

PERMIT FEES

NUMBER	TYPE OF FIXTURE OR ITEM	EACH	FEE
	FURNACE—RESIDENTIAL	\$1.00	
	WARM AIR OUTLET	25	
	FURNACE VENTS	1.00	
	GAS PIPING—OUTLETS	1.00	
	COMMERCIAL HEATING	2.00	
	COMMERCIAL WARM AIR OUTLETS	.50	
	COMMERCIAL FURNACE VENTS	2.00	
	EXHAUST OUTLETS	1.00	
	REPAIR, ALTERATION OR ADDITION TO HEATING SYSTEM	RES. OR COMM. 1.00	
	VENTILATION SYSTEM	3.00	
1	RESTAURANT KITCHEN HOOD	3.00	3.00
	CONDENSING UNIT 20 H.P. OR LESS	2.00	
	CONDENSING UNIT TO 50 H.P.	5.00	
	CONDENSING UNIT OVER 50 H.P.	10.00	
	REPAIR OR ALTERATION TO REFRIGERATION SYSTEM	3.00	
	EVAPORATIVE COOLERS	1.00	
	ISSUANCE OF PERMIT		1.00

TOTAL FEE

\$ 4.00

PERMIT AUTHORIZED BY

DATE

12-21-65

ROUTING:

BUILDING PERMIT NO.

#1 INSPECTOR #2 OFFICE FILE #3 OWNER

JOB ADDRESS

9822 Russell

LOT NO.

TRACT NO.

OWNER

Church of Christ

OWNER'S ADDRESS

9822 Russell St.

CONTRACTOR

Kenney Heating

CONTRACTOR'S ADDRESS

1441 S. Anaheim, Anaheim

PHONE

774-8120

CITY

LIC. NO.

963

USE OF BUILDING

NEW BUILDING

☒

OLD BUILDING

☐

VALIDATION

DEC 21-65 11 033 M *****4.00

I hereby acknowledge that I have read this application and state that the above is correct and agree to comply with all ordinances and State laws regulating plumbing. I hereby certify that I am properly registered with and/or licensed as required by the City of Garden Grove and/or State of California, or that I am the legal owner of the above described property, and I certify that in the performance of the work for which this permit is issued I shall not employ any person in violation of the workmen's compensation laws of the State of California.

SIGNATURE OF PERMITTEE

Bill Kenney

DATE

ADDRESS

APPROVALS

DATE

INSPECTOR

FURNACE

REGISTER OUTLETS

FURNACE VENTS

GAS PIPING

DUCTS

EXHAUST OUTLETS

RESTAURANT KITCHEN HOOD

VENTILATION SYSTEM

CONDENSING UNIT 20 H.P. OR LESS

CONDENSING UNIT 50 H.P.

CONDENSING UNIT OVER 50 H.P.

FINAL


UTILITY CO. NOTIFIED

APPEND A DRAWING #1

CHURCH OF CHRIST - GARDEN GROVE, CALIF.

JAMES H. VANCE, JR. ARCHITECT & ENGINEER
22002 E. 11th Ave., Suite 200, Garden Grove, CA 92647

8/20/65



TYPICAL 2 STORY EXT. WALL FOOTING

SCALE: 1" = 1'-0"

NOTE: CONSTRUCTION JOINT PERMITTED @ BOTTOM OF FIRST STORY PROVIDED A.B. ARE EXTENDED TO 12" LONG W/ MIN 6" EMBEDMENT INTO FOOTING STEEL WALL. WHERE VERTICAL CONSTRUCTION JOINTS ARE REQUIRED @ EXISTING FOUNDATIONS @ INTERSECTION OF EXISTING BUILDING PROVIDED A MIN. 18" JAP UP T.O.B. BASE STL IN EXISTING FOOTING & BASE STEEL IN SPREAD FOOTING.

PLOT PLAN

Department of Building

CITY OF
GARDEN GROVE

Job Address

9822 1/2 Russell

Permit Number


255579

Lot

Tract

Blk.
No.

DIMENSION PLOT PLAN COMPLETELY SHOWING
ALL BLDGS. ON THE LOT AND THEIR USE



I certify the information hereon is complete and correct.
Routing: #1 Building Inspector #2 Office File #3 Owner

By

Date

DATE 3-10-66 OUR SEWER NO. 326

BUILDING PERMIT NO. 11351

OWNER'S NAME L. G. Church of Christ

JOB ADDRESS 9822 Russell St.

LOT NO. Addition

DATE SEWER APPROVED 3-10-66

GARDEN GROVE SANITARY DISTRICT

By R. C. Scott

Garden Grove Church of Christ

RICHARD L. MILLER, MINISTER
 RICHARD L. MILLER, MINISTER
 GARY DAVIS, YOUTH MINISTER
 GARY K. DAVIS, YOUTH MINISTER
 FRANK R. SCOTT, SECRETARY
 FRANK R. SCOTT, SECRETARY

2222 RUSSELL STREET
 2222 RUSSELL STREET

(CHRISTIAN CHURCH)

GARDEN GROVE, CALIFORNIA 92622-242

P. O. BOX 10785

TELEPHONE 537-4190
 TELEPHONE 537-8190

98222 Russell St

December 12, 1965

Mr. Harry Peirce, Building Department
 City of Garden Grove,
 11301 Acacia Street,
 Garden Grove, California

Dear Mr. Peirce:


I am writing to clarify to your department the use we plan to make of the kitchen facility which is now under construction on our church property. In our initial planning we had considered the use of heavier equipment than we are now proposing. The reason for the change is simply that it is against our church policy to prepare dinners or banquets for the purpose of raising money, either for the church or any organization of the church. Furthermore, we do not loan or lease our facilities to any other group or organization. It was therefore concluded that a commercial type of kitchen installation would be an extreme waste of funds.

We plan to use this new facility for "fellowship" type dinners, for Sunday School class groups, Women's Council, or Men's Meetings. The usual arrangement for groups such as these is a "pot-luck dinner." In this case the main food dishes are prepared in the homes and brought to the church. Actually, our need is for counter top burners for heating vegetables, and ovens for the purpose of keeping casserole dishes warm. It is for this reason we are planning to go to a simpler installation.

Because of the small amount of use our kitchen will be getting, compared to what it was originally designed for, there will be no dishwasher installation and there will be no freezer unit. The stoves have been changed from counter top burners and wall ovens to simple domestic free-standing range and oven units. We feel therefore that a domestic hood fan over the units will be sufficient. We sincerely appreciate your consideration of this matter.

Should you wish further clarification of this matter I will be most happy to write again or converse with you.

Very sincerely,



Richard L. Miller, Minister

May 28, 1965

Church of Christ
9822 Innesell
Garden Grove, California

Gentlemen:

Before this department can complete a plan check of your proposed new addition, we will require one additional copy of the plot plan.

Very truly yours,

Stewart O. Miller
Zoning Technician

or

General Information:
658-0601

For Applicant to Fill in

[illegible]

CITY OF GARDEN GROVE


PLOT PLAN

PUBLIC WORKS & DEVELOPMENT

OWNER GARDEN GROVE CHRISTIAN CHURCH	JOB ADDRESS 9822 RUSSELL ST.	PERMIT NO. 118102A
NAME OF CONSTRUCTION LENDER & BRANCH	ASSESSORS PARCEL NO. 98-081-19	LOT BLOCK TRACT
	PLEASE CHECK ONE OR MORE ☐ New ☒ Addition ☐ Alteration ☐ Repair ☐ Move ☐ Demolish	
ADDRESS	DATE 12-3-80	JOB DESCRIPTION PARTITION WALLS IN PANTRY
CITY		PERMIT VALUE 190.00

SHOW NORTH ARROW AND PROPERTY LINES AND ADJACENT STREETS.
SHOW NORTH ARROW AND PROPERTY LINES AND ADJACENT STREETS.**1992 F.F.
190 FT. HIGH**

RUSSELL

*1 Building Dept. *2 Assessor's Office *3 Permit Office *4 File
I certify the information herein is complete and correct. By _____

PLOT PLAN APPROVED BY _____

6-5-80 7/78

RE-LOCATED

ADDITIONAL
PANTRY

PANTRY

KITCHEN

NEW 1/2" GAS OUTLET

FELLOWSHIP HALL

City of Garden Grove, Department of Public Works & Development
APPROVED

This set of plans & specifications must be kept on the job at all times and it is unlawful to make any changes or alterations on same without written permission from the Department of Public Works & Development, City of Garden Grove, County of Orange. The stamping of this plan & specifications SHALL NOT be held to permit or to be an approval of the violation of any provisions of ANY City Ordinance or State Law. Inspections by officers and employees of the City of Garden Grove are made to determine that the MINIMUM standards required by the Garden Grove Municipal Code are satisfied. The City of Garden Grove does not guarantee construction to specifications contained in this plan which are greater than the minimum standards required by the Garden Grove Municipal Code.

APPROVED BY RAYMOND T. HOLLAND, BUILDING OFFICIAL

DATE 12-3-80 BY [Signature]

FLOOR PLAN: FELLOWSHIP HALL

SCALE 1/8" = 1'-0"

GARDEN GROVE CHRISTIAN CHURCH - 1822 RUSSELL ST GARDEN GROVE, CA. 92644

INSTALL NEW GAS OUTLET FOR ADDITIONAL FOOD WARMER
EXTEND EXISTING PANTRY AND RELOCATE DOOR
REMOVE TWO EXISTING RANGES AND INSTALL COMMERCIAL RANGE
RELOCATE EXISTING RECEPTICAL

BUILDING PEERNTT

**Inspection Requests
741-5332**

General Information
741-5307

For Applicant to Fill in

INSPECTION RECORD

PG #		OCC LOAD		FIRE SPRINK		
OCCUPANCY		TYPE	FRONT	LEFT	RIGHT	REAR
USE ZONE		Eav. Proj.				
		Soffbacks				
PLANNING ACTION					PLANS	
					DATE	
LAND USE APPROVED BY						
REMARKS						
G.G.SANT DIS FEE REQ'D		O.C.SANT DIS FEE REQ'D		DATE		PAYAL
				REQ'D		PROVIDED
PARCEL MAP						
R/W DEDICATION						
FEES AND BONDS						
			REV. CODE	AMOUNT		
ST. BOND						
WATER BOND						
WATER ASSMT FEE (ACRG)						
WATER ASSMT FEE (FT)						
PARKWAY TREE FEE						
PARK & REG. FEE (DIST)						
PARK & REG. FEE (DIST)						
DRAIN ASSMT FEE (DIST)						
PLAN RETENTION FEE						
BLDG PLAN CHECK					15	00
BLDG PERMIT FEE					63	50
ISSUANCE					10	00
VALUATION						
TOTAL FEES					88	50
DATE						
AUTHORIZED BY						

APPROVAL	DATE	INSPECTOR
E INSPECTION	11 / 89	[Signature]
FOUNDATION & LOCATION		
CONCRETE FLOOR		
REINFORCING		
MASONRY		
ROOF SHEET		
ROUGH FRAME		
INSULATION, ENERGY		
BRYWALL		
PAINT		
PLAS. BROWN CT		
LANDSCAPING		
PREFAB GUNIT		
PREFAB DECK		
PREFAB PLASTER		
PLANING		
FINAL	10.6.89	[Signature]

WORKER'S COMPENSATION REQUIREMENTS

BUSINESS TAX CERTIFICATE INFORMATION I certify that the following Contractor's License No. <u>6624</u> and Classification <u>31</u> is in full force and effect. <u>NO CHANGE</u> <u>1/16/31</u> (PRINT, CONTRACTOR) DATE		SIGNATURE CONTRACTOR OR AUTHORIZED AGENT
ONE YEAR EXPIRATION DATE I certify that I am exempt from Section 7041B of the Business and Professions Code because I am a <u>Chartered</u> member of the following fraternal organization: <u>Knights of Pythias</u> My work would be under Section 7041B of the Business and Professions Code.		EXPIRATION DATE
OTHER (PRINT, PROPERTY OWNER)		SIGNATURE PROPERTY OWNER OR AUTHORIZED AGENT

ADDRESS 9822 Russell		PERMIT NO. 167239A 167239A	
LOT NO. BLK NO. TRACT NO.		CITY	
OWNER Christian Church		CITY	
MAILING ADDRESS Same		CITY	
☐ ARCH ☐ ENGR.		CITY	
TEL. NO.		STATE LIC. NO. & TYPE	
VALIDATION INSPECT 15.00 B-PER 63.50 ISS 10.00			
CONTRACTOR ROYL C. HARTLEY ROOFING		CHECKED 10.50	
MAILING ADDRESS		CITY	
10462 - E TASK BLK 90643		CITY	
TEL. NO. 636-1747		STATE LIC. NO. & TYPE 5.56621	
PRESENT BLDG. USE Church		PROPOSED BLDG. USE	
DESCRIBE WORK TO BE DONE Removal of existing roof with Comp Shingles			
☐ NEW ☐ ADD N ☐ ALTER ☐ REPAIR ☐ DEMOLISH ☐ ☐ FLOOR AREA ☐ NO OF STORIES ☐ NO OF SWELLING ☐ FLOOR AREA ☐ NO OF STORIES ☐ NO OF SWELLING ☐ FLOOR AREA ☐ NO OF STORIES ☐ NO OF SWELLING			
If work is not started within 180 days from date of issue or if abandoned If work is not started within 180 days from date of issue or if abandoned If work is not started within 180 days from date of issue or if abandoned A FEE MAY BE CHARGED FOR REINSPECTION DUE TO REINVESTMENT IN COMPLETE WORK OR FAILURE TO MAKE CORRECTIONS.			
RELOCATION RELOCATION			
CONTRACTOR ADDRESS CITY STATE ZIP			

1. INSPECTOR

RUSSELL		009822		5	
STREET NAME		ADDRESS		APT. NO.	
				CARD NO.	

FEES	
Plan Check \$	Building Permil \$23.00
Permit Authorized By	Date
1 ORIGINAL	3/1/77

ELECTRICAL PERMIT

Public Works & Development — Garden Grove, Ca.
 Inspection 638-6771 Information 638-6661

LOT NO.	TRACT NO.	NUMBER	EACH	FEE
IF NOT LISTED BELOW SEE CODE				
Residential (1 & 2) sq. ft.			.015	
Garage, Resid. (1) sq. ft.			.01	
Service Meter, Single Phase			5.00	
Service Meter, Three Phase			5.00	
Temporary Power Pole			3.00	9.00
Pole, Power, Light, etc.	3		2.00	
Sub-Panels 1 ϕ			2.00	
Sub-Panels 3 ϕ			.20	
Outlets			.20	
Fixtures			1.00	
Fixtures, Merc. Quartz, etc.			2.00	
Heater—Not Over 1650 W			2.00	
Water Heaters			2.00	
Range or Oven			2.00	
Domestic Range or Oven				
Power Apparatus—H.P., K.W. or				
K.V.A. Motors, Transformers, etc.				
K.V.A. Motors, Transformers, etc.			1.50	
Not Over 1 each			3.00	
Over 1, Not Over 30 each			5.00	
Over 30, Not Over 60 each				
Time Clock			1.00	
Sign			.50	
Sign Hookup			2.00	

REC'D BY.	PLAN CHECKS \$	
AUTHORIZED BY ERB	PERMIT \$	9.00
DATE 2-19-76	ISSUANCE \$	5.00
	TOTAL \$	14.00

INSTRUCTION: USE TYPEWRITER OR BALL POINT PEN, PRESS FIRMLY. BE SURE ALL COPIES ARE SIBLE, NO ERASURES PERMITTED. A DOUBLE FEE WILL CHARGED IF WORK IS STARTED BEFORE PERMIT IS ISSUED. (PLEASE PRINT)

ADDRESS 9822 RUSSELL		ELECTRIC PERMIT NO. 082979 A	
OWNER CHURCH OF CHRIST		PHONE	
OWNER'S ADDRESS SAME		CITY	
NEW BUILDING OR ADDITION - AREA SQ. FT.	EXISTING BUILDING REMODEL AREA SQ. FT.	OCCUPANCY GROUP B-2	USE OF BUILDING AND OR NUMBER OF UNITS CHURCH
ELECTRICAL CONTRACTOR OWNER		PHONE	
ADDRESS		CITY	
		STATE LIC. NO.	

VALIDATION
 FEB 19-76 11 011 M***W14.00

I HAVE CAREFULLY READ THE ABOVE APPLICATION AND KNOW THE SAME TO BE TRUE AND CORRECT. ALL PROVISIONS OF STATE AND LOCAL LAWS COVERING THIS TYPE OF CONSTRUCTION WILL BE COMPLIED WITH WHETHER SPECIFIED HEREIN OR NOT. NO PERSON SHALL BE EMPLOYED IN VIOLATION OF THE LABOR CODE OF THE STATE OF CALIFORNIA.
 SIGNATURE OF PERMITTEE **Queen Williams** DATE **2-19-76**

BRANCH CIRCUIT PANEL CIRCUITRY

CIR. NO.	BRKR. SIZE	WIRE SIZE	NOMENCLATURE	NO. OF OUTLET	WATTS L1	WATTS L2	WATTS L3
1							
2							
3							
4							
5							
6							

INSPECTION RECORD

APPROVAL	DATE	INSPECTOR
Underground		
Conduit		
Wiring		
Heater		
Fixtures		
Ufer		
Serviced		
FINAL	5-3-76	
Utility Notified		
BUILDING PERMIT NO.	SIGN PERMIT NO.	VENT, HEAT, HR COND. PERMIT NO.

1 INSPECTED

05-0010-0

**CITY OF GARDEN GROVE
Public Works & Development**

ELECTRICAL PERMIT

Inspection Requests
638-6771

General Information
638-6661

INSPECTION RECORD

FEES

For Applicant to Fill in

AMPS	VOLT	WATT	IF NOT LISTED BELOW SEE CODE	NO.	EA	FEE
			Residential (1 & 2 R-3) sq. ft.			
			Garage Resort (1 & 2 R-3) sq. ft.			
			Service Meter, Single Phase			
			Service Meter, Three Phase			
			4 in. Meter Three Phase			
			Temporary Power Pole			
			Pole, Power, Light etc.			
			Sub-Panels 1			
			Sub-Panels 2			
			Heater - Not Over 1000W			
			Washer			
			Dryer			
			Hot Water Heaters			
			Disposal			
			Domestic Range or Oven			
			Power Apparatus - 1000 W. or less			
			Over 1000 W. or 10 each			
			Over 10 W. or 30 each			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
			Timing Clock			
			Sign			
			Sign Hookup			
	</					

CITY OF GARDEN GROVE
Public Works & Development

ELECTRICAL PERMIT

Inspection Requests
638-6771

General Information
638-6661

INSPECTION RECORD

FEES

For Applicant to Fill in

SINGLE PHASE SERVICE SIZE ☐ 3 WIRE ☐ 4 WIRE ☐ 5 WIRE			THREE PHASE SERVICE SIZE ☐ 3 WIRE ☐ 4 WIRE ☐ 5 WIRE		
AMPS	VOLTS	RIG. CONDUIT	AMPS	VOLTS	RIG. CONDUIT
APPROVAL	DATE	INSPECTOR			
Underground					
Conduit					
Wiring - Rough					
Heater					
Fixtures & Trim					
Motors					
Uter					
Service					
FINAL					
Utility Notified					

IF NOT LISTED BELOW SEE CODE	NO.	EA.	FEE
Residential (R-1 & R-2) sq. ft.			
Garage, Resid. (M) sq. ft.			
Service Meter, Single Phase			
Service Meter, Three Phase			
Add'l Meter, Three Phase			
Temporary Power Pole			
Pole, Power, Light, etc.			
Sub-Panels 1 ϕ			
Sub-Panels 2 ϕ			
Outlets	3		7.00
Fixtures			
Fixtures, Merc. Quartz, etc.			
Power Apparatus - H.P., K.W. or K.V.A. Motors, Transformers, etc.			
Not Over 1 each			
Over 1, Not Over 10 each			
Over 10, Not Over 30 each			
In-lv. Circuits			
Time Clock			
Sign			
Sign Holder			
MANUEL FULL ALLEN SYSTEM	1		
2 PULLS 1-BELL			
CONTROL BOX			

ITEM	CODE	FEES
Plan Retention Fee		
Plan Check		
Permit		
Issuance		
TOTAL FEES		10.00

LAND USE: _____ AUTHORIZED BY: H. E. Culver BUILDING DATE: 8-5-81

ADDRESS
9822 RUSSELL ST.

LOT NO. BLK NO. TRACT NO.
ELECTRIC PERMIT NO. **1210000**

OWNER
GARDEN GROVE CHRISTIAN CHURCH
OWNER'S ADDRESS: 9822 RUSSELL ST.
CITY: _____ PHONE: 557-4190

NEW BUILDING OR ADDITION - AREA
SQ. FT. **2000**

EXISTING BUILDING REMODEL AREA
SQ. FT. **E-1**

OCCUPANCY
USE OF BUILDING AND OR NUMBER OF UNITS

VALIDATION
08/05/81
ELT PER
ISSUANCE
CHECK

ELECTRICAL CONTRACTOR
OWNER/BUILDER
CITY: _____ PHONE: _____

WORKER'S COMPENSATION REQUIREMENTS
State Compensation Insurance Policy No. _____ Expiration Date: _____
I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the Worker's Compensation Law unless he or she becomes a member of the State Compensation Fund.
NOTE: If, after making such certification, the applicant for the permit should become subject to the Worker's Compensation Law, he or she shall be liable for the cost of the premium for the period of the permit.
I certify that I have read this notice and state that the above information is correct. I agree to comply with the City of Garden Grove and State laws relating to Worker's Compensation. I agree to indemnify and hold the City of Garden Grove harmless from any and all claims, damages, costs or expenses, including attorney's fees, which may be incurred by the City of Garden Grove as a result of any injury or property damage resulting from work performed pursuant to this permit.

BUSINESS TAX CERTIFICATE INFORMATION
I certify that the information provided is true and correct and is in full force and effect.
(PRINT) CONTRACTOR: _____ (SIGNATURE) CONTRACTOR: _____ DATE: 8-4-81
(PRINT) PROPERTY OWNER: _____ (SIGNATURE) PROPERTY OWNER: _____ DATE: 8-4-81

BUSINESS TAX CERTIFICATE NO. _____ **EXPIRATION DATE** _____
I certify that I am exempt from Section 7031.5 of the Business and Professions Code, Division 3, Chapter 9, Contractors' License Law, under the following Section:
Owner: Section 7044 [X] Minor work under \$100. Section 7048 []
Employee working for wages only: Section 7053 []
Other: _____

GARDEN GROVE CHRISTIAN CHURCH
(PRINT) PROPERTY OWNER: _____ (SIGNATURE) PROPERTY OWNER: _____ DATE: 8-4-81
(PRINT) CONTRACTOR: _____ (SIGNATURE) CONTRACTOR: _____ DATE: 8-4-81

A FEE MAY BE CHARGED FOR RE-INSPECTION DUE TO NEGLIGENCE, INCOMPLETE WORK, OR FAILURE TO MAKE CORRECTIONS.

1. INSPECTOR

PLANNING **PROFIT**

General Information
630.6663

FEEES

M 14

For Applicant to Fill in

[illegible]

PLUMBING **PERMITTING**

General Information
628,566

FEEES

For Applicant to Fill in

ADDRESS <div style="font-size: 2em; font-weight: bold; text-align: center;">7822 RUSSELL ST.</div>			
LOT/BLK. NO. 1101044		PERMIT NO.	
OWNER GARDEN GROVE CHRISTIAN		PHONE	
OWNER'S ADDRESS 9822 RUSSELL		CITY GARDEN GROVE	
NAME OF CONTRACTOR JACOBS PLUMBING	CONTRACTOR'S ADDRESS 11307 JANE WAY	CITY STANTON	PHONE 534-1271
WORKER'S COMPENSATION REQUIREMENTS			
State Compensation Insurance Policy No. _____ Expiration Date _____			
☒ I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the Worker's Compensation laws of California.			
NOTE: If, after making such certification, the applicant for the permit should become subject to the Worker's Compensation provisions of this code, he shall forthwith comply with the provisions of Section 3700 or his permit shall be deemed revoked.			
☐ I certify that I have read this application and state that the above information is correct. I agree to comply with all City Ordinances and State laws relating to bonding construction. I further agree to hold the City of Garden Grove free and harmless from any liability arising out of injury or bodily damage resulting from work performed pursuant to this permit.			
Signature of Contractor <i>Michael M. Jones</i>		Date 12-3-90	
BUSINESS TAX CERTIFICATE INFORMATION			
I certify that the following is a contractor's License No. _____ and Classification _____ as in full force and effect.			
Licensee's Name MICHAEL M. JONES		Date 12-3-90	
(Licensee) CONTRACTOR		(Contractor) AGENT	
BUSINESS TAX CERTIFICATE NO.			
I certify that I am exempt from Section 7091.5 of my Business and Professional Code, Division 3, Chapter 9, Contractors' License Law, under the following section:			
Owner: Section 7094.1		Minor work under \$100: Section 7095	
Employee working for wage only: Section 7093		☐	
Other: <u>LABORER MATERIAL DONATED</u>			
(Licensee) CONTRACTOR		(Contractor) AGENT	
A FINE MAY BE CHARGED FOR THE INFRACTION OF NON-EXISTENCE, INCOMPLETE WORK, OR FAILURE TO MAKE CORRECTIONS.			

INSPECTOR'S NOTES

3.9.81

Phonetic 4, 1, 4, 4, 4 (44)

No Parents For

Still

No Hens/Km-

Water Softener-

Seal about Seal

Seal

1181047

HEATING, VENTILATING, REFRIGERATION & AIRCOND. PERMIT

Inspection Requests
638-6671

General Information
638-6661

INSPECTION RECORD

FEES

For Applicant to Fill In

APPROVALS	DATE	INSPECTOR	TYPE OF FIXTURE OR ITEM	NO.	EA.	\$ FEE
FURNACE			Furnace to & incl. 100M B.T.U.			
FURNACE VENTS			More than 100M & incl. 500M B.T.U.			
			More than 500M & incl. 1MM B.T.U.			
GAS PIPING			Installation or Relocation of Susp. Heater			
			Installation or Relocation of Wall Heater			
			Installation or Relocation of Unit Heater			
DUCTS			Installation of Appliance Vent Only			
SINGLE DUCT			Repair, Alteration or Addition to any			
SINGLE DUCT			Heating or Cooling System			
FAN VENT			Installation of Fan			
KITCHEN HOOD	2-3-81	MA	Each Range Hood Incl. Duct and Fan	1		5.00
KITCHEN HOOD			Each Vent Fan Connected to a Single Duct			
AIR HANDLING			Each Ventilating System not a Part of a			
AIR HANDLING			Heating or Air Conditioning System			
UNIT			Authorized by Permit			
EVAPORATIVE			Motor or Compressor to & incl. 5 Hp.			
EVAPORATIVE			Absorption System to & incl. 100M B.T.U.			
COOLER			Boiler or Compressor to & incl. 15 Hp.			
BOILER OR			Absorption System to & incl. 500M B.T.U.			
BOILER OR			Boiler or Compressor to & incl. 30 Hp.			
COMPRESSOR			Absorption System to & incl. 1MM B.T.U.			
DECORATIVE			Boiler or Compressor to & incl. 50 Hp.			
DECORATIVE			Absorption System to & incl. 2MM B.T.U.			
APPLIANCE			Boiler or Compressor over 50 Hp.			
			Each Evaporative Cooler			
			Air Handling Unit to & incl. 2M C.F.M.			
			Air Handling Unit to & incl. 10M C.F.M.			
			Air Handling Unit over 10M C.F.M.			
			OTHER:			
FINAL	3-2-81	MA				
UTILITY CO.						
NOTIFIED						
IDENTIFICATION CODE			ITEM	CODE	FEES	
			Plan Retention Fee			
			Plan Check			
			Permit	227	5.00	
			Issuance	3117	6.00	
			TOTAL FEES		11.00	
BUILDING PERMIT NO.			AUTHORIZED BY		DATE	
ELECTRIC PERMIT NO.			LAND USE		BUILDING	
			DATE			
If work is not started within 120 days from date of issue or if abandoned for more than 120 days, this permit will be null and void.						

ADDRESS
9822 Russell

LOT NO. BLK NO. TRACT NO. PERMIT NO.
118587A

OWNER
Garden Grove Christian Church

PHONE
539-0408

OWNER'S ADDRESS
SAME

CITY

NEW BUILDING OR
ADDITION - AREA

EXISTING BUILDING
REMODEL AREA

OCCUPANCY
GROUP

USE OF BUILDING AND
OR NUMBER OF UNITS

VALIDATION
01-16-81
HTGPER
ISSNCE
CHECK

HEATING CONTRACTOR
MONICO

STATE LIC. NO. & TYPE
317930 - C-20

ADDRESS
1007 E. WASHINGTON, SANTA ANA

CITY
SANTA ANA

PHONE
972-1140

WORKER'S COMPENSATION REQUIREMENTS

State Compensation Insurance Policy No. 11441758-81 Expiration Date 4/81

☐ I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the Worker's Compensation laws of California.

NOTE: If, after making such certificate, the applicant for the permit should become subject to the Worker's Compensation provisions of this code, he shall forthwith comply with the provisions of Section 3700 or his permit shall be deemed revoked.

☒ I certify that I have read this application and state that the above information is correct. I agree to comply with all City ordinances and state laws relating to pending construction. I further agree to hold the City of Garden Grove free and harmless from any liability arising out of injury or bodily damage resulting from work performed relevant to this permit.

PERMIT APPLICANT SIGNATURE
DATE 1/16/81

BUSINESS TAX CERTIFICATE INFORMATION

I certify that the following Contractor's License No. 317930 and Classification MONICO is in full force and effect.

(PRINT) CONTRACTOR (SIGNATURE) CONTRACTOR OR AUTHORIZED AGENT DATE 1/16/81

EXPIRATION DATE

I certify that I am exempt from Section 7031.5 of the Labor Code and Professional Code, Division 3, Chapter 9, Contractors' License Law, under the following conditions:

Minor work under \$1000; Section 7048

Employer working for wages only; Section 7053

Other:

(PRINT) PROPERTY OWNER (SIGNATURE) PROPERTY OWNER OR AUTHORIZED AGENT DATE

A FEE MAY BE CHARGED FOR RE-INSPECTION DUE TO NEGLIGENCE, INCOMPLETE WORK, OR FAILURE TO MAKE CORRECTIONS.

DATE

INSPECTOR'S NOTES

1-19-81

Effect of complete
Nec. Penetration from inside
of wall: calculation with
Kara Estimate

BY

12-81

Q to Bolt if not end of

Dir

BY

1100000

9822

General Information
638-6661
038-0001

For Applicant to Fill in

INSPECTOR
INSPECTOR


CITY OF GARDEN GROVE

PLOT PLAN

PUBLIC WORKS & DEVELOPMENT 1

OWNER GARDEN GROVE CHRISTIAN CHURCH	JOB ADDRESS 9822 RUSSELL ST., G.G.		PERMIT NO. 121231A	
NAME OF CONSTRUCTION LENDER & BRANCH NONE	ASSESSORS PARCEL NO. 98-081-19	LOT	BLOCK	TRACT
PERMISSIONS REQUIRED				
☐ New ☐ Addition ☒ Alteration ☐ Repair ☐ Move ☐ Demolish				
ADDRESS	CITY	DATE 7-10-88	DESCRIPTION ALTERED DR. DRIVEWAY	PERMIT FEE 10,000

SHOW NORTH ARROW, PROPERTY LINES AND ADJACENT STREETS.

PLOT PLAN APPROVED BY
PLOT PLAN APPROVED BY#1 Building Inset, #22 Assessment, #3 Permitting, #4 Filing
I certify the information herein is complete and correct.By Owen Withers

DATE 7/14/88

RUSSELL

STREET NAME

9822

ADDRESS

APT. NO.

CARD NO.

9822


CITY OF GARDEN GROVE

PLOT PLAN

PUBLIC WORKS & DEVELOPMENT 1

OWNER GARDEN GROVE CHRISTIAN CHURCH	JOB ADDRESS 9822 RUSSELL ST.	PERMIT NO. 1290624
NAME OF CONSTRUCTION LENDER & BRANCH NONE	ASSESSOR'S PARCEL NO. LOT BLOCK TRACT 95-381-19	
	PLEASE CHECK ONE OR MORE ☐ New ☐ Addition ☒ Alteration ☐ Repair ☐ Move ☐ Demolish	
ADDRESS	DATE 5-4-83	JOB DESCRIPTION NEW DOOR & REMOVE WALL
CITY		PERMIT VALUE 200.00

SHOW NORTH ARROW, PROPERTY LINES AND ADJACENT STREETS.



#1 Building Insp./#2 Assessor/#3 Permittee/#4 File
 I certify the information hereon is complete and correct.

5y

PLOT REAS APPROVED BY

1. INSPECTOR

RUSSELL AVE

9822



CITY OF GARDEN GROVE
DEVELOPMENT SERVICES DEPARTMENT

RE-ROOFING INFORMATION
Permits/Inspection

17624

INFORMATION REQUIRED

1. Number of buildings to be re-roofed: (1) ONE
2. Number of existing roof coverings and types.
a. 1 HOT BUR - EXISTING b. 1 3-TAB SHINGLE c. 0 2-TAB SHINGLE
3. Pitch of roof(s). FLAT - FLAT // SHINGLE SHED
4. Number of squares to be re-roofed. 150
5. Complete description of work to be done, including materials to be used;
number and type of under layment:
SHINGLE: NAL 15# UNDERLAYMENT; NAL 3-TAB CORR SHINGLES; 34 IN/40 IN NAL
HOT: REE ROOF; NAL 22# GLASS BASE SHEET; HOT 2-1/2# NAL; HOT 3-1/2# CITY SHEET.

6. I.C.B.O. Research Number _____ Class _____
(if applicable)

7. Contract Price: \$ 16,000.00

METHOD OF PAYMENT

Pre-inspection and permit fees may be included on one check.
Permits will be required for each building.

INSPECTION PROCEDURE

1. Provide a safe ladder for each phase of inspection.
2. All materials to be on site at time of inspection.
3. If roof covering is to be removed or made smooth, work should be completed before pre-inspection.
4. Inspection and written approval by the building inspector shall be obtained prior to application of any re-roofing materials; then contact building inspection department at 741-8332 when starting re-roofing application.
5. "See Your Inspection Record Card." Inspection Record Card shall be conspicuous; posted on premises.
6. A final inspection and approval shall be obtained when re-roofing is completed.

Signatures: _____

[Signature]
Owner/Contractor/Agent

Job Address: 9822 RUSSELL AVE

1. Building Inspector
2. Permittee

468781/4900A



General Information: 714-741-5307

CITY OF GARDEN GROVE - DEVELOPMENT SERVICES DEPARTMENT

Inspection Requests: 714-741-5332

PERMIT (PAGE 2 of 2)**PROJECT/SITE/BUILDING DESCRIPTION**

JOB Address :
Suite :
PERMIT NO. : 29720
Permit Type : SIGN
Type : B11
 SIGNS
Owner : CHURCH GARDEN GROVE CHRISTIAN
Applicant : OWNER
Appl Address : 9822 RUSSELL AVE

Phone :

Insp Dist : SB
Date : 08/11/95
Parcel No : 09808119

PROPOSED WORK:

SIGN FACE CHANGE

FEEs

Permit	1	30.00
Issuance	1	25.00
Cultural Arts	1	1.25
General Plan	1	2.50

INSPECTION RECORD

APPROVAL DATE INSPECTOR

Pre Inspect _____
Foundation _____
Concrete Floor _____
Reinforcing _____
Masonry _____
Roof Shtg _____
Rough Frame _____
Insul / Energy _____
Drywall _____
Lath _____
Plas. Brown Ct. _____
Landscaping _____
Pre Gunita _____
Pre Deck _____
Pre Plaster _____

Planning Final _____

Bldg Final 8-22-95 H. Hodge

Utility Notified _____

11 3226 BLDG PERM & 30.00
11 3517 ISSUANCE FEE 25.00
80 3224 PERMITS/CULT 1.25
92 2163 GENERAL PLAN 2.50

TOTAL

58.75

AUTHORIZATIONIssued By: MK Date 8-12-95**DECLARATION**

I certify that I have read this application/permit and state that the information on all pages of this document is correct. I agree to comply with all City and County ordinances and State laws relating to building construction, and hereby authorize representatives of this City and County to enter upon the above mentioned property for inspection purposes.

Applicant's Signature C. Allen HodgePrint Name C. ALLEN HODGE Date 8/12/95

PERMIT (PAGE 1 OF 2)

Permit No.: 29720
 Job Address: 9822 Russell Ave

Type of Permit: ☐ Bldg. ☐ Elec.
☐ Mech. ☐ Plumb. ☐ Grading ☐ Street
☐ Sign ☐ Pool/Spa ☐ Fire Supp. Syst.

Owner STEVE BAEDER (MINISTEL)
 Address 6802 CHARLWOOD LAKENIA
CA 90713 Phone (310) 866-4071

Contractor AMU
 Address _____
 Phone _____

Lic. Class _____ Lic. No. _____

Architect/Engineer None
 Address _____
 Phone _____

Type of Lic. _____ Lic. No. _____

Applicant C. AULEN HODGE
 Address 15702 RYON AVE
BEVERLY CA Phone (310) 804-4558

DECLARATIONS

CONTRACTOR DECLARATION

☐ I hereby affirm under penalty of perjury that I am licensed under provisions of Chapter 9 (commencing with Section 7000) of Division 3 of the Business and Professions Code, and my license is in full force and effect.

OWNER-BUILDER DECLARATION

Sec. 7031.5, Business and Professions Code (B&PC) states: "Any city or county which requires a permit to construct, alter, improve, demolish, or repair any structure, prior to its issuance, also requires the applicant for such permit to file a signed statement that he or she is licensed pursuant to the provisions of the Contractors License Law (Chapter 9, commencing with Section 7000, of Division 3 of the B&PC) or that he or she is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit subjects the applicant to a civil penalty of not more than \$500." I hereby affirm under penalty of perjury that I am exempt from the Contractors License Law for the following reason.

☒ I, as owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered for sale. Sec. 7044, B&PC states: "The Contractor License Law does not apply to an owner of property who builds or improves thereon, and who does such work himself or herself or through his or her own employees, provided that such improvements are not intended or offered for sale. If, however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he or she did not build or improve for the purpose of sale."

☐ I, as owner of the property, am exclusively contracting with licensed contractors to construct the project. Sec. 7044, B&PC states: "The Contractors License Law does not apply to an owner of property who builds or improves thereon, and who contracts for such project with a contractor(s) licensed pursuant to the Contractor License Law."

☐ I am exempt under Sec. _____, B&PC for the following reason: _____

WORKERS' COMPENSATION DECLARATION

I hereby affirm under penalty of perjury one of the following declarations:

☐ I have and will maintain workers' compensation insurance, as required by Section 3700 of the Labor Code, for the performance of the work for which this permit is issued. My workers' compensation insurance carrier and policy number are:

Carrier N/A
 Policy Number N/A

☒ I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the worker's compensation laws of California, and agree that if I should become subject to the workers' compensation provisions of Sec. 3700 of the Labor Code, I shall forthwith comply with those provisions.

☒ I have and will maintain a certificate of consent to self insure for workers' compensation, as provided for by Section 3700 of the Labor Code, for the performance of the work for which this permit is issued.

WARNING: FAILURE TO SECURE WORKERS' COMPENSATION COVERAGE IS UNLAWFUL, AND SHALL SUBJECT AN EMPLOYER TO CRIMINAL PENALTIES AND CIVIL FINES UP TO ONE HUNDRED THOUSAND DOLLARS (\$100,000), IN ADDITION TO THE COST OF COMPENSATION, DAMAGES AS PROVIDED FOR IN SECTION 3706 OF THE LABOR CODE, INTEREST, AND ATTORNEY'S FEES.

CONSTRUCTION LENDING AGENCY

☐ I hereby affirm under penalty of perjury that there is a construction lending agency for the performance of the work for which this permit is issued (Sec. 3097 Civil Code).

Lender N/A
 Address _____

HAZMAT/AQMD DECLARATION

Will the applicant or future building occupant handle a hazardous material or a mixture containing a hazardous material equal or greater than the amounts specified in the hazardous materials information guide?

☒ NO ☐ YES

Refer to the AQMD permitting checklist and/or guidelines. Will the intended use of the building by the applicant or future building occupant require a permit for construction or modification from the South Coast Air Quality Management District (SCAQMD)?

☒ NO ☐ YES

I have read the hazardous material information guide and the SCAQMD permitting checklist. I understand my requirements under State of California Health and Safety Code, Section 2505, 2533, and 2534 concerning hazardous material reporting.

☒ YES ☐ NO

DEMOLITION/ASBESTOS DECLARATION

☒ I declare that written asbestos notification is not applicable to the scheduled project.

☐ On the attached sheet(s) are copies of all written asbestos notifications regarding the above referenced building that are required to be submitted to the United States Environmental Protection Agency or to a designated State agency, or both, pursuant to Part 61 of Title 40 of the Code of Federal Regulation or successor to that part.

DECLARATION

I certify that I have read this application/permit and state that the information on all pages of this document is correct. Under penalty of perjury, I hereby affirm all of the checked/marked declarations on this document. I agree to comply with all City and County ordinances and State laws relating to building construction, and hereby authorize representatives of this City and County to enter upon the above mentioned property for inspection purposes. I acknowledge that if work is not started within 180 days from the date of issue or if abandoned for more than 180 days, this permit will be null and void. I acknowledge that a fee may be charged for reinspection due to negligence, incomplete work, or failure to make corrections.


Signature C. Aulen Hodge
 Print Name C. Aulen Hodge Date 8/12/95

CITY OF GARDEN GROVE - DEVELOPMENT SERVICES DEPARTMENT - PLOT PLAN FORM

Planning action:	Use zone:
Land use approved by: <i>M/LH</i>	Lot size:
Date: <i>8/11/95</i>	Lot coverage:
Remarks:	↑ increase
<i>FACE CHANGE ONLY</i>	

Job address: <i>9822 Russell Ave</i>		Permit No. <i>29720</i>	
Assessor Parcel No. <i>09808119</i>		Legal desc.:	
Occupancy:	Const. type:	Sprinklers:	Value:
New		Alter	Add
Repair		Demo	

Job Description:
SIGN FACE CHANGE 9822 RUSSELL



White: Inspection
Yellow: Assessor
Pink: Permittee

I certify the information hereon is complete & correct.
STEVE BAEDER *C. Du Hu* 8/12/95
 Owner's name (print) Signature (owner/agent) Date

APPROVED
SIGN CODE DIV.
CITY OF GARDEN GROVE
BY [Signature]
DATE 8/11/98
COMMENTS
FACE CHANGE ONLY

*Cross
County*

upbeat
Worship Service
10:00 a.m.

CHRISTIAN CHURCH

"a friendly place"

537-4190

Permit 29720

PROJECT/SITE/BUILDING DESCRIPTION

JOB Address : 9822 RUSSELL AVE
Suite :
PERMIT NO. : 70871 - 70870
Permit Type : BUILDING
Type : B33
REPAIRS
Owner : CROSS COUNTY CHRISTIAN CHURCH
Applicant : ELLIOTT ROOF MAINTENANCE AND I
Appl Address : 324 SOUTH EARLHAM
ORANGE, CA 92869
Phone : 997-4938

Insp Dist : N-14
Date : 11/07/03
Parcel No : 09808119

Value : 29130
Floor area : 0

PROPOSED WORK:

T/O EXIST, APPLY (1) LAYER 30# ASTM FELT &
30YR GAF TIMERLINE ASPHALT SHINGLES.

FEES

111 32410 Permit	1	465.12
111 32401 issuance	1	35.00
942 22130 General Plan	1	35.50
080 32550 Cultural Arts	1	17.48
TOTAL		553.10

INSPECTION RECORD

APPROVAL	DATE	INSPECTOR
Pre Inspect	12-16-03	
Foundation		
Concrete Floor		
Reinforcing		
Masonry		
Roof Shtg		
Rough Frame		
Insul / Energy		
Drywall		
Lath		
Plas. Brown Ct.		
Landscaping		
Pre Gunit		
Pre Deck		
Pre Plaster		
Planning Final		
Bldg Final	2/2/04	
Utility Notified		

AUTHORIZATION

Issued By: jmc Date

DECLARATION

I certify that I have read this application/permit and state that the information on all pages of this document is correct. I agree to comply with all City and County ordinances and State laws relating to building construction, and hereby authorize representatives of this City and County to enter upon the above mentioned property for inspection purposes.

Applicant's Signature James H Elliott

Print Name: JAMES H ELLIOTT Date 11/7/03

***** VALIDATION *****

PAID ON 07 Nov 2003 AT 11:24
RECEIVED BY LARAINEM 198.245.206.215/2 TRANS# 54
AMOUNT PAID \$824.83 BY CHECK#21613
TOTAL PAID = \$824.83

PROJECT/SITE/BUILDING DESCRIPTION

JOB Address : 9822 RUSSELL AVE
 Suite :
 PERMIT NO. : 70870
 Permit Type : BUILDING
 Type : B33
 REPAIRS
 Owner : CROSS COUNTY CHRISTIAN CHURCH
 Applicant : ELLIOTT ROOF MAINTENANCE AND I
 Appl Address : 324 SOUTH EARLHAM
 ORANGE, CA 92869
 Phone : 997-4938

Insp Dist : ZB
 Date : 11/07/03
 Parcel No : 09808119

Value : 11000
 Floor area : 0

PROPOSED WORK:

T/O EXISTING/REROOF W/BUILT UP ASPHALT
 ROOFING SYSTEM/4 PLY/GRANULAR SURFING

FEES

111 32410 Permit	1	215.48
111 32401 issuance	1	35.00
942 22130 General Plan	1	14.24
080 32550 Cultural Arts	1	7.01
TOTAL		271.73

INSPECTION RECORD

APPROVAL DATE INSPECTOR
 Pre Inspect 12/16/03 GUY/CAO W FIBRO
 Foundation
 Concrete Floor
 Reinforcing
 Masonry 12/16/03 GUY/CAO W FIBRO
 Roof Shtg
 Rough Frame
 Insul / Energy
 Drywall
 Lath
 Plas.Brown Ct.
 Landscaping
 Pre Gunite
 Pre Deck
 Pre Plaster

Planning Final

Bldg Final 2/3/04

Utility Notified

AUTHORIZATION

Issued By: janetw Date

DECLARATION

I certify that I have read this application/permit and state that the information on all pages of this document is correct. I agree to comply with all City and County ordinances and State laws relating to building construction, and hereby authorize representatives of this City and County to enter upon the above mentioned property for inspection purposes.

Applicant's Signature James H Elliott

Print Name JAMES H ELLIOTT Date 11/7/03

***** VALIDATION *****

PAID ON 07 Nov 2003 AT 11:24

RECEIVED BY LARAINEM 198.245.206.215/2 TRANS# 54

AMOUNT PAID \$824.83 BY CHECK#21613

TOTAL PAID = \$824.83



General Information: 714-741-5307

CITY OF GARDEN GROVE - DEVELOPMENT SERVICES DEPARTMENT

Inspection Requests: 714-741-5332

PERMIT (PAGE 2 of 2)

PROJECT/SITE/BUILDING DESCRIPTION

JOB Address : 9822 RUSSELL AVE
Suite :
PERMIT NO. : 90636
Permit Type : SIGN
Type : B11
SIGNS
Owner : DE CRISTO DE RESTAURAC IGLESIA
Applicant : KATELYN LE
Phone : 714-534-3916

Contractor : OWNER
Address : 9822 RUSSELL AVE
CityStZip :
Phone :

Insp Dist : SB
Date : 06/07/07
Parcel No : 09808119

Value : 3100
Floor area : 0

PROPOSED WORK:

O28 - SIGNS

(1) CAN WALL SIGN.

FEES

111 32509 PLAN CHECK 65% (\$42.0	1	20.15
111 32410 Permit	1	31.00
111 32401 issuance	1	35.00
942 22130 General Plan	1	4.98
080 32550 Cultural Arts	1	2.45
TOTAL		93.58

APPROVAL DATE INSPECTOR

Pre Inspect _____
Foundation _____
Concrete Floor _____
Reinforcing _____
Masonry _____
Roof Shtg _____
Rough Frame _____
Insul / Energy _____
Drywall _____
Lath _____
Plas. Brown Ct. _____
Landscaping _____
Pre Gunitite _____
Pre Deck _____
Pre Plaster _____

Planning Final _____

Bldg Final 6-27-07 T.H

Utility Notified _____

***** VALIDATION *****
PAID ON 07 Jun 2007 AT 10:34
RECEIVED BY EVAR 198.245.206.215/2 TRANS# 50
CASH PAID = \$100.00 CASH RETURNED = \$6.42
TOTAL PAID = \$93.58

AUTHORIZATION

Issued By: jimc Date _____

DECLARATION

I certify that I have read this application/permit and state that the information on all pages of this document is correct. I agree to comply with all City and County ordinances and State laws relating to building construction, and hereby authorize representatives of this City and County to enter upon the above mentioned property for inspection purposes.

Applicant's Signature [Signature]Print Name XUAN MINH HO Date 6/07/2007




CITY OF GARDEN GROVE BUILDING SERVICES

General Info : 714-741-5307
Inspection Requests : 714-741-5332

9822 RUSSELL ST

PERMIT#:11-2640

ISSUED:12/1/11


Owner IGLESIA DE CRISTO DE RESTAURACION		Telephone	Zip 92844	Building Address 9822 RUSSELL ST																												
Address 9822 RUSSELL ST		City Garden Grove	State CA	Suite/Unit/Building																												
Applicant IGLESIA DE CRISTO DE RESTAURACION		Telephone	Zip 92844	TYPE Miscellaneous																												
Address 9822 RUSSELL ST		City Garden Grove	State CA	ISSUED BY Joanne Chung																												
Floor Area(sq. ft.)		Residential/Commercial Commercial		Inspector Dist. M14	Parcel Number 09808119																											
Job Description WROUGHT IRON FENCE BETWEEN (E)WOOD COLUMNS 110' X 5' IN FRONT OF PARKING AREA AT PRESCHOOL				LOT	TRACT																											
DECLARATION I certify that I have read this application/permit and state that the information on all pages of this document is correct. I agree to comply with all City and County ordinances and State laws relating to building construction, and hereby authorize representatives of this City and County to enter upon the above mentioned property for inspection purposes.				Valuation \$800.00																												
X Applicant's Signature 				Final Inspector's Signature _____ Date _____																												
Print Name <u>Jim Spencer</u> Date <u>12-1-11</u>				<table border="1"><thead><tr><th>Description</th><th>Quantity</th><th>Amount</th></tr></thead><tbody><tr><td>BSASRF State Fee</td><td></td><td>\$1.00</td></tr><tr><td>Issuance Fee</td><td>1</td><td>\$35.00</td></tr><tr><td>One-Stop Permit Center Surcharge</td><td></td><td>\$0.98</td></tr><tr><td>Building Permit Fee</td><td></td><td>\$49.00</td></tr><tr><td>Plan Check Fee</td><td></td><td>\$60.00</td></tr><tr><td>Cultural Arts Fee, Valuation</td><td></td><td>\$1.25</td></tr><tr><td>General Plan Update Fee, Valuation</td><td></td><td>\$2.50</td></tr><tr><td>TOTAL</td><td></td><td>\$149.73</td></tr></tbody></table>		Description	Quantity	Amount	BSASRF State Fee		\$1.00	Issuance Fee	1	\$35.00	One-Stop Permit Center Surcharge		\$0.98	Building Permit Fee		\$49.00	Plan Check Fee		\$60.00	Cultural Arts Fee, Valuation		\$1.25	General Plan Update Fee, Valuation		\$2.50	TOTAL		\$149.73
Description	Quantity	Amount																														
BSASRF State Fee		\$1.00																														
Issuance Fee	1	\$35.00																														
One-Stop Permit Center Surcharge		\$0.98																														
Building Permit Fee		\$49.00																														
Plan Check Fee		\$60.00																														
Cultural Arts Fee, Valuation		\$1.25																														
General Plan Update Fee, Valuation		\$2.50																														
TOTAL		\$149.73																														

This is a building permit when property filled out, signed and validated, and is subject to expiration if work thereunder is suspended for 180 days.

EXPIRED

Permit Type: BLDG


ORIGINAL




LEGEND - CHOOSE MORE SITES ✕

- Federal Superfund - REMOVE
- State Response - REMOVE
- Voluntary Cleanup - REMOVE
- School Cleanup - REMOVE
- Evaluation - REMOVE
- School Investigation - REMOVE
- Military Evaluation - REMOVE
- Tiered Permit - REMOVE
- Corrective Action - REMOVE
- Historical - REMOVE
- Field Points - REMOVE
- Operating - REMOVE
- Post-Closure - REMOVE
- Non-Operating - REMOVE

☐ Signifies a Closed Site





9822 russell

10 sites found

Did you mean: **9822 Russell Ave, Garden Grove, CA 92844**


MOBIL #18-GOE
13521 BROOKHURST
GARDEN GROVE CA 92643

Garden Grove Hyundai
9898 TRASK AVE
GARDEN GROVE CA 92844

TOYOTA PLACE
9670 TRASK AVE
GARDEN GROVE CA 92844

EXXON #7-0833
13502 BROOKHURST
GARDEN GROVE CA 92643

GAMMO CORP
13482 BROOKHURST ST
GARDEN GROVE CA 92843



Claude Parrish, Orange County Assessor

Property Address: 9822 RUSSELL AVE GARDEN GROVE CA 92844-2429

General Information

Parcel # (APN): 098-081-19

Owner: Available

Mailing Address: 9822 RUSSELL AVE GARDEN GROVE CA 92844

Legal Description: S TWP 5 RGE 10 SEC 6 SEC 6 T 5 R 10 S 226 FT N 256 FT E 5 AC SW1/4

Use Type: COMMERCIAL

Tax Rate Area: 018-032

Download Assessor Map



Assessment

Total Value: \$3,215,491

Land: \$2,639,390

Structures: \$576,101

Other:

% Improved: Available

Exempt Amt: \$3,215,491

Exempt Type: N

Year Assd: 2024

Zoning:

Use Code: Available

Census Tract: Available

Price/SqFt:

Detail Report \$14.95 [Learn More](#)

Sale History

	Sale 1	Sale 2	Sale 3	Transfer
Document Date:	02/28/2006	Available		Available
Document Number:	00136242	Available		Available
Document Type:	Available	Available		
Transfer Amount:	\$2,400,000			
Seller (Grantor):	Available			

Property Characteristics

Bedrooms:

Baths (Full):

Baths (Half):

Total Rooms:

Bldg/Liv Area:

Lot Acres: 1.806

Lot SqFt: 78,710

Year Built:

Effective Year:

Fireplace:

A/C:

Heating:

Pool:

Park Type:

Spaces:

Garage SqFt:

Units:

Stories:

Quality:

Building Class:

Condition:


Site Influence:

Timber Preserve:

Ag Preserve:

**The information provided here is deemed reliable, but is not guaranteed.

[Additional reports on this property](#)





Hazardous Waste Tracking System

Handler Search
Reports
ID Number
LoginSearch by... 

Filters



Advanced Search

Physical Address

9822 russell

garden grove

Zip Code...

County...

Handler...

Status...


Category...

ID Type...

Update

Clear

No Results Found.



NOTES TO USERS

is for use in administering the National Flood Insurance Program. It is not to be used for any other purpose. The community map repository should be used for possible updates or additional flood hazard information.

In more detailed information in areas where Base Flood Elevations and/or Floodways have been determined, users are encouraged to consult the Flood Insurance Study (FIS) report that accompanies the community map. Users should be aware that SFEs shown on the FIRM represent whole-foot elevations. These SFEs are intended for flood insurance purposes only and should not be used as the sole source of flood information. Accordingly, flood elevation data presented in the FIS should be utilized in conjunction with the FIRM for purposes of flood insurance.

Base Flood Elevations shown on this map apply only to landward of American Vertical Datum of 1988 (AVD 88). Users of this FIRM should be aware that coastal flood elevations are also provided in the Summary of Elevations tables in the Flood Insurance Study report for this jurisdiction. Users should be aware that SFEs shown on the FIRM represent whole-foot elevations. These SFEs are intended for flood insurance purposes only and should not be used as the sole source of flood information. Accordingly, flood elevation data presented in the FIS should be utilized in conjunction with the FIRM for purposes of flood insurance.

es of the floodways were computed at cross sections and interpolated cross sections. The floodways were based on hydraulic considerations and are not to be used for flood insurance purposes. Floodway and other pertinent floodway data are provided in the Flood Insurance Study report for this jurisdiction.

Areas not in Special Flood Hazard Areas may be protected by flood structures. Refer to Section 2.4 "Flood Protection Measures" of the Flood Insurance Study report for information on flood control structures for this jurisdiction.

ection used in the preparation of this map was Universal Transverse Mercator (UTM) Zone 11. The horizontal datum was NAD 83. CRS 83 is a datum, spheroid, projection or UTM zones used in the production of adjacent jurisdictions may result in slight positional differences in map across jurisdiction boundaries. These differences do not affect the use of this FIRM.

ations on this map are referenced to the North American Vertical Datum of 1988 (NAVD 88). These flood elevations must be compared to structure and ground elevations referenced to the same vertical datum. For information regarding the difference between the National Geodetic Vertical Datum of 1929 and the North American Vertical Datum of 1988, visit the National Geodetic Survey at <http://www.ngs.noaa.gov> or contact the National Geodetic Survey at the address below.

Information Services Branch
FEMA
Geodetic Survey
#9202
1600 Highway
Bldg. Maryland 20810-3282
3-3242

For current elevation, description, and/or location information for bench marks shown on this map, please contact the Information Services Branch, National Geodetic Survey at (800) 713-3242, or visit its website at www.ngs.noaa.gov.

Map information shown on this FIRM was derived from the National Flood Insurance Program, dated 2005.

This map reflects more detailed and up-to-date stream channel configurations than shown on the previous FIRM for this jurisdiction. The floodplains and floodway areas that were transferred from the previous FIRM may have been adjusted in to these new stream channel configurations. As a result, the Flood and Floodway Data tables in the Flood Insurance Study Report (which contain authoritative hydraulic data) may reflect stream channel distances that are different from those shown on this map.

he limits shown on this map are based on the best data available at the time of publication. Because changes due to annexations or de-annexations may occur after this map was published, map users should contact appropriate local officials to verify current corporate limit locations.

Refer to the separately printed Map Index for an overview map of the County showing the layout of map panels, community map repository addresses, and listing of communities table containing National Flood Insurance Program data for each community as well as a listing of the panels on which each community is located.

The FEMA Map Service Center at 1-800-358-8616 for information on products associated with this FIRM. Available products may include Flood Insurance Study, Flood Insurance Study Report, and/or Flood Insurance Study Map. The FEMA Map Service Center may also be reached at 1-800-358-8620 and its website at <http://msc.fema.gov>.

For questions about this map or questions concerning the National Flood Insurance Program in general, please call 1-877-FEMA-MAP (1-877-336-2627) or visit the FEMA website at <http://www.fema.gov>.



LEGEND

SPECIAL FLOOD HAZARD AREAS SUBJECT TO INUNDATION BY THE 1% ANNUAL CHANCE FLOOD

The 1% annual flood (100-year flood), also known as the base flood, is the flood that has a 1% chance of being equaled or exceeded in any given year. The Special Flood Hazard Areas are subject to flooding by the 1% annual chance flood. Areas of Special Flood Hazard Zones A, AE, AH, AO, AR, ASR, V, and VE. The Base Flood Elevation is the water elevation of the 1% annual chance flood.

Zone A
Flood depths of 1 to 3 feet (usually areas of ponding); Base Flood Elevations determined.

Zone AE
Flood depths of 1 to 3 feet (usually areas of ponding); Base Flood Elevations determined.

Zone AH
Flood depths of 1 to 3 feet (usually areas of ponding); Base Flood Elevations determined.

Zone AO
Flood depths of 1 to 3 feet (usually areas of ponding); Base Flood Elevations determined.

Zone AR
Special Flood Hazard Area formerly protected from the 1% annual flood by a flood control system that was subsequently dismantled. Indicated areas are not protected from the 1% annual flood by a flood control system under construction; no Base Flood Elevation is determined.

Zone ASR
Area to be protected from 1% annual chance flood by a Federal protection system under construction; no Base Flood Elevation is determined.

Zone V
Coastal flood zone with velocity hazard (wave action); no Base Flood Elevation is determined.

Zone VE
Coastal flood zone with velocity hazard (wave action); Base Flood Elevation is determined.

FLOODWAY AREAS IN ZONE AE

The floodway is the reach of a stream plus any adjacent floodplain areas that must be kept free of encroachment so that the 1% annual chance flood can be carried without substantial increase in flood heights.

OTHER FLOOD AREAS

Zone X
Areas of 0.2% annual chance flood; areas of 1% annual chance flood with average depths of less than 1 foot or with drainage areas less than 1 square mile and are unprotected by levees from 1% annual chance flood.

OTHER AREAS

Zone D
Areas determined to be outside the 0.2% annual chance floodplain.

Zone U
Areas in which flood hazards are undetermined, but possible.

COASTAL BARRIER RESOURCES SYSTEM (CBRS) AREAS

OTHERWISE PROTECTED AREAS (OPAs)

CBRS areas and OPAs are normally located within or adjacent to Special Flood Hazard Areas.

1% annual chance floodplain boundary

0.2% annual chance floodplain boundary

Floodway boundary

Zone D boundary

CBRS and OPA boundary

Boundary dividing Special Flood Hazard Area Zone AE from Zone V

Base Flood Elevation line and value; elevation in feet

Base Flood Elevation value where uniform within zone; elevation in feet

*** Referenced to the North American Vertical Datum of 1988**

Zone A
Zone AE

Geographic coordinates referenced to the North American Datum of 1983 (NAD 83), Western Hemisphere

1000-meter Universal Transverse Mercator grid values, NAD 83 UTM Zone 11N

5000-foot grid ticks: California State Plane coordinate system, zone VI (FIPS 5000-10406), Lambert Conformal Conic projection

Boundary mark (see explanation in Notes to Users section of FIS report)

River Mile

MAP REPOSITORY
Refer to listing of Map Repositories on Map Index

EFFECTIVE DATE OF COUNTYWIDE FLOOD INSURANCE RATE MAP
September 15, 1989

EFFECTIVE DATE OF REVISIONS TO THIS PANEL
February 5, 1989 - November 3, 1993 - January 1, 1997 - February 18, 2004 - December 5, 2005

For community map revision history prior to countywide mapping, refer to the Community Map History table located in the Flood Insurance Study report for this jurisdiction. For descriptions of revisions, see Notes to Users page in the Flood Insurance Study report.

For community map revision history prior to countywide mapping, refer to the Community Map History table located in the Flood Insurance Study report for this jurisdiction. For descriptions of revisions, see Notes to Users page in the Flood Insurance Study report.

To determine if flood insurance is available in this community, contact your insurance agent or call the National Flood Insurance Program at 1-800-438-6635.

MAP SCALE 1" = 500'

250 0 500 1000 FEET

150 0 150 300 METERS

NFIP

PANEL 0139J

FIRM

FLOOD INSURANCE RATE

ORANGE COUNTY, CALIFORNIA AND INCORPORATED AREAS

PANEL 139 OF 539

(SEE MAP INDEX FOR FIRM PANEL LIST)

CONTAINS

COMMUNITY	NUMBER	PANEL
GARDEN GROVE CITY OF	060230	0139
SANTA ANA CITY OF	060232	0139
WESTMINSTER CITY OF	060237	0139

Notice to User: The Map Number shown below is used when placing map orders. The Community Number shown above should be used on insurance applications.

FEDERAL EMERGENCY MANAGEMENT AGENCY

MAP NO. 06059C

MAP REVISION: DECEMBER 5, 2005

Case Closure Summary

Leaking Underground Fuel Tank Program

Date: February 28, 2005

I. Agency Information

Agency Name: Orange County Health Care Agency	Address: 2009 E. Edinger Avenue
City/State/Zip: Santa Ana , CA 92705	Phone: (714) 433-6255
Responsible staff person: Steven A. Speer	Title: Hazardous Waste Specialist

II. Case Information

Site Facility Name: ARCO Facility #0629				
Site Facility address: 13482 Brookhurst Street, Garden Grove, CA 92843				
RB LUSTIS Case No. 083002773T		Local Case No.		LOP Case No: 95UT62
URF filing date: 9/28/95		SWEEPS No.		
Responsible Parties		Addresses		Phone Numbers
Darrell Fah		ARCO Products Company		(714) 378-5105
		P.O. Box 5077		
		Buena Park, CA 90622-5077		
Tank No	Size in Gal.	Contents	Closed In-Place/Removed?	Date
1	6000	gasoline	removed	10/5/95
2	6000	gasoline	removed	10/5/95
3	6000	gasoline	removed	10/5/95
4	6000	gasoline	removed	10/5/95

III. Release and Site Characterization Information

Cause and type of release: Unknown			
Site characterization complete Yes		Date approved by oversight agency: October 25, 2000	
Monitoring Wells Installed? Yes		Number: 9	Proper screened interval? Yes
Highest GW depth BGS: 12.48 feet		Lowest depth: 22.84 feet	Flow direction: South
Most Sensitive Current Use: Municipal and domestic supply			
Are drinking water wells affected? No		Aquifer name: NA	
Is surface water affected? No		Nearest/affected SW name: NA	
Off-site beneficial use impacts (addresses/locations): NA			
Report(s) on file? Yes		Where is report(s) filed? OCHCA	
Treatment and Disposal of Affected Material			
Material	Amount (include Units)	Action (Treatment or Disposal/ Destination)	Date

Case Closure Summary
Leaking Underground Fuel Storage Tank Program

Case #: 95U162
Date: February 28, 2005

Tank	(4) 6000 gallon	L.A. Industrial Services, Inc.	10/5/95
Piping	Unknown	Removed	10/5/95
Soil	106 tons	Bradley Landfill	10/5/95
Rinsate	800 gallons	Demeco-Kerdecia	10/95
Groundwater	NA		
Product	NA		

IV. Release and Site Characterization Information (Continued)

Maximum Documented Contaminant Concentrations - - Before and After Cleanup									
Contaminant	Soil (ppm)		Water (ppm)		Contaminant	Soil (ppm)		Water (ppm)	
	Before	After	Before	After		Before	After	Before	After
TPH (gasoline)	12,000	290	81	25.0	MTBE	0.056	0.056	10.0	0.027
Benzene	8.8	1.4	5.7	0.15	TBA	<5.0	<5.0	0.84	<0.25
Toluene	250	7.4	22	0.14	ETBE	<0.25	<0.25	ND<50	<0.00
Ethylbenzene	310	5.1	5.9	3.5	TAME	<0.25	<0.25	ND<50	<0.00
Xylene	2000	24	21	4.5	DIPE	<0.25	<0.25	ND<50	<0.00

(Comments)

The case was opened in October 1995 with the removal of four 6000 gallon gasoline Underground Storage Tanks (UST). The soil samples that were obtained from beneath the eastern and southern dispenser islands and the two southernmost USTs were found to be contaminated with petroleum hydrocarbons. The most contaminated soil sample contained: Total Petroleum Hydrocarbons - gasoline range (TPHg) at a concentration of 12,000 ppm, benzene at a concentration of 8.8 ppm, toluene at a concentration of 250 ppm, ethylbenzene at a concentration of 310 ppm, and xylene at a concentration of 2000 ppm. These concentrations are listed in the above Maximum Documented Contaminant Concentrations Table as the "before" values for soil.

Prior to the UST removal, ARCO performed a Preliminary Site Assessment that involved the installation of two soil borings and one monitoring well. Soil boring B-1 was placed in the tank pit for the new USTs. This boring was found to be contaminated with benzene at a concentration of 2.4 ppm. Non-aqueous Phase Liquid (NAPL) was found in the 20 foot sample. This was the most contaminated sample from the boring. Unfortunately, a deeper soil sample was not obtained at that time.

In March, 1996 four additional monitoring wells were placed on the site. These monitoring wells completed a network of on-site monitoring wells that defined the groundwater contaminant plume to the west, east, and south of the site. Soil samples from these four additional wells were found to be "non-detect" for TPH-g, benzene, toluene, ethylbenzene, and xylene.

Offsite assessment was performed in December, 1996. Monitoring well MW-6 was installed across Brookhurst Street, in the westbound right hand lane of Trank Avenue. Soil samples from the boring for MW-6 were found to contain only non-detectable concentrations of petroleum hydrocarbons.

(continued)

Case Closure Summary
Leaking Underground Fuel Storage Tank Program

Case #: 95UT62
Date: February 28, 2005

(Additional comments, etc.)

Initially monitoring well MW-4, which is located at the midpoint of the line between the existing UST pit and the western dispenser island, was the most contaminated well on the site. The concentrations of petroleum hydrocarbons, that were found in the first groundwater sample from MW-4, were as follows: TPHg at a concentration of 81,000 ppb, benzene at a concentration of 5700 ppb, toluene at a concentration of 22,000 ppb, ethylbenzene at a concentration of 4800 ppb, and xylene at a concentration of 21,000 ppb.

With the exception of the concentration of ethylbenzene, these concentrations are listed in the Maximum Documented Contaminant Concentrations table as the "before" values for groundwater. The maximum documented contaminant concentration for ethylbenzene, as listed in the above table, was found in a sample from MW-4 that was obtained in March, 1997.

The maximum documented contaminant concentration of methyl tertiary-butyl ether (MTBE) was found in a groundwater sample from monitoring well MW-1. Using EPA Method 8020 as the laboratory analysis method, a groundwater sample that was obtained in March, 1997, was found to have an MTBE concentration of 10,000 ppb. This value is recorded as the "before" value for groundwater in the above Maximum Documented Contaminant Concentrations table. It should be noted, however, that the sample that was obtained from this same well, during the following quarter, was analyzed using EPA Method 8260B. This sample was found to contain MTBE at a concentration of 2500 ppb. EPA Method 8260B is considered to be the more accurate analytical method.

Because MW-1 continued to produce groundwater samples with the highest concentration of MTBE on the site, ARCO submitted a workplan for additional off site (downgradient) groundwater assessment. Monitoring wells MW-7 and MW-8 were installed in May, 2000. The soil samples that were obtained from the borings for these wells were found to contain only nondetectable concentrations of petroleum hydrocarbons, except for the 20 - foot soil sample from the boring for MW-7. This sample contained MTBE at a concentration of only 56 ppb. The groundwater samples from these offsite wells never contained benzene, toluene, ethylbenzene, and xylene above detectable concentrations. MTBE was detected in one groundwater sample from MW-8, at a concentration of 120 ppb. MTBE was detected in three groundwater samples from MW-7. The highest detected concentration of MTBE in these groundwater samples was 64 ppb.

Tertiary-butyl alcohol (TBA) was only detected twice in groundwater samples from the site. The first sample was obtained from MW-1 in June, 2001. This sample was found to contain TBA at a concentration of 840 ppb. This concentration is listed in the Maximum Documented Contaminant Concentrations table as the "before" value for groundwater. The previous quarter a groundwater sample from MW-1 was found to contain nondetectable concentrations of TBA. Likewise, the sample that was obtained during the quarter following the sample, that contained TBA at a concentration of 840 ppb, was also found to contain nondetectable concentrations of TBA. The other groundwater sample that contained a detectable concentration of TBA was obtained from monitoring well MW-3, in March, 2002. All other groundwater samples from MW-3 did not contain detectable concentrations of TBA.

A final set of monitoring wells was installed in October 2003. Monitoring well MW-9 was located approximately in the location of boring C-5, which was the boring that contained the "maximum documented contaminant concentrations" in soil. The soil from the boring for MW-9 was found to contain benzene at a concentration of only 1.4 ppm, at 25 feet bgs. Likewise, the concentration of toluene was 7.4 ppm, the concentration of ethylbenzene was 5.1 ppm, and the concentration of xylene was 24 ppm. The concentration of fuel oxygenates was nondetectable in the same soil sample. The above concentrations are listed as the "after" concentrations for soil in the above "Maximum Documented Contaminant Concentrations table.

The final groundwater samples that were obtained from monitoring well MW-9 were found to contain TPHg at a concentration of 25,000 ppb, benzene at a concentration of 150 ppb, toluene at a

Case Closure Summary
Leaking Underground Fuel Storage Tank Program

Case: #95UT62
Date: February 28, 2005

(Additional comments, etc.)

concentration of 140 ppb, ethylbenzene at a concentration of 3500 ppb, xylenes at a concentration of 4500 ppb, and MTBE at a concentration of 27 ppb. The groundwater samples did not contain detectable concentrations of the other fuel oxygenates. The above concentrations represent the "after" concentrations for groundwater in the above Maximum Documented Contaminant Concentrations table.

A deep cluster well was placed in a casing that was within five feet of MW-9. This well was called MW-9d. The soil samples from MW-9d were found to be lightly contaminated with benzene, toluene, ethylbenzene, and xylene, at a depth of 30 feet bgs. No detectable concentrations of fuel oxygenates were found in any soil samples from MW-9d. Detectable concentrations of ethylbenzene and xylene, however, were found down to 40 feet bgs, and possibly deeper.

The groundwater sample from MW-9d was found to contain benzene at a concentration of 130 ppb, toluene at a concentration of 320 ppb, ethylbenzene at a concentration of 120 ppb, and xylene at a concentration of 660 ppb. No fuel oxygenates were found in the groundwater.

The presence of TBA in the groundwater at the site is questionable. Furthermore, no other gasoline oxygenates (with the exception of MTBE), have been found in the groundwater samples from the site. There has been no active remediation of the soil and/or groundwater at this site. The extent of the petroleum hydrocarbon contamination, however, is known and the concentrations of benzene, toluene, MTBE, and TBA in the groundwater has been below "low-risk" guideline concentrations for at least one year.

This site is a low risk site and therefore not a risk to public health and the environment for the following reasons: 1) the source of the contamination which was the former UST system was removed in 1995; 2) the maximum benzene concentration in groundwater has diminished, through natural attenuation, to levels below "low risk" guidelines; 3) the groundwater has been monitored for 31 quarters and the concentrations of dissolved-phase contaminants are now stable; 4) sampling for MTBE and has shown that the concentrations of MTBE in the groundwater has been reduced to low-risk levels by natural attenuation; 5) the site has been adequately assessed with the remaining groundwater contamination confined to an area of limited lateral extent around the western dispenser island; 6) it is doubtful that the site has been contaminated with TBA, because past groundwater samples with detectable concentrations were both preceded and followed by groundwater samples without detectable concentrations; 7) the closest downgradient production drinking water well is located over 4000 feet from the site and is not likely to be impacted by the contaminant plume.

V. Closure

Does completed corrective action protect <i>existing</i> beneficial uses per the Regional Board Basin Plan?		Yes
Does completed corrective action protect <i>potential</i> beneficial uses per the Regional Board Basin Plan?		Yes
Does corrective action protect public health for current land use?		Yes
Site Management requirements: Soil contamination remains. Should future site activity disturb this soil, it should be handled per current regulations.		
Should corrective action be reviewed if land use changes? Yes, a health risk assessment should be conducted.		
Monitoring Wells Decommissioned: NA	Number Decommissioned: NA	Number Retained: NA
List enforcement actions taken: None		
List enforcement actions rescinded: None		

Case Closure Summary **Leaking Underground Fuel Storage Tank Program**

Case: #001702

Date: September 24, 2005

VI. Local Agency Representative Data

Name: Steven A. Speer, Ph.D.	Title: Hazardous Waste Specialist
Signature: <i>Steven A. Speer, Ph.D.</i>	Signature: <i>[Signature]</i>
Date: 9/24/05	Date: 9/24/05

VII. RWQCB Notification

Date Submitted to RB:	RB Response: <i>Compliance / Closure</i>
RWQCB Staff Name: Valerie John	Title: Environmental Scientist
Signature: <i>[Signature]</i>	Date:
RWQCB Supervisor Name: Ken Williams	Title: Chief Pollutant Investigation Section
Signature: <i>Kenneth R. Williams</i>	Date: 10/18/05

ANNUAL WATER QUALITY REPORT

Reporting Year 2024



Presented by
**City of Garden
Grove**

This report contains important information
about your drinking water. Translate it, or
speak with someone who understands it.

Este informe contiene información importante
sobre su agua potable. Traducirlo, o hablar con
alguien que lo entienda.

이 보고서에는 식수에 관한 중요한 정보가
포함되어 있습니다. 번역해 보세요,
아니면 이해해주는 사람과 얘기해봐

Báo cáo này chứa thông tin quan trọng
về nước uống của bạn. Dịch nó,
hoặc nói chuyện với người hiểu nó

Your 2025 Water Quality Report

Since 1990, California public water utilities have been providing an annual Water Quality Report to their customers. This year's report covers 2024 drinking water quality testing and reporting. The City of Garden Grove Water Services Division vigilantly safeguards its water supply, and as in years past, the water delivered to your home meets the quality standards required by federal and state regulatory agencies. The U.S. Environmental Protection Agency (U.S. EPA) and the State Water Resources Control Board (SWRCB), Division of Drinking Water (DDW) are the agencies responsible for establishing and enforcing drinking water quality standards.

In some cases, the City goes beyond what is required by testing for unregulated chemicals that may have known health risks but do not have drinking water standards. For example, the Orange County Water District (OCWD), which manages the groundwater basin, and the Metropolitan Water District of Southern California (MWDSC), which supplies imported, treated surface water to the City, test for unregulated chemicals in our water supply. Unregulated chemical monitoring helps U.S. EPA and DDW determine where certain chemicals occur and whether new standards need to be established for those chemicals to protect public health.

Through drinking water quality testing programs carried out by OCWD for groundwater, MWDSC for treated surface water, and the City for the water distribution system, your drinking water is constantly monitored from source to tap for regulated and unregulated constituents. The state allows us to monitor for some contaminants less than once per year because the concentrations of these contaminants do not change frequently. Some of our data, though representative, are more than a year old.

Source Water Assessment

Imported (MWDSC) Water Assessment

Every five years, MWDSC is required by DDW to examine possible sources of drinking water contamination in its State Water Project and Colorado River source waters. The most recent surveys for MWDSC's source waters are the Colorado River Watershed Sanitary Survey—2020 Update and the State Water Project Watershed Sanitary Survey—2021 Update. Water from the Colorado River is considered to be most vulnerable to contamination from recreation, urban/stormwater runoff, increasing urbanization in the watershed, and wastewater. Water supplies from Northern California's State Water Project are most vulnerable to contamination from urban/stormwater runoff, wildlife, agriculture, recreation, and wastewater. U.S. EPA also requires MWDSC to complete a source water assessment (SWA) that uses information collected in the watershed sanitary surveys. MWDSC completed its SWA in December 2002. The SWA is used to evaluate the vulnerability of water sources to contamination and helps determine whether more protective measures are needed. A copy of the most recent summary of the Watershed Sanitary Surveys or the SWA can be obtained by calling MWDSC at (800) CALL-MWD (800-225-5693).


Groundwater Assessment

An assessment of the drinking water sources for the City was completed in December 2002. The groundwater sources are considered most vulnerable to the following activities associated with contaminants detected in the water supply: known contaminant plumes, historic agricultural activities and application of fertilizers, and parks. The groundwater sources are considered most vulnerable to the following activities not associated with detected contaminants: confirmed leaking underground storage tanks, dry cleaners, gas stations, and photo processing/printing. A copy of the complete assessment is available at State Water Resources Control Board, Division of Drinking Water, 2 MacArthur Place, Suite 150, Santa Ana, CA 92707. You may request a summary of the assessment by contacting the City at (714) 741-5395.

Sources of Supply

Your drinking water is a blend of mostly groundwater from 11 wells in the Orange County groundwater basin and surface water imported by MWDSC. Imported water sources are the State Water Project from Northern California and the Colorado River Aqueduct. Your groundwater comes from a natural underground reservoir managed by the OCWD that stretches from the Prado Dam across the northwestern portion of Orange County, excluding the communities of Brea and La Habra, and stretching as far south as the El Toro Y.

Last year, as in years past, your tap water met all U.S. EPA and state drinking water health standards. The City vigilantly safeguards its water supplies, and once again, we are proud to report that our system has never violated a maximum contaminant level (MCL) or any other water quality standard. This brochure is a snapshot of last year's water quality. Included are details about where your water comes from, what it contains, and how it compares to federal and state standards.



We Invite You to Learn More About Your Water's Quality

For information about this report, or your water quality in general, please contact the water quality staff at (714) 741-5395. Public Garden Grove City Council meetings are held on the second and fourth Tuesday of each month at 6:30 p.m. in Council Chambers at the Community Meeting Center, 11300 Stanford Avenue. Contact our city clerk's office, Garden Grove City Hall, 11222 Acacia Parkway, or call (714) 741-5040 for information about city council meetings. Please feel free to participate in these meetings.

Quality Water is Our Priority

Turn the tap and the water flows, as if by magic. Or so it seems. The reality is considerably different. Delivering high-quality drinking water to our customers is a scientific and engineering feat that requires considerable effort and talent to ensure the water is always there, always safe to drink. Because tap water is highly regulated by state and federal laws, water treatment and distribution operators must be licensed.

Our licensed water professionals have an understanding of a wide range of subjects, including mathematics, biology, chemistry, physics, and engineering. Some of the tasks they complete on a regular basis include:

- Operating and maintaining equipment to purify and clarify water;
- Monitoring and inspecting machinery, meters, gauges, and operating conditions;
- Conducting tests and inspections on water and evaluating the results;
- Documenting and reporting test results and system operations to regulatory agencies; and
- Serving our community through customer support, education, and outreach.

So the next time you turn on your faucet, think of the skilled professionals who stand behind every drop.

About Lead in Tap Water

Lead can cause serious health effects in people of all ages, especially pregnant women, infants (both formula-fed and breastfed), and young children. Lead in drinking water is primarily from materials and parts used in service lines and home plumbing. Garden Grove is responsible for providing high-quality drinking water and removing lead pipes but cannot control the variety of materials used in the plumbing in your home. Because lead levels may vary over time, lead exposure is possible even when your tap sampling results do not detect lead at one point in time. You can help protect yourself and your family by identifying and removing lead materials within your home plumbing and taking steps to reduce your family's risk. Using a filter certified by an American National Standards Institute-accredited certifier to reduce lead is effective in reducing lead exposures. Follow the instructions provided with the filter to ensure it is used properly. Use only cold water for drinking, cooking, and making baby formula. Boiling does not remove lead from water.

Before using tap water for drinking, cooking, or making baby formula, flush your pipes for several minutes. You can do this by running your tap, taking a shower, or doing laundry or a load of dishes. If you have a lead or galvanized service line requiring replacement, you may need to flush your pipes for a longer period. If you are concerned about lead and wish to have your water tested, contact the Garden Grove water quality staff at (714) 741-5395. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available at epa.gov/safewater/lead.

Important Health Information

Some people may be more vulnerable to contaminants in drinking water than the general population. Immunocompromised persons such as persons with cancer undergoing chemotherapy, persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health-care providers. U.S. EPA/CDC guidelines on appropriate means to lessen the risk of infection by *Cryptosporidium* and other microbial contaminants are available from the Safe Drinking Water Hotline (1-800-426-4791).

Lead Service Line Inventory

Garden Grove has completed the lead service line initial inventory (LSLI) required by U.S. EPA's Lead and Copper Rule Revisions. The deadline for the LSLI was October 16, 2024. Through completing a historical records review and field investigations, Garden Grove has determined it has no lead or galvanized service lines requiring replacement in its distribution system. This includes any privately or customer-owned service lines. For more information, please visit <https://ggcity.org/pw/water-quality>.



2024 City of Garden Grove Drinking Water Quality

For more information about the health effects of the listed contaminants in the following tables, call the U.S. EPA hotline at (800) 426-4791.

2024 CITY OF GARDEN GROVE DISTRIBUTION SYSTEM WATER QUALITY					
	MCL (MRDL/ MRDLG)	AVERAGE AMOUNT	RANGE OF DETECTIONS	MCL VIOLATION	TYPICAL SOURCE OF CONTAMINANT
Disinfection Byproducts					
Total Trihalomethanes (ppb)	80	7	ND - 28	No	Byproducts of Chlorine Disinfection
Haloacetic Acids (ppb)	60	12	ND - 26	No	Byproducts of Chlorine Disinfection
Chlorine Residual (ppm)	(4 / 4)	0.77	0.08 - 2.8	No	Disinfectant Added for Treatment
Aesthetic Quality					
Color (color units)	15*	0.92	ND - 1	No	Erosion of Natural Deposits
Odor (threshold odor number)	3*	0.92	ND - 1	No	Erosion of Natural Deposits
Turbidity (ntu)	5*	0.15	ND - 0.32	No	Erosion of Natural Deposits

Eight locations in the distribution system are tested quarterly for total trihalomethanes and haloacetic acids; thirty-three locations are tested each month for color, odor and turbidity. MRDL = Maximum Residual Disinfectant Level; MRDLG = Maximum Residual Disinfectant Level Goal; *Contaminant is regulated by a secondary standard to maintain aesthetic qualities (taste, odor, color).

LEAD AND COPPER ACTION LEVELS AT RESIDENTIAL TAPS						
	ACTION LEVEL (AL)	PUBLIC HEALTH GOAL	90TH PERCENTILE VALUE	SITES EXCEEDING AL / NUMBER OF SITES	AL VIOLATION?	TYPICAL SOURCE OF CONTAMINANT
Lead (ppb)	15	0.2	ND<5	0 / 50	No	Corrosion of Household Plumbing
Copper (ppm)	1.3	0.3	0.11	0 / 50	No	Corrosion of Household Plumbing

Every three years, at least 50 residences are tested for lead and copper at-the-tap. The most recent set of samples was collected in 2022. Lead was detected above the reporting level in 1 sample, but did not exceed the lead Action Level. Copper was detected above the reporting level in 32 samples, but none of the samples exceeded the copper Action Level. A regulatory Action Level is the concentration of a contaminant which, if exceeded, triggers treatment or other requirements that a water system must follow.

Drinking Water Definitions

What are water quality standards?

Drinking water standards established by U.S. EPA and DDW set limits for substances that may affect consumer health or aesthetic qualities of drinking water.

The tables in this report show the following types of water quality standards:

- Maximum contaminant level (MCL):** The highest level of a contaminant that is allowed in drinking water. Primary MCLs are set as close to the PHGs (or MCLGs) as is economically and technologically feasible.
- Maximum residual disinfectant level (MRDL):** The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.
- Secondary MCLs are set to protect the odor, taste, and appearance of drinking water.
- Primary drinking water standard:** MCLs for contaminants that affect health, along with their monitoring and reporting requirements and water treatment requirements.
- Regulatory action level (AL):** The concentration of a contaminant that, if exceeded, triggers treatment or other requirements that a water system must follow.

What is a water quality goal?

In addition to mandatory water quality standards, U.S. EPA and DDW have set voluntary water quality goals for some contaminants. Water quality goals are often set at such low levels that they are not achievable in practice and are not directly measurable. Nevertheless, these goals provide useful guideposts and direction for water management practices.

The tables in this report include three types of water quality goals:

- Maximum contaminant level goal (MCLG):** The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs are set by U.S. EPA.
- Maximum residual disinfectant level goal (MRDLG):** The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.
- Public health goal (PHG):** The level of a contaminant in drinking water below which there is no known or expected risk to health. PHGs are set by the California EPA.

How are contaminants measured?

Water is sampled and tested throughout the year. Contaminants are measured in:

- Parts per million (ppm) or milligrams per liter (mg/L)
- Parts per billion (ppb) or micrograms per liter (µg/L)
- Parts per trillion (ppt) or nanograms per liter (ng/L)

2024 CITY OF GARDEN GROVE GROUNDWATER QUALITY

CHEMICAL	MCL	PHG (MCLG)	AVERAGE AMOUNT	RANGE OF DETECTIONS	MCL VIOLATION?	MOST RECENT SAMPLING DATE	TYPICAL SOURCE OF CONTAMINATION
Radiologicals							
Gross Alpha Particle Activity (pCi/L)	15	(0)	ND	ND - 4.8	No	2024	Erosion of Natural Deposits
Uranium (pCi/L)	20	0.43	8.2	5.9 - 10	No	2024	Erosion of Natural Deposits
Inorganic Chemicals							
Arsenic (ppb)	10	0.004	ND	ND - 4.7	No	2024	Erosion of Natural Deposits
Barium (ppm)	1	2	ND	ND - 0.13	No	2024	Erosion of Natural Deposits
Chromium, Hexavalent (ppb)	10	0.02	1.3	0.19 - 2	No	2024	Erosion of Natural Deposits; Industrial Discharge
Fluoride (ppm)	2	1	0.45	0.4 - 0.51	No	2024	Erosion of Natural Deposits
Nitrate (ppm as N)	10	10	3.2	0.52 - 4.2	No	2024	Fertilizers, Septic Tanks
Nitrate+Nitrite (ppm as N)	10	10	3.2	0.52 - 4.2	No	2024	Fertilizers, Septic Tanks
Perchlorate (ppb)	6	1	1.7	ND - 3.4	No	2024	Industrial Discharge
Secondary Standards*							
Chloride (ppm)	500*	n/a	72	26 - 116	No	2024	Erosion of Natural Deposits
Odor (threshold odor number)	3*	n/a	ND	ND - 1	No	2024	Erosion of Natural Deposits
Specific Conductance (µmho/cm)	1,600*	n/a	821	513 - 1,040	No	2024	Erosion of Natural Deposits
Sulfate (ppm)	500*	n/a	113	59 - 144	No	2024	Erosion of Natural Deposits
Total Dissolved Solids (ppm)	1,000*	n/a	516	300 - 662	No	2024	Erosion of Natural Deposits
Turbidity (ntu)	5*	n/a	ND	ND - 0.3	No	2024	Erosion of Natural Deposits
Unregulated Chemicals							
Alkalinity, total as CaCO3 (ppm)	Not Regulated	n/a	190	171 - 218	n/a	2024	Erosion of Natural Deposits
Boron (ppm)	NL = 1	n/a	0.1	ND - 0.25	n/a	2024	Erosion of Natural Deposits
Calcium (ppm)	Not Regulated	n/a	98	59 - 117	n/a	2024	Erosion of Natural Deposits
Hardness, total (grains per gallon)	Not Regulated	n/a	18	11 - 22	n/a	2024	Erosion of Natural Deposits
Hardness, total (ppm as CaCO3)	Not Regulated	n/a	316	189 - 374	n/a	2024	Erosion of Natural Deposits
Lithium (ppb) ¹	Not Regulated	n/a	ND	ND - 11	n/a	2024	Various Natural & Man-made Sources
Magnesium (ppm)	Not Regulated	n/a	18	10 - 21	n/a	2024	Erosion of Natural Deposits
Perfluorobutanoic acid (ppt)	Not Regulated	n/a	ND	ND - 15	n/a	2024	Industrial Discharge
Perfluorobutanoic acid (ppt) ¹	Not Regulated	n/a	ND	ND - 15	n/a	2024	Industrial Discharge
Perfluoro butane sulfonic acid (ppt)	NL = 500	n/a	ND	ND - 3.3	n/a	2024	Industrial Discharge
Perfluoro butane sulfonic acid (ppt) ¹	NL = 500	n/a	ND	ND - 2.7	n/a	2024	Industrial Discharge
Perfluoro hexane sulfonic acid (ppt)	NL = 3	n/a	3	ND - 11	n/a	2024	Industrial Discharge
Perfluoro hexane sulfonic acid (ppt) ¹	NL = 3	n/a	ND	ND - 9.6	n/a	2024	Industrial Discharge
Perfluorohexanoic acid (ppt)	Not Regulated	n/a	ND	ND - 8.1	n/a	2024	Industrial Discharge
Perfluorohexanoic acid (ppt) ¹	Not Regulated	n/a	ND	ND - 5.4	n/a	2024	Industrial Discharge
Perfluoro octane sulfonic acid (ppt)	NL = 6.5	1	4.7	ND - 18	n/a	2024	Industrial Discharge
Perfluoro octane sulfonic acid (ppt) ¹	NL = 6.5	1	4	ND - 19	n/a	2024	Industrial Discharge
Perfluoro octanoic acid (ppt)	NL = 5.1	0.007	ND	ND - 8.9	n/a	2024	Industrial Discharge
Perfluoro octanoic acid (ppt) ¹	NL = 5.1	0.007	ND	ND - 8.1	n/a	2024	Industrial Discharge
Perfluoropentanoic acid (ppt)	Not Regulated	n/a	3.7	ND - 9.8	n/a	2024	Industrial Discharge
Perfluoropentanoic acid (ppt) ¹	Not Regulated	n/a	2.9	ND - 8.6	n/a	2024	Industrial Discharge
pH (pH unit)	Not Regulated	n/a	7.9	7.7 - 8.1	n/a	2024	Acidity, hydrogen ions
Potassium (ppm)	Not Regulated	n/a	3.9	2.6 - 5.2	n/a	2024	Erosion of Natural Deposits
Sodium (ppm)	Not Regulated	n/a	53	35 - 89	n/a	2024	Erosion of Natural Deposits
Vanadium, Total (ppb)	NL = 50	n/a	1.9	ND - 3.8	n/a	2024	Erosion of Natural Deposits; Industrial Discharge

ppb = parts-per-billion; ppm = parts-per-million; ppt = parts per trillion; pCi/L = picoCuries per liter; ntu = nephelometric turbidity units; ND = not detected; NL = Notification Level; n/a = not applicable; MCL = Maximum Contaminant Level; PHG = California Public Health Goal; µmho/cm = micromho per centimeter; *Contaminant is regulated by a secondary standard to maintain aesthetic qualities (taste, odor, color).

¹ Constituent is part of the Fifth Unregulated Contaminant Rule (UCMR 5)

2024 METROPOLITAN WATER DISTRICT OF SOUTHERN CALIFORNIA TREATED SURFACE WATER

CONSTITUENT	MCL	PHG (MCLG)	AVERAGE AMOUNT	RANGE OF DETECTIONS	MCL VIOLATION?	TYPICAL SOURCE IN DRINKING WATER
Radiologicals - Tested in 2023 and 2024						
Gross Alpha Particle Activity (pCi/L)	15	(0)	ND	ND - 5	No	Erosion of Natural Deposits
Gross Beta Particle Activity (pCi/L)	50	(0)	4	ND - 5	No	Decay of Natural and Man-made Deposits
Uranium (pCi/L)	20	0.43	1	ND - 3	No	Erosion of Natural Deposits
Inorganic Chemicals - Tested in 2024						
Aluminum (ppm)	1	0.6	ND	ND - 0.11	No	Treatment Process Residue, Natural Deposits
Barium (ppm)	1	2	0.124	0.124	No	Refinery Discharge, Erosion of Natural Deposits
Bromate (ppb)	10	0.1	ND	ND - 1.6	No	Byproduct of Drinking Water Ozonation
Fluoride (ppm) treatment-related	2	1	0.7	0.6 - 0.8	No	Water Additive for Dental Health
Secondary Standards* - Tested in 2024						
Aluminum (ppb)	200*	600	ND	ND - 110	No	Treatment Process Residue, Natural Deposits
Chloride (ppm)	500*	n/a	104	93 - 116	No	Runoff or Leaching from Natural Deposits
Color (color units)	15*	n/a	2	1 - 2	No	Runoff or Leaching from Natural Deposits
Odor (threshold odor number)	3*	n/a	1	1	No	Naturally-occurring Organic Materials
Specific Conductance (µmho/cm)	1,600*	n/a	979	888 - 1,070	No	Substances that Form Ions in Water
Sulfate (ppm)	500*	n/a	224	196 - 253	No	Runoff or Leaching from Natural Deposits
Total Dissolved Solids (ppm)	1,000*	n/a	621	556 - 686	No	Runoff or Leaching from Natural Deposits
Unregulated Chemicals - Tested in 2024						
Alkalinity, total (ppm as CaCO ₃)	Not Regulated	n/a	114	105 - 123	n/a	Runoff or Leaching from Natural Deposits
Boron (ppm)	NL = 1	n/a	0.14	0.14	n/a	Runoff or Leaching from Natural Deposits
Calcium (ppm)	Not Regulated	n/a	68	58 - 78	n/a	Runoff or Leaching from Natural Deposits
Hardness, total (ppm as CaCO ₃)	Not Regulated	n/a	270	235 - 305	n/a	Runoff or Leaching from Natural Deposits
Hardness, total (grains/gal)	Not Regulated	n/a	16	14 - 18	n/a	Runoff or Leaching from Natural Deposits
Magnesium (ppm)	Not Regulated	n/a	26	22 - 29	n/a	Runoff or Leaching from Natural Deposits
pH (units)	Not Regulated	n/a	8.2	8.2	n/a	Hydrogen Ion Concentration
Potassium (ppm)	Not Regulated	n/a	4.9	4.4 - 5.4	n/a	Runoff or Leaching from Natural Deposits
Sodium (ppm)	Not Regulated	n/a	103	90 - 116	n/a	Runoff or Leaching from Natural Deposits
Total Organic Carbon (ppm)	TT	n/a	2.4	2 - 2.5	n/a	Various Natural and Man-made Sources

ppb = parts per billion; ppm = parts per million; pCi/L = picoCuries per liter; µmho/cm = micromhos per centimeter; ND = not detected; MCL = Maximum Contaminant Level; (MCLG) = federal MCL Goal; PHG = California Public Health Goal NL = Notification Level; n/a = not applicable; TT = treatment technique; * Chemical is regulated by a secondary standard.



METROPOLITAN WATER DISTRICT DIEMER FILTRATION PLANT	TREATMENT TECHNIQUE	TURBIDITY MEASUREMENTS	TT VIOLATION?	TYPICAL SOURCE IN DRINKING WATER
Turbidity - combined filter effluent				
1) Highest single turbidity measurement (NTU)	0.3	0.06	No	Soil Runoff
2) Percentage of samples less than or equal to 0.3 NTU	95%	100%	No	Soil Runoff

Turbidity is a measure of the cloudiness of the water, an indication of particulate matter, some of which might include harmful microorganisms. Low turbidity in Metropolitan's treated water is a good indicator of effective filtration. Filtration is called a "treatment technique" (TT). A treatment technique is a required process intended to reduce the level of chemicals in drinking water that are difficult and sometimes impossible to measure directly. NTU = nephelometric turbidity units

UNREGULATED CONSTITUENTS REQUIRING MONITORING

CONSTITUENT	NL	PHG	AVERAGE AMOUNT	RANGE OF DETECTIONS	MOST RECENT SAMPLING DATE
Lithium (ppb)	n/a	n/a	21	ND - 35	2023

NL = Notification Level

Drinking Water Contaminants

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally occurring minerals and, in some cases, radioactive material and can pick up substances resulting from the presence of animals or from human activity.



Contaminants that may be present in source water include:

- Microbial contaminants, such as viruses and bacteria, that may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- Inorganic contaminants, such as salts and metals, that can be naturally occurring or result from urban stormwater runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- Pesticides and herbicides that may come from a variety of sources such as agriculture, urban stormwater runoff, and residential uses.
- Organic chemical contaminants, including synthetic and volatile organic chemicals, that are by-products of industrial processes and petroleum production and can also come from gas stations, urban stormwater runoff, agricultural application, and septic systems.
- Radioactive contaminants that can be naturally occurring or the result of oil and gas production and mining activities.

To ensure that tap water is safe to drink, the U.S. EPA and SWRCB prescribe regulations that limit the amount of certain contaminants in water provided by public water systems. U.S. Food and Drug Administration regulations and California law also establish limits for contaminants in bottled water that provide the same protection for public health. Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the U.S. EPA's Safe Drinking Water Hotline (1-800-426-4791).



PFAS Advisory

Per- and polyfluoroalkyl substances (PFAS) are a group of human-made chemicals that have been used in various consumer products since the 1940s due to their resistance to heat, water, oils, and stains. These chemicals are prevalent in the environment and have been detected in water supplies nationwide. Studies suggest that exposure to certain PFAS may pose health risks. The U.S. EPA and DDW have established health-based advisories for PFAS. If PFAS levels exceed these guidelines, water agencies must notify their governing bodies and take necessary actions, such as removing affected sources from service or implementing treatment solutions.

To address PFAS contamination, water providers have conducted testing and taken proactive steps to ensure safe drinking water.

Regulatory actions: The U.S. EPA announced final National Primary Drinking Water Regulations for six PFAS in April 2024. Public water systems are required to monitor these substances, with full reporting and compliance expected by 2027.

For more details on PFAS regulations and water safety, visit:

- California State Water Resources Control Board, Division of Drinking Water: waterboards.ca.gov/pfas
- Orange County Water District: ocwd.com/what-we-do/water-quality/pfas
- U.S. EPA: epa.gov/pfas

Cross Connections

The SWRCB updated the Cross-Connection Control Policy Handbook (CCCPH) on July 1, 2024. More information about the City of Garden Grove's Cross-Connection Control (CCC) Plan is available at <https://ggcity.org/pw/cross-connections-faqs>.



City of Garden Grove, Water Services Division
(714) 741-5395 • <https://ggcity.org/pw/water>

Drinking Water Fluoridation

Fluoride has been added to U.S. drinking water supplies since 1945 to help prevent tooth decay. As of today, the majority of public water suppliers in the country, including the MWDSC, fluoridate their water. MWDSC began adding fluoride in December 2007, complying with all provisions of California's fluoridation system requirements. Fluoride levels in drinking water are regulated in California and limited to a maximum of 2 parts per million (ppm). Some local groundwater supplies naturally contain fluoride, but they are not supplemented with additional fluoride.

Additional Information

For more details on water fluoridation, please visit:

- **U.S. Centers for Disease Control and Prevention (CDC):** cdc.gov/fluoridation or (800) 232-4636
- **State Water Resources Control Board, Division of Drinking Water:** waterboards.ca.gov/drinking_water/certlic/drinkingwater/Fluoridation.html
- **American Dental Association:** ada.org
- **American Water Works Association:** awwa.org

For specific inquiries about MWDSC's fluoridation program, please contact MWDSC directly at (800) 225-5693.

Cryptosporidium

Cryptosporidium is a microscopic organism that originates from animal and human waste and may be present in surface water. When ingested, it can cause diarrhea, fever, and other gastrointestinal symptoms. In 2024 the MWDSC tested for Cryptosporidium and did not detect its presence in any water after it had been treated. If Cryptosporidium is ever detected in drinking water, it is effectively removed through a combination of sedimentation, filtration, and disinfection.

The U.S. EPA and the Centers for Disease Control and Prevention (CDC) provide guidelines on how to reduce the risk of infection from Cryptosporidium and other microbial contaminants. For more information, contact the U.S. EPA's Safe Drinking Water Hotline at (800) 426-4791 or visit epa.gov/safewater.



APPENDIX C: REGULATORY DATABASE REPORT



DATABASE REPORT

Project Property:	9822 Russell Avenue 9822 Russell Avenue GARDEN GROVE CA 92844
Project No:	25-500978.1
Report Type:	Database Report
Order No:	25061300823
Requested by:	Partner Engineering and Science, Inc.
Date Completed:	June 16, 2025

Environmental Risk Information Services

A division of Glacier Media Inc.

1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....	2
Executive Summary.....	3
Executive Summary: Report Summary.....	4
Executive Summary: Site Report Summary - Project Property.....	10
Executive Summary: Site Report Summary - Surrounding Properties.....	11
Executive Summary: Summary by Data Source.....	21
Map.....	34
Aerial.....	37
Topographic Map.....	38
Detail Report.....	39
Unplottable Summary.....	295
Unplottable Report.....	296
Appendix: Database Descriptions.....	299
Definitions.....	319

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property: 9822 Russell Avenue
9822 Russell Avenue GARDEN GROVE CA 92844

Project No: 25-500978.1

Coordinates:

Latitude:	33.7681234
Longitude:	-117.9578273
UTM Northing:	3,736,867.00
UTM Easting:	411,313.04
UTM Zone:	11S

Elevation: 74 FT

Order Information:

Order No: 25061300823
Date Requested: June 13, 2025
Requested by: Partner Engineering and Science, Inc.
Report Type: Database Report

Historicals/Products:

Aerial Photographs	Historical Aerials (with Project Boundaries)
City Directory Search	Smart CD Search
ERIS Xplorer	ERIS Xplorer
Excel Add-On	Excel Add-On
Fire Insurance Maps	US Fire Insurance Maps
Physical Setting Report (PSR)	Physical Setting Report (PSR)
Topographic Map	Topographic Maps
Vapor Screening Tool	Vapor Screening Tool

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
<u>Standard Environmental Records</u>								
Federal								
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	0	-	0
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	0	0	2	-	2
RCRA LQG	Y	0.25	0	0	0	-	-	0
RCRA SQG	Y	0.25	0	2	3	-	-	5
RCRA VSQG	Y	0.25	0	0	0	-	-	0
RCRA NON GEN	Y	0.25	0	11	18	-	-	29
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
FRP	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
RESPONSE	Y	1	0	0	0	0	0	0
ENVIROSTOR	Y	1	0	0	0	0	0	0
DELISTED ENVS	Y	1	0	0	0	0	0	0
SWF/LF	Y	0.5	0	0	0	0	-	0
SWRCB SWF	Y	0.5	0	0	0	0	-	0
WMUD	Y	0.5	0	0	0	0	-	0
HWP	Y	1	0	0	0	0	0	0
SWAT	Y	0.5	0	0	0	0	-	0
C&D DEBRIS RECY	Y	0.5	0	2	0	1	-	3
RECYCLING	Y	0.5	0	0	0	0	-	0
PROCESSORS	Y	0.5	0	0	0	0	-	0
CONTAINER RECY	Y	0.5	0	0	0	0	-	0
LDS	Y	0.5	0	0	0	0	-	0
LUST	Y	0.5	0	0	6	5	-	11
DELISTED LST	Y	0.5	0	0	0	0	-	0
UST	Y	0.25	0	0	2	-	-	2
UST CLOSURE	Y	0.5	0	0	1	0	-	1
HHSS	Y	0.25	0	0	4	-	-	4
UST SWEEPS	Y	0.25	0	2	7	-	-	9
AST	Y	0.25	0	2	0	-	-	2
AST SWRCB	Y	0.25	0	1	0	-	-	1
TANK OIL GAS	Y	0.25	0	0	0	-	-	0
DELISTED TNK	Y	0.25	0	3	6	1	-	10
CERS TANK	Y	0.25	0	2	2	-	-	4
DELISTED CTNK	Y	0.25	0	0	0	-	-	0
HIST TANK	Y	0.25	0	0	4	-	-	4
LUR	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
CALSITES	Y	0.5	0	0	0	0	-	0
HLUR	Y	0.5	0	0	0	0	-	0
DEED	Y	0.5	0	0	0	0	-	0
VCP	Y	0.5	0	0	0	0	-	0
CLEANUP SITES	Y	0.5	0	0	0	0	-	0
DELISTED CLEANUP	Y	0.5	0	0	0	0	-	0
DELISTED COUNTY	Y	0.25	0	0	0	-	-	0

Tribal

INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED INDIAN LST	Y	0.5	0	0	0	0	-	0
DELISTED INDIAN UST	Y	0.25	0	0	0	-	-	0

County

ICP ORANGE	Y	0.25	0	0	0	-	-	0
LOP ORANGE	Y	0.5	0	0	7	5	-	12
NPUT ORANGE	Y	0.5	0	0	0	0	-	0
UST ORANGE	Y	0.25	0	0	4	-	-	4
AST ORANGE	Y	0.25	0	2	0	-	-	2
UST CLP ANAHEIM	Y	0.5	0	0	0	0	-	0
UST ANAHEIM	Y	0.25	0	0	0	-	-	0
AST ANAHEIM	Y	0.25	0	0	0	-	-	0

Additional Environmental Records

Federal

OSC RESPONSE	Y	0.125	0	0	-	-	-	0
PFAS GHG	Y	0.5	0	0	0	0	-	0
FINDS/FRS	Y	PO	0	-	-	-	-	0
TRIS	Y	PO	0	-	-	-	-	0
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS FED SITES	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
PFAS ERNS	Y	0.5	0	0	0	0	-	0
PFAS NPDES	Y	0.5	0	0	0	0	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
PFAS TSCA	Y	0.5	0	0	0	0	-	0
PFAS E-MANIFEST	Y	0.5	0	0	0	0	-	0
PFAS IND	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	1	-	-	1
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	0	0
FUDS MRS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
LM SITES	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	0	-	-	0
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
AFS	Y	PO	0	-	-	-	-	0
SSTS	Y	0.25	0	0	0	-	-	0
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	0	-	0
POWER PLANTS	Y	0.125	0	0	-	-	-	0
HIST RISK	Y	0.125	0	0	-	-	-	0
State								
PFAS SAMPLING	Y	0.5	0	0	0	0	-	0
DRYCLEANERS	Y	0.25	0	0	1	-	-	1

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DRYC GRANT	Y	0.25	0	0	0	-	-	0
PFAS GT CLEANUPS	Y	0.5	0	0	0	0	-	0
PFAS GW	Y	0.5	0	0	0	0	-	0
PFAS INVEST	Y	0.5	0	0	0	0	-	0
HWSS CLEANUP	Y	0.5	0	0	0	0	-	0
TOXIC PITS	Y	1	0	0	0	0	0	0
DTSC HWF	Y	0.5	0	0	0	0	-	0
INSP COMP ENF	Y	1	0	0	0	0	1	1
SCH	Y	1	0	0	0	0	0	0
CHMIRS	Y	PO	0	-	-	-	-	0
HIST CHMIRS	Y	PO	0	-	-	-	-	0
HAZNET	Y	PO	0	-	-	-	-	0
HAZ GEN	Y	PO	0	-	-	-	-	0
HAZ TSD	Y	0.5	0	0	0	0	-	0
HIST MANIFEST	Y	PO	0	-	-	-	-	0
HW TRANSPORT	Y	0.125	0	0	-	-	-	0
WASTE TIRE	Y	PO	0	-	-	-	-	0
MEDICAL WASTE	Y	0.25	0	0	0	-	-	0
HIST CORTESE	Y	0.5	0	0	0	0	-	0
CDO/CAO	Y	0.5	0	0	0	0	-	0
CERS HAZ	Y	0.125	0	2	-	-	-	2
DELISTED HAZ	Y	0.5	0	0	0	0	-	0
GEOTRACKER	Y	0.125	0	0	-	-	-	0
MINE	Y	1	0	0	0	0	0	0
LIEN	Y	PO	0	-	-	-	-	0
WASTE DISCHG	Y	0.25	0	0	0	-	-	0
EMISSIONS	Y	0.25	0	0	5	-	-	5
CDL	Y	0.125	0	0	-	-	-	0

Tribal

No Tribal additional environmental record sources available for this State.

County

HW ORANGE	Y	0.125	0	4	-	-	-	4
-----------	---	-------	---	---	---	---	---	---

Total: 0 33 71 14 1 119

** PO – Property Only*

** 'Property and adjoining properties' database search radii are set at 0.25 miles.*

Executive Summary: Site Report Summary - Project Property

<i>Map Key</i>	<i>DB</i>	<i>Company/Site Name</i>	<i>Address</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev Diff (ft)</i>	<i>Page Number</i>
--------------------	-----------	--------------------------	----------------	------------------	-----------------------------	---------------------------	------------------------

No records found in the selected databases for the project property.

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	RCRA NON GEN	SUNNYSIDE ELEMENTARY SCHOOL	9972 RUSSELL AVE GARDEN GROVE CA 92844	ESE	0.06 / 309.08	-1	39
Handler ID Recycler Activity?: CAC003292523 NO							
2	RCRA NON GEN	LARRY LOCKWOOD	13292 VERDE ST GARDEN GROVE CA 92844	NNE	0.07 / 366.46	0	41
Handler ID Recycler Activity?: CAC003099098 NO							
2	RCRA NON GEN	LARRY LOCKWOOD	13292 VERDE ST GARDEN GROVE CA 92844	NNE	0.07 / 366.46	0	43
Handler ID Recycler Activity?: CAC003114378 NO							
3	RCRA NON GEN	13282 VERDE ST, #3	13282 VERDE ST, #3 GARDEN GROVE CA 92844	NNE	0.08 / 431.94	0	45
Handler ID Recycler Activity?: CAC003232900 NO							
4	DELISTED TNK	GARDEN GROVE DODGE/SUBARU/HYUND AI	9666 TRASK AVE GARDEN GROVE CA 92844	SW	0.09 / 476.68	-3	48
4	UST SWEEPS	QUALITY NISSAN	9666 TRASK AVE GARDEN GROVE CA	SW	0.09 / 476.68	-3	48
C C Status: A30-000-12923 ACTIVE Tank ID: 000007, 000005							
5	CERS HAZ	VUNG TAU AUTO REPAIR	13331 BROOKHURST ST C GARDEN GROVE CA 92843	ENE	0.09 / 494.13	2	48
6	CERS HAZ	QUOC AUTO REPAIR	13331 BROOKHURST ST #A GARDEN GROVE CA 92843	ENE	0.09 / 500.98	2	54
7	RCRA NON GEN	KHOI VU	9791 IMPERIAL AVE GARDEN GROVE CA 92844- 2413	NNW	0.10 / 531.25	0	59
Handler ID Recycler Activity?: CAC003060207 NO							
8	RCRA SQG	UNION DODGE	9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	-2	61
Handler ID Recycler Activity?: CAD982313199 NO							
8	DELISTED TNK	GARDEN GROVE MITSUBISHI	9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	-2	63
8	AST ORANGE	Russell Westbrook Hyundai Of Garden Grove	9898 Trask Ave Garden Grove, Ca 92844-2800 CA	SE	0.10 / 547.63	-2	64
Establishment ID: FA0054812							

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
8	AST		9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	-2	64
8	HW ORANGE	Russell Westbrook Hyundai Of Garden Grove	9898 Trask Ave Garden Grove, Ca 92844-2800 Garden Grove CA 92844-2800	SE	0.10 / 547.63	-2	64
8	CERS TANK	Garden Grove Hyundai	9898 TRASK AVE GARDEN GROVE CA 92844 <i>Site ID: 118782</i>	SE	0.10 / 547.63	-2	64
8	RCRA NON GEN	DYNAMIC AUTO IMAGES	9898 TRASK AVENUE GARDEN GROVE CA 92844 <i>Handler ID Recycler Activity?: CAL000429991 NO</i>	SE	0.10 / 547.63	-2	73
8	RCRA NON GEN	YNOT6 II LLC DBA GARDEN GROVE HYUNDAI	9898 TRASK AVE GARDEN GROVE CA 92844 <i>Handler ID Recycler Activity?: CAL000428944 NO</i>	SE	0.10 / 547.63	-2	75
8	UST SWEEPS	GARDEN GROVE MITSUBISHI	9898 TRASK AVE GARDEN GROVE CA <i>C C Status: A30-000-6947 ACTIVE Tank ID: 000001, 000002</i>	SE	0.10 / 547.63	-2	78
8	C&D DEBRIS RECY	UNION CHRYSLER JEEP DODGE	9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	-2	78
9	RCRA SQG	QUALITY NISSAN	9670 TRASK AVE GARDEN GROVE CA 92844 <i>Handler ID Recycler Activity?: CAD982357949 NO</i>	SW	0.11 / 557.72	-3	78
9	DELISTED TNK	QUALITY NISSAN	9670 TRASK AVE GARDEN GROVE CA 92844	SW	0.11 / 557.72	-3	80
9	AST ORANGE	Toyota Place	9670 Trask Ave Garden Grove, Ca 92844-2801 CA <i>Establishment ID: FA0051444</i>	SW	0.11 / 557.72	-3	81
9	AST		9670 TRASK AVE GARDEN GROVE CA 92844	SW	0.11 / 557.72	-3	81
9	HW ORANGE	Toyota Place	9670 Trask Ave Garden Grove, Ca 92844-2801 Garden Grove CA 92844-2801	SW	0.11 / 557.72	-3	81
9	CERS TANK	TOYOTA PLACE	9670 TRASK AVE GARDEN GROVE CA 92844 <i>Site ID: 178742</i>	SW	0.11 / 557.72	-3	81

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
9	RCRA NON GEN	NOARUS TGG INC DBA TOYOTA PLACE	9670 TRASK AVE GARDEN GROVE CA 92844- 2801 <i>Handler ID Recycler Activity?:</i> CAL000330099 NO	SW	0.11 / 557.72	-3	95
9	AST SWRCB	NISSAN	9670 TRASK AVE GARDEN GROVE CA 92844- 2801	SW	0.11 / 557.72	-3	97
9	C&D DEBRIS RECY	TOYOTA PLACE	9670 TRASK AVE GARDEN GROVE CA 92844	SW	0.11 / 557.72	-3	97
10	RCRA NON GEN	ROBERT KELLEY	13262 VERDE ST, UNIT 1 GARDEN GROVE CA 92884 <i>Handler ID Recycler Activity?:</i> CAC003203540 NO	N	0.11 / 559.27	0	97
11	RCRA NON GEN	LORI DUNHAM	9771 IMPERIAL AVE GARDEN GROVE CA 92844 <i>Handler ID Recycler Activity?:</i> CAC003174431 NO	NW	0.11 / 569.37	0	100
11	RCRA NON GEN	9771 IMPERIAL AVE	9771 IMPERIAL AVE GARDEN GROVE CA 92840- 3434 <i>Handler ID Recycler Activity?:</i> CAC003214811 NO	NW	0.11 / 569.37	0	102
12	HW ORANGE	Vung Tau Auto Repair	13331 Brookhurst St Ste C Garden Grove, Ca 92843-7000 Garden Grove CA 92843-7000	ENE	0.12 / 649.42	1	104
12	HW ORANGE	Quoc Auto Repair	13331 Brookhurst St Ste A Garden Grove, Ca 92843-7000 Garden Grove CA 92843-7000	ENE	0.12 / 649.42	1	104
13	RCRA NON GEN	JANNIEN NGUYEN	9942 CENTRAL AVE, APT F GARDEN GROVE CA 92844 <i>Handler ID Recycler Activity?:</i> CAC003271573 NO	NE	0.14 / 722.41	2	104
14	RCRA SQG	BIG O TIRES	13388 BROOKHURST ST GARDEN GROVE CA 92841 <i>Handler ID Recycler Activity?:</i> CAD981668973 NO	E	0.15 / 775.47	1	107
14	RCRA NON GEN	HAS INC DBA ZUBYS BRAKES TIRES AND WHEELS	13388 BROOKHURST ST GARDEN GROVE CA 92843- 3153 <i>Handler ID Recycler Activity?:</i> CAL000313023 NO	E	0.15 / 775.47	1	109
15	DELISTED TNK	MOBIL #18-G03E	13521 BROOKHURST ST # 18-G03E GARDEN GROVE CA 92843	ESE	0.15 / 782.79	-2	111
15	LUST	MOBIL #18-GOE	13521 BROOKHURST GARDEN GROVE CA 92643 <i>Global ID Status:</i> T0605901769	ESE	0.15 / 782.79	-2	111

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
15	LOP ORANGE	Mobil #18-Goe	13521 Brookhurst St Garden Grove Ca 92643 CA Case ID: 94UT037 Closed Date: 3/7/1995	ESE	0.15 / 782.79	-2	113
15	UST SWEEPS	MOBIL #18-G03E	13521 BROOKHURST ST GARDEN GROVE CA C C Status: A30-000-2129 ACTIVE Tank ID: 000004, 000001, 000003, 000005	ESE	0.15 / 782.79	-2	114
16	RCRA SQG	BP WEST COAST PRODUCTS LLC NO 0629	13482 BROOKHURST ST GARDEN GROVE CA 92643 Handler ID Recycler Activity?: CAR000174276 NO	ESE	0.15 / 811.75	-1	115
16	UST ORANGE	Gammo Corporation	13482 Brookhurst St Garden Grove, Ca 92843-3119 Garden Grove CA FA No: FA0052965	ESE	0.15 / 811.75	-1	117
16	LUST	ARCO #629	13482 BROOKHURST GARDEN GROVE CA 92844 Global ID Status: T0605901913	ESE	0.15 / 811.75	-1	117
16	HHSS	LIAQUAT ALI JUMANI	13482 BROOKHURST ST GARDEN GROVE CA 92643	ESE	0.15 / 811.75	-1	122
16	UST	GAMMO CORP	13482 BROOKHURST ST GARDEN GROVE CA 92843 Facility ID: FA0052965 Tank ID No. Tank Status Tank Closure Date: 3 Confirmed/Updated Information , 2 Renewal Permit , 1 Renewal Permit , 4 Renewal Permit	ESE	0.15 / 811.75	-1	122
16	EMISSIONS	GAMMO C30P30ATION	13482 BROOKHURST ST GARDEN GROVE CA 92843	ESE	0.15 / 811.75	-1	124
16	LOP ORANGE	Arco #629	13482 Brookhurst St Garden Grove Ca 92843-3119 CA Case ID: 95UT062 Closed Date: 11/17/2005	ESE	0.15 / 811.75	-1	124
16	CERS TANK	GAMMO CORP	13482 BROOKHURST ST GARDEN GROVE CA 92843 Site ID: 393660	ESE	0.15 / 811.75	-1	124
16	HIST TANK	LIAQUAT ALI JUMANI	13482 BROOKHURST ST. GARDEN GROVE CA	ESE	0.15 / 811.75	-1	145
16	EMISSIONS	GAMMO CORPORATION	13482 BROOKHURST ST GARDEN GROVE CA 92843	ESE	0.15 / 811.75	-1	146
16	RCRA NON GEN	GAMMO CORPORATION	13482 BROOKHURST ST GARDEN GROVE CA 92843-3119 Handler ID Recycler Activity?: CAL000338171 NO	ESE	0.15 / 811.75	-1	147

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
16	UST SWEEPS	ARCO #629	13482 BROOKHURST ST GARDEN GROVE CA C C Status: A30-000-4348 ACTIVE Tank ID: 000002, 000003, 000001, 000004	ESE	0.15 / 811.75	-1	149
17	DELISTED TNK	EXXON #7-0833	13502 BROOKHURST ST # 7-0833 GARDEN GROVE CA 92843	ESE	0.16 / 829.33	-2	150
17	LUST	EXXON #7-0833	13502 BROOKHURST GARDEN GROVE CA 92643 Global ID Status: T0605970421	ESE	0.16 / 829.33	-2	150
17	HHSS	EXXON SERVICE STATION	13502 BROOKHURST GARDEN GROVE CA 92640	ESE	0.16 / 829.33	-2	156
17	LOP ORANGE	Exxon #7-0833	13502 Brookhurst St Garden Grove Ca 92643 CA Case ID: 92UT061 Closed Date: 2/7/1996	ESE	0.16 / 829.33	-2	156
17	HIST TANK	EXXON SERVICE STATION	13502 BROOKHURST GARDEN GROVE CA	ESE	0.16 / 829.33	-2	156
17	UST SWEEPS	EXXON #7-0833	13502 BROOKHURST ST GARDEN GROVE CA C C Status: A30-000-2122 ACTIVE Tank ID: 000004, 000003, 000001, 000005	ESE	0.16 / 829.33	-2	156
17	LOP ORANGE	Exxon #7-0833	13502 Brookhurst St Garden Grove Ca 92643 CA Case ID: 92UT125 Closed Date: 1/1/1992	ESE	0.16 / 829.33	-2	157
18	RCRA NON GEN	9705 IMPERIAL AVE	9705 IMPERIAL AVE GARDEN GROVE CA 92844 Handler ID Recycler Activity?: CAC003239797 NO	WNW	0.16 / 842.99	-2	157
19	RCRA NON GEN	GABRIEL RASCOL	10021 RUSSELL AVE GARDEN GROVE CA 92843 Handler ID Recycler Activity?: CAC003121243 NO	ENE	0.17 / 880.94	1	160
20	RCRA SQG	SEXTONS AUTOMOTIVE	10041 TRASK AVE GARDEN GROVE CA 92843 Handler ID Recycler Activity?: CAD982052995 NO	ESE	0.18 / 939.28	0	162
20	DELISTED TNK	SEXTONS AUTOMOTIVE	10041 TRASK AVE GARDEN GROVE CA 92843	ESE	0.18 / 939.28	0	164
20	UST SWEEPS	SEXTONS AUTOMOTIVE	10041 TRASK AVE GARDEN GROVE CA C C Status: A30-000-3140 ACTIVE Tank ID: 000002	ESE	0.18 / 939.28	0	164

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
21	DELISTED TNK	KARAMAT STATION	13231 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.18 / 944.26	2	165
21	LUST	ANDYS UNOCAL	13231 BROOKHURST GARDEN GROVE CA 92844 <i>Global ID Status:</i> T0605900976	NE	0.18 / 944.26	2	165
21	HHSS	A SAADAI UNION 76	13231 BROOKHURST ST. GARDEN GROVE CA 92643	NE	0.18 / 944.26	2	182
21	LOP ORANGE	Andys Unocal	13231 Brookhurst St Garden Grove Ca 92843-1009 CA <i>Case ID:</i> 89UT095 <i>Closed Date:</i> 5/26/2014	NE	0.18 / 944.26	2	182
21	HIST TANK	A. SAADI UNION 76	13231 BROOKHURST ST. GARDEN GROVE CA	NE	0.18 / 944.26	2	182
21	UST CLOSURE	FKA Andy's Unocal	13231 Brookhurst Ave., Garden Grove, CA 92643 CA <i>Claim Case No:</i> Claim No. 2776	NE	0.18 / 944.26	2	182
21	RCRA NON GEN	VN AUTO	13231 BROOKHURST ST GARDEN GROVE CA 92843 <i>Handler ID Recycler Activity?:</i> CAP000186775 NO	NE	0.18 / 944.26	2	183
22	UST SWEEPS	DON THIO	13231 S BROOKHURST ST GARDEN GROVE CA <i>C C Status:</i> A30-000-13410 ACTIVE <i>Tank ID:</i> 000004, 000002, 000001, 000003	NE	0.18 / 960.03	2	186
22	UST SWEEPS	KARAMAT STATION	13231 S BROOKHURST ST GARDEN GROVE CA <i>C C Status:</i> A30-000-4349 ACTIVE <i>Tank ID:</i> 000001, 000004, 000003, 000005	NE	0.18 / 960.03	2	187
23	RCRA NON GEN	DANG DANG	9672 IMPERIAL AVENUE GARDEN GROVE CA 92844 <i>Handler ID Recycler Activity?:</i> CAC003205204 NO	WNW	0.19 / 984.44	-1	188
24	RCRA NON GEN	MARIE CALLENDARS	13252 BROOKHURST STREET GARDEN GROVE CA 92843 <i>Handler ID Recycler Activity?:</i> CAC003164178 NO	ENE	0.19 / 986.51	3	190
24	RCRA NON GEN	13252 BROOKHURST ST	13252 BROOKHURST ST GARDEN GROVE CA 92843 <i>Handler ID Recycler Activity?:</i> CAC003246861 NO	ENE	0.19 / 986.51	3	192
25	RCRA NON GEN	9671 IMPERIAL AVE	9671 IMPERIAL AVE GARDEN GROVE CA 92844 <i>Handler ID Recycler Activity?:</i> CAC003108729 NO	WNW	0.19 / 1,015.19	-1	194
26	RCRA NON GEN	MEAALII LOLOGO	9642 IMPERIAL AVE GARDEN GROVE CA 92844	WNW	0.21 / 1,106.38	-1	196

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
Handler ID Recycler Activity?: CAC003257686 NO							
26	RCRA NON GEN	MEAAALII LOLOGO	9642 IMPERIAL AVE GARDEN GROVE CA 92844	WNW	0.21 / 1,106.38	-1	199
Handler ID Recycler Activity?: CAC003257533 NO							
27	RCRA NON GEN	BOWERS COMPANIES	13222 BROOKHURST ST GARDEN GROVE CA 92840	NE	0.21 / 1,110.53	0	201
Handler ID Recycler Activity?: CAD028230811 NO							
27	DELISTED TNK	BOWERS CO	13222 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.21 / 1,110.53	0	203
27	LUST	BOWERS CO	13222 BROOKHURST GARDEN GROVE CA 92844	NE	0.21 / 1,110.53	0	204
Global ID Status: T0605900855							
27	LOP ORANGE	Bowers Co	13222 Brookhurst St Garden Grove Ca 92843-1010 CA Case ID: 88UT176 Closed Date: 4/19/2012	NE	0.21 / 1,110.53	0	218
28	RCRA NON GEN	ANA FIGUEROA	9651 IMPERIAL AVE. GARDEN GROVE CA 92844	WNW	0.21 / 1,133.87	-1	218
Handler ID Recycler Activity?: CAC003077198 NO							
29	DRYCLEANERS	MY FAVORITE CLEANERS	13197 BROOKHURST ST GARDEN GROVE CA	NE	0.22 / 1,140.42	1	220
29	EMISSIONS	MY FAVORITE CLEANERS, SEONG HE	13197 BROOKHURST ST. GARDEN GROVE CA 92640	NE	0.22 / 1,140.42	1	220
29	RCRA NON GEN	MY FAVORITE CLEANERS	13197 BROOKHURST ST GARDEN GROVE CA 92843- 1009	NE	0.22 / 1,140.42	1	221
Handler ID Recycler Activity?: CAL000015627 NO							
29	FED DRYCLEANERS	MY FAVORITE CLEANERS	13197 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.22 / 1,140.42	1	224
FRS Facility ID: 110070442968							
30	DELISTED TNK	PRONTO MARKETING 312	13202 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	1	224
30	UST ORANGE	Garden Grove Shell	13202 Brookhurst St Garden Grove, Ca 92843-1010 Garden Grove CA FA No: FA0057500	NE	0.23 / 1,217.53	1	224
30	LUST	JET GAS STATION	13202 BROOKHURST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	1	224

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
Global ID Status: T0605900794							
30	HHSS	JET	13202 BROOKHURST GARDEN GROVE CA 92643	NE	0.23 / 1,217.53	1	239
30	UST	GARDEN GROVE SHELL	13202 Brookhurst St Garden Grove CA 92843 Facility ID: FA0057500 Tank ID No. Tank Status Tank Closure Date: 3 Confirmed/Updated Information , 1 Confirmed/Updated Information , 2 Confirmed/Updated Information	NE	0.23 / 1,217.53	1	239
30	LOP ORANGE	Jet Gas Station	13202 Brookhurst St Garden Grove Ca 92843-1010 CA Case ID: 88UT135 Closed Date: 4/18/2014	NE	0.23 / 1,217.53	1	241
30	CERS TANK	GARDEN GROVE SHELL	13202 BROOKHURST ST GARDEN GROVE CA 92843 Site ID: 366507	NE	0.23 / 1,217.53	1	241
30	HIST TANK	JET	13202 BROOKHURST GARDEN GROVE CA	NE	0.23 / 1,217.53	1	265
30	EMISSIONS	BR PETROLEUM INC	13202 BROOKHURST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	1	265
30	UST ORANGE	M & R STATION	13202 BROOKHURST GARDEN GROVE CA 92843 FA No: FA24722	NE	0.23 / 1,217.53	1	266
30	UST ORANGE	ULTRAMAR STATION	13202 BROOKHURST GARDEN GROVE CA 92843 FA No: FA24722	NE	0.23 / 1,217.53	1	266
30	RCRA NON GEN	GARDEN GROVE SHELL	13202 BROOKHURST GARDEN GROVE CA 92843 Handler ID Recycler Activity?: CAL000453941 NO	NE	0.23 / 1,217.53	1	266
30	UST SWEEPS	PRONTO MARKETING	13202 BROOKHURST ST GARDEN GROVE CA C C Status: A30-000-4347 ACTIVE Tank ID: 000002, 000003, 000001	NE	0.23 / 1,217.53	1	268
30	EMISSIONS	KORMEX MANAGEMENT & MARKETING, INC.	13202 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	1	269
31	RCRA NON GEN	PACIFIC COAST OIL CO	13169 J BROOKHURST ST GARDEN GROVE CA 92843 Handler ID Recycler Activity?: CAD981428766 NO	NE	0.24 / 1,263.24	1	269
32	RCRA NON GEN	DENTAL OFFICE LIEN HUONG	13161 BROOKHURST ST GARDEN GROVE CA 92843-0000	NE	0.24 / 1,281.70	1	272

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
Handler ID Recycler Activity?: CAL000223611 NO							
33	DELISTED TNK	ARCO #629	13482 BROOKHURST ST GARDEN GROVE CA 92843	E	0.25 / 1,321.03	2	274
34	LOP ORANGE	Ejax Water Systems	9911 Larson Ave Garden Grove Ca 92844-1657 CA Case ID: 89UT181 Closed Date: 12/14/1989	N	0.28 / 1,453.83	2	274
35	LUST	EJAX WATER SYSTEMS	9911 LARSON GARDEN GROVE CA 92644 Global ID Status: T0605901020	N	0.28 / 1,454.05	2	274
36	LUST	COUNTY WIDE CHRYSLER/JEEP	10080 GARDEN GROVE GARDEN GROVE CA 92842 Global ID Status: T0605918872	N	0.33 / 1,768.44	6	277
37	RCRA TSD	MARCOS LOPEZ	13632 DAWSON ST GARDEN GROVE CA 92843 Handler ID Recycler Activity?: CAC003017595 NO	ESE	0.35 / 1,870.77	-2	280
38	LOP ORANGE	County Wide Chrysler/Jeep	10080 Garden Grove Blvd Garden Grove Ca 92844-1694 CA Case ID: 99UT016 Closed Date: 2/12/2003	N	0.37 / 1,959.35	6	282
39	LUST	TOYOTA OF GARDEN GROVE	10081 GARDEN GROVE GARDEN GROVE CA 92641 Global ID Status: T0605901533	N	0.43 / 2,266.02	7	283
39	LOP ORANGE	Toyota Of Garden Grove	10081 Garden Grove Blvd Garden Grove Ca 92844-1620 CA Case ID: 92UT026 Closed Date: 4/14/1992	N	0.43 / 2,266.02	7	285
39	C&D DEBRIS RECY	GARDEN GROVE KIA	10081 GARDEN GROVE BLVD GARDEN GROVE CA 92844	N	0.43 / 2,266.02	7	285
40	RCRA TSD	HOUSE OF HYBRIDS	9825 GARDEN GROVE BLVD GARDEN GROVE CA 92844 Handler ID Recycler Activity?: CAL000444865 YES	NNW	0.46 / 2,417.25	3	285
41	LUST	ORIENTAL LEASING	9672 GARDEN GROVE GARDEN GROVE CA 92641 Global ID Status: T0605900714	NW	0.46 / 2,453.34	2	288
42	LUST	4 DAY TIRE STORE	13961 BROOKHURST GARDEN GROVE CA 92643 Global ID Status: T0605901280	SSE	0.47 / 2,478.76	-4	290
43	LOP ORANGE	Oriental Leasing	9672 Garden Grove Blvd Garden Grove Ca 92844-1516 CA	NW	0.48 / 2,548.01	0	293

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			Case ID: 88UT083 Closed Date: 8/7/2000				
43	LOP ORANGE	Orental Leasing	9672 Garden Grove Blvd Garden Grove Ca 92844-1516 CA	NW	0.48 / 2,548.01	0	293
			Case ID: 88UT077 Closed Date: 1/1/1988				
44	INSP COMP ENF	VETERANS ED'S INC	10372 STANFORD AVENUE #S GARDEN GROVE CA 92840	NE	0.68 / 3,589.02	11	293

Executive Summary: Summary by Data Source

Standard

Federal

RCRA TSD - RCRA non-CORRACTS TSD Facilities

A search of the RCRA TSD database, dated Jan 6, 2025 has found that there are 2 RCRA TSD site(s) within approximately 0.50miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
HOUSE OF HYBRIDS	9825 GARDEN GROVE BLVD GARDEN GROVE CA 92844	NNW	0.46 / 2,417.25	40
<i>Handler ID Recycler Activity?: CAL000444865 YES</i>				

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
MARCOS LOPEZ	13632 DAWSON ST GARDEN GROVE CA 92843	ESE	0.35 / 1,870.77	37
<i>Handler ID Recycler Activity?: CAC003017595 NO</i>				

RCRA SQG - RCRA Small Quantity Generators List

A search of the RCRA SQG database, dated Jan 6, 2025 has found that there are 5 RCRA SQG site(s) within approximately 0.25miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
BIG O TIRES	13388 BROOKHURST ST GARDEN GROVE CA 92841	E	0.15 / 775.47	14
<i>Handler ID Recycler Activity?: CAD981668973 NO</i>				

SEXTONS AUTOMOTIVE	10041 TRASK AVE GARDEN GROVE CA 92843	ESE	0.18 / 939.28	20
<i>Handler ID Recycler Activity?: CAD982052995 NO</i>				

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
UNION DODGE	9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	8
<i>Handler ID Recycler Activity?: CAD982313199 NO</i>				

QUALITY NISSAN	9670 TRASK AVE GARDEN GROVE CA 92844	SW	0.11 / 557.72	9
<i>Handler ID Recycler Activity?: CAD982357949 NO</i>				

BP WEST COAST PRODUCTS LLC NO 0629	13482 BROOKHURST ST GARDEN GROVE CA 92643	ESE	0.15 / 811.75	16
<i>Handler ID Recycler Activity?: CAR000174276 NO</i>				

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Jan 6, 2025 has found that there are 29 RCRA NON GEN site(s) within approximately 0.25miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
LARRY LOCKWOOD	13292 VERDE ST GARDEN GROVE CA 92844	NNE	0.07 / 366.46	<u>2</u>
	Handler ID Recycler Activity?: CAC003099098 NO			
LARRY LOCKWOOD	13292 VERDE ST GARDEN GROVE CA 92844	NNE	0.07 / 366.46	<u>2</u>
	Handler ID Recycler Activity?: CAC003114378 NO			
13282 VERDE ST, #3	13282 VERDE ST, #3 GARDEN GROVE CA 92844	NNE	0.08 / 431.94	<u>3</u>
	Handler ID Recycler Activity?: CAC003232900 NO			
KHOI VU	9791 IMPERIAL AVE GARDEN GROVE CA 92844-2413	NNW	0.10 / 531.25	<u>7</u>
	Handler ID Recycler Activity?: CAC003060207 NO			
ROBERT KELLEY	13262 VERDE ST, UNIT 1 GARDEN GROVE CA 92884	N	0.11 / 559.27	<u>10</u>
	Handler ID Recycler Activity?: CAC003203540 NO			
LORI DUNHAM	9771 IMPERIAL AVE GARDEN GROVE CA 92844	NW	0.11 / 569.37	<u>11</u>
	Handler ID Recycler Activity?: CAC003174431 NO			
9771 IMPERIAL AVE	9771 IMPERIAL AVE GARDEN GROVE CA 92840-3434	NW	0.11 / 569.37	<u>11</u>
	Handler ID Recycler Activity?: CAC003214811 NO			
JANNIEN NGUYEN	9942 CENTRAL AVE, APT F GARDEN GROVE CA 92844	NE	0.14 / 722.41	<u>13</u>
	Handler ID Recycler Activity?: CAC003271573 NO			
HAS INC DBA ZUBYS BRAKES TIRES AND WHEELS	13388 BROOKHURST ST GARDEN GROVE CA 92843-3153	E	0.15 / 775.47	<u>14</u>
	Handler ID Recycler Activity?: CAL000313023 NO			
GABRIEL RASCOL	10021 RUSSELL AVE GARDEN GROVE CA 92843	ENE	0.17 / 880.94	<u>19</u>
	Handler ID Recycler Activity?: CAC003121243 NO			
VN AUTO	13231 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.18 / 944.26	<u>21</u>
	Handler ID Recycler Activity?: CAP000186775 NO			
MARIE CALLENDARS	13252 BROOKHURST STREET GARDEN GROVE CA 92843	ENE	0.19 / 986.51	<u>24</u>
	Handler ID Recycler Activity?: CAC003164178 NO			

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
13252 BROOKHURST ST	13252 BROOKHURST ST GARDEN GROVE CA 92843	ENE	0.19 / 986.51	<u>24</u>
	Handler ID Recycler Activity?: CAC003246861 NO			
BOWERS COMPANIES	13222 BROOKHURST ST GARDEN GROVE CA 92840	NE	0.21 / 1,110.53	<u>27</u>
	Handler ID Recycler Activity?: CAD028230811 NO			
MY FAVORITE CLEANERS	13197 BROOKHURST ST GARDEN GROVE CA 92843-1009	NE	0.22 / 1,140.42	<u>29</u>
	Handler ID Recycler Activity?: CAL000015627 NO			
GARDEN GROVE SHELL	13202 BROOKHURST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	<u>30</u>
	Handler ID Recycler Activity?: CAL000453941 NO			
PACIFIC COAST OIL CO	13169 J BROOKHURST ST GARDEN GROVE CA 92843	NE	0.24 / 1,263.24	<u>31</u>
	Handler ID Recycler Activity?: CAD981428766 NO			
DENTAL OFFICE LIEN HUONG	13161 BROOKHURST ST GARDEN GROVE CA 92843-0000	NE	0.24 / 1,281.70	<u>32</u>
	Handler ID Recycler Activity?: CAL000223611 NO			
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
SUNNYSIDE ELEMENTARY SCHOOL	9972 RUSSELL AVE GARDEN GROVE CA 92844	ESE	0.06 / 309.08	<u>1</u>
	Handler ID Recycler Activity?: CAC003292523 NO			
DYNAMIC AUTO IMAGES	9898 TRASK AVENUE GARDEN GROVE CA 92844	SE	0.10 / 547.63	<u>8</u>
	Handler ID Recycler Activity?: CAL000429991 NO			
YNOT6 II LLC DBA GARDEN GROVE HYUNDAI	9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	<u>8</u>
	Handler ID Recycler Activity?: CAL000428944 NO			
NOARUS TGG INC DBA TOYOTA PLACE	9670 TRASK AVE GARDEN GROVE CA 92844-2801	SW	0.11 / 557.72	<u>9</u>
	Handler ID Recycler Activity?: CAL000330099 NO			
GAMMO CORPORATION	13482 BROOKHURST ST GARDEN GROVE CA 92843-3119	ESE	0.15 / 811.75	<u>16</u>
	Handler ID Recycler Activity?: CAL000338171 NO			
9705 IMPERIAL AVE	9705 IMPERIAL AVE GARDEN GROVE CA 92844	WNW	0.16 / 842.99	<u>18</u>
	Handler ID Recycler Activity?: CAC003239797 NO			
DANG DANG	9672 IMPERIAL AVENUE GARDEN GROVE CA 92844	WNW	0.19 / 984.44	<u>23</u>

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
<i>Handler ID Recycler Activity?: CAC003205204 NO</i>				
9671 IMPERIAL AVE	9671 IMPERIAL AVE GARDEN GROVE CA 92844	WNW	0.19 / 1,015.19	25
<i>Handler ID Recycler Activity?: CAC003108729 NO</i>				
MEAALII LOLOGO	9642 IMPERIAL AVE GARDEN GROVE CA 92844	WNW	0.21 / 1,106.38	26
<i>Handler ID Recycler Activity?: CAC003257686 NO</i>				
MEAALII LOLOGO	9642 IMPERIAL AVE GARDEN GROVE CA 92844	WNW	0.21 / 1,106.38	26
<i>Handler ID Recycler Activity?: CAC003257533 NO</i>				
ANA FIGUEROA	9651 IMPERIAL AVE. GARDEN GROVE CA 92844	WNW	0.21 / 1,133.87	28
<i>Handler ID Recycler Activity?: CAC003077198 NO</i>				

State

C&D DEBRIS RECY - Construction and Demolition Debris Recyclers

A search of the C&D DEBRIS RECY database, dated Jun 20, 2018 has found that there are 3 C&D DEBRIS RECY site(s) within approximately 0.50miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
GARDEN GROVE KIA	10081 GARDEN GROVE BLVD GARDEN GROVE CA 92844	N	0.43 / 2,266.02	39

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
UNION CHRYSLER JEEP DODGE	9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	8
TOYOTA PLACE	9670 TRASK AVE GARDEN GROVE CA 92844	SW	0.11 / 557.72	9

LUST - Leaking Underground Fuel Tank Reports

A search of the LUST database, dated Apr 4, 2025 has found that there are 11 LUST site(s) within approximately 0.50miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
ANDYS UNOCAL	13231 BROOKHURST GARDEN GROVE CA 92844	NE	0.18 / 944.26	21
<i>Global ID Status: T0605900976 </i>				

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
BOWERS CO	13222 BROOKHURST GARDEN GROVE CA 92844	NE	0.21 / 1,110.53	27
	Global ID Status: T0605900855			
JET GAS STATION	13202 BROOKHURST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	30
	Global ID Status: T0605900794			
EJAX WATER SYSTEMS	9911 LARSON GARDEN GROVE CA 92644	N	0.28 / 1,454.05	35
	Global ID Status: T0605901020			
COUNTY WIDE CHRYSLER/JEEP	10080 GARDEN GROVE GARDEN GROVE CA 92842	N	0.33 / 1,768.44	36
	Global ID Status: T0605918872			
TOYOTA OF GARDEN GROVE	10081 GARDEN GROVE GARDEN GROVE CA 92641	N	0.43 / 2,266.02	39
	Global ID Status: T0605901533			
ORIENTAL LEASING	9672 GARDEN GROVE GARDEN GROVE CA 92641	NW	0.46 / 2,453.34	41
	Global ID Status: T0605900714			

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
MOBIL #18-GOE	13521 BROOKHURST GARDEN GROVE CA 92643	ESE	0.15 / 782.79	15
	Global ID Status: T0605901769			
ARCO #629	13482 BROOKHURST GARDEN GROVE CA 92844	ESE	0.15 / 811.75	16
	Global ID Status: T0605901913			
EXXON #7-0833	13502 BROOKHURST GARDEN GROVE CA 92643	ESE	0.16 / 829.33	17
	Global ID Status: T0605970421			
4 DAY TIRE STORE	13961 BROOKHURST GARDEN GROVE CA 92643	SSE	0.47 / 2,478.76	42
	Global ID Status: T0605901280			

UST - Permitted Underground Storage Tank (UST) in GeoTracker

A search of the UST database, dated May 25, 2025 has found that there are 2 UST site(s) within approximately 0.25miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
GARDEN GROVE SHELL	13202 Brookhurst St Garden Grove CA 92843	NE	0.23 / 1,217.53	30
	Facility ID: FA0057500			
	Tank ID No. Tank Status Tank Closure Date: 3 <i>Confirmed/Updated Information</i> , 1 <i>Confirmed/Updated</i>			

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
-------------------------------	----------------	------------------	-------------------------	----------------

Information | , 2 | Confirmed/Updated Information |

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
------------------------	----------------	------------------	-------------------------	----------------

GAMMO CORP	13482 BROOKHURST ST GARDEN GROVE CA 92843	ESE	0.15 / 811.75	16
------------	--	-----	---------------	--------------------

Facility ID: FA0052965

Tank ID No. | Tank Status | Tank Closure Date: 3 | Confirmed/Updated Information | , 2 | Renewal Permit | , 1 |
Renewal Permit | , 4 | Renewal Permit |

UST CLOSURE - Proposed Closure of Underground Storage Tank Cases

A search of the UST CLOSURE database, dated Apr 7, 2025 has found that there are 1 UST CLOSURE site(s) within approximately 0.50miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
-------------------------------	----------------	------------------	-------------------------	----------------

FKA Andy's Unocal	13231 Brookhurst Ave., Garden Grove, CA 92643 CA Claim Case No: Claim No. 2776	NE	0.18 / 944.26	21
-------------------	--	----	---------------	--------------------

HHSS - Historical Hazardous Substance Storage Information Database

A search of the HHSS database, dated Aug 27, 2015 has found that there are 4 HHSS site(s) within approximately 0.25miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
-------------------------------	----------------	------------------	-------------------------	----------------

A SAADAI UNION 76	13231 BROOKHURST ST. GARDEN GROVE CA 92643	NE	0.18 / 944.26	21
-------------------	---	----	---------------	--------------------

JET	13202 BROOKHURST GARDEN GROVE CA 92643	NE	0.23 / 1,217.53	30
-----	---	----	-----------------	--------------------

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
------------------------	----------------	------------------	-------------------------	----------------

LIAQUAT ALI JUMANI	13482 BROOKHURST ST GARDEN GROVE CA 92643	ESE	0.15 / 811.75	16
--------------------	--	-----	---------------	--------------------

EXXON SERVICE STATION	13502 BROOKHURST GARDEN GROVE CA 92640	ESE	0.16 / 829.33	17
-----------------------	---	-----	---------------	--------------------

UST SWEEPS - Statewide Environmental Evaluation and Planning System

A search of the UST SWEEPS database, dated Oct 1, 1994 has found that there are 9 UST SWEEPS site(s) within approximately 0.25 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
-------------------------------	----------------	------------------	-------------------------	----------------

SEXTONS AUTOMOTIVE	10041 TRASK AVE GARDEN GROVE CA	ESE	0.18 / 939.28	20
--------------------	------------------------------------	-----	---------------	--------------------

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
C C Status: A30-000-3140 ACTIVE Tank ID: 000002				
DON THIO	13231 S BROOKHURST ST GARDEN GROVE CA	NE	0.18 / 960.03	22
C C Status: A30-000-13410 ACTIVE Tank ID: 000004, 000002, 000001, 000003				
KARAMAT STATION	13231 S BROOKHURST ST GARDEN GROVE CA	NE	0.18 / 960.03	22
C C Status: A30-000-4349 ACTIVE Tank ID: 000001, 000004, 000003, 000005				
PRONTO MARKETING	13202 BROOKHURST ST GARDEN GROVE CA	NE	0.23 / 1,217.53	30
C C Status: A30-000-4347 ACTIVE Tank ID: 000002, 000003, 000001				
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
QUALITY NISSAN	9666 TRASK AVE GARDEN GROVE CA	SW	0.09 / 476.68	4
C C Status: A30-000-12923 ACTIVE Tank ID: 000007, 000005				
GARDEN GROVE MITSUBISHI	9898 TRASK AVE GARDEN GROVE CA	SE	0.10 / 547.63	8
C C Status: A30-000-6947 ACTIVE Tank ID: 000001, 000002				
MOBIL #18-G03E	13521 BROOKHURST ST GARDEN GROVE CA	ESE	0.15 / 782.79	15
C C Status: A30-000-2129 ACTIVE Tank ID: 000004, 000001, 000003, 000005				
ARCO #629	13482 BROOKHURST ST GARDEN GROVE CA	ESE	0.15 / 811.75	16
C C Status: A30-000-4348 ACTIVE Tank ID: 000002, 000003, 000001, 000004				
EXXON #7-0833	13502 BROOKHURST ST GARDEN GROVE CA	ESE	0.16 / 829.33	17
C C Status: A30-000-2122 ACTIVE Tank ID: 000004, 000003, 000001, 000005				

AST - Aboveground Storage Tanks

A search of the AST database, dated Aug 31, 2009 has found that there are 2 AST site(s) within approximately 0.25miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
	9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	8
	9670 TRASK AVE GARDEN GROVE CA 92844	SW	0.11 / 557.72	9

AST SWRCB - SWRCB Historical Aboveground Storage Tanks

A search of the AST SWRCB database, dated Dec 1, 2007 has found that there are 1 AST SWRCB site(s) within approximately 0.25 miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
NISSAN	9670 TRASK AVE GARDEN GROVE CA 92844-2801	SW	0.11 / 557.72	<u>9</u>

DELISTED TNK - Delisted Storage Tanks

A search of the DELISTED TNK database, dated Jun 1, 2025 has found that there are 10 DELISTED TNK site(s) within approximately 0.25miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
SEXTONS AUTOMOTIVE	10041 TRASK AVE GARDEN GROVE CA 92843	ESE	0.18 / 939.28	<u>20</u>
KARAMAT STATION	13231 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.18 / 944.26	<u>21</u>
BOWERS CO	13222 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.21 / 1,110.53	<u>27</u>
PRONTO MARKETING 312	13202 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	<u>30</u>
ARCO #629	13482 BROOKHURST ST GARDEN GROVE CA 92843	E	0.25 / 1,321.03	<u>33</u>

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
GARDEN GROVE DODGE/SUBARU/HYUNDAI	9666 TRASK AVE GARDEN GROVE CA 92844	SW	0.09 / 476.68	<u>4</u>
GARDEN GROVE MITSUBISHI	9898 TRASK AVE GARDEN GROVE CA 92844	SE	0.10 / 547.63	<u>8</u>
QUALITY NISSAN	9670 TRASK AVE GARDEN GROVE CA 92844	SW	0.11 / 557.72	<u>9</u>
MOBIL #18-G03E	13521 BROOKHURST ST # 18-G03E GARDEN GROVE CA 92843	ESE	0.15 / 782.79	<u>15</u>

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
EXXON #7-0833	13502 BROOKHURST ST # 7-0833 GARDEN GROVE CA 92843	ESE	0.16 / 829.33	17

CERS TANK - California Environmental Reporting System (CERS) Tanks

A search of the CERS TANK database, dated May 28, 2025 has found that there are 4 CERS TANK site(s) within approximately 0.25 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
GARDEN GROVE SHELL	13202 BROOKHURST ST GARDEN GROVE CA 92843 <i>Site ID: 366507</i>	NE	0.23 / 1,217.53	30

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Garden Grove Hyundai	9898 TRASK AVE GARDEN GROVE CA 92844 <i>Site ID: 118782</i>	SE	0.10 / 547.63	8
TOYOTA PLACE	9670 TRASK AVE GARDEN GROVE CA 92844 <i>Site ID: 178742</i>	SW	0.11 / 557.72	9
GAMMO CORP	13482 BROOKHURST ST GARDEN GROVE CA 92843 <i>Site ID: 393660</i>	ESE	0.15 / 811.75	16

HIST TANK - Historical Hazardous Substance Storage Container Information - Facility Summary

A search of the HIST TANK database, dated May 27, 1988 has found that there are 4 HIST TANK site(s) within approximately 0.25 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
A. SAADI UNION 76	13231 BROOKHURST ST. GARDEN GROVE CA	NE	0.18 / 944.26	21
JET	13202 BROOKHURST GARDEN GROVE CA	NE	0.23 / 1,217.53	30
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
LIAQUAT ALI JUMANI	13482 BROOKHURST ST. GARDEN GROVE CA	ESE	0.15 / 811.75	16

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
EXXON SERVICE STATION	13502 BROOKHURST GARDEN GROVE CA	ESE	0.16 / 829.33	17

County

LOP ORANGE - Orange County - LOP Lead Cases List

A search of the LOP ORANGE database, dated May 15, 2023 has found that there are 12 LOP ORANGE site(s) within approximately 0.50miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Andys Unocal	13231 Brookhurst St Garden Grove Ca 92843-1009 CA Case ID: 89UT095 Closed Date: 5/26/2014	NE	0.18 / 944.26	21
Bowers Co	13222 Brookhurst St Garden Grove Ca 92843-1010 CA Case ID: 88UT176 Closed Date: 4/19/2012	NE	0.21 / 1,110.53	27
Jet Gas Station	13202 Brookhurst St Garden Grove Ca 92843-1010 CA Case ID: 88UT135 Closed Date: 4/18/2014	NE	0.23 / 1,217.53	30
Ejax Water Systems	9911 Larson Ave Garden Grove Ca 92844-1657 CA Case ID: 89UT181 Closed Date: 12/14/1989	N	0.28 / 1,453.83	34
County Wide Chrysler/Jeep	10080 Garden Grove Blvd Garden Grove Ca 92844-1694 CA Case ID: 99UT016 Closed Date: 2/12/2003	N	0.37 / 1,959.35	38
Toyota Of Garden Grove	10081 Garden Grove Blvd Garden Grove Ca 92844-1620 CA Case ID: 92UT026 Closed Date: 4/14/1992	N	0.43 / 2,266.02	39
Oriental Leasing	9672 Garden Grove Blvd Garden Grove Ca 92844-1516 CA Case ID: 88UT083 Closed Date: 8/7/2000	NW	0.48 / 2,548.01	43
Oriental Leasing	9672 Garden Grove Blvd Garden Grove Ca 92844-1516 CA Case ID: 88UT077 Closed Date: 1/1/1988	NW	0.48 / 2,548.01	43

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Mobil #18-Goe	13521 Brookhurst St Garden Grove Ca 92643 CA	ESE	0.15 / 782.79	15

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
	Case ID: 94UT037 Closed Date: 3/7/1995			
Arco #629	13482 Brookhurst St Garden Grove Ca 92843-3119 CA	ESE	0.15 / 811.75	16
	Case ID: 95UT062 Closed Date: 11/17/2005			
Exxon #7-0833	13502 Brookhurst St Garden Grove Ca 92643 CA	ESE	0.16 / 829.33	17
	Case ID: 92UT061 Closed Date: 2/7/1996			
Exxon #7-0833	13502 Brookhurst St Garden Grove Ca 92643 CA	ESE	0.16 / 829.33	17
	Case ID: 92UT125 Closed Date: 1/1/1992			

UST ORANGE - Orange County - Underground Storage Tanks Listing

A search of the UST ORANGE database, dated May 15, 2023 has found that there are 4 UST ORANGE site(s) within approximately 0.25miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
M & R STATION	13202 BROOKHURST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	30
	FA No: FA24722			
ULTRAMAR STATION	13202 BROOKHURST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	30
	FA No: FA24722			
Garden Grove Shell	13202 Brookhurst St Garden Grove, Ca 92843-1010 Garden Grove CA FA No: FA0057500	NE	0.23 / 1,217.53	30

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Gammo Corporation	13482 Brookhurst St Garden Grove, Ca 92843-3119 Garden Grove CA FA No: FA0052965	ESE	0.15 / 811.75	16

AST ORANGE - Orange County - Aboveground Petroleum Storage Tank Listing

A search of the AST ORANGE database, dated May 15, 2023 has found that there are 2 AST ORANGE site(s) within approximately 0.25miles of the project property.

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Russell Westbrook Hyundai Of Garden Grove	9898 Trask Ave Garden Grove, Ca 92844-2800 CA Establishment ID: FA0054812	SE	0.10 / 547.63	8
Toyota Place	9670 Trask Ave Garden Grove, Ca 92844-2801 CA Establishment ID: FA0051444	SW	0.11 / 557.72	9

Non Standard

Federal

FED DRYCLEANERS - Drycleaner Facilities

A search of the FED DRYCLEANERS database, dated Jan 6, 2025 has found that there are 1 FED DRYCLEANERS site(s) within approximately 0.25miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
MY FAVORITE CLEANERS	13197 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.22 / 1,140.42	<u>29</u>
FRS Facility ID: 110070442968				

State

DRYCLEANERS - Dry Cleaning Facilities

A search of the DRYCLEANERS database, dated Dec 20, 2021 has found that there are 1 DRYCLEANERS site(s) within approximately 0.25miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
MY FAVORITE CLEANERS	13197 BROOKHURST ST GARDEN GROVE CA	NE	0.22 / 1,140.42	<u>29</u>

INSP COMP ENF - EnviroStor Inspection, Compliance, and Enforcement

A search of the INSP COMP ENF database, dated Nov 23, 2023 has found that there are 1 INSP COMP ENF site(s) within approximately 1.00miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
VETERANS ED'S INC	10372 STANFORD AVENUE #S GARDEN GROVE CA 92840	NE	0.68 / 3,589.02	<u>44</u>

CERS HAZ - California Environmental Reporting System (CERS) Hazardous Waste Sites

A search of the CERS HAZ database, dated May 28, 2025 has found that there are 2 CERS HAZ site(s) within approximately 0.12miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
VUNG TAU AUTO REPAIR	13331 BROOKHURST ST C GARDEN GROVE CA 92843	ENE	0.09 / 494.13	<u>5</u>
QUOC AUTO REPAIR	13331 BROOKHURST ST #A GARDEN GROVE CA 92843	ENE	0.09 / 500.98	<u>6</u>

EMISSIONS - Toxic Pollutant Emissions Facilities

A search of the EMISSIONS database, dated Dec 31, 2021 has found that there are 5 EMISSIONS site(s) within approximately 0.25

miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
MY FAVORITE CLEANERS, SEONG HE	13197 BROOKHURST ST. GARDEN GROVE CA 92640	NE	0.22 / 1,140.42	<u>29</u>
KORMEX MANAGEMENT & MARKETING, INC.	13202 BROOKHURST ST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	<u>30</u>
BR PETROLEUM INC	13202 BROOKHURST GARDEN GROVE CA 92843	NE	0.23 / 1,217.53	<u>30</u>


<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
GAMMO C30P30ATION	13482 BROOKHURST ST GARDEN GROVE CA 92843	ESE	0.15 / 811.75	<u>16</u>
GAMMO CORPORATION	13482 BROOKHURST ST GARDEN GROVE CA 92843	ESE	0.15 / 811.75	<u>16</u>

County

HW ORANGE - Orange County - Hazardous Waste Facilities

A search of the HW ORANGE database, dated May 15, 2023 has found that there are 4 HW ORANGE site(s) within approximately 0.12 miles of the project property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Vung Tau Auto Repair	13331 Brookhurst St Ste C Garden Grove, Ca 92843-7000 Garden Grove CA 92843-7000	ENE	0.12 / 649.42	<u>12</u>
Quoc Auto Repair	13331 Brookhurst St Ste A Garden Grove, Ca 92843-7000 Garden Grove CA 92843-7000	ENE	0.12 / 649.42	<u>12</u>
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction</u>	<u>Distance (mi/ft)</u>	<u>Map Key</u>
Russell Westbrook Hyundai Of Garden Grove	9898 Trask Ave Garden Grove, Ca 92844-2800 Garden Grove CA 92844-2800	SE	0.10 / 547.63	<u>8</u>
Toyota Place	9670 Trask Ave Garden Grove, Ca 92844-2801 Garden Grove CA 92844-2801	SW	0.11 / 557.72	<u>9</u>



Map: 1.0 Mile Radius

Order Number: 25061300823

Address: 9822 Russell Avenue, GARDEN GROVE, CA



Project Property

Buffer Outline

Sites with Higher Elevation

Sites with Same Elevation

Sites with Lower Elevation

Sites with Unknown Elevation

Areas with Higher Elevation

Areas with Same Elevation

Areas with Lower Elevation

Areas with Unknown Elevation

Freeways; Highways

Traffic Circle; Ramp

Major & Minor Arterial

Traffic Circle; Ramp

Local Road

Rail

State

Country

National Wetland


Indian Reserve Land

100 Year Flood Zone

500 Year Flood Zone

FWS Special Designation Areas

National Priorities List (Active, Delisted, Proposed, Institutional Control)




Map: 0.5 Mile Radius

Order Number: 25061300823

Address: 9822 Russell Avenue, GARDEN GROVE, CA





Map: 0.25 Mile Radius

Order Number: 25061300823

Address: 9822 Russell Avenue, GARDEN GROVE, CA



Project Property

Buffer Outline

▲ Sites with Higher Elevation

■ Sites with Same Elevation

▼ Sites with Lower Elevation

○ Sites with Unknown Elevation

Areas with Higher Elevation

Areas with Same Elevation

Areas with Lower Elevation

Areas with Unknown Elevation

Freeways; Highways

Traffic Circle; Ramp

Major & Minor Arterial

Traffic Circle; Ramp

Local Road

Rail

State

Country

National Wetland

Indian Reserve Land

100 Year Flood Zone

500 Year Flood Zone

FWS Special Designation Areas

National Priorities List (Active, Delisted, Proposed, Institutional Control)

117°58'W

117°57'30"W

117°57'W

33°46'30"N


33°46'30"N

33°46'N

33°46'N

33°45'30"N

33°45'30"N



Aerial Year: 2024


Address: 9822 Russell Avenue, GARDEN GROVE, CA

Source: ESRI World Imagery

Order Number: 25061300823



© ERIS Information Inc.



Topographic Map Year: 2022

Address: 9822 Russell Avenue, CA

Quadrangle(s): Newport Beach CA, Anaheim CA

Source: USGS Topographic Map

Order Number: 25061300823



© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 1	ESE	0.06 / 309.08	72.95 / -1	SUNNYSIDE ELEMENTARY SCHOOL 9972 RUSSELL AVE GARDEN GROVE CA 92844	RCRA NON GEN

Handler ID: CAC003292523
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	611110
Seq No:	2	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20240917	NAIC 4:	
Active Site:	----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	D		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20241001				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		SUNNYSIDE ELEMENTARY SCHOOL				
Location Street No:						
Location Street1:		9972 RUSSELL AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		SCOTT MACCARTHY				
Contact Street No:						
Contact Street1:		11852 KNOTT				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92841				
Contact Country:						
Contact Phone And Ext:		714-663-6185				
Contact Fax:						
Contact Email Address:		SMACCARTHY@GGUSD.US				
Contact Title:						
Owner Name:						
Owner Type:						
Owner Seq:						
Operator Name:						
Operator Type:						
Operator Seq:						
Public Notes:						

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20240618
 Handler Name: SUNNYSIDE ELEMENTARY SCHOOL
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Source Type:	Implementer
--------------	-------------

Hazardous Waste Handler Details

Seq No:	2
Receive Date:	20240917
Handler Name:	SUNNYSIDE ELEMENTARY SCHOOL
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	11852 KNOTT
Name:	SCOTT MACCARTHY	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-663-6185	Country:	
Source Type:	Implementer	Zip:	92841
Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	11852 KNOTT
Name:	GGUSD	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-663-6185	Country:	
Source Type:	Implementer	Zip:	92841

Historical Handler Details

Receive Dt:	20240618
Generator Code Description:	Not a Generator, Verified
Handler Name:	SUNNYSIDE ELEMENTARY SCHOOL

<u>2</u>	1 of2	NNE	0.07 / 366.46	73.72 / 0	LARRY LOCKWOOD 13292 VERDE ST GARDEN GROVE CA 92844	RCRA NON GEN
--------------------------	-------	-----	---------------	-----------	---	-----------------

Handler ID:	CAC003099098
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).
-------	--

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Additional Handler Summary Details

Source Type:	I			NAIC 1:	56299
Seq No:	1			NAIC 2:	
Non Notifier:				NAIC 3:	
Receive Date:	20201230			NAIC 4:	
Active Site:	----			State:	CA
Land Type:				Location Latitude:	
In Handler Univ:	N			Location Longitude:	
In A Universe:	N			Loc GIS Primary:	N
Gen Status:	N			Loc GIS Origin:	
Report Cycle:				State District Owner:	
Accessibility:				State District:	
Region:	09				
Fed Waste Gen Owner:		HQ			
State Waste Generator Owner:		CA			
State Waste Generator:		2			
Short Term Generator:		N			
Uni Waste:		N			
Universal Waste Dest Facility:		N			
Federal Universal Waste:		N			
As Federally Regulated Tsdf:		-----			
As Converter Tsdf:		-----			
As State Regulated Tsdf:		-----			
As State Regulated Handler:		---			
Federal Indicator:		---			
Hsm:		N			
Subpart K:		----			
GPRA Permit:		N			
GPRA Renewal:		N			
Permit Renewal Wrkld:		-----			
Permwrk ID:		-----			
Perm Prog:		-----			
Pcwrkld:		-----			
Closwrkld:		-----			
GPRA Ca:		N			
Cawrkld:		N			
Subjca Tsd Discretion:		N			
NCAPS:		N			
EC Indicator:		N			
Ca725 Indicator:		N			
Ca750 Indicator:		N			
Operating Tsdf:		-----			
Full Enforcement:		-----			
Snc:		N			
Unaddressed Snc:		N			
Addressed Snc:		N			
Snc With Comp Sched:		N			
Fa Required:		----			
Hhandler Last Change:		20210226			
Recognized Trader Importer:		N			
Recognized Trader Exporter:		N			
Slab Importer:		N			
Slab Exporter:		N			
Manifest Broker:		N			
Subpart P:		N			
Contact Language:		EN			
Handler Name:		LARRY LOCKWOOD			
Location Street No:					
Location Street1:		13292 VERDE ST			
Location Street2:					
Location City:		GARDEN GROVE			
Location State:		CA			
Location Zip:		92844			
Location County Code:		CA059			
Location County Name:		ORANGE			
Location Country:		US			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Contact Name:	LARRY LOCKWOOD
Contact Street No:	
Contact Street1:	13292 VERDE ST
Contact Street2:	
Contact City:	GARDEN GROVE
Contact State:	CA
Contact Zip:	92844
Contact Country:	
Contact Phone And Ext:	714-290-9584
Contact Fax:	
Contact Email Address:	SCHEDULING@PWSEI.COM
Contact Title:	
Owner Name:	LARRY LOCKWOOD
Owner Type:	O
Owner Seq:	1
Operator Name:	LARRY LOCKWOOD
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20201230
Handler Name:	LARRY LOCKWOOD
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	13292 VERDE ST
Name:	LARRY LOCKWOOD	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-290-9584	Country:	
Source Type:	Implementer	Zip:	92844
Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	13292 VERDE ST
Name:	LARRY LOCKWOOD	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-290-9584	Country:	
Source Type:	Implementer	Zip:	92844

2	2 of 2	NNE	0.07 / 366.46	73.72 / 0	LARRY LOCKWOOD 13292 VERDE ST GARDEN GROVE CA 92844	RCRA NON GEN
-------------------	--------	-----	------------------	--------------	---	-----------------

Handler ID:	CAC003114378
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Handler Summary

Importer:	No				Used Oil Transpor:	No
Mixed Waste Gen:	No				Used Oil Trans Fac:	No
Transporter:	No				Used Oil Processor:	No
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:	No					
Used Oil Spec Marketer:	No					

Additional Handler Summary Details

Source Type:	I				NAIC 1:	56299
Seq No:	1				NAIC 2:	
Non Notifier:					NAIC 3:	
Receive Date:	20210412				NAIC 4:	
Active Site:	----				State:	CA
Land Type:					Location Latitude:	
In Handler Univ:	N				Location Longitude:	
In A Universe:	N				Loc GIS Primary:	N
Gen Status:	N				Loc GIS Origin:	
Report Cycle:					State District Owner:	
Accessibility:					State District:	
Region:	09					
Fed Waste Gen Owner:	HQ					
State Waste Generator Owner:	CA					
State Waste Generator:	2					
Short Term Generator:	N					
Uni Waste:	N					
Universal Waste Dest Facility:	N					
Federal Universal Waste:	N					
As Federally Regulated Tsdf:	-----					
As Converter Tsdf:	-----					
As State Regulated Tsdf:	-----					
As State Regulated Handler:	---					
Federal Indicator:	---					
Hsm:	N					
Subpart K:	----					
GPRA Permit:	N					
GPRA Renewal:	N					
Permit Renewal Wrkld:	-----					
Permwrk ID:	-----					
Perm Prog:	-----					
Pcwrkld:	-----					
Closwrkld:	-----					
GPRA Ca:	N					
Cawrkld:	N					
Subjca Tsd Discretion:	N					
NCAPS:	N					
EC Indicator:	N					
Ca725 Indicator:	N					
Ca750 Indicator:	N					
Operating Tsdf:	-----					
Full Enforcement:	-----					
Snc:	N					
Unaddressed Snc:	N					
Addressed Snc:	N					
Snc With Comp Sched:	N					
Fa Required:	----					
Hhandler Last Change:	20210415					
Recognized Trader Importer:	N					
Recognized Trader Exporter:	N					
Slab Importer:	N					
Slab Exporter:	N					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		LARRY LOCKWOOD				
Location Street No:						
Location Street1:		13292 VERDE ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		LARRY LOCKWOOD				
Contact Street No:						
Contact Street1:		13292 VERDE ST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:						
Contact Phone And Ext:		714-290-9584				
Contact Fax:						
Contact Email Address:		SCHEDULING@PWSEI.COM				
Contact Title:						
Owner Name:		LARRY LOCKWOOD				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		LARRY LOCKWOOD				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20210412
Handler Name:	LARRY LOCKWOOD
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	13292 VERDE ST
Name:	LARRY LOCKWOOD	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-290-9584	Country:	
Source Type:	Implementer	Zip:	92844
Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	13292 VERDE ST
Name:	LARRY LOCKWOOD	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-290-9584	Country:	
Source Type:	Implementer	Zip:	92844

<u>3</u>	1 of 1	NNE	0.08 / 431.94	73.59 / 0	13282 VERDE ST, #3 13282 VERDE ST, #3 GARDEN GROVE CA 92844	RCRA NON GEN
----------	--------	-----	------------------	--------------	---	-----------------

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Handler ID:	CAC003232900
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20230517	NAIC 4:	
Active Site:	----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20241212				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		13282 VERDE ST, #3				
Location Street No:						
Location Street1:		13282 VERDE ST, #3				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		ROBERT KELLEY				
Contact Street No:						
Contact Street1:		13282 VERDE ST, #3				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:						
Contact Phone And Ext:		205-678-0360				
Contact Fax:						
Contact Email Address:		ELIZABETHS@PWSEI.COM				
Contact Title:						
Owner Name:		ROBERT KELLEY				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		ROBERT KELLEY				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20230517
Handler Name: 13282 VERDE ST, #3
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	13282 VERDE ST, #3
Name:	ROBERT KELLEY	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	205-678-0360	Country:	
Source Type:	Implementer	Zip:	92844

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Owner/Operator Ind: Current Operator Type: Other Name: ROBERT KELLEY Dt Became Current: Dt Ended Current: Phone: 205-678-0360 Source Type: Implementer						
Street No: Street1: 13282 VERDE ST, #3 Street2: City: GARDEN GROVE State: CA Country: Zip: 92844						

<u>4</u>	1 of 2	SW	0.09 / 476.68	70.46 / -3	GARDEN GROVE DODGE/SUBARU/HYUNDAI 9666 TRASK AVE GARDEN GROVE CA 92844	DELISTED TNK
----------	--------	----	---------------	------------	---	-----------------

Delisted Storage Tanks

Facility ID:	8659	County:	Orange
Latitude:	33.7679355	Original Source:	UST
Longitude:	-117.959704	Record Date:	30-JAN-2017
Permitting Agency:	ORANGE COUNTY		

<u>4</u>	2 of 2	SW	0.09 / 476.68	70.46 / -3	QUALITY NISSAN 9666 TRASK AVE GARDEN GROVE CA	UST SWEEPS
----------	--------	----	---------------	------------	---	------------

C C:	A30-000-12923	D Filename:	SITE12A
BOE:		Page No:	133
Comp:	12923	County:	ORANGE
Status:	ACTIVE	State :	CA
No of Tanks:	2	Zip:	92644
Jurisdict:	ORANGE COUNTY	Latitude:	33.766639
Agency:	ENVIRONMENTAL HEALTH	Longitude:	-117.961096
Phone:		Georesult:	S5HPNTSC-A

Tank Details

Tank ID:	000007	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-012923-000007	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	REG UNLEADED
Capac:	6000	ONA:	
Tank Use:	M.V. FUEL	D File Name:	TANK12A

Tank Details

Tank ID:	000005	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-012923-000005	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	
Capac:	1000	ONA:	
Tank Use:	PETROLEUM	D File Name:	TANK12A

<u>5</u>	1 of 1	ENE	0.09 / 494.13	75.55 / 2	VUNG TAU AUTO REPAIR 13331 BROOKHURST ST C GARDEN GROVE CA 92843	CERS HAZ
----------	--------	-----	---------------	-----------	--	----------

Site ID:	629686
Latitude:	33.768990

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Longitude: -117.955150

Regulated Programs

EI ID:	10567468	EI Description:	Hazardous Waste Generator
EI ID:	10567468	EI Description:	Chemical Storage Facilities

Violations

Violation Date:	09/12/2019	Violation Source:	CERS
Violation Program:	HMRRP	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507		
Violation Notes:			

Returned to compliance on 09/30/2019. OBSERVATION: The business failed to establish and implement a business plan when handling hazardous materials at or above the reportable threshold quantities. CORRECTIVE ACTION: Establish and implement a business plan for the facility. Complete the required Hazardous Materials Business Plan via the California Electronic Reporting System <http://cers.calepa.ca.gov> within 30 days.

Violation Description:

Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date:	03/07/2016	Violation Source:	CERS
Violation Program:	HW	Violation Division:	Orange County Environmental Health
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)		
Violation Notes:			

Returned to compliance on 02/01/2017. Used oil tank had faded labels and no longer contained the required information. Violation was noted for improper labeling, and the violation was corrected on-site.

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date:	03/07/2016	Violation Source:	CERS
Violation Program:	HW	Violation Division:	Orange County Environmental Health
Citation:	22 CCR 15 66265.173 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.173		
Violation Notes:			

Returned to compliance on 02/01/2017. Used oil tank's lid was not closed properly. The violation was corrected during the inspection.

Violation Description:

Failure to properly close hazardous waste containers when not in active use.

Violations

Violation Date:	04/29/2024	Violation Source:	CERS
Violation Program:	HMRRP	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2		
Violation Notes:			

Returned to compliance on 04/29/2024. Business failed to certify HMBP by March 1, 2024.

Violation Description:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 10/08/2014
Violation Program: HW
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Notes:

Returned to compliance on 12/07/2014. You must obtain an EPA ID # to legally dispose of hazardous waste. Notify this Agency when you have obtained and EPA ID# Contact DTSC to obtain and EPA ID #

Violation Description:

Failure to obtain and/or maintain an Active EPA ID.

Violations

Violation Date: 03/01/2023
Violation Program: HW
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Notes:

Returned to compliance on 03/03/2023. The operator did not have hazardous waste manifests available for the disposal of the following hazardous waste observed onsite: - Used oil metal filters - 55-gallon drum

Violation Description:

Failure to keep a copy of each properly signed manifest for at least three years from the date the waste was accepted by the initial transporter. The manifest signed at the time the waste was accepted for transport shall be kept until receiving a signed copy from the designated facility which received the waste.

Evaluations

Eval Date: 03/01/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site to conduct a routine hazardous materials inspection. Consent to enter, inspect, and take photos was given by Van Vong, Owner. The following disclosable materials were observed onsite: - Used oil - New oil CERS submittal was completed onsite. Documented employee training was verified. On an ongoing basis, electronically review and submit/certify the Hazardous Materials Business Plan on the CERS website by March 1st of every year. Emailed a copy of this report to wongisking95@gmail.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/01/2023
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Onsite for a routine hazardous waste inspection. Consent to enter and inspect was granted by Van Vong, Owner. The facility generates the following automotive wastes: - Used oil - Used oil filters (metal/paper) - Waste coolant Hazardous waste label requirements were discussed on site. On an ongoing basis, labels are required to have the following information: 1) the words "Hazardous Waste"; 2) name and address of generator; 3) hazardous properties; 4) physical state; 5) composition (contents); 6) accumulation start date. Observed facility, hazardous waste storage area, perimeter, and dumpster area. Hazardous waste containers were stored closed. No indication of hazardous waste spillage, runoff, or illegal disposal was observed. Emergency response plan in onsite. Employees are reported to be trained. Facility has 1 employee. Emailed a copy of this report to

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

wnguyen630@gmail.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/30/2019
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

INSPECTOR COMMENT: On-site for a follow-up hazardous materials business plan inspection. Assisted the owner with document submission via California Environmental Reporting System. Facility has successfully submitted a hazardous materials business plan with all the required documents via the California Environmental Reporting System. The following violation has been corrected: I208- Established/implemented a business plan when handling hazardous materials in reportable quantities Facility does not have any other open hazardous materials business plan violation at this time.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/07/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

3/7/2016- Vung Tau Auto Repair On site to conduct a routine hazardous material and business plan inspection. The site had moved from 10151 Garden Grove Blvd. Ste J to 13331 Brookhurst Street. The business is still operating as an Auto repair shop. Consent to enter, inspect and take pictures was given by Van Vong at 1:05 pm. Walked the site with Mr. Vong and observed the hazardous material storage areas throughout the auto body shop and the following materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: - Oxygen, (2X145 CF), total oxygen = 290 CF - Acetylene (2X150 CF), total acetylene = 300 CF - Engine Oil (27 boxes of 12X1 quart), total oil = 81 gallons - Used Oil = 1X 200 gallon poly tote - Used Oil filters = 10 items (1X55 gallon drum) As the materials stored on site exceed 55 gallons in liquid and 200 cubic feet of gas, the owner was asked to complete and submit a hazardous material business emergency plan within [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/03/2024
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

The purpose of this off-site reinspection is to follow up on a violation cited on a previous inspection report. The Hazardous Materials Business Plan (HMBP) was submitted in CERS on 4/27/24. Violation 1010008 has been corrected. No outstanding violations remain. A copy of this report will be emailed to wongisking95@gmail.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/29/2024
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

According to the CERS database, your business remains out of compliance with the annual certification requirement and a violation is being cited. Businesses are required to annually review and certify that their information in the California Electronic Reporting System (CERS) is complete, accurate and in compliance by March 1st. Your business was notified via email on March 27, 2024 that your facility was out of compliance with this requirement. Please note the following important details: 1) Complete submittal includes the HazMat Inventory AND the Emergency Plan / Training sections. Both sections must be submitted. 2) If your business qualifies (see below) you may submit 2024 via the Certify option available on CERS. You must be logged in to use. HMBP Certify: A business may use the Certify option button located on their forms page if: 1) A previous, complete submittal was made the prior year, and 2) The business is not subject to the Federal EPCRA reporting requirements, and 3) The; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Eval Date:		10/08/2014				
Violations Found:		Yes				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HW				
Eval Source:		CERS				
Eval Notes:						
VUNG TAU AUTO REPAIR MUFFLER AND TIRE 13331 Brookhurst #c Garden Grove CA 92843 714-534-4800 owner is VAN VONG CAL000071804 Facility has one 250 gallon tote for waste oil, one 55 gallon drum of waste coolant, and one 55 gallon drum of used oil filters You must obtain an EPA ID # to legally dispose of hazardous waste. Notify this Agency when you have obtained and EPA ID# Drums are labeled and stored closed; Note: data in [EVAL Notes] field for some records is truncated from the source.						
Eval Date:		10/16/2013				
Violations Found:		No				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HW				
Eval Source:		CERS				
Eval Notes:						
On-site for routine inspection. Consent to enter, inspect, and take photographs granted by Jack Nguyen this date. Hazardous Waste receipts from Action Waste Oil made available and reviewed. HW containers properly labeled and stored closed. Accumulation start dates 8-16-13 are on the labels Emergency numbers posted at site. Inspected trash/dumpster and it does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted.; Note: data in [EVAL Notes] field for some records is truncated from the source.						
Eval Date:		10/07/2015				
Violations Found:		No				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HMRP				
Eval Source:		CERS				
Eval Notes:						
out of business no hazm mat at site from this business .; Note: data in [EVAL Notes] field for some records is truncated from the source.						
Eval Date:		03/07/2016				
Violations Found:		Yes				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HW				
Eval Source:		CERS				
Eval Notes:						
3/7/2016- Vung Tau Auto Repair On site to conduct a routine hazardous waste inspection. Consent to enter, inspect and take pictures was given by Van Vong at 1:05 pm. The hazardous waste containers found here: a. Used Oil = 1X 200 gallon poly tote b. Used Oil filters = 10 items (1X55 gallon drum) Manifests were available and were checked. The generator was using their old EPA ID (CAL00071804) from 10151 Garden Grove Blvd. Informed Mr. Vong to utilize the new EPA ID #: CAL000401291 moving forward to dispose of hazardous waste. Dumpster was covered for rain, but no hazardous waste was observed. Per Mr. Vong quarterly trainings are being conducted to educate employee on proper disposal techniques. Walked the perimeter of the site, and there were no hazardous waste spills or discharges observed during this inspection. Minor Violations: a. Used oil tank had faded labels and no longer contained the required information. Violation was noted for improper labeling, [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.						
Eval Date:		10/08/2014				
Violations Found:		No				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HW				
Eval Source:		CERS				
Eval Notes:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Facility is out of business before June 2014 New Business at site is VUNG TAU AUTO REPAIR MUFFLER AND TIRE 13331 Brookhurst #c Garden Grove CA 92843 714-534-4800 owner is VAN VONG CAL000071804 Facility has one 250 gallon tote for waste oil, one 55 gallon drum of waste coolant, and one 55 gallon drum of used oil filters One manifest for waste oil hauled by Action Waste Oil at site Drums are labeled and stored closed; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/12/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

INSPECTOR COMMENT: On site for a routine hazardous waste inspection. Walked throughout the facility. Observed hazardous waste storage areas. Containers were closed and properly labeled. Employees are reported to be trained. Manifests were available for review. Facility generates the following waste streams: - Waste Coolant - Waste Oil - Drained Used Oil Filters Emergency plan is available on site. No hazardous waste or universal waste observed in the dumpster/enclosure area. No hazardous waste violations were observed this date.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/12/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

INSPECTOR COMMENT: On-site for a hazardous materials business plan inspection. The following materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: - Waste Oil (250 gallons) REQUIREMENT FOR ELECTRONIC SUBMITTAL OF HMBEP DOCUMENTS: This report serves as a notice that the facility must electronically submit a Hazardous Materials Business Emergency Plan (HMBEP), which includes the following documents within 30 days of this report: - Business Activities - Owner/Operator Information - Hazardous Materials Inventory - Site Map - Emergency Response Plan - Employee Training Plan Facility must conduct and document annual training for employees as specified in the employee training plan. The facility is responsible for identifying all hazardous materials, to include hazardous wastes, which are above disclosure thresholds of 55 gallons for a liquid, 500 pounds for a solid, and 200 cubic feet for a compressed If [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/22/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERS ID- reissue 10567468; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: CUPA District
Entity Name: Orange County Env Health
Entity Title:
Address: 1241 East Dyer Road Suite 120
City: Santa Ana
State: CA
Country:
Zip Code: 92705-5611
Phone: (714) 433-6406

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 13331 Brookhurst St Ste. C

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
City: State: Country: Zip Code: Phone:		Garden Grove CA 92843				
Affil Type Desc: Entity Name: Entity Title: Address: City: State: Country: Zip Code: Phone:		Environmental Contact Van Vong 13331 Brookhurst St Ste. C Garden Grove CA 92843				
Affil Type Desc: Entity Name: Entity Title: Address: City: State: Country: Zip Code: Phone:		Document Preparer van vong				
Affil Type Desc: Entity Name: Entity Title: Address: City: State: Country: Zip Code: Phone:		Identification Signer van vong				
Affil Type Desc: Entity Name: Entity Title: Address: City: State: Country: Zip Code: Phone:		Legal Owner VAN CA VONG 13331 Brookhurst St Ste. C Garden Grove CA United States 92843 (714) 791-3779				
Affil Type Desc: Entity Name: Entity Title: Address: City: State: Country: Zip Code: Phone:		Operator Van Vong (714) 791-3779				
Affil Type Desc: Entity Name: Entity Title: Address: City: State: Country: Zip Code: Phone:		Parent Corporation VUNG TAU AUTO REPAIR				
<u>6</u>	1 of 1	ENE	0.09 / 500.98	75.55 / 2	QUOC AUTO REPAIR 13331 BROOKHURST ST #A	CERS HAZ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

GARDEN GROVE CA 92843

Site ID: 437384
Latitude: 33.768990
Longitude: -117.955150

Regulated Programs

EI ID:	10567474	EI Description:	Hazardous Waste Generator
EI ID:	10567474	EI Description:	Chemical Storage Facilities

Violations

Violation Date:	07/25/2014	Violation Source:	CERS
Violation Program:	HMRRP	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)		
Violation Notes:			

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violations

Violation Date:	10/15/2014	Violation Source:	CERS
Violation Program:	HW	Violation Division:	Orange County Environmental Health
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)		
Violation Notes:			

Returned to compliance on 10/15/2014. The waste oil drum label did not have the correct beginning date of accumulation written on it. The date was added at my request and the violation was abated.

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date:	12/04/2019	Violation Source:	CERS
Violation Program:	HMRRP	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507		
Violation Notes:			

Returned to compliance on 12/04/2019. OBSERVATION: Facility is storing hazardous materials over reportable quantities on site and has not electronically submitted a Hazardous Materials Business Emergency Plan (HMBEP). CORRECTIVE ACTION: Business has submitted their HMBEP to CERS during the inspection. No further action required.

Violation Description:

Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date:	12/04/2019	Violation Source:	CERS
Violation Program:	HW	Violation Division:	Orange County Environmental Health
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)		
Violation Notes:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Returned to compliance on 12/04/2019. OBSERVATION: The following hazardous waste drums were observed in the shop area without a hazardous waste label: - (3) 55 gallon drums of Used Oil - One 55 gallon drum of Metal Used Oil Filters - One 55 gallon drum of Paper Used Oil Filters - One 55 gallon drum of Waste Antifreeze CORRECTIVE ACTION: Hazardous waste drums were labeled during the inspection. No further action required.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Evaluations

Eval Date: 07/25/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CHEMICAL INVENTORY IS INCOMPLETE.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/08/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Your HMBEP has been declined, please revise and resubmit within 30 days. Your EPA ID# is inactive, please reactivate your number. For your chemical "oil filters" if you only have one drum of filters, which weigh about 200 pounds when full, you are under threshold quantities for a solid, which is 500 pounds. Please remove this chemical entirely from your submittal. For your site map please add the location of the evacuation staging area, nearby storm drains and sewers, and emergency response equipment. If you have any questions please contact me at anesbit@ochca.com or 714-640-4249. Thank you; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/01/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Onsite to conduct a routine hazardous materials inspection. Consent to enter and inspect was granted by Victor Nguyen, Owner. Observed the following disclosable materials: - Used oil Documented employee training was verified. On an ongoing basis, electronically review and submit/certify the Hazardous Materials Business Plan on the CERS website by March 1st of every year. Emailed a copy of this report to wnguyen630@gmail.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/12/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 12/04/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Eval Division:		Orange County Environmental Health				
Eval Program:		HW				
Eval Source:		CERS				
Eval Notes:		On site for a routine hazardous waste inspection. Consent to inspect and take any necessary photos was given by Victor Nguyen, Owner. The Owner's son-in-law, Cory Freitas was also present during the inspection. Walked throughout the facility. Observed hazardous waste storage areas. Manifests were available and reviewed. Emergency plan is posted in the shop. No hazardous waste or universal waste observed in the dumpster/enclosure area.; Note: data in [EVAL Notes] field for some records is truncated from the source.				
Eval Date:		12/04/2019				
Violations Found:		Yes				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HMRRP				
Eval Source:		CERS				
Eval Notes:		On site for routine hazardous materials and business emergency plan inspection. The inspection was conducted with Victor Nguyen, Owner. The Owner's son-in-law, Corey Freitas, was also present for the inspection. Observed the facility and inspected hazardous materials storage. The following materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: - 165 gallons of Waste Motor Oil The facility is responsible for identifying all hazardous materials, to include hazardous wastes, which are above disclosure thresholds of 55 gallons for liquids, 500 pounds for solids, & 200 cubic feet for gases. If there is a change in the type or amount of chemicals that are maintained on site, please submit revised documents (electronically) within 30 days of the change. Hazardous Materials documents can be submitted via the California Environmental Reporting System (CERS) located at http://cers.calepa.ca.gov/ ; Note: data in [EVAL Notes] field for some records is truncated from the source.				
Eval Date:		04/12/2016				
Violations Found:		No				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HMRRP				
Eval Source:		CERS				
Eval Notes:		On site for routine hazardous materials and business emergency plan inspection. Consent to enter and inspect was given by Victor Nguyen, owner. Observed the facility and inspected hazardous materials storage. The following materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: -Waste oil, 3 x 55 gallon drums. -Waste antifreeze, 1 x 55 gallon drums. Business emergency plan was available. Mr. Nguyen is the only employee at the facility and is exempt from the training requirements. The facility is responsible for identifying all hazardous materials, to include hazardous wastes, which are above disclosure thresholds. If there is a change in the type or amount of chemicals that are maintained on site, please submit revised documents (electronically) within 30 days of the change.; Note: data in [EVAL Notes] field for some records is truncated from the source.				
Eval Date:		12/21/2017				
Violations Found:		No				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HW				
Eval Source:		CERS				
Eval Notes:		Facility has three 55 gallon drums for waste oil, one drum filters, and one drum for waste coolant. All waste is hauled by Action Waste Oil. EPA ID# CAL00-0330210 verified active.; Note: data in [EVAL Notes] field for some records is truncated from the source.				
Eval Date:		10/15/2014				
Violations Found:		Yes				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HW				
Eval Source:		CERS				
Eval Notes:		Mark Sutphin on site to conduct a routine hazardous waste inspection. Consent to enter ,inspect and take photographs granted by the owner Mr. Victor				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Nguyen. The facility generates waste oil , drained used oil filters and coolant waste. Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Emergency Response Informational Sticker was available for review. The beginning date of accumulation was added to the waste oil storage tote. Hazardous waste containers must be properly labeled and covered . Each container and portable tank holding hazardous waste must be marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. The Accumulation start date Reviewed manifests, [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/01/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Onsite for a routine hazardous waste inspection. Consent to enter and inspect was granted by Victor Nguyen, Owner. The facility generates the following automotive wastes: - Used oil - Used oil filters (metal/paper) - Waste coolant Hazardous waste label requirements were discussed on site. On an ongoing basis, labels are required to have the following information: 1) the words "Hazardous Waste"; 2) name and address of generator; 3) hazardous properties; 4) physical state; 5) composition (contents); 6) accumulation start date. Observed facility, hazardous waste storage area, perimeter, and dumpster area. Hazardous waste containers were stored closed. No indication of hazardous waste spillage, runoff, or illegal disposal was observed. Emergency response plan in onsite. Employees are reported to be trained. Manifests were available for review. Facility has 1 employee. Emailed a copy of this report to wnguyen630@gmail.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Identification Signer
Entity Name: Victor Nguyen
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Victor Nguyen
Entity Title:
Address: 13331 Brookhurst st #A
City: Garden Grove
State: CA
Country: United States
Zip Code: 92843
Phone: (714) 530-5138

Affil Type Desc: Environmental Contact
Entity Name: Wendy Freitas
Entity Title:
Address: 13331 Brookhurst st #A
City: Garden Grove
State: CA
Country:
Zip Code: 92843
Phone:

Affil Type Desc: Document Preparer
Entity Name: Victor Nguyen
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Affil Type Desc:		Facility Mailing Address				
Entity Name:		Mailing Address				
Entity Title:						
Address:		13331 Brookhurst st #A				
City:		Garden Grove				
State:		CA				
Country:						
Zip Code:		92843				
Phone:						
Affil Type Desc:		CUPA District				
Entity Name:		Orange County Env Health				
Entity Title:						
Address:		1241 East Dyer RoadSuite 120				
City:		Santa Ana				
State:		CA				
Country:						
Zip Code:		92705-5611				
Phone:		(714) 433-6406				
Affil Type Desc:		Parent Corporation				
Entity Name:		QUOC AUTO REPAIR				
Entity Title:						
Address:						
City:						
State:						
Country:						
Zip Code:						
Phone:						
Affil Type Desc:		Operator				
Entity Name:		Victor Nguyen				
Entity Title:						
Address:						
City:						
State:						
Country:						
Zip Code:						
Phone:		(714) 343-3727				

<u>7</u>	1 of 1	NNW	0.10 / 531.25	73.85 / 0	KHOI VU 9791 IMPERIAL AVE GARDEN GROVE CA 92844-2413	RCRA NON GEN
--------------------------	--------	-----	------------------	--------------	--	-----------------

Handler ID:	CAC003060207
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).
--------------	--

Handler Summary

Importer:	No	Used Oil Transport:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Used Oil Spec Marketer:		No				
<u>Additional Handler Summary Details</u>						
Source Type:	I			NAIC 1:	56299	
Seq No:	1			NAIC 2:		
Non Notifier:				NAIC 3:		
Receive Date:	20200316			NAIC 4:		
Active Site:	----			State:	CA	
Land Type:				Location Latitude:		
In Handler Univ:	N			Location Longitude:		
In A Universe:	N			Loc GIS Primary:	N	
Gen Status:	N			Loc GIS Origin:		
Report Cycle:				State District Owner:		
Accessibility:				State District:		
Region:	09					
Fed Waste Gen Owner:	HQ					
State Waste Generator Owner:	CA					
State Waste Generator:	2					
Short Term Generator:	N					
Uni Waste:	N					
Universal Waste Dest Facility:	N					
Federal Universal Waste:	N					
As Federally Regulated Tsdf:	-----					
As Converter Tsdf:	-----					
As State Regulated Tsdf:	-----					
As State Regulated Handler:	---					
Federal Indicator:	---					
Hsm:	N					
Subpart K:	----					
GPRA Permit:	N					
GPRA Renewal:	N					
Permit Renewal Wrkld:	-----					
Permwrk ID:	-----					
Perm Prog:	-----					
Pcwrkld:	-----					
Closwrkld:	-----					
GPRA Ca:	N					
Cawrkld:	N					
Subjca Tsd Discretion:	N					
NCAPS:	N					
EC Indicator:	N					
Ca725 Indicator:	N					
Ca750 Indicator:	N					
Operating Tsdf:	-----					
Full Enforcement:	-----					
Snc:	N					
Unaddressed Snc:	N					
Addressed Snc:	N					
Snc With Comp Sched:	N					
Fa Required:	-----					
Hhandler Last Change:	20200320					
Recognized Trader Importer:	N					
Recognized Trader Exporter:	N					
Slab Importer:	N					
Slab Exporter:	N					
Manifest Broker:	N					
Subpart P:	N					
Contact Language:	EN					
Handler Name:	KHOI VU					
Location Street No:						
Location Street1:	9791 IMPERIAL AVE					
Location Street2:						
Location City:	GARDEN GROVE					
Location State:	CA					
Location Zip:	92844-2413					
Location County Code:	CA059					
Location County Name:	ORANGE					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Location Country:	US
Contact Name:	KHOI VU
Contact Street No:	
Contact Street1:	9791 IMPERIAL AVE
Contact Street2:	
Contact City:	GARDEN GROVE
Contact State:	CA
Contact Zip:	92844-2413
Contact Country:	
Contact Phone And Ext:	909-364-1904
Contact Fax:	
Contact Email Address:	NANCYRUIZ@ALLIANCE-ENVIRO.COM
Contact Title:	
Owner Name:	KHOI VU
Owner Type:	O
Owner Seq:	1
Operator Name:	KHOI VU
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20200316
Handler Name:	KHOI VU
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9791 IMPERIAL AVE
Name:	KHOI VU	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	909-364-1904	Country:	
Source Type:	Implementer	Zip:	92844-2413

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	9791 IMPERIAL AVE
Name:	KHOI VU	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	909-364-1904	Country:	
Source Type:	Implementer	Zip:	92844-2413

8	1 of10	SE	0.10 / 547.63	72.11 / -2	UNION DODGE 9898 TRASK AVE GARDEN GROVE CA 92844	RCRA SQG
-------------------	--------	----	------------------	---------------	--	----------

Handler ID:	CAD982313199
Generator Status:	SQG
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Handler Summary

Importer:	No				Used Oil Transpor:	No
Mixed Waste Gen:	No				Used Oil Trans Fac:	No
Transporter:	No				Used Oil Processor:	No
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Additional Handler Summary Details

Source Type:	N				NAIC 1:	
Seq No:	1				NAIC 2:	
Non Notifier:					NAIC 3:	
Receive Date:	19970714				NAIC 4:	
Active Site:	H----				State:	CA
Land Type:	P				Location Latitude:	33.766389
In Handler Univ:	Y				Location Longitude:	-117.956457
In A Universe:	Y				Loc GIS Primary:	N
Gen Status:	SQG				Loc GIS Origin:	AG
Report Cycle:					State District Owner:	CA
Accessibility:					State District:	4
Region:	09					
Fed Waste Gen Owner:		HQ				
State Waste Generator Owner:						
State Waste Generator:						
Short Term Generator:		N				
Uni Waste:		N				
Universal Waste Dest Facility:		N				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20020627				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		UNION DODGE				
Location Street No:						
Location Street1:		9898 TRASK AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		TED OKADA				
Contact Street No:						
Contact Street1:		9898 TRASK AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:		US				
Contact Phone And Ext:		714-539-5757				
Contact Fax:						
Contact Email Address:						
Contact Title:						
Owner Name:		CHARLES LEE				
Owner Type:		P				
Owner Seq:		3				
Operator Name:		NOT REQUIRED				
Operator Type:		P				
Operator Seq:		4				
Public Notes:						
<u>Hazardous Waste Handler Details</u>						
Seq No:		1				
Receive Date:		19970714				
Handler Name:		UNION DODGE				
Fed Waste Generator:		2				
Generator Code Description:		Small Quantity Generator				
Source Type:		Notification				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:	Current Owner				Street No:	
Type:	Private				Street1:	9898 TRASK AVE
Name:	CHARLES LEE				Street2:	
Dt Became Current:					City:	GARDEN GROVE
Dt Ended Current:					State:	CA
Phone:	714-539-5757				Country:	
Source Type:	Notification				Zip:	92844
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Private				Street1:	NOT REQUIRED
Name:	NOT REQUIRED				Street2:	
Dt Became Current:					City:	NOT REQUIRED
Dt Ended Current:					State:	ME
Phone:	415-555-1212				Country:	
Source Type:	Notification				Zip:	99999
<hr/>						
8	2 of 10	SE	0.10 / 547.63	72.11 / -2	GARDEN GROVE MITSUBISHI 9898 TRASK AVE GARDEN GROVE CA 92844	DELISTED TNK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>Delisted Storage Tanks</u>						
Facility ID:	6947				County:	Orange
Latitude:	33.767813				Original Source:	UST
Longitude:	-117.954121				Record Date:	30-JAN-2017
Permitting Agency:	ORANGE COUNTY					
8	3 of 10	SE	0.10 / 547.63	72.11 / -2	Russell Westbrook Hyundai Of Garden Grove 9898 Trask Ave Garden Grove, Ca 92844-2800 CA	AST ORANGE
Establishment ID:	FA0054812					
8	4 of 10	SE	0.10 / 547.63	72.11 / -2	9898 TRASK AVE GARDEN GROVE CA 92844	AST
Total Capacity(Gal):	1,320				Owner Name:	UNION DODGE
CUPA:	Orange				County:	Orange
8	5 of 10	SE	0.10 / 547.63	72.11 / -2	Russell Westbrook Hyundai Of Garden Grove 9898 Trask Ave Garden Grove, Ca 92844-2800 Garden Grove CA 92844-2800	HW ORANGE
Establishment ID:	FA0054812					
8	6 of 10	SE	0.10 / 547.63	72.11 / -2	Garden Grove Hyundai 9898 TRASK AVE GARDEN GROVE CA 92844	CERS TANK
Site ID:	118782					
Latitude:	33.766479					
Longitude:	-117.956551					
<u>Regulated Programs</u>						
EI ID:	10489162					
EI Description:	Aboveground Petroleum Storage					
<u>Violations</u>						
Violation Date:	03/23/2016				Violation Source:	CERS
Violation Program:	HW				Violation Division:	Orange County Environmental Health
Citation:	22 CCR 15 66265.173 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.173					
Violation Notes:						
Returned to compliance on 03/23/2016. Used oil filter did not have a cover. A cover was located by Mr. Atchison and the violation was corrected during the inspection.						
<u>Violation Description:</u>						
Failure to properly close hazardous waste containers when not in active use.						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violations

Violation Date: 04/29/2014
Violation Program: APSA
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 05/02/2017. Locate the SPCC plan or develop a plan if one has not been completed and notify this agency when the plan has been completed

Violation Description:

Failure to maintain SPCC plan onsite (applies if facility is manned at least four (4) hours per day).

Violations

Violation Date: 06/18/2020
Violation Program: APSA
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Notes:

Returned to compliance on 12/17/2021. The SPCC plan is dated 2-15-13 and must be reviewed every 5 years submit the date reviewed on CERS

Violation Description:

Failure to complete a review and evaluation of the SPCC Plan at least once every five years, document the completion of the review, and sign a statement as to whether the SPCC Plan will be amended.

Violations

Violation Date: 04/29/2014
Violation Program: HW
Citation: 22 CCR 15 66265.173 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.173
Violation Notes:

Returned to compliance on 04/29/2014. One of the three drums on waste oil filters was not stored with the lid closed. The drum was closed at my request this date. Make sure that all hazardous waste containers are stored closed and the violation was abated.

Violation Description:

Failure to properly close hazardous waste containers when not in active use.

Violations

Violation Date: 03/23/2016
Violation Program: HW
Citation: 22 CCR 23 66273.34 - California Code of Regulations, Title 22, Chapter 23, Section(s) 66273.34
Violation Notes:

Returned to compliance on 03/23/2016. Waste Fluorescent lamps were in a 4' tall box, the container was unlabeled. Issue was rectified during the inspection, as Mr. Atchison labeled the box as Universal Waste and added the accumulation start date to the box.

Violation Description:

Failure to properly label the following categories of universal waste as:

- 1) Each batteries or the container in which the batteries are contained as "Universal Waste-Battery(ies)".
- 2) Each mercury-containing equipment or the container in which the mercury-containing equipment is contained as "Universal Waste -Mercury-Containing Equipment".
- 3) Each Florescent lamp or the container or package in which the lamps are contained as "Universal Waste-Lamp(s)".
- 4) Each electronic devices or the container or pallet in or on which the electronic devices are contained as "Universal Waste-Electronic Device(s)".
- 5) Each CRTs or the container or pallet in or on which the CRTs are contained as "Universal Waste-CRT(s)".
- 6) A container of CRT glass shall be labeled or marked clearly with the following phrase: "Universal Waste-CRT glass".
- 7) In lieu of labeling individual electronic devices, CRTs, and/or containers of CRT glass pursuant to subsections d) through f) of this section, a universal waste handler may combine, package, and accumulate those universal wastes in appropriate containers or within a designated area demarcated by

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

boundaries that are clearly labeled with the applicable portion(s) of the following phrase: "Universal Waste-Electronic Device(s)/Universal Waste - CRT (s)/Universal Waste-CRT Glass".

Violations

Violation Date: 03/23/2016
Violation Program: HMRRP
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Source: CERS
Violation Division: Orange County Environmental Health
Violation Notes:

Returned to compliance on 06/13/2017. A copy of the hazardous material business emergency program was not present on site. The facility's point of contact was not able to access the HMBP plan on CERS either. The facility primary contact email needs to be updated on CERS. Please maintain an updated copy of HMBP plan on site.

Violation Description:

Business Plan Program - Administration/Documentation - General

Evaluations

Eval Date: 01/10/2019
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Emergency plan reviewed and accepted by M Sutphin SPCC plan at site notification accepted by M Sutphin Business activity and owner information accepted by M Sutphin Hazmat inventory and site map reviewed and accepted by M Sutphin; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/21/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERS submittal Hazmat business emergency plan reviewed and accepted by M Sutphin .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/04/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERS 10489162 The 2017 HMBEP submittal was accepted today. NOTE the cleaners and the waste absorbents were asked to be removed from the disclosure because they were not at the regulated volume.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/30/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Source: CERS
Eval Notes:

Review of CERS submittal. Accepted facility info for 2016; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/28/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

On site for a routine hazardous waste inspection. Facility went through a change of ownership on 11/7/2022. Business will be removed from the hazardous waste program.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/29/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

On-site for a routine inspection. Met with Vagas Le and Abel Lara this date. There is 2,740 gallons of petroleum storage on-site in above ground tanks No SPCC Plan could be located. A spill prevention control and counter measure plan (SPCC) must be developed for the aboveground storage at your facility. For more information on the SPCC please visit <http://www.calepa.ca.gov/CUPA/Aboveground/FactSheetSPCC.pdf>. --Facilities with less than 10,000 gallons of petroleum storage on-site and no one single container more than 5,000 gallons can complete and self certify an SPCC template which can be found at <http://www.epa.gov/fedrgstr/EPA-WASTE/2008/December/Day-05/f28159.pdf> (appendix G). --Facilities with less than 10,000 gallons on-site and have individual containers more than 5,000 gallons can prepare and self certify SPCC in accordance with 40 CFR 112.6, 112.7 and subpart B. --Facilities with greater than 10,000 gallons of petroleum storage on-site are [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/23/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Garden Grove Hyundai – 3/23/2016 On site to conduct a routine hazardous waste inspection. Consent to enter, inspect and take pictures was given by Mr. Craig Atchison at 11:07 am. The hazardous waste containers found here: a. Used Oil filters = 600 items (4X 55 gallon drums) b. Used Motor Oil = 600 gallons (one 1000 gallon tank, 2/3 full) c. Used Antifreeze = 100 gallons (one 500 gallon tank) d. Waste absorbent = 250 pounds e. Fluorescent light bulbs = 20 tubes (4' cardboard box) Manifests were available and reviewed. Walked the perimeter of the site, and there were no hazardous waste spills or discharges were observed during this inspection. Emergency response poster were posted with necessary information at the common area. The common dumpster on site was checked and empty aerosol cans and empty oil filter boxes were found. Owner was notified to dispose of aerosol cans as universal waste if the aerosol cans are not empty. Training documents were [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/18/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to conduct a routine Hazmat facility inspection. Permission to enter, inspect, and take photographs granted by David Sanchez Car dealership generates hazardous waste from servicing autos and has disclosed 5 hazardous materials Facility has active EPA ID#.CAL000438576. Facility has Submitted a Hazmat Emergency Plan on CERS 10489162. The hazmat plan appears correct. The facility has implemented a Hazmat Business plan and provides employee training.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Date: 07/30/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERS 10489162 reviewed and accepted by M Sutphin Facility has listed lube oil, coolant, waste oil, waste coolant, cleaner soap, degreaser, and fuel contaminated absorbent. ...; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/02/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

On site to conduct a routine Aboveground Petroleum Storage Tank inspection. Consent to inspect, take photos and collect samples was provided by Craig Atchinson. The facility has the following Petroleum products stored in aboveground tanks or containers equal to or greater than 55 gallons: - 1000 gallons waste oil - 1000 gallons motor oil (5W-20) - 100 gallons ATF - 500 gallon motor oil (5W-30) - 100 gallon motor oil The facility provided a copy of a current Spill Prevention Control & Countermeasures Plan and it was available for review at the facility. A training records for training conducted with regards the SPCC plan was also available for review. No APST violations were issued to the facility on this date. Thank you; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/28/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site for routine Hazardous Materials and Business Emergency Plan (HMBEP) inspection. Consent to enter, inspect and take any necessary photos was given by Parts Manager, Paco Montiel. Observed the facility and inspected hazardous materials storage. The hazardous materials observed were in amounts that met or exceeded the minimum volumes required for disclosure: - Lubricating Oils 1500 gallons - Used Oil 1000 gallons - Coolant 100 gallons - Used Coolant 500 gallons - Cleaners/Soaps 55 gallons - Waste Absorbent 55 gallons Employee training documentation was available for review. Emergency Response Notification is posted in the office. Facility went through a change of ownership and a new CERS (California Environmental Report System) submittal has not been submitted under the new ownership, Garden Grove HY LLC. Hazardous Materials documents can be submitted via the California Electronic Reporting System (CERS) located at <http://cers.calepa.ca.gov/>. Please note, you are required to; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/02/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site to conduct a routine Hazardous Materials Business Emergency Plan inspection. Consent to inspect and take photos was provided by Craig Atchison. The facility has submitted in CERS (10489162). A walk through of the facility was conducted. The following Hazardous Substances were observed being stored at above the reporting threshold: HM -Motor oil -Antifreeze Coolant -Degreaser HW -Waste Oil -Waste Coolant This facility is responsible for identifying all hazardous materials and hazardous wastes, which are above the following disclosure thresholds: Solids > 500 pounds. Liquids > or = 55 gallons Gas > or = 200 cubic feet Site map is available for review. Employee training is available for review. Ensure the HMBEP is resubmitted by March 1st every year.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/20/2020
Violations Found: No
Eval General Type: Other/Unknown

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Reviewed CERS , hw inspections , AST and HMBP; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/20/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Reviewed CERS , hw inspections and HMBP; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/13/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

SPCC plan at site per last inspection Facility has submitted SPCC information on CERS for 2795 gallons of petroleum and notification that the SPCC plan was completed 2-15-13; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/18/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by David Sanchez Car dealership generates hazardous waste from servicing autos Facility has active EPA ID#.CAL000428944 Facility has 1000 gallon waste oil capacity in a double walled above ground storage tank. Facility has one 500 gallon double walled AST for waste coolant. Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Emergency Response Information was available for review. Hazardous waste containers were properly labeled and covered. Containers holding hazardous waste were marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/23/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Garden Grove Hyundai – 3/23/2016 On site to conduct a routine hazardous material and business plan inspection. Consent to enter, inspect and take pictures was given by Mr. Craig Atchison at 11:07 am. Walked the site with Mr. Atchison and observed the hazardous material storage areas throughout car dealership and the following hazardous materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: Motor oil = 1000 gallons (two 500 gallon tanks) Engine oil = 120 gallons Coolant = 150 gallons Used Oil filters = 600 items (4X 55 gallon drums) Used Motor Oil = 600 gallons (one 1000 gallon tank, 2/3 full) Used Antifreeze = 100 gallons (one 500 gallon tank) A copy of the hazardous material business emergency program was not present on site. The facility primary contact email needs to be updated on CERS. Update chemical inventory to reflect what's currently on site. Emergency response equipment was present onsite and [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Eval Date: 11/28/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site for a routine hazardous materials inspection. Facility went through a change of ownership on 11/7/2022. Business will be removed from the hazardous materials program.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/18/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to conduct a routine Above ground Tank (AST) facility inspection. Permission to enter, inspect, and take photographs granted by David Sanchez Facility has submitted HMBP on CERS ID 10489162 The SPCC template is available at www.occupainfo.com Auto dealership service department has disclosed 1550 gallons of petroleum in ASTs and 1000gallons of waste oil is ASTs. The Plan also lists 500 gallons of waste antifreeze that does not need to be listed since it is not petroleum. Weekly inspections logs must be kept for the oil tanks. The SPCC plan reviewed at site was dated 2-15-13 and must be recertified every 5 years . please review sign and date the SPCC plan .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/25/2021
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

SPCC plan at site per last inspection Facility has submitted SPCC information on CERS for 2795 gallons of petroleum and notification that the SPCC plan was completed 2-15-13. Please note that the SPCC plan must be reviewed every 5 years and recertification date listed on the CERS APSA facility form must list a date within 5 years , not 2-15-2013. Please note the SPCC plan at site must also list a certification date within 5 years.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/01/2021
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Reviewed and accepted by M Sutphin.SPCC plan at site per last inspection Facility has submitted SPCC information on CERS for 2795 gallons of petroleum and notification that the SPCC plan was completed 2-15-13. and has been re certified in 2021; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/03/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Reviewed and approved CERS APSA submittal; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/20/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Reviewed the facility's 2018 CERS HMBP submission. Facility Information accepted. Waste Coolant/Ethylene Glycol – Please remove the obsolete federal hazard categories listed for this material and check off the appropriate updated federal hazard categories. Emergency Response/Contingency Plan declined - Section C. Emergency Communications... change Local Unified Program Agency (UPA/CUPA) to (714)433-6000.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/28/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

On site to conduct routine Hazardous Waste Inspection. Consent to enter, inspect and take any necessary photos was given by Paco Montiel, Parts Manager. Observed facility, hazardous waste storage area, perimeter, and dumpster area. Hazardous waste containers were stored closed and properly labeled. No indication of hazardous waste spillage, runoff, or illegal disposal was observed. Manifests and emergency response plan were reviewed. Training was reported to be done for employees. No hazardous waste violations were observed on this date. This inspection report was sent to leonarda@gghyundai.com and pacom@hbhyundai.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/02/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

On site to conduct a routine hazardous waste inspection. Consent to inspect and take photos at the facility was provided by Craig Atchison. Municipal dumpster area does not contain any hazardous waste. The perimeter of the facility was also inspected; no signs of releases were noted. Emergency Response Information was complete. Hazardous waste containers were properly labeled and covered. Reviewed manifests, bills of lading and consolidated manifests for all hazardous waste streams. For further information about Hazardous Waste management, please refer to the Orange County CUPA website at www.occupainfo.com and open the PDF "Hazardous Waste the Basics". No hazardous waste violations noted today.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/29/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

On-site for routine hazardous waste generator inspection. Permission to enter, inspect, and take photographs granted by Vargas Le the service manager. Abel Lara the parts manager was also present during the inspection this date. Hazardous Waste receipts made available and reviewed Facility generates Safety-Kleen parts washers waste, clarifier sump waste, waste coolant, oil, and used oil filters. HW containers properly labeled and dated with the beginning date of accumulation One of the three drums on waste oil filters was not stored with the lid closed. The drum was closed at my request this date. Make sure that all hazardous waste containers are stored closed Emergency numbers posted at site Inspected trash/dumpster and it does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. A waste tire generator inspection was also performed this date and a copy of the report will be [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Eval Date:	01/10/2019
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	APSA
Eval Source:	CERS
Eval Notes:	

SPCC plan at site notification accepted by M Sutphin Bussiness activity and owner information accepted by M Sutphin; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	03/21/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Affiliations

Affil Type Desc:	Legal Owner
Entity Name:	GARDEN GROVE HY LLC
Entity Title:	
Address:	9898 Trask Ave
City:	Garden Grove
State:	CA
Country:	United States
Zip Code:	92844
Phone:	(714) 793-0035

Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	9898 Trask Ave
City:	Garden Grove
State:	CA
Country:	
Zip Code:	92844
Phone:	

Affil Type Desc:	Identification Signer
Entity Name:	Leonard Arsanos
Entity Title:	Service Manager
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Parent Corporation
Entity Name:	Garden Grove Hyundai
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Operator
Entity Name:	ARMINA MJERIAN
Entity Title:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Address:

City:

State:

Country:

Zip Code:

Phone:

(714) 793-0035

Affil Type Desc:

Entity Name:

Entity Title:

Address:

City:

State:

Country:

Zip Code:

Phone:

Environmental Contact

Leonard Arsanos

9898 Trask Ave

Garden Grove

CA

92844

Affil Type Desc:

Entity Name:

Entity Title:

Address:

City:

State:

Country:

Zip Code:

Phone:

CUPA District

Orange County Env Health

1241 East Dyer RoadSuite 120

Santa Ana

CA

92705-5611

(714) 433-6406

Affil Type Desc:

Entity Name:

Entity Title:

Address:

City:

State:

Country:

Zip Code:

Phone:

Document Preparer

Celly Services, Inc.

Coordinates

Env Int Type Code:

Program ID:

Latitude:

HWG

10489162

33.766490

Longitude:

Coord Name:

Ref Point Type Desc:

-117.956920

Center of a facility or station.

8	7 of10	SE	0.10 / 547.63	72.11 / -2	DYNAMIC AUTO IMAGES 9898 TRASK AVENUE GARDEN GROVE CA 92844	RCRA NON GEN
-------------------	--------	----	------------------	---------------	---	-----------------

Handler ID:

Generator Status:

Recycler Activity?:

Recycler Activity Note:

CAL000429991

N

NO

This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:

NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Additional Handler Summary Details

Source Type:	I	NAIC 1:	811192
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20170810	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.766389
In Handler Univ:	Y	Location Longitude:	-117.956457
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	Y		
Universal Waste Dest Facility:	Y		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	---		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	-----		
Full Enforcement:	-----		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20180907		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		
Manifest Broker:	N		
Subpart P:	N		
Contact Language:	EN		
Handler Name:	DYNAMIC AUTO IMAGES		
Location Street No:			
Location Street1:	9898 TRASK AVENUE		
Location Street2:			
Location City:	GARDEN GROVE		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		COREY MILLER				
Contact Street No:						
Contact Street1:		1407 N BATAVIA ST STE 102				
Contact Street2:						
Contact City:		ORANGE				
Contact State:		CA				
Contact Zip:		92867				
Contact Country:						
Contact Phone And Ext:		714-981-4367				
Contact Fax:		714-646-5458				
Contact Email Address:		ELISA@DYNAMICAUTOIMAGES.COM				
Contact Title:						
Owner Name:		TOM MILLER				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		COREY MILLER				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						
Contact DTSC for information.						
<u>Hazardous Waste Handler Details</u>						
Seq No:		1				
Receive Date:		20170810				
Handler Name:		DYNAMIC AUTO IMAGES				
Fed Waste Generator:		N				
Generator Code Description:		Not a Generator, Verified				
Source Type:		Implementer				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:		Current Owner			Street No:	
Type:		Other			Street1:	
Name:		TOM MILLER			Street2:	
Dt Became Current:					City:	
Dt Ended Current:					State:	
Phone:		714-771-3400			Country:	
Source Type:		Implementer			Zip:	
					92867	
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Other			Street1:	
Name:		COREY MILLER			Street2:	
Dt Became Current:					City:	
Dt Ended Current:					State:	
Phone:		714-981-4367			Country:	
Source Type:		Implementer			Zip:	
					92867	

<u>8</u>	8 of 10	SE	0.10 / 547.63	72.11 / -2	YNOT6 II LLC DBA GARDEN GROVE HYUNDAI 9898 TRASK AVE GARDEN GROVE CA 92844	RCRA NON GEN
Handler ID: Generator Status: Recycler Activity?: Recycler Activity Note:		CAL000428944 N NO This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	44111
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20170706	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.766389
In Handler Univ:	Y	Location Longitude:	-117.956457
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	Y		
Universal Waste Dest Facility:	Y		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	-----		
Full Enforcement:	-----		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Fa Required:		----				
Hhandler Last Change:		20180907				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		YNOT6 II LLC DBA GARDEN GROVE HYUNDAI				
Location Street No:						
Location Street1:		9898 TRASK AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		MEHRZAD KHAJENOORI				
Contact Street No:						
Contact Street1:		6400 CHRISTIE AVE #5405				
Contact Street2:						
Contact City:		EMERYVILLE				
Contact State:		CA				
Contact Zip:		94608				
Contact Country:						
Contact Phone And Ext:		415-867-8644				
Contact Fax:		949-606-8190				
Contact Email Address:		MEHRZAD@BNDEALERSHIPS.COM				
Contact Title:						
Owner Name:		YNOT6 II LLC				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		MEHRZAD KHAJENOORI				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20170706
Handler Name: YNOT6 II LLC DBA GARDEN GROVE HYUNDAI
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	6400 CHRISTIE AVE #5405
Name:	YNOT6 II LLC	Street2:	
Dt Became Current:		City:	EMERYVILLE
Dt Ended Current:		State:	CA
Phone:	405-620-0511	Country:	
Source Type:	Implementer	Zip:	94608

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	6400 CHRISTIE AVE #5405
Name:	MEHRZAD KHAJENOORI	Street2:	
Dt Became Current:		City:	EMERYVILLE
Dt Ended Current:		State:	CA
Phone:	415-867-8644	Country:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Source Type:		Implementer		Zip:		94608
8	9 of10	SE	0.10 / 547.63	72.11 / -2	GARDEN GROVE MITSUBISHI 9898 TRASK AVE GARDEN GROVE CA	UST SWEEPS
C C:		A30-000-6947		D Filename:		SITE12A
BOE:		44-016549		Page No:		133
Comp:		6947		County:		ORANGE
Status:		ACTIVE		State :		CA
No of Tanks:		2		Zip:		92644
Jurisdict:		ORANGE COUNTY		Latitude:		33.76667
Agency:		ENVIRONMENTAL HEALTH		Longitude:		-117.95677
Phone:				Georesult:		S5HPNTSC-A
<u>Tank Details</u>						
Tank ID:		000001		S Contain:		
O Tank ID:				Stg:		P
SWRCB No:		30-000-006947-000001		Storage :		
Removed:				Storag Type:		PRODUCT
Installed:				P Contain:		
A Date:				Content:		REG UNLEADED
Capac:		3000		ONA:		
Tank Use:		M.V. FUEL		D File Name:		TANK12A
<u>Tank Details</u>						
Tank ID:		000002		S Contain:		
O Tank ID:				Stg:		P
SWRCB No:		30-000-006947-000002		Storage :		
Removed:				Storag Type:		PRODUCT
Installed:				P Contain:		
A Date:				Content:		
Capac:		550		ONA:		
Tank Use:		PETROLEUM		D File Name:		TANK12A
8	10 of10	SE	0.10 / 547.63	72.11 / -2	UNION CHRYSLER JEEP DODGE 9898 TRASK AVE GARDEN GROVE CA 92844	C&D DEBRIS RECY
County:		ORANGE				
Activity Type:		USED OIL COLLECTION				
Phone No:		(714) 741-3100				
9	1 of9	SW	0.11 / 557.72	70.33 / -3	QUALITY NISSAN 9670 TRASK AVE GARDEN GROVE CA 92844	RCRA SQG
Handler ID:		CAD982357949				
Generator Status:		SQG				
Recycler Activity?:		NO				
Recycler Activity Note:		This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.				
<u>Violation/Evaluation Summary</u>						
Note:		NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).				
<u>Handler Summary</u>						

78

erisinfo.com | Environmental Risk Information Services

Order No: 25061300823

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Importer:	No				Used Oil Transpor:	No
Mixed Waste Gen:	No				Used Oil Trans Fac:	No
Transporter:	No				Used Oil Processor:	No
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Additional Handler Summary Details

Source Type:	N			NAIC 1:	
Seq No:	1			NAIC 2:	
Non Notifier:				NAIC 3:	
Receive Date:	19970129			NAIC 4:	
Active Site:	H----			State:	CA
Land Type:	P			Location Latitude:	33.766673
In Handler Univ:	Y			Location Longitude:	-117.959531
In A Universe:	Y			Loc GIS Primary:	N
Gen Status:	SQG			Loc GIS Origin:	AG
Report Cycle:				State District Owner:	CA
Accessibility:				State District:	4
Region:	09				
Fed Waste Gen Owner:		HQ			
State Waste Generator Owner:					
State Waste Generator:					
Short Term Generator:		N			
Uni Waste:		N			
Universal Waste Dest Facility:		N			
Federal Universal Waste:		N			
As Federally Regulated Tsdf:		-----			
As Converter Tsdf:		-----			
As State Regulated Tsdf:		-----			
As State Regulated Handler:		---			
Federal Indicator:		---			
Hsm:		N			
Subpart K:		----			
GPRA Permit:		N			
GPRA Renewal:		N			
Permit Renewal Wrkld:		-----			
Permwrk ID:		-----			
Perm Prog:		-----			
Pcwrkld:		-----			
Closwrkld:		-----			
GPRA Ca:		N			
Cawrkld:		N			
Subjca Tsd Discretion:		N			
NCAPS:		N			
EC Indicator:		N			
Ca725 Indicator:		N			
Ca750 Indicator:		N			
Operating Tsdf:		-----			
Full Enforcement:		-----			
Snc:		N			
Unaddressed Snc:		N			
Addressed Snc:		N			
Snc With Comp Sched:		N			
Fa Required:		-----			
Hhandler Last Change:		20020627			
Recognized Trader Importer:		N			
Recognized Trader Exporter:		N			
Slab Importer:		N			
Slab Exporter:		N			
Manifest Broker:		N			
Subpart P:		N			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Language:		EN				
Handler Name:		QUALITY NISSAN				
Location Street No:						
Location Street1:		9670 TRASK AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		TED DIESEL				
Contact Street No:						
Contact Street1:		9670 TRASK AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92644				
Contact Country:		US				
Contact Phone And Ext:		714-537-0900				
Contact Fax:						
Contact Email Address:						
Contact Title:						
Owner Name:		QUALITY NISSAN				
Owner Type:		P				
Owner Seq:		4				
Operator Name:		NOT REQUIRED				
Operator Type:		P				
Operator Seq:		5				
Public Notes:						
<u>Hazardous Waste Handler Details</u>						
Seq No:		1				
Receive Date:		19970129				
Handler Name:		QUALITY NISSAN				
Fed Waste Generator:		2				
Generator Code Description:		Small Quantity Generator				
Source Type:		Notification				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:		Current Operator			Street No:	
Type:		Private			Street1:	
Name:		NOT REQUIRED			NOT REQUIRED	
Dt Became Current:					City:	
Dt Ended Current:					NOT REQUIRED	
Phone:		415-555-1212			State:	
Source Type:		Notification			ME	
					Country:	
					Zip:	
					99999	
Owner/Operator Ind:		Current Owner			Street No:	
Type:		Private			Street1:	
Name:		QUALITY NISSAN			9670 TRASK AVE	
Dt Became Current:					Street2:	
Dt Ended Current:					City:	
Phone:		714-537-0900			GARDEN GROVE	
Source Type:		Notification			State:	
					CA	
					Country:	
					Zip:	
					92644	
9	2 of 9	SW	0.11 / 557.72	70.33 / -3	QUALITY NISSAN 9670 TRASK AVE GARDEN GROVE CA 92844	DELISTED TNK

Delisted Storage Tanks

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Facility ID: 12923 County: Orange Latitude: 33.7677806 Original Source: UST Longitude: -117.9600233 Record Date: 30-JAN-2017 Permitting Agency: ORANGE COUNTY						
9	3 of 9	SW	0.11 / 557.72	70.33 / -3	Toyota Place 9670 Trask Ave Garden Grove, Ca 92844-2801 CA	AST ORANGE
Establishment ID: FA0051444						
9	4 of 9	SW	0.11 / 557.72	70.33 / -3	9670 TRASK AVE GARDEN GROVE CA 92844	AST
Total Capacity(Gal): 1,320 Owner Name: TOYOTA PLACE CUPA: Orange County: Orange						
9	5 of 9	SW	0.11 / 557.72	70.33 / -3	Toyota Place 9670 Trask Ave Garden Grove, Ca 92844-2801 Garden Grove CA 92844-2801	HW ORANGE
Establishment ID: FA0051444						
9	6 of 9	SW	0.11 / 557.72	70.33 / -3	TOYOTA PLACE 9670 TRASK AVE GARDEN GROVE CA 92844	CERS TANK
Site ID: 178742 Latitude: 33.766693 Longitude: -117.960300						

Regulated Programs

EI ID: 10563634
EI Description: Aboveground Petroleum Storage

Violations

Violation Date: 03/10/2022 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Orange County Environmental Health
Citation: 22 CCR 15 66265.16 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.16
Violation Notes:

Documented training of personnel was not available at the time of inspection. CORRECTIVE ACTION: Locate training documentation or conduct training with applicable personnel and document it. Training program must be run by a person trained in hazardous waste management procedures, shall teach personnel hazardous waste management procedures relevant to the positions in which they are employed (including contingency plan implementation), and shall be designed to ensure that facility personnel are able to respond to emergencies by familiarizing them with emergency procedures, equipment, and systems. Facility employees shall complete the training within 6 months of hire/assignment and shall have annual review of the initial training material. Written documentation must include the job title for each person at the facility related to hazardous waste management, name of each employee filling each of these jobs, written job description for each of these positions, to [Truncated]

Violation Description:

Failure to provide employees with hazardous waste training program of class room instructions or on-the-job training within the first six months after the date of their employment or assignment to a facility, or to a new position at a facility and annually thereafter. Training records on current personnel shall be kept until closure of the facility and for former employees the record shall be kept for at least three years from the date the employee last worked at the facility. The records shall include the following: the job title for each position at the facility related to hazardous waste management, and the name of

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

the employee filling each job; a written job description for each position, duties of facility personnel assigned to each position, and a written description of the type and amount of both introductory and continuing training that will be given to each person filling a position.

Violations

Violation Date: 03/10/2022
Violation Program: HW
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 06/08/2022. The following hazardous waste observed inside of the shop area were without a hazardous waste label: -Used oil paper filter - 55 gallon drum -Used oil metal filters - three 55 gallon drums
CORRECTIVE ACTION: Submit a photo demonstrating that the containers listed above have been properly labeled to this Agency by email within 30 days.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 03/10/2022
Violation Program: HW
Citation: 22 CCR 15 66265.192(a) - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.192(a)
Violation Notes:

A written hazardous waste tank assessment has not been obtained for the used oil and waste antifreeze tank systems prior to placing the systems into service. **CORRECTIVE ACTION:** Obtain a written hazardous waste tank system assessment for the used oil and waste antifreeze tank systems in accordance with 22 CCR 15 66265.192 and submit a copy to this Agency by email within 30 days.

Violation Description:

Failure to obtain and maintain a written assessment reviewed and certified by an independent, qualified, professional engineer prior to placing the tank system in service. The written assessment shall state that, the new hazardous waste tank system has sufficient structural integrity, is acceptable for the transferring, storing and treating of hazardous waste, and that the tanks and containment system including the foundation, structural support, seams, connections, and pressure controls (if applicable) are suitably designed to meet the regulation.

Violations

Violation Date: 09/27/2017
Violation Program: APSA
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 10/19/2017. The facility did not have a record for the inspections conducted on the Aboveground Petroleum Storage Tanks. The facility must conduct inspections in accordance with written procedures and maintain records for 3 years. An inspection checklist was created from the SPCC plan and an inspection was documented today. Ensure the inspection log for the Aboveground tanks is kept and please send me proof of completion of the log after 30 days, send a copy of the completed inspection log to berdman@ochca.com.

Violation Description:

Failure to comply with one or more of the following requirements:

1. Have record of inspections and integrity tests signed by the appropriate supervisor or inspector.
2. Keep written procedures and records of inspections and integrity tests for at least three years.
3. Keep comparison records.

Violations

Violation Date: 03/10/2022
Violation Source: CERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violation Program: APSA
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 06/22/2022. The owner/operator failed to ensure that tanks are inspected by an appropriately qualified person in accordance with industry standards. The operator is inspecting tanks on a monthly basis but has not been conducting inspections of the tanks' interstitial space or the system's piping runs. **CORRECTIVE ACTION:** Ensure that tanks are inspected by an appropriately qualified person in accordance with industry standards. Provide proof of compliance to this Agency by email within 30 days.

Violation Description:

Failure to ensure that tanks are inspected and tested by an appropriately qualified person in accordance with industry standards.

Violations

Violation Date: 03/10/2022
Violation Program: APSA
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 06/22/2022. The owner/operator failed to regularly inspect aboveground valves, piping, and appurtenances. **CORRECTIVE ACTION:** Inspect aboveground valves, piping, and appurtenances on a monthly basis. Provide proof of compliance to this Agency by email within 30 days.

Violation Description:

Failure to regularly inspect aboveground valves, piping, and appurtenances.

Violations

Violation Date: 03/10/2022
Violation Program: APSA
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 06/22/2022. The owner/operator failed to follow procedures to prevent overfills as described in the SPCC Plan, and/or failure to routinely test to ensure proper operation. The operator stated that a facility employee is not present during filling of the motor oil and AFT tanks. **CORRECTIVE ACTION:** Begin following procedures to prevent overfills as described in SPCC plan, and routinely test systems or devices used to prevent overfilling. Provide proof of compliance to this Agency by email within 30 days.

Violation Description:

Failure to provide systems or follow procedures to prevent overfills as described in the SPCC Plan, and/or failure to routinely test to ensure proper operation.

Violations

Violation Date: 04/13/2016
Violation Program: HMRRP
Citation: HSC 6.95 25508.1(a)-(e) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(e)
Violation Notes:

Returned to compliance on 06/12/2017. The chemicals present on site were not representative of what was reported on the HMBP. Please revise the chemical inventory form on CERS and add the additional chemicals that meet or exceed threshold within 30 days.

Violation Description:

Failure to electronically update business plan within 30 days of any one of the following events:
A 100 percent or more increase in the quantity of a previously disclosed material.
Any handling of a previously undisclosed hazardous materials at or above reportable quantities.
A change of business address, business ownership, or business name.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violations

Violation Date: 03/10/2022
Violation Program: APSA
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 05/26/2023. The owner/operator failed to schedule and conduct spill prevention briefings at least once a year and/or to maintain records of briefings. CORRECTIVE ACTION: Conduct spill prevention briefings annually. Provide proof of compliance to this Agency by email within 30 days.

Violation Description:

Failure to conduct spill prevention briefing for oil-handling personnel at least once a year to assure adequate understanding of the SPCC Plan.

Violations

Violation Date: 03/10/2022
Violation Program: APSA
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 06/22/2022. The owner/operator failed to provide Aboveground Storage Tank training to all oil-handling personnel on an annual basis and/or failed to maintain records of training. CORRECTIVE ACTION: Provide training in: 1. The operation and maintenance of equipment to prevent discharges; 2. Discharge procedure protocols; 3. Applicable pollution control laws, rules, and regulations; 4. General facility operations; AND 5. The contents of the SPCC Plan. Provide proof of employee training to this Agency by email within 30 days.

Violation Description:

Failure to provide the following training to all oil-handling personnel:

1. Operation and maintenance of equipment to prevent discharges.
2. Discharge procedure protocols.
3. Applicable pollution control laws, rules, and regulations.
4. General facility operations.
5. Contents of the SPCC Plan.

Violations

Violation Date: 04/13/2016
Violation Program: HW
Citation: 22 CCR 15 66265.173 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.173
Violation Notes:

Returned to compliance on 07/03/2017. Four used oil filter drums were not closed and had used oil filters piled up on the drum. Please dispose of used oil filters immediately or start a new drum to accumulate the used oil filters. All hazardous waste drums must be closed unless you are in the process of filling or emptying the drum. Violation was corrected during the inspection.

Violation Description:

Failure to properly close hazardous waste containers when not in active use.

Violations

Violation Date: 03/10/2022
Violation Program: HW
Citation: 22 CCR 15 66265.173 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.173
Violation Notes:

Returned to compliance on 06/08/2022. 1. The following hazardous waste observed inside of the shop area were observed to be open/missing a lid: -

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Used oil paper filter - 55 gallon drum -Used oil metal filters - three 55 gallon drums CORRECTIVE ACTION: Submit a photo to this Agency by email within 30 days, demonstrating that the containers listed above have been properly closed.

Violation Description:

Failure to meet the following container management requirements:

(a) A container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste.

(b) A container holding hazardous waste must not be opened, handled, or stored in a manner which may rupture the container or cause it to leak.

Violations

Violation Date: 03/10/2022
Violation Program: HW
Citation: 22 CCR 15 66265.174 - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.174
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Returned to compliance on 06/08/2022. The owner/operator failed to document the weekly inspections of the following hazardous waste containers: • Used absorbent contaminated with used oil • Used oil paper filters • Used oil metal filters • Used absorbent contaminated with gasoline CORRECTIVE ACTION: Submit a copy of the inspection log demonstrating that the hazardous waste containers are being inspected weekly to this Agency by email within 30 days.

Violation Description:

Failure to inspect weekly, areas where hazardous waste containers are stored or transferred. The owner or operator shall look for leaking containers and for deterioration of containers and the containment system caused by corrosion or other factors.

Violations

Violation Date: 03/10/2022
Violation Program: HMRRP
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Returned to compliance on 05/27/2022. Make the following corrections/additions to the Site Map section: a. Add the location of the absorbent, hazardous waste storage, and brake cleaner 55 gallon drum, in the area labeled as Tool Room, b. Add the two eyewash stations adjacent to the Tool Room and Electrical Shut-Off switch room, c. Add the location of the 200 gallons of ATF in the oil storage room, and d. Add the location of the loading area, and storm drains. CORRECTIVE ACTION: Make all mentioned corrections on the CERS website, <https://cers.calepa.ca.gov/>, within 30 days.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date: 04/13/2016
Violation Program: HW
Citation: 22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Returned to compliance on 07/03/2017. A drum with a hazardous waste label for used antifreeze was found on the west side dumpster enclosure. The drum was not in not condition and had about 10 gallons of used antifreeze inside. Please move drum to hazardous waste storage area and dispose of the drum immediately. Please send me a copy of the manifest from the disposal within 30 days.

Violation Description:

Failure to dispose of hazardous waste within 180 days (or 270 if waste is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.

Violations

Violation Date: 03/10/2022
Violation Program: HW
Citation:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Citation: 22 CCR 15 66265.195(c) - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.195(c)

Violation Notes:

Returned to compliance on 06/08/2022. Daily inspections of the waste coolant and used oil tank systems have not been conducted and documented. CORRECTIVE ACTION: Submit documentation to this Agency by email within 30 days demonstrating that the waste coolant and used oil tank systems are being properly inspected daily and that the inspections are being documented.

Violation Description:

Failure to conduct and document inspections of hazardous waste tank systems each operating day and retain records of those inspections at the facility.

Violations

Violation Date: 09/27/2017
Violation Program: APSA
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Notes:

Returned to compliance on 09/27/2017. Failure to perform the five-year review of the SPCC plan. The facility provided a copy of an Spill Prevention Control & Countermeasures Plan and the 5 year review of the SPCC Plan was due on 5-14-17. The facility was able to conduct a 5 year amendment and the signed updated SPCC plan today 9-27-17. Violation 1757 is corrected.

Violation Description:

Failure to complete a review and evaluation of the SPCC Plan at least once every five years, document the completion of the review, and sign a statement as to whether the SPCC Plan will be amended.

Violations

Violation Date: 03/10/2022
Violation Program: HMRRP
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

Returned to compliance on 05/27/2022. Make the following correction to the Hazardous Materials Inventory section: a. Disclose Motor Oil and ATF separately, b. Remove Glass Cleaner, Wash n Wax Solution, and Degreaser as they are not stored on-site above reportable threshold quantities, c. Add Brake Cleaner - 55 gallons, d. For Used Oil Filters, add the annual waste amount and the waste code (221), and e. For Lead Acid Batteries, correct the Units to gallons (Gallons of electrolytes), convert all quantities to gallons, and add the Waste Code. CORRECTIVE ACTION: Make all mentioned corrections on the CERS website, <https://cers.calepa.ca.gov/>, within 30 days.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Evaluations

Eval Date: 07/16/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Reviewed and not accepted by M Sutphin Please correct the following List waste antifreeze as a waste not pure also list the CAS # 107-21-1 in the mixture component box for waste antifreeze List the CAS# for waste oil 64742-54-7 in the mixture component box for waste oil; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/04/2025
Violations Found: No
Eval General Type: Compliance Evaluation Inspection

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

On site to conduct a routine Hazardous material inspection. Consent to enter and inspect was granted by Bruce Granse. Verified Hazardous Material Business Plan (HMBP) components submitted in the California Environmental Reporting System (CERS). Employee training records were reviewed. A copy of this report will be emailed to andy@toyotapalace.com; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	03/09/2022
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

On site for a routine non-RCRA LQG hazardous waste inspection. Andy Fu, the Service Manager, was present for the inspection. The following hazardous waste streams were observed: • Used oil • Used absorbent contaminated with used oil • Used oil paper filters • Used oil metal filters • Used absorbent contaminated with gasoline • Waste ethylene glycol • Aerosol waste Walked the interior and exterior of the facility to inspect the hazardous waste storage area and trash dumpster. Hazardous wastes are stored in containers or tanks that are in good condition, closed, and properly labeled. No hazardous waste was observed in the dumpster. Hazardous Waste Emergency Response information was posted. Manifest were available and reviewed. Provided hazardous waste information for the business. Provided education in regards to containers being labeled and emptied daily for the waste oil plumbing lines and the aerosol cans crusher catch buckets. E-mailed [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	07/16/2015
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

cers 10563634 REVIEWED FACILITY HAS REPORTABLE QUANTITIES OF WASTE OIL AND WASTE COOLANT; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	02/13/2020
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	APSA
Eval Source:	CERS
Eval Notes:	

SPCC plan at site per last inspection Facility has submitted SPCC information on CERS for 2400 gallons of petroleum and notification that the SPCC plan review was completed 9-27-17 Business Emergency Contingency plan reviewed and accepted by M Sutphin; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	09/03/2015
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Reviewed and accepted by M Sutphin the waste antifreeze was corrected to waste for type of hazardous material; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Eval Date:		04/13/2016				
Violations Found:		Yes				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HW				
Eval Source:		CERS				
Eval Notes:						
<p>Toyota Place – 4/13/16 On site to conduct a routine hazardous waste inspection. Consent to enter, inspect and take pictures was given by the Parts & Service director Pat Petty at 7:27 am. The hazardous waste containers found inside the Toyota Car dealership are: - Used oil = 600 gallons (AST) - Used antifreeze = 300 gallons (AST and one 55 G drum) - Used oil filters = 600 items (Four 55 G drums) Manifests were available and reviewed. Hazardous waste was picked up by Asbury Environmental services. Emergency response information was posted in the common area and lunch area for employees. Walked the perimeter of the site with Mr. Doan, and there were no hazardous waste spills or discharges observed during this inspection. The dumpsters in the east and west end of the facility was inspected. A drum with a hazardous waste label for used coolant was found on the west side dumpster enclosure with very little liquid. Mr. Doan was asked to dispose of it [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.</p>						
Eval Date:		05/30/2019				
Violations Found:		No				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HMRRP				
Eval Source:		CERS				
Eval Notes:						
<p>Mark Sutphin on site to conduct a routine Hazmat facility inspection. Permission to enter, inspect, and take photographs granted by Randy Doan Facility has submitted a hazmat business plan on CERS 10563634 Facility has disclosed 11 hazardous materials above reportable quantities. Hazmat disclosure appears correct and site map appears correct. Facility has submitted an SPCC plan Facility has implemented hazmat business plan and provides employee training.; Note: data in [EVAL Notes] field for some records is truncated from the source.</p>						
Eval Date:		03/18/2016				
Violations Found:		No				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HMRRP				
Eval Source:		CERS				
Eval Notes:						
<p>The following documents were reviewed and ACCEPTED on CERS: - Hazardous Materials Inventory (2) - Site Map - Emergency Response Plan - Training Plan; Note: data in [EVAL Notes] field for some records is truncated from the source.</p>						
Eval Date:		06/23/2022				
Violations Found:		No				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HMRRP				
Eval Source:		CERS				
Eval Notes:						
<p>Off-site reinspection. The following documents were reviewed by this Agency: -CERS submittal submitted for CERS ID 10563634 on 5/27/2022. The Hazardous Materials Inventory and the Site Map were corrected. Violations I169 and I632 were observed corrected. All violations have been corrected. No further action is required at this time. A copy of this inspection report will be emailed to bruce@toyotaplace.com; andy@toyotaplace.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.</p>						
Eval Date:		09/02/2015				
Violations Found:		No				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HMRRP				
Eval Source:		CERS				
Eval Notes:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Reviewed and not accepted by M Sutphin. For the waste antifreeze please change the hazardous material type from pure to waste; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/05/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Coded 3-3-15 has mat review to HW; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 10/19/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

This is an in-office inspection report. A copy of the Inspection record for the Aboveground Petroleum Storage Tanks was received and has been completed for this month. Violation I258 is corrected. No outstanding APST violations remain at this time. Thank you; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/27/2022
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

The following documents were reviewed by this Agency: 1. Training documents (Received 6/22/2022). Refer to violation I284. 2. Pictures of hazardous waste labeled containers (Received 6/8/2022). Correcting violation I400. 3. Pictures of hazardous waste closed containers (Received 6/8/2022). Correcting violation I617. 4. Hazardous waste areas weekly inspection logs dated 3/14/2022 - 6/6/2022 (Received 6/8/2022). Correcting violation I364. 5. Written hazardous waste tank system assessment for the 313 gallon waste coolant tank and the 721 gallon waste oil tank (Received 6/23/2022 and 6/27/2022). Refer to violation I162. 6. Daily inspection logs of the waste coolant and used oil tank systems (Received 6/8/2022). Correcting violation I266. The following violations were observed corrected and will be abated: I400, I617, I364, and I266. CORRECT ALL VIOLATIONS NOTED ON THIS INSPECTION REPORT. 1. Violation I284 Training documents were provided to this Agency but did not include: a. Teach; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/15/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

The facility has made required changes to their Hazmat inventory. All submittal elements have been accepted. 2018 Annual HMBP Certification is approved.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/17/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Notes:

Reviewed and accepted by M Sutphin APSA SPCC in Emergency Response/Contingency Plan in CERS 10563634 .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/13/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 03/09/2022
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

On site to conduct a routine Aboveground Petroleum Storage Act (APSA) inspection. Consent to inspect was given from Andy Fu, the Service Manager. Facility has approximately 2600 gallons of petroleum stored. The facility has the following petroleum storage containers and tanks on site regulated under APSA: • Waste Oil tank - 700 gallon tank • Motor Oil - Two 500 gallon tanks • ATF - Two 350 gallon tanks and 200 gallon tank Spill prevention Control and Countermeasure (SPCC) plan was on site and reviewed. SPCC plan was last reviewed and certified on 9/27/2017. The SPCC Plan will need to be recertified by September 2022. No spills greater than 42 gallons were reported by Mr. Fu. This inspection report will be sent to bruce@toyotaplace.com; andy@toyotaplace.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/24/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Mark Sutphin on site for routine aboveground petroleum storage tank (APST) inspection. Permission to enter, inspect, and take photographs granted by Doug Graf The facility has the following aboveground petroleum storage: - 2,000 gallon split tank with the following storage: 1 x 700 gallons of waste oil, 2 x 500 gallons of new oil, 1 x 300 gallons of waste antifreeze (not regulated under APST program) - 1 x 350 gallons of ATF - 1 x 350 gallons of Dextron (transmission fluid) All tanks have integral secondary containment. The SPCC plan is dated 5/14/12. Training records are available for review. .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/16/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Facility has notified of APST on CERS 10563634 Facility has 1700 gallons of good oil and 300 gallons of waste oil in ASTs SPCC plan is kept at site .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/30/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by Randy Doan Facility generates hazardous waste from servicing autos Facility has active EPA ID# Manifests from Asbury / World oil reviewed at site and in good order Facility has one 500 gallon waste oil AST and one 500 gallon waste coolant AST, waste oil filters are stored in closed drums . Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Emergency Response Information was available for review. Hazardous waste containers were properly labeled and covered. Containers holding hazardous waste were marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/13/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Toyota Place – 4/13/16 On site to conduct a routine hazardous material and business plan inspection. Consent to enter, inspect and take pictures was given by the Parts & Service director Pat Petty at 7:27 am. Walked the site with the Warranty Administrator Randy Doan and observed the hazardous material storage areas throughout the Toyota car dealership and the following materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: - Brake Fluid = 110 gallons (2X 55 gallon drums) - Nitrogen = 300 CF - Degreaser = 110 gallons (2X55 gallons) - Propane = 14 gallons - Clean Glass cleaners = 55 gallons - Wash and Wax solution = 55 gallons - Motor Oil = 1000 gallons (AST) - Used Oil = 600 gallons (AST) - Used antifreeze = 300 gallons (AST and one 55 G drum) - Antifreeze = 70 gallons (multiple 1 gallon containers) - Used oil filters = 600 items (Four 55 G drums) -Car batteries Business emergency plan was completed and [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/27/2022
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: APSA
Eval Source: CERS
Eval Notes:

THIS REPORT SUPERSEDES THE PREVIOUS REPORT The following documents were reviewed by this Agency: 1. Training documentation (Received 6/22/2022). Correcting violation I009. 2. AST system inspection logs from 1/3/2022 - 6/22/2022 (Received 6/22/2022). Correcting violation I383 and I722. 3. Notification that the facility is following its procedures to prevent overfills as described in the SPCC Plan (Employee is present during filling of the motor oil and AFT tanks). Correcting violation I037. The following violations were observed corrected and will be abated: I009, I383, I722, and I037. CORRECT ALL OF THE VIOLATIONS NOTED ON THIS INSPECTION REPORT: 1. Violation I039 The owner/operator failed to schedule and conduct spill prevention briefings at least once a year and/or to maintain records of briefings. CORRECTIVE ACTION: Conduct spill prevention briefings annually. Provide proof of compliance to this Agency by email immediately. A copy of this inspection report will be emailed; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/25/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

The facility's CERS HMBEP Submission was reviewed. All submittal elements were accepted.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/04/2025
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

On site to conduct a routine hazardous waste inspection. Consent to enter and inspect was granted by Bruce Granse. The facility is a Non-RCRA large quantity generator of automotive repair waste. A hazardous waste tank assessment for waste oil and waste coolant tank were available for review, completed 6-1-22. Daily tank inspections are currently being conducted. Hazardous waste containers were observed closed and properly labeled. Hazardous waste manifests were available for review. No hazardous waste was observed in the municipal trash area. Employees are reported to have completed hazardous waste training. A copy of this report will be provided to andy@toyotapalace.com; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	04/12/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Arrived on site to perform an inspection. Manager was not available on site, and had to make an appointment for tomorrow.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	04/13/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

Eval Date:	09/27/2017
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	APSA
Eval Source:	CERS
Eval Notes:	

On site to conduct a routine Aboveground Petroleum Storage Tank inspection. Consent to inspect was provided by Pat Petty. The facility has the following Petroleum products stored in aboveground tanks or containers equal to or greater than 55 gallons: - 350 gallons 5W - 20 - 350 gallons 5W - 30 - 55 gallons ATF - 700 galons Used oil - 500 gallons OW - 20 - 500 gallons OW - 20 - 55 Brake Cleaner Total = 2510 gallons The facility provided a copy of an Spill Prevention Control & Countermeasures Plan and it was available for review at the facility however the 5 year review and amendment was due on 5-14-17 (see violation). The facility was able to conduct a 5 year review and signed an updated SPCC plan today 9-27-17. A training record for training conducted with regards the SPCC plan was also available for review. The facility APST Inspections have not been conducted. An Inspection Log was printed and completed during this inspection. However as per Susan [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	03/09/2022
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

On site for a routine hazardous materials inspection. Andy Fu, the Service Manager, was present for the inspection. Observed the following disclosable materials: • Waste Oil - 500 gallons • Motor Oil - 1000 gallons • ATF - 700 gallons • Waste antifreeze - 150 gallons • Antifreeze - 55 gallons • Liquefied Petroleum Gas - 14 gallons • Used oil filters - 500 pounds • Brake fluid - 55 gallons • Brake Cleaner -55 gallon drum • Lead acid batteries The Hazardous Materials Business Plan submitted on CERS on 2/21/2022 was reviewed/verified this date. REQUIREMENT FOR ELECTRONIC SUBMITTAL OF HMBEP DOCUMENTS: This report serves as notice that the facility must submit the following documents electronically within 30 days of this report: • Hazardous Materials Inventory • Site Map Documented employee training was verified. The facility is responsible for identifying all hazardous materials, to include hazardous wastes, which are above disclosure [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Eval Date:	04/28/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

The following documents were reviewed and ACCEPTED on CERS: - Hazardous Materials Inventory (9)- Please include the car batteries as they were observed above the threshold quantity. - Site Map - Facility information Please contact Shruthi Sill at ssill@ochca.com with regards to any questions. Submitted RUR to change status to 5802.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	09/24/2014
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

Mark Sutphin on-site for routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by Doug Graf the Building Operations Manager this date. The facility generates waset oil, filters, coolant, and brake cleaner Hazardous Waste receipts made available and reviewed. Garden Grove BEP on-site and contains contact information for the emergency coordinator. Inspected trash/dumpster and it does not appear to contain any hazardous waste. facility has an SPCC plan and has over 1320 gallons of petroleum stored in above ground tanks .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	05/30/2019
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	APSA
Eval Source:	CERS
Eval Notes:	

Mark Sutphin on site to conduct a routine SPCC facility inspection. Permission to enter, inspect, and take photographs granted by Randy Doan Facility has submitted a hazmat business plan on CERS 10563634 Facility has completed an SPCC plan and the plan was reviewed at site. Facility has reported 2750 gallons of petroleum product and waste at site in 55 gallon drums or greater. Please note that the 500 gallon tank of waste coolant should not be included in the SPCC plan. Facility has implemented an SPCC plan and provides employee training.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	03/03/2015
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

CERS submittal 10514770 reviewed and declined 3-3-15 by M Sutphin Submittal reviewed by M Sutphin. Correct the hazmat inventory with the CAS #s in the mixture box ATF mineral oil 64743570, Alkyl phosphites 66610-62-8, waste antifreeze 20 to 100 % Ethylene Glycol 107211 On the plot plan note the location of the storm drains , the fire hydrants, electrical shut off, water shut off and other areas that are noted in the legend but are not noted on the map .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	02/23/2021
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	APSA
Eval Source:	CERS
Eval Notes:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

APSA facility SPCC plan certification dated 9-27-17 submitted on CERS . 2400 gallons of petroleum noted; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc:	Environmental Contact
Entity Name:	Andy Fu
Entity Title:	
Address:	9670 TRASK AVE
City:	GARDEN GROVE
State:	CA
Country:	
Zip Code:	92844
Phone:	
Affil Type Desc:	Operator
Entity Name:	Sam Chaalan
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(714) 895-5595
Affil Type Desc:	Parent Corporation
Entity Name:	TOYOTA PLACE
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	
Affil Type Desc:	Document Preparer
Entity Name:	Chris Mamoulelis, Celly Services, Inc.
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	
Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	9670 TRASK AVE
City:	GARDEN GROVE
State:	CA
Country:	
Zip Code:	92844
Phone:	
Affil Type Desc:	Legal Owner
Entity Name:	Noarus TGG, Inc.
Entity Title:	
Address:	9670 TRASK AVE
City:	GARDEN GROVE
State:	CA
Country:	United States
Zip Code:	92844
Phone:	(714) 895-5595
Affil Type Desc:	Identification Signer
Entity Name:	Andy Fu

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Entity Title:	Service Manager
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	
Affil Type Desc:	CUPA District
Entity Name:	Orange County Env Health
Entity Title:	
Address:	1241 East Dyer RoadSuite 120
City:	Santa Ana
State:	CA
Country:	
Zip Code:	92705-5611
Phone:	(714) 433-6406

Coordinates

Env Int Type Code:	HWG	Longitude:	-117.960300
Program ID:	10563634	Coord Name:	
Latitude:	33.766690	Ref Point Type Desc:	Center of a facility or station.

9	7 of9	SW	0.11 / 557.72	70.33 / -3	NOARUS TGG INC DBA TOYOTA PLACE 9670 TRASK AVE GARDEN GROVE CA 92844-2801	RCRA NON GEN
-------------------	-------	----	---------------	------------	---	-----------------

Handler ID:	CAL000330099
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).
-------	--

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	44111
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20080226	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.766673
In Handler Univ:	Y	Location Longitude:	-117.959531
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Report Cycle:			State District Owner:			
Accessibility:			State District:			
Region:	09					
Fed Waste Gen Owner:		HQ				
State Waste Generator Owner:		CA				
State Waste Generator:		2				
Short Term Generator:		N				
Uni Waste:		Y				
Universal Waste Dest Facility:		Y				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20180905				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		NOARUS TGG INC DBA TOYOTA PLACE				
Location Street No:						
Location Street1:		9670 TRASK AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844-2801				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		PAT PETTY				
Contact Street No:						
Contact Street1:		9670 TRASK AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:						
Contact Phone And Ext:		714-895-5595				
Contact Fax:		714-889-2107				
Contact Email Address:		PAT@TOYOTAPLACE.COM				
Contact Title:						
Owner Name:		NORRIS J BISHTON				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Owner Type:		O				
Owner Seq:		1				
Operator Name:		PAT PETTY				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20080226
Handler Name: NOARUS TGG INC DBA TOYOTA PLACE
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	9670 TRASK AVE
Name:	PAT PETTY	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-895-5595	Country:	
Source Type:	Implementer	Zip:	92844

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9670 TRASK AVE
Name:	NORRIS J BISHTON	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	VA
Phone:	714-895-5545	Country:	
Source Type:	Implementer	Zip:	22102-4909

<u>9</u>	8 of 9	SW	0.11 / 557.72	70.33 / -3	NISSAN 9670 TRASK AVE GARDEN GROVE CA 92844-2801	AST SWRCB
--------------------------	--------	----	------------------	---------------	--	-----------

Total Gals: 0
Owner Name: NISSAN
Data Source: SWRCB Aboveground Storage Tanks Listing 2003;SWRCB Aboveground Storage Tanks Listing 2005;SWRCB Aboveground Storage Tanks Listing 2007

<u>9</u>	9 of 9	SW	0.11 / 557.72	70.33 / -3	TOYOTA PLACE 9670 TRASK AVE GARDEN GROVE CA 92844	C&D DEBRIS RECY
--------------------------	--------	----	------------------	---------------	---	--------------------

County: ORANGE
Activity Type: USED OIL COLLECTION
Phone No:

<u>10</u>	1 of 1	N	0.11 / 559.27	73.61 / 0	ROBERT KELLEY 13262 VERDE ST, UNIT 1 GARDEN GROVE CA 92884	RCRA NON GEN
---------------------------	--------	---	------------------	--------------	--	-----------------

Handler ID: CAC003203540
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20221109	NAIC 4:	
Active Site:	----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	-----		
Full Enforcement:	-----		
Snc:	N		
Unaddressed Snc:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20221109				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		ROBERT KELLEY				
Location Street No:						
Location Street1:		13262 VERDE ST, UNIT 1				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92884				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		ROBERT KELLEY				
Contact Street No:						
Contact Street1:		13262 VERDE ST, UNIT 1				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92884				
Contact Country:						
Contact Phone And Ext:		205-678-0360				
Contact Fax:						
Contact Email Address:		ELIZABETHS@PWSEI.COM				
Contact Title:						
Owner Name:		ROBERT KELLEY				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		ROBERT KELLEY				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20221109
 Handler Name: ROBERT KELLEY
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	13262 VERDE ST, UNIT 1
Name:	ROBERT KELLEY	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	205-678-0360	Country:	
Source Type:	Implementer	Zip:	92884

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	13262 VERDE ST, UNIT 1
Name:	ROBERT KELLEY	Street2:	
Dt Became Current:		City:	GARDEN GROVE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Dt Ended Current:				State:	CA	
Phone:	205-678-0360			Country:		
Source Type:	Implementer			Zip:	92884	

11	1 of 2	NW	0.11 / 569.37	73.57 / 0	LORI DUNHAM 9771 IMPERIAL AVE GARDEN GROVE CA 92844	RCRA NON GEN
--------------------	--------	----	---------------	-----------	---	-----------------

Handler ID: CAC003174431
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20220504	NAIC 4:	
Active Site:	-----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20220509				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		LORI DUNHAM				
Location Street No:						
Location Street1:		9771 IMPERIAL AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		ASBESTOS ABATEMENT INC				
Contact Street No:						
Contact Street1:		2296 E VIA BURTON				
Contact Street2:						
Contact City:		ANAHEIM				
Contact State:		CA				
Contact Zip:		92806				
Contact Country:						
Contact Phone And Ext:		714-780-1701				
Contact Fax:						
Contact Email Address:		ELENA@ABGCONSTRUCTIONCO.COM				
Contact Title:						
Owner Name:		LORI DUNHAM				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		ASBESTOS ABATEMENT INC				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20220504
Handler Name: LORI DUNHAM
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Other				Street1:	2296 E VIA BURTON
Name:	ASBESTOS ABATEMENT INC				Street2:	
Dt Became Current:					City:	ANAHEIM
Dt Ended Current:					State:	CA
Phone:	714-780-1701				Country:	
Source Type:	Implementer				Zip:	92806
Owner/Operator Ind:	Current Owner				Street No:	
Type:	Other				Street1:	9771 IMPERIAL AVE
Name:	LORI DUNHAM				Street2:	
Dt Became Current:					City:	GARDEN GROVE
Dt Ended Current:					State:	CA
Phone:	714-397-9180				Country:	
Source Type:	Implementer				Zip:	92844

<u>11</u>	2 of2	NW	0.11 / 569.37	73.57 / 0	9771 IMPERIAL AVE 9771 IMPERIAL AVE GARDEN GROVE CA 92840-3434	RCRA NON GEN
---------------------------	-------	----	------------------	--------------	--	-----------------

Handler ID: CAC003214811
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20230130	NAIC 4:	
Active Site:	-----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20241212				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		9771 IMPERIAL AVE				
Location Street No:						
Location Street1:		9771 IMPERIAL AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92840-3434				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		LORI DUNHAM				
Contact Street No:						
Contact Street1:		9771 IMPERIAL AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92840-3434				
Contact Country:						
Contact Phone And Ext:		714-397-9180				
Contact Fax:						
Contact Email Address:		ERNIE@SIRRIS.BIZ				
Contact Title:						
Owner Name:		LORI DUNHAM				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		LORI DUNHAM				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20230130
 Handler Name: 9771 IMPERIAL AVE
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9771 IMPERIAL AVE
Name:	LORI DUNHAM	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-397-9180	Country:	
Source Type:	Implementer	Zip:	92840-3434

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	9771 IMPERIAL AVE
Name:	LORI DUNHAM	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-397-9180	Country:	
Source Type:	Implementer	Zip:	92840-3434

12	1 of2	ENE	0.12 / 649.42	74.16 / 1	Vung Tau Auto Repair 13331 Brookhurst St Ste C Garden Grove, Ca 92843-7000 Garden Grove CA 92843-7000	HW ORANGE
--------------------	-------	-----	---------------	-----------	---	-----------

Establishment ID: FA0067316

12	2 of2	ENE	0.12 / 649.42	74.16 / 1	Quoc Auto Repair 13331 Brookhurst St Ste A Garden Grove, Ca 92843-7000 Garden Grove CA 92843-7000	HW ORANGE
--------------------	-------	-----	---------------	-----------	---	-----------

Establishment ID: FA0055612

13	1 of1	NE	0.14 / 722.41	75.62 / 2	JANNIEN NGUYEN 9942 CENTRAL AVE, APT F GARDEN GROVE CA 92844	RCRA NON GEN
--------------------	-------	----	---------------	-----------	--	-----------------

Handler ID: CAC003271573
 Generator Status: N
 Recycler Activity?: NO
 Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer: No Used Oil Transpor: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Mixed Waste Gen:	No				Used Oil Trans Fac:	No
Transporter:	No				Used Oil Processor:	No
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Additional Handler Summary Details

Source Type:	1			NAIC 1:	56299
Seq No:	2			NAIC 2:	
Non Notifier:				NAIC 3:	
Receive Date:	20240503			NAIC 4:	
Active Site:	----			State:	CA
Land Type:				Location Latitude:	
In Handler Univ:	N			Location Longitude:	
In A Universe:	N			Loc GIS Primary:	N
Gen Status:	N			Loc GIS Origin:	
Report Cycle:				State District Owner:	
Accessibility:				State District:	
Region:	09				
Fed Waste Gen Owner:	HQ				
State Waste Generator Owner:	CA				
State Waste Generator:	D				
Short Term Generator:	N				
Uni Waste:	N				
Universal Waste Dest Facility:	N				
Federal Universal Waste:	N				
As Federally Regulated Tsdf:	-----				
As Converter Tsdf:	-----				
As State Regulated Tsdf:	-----				
As State Regulated Handler:	---				
Federal Indicator:	---				
Hsm:	N				
Subpart K:	----				
GPRA Permit:	N				
GPRA Renewal:	N				
Permit Renewal Wrkld:	-----				
Permwrk ID:	-----				
Perm Prog:	-----				
Pcwrkld:	-----				
Closwrkld:	-----				
GPRA Ca:	N				
Cawrkld:	N				
Subjca Tsd Discretion:	N				
NCAPS:	N				
EC Indicator:	N				
Ca725 Indicator:	N				
Ca750 Indicator:	N				
Operating Tsdf:	-----				
Full Enforcement:	-----				
Snc:	N				
Unaddressed Snc:	N				
Addressed Snc:	N				
Snc With Comp Sched:	N				
Fa Required:	----				
Hhandler Last Change:	20240918				
Recognized Trader Importer:	N				
Recognized Trader Exporter:	N				
Slab Importer:	N				
Slab Exporter:	N				
Manifest Broker:	N				
Subpart P:	N				
Contact Language:	EN				
Handler Name:	JANNIEN NGUYEN				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Location Street No:						
Location Street1:		9942 CENTRAL AVE, APT F				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		JANNIEN NGUYEN				
Contact Street No:						
Contact Street1:		9942 CENTRAL AVE, APT F				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:						
Contact Phone And Ext:		714-376-7492				
Contact Fax:						
Contact Email Address:		ELIZABETHS@PWSEI.COM				
Contact Title:						
Owner Name:						
Owner Type:						
Owner Seq:						
Operator Name:						
Operator Type:						
Operator Seq:						
Public Notes:						

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20240202
Handler Name: JANNIEN NGUYEN
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20240503
Handler Name: JANNIEN NGUYEN
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	9942 CENTRAL AVE, APT F
Name:	JANNIEN NGUYEN	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-376-7492	Country:	
Source Type:	Implementer	Zip:	92844

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9942 CENTRAL AVE, APT F
Name:	JANNIEN NGUYEN	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-376-7492	Country:	
Source Type:	Implementer	Zip:	92844

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Historical Handler Details

Receive Dt:	20240202
Generator Code Description:	Not a Generator, Verified
Handler Name:	JANNIEN NGUYEN

14	1 of2	E	0.15 / 775.47	74.45 / 1	BIG O TIRES 13388 BROOKHURST ST GARDEN GROVE CA 92841	RCRA SQG
--------------------	-------	---	---------------	-----------	---	----------

Handler ID:	CAD981668973
Generator Status:	SQG
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).
-------	--

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	NAIC 1:	
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	19861212	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:	O	Location Latitude:	33.768306
In Handler Univ:	Y	Location Longitude:	-117.954892
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	SQG	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	CA
Accessibility:		State District:	4
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:			
State Waste Generator:			
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20020627				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		BIG O TIRES				
Location Street No:						
Location Street1:		13388 BROOKHURST ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92841				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		ENVIRONMENTAL MANAGER				
Contact Street No:						
Contact Street1:		13388 BROOKHURST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92663				
Contact Country:		US				
Contact Phone And Ext:		714-546-9961				
Contact Fax:						
Contact Email Address:						
Contact Title:						
Owner Name:		SECURITY CAL INC				
Owner Type:		P				
Owner Seq:		1				
Operator Name:		NOT REQUIRED				
Operator Type:		P				
Operator Seq:		2				
Public Notes:						

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 19861212
 Handler Name: BIG O TIRES
 Fed Waste Generator: 2
 Generator Code Description: Small Quantity Generator
 Source Type: Notification

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Private	Street1:	NOT REQUIRED
Name:	NOT REQUIRED	Street2:	
Dt Became Current:		City:	NOT REQUIRED
Dt Ended Current:		State:	ME
Phone:	415-555-1212	Country:	
Source Type:	Notification	Zip:	99999
Owner/Operator Ind:	Current Owner	Street No:	
Type:	Private	Street1:	NOT REQUIRED
Name:	SECURITY CAL INC	Street2:	
Dt Became Current:		City:	NOT REQUIRED
Dt Ended Current:		State:	ME
Phone:	415-555-1212	Country:	
Source Type:	Notification	Zip:	99999

14	2 of2	E	0.15 / 775.47	74.45 / 1	HAS INC DBA ZUBYS BRAKES TIRES AND WHEELS 13388 BROOKHURST ST GARDEN GROVE CA 92843-3153	RCRA NON GEN
--------------------	-------	---	------------------	--------------	---	-----------------

Handler ID:	CAL000313023
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20061027	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.768306
In Handler Univ:	Y	Location Longitude:	-117.954892
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Short Term Generator:		N				
Uni Waste:		Y				
Universal Waste Dest Facility:		Y				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20180905				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		HAS INC DBA ZUBYS BRAKES TIRES AND WHEELS				
Location Street No:						
Location Street1:		13388 BROOKHURST ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843-3153				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		PETER SOLAKIAN/PRES.				
Contact Street No:						
Contact Street1:		13388 BROOKHURST ST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92843				
Contact Country:						
Contact Phone And Ext:		714-636-8835				
Contact Fax:		714-636-8912				
Contact Email Address:		ANIEJERSEY@GMAIL.COM				
Contact Title:						
Owner Name:		HAS INC				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		PETER SOLAKIAN/PRES.				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20061027
 Handler Name: HAS INC DBA ZUBYS BRAKES TIRES AND WHEELS
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	13388 BROOKHURST ST
Name:	PETER SOLAKIAN/PRES.	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-636-8835	Country:	
Source Type:	Implementer	Zip:	92843

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	13388 BROOKHURST ST
Name:	HAS INC	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-636-8835	Country:	
Source Type:	Implementer	Zip:	92843-3153

15	1 of 4	ESE	0.15 / 782.79	71.28 / -2	MOBIL #18-G03E 13521 BROOKHURST ST # 18-G03E GARDEN GROVE CA 92843	DELISTED TNK
--------------------	--------	-----	------------------	---------------	--	-----------------

Delisted Storage Tanks

Facility ID:	2129	County:	Orange
Latitude:	33.76657	Original Source:	UST
Longitude:	-117.95514	Record Date:	30-JAN-2017
Permitting Agency:	ORANGE COUNTY		

15	2 of 4	ESE	0.15 / 782.79	71.28 / -2	MOBIL #18-GOE 13521 BROOKHURST GARDEN GROVE CA 92643	LUST
--------------------	--------	-----	------------------	---------------	--	------

Global ID:	T0605901769	Case Type (DL):	LUST Cleanup Site
Site Facility Type:	LUST CLEANUP SITE	Oil Field (SRCH):	
Site Fac Type (SRCH):	LUST CLEANUP SITE	Oil Field Oper (SRCH):	
Status:		Census Tract (SRCH):	6059088901
Status (SRCH):	COMPLETED - CASE CLOSED	Latitude (DL):	33.7664374
Status (DL):	Completed - Case Closed	Longitude (DL):	-117.9551106
Status Date (DL):	3/7/1995	RWQCB Region (DL):	SANTA ANA RWQCB (REGION 8)
Cleanup Status:	COMPLETED - CASE CLOSED		
Site Facility Name (SRCH):	MOBIL #18-GOE		
Address (SRCH):	13521 BROOKHURST		
City (SRCH):	GARDEN GROVE		
Zip (SRCH):	92643		
County (SRCH):	ORANGE		
Street No (DL):	13521		
Street Name (DL):	BROOKHURST		
City (DL):	GARDEN GROVE		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Zip (DL):		92643				
County (DL):		Orange				
State (DL):		CA				
Business Name (DL):		MOBIL #18-GOE				
Site Facility Name:		MOBIL #18-GOE				
Address :		13521 BROOKHURST				
City :		GARDEN GROVE				
Zip :		92643				
County :		ORANGE				
Report Source:		LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search				

GeoTracker Sites Data Download - Site Details

CUF Case:
Lead Agency: ORANGE COUNTY LOP
Case Worker:
Local Agency:
RB Case No: 083002491T
Local Case No: 94UT037
File Location: Local Agency
Potential COC: Gasoline
Potential Media of Concern: Soil
Begin Date: 7/21/1994
How Discovered: Tank Closure
How Discovered Description:
Stop Method: Close and Remove Tank
Stop Description:
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name: Coastal Plain Of Orange County (8-001)
Disadvantaged Community:
CalEnvScreen Score:
Coordinate Source: Google Geocode
Discharge Cause:
Discharge Source:
EPA Region: 9
Leak Reported Dt: 1994-07-21 00:00:00
Military DoD Site: No
No Further Action Dt: 1995-03-07 00:00:00
Qty Rlsd Gallons: 0
Facility Project Sub Type:
Calenviroscreen 3 Score: 56-60%
Calenviroscreen 4 Score: 55-60%
A2022 Assembly District: 70
Claim No:
Claim Status:
A2022 Congressional District: 45
A2022 Senate District: 36
Site History:

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 3/7/1995

Status: Open - Case Begin Date
Status Date: 7/21/1994

GeoTracker Search - Regulatory Profile

Site Facility Name: MOBIL #18-GOE
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 13521 BROOKHURST
City: GARDEN GROVE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Zip:		92643				
County:		ORANGE				
Report Link:		https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605901769				
Cleanup Status Detail:		COMPLETED - CASE CLOSED AS OF 3/7/1995				
Project Status:						
Cleanup History Link:		https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605901769&tabname=regulatoryhistory				
Potential COC:		GASOLINE				
Potential Media of Concern:		SOIL				
File Location:		LOCAL AGENCY				
User Defined Beneficial Use:						
Designated Beneficial Use:		MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.				
DWR GW Sub Basin:		Coastal Plain Of Orange County (8-001)				
Calwater Watershed Name:		Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)				
Post Closure Site Management:						
Future Land Use:						
Cleanup Oversight Agencies:		ORANGE COUNTY LOP (LEAD) - CASE #: 94UT037 SANTA ANA RWQCB (REGION 8) - CASE #: 083002491T				
CUF Claim No:						
CUF Priority Assig:						
CUF Amount Paid:						
WDR Place Type:						
WDR File No:						
WDR Order No:						
Project Oversight Agencies:						
Facility Type:						
Composting Method:						
Grndwtr Monitoring Frequency:						
Designated Beneficial Use Desc:		Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.				
Site History:						
No site history available						

GeoTracker Search - Cleanup Status History

Status:	Completed - Case Closed
Date :	3/7/1995
Status:	Open - Case Begin Date
Date :	7/21/1994

GeoTracker Search - Regulatory Activities

Action Type:	Leak Action
Action:	Leak Reported
Action Date:	7/21/1994
Received Issue Date:	
Doc Link:	
Title Description Comments:	
Action Type:	Leak Action
Action:	Leak Discovery
Action Date:	7/21/1994
Received Issue Date:	
Doc Link:	
Title Description Comments:	

15	3 of 4	ESE	0.15 / 782.79	71.28 / -2	Mobil #18-Goe 13521 Brookhurst St Garden Grove Ca 92643 CA	LOP ORANGE
--------------------	--------	-----	---------------	------------	---	------------

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Case ID:	94UT037					
Details						
Current Status:		Closed				
Type of Closure:		Closure certification issued				
Closed Date:		3/7/1995				
File Location:		Local Agency				
15	4 of 4	ESE	0.15 / 782.79	71.28 / -2	MOBIL #18-G03E 13521 BROOKHURST ST GARDEN GROVE CA	UST SWEEPS
C C:	A30-000-2129			D Filename:	SITE12A	
BOE:	44-000400			Page No:	123	
Comp:	2129			County:	ORANGE	
Status:	ACTIVE			State :	CA	
No of Tanks:	4			Zip:	92643	
Jurisdic:	ORANGE COUNTY			Latitude:	33.766349	
Agency:	ENVIRONMENTAL HEALTH			Longitude:	-117.955186	
Phone:				Georesult:	S5HPNTSC-A	
Tank Details						
Tank ID:	000004			S Contain:		
O Tank ID:				Stg:	P	
SWRCB No:	30-000-002129-000004			Storage :		
Removed:				Storag Type:	PRODUCT	
Installed:				P Contain:		
A Date:				Content:	REG UNLEADED	
Capac:	8000			ONA:		
Tank Use:	M.V. FUEL			D File Name:	TANK12A	
Tank Details						
Tank ID:	000001			S Contain:		
O Tank ID:				Stg:	P	
SWRCB No:	30-000-002129-000001			Storage :		
Removed:				Storag Type:	PRODUCT	
Installed:				P Contain:		
A Date:				Content:		
Capac:	550			ONA:		
Tank Use:	PETROLEUM			D File Name:	TANK12A	
Tank Details						
Tank ID:	000003			S Contain:		
O Tank ID:				Stg:	P	
SWRCB No:	30-000-002129-000003			Storage :		
Removed:				Storag Type:	PRODUCT	
Installed:				P Contain:		
A Date:				Content:	REG UNLEADED	
Capac:	6000			ONA:		
Tank Use:	M.V. FUEL			D File Name:	TANK12A	
Tank Details						
Tank ID:	000005			S Contain:		
O Tank ID:				Stg:	P	
SWRCB No:	30-000-002129-000005			Storage :		
Removed:				Storag Type:	PRODUCT	
Installed:				P Contain:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
A Date:				Content:	REG UNLEADED	
Capac:				ONA:		
Tank Use:				D File Name:	TANK12A	

16	1 of 12	ESE	0.15 / 811.75	72.89 / -1	BP WEST COAST PRODUCTS LLC NO 0629 13482 BROOKHURST ST GARDEN GROVE CA 92643	RCRA SQG
--------------------	---------	-----	---------------	------------	---	----------

Handler ID: CAR000174276
Generator Status: SQG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	NAIC 1:	44711
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20060606	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:	P	Location Latitude:	33.767089
In Handler Univ:	Y	Location Longitude:	-117.954867
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	SQG	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20060620				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		BP WEST COAST PRODUCTS LLC NO 0629				
Location Street No:						
Location Street1:		13482 BROOKHURST ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92643				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		WASTE SPECIALIST				
Contact Street No:						
Contact Street1:		PO BOX 80249				
Contact Street2:						
Contact City:		RANCHO SANTA MARGARITA				
Contact State:		CA				
Contact Zip:		92688				
Contact Country:		US				
Contact Phone And Ext:		714-670-3958				
Contact Fax:						
Contact Email Address:						
Contact Title:						
Owner Name:		BP WEST COAST PRODUCTS LLC				
Owner Type:		P				
Owner Seq:		2				
Operator Name:		BP WEST COAST PRODUCTS LLC				
Operator Type:		P				
Operator Seq:		1				
Public Notes:						

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20060606
Handler Name:	BP WEST COAST PRODUCTS LLC NO 0629
Fed Waste Generator:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification

Waste Code Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Waste Code:		D001				
Waste Code Desc:		IGNITABLE WASTE				
Waste Code:		D018				
Waste Code Desc:		BENZENE				
<hr/>						
<u>Owner/Operator Details</u>						
Owner/Operator Ind:	Current Owner				Street No:	
Type:	Private				Street1:	
Name:	BP WEST COAST PRODUCTS LLC				Street2:	
Dt Became Current:	19501231				City:	
Dt Ended Current:					State:	
Phone:					Country:	US
Source Type:	Notification				Zip:	
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Private				Street1:	
Name:	BP WEST COAST PRODUCTS LLC				Street2:	
Dt Became Current:	19501231				City:	
Dt Ended Current:					State:	
Phone:					Country:	US
Source Type:	Notification				Zip:	
<hr/>						
16	2 of12	ESE	0.15 / 811.75	72.89 / -1	Gammo Corporation 13482 Brookhurst St Garden Grove, Ca 92843-3119 Garden Grove CA	UST ORANGE
FA No:		FA0052965				
SR No:						
Notes:						
Data Source:		Permitted Underground Storage Tank (UST) Facilities Listing				
<hr/>						
16	3 of12	ESE	0.15 / 811.75	72.89 / -1	ARCO #629 13482 BROOKHURST GARDEN GROVE CA 92844	LUST
Global ID:	T0605901913				Case Type (DL):	LUST Cleanup Site
Site Facility Type:	LUST CLEANUP SITE				Oil Field (SRCH):	
Site Fac Type (SRCH):	LUST CLEANUP SITE				Oil Field Oper (SRCH):	
Status:					Census Tract (SRCH):	6059088702
Status (SRCH):	COMPLETED - CASE CLOSED				Latitude (DL):	33.7677034
Status (DL):	Completed - Case Closed				Longitude (DL):	-117.9548174
Status Date (DL):	11/17/2005				RWQCB Region (DL):	SANTA ANA RWQCB (REGION 8)
Cleanup Status:	COMPLETED - CASE CLOSED					
Site Facility Name (SRCH):	ARCO #629					
Address (SRCH):	13482 BROOKHURST					
City (SRCH):	GARDEN GROVE					
Zip (SRCH):	92844					
County (SRCH):	ORANGE					
Street No (DL):	13482					
Street Name (DL):	BROOKHURST					
City (DL):	GARDEN GROVE					
Zip (DL):	92844					
County (DL):	Orange					
State (DL):	CA					
Business Name (DL):	ARCO #629					
Site Facility Name:	ARCO #629					
Address :	13482 BROOKHURST					
City :	GARDEN GROVE					
Zip :	92844					
County :	ORANGE					
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

GeoTracker Sites Data Download - Site Details

CUF Case:
Lead Agency: ORANGE COUNTY LOP
Case Worker:
Local Agency:
RB Case No: 083002773T
Local Case No: 95UT062
File Location: Local Agency Warehouse
Potential COC: Gasoline
Potential Media of Concern: Other Groundwater (uses other than drinking water)
Begin Date: 9/28/1995
How Discovered: Tank Closure
How Discovered Description:
Stop Method: Close and Remove Tank
Stop Description:
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name: Coastal Plain Of Orange County (8-001)
Disadvantaged Community:
CalEnvScreen Score:
Coordinate Source: * Historical Geocode - Exact Address Match
Discharge Cause:
Discharge Source: Tank
EPA Region: 9
Leak Reported Dt: 1995-09-28 00:00:00
Military DoD Site: No
No Further Action Dt: 2005-11-17 00:00:00
Qty Rlsd Gallons: 0
Facility Project Sub Type:
Calenviroscreen 3 Score: 51-55%
Calenviroscreen 4 Score: 60-65%
A2022 Assembly District: 70
Claim No: 15304
Claim Status: Ineligible
A2022 Congressional District: 45
A2022 Senate District: 36
Site History:

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: JESSICA LAW
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 Main Street, Suite 500
City: RIVERSIDE
Email: jessica.law@waterboards.ca.gov
Phone No: 9517824381

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 11/17/2005

Status: Open - Site Assessment
Status Date: 7/25/2000

Status: Open - Site Assessment
Status Date: 1/16/1996

Status: Open - Site Assessment
Status Date: 10/5/1995

Status: Open - Case Begin Date
Status Date: 9/28/1995

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

GeoTracker Search - Regulatory Profile

Site Facility Name: ARCO #629
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 13482 BROOKHURST
City: GARDEN GROVE
Zip: 92844
County: ORANGE
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605901913
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 11/17/2005
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605901913&tabname=regulatoryhistory
Potential COC: GASOLINE
Potential Media of Concern: OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)
File Location: LOCAL AGENCY WAREHOUSE
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
DWR GW Sub Basin: Coastal Plain Of Orange County (8-001)
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: ORANGE COUNTY LOP (LEAD) - CASE #: 95UT062
SANTA ANA RWQCB (REGION 8) - CASE #: 083002773T
CASE MANAGER: JESSICA LAW
15304
CUF Claim No: D
CUF Priority Assig: \$0
CUF Amount Paid:
WDR Place Type:
WDR File No:
WDR Order No:
Project Oversight Agencies:
Facility Type:
Composting Method:
Grndwtr Monitoring Frequency:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
Site History:

No site history available

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 11/17/2005

Status: Open - Site Assessment
Date : 7/25/2000

Status: Open - Site Assessment
Date : 1/16/1996

Status: Open - Site Assessment
Date : 10/5/1995

Status: Open - Case Begin Date
Date : 9/28/1995

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Action Date: 11/16/2005

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Received Issue Date:		11/16/2005				
Doc Link:		https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605901913&enforcement_id=5958429&temptable=ENFORCEMENT				
Title Description Comments:		ISSUED CLOSURE LETTER.				
Action Type:		Other Regulatory Actions				
Action:		Staff Letter				
Action Date:		1/8/2004				
Received Issue Date:		1/8/2004				
Doc Link:						
Title Description Comments:		ISSUED DEPTH-DISCRETE MONITORING WELL INSTALLATION WORKPLAN APPROVAL LETTER.				
Action Type:		Other Regulatory Actions				
Action:		Staff Letter				
Action Date:		12/15/2003				
Received Issue Date:		12/15/2003				
Doc Link:						
Title Description Comments:		ISSUED REQUEST FOR DEPTH-DISCRETE MONITORING WELL INSTALLATION WORKPLAN.				
Action Type:		Other Regulatory Actions				
Action:		Staff Letter				
Action Date:		9/3/2003				
Received Issue Date:		9/3/2003				
Doc Link:						
Title Description Comments:		ISSUED ADDITIONAL ASSESSMENT WORKPLAN APPROVAL LETTER.				
Action Type:		Other Regulatory Actions				
Action:		Staff Letter				
Action Date:		7/23/2003				
Received Issue Date:		7/23/2003				
Doc Link:						
Title Description Comments:		ISSUED REQUEST FOR ASSESSMENT WORKPLAN WITHIN 30 DAYS.				
Action Type:		Leak Action				
Action:		Leak Discovery				
Action Date:		10/5/1995				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Leak Action				
Action:		Leak Began				
Action Date:		10/5/1995				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Leak Action				
Action:		Leak Reported				
Action Date:		9/28/1995				
Received Issue Date:						
Doc Link:						
Title Description Comments:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

GeoTracker Search - Site Maps

Submitted: 9/15/2005
Submitted By: DELTA ENVIRONMENTAL (CONTRACTOR)
Title: GEO_MAP
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/2866779923/T0605901913.pdf

Submitted: 2/5/2002
Submitted By: DELTA ENVIRONMENTAL (CONTRACTOR)
Title: GEO_MAP
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/6108747184/T0605901913.pdf

GeoTracker Search - Documents

Document Type: Site Documents
Type: REPORTS - OTHER
Submitted By: DELTA ENVIRONMENTAL (CONTRACTOR)
Title: WELL DESTRUCTION REPORT **Note: Many records provided by the department have a truncated [Title] field.
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8135587394/T0605901913.PDF

Document Type: Site Documents
Type:
Submitted By: (REGULATOR)
Title: REMEDIAL ACTION COMPLETION CERTIFICATION **Note: Many records provided by the department have a truncated [Title] field.
Title Link: https://geotracker.waterboards.ca.gov/site_documents/2353718400/95UT062%2Epdf

Document Type: Site Documents
Type:
Submitted By: (REGULATOR)
Title: CASE CLOSURE SUUMARY **Note: Many records provided by the department have a truncated [Title] field.
Title Link: https://geotracker.waterboards.ca.gov/site_documents/1810444474/95UT062%2Epdf

Document Type: Monitoring Reports
Type: MONITORING REPORT - QUARTERLY
Submitted By: DELTA ENVIRONMENTAL (CONTRACTOR)
Title: 4TH QUARTER 2005 MONITORING REPORT **Note: Many records provided by the department have a truncated [Title] field.
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9443194329/T0605901913.PDF

Document Type: Site Documents
Type: CLOSURE/NO FURTHER ACTION LETTER
Submitted By: (REGULATOR), PAMELA YBARRA (REGULATOR)
Title: ISSUED CLOSURE LETTER.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605901913&enforcement_id=5958429

Document Type: Monitoring Reports
Type: MONITORING REPORT - QUARTERLY
Submitted By: DELTA ENVIRONMENTAL (CONTRACTOR)
Title: 3RD QUARTER 2005 MONITORING REPORT **Note: Many records provided by the department have a truncated [Title] field.
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3985364615/T0605901913.PDF

Document Type: Monitoring Reports
Type: MONITORING REPORT - QUARTERLY
Submitted By: DELTA ENVIRONMENTAL (CONTRACTOR)
Title: 3RD QUARTER 2005 MONITORING REPORT **Note: Many records provided by the department have a truncated [Title] field.
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7380963981/T0605901913.PDF

Document Type: Monitoring Reports
Type: MONITORING REPORT - QUARTERLY
Submitted By: DELTA ENVIRONMENTAL (CONTRACTOR)
Title: SECOND QUARTER 2005 QMR **Note: Many records provided by the department have a truncated [Title] field.
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9047256290/T0605901913.PDF

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Document Type:	Site Documents	Document Date:	4/20/2005
Type:	REPORTS - OTHER	Submitted:	
Submitted By:	DELTA ENVIRONMENTAL (CONTRACTOR)		
Title:	SOIL SAMPLING REPORT **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6452756583/T0605901913.PDF		

Document Type:	Monitoring Reports	Document Date:	4/5/2005
Type:	MONITORING REPORT - QUARTERLY	Submitted:	
Submitted By:	DELTA ENVIRONMENTAL (CONTRACTOR)		
Title:	FIRST QUARTER 2005 QMR **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8149457633/T0605901913.PDF		

16	4 of 12	ESE	0.15 / 811.75	72.89 / -1	LIAQUAT ALI JUMANI 13482 BROOKHURST ST GARDEN GROVE CA 92643	HHSS
--------------------	---------	-----	---------------	------------	--	------

County:
Tank Details Microfiche: <http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002e4f6.pdf>

16	5 of 12	ESE	0.15 / 811.75	72.89 / -1	GAMMO CORP 13482 BROOKHURST ST GARDEN GROVE CA 92843	UST
--------------------	---------	-----	---------------	------------	--	-----

Facility ID: FA0052965 **CERS ID:** 10512283
Site Facility Type: PERMITTED UNDERGROUND STORAGE TANK (UST)
Note: Information related to facilities can be searched on Geo Tracker Website: <https://geotracker.waterboards.ca.gov/search>

Permitted UST Tank Details

Epa Region:	9	Tank Closure Date:	
No. of Closed UST:	0	Tank Configuration:	Stand Alone Tank
No. of Inuse UST:		Tank Contents:	Premium Unleaded
No. of Oos UST:	0	Tank Cp Impr Curr:	No
Owner Type:	Non-Government	Tank Cp Shutoff:	Yes
Tank ID No.:	3	Tank Installatn Dt:	1/1/2000 12:00:00 AM
Tank Status:	Confirmed/Updated Information	Tank No of Compart:	1
Tank Type:	Double Wall	Tank Pc Constructn:	Fiberglass
Tank Alarms:	No	Tank Spill Bucket:	Yes
Tank Ball Float:	No	Tribal Lands:	No
Tank Operator Name:	GAMMO CORP		
Tank Operator Mail Address:	13482 BROOKHURST ST		
Tank Operator Mail City:	GARDEN GROVE		
Tank Operator Mail State:	CA		
Tank Operator Mail Zip:	92843		
Tank Owner Name:	GAMMO CORP		
Tank Owner Mailing Address:	13482 BROOKHURST ST		
Tank Owner Mailing City:	GARDEN GROVE		
Tank Owner Mailing State:	CA		
Tank Owner Mailing Zip:	92843		
Tank Capacity Gallons:	10000		
Tank Piping Construction:	Double Walled		
Tank Piping Type:	Pressure		
Tank Pw Piping Construction:	Fiberglass		
Tank Sacrificial Anode:	No		

Permitted UST Tank Details

Epa Region:	9	Tank Closure Date:	
No. of Closed UST:	0	Tank Configuration:	Stand Alone Tank
No. of Inuse UST:		Tank Contents:	Regular Unleaded
No. of Oos UST:	0	Tank Cp Impr Curr:	No
Owner Type:	Non-Government	Tank Cp Shutoff:	Yes
Tank ID No.:	2	Tank Installatn Dt:	1/1/2000 12:00:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank Status:	Renewal Permit				Tank No of Compart:	1
Tank Type:	Double Wall				Tank Pc Constructn:	Fiberglass
Tank Alarms:	No				Tank Spill Bucket:	Yes
Tank Ball Float:	No				Tribal Lands:	No
Tank Operator Name:	GAMMO CORP					
Tank Operator Mail Address:	13482 BROOKHURST ST					
Tank Operator Mail City:	GARDEN GROVE					
Tank Operator Mail State:	CA					
Tank Operator Mail Zip:	92843					
Tank Owner Name:	GAMMO CORP					
Tank Owner Mailing Address:	13482 BROOKHURST ST					
Tank Owner Mailing City:	GARDEN GROVE					
Tank Owner Mailing State:	CA					
Tank Owner Mailing Zip:	92843					
Tank Capacity Gallons:	10000					
Tank Piping Construction:	Double Walled					
Tank Piping Type:	Pressure					
Tank Pw Piping Construction:	Fiberglass					
Tank Sacrificial Anode:	No					

Permitted UST Tank Details

Epa Region:	9				Tank Closure Date:	
No. of Closed UST:	0				Tank Configuration:	Stand Alone Tank
No. of Inuse UST:					Tank Contents:	Regular Unleaded
No. of Oos UST:	0				Tank Cp Impr Curr:	No
Owner Type:	Non-Government				Tank Cp Shutoff:	Yes
Tank ID No.:	1				Tank Installatn Dt:	1/1/2000 12:00:00 AM
Tank Status:	Renewal Permit				Tank No of Compart:	1
Tank Type:	Double Wall				Tank Pc Constructn:	Fiberglass
Tank Alarms:	No				Tank Spill Bucket:	Yes
Tank Ball Float:	No				Tribal Lands:	No
Tank Operator Name:	GAMMO CORP					
Tank Operator Mail Address:	13482 BROOKHURST ST					
Tank Operator Mail City:	GARDEN GROVE					
Tank Operator Mail State:	CA					
Tank Operator Mail Zip:	92843					
Tank Owner Name:	GAMMO CORP					
Tank Owner Mailing Address:	13482 BROOKHURST ST					
Tank Owner Mailing City:	GARDEN GROVE					
Tank Owner Mailing State:	CA					
Tank Owner Mailing Zip:	92843					
Tank Capacity Gallons:	10000					
Tank Piping Construction:	Double Walled					
Tank Piping Type:	Pressure					
Tank Pw Piping Construction:	Fiberglass					
Tank Sacrificial Anode:	No					

Permitted UST Tank Details

Epa Region:	9				Tank Closure Date:	
No. of Closed UST:	0				Tank Configuration:	Stand Alone Tank
No. of Inuse UST:					Tank Contents:	Diesel
No. of Oos UST:	0				Tank Cp Impr Curr:	No
Owner Type:	Non-Government				Tank Cp Shutoff:	Yes
Tank ID No.:	4				Tank Installatn Dt:	1/1/2000 12:00:00 AM
Tank Status:	Renewal Permit				Tank No of Compart:	1
Tank Type:	Double Wall				Tank Pc Constructn:	Fiberglass
Tank Alarms:	No				Tank Spill Bucket:	Yes
Tank Ball Float:	No				Tribal Lands:	No
Tank Operator Name:	GAMMO CORP					
Tank Operator Mail Address:	13482 BROOKHURST ST					
Tank Operator Mail City:	GARDEN GROVE					
Tank Operator Mail State:	CA					
Tank Operator Mail Zip:	92843					
Tank Owner Name:	GAMMO CORP					
Tank Owner Mailing Address:	13482 BROOKHURST ST					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank Owner Mailing City:		GARDEN GROVE				
Tank Owner Mailing State:		CA				
Tank Owner Mailing Zip:		92843				
Tank Capacity Gallons:		10000				
Tank Piping Construction:		Double Walled				
Tank Piping Type:		Pressure				
Tank Pw Piping Construction:		Fiberglass				
Tank Sacrificial Anode:		No				

Permitted UST Site Details

CERS ID:	10512283	CalEnviroScrn 4 Pct:	60-65%
Facility ID:	FA0052965	Latitude:	33.76712
Permitting Agency:	Orange County Environmental Health	Longitude:	-117.9544
Senate District:	36	County:	Orange
Congress District:	45		

16	6 of 12	ESE	0.15 / 811.75	72.89 / -1	GAMMO C30P30ATION 13482 BROOKHURST ST GARDEN GROVE CA 92843	EMISSIONS
--------------------	---------	-----	---------------	------------	---	-----------

2015 Toxic Data

Facility ID:	157786	COID:	ORA
Facility SIC Code:	5541	DISN:	SOUTH COAST AQMD
CO:	30	CHAPIS:	
Air Basin:	SC	CERR Code:	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

16	7 of 12	ESE	0.15 / 811.75	72.89 / -1	Arco #629 13482 Brookhurst St Garden Grove Ca 92843-3119 CA	LOP ORANGE
--------------------	---------	-----	---------------	------------	--	------------

Case ID: 95UT062

Details

Current Status:	Closed
Type of Closure:	Closure certification issued
Closed Date:	11/17/2005
File Location:	Warehouse

16	8 of 12	ESE	0.15 / 811.75	72.89 / -1	GAMMO CORP 13482 BROOKHURST ST GARDEN GROVE CA 92843	CERS TANK
--------------------	---------	-----	---------------	------------	--	-----------

Site ID:	393660
Latitude:	33.767120
Longitude:	-117.954399

Regulated Programs

EI ID:	10512283
EI Description:	Underground Storage Tank

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violations

Violation Date:	12/22/2014	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2636(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)		
Violation Notes:			

Returned to compliance on 12/22/2014. The diesel turbine sump 208 sensor failed and was replaced this date.

Violation Description:

Failure to continuously monitor the interstitial space of the tank, piping and/or sumps sump such that the leak detection activates an audible/visual alarm when a leak is detected.

Violations

Violation Date:	05/19/2015	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2715(a) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(a)		
Violation Notes:			

Returned to compliance on 05/28/2015. Please submit a current statement identifying the designated UST operator for the facility to an approved electronic reporting database within 30 days.

Violation Description:

Failure to submit statement of UST compliance and/or Designated Operator certification.

Violations

Violation Date:	12/28/2018	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)		
Violation Notes:			

Returned to compliance on 12/28/2018. OBSERVATION: 87 AUX STP VR208 sensor failed testing. CORRECTIVE ACTION: Sensor was replaced with another VR208 which was tested and passed; issue corrected on site.

Violation Description:

Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.

Violations

Violation Date:	12/03/2024	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.7 25284.2 - California Health and Safety Code, Chapter 6.7, Section(s) 25284.2		
Violation Notes:			

Returned to compliance on 12/03/2024. Premium spill container failed initial testing.

Violation Description:

"Failure to meet one or more of the following requirements:

Install or maintain a liquid-tight spill container.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill container.

Be resistant to galvanic corrosion.

Perform a tightness test at installation, every 12 months thereafter, or within 30 days after a repair to the spill container.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

Tested using applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Tested by a certified UST service technician.

Maintain records of spill containment testing for 36 months.

"

Violations

Violation Date: 12/22/2014
Violation Program: HW
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Returned to compliance on 12/22/2014. The facility has one drum of waste fuel contaminated absorbent/ filters that had an incomplete hazardous waste label. The label was completed this date and the violation was abated

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 12/20/2019
Violation Program: UST
Citation: 23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Returned to compliance on 03/11/2020. Designated UST Operator visual inspections have not been completed at least once every 30 days and signed/dated by the owner/operator within 48 hours of receiving the report. The following inspections were conducted past the 30 day time frame: - 7/17/19 - 9/22/19 - 11/25/19 Complete the January Designated UST Operator visual inspection report within 30 days of the December inspection report and provide a copy to this Agency within 30 days.

Violation Description:

For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements:
 Be performed by an ICC certified DO.
 Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy.
 Inspect for the presence of liquid/debris in spill containers.
 Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly.
 Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit.
 Check that all testing and maintenance has been completed and documented.
 Verify that all facility employees have been trained in accordance with 23 CCR 2715(c).
 For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.

Violations

Violation Date: 12/28/2018
Violation Program: UST
Citation: 23 CCR 16 2712(b)(1)(G) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(G)
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Returned to compliance on 10/21/2019. OBSERVATION: ATG with audible/visual and ball floats were not tested during the monitoring cert.
 CORRECTIVE ACTION: Have these components observed and tested and submit results to this Agency within 30 days.

Violation Description:

Failure to comply with one or more of the following overfill prevention equipment requirements:
 Alert the transfer operator when the tank is 90 percent full by restricting the flow into the tank or triggering an audible and visual alarm; or
 Restrict delivery of flow to the tank at least 30 minutes before the tank overfills, provided the restriction occurs when the tank is filled to no more than 95 percent of capacity; and activate an audible alarm at least five minutes before the tank overfills; or

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

Provide positive shut-off of flow to the tank when the tank is filled to no more than 95 percent of capacity; or
Provide positive shut-off of flow to the tank so that none of the fittings located on the top of the tank are exposed to product due to overfilling.

Install/retrofit overfill prevention equipment that does not use flow restrictors on vent piping to meet overfill prevention equipment requirements when the overfill prevention equipment is installed, repaired, or replaced on and after October 1, 2018.

For USTs installed before October 1, 2018, perform an inspection by October 13, 2018 and every 36 months thereafter.

For USTs installed on and after October 1, 2018, perform an inspection at installation and every 36 months thereafter.

Inspected within 30 days after a repair to the overfill prevention equipment.

Inspected using an applicable manufacturer guidelines, industry codes, engineering standards, or a method approved by a professional engineer.

Inspected by a certified UST service technician.

Maintain records of overfill prevention equipment inspection for 36 months.

Violations

Violation Date: 12/03/2024
Violation Program: HMRRP
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

Facility's hazardous materials inventory, last submitted to CERS on 01/02/2024, is inaccurate. Submittal did not include reportable propane that was observed onsite at time of inspection.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violations

Violation Date: 12/08/2020
Violation Program: HMRRP
Citation: HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)
Violation Notes:

Returned to compliance on 12/10/2020. Site map does not list the correct fuel product tanks on site. Please change the fuel tank listed as "midgrade" to "diesel". Submit corrections to this Agency via CERS at <http://cers.calepa.ca.gov/> within 30 days.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date: 12/16/2022
Violation Program: UST
Citation: 23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Notes:

Returned to compliance on 02/10/2023. Designated operator monthly inspections have the incorrect secondary containment test date. DO is incorrectly referencing the retest date of 4/10/2020.

Violation Description:

For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements:
Be performed by an ICC certified DO.
Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy.
Inspect for the presence of liquid/debris in spill containers.
Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit.
 Check that all testing and maintenance has been completed and documented.
 Verify that all facility employees have been trained in accordance with 23 CCR 2715(c).
 For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.

Violations

Violation Date: 08/16/2019
Violation Program: UST
Citation: HSC 6.7 25284 - California Health and Safety Code, Chapter 6.7, Section(s) 25284
Violation Notes:

Returned to compliance on 04/23/2020. OBSERVATION: Facility does not have a Permit to Operate UST system issued by this Agency. CORRECTIVE ACTION: Address all open violations within 30 days to receive a Permit to Operate.

Violation Description:

Failure to obtain a valid permit to operate from the UPA including but not limited to unpaid permit fees.

Violations

Violation Date: 12/29/2021
Violation Program: UST
Citation: HSC 6.7 25292.1(a) - California Health and Safety Code, Chapter 6.7, Section(s) 25292.1(a)
Violation Notes:

Returned to compliance on 12/20/2022. The Overfill prevention at site does not meet state code and must be repaired and the monitoring plan on CERS for each tank must be corrected after repairs are made.

Violation Description:

Failure to operate the UST system to prevent unauthorized releases including leaks, spills, and/or overfills.

Violations

Violation Date: 12/20/2019
Violation Program: UST
Citation: 23 CCR 16 2712(b)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(2)
Violation Notes:

Returned to compliance on 01/13/2020. Owner/Operator failed to maintain monitoring records for release detection (e.g., alarm logs) and/or retain records of appropriate follow-up actions (e.g. maintenance records). Facility did not retain the maintenance record for the fuel alarm that occurred at UDC 9-10 on 6/11/2019. Please provide documentation for response to fuel alarm from 6/11/2019 to this Agency within 30 days.

Violation Description:

Failure to maintain monitoring records for release detection and/or maintain records of appropriate follow-up actions.

Violations

Violation Date: 03/09/2020
Violation Program: UST
Citation: 23 CCR 16 2638(d) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2638(d)
Violation Notes:

Returned to compliance on 03/11/2020. Facility has not submitted Monitoring System Certification and Spill Bucket test results dated 12/20/2019 to this Agency within 30 days of testing. Submit a copy of test results to this Agency immediately.

Violation Description:

Failure to submit the "Monitoring System Certification Form" to the UPA within 30 days of completion of the test.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violations

Violation Date: 12/20/2019
Violation Program: UST
Citation: HSC 6.7 25284 - California Health and Safety Code, Chapter 6.7, Section(s) 25284
Violation Notes:

Returned to compliance on 05/06/2020. Facility does not have a Permit to Operate UST system issued by this Agency. Address all open violations within 30 days to receive a Permit to Operate.

Violation Description:

Failure to obtain a valid permit to operate from the UPA including but not limited to unpaid permit fees.

Violations

Violation Date: 12/08/2020
Violation Program: UST
Citation: 23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Notes:

Returned to compliance on 01/07/2021. Facility did not comply with the following requirements: - Fuel alarm on 8/21/20 for 91 STP was not listed on the 9/16/20 DO report. - DO reports dated 6/17/20 & 8/18/20 were not conducted within 30 days of the previous report. - The Owner/Operator has not signed the following DO reports within 72 hours of receipt from DO (48 hours for reports completed prior to October): - 7/17/20, 8/18/20, 9/16/20, 10/16/20, 11/16/20 - The required testing dates listed on all 2020 DO reports are incorrect. The following testing dates should be corrected and listed as: - Monitoring System Certification: 12/20/2019 - Secondary Containment: 12/20/2019 Provide corrected copies of reports containing incorrect testing dates, missing fuel alarms, and provide a copy of the December DO report demonstrating that it has been conducted within the required time frame and has been signed by the owner/operator within 72 hours of receipt. Corrections must be [Truncated]

Violation Description:

For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO. Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy. Inspect for the presence of liquid/debris in spill containers. Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly. Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit. Check that all testing and maintenance has been completed and documented. Verify that all facility employees have been trained in accordance with 23 CCR 2715(c). For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.

Violations

Violation Date: 12/28/2018
Violation Program: UST
Citation: HSC 6.7 25284, 25286 - California Health and Safety Code, Chapter 6.7, Section(s) 25284, 25286
Violation Notes:

Returned to compliance on 01/13/2020. OBSERVATION: UST submittal through the California Environmental Reporting System (CERS) requires corrections. CORRECTIVE ACTION: Please see regulator comments on CERS and make appropriate changes to the UST submittal and submit within 30 days.

Violation Description:

Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.

Violations

Violation Date: 12/28/2018
Violation Program: UST
Violation Source: CERS
Violation Division: Orange County Environmental Health

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Citation: 23 CCR 16 2711(a)(8) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2711(a)(8)

Violation Notes:

Returned to compliance on 12/05/2019. OBSERVATION: Plot Plan indicates site has a mid-grade tank. Confirmed on site that tank in question is a diesel tank. CORRECTIVE ACTION: Make corrections to the Plot Plan to reflect this and submit to this Agency via California Environmental Reporting System within 30 days.

Violation Description:

Failure to submit or maintain a current facility plot plan.

Violations

Violation Date:	12/20/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.7 25284, 25286 - California Health and Safety Code, Chapter 6.7, Section(s) 25284, 25286		
Violation Notes:			

Returned to compliance on 12/20/2019. UST submittal through the California Environmental Reporting System (CERS) requires corrections. Please see regulator comments on CERS and make appropriate changes to the UST submittal. Re-submit within 30 days.

Violation Description:

Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.

Violations

Violation Date:	12/22/2014	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	Un-Specified		
Violation Notes:			

Returned to compliance on 05/28/2015. The facility has not submitted the tank facility CUPA forms, financial assurance, CFO statement,, and owner statement of DO. The forms must be submitted on CERS or E submit .

Violation Description:

UST Program - Administration/Documentation - For use of Local Ordinance only

Violations

Violation Date:	03/11/2020	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.7 25291(a)(2) - California Health and Safety Code, Chapter 6.7, Section(s) 25291(a)(2)		
Violation Notes:			

Returned to compliance on 04/23/2020. Secondary containment has not been properly maintained as evidenced by failed test results dated 12/20/2019 for the Product Piping Sump, Fill Sump, and UDC 3/4. Repair the secondary containment, re-test, and re-submit passing test results to this Agency within 30 days.

Violation Description:

Failure to maintain secondary containment (e.g., failure of secondary containment testing).

Violations

Violation Date:	12/28/2018	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)		
Violation Notes:			

Returned to compliance on 01/29/2019. OBSERVATION: Response Plan must be signed. CORRECTIVE ACTION: Please re-submit the Leak

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Response Plan with owner signature through CERS within 30 days.

Violation Description:

Failure to have an approved UST Response Plan.

Violations

Violation Date:	05/19/2015	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34		
Violation Notes:			

Returned to compliance on 05/28/2015. Please submit a current Certification of Financial Responsibility, with supporting documents, to an approved electronic reporting database within 30 days.

Violation Description:

Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.

Violations

Violation Date:	12/28/2018	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)		
Violation Notes:			

Returned to compliance on 06/11/2019. OBSERVATION: 87 Main PLLD failed testing. CORRECTIVE ACTION: Make necessary repairs and retest and submit results to this Agency within 30 days.

Violation Description:

Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.

Evaluations

Eval Date:	01/13/2020
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

This Agency has received a copy of the work order documentation for the fuel alarm that occurred at UDC 9-10 on 6/11/2019 at this facility. Violation I122 has been corrected. The following violations remain outstanding and must be corrected immediately: - I481: Failure to obtain a valid permit to operate a UST. - I106: Failure to conduct the designated UST operator visual inspection at least once every 30 days. Please submit all documents to this Agency within 30 days.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	02/14/2017
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Reviewed CERS submittal and it was not accepted. Reviewed and not accepted The submittal must include the date installed on the Tank information page for each tank. Include and updated financial responsibility form and updated Statement of DO form; Note: data in [EVAL Notes] field for some

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

records is truncated from the source.

Eval Date: 12/20/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

On site to witness annual monitoring certification and spill bucket test and conduct UST inspection. Tester: Byron Cruz, Clean Air Testing. Tester certifications (VR, ICC, VMI) were verified. Tanks: - 87 main (10,000 gal) - 87 aux (10,000 gal) - 91 (10,000 gal) - Diesel (10,000 gal) Monitoring Panel: Veeder Root TLS-350 Annulars: - All tanks have VR407 Fill/STP/UDC sumps + Vent Sump - VR208 All liquid detection sensors were tested on site. Positive shutdown, fail safe and sensor out were verified. LLD: - All STPs have VR PLLD All LLDs were tested on site. Facility has a submittal in CERS. The following documents were available for review on site: - Monitoring Plan + Tank Pages - Response Plan - Certificate of Financial Responsibility w/ CFO Letter - DO Agreement - Statement of Understanding and Compliance - DO Training - DO Monthly Reports - Overfill Prevention Equipment Test last conducted on 4/9/19, must be conducted every [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/23/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This Agency has received the following re-test results dated 4/10/2020 in CERS and results indicate that the previously failed components have PASSED: - Overfill Prevention: - Product Piping Sump (87 Master, 87 Siphon, 91, Diesel) - Fill Sump (87 Master, 87 Siphon, 91, Diesel) - UDC 3/4 The following violations have been corrected: - I382: Failure to maintain secondary containment. - I481: Failure to obtain a valid permit to operate from the CUPA. There are no remaining violations for this facility as of this date.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/05/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

On site for routine UST inspection, monitoring system certification and spill bucket testing. The facility has four double-walled tanks (87, 87, 91, Diesel) monitored by a Veeder Root TLS-350 system. The monitor is operational for audible and visual alarms. Positive shutdown and fail safe programming were verified for pressurized piping. Flapper valves are used for overfill prevention. The following sensors are installed and were determined to be operational: Tank annular- 407 Turbine sumps- 208 Fill sumps- 208 UDCs- 208 Line leak detectors: PLLD/electronic Testing was conducted by Luis Rivera of Universal Nozzle. Technician certifications (VR, ICC, VMI) were verified. Please submit the test reports to this Agency within 30 days. The following documents are available for review: permit to operate, leak response plan, monitoring plan, test reports, DO monthly reports, and DO annual employee training records. Secondary containment testing was last conducted on 12/20/2022. Overfill p; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/16/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERS submittal 10512283 was not accepted. A site plan must be submitted on CERS and the CO2 must be removed from disclosure 120 cubic feet reported and if less than 1000 cubic feet it is not a reportable quantity; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/12/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Annual monitor certification being performed by Steve Loera. ICC , VMI, and Veederroot Certification were up to date. Testing passed this date; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/22/2014
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by the manager, Joseph hamoush. The facility has an active EPA ID # CAL000338171 Manifests from Able Environmental reviewed at site. The facility has one drum for waste fuel contaminated debris with about 20 pounds of waste absorbent. The facility has one empty drum for fuel contaminated liquids Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. The facility has not completed an HMBP plan and a plan must be submitted on CERS or E Submit Hazardous waste containers must be labeled and stored closed. Each container and portable tank was marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	10/15/2015
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Reviewed HMBEP submission package on CERS, DENIED. Request for resubmittal within 30 days; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/22/2014
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Mark Sutphin on site to inspect tank sumps, dispenser containment (UDC) sumps, and review required documentation during the annual monitoring system certification testing, leak detector testing, and spill bucket testing. Met with station manager, Joseph hamoush , obtained consent inspect , take photographs , and to review documentation. Annual monitor certification being performed by David Lopez . ICC , VMI, and Veederroot Certification were up to date On site to observe and visually verify upon arrival tank sumps and UDC sumps are dry and sensors are located at the lowest point in the sumps. Also verified the secondary containment pipes to be open to the turbine sumps. Site has four underground storage tanks. Three for gasoline and one fore diesel.Piping observed in sumps appears to double-wall fiberglass, and 6 dispenser with UDC sumps. The turbine/piping sumps ,fill sumps, and UDCs are monitored with Veeder-Root 208 sensors Leak detection is monitored with [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/29/2021
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Mark Sutphin on site for annual UST Facility inspection and to witness monitor Certification testing Met with station manager Salam Gammo, , obtained consent inspect , take photographs , and to review documentation. Annual monitor certification being performed by Luis Rivera. ICC , VMI, and Veederroot Certification were up to date Upon arrival tank sumps , UDC sumps and vent sump were inspected and were dry and sensors were located at the lowest point in the sumps. Also verified the secondary containment pipes to be open to the turbine sumps. Site has four underground storage tanks. Three for gasoline and one for diesel. Piping observed in sumps appears to double-wall fiberglass, and 6 dispenser with UDC sumps. The turbine/piping sumps ,fill sumps, and UDCs are monitored with Veeder-Root 208 sensors Leak detection is monitored with Vaporless line leak detectors. The fill and vapor spill buckets were filled with water for the spill bucket test. The following documents [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/08/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

reviewed file . monitor cert and SB989 scheduled 12-12-16; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/18/2019
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

UST submittal has been DECLINED: Tank Pages: The tank primary containment should be fiberglass for all tanks, not steel. Plot Plan Map: Map should also depict piping layout from tank to dispensers and vent risers. This facility has a vent sump right below the vent risers next to the car wash. Add this to the map and no in the monitoring plan. Specify sensor in UDCs (VR208) on the legend. Make submittal corrections are resubmit within 30 days.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 10/05/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Mark Sutphin reviewed CERS submittal 10512283 Violations I583, I616, and TR05 have been abated Facility UST permit can be issued .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/12/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by Salam Gammo. The facility has an active EPA ID # CAL000338171 Manifests from Able Environmental reviewed at site. The facility has one drum for waste fuel contaminated debris. The facility has one empty drum for fuel contaminated liquids Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Each container and portable tank was marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. The Accumulation start date For further information about Hazardous Waste management, please refer to the Orange County Hazardous Waste website at [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/16/2015
Violations Found: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by Salam Gammo. The facility has an active EPA ID # CAL000338171 Manifests from Able Environmental reviewed at site. The facility has one drum for waste fuel contaminated debris with about 20 pounds of waste absorbent. The facility has one empty drum for fuel contaminated liquids Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Hazardous waste containers must be labeled and stored closed. Each container and portable tank was marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. The Accumulation start date For further information [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	03/12/2018
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Reviewed and not accepted by M Sutphin For the oxygen state no for explosive, for propane state no for explosive and oxidizer. please submit a new site plan the old plan did not sync and is no longer on the hazmat business plan. Please note for diesel and gasoline state no for gas under pressure; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/03/2024
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

On site to conduct a routine monitoring system certification inspection. The facility has the following double-walled (DW) tanks: - Regular (2 x 10,000-gal.) - Premium (10,000-gal.) - Diesel (10,000-gal.) The UST system is monitored by a Veeder Root (VR) TLS-350. The monitor was operational for audible and visual alarms. Overfill prevention is provided by fill tube shut-off valves for all tanks. The UST system is monitored as follows: - Tank interstitials: VR-407 - STP sumps, fill sumps, U; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	07/08/2021
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Received overfill prevention certification testing results dated 7-6-21. System passed testing four USTs tested . audible / visual high level alarm set at 90%.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	10/08/2015
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

NOV issued for operating without a permit, due to non-compliance. NOV mailed October 1, 2015.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Date: 06/28/2019
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Facility has submitted a signed Leak Response Plan to CERS and submitted the re-test results for the 87 line leak detector. The following violations have been closed: -I005: Signed Leak Response Plan submitted to CERS. -I198: 87 LLD tested and passed on 6/11/19. The following violations remain outstanding: -I582: Operating Permit Application and Tank Pages submitted to CERS requires corrections. -I101: Ball floats are reported on CERS and must be tested. Update Tank Pages or test ball floats to abate violation. -I161: Plot Plan requires updates. Please see regulator comments on CERS. Submit documentation to this Agency within 30 days to abate the open violations.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 10/21/2019
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This Agency has reviewed the following documents: - Overfill Prevention Equipment Inspection Report dated 4/9/19 Tanks utilize ATG w/ audible/visual alarm. The following violation has been closed: - I101: Overfill equipment has been inspected. The following remain outstanding: - I161: Plot plan requires updates. Submit map to CERS. - I582: UST submittal still requires corrections. Submit to CERS. - I481: Permit to Operate to be issued once compliance is achieved. Please submit all required documents to close out the remaining outstanding violations. Contact me at acabudol@ochca.com or 714-625-2702 if you have questions.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/12/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to inspect tank sumps, dispenser containment (UDC) sumps, and review required documentation during the annual monitoring system certification testing, leak detector testing, and spill bucket testing. SB989 testing was also performed while I was at site. Met with station owner Salam Gammo, obtained consent inspect , take photographs , and to review documentation. Annual monitor certification being performed by Steve Loera. ICC , VMI, and Veederroot Certification were up to date On site to observe and visually verify upon arrival tank sumps and UDC sumps are dry and sensors are located at the lowest point in the sumps. Also verified the secondary containment pipes to be open to the turbine sumps. Site has four underground storage tanks. Three for gasoline and one for diesel. Piping observed in sumps appears to double-wall fiberglass, and 6 dispenser with UDC sumps. The turbine/piping sumps ,fill sumps, and UDCs are monitored with Veeder-Root 208 [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/03/2024
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

On site to conduct a routine hazardous waste inspection. Consent to inspect the facility was granted by Joseph Hamouche (Manager). Observed the facility and its hazardous waste storage area. The facility was not observed to be storing any hazardous waste at the time of inspection. No hazardous waste was observed in the facility dumpster or enclosure area. Emergency response information was available on site. Hazardous waste manifests were available for review. The facility has not had a hazar; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/29/2021
Violations Found: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by Salam Gammo. The facility has an active EPA ID # CAL000338171 Manifests from Able Environmental reviewed at site. The facility has one drum for waste fuel contaminated debris. The facility has one empty drum for fuel contaminated liquids Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Each container and portable tank was marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. The Accumulation start date For further information about Hazardous Waste management, please refer to the Orange County Hazardous Waste website at [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	03/09/2020
Violations Found:	Yes
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

This is an off site follow up inspection to review the outstanding UST violations for this facility. The following class II violations were cited on previous inspection reports and remain outstanding: - I481: Facility operating without a Permit from this Agency. Correct all outstanding violations immediately to be issued a Permit. - I106: DO monthly inspection reports dated 7/17/19, 9/22/19, and 11/25/19 were not conducted within 30 days of each other as required. Submit a copy of the December - February DO reports to this Agency immediately. Please submit all required documentation to this Agency immediately. Failure to comply with Underground Storage Tank laws and regulations will result in enforcement actions.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	10/05/2015
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Change status to receive a UST permit, per Sutphin.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	11/29/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Monitor cert notification; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/08/2020
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

On site for a routine hazardous waste inspection. Consent to inspect and take any necessary photos was given by Joseph Hamouche, Manager. Walked throughout the facility. Observed hazardous waste storage areas. Containers were closed and properly labeled. Manifests were available and reviewed. Employees are reported to be trained. Emergency plan is posted in back office. No hazardous waste or universal waste observed in the

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

dumpster/enclosure area. No hazardous waste violations were observed this date.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/19/2015
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

INSPECTOR COMMENTS Violation (I213) was cited on a previous inspection report and remains outstanding. Please submit UST permitting documents to an approved electronic database immediately. UST documents must be submitted via the e-Submit Portal at <https://www.esubmit.ocgov.com/home/> or through the California Electronic Reporting System (CERS). If there are questions regarding this report or compliance issues, please contact your district inspector at msutphin@ochca.com Thank you.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/10/2023
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This Agency has received the following documents: - Copy of January designated operator inspection report with correct secondary containment test date - Overfill prevention (flapper) test report dated 12/20/2022 for final inspection of SR0149357 Violations 20300013 and 2030035 have been corrected.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/12/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Reviewed and accepted by M Sutphin UST installation date is 1-1-2000; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/05/2019
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

UST submittal on CERS has been reviewed. The following violations have been closed: - I161: Facility has a current plot plan. The following remain outstanding: - I582: UST submittal on CERS still requires corrections. - I481: Permit to Operate to be issued once compliance is achieved. Please re-submit UST submittal to CERS immediately to close out the remaining violations. Refer to regulator comments on CERS for guidance.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/08/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site for routine hazardous materials and business emergency plan inspection. The inspection was conducted with Joseph Hamouche, Manager.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Observed the facility and inspected hazardous materials storage. The following materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: - Gasoline (30,000 gallons) - Diesel (10,000 gallons) - Carbon Dioxide (42 gallons) REQUIREMENT FOR ELECTRONIC SUBMITTAL OF HMBEP DOCUMENTS: This report serves as notice that the facility must submit the following documents electronically within 30 days of this report: - Hazardous Materials Inventory - Site Map The facility is responsible for identifying all hazardous materials, to include hazardous wastes, which are above disclosure thresholds of 55 gallons for liquids, 500 pounds for solids, & 200 cubic feet for gases. If there is a change in the type or amount of chemicals that are maintained on site, please submit revised documents [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/13/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

The following UST documents have been received in CERS on 1/6/2020 and ACCEPTED: - UST Facility Operating Permit Application - UST Monitoring Site Plan Violation I582 has been corrected. Please note, there are pending corrections to other documents related to your CERS submittal that require your attention at <http://cers.calepa.ca.gov/>. The following violations remain outstanding and must be corrected immediately: - I481: Failure to obtain a valid permit to operate a UST. - I122: Failure to maintain monitoring records for release detection and/or maintain records of appropriate follow-up actions. - I106: Failure to conduct the designated UST operator visual inspection at least once every 30 days. Please submit all documents to this Agency within 30 days.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/16/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Monitor cert notification; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/08/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

On site to witness annual monitoring certification, spill bucket testing, and conduct UST inspection. Tester: - Luis Rivera of Universal Nozzle. Tester certifications (VR, ICC, VMI) were verified. Tanks: - 87 main (10,000 gal) - 87 aux (10,000 gal) - 91 (10,000 gal) - Diesel (10,000 gal) Monitoring Panel: Veeder Root TLS-350 Annulars: - VR-407 Fill/STP/UDC Sumps + Vent Sump - VR-208 All liquid detection sensors were tested on site. Positive shutdown, fail safe and sensor out were verified. LLD: - VR PLLD Facility has a submittal in CERS. The following documents were available for review on site: - Permit to Operate - Monitoring Plan + Tank Pages - Plot Plan Map - Leak Response Plan - CFR + CFO Letter - Statement of Understanding and Compliance - DO Agreement - DO Training - DO Monthly Reports - Alarm Logs - Maintenance Records - Monitoring System Certification test results dated 12/20/19 - Secondary Containment test [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/16/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to inspect tank sumps, dispenser containment (UDC) sumps, and review required documentation during the annual monitoring system certification testing, leak detector testing, and spill bucket testing. Met with station owner Salam Gammo, , obtained consent inspect , take photographs , and to review documentation. Annual monitor certification being performed by David Lopez . ICC , VMI, and Veederoot Certification were up to date On site to observe and visually verify upon arrival tank sumps and UDC sumps are dry and sensors are located at the lowest point in the sumps. Also verified the secondary containment pipes to be open to the turbine sumps. Site has four underground storage tanks. Three for gasoline and

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

one fore diesel.Piping observed in sumps appears to double-wall fiberglass, and 6 dispenser with UDC sumps. The turbine/piping sumps ,fill sumps, and UDCs are monitored with Veeder-Root 208 sensors Leak detection is monitored with Vaporless [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/10/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

This Agency has received the following documentation submitted to CERS on 12/10/2020 which has been reviewed and ACCEPTED: - Hazardous Materials Inventory - Site Map Violation I632 has been corrected. There are no remaining hazardous materials violations for this facility. REMINDER: Please re-certify your HMBEP annually between January 1st – March 1st at <http://cers.calepa.ca.gov/>.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/14/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This Agency has received the following test reports dated 12/8/2020: - Monitoring System Certification - Spill Containers - Line Leak Detectors All components were tested and PASSED.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/21/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Recieved monitor certification test results and SB989 test results for testing witnessed by M Sutphin on 12-12-16. The testing passed that date. ...; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/28/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

On site to witness annual monitoring certification and spill bucket test and conduct UST inspection. The site has the following tanks: - 87 main (10,000 gal) - 87 aux (10,000 gal) - 91 (10,000 gal) - Diesel (10,000 gal) The UST system is monitored via Veeder Root TLS-350 panel. Annulars: - All tanks have VR407 Fill/STP/UDC sumps + Vent Sump - VR208 All liquid detection sensors tested; 87 aux STP 208 sensor failed - replaced with another VR208 and tested - passed. Positive shutdown, fail safe and sensor out were verified. LLD: - All STPs have VR PLLD All LLDs were tested and passed with the exception of the 87 main LLD which failed. Testing was conducted by Jimmy Quintanilla with JQ Engineering. Technician certs (ICC, VR and VMI) were verified. Facility has submitted on CERS. The following documents were available for review: - Permit to Operate (needs to be updated to reflect diesel tank) - Certificate of Financial Responsibility [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/06/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Source:	CERS
Eval Notes:	

Reviewed file for 12-12-17 scheduled monitor certification per review of file FA0023947 the 4 new UST were installed 10-12-1995 on plan 95PC78; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	01/07/2021
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

This Agency has received the following documentation demonstrating that violation I106 has been corrected: - DO report from 9/16/20 listing 91 STP fuel alarm from 8/21/20 and corrective actions. - DO reports corrected for January 2020 - December 2020. - DO letter acknowledging requirement for visual inspection at least every 30 days. There are no remaining UST violations for this facility. Please conduct DO visual inspections at least once every 30 days, document all fuel alarms, ensure owner/operator has received DO inspection reports within 48 hours, and signed and dated by owner/operator within 72 hours of receipt per 23 CCR 16 2716(a)-(e).; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	07/22/2021
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

CERS submittal reviewed and accepted . Updated CFR dated 1-1-21 2021 overfill cert test submitted; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	05/22/2015
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Change UST status to not get a permit, per Sutphin.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	08/16/2019
Violations Found:	Yes
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

This Agency has not received documentation to address the following open violations: -I161: Plot Plan submitted to CERS requires corrections. -I582: Tank Pages submitted to CERS requires corrections. -I101: Conduct overfill prevention equipment inspection and submit report to this Agency within 30 days. In addition to the aforementioned open violations, the following additional violation has been issued: - I481: Facility is operating UST system without a Permit to Operate from this Agency. Submit documentation to close out the aforementioned violations within 30 days to receive a Permit to Operate from this Agency. Contact me at acabudol@ochca.com or 714-625-2702 if you have questions.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	03/11/2020
Violations Found:	Yes
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

This Agency has received a copy of the following documentation for this facility: - Monitoring System Certification test report dated 12/20/2019. - All components tested and PASSED. - Spill Bucket test report dated 12/20/2019. - All components tested and PASSED. - Secondary Containment test report dated 12/20/2019: - Product Piping Sump (87 Master, 87 Siphon, 91, Diesel) - FAILED. - Fill Sump (87 Master, 87 Siphon, 91, Diesel) - FAILED. - UDC 3/4 - FAILED. - All other components PASSED. - DO Reports (corrected): - 12/19/2019 - 1/28/2020 - 2/17/2020 - Received letter from owner with justification for DO inspections exceeding 30 day time frame. The following violations have been corrected: - Failure to conduct the designated UST operator visual inspection at least once every 30 days. - Failure to submit Annual Monitoring System Certification test results [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/28/2021
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Reviewed UST CERS submittal. Facility does not list fill tube shut off valves on UST tank information pages on CERS . Inspection set up for 12-29-21 to confirm; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/29/2021
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by Salam Gammo. The facility has an active EPA ID # CAL000338171 Manifests from Able Environmental reviewed at site. The facility has one drum for waste fuel contaminated debris. The facility has one empty drum for fuel contaminated liquids Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Each container and portable tank was marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. The Accumulation start date For further information about Hazardous Waste management, please refer to the Orange County Hazardous Waste website at [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	01/18/2022
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

CERS submittal reviewed and accepted . CERS tank ID lists Audible visual alarm for Overfill prevention. Recently the SWRCB issued LG 150-3, which includes clarification on existing overfill prevention requirements related to the overfill alarm. This affects sites with more than one UST that utilize an ATG system with overfill alarm to meet the requirements. The clarification provided in LG 150-3 includes the following "Systems that only can activate external alarms when the first UST overfill condition occurs must be noted as failing the inspection and additional actions must be taken to ensure each UST has a functional overfill prevention independent of the other USTs at the facility (i.e. installing a separate alarm unit or other appropriate OPE equipment for each tank). Please ensure that your tank system meets overfill prevention requirements.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	12/06/2017
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Notes:

Reviewed CERS UST info needs updated DO Statement , Financial , and tank install date and Xerxes primary tank should be listed as fiberglass; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/21/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 12/03/2024
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site to conduct a routine hazardous materials business plan (HMBP) inspection. Consent to inspect the facility was granted by Joseph Hamouche (Manager). Observed the facility, perimeter, and hazardous materials storage areas. The following materials were present at disclosable quantities: - Carbon dioxide (1 x 40-gal. container) - Diesel (1 x 10,000-gal. UST) - Gasoline (3 x 10,000-gal. in USTs; 30,000-gal. total) - Propane (21 x 5-gal. containers; 105-gal. total) Declined HMBP components s; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/13/2022
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

On site for routine UST inspection, monitoring system certification and spill bucket testing. The facility has four double-walled tanks (87, 87, 91, Diesel) monitored by a Veeder Root TLS-350 system. The monitor is operational for audible and visual alarms. Positive shutdown and fail safe programming were verified for pressurized piping. In-tank probes with external alarms are used for overfill prevention. Facility is in the process of installing flapper valves (SR0149357). The following senso; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/12/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERSINFO FOR UST INSTALLATION DATE IS 10-12-95. 4 USTS AT SITE ARE xERXES DOUBLE WALLED FIBERGLASS TANKS; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Identification Signer
Entity Name: JOSEPH HAMOUCHE
Entity Title: OWNER
Address:
City:
State:
Country:
Zip Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Phone:						
Affil Type Desc:		Operator				
Entity Name:		GAMMO CORPORATION				
Entity Title:						
Address:						
City:						
State:						
Country:						
Zip Code:						
Phone:		(714) 534-2530				
Affil Type Desc:		Document Preparer				
Entity Name:		JOSEPH HAMOUCHE				
Entity Title:						
Address:						
City:						
State:						
Country:						
Zip Code:						
Phone:						
Affil Type Desc:		UST Permit Applicant				
Entity Name:		SALAM GAMMO				
Entity Title:		OWNER				
Address:						
City:						
State:						
Country:						
Zip Code:						
Phone:		(714) 534-2530				
Affil Type Desc:		UST Tank Operator				
Entity Name:		GAMMO CORP				
Entity Title:						
Address:		13482 BROOKHURST ST				
City:		GARDEN GROVE				
State:		CA				
Country:		United States				
Zip Code:		92843				
Phone:		(714) 534-2530				
Affil Type Desc:		CUPA District				
Entity Name:		Orange County Env Health				
Entity Title:						
Address:		1241 East Dyer RoadSuite 120				
City:		Santa Ana				
State:		CA				
Country:						
Zip Code:		92705-5611				
Phone:		(714) 433-6406				
Affil Type Desc:		Facility Mailing Address				
Entity Name:		Mailing Address				
Entity Title:						
Address:		13482 BROOKHURST ST				
City:		GARDEN GROVE				
State:		CA				
Country:						
Zip Code:		92843				
Phone:						
Affil Type Desc:		Parent Corporation				
Entity Name:		GAMMO CORP				
Entity Title:						
Address:						
City:						
State:						
Country:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Zip Code: Phone: Affil Type Desc: UST Property Owner Name Entity Name: SALAM GAMMO Entity Title: Address: 13482 BROOKHURST ST City: GARDEN GROVE State: CA Country: United States Zip Code: 92843 Phone: (714) 534-2530 Affil Type Desc: UST Tank Owner Entity Name: GAMMO CORP Entity Title: Address: 13482 BROOKHURST ST City: GARDEN GROVE State: CA Country: United States Zip Code: 92843 Phone: (714) 534-2530 Affil Type Desc: Environmental Contact Entity Name: JOSEPH HAMOUCHE Entity Title: Address: 13482 BROOKHURST ST City: GARDEN GROVE State: CA Country: Zip Code: 92843 Phone: Affil Type Desc: Legal Owner Entity Name: GAMMO CORPORATION Entity Title: Address: 13482 BROOKHURST ST City: GARDEN GROVE State: CA Country: United States Zip Code: 92843 Phone: (714) 534-2530 Affil Type Desc: Property Owner Entity Name: SALAM GAMMO Entity Title: Address: 13482 BROOKHURST ST City: GARDEN GROVE State: CA Country: United States Zip Code: 92843 Phone: (714) 534-2530						
<u>Coordinates</u>						
Env Int Type Code:	HMBP			Longitude:	-117.954400	
Program ID:	10512283			Coord Name:		
Latitude:	33.767120			Ref Point Type Desc:	Center of a facility or station.	
<u>16</u>	9 of12	ESE	0.15 / 811.75	72.89 / -1	LIAQUAT ALI JUMANI 13482 BROOKHURST ST. GARDEN GROVE CA	HIST TANK
Owner Name:	ARCO PETROLEUM PRODUCTS CO.			No of Containers:	4	
Owner Street:	515 SOUTH FLOWER STREET			County:	ORANGE	
Owner City:	LOS ANGELES			Facility State:	CA	
Owner State:	CA			Facility Zip:	92643	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Owner Zip:	90071					
<hr/>						
16	10 of 12	ESE	0.15 / 811.75	72.89 / -1	GAMMO CORPORATION 13482 BROOKHURST ST GARDEN GROVE CA 92843	EMISSIONS

2016 Toxic Data

Facility ID:	157786	TS:	
Facility SIC Code:	5541	HRA:	
CERR CODE:		CH Index:	
CROID:	ORA	AH Index:	
CO:	30	Air Basin:	SC
DISN:	SOUTH COAST AQMD	District:	SC
CHAPIS:			

2017 Toxic Data

Facility ID:	157786	CROID:	ORA
Facility SIC Code:	5541	DISN:	SOUTH COAST AQMD
CO:	30	CHAPIS:	
Air Basin:	SC	CERR Code:	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Toxic Data

Facility ID:	157786	CROID:	ORA
Facility SIC Code:	5541	DISN:	SOUTH COAST AQMD
CO:	30	CHAPIS:	
Air Basin:	SC	CERR Code:	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Toxic Data

CO:	30	DISN:	SOUTH COAST AQMD
Air Basin:	SC	CHAPIS:	
Facility ID:	157786	CERR Code:	
District:	SC	TS:	
Facility SIC Code:	5541	Health Risk Asmt:	
CROID:	ORA		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2020 Toxic Data

CO:	30	DISN:	SOUTH COAST AQMD
Air Basin:	SC	CHAPIS:	
Facility ID:	157786	CHERR Code:	
District:	SC	TS:	
Facility SIC Code:	5541	Health Risk Asmt:	
CROID:	ORA		
Non-Cancer Chronic Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Non-Cancer Acute Haz Ind:

2021 Toxic Data

Co:	30	DISN:	SOUTH COAST AQMD
Air Basin:	SC	CHAPIS:	
Facility ID:	157786	Cerr Code:	
District:	SC	TS:	
Facility SIC Code:	5541	Health Risk Asmt:	
COID:	ORA		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

16	11 of 12	ESE	0.15 / 811.75	72.89 / -1	GAMMO CORPORATION 13482 BROOKHURST ST GARDEN GROVE CA 92843-3119	RCRA NON GEN
--------------------	----------	-----	------------------	---------------	--	-----------------

Handler ID:	CAL000338171
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	44719
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20081124	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.767089
In Handler Univ:	Y	Location Longitude:	-117.954867
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	Y		
Universal Waste Dest Facility:	Y		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
As State Regulated Tsdf:	-----					
As State Regulated Handler:	---					
Federal Indicator:	---					
Hsm:	N					
Subpart K:	----					
GPRA Permit:	N					
GPRA Renewal:	N					
Permit Renewal Wrkld:	-----					
Permwrk ID:	-----					
Perm Prog:	-----					
Pcwrkld:	-----					
Closwrkld:	-----					
GPRA Ca:	N					
Cawrkld:	N					
Subjca Tsd Discretion:	N					
NCAPS:	N					
EC Indicator:	N					
Ca725 Indicator:	N					
Ca750 Indicator:	N					
Operating Tsdf:	-----					
Full Enforcement:	-----					
Snc:	N					
Unaddressed Snc:	N					
Addressed Snc:	N					
Snc With Comp Sched:	N					
Fa Required:	-----					
Hhandler Last Change:	20180905					
Recognized Trader Importer:	N					
Recognized Trader Exporter:	N					
Slab Importer:	N					
Slab Exporter:	N					
Manifest Broker:	N					
Subpart P:	N					
Contact Language:	EN					
Handler Name:	GAMMO CORPORATION					
Location Street No:						
Location Street1:	13482 BROOKHURST ST					
Location Street2:						
Location City:	GARDEN GROVE					
Location State:	CA					
Location Zip:	92843-3119					
Location County Code:	CA059					
Location County Name:	ORANGE					
Location Country:	US					
Contact Name:	SALAM GAMMO					
Contact Street No:						
Contact Street1:	13482 BROOKHURST ST					
Contact Street2:						
Contact City:	GARDEN GROVE					
Contact State:	CA					
Contact Zip:	92843					
Contact Country:						
Contact Phone And Ext:	714-863-7488					
Contact Fax:	000-000-0000					
Contact Email Address:	JUSTINPARKCPA@GMAIL.COM					
Contact Title:						
Owner Name:	GAMMO CORPORATION					
Owner Type:	O					
Owner Seq:	1					
Operator Name:	SALAM GAMMO					
Operator Type:	O					
Operator Seq:	2					
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Seq No: 1
 Receive Date: 20081124
 Handler Name: GAMMO CORPORATION
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	13482 BROOKHURST ST
Name:	SALAM GAMMO	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-863-7488	Country:	
Source Type:	Implementer	Zip:	92843
Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	13482 BROOKHURST ST
Name:	GAMMO CORPORATION	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-863-7488	Country:	
Source Type:	Implementer	Zip:	92843-3119

16	12 of12	ESE	0.15 / 811.75	72.89 / -1	ARCO #629 13482 BROOKHURST ST GARDEN GROVE CA	UST SWEEPS
--------------------	---------	-----	------------------	---------------	---	------------

C C:	A30-000-4348	D Filename:	SITE12A
BOE:		Page No:	123
Comp:	4348	County:	ORANGE
Status:	ACTIVE	State :	CA
No of Tanks:	4	Zip:	92643
Jurisdic:	ORANGE COUNTY	Latitude:	33.767116
Agency:	ENVIRONMENTAL HEALTH	Longitude:	-117.954882
Phone:		Georesult:	S5HPNTSC-A

Tank Details

Tank ID:	000002	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-004348-000002	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	REG UNLEADED
Capac:	6000	ONA:	
Tank Use:	M.V. FUEL	D File Name:	TANK12A

Tank Details

Tank ID:	000003	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-004348-000003	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	REG UNLEADED
Capac:	6000	ONA:	
Tank Use:	M.V. FUEL	D File Name:	TANK12A

Tank Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank ID: O Tank ID: SWRCB No: Removed: Installed: A Date: Capac: Tank Use:	000001 30-000-004348-000001 6000 M.V. FUEL				S Contain: Stg: Storage : Storag Type: P Contain: Content: ONA: D File Name:	P PRODUCT REG UNLEADED TANK12A
<u>Tank Details</u>						
Tank ID: O Tank ID: SWRCB No: Removed: Installed: A Date: Capac: Tank Use:	000004 30-000-004348-000004 6000 M.V. FUEL				S Contain: Stg: Storage : Storag Type: P Contain: Content: ONA: D File Name:	P PRODUCT REG UNLEADED TANK12A
17	1 of 7	ESE	0.16 / 829.33	71.63 / -2	EXXON #7-0833 13502 BROOKHURST ST # 7-0833 GARDEN GROVE CA 92843	DELISTED TNK
<u>Delisted Storage Tanks</u>						
Facility ID: Latitude: Longitude: Permitting Agency:	2122 33.76667 -117.95494 ORANGE COUNTY				County: Original Source: Record Date:	Orange UST 30-JAN-2017
17	2 of 7	ESE	0.16 / 829.33	71.63 / -2	EXXON #7-0833 13502 BROOKHURST GARDEN GROVE CA 92643	LUST
Global ID: Site Facility Type: Site Fac Type (SRCH): Status: Status (SRCH): Status (DL): Status Date (DL): Cleanup Status: Site Facility Name (SRCH): Address (SRCH): City (SRCH): Zip (SRCH): County (SRCH): Street No (DL): Street Name (DL): City (DL): Zip (DL): County (DL): State (DL): Business Name (DL): Site Facility Name: Address : City : Zip : County : Report Source:	T0605970421 LUST CLEANUP SITE LUST CLEANUP SITE COMPLETED - CASE CLOSED Completed - Case Closed 2/7/1996 COMPLETED - CASE CLOSED EXXON #7-0833 13502 BROOKHURST GARDEN GROVE 92643 ORANGE 13502 BROOKHURST GARDEN GROVE 92643 Orange CA EXXON #7-0833 EXXON #7-0833 13502 BROOKHURST GARDEN GROVE 92643 ORANGE LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search				Case Type (DL): Oil Field (SRCH): Oil Field Oper (SRCH): Census Tract (SRCH): Latitude (DL): Longitude (DL): RWQCB Region (DL):	LUST Cleanup Site 6059088902 33.766726 -117.954899 SANTA ANA RWQCB (REGION 8)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

GeoTracker Sites Data Download - Site Details

CUF Case:
Lead Agency: ORANGE COUNTY LOP
Case Worker:
Local Agency:
RB Case No:
Local Case No: 92UT061
File Location: Local Agency
Potential COC: Gasoline
Potential Media of Concern: Other Groundwater (uses other than drinking water)
Begin Date: 4/20/1992
How Discovered: Tank Closure
How Discovered Description:
Stop Method: Close and Remove Tank
Stop Description:
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name: Coastal Plain Of Orange County (8-001)
Disadvantaged Community:
CalEnvScreen Score:
Coordinate Source: Google Geocode
Discharge Cause:
Discharge Source:
EPA Region: 9
Leak Reported Dt: 1992-04-20 00:00:00
Military DoD Site: No
No Further Action Dt: 1996-02-07 00:00:00
Qty Rlsd Gallons: 0
Facility Project Sub Type:
Calenviroscreen 3 Score: 71-75%
Calenviroscreen 4 Score: 75-80%
A2022 Assembly District: 70
Claim No: 14455
Claim Status: Active
A2022 Congressional District: 45
A2022 Senate District: 36
Site History:

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: JESSICA LAW
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 Main Street, Suite 500
City: RIVERSIDE
Email: jessica.law@waterboards.ca.gov
Phone No: 9517824381

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2/7/1996

Status: Open - Case Begin Date
Status Date: 4/20/1992

GeoTracker Search - Regulatory Profile

Site Facility Name: EXXON #7-0833
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 13502 BROOKHURST
City: GARDEN GROVE
Zip: 92643

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
County:		ORANGE				
Report Link:		https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605970421				
Cleanup Status Detail:		COMPLETED - CASE CLOSED AS OF 2/7/1996				
Project Status:						
Cleanup History Link:		https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605970421&tabname=regulatoryhistory				
Potential COC:		GASOLINE				
Potential Media of Concern:		OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)				
File Location:		LOCAL AGENCY				
User Defined Beneficial Use:						
Designated Beneficial Use:		MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.				
DWR GW Sub Basin:		Coastal Plain Of Orange County (8-001)				
Calwater Watershed Name:		Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)				
Post Closure Site Management:						
Future Land Use:						
Cleanup Oversight Agencies:		ORANGE COUNTY LOP (LEAD) - CASE #: 92UT061 SANTA ANA RWQCB (REGION 8) CASE MANAGER: JESSICA LAW				
CUF Claim No:		14455				
CUF Priority Assig:		D				
CUF Amount Paid:		\$117,613				
WDR Place Type:						
WDR File No:						
WDR Order No:						
Project Oversight Agencies:						
Facility Type:						
Composting Method:						
Grndwtr Monitoring Frequency:						
Designated Beneficial Use Desc:		Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.				
Site History:						
No site history available						

GeoTracker Search - Cleanup Status History

Status:	Completed - Case Closed
Date :	2/7/1996
Status:	Open - Case Begin Date
Date :	4/20/1992

GeoTracker Search - Regulatory Activities

Action Type:	Leak Action
Action:	Leak Discovery
Action Date:	4/20/1992
Received Issue Date:	
Doc Link:	
Title Description Comments:	

Action Type:	Leak Action
Action:	Leak Reported
Action Date:	4/20/1992
Received Issue Date:	
Doc Link:	
Title Description Comments:	

GeoTracker Search - Documents

Document Type:	Site Documents	Document Date:	4/30/1996*
Type:	STATUS / PROGRESS REPORTS	Submitted:	
Submitted By:	LORI BRASHERS (AUTH_RP)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Title: Title Link:		1Q 1996 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7715171515/T0605970421.PDF				
Document Type: Type: Submitted By: Title: Title Link:	Site Documents WELL DESTRUCTION REPORT LORI BRASHERS (AUTH_RP) WELL ABANDONMENT LETTER REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3475891351/T0605970421.PDF			Document Date: Submitted:	3/1/1996*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CORRESPONDENCE LORI BRASHERS (AUTH_RP) AGENCY'S REMEDIAL ACTION COMPLETION CERTIFICATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5141153156/T0605970421.PDF			Document Date: Submitted:	2/7/1996*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 4Q 1995 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8048361420/T0605970421.PDF			Document Date: Submitted:	1/2/1996*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents OTHER REPORT / DOCUMENT LORI BRASHERS (AUTH_RP) NOTIFICATION OF AS/SVE 90 DAY SHUTDOWN **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7230908334/T0605970421.PDF			Document Date: Submitted:	11/17/1995*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 3Q 1995 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2174835443/T0605970421.PDF			Document Date: Submitted:	10/15/1995*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CORRESPONDENCE LORI BRASHERS (AUTH_RP) AGENCY APPROVAL OF PROTOCOL FOR GROUNDWATER MONITORING DURING OPERATION OF REMEDIATION SYSTEM **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8334054768/T0605970421.PDF			Document Date: Submitted:	9/15/1995*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents WELL INSTALLATION REPORT LORI BRASHERS (AUTH_RP) LETTER REPORT DOCUMENTING INSTALLATION OF 10 AS/SVE WELLS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9009086310/T0605970421.PDF			Document Date: Submitted:	8/7/1995*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents OTHER REPORT / DOCUMENT LORI BRASHERS (AUTH_RP) PROTOCOL FOR GROUNDWATER MONITORING DURING OPERATION OF REMEDIATION SYSTEM **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1994659662/T0605970421.PDF			Document Date: Submitted:	8/7/1995*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 2Q 1995 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6237098395/T0605970421.PDF			Document Date: Submitted:	7/24/1995*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents OTHER REPORT / DOCUMENT LORI BRASHERS (AUTH_RP) WELL CONSTRUCTION DIAGRAMS (COVER LETTER ONLY) **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4007656991/T0605970421.PDF			Document Date: Submitted:	7/20/1995*	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 1Q 1995 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7301428437/T0605970421.PDF				Document Date: 4/19/1995* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 4Q 1994 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6151679694/T0605970421.PDF				Document Date: 1/24/1995* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 3Q 1994 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5244964838/T0605970421.PDF				Document Date: 10/24/1994* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 2Q 1994 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3550146698/T0605970421.PDF				Document Date: 7/18/1994* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CORRESPONDENCE LORI BRASHERS (AUTH_RP) AGENCY'S CONDITIONAL APPROVAL OF CORRECTIVE ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9281753778/T0605970421.PDF				Document Date: 7/13/1994* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CAP/RAP - OTHER REPORT LORI BRASHERS (AUTH_RP) CORRECTIVE ACTION PLAN REMOVAL OF HYDROCARBONS FROM SOIL AND GROUNDWATER **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6582989633/T0605970421.PDF				Document Date: 6/30/1994* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents SITE INVESTIGATION LORI BRASHERS (AUTH_RP) ADDITIONAL SUBSURFACE INVESTIGATION AND GROUNDWATER MONITORING REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2129544198/T0605970421.PDF				Document Date: 6/1/1994* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 1Q 1994 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6074597299/T0605970421.PDF				Document Date: 4/21/1994* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STATUS / PROGRESS REPORTS LORI BRASHERS (AUTH_RP) 4Q 1993 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8453384637/T0605970421.PDF				Document Date: 1/26/1994* Submitted:	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CORRESPONDENCE LORI BRASHERS (AUTH_RP) AGENCY'S APPROVAL OF REMEDIAL ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3118982136/T0605970421.PDF				Document Date: 11/15/1993* Submitted:	
Document Type: Type: Submitted By: Title:	Site Documents CAP/RAP - OTHER REPORT LORI BRASHERS (AUTH_RP) REMEDIAL ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field.				Document Date: 11/8/1993* Submitted:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9608459711/T0605970421.PDF				
Document Type:	Site Documents			Document Date:	10/21/1993*	
Type:	STATUS / PROGRESS REPORTS			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	3Q 1993 QUARTERLY REPORT	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9616287469/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	8/31/1993*	
Type:	CORRESPONDENCE			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	AGENCY REQUEST FOR WORKPLAN FOR REMEDIATION	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7327707111/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	8/24/1993*	
Type:	SITE INVESTIGATION			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	ADDITIONAL SITE INVESTIGATION REPORT	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6434744477/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	7/31/1993*	
Type:	STATUS / PROGRESS REPORTS			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	2Q 1993 QUARTERLY REPORT	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4859070062/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	4/27/1993*	
Type:	STATUS / PROGRESS REPORTS			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	1Q 1993 QUARTERLY REPORT	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1804605305/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	4/2/1993*	
Type:	CORRESPONDENCE			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	AGENCY'S ACTION PLAN APPROVAL LETTER WITH CONSIDERATIONS	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6173407196/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	3/24/1993*	
Type:	OTHER REPORT / DOCUMENT			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	WORKPLAN FOR ADDITIONAL ENVIRONMENTAL INVESTIGATION	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6416739344/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	2/3/1993*	
Type:	STATUS / PROGRESS REPORTS			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	4Q 1992 QUARTERLY REPORT	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1618887543/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	11/10/1992*	
Type:	STATUS / PROGRESS REPORTS			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	3Q 1992 QUARTERLY REPORT	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8542245686/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	10/30/1992*	
Type:	CORRESPONDENCE			Submitted:		
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	AGENCY'S REQUEST FOR WORK PLAN FOR ADDITIONAL SITE ASSESSMENT	**Note: Many records provided by the department have a truncated [Title] field.				
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2676733613/T0605970421.PDF					
Document Type:	Site Documents			Document Date:	10/5/1992*	
Type:	TANK REMOVAL REPORT / UST SAMPLING			Submitted:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
REPORT						
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	TANK EXCAVATION ASSESSMENT REPORT **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2561759650/T0605970421.PDF					
Document Type:	Site Documents	Document Date:	7/31/1992*			
Type:	STATUS / PROGRESS REPORTS	Submitted:				
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	2Q 1992 QUARTERLY REPORT **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1223556756/T0605970421.PDF					
Document Type:	Site Documents	Document Date:	5/18/1992*			
Type:	CORRESPONDENCE	Submitted:				
Submitted By:	LORI BRASHERS (AUTH_RP)					
Title:	AGENCY'S REQUEST FOR WORK PLAN OF SITE ASSESSMENT **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1721884369/T0605970421.PDF					
<hr/>						
17	3 of7	ESE	0.16 / 829.33	71.63 / -2	EXXON SERVICE STATION 13502 BROOKHURST GARDEN GROVE CA 92640	HHSS
County:						
Tank Details Microfiche:	http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002e8b3.pdf					
<hr/>						
17	4 of7	ESE	0.16 / 829.33	71.63 / -2	Exxon #7-0833 13502 Brookhurst St Garden Grove Ca 92643 CA	LOP ORANGE
Case ID:	92UT061					
<u>Details</u>						
Current Status:	Closed					
Type of Closure:	Closure certification issued					
Closed Date:	2/7/1996					
File Location:	Local Agency					
<hr/>						
17	5 of7	ESE	0.16 / 829.33	71.63 / -2	EXXON SERVICE STATION 13502 BROOKHURST GARDEN GROVE CA	HIST TANK
Owner Name:	EXXON COMPANY U.S.A.			No of Containers:	4	
Owner Street:	16945 NORTHCHASE BLVD.			County:	ORANGE	
Owner City:	HOUSTON			Facility State:	CA	
Owner State:	TX			Facility Zip:	92640	
Owner Zip:	77210					
<hr/>						
17	6 of7	ESE	0.16 / 829.33	71.63 / -2	EXXON #7-0833 13502 BROOKHURST ST GARDEN GROVE CA	UST SWEEPS
C C:	A30-000-2122			D Filename:	SITE12A	
BOE:	44-000285			Page No:	123	
Comp:	2122			County:	ORANGE	
Status:	ACTIVE			State :	CA	
No of Tanks:	4			Zip:	92643	
Jurisdic:	ORANGE COUNTY			Latitude:	33.76666	
Agency:	ENVIRONMENTAL HEALTH			Longitude:	-117.954884	
Phone:				Geosresult:	S5HPNTSC-A	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>Tank Details</u>						
Tank ID:	000004				S Contain:	
O Tank ID:					Stg:	P
SWRCB No:	30-000-002122-000004				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	REG UNLEADED
Capac:	8000				ONA:	
Tank Use:	M.V. FUEL				D File Name:	TANK12A
<u>Tank Details</u>						
Tank ID:	000003				S Contain:	
O Tank ID:					Stg:	P
SWRCB No:	30-000-002122-000003				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	REG UNLEADED
Capac:	8000				ONA:	
Tank Use:	M.V. FUEL				D File Name:	TANK12A
<u>Tank Details</u>						
Tank ID:	000001				S Contain:	
O Tank ID:					Stg:	P
SWRCB No:	30-000-002122-000001				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	LEADED
Capac:	8000				ONA:	
Tank Use:	M.V. FUEL				D File Name:	TANK12A
<u>Tank Details</u>						
Tank ID:	000005				S Contain:	
O Tank ID:					Stg:	P
SWRCB No:	30-000-002122-000005				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	
Capac:	1000				ONA:	
Tank Use:	PETROLEUM				D File Name:	TANK12A
17	7 of 7	ESE	0.16 / 829.33	71.63 / -2	Exxon #7-0833 13502 Brookhurst St Garden Grove Ca 92643 CA	LOP ORANGE
Case ID:	92UT125					
<u>Details</u>						
Current Status:		Closed				
Type of Closure:		Invalidated				
Closed Date:		1/1/1992				
File Location:		Local Agency				
18	1 of 1	WNW	0.16 / 842.99	71.52 / -2	9705 IMPERIAL AVE 9705 IMPERIAL AVE	RCRA NON GEN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

GARDEN GROVE CA 92844

Handler ID: CAC003239797
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20230629	NAIC 4:	
Active Site:	----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsd:	-----		
As Converter Tsd:	-----		
As State Regulated Tsd:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20241212				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		9705 IMPERIAL AVE				
Location Street No:						
Location Street1:		9705 IMPERIAL AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		MINH NGUYEN				
Contact Street No:						
Contact Street1:		9705 IMPERIAL AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:						
Contact Phone And Ext:		714-562-4040				
Contact Fax:						
Contact Email Address:		ELIZABETHS@PWSEI.COM				
Contact Title:						
Owner Name:		MINH NGUYEN				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		MINH NGUYEN				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20230629
Handler Name: 9705 IMPERIAL AVE
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9705 IMPERIAL AVE
Name:	MINH NGUYEN	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Phone:	714-562-4040				Country:	
Source Type:	Implementer				Zip:	92844
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Other				Street1:	9705 IMPERIAL AVE
Name:	MINH NGUYEN				Street2:	
Dt Became Current:					City:	GARDEN GROVE
Dt Ended Current:					State:	CA
Phone:	714-562-4040				Country:	
Source Type:	Implementer				Zip:	92844

19 **1 of 1** **ENE** **0.17 / 880.94** **75.05 / 1** **GABRIEL RASCOL
10021 RUSSELL AVE
GARDEN GROVE CA 92843** **RCRA
NON GEN**

Handler ID: CAC003121243
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20210524	NAIC 4:	
Active Site:	----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20210601				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		GABRIEL RASCOL				
Location Street No:						
Location Street1:		10021 RUSSELL AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		GABRIEL RASCOL				
Contact Street No:						
Contact Street1:		10021 RUSSELL AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92843				
Contact Country:						
Contact Phone And Ext:		714-588-1769				
Contact Fax:						
Contact Email Address:		CARTERMOISE97@YAHOO.COM				
Contact Title:						
Owner Name:		GABRIEL RASCOL				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		GABRIEL RASCOL				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20210524

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Handler Name: GABRIEL RASCOL Fed Waste Generator: N Generator Code Description: Not a Generator, Verified Source Type: Implementer						
<u>Owner/Operator Details</u>						
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Other				Street1:	10021 RUSSELL AVE
Name:	GABRIEL RASCOL				Street2:	
Dt Became Current:					City:	GARDEN GROVE
Dt Ended Current:					State:	CA
Phone:	714-588-1769				Country:	
Source Type:	Implementer				Zip:	92843
Owner/Operator Ind:	Current Owner				Street No:	
Type:	Other				Street1:	10021 RUSSELL AVE
Name:	GABRIEL RASCOL				Street2:	
Dt Became Current:					City:	GARDEN GROVE
Dt Ended Current:					State:	CA
Phone:	714-588-1769				Country:	
Source Type:	Implementer				Zip:	92843
20	1 of 3	ESE	0.18 / 939.28	73.23 / 0	SEXTONS AUTOMOTIVE 10041 TRASK AVE GARDEN GROVE CA 92843	RCRA SQG
Handler ID: CAD982052995 Generator Status: SQG Recycler Activity?: NO Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.						
<u>Violation/Evaluation Summary</u>						
Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).						
<u>Handler Summary</u>						
Importer:	No				Used Oil Transpor:	No
Mixed Waste Gen:	No				Used Oil Trans Fac:	No
Transporter:	No				Used Oil Processor:	No
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:	No					
Used Oil Spec Marketer:	No					
<u>Additional Handler Summary Details</u>						
Source Type:	N				NAIC 1:	811111
Seq No:	1				NAIC 2:	
Non Notifier:					NAIC 3:	
Receive Date:	19871016				NAIC 4:	
Active Site:	H----				State:	CA
Land Type:	O				Location Latitude:	33.766837
In Handler Univ:	Y				Location Longitude:	-117.954161
In A Universe:	Y				Loc GIS Primary:	N
Gen Status:	SQG				Loc GIS Origin:	AG
Report Cycle:					State District Owner:	CA
Accessibility:					State District:	4

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Region:	09					
Fed Waste Gen Owner:		HQ				
State Waste Generator Owner:						
State Waste Generator:						
Short Term Generator:		N				
Uni Waste:		N				
Universal Waste Dest Facility:		N				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20020627				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		SEXTONS AUTOMOTIVE				
Location Street No:						
Location Street1:		10041 TRASK AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		ENVIRONMENTAL MANAGER				
Contact Street No:						
Contact Street1:		10041 TRASK AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92643				
Contact Country:		US				
Contact Phone And Ext:		714-534-2560				
Contact Fax:						
Contact Email Address:						
Contact Title:						
Owner Name:		CARPENTER & SPRINGER				
Owner Type:		P				
Owner Seq:		1				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Operator Name:
Operator Type:
Operator Seq:
Public Notes:

NOT REQUIRED
 P
 2

Hazardous Waste Handler Details

Seq No:
Receive Date:
Handler Name:
Fed Waste Generator:
Generator Code Description:
Source Type:

1
 19871016
 SEXTONS AUTOMOTIVE
 2
 Small Quantity Generator
 Notification

Owner/Operator Details

Owner/Operator Ind:
Type:
Name:
Dt Became Current:
Dt Ended Current:
Phone:
Source Type:

Current Owner
 Private
 CARPENTER & SPRINGER

 415-555-1212
 Notification

Street No:
Street1:
Street2:
City:
State:
Country:
Zip:

NOT REQUIRED
 NOT REQUIRED
 ME
 99999

Owner/Operator Ind:
Type:
Name:
Dt Became Current:
Dt Ended Current:
Phone:
Source Type:

Current Operator
 Private
 NOT REQUIRED

 415-555-1212
 Notification

Street No:
Street1:
Street2:
City:
State:
Country:
Zip:

NOT REQUIRED
 NOT REQUIRED
 ME
 99999

20	2 of 3	ESE	0.18 / 939.28	73.23 / 0	SEXTONS AUTOMOTIVE 10041 TRASK AVE GARDEN GROVE CA 92843	DELISTED TNK
--------------------	--------	-----	---------------	-----------	--	-----------------

Delisted Storage Tanks

Facility ID:
Latitude:
Longitude:
Permitting Agency:

3140
 33.76682
 -117.95435
 ORANGE COUNTY

County:
Original Source:
Record Date:

Orange
 UST
 30-JAN-2017

20	3 of 3	ESE	0.18 / 939.28	73.23 / 0	SEXTONS AUTOMOTIVE 10041 TRASK AVE GARDEN GROVE CA	UST SWEEPS
--------------------	--------	-----	---------------	-----------	--	------------

C C:
BOE:
Comp:
Status:
No of Tanks:
Jurisdic:
Agency:
Phone:

A30-000-3140
 44-016010
 3140
 ACTIVE
 1
 ORANGE COUNTY
 ENVIRONMENTAL HEALTH

D Filename:
Page No:
County:
State :
Zip:
Latitude:
Longitude:
Georesult:

SITE12A
 133
 ORANGE
 CA
 92643
 33.766905
 -117.95425
 S5HPNTSC-A

Tank Details

Tank ID:
O Tank ID:
SWRCB No:

000002

 30-000-003140-000002

S Contain:
Stg:
Storage :

P

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Removed: Installed: A Date: Capac: Tank Use:	550 PETROLEUM				Storag Type: P Contain: Content: ONA: D File Name:	PRODUCT TANK12A

21	1 of 7	NE	0.18 / 944.26	76.08 / 2	KARAMAT STATION 13231 BROOKHURST ST GARDEN GROVE CA 92843	DELISTED TNK
--------------------	--------	----	---------------	-----------	---	--------------

Delisted Storage Tanks

Facility ID:	4349	County:	Orange
Latitude:	33.7720542	Original Source:	UST
Longitude:	-117.9540969	Record Date:	30-JAN-2017
Permitting Agency:	ORANGE COUNTY		

21	2 of 7	NE	0.18 / 944.26	76.08 / 2	ANDYS UNOCAL 13231 BROOKHURST GARDEN GROVE CA 92844	LUST
--------------------	--------	----	---------------	-----------	---	------

Global ID:	T0605900976	Case Type (DL):	LUST Cleanup Site
Site Facility Type:	LUST CLEANUP SITE	Oil Field (SRCH):	
Site Fac Type (SRCH):	LUST CLEANUP SITE	Oil Field Oper (SRCH):	
Status:		Census Tract (SRCH):	6059088702
Status (SRCH):	COMPLETED - CASE CLOSED	Latitude (DL):	33.7707273
Status (DL):	Completed - Case Closed	Longitude (DL):	-117.9551414
Status Date (DL):	6/26/2014	RWQCB Region (DL):	SANTA ANA RWQCB (REGION 8)
Cleanup Status:	COMPLETED - CASE CLOSED		
Site Facility Name (SRCH):	ANDYS UNOCAL		
Address (SRCH):	13231 BROOKHURST		
City (SRCH):	GARDEN GROVE		
Zip (SRCH):	92844		
County (SRCH):	ORANGE		
Street No (DL):	13231		
Street Name (DL):	BROOKHURST		
City (DL):	GARDEN GROVE		
Zip (DL):	92844		
County (DL):	Orange		
State (DL):	CA		
Business Name (DL):	ANDYS UNOCAL		
Site Facility Name:	ANDYS UNOCAL		
Address :	13231 BROOKHURST		
City :	GARDEN GROVE		
Zip :	92844		
County :	ORANGE		
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search		

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	ORANGE COUNTY LOP
Case Worker:	
Local Agency:	
RB Case No:	083001258T
Local Case No:	89UT095
File Location:	Local Agency
Potential COC:	Gasoline
Potential Media of Concern:	Aquifer used for drinking water supply
Begin Date:	5/14/1989
How Discovered:	* SA
How Discovered Description:	
Stop Method:	Close and Remove Tank

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Stop Description:

Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)

DWR GW Subbasin Name: Coastal Plain Of Orange County (8-001)

Disadvantaged Community:

CalEnvScreen Score:

Coordinate Source: * Historical Geocode - Exact Address Match

Discharge Cause:

Discharge Source: Piping

EPA Region: 9

Leak Reported Dt: 1989-05-18 00:00:00

Military DoD Site: No

No Further Action Dt: 2014-06-26 00:00:00

Qty Rlsd Gallons: 0

Facility Project Sub Type:

Calenviroscreen 3 Score: 51-55%

Calenviroscreen 4 Score: 60-65%

A2022 Assembly District: 70

Claim No: 2776

Claim Status: Active

A2022 Congressional District: 45

A2022 Senate District: 36

Site History:

Please refer to recent Site Documents or Monitoring Reports in GeoTracker for site history. Orange County is not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants for the responsible party.

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: MIGUEL OVIEDO
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 Main Street, Suite 500
City: RIVERSIDE
Email: miguel.oviedo@waterboards.ca.gov
Phone No: 9517823238

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 6/26/2014

Status: Open - Eligible for Closure
Status Date: 1/30/2012

Status: Open - Remediation
Status Date: 1/9/2004

Status: Open - Remediation
Status Date: 5/5/1997

Status: Open - Site Assessment
Status Date: 6/11/1991

Status: Open - Site Assessment
Status Date: 5/15/1989

Status: Open - Site Assessment
Status Date: 5/14/1989

Status: Open - Case Begin Date
Status Date: 5/14/1989

GeoTracker Search - Regulatory Profile

Site Facility Name: ANDYS UNOCAL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Site Facility Type:		LUST CLEANUP SITE				
Cleanup Status:		COMPLETED - CASE CLOSED				
Address:		13231 BROOKHURST				
City:		GARDEN GROVE				
Zip:		92844				
County:		ORANGE				
Report Link:		https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605900976				
Cleanup Status Detail:		COMPLETED - CASE CLOSED AS OF 6/26/2014				
Project Status:						
Cleanup History Link:		https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605900976&tabname=regulatoryhistory				
Potential COC:		GASOLINE				
Potential Media of Concern:		AQUIFER USED FOR DRINKING WATER SUPPLY				
File Location:		LOCAL AGENCY				
User Defined Beneficial Use:						
Designated Beneficial Use:		MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.				
DWR GW Sub Basin:		Coastal Plain Of Orange County (8-001)				
Calwater Watershed Name:		Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)				
Post Closure Site Management:						
Future Land Use:						
Cleanup Oversight Agencies:		ORANGE COUNTY LOP (LEAD) - CASE #: 89UT095 SANTA ANA RWQCB (REGION 8) - CASE #: 083001258T CASE MANAGER: MIGUEL OVIEDO				
CUF Claim No:		2776				
CUF Priority Assig:		B				
CUF Amount Paid:		\$1,457,687				
WDR Place Type:						
WDR File No:						
WDR Order No:						
Project Oversight Agencies:						
Facility Type:						
Composting Method:						
Grndwtr Monitoring Frequency:		# OF WELLS MONITORED - QUARTERLY : 5, SEMI-ANNUALLY : 3				
Designated Beneficial Use Desc:		REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING: Well Being Sampled During Remedial Action for Progress Assessment				
Site History:		Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.				

Please refer to recent Site Documents or Monitoring Reports in GeoTracker for site history. Orange County is not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants for the responsible party.

GeoTracker Search - Cleanup Status History

Status:	Completed - Case Closed
Date :	6/26/2014
Status:	Open - Eligible for Closure
Date :	1/30/2012
Status:	Open - Remediation
Date :	1/9/2004
Status:	Open - Remediation
Date :	5/5/1997
Status:	Open - Site Assessment
Date :	6/11/1991
Status:	Open - Site Assessment
Date :	5/15/1989
Status:	Open - Site Assessment
Date :	5/14/1989
Status:	Open - Case Begin Date

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Date : 5/14/1989

GeoTracker Search - Cleanup Action Report

Action Type: PUMP & TREAT (P&T) GROUNDWATER
Begin Date: 1/9/2004
End Date: 9/9/9999
Phase:
Contaminant Mass Removed:
Description:

Action Type: SOIL VAPOR EXTRACTION (SVE)
Begin Date: 1/9/2004
End Date: 9/9/9999
Phase:
Contaminant Mass Removed:
Description:

Action Type: EXCAVATION
Begin Date: 7/18/1989
End Date: 4/3/1996
Phase:
Contaminant Mass Removed:
Description:

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Clean Up Fund - Letter to RP
Action Date: 6/26/2014
Received Issue Date: 6/26/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6209871&temptable=ENFORCEMENT

Title Description Comments:

Claim 2776 Closure/No Further Action Letter **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: State Water Board - Closure Order
Action Date: 9/16/2013
Received Issue Date: 9/16/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6175982&temptable=ENFORCEMENT

Title Description Comments:

Claim 2776 Final Order State Water Board Case Closure **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Clean Up Fund - Letter to RP
Action Date: 6/27/2013
Received Issue Date: 6/27/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6165659&temptable=ENFORCEMENT

Title Description Comments:

Claim 2776 Public Notice State Water Board Case Closure **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)
Action Date: 6/27/2013
Received Issue Date: 6/27/2013
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6165656&temptable=ENFORCEMENT

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Title Description Comments:

Claim 2776 Fund Manager Case Closure RSR/FM Determination/FM Closure Recommendation **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: File review

Action Date: 10/18/2012

Received Issue Date: 10/18/2012

Doc Link:

Title Description Comments:

CASE FILE REVIEW **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Action Date: 12/19/2011

Received Issue Date: 12/19/2011

Doc Link: [https://geotracker.waterboards.ca.gov/view_documents?](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6393619&temptable=ENFORCEMENT)

[global_id=T0605900976&enforcement_id=6393619&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6393619&temptable=ENFORCEMENT)

Title Description Comments:

3rd 5-Year Review **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Staff Letter

Action Date: 9/12/2011

Received Issue Date: 9/12/2011

Doc Link: [https://geotracker.waterboards.ca.gov/view_documents?](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6098327&temptable=ENFORCEMENT)

[global_id=T0605900976&enforcement_id=6098327&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6098327&temptable=ENFORCEMENT)

Title Description Comments:

CONFIRMATION BORING WORK PLAN **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: File review

Action Date: 6/13/2011

Received Issue Date: 6/13/2011

Doc Link:

Title Description Comments:

FILE REVIEW **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Site Visit / Inspection / Sampling

Action Date: 5/5/2011

Received Issue Date: 5/5/2011

Doc Link:

Title Description Comments:

SITE VISIT **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Clean Up Fund - Case Closure Review Summary Report (RSR)

Action Date: 6/2/2010

Received Issue Date: 6/2/2010

Doc Link: [https://geotracker.waterboards.ca.gov/view_documents?](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6391323&temptable=ENFORCEMENT)

[global_id=T0605900976&enforcement_id=6391323&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6391323&temptable=ENFORCEMENT)

Title Description Comments:

Preliminary 5-Year Review **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Staff Letter

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Action Date: 7/14/2009
Received Issue Date: 7/14/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6021060&temptable=ENFORCEMENT

Title Description Comments:

QUARTERLY GROUNDWATER MONITORING REQUIREMENTS **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 2/25/2009
Received Issue Date: 2/25/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6004306&temptable=ENFORCEMENT

Title Description Comments:

CAP ADDENDUM **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 9/12/2007
Received Issue Date: 9/12/2007
Doc Link:

Title Description Comments:

2ND QTR 2007 **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 9/28/2006
Received Issue Date: 9/28/2006
Doc Link:

Title Description Comments:

ISSUED RESPONSE TO CAP ADDENDUM DIRECTED TO INSTALL ADDITIONAL VE WELL **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 4/14/2006
Received Issue Date: 4/14/2006
Doc Link:

Title Description Comments:

ISSUED LETTER REQUESTING ALTERNATIVE CAP.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 9/28/2005
Received Issue Date: 9/28/2005
Doc Link:

Title Description Comments:

ISSUED LETTER REQUESTING CORRECTION OF TABLE 3 FOR RW-1 BENZENE CONCENTRATION.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 6/8/2005
Received Issue Date: 6/8/2005
Doc Link:

Title Description Comments:

Action Type: Other Regulatory Actions

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Action:		Staff Letter				
Action Date:		9/10/2004				
Received Issue Date:		9/10/2004				
Doc Link:						
Title Description Comments:						
ISSUED LETTER REQUESTING THAT EDF COPIES OF GW MONITORING REPORTS BE SUBMITTED TO GEOTRACKER.						
Action Type:		Cleanup Action				
Action:		Pump & Treat (P&T) Groundwater				
Action Date:		1/9/2004				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Cleanup Action				
Action:		Soil Vapor Extraction (SVE)				
Action Date:		1/9/2004				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Other Regulatory Actions				
Action:		Staff Letter				
Action Date:		3/13/2003				
Received Issue Date:		3/13/2003				
Doc Link:						
Title Description Comments:						
ISSUED LETTER REQUESTING THAT THE GROUNDWATER PUMP AND TREAT SYSTEM BE RESTARTED.						
Action Type:		Cleanup Action				
Action:		Excavation				
Action Date:		7/18/1989				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Leak Action				
Action:		Leak Discovery				
Action Date:		6/12/1989				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Leak Action				
Action:		Leak Began				
Action Date:		5/18/1989				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Leak Action				
Action:		Leak Reported				
Action Date:		5/18/1989				
Received Issue Date:						
Doc Link:						
Title Description Comments:						

[GeoTracker Search - Site Maps](#)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR7 (PR7) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2797028541/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR9 (PR9) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1629456520/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR4 (PR4) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7430129945/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012* JOE FREY (AUTH_RP) GEO_MAP https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/2438669860/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR2 (PR2) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6195649147/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR10 (PR10) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6459675610/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR1 (PR1) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7678940773/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR5 (PR5) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9402555108/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR8 (PR8) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5372029125/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR6 (PR6) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7112075746/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		1/3/2012 JOE FREY (AUTH_RP) PR3 (PR3) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/4450276196/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		9/20/2009 JOE FREY (AUTH_RP) GEO_MAP https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/4400063633/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		8/19/2009 JOE FREY (AUTH_RP) SW16 (SW16) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6467725455/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		8/19/2009 JOE FREY (AUTH_RP) SW17 (SW17) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7468407750/T0605900976.PDF				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Submitted: Submitted By: Title: Link:		8/19/2009 JOE FREY (AUTH_RP) VEW9 (VEW9) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/4867357552/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		8/19/2009 JOE FREY (AUTH_RP) SW18 (SW18) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3354439854/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		8/19/2009 JOE FREY (AUTH_RP) SW14 (SW14) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9241051793/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		8/19/2009 JOE FREY (AUTH_RP) SW15 (SW15) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1617712736/T0605900976.PDF				
Submitted: Submitted By: Title: Link:		11/14/2007 JOE FREY (AUTH_RP) GEO_BORE (SW11) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6185459971/T0605900976.pdf				
Submitted: Submitted By: Title: Link:		11/14/2007 JOE FREY (AUTH_RP) GEO_BORE (VEW8) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2100601017/T0605900976.pdf				
Submitted: Submitted By: Title: Link:		11/14/2007 JOE FREY (AUTH_RP) GEO_BORE (SW8) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8734205484/T0605900976.pdf				
Submitted: Submitted By: Title: Link:		11/14/2007 JOE FREY (AUTH_RP) GEO_BORE (SW10) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1717360556/T0605900976.pdf				
Submitted: Submitted By: Title: Link:		11/14/2007 JOE FREY (AUTH_RP) GEO_MAP https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/2589492619/T0605900976.pdf				
Submitted: Submitted By: Title: Link:		11/14/2007 JOE FREY (AUTH_RP) GEO_BORE (SW12) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6037199258/T0605900976.pdf				
Submitted: Submitted By: Title: Link:		11/14/2007 JOE FREY (AUTH_RP) GEO_BORE (SW13) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5893218815/T0605900976.pdf				
Submitted: Submitted By: Title: Link:		11/14/2007 JOE FREY (AUTH_RP) GEO_BORE (SW9) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8461140513/T0605900976.pdf				
Submitted: Submitted By: Title: Link:		5/23/2007 JOE FREY (AUTH_RP) GEO_BORE (VEW7) https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7894534051/T0605900976.pdf				
Submitted: Submitted By: Title:		5/23/2007 JOE FREY (AUTH_RP) GEO_MAP				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Link:					https://geotracker.waterboards.ca.gov/uploads/geo_map/7202161490/T0605900976.pdf	
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW2)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/8418623208/T0605900976.pdf				
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW4)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/1982790887/T0605900976.pdf				
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (VEW6)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/5825932383/T0605900976.pdf				
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW3A)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/6610410928/T0605900976.pdf				
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW7)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/2460146844/T0605900976.pdf				
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW3B)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/8384290397/T0605900976.pdf				
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW5)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/8003477334/T0605900976.pdf				
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW6A)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/2938780069/T0605900976.pdf				
Submitted:		5/23/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW6B)				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_bore/9907393515/T0605900976.pdf				
Submitted:		11/10/2005				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_MAP				
Link:		https://geotracker.waterboards.ca.gov/uploads/geo_map/8922620475/T0605900976.pdf				

GeoTracker Search - Documents

Document Type:	Site Documents	Document Date:	6/26/2014
Type:	CLEAN UP FUND - LETTER TO RP	Submitted:	
Submitted By:	JESSICA AMAYA (REGULATOR)		
Title:	CLAIM 2776 CLOSURE/NO FURTHER ACTION LETTER **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6209871		
Document Type:	Site Documents	Document Date:	4/8/2014
Type:	WELL DESTRUCTION REPORT	Submitted:	
Submitted By:	JOE FREY (AUTH_RP)		
Title:	WELL ABANDONMENT REPORT **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/uploads/geo_report/3610261440/T0605900976.PDF		
Document Type:	Site Documents	Document Date:	9/16/2013

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Type: Submitted By: Title: Title Link:	STATE WATER BOARD - CLOSURE ORDER (REGULATOR) CLAIM 2776 FINAL ORDER STATE WATER BOARD CASE CLOSURE **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6175982		Submitted:			
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CLEAN UP FUND - LETTER TO RP (REGULATOR) CLAIM 2776 PUBLIC NOTICE STATE WATER BOARD CASE CLOSURE **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6165659		Document Date: Submitted:		6/27/2013	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CLEAN UP FUND - CASE CLOSURE REVIEW SUMMARY REPORT (RSR) (REGULATOR) CLAIM 2776 FUND MANAGER CASE CLOSURE RSR/FM DETERMINATION/FM CLOSURE RECOMMENDATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6165656		Document Date: Submitted:		6/27/2013	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REQUEST FOR CLOSURE JOE FREY (AUTH_RP) SITE CONCEPTUAL MODEL AND REQUEST FOR NO FURTHER ACTION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9193211376/T0605900976.PDF		Document Date: Submitted:		4/24/2012*	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FOURTH QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7908522844/T0605900976.PDF		Document Date: Submitted:		1/16/2012	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents OTHER REPORT / DOCUMENT JOE FREY (AUTH_RP) DRILLING AND SAMPLING OF POST-REMEDIATION CONFIRMATION SOIL BORINGS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7867765069/T0605900976.PDF		Document Date: Submitted:		12/30/2011	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CLEAN UP FUND - CASE CLOSURE REVIEW SUMMARY REPORT (RSR) (REGULATOR) 3RD 5-YEAR REVIEW **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6393619		Document Date: Submitted:		12/19/2011	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2985885560/T0605900976.PDF		Document Date: Submitted:		9/23/2011	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STAFF LETTER KEVIN LAMBERT (REGULATOR) CONFIRMATION BORING WORK PLAN **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6098327		Document Date: Submitted:		9/12/2011	
Document Type: Type: Submitted By: Title:	Site Documents SITE INVESTIGATION WORKPLAN JOE FREY (AUTH_RP) WORKPLAN DRILLING AND SAMPLING OF POST REMEDIATION SOIL BORINGS **Note: Many records provided by the department have a truncated [Title] field.		Document Date: Submitted:		8/24/2011	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7396451592/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	8/4/2011	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8958158135/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	5/25/2011	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9404972851/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	5/23/2011	
Type:	REMEDIAL PROGRESS REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FIRST QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6679803431/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	3/15/2011	
Type:	OPERATION AND MAINTENANCE PLAN/MONITORING REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1656168639/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	2/28/2011	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION - FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4024545252/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	1/18/2011	
Type:	INTERIM REMEDIAL ACTION REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIESTHIRD QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3199952125/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	12/30/2010	
Type:	MONITORING REPORT - OTHER			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	VAPOR EXTRACTION REBOUND TESTING **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7947278618/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	12/21/2010*	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3636655449/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	10/27/2010*	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9001078307/T0605900976.PDF					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL REMEDIATION SECOND QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6455693066/T0605900976.PDF			Document Date: Submitted:	7/17/2010	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents OTHER WORKPLAN JOE FREY (AUTH_RP) WORKPLAN - VAPOR EXTRACTION REBOUND TESTING **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7923319518/T0605900976.PDF			Document Date: Submitted:	6/15/2010	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CLEAN UP FUND - CASE CLOSURE REVIEW SUMMARY REPORT (RSR) (REGULATOR) PRELIMINARY 5-YEAR REVIEW **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6391323			Document Date: Submitted:	6/2/2010	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents INTERIM REMEDIAL ACTION REPORT JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6340253472/T0605900976.PDF			Document Date: Submitted:	5/25/2010	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2778420984/T0605900976.PDF			Document Date: Submitted:	5/14/2010	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REMEDIAL PROGRESS REPORT JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES - FOURTH QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6934075772/T0605900976.PDF			Document Date: Submitted:	2/18/2010	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3047013640/T0605900976.PDF			Document Date: Submitted:	1/11/2010	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents INTERIM REMEDIAL ACTION REPORT JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4275384366/T0605900976.PDF			Document Date: Submitted:	12/21/2009	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2424874722/T0605900976.PDF			Document Date: Submitted:	9/24/2009*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents WELL INSTALLATION REPORT JOE FREY (AUTH_RP) INSTALLATION OF OFF-SITE REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field.			Document Date: Submitted:	8/10/2009	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5944952726/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	8/6/2009	
Type:	INTERIM REMEDIAL ACTION REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGE REMEDIATION ACTIVITIES SECOND QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9561593472/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	8/6/2009	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8304541349/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	7/14/2009	
Type:	STAFF LETTER			Submitted:		
Submitted By:	KEVIN LAMBERT (REGULATOR)					
Title:	QUARTERLY GROUNDWATER MONITORING REQUIREMENTS **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6021060					
Document Type:	Monitoring Reports			Document Date:	6/24/2009	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS AND GROUNDWATER REMEDIATION FIRST QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4564330160/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	3/10/2009	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDATION ACTIVITIES FOURTH QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9740206062/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	2/25/2009	
Type:	STAFF LETTER			Submitted:		
Submitted By:	KEVIN LAMBERT (REGULATOR)					
Title:	CAP ADDENDUM **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900976&enforcement_id=6004306					
Document Type:	Monitoring Reports			Document Date:	2/17/2009	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITROING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2811403572/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	1/30/2009	
Type:	CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN - ADDENDUM			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	ADDENDUM TO CORRECTIVE ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6785095691/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	11/20/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4708542346/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	10/15/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Title:		GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7741570889/T0605900976.PDF				
Document Type:	Monitoring Reports			Document Date:	10/6/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2434722721/T0605900976.PDF				
Document Type:	Site Documents			Document Date:	8/8/2008	
Type:	REMEDIAL PROGRESS REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1471514642/T0605900976.PDF				
Document Type:	Site Documents			Document Date:	7/14/2008	
Type:	REMEDIAL PROGRESS REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		SOIL VAPOR EXTRACTION AND AIR SPARGINH REMEDIATION ACTIVITIES FIRST QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8190464854/T0605900976.PDF				
Document Type:	Monitoring Reports			Document Date:	6/6/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7905561149/T0605900976.PDF				
Document Type:	Monitoring Reports			Document Date:	3/11/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FOURTH QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2835453867/T0605900976.PDF				
Document Type:	Monitoring Reports			Document Date:	2/26/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2157336175/T0605900976.PDF				
Document Type:	Monitoring Reports			Document Date:	1/21/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1083463907/T0605900976.PDF				
Document Type:	Site Documents			Document Date:	11/14/2007	
Type:	REPORTS - INVESTIGATION RPT.			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		INSTALLATION OF ADDITIONAL OFF-SITE REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7872012078/T0605900976.PDF				
Document Type:	Monitoring Reports			Document Date:	11/5/2007	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:		GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/2463305413/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	8/30/2007	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2007					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/9299822747/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	7/31/2007	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2007					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/9614759683/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	6/6/2007*	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	THIRD QUARTER 2006, GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/4581648111/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	6/1/2007	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2007					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/2427915811/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	5/23/2007	
Type:	REPORTS - INVESTIGATION RPT.			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	INSTALLATION OF ADDITIONAL REMEDIAL WELLS					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/2969129800/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	2/8/2007	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION, FOURTH QUARTER 2006					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/4688764810/T0605900976.PDF					
Document Type:	Monitoring Reports			Document Date:	9/11/2006*	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION SECOND QUARTER 2006					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/7755597770/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	7/21/2006*	
Type:	WORKPLANS - REMEDIAL ACTION PLAN			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	ADDENDUM TO CORRECTIVE ACTION PLAN					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/7331662833/T0605900976.PDF					
Document Type:	Site Documents			Document Date:	7/3/2006*	
Type:	REPORTS - REMEDIAL ACTION RPT.			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	VAPOR EXTRACTION, AIR SPARGING AND GROUNDWATER TREATMENT SYSTEM PERFORMANCE - FIRST QUARTER 2006					
	**Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/9230649650/T0605900976.PDF					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5131728947/T0605900976.PDF			Document Date: Submitted:	4/27/2006*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REPORTS - REMEDIAL ACTION RPT. JOE FREY (AUTH_RP) NPDES MONITORING REPORT - MARCH 2006 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4740949332/T0605900976.PDF			Document Date: Submitted:	4/21/2006*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REPORTS - REMEDIAL ACTION RPT. JOE FREY (AUTH_RP) VAPOR EXTRACTION, AIR SPARGING AND GROUNDWATER TREATMENT SYSTEM PERFORMANCE - FOURTH QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7524844110/T0605900976.PDF			Document Date: Submitted:	4/11/2006*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REPORTS - REMEDIAL ACTION RPT. JOE FREY (AUTH_RP) NPDES MONITORING REPORT - FEBRUARY 2006 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4364491105/T0605900976.PDF			Document Date: Submitted:	3/31/2006*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REPORTS - REMEDIAL ACTION RPT. JOE FREY (AUTH_RP) NPDES MONITORING REPORT - JANUARY 2006 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3238921940/T0605900976.PDF			Document Date: Submitted:	2/28/2006*	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION FOURTH QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2485534489/T0605900976.PDF			Document Date: Submitted:	1/27/2006	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REPORTS - REMEDIAL ACTION RPT. JOE FREY (AUTH_RP) NPDES MONITORING REPORT - DECEMBER 2005 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2327527701/T0605900976.PDF			Document Date: Submitted:	1/25/2006*	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REPORTS - REMEDIAL ACTION RPT. JOE FREY (AUTH_RP) VAPOR EXTRACTION, AIR SPARGING AND GROUNDWATER TREATMENT SYSTEM PERFORMANCE - THIRD QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9880628287/T0605900976.PDF			Document Date: Submitted:	1/5/2006	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION SECOND QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9758130729/T0605900976.PDF			Document Date: Submitted:	11/10/2005	
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION THIRD QUARTER 2005 **Note: Many records provided by the department have a truncated [Title]			Document Date: Submitted:	11/10/2005	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Title Link:		field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8361905753/T0605900976.PDF				
Document Type:	Monitoring Reports			Document Date:	11/10/2005	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION FIRST QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field.				
Title:						
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6267852604/T0605900976.PDF				
Document Type:	Site Documents			Document Date:	10/6/2005	
Type:	REPORTS - REMEDIAL ACTION RPT.			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)	VAPOR EXTRACTION, AIR SPARGING AND GROUNDWATER TREATMENT SYSTEM PERFORMANCE - SECOND QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field.				
Title:						
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7869718253/T0605900976.PDF				
Document Type:	Site Documents			Document Date:	9/21/2005	
Type:	REPORTS - REMEDIAL ACTION RPT.			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)	NPDES MONITORING REPORT - AUGUST 2005 **Note: Many records provided by the department have a truncated [Title] field.				
Title:						
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4509549796/T0605900976.PDF				

21	3 of 7	NE	0.18 / 944.26	76.08 / 2	A SAADAI UNION 76 13231 BROOKHURST ST. GARDEN GROVE CA 92643	HHSS
County:						
Tank Details Microfiche:		http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002e488.pdf				

21	4 of 7	NE	0.18 / 944.26	76.08 / 2	Andys Unocal 13231 Brookhurst St Garden Grove Ca 92843-1009 CA	LOP ORANGE
Case ID: 89UT095						
Details						
Current Status:		Closed				
Type of Closure:		Closure certification issued				
Closed Date:		5/26/2014				
File Location:		Local Agency				

21	5 of 7	NE	0.18 / 944.26	76.08 / 2	A. SAADI UNION 76 13231 BROOKHURST ST. GARDEN GROVE CA	HIST TANK
Owner Name:	ABOLFAZL SAADAI			No of Containers:	3	
Owner Street:	13231 BROOKHURST ST.			County:	ORANGE	
Owner City:	GARDEN GROVE			Facility State:	CA	
Owner State:	CA			Facility Zip:	92643	
Owner Zip:	92643					

21	6 of 7	NE	0.18 / 944.26	76.08 / 2	FKA Andy's Unocal 13231 Brookhurst Ave., Garden Grove, CA 92643 CA	UST CLOSURE
Claim Case No: Claim No. 2776						
ID:		2776				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Deadline to Recv Comments:		2013/08/28				
Prop UST Case Closure Type:		Closure of Underground Storage Tank (UST) Cases - Closure Denials and Approved Orders				
<u>Documents</u>						
Doc Type:		Final Closure Summary				
Documents Link:		https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/7862303018/2776%20Review%20Summary.pdf				
Doc Type:		Notice				
Documents Link:		https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/9569813370/2776%20Public%20Notice.pdf				
Doc Type:		Exec Draft Order				
Documents Link:		https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/6603347599/2776%20Draft%20Order.pdf				
<u>Closur Denial Approved Orders</u>						
Doc Title:		WQO 2013-0085-UST (09/16/2013)				
Denial Link:		https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/2417849481/2776%20wqo%202013-0085.pdf				
<u>Closure Letter Signed</u>						
Letter Title:		Uniform Closure Letter (06/19/2014)				
Letter Link:		https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/4241154551/2776%20NFA%20FINAL.pdf				
<u>Main Info Details</u>						
Site Name:		FKA Andy's Unocal				
Site Address:		13231 Brookhurst Ave., Garden Grove, CA 92643				

21	7 of 7	NE	0.18 / 944.26	76.08 / 2	VN AUTO 13231 BROOKHURST ST GARDEN GROVE CA 92843	RCRA NON GEN
--------------------	--------	----	---------------	-----------	---	-----------------

Handler ID: CAP000186775
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>Additional Handler Summary Details</u>						
Source Type:	N			NAIC 1:	44112	
Seq No:	1			NAIC 2:		
Non Notifier:				NAIC 3:		
Receive Date:	20071210			NAIC 4:		
Active Site:	-----			State:	CA	
Land Type:	P			Location Latitude:		
In Handler Univ:	N			Location Longitude:		
In A Universe:	N			Loc GIS Primary:	N	
Gen Status:	N			Loc GIS Origin:		
Report Cycle:				State District Owner:		
Accessibility:				State District:		
Region:	09					
Fed Waste Gen Owner:	HQ					
State Waste Generator Owner:	CA					
State Waste Generator:	N					
Short Term Generator:	N					
Uni Waste:	N					
Universal Waste Dest Facility:	N					
Federal Universal Waste:	N					
As Federally Regulated Tsdf:	-----					
As Converter Tsdf:	-----					
As State Regulated Tsdf:	-----					
As State Regulated Handler:	---					
Federal Indicator:	---					
Hsm:	N					
Subpart K:	----					
GPRA Permit:	N					
GPRA Renewal:	N					
Permit Renewal Wrkld:	-----					
Permwrk ID:	-----					
Perm Prog:	-----					
Pcwrkld:	-----					
Closwrkld:	-----					
GPRA Ca:	N					
Cawrkld:	N					
Subjca Tsd Discretion:	N					
NCAPS:	N					
EC Indicator:	N					
Ca725 Indicator:	N					
Ca750 Indicator:	N					
Operating Tsdf:	-----					
Full Enforcement:	-----					
Snc:	N					
Unaddressed Snc:	N					
Addressed Snc:	N					
Snc With Comp Sched:	N					
Fa Required:	----					
Hhandler Last Change:	20071210					
Recognized Trader Importer:	N					
Recognized Trader Exporter:	N					
Slab Importer:	N					
Slab Exporter:	N					
Manifest Broker:	N					
Subpart P:	N					
Contact Language:	EN					
Handler Name:	VN AUTO					
Location Street No:						
Location Street1:	13231 BROOKHURST ST					
Location Street2:						
Location City:	GARDEN GROVE					
Location State:	CA					
Location Zip:	92843					
Location County Code:	CA059					
Location County Name:	ORANGE					
Location Country:	US					
Contact Name:	ED D RANDS					
Contact Street No:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Street1:		2817 A LAFAYETTE AVE				
Contact Street2:						
Contact City:		NEWPORT BEACH				
Contact State:		CA				
Contact Zip:		92663				
Contact Country:		US				
Contact Phone And Ext:		949-723-1645				
Contact Fax:						
Contact Email Address:		EDRANDS@FREYINC.COM				
Contact Title:						
Owner Name:		DON THIO				
Owner Type:		P				
Owner Seq:		1				
Operator Name:		VN AUTO				
Operator Type:		P				
Operator Seq:		2				
Public Notes:						

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20070828
 Handler Name: VN AUTO
 Fed Waste Generator: 1
 Generator Code Description: Large Quantity Generator
 Source Type: Temporary

Waste Code Details

Waste Code: D002
 Waste Code Desc: CORROSIVE WASTE

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20071210
 Handler Name: VN AUTO
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Notification

Owner/Operator Details

Owner/Operator Ind: Current Owner
 Type: Private
 Name: DON THIO
 Dt Became Current: 19950101
 Dt Ended Current:
 Phone:
 Source Type: Notification

Street No:
 Street1: 11478 WHITTIER AVE
 Street2:
 City: LOMA LINDA
 State: CA
 Country: US
 Zip: 92354

Owner/Operator Ind: Current Owner
 Type: Private
 Name: DON THIO
 Dt Became Current: 19950101
 Dt Ended Current:
 Phone:
 Source Type: Temporary

Street No:
 Street1: 11478 WHITTIER AVE
 Street2:
 City: LOMA LINDA
 State: CA
 Country: US
 Zip: 92354

Owner/Operator Ind: Current Operator
 Type: Private
 Name: VN AUTO
 Dt Became Current: 19950101

Street No:
 Street1:
 Street2:
 City:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Dt Ended Current:				State:
Phone:				Country:
Source Type:	Temporary			Zip:
Owner/Operator Ind:	Current Operator			Street No:
Type:	Private			Street1:
Name:	VN AUTO			Street2:
Dt Became Current:	19950101			City:
Dt Ended Current:				State:
Phone:				Country:
Source Type:	Notification			Zip:

Historical Handler Details

Receive Dt:	20070828
Generator Code Description:	Large Quantity Generator
Handler Name:	VN AUTO

<u>22</u>	1 of2	NE	0.18 / 960.03	76.08 / 2	DON THIO 13231 S BROOKHURST ST GARDEN GROVE CA	UST SWEEPS
---------------------------	-------	----	------------------	--------------	--	------------

C C:	A30-000-13410	D Filename:	SITE12A
BOE:		Page No:	123
Comp:	13410	County:	ORANGE
Status:	ACTIVE	State :	CA
No of Tanks:	4	Zip:	92644
Jurisdic:	ORANGE COUNTY	Latitude:	0
Agency:	ENVIRONMENTAL HEALTH	Longitude:	0
Phone:		Georesult:	N

Tank Details

Tank ID:	000004	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-013410-000004	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	DIESEL
Capac:	10000	ONA:	
Tank Use:	M.V. FUEL	D File Name:	TANK12A

Tank Details

Tank ID:	000002	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-013410-000002	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	REG UNLEADED
Capac:	10000	ONA:	
Tank Use:	M.V. FUEL	D File Name:	TANK12A

Tank Details

Tank ID:	000001	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-013410-000001	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	
Capac:	550	ONA:	
Tank Use:	PETROLEUM	D File Name:	TANK12A

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>Tank Details</u>						
Tank ID:	000003				S Contain:	
O Tank ID:					Stg:	P
SWRCB No:	30-000-013410-000003				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	REG UNLEADED
Capac:	10000				ONA:	
Tank Use:	M.V. FUEL				D File Name:	TANK12A
22	2 of 2	NE	0.18 / 960.03	76.08 / 2	KARAMAT STATION 13231 S BROOKHURST ST GARDEN GROVE CA	UST SWEEPS
C C:	A30-000-4349				D Filename:	SITE12A
BOE:	44-016176				Page No:	123
Comp:	4349				County:	ORANGE
Status:	ACTIVE				State :	CA
No of Tanks:	4				Zip:	92644
Jurisdic:	ORANGE COUNTY				Latitude:	0
Agency:	ENVIRONMENTAL HEALTH				Longitude:	0
Phone:					Georesult:	N
<u>Tank Details</u>						
Tank ID:	000001				S Contain:	
O Tank ID:					Stg:	P
SWRCB No:	30-000-004349-000001				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	
Capac:	550				ONA:	
Tank Use:	PETROLEUM				D File Name:	TANK12A
<u>Tank Details</u>						
Tank ID:	000004				S Contain:	
O Tank ID:					Stg:	P
SWRCB No:	30-000-004349-000004				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	REG UNLEADED
Capac:	10000				ONA:	
Tank Use:	M.V. FUEL				D File Name:	TANK12A
<u>Tank Details</u>						
Tank ID:	000003				S Contain:	
O Tank ID:					Stg:	P
SWRCB No:	30-000-004349-000003				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	REG UNLEADED
Capac:	10000				ONA:	
Tank Use:	M.V. FUEL				D File Name:	TANK12A
<u>Tank Details</u>						
Tank ID:	000005				S Contain:	
O Tank ID:					Stg:	P

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
SWRCB No:	30-000-004349-000005				Storage :	
Removed:					Storag Type:	PRODUCT
Installed:					P Contain:	
A Date:					Content:	DIESEL
Capac:	10000				ONA:	
Tank Use:	M.V. FUEL				D File Name:	TANK12A

[23](#) 1 of1 WNW 0.19 / 984.44 72.50 / -1 DANG DANG 9672 IMPERIAL AVENUE GARDEN GROVE CA 92844 RCRA NON GEN

Handler ID: CAC003205204
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20221121	NAIC 4:	
Active Site:	----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Permit Renewal Wrkld:	-----					
Permwrk ID:	-----					
Perm Prog:	-----					
Pcwrkld:	-----					
Closwrkld:	-----					
GPRA Ca:	N					
Cawrkld:	N					
Subjca Tsd Discretion:	N					
NCAPS:	N					
EC Indicator:	N					
Ca725 Indicator:	N					
Ca750 Indicator:	N					
Operating Tsdf:	-----					
Full Enforcement:	-----					
Snc:	N					
Unaddressed Snc:	N					
Addressed Snc:	N					
Snc With Comp Sched:	N					
Fa Required:	-----					
Hhandler Last Change:	20221121					
Recognized Trader Importer:	N					
Recognized Trader Exporter:	N					
Slab Importer:	N					
Slab Exporter:	N					
Manifest Broker:	N					
Subpart P:	N					
Contact Language:	EN					
Handler Name:	DANG DANG					
Location Street No:						
Location Street1:	9672 IMPERIAL AVENUE					
Location Street2:						
Location City:	GARDEN GROVE					
Location State:	CA					
Location Zip:	92844					
Location County Code:	CA059					
Location County Name:	ORANGE					
Location Country:	US					
Contact Name:	DANG DANG					
Contact Street No:						
Contact Street1:	9672 IMPERIAL AVENUE					
Contact Street2:						
Contact City:	GARDEN GROVE					
Contact State:	CA					
Contact Zip:	92844					
Contact Country:						
Contact Phone And Ext:	714-308-0927					
Contact Fax:						
Contact Email Address:	KARLA@SUPERIORENV.COM					
Contact Title:						
Owner Name:	DANG DANG					
Owner Type:	O					
Owner Seq:	1					
Operator Name:	DANG DANG					
Operator Type:	O					
Operator Seq:	2					
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20221121
Handler Name:	DANG DANG
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9672 IMPERIAL AVENUE
Name:	DANG DANG	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-308-0927	Country:	
Source Type:	Implementer	Zip:	92844

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	9672 IMPERIAL AVENUE
Name:	DANG DANG	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-308-0927	Country:	
Source Type:	Implementer	Zip:	92844

24	1 of2	ENE	0.19 / 986.51	76.29 / 3	MARIE CALLENDARS 13252 BROOKHURST STREET GARDEN GROVE CA 92843	RCRA NON GEN
--------------------	-------	-----	------------------	--------------	--	-----------------

Handler ID:	CAC003164178
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).
--------------	--

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20220301	NAIC 4:	
Active Site:	-----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Short Term Generator:		N				
Uni Waste:		N				
Universal Waste Dest Facility:		N				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20220301				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		MARIE CALLENDARS				
Location Street No:						
Location Street1:		13252 BROOKHURST STREET				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		DAVE QUIMBY				
Contact Street No:						
Contact Street1:		1320 N MANZANITA STREET				
Contact Street2:						
Contact City:		ORANGE				
Contact State:		CA				
Contact Zip:		92867				
Contact Country:						
Contact Phone And Ext:		714-633-7844				
Contact Fax:						
Contact Email Address:		DQUIMBY@RODRIGOS.COM				
Contact Title:						
Owner Name:		ROD FRASER ENTERPRISES, INC				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		DAVE QUIMBY				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20220301
Handler Name:	MARIE CALLENDARS
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	1320 N MANZANITA STREET
Name:	ROD FRASER ENTERPRISES, INC	Street2:	
Dt Became Current:		City:	ORANGE
Dt Ended Current:		State:	CA
Phone:	714-633-7844	Country:	
Source Type:	Implementer	Zip:	92867
Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	1320 N MANZANITA STREET
Name:	DAVE QUIMBY	Street2:	
Dt Became Current:		City:	ORANGE
Dt Ended Current:		State:	CA
Phone:	714-633-7844	Country:	
Source Type:	Implementer	Zip:	92867

24	2 of2	ENE	0.19 / 986.51	76.29 / 3	13252 BROOKHURST ST 13252 BROOKHURST ST GARDEN GROVE CA 92843	RCRA NON GEN
--------------------	-------	-----	------------------	--------------	---	-----------------

Handler ID:	CAC003246861
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).
--------------	--

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Non Notifier:				NAIC 3:		
Receive Date:	20230814			NAIC 4:		
Active Site:	-----			State:	CA	
Land Type:				Location Latitude:		
In Handler Univ:	N			Location Longitude:		
In A Universe:	N			Loc GIS Primary:	N	
Gen Status:	N			Loc GIS Origin:		
Report Cycle:				State District Owner:		
Accessibility:				State District:		
Region:	09					
Fed Waste Gen Owner:		HQ				
State Waste Generator Owner:		CA				
State Waste Generator:		2				
Short Term Generator:		N				
Uni Waste:		N				
Universal Waste Dest Facility:		N				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20241212				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		13252 BROOKHURST ST				
Location Street No:						
Location Street1:		13252 BROOKHURST ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		JEREMY BECK				
Contact Street No:						
Contact Street1:		13252 BROOKHURST ST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Contact Zip:	92843
Contact Country:	
Contact Phone And Ext:	949-991-4500
Contact Fax:	
Contact Email Address:	LISA@5MCONTRACTING.ORG
Contact Title:	
Owner Name:	MELIA HOMES
Owner Type:	O
Owner Seq:	1
Operator Name:	JEREMY BECK
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20230814
Handler Name:	13252 BROOKHURST ST
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	13252 BROOKHURST ST
Name:	JEREMY BECK	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	949-991-4500	Country:	
Source Type:	Implementer	Zip:	92843
Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9660 IRVINE CENTER DR
Name:	MELIA HOMES	Street2:	
Dt Became Current:		City:	IRVINE
Dt Ended Current:		State:	CA
Phone:	949-991-4500	Country:	
Source Type:	Implementer	Zip:	92843

25	1 of1	WNW	0.19 / 1,015.19	72.69 / -1	9671 IMPERIAL AVE 9671 IMPERIAL AVE GARDEN GROVE CA 92844	RCRA NON GEN
--------------------	-------	-----	--------------------	---------------	---	-----------------

Handler ID:	CAC003108729
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).
-------	--

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Additional Handler Summary Details

Source Type:	I			NAIC 1:	56299
Seq No:	1			NAIC 2:	
Non Notifier:				NAIC 3:	
Receive Date:	20210305			NAIC 4:	
Active Site:	----			State:	CA
Land Type:				Location Latitude:	
In Handler Univ:	N			Location Longitude:	
In A Universe:	N			Loc GIS Primary:	N
Gen Status:	N			Loc GIS Origin:	
Report Cycle:				State District Owner:	
Accessibility:				State District:	
Region:	09				
Fed Waste Gen Owner:	HQ				
State Waste Generator Owner:	CA				
State Waste Generator:	2				
Short Term Generator:	N				
Uni Waste:	N				
Universal Waste Dest Facility:	N				
Federal Universal Waste:	N				
As Federally Regulated Tsdf:	-----				
As Converter Tsdf:	-----				
As State Regulated Tsdf:	-----				
As State Regulated Handler:	---				
Federal Indicator:	---				
Hsm:	N				
Subpart K:	----				
GPRA Permit:	N				
GPRA Renewal:	N				
Permit Renewal Wrkld:	-----				
Permwrk ID:	-----				
Perm Prog:	-----				
Pcwrkld:	-----				
Closwrkld:	-----				
GPRA Ca:	N				
Cawrkld:	N				
Subjca Tsd Discretion:	N				
NCAPS:	N				
EC Indicator:	N				
Ca725 Indicator:	N				
Ca750 Indicator:	N				
Operating Tsdf:	-----				
Full Enforcement:	-----				
Snc:	N				
Unaddressed Snc:	N				
Addressed Snc:	N				
Snc With Comp Sched:	N				
Fa Required:	----				
Hhandler Last Change:	20241211				
Recognized Trader Importer:	N				
Recognized Trader Exporter:	N				
Slab Importer:	N				
Slab Exporter:	N				
Manifest Broker:	N				
Subpart P:	N				
Contact Language:	EN				
Handler Name:	9671 IMPERIAL AVE				
Location Street No:					
Location Street1:	9671 IMPERIAL AVE				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Location Street2:
Location City: GARDEN GROVE
Location State: CA
Location Zip: 92844
Location County Code: CA059
Location County Name: ORANGE
Location Country: US
Contact Name: HERNANDEZ SHELLIE LIVING TRUST
Contact Street No:
Contact Street1: 9671 IMPERIAL AVE
Contact Street2:
Contact City: GARDEN GROVE
Contact State: CA
Contact Zip: 92844
Contact Country:
Contact Phone And Ext: 714-329-2717
Contact Fax:
Contact Email Address: SHELLEB54@GMAIL.COM
Contact Title:
Owner Name: HERNANDEZ SHELLIE LIVING TRUST
Owner Type: O
Owner Seq: 1
Operator Name: HERNANDEZ SHELLIE LIVING TRUST
Operator Type: O
Operator Seq: 2
Public Notes:

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20210305
Handler Name: 9671 IMPERIAL AVE
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	9671 IMPERIAL AVE
Name:	HERNANDEZ SHELLIE LIVING TRUST	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-329-2717	Country:	
Source Type:	Implementer	Zip:	92844

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9671 IMPERIAL AVE
Name:	HERNANDEZ SHELLIE LIVING TRUST	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-329-2717	Country:	
Source Type:	Implementer	Zip:	92844

26	1 of 2	WNW	0.21 / 1,106.38	72.51 / -1	MEAAALII LOLOGO 9642 IMPERIAL AVE GARDEN GROVE CA 92844	RCRA NON GEN
--------------------	--------	-----	--------------------	---------------	---	-----------------

Handler ID: CAC003257686
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	2	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20240918	NAIC 4:	
Active Site:	-----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	D		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	-----		
Full Enforcement:	-----		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20240918				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		MEAALII LOLOGO				
Location Street No:						
Location Street1:		9642 IMPERIAL AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		MEAALII LOLOGO				
Contact Street No:						
Contact Street1:		9642 IMPERIAL AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:						
Contact Phone And Ext:		714-381-8058				
Contact Fax:						
Contact Email Address:		MAC.S.LOLOGO@GMAIL.COM				
Contact Title:						
Owner Name:						
Owner Type:						
Owner Seq:						
Operator Name:						
Operator Type:						
Operator Seq:						
Public Notes:						

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20231023
 Handler Name: MEAALII LOLOGO
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Implementer

Hazardous Waste Handler Details

Seq No: 2
 Receive Date: 20240918
 Handler Name: MEAALII LOLOGO
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9642 IMPERIAL AVE
Name:	MEAALII LOLOGO	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Phone:	714-381-8058				Country:	
Source Type:	Implementer				Zip:	92844
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Other				Street1:	9642 IMPERIAL AVE
Name:	MEAALII LOLOGO				Street2:	
Dt Became Current:					City:	GARDEN GROVE
Dt Ended Current:					State:	CA
Phone:	714-381-8058				Country:	
Source Type:	Implementer				Zip:	92844

Historical Handler Details

Receive Dt: 20231023
 Generator Code Description: Not a Generator, Verified
 Handler Name: MEAALII LOLOGO

26	2 of 2	WNW	0.21 / 1,106.38	72.51 / -1	MEAALII LOLOGO 9642 IMPERIAL AVE GARDEN GROVE CA 92844	RCRA NON GEN
--------------------	--------	-----	--------------------	---------------	--	-----------------

Handler ID: CAC003257533
 Generator Status: N
 Recycler Activity?: NO
 Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	2	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20240918	NAIC 4:	
Active Site:	----	State:	CA
Land Type:		Location Latitude:	
In Handler Univ:	N	Location Longitude:	
In A Universe:	N	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	D		
Short Term Generator:	N		
Uni Waste:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Universal Waste Dest Facility:		N				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		----				
Hhandler Last Change:		20240918				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		MEAALII LOLOGO				
Location Street No:						
Location Street1:		9642 IMPERIAL AVE				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		MEAALII LOLOGO				
Contact Street No:						
Contact Street1:		9642 IMPERIAL AVE				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:						
Contact Phone And Ext:		714-381-8058				
Contact Fax:						
Contact Email Address:		MAC.S.LOLOGO@GMAIL.COM				
Contact Title:						
Owner Name:						
Owner Type:						
Owner Seq:						
Operator Name:						
Operator Type:						
Operator Seq:						
Public Notes:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20231020
Handler Name:	MEAALII LOLOGO
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Hazardous Waste Handler Details

Seq No:	2
Receive Date:	20240918
Handler Name:	MEAALII LOLOGO
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9642 IMPERIAL AVE
Name:	MEAALII LOLOGO	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-381-8058	Country:	
Source Type:	Implementer	Zip:	92844

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	9642 IMPERIAL AVE
Name:	MEAALII LOLOGO	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-381-8058	Country:	
Source Type:	Implementer	Zip:	92844

Historical Handler Details

Receive Dt:	20231020
Generator Code Description:	Not a Generator, Verified
Handler Name:	MEAALII LOLOGO

27	1 of 4	NE	0.21 / 1,110.53	74.00 / 0	BOWERS COMPANIES 13222 BROOKHURST ST GARDEN GROVE CA 92840	RCRA NON GEN
--------------------	--------	----	-----------------	-----------	--	-----------------

Handler ID:	CAD028230811
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).
-------	--

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Transporter:	Yes				Used Oil Processor:	No
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Additional Handler Summary Details

Source Type:	N			NAIC 1:	
Seq No:	1			NAIC 2:	
Non Notifier:				NAIC 3:	
Receive Date:	19860407			NAIC 4:	
Active Site:	H----			State:	CA
Land Type:	O			Location Latitude:	33.770826
In Handler Univ:	Y			Location Longitude:	-117.954914
In A Universe:	Y			Loc GIS Primary:	N
Gen Status:	N			Loc GIS Origin:	AG
Report Cycle:				State District Owner:	CA
Accessibility:				State District:	4
Region:	09				
Fed Waste Gen Owner:	HQ				
State Waste Generator Owner:	HQ				
State Waste Generator:	N				
Short Term Generator:	N				
Uni Waste:	N				
Universal Waste Dest Facility:	N				
Federal Universal Waste:	N				
As Federally Regulated Tsdf:	-----				
As Converter Tsdf:	-----				
As State Regulated Tsdf:	-----				
As State Regulated Handler:	---				
Federal Indicator:	---				
Hsm:	N				
Subpart K:	----				
GPRA Permit:	N				
GPRA Renewal:	N				
Permit Renewal Wrkld:	-----				
Permwrk ID:	-----				
Perm Prog:	-----				
Pcwrkld:	-----				
Closwrkld:	-----				
GPRA Ca:	N				
Cawrkld:	N				
Subjca Tsd Discretion:	N				
NCAPS:	N				
EC Indicator:	N				
Ca725 Indicator:	N				
Ca750 Indicator:	N				
Operating Tsdf:	-----				
Full Enforcement:	-----				
Snc:	N				
Unaddressed Snc:	N				
Addressed Snc:	N				
Snc With Comp Sched:	N				
Fa Required:	-----				
Hhandler Last Change:	20020627				
Recognized Trader Importer:	N				
Recognized Trader Exporter:	N				
Slab Importer:	N				
Slab Exporter:	N				
Manifest Broker:	N				
Subpart P:	N				
Contact Language:	EN				
Handler Name:	BOWERS COMPANIES				
Location Street No:					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Location Street1:		13222 BROOKHURST ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92840				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		ENVIRONMENTAL MANAGER				
Contact Street No:						
Contact Street1:		13222 BROOKHURST ST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92640				
Contact Country:		US				
Contact Phone And Ext:		213-591-0501				
Contact Fax:						
Contact Email Address:						
Contact Title:						
Owner Name:		ROBERT BOWERS				
Owner Type:		P				
Owner Seq:		1				
Operator Name:		NOT REQUIRED				
Operator Type:		P				
Operator Seq:		2				
Public Notes:						

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 19860407
 Handler Name: BOWERS COMPANIES
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Notification

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Private	Street1:	NOT REQUIRED
Name:	ROBERT BOWERS	Street2:	
Dt Became Current:		City:	NOT REQUIRED
Dt Ended Current:		State:	ME
Phone:	415-555-1212	Country:	
Source Type:	Notification	Zip:	99999

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Private	Street1:	NOT REQUIRED
Name:	NOT REQUIRED	Street2:	
Dt Became Current:		City:	NOT REQUIRED
Dt Ended Current:		State:	ME
Phone:	415-555-1212	Country:	
Source Type:	Notification	Zip:	99999

27	2 of 4	NE	0.21 / 1,110.53	74.00 / 0	BOWERS CO 13222 BROOKHURST ST GARDEN GROVE CA 92843	DELISTED TNK
--------------------	--------	----	--------------------	--------------	---	-------------------------

Delisted Storage Tanks

Facility ID:	10117	County:	Orange
Latitude:	33.7721264	Original Source:	UST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Longitude:	-117.953266				Record Date:	30-JAN-2017
Permitting Agency:	ORANGE COUNTY					

27	3 of 4	NE	0.21 / 1,110.53	74.00 / 0	BOWERS CO 13222 BROOKHURST GARDEN GROVE CA 92844	LUST
--------------------	--------	----	--------------------	--------------	--	------

Global ID:	T0605900855	Case Type (DL):	LUST Cleanup Site
Site Facility Type:	LUST CLEANUP SITE	Oil Field (SRCH):	
Site Fac Type (SRCH):	LUST CLEANUP SITE	Oil Field Oper (SRCH):	
Status:		Census Tract (SRCH):	6059088702
Status (SRCH):	COMPLETED - CASE CLOSED	Latitude (DL):	33.7707223
Status (DL):	Completed - Case Closed	Longitude (DL):	-117.9548774
Status Date (DL):	3/27/2013	RWQCB Region (DL):	SANTA ANA RWQCB (REGION 8)
Cleanup Status:	COMPLETED - CASE CLOSED		
Site Facility Name (SRCH):	BOWERS CO		
Address (SRCH):	13222 BROOKHURST		
City (SRCH):	GARDEN GROVE		
Zip (SRCH):	92844		
County (SRCH):	ORANGE		
Street No (DL):	13222		
Street Name (DL):	BROOKHURST		
City (DL):	GARDEN GROVE		
Zip (DL):	92844		
County (DL):	Orange		
State (DL):	CA		
Business Name (DL):	BOWERS CO		
Site Facility Name:	BOWERS CO		
Address :	13222 BROOKHURST		
City :	GARDEN GROVE		
Zip :	92844		
County :	ORANGE		
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search		

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	ORANGE COUNTY LOP
Case Worker:	
Local Agency:	
RB Case No:	083001081T
Local Case No:	88UT176
File Location:	Local Agency
Potential COC:	Gasoline
Potential Media of Concern:	Aquifer used for drinking water supply
Begin Date:	9/23/1988
How Discovered:	Tank Closure
How Discovered Description:	
Stop Method:	Close and Remove Tank
Stop Description:	
Calwater Watershed Name:	Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name:	Coastal Plain Of Orange County (8-001)
Disadvantaged Community:	
CalEnvScreen Score:	
Coordinate Source:	* Historical Geocode - Exact Address Match
Discharge Cause:	
Discharge Source:	Tank
EPA Region:	9
Leak Reported Dt:	1989-01-12 00:00:00
Military DoD Site:	No
No Further Action Dt:	2013-03-27 00:00:00
Qty Rlsd Gallons:	0
Facility Project Sub Type:	
Calenviroscreen 3 Score:	51-55%
Calenviroscreen 4 Score:	60-65%
A2022 Assembly District:	70

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Claim No:		2680				
Claim Status:		Active				
A2022 Congressional District:		45				
A2022 Senate District:		36				
Site History:						

Please refer to recent Site Documents or Monitoring Reports in GeoTracker for site history. Orange County is not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants for the responsible party. CASE CLOSED PURSUANT TO STATE WATER RESOURCES CONTROL BOARD ORDER.

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: MIGUEL OVIEDO
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 Main Street, Suite 500
City: RIVERSIDE
Email: miguel.oviedo@waterboards.ca.gov
Phone No: 9517823238

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 3/27/2013

Status: Open - Eligible for Closure
Status Date: 3/26/2013

Status: Completed - Case Closed
Status Date: 4/19/2012

Status: Completed - Case Closed
Status Date: 4/12/2012

Status: Open - Remediation
Status Date: 1/9/2004

Status: Open - Remediation
Status Date: 5/5/1997

Status: Open - Site Assessment
Status Date: 6/30/1995

Status: Open - Site Assessment
Status Date: 6/17/1991

Status: Open - Site Assessment
Status Date: 9/23/1988

Status: Open - Case Begin Date
Status Date: 9/23/1988

GeoTracker Search - Regulatory Profile

Site Facility Name: BOWERS CO
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 13222 BROOKHURST
City: GARDEN GROVE
Zip: 92844
County: ORANGE
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605900855
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 3/27/2013
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605900855&tabname=regulatoryhistory

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Potential COC:		GASOLINE				
Potential Media of Concern:		AQUIFER USED FOR DRINKING WATER SUPPLY				
File Location:		LOCAL AGENCY				
User Defined Beneficial Use:						
Designated Beneficial Use:		MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.				
DWR GW Sub Basin:		Coastal Plain Of Orange County (8-001)				
Calwater Watershed Name:		Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)				
Post Closure Site Management:						
Future Land Use:						
Cleanup Oversight Agencies:		ORANGE COUNTY LOP (LEAD) - CASE #: 88UT176 SANTA ANA RWQCB (REGION 8) - CASE #: 083001081T CASE MANAGER: MIGUEL OVIEDO				
CUF Claim No:		2680				
CUF Priority Assig:		C				
CUF Amount Paid:		\$1,302,652				
WDR Place Type:						
WDR File No:						
WDR Order No:						
Project Oversight Agencies:						
Facility Type:						
Composting Method:						
Grndwtr Monitoring Frequency:		# OF WELLS MONITORED - QUARTERLY : 2, SEMI-ANNUALLY : 2				
		REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:				
		Well Being Sampled During Remedial Action for Progress Assessment				
Designated Beneficial Use Desc:		Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.				
Site History:						

Please refer to recent Site Documents or Monitoring Reports in GeoTracker for site history. Orange County is not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants for the responsible party.

CASE CLOSED PURSUANT TO STATE WATER RESOURCES CONTROL BOARD ORDER.

GeoTracker Search - Cleanup Status History

Status:	Completed - Case Closed
Date :	3/27/2013
Status:	Open - Eligible for Closure
Date :	3/26/2013
Status:	Completed - Case Closed
Date :	4/19/2012
Status:	Completed - Case Closed
Date :	4/12/2012
Status:	Open - Remediation
Date :	1/9/2004
Status:	Open - Remediation
Date :	5/5/1997
Status:	Open - Site Assessment
Date :	6/30/1995
Status:	Open - Site Assessment
Date :	6/17/1991
Status:	Open - Site Assessment
Date :	9/23/1988
Status:	Open - Case Begin Date
Date :	9/23/1988

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

GeoTracker Search - Cleanup Action Report

Action Type: PUMP & TREAT (P&T) GROUNDWATER
Begin Date: 1/9/2004
End Date: 9/9/9999
Phase:
Contaminant Mass Removed:
Description:

Action Type: SOIL VAPOR EXTRACTION (SVE)
Begin Date: 1/9/2004
End Date: 9/9/9999
Phase:
Contaminant Mass Removed:
Description:

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)
Action Date: 4/19/2012
Received Issue Date: 4/19/2012
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6389755&temptable=ENFORCEMENT

Title Description Comments:

State Board Well Destruction Letter **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)
Action Date: 4/17/2012
Received Issue Date: 4/17/2012
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6394123&temptable=ENFORCEMENT

Title Description Comments:

State Board NFA Letter **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)
Action Date: 4/12/2012
Received Issue Date: 4/12/2012
Doc Link:

Title Description Comments:

State Board Well Destruction Letter **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)
Action Date: 12/19/2011
Received Issue Date: 12/19/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6393561&temptable=ENFORCEMENT

Title Description Comments:

3rd 5-Year Review **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 9/12/2011
Received Issue Date: 9/12/2011
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6098325&temptable=ENFORCEMENT

Title Description Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

CONFIRMATION BORING WORK PLAN **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 6/13/2011
Received Issue Date: 6/13/2011
Doc Link:
Title Description Comments:

FILE REVIEW **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Site Visit / Inspection / Sampling
Action Date: 5/5/2011
Received Issue Date: 5/5/2011
Doc Link:
Title Description Comments:

SITE VISIT **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Clean Up Fund - Case Closure Review Summary Report (RSR)
Action Date: 6/2/2010
Received Issue Date: 6/2/2010
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6391322&temptable=ENFORCEMENT
Title Description Comments:

Preliminary 5-Year Review **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 7/14/2009
Received Issue Date: 7/14/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6021059&temptable=ENFORCEMENT
Title Description Comments:

QUARTERLY GROUNDWATER MONITORING REQUIREMENTS **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 2/25/2009
Received Issue Date: 2/25/2009
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6004305&temptable=ENFORCEMENT
Title Description Comments:

CAP ADDENDUM **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 9/12/2007
Received Issue Date: 9/12/2007
Doc Link:
Title Description Comments:

2ND QTR 2007 **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Staff Letter
Action Date: 4/14/2006
Received Issue Date: 4/14/2006

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Doc Link:

Title Description Comments:

ISSUED LETTER REQUESTING ALTERNATIVE CAP.

Action Type: Other Regulatory Actions

Action: Staff Letter

Action Date: 9/10/2004

Received Issue Date: 9/10/2004

Doc Link:

Title Description Comments:

ISSUED LETTER REQUESTING THAT THE EDF COPIES OF THE GROUNDWATER MONITORING REPORTS BE SUBMITTED TO GEOTRACKER.

Action Type: Cleanup Action

Action: Soil Vapor Extraction (SVE)

Action Date: 1/9/2004

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type: Cleanup Action

Action: Pump & Treat (P&T) Groundwater

Action Date: 1/9/2004

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type: Other Regulatory Actions

Action: Staff Letter

Action Date: 3/17/2003

Received Issue Date: 3/17/2003

Doc Link:

Title Description Comments:

ISSUED LETTER REQUESTING THAT THE PUMP AND TREAT SYSTEM BE RESTARTED.

Action Type: Leak Action

Action: Leak Reported

Action Date: 1/12/1989

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type: Leak Action

Action: Leak Began

Action Date: 9/23/1988

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type: Leak Action

Action: Leak Discovery

Action Date: 9/23/1988

Received Issue Date:

Doc Link:

Title Description Comments:

Action Type: Enforcement - Other

Action: UNK

Action Date:

Received Issue Date:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Doc Link:		https://geotracker.waterboards.ca.gov/view_documents? global_id=T0605900855&enforcement_id=6119021&temptable=ENFORCEMENT				
Title Description Comments:						
GeoTracker Search - Site Maps						
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR10 (PR10)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9219358086/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR3 (PR3)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9653538525/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_MAP				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/1687026917/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR2 (PR2)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6610791802/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR4 (PR4)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5845047950/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR5 (PR5)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6421826958/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR7 (PR7)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/4681213319/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR6 (PR6)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2437056779/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR8 (PR8)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7857537806/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR9 (PR9)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2433872997/T0605900855.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR1 (PR1)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1806716203/T0605900855.PDF				
Submitted:		9/20/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_MAP				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/4511178433/T0605900855.PDF				
Submitted:		11/14/2007				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_MAP				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_map/4322645425/T0605900855.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW10)				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_bore/1303053140/T0605900855.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW11)				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_bore/3379333972/T0605900855.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (VEW8)				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_bore/5721439957/T0605900855.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW9)				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_bore/5140518009/T0605900855.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW13)				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_bore/1222536981/T0605900855.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW8)				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_bore/2137464761/T0605900855.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW12)				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_bore/1902892172/T0605900855.pdf				
Submitted:		11/10/2005				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_MAP				
Link:		https://geotracker.waterboards.ca.gov/es/uploads/geo_map/2383910953/T0605900855.pdf				

GeoTracker Search - Documents

Document Type:	Site Documents	Document Date:	
Type:	UNKNOWN	Submitted:	
Submitted By:	(REGULATOR)		
Title:	UNKNOWN **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6119021		
Document Type:	Site Documents	Document Date:	4/4/2013*
Type:	WELL DESTRUCTION REPORT	Submitted:	
Submitted By:	JOE FREY (AUTH_RP)		
Title:	WELL ABANDONMENT **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/7183713793/T0605900855.PDF		
Document Type:	Site Documents	Document Date:	4/24/2012*
Type:	REQUEST FOR CLOSURE	Submitted:	
Submitted By:	JOE FREY (AUTH_RP)		
Title:	SITE CONCEPTUAL MODEL AND REQUEST FOR NO FURTHER ACTION **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/1593747735/T0605900855.PDF		
Document Type:	Site Documents	Document Date:	4/19/2012
Type:	CLEAN UP FUND - CASE CLOSURE	Submitted:	
	REVIEW SUMMARY REPORT (RSR)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Submitted By:		JAMES YOUNG (REGULATOR)				
Title:		STATE BOARD WELL DESTRUCTION LETTER **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6389755				
Document Type:		Site Documents		Document Date:		4/17/2012
Type:		CLEAN UP FUND - CASE CLOSURE		Submitted:		
		REVIEW SUMMARY REPORT (RSR)				
Submitted By:		(REGULATOR)				
Title:		STATE BOARD NFA LETTER **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6394123				
Document Type:		Monitoring Reports		Document Date:		1/16/2012
Type:		MONITORING REPORT - QUARTERLY		Submitted:		
Submitted By:		JOE FREY (AUTH_RP)				
Title:		POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9199170708/T0605900855.PDF				
Document Type:		Site Documents		Document Date:		12/30/2011
Type:		OTHER REPORT / DOCUMENT		Submitted:		
Submitted By:		JOE FREY (AUTH_RP)				
Title:		DRILLING AND SAMPLING OF POST-REMEDATION CONFIRMATION SOIL BORINGS **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5878488123/T0605900855.PDF				
Document Type:		Site Documents		Document Date:		12/19/2011
Type:		CLEAN UP FUND - CASE CLOSURE		Submitted:		
		REVIEW SUMMARY REPORT (RSR)				
Submitted By:		(REGULATOR)				
Title:		3RD 5-YEAR REVIEW **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6393561				
Document Type:		Monitoring Reports		Document Date:		9/23/2011
Type:		MONITORING REPORT - QUARTERLY		Submitted:		
Submitted By:		JOE FREY (AUTH_RP)				
Title:		POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8134678661/T0605900855.PDF				
Document Type:		Site Documents		Document Date:		9/12/2011
Type:		STAFF LETTER		Submitted:		
Submitted By:		KEVIN LAMBERT (REGULATOR)				
Title:		CONFIRMATION BORING WORK PLAN **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6098325				
Document Type:		Site Documents		Document Date:		8/24/2011
Type:		SITE INVESTIGATION WORKPLAN		Submitted:		
Submitted By:		JOE FREY (AUTH_RP)				
Title:		WORKPLAN DRILLING AND SAMPLING OF POST REMEDIATION SOIL BORINGS **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3356037914/T0605900855.PDF				
Document Type:		Monitoring Reports		Document Date:		8/4/2011
Type:		MONITORING REPORT - QUARTERLY		Submitted:		
Submitted By:		JOE FREY (AUTH_RP)				
Title:		POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field.				
Title Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1478499650/T0605900855.PDF				
Document Type:		Monitoring Reports		Document Date:		5/25/2011
Type:		MONITORING REPORT - QUARTERLY		Submitted:		
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field.				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Title Link: https://geotracker.waterboards.ca.gov/es/uploads/geo_report/2916584789/T0605900855.PDF						
Document Type:	Monitoring Reports			Document Date:	5/23/2011	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FIRST QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/1010619401/T0605900855.PDF					
Document Type:	Site Documents			Document Date:	3/15/2011	
Type:	OPERATION AND MAINTENANCE PLAN/MONITORING REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/5758813321/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	2/28/2011	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION - FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/8670399487/T0605900855.PDF					
Document Type:	Site Documents			Document Date:	1/18/2011	
Type:	INTERIM REMEDIAL ACTION REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIESTHIRD QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/4541932106/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	12/30/2010	
Type:	MONITORING REPORT - OTHER			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	VAPOR EXTRACTION REBOUND TESTING **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/2338007628/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	12/21/2010	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/1203873634/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	9/21/2010*	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/6677262306/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	7/17/2010	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL REMEDIATION SECOND QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/6837796807/T0605900855.PDF					
Document Type:	Site Documents			Document Date:	6/15/2010	
Type:	OTHER WORKPLAN			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	WORKPLAN - VAPOR EXTRACTION REBOUND TESTING **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/es/uploads/geo_report/3820085823/T0605900855.PDF					
Document Type:	Site Documents			Document Date:	6/2/2010	
Type:	CLEAN UP FUND - CASE CLOSURE			Submitted:		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Submitted By: Title: Title Link:	REVIEW SUMMARY REPORT (RSR) (REGULATOR) PRELIMINARY 5-YEAR REVIEW **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6391322					
	Document Type:	Site Documents		Document Date:	5/25/2010	
	Type:	INTERIM REMEDIAL ACTION REPORT		Submitted:		
	Submitted By: Title: Title Link:	JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3038191854/T0605900855.PDF				
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2381192803/T0605900855.PDF					
	Document Type:	Site Documents		Document Date:	5/14/2010	
	Type:	REMEDIAL PROGRESS REPORT		Submitted:		
	Submitted By: Title: Title Link:	JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES - FOURTH QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2015331447/T0605900855.PDF				
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1418749153/T0605900855.PDF					
	Document Type:	Site Documents		Document Date:	1/11/2010	
	Type:	INTERIM REMEDIAL ACTION REPORT		Submitted:		
	Submitted By: Title: Title Link:	JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3595643401/T0605900855.PDF				
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6111120939/T0605900855.PDF					
	Document Type:	Site Documents		Document Date:	12/21/2009	
	Type:	INTERIM REMEDIAL ACTION REPORT		Submitted:		
	Submitted By: Title: Title Link:	JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3595643401/T0605900855.PDF				
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6111120939/T0605900855.PDF					
	Document Type:	Site Documents		Document Date:	9/24/2009*	
	Type:	WELL INSTALLATION REPORT		Submitted:		
	Submitted By: Title: Title Link:	JOE FREY (AUTH_RP) INSTALLATION OF OFF-SITE REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8064980924/T0605900855.PDF				
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5152642667/T0605900855.PDF					
	Document Type:	Site Documents		Document Date:	8/10/2009	
	Type:	WELL INSTALLATION REPORT		Submitted:		
	Submitted By: Title: Title Link:	JOE FREY (AUTH_RP) INSTALLATION OF OFF-SITE REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8064980924/T0605900855.PDF				
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5152642667/T0605900855.PDF					
	Document Type:	Site Documents		Document Date:	8/6/2009	
	Type:	INTERIM REMEDIAL ACTION REPORT		Submitted:		
	Submitted By: Title: Title Link:	JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGE REMEDIATION ACTIVITIES SECOND QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4843874275/T0605900855.PDF				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STAFF LETTER KEVIN LAMBERT (REGULATOR) QUARTERLY GROUNDWATER MONITORING REQUIREMENTS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6021059			Document Date: Submitted:	7/14/2009	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1911597013/T0605900855.PDF			Document Date: Submitted:	6/24/2009	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7018505275/T0605900855.PDF			Document Date: Submitted:	3/10/2009	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STAFF LETTER KEVIN LAMBERT (REGULATOR) CAP ADDENDUM **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900855&enforcement_id=6004305			Document Date: Submitted:	2/25/2009	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITROING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7993122935/T0605900855.PDF			Document Date: Submitted:	2/17/2009	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN - ADDENDUM JOE FREY (AUTH_RP) ADDENDUM TO CORRECTIVE ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4207190275/T0605900855.PDF			Document Date: Submitted:	1/30/2009	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8020782947/T0605900855.PDF			Document Date: Submitted:	11/20/2008	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8490701138/T0605900855.PDF			Document Date: Submitted:	10/15/2008	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5796858847/T0605900855.PDF			Document Date: Submitted:	10/6/2008	
Document Type: Type: Submitted By:	Site Documents REMEDIAL PROGRESS REPORT JOE FREY (AUTH_RP)			Document Date: Submitted:	8/8/2008	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2008					
Title Link:	**Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5646168589/T0605900855.PDF					
Document Type:	Site Documents			Document Date:	7/14/2008	
Type:	REMEDIAL PROGRESS REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGINH REMEDIATION ACTIVITIES FIRST QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1528533041/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	6/6/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7270689249/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	3/11/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FOURTH QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9787602305/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	2/26/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5867720663/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	1/21/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6551180779/T0605900855.PDF					
Document Type:	Site Documents			Document Date:	11/14/2007	
Type:	REPORTS - INVESTIGATION RPT.			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	INSTALLATION OF ADDITIONAL OFF-SITE REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5161314249/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	11/5/2007	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4303378045/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	8/30/2007	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6438062906/T0605900855.PDF					
Document Type:	Monitoring Reports			Document Date:	7/31/2007	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8310091912/T0605900855.PDF					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 6/6/2007* Submitted:	
Title Link:	THIRD QUARTER 2006, GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2087417423/T0605900855.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 6/1/2007 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2460952579/T0605900855.PDF					
Document Type: Type: Submitted By: Title:	Site Documents REPORTS - INVESTIGATION RPT. JOE FREY (AUTH_RP)				Document Date: 5/23/2007 Submitted:	
Title Link:	INSTALLATION OF ADDITIONAL REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4510099649/T0605900855.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 2/8/2007 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION, FOURTH QUARTER 2006 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7425459146/T0605900855.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 9/11/2006* Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION SECOND QUARTER 2006 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1420821964/T0605900855.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 4/27/2006* Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4189161002/T0605900855.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 1/27/2006 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION FOURTH QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6316663444/T0605900855.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 11/21/2005 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION SECOND QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9805371940/T0605900855.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 11/21/2005 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION FIRST QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2994750797/T0605900855.PDF					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<div><div><div><div><div>Document Type:</div><div>Type:</div><div>Submitted By:</div><div>Title:</div></div><div>Monitoring Reports</div><div>MONITORING REPORT - QUARTERLY</div><div>JOE FREY (AUTH_RP)</div><div>GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION THIRD QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field.</div></div><div><div>Title Link:</div><div>https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6858426749/T0605900855.PDF</div></div></div><div><div>Document Date:</div><div>Submitted:</div><div>11/21/2005</div></div></div>						
27	4 of4	NE	0.21 / 1,110.53	74.00 / 0	Bowers Co 13222 Brookhurst St Garden Grove Ca 92843-1010 CA	LOP ORANGE
<div><div>Case ID:</div><div>88UT176</div></div>						
<div>Details</div> <div><div><div>Current Status:</div><div>Type of Closure:</div><div>Closed Date:</div><div>File Location:</div></div><div>Closed</div><div>Closure certification issued</div><div>4/19/2012</div><div>Local Agency</div></div>						
28	1 of1	WNW	0.21 / 1,133.87	72.58 / -1	ANA FIGUEROA 9651 IMPERIAL AVE. GARDEN GROVE CA 92844	RCRA NON GEN
<div><div><div>Handler ID:</div><div>Generator Status:</div><div>Recycler Activity?:</div><div>Recycler Activity Note:</div></div><div>CAC003077198</div><div>N</div><div>NO</div><div>This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.</div></div>						
<div>Violation/Evaluation Summary</div> <div><div>Note:</div><div>NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).</div></div>						
<div>Handler Summary</div> <div><div><div><div>Importer:</div><div>Mixed Waste Gen:</div><div>Transporter:</div><div>Transfer Facility:</div><div>Recycler:</div><div>Onsite Burner Exem:</div><div>Furnace Exemption:</div><div>Underground Injec:</div><div>Used Oil Market Burner:</div><div>Used Oil Spec Marketer:</div></div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div></div><div><div><div>Used Oil Transpor:</div><div>Used Oil Trans Fac:</div><div>Used Oil Processor:</div><div>Used Oil Refiner:</div><div>Used Oil Burner:</div><div>Commercial TSD:</div><div>Recycl Nonstorage:</div></div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div><div>No</div></div></div>						
<div>Additional Handler Summary Details</div> <div><div><div><div>Source Type:</div><div>Seq No:</div><div>Non Notifier:</div><div>Receive Date:</div><div>Active Site:</div><div>Land Type:</div><div>In Handler Univ:</div><div>In A Universe:</div><div>Gen Status:</div><div>Report Cycle:</div></div><div>I</div><div>1</div><div></div><div>20200730</div><div>-----</div><div></div><div>N</div><div>N</div><div>N</div><div></div></div><div><div><div>NAIC 1:</div><div>NAIC 2:</div><div>NAIC 3:</div><div>NAIC 4:</div><div>State:</div><div>Location Latitude:</div><div>Location Longitude:</div><div>Loc GIS Primary:</div><div>Loc GIS Origin:</div><div>State District Owner:</div></div><div>56299</div><div></div><div></div><div></div><div>CA</div><div></div><div></div><div>N</div><div></div><div></div></div></div>						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Accessibility:			State District:			
Region:	09					
Fed Waste Gen Owner:		HQ				
State Waste Generator Owner:		CA				
State Waste Generator:		2				
Short Term Generator:		N				
Uni Waste:		N				
Universal Waste Dest Facility:		N				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20200814				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		ANA FIGUEROA				
Location Street No:						
Location Street1:		9651 IMPERIAL AVE.				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		ANA FIGUEROA				
Contact Street No:						
Contact Street1:		9651 IMPERIAL AVE.				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92844				
Contact Country:						
Contact Phone And Ext:		714-688-1023				
Contact Fax:						
Contact Email Address:		KARLA@SUPERIORENV.COM				
Contact Title:						
Owner Name:		ANA FIGUEROA				
Owner Type:		O				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Owner Seq:	1
Operator Name:	ANA FIGUEROA
Operator Type:	O
Operator Seq:	2
Public Notes:	

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20200730
Handler Name:	ANA FIGUEROA
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	9651 IMPERIAL AVE.
Name:	ANA FIGUEROA	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-688-1023	Country:	
Source Type:	Implementer	Zip:	92844

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	9651 IMPERIAL AVE.
Name:	ANA FIGUEROA	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-688-1023	Country:	
Source Type:	Implementer	Zip:	92844

29	1 of4	NE	0.22 / 1,140.42	74.17 / 1	MY FAVORITE CLEANERS 13197 BROOKHURST ST GARDEN GROVE CA	DRYCLEANERS
--------------------	-------	----	--------------------	--------------	--	-------------

EPA ID:	CAL000015627	Owner City:	GARDEN GROVE
Create Date:	11/14/1989	Owner State:	CA
Facility Act Ind:	Yes	Owner Zip:	928430000
Inact Date:		Owner Phone:	7145373400
Reason:	SIC/NAICS	Owner Fax:	0
Region Code:	4	Contact Name:	HAN SEONG HEE
DD Latitude:	33.77117	Contact Street 1:	13197 BROOKHURST ST
DD Longitude:	-117.95513	Contact Street 2:	
Facility County Code:	(30) ORANGE	Contact City:	GARDEN GROVE
Mail Name:		Contact State:	CA
Owner Name:	HAN SEONG HEE	Contact Zip:	92843
Owner Street 1:	13197 BROOKHURST ST	Contact Phone:	7145373400
Owner Street 2:		Contact Fax:	0

NAICS Details

NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
SIC Description:	Power Laundries, Family and Commercial

29	2 of4	NE	0.22 / 1,140.42	74.17 / 1	MY FAVORITE CLEANERS, SEONG HE 13197 BROOKHURST ST.	EMISSIONS
--------------------	-------	----	--------------------	--------------	---	-----------

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

GARDEN GROVE CA 92640

1987 Criteria Data

Facility ID:	19731	CERR Code:	
Facility SIC Code:	7216	TOGT:	0
CO:	30	ROGT:	0
Air Basin:	SC	COT:	
District:	SC	NOXT:	
COID:	ORA	SOXT:	
DISN:	SOUTH COAST AQMD	PMT:	
CHAPIS:		PM10T:	

1987 Toxic Data

Facility ID:	19731	COID:	ORA
Facility SIC Code:	7216	DISN:	SOUTH COAST AQMD
CO:	30	CHAPIS:	
Air Basin:	SC	CERR Code:	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1990 Criteria Data

Facility ID:	19731	CERR Code:	
Facility SIC Code:	7216	TOGT:	0
CO:	30	ROGT:	0
Air Basin:	SC	COT:	
District:	SC	NOXT:	
COID:	ORA	SOXT:	
DISN:	SOUTH COAST AQMD	PMT:	
CHAPIS:		PM10T:	

1990 Toxic Data

Facility ID:	19731	COID:	ORA
Facility SIC Code:	7216	DISN:	SOUTH COAST AQMD
CO:	30	CHAPIS:	
Air Basin:	SC	CERR Code:	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

29	3 of4	NE	0.22 / 1,140.42	74.17 / 1	MY FAVORITE CLEANERS 13197 BROOKHURST ST GARDEN GROVE CA 92843-1009	RCRA NON GEN
--------------------	-------	----	--------------------	--------------	---	-----------------

Handler ID:	CAL000015627
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	81232
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	19891114	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.771161
In Handler Univ:	Y	Location Longitude:	-117.955174
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	Y		
Universal Waste Dest Facility:	Y		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	-----		
Full Enforcement:	-----		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	----		
Hhandler Last Change:	20180905		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		MY FAVORITE CLEANERS				
Location Street No:						
Location Street1:		13197 BROOKHURST ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843-1009				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		HAN SEONG HEE				
Contact Street No:						
Contact Street1:		13197 BROOKHURST ST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92843				
Contact Country:						
Contact Phone And Ext:		714-537-3400				
Contact Fax:		000-000-0000				
Contact Email Address:		ROSEBAKH@GMAIL.COM				
Contact Title:						
Owner Name:		HAN SEONG HEE				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		HAN SEONG HEE				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						
Contact DTSC for information.						
<u>Hazardous Waste Handler Details</u>						
Seq No:		1				
Receive Date:		19891114				
Handler Name:		MY FAVORITE CLEANERS				
Fed Waste Generator:		N				
Generator Code Description:		Not a Generator, Verified				
Source Type:		Implementer				
<u>Owner/Operator Details</u>						
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Other				Street1:	13197 BROOKHURST ST
Name:	HAN SEONG HEE				Street2:	
Dt Became Current:					City:	GARDEN GROVE
Dt Ended Current:					State:	CA
Phone:	714-537-3400				Country:	
Source Type:	Implementer				Zip:	92843
Owner/Operator Ind:	Current Owner				Street No:	
Type:	Other				Street1:	13197 BROOKHURST ST
Name:	HAN SEONG HEE				Street2:	
Dt Became Current:					City:	GARDEN GROVE
Dt Ended Current:					State:	CA
Phone:	714-537-3400				Country:	
Source Type:	Implementer				Zip:	92843-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
29	4 of4	NE	0.22 / 1,140.42	74.17 / 1	MY FAVORITE CLEANERS 13197 BROOKHURST ST GARDEN GROVE CA 92843	FED DRYCLEANERS
FRS Facility ID:		110070442968				
NPDES IDs:						
NAICS Codes:		81232				
SIC Codes:						
Latitude:		33.771161				
Longitude:		-117.955174				
30	1 of14	NE	0.23 / 1,217.53	74.91 / 1	PRONTO MARKETING 312 13202 BROOKHURST ST GARDEN GROVE CA 92843	DELISTED TNK
<u>Delisted Storage Tanks</u>						
Facility ID:		4347		County:		Orange
Latitude:		33.772442		Original Source:		UST
Longitude:		-117.9531987		Record Date:		30-JAN-2017
Permitting Agency:		ORANGE COUNTY				
30	2 of14	NE	0.23 / 1,217.53	74.91 / 1	Garden Grove Shell 13202 Brookhurst St Garden Grove, Ca 92843-1010 Garden Grove CA	UST ORANGE
FA No:		FA0057500				
SR No:						
Notes:						
Data Source:		Permitted Underground Storage Tank (UST) Facilities Listing				
30	3 of14	NE	0.23 / 1,217.53	74.91 / 1	JET GAS STATION 13202 BROOKHURST GARDEN GROVE CA 92843	LUST
Global ID:		T0605900794		Case Type (DL):		LUST Cleanup Site
Site Facility Type:		LUST CLEANUP SITE		Oil Field (SRCH):		
Site Fac Type (SRCH):		LUST CLEANUP SITE		Oil Field Oper (SRCH):		
Status:				Census Tract (SRCH):		6059088702
Status (SRCH):		COMPLETED - CASE CLOSED		Latitude (DL):		33.7710063
Status (DL):		Completed - Case Closed		Longitude (DL):		-117.9548864
Status Date (DL):		4/18/2014		RWQCB Region (DL):		SANTA ANA RWQCB (REGION 8)
Cleanup Status:		COMPLETED - CASE CLOSED				
Site Facility Name (SRCH):		JET GAS STATION				
Address (SRCH):		13202 BROOKHURST				
City (SRCH):		GARDEN GROVE				
Zip (SRCH):		92843				
County (SRCH):		ORANGE				
Street No (DL):		13202				
Street Name (DL):		BROOKHURST				
City (DL):		GARDEN GROVE				
Zip (DL):		92843				
County (DL):		Orange				
State (DL):		CA				
Business Name (DL):		JET GAS STATION				
Site Facility Name:		JET GAS STATION				
Address :		13202 BROOKHURST				
City :		GARDEN GROVE				
Zip :		92843				
County :		ORANGE				
Report Source:		LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites &				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search

GeoTracker Sites Data Download - Site Details

CUF Case:
Lead Agency: ORANGE COUNTY LOP
Case Worker:
Local Agency:
RB Case No: 083001004T
Local Case No: 88UT135
File Location: Local Agency
Potential COC: Gasoline
Potential Media of Concern: Other Groundwater (uses other than drinking water)
Begin Date: 7/5/1988
How Discovered: * SA
How Discovered Description:
Stop Method: Close and Remove Tank
Stop Description:
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name: Coastal Plain Of Orange County (8-001)
Disadvantaged Community:
CalEnvScreen Score:
Coordinate Source: * Historical Geocode - Exact Address Match
Discharge Cause:
Discharge Source: Tank
EPA Region: 9
Leak Reported Dt: 1988-07-28 00:00:00
Military DoD Site: No
No Further Action Dt: 2014-04-18 00:00:00
Qty Rlsd Gallons: 0
Facility Project Sub Type:
Calenviroscreen 3 Score: 51-55%
Calenviroscreen 4 Score: 60-65%
A2022 Assembly District: 70
Claim No: 1459
Claim Status: Ineligible
A2022 Congressional District: 45
A2022 Senate District: 36
Site History:

Please refer to recent Site Documents or Monitoring Reports in GeoTracker for site history. Orange County is not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants for the responsible party.

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: MIGUEL OVIEDO
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 Main Street, Suite 500
City: RIVERSIDE
Email: miguel.oviedo@waterboards.ca.gov
Phone No: 9517823238

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 4/18/2014

Status: Open - Eligible for Closure
Status Date: 1/30/2012

Status: Open - Remediation
Status Date: 1/9/2004

Status: Open - Remediation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Status Date:		5/5/1997				
Status:		Open - Site Assessment				
Status Date:		6/11/1991				
Status:		Open - Site Assessment				
Status Date:		5/15/1989				
Status:		Open - Site Assessment				
Status Date:		5/14/1989				
Status:		Open - Case Begin Date				
Status Date:		7/5/1988				

GeoTracker Search - Regulatory Profile

Site Facility Name:	JET GAS STATION
Site Facility Type:	LUST CLEANUP SITE
Cleanup Status:	COMPLETED - CASE CLOSED
Address:	13202 BROOKHURST
City:	GARDEN GROVE
Zip:	92843
County:	ORANGE
Report Link:	https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605900794
Cleanup Status Detail:	COMPLETED - CASE CLOSED AS OF 4/18/2014
Project Status:	
Cleanup History Link:	https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605900794&tabname=regulatoryhistory
Potential COC:	GASOLINE
Potential Media of Concern:	OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)
File Location:	LOCAL AGENCY
User Defined Beneficial Use:	
Designated Beneficial Use:	MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
DWR GW Sub Basin:	Coastal Plain Of Orange County (8-001)
Calwater Watershed Name:	Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
Post Closure Site Management:	
Future Land Use:	
Cleanup Oversight Agencies:	ORANGE COUNTY LOP (LEAD) - CASE #: 88UT135 SANTA ANA RWQCB (REGION 8) - CASE #: 083001004T CASE MANAGER: MIGUEL OVIEDO
CUF Claim No:	1459
CUF Priority Assig:	D
CUF Amount Paid:	\$0
WDR Place Type:	
WDR File No:	
WDR Order No:	
Project Oversight Agencies:	
Facility Type:	
Composting Method:	
Grndwtr Monitoring Frequency:	# OF WELLS MONITORED - QUARTERLY : 5, SEMI-ANNUALLY : 6
Designated Beneficial Use Desc:	REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING: Well Being Sampled During Remedial Action for Progress Assessment Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
Site History:	

Please refer to recent Site Documents or Monitoring Reports in GeoTracker for site history. Orange County is not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants for the responsible party.

GeoTracker Search - Cleanup Status History

Status:	Completed - Case Closed
Date :	4/18/2014
Status:	Open - Eligible for Closure

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
Date :		1/30/2012				
Status:		Open - Remediation				
Date :		1/9/2004				
Status:		Open - Remediation				
Date :		5/5/1997				
Status:		Open - Site Assessment				
Date :		6/11/1991				
Status:		Open - Site Assessment				
Date :		5/15/1989				
Status:		Open - Site Assessment				
Date :		5/14/1989				
Status:		Open - Case Begin Date				
Date :		7/5/1988				

GeoTracker Search - Cleanup Action Report

Action Type: SOIL VAPOR EXTRACTION (SVE)
Begin Date: 1/9/2004
End Date: 9/9/9999
Phase:
Contaminant Mass Removed:
Description:

Action Type: PUMP & TREAT (P&T) GROUNDWATER
Begin Date: 1/9/2004
End Date: 9/9/9999
Phase:
Contaminant Mass Removed:
Description:

Action Type: EXCAVATION
Begin Date: 12/30/1998
End Date: 5/15/2000
Phase:
Contaminant Mass Removed:
Description:

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
Action: Historic Files
Action Date: 5/6/2024
Received Issue Date: 5/6/2024
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6579186&temptable=ENFORCEMENT
Title Description Comments:

Historic Files **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions
Action: Closure/No Further Action Letter
Action Date: 4/18/2014
Received Issue Date: 4/18/2014
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6200367&temptable=ENFORCEMENT
Title Description Comments:

Remedial Action Completion Certification **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Action Type:	Other Regulatory Actions					
Action:	LOP Case Closure Summary to RB					
Action Date:	4/18/2014					
Received Issue Date:	4/18/2014					
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6200365&temptable=ENFORCEMENT					
Title Description Comments:						
CCS **Note: Many records provided by the department have a truncated [Title Description Comments] field.						
Action Type:	Notices					
Action:	Notification - Preclosure					
Action Date:	2/10/2014					
Received Issue Date:	2/10/2014					
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6192055&temptable=ENFORCEMENT					
Title Description Comments:						
WELL ABANDONMENT LETTER **Note: Many records provided by the department have a truncated [Title Description Comments] field.						
Action Type:	Notices					
Action:	Letter - Notice					
Action Date:	12/9/2013					
Received Issue Date:	12/9/2013					
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6185346&temptable=ENFORCEMENT					
Title Description Comments:						
DRAFT CASE CLOSURE SUMMARY TO RESPONSIBLE PARTY AND LANDOWNERS **Note: Many records provided by the department have a truncated [Title Description Comments] field.						
Action Type:	Notices					
Action:	Notification - Public Participation Document					
Action Date:	12/9/2013					
Received Issue Date:	12/9/2013					
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6185343&temptable=ENFORCEMENT					
Title Description Comments:						
DRAFT CASE CLOSURE SUMMARY **Note: Many records provided by the department have a truncated [Title Description Comments] field.						
Action Type:	Notices					
Action:	Notification - Public Notice of Case Closure					
Action Date:	12/9/2013					
Received Issue Date:	12/9/2013					
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6185345&temptable=ENFORCEMENT					
Title Description Comments:						
NOTICE OF OPPORTUNITY FOR PUBLIC COMMENT **Note: Many records provided by the department have a truncated [Title Description Comments] field.						
Action Type:	Other Regulatory Actions					
Action:	File review					
Action Date:	7/9/2013					
Received Issue Date:	7/9/2013					
Doc Link:						
Title Description Comments:						
REVIEW AND RECEIVE GEOTRACKER UPLOADS **Note: Many records provided by the department have a truncated [Title Description Comments] field.						
Action Type:	Other Regulatory Actions					
Action:	File review					
Action Date:	10/18/2012					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Received Issue Date: 10/18/2012

Doc Link:

Title Description Comments:

CASE FILE REVIEW **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Staff Letter

Action Date: 9/12/2011

Received Issue Date: 9/12/2011

Doc Link: [https://geotracker.waterboards.ca.gov/view_documents?](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6098323&temptable=ENFORCEMENT)

[global_id=T0605900794&enforcement_id=6098323&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6098323&temptable=ENFORCEMENT)

Title Description Comments:

CONFIRMATION BORING WORK PLAN **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: File review

Action Date: 6/13/2011

Received Issue Date: 6/13/2011

Doc Link:

Title Description Comments:

FILE REVIEW **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Site Visit / Inspection / Sampling

Action Date: 5/5/2011

Received Issue Date: 5/5/2011

Doc Link:

Title Description Comments:

SITE VISIT **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Staff Letter

Action Date: 7/14/2009

Received Issue Date: 7/14/2009

Doc Link: [https://geotracker.waterboards.ca.gov/view_documents?](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6021058&temptable=ENFORCEMENT)

[global_id=T0605900794&enforcement_id=6021058&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6021058&temptable=ENFORCEMENT)

Title Description Comments:

QUARTERLY GROUNDWATER MONITORING REQUIREMENTS **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Staff Letter

Action Date: 2/25/2009

Received Issue Date: 2/25/2009

Doc Link: [https://geotracker.waterboards.ca.gov/view_documents?](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6004303&temptable=ENFORCEMENT)

[global_id=T0605900794&enforcement_id=6004303&temptable=ENFORCEMENT](https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6004303&temptable=ENFORCEMENT)

Title Description Comments:

CAP ADDENDUM **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Other Regulatory Actions

Action: Staff Letter

Action Date: 9/12/2007

Received Issue Date: 9/12/2007

Doc Link:

Title Description Comments:

2ND QTR 2007 RPT **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Action Type:		Other Regulatory Actions				
Action:		Staff Letter				
Action Date:		4/14/2006				
Received Issue Date:		4/14/2006				
Doc Link:						
Title Description Comments:						
ISSUED LETTER REQUESTING AN ALTERNATIVE CAP.						
Action Type:		Other Regulatory Actions				
Action:		Staff Letter				
Action Date:		9/10/2004				
Received Issue Date:		9/10/2004				
Doc Link:						
Title Description Comments:						
ISSUED LETTER REQUESTING THAT THE EDF COPIES OF GW MONITORING REPORTS BE SUBMITTED TO GEOTRACKER.						
Action Type:		Cleanup Action				
Action:		Soil Vapor Extraction (SVE)				
Action Date:		1/9/2004				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Cleanup Action				
Action:		Pump & Treat (P&T) Groundwater				
Action Date:		1/9/2004				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Other Regulatory Actions				
Action:		Staff Letter				
Action Date:		3/17/2003				
Received Issue Date:		3/17/2003				
Doc Link:						
Title Description Comments:						
ISSUED LETTER REQUESTING THAT THE PUMP AND TREAT SYSTEM BE RESTARTED.						
Action Type:		Cleanup Action				
Action:		Excavation				
Action Date:		12/30/1998				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Leak Action				
Action:		Leak Reported				
Action Date:		7/28/1988				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
Action Type:		Leak Action				
Action:		Leak Discovery				
Action Date:		7/5/1988				
Received Issue Date:						
Doc Link:						
Title Description Comments:						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Action Type:		Leak Action				
Action:		Leak Began				
Action Date:		7/5/1988				
Received Issue Date:						
Doc Link:						
Title Description Comments:						
<u>GeoTracker Search - Site Maps</u>						
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR9 (PR9)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9930556535/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR8 (PR8)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3661682069/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR3 (PR3)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2694028496/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR4 (PR4)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6296656310/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_MAP				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/6348630547/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR5 (PR5)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8197112977/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR6 (PR6)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7363978087/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR1 (PR1)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3723967790/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR2 (PR2)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2305936455/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR10 (PR10)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5194874584/T0605900794.PDF				
Submitted:		1/3/2012				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		PR7 (PR7)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9335484325/T0605900794.PDF				
Submitted:		9/20/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO MAP				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Link:					https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/8517813444/T0605900794.PDF	
Submitted:		8/19/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		V4 (V4)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2884024381/T0605900794.PDF				
Submitted:		8/19/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		A4 (A4)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5379257678/T0605900794.PDF				
Submitted:		8/19/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		A5 (A5)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1228934049/T0605900794.PDF				
Submitted:		8/19/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		V5 (V5)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1032278776/T0605900794.PDF				
Submitted:		8/19/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		A6 (A6)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1544378995/T0605900794.PDF				
Submitted:		8/19/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		A7 (A7)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1556764900/T0605900794.PDF				
Submitted:		8/19/2009				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		A8 (A8)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8751748204/T0605900794.PDF				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW11)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1667195200/T0605900794.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW10)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/2561340153/T0605900794.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW9)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1981692254/T0605900794.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW8)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3428728997/T0605900794.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW12)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8705581486/T0605900794.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (VEW8)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5528335392/T0605900794.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Title:		GEO_MAP				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7719009220/T0605900794.pdf				
Submitted:		11/14/2007				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_BORE (SW13)				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3976576089/T0605900794.pdf				
Submitted:		11/10/2005				
Submitted By:		JOE FREY (AUTH_RP)				
Title:		GEO_MAP				
Link:		https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/2045120060/T0605900794.pdf				

GeoTracker Search - Documents

Document Type:	Site Documents	Document Date:	5/6/2024
Type:	HISTORIC FILES	Submitted:	
Submitted By:	LENA SHAW (REGULATOR)		
Title:	HISTORIC FILES **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6579186		
Document Type:	Site Documents	Document Date:	4/18/2014
Type:	LOP CASE CLOSURE SUMMARY TO RB	Submitted:	
Submitted By:	KEVIN LAMBERT (REGULATOR)		
Title:	CCS **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6200365		
Document Type:	Site Documents	Document Date:	4/18/2014
Type:	CLOSURE/NO FURTHER ACTION LETTER	Submitted:	
Submitted By:	KEVIN LAMBERT (REGULATOR)		
Title:	REMEDIAL ACTION COMPLETION CERTIFICATION **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6200367		
Document Type:	Site Documents	Document Date:	4/8/2014
Type:	WELL DESTRUCTION REPORT	Submitted:	
Submitted By:	JOE FREY (AUTH_RP)		
Title:	WELL ABANDONMENT REPORT **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2744987249/T0605900794.PDF		
Document Type:	Site Documents	Document Date:	2/10/2014
Type:	NOTIFICATION - PRECLOSURE	Submitted:	
Submitted By:	KEVIN LAMBERT (REGULATOR)		
Title:	WELL ABANDONMENT LETTER **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6192055		
Document Type:	Site Documents	Document Date:	12/9/2013
Type:	NOTIFICATION - PUBLIC PARTICIPATION DOCUMENT	Submitted:	
Submitted By:	KEVIN LAMBERT (REGULATOR)		
Title:	DRAFT CASE CLOSURE SUMMARY **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6185343		
Document Type:	Site Documents	Document Date:	12/9/2013
Type:	NOTIFICATION - PUBLIC NOTICE OF CASE CLOSURE	Submitted:	
Submitted By:	KEVIN LAMBERT (REGULATOR)		
Title:	NOTICE OF OPPORTUNITY FOR PUBLIC COMMENT **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6185345		
Document Type:	Site Documents	Document Date:	12/9/2013
Type:	LETTER - NOTICE	Submitted:	
Submitted By:	KEVIN LAMBERT (REGULATOR)		
Title:	DRAFT CASE CLOSURE SUMMARY TO RESPONSIBLE PARTY AND LANDOWNERS **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6185346		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REQUEST FOR CLOSURE JOE FREY (AUTH_RP) SITE CONCEPTUAL MODEL AND REQUEST FOR NO FURTHER ACTION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2903126537/T0605900794.PDF			Document Date: Submitted:	4/24/2012	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FOURTH QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9694350481/T0605900794.PDF			Document Date: Submitted:	1/16/2012	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents OTHER REPORT / DOCUMENT JOE FREY (AUTH_RP) DRILLING AND SAMPLING OF POST-REMEDATION CONFIRMATION SOIL BORINGS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2820067644/T0605900794.PDF			Document Date: Submitted:	12/30/2011	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8449111878/T0605900794.PDF			Document Date: Submitted:	9/23/2011	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STAFF LETTER KEVIN LAMBERT (REGULATOR) CONFIRMATION BORING WORK PLAN **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6098323			Document Date: Submitted:	9/12/2011	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents SITE INVESTIGATION WORKPLAN JOE FREY (AUTH_RP) WORKPLAN DRILLING AND SAMPLING OF POST REMEDIATION SOIL BORINGS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9099140942/T0605900794.PDF			Document Date: Submitted:	8/24/2011	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) POST REMEDIATION GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6877210259/T0605900794.PDF			Document Date: Submitted:	8/4/2011	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8675034880/T0605900794.PDF			Document Date: Submitted:	5/25/2011	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FIRST QUARTER 2011 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4458266496/T0605900794.PDF			Document Date: Submitted:	5/23/2011	
Document Type: Type:	Site Documents OPERATION AND MAINTENANCE			Document Date: Submitted:	3/15/2011	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Submitted By:	PLAN/MONITORING REPORT					
Title:	JOE FREY (AUTH_RP) SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1583932459/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	2/28/2011	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING AND SAMPLING & STATUS OF SOIL AND GROUNDWATER REMEDIATION FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2003537774/T0605900794.PDF					
Document Type:	Site Documents			Document Date:	1/18/2011	
Type:	INTERIM REMEDIAL ACTION REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIESTHIRD QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2195573210/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	12/30/2010	
Type:	MONITORING REPORT - OTHER			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	VAPOR EXTRACTION REBOUND TESTING **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9996576964/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	12/21/2010	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1150224089/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	9/21/2010	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4722245216/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	8/17/2010	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL REMEDIATION SECOND QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3379075407/T0605900794.PDF					
Document Type:	Site Documents			Document Date:	6/15/2010	
Type:	OTHER WORKPLAN			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	WORKPLAN - VAPOR EXTRACTION REBOUND TESTING **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6672250330/T0605900794.PDF					
Document Type:	Site Documents			Document Date:	5/25/2010	
Type:	INTERIM REMEDIAL ACTION REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6720040857/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	5/14/2010	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2010 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1183752775/T0605900794.PDF					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Document Type: Type: Submitted By: Title: Title Link:	Site Documents REMEDIAL PROGRESS REPORT JOE FREY (AUTH_RP)			Document Date: Submitted:	2/18/2010 SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES - FOURTH QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2024758875/T0605900794.PDF	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)			Document Date: Submitted:	1/11/2010 GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7150704920/T0605900794.PDF	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents INTERIM REMEDIAL ACTION REPORT JOE FREY (AUTH_RP)			Document Date: Submitted:	12/21/2009 SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1103082120/T0605900794.PDF	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)			Document Date: Submitted:	9/24/2009 GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2009264290/T0605900794.PDF	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents WELL INSTALLATION REPORT JOE FREY (AUTH_RP)			Document Date: Submitted:	8/10/2009 INSTALLATION OF OFF-SITE REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2724336922/T0605900794.PDF	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents INTERIM REMEDIAL ACTION REPORT JOE FREY (AUTH_RP)			Document Date: Submitted:	8/6/2009 SOIL VAPOR EXTRACTION AND AIR SPARGE REMEDIATION ACTIVITIES SECOND QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8384878873/T0605900794.PDF	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)			Document Date: Submitted:	8/6/2009 GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5341454625/T0605900794.PDF	
Document Type: Type: Submitted By: Title: Title Link:	Site Documents STAFF LETTER KEVIN LAMBERT (REGULATOR)			Document Date: Submitted:	7/14/2009 QUARTERLY GROUNDWATER MONITORING REQUIREMENTS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6021058	
Document Type: Type: Submitted By: Title: Title Link:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)			Document Date: Submitted:	6/24/2009 GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2009 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4882601082/T0605900794.PDF	
Document Type: Type: Submitted By:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)			Document Date: Submitted:	3/10/2009	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2008					
Title Link:	**Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7208893299/T0605900794.PDF					
Document Type:	Site Documents			Document Date:	2/25/2009	
Type:	STAFF LETTER			Submitted:		
Submitted By:	KEVIN LAMBERT (REGULATOR)					
Title:	CAP ADDENDUM **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605900794&enforcement_id=6004303					
Document Type:	Monitoring Reports			Document Date:	2/17/2009	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITROING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8235491096/T0605900794.PDF					
Document Type:	Site Documents			Document Date:	1/30/2009	
Type:	CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN - ADDENDUM			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	ADDENDUM TO CORRECTIVE ACTION PLAN **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2347031116/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	11/20/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4350113391/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	10/15/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3702057361/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	10/6/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4024311900/T0605900794.PDF					
Document Type:	Site Documents			Document Date:	8/8/2008	
Type:	REMEDIAL PROGRESS REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5849060535/T0605900794.PDF					
Document Type:	Site Documents			Document Date:	7/14/2008	
Type:	REMEDIAL PROGRESS REPORT			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	SOIL VAPOR EXTRACTION AND AIR SPARGINH REMEDIATION ACTIVITIES FIRST QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3265980601/T0605900794.PDF					
Document Type:	Monitoring Reports			Document Date:	6/6/2008	
Type:	MONITORING REPORT - QUARTERLY			Submitted:		
Submitted By:	JOE FREY (AUTH_RP)					
Title:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2008 **Note: Many records provided by the department have a truncated [Title] field.					
Title Link:	https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8440321207/T0605900794.PDF					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 3/11/2008 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FOURTH QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5758695304/T0605900794.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 2/26/2008 Submitted:	
Title Link:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES FOURTH QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9118177652/T0605900794.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 1/21/2008 Submitted:	
Title Link:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES THIRD QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4288313150/T0605900794.PDF					
Document Type: Type: Submitted By: Title:	Site Documents REPORTS - INVESTIGATION RPT. JOE FREY (AUTH_RP)				Document Date: 11/14/2007 Submitted:	
Title Link:	INSTALLATION OF ADDITIONAL OFF-SITE REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6273226678/T0605900794.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 11/5/2007 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION THIRD QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8627363443/T0605900794.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 8/30/2007 Submitted:	
Title Link:	SOIL VAPOR EXTRACTION AND AIR SPARGING REMEDIATION ACTIVITIES SECOND QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3155308365/T0605900794.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 7/31/2007 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION SECOND QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4130480706/T0605900794.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 6/6/2007* Submitted:	
Title Link:	THIRD QUARTER 2006, GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1615298211/T0605900794.PDF					
Document Type: Type: Submitted By: Title:	Monitoring Reports MONITORING REPORT - QUARTERLY JOE FREY (AUTH_RP)				Document Date: 6/1/2007 Submitted:	
Title Link:	GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF SOIL AND GROUNDWATER REMEDIATION FIRST QUARTER 2007 **Note: Many records provided by the department have a truncated [Title] field. https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1484052360/T0605900794.PDF					
Document Type: Type:	Site Documents REPORTS - INVESTIGATION RPT.				Document Date: 5/23/2007 Submitted:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<p>Submitted By: JOE FREY (AUTH_RP)</p> <p>Title: INSTALLATION OF ADDITIONAL REMEDIAL WELLS **Note: Many records provided by the department have a truncated [Title] field.</p> <p>Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9171131968/T0605900794.PDF</p>						
<p>Document Type: Monitoring Reports Document Date: 2/8/2007</p> <p>Type: MONITORING REPORT - QUARTERLY Submitted:</p> <p>Submitted By: JOE FREY (AUTH_RP)</p> <p>Title: GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION, FOURTH QUARTER 2006 **Note: Many records provided by the department have a truncated [Title] field.</p> <p>Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3529940545/T0605900794.PDF</p>						
<p>Document Type: Monitoring Reports Document Date: 9/11/2006*</p> <p>Type: MONITORING REPORT - QUARTERLY Submitted:</p> <p>Submitted By: JOE FREY (AUTH_RP)</p> <p>Title: GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION SECOND QUARTER 2006 **Note: Many records provided by the department have a truncated [Title] field.</p> <p>Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3556486368/T0605900794.PDF</p>						
<p>Document Type: Monitoring Reports Document Date: 4/27/2006*</p> <p>Type: MONITORING REPORT - QUARTERLY Submitted:</p> <p>Submitted By: JOE FREY (AUTH_RP)</p> <p>Title: GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION **Note: Many records provided by the department have a truncated [Title] field.</p> <p>Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4028838932/T0605900794.PDF</p>						
<p>Document Type: Monitoring Reports Document Date: 1/27/2006</p> <p>Type: MONITORING REPORT - QUARTERLY Submitted:</p> <p>Submitted By: JOE FREY (AUTH_RP)</p> <p>Title: GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION FOURTH QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field.</p> <p>Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2053104996/T0605900794.PDF</p>						
<p>Document Type: Monitoring Reports Document Date: 11/21/2005</p> <p>Type: MONITORING REPORT - QUARTERLY Submitted:</p> <p>Submitted By: JOE FREY (AUTH_RP)</p> <p>Title: GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION THIRD QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field.</p> <p>Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2878492593/T0605900794.PDF</p>						
<p>Document Type: Monitoring Reports Document Date: 11/21/2005</p> <p>Type: MONITORING REPORT - QUARTERLY Submitted:</p> <p>Submitted By: JOE FREY (AUTH_RP)</p> <p>Title: GROUNDWATER MONITORING WELL MONITORING AND SAMPLING AND STATUS OF GROUNDWATER REMEDIATION SECOND QUARTER 2005 **Note: Many records provided by the department have a truncated [Title] field.</p> <p>Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1854566276/T0605900794.PDF</p>						
30	4 of 14	NE	0.23 / 1,217.53	74.91 / 1	JET 13202 BROOKHURST GARDEN GROVE CA 92643	HHSS
<p>County:</p> <p>Tank Details Microfiche: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002ea71.pdf</p>						
30	5 of 14	NE	0.23 / 1,217.53	74.91 / 1	GARDEN GROVE SHELL 13202 Brookhurst St Garden Grove CA 92843	UST
<p>Facility ID: FA0057500 CERS ID: 10571791</p> <p>Site Facility Type: PERMITTED UNDERGROUND STORAGE TANK (UST)</p> <p>Note: Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca.gov/search</p>						

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Permitted UST Tank Details

Epa Region:	9				Tank Closure Date:	
No. of Closed UST:	0				Tank Configuration:	One in a Compartmented Unit
No. of Inuse UST:					Tank Contents:	Premium Unleaded
No. of Oos UST:	0				Tank Cp Impr Curr:	No
Owner Type:	Non-Government				Tank Cp Shutoff:	Yes
Tank ID No.:	3				Tank Installatn Dt:	10/1/1999 12:00:00 AM
Tank Status:	Confirmed/Updated Information				Tank No of Compart:	2
Tank Type:	Double Wall				Tank Pc Constructn:	Steel
Tank Alarms:	No				Tank Spill Bucket:	Yes
Tank Ball Float:	No				Tribal Lands:	No
Tank Operator Name:	KORMEX MANAGEMENT, INC					
Tank Operator Mail Address:	13202 BROOKHURST ST					
Tank Operator Mail City:	FULLERTON					
Tank Operator Mail State:	CA					
Tank Operator Mail Zip:	92843					
Tank Owner Name:	KORMEX MANAGEMENT, INC					
Tank Owner Mailing Address:	13202 BROOKHURST ST					
Tank Owner Mailing City:	FULLERTON					
Tank Owner Mailing State:	CA					
Tank Owner Mailing Zip:	92843					
Tank Capacity Gallons:	6000					
Tank Piping Construction:	Double Walled					
Tank Piping Type:	Pressure					
Tank Pw Piping Construction:	Fiberglass					
Tank Sacrificial Anode:	No					

Permitted UST Tank Details

Epa Region:	9				Tank Closure Date:	
No. of Closed UST:	0				Tank Configuration:	Stand Alone Tank
No. of Inuse UST:					Tank Contents:	Regular Unleaded
No. of Oos UST:	0				Tank Cp Impr Curr:	No
Owner Type:	Non-Government				Tank Cp Shutoff:	Yes
Tank ID No.:	1				Tank Installatn Dt:	10/1/1999 12:00:00 AM
Tank Status:	Confirmed/Updated Information				Tank No of Compart:	1
Tank Type:	Double Wall				Tank Pc Constructn:	Steel
Tank Alarms:	No				Tank Spill Bucket:	Yes
Tank Ball Float:	No				Tribal Lands:	No
Tank Operator Name:	KORMEX MANAGEMENT, INC					
Tank Operator Mail Address:	13202 BROOKHURST ST					
Tank Operator Mail City:	FULLERTON					
Tank Operator Mail State:	CA					
Tank Operator Mail Zip:	92843					
Tank Owner Name:	KORMEX MANAGEMENT, INC					
Tank Owner Mailing Address:	13202 BROOKHURST ST					
Tank Owner Mailing City:	FULLERTON					
Tank Owner Mailing State:	CA					
Tank Owner Mailing Zip:	92843					
Tank Capacity Gallons:	12000					
Tank Piping Construction:	Double Walled					
Tank Piping Type:	Pressure					
Tank Pw Piping Construction:	Fiberglass					
Tank Sacrificial Anode:	No					

Permitted UST Tank Details

Epa Region:	9				Tank Closure Date:	
No. of Closed UST:	0				Tank Configuration:	One in a Compartmented Unit
No. of Inuse UST:					Tank Contents:	Diesel
No. of Oos UST:	0				Tank Cp Impr Curr:	No
Owner Type:	Non-Government				Tank Cp Shutoff:	Yes
Tank ID No.:	2				Tank Installatn Dt:	10/1/1999 12:00:00 AM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tank Status:	Confirmed/Updated Information			Tank No of Compart:	2	
Tank Type:	Double Wall			Tank Pc Constructn:	Steel	
Tank Alarms:	No			Tank Spill Bucket:	Yes	
Tank Ball Float:	No			Tribal Lands:	No	
Tank Operator Name:	KORMEX MANAGEMENT, INC					
Tank Operator Mail Address:	13202 BROOKHURST ST					
Tank Operator Mail City:	FULLERTON					
Tank Operator Mail State:	CA					
Tank Operator Mail Zip:	92843					
Tank Owner Name:	KORMEX MANAGEMENT, INC					
Tank Owner Mailing Address:	13202 BROOKHURST ST					
Tank Owner Mailing City:	FULLERTON					
Tank Owner Mailing State:	CA					
Tank Owner Mailing Zip:	92843					
Tank Capacity Gallons:	6000					
Tank Piping Construction:	Double Walled					
Tank Piping Type:	Pressure					
Tank Pw Piping Construction:	Fiberglass					
Tank Sacrificial Anode:	No					

Permitted UST Site Details

CERS ID:	10571791	CalEnviroScrn 4 Pct:	60-65%
Facility ID:	FA0057500	Latitude:	33.77107
Permitting Agency:	Orange County Environmental Health	Longitude:	-117.95463
Senate District:	36	County:	Orange
Congress District:	45		

<u>30</u>	6 of 14	NE	0.23 / 1,217.53	74.91 / 1	Jet Gas Station 13202 Brookhurst St Garden Grove Ca 92843-1010 CA	LOP ORANGE
---------------------------	---------	----	--------------------	--------------	--	------------

Case ID: 88UT135

Details

Current Status:	Closed
Type of Closure:	Closure certification issued
Closed Date:	4/18/2014
File Location:	Local Agency

<u>30</u>	7 of 14	NE	0.23 / 1,217.53	74.91 / 1	GARDEN GROVE SHELL 13202 BROOKHURST ST GARDEN GROVE CA 92843	CERS TANK
---------------------------	---------	----	--------------------	--------------	--	-----------

Site ID: 366507
Latitude: 33.771080
Longitude: -117.954628

Regulated Programs

EI ID:	10571791
EI Description:	Underground Storage Tank

Violations

Violation Date:	01/03/2020	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)		
Violation Notes:			

Returned to compliance on 03/24/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

originally cited on 6/27/2019. Make necessary repairs and submit passing test results to this Agency.

Violation Description:

Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.

Violations

Violation Date: 06/15/2018
Violation Program: UST
Citation: HSC 6.7 Multiple - California Health and Safety Code, Chapter 6.7, Section(s) Multiple
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Designated Operator training records are required annually the record on file were dated 3-10-17

Violation Description:

UST Program -General - Must include violation description, proper statute and regulation citation in the "comment" section.

Violations

Violation Date: 01/03/2020
Violation Program: UST
Citation: 23 CCR 16 2715(c)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)(2)
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Returned to compliance on 01/27/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was originally cited on 6/27/2019. Have the Designated Operator conduct training with employees annually. Provide a copy of the most recent training records to this Agency.

Violation Description:

Failure to have at least one facility employee present during operating hours that has been trained in the proper operation and maintenance of the UST system by a designated operator (DO).

Violations

Violation Date: 06/27/2019
Violation Program: UST
Citation: 23 CCR 16 2716(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(f)
Violation Notes:

Violation Source: CERS
Violation Division: Orange County Environmental Health

Returned to compliance on 01/03/2020. OBSERVATION: December 2018 Designated Operator inspection report is not available for review. CORRECTIVE ACTION: Submit a copy of the December 2018 inspection report to this Agency and maintain on site within 30 days.

Violation Description:

"Failure to maintain on-site, or off-site at a readily available location if approved by the UPA, copies of Designated Operator inspection records as follows:

Designated operator monthly inspection records for inspections performed before October 1, 2018 must be kept for 12 months from the month of inspection.

For inspections performed on or after October 1, 2018, copies of the ""Designated Underground Storage Tank Operator Visual Inspection Report"" must be kept for 36 months from the month of inspection.

Violations

Violation Date: 06/15/2016
Violation Source: CERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2715(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(i)		
Violation Notes:			

Returned to compliance on 06/15/2016. The Monitor certification testing was due by 6-10-16 but was completed 5 days late. Violation has been abated

Violation Description:

Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.).

Violations

Violation Date:	06/27/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.7 25292.2(a) - California Health and Safety Code, Chapter 6.7, Section(s) 25292.2(a)		
Violation Notes:			

Returned to compliance on 12/28/2019. OBSERVATION: Certificate of Financial Responsibility last signed on 3/16/17 and is expired (valid for 1 year from signed date.) CORRECTIVE ACTION: Submit a current CFR to CERS within 30 days.

Violation Description:

Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.

Violations

Violation Date:	06/27/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)		
Violation Notes:			

Returned to compliance on 01/03/2020. OBSERVATION: Monitoring Plan submitted to CERS requires corrections. CORRECTIVE ACTION: Review regulator comments on CERS, make corrections and resubmit within 30 days.

Violation Description:

Failure to have an approved UST Monitoring Plan.

Violations

Violation Date:	06/10/2020	Violation Source:	CERS
Violation Program:	HW	Violation Division:	Orange County Environmental Health
Citation:	22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)		
Violation Notes:			

Returned to compliance on 06/10/2020. One 55 gallon drum of Fuel/Water Mixture located in the dumpster area was observed 1/4 full without a hazardous waste label. The 55 gallon waste drum was labeled during the inspection. No further action required.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date:	06/27/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2712(b)(1)(F) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(F)		
Violation Notes:			

Returned to compliance on 01/03/2020. OBSERVATION: Secondary containment test results dated 7/9/18 is not available on site for review.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

CORRECTIVE ACTION: Maintain 7/9/18 secondary containment test results on site within 30 days and notify this Agency when this has been done.

Violation Description:

"Failure to conduct secondary containment testing, or one or more of the following requirements:

Perform the test of the secondary containment system upon installation, within six months of installation and every 36 months thereafter.

Perform the test of a secondary containment component within 30 days of a repair or discontinuing vacuum, pressure or hydrostatic monitoring.

Use a procedure that demonstrates the system works as well as at installation.

Use applicable manufacturer guidelines, industry codes, engineering standard, or professional engineer approval.

Performed by a certified service technician.

Maintain records of secondary containment testing for 36 months."

Violations

Violation Date: 01/03/2020
Violation Program: UST
Citation: 23 CCR 16 2641(h) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(h)
Violation Notes:

Returned to compliance on 01/27/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was originally cited on 6/27/2019. Review regulator comments in CERS and make corrections immediately.

Violation Description:

Failure to have an approved UST Monitoring Plan.

Violations

Violation Date: 06/15/2016
Violation Program: UST
Citation: 23 CCR 16 2631(g), 2632(c)(2)(A) & (B) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2631(g), 2632(c)(2)(A) & (B)
Violation Notes:

Returned to compliance on 07/02/2016. The veederroot alarm lite is stuck on even though monitor certification testing indicated all leak detection components are operational. Per consultant a cold start is required to fix this. This must be corrected within 30 days and documentation submitted to this agency

Violation Description:

Failure of the double-walled interstitial space of the tank to be continuously monitored with an audible and visual alarm.

Violations

Violation Date: 06/10/2020
Violation Program: HMRRP
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 08/30/2020. The Emergency Response Plan submitted to CERS is not complete. Please make the following corrections: - In Section A., please also select "Hazardous Waste". - In Section C., please include the Local Unified Program Agency phone number: (714) 433-6406. Re-submit a corrected Emergency Response Plan to this Agency via CERS at <http://cers.calepa.ca.gov/> within 30 days and maintain an updated copy of the plan on site.

Violation Description:

Failure to establish and electronically submit an adequate emergency response plan and procedures for a release or threatened release of a hazardous material.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violations

Violation Date: 01/03/2020
Violation Program: UST
Citation: 23 CCR 16 2712(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(i)
Violation Notes:

Returned to compliance on 01/27/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was originally cited on 6/27/2019. A copy of the Permit to Operate has been provided with this report. Please notify this Agency once the Permit has been received and a copy has been printed to keep on site.

Violation Description:

Failure to retain a copy of the permit to operate at the facility.

Violations

Violation Date: 06/27/2019
Violation Program: UST
Citation: 23 CCR 16 2716(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(e)
Violation Notes:

Returned to compliance on 01/27/2020. OBSERVATION: There is more than a 30 day gap between the 3/14/19 and 4/22/19 Designated Operator inspection. Inspections must be done within 30 days. Moving forward, ensure every inspection is completed within 30 days. DO inspection report from July 2018 does not have a secondary containment test date indicated and inspection reports from August 2018 through June 2019 indicate a secondary containment test date of 6/16/17 which is incorrect. CORRECTIVE ACTION: Submit a copy of the July 2019 inspection (once completed) with correct secondary containment test date to this Agency within 30 days

Violation Description:

For designated operator (DO) monthly inspections conducted before October 1, 2018, failure to comply with one or more of the following requirements: Be performed by an ICC certified DO.
Inspect monthly alarm history report, check that alarms are documented and responded to appropriately, and attach a copy.
Inspect for the presence of liquid/debris in spill containers.
Inspect for the presence of liquid/debris in under dispenser containment (UDC) and ensure that the monitoring equipment is positioned correctly.
Inspect for liquid or debris in containment sumps where an alarm occurred with no service visit.
Check that all testing and maintenance has been completed and documented.
Verify that all facility employees have been trained in accordance with 23 CCR 2715(c).
For designated operator (DO) 30 day inspections conducted on and after October 1, 2018, failure to conduct the designated UST operator visual inspection at least once every 30 days.

Violations

Violation Date: 06/27/2019
Violation Program: UST
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Notes:

Returned to compliance on 01/03/2020. OBSERVATION: 91 and Diesel line leak detectors failed testing. CORRECTIVE ACTION: Make any necessary repairs/replacements, conduct retest and submit passing results to this Agency within 30 days.

Violation Description:

Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.

Violations

Violation Date: 01/03/2020
Violation Program: UST
Citation: 23 CCR 16 2716(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2716(f)
Violation Notes:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Returned to compliance on 01/27/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was previously cited as I127 on 6/15/2018. Submit a copy of the December 2018 Designated Operator inspection report to this Agency and maintain on site.

Violation Description:

"Failure to maintain on-site, or off-site at a readily available location if approved by the UPA, copies of Designated Operator inspection records as follows:

Designated operator monthly inspection records for inspections performed before October 1, 2018 must be kept for 12 months from the month of inspection.

For inspections performed on or after October 1, 2018, copies of the ""Designated Underground Storage Tank Operator Visual Inspection Report"" must be kept for 36 months from the month of inspection.

"

Violations

Violation Date: 01/03/2020
Violation Program: UST
Citation: HSC 6.7 25284, 25286 - California Health and Safety Code, Chapter 6.7, Section(s) 25284, 25286
Violation Notes:

Returned to compliance on 01/27/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was originally cited on 6/27/2019. Review regulator comments in CERS and make corrections immediately.

Violation Description:

Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.

Violations

Violation Date: 06/15/2018
Violation Program: UST
Citation: HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34
Violation Notes:

The certification of financial responsibility must be submitted annually on CERS the CFR is dated 3-16-17 an updated form must be submitted

Violation Description:

Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.

Violations

Violation Date: 06/16/2017
Violation Program: UST
Citation: 23 CCR 16 2715(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(i)
Violation Notes:

Returned to compliance on 06/16/2017. The monitor certification testing was due by 6-15-17 but was completed on 6-16-17. Violation has been abated

Violation Description:

Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.).

Violations

Violation Date: 04/08/2019
Violation Program: UST
Citation: HSC 6.7 25284, 25286 - California Health and Safety Code, Chapter 6.7, Section(s) 25284, 25286

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violation Notes:

Returned to compliance on 06/27/2019. OBSERVATION: The Permit to Operate application on the California Environmental Reporting System (CERS) requires corrections. CORRECTIVE ACTION: Please refer to regulator comments on CERS and make appropriate changes to the application within 30 days.

Violation Description:

Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.

Violations

Violation Date:	06/27/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.7 25284, 25286 - California Health and Safety Code, Chapter 6.7, Section(s) 25284, 25286		
Violation Notes:			

Returned to compliance on 01/03/2020. OBSERVATION: Tank pages submitted to CERS requires corrections. CORRECTIVE ACTION: Please review regulator comments on CERS, make necessary corrections and resubmit within 30 days.

Violation Description:

Failure to submit a complete and accurate application for a permit to operate a UST, or for renewal of the permit.

Violations

Violation Date:	06/27/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2712(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(i)		
Violation Notes:			

Returned to compliance on 01/03/2020. OBSERVATION: Unable to locate current monitoring plan on site. CORRECTIVE ACTION: Monitoring Plan must be kept and maintained on site. Obtain monitoring plan from CERS and maintain on site within 30 days.

Violation Description:

Failure to have current UST Monitoring Plan available on site.

Violations

Violation Date:	06/10/2020	Violation Source:	CERS
Violation Program:	HMRRP	Violation Division:	Orange County Environmental Health
Citation:	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)		
Violation Notes:			

Returned to compliance on 08/30/2020. The Facility Information section submitted is inaccurate. Please make the following corrections: - Under Business Activities, the previous owner's EPA ID # is listed. Please update the EPA ID # to the current owner's ID #: CAL000453941. - Under Owner/Operator Identification - Update the owner name to reflect the business name: Kormex Management, Inc. Re-submit corrections to this Agency via CERS at <http://cers.calepa.ca.gov/> within 30 days.

Violation Description:

Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Violations

Violation Date:	06/10/2020	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)		
Violation Notes:			

Returned to compliance on 06/10/2020. The 91 LLD failed testing. The LLD was repaired, re-tested, and passed. Violation corrected on site.

Violation Description:

Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.

Violations

Violation Date:	01/03/2020	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2711(a)(8) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2711(a)(8)		
Violation Notes:			

Returned to compliance on 01/27/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was originally cited on 6/27/2019. Review regulator comments in CERS and make corrections immediately.

Violation Description:

Failure to submit or maintain a current facility plot plan.

Violations

Violation Date:	06/16/2014	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2715 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715		
Violation Notes:			

Returned to compliance on 07/28/2014. Copies of annual UST training records were not available for review. send this agency copies of the most recent training records

Violation Description:

The owner/operator has failed to comply with one or more of the following: to maintain a copy of the designated operator monthly inspections for the last 12 months

and/or

maintain a list of trained employees on-site or off-site at a readily available location, if approved by the CUPA.

Violations

Violation Date:	06/27/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2711(a)(8) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2711(a)(8)		
Violation Notes:			

Returned to compliance on 01/03/2020. OBSERVATION: Plot Plan submitted to CERS requires corrections. CORRECTIVE ACTION: Review regulator comments on CERS, make corrections and resubmit within 30 days.

Violation Description:

Failure to submit or maintain a current facility plot plan.

Violations

Violation Date:	06/27/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2636(f)(1) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(1)		
Violation Notes:			

Returned to compliance on 06/27/2019. OBSERVATION: Diesel STP sump sensor did not shut down the diesel product when sensor was tested in

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

water. CORRECTIVE ACTION: Issue traced to output relay wire. Contractor corrected issue on site. No further action required.

Violation Description:

Failure of the double-walled pressurized piping to be continuously monitored with a system that activates an audible and visual alarm or stops flow at the dispenser when a leak is detected.

Violations

Violation Date: 06/15/2018
Violation Program: UST
Citation: 23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)
Violation Notes:

The diesel sump sensors did not shut down the turbines when a leak was detected and must be repaired

Violation Description:

Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.

Violations

Violation Date: 01/03/2020
Violation Program: UST
Citation: 23 CCR 16 2712(b)(1)(F) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(b)(1)(F)
Violation Notes:

Returned to compliance on 01/27/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was originally cited on 6/27/2019. Obtain a copy of the secondary containment test results dated 7/9/2018 and print a copy to keep on site. Notify this Agency once complete.

Violation Description:

"Failure to conduct secondary containment testing, or one or more of the following requirements:

Perform the test of the secondary containment system upon installation, within six months of installation and every 36 months thereafter.

Perform the test of a secondary containment component within 30 days of a repair or discontinuing vacuum, pressure or hydrostatic monitoring.

Use a procedure that demonstrates the system works as well as at installation.

Use applicable manufacturer guidelines, industry codes, engineering standard, or professional engineer approval.

Performed by a certified service technician.

Maintain records of secondary containment testing for 36 months."

Violations

Violation Date: 06/20/2018
Violation Program: HMRRP
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 06/27/2019
Violation Program: UST
Citation: 23 CCR 16 2715(c)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)(2)
Violation Notes:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violation Notes:

Returned to compliance on 01/03/2020. OBSERVATION: Most recent training records available on site indicate training was last conducted on 3/10/17. Training must be conducted annually for facility employees. CORRECTIVE ACTION: Have Designated Operator conduct training for employees and submit most current training records as demonstration of completing training to this Agency within 30 days.

Violation Description:

Failure to have at least one facility employee present during operating hours that has been trained in the proper operation and maintenance of the UST system by a designated operator (DO).

Violations

Violation Date:	01/03/2020	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2712(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(i)		
Violation Notes:			

Returned to compliance on 01/27/2020. This violation is being elevated to a Class II Violation which is a more serious violation. The violation was originally cited on 6/27/2019. Print the current monitoring plan from CERS and maintain on site. Notify this Agency once complete.

Violation Description:

Failure to have current UST Monitoring Plan available on site.

Violations

Violation Date:	06/27/2019	Violation Source:	CERS
Violation Program:	UST	Violation Division:	Orange County Environmental Health
Citation:	23 CCR 16 2712(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2712(i)		
Violation Notes:			

Returned to compliance on 01/03/2020. OBSERVATION: Permit to Operate located on site expired on 6/30/17. CORRECTIVE ACTION: Current permit must be maintained on site at all times. Request current permit from this Agency for the 2017-2019 period and maintain on site within 30 days.

Violation Description:

Failure to retain a copy of the permit to operate at the facility.

Evaluations

Eval Date:	03/08/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Eval Date:	07/25/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Mark Sutphin at site for a follow up inspection. Permission to enter inspect and take photographs granted by Reda Sad. I verified that the Veederroot panel was operating properly and the red warning light was no longer stuck on. Violation I95 has been abated. Facility has submitted UST documents on CERS 10571791. Facility can be permitted. .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Date: 06/15/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by the manager Akram Ahmed Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Emergency Response Information was available for review. Facility did not have any hazardous waste stored at site. Per Akram any hazardous waste generated it self hauled to associated facility in 5 gallon gas cans. i informed Akram that he needs larger containers in case of a large spill; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/02/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Reviewed file and confirmed that the monitor cert is due by 6-15-17. I called station and ahmed Saad and informed him that testing must be done by 6-15-15; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/17/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

The following documentation submitted to CERS on 1/27/2020 has been reviewed and ACCEPTED: - Business Activities - Business Owner/Operator Identification - Hazardous Materials Inventory - Site Map - Emergency Contingency Plan/Training Records Violation I292 has been corrected. REMINDER: Please re-certify your HMBEP annually in the California Environmental Reporting System (CERS) between January 1st – March 1st at <http://cers.calepa.ca.gov/>; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/02/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Per additional review the tank installation date for all three tanks is not noted on the tank information pages if the date is not known use 1-1-1900 as the default dat. The over fill information for the tank # 2 and 3 is not given . For tank #1 it is given . The tank overfill info must be given for all three tanks; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/15/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by Mohamed Shazly Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

were noted. The facility has not completed an HMBP plan The Facility does not currently have a hazardous waste storage drum at site but per Mohamad Shazly they are getting one. Each container and portable tank must be labeled with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. The Accumulation start date For further information about Hazardous Waste management, please refer to the Orange County Hazardous Waste website at www.occupainfo.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/16/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by Patricia Abalos Facility EPA ID # CAL000453941 Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. The facility has completed an HMBP plan Hazardous waste containers must be labeled and stored closed. Each container and portable tank was marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. The Accumulation start date For further information about Hazardous Waste management, please refer to the Orange County Hazardous Waste website at www.occupainfo.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/12/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

SB989 Notification (7/16/18).; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/25/2022
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This Agency has received a copy of the following test results dated 6/1/2022: - Monitoring System Certification - Spill Buckets - Line Leak Detectors All components were tested and PASSED.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/22/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERS submittal 10571791 reviewed and accepted by M Sutphin Emergency plan and training included in submittal Only gasoline in fuel tanks was listed in inventory.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/10/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Eval Notes:

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted Mina Labib Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. The facility has not completed an HMBP plan Hazardous waste containers must be labeled and stored closed. Each container and portable tank was marked with the following information: 1. "HAZARDOUS WASTE" 2. Waste (name) 3. Hazardous property of the waste (e.g. - toxic, flammable, corrosive, etc.) 4. Physical state of the waste (liquid or solid) 5. Name and address of the business 6. The Accumulation start date For further information about Hazardous Waste management, please refer to the Orange County Hazardous Waste website at www.occupainfo.com; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/08/2021
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Received a copy of the passing monitor certification test results for testing performed 6-16-21 and witnessed by M Sutphin; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 10/26/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No submittal in CERS or eSubmit, preparing for inspection; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/05/2013
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This is an in-office inspection report to document the submittal of a leeter from the owner Mr. Walid Shafik stating that the previous owner generated this waste from the 2009 SB989 testing. He stated the testing company "Shancor" picked up the drum and removed it from the site. Violation W009 is abated today.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/21/2021
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

CERS submittal reviewed and accepted. Information confirmed accurate during 6-16-21 on site inspection; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/10/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval Notes:

Onsite to conduct routine UST inspection and hazardous waste inspection. Consent to enter, inspect the facility and take photographs was granted by the cashier Mina Labib. The Veeder-Root TLS-350 monitoring panel displayed "all functions normal" and audible and visual alarms were demonstrated operational. The panel was noted marked with a sticker from the most recent monitoring certification (6-11-14). Dave Simon was at site to perform the annual monitor certification testing this date and the system passed. Certifications were up to date Opened UDCs were inspected this date and the UDCs were dry and Chain floats appear ok The following documents were available for review on this date: - Permit - Monitoring plan (5/14/11) - Monitoring plot plan - Response plan (5/14/11) - Designated operator monthly reports - Maintenance and spill log (see violation) - Employee training conducted by DO within the last year 7-5-14 - Financial responsibility and CFO [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/13/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Monitor cert notification for 6-16; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/16/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

On site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by the cashier Joey Manlangit and he provided consent to inspect the facility. Facility has active EPA ID# CAL000364039. No record for disposal of any waste was observed in the compliance binder. No disposal records are noted on the DTSC we site. No hazardous waste was observed at site Keep copies of manifests ate site for review for three years. Municipal dumpster area does not appear to contain any hazardous waste. The perimeter of the facility was also inspected; no obvious signs of releases were noted. Emergency Response Information was available for review. Discussed proper management of Universal Wastes; Fluorescent tubes, e-waste, and batteries must be disposed properly, not to the municipal trash. For further information about Hazardous Waste management, please refer to the Orange County Hazardous Waste website at www.occupainfo.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/09/2014
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Monitor cert notification; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/13/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Mark Sutphin inspected site and spoke with manager Akram. I informed him that the monitor certification is due by 6-16-18 but was not scheduled yet. i inspected the Veederoot panel and verified that the certification sticker was dated 6-16-17. i inspected compliance note book and verified that SB 989 testing was due by 7-7-18. I requested that Akram notify the manager to schedule testing and notify this agency.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/15/2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Onsite to conduct routine UST inspection and hazardous waste inspection. Consent to enter, inspect the facility and take photographs was granted by the cashier Mohamad Shazly. The Veeder-Root TLS-350 monitoring panel displayed "all functions normal" but the red alarm lite was flashing. The panel was noted marked with a sticker from the most recent monitoring certification (6-10-15). Ricardo Martinez was at site to perform the annual monitor certification testing this date and the system passed. Certifications were up to date The facility has three double walled modern welding tanks. The fill sumps and turbine sumps were dry and the VR 208 sensors were properly [positioned at the low points. The 5 UDCs were inspected this date and the UDCs were dry and Chain floats appear oThe tank annuli sensors are VR 420 sensors All sensors were tested and passed The spill buckets were water tested and passed Fail safe, sensor out, and ESO passed this date The three VMI [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/04/2015
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Monitor cert notification; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	07/31/2017
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Received passing test results for Monitor certification testing performed 6-16-17. Testing was witnessed by M Sutphin; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/10/2020
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HW
Eval Source:	CERS
Eval Notes:	

On site for a routine hazardous waste inspection. Consent to inspect and take any necessary photos was given by Patricia Avalos, Cashier. Ownership changed from BR Petroleum, Inc. to Kormex Management, Inc. on 3/14/2020. Walked throughout the facility. Observed hazardous waste storage areas. Containers were properly closed. Employees are reported to be trained. Emergency plan is posted at front counter. No hazardous waste or universal waste observed in the dumpster/enclosure area.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	02/18/2022
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

CERS submitta UST information reviewed and accepted.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Eval Date:		06/17/2014				
Violations Found:		No				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		UST				
Eval Source:		CERS				
Eval Notes:						

At site to witness the open sump inspection. permission to enter, inspect and take photographs granted by Walid Shafik the sumps were open for the three tanks at site and the sumps were verified dry, and the veederroot 208 sensors were verified at the low points. I also received and updated Certification of Financial Responsibility form at site this date; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/25/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

M Sutphin at site for hazardous materials inspection Facility has submitted HMBP on CERS 10571791 Facility has reportable quantities of gasoline in underground tanks Facility has implemented plan and employees receive training ..; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/28/2014
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Received Designated Operator training record for employee Walid Shafik dated 7-15-14. Violation TS12 has been abated; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/01/2022
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

INSPECTION COMMENT: TESTER: Jimmy Kong – verified ICC & Veeder-Root, & VMI TANK: 87 (12,000 gallons) 91 6,000 gallons/split tank) Diesel (6,000 gallons/split tank) MONITORING PANEL: Veeder-Root TLS-350R LEAK SENSORS: All turbine and fill sumps are monitored by VR-208 leak sensors All tank interstitial spaces are monitored by VR-420 leak sensors LLD: Mechanical line leak detector OVERFILL: Flappers UDCs: All monitored by float and chain mechanism. Monitoring Certification was last conducted on 6/16/2021. Secondary Containment Testing was last conducted on 7/20/2021. Overfill Prevention Equipment Test was conducted on 7/20/2021. Please submit all test results within 30 days to this Agency.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/05/2024
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

On site to conduct a routine monitoring certification inspection. Consent to enter and inspect was provided by Juan Garcia, Cashier. Testing was conducted by Jimmy Kong of COX UST Services. ICC, VMI, and Veeder Root certifications were verified. The facility has two double-walled tanks: - 12K gallon 87 tank - 6K gallon 91 tank* - 6K gallon Diesel tank* *compartment tank Product piping is double-walled and pressurized. The UST system is

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

monitored using a Veeder Root TLS-350 panel. The panel displays indicate "All Functions Normal". The monitor is operational for audible and visual alarms. Flapper valves are used for overfill prevention. The tanks are monitored as follows: Annulars: 420 STPs: 208 UDC's: Bravo with floats/chains LLDs: VMI LD2000 (87, 91), RJ FX1DV (diesel) Sensors were observed positioned to initiate alarms at the earliest point possible. All regulated sensors were tested hydrostatically and passed. Positive Shutdown and Fail Safe programming were verified. The fol; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/10/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site for routine hazardous materials and business emergency plan inspection. The inspection was conducted with Patricia Avalos, Cashier. Ownership changed from BR Petroleum, Inc. to Kormex Management, Inc. on 3/14/2020. Observed the facility and inspected hazardous materials storage. The following materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: - Gasoline, 18,000 gal - Diesel, 6,000 gal The facility is responsible for identifying all hazardous materials, to include hazardous wastes, which are above disclosure thresholds of 55 gallons for liquids, 500 pounds for solids, & 200 cubic feet for gases. If there is a change in the type or amount of chemicals that are maintained on site, please submit revised documents (electronically) within 30 days of the change. Hazardous Materials documents can be submitted via the California Environmental Reporting System (CERS) located at <http://cers.calepa.ca.gov/>. [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/27/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

On site to witness annual monitoring system certification and spill bucket test and to conduct a routine UST inspection. The site has the following double-walled tanks: - 87 (12,000 gal) - 91/Diesel (6,000 gal each - split tank) Product piping for all tanks is double-walled and pressurized. UST system is monitored via Veeder Root TLS-350 Panel. Annulars: - VR420 Fill/STP sumps: - VR208 UDCs: - Bravo Box w/ Float & Chain Mechanism LLDs: - 87 and 91 = VMI LD 2000 - Diesel = Red Jacket FX1DV The following were tested: - Spill buckets (hydrostatic test), spill buckets passed testing. - All liquid detection sensors (sensors submerged in liquid, positive shutdown verified) - Sensor out and fail-safe (verified) - LLDs (91 and Diesel LLD failed) Tanks utilize flapper valves for overfill prevention and were inspected/tested today. Testing was conducted by David Simon with ShanCor Testing. Technician certs (VR, ICC and VMI) were [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/01/2013
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This is an in-office inspection report to document the submittal of the following: - DO monthly Inspection report from 2/21/13, 3/15/13, - Equipment repair log and service invoice from John Reilly from 6-24/13, 1/17/13 This is proof of compliance, therefore violations TR05 and TS11 are abated today. Thank you; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/15/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

Mark Sutphin onsite to conduct routine UST inspection and hazardous waste inspection and to witness monitor certification testing . Consent to enter, inspect the facility and take photographs was granted by the cashier Akram Ahmed. The Veeder-Root TLS-350 monitoring panel displayed "all functions normal" The panel was noted marked with a sticker from the most recent monitoring certification (6-16-17). Dave Simon was at site to perform the

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

annual monitor certification testing this date and the system passed. Certifications reviewed and were up to date The facility has three double walled modern welding tanks. The diesel ,91 tank is a dual compartment tank. The fill sumps and turbine sumps were dry and the VR 208 sensors were properly positioned at the low points. The 4 UDCs were inspected this date and the UDCs were dry and have Chain floats The two tank annuli sensors are VR 420 sensors The diesel sump sensors were tested and did not shut down the turbines [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/08/2019
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

The UST submittal on the California Environmental Reporting System (CERS) requires corrections. The following violation has been issued: - I582: Complete and accurate UST operating permit application has not been submitted. In addition, the following violations cited during the 6/15/18 inspection remain outstanding: - I188: Diesel sump sensors did not shut down the turbines when a leak was detected. - I583: Financial responsibility documents submitted on CERS are dated 3/16/17; documents must be current and submitted annually. - I127: Designated Operator training records show that last training was done on 3/10/17; must be conducted annually. Submit current documentation to this Agency within 30 days to abate these outstanding violations. Contact me at acabadol@ochca.com or 714-625-2702 if you have questions.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/15/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Reviewed CERS submittal 10571791.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/08/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site for routine hazardous materials and business emergency plan inspection at Shell Gas Station, 13202 Brookhurst Blvd, Garden Grove. Consent to enter and inspect was given by Ahmed Saad, owner. Observed the facility and inspected hazardous materials storage. The following materials were observed in amounts that meet or exceed the minimum volumes required for disclosure: -Gasoline, UST -Diesel, UST Business emergency plan was not maintained on-site. A copy of the HMBEP was provided to Annual employee safety training records were not available. A violation was issued for the records. The facility is responsible for identifying all hazardous materials, to include hazardous wastes, which are above disclosure thresholds. If there is a change in the type or amount of chemicals that are maintained on site, please submit revised documents (electronically) within 30 days of the change.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/16/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Mark Sutphin on site to conduct a routine Hazmat facility e inspection. Permission to enter, inspect, and take photographs granted by Patricia Abalos Facility has submitted a hazmat Business Emergency plan on CERS 10571791 Facility has reported gasoline in USTs Diesel, and fuel contaminated absorbent. Facility has less than 1000 cubic feet of CO2 at site. Facility has implemented a hazmat business plan and provides employee training; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/24/2020

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Violations Found:		No				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		UST				
Eval Source:		CERS				
Eval Notes:						
This Agency has received documentation dated 7/1/2019 that the 91 & Diesel line leak detectors have been repaired, re-tested, and PASSED. Violation I198 has been corrected. There are no remaining violations for this facility as of this date.; Note: data in [EVAL Notes] field for some records is truncated from the source.						
Eval Date:		06/22/2023				
Violations Found:		No				
Eval General Type:		Compliance Evaluation Inspection				
Eval Type:		Routine done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		UST				
Eval Source:		CERS				
Eval Notes:						
On site for routine UST inspection, monitoring system certification and spill bucket testing. The facility has three double-walled tanks (87, 91/diesel split) monitored by a Veeder Root TLS-350 system. The monitor is operational for audible and visual alarms. Flapper valves are used for overfill prevention. The following sensors are used for monitoring: - Tank annulars- M420 - Sumps: M208 - UDCs: Bravo B2000 with floats/chains - LLD: VMI LD2000 (87, 91), RJ FXIDV (diesel) Testing was conducted by Jimmy Kong of Cox Compliance. Technician certifications (VR, ICC, VMI) were verified. Please submit the test reports to this Agency within 30 days. The following documents are available for review: permit, leak response plan, monitoring plan, test reports, maintenance records, DO monthly reports, and DO annual employee training records. Secondary containment testing was last conducted on 7/20/2021. Overfill prevention was last tested on 7/20/2021. These must be tested every 3 years. Certi; Note: data in [EVAL Notes] field for some records is truncated from the source.						
Eval Date:		06/22/2021				
Violations Found:		No				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		UST				
Eval Source:		CERS				
Eval Notes:						
Received monitor certification test results for testing performed 6-16-21. Testing was witnessed by M Sutphin and passed; Note: data in [EVAL Notes] field for some records is truncated from the source.						
Eval Date:		01/03/2020				
Violations Found:		Yes				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		UST				
Eval Source:		CERS				
Eval Notes:						
This is a follow up inspection to the on site UST inspection conducted on 6/27/2019. The UST submittal received on 12/28/2019 to the California Environmental Reporting System (CERS) has been reviewed and declined. The following violations have been corrected: - I188: Leak detection equipment properly installed, calibrated, operated and maintained. - I583: Submitted/maintained current Certificate of Financial Responsibility Please see regulator comments in CERS and re-submit all corrections to this Agency immediately at http://cers.calepa.ca.gov/ .; Note: data in [EVAL Notes] field for some records is truncated from the source.						
Eval Date:		04/27/2016				
Violations Found:		No				
Eval General Type:		Other/Unknown				
Eval Type:		Other, not routine, done by local agency				
Eval Division:		Orange County Environmental Health				
Eval Program:		HMRRP				
Eval Source:		CERS				
Eval Notes:						

<i>Map Key</i>	<i>Number of Records</i>	<i>Direction</i>	<i>Distance (mi/ft)</i>	<i>Elev/Diff (ft)</i>	<i>Site</i>	<i>DB</i>
----------------	--------------------------	------------------	-------------------------	-----------------------	-------------	-----------

HMBEP declined in CERS. The following notes were included in the review: "Label the following on the site map: -Evacuation staging area -Storm drains and sewers -Emergency response equipment"; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/11/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HW
Eval Source: CERS
Eval Notes:

Onsite for a routine hazardous waste inspection. Consent to enter and inspect was granted by Patricia Avalos. The facility generates the following hazardous wastes: - Used oil absorbent Observed facility, perimeter, hazardous waste storage area, and dumpster area. Hazardous waste containers were stored closed. No indication of hazardous waste spillage, runoff, or illegal disposal was observed. Emergency response plan in onsite. Employees are reported to be trained. Manifests were available for review. Facility has 6 employees. No hazardous waste violations were observed. Emailed a copy of the report to ggshell@rmshell.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/05/2013
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This is an in-office inspection report to document the submittal of the results of the Annual monitoring system certification test conducted on 6-26-13 by Peyman Nasibi of Shancor. The Results indicated the following: - all sensors passed testing - all 3 leak detectors passed - All spill buckets passed a 1 hr visual hydrostatic test - Chain and Float mechanisms all passed All components of the test passed.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/11/2023
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Orange County Environmental Health
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

On site to conduct a routine hazardous materials inspection. Consent to enter and inspect was granted by Patricia Avalos. Observed the following disclosable hazardous materials: - Gasoline - Diesel Documented employee training was verified. Hazardous Materials Business Plan (HMBP) submittal in CERS was verified. No hazardous materials violations were observed. Emailed a copy of this report to ggshell@rmshell.com.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/13/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Orange County Environmental Health
Eval Program: UST
Eval Source: CERS
Eval Notes:

This Agency has received the following documents in CERS on 1/27/2020 and have been ACCEPTED: - UST Monitoring Plan/Tank Pages - UST Monitoring Site Plan (Plot Plan Map) - CFR + CFO Letter - Response Plan - DO Agreement - Statement of Understanding & Compliance - Owner/Operator Agreement The following violations have been corrected: - I003: Facility has an approved Monitoring Plan. - I582: Complete and accurate UST Operating Permit Application has been submitted. - I421: A current UST monitoring plan is available on site. - I161: A current facility plot plan is maintained and has been submitted. - I506: Secondary containment testing conducted per requirements & records kept for 36 months. - I276: Copies of DO inspections for last 36 months maintained, 36 months after 10/1/18. - I651: At least one employee is present during operating hours that has received DO training. - I015: Owner/Operator retained a copy of the permit to operate at the facility. The [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 06/01/2016
Violations Found: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

monitor cert due 6-10-16 no notification received; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/10/2020
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

On site to witness annual monitoring system certification, spill bucket test, and conduct a UST inspection. Ownership changed from BR Petroleum, Inc. to Kormex Management, Inc. on 3/14/2020. Tester: - Jimmy Kong, Cox Testing. Technician certifications (VR, VMI, ICC) were verified.. Tanks (DW): - 87 (12,000 gal) - 91 (6,000 gal)/Diesel (6,000 gal) - split tank Panel: - Veeder Root TLS-350 Annulars: - VR-420 Fill/STP sumps: - VR208 UDC's: - Bravo Box w/ Float & Chain Mechanism LLD's: - 87 + 91 = VMI LD2000 - Diesel = Red Jacket FX1DV Sensor out, fail safe, and positive shut down were verified. Tanks utilize flapper valves for overfill prevention. Facility has a submission in CERS. The following documentation was available for review: - Monitoring Plan/Tank Pages - Plot Plan Map - CFR + CFO Letter - Leak Response Plan - DO Agreement - DO Training - DO Report - Maintenance Records - Alarm Logs - Monitoring System [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	09/03/2020
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRP
Eval Source:	CERS
Eval Notes:	

This Agency has received and ACCEPTED the following documentation submitted to CERS on 8/30/2020: - Business Activities - Business Owner/Operator Identification - Emergency Response Plan - Employee Training Plan Violations I368 and I736 have been corrected. There are no remaining outstanding violations for this facility.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/05/2017
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Per review of file the monitor certification testing is due by 6-15-17; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/07/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Reviewed CERS 10571791 and it is up to date Monitor certification is due by 6-10-16. I called the Owner Ahmed Saad and left as message saying the Certification is due. I inspected site this date and spoke with Mohamed Elshazly. The documentation at site is up to date and Monthly DO reports are in good order. .; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/16/2014
Violations Found:	Yes

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Onsite to conduct routine UST inspection and hazardous waste inspection. Consent to enter, inspect the facility and take photographs was granted by the cashier Joey Manlangit. The Veeder-Root TLS-350 monitoring panel displayed "all functions normal" and audible and visual alarms were demonstrated operational. The panel was noted marked with a sticker from the most recent monitoring certification (6-11-14). Opened UDCs were inspected this date and the UDCs were dry and Chain floats appear ok The following documents were available for review on this date: - Permit - Monitoring plan (5/14/11) - Monitoring plot plan - Response plan (5/14/11) - Designated operator monthly reports - Maintenance and spill log (see violation) - Employee training conducted by DO note that no records were observed that were less than one year old (see violation) - Financial responsibility and CFO letter 6-20-13 Note that a new form is due by 6-20-14 - Owner statement of [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/16/2017
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Mark Sutphin onsite to conduct routine UST inspection and hazardous waste inspection and to witness monitor certification testing . Consent to enter, inspect the facility and take photographs was granted by the cashierAkram Ahmed. The Veeder-Root TLS-350 monitoring panel displayed "all functions normal" The panel was noted marked with a sticker from the most recent monitoring certification (6-15-16). Dave Simon was at site to perform the annual monitor certification testing this date and the system passed. Certifications reviewed and were up to date The facility has three double walled modern welding tanks. The diesel ,91 tank is a dual compartment tank. The fill sumps and turbine sumps were dry and the VR 208 sensors were properly positioned at the low points. The 4 UDCs were inspected this date and the UDCs were dry and have Chain floats The two tank annuli sensors are VR 420 sensors All sensors were tested and passed The spill buckets were water tested [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	04/08/2016
Violations Found:	No
Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Reviewed CERS 10571791 and accepted by M Sutphin Financial responsibility dated 3-16-16. Owner statement of DO dated 3-16-16 ..; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/15/2018
Violations Found:	Yes
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	HMRRP
Eval Source:	CERS
Eval Notes:	

Mark Sutphin on site to conduct a routine hazardous waste inspection. Permission to enter, inspect, and take photographs granted by the manager Akram Ahmed Facility has not annually submitted on CERS. The Underground tank information on CERS must have the date of installation listed use 1-1-1900 if installation date is unknown . CHANGED FEDERAL HAZARD CATEGORIES Cal EPA recently replaced the previous five federal hazard categories with twenty-four new federal hazard categories, these categories for all of your disclosed hazardous materials are required to by updated to the new classification. Your hazardous materials inventory forms are conditionally accepted but must be updated with new categories in your next submission. Please uncheck boxes for federal hazard categories that are "(Obsolete)", and check the appropriate categories for each disclosed material. Consult your SDS (safety data sheet) for each material, and look under "Section 2 – Hazards Identification" [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	05/15/2017
Violations Found:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Eval General Type:	Other/Unknown
Eval Type:	Other, not routine, done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Reviewed CERS submittal 10571791. CFR dated 3-16-17. DO statement dated 3-16-17. Submittal approved; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date:	06/16/2021
Violations Found:	No
Eval General Type:	Compliance Evaluation Inspection
Eval Type:	Routine done by local agency
Eval Division:	Orange County Environmental Health
Eval Program:	UST
Eval Source:	CERS
Eval Notes:	

Mark Sutphin onsite to conduct routine UST inspection and hazardous waste inspection and to witness monitor certification testing . Consent to enter, inspect the facility and take photographs was granted by the cashier Patricia Abalos. The Veeder-Root TLS-350 monitoring panel displayed "all functions normal" The panel was noted marked with a sticker from the most recent monitoring certification . Jimmy Kong was at site to perform the annual monitor certification testing this date and the system passed. Certifications reviewed and were up to date The facility has three double walled modern welding tanks. The diesel ,91 tank is a dual compartment tank. The fill sumps and turbine sumps were dry and the VR 208 sensors were properly positioned at the low points. The 4 UDCs were inspected this date and the UDCs were dry and have Chain floats The two tank annuli sensors are VR 420 sensors The diesel sump sensors were tested and did not shut down the turbines when a [Truncated]; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc:	Legal Owner
Entity Name:	KORMEX MANAGEMENT INC
Entity Title:	
Address:	13202 Brookhurst St
City:	Garden Grove
State:	CA
Country:	United States
Zip Code:	92843
Phone:	(714) 606-7484

Affil Type Desc:	CUPA District
Entity Name:	Orange County Env Health
Entity Title:	
Address:	1241 East Dyer RoadSuite 120
City:	Santa Ana
State:	CA
Country:	
Zip Code:	92705-5611
Phone:	(714) 433-6406

Affil Type Desc:	Parent Corporation
Entity Name:	SHELL #120718
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Facility Mailing Address
Entity Name:	Mailing Address
Entity Title:	
Address:	13202 BROOKHURST ST
City:	GARDEN GROVE
State:	CA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Country:						
Zip Code:		92843				
Phone:						
Affil Type Desc:		Operator				
Entity Name:		GARDEN GROVE SHELL				
Entity Title:						
Address:						
City:						
State:						
Country:						
Zip Code:						
Phone:		(714) 606-7484				
Affil Type Desc:		UST Tank Operator				
Entity Name:		KORMEX MANAGEMENT, INC				
Entity Title:						
Address:		13202 BROOKHURST ST				
City:		FULLERTON				
State:		CA				
Country:		United States				
Zip Code:		92843				
Phone:		(714) 606-7484				
Affil Type Desc:		Identification Signer				
Entity Name:		Jimmy Kong				
Entity Title:		AUTHORIZED REPRESENTATIVE				
Address:						
City:						
State:						
Country:						
Zip Code:						
Phone:						
Affil Type Desc:		Document Preparer				
Entity Name:		JIMMY KONG				
Entity Title:						
Address:						
City:						
State:						
Country:						
Zip Code:						
Phone:						
Affil Type Desc:		UST Property Owner Name				
Entity Name:		AHMED SAAD				
Entity Title:						
Address:		13202 BROOKHURST ST				
City:		FULLERTON				
State:		CA				
Country:		United States				
Zip Code:		92843				
Phone:		(562) 682-5763				
Affil Type Desc:		Environmental Contact				
Entity Name:		JIMMY KONG				
Entity Title:						
Address:		418 E COMMONWEALTH AVE #7				
City:		FULLERTON				
State:		CA				
Country:						
Zip Code:		92832				
Phone:						
Affil Type Desc:		UST Tank Owner				
Entity Name:		KORMEX MANAGEMENT, INC				
Entity Title:						
Address:		13202 BROOKHURST ST				
City:		FULLERTON				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
State:		CA				
Country:		United States				
Zip Code:		92843				
Phone:		(714) 606-7484				
<u>Coordinates</u>						
Env Int Type Code:		HMBP		Longitude:		-117.954630
Program ID:		10571791		Coord Name:		
Latitude:		33.771070		Ref Point Type Desc:		Center of a facility or station.

30	8 of14	NE	0.23 / 1,217.53	74.91 / 1	JET 13202 BROOKHURST GARDEN GROVE CA	HIST TANK
Owner Name:		KAYO OIL COMPANY		No of Containers:		3
Owner Street:		1221 E. MAIN STREET		County:		ORANGE
Owner City:		CHATTANOOGA		Facility State:		CA
Owner State:		TN		Facility Zip:		92640
Owner Zip:		37408				

30	9 of 14	NE	0.23 / 1,217.53	74.91 / 1	BR PETROLEUM INC 13202 BROOKHURST GARDEN GROVE CA 92843	EMISSIONS
--------------------	---------	----	--------------------	--------------	---	-----------

2016 Toxic Data

Facility ID:	181190	TS:	
Facility SIC Code:	5172	HRA:	
CERR CODE:		CH Index:	
COID:	ORA	AH Index:	
CO:	30	Air Basin:	SC
DISN:	SOUTH COAST AQMD	District:	SC
CHAPIS:			

2017 Toxic Data

Facility ID:	181190	COID:	ORA
Facility SIC Code:	9999	DISN:	SOUTH COAST AQMD
CO:	30	CHAPIS:	
Air Basin:	SC	CERR Code:	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Toxic Data

Facility ID:	181190	COID:	ORA
Facility SIC Code:	9999	DISN:	SOUTH COAST AQMD
CO:	30	CHAPIS:	
Air Basin:	SC	CERR Code:	
District:	SC		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<u>2019 Toxic Data</u>						
CO:	30				DISN:	SOUTH COAST AQMD
Air Basin:	SC				CHAPIS:	
Facility ID:	181190				CERR Code:	
District:	SC				TS:	
Facility SIC Code:	9999				Health Risk Asmt:	
COID:	ORA					
Non-Cancer Chronic Haz Ind:						
Non-Cancer Acute Haz Ind:						
30	10 of 14	NE	0.23 / 1,217.53	74.91 / 1	M & R STATION 13202 BROOKHURST GARDEN GROVE CA 92843	UST ORANGE
FA No:		FA24722				
SR No:						
Notes:						
Data Source:		Removed Underground Storage Tank (UST) Facilities				
30	11 of 14	NE	0.23 / 1,217.53	74.91 / 1	ULTRAMAR STATION 13202 BROOKHURST GARDEN GROVE CA 92843	UST ORANGE
FA No:		FA24722				
SR No:						
Notes:						
Data Source:		Removed Underground Storage Tank (UST) Facilities				
30	12 of 14	NE	0.23 / 1,217.53	74.91 / 1	GARDEN GROVE SHELL 13202 BROOKHURST GARDEN GROVE CA 92843	RCRA NON GEN
Handler ID:		CAL000453941				
Generator Status:		N				
Recycler Activity?:		NO				
Recycler Activity Note:		This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.				
<u>Violation/Evaluation Summary</u>						
Note:		NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).				
<u>Handler Summary</u>						
Importer:	No				Used Oil Transpor:	No
Mixed Waste Gen:	No				Used Oil Trans Fac:	No
Transporter:	No				Used Oil Processor:	No
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:	No					
Used Oil Spec Marketer:	No					
<u>Additional Handler Summary Details</u>						
Source Type:	I				NAIC 1:	447190
Seq No:	1				NAIC 2:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Non Notifier:				NAIC 3:		
Receive Date:	20200325			NAIC 4:		
Active Site:	----			State:	CA	
Land Type:	P			Location Latitude:		
In Handler Univ:	N			Location Longitude:		
In A Universe:	N			Loc GIS Primary:	N	
Gen Status:	N			Loc GIS Origin:		
Report Cycle:				State District Owner:		
Accessibility:				State District:		
Region:	09					
Fed Waste Gen Owner:		HQ				
State Waste Generator Owner:		CA				
State Waste Generator:		2				
Short Term Generator:		N				
Uni Waste:		N				
Universal Waste Dest Facility:		N				
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20200330				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		GARDEN GROVE SHELL				
Location Street No:		13202				
Location Street1:		BROOKHURST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		FREDERICK KIM				
Contact Street No:		20220				
Contact Street1:		LANDIG CIR				
Contact Street2:						
Contact City:		YORBA LINDA				
Contact State:		CA				

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Zip:		92887				
Contact Country:		US				
Contact Phone And Ext:		714-606-7484				
Contact Fax:		562-402-8084				
Contact Email Address:		FKIM@RMSHELL.COM				
Contact Title:		CFO				
Owner Name:		KORMEX MANAGING & MARKETING INC				
Owner Type:		P				
Owner Seq:		1				
Operator Name:		KORMEX MANAGING & MARKETING INC				
Operator Type:		P				
Operator Seq:		2				
Public Notes:						

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20200325
Handler Name: GARDEN GROVE SHELL
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	14251
Type:	Private	Street1:	FIRESTONE #210
Name:	KORMEX MANAGING & MARKETING INC	Street2:	
Dt Became Current:		City:	LA MIRADA
Dt Ended Current:		State:	CA
Phone:	562-402-8080	Country:	US
Source Type:	Implementer	Zip:	90638

Owner/Operator Ind:	Current Owner	Street No:	14251
Type:	Private	Street1:	FIRESTONE #210
Name:	KORMEX MANAGING & MARKETING INC	Street2:	
Dt Became Current:		City:	LA MIRADA
Dt Ended Current:		State:	CA
Phone:	562-402-8080	Country:	US
Source Type:	Implementer	Zip:	90638

30	13 of 14	NE	0.23 / 1,217.53	74.91 / 1	PRONTO MARKETING 13202 BROOKHURST ST GARDEN GROVE CA	UST SWEEPS
--------------------	----------	----	--------------------	--------------	--	------------

C C:	A30-000-4347	D Filename:	SITE12A
BOE:	44-016175	Page No:	123
Comp:	4347	County:	ORANGE
Status:	ACTIVE	State :	CA
No of Tanks:	3	Zip:	92643
Jurisdict:	ORANGE COUNTY	Latitude:	33.771001
Agency:	ENVIRONMENTAL HEALTH	Longitude:	-117.954884
Phone:		Georesult:	S5HPNTSC-A

Tank Details

Tank ID:	000002	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-004347-000002	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	DIESEL
Capac:	12000	ONA:	
Tank Use:	M.V. FUEL	D File Name:	TANK12A

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Tank Details

Tank ID:	000003	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-004347-000003	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	DIESEL
Capac:	12000	ONA:	
Tank Use:	M.V. FUEL	D File Name:	TANK12A

Tank Details

Tank ID:	000001	S Contain:	
O Tank ID:		Stg:	P
SWRCB No:	30-000-004347-000001	Storage :	
Removed:		Storag Type:	PRODUCT
Installed:		P Contain:	
A Date:		Content:	REG UNLEADED
Capac:	12000	ONA:	
Tank Use:	M.V. FUEL	D File Name:	TANK12A

30	14 of 14	NE	0.23 / 1,217.53	74.91 / 1	KORMEX MANAGEMENT & MARKETING, INC. 13202 BROOKHURST ST GARDEN GROVE CA 92843	EMISSIONS
--------------------	----------	----	--------------------	--------------	--	-----------

2020 Toxic Data

CO:	30	DISN:	SOUTH COAST AQMD
Air Basin:	SC	CHAPIS:	
Facility ID:	192038	CHERR Code:	
District:	SC	TS:	
Facility SIC Code:	9999	Health Risk Asmt:	
COID:	ORA		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2021 Toxic Data

Co:	30	DISN:	SOUTH COAST AQMD
Air Basin:	SC	CHAPIS:	
Facility ID:	192038	Cerr Code:	
District:	SC	TS:	
Facility SIC Code:	9999	Health Risk Asmt:	
COID:	ORA		
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

31	1 of 1	NE	0.24 / 1,263.24	74.59 / 1	PACIFIC COAST OIL CO 13169 J BROOKHURST ST GARDEN GROVE CA 92843	RCRA NON GEN
--------------------	--------	----	--------------------	--------------	--	-----------------

Handler ID:	CAD981428766
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	Yes	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	NAIC 1:	
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	19860722	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:	O	Location Latitude:	33.771559
In Handler Univ:	Y	Location Longitude:	-117.955178
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	CA
Accessibility:		State District:	4
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	HQ		
State Waste Generator:	N		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	-----		
Full Enforcement:	-----		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Fa Required:		----				
Hhandler Last Change:		20020627				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		PACIFIC COAST OIL CO				
Location Street No:						
Location Street1:		13169 J BROOKHURST ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		ENVIRONMENTAL MANAGER				
Contact Street No:						
Contact Street1:		13169 J BROOKHURST ST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92643				
Contact Country:		US				
Contact Phone And Ext:		714-539-7009				
Contact Fax:						
Contact Email Address:						
Contact Title:						
Owner Name:		WILLIAM HUH				
Owner Type:		P				
Owner Seq:		1				
Operator Name:		NOT REQUIRED				
Operator Type:		P				
Operator Seq:		2				
Public Notes:						

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19860722
Handler Name: PACIFIC COAST OIL CO
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19900419
Handler Name: SORENSON ENGINEERING, INC.
Fed Waste Generator: 1
Generator Code Description: Large Quantity Generator
Source Type: Annual/Biennial Report

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Private	Street1:	NOT REQUIRED
Name:	WILLIAM HUH	Street2:	
Dt Became Current:		City:	NOT REQUIRED
Dt Ended Current:		State:	ME
Phone:	415-555-1212	Country:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Source Type:	Notification			Zip:	99999	
Owner/Operator Ind:	Current Operator			Street No:		
Type:	Private			Street1:	NOT REQUIRED	
Name:	NOT REQUIRED			Street2:		
Dt Became Current:				City:	NOT REQUIRED	
Dt Ended Current:				State:	ME	
Phone:	415-555-1212			Country:		
Source Type:	Notification			Zip:	99999	

Historical Handler Details

Receive Dt: 19900419
 Generator Code Description: Large Quantity Generator
 Handler Name: SORENSON ENGINEERING, INC.

32	1 of 1	NE	0.24 / 1,281.70	74.74 / 1	DENTAL OFFICE LIEN HUONG 13161 BROOKHURST ST GARDEN GROVE CA 92843-0000	RCRA NON GEN
--------------------	--------	----	--------------------	--------------	---	-----------------

Handler ID: CAL000223611
 Generator Status: N
 Recycler Activity?: NO
 Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	No	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	62121
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20010713	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.771861
In Handler Univ:	Y	Location Longitude:	-117.955146
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	Y		
Universal Waste Dest Facility:	Y		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Federal Universal Waste:		N				
As Federally Regulated Tsdf:		-----				
As Converter Tsdf:		-----				
As State Regulated Tsdf:		-----				
As State Regulated Handler:		---				
Federal Indicator:		---				
Hsm:		N				
Subpart K:		----				
GPRA Permit:		N				
GPRA Renewal:		N				
Permit Renewal Wrkld:		-----				
Permwrk ID:		-----				
Perm Prog:		-----				
Pcwrkld:		-----				
Closwrkld:		-----				
GPRA Ca:		N				
Cawrkld:		N				
Subjca Tsd Discretion:		N				
NCAPS:		N				
EC Indicator:		N				
Ca725 Indicator:		N				
Ca750 Indicator:		N				
Operating Tsdf:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20180905				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		DENTAL OFFICE LIEN HUONG				
Location Street No:						
Location Street1:		13161 BROOKHURST ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843-0000				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		LIEN-HUONG D NGUYEN DDS				
Contact Street No:						
Contact Street1:		13161 BROOKHURST ST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92843				
Contact Country:						
Contact Phone And Ext:		714-539-4140				
Contact Fax:		714-539-4401				
Contact Email Address:		CUNGH11997@YAHOO.COM				
Contact Title:						
Owner Name:		LIEN-HUONG D NGUYEN				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		LIEN-HUONG D NGUYEN DDS				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20010713
 Handler Name: DENTAL OFFICE LIEN HUONG
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	13161 BROOKHURST ST
Name:	LIEN-HUONG D NGUYEN	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-539-4140	Country:	
Source Type:	Implementer	Zip:	92843-0000

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	13161 BROOKHURST ST
Name:	LIEN-HUONG D NGUYEN DDS	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-539-4140	Country:	
Source Type:	Implementer	Zip:	92843

33	1 of1	E	0.25 / 1,321.03	75.45 / 2	ARCO #629 13482 BROOKHURST ST GARDEN GROVE CA 92843	DELISTED TNK
--------------------	-------	---	--------------------	--------------	---	-----------------

Delisted Storage Tanks

Facility ID:	4348	County:	Orange
Latitude:	33.768472	Original Source:	UST
Longitude:	-117.9528279	Record Date:	30-JAN-2017
Permitting Agency:	ORANGE COUNTY		

34	1 of1	N	0.28 / 1,453.83	75.58 / 2	Ejax Water Systems 9911 Larson Ave Garden Grove Ca 92844-1657 CA	LOP ORANGE
--------------------	-------	---	--------------------	--------------	---	------------

Case ID: 89UT181

Details

Current Status: Closed
 Type of Closure: Closure certification issued
 Closed Date: 12/14/1989
 File Location: Local Agency

35	1 of1	N	0.28 / 1,454.05	75.63 / 2	EJAX WATER SYSTEMS 9911 LARSON GARDEN GROVE CA 92644	LUST
--------------------	-------	---	--------------------	--------------	--	------

Global ID:	T0605901020	Case Type (DL):	LUST Cleanup Site
Site Facility Type:	LUST CLEANUP SITE	Oil Field (SRCH):	
Site Fac Type (SRCH):	LUST CLEANUP SITE	Oil Field Oper (SRCH):	
Status:		Census Tract (SRCH):	6059088702

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Status (SRCH):	COMPLETED - CASE CLOSED			Latitude (DL):	33.7725089	
Status (DL):	Completed - Case Closed			Longitude (DL):	-117.9579643	
Status Date (DL):	12/14/1989			RWQCB Region (DL):	SANTA ANA RWQCB (REGION 8)	
Cleanup Status:	COMPLETED - CASE CLOSED					
Site Facility Name (SRCH):	EJAX WATER SYSTEMS					
Address (SRCH):	9911 LARSON					
City (SRCH):	GARDEN GROVE					
Zip (SRCH):	92644					
County (SRCH):	ORANGE					
Street No (DL):	9911					
Street Name (DL):	LARSON					
City (DL):	GARDEN GROVE					
Zip (DL):	92644					
County (DL):	Orange					
State (DL):	CA					
Business Name (DL):	EJAX WATER SYSTEMS					
Site Facility Name:	EJAX WATER SYSTEMS					
Address :	9911 LARSON					
City :	GARDEN GROVE					
Zip :	92644					
County :	ORANGE					
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search					

GeoTracker Sites Data Download - Site Details

CUF Case:
Lead Agency: ORANGE COUNTY LOP
Case Worker:
Local Agency:
RB Case No: 083001342T
Local Case No: 89UT181
File Location: Local Agency
Potential COC: Gasoline
Potential Media of Concern: Soil
Begin Date: 8/24/1989
How Discovered: Tank Closure
How Discovered Description:
Stop Method: Close and Remove Tank
Stop Description:
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name: Coastal Plain Of Orange County (8-001)
Disadvantaged Community:
CalEnvScreen Score:
Coordinate Source: Google Geocode
Discharge Cause:
Discharge Source:
EPA Region: 9
Leak Reported Dt: 1989-08-24 00:00:00
Military DoD Site: No
No Further Action Dt: 1989-12-14 00:00:00
Qty Rlsd Gallons: 0
Facility Project Sub Type:
Calenviroscreen 3 Score: 51-55%
Calenviroscreen 4 Score: 60-65%
A2022 Assembly District: 70
Claim No:
Claim Status:
A2022 Congressional District: 45
A2022 Senate District: 36
Site History:

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: PATRICIA HANNON

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 MAIN STREET, SUITE 500
City: RIVERSIDE
Email: patricia.hannon@waterboards.ca.gov
Phone No:

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 12/14/1989

Status: Open - Case Begin Date
Status Date: 8/24/1989

GeoTracker Search - Regulatory Profile

Site Facility Name: EJAX WATER SYSTEMS
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 9911 LARSON
City: GARDEN GROVE
Zip: 92644
County: ORANGE
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605901020
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 12/14/1989
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605901020&tabname=regulatoryhistory
Potential COC: GASOLINE
Potential Media of Concern: SOIL
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
DWR GW Sub Basin: Coastal Plain Of Orange County (8-001)
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: ORANGE COUNTY LOP (LEAD) - CASE #: 89UT181
 SANTA ANA RWQCB (REGION 8) - CASE #: 083001342T
 CASE MANAGER: PATRICIA HANNON
CUF Claim No:
CUF Priority Assig:
CUF Amount Paid:
WDR Place Type:
WDR File No:
WDR Order No:
Project Oversight Agencies:
Facility Type:
Composting Method:
Grndwtr Monitoring Frequency:
Designated Beneficial Use Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
Desc:
Site History:

No site history available

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 12/14/1989

Status: Open - Case Begin Date
Date : 8/24/1989

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

GeoTracker Search - Cleanup Action Report

Action Type: EXCAVATION
 Begin Date: 1/1/1965
 End Date: 1/1/1965
 Phase:
 Contaminant Mass Removed:
 Description:

GeoTracker Search - Regulatory Activities

Action Type: Other Regulatory Actions
 Action: Historic Files
 Action Date: 2/1/2024
 Received Issue Date: 2/1/2024
 Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605901020&enforcement_id=6571153&temptable=ENFORCEMENT

Title Description Comments:

Historic Files **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type: Leak Action
 Action: Leak Reported
 Action Date: 8/24/1989
 Received Issue Date:
 Doc Link:
 Title Description Comments:

Action Type: Leak Action
 Action: Leak Discovery
 Action Date: 8/24/1989
 Received Issue Date:
 Doc Link:
 Title Description Comments:

GeoTracker Search - Documents

Document Type: Site Documents
 Type: HISTORIC FILES
 Submitted By: LENA SHAW (REGULATOR)
 Title: HISTORIC FILES **Note: Many records provided by the department have a truncated [Title] field.
 Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605901020&enforcement_id=6571153

36	1 of1	N	0.33 / 1,768.44	79.52 / 6	COUNTY WIDE CHRYSLER/JEEP 10080 GARDEN GROVE GARDEN GROVE CA 92842	LUST
Global ID:	T0605918872		Case Type (DL):		LUST Cleanup Site	
Site Facility Type:	LUST CLEANUP SITE		Oil Field (SRCH):			
Site Fac Type (SRCH):	LUST CLEANUP SITE		Oil Field Oper (SRCH):			
Status:			Census Tract (SRCH):		6059088702	
Status (SRCH):	COMPLETED - CASE CLOSED		Latitude (DL):		33.773375	
Status (DL):	Completed - Case Closed		Longitude (DL):		-117.957265	
Status Date (DL):	2/12/2003		RWQCB Region (DL):		SANTA ANA RWQCB (REGION 8)	
Cleanup Status:	COMPLETED - CASE CLOSED					
Site Facility Name (SRCH):	COUNTY WIDE CHRYSLER/JEEP					
Address (SRCH):	10080 GARDEN GROVE					
City (SRCH):	GARDEN GROVE					
Zip (SRCH):	92842					
County (SRCH):	ORANGE					
Street No (DL):	10080					
Street Name (DL):	GARDEN GROVE					
City (DL):	GARDEN GROVE					

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Zip (DL):		92842				
County (DL):		Orange				
State (DL):		CA				
Business Name (DL):		COUNTY WIDE CHRYSLER/JEEP				
Site Facility Name:		COUNTY WIDE CHRYSLER/JEEP				
Address :		10080 GARDEN GROVE				
City :		GARDEN GROVE				
Zip :		92842				
County :		ORANGE				
Report Source:		LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search				

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	ORANGE COUNTY LOP
Case Worker:	
Local Agency:	
RB Case No:	
Local Case No:	99UT016
File Location:	Local Agency
Potential COC:	Gasoline
Potential Media of Concern:	Other Groundwater (uses other than drinking water)
Begin Date:	2/23/1999
How Discovered:	Tank Closure
How Discovered Description:	
Stop Method:	Close and Remove Tank
Stop Description:	
Calwater Watershed Name:	Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name:	Coastal Plain Of Orange County (8-001)
Disadvantaged Community:	
CalEnvScreen Score:	
Coordinate Source:	Google Geocode
Discharge Cause:	
Discharge Source:	
EPA Region:	9
Leak Reported Dt:	1999-02-23 00:00:00
Military DoD Site:	No
No Further Action Dt:	2003-02-12 00:00:00
Qty Rlsd Gallons:	0
Facility Project Sub Type:	
Calenviroscreen 3 Score:	51-55%
Calenviroscreen 4 Score:	60-65%
A2022 Assembly District:	70
Claim No:	15872
Claim Status:	Ineligible
A2022 Congressional District:	45
A2022 Senate District:	36
Site History:	

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type:	Regional Board Caseworker
Contact Name:	JESSICA LAW
Organization Name:	SANTA ANA RWQCB (REGION 8)
Address:	3737 Main Street, Suite 500
City:	RIVERSIDE
Email:	jessica.law@waterboards.ca.gov
Phone No:	9517824381

GeoTracker Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	2/12/2003

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Status: Open - Case Begin Date
Status Date: 2/23/1999

GeoTracker Search - Regulatory Profile

Site Facility Name: COUNTY WIDE CHRYSLER/JEEP
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 10080 GARDEN GROVE
City: GARDEN GROVE
Zip: 92842
County: ORANGE
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605918872
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 2/12/2003
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605918872&tabname=regulatoryhistory
Potential COC: GASOLINE
Potential Media of Concern: OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
DWR GW Sub Basin: Coastal Plain Of Orange County (8-001)
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: ORANGE COUNTY LOP (LEAD) - CASE #: 99UT016
SANTA ANA RWQCB (REGION 8)
CASE MANAGER: JESSICA LAW

CUF Claim No:
CUF Priority Assig:
CUF Amount Paid:
WDR Place Type:
WDR File No:
WDR Order No:
Project Oversight Agencies:
Facility Type:
Composting Method:
Grndwtr Monitoring Frequency:
Designated Beneficial Use: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note:
Desc: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
Site History:

No site history available

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 2/12/2003

Status: Open - Case Begin Date
Date : 2/23/1999

GeoTracker Search - Cleanup Action Report

Action Type: EXCAVATION
Begin Date: 1/1/1965
End Date: 1/1/1965
Phase:
Contaminant Mass Removed:
Description:

GeoTracker Search - Regulatory Activities

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Action Type: Other Regulatory Actions Action: Closure/No Further Action Letter Action Date: 2/12/2003 Received Issue Date: 2/12/2003 Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605918872&enforcement_id=6194304&temptable=ENFORCEMENT Title Description Comments: RACC and case closure summary **Note: Many records provided by the department have a truncated [Title Description Comments] field.						
Action Type: Leak Action Action: Leak Discovery Action Date: 2/23/1999 Received Issue Date: Doc Link: Title Description Comments:						
Action Type: Leak Action Action: Leak Reported Action Date: 2/23/1999 Received Issue Date: Doc Link: Title Description Comments:						
<u>GeoTracker Search - Documents</u>						
Document Type: Site Documents Type: Submitted By: (REGULATOR) Title: REMEDIAL ACTION COMPLETION CERTIFICATION **Note: Many records provided by the department have a truncated [Title] field. Title Link: https://geotracker.waterboards.ca.gov/site_documents/8116086661/99UT016%2Epdf Document Date: 6/4/2003 Submitted:						
Document Type: Site Documents Type: Submitted By: (REGULATOR) Title: CASE CLOSURE SUMMARY **Note: Many records provided by the department have a truncated [Title] field. Title Link: https://geotracker.waterboards.ca.gov/site_documents/2791150748/99UT016%2Epdf Document Date: 3/26/2003 Submitted:						
Document Type: Site Documents Type: CLOSURE/NO FURTHER ACTION LETTER Submitted By: PAMELA YBARRA (REGULATOR) Title: RACC AND CASE CLOSURE SUMMARY **Note: Many records provided by the department have a truncated [Title] field. Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605918872&enforcement_id=6194304 Document Date: 2/12/2003 Submitted:						
37	1 of 1	ESE	0.35 / 1,870.77	71.48 / -2	MARCOS LOPEZ 13632 DAWSON ST GARDEN GROVE CA 92843	RCRA TSD

Handler ID: CAC003017595
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Importer:	No				Used Oil Transpor:	No
Mixed Waste Gen:	No				Used Oil Trans Fac:	No
Transporter:	No				Used Oil Processor:	No
Transfer Facility:	No				Used Oil Refiner:	No
Recycler:	No				Used Oil Burner:	No
Onsite Burner Exem:	No				Commercial TSD:	No
Furnace Exemption:	No				Recycl Nonstorage:	No
Underground Injec:	No					
Used Oil Market Burner:		No				
Used Oil Spec Marketer:		No				

Additional Handler Summary Details

Source Type:	I	NAIC 1:	56299
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20190531	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.764778
In Handler Univ:	Y	Location Longitude:	-117.952561
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	Y		
Universal Waste Dest Facility:	Y		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	-----		
Full Enforcement:	-----		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20190627		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		
Manifest Broker:	N		
Subpart P:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Contact Language:		EN				
Handler Name:		MARCOS LOPEZ				
Location Street No:						
Location Street1:		13632 DAWSON ST				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92843				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		MARCOS LOPEZ				
Contact Street No:						
Contact Street1:		13632 DAWSON ST				
Contact Street2:						
Contact City:		GARDEN GROVE				
Contact State:		CA				
Contact Zip:		92843				
Contact Country:						
Contact Phone And Ext:		714-654-3111				
Contact Fax:						
Contact Email Address:		OCABATEMENT@GMAIL.COM				
Contact Title:						
Owner Name:		MARCOS LOPEZ				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		MARCOS LOPEZ				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20190531
Handler Name: MARCOS LOPEZ
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Tsd Activity: Y
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Operator	Street No:	
Type:	Other	Street1:	13632 DAWSON ST
Name:	MARCOS LOPEZ	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-654-3111	Country:	
Source Type:	Implementer	Zip:	92843

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	13632 DAWSON ST
Name:	MARCOS LOPEZ	Street2:	
Dt Became Current:		City:	GARDEN GROVE
Dt Ended Current:		State:	CA
Phone:	714-654-3111	Country:	
Source Type:	Implementer	Zip:	92843

38	1 of 1	N	0.37 / 1,959.35	79.17 / 6	County Wide Chrysler/Jeep 10080 Garden Grove Blvd Garden Grove Ca 92844-1694 CA	LOP ORANGE
--------------------	--------	---	--------------------	--------------	--	------------

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Case ID:	99UT016
----------	---------

Details

Current Status:	Closed
Type of Closure:	Closure certification issued
Closed Date:	2/12/2003
File Location:	Local Agency

39	1 of 3	N	0.43 / 2,266.02	80.78 / 7	TOYOTA OF GARDEN GROVE 10081 GARDEN GROVE GARDEN GROVE CA 92641	LUST
--------------------	--------	---	-----------------	-----------	---	------

Global ID:	T0605901533	Case Type (DL):	LUST Cleanup Site
Site Facility Type:	LUST CLEANUP SITE	Oil Field (SRCH):	
Site Fac Type (SRCH):	LUST CLEANUP SITE	Oil Field Oper (SRCH):	
Status:		Census Tract (SRCH):	6059088701
Status (SRCH):	COMPLETED - CASE CLOSED	Latitude (DL):	33.775424
Status (DL):	Completed - Case Closed	Longitude (DL):	-117.956801
Status Date (DL):	4/14/1992	RWQCB Region (DL):	SANTA ANA RWQCB (REGION 8)
Cleanup Status:	COMPLETED - CASE CLOSED		
Site Facility Name (SRCH):	TOYOTA OF GARDEN GROVE		
Address (SRCH):	10081 GARDEN GROVE		
City (SRCH):	GARDEN GROVE		
Zip (SRCH):	92641		
County (SRCH):	ORANGE		
Street No (DL):	10081		
Street Name (DL):	GARDEN GROVE		
City (DL):	GARDEN GROVE		
Zip (DL):	92641		
County (DL):	Orange		
State (DL):	CA		
Business Name (DL):	TOYOTA OF GARDEN GROVE		
Site Facility Name:	TOYOTA OF GARDEN GROVE		
Address :	10081 GARDEN GROVE		
City :	GARDEN GROVE		
Zip :	92641		
County :	ORANGE		
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search		

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	ORANGE COUNTY LOP
Case Worker:	
Local Agency:	
RB Case No:	083002065T
Local Case No:	92UT026
File Location:	Local Agency
Potential COC:	Waste Oil / Motor / Hydraulic / Lubricating
Potential Media of Concern:	Other Groundwater (uses other than drinking water)
Begin Date:	1/29/1992
How Discovered:	Tank Closure
How Discovered Description:	
Stop Method:	Close and Remove Tank
Stop Description:	
Calwater Watershed Name:	Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name:	Coastal Plain Of Orange County (8-001)
Disadvantaged Community:	
CalEnvScreen Score:	
Coordinate Source:	Google Map Move
Discharge Cause:	
Discharge Source:	
EPA Region:	9

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Leak Reported Dt:		1992-01-29 00:00:00				
Military DoD Site:		No				
No Further Action Dt:		1992-04-14 00:00:00				
Qty Rlsd Gallons:		0				
Facility Project Sub Type:						
Calenviroscreen 3 Score:		61-65%				
Calenviroscreen 4 Score:		45-50%				
A2022 Assembly District:		70				
Claim No:						
Claim Status:						
A2022 Congressional District:		45				
A2022 Senate District:		36				
Site History:						

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: JESSICA LAW
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 Main Street, Suite 500
City: RIVERSIDE
Email: jessica.law@waterboards.ca.gov
Phone No: 9517824381

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 4/14/1992

Status: Open - Case Begin Date
Status Date: 1/29/1992

GeoTracker Search - Regulatory Profile

Site Facility Name: TOYOTA OF GARDEN GROVE
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 10081 GARDEN GROVE
City: GARDEN GROVE
Zip: 92641
County: ORANGE
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605901533
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 4/14/1992
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605901533&tabname=regulatoryhistory
Potential COC: WASTE OIL / MOTOR / HYDRAULIC / LUBRICATING
Potential Media of Concern: OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
DWR GW Sub Basin: Coastal Plain Of Orange County (8-001)
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: ORANGE COUNTY LOP (LEAD) - CASE #: 92UT026
SANTA ANA RWQCB (REGION 8) - CASE #: 083002065T
CASE MANAGER: JESSICA LAW
CUF Claim No:
CUF Priority Assig:
CUF Amount Paid:
WDR Place Type:
WDR File No:
WDR Order No:
Project Oversight Agencies:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Facility Type:

Composting Method:

Grndwtr Monitoring Frequency:

Designated Beneficial Use

Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.

Desc:

Site History:

No site history available

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 4/14/1992

Status: Open - Case Begin Date
Date : 1/29/1992

GeoTracker Search - Regulatory Activities

Action Type: Leak Action
Action: Leak Discovery
Action Date: 1/29/1992
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Reported
Action Date: 1/29/1992
Received Issue Date:
Doc Link:
Title Description Comments:

39	2 of3	N	0.43 / 2,266.02	80.78 / 7	Toyota Of Garden Grove 10081 Garden Grove Blvd Garden Grove Ca 92844-1620 CA	LOP ORANGE
--------------------	-------	---	--------------------	--------------	---	------------

Case ID: 92UT026

Details

Current Status: Closed
Type of Closure: Closure certification issued
Closed Date: 4/14/1992
File Location: Local Agency

39	3 of3	N	0.43 / 2,266.02	80.78 / 7	GARDEN GROVE KIA 10081 GARDEN GROVE BLVD GARDEN GROVE CA 92844	C&D DEBRIS RECY
--------------------	-------	---	--------------------	--------------	--	--------------------

County: ORANGE
Activity Type: USED OIL COLLECTION
Phone No: (855) 807-9285

40	1 of1	NNW	0.46 / 2,417.25	76.55 / 3	HOUSE OF HYBRIDS 9825 GARDEN GROVE BLVD GARDEN GROVE CA 92844	RCRA TSD
--------------------	-------	-----	--------------------	--------------	---	----------

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Handler ID:		CAL000444865				
Generator Status:		N				
Recycler Activity?:		YES				
Recycler Activity Note:		This facility has been identified as a Recycler Facility from the RCRA Handler Report Module with a 'Yes' for Recycler Activity with or without Storage.				

Violation/Evaluation Summary

Note: NO RECORDS: As of Jan 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	Used Oil Transpor:	No
Mixed Waste Gen:	No	Used Oil Trans Fac:	No
Transporter:	No	Used Oil Processor:	No
Transfer Facility:	No	Used Oil Refiner:	No
Recycler:	Yes	Used Oil Burner:	No
Onsite Burner Exem:	No	Commercial TSD:	No
Furnace Exemption:	No	Recycl Nonstorage:	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	NAIC 1:	811111
Seq No:	1	NAIC 2:	
Non Notifier:		NAIC 3:	
Receive Date:	20190327	NAIC 4:	
Active Site:	H----	State:	CA
Land Type:		Location Latitude:	33.774027
In Handler Univ:	Y	Location Longitude:	-117.961439
In A Universe:	Y	Loc GIS Primary:	N
Gen Status:	N	Loc GIS Origin:	AG
Report Cycle:		State District Owner:	
Accessibility:		State District:	
Region:	09		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	CA		
State Waste Generator:	2		
Short Term Generator:	N		
Uni Waste:	Y		
Universal Waste Dest Facility:	Y		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	-----		
As Converter Tsdf:	-----		
As State Regulated Tsdf:	-----		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	-----		
Permwrk ID:	-----		
Perm Prog:	-----		
Pcwrkld:	-----		
Closwrkld:	-----		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Operating Tsd:		-----				
Full Enforcement:		-----				
Snc:		N				
Unaddressed Snc:		N				
Addressed Snc:		N				
Snc With Comp Sched:		N				
Fa Required:		-----				
Hhandler Last Change:		20190628				
Recognized Trader Importer:		N				
Recognized Trader Exporter:		N				
Slab Importer:		N				
Slab Exporter:		N				
Manifest Broker:		N				
Subpart P:		N				
Contact Language:		EN				
Handler Name:		HOUSE OF HYBRIDS				
Location Street No:						
Location Street1:		9825 GARDEN GROVE BLVD				
Location Street2:						
Location City:		GARDEN GROVE				
Location State:		CA				
Location Zip:		92844				
Location County Code:		CA059				
Location County Name:		ORANGE				
Location Country:		US				
Contact Name:		REMTO VASCONCELOS				
Contact Street No:						
Contact Street1:		2546 ORANGE AVE APT B				
Contact Street2:						
Contact City:		COSTA MESA				
Contact State:		CA				
Contact Zip:		92627				
Contact Country:						
Contact Phone And Ext:		949-254-5204				
Contact Fax:						
Contact Email Address:		HHYBRIDS@YAHOO.COM				
Contact Title:						
Owner Name:		REMTO VASCONCELOS				
Owner Type:		O				
Owner Seq:		1				
Operator Name:		REMTO VASCONCELOS				
Operator Type:		O				
Operator Seq:		2				
Public Notes:						

Contact DTSC for information.

Hazardous Waste Handler Details

Seq No: 1
 Receive Date: 20190327
 Handler Name: HOUSE OF HYBRIDS
 Fed Waste Generator: N
 Generator Code Description: Not a Generator, Verified
 Tsd Activity: Y
 Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	Street No:	
Type:	Other	Street1:	2546 ORANGE AVE APT B
Name:	REMTO VASCONCELOS	Street2:	
Dt Became Current:		City:	COSTA MESA
Dt Ended Current:		State:	CA
Phone:	949-254-5204	Country:	
Source Type:	Implementer	Zip:	92627

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
<hr/>						
Owner/Operator Ind:	Current Operator				Street No:	
Type:	Other				Street1:	2546 ORANGE AVE APT B
Name:	REMTO VASCONCELOS				Street2:	
Dt Became Current:					City:	COSTA MESA
Dt Ended Current:					State:	CA
Phone:	949-254-5204				Country:	
Source Type:	Implementer				Zip:	92627

41	1 of 1	NW	0.46 / 2,453.34	75.16 / 2	ORIENTAL LEASING 9672 GARDEN GROVE GARDEN GROVE CA 92641	LUST
--------------------	--------	----	--------------------	--------------	--	------

Global ID:	T0605900714	Case Type (DL):	LUST Cleanup Site
Site Facility Type:	LUST CLEANUP SITE	Oil Field (SRCH):	
Site Fac Type (SRCH):	LUST CLEANUP SITE	Oil Field Oper (SRCH):	
Status:		Census Tract (SRCH):	6059088702
Status (SRCH):	COMPLETED - CASE CLOSED	Latitude (DL):	33.773646
Status (DL):	Completed - Case Closed	Longitude (DL):	-117.96357
Status Date (DL):	8/7/2000	RWQCB Region (DL):	SANTA ANA RWQCB (REGION 8)
Cleanup Status:	COMPLETED - CASE CLOSED		
Site Facility Name (SRCH):	ORIENTAL LEASING		
Address (SRCH):	9672 GARDEN GROVE		
City (SRCH):	GARDEN GROVE		
Zip (SRCH):	92641		
County (SRCH):	ORANGE		
Street No (DL):	9672		
Street Name (DL):	GARDEN GROVE		
City (DL):	GARDEN GROVE		
Zip (DL):	92641		
County (DL):	Orange		
State (DL):	CA		
Business Name (DL):	ORIENTAL LEASING		
Site Facility Name:	ORIENTAL LEASING		
Address :	9672 GARDEN GROVE		
City :	GARDEN GROVE		
Zip :	92641		
County :	ORANGE		
Report Source:	LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search		

GeoTracker Sites Data Download - Site Details

CUF Case:	
Lead Agency:	ORANGE COUNTY LOP
Case Worker:	
Local Agency:	
RB Case No:	083000900T
Local Case No:	88UT083
File Location:	Local Agency
Potential COC:	Gasoline
Potential Media of Concern:	Other Groundwater (uses other than drinking water)
Begin Date:	4/15/1988
How Discovered:	Tank Closure
How Discovered Description:	
Stop Method:	Close and Remove Tank
Stop Description:	
Calwater Watershed Name:	Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name:	Coastal Plain Of Orange County (8-001)
Disadvantaged Community:	
CalEnvScreen Score:	
Coordinate Source:	Google Geocode
Discharge Cause:	
Discharge Source:	
EPA Region:	9
Leak Reported Dt:	1988-04-15 00:00:00
Military DoD Site:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
No Further Action Dt:		2000-08-07 00:00:00				
Qty Rlsd Gallons:		0				
Facility Project Sub Type:						
Calenviroscreen 3 Score:		51-55%				
Calenviroscreen 4 Score:		60-65%				
A2022 Assembly District:		70				
Claim No:						
Claim Status:						
A2022 Congressional District:		45				
A2022 Senate District:		36				
Site History:						

GeoTracker Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: JESSICA LAW
Organization Name: SANTA ANA RWQCB (REGION 8)
Address: 3737 Main Street, Suite 500
City: RIVERSIDE
Email: jessica.law@waterboards.ca.gov
Phone No: 9517824381

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 8/7/2000

Status: Open - Case Begin Date
Status Date: 4/15/1988

GeoTracker Search - Regulatory Profile

Site Facility Name: ORIENTAL LEASING
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 9672 GARDEN GROVE
City: GARDEN GROVE
Zip: 92641
County: ORANGE
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605900714
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 8/7/2000
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605900714&tabname=regulatoryhistory
Potential COC: GASOLINE
Potential Media of Concern: OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER)
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
DWR GW Sub Basin: Coastal Plain Of Orange County (8-001)
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: ORANGE COUNTY LOP (LEAD) - CASE #: 88UT083
 SANTA ANA RWQCB (REGION 8) - CASE #: 083000900T
 CASE MANAGER: JESSICA LAW
CUF Claim No:
CUF Priority Assig:
CUF Amount Paid:
WDR Place Type:
WDR File No:
WDR Order No:
Project Oversight Agencies:
Facility Type:
Composting Method:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Grndwtr Monitoring Frequency:
Designated Beneficial Use
Desc:
Site History:

Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.

No site history available

GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 8/7/2000

Status: Open - Case Begin Date
Date : 4/15/1988

GeoTracker Search - Regulatory Activities

Action Type: Leak Action
Action: Leak Discovery
Action Date: 4/15/1988
Received Issue Date:
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action: Leak Reported
Action Date: 4/15/1988
Received Issue Date:
Doc Link:
Title Description Comments:

42

1 of1

SSE

0.47 /
2,478.76

69.75 /
-4

4 DAY TIRE STORE

13961 BROOKHURST

GARDEN GROVE CA 92643

LUST

Global ID:

T0605901280

Site Facility Type:

LUST CLEANUP SITE

Site Fac Type (SRCH):

LUST CLEANUP SITE

Status:

COMPLETED - CASE CLOSED

Status (SRCH):

Completed - Case Closed

Status (DL):

9/14/1992

Status Date (DL):

COMPLETED - CASE CLOSED

Cleanup Status:

4 DAY TIRE STORE

Site Facility Name (SRCH):

13961 BROOKHURST

Address (SRCH):

GARDEN GROVE

City (SRCH):

92643

Zip (SRCH):

ORANGE

County (SRCH):

13961

Street No (DL):

BROOKHURST

Street Name (DL):

GARDEN GROVE

City (DL):

92643

Zip (DL):

Orange

County (DL):

CA

State (DL):

4 DAY TIRE STORE

Business Name (DL):

4 DAY TIRE STORE

Site Facility Name:

13961 BROOKHURST

Address :

GARDEN GROVE

City :

92643

Zip :

ORANGE

County :

LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download; LUST Cleanup Sites from GeoTracker Search

Report Source:

Case Type (DL):

LUST Cleanup Site

Oil Field (SRCH):

Oil Field Oper (SRCH):

Census Tract (SRCH):

6059088901

Latitude (DL):

33.7613062

Longitude (DL):

-117.9550853

RWQCB Region (DL):

SANTA ANA RWQCB (REGION 8)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

GeoTracker Sites Data Download - Site Details

CUF Case:
Lead Agency: ORANGE COUNTY LOP
Case Worker:
Local Agency:
RB Case No: 083001694T
Local Case No: 90UT255
File Location: Local Agency
Potential COC: Gasoline
Potential Media of Concern: Soil
Begin Date: 11/14/1990
How Discovered: Tank Closure
How Discovered Description:
Stop Method: Close and Remove Tank
Stop Description:
Calwater Watershed Name: Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)
DWR GW Subbasin Name: Coastal Plain Of Orange County (8-001)
Disadvantaged Community:
CalEnvScreen Score:
Coordinate Source: Google Geocode
Discharge Cause:
Discharge Source:
EPA Region: 9
Leak Reported Dt: 1990-11-14 00:00:00
Military DoD Site: No
No Further Action Dt: 1992-09-14 00:00:00
Qty Rlsl Gallons: 0
Facility Project Sub Type:
Calenviroscreen 3 Score: 56-60%
Calenviroscreen 4 Score: 55-60%
A2022 Assembly District: 70
Claim No: 1856
Claim Status: Active
A2022 Congressional District: 45
A2022 Senate District: 36
Site History:

GeoTracker Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 9/14/1992

Status: Open - Case Begin Date
Status Date: 11/14/1990

GeoTracker Search - Regulatory Profile

Site Facility Name: 4 DAY TIRE STORE
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Address: 13961 BROOKHURST
City: GARDEN GROVE
Zip: 92643
County: ORANGE
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0605901280
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 9/14/1992
Project Status:
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0605901280&tabname=regulatoryhistory
Potential COC: GASOLINE
Potential Media of Concern: SOIL
File Location: LOCAL AGENCY
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, 8 - Note: Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.
DWR GW Sub Basin: Coastal Plain Of Orange County (8-001)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Calwater Watershed Name:	Santa Ana River - Lower Santa Ana River - East Coastal Plain (801.11)					
Post Closure Site Management:						
Future Land Use:						
Cleanup Oversight Agencies:	ORANGE COUNTY LOP (LEAD) - CASE #: 90UT255 SANTA ANA RWQCB (REGION 8) - CASE #: 083001694T					
CUF Claim No:	1856					
CUF Priority Assig:	C					
CUF Amount Paid:	\$79,652					
WDR Place Type:						
WDR File No:						
WDR Order No:						
Project Oversight Agencies:						
Facility Type:						
Composting Method:						
Grndwtr Monitoring Frequency:						
Designated Beneficial Use	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, 8 - Note:					
Desc:	Also incl parts of 801.13, 801.14, 845.61 - Note: Also incl parts of 801.13, 801.14, 845.61, 845.63.					
Site History:						

No site history available

GeoTracker Search - Cleanup Status History

Status:	Completed - Case Closed
Date :	9/14/1992

Status:	Open - Case Begin Date
Date :	11/14/1990

GeoTracker Search - Cleanup Action Report

Action Type:	PERMEABLE REACTIVE BARRIER
Begin Date:	1/1/1965
End Date:	1/1/1965
Phase:	
Contaminant Mass Removed:	
Description:	

Action Type:	EXCAVATION
Begin Date:	1/1/1965
End Date:	1/1/1965
Phase:	
Contaminant Mass Removed:	
Description:	

GeoTracker Search - Regulatory Activities

Action Type:	Reports
Action:	Other Report
Action Date:	4/30/2022
Received Issue Date:	4/30/2022
Doc Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605901280&enforcement_id=6458307&temptable=ENFORCEMENT

Title Description Comments:

Historic Files **Note: Many records provided by the department have a truncated [Title Description Comments] field.

Action Type:	Leak Action
Action:	Leak Reported
Action Date:	11/14/1990
Received Issue Date:	
Doc Link:	
Title Description Comments:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	-------------------	-----------	------------------	----------------	------	----

Action Type: Leak Action
Action: Leak Discovery
Action Date: 11/14/1990
Received Issue Date:
Doc Link:
Title Description Comments:

GeoTracker Search - Documents

Document Type:	Site Documents	Document Date:	4/30/2022
Type:	OTHER REPORT	Submitted:	
Submitted By:	GENIECE HIGGINS (REGULATOR), KARL BEWLEY (REGULATOR)		
Title:	HISTORIC FILES **Note: Many records provided by the department have a truncated [Title] field.		
Title Link:	https://geotracker.waterboards.ca.gov/view_documents?global_id=T0605901280&enforcement_id=6458307		

43	1 of 2	NW	0.48 / 2,548.01	74.14 / 0	Oriental Leasing 9672 Garden Grove Blvd Garden Grove Ca 92844-1516 CA	LOP ORANGE
--------------------	--------	----	-----------------	-----------	--	------------

Case ID: 88UT083

Details

Current Status: Closed
Type of Closure: Closure certification issued
Closed Date: 8/7/2000
File Location: Local Agency

43	2 of 2	NW	0.48 / 2,548.01	74.14 / 0	Orental Leasing 9672 Garden Grove Blvd Garden Grove Ca 92844-1516 CA	LOP ORANGE
--------------------	--------	----	-----------------	-----------	---	------------

Case ID: 88UT077

Details

Current Status: Closed
Type of Closure: Invalidated
Closed Date: 1/1/1988
File Location: Local Agency

44	1 of 1	NE	0.68 / 3,589.02	84.87 / 11	VETERANS ED'S INC 10372 STANFORD AVENUE #S GARDEN GROVE CA 92840	INSP COMP ENF
--------------------	--------	----	-----------------	------------	---	------------------

EPA ID:	CAL000429855	County:	ORANGE
Geotracker Address:		Geotracker Lat:	
Geotracker City:		Geotracker Long:	
Report URL:	https://www.envirostor.dtsc.ca.gov/public/eeerp_profile_report?global_id=3004769		

Inspection Information

Inspection Type: Focused Compliance Inspection - Transporter
Violations: No Violations
Inspection Date: 5/18/2022
Return to Compliance:
Report Sent Date: 5/18/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
---------	----------------------	-----------	---------------------	-------------------	------	----

Site Details (Download)

Envirostor ID:	3004769	Status:	No Action
Site Type:	INSPECTION		

Unplottable Summary

Total: 4 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID
HHSS	PINEHURST	STAR ROUTE' (1.10 MI N OF C. RD	NONE CA	95814	822979342
HHSS	CASA DE ORO VERDE	CASA DE ORO VERDE	NONE CA	NONE	822942878
HHSS	STOCKDALE HWY SHELL	S-E. CORNER I-5 AT STOCKDALE H TRASK	NONE CA	93206	822951300
HMIRS		BROOKHURST AVENUE	GARDEN GROVE CA		818603713

Unplottable Report

Site: PINEHURST
STAR ROUTE' (1.10 MI N OF C. RD NONE CA 95814

HHSS

County: Sacramento
Tank Details Microfiche: <http://geotracker.waterboards.ca.gov/ustpdfs/pdf/00023a9f.pdf>

Site: CASA DE ORO VERDE
CASA DE ORO VERDE NONE CA NONE

HHSS

County:
Tank Details Microfiche: <http://geotracker.waterboards.ca.gov/ustpdfs/pdf/0002f209.pdf>

Site: STOCKDALE HWY SHELL
S-E. CORNER I-5 AT STOCKDALE H TRASK NONE CA 93206

HHSS

County:
Tank Details Microfiche: <http://geotracker.waterboards.ca.gov/ustpdfs/pdf/000250dd.pdf>

Site: BROOKHURST AVENUE GARDEN GROVE CA

HMIRS

Incident County: ORANGE

HMIR Historical Reports

Report No: I-1994020201
Report Type: A hazardous material incident
Date of Incident: 1994-01-07
Time of Incident: 1315
Haz Class Code:
Hazardous Class: 3
Commodity Short Nm: GASOLINE INCLUDES GASOLI
Commodity Long Nm: GASOLINE INCLUDES GASOLINE MIXED
WITH ETHYL ALCOHOL, WITH NOT MORE
THAN 10% ALCOHOL

Trade Name: ARCO UNLEADED GASOLI
ID No: UN1203
Haz Waste Ind: No
Haz Waste EPA No:
HMIS Tox Inhalation?: No
TIH Hazard Zone:
Qty Released: 1
Unit of Measure: Liquid - Gallon

What Failed:
What Failed Desc:
How Failed Code:
How Failed Desc:
Failure Cause Code:
Failure Cause Desc:
Ident. Markings:
Cont1 Pkging Type:
Cont1 Const Mat:
Cont1 Head Type:
Cont1 Pkg Capacity: 8900
C1 Capacity UOM: LGA

Fed DOT Agency Nm:
Fed DOT Report No:
Report Submit Src: Paper
Inc Multiple Rows: No
Inc Non US State:
Mode Transport: Highway
Transport Phase: Unloading
Incident Occrrnce:

Mat Ship Approval?: No
Mat Ship Approv No:
Undecl Hazmat Ship?: No
Packaging Type: Cargo Tank Motor Vehicle (CTMV)
Packing Group:
Carrier Reporter: ARCO PRODUCTS COMPANY
CR Street Name: 1055 WEST 7TH STREET
CR City: LOS ANGELES
CR State: CA
CR Postal Code: 90017
CR Non US State:
CR Fed DOT ID: 0
CR Hazmat Reg ID:
CR Country: US
Shipper Name: ARCO PRODUCTS COMPANY
Shipper Street Name: 1055 W SEVENTH ATREET
Shipper City: LOS ANGELES
Shipper State: CA
Shipper Postal: 90017
Shipper Non US St:

Cont1 Pkg Amt: 0
 C1 Pkg Amt UOM:
 Cont1 Pkg No: 1
 C1 Pkg NO Failed: 1
 Cont1 Pkg Mnfctr: WELD-IT INC
 Cont1 Pkg MnfcDt: 0-00-00 00:00:00
 Cont1 Pkg Serial NO: 4N61418
 C1 Pkg Last Test Dt: 1993-07-01 00:00:00
 C1 Test Const Mat:
 C1 Pkg Dsign Pres.: 0
 C1 Dsign Press UOM:
 C1 Pkg Shell Thick: 0
 C1 Shell Thick UOM:
 C1 Head Thickness: 0
 C1 Head Thick UOM:
 C1 Pkg Srvc Pres.: 0
 C1 Srvc Press UOM:
 C1 Valve/Device Fail?: No
 C1 Device Type:
 C1 Device Mnfctr:
 C1 Device Model:
 NRC No:

RAM Pkg Category:
 RAM Pkg Cert.: FALSE
 RAM Pkg Cert. NBR:
 RAM Nuclide S:
 RAM Transport Index:
 RAM UOM:
 RAM Activity Rpted: 0
 RAM UOM Rpted:
 RAM Activity: 0
 RAM Activity UOM:
 RAM Mat Safety:
 Spillage Result: Yes
 Fire Result: No
 Explosion Result: No
 Water Sewer Result: No
 Gas Dispersion: No
 Environment Damage: No
 No Release Result: No
 Fire EMS Report: No
 Fire EMS EMS Report:
 Police Report: No
 Police Report No:
 In House Cleanup: No
 Other Cleanup: No
 Damage > 500: No
 Material Loss: 1
 Carrier Damage: 0
 Property Damage: 0
 Response Cost: 0
 Remediation Cost: 4
 Damage Old Form: 0
 Total Damages Amt: 5
 Hazmat Fatality: No
 Haz Fatal Employees: 0
 Haz Fatal Respntrs: 0
 Haz Fatal Gen Public: 0
 Tot Hazmat Fatalities: 0
 Non Hazmat Fatality: No
 Non Hazmat FataIs: 0
 Hazmat Injury: No
 Haz Hospital Empl: 0
 Haz Hospital Resp: 0
 Haz Hosp Gen Public: 0
 Haz Hosp Old Form: 0
 Total Haz Hosp Inj: 0
 Haz Non Hosp Empl: 0
 Haz Non Hosp Resp: 0
 Description of Events:

Shipper Country: US
 Shipper Waybill: 593203
 Ship Hazmat Reg ID:
 Origin City: SOUTH GATE
 Origin State: CA
 Origin Postal: 90280
 Origin Non US St:
 Origin Country: US
 Destination City: GARDEN GROVE
 Destination State: CALIFORNIA
 Destination Postal:
 Destination Non US:
 Destination Country: US
 Cont2 Package Type:
 Cont2 Const Mat:
 Cont2 Pkg Capacity: 0
 Cont2 Capacity UOM:
 Cont2 Pkg Amount: 0
 Cont2 Pkg Amt UOM:
 Cont2 Pkg No: 0
 Cont2 Pkg No Failed: 0

Haz NonHosp Public: 0
 Haz NonHosp Old:
 Tot Haz Non Hosp Inj:
 Total Hazmat Injuries: 0
 Evacuation Indicator: No
 Public Evacuated: 0
 Employees Evac: 0
 Total Evacuated: 0
 Total Evacuation Hrs: 0
 Major Artery Closed: No
 Mjr Artery Hrs Closed: 0
 Material Involved: No
 Estimated Speed: 0
 Weather Conditions:
 Vehicle Overturn: No
 Vehicle Left Roadway: No
 Passenger Aircraft: No
 Cargo Baggage:
 Ship Non Transport: No
 Ship Air First Flight: No
 Ship Air Subflight: No
 Ship Init Transport: No
 Ship Phase Transfer: No
 Contact Name: B.W. SPENCER
 Contact Title: MANAGER E H & S
 Contact Business:
 Contact Street:
 Contact City:
 Contact State:
 Contact Postal:
 Contact Non US St:
 Contact Country: US
 Inc. Report Prepared:
 HMIS Serious Incidnt: No
 HMIS Serious Fatality: No
 HMIS Serious Injury: No
 HMIS Flight Plan: No
 HMIS Serious Evacs: No
 HMIS Major Artery: No
 HMIS Bulk Release: No
 HMIS Marine Pollutnt: No
 HMIS Radioactive: No
 HMIS Gen Pkg Type: TANK
 HMIS Container Code: MC306
 HMIS Container Desc: Cargo tanks
 HMIS Bulk Incident: Yes
 Undeclared Shipment: No

WHILE DELIVERING TO COMPANY STATION, THE VAPOR RECOVERY HOSE FILLED WITH PRODUCT.

WHEN THE DRIVER DISCONNECTED THE HOSE FROM THE FITTING, 1 GALLON OF PRODUCT WAS RELEASED ONTO THE CONCRETE PAD. THE RELEASE WAS CLEANED UP BY THE DRIVER. THE CLEAN-UP MATERIAL WAS RETURNED TO THE TERMINAL FOR PROPER DISPOSAL.

Recommend Actions Taken:

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

National Priority List:

NPL

The U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL) includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program, based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. This data includes NPL sites represented as polygons, where available, that can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. As site investigation and remediation progress, OUs may be added, modified or refined. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 8, 2025

National Priority List - Proposed:

PROPOSED NPL

Sites proposed by the U.S. Environmental Protection Agency (EPA), the state agency, or concerned citizens for addition to the National Priorities List (NPL) due to contamination by hazardous waste and identified by the EPA as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 8, 2025

Deleted NPL:

DELETED NPL

Sites deleted from the U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL). The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425(e), sites may be deleted from the NPL where no further response is appropriate. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Mar 8, 2025

SEMS List 8R Active Site Inventory:[SEMS](#)

The U.S. Environmental Protection Agency's (EPA) Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. This data includes SEMS sites from the List 8R Active file as well as applicable sites from the EPA's Facility Registry Service map tool.

Government Publication Date: Feb 26, 2025

SEMS List 8R Archive Sites:[SEMS ARCHIVE](#)

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. This data includes sites from the List 8R Archived site file.

Government Publication Date: Feb 26, 2025

Inventory of Open Dumps, June 1985:[ODI](#)

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

EPA Report on the Status of Open Dumps on Indian Lands:[IODI](#)

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

Comprehensive Environmental Response, Compensation and Liability Information System -[CERCLIS](#)**CERCLIS:**

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

CERCLIS - No Further Remedial Action Planned:[CERCLIS NFRAP](#)

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens:[CERCLIS LIENS](#)

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action:[RCRA CORRACTS](#)

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Jan 6, 2025

RCRA non-CORRACTS TSD Facilities:[RCRA TSD](#)

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites that have indicated engagement in the treatment, storage, or disposal of hazardous waste which requires a RCRA hazardous waste permit.

Government Publication Date: Jan 6, 2025

RCRA Generator List:[RCRA LQG](#)

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Jan 6, 2025

RCRA Small Quantity Generators List:[RCRA SQG](#)

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Jan 6, 2025

RCRA Very Small Quantity Generators List:[RCRA VSQG](#)

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Jan 6, 2025

RCRA Non-Generators:[RCRA NON GEN](#)

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Jan 6, 2025

RCRA Sites with Controls:[RCRA CONTROLS](#)

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Jan 6, 2025

Federal Engineering Controls-ECs:[FED ENG](#)

List of Engineering controls (ECs) made available by the United States Environmental Protection Agency (EPA). ECs encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. The EC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Mar 27, 2025

Federal Institutional Controls- ICs:

FED INST

List of Institutional controls (ICs) made available by the United States Environmental Protection Agency (EPA). ICs are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site. The IC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Mar 27, 2025

Land Use Control Information System:

LUCIS

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Institutional Control Boundaries at NPL sites:

NPL IC

These boundaries of Institutional Control areas at sites on the U.S. Environmental Protection Agency's (EPA) National Priorities List (NPL), or as Proposed or Deleted, are sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). The EPA's NPL includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes.

Government Publication Date: Mar 8, 2025

Emergency Response Notification System:

ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System:

ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System:

ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Apr 6, 2025

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database:

FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This data is provided by the United States Environmental Protection Agency (EPA) and includes Brownfield sites from the Cleanups in My Community (CIMC) web application.

Government Publication Date: Feb 19, 2025

FEMA Underground Storage Tank Listing:

FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan:

FRP

This listing contains facilities that have submitted Facility Response Plans (FRPs) to the U.S. Environmental Protection Agency (EPA). Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit FRPs. Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments. This listing includes FRP facilities from an applicable EPA FOIA file and Homeland Infrastructure Foundation-Level Data (HIFLD) data file.

Government Publication Date: Jan 9, 2024

Delisted Facility Response Plans:

DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Jan 9, 2024

Historical Gas Stations:

HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries:

REFN

This list of petroleum refineries is sourced from the U.S. Energy Information Administration (EIA), Refinery Capacity Report. The listing includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year. The geographic area the report covers is the 50 States, the District of Columbia, Puerto Rico, the U.S. Virgin Islands, Guam, and other U.S. possessions. Per the EIA, the facility location data represents the approximate location based on research of publicly available information from sources such as Federal agencies, company websites, and satellite images on public websites.

Government Publication Date: Oct 31, 2024

Petroleum Product and Crude Oil Rail Terminals:

BULK TERMINAL

A list of petroleum product and crude oil rail terminals from the U.S. Energy Information Administration (EIA), as well as petroleum terminals sourced from Oak Ridge National Laboratory hosted by the Homeland Infrastructure Foundation-Level Database. Data includes operable bulk petroleum product terminals with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil with activity between 2017 and 2018. EIA petroleum product terminal data comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings.

Government Publication Date: Oct 31, 2024

Lien on Property:

SEMS LIEN

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) provides Lien details on applicable properties, such as the Superfund lien on property activity, the lien property information, and the parties associated with the lien.

Government Publication Date: Jan 29, 2025

Superfund Decision Documents:

SUPERFUND ROD

This database contains a list of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include completed Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD) for active and archived sites stored in the Superfund Enterprise Management System (SEMS), along with other associated memos and files. This information is maintained and made available by the U.S. Environmental Protection Agency.

Government Publication Date: Feb 26, 2025

State**State Response Sites:**

RESPONSE

A list of identified confirmed release sites where the Department of Toxic Substances Control (DTSC) is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk. This database serves a purpose similar to that of the federal NPL, functioning as a state-level counterpart for prioritizing cleanup efforts at hazardous substance release sites.

Government Publication Date: Jun 1, 2025

EnviroStor Database:[ENVIROSTOR](#)

The EnviroStor Data Management System is made available by the Department of Toxic Substances Control (DTSC). Includes Corrective Action sites, Tiered Permit sites, Historical Sites and Evaluation/Investigation sites. This database serves a purpose similar to that of the federal Superfund Enterprise Management System (SEMS), functioning as a state-level counterpart for tracking potential hazardous substance release sites.

Government Publication Date: Jun 1, 2025

Delisted State Response Sites:[DELISTED ENVS](#)

Sites removed from the list of State Response Sites made available by the EnviroStor Data Management System, Department of Toxic Substances Control (DTSC).

Government Publication Date: Jun 1, 2025

Solid Waste Information System (SWIS):[SWF/LF](#)

The Solid Waste Information System (SWIS) database made available by the Department of Resources Recycling and Recovery (CalRecycle) contains information on solid waste facilities, operations, and disposal sites throughout the State of California. The types of facilities found in this database include landfills, transfer stations, material recovery facilities, composting sites, transformation facilities, waste tire sites, and closed disposal sites.

Government Publication Date: Apr 7, 2025

Solid Waste Disposal Sites with Waste Constituents Above Hazardous Waste Levels:[SWRCB SWF](#)

This is a list of solid waste disposal sites identified by California State Water Resources Control Board with waste constituents above hazardous waste levels outside the waste management unit.

Government Publication Date: Sep 20, 2006

Waste Management Unit Database:[WMUD](#)

The Waste Management Unit Database System tracks and inventories waste management units. CCR Title 27 contains criteria stating that Waste Management Units are classified according to their ability to contain wastes. Containment shall be determined by geology, hydrology, topography, climatology, and other factors relating to the ability of the Unit to protect water quality. Water Code Section 13273.1 requires that operators submit a water quality solid waste assessment test (SWAT) report to address leak status. The WMUDS was last updated by the State Water Resources control board in 2000.

Government Publication Date: Jan 1, 2000

EnviroStor Hazardous Waste Facilities:[HWP](#)

A list of hazardous waste facilities including permitted, post-closure and historical facilities found in the Department of Toxic Substances Control (DTSC) EnviroStor database.

Government Publication Date: Jun 1, 2025

Sites Listed in the Solid Waste Assessment Test (SWAT) Program Report:[SWAT](#)

In a 1993 Memorandum of Understanding, the State Water Resources Control Board (SWRCB) agreed to submit a comprehensive report on the Solid Waste Assessment Test (SWAT) Program to the California Integrated Waste Management Board (CIWMB). This report summarizes the work completed to date on the SWAT Program, and addresses both the impacts that leakage from solid waste disposal sites (SWDS) may have upon waters of the State and the actions taken to address such leakage.

Government Publication Date: Dec 31, 1995

Construction and Demolition Debris Recyclers:[C&D DEBRIS RECY](#)

This listing of Construction and Demolition Debris Recyclers is maintained by the California Intergrated Waste Management Board-common C&D materials include lumber, drywall, metals, masonry (brick, concrete, etc.), carpet, plastic, pipe, rocks, dirt, paper, cardboard, or green waste related to land development.

Government Publication Date: Jun 20, 2018

Recycling Centers:[RECYCLING](#)

This list of Certified Recycling Centers that are operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Mar 5, 2025

Listing of Certified Processors:[PROCESSORS](#)

This list of Certified Processors that are operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: May 31, 2025

Listing of Certified Dropoff, Collection, and Community Service Programs:

CONTAINER RECY

This list of Certified Dropoff, Collection, and Community Service Programs (non-buyback) operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: May 22, 2025

Land Disposal Sites:

LDS

Land Disposal Sites in GeoTracker, the State Water Resources Control Board (SWRCB)'s data management system. The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units. Waste management units include waste piles, surface impoundments, and landfills.

Government Publication Date: Apr 4, 2025

Leaking Underground Fuel Tank Reports:

LUST

List of Leaking Underground Storage Tanks within the Cleanup Sites data in GeoTracker database. GeoTracker is the State Water Resources Control Board's (SWRCB) data management system for managing sites that impact groundwater, especially those that require groundwater cleanup (Underground Storage Tanks, Department of Defense and Site Cleanup Program) as well as permitted facilities such as operating Underground Storage Tanks. The Leak Prevention Program that overlooks LUST sites is the SWRCB in California's Environmental Protection Agency.

Government Publication Date: Apr 4, 2025

Delisted Leaking Storage Tanks:

DELISTED LST

List of Leaking Underground Storage Tanks (LUST) cleanup sites removed from GeoTracker, the State Water Resources Control Board (SWRCB)'s database system, as well as sites removed from the SWRCB's list of UST Case closures.

Government Publication Date: May 27, 2025

Permitted Underground Storage Tank (UST) in GeoTracker:

UST

List of Permitted Underground Storage Tank (UST) sites made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA).

Government Publication Date: May 25, 2025

Proposed Closure of Underground Storage Tank Cases:

UST CLOSURE

This listing includes Proposed Closure of Underground Storage Tank (UST) Cases which are being considered for closure by either the State Water Resources Control Board at a Future Board Meeting or the Executive Director that have been posted for a 60-day public comment period, and Closure of UST Cases with Closure Denials and Approved Orders. The lists are provided by the California Water Boards.

Government Publication Date: Apr 7, 2025

Historical Hazardous Substance Storage Information Database:

HHSS

The Historical Hazardous Substance Storage database contains information collected in the 1980s from facilities that stored hazardous substances. The information was originally collected on paper forms, was later transferred to microfiche, and recently indexed as a searchable database. When using this database, please be aware that it is based upon self-reported information submitted by facilities which has not been independently verified. It is unlikely that every facility responded to the survey and the database should not be expected to be a complete inventory of all facilities that were operating at that time. This database is maintained by the California State Water Resources Control Board's (SWRCB) Geotracker.

Government Publication Date: Aug 27, 2015

Statewide Environmental Evaluation and Planning System:

UST SWEEPS

The Statewide Environmental Evaluation and Planning System (SWEEPS) is a historical listing of active and inactive underground storage tanks made available by the California State Water Resources Control Board (SWRCB).

Government Publication Date: Oct 1, 1994

Aboveground Storage Tanks:

AST

A statewide list from 2009 of aboveground storage tanks (ASTs) made available by the Cal FIRE Office of the State Fire Marshal (OSFM). This list is no longer maintained or updated by the Cal FIRE OSFM.

Government Publication Date: Aug 31, 2009

SWRCB Historical Aboveground Storage Tanks:

AST SWRCB

A list of aboveground storage tanks made available by the California State Water Resources Control Board (SWRCB). Effective January 1, 2008, the Certified Unified Program Agencies (CUPAs) are vested with the responsibility and authority to implement the Aboveground Petroleum Storage Act (APSA).

Government Publication Date: Dec 1, 2007

Oil and Gas Facility Tanks:

TANK OIL GAS

Locations of oil and gas tanks that fall under the jurisdiction of the Geologic Energy Management Division of the California Department of Conservation (CalGEM) (CCR 1760). CalGEM was formerly the Division of Oil, Gas, and Geothermal Resources (DOGGR).

Government Publication Date: Feb 20, 2025

Delisted Storage Tanks:

DELISTED TNK

This database contains a list of storage tank sites that were removed by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA) and the Cal FIRE Office of State Fire Marshal (OSFM).

Government Publication Date: Jun 1, 2025

California Environmental Reporting System (CERS) Tanks:

CERS TANK

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: May 28, 2025

Delisted California Environmental Reporting System (CERS) Tanks:

DELISTED CTNK

This database contains a list of Aboveground Petroleum Storage and Underground Storage Tank sites that were removed from in the California Environmental Protection Agency (CalEPA) Regulated Site Portal.

Government Publication Date: May 28, 2025

Historical Hazardous Substance Storage Container Information - Facility Summary:

HIST TANK

The State Water Resources Control Board maintained the Hazardous Substance Storage Containers listing and inventory in the 1980s. This facility summary lists historic tank sites where the following container types were present: farm motor vehicle fuel tanks; waste tanks; sumps; pits, ponds, lagoons, and others; and all other product tanks. This set, published in May 1988, lists facility and owner information, as well as the number of containers. This data is historic and will not be updated.

Government Publication Date: May 27, 1988

Site Mitigation and Brownfields Reuse Program Facility Sites with Land Use Restrictions:

LUR

The Department of Toxic Substances Control (DTSC) Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents land use restrictions that are active. Some sites have multiple land use restrictions.

Government Publication Date: Jun 1, 2025

CALSITES Database:

CALSITES

This historical database was maintained by the Department of Toxic Substance Control (DTSC) for more than a decade. CALSITES contains information on Brownfield properties with confirmed or potential hazardous contamination. In 2006, DTSC introduced EnviroStor as the latest Brownfields site database.

Government Publication Date: May 1, 2004

Hazardous Waste Management Program Facility Sites with Deed / Land Use Restrictions:

HLUR

The Department of Toxic Substances Control (DTSC) Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Government Publication Date: Feb 18, 2021

Deed Restrictions and Land Use Restrictions:

DEED

List of Deed Restrictions, Land Use Restrictions and Covenants in GeoTracker made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency. A deed restriction (land use covenant) may be required to facilitate the remediation of past environmental contamination and to protect human health and the environment by reducing the risk of exposure to residual hazardous materials.

Government Publication Date: May 27, 2025

Voluntary Cleanup Program:

VCP

List of sites in the Voluntary Cleanup Program made available by the Department of Toxic Substances and Control (DTSC). The Voluntary Cleanup Program was designed to respond to lower priority sites. Under the Voluntary Cleanup Program, DTSC enters site-specific agreements with project proponents for DTSC oversight of site assessment, investigation, and/or removal or remediation activities, and the project proponents agree to pay DTSC's reasonable costs for those services.

GeoTracker Cleanup Program Sites:

[CLEANUP SITES](#)

A list of Cleanup Program sites in the state of California made available by The State Water Resources Control Board (SWRCB) of the California Environmental Protection Agency (EPA). SWRCB tracks leaking underground storage tank cleanups as well as other water board cleanups.

Government Publication Date: Apr 4, 2025

Delisted Cleanup Program Sites:

[DELISTED CLEANUP](#)

A list of Cleanup Program sites which were once included - and have since been removed from - the list of Cleanup Program Sites in GeoTracker. GeoTracker is the State Water Resource Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater.

Government Publication Date: May 27, 2025

Delisted County Records:

[DELISTED COUNTY](#)

Records removed from county or CUPA databases. Records may be removed from the county lists made available by the respective county departments because they are inactive, or because they have been deemed to be below reportable thresholds.

Government Publication Date: May 15, 2025

Tribal

Leaking Underground Storage Tanks on Tribal/Indian Lands:

[INDIAN LUST](#)

This list of leaking underground storage tanks (LUSTs) on Tribal/Indian Lands in Region 9, which includes California, is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Oct 15, 2024

Underground Storage Tanks on Tribal/Indian Lands:

[INDIAN UST](#)

This list of underground storage tanks (USTs) on Tribal/Indian Lands in Region 9, which includes California, is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Oct 15, 2024

Delisted Tribal Leaking Storage Tanks:

[DELISTED INDIAN LST](#)

Leaking Underground Storage Tank (LUST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian LUST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Nov 18, 2024

Delisted Tribal Underground Storage Tanks:

[DELISTED INDIAN UST](#)

Underground Storage Tank (UST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian UST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Nov 18, 2024

County

Orange County - Industrial Cleanup Program Cases Listing:

[ICP ORANGE](#)

Orange County Health Care Agency's Environmental Health Division has an Industrial Cleanup (IC) program which oversees the voluntary cleanup of contaminated property. This is a list of cases (by city) which the IC program has overseen in the past, or is currently overseeing.

Government Publication Date: May 15, 2023

Orange County - LOP Lead Cases List:

[LOP ORANGE](#)

The Local Oversight Program of the County of Orange provides regulatory cleanup oversight for cleanup of leaking underground storage tanks (USTs). This dataset is provided by the Orange County Health Care Agency.

Government Publication Date: May 15, 2023

Orange County - Non-Petroleum Underground Storage Tank Cases:

[NPOT ORANGE](#)

This list of open and closed non-petroleum underground storage tank cases is maintained by the Orange County Health Care Agency.

Government Publication Date: Sep 13, 2024

Orange County - Underground Storage Tanks Listing:[UST ORANGE](#)

A list of registered Underground Storage Tank (UST) sites in Orange County. This list is made available by Orange County Health Care Agency (OCHCA), Environmental Health Division which oversees the underground storage tank inspection program in most of the cities of Orange County, with the exception of Anaheim, Fullerton, and Orange.

Government Publication Date: May 15, 2023

Orange County - Aboveground Petroleum Storage Tank Listing:[AST ORANGE](#)

A list of Aboveground Petroleum Storage Tank (APST) facilities inspected by Orange County Certified Unified Program Agency (CUPA) Under the Aboveground Petroleum Storage Act (APSA). This list is made available by the Environmental Health Division of Orange County Health Care Agency.

Government Publication Date: May 15, 2023

Orange County - Anaheim City UST Cleanup Cases:[UST CLP ANAHEIM](#)

A list of UST Cleanup Cases in the City of Anaheim in Orange County. As part of its Groundwater Protection Program, the City of Anaheim managed the UST Cleanup Oversight Program from April 1991 to June 2014. This list is published by the City of Anaheim Underground Storage Tank Cleanup Program.

Government Publication Date: May 26, 2015

Orange County - Anaheim City UST List:[UST ANAHEIM](#)

A list of Underground Storage Tanks in Anaheim City, Orange County. This list is made available by Anaheim Fire & Rescue Department.

Government Publication Date: Oct 9, 2024

Orange County - Anaheim City AST List:[AST ANAHEIM](#)

List of Aboveground Storage Tanks (ASTs) in Anaheim City, Orange County made available by Anaheim Fire & Rescue.

Government Publication Date: Oct 9, 2024

Additional Environmental Record Sources**Federal****On-Scene Coordinator Response Sites:**[OSC RESPONSE](#)

This list of On-Scene Coordinator (OSC) Response Sites is provided by the U.S. Environmental Protection Agency (EPA). OSCs are the federal officials responsible for monitoring or directing responses to all oil spills and hazardous substance releases reported to the federal government. OSCs coordinate all federal efforts with, and provide support and information to local, state, and regional response communities. An OSC is an agent of either EPA or the U.S. Coast Guard (USCG), depending on where the incident occurs. EPA's OSCs have primary responsibility for spills and releases to inland areas and waters. USCG OSCs have responsibility for coastal waters and the Great Lakes. In general, an OSC has the following key responsibilities during and after a response: Assessment, Monitoring, Response Assistance, and Evaluation.

Government Publication Date: Apr 4, 2024

PFAS Greenhouse Gas Emissions Data:[PFAS GHG](#)

The U.S. Environmental Protection Agency's Greenhouse Gas Reporting Program (GHGRP) collects Greenhouse Gas (GHG) data from large emitting facilities (25,000 metric tons of carbon dioxide equivalent (CO₂e) per year), and suppliers of fossil fuels and industrial gases that results in GHG emissions when used. Includes GHG emissions data for facilities that emit or have emitted since 2010 chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures in DSSTox. PFAS emissions data has been identified for facilities engaged in the following industrial processes: Aluminum Production (GHGRP Subpart F), HCFC-22 Production and HFC-23 Destruction (Subpart O), Electronics Manufacturing (Subpart I), Fluorinated Gas Production (Subpart L), Magnesium Production (Subpart T), Electrical Transmission and Distribution Equipment Use (Subpart DD), and Manufacture of Electric Transmission and Distribution Equipment (Subpart SS). Over time, other industrial processes with required GHGRP reporting may include PFAS emissions data and the list of reportable gases may change over time. Note that some regulatory programs have specified chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard.

Government Publication Date: May 9, 2025

Facility Registry Service/Facility Index:[FINDS/FRS](#)

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Apr 23, 2025

Toxics Release Inventory (TRI) Program:

TRIS

The U.S. Environmental Protection Agency's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of toxic chemicals from U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. There are currently 770 individually listed chemicals and 33 chemical categories covered by the TRI Program. Facilities that manufacture, process or otherwise use these chemicals in amounts above established levels must submit annual reporting forms for each chemical. Note that the TRI chemical list does not include all toxic chemicals used in the U.S. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment. This database includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFOA/PFOS Contaminated Sites:

PFAS NPL

This list of Superfund Sites with Per- and Polyfluoroalkyl Substances (PFAS) detections is made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data, previously the list was obtained by EPA FOIA requests. EPA's Office of Land and Emergency Management and EPA Regional Offices maintain what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment. Limitations: Detections of PFAS at National Priorities List (NPL) sites do not mean that people are at risk from PFAS, are exposed to PFAS, or that the site is the source of the PFAS. The information in the Superfund NPL and Superfund Alternative Agreement (SAA) PFAS detection site list is years old and may not be accurate today. Site information such as site name, site ID, and location has been confirmed for accuracy; however, PFAS-related information such as media sampled, drinking water being above the health advisory, or mitigation efforts has not been verified. For Federal Facilities data, the other Federal agencies (OFA) are the lead agency for their data and provided them to EPA.

Government Publication Date: Mar 31, 2025

Federal Agency Locations with Known or Suspected PFAS Detections:

PFAS FED SITES

This list of federal agency locations with known or suspected detections of Per- and Polyfluoroalkyl Substances (PFAS) is made available by the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools data. The EPA outlines that these data are gathered from several federal entities, such as the federal Superfund program, Department of Defense (DOD), National Aeronautics and Space Administration (NASA), Department of Transportation (DOT), and Department of Energy (DOE). The dates this data was extracted for the PFAS Analytic Tools range from 2022 to 2024. Sites on this list do not necessarily reflect the source/s of PFAS contamination and detections do not indicate level of risk or human exposure at the site. Agricultural notifications in this data are limited to DOD sites only. At this time, the EPA is aware that this list is not comprehensive of all Federal agencies.

Government Publication Date: Oct 24, 2024

SSEHRI PFAS Contamination Sites:

PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the PFAS Project Lab, part of the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents. Locations for the Known PFAS Contamination Sites are sourced from the PFAS Sites and Community Resources Map by the PFAS-REACH team, credited to PFAS Project Lab, Silent Spring Institute, and PFAS Exchange. Disclaimer: The source conveys the data undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Access the following source link for the most current information: <https://pfasproject.com/pfas-sites-and-community-resources/>

Government Publication Date: Jun 27, 2024

National Response Center PFAS Spills:

PFAS ERNS

This Per- and Poly-Fluoroalkyl Substances (PFAS) Spills dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The National Response Center (NRC), operated by the U.S. Coast Guard, is the designated federal point of contact for reporting all oil, chemical, and other discharges into the environment, for the United States and its territories. This dataset contains NRC spill information from 1990 to the present that is restricted to records associated with PFAS and PFAS-containing materials. Incidents are filtered to include only records with a "Material Involved" or "Incident Description" related to Aqueous Film Forming Foam (AFFF). The keywords used to filter the data included "AFFF," "Fire Fighting Foam," "Aqueous Film Forming Foam," "Fire Suppressant Foam," "PFAS," "PERFL," "PFOA," "PFOS," and "Genx." Limitations: The data from the NRC website contains initial incident data that has not been validated or investigated by a federal/state response agency. Keyword searches may misidentify some incident reports that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS spills/release incidents.

PFAS NPDES Discharge Monitoring:

[PFAS NPDES](#)

This list of National Pollutant Discharge Elimination System (NPDES) permitted facilities with required monitoring for Per- and Polyfluoroalkyl (PFAS) Substances is made available via the U.S. Environmental Protection Agency (EPA)'s PFAS Analytic Tools. Any point-source wastewater discharger to waters of the United States must have a NPDES permit, which defines a set of parameters for pollutants and monitoring to ensure that the discharge does not degrade water quality or impair human health. This list includes NPDES permitted facilities associated with permits that monitor for Per- and Polyfluoroalkyl Substances (PFAS), limited to the years 2007 - present. EPA further advises the following regarding these data: currently, fewer than half of states have required PFAS monitoring for at least one of their permittees, and fewer states have established PFAS effluent limits for permittees. For states that may have required monitoring, some reporting and data transfer issues may exist on a state-by-state basis.

Government Publication Date: Dec 16, 2024

Perfluorinated Alkyl Substances (PFAS) from Toxic Release Inventory:

[PFAS TRI](#)

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a per- or polyfluoroalkyl (PFAS) substance included in the U.S. Environmental Protection Agency's (EPA) consolidated PFAS Master List of PFAS Substances. Encompasses Toxics Release Inventory records included in the EPA PFAS Analytic Tools. The EPA's TRI database currently tracks information on disposal or releases of 770 individually listed toxic chemicals and 33 chemical categories from thousands of U.S. facilities and details about how facilities manage those chemicals through recycling, energy recovery, and treatment. This listing includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFAS Water Quality Portal Sampling Data:

[PFAS WATER](#)

This Per- and Poly-Fluoroalkyl Substances (PFAS) Environmental Media Sampling Data is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The Water Quality Portal (WQP), as a cooperative service sponsored by the United States Geological Survey, the EPA, and the National Water Quality Monitoring Council, is part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations, and individuals submit project details and sampling results to this public repository. Limitations: EPA did not carry out the sampling or testing of a majority of the data in the WQP PFAS dataset. EPA can only speak to the accuracy and completeness of the data from projects like the National Aquatic Resource Surveys for which EPA is the data owner/organization. Data may exist within the file on Quality Assurance Project Plans (QAPPs) and the approving agency of the QAPP, if a QAPP is entered.

Government Publication Date: Jan 13, 2025

PFAS TSCA Manufacture and Import Facilities:

[PFAS TSCA](#)

The U.S. Environmental Protection Agency (EPA) issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. This list is specific only to TSCA Manufacture and Import Facilities with reported per- and poly-fluoroalkyl (PFAS) substances. Data file is sourced from EPA's PFAS Analytic Tools TSCA dataset which includes CDR/Inventory Update Reporting data from 1998 up to 2020. Disclaimer: This data file includes production and importation data for chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures in DSSTox. Note that some regulations have specific chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard. Reporting information on manufactured or imported chemical substance amounts should not be compared between facilities, as some companies claim Chemical Data Reporting Rule data fields for PFAS information as Confidential Business Information.

Government Publication Date: Jan 5, 2023

PFAS Waste Transfers from RCRA e-Manifest :

[PFAS E-MANIFEST](#)

This Per- and Poly-Fluoroalkyl Substances (PFAS) Waste Transfers dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. Every shipment of hazardous waste in the U.S. must be accompanied by a shipment manifest, which is a critical component of the cradle-to-grave tracking of wastes mandated by the Resource Conservation and Recovery Act (RCRA). According to the EPA, currently no Federal Waste Code exists for any PFAS compounds. To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: • PFAS • PFOA • PFOS • PERFL • AFFF • GENX • GEN-X (plus the Vermont state-specific waste codes). Limitations: Amount or concentration of PFAS being transferred cannot be determined from the manifest information. Keyword searches may misidentify some manifest records that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS waste transfers.

Government Publication Date: Mar 23, 2025

PFAS Industry Sectors:

[PFAS IND](#)

This Per- and Poly-Fluoroalkyl Substances (PFAS) Industry Sectors dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The EPA developed the dataset from various sources that show which industries may be handling PFAS including: EPA's Enforcement and Compliance History Online (ECHO) records restricted to potential PFAS-handling industry sectors; ECHO records for Fire Training Sites identified where fire-fighting foam may have been used in training exercises; and 14 CFR Part 139 Airports compiled from historic and current records from the FAA Airport Data and Information Portal. Since July 2006, all certificated Part 139 Airports are required to have fire-fighting foam onsite that meet certain military specifications, which to date have been fluorinated (Aqueous Film Forming Foam). Limitations: Inclusion in this dataset does not indicate that PFAS are being manufactured, processed, used, or released by the facility. Listed facilities potentially handle PFAS based on their industrial profile, but are unconfirmed by the EPA. Keyword searches in ECHO for Fire Training sites may misidentify some facilities and should not be considered to be an exhaustive list of fire training facilities in the U.S.

Government Publication Date: Mar 24, 2025

Hazardous Materials Information Reporting System:

[HMIRS](#)

The Hazardous Materials Incident Reporting System (HMIRS) database contains unintentional hazardous materials release information reported to the U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration.

Government Publication Date: May 29, 2024

National Clandestine Drug Labs:

[NCDL](#)

The U.S. Department of Justice ("the Department"), Drug Enforcement Administration (DEA), provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Nov 30, 2023

Toxic Substances Control Act:

[TSCA](#)

The U.S. Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule. The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI). EPA CDR collections occur approximately every four years and reporting requirements change per collection.

Government Publication Date: May 12, 2022

Hist TSCA:

[HIST TSCA](#)

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing:

[FTTS ADMIN](#)

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing:

[FTTS INSP](#)

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List:

[PRP](#)

Early in the site cleanup process, the U.S. Environmental Protection Agency (EPA) conducts a search to find the Potentially Responsible Parties (PRPs). The EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site. This listing contains PRPs, Noticed Parties, at sites in the EPA's Superfund Enterprise Management System (SEMS).

Government Publication Date: Apr 25, 2025

State Coalition for Remediation of Drycleaners Listing:

SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS):

ICIS

The Integrated Compliance Information System (ICIS) database contains integrated enforcement and compliance information across most of U.S. Environmental Protection Agency's (EPA) programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained by the EPA Headquarters and at the Regional offices. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Government Publication Date: Apr 13, 2024

Drycleaner Facilities:

FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jan 6, 2025

Delisted Drycleaner Facilities:

DELISTED FED DRY

List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).

Government Publication Date: Jan 6, 2025

Formerly Used Defense Sites:

FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DOD) is responsible for an environmental restoration. The FUDS Annual Report to Congress (ARC) is published by the U.S. Army Corps of Engineers (USACE). This data is compiled from the USACE's Geospatial FUDS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) FUDS dataset which applies to the Fiscal Year 2021 FUDS Inventory.

Government Publication Date: May 15, 2023

FUDS Munitions Response Sites:

FUDS MRS

Boundaries of Munitions Response Sites (MRS), published with the Formerly Used Defense Sites (FUDS) Annual Report to Congress (ARC) by the U.S. Army Corps of Engineers (USACE). An MRS is a discrete location within a Munitions response area (MRA) that is known to require a munitions response. An MRA means any area on a defense site that is known or suspected to contain unexploded ordnance (UXO), discarded military munitions (DMM), or munitions constituents (MC). This data is compiled from the USACE's Geospatial MRS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) MRS dataset.

Government Publication Date: May 15, 2023

Former Military Nike Missile Sites:

FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents:

PIPELINE INCIDENT

This list of flagged pipeline incidents is made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types. Accidents reported on hazardous liquid gravity lines (§195.13) and reporting-regulated-only hazardous liquid gathering lines (§195.15) and incidents reported on Type R gas gathering (§192.8(c)) are not included in the flagged incident file data.

Government Publication Date: May 6, 2024

Material Licensing Tracking System (MLTS):

MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites:

HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File:

MINES

The Master Index File (MIF) is provided by the United States Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Feb 5, 2024

Surface Mining Control and Reclamation Act Sites:

SMCRA

This inventory of land and water impacted by past mining (primarily legacy coal mining operations) is maintained by the U.S. Department of the Interior's Office of Surface Mining Reclamation and Enforcement (OSMRE), as it provides information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). This inventory contains information on the type and extent of Abandoned Mine Land (AML) Problems, as well as information on the cost associated with the reclamation of those problems. The data is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed. Disclaimer: Per the OSMRE, States and tribes who enter their data into e-AMLIS (AML Inventory System) may truncate their latitude and longitude so the precise location of usually dangerous AMLs is not revealed in an effort to protect the public from searching for these AMLs, most of which are on private property. If more precise location information is needed, please contact the applicable state/tribe of interest.

Government Publication Date: May 20, 2024

Mineral Resource Data System:

MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

DOE Legacy Management Sites:

LM SITES

The U.S. Department of Energy (DOE) Office of Legacy Management (LM) currently manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The LM manages sites with diverse regulatory drivers (statutes or programs that direct cleanup and management requirements at DOE sites) or as part of internal DOE or congressionally-recognized programs, such as but not limited to: Formerly Utilized Sites Remedial Action Program (FUSRAP), Uranium Mill Tailings Radiation Control Act (UMTRCA Title I, Title II), Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Resource Conservation and Recovery Act (RCRA), Decontamination and Decommissioning (D&D), Nuclear Waste Policy Act (NWPA). This site listing includes data exported from the DOE Office of LM's Geospatial Environmental Mapping System (GEMS). GEMS Data disclaimer: The DOE Office of LM makes no representation or warranty, expressed or implied, regarding the use, accuracy, availability, or completeness of the data presented herein.

Government Publication Date: Dec 12, 2023

Alternative Fueling Stations:

ALT FUELS

This list of alternative fueling stations is sourced from the Alternative Fuels Data Center (AFDC). The U.S. Department of Energy's Office of Energy Efficiency & Renewable Energy launched the AFDC in 1991 as a repository for alternative fuel vehicle performance data, which provides a wealth of information and data on alternative and renewable fuels, advanced vehicles, fuel-saving strategies, and emerging transportation technologies. The data includes Biodiesel (B20 and above), Compressed Natural Gas (CNG), Electric, Ethanol (E85), Hydrogen, Liquefied Natural Gas (LNG), Propane (LPG), and Renewable Diesel (R20 and above) fuel type locations.

Government Publication Date: May 12, 2025

Superfunds Consent Decrees:

CONSENT DECREES

This list of Superfund consent decrees is provided by the Department of Justice, Environment & Natural Resources Division (ENRD) through a Freedom of Information Act (FOIA) applicable file. This listing includes Cases filed since 2010 limited to the following: Consent Decrees for CERCLA or Superfund Sites filed and/or as proposed within the ENRD's Case Management System (CMS); and applicable ENRD's Environmental Defense Section (EDS) CERCLA Cases with "Consent" in History Note. CMS may not reflect the latest developments in a case, nor can the agency guarantee the accuracy of the data. ENRD Disclaimer: Congress excluded three discrete categories of law enforcement and national security records from the requirements of the FOIA; response is limited to those records that are subject to the requirements of the FOIA; however, this should not be taken as an indication that excluded records do, or do not, exist.

Government Publication Date: Jun 26, 2024

Air Facility System:

AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments:

SSTS

This national list of active EPA-registered foreign and domestic pesticide and/or device-producing establishments is based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that each producing establishment must place its EPA establishment number on the label or immediate container of each pesticide, active ingredient or device produced. An EPA establishment number on a pesticide product label identifies the EPA registered location where the product was produced. The list of establishments is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Feb 29, 2024

Polychlorinated Biphenyl (PCB) Transformers:

PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers:

PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: May 23, 2024

Power Plants:

POWER PLANTS

This list of power plants is provided by the U.S. Energy Information Administration (EIA). The listing includes operable electric generating plants in the United States by energy source, originating from the EIA-860, Annual Electric Generator Report; EIA-860M, Monthly Update to the Annual Electric Generator Report; and EIA-923, Power Plant Operations Report. It includes all operable plants by energy source with a combined nameplate capacity of 1 megawatt or more that are operating, are on standby, or out of service for short- or long-term.

Government Publication Date: Apr 15, 2024

Historical Business Activity Risk:

HIST RISK

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this listing does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including Polks, Millers, Mullin Kille, Interstate Directory, and State Directory Co; spanning roughly 1920s through 1960 depending on information available by city.

Government Publication Date: Jan 1, 1960

State

PFAS Sampling Locations:

PFAS SAMPLING

This data is sourced from the State Water Board's GeoTracker Per- and Polyfluoroalkyl Substances (PFAS) Map tool which contains individual sampling points (i.e., soil boring, groundwater monitoring well, drinking water well for municipal drinking water systems, etc.) or a site location with PFAS analytical data. Includes analytical results that are finalized and submitted electronically by the Responsible Parties via GeoTracker's Electronic Submittal of Information Portal, and after it's accepted by a Regional Water Quality Control Board.

Government Publication Date: Feb 25, 2025

Dry Cleaning Facilities:

DRYCLEANERS

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial, linen supply, commercial laundry, dry cleaning and pressing machines - Coin Operated Laundry and Dry Cleaning. This is provided by the Department of Toxic Substance Control.

Government Publication Date: Dec 20, 2021

Delisted Drycleaners:

DELISTED DRYCLEANERS

Sites removed from the list of drycleaner related facilities that have EPA ID numbers, made available by the California Department of Toxic Substance Control.

Government Publication Date: Jan 31, 2022

Non-Toxic Dry Cleaning Incentive Program:

DRYC GRANT

A list of grant recipients of the Non-Toxic Dry Cleaning Incentive Program made available by the California Air Resources Board (CARB). The program provides grants to eligible dry cleaning businesses to assist them in transitioning away from PERC machines to alternative non-toxic and non-smog forming technologies.

Government Publication Date: Jan 31, 2022

PFAS GeoTracker Cleanup Sites:

PFAS GT CLEANUPS

A list of applicable cleanup sites from the State Water Resources Control Board's (SWRCB) GeoTracker data management system where one or more of the potential contaminants of concern are identified in the PFAS Structure List and/or PFAS Chemicals Without Explicit Structure List made available by the United States Environmental Protection Agency (US EPA).

Government Publication Date: May 27, 2025

PFOA/PFOS Groundwater:

PFAS GW

A list of water wells from the Groundwater Ambient Monitoring and Assessment Program (GAMA) Groundwater Information System with the groundwater chemical perfluorooctanoic acid (PFOA) (NL = 0.014 UG/L) or perfluorooctanoic sulfonate (PFOS) (NL = 0.013 UG/L). The GAMA Groundwater Information System search is made available by California Water Boards.

Government Publication Date: Feb 15, 2025

PFAS Investigations:

PFAS INVEST

This list of potential Per- and Polyfluoroalkyl Substance (PFAS) sites is compiled from the California State Water Resources Control Board's (SWRCB) PFAS Investigations Map tool. The SWRCB issued investigative orders, per California Water Code (CWC) Section 13267 and/or 13383, to these sites. Orders were also issued to the public water systems to sample wells in the vicinity of these locations. Military facilities have been identified by the Department of Defense (DOD) as part of their efforts to investigate PFAS per the Defense Environmental Restoration Program (DERP) under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). The data includes locations for Airports, Chrome Plating Facilities, Landfills, Publicly Owned Treatment Works, Refineries and Bulk Terminals, DOD Facilities, and Monitored Drinking Water Wells being investigated for potential PFAS.

Government Publication Date: Jan 23, 2024

Hazardous Waste and Substances Site List - Site Cleanup:

HWSS CLEANUP

The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements in providing information about the location of hazardous materials release sites. This list is published by California Department of Toxic Substance Control.

Government Publication Date: Mar 15, 2023

Toxic Pit Cleanup Act Sites:

TOXIC PITS

The Toxic Pits Cleanup Act (TPCA) list identifies sites suspected of containing hazardous substances where cleanup has not yet been completed. This list was maintained by the State Water Resources Control Board (SWRCB), is no longer maintained, and updates are not planned.

Government Publication Date: Jul 1, 1995

List of Hazardous Waste Facilities Subject to Corrective Action:

[DTSC HWF](#)

This is a list of hazardous waste facilities identified in Health and Safety Code (HSC) § 25187.5. These facilities are those where Department of Toxic Substances Control (DTSC) has taken or contracted for corrective action because a facility owner/operator has failed to comply with a date for taking corrective action in an order issued under HSC § 25187, or because DTSC determined that immediate corrective action was necessary to abate an imminent or substantial endangerment.

Government Publication Date: Jul 18, 2016

EnviroStor Inspection, Compliance, and Enforcement:

[INSP COMP ENF](#)

A list of permitted facilities with inspections and enforcements tracked by the California Department of Toxic Substance Control's (DTSC) EnviroStor data management system.

Government Publication Date: Nov 23, 2023

School Property Evaluation Program Sites:

[SCH](#)

A list of sites registered with The Department of Toxic Substances Control (DTSC) School Property Evaluation and Cleanup (SPEC) Division. SPEC is responsible for assessing, investigating and cleaning up proposed school sites. The Division ensures that selected properties are free of contamination or, if the properties were previously contaminated, that they have been cleaned up to a level that protects the students and staff who will occupy the new school.

Government Publication Date: Jun 1, 2025

California Hazardous Material Incident Report System (CHMIRS):

[CHMIRS](#)

A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS). This listing has been made available by the California Governor's Office of Emergency Services (Cal OES).

Government Publication Date: Jan 8, 2025

Historical California Hazardous Material Incident Report System (CHMIRS):

[HIST CHMIRS](#)

A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS) prior to 1993. This list has been made available by the California Office of Emergency Services (OES).

Government Publication Date: Jan 1, 1993

Handlers from Hazardous Waste Manifest Data:

[HAZNET](#)

A list of handlers not otherwise classified as Treatment, Storage, Disposal facilities (TSDF) or generators from the facilities and manifests data made available by the California Department of Toxic Substances Control (DTSC) in their Hazardous Waste Tracking System (HWTS).

Government Publication Date: Feb 20, 2025

Generators from Hazardous Waste Manifest Data:

[HAZ GEN](#)

List of handlers listed as having generated waste from the facilities and manifests data made available by the California Department of Toxic Substances Control (DTSC) in their Hazardous Waste Tracking System (HWTS).

Government Publication Date: Feb 20, 2025

TSDF from Hazardous Waste Manifest Data:

[HAZ TSD](#)

List of Treatment, Storage, and Disposal Facilities (TSDFs) from the facilities and manifests data made available by the California Department of Toxic Substances Control (DTSC) in their Hazardous Waste Tracking System (HWTS).

Government Publication Date: Feb 20, 2025

Historical Hazardous Waste Manifest Data:

[HIST MANIFEST](#)

A list of historic hazardous waste manifests received by the Department of Toxic Substances Control (DTSC) from year the 1980 to 1992. The volume of manifests is typically 900,000 - 1,000,000 annually, representing approximately 450,000 - 500,000 shipments.

Government Publication Date: Dec 31, 1992

DTSC Registered Hazardous Waste Transporters:

[HW TRANSPORT](#)

The California Department of Toxic Substances Control (DTSC) maintains this list of Registered Hazardous Waste Transporters.

Government Publication Date: Mar 20, 2025

Registered Waste Tire Haulers:[WASTE TIRE](#)

This list of registered waste tire haulers is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Apr 19, 2025

California Medical Waste Management Program Facility List:[MEDICAL WASTE](#)

This list of Medical Waste Management Program Facilities is maintained by the California Department of Public Health. The Medical Waste Management Program (MWMP) regulates the generation, handling, storage, treatment, and disposal of medical waste by providing oversight for the implementation of the Medical Waste Management Act (MWMA). The MWMP permits and inspects all medical waste off-site treatment facilities, medical waste transporters, and medical waste transfer stations. This list contains transporters, treatment, and transfer facilities.

Government Publication Date: Apr 28, 2025

Historical Cortese List:[HIST CORTESE](#)

List of sites which were once included on the Cortese list. The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements for providing information about the location of hazardous sites.

Government Publication Date: Nov 13, 2008

Cease and Desist Orders and Cleanup and Abatement Orders:[CDO/CAO](#)

The California Environment Protection Agency "Cortese List" of active Cease and Desist Orders (CDO) and Cleanup and Abatement Orders (CAO). This list contains many CDOs and CAOs that do NOT concern the discharge of wastes that are hazardous materials. Many of the listed orders concern, as examples, discharges of domestic sewage, food processing wastes, or sediment that do not contain hazardous materials, but the Water Boards' database does not distinguish between these types of orders.

Government Publication Date: Dec 6, 2021

California Environmental Reporting System (CERS) Hazardous Waste Sites:[CERS HAZ](#)

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: May 28, 2025

Delisted Environmental Reporting System (CERS) Hazardous Waste Sites:[DELISTED HAZ](#)

This database contains a list of sites that were removed from the California Environmental Protection Agency (CalEPA) in the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator.

Government Publication Date: Nov 29, 2018

Sites in GeoTracker:[GEOTRACKER](#)

GeoTracker is the State Water Resource Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater. This is a list of sites in GeoTracker that aren't otherwise categorized as LUST, Land Disposal Sites (LDS), Cleanup Sites, or sites having Waste Discharge Requirements (WDR). This listing includes program types such as Underground Injection Control (UIC), Confined Animal Facilities (CAF), Irrigated Lands Regulatory Program, plans, and non-case information.

Government Publication Date: Apr 4, 2025

Mines Listing:[MINE](#)

This list includes mine site locations extracted from the Mines Online database, maintained by the California Department of Conservation. Mines Online (MOL) is an interactive web map designed with GIS features that provide information such as the mine name, mine status, commodity sold, location, and other mine specific data. Please note: Mine location information is provided to assist experts in determining the location of mine operators in accordance with California Civil Code section 1103.4 and reflects information reported by mine operators in annual reports provided under Public Resources Code section 2207. While the Division of Mine Reclamation (DMR) attempts to populate MOL with accurate location information, the DMR cannot guarantee the accuracy of operator reported location information.

Government Publication Date: Apr 10, 2025

Recorded Environmental Cleanup Liens:[LIEN](#)

The California Department of Toxic Substance Control (DTSC) maintains this list of liens placed upon real properties. A lien is utilized by the DTSC to obtain reimbursement from responsible parties for costs associated with the remediation of contaminated properties.

Government Publication Date: Apr 10, 2025

Waste Discharge Requirements:[WASTE DISCHG](#)

List of sites in California State Water Resources Control Board (SWRCB) Waste Discharge Requirements (WDRs) Program in California, made available by the SWRCB via GeoTracker. The WDR program regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Government Publication Date: Apr 4, 2025

Toxic Pollutant Emissions Facilities:[EMISSIONS](#)

A list of criteria and toxic pollutant emissions data for facilities in California made available by the California Environmental Protection Agency - Air Resources Board (ARB). Risk data may be based on previous inventory submittals. The toxics data are submitted to the ARB by the local air districts as requirement of the Air Toxics "Hot Spots" Program.

Government Publication Date: Dec 31, 2021

Clandestine Drug Lab Sites:[CDL](#)

The Department of Toxic Substances Control (DTSC) maintains a listing of drug lab sites. DTSC is responsible for removal and disposal of hazardous substances discovered by law enforcement officials while investigating illegal/ clandestine drug laboratories.

Government Publication Date: Jan 19, 2021

Tribal

No Tribal additional environmental record sources available for this State.

County**Orange County - Hazardous Waste Facilities:**[HW ORANGE](#)

A list of Hazardous Waste Facilities in Orange County. This list is made available by Orange County Environmental Health Department.

Government Publication Date: May 15, 2023

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.



Property Information

Order Number: 25061300823p
Date Completed: June 15, 2025
Project Number: 25-500978.1
Project Property: 9822 Russell Avenue
9822 Russell Avenue GARDEN GROVE CA 92844
Coordinates:
Latitude: 33.7681234
Longitude: -117.9578273
UTM Northing: 3736866.99597 Meters
UTM Easting: 411313.043885 Meters
UTM Zone: UTM Zone 11S
Elevation: 73.65 ft
Slope Direction: SW

Topographic Information.....	2
Hydrologic Information.....	4
Geologic Information.....	7
Soil Information.....	9
Wells and Additional Sources.....	13
Summary.....	14
Detail Report.....	17
Radon Information.....	69
Appendix.....	70
Liability Notice.....	72


The ERIS **Physical Setting Report - PSR** provides comprehensive information about the physical setting around a site and includes a complete overview of topography and surface topology, in addition to hydrologic, geologic and soil characteristics. The location and detailed attributes of oil and gas wells, water wells, public water systems and radon are also included for review.

The compilation of both physical characteristics of a site and additional attribute data is useful in assessing the impact of migration of contaminants and subsequent impact on soils and groundwater.

Disclaimer

This Report does not provide a full environmental evaluation for the site or adjacent properties. Please see the terms and disclaimer at the end of the Report for greater detail.

Topographic Information



Current USGS Topo (2022)



Quadrangle(s): Anaheim, CA

Source: USGS 7.5 Minute Topographic Map




Topographic Information

The previous topographic map(s) are created by seamlessly merging and cutting current USGS topographic data. Below are shaded relief map(s), derived from USGS elevation data to show surrounding topography in further detail.

Topographic information at project property:

Elevation: 73.65 ft
Slope Direction: SW



Hydrologic Information




Wetland




This map shows wetland existence using data from US Fish & Wildlife. Data coverage is shown to the right. Gray indicates no data available in the area.

- | | |
|---|---|
|  Estuarine and Marine Deepwater |  Freshwater Pond |
|  Estuarine and Marine Wetland |  Lake |
|  Freshwater Emergent Wetland |  Other |
|  Freshwater Forested/Shrub Wetland |  Riverine |



Hydrologic Information



Flood Hazard Zones

This map shows FEMA flood hazard zones based on FEMA's National Flood Hazard Layer. FIRM Panels are overlayed. An absent FIRM panel represents no data available.

- 1% Annual Chance Flood Hazard
- Regulatory Floodway
- Special Floodway
- Area of Undetermined Flood Hazard

- 0.2% Annual Chance Flood Hazard
- Future Conditions 1% Annual Chance Flood Hazard
- Area with Reduced Risk Due to Levee
- Area with Risk Due to Levee
- Open Water

Quadrangle(s): Anaheim, CA

0 0.075 0.15 Miles



Hydrologic Information


The Wetland Type map shows wetland existence overlaid on an aerial imagery. The Flood Hazard Zones map shows FEMA flood hazard zones overlaid on an aerial imagery. Relevant FIRM panels and detailed zone information is provided below. For detailed Zone descriptions please click the link: <https://floodadvocate.com/fema-zone-definitions>

Available FIRM Panels in area:	06059C0139J(effective:2009-12-03)
--------------------------------	-----------------------------------

Flood Zone X-01

Zone:	X
Zone subtype:	0.2 PCT ANNUAL CHANCE FLOOD HAZARD

Geologic Information



Geologic Units

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.




Geologic Information

The previous page shows USGS geology information. Detailed information about each unit is provided below.

Geologic Unit Q

Unit Name:	Quaternary alluvium and marine deposits
Unit Age:	Pleistocene to Holocene
Primary Rock Type:	Coarse-detrital
Secondary Rock Type:	
Unit Description:	Alluvium, lake, playa, and terrace deposits; unconsolidated and semi-consolidated. Mostly nonmarine, but includes marine deposits near the coast.

Soil Information



SSURGO Soils



This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.



Soil Information

The previous page shows a soil map using SSURGO data from USDA Natural Resources Conservation Service. Detailed information about each unit is provided below.

Map Unit 123 (0.5%)

Map Unit Name:	Bolsa silt loam, drained
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Somewhat poorly drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Bolsa(70%)

horizon Ap1(0cm to 15cm)	Silt loam
horizon Ap2(15cm to 30cm)	Silt loam
horizon C1(30cm to 46cm)	Silt loam
horizon C2(46cm to 74cm)	Silt loam
horizon C3(74cm to 99cm)	Silty clay loam
horizon C4(99cm to 124cm)	Silty clay loam
horizon C5(124cm to 140cm)	Silty clay loam
horizon Cg(140cm to 175cm)	Silty clay loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 123 - Bolsa silt loam, drained

Component: Bolsa (70%)

The Bolsa component makes up 70 percent of the map unit. Slopes are 0 to 2 percent. This component is on alluvial fans, coastal plains. The parent material consists of mixed alluvium derived from igneous, metamorphic and sedimentary rock. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat poorly drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is moderate. This soil is rarely flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 0 percent. Nonirrigated land capability classification is 3w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 3 percent. There are no saline horizons within 30 inches of the soil surface.

Component: Hueneme (10%)

Generated brief soil descriptions are created for major soil components. The Hueneme soil is a minor component.

Component: Chino (10%)

Generated brief soil descriptions are created for major soil components. The Chino soil is a minor component.

Component: Metz (4%)

Generated brief soil descriptions are created for major soil components. The Metz soil is a minor component.

Component: Omni (2%)

Generated brief soil descriptions are created for major soil components. The Omni soil is a minor component.

Component: San Emigdio (2%)

Generated brief soil descriptions are created for major soil components. The San Emigdio soil is a minor component.

Component: Bolsa (2%)

Generated brief soil descriptions are created for major soil components. The Bolsa soil is a minor component.

Soil Information

Map Unit 158 (45.24%)

Map Unit Name:	Hueneme fine sandy loam, drained
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Poorly drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Hueneme(85%)

horizon H1(0cm to 69cm)	Fine sandy loam
horizon H2(69cm to 152cm)	Stratified sand to silt loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 158 - Hueneme fine sandy loam, drained

Component: Hueneme (85%)

The Hueneme component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on alluvial fans. The parent material consists of stratified alluvium derived from sedimentary rock. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is poorly drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. Nonirrigated land capability classification is 3c. Irrigated land capability classification is 1 This soil meets hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 1 percent. The soil has a very slightly saline horizon within 30 inches of the soil surface.

Component: San Emigdio (5%)

Generated brief soil descriptions are created for major soil components. The San Emigdio, FINE SANDY LOAM soil is a minor component.

Component: Bolsa (5%)

Generated brief soil descriptions are created for major soil components. The Bolsa, SILT LOAM, DRAINED soil is a minor component.

Component: Hueneme (5%)

Generated brief soil descriptions are created for major soil components. The Hueneme, FINE SANDY LOAM soil is a minor component.

Map Unit 163 (54.26%)

Map Unit Name:	Metz loamy sand
Bedrock Depth - Min:	null
Watertable Depth - Annual Min:	null
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.

Major components are printed below

Metz(80%)

horizon H1(0cm to 43cm)	Loamy sand
horizon H2(43cm to 160cm)	Stratified sand to fine sandy loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 163 - Metz loamy sand

Soil Information

Component: Metz (80%)

The Metz component makes up 80 percent of the map unit. Slopes are 0 to 2 percent. This component is on alluvial fans. The parent material consists of alluvium derived from mixed. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R019XD035CA Sandy (1975) ecological site. Nonirrigated land capability classification is 4e. Irrigated land capability classification is 2s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 3 percent. There are no saline horizons within 30 inches of the soil surface.

Component: San Emigdio (4%)

Generated brief soil descriptions are created for major soil components. The San Emigdio soil is a minor component.

Component: Hueneme (4%)

Generated brief soil descriptions are created for major soil components. The Hueneme soil is a minor component.

Component: Riverwash (4%)

Generated brief soil descriptions are created for major soil components. The Riverwash soil is a minor component.

Component: Corralitos (4%)

Generated brief soil descriptions are created for major soil components. The Corralitos soil is a minor component.

Component: Metz (4%)

Generated brief soil descriptions are created for major soil components. The Metz soil is a minor component.

Wells and Additional Sources



Wells & Additional Sources



- | | |
|--------------------------------|------------------------------------|
| ▲ Sites with Higher Elevation | ▲ OGW Sites with Higher Elevation |
| ■ Sites with Same Elevation | ■ OGW Sites with Same Elevation |
| ▼ Sites with Lower Elevation | ▼ OGW Sites with Lower Elevation |
| ○ Sites with Unknown Elevation | ● OGW Sites with Unknown Elevation |



Wells and Additional Sources Summary

Federal Sources

Public Water Systems Violations and Enforcement Data

Map Key	PWS ID	Distance (ft)	Direction
3	CA3000601	3234.51	SSW
11	CA3000596	4587.09	SSE

Safe Drinking Water Information System (SDWIS)

Map Key	PWS ID	Distance (ft)	Direction
3	CA3000601	3234.51	SSW
11	CA3000596	4587.09	SSE

USGS National Water Information System

Map Key	Site No	Distance (ft)	Direction
6	USGS-334637117580001	4159.80	NW
12	USGS-334548117562901	4816.84	ESE
13	USGS-334601117582401	4845.57	W

State Sources

Oil and Gas Wells

Map Key	API No	Distance (ft)	Direction
10	0405901160	4399.66	ENE

Periodic Groundwater Level Measurement Locations

Map Key	Site Code	Distance (ft)	Direction
5	337744N1179482W001	3467.26	NE
7	337770N1179685W001	4367.79	NW
8	337680N1179728W001	4400.13	W
9	337779N1179480W001	4386.24	NE
9	337779N1179480W003	4386.24	NE
9	337779N1179480W002	4386.24	NE
14	337632N1179423W001	4830.36	ESE
15	337588N1179714W001	5169.97	SW

Well Completion Reports

Map Key	WCR No	Distance (ft)	Direction
1	WCR0063856	1756.60	WSW
1	WCR2003-014554	1756.60	WSW
1	WCR2002-012376	1756.60	WSW
1	WCR0089995	1756.60	WSW
1	WCR1951-002234	1756.60	WSW
1	WCR0211065	1756.60	WSW

Wells and Additional Sources Summary

1	WCR1916-000053	1756.60	WSW
1	WCR2005-016303	1756.60	WSW
1	WCR1951-002233	1756.60	WSW
1	WCR1916-000098	1756.60	WSW
1	WCR2003-014553	1756.60	WSW
1	WCR2005-016302	1756.60	WSW
1	WCR0192657	1756.60	WSW
2	WCR2018-006771	3012.72	NE
2	WCR2018-006773	3012.72	NE
2	WCR2018-006770	3012.72	NE
2	WCR2018-006772	3012.72	NE
4	WCR2013-011024	3406.52	E
4	WCR1991-018197	3406.52	E
4	WCR1994-012639	3406.52	E
4	WCR2000-012810	3406.52	E
4	WCR1996-011170	3406.52	E
4	WCR0188896	3406.52	E
4	WCR0018492	3406.52	E
4	WCR1994-012638	3406.52	E
4	WCR2003-011639	3406.52	E
4	WCR0048313	3406.52	E
4	WCR0213456	3406.52	E
4	WCR0101687	3406.52	E
4	WCR2015-002061	3406.52	E
4	WCR2003-013248	3406.52	E
4	WCR2000-012811	3406.52	E
4	WCR0312206	3406.52	E
4	WCR0004384	3406.52	E
4	WCR1994-012641	3406.52	E
4	WCR2015-002048	3406.52	E
4	WCR0317682	3406.52	E
4	WCR1996-009469	3406.52	E
4	WCR2000-010560	3406.52	E
4	WCR2015-001904	3406.52	E
4	WCR2004-011703	3406.52	E
4	WCR2000-010588	3406.52	E
4	WCR2015-002050	3406.52	E
4	WCR1982-006459	3406.52	E
4	WCR0245173	3406.52	E
4	WCR1925-000213	3406.52	E
4	WCR1913-000197	3406.52	E
4	WCR0218899	3406.52	E
4	WCR2000-010559	3406.52	E
4	WCR0048314	3406.52	E
4	WCR2015-002052	3406.52	E
4	WCR1995-009635	3406.52	E
4	WCR1913-000112	3406.52	E
4	WCR2013-011023	3406.52	E
4	WCR2003-014689	3406.52	E
4	WCR2015-001907	3406.52	E
4	WCR1994-012635	3406.52	E
4	WCR0109811	3406.52	E
4	WCR0032803	3406.52	E
4	WCR1952-001800	3406.52	E
4	WCR0032802	3406.52	E
4	WCR0162237	3406.52	E
4	WCR0159395	3406.52	E
4	WCR0089994	3406.52	E
4	WCR0199919	3406.52	E
4	WCR0135543	3406.52	E
4	WCR2015-002047	3406.52	E
4	WCR2015-001906	3406.52	E
4	WCR2015-002051	3406.52	E
4	WCR1995-010624	3406.52	E
4	WCR2015-001905	3406.52	E
4	WCR0289442	3406.52	E

Wells and Additional Sources Summary

4	WCR1993-010775	3406.52	E
4	WCR0151862	3406.52	E
4	WCR2015-002060	3406.52	E
4	WCR2004-014549	3406.52	E
4	WCR0048315	3406.52	E
4	WCR1952-001801	3406.52	E
4	WCR0099525	3406.52	E
4	WCR2015-002049	3406.52	E
4	WCR1994-012640	3406.52	E
16	WCR2001-012359	5235.98	NNE
16	WCR2015-001794	5235.98	NNE
16	WCR0216525	5235.98	NNE
16	WCR1935-000227	5235.98	NNE
16	WCR2015-001797	5235.98	NNE
16	WCR2001-014491	5235.98	NNE
16	WCR1991-020973	5235.98	NNE
16	WCR0004415	5235.98	NNE
16	WCR1998-010754	5235.98	NNE
16	WCR1952-001717	5235.98	NNE
16	WCR2015-001793	5235.98	NNE
16	WCR2010-010358	5235.98	NNE
16	WCR1916-000043	5235.98	NNE
16	WCR1987-014318	5235.98	NNE
16	WCR1997-010365	5235.98	NNE
16	WCR2015-001792	5235.98	NNE
16	WCR0098806	5235.98	NNE
16	WCR1998-010753	5235.98	NNE
16	WCR2010-010357	5235.98	NNE
16	WCR0124850	5235.98	NNE
16	WCR1916-000105	5235.98	NNE
16	WCR2015-001796	5235.98	NNE
16	WCR2010-010356	5235.98	NNE
16	WCR1776-008728	5235.98	NNE
16	WCR2015-001798	5235.98	NNE
16	WCR2015-001795	5235.98	NNE
16	WCR1992-017555	5235.98	NNE
16	WCR1998-010752	5235.98	NNE
16	WCR0269481	5235.98	NNE
16	WCR2010-010355	5235.98	NNE
16	WCR0089617	5235.98	NNE

Wells and Additional Sources Detail Report

Public Water Systems Violations and Enforcement Data

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
3	SSW	0.61	3,234.51	61.97	PWSV

PWS ID: CA3000601
 PWS Type Code: CWS
 PWS Type Description: Community water system
 Primary Source Code: GW
 Primary Source Desc: Ground water
 PWS Activity Code: I
 PWS Activity Description: Inactive
 PWS Deactivation Date: 09/01/1981
 Zip Code:
 Phone No:
 Phone Ext No:
 Admin Name: OCEAN BREEZE TRAILER PARK
 Alt Phone No:
 Email Addr:
 Fax No:
 Cds ID:
 Population Served Count: 190
 Epa Region Desc: Region 9
 Epa Region: 09
 First Reported Date: 03/22/1979
 Gw or Sw: Groundwater
 Gw Sw Code: GW
 Is Grant Eligible Ind: No
 Outstanding Performer:
 Is School or Daycare Ind: No
 Is Source Water Protection:
 Is Wholesaler Ind: No
 Lt2 Schedule Cat:
 Lt2 Schedule Cat Code:
 Last Reported Date: 07/24/1995
 Org Name:
 Outstanding Perform
 Begin Date:
 Owner Type:
 Pop Cat 11: 101-500
 Pop Cat 2: <10,000
 Pop Cat 3: <=3300
 Pop Cat 4: <10K
 Pop Cat 5: <=500
 Primacy Agency: California
 Season Begin Date: 01-01

Wells and Additional Sources Detail Report

Season End Date: 12-31
Service Connections Count: 0
Submission Status Code: Y
Submissionyearquarter: 2023Q3
Primacy Type: State
Dbpr Schedule Category:
Submission Status: Reported and accepted
Reduced Monitoring Begin Date:
Reduced Monitoring End Date:
Reduced Rtr Monitoring:
Seasonal Startup System:
Source Protection Begin Date:
City Served:
County Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
11	SSE	0.87	4,587.09	62.50	PWSV

PWS ID: CA3000596
PWS Type Code: CWS
PWS Type Description: Community water system
Primary Source Code: GW
Primary Source Desc: Ground water
PWS Activity Code: I
PWS Activity Description: Inactive
PWS Deactivation Date: 11/01/1993
Zip Code: 92643
Phone No:
Phone Ext No:
Admin Name: GARDEN GROVE ACRES01
Alt Phone No:
Email Addr:
Fax No:
Cds ID:
Population Served Count: 220
Epa Region Desc: Region 9
Epa Region: 09
First Reported Date: 03/22/1979
Gw or Sw: Groundwater
Gw Sw Code: GW
Is Grant Eligible Ind: No
Outstanding Performer:
Is School or Daycare Ind: No
Is Source Water Protection:

Wells and Additional Sources Detail Report

Is Wholesaler Ind: No
Lt2 Schedule Cat:
Lt2 Schedule Cat Code:
Last Reported Date: 07/24/1995
Org Name:
Outstanding Perform
Begin Date:
Owner Type:
Pop Cat 11: 101-500
Pop Cat 2: <10,000
Pop Cat 3: <=3300
Pop Cat 4: <10K
Pop Cat 5: <=500
Primacy Agency: California
Season Begin Date: 01-01
Season End Date: 12-31
Service Connections
Count: 168
Submission Status Code: Y
Submissionyearquarter: 2023Q3
Primacy Type: State
Dbpr Schedule Category:
Submission Status: Reported and accepted
Reduced Monitoring Begin
Date:
Reduced Monitoring End
Date:
Reduced Rtr Monitoring:
Seasonal Startup System:
Source Protection Begin
Date:
City Served:
County Served: Orange

Safe Drinking Water Information System (SDWIS)

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
3	SSW	0.61	3,234.51	61.97	SDWIS

PWS ID: CA3000601
PWS Type Code: CWS
PSW Type: Community water system
Primary Source Code: GW
Primary Source: Ground water
Pws Activity Code: I
Activity: Inactive
PWS Deactivation Dt: 09/01/1981
Phone No:
Phone Ext No:
Admin Name: OCEAN BREEZE TRAILER PARK

Wells and Additional Sources Detail Report

Alt Phone No:
Email Addr:
Fax No:
Cds ID:
Population Served Count: 190
Epa Region Desc: Region 9
Epa Region: 09
First Reported Date: 03/22/1979
Gw or Sw: Groundwater
Is Grant Eligible Ind: No
Outstanding Performer:
Is School or Daycare Ind: No
Is Wholesaler Ind: No
Lt2 Schedule Cat:
Last Reported Date: 07/24/1995
Org Name:
Outstanding Perform
Begin Date:
Owner Type:
Pop Cat 11: 101-500
Pop Cat 2: <10,000
Pop Cat 3: <=3300
Pop Cat 4: <10K
Pop Cat 5: <=500
Primacy Agency: California
Primacy Agency Code: CA
Season Begin Date: 01-01
Season End Date: 12-31
Service Connections
Count: 0
Submission Yr Qtr: 2023Q3
Primacy Type: State
Dbpr Schedule Category:
Submission Status: Reported and accepted
Reduced Monitoring
Begin:
Reduced Monitoring End
Date:
Reduced Rtr Monitoring:
Seasonal Startup System:
Source Protection Begin
Date:
City Served:
County Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
11	SSE	0.87	4,587.09	62.50	SDWIS

PWS ID: CA3000596

Wells and Additional Sources Detail Report

PWS Type Code: CWS
PSW Type: Community water system
Primary Source Code: GW
Primary Source: Ground water
Pws Activity Code: I
Activity: Inactive
PWS Deactivation Dt: 11/01/1993
Phone No:
Phone Ext No:
Admin Name: GARDEN GROVE ACRES01
Alt Phone No:
Email Addr:
Fax No:
Cds ID:
Population Served Count: 220
Epa Region Desc: Region 9
Epa Region: 09
First Reported Date: 03/22/1979
Gw or Sw: Groundwater
Is Grant Eligible Ind: No
Outstanding Performer:
Is School or Daycare Ind: No
Is Wholesaler Ind: No
Lt2 Schedule Cat:
Last Reported Date: 07/24/1995
Org Name:
Outstanding Perform
Begin Date:
Owner Type:
Pop Cat 11: 101-500
Pop Cat 2: <10,000
Pop Cat 3: <=3300
Pop Cat 4: <10K
Pop Cat 5: <=500
Primacy Agency: California
Primacy Agency Code: CA
Season Begin Date: 01-01
Season End Date: 12-31
Service Connections
Count: 168
Submission Yr Qtr: 2023Q3
Primacy Type: State
Dbpr Schedule Category:
Submission Status: Reported and accepted
Reduced Monitoring
Begin:
Reduced Monitoring End
Date:
Reduced Rtr Monitoring:
Seasonal Startup System:

Wells and Additional Sources Detail Report

Source Protection Begin

Date:

City Served:

County Served: Orange

USGS National Water Information System

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
6	NW	0.79	4,159.80	74.79	FED USGS

Site No: USGS-334637117580001

Site Type: Well

Formation Type:

Date Drilled:

Well Depth:

Well Depth Unit:

Well Hole Depth:

Well Hole Depth Unit:

Reporting Agency: USGS California Water Science Center

Station Name: 004S010W31P001S

Latitude: 33.77696058000000

Longitude: -117.9675596000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
12	ESE	0.91	4,816.84	77.67	FED USGS

Site No: USGS-334548117562901

Site Type: Well

Formation Type:

Date Drilled:

Well Depth:

Well Depth Unit:

Well Hole Depth: 987

Well Hole Depth Unit: ft

Reporting Agency: USGS California Water Science Center

Station Name: 005S010W05J002S

Latitude: 33.76334989000000

Longitude: -117.9422808000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	W	0.92	4,845.57	63.29	FED USGS

Site No: USGS-334601117582401

Site Type: Well

Formation Type:

Date Drilled:

Wells and Additional Sources Detail Report

Well Depth: 960
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS California Water Science Center
Station Name: 005S011W01H002S
Latitude: 33.76696070000000
Longitude: -117.9742263000000

Oil and Gas Wells

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
10	ENE	0.83	4,399.66	87.10	OGW

API No:	0405901160	Directional:	
All Well Key:		BLM Well:	
OP Well ID:		EPA Well:	
OID:		Operator Code:	C5640
Well No:	1	Operator Name:	Chevron U.S.A. Inc.
Well Status:	Plugged	Operator St:	
Well Stat Desc:	Plugged	County APIC:	
Well Type:	DH	District:	Southern
Well Type Desc:	Dry Hole	Geo District:	
Well Symbol:	PluggedDH	Field Code:	
Well Sym Desc:		Field Name:	Any Field
Release Date:		Area Code:	
Completion Date:		Area Name:	Any Area
Abandoned Date:		County Name:	Orange
Lease Name:	Chaffee	Section:	32
Elevation:		Township:	04S
Total Depth:		Range:	10W
Redrilled Depth:		Lat27:	
Redrill Cancel Flag:		Long27:	
Dryhole:		Lat83:	33.77463913
Confidential:		Long83:	-117.94469452
Confidential Well:	No	Base Meridian:	SB
Directional Drilled:	No	GIS Source Code:	hud
Hydr Fractured:		INHPZ:	Verified HPZ
Well Design:	Chaffee 1		
Location:			
Place:	Garden Grove		
Source83 Desc:	Heads Up Digitized - Coordinates generated from scanned, geo-referenced, static scale, Mylar maps		
URL:			

Periodic Groundwater Level Measurement Locations

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	NE	0.66	3,467.26	84.75	MONITOR WELLS

Wells and Additional Sources Detail Report

Station ID:	38658	Basin Region Desc:	North Lahontan
Site Code:	337744N1179482W001	Basin Region Actv:	Y
WCR No:		Basin Region Order:	8
State Well No:	04S10W32Q002S	WLM Method:	
Well Depth:		WLM Accuracy:	
Well Use:	Unknown	Ground Surf Elevtn:	85.32000
Monitoring Program:	VOLUNTARY	GSE Method:	Unknown
RPE:	85.32000	GSE Accuracy:	Unknown
Basin ID:	197	County Name:	Orange
Basin Code:	8-001	Latitude:	33.77440
Basin Name:	Coastal Plain Of Orange County	Longitude:	-117.94820
Basin Region Code:	8		
Continuous Data Station No:			
Well Name:	04S10W32Q002S		
Well Type:	Unknown		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
7	NW	0.83	4,367.79	73.35	MONITOR WELLS

Station ID:	5235	Basin Region Desc:	North Lahontan
Site Code:	337770N1179685W001	Basin Region Actv:	Y
WCR No:		Basin Region Order:	8
State Well No:	04S10W31P001S	WLM Method:	
Well Depth:		WLM Accuracy:	
Well Use:	Unknown	Ground Surf Elevtn:	74.21000
Monitoring Program:	VOLUNTARY	GSE Method:	Unknown
RPE:	73.83000	GSE Accuracy:	Unknown
Basin ID:	197	County Name:	Orange
Basin Code:	8-001	Latitude:	33.77700
Basin Name:	Coastal Plain Of Orange County	Longitude:	-117.96850
Basin Region Code:	8		
Continuous Data Station No:			
Well Name:	04S10W31P001S		
Well Type:	Unknown		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	W	0.83	4,400.13	63.98	MONITOR WELLS

Station ID:	25333	Basin Region Desc:	North Lahontan
Site Code:	337680N1179728W001	Basin Region Actv:	Y
WCR No:		Basin Region Order:	8
State Well No:	05S11W01H001S	WLM Method:	
Well Depth:		WLM Accuracy:	
Well Use:	Unknown	Ground Surf Elevtn:	64.97000

Wells and Additional Sources Detail Report

Monitoring Program:	VOLUNTARY	GSE Method:	Unknown
RPE:	64.97000	GSE Accuracy:	Unknown
Basin ID:	197	County Name:	Orange
Basin Code:	8-001	Latitude:	33.76800
Basin Name:	Coastal Plain Of Orange County	Longitude:	-117.97280
Basin Region Code:	8		
Continuous Data Station No:			
Well Name:	05S11W01H001S		
Well Type:	Unknown		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	NE	0.83	4,386.24	88.33	MONITOR WELLS

Station ID:	47312	Basin Region Desc:	North Lahontan
Site Code:	337779N1179480W001	Basin Region Actv:	Y
WCR No:	349227,28	Basin Region Order:	8
State Well No:	04S10W32K001S	WLM Method:	
Well Depth:	2058.00000	WLM Accuracy:	
Well Use:	Observation	Ground Surf Elevtn:	87.91000
Monitoring Program:	SGMA	GSE Method:	Surveyed to a benchmark
RPE:	87.19000	GSE Accuracy:	0.1 ft.
Basin ID:	197	County Name:	Orange
Basin Code:	8-001	Latitude:	33.77785
Basin Name:	Coastal Plain Of Orange County	Longitude:	-117.94804
Basin Region Code:	8		
Continuous Data Station No:			
Well Name:	GGM-1/MP1		
Well Type:	Part of a nested/multi-completion well		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	NE	0.83	4,386.24	88.33	MONITOR WELLS

Station ID:	47314	Basin Region Desc:	North Lahontan
Site Code:	337779N1179480W003	Basin Region Actv:	Y
WCR No:	349227,28	Basin Region Order:	8
State Well No:		WLM Method:	
Well Depth:	2058.00000	WLM Accuracy:	
Well Use:	Observation	Ground Surf Elevtn:	87.91000
Monitoring Program:	SGMA	GSE Method:	Surveyed to a benchmark
RPE:	87.19000	GSE Accuracy:	0.1 ft.
Basin ID:	197	County Name:	Orange
Basin Code:	8-001	Latitude:	33.77785
Basin Name:	Coastal Plain Of Orange County	Longitude:	-117.94804
Basin Region Code:	8		
Continuous Data Station			

Wells and Additional Sources Detail Report

No:
 Well Name: GGM-1/MP8
 Well Type: Part of a nested/multi-completion well

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	NE	0.83	4,386.24	88.33	MONITOR WELLS

Station ID:	47313	Basin Region Desc:	North Lahontan
Site Code:	337779N1179480W002	Basin Region Actv:	Y
WCR No:	349227,28	Basin Region Order:	8
State Well No:		WLM Method:	
Well Depth:	2058.00000	WLM Accuracy:	
Well Use:	Observation	Ground Surf Elevtn:	87.91000
Monitoring Program:	SGMA	GSE Method:	Surveyed to a benchmark
RPE:	87.19000	GSE Accuracy:	0.1 ft.
Basin ID:	197	County Name:	Orange
Basin Code:	8-001	Latitude:	33.77785
Basin Name:	Coastal Plain Of Orange County	Longitude:	-117.94804
Basin Region Code:	8		
Continuous Data Station No:			
Well Name:	GGM-1/MP13		
Well Type:	Part of a nested/multi-completion well		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
14	ESE	0.91	4,830.36	77.89	MONITOR WELLS

Station ID:	25151	Basin Region Desc:	North Lahontan
Site Code:	337632N1179423W001	Basin Region Actv:	Y
WCR No:		Basin Region Order:	8
State Well No:	05S10W05R002S	WLM Method:	
Well Depth:		WLM Accuracy:	
Well Use:	Unknown	Ground Surf Elevtn:	77.91000
Monitoring Program:	VOLUNTARY	GSE Method:	Unknown
RPE:	77.91000	GSE Accuracy:	Unknown
Basin ID:	197	County Name:	Orange
Basin Code:	8-001	Latitude:	33.76320
Basin Name:	Coastal Plain Of Orange County	Longitude:	-117.94230
Basin Region Code:	8		
Continuous Data Station No:			
Well Name:	05S10W05R002S		
Well Type:	Unknown		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	SW	0.98	5,169.97	57.61	MONITOR WELLS

Wells and Additional Sources Detail Report

Station ID:	28371	Basin Region Desc:	North Lahontan
Site Code:	337588N1179714W001	Basin Region Actv:	Y
WCR No:		Basin Region Order:	8
State Well No:	05S10W07D003S	WLM Method:	
Well Depth:		WLM Accuracy:	
Well Use:	Unknown	Ground Surf Elevtn:	55.64000
Monitoring Program:	VOLUNTARY	GSE Method:	Unknown
RPE:	56.22000	GSE Accuracy:	Unknown
Basin ID:	197	County Name:	Orange
Basin Code:	8-001	Latitude:	33.75880
Basin Name:	Coastal Plain Of Orange County	Longitude:	-117.97140
Basin Region Code:	8		
Continuous Data Station No:			
Well Name:	05S10W07D003S		
Well Type:	Unknown		

Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No:	WCR0063856
Location:	
City:	
County:	Orange
Decimal Latitude:	33.767
Decimal Longitude:	-117.964
Location(OSWCR):	
City(OSWCR):	
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.767
Decim Long(OSWCR):	-117.964
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No:	WCR2003-014554
Location:	9011 Westminster Ave, Magnolia St
City:	Garden Grove
County:	Orange
Decimal Latitude:	33.767
Decimal Longitude:	-117.964
Location(OSWCR):	9011 Westminster Ave, Magnolia St
City(OSWCR):	Garden Grove

Wells and Additional Sources Detail Report

County(OSWCR): Orange
Decimal Lat(OSWCR): 33.767
Decim Long(OSWCR): -117.964
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR2002-012376
Location: 9001 Garden Grove Blvd
City: Garden Grove
County: Orange
Decimal Latitude: 33.767
Decimal Longitude: -117.964
Location(OSWCR): 9001 Garden Grove Blvd
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.767
Decim Long(OSWCR): -117.964
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR0089995
Location:
City:
County: Orange
Decimal Latitude: 33.767
Decimal Longitude: -117.964
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.767
Decim Long(OSWCR): -117.964
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR1951-002234
Location: WRIGHT ST,17TH ST
City:
County: Orange

Wells and Additional Sources Detail Report

Decimal Latitude: 33.767
 Decimal Longitude: -117.964
 Location(OSWCR): WRIGHT ST,17TH ST
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.767
 Decim Long(OSWCR): -117.964
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR0211065
 Location:
 City:
 County: Orange
 Decimal Latitude: 33.767
 Decimal Longitude: -117.964
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.767
 Decim Long(OSWCR): -117.964
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR1916-000053
 Location: EMFRAL AVE, OCEAN AVE, WRIGHT ST
 City:
 County: Orange
 Decimal Latitude: 33.767
 Decimal Longitude: -117.964
 Location(OSWCR): EMFRAL AVE, OCEAN AVE, WRIGHT ST
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.767
 Decim Long(OSWCR): -117.964
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

Wells and Additional Sources Detail Report

WCR No: WCR2005-016303
Location: 8990 Westminster Avenue
City: Westminster
County: Orange
Decimal Latitude: 33.767
Decimal Longitude: -117.964
Location(OSWCR): 8990 Westminster Avenue
City(OSWCR): Westminster
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.767
Decim Long(OSWCR): -117.964
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR1951-002233
Location: WRIGHT AVE, 17TH ST
City:
County: Orange
Decimal Latitude: 33.767
Decimal Longitude: -117.964
Location(OSWCR): WRIGHT AVE, 17TH ST
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.767
Decim Long(OSWCR): -117.964
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR1916-000098
Location: EMFRAL AVE, OCEAN AVE, WRIGHT ST
City:
County: Orange
Decimal Latitude: 33.767
Decimal Longitude: -117.964
Location(OSWCR): EMFRAL AVE, OCEAN AVE, WRIGHT ST
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.767
Decim Long(OSWCR): -117.964
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR2003-014553
 Location: 9011 Westminster Ave, Magnolia St
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.767
 Decimal Longitude: -117.964
 Location(OSWCR): 9011 Westminster Ave, Magnolia St
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.767
 Decim Long(OSWCR): -117.964
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR2005-016302
 Location: 8990 Westminster Avenue
 City: Westminster
 County: Orange
 Decimal Latitude: 33.767
 Decimal Longitude: -117.964
 Location(OSWCR): 8990 Westminster Avenue
 City(OSWCR): Westminster
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.767
 Decim Long(OSWCR): -117.964
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	WSW	0.33	1,756.60	69.87	WATER WELLS

WCR No: WCR0192657
 Location:
 City:
 County: Orange
 Decimal Latitude: 33.767
 Decimal Longitude: -117.964
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange

Wells and Additional Sources Detail Report

Decimal Lat(OSWCR): 33.767
 Decim Long(OSWCR): -117.964
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	NE	0.57	3,012.72	80.76	WATER WELLS

WCR No: WCR2018-006771
 Location: 10510 Garden Grove BLVD
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7732
 Decimal Longitude: -117.949
 Location(OSWCR): 10510 Garden Grove BLVD
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7732
 Decim Long(OSWCR): -117.949
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	NE	0.57	3,012.72	80.76	WATER WELLS

WCR No: WCR2018-006773
 Location: 10510 Garden Grove BLVD
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7732
 Decimal Longitude: -117.949
 Location(OSWCR): 10510 Garden Grove BLVD
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7732
 Decim Long(OSWCR): -117.949
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	NE	0.57	3,012.72	80.76	WATER WELLS

WCR No: WCR2018-006770
 Location: 10510 Garden Grove BLVD
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7732

Wells and Additional Sources Detail Report

Decimal Longitude: -117.949
 Location(OSWCR): 10510 Garden Grove BLVD
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7732
 Decim Long(OSWCR): -117.949
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	NE	0.57	3,012.72	80.76	WATER WELLS

WCR No: WCR2018-006772
 Location: 10510 Garden Grove BLVD
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7732
 Decimal Longitude: -117.949
 Location(OSWCR): 10510 Garden Grove BLVD
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7732
 Decim Long(OSWCR): -117.949
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2013-011024
 Location: 11162 Garden Grove Blvd
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 11162 Garden Grove Blvd
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1991-018197

Wells and Additional Sources Detail Report

Location: 13222 Brookhurst
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 13222 Brookhurst
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1994-012639
 Location: 13331 EUCLID BLVD
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 13331 EUCLID BLVD
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2000-012810
 Location: 9972 Westminster Avenue
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 9972 Westminster Avenue
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

4	E	0.65	3,406.52	77.31	WATER WELLS
---	---	------	----------	-------	-------------

WCR No: WCR1996-011170
Location: BROOKHURST
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): BROOKHURST
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0188896
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0018492
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1994-012638
Location: 13331 EUCLID BLVD
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 13331 EUCLID BLVD
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2003-011639
Location: 13954 Mills Rd
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 13954 Mills Rd
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0048313
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946

Wells and Additional Sources Detail Report

Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0213456
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0101687
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-002061
Location: 11162 Garden Grove Blvd

Wells and Additional Sources Detail Report

City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 11162 Garden Grove Blvd
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2003-013248
Location: 13482 Brookhurst Street
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 13482 Brookhurst Street
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2000-012811
Location: 13842 Brookhurst Street
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 13842 Brookhurst Street
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

4	E	0.65	3,406.52	77.31	WATER WELLS
---	---	------	----------	-------	-------------

WCR No: WCR0312206
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0004384
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1994-012641
Location: 13331 EUCLID BLVD
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 13331 EUCLID BLVD
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-002048
 Location: 11162 Garden Grove Blvd
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 11162 Garden Grove Blvd
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0317682
 Location:
 City:
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1996-009469
 Location: 13482 Brookhurst Street
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946

Wells and Additional Sources Detail Report

Location(OSWCR): 13482 Brookhurst Street
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2000-010560
Location: 9972 Westminster Avenue
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 9972 Westminster Avenue
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-001904
Location: 11162 Garden Grove Blvd
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 11162 Garden Grove Blvd
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2004-011703
Location: 13482 Brookhurst Street

Wells and Additional Sources Detail Report

City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 13482 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2000-010588
 Location: 13842 Brookhurst Street
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 13842 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-002050
 Location: 11162 Garden Grove Blvd
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 11162 Garden Grove Blvd
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

4	E	0.65	3,406.52	77.31	WATER WELLS
---	---	------	----------	-------	-------------

WCR No:	WCR1982-006459
Location:	WOODBURY, TAFT
City:	Graden Grove
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	WOODBURY, TAFT
City(OSWCR):	Graden Grove
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671
Decim Long(OSWCR):	-117.946
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No:	WCR0245173
Location:	
City:	
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	
City(OSWCR):	
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671
Decim Long(OSWCR):	-117.946
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No:	WCR1925-000213
Location:	WRIGHT ST, OCEAN AVE, GARDEN GROVE
City:	
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	WRIGHT ST, OCEAN AVE, GARDEN GROVE
City(OSWCR):	
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1913-000197
 Location: VERANO ST, TRASK AVE, OCEAN AVE
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): VERANO ST, TRASK AVE, OCEAN AVE
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0218899
 Location:
 City:
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2000-010559
 Location: WESTMINSTER AVENUE
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946

Wells and Additional Sources Detail Report

Location(OSWCR): WESTMINSTER AVENUE
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0048314

Location:

City:

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Location(OSWCR):

City(OSWCR):

County(OSWCR): Orange

Decimal Lat(OSWCR): 33.7671

Decim Long(OSWCR): -117.946

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-002052

Location: 11162 Garden Grove Blvd

City: Garden Grove

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Location(OSWCR): 11162 Garden Grove Blvd

City(OSWCR): Garden Grove

County(OSWCR): Orange

Decimal Lat(OSWCR): 33.7671

Decim Long(OSWCR): -117.946

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1995-009635

Location: 13482 Brookhurst Street

Wells and Additional Sources Detail Report

City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 13482 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1913-000112
 Location: VERANO ST, TRASK AVE, OCEAN AVE
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): VERANO ST, TRASK AVE, OCEAN AVE
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2013-011023
 Location: 11162 Garden Grove Blvd
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 11162 Garden Grove Blvd
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

4	E	0.65	3,406.52	77.31	WATER WELLS
---	---	------	----------	-------	-------------

WCR No:	WCR2003-014689
Location:	10972 Westminster Avenue
City:	Westminster
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	10972 Westminster Avenue
City(OSWCR):	Westminster
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671
Decim Long(OSWCR):	-117.946
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No:	WCR2015-001907
Location:	11162 Garden Grove Blvd
City:	Garden Grove
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	11162 Garden Grove Blvd
City(OSWCR):	Garden Grove
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671
Decim Long(OSWCR):	-117.946
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No:	WCR1994-012635
Location:	13331 Euclid
City:	Garden Grove
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	13331 Euclid
City(OSWCR):	Garden Grove
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0109811

Location:

City:

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Location(OSWCR):

City(OSWCR):

County(OSWCR): Orange

Decimal Lat(OSWCR): 33.7671

Decim Long(OSWCR): -117.946

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0032803

Location:

City:

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Location(OSWCR):

City(OSWCR):

County(OSWCR): Orange

Decimal Lat(OSWCR): 33.7671

Decim Long(OSWCR): -117.946

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1952-001800

Location: E WESTMINSTER BLVD, 17TH ST, TAFT

City: Garden Grove

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Wells and Additional Sources Detail Report

Location(OSWCR): E WESTMINSTER BLVD, 17TH ST, TAFT
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0032802

Location:

City:

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Location(OSWCR):

City(OSWCR):

County(OSWCR): Orange

Decimal Lat(OSWCR): 33.7671

Decim Long(OSWCR): -117.946

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0162237

Location:

City:

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Location(OSWCR):

City(OSWCR):

County(OSWCR): Orange

Decimal Lat(OSWCR): 33.7671

Decim Long(OSWCR): -117.946

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0159395

Location:

Wells and Additional Sources Detail Report

City:
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0089994
 Location:
 City:
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0199919
 Location:
 City:
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

4	E	0.65	3,406.52	77.31	WATER WELLS
---	---	------	----------	-------	-------------

WCR No:	WCR0135543
Location:	
City:	
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	
City(OSWCR):	
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671
Decim Long(OSWCR):	-117.946
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No:	WCR2015-002047
Location:	11162 Garden Grove Blvd
City:	Garden Grove
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	11162 Garden Grove Blvd
City(OSWCR):	Garden Grove
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671
Decim Long(OSWCR):	-117.946
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No:	WCR2015-001906
Location:	11162 Garden Grove Blvd
City:	Garden Grove
County:	Orange
Decimal Latitude:	33.7671
Decimal Longitude:	-117.946
Location(OSWCR):	11162 Garden Grove Blvd
City(OSWCR):	Garden Grove
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7671

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-002051
Location: 11162 Garden Grove Blvd
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 11162 Garden Grove Blvd
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1995-010624
Location: 13502 BROOKHURST
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 13502 BROOKHURST
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-001905
Location: 11162 Garden Grove Blvd
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946

Wells and Additional Sources Detail Report

Location(OSWCR): 11162 Garden Grove Blvd
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0289442

Location:

City:

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Location(OSWCR):

City(OSWCR):

County(OSWCR): Orange

Decimal Lat(OSWCR): 33.7671

Decim Long(OSWCR): -117.946

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1993-010775

Location: 10972 Westminster Avenue

City: Garden Grove

County: Orange

Decimal Latitude: 33.7671

Decimal Longitude: -117.946

Location(OSWCR): 10972 Westminster Avenue

City(OSWCR): Garden Grove

County(OSWCR): Orange

Decimal Lat(OSWCR): 33.7671

Decim Long(OSWCR): -117.946

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0151862

Location:

Wells and Additional Sources Detail Report

City:
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-002060
 Location: 11162 Garden Grove Blvd
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 11162 Garden Grove Blvd
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2004-014549
 Location: 13511 Euclid Street
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7671
 Decimal Longitude: -117.946
 Location(OSWCR): 13511 Euclid Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7671
 Decim Long(OSWCR): -117.946
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

4	E	0.65	3,406.52	77.31	WATER WELLS
---	---	------	----------	-------	-------------

WCR No: WCR0048315
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1952-001801
Location: TAFT ST, 17TH ST, VERANO RD
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): TAFT ST, 17TH ST, VERANO RD
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR0099525
Location:
City:
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR2015-002049
Location: 11162 Garden Grove Blvd
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 11162 Garden Grove Blvd
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	E	0.65	3,406.52	77.31	WATER WELLS

WCR No: WCR1994-012640
Location: 13331 EUCLID BLVD
City: Garden Grove
County: Orange
Decimal Latitude: 33.7671
Decimal Longitude: -117.946
Location(OSWCR): 13331 EUCLID BLVD
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7671
Decim Long(OSWCR): -117.946
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2001-012359
Location:
City:
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95

Wells and Additional Sources Detail Report

Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2015-001794
Location: 12012 Brookhurst Street
City: Garden Grove
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR): 12012 Brookhurst Street
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR0216525
Location:
City:
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1935-000227
Location: VALENCIA, BROOKHURST, NICHOLS

Wells and Additional Sources Detail Report

City: FULLERTON
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): VALENCIA, BROOKHURST, NICHOLS
 City(OSWCR): FULLERTON
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2015-001797
 Location: 12012 Brookhurst Street
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): 12012 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2001-014491
 Location: 12012 Brookhurst Street
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): 12012 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

16	NNE	0.99	5,235.98	88.94	WATER WELLS
----	-----	------	----------	-------	-------------

WCR No: WCR1991-020973
Location: BROOKHURST ST, BROOKHURST WAY, STANFORD
City:
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR): BROOKHURST ST, BROOKHURST WAY, STANFORD
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR0004415
Location:
City:
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1998-010754
Location: BROCKHURST, CHAPMAN
City: Garden Grove
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR): BROCKHURST, CHAPMAN
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1952-001717
Location: BROOKHURST, CHAPMAN
City: Garden Grove
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR): BROOKHURST, CHAPMAN
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2015-001793
Location: 12012 Brookhurst Street
City: Garden Grove
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR): 12012 Brookhurst Street
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2010-010358
Location: 12711 Brookhurst Street
City: Garden Grove
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95

Wells and Additional Sources Detail Report

Location(OSWCR): 12711 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1916-000043
 Location: OCEAN AVE, EUCLID AVE
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): OCEAN AVE, EUCLID AVE
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1987-014318
 Location: BROOKHURST ST, STANFORD AVE
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): BROOKHURST ST, STANFORD AVE
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1997-010365
 Location: SWC GARDEN GROVE BLVD & EUCLID

Wells and Additional Sources Detail Report

City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): SWC GARDEN GROVE BLVD & EUCLID
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2015-001792
 Location: 12012 Brookhurst Street
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): 12012 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR0098806
 Location:
 City:
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

16	NNE	0.99	5,235.98	88.94	WATER WELLS
----	-----	------	----------	-------	-------------

WCR No:	WCR1998-010753
Location:	BROCKHURST, CHAPMAN
City:	Garden Grove
County:	Orange
Decimal Latitude:	33.7816
Decimal Longitude:	-117.95
Location(OSWCR):	BROCKHURST, CHAPMAN
City(OSWCR):	Garden Grove
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7816
Decim Long(OSWCR):	-117.95
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No:	WCR2010-010357
Location:	12711 Brookhurst Street
City:	Garden Grove
County:	Orange
Decimal Latitude:	33.7816
Decimal Longitude:	-117.95
Location(OSWCR):	12711 Brookhurst Street
City(OSWCR):	Garden Grove
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7816
Decim Long(OSWCR):	-117.95
Data Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No:	WCR0124850
Location:	
City:	
County:	Orange
Decimal Latitude:	33.7816
Decimal Longitude:	-117.95
Location(OSWCR):	
City(OSWCR):	
County(OSWCR):	Orange
Decimal Lat(OSWCR):	33.7816

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1916-000105
Location: GARDEN GROVE, OCEAN AVE, EUCLID AVE
City:
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR): GARDEN GROVE, OCEAN AVE, EUCLID AVE
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2015-001796
Location: 12012 Brookhurst Street
City: Garden Grove
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR): 12012 Brookhurst Street
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2010-010356
Location: 12711 Brookhurst Street
City: Garden Grove
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95

Wells and Additional Sources Detail Report

Location(OSWCR): 12711 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1776-008728
 Location:
 City:
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR):
 City(OSWCR):
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2015-001798
 Location: 12012 Brookhurst Street
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): 12012 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2015-001795
 Location: 12012 Brookhurst Street

Wells and Additional Sources Detail Report

City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): 12012 Brookhurst Street
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1992-017555
 Location: STANFORD AVE, NUTWOOD ST
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): STANFORD AVE, NUTWOOD ST
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR1998-010752
 Location: BROCKHURST, CHAPMAN
 City: Garden Grove
 County: Orange
 Decimal Latitude: 33.7816
 Decimal Longitude: -117.95
 Location(OSWCR): BROCKHURST, CHAPMAN
 City(OSWCR): Garden Grove
 County(OSWCR): Orange
 Decimal Lat(OSWCR): 33.7816
 Decim Long(OSWCR): -117.95
 Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
---------	-----------	---------------	---------------	----------------	----

Wells and Additional Sources Detail Report

16	NNE	0.99	5,235.98	88.94	WATER WELLS
----	-----	------	----------	-------	-------------

WCR No: WCR0269481
Location:
City:
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR2010-010355
Location: 12711 Brookhurst Street
City: Garden Grove
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR): 12711 Brookhurst Street
City(OSWCR): Garden Grove
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816
Decim Long(OSWCR): -117.95
Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.99	5,235.98	88.94	WATER WELLS

WCR No: WCR0089617
Location:
City:
County: Orange
Decimal Latitude: 33.7816
Decimal Longitude: -117.95
Location(OSWCR):
City(OSWCR):
County(OSWCR): Orange
Decimal Lat(OSWCR): 33.7816

Wells and Additional Sources Detail Report

Decim Long(OSWCR): -117.95

Data Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Radon Information

This section lists any relevant radon information found for the target property.

Federal EPA Radon Zone for *ORANGE* County: **3**

Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L

Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L

Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L

Federal Area Radon Information for *ORANGE* County

No Measures/Homes:	31
Geometric Mean:	0.5
Arithmetic Mean:	0.7
Median:	0.6
Standard Deviation:	0.7
Maximum:	2.2
% >4 pCi/L:	0
% >20 pCi/L:	0
Notes on Data Table:	TABLE 1. Screening indoor radon data from the EPA/State Residential Radon Survey of California conducted during 1989-90. Data represent 2-7 day charcoal canister measurements from the lowest level of each home tested.

Federal Sources

FEMA National Flood Hazard Layer

FEMA FLOOD

The National Flood Hazard Layer (NFHL) data incorporates Flood Insurance Rate Map (FIRM) databases published by the Federal Emergency Management Agency (FEMA), and any Letters Of Map Revision (LOMRs) that have been issued against those databases since their publication date. The FIRM Database is the digital, geospatial version of the flood hazard information shown on the published paper FIRMs. The FIRM Database depicts flood risk information and supporting data used to develop the risk data. The FIRM Database is derived from Flood Insurance Studies (FISs), previously published FIRMs, flood hazard analyses performed in support of the FISs and FIRMs, and new mapping data, where available.

Indoor Radon Data

INDOOR RADON

Indoor radon measurements tracked by the Environmental Protection Agency(EPA) and the State Residential Radon Survey.

Public Water Systems Violations and Enforcement Data

PWSV

This list of drinking water violations and enforcement actions is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database, as part of the national download of Safe Drinking Water Act (SDWA) data. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program, including monitoring, enforcement, and violation data related to requirements established by the SWDA. Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Radon Zone Level

RADON ZONE

Areas showing the level of Radon Zones (level 1, 2 or 3) by county. This data is maintained by the Environmental Protection Agency (EPA).

Safe Drinking Water Information System (SDWIS)

SDWIS

This national download of Safe Drinking Water Act (SDWA) data is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program related to requirements established by the Safe Drinking Water Act (SDWA). Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Soil Survey Geographic database

SSURGO

The Soil Survey Geographic database (SSURGO) contains information about soil as collected by the National Cooperative Soil Survey at the Natural Resources Conservation Service (NRCS). Soil maps outline areas called map units. The map units are linked to soil properties in a database. Each map unit may contain one to three major components and some minor components.

U.S. Fish & Wildlife Service Wetland Data

US WETLAND

The U.S. Fish & Wildlife Service Wetland layer represents the approximate location and type of wetlands and deepwater habitats in the United States.

USGS Current Topo

US TOPO

US Topo topographic maps are produced by the National Geospatial Program of the U.S. Geological Survey (USGS). The project was launched in late 2009, and the term "US Topo" refers specifically to quadrangle topographic maps published in 2009 and later.

USGS Geology

US GEOLOGY

Seamless maps depicting geological information provided by the United States Geological Survey (USGS).

USGS National Water Information System

FED USGS

The U.S. Geological Survey's (USGS) National Water Information System (NWIS) is the nation's principal repository of water resources data. The data includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data. This NWIS database information is obtained through the Water Quality Data Portal (WQP). The WQP

Appendix

is a cooperative service sponsored by the USGS, the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC).

State Sources

Oil and Gas Wells

OGW

The California Department of Conservation, Geologic Energy Management Division (CalGEM) provides this oil and gas wells dataset. CalGEM makes no warranties, whether expressed or implied, and the data is for informational purposes.

Periodic Groundwater Level Measurement Locations

MONITOR WELLS

Locations of groundwater level monitoring wells in the Department of Water Resources (DWR)'s Periodic Groundwater Levels dataset. The DWR Periodic Groundwater Levels dataset contains seasonal and long-term groundwater level measurements collected by the Department of Water Resources and cooperating agencies.

Well Completion Reports

WATER WELLS

List of wells from the Well Completion Reports data made available by the California Department of Water Resources' (DWR) Online System for Well Completion Reports (OSWCR). Please note that the majority of well completion reports have been spatially registered to the center of the 1x1 mile Public Land Survey System section that the well is located in.

Liability Notice

Reliance on information in Report: The Physical Setting Report (PSR) DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a review of environmental databases and physical characteristics for the site or adjacent properties.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS Information Inc. disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

APPENDIX D: QUALIFICATIONS/INSURANCE



Education

Bachelor of Arts, Global Studies with an Emphasis on Socioeconomics and Asian American Studies,
University of California Santa Barbara

Highlights

19 years experience in various environmental assessments

Phase I Environmental Site Assessments
Transaction Screen Assessments
Phase II Subsurface Investigations
Environmental Desktop Reports
Review of Environmental Assessment Reports

Experience Summary

Richard Kim currently holds the role of Senior Project Manager for Partner Engineering and Science, Inc. (Partner). His responsibilities include due diligence practices such as environmental desktop reports and Phase I Environmental Site Assessment (ESA) Reports on property types within the scope of the ASTM E1527-21/AAI Standard.

Mr. Kim is responsible for the duties performed within the scope of a Phase I ESA, including site inspection, historical research, document review, and interviews. He has experience working with a variety of site types, including commercial buildings, industrial properties, agricultural properties, special-use sites, and vacant land.

Mr. Kim has personally conducted site visits and managed over 3,000 projects across multiple states, covering commercial, industrial, special-use, and agricultural properties. His hands-on experience includes performing preliminary screenings, assessing on-site conditions, and supporting Phase II investigations. Additionally, he reviews Phase I ESA reports and other environmental due diligence documents to ensure accuracy, compliance with ASTM and EPA AAI standards, and overall quality before finalizing deliverables.

Contact

rkim@partneresi.com



Education

B.S. Geobiology, Penn State University, University Park, PA

Registrations

California Department of Real Estate, Salesperson License #02166383

Training

OSHA 40-Hour HAZWOPER and OSHA 8-Hour HAZWOPER Refreshers

Highlights

Phase I Environmental Site Assessments per ASTM E1527-21
Phase II Environmental Site Assessments per ASTM E1903-19
Subsurface Investigations
Environmental Desktop Reports

Experience Summary

Mr. Davis is a Project Assessor at Partner Engineering and Science, Inc. (Partner), with three years of experience conducting Phase I Environmental Site Assessments (ESAs) for a variety of commercial real estate property types and clients, according to the ASTM E1527-21 standard and the US Environmental Protection Agency (USEPA) All Appropriate Inquiries (AAI) requirements.

Additionally, Mr. Davis has three years of experience conducting Phase II ESAs, according to the ASTM E1903-19 standard and the USEPA AAI requirements, and four years of experience with subsurface investigations in the form of fieldwork and technical report preparation. Mr. Davis exhibits expertise in a variety of soil and groundwater sampling techniques.

Mr. Davis has worked on various large-scope projects, including commercial, multi-family residential, industrial, and agricultural use. Mr. Davis works closely with state and local agencies to identify environmental issues pertaining to tank removal and regional groundwater plumes.

Contact

reese.davis@partneresi.com



Education

B.A., Environmental Health & Planning and Criminal Justice, University of California, Irvine

Registrations/Training

OSHA 40-Hour Hazwoper Health and Safety Training
EPA Accredited Asbestos Inspector
EPA Accredited Asbestos Management Planner
EPA Accredited Asbestos Abatement/Contractor Supervisor
HUD Map Underwriter Certification – 2004

Highlights

31 Years of Experience in National Environmental Due Diligence Consulting
Phase I Environmental Site Assessments
Phase II Subsurface Soil/Soil Gas Investigations
Property Condition Assessments
Asbestos/Lead-Based Paint Inspections

Experience Summary

Mr. Vaughn currently serves as a National Client Manager with significant environmental and due diligence engineering experience nationwide. Mr. Vaughn's experience includes two former Engineering News-Record Top 500 Design firms and a Fortune 500 firm. His responsibilities include full-phase environmental consulting, national client management, multi-scope contract negotiation/execution, portfolio project management, and technical report quality control. Mr. Vaughn's regional and national expertise compliments the wide variety of Partner projects and client types including prominent fast-food retail chains, attorneys, commercial developers, mortgage bankers, real estate brokers, individual investors, equity/institutional investment groups, and financial lending institutions, including CMBS lenders, SBA lenders, and GSA (Fannie and Freddie) lenders.

Mr. Vaughn has served as an environmental scientist, project manager, or executive senior author on over 20,000 real estate transactions. Mr. Vaughn's due diligence resume includes experience at all levels, advising lenders and real estate investors through the following product types:

- Phase I Environmental Site Assessments
- Phase II Subsurface Investigations
- Phase III Site Characterizations
- Remedial Cost Estimates
- Remediation Design and Implementation
- Facility Condition Assessments
- Property Condition Assessments
- Probable Maximum Loss Assessments
- Property Condition Evaluations
- Asbestos Surveys
- Lead-Based Surveys

Robert Vaughn

Real estate investors, redevelopment agencies, financial institutions, insurance lenders, and real estate equity funds have come to rely on his advice and judgment to help them with their real estate business decisions. Mr. Vaughn is a dedicated professional who takes pride and pleasure in meeting his client's needs and spearheading and assembling the team with the expertise to handle any issue that may come up during the transaction.

Project Experience

Multi-Site Portfolio, Nationwide - Managed performance and delivery of summary matrix and completed Phase I reports for a 300+-site portfolio of apartments for a large stakeholder group.

Multi-Site Portfolio, Nationwide - Managed a 350+-site portfolio of bank branches for one of the largest bank mergers the mid-1990s.

High Rise Office Building, San Francisco - Worked on one of the largest high-rise acquisitions in San Francisco in 2015 to manage pre-acquisition due diligence for equity investor of a high rise office building in downtown San Francisco. Included a Phase I ESA, equity PCA with specialty evaluations of facade, MEP, Fire and Life Safety, Roof, and ADA.

Multi-Site Gas Station Portfolio, California - Managed performance and delivery of complete reports for a 25-site portfolio of gas stations for national lender.

Multi-Site Fast-Food Portfolio, Midwest - Managed the completion of 25 Phase I ESAs located in the Midwest in a 10-business day turnaround.

Affiliations

Environmental Banks Association
National Retail Tenants Association

Speaking

Due Diligence 101, National Retail Tenants Association, Orlando, FL.

Environmental Due Diligence: What You Don't Know Can Hurt You, National Retail Tenants Association, Reno NV.

Contact

rvaughn@partneresi.com